

TOM PEACOCK CADILLAC

CUSTOMER #: C2046416

329406

15480 I-45 NORTH
HOUSTON, TX 77090
(281) 443-7700
SERVICE: (281) 230-4400
FAX: (281) 230-4450



Cadillac

GEORGE FOREMAN

INVOICE

PAGE 2

SERVICE DEPARTMENT HOURS
Mon - Fri: 7:30 a.m. to 6:30 p.m.
Sat: 8:00 a.m. to 2:00 p.m.

SERVICE ADVISOR: 404 JOHN FISK


COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLUE	76	CADILLAC DEVILLE	6L67S60240334		2002/2012	T4505	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN76 DD			17:00 21NOV13		135.00	CASH	13DEC13

R.O. OPENED READY OPTIONS: DLR:39129

10:41 29OCT13 11:04 13DEC13

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
	AC	REPLACED	BLOWER MOTOR				
		456	CPC			300.00	300.00
	1	PM102	BLO-MOTOR		48.07	48.07	48.07
	2	INTPY7	ESTEROIL		15.01	15.01	30.02

2002 4.50 4.5 ck. a/c control panel + ck. all blown motor fuses
replaced motor + replaced blower motor high speed relay + partial
removal of a/c programmer/transducer + freed internal components.



PAID
PAID
DEC 16 2013
PAID
BY: *[Signature]*

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE: "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

Tom Peacock Cadillac, INC., including its agents, employees and representatives, (collectively Dealer) and Customer mutually agree to submit to binding arbitration, pursuant to the Federal Arbitration Act, 9 U.S.C. 1-16, or the Texas General Arbitration Act, Tex. Rev. Civ. Stat. Ann., Art. 224-236-B, as may be amended and applicable, or the common law of the State of Texas, or federal common law, as may be applicable, any and all disputes (of any kind whatsoever, including but not limited to, disputes based upon the common and or statutory law of the State of Texas) which may arise (in any way whatsoever) between them and which relate to or involve or arise out of the purchase, sale, lease, use, repair, service, testing or possession of any vehicle sold, leased repaired, serviced, tested, or possessed by Dealer and/or purchased leased or used by Customer. Dealer and Customer mutually agree to submit any dispute (as previously identified and described) to binding arbitration before the Better Business Bureau in Houston, Harris County, Texas, in accordance with the procedures and rules of the Better Business Bureau. Dealer and Customer further mutually agree that their agreement to arbitrate may be specifically enforced by a court and that a court may enter an enforceable judgment on any arbitration award. Dealer and Customer further mutually agree that binding arbitration and any award resulting there from shall be the exclusive method for resolution of any dispute between them.

DESCRIPTION	TOTALS
LABOR AMOUNT	1600.00
PARTS AMOUNT	726.97
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	2326.97
LESS INSURANCE	0.00
SALES TAX	59.98
PLEASE PAY THIS AMOUNT	2386.95

NO RETURN ON ELECTRICAL OR
SAFETY ITEMS OR SPECIAL ORDERS.

X

TOM PEACOCK CADILLAC

CUSTOMER #: C2046416

329406

15480 I-45 NORTH
HOUSTON, TX 77090
(281) 443-7700



SERVICE: (281) 230-4400
FAX: (281) 230-4450

Cadillac

GEORGE FOREMAN

INVOICE

PAGE 1

SERVICE DEPARTMENT HOURS
Mon - Fri: 7:30 a.m. to 6:30 p.m.
Sat: 8:00 a.m. to 2:00 p.m.

SERVICE ADVISOR: 404 JOHN FISK

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE:IN / OUT	TAG	
BLUE	76	CADILLAC DEVILLE	6L67S60240334		2002/2012	T4505	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN76 DD			17:00 21NOV13		135.00	CASH	13DEC13

R.O. OPENED READY OPTIONS: DLR:39129

10:41 29OCT13 11:04 13DEC13

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUST STATES AC NOT COOLING---ADVISE---
AC REPLACED POA DRYER, A/C COMPRESSOR, RADIATOR
CAP AND ADDED COOLANT

479	CPC					650.00	650.00
1	MRY35769 RELAY				42.36	42.36	42.36
427	146329						
1	QSTVA-LH11 ADAPTORS				15.13	15.13	15.13
	CQ INV#191435						
1	15211 RETROKIT				211.49	211.49	211.49
1	57098 A/C COMP				205.37	205.37	205.37
1	MCS7616 CAP				8.46	8.46	8.46
1	COOLANT NON MFR				20.32	20.32	20.32

2012 6.50 FOUND THE A/C HAD NO FREON IN SYSTEM. CONVERT THE A/C
FROM R12 TO R134. REPLACE THE POA DRYER SYSTEM TO A ACCUMULATOR ORIFICE
SYSTEM, REPLACE THE A/C COMPRESSOR FOR LEAKING OUT OF THE BACK OF THE
COMPRESSOR. REPLACE THE RADIATOR CAP AND ADD COOLANT TO SYSTEM

B CUST STATES CRUIS CANTROLL IN-OP---ADVISE---
ELECT REPLACE CRUISE CONTROL TRANSDUCER

456	CPC					450.00	450.00
1	A136102 TRANSDUCER				145.75	145.75	145.75

2002 4.50 4.5 ck. brake release switches + ck. dash on/off control
switch + ck. steering column engagement switch + ck. /sealed all
pertinent vacuum hoses + replaced cruise control transducer assy. + tes
drove

C** CUST STATES CK CONVERTABLE TOP TO WORK
ELECT LUBED ALL CONVERTIBLE TOP BRACES, LINKS,
LUBED BOTH MAIN DRIVE GEARS

456	CPC					200.00	200.00
-----	-----	--	--	--	--	--------	--------

2002 2.00 2.0 lubed all convertible top braces + links + lubed both
main drive gears + partial removal of drive cables lubed.

D** REPAIR AC TO BLOW

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE: "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

Tom Peacock Cadillac, INC., including its agents, employees and representatives, (collectively Dealer) and Customer mutually agree to submit to binding arbitration, pursuant to the Federal Arbitration Act, 9 U.S.C. 1-16, or the Texas General Arbitration Act, Tex. Rev. Civ. Stat. Ann., Art. 224-236-B, as may be amended and applicable, or the common law of the State of Texas, or federal common law, as may be applicable, any and all disputes (of any kind whatsoever) including but not limited to, disputes based upon the common and or statutory law of the State of Texas which may arise in any way whatsoever between them and which relate to or involve or arise out of the purchase, sale, lease, use, repair, service, testing or possession of any vehicle sold, leased repaired, serviced, tested, or possessed by Dealer and/or purchased leased or used by Customer. Dealer and Customer mutually agree to submit any dispute (as previously identified and described) to binding arbitration before the Better Business Bureau in Houston, Harris County, Texas, in accordance with the procedures and rules of the Better Business Bureau. Dealer and Customer further mutually agree that their agreement to arbitrate may be specifically enforced by a court and that a court may enter an enforceable judgment on any arbitration award. Dealer and Customer further mutually agree that binding arbitration and any award resulting therefrom shall be the exclusive method for resolution of any dispute between them.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

NO RETURN ON ELECTRICAL OR
SAFETY ITEMS OR SPECIAL ORDERS.

X

TOM PEACOCK CADILLAC
15480 N FREEWAY
HOUSTON, TX 77090
281-443-7700

TERMINAL ID.: 71889402
MERCHANT #: 220607952000

AMEX

*****2035 EXP:*/** KEY ENTERED

SALE

BATCH: 000012 IHU: 329406

Dec 16, 13 15:29

RRN: 335021601590 AUTH: 106693

TRAN SEQ #: 000512

ZIP CODE: 77090

SALES TAX: \$2386.95

TRANSACTION ID: 001878506554577

APPROVAL 106693

~~INFORMATIONAL~~

THANK YOU!

CUSTOMER COPY



DEDICATED TO THE PROFESSIONAL

Store 500, 3219 W LAKE HOUSTON PKWY,
KINGWOOD, TX 77339 (281) 361-5000

Bill To:

DR. D'TAIL
1956 NORTH PARK DR.
KINGWOOD, TX 77339
(281) 315-0647

Invoice	0500-276121
Sale Type	DBT. CARD SALE
Date	08/21/2019 11:36 AM
Ship Via	
PO Number	

Counter #	Customer Account	Ordered By	Special Instructions
471746	2660950		

Qty	Line	Item Number	Description	Warr	Unit	Tax	List	Net	Extended
1	SSB	75PRM	BATTERY	2Y	EA	Y	237.27	99.75	99.75
		75PRM	Core Charge		EA	Y		18.00	18.00
		BATTERY FEE	BATTERY FEE		EA	N	5.08	3.00	3.00
1	SSB	24PRM	BATTERY	2Y	EA	Y	237.27	107.09	107.09
		24PRM	Core Charge		EA	Y		18.00	18.00
		BATTERY FEE	BATTERY FEE		EA	N	5.08	3.00	3.00
1	OMS	9046	IGN WIRE SET	LT	ST	Y	37.27	21.00	21.00
1	PPS	13402009	PWR STG HOSE	LT	EA	Y	37.27	20.32	20.32

Cadillac Eldorado Tune up

4 Items

Call 866-830-4351 for Super Start National Warranty Information.

Pay your First Call invoices online. Visit First Call Online to learn more.

Chip Used: Y A000000980840 8000048000 6800 06010A03A00000 Verified By PIN REF #: 334538024671 AUTH CD: 415373

Sub-Total	290.16
Sales Tax	23.44
Total	313.60
VISA #2495	313.60



WWW.FIRSTCALLONLINE.COM

Please visit www.firstcallonline.com/warranty for warranty details

1/1

WE APPRECIATE YOUR BUSINESS!

Remit To: PO BOX 9464, SPRINGFIELD, MO 65801-9464

Cadillac Eldorado



Limitless Parts Company

(281) 359-6272

1700 Northpark Drive

281-359-6272

Kingwood, TX 77339

Emp.5 08/19/2019 15:33 (19)

INVOICE 329785

32044 DR. D'TAIL VEHICLE SPA & SUPPLIES
1956 NORTH PARK DRIVE
KINGWOOD, TX 77339

Description	Qty	Net	Total
1976 Cadillac Eldorado			
Spark Plug Co	8	2.49	19.92 T
AC R15XLS6			
Qty: 8 from: 001 - HOU MAIN STORE			
Gap .060"			
Distributor Cap	1	26.49	26.49 T
RR171			
Distributor Rot	1	14.99	14.99 T
ECH RR173			
WESTLEYS BLEACH	1	4.99	4.99 T
BC 800002224			

Subtotal

66.39

TAXTABLE Montgomery 5 8.2500%

5.48

% 0.00

TOTAL DUE

71.87

PINdebit 2495 93155

71.87

Name Not Available

I agree to pay total amount
according to card issuer agreement.

NO REFUNDS, DOOLS, SPECIAL
ORDERS OR ELECTRICAL
PARTS.

RECEIPT REQUIRED
FOR RETURNS
WARRANTY INFORMATION
AVAILABLE
ON REQUEST

CUSTOMER COPY

Vehicle Detail

Dr. D'Tail Vehicle Spa and Supplies

1956 NorthPark Dr., Kingwood Texas 77339 281-315-0647

Customer:

George Foreman

Date:

8/25/2019

Technician:

CHRISTOPHER ANDERSON






License Plate #	Make & Model	Year	Color
	<i>Cadillac Eldorado</i>	<i>76</i>	<i>Blue</i>
Notes	Service To Be Performed	Price	
	<i>3 step PAINT CORRECTION</i>		
	<i>TUNE UP (Plugs, Lines, Rotor Cap, etc)</i>		
	<i>BATTERY REPLACEMENT</i>		
Payment	How Paid	Total	

EXTERIOR DAMAGE

S--Scratch
D--Dent
W--Windshield Crack
P--Paint Chip

OTHER:

Crome needs Deep/extensive Polishing. Vehicle keeps draining Battery other than that everything fine.



TO BEGIN VEHICLE DETAIL:

I the undersigned, authorize Dr. D'Tail to perform the above services. I agree to pay the charges listed above in full at the time service is rendered. In the unlikely event that we cannot perform to your satisfaction, our liability is limited to a refund of any amount paid for services. I have been instructed as to the expectations (improvement but not new condition) and warranties involved with our services and I understand the policies regarding these matters. Signing below indicates that I have read this paragraph and I agree to the terms set herein and I acknowledge the damage identified as pre-existing on this form.

SIGNATURE: _____

DATE: _____

PICKING UP THIS VEHICLE:

I the undersigned, have inspected this vehicle and I am pleased with the result.

SIGNATURE: _____

DATE: _____



2519175

IDENTIFICATION CERTIFICATE

FOR A MOTOR VEHICLE LAST REGISTERED
OR TITLED IN SOME OTHER STATE OR COUNTRY

VEHICLE YEAR 1976	MAKE cadillac	BODY STYLE 2 - Door
MANUFACTURER'S VEHICLE IDENTIFICATION NUMBER 6 6 7 8 6 0 2 4 0 3 3 4		
NAME OF STATE OR COUNTRY IN WHICH LAST REGISTERED NA	YEAR OF LICENSE NA	LICENSE NUMBER NA
INSPECTION CERTIFICATE NO. K 4 8 5 7 7 7 0		
ODOMETER READING 01903		

NOT ACCEPTABLE WITH ERASURES OR ALTERATIONS

STATEMENT OF INSPECTOR

I, the undersigned duly appointed Inspector, hereby certify that I have physically examined the manufacturer's vehicle identification number of the motor vehicle described above.

2-17-94
Date

Kevin D. Wood
Signature of Inspector

2P05378
Station Number

Kingscrossing Exxon
Name of Station

— NOTE TO OWNER —

This form must be attached to your application for Texas Certificate of Title at the time you purchase Texas License plates from county Tax Assessor-Collector. This inspection required by law.

ADJUSTING THE CRUISE CONTROL SET SPEED

NOTE: Before zeroing the cruise resume speed, inspect the vacuum system. Make sure there are no pinched lines or disconnected hoses.

1. Locate the orifice tube on the transducer and loosen the locknut.
2. If the cruising speed is lower than the engagement speed, turn the orifice tube outward; if cruise speed is too high, turn the tube inward. Each 1/4 turn on the orifice tube will change the engage/cruise speed approximately one mile per hour.

3. Tighten the lock nut after completing orifice tube adjustment.
4. Verify proper engagement/cruising speed operation at 55 miles per hour. Repeat adjustment procedure if necessary.

CAUTION: DO NOT remove the orifice tube from the transducer! It cannot be replaced once it has been removed from the unit.

TROUBLESHOOTING CHART

Problem	Cause and possible solution							
	Pinched/disconnected vacuum lines	Leaking vacuum lines or solenoid	Defective fuse or resume switch	Loose or binding throttle linkage	Defective resume solenoid valve	Poor connection/open wiring/bad switch	Speedometer cable bent/kinked	Orifice tube out of adjustment
System inoperative, cruise light on	X				X	X		
System inoperative, cruise light off			X			X		
Surges in vehicle speed	X			X			X	
Speed increases after cruise engagement							X	X
Speed decreases after cruise engagement	X	X		X				X
Excessive downhill speed				X				X

©Copyright 1991 Automotive Cataloging, Inc.
All rights reserved. No part of the contents can be reproduced in any form including entry in an electronic data system without express written permission.

GZ-DM-3/91
Part No. 93-0338-36

CRUISE CONTROL TRANSDUCER

Step-by-Step Installation Instructions

CRUISE
CONTROL
TRANSDUCER

Make these three checks to avoid warranty problems!

1. Make sure you check the engagement switch.
2. Make sure you check the brake/clutch release switch.
3. Make sure you check the vacuum supply.

IMPORTANT: Although diesel and gasoline engine transducers appear similar, they cannot be interchanged, because their vacuum characteristics are different.

REMOVING THE ORIGINAL TRANSDUCER

1. Disconnect the ground cable from the battery.
2. Carefully remove electrical connector(s) from the transducer. If the vehicle is equipped with resume feature, separate electrical connector from the transducer's solenoid valve.
3. Remove vacuum hoses/fittings from the transducer. Note the location of various hoses so they can be properly installed on the replacement transducer.
4. Remove both speedometer cables from the transducer.
5. Loosen and remove screws/bolts that secure transducer to the mounting bracket.


NOTE: If the transducer is equipped with a resume solenoid, you must transfer the solenoid to the replacement unit before installation.

7. Put the original transducer in the replacement unit carton to assure proper core credit upon return.

INSTALLING THE REPLACEMENT TRANSDUCER

1. Inspect vacuum system for pinched or disconnected hoses. Also, check for cracked or spongy hoses and replace any found. Be sure vehicle's manifold fitting isn't blocked to assure adequate vacuum supply.

2. Position the transducer on its bracket and install mounting screws or bolts.
3. Connect speedometer cables to transducer. These must be secure for proper transducer operation. Make sure they are routed correctly to prevent kinking or other damage.
4. Install vacuum hoses/fittings to vacuum ports on the replacement transducer.
5. Carefully push electrical connector(s) onto the transducer terminals and install resume solenoid electrical connector, if so equipped.
6. Reconnect the ground cable to the battery.
7. Perform electrical and vacuum system checks as described in following instructions.



S&S Wrecker Service
19026 Aquatic Dr. • Humble, Texas 77346
TDLR 006416584C

832-382-8729

Invoice # 20847
Date 8/30/19
Mileage

Keys ☒ Yes ☐ No
(H) Phone (W) Phone
Year 76' Make & Model Ford Eldorado
License State TX Color Blue
VIN # H26877381

Owner Dr. Detail
Address
City State Zip
Location Pickup
Location Towed
Location Transferred

Accident ☐ Prisoner ☐ Stolen ☐ Abandoned ☐
Private Property ☐ Agency Time 2:27 am/pm
Name Control #

CHARGES	Wrecker Service	\$ 98.00
	Transfer	\$
	Dolly	\$
	Recovery	\$
	Impoundment	\$
	Notification	\$
	Drive Line	\$
	Storage Rate _____ per day	\$
	Tax _____ x 8.25%	\$
	Total	\$ 98.00
Time: 2:27 am/pm		

We Authorize this Wrecker Service to remove from our Property above listed vehicle.

X Phone

Personal Property:

I x authorize this tow agree to all charges. I have received a copy of this invoice, and here have been notified in accordance with Chapter 70 of the Tex Property Code that your vehicle will be subject to repossession al with fees and other incurred expenses associated with such returned checks, credit card charge backs and stop payments.

☐ Cash ☐ Check #
Released Date
Approval / RO# PO#
Wrecker Driver Katie Sarafin
T.T. # 70864K Permit # 47034

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL
Complaints Directed to: TEXAS DEPARTMENT OF LICENSING and REGULATION • P.O. Box 12157 • Austin, Texas 78711 • 1-800-803-9202

S&S Wrecker Service
19026 Aquatic Dr. • Humble, Texas 77346
TDLR 006416584C

832-382-8729

Invoice # 20825
Date 8/15/19
Mileage

Keys ☐ Yes ☐ No
(H) Phone 781-315-0647 (W) Phone
Year 1976 Make & Model Ford Eldorado
License # N/A State TX Color Blue
VIN # H26877381

Owner Dr. Detail (Chris)
Address 1956 Northpark Dr.
City State Zip
Location Pickup
Location Towed
Location Transferred

Accident ☐ Prisoner ☐ Stolen ☐ Abandoned ☐
Private Property ☐ Agency Time am/pm
Name Control #

CHARGES	Wrecker Service	\$ 90.00
	Transfer	\$
	Dolly	\$
	Recovery	\$
	Impoundment	\$
	Notification	\$
	Drive Line	\$
	Storage Rate _____ per day	\$
	Tax _____ x 8.25%	\$
	Total	\$ 90.00
Time: 8:00 am/pm		

We Authorize this Wrecker Service to remove from our Property above listed vehicle.

X Phone

Personal Property:

I x authorize this tow agree to all charges. I have received a copy of this invoice, and here have been notified in accordance with Chapter 70 of the Tex Property Code that your vehicle will be subject to repossession al with fees and other incurred expenses associated with such returned checks, credit card charge backs and stop payments.

☐ Cash ☐ Check #
Released Date
Approval / RO# PO#
Wrecker Driver Katie Sarafin
T.T. # 70864K Permit # 47034

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL
Complaints Directed to: TEXAS DEPARTMENT OF LICENSING and REGULATION • P.O. Box 12157 • Austin, Texas 78711 • 1-800-803-9202