



Honda Suzuki of Warren

30822 Ryan Road
Warren, MI 48092

586-751-1200


Repair Order

In Date: Nov. 10, 2022

P/U Date: Dec. 03, 2022

Service Writer: SD

RO #60874



Sold To :

Unit Information

Year	Manufacturer	Model	VIN/HIN/SN	Engine #	Keyboard	Miles/Hours
1976	HONDA	CB550F	CB550F-2004238			12035.00

Job: TUNE UP/OIL CHANGE

HONDA CB550F 1976 - CB550F-2004238

PLUGS / VALVES / TIMING CHAIN / OIL CHANGE / SINC CARBS / 1 CYLINDER RUNNING HOTTER THAN THE OTHERS

Part #	Part Description	Qty	Price	Unit Extension	Extension
98069-57717	SPARK PLUG (D7EA)	4	\$3.99	\$3.99	\$15.96
15410-426-010	ELEMENT, OIL FILTER	1	\$12.99	\$12.99	\$12.99
08C35-A141M01/B	GN4 OIL QT BULK	4	\$6.99	\$6.99	\$27.96
ODF	USED OIL PROD. DISPOSAL FEE	1	\$2.99	\$2.99	\$2.99
DPW	DRAIN PLUG WASHER	1	\$0.99	\$0.99	\$0.99
12361-300-000	CAP, VALVE ADJ.	1	\$10.99	\$10.99	\$10.99
91302-001-020	O-RING (30.8MM)	1	\$3.99	\$3.99	\$3.99

Parts Subtotal: \$75.87

Technician	Description	Hours	Rate	Discount	Labor Cost
JOSH	TUNE UP/OIL CHANGE	3.20	\$109.00	0.00 %	\$348.80

Labor Subtotal: \$348.80

Fees	Qty	Fee Cost
MISC	1	\$20.93
MISC	1	\$75.00

Fees Subtotal: \$95.93

Tax: \$10.32

Job Subtotal: \$530.92

Resolution:

N/A

Recommended Repairs:

N/A

Notes:

Parts S/O - Completely Received (RO#60874
VELARDO, MICHAEL) Invoice: 47454
Service - All Jobs Completed (RO#60874 VELARDO,
MICHAEL VIN#CB550F-2004238) Invoice: 60874
Service - All Jobs Completed (RO#60874 VELARDO,
MICHAEL VIN#CB550F-2004238) Invoice: 60874

12/03/2022 TXN 337770436692

Invoice Summary

Parts Total: \$75.87

Labor Total: \$348.80

Fees Total: \$95.93

Sublet: \$0.00

Sub Total: \$520.60

Total Tax: \$10.32

Total: \$530.92

CLOVER CARD
Payment: \$530.92

Balance: \$0.00



Honda Suzuki of Warren
30822 Ryan Road
Warren, MI 48092
586-751-1200

Repair Order

In Date: Nov. 10, 2022

Follow up Date: Nov. 13, 2022

Service Writer: SD

RO #60874



Unit Information

Year	Manufacturer	Model	VIN/HIN/SN	Engine #	Keyboard	Miles/Hours
1976	HONDA	CB550F				

Job: ESTIMATE

HONDA CB550F 1976

PLUGS / VALVES / TIMING CHAIN / OIL CHANGE / SINC CARBS / 1 CYLINDER RUNNING HOTTER THAN THE OTHERS

Technician	Description	Hours	Rate	Discount	Labor Cost
Not Assigned		1.00	\$109.00	0.00 %	\$109.00

Labor Subtotal: \$109.00

Tax: \$0.00

Job Subtotal: \$109.00

Resolution:

N/A

Recommended Repairs:

N/A

Notes:

Invoice Summary

Parts Total: \$0.00

Labor Total: \$109.00

Fees Total: \$0.00

Sublet: \$0.00

Sub Total: \$109.00

Total Tax: \$0.00

Total: \$109.00

Balance: \$109.00

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control. Service Fee Charges – This is added for supplies used in the Service and Parts Department(s).

The Only Warranties Applying to the Part(s) are those which may be offered by the Manufacture. The Selling Dealer hereby expressly Disclaims All Warranties, either expressed or implied, including any implied warranties of merchantability of fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damage for loss of use, loss of time, loss of profits, or income or any other incidental damages.

Vehicles left over 5 days after notification of completion will be subject to a \$20.00 per day storage charge.

Signature

Save Old Parts? Yes _____ No _____

CERTIFICATION: All repairs and parts listed were furnished in compliance with Michigan Auto Repair Act(A300)