

Snook's DREAM CARS

Invoice

DATE	INVOICE #
8/19/2021	4868

BILL TO

Mileage	TERMS	PROJECT
95,225	Due upon receipt	1971 Datsun 240Z

QUANTITY	DESCRIPTION	RATE	AMOUNT
61	Hours to address the following: Install new horn pad. Free-up stuck left turn signal cancel pawl. Install steering wheel in centered position. Disconnect radio power antenna. Tighten all fasteners on rear bumper. R&R front wheels to clean & dedust brake hardware. Diagnose worn bushings in rear lower control arms. Clearance carpet for full throttle of gas pedal. Tighten steering shaft clamp at rack. Drain/refill transmission and differential fluids. Tighten differential fasteners. LOF service. Flush brake/clutch hydraulics. Drain, flush, & refresh cooling system. Replace thermostat and housing. Properly fit and mount voltage regulator. Replace broken connector on coil for distributor & tach wires. R&R door panels to get windows operating properly. Install & repair window track channels. Diagnose worn driver side window regulator. Fabricate & install AC control binnacle. Fabricate & install power wire & fuse for AC. Repair wiring for tach & get operational. R&R oil/temp gauge to repair loose plastic cover. Replace instrument light bulbs. Replace ignition switch/tumbler. Diagnose temp gauge faulty. R&R carb tops to adjust floats, clean bowls, pistons & needles. Install new vent knobs & turn signal knob.	65.00	3,965.00
		Total	

Snook's DREAM CARS

Invoice

DATE	INVOICE #
8/19/2021	4868

BILL TO

Mileage	TERMS	PROJECT
95,225	Due upon receipt	1971 Datsun 240Z

QUANTITY	DESCRIPTION	RATE	AMOUNT
	PARTS		
1	WIX 51512 Oil Filter	13.00	13.00
4.5	Quart(s) of Brad Penn 20W50 High Performance Oil	10.00	45.00
2	12 oz Bottles of Castrol Dot 4 Brake Fluid	4.50	9.00
2	Gallon(s) of 50/50 Pre-Mix Coolant	8.85	17.70
1	Thermostat	24.87	24.87
1	Thermostat Gasket	0.89	0.89
1	Thermostat Housing	21.63	21.63
1	Ignition Switch	52.95	52.95
1	Door channel window gasket.	25.98	25.98
1	Set of Lower Door Window Stops.	27.00	27.00
1	Plastic Box for AC Controls	24.41	24.41
1	Set of Lug Nuts	20.82	20.82
1	Set of Wheel Center Caps	47.97	47.97
1	Horn Pad/Button	89.00	89.00
1	Door Latch Dovetail & Screws	19.26	19.26
4	Vredestein 175HR-14 Tires	103.15	412.60
1	Mount & Balance 4 Tires	147.60	147.60
1	Set Air Vent Knobs	34.95	34.95
1	Turn Signal Knob	19.95	19.95
1	Shipping Expenses (at cost)	39.45	39.45
	State of Ohio	6.75%	335.96
		Total	\$5,394.99

Snook's DREAM CARS

Invoice

DATE	INVOICE #
10/12/2021	4899

BILL TO

Mileage	TERMS	PROJECT
95,440	Due upon receipt	1971 Datsun 240Z

QUANTITY	DESCRIPTION	RATE	AMOUNT
23	Hours to complete the following work: Install driver side carpet clips. Install passenger side door pull handle. Install driver door window regulator. Reattach right rear bumper ends. Replace clevis pin on clutch pedal & lube. R&R rear lower control arms to replace bushings & pins. Fabricate & install driver side defrost duct. R&R driver seat for seat bottom repair. Adjust carburetors.	75.00	1,725.00
1	Left Side Window Crank Regulator	188.98	188.98
1	Carpet Anti Slide Clip Set	47.26	47.26
1	Interior Door Pull Handle	73.70	73.70
2	Rear Control Arm Bushing Kits	87.95	175.90
1	Rear Suspension Spindle Pin Kit	152.90	152.90
1	Press Control Arm Pins & Bushings	264.00	264.00
1	Defroster Hose	30.13	30.13
1	Repair Driver Seat Bottom	147.98	147.98
1	Incoming Shipping	91.17	91.17
	State of Ohio	6.75%	159.79
		Total	\$3,056.81

Snook's DREAM CARS

Invoice

DATE	INVOICE #
11/18/2021	4942

BILL TO

Mileage	TERMS	PROJECT
95,520	Due upon receipt	1971 Datsun 240Z

QUANTITY	DESCRIPTION	RATE	AMOUNT
22	Hours to complete the following: Remove rear facia panel to replace loose clips & plastic rivets. Install "anti-vibration" rubber pieces to stop rattles. Install rivet to left side rear bumper sections. Replace right headlight. Remove short shift lever & replace with used 280Z shift lever. Install new shifter pin & bushings. Install lower & upper shift boots and modify console for better fit. Inspect rear axles for "clunking" noise. (Testing suggests excessive differential wear.) Repair cracked mini buss-bar to get water temp gauge operational. Install new driver door mirror. Install new driver outside door handle. R&R front wheels for balancing.	75.00	1,650.00
1	Outside Rearview Mirror	34.38	34.38
1	Lower Shifter Boot	11.24	11.24
1	Upper Shifter Boot	54.99	54.99
1	Sealed Beam Headlight	22.99	22.99
1	Set Rear Finisher Plastic Rivets	43.75	43.75
1	Set Rear Finisher Bottom Clips	87.50	87.50
1	Shift Knob	50.49	50.49
1	Shifter Pin & Bushing Kit	33.74	33.74
1	Used 280Z Shift Lever	123.75	123.75
1	Pair Outside Door Handles	80.59	80.59
1	Sublet: Roadforce Balance Front Wheels @ Tireman	25.00	25.00
1	Total Shipping & Handling Charges	38.71	38.71
1	Shop Supplies @ 2% of Invoice Total	45.14	45.14
	State of Ohio	6.75%	133.90
		Total	\$2,436.17