

INVOICE

Date: 09/21/2017

1978 Mercedes-Benz - 450SL -

Lic # :AV16290 - SC

Odometer In : 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Thermostat Kit (MB3-5) 116 200 00 15	1.00	48.95	48.95	COOLANT LEAK,	0.00
Radiator Hose-Lower 107 501 00 82	1.00	26.40	26.40	WATER PUMP - Remove & Replace - All Applicable Models	595.49
Radiator Hose-Upper 116 501 34 82	1.00	21.12	21.12	BRAKE FLUID SERVICE FLUSH / BLEED BRAKE HYDRAULIC SYSTEM INCLUDING ABS	73.95
Water Pump - Without Housing 117 200 38 01	1.00	86.95	86.95	Hazardous Materials	33.47
A/C Idler Pulley 116 130 04 60	1.00	124.72	124.72		
Belt - A/C 259341	1.00	43.72	43.72		
Belt - Fan & Power Steering 257470	2.00	44.34	88.68		
Belt - Air Pump 257345	1.00	32.28	32.28		
Belt - Alternator 257395	1.00	37.47	37.47		
BRAKE FLUID DOT4	2.00	6.00	12.00		
Shop Supplies			26.11		

[Recommendations]

TUNE UP AND VALVE COVER GASKETS \$999

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	669.44
Parts:	548.40
HazMat:	33.47
SubTotal:	1,251.31
Tax:	43.87
Total:	1,295.18
Bal Due:	\$0.00

[Payments - Visa - \$1,295.18]
 Vehicle Received: 9/14/2017

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____

MILESS 100442

77 MERC 450SL

Vin# 12 046585

1 used Transistor Ignition Box	cost	188 ⁰⁰
1 reb. Fuel distributor	cost	890 ⁰⁰
1 reb. Warmup Compensator	cost	485 ⁰⁰
8 Bosch Sp. Plugs		54 ⁰⁰
8 Fuel injectors W4950 (79 ⁰⁴)		396 ⁰⁰
8 Injector Seals		24 ⁸⁰
1 Fuel filter and Fuel pump (409)		342.80
1 org. Dist. Ignitor Cap (115)	cost	65.60
1 org. Ignitor Retar (54)	cost	22.90
1 org. Ignitor Resistor 0.4R	cost	36.00
1 org. Ignitor Resistor 0.6R	cost	42.90
1 org. Coil	cost	80.40
1 Master Brake Cylinder (185)		105 ⁰⁰
1 Vac. Filter hose		13 ⁵⁰
1 Vac. Ign. hose		9 ²⁵
1 Vac. Filter hose		14. ⁰¹
1 left Tierod Assembly		135.29
1 right " "		135.29
1 center Drag link		90 ³⁵
1 Steering Shock		60 ²⁹
Misc. Parts (2 oilchangers)		31 ⁰⁰
Fuel		76 ¹⁵
Front end alignment		79. ⁰⁰
		206 ¹⁵

check 1275
 Paid in full
 PARTS and TAX 1850.40
 Labor (850) 1400.00
 Total \$ 3250.40

	3198.38
TAX	253.87
	3444.25
	206.15
	3650.40
	1800.00
	1850.40