

## HQ Engineering

125 S Pine St  
San Gabriel, CA 91776  
+1 6263858171  
hqengineering88@gmail.com



## INVOICE

BILL TO



INVOICE 1061  
DATE 11/25/2021  
DUE DATE 12/25/2021

DATE	DESCRIPTION	QTY	RATE	AMOUNT
	HQ550 3.0 NSX engine build Cometic / OEM MLS head gaskets New valve seats Hone and bore New LMA's Deck / resurfaced head Valve adjustment Valve cover gasket set Racing spark plugs Timing belt kit, water pump, tensioners, cam seals Oil pan gasket, o-rings, rear main seal Brand new Oil Pump gears WPC Treated (Toda add \$850) Rod and main bearings (WPC treated) Custom pistons WPC treated Micro-polished and modded crank Dynamic Balanced rotating assembly Engine oil, coolant, misc. fluids Oil pan baffle ARP head studs ARP rod bolts Titanium retainers and dual valve springs Time Serts	1	3,500.00	3,500.00T
	Engine building Complete engine tear down, assembly and R&I	1	8,350.00	8,350.00
	OEM Honda Crankshaft Crankshaft modify & treated (old crank has 3 spun rod journals)	1	1,900.00	1,900.00
	Connecting Rods Used Connecting Rod	3	80.00	240.00
	Bare Short block exchange Engine cylinder sleeve beyond serviceable limits	1	500.00	500.00
	Aftermarket lighten flyhweel NA1 T3 Used lightweight flywheel	1	350.00	350.00
	Pride V2 headers Pride V2 headers w/adapters	1	1,150.00	1,150.00T
	Pride Resonated test pipes Pride resonated test pipes 91-94	1	300.00	300.00T

Aftermarkert Fuel Pump	Walbro 255 fuel pump R&I	1	120.00	120.00T
Fuel Pump Install	Fuel Tank R&I	1	130.00	130.00
Transmission rebuild kit 91-96	Installed and Rebuilt 5 Speed transmission. (Core exchange previous transmission casing completely cracked at lower tranny mount)	1	3,000.00	3,000.00
Clutch Master Cylinder	46920-SL0-A01 Clutch Master	1	130.00	130.00T
Clutch Master & Slave Install	R&I Clutch Master and Slave Cylinder	1	375.00	375.00
NSX KW V3 (new)	91-05 NSX KW V3 Coilover set	1	2,500.00	2,500.00T
Stance Cup kit front & Rear	Stance cup kit front & rear cup kit install with Oem Honda panel switches	1	1,150.00	1,150.00T
Stance Cup kit install	Front cup kit installed	1	750.00	750.00
Cup Kit Install Labor	Rear cup kit install (customer added after kw's were installed)	1	750.00	750.00
Comptech exhaust	Used Comptech exhaust	1	700.00	700.00
Rear Glass Struts	74820-SL0-315 Rear Glass Struts	1	150.00	150.00T
Trunk Struts	74872-SL0-305 Trunk Struts	1	150.00	150.00T
Steering wheel & Hub Install	Works Bell hub and Steering wheel install	1	150.00	150.00
Clutch Slave Cylinder	46930-SL0-003 Clutch Slave	1	95.00	95.00T
Alignment (deleted)	Front wheel computer alignment	1	100.00	100.00
Electrical diagnose and repair	Multiple shorts, repair grounds, remove existing harness and repair underdash	1	700.00	700.00
Car Audio Install	full audio install, parts provided by customer	1	500.00	500.00
Window Regulator Passenger	72210-SL0-A02 Passenger & 72250-SL0-A02 Driver window regulators	1	850.00	850.00T
Window Regulator Install	Clean Rails and Install Window Regulator	2	350.00	700.00
CCU Repair	Brian K CCU repair R&I with shipping	1	350.00	350.00
Tire mount & Balance	Drop off tires for mount & balance	1	80.00	80.00
Smog diagnose	Diagnose failed smog & repair (bad EGR )	1	250.00	250.00
Science of Speed	Sos door speaker panel kit Hushmat Ultra sound dampening Sos double din head unit bracket Sos 7" IPS LCD screen & mounting kit	1	470.00	470.00T
Alarm System	Viper Alarm Model 3305V	1	140.00	140.00T
Alarm System Install	Removal Old Alarm System and Install Viper Alarm System	1	300.00	300.00
Electrical Diagnostic	multiple shorts in chassis harness	3	100.00	300.00
HID Kit Onex	HID ONEX 5K Install	1	150.00	150.00
Clock Spring	Used clock spring R&I	1	525.00	525.00

Gasoline	91 Octane full tank	1	75.00	75.00
Starter Rebuilt	Rebuilt Starter R&I	1	150.00	150.00
Key Cylinder Switch	OEM Key Cylinder Ignition switch R&I	1	120.00	120.00
AC condenser fan	80151-SL0-A01 AC condenser fan	2	270.00	540.00T
AC Compressor Denso	471-1424 Denso AC Compressor	1	250.00	250.00T
AC Compressor Install	AC Compressor R&I	1	150.00	150.00
AC condenser fan install	AC condenser fan install	2	80.00	160.00
AC Flush & Charge	AC Flushed & R134A Freon Charged, Changed out AC O Rings	1	350.00	350.00
AC Expansion Valve	80220-SL0-901 Expansion Valve	1	120.00	120.00T
AC Expansion Valve Install	Expansion Valve install (Customer Low side valve connection is seized, remove unit to tap new threads)	1	800.00	800.00

1991 Acura Nsx  
JH4NA115XMT002196  
89046

Deposited 7k on  
Deposited \$9700 on 12/21/21  
Deposited \$9710.51 on 1/20/22

SUBTOTAL	34,570.00
TAX	1,190.54
TOTAL	35,760.54
BALANCE DUE	<b>\$35,760.54</b>