

**A-Z MOTORS**  
 27521 GRATIOT AVE.  
 ROSEVILLE, MI. 48066  
 Phone: 586-250-8877

INVOICE

**8805**

**MICHIGAN REGISTRATION: F167786**

**Proposed completion date: 11/29/2024**

**INVOICE FROM HISTORY**

Printed Date: 07/07/2025

**Work Completed: 12/30/2024**

1983 Mercedes-Benz - 300D - 3L, In-Line5 (183CI) VIN(Not Availa

Lic #: BIMBA - MI

Odometer In : 100

Cell:

VIN #: WDBAB33A3 **DB016397**

Cust ID : 2649

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Transmission Assembly 250K 6 MONTHS P ONLY	1.00	1400.00	1400.00	NEEDS A TRANSMISSION ASSEMBLY TRANSMISSION ASSEMBLY REMOVE & REPLACE	945.00
Valvoline ATF+4 Automatic Transmission Fluid 1 Qt 822348	8.00	18.50	148.00	NEEDS BOTH OUTER TIE ROD ENDS BOTH OUTER TIE ROD ENDS REMOVE & REPLACE	105.00
Automatic Transmission Filter (Filter Only) 1262770295	1.00	43.45	43.45	NEEDS BOTH INNER TIE ROD ENDS BOTH INNER TIE ROD ENDS REMOVE & REPLACE	105.00
Automatic Transmission Oil Pan Gasket 1262711180	1.00	17.99	17.99	NEEDS BOTH FRONT BRAKES PADS AND ROTORS FRONT BRAKES PADS AND ROTORS REMOVE & REPLACE	315.00
Steering Tie Rod End Assembly 1233301803	1.00	17.99	17.99	NEEDS BOTH REAR BRAKES PADS AND ROTORS BOTH REAR BRAKES PADS AND ROTORS REMOVE & REPLACE	262.50
Disc Brake Pad Set 001420062041	2.00	58.00	116.00	NEEDS ENGINE OIL CHANGE	52.50
Disc Brake Rotor 1234210012	1.00	53.70	53.70	CHANGED ENGINE OIL AND FILTER NEEDS A BRAKE FLUID FLUSH	105.00
Disc Brake Pad Wear Sensor 1405401217	2.00	103.00	206.00	PERFORMED A BRAKE FLUID FLUSH AND POWER BLEED BRAKES NEEDS A WHEEL ALIGNMENT	125.00
Rear Disc Brake Pad Set 0054204520	2.00	13.99	27.98	PERFORMED A WHEEL ALIGNMENT	210.00
Disc Brake Rotor Rear 126423001264	1.00	58.99	58.99	COSTUMER IS ADVISED ENGINE IS LEAKING OIL. COSTUMER IS RECOMMENDED TO REPLACE VALVE COVER GASKETS (LEAKING ENGINE OIL) VALVE COVER GASKETS REMOVE & REPLACE	105.00
Oil Filter OX78D	2.00	58.00	116.00	COSTUMER ADVISED NEED TO STEAM CLEAN THE ENGINE POST VALVE COVER GASKET REPLACEMENT AND CHECK FOR OTHER LEAKS STEAM CLEAN ENGINE ASSEMBLY	0.00
Engine Oil SAE 5W-20	1.00	39.98	39.98	COSTUMER IS RECOMMENDED A FUEL ADDITIVE ADDED DIESEL FUEL ADDITIVE TO PREVENT GELLING AND FUEL FILTER ICING	210.00
OIL ADDITVE MOA	1.00	15.99	15.99	COSTUMER REQUESTED TO REMOVE ALL 4 DOOR WINDOW TINTS	0.00
Brake Fluid BGF	1.00	25.00	25.00	ALL 4 DOOR WINDOW TINTS REMOVED PER COSTUMERS REQUEST	0.00
Engine Valve Cover Gasket 6170160180	1.00	22.50	22.50	PERFORMED A BATTERY TEST, VEHICLE NEEDS A BATTERY BATTERY REMOVE & REPLACE	10.00
Service Diesel Fuel Supplement Plus 1026	1.00	26.99	26.99	Hazardous Materials	
Battery - NAPA Legend Professional - OE Exact Fit 7549	1.00	186.50	186.50		
Shop Supplies			25.00		

**A-Z MOTORS**  
 27521 GRATIOT AVE.  
 ROSEVILLE, MI. 48066  
 Phone: 586-250-8877

INVOICE

**8805**

**MICHIGAN REGISTRATION: F167786**

**Proposed completion date: 11/29/2024**

**INVOICE FROM HISTORY**

Printed Date: 07/07/2025

**Work Completed: 12/30/2024**

1983 Mercedes-Benz - 300D - 3L, In-Line5 (183CI) VIN(Not Availa

Lic # : BIMBA - MI

Odometer In : 100

Cell:

VIN # : WDBAB33A3 **DB016397**

Cust ID : 2649

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Extended
------------------	----------	-----	------	-----	-------------------	----------

Original Estimate Amount: 5,320.91

YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTUER OR DISTRIBUTOR BECAUSE WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU.

Save \_\_\_\_\_ Discard \_\_\_\_\_ Signature \_\_\_\_\_

I hereby authorize the above repair work to be done along with the necessary materials, and hereby grant you and/or your employee permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. **X** \_\_\_\_\_

<b>Labor:</b>	<b>2,540.00</b>
<b>Parts:</b>	<b>2,614.07</b>
<b>Sublet:</b>	<b>0.00</b>
<b>Sub:</b>	<b>5,154.07</b>
<b>HazMat:</b>	<b>10.00</b>
<b>Tax:</b>	<b>156.84</b>
<b>Total:</b>	<b>\$5,320.91</b>
<b>Bal Due:</b>	<b>\$0.00</b>

Estimated Increased Total: \_\_\_\_\_ Authorized by: \_\_\_\_\_  
**\$** \_\_\_\_\_ **X** \_\_\_\_\_  
 Mechanic's Name & Michigan Certification Number  
 Repairs Performed by:  
 VORONENKO, OLEKSANDER M267685

-CERTIFICATION-  
 ALL REPAIRS AND PARTS LISTED WERE FURNISHED IN COMPLIANCE WITH THE MICHIGAN AUTO REPAIR ACT (P.A. 300) ALL PARTS ARE NEW UNLESS OTHERWISE STATED.

ALL REPAIRS PROPERLY COMPLETED  
 Company Authorized Representative:

**X** \_\_\_\_\_

[ Payments - Discover - \$5,320.91 ]