

**EURO TECH OF HOLLAND**

11058 Water Tower Court

Holland, MI. 49424

Phone - 616-393-7733 Fax - 616-393-7738

**Customer and Vehicle Report**

Print Date: 06/01/2026

**Vehicle: 1999 Porsche - Boxster, 2.5L,H6 (151CI) VIN(A)**

Average Daily Mileage: 32

Invoice: 061236, Posted On: 05/15/2024, SW: Roberts, Shane

Odometer in: 80,282 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
3.60	Cust states convertible top inop, can hear motor run but doesn't move. <b>Notes</b> - -- Tires at 7/32 fronts, 4/32RL, 7/32RR -Brake pads at about 6mm fronts, 7mm rears.			Jason Cox	3.60	500.00	500.00		138.76
0.50	Oil change. Change engine oil and oil filter. Check and if necessary top off all other engine compartment fluids. Check tire pressures (including spare tire). Check all exterior lamp operation. Visual (only) inspection of overall mechanical condition of vehicle.		Maintenance	Ben Fisher	0.50	14.95	14.95		138.76
-	5W-40 Full Synthetic	SYN	Fluids	Parts	9.00	10.87	97.83	17.65	
-	Oil Filter Kit w/ O-Ring	996 107 225 60	Engine Mechanical Repair	Parts	1.00	26.26	26.26	29.43	
	<b>Notes</b> - Verified complaint. Top releases, windows drop. Motor working in back when pressing button but nothing happens. No faults stored related to top. Voltage supply is good. Manually opened top to inspect. Actuated motor manually to check, not turning LH or RH mechanism. Inspected control rods and fitment, both OK (RH control rod is new). Found cables are broken/fatigue that go between motor and spin mechanism. Motor may have been binding. Spun mechanisms, no obstructions felt. Recommend replacing both cables, motor and realigning top drive units.								
2.40	CONVERTIBLE TOP MOTOR - Remove & Replace			Ben Fisher	2.40	333.02	333.02		138.76
-	Convertible Top Motor	986 624 117 01	Suspension	Parts	1.00	455.71	455.71	547.87	
4.80	CONVERTIBLE TOP ACTUATOR CABLE - Remove & Replace - Tensioning Rope,Both			Ben Fisher	4.80	666.05	666.05		138.76
-	Convertible Top Input Shaft	986 561 717 03	Electrical	Parts	2.00	90.30	180.60	108.54	
-	Spring Clip	987 561 717 03	Miscellaneous	Parts	2.00	8.75	17.50	8.25	
2.00	Realign Convertible Top			Ben Fisher	2.00	277.52	277.52		138.76

**Customer and Vehicle Report**

Print Date: 06/01/2026

**Vehicle: 1999 Porsche - Boxster, 2.5L,H6 (151CI) VIN(A)**

Average Daily Mileage: 32

Invoice: 061236, Posted On: 05/15/2024, SW: Roberts, Shane

Odometer in: 80,282 Odometer Out: 0

<u>Time</u>	<u>Description</u>	<u>Part No.</u>	<u>Category</u>	<u>Technician</u>	<u>Qty</u>	<u>Sale</u>	<u>Extd</u>	<u>Price</u>	<u>Rate</u>
2.00	CONVERTIBLE TOP TRANSMISSION GEAR - Remove and Replace - Both Sides			Ben Fisher	2.00	277.52	277.52		138.76
-	Convertible Top Trans. Gear -Left	987 561 179 GEAR	Miscellaneous	Parts	1.00	229.99	229.99	220.82	
-	Convertible Top Trans. Gear -Right	987 561 180 GEAR	Miscellaneous	Parts	1.00	229.99	229.99	216.52	
<b>Totals for Invoice:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		1,237.88	2,069.06	0.00	3,306.94	10.00	10.00	74.87	3,401.81
.....									
<b>Totals for Owner:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		1,237.88	2,069.06	0.00	3,306.94	10.00	10.00	74.87	3,401.81