

Wolt



PRODUCT SAFETY RECALL

16.02.2026



NAME: **LED Lamp**

BRAND: **Néonail**

Dear Customer,

There is a recall of the product on the Safety Gate portal ([details here](#)). The insulation of the transformer installed in the power supply housing is insufficient and there is no Y capacitor to protect it from an electrical breakdown. This may lead to electric shock.

Please do not use it if you have an affected product with the EAN **5903657800977**. Please contact support@wolt.com to get a refund or Wolt credit if you have an affected product.

From our side, we have taken all necessary steps to make sure all the affected products are no longer available on our platform. If you have any questions or concerns, please don't hesitate to contact support@wolt.com. We are here for you!

Best regards,
Wolt Support