

Skilyrði faggildingar / Terms of Accreditation**Viðauki 1** / Annex 1

Faggildingarnúmer:	33
Accreditation number:	
Tilvísunarnúmer	202207-10728
Reference number:	
Dagsetning:	08.08.2022
Date:	

1 Almennar upplýsingar / General information

Kröfur vegna faggildingar koma fram í eftirfarandi skjölum:

Requirements for the accreditation are in the following documents:

Lög nr. 24/2006 um faggildingu o.fl.	Laws no. 24/2006 on accreditation etc.
R01 Verklags- og leiðbeiningarreglur ISAC	R01e General Regulation ISAC
R02 Faggildingarmerki og tilvísanir í faggildingu	R02e Accreditation symbol and reference to accreditation
Reglugerð 678/2009 um raforkuvirki	Regulation 678/2009 Electrical installations
ÍST EN ISO/IEC 17020:2012	ÍST EN ISO/IEC 17020:2012
Reglur um skoðun gefnar út af Húsnæðis- og mannvirkjastofnun	Inspection rules issued by the Housing and Construction Authority

2 Aðrar upplýsingar / Other information**2.1 Samræmismatsstofa** / Conformity Assessment Body

BSI á Íslandi ehf.

Kennitala / ID no: 551104-2140

www.bsiaislandi.is

2.2 Tengiliður / Contact person

Edda Sif Oddsdóttir

e-mail: edda@bsiaislandi.is

2.3 Aðsetur aðalskrifstofu / Head office address

Skútuvogi 1d

104 Reykjavík

Iceland

2.4 Útibú samræmismatsstofu / Locations of Conformity Assessment Body

Faggilt samræmismat fer fram á eftirtöldum stöðum:

Accredited Conformity Assessment is performed in the following locations:

Skoðun er framkvæmd á vettvangi.

Inspection is carried out on-site.

Endir

End