

ISAC – Faggildingarsvið Hugverkastofunnar

Viðauki við faggildingarskírteini nr. 30

Annex to Accreditation Certificate no. 30

Tilvísunarnúmer

Reference number

202401-0440

Dagsetning

Date of decision

2024-10-09



30

Skoðun

ISO/IEC 17020

BSI á Íslandi ehf, kt. 551104-2140, Skútuvogur 1d, 104 Reykjavík

er faggilt skoðunarstofa af gerð A samkvæmt kröfum **ÍST EN ISO/IEC 17020:2012**

Is an accredited inspection body of type A according to the requirements of ÍST EN ISO/IEC 17020:2012

Faggilding upphaflega veitt Accreditation initially granted	Síðasta endurmat Last re-assessment	Næsta endurmat Next re-assessment
2011-03-10	2024-06-03	2028-06-03

Skilyrði og umfang faggildingar

Terms and scope of accreditation

Svið Field of inspection	Tegund og gildissvið Type and range	Faggildingarkröfur Accreditation requirements
Skip Ships	Aðalskoðun skipa og báta allt að 15 metrum Annual main inspection of ships and boats up to 15 meters Aðalskoðun skip og báta 15 metrum og lengri Annual main inspection of ships and boats longer than 15 meters	R01 Verklags- og leiðbeiningareglur ISAC R01 General regulation ISAC R02 Faggildingarmerki og tilvísanir í faggildingu R02 Accreditation symbol and reference to accreditation Reglugerð 94/2004 um starfshætti faggiltra skoðunarstofa skipa og búnaðar Regulation 94/2004 on the operation of accredited inspection bodies of ships and equipment Reglugerð 466/2023 um skoðanir á skipum og búnaði þeirra Regulation 466/2023 on inspections of ships and their equipment Skoðunarhandbækur Samgöngustofu Inspection Manuals from the Icelandic Transport Authority

Útibú:

Locations

N/A

Faggilt samræmismat fer fram á eftirtöldum stöðum:

Accredited Conformity Assessment is performed in the following locations:

Aðalskrifstofa samræmismatsstofu.

Skoðun er framkvæmd á vettvangi.

Inspection is carried out on-site.

Endir

End