Lanes Group

Rapid Response at Seascale



Lanes Group Case Study

October 2026



A Challenge Below Ground

Lanes Group recently delivered an emergency repair following the collapse of a **600mm outfall at Seascale**. Through specialist engineering expertise, the team safely restored the asset and reopened the area within just **five days.**

Working Against the Clock

Following the sudden collapse of the outfall, immediate action was required to make the area safe and assess the extent of the damage. Specialist teams carried out two days of 24/7 cleaning and CCTV investigations to remove debris from the collapsed outfall and provide the information needed to plan a permanent repair.





Back Open in Five Days

Working around the clock, specialist teams excavated and exposed the damaged asset, allowing a permanent repair to be completed using bespoke VJ clamps manufactured at short notice. Once the repair was finished, the site was fully reinstated and the car park reopened ahead of the Christmas weekend.