



**WORTHINGTON**  
INDUSTRIES


*Learn how our Material Support & Solutions team solved this customer material issue:*

## CRACKING ON DRAWN PART




### THE PROBLEM:

The customer experienced cracking on a drawn part which led to excess scrap and material waste.



### THE ANALYSIS:

Using our state-of-the-art in-house lab, our Material Solutions team completed chemical composition and mechanical property analyses.



### THE SOLUTION:

From the analyses, Worthington provided the customer with a property guidelines report to ensure proper forming.

### THE ACTION:

*When the root cause of intermittent cracking of formed parts can't be identified, contact the Material Support & Solution team at Worthington.*

**CALL US AT 1-800-944-2255**

WORTHINGTON INDUSTRIES. 200 WEST OLD WILSON BRIDGE ROAD COLUMBUS, OH 43085