




Learn how our Material Support & Solutions team solved this customer material issue:

IMPROVED STEEL GRADE



THE PROBLEM:

The customer was experiencing cracking and forming issues on a drawn part, resulting in additional lubrication and tooling modifications at their expense.



THE ANALYSIS:

The Materials Support & Solution team at Worthington Industries analyzed the material properties and chemistry, as well as the resulting cracking.



THE SOLUTION:

From the analysis, the specified raw material did not meet forming needs. A raw material with leaner chemistry was trialed, and the cracking issues were eliminated.

THE ACTION:

When a new program and/or supplier material is not meeting expectations for part formation, contact the Materials Support & Solution team at Worthington.

CALL US AT 1-800-944-2255

WORTHINGTON INDUSTRIES. 200 WEST OLD WILSON BRIDGE ROAD COLUMBUS, OH 43085