



CREMORNE STREET LANDSLIP REMEDIATION

HERNE BAY, AUCKLAND, NEW ZEALAND



ROCKFALL PROTECTION BARRIER INSTALLATION FOLLOWING AVALANCHE EVENT

PROJECT OVERVIEW:

After prolonged periods of heavy rain in the Auckland region significant slips occurred and put a variety of private & public infrastructure at risk of loss or damage. Geovert were contracted to complete emergency slip repairs to prevent continued slope failures by using technical access to soil nail and TECCO mesh the affected slope.

SOLUTION:

Once stabilised a mini-piled & anchored retaining wall were constructed to reclaim lost land and prevent further failures. Geovert worked closely with the consultants on a bespoke design & build solution to satisfy the engineers and client as no cranes, concrete trucks or vehicles could access the site, all materials were placed by helicopter.

Services related to this project

rope access
soil nails
rock bolts

More information is available online at www.geovert.com