



Monthly Fire Extinguisher Inspection

Flower Blooms Ent / MNO0210-23 / 1 Feb 2023 / Krist Haynes

Complete

Score	8 / 12 (66.67%)	Flagged items	4	Actions	0
-------	-----------------	---------------	---	---------	---

Client / Site

Flower Blooms Ent

Reference Number

MNO0210-23

Conducted on

1 Feb 2023 11:10 PST

Inspected by

Krist Haynes

Location

3CC7+57 Nattai NSW, Australia
(-33.9295256, 150.4131534)

Flagged items

4 flagged

Monthly Inspection / Fire Extinguisher Inspection / Fire Extinguisher / Fire Extinguisher 1 / Fire Extinguisher Inspection

2. Mounted in an easily accessible place, no debris or material stacked in front of it.

Non-Compliant

Monthly Inspection / Fire Extinguisher Inspection / Fire Extinguisher / Fire Extinguisher 1 / Fire Extinguisher Inspection

5. Handle is intact and not bent or broken.

Non-Compliant

The handle is broken

Monthly Inspection / Fire Extinguisher Inspection / Fire Extinguisher / Fire Extinguisher 1 / Fire Extinguisher Inspection

7. Discharge hoses/nozzle is in good shape and not clogged, cracked, or broken

Non-Compliant

Monthly Inspection / Fire Extinguisher Inspection / Fire Extinguisher / Fire Extinguisher 1 / Fire Extinguisher Inspection

10. Dust and wipe down the extinguisher

Non-Compliant

Monthly Inspection	4 flagged, 8 / 12 (66.67%)
Fire Extinguisher Inspection	4 flagged, 8 / 12 (66.67%)

Click "Add Fire Extinguisher" to list equipment available in the area. You may add multiple items.

Fire Extinguisher	4 flagged, 8 / 12 (66.67%)
Fire Extinguisher 1	4 flagged, 8 / 12 (66.67%)
Fire Extinguisher Information	

Location of Extinguisher

Behind the door

Serial No. of Extinguisher

1929391

Manufacture Date 2 Nov 2022 00:00 PST

Expiry Date 2 Nov 2032 00:00 PST

Type of Fire Extinguisher Dry Powder

Size (KG)

15

Rating ABC

Fire Extinguisher Inspection 4 flagged, 8 / 12 (66.67%)

1. Has a valid maintenance tag Compliant

2. Mounted in an easily accessible place, no debris or material stacked in front of it. Non-Compliant

3. Safety pin is in place and intact. Nothing else should be used in place of the pin. Compliant

REFERENCE: Safety pin is in place and intact
 [This is an example of how you can use iAuditor to include best practice reference images in your templates to assist with inspections]



4. Label is clear and extinguisher type and instructions can be read easily.

Compliant

5. Handle is intact and not bent or broken.

Non-Compliant

The handle is broken

6. Pressure gauge is in the green and is not damaged or showing "recharge"

Compliant

7. Discharge hoses/nozzle is in good shape and not clogged, cracked, or broken

Non-Compliant

8. Extinguisher was turned upside down at least three times (shaken) to make sure it is full.

Compliant

9. Location of extinguisher is easily identifiable by signs

Compliant

10. Dust and wipe down the extinguisher

Non-Compliant

11. Annual maintenance tag is signed and dated

Compliant

Take a photo of the annual maintenance tag



Photo 1

Overall condition of fire extinguisher

Pass

Completion

Write down observations

Although the result of this inspection is passed, there are a couple of non-compliance noted for this particular item.

State recommendations about the inspections here

Immediately rectify the items tagged as non-compliance and add a note to this inspection.

Name and Signature of Inspector

krist haynes

Krist Haynes
10 Feb 2023 16:07 PST

Media summary

FIRE EXTINGUISHER
INSPECTION RECORD

EXTINGUISHER NUMBER

	YEAR	YEAR
JANUARY		
FEBRUARY		
MARCH		
APRIL		
MAY		
JUNE		
JULY		
AUGUST		
SEPTEMBER		
OCTOBER		
NOVEMBER		
DECEMBER		

Photo 1