



Site Hazard Report

Complete

Score	0 / 3 (0%)	Flagged items	0	Actions	3
Site conducted	Unanswered				
Audit Title	Kensington 2 Project				
Client / Site	Nexus Prime Corp				
Conducted on	7 Mar 2023 11:30 PST				
Prepared by	Scott Rolf				
Location	174 James Boulevard, Kensington				

Actions

3 actions

Audit / Hazard observations / Hazard / Hazard 1

Assign corrective action?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 14 Mar 2023 11:43 PST | Created by: SafetyCulture Staff

Ensure that all employees are provided safety harnesses, and other prescribed PPEs.

Audit / Hazard observations / Hazard / Hazard 2

Assign corrective action?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 14 Mar 2023 11:44 PST | Created by: SafetyCulture Staff

Ensure that tools, especially when not in use, are sorted and put in an organized box/shelf.

Audit / Hazard observations / Hazard / Hazard 3

Assign corrective action?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 14 Mar 2023 11:45 PST | Created by: SafetyCulture Staff

Inspect all PPEs and replace damaged ones immediately.

INSTRUCTIONS

- 1. Add a safety hazard observation by clicking on "Add Hazard"
- 2. Enter description of hazard
- 3. Create a Corrective Action by clicking on the paperclip icon and clicking "Action", then enter description, assign to member, set priority and due date
- 4. Take relevant photos, enter location and date
- 5. Complete audit by providing digital signature
- 6. Share your report by exporting as PDF, Word, Excel or Web Link



Hazard observations

3 actions, 0 / 3 (0%)

Add Hazard Observation

Hazard

3 actions, 0 / 3 (0%)

Hazard 1

1 action, 0 / 1 (0%)

Description/ Observation

Found someone working at a height of approximately 20 feet without a safety harness.

Take a photo



Photo 1

Location

3rd level, building 1

Assign corrective action?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 14 Mar 2023 11:43 PST | Created by: SafetyCulture Staff

Ensure that all employees are provided safety harnesses, and other prescribed PPEs.

Click on paperclip icon above, click "Action", provide description, assign to responsible person (either within or outside your organisation), set priority and due date

Hazard 2

1 action, 0 / 1 (0%)

Description/ Observation

Tools and equipment are thrown together in a box with no organization.

Take a photo




Photo 2

Location

6th level, Main Conference Room

Assign corrective action?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 14 Mar 2023 11:44 PST | Created by: SafetyCulture Staff

Ensure that tools, especially when not in use, are sorted and put in an organized box/shelf.

Click on paperclip icon above, click "Action", provide description, assign to responsible person (either within or outside your organisation), set priority and due date

Hazard 3

1 action, 0 / 1 (0%)

Description/ Observation

Found a damaged hard hat that should no longer be in use.

Take a photo



Photo 3

Location

Parking Lot, Building 2

Assign corrective action?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 14 Mar 2023 11:45 PST | Created by: SafetyCulture Staff

Inspect all PPEs and replace damaged ones immediately.

Click on paperclip icon above, click "Action", provide description, assign to responsible person (either within or outside your organisation), set priority and due date

Completion

Comments

Found some major safety compliance issues. I have assigned corrective actions to the appropriate person and will be updated once these recommended actions are completed.

Inspected by:



Scott Rolf
7 Mar 2023 11:45 PST

Media summary



PHOTO 1



PHOTO 2



Notes