



Vehicle Condition Report Template

2 Jun 2023 / Dani Cheadle

Complete

Score	0 / 0 (0%)	Flagged items	2	Actions	2
Conducted on	2 Jun 2023 16:00 PST				
Prepared by	Dani Cheadle				
Location	Boston, MA, USA (42.3600825, -71.0588801)				
Purpose of Vehicle Assessment	For Rent				

Flagged items & Actions

2 flagged, 2 actions

Flagged items

2 flagged, 0 actions

Vehicle Condition Report / Exterior Assessment

Paint Condition

Poor Condition

Vehicle Condition Report / Interior Assessment

Seats

Poor Condition

Other actions

2 actions

Vehicle Condition Report / Exterior Assessment

Describe the damage/issue including its location and attach photo/s.

Scratches and chipped paint on the left back part of the car



Photo 1

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 9 Jun 2023 14:04 PST | Created by: SafetyCulture Staff

Repair chipped paint and fix scratches on the blue Toyota Camry.

Vehicle Condition Report / Interior Assessment

Describe the damage/issue including its location and attach photo/s.

Damaged driver's seat



Photo 2

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 9 Jun 2023 14:05 PST | Created by: SafetyCulture Staff

Replace damaged driver's seat.

Vehicle Condition Report		2 flagged, 2 actions
Vehicle Information		
Make	Toyota	
Model	Camry (Blue)	
Year	2019	
VIN (Vehicle Identification Number)	1HGCM82633A123456	
License Plate Number	ABC123	
Mileage	50,000	
Exterior Assessment		1 flagged, 1 action
Paint Condition	Poor Condition	
Describe the damage/issue including its location and attach photo/s.		
Scratches and chipped paint on the left back part of the car		
		
Photo 1		
To do Assignee: SafetyCulture Staff Priority: Low Due: 9 Jun 2023 14:04 PST Created by: SafetyCulture Staff		
Repair chipped paint and fix scratches on the blue Toyota Camry.		
Body Panels	Excellent Condition	
Glass and Windshield	Excellent Condition	
Lights	Excellent Condition	
Wipers	Excellent Condition	
Bumpers and Grilles	Excellent Condition	
Interior Assessment		1 flagged, 1 action
Seats	Poor Condition	

Describe the damage/issue including its location and attach photo/s.

Damaged driver's seat



Photo 2

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 9 Jun 2023 14:05 PST | Created by: SafetyCulture Staff

Replace damaged driver's seat.

Upholstery

Very Good Condition

Aside from the damaged driver's seat, the rest of the car seats are in very good condition.

Dashboard and Controls

Excellent Condition

Carpets

Very Good Condition

Odor

Very Good Condition

Mechanical Assessment

Engine

Excellent Condition

Transmission

Excellent Condition

Brakes

Excellent Condition

Tires

Very Good Condition

Suspension

Excellent Condition

Additional Details

Fuel Level

3/4 tank

Tire Pressure

Front Left - 34 psi, Front Right - 34 psi, Rear Left - 33 psi, Rear Right - 33 psi

Existing Damages

- Scratches and chipped paint on the left back part of the car
- Damaged driver's seat

Completion

Other Observations

Overall, the vehicle is fairly in good condition apart from the needed repairs and replacements to be done this weekend.

The Toyota Camry is scheduled to be rented two Mondays from now (June 12), so the repairs and replacements must be completed before next week starts.

Assessor's Name and Signature



Dani Cheadle
2 Jun 2023 16:49 PST

Vehicle Owner's/Authorized Representative's Name and Signature



Clyde Morris
2 Jun 2023 16:50 PST

Media summary



Photo 1



Photo 2