



Emergency Lighting and Exit Sign Inspection Checklist

Joe and Jack Incorporation / 5 May 2023 / John James Marz

Complete

Score	5 / 6 (83.33%)	Flagged items	2	Actions	0
Client	Joe and Jack Incorporation				
Conducted on (Date and Time)	5 May 2023 08:55 PST				
Inspected by	John James Marz				
Address	Manor Grove Farm, 811 Undergrowth Way, Moffat US2 9EI, UK				

Flagged items

2 flagged

Audit / Emergency Light Checks / Emergency Light / Emergency Light 1

Test results: Battery

Needs Action

Faulty battery indicator



Photo 1

Audit / Emergency Light Checks / Emergency Light / Emergency Light 1

Overall Assessment

Fail

Audit	2 flagged, 5 / 6 (83.33%)
Emergency Light Checks	2 flagged, 5 / 6 (83.33%)
Emergency light inspection? Click "Add"	
Emergency Light	2 flagged, 5 / 6 (83.33%)
Emergency Light 1	2 flagged, 2 / 3 (66.67%)
Time on	5 May 2023 01:00 PST
Emergency light reference number	EL-12345
Emergency light location	Conference Room 1
Test results: Physical condition of equipment	OK
Test results: Battery	Needs Action
Faulty battery indicator	
	
Photo 1	
Test results: luminous	OK
Time off	5 May 2023 01:05 PST
Overall Assessment	Fail
Emergency Light 2	3 / 3 (100%)
Time on	5 May 2023 01:30 PST
Emergency light reference number	EL-12347
Emergency light location	Fire exit
Test results: Physical condition of equipment	OK
Test results: Battery	OK
Test results: luminous	OK
Time off	5 May 2023 01:35 PST

Overall Assessment

Pass

Exit sign in good working condition

Completion

Recommendations

Change faulty battery immediately

Maintenance Inspector (Full Name and Signature)



John James Marz
5 May 2023 09:00 PST

Media summary



Photo 1