



Malcolm Excavating Retirement Auction, CAN - Sep 28, 2026

Lot #	Details	Lot #	Details
1	2022 Case IH Magnum 250 4WD Tractor S/N: JJAMG250HNRK01995 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, CVT, Left Hand Reverser, AFS Pro 1200 Display, 250 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, Suspended Front Axle, LED Lights, 5 Rear Remotes, ISOBUS, Exterior 3-Point Hitch Controls, Big 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar, 650/60R34 Front Tires, 900/60R42 Rear Tires, Rear Wheel Weights Usage: 1,395 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:00 PM EDT Asset located in: Burgessville, ON, CAN	3	1967 John Deere 400 Industrial Tractor S/N: 055651T C/W: John Deere E7400 Loader, LED Lights, Rear Weights, Concrete Weight, 7.50-16 Front Tires, 16/70-24 Rear Tires Usage: 2,204 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:02 PM EDT Asset located in: Burgessville, ON, CAN
2	2021 Case IH Magnum 250 4WD Tractor S/N: JJAMG250AMRK02687 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, CVT, Left Hand Reverser, AFS Pro 1200 Display, 250 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, Suspended Front Axle, LED Lights, 5 Rear Remotes, Power Beyond, Load Sensing, ISOBUS, Exterior 3-Point Hitch Controls, Big 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar, 650/60R34 Front Tires, 900/60R42 Rear Tires, Rear Wheel Weights Usage: 1,927 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:01 PM EDT Asset located in: Burgessville, ON, CAN	4	Leyland 2WD Tractor S/N: Not Available C/W: 10 Forward 10 Reverse, Manual Transmission, Allied 660 Loader w/Joystick, 72 in Bucket, HID Lights, 540 PTO, Trailer Hitch, Swing Drawbar, 7.50-16 Front Tires, 18.4x30 Rear Tires Usage: 3,425 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:03 PM EDT Asset located in: Burgessville, ON, CAN
		5	1956 John Deere 420 2WD Antique Tractor S/N: 104014 C/W: 4 Forward 1 Reverse, Gasoline Engine, Electric Start, 540 PTO, Drawbar, 6.00-16 Front Tires, 11.-34 Rear Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:04 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
6	1954 John Deere 40-S 2WD Antique Tractor S/N: 67505 C/W: 4 Forward 1 Reverse, Gasoline Engine, Electric Start, 540 PTO, Drawbar, 6.00-16 Front Tires, 12.4-24 Rear Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:05 PM EDT Asset located in: Burgessville, ON, CAN	9	John Deere 2WD Narrow Front Antique Tractor S/N: Not Available C/W: 4 Forward 1 Reverse, Gasoline Engine, Electric Start, 540 PTO, Drawbar, 5.00-15 Front Tires, 15.5-38 Rear Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:08 PM EDT Asset located in: Burgessville, ON, CAN
7	1942 John Deere H 2WD Narrow Front Row Crop Antique Tractor S/N: 43278 C/W: 3 Forward 1 Reverse, Gasoline Engine, Hand Crank Start, 540 PTO, Drawbar, 4-15 Front Tires, 9.5- 32 Rear Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:06 PM EDT Asset located in: Burgessville, ON, CAN	10	1944 Farmall M 2WD Narrow Front Row Crop Antique Tractor S/N: FBK74627 C/W: 5 Forward 1 Reverse, Manual Transmission, Gasoline Engine, Electric Start, 540 PTO, Drawbar, 6.00-14 Front Tires, 12.4/11-38 Rear Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:09 PM EDT Asset located in: Burgessville, ON, CAN
8	John Deere 2WD Narrow Front Antique Tractor S/N: Not Available C/W: 6 Forward 1 Reverse, Gasoline Engine, Electric Start, 1 Rear Remotes, 540 PTO, Drawbar, 6.00-16 Front Tires, 12.4-38 Rear Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:07 PM EDT Asset located in: Burgessville, ON, CAN	11	Massey Ferguson MF880 3-Point 5 Bottom Breaking Plow S/N: 003970 C/W: 31 in Interbody Clearance, Coulters, Auto-Reset Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:10 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
12	Miller 22 ft Offset Breaking Disc S/N: Not Available C/W: 26 in Shallow Face Front Discs, 23 in Wave Edge Rear Discs, 11 in Spacing, Hitch Leveling Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:11 PM EDT Asset located in: Burgessville, ON, CAN	16	S/A Turntable Bale Wagon S/N: Not Available C/W: 235/75R15 Tires, 15 ft x 8 ft Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:15 PM EDT Asset located in: Burgessville, ON, CAN
13	22 ft Packer S/N: Not Available C/W: (1) 12 ft, (2) 5 ft sections Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:12 PM EDT Asset located in: Burgessville, ON, CAN	17	2021 Kubota SVL97-2 Compact Track Loader S/N: KBCZ064CVM1B61348 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Electric Kit, Hydraulic Coupler, 72 in Bucket Usage: 1,795 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:16 PM EDT Asset located in: Burgessville, ON, CAN
14	2010 Unverferth 235 235 bu T/A Grain Wagon S/N: D53 000 114 C/W: 6 in Hydraulic Driven Auger, 235/75R15 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:13 PM EDT Asset located in: Burgessville, ON, CAN	18	2021 Bobcat T76 Two-Speed Compact Track Loader S/N: B4CE13779 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, Rear View Camera, 2020 US EPA Label, 15.5 in Track Belts, Electric Kit, Hydraulic Coupler, 78 in Bucket Usage: 2,174 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:17 PM EDT Asset located in: Burgessville, ON, CAN
15	T/A Grain Wagon S/N: Not Available C/W: Hydraulic Driven Auger, 225/75R15 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:14 PM EDT Asset located in: Burgessville, ON, CAN		

Lot #	Details	Lot #	Details
19	2023 Kubota SVL75-2 Compact Track Loader S/N: KBCZ052CLN1L72449 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Self Leveling, Rear View Camera, 15.5 in Track Belts, Electric Kit, Hydraulic Coupler, 80 in Bucket Usage: 937 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:18 PM EDT Asset located in: Burgessville, ON, CAN	22	2010 Cat 420E IT 4x4 Backhoe Loader S/N: CAT0420EHDAN00373 C/W: Enclosed Cab, Air Conditioner, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, Auxiliary Hydraulics, Front Hydraulic Coupler, 92 in Loader Bucket, Extendable Stick, Rear Quick Coupler, 32 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 6,258 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:21 PM EDT Asset located in: Burgessville, ON, CAN
20	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P19187 C/W: Open Operator Station, Tier 4, 2021 US EPA Label, CARB Compliant, 7 in Track Belts, Electric Kit, Manual Quick Coupler, 35.5 in Bucket Usage: 389 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:19 PM EDT Asset located in: Burgessville, ON, CAN	23	2009 Cat 966H Wheel Loader S/N: CAT0966HLA6D02385 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Ez-Scale On-Board Scale w /Printer, 125 in Bucket, Blade, Auto Lube, 26.5 R25 Tires Usage: 17,944 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:22 PM EDT Asset located in: Burgessville, ON, CAN
21	2018 Cat 430F2 IT 4x4 Backhoe Loader S/N: CAT0430FELYE00234 C/W: Enclosed Cab, Air Conditioner, Ride Control, Backhoe Pilot Controls, Powershift Transmission, Auxiliary Hydraulics, Front Hydraulic Coupler, 86.5 in Loader Bucket, Extendable Stick, Rear Quick Coupler, 35 in Backhoe Cleanup Bucket, Rear Auxiliary Hydraulics Usage: 2,007 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:20 PM EDT Asset located in: Burgessville, ON, CAN	24	2016 Cat 950K Wheel Loader S/N: CAT0950KHFER01166 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Traction Control, EZ Scale On-Board Scale w/Printer, Hydraulic Coupler, 114 in Bucket, Auto Lube, 23.5R25 Tires Usage: 12,361 Hr Notes: Deleted/Altered Emissions-Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Additional information available online Lot closing time: Mon, Sep 28, 01:23 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
25	2006 Cat 950G Wheel Loader S/N: CAT0950GVAXX02073 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, LoadRite On-Board Scale w/Printer, 2005 US EPA Label, Hydraulic Coupler, 107.5 in Bucket, 23.5R25 Tires Usage: 20,478 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:24 PM EDT Asset located in: Burgessville, ON, CAN	28	2018 JCB 427 HT Wheel Loader S/N: JCB4A5AEEJ2407733 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Traction Control, Auxiliary Hydraulics, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 2,372 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:27 PM EDT Asset located in: Burgessville, ON, CAN
26	2018 Cat 924K Wheel Loader S/N: CAT0924KTSNZ00686 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, Traction Control, 2017 US EPA Label, Engine Coolant Heater, Positive Air Shutoff, Auxiliary Hydraulics, Hydraulic Coupler, 99 in Bucket, 20.5R25 Tires Usage: 2,379 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:25 PM EDT Asset located in: Burgessville, ON, CAN	29	2014 JCB 427 HT Agri Wheel Loader S/N: JCB4270SJ02312109 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Traction Control, Auxiliary Hydraulics, Hydraulic Coupler, 2.3 m3 104 in Bucket, 20.5R25 Tires Usage: 6,763 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - TCU replaced March 2026 - Additional information available online Lot closing time: Mon, Sep 28, 01:28 PM EDT Asset located in: Burgessville, ON, CAN
27	2015 Cat 924K Wheel Loader S/N: CAT0924KEHJF00529 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, Traction Control, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: 3,188 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - This lot will be available for pickup on Monday, October 26th. The lot will be used for loadout, and additional machine hours will accrue during this time - Lot closing time: Mon, Sep 28, 01:26 PM EDT Asset located in: Burgessville, ON, CAN	30	2012 Cat D6T LGP Crawler Dozer S/N: CAT00D6TAKSB00351 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Trimble GCS900 Grade Control System, 162 in Wide PAT Blade, 31 in Single Grouser Track Shoes, SystemOne Undercarriage, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 9,704 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:29 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
31	2020 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KLEL703319 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, GRADE with 3D, Requires Diesel Exhaust Fluid, 136 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar, Trimble laser GPS Usage: 3,906 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:30 PM EDT Asset located in: Burgessville, ON, CAN	34	2001 John Deere 550H LT Crawler Dozer S/N: T0550HX901527 C/W: Open Operator Station, 105 in Wide PAT Blade, 17.5 in Single Grouser Track Shoes, Drawbar Usage: 12,419 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:33 PM EDT Asset located in: Burgessville, ON, CAN
32	2016 Cat D4K2 XL Crawler Dozer S/N: CAT00D4KEKM200269 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2015 US EPA Label, 107 in Wide PAT Blade, 18 in Single Grouser Track Shoes, Drawbar Usage: 6,966 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:31 PM EDT Asset located in: Burgessville, ON, CAN	35	2021 Hyundai HR70C-9 Smooth Drum Compactor S/N: 25101130E123826 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2019 US EPA Label, Deutz 4 Cylinder Diesel Engine, 67 in Drum, Padfoot Shell Kit Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:34 PM EDT Asset located in: Burgessville, ON, CAN
33	2005 Cat D5G XL Crawler Dozer S/N: CAT00D5GAWGB02128 C/W: Enclosed Cab, Air Conditioner, 104 in Wide PAT Blade, 19.75 in Single Grouser Track Shoes, Drawbar Usage: 13,098 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:32 PM EDT Asset located in: Burgessville, ON, CAN	36	2018 Hyundai HR70C-9 Smooth Drum Compactor S/N: 25011210E120660 C/W: Enclosed Cab, Air Conditioner, US EPA Label, Perkins 4 Cylinder Diesel Engine, 67 in Drum Usage: 1,385 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:35 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
37	2014 Cat 329E L Tracked Excavator S/N: CAT0329EPZCD00717 C/W: Air Conditioner, Straight Travel Pedal, Rear View Camera, 2014 US EPA Label, 11 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 48 in Digging Bucket, Thumb Bracket Usage: 15,984 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:36 PM EDT Asset located in: Burgessville, ON, CAN	40	2021 Cat 323 Tracked Excavator S/N: CAT00323CNDL00674 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket, Hydraulic Thumb Usage: 4,653 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:39 PM EDT Asset located in: Burgessville, ON, CAN
38	2022 Cat 326 Tracked Excavator S/N: CAT0032HMFJ10464 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 46 in Digging Bucket Usage: 2,850 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:37 PM EDT Asset located in: Burgessville, ON, CAN	41	2021 Cat 320 Tracked Excavator S/N: CAT00320EMYK10176 C/W: Air Conditioner, Straight Travel Pedal, Rear & Side View Cameras, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 49 in Digging Bucket, Hydraulic Thumb Usage: 4,420 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:40 PM EDT Asset located in: Burgessville, ON, CAN
39	2015 Cat 326F L Tracked Excavator S/N: CAT0326FVWGL00673 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Manual Quick Coupler, NYE Pulverizer Usage: 11,385 Hr Notes: Deleted/Altered Emissions- Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:38 PM EDT Asset located in: Burgessville, ON, CAN	42	2012 Cat 320E L Tracked Excavator S/N: CAT0320ECTNJ00228 C/W: Air Conditioner, Straight Travel Pedal, Rear View Camera, 2012 US EPA Label, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 45 in Digging Bucket, Thumb Bracket Usage: 12,485 Hr Notes: Reconditioned engine installed September 2026 - Undercarriage replaced December 2024 - Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - Additional information available online Lot closing time: Mon, Sep 28, 01:41 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
43	2014 Cat 314E L CR Tracked Excavator S/N: CAT0314EKZJT00728 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 27.5 in Triple Grouser Track Shoes, Rototilt Coupler, 64 in Cleanup Bucket Usage: 9,341 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:42 PM EDT Asset located in: Burgessville, ON, CAN	46	2021 Kubota U35-4 Mini Excavator S/N: KBCCZ78CAM3C19721 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, Tier 4, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 12 in Rubber Tracks, Manual Quick Coupler, 28 in Digging Bucket, Hydraulic Thumb Usage: 2,102 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:45 PM EDT Asset located in: Burgessville, ON, CAN
44	2020 Kubota KX080-4S2 Tracked Excavator S/N: KBCDZ84CCL3G10623 C/W: Air Conditioner, Control Pattern Changer, Tier 4, 2020 US EPA Label, Swing Boom, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.75 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Rotating Tilting Bucket, Lot 44 Grapple to fit Usage: 3,710 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:43 PM EDT Asset located in: Burgessville, ON, CAN	47	2011 Lippmann 4800 Impact Crusher S/N: 20110465 C/W: 8 ft x 17 ft 5 in Vibratory Pan Feeder 50 in Impact Crusher, 9 ft x 5 ft Single Deck Screen, 18 in Wide Fines Discharge Conveyor, 48 in Wide Under Crusher Conveyor, 48 in Crusher to Screen Conveyor, 42 in Wide Right Discharge Conveyor, 42 in Wide End Discharge Conveyor, 32 in x 7 ft Cross Belt Magnet, Cat C13 6 Cylinder 415 hp Diesel Engine, Quad/A Carrier, Spring Suspension, Hydraulic Leveling Usage: 13,103 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Impactor rotor replaced March 2022 - Additional information available online Lot closing time: Mon, Sep 28, 01:46 PM EDT Asset located in: Burgessville, ON, CAN
45	2020 Kubota U55-4 Mini Excavator S/N: KBCDZ56CVL3G28682 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, Swing Boom, 5 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 15.5 in Triple Grouser Track Shoes w /Rubber Pads, Rototilt Coupler, 48 in Cleanup Bucket, Additional 24 in Digging Bucket Usage: 3,890 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:44 PM EDT Asset located in: Burgessville, ON, CAN	48	2015 Tesab TS2430 Tracked Incline Screen Plant S/N: 731026038 C/W: Tesab 6 ft x 16 ft Belt Feeder w/Hydraulic Raise Grizzly 15 ft x 5 ft Double Deck Screen, 40 in Wide Feed Conveyor, 25 in Wide Under Screen Conveyor, 25 in Wide Left Discharge Conveyor, 47 in Wide End Discharge Conveyor, Cat C4.4 4 Cylinder 4.4 L Diesel Engine, Hydraulic Leveling, 19.75 in Triple Grouser Track Shoes Usage: 6,768 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:47 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
49	2004 McCloskey Portable 621RE Trommel Screen Plant S/N: 11938 C/W: 0 ft 44 in x 11 ft Belt Feeder 18 ft Trommel Screen, 44 in Wide Feed Conveyor, 36 in Wide Fines Discharge Conveyor, 30 in Wide End Discharge Conveyor, Cat 6 Cylinder Diesel Engine, Tri/A Carrier, Walking Beam, Hydraulic Leveling Usage: 9,603 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Screens replaced November 2024 - Additional information available online Lot closing time: Mon, Sep 28, 01:48 PM EDT Asset located in: Burgessville, ON, CAN	52	1999 Toyota 42-6FGU25 3750 lb Pneumatic Tire Forklift S/N: 69635 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, Toyota 4 Cylinder Dual Fuel Engine Usage: 25,384 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - This lot will be available for pickup on Monday, October 26th. The lot will be used for loadout, and additional machine hours will accrue during this time - Lot closing time: Mon, Sep 28, 01:51 PM EDT Asset located in: Burgessville, ON, CAN
50	2019 McCloskey ST100 36 in x 100 ft Portable Radial Stacking Conveyor S/N: 89795 C/W: Lattice Frame, Folding Head Section, Hydraulic Raise, Control Panel, Kingpin, 2018 US EPA Label, Cat 4 Cylinder 55 kW 3.4 L Diesel Engine Usage: 3,292 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:49 PM EDT Asset located in: Burgessville, ON, CAN	53	2021 Husqvarna TF146XK 4x2 Ride-On Lawn Mower S/N: 032421D002954 C/W: Hydrostatic Drive, 2021 US EPA Label, 15x6.00-6 Front Tires, 20x10.00-8 Rear Tires, 46 in Mower, Bagger System Usage: 149 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:52 PM EDT Asset located in: Burgessville, ON, CAN
51	2013 Trackstack 8042T 42 in x 77 ft Tracked Stacking Conveyor S/N: 1156 C/W: Folding Head & End Sections, Hydraulic Raise, Control Panel, 2012 US EPA Label, Deutz 4 Cylinder Diesel Engine Usage: 8,544 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:50 PM EDT Asset located in: Burgessville, ON, CAN	55	2012 Club Car Villager Electric Golf Cart S/N: 5J5LD42B0DA361489 C/W: 4 Passenger, Canopy, Windshield, Brand New Batteries Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:54 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
56	2010 Club Car Villager Electric Golf Cart S/N: 5J5LD42B5AA127702 C/W: 36 Volt 4 Passenger, Canopy, Windshield, Brand New Batteries Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 01:55 PM EDT Asset located in: Burgessville, ON, CAN	59	2012 Monaco Dynasty Palace IV Motor Home S/N: 51Z175616C1056730 C/W: Air Conditioner, Allison Automatic Transmission, Cummins ISX 650 6 Cylinder 15 L Diesel 650 hp Engine, 2009 US EPA Label, Sleeps 4 People, Dish Washer, Clothes Washer & Dryer, 22752 kg GVWR, 4 Slide Outs, Power Entrance Step, Power Leveling Jacks, Air Ride Suspension Usage: 31,784 Mi Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Buyer information will be provided to OMVIC as per regulations - Carfax provided-per document #72950237 damage claim reported - Lot closing time: Mon, Sep 28, 01:58 PM EDT Asset located in: Burgessville, ON, CAN
57	E-Z-Go Golf Cart S/N: 967815 C/W: 2 Passenger, Canopy, 2 Cylinder Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:56 PM EDT Asset located in: Burgessville, ON, CAN	60	2008 Heartland Cyclone 40 ft Tri/A Toy Hauler Travel Trailer S/N: 5SFGF40348E007642 C/W: Sleeps 10 People, 18000 lb GVWR, 3 Slide Outs, Onan 5.5HGJAB-1038D 5.5 kW Generator, 5th Wheel, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 01:59 PM EDT Asset located in: Burgessville, ON, CAN
58	CK 12 ft Fishing Boat S/N: Not Available C/W: Aluminum Hull, 3 Passenger Capacity, 12 ft Overall Length, Outboard Evinrude 6 hp Engine, S/A Trailer Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - No registration/title for the homebuilt trailer. Buyer will be responsible to obtain a homebuilt file at the ministry - Lot closing time: Mon, Sep 28, 01:57 PM EDT Asset located in: Burgessville, ON, CAN	61	2008 Cadillac Escalade ESV Limousine S/N: 1GYFK66838R137519 C/W: V8 6.2 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, Towing Hitch Usage: 77,964 Mi Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-per document #72314711 vehicle imported from the U.S.A. - Additional information available online - Buyer information will be provided to OMVIC as per regulations - Lot closing time: Mon, Sep 28, 02:00 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
62	2000 Ford F-450 XLT 4x2 Crew Cab Pickup S/N: 1FDXW46S6YED62485 C/W: 6.8 L V10 Gasoline Engine, 2000 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Fuel Tank /w Pump, 225/70R19.5 Tires, 8 ft Bed Usage: 293,451 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:01 PM EDT Asset located in: Burgessville, ON, CAN	65	2015 GMC Sierra 3500 Sierra 4x4 Crew Cab Pickup S/N: 1GT421CG5FF550598 C/W: 6.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 85 gal Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 10800 lb GVWR, 265/70R18 Tires, 6 ft 8 in Bed Usage: 254,489 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314287 - Lot closing time: Mon, Sep 28, 02:04 PM EDT Asset located in: Burgessville, ON, CAN
63	2004 Dodge Ram 3500 4x4 Crew Cab Pickup S/N: 3D7MU48C94G151776 C/W: 5.9 L 6 Cylinder Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Dual Rear Wheel, Fuel Tank /w Pump, Spray-On Bed Liner, 12000 lb GVWR, 235/80R17 Tires, 8 ft Bed Usage: 432,142 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:02 PM EDT Asset located in: Burgessville, ON, CAN	66	2024 Chevrolet Silverado 2500 4x4 Crew Cab Pickup S/N: 1GC4YLE79RF439922 C/W: 6.6 L V8 Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 10850 lb GVWR, 275/70R18 Tires, 6 ft 8 in Bed Usage: 101,293 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314253 - Lot closing time: Mon, Sep 28, 02:05 PM EDT Asset located in: Burgessville, ON, CAN
64	2026 Ford F-350 XL 4x4 Crew Cab Pickup S/N: 1FT8W3BA1TEC76722 C/W: 6.8 L V8 Gasoline Engine, 2026 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 5990 lb GVWR, 265/60R20 Tires, 8 ft Bed, Artic Plow Harness w/Remote Usage: 20,925 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:03 PM EDT Asset located in: Burgessville, ON, CAN	67	2010 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT4K0BG1AF116702 C/W: 6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 4173 kg GVWR, 285/75R16 Tires, 6 ft 6 in Bed Usage: 338,021 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314296 - Lot closing time: Mon, Sep 28, 02:06 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
68	2006 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GTHK23D46F141103 C/W: 6.6 L V8 Diesel Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Drop-In Bed Liner, 9200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 561,036 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314290 - Lot closing time: Mon, Sep 28, 02:07 PM EDT Asset located in: Burgessville, ON, CAN	71	2006 Ford F-250 Super Duty XL 4x4 Pickup S/N: 1FTNF21506ED50220 C/W: 5.4 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Arctic 102 in Snow Plow, 9000 lb GVWR, 265/70R17 Tires, 8 ft Bed, Salt Dogg Pro 1500 Salt Spreader Usage: 236,801 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-per document #72314273 vehicle sustained minor accident damage - Lot closing time: Mon, Sep 28, 02:10 PM EDT Asset located in: Burgessville, ON, CAN
69	2013 GMC Sierra 2500 4x4 Extended Cab Pickup S/N: 1GT220C86DZ136025 C/W: 6.6 L V8 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Tool Box, Drop-In Bed Liner, 4536 kg GVWR, 265/70R17 Tires, 6 ft 8 in Bed Usage: 185,669 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314683 - Lot closing time: Mon, Sep 28, 02:08 PM EDT Asset located in: Burgessville, ON, CAN	72	2008 Dodge Ram 1500 SXT 4x4 Crew Cab Pickup S/N: 1D7HU18248J109592 C/W: 5.7 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Tool Box, Drop-In Bed Liner, 265/70R17 Tires, 6 ft 2 in Bed Usage: 371,440 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314267 - Lot closing time: Mon, Sep 28, 02:11 PM EDT Asset located in: Burgessville, ON, CAN
70	2004 GMC Sierra 2500 4x4 Extended Cab Pickup S/N: 1GTGK29U64Z204300 C/W: 6.0 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Drop-In Bed Liner, 8600 lb GVWR, 245/75R16 Tires, 6 ft 5 in Bed Usage: 201,252 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-per document #72314679 vehicle sustained minor accident damage in three separate accidents - Lot closing time: Mon, Sep 28, 02:09 PM EDT Asset located in: Burgessville, ON, CAN	73	2002 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 2GCEK19T821374124 C/W: 5.3 L V8 Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 2903 kg GVWR, 265/75R16 Tires, 8 ft Bed Usage: 417,751 Km Notes: See Deficiencies in Inspection- Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314258 - Lot closing time: Mon, Sep 28, 02:12 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
74	2007 Ford F-150 XLT 4x4 Pickup S/N: 1FTRF14W47KD10581 C/W: 4.6 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Hassco 450 L Fuel Tank /w Pump, Drop-In Bed Liner, 6950 lb GVWR, 255/70R17 Tires, 8 ft Bed Usage: 205,483 Km Notes: See Deficiencies in Inspection- Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314282 - Lot closing time: Mon, Sep 28, 02:13 PM EDT Asset located in: Burgessville, ON, CAN	76	Soil-King Extreme XTR25HD on 2020 Kenworth T880 8x4 Stone Spreader Truck S/N: 1NKZL40X6LJ969270 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11871 Engine hrs, Engine Brake, Automated Transmission, Double Differential Locks, 9458 kg Front Axle, 20866 kg Rears, 4.10:1 Axle Ratio, 30324 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Neway Air Ride Suspension, 276 in Wheelbase, PTO, Wet Kit, 14 in x 19 ft Conveyor, Cordless Remote Control Usage: 350,043 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Chassis harness replaced December 2025 - Additional information available online - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:15 PM EDT Asset located in: Burgessville, ON, CAN
75	1998 GMC Sierra 1500 SL 4x4 Pickup S/N: 1GTEK14M1WE538530 C/W: 5.0 L V8 Gasoline Engine, 1998 US EPA Label, Automatic Transmission, Air Conditioner, Hassan Steel Fabricators 450 L Fuel Tank /w Pump, Tool Box, 2767 kg GVWR, 265/70R17 Tires, 8 ft Bed Usage: 287,767 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-no disclosures per document #72314685 - Lot closing time: Mon, Sep 28, 02:14 PM EDT Asset located in: Burgessville, ON, CAN	77	Soil-King Extreme XTR25 on 2019 Kenworth T880 8x4 Stone Spreader Truck S/N: 1NKZL40X4KJ999141 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12404 Engine hrs, Engine Brake, Automated Transmission, Double Differential Locks, 9458 lb Front Axle, 20866 lb Rears, 4.10:1 Axle Ratio, 30324 kg GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Neway Air Ride Suspension, 280 in Wheelbase, PTO, 1 Compartments, 13 in x 19 ft Conveyor, Cordless Remote Control Usage: 360,257 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Outlet catalyst replaced May 2026 - Additional information available online - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:16 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
78	2022 Peterbilt 567 8x4 Tri/A Dump Truck S/N: 1NPCX4TX4ND783079 C/W: Cummins X15 6 Cylinder Diesel 525 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 7170 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 9072 kg Front Axle, 29936 kg Rears, 37649 kg GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Spring over Walking Beam Suspension, 264 in Wheelbase, PTO, Bibeau 20 ft Long x 3 ft 6 in High Steel Body, Air Powered Roll Tarp Usage: 275,771 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:17 PM EDT Asset located in: Burgessville, ON, CAN	80	2018 Kenworth T800 8x4 Tri/A Dump Truck S/N: 3BKDX4TX5JF994554 C/W: Cummins X15 6 Cylinder Diesel 500 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 16060 Engine hrs, Engine Brake, Automatic Transmission, Double Differential Locks, 9457 kg Front Axle, 29257 kg Rears, 4.10:1 Axle Ratio, 38714 kg GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Neway Air Ride Suspension, 270 in Wheelbase, PTO, Bibeau 20 ft Long x 4 ft High Steel Body, Heated Box, Air Powered Roll Tarp, Tailgate Chute Usage: 574,840 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:19 PM EDT Asset located in: Burgessville, ON, CAN
79	2018 Kenworth T880 8x4 Tri/A Dump Truck S/N: 1NKZXPTX5JJ992666 C/W: Paccar MX-13 6 Cylinder Diesel 510 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14727 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 9072 kg Front Axle, 29711 kg Rears, 4.10:1 Axle Ratio, 38783 kg GVWR, Air Ride Cab, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Chalmers Rubber over Walking Beam Suspension, 260 in Wheelbase, PTO, Lanau 20 ft 6 in Long x 3 ft 8 in High Steel Body, Heated Box, Air Powered Roll Tarp, Tailgate Chute Usage: 527,826 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:18 PM EDT Asset located in: Burgessville, ON, CAN	81	2016 Peterbilt 567 8x4 Tri/A Dump Truck S/N: 1NPCXPTX1GD323673 C/W: Paccar MX-13 6 Cylinder Diesel 12.9 L Diesel 500 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2089 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 66000 lb Rears, 83000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 262 in Wheelbase, PTO, Lanau 20 ft 6 in Long x 4 ft High Steel Body, Heated Box, Air Powered Roll Tarp Usage: 696,660 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Additional Information available online Lot closing time: Mon, Sep 28, 02:20 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
82	2006 Western Star 4900 8x4 Tri/A Dump Truck S/N: 5KKMALCK96PV49143 C/W: Detroit Series 60 6 Cylinder 14 L Diesel 515 hp Engine, 2005 US EPA Label, 35472 Engine hrs, Engine Brake, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 66000 lb Rears, Meritor RT-46-164PEH Drive Axles, 4.10:1 Axle Ratio, 86000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Spring Suspension, 260 in Wheelbase, PTO, 20 ft 6 in Long x 4 ft High Steel Body, Heated Box, Air Powered Roll Tarp, Tailgate Chute Usage: 239,646 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:21 PM EDT Asset located in: Burgessville, ON, CAN	84	2001 Ford F-450 XL 4x2 Crew Cab Dump Truck S/N: 1FDXW46F41EC89917 C/W: Ford Powerstroke V8 Diesel Engine, 4771 Engine hrs, Automatic Transmission, 2727 kg Front Axle, 4989 kg Rears, 6803 kg GVWR, 225 /70R19.5, Spring Suspension, 176 in Wheelbase, PTO, 9 ft Long x 2 ft High Steel Body, Electric Roll Tarp, Split Swing Tailgate, Receiver Hitch, C/W Arctic Salt Spreader and 8 ft 6 in Arctic Poly plow Usage: 162,711 Km Notes: See Deficiencies in Inspection-Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Inspection required-no trip permit/transit can be issued - Lot closing time: Mon, Sep 28, 02:23 PM EDT Asset located in: Burgessville, ON, CAN
83	2013 Ford F-450 XL 4x4 Crew Cab Dump Truck S/N: 1FD0W4HYXDEA95204 C/W: V10 6.8 L Gasoline Engine, 2013 US EPA Label, 10385 Engine hrs, Automatic Transmission, 3175 kg Front Axle, 5343 kg Rears, 7484 kg GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, PTO, Eloquip 9 ft 6 in Long x 0 ft 12 in High Aluminium Body, Manual Roll Tarp, 2-Way Tailgate, 2"coupler Usage: 187,201 Km Notes: See Deficiencies in Inspection-Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Engine replaced October 2023 - Additional information available online - Lot closing time: Mon, Sep 28, 02:22 PM EDT Asset located in: Burgessville, ON, CAN	85	2014 Peterbilt PB330 4x2 Flatbed Truck S/N: 2NPNHM6X7EM243270 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 8210 Engine hrs, Allison Automatic Transmission, 7998 lb Front Axle, 5.57:1 Axle Ratio, 25993 lb GVWR, Aluminum Wheels, 245/70R19.5 Front Tires, 265/70R19.5 Rear Tires, Reyco Spring Suspension, 162 in Wheelbase, 12 ft 8 in x 96 in Bed, Pintle Hitch Usage: 294,561 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:24 PM EDT Asset located in: Burgessville, ON, CAN
		86	2012 Ford F-350 XL 4x4 Extended Cab Flatbed Truck S/N: 1FT8X3D64CED02199 C/W: V8 6.2 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 2359 kg Front Axle, 4082 kg Rears, 6033 kg GVWR, 245 /75R17, Spring Suspension, 158 in Wheelbase, 11 ft x 89 in Bed, Aluminum Frame Usage: 281,165 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:25 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
87	2020 Kenworth T800 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1XKDP4TX0LR957858 C/W: Cummins X15 500 hp Engine, 2019 US EPA Label, 12742 Engine hrs, Eaton Fuller Automated Transmission, 9072 kg Front Axle, 20866 lb Rears, 39463 kg GVWR, Engine Brake, 248 in Wheelbase, 8-Bag Air Suspension, Air Lift Pusher Axle, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Wet Kit, Air Sliding 5th Wheel Usage: 493,796 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-see additional information - Lot closing time: Mon, Sep 28, 02:26 PM EDT Asset located in: Burgessville, ON, CAN	90	2026 Western Star 49X 8x4 Tri/A Sleeper Truck Tractor S/N: 5KJNBWD15TLWS1424 C/W: Detroit DD16 Engine, 1655 Engine hrs, Automated Transmission, 20000 lb Front Axle, 46000 lb Rears, 88000 lb GVWR, Engine Brake, 246 in Wheelbase, Air Suspension, Air Lift Pusher Axle, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 59,433 Km Notes: Basic Engine and Engine Major Component Warranty until August 2027 - Emissions Warranty until August 2030 or 161,000kms - Basic Transmission Warranty until August 2028 - Please contact your local dealer for details Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Additional information available online - Carfax provided-see additional information - Lot closing time: Mon, Sep 28, 02:29 PM EDT Asset located in: Burgessville, ON, CAN
88	2004 Peterbilt 357 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1XPADB0X74D814192 C/W: Cat C15 Engine, 16317 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 16000 kg Front Axle, 46000 lb Rears, 62000 lb GVWR, Engine Brake Usage: 677,998 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Turbo replaced July 2024 - Transmission replaced April 2026 - Additional information available online Lot closing time: Mon, Sep 28, 02:27 PM EDT Asset located in: Burgessville, ON, CAN	91	2023 Kenworth T880 6x4 Heavy Haul T/A Day Cab Truck Tractor S/N: 1XKZD40X1PJ999558 C/W: Cummins X15 525 hp Engine, 2022 US EPA Label, 7635 Engine hrs, Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Engine Brake, Double Differential Locks, 240 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 343,955 Km Notes: Premium Remanufactured Injectors Installed September 2026-Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-see additional information - Additional information available online - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:30 PM EDT Asset located in: Burgessville, ON, CAN
89	1995 Ford LT9000 8x4 Tri/A Day Cab Truck Tractor S/N: 1FDZA95D2SVA57354 C/W: Detroit Series 60 Engine, 1995 US EPA Label, Eaton Fuller 18-Speed Manual Transmission, 60600 lb GVWR, Engine Brake, 230 in Wheelbase, Walking Beam Suspension, Air Lift Pusher Axle, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:28 PM EDT Asset located in: Burgessville, ON, CAN		

Lot #	Details	Lot #	Details
92	2023 Kenworth T880 6x4 Heavy Haul T/A Day Cab Truck Tractor S/N: 1XKZD40X5PJ999563 C/W: Cummins X15 525 hp Engine, 2022 US EPA Label, 7287 Engine hrs, Paccar Automated Transmission, 20000 kg Front Axle, 46000 lb Rears, 66000 lb GVWR, Engine Brake, Double Differential Locks, 240 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 345,557 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-see additional information - Additional information available online - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:31 PM EDT Asset located in: Burgessville, ON, CAN	94	2014 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP0X2ED222170 C/W: Paccar MX-13 456 hp Engine, 2013 US EPA Label, 22917 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Engine Brake, Double Differential Locks, 208 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Wet Kit, Air Sliding 5th Wheel Usage: 880,329 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:33 PM EDT Asset located in: Burgessville, ON, CAN
93	2023 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD40X0PD834746 C/W: Cummins X15 500 hp Engine, 2022 US EPA Label, 9662 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Engine Brake, Double Differential Locks, 225 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Double Frame, Wet Kit, Air Sliding 5th Wheel Usage: 439,413 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-see additional information - Lot closing time: Mon, Sep 28, 02:32 PM EDT Asset located in: Burgessville, ON, CAN	95	2014 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP0X6ED222169 C/W: Paccar MX-13 456 hp Engine, 2013 US EPA Label, 22726 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Engine Brake, Differential Lock, 205 in Wheelbase, Air Suspension, Aluminum Wheels, 295/80R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 957,329 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:34 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
96	1993 International 9200 6x4 T/A Day Cab Truck Tractor S/N: 2HSFMA7R6PC073084 C/W: 12080 lb Front Axle, 40000 lb Rears, 23623 kg GVWR, Differential Lock, 172 in Wheelbase, Air Suspension, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks, Lowboy Ramps Usage: 626,798 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Inspection required-no trip permit/transit can be issued - Lot closing time: Mon, Sep 28, 02:35 PM EDT Asset located in: Burgessville, ON, CAN	99	2018 Sure-Trac 25 ft T/A Equipment Trailer S/N: 5JW2U2524J3237569 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 98 in Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 22500 lb GVWR Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:38 PM EDT Asset located in: Burgessville, ON, CAN
97	2023 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3PD881157 C/W: Cummins X15 500 hp Engine, 2022 US EPA Label, 8550 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Double Differential Locks, 70 in Mid Roof Sleeper Cab, Bunk Beds, 260 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,453 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-see additional information - Lot closing time: Mon, Sep 28, 02:36 PM EDT Asset located in: Burgessville, ON, CAN	100	2015 Trailtech 18 ft T/A Equipment Trailer S/N: 2CU138LA7F2036287 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 18 ft Main Deck, Fixed Dovetail, Manual Ramps, 235/80R16 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:39 PM EDT Asset located in: Burgessville, ON, CAN
98	2009 Ford E-350 4x2 Van Truck S/N: 1FDWE35L09DA55419 C/W: V8 5.4 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, 4600 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, 225 /75R16, Spring Suspension, 176 in Wheelbase, Unicellular 16 ft x 96 in Wide x 70 in High Body, Walk-Up Ramp, fuel tank w/ elec pump hose and nozzle Usage: 405,379 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:37 PM EDT Asset located in: Burgessville, ON, CAN	101	Homemade 24 ft T/A Flatbed Trailer S/N: FILE271205562 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:40 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
102	1991 JC Trailer 22 ft Tri/A Utility Trailer S/N: 2J9B3V5C8MK001049 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, Lift 1st- Axles, 102 in Deck Width, Steel Decking, 10R17.5 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:41 PM EDT Asset located in: Burgessville, ON, CAN	106	Homemade 12 ft S/A Utility Trailer S/N: Not Available C/W: Spring Suspension, 65 in Deck Width, Wood Flooring, 175/80R13 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - No registration/title for trailer. Buyer will be responsible to obtain a homebuilt file # at the ministry office Lot closing time: Mon, Sep 28, 02:45 PM EDT Asset located in: Burgessville, ON, CAN
103	Homemade 16 ft T/A Utility Trailer S/N: FILE338642362 C/W: Ball Hitch, Spring Suspension, 74 in Deck Width, Wood Flooring, 205/75R15 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:42 PM EDT Asset located in: Burgessville, ON, CAN	107	2015 8 ft S/A Utility Trailer S/N: LN2SD0012FJ000349 C/W: Ball Hitch, Spring Suspension, Surge Brakes, Aluminum Wheels, 4.80-12 Tires, 1180 lb GVWR Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:46 PM EDT Asset located in: Burgessville, ON, CAN
104	Homemade 14 ft T/A Utility Trailer S/N: FILE371631081 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:43 PM EDT Asset located in: Burgessville, ON, CAN	108	Homebuilt 8 ft S/A Snowmobile Utility Trailer S/N: FILE206872907 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 84 in Deck Width, Wood Flooring, 5.70-8 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:47 PM EDT Asset located in: Burgessville, ON, CAN
105	10 ft T/A Utility Trailer S/N: Not Available C/W: 4.80-8 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - No registration/title for trailer. Buyer will be responsible to obtain a homebuilt file # at the ministry office Lot closing time: Mon, Sep 28, 02:44 PM EDT Asset located in: Burgessville, ON, CAN	109	Yard Commander 3 ft S/A Utility Trailer S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:48 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
110	2025 Miska 16 ft Tri/A Dump Utility Trailer S/N: 2MSUD2024S1034643 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 16 ft Body, 24 in Side Walls, Steel Body, Manual Roll Tarp, Swing Tailgate, 235/80R16 Tires, 21000 lb GVWR Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:49 PM EDT Asset located in: Burgessville, ON, CAN	113	1988 Bett BBT S/A Lowboy Trailer S/N: 2B9TSM119J1035090 C/W: 19 ft x 98 in Main Deck Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:52 PM EDT Asset located in: Burgessville, ON, CAN
111	1989 42 ft T/A Flatbed Trailer S/N: 2R1B3X3E4K1009581 C/W: Spring Suspension, Air Brakes, 91 in Deck Width, Wood Flooring, 11R22.5 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Title in transit-item must remain in yard until title received. NOTE-Buyer will need to sign documents prior to a registration being issued - Lot closing time: Mon, Sep 28, 02:50 PM EDT Asset located in: Burgessville, ON, CAN	114	2020 Trail King TK110SA 70000 lb 53 ft Tri/A Sliding Axle Trailer S/N: 1TKA05334LM123412 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 10 ft Upper Deck, 43 ft Main Deck, 102 in Deck Width, Winch, Deck Over Tires, Aluminum Wheels, 245/70R17.5 Tires, 60580 lb GVWR Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:53 PM EDT Asset located in: Burgessville, ON, CAN
112	2018 Scheltema Quad/A Removable Gooseneck 75 Ton Lowboy Trailer S/N: 2S9HR4617JW080557 C/W: 68750 lb GVWR, Hydraulic Removable Gooseneck, 27 ft x 114 in Main Deck, Deck Over Tires, Side Extensions, Air Lift Axle(s), Air Ride Suspension, Gasoline Driven Self Contained Hydraulic System Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Additional information available online Lot closing time: Mon, Sep 28, 02:51 PM EDT Asset located in: Burgessville, ON, CAN	115	2026 Titan 45 ft Quad/A Aluminum End Dump Trailer S/N: 2TVDP4546TD000569 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Lift 1st- Axles, Steering 1st- Axle, 45 ft Body, 58 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 60349 kg GVWR Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:54 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
116	2013 Stargate 44 ft Quad/A Aluminum End Dump Trailer S/N: 2S9DA6460DM116539 C/W: Air Ride Suspension, Air Brakes, Lift 1st-Axles, Steering 1st- Axle, 44 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Outer Wheels, 11R22.5 Tires, 62500 kg GVWR Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Additional information available online Lot closing time: Mon, Sep 28, 02:55 PM EDT Asset located in: Burgessville, ON, CAN	119	2022 Stargate 34 ft Tri/A Aluminum End Dump Trailer S/N: 2S9DA5358NM119483 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Lift 1st- Axles, Steering 1st- Axle, 34 ft Body, 54 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 52500 kg GVWR Usage: 169,279 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:58 PM EDT Asset located in: Burgessville, ON, CAN
117	2022 Midland SL3000 35 ft Tri/A End Dump Trailer S/N: 2MFB2R5D6NR009800 C/W: Air Ride Suspension, Air Brakes, Lift 1st-Axles, Steering 1st- Axle, 35 ft Body, 50 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, Aluminum Wheels, 11R22.5 Tires, 50000 kg GVWR Usage: 281,127 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:56 PM EDT Asset located in: Burgessville, ON, CAN	120	Homebuilt 22 ft T/A End Dump Trailer S/N: H0M06M17171231123 C/W: Air Ride Suspension, Air Brakes, 22 ft Body, 52 in Side Walls, Steel Body, Electric Roll Tarp, 11R22.5 Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 02:59 PM EDT Asset located in: Burgessville, ON, CAN
118	2022 Stargate 34 ft Tri/A Aluminum End Dump Trailer S/N: 2S9DA535XNM119484 C/W: Air Ride Suspension, Air Brakes, Lift 1st-Axles, Steering 1st- Axle, 34 ft Body, 54 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 115500 lb GVWR Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 02:57 PM EDT Asset located in: Burgessville, ON, CAN	121	2021 Joskin Trans-KTP 22/50 T/A Off-Road End Dump Trailer S/N: YD80022TPMJB09088 C/W: Lunette Ring Hitch, Walking Beam Suspension, Hydraulic Brakes, 17 ft Body, 36 in Side Walls, Steel Body, High Lift Tailgate, 710 /50R26.5 Super Single Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 03:00 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
122	2017 Joskin Trans-KTP 22/50 T/A Off-Road End Dump Trailer S/N: YD80022TPHJB07226 C/W: Lunette Ring Hitch, Walking Beam Suspension, Hydraulic Brakes, 17 ft Body, 36 in Side Walls, Hardox Body, High Lift Tailgate, 710 /50R26.5 Super Single Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 03:01 PM EDT Asset located in: Burgessville, ON, CAN	125	Cat 54 in Q/C Wheel Loader Forks S/N: 140503048 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - This lot will be available for pickup on Monday, October 26th. The lot will be used for loadout, and additional machine hours will accrue during this time - Lot closing time: Mon, Sep 28, 03:04 PM EDT Asset located in: Burgessville, ON, CAN
123	2017 Joskin Trans-KTP 22/50 T/A Off-Road End Dump Trailer S/N: YD80022TPHJB07225 C/W: Lunette Ring Hitch, Walking Beam Suspension, Hydraulic Brakes, 17 ft Body, 36 in Side Walls, Hardox Body, High Lift Tailgate, 710 /50R26 Super Single Tires Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - - This lot is part of a group. If a bid is received, a time extension will be applied to all lots - Lot closing time: Mon, Sep 28, 03:02 PM EDT Asset located in: Burgessville, ON, CAN	126	HLA 48 in Skid Steer Forks S/N: 20LA74940 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:04 PM EDT Asset located in: Burgessville, ON, CAN
124	1999 Ford F-250 Lariat 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTNW21S2XEE57776 C/W: 6.8 L V10 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Arctic 102 in Snow Plow, 8800 lb GVWR, 285/75R16 Tires, 8 ft Bed, Western Tornado Sander Usage: 293,072 Km Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Carfax provided-per document #72314276 unknown claim reported in the amount of \$134 - Lot closing time: Mon, Sep 28, 03:03 PM EDT Asset located in: Burgessville, ON, CAN	127	HLA 42 in Mini Skid Steer Forks S/N: 20LA62794 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:04 PM EDT Asset located in: Burgessville, ON, CAN
		128	wrecking ball S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:04 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
129	AMI Excavator Coupler S/N: 1835140101 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:04 PM EDT Asset located in: Burgessville, ON, CAN	133	Cat 44 in Excavator Bucket - Fits Cat S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:05 PM EDT Asset located in: Burgessville, ON, CAN
130	Quick Coupler S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:04 PM EDT Asset located in: Burgessville, ON, CAN	134	AMI 68 in Excavator Bucket S/N: 21043850401 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:05 PM EDT Asset located in: Burgessville, ON, CAN
131	AMI 36 in Demolition Pulverizer - Fits Cat 336 S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:05 PM EDT Asset located in: Burgessville, ON, CAN	135	H & H 60 in Cleanup Excavator Bucket S/N: 65881 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:05 PM EDT Asset located in: Burgessville, ON, CAN
132	Cat 48 in Q/C Digging Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:05 PM EDT Asset located in: Burgessville, ON, CAN	136	A 57 in Cleanup Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:05 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
137	44 in Q/C Digging Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:06 PM EDT Asset located in: Burgessville, ON, CAN	141	13 in Q/C Digging Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:06 PM EDT Asset located in: Burgessville, ON, CAN
138	H & H 24 in Q/C Scoop Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:06 PM EDT Asset located in: Burgessville, ON, CAN	142	JR 60 in Q/C Excavator Rake S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:06 PM EDT Asset located in: Burgessville, ON, CAN
139	Cat 59 in Q/C Cleanup Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:06 PM EDT Asset located in: Burgessville, ON, CAN	143	35 in Q/C Plate Compactor Attachment - Fits Excavator S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:07 PM EDT Asset located in: Burgessville, ON, CAN
140	Cat 33 in Q/C Digging Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:06 PM EDT Asset located in: Burgessville, ON, CAN	144	Bobcat Vibratory Plate Compactor S/N: 6733165 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:07 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
145	40 in Hydraulic Tilting Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:07 PM EDT Asset located in: Burgessville, ON, CAN	149	H & H 12 in Q/C Backhoe Loader Bucket - Fits Cat 420D S/N: 195-7205 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:08 PM EDT Asset located in: Burgessville, ON, CAN
146	AMI 15 in Q/C Cleanup Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:07 PM EDT Asset located in: Burgessville, ON, CAN	150	30 in Q/C Excavator Bucket S/N: 6735362 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:08 PM EDT Asset located in: Burgessville, ON, CAN
147	AMC 31 in Q/C Cleanup Excavator Bucket S/N: D1012E361S40 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:07 PM EDT Asset located in: Burgessville, ON, CAN	151	Rototilt R3 44 in Q/C Cleanup Excavator Bucket S/N: 203850-01-03 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:08 PM EDT Asset located in: Burgessville, ON, CAN
148	Cat 22 in Q/C Digging Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:07 PM EDT Asset located in: Burgessville, ON, CAN	152	H & H 71 in Hydraulic Tilting Excavator Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:08 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
153	NYE 64 in Q/C Tilting Excavator Bucket S/N: 509948 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:08 PM EDT Asset located in: Burgessville, ON, CAN	157	Promac 52II 52 in Disc Mulcher Attachment - Fits Excavator S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:09 PM EDT Asset located in: Burgessville, ON, CAN
154	2024 Diamond Mowers DER072-C 72 in Excavator Rotary Cutter S/N: 46107 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:08 PM EDT Asset located in: Burgessville, ON, CAN	158	AMI 48 in Excavator Ripper S/N: 181206-03-03 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:09 PM EDT Asset located in: Burgessville, ON, CAN
155	Cat H120S Q/C Hydraulic Breaker - Fits Cat 320 S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:09 PM EDT Asset located in: Burgessville, ON, CAN	159	H & H 32 in Excavator Ripper S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:09 PM EDT Asset located in: Burgessville, ON, CAN
156	Hydraulic Breaker - Fits Excavator S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:09 PM EDT Asset located in: Burgessville, ON, CAN	160	AMI 28 in Excavator Ripper S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:09 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
161	H & H 72 in Hydraulic Excavator Thumb S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:10 PM EDT Asset located in: Burgessville, ON, CAN	165	Cat Hydraulic Excavator Coupler - Fits Cat S/N: Not Available C/W: 90 mm Pin Diameter Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:10 PM EDT Asset located in: Burgessville, ON, CAN
162	USA Excavator Thumb S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:10 PM EDT Asset located in: Burgessville, ON, CAN	166	96 in Q/C Skeleton Wheel Loader Grapple S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:10 PM EDT Asset located in: Burgessville, ON, CAN
163	H & H Excavator Coupler S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:10 PM EDT Asset located in: Burgessville, ON, CAN	167	AMI Cat Fusion Q 98 in Q/C Grapple Wheel Loader Bucket - Fits Cat 924, 936 Cat Fusion Coupler S/N: 150592-01-03 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:11 PM EDT Asset located in: Burgessville, ON, CAN
164	Volvo Excavator Coupler S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:10 PM EDT Asset located in: Burgessville, ON, CAN	168	32 in Spoon Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:11 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
169	38 in Spoon Bucket Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:11 PM EDT Asset located in: Burgessville, ON, CAN	173	Cat Hydraulic Excavator Coupler - Fits Cat S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:12 PM EDT Asset located in: Burgessville, ON, CAN
170	54 in Blade S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:11 PM EDT Asset located in: Burgessville, ON, CAN	174	89 in Q/C Multi-Purpose Wheel Loader Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:12 PM EDT Asset located in: Burgessville, ON, CAN
171	Quantity of (2) Excavator Coupler S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:11 PM EDT Asset located in: Burgessville, ON, CAN	175	Cat 92 in Q/C Backhoe Loader Bucket - Fits Cat 420 S/N: DD180608858 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:12 PM EDT Asset located in: Burgessville, ON, CAN
172	AMI 58 in Q/C Rotating Excavator Grapple - Fits Lot 44 Kubota KX080-4S2 S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:11 PM EDT Asset located in: Burgessville, ON, CAN	176	48 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:12 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
177	30 in Skid Steer Gravel Scoop S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:12 PM EDT Asset located in: Burgessville, ON, CAN	181	Kodiak HD 7 ft 3-Point Hitch Rotary Cutter S/N: 13235 C/W: 540 PTO Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:13 PM EDT Asset located in: Burgessville, ON, CAN
178	2012 Bobcat Brushcat 60 60 in Skid Steer Mower S/N: A01902402 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:12 PM EDT Asset located in: Burgessville, ON, CAN	182	71 in Q/C Multi-Purpose Skid Steer Bucket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:13 PM EDT Asset located in: Burgessville, ON, CAN
179	Bobcat 78 in Skid Steer Tiller S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:13 PM EDT Asset located in: Burgessville, ON, CAN	183	Erskine 77 in Skid Steer Landplane S/N: 1099577 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:13 PM EDT Asset located in: Burgessville, ON, CAN
180	2020 Bobcat 72SCH 74 in Skid Steer Power Rake S/N: S6TE03826 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:13 PM EDT Asset located in: Burgessville, ON, CAN	184	Bobcat Skid Steer to Excavator Adapter S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:13 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
184A	2011 Bobcat 72 Sweeper 72 in Skid Steer Sweeper S/N: 7837248333 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:13 PM EDT Asset located in: Burgessville, ON, CAN	188	30 in Tractor Gravel Scoop S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:14 PM EDT Asset located in: Burgessville, ON, CAN
185	60 in Wheel Loader Forks S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:14 PM EDT Asset located in: Burgessville, ON, CAN	189	HLA 96 in Skid Steer Bucket S/N: 11LA10171 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:14 PM EDT Asset located in: Burgessville, ON, CAN
186	54 in Backhoe Forks S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:14 PM EDT Asset located in: Burgessville, ON, CAN	190	Cat 24 in Skid Steer Auger - Fits Bobcat T76 S/N: MRS0048 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:14 PM EDT Asset located in: Burgessville, ON, CAN
187	JCB 48 in Q/C Wheel Loader Forks S/N: 304721 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:14 PM EDT Asset located in: Burgessville, ON, CAN	191	Quantity of (5) Cat A14B Auger Attachment S/N: Not Available C/W: 31 IN/21IN/18IN/12IN/bar Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:15 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
192	2015 Bobcat Grader 96 96 in Skid Steer Grader - Fits Bobcat T76 S/N: ACW900961 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:15 PM EDT Asset located in: Burgessville, ON, CAN	196	Metal Pless ReverseMaxx 78 in Skid Steer Snow Pusher S/N: Not Available C/W: Extends to 11 ft Width, Back Drag Cutting Edge Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:15 PM EDT Asset located in: Burgessville, ON, CAN
193	Arctic 9 ft Power-V Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:15 PM EDT Asset located in: Burgessville, ON, CAN	197	2011 Metal Pless ReverseMaxx 78 in Skid Steer Snow Pusher S/N: R3M651110092289 C/W: 6.5 wide extended to 11 width, back drag cutting edge Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:16 PM EDT Asset located in: Burgessville, ON, CAN
194	Arctic Mounting Bracket S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:15 PM EDT Asset located in: Burgessville, ON, CAN	198	Arctic 7 ft 6 in 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:16 PM EDT Asset located in: Burgessville, ON, CAN
195	Frame Cross-Members S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:15 PM EDT Asset located in: Burgessville, ON, CAN	199	Arctic 7 ft 6 in 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:16 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
200	Arctic 9 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:16 PM EDT Asset located in: Burgessville, ON, CAN	204	10 ft Snow Pusher S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:17 PM EDT Asset located in: Burgessville, ON, CAN
201	Arctic 96 in V Skid Steer Snow Blade S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:16 PM EDT Asset located in: Burgessville, ON, CAN	205	2016 Bay Lynx 140F48 Snow Pusher - Fits Wheel Loader S/N: 6065 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:17 PM EDT Asset located in: Burgessville, ON, CAN
202	Arctic 96 in Skid Steer Snow Blade S/N: 14021 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:16 PM EDT Asset located in: Burgessville, ON, CAN	206	CQM 1200L 12 ft Snow Pusher S/N: 2019-053 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:17 PM EDT Asset located in: Burgessville, ON, CAN
203	Arctic 96 in Skid Steer Snow Blade S/N: 14028 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:17 PM EDT Asset located in: Burgessville, ON, CAN	207	CQM 14 ft Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:17 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
208	Horst Welding SP550012 12 ft 1 Way Snow Pusher - Fits Wheel Loader S/N: 147074 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:17 PM EDT Asset located in: Burgessville, ON, CAN	212	CQM 12 ft Snow Pusher - Fits Wheel Loader S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:18 PM EDT Asset located in: Burgessville, ON, CAN
209	AMI S21016 120 in 10-16 ft Snow Blade - Fits Wheel loader S/N: 191228-01-01 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:18 PM EDT Asset located in: Burgessville, ON, CAN	213	Arctic 8 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:18 PM EDT Asset located in: Burgessville, ON, CAN
210	CQM 12 ft Snow Pusher - Fits Backhoe Loader S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:18 PM EDT Asset located in: Burgessville, ON, CAN	214	Arctic 8 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:18 PM EDT Asset located in: Burgessville, ON, CAN
211	CQM 12 ft Snow Pusher - Fits Wheel Loader S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:18 PM EDT Asset located in: Burgessville, ON, CAN	215	Arctic 96P 8 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:19 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
216	Arctic 8 ft 2 Way Snow Plow S/N: 53932340-0014 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:19 PM EDT Asset located in: Burgessville, ON, CAN	220	Arctic 8 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:19 PM EDT Asset located in: Burgessville, ON, CAN
217	Western 8 ft 6 in Power-V Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:19 PM EDT Asset located in: Burgessville, ON, CAN	221	Arctic 8 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:20 PM EDT Asset located in: Burgessville, ON, CAN
218	Boss 8 ft 2 in Power-V Snow Plow S/N: 276402 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:19 PM EDT Asset located in: Burgessville, ON, CAN	222	Arctic 8 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:20 PM EDT Asset located in: Burgessville, ON, CAN
219	Arctic 8 ft 6 in 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:19 PM EDT Asset located in: Burgessville, ON, CAN	223	Arctic 9 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:20 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
224	Arctic 9 ft 2 Way Snow Plow S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:20 PM EDT Asset located in: Burgessville, ON, CAN	228	2024 Powerforce KCG-5100G Portable Generator Set S/N: 20092-0071 C/W: 1 Cylinder 224 cc Gasoline Engine, /4 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:21 PM EDT Asset located in: Burgessville, ON, CAN
225	Yamaha EF4600 DX Generator Set S/N: Not Available C/W: Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:20 PM EDT Asset located in: Burgessville, ON, CAN	229	Powerforce 1.5 kW Mobile 1500W Gasoline Generator Set S/N: Not Available C/W: 3 hp Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:21 PM EDT Asset located in: Burgessville, ON, CAN
226	Champion Portable Generator Set S/N: Not Available C/W: Champion Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:20 PM EDT Asset located in: Burgessville, ON, CAN	230	Champion 3 kW Portable Generator Set S/N: Not Available C/W: 2014 US EPA Label, Champion Gasoline Engine, 120 V Receptacles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:21 PM EDT Asset located in: Burgessville, ON, CAN
227	Generac 5.5 kW Portable Generator Set S/N: 3004113996 C/W: 2019 US EPA Label, Generac 389 cc Gasoline Engine, 120 V / 240 V Rated Voltage, 120 V Receptacles Usage: 1,303 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:21 PM EDT Asset located in: Burgessville, ON, CAN	231	Champion 201077 8 kW Generator Set S/N: Y2507210188 C/W: 2025 US EPA Label, Champion 389 cc Dual Fuel Engine, 120 V / 240 V Rated Voltage Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:21 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
232	2022 Champion 201069 1.2 kW Portable Generator Set S/N: Y2209270074 C/W: 2022 US EPA Label, Champion 80 cc Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:21 PM EDT Asset located in: Burgessville, ON, CAN	236	Air Compressor S/N: Not Available C/W: Honda GX 160 Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:22 PM EDT Asset located in: Burgessville, ON, CAN
233	Patron GI-2100 2.1 kW Portable Generator Set S/N: Not Available C/W: 2019 US EPA Label, 79.7 cc Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:22 PM EDT Asset located in: Burgessville, ON, CAN	237	Lincoln SA-200-F163 Mobile Stick Engine Driven Welder S/N: A63373 C/W: Gasoline Engine, 90 V Input, Welding Leads, Ball Hitch Carrier Trailer Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:22 PM EDT Asset located in: Burgessville, ON, CAN
234	Miller Millermatic 252 Electric Welder S/N: MJ040377N C/W: 230 V/ 460 V Input, Wire Feeder Attachment Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:22 PM EDT Asset located in: Burgessville, ON, CAN	238	Hyundai HP370 Water Pump S/N: Not Available C/W: 3.5 in Intake, 3.5 in Discharge, 2022 US EPA Label, 212 cc Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:22 PM EDT Asset located in: Burgessville, ON, CAN
235	Lincoln Electric Idealarc 250 250 A Electric Welder S/N: C1960200064 C/W: 3 Phase, 22 V/ 30 V Input Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:22 PM EDT Asset located in: Burgessville, ON, CAN	239	Quantity of (3) Submersible Water Pump S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:23 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
240	Bolton Pro Water Pump S/N: Not Available C/W: 3.5 in Intake, 4.5 in Discharge, Centrifugal Water Pump, 2006 US EPA Label, Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:23 PM EDT Asset located in: Burgessville, ON, CAN	245	Quantity of (2) 450 L Fuel Tank S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:24 PM EDT Asset located in: Burgessville, ON, CAN
241	Wacker Neuson Water Pump (Inoperable) S/N: Not Available C/W: 3.5 in Intake, 3.5 in Discharge, Centrifugal 2005 US EPA Label, Honda GX240 243 cid Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:23 PM EDT Asset located in: Burgessville, ON, CAN	246	Quantity of (2) Fuel Tank S/N: Not Available C/W: (1) 12 V Transfer Pump Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:24 PM EDT Asset located in: Burgessville, ON, CAN
242	Honda WB20XT Water Pump S/N: 3139169 C/W: 2.5 in Intake, 2.5 in Discharge, Water Pump, 2017 US EPA Label, Honda GX 120 Gasoline Engine, 119cm3 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:23 PM EDT Asset located in: Burgessville, ON, CAN	247	Quantity of Steel Hydraulic/Fuel Tanks S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:24 PM EDT Asset located in: Burgessville, ON, CAN
243	2015 Wacker Neuson PT3A Water Pump S/N: 24249248 C/W: 3.5 in Intake, 3.5 in Discharge, Centrifugal 2014 US EPA Label, CARB Compliant, Honda Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:23 PM EDT Asset located in: Burgessville, ON, CAN	248	500 gal Trailer Mounted Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump, 15 ft Hose Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:24 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
249	Trailer Mounted Fuel Tank S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:24 PM EDT Asset located in: Burgessville, ON, CAN	253	2011 Hassco 4500 L Steel Gasoline Fuel Tank S/N: SW1845 C/W: 120 V Transfer Pump, 12 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:25 PM EDT Asset located in: Burgessville, ON, CAN
250	Trailer Mounted Fuel Tank S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:24 PM EDT Asset located in: Burgessville, ON, CAN	254	2011 Hassco 4500 L Steel Diesel Fuel Tank S/N: SW2006 C/W: 120 V Transfer Pump, 20 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:25 PM EDT Asset located in: Burgessville, ON, CAN
251	100 gal Steel Fuel Tank S/N: 301887 C/W: 12 V Transfer Pump Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:25 PM EDT Asset located in: Burgessville, ON, CAN	255	2019 Nithwood 4500 L Steel Diesel Fuel Tank S/N: D66194345 C/W: 120 V Transfer Pump, 25 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:25 PM EDT Asset located in: Burgessville, ON, CAN
252	2011 Hassco 4500 L Steel Diesel Fuel Tank S/N: SW1949 C/W: 120 V Transfer Pump, 25 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:25 PM EDT Asset located in: Burgessville, ON, CAN	256	2008 Hassco 2200 L Steel Gasoline Fuel Tank S/N: 615 C/W: 120 V Transfer Pump, 10 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:25 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
257	Quantity of Tank S/N: Not Available C/W: 2 tanks with pneumatic pumps and hose reels with metered nozzles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:26 PM EDT Asset located in: Burgessville, ON, CAN	261	Futura LT-850 Grade Laser S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:26 PM EDT Asset located in: Burgessville, ON, CAN
258	Quantity of (2) Fuel Tank S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:26 PM EDT Asset located in: Burgessville, ON, CAN	262	Leica Wild NA24 Automatic Level S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:26 PM EDT Asset located in: Burgessville, ON, CAN
259	Water Tank S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 03:26 PM EDT Asset located in: Burgessville, ON, CAN	263	Quantity of (3) Code Readers and (1) Handheld Thermal Imager S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:27 PM EDT Asset located in: Burgessville, ON, CAN
260	Spectra Precision Tremble GL422N Grade Laser S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:26 PM EDT Asset located in: Burgessville, ON, CAN	264	Bobcat BLR2 Laser Receiver S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:27 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
265	Bobcat BLR2 Laser Receiver - Fits Bobcat S/N: AD0V01762 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:27 PM EDT Asset located in: Burgessville, ON, CAN	269	2022 Evolution S28MAG 1-1/8 in Industrial Magnetic Drill S/N: I2212US00225 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:28 PM EDT Asset located in: Burgessville, ON, CAN
266	Snap-On Wireless Electrical System Analyzer S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:27 PM EDT Asset located in: Burgessville, ON, CAN	270	Quantity of Topcon Remotes/Dewalt Battery Chargers S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:28 PM EDT Asset located in: Burgessville, ON, CAN
267	CST/Berger RL25H Grade Laser S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:27 PM EDT Asset located in: Burgessville, ON, CAN	271	Quantity of (3) Boxes of Roll-Rite Rebuilt 12V Thru-Shaft Motor S/N: Not Available C/W: 2 Open Box Rebuilt, 1 Sealed Rebuilt Box Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:28 PM EDT Asset located in: Burgessville, ON, CAN
268	Topcon RL-SV1S Laser Level S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:27 PM EDT Asset located in: Burgessville, ON, CAN	272	CST/Berger Magna-Trak Magnetic Locator S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:28 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
273	Remanufactured Alternator S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:28 PM EDT Asset located in: Burgessville, ON, CAN	277	Quantity of Tables S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:29 PM EDT Asset located in: Burgessville, ON, CAN
274	Case IH Vector Pro GNSS Receiver (Unused) S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:28 PM EDT Asset located in: Burgessville, ON, CAN	278	Portable Air Tanks and Floor Jack S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:29 PM EDT Asset located in: Burgessville, ON, CAN
275	Quantity of Boost Cables, Tools, Chest Waders, Screws S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:29 PM EDT Asset located in: Burgessville, ON, CAN	279	Steel Wire S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:29 PM EDT Asset located in: Burgessville, ON, CAN
276	Ultra Pro 1300 Wheel Balancer S/N: Not Available C/W: Tire Changer, Assorted Wheel Weights Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:29 PM EDT Asset located in: Burgessville, ON, CAN	280	PowerMake CH-16N 16-speed Drill Press S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:29 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
281	FMC 4200 Wheel Balancer S/N: E61EJ077 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:30 PM EDT Asset located in: Burgessville, ON, CAN	285	Shop Press S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:30 PM EDT Asset located in: Burgessville, ON, CAN
282	Quantity of Assorted Bolts/Assorted Lights S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:30 PM EDT Asset located in: Burgessville, ON, CAN	286	Thermal Dynamics Cutmaster 42 40 A Mobile Plasma Cutter S/N: Not Available C/W: 120 V/ 230 V Input Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:30 PM EDT Asset located in: Burgessville, ON, CAN
283	Quantity of Assorted Bolts/Assorted Lights S/N: Not Available C/W: Bolt Bin Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:30 PM EDT Asset located in: Burgessville, ON, CAN	287	DeWalt DW872 Circular Saw S/N: W09JORQ Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:31 PM EDT Asset located in: Burgessville, ON, CAN
284	Quantity of Assorted Tools in Tool Box S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:30 PM EDT Asset located in: Burgessville, ON, CAN	288	Shop Table S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:31 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
289	Quantity of Bolt Bin, Assorted Bolts, Washers, Nuts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:31 PM EDT Asset located in: Burgessville, ON, CAN	293	Quantity of Chains S/N: Not Available C/W: 72" x 37" Steel mesh grating panels Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:32 PM EDT Asset located in: Burgessville, ON, CAN
290	Trimble R750 Grade Control GNSS Receiver S/N: 6406R06008 C/W: Crain Tripod, Soft Case, 115000-10 Antenna Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 03:31 PM EDT Asset located in: Burgessville, ON, CAN	294	Quantity of Heavy Duty Chains S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:32 PM EDT Asset located in: Burgessville, ON, CAN
291	Trimble R780 Rover Grade Control GNSS Receiver S/N: Not Available C/W: Trimble Offset 4CM 13Ft Pole, Trimble T7 Tablet Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 03:31 PM EDT Asset located in: Burgessville, ON, CAN	295	Quantity of Ratchet Straps S/N: Not Available C/W: bindings, chains and Pry bars Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:32 PM EDT Asset located in: Burgessville, ON, CAN
292	Titan XT330 Pressure Washer S/N: Not Available C/W: Hose, Spray Wand Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:31 PM EDT Asset located in: Burgessville, ON, CAN	296	Quantity of Chains S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:32 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
297	Quantity of 3 ft-8 ft Assorted Ladders S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:32 PM EDT Asset located in: Burgessville, ON, CAN	301	Quantity of Lubricant and Grease Pumps S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:33 PM EDT Asset located in: Burgessville, ON, CAN
298	Quantity of (2) 6 ft Tables S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:32 PM EDT Asset located in: Burgessville, ON, CAN	302	Quantity of Assorted Sockets, Drill Bits, Power Tools, Battery Chargers, Extension Cables S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:33 PM EDT Asset located in: Burgessville, ON, CAN
299	2021 Luggernaught SG1300 Clamp S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:33 PM EDT Asset located in: Burgessville, ON, CAN	303	Quantity of (2) Stihl ER-430 Backpack Blower S/N: 501768030 C/W: 2014 US EPA Label, 63 cc Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:33 PM EDT Asset located in: Burgessville, ON, CAN
300	Quantity of Quantity of Grease/Fluid Pumps S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:33 PM EDT Asset located in: Burgessville, ON, CAN	304	Quantity of Cylinder Metal Bars S/N: Not Available C/W: Truck tow hitch's Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:33 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
305	DSR 6V/12V/24V Boost/Battery Charger S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:34 PM EDT Asset located in: Burgessville, ON, CAN	309	Quantity of Ratchets S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:34 PM EDT Asset located in: Burgessville, ON, CAN
306	Quantity of (3) Ridgid Shop Vacuum Cleaner S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:34 PM EDT Asset located in: Burgessville, ON, CAN	310	Quantity of Landscaping and Digging Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:34 PM EDT Asset located in: Burgessville, ON, CAN
307	Quantity of Shop Vacuum Cleaner S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:34 PM EDT Asset located in: Burgessville, ON, CAN	311	Quantity of Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:35 PM EDT Asset located in: Burgessville, ON, CAN
308	Quantity of Hard Hats S/N: Not Available C/W: 2014 US EPA Label, CARB Compliant, 21.2 cc Gasoline Engine, Stihl Circular Saw, Trimmer,, Mastercraft Tool Kit Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:34 PM EDT Asset located in: Burgessville, ON, CAN	312	Quantity of Assorted Tools, Sledgehammers, Shovels, Bolt Cutters S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:35 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
313	Stihl Cut-Off Saw S/N: Not Available C/W: 2015 US EPA Label, Sthil Gasoline Engine, Quantity of Sprayers Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:35 PM EDT Asset located in: Burgessville, ON, CAN	317	Quantity of Sawhorses, Jack Stands, Step Ladder, Straps, Chains S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:36 PM EDT Asset located in: Burgessville, ON, CAN
314	Quantity of (2) Topcon RL-SV Laser Level S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:35 PM EDT Asset located in: Burgessville, ON, CAN	318	Quantity of Tools and Miscellaneous parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:36 PM EDT Asset located in: Burgessville, ON, CAN
315	Spectra LL300N Laser Level S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:35 PM EDT Asset located in: Burgessville, ON, CAN	319	Quantity of Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:36 PM EDT Asset located in: Burgessville, ON, CAN
316	Quantity of (2) Topcon Rotating Laser Level S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:35 PM EDT Asset located in: Burgessville, ON, CAN	320	Quantity of Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:36 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
321	Portable Air Tank, Floor Jack, (2) Dump-Lok Safety Braces S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:36 PM EDT Asset located in: Burgessville, ON, CAN	325	Air/Hydraulic High-Lift Transmission Jack S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:37 PM EDT Asset located in: Burgessville, ON, CAN
322	Quantity of Jack stands S/N: Not Available C/W: , C-clamps Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:36 PM EDT Asset located in: Burgessville, ON, CAN	326	Transmission Jack S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:37 PM EDT Asset located in: Burgessville, ON, CAN
323	Wheel Dolly S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:37 PM EDT Asset located in: Burgessville, ON, CAN	327	2 Ton hydraulic Engine hoist S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:37 PM EDT Asset located in: Burgessville, ON, CAN
324	Quantity of Mats S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:37 PM EDT Asset located in: Burgessville, ON, CAN	328	Quantity of Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:37 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
329	Quantity of Topcon RL-H3C Rotating Laser Level S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:38 PM EDT Asset located in: Burgessville, ON, CAN	333	Quantity of Floor Jack Stand S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:38 PM EDT Asset located in: Burgessville, ON, CAN
330	Quantity of Tools and Miscellaneous Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:38 PM EDT Asset located in: Burgessville, ON, CAN	334	Mastercraft Tool Set, Makita Bit Set, UCAN Fastening Tool, Simpson Anchor System S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:38 PM EDT Asset located in: Burgessville, ON, CAN
331	Quantity of Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:38 PM EDT Asset located in: Burgessville, ON, CAN	335	Broyhill Estate Sprayer S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:39 PM EDT Asset located in: Burgessville, ON, CAN
332	Tool Cabinet S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:38 PM EDT Asset located in: Burgessville, ON, CAN	336	Honda Engine (Inoperable) S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:39 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
337	Hose S/N: Not Available C/W: 4" Diameter for green hose Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:39 PM EDT Asset located in: Burgessville, ON, CAN	341	Quantity of Fluids S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:40 PM EDT Asset located in: Burgessville, ON, CAN
338	Quantity of Water Hose S/N: Not Available C/W: Submersible Water Pumps Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:39 PM EDT Asset located in: Burgessville, ON, CAN	342	Quantity of Fluids S/N: Not Available C/W: Hydraulic fluid, transmission fluid, engine oil Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:40 PM EDT Asset located in: Burgessville, ON, CAN
339	WetJet Pressure Washer S/N: Not Available C/W: Honda GX 390 Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:39 PM EDT Asset located in: Burgessville, ON, CAN	343	Quantity of Cat Transmission and Drivetrain Oil S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:40 PM EDT Asset located in: Burgessville, ON, CAN
340	Quantity of Small Engines, and Power Cords S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:39 PM EDT Asset located in: Burgessville, ON, CAN	344	Quantity of Mobil Transmission Fluid S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:40 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
345	Quantity of Engine/Transmission Fluid S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:40 PM EDT Asset located in: Burgessville, ON, CAN	349	Quantity of (2) Tires S/N: Not Available C/W: Some Tires with Wheels, (1) 11R22.5, (1) 255/70R17 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:41 PM EDT Asset located in: Burgessville, ON, CAN
346	Pelican Kayak S/N: Not Available C/W: paddles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:40 PM EDT Asset located in: Burgessville, ON, CAN	350	Cat Hydraulic Cooler Core and Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:41 PM EDT Asset located in: Burgessville, ON, CAN
347	Pelican Kayak S/N: Not Available C/W: paddles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:41 PM EDT Asset located in: Burgessville, ON, CAN	351	16' 4" x 41.5" Shelving S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:41 PM EDT Asset located in: Burgessville, ON, CAN
348	Dolly & Portable Stairs S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:41 PM EDT Asset located in: Burgessville, ON, CAN	352	Quantity of (2) 8 ft x 4 ft Shelving S/N: Not Available C/W: 8 ft Height Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:41 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
353	Cabinet & Locker S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:42 PM EDT Asset located in: Burgessville, ON, CAN	357	Saw, Pesticide Sprayer, Assorted Nails/Screws, Hydraulic Cylinder S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:42 PM EDT Asset located in: Burgessville, ON, CAN
354	Tarp S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 03:42 PM EDT Asset located in: Burgessville, ON, CAN	358	Quantity of Plastic Membrane S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:42 PM EDT Asset located in: Burgessville, ON, CAN
355	1/4 in Acetylene Lines, Assorted Valves. Straps S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:42 PM EDT Asset located in: Burgessville, ON, CAN	359	Quantity of Ladder S/N: Not Available C/W: wood, outdoor shiplap Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:43 PM EDT Asset located in: Burgessville, ON, CAN
356	Blue Giant 72 in Loading Dock S/N: 0345653 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:42 PM EDT Asset located in: Burgessville, ON, CAN	360	Tires and Assorted Woodshop Items S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:43 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
361	Quantity of Tool Box S/N: Not Available C/W: parts, weather barrier, Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:43 PM EDT Asset located in: Burgessville, ON, CAN	365	54 in Snow Blade S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:44 PM EDT Asset located in: Burgessville, ON, CAN
362	Quantity of Road signs S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:43 PM EDT Asset located in: Burgessville, ON, CAN	366	46 in Snow Blade S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:44 PM EDT Asset located in: Burgessville, ON, CAN
363	Quantity of Traffic Cones S/N: Not Available C/W: , flags, wooden stakes, salt bags Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:43 PM EDT Asset located in: Burgessville, ON, CAN	367	54 in Snow Blade S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:44 PM EDT Asset located in: Burgessville, ON, CAN
364	Quantity of Safety Signs S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:43 PM EDT Asset located in: Burgessville, ON, CAN	368	Outdoor Table & Chairs S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:44 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
369	Quantity of (3) Outdoor Chairs S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:44 PM EDT Asset located in: Burgessville, ON, CAN	373	Performance Built Electric 5 ton Log Splitter S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:45 PM EDT Asset located in: Burgessville, ON, CAN
370	Bench Grinder S/N: F576 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:44 PM EDT Asset located in: Burgessville, ON, CAN	374	Seed Spreaders S/N: Not Available C/W: , hoses Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:45 PM EDT Asset located in: Burgessville, ON, CAN
371	Sod Roller S/N: Not Available C/W: , crossbow target Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:45 PM EDT Asset located in: Burgessville, ON, CAN	375	Kodiak Wood Chipper S/N: 60112 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine, 9 in Feed Opening Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:45 PM EDT Asset located in: Burgessville, ON, CAN
372	36 in lawn aerator S/N: Not Available C/W: dethatcher Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:45 PM EDT Asset located in: Burgessville, ON, CAN	376	Aerator S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:45 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
377	Yard Commander 40 in Lawn Dethatcher S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:46 PM EDT Asset located in: Burgessville, ON, CAN	381	Cub Cadet 28 in Walk-Behind Snow Blower S/N: 1G164B70576 C/W: Cub Cadet 420 cc Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:46 PM EDT Asset located in: Burgessville, ON, CAN
378	36 in Lawn Roller S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:46 PM EDT Asset located in: Burgessville, ON, CAN	382	Quantity of Assorted Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:46 PM EDT Asset located in: Burgessville, ON, CAN
379	PowerSmart 22 in 2 Way Walk-Behind Snow Blower S/N: Not Available C/W: 212 cc Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:46 PM EDT Asset located in: Burgessville, ON, CAN	383	Honda HS520C2A 19 in Snow Blower S/N: SZBG-6627082 C/W: Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:47 PM EDT Asset located in: Burgessville, ON, CAN
380	YardWorks 27 in 2 Way Walk-Behind Snow Blower S/N: 1J255I40189 C/W: 8.5 hp Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:46 PM EDT Asset located in: Burgessville, ON, CAN	384	MTD 21 in 1 Way Snow Blower S/N: 1J135B20608 C/W: 5 hp Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:47 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
385	TPI MCSII-8H Walk-Behind Saw S/N: 163418 C/W: Honda GX240 Gasoline Engine, 14 in Blade Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:47 PM EDT Asset located in: Burgessville, ON, CAN	389	Quantity of Filters for Screeners and Stackers S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:48 PM EDT Asset located in: Burgessville, ON, CAN
386	2016 Wacker Neuson DPU4545H Vibratory Plate Compactor S/N: 10603948 C/W: 2016 US EPA Label, Hatz 1D42S Diesel Engine Usage: 579 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:47 PM EDT Asset located in: Burgessville, ON, CAN	390	Quantity of Hand Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:48 PM EDT Asset located in: Burgessville, ON, CAN
387	2018 Wacker Neuson DPU 4545H Vibratory Plate Compactor S/N: Not Available C/W: 2018 US EPA Label, Hatz 1D42S 5.8 kW 0.4 L Diesel Engine Usage: 98 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:47 PM EDT Asset located in: Burgessville, ON, CAN	391	Quantity of (12) Shovels S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:48 PM EDT Asset located in: Burgessville, ON, CAN
388	2022 Wacker Neuson DPU4545 Vibratory Plate Compactor S/N: 5100063121 C/W: Yanmar L70W6AJ8T8AAWK 4.8 kW 0.32 L Engine Usage: 158 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:47 PM EDT Asset located in: Burgessville, ON, CAN	392	Quantity of (10) Shovels S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:48 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
393	Quantity of (15) Shovels S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:48 PM EDT Asset located in: Burgessville, ON, CAN	397	Quantity of Tools S/N: Not Available C/W: Shovels, rakes, brooms, pitchfork, sledgehammer, pickaxe Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:49 PM EDT Asset located in: Burgessville, ON, CAN
394	Quantity of Tools S/N: Not Available C/W: Shovels, rakes, brooms, pitchfork, sledgehammer, pickaxe Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:48 PM EDT Asset located in: Burgessville, ON, CAN	398	YoungesE E Bike Scooter S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:49 PM EDT Asset located in: Burgessville, ON, CAN
395	Quantity of Tools S/N: Not Available C/W: Shovels, rakes, brooms, pitchfork, sledgehammer, pickaxe Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:49 PM EDT Asset located in: Burgessville, ON, CAN	399	Quantity of Hydraulic Hoses, Cylinders, Fittings S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:49 PM EDT Asset located in: Burgessville, ON, CAN
396	Quantity of Tools S/N: Not Available C/W: Shovels, rakes, brooms, pitchfork, sledgehammer, pickaxe Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:49 PM EDT Asset located in: Burgessville, ON, CAN	400	Quantity of Air Bag Suspension Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:49 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
401	Assorted Filters S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:50 PM EDT Asset located in: Burgessville, ON, CAN	405	Quantity of Truck/Trailer Parts S/N: Not Available C/W: Hub caps, Oil seals Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:50 PM EDT Asset located in: Burgessville, ON, CAN
402	Quantity of Truck Parts S/N: Not Available C/W: Wipers, Titan steps, CAC hot hose charge air, U-Joint kit Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:50 PM EDT Asset located in: Burgessville, ON, CAN	406	Quantity of Brake Chambers S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:50 PM EDT Asset located in: Burgessville, ON, CAN
403	Quantity of Air Bags S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:50 PM EDT Asset located in: Burgessville, ON, CAN	407	Salt Spreader S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:51 PM EDT Asset located in: Burgessville, ON, CAN
404	Quantity of Filters S/N: Not Available C/W: Oil seals Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:50 PM EDT Asset located in: Burgessville, ON, CAN	408	Sanborn G500BPC60V 60 gal Air Compressor S/N: P1555192 C/W: 5 hp Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:51 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
409	Quantity of Truck Parts S/N: Not Available C/W: Coolant Reservoir, blower motor assembly, evaporator, lower door hinges, Baldwin filters, Cummins Nitrogen Oxide Sensors, Universal Joint kits, Paccar Sensors Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:51 PM EDT Asset located in: Burgessville, ON, CAN	413	Quantity of Brake And Suspension Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:52 PM EDT Asset located in: Burgessville, ON, CAN
410	Quantity of Parts S/N: Not Available C/W: Valves, Exhaust Clamps, Antennas, Fiberglass Antennas, Mini Lamps, Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:51 PM EDT Asset located in: Burgessville, ON, CAN	414	Quantity of Assorted Parts S/N: Not Available C/W: Kubota, John Deere, Paccar, Bobcat And More Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:52 PM EDT Asset located in: Burgessville, ON, CAN
411	Quantity of Air Bags S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:51 PM EDT Asset located in: Burgessville, ON, CAN	415	Quantity of Assorted Cabin/Air/Oil Filters S/N: Not Available C/W: Brake Chambers Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:52 PM EDT Asset located in: Burgessville, ON, CAN
412	Quantity of Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:51 PM EDT Asset located in: Burgessville, ON, CAN	416	Quantity of Assorted CAT Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:52 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
417	Quantity Of Assorted Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:52 PM EDT Asset located in: Burgessville, ON, CAN	421	Quantity of Assorted Parts S/N: Not Available C/W: Winch, Quantity Of Straps/Wire. , Pickup Truck Side Mirrors Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:53 PM EDT Asset located in: Burgessville, ON, CAN
418	Quantity of Filters S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:52 PM EDT Asset located in: Burgessville, ON, CAN	422	Quantity of Assorted Headlights, Mirror Brackets/Mirrors S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:53 PM EDT Asset located in: Burgessville, ON, CAN
419	Quantity of Chainsaws And Assorted Tools S/N: Not Available C/W: , Quantity Of Emergency Warning Triangles Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:53 PM EDT Asset located in: Burgessville, ON, CAN	423	Quantity of Assorted Dewalt Power Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:53 PM EDT Asset located in: Burgessville, ON, CAN
420	Sump Pump Drainage Kit S/N: Not Available C/W: Piping Manifold, Quantity Of Landscape Stakes Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:53 PM EDT Asset located in: Burgessville, ON, CAN	424	Quantity of Assorted Cat Filters S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:53 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
425	Quantity of Hydraulic Fluid S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:54 PM EDT Asset located in: Burgessville, ON, CAN	429	Quantity of Power Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:54 PM EDT Asset located in: Burgessville, ON, CAN
426	2025 PowerFist HVD-36CSL Fan S/N: 3166613 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:54 PM EDT Asset located in: Burgessville, ON, CAN	430	Utility Pump, Extension Cords, Tail Lights, Hydraulic Lines S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:54 PM EDT Asset located in: Burgessville, ON, CAN
427	Quantity of Parts S/N: Not Available C/W: Brake parts, chains, barrel pump Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:54 PM EDT Asset located in: Burgessville, ON, CAN	431	Quantity of Truck Parts S/N: Not Available C/W: Quantity of filters Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:55 PM EDT Asset located in: Burgessville, ON, CAN
428	Quantity of Miscellaneous parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:54 PM EDT Asset located in: Burgessville, ON, CAN	432	Eaton Clutch 122002-35EX S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:55 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
433	Quantity of Assorted Nuts, Bolts, Tyre Repair Kits. Bead Bazooka 10L S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:55 PM EDT Asset located in: Burgessville, ON, CAN	437	Quantity of Tool Box S/N: Not Available C/W: with miscellaneous Parts Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:56 PM EDT Asset located in: Burgessville, ON, CAN
434	Husqvarna Circular Saw S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:55 PM EDT Asset located in: Burgessville, ON, CAN	438	Quantity of Fire Extinguishers S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:56 PM EDT Asset located in: Burgessville, ON, CAN
435	Quantity of Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:55 PM EDT Asset located in: Burgessville, ON, CAN	439	Quantity of Assorted Fluids/Bug Sprays, Assorted Fire Extinguishers S/N: Not Available C/W: Assorted Fire Extinguishers Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:56 PM EDT Asset located in: Burgessville, ON, CAN
436	Quantity of Tool Cabinets and Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:55 PM EDT Asset located in: Burgessville, ON, CAN	440	Quantity of Ratchet Straps S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:56 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
440A	Quantity of (2) Lights & Clothing S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:56 PM EDT Asset located in: Burgessville, ON, CAN	444	Quantity of Lights S/N: Not Available C/W: Cabinet Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:57 PM EDT Asset located in: Burgessville, ON, CAN
441	1040 L Skid Mounted Poly Insulated DEF Tank S/N: Not Available C/W: 120 V Transfer Pump, 15 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Insulated Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:56 PM EDT Asset located in: Burgessville, ON, CAN	445	Quantity of Bins S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:57 PM EDT Asset located in: Burgessville, ON, CAN
442	Quantity of Jerry Cans S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:56 PM EDT Asset located in: Burgessville, ON, CAN	446	55" x 33.5 Table S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:57 PM EDT Asset located in: Burgessville, ON, CAN
443	Quantity of (4) Salt Bins S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:57 PM EDT Asset located in: Burgessville, ON, CAN	447	Quantity of PVC Caps/Fittings S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:57 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
448	Quantity of PVC Cement, Primers, fittings S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:57 PM EDT Asset located in: Burgessville, ON, CAN	452	Baby Jogger Summit X3 Stroller S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:58 PM EDT Asset located in: Burgessville, ON, CAN
449	Quantity of (3) Ladders S/N: Not Available C/W: 11 Ft, 8 Ft, 6 Ft Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:58 PM EDT Asset located in: Burgessville, ON, CAN	453	53 ft x 36 ft Table S/N: Not Available C/W: With cabinet Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:58 PM EDT Asset located in: Burgessville, ON, CAN
450	Quantity of PVC Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:58 PM EDT Asset located in: Burgessville, ON, CAN	454	Rockwell Sander/Grinder S/N: LY3804 C/W: Table and Bench Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:58 PM EDT Asset located in: Burgessville, ON, CAN
451	Tool box with miscellaneous tools and a storm drainer S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:58 PM EDT Asset located in: Burgessville, ON, CAN	455	Robinair 34788 Refrigerant Recovery, Recycling And Recharging Station S/N: 242696 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:59 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
456	2016 Robinair Cool Tech 75700 Coolant Exchanger S/N: 205994 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:59 PM EDT Asset located in: Burgessville, ON, CAN	460	DeWalt 20V Brushless Circular Saw S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:59 PM EDT Asset located in: Burgessville, ON, CAN
457	Power Fist 25 ft 1 Gauge Booster Cables S/N: Not Available C/W: With quantity of Master Locks Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:59 PM EDT Asset located in: Burgessville, ON, CAN	461	DeWalt DCS573B Circular Saw S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:00 PM EDT Asset located in: Burgessville, ON, CAN
458	DeWalt 20V Brushless Circular Saw S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:59 PM EDT Asset located in: Burgessville, ON, CAN	462	DeWalt 20V Brushless Circular Saw S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:00 PM EDT Asset located in: Burgessville, ON, CAN
459	Quantity of Conveyor Rollers S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 03:59 PM EDT Asset located in: Burgessville, ON, CAN	463	Quantity of (2) Parking Boards S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:00 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
464	Quantity of Chairs S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:00 PM EDT Asset located in: Burgessville, ON, CAN	468	Quantity of Auxiliary Hydraulic Lines S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:01 PM EDT Asset located in: Burgessville, ON, CAN
465	2 ft x 6 ft Table S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:00 PM EDT Asset located in: Burgessville, ON, CAN	469	Quantity of Screener Conveyor Belts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:01 PM EDT Asset located in: Burgessville, ON, CAN
466	Quantity of Miscellaneous Items S/N: Not Available C/W: Golf Clubs, lumber, saw horse Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:00 PM EDT Asset located in: Burgessville, ON, CAN	470	41.5 in Wide Conveyor Belt S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:01 PM EDT Asset located in: Burgessville, ON, CAN
467	Quantity of Valves S/N: Not Available C/W: Comes w/ Electric motor, metal plates Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:01 PM EDT Asset located in: Burgessville, ON, CAN	471	Quantity of (2) Conveyor Belt S/N: Not Available C/W: 29.5 in, 23.5 in Wide Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:01 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
472	Router Crafter Woodworking Tool S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:01 PM EDT Asset located in: Burgessville, ON, CAN	476	Quantity of Crusher Belts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:02 PM EDT Asset located in: Burgessville, ON, CAN
473	Quantity of Miscellaneous Woodworking Tools S/N: Not Available C/W: Dewalt Grease Gun, workbench with clamp Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:02 PM EDT Asset located in: Burgessville, ON, CAN	477	Quantity of Crusher Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:02 PM EDT Asset located in: Burgessville, ON, CAN
474	GE SensorDry Dryer S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:02 PM EDT Asset located in: Burgessville, ON, CAN	478	Quantity of Measuring Wheels S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:02 PM EDT Asset located in: Burgessville, ON, CAN
475	43 in x 33 in Workbench S/N: Not Available C/W: 14 in Cut-off Saw Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:02 PM EDT Asset located in: Burgessville, ON, CAN	479	Quantity of Parts S/N: Not Available C/W: Alternator, Assorted Hoses/Springs /Fittings/Wire Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:03 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
480	Quantity of Quantity of Bucket Teeth S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:03 PM EDT Asset located in: Burgessville, ON, CAN	484	Campbell Hausfeld Flux Core 80 Electric Welder S/N: Not Available C/W: Air Hose, Quantity Of Fastners/Fittings, Hydraulic Gear Pumps Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:03 PM EDT Asset located in: Burgessville, ON, CAN
481	Quantity of Torque Rods and Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:03 PM EDT Asset located in: Burgessville, ON, CAN	485	Quantity of Quantity Of GPS Modules, Nuts /Screws/Bolts, Plow Controllers S/N: Not Available C/W: Assorted Truck Parts Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:04 PM EDT Asset located in: Burgessville, ON, CAN
482	Quantity of Hose S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:03 PM EDT Asset located in: Burgessville, ON, CAN	486	Quantity of Assorted Truck Parts/Accessories S/N: Not Available C/W: Alternator, PTO Kit, Assorted Air Filters Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:04 PM EDT Asset located in: Burgessville, ON, CAN
483	Quantity of Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:03 PM EDT Asset located in: Burgessville, ON, CAN	487	Quantity of Assorted Fluids S/N: Not Available C/W: Brake Cleaner, Oil, ATF(Transmission Fluid), Spray Paint Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:04 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
488	Quantity of Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:04 PM EDT Asset located in: Burgessville, ON, CAN	492	Quantity of Batteries/ Battery Boosters S/N: Not Available C/W: Quantity Of Assorted Truck Parts /Hardware Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:05 PM EDT Asset located in: Burgessville, ON, CAN
489	Quantity of Straps/Headed Pins, Safety Equipment S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:04 PM EDT Asset located in: Burgessville, ON, CAN	493	Quantity of Miscellaneous Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:05 PM EDT Asset located in: Burgessville, ON, CAN
490	Quantity of Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:04 PM EDT Asset located in: Burgessville, ON, CAN	494	Quantity of Ryobi Angle Grinders, Mixed Signs, Bobcat Parts, Fasteners S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:05 PM EDT Asset located in: Burgessville, ON, CAN
491	Quantity of Assorted Tools S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:05 PM EDT Asset located in: Burgessville, ON, CAN	495	Quantity of Conveyor Rollers S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:05 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
496	Quantity of Spiral Wrap S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:05 PM EDT Asset located in: Burgessville, ON, CAN	500	Quantity of PVC Parts S/N: Not Available C/W: Pipes, fittings Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:06 PM EDT Asset located in: Burgessville, ON, CAN
497	Quantity of Bearing Units and Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:06 PM EDT Asset located in: Burgessville, ON, CAN	501	Quantity of PVC Fittings and Pipe S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:06 PM EDT Asset located in: Burgessville, ON, CAN
498	Quantity of Welding Wire and Miscellaneous Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:06 PM EDT Asset located in: Burgessville, ON, CAN	502	Quantity of PVC Parts/ Pipe S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:06 PM EDT Asset located in: Burgessville, ON, CAN
499	Quantity of Truck Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:06 PM EDT Asset located in: Burgessville, ON, CAN	503	Tool box S/N: Not Available C/W: mower lift Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:07 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
504	Quantity of S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:07 PM EDT Asset located in: Burgessville, ON, CAN	508	Tire Inflation Cage S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:07 PM EDT Asset located in: Burgessville, ON, CAN
505	Miscellaneous Lumber S/N: Not Available C/W: HBC-30 String Trimmer Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:07 PM EDT Asset located in: Burgessville, ON, CAN	509	Solideal 19.5L-24 Tire S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:08 PM EDT Asset located in: Burgessville, ON, CAN
506	Quantity of Wood and Siding S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:07 PM EDT Asset located in: Burgessville, ON, CAN	510	Quantity of (2) 710/50R26.5 Wheel Loader Tires S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:08 PM EDT Asset located in: Burgessville, ON, CAN
507	Quantity of Sheet Metal S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:07 PM EDT Asset located in: Burgessville, ON, CAN	511	Quantity of (3) Wheel Loader Tires S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:08 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
512	Quantity of (3) Miscellaneous Tires S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:08 PM EDT Asset located in: Burgessville, ON, CAN	516	Quantity of (4) 285/75R16 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:09 PM EDT Asset located in: Burgessville, ON, CAN
513	Quantity of (2) Mixed Tires S/N: Not Available C/W: Some Tires with Wheels, (1) 255/70R17, (1) 235/80R17 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:08 PM EDT Asset located in: Burgessville, ON, CAN	517	Quantity of (4) 285/75R16 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:09 PM EDT Asset located in: Burgessville, ON, CAN
514	Quantity of (2) 265/70R17 Tires S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:08 PM EDT Asset located in: Burgessville, ON, CAN	518	Quantity of (2) Mixed Tires S/N: Not Available C/W: Some Tires with Wheels, (1) 245/75R16, (1) 245/75R17 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:09 PM EDT Asset located in: Burgessville, ON, CAN
515	Quantity of (2) 235/80R16 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:09 PM EDT Asset located in: Burgessville, ON, CAN	519	Quantity of (2) Mixed Tires S/N: Not Available C/W: All Tires with Wheels, (1) 235/60R17, (1) 245/75R16 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:09 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
520	Heavy Duty Driven Conveyor Pulley (Unused) S/N: Not Available C/W: To Fit Lippmann 4800 Impact Crusher, 12.6" Diameter, Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Additional information available online Lot closing time: Mon, Sep 28, 04:09 PM EDT Asset located in: Burgessville, ON, CAN	524	55 in x 51 in Metal plate S/N: Not Available C/W: 1 in Thickness Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:10 PM EDT Asset located in: Burgessville, ON, CAN
521	Quantity of Wooden Blocks and Tarps S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:10 PM EDT Asset located in: Burgessville, ON, CAN	525	Headlamp Aligner, Tint Meter S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:10 PM EDT Asset located in: Burgessville, ON, CAN
522	Quantity of Outrigging Bases and Bolts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:10 PM EDT Asset located in: Burgessville, ON, CAN	526	2018 Bauman 1140P Salt Spreader - Fits Tractor S/N: 18018 C/W: 3 PT, steel hopper, PTO driven, 40in spread width, 11 cu ft capacity Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:10 PM EDT Asset located in: Burgessville, ON, CAN
523	Message Board S/N: Not Available C/W: Ball Hitch Carrier Trailer Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:10 PM EDT Asset located in: Burgessville, ON, CAN	527	2023 Bauman 1140P Salt Spreader - Fits Tractor S/N: 230462 C/W: 3PT, steel hopper, PTO driven, 40in spread width, 11 cu ft capacity Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:11 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
528	Fisher Salt Spreader S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:11 PM EDT Asset located in: Burgessville, ON, CAN	532	Quantity of Wooden Stakes S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:11 PM EDT Asset located in: Burgessville, ON, CAN
529	Tornado Electric Salt Spreader - Fits Truck S/N: Not Available C/W: To Fit Tornado Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:11 PM EDT Asset located in: Burgessville, ON, CAN	533	2017 Bauman 1140P Salt Spreader - Fits Tractor S/N: 17539 C/W: 3 pt, Cat 1, drop salter, steel hopper, PTO driven, 40in spread width, 11 cy ft capacity Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:12 PM EDT Asset located in: Burgessville, ON, CAN
530	Quantity of Cat Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:11 PM EDT Asset located in: Burgessville, ON, CAN	534	2017 Bauman 640P Salt Spreader - Fits Tractor S/N: 17485 C/W: 3PT, drop salter, steel hopper, PTO driven, 40in spread width, 6 cu ft capacity Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:12 PM EDT Asset located in: Burgessville, ON, CAN
531	Quantity of Belts/ Conveyor Belt S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:11 PM EDT Asset located in: Burgessville, ON, CAN	535	HLA Mounting Bracket S/N: 20LA87637 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:12 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
536	Quantity of Rims S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:12 PM EDT Asset located in: Burgessville, ON, CAN	540	8 ft Aluminum Trench Box (adjustable width) S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:13 PM EDT Asset located in: Burgessville, ON, CAN
537	Quantity of (2) Steel Rim S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:12 PM EDT Asset located in: Burgessville, ON, CAN	541	Quantity of Double Net Straw Blankets S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:13 PM EDT Asset located in: Burgessville, ON, CAN
538	Stump Jumper S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:12 PM EDT Asset located in: Burgessville, ON, CAN	542	Cylindrical Steel Tank S/N: Not Available C/W: 41 in Diameter Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:13 PM EDT Asset located in: Burgessville, ON, CAN
539	Assorted Fluid Pails S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:13 PM EDT Asset located in: Burgessville, ON, CAN	543	Tarps, Quantity of Electrical Cables, Mud-flaps S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:13 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
544	Quantity of Conveyor Rollers S/N: Not Available C/W: 15", 19" Rollers Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:13 PM EDT Asset located in: Burgessville, ON, CAN	548	Conveyor Belt S/N: Not Available C/W: 37.5" (Width) Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:14 PM EDT Asset located in: Burgessville, ON, CAN
545	Quantity of Miscellaneous parts S/N: Not Available C/W: Goodyear 265/70R17 Wheel with tire Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:14 PM EDT Asset located in: Burgessville, ON, CAN	549	Quantity of Shelves S/N: Not Available C/W: (2) 6' x 2', (1) 7' x 2' Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:14 PM EDT Asset located in: Burgessville, ON, CAN
546	Conveyor Belt S/N: Not Available C/W: 40" (Width) Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:14 PM EDT Asset located in: Burgessville, ON, CAN	550	Quantity of (4) Metal Crates S/N: Not Available C/W: (3) 58" x 45", (1) 66" x 32" Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:14 PM EDT Asset located in: Burgessville, ON, CAN
547	Quantity of Conveyor Belt S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:14 PM EDT Asset located in: Burgessville, ON, CAN	551	61 in (L) x 48 in (W) Frame Material Handling Cart S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:15 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
552	75 in x 75 in Bin S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:15 PM EDT Asset located in: Burgessville, ON, CAN	556	Quantity of Metal Parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:15 PM EDT Asset located in: Burgessville, ON, CAN
553	Quantity of (4) Brake Drums S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:15 PM EDT Asset located in: Burgessville, ON, CAN	557	Quantity of (3) 1040 L Chemical Totes S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:16 PM EDT Asset located in: Burgessville, ON, CAN
554	Quantity of Miscellaneous Tubing S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:15 PM EDT Asset located in: Burgessville, ON, CAN	558	Quantity of (2) 8 ft 10 in x 4 ft Metal Crates S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:16 PM EDT Asset located in: Burgessville, ON, CAN
555	Quantity of 67 in Scrapers S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:15 PM EDT Asset located in: Burgessville, ON, CAN	559	Quantity of (4) 53 in x 44 in Metal Crates S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:16 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
560	Quantity of Miscellaneous metal parts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:16 PM EDT Asset located in: Burgessville, ON, CAN	564	Quantity of Conveyor Belt Fragments S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:17 PM EDT Asset located in: Burgessville, ON, CAN
561	Quantity of Fittings and Connectors S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:16 PM EDT Asset located in: Burgessville, ON, CAN	565	Quantity of (4) Totes S/N: Not Available C/W: (3) 1000 L Totes Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:17 PM EDT Asset located in: Burgessville, ON, CAN
562	Quantity of (2) 30000 BTU Air Handlers S/N: Not Available C/W: Single Phase, 240 V / 208 V Input Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:16 PM EDT Asset located in: Burgessville, ON, CAN	566	Quantity of Rope Slings S/N: Not Available C/W: Booster cables Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:17 PM EDT Asset located in: Burgessville, ON, CAN
563	Quantity of Spools with Cable S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:17 PM EDT Asset located in: Burgessville, ON, CAN	567	Quantity of (2) 62 in x 22 in Corrugated Arch Culvert S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:17 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
568	Quantity of Hitch Arms S/N: Not Available C/W: 24" Narrowed Disc, quantity of hex bolts Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:17 PM EDT Asset located in: Burgessville, ON, CAN	572	Quantity of Scaffolding Frames S/N: Not Available C/W: 91" Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:18 PM EDT Asset located in: Burgessville, ON, CAN
569	Quantity of Plastic Sheetings S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:18 PM EDT Asset located in: Burgessville, ON, CAN	573	Quantity of Grader Blades S/N: Not Available C/W: Toolbox with bolts Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:18 PM EDT Asset located in: Burgessville, ON, CAN
570	Quantity of Hoses S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:18 PM EDT Asset located in: Burgessville, ON, CAN	574	Quantity of Septic Parts S/N: Not Available C/W: Septic Risers, Riser lids, Adapter Rings, cast iron water line valve Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:18 PM EDT Asset located in: Burgessville, ON, CAN
571	48 in x 50 in Screen Mesh S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:18 PM EDT Asset located in: Burgessville, ON, CAN	575	Quantity of Mounting Brackets S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:19 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
576	Quantity of (2) 175/80D13 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:19 PM EDT Asset located in: Burgessville, ON, CAN	580	Quantity of Concrete Blocks S/N: Not Available C/W: (approx 25) Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:19 PM EDT Asset located in: Burgessville, ON, CAN
577	Quantity of Pipe S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:19 PM EDT Asset located in: Burgessville, ON, CAN	581	Quantity of Hose S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:20 PM EDT Asset located in: Burgessville, ON, CAN
578	16.9-24 Tires S/N: Not Available C/W: 15 in Rim Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:19 PM EDT Asset located in: Burgessville, ON, CAN	582	Quantity of Mixed Tires S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:20 PM EDT Asset located in: Burgessville, ON, CAN
579	Quantity of (9) Pallets of Ice Melt S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:19 PM EDT Asset located in: Burgessville, ON, CAN	583	Quantity of (4) Mixed Tires S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:20 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
584	Quantity of (3) 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:20 PM EDT Asset located in: Burgessville, ON, CAN	589	Job Site Box S/N: Not Available C/W: 48 in x 24 in x 28 in Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:21 PM EDT Asset located in: Burgessville, ON, CAN
585	Quantity of (21) Pallets of Sewer Risers, Grates and Cement Blocks S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:20 PM EDT Asset located in: Burgessville, ON, CAN	590	40 Channel CB Radios S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:21 PM EDT Asset located in: Burgessville, ON, CAN
586	Yardworks 27 in Walk-Behind Snow Blower S/N: 113640318 C/W: Tecumseh 318 cc Gasoline Engine Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:20 PM EDT Asset located in: Burgessville, ON, CAN	591	Quantity of (2) Barrels S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:21 PM EDT Asset located in: Burgessville, ON, CAN
587	Fowlee High Precision Dial Indicator S/N: Not Available C/W: Magnetic Base Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:21 PM EDT Asset located in: Burgessville, ON, CAN	592	Quantity of (4) Shop Carts S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:21 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
593	Plate and Truck Fender S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN	597	Tractor Rim S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN
594	Crusher Drum- To Fit Lippmann 4800 S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN	598	JET JEDG-1 Electronic Digital Drum Gauge S/N: 310604 C/W: 0-20 In. Range, Pointed Anvils Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN
595	Tailgate, Fender - Fits Truck S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN	598A	Quantity of (20) 3 in Rolls for 950k and 966 Cat Loader S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN
596	Quantity of (2) 48 in Fork Tines S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN	598B	3 in Thermal Rolls for 950k and 966 S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
598C	Quantity of (3) 57 mm x 22.8 m Ribbon for 950 Cat Loader S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:22 PM EDT Asset located in: Burgessville, ON, CAN	600B	7 ft 3-Point Back Blade S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN
599	Patron TA 65 Jumping Jack Tamper S/N: Not Available C/W: 2022 US EPA Label, Honda GXR 120 Gasoline Engine, 121cm3 Usage: 43 Hr Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN	600C	36 in Bale Spear S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN
600	8 ft x 5 ft 6 in Illuminated Message Board S/N: Not Available C/W: Flag Pole Attachments Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN	601	2004 40 ft High Cube Storage Container S/N: TCNU9132214 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN
600A	Quantity of (4) Tires S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN	602	2004 40 ft High Cube Storage Container S/N: TCNU9004300 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN

Lot #	Details	Lot #	Details
603	2004 40 ft High Cube Storage Container S/N: TCKU9871890 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN		
604	20 ft Standard Storage Container S/N: Not Available Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:23 PM EDT Asset located in: Burgessville, ON, CAN		
605	2002 20 ft Standard Storage Container S/N: HJCU8166829 Usage: Not Available Notes: Equipment viewing will be available September 21-27 from 8:30am to 4:30PM, For more information, please contact TM: Steve Gagner PH: 226.688.8800 - Located at 385432 Oxford 59, Burgessville, ON - Buyer's responsibility for removal of this item ; Must be picked up within 14 days. Cannot be resold from this location - Lot closing time: Mon, Sep 28, 04:24 PM EDT Asset located in: Burgessville, ON, CAN		