



Darlingford, MB, CAN - Jun 11, 2025

Lot #	Details	Lot #	Details
1	Labtronics 919 Moisture Meter S/N: 780644 C/W: Moisture Charts, Smart Scoop, Bin Probe, Scale Usage: Not Available Lot closing time: Wed, Jun 11, 12:00 PM CDT Asset located in: Darlingford, MB	7	2008 Chevrolet 2500HD 4x4 Crew Cab Silverado Pickup S/N: 1GCHK23K68F218930 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Tool Box, 4173 kg GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 383,515 Km Notes: CARFAX AVAILABLE ONLINE; Lot closing time: Wed, Jun 11, 12:06 PM CDT Asset located in: Darlingford, MB
2	FARMI 35 Grain Moisture Tester S/N: Not Available C/W: Sieves, Sample Scoops, Aluminum Drop Pan Usage: Not Available Lot closing time: Wed, Jun 11, 12:01 PM CDT Asset located in: Darlingford, MB	8	Woods 2162 Batwing 14 Ft Brush Cutter S/N: 891642 Usage: Not Available Lot closing time: Wed, Jun 11, 12:07 PM CDT Asset located in: Darlingford, MB
3	Custombuilt Fuel Trailer S/N: CANNOT VERIFY C/W: 1450 gal Diesel Tank, 12.5L-15SL Tires, 120v Pump, Hose Usage: Not Available Lot closing time: Wed, Jun 11, 12:02 PM CDT Asset located in: Darlingford, MB	9	Crown 4 Tire Hydraulic Dump Pull Scraper S/N: Not Available C/W: 6 cyd Capacity, 9.00-20 Usage: Not Available Lot closing time: Wed, Jun 11, 12:08 PM CDT Asset located in: Darlingford, MB
4	1995 ULC Bulk Oil Steel Storage Tank S/N: 8937C C/W: Pneumatic Hose Reel Usage: Not Available Lot closing time: Wed, Jun 11, 12:03 PM CDT Asset located in: Darlingford, MB	10	168 in Hydraulic Pull Grader S/N: CANNOT VERIFY C/W: 2-way Tilt & Angle Usage: Not Available Lot closing time: Wed, Jun 11, 12:09 PM CDT Asset located in: Darlingford, MB
5	Yamaha Kodiak 4x4 ATV S/N: CANNOT VERIFY C/W: Electric Start, 5 Forward Gears w/ Reverse, Yamaha Gasoline Engine, High/Low Gears, Winch Usage: 9,701 Km Lot closing time: Wed, Jun 11, 12:04 PM CDT Asset located in: Darlingford, MB	11	1500 gal NH3 Tank S/N: W28W01816 C/W: 16.5L-16.1 Tires, Steel Tank, Tank Certified, Safety Kit Usage: Not Available Lot closing time: Wed, Jun 11, 12:10 PM CDT Asset located in: Darlingford, MB
6	2012 General Metal 6108 108 in Everest Snow Blower S/N: 60129072 C/W: 1000 PTO, Dual Auger, Hyd. Spout & Tip Usage: Not Available Lot closing time: Wed, Jun 11, 12:05 PM CDT Asset located in: Darlingford, MB	12	1994 REM 1026 Grain Vac S/N: RM9410261648 C/W: 1000 PTO, 10 in Auger, Hose, Cleanup Nozzle Usage: Not Available Notes: SHEDDED Lot closing time: Wed, Jun 11, 12:11 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
13	2014 Farm King 1370 13 in x 70 ft Swing Grain Auger S/N: Y137014000153 C/W: 540 PTO, Reverser, Double Flight Hopper, Hydraulic Winch, Mover, Bin Full Sensor Usage: Not Available Notes: ONE OWNER ; NO FERTILIZER AS PER OWNER Lot closing time: Wed, Jun 11, 12:12 PM CDT Asset located in: Darlingford, MB	19	1999 Flexi-Coil 820 62 ft Chisel Plow S/N: C820B00U09432599 C/W: 12 in Spacing, C-Shanks, Sweeps, Rear Harrow, Rear Hitch Usage: Not Available Lot closing time: Wed, Jun 11, 12:18 PM CDT Asset located in: Darlingford, MB
14	1997 Farm King 10 in x 60 ft Swing Grain Auger S/N: 9101957 C/W: 540 PTO, Electric Winch, Grain Bin Fill Indicator Usage: Not Available Notes: NO FERTILIZER AS PER OWNER Lot closing time: Wed, Jun 11, 12:13 PM CDT Asset located in: Darlingford, MB	20	1990 Wil-Rich 47 ft Cultivator S/N: 436904 C/W: 7 in Spacing, C-Shanks, Sweeps, Rear Harrow Usage: Not Available Lot closing time: Wed, Jun 11, 12:19 PM CDT Asset located in: Darlingford, MB
15	Farm King 8 in x 41 ft Grain Auger S/N: Not Available C/W: Honda 18 hp Gasoline Engine, Hydraulic Winch Usage: Not Available Notes: The closing times of Lots 15 & 16 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 12:14 PM CDT Asset located in: Darlingford, MB	21	1993 Case 5600 39 ft Chisel Plow S/N: JAG0003964 C/W: 12 in Spacing, C-Shanks, Rear Harrow, Rear Hitch, NH3 Package, Rear Winch Usage: Not Available Lot closing time: Wed, Jun 11, 12:20 PM CDT Asset located in: Darlingford, MB
16	1999 Farm King 831 8 in x 31 ft Grain Auger S/N: 9115519 C/W: Honda 13 hp Gasoline Engine Usage: Not Available Notes: ONE OWNER ; The closing times of Lots 15 & 16 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 12:15 PM CDT Asset located in: Darlingford, MB	22	M&W Earthmaster 1165 12 ft Tandem Disc Ripper S/N: 001438 C/W: 21 in Smooth Front Discs, 21.5 in Smooth Rear Discs, 15 in Spacing, Hitch Leveling Usage: Not Available Lot closing time: Wed, Jun 11, 12:21 PM CDT Asset located in: Darlingford, MB
17	1967 Farmall 656 2WD Tractor S/N: 25860 C/W: 5 Forward 1 Reverse, Manual Transmission, 70 hp Engine, 2 Rear Remotes, 540 PTO, Drawbar, 11L-15 Front Tires, 18.4x34 Rear Tires, Rear Wheel Weights, 11 in x 41 ft Mounted Auger Usage: 6,087 Hr Lot closing time: Wed, Jun 11, 12:16 PM CDT Asset located in: Darlingford, MB	23	2021 Riteway RR 900 ST 60 in Paddle Rock Picker S/N: 211700 C/W: Hydraulic Drive, Hydraulic Swing Hitch Usage: Not Available Notes: ONE OWNER ; SHEDDED Lot closing time: Wed, Jun 11, 12:22 PM CDT Asset located in: Darlingford, MB
18	1995 Westfield J207-31 7 in x 31 ft Grain Auger S/N: 84145 C/W: Briggs & Stratton 23A Gasoline Engine Usage: Not Available Notes: ONE OWNER Lot closing time: Wed, Jun 11, 12:17 PM CDT Asset located in: Darlingford, MB	24	2010 Summers Super 72 ft Heavy Harrow S/N: J1189 C/W: 5 Bar, 9/16 in x 23 in Tines, Hydraulic Down Pressure Usage: Not Available Lot closing time: Wed, Jun 11, 12:23 PM CDT Asset located in: Darlingford, MB
		25	2014 Great Plains Turbo-Max 40 ft Vertical Disc S/N: GPC4681H C/W: 18 in Wave Edge Front Discs, 18 in Wave Edge Rear Discs, 8 in Spacing, Hitch Leveling, Roller Cage, Rolling Spike Harrows Usage: Not Available Notes: NEW FRONT DISC BLADES ON FRONT GANGS OF MAIN FRAME AS PER OWNER Lot closing time: Wed, Jun 11, 12:24 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
26	2019 Excel 50 ft Land Roller S/N: 1972 C/W: 42 in Drum Diameter, 5/8 in Drum Wall Thickness, Rear Steering, Floating Hitch Usage: Not Available Notes: ONE OWNER Lot closing time: Wed, Jun 11, 12:25 PM CDT Asset located in: Darlingford, MB	34	2003 Freightliner CL120 Columbia 6x4 Grain Truck S/N: 1FUJA6CG13PK34052 C/W: Detroit Series 60 12.7 L Diesel 470 hp Engine, 2002 US EPA Label, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 3.7:1 Axle Ratio, Aluminum Wheels, 11R22.5, Air Ride Suspension, 232 in Wheelbase, 20 ft Long x 64 in High Body, Electric Roll Tarp, Remote End Gate & Hoist Control, A/C Usage: 1,363,144 Km Notes: SHEDDED ; MB SAFETY VALID UNTIL APRIL 30, 2026; CARFAX AVAILABLE ONLINE ; Lot closing time: Wed, Jun 11, 12:32 PM CDT Asset located in: Darlingford, MB
27	Letorneau LP 12-15 4 Tire Hydraulic Pull Scraper S/N: CANNOT VERIFY C/W: 15 cyd Capacity, Trail Scraper, 26.5R25 Tires, Hydraulic Push Off Unload Usage: Not Available Lot closing time: Wed, Jun 11, 12:26 PM CDT Asset located in: Darlingford, MB	35	1988 Kenworth T600A 6x4 Grain Truck S/N: 2XKADB9XXJM919694 C/W: Cat 3406B Diesel Engine, Eaton Fuller 15-Speed Manual Transmission, Differential Lock, 5443 kg Front Axle, 18144 kg Rears, 3.90:1 Axle Ratio, 11R22.5, Air Ride Suspension, 240 in Wheelbase, PTO, Tracker 20 ft Long x 63 in High Steel Body, Manual Roll Tarp, Swing Tailgate, A/C Usage: 1,303,604 Km Notes: SHEDDED ; MB SAFETY VALID UNTIL APRIL 30, 2026; CARFAX AVAILABLE ONLINE ; Lot closing time: Wed, Jun 11, 12:33 PM CDT Asset located in: Darlingford, MB
28	1982 Case 780B 4x2 Backhoe Loader S/N: 9146252 C/W: Enclosed Cab, 96 in Loader Bucket, 36 in Backhoe Digging Bucket Usage: 6,395 Hr Notes: LEAKING CYLINDER Lot closing time: Wed, Jun 11, 12:27 PM CDT Asset located in: Darlingford, MB	36	1984 Ford 800 6x4 Grain Truck S/N: 1FDYT80K5EVA11608 C/W: Ford V8 Gasoline Engine, 1984 US EPA Label, Eaton Fuller Manual Transmission, 4082 kg Front Axle, 15422 kg Rears, 365/80R20 Front Tires, 10R22.5 Rear Tires, Spring Suspension, 204 in Wheelbase, PTO, Midland 18 ft Long x 58 in High Steel Body, Manual Roll Tarp, Swing Tailgate Usage: 261,424 Km Notes: MB PROOF OF OWNERSHIP/TOD; SHEDDED ; CARFAX AVAILABLE ONLINE ; Lot closing time: Wed, Jun 11, 12:34 PM CDT Asset located in: Darlingford, MB
29	84 in General Purpose Skid Steer Bucket S/N: CANNOT VERIFY Usage: Not Available Lot closing time: Wed, Jun 11, 12:28 PM CDT Asset located in: Darlingford, MB	37	2017 Peterbilt 567 6x4 T/A Sleeper Truck Tractor S/N: 1XPCDP0X3HD435461 C/W: Paccar MX-13 12.9 L Diesel 500 hp Engine, 17301 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Triple Differential Locks, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 918,610 Km Notes: DELETED EMISSIONS ; SHEDDED ; MB SAFETY VALID UNTIL MARCH 31, 2026; CARFAX AVAILABLE ONLINE ; Lot closing time: Wed, Jun 11, 12:35 PM CDT Asset located in: Darlingford, MB
30	58 in Digging Bucket - Fits Case 780B S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 12:42 PM CDT Asset located in: Darlingford, MB		
31	1981 Fiat Allis FR20 Wheel Loader S/N: 80C0171 C/W: Enclosed Cab, 116 in Bucket, 23.5-25 Tires Usage: 542 Hr Lot closing time: Wed, Jun 11, 12:30 PM CDT Asset located in: Darlingford, MB		
33	Cat D6D Crawler Dozer S/N: Not Available C/W: Open Operator Station, 142 in Wide Straight Blade 30 in Single Grouser Track Shoes, Carco 60 Winch, Rear Auxiliary Hydraulics, Direct Drive Usage: 8,992 Hr Lot closing time: Wed, Jun 11, 12:31 PM CDT Asset located in: Darlingford, MB		

Lot #	Details	Lot #	Details
38	2016 Bergs GT238 38 ft T/A Grain Trailer S/N: 2M9GT2389GW189135 C/W: Air Ride Suspension, Air Brakes, 2 Hoppers, Manual Traps, Steel Sides & Aluminum Slopes Box, 84 in, Side Walls, Electric Roll Tarp, Air Scales, Aluminum Wheels, 11R22.5 Tires, Tarp Remote Usage: Not Available Notes: ONE OWNER ; SHEDDED ; MB SAFETY VALID UNTIL MARCH 31, 2026; CROSS CANADA SEARCH AVAILABLE ONLINE ; Lot closing time: Wed, Jun 11, 12:36 PM CDT Asset located in: Darlingford, MB	42	2005 John Deere 4920 120 ft 4x4 High Clearance Self-Propelled Sprayer S/N: N04920X002507 C/W: 4064 Machine Hours Showing, Hydrostatic, Air Conditioner, Air Ride Seat, GreenStar Display, Trimble Antenna/ Receiver, Autosteer, Automatic Boom Height Control, 1200 gal Stainless Steel Tank, Foam Markers, Rinse Tank, 5 Nozzle Bodies, 7 Section Control, 380/105R50, Rear Duals, Hydraulic Axle Adjustment, Norac AutoBoom, High Flow Product Pump Usage: 4,065 Hr Lot closing time: Wed, Jun 11, 12:40 PM CDT Asset located in: Darlingford, MB
39	53 ft T/A Sprayer Step Deck Trailer S/N: CANNOT VERIFY C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 11 ft Upper Deck, 42 ft Main Deck, 96 in Overall Deck Width, Storage Compartments, Wood Flooring, 10R17.5 Tires, Chemical Handler, Pump, 2550 gal Poly Tank, 2500 gal Poly Tank, 1600 gal Poly Tank Usage: Not Available Notes: MB PROOF OF OWNERSHIP/TOD AS PER OWNER ; CANNOT VERIFY SERIAL NUMBER - WILL REQUIRE GOVERNMENT ISSUED VIN TO REGISTER/EXPORT; Lot closing time: Wed, Jun 11, 12:37 PM CDT Asset located in: Darlingford, MB	43	Quantity of (4) Crop Dividers S/N: Not Available Usage: Not Available Notes: TWO BRACKETS INCLUDED Lot closing time: Wed, Jun 11, 12:55 PM CDT Asset located in: Darlingford, MB
40	2002 Brent 876 850 bu S/A Grain Cart S/N: B19670136 C/W: 16 in PTO Driven Hydraulic Folding Auger, Roll Tarp, Big 1000 PTO, 30.5x32 Usage: Not Available Notes: NEW BOTTOM AUGER 2025 AS PER OWNER Lot closing time: Wed, Jun 11, 12:38 PM CDT Asset located in: Darlingford, MB	44	2010 Bourgault 3310 65 ft PHD Air Drill S/N: 40281PH01 C/W: 9.8 in Spacing, Double Shoot, Mid-Row Banding, Variable Rate Control, Seed Monitor, Semi-Pneumatic 4.5 in Packer, 19 in Discs, 2010 Bourgault 6550 550 bu 4 Compartment Tow-Behind Air Cart, Tank S/N 40093AS-07 Double Fan, 10 in Auger Loading System, Bag Lift, Storage Platform, 591 Display, 540/65R24 Front Tires Dual 650/75R34 Rear Tires, Deluxe L/U Auger Usage: Not Available Notes: SHEDDED Lot closing time: Wed, Jun 11, 12:42 PM CDT Asset located in: Darlingford, MB
41	2009 Massey Ferguson 9220 30 ft Swather Windrower S/N: HU08193 C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive, Outback S3 Display, Outback GPS Autosteer Autosteer, Tier 2, 2008 US EPA Label, 18.4x26 Front Tires, 12.5-15 Rear Tires, Header S/N - AGCM52300AHDW1171, Massey Ferguson 5200 30 ft Draper Header, P/U Reel, Center Delivery Usage: 669 Hr Notes: ONE OWNER ; SHEDDED Lot closing time: Wed, Jun 11, 12:39 PM CDT Asset located in: Darlingford, MB	45	1980 Case 2290 2WD Tractor S/N: 9906363 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 4 Reverse, Partial Powershift, 109 hp Engine, 2 Rear Remotes, 540/1000 PTO, 3-Point Hitch, Drawbar, 11.00x16 Front Tires, Dual 18.4x38 Rear Tires Usage: 4,917 Hr Notes: SHEDDED Lot closing time: Wed, Jun 11, 12:43 PM CDT Asset located in: Darlingford, MB
		46	1994 Ford 8670 4WD Tractor S/N: D401002XFORD8670 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 10 Reverse, Powershift, 170 hp Engine, Buhler Allied 2895S Loader, 4 Rear Remotes, Exterior 3-Point Hitch Controls, 540/1000 PTO, 3-Point Hitch, Drawbar, 16.9-28 Front Tires, 20.8x42 Rear Tires Usage: 7,679 Hr Notes: SHEDDED Lot closing time: Wed, Jun 11, 12:44 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
46A	Custom Built 52 in Tractor Pallet Forks S/N: CANNOT VERIFY C/W: To Fit Allied Usage: Not Available Lot closing time: Wed, Jun 11, 12:59 PM CDT Asset located in: Darlingford, MB	51	2015 John Deere S680 Combine Harvester S/N: 1H0S680STF0775599 C/W: 1671 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, Rear View Camera, GS3 CommandCentre 4600 Display, StarFire 3000 Antenna/ Receiver, AutoTrac Autosteer, SF1 Activation, Rock Trap, Single Rotor, 26 ft Auger, Contour Master Lateral Tilt Feederhouse, Power Folding Grain Tank Extensions, Chaff Spreader, Fine Cut Chopper, PowerCast Tailboard, 580/85R42 Dual Front Tires, 750/65R26 Rear Tires, Heated Seat Usage: 2,556 Hr Notes: DELETED EMISSIONS ; SELLING WITH ORIGINAL DEF SYSTEM COMPONENTS Lot closing time: Wed, Jun 11, 12:50 PM CDT Asset located in: Darlingford, MB
47	Quantity of (2) 20.8R42 Tires - Fits Ford 8670 S/N: Not Available C/W: (2) Dual Spacers, Bolts Usage: Not Available Lot closing time: Wed, Jun 11, 01:00 PM CDT Asset located in: Darlingford, MB	52	2012 John Deere 640FD 40 ft Flex Draper Combine Header S/N: 1H0640FDEC0745609 C/W: Air Reel, Cross Auger, Double Knife Drive, Auto HHS In Flex Or Rigid, Both Long & Short Dividers Usage: Not Available Notes: SHEDDED ; The closing times of Lots 52 & 53 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:05 PM CDT Asset located in: Darlingford, MB
48	2007 New Holland TG275 Row Crop 4WD Tractor S/N: Z7RW01834 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Power Shift, IntelliView III Display, New Holland 372 Antenna/ Receiver, IntelliSteer Autosteer, 275 hp Engine, 2007 US EPA Label, Front Weights, 4 Rear Remotes, ISOBUS, Exterior 3-Point Hitch Controls, 540 /1000/Big 1000 PTO, 3-Point Hitch, Drawbar, Dual 380/80R38 Front Tires, Dual 480/80R50 Rear Tires, Rear Wheel Weights, Cruise Control, Super Steer, Heated Seats Usage: 7,476 Hr Notes: SHEDDED Lot closing time: Wed, Jun 11, 12:47 PM CDT Asset located in: Darlingford, MB	53	2011 John Deere 635F 35 ft Flex Combine Header S/N: 1H00635FEB0742583 C/W: To Fit John Deere S680, P/U Reel, AWS Air Assist Bar, Poly Skid Plates, Auto HHS In Flex Or Rigid, Long & Short Dividers Usage: Not Available Notes: SHEDDED ; The closing times of Lots 52 & 53 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 12:52 PM CDT Asset located in: Darlingford, MB
49	2012 Versatile 2375 Articulated Tractor S/N: 334954 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 12 Forward 4 Reverse, Standard Shift, Outback STS Display, Hemisphere Antenna/ Receiver, Outback Autosteer, 375 hp Engine, 2012 US EPA Label, 4 Rear Remotes, Drawbar, Dual 710/70R38 Tires Usage: 2,753 Hr Notes: ONE OWNER ; SHEDDED Lot closing time: Wed, Jun 11, 12:48 PM CDT Asset located in: Darlingford, MB	54	2015 John Deere 615P 15 ft Combine Pickup Header S/N: 1H00615PEF0775389 C/W: To Fit John Deere S680 Usage: Not Available Notes: SHEDDED Lot closing time: Wed, Jun 11, 01:06 PM CDT Asset located in: Darlingford, MB
50	2012 Case IH Quadtrac 550 Track Tractor S/N: ZBF128192 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 16 Forward 4 Reverse, Forward/ Reverse Shuttle, AFS Pro 700 Display, AFS 372 Antenna/ Receiver, AccuGuide Autosteer, 550 hp Engine, Tow-Cable, Front Weights, 6 Rear Remotes, ISOBUS, Big 1000 PTO, Drawbar, 30 in Tracks, 3127 Driveline Hrs, Twin-Flow 113 GPM, Heated Seats, Belly Mount Tow Cable Usage: 5,141 Hr Notes: SHEDDED ; DELETED EMISSIONS Lot closing time: Wed, Jun 11, 12:49 PM CDT Asset located in: Darlingford, MB	55	Case AFS Pro 600 Guidance Display S/N: 813310036 Usage: Not Available Lot closing time: Wed, Jun 11, 12:54 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
56	2007 John Deere StarFire ITC GNSS Receiver S/N: PCGT01C340979 Usage: Not Available Lot closing time: Wed, Jun 11, 12:55 PM CDT Asset located in: Darlingford, MB	63	2017 Concept 1825G +/- 6400 bu Smooth Wall Hopper Grain Bin S/N: 20170700014 C/W: 18 ft Diameter, Bolted To Concrete, Horizontal Aeration System Lid Opener, Ladder, Grain Gauge, OPI Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 61 - 64 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:02 PM CDT Asset located in: Darlingford, MB
57	Outback Antenna Cables & Power Cables S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 12:56 PM CDT Asset located in: Darlingford, MB	64	2017 Concept 1825G +/- 6400 bu Smooth Wall Hopper Grain Bin S/N: 20170700013 C/W: 18 ft Diameter, Bolted To Concrete, Horizontal Aeration System Lid Opener, Ladder, Grain Gauge, OPI Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 61 - 64 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:03 PM CDT Asset located in: Darlingford, MB
58	Quantity of (3) Large Wire Combine Concave - Fits John Deere STS & S Series S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 01:07 PM CDT Asset located in: Darlingford, MB		
59	Quantity of Combine Concave - Fits John Deere STS & S Series S/N: Not Available C/W: Small & Large Wire Usage: Not Available Lot closing time: Wed, Jun 11, 12:58 PM CDT Asset located in: Darlingford, MB		
60	Quantity of (3) Small Wire Combine Concave - Fits John Deere STS & S Series S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 01:08 PM CDT Asset located in: Darlingford, MB		
61	2019 Concept 1825G +/- 6400 bu Smooth Wall Hopper Grain Bin S/N: 20190100610 C/W: 18 ft Diameter, Bolted To Concrete, Horizontal Aeration System Lid Opener, Ladder, Grain Gauge, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 61 - 64 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:00 PM CDT Asset located in: Darlingford, MB	65	Westeel +/- 4750 bu 6 Ring Hopper Grain Bin S/N: Not Available C/W: 19 ft Diameter, Stor-King Hopper, Tube Aeration, OPI Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 65 - 67 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:04 PM CDT Asset located in: Darlingford, MB
62	2019 Concept 1825G +/- 6400 bu Smooth Wall Hopper Grain Bin S/N: 20190400739 C/W: 18 ft Diameter, Bolted To Concrete, Horizontal Aeration System Lid Opener, Ladder, Grain Gauge, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 61 - 64 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:01 PM CDT Asset located in: Darlingford, MB	66	Westeel +/- 4750 bu 6 Ring Hopper Grain Bin S/N: Not Available C/W: 19 ft Diameter, Rocket Aeration, Ladder, OPI Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 65 - 67 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:05 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
67	Westeel +/- 4750 bu 6 Ring Hopper Grain Bin S/N: Not Available C/W: 19 ft Diameter, Bolted to Cement, Hopper, Rocket Aeration, Lid Opener, OPI Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 65 - 67 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:06 PM CDT Asset located in: Darlingford, MB	71	Behlen +/- 4000 bu Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Bolted To Concrete, Stor-King 1600C Hopper, Tube Aeration Ladder w /Cage, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:10 PM CDT Asset located in: Darlingford, MB
68	Behlen +/- 4000 bu Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Bolted To Concrete, Stor-King 1600C Hopper, Tube Aeration Ladder w /Cage, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:07 PM CDT Asset located in: Darlingford, MB	72	Behlen +/- 4000 bu Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Bolted To Concrete, Stor-King 1600C Hopper, Tube Aeration Lid Opener, Ladder w/Cage, Temperature Cable Usage: Not Available Notes: LIGHT NOT SELLING WITH ; BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:11 PM CDT Asset located in: Darlingford, MB
69	Behlen +/- 4000 bu Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Bolted To Concrete, Stor-King 1600C Hopper, Tube Aeration Lid Opener, Ladder w/Cage, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:08 PM CDT Asset located in: Darlingford, MB	73	Behlen +/- 4000 bu Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Bolted To Concrete, Aeration Lid Opener, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:12 PM CDT Asset located in: Darlingford, MB
70	Behlen +/- 4000 bu Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Bolted To Concrete, Tube Aeration Lid Opener, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:09 PM CDT Asset located in: Darlingford, MB	74	Behlen +/- 4000 bu Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Meridian Hopper, Tube Aeration Lid Opener, Ladder w/Cage Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:13 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
75	Behlen +/- 4000 bu 3 Ring Hopper Grain Bin S/N: Not Available C/W: 16 ft Diameter, Stor King Hopper, Tube Aeration Lid Opener, Ladder w/Cage Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:14 PM CDT Asset located in: Darlingford, MB	79	2009 Westeel 1412F +/- 2250 bu Epoxy Lined Hopper Grain Bin S/N: 65090690 C/W: 14 ft Diameter, Double Skids, Lid Opener, Ladder, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 77 - 80 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:18 PM CDT Asset located in: Darlingford, MB
76	Westeel +/- 4000 bu 5 Ring Hopper Grain Bin S/N: Not Available C/W: 19 ft Diameter, Bolted To Concrete, Hopper, Lid Opener, Ladder, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 68 - 76 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:15 PM CDT Asset located in: Darlingford, MB	80	Meridian Grainmax 2000 +/- 2000 bu Smooth Wall Hopper Grain Bin S/N: Not Available C/W: 14 ft Diameter, Single Skids, Tube Aeration Lid Opener, Ladder, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 77 - 80 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:19 PM CDT Asset located in: Darlingford, MB
77	Westeel +/- 2000 bu Hopper Grain Bin S/N: Not Available C/W: 14 ft Diameter, Tube Aeration, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 77 - 80 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:16 PM CDT Asset located in: Darlingford, MB	81	+/- 1500 bu Smooth Wall Hopper Grain Bin S/N: Not Available C/W: 12 ft Diameter, Cement Floor, Lid Opener, Ladder Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 81 - 87 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:20 PM CDT Asset located in: Darlingford, MB
78	Univision 16-12 +/- 2700 bu 3 Ring Epoxy Lined Hopper Grain Bin S/N: UB002034 C/W: 16 ft Diameter, Ladder, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 77 - 80 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:17 PM CDT Asset located in: Darlingford, MB	82	Lode King +/- 1500 bu Smooth Wall Hopper Grain Bin S/N: Not Available C/W: 12 ft Diameter, Bolted To Concrete, Lid Opener, Ladder, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 81 - 87 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:21 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
83	1987 Lode King +/- 1500 bu Smooth Wall Hopper Grain Bin S/N: 3265 C/W: 12 ft Diameter, Bolted To Concrete, Lid Opener, Ladder Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 81 - 87 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:22 PM CDT Asset located in: Darlingford, MB	87	+/- 1300 bu Smooth Wall Hopper Grain Bin S/N: Not Available C/W: 12 ft Diameter, Cement Floor, Lid Opener, Ladder Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 81 - 87 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:26 PM CDT Asset located in: Darlingford, MB
84	+/- 1500 bu Smooth Wall Hopper Grain Bin S/N: Not Available C/W: 12 ft Diameter, Cement Floor, Lid Opener, Ladder Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 81 - 87 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:23 PM CDT Asset located in: Darlingford, MB	88	Westeel +/- 5000 bu 8 Ring Grain Bin S/N: Not Available C/W: 19 ft Diameter, Cement Floor, Tube Style Lid Opener, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 88 - 91 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:27 PM CDT Asset located in: Darlingford, MB
85	Meridian +/- 1500 bu Smooth Wall Hopper Grain Bin S/N: 1790288 C/W: 12 ft Diameter, Single Skids, Ladder Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 81 - 87 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:24 PM CDT Asset located in: Darlingford, MB	89	Westeel +/- 5000 bu 8 Ring Grain Bin S/N: Not Available C/W: 19 ft Diameter, Cement Floor, Tube Style, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 88 - 91 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:28 PM CDT Asset located in: Darlingford, MB
86	+/- 1500 bu Smooth Wall Hopper Grain Bin S/N: Not Available C/W: 12 ft Diameter, Cement Floor, Tube Style Lid Opener, Ladder Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 81 - 87 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:25 PM CDT Asset located in: Darlingford, MB	90	Westeel +/- 5000 bu 8 Ring Grain Bin S/N: Not Available C/W: 19 ft Diameter, Cement Floor, Tube Style Ladder w/Cage, OPI Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 88 - 91 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:29 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
91	Westeel +/- 5000 bu 8 Ring Grain Bin S/N: Not Available C/W: 19 ft Diameter, Cement Floor, Tube Style Ladder w/Cage, Temperature Cable Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. ; The closing times of Lots 88 - 91 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:30 PM CDT Asset located in: Darlingford, MB	97	GSI 7.5 hp Aeration Fan S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 01:36 PM CDT Asset located in: Darlingford, MB
92	Westeel +/- 2800 bu 5 Ring Grain Bin S/N: Not Available C/W: 19 ft Diameter, Lid Opener Usage: Not Available Notes: BIN REMOVAL DEADLINE: SEP/1/2025 ; BIN LOCATION: 49.2147818, -98.3218492 ; BUYER RESPONSIBLE FOR LOAD OUT AND ALL ASSOCIATED COSTS. Lot closing time: Wed, Jun 11, 01:31 PM CDT Asset located in: Darlingford, MB	98	2017 Grain Guard GGF-80511 5 hp Aeration Fan S/N: 2017FCW05797 Usage: Not Available Notes: The closing times of Lots 98 - 103 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:37 PM CDT Asset located in: Darlingford, MB
93	StorMax OPI Controller S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 01:32 PM CDT Asset located in: Darlingford, MB	99	2017 Grain Guard GGF-80511 5 hp Aeration Fan S/N: 2017FCW00152 Usage: Not Available Notes: The closing times of Lots 98 - 103 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:38 PM CDT Asset located in: Darlingford, MB
94	Grain Guard GG914-100 Propane Aeration Heater S/N: 02056 C/W: 100,000 BTU Usage: Not Available Notes: The closing times of Lots 94 - 96 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:33 PM CDT Asset located in: Darlingford, MB	100	2017 Grain Guard GGF-80511 5 hp Aeration Fan S/N: 2017FCW00150 Usage: Not Available Notes: The closing times of Lots 98 - 103 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:39 PM CDT Asset located in: Darlingford, MB
95	Grain Guard GG914-60 Propane Aeration Heater S/N: 2210 C/W: 60,000 BTU Usage: Not Available Notes: The closing times of Lots 94 - 96 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:34 PM CDT Asset located in: Darlingford, MB	101	2016 Grain Guard GGF-80511 5 hp Aeration Fan S/N: 2016FCW8479 Usage: Not Available Notes: The closing times of Lots 98 - 103 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:40 PM CDT Asset located in: Darlingford, MB
96	2015 Grain Guard GGH-8351 Propane Aeration Heater S/N: 20150117 C/W: 100,000 BTU Usage: Not Available Notes: The closing times of Lots 94 - 96 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:35 PM CDT Asset located in: Darlingford, MB	102	2014 Grain Guard GGF-80511 5 hp Aeration Fan S/N: 2014FC53991 Usage: Not Available Notes: The closing times of Lots 98 - 103 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:41 PM CDT Asset located in: Darlingford, MB
		103	Grain Guard 5 hp Aeration Fan S/N: 98002159 Usage: Not Available Notes: The closing times of Lots 98 - 103 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:42 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
104	2014 GSI ILC-318-1C 3 hp Aeration Fan S/N: VA146914 Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:43 PM CDT Asset located in: Darlingford, MB	111	Keho 3 hp Aeration Fan S/N: Not Available Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:50 PM CDT Asset located in: Darlingford, MB
105	Field King 3 hp Aeration Fan S/N: Not Available Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:44 PM CDT Asset located in: Darlingford, MB	112	Caldwell 1 hp Aeration Fan S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 01:51 PM CDT Asset located in: Darlingford, MB
106	Behlen 3 hp Aeration Fan S/N: Not Available Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:45 PM CDT Asset located in: Darlingford, MB	113	The Adventer 3 hp Aeration Fan S/N: 0249 Usage: Not Available Notes: The closing times of Lots 113 - 117 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:52 PM CDT Asset located in: Darlingford, MB
107	Caldwell 3 hp Aeration Fan S/N: 86F336 Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:46 PM CDT Asset located in: Darlingford, MB	114	The Adventer 3 hp Aeration Fan S/N: 0252 Usage: Not Available Notes: The closing times of Lots 113 - 117 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:53 PM CDT Asset located in: Darlingford, MB
108	Keho 3 hp Aeration Fan S/N: Not Available Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:47 PM CDT Asset located in: Darlingford, MB	115	Keho Aeration Fan S/N: Not Available Usage: Not Available Notes: The closing times of Lots 113 - 117 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:54 PM CDT Asset located in: Darlingford, MB
109	Keho 3 hp Aeration Fan S/N: Not Available Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:48 PM CDT Asset located in: Darlingford, MB	116	The Adventer 3 hp Aeration Fan S/N: 0263 Usage: Not Available Notes: The closing times of Lots 113 - 117 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:55 PM CDT Asset located in: Darlingford, MB
110	Keho 3 hp Aeration Fan S/N: Not Available Usage: Not Available Notes: The closing times of Lots 104 - 111 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:49 PM CDT Asset located in: Darlingford, MB	117	The Adventer 3 hp Aeration Fan S/N: CANNOT VERIFY Usage: Not Available Notes: The closing times of Lots 113 - 117 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:56 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
118	Quantity of Aeration Transitions S/N: Not Available Usage: Not Available Notes: ; The closing times of Lots 118 - 120 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:57 PM CDT Asset located in: Darlingford, MB	127	Quick Attach 3-Point Hitch S/N: Not Available C/W: To Fit Ford 8670 Usage: Not Available Lot closing time: Wed, Jun 11, 02:06 PM CDT Asset located in: Darlingford, MB
119	Quantity of (3) Aeration Transitions S/N: Not Available Usage: Not Available Notes: ; The closing times of Lots 118 - 120 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:58 PM CDT Asset located in: Darlingford, MB	128	Quick Attach 3-Point Hitch S/N: Not Available C/W: To Fit New Holland Usage: Not Available Lot closing time: Wed, Jun 11, 02:07 PM CDT Asset located in: Darlingford, MB
120	Quantity of Aeration Transitions S/N: Not Available Usage: Not Available Notes: ; The closing times of Lots 118 - 120 are tied together. Any time extensions will be applied to all lots. Lot closing time: Wed, Jun 11, 01:59 PM CDT Asset located in: Darlingford, MB	129	CWS 40 ft Air Reel S/N: Not Available C/W: Fan, Accessories, To Fit John Deere 640FD Header Usage: Not Available Lot closing time: Wed, Jun 11, 02:08 PM CDT Asset located in: Darlingford, MB
121	Quantity of (2) Aeration Fan Stands S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:00 PM CDT Asset located in: Darlingford, MB	130	2012 Farm King 10 ft Tow-Behind Steel Tapered Swath Roller S/N: C1000SR12000087 Usage: Not Available Notes: ONE OWNER Lot closing time: Wed, Jun 11, 02:09 PM CDT Asset located in: Darlingford, MB
122	Grain Bin Floor Aeration S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:01 PM CDT Asset located in: Darlingford, MB	131	16 ft Wagon Frame S/N: CANNOT VERIFY Usage: Not Available Lot closing time: Wed, Jun 11, 02:10 PM CDT Asset located in: Darlingford, MB
123	Quantity of Grain Bin Bolts S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:02 PM CDT Asset located in: Darlingford, MB	132	60 in Chain Rock Picker S/N: CANNOT VERIFY Usage: Not Available Lot closing time: Wed, Jun 11, 02:11 PM CDT Asset located in: Darlingford, MB
124	Quantity of (7) Grain Bin Lid Openers S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:03 PM CDT Asset located in: Darlingford, MB	133	Quantity of (8) Maxon 2-Way Radios S/N: Not Available C/W: (2) Handhelds With Charger Usage: Not Available Lot closing time: Wed, Jun 11, 02:12 PM CDT Asset located in: Darlingford, MB
125	Quantity of Grain Bin Leg Extensions S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:04 PM CDT Asset located in: Darlingford, MB	134	Quantity of (3) GE 2-Way Radios S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:13 PM CDT Asset located in: Darlingford, MB
126	Quantity of Grain Bin Parts S/N: Not Available C/W: Lids, Door Panels, Wall Panels Usage: Not Available Lot closing time: Wed, Jun 11, 02:05 PM CDT Asset located in: Darlingford, MB	135	Quantity of 2-Way Radios S/N: Not Available C/W: Wiring, Antennas, Quick Connectors Usage: Not Available Lot closing time: Wed, Jun 11, 02:14 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
136	Quick Control Spray Boom Remote Control S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:15 PM CDT Asset located in: Darlingford, MB	146	Quantity of (9) Manure Bucket Tines S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:25 PM CDT Asset located in: Darlingford, MB
137	Quantity of Sprayer Parts & Hose S/N: Not Available C/W: Spraying Tips, Sotera Meter, Filters Usage: Not Available Lot closing time: Wed, Jun 11, 02:16 PM CDT Asset located in: Darlingford, MB	147	Pallet Wrangler 90 Pallet Jack S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:26 PM CDT Asset located in: Darlingford, MB
138	MicroTrak MT-NH3 Kit S/N: Not Available C/W: Manifolds, Controller Usage: Not Available Lot closing time: Wed, Jun 11, 02:17 PM CDT Asset located in: Darlingford, MB	148	Cutting Torch Cart S/N: Not Available C/W: Torch Hose Usage: Not Available Lot closing time: Wed, Jun 11, 02:27 PM CDT Asset located in: Darlingford, MB
139	Quantity of (32) NH3 Cultivator Knives S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:18 PM CDT Asset located in: Darlingford, MB	149	Quantity of (5) Oil Barrel Pumps S/N: Not Available C/W: (1) Dozer Greaser Usage: Not Available Lot closing time: Wed, Jun 11, 02:28 PM CDT Asset located in: Darlingford, MB
140	Quantity of Cultivator Sweeps S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:19 PM CDT Asset located in: Darlingford, MB	150	Quantity of Tractor Wheel Weights S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:29 PM CDT Asset located in: Darlingford, MB
141	Quantity of Cultivator Chisels S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:20 PM CDT Asset located in: Darlingford, MB	151	SAFTFIL Bin Level Indicators S/N: Not Available C/W: (3) 8 In Grain Auger Spouts Usage: Not Available Lot closing time: Wed, Jun 11, 02:30 PM CDT Asset located in: Darlingford, MB
142	Quantity of Cultivator Shanks S/N: Not Available C/W: C-Shanks, S-Shanks Usage: Not Available Lot closing time: Wed, Jun 11, 02:21 PM CDT Asset located in: Darlingford, MB	152	Quantity of (3) Hydraulic Cylinders S/N: Not Available C/W: Quantity Of PTO Shafts Usage: Not Available Lot closing time: Wed, Jun 11, 02:31 PM CDT Asset located in: Darlingford, MB
143	Quantity of Harrow Tines S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:22 PM CDT Asset located in: Darlingford, MB	153	Air Drill Manifolds S/N: Not Available C/W: Hose Usage: Not Available Lot closing time: Wed, Jun 11, 02:32 PM CDT Asset located in: Darlingford, MB
144	Quantity of Crop Lifters S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:23 PM CDT Asset located in: Darlingford, MB	154	Quantity of Air Seeder Hose S/N: Not Available C/W: Various Sizes Usage: Not Available Lot closing time: Wed, Jun 11, 02:33 PM CDT Asset located in: Darlingford, MB
145	Truck Cushion Hitch S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:24 PM CDT Asset located in: Darlingford, MB		

Lot #	Details	Lot #	Details
155	U.S. Electrical Motors Electric Motor S/N: Not Available C/W: 5 hp Engine Usage: Not Available Lot closing time: Wed, Jun 11, 02:34 PM CDT Asset located in: Darlingford, MB	165	Sailun 235/75R17.5 Tires (Unused) S/N: Not Available C/W: 8 Bolt Rim Usage: Not Available Lot closing time: Wed, Jun 11, 02:44 PM CDT Asset located in: Darlingford, MB
156	Ford 9682 Cab Fan Motor S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:35 PM CDT Asset located in: Darlingford, MB	166	Carlisle 11L-15 Tires (Unused) S/N: Not Available C/W: (1) On Rim, (1) Not On Rim Usage: Not Available Lot closing time: Wed, Jun 11, 02:45 PM CDT Asset located in: Darlingford, MB
157	32 in Tracks - Fits Case IH 550 S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:36 PM CDT Asset located in: Darlingford, MB	167	Quantity of (2) 9.5L-15 Tires (Unused) S/N: Not Available C/W: (1) On 6 Bolt Rim Usage: Not Available Lot closing time: Wed, Jun 11, 02:46 PM CDT Asset located in: Darlingford, MB
158	Quantity of (2) 20.8R42 Tires - Fits Ford 8670 S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:37 PM CDT Asset located in: Darlingford, MB	168	Quantity of Rims & Tires S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:47 PM CDT Asset located in: Darlingford, MB
159	18.4-38 Tires S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:38 PM CDT Asset located in: Darlingford, MB	169	Load Star 7.00-15 Tires S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:48 PM CDT Asset located in: Darlingford, MB
160	Quantity of (2) 11R24.5 Tires S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:39 PM CDT Asset located in: Darlingford, MB	170	Side Mount Storage Box S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:49 PM CDT Asset located in: Darlingford, MB
161	Quantity of (2) Hankook 11R24.5 Tires S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:40 PM CDT Asset located in: Darlingford, MB	171	Quantity of (5) Grain Auger Hoppers S/N: Not Available C/W: Steel Protection Cage Usage: Not Available Lot closing time: Wed, Jun 11, 02:50 PM CDT Asset located in: Darlingford, MB
162	Quantity of (4) 11R24.5 Mixed Tires S/N: Not Available C/W: Aluminum Rim Usage: Not Available Lot closing time: Wed, Jun 11, 02:41 PM CDT Asset located in: Darlingford, MB	172	Grain Auger Hopper Cover S/N: Not Available C/W: To Fit Farm King 1370 Swing Hopper Usage: Not Available Lot closing time: Wed, Jun 11, 02:51 PM CDT Asset located in: Darlingford, MB
163	Quantity of (4) Hercules 11R22.5 Tires S/N: Not Available C/W: Rims Usage: Not Available Lot closing time: Wed, Jun 11, 02:42 PM CDT Asset located in: Darlingford, MB	173	Quantity of (3) Flexi-Coil Harrow Sections S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:52 PM CDT Asset located in: Darlingford, MB
164	Quantity of (4) 10.00-20 Tires S/N: Not Available C/W: Rims Usage: Not Available Lot closing time: Wed, Jun 11, 02:43 PM CDT Asset located in: Darlingford, MB	174	Quantity of (4) Diamond Harrows Sections S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:53 PM CDT Asset located in: Darlingford, MB

Lot #	Details	Lot #	Details
175	Gooseneck Hitch S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:54 PM CDT Asset located in: Darlingford, MB	185	Engine (Inoperable) S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 03:04 PM CDT Asset located in: Darlingford, MB
176	Truck PTO S/N: Not Available C/W: Contoller Usage: Not Available Lot closing time: Wed, Jun 11, 02:55 PM CDT Asset located in: Darlingford, MB	186	Quantity of (3) Water Pump (Inoperable) S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 03:05 PM CDT Asset located in: Darlingford, MB
177	Quantity of Ladders S/N: Not Available C/W: Various Sizes Usage: Not Available Lot closing time: Wed, Jun 11, 02:56 PM CDT Asset located in: Darlingford, MB	187	Quantity of (3) Kohler 12 hp Engines (Inoperable) S/N: Not Available C/W: Gasoline Engine Usage: Not Available Lot closing time: Wed, Jun 11, 03:06 PM CDT Asset located in: Darlingford, MB
178	Metal Scaffold S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:57 PM CDT Asset located in: Darlingford, MB	188	Aeration Fan (Inoperable) S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 03:07 PM CDT Asset located in: Darlingford, MB
179	Engine Oil Tote S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 02:58 PM CDT Asset located in: Darlingford, MB		
180	Truck Parts S/N: Not Available C/W: Ferring, Wheel Caps, Air Hose, Fifth Wheel Plate Usage: Not Available Lot closing time: Wed, Jun 11, 02:59 PM CDT Asset located in: Darlingford, MB		
181	Quantity of Hydraulic Hoses S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 03:00 PM CDT Asset located in: Darlingford, MB		
182	Quantity of Cable S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 03:01 PM CDT Asset located in: Darlingford, MB		
183	Quantity of Hair Pin Clips S/N: Not Available Usage: Not Available Lot closing time: Wed, Jun 11, 03:02 PM CDT Asset located in: Darlingford, MB		
184	Quantity of Grain Bin Sweep S/N: Not Available C/W: Electric Motors Usage: Not Available Lot closing time: Wed, Jun 11, 03:03 PM CDT Asset located in: Darlingford, MB		