



Texas Regional Auction, USA - Sep 16, 2026

Lot #	Details	Lot #	Details
1	2020 John Deere 4044M 4WD Utility Tractor S/N: 1LV4044MCLM112473 C/W: Located in Lane 14 Spot 23, Differential Lock, 12 Forward 12 Reverse, PowrReverser, Forward/ Reverse Shuttle, 42.5 hp Engine, John Deere 400E Loader w/Joystick, Quick Coupler, 75 in Bucket, 540 PTO, 3-Point Hitch, Drawbar, 260/70D16.5 Front Tires, 420/85D24 Rear Tires Usage: 183 Hr Lot closing time: Wed, Sep 16, 09:00 AM CDT Asset located in: Humble, TX, USA	3	2020 Bobcat CT2025 4WD Utility Tractor S/N: B4VH11017 C/W: 3 Forward 3 Reverse, Hydrostatic Drive, 24.5 hp Engine, 2019 US EPA Label, Bobcat FL7 Loader w/Joystick, Quick Coupler, 57 in Bucket, 540 PTO, 3-Point Hitch, 215/65-14 Front Tires, 385/65-19.5 Rear Tires Usage: 377 Hr Lot closing time: Wed, Sep 16, 09:00 AM CDT Asset located in: Oklahoma City, OK, USA
1A	2021 Massey Ferguson MF2860MH 4WD Utility Tractor S/N: M28600LJT62245 C/W: Located in Lane 14 Spot 20, Enclosed Cab, Air Conditioner, Differential Lock, Hydrostatic Drive, Massey Ferguson FL2814 Loader w/Joystick, Skid Steer Coupler, 68 in Bucket, 2 Rear Remotes, 540 PTO, 9.5-16 Front Tires, 13.6-28 Rear Tires Usage: 1,327 Hr Lot closing time: Wed, Sep 16, 09:00 AM CDT Asset located in: Humble, TX, USA	4	2021 Kubota BX23SLB-R 4WD Utility Tractor S/N: KBUC1DHRVMGJ67467 C/W: Located in Lane 5 Spot 18, Differential Lock, Tier 4, 15.9 kW Engine, 2021 US EPA Label, CARB Compliant, Kubota LA340 Loader w/Joystick, 48 in Bucket, Mid-Mount Remotes, Kubota Backhoe Attachment With 12 in Bucket, 18x8.50-10 Front Tires, 26x12.00-12 Rear Tires Usage: 841 Hr Lot closing time: Wed, Sep 16, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
1B	2021 Massey Ferguson MF2850MH 4WD Utility Tractor S/N: AG3M28500LJT43640 C/W: Located in Lane 14 Spot 25, Differential Lock, Hydrostatic Drive, 48 hp Engine, Massey Ferguson FL2814 Loader w/Joystick, Skid Steer Coupler, 66 in Bucket, 1 Rear Remotes, 540 PTO, 3-Point Hitch, 10x16.5 Front Tires, 17.5L-24 Rear Tires Usage: 252 Hr Lot closing time: Wed, Sep 16, 09:00 AM CDT Asset located in: Humble, TX, USA	5	2014 Kubota MX5100D 4WD Utility Tractor S/N: 68510 C/W: Located in Lane 4 Spot 4, Hydrostatic Drive, 52 hp Engine, 2013 US EPA Label, Kubota LA844 Loader w/Joystick, Quick Coupler, 72 in Bucket, 540 PTO, 3-Point Hitch, 12-16.5 NHS Front Tires, 17.5L-24 Rear Tires Usage: 2,141 Hr Lot closing time: Wed, Sep 16, 09:01 AM CDT Asset located in: Lake Worth, TX, USA
1C	2023 Bad Boy BB4035CHIL 4WD Utility Tractor S/N: BB4035CHIL01230022 C/W: Located in Lane 14 Spot 21, Enclosed Cab, Air Conditioner, Hydrostatic Drive, Bad Boy BBL400C Loader w/Joystick, Skid Steer Coupler, 540 PTO, 3-Point Hitch, 28x8.50-15 Front Tires, 8x16.00-20 Rear Tires Usage: 392 Hr Lot closing time: Wed, Sep 16, 09:00 AM CDT Asset located in: Humble, TX, USA	6	1990 Kubota B8200 HST-D 4WD Utility Tractor S/N: 52896 C/W: Located in Lane 4 Spot 3, Hydrostatic Drive, 19 hp Engine, Kubota BF-300-R Loader w/Joystick, 50 in Bucket, 540 PTO, 3-Point Hitch, Land Pride BB1560 60 in Box Blade, 24x9.50-12 Front Tires, 13.6x16 Rear Tires Usage: 512 Hr Lot closing time: Wed, Sep 16, 09:01 AM CDT Asset located in: Lake Worth, TX, USA
2	2025 John Deere 2032R 4WD Utility Tractor S/N: 1LV2032RVRS128517 C/W: Located in Lane 100 Spot 1, Differential Lock, Hydrostatic Drive, 30.6 hp Engine, 2024 US EPA Label, Mid-Mount Remotes, 72 in Mower Deck, 540 PTO, 3-Point Hitch, Drawbar, 23x8.50-14 Front Tires, 14-17.5 Rear Tires Usage: 7 Hr Lot closing time: Wed, Sep 16, 09:00 AM CDT Asset located in: Humble, TX, USA	7	2007 Mahindra 3525 2WD Utility Tractor S/N: EMBN2686 C/W: Located in Lane 14 Spot 24, Differential Lock, 8 Forward 8 Reverse, 35 hp Engine, 540 PTO, 3-Point Hitch, 6.00-16 Front Tires, 12.4 x28 Rear Tires Usage: 898 Hr Lot closing time: Wed, Sep 16, 09:01 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
8	1993 John Deere 7800 2WD Tractor S/N: RW7800H004700 C/W: Located in Lane 4 Spot 1, Enclosed Cab, Differential Lock, 16 Forward 12 Reverse, PowrQuad, Quick Coupler, 85 in Bucket, 1000 PTO, 3-Point Hitch, 11.00-16SL Front Tires, 18.4 R42 Rear Tires Usage: 7,391 Hr Lot closing time: Wed, Sep 16, 09:02 AM CDT Asset located in: Lake Worth, TX, USA	14	2009 John Deere 5093E 4WD Tractor S/N: LZ5093E160334 C/W: Located in Lane 14 Spot 22, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 12 Forward 12 Reverse, PowrReverser, Forward/ Reverse Shuttle, 69 kW Engine, US EPA Label, Mid-Mount Remotes, LED Lights, 3 Rear Remotes, 540 PTO, 11.2x24 Front Tires, 16.9x30 Rear Tires Usage: 3,967 Hr Lot closing time: Wed, Sep 16, 09:03 AM CDT Asset located in: Humble, TX, USA
8A	2017 John Deere 5045E 4WD Tractor S/N: 5045EJHJ103354 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, SyncShuttle, 75 hp Engine, 2018 US EPA Label, John Deere 520M Loader w /Joystick, Quick Coupler, John Deere 75 in Bucket, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, 9.5x24 Front Tires, 14.9x28 Rear Tires Usage: 424 Hr Lot closing time: Wed, Sep 16, 09:02 AM CDT Asset located in: Lake Worth, TX, USA	15	2016 Kubota L4701 4WD Tractor S/N: 50587 C/W: Located in Lane 4 Spot 2, Hydrostatic Drive, 47 hp Engine, Kubota LA765 Loader w /Joystick, Skid Steer Coupler, Kubota L2236 72 in Bucket, 540 PTO, 3-Point Hitch, 27x10.50-15 Front Tires, 17.5L-24 Rear Tires Usage: 1,050 Hr Lot closing time: Wed, Sep 16, 09:04 AM CDT Asset located in: Lake Worth, TX, USA
10	2019 John Deere 6155M 4WD Tractor S/N: 1L06155MVKK943323 C/W: Located in Lane 14 Spot 26, Enclosed Cab, Air Conditioner, Differential Lock, 16 Forward 16 Reverse, PowerShift, Forward/ Reverse Shuttle, 155 hp Engine, 3 Rear Remotes, 540 PTO, 3-Point Hitch, 540/65R28 Front Tires, 650/65R38 Rear Tires Usage: 916 Hr Notes: Service Records see Documents Lot closing time: Wed, Sep 16, 09:02 AM CDT Asset located in: Humble, TX, USA	16	2013 Kubota M9960D 4WD Tractor S/N: 51642 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 8 Forward 8 Reverse, Manual Transmission, Forward/ Reverse Shuttle, Tier 4, 77.9 kW Engine, 2012 US EPA Label, Kubota LA1353 Loader w/Joystick, Quick Coupler, Bale Fork, 3 Rear Remotes, 540 PTO, 3-Point Hitch, 12.4x24 Front Tires, 18.4x30 Rear Tires Usage: 3,462 Hr Notes: Item at offsite location must be picked up within 14 days of auction (October 2nd) or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 09:04 AM CDT Asset located in: Johnson City, TX, USA
11	2008 John Deere 8330 4WD Tractor S/N: RW8330P020194 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 4 Reverse, PowerShift, 223 kW Engine, 2007 US EPA Label, Front Weights, 4 Rear Remotes, ISOBUS, Exterior 3-Point Hitch Controls, 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar, 420 /85R30 Front Tires, Dual 480/80R46 Rear Tires Usage: 11,672 Hr Notes: From the Fleet of Harvest Time Farms ; September 2025 at 11,649 Hours - John Deere Dealer - Rebuilt Front Steering Cylinders, Front Axle Pins & Bushings, New Complete Tire Set, Turbo Replacement Lot closing time: Wed, Sep 16, 09:03 AM CDT Asset located in: Lake Worth, TX, USA	17	2020 JCB 512-56 Telehandler S/N: JCB5CH7GLK2929401 C/W: Located in Lane 0 Spot 0, Enclosed Cab, Air Conditioner, 56 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 4,731 Hr Notes: The closing times of lots 17 thru 18 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:04 AM CDT Asset located in: Humble, TX, USA
13	2017 Case IH Farmall F120C 4WD Tractor S/N: ZGLF50579 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 12 Reverse, Power Shuttle, Forward/ Reverse Shuttle, Case IH L630 Loader w/Joystick, Skid Steer Coupler, 84 in Bucket, 2 Rear Remotes, 1000 PTO, 3-Point Hitch, Drawbar, 380/85R24 Front Tires, 460 /85R34 Rear Tires, Rear Wheel Weights Usage: 600 Hr Lot closing time: Wed, Sep 16, 09:03 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
18	2020 JCB 512-56 Telehandler S/N: JCB5CH7GHL2930762 C/W: Located in Lane 0 Spot 0, Enclosed Cab, Air Conditioner, 56 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires Usage: 8,333 Hr Notes: The closing times of lots 17 thru 18 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:05 AM CDT Asset located in: Humble, TX, USA	22	2019 Xtreme XR1255 Telehandler S/N: XR125511190794519 C/W: Located in Lane 12 Spot 1, Enclosed Cab, Air Conditioner, Rear View Camera, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Fork Positioner, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 3,755 Hr Notes: The closing times of lots 21 thru 22 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:06 AM CDT Asset located in: Humble, TX, USA
20	2019 JLG 1255 Telehandler S/N: 0160092060 C/W: Located in Lane 7 Spot 16, Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Outriggers, 400/75-28 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: 3,680 Hr Lot closing time: Wed, Sep 16, 09:05 AM CDT Asset located in: Lake Worth, TX, USA	23	2018 Xtreme XR1245 Telehandler S/N: XR124511180493957 C/W: Located in Lane 12 Spot 3, Open Operator Station, 45 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 96 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 9,559 Hr Lot closing time: Wed, Sep 16, 09:06 AM CDT Asset located in: Humble, TX, USA
20A	2012 JLG G12-55A Telehandler S/N: 0160045572 C/W: Open Operator Station, 56 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, 17.5-25 Foam Filled Tires Usage: 2,193 Hr Lot closing time: Wed, Sep 16, 09:05 AM CDT Asset located in: Midland, TX, USA	28	2019 Skyjack SJ1056 Telehandler S/N: 87311403 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 2019 US EPA Label, 72 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires Usage: 3,368 Hr Notes: The closing times of lots 28 thru 29 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:08 AM CDT Asset located in: Midland, TX, USA
21	2019 Xtreme XR1255 Telehandler S/N: XR125511190894584 C/W: Located in Lane 12 Spot 17, Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 96 in Forks, Fork Positioner, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 12,431 Hr Notes: The closing times of lots 21 thru 22 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:06 AM CDT Asset located in: Humble, TX, USA	29	2019 Skyjack SJ1056 Telehandler S/N: 87311399 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2019 US EPA Label, 60 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires Usage: 4,310 Hr Notes: The closing times of lots 28 thru 29 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:08 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
30	2018 Skyjack SJ1056 Telehandler S/N: 87310730 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 2018 US EPA Label, 72 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires Usage: 5,174 Hr Lot closing time: Wed, Sep 16, 09:08 AM CDT Asset located in: Midland, TX, USA	35	2012 JLG G10-55A Telehandler S/N: 0160047904 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Outriggers, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 8,158 Hr Lot closing time: Wed, Sep 16, 09:10 AM CDT Asset located in: Midland, TX, USA
30A	2013 Genie GTH-1056 Telehandler S/N: GTH1013-17589 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 2013 US EPA Label, 60 in Forks, Outriggers, 14.00-24 Foam Filled Tires Usage: 334 Hr Lot closing time: Wed, Sep 16, 09:08 AM CDT Asset located in: Midland, TX, USA	36	2010 JLG G10-55A Telehandler S/N: 0160039015 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Auxiliary Hydraulic Plumbing, 400 /75-28 Tires Usage: 1,518 Hr Lot closing time: Wed, Sep 16, 09:10 AM CDT Asset located in: Midland, TX, USA
31	2018 Cat TL1055 Telehandler S/N: ML501280 C/W: Open Operator Station, Rear View Camera, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Outriggers, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 4,041 Hr Lot closing time: Wed, Sep 16, 09:09 AM CDT Asset located in: Midland, TX, USA	37	2009 JLG G10-55A Telehandler S/N: 160038141 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 878 Hr Lot closing time: Wed, Sep 16, 09:10 AM CDT Asset located in: Midland, TX, USA
32	2012 Cat TL1055C Telehandler S/N: KDE00294 C/W: Located in Lane 12 Spot 18, Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 44 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 7,104 Hr Lot closing time: Wed, Sep 16, 09:09 AM CDT Asset located in: Humble, TX, USA	37A	2008 Genie GTH-1056 Telehandler S/N: GTH1008A12573 C/W: Located in Lane 7 Spot 35, Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, 14.00-24 Tires Usage: 960 Hr Lot closing time: Wed, Sep 16, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
33	2018 Xtreme XR1055 Telehandler S/N: XR105511181094138 C/W: Located in Lane 12 Spot 15, Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Fork Positioner, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 8,730 Hr Lot closing time: Wed, Sep 16, 09:09 AM CDT Asset located in: Humble, TX, USA	39	2019 SkyTrak 10054 Telehandler S/N: 0160098121 C/W: Located in Lane 12 Spot 2, Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 360/85-28 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 09:11 AM CDT Asset located in: Humble, TX, USA
34	2018 Gehl RS10-55 Telehandler S/N: RS1055CL492207 C/W: Located in Lane 7 Spot 32, Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 60 in Forks, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 6,642 Hr Lot closing time: Wed, Sep 16, 09:09 AM CDT Asset located in: Lake Worth, TX, USA	40	2017 SkyTrak 10042 Telehandler S/N: 0160083247 C/W: Open Operator Station, Rear View Camera, 42 ft Max Lift Height, 10000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 400 /75-28 Tires Usage: 7,820 Hr Lot closing time: Wed, Sep 16, 09:11 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
41	2014 JLG 10054 Telehandler S/N: 0160057497 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Manual Coupler, Outriggers, 17.5-25 Tires Usage: 6,511 Hr Lot closing time: Wed, Sep 16, 09:12 AM CDT Asset located in: Midland, TX, USA	45	2007 SkyTrak 10054 Telehandler S/N: 160025304 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 3,400 Hr Notes: The closing times of lots 45 thru 46 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:13 AM CDT Asset located in: Midland, TX, USA
42	2013 SkyTrak 10054 Telehandler S/N: 160054895 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2013 US EPA Label, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires Usage: 6,591 Hr Notes: The closing times of lots 42 thru 44 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:12 AM CDT Asset located in: Midland, TX, USA	46	2006 SkyTrak 10054 Telehandler S/N: 160017987 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Outriggers, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 7,056 Hr Notes: The closing times of lots 45 thru 46 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:13 AM CDT Asset located in: Midland, TX, USA
43	2013 SkyTrak 10054 Telehandler S/N: 0160055414 C/W: 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: Not Available Notes: The closing times of lots 42 thru 44 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:12 AM CDT Asset located in: Midland, TX, USA	49	2014 SkyTrak 10042 Telehandler S/N: 160056818 C/W: Located in Lane 7 Spot 2, Open Operator Station, 42 ft Max Lift Height, 10000 lb Max Lift Capacity, 2013 US EPA Label, 47 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 6,610 Hr Lot closing time: Wed, Sep 16, 09:14 AM CDT Asset located in: Lake Worth, TX, USA
44	2013 SkyTrak 10054 Telehandler S/N: 160050713 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 9,770 Hr Notes: The closing times of lots 42 thru 44 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:12 AM CDT Asset located in: Midland, TX, USA	50	2015 Cat TL943C Telehandler S/N: THH01502 C/W: Open Operator Station, 42 ft Max Lift Height, 9000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 370/75-28 Foam Filled Tires Usage: 5,939 Hr Lot closing time: Wed, Sep 16, 09:14 AM CDT Asset located in: Midland, TX, USA
44A	2010 SkyTrak 10054 Telehandler S/N: 0160039906 C/W: Located in Lane 7 Spot 34, Enclosed Cab, Air Conditioner, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, 17.5-25 Tires Usage: 12,766 Hr Lot closing time: Wed, Sep 16, 09:13 AM CDT Asset located in: Lake Worth, TX, USA	51	2014 Cat TL943C Telehandler S/N: THH01018 C/W: Located in Lane 7 Spot 29, Open Operator Station, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 13.00-24 Aperture Tires Usage: Not Available Lot closing time: Wed, Sep 16, 09:15 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
52	2012 Lull 944E-42 Telehandler S/N: 160049312 C/W: Located in Lane 7 Spot 5, Open Operator Station, Air Ride Seat, 9000 lb Max Lift Capacity, 2010 US EPA Label, 48 in Forks, Auxiliary Hydraulic Plumbing, 14.00-24 Solid Tires Usage: 4,954 Hr Notes: The closing times of lots 52 thru 53 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:15 AM CDT Asset located in: Lake Worth, TX, USA	57	2006 Gehl RS8-44 Telehandler S/N: RS844JX1116235 C/W: Located in Lane 7 Spot 24, Open Operator Station, 44 ft Max Lift Height, 6000 lb Max Lift Capacity, 2006 US EPA Label, 48 in 14.00-24 Tires Usage: 1,705 Hr Lot closing time: Wed, Sep 16, 09:16 AM CDT Asset located in: Lake Worth, TX, USA
53	2012 Lull 944E-42 Telehandler S/N: 0160044613 C/W: Enclosed Cab, Air Conditioner, 42 ft Max Lift Height, 9000 lb Max Lift Capacity, 2012 US EPA Label, 47.5 in Forks, Tilt Carriage, Manual Coupler, 370/75-28 Tires Usage: 10,263 Hr Notes: The closing times of lots 52 thru 53 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:15 AM CDT Asset located in: Livingston, LA, USA	58	2006 Gehl RS8-44 Telehandler S/N: RS844JX1116243 C/W: Located in Lane 7 Spot 3, Open Operator Station, 44 ft Max Lift Height, 8000 lb Max Lift Capacity, 2006 US EPA Label, 60 in Forks, Manual Coupler, 13.00-24 Tires Usage: 2,221 Hr Lot closing time: Wed, Sep 16, 09:17 AM CDT Asset located in: Lake Worth, TX, USA
54	2019 JCB 509.42 Telehandler S/N: JCB5CF7GPK2794772 C/W: Located in Lane 7 Spot 21, Open Operator Station, Air Ride Seat, 42 ft Max Lift Height, 9000 lb Max Lift Capacity, 2019 US EPA Label, 48 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 2,624 Hr Lot closing time: Wed, Sep 16, 09:15 AM CDT Asset located in: Lake Worth, TX, USA	58A	2018 Skyjack SJ843TH Telehandler S/N: 87111262 C/W: Open Operator Station, 43 ft Max Lift Height, 8000 lb Max Lift Capacity, 2018 US EPA Label, 13.00-24 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 09:17 AM CDT Asset located in: Lake Worth, TX, USA
55	2006 JLG G9-43A Telehandler S/N: 160020104 C/W: Located in Lane 7 Spot 18, Open Operator Station, Air Ride Seat, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 60 in Forks, Tilt Carriage, Auxiliary Hydraulic Plumbing, 13.00-24 Tires Usage: 2,777 Hr Lot closing time: Wed, Sep 16, 09:16 AM CDT Asset located in: Lake Worth, TX, USA	61	2018 SkyTrak 8042 Telehandler S/N: 0160087593 C/W: Located in Lane 13 Spot 1, Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, 28 mixed Tires, Hydraulic leveling Usage: Not Available Notes: The closing times of lots 61 thru 62 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:18 AM CDT Asset located in: Humble, TX, USA
56	2020 Genie GTH844 Telehandler S/N: GTH08E-12978 C/W: Located in Lane 13 Spot 2, Open Operator Station, 44 ft Max Lift Height, 8000 lb Max Lift Capacity, 2019 US EPA Label, 60 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 13.00-24 Tires Usage: 2,660 Hr Lot closing time: Wed, Sep 16, 09:16 AM CDT Asset located in: Humble, TX, USA	62	2017 JLG 8042 Telehandler S/N: 0160083563 C/W: Located in Lane 7 Spot 37, Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2017 US EPA Label, 72 in Forks, Auxiliary Hydraulic Plumbing, 13.00-24 Aperture Tires Usage: 5,998 Hr Notes: The closing times of lots 61 thru 62 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:18 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
63	2016 SkyTrak 8042 Telehandler S/N: 0160077150 C/W: Located in Lane 7 Spot 33, Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, 370/75-28 Tires Usage: 4,807 Hr Lot closing time: Wed, Sep 16, 09:18 AM CDT Asset located in: Lake Worth, TX, USA	70	2011 Lull 644E-42 Telehandler S/N: 0160042991 C/W: Located in Lane 7 Spot 1, Open Operator Station, 2008 US EPA Label, 47 in Forks, Tilt Carriage, Manual Coupler, Auxiliary Hydraulic Plumbing, 13.00-24 Aperture Tires, Sliding Boom Usage: 5,559 Hr Lot closing time: Wed, Sep 16, 09:20 AM CDT Asset located in: Lake Worth, TX, USA
65	2005 Gehl RS8-42 Telehandler S/N: RS842JW0415382 C/W: Located in Lane 7 Spot 38, Open Operator Station, Air Ride Seat, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 60 in Forks, 13.00-24 Tires Usage: 3,376 Hr Lot closing time: Wed, Sep 16, 09:19 AM CDT Asset located in: Lake Worth, TX, USA	72	2014 SkyTrak 6042 Telehandler S/N: 0160064001 C/W: Located in Lane 7 Spot 30, Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, 13.00-24 Tires Usage: 2,817 Hr Notes: The closing times of lots 72 thru 73 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:21 AM CDT Asset located in: Lake Worth, TX, USA
67	2022 Cat TL642 Telehandler S/N: T6900340 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 42 ft Max Lift Height, 6500 lb Max Lift Capacity, US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 13.00-24 Tires Usage: 1,546 Hr Notes: The closing times of lots 67 thru 68 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:19 AM CDT Asset located in: Midland, TX, USA	73	2014 SkyTrak 6042 Telehandler S/N: 160063861 C/W: Located in Lane 7 Spot 28, Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US EPA Label, 60 in Forks, Manual Coupler, 13.00-24 Tires Usage: 3,360 Hr Notes: The closing times of lots 72 thru 73 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:21 AM CDT Asset located in: Lake Worth, TX, USA
68	2022 Cat TL642 Telehandler S/N: T6900388 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 42 ft Max Lift Height, 6500 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 13.00-24 Tires Usage: 1,972 Hr Notes: The closing times of lots 67 thru 68 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:20 AM CDT Asset located in: Midland, TX, USA	74	2012 JLG G642-A Telehandler S/N: 0160045441 C/W: Located in Lane 7 Spot 25, Open Operator Station, 0 ft Max Lift Height, 48 in Forks, 13.00-24 Aperture Tires Usage: 4,337 Hr Lot closing time: Wed, Sep 16, 09:21 AM CDT Asset located in: Lake Worth, TX, USA
69	2013 JLG 644E-42 Telehandler S/N: 160050535 C/W: Located in Lane 7 Spot 19, Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 47 in Forks, Auxiliary Hydraulic Plumbing, 13.00-24 Aperture Tires Usage: 5,927 Hr Lot closing time: Wed, Sep 16, 09:20 AM CDT Asset located in: Lake Worth, TX, USA	75	2016 SkyTrak 6036 Telehandler S/N: 160073477 C/W: Located in Lane 7 Spot 22, Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 2015 US EPA Label, 48 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 330 Hr Lot closing time: Wed, Sep 16, 09:22 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
77	2005 Gradall 534D-9 Telehandler S/N: 0160011441 C/W: Open Operator Station, 45 ft Max Lift Height, 9000 lb Max Lift Capacity, 2005 US EPA Label, 47.5 in Forks, Manual Coupler, 13.00-24 Tires Usage: 233 Hr Lot closing time: Wed, Sep 16, 09:22 AM CDT Asset located in: Livingston, LA, USA	80	2019 JCB 930-4 6000 lb Rough Terrain Forklift S/N: JCB93004TK2743768 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 127 in Lowered Mast Height, 47 in Forks, 2019 US EPA Label, JCB 444 TA4-55 R1 4 Cylinder 55 kW 4.4 L Diesel Engine Usage: 3,473 Hr Notes: The closing times of lots 78 thru 81 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:23 AM CDT Asset located in: Lake Worth, TX, USA
78	2019 JCB 9504 10000 lb 4x4 Rough Terrain Forklift S/N: JCB95004VK2743755 C/W: 3 Stage Mast, 125 in Lowered Mast Height, 47 in Forks, Side Shift, 2019 US EPA Label, JCB 444 TA4-55 R1 4 Cylinder 55 kW 4.4 L Diesel Engine Usage: 2,616 Hr Notes: The closing times of lots 78 thru 81 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:23 AM CDT Asset located in: Lake Worth, TX, USA	82	2018 Case 586H 6000 lb 4x2 Rough Terrain Forklift S/N: JJGN580HCJC749471 C/W: Located in Lane 0 Spot 0, 3 Stage Mast, 132 in Lowered Mast Height, 66 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 2,782 Hr Notes: The closing times of lots 82 thru 86 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:24 AM CDT Asset located in: Humble, TX, USA
78A	2018 JCB 950-4 8000 lb 4x4 Rough Terrain Forklift S/N: JCB95004VJ2743463 C/W: 3 Stage Mast, 125 in Lowered Mast Height, 47 in Forks, Fork Positioner, 2018 US EPA Label, JCB 444 TA4-55 R1 4 Cylinder 4.4 L Diesel Engine Usage: 1,404 Hr Notes: The closing times of lots 78 thru 81 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:23 AM CDT Asset located in: Lake Worth, TX, USA	83	2019 Case 586H 6000 lb 4x2 Rough Terrain Forklift S/N: JJGN580HEKC759068 C/W: Located in Lane 0 Spot 0, 3 Stage Mast, 264 in Max Lift Height, 127 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 5,779 Hr Notes: The closing times of lots 82 thru 86 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:24 AM CDT Asset located in: Humble, TX, USA
79	2019 JCB 930-4 T4 6000 lb 4x4 Rough Terrain Forklift S/N: 2743770 C/W: Located in Lane 0 Spot 0, 3 Stage Mast, 120 in Lowered Mast Height, 72 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 2,526 Hr Notes: The closing times of lots 78 thru 81 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:23 AM CDT Asset located in: Humble, TX, USA	84	2019 Case 586H 6000 lb 4x2 Rough Terrain Forklift S/N: JJGN580HPKC759088 C/W: Located in Lane 0 Spot 0, 3 Stage Mast, 264 in Max Lift Height, 127 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 5,848 Hr Notes: The closing times of lots 82 thru 86 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:24 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
85	2019 Case 586H 6000 lb 4x2 Rough Terrain Forklift S/N: JJGN580HPKC759107 C/W: Located in Lane 0 Spot 0, 3 Stage Mast, 120 in Lowered Mast Height, 72 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 5,194 Hr Notes: The closing times of lots 82 thru 86 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:25 AM CDT Asset located in: Humble, TX, USA	96	2024 Yanmar TL100VS Compact Track Loader S/N: ASVTL100VR0000128 C/W: Located in Lane 6 Spot 1, Enclosed Cab, Air Conditioner, Ride Control, Creep Mode, Joystick Steering, Rear View Camera, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Quick Coupler, 86 in Bucket Usage: 1,173 Hr Lot closing time: Wed, Sep 16, 09:28 AM CDT Asset located in: Lake Worth, TX, USA
86	2017 Case 586H 6000 lb 4x2 Rough Terrain Forklift S/N: JJGN580HPHC738895 C/W: Located in Lane 13 Spot 31, 3 Stage Mast, 264 in Max Lift Height, 132 in Lowered Mast Height, 44 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 4,940 Hr Notes: The closing times of lots 82 thru 86 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:25 AM CDT Asset located in: Humble, TX, USA	98	2020 Takeuchi TL12V2 Two-Speed High Flow Compact Track Loader S/N: 412003048 C/W: Located in Lane 6 Spot 33, Enclosed Cab, Air Conditioner, Joystick Steering, Self Leveling, Rear View Camera, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Electric Kit, Hydraulic Coupler, 80 in Bucket Usage: 4,179 Hr Notes: The closing times of lots 98 thru 99 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
86A	2012 Harlo HP6500 6500 lb 4x4 Rough Terrain Forklift S/N: 101716 C/W: 2 Stage Mast, 240 in Max Lift Height, 115 in Lowered Mast Height, 48 in Forks, Side Shift, John Deere 4045TF290A 4 Cylinder 56 kW 4.5 L Diesel Engine Usage: 2,604 Hr Lot closing time: Wed, Sep 16, 09:25 AM CDT Asset located in: Lake Worth, TX, USA	99	2020 Takeuchi TL12V2 Two-Speed High Flow Compact Track Loader S/N: 412003040 C/W: Located in Lane 6 Spot 35, Enclosed Cab, Air Conditioner, Joystick Steering, Self Leveling, Rear View Camera, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Electric Kit, Hydraulic Coupler, 84 in Bucket Usage: 4,818 Hr Notes: The closing times of lots 98 thru 99 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
89	Case 6WMVR 6000 lb 4x2 Rough Terrain Forklift S/N: JJG0291496 C/W: Located in Lane 13 Spot 28, 2 Stage Mast, 128 in Lowered Mast Height, 47 in Forks, Side Shift, Case 4 Cylinder 75 hp 3.9 L Diesel Engine Usage: 3,769 Hr Lot closing time: Wed, Sep 16, 09:26 AM CDT Asset located in: Humble, TX, USA	100	2023 John Deere 333G Compact Track Loader S/N: 1T0333GMPPF455806 C/W: Located in Lane 5 Spot 7, Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Control Pattern Changer, Rear View Camera, Requires Diesel Exhaust Fluid, 18 in Track Belts, Electric Kit, Hydraulic Coupler, 84 in Bucket Usage: 28 Hr Lot closing time: Wed, Sep 16, 09:29 AM CDT Asset located in: Humble, TX, USA
90	2025 Yanmar TL100VS Compact Track Loader S/N: ASVTL100CS0000594 C/W: Located in Lane 7 Spot 65, Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Quick Coupler, 84 in Bucket Usage: 607 Hr Lot closing time: Wed, Sep 16, 09:26 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
101	2021 John Deere 333G Two-Speed Compact Track Loader S/N: 1T0333GMEMF396229 C/W: Located in Lane 6 Spot 1, Enclosed Cab, Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, 73 in Bucket Usage: 1,067 Hr Notes: The closing times of lots 101 thru 102 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	106	2021 Bobcat T770 Two-Speed Compact Track Loader S/N: AT6328612 C/W: Located in Lane 5 Spot 20, Enclosed Cab, Air Conditioner, Ride Control, Creep Mode, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Hydraulic Coupler, Forks Usage: 1,815 Hr Lot closing time: Wed, Sep 16, 09:31 AM CDT Asset located in: Humble, TX, USA
102	2021 John Deere 333G Compact Track Loader S/N: 1T0333GKPLF390108 C/W: Located in Lane 6 Spot 25, Enclosed Cab (Door missing), Joystick Steering, Rear View Camera, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Electric Kit, Hydraulic Coupler, 74 in Bucket, Counterweight Kit Usage: 3,570 Hr Notes: The closing times of lots 101 thru 102 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	108	2022 Cat 299D3 Two-Speed High Flow XPS Compact Track Loader S/N: CAT0299DKDY905592 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 18 in Track Belts, Electric Kit, Hydraulic Coupler, Forks, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Notes: The closing times of lots 108 thru 109 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:32 AM CDT Asset located in: Midland, TX, USA
103	2020 John Deere 333G Two-Speed Compact Track Loader S/N: 1T0333GKTLF370648 C/W: Located in Lane 6 Spot 1, Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler, 78 in Bucket, Counterweight Kit Usage: 2,640 Hr Notes: The closing times of lots 103 thru 104 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	109	2020 Cat 299D3 Compact Track Loader S/N: CAT0299DVDY901515 C/W: Located in Lane 6 Spot 36, Open Operator Station, Joystick Steering, 2019 US EPA Label, 18 in Track Belts, Manual Quick Coupler, Bucket Usage: 4,536 Hr Notes: The closing times of lots 108 thru 109 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:32 AM CDT Asset located in: Lake Worth, TX, USA
104	2020 John Deere 333G Two-Speed Compact Track Loader S/N: 1T0333GKVL370642 C/W: Located in Lane 6 Spot 21, Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler, 72 in Bucket, Counterweight Kit Usage: 3,426 Hr Notes: The closing times of lots 103 thru 104 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	110	2018 Cat 299D2 Two-Speed High Flow XPS Compact Track Loader S/N: CAT0299DHFD204053 C/W: Located in Lane 6 Spot 42, Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Electric Kit, Hydraulic Coupler, 86 in Bucket Usage: 5,137 Hr Notes: The closing times of lots 110 thru 110 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:32 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
111A	2014 Cat 299D Two-Speed Compact Track Loader S/N: CAT0299DKGTC00926 C/W: Located in Lane 6 Spot 45, Open Operator Station, Joystick Steering, 17.6 in Track Belts, Electric Kit, Manual Quick Coupler, 78 in Bucket Usage: 4,658 Hr Notes: All Units from Same Well Maintained Owner Fleet - Lot 111A, 1045, 1052, 1053, 1054 Lot closing time: Wed, Sep 16, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	123	2018 Bobcat T650 Two-Speed Compact Track Loader S/N: ALJG27602 C/W: Located in Lane 6 Spot 58, Enclosed Cab, Air Conditioner, Joystick Steering, 2018 US EPA Label, 18 in Track Belts, Manual Quick Coupler Usage: 3,211 Hr Lot closing time: Wed, Sep 16, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
113	2022 Bobcat T740 Two-Speed Compact Track Loader S/N: B3CA21881 C/W: Located in Lane 5 Spot 18, Open Operator Station, Ride Control, Creep Mode, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, 18 in Track Belts, Manual Quick Coupler, 76 in Bucket Usage: 1,297 Hr Lot closing time: Wed, Sep 16, 09:33 AM CDT Asset located in: Humble, TX, USA	124	2018 Bobcat T650 Compact Track Loader S/N: ALJG27357 C/W: Located in Lane 5 Spot 15, Open Operator Station, Creep Mode, Joystick Steering, Control Pattern Changer, 17.5 in Track Belts, Hydraulic Coupler, 77 in Bucket Usage: 720 Hr Lot closing time: Wed, Sep 16, 09:36 AM CDT Asset located in: Humble, TX, USA
117	2023 Kubota SVL97-2 High Flow Compact Track Loader S/N: KBCZ064CKP1J79524 C/W: Located in Lane 5 Spot 8, Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, Tier 4, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Hydraulic Coupler, 81 in Bucket Usage: 664 Hr Lot closing time: Wed, Sep 16, 09:34 AM CDT Asset located in: Humble, TX, USA	125	2017 Bobcat T650 Two-Speed Compact Track Loader S/N: ALJG22766 C/W: Located in Lane 5 Spot 10, Enclosed Cab (Door missing), Air Conditioner, 17.5 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 4,618 Hr Lot closing time: Wed, Sep 16, 09:37 AM CDT Asset located in: Humble, TX, USA
118	2019 John Deere 331G Two-Speed Compact Track Loader S/N: 1T0331GMCJF338856 C/W: Located in Lane 6 Spot 29, Enclosed Cab, Air Conditioner, Creep Mode, Joystick Steering, Control Pattern Changer, Requires Diesel Exhaust Fluid, 15.5 in Track Belts, Electric Kit, Hydraulic Coupler, 83 in Bucket Usage: 5,970 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 09:35 AM CDT Asset located in: Lake Worth, TX, USA	126	2020 Takeuchi TL10V2 Compact Track Loader S/N: 410003897 C/W: Open Operator Station, Joystick Steering, Rear View Camera, 16 in Track Belts, Electric Kit, Manual Quick Coupler, 75 in Bucket Usage: 1,583 Hr Lot closing time: Wed, Sep 16, 09:37 AM CDT Asset located in: Newnan, GA, USA
122	2023 ASV RT75 Compact Track Loader S/N: ASVRT075VPDS05265 C/W: Located in Lane 6 Spot 28, Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, 17.5 in Track Belts, Electric Kit, Hydraulic Coupler, 48 in Forks Usage: 1,208 Hr Lot closing time: Wed, Sep 16, 09:36 AM CDT Asset located in: Lake Worth, TX, USA	129	2023 Kubota SVL75-2 Two-Speed Compact Track Loader S/N: KBCZ052CCP1A74128 C/W: Located in Lane 5 Spot 22, Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Quick Coupler Usage: 1,666 Hr Lot closing time: Wed, Sep 16, 09:38 AM CDT Asset located in: Humble, TX, USA
		130	2017 Kubota SVL75-2 Compact Track Loader S/N: 30380 C/W: Located in Lane 7 Spot 64, Open Operator Station, Joystick Steering, 15 in Track Belts, Hydraulic Coupler Usage: 4,222 Hr Lot closing time: Wed, Sep 16, 09:38 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
133	2023 Bobcat T62 Two-Speed Compact Track Loader S/N: B4SF18778 C/W: Located in Lane 5 Spot 2, Open Operator Station, Ride Control, Creep Mode, Joystick Steering, Control Pattern Changer, 12 in Track Belts, Manual Quick Coupler, 66 in Bucket Usage: 1,537 Hr Notes: The closing times of lots 132 thru 138 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:39 AM CDT Asset located in: Humble, TX, USA	147	2022 John Deere 325G Two-Speed Compact Track Loader S/N: 1T0325GKHNJ419101 C/W: Located in Lane 6 Spot 44, Enclosed Cab, Air Conditioner, Creep Mode, Joystick Steering, Self Leveling, 2021 US EPA Label, 15.5 in Track Belts, Electric Kit, Electric Coupler, 78 in Bucket, Counterweight Kit Usage: 1,071 Hr Lot closing time: Wed, Sep 16, 09:43 AM CDT Asset located in: Lake Worth, TX, USA
135	2022 Bobcat T62 Compact Track Loader S/N: B4SF12817 C/W: Located in Lane 5 Spot 17, Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts, 68 in Bucket Usage: 1,586 Hr Notes: The closing times of lots 132 thru 138 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:40 AM CDT Asset located in: Humble, TX, USA	149	2019 Cat 289D Two-Speed Compact Track Loader S/N: CAT0289DCTAW13468 C/W: Located in Lane 6 Spot 50, Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2019 US EPA Label, 18 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 5,790 Hr Notes: The closing times of lots 149 thru 152 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:44 AM CDT Asset located in: Lake Worth, TX, USA
138	2022 Bobcat T62 Two-Speed Compact Track Loader S/N: B4SF12912 C/W: Located in Lane 5 Spot 4, Open Operator Station, Ride Control, Creep Mode, Joystick Steering, Control Pattern Changer, 16 in Track Belts, Manual Quick Coupler, 66 in Bucket Usage: 1,671 Hr Notes: The closing times of lots 132 thru 138 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:41 AM CDT Asset located in: Humble, TX, USA	151	2019 Cat 289D Two-Speed Compact Track Loader S/N: CAT0289DLTAW13465 C/W: Located in Lane 6 Spot 51, Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2019 US EPA Label, 18 in Track Belts, Hydraulic Coupler, 84 in Bucket Usage: 5,836 Hr Notes: The closing times of lots 149 thru 152 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
142	2021 Bobcat T62 Two-Speed Compact Track Loader S/N: B4SF11439 C/W: Located in Lane 5 Spot 19, Open Operator Station, Ride Control, Creep Mode, Joystick Steering, Control Pattern Changer, 12 in Track Belts, Manual Quick Coupler, 78 in Bucket Usage: 2,341 Hr Lot closing time: Wed, Sep 16, 09:42 AM CDT Asset located in: Humble, TX, USA	152	2017 Cat 289D Two-Speed Compact Track Loader S/N: CAT0289DKTAW06198 C/W: Located in Lane 6 Spot 26, Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, 18 in Track Belts, Electric Kit, Manual Quick Coupler, 68 in Bucket Usage: 6,188 Hr Notes: The closing times of lots 149 thru 152 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
146	2018 Case TR270 Compact Track Loader S/N: JAFTR270TJM448426 C/W: Located in Lane 6 Spot 8, Open Operator Station, Joystick Steering, 2018 US EPA Label, 12.5 in Track Belts, Manual Quick Coupler, 72 in Bucket Usage: 2,657 Hr Lot closing time: Wed, Sep 16, 09:43 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
153	2016 John Deere 317G Two-Speed Compact Track Loader S/N: 1T0317GJTGJ303104 C/W: Located in Lane 6 Spot 22, Open Operator Station, Joystick Steering, 2016 US EPA Label, 12.5 in Track Belts, Manual Quick Coupler, 67 in Bucket Usage: 1,922 Hr Lot closing time: Wed, Sep 16, 09:45 AM CDT Asset located in: Lake Worth, TX, USA	160	Takeuchi TL6R Two-Speed Compact Track Loader S/N: Not Available C/W: Located in Lane 58 Spot 0, Open Operator Station, Joystick Steering, 2019 US EPA Label, CARB Compliant, 12 in Track Belts, Electric Kit, Manual Quick Coupler, 67 in Bucket Usage: 2,189 Hr Lot closing time: Wed, Sep 16, 09:47 AM CDT Asset located in: Humble, TX, USA
155	2019 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DTFTL21795 C/W: Located in Lane 5 Spot 5, Enclosed Cab (Door missing), Joystick Steering, Tier 4, 2018 US EPA Label, 12.5 in Track Belts, Manual Quick Coupler, 74 in Bucket Usage: 3,274 Hr Notes: The closing times of lots 155 thru 158 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:46 AM CDT Asset located in: Humble, TX, USA	161	2019 Cat 249D Compact Track Loader S/N: CAT0249DVGWR03400 C/W: Located in Lane 5 Spot 11, Open Operator Station, Joystick Steering, 12.5 in Track Belts, Manual Quick Coupler, 78 in Bucket Usage: 3,571 Hr Notes: The closing times of lots 161 thru 162 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:48 AM CDT Asset located in: Humble, TX, USA
157	2017 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DLFTL10452 C/W: Located in Lane 6 Spot 27, Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, 12.5 in Track Belts, Manual Quick Coupler, 78 in Rock Bucket Usage: 3,748 Hr Notes: The closing times of lots 155 thru 158 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:46 AM CDT Asset located in: Lake Worth, TX, USA	163	2018 Cat 249D Two-Speed Compact Track Loader S/N: CAT0249DVGWR02635 C/W: Located in Lane 6 Spot 41, Open Operator Station, Joystick Steering, 15.5 in Track Belts, Electric Kit, Hydraulic Coupler, 73 in Bucket Usage: 4,394 Hr Lot closing time: Wed, Sep 16, 09:48 AM CDT Asset located in: Lake Worth, TX, USA
158	2017 Cat 259D Compact Track Loader S/N: CAT0259DVFTL12778 C/W: Located in Lane 5 Spot 16, Open Operator Station, Joystick Steering, 16 in Track Belts, Electric Kit, Hydraulic Coupler, 72 in Bucket Usage: 4,283 Hr Notes: The closing times of lots 155 thru 158 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:47 AM CDT Asset located in: Humble, TX, USA	164	2019 Cat 239D3 Compact Track Loader S/N: CAT0239DHHC900658 C/W: Located in Lane 6 Spot 17, Open Operator Station, Joystick Steering, 12.5 in Track Belts, Manual Quick Coupler, 68 in Bucket Usage: 3,066 Hr Lot closing time: Wed, Sep 16, 09:48 AM CDT Asset located in: Lake Worth, TX, USA
159	2016 Bobcat T550 Compact Track Loader S/N: AJZV16488 C/W: Located in Lane 6 Spot 43, Open Operator Station, 2016 US EPA Label, 13 in Track Belts, Manual Quick Coupler, 73 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	166	2022 Manitou 1350RT Compact Track Loader S/N: MAN1350TF0D304545 C/W: Located in Lane 5 Spot 13, Open Operator Station, Joystick Steering, 2021 US EPA Label, 12 in Track Belts, Manual Quick Coupler, 60 in Bucket Usage: 1,190 Hr Lot closing time: Wed, Sep 16, 09:49 AM CDT Asset located in: Humble, TX, USA
		167	2022 Gehl RT105 Compact Track Loader S/N: GHLRT105F0D702105 C/W: Located in Lane 5 Spot 12, Open Operator Station, Joystick Steering, 2021 US EPA Label, 10 in Track Belts, Manual Quick Coupler, 54 in Bucket Usage: 511 Hr Lot closing time: Wed, Sep 16, 09:49 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
167A	2007 Bobcat T140 Compact Track Loader S/N: 529311982 C/W: Located in Lane 6 Spot 48, Open Operator Station, 2007 US EPA Label, 12 in Track Belts, Manual Quick Coupler, 62 in Bucket Usage: 2,809 Hr Lot closing time: Wed, Sep 16, 09:49 AM CDT Asset located in: Lake Worth, TX, USA	175	2022 Toro TX427 Mini Compact Track Loader S/N: 412195359 C/W: Located in Lane 58 Spot 0, Open Operator Station, 2022 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 34 in Bucket, Auger, Ball Hitch Carrier Trailer, Surge Brakes Usage: 996 Hr Lot closing time: Wed, Sep 16, 09:52 AM CDT Asset located in: Humble, TX, USA
169	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P21701 C/W: Located in Lane 58 Spot 0, Open Operator Station, Joystick Steering, Tier 4, 2022 US EPA Label, CARB Compliant, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket Usage: 624 Hr Notes: The closing times of lots 168 thru 171 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:50 AM CDT Asset located in: Humble, TX, USA	176	2021 Toro Dingo TX427 Mini Compact Track Loader S/N: 410391008 C/W: Located in Lane 58 Spot 0, Open Operator Station, 5.5 in Track Belts, Manual Quick Coupler, 34 in Bucket, Auger w/ bits, Ball Hitch Carrier Trailer, Surge Brakes Usage: 643 Hr Lot closing time: Wed, Sep 16, 09:52 AM CDT Asset located in: Humble, TX, USA
170	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P20931 C/W: Located in Lane 58 Spot 0, Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Quick Coupler Usage: 529 Hr Notes: The closing times of lots 168 thru 171 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 09:50 AM CDT Asset located in: Humble, TX, USA	177	2019 Toro TX427 Mini Compact Track Loader S/N: 405528627 C/W: Located in Lane 58 Spot 0, Open Operator Station, Joystick Steering, 6 in Track Belts, Manual Quick Coupler, 34 in Bucket, Auger Attachment, (2) Auger Bits, Ball Hitch Carrier Trailer, Surge Brakes Usage: Not Available Lot closing time: Wed, Sep 16, 09:52 AM CDT Asset located in: Humble, TX, USA
172	2019 Ditch Witch SK1050 Mini Compact Track Loader S/N: DWPSK105HK0001172 C/W: Located in Lane 0 Spot 0, Open Operator Station, 9 in Track Belts, Manual Quick Coupler, 52 in Bucket Usage: 1,794 Hr Lot closing time: Wed, Sep 16, 09:51 AM CDT Asset located in: Humble, TX, USA	178	2013 Toro TX427 Mini Compact Track Loader S/N: 313000253 C/W: Located in Lane 58 Spot 0, Open Operator Station, 2013 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 41 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 09:53 AM CDT Asset located in: Humble, TX, USA
174	2022 Toro TX427 Mini Compact Track Loader S/N: 412195369 C/W: Located in Lane 58 Spot 0, Open Operator Station, 2022 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 34 in Bucket, Ball Hitch Carrier Trailer, Surge Brakes Usage: 439 Hr Lot closing time: Wed, Sep 16, 09:51 AM CDT Asset located in: Humble, TX, USA	179	Barreto 825TKL Mini Compact Track Loader S/N: MS111 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 9 in Track Belts, Manual Quick Coupler, 44 in Bucket Usage: 1,006 Hr Lot closing time: Wed, Sep 16, 09:53 AM CDT Asset located in: Lake Worth, TX, USA
		180	2026 SSL1500-RED Mini Compact Track Loader (Unused) S/N: 07145A C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2025 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 40 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:53 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
181	2026 SSL1500-RED Mini Compact Track Loader (Unused) S/N: 07380A C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	187	2026 SSL1200-GRAY Mini Yanmar Diesel Compact Track Loader (Unused) S/N: 56386 C/W: Located in Lane 56, 9 in Track Belts, Manual Quick Coupler, 42 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:55 AM CDT Asset located in: Lake Worth, TX, USA
182	2026 SSL1200-GRAY Mini Compact Track Loader (Unused) S/N: 06743A C/W: Located in Lane 56 Spot 1, 2016 US EPA Label, 9 in Track Belts, Manual Quick Coupler, 44 in, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	188	2026 CFG KJT27 Mini Compact Track Loader (Unused) S/N: KJT272026M0715260 C/W: 7.75 in Track Belts, Manual Quick Coupler, 44 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:56 AM CDT Asset located in: Oklahoma City, OK, USA
183	2026 SSL1200-GRAY Mini Compact Track Loader (Unused) S/N: 07400A C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2016 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 42 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	189	2026 CFG KJT27 Mini Compact Track Loader (Unused) S/N: KJT272026M0620173 C/W: Located in Lane 56, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:56 AM CDT Asset located in: Lake Worth, TX, USA
184	2026 SDLL1200 Mini Compact Track Loader (Unused) S/N: 56318 C/W: Located in Lane 56, 2026 US EPA Label, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	190	2026 SDLOOL SL-1050K Mini Compact Track Loader (Unused) S/N: F-1050K260745 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2025 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 09:56 AM CDT Asset located in: Lake Worth, TX, USA
185	2026 SDLL1200 Mini Compact Track Loader (Unused) S/N: 56317 C/W: Located in Lane 56, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:55 AM CDT Asset located in: Lake Worth, TX, USA	191	2026 SDLOOL SL-1050K Mini Compact Track Loader (Unused) S/N: F-1050K260744 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2025 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 09:57 AM CDT Asset located in: Lake Worth, TX, USA
186	2026 SSL1200-GRAY Mini Compact Track Loader (Unused) S/N: 56387 C/W: Located in Lane 56, 2026 US EPA Label, 9 in Track Belts, Manual Quick Coupler, 42 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:55 AM CDT Asset located in: Lake Worth, TX, USA	192	2026 SDLOOL SL-1050K Mini Compact Track Loader (Unused) S/N: F-1050K260766 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2025 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 09:57 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
193	2026 SDLOOL SL-1050K Mini Compact Track Loader (Unused) S/N: F-1050K260767 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	199	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605209359 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:59 AM CDT Asset located in: Humble, TX, USA
194	2026 SSL60 Mini Compact Track Loader (Unused) S/N: A2604280478 C/W: Located in Lane 56, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	200	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605228548 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:59 AM CDT Asset located in: Humble, TX, USA
195	2026 SSL60 Mini Compact Track Loader (Unused) S/N: A2604280368 C/W: Located in Lane 56, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:58 AM CDT Asset located in: Lake Worth, TX, USA	201	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605088144 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:00 AM CDT Asset located in: Humble, TX, USA
196	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: A2605029207 C/W: Located in Lane 56, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:58 AM CDT Asset located in: Lake Worth, TX, USA	202	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605088875 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:00 AM CDT Asset located in: Humble, TX, USA
197	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: A2605209703 C/W: Located in Lane 56, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:58 AM CDT Asset located in: Lake Worth, TX, USA	203	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605209487 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:00 AM CDT Asset located in: Humble, TX, USA
198	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: A2602075941 C/W: Located in Lane 46 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 09:59 AM CDT Asset located in: Humble, TX, USA	204	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605209492 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:00 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
205	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605209394 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:01 AM CDT Asset located in: Humble, TX, USA	211	2026 SSL60 Mini Compact Track Loader (Unused) S/N: A2602112906 C/W: Located in Lane 56 Spot 1, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
206	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605250545 C/W: Located in Lane 47, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:01 AM CDT Asset located in: Humble, TX, USA	212	2026 SSL60 Mini Compact Track Loader (Unused) S/N: A2602081486 C/W: Located in Lane 56 Spot 1, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
207	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2605209495 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:01 AM CDT Asset located in: Humble, TX, USA	215	2026 SSL580 Mini Compact Track Loader (Unused) S/N: A2605228408 C/W: Located in Lane 56, Open Operator Station, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:04 AM CDT Asset located in: Lake Worth, TX, USA
208	2026 SSL60-RED Mini Compact Track Loader (Unused) S/N: 2606058664 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 36 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:02 AM CDT Asset located in: Humble, TX, USA	216	2026 SSL580 Mini Compact Track Loader (Unused) S/N: A2605228397 C/W: Located in Lane 56, Open Operator Station, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:04 AM CDT Asset located in: Lake Worth, TX, USA
209	2026 SSL60 Mini Compact Track Loader (Unused) S/N: A2602081481 C/W: Located in Lane 56 Spot 1, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:02 AM CDT Asset located in: Lake Worth, TX, USA	217	2026 STARVOX SV-480 Mini Compact Track Loader (Unused) S/N: STV2025CT66602771 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 44 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:04 AM CDT Asset located in: Humble, TX, USA
210	2026 SSL60 Mini Compact Track Loader (Unused) S/N: A2602112942 C/W: Located in Lane 56 Spot 1, Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:02 AM CDT Asset located in: Lake Worth, TX, USA	218	2026 STARVOX SV-480 Mini Compact Track Loader (Unused) S/N: STV2025CT66602742 C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, 44 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:05 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
225	2026 Landhero ATS-T460 Mini Compact Track Loader (Unused) S/N: 26010508170YM C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 7 in Track Belts, 40 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:07 AM CDT Asset located in: Lake Worth, TX, USA	231	2026 SDLOOL SL360T Mini Compact Track Loader (Unused) S/N: 360TJ260787 C/W: Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 41 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:09 AM CDT Asset located in: Oklahoma City, OK, USA
226	2026 Landhero ATS-T460 Mini Compact Track Loader (Unused) S/N: 26010508156YM C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 7 in Track Belts, 40 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:07 AM CDT Asset located in: Lake Worth, TX, USA	232	2026 SDLOOL SL360T Mini Compact Track Loader (Unused) S/N: 360TJ260786 C/W: Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 41 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:09 AM CDT Asset located in: Oklahoma City, OK, USA
227	2026 ATS POWER ATS-T460 Mini Compact Track Loader (Unused) S/N: 26010708074YM C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:07 AM CDT Asset located in: Humble, TX, USA	233	2026 SDLOOL SL360T Mini Compact Track Loader S/N: 360TJ260765 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 6 in Track Belts, Manual Quick Coupler, 43 in Bucket Usage: 854 Hr Lot closing time: Wed, Sep 16, 10:09 AM CDT Asset located in: Lake Worth, TX, USA
228	2026 ATS POWER ATS-T460 Mini Compact Track Loader (Unused) S/N: 26010708023YM C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:08 AM CDT Asset located in: Humble, TX, USA	234	2026 SDLOOL SL360T Mini Compact Track Loader (Unused) S/N: 360TJ260730 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 6 in Track Belts, Manual Quick Coupler, 43 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:09 AM CDT Asset located in: Lake Worth, TX, USA
229	2026 ATS POWER ATS-T460 Mini Compact Track Loader (Unused) S/N: 26010708120YM C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:08 AM CDT Asset located in: Humble, TX, USA	235	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607017 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 43 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:10 AM CDT Asset located in: Lake Worth, TX, USA
230	2026 ATS POWER ATS-T460 Mini Compact Track Loader (Unused) S/N: 26010708065YM C/W: Located in Lane 47 Spot 0, 7 in Track Belts, Manual Quick Coupler, Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:08 AM CDT Asset located in: Humble, TX, USA	236	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607015 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 43 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:10 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
237	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607132 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:10 AM CDT Asset located in: Lake Worth, TX, USA	243	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607150 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:12 AM CDT Asset located in: Lake Worth, TX, USA
238	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607133 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	244	2025 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2510303 C/W: Located in Lane 48 Spot 0, Open Operator Station, Joystick Steering, 6 in Track Belts, Manual Quick Coupler, 39 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:12 AM CDT Asset located in: Humble, TX, USA
239	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607131 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	245	2026 CFG KJT27 Mini Compact Track Loader (Unused) S/N: KJT272026M0615155 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2023 US EPA Label, 8 in Track Belts, Manual Quick Coupler, 44 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:13 AM CDT Asset located in: Lake Worth, TX, USA
240	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607147 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	246	2026 AGT MX-MRT14 Mini Compact Track Loader (Unused) S/N: MXMRT142026000301 C/W: Located in Lane 56 Spot 1, 7 in Track Belts, Manual Quick Coupler, 31 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:13 AM CDT Asset located in: Lake Worth, TX, USA
241	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607126 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 43 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:12 AM CDT Asset located in: Lake Worth, TX, USA	247	2026 AGT MX-CRT23 Mini Compact Track Loader (Unused) S/N: MXCRT232026J00559 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 33 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:13 AM CDT Asset located in: Lake Worth, TX, USA
242	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2607199 C/W: Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 38 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:12 AM CDT Asset located in: Oklahoma City, OK, USA	248	2026 AGT MX-CRT23 Mini Compact Track Loader (Unused) S/N: MXCRT232026J00557 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 33 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:14 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
249	2026 AGT MX-CRT23 Mini Compact Track Loader (Unused) S/N: MXCRT232026J00593 C/W: Located in Lane 56, 6 in Track Belts, Manual Quick Coupler, 32 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:14 AM CDT Asset located in: Lake Worth, TX, USA	255	2026 AGT YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1426M05080542 C/W: Located in Lane 49 Spot 0, 6 in Track Belts, Manual Quick Coupler, 38 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:16 AM CDT Asset located in: Humble, TX, USA
250	2026 AGT MX-CRT23 Mini Compact Track Loader (Unused) S/N: MXCRT232026J00591 C/W: Located in Lane 56, 6 in Track Belts, Manual Quick Coupler, 32 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:14 AM CDT Asset located in: Lake Worth, TX, USA	256	2026 CFG YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1426M07101158 C/W: Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 31 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:16 AM CDT Asset located in: Oklahoma City, OK, USA
251	2026 AGT MX-CRT23 Mini Compact Track Loader (Unused) S/N: MXCRT232026J00696 C/W: 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 32 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:15 AM CDT Asset located in: Oklahoma City, OK, USA	257	2026 CFG YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1426M07101197 C/W: Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 31 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:16 AM CDT Asset located in: Oklahoma City, OK, USA
252	2026 AGT MX-CRT23 Mini Compact Track Loader (Unused) S/N: MXCRT232026J00692 C/W: 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 32 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 10:15 AM CDT Asset located in: Oklahoma City, OK, USA	258	2025 Rippa RS03 Mini Compact Track Loader (Unused) S/N: LPR20251T20100015 C/W: Located in Lane 100 Spot 0, Open Operator Station, 7 in Track Belts, Manual Quick Coupler, 44 in Bucket Usage: 2 Hr Lot closing time: Wed, Sep 16, 10:17 AM CDT Asset located in: Humble, TX, USA
253	2026 AGT YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1426M06050804 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 33 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:15 AM CDT Asset located in: Lake Worth, TX, USA	259	2026 Rippa RS04 Mini Compact Track Loader (Unused) S/N: LPR0RS04A26020038 C/W: Located in Lane 100 Spot 0, Open Operator Station, 2025 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 44 in Bucket Usage: 6 Hr Lot closing time: Wed, Sep 16, 10:17 AM CDT Asset located in: Humble, TX, USA
254	2026 AGT YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1426M06050803 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, 2026 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 33 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:15 AM CDT Asset located in: Lake Worth, TX, USA	260	2023 Bobcat S76 Two-Speed Skid Steer Loader S/N: B4CD22166 C/W: Located in Lane 6 Spot 2, Enclosed Cab, Ride Control, Joystick Steering, Electric Kit, Manual Quick Coupler Usage: 3,470 Hr Notes: The closing times of lots 260 thru 261 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:17 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
261	2023 Bobcat S76 Two-Speed Skid Steer Loader S/N: B4CD21933 C/W: Located in Lane 6 Spot 1, Enclosed Cab, Ride Control, Joystick Steering, 2022 US EPA Label, Manual Quick Coupler Usage: 2,196 Hr Notes: The closing times of lots 260 thru 261 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:18 AM CDT Asset located in: Lake Worth, TX, USA	266	2020 John Deere 332G Two-Speed Skid Steer Loader S/N: 1T0332GKALF371513 C/W: Located in Lane 6 Spot 5, Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 84 in Bucket Usage: 2,990 Hr Notes: The closing times of lots 265 thru 266 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:19 AM CDT Asset located in: Lake Worth, TX, USA
262	2022 Bobcat S76 Skid Steer Loader S/N: B4CD15288 C/W: Located in Lane 5 Spot 14, Enclosed Cab, Air Conditioner, Joystick Steering, Manual Quick Coupler, 77 in Bucket Usage: 1,629 Hr Lot closing time: Wed, Sep 16, 10:18 AM CDT Asset located in: Humble, TX, USA	267	2015 New Holland L228 Two-Speed Skid Steer Loader S/N: JAF0L228HFM407718 C/W: Located in Lane 6 Spot 7, Enclosed Cab, Air Conditioner, Hydraulic Coupler, 78 in Bucket Usage: 2,352 Hr Lot closing time: Wed, Sep 16, 10:19 AM CDT Asset located in: Lake Worth, TX, USA
263	2011 JCB 260 Two-Speed Skid Steer Loader S/N: GE0260WVPB1745807 C/W: Located in Lane 6 Spot 8, Enclosed Cab, Air Conditioner, Joystick Steering, Self Leveling, 2011 US EPA Label, Manual Quick Coupler, 78 in Bucket Usage: 3,948 Hr Lot closing time: Wed, Sep 16, 10:18 AM CDT Asset located in: Lake Worth, TX, USA	268	2021 John Deere 324G Two-Speed Skid Steer Loader S/N: 1T0324GKEMJ396252 C/W: Open Operator Station, Ride Control, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, Manual Quick Coupler, 77 in Bucket Usage: 2,926 Hr Lot closing time: Wed, Sep 16, 10:20 AM CDT Asset located in: Midland, TX, USA
264	2021 John Deere 332G Skid Steer Loader S/N: 1T0332GKHMF396027 C/W: Located in Lane 6 Spot 11, Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control Pattern Changer, Rear View Camera, Requires Diesel Exhaust Fluid, Aperture Tires, Hydraulic Coupler, 72 in Bucket, Counterweight Kit Usage: 2,636 Hr Lot closing time: Wed, Sep 16, 10:18 AM CDT Asset located in: Lake Worth, TX, USA	269	2014 Mustang 4000V Two-Speed High Flow Skid Steer Loader S/N: MMC04000D00161423 C/W: Located in Lane 5 Spot 9, Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Manual Quick Coupler, 84 in Bucket Usage: 427 Hr Lot closing time: Wed, Sep 16, 10:20 AM CDT Asset located in: Humble, TX, USA
265	2020 John Deere 332G Two-Speed Skid Steer Loader S/N: 1T0332GKCLF371517 C/W: Located in Lane 6 Spot 6, Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 80 in Bucket, Counterweight Kit Usage: 3,130 Hr Notes: The closing times of lots 265 thru 266 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:19 AM CDT Asset located in: Lake Worth, TX, USA	270	2020 Cat 236D3 Two-Speed Skid Steer Loader S/N: CAT0236DJKXL00901 C/W: Located in Lane 6 Spot 3, Enclosed Cab, Air Conditioner, Joystick Steering, 2019 US EPA Label, Electric Kit, Hydraulic Coupler, 68 in Bucket Usage: 3,131 Hr Lot closing time: Wed, Sep 16, 10:20 AM CDT Asset located in: Lake Worth, TX, USA
		271	2008 Case 445 Skid Steer Loader S/N: N8M485626 C/W: Located in Lane 6 Spot 4, Open Operator Station, Joystick Steering, Electric Kit, Manual Quick Coupler, 72 in Multi-Purpose Bucket, Counterweight Kit Usage: 1,003 Hr Lot closing time: Wed, Sep 16, 10:21 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
271A	2000 John Deere 250 Skid Steer Loader S/N: V0250A250207 C/W: Located in Lane 6 Spot 12, Open Operator Station, Manual Quick Coupler, 72 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:21 AM CDT Asset located in: Lake Worth, TX, USA	282	2010 Cat 420E 4x4 Backhoe Loader S/N: CAT0420EADJL00400 C/W: Located in Lane 5 Spot 15, Open Operator Station, Front Hydraulic Coupler, 93 in Loader Bucket, Extendable Stick, 25 in Backhoe Digging Bucket Usage: 4,316 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
275	Clark Bobcat 631 Skid Steer Loader S/N: 5005M11270 C/W: Located in Lane 6 Spot 9, Open Operator Station, Manual Quick Coupler, 55 in Bucket Usage: 1,398 Hr Lot closing time: Wed, Sep 16, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	283	2018 Cat 416F2 4x4 Backhoe Loader S/N: CAT0416FCHWB01365 C/W: Open Operator Station, Tier 4, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 88 in Loader Bucket, 22 in Backhoe V Bottom,, Thumb Bracket, Equipment-from-a-Primoris-Services-Corp-company Usage: 6,666 Hr Lot closing time: Wed, Sep 16, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
276	2026 SDLOOL SL-323TZ Mini Skid Steer Loader (Unused) S/N: 323TZ2607111 C/W: Open Operator Station, Joystick Steering, 2026 US EPA Label, Manual Quick Coupler, 41 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:22 AM CDT Asset located in: Oklahoma City, OK, USA	284	2011 Cat 416E 4x4 Backhoe Loader S/N: CAT0416ECLMS01393 C/W: Located in Lane 5 Spot 6, Open Operator Station, 89 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket Usage: Not Available Lot closing time: Wed, Sep 16, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
277	2026 SDLOOL SL-323TZ High Flow Skid Steer Loader (Unused) S/N: 323TZ260767 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, Manual Quick Coupler, 40 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	285	2015 Cat 415F2 4x4 Backhoe Loader S/N: CAT0415FJHWA00200 C/W: Open Operator Station, 2015 US EPA Label, 88 in Loader Bucket, 24 in Backhoe Cleanup Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:25 AM CDT Asset located in: Midland, TX, USA
278	2026 SDLOOL SL-323TZ Mini Skid Steer Loader (Unused) S/N: 323TZ260754 C/W: Located in Lane 56 Spot 1, Open Operator Station, Joystick Steering, Manual Quick Coupler, 43 in Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:23 AM CDT Asset located in: Lake Worth, TX, USA	288	2022 Case 590SN 4x4 Backhoe Loader S/N: JJGN59SNCNC782615 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, 93 in Loader Bucket, Extendable Stick, 23 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 2,496 Hr Lot closing time: Wed, Sep 16, 10:26 AM CDT Asset located in: Midland, TX, USA
279	2017 Cat 420 F2 4x4 Backhoe Loader S/N: CAT0420FVHWC02809 C/W: Located in Lane 5 Spot 8, Open Operator Station, Backhoe Pilot Controls, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 94 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket Usage: 4,356 Hr Lot closing time: Wed, Sep 16, 10:23 AM CDT Asset located in: Lake Worth, TX, USA		
281	2010 Cat 420E IT 4x4 Backhoe Loader S/N: CAT0420EPPHC00868 C/W: Located in Lane 5 Spot 3, Open Operator Station, Ride Control, Backhoe Pilot Controls, Hydraulic Coupler, 96 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Thumb Bracket Usage: 10,033 Hr Lot closing time: Wed, Sep 16, 10:24 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
289	2018 John Deere 410L 4x4 Backhoe Loader S/N: 1T0410LXKJF330614 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92 in Multi-Purpose Loader Bucket, Quick Coupler, Rear Auxiliary Hydraulics, Manual Thumb Usage: 5,796 Hr Notes: Item at offsite location must be picked up within 14 days of auction or will be subject to 3rd party storage fees ; John Deere Dealer Trade-In Units Lot closing time: Wed, Sep 16, 10:26 AM CDT Asset located in: Pflugerville, TX, USA	294	2013 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKEDE249067 C/W: Located in Lane 14 Spot 2, Open Operator Station, Front Hydraulic Coupler, 90 in Loader Bucket, Forks, Side Shift, Extendable Stick, 24 in Backhoe Digging Bucket Usage: 4,159 Hr Lot closing time: Wed, Sep 16, 10:27 AM CDT Asset located in: Humble, TX, USA
290	2014 John Deere 410K 4x4 Backhoe Loader S/N: 1T0410KXVDE252562 C/W: Located in Lane 5 Spot 1, Enclosed Cab, Air Conditioner, Front Hydraulic Coupler, 94 in Loader Bucket, 25 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 9,850 Hr Lot closing time: Wed, Sep 16, 10:26 AM CDT Asset located in: Lake Worth, TX, USA	297	2010 Case 580N 4x4 Backhoe Loader S/N: JJGN580NJAC535293 C/W: Located in Lane 5 Spot 20, Open Operator Station, US EPA Label, 83 in Loader Bucket, 25 in Backhoe Digging Bucket Usage: 4,608 Hr Lot closing time: Wed, Sep 16, 10:28 AM CDT Asset located in: Lake Worth, TX, USA
291	2020 John Deere 310SL 4x4 Backhoe Loader S/N: 1T0310SLHLF389183 C/W: Located in Lane 5 Spot 17, Open Operator Station, 2020 US EPA Label, Front Hydraulic Coupler, 92 in Loader Bucket, Rear Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 6,118 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	298	2014 Kubota L45 4x4 Backhoe Loader S/N: BT115 C/W: Located in Lane 5 Spot 16, Open Operator Station, Tier 4, 2009 US EPA Label, Front Manual Quick Coupler, 72 in Loader Bucket, 12 in Backhoe Digging Bucket, Thumb Bracket Usage: Not Available Lot closing time: Wed, Sep 16, 10:29 AM CDT Asset located in: Lake Worth, TX, USA
292	2018 John Deere 310SL 4x4 Backhoe Loader S/N: 1T0310SLKJF338271 C/W: Located in Lane 5 Spot 7, Open Operator Station, Backhoe Pilot Controls, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Front Hydraulic Coupler, 94 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket Usage: 6,031 Hr Lot closing time: Wed, Sep 16, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	299	2004 Cat 420D 4x4 Backhoe Loader S/N: CAT0420DAFDP19467 C/W: Enclosed Cab, Backhoe Pilot Controls, 87 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:29 AM CDT Asset located in: Midland, TX, USA
293	2016 John Deere 310SL 4x4 Backhoe Loader S/N: 1T0310SLKGF295379 C/W: Located in Lane 5 Spot 25, Enclosed Cab, Air Conditioner, 2016 US EPA Label, Front Hydraulic Coupler, 92 in Loader Bucket, Rear Quick Coupler, 22 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 9,220 Hr Notes: Maintenance & Full Services Completed by John Deere Dealer since Purchased New ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	300	2008 John Deere 310SJ 4x4 Backhoe Loader S/N: T0310SJ156468 C/W: Located in Lane 14 Spot 01, Open Operator Station, 2007 US EPA Label, 91 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 10:29 AM CDT Asset located in: Humble, TX, USA
		301	2007 John Deere 310SJ 4x4 Backhoe Loader S/N: T0310SJ143454 C/W: Located in Lane 5 Spot 9, Open Operator Station, Powershift Transmission, 90 in Loader Bucket, 26 in Backhoe Digging Bucket Usage: 3,703 Hr Lot closing time: Wed, Sep 16, 10:30 AM CDT Asset located in: Lake Worth, TX, USA
		301A	2003 Komatsu WB140-2 4x4 Backhoe Loader S/N: A20202 C/W: Located in Lane 5 Spot 21, Open Operator Station, 92 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,229 Hr Lot closing time: Wed, Sep 16, 10:30 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
302	2014 Cat 416F 4x2 Backhoe Loader S/N: CAT0416FHKSF01379 C/W: Located in Lane 5 Spot 6, Open Operator Station, 2014 US EPA Label, 89 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 4,185 Hr Notes: The closing times of lots 302 thru 303 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:30 AM CDT Asset located in: Lake Worth, TX, USA	309	2020 Komatsu WA500-8 Wheel Loader S/N: KMTWA134ELNA97182 C/W: Located in Lane 2 Spot 20, Enclosed Cab, Air Conditioner, Rear View Camera, Joystick Steering, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 134 in Bucket, 29.5R25 Tires, Equipment from Big Creek Construction Usage: 15,020 Hr Notes: The closing times of lots 309 thru 310 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:32 AM CDT Asset located in: Lake Worth, TX, USA
303	2014 Cat 416F 4x2 Backhoe Loader S/N: CAT0416FKKSF01342 C/W: Located in Lane 5 Spot 7, Open Operator Station, 2013 US EPA Label, 88 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 6,147 Hr Notes: The closing times of lots 302 thru 303 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:30 AM CDT Asset located in: Lake Worth, TX, USA	310	2020 Komatsu WA500-8 Wheel Loader S/N: KMTWA134HLNA97231 C/W: Located in Lane 2 Spot 25, Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, Joystick Steering, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 134 in Bucket, 875/65R29 Tires, Equipment from Big Creek Construction Usage: 15,111 Hr Notes: The closing times of lots 309 thru 310 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:32 AM CDT Asset located in: Lake Worth, TX, USA
303A	2015 Case 580N 4x2 Backhoe Loader S/N: JJGN580NJFC717602 C/W: Located in Lane 14 Spot 16, Open Operator Station, 82 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,942 Hr Lot closing time: Wed, Sep 16, 10:30 AM CDT Asset located in: Humble, TX, USA	311	2019 John Deere 844K-III Wheel Loader S/N: 1DW844KAEJF692779 C/W: Located in Lane 6 Spot 9, Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, Autoshift, Veigroup On-Board Scale, Requires Diesel Exhaust Fluid, 140 in Bucket, 875/65R29 Tires Usage: 11,262 Hr Lot closing time: Wed, Sep 16, 10:33 AM CDT Asset located in: Humble, TX, USA
305	2018 Cat 415F2IL 4x4 Landscape Loader S/N: CAT0415PHPF400714 C/W: Located in Lane 5 Spot 2, Open Operator Station, 89 in Bucket, 89 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Equipment-from-a-Primoris-Services-Corp-company Usage: 4,412 Hr Lot closing time: Wed, Sep 16, 10:31 AM CDT Asset located in: Lake Worth, TX, USA	313	2022 Komatsu WA475-10 Wheel Loader S/N: KMTWA142VMNA40098 C/W: Located in Lane 2 Spot 5, Enclosed Cab, Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Bucket, 26.5R25 Tires, Equipment from Big Creek Construction Usage: 8,397 Hr Notes: The closing times of lots 313 thru 314 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:33 AM CDT Asset located in: Lake Worth, TX, USA
307	2012 Case 570MXT Series 3 4x4 Landscape Loader S/N: JJGN570MLCC548653 C/W: Located in Lane 5 Spot 10, Open Operator Station, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier Usage: 5,972 Hr Lot closing time: Wed, Sep 16, 10:31 AM CDT Asset located in: Lake Worth, TX, USA		
308	2007 Case 570MXT 4x4 Landscape Loader S/N: JJG0380781 C/W: Located in Lane 5 Spot 19, Open Operator Station, 2007 US EPA Label, Auxiliary Hydraulics, 83 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier Usage: 9,261 Hr Lot closing time: Wed, Sep 16, 10:32 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
314	2022 Komatsu WA475-10 Wheel Loader S/N: KMTWA142AMNA40099 C/W: Located in Lane 2 Spot 18, Enclosed Cab, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 125 in Bucket, 26.5R25 Tires, Equipment from Big Creek Construction Usage: 8,449 Hr Notes: The closing times of lots 313 thru 314 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	319	2020 John Deere 744L Wheel Loader S/N: 1DW744LXTLF707284 C/W: Located in Lane 2 Spot 4, Enclosed Cab, Air Conditioner, Rear View Camera, Autoshift, Joystick Steering, Hydraulic Coupler, 130 in Bucket, 26.5R25 Tires Usage: 19,460 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Forks to fit this machine - Lot 4160 Lot closing time: Wed, Sep 16, 10:35 AM CDT Asset located in: Lake Worth, TX, USA
315	2019 Cat 972M Wheel Loader S/N: CAT0972MVA7800406 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, 126 in Bucket, 26.5R25 Tires Usage: 12,195 Hr Lot closing time: Wed, Sep 16, 10:34 AM CDT Asset located in: Lake Worth, TX, USA	320	2019 John Deere 744K-II Wheel Loader S/N: 1DW744KXLJF692875 C/W: Located in Lane 2 Spot 10, Enclosed Cab, Air Conditioner, Hydraulic Coupler, 128 in Bucket, 26.5R25 Tires, Complete Engine Replaced by Deere Dealer at 8,202 Hours Usage: 11,714 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Forks to fit this machine - Lots 4150, 4148, 4149 ; Complete Engine Replaced by Deere Dealer at 8,202 Hours ; The closing times of lots 320 thru 322 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:35 AM CDT Asset located in: Lake Worth, TX, USA
316	2016 Cat 966M Wheel Loader S/N: CAT0966MER8D00202 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 26.5-25 Tires, Rear Auxiliary Hydraulic Plumbing Usage: 15,626 Hr Notes: The closing times of lots 316 thru 317 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Item at offsite location must be picked up within 14 days of auction (October 2nd) or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 10:34 AM CDT Asset located in: Florence, TX, USA	321	2019 John Deere 744K Wheel Loader S/N: 1DW744KXXKF692822 C/W: Located in Lane 2 Spot 3, Enclosed Cab, Air Conditioner, Rear View Camera, Autoshift, Hydraulic Coupler, 128 in Bucket, 26.5R25 Tires Usage: 25,378 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Forks to fit this machine - Lots 4150, 4148, 4149 ; The closing times of lots 320 thru 322 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
317	2016 Cat 966M Wheel Loader S/N: CAT0966MPKJP01801 C/W: Located in Lane 2 Spot 29, Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 126 in Bucket, Forks, 26.5R25 Tires Usage: 17,817 Hr Notes: The closing times of lots 316 thru 317 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:34 AM CDT Asset located in: Lake Worth, TX, USA	322	2016 John Deere 744K Wheel Loader S/N: 1DW744KXLGF676149 C/W: Located in Lane 2 Spot 14, Enclosed Cab, Air Conditioner, Rear View Camera, Hydraulic Coupler, 120 in Bucket, 26.5R25 Tires, Complete Transmission Replaced by Dealer at 13,761 hours Usage: 15,673 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Forks to fit this machine - Lots 4150, 4148, 4149 ; Complete Transmission Replaced by Dealer at 13,761 hours ; The closing times of lots 320 thru 322 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:36 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
324	2021 John Deere 644L Wheel Loader S/N: 1DW644LZAML708816 C/W: Located in Lane 2 Spot 16, Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 119 in Bucket, 23.5R25 Tires Usage: 9,135 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 10:36 AM CDT Asset located in: Lake Worth, TX, USA	328A	2012 John Deere 644K Wheel Loader S/N: 1DW644KZHCE645871 C/W: Located in Lane 2 Spot 19, Enclosed Cab, Air Conditioner, Forks, 23.5R25 Tires Usage: 18,012 Hr Lot closing time: Wed, Sep 16, 10:38 AM CDT Asset located in: Lake Worth, TX, USA
326	2019 John Deere 644K Wheel Loader S/N: 1DW644KZVKF700209 C/W: Located in Lane 2 Spot 11, Enclosed Cab, Air Conditioner, Rear View Camera, Autoshift, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 120 in Bucket Usage: 9,338 Hr Notes: The closing times of lots 326 thru 327 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Forks to fit this machine - Lot 4159 Lot closing time: Wed, Sep 16, 10:37 AM CDT Asset located in: Lake Worth, TX, USA	328B	2017 Komatsu WA380-8 Wheel Loader S/N: KMTWA130CHA015226 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Loadrite On-Board Scale, 23.5R25 Tires Usage: 11,497 Hr Lot closing time: Wed, Sep 16, 10:38 AM CDT Asset located in: Lake Worth, TX, USA
327	2018 John Deere 644 K Wheel Loader S/N: 1DW644KZTJF691390 C/W: Located in Lane 2 Spot 34, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 118 in Bucket, 23.5R25 Tires Usage: 15,891 Hr Notes: The closing times of lots 326 thru 327 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Forks to fit this machine - Lot 4158 Lot closing time: Wed, Sep 16, 10:37 AM CDT Asset located in: Lake Worth, TX, USA	329	2011 Cat 950 H Wheel Loader S/N: CAT0950HJK5K03289 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, Bucket, 23.5R25 Tires Usage: 13,258 Hr Lot closing time: Wed, Sep 16, 10:38 AM CDT Asset located in: Lake Worth, TX, USA
327A	2020 Cat 950GC Wheel Loader S/N: CAT00950CM5T03899 C/W: Located in Lane 2 Spot 22, Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 114 in Bucket, 23.5R25 Tires Usage: 13,091 Hr Lot closing time: Wed, Sep 16, 10:37 AM CDT Asset located in: Lake Worth, TX, USA	330	2023 Komatsu WA320-8 Wheel Loader S/N: KMTWA135CNA51350 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, Autoshift, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 2,687 Hr Lot closing time: Wed, Sep 16, 10:38 AM CDT Asset located in: San Antonio, TX, USA
328	2018 Cat 950GC Wheel Loader S/N: CAT00950PM5T01114 C/W: Located in Lane 2 Spot 20, Enclosed Cab, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 101 in Bucket, 23.5 R25 Tires Usage: 10,303 Hr Lot closing time: Wed, Sep 16, 10:38 AM CDT Asset located in: Lake Worth, TX, USA	330A	2012 Komatsu WA320PZ-6 Wheel Loader S/N: KMTWA108J01071096 C/W: Located in Lane 2 Spot 31, Enclosed Cab, Air Conditioner, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:39 AM CDT Asset located in: Lake Worth, TX, USA
		332	2022 John Deere 624 P-Tier High Lift Wheel Loader S/N: 1DW624PAJNLH13377 C/W: Located in Lane 6 Spot 15, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Bucket, 20.5R25 Tires Usage: 4,267 Hr Notes: The closing times of lots 332 thru 333 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:39 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
333	2021 John Deere 624 P-Tier Wheel Loader S/N: 1DW624PAJMLZ11386 C/W: Located in Lane 2 Spot 7, Enclosed Cab, Air Conditioner, Rear View Camera, Autoshift, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 105 in Bucket, 20.5R25 Tires Usage: 9,061 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; The closing times of lots 332 thru 333 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:39 AM CDT Asset located in: Lake Worth, TX, USA	337	2019 Cat 930M Wheel Loader S/N: CAT0930MPKTG04645 C/W: Enclosed Cab, Air Conditioner, Ride Control, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 99 in Bucket, 20.5R25 Tires Usage: 3,305 Hr Notes: The closing times of lots 336 thru 338 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:40 AM CDT Asset located in: Midland, TX, USA
334	2023 Cat 938M Wheel Loader S/N: CAT0938MJJ3R10702 C/W: Located in Lane 6 Spot 1, Enclosed Cab, Air Ride Seat, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires, Equipment-from-R-Construction Usage: 6,740 Hr Notes: From the Well Maintained Fleet of R Construction ; The closing times of lots 334 thru 335 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:39 AM CDT Asset located in: Humble, TX, USA	337A	2019 Cat 930M Wheel Loader S/N: CAT0930MKKTG04467 C/W: Enclosed Cab, Air Conditioner, 2018 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 3.2 cyd 100 in Bucket, 20.5R25 Tires Usage: 2,395 Hr Lot closing time: Wed, Sep 16, 10:40 AM CDT Asset located in: Midland, TX, USA
335	2023 Cat 938M Wheel Loader S/N: CAT0938MKJ3R10049 C/W: Located in Lane 6 Spot 14, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, 28L-26 Tires Usage: 8,173 Hr Notes: The closing times of lots 334 thru 335 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:40 AM CDT Asset located in: Humble, TX, USA	338	2019 Cat 930M Wheel Loader S/N: CAT0930MJKTG04664 C/W: Located in Lane 2 Spot 21, Enclosed Cab, Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 100 in Bucket, 20.5R25 Tires Usage: 12,181 Hr Notes: The closing times of lots 336 thru 338 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:41 AM CDT Asset located in: Lake Worth, TX, USA
336	2022 Cat 930M Wheel Loader S/N: CAT0930MVF5K02430 C/W: Located in Lane 6 Spot 11, Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires, Equipment-from-R-Construction Usage: 5,654 Hr Notes: From the Well-Maintained Fleet of R Construction Company ; The closing times of lots 336 thru 338 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:40 AM CDT Asset located in: Humble, TX, USA	339	2014 Hyundai HL757-9A Wheel Loader S/N: HHKHL04J30000105 C/W: Located in Lane 6 Spot 18, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Autoshift, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires Usage: 2,953 Hr Lot closing time: Wed, Sep 16, 10:41 AM CDT Asset located in: Humble, TX, USA
		340	2015 Volvo L90H Wheel Loader S/N: VCE0L90HC0S623203 C/W: Located in Lane 6 Spot 2, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires Usage: 19,399 Hr Lot closing time: Wed, Sep 16, 10:41 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
341	2020 Volvo L70H Wheel Loader S/N: VCE0L70HE0S623754 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Autoshift, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires Usage: 13,533 Hr Lot closing time: Wed, Sep 16, 10:42 AM CDT Asset located in: Oklahoma City, OK, USA	345	2024 John Deere 544 G-Tier Wheel Loader S/N: 1YN544GACPLA00434 C/W: Located in Lane 6 Spot 23, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 113 in Bucket, 20.5R25 Tires Usage: 1,725 Hr Notes: The closing times of lots 343 thru 346 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:43 AM CDT Asset located in: Humble, TX, USA
342	2019 John Deere 544L Wheel Loader S/N: 1DW544LZHKF695706 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Requires Diesel Exhaust Fluid, 108 in Bucket, 20.5R25 Tires Usage: 4,589 Hr Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Wed, Sep 16, 10:42 AM CDT Asset located in: Brownwood, TX, USA	346	2024 John Deere 544 G-Tier Wheel Loader S/N: 1YN544GAPPLA00436 C/W: Located in Lane 6 Spot 7, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 114 in Bucket, 20.5R25 Tires Usage: 2,384 Hr Notes: Warranty Available for this unit ; The closing times of lots 343 thru 346 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:43 AM CDT Asset located in: Humble, TX, USA
343	2024 John Deere 544 G-Tier Wheel Loader S/N: 1YN544GAJPLA00438 C/W: Located in Lane 6 Spot 10, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 114 in Bucket, 20.5R25 Tires Usage: 4,888 Hr Notes: Warranty Available for this unit ; The closing times of lots 343 thru 346 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:42 AM CDT Asset located in: Humble, TX, USA	347	2024 John Deere 544 G-Tier Wheel Loader S/N: 1YN544GAKPLA00437 C/W: Located in Lane 6 Spot 21, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 114 in Bucket, 20.5R25 Tires Usage: 2,676 Hr Notes: Comes with Full Powertrain & hydraulic systems warranty. Expires at 6k Hours or 4/29 /2027 Lot closing time: Wed, Sep 16, 10:43 AM CDT Asset located in: Humble, TX, USA
344	2024 John Deere 544 G-Tier Wheel Loader S/N: 1YN544GACPLA00439 C/W: Located in Lane 6 Spot 20, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Auxiliary Hydraulics, Hydraulic Coupler, 113 in Bucket, 20.5R25 Tires Usage: 2,451 Hr Notes: Warranty Available for this unit ; The closing times of lots 343 thru 346 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:42 AM CDT Asset located in: Humble, TX, USA	348	2023 John Deere 544 G-Tier Wheel Loader S/N: 1YN544GATPLA00435 C/W: Located in Lane 6 Spot 19, Enclosed Cab, Rear View Camera, Air Ride Seat, Autoshift, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 114 in Bucket, 20.5R25 Tires Usage: 2,338 Hr Notes: Comes with Full Powertrain & hydraulic systems warranty. Expires at 6k Hours or 4/29 /2027 Lot closing time: Wed, Sep 16, 10:44 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
348A	2022 John Deere 544P Wheel Loader S/N: 1DW544PAVNLZ15528 C/W: Located in Lane 6 Spot 13, Enclosed Cab, Air Conditioner, Rear View Camera, Autoshift, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 105 in Bucket, 20.5R25 Tires Usage: 6,781 Hr Lot closing time: Wed, Sep 16, 10:44 AM CDT Asset located in: Humble, TX, USA	351A	2013 Cat 924K Wheel Loader S/N: CAT0924KEPWR01349 C/W: Located in Lane 100 Spot 1, Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, Hydraulic Coupler, 20.5R25 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:45 AM CDT Asset located in: Lake Worth, TX, USA
349	2017 Case 621G Wheel Loader S/N: JEEN0G21JHF240706 C/W: Enclosed Cab, Air Conditioner, Ride Control, Autoshift, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 10,855 Hr Lot closing time: Wed, Sep 16, 10:44 AM CDT Asset located in: San Antonio, TX, USA	352	2012 Cat 928HZ Wheel Loader S/N: CAT0928HCCXK01660 C/W: Enclosed Cab, Air Conditioner, 96 in Forks, 20.5R25 Tires Usage: 9,853 Hr Lot closing time: Wed, Sep 16, 10:45 AM CDT Asset located in: San Antonio, TX, USA
349A	2024 Komatsu WA270-8 Wheel Loader S/N: KMTWA136LRNA30735 C/W: Located in Lane 00 Spot 00, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 3.5 cyd 108 in Bucket, 20.5R25 Tires Usage: 3,270 Hr Lot closing time: Wed, Sep 16, 10:44 AM CDT Asset located in: Lake Worth, TX, USA	353	2011 John Deere 524K Wheel Loader S/N: 1DW524KZJBD637834 C/W: Enclosed Cab, Autoshift, 2011 US EPA Label, 20.5R25 Tires, Hydraulic Coupler, 3 cyd 97 in Bucket Usage: 12,106 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Lot closing time: Wed, Sep 16, 10:45 AM CDT Asset located in: Austin, TX, USA
350	2017 Komatsu WA270-8 Wheel Loader S/N: KMTWA136CHA083359 C/W: Located in Lane 2 Spot 13, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 12,591 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 10:44 AM CDT Asset located in: Lake Worth, TX, USA	355	2005 Cat 914G Wheel Loader S/N: CAT0914GHPDF00418 C/W: Located in Lane 2 Spot 23, Open Operator Station, 94 in Bucket, 17.5-25 Tires Usage: 959 Hr Lot closing time: Wed, Sep 16, 10:46 AM CDT Asset located in: Lake Worth, TX, USA
350A	2013 John Deere 624K Wheel Loader S/N: 1DW624KZJCE649966 C/W: Located in Lane 00 Spot 00, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 9,906 Hr Lot closing time: Wed, Sep 16, 10:44 AM CDT Asset located in: Lake Worth, TX, USA	356	1996 Cat 980F Wheel Loader S/N: 4RN00850 C/W: Located in Lane 2 Spot 32, Enclosed Cab, 142 in Bucket, 29.5-25 Tires Usage: 5,255 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 10:46 AM CDT Asset located in: Lake Worth, TX, USA
351	2018 Cat 926M Wheel Loader S/N: CAT0926MVLTE05474 C/W: Located in Lane 6 Spot 6, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires Usage: 8,933 Hr Lot closing time: Wed, Sep 16, 10:45 AM CDT Asset located in: Humble, TX, USA	357	2005 Cat 966G Series II Wheel Loader S/N: CAT0966GTAXJ02272 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Laodrite On-Board Scale, 116 in Bucket, 26.5R25 Tires Usage: 21,627 Hr Lot closing time: Wed, Sep 16, 10:46 AM CDT Asset located in: Lake Worth, TX, USA
		358	2004 John Deere 644J Wheel Loader S/N: DW644JX592035 C/W: Located in Lane 2 Spot 9, Enclosed Cab, Air Ride Seat, 2004 US EPA Label, Hydraulic Coupler, 114 in Bucket, 23.5R25 Tires Usage: 29,493 Hr Lot closing time: Wed, Sep 16, 10:47 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
359	2007 Volvo L110E Wheel Loader S/N: L110EV61212 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2006 US EPA Label, 110 in Bucket, 23.5R25 Tires Usage: 13,299 Hr Lot closing time: Wed, Sep 16, 10:47 AM CDT Asset located in: Brownwood, TX, USA	364	2008 Cat 928H Wheel Loader S/N: CAT0928HKCXX00433 C/W: Enclosed Cab, Air Conditioner, Autoshift, Forks, 20.5R25 Tires Usage: 12,208 Hr Lot closing time: Wed, Sep 16, 10:48 AM CDT Asset located in: San Antonio, TX, USA
360A	2007 John Deere 644J Wheel Loader S/N: DW644JZ615917 C/W: Located in Lane 2 Spot 38, Enclosed Cab, Air Conditioner, 2007 US EPA Label, Hydraulic Coupler, 114 in Bucket, 23.5R25 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:47 AM CDT Asset located in: Lake Worth, TX, USA	365	2002 Cat 928G Wheel Loader S/N: CAT0928GL6XR03520 C/W: Enclosed Cab, Air Conditioner, Autoshift, 96 in Forks, 20.5R25 Tires Usage: 5,963 Hr Lot closing time: Wed, Sep 16, 10:49 AM CDT Asset located in: San Antonio, TX, USA
360B	1994 John Deere 644G Wheel Loader S/N: DW644GB544756 C/W: Located in Lane 6 Spot 16, Enclosed Cab, 98 in Bucket, 20.5R25 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:47 AM CDT Asset located in: Humble, TX, USA	366	1998 Cat IT28G Wheel Loader S/N: 8CR00851 C/W: Enclosed Cab, Autoshift, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: 13,965 Hr Lot closing time: Wed, Sep 16, 10:49 AM CDT Asset located in: San Antonio, TX, USA
361	1993 Cat 950F Series II Wheel Loader S/N: 5SK0324 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 109 in Bucket, Forks, 23.5R25 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:48 AM CDT Asset located in: San Antonio, TX, USA	367	2005 Volvo L60E Wheel Loader S/N: L60EV70424 C/W: Enclosed Cab, Air Conditioner, 2006 US EPA Label, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 12,197 Hr Lot closing time: Wed, Sep 16, 10:49 AM CDT Asset located in: Lake Worth, TX, USA
361A	2005 John Deere 544J Wheel Loader S/N: DW544JZ598651 C/W: Located in Lane 2 Spot 26, Enclosed Cab, Air Conditioner, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 7,717 Hr Lot closing time: Wed, Sep 16, 10:48 AM CDT Asset located in: Lake Worth, TX, USA	368	2006 Komatsu WA250-5 Wheel Loader S/N: KMTWA055V57A73983 C/W: Located in Lane 6 Spot 12, Enclosed Cab, Air Conditioner, 2006 US EPA Label, Hydraulic Coupler, 105 in Bucket, 20.5R25 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:50 AM CDT Asset located in: Humble, TX, USA
362	2005 John Deere 544J Wheel Loader S/N: DW544JZ600357 C/W: Located in Lane 2 Spot 28, Enclosed Cab, Air Conditioner, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires Usage: 13,316 Hr Lot closing time: Wed, Sep 16, 10:48 AM CDT Asset located in: Lake Worth, TX, USA	369	1998 Cat 623F Motor Scraper S/N: 6BK00558 C/W: Located in Lane 5 Spot 32, Enclosed Cab, Air Conditioner, 29.5-35 Tires Usage: 5,681 Hr Lot closing time: Wed, Sep 16, 10:50 AM CDT Asset located in: Lake Worth, TX, USA
363	2001 Cat 938G Wheel Loader S/N: 4YS01800 C/W: Located in Lane 2 Spot 10, Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 107 in Bucket, 23.5R25 Tires Usage: 8,192 Hr Lot closing time: Wed, Sep 16, 10:48 AM CDT Asset located in: Lake Worth, TX, USA	370	1997 Cat 623F Motor Scraper S/N: 6BK00385 C/W: Located in Lane 5 Spot 34, Enclosed Cab, Air Conditioner, 29.5-35 Tires Usage: 12,538 Hr Lot closing time: Wed, Sep 16, 10:50 AM CDT Asset located in: Lake Worth, TX, USA
		371	2006 Cat 613C Elevating Motor Scraper S/N: CAT0613CC8LJ03080 C/W: Located in Lane 5 Spot 44, Enclosed Cab, Tier 1, 2001 US EPA Label, 23.5R25 Tires, Equipment from Big Creek Construction Usage: Not Available Lot closing time: Wed, Sep 16, 10:51 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
372	1985 Cat 621B Motor Scraper S/N: 2DB00394 C/W: Located in Lane 0 Spot 0, Enclosed Cab, Air Conditioner, 29.5-29 Tires Usage: Not Available Notes: The closing times of lots 372 thru 373 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:51 AM CDT Asset located in: Humble, TX, USA	375	2023 Case IH Steiger 580S Scraper Tractor S/N: JEEZC580VPF509158 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 2 Reverse, Power Shift, Forward/ Reverse Shuttle, Cab Suspension, AFS Pro 1200 Display, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Dual 710/70R42 Front Tires, Dual 710/70R42 Rear Tires Usage: 4,516 Hr Notes: Tractor can be Sold & Picked Up with Either UNUSED Ag Hitch or Scraper Hitch ; Comes with Ironclad Assurance. Subject to Texas Sales Tax. ; Extended Powertrain Warranty Active through August 2027 or 5,000 Hours ; The closing times of lots 374 thru 376 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:52 AM CDT Asset located in: Taylor, TX, USA
373	1985 Cat 621B Motor Scraper S/N: 2DB00711 C/W: Located in Lane 60 Spot 00, Enclosed Cab, Air Conditioner, 29.5-29 Tires Usage: 3,820 Hr Notes: The closing times of lots 372 thru 373 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:51 AM CDT Asset located in: Humble, TX, USA	376	2022 Case IH Steiger 580S Scraper Tractor S/N: JEEZC580ANF505481 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 2 Reverse, Power Shift, Forward/ Reverse Shuttle, Cab Suspension, AFS Pro 1200 Display, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Dual 710/70R42 Front Tires, Dual 710/70R42 Rear Tires Usage: 4,495 Hr Notes: Tractor can be Sold & Picked Up with Either UNUSED Ag Hitch or Scraper Hitch ; Comes with Ironclad Assurance. Subject to Texas Sales Tax ; No Scraper Hitch ; Extended Powertrain Warranty Active through November 2026 or 5,000 Hours ; The closing times of lots 374 thru 376 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:52 AM CDT Asset located in: Taylor, TX, USA
374	2023 Case IH Steiger 580S Scraper Tractor S/N: JEEZC580LPF508014 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 2 Reverse, Power Shift, Forward/ Reverse Shuttle, Cab Suspension, AFS Pro 1200 Display, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Dual 710/70R42 Front Tires, Dual 710/70R42 Rear Tires Usage: 4,500 Hr Notes: Tractor can be Sold & Picked Up with Either UNUSED Ag Hitch or Scraper Hitch ; Comes with Ironclad Assurance. Subject to Texas Sales Tax. ; Extended Powertrain Warranty Active through March 2027 or 5,000 Hours ; The closing times of lots 374 thru 376 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:51 AM CDT Asset located in: Taylor, TX, USA	376A	2013 John Deere 9560R Scraper Special Scraper Tractor S/N: 1RW9560RVDE008631 C/W: Located in Lane 7 Spot 26, Enclosed Cab, Air Conditioner, Air Ride Seat, 18 Forward 6 Reverse, PowerShift, GS3 CommandCenter Display, 4 Rear Remotes, ISOBUS, Scraper Hitch, Dual 710/70R42 Front Tires, Front Wheel Weights, Dual 710/70R42 Rear Tires Usage: 7,487 Hr Notes: Inoperable items must be removed from yard Sept 4th and cannot be relisted; Buyer's responsibility for removal Lot closing time: Wed, Sep 16, 10:52 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
376B	2013 John Deere 9560R Scraper Special Scraper Tractor S/N: 1RW9560RJDE008884 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, PowerShift, Tier 4, 4 Rear Remotes, ISOBUS, Drawbar, Dual 710/70R42 Front Tires, Front Wheel Weights, Dual 710/70R42 Rear Tires, Rear Wheel Weights Usage: 9,420 Hr Lot closing time: Wed, Sep 16, 10:52 AM CDT Asset located in: Lake Worth, TX, USA	383	2016 John Deere 872GP AWD Motor Grader S/N: 1DW872GPVGF676013 C/W: Located in Lane 3 Spot 26, Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 15 ft / 4.58 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires, Trimble SNR Cab Mounted Radio Usage: 9,591 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 10:54 AM CDT Asset located in: Lake Worth, TX, USA
377	2020 Komatsu GD655-6 Motor Grader S/N: KMTGD032VKA060635 C/W: Located in Lane 3 Spot 18, Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Rear Scarifier, 17.5R25 Tires, Equipment from Big Creek Construction Usage: 5,514 Hr Lot closing time: Wed, Sep 16, 10:52 AM CDT Asset located in: Lake Worth, TX, USA	384	2011 John Deere 872GP AWD Motor Grader S/N: 1DW872GPKBE639117 C/W: Located in Lane 3 Spot 13, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Lift Group, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 6,388 Hr Notes: March 2026 - Complete Deere Dealer Installed Reman Transmission ; Please See Seller Supplied Repair Record Attached Lot closing time: Wed, Sep 16, 10:54 AM CDT Asset located in: Lake Worth, TX, USA
378	2014 Cat 140M2AWD AWD Motor Grader S/N: CAT0140MCM9J00846 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, 14 ft / 4.27 m Moldboard w/ Extension, Front Auxiliary Hydraulics, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 8,734 Hr Lot closing time: Wed, Sep 16, 10:53 AM CDT Asset located in: Oklahoma City, OK, USA	384A	2011 John Deere 772G AWD Motor Grader S/N: 1DW772GXJBE634934 C/W: Located in Lane 3 Spot 14, Enclosed Cab, Air Conditioner, Differential Lock, Pre-Wired for Grade Control, 2011 US EPA Label, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 10,347 Hr Lot closing time: Wed, Sep 16, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
380	2012 Cat 140M2 VHP Motor Grader S/N: CAT0140MCM9D00877 C/W: Located in Lane 8 Spot 8, Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 14,444 Hr Lot closing time: Wed, Sep 16, 10:53 AM CDT Asset located in: Humble, TX, USA	385A	2008 Cat 140M Motor Grader S/N: CAT0140MJB9D01359 C/W: Located in Lane 3 Spot 11, Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 14.00-24 Tires Usage: 10,140 Hr Lot closing time: Wed, Sep 16, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
381	2016 Cat 120M2 AWD Motor Grader S/N: CAT0120MHM9H00383 C/W: Located in Lane 8 Spot 7, Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 4,940 Hr Lot closing time: Wed, Sep 16, 10:54 AM CDT Asset located in: Humble, TX, USA	386	2007 Cat 160H VHP Motor Grader S/N: CAT0160HLASD00739 C/W: Located in Lane 8 Spot 10, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper /Scarifier, 17.5R25 Tires Usage: 17,712 Hr Lot closing time: Wed, Sep 16, 10:55 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
387	2001 Cat 16H Motor Grader S/N: CAT0016HV6ZJ00921 C/W: Located in Lane 3 Spot 25, Enclosed Cab, Differential Lock, 16 ft / 4.88 m Moldboard, Push Block, Accumulators, Ripper, Fast Fuel System, 23.5R25 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:55 AM CDT Asset located in: Lake Worth, TX, USA	395	2019 Cat D8T Crawler Dozer S/N: CAT00D8TCAW400639 C/W: Enclosed Cab, Air Conditioner, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 158 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics Usage: 8,832 Hr Lot closing time: Wed, Sep 16, 10:58 AM CDT Asset located in: Midland, TX, USA
388	2007 Cat 12H Motor Grader S/N: CAT0012HLAMZ01329 C/W: Located in Lane 3 Spot 27, Enclosed Cab, Air Conditioner, 2007 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, 17.5-25 Tires Usage: 14,322 Hr Lot closing time: Wed, Sep 16, 10:56 AM CDT Asset located in: Lake Worth, TX, USA	396	2013 Cat D8T Crawler Dozer S/N: CAT00D8TTTCT01135 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2013 US EPA Label, 154 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Multi-Shank Ripper Usage: 7,455 Hr Lot closing time: Wed, Sep 16, 10:58 AM CDT Asset located in: Midland, TX, USA
389	2008 Komatsu GD655-3 Motor Grader S/N: KMTGD022P01051636 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 14 ft / 4.27 m Moldboard w/ Extension, Front Auxiliary Hydraulics, Push Block, Combination Ripper /Scarifier, Rear Auxiliary Hydraulics, 17.5R25 Tires, EROPS, Side Shift, Tip Control, Ripper, Engine Enclosures, Low Profile Cab, Diff Lock /UnLoc, A/C, Push block, Lighting. Usage: 9,113 Hr Lot closing time: Wed, Sep 16, 10:56 AM CDT Asset located in: Oklahoma City, OK, USA	396A	2020 Cat D6 Crawler Dozer S/N: CAT000D6EHNK00383 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, 132 in Wide Semi-U Blade w/ Single Tilt, 1 Cylinder Multi-Shank Ripper, Sweeps, 24 in Single Grouser Track Shoes Usage: 8,766 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Lot closing time: Wed, Sep 16, 10:58 AM CDT Asset located in: Rockdale, TX, USA
390	2000 John Deere 670CH Motor Grader S/N: DW670CH575785 C/W: Enclosed Cab, Air Conditioner Usage: 8,420 Hr Lot closing time: Wed, Sep 16, 10:56 AM CDT Asset located in: San Antonio, TX, USA	397	2020 Cat D6 LGP Crawler Dozer S/N: CAT000D6ERDC00555 C/W: Located in Lane 10 Spot 14, Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 156 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics, Equipment-from-R-Construction Usage: 8,045 Hr Notes: From the Well-Maintained Fleet of R Construction Company ; The closing times of lots 397 thru 398 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:58 AM CDT Asset located in: Humble, TX, USA
391	John Deere 570A Motor Grader S/N: 07488T C/W: Enclosed Cab, 12 ft / 3.66 m Moldboard, Front Scarifier, 14.00-24 Tires Usage: 9,727 Hr Lot closing time: Wed, Sep 16, 10:57 AM CDT Asset located in: Midland, TX, USA		
392	1988 Cat 12G Motor Grader S/N: 61M12891 C/W: Located in Lane 3 Spot 19, Enclosed Cab, Air Ride Seat, 14 ft / 4.27 m Moldboard, Push Block, Snow Wing, Ripper, 14.00-24 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:57 AM CDT Asset located in: Lake Worth, TX, USA		
394	Cat 12E Motor Grader S/N: 99E10247 C/W: Located in Lane 3 Spot 22, Enclosed Cab, 12 ft / 3.66 m Moldboard, 13.00-24 Tires Usage: Not Available Lot closing time: Wed, Sep 16, 10:57 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
398	2020 Cat D6 Crawler Dozer S/N: CAT000D6CHR900423 C/W: Located in Lane 10 Spot 15, Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 156 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 13,153 Hr Notes: The closing times of lots 397 thru 398 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:59 AM CDT Asset located in: Humble, TX, USA	402	2017 Cat D6T XW Crawler Dozer S/N: CAT00D6TKJNM00301 C/W: Located in Lane 10 Spot 22, Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 162 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 10,679 Hr Lot closing time: Wed, Sep 16, 11:00 AM CDT Asset located in: Humble, TX, USA
399	2019 Cat D6T LGP Crawler Dozer S/N: CAT00D6THSGZ00621 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Tier 4, Requires Diesel Exhaust Fluid, 195 in Wide PAT Blade, Cat PA56-E00100E Winch, Rear Auxiliary Hydraulics, 36 in Single Grouser Track Shoes, SystemOne Undercarriage Usage: 6,308 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. ; The closing times of lots 399 thru 400 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:59 AM CDT Asset located in: Abilene, TX, USA	403	2022 Cat D5 Crawler Dozer S/N: CAT000D5JZDA01083 C/W: Located in Lane 1 Spot 5, Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 128 in Wide PAT Blade, 23.5 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 6,502 Hr Lot closing time: Wed, Sep 16, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
400	2018 Cat D6T LGP Crawler Dozer S/N: CAT00D6TVMH700900 C/W: Located in Lane 10 Spot 12, Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 162 in Wide PAT Blade, 31 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 7,083 Hr Notes: Trimble GPS System to fit this Machine - Lot 6316 ; The closing times of lots 399 thru 400 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 10:59 AM CDT Asset located in: Humble, TX, USA	404	2022 Cat D5 LGP Crawler Dozer S/N: CAT000D5PZ6A01585 C/W: Located in Lane 10 Spot 18, Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 157 in Wide PAT Blade, 33 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics, Equipment-from-R-Construction Usage: 8,101 Hr Notes: From the Well-Maintained Fleet of R Construction Company Lot closing time: Wed, Sep 16, 11:00 AM CDT Asset located in: Humble, TX, USA
401	2018 Cat D6T XL Crawler Dozer S/N: CAT00D6TEHYT00377 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Sweeps, 151.5 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics Usage: 6,016 Hr Lot closing time: Wed, Sep 16, 11:00 AM CDT Asset located in: Oklahoma City, OK, USA	405	2020 Cat D5 Crawler Dozer S/N: CAT000D5EZ6A00304 C/W: Located in Lane 1 Spot 21, Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 160 in Wide PAT Blade, 33 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics Usage: 12,107 Hr Lot closing time: Wed, Sep 16, 11:01 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
407	2015 Cat D6N LGP Crawler Dozer S/N: CAT00D6NCPBA02748 C/W: Located in Lane 10 Spot 10, Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Sweeps, 161 in Wide PAT Blade, 33 in Single Grouser Track Shoes, Paccar PA55-E00100E Winch Usage: 6,347 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Wed, Sep 16, 11:01 AM CDT Asset located in: Humble, TX, USA	413	2014 John Deere 850 K Crawler Dozer S/N: 1T0850KXEDE252136 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Sweeps, 129 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 9,616 Hr Notes: The closing times of lots 413 thru 414 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:03 AM CDT Asset located in: Lake Worth, TX, USA
408	2011 Cat D6N LGP Crawler Dozer S/N: CAT00D6NHGHS00844 C/W: Located in Lane 10 Spot 26, Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 160 in Wide PAT Blade, 34 in Single Grouser Track Shoes, Drawbar Usage: Not Available Lot closing time: Wed, Sep 16, 11:02 AM CDT Asset located in: Humble, TX, USA	414	2014 John Deere 850K WLT Crawler Dozer S/N: 1T0850KXHEE265565 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2014 US EPA Label, CARB Compliant, 157 in Wide PAT Blade, 29.5 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 11,029 Hr Notes: The closing times of lots 413 thru 414 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:03 AM CDT Asset located in: San Antonio, TX, USA
410	2019 Komatsu D85PX-18 Crawler Dozer S/N: KMT0D128CJA023300 C/W: Located in Lane 10 Spot 1, Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, 174 in Wide Straight Blade 36 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics Usage: 7,375 Hr Notes: The closing times of lots 409 thru 410 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:02 AM CDT Asset located in: Humble, TX, USA	415	2021 Komatsu D65PX-18 Crawler Dozer S/N: KMT0D127CMA092927 C/W: Located in Lane 10 Spot 11, Enclosed Cab, Air Conditioner, Rear View Camera, 2021 US EPA Label, CARB Compliant, 156 in Wide Straight Blade w/ Single Tilt, 36.5 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics, Equipment-from-R-Construction Usage: 6,726 Hr Notes: From the Well Maintained Fleet of R Construction ; The closing times of lots 415 thru 416 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:04 AM CDT Asset located in: Humble, TX, USA
411	2021 Komatsu D71PX-24 Crawler Dozer S/N: KMT0D137VMA070250 C/W: Located in Lane 1 Spot 2, Enclosed Cab, Air Conditioner, Rear View Camera, 169 in Wide PAT Blade, 36 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 8,011 Hr Lot closing time: Wed, Sep 16, 11:03 AM CDT Asset located in: Lake Worth, TX, USA	416	2021 Komatsu D65PX-18 Crawler Dozer S/N: KMT0D127CMA092863 C/W: Located in Lane 10 Spot 19, Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 156 in Wide Straight Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics, Equipment-from-R-Construction Usage: 7,169 Hr Notes: From the Well-Maintained Fleet of R Construction Company ; The closing times of lots 415 thru 416 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:04 AM CDT Asset located in: Humble, TX, USA
412	2019 John Deere 850K LGP Crawler Dozer S/N: 1T0850KXKJF339935 C/W: Located in Lane 10 Spot 25, Enclosed Cab, Air Conditioner, 165 in Wide PAT Blade, 35.5 in Single Grouser Track Shoes, Carco H110B 245V JD850J Winch Usage: 4,334 Hr Lot closing time: Wed, Sep 16, 11:03 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
417	2021 John Deere 750L Crawler Dozer S/N: 1T0750LXAMF399122 C/W: Located in Lane 10 Spot 6, Enclosed Cab, Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 156 in Wide PAT Blade, 34 in Single Grouser Track Shoes Usage: Not Available Notes: The closing times of lots 417 thru 418 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:04 AM CDT Asset located in: Humble, TX, USA	421	2023 Komatsu D61EXI-24 Crawler Dozer S/N: KMT0D129KNA045753 C/W: Located in Lane 1 Spot 3, Enclosed Cab, Pre-Wired for Grade Control, Topcon Grade Control System, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 129 in Wide PAT Blade, 24 in Single Grouser Track Shoes, PLUS Undercarriage, 1 Cylinder Multi-Shank Ripper Usage: 4,794 Hr Notes: The closing times of lots 421 thru 422 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:06 AM CDT Asset located in: Lake Worth, TX, USA
418	2021 John Deere 750L Crawler Dozer S/N: 1T0750LXCMF394712 C/W: Located in Lane 10 Spot 20, Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, 160 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 5,795 Hr Notes: The closing times of lots 417 thru 418 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:05 AM CDT Asset located in: Humble, TX, USA	422	2023 Komatsu D61PX-24 Crawler Dozer S/N: B66027 C/W: Located in Lane 10 Spot 16, Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 150 in Wide PAT Blade, 34 in Single Grouser Track Shoes Usage: 4,074 Hr Notes: The closing times of lots 421 thru 422 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:06 AM CDT Asset located in: Humble, TX, USA
419	2019 John Deere 750K LGP Crawler Dozer S/N: 1T0750KXKKF358112 C/W: Located in Lane 10 Spot 4, Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,675 Hr Lot closing time: Wed, Sep 16, 11:05 AM CDT Asset located in: Humble, TX, USA	422A	2012 Komatsu D61PX-15E0 Crawler Dozer S/N: B47146 C/W: Located in Lane 10 Spot 24, Enclosed Cab, 2011 US EPA Label, 148 in Wide PAT Blade, 36 in Single Grouser Track Shoes Usage: 8,314 Hr Lot closing time: Wed, Sep 16, 11:06 AM CDT Asset located in: Humble, TX, USA
420	2012 John Deere 750J LT Crawler Dozer S/N: 1T0750JXTBD215378 C/W: Located in Lane 1 Spot 13, Enclosed Cab, Pre-Wired for Grade Control, 126 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 14,557 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; At 13,320 Hours - Reman John Deere Complete Engine, New John Deere Undercarriage, Rebuilt & Line Bored Crossbar, Pivot Shafts, Track Frame Bushings & Seals, C-Frame Pins & Bushings Rebuilt Lot closing time: Wed, Sep 16, 11:05 AM CDT Asset located in: Lake Worth, TX, USA	423	2015 Komatsu D61EX-23 Crawler Dozer S/N: KMT0D120CEA031624 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 126 in Wide PAT Blade, 23.5 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 7,028 Hr Lot closing time: Wed, Sep 16, 11:06 AM CDT Asset located in: Midland, TX, USA
		423A	2019 John Deere 700K LGP Crawler Dozer S/N: 1T0700KXVKF351311 C/W: Located in Lane 1 Spot 9, Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, US EPA Label, Requires Diesel Exhaust Fluid, 132 in Wide PAT Blade, 30 in Single Grouser Track Shoes Usage: 5,723 Hr Lot closing time: Wed, Sep 16, 11:06 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
424	2016 John Deere 700K Crawler Dozer S/N: 1T0700KXKGF297785 C/W: Located in Lane 1 Spot 6, Enclosed Cab, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 120 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 9,193 Hr Lot closing time: Wed, Sep 16, 11:06 AM CDT Asset located in: Lake Worth, TX, USA	429A	2012 John Deere 650K LGP Crawler Dozer S/N: 1T0650KXACE224774 C/W: Located in Lane 10 Spot 9, Open Operator Station, 2012 US EPA Label, Sweeps, 120 in Wide PAT Blade, 24 in Single Grouser Track Shoes Usage: 2,263 Hr Lot closing time: Wed, Sep 16, 11:08 AM CDT Asset located in: Humble, TX, USA
425	2012 John Deere 700K XLT Crawler Dozer S/N: 1T0700KXCCE232303 C/W: Located in Lane 10 Spot 23, Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 121 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics Usage: 5,763 Hr Lot closing time: Wed, Sep 16, 11:07 AM CDT Asset located in: Humble, TX, USA	430	2016 Cat D4K2 XL Crawler Dozer S/N: CAT00D4KHKM200285 C/W: Located in Lane 1 Spot 10, Open Operator Station, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 113 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 9,103 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:08 AM CDT Asset located in: Lake Worth, TX, USA
426	2014 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KCRST00500 C/W: Located in Lane 1 Spot 20, Enclosed Cab, Pre-Wired for Grade Control, Sweeps, 144 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 15,888 Hr Lot closing time: Wed, Sep 16, 11:07 AM CDT Asset located in: Lake Worth, TX, USA	431	2011 Cat D4K XL Crawler Dozer S/N: CAT00D4KCM MM00587 C/W: Located in Lane 1 Spot 17, Open Operator Station, 114 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 15,137 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:09 AM CDT Asset located in: Lake Worth, TX, USA
427	2022 Cat D3 Crawler Dozer S/N: CAT000D3VXKW02095 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Sweeps, 110 in Wide PAT Blade, 20 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics Usage: 3,165 Hr Lot closing time: Wed, Sep 16, 11:07 AM CDT Asset located in: Oklahoma City, OK, USA	432	2013 Cat D3K2 Crawler Dozer S/N: CAT0D3K2JKLL00340 C/W: Located in Lane 1 Spot 12, Open Operator Station, 2012 US EPA Label, 123 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: 9,301 Hr Lot closing time: Wed, Sep 16, 11:09 AM CDT Asset located in: Lake Worth, TX, USA
428	2014 Cat D5K2 XL Crawler Dozer S/N: CAT0D5K2KKWW00730 C/W: Open Operator Station, 2013 US EPA Label, Sweeps, 114 in Wide PAT Blade, 20 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,161 Hr Lot closing time: Wed, Sep 16, 11:08 AM CDT Asset located in: Lake Worth, TX, USA	433	2021 John Deere 550K Crawler Dozer S/N: 1T0550KKPMF394136 C/W: Located in Lane 1 Spot 11, Open Operator Station, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 114 in Wide PAT Blade, 17.6 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 5,703 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; The closing times of lots 433 thru 437 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:09 AM CDT Asset located in: Lake Worth, TX, USA
429	2011 Cat D5K LGP Crawler Dozer S/N: CAT00D5KAYYY01368 C/W: Located in Lane 10 Spot 17, Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Sweeps, 126 in Wide PAT Blade, 26 in Single Grouser Track Shoes Usage: 4,858 Hr Lot closing time: Wed, Sep 16, 11:08 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
434	2019 John Deere 550K Crawler Dozer S/N: 1T0550KKCKF355600 C/W: Located in Lane 10 Spot 21, Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 114 in Wide PAT Blade, 24 in Single Grouser Track Shoes Usage: 4,216 Hr Notes: The closing times of lots 433 thru 437 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:09 AM CDT Asset located in: Humble, TX, USA	438	2014 John Deere 450J LGP Crawler Dozer S/N: 1T0450JXVED258388 C/W: Located in Lane 1 Spot 7, Open Operator Station, 2014 US EPA Label, 114 in Wide PAT Blade, 24 in Single Grouser Track Shoes Usage: 4,804 Hr Lot closing time: Wed, Sep 16, 11:11 AM CDT Asset located in: Lake Worth, TX, USA
435	2019 John Deere 550K Crawler Dozer S/N: 1T0550KKEKF358200 C/W: Located in Lane 1 Spot 7, Open Operator Station, 2019 US EPA Label, 114 in Wide PAT Blade, 17.75 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 9,324 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; The closing times of lots 433 thru 437 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:10 AM CDT Asset located in: Lake Worth, TX, USA	439	2006 Cat D7R Series II Crawler Dozer S/N: CAT00D7RHAEC00937 C/W: Located in Lane 1 Spot 24, Enclosed Cab, 2015 US EPA Label, 143 in Wide Semi-U Blade w/ Single Tilt, 4 Cylinder Multi-Shank Ripper, 24 in Single Grouser Track Shoes Usage: 26,273 Hr Lot closing time: Wed, Sep 16, 11:11 AM CDT Asset located in: Lake Worth, TX, USA
436	2018 John Deere 550K Crawler Dozer S/N: 1T0550KKAJF332951 C/W: Located in Lane 1 Spot 18, Open Operator Station, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 104 in Wide PAT Blade, 17.5 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 7,548 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; The closing times of lots 433 thru 437 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:10 AM CDT Asset located in: Lake Worth, TX, USA	440	2004 Cat D6N LGP Crawler Dozer S/N: ALY571 C/W: Located in Lane 10 Spot 7, Enclosed Cab, 158 in Wide PAT Blade, 33.75 in Single Grouser Track Shoes, Winch Usage: 10,980 Hr Lot closing time: Wed, Sep 16, 11:11 AM CDT Asset located in: Humble, TX, USA
437	2019 John Deere 550K Crawler Dozer S/N: 1T0550KKLJF341277 C/W: Located in Lane 1 Spot 19, Open Operator Station, Pre-Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 114 in Wide PAT Blade, w/ Power Pitch, 17.5 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 8,685 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; The closing times of lots 433 thru 437 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:10 AM CDT Asset located in: Lake Worth, TX, USA	442	2002 John Deere 700H LGP Crawler Dozer S/N: 845766 C/W: Located in Lane 1 Spot 15, Enclosed Cab, Air Conditioner, 2001 US EPA Label, Sweeps, 132 in Wide PAT Blade, 20 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 11,821 Hr Lot closing time: Wed, Sep 16, 11:12 AM CDT Asset located in: Lake Worth, TX, USA
		443	2007 Cat D6K LGP Crawler Dozer S/N: CAT00D6KEDHA00231 C/W: Open Operator Station, Sweeps, 130 in Wide PAT Blade, 30 in Single Grouser Track Shoes Usage: 8,184 Hr Lot closing time: Wed, Sep 16, 11:12 AM CDT Asset located in: Lake Worth, TX, USA
		443A	2006 Komatsu D31EX-21 Crawler Dozer S/N: KMT0D005A01050640 C/W: Located in Lane 1 Spot 23, Open Operator Station, 96 in Wide PAT Blade, 16 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 2,013 Hr Lot closing time: Wed, Sep 16, 11:12 AM CDT Asset located in: Lake Worth, TX, USA
		444	1996 John Deere 450G Crawler Dozer S/N: T0450GH824406 C/W: Open Operator Station, 120 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 5,468 Hr Lot closing time: Wed, Sep 16, 11:12 AM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
445	1986 Case 450C Crawler Dozer S/N: 3077787 C/W: Open Operator Station, Sweeps, 88 in Wide PAT Blade, 16 in Single Grouser Track Shoes Usage: 5,193 Hr Lot closing time: Wed, Sep 16, 11:13 AM CDT Asset located in: Humble, TX, USA	452	2017 Cat 745C Articulated Dump Truck S/N: CAT0745CHTFK01557 C/W: Located in Lane 3 Spot 5, Air Conditioner, Engine Brake, Air Ride Seat, 2016 US EPA Label, 29.5R25 Tires Usage: 10,868 Hr Lot closing time: Wed, Sep 16, 11:15 AM CDT Asset located in: Lake Worth, TX, USA
448	1996 Cat 775D Haul Truck S/N: 6KR00083 C/W: Air Conditioner, Retarder, Auto Lube, Fast Fuel Fill, 24.00R35 Tires Usage: 46,392 Hr Lot closing time: Wed, Sep 16, 11:14 AM CDT Asset located in: Oklahoma City, OK, USA	452A	2018 Bell B50E Articulated Dump Truck S/N: B93A650ET01205849 C/W: Located in Lane 3 Spot 5, Air Conditioner, Retarder, Air Ride Seat, Auto Lube, 875/65R29 Tires Usage: 10,095 Hr Lot closing time: Wed, Sep 16, 11:15 AM CDT Asset located in: Lake Worth, TX, USA
449	2019 Cat 745 Articulated Dump Truck S/N: CAT00745V3T601995 C/W: Located in Lane 3 Spot 4, Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Tailgate, Auto Lube, 29.5 R25 Tires Usage: 7,970 Hr Notes: Cat Dealer Rebuilt Transmission at 7,697 Hours , Replaced Brake Accumulators at 6,135 Hours ; The closing times of lots 449 thru 451 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:14 AM CDT Asset located in: Lake Worth, TX, USA	452B	2020 Bell B45E Articulated Dump Truck S/N: B93A345FH03007414 C/W: Located in Lane 3 Spot 6, Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 9,548 Hr Lot closing time: Wed, Sep 16, 11:15 AM CDT Asset located in: Lake Worth, TX, USA
450	2019 Cat 745 Articulated Dump Truck S/N: CAT00745A3T601920 C/W: Located in Lane 3 Spot 1, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5 R25 Tires Usage: 8,376 Hr Notes: Cat Dealer Reman Transmission - Installed at 6,225 Hours Dealer Reconditioned Engine at 6,255 Hours ; The closing times of lots 449 thru 451 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:14 AM CDT Asset located in: Lake Worth, TX, USA	453	2012 Terex TA400 Articulated Dump Truck S/N: A11151042 C/W: Located in Lane 3 Spot 4, Air Conditioner, Retarder, Rear View Camera, 29.5R25 Tires Usage: 542 Hr Lot closing time: Wed, Sep 16, 11:15 AM CDT Asset located in: Lake Worth, TX, USA
451	2019 Cat 745 Articulated Dump Truck S/N: CAT00745E3T601968 C/W: Located in Lane 3 Spot 3, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 8,551 Hr Notes: Updated Cat Service Letter - Transmission Software, Wiring Harness, Modulating Valves at 3,844 Hours ; The closing times of lots 449 thru 451 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:15 AM CDT Asset located in: Lake Worth, TX, USA	454	2015 Komatsu HM300-5 Articulated Dump Truck S/N: KMTHM015HED010097 C/W: Air Conditioner, Rear View Camera, Emissions Altered, 2018 US EPA Label, Tailgate, 23.5R25 Tires, Equipment-from-Reclamation-Contractors-of-Texas Usage: 8,838 Hr Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Buyer responsible for removal of this item. Item at an offsite location must be picked up within 14 days of the auction ; The closing times of lots 454 thru 455 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:15 AM CDT Asset located in: New London, TX, USA

Lot #	Details	Lot #	Details
455	2015 Komatsu HM300-5 Articulated Dump Truck S/N: KMTM015CED010099 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Emissions Altered, 2014 US EPA Label, Tailgate, 23.5R25 Tires, Equipment-from-Reclamation-Contractors-of-Texas Usage: 9,916 Hr Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard; Buyer responsible for removal of this item. Item at an offsite location must be picked up within 14 days of the auction ; The closing times of lots 454 thru 455 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:16 AM CDT Asset located in: New London, TX, USA	460	2026 DT1300-BLUE 6-Wheel Dumper (Unused) S/N: A2604230637 C/W: Located in Lane 56 Spot 1, 1 Cylinder 13.5 hp 420 cc Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:17 AM CDT Asset located in: Lake Worth, TX, USA
456	2014 John Deere 250D SERIES II Articulated Dump Truck S/N: 1DW250DXLEE661408 C/W: Air Conditioner, Retarder, 23.5R25 Tires Usage: 11,409 Hr Notes: The closing times of lots 456 thru 457 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:16 AM CDT Asset located in: San Antonio, TX, USA	461	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605028952 C/W: Located in Lane 56, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:18 AM CDT Asset located in: Lake Worth, TX, USA
457	2013 John Deere 250D Series II Articulated Dump Truck S/N: 1DW250DXACE650243 C/W: Air Conditioner, Retarder, 23.5R25 Tires Usage: 14,002 Hr Notes: The closing times of lots 456 thru 457 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Wed, Sep 16, 11:16 AM CDT Asset located in: San Antonio, TX, USA	462	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605228481 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:18 AM CDT Asset located in: Humble, TX, USA
459	2026 DT1300-BLUE 6-Wheel Dumper (Unused) S/N: A2604230634 C/W: Located in Lane 56 Spot 1, 1 Cylinder 13.5 hp 420 cc Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:17 AM CDT Asset located in: Lake Worth, TX, USA	463	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605228470 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:18 AM CDT Asset located in: Humble, TX, USA
		464	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605029011 C/W: Located in Lane 56, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:18 AM CDT Asset located in: Lake Worth, TX, USA
		465	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605228555 C/W: Located in Lane 56, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:19 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
466	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605029179 C/W: Located in Lane 56, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:19 AM CDT Asset located in: Lake Worth, TX, USA	472	2026 CDW25S Mini Crawler Dumper (Unused) S/N: 2605088264 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:21 AM CDT Asset located in: Humble, TX, USA
467	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605228436 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:19 AM CDT Asset located in: Humble, TX, USA	473	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: A2512392937 C/W: Located in Lane 56 Spot 1, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
468	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605228790 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:20 AM CDT Asset located in: Humble, TX, USA	474	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: A2512393598 C/W: Located in Lane 56 Spot 1, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
469	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605209407 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:20 AM CDT Asset located in: Humble, TX, USA	477	2018 LeeBoy RB50 Self-Propelled Broom S/N: 201085 C/W: Located in Lane 14 Spot 33, Enclosed Cab, Air Conditioner, 8 ft 2 in Broom, Water System, 4 Cylinder Diesel Engine Usage: 3,031 Hr Lot closing time: Wed, Sep 16, 11:22 AM CDT Asset located in: Humble, TX, USA
470	2026 CD25,CDW25 Mini Crawler Dumper (Unused) S/N: 2605228543 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:20 AM CDT Asset located in: Humble, TX, USA	478	2013 Broce KR350 Self-Propelled Broom S/N: 408131 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, Tier 3, 2011 US EPA Label, Kubota V3600-t-et02 4 Cylinder 63 kW 3.6 L Diesel Engine Usage: 897 Hr Lot closing time: Wed, Sep 16, 11:23 AM CDT Asset located in: Midland, TX, USA
471	2026 CDW25S Mini Crawler Dumper (Unused) S/N: 2605097013 C/W: Located in Lane 47 Spot 0, 1 Cylinder 15 hp 420 cc Gasoline Engine, 9 in Rubber Tracks, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 11:21 AM CDT Asset located in: Humble, TX, USA	479A	2001 Broce RJ350 Self-Propelled Broom S/N: 401200 C/W: Open Operator Station, 7 ft 8 in Broom, Water System, John Deere 4 Cylinder Diesel Engine Usage: 4,857 Hr Lot closing time: Wed, Sep 16, 11:23 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
480A	Broce BW-260 Self-Propelled Broom S/N: 201866 C/W: Located in Lane 14 Spot 32, Open Operator Station, 8 ft 5 in Broom, Water System, Tier 4, 2018 US EPA Label, Kubota V1505-EF01 4 Cylinder 18.2 kW 1.5 L Diesel Engine Usage: 6,022 Hr Lot closing time: Wed, Sep 16, 11:23 AM CDT Asset located in: Humble, TX, USA	486	2014 Hamm H11i Padfoot Drum Compactor S/N: P2110202 C/W: Located in Lane 4 Spot 26, Open Operator Station, 2014 US EPA Label, Deutz TCD 4.1 L4 4 Cylinder 141 hp 4.03 L Diesel Engine, 84 in Drum Usage: 3,481 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:25 AM CDT Asset located in: Lake Worth, TX, USA
481	2011 Lay-Mor 8HC Self-Propelled Broom S/N: 33449 C/W: Located in Lane 4 Spot 20, Open Operator Station, 7 ft 8 in Broom, Water System, Tier 4, 2011 US EPA Label, Kubota 4 Cylinder 1.5 L Diesel Engine Usage: 1,983 Hr Lot closing time: Wed, Sep 16, 11:24 AM CDT Asset located in: Lake Worth, TX, USA	486A	2015 Hamm H7iP Padfoot Drum Compactor S/N: H2220077 C/W: Located in Lane 4 Spot 24, Open Operator Station, Tier 4, 2014 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 66 in Drum Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:25 AM CDT Asset located in: Lake Worth, TX, USA
482	2013 Dynapac CT3000 Soil Compactor S/N: 10000505A0B003683 C/W: Located in Lane 56 Spot 2, Enclosed Cab, Air Conditioner, Swivel Operator Controls, Cummins 6 Cylinder Diesel Engine, 40 in Compaction Wheel Width, 136 in Semi-U Blade w/ Dual Tilt Usage: Not Available Lot closing time: Wed, Sep 16, 11:24 AM CDT Asset located in: Lake Worth, TX, USA	487	2001 Cat CP433C Padfoot Drum Compactor S/N: 2JM01057 C/W: Located in Lane 4 Spot 36, Open Operator Station, 4 Cylinder Diesel Engine, 66 in Drum, Leveling Blade Usage: 4,118 Hr Lot closing time: Wed, Sep 16, 11:25 AM CDT Asset located in: Lake Worth, TX, USA
483	2023 Sakai SV544 Padfoot Drum Compactor S/N: 3SV56-10819 C/W: Located in Lane 11 Spot 2, Open Operator Station, Cummins 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 2,603 Hr Lot closing time: Wed, Sep 16, 11:24 AM CDT Asset located in: Humble, TX, USA	489	2000 Cat CP-323C Padfoot Drum Compactor S/N: 6DM00460 C/W: Located in Lane 4 Spot 32, Open Operator Station, US EPA Label, Perkins 4 Cylinder 51.9 kW Diesel Engine, 50 in Drum, Leveling Blade Usage: Not Available Lot closing time: Wed, Sep 16, 11:26 AM CDT Asset located in: Lake Worth, TX, USA
484	Sakai SV544T Padfoot Drum Compactor S/N: 3SV56-10759 C/W: Located in Lane 75 Spot 0, Open Operator Station, Cummins 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 2,989 Hr Lot closing time: Wed, Sep 16, 11:24 AM CDT Asset located in: Humble, TX, USA	490	2007 Dynapac CA362D Smooth Drum Compactor S/N: 72490969 C/W: Enclosed Cab, Air Conditioner, Cummins 6 Cylinder Diesel Engine, 84 in Drum Usage: 2,886 Hr Lot closing time: Wed, Sep 16, 11:26 AM CDT Asset located in: Oklahoma City, OK, USA
484A	2009 Sakai SV505 Padfoot Drum Compactor S/N: VSV1650656 C/W: Located in Lane 4 Spot 30, Open Operator Station, 2008 US EPA Label, Cummins QSB4.5 4 Cylinder 130 hp 4.5 L Diesel Engine, 84 in Drum Usage: 5,974 Hr Lot closing time: Wed, Sep 16, 11:25 AM CDT Asset located in: Lake Worth, TX, USA	491	2022 Cat CS56B Smooth Drum Compactor S/N: CATCS56BKS5601668 C/W: Located in Lane 75 Spot 0, Open Operator Station, Rear View Camera, Cat 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: Not Available Lot closing time: Wed, Sep 16, 11:27 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
493	2008 Sakai SV505 Smooth Drum Compactor S/N: VSV16-50612 C/W: Located in Lane 4 Spot 31, Open Operator Station, 2007 US EPA Label, Cummins QSB4.5 4 Cylinder 130 hp 4.5 L Diesel Engine, 84 in Drum Usage: 3,943 Hr Lot closing time: Wed, Sep 16, 11:27 AM CDT Asset located in: Lake Worth, TX, USA	501	2019 Dynapac CC4200 VI Double Drum Roller S/N: 10000385CKA024542 C/W: Located in Lane 4 Spot 28, Open Operator Station, 2018 US EPA Label, Cummins 4 Cylinder 3.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 66 in Compaction Width, Water System Usage: 4,134 Hr Lot closing time: Wed, Sep 16, 11:30 AM CDT Asset located in: Lake Worth, TX, USA
494	Raygo 404B Smooth Drum Compactor S/N: Not Available C/W: Located in Lane 45 Spot 0, Open Operator Station, Detroit 3 Cylinder Diesel Engine, 84 in Drum Usage: 4,309 Hr Lot closing time: Wed, Sep 16, 11:27 AM CDT Asset located in: Humble, TX, USA	502	2018 Dynapac CC6200VI Double Drum Roller S/N: 10000387PJA022485 C/W: Open Operator Station, Swivel Operator Controls, 2017 US EPA Label, Cummins QSF3.8 4 Cylinder 3.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Compaction Width, Water System Usage: 867 Hr Lot closing time: Wed, Sep 16, 11:30 AM CDT Asset located in: Midland, TX, USA
495	2012 Bomag BW177D-40 Smooth Drum Compactor S/N: 901582261214 C/W: Located in Lane 4 Spot 31, Open Operator Station, 2011 US EPA Label, Cummins B3.3 4 Cylinder 80 hp 3.26 L Diesel Engine, 68 in Drum Usage: 4,249 Hr Lot closing time: Wed, Sep 16, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	504	2010 Cat CB64 Double Drum Roller S/N: CAT0CB64VDJM00139 C/W: Located in Lane 4 Spot 29, Open Operator Station, Swivel Operator Controls, Air Ride Seat, Cat 4 Cylinder Diesel Engine, 84 in Compaction Width, Water System Usage: 7,662 Hr Lot closing time: Wed, Sep 16, 11:30 AM CDT Asset located in: Lake Worth, TX, USA
497	2021 Cat CS34 Smooth Drum Compactor S/N: CAT0CS34L51400702 C/W: Located in Lane 75 Spot 0, Open Operator Station, Rear View Camera, Cat 4 Cylinder Diesel Engine, 50 in Drum Usage: 1,344 Hr Lot closing time: Wed, Sep 16, 11:28 AM CDT Asset located in: Humble, TX, USA	506	2020 Case DV45E Double Drum Roller S/N: DDDDV45ENLWTX3132 C/W: Located in Lane 11 Spot 3, Open Operator Station, Dual Controls, Tier 4, 2019 US EPA Label, Kubota D1803-CR-T-EW02 3 Cylinder 32.3 kW 1.8 L Diesel Engine, 54 in Compaction Width, Water System Usage: Not Available Lot closing time: Wed, Sep 16, 11:31 AM CDT Asset located in: Humble, TX, USA
499	2019 Cat CB15 Double Drum Roller S/N: CAT0CB15PM9400220 C/W: Open Operator Station, Swivel Operator Controls, 2019 US EPA Label, Cat C4.4 4 Cylinder 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Compaction Width, Water System Usage: 3,573 Hr Lot closing time: Wed, Sep 16, 11:29 AM CDT Asset located in: Midland, TX, USA	506A	2017 Cat CB34B Double Drum Roller S/N: CATCB34BCXB400400 C/W: Open Operator Station, Cat 4 Cylinder Diesel Engine, 51 in Compaction Width, Water System, Edge Cutter Usage: 11,016 Hr Lot closing time: Wed, Sep 16, 11:31 AM CDT Asset located in: Lake Worth, TX, USA
500	2020 Volvo DD140C Double Drum Roller S/N: VCED140CT08290081 C/W: Located in Lane 4 Spot 35, Open Operator Station, Swivel Operator Controls, Air Ride Seat, 2020 US EPA Label, Volvo D4J 148 hp 4.03 L Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Compaction Width, Water System Usage: 1,957 Hr Lot closing time: Wed, Sep 16, 11:29 AM CDT Asset located in: Lake Worth, TX, USA	507	2006 Dynapac CC142 Double Drum Roller S/N: 60213292 C/W: Located in Lane 4 Spot 22, Open Operator Station, 2005 US EPA Label, Deutz F 3L 2011 3 Cylinder 45 hp 2.3 L Diesel Engine, 51 in Compaction Width Usage: 1,509 Hr Lot closing time: Wed, Sep 16, 11:31 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
508	2012 Wacker Neuson RD12A Double Drum Roller S/N: 20012604 C/W: Located in Lane 46 Spot 0, Open Operator Station, 2020 US EPA Label, Honda 4 Cylinder Gasoline Engine, 36 in Compaction Width, Water System Usage: Not Available Lot closing time: Wed, Sep 16, 11:32 AM CDT Asset located in: Humble, TX, USA	513	2010 Volvo PT240R 8 Wheel Pneumatic Roller (Inoperable) S/N: VCE0T240L0S325094 C/W: Open Operator Station, Dual Controls, Diesel Engine, 68 in Compaction Width, Water System Usage: Not Available Notes: Item at offsite location must be picked up within 14 days of auction (October 2nd) or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 11:33 AM CDT Asset located in: Austin, TX, USA
509	Wacker Neuson RD11A Double Drum Roller S/N: Not Available C/W: Located in Lane 4 Spot 21, Open Operator Station, Briggs & Stratton Vanguard 2 Cylinder 18 hp 570 cc Gasoline Engine, 36 in Compaction Width, Water System, Edge Cutter Usage: Not Available Lot closing time: Wed, Sep 16, 11:32 AM CDT Asset located in: Lake Worth, TX, USA	517	1998 Cat 325B L Long Reach Tracked Excavator S/N: 2JR01824 C/W: Located in Lane 00 Spot 1, 33 ft 8 in Boom, 25 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, 58 in Cleanup Bucket Usage: 9,343 Hr Lot closing time: Wed, Sep 16, 11:34 AM CDT Asset located in: Lake Worth, TX, USA
510	2020 Case PT240D 8 Wheel Pneumatic Roller S/N: DDDP240DNKNTJ2100 C/W: Located in Lane 4 Spot 23, Open Operator Station, 2019 US EPA Label, Deutz TCD 3.6 L4 4 Cylinder 100 hp 3.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 68 in Compaction Width, Water System Usage: 999 Hr Lot closing time: Wed, Sep 16, 11:32 AM CDT Asset located in: Lake Worth, TX, USA	517A	2018 Cat 352FLRE Tracked Excavator S/N: CAT0352FCA9J20032 C/W: Located in Lane 2 Spot 20, Air Conditioner, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 35.5 in Triple Grouser Track Shoes, 72 in Digging Bucket, Counterweight Removal System Usage: 12,335 Hr Lot closing time: Wed, Sep 16, 11:34 AM CDT Asset located in: Humble, TX, USA
511	2014 Cat CW34 8 Wheel Pneumatic Roller S/N: CAT0CW34PTLJ00173 C/W: Located in Lane 4 Spot 27, Open Operator Station, 2013 US EPA Label, Cat 4.4 L Diesel Engine, 82 in Compaction Width, Heat Retention Shields, Water System Usage: 4,924 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:33 AM CDT Asset located in: Lake Worth, TX, USA	519	2019 Volvo EC480EL Tracked Excavator S/N: VCEC480EE00314142 C/W: Located in Lane 2 Spot 2, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 11 ft Stick, Auxiliary Hydraulic Plumbing, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 66 in Digging Bucket Usage: 8,361 Hr Notes: The closing times of lots 519 thru 520 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:35 AM CDT Asset located in: Humble, TX, USA
512	2015 Cat CW14 9 Wheel Pneumatic Roller S/N: CAT0CW14VLTJ00389 C/W: Located in Lane 4 Spot 25, Open Operator Station, 2015 US EPA Label, Cat C3.4B 4 Cylinder 3.4 L Diesel Engine, 69 in Compaction Width Usage: 764 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:33 AM CDT Asset located in: Lake Worth, TX, USA	520	2019 Volvo EC480EL VG Tracked Excavator S/N: VCEC480EC00311167 C/W: Located in Lane 57 Spot 8, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 13 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, Counterweight Removal System Usage: 8,254 Hr Notes: The closing times of lots 519 thru 520 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:35 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
521	2022 Hyundai HX480A L Tracked Excavator S/N: HHKHKB04CE0000081 C/W: Located in Lane 2 Spot 28, Air Conditioner, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, 32 in Triple Grouser Track Shoes, 72 in Digging Bucket Usage: 1,235 Hr Lot closing time: Wed, Sep 16, 11:36 AM CDT Asset located in: Humble, TX, USA	526	2020 Volvo EC350EL Tracked Excavator S/N: VCEC350EV00314153 C/W: Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, Auxiliary Hydraulic Plumbing, 36 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 5,108 Hr Notes: The closing times of lots 524 thru 526 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:37 AM CDT Asset located in: Midland, TX, USA
523A	2022 Sany SY365C9C5K Tracked Excavator S/N: SY0361CC00058 C/W: Located in Lane 75 Spot 0, Rear View Camera, US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulic Plumbing, Track Shoes, Equipment-From-Herc-Rentals Usage: 2,216 Hr Lot closing time: Wed, Sep 16, 11:36 AM CDT Asset located in: Humble, TX, USA	528	2023 Cat 340 Tracked Excavator S/N: CAT00340PGDZ10180 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 3,279 Hr Notes: The closing times of lots 528 thru 532 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner ; Comes with Ironclad Assurance. Subject to Texas Sales Tax. Lot closing time: Wed, Sep 16, 11:38 AM CDT Asset located in: Abilene, TX, USA
524	2023 Volvo EC350EL Tracked Excavator S/N: VCEC350ET00314713 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 36 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 571 Hr Notes: The closing times of lots 524 thru 526 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:36 AM CDT Asset located in: Midland, TX, USA	529	2023 Cat 340 Tracked Excavator S/N: CAT00340LGDZ10091 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 3,016 Hr Notes: The closing times of lots 528 thru 532 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner ; Comes with Ironclad Assurance. Subject to Texas Sales Tax. Lot closing time: Wed, Sep 16, 11:38 AM CDT Asset located in: Abilene, TX, USA
525	2023 Volvo EC350EL Tracked Excavator S/N: VCEC350EJ00314652 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Surround View Cameras, Volvo Dig Assist Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 1,313 Hr Notes: The closing times of lots 524 thru 526 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:37 AM CDT Asset located in: Oklahoma City, OK, USA	530	2023 Cat 340 Tracked Excavator S/N: CAT00340KGDZ00332 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, 33.5 in Triple Grouser Track Shoes, 37 in Digging Bucket Usage: 4,109 Hr Notes: The closing times of lots 528 thru 532 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner ; Comes with Ironclad Assurance. Subject to Texas Sales Tax. Lot closing time: Wed, Sep 16, 11:38 AM CDT Asset located in: Odessa, TX, USA

Lot #	Details	Lot #	Details
531	2023 Cat 340 Tracked Excavator S/N: CAT00340CEFH10112 C/W: Located in Lane 2 Spot 3, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Surround View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket, Equipment-from-R-Construction Usage: 6,787 Hr Notes: From the Well Maintained Fleet of R Construction ; The closing times of lots 528 thru 532 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:39 AM CDT Asset located in: Humble, TX, USA	535	2021 Cat 336 Tracked Excavator S/N: CAT00336JYBN20489 C/W: Located in Lane 2 Spot 1, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket, Equipment-from-R-Construction Usage: 7,626 Hr Notes: From the Well Maintained Fleet of R Construction ; The closing times of lots 534 thru 540 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:40 AM CDT Asset located in: Humble, TX, USA
532	2023 Cat 340 Tracked Excavator S/N: CAT00340JEFH10228 C/W: Located in Lane 2 Spot 4, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Surround View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket, Equipment-from-R-Construction Usage: 7,002 Hr Notes: From the Well Maintained Fleet of R Construction ; The closing times of lots 528 thru 532 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:39 AM CDT Asset located in: Humble, TX, USA	536	2021 Cat 336 Tracked Excavator S/N: CAT00336EYBN20694 C/W: Located in Lane 2 Spot 13, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 54 in Digging Bucket Usage: 8,025 Hr Notes: The closing times of lots 534 thru 540 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:40 AM CDT Asset located in: Humble, TX, USA
534	2022 Cat 336 Tracked Excavator S/N: CAT00336EDKS20308 C/W: Located in Lane 75, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 8,496 Hr Notes: The closing times of lots 534 thru 540 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:39 AM CDT Asset located in: Humble, TX, USA	537	2021 Cat 336 Tracked Excavator S/N: CAT00336VDKS20223 C/W: Located in Lane 2 Spot 2, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket, Equipment-from-R-Construction Usage: 8,124 Hr Notes: From the Well Maintained Fleet of R Construction ; The closing times of lots 534 thru 540 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:40 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
538	2020 Cat 336 Tracked Excavator S/N: CAT00336CYBN10031 C/W: Located in Lane 2 Spot 9, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket, Equipment-from-R-Construction Usage: 8,493 Hr Notes: From the Well Maintained Fleet of R Construction ; The closing times of lots 534 thru 540 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:41 AM CDT Asset located in: Humble, TX, USA	542	2017 Cat 336F L Tracked Excavator S/N: CAT0336FLRKB10594 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 37.5 in Digging Bucket Usage: 5,714 Hr Notes: The closing times of lots 542 thru 544 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:42 AM CDT Asset located in: Midland, TX, USA
540	2019 Cat 336 Tracked Excavator S/N: CAT00336TDKS00434 C/W: Air Conditioner, Straight Travel Pedal, US EPA Label, 12 ft 9 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 40 in Digging Bucket, Equipment-from-Mead-Lake-Point Usage: 726 Hr Notes: The closing times of lots 534 thru 540 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:41 AM CDT Asset located in: Midland, TX, USA	543	2015 Cat 336FL Tracked Excavator S/N: CAT0336FATZA00271 C/W: Located in Lane 58 Spot 6, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes Usage: 9,297 Hr Notes: The closing times of lots 542 thru 544 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:42 AM CDT Asset located in: Lake Worth, TX, USA
540A	2018 Cat 336FL Tracked Excavator S/N: CAT0336FTRKB20208 C/W: Located in Lane 60 Spot 8, Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, 34 in Triple Grouser Track Shoes, 50 in Digging Bucket Usage: 13,490 Hr Lot closing time: Wed, Sep 16, 11:41 AM CDT Asset located in: Lake Worth, TX, USA	545	2023 Komatsu PC360LC-11 Tracked Excavator S/N: KMTPC256LNWA39246 C/W: Located in Lane 2 Spot 17, Air Conditioner, Control Pattern Changer, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 47 in Digging Bucket, Equipment-from-R-Construction Usage: 6,826 Hr Notes: From the Well Maintained Fleet of R Construction ; Lot closing time: Wed, Sep 16, 11:43 AM CDT Asset located in: Humble, TX, USA
540B	2018 Cat 336FL Tracked Excavator S/N: CAT0336FCTZA20114 C/W: Located in Lane 2 Spot 24, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera, US EPA Label, 12 ft 6 in Stick, 27.5 in Single Grouser Track Shoes, Hydraulic Quick Coupler Usage: 11,972 Hr Lot closing time: Wed, Sep 16, 11:41 AM CDT Asset located in: Humble, TX, USA	545A	2016 Komatsu PC360LC-11 Tracked Excavator S/N: KMTPC256VFC090131 C/W: Located in Lane 57 Spot 4, Air Conditioner, Rear View Camera, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 2 in Stick, 33.6 in Triple Grouser Track Shoes, 43 in Digging Bucket Usage: 4,729 Hr Lot closing time: Wed, Sep 16, 11:43 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
546	2013 Komatsu PC360LC-10 Tracked Excavator S/N: KMTPC242L54A32498 C/W: Air Conditioner, Rear View Camera, 2012 US EPA Label, 10 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Rock Guards Usage: 6,547 Hr Lot closing time: Wed, Sep 16, 11:43 AM CDT Asset located in: Livingston, LA, USA	552A	2015 John Deere 350G LC Tracked Excavator S/N: 1FF350GXAFF810612 C/W: Located in Lane 61 Spot 24, Requires Diesel Exhaust Fluid, 13 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 68 in Digging Bucket Usage: 7,921 Hr Lot closing time: Wed, Sep 16, 11:45 AM CDT Asset located in: Lake Worth, TX, USA
547	2021 Sany SY365C9C5K Tracked Excavator S/N: SY0361CB00318 C/W: Located in Lane 2 Spot 14, Air Conditioner, Control Pattern Changer, Rear View Camera, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 60 in Digging Bucket Usage: 3,803 Hr Notes: ***Please see the attached warranty document below.*** Lot closing time: Wed, Sep 16, 11:43 AM CDT Asset located in: Humble, TX, USA	555	2013 Kobelco SK350LC-9 Tracked Excavator S/N: YC12-10207 C/W: Located in Lane 2 Spot 23, Air Conditioner, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 10 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket, Thumb Bracket Usage: 9,865 Hr Lot closing time: Wed, Sep 16, 11:46 AM CDT Asset located in: Humble, TX, USA
550	2021 John Deere 350G LC Tracked Excavator S/N: 1FF350GXLMF814948 C/W: Located in Lane 57 Spot 13, Air Conditioner, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket Usage: 8,260 Hr Notes: The closing times of lots 550 thru 552 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:44 AM CDT Asset located in: Lake Worth, TX, USA	556	2018 Hyundai HX330L Tracked Excavator S/N: HHKHK901KK0000329 C/W: Located in Lane 3 Spot 28, Air Conditioner, Control Pattern Changer, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 60 in Digging Bucket Usage: 7,974 Hr Lot closing time: Wed, Sep 16, 11:46 AM CDT Asset located in: Humble, TX, USA
552	2019 John Deere 350GLC Tracked Excavator S/N: 1FF350GXVKF813888 C/W: Located in Lane 61 Spot 21, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 2,260 Hr Notes: The closing times of lots 550 thru 552 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:45 AM CDT Asset located in: Lake Worth, TX, USA	558	2018 Cat 330FL Tracked Excavator S/N: CAT0330FAMBX20489 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 8 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 33 in Bucket Usage: 3,762 Hr Notes: The closing times of lots 558 thru 561 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:47 AM CDT Asset located in: Midland, TX, USA
		559	2018 Cat 330F L Tracked Excavator S/N: CAT0330FPHCK20146 C/W: Straight Travel Pedal, Control Pattern Changer, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.2 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 32 in Digging Bucket Usage: 3,829 Hr Notes: The closing times of lots 558 thru 561 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:47 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
560	2018 Cat 330FL Tracked Excavator S/N: CAT0330FEMBX20531 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 3 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 33 in Cleanup Bucket Usage: 4,226 Hr Notes: The closing times of lots 558 thru 561 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:47 AM CDT Asset located in: Midland, TX, USA	563	2020 Komatsu PC290LC11 Tracked Excavator S/N: KMTPC255AKKK73215 C/W: Located in Lane 57, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 30 in V-Bottom Bucket Usage: 7,721 Hr Notes: The closing times of lots 563 thru 565 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:48 AM CDT Asset located in: Lake Worth, TX, USA
561	2018 Cat 330F L Tracked Excavator S/N: CAT0330FVMBX20393 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Tier 4, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 35 in Digging Bucket Usage: 4,708 Hr Notes: The closing times of lots 558 thru 561 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:48 AM CDT Asset located in: Midland, TX, USA	564	2019 Komatsu PC290LC11 Tracked Excavator S/N: KMTPC255JJKK73080 C/W: Located in Lane 60 Spot 7, Air Conditioner, Rear View Camera, 11 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 46 in Digging Bucket, Thumb Bracket Usage: 5,157 Hr Notes: The closing times of lots 563 thru 565 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:48 AM CDT Asset located in: Lake Worth, TX, USA
561A	2018 Cat 330F L Tracked Excavator S/N: CAT0330FAMBX20055 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 33 in Digging Bucket Usage: 4,324 Hr Lot closing time: Wed, Sep 16, 11:48 AM CDT Asset located in: Midland, TX, USA	565	2016 Komatsu PC290LC-11 Tracked Excavator S/N: KNTPC255TEWA27207 C/W: Located in Lane 60 Spot 15, Air Conditioner, Rear View Camera, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket Usage: 4,832 Hr Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. ; The closing times of lots 563 thru 565 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:49 AM CDT Asset located in: Lake Worth, TX, USA
562	2023 John Deere 300 P-Tier Tracked Excavator S/N: 1FF300PAVPF000231 C/W: Located in Lane 57 Spot 5, Air Conditioner, Rear View Camera, 2023 US EPA Label, 12 ft Stick, Auxiliary Hydraulic Plumbing, 31.6 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 3,943 Hr Lot closing time: Wed, Sep 16, 11:48 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
568	2022 Kobelco SK260LC-11 Tracked Excavator S/N: LQ18020146 C/W: Located in Lane 2 Spot 8, Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 724 Hr Notes: The closing times of lots 568 thru 570 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:50 AM CDT Asset located in: Humble, TX, USA	572	2017 Komatsu PC240-LC-11 Tracked Excavator S/N: KMTPC252AHWA22270 C/W: Located in Lane 58 Spot 8, Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 11 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket, Thumb Bracket Usage: 5,769 Hr Lot closing time: Wed, Sep 16, 11:51 AM CDT Asset located in: Lake Worth, TX, USA
569	2022 Kobelco SK260LC-11 Tracked Excavator S/N: LQ18020039 C/W: Air Conditioner, Control Pattern Changer, Surround View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 1,093 Hr Notes: The closing times of lots 568 thru 570 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:50 AM CDT Asset located in: Oklahoma City, OK, USA	573	2023 Sany SY225C9C5KL Tracked Excavator S/N: SY0225CDM1268 C/W: Located in Lane 60 Spot 1, Control Pattern Changer, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 1,608 Hr Notes: The closing times of lots 573 thru 576 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; ***Click on the link below for Seller Supplied Warranty Transfer Notice*** Lot closing time: Wed, Sep 16, 11:51 AM CDT Asset located in: Lake Worth, TX, USA
570	2022 Kobelco Sk260LC-11 Tracked Excavator S/N: LQ18020135 C/W: Located in Lane 74, Air Conditioner, Control Pattern Changer, Surround View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 30 in Digging Bucket Usage: 1,228 Hr Notes: The closing times of lots 568 thru 570 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:50 AM CDT Asset located in: Humble, TX, USA	574	2022 Sany SY225C9C5KL Tracked Excavator S/N: SY0221CCM8318 C/W: Located in Lane 74 Spot 0, Air Conditioner, Control Pattern Changer, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 1,432 Hr Notes: The closing times of lots 573 thru 576 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; ***Please see the attached warranty document below.*** Lot closing time: Wed, Sep 16, 11:51 AM CDT Asset located in: Humble, TX, USA
571	2022 Komatsu PC240LC-11 Tracked Excavator S/N: KMTPC252EMWA22624 C/W: Located in Lane 2 Spot 22, Air Conditioner, Control Pattern Changer, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft Stick, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket, Equipment-from-R-Construction Usage: 6,919 Hr Notes: From the Well Maintained Fleet of R Construction Lot closing time: Wed, Sep 16, 11:51 AM CDT Asset located in: Humble, TX, USA	575	2022 Sany SY225C LC Tracked Excavator S/N: SY0221CCM5608 C/W: Located in Lane 58 Spot 7, Air Conditioner, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 1,460 Hr Notes: The closing times of lots 573 thru 576 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; Lot closing time: Wed, Sep 16, 11:52 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
576	2022 Sany SY225C9C5KL Tracked Excavator S/N: SY0221CCM9578 C/W: Located in Lane 74 Spot 0, Air Conditioner, Control Pattern Changer, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 1,798 Hr Notes: The closing times of lots 573 thru 576 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; ***Please see the attached warranty document below.*** Lot closing time: Wed, Sep 16, 11:52 AM CDT Asset located in: Humble, TX, USA	580	2016 John Deere 210G LC Tracked Excavator S/N: 1FF210GXAGF524154 C/W: Located in Lane 61 Spot 31, 2015 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 11:53 AM CDT Asset located in: Lake Worth, TX, USA
576A	2016 Cat 325F LCR Tracked Excavator S/N: CAT0325FAXAA00416 C/W: Located in Lane 61 Spot 4, Air Conditioner, Rear View Camera, 9 ft 6 in Stick, 23.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: 8,477 Hr Lot closing time: Wed, Sep 16, 11:52 AM CDT Asset located in: Lake Worth, TX, USA	581	2012 John Deere 210GLC Tracked Excavator S/N: 1FF210GXECE520397 C/W: Located in Lane 60 Spot 5, Air Conditioner, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 47 in Digging Bucket, Thumb Bracket Usage: 13,064 Hr Lot closing time: Wed, Sep 16, 11:54 AM CDT Asset located in: Lake Worth, TX, USA
577	2020 John Deere 245G LC Tracked Excavator S/N: 1FF245GXJLF801668 C/W: Located in Lane 00 Spot 00, Air Conditioner, Rear View Camera, 2020 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 51 in Digging Bucket Usage: 7,142 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:52 AM CDT Asset located in: Lake Worth, TX, USA	582	2015 Hyundai 235LCR-9A Tracked Excavator S/N: HHKHZ613LF0000094 C/W: Located in Lane 3 Spot 7, Air Conditioner, Control Pattern Changer, 2014 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 30 in Digging Bucket Usage: 9,491 Hr Lot closing time: Wed, Sep 16, 11:54 AM CDT Asset located in: Humble, TX, USA
578	LiuGong CLG925E Tracked Excavator S/N: CLG925EZTLE004015 C/W: Located in Lane 61 Spot 18, Air Conditioner, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 29 in Digging Bucket Usage: 3,968 Hr Lot closing time: Wed, Sep 16, 11:53 AM CDT Asset located in: Lake Worth, TX, USA	583	2022 Link-Belt 210X4 Tracked Excavator S/N: LBX210Q7NNHEX2333 C/W: Located in Lane 2 Spot 11, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket, Hydraulic Thumb Usage: 3,654 Hr Lot closing time: Wed, Sep 16, 11:54 AM CDT Asset located in: Humble, TX, USA
579	2019 John Deere 210G Tracked Excavator S/N: 1FF210GXLKF527419 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 41 in Digging Bucket, Thumb Bracket Usage: 4,391 Hr Lot closing time: Wed, Sep 16, 11:53 AM CDT Asset located in: San Antonio, TX, USA	585	2022 Case CX210D Tracked Excavator S/N: DAC210K7NNS7H2709 C/W: Located in Lane 60 Spot 9, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket Usage: 3,547 Hr Notes: The closing times of lots 585 thru 586 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:55 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
586	2022 Case CX210D Tracked Excavator S/N: DAC210K7NNS7H2653 C/W: Located in Lane 60 Spot 12, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 4,058 Hr Notes: The closing times of lots 585 thru 586 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:55 AM CDT Asset located in: Lake Worth, TX, USA	590	2016 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257KFTC80065 C/W: Located in Lane 60 Spot 16, Air Conditioner, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 9,869 Hr Notes: The closing times of lots 589 thru 590 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 11:56 AM CDT Asset located in: Lake Worth, TX, USA
587	2022 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257HNTC81580 C/W: Located in Lane 2 Spot 25, Air Conditioner, Control Pattern Changer, Rear View Camera, Tier 4, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 3,130 Hr Notes: The closing times of lots 587 thru 588 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:55 AM CDT Asset located in: Humble, TX, USA	591	2022 Kobelco SK210LC Tracked Excavator S/N: YN17010465 C/W: Located in Lane 000 Spot 1, Air Conditioner, Tier 4, 2022 US EPA Label, 11 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 24 in Digging Bucket Usage: 1,185 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:57 AM CDT Asset located in: Lake Worth, TX, USA
588	2021 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257KMWA13262 C/W: Located in Lane 2 Spot 15, Air Conditioner, Control Pattern Changer, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 3,995 Hr Notes: The closing times of lots 587 thru 588 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:56 AM CDT Asset located in: Humble, TX, USA	593	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010338 C/W: Located in Lane 76, Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Manual Quick Coupler, 36 in Digging Bucket, Thumb Bracket Usage: 1,827 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:57 AM CDT Asset located in: Humble, TX, USA
588A	2017 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257CGC500452 C/W: Located in Lane 61 Spot 26, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 4 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket, Thumb Bracket Usage: 9,556 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Lot closing time: Wed, Sep 16, 11:56 AM CDT Asset located in: Lake Worth, TX, USA	595	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010317 C/W: Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket Usage: 169 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:58 AM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
597	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010604 C/W: Air Conditioner, Straight Travel Pedal, Surround View Cameras, Tier 4, US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 1,074 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:58 AM CDT Asset located in: Lake Worth, TX, USA	601	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010443 C/W: Air Conditioner, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket Usage: 1,762 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:00 PM CDT Asset located in: Midland, TX, USA
598	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010344 C/W: Located in Lane 2 Spot 12, Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket, Thumb Bracket Usage: 1,266 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:59 AM CDT Asset located in: Humble, TX, USA	602	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010400 C/W: Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Rock Guards, 36 in Digging Bucket Usage: 2,054 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:00 PM CDT Asset located in: Oklahoma City, OK, USA
599	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010427 C/W: Located in Lane 2 Spot 16, Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Manual Quick Coupler, 42 in Digging Bucket Usage: 1,316 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:59 AM CDT Asset located in: Humble, TX, USA	603	2021 Cat 320 Tracked Excavator S/N: CAT00320AMYK11355 C/W: Located in Lane 2 Spot 5, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 12:00 PM CDT Asset located in: Humble, TX, USA
600	2022 Kobelco SK210LC-11 Tracked Excavator S/N: YN17010242 C/W: Located in Lane 58 Spot 19, Air Conditioner, Tier 4, 2021 US EPA Label, 11 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket, Catwalks Usage: 1,375 Hr Notes: The closing times of lots 591 thru 602 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 11:59 AM CDT Asset located in: Lake Worth, TX, USA	605	2013 Cat 320E L Tracked Excavator S/N: CAT0320EEREE00460 C/W: Located in Lane 57 Spot 12, Air Conditioner, Straight Travel Pedal, Rear View Camera, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 12,522 Hr Lot closing time: Wed, Sep 16, 12:01 PM CDT Asset located in: Lake Worth, TX, USA
		605A	2010 Komatsu PC200LC-8 Tracked Excavator S/N: KMIPC180C54A89503 C/W: Located in Lane 61 Spot 25, 2010 US EPA Label, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 43 in Digging Bucket, Hydraulic Thumb Usage: 14,780 Hr Lot closing time: Wed, Sep 16, 12:01 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
606	2023 Volvo EC200EL Tracked Excavator S/N: VCEC200EL00315134 C/W: Air Conditioner, Rear & Side View Cameras, 2022 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 218 Hr Notes: The closing times of lots 606 thru 607 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:01 PM CDT Asset located in: Midland, TX, USA	611	2023 Cat 315 Tracked Excavator S/N: CAT00315LWKX21922 C/W: Located in Lane 58 Spot 14, Rear & Side View Cameras, 2022 US EPA Label, 9 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 19.5 in Triple Grouser Track Shoes w /Rubber Inserts, 42 in Digging Bucket, Thumb Bracket Usage: 2,640 Hr Notes: The closing times of lots 611 thru 612 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:03 PM CDT Asset located in: Lake Worth, TX, USA
607	2023 Volvo EC200EL Tracked Excavator S/N: VCEC200EA00315178 C/W: Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 971 Hr Notes: The closing times of lots 606 thru 607 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:01 PM CDT Asset located in: Midland, TX, USA	612	2022 Cat 315 Tracked Excavator S/N: CAT00315AWKX11647 C/W: Located in Lane 00 Spot 00, Air Conditioner, Rear & Side View Cameras, 9 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 19.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket, Thumb Bracket Usage: 6,013 Hr Notes: The closing times of lots 611 thru 612 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:03 PM CDT Asset located in: Lake Worth, TX, USA
608	2023 Volvo EC160EL Tracked Excavator S/N: VCEC160ET00314772 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket Usage: 1,504 Hr Lot closing time: Wed, Sep 16, 12:02 PM CDT Asset located in: Midland, TX, USA	613	2023 Sany SY155U Tracked Excavator S/N: SY015GCC10738 C/W: Located in Lane 76 Spot 0, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 23.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, Digging Bucket, Hydraulic Thumb Usage: 1,124 Hr Notes: The closing times of lots 613 thru 615 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:03 PM CDT Asset located in: Humble, TX, USA
609	2019 Hyundai HX160 L Tracked Excavator S/N: HHKHK502JK0000303 C/W: Located in Lane 61 Spot 23, Air Conditioner, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 37 in Digging Bucket Usage: 1,658 Hr Lot closing time: Wed, Sep 16, 12:02 PM CDT Asset located in: Lake Worth, TX, USA		
610	2012 Cat 316E L Tracked Excavator S/N: CAT0316EEDZW00450 C/W: Located in Lane 61 Spot 32, Air Conditioner, Straight Travel Pedal, 10 ft 4 in Stick, 27.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 11,062 Hr Lot closing time: Wed, Sep 16, 12:02 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
614	2022 Sany SY155U Tracked Excavator S/N: SY015GCC08918 C/W: Located in Lane 58 Spot 17, Air Conditioner, Control Pattern Changer, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 23.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 1,617 Hr Notes: The closing times of lots 613 thru 615 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ***Click on the link below for Seller Supplied Warranty Transfer Notice*** Lot closing time: Wed, Sep 16, 12:03 PM CDT Asset located in: Lake Worth, TX, USA	618	2022 Link-Belt 145X4 Tracked Excavator S/N: LBX145Q7NNHEX2611 C/W: Located in Lane 3 Spot 14, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 6 ft 11 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, 30 in Digging Bucket Usage: 4,148 Hr Notes: The closing times of lots 618 thru 620 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:05 PM CDT Asset located in: Humble, TX, USA
615	2022 Sany SY155U Tracked Excavator S/N: SY015GCC08928 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2021 US EPA Label, 8 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 23.5 in Triple Grouser Track Shoes, 30.5 in Digging Bucket, Thumb Bracket Usage: 2,562 Hr Notes: The closing times of lots 613 thru 615 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ***Please see warranty transfer document below.*** Lot closing time: Wed, Sep 16, 12:04 PM CDT Asset located in: Oklahoma City, OK, USA	619	2021 Link-Belt 145X4LC Tracked Excavator S/N: LBX145Q7NLHEX1820 C/W: Located in Lane 3 Spot 16, Air Conditioner, Control Pattern Changer, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 11 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,286 Hr Notes: The closing times of lots 618 thru 620 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:05 PM CDT Asset located in: Humble, TX, USA
616	2022 Kobelco SK140LC-7 Tracked Excavator S/N: YY09049503 C/W: Located in Lane 000 Spot 4, Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 2,117 Hr Lot closing time: Wed, Sep 16, 12:04 PM CDT Asset located in: Lake Worth, TX, USA	620	2021 Link-Belt 145X4LC Tracked Excavator S/N: LBX145Q7NLHEX1818 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 37 in Digging Bucket, Thumb Bracket, 20 in Rubber Pads Usage: 9,161 Hr Notes: The closing times of lots 618 thru 620 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:05 PM CDT Asset located in: Oklahoma City, OK, USA
617	2023 Volvo ECR145EL Tracked Excavator S/N: VCECR145L00316490 C/W: Located in Lane 59 Spot 20, Air Conditioner, Rear View Camera, Tier 4, 2022 US EPA Label, 2 Piece Boom, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 12:04 PM CDT Asset located in: Lake Worth, TX, USA	624	2021 Kobelco SK130LC-11 Tracked Excavator S/N: LP10030086 C/W: Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2020 US EPA Label, 9 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 23.75 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: Not Available Lot closing time: Wed, Sep 16, 12:06 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
625	2015 Cat 313F L GC Tracked Excavator S/N: CAT0313FFGJD00264 C/W: Located in Lane 3 Spot 5, Air Conditioner, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 28 in Triple Grouser Track Shoes, 42 in Digging Bucket, Manual Thumb Usage: 1,422 Hr Notes: Service Records See Documents Lot closing time: Wed, Sep 16, 12:07 PM CDT Asset located in: Humble, TX, USA	632	2018 Volvo ECR88D Tracked Excavator S/N: VCE00E88V00214077 C/W: Tier 4, 2018 US EPA Label, Swing Boom, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 1,418 Hr Notes: The closing times of lots 631 thru 632 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:09 PM CDT Asset located in: Lake Worth, TX, USA
627	2005 Cat 320C Tracked Excavator S/N: CAT0320CEGAA00675 C/W: Located in Lane 58 Spot 2, Air Conditioner, 9 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 42 in Digging Bucket, Thumb Bracket Usage: 4,195 Hr Lot closing time: Wed, Sep 16, 12:07 PM CDT Asset located in: Lake Worth, TX, USA	633	2022 Bobcat E88 Tracked Excavator S/N: B4NM11647 C/W: Located in Lane 59 Spot 18, Air Conditioner, Control Pattern Changer, 2022 US EPA Label, Swing Boom, 7 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, 35 in Digging Bucket, Thumb Bracket Usage: 1,330 Hr Lot closing time: Wed, Sep 16, 12:09 PM CDT Asset located in: Lake Worth, TX, USA
628	2006 Komatsu PC158USLC-2 Tracked Excavator S/N: KMTPC046J02010164 C/W: Located in Lane 58 Spot 7, Air Conditioner, 8 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, 37 in Digging Bucket, Thumb Bracket Usage: 6,541 Hr Lot closing time: Wed, Sep 16, 12:08 PM CDT Asset located in: Lake Worth, TX, USA	633A	2017 John Deere 85G Tracked Excavator S/N: 1FF085GXAGJ018787 C/W: Located in Lane 00 Spot 14, Air Conditioner, Straight Travel Pedal, 2022 US EPA Label, Swing Boom, 6 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Single Grouser Track Shoes w/Rubber Pads, 18 in Digging Bucket, Thumb Bracket Usage: 9,171 Hr Lot closing time: Wed, Sep 16, 12:09 PM CDT Asset located in: Lake Worth, TX, USA
629	2023 Volvo ECR88D Tracked Excavator S/N: VCE00E88H00219333 C/W: 2023 US EPA Label, 6 ft Stick, Backfill Blade, 18 in Rubber Tracks, 18 in Digging Bucket, Hydraulic Thumb Usage: 134 Hr Notes: The closing times of lots 629 thru 630 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:08 PM CDT Asset located in: Midland, TX, USA	634	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308EHFJX12690 C/W: Located in Lane 00 Spot 00, Rear View Camera, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Triple Grouser Track Shoes w/Rubber Pads, 24 in Digging Bucket, Hydraulic Thumb, Equipment-from-a-Primoris-Services-Corp-company Usage: 2,612 Hr Lot closing time: Wed, Sep 16, 12:09 PM CDT Asset located in: Lake Worth, TX, USA
631	2018 Volvo ECR88D Tracked Excavator S/N: VCE00E88C00214068 C/W: Located in Lane 3 Spot 13, 2018 US EPA Label, Swing Boom, 6 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Smooth Track Shoes w/Rubber Pads, Hydraulic Quick Coupler, 24 in Digging Bucket, Thumb Bracket Usage: 1,213 Hr Notes: The closing times of lots 631 thru 632 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:09 PM CDT Asset located in: Humble, TX, USA	635	2012 Cat 308 ECR Tracked Excavator S/N: CAT0308EKGBJ00590 C/W: Located in Lane 00 Spot 17, Air Conditioner, Tier 4, 2012 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Triple Grouser Track Shoes w/Rubber Pads, Thumb Bracket Usage: 7,064 Hr Lot closing time: Wed, Sep 16, 12:10 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
636	2022 Yanmar ViO80-1A Tracked Excavator S/N: YMRVIO80VNAJAJ074 C/W: Located in Lane 4 Spot 12, Air Conditioner, Control Pattern Changer, Rear View Camera, 2022 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 1,690 Hr Notes: The closing times of lots 636 thru 639 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:10 PM CDT Asset located in: Humble, TX, USA	640	2021 Yanmar ViO80-1A Tracked Excavator S/N: YMRVIO80LMAJAH598 C/W: Located in Lane 75 Spot 0, 2021 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Hydraulic Quick Coupler, 18 in Digging Bucket Usage: 1,774 Hr Lot closing time: Wed, Sep 16, 12:11 PM CDT Asset located in: Humble, TX, USA
637	2022 Yanmar ViO80-1A Tracked Excavator S/N: YMRVIO80PNAJAJ019 C/W: Located in Lane 00 Spot 00, 2021 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,785 Hr Notes: The closing times of lots 636 thru 639 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:10 PM CDT Asset located in: Lake Worth, TX, USA	642	2010 Komatsu PC78US-8 Tracked Excavator S/N: KMTPC213C01016259 C/W: Located in Lane 00 Spot 18, 2010 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Triple Grouser Track Shoes, 25 in Bucket Usage: 7,435 Hr Lot closing time: Wed, Sep 16, 12:12 PM CDT Asset located in: Lake Worth, TX, USA
638	2022 Yanmar ViO801A Tracked Excavator S/N: YMRVIO80HNAJAH975 C/W: Located in Lane 59 Spot 6, Air Conditioner, Control Pattern Changer, 2021 US EPA Label, Swing Boom, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 2,012 Hr Notes: The closing times of lots 636 thru 639 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:11 PM CDT Asset located in: Lake Worth, TX, USA	643	2004 Komatsu PC78US-6 Tracked Excavator S/N: 6881 C/W: Air Conditioner, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Track Shoes w/Rubber Pads, 28 in Digging Bucket Usage: Not Available Notes: Hours Shown Are Not Accurate Lot closing time: Wed, Sep 16, 12:12 PM CDT Asset located in: Lake Worth, TX, USA
639	2022 Yanmar ViO80-1A Tracked Excavator S/N: YMRVIO80ENAJAJ011 C/W: Located in Lane 59 Spot 19, 2021 US EPA Label, Swing Boom, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Thumb Bracket Usage: 2,123 Hr Notes: The closing times of lots 636 thru 639 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:11 PM CDT Asset located in: Lake Worth, TX, USA	643A	2019 Hitachi Zaxis ZX75US-5B Tracked Excavator S/N: HCMDEPA0L00074931 C/W: Located in Lane 4 Spot 4, Air Conditioner, Rear & Side View Cameras, 5 ft 4 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Pads, 30 in Digging Bucket Usage: 1,295 Hr Lot closing time: Wed, Sep 16, 12:12 PM CDT Asset located in: Humble, TX, USA
		644	2015 Terex TC75 Tracked Excavator S/N: TC07520537 C/W: Located in Lane 3 Spot 1, 2012 US EPA Label, Swing Boom, 6 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, 36 in Digging Bucket, Hydraulic Thumb Usage: 1,869 Hr Lot closing time: Wed, Sep 16, 12:12 PM CDT Asset located in: Humble, TX, USA
		645	2012 Cat 306 CR Tracked Excavator S/N: CAT00306AMXH01908 C/W: Located in Lane 00 Spot 00, Air Conditioner, 2010 US EPA Label, Swing Boom, 5 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Triple Grouser Track Shoes, Manual Quick Coupler, 29 in Digging Bucket Usage: 1,732 Hr Lot closing time: Wed, Sep 16, 12:13 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
646	2015 John Deere 60G Tracked Excavator S/N: 1FF060GXAMJ294046 C/W: Located in Lane 59 Spot 10, 2021 US EPA Label, Swing Boom, 6 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 30 in Digging Bucket, Thumb Bracket Usage: 4,704 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 12:13 PM CDT Asset located in: Lake Worth, TX, USA	652	2023 Volvo EC60E Mini Excavator S/N: VCEEC60EG00318502 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, Tier 4, 2023 US EPA Label, CARB Compliant, Swing Boom, 6 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, 18 in Digging Bucket, Hydraulic Thumb Usage: 423 Hr Notes: The closing times of lots 651 thru 652 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:15 PM CDT Asset located in: Oklahoma City, OK, USA
647	2011 Komatsu PC60-8 Tracked Excavator S/N: KMTPC238C38A10422 C/W: Located in Lane 00 Spot 00, Air Conditioner, 2011 US EPA Label, 5 ft 1 in Stick, 18 in Triple Grouser Track Shoes, 30 in Digging Bucket Usage: 1,219 Hr Lot closing time: Wed, Sep 16, 12:13 PM CDT Asset located in: Lake Worth, TX, USA	653	2022 Volvo EC60E Mini Excavator S/N: VCEEC60EC00316880 C/W: Located in Lane 000 Spot 000, Enclosed Cab, Air Conditioner, Tier 4, 2021 US EPA Label, Swing Boom, 5 ft 3 in Stick, Backfill Blade, 16 in Rubber Tracks, 18 in Digging Bucket, Hydraulic Thumb Usage: 605 Hr Lot closing time: Wed, Sep 16, 12:15 PM CDT Asset located in: Lake Worth, TX, USA
649	2021 Sunward SWF90UF Tracked Excavator S/N: SWF90UF00130 C/W: Located in Lane 3 Spot 2, Air Conditioner, 2020 US EPA Label, Swing Boom, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 121 Hr Lot closing time: Wed, Sep 16, 12:14 PM CDT Asset located in: Humble, TX, USA	655	2023 Volvo ECR58F Mini Excavator S/N: VCECR58FC00012534 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, Tier 4, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, 24 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:16 PM CDT Asset located in: Midland, TX, USA
650	2022 John Deere 60G Mini Excavator S/N: 1FF060GXANJ295147 C/W: Located in Lane 59 Spot 17, Enclosed Cab, Air Conditioner, Swing Boom, 72 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket, Hydraulic Thumb Usage: 613 Hr Lot closing time: Wed, Sep 16, 12:14 PM CDT Asset located in: Lake Worth, TX, USA	655A	2012 Volvo ECR58 Mini Excavator S/N: VCEOEC58100013383 C/W: Located in Lane 00 Spot 00, 2012 US EPA Label, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 24 in Digging Bucket, Thumb Bracket Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 12:16 PM CDT Asset located in: Lake Worth, TX, USA
651	2023 Volvo EC60E Mini Excavator S/N: VCEEC60ET00318503 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, Rear View Camera, Tier 4, 2023 US EPA Label, CARB Compliant, Swing Boom, 6 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb Usage: 417 Hr Notes: The closing times of lots 651 thru 652 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:15 PM CDT Asset located in: Oklahoma City, OK, USA	656	2018 Takeuchi TB260 Mini Excavator S/N: 126103434 C/W: Enclosed Cab, Air Conditioner, 2018 US EPA Label, Swing Boom, 5 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 17 in Digging Bucket, Thumb Bracket Usage: 1,683 Hr Lot closing time: Wed, Sep 16, 12:16 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
657	2024 Takeuchi TB240 Mini Excavator S/N: 124010174 C/W: Located in Lane 59 Spot 11, Enclosed Cab, Air Conditioner, 2024 US EPA Label, Swing Boom, 5 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 14 in Rubber Tracks, 19 in Digging Bucket, Thumb Bracket Usage: 708 Hr Lot closing time: Wed, Sep 16, 12:16 PM CDT Asset located in: Lake Worth, TX, USA	664	2017 Bobcat E50 Mini Excavator S/N: AJ1813503 C/W: 2016 US EPA Label, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Manual Quick Coupler, 19 in Digging Bucket, Thumb Bracket Usage: 3,210 Hr Lot closing time: Wed, Sep 16, 12:18 PM CDT Asset located in: Oklahoma City, OK, USA
658	2016 Hyundai 60CR-9A Mini Excavator S/N: HHKHML04AH0000699 C/W: Located in Lane 3 Spot 4, Enclosed Cab, Air Conditioner, 2016 US EPA Label, Swing Boom, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 26 in Digging Bucket Usage: 5,089 Hr Lot closing time: Wed, Sep 16, 12:17 PM CDT Asset located in: Humble, TX, USA	666	2020 John Deere 50G Mini Excavator S/N: 1FF050GXJKH291752 C/W: Located in Lane 59 Spot 58, Straight Travel Pedal, Control Pattern Changer, 2019 US EPA Label, Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.6 in Rubber Tracks, Manual Quick Coupler, 14.6 in Cleanup Bucket, Thumb Bracket Usage: 4,503 Hr Notes: The closing times of lots 665 thru 671 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:19 PM CDT Asset located in: Lake Worth, TX, USA
659	2011 Case CX58C Mini Excavator S/N: PS02-00282 C/W: Located in Lane 00 Spot 00, Enclosed Cab, Air Conditioner, 2011 US EPA Label, Swing Boom, 6 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Triple Grouser Track Shoes, Manual Quick Coupler, 28 in Digging Bucket, Hydraulic Thumb Usage: 1,321 Hr Lot closing time: Wed, Sep 16, 12:17 PM CDT Asset located in: Lake Worth, TX, USA	667	2020 John Deere 50G Mini Excavator S/N: 1FF050GXJLH292450 C/W: Located in Lane 59 Spot 55, Swing Boom, 5 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 18 in Digging Bucket, Thumb Bracket Usage: Not Available Notes: The closing times of lots 665 thru 671 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:19 PM CDT Asset located in: Lake Worth, TX, USA
660	2019 Cat 305.5E2 Mini Excavator S/N: CAT3055EAW210422 C/W: Located in Lane 59 Spot 19, Enclosed Cab, 2017 US EPA Label, 4 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Triple Grouser Track Shoes, Manual Quick Coupler, 29 in Digging Bucket, Hydraulic Thumb Usage: 866 Hr Lot closing time: Wed, Sep 16, 12:17 PM CDT Asset located in: Lake Worth, TX, USA	668	2020 John Deere 50G Mini Excavator S/N: 1FF050GXCLH292448 C/W: Located in Lane 59 Spot 28, Swing Boom, 5 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket, Thumb Bracket Usage: Not Available Notes: The closing times of lots 665 thru 671 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:20 PM CDT Asset located in: Lake Worth, TX, USA
662	2021 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55KMAJAJ109 C/W: Located in Lane 3, Control Pattern Changer, 2021 US EPA Label, Swing Boom, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,726 Hr Lot closing time: Wed, Sep 16, 12:18 PM CDT Asset located in: Humble, TX, USA		
663	2017 Yanmar ViO55-6A Mini Excavator S/N: YMRV1055EHAJAF424 C/W: Control Pattern Changer, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler Usage: 4,683 Hr Lot closing time: Wed, Sep 16, 12:18 PM CDT Asset located in: San Antonio, TX, USA		

Lot #	Details	Lot #	Details
669	2020 John Deere 50G Mini Excavator S/N: 1FF050GXKKH291751 C/W: Located in Lane 3 Spot 8, Control Pattern Changer, Swing Boom, 5 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket, Thumb Bracket Usage: 3,408 Hr Notes: The closing times of lots 665 thru 671 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:20 PM CDT Asset located in: Humble, TX, USA	681	2012 Kubota KX41-3V Mini Excavator S/N: 41564 C/W: Located in Lane 4 Spot 20, Control Pattern Changer, Tier 4, 2012 US EPA Label, Swing Boom, 3 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 1,412 Hr Lot closing time: Wed, Sep 16, 12:24 PM CDT Asset located in: Humble, TX, USA
673	2022 Bobcat E50 Mini Excavator S/N: B4GP14827 C/W: Located in Lane 4 Spot 8, 2021 US EPA Label, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Manual Quick Coupler, 24 in Cleanup Bucket, Hydraulic Thumb Usage: 2,117 Hr Notes: The closing times of lots 672 thru 680 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:21 PM CDT Asset located in: Humble, TX, USA	682	2008 Kubota KX41-3V Mini Excavator S/N: S32187 C/W: Located in Lane 4 Spot 21, Control Pattern Changer, Tier 4, 2008 US EPA Label, Swing Boom, 3 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: Not Available Lot closing time: Wed, Sep 16, 12:24 PM CDT Asset located in: Humble, TX, USA
675	2022 Bobcat E50 Mini Excavator S/N: B4GP14868 C/W: Located in Lane 3 Spot 11, 2021 US EPA Label, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Manual Quick Coupler, Hydraulic Thumb Usage: 1,408 Hr Notes: The closing times of lots 672 thru 680 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:22 PM CDT Asset located in: Humble, TX, USA	683	2016 Cat 304E2 Mini Excavator S/N: CAT0304EEME401371 C/W: Located in Lane 4 Spot 40, Control Pattern Changer, Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 14 in Rubber Tracks, Manual Quick Coupler, 18 in Cleanup Bucket, Thumb Bracket Usage: Not Available Lot closing time: Wed, Sep 16, 12:24 PM CDT Asset located in: Humble, TX, USA
677	2019 Bobcat E50 Mini Excavator S/N: AJ1816320 C/W: Located in Lane 0 Spot 0, Control Pattern Changer, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 24 in Digging Bucket, Hydraulic Thumb Usage: 3,370 Hr Notes: The closing times of lots 672 thru 680 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:22 PM CDT Asset located in: Humble, TX, USA	684	2012 Cat 304E CR Mini Excavator S/N: CAT0304EJTTN00483 C/W: Located in Lane 4 Spot 41, Control Pattern Changer, 2012 US EPA Label, Swing Boom, 3 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 14 in Rubber Tracks, 12 in Digging Bucket, Thumb Bracket Usage: 9 Hr Lot closing time: Wed, Sep 16, 12:24 PM CDT Asset located in: Humble, TX, USA
		685	2021 Volvo ECR40D Mini Excavator S/N: VCECR40DT00015321 C/W: Located in Lane 000 Spot 11, Tier 4, 2021 US EPA Label, Swing Boom, 4 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, 12 in Digging Bucket Usage: 264 Hr Lot closing time: Wed, Sep 16, 12:25 PM CDT Asset located in: Lake Worth, TX, USA
		687	2016 Kubota KX040-4 Mini Excavator S/N: JKUK0404K01H24961 C/W: Located in Lane 00 Spot 5, Control Pattern Changer, Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Tilt Blade, 13.6 in Rubber Tracks, Hydraulic Thumb Usage: 5,870 Hr Lot closing time: Wed, Sep 16, 12:25 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
688	2022 Kobelco SK35SR-6E Mini Excavator S/N: PX17043839 C/W: Located in Lane 75, Control Pattern Changer, 2022 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 18 in Digging Bucket, Thumb Bracket Usage: 69 Hr Notes: The closing times of lots 688 thru 693 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:26 PM CDT Asset located in: Humble, TX, USA	693	2022 Kobelco SK35SR-6E Mini Excavator S/N: PX17043747 C/W: Located in Lane 000 Spot 6, Tier 4, 2022 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 36 in Cleanup Bucket, Thumb Bracket Usage: 542 Hr Notes: The closing times of lots 688 thru 693 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:27 PM CDT Asset located in: Lake Worth, TX, USA
690	2022 Kobelco SK35SR-6E Mini Excavator S/N: PX17043577 C/W: Located in Lane 000 Spot 7, Swing Boom, 4 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: 172 Hr Notes: The closing times of lots 688 thru 693 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:26 PM CDT Asset located in: Lake Worth, TX, USA	694	2022 Bobcat E35i Mini Excavator S/N: B57912942 C/W: Located in Lane 61 Spot 4, Control Pattern Changer, 2022 US EPA Label, Swing Boom, 5 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 18 in Bucket, Hydraulic Thumb Usage: Not Available Notes: The closing times of lots 694 thru 695 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:27 PM CDT Asset located in: Lake Worth, TX, USA
691	2022 Kobelco SK35SR-6E Mini Excavator S/N: PX17043907 C/W: Located in Lane 4 Spot 10, Control Pattern Changer, 2022 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket, Thumb Bracket Usage: 262 Hr Notes: The closing times of lots 688 thru 693 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:27 PM CDT Asset located in: Humble, TX, USA	695	2022 Bobcat E35i Mini Excavator S/N: B57912947 C/W: Located in Lane 00 Spot 12, Control Pattern Changer, 2022 US EPA Label, Swing Boom, 5 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 12 in Digging Bucket, Hydraulic Thumb Usage: 1,478 Hr Notes: The closing times of lots 694 thru 695 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:28 PM CDT Asset located in: Lake Worth, TX, USA
692	2022 Kobelco SK35SR-6E Mini Excavator S/N: PX17043768 C/W: Located in Lane 75, Control Pattern Changer, Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 12 in Digging Bucket, Thumb Bracket Usage: 347 Hr Notes: The closing times of lots 688 thru 693 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:27 PM CDT Asset located in: Humble, TX, USA	696	2021 John Deere 35G Mini Excavator S/N: 1FF035GXHLK291232 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, 2020 US EPA Label, Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 1,971 Hr Notes: The closing times of lots 696 thru 701 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:28 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
697	2020 John Deere 35G Mini Excavator S/N: 1FF035GXALK289476 C/W: Located in Lane 59 Spot 48, Control Pattern Changer, 2020 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.6 in Rubber Tracks, Manual Quick Coupler, 12 in Cleanup Bucket, Thumb Bracket Usage: 2,703 Hr Notes: The closing times of lots 696 thru 701 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:28 PM CDT Asset located in: Lake Worth, TX, USA	702	2018 John Deere 35G Mini Excavator S/N: 1FF035GXLJK282352 C/W: Located in Lane 59 Spot 25, Swing Boom, 5 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Wed, Sep 16, 12:30 PM CDT Asset located in: Lake Worth, TX, USA
698	2020 John Deere 35G Mini Excavator S/N: 1FF035GXTLK289565 C/W: Located in Lane 59 Spot 31, Control Pattern Changer, 2020 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 12 in Cleanup Bucket, Thumb Bracket Usage: 2,838 Hr Notes: The closing times of lots 696 thru 701 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:29 PM CDT Asset located in: Lake Worth, TX, USA	703	2017 John Deere 35G Mini Excavator S/N: 1FF035GXHHK280175 C/W: Located in Lane 00 Spot 8, 2017 US EPA Label, Swing Boom, 4 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.6 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket, Thumb Bracket Usage: 864 Hr Lot closing time: Wed, Sep 16, 12:30 PM CDT Asset located in: Lake Worth, TX, USA
699	2019 John Deere 35G Mini Excavator S/N: 1FF035GXCKK287757 C/W: Located in Lane 4 Spot 3, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 3,336 Hr Notes: The closing times of lots 696 thru 701 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:29 PM CDT Asset located in: Humble, TX, USA	705	2022 Volvo EC35D Mini Excavator S/N: VCE0C35DT00014421 C/W: Located in Lane 4 Spot 5, Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket, Thumb Bracket Usage: 415 Hr Notes: The closing times of lots 704 thru 708 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:31 PM CDT Asset located in: Humble, TX, USA
700	2019 John Deere 35G Mini Excavator S/N: 1FF035GXJJK284029 C/W: Located in Lane 4 Spot 2, Control Pattern Changer, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket, Thumb Bracket Usage: 401 Hr Notes: The closing times of lots 696 thru 701 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:29 PM CDT Asset located in: Humble, TX, USA	706	2022 Volvo EC35D Mini Excavator S/N: VCE0C35DL00014428 C/W: Tier 4, 2021 US EPA Label, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: 788 Hr Notes: The closing times of lots 704 thru 708 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:31 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
707	2021 Volvo EC35D Mini Excavator S/N: VCE0C35DC00014417 C/W: Located in Lane 4 Spot 13, Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 16 in Digging Bucket, Thumb Bracket Usage: 347 Hr Notes: The closing times of lots 704 thru 708 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:31 PM CDT Asset located in: Humble, TX, USA	712	2015 Kubota KX71-3S Mini Excavator S/N: JKUK0713H01H20683 C/W: Located in Lane 4 Spot 6, Control Pattern Changer, 2014 US EPA Label, Swing Boom, 4 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 12 in Bucket, Thumb Bracket Usage: 1,088 Hr Notes: The closing times of lots 712 thru 713 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:33 PM CDT Asset located in: Humble, TX, USA
708	2021 Volvo EC35D Mini Excavator S/N: VCE0C35DE00014397 C/W: Located in Lane 000 Spot 12, Tier 4, 2021 US EPA Label, Swing Boom, 7 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, 16 in Digging Bucket Usage: 590 Hr Notes: The closing times of lots 704 thru 708 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:32 PM CDT Asset located in: Lake Worth, TX, USA	713	2014 Kubota KX71-3S Mini Excavator S/N: KBCCZ350CCL3L24653 C/W: Located in Lane 00 Spot 6, Tier 4, 2020 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.6 in Rubber Tracks, Manual Quick Coupler, 13 in Digging Bucket, Thumb Bracket Usage: 3,697 Hr Notes: The closing times of lots 712 thru 713 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:33 PM CDT Asset located in: Lake Worth, TX, USA
709	2021 Yanmar ViO35-6A Mini Excavator S/N: YMRVIO35JMAJAN780 C/W: Located in Lane 00 Spot 15, Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 1,403 Hr Lot closing time: Wed, Sep 16, 12:32 PM CDT Asset located in: Lake Worth, TX, USA	715	2019 Cat 303.5E2CR Mini Excavator S/N: CAT3035EPJWY04718 C/W: Located in Lane 59 Spot 8, 2018 US EPA Label, Swing Boom, 5 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 11.75 in Rubber Tracks, 12 in Digging Bucket, Thumb Bracket, Equipment-from-a-Primoris-Services-Corp-company Usage: 3,422 Hr Notes: The closing times of lots 715 thru 716 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:34 PM CDT Asset located in: Lake Worth, TX, USA
711	2019 Kubota KX71-3S Mini Excavator S/N: JKUK0713C01H23490 C/W: Located in Lane 00 Spot 9, Tier 4, 2019 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 19 in Digging Bucket, Thumb Bracket Usage: 483 Hr Lot closing time: Wed, Sep 16, 12:33 PM CDT Asset located in: Lake Worth, TX, USA	716	2019 Cat 303.5E2 CR Mini Excavator S/N: CAT3035ETJWY05589 C/W: Located in Lane 00 Spot 13, 2019 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 11.5 in Digging Bucket, Thumb Bracket, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Notes: The closing times of lots 715 thru 716 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:34 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
720	2019 Bobcat E32i Mini Excavator S/N: B3Y113167 C/W: Located in Lane 4 Spot 15, 4 ft 5 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:35 PM CDT Asset located in: Humble, TX, USA	727	2022 Cat 302CR Mini Excavator S/N: CAT00302TRHM04706 C/W: Located in Lane 00 Spot 11, Straight Travel Pedal, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9.5 in Rubber Tracks, Expandable Width Tracks, 11 in Digging Bucket, Thumb Bracket Usage: 2,331 Hr Notes: The closing times of lots 727 thru 728 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:37 PM CDT Asset located in: Lake Worth, TX, USA
722	2017 IHI 85V4 Mini Excavator S/N: WK020075 C/W: Located in Lane 3 Spot 3, Enclosed Cab, Air Conditioner, Control Pattern Changer, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, 24 in Digging Bucket Usage: 1,890 Hr Lot closing time: Wed, Sep 16, 12:36 PM CDT Asset located in: Humble, TX, USA	728	2022 Cat 302CR Mini Excavator S/N: CAT00302ERHM04699 C/W: Located in Lane 00 Spot 10, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9.6 in Rubber Tracks, Expandable Width Tracks, 11 in Digging Bucket, Thumb Bracket Usage: 2,089 Hr Notes: The closing times of lots 727 thru 728 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:38 PM CDT Asset located in: Lake Worth, TX, USA
723	IHI 35NX Mini Excavator S/N: WF000979 C/W: Located in Lane 4 Spot 7, Control Pattern Changer, Swing Boom, 4 ft 7 in Stick, Backfill Blade, 12 in Rubber Tracks, 12 in Bucket Usage: 7,206 Hr Lot closing time: Wed, Sep 16, 12:36 PM CDT Asset located in: Humble, TX, USA	729	2022 Takeuchi TB20e Electric Mini Excavator S/N: 120000122 C/W: Located in Lane 3 Spot 17, 3 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 8 in Digging Bucket Usage: 408 Hr Lot closing time: Wed, Sep 16, 12:38 PM CDT Asset located in: Humble, TX, USA
724	2023 John Deere 26G Mini Excavator S/N: 1FF026GXVKNK268883 C/W: Located in Lane 4 Spot 0, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 495 Hr Lot closing time: Wed, Sep 16, 12:36 PM CDT Asset located in: Humble, TX, USA	730	2022 Takeuchi TB20e Electric Mini Excavator S/N: 120000097 C/W: Located in Lane 76 Spot 0, 3 ft 8 in Stick, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 533 Hr Lot closing time: Wed, Sep 16, 12:38 PM CDT Asset located in: Humble, TX, USA
724A	2021 Bobcat E26 Mini Excavator S/N: B4S913147 C/W: Located in Lane 48 Spot 0, Tier 4, 2020 US EPA Label, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 1,551 Hr Lot closing time: Wed, Sep 16, 12:37 PM CDT Asset located in: Humble, TX, USA	731	2021 John Deere 17G Mini Excavator S/N: 1FF017GXLLK230401 C/W: Located in Lane 4 Spot 9, Control Pattern Changer, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Digging Bucket, Thumb Bracket Usage: 1,642 Hr Lot closing time: Wed, Sep 16, 12:39 PM CDT Asset located in: Humble, TX, USA
725	2014 Bobcat E26 Mini Excavator S/N: B33212364 C/W: Located in Lane 59 Spot 5, Tier 4, 2014 US EPA Label, Swing Boom, 3 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 15 in Digging Bucket Usage: 1,999 Hr Lot closing time: Wed, Sep 16, 12:37 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
732	2021 Kubota U17 Mini Excavator S/N: KBCAZ24CLM3E53049 C/W: Located in Lane 4 Spot 18, Control Pattern Changer, 2021 US EPA Label, 2 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, 16 in Digging Bucket Usage: 757 Hr Notes: The closing times of lots 732 thru 736 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:39 PM CDT Asset located in: Humble, TX, USA	737	2023 Kobelco SK17SR-6E Mini Excavator S/N: PU12-01346 C/W: Located in Lane 00 Spot 7, 2022 US EPA Label, Swing Boom, 3 ft 2 in Stick, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 612 Hr Lot closing time: Wed, Sep 16, 12:40 PM CDT Asset located in: Lake Worth, TX, USA
733	2021 Kubota U17 Mini Excavator S/N: KBCAZ24CTM3F53285 C/W: Located in Lane 76 Spot 0, Control Pattern Changer, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 18 in Digging Bucket Usage: 1,000 Hr Notes: The closing times of lots 732 thru 736 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:39 PM CDT Asset located in: Humble, TX, USA	738	2023 Volvo EC27D Mini Excavator S/N: VCE0C27DJ00028735 C/W: Control Pattern Changer, Tier 4, 2023 US EPA Label, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 12 in Digging Bucket Usage: 118 Hr Notes: The closing times of lots 738 thru 742 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:41 PM CDT Asset located in: Midland, TX, USA
735	2019 Kubota U17 Mini Excavator S/N: JKUU0173P01H47319 C/W: Located in Lane 4 Spot 17, Control Pattern Changer, 2018 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 10 in Digging Bucket, Equipment-from-a-Primoris-Services-Corp-company Usage: 1,728 Hr Notes: The closing times of lots 732 thru 736 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:40 PM CDT Asset located in: Humble, TX, USA	739	2023 Volvo EC27D Mini Excavator S/N: VCE0C27DA00028772 C/W: Control Pattern Changer, Tier 4, 2023 US EPA Label, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 12 in Digging Bucket Usage: 136 Hr Notes: The closing times of lots 738 thru 742 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:41 PM CDT Asset located in: Midland, TX, USA
736	2018 Kubota U17 Mini Excavator S/N: 46685 C/W: Located in Lane 4 Spot 19, Control Pattern Changer, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 18 in Digging Bucket Usage: 1,702 Hr Notes: The closing times of lots 732 thru 736 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:40 PM CDT Asset located in: Humble, TX, USA	740	2022 Volvo EC27D Mini Excavator S/N: VCE0C27DC00028266 C/W: Control Pattern Changer, Tier 4, 2021 US EPA Label, CARB Compliant, Swing Boom, 3 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 10 in Rubber Tracks, 12 in Digging Bucket Usage: 228 Hr Notes: The closing times of lots 738 thru 742 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:41 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
741	2022 Volvo EC27D Mini Excavator S/N: VCE0C27DJ00028234 C/W: Control Pattern Changer, Tier 4, 2021 US EPA Label, CARB Compliant, Swing Boom, 3 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 10 in Rubber Tracks, 12 in Digging Bucket Usage: 245 Hr Notes: The closing times of lots 738 thru 742 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:42 PM CDT Asset located in: Oklahoma City, OK, USA	745	2023 Volvo ECR18E Mini Excavator S/N: VCECR18EA00030180 C/W: Control Pattern Changer, Tier 4, 2023 US EPA Label, CARB Compliant, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 39 Hr Notes: The closing times of lots 745 thru 748 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:43 PM CDT Asset located in: Oklahoma City, OK, USA
742	2021 Volvo EC27D Mini Excavator S/N: VCE0C27DV00028091 C/W: Control Pattern Changer, Tier 4, 2021 US EPA Label, CARB Compliant, Swing Boom, 3 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 10 in Rubber Tracks, 23.5 in Digging Bucket Usage: 107 Hr Notes: The closing times of lots 738 thru 742 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:42 PM CDT Asset located in: Oklahoma City, OK, USA	746	2023 Volvo ECR18E Mini Excavator S/N: VCECR18EK00030013 C/W: Control Pattern Changer, Swing Boom, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 105 Hr Notes: The closing times of lots 745 thru 748 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:43 PM CDT Asset located in: Midland, TX, USA
743	2023 Volvo EC20E Mini Excavator S/N: VCE0C20EC00021417 C/W: Control Pattern Changer, Swing Boom, 4 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 47 Hr Notes: The closing times of lots 743 thru 744 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:42 PM CDT Asset located in: Midland, TX, USA	747	2021 Volvo ECR18E Mini Excavator S/N: VCECR18EE00029454 C/W: Located in Lane 76, Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 8 in Digging Bucket Usage: Not Available Notes: The closing times of lots 745 thru 748 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:43 PM CDT Asset located in: Humble, TX, USA
744	2022 Volvo EC20E Mini Excavator S/N: VCE0C20EC00020809 C/W: Tier 4, 2021 US EPA Label, Swing Boom, 3 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, 11.5 in Digging Bucket Usage: 168 Hr Notes: The closing times of lots 743 thru 744 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:42 PM CDT Asset located in: Oklahoma City, OK, USA	748	2021 Volvo ECR18E Mini Excavator S/N: VCECR18EP00029264 C/W: Control Pattern Changer, Tier 4, 2021 US EPA Label, CARB Compliant, Swing Boom, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Cleanup Bucket Usage: 465 Hr Notes: The closing times of lots 745 thru 748 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Lot closing time: Wed, Sep 16, 12:44 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
749	2019 Yanmar SV08 Mini Excavator S/N: YMRSV08YJKB423 C/W: 2019 US EPA Label, Swing Boom, 2 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12.5 in Digging Bucket Usage: 552 Hr Lot closing time: Wed, Sep 16, 12:44 PM CDT Asset located in: Livingston, LA, USA	756	2026 CFG MX20R Mini Excavator (Unused) S/N: MX20R2026X1000400 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:46 PM CDT Asset located in: Midland, TX, USA
751	2020 Kubota K008-3 Mini Excavator S/N: 43545 C/W: Swing Boom, 2 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 11.5 in Digging Bucket Usage: 1,203 Hr Lot closing time: Wed, Sep 16, 12:45 PM CDT Asset located in: Oklahoma City, OK, USA	757	2026 CFG MX20R Mini Excavator (Unused) S/N: MX20R2026X1000446 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:46 PM CDT Asset located in: Oklahoma City, OK, USA
752	2019 Kubota K008 Mini Excavator S/N: 43077 C/W: Located in Lane 4 Spot 0, Control Pattern Changer, Swing Boom, 3 ft Stick, Backfill Blade, 7 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 1,066 Hr Lot closing time: Wed, Sep 16, 12:45 PM CDT Asset located in: Humble, TX, USA	758	2026 CFG MX20R Mini Excavator (Unused) S/N: MX20R2026X1000407 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:47 PM CDT Asset located in: Midland, TX, USA
753	2026 ZT ZT35G Mini Excavator (Unused) S/N: 000031 C/W: Located in Lane 59 Spot 57, Enclosed Cab, Air Conditioner, 2026 US EPA Label, Swing Boom, 4 ft 9 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 12 in Rubber Tracks, 22 in Digging Bucket, Thumb Bracket, Tool Box, Strobe Light Usage: Not Available Lot closing time: Wed, Sep 16, 12:45 PM CDT Asset located in: Lake Worth, TX, USA	759	2026 CFG MX20R Mini Excavator (Unused) S/N: MX20R2026X1000367 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:47 PM CDT Asset located in: Oklahoma City, OK, USA
754	2026 SDEE22-RED Mini Excavator (Unused) S/N: 55643 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:45 PM CDT Asset located in: Lake Worth, TX, USA	760	2026 CFG NT20Z Mini Excavator (Unused) S/N: NT20Z2026J0720153 C/W: 2026 US EPA Label, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:47 PM CDT Asset located in: Oklahoma City, OK, USA
755	2026 SDEE22-RED Mini Excavator (Unused) S/N: 55927 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:46 PM CDT Asset located in: Lake Worth, TX, USA	761	2026 CFG QK20R Mini Excavator (Unused) S/N: QK20R260716000403 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:48 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
762	2026 CFG QK20R Mini Excavator (Unused) S/N: QK20R260714000394 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:48 PM CDT Asset located in: Oklahoma City, OK, USA	768	2026 VICSEC VC20P Mini Excavator (Unused) S/N: 20K260715 C/W: Located in Lane 56, 2025 US EPA Label, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:50 PM CDT Asset located in: Lake Worth, TX, USA
763	2026 CFG QK20R Mini Excavator (Unused) S/N: QK20R260716000420 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:48 PM CDT Asset located in: Midland, TX, USA	770	2026 CFG QK20R Mini Excavator (Unused) S/N: QK20R260620000222 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:50 PM CDT Asset located in: Humble, TX, USA
764	2026 CFG QK20R Mini Excavator (Unused) S/N: QK20R260716000413 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:48 PM CDT Asset located in: Midland, TX, USA	771	2026 VICSEC VC20P Mini Excavator (Unused) S/N: 20K2506317 C/W: Located in Lane 46 Spot 0, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16.5 in Digging Bucket, Thumb Bracket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:51 PM CDT Asset located in: Humble, TX, USA
765	2026 CFG XZ20R Mini Excavator (Unused) S/N: XZ20R202607170620 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:49 PM CDT Asset located in: Oklahoma City, OK, USA	772	2026 VICSEC 30P Mini Excavator (Unused) S/N: 30PK260305 C/W: Located in Lane 49 Spot 0, Swing Boom, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, 20 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:51 PM CDT Asset located in: Humble, TX, USA
766	2026 CFG XZ20R Mini Excavator (Unused) S/N: XZ20R202607170616 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:49 PM CDT Asset located in: Midland, TX, USA	773	2026 CFG XZ20R Mini Excavator (Unused) S/N: XZ20R202606240431 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:51 PM CDT Asset located in: Humble, TX, USA
767	2026 VICSEC VC20P Mini Excavator (Unused) S/N: 20K260716 C/W: Located in Lane 56, 2025 US EPA Label, 2 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:49 PM CDT Asset located in: Lake Worth, TX, USA	774	2026 CFG XZ20R Mini Excavator (Unused) S/N: XZ20R202606250465 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:51 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
775	2026 CFG XZ20R Mini Excavator (Unused) S/N: XZ20R202606260471 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:52 PM CDT Asset located in: Lake Worth, TX, USA	781	2026 CFG QK20R Mini Excavator (Unused) S/N: QK20R260611000169 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:54 PM CDT Asset located in: Livingston, LA, USA
776	2026 CFG XZ20R Mini Excavator (Unused) S/N: XZ20R202606240436 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:52 PM CDT Asset located in: Humble, TX, USA	782	2026 CFG QK20R Mini Excavator (Unused) S/N: QK20R260613000186 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:54 PM CDT Asset located in: Livingston, LA, USA
777	2026 CFG XZ20R Mini Excavator (Unused) S/N: XZ20R202606100337 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:52 PM CDT Asset located in: Livingston, LA, USA	783	2026 CFG NT20Z Mini Excavator (Unused) S/N: NT20Z2026J0626056 C/W: Located in Lane 56, 2026 US EPA Label, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:54 PM CDT Asset located in: Lake Worth, TX, USA
778	2026 CFG MX20R Mini Excavator (Unused) S/N: MX20R2026X1000276 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:53 PM CDT Asset located in: Humble, TX, USA	784	2026 CFG NT20Z Mini Excavator (Unused) S/N: NT20Z2026J0626055 C/W: Located in Lane 56, 2026 US EPA Label, 3 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:54 PM CDT Asset located in: Lake Worth, TX, USA
779	2026 CFG MX20R Mini Excavator (Unused) S/N: MX20R2026X1000294 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:53 PM CDT Asset located in: Humble, TX, USA	785	2026 CFG NT20Z Mini Excavator (Unused) S/N: NT20Z2026S0620002 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: 15 Hr Lot closing time: Wed, Sep 16, 12:55 PM CDT Asset located in: Humble, TX, USA
780	2026 CFG MX20R Mini Excavator (Unused) S/N: MX20R2026X1000106 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:53 PM CDT Asset located in: Livingston, LA, USA	786	2026 CFG NT20Z Mini Excavator (Unused) S/N: NT20Z2026S0620030 C/W: Located in Lane 56, 2026 US EPA Label, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:55 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
787	2026 ME20-RED Mini Excavator (Unused) S/N: 56582 C/W: Located in Lane 56 Spot 0, Swing Boom, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:55 PM CDT Asset located in: Humble, TX, USA	793	2026 ME20-YELLOW Mini Excavator (Unused) S/N: 56122 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:57 PM CDT Asset located in: Lake Worth, TX, USA
788	2026 ME20-RED Mini Excavator (Unused) S/N: 56581 C/W: Located in Lane 56 Spot 0, Swing Boom, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:56 PM CDT Asset located in: Humble, TX, USA	794	2026 ME20-YELLOW Mini Excavator (Unused) S/N: 56130 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:57 PM CDT Asset located in: Lake Worth, TX, USA
789	2026 ME20-RED Mini Excavator (Unused) S/N: 56319 C/W: Located in Lane 56 Spot 0, Swing Boom, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:56 PM CDT Asset located in: Humble, TX, USA	795	2026 ME20-YELLOW Mini Excavator (Unused) S/N: 06345A C/W: Located in Lane 56, 2026 US EPA Label, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:58 PM CDT Asset located in: Lake Worth, TX, USA
790	2026 ME20-RED Mini Excavator (Unused) S/N: 55492A C/W: Located in Lane 56 Spot 0, Swing Boom, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:56 PM CDT Asset located in: Humble, TX, USA	796	2026 ME20-YELLOW Mini Excavator (Unused) S/N: 06238A C/W: Located in Lane 56, 2026 US EPA Label, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:58 PM CDT Asset located in: Lake Worth, TX, USA
791	2026 LE20 Mini Excavator (Unused) S/N: 57640 C/W: Located in Lane 56 Spot 0, Swing Boom, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:57 PM CDT Asset located in: Humble, TX, USA	797	2026 ME20-YELLOW Mini Excavator (Unused) S/N: 06350A C/W: Located in Lane 56, 2026 US EPA Label, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:58 PM CDT Asset located in: Lake Worth, TX, USA
792	2026 LE20 Yanmar Diesel Mini Excavator (Unused) S/N: 57674 C/W: Located in Lane 56 Spot 0, Swing Boom, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:57 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
798	2026 ME20-YELLOW Mini Excavator (Unused) S/N: 06275A C/W: Located in Lane 56, 2026 US EPA Label, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:59 PM CDT Asset located in: Lake Worth, TX, USA	804	2026 CFG QK18R Mini Excavator (Unused) S/N: QK18R202606180167 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:00 PM CDT Asset located in: Lake Worth, TX, USA
799	2026 CFG QK18R Mini Excavator (Unused) S/N: QK18R202606290190 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 12:59 PM CDT Asset located in: Midland, TX, USA	805	2026 ATS ATS-ME18 Mini Excavator (Unused) S/N: 2605072421SH C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:01 PM CDT Asset located in: Lake Worth, TX, USA
800	2026 ATS POWER ATS-ME18-Z Mini Excavator (Unused) S/N: 2606254A0110SH C/W: Located in Lane 56, 2026 US EPA Label, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 12:59 PM CDT Asset located in: Humble, TX, USA	806	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260716W0196 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:01 PM CDT Asset located in: Oklahoma City, OK, USA
801	2026 ATS POWER ATS-ME18-Z Mini Excavator (Unused) S/N: 2606254A0619SH C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:00 PM CDT Asset located in: Humble, TX, USA	807	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260716W0197 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:01 PM CDT Asset located in: Oklahoma City, OK, USA
802	2026 ATS POWER ATS-ME18-Z Mini Excavator (Unused) S/N: 2606254A0131SH C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:00 PM CDT Asset located in: Humble, TX, USA	808	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260716W0199 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:02 PM CDT Asset located in: Midland, TX, USA
803	2026 CFG QK18R Mini Excavator (Unused) S/N: QK18R202606250177 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:00 PM CDT Asset located in: Lake Worth, TX, USA	809	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260716W0198 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:02 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
810	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260703W115 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:02 PM CDT Asset located in: Midland, TX, USA	816	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260610W138 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:04 PM CDT Asset located in: Humble, TX, USA
811	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260716W201 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:03 PM CDT Asset located in: Midland, TX, USA	819	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260610W099 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:05 PM CDT Asset located in: Humble, TX, USA
812	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260716W200 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:03 PM CDT Asset located in: Oklahoma City, OK, USA	822	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260610W098 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:06 PM CDT Asset located in: Humble, TX, USA
813	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260716W199 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:03 PM CDT Asset located in: Oklahoma City, OK, USA	823	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260610W137 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:06 PM CDT Asset located in: Humble, TX, USA
814	2026 CFG QK16R Mini Excavator (Unused) S/N: QK16R202606250770 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:03 PM CDT Asset located in: Lake Worth, TX, USA	824	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260610W0128 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:06 PM CDT Asset located in: Humble, TX, USA
815	2026 CFG QK16R Mini Excavator (Unused) S/N: QK16R202606200760 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 223 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:04 PM CDT Asset located in: Humble, TX, USA	826	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260610W0157 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:07 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
827	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260610W0127 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:07 PM CDT Asset located in: Humble, TX, USA	835	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260610W004 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:10 PM CDT Asset located in: Livingston, LA, USA
829	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260610W0158 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: 1 Hr Lot closing time: Wed, Sep 16, 01:08 PM CDT Asset located in: Humble, TX, USA	836	2026 ME15 Mini Excavator (Unused) S/N: 2605096996 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:10 PM CDT Asset located in: Lake Worth, TX, USA
830	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260610W0178 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:08 PM CDT Asset located in: Lake Worth, TX, USA	837	2026 ME15 Mini Excavator (Unused) S/N: 2605097246 C/W: Located in Lane 56, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:10 PM CDT Asset located in: Lake Worth, TX, USA
832	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260610W0027 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:09 PM CDT Asset located in: Livingston, LA, USA	838	2026 ME15 Mini Excavator (Unused) S/N: 2605097391 C/W: Located in Lane 56, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:11 PM CDT Asset located in: Lake Worth, TX, USA
833	2026 CFG H16R Mini Excavator (Unused) S/N: H16R20260416W0185 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:09 PM CDT Asset located in: Livingston, LA, USA	839	2026 ME15 Mini Excavator (Unused) S/N: 2602113075 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:11 PM CDT Asset located in: Lake Worth, TX, USA
834	2026 CFG KV16R Mini Excavator (Unused) S/N: KV16R20260601W077 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:09 PM CDT Asset located in: Livingston, LA, USA	840	2026 ME15 Mini Excavator (Unused) S/N: 2602113066 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:11 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
841	2026 ME15 Mini Excavator (Unused) S/N: 2602113086 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:12 PM CDT Asset located in: Lake Worth, TX, USA	846	2026 ME15 Mini Excavator (Unused) S/N: 2605250472 C/W: Located in Lane 56 Spot 0, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:13 PM CDT Asset located in: Humble, TX, USA
842	2026 ME15 Mini Excavator (Unused) S/N: 2602113092 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:12 PM CDT Asset located in: Lake Worth, TX, USA	847	2026 ME15 Mini Excavator (Unused) S/N: 2606058584 C/W: Located in Lane 56 Spot 0, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:13 PM CDT Asset located in: Humble, TX, USA
843	2026 ME15 Mini Excavator (Unused) S/N: 2602113085 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:12 PM CDT Asset located in: Lake Worth, TX, USA	848	2026 SDLANCH ME15 Mini Excavator (Unused) S/N: 2604280531 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 6 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:14 PM CDT Asset located in: Humble, TX, USA
844	2026 ME15 Mini Excavator (Unused) S/N: 2512393360 C/W: Located in Lane 56, 2026 US EPA Label, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:12 PM CDT Asset located in: Lake Worth, TX, USA	849	2026 SDLANCH ME15 Mini Excavator (Unused) S/N: 2602013276 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 6 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:14 PM CDT Asset located in: Humble, TX, USA
845	2026 ME15 Mini Excavator (Unused) S/N: 2605197587 C/W: Located in Lane 56 Spot 0, 2 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:13 PM CDT Asset located in: Humble, TX, USA	850	2026 SDLANCH ME15 Mini Excavator (Unused) S/N: 2604280520 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 6 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:14 PM CDT Asset located in: Humble, TX, USA
		851	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30714510 C/W: Enclosed Cab, 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:15 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
852	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106230299 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:15 PM CDT Asset located in: Midland, TX, USA	859	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20716555 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:17 PM CDT Asset located in: Oklahoma City, OK, USA
853	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A107160575 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:15 PM CDT Asset located in: Oklahoma City, OK, USA	860	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20716557 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:17 PM CDT Asset located in: Oklahoma City, OK, USA
854	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A107160587 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:15 PM CDT Asset located in: Oklahoma City, OK, USA	861	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20604024 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:18 PM CDT Asset located in: Livingston, LA, USA
855	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106060074 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:16 PM CDT Asset located in: Livingston, LA, USA	862	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20611152 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:18 PM CDT Asset located in: Livingston, LA, USA
856	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106060072 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:16 PM CDT Asset located in: Livingston, LA, USA	863	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106180223 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:18 PM CDT Asset located in: Humble, TX, USA
857	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20718577 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:16 PM CDT Asset located in: Midland, TX, USA	865	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106230294 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:19 PM CDT Asset located in: Humble, TX, USA
858	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20420036 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:17 PM CDT Asset located in: Midland, TX, USA		

Lot #	Details	Lot #	Details
868	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106180222 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:20 PM CDT Asset located in: Humble, TX, USA	877	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30618240 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:22 PM CDT Asset located in: Lake Worth, TX, USA
869	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106180252 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:20 PM CDT Asset located in: Lake Worth, TX, USA	878	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30622266 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:23 PM CDT Asset located in: Humble, TX, USA
870	2026 CFG KT13R Mini Excavator (Unused) S/N: KT13R26A106230297 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:20 PM CDT Asset located in: Humble, TX, USA	880	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20622276 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:23 PM CDT Asset located in: Lake Worth, TX, USA
871	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30609132 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:21 PM CDT Asset located in: Humble, TX, USA	881	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20618240 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:24 PM CDT Asset located in: Humble, TX, USA
873	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30618239 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:21 PM CDT Asset located in: Humble, TX, USA	882	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20622273 C/W: Located in Lane 56 Spot 1, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:24 PM CDT Asset located in: Lake Worth, TX, USA
874	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30607043 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:21 PM CDT Asset located in: Humble, TX, USA	883	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20618249 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:24 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
884	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20615186 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:24 PM CDT Asset located in: Humble, TX, USA	892	2016 Grove RT880E 80 ton 4x4 Rough Terrain Crane S/N: 235420 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, 2016 US EPA Label, Cummins B6.7 275 6 Cylinder 275 hp 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 41 ft Minimum 128 ft Maximum Boom Length, 33 ft to 56 ft Bifold Offset Jib, Overhaul Ball, 17590 lb Counterweight, Counterweight Removal System Usage: 11,031 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:27 PM CDT Asset located in: Dallas, TX, USA
885	2026 CFG MH13RX Mini Excavator (Unused) S/N: MH13RX26A20618242 C/W: Located in Lane 56 Spot 0, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 01:25 PM CDT Asset located in: Humble, TX, USA	893	2014 Grove RT880E 80 ton 4x4 Rough Terrain Crane S/N: 234771 C/W: Air Conditioner, Tilt Cab, 13211 hrs Crane Operation, Cummins QSB6.7 6.7 L Diesel Engine, 41 ft Minimum 128 ft Maximum Boom Length, Rooster Sheave, 33 ft to 56 ft Bifold Jib, 1276 lb 82.7 ton Capacity Johnson 3 Sheave Hook Block, 500 lb 12 ton Capacity Overhaul Ball, Counterweight Removal System Usage: 13,211 Hr Notes: The closing times of lots 893 thru 894 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; Lot closing time: Wed, Sep 16, 01:27 PM CDT Asset located in: Lake Worth, TX, USA
887	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30607072 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:25 PM CDT Asset located in: Livingston, LA, USA	894	2014 Grove RT880E 80 ton 4x4 Rough Terrain Crane S/N: 234498 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, Cummins 6 Cylinder Diesel Engine, 41 ft Minimum 128 ft Maximum Boom Length, 33 ft to 56 ft Bifold Offset Jib, 17630 lb Counterweight Usage: 12,220 Hr Notes: The closing times of lots 893 thru 894 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Current Annual Crane Inspection Valid Through 10-8-2026 Lot closing time: Wed, Sep 16, 01:27 PM CDT Asset located in: Dallas, TX, USA
888	2026 CFG H13R Mini Excavator (Unused) S/N: H13R2026A30609109 C/W: 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:26 PM CDT Asset located in: Livingston, LA, USA		
889	2026 CFG MX12R Mini Excavator (Unused) S/N: MX12R2026J0000345 C/W: Located in Lane 56 Spot 0, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:26 PM CDT Asset located in: Humble, TX, USA		
891	2026 ATS POWER ATS-RT15R Mini Excavator (Unused) S/N: 2605072374SH C/W: Located in Lane 56, 2026 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Lot closing time: Wed, Sep 16, 01:27 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
895	2008 Grove RT880E 80 ton 4x4 Rough Terrain Crane S/N: 229710 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, Cummins 6 Cylinder Diesel Engine, 41 ft Minimum 128 ft Maximum Boom Length, Auxiliary Hoist, 33 ft to 56 ft Bifold Swingaway Offset Jib, Overhaul Ball, 18000 lb Counterweight Usage: 17,790 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:28 PM CDT Asset located in: Dallas, TX, USA	902	2016 John Deere 437E Trailer Mounted Log Loader S/N: IT0437EDJGF300299 C/W: Located in Lane 56 Spot 1, Air Conditioner, Rotobec Log Grapple, Hydraulic Outrigger, Knuckle Boom w/Heel Usage: 14,225 Hr Lot closing time: Wed, Sep 16, 01:30 PM CDT Asset located in: Lake Worth, TX, USA
896	2010 Grove RT700E 80 ton 4x4 Rough Terrain Crane S/N: 231140 C/W: Anti Two-Block, PAT Load Moment Indicator, 2010 US EPA Label, Cummins QSB6.7 6 Cylinder 240 hp 6.7 L Diesel Engine, 110 ft Maximum Boom Length, Auxiliary Hoist, 33 ft to 56 ft Bifold Swingaway Offset Jib, Overhaul Ball Usage: 15,053 Hr Notes: The closing times of lots 66 thru 69 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Current Annual Crane Inspection Valid Through 10-8-2026 Lot closing time: Wed, Sep 16, 01:28 PM CDT Asset located in: Dallas, TX, USA	903	RWF Bron 475B Tracked Mulcher Tractor S/N: 09M091328 C/W: Located in Lane 60 Spot 0, Joystick Steering Usage: Not Available Lot closing time: Wed, Sep 16, 01:30 PM CDT Asset located in: Humble, TX, USA
897	2010 Grove RT700E 80 ton 4x4 Rough Terrain Crane S/N: 231206 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, 2010 US EPA Label, Cummins QSB6.7 6 Cylinder 240 hp 6.7 L Diesel Engine, 110 ft Maximum Boom Length, Auxiliary Hoist, 33 ft to 56 ft Bifold Swingaway Offset Jib, Overhaul Ball Usage: 12,867 Hr Notes: The closing times of lots 66 thru 69 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:28 PM CDT Asset located in: Dallas, TX, USA	904	2006 Gyro-Trac GT25 Tracked Mulcher Tractor S/N: BCT25061115C C/W: Located in Lane 56 Spot 2, Enclosed Cab, Joystick Steering, US EPA Label, 28 in Track Belts, 7 ft 9 in, Mulcher, Winch Usage: Not Available Lot closing time: Wed, Sep 16, 01:30 PM CDT Asset located in: Lake Worth, TX, USA
901	2020 Tiger Cat 234B Trailer Mounted Heel Boom Log Loader S/N: 3277 C/W: Located in Lane 56 Spot 0, Air Conditioner, 2019 US EPA Label, Tigercat Log Grapple, Hydraulic Outrigger, Knuckle Boom w /Heel Usage: Not Available Lot closing time: Wed, Sep 16, 01:30 PM CDT Asset located in: Lake Worth, TX, USA	906	Barreto E30SGB Walk Behind Stump Grinder w/ Barreto E4X6TBT Trailer S/N: SG2012 C/W: 2019 US EPA Label, Vanguard 2 Cylinder 890 cc Gasoline Engine, Hydrostatic Drive, 18 in Grinding Wheel, 7 in Rubber Tracks Usage: 507 Hr Lot closing time: Wed, Sep 16, 01:31 PM CDT Asset located in: Humble, TX, USA
		907	2022 Toro STX-26 Walk Behind Stump Grinder w/ Teske 4X5 Dingo Trailer Trailer S/N: 412473906 C/W: 2021 US EPA Label, Kawasaki FX730V 2 Cylinder 726 cc Gasoline Engine, Hydrostatic Drive, 16 in Grinding Wheel, 6 in Rubber Tracks, S/A Trailer w/ S/N- 5ERBU0819MM132191, Ball Hitch Usage: 226 Hr Lot closing time: Wed, Sep 16, 01:31 PM CDT Asset located in: Humble, TX, USA
		908	2022 Vermeer BC700XL Tow-Behind Wood Chipper S/N: 1VRC101V3N1004758 C/W: Located in Lane 58 Spot 0, 2021 US EPA Label, Kohler ECH740 2 Cylinder 740 cc Gasoline Engine, 8 in Feed Opening, Swivel Discharge Chute, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 01:32 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
909	2022 Vermeer BC700XL Tow-Behind Wood Chipper S/N: 1VRC101V5N1004759 C/W: Located in Lane 58 Spot 0, 2021 US EPA Label, Kohler ECH740 2 Cylinder 747 cc Gasoline Engine, 8 in Feed Opening, Swivel Discharge Chute, Ball Hitch Carrier Trailer Usage: 398 Hr Lot closing time: Wed, Sep 16, 01:32 PM CDT Asset located in: Humble, TX, USA	919	Erie Industries GF480 Trommel Screen S/N: Not Available C/W: Located in Lane 58 Spot 0 Usage: Not Available Lot closing time: Wed, Sep 16, 01:35 PM CDT Asset located in: Humble, TX, USA
911	Future PSJ220 Jaw Crusher (Unused) S/N: PSJ2202507111 C/W: Located in Lane 54 Spot 0, 14 in x 9 in Jaw Crusher Usage: Not Available Lot closing time: Wed, Sep 16, 01:33 PM CDT Asset located in: Humble, TX, USA	920	Eingp G480 Skid Mounted Trommel Screen (Unused) S/N: Not Available C/W: Located in Lane 58 Spot 0, 4 ft 10 in x 2 ft 4 ft 7 in x 2 ft 10 in Trommel Screen Usage: Not Available Lot closing time: Wed, Sep 16, 01:35 PM CDT Asset located in: Humble, TX, USA
911A	2025 PSJ220 14 in Jaw Crusher (Unused) S/N: PSJ22025006251 C/W: Vertical Shaft Impact Crusher Usage: Not Available Lot closing time: Wed, Sep 16, 01:33 PM CDT Asset located in: Lake Worth, TX, USA	921	Triple S Dynamics TS-2306S Screen S/N: TS-2011-04 C/W: Located in Lane 56 Spot 2, 5 ft 4 in x 2 ft 8 in Single Deck Screen Usage: Not Available Lot closing time: Wed, Sep 16, 01:36 PM CDT Asset located in: Lake Worth, TX, USA
912	2002 Universal 3254 WRB Jaw Crusher S/N: 147X55 Usage: Not Available Notes: Units Can Be Loaded Onsite with a High Capacity Gantry Crane Post Auction ; 250 HP AO Smith Electric Motor Also in Auction;Item at offsite location must be picked up within 14 days of auction (October 2nd) or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:33 PM CDT Asset located in: Georgetown, TX, USA	923	E-Z Lift 18 in x 30 ft Portable Transfer Conveyor S/N: Not Available C/W: Located in Lane 56 Spot 2, Lattice Frame, Baldor Electric Motor Usage: Not Available Lot closing time: Wed, Sep 16, 01:36 PM CDT Asset located in: Lake Worth, TX, USA
913	Astec Fast Trax RT 4250 Tracked Crushing Plant S/N: 602073 C/W: Located in Lane 58, 12 ft 6 in x 5 ft Single Deck Screen, 44 in Wide Feed Conveyor, 44 in Wide Under Crusher Conveyor, 44 in Crusher to Screen Conveyor, 22.5 in Wide Left Discharge Conveyor, 48 in Wide End Discharge Conveyor, Radio Remote Control, Cummins 6 Cylinder Diesel Engine, 24 in Triple Grouser Track Shoes Usage: 1,620 Hr Notes: The blown hydraulic valve will be replaced post-sale. Please call before scheduling a pickup. Lot closing time: Wed, Sep 16, 01:33 PM CDT Asset located in: Humble, TX, USA	924	2018 Atlas Portable Conveyor S/N: TRX110ICKOMH23778 C/W: Lattice Frame, Folding Head Section, Manual Raise, Electric Radial Drive, Pintle Ring Usage: Not Available Lot closing time: Wed, Sep 16, 01:36 PM CDT Asset located in: Lake Worth, TX, USA
918	GF480 Skid Mounted Rotary Trommel Screen S/N: Not Available C/W: Located in Lane 58 Spot 0, 4 ft x 7 ft Vibratory Grizzly Feeder Usage: Not Available Lot closing time: Wed, Sep 16, 01:35 PM CDT Asset located in: Humble, TX, USA	927	2016 Rome TRCW-16 12 ft 6 in Pull Offset Disc Harrow S/N: 8TRCW-OB-331 C/W: Located in Lane 56 Spot 2, 34 in Notched Front Discs, 34 in Notched Rear Discs, 20 in Spacing Usage: Not Available Lot closing time: Wed, Sep 16, 01:37 PM CDT Asset located in: Lake Worth, TX, USA
		928	John Deere 435 Round Baler S/N: E00435X899800 C/W: 540 PTO, Clevis Pin Hitch, 48 in Pickup, Twine Tie, Push Bar Ejector Usage: Not Available Lot closing time: Wed, Sep 16, 01:38 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
929	2018 J&M 1151-22 1150 bu S/A Grain Cart S/N: 1801490 C/W: 22 in PTO Driven Hydraulic Folding Auger, Hydraulic Spout, Clean Out Doors, Roll Tarp, 1000 PTO, Digi-Star Scale, In-Cab Controls, Duals 480/80R42 Usage: Not Available Notes: From the Fleet of Harvest Time Farms Lot closing time: Wed, Sep 16, 01:38 PM CDT Asset located in: Lake Worth, TX, USA	936	2018 Wirtgen WR240i Wheel Soil Stabilizer Reclaimer S/N: 10WR1185 C/W: Located in Lane 56 Spot 2, Enclosed Cab, Air Conditioner, Rear View Camera, 2018 US EPA Label, 98 in Combination Rotor, 20 in Cutting Depth Usage: 5,884 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:40 PM CDT Asset located in: Lake Worth, TX, USA
929A	Unverferth GC8200 S/A Grain Cart S/N: B18520107 C/W: 16 in Hydraulic Driven Hydraulic Folding Auger, 30.5L-32 Usage: Not Available Notes: From the Fleet of Harvest Time Farms Lot closing time: Wed, Sep 16, 01:38 PM CDT Asset located in: Lake Worth, TX, USA	937	2015 Wirtgen WR200XLi Wheel Soil Stabilizer Reclaimer S/N: 09WR0049 C/W: Located in Lane 55 Spot 2, Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 94 in Combination Rotor, 20 in Cutting Depth Usage: 4,090 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:40 PM CDT Asset located in: Lake Worth, TX, USA
929B	Wheatheart BH36-10 10 in x 36 ft 6000 bu Grain Auger S/N: Not Available C/W: Located in Lane 58 Spot 0, Electric Usage: Not Available Lot closing time: Wed, Sep 16, 01:38 PM CDT Asset located in: Humble, TX, USA	938	2003 Bomag MPH364S Wheel Soil Stabilizer Reclaimer S/N: 109A23001503 C/W: Located in Lane 63 Spot 0, 2010 US EPA Label, 79 in Combination Rotor, 12 in Cutting Depth Usage: 334 Hr Lot closing time: Wed, Sep 16, 01:41 PM CDT Asset located in: Humble, TX, USA
930	John Deere 22 Row 12 in Sunflower Combine Header S/N: Not Available C/W: Located in Lane 56 Spot 2, Hydraulic Fore & Aft Usage: Not Available Notes: From the Fleet of Harvest Time Farms Lot closing time: Wed, Sep 16, 01:38 PM CDT Asset located in: Lake Worth, TX, USA	940	1991 Cat SS-250 Wheel Soil Stabilizer Reclaimer S/N: 6DD00202 C/W: Located in Lane 56 Spot 1, 100 in Soil Rotor Usage: 1,584 Hr Lot closing time: Wed, Sep 16, 01:41 PM CDT Asset located in: Lake Worth, TX, USA
931	Boeing 400 Asphalt Plant S/N: BEECH-400-475 C/W: Drum, Blending Bins, Drag Slag, Scrubber, Conveyor, Asphalt Silo, Control Van; Equipment-from-Whitaker-Aggregates Usage: Not Available Notes: ***The plant components selling under this item number are at 3 different locations in Kansas. The Control Van is located in 555 Delaware Rd, Humboldt, KS 667481301, USA, Asphalt Silo is located in Hwy 39 and Udall Rd, Chanute, KS 66720, USA and the Asphalt Plant is located in 300 SW 1000 Rd, Welda, KS 66091, USA.*** Lot closing time: Wed, Sep 16, 01:39 PM CDT Asset located in: Welda, KS, USA	941	2014 Blaw-Knox PF-1510 Track Asphalt Paver S/N: 117300 C/W: Located in Lane 60 Spot 0, Electric Heated 8 ft - 14 ft Screed, Truck Hitch, 14 in Triple Grouser Track Shoes w/Rubber Pads Usage: 7,883 Hr Lot closing time: Wed, Sep 16, 01:42 PM CDT Asset located in: Humble, TX, USA
		942A	2021 Cimline M2DH Melter Applicator S/N: 1G92M1525MM119132 C/W: Diesel Fired Heater, Hydraulic Agitator, Hydraulic Driven Pump, Hose & Wand, T/A Trailer Mounted Usage: 489 Hr Lot closing time: Wed, Sep 16, 01:42 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
943	2017 Craftco Clutch Dust Control Pavement Router S/N: 173119 C/W: Located in Lane 54 Spot 1, Kohler Command Pro 27 hp 747 cc Gasoline Engine Usage: Not Available Lot closing time: Wed, Sep 16, 01:42 PM CDT Asset located in: Humble, TX, USA	953	Gomaco TC600 Texture Cure Machine S/N: 904700032 C/W: Located in Lane 56 Spot 2, 25 ft 1 in Paving Width, Cure Spraying Applicator, 12 in Smooth Track Shoes Usage: 726 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:45 PM CDT Asset located in: Lake Worth, TX, USA
945	U-Card CB2 Concrete Batch Plant S/N: Not Available C/W: Stationary 4 Aggregate Bins, 1 ft 5 in x 34 ft Radial Charging Conveyor Usage: Not Available Notes: Item at offsite location must be picked up within 14 days of auction (October 2nd) or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:43 PM CDT Asset located in: Wichita Falls, TX, USA	954	2021 E-Z Drill 210B -SR 4 Way Pneumatic Concrete Drill S/N: A16260 C/W: Located in Lane 72 Spot 1 Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:45 PM CDT Asset located in: Lake Worth, TX, USA
947	Gomaco 9000 Trimmer and Placer S/N: 909000-026 C/W: Located in Lane 56 Spot 2, 2018 US EPA Label, 15 ft 5 in Trimmer, 32 in Feed Conveyor, 13.75 in Triple Grouser Track Shoes Usage: 1,194 Hr Lot closing time: Wed, Sep 16, 01:43 PM CDT Asset located in: Lake Worth, TX, USA	955	2021 E-Z Drill 210BSRA Pneumatic Concrete Drill S/N: A16259 Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:46 PM CDT Asset located in: Lake Worth, TX, USA
949	1999 CMI MTP-4004 Concrete Placer S/N: 537182 C/W: Located in Lane 56 Spot 2, 1999 US EPA Label Usage: Not Available Lot closing time: Wed, Sep 16, 01:44 PM CDT Asset located in: Lake Worth, TX, USA	957	Chicago Mfg. 201-1353A 10x4 Work Over Rig S/N: 135819 C/W: Located in Lane 9 Spot 23, PTO Driven, Straight Down Outriggers, Cat D3408 V8 Diesel Engine, Automatic Transmission, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Tag Axle, Ryco Spring Suspension, PTO Usage: Not Available Lot closing time: Wed, Sep 16, 01:46 PM CDT Asset located in: Humble, TX, USA
950	Gomaco PS2600 Concrete Spreader S/N: 904900010 C/W: Located in Lane 56 Spot 2, 16 in Triple Grouser Track Shoes Usage: 8,229 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:44 PM CDT Asset located in: Lake Worth, TX, USA	958	2019 Gefco DP2000 Twin Fluid Pumper Unit S/N: 1G9G6UF35HE483138 C/W: Cat C27 12 Cylinder Diesel Engine Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:47 PM CDT Asset located in: Pecos, TX, USA
952	2003 Gomaco GP-4000 Slip Form Paver S/N: 905100026 C/W: Located in Lane 56 Spot 2, 20 in Triple Grouser Track Shoes Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 01:45 PM CDT Asset located in: Lake Worth, TX, USA	959	2022 Nexus NE-080-A145 Blowout Preventer S/N: 022719NX-02 C/W: Studded Top & Flanged Bottom, NXL 5.12, 15K Dual Combi. BOP with stand Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:47 PM CDT Asset located in: Pecos, TX, USA

Lot #	Details	Lot #	Details
960	2020 Nexus NE-080-A124 Blowout Preventer S/N: 041219NX-01 C/W: Studded Top & Flanged Bottom, 10K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:47 PM CDT Asset located in: Pecos, TX, USA	966	2012 Texas Oil Tools M60ES56-L569XL Blowout Preventer S/N: 123-38325 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:49 PM CDT Asset located in: Pecos, TX, USA
961	2014 Texas Oil Tools M60ES54-L549X Blowout Preventer S/N: 142-44874 C/W: Studded Top & Flanged Bottom, 10K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:48 PM CDT Asset located in: Pecos, TX, USA	968	2012 Texas Oil Tools M60ES56-L569XL Blowout Preventer S/N: 123-38321 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:50 PM CDT Asset located in: Pecos, TX, USA
962	2014 Texas Oil Tools M60ES54-NA549X Blowout Preventer S/N: 142-45255 C/W: Studded Top & Flanged Bottom, 10k BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:48 PM CDT Asset located in: Pecos, TX, USA	970	2011 Texas Oil Tools M60ES54-P549X Blowout Preventer S/N: 114-34745 C/W: Studded Top & Flanged Bottom, BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:50 PM CDT Asset located in: Pecos, TX, USA
964	2013 Texas Oil Tools M60ES56-L569XL Blowout Preventer S/N: 134-43435 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:48 PM CDT Asset located in: Pecos, TX, USA	971	2011 Texas Oil Tools ES56-N569YL Blowout Preventer S/N: 114-34960 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:51 PM CDT Asset located in: Pecos, TX, USA
965	2013 Texas Oil Tools M60ES54-P549YB Blowout Preventer S/N: 134-43194 C/W: Studded Top & Flanged Bottom, 10k BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:49 PM CDT Asset located in: Pecos, TX, USA	972	2011 Texas Oil Tools ES56-N569YB Blowout Preventer S/N: 113-33803 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:51 PM CDT Asset located in: Pecos, TX, USA

Lot #	Details	Lot #	Details
973	2011 Texas Oil Tools ES56-N569YL Blowout Preventer S/N: 112-33171 C/W: Studded Top & Flanged Bottom, BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:51 PM CDT Asset located in: Pecos, TX, USA	978	2011 Texas Oil Tools ES56-N569YL Blowout Preventer S/N: 114-34964 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:53 PM CDT Asset located in: Pecos, TX, USA
974	2011 Texas Oil Tools M60ES56-L569XL Blowout Preventer S/N: 112-33165 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:51 PM CDT Asset located in: Pecos, TX, USA	979	2011 Texas Oil Tools M60ES54-L549X Blowout Preventer S/N: 114-34582 C/W: Studded Top & Flanged Bottom, 10K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:53 PM CDT Asset located in: Pecos, TX, USA
975	2011 Texas Oil Tools ES56-N569YL Blowout Preventer S/N: 114-34638 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:52 PM CDT Asset located in: Pecos, TX, USA	980	2011 Texas Oil Tools ES56-N569YL Blowout Preventer S/N: 112-33168 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:53 PM CDT Asset located in: Pecos, TX, USA
976	2011 Texas Oil Tools ES56-N569YL Blowout Preventer S/N: 114-34801 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:52 PM CDT Asset located in: Pecos, TX, USA	981	2010 Texas Oil Tools ES46-L469X Blowout Preventer S/N: 113-33825 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:54 PM CDT Asset located in: Pecos, TX, USA
977	2011 Texas Oil Tools ES56-N569YL Blowout Preventer S/N: 114-34657 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:52 PM CDT Asset located in: Pecos, TX, USA	982	2008 Texas Oil Tools ES46-L469X Blowout Preventer S/N: 082-27566 C/W: Studded Top & Flanged Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:54 PM CDT Asset located in: Pecos, TX, USA

Lot #	Details	Lot #	Details
983	2008 Texas Oil Tools ES46-C463X Blowout Preventer S/N: 083-28466 C/W: Studded Top & Bottom, 15K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:54 PM CDT Asset located in: Pecos, TX, USA	989	Farum Blowout Preventer S/N: P09233 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:56 PM CDT Asset located in: Pecos, TX, USA
984	2000 Texas Oil Tools ES54-N549X Blowout Preventer S/N: 091-29808 C/W: Studded Top & Flanged Bottom, 10K BOP Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 01:54 PM CDT Asset located in: Pecos, TX, USA	990	10000 psi Quad Blowout Preventer S/N: 132-41543 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:56 PM CDT Asset located in: Pecos, TX, USA
985	Double Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:55 PM CDT Asset located in: Pecos, TX, USA	991	Single Blowout Preventer S/N: 08328452R Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:57 PM CDT Asset located in: Pecos, TX, USA
986	10000 psi Quad Blowout Preventer S/N: 14245182 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:55 PM CDT Asset located in: Pecos, TX, USA	992	Quad Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:57 PM CDT Asset located in: Pecos, TX, USA
987	Double Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:55 PM CDT Asset located in: Pecos, TX, USA	993	Quad Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:57 PM CDT Asset located in: Pecos, TX, USA
988	Single Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:56 PM CDT Asset located in: Pecos, TX, USA	994	Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:57 PM CDT Asset located in: Pecos, TX, USA
		995	Quad Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:58 PM CDT Asset located in: Pecos, TX, USA

Lot #	Details	Lot #	Details
996	Quad Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:58 PM CDT Asset located in: Pecos, TX, USA	1005	2014 Hydra Rig HR6100 Injector Equipment S/N: CC303305 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 02:01 PM CDT Asset located in: Pecos, TX, USA
997	5 in 10000 psi Quad Blowout Preventer S/N: 031114NX-02 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:58 PM CDT Asset located in: Pecos, TX, USA	1006	2011 Hydra Rig HR-680 Injector Equipment S/N: CC302576 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:01 PM CDT Asset located in: Pecos, TX, USA
998	15000 psi Quad Blowout Preventer S/N: 071-24312 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:59 PM CDT Asset located in: Pecos, TX, USA	1007	2011 Hydra Rig HR680 Injector Equipment S/N: CC302719 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 02:01 PM CDT Asset located in: Pecos, TX, USA
999	Quad Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:59 PM CDT Asset located in: Pecos, TX, USA	1008	2008 Hydra Rig HR-680 Injector Equipment S/N: CC302124 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:02 PM CDT Asset located in: Pecos, TX, USA
1000	Quad Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 01:59 PM CDT Asset located in: Pecos, TX, USA	1009	2008 Hydra Rig HR-680 Injector Equipment S/N: CC302125 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:02 PM CDT Asset located in: Pecos, TX, USA
1003	Texas Oil Tools Blowout Preventer S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 02:00 PM CDT Asset located in: Lake Worth, TX, USA	1010	2007 Hydra Rig HR-680 Injector Equipment S/N: CC300752 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:02 PM CDT Asset located in: Pecos, TX, USA
1004	2014 Hydra Rig HR-680 Injector Equipment S/N: CC303395 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:00 PM CDT Asset located in: Pecos, TX, USA		

Lot #	Details	Lot #	Details
1011	2006 Hydra Rig HR680 Injector Equipment S/N: CC300846 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 02:03 PM CDT Asset located in: Pecos, TX, USA	1018	2017 Vermeer D40X55III Directional Drill S/N: 1VRY200G1H1000203 C/W: Located in Lane 56 Spot 2, Open Operator Station, 2016 US EPA Label, John Deere 4045HFC07A 4 Cylinder 130 kW 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, Drill Rod Loading System, 40 Drill Rods, 16 in Triple Grouser Track Shoes, Equipment-from-a-Primoris-Services-Corp-company Usage: 2,417 Hr Lot closing time: Wed, Sep 16, 02:05 PM CDT Asset located in: Lake Worth, TX, USA
1013	2011 Hydra Rig HR-580 Injector Equipment S/N: CE310364 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:03 PM CDT Asset located in: Pecos, TX, USA	1019	2018 Ditch Witch JT40 Directional Drill S/N: DWPJT40XPJ0000068 C/W: Located in Lane 56 Spot 2, Enclosed Cab, Air Conditioner, 2017 US EPA Label, Cummins QSB4.5 4 Cylinder 160 hp 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, Drill Rod Loading System, 16 in Rubber Tracks Usage: 4,174 Hr Lot closing time: Wed, Sep 16, 02:05 PM CDT Asset located in: Lake Worth, TX, USA
1014	2008 Hydra Rig HR-580 Injector Equipment S/N: CC302150 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:03 PM CDT Asset located in: Pecos, TX, USA	1020	2014 Vermeer D36X50II Directional Drill S/N: 1VR4230DXE1003005 C/W: Located in Lane 63 Spot 0, Enclosed Cab, Air Conditioner, 4 Cylinder Diesel Engine, Drill Rod Loading System, 16 in Triple Grouser Track Shoes w/Rubber Pads Usage: 6,581 Hr Lot closing time: Wed, Sep 16, 02:05 PM CDT Asset located in: Humble, TX, USA
1015	2008 Hydra Rig HR-560 Injector Equipment S/N: CC302148 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:04 PM CDT Asset located in: Pecos, TX, USA	1021	2016 Vermeer D23x30III Directional Drill S/N: 1VRN20075G1000447 C/W: Located in Lane 60 Spot 0, Open Operator Station, Deutz 4 Cylinder Diesel Engine, Drill Rod Loading System, 18 Drill Rods, 12 in Rubber Tracks Usage: 3,306 Hr Lot closing time: Wed, Sep 16, 02:06 PM CDT Asset located in: Humble, TX, USA
1016	Hydra Rig DOSR-560EG Injector Equipment S/N: 54 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 02:04 PM CDT Asset located in: Pecos, TX, USA	1022	2019 Ditch Witch JT20 Directional Drill w/2020 Felling FT-20 Trailer S/N: DWPJT20BHK0000253 C/W: Located in Lane 56 Spot 1, Open Operator Station, Mud Mixing System, Drill Rod Loading System, 45 Drill Rods, 11 in Rubber Tracks, T/A Trailer w/ S/N- 5FTCE2926K2005313, Lunette Ring, Electric Brakes, Ditch Witch FM13x vin# DWPFM13XHK0000984 Usage: 1,511 Hr Lot closing time: Wed, Sep 16, 02:06 PM CDT Asset located in: Lake Worth, TX, USA
1017	Texas Oil Tools Stripper Packer S/N: 11434629 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 02:04 PM CDT Asset located in: Lake Worth, TX, USA	1023	2018 Ditch Witch JT20 Directional Drill S/N: DWPJT20XPJ0001533 C/W: Located in Lane 58 Spot 0, Open Operator Station, US EPA Label, Deutz 4 Cylinder 74 hp 2.9 L Diesel Engine, Mud Mixing System, Drill Rod Loading System, 30 Drill Rods, 12 in Rubber Tracks Usage: 2,617 Hr Lot closing time: Wed, Sep 16, 02:06 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1026	2018 Doonan Additive Mixing Trailer S/N: 1D9BG4829J1609467 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:07 PM CDT Asset located in: Pecos, TX, USA	1036	2021 Ditch Witch C24X Walk Behind Trencher S/N: DWPC24XAJM0002603 C/W: Located in Lane 58 Spot 0, 2020 US EPA Label, Honda GX690 2 Cylinder Gasoline Engine, Hydrostatic Drive, 4 in Wide x 39 in Long 8 in Rubber Tracks, S/A Trailer w/ S/N-ADSB111F4M1703224, Ball Hitch Usage: 722 Hr Lot closing time: Wed, Sep 16, 02:10 PM CDT Asset located in: Humble, TX, USA
1027	2014 Texas Pride Mud Mixing System S/N: 1B9R3TGT0EB624593 C/W: Located in Lane 56 Spot 1, Centrifugal Pump, 2011 US EPA Label, 6 Cylinder 174 hp 6.4 L Diesel Engine Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 02:07 PM CDT Asset located in: Lake Worth, TX, USA	1037	2021 Ditch Witch C24X Walk Behind Trencher w/2020 Ditch Witch S3C Trailer S/N: DWPC24XAEM0002707 C/W: 2020 US EPA Label, Honda GX690 Gasoline Engine, Hydrostatic Drive, 6 in Wide x 4 ft 4 in Long Dirt Trencher Chain, 8 in Rubber Tracks, S/A Trailer w/ S/N-TDSB111F5M1703295, Ball Hitch Usage: 825 Hr Lot closing time: Wed, Sep 16, 02:10 PM CDT Asset located in: Midland, TX, USA
1028	2014 Texas Pride Mixing Trailer Mud Mixing System S/N: 1B9R3TGT3EB624426 C/W: Centrifugal Pump, Isuzu TCD914L06 6 Cylinder Diesel Engine, Tri/A Gooseneck Trailer, Electric Brakes Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 02:08 PM CDT Asset located in: Pecos, TX, USA	1038	2021 Ditch Witch C24X Walk Behind Trencher w/2020 Ditch Witch S3C Trailer S/N: DWPC24XAHM0002737 C/W: 2020 US EPA Label, Honda GX690 Gasoline Engine, Hydrostatic Drive, 6 in Wide x 4 ft 4 in Long Dirt Trencher Chain, 8 in Rubber Tracks, S/A Trailer w/ S/N-1DSB111F7M1703296, Ball Hitch Usage: 788 Hr Lot closing time: Wed, Sep 16, 02:11 PM CDT Asset located in: Midland, TX, USA
1030	CCI BM260 Pipe Bending Machine S/N: BM0620173 C/W: Tow Behind, Winch, Cat 4 Cylinder Diesel Engine Usage: 315 Hr Lot closing time: Wed, Sep 16, 02:08 PM CDT Asset located in: Humble, TX, USA	1039A	2020 Vermeer RTX250 Tracked Trencher S/N: 1VRD070D8L1001621 C/W: 2019 US EPA Label, Kohler Gasoline Engine, 4 ft 4 in Cable Plow, 7 in Rubber Tracks Usage: 688 Hr Lot closing time: Wed, Sep 16, 02:11 PM CDT Asset located in: Lake Worth, TX, USA
1031	2018 Vermeer RTX750 4x4 Rock Saw S/N: 1VR9112MXJ1003218 C/W: Canopy, 2017 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 74 hp 2.92 L Diesel Engine, Hydrostatic Drive, 3.5 in Trenching Width, 36 in Trenching Depth, Straight Blade Usage: 2,742 Hr Lot closing time: Wed, Sep 16, 02:09 PM CDT Asset located in: Lake Worth, TX, USA	1040	Barreto 712MT Walk Behind Trencher S/N: Not Available C/W: Located in Lane 56 Spot 1, 2022 US EPA Label, Honda 1 Cylinder 196 cc Gasoline Engine, Hydrostatic Drive, 3 in Wide x 24 in Long Dirt Trencher Chain Usage: Not Available Lot closing time: Wed, Sep 16, 02:11 PM CDT Asset located in: Lake Worth, TX, USA
1034	2014 Ditch Witch RT30 4x4 Trencher S/N: CMWRT30XCE0000065 C/W: Located in Lane 60 Spot 0, Tier 4, 2013 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.5 L Diesel Engine, Hydrostatic Drive, 6 in Wide x 64 in Long Dirt Trencher Chain, Angle Blade Usage: 404 Hr Lot closing time: Wed, Sep 16, 02:09 PM CDT Asset located in: Humble, TX, USA	1041	Barreto E924HM-4MS Walk Behind Trencher S/N: M4218 C/W: Located in Lane 58 Spot 0, Honda Gasoline Engine, Hydrostatic Drive, 4 in Wide x 2 ft 10 in Long Dirt Trencher Chain, Crumbling Shoe Usage: 256 Hr Lot closing time: Wed, Sep 16, 02:12 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1042	Barreto E924HM-4MS Walk Behind Trencher S/N: M3997 C/W: Located in Lane 58 Spot 0, 2019 US EPA Label, Honda GX270 270 cc Gasoline Engine, Hydrostatic Drive, 4 in Wide x 2 ft 10 in Long Dirt Trencher Chain, Crumbling Shoe Usage: 301 Hr Lot closing time: Wed, Sep 16, 02:12 PM CDT Asset located in: Humble, TX, USA	1053	2017 Vermeer VX50-800LT T/A Vacuum Excavation Unit S/N: 1M9FE1228GS284442 C/W: Located in Lane 56 Spot 1, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Vermeer Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Wash Down System, 4 in Suction Hose, Engine Driven Pump, Blower, Aluminum Wheels, 215/75R17.5 Tires, 2016 US EPA Label, Kubota V2403-CR-EF08 4 Cylinder 36 kW 2.4 L Diesel Engine Usage: 3,468 Hr Notes: All Units from Same Well Maintained Owner Fleet - Lot 111A, 1045, 1052, 1053, 1054 Lot closing time: Wed, Sep 16, 02:15 PM CDT Asset located in: Lake Worth, TX, USA
1043	Barreto E2036RTKH-6MS Walk Behind Trencher w/ Barreto Trailer S/N: RTK2041 C/W: 2018 US EPA Label, Honda GX630 2 Cylinder Gasoline Engine, Hydrostatic Drive, 6 in Wide x 4 ft 4 in Long Dirt Trencher Chain, 7 in Rubber Tracks, S/A Trailer w/ S/N-1B9UC0618LL280544, Ball Hitch Usage: 575 Hr Lot closing time: Wed, Sep 16, 02:12 PM CDT Asset located in: Midland, TX, USA	1054	2016 Vermeer VX50-800LT T/A Vacuum Excavation Unit S/N: 1M9FE1229GS284286 C/W: Located in Lane 56 Spot 1, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Vermeer Steel Debris Tank, Rear Hose Reel, 100 gal Fresh Water Tank, Full Open Tailgate, Hydraulic Tailgate Locks, Engine Driven Pump, 215 /75R17.5 Tires, 2015 US EPA Label, Kubota V2403-CR-EF08 4 Cylinder 36.0 kW 2.4 L Diesel Engine Usage: 4,699 Hr Notes: All Units from Same Well Maintained Owner Fleet - Lot 111A, 1045, 1052, 1053, 1054 Lot closing time: Wed, Sep 16, 02:15 PM CDT Asset located in: Lake Worth, TX, USA
1044	Barreto E2036RTKH-6MS Walk Behind Trencher w/2020 Barreto Trailer S/N: RTK2046 C/W: 2018 US EPA Label, Honda GX630 Gasoline Engine, Hydrostatic Drive, 6 in Wide x 4 ft 6 in Long Dirt Trencher Chain, 7 in Rubber Tracks, S/A Trailer w/ S/N-B9UC061XEL280545, Ball Hitch Usage: 608 Hr Lot closing time: Wed, Sep 16, 02:12 PM CDT Asset located in: Midland, TX, USA	1055	2013 McLaughlin V500LEHD 500 gal Vacuum System S/N: 1M9FE1228DS284369 C/W: Located in Lane 58 Spot 0, Lunette Ring Hitch, Spring Suspension, Vermeer Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Wash Down System, 4 in Suction Hose, Engine Driven Pump, Blower, 235/80R16 Tires, Tier 4, 2011 US EPA Label, Kubota V2203 3 Cylinder 35.9 kW Diesel Engine Usage: 1,084 Hr Lot closing time: Wed, Sep 16, 02:16 PM CDT Asset located in: Humble, TX, USA
1045	2017 Vermeer LP873SDT T/A Vacuum Excavation Unit S/N: 5HZBF1925HLCH2135 C/W: Located in Lane 56 Spot 1, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Vermeer LP873 Steel Debris Tank, Rear Hose Reel, Hydraulic Lift Tailgate, 6 in Suction Hose, Engine Driven Pump, 235/80R16 Tires, 14000 lb GVWR, Yanmar 4 Cylinder Diesel Engine Usage: 4,331 Hr Notes: All Units from Same Well Maintained Owner Fleet - Lot 111A, 1045, 1052, 1053, 1054 Lot closing time: Wed, Sep 16, 02:13 PM CDT Asset located in: Lake Worth, TX, USA	1057	2013 Ditch Witch FX30 800 gal T/A Vacuum Excavation Unit S/N: 1D5B202S3D1701970 C/W: Located in Lane 58 Spot 0, Lunette Ring Hitch, Spring Suspension, Ditch Witch Steel Debris Tank, Rear Hose Reel, 300 gal Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Wash Down System, Telescopic Boom, 4 in Suction Hose, Tuthill Engine Driven Pump, Blower, Remote Control w/ Cord, 215/75R17.5 Tires, 18000 lb GVWR, Tier 4, 2013 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.1 L Diesel Engine Usage: 1,346 Hr Lot closing time: Wed, Sep 16, 02:16 PM CDT Asset located in: Humble, TX, USA
1052	2021 Vermeer VX50-800 T/A Vacuum Excavation Unit S/N: 1M9FE1221MS284830 C/W: Located in Lane 56 Spot 1, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Vermeer VX50 Steel Debris Tank, Rear Hose Reel, Hydraulic Lift Tailgate, Wash Down System, 6 in Suction Hose, Engine Driven Pump, 215 /75R17.5 Tires, 18000 lb GVWR, Kubota 4 Cylinder Diesel Engine Usage: 3,039 Hr Notes: All Units from Same Well Maintained Owner Fleet - Lot 111A, 1045, 1052, 1053, 1054 Lot closing time: Wed, Sep 16, 02:15 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
1058	2022 Vermeer PD10R Crawler Mounted Post Driver S/N: 1VRR1008KN1001125 C/W: Located in Lane 56 Spot 1, 2021 US EPA Label, Vermeer Hydraulic Pile Hammer, 17 in Triple Grouser Track Shoes Usage: 3,950 Hr Lot closing time: Wed, Sep 16, 02:17 PM CDT Asset located in: Lake Worth, TX, USA	1063	2018 Hyundai 160D-9 36000 lb Pneumatic Tire Forklift S/N: HHKHFT23EJ0000212 C/W: Located in Lane 13 Spot 36, Enclosed Cab, Air Conditioner, 2 Stage Mast, 158 in Max Lift Height, 134 in Lowered Mast Height, 96 in Forks, Side Shift, Fork Positioner, Tier 4, 2017 US EPA Label, Cummins QSB6.7 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid Usage: 7,274 Hr Lot closing time: Wed, Sep 16, 02:18 PM CDT Asset located in: Humble, TX, USA
1059	Delmag Pile Hammer S/N: Not Available C/W: C/W Boom Sections Usage: Not Available Lot closing time: Wed, Sep 16, 02:17 PM CDT Asset located in: Lake Worth, TX, USA	1064	2018 Hyundai 160D-9 36000 lb Pneumatic Tire Forklift S/N: HHKHFT23KJ0000216 C/W: Located in Lane 13 Spot 35, Enclosed Cab, Air Conditioner, 2 Stage Mast, 158 in Max Lift Height, 134 in Lowered Mast Height, 90 in Forks, Fork Positioner, Tier 4, 2017 US EPA Label, Cummins QSB6.7 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid Usage: 11,927 Hr Lot closing time: Wed, Sep 16, 02:18 PM CDT Asset located in: Humble, TX, USA
1060	2019 Hyundai 160D-9 36000 lb Pneumatic Tire Forklift S/N: HHKHFT23JK0000400 C/W: Located in Lane 13 Spot 32, Enclosed Cab, Air Conditioner, 2 Stage Mast, 158 in Max Lift Height, 134 in Lowered Mast Height, 96 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Fork Positioner, Tier 4, 2018 US EPA Label, Cummins QSB6.7 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid Usage: Not Available Lot closing time: Wed, Sep 16, 02:17 PM CDT Asset located in: Humble, TX, USA	1065	2015 Hyster H300HD2 29000 lb Pneumatic Tire Forklift S/N: J019E02644N C/W: Located in Lane 100 Spot 1, Enclosed Cab, 2 Stage Mast, 183.1 in Max Lift Height, 160 in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, Cummins 6 Cylinder Diesel Engine Usage: 8,934 Hr Lot closing time: Wed, Sep 16, 02:19 PM CDT Asset located in: Lake Worth, TX, USA
1061	2019 Hyundai 160D-9 36000 lb Pneumatic Tire Forklift S/N: HHKHFT23CK0000382 C/W: Located in Lane 13 Spot 29, Enclosed Cab, Air Conditioner, 2 Stage Mast, 158 in Max Lift Height, 134 in Lowered Mast Height, 90 in Forks, Side Shift, Fork Positioner, US EPA Label, Cummins QSB6.7 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid Usage: 14,859 Hr Lot closing time: Wed, Sep 16, 02:18 PM CDT Asset located in: Humble, TX, USA	1066	2018 Hyundai 80D-9 17500 lb Pneumatic Tire Forklift S/N: HHKHFT23LJ0000448 C/W: Located in Lane 13 Spot 34, Enclosed Cab, Air Conditioner, 2 Stage Mast, 177 in Max Lift Height, 132 in Lowered Mast Height, Side Shift, Tier 4, Cummins QSF3.8 4 Cylinder 3.8 L Diesel Engine, Requires Diesel Exhaust Fluid Usage: 4,576 Hr Lot closing time: Wed, Sep 16, 02:19 PM CDT Asset located in: Humble, TX, USA
1062	2018 Hyundai 160D-9 36000 lb Pneumatic Tire Forklift S/N: HHKHFT23JJ0000234 C/W: Located in Lane 13 Spot 26, Enclosed Cab, Air Conditioner, 2 Stage Mast, 158 in Max Lift Height, 151 in Lowered Mast Height, 96 in Forks, Side Shift, Solid Pneumatic Tires, 2018 US EPA Label, CARB Compliant, Cummins QSB6.7 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid Usage: 6,073 Hr Lot closing time: Wed, Sep 16, 02:18 PM CDT Asset located in: Humble, TX, USA	1068	2018 Hyundai 9000 lb Pneumatic Tire Forklift S/N: HHKHFT26TJ0000137 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, 92 in Lowered Mast Height, 69 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, Cummins 4 Cylinder Diesel Engine Usage: 13,525 Hr Lot closing time: Wed, Sep 16, 02:20 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1070	2009 Hyster S120FT 6450 lb Cushion Tire Forklift S/N: G004V04553G C/W: Located in Lane 62, 3 Stage Mast, Full Free Lift, 208.7 in Max Lift Height, 102 in Lowered Mast Height, Auxiliary Hydraulic Plumbing, 2009 US EPA Label, TGFO 6 Cylinder 75 kW 4.3 L LPG Engine Usage: 9,766 Hr Lot closing time: Wed, Sep 16, 02:20 PM CDT Asset located in: Humble, TX, USA	1079	2018 Toyota 8FG35U 7000 lb Pneumatic Tire Forklift S/N: 12794 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, 187 in Max Lift Height, 88 in Lowered Mast Height, 72 in Forks, Side Shift, 2018 US EPA Label, Toyota 4 Cylinder 3.685 L LPG Engine Usage: 3,033 Hr Lot closing time: Wed, Sep 16, 02:23 PM CDT Asset located in: Humble, TX, USA
1071	2014 Clark C45D 8050 lb Cushion Tire Forklift S/N: P455D-0183-9913 C/W: Located in Lane 61 Spot 00, 3 Stage Mast, 177 in Max Lift Height, 87 in Lowered Mast Height, 47 in Forks, Side Shift, 2014 US EPA Label, Deutz TD3.6L4 4 Cylinder 74 hp 3.6 L Diesel Engine Usage: 9,228 Hr Lot closing time: Wed, Sep 16, 02:21 PM CDT Asset located in: Humble, TX, USA	1079A	Heli CPYD35-TY 6000 lb Pneumatic Tire Forklift S/N: 23035F9073 C/W: 3 Stage Mast, 189 in Max Lift Height, 92 in Lowered Mast Height, Solid Pneumatic Tires, 2006 US EPA Label, Impco 4 Cylinder LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:23 PM CDT Asset located in: Lake Worth, TX, USA
1074	Komatsu FG40ZT-4 7720 lb Pneumatic Tire Forklift S/N: 110371A C/W: Located in Lane 61, 3 Stage Mast, Full Free Lift, 169 in Max Lift Height, 83 in Lowered Mast Height, 41 in Forks, Solid Pneumatic Tires, Nissan 6 Cylinder LPG Engine Usage: 6,456 Hr Lot closing time: Wed, Sep 16, 02:21 PM CDT Asset located in: Humble, TX, USA	1080	2021 Doosan GC30S-9 5500 lb Cushion Tire Forklift S/N: FGA1F-1290-00285 C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 96 in Forks, Side Shift, 2020 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 2,827 Hr Lot closing time: Wed, Sep 16, 02:23 PM CDT Asset located in: Lake Worth, TX, USA
1075	2018 Hyundai 35D-9 7400 lb Pneumatic Tire Forklift S/N: HHKHfV25EJ0000319 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, 185 in Max Lift Height, 92 in Lowered Mast Height, 72 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, Cummins 4 Cylinder Diesel Engine Usage: 16,286 Hr Lot closing time: Wed, Sep 16, 02:22 PM CDT Asset located in: Humble, TX, USA	1080A	Toyota FGC35 6600 lb Forklift S/N: I2062 C/W: Located in Lane 62 Spot 0, 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: 5,747 Hr Lot closing time: Wed, Sep 16, 02:23 PM CDT Asset located in: Humble, TX, USA
1078	2021 Hyundai 35D-9 6930 lb Pneumatic Tire Forklift S/N: HHKHfV25EF0000361 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 92 in Lowered Mast Height, 72 in Forks, Side Shift, Solid Pneumatic Tires, Cummins 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid Usage: 14,482 Hr Lot closing time: Wed, Sep 16, 02:23 PM CDT Asset located in: Humble, TX, USA	1081	2020 Taylor GT60L 5625 lb Pneumatic Tire Forklift S/N: XHT466L005210030KF C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2020 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:24 PM CDT Asset located in: Lake Worth, TX, USA
		1082	Clark S30L 5750 lb Pneumatic Tire Forklift S/N: S232L053812000VN C/W: Located in Lane 50 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 85 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2020 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 4,072 Hr Lot closing time: Wed, Sep 16, 02:24 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1083	2017 Hyundai 30D-9 6000 lb Pneumatic Tire Forklift S/N: HHKHHN13KH0001741 C/W: Located in Lane 62, 3 Stage Mast, 185 in Max Lift Height, 86 in Lowered Mast Height, 47 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, Kubota 4 Cylinder Diesel Engine Usage: 6,218 Hr Lot closing time: Wed, Sep 16, 02:24 PM CDT Asset located in: Humble, TX, USA	1085D	2015 Toyota 8FGCU25 4500 lb Forklift S/N: 70223 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2015 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 2,884 Hr Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Lake Worth, TX, USA
1084	2016 Toyota 8FGCU30 6000 kg Pneumatic Tire Forklift S/N: 66611 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 85 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, Toyota 4YECs 4 Cylinder 38 kW 2.23 L LPG Engine Usage: Not Available Notes: Unable to confirm year, may be difficult to export Lot closing time: Wed, Sep 16, 02:24 PM CDT Asset located in: Lake Worth, TX, USA	1085E	2019 Toyota 8FGU25 4500 lb Forklift S/N: 98082 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 198 in Max Lift Height, 86 in Lowered Mast Height, 42 in Forks, Side Shift, 2019 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 2,425 Hr Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Lake Worth, TX, USA
1084A	2021 Toyota 8FDU25 4850 lb Forklift S/N: C0619 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Toyota 3 Cylinder Engine Usage: 7,003 Hr Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Lake Worth, TX, USA	1085F	2011 Toyota 8FGU25 4500 lb Forklift S/N: 38117 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2011 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Humble, TX, USA
1085A	2020 Toyota 8FGCU25 4500 lb Forklift S/N: C0227 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, US EPA Label, Toyota 4 Cylinder LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Lake Worth, TX, USA	1087	2013 Mitsubishi FD25N-D Pneumatic Tire Forklift S/N: AF18C30479 C/W: Located in Lane 61, 3 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder 3.3 L Diesel Engine Usage: 124 Hr Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Humble, TX, USA
1085B	2020 Toyota 8FGCU25 4500 lb Forklift S/N: C0057 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, US EPA Label, Toyota 4 Cylinder LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Lake Worth, TX, USA	1087A	2012 Toyota 8FGCU25 4800 lb Cushion Tire Forklift S/N: 38796 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2012 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 2,796 Hr Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Lake Worth, TX, USA
1085C	2019 Toyota 8FGCU25 4500 lb Forklift S/N: 99142 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, US EPA Label, Toyota 4 Cylinder LPG Engine Usage: 5,402 Hr Lot closing time: Wed, Sep 16, 02:25 PM CDT Asset located in: Lake Worth, TX, USA	1087B	2016 Toyota 8FDU25 4500 lb Pneumatic Tire Forklift S/N: 61198 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:26 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1087C	2018 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 86090 C/W: Located in Lane 51 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, 2018 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:26 PM CDT Asset located in: Lake Worth, TX, USA	1093	2021 Doosan G25N-7 4600 lb Forklift S/N: FGA14-1290-05504 C/W: 2 Stage Mast, 189 in Max Lift Height, 85 in Lowered Mast Height, 41 in Forks, Side Shift, 2021 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:27 PM CDT Asset located in: Lake Worth, TX, USA
1087D	2018 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 91319 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, US EPA Label, Toyota 4 Cylinder LPG Engine Usage: 5,128 Hr Lot closing time: Wed, Sep 16, 02:26 PM CDT Asset located in: Lake Worth, TX, USA	1094	2021 Doosan G25N-7 4600 lb Forklift S/N: FGA14-1290-04720 C/W: 2 Stage Mast, 189 in Max Lift Height, 85 in Lowered Mast Height, 41 in Forks, Side Shift, 2020 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 3,851 Hr Lot closing time: Wed, Sep 16, 02:27 PM CDT Asset located in: Lake Worth, TX, USA
1087E	2013 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 50781 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Toyota LPG Engine Usage: 4,033 Hr Lot closing time: Wed, Sep 16, 02:26 PM CDT Asset located in: Lake Worth, TX, USA	1095	2021 Doosan GC25S-9 4600 lb Cushion Tire Forklift S/N: FGA1E-1290-01217 C/W: 2 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, 2020 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 4,423 Hr Lot closing time: Wed, Sep 16, 02:28 PM CDT Asset located in: Lake Worth, TX, USA
1090	Doosan D25 S-5 4600 lb Pneumatic Tire Forklift S/N: FDA2B525000733 C/W: Located in Lane 50 Spot 1, 2 Stage Mast, 189 in Max Lift Height, 85 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 2022 US EPA Label, Doosan 4 Cylinder Diesel Engine Usage: 5,068 Hr Lot closing time: Wed, Sep 16, 02:26 PM CDT Asset located in: Lake Worth, TX, USA	1096	2021 Doosan GC25S-9 4600 lb Cushion Tire Forklift S/N: FGA1E-1290-01220 C/W: 2 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, 2020 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 4,155 Hr Lot closing time: Wed, Sep 16, 02:28 PM CDT Asset located in: Lake Worth, TX, USA
1090A	Doosan GC25S-9 4600 lb Cushion Tire Forklift S/N: FGA1E-1290-01365 C/W: 2 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 41 in Forks, Side Shift, 2020 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:27 PM CDT Asset located in: Lake Worth, TX, USA	1097	2021 Doosan GC25S-9 4600 lb Cushion Tire Forklift S/N: FGA1E-1290-01218 C/W: 2 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, 2020 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 4,054 Hr Lot closing time: Wed, Sep 16, 02:28 PM CDT Asset located in: Lake Worth, TX, USA
1092	2023 Doosan G25E-7 4600 lb Pneumatic Tire Forklift S/N: FGA1M-1290-04886 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Solid Pneumatic Tires, 2023 US EPA Label, ATECH LPG Engine Usage: 1,734 Hr Lot closing time: Wed, Sep 16, 02:27 PM CDT Asset located in: Humble, TX, USA	1097A	2018 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 98191 C/W: 3 Stage Mast, 198 in Max Lift Height, 86 in Lowered Mast Height, 48 in Forks, Side Shift, 2019 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:28 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1098A	2016 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 74801 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, 2016 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 5,467 Hr Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA	1100	2000 Mitsubishi FG25 4400 lb Pneumatic Tire Forklift S/N: AF17B11028 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 188 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: 4,113 Hr Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA
1098B	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 66174 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 1,736 Hr Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA	1100A	2014 Toyota 8FGU25 3750 lb Pneumatic Tire Forklift S/N: 53194 C/W: Located in Lane 51 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA
1098C	2015 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 70218 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2015 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 2,367 Hr Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA	1100B	2014 Toyota 8FGU25 3750 lb Pneumatic Tire Forklift S/N: 53322 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4 Cylinder LPG Engine Usage: 2,563 Hr Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA
1099	2011 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 34044 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 85 in Lowered Mast Height, 72 in Forks, Side Shift, Solid Pneumatic Tires, 2011 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L Dual Fuel Engine Usage: 10,838 Hr Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA	1101	2019 Toyota 8FGU15 2500 lb Pneumatic Tire Forklift S/N: 66400 C/W: 3 Stage Mast, 189 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4 Cylinder 2.237 L LPG Engine Usage: 6,318 Hr Lot closing time: Wed, Sep 16, 02:30 PM CDT Asset located in: Midland, TX, USA
1099A	2007 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 11583 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, 2007 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 2,146 Hr Lot closing time: Wed, Sep 16, 02:29 PM CDT Asset located in: Lake Worth, TX, USA	1102	Mitsubishi 3000 lb Cushion Tire Forklift S/N: AF81A51468 C/W: Located in Lane 53 Spot 1, 2 Stage Mast, 130 in Max Lift Height, 82 in Lowered Mast Height, 40 in Forks, Side Shift Usage: 5,855 Hr Lot closing time: Wed, Sep 16, 02:30 PM CDT Asset located in: Lake Worth, TX, USA
		1103	Toyota 05-8FBM40T 7959 lb Electric Forklift S/N: 8FBMT40-10015 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 118.1 in Max Lift Height, Side Shift, 80 V, Battery Watering System, Battery Charger Usage: Not Available Lot closing time: Wed, Sep 16, 02:30 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1104	Toyota 05-8FBM25T 5000 lb Electric Forklift S/N: 058FBM25T-10198 C/W: Located in Lane 53 Spot 1, Enclosed Cab, 3 Stage Mast, Full Free Lift, 118.1 in Max Lift Height, 80 in Lowered Mast Height, Side Shift, 80 V, Battery Charger Usage: Not Available Lot closing time: Wed, Sep 16, 02:30 PM CDT Asset located in: Lake Worth, TX, USA	1108C	2012 Toyota 8FBCU25 4400 lb Electric Forklift S/N: 62784 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, Side Shift, 36 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:32 PM CDT Asset located in: Lake Worth, TX, USA
1105	2020 Hyster ERC050VG 4750 lb Electric Forklift S/N: A268N30533U C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 194 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Fork Positioner Usage: Not Available Lot closing time: Wed, Sep 16, 02:31 PM CDT Asset located in: Lake Worth, TX, USA	1109	2023 Toyota 8FBCHU25 4500 lb Electric Forklift S/N: 68995 C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 48 V Usage: 5,654 Hr Lot closing time: Wed, Sep 16, 02:32 PM CDT Asset located in: Livingston, LA, USA
1106	2020 Hyster ERC050VG 4750 lb Electric Forklift S/N: A268N30520U C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 194 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Fork Positioner Usage: Not Available Lot closing time: Wed, Sep 16, 02:31 PM CDT Asset located in: Lake Worth, TX, USA	1110	2023 Toyota 8FBCHU25 4500 lb Electric Forklift S/N: 68990 C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 48 V Usage: 3,851 Hr Lot closing time: Wed, Sep 16, 02:32 PM CDT Asset located in: Livingston, LA, USA
1107	2020 Hyster ERC050VG 4750 lb Electric Forklift S/N: A268N30525U C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 194 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Fork Positioner Usage: Not Available Lot closing time: Wed, Sep 16, 02:31 PM CDT Asset located in: Lake Worth, TX, USA	1111	2023 Toyota 8FBCHU25 4500 lb Electric Forklift S/N: 68801 C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 48 V Usage: 7,753 Hr Lot closing time: Wed, Sep 16, 02:33 PM CDT Asset located in: Livingston, LA, USA
1108	2020 Hyster ERC050VG 4750 lb Electric Forklift S/N: A268N30524U C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 194 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Fork Positioner Usage: Not Available Lot closing time: Wed, Sep 16, 02:32 PM CDT Asset located in: Lake Worth, TX, USA	1112	2013 Toyota 8FBCU25 4400 lb Electric Forklift S/N: 65878 C/W: Located in Lane 46, 3 Stage Mast, 189 in Max Lift Height, 81 in Lowered Mast Height, Auxiliary Hydraulic Plumbing, 36 V, Battery Watering System Usage: Not Available Lot closing time: Wed, Sep 16, 02:33 PM CDT Asset located in: Humble, TX, USA
1108A	2015 Toyota 8FBCU25 4600 lb Electric Forklift S/N: 69278 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 218 in Max Lift Height, 92 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 36 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:32 PM CDT Asset located in: Lake Worth, TX, USA	1113	2026 STARVOX CPD-20 4400 lb Electric Forklift (Unused) S/N: DLK2026-6864 C/W: Located in Lane 47 Spot 0, 2 Stage Mast, 118 in Max Lift Height, 48 in Forks, 60 V, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 02:33 PM CDT Asset located in: Humble, TX, USA
1108B	2018 Toyota 8FBCU25 4400 lb Electric Forklift S/N: 78314 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 46 in Forks, Side Shift, 36 V Usage: 18,345 Hr Lot closing time: Wed, Sep 16, 02:32 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
1114	2016 Crown SC5225-35 Electric Forklift S/N: 9A231358 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 83 in Lowered Mast Height, 42 in Forks, 36 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:33 PM CDT Asset located in: Lake Worth, TX, USA	1125	2023 Toyota 8FBE20U 3220 lb Electric Forklift S/N: 30341 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 94 in Lowered Mast Height, 60 in Forks, Side Shift, 36 V, Battery Watering System, Battery Charger Usage: 2,322 Hr Lot closing time: Wed, Sep 16, 02:37 PM CDT Asset located in: Lake Worth, TX, USA
1115	Crown 3500 lb Electric Forklift S/N: 1A356292 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 198 in Max Lift Height, 89 in Lowered Mast Height, 42 in Forks, 36 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:34 PM CDT Asset located in: Lake Worth, TX, USA	1128	2021 Toyota 8FBE20U 3220 lb Electric Forklift S/N: 22933 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 94 in Lowered Mast Height, 60 in Forks, Side Shift, 36 V, Battery Watering System, Battery Charger Usage: 5,741 Hr Lot closing time: Wed, Sep 16, 02:38 PM CDT Asset located in: Lake Worth, TX, USA
1117	Toyota 8BNCU18 3500 lb Electric Forklift S/N: 8BNCU18-56153 C/W: Located in Lane 52 Spot 1, 4 Stage Mast, 276.5 in Max Lift Height, 96 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:34 PM CDT Asset located in: Lake Worth, TX, USA	1129	2021 Toyota 8FBE20U 3220 lb Electric Forklift S/N: 23888 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 94 in Lowered Mast Height, 60 in Forks, Side Shift, 36 V, Battery Watering System, Battery Charger Usage: 5,071 Hr Lot closing time: Wed, Sep 16, 02:38 PM CDT Asset located in: Lake Worth, TX, USA
1118	Toyota 8BNCU18 3500 lb Electric Forklift S/N: 8BNCU18-56147 C/W: Located in Lane 52 Spot 1, 4 Stage Mast, 276.5 in Max Lift Height, 96 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: 13,306 Hr Lot closing time: Wed, Sep 16, 02:35 PM CDT Asset located in: Lake Worth, TX, USA	1130	2021 Toyota 8FBE20U 3220 lb Electric Forklift S/N: 22924 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 94 in Lowered Mast Height, 60 in Forks, Side Shift, 36 V, Battery Watering System, Battery Charger Usage: 4,587 Hr Lot closing time: Wed, Sep 16, 02:38 PM CDT Asset located in: Lake Worth, TX, USA
1119	Toyota 8BNCU18 3500 lb Reach Truck S/N: 8BNCU18-56300 C/W: 3 Stage Mast, 244 in Max Lift Height, 83 in Lowered Mast Height, Side Shift, 36 V Usage: 12,452 Hr Lot closing time: Wed, Sep 16, 02:35 PM CDT Asset located in: Lake Worth, TX, USA	1130A	2019 Toyota 8FBE20U 3450 lb Electric Forklift S/N: 18081 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:38 PM CDT Asset located in: Lake Worth, TX, USA
1120	Toyota 8BNCU18 3500 lb Electric Forklift S/N: 56301 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, 36 V, Battery Watering System Usage: Not Available Lot closing time: Wed, Sep 16, 02:35 PM CDT Asset located in: Lake Worth, TX, USA	1130B	2016 Toyota 8FBE20U Electric Forklift S/N: 12438 C/W: Located in Lane 52 Spot 1, 3 Stage Mast, 93 in Lowered Mast Height, Side Shift, Fork Positioner, 36 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:38 PM CDT Asset located in: Lake Worth, TX, USA
1121	2023 Toyota 8FBE20U 3220 lb Electric Forklift S/N: 30401 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 94 in Lowered Mast Height, 60 in Forks, Side Shift, 36 V, Battery Watering System, Battery Charger Usage: 3,364 Hr Lot closing time: Wed, Sep 16, 02:36 PM CDT Asset located in: Lake Worth, TX, USA	1132	2022 Toyota 8FBE15U 2600 lb Electric Forklift S/N: 25165 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 85 in Lowered Mast Height, 42 in Forks, Side Shift, 48 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:39 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1132A	1991 Toyota 2FBE15 2800 lb Electric Forklift S/N: 2FBE1520515 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V, Battery Charger Usage: 5,060 Hr Lot closing time: Wed, Sep 16, 02:39 PM CDT Asset located in: Lake Worth, TX, USA	1149	2019 Yale MPE060LVHN24T2748 6000 lb Electric Pallet Jack S/N: C292N01846T C/W: Self-Propelled, 24 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:44 PM CDT Asset located in: Lake Worth, TX, USA
1133	2022 Doosan BOP15S-9 800 lb Order Picker S/N: FOA01-5052-00227 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, Full Free Lift, 240 in Max Lift Height, 108 in Lowered Mast Height, 42 in Forks, 24 V Usage: 732 Hr Lot closing time: Wed, Sep 16, 02:39 PM CDT Asset located in: Humble, TX, USA	1150	2019 Yale MPE060LVHN24T2748 6000 lb Electric Pallet Jack S/N: C292N01847T C/W: Self-Propelled, 24 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:44 PM CDT Asset located in: Lake Worth, TX, USA
1134	2022 Doosan BOP15S-9 800 lb Order Picker S/N: FOA01-5052-00206 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, Full Free Lift, 240 in Max Lift Height, 108 in Lowered Mast Height, 42 in Forks, 24 V Usage: 830 Hr Lot closing time: Wed, Sep 16, 02:39 PM CDT Asset located in: Humble, TX, USA	1151	2019 Yale MPE060LVHN24T2748 6000 lb Electric Pallet Jack S/N: C292N01843T C/W: Self-Propelled, 24 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:45 PM CDT Asset located in: Lake Worth, TX, USA
1135	2022 Doosan BOP15S-9 800 lb Order Picker S/N: FOA01-5052-00228 C/W: Located in Lane 61 Spot 0, 3 Stage Mast, 240 in Max Lift Height, 108 in Lowered Mast Height, 42 in Forks, 24 V Usage: 1,493 Hr Lot closing time: Wed, Sep 16, 02:40 PM CDT Asset located in: Humble, TX, USA	1152	2019 Yale MPE060LVHN24T2748 6000 lb Electric Pallet Jack S/N: C292N01845T C/W: Self-Propelled, 24 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:45 PM CDT Asset located in: Lake Worth, TX, USA
1146	2026 STARVOX CBD-30 6600 lb Electric Pallet Jack (Unused) S/N: 20260228245 C/W: 48 V, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 02:43 PM CDT Asset located in: Humble, TX, USA	1152A	2019 Yale MPB045VGN24T264 4510 lb Electric Pallet Jack S/N: A245N26657U C/W: Self-Propelled, 24 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:45 PM CDT Asset located in: Lake Worth, TX, USA
1147	2026 STARVOX CBD-30 6600 lb Electric Pallet Jack (Unused) S/N: 20260228246 C/W: 48 V, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Wed, Sep 16, 02:43 PM CDT Asset located in: Humble, TX, USA	1153	Quantity of (6) Pallet Jack S/N: Not Available Usage: Not Available Lot closing time: Wed, Sep 16, 02:45 PM CDT Asset located in: Lake Worth, TX, USA
1148	2019 Yale MPE060LVHN24T2748 6000 lb Electric Pallet Jack S/N: C292N01844T C/W: Self-Propelled, 24 V Usage: Not Available Lot closing time: Wed, Sep 16, 02:44 PM CDT Asset located in: Lake Worth, TX, USA	1154	Quantity of (6) Pallet Jack S/N: Not Available Usage: Not Available Lot closing time: Wed, Sep 16, 02:45 PM CDT Asset located in: Lake Worth, TX, USA
		1155	2019 Manitou TMT55 5500 lb 3x3 Truck Mounted Forklift S/N: 880571 C/W: Located in Lane 52 Spot 1, 2 Stage Mast, 135 in Max Lift Height, 48 in Forks, 2019 US EPA Label, Kubota D1803 3 Cylinder 1.8 L Diesel Engine Usage: 1,462 Hr Lot closing time: Wed, Sep 16, 02:46 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1158	2019 Genie SX-125XC 4WD Diesel Telescopic Boom Lift S/N: SX125D-755 C/W: Located in Lane 27 Spot 7, 125 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2018 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 74 hp 2.92 L Diesel Engine, 445/50D710 Tires Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:47 PM CDT Asset located in: Lake Worth, TX, USA	1164	2021 Genie S-80 XC 4WD Diesel Telescopic Boom Lift S/N: S80XCH-2625 C/W: Located in Lane 27 Spot 10, 80 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2021 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 55.4 kW 2.92 L Diesel Engine, 18-625 NHS Tires Usage: Not Available Notes: ; aerial units require proper safety harness, lanyard, and ppe to function test and load Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 02:48 PM CDT Asset located in: Lake Worth, TX, USA
1160	2019 Genie SX-125XC 4WD Diesel Telescopic Boom Lift S/N: SX125D-759 C/W: Located in Lane 29 Spot 10, 125 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2018 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 74 hp 2.92 L Diesel Engine, 445/50D710 Tires Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:47 PM CDT Asset located in: Lake Worth, TX, USA	1167	2014 Genie S-80X 4WD Diesel Telescopic Boom Lift S/N: S80X14-11623 C/W: Located in Lane 28 Spot 12, 80 ft Max Platform Height, 1000 lb Max Weight Capacity, 2014 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 74 hp 2.92 L Diesel Engine, 18-625 NHS Tires Usage: Not Available Notes: ; aerial units require proper safety harness, lanyard, and ppe to function test and load Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 02:49 PM CDT Asset located in: Lake Worth, TX, USA
1161	2017 Skyjack SJ86T 4WD Diesel Telescopic Boom Lift S/N: 97100370 C/W: 86 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, CARB Compliant, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Tires Usage: 4,201 Hr Notes: Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:48 PM CDT Asset located in: Lake Worth, TX, USA	1173	2016 Genie S-80X 4WD Diesel Telescopic Boom Lift S/N: S80X16H-13598 C/W: Located in Lane 110 Spot 2, 80 ft Max Platform Height, 1000 lb Max Weight Capacity, 2015 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 74 hp 2.92 L Diesel Engine, 18-625 NHS Tires Usage: 7,804 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:51 PM CDT Asset located in: Lake Worth, TX, USA
1163	2012 JLG 860SJ 4WD Diesel Telescopic Boom Lift S/N: 0300154478 C/W: Located in Lane 72, 86 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2011 US EPA Label, Deutz D2011L04 4 Cylinder 62 hp 3.619 L Diesel Engine, 15-625 NHS Tires Usage: 7,514 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:48 PM CDT Asset located in: Humble, TX, USA	1176A	2011 Genie S-80X Telescopic Boom Lift S/N: S80X11-8850 C/W: 2011 US EPA Label, Deutz TD-2011L04I 4 Cylinder 74 hp 3.6 L Diesel Engine, 18-625 Tires Usage: 6,327 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:52 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
1178	2010 Genie S-80X 4WD Diesel Telescopic Boom Lift S/N: S80X108510 C/W: Located in Lane 26, 80 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Deutz TD2011L04I 4 Cylinder Diesel Engine, 18-625 Tires Usage: 13,381 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:53 PM CDT Asset located in: Lake Worth, TX, USA	1186	2016 Snorkel 660SJ 4WD Diesel Telescopic Boom Lift S/N: 660SJ-11-161200022 C/W: Located in Lane 71 Spot 2, 66 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Kubota V2403-M-T-ET05 4 Cylinder 44 kW 2.4 L Diesel Engine, 355/55D625 Foam-Filled Tires Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:55 PM CDT Asset located in: Humble, TX, USA
1181	2018 Genie S-65TraX Crawler Diesel Telescopic Boom Lift S/N: S60TXH-38806 C/W: Located in Lane 71, 56 ft 2 in Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2018 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 17" Tracks Tires Usage: 3,776 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:54 PM CDT Asset located in: Humble, TX, USA	1187	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300233225 C/W: Located in Lane 71, 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Foam-Filled Tires Usage: 1,391 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:55 PM CDT Asset located in: Humble, TX, USA
1183	2017 JLG 660 SJC Crawler Diesel Telescopic Boom Lift S/N: 300238271 C/W: Located in Lane 71, 65 ft 6 in Max Platform Height, 550 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, Tracks Tires Usage: 3,408 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:54 PM CDT Asset located in: Humble, TX, USA	1191	2014 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300192857 C/W: Located in Lane 110 Spot 2, 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz TD2.9 L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Solid Tires Usage: 4,543 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:57 PM CDT Asset located in: Lake Worth, TX, USA
1185	2013 Haulotte HT67RTJ 4WD Diesel Telescopic Boom Lift S/N: TD500036 C/W: Located in Lane 72, 67 ft 7 in Max Platform Height, 500 lb Max Weight Capacity, Jib, Kubota V2403 4 Cylinder 36.5 kW Diesel Engine, 385/65-22.5 Foam-Filled Tires Usage: 910 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:55 PM CDT Asset located in: Humble, TX, USA	1192	2014 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300191850 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine Usage: 2,348 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:57 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
1196	2019 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S60D-2137 C/W: Located in Lane 28 Spot 10, 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.92 L Diesel Engine, 355/55D625 Tires Usage: 2,547 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:58 PM CDT Asset located in: Lake Worth, TX, USA	1200A	2017 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300236573 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 67 hp 2.92 L Diesel Engine, 355/55D625 Tires Usage: 7,139 Hr Lot closing time: Wed, Sep 16, 02:59 PM CDT Asset located in: Lake Worth, TX, USA
1198	2018 Genie S65 4WD Diesel Telescopic Boom Lift S/N: S60D1155 C/W: Located in Lane 110 Spot 2, 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.92 L Diesel Engine, 355/55S625 Tires Usage: 5,569 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:59 PM CDT Asset located in: Lake Worth, TX, USA	1201	2017 MEC 60-J Diesel 4WD Diesel Telescopic Boom Lift S/N: 14400196 C/W: Located in Lane 71, 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, Kubota 4 Cylinder 1.5 L Diesel Engine, 316/55D20 Foam-Filled Tires Usage: 2,882 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:00 PM CDT Asset located in: Humble, TX, USA
1199	2018 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S60H38940 C/W: Located in Lane 110 Spot 2, 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355/55D625 Tires Usage: 6,673 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:59 PM CDT Asset located in: Lake Worth, TX, USA	1208	2011 Genie S60X 4WD Diesel Telescopic Boom Lift S/N: S601121348 C/W: Located in Lane 28, 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2010 US EPA Label, Deutz D2011L03I 3 Cylinder 49 hp 2.3 L Diesel Engine, 355 /55D625 Tires Usage: 14,169 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:02 PM CDT Asset located in: Lake Worth, TX, USA
1200	2018 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S60H38849 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355/55D625 Tires Usage: 6,154 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 02:59 PM CDT Asset located in: Lake Worth, TX, USA	1209	2010 Genie S-60X 4WD Diesel Telescopic Boom Lift S/N: S60X10-21002 C/W: Located in Lane 28 Spot 4, 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, US EPA Label, Deutz 3 Cylinder 49 hp 2.3 L Diesel Engine, 355 /55D625 Solid Tires Usage: 12,321 Hr Notes: ; aerial units require proper safety harness, lanyard, and ppe to function test and load Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 03:02 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1212	2006 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300091986 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Onboard Generator, 2008 US EPA Label, Deutz F4m2011 4 Cylinder 48.5 kW 3.1 L Diesel Engine, 15-19.5 Tires Usage: 3,734 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:03 PM CDT Asset located in: Midland, TX, USA	1217	2016 Skyjack SJ45T 4WD Diesel Telescopic Boom Lift S/N: 98001840 C/W: Located in Lane 28 Spot 11, 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 2.9 L Diesel Engine, 305/70D16.5 Tires Usage: 3,519 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:04 PM CDT Asset located in: Lake Worth, TX, USA
1213	2006 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 300102438 C/W: Located in Lane 27 Spot 2, 60 ft Max Platform Height, Power to Platform, Onboard Generator, Deutz F 4M 2011 4 Cylinder Diesel Engine, 15-19.5 Tires Usage: 1,744 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:03 PM CDT Asset located in: Lake Worth, TX, USA	1217A	2012 Genie S-45 4WD Diesel Telescopic Boom Lift S/N: S4512-16543 C/W: Located in Lane 72, 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2011 US EPA Label, Deutz D2011L03L 3 Cylinder 49 hp 2.3 L Diesel Engine, 12-16.5 Tires Usage: 5,386 Hr Lot closing time: Wed, Sep 16, 03:04 PM CDT Asset located in: Humble, TX, USA
1214	2006 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300097325 C/W: Located in Lane 71 Spot 0, 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Cat 4 Cylinder Diesel Engine, 15-19.5 NHS Tires Usage: 6,454 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:03 PM CDT Asset located in: Humble, TX, USA	1218A	2019 Genie S-40 4WD Diesel Telescopic Boom Lift S/N: S40H-27249 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2018 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.92 L Diesel Engine, 12-16.6 Tires Usage: 1,508 Hr Lot closing time: Wed, Sep 16, 03:05 PM CDT Asset located in: Lake Worth, TX, USA
1215	2005 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300086394 C/W: Located in Lane 100 Spot 1, 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Deutz 4 Cylinder Diesel Engine, 15-19.5 Tires Usage: 3,785 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:04 PM CDT Asset located in: Lake Worth, TX, USA	1224	2018 Genie Z-80/60 4WD Diesel Articulating Boom Lift S/N: Z80H7284 C/W: Located in Lane 101 Spot 1, 78 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 74 hp 2.92 L Diesel Engine, 18-625 Tires Usage: 1,070 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:06 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1227	2023 Teupen TC60AJ Crawler Diesel Articulating Boom Lift S/N: L18GTP0047 C/W: 60 ft Max Platform Height, 441 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2022 US EPA Label, Kubota Z602-EF03 2 Cylinder 10.6 kW Diesel Engine Usage: 405 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:07 PM CDT Asset located in: Livingston, LA, USA	1231	2017 JLG 600AJ 4WD Diesel Articulating Boom Lift S/N: 0300233768 C/W: Located in Lane 72 Spot 19, 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Tires Usage: 2,343 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:09 PM CDT Asset located in: Humble, TX, USA
1228	2016 Teupen TL69A Crawler Electric Articulating Boom Lift S/N: 10000958 C/W: Located in Lane 71, Power to Platform Usage: 2,406 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:08 PM CDT Asset located in: Humble, TX, USA	1232	2017 MEC 60-J 4WD Diesel Articulating Boom Lift S/N: 14400227 C/W: Located in Lane 71 Spot 0, 60 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, Kubota V1505-T-ET03 4 Cylinder 33 kW 1.5 L Diesel Engine, 315/55D20 Foam-Filled Tires Usage: 3,027 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:09 PM CDT Asset located in: Humble, TX, USA
1229	2019 Genie Z-62/40 4WD Diesel Articulating Boom Lift S/N: Z62H4519 C/W: 61 ft 11 in Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2019 US EPA Label, Deutz D2.9L4 4 Cylinder 2.9 L Diesel Engine, 355/55D625 Tires Usage: 447 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:08 PM CDT Asset located in: Lake Worth, TX, USA	1233	2017 MEC 60J-D 4WD Diesel Articulating Boom Lift S/N: 14400226 C/W: Located in Lane 72 Spot 17, 60 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, Kubota V1505 4 Cylinder 33 kW 1.5 L Diesel Engine, 315/55D20 NHS Foam-Filled Tires Usage: 2,952 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:09 PM CDT Asset located in: Humble, TX, USA
1230	2022 Snorkel AB60J 4WD Diesel Articulating Boom Lift S/N: AB60J-04-220300325 C/W: Located in Lane 72 Spot 25, 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2021 US EPA Label, Kubota V2403 4 Cylinder 47.9 kW 2.4 L Diesel Engine, 15-19.5 NHS Tires Usage: 71 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:08 PM CDT Asset located in: Humble, TX, USA	1234	2022 Snorkel A46JRT 2WD Diesel Articulating Boom Lift S/N: A46JRT04220701380 C/W: Located in Lane 27 Spot 3, 47 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2021 US EPA Label, Kubota V1505-EF01 4 Cylinder 18.2 kW 1.5 L Diesel Engine, 355/55D625 Tires Usage: 180 Hr Notes: ; aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:09 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1235	2018 Snorkel A46JE 2WD Electric Articulating Boom Lift S/N: A46JE04180100391 C/W: Located in Lane 71 Spot 20, 46.4 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 240/55D17.5 Non-Marking Tires Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:10 PM CDT Asset located in: Humble, TX, USA	1243	Haulotte HA46RTJO 4WD Diesel Articulating Boom Lift S/N: 2048565 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2018 US EPA Label, Kubota V1505-EF01e 4 Cylinder 18.2 kW 1.5 L Diesel Engine, 850-340 Aperture Tires Usage: 3,528 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:12 PM CDT Asset located in: Lake Worth, TX, USA
1236	2017 Skyjack SJ46AJ 4WD Diesel Articulating Boom Lift S/N: 95002170 C/W: Located in Lane 0 Spot 0, 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz D2.9L4 4 Cylinder 2.9 L Diesel Engine, 305/70D16.5NHS Foam-Filled Tires Usage: 1,092 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:10 PM CDT Asset located in: Humble, TX, USA	1250	2018 Snorkel A38E 2WD Electric Articulating Boom Lift S/N: A38E-01-180700802 C/W: Located in Lane 71, 37 ft 6 in Max Platform Height, 475 lb Max Weight Capacity, Power to Platform, 22x9x16 Non-Marking Tires Usage: 231 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:14 PM CDT Asset located in: Humble, TX, USA
1240	2018 JLG 450AJ 4WD Diesel Articulating Boom Lift S/N: 0300252238 C/W: Located in Lane 71, 45 ft Max Platform Height, 550 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2018 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 33x15.50-16.5NHS Foam-Filled Tires Usage: 410 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:11 PM CDT Asset located in: Humble, TX, USA	1251	2017 Genie Z-34/22N 2WD Electric Articulating Boom Lift S/N: Z34NF14286 C/W: Located in Lane 110 Spot 2, 34 ft 6 in Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22x7x17-3/4 Non-Marking Tires Usage: 244 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:15 PM CDT Asset located in: Lake Worth, TX, USA
1241	2007 JLG 450A 4WD Articulating Boom Lift S/N: 0300120095 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 4 Cylinder Diesel Engine, 33X15.50-16.5 Tires Usage: 2,815 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:12 PM CDT Asset located in: Livingston, LA, USA	1252	2019 Haulotte HA32CJ+ 2WD Electric Articulating Boom Lift S/N: 2062494 C/W: Located in Lane 52 Spot 1, 31 ft 1 in Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 600x190 Non-Marking Tires Usage: 266 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:15 PM CDT Asset located in: Lake Worth, TX, USA
		1254	2016 JLG T500J Towable Lift S/N: 5DYACJ1J2GP007326 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Honda 1 Cylinder Gasoline Engine Usage: 1,264 Hr Lot closing time: Wed, Sep 16, 03:15 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1255	2020 JLG T350 Towable Lift S/N: 0030012427 C/W: Located in Lane 71, 35 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 128 Hr Lot closing time: Wed, Sep 16, 03:16 PM CDT Asset located in: Humble, TX, USA	1267	2014 Genie GS3246 Electric Scissor Lift S/N: GS4614A135007 C/W: Located in Lane 69, 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:19 PM CDT Asset located in: Humble, TX, USA
1256	2016 Haulotte/Bil-Jax 4527A Towable Lift S/N: 5CUAJ2012GA000116 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: Not Available Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 03:16 PM CDT Asset located in: Lake Worth, TX, USA	1268	2022 Skyjack SJ 4732 Electric Scissor Lift S/N: A102006155 C/W: 31 ft 8 in Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:20 PM CDT Asset located in: Lake Worth, TX, USA
1258	2012 Skyjack SJ9250 4x4 Dual Fuel Scissor Lift S/N: 50000870 C/W: Located in Lane 55 Spot 45, 50 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2012 US EPA Label, GM GM-1.6L 4 Cylinder 1.6 L Dual Fuel Engine Usage: 3,011 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:17 PM CDT Asset located in: Lake Worth, TX, USA	1269	2013 Genie GS3246 Electric Scissor Lift S/N: GS4613A111713 C/W: Located in Lane 36 Spot 0, 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 141 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:20 PM CDT Asset located in: Humble, TX, USA
1261	2018 Snorkel S2770RTV7 Diesel Scissor Lift S/N: S2770RT07180500510 C/W: 27 ft Max Platform Height, 1280 lb Max Weight Capacity, Platform Extension, Upper Control Box, Tier 4, 2018 US EPA Label, Kubota 3 Cylinder .89 L Diesel Engine Usage: 889 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:18 PM CDT Asset located in: Lake Worth, TX, USA	1269A	2015 Genie GS-3232 Electric Scissor Lift S/N: GS3215A137916 C/W: Located in Lane 55, 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:20 PM CDT Asset located in: Lake Worth, TX, USA
1262	2014 Genie GS-5390 4x4 Diesel Scissor Lift S/N: GS901449971 C/W: Located in Lane 55 Spot 1, 53 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2014 US EPA Label, Deutz 4 Cylinder 2.9 L Diesel Engine Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:18 PM CDT Asset located in: Lake Worth, TX, USA	1272	2018 Snorkel S4726E Scissor Lift S/N: S4726E04181101016 C/W: Located in Lane 55 Spot 1, 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 65,535 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:21 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1273	2021 JCB S3246 Electric Scissor Lift S/N: RAJA0603CM5312623 C/W: Located in Lane 55 Spot 1, 32 ft Max Platform Height, 500 lb Max Weight Capacity, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:21 PM CDT Asset located in: Lake Worth, TX, USA	1280	2023 Snorkel S3226E Electric Scissor Lift S/N: S3226E04230102916 C/W: Located in Lane 69 Spot 0, 26 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:23 PM CDT Asset located in: Humble, TX, USA
1275	2015 Skyjack SJ4632 Electric Scissor Lift S/N: 70025469 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 226 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:22 PM CDT Asset located in: Lake Worth, TX, USA	1281	2023 Snorkel S3226E ANSI Electric Scissor Lift S/N: S3226E04230102915 C/W: Located in Lane 69 Spot 0, 26 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:24 PM CDT Asset located in: Humble, TX, USA
1277	2019 JLG 4069LE Electric Scissor Lift S/N: M200033340 C/W: 30 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 371 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:22 PM CDT Asset located in: Humble, TX, USA	1282	2023 Snorkel S3226E Electric Scissor Lift S/N: S3226E04230102918 C/W: Located in Lane 69 Spot 0, 26 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:24 PM CDT Asset located in: Humble, TX, USA
1278	2016 Skyjack SJ4626 Electric Scissor Lift S/N: 70030802 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box Usage: 368 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:23 PM CDT Asset located in: Lake Worth, TX, USA	1282A	2023 Genie GS2632 Electric Scissor Lift S/N: GS32P-208202 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:24 PM CDT Asset located in: Lake Worth, TX, USA
1279	2017 JLG 2632ES Electric Scissor Lift S/N: M200013057 C/W: 25 ft 5 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 528 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:23 PM CDT Asset located in: Lake Worth, TX, USA	1283	2020 Skyjack SJIII 3226 Electric Scissor Lift S/N: 27047112 C/W: Located in Lane 55 Spot 1, 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 156 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:24 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1284	2019 Skyjack SJIII 3226 Electric Scissor Lift S/N: 27044374 C/W: Located in Lane 55 Spot 1, 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 266 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:24 PM CDT Asset located in: Lake Worth, TX, USA	1289	2014 JLG 2030ES Electric Scissor Lift S/N: 0200224399 C/W: Located in Lane 55 Spot 1, 20 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 165 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:26 PM CDT Asset located in: Lake Worth, TX, USA
1285	2014 Skyjack SJ3226 Electric Scissor Lift S/N: 27022062 C/W: Located in Lane 70, 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 349 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:25 PM CDT Asset located in: Humble, TX, USA	1290	2019 JLG 1932R Electric Scissor Lift S/N: M200029511 C/W: Located in Lane 55 Spot 1, 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: 99 Hr Notes: ; aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 03:26 PM CDT Asset located in: Lake Worth, TX, USA
1286	2013 Skyjack SJIII 3226 Electric Scissor Lift S/N: 27014295 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:25 PM CDT Asset located in: Oklahoma City, OK, USA	1291	2017 JLG 1932R Electric Scissor Lift S/N: M200005752 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 308 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:27 PM CDT Asset located in: Lake Worth, TX, USA
1286A	Haulotte 2632E Electric Scissor Lift S/N: Not Available C/W: Located in Lane 73 Spot 0, 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Non-Marking Tires, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:25 PM CDT Asset located in: Humble, TX, USA	1292	2020 Genie GS-1930 Electric Scissor Lift S/N: GS30P-192762 C/W: Located in Lane 69, 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 191 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:27 PM CDT Asset located in: Humble, TX, USA
1288	2015 JLG 2632ES Electric Scissor Lift S/N: M200000292 C/W: Located in Lane 55 Spot 1, 25 ft 5 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 174 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:26 PM CDT Asset located in: Lake Worth, TX, USA	1293	2018 Genie GS-1930 Electric Scissor Lift S/N: GS30P-173103 C/W: Located in Lane 70, 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 250 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:27 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1293A	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P169291 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 365 Hr Lot closing time: Wed, Sep 16, 03:27 PM CDT Asset located in: Lake Worth, TX, USA	1297	2013 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22055167 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:28 PM CDT Asset located in: Oklahoma City, OK, USA
1294	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P-168696 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Non-Marking Tires, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:27 PM CDT Asset located in: Midland, TX, USA	1297A	2013 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22045008 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:28 PM CDT Asset located in: Oklahoma City, OK, USA
1294A	2018 JLG 1930 ES Scissor Lift S/N: M200023842 C/W: Located in Lane 55 Spot 1, 18 ft 8 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 224 Hr Lot closing time: Wed, Sep 16, 03:28 PM CDT Asset located in: Lake Worth, TX, USA	1298	2008 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22015354 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 514 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:29 PM CDT Asset located in: Livingston, LA, USA
1294B	2018 JLG 1930 ES Electric Scissor Lift S/N: M200023839 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 275 Hr Lot closing time: Wed, Sep 16, 03:28 PM CDT Asset located in: Lake Worth, TX, USA	1300	2016 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22102870 C/W: Located in Lane 55 Spot 1, 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension Usage: 304 Hr Lot closing time: Wed, Sep 16, 03:29 PM CDT Asset located in: Lake Worth, TX, USA
1295	2017 Skyjack SJ 3219 Electric Scissor Lift S/N: 22107876 C/W: Located in Lane 69 Spot 0, 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 679 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:28 PM CDT Asset located in: Humble, TX, USA	1301	2022 GMG 1530ED Electric Scissor Lift S/N: 2153001315 C/W: Located in Lane 55 Spot 1, 14 ft 7 in Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 170 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:30 PM CDT Asset located in: Lake Worth, TX, USA
1296	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22058283 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:28 PM CDT Asset located in: Oklahoma City, OK, USA		

Lot #	Details	Lot #	Details
1302	2022 GMG 1530ED Electric Scissor Lift S/N: 2153001311 C/W: Located in Lane 55 Spot 1, 15 ft Max Platform Height, 530 lb Max Weight Capacity, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:30 PM CDT Asset located in: Lake Worth, TX, USA	1308	GMG 1530ED Electric Scissor Lift S/N: Not Available C/W: Located in Lane 55 Spot 1, 15 ft Max Platform Height, Upper Control Box Usage: 52 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:32 PM CDT Asset located in: Lake Worth, TX, USA
1304	2021 GMG 1530ED Electric Scissor Lift S/N: 2153001304 C/W: Located in Lane 55 Spot 1, 15 ft Max Platform Height, 530 lb Max Weight Capacity, Upper Control Box Usage: 57 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:30 PM CDT Asset located in: Lake Worth, TX, USA	1309	2016 MEC 1330SE Electric Scissor Lift S/N: 16300322 C/W: Located in Lane 36 Spot 0, 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:32 PM CDT Asset located in: Humble, TX, USA
1305	2021 GMG 1530ED Electric Scissor Lift S/N: 2153001261 C/W: Located in Lane 55 Spot 1, 14 ft 7 in Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 143 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:31 PM CDT Asset located in: Lake Worth, TX, USA	1310	2017 JLG 36AM Vertical Mast Lift S/N: 0900037330 C/W: Located in Lane 36 Spot 0, 36 ft Max Platform Height, 300 lb Max Weight Capacity, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:32 PM CDT Asset located in: Humble, TX, USA
1306	2021 GMG 1530ED Electric Scissor Lift S/N: 2153001294 C/W: Located in Lane 55 Spot 1, 14 ft 7 in Max Platform Height, 534 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 261 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:31 PM CDT Asset located in: Lake Worth, TX, USA	1312	2018 JLG 20MVL Vertical Mast Lift S/N: 0130032439 C/W: Located in Lane 69, 19 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:33 PM CDT Asset located in: Humble, TX, USA
1307	2021 GMG 1530ED Electric Scissor Lift S/N: 2153001256 C/W: Located in Lane 100 Spot 0, 15 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 5 Hr Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:31 PM CDT Asset located in: Humble, TX, USA	1313	2022 Skyjack SJ20 Vertical Mast Lift S/N: A601000861 C/W: Located in Lane 55 Spot 1, 19 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:33 PM CDT Asset located in: Lake Worth, TX, USA
		1314	2019 Genie GR20 Vertical Mast Lift S/N: GRP54948 C/W: Located in Lane 55 Spot 1, 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:33 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1315	2019 Genie GR-20 Vertical Mast Lift S/N: GRP-54942 C/W: Located in Lane 70 Spot 1, 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:34 PM CDT Asset located in: Humble, TX, USA	1322	2016 Ballymore PS-140H-DRV-FGLS Vertical Mast Lift S/N: R-DBA160811-67 C/W: Located in Lane 69, 13 ft 8 in Max Platform Height, 650 lb Max Weight Capacity, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:36 PM CDT Asset located in: Humble, TX, USA
1316	2017 Genie GR20 Vertical Mast Lift S/N: GRP46698 C/W: Located in Lane 55 Spot 1, 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform Usage: Not Available Lot closing time: Wed, Sep 16, 03:34 PM CDT Asset located in: Lake Worth, TX, USA	1324	2000 Cat 375 kVA Skid-Mounted Generator Set S/N: 40934 C/W: 2000 US EPA Label, Cat 3406 6 Cylinder 14.6 L Diesel Engine, 375 kVA/300 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: Not Available Lot closing time: Wed, Sep 16, 03:36 PM CDT Asset located in: Lake Worth, TX, USA
1316A	2013 Genie GR-20 Vertical Mast Lift S/N: GR13-27625 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 480 Hr Notes: Aerial units require proper safety harness, lanyard, and ppe to function test and load; Lot closing time: Wed, Sep 16, 03:34 PM CDT Asset located in: Oklahoma City, OK, USA	1324A	Wacker Neuson G240 191 kW Skid-Mounted Generator Set S/N: 20082261 C/W: US EPA Label, John Deere 6068HF485T,U 6 Cylinder 6.8 L Diesel Engine, 238 kVA/191 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, /68 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles Usage: 4,380 Hr Lot closing time: Wed, Sep 16, 03:37 PM CDT Asset located in: Lake Worth, TX, USA
1318	2016 Skyjack SJ16 Electric Vertical Mast Lift S/N: 14009003 C/W: 16 ft Max Platform Height, 500 lb Max Weight Capacity, Upper Control Box Usage: 74 Hr Lot closing time: Wed, Sep 16, 03:35 PM CDT Asset located in: Lake Worth, TX, USA	1325	Cat M620KAC-006 Skid-Mounted Generator Set S/N: II-3330 C/W: Cat 6 Cylinder Diesel Engine Usage: Not Available Lot closing time: Wed, Sep 16, 03:37 PM CDT Asset located in: San Antonio, TX, USA
1319	2017 Genie GR-15 Vertical Mast Lift S/N: GRP51294 C/W: Located in Lane 55 Spot 1, 14 ft 8 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 90 Hr Lot closing time: Wed, Sep 16, 03:35 PM CDT Asset located in: Lake Worth, TX, USA	1326	Generac 99A03678-S Skid-Mounted Generator Set S/N: 2049150 C/W: 6 Cylinder Diesel Engine, 225 kVA,/ Rated Single Phase Output, 208 V / 120 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Lot closing time: Wed, Sep 16, 03:37 PM CDT Asset located in: Lake Worth, TX, USA
1320	2017 Genie GR-15 Vertical Mast Lift S/N: GRP51202 C/W: 14 ft 8 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Lot closing time: Wed, Sep 16, 03:35 PM CDT Asset located in: San Antonio, TX, USA	1327	Generac 20A00385-S Skid-Mounted Generator Set S/N: 2056582 C/W: 6 Cylinder Diesel Engine, 225 kVA,/ Rated Single Phase Output, 208 V / 120 V Rated Voltage Usage: Not Available Lot closing time: Wed, Sep 16, 03:37 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1329	2026 Kohler 60RCLB 58 kW Generator Set (Unused) S/N: 34DDHHPJ0066 C/W: Located in Lane 56, 2026 US EPA Label, Kohler KG6208 V8 6.17 cc Dual Fuel Engine, 58 kVA, /58 kW, Rated Single Phase Output, 240 V Rated Voltage Usage: Not Available Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Wed, Sep 16, 03:38 PM CDT Asset located in: Humble, TX, USA	1334	2026 World Class Silent Generator 32 kW Skid-Mounted Generator Set (Unused) S/N: 33KW2605031258 C/W: Located in Lane 56, Baudouin 4M06G33 /6 4 Cylinder 55 hp Diesel Engine, /32 kW, Rated Single Phase Output, 110 V / 220 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 1 Hr Lot closing time: Wed, Sep 16, 03:39 PM CDT Asset located in: Humble, TX, USA
1330	2018 Generac G0079600 48 kW Skid-Mounted Generator Set S/N: 3008429647 C/W: 2021 US EPA Label, Mitsubishi 4 Cylinder 3.3 L Diesel Engine, 48 kVA, /48 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Notes: ***Please see seller-supplied service records in the documentation section*** Lot closing time: Wed, Sep 16, 03:38 PM CDT Asset located in: Livingston, LA, USA	1335	2026 World Class Silent Generator 25 kW Skid-Mounted Generator Set (Unused) S/N: 25KW2605031256 C/W: Located in Lane 56, Banding 4M06G25/6 4 Cylinder 40 hp Diesel Engine, /25 kW, Rated Single Phase Output, 110 V / 220 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: Not Available Lot closing time: Wed, Sep 16, 03:40 PM CDT Asset located in: Humble, TX, USA
1331	Generac XG04845CNAX 48 kW Skid-Mounted Generator Set (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, 4 Cylinder Natural Gas Engine, /48 kW Rated 3 Phase Output, 120 V / 240 V / 480 V Rated Voltage Usage: Not Available Notes: Manufacturer Warranty Available Lot closing time: Wed, Sep 16, 03:39 PM CDT Asset located in: Humble, TX, USA	1336	2026 World Class KAL184D2 27.5 kW Skid-Mounted Generator Set (Unused) S/N: 25KW2605031253 C/W: Located in Lane 56, Baudouin 4M06G25 /6 4 Cylinder 40 hp Diesel Engine, 27.5 kVA, /27.5 kW, Rated Single Phase Output, 220 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 1 Hr Lot closing time: Wed, Sep 16, 03:40 PM CDT Asset located in: Humble, TX, USA
1332	Silent Generator 33 kW Skid-Mounted Generator Set (Unused) S/N: 33KW2605031257 C/W: Located in Lane 57 Spot 00, Baudouin 4M06G33/6 4 Cylinder 55 hp Diesel Engine, /33 kW, Rated Single Phase Output, 110 V / 220 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: Not Available Lot closing time: Wed, Sep 16, 03:39 PM CDT Asset located in: Humble, TX, USA	1337	Generac 22 kW Generator Set S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Wed, Sep 16, 03:40 PM CDT Asset located in: Humble, TX, USA
1333	Generac RA03022JDAE 30 kW Skid-Mounted Generator Set (Unused) S/N: 3018693808 C/W: Located in Lane 57 Spot 00, Perkins 404D-22TA 4 Cylinder 37 kW 2.2 L Diesel Engine, /30 kW Rated 3 Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: Not Available Notes: Manufacturer Warranty Available Lot closing time: Wed, Sep 16, 03:39 PM CDT Asset located in: Humble, TX, USA	1338	Cat SR4 545 kW Mobile Generator Set S/N: 6FA09661 C/W: Cat V12 27.0 L Diesel Engine, 681 kVA /545 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: Not Available Lot closing time: Wed, Sep 16, 03:41 PM CDT Asset located in: Lake Worth, TX, USA
		1341	2022 Atlas Copco QAS200JDT4F 160 kW Mobile Generator Set S/N: 16MBB1825MD083172 C/W: 2021 US EPA Label, John Deere 6068HF 6 Cylinder 6.8 L Diesel Engine, 160 kVA/200 kW Rated 3 Phase Output, 480 V / 240 V / 208 V Rated Voltage, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Lunette Ring Carrier Trailer, Electric Brakes Usage: 5,596 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:42 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1343	2001 SDMO GS350UC-SA 350 kW Skid-Mounted Generator Set S/N: AVP9537403Z478134002 C/W: Located in Lane 52, 2001 US EPA Label, VolvoPenta TAD1232GE 6 Cylinder 397 kW 12 L Diesel Engine, 437.5 kVA/350 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Lot closing time: Wed, Sep 16, 03:42 PM CDT Asset located in: Humble, TX, USA	1347C	2021 Airman SDG45S 45 kVA Mobile Generator Set S/N: 7H6BX12B2MA003154 C/W: 2021 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW 2.2 L Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer, Surge Brakes Usage: 17,679 Hr Lot closing time: Wed, Sep 16, 03:43 PM CDT Asset located in: Midland, TX, USA
1346	2023 JCB G70RST4F 56 kW Mobile Generator Set S/N: 5632G162XPM003192 C/W: Located in Lane 57 Spot 0, 2023 US EPA Label, JCB 444YA4-8113A 4 Cylinder 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 208 V / 240 V / 480 V Rated Voltage, 37 kVA/37 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, E-Stops, Lunette Ring Carrier Trailer, Electric Brakes Usage: 7 Hr Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Wed, Sep 16, 03:43 PM CDT Asset located in: Humble, TX, USA	1347D	2021 Airman SDG45S 45 kVA Mobile Generator Set S/N: 7H6BX12BXMA003225 C/W: 2020 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 hp 2.2 L Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer, Surge Brakes Usage: 17,691 Hr Lot closing time: Wed, Sep 16, 03:43 PM CDT Asset located in: Midland, TX, USA
1347A	2022 Airman 45 kVA Mobile Generator Set S/N: 7H6BX12B6N6006625 C/W: 2022 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW 2.2 L Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer Usage: 16,309 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:43 PM CDT Asset located in: Midland, TX, USA	1347E	2021 Airman SDG45S 45 kVA Mobile Generator Set S/N: 7H6BX12B3MA002448 C/W: 2020 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW 2.2 L Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer, Surge Brakes Usage: 12,190 Hr Lot closing time: Wed, Sep 16, 03:44 PM CDT Asset located in: Midland, TX, USA
1347B	2021 Airman SDG45S 45 kVA Mobile Generator Set S/N: 7H6BX12B1MA002447 C/W: 2020 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW 2.2 L Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer, Surge Brakes Usage: 14,386 Hr Lot closing time: Wed, Sep 16, 03:43 PM CDT Asset located in: Midland, TX, USA	1348B	2024 Modasa MH-25I 25.4 kW Mobile Generator Set S/N: 1U9P7F31XKR216401 C/W: 3 Cylinder Diesel Engine, /25.4 kW Rated 3 Phase Output, 480 V / 208 V Rated Voltage, 240 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer, Electric Brakes Usage: 1,413 Hr Notes: Texas buyers must stop in office to sign required documents to process title Lot closing time: Wed, Sep 16, 03:44 PM CDT Asset located in: Midland, TX, USA
		1349	World Class 25 kW Skid-Mounted Generator Set S/N: 25KW2605031254 C/W: Baudouin 4M06G25/6 4 Cylinder 40 hp Diesel Engine, 25 kVA/25 kW, Rated Single Phase Output, 110 V / 220 V Rated Voltage Usage: Not Available Lot closing time: Wed, Sep 16, 03:44 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1350	2019 Wacker G25 T4F 24.4 kW Mobile Generator Set S/N: 24483467 C/W: Located in Lane 56, 2018 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW 2.2 L Diesel Engine, /24.4 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, /16 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer Usage: 9,920 Hr Lot closing time: Wed, Sep 16, 03:44 PM CDT Asset located in: Humble, TX, USA	1351B	Kohler 16ROZ 10 kW Mobile Generator Set S/N: Not Available C/W: 1995 US EPA Label, Yanmar 3 Cylinder 1496 cc Diesel Engine, 10 kVA, /10 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Lunette Ring Carrier Trailer Usage: 1,188 Hr Lot closing time: Wed, Sep 16, 03:45 PM CDT Asset located in: Lake Worth, TX, USA
1350A	2019 Multiquip DCA-25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0918KB053977 C/W: Located in Lane 56, 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA, /14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer Usage: 7,909 Hr Lot closing time: Wed, Sep 16, 03:44 PM CDT Asset located in: Humble, TX, USA	1353	Atlas Copco XAS1800 JD7 T4F 1800 cfm Mobile Air Compressor S/N: Not Available C/W: Located in Lane 77 Spot 0, Air Cooler, Air Dryer, 2017 US EPA Label, John Deere 6135 6 Cylinder 560 kW 13.5 L Diesel Engine, Lunette Ring Carrier Trailer, Electric Brakes Usage: 8,560 Hr Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Wed, Sep 16, 03:45 PM CDT Asset located in: Humble, TX, USA
1350B	2022 Airman SDG25S 25 kVA Mobile Generator Set S/N: 7H6BX10A7NA006157 C/W: 2022 US EPA Label, Isuzu BZ-4LE2T 30 kW 2.2 L Diesel Engine, 25 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 03:44 PM CDT Asset located in: Midland, TX, USA	1354	2020 Doosan XP825/HP750WCU Mobile Air Compressor S/N: 498022UBAEF72 C/W: 2019 US EPA Label, Cummins OSB6.7 6 Cylinder 260 hp 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Lunette Ring Carrier Trailer, Electric Brakes Usage: 7,021 Hr Lot closing time: Wed, Sep 16, 03:45 PM CDT Asset located in: Livingston, LA, USA
1351	2017 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0918HB046195 C/W: Located in Lane 56, 2017 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW 2.179 L Diesel Engine, /20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, /14 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Lunette Ring Carrier Trailer Usage: 5,777 Hr Lot closing time: Wed, Sep 16, 03:45 PM CDT Asset located in: Humble, TX, USA	1354A	2020 Doosan XP825/HP750WCU 825 m3/min Mobile Air Compressor S/N: 498024UBAEF72 C/W: Located in Lane 56, Air Cooler, Air Dryer, 150 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Lunette Ring Carrier Trailer, Electric Brakes Usage: 7,896 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:46 PM CDT Asset located in: Humble, TX, USA
1351A	2021 Generac MLG15 Mobile Generator Set S/N: 7FSBG0915MB904287 C/W: Located in Lane 54, 2021 US EPA Label, Mitsubishi S4L2 4 Cylinder 1.8 L Diesel Engine, 13 kVA, /13 kW, Rated Single Phase Output, / 240 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Ball Hitch Carrier Trailer Usage: 5,112 Hr Lot closing time: Wed, Sep 16, 03:45 PM CDT Asset located in: Lake Worth, TX, USA	1355	2018 Atlas Copco XAS440JD8T4F 440 cfm Mobile Air Compressor S/N: 4500B1412JR077507 C/W: 150 psi Working Pressure, 2018 US EPA Label, John Deere 4045HFC04A 4.5 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 19,679 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:46 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1356	2021 Atlas Copco XATS400JDFT4 400 cfm Mobile Air Compressor S/N: 4500B1419MR079503 C/W: Located in Lane 56, 200 psi Working Pressure, 2021 US EPA Label, John Deere 4045 4 Cylinder 4.5 L Diesel Engine, Ball Hitch Carrier Trailer, Electric Brakes Usage: 822 Hr Lot closing time: Wed, Sep 16, 03:46 PM CDT Asset located in: Humble, TX, USA	1361	2023 Sullivan 375PHJD4 Mobile Air Compressor S/N: 4YAHH1210PM000472 C/W: Located in Lane 56, 150 psi Working Pressure, 2022 US EPA Label, John Deere 4045HFC04A 4 Cylinder 130 kW 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, Lunette Ring Carrier Trailer, Electric Brakes Usage: 1,538 Hr Lot closing time: Wed, Sep 16, 03:48 PM CDT Asset located in: Humble, TX, USA
1356A	2015 Atlas Copco XAS 400 PE CD7 IT4 EB Mobile Air Compressor S/N: 4500B1312FR075863 C/W: Cat Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 03:46 PM CDT Asset located in: Midland, TX, USA	1361A	2012 Atlas Copco XAS 375 T3 Mobile Air Compressor S/N: 4500B1318CR072557 C/W: John Deere 4 Cylinder 4.5 L Diesel Engine, Lunette Ring Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 03:48 PM CDT Asset located in: Midland, TX, USA
1356B	2015 Atlas Copco XAS 400 PE CD7 IT4 EB Mobile Air Compressor S/N: 4500B1312FR075930 C/W: Air Cooler, Air Dryer, 125 psi Working Pressure, 2013 US EPA Label, Cat C4.4 4 Cylinder 56 kW 4.4 cc Diesel Engine, Ball Hitch Carrier Trailer, Electric Brakes, VIN: 4500B1312FR075930 Usage: 1,484 Hr Lot closing time: Wed, Sep 16, 03:46 PM CDT Asset located in: Midland, TX, USA	1362	2004 Quincy QSI-370 370 cfm Skid-Mounted Air Compressor S/N: 96024J C/W: 3 Phase Usage: 41,369 Hr Lot closing time: Wed, Sep 16, 03:48 PM CDT Asset located in: Lake Worth, TX, USA
1358	2022 Rotair D400T4F 400 cfm Mobile Air Compressor S/N: 16MBB1311ND083735 C/W: Located in Lane 54, 150 psi Working Pressure, 2022 US EPA Label, Cummins QSF3.8 4 Cylinder 97 kW Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 03:47 PM CDT Asset located in: Lake Worth, TX, USA	1364	2011 Ingersoll Rand P250WJD 250 cfm Mobile Air Compressor S/N: 418069UIUD81 C/W: Located in Lane 54, 2010 US EPA Label, CARB Compliant, John Deere 4045TF280 4 Cylinder 56 kW 4.5 L Diesel Engine, Ball Hitch Carrier Trailer, Electric Brakes Usage: 1,870 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:48 PM CDT Asset located in: Lake Worth, TX, USA
1358A	2017 Sullair 400DHH 400 cfm Mobile Air Compressor S/N: 201702220065 C/W: 2016 US EPA Label, Cat C4.4 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Lunette Ring Carrier Trailer Usage: 5,122 Hr Lot closing time: Wed, Sep 16, 03:47 PM CDT Asset located in: Lake Worth, TX, USA	1364A	2021 Allmand Bros Maxi-Air 185 185 cfm Mobile Air Compressor S/N: 5AEA1KF13MH001372 C/W: 2019 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 5,413 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:49 PM CDT Asset located in: Livingston, LA, USA
1360	2023 Sullivan 375PHJD4 Mobile Air Compressor S/N: 4YAHH1219PM000468 C/W: Located in Lane 56, 150 psi Working Pressure, 2022 US EPA Label, John Deere 4045HFC04A 4 Cylinder 130 kW 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, Ball Hitch Carrier Trailer, Electric Brakes Usage: 450 Hr Lot closing time: Wed, Sep 16, 03:47 PM CDT Asset located in: Humble, TX, USA	1365	2021 Allmand Bros Maxi-Air 185 185 cfm Mobile Air Compressor S/N: 5AEA1KF13MH001274 C/W: 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.190 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 7,314 Hr Lot closing time: Wed, Sep 16, 03:49 PM CDT Asset located in: Livingston, LA, USA

Lot #	Details	Lot #	Details
1366	2021 Atlas Copco XAS188 KD T4F Air Compressor S/N: 4500A1017MR200280 C/W: Located in Lane 57, 124 psi Working Pressure, 2021 US EPA Label, Kubota D1803-CR-TI-EF02 4 Cylinder 36.5 kW 1.8 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 6,415 Hr Lot closing time: Wed, Sep 16, 03:49 PM CDT Asset located in: Humble, TX, USA	1369A	2021 Rotair D185T4F 185 cfm Mobile Air Compressor S/N: C44855 C/W: 100 psi Working Pressure, 2020 US EPA Label, Kohler 3 Cylinder 1.86 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 1,803 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:50 PM CDT Asset located in: Lake Worth, TX, USA
1366A	2023 Chicago Pneumatic 185 CFM 185 cfm Mobile Air Compressor S/N: 4500A1019PR202556 C/W: Located in Lane 57 Spot 0, 2022 US EPA Label, Kohler NKHXL02.5TCR 3 Cylinder 37 kW 1.861 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 1,432 Hr Lot closing time: Wed, Sep 16, 03:49 PM CDT Asset located in: Humble, TX, USA	1370	2018 Rotair D185T41 185 cfm Mobile Air Compressor S/N: C40943 C/W: 100 psi Working Pressure, 2017 US EPA Label, Kubota V2403-M-DI-ET02 4 Cylinder 36.5 kW 2.4 L Diesel Engine Usage: 1,437 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 03:50 PM CDT Asset located in: Lake Worth, TX, USA
1367	2017 Atlas Copco APT185KD7T4F 185 cfm Mobile Air Compressor S/N: 4500A1014HR055172 C/W: Located in Lane 55 Spot 0, 125 psi Working Pressure, 2017 US EPA Label, Kubota D1083-CR-TI-EF02 4 Cylinder 36.5 kW 1.8 L Diesel Engine, Lunette Ring Carrier Trailer Usage: 1,337 Hr Lot closing time: Wed, Sep 16, 03:49 PM CDT Asset located in: Lake Worth, TX, USA	1371	2022 Sullivan D185PIZ4 185 cfm Skid-Mounted Air Compressor S/N: 4YAHH1117NM000449 C/W: 110 psi Working Pressure, 2021 US EPA Label, Isuzu AZ-4LE2T 4 Cylinder 36 kW Diesel Engine Usage: 970 Hr Lot closing time: Wed, Sep 16, 03:51 PM CDT Asset located in: Lake Worth, TX, USA
1368	2017 Atlas Copco XAS185KD 185 cfm Mobile Air Compressor S/N: 4500A1010HR055900 C/W: 125 psi Working Pressure, US EPA Label, Kubota D1803-CR-TI-EF02 4 Cylinder 36.5 kW 1.8 L Diesel Engine, Lunette Ring Carrier Trailer Usage: 2,527 Hr Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 03:50 PM CDT Asset located in: Lake Worth, TX, USA	1372	2020 Sullair 185 105 cfm Mobile Air Compressor S/N: 202001270047 C/W: Located in Lane 56, 2019 US EPA Label, Kubota D1803 3 Cylinder 36.5 kW 1.8 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 2,273 Hr Lot closing time: Wed, Sep 16, 03:51 PM CDT Asset located in: Humble, TX, USA
1369	2017 Atlas Copco XAS185KD 185 cfm Mobile Air Compressor S/N: 4500A1010HR055413 C/W: 125 psi Working Pressure, 2017 US EPA Label, Kubota D1803-CR-TI-EF02 4 Cylinder 36.5 kW 1.8 L Diesel Engine, Lunette Ring Carrier Trailer Usage: 2,330 Hr Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 03:50 PM CDT Asset located in: Lake Worth, TX, USA	1374	2018 Sullair 185DPQ 185 cfm Mobile Air Compressor S/N: 201802060001 C/W: Located in Lane 56, 2017 US EPA Label, Kubota D1803 3 Cylinder 36.5 kW 1.8 L Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 03:51 PM CDT Asset located in: Humble, TX, USA
		1375	Sullair 185 185 cfm Mobile Air Compressor S/N: Not Available C/W: 2008 US EPA Label, John Deere 4024TF270G 2.4 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 1,953 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:52 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1376	2014 Sullair 185 m3/min Mobile Air Compressor S/N: 201407230055 C/W: 4 Cylinder Diesel Engine, Lunette Ring Carrier Trailer, Equipment-from-a-Primoris-Services-Corp-company Usage: 1,160 Hr Lot closing time: Wed, Sep 16, 03:52 PM CDT Asset located in: Lake Worth, TX, USA	1382	2018 Atlas Copco XAS110 110 cfm Mobile Air Compressor S/N: YA3064288J0515151 C/W: Located in Lane 56, 2017 US EPA Label, Kubota D902 3 Cylinder 18.5 kW 0.89 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 1 Hr Lot closing time: Wed, Sep 16, 03:54 PM CDT Asset located in: Humble, TX, USA
1377	2021 Doosan C185WDO-T4F Mobile Air Compressor S/N: 4FVCABAA3MU502918 C/W: Located in Lane 57, 3 Cylinder Diesel Engine, Ball Hitch Carrier Trailer Usage: 6,435 Hr Lot closing time: Wed, Sep 16, 03:52 PM CDT Asset located in: Humble, TX, USA	1382A	2018 Atlas Copco XAS110KD 110 cfm Mobile Air Compressor S/N: APP546505 C/W: Kubota D902-EF01 3 Cylinder 18.2 kW 0.89 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 1,192 Hr Notes: Temporary tags will not be issued; No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:54 PM CDT Asset located in: Oklahoma City, OK, USA
1378	2012 Ingersoll Rand P185WJD-T4I 185 cfm Mobile Air Compressor S/N: 440880UEWD75 C/W: 2012 US EPA Label, John Deere 4014TF281C 2.4 L Diesel Engine, Ball Hitch Carrier Trailer, Equipment-from-a-Primoris-Services-Corp-company Usage: 459 Hr Lot closing time: Wed, Sep 16, 03:53 PM CDT Asset located in: Lake Worth, TX, USA	1383	2018 Atlas Copco XAS110KD 110 cfm Mobile Air Compressor S/N: YA3064281J0549755 C/W: Located in Lane 56, 2018 US EPA Label, Kubota D902 3 Cylinder 18.2 kW 0.898 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 1,695 Hr Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Wed, Sep 16, 03:54 PM CDT Asset located in: Humble, TX, USA
1379	2011 Ingersoll Rand P185WJD-T4I 185 cfm Air Compressor S/N: 427280UFVD75 C/W: 2011 US EPA Label, John Deere 4024TF281C 2.4 L Diesel Engine, Equipment-from-a-Primoris-Services-Corp-company Usage: 915 Hr Lot closing time: Wed, Sep 16, 03:53 PM CDT Asset located in: Lake Worth, TX, USA	1384	2017 Kaeser M58 Mobile Air Compressor S/N: WKA0N1352H6062795 C/W: 2015 US EPA Label, Kubota 4 Cylinder 2.4 L Diesel Engine, Lunette Ring Carrier Trailer Usage: 23 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:54 PM CDT Asset located in: Lake Worth, TX, USA
1380	2022 Rotair D185T4F 125 cfm Mobile Air Compressor S/N: C46816 C/W: 125 psi Working Pressure, 2022 US EPA Label, Kohler 3 Cylinder 1.86 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 1,885 Hr Lot closing time: Wed, Sep 16, 03:53 PM CDT Asset located in: Lake Worth, TX, USA	1385	2012 Kaeser M57 Mobile Air Compressor S/N: WKA0N1301C4602223 C/W: 100 psi Working Pressure, 2012 US EPA Label, Kubota V2403-M-ET04 4 Cylinder 36.5 kW 2.4 L Diesel Engine, Lunette Ring Carrier Trailer, Equipment-from-a-Primoris-Services-Corp-company Usage: 746 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 03:55 PM CDT Asset located in: Lake Worth, TX, USA
1381	Airman 125 cfm Mobile Air Compressor S/N: Not Available C/W: 125 psi Working Pressure, 4 Cylinder Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 03:54 PM CDT Asset located in: Lake Worth, TX, USA	1386	2011 Kaeser M50 Mobile Air Compressor S/N: WKA0N0755B4187144 C/W: 2010 US EPA Label, Kubota V1505-T-ET03 4 Cylinder 33 kW 1.5 L Diesel Engine Usage: 2,562 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Lot closing time: Wed, Sep 16, 03:55 PM CDT Asset located in: Austin, TX, USA

Lot #	Details	Lot #	Details
1388	2020 Miller Trailblazer 325 325 A Multi-Process Engine Driven Welder S/N: NA380796R C/W: Kohler 2 Cylinder Gasoline Engine, Welding Leads Not Included, /10.5 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage, Equipment-from-a-Primoris-Services-Corp-company Usage: 1,842 Hr Lot closing time: Wed, Sep 16, 03:56 PM CDT Asset located in: Lake Worth, TX, USA	1391	2020 Miller Big Blue 500 Pro 500 A Mobile Multi-Process Engine Driven Welder S/N: NA101012R C/W: Located in Lane 53, Kubota V2403 4 Cylinder 48.9 hp 2.43 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, Reversible Hitch Carrier Trailer Usage: 6,993 Hr Lot closing time: Wed, Sep 16, 03:57 PM CDT Asset located in: Humble, TX, USA
1388A	2009 Miller Bobcat 225 225 A Multi-Process Engine Driven Welder S/N: LK180091H C/W: Kohler 2 Cylinder Gasoline Engine, Welding Leads Not Included, /11 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: 4,090 Hr Lot closing time: Wed, Sep 16, 03:56 PM CDT Asset located in: Lake Worth, TX, USA	1394	2020 Miller Big Blue 400 Pro 400 A Mobile Multi-Process Engine Driven Welder S/N: 7LT1A1016LA002495 C/W: Mitsubishi S4L2 4 Cylinder 1.8 L Diesel Engine Usage: 3,199 Hr Lot closing time: Wed, Sep 16, 03:57 PM CDT Asset located in: Lake Worth, TX, USA
1389	2019 Lincoln Vantage 549 525 A Mobile Multi-Process Engine Driven Welder S/N: U1190800021 C/W: Located in Lane 53, 2019 US EPA Label, Deutz TD2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Welding Leads Not Included, /19 kW Rated 3 Phase Output, 240 V Rated Voltage, /11 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage, Reversible Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 03:56 PM CDT Asset located in: Humble, TX, USA	1395	Miller Electric Big Blue 400 Pro 400 A Mobile Multi-Process Engine Driven Welder S/N: 7LT1A1018LA002305 C/W: 2019 US EPA Label, Mitsubishi S4L2 4 Cylinder 1.8 L Diesel Engine, 120 V / 240 V Rated Voltage Usage: 2,960 Hr Lot closing time: Wed, Sep 16, 03:58 PM CDT Asset located in: Lake Worth, TX, USA
1389A	2019 Lincoln Electric Vantage 549 575 A Mobile Multi-Process Engine Driven Welder S/N: U1190510481 C/W: Located in Lane 53, 2019 US EPA Label, Deutz TD2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Welding Leads Not Included, /19 kW Rated 3 Phase Output, 240 V Rated Voltage, /11 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage, Reversible Hitch Carrier Trailer Usage: 4,474 Hr Lot closing time: Wed, Sep 16, 03:56 PM CDT Asset located in: Humble, TX, USA	1396	2017 Miller Big Blue 400 Pro 400 A Mobile Multi-Process Engine Driven Welder S/N: 1R91A1013HA820963 C/W: 2019 US EPA Label, Mitsubishi S4L2 4 Cylinder 1.8 L Diesel Engine, 120 V / 240 V Rated Voltage Usage: 2,903 Hr Lot closing time: Wed, Sep 16, 03:58 PM CDT Asset located in: Lake Worth, TX, USA
1390	2019 Lincoln Electric Vantage 549 525 A Mobile Multi-Process Engine Driven Welder S/N: U1190507091 C/W: Located in Lane 53, 2019 US EPA Label, Deutz TD2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Welding Leads Not Included, 19 kVA/ Rated 3 Phase Output, 240 V Rated Voltage, /11 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage, Reversible Hitch Carrier Trailer Usage: 4,756 Hr Lot closing time: Wed, Sep 16, 03:56 PM CDT Asset located in: Humble, TX, USA	1397	2020 Miller Big Blue 400 Pro 400 A Mobile Multi-Process Engine Driven Welder S/N: 1R91A1010JA820263 C/W: Kubota Diesel Engine Usage: 4,782 Hr Lot closing time: Wed, Sep 16, 03:58 PM CDT Asset located in: Lake Worth, TX, USA
		1398	2020 Miller Big Blue 400 Pro 400 A Mobile Multi-Process Engine Driven Welder S/N: 7LT1A1011LA002341 C/W: 2019 US EPA Label, Mitsubishi S4L2 4 Cylinder 1.8 L Diesel Engine, 120 V / 240 V Rated Voltage Usage: 2,913 Hr Lot closing time: Wed, Sep 16, 03:59 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1399	2020 Miller Big Blue 400 Pro 400 A Mobile Multi-Process Engine Driven Welder S/N: 7LT1A101XLA002368 C/W: 2019 US EPA Label, Mitsubishi S4L2 4 Cylinder 1.8 L Diesel Engine, 120 V / 240 V Rated Voltage Usage: 167 Hr Lot closing time: Wed, Sep 16, 03:59 PM CDT Asset located in: Lake Worth, TX, USA	1405	Miller 903512 300 A Skid-Mounted Multi-Process 8 Bank Electric Welder S/N: LC256454 C/W: Located in Lane 53 Spot 0, 3 Phase, 230 V / 460 V Input, Welding Leads Not Included Usage: Not Available Lot closing time: Wed, Sep 16, 04:01 PM CDT Asset located in: Humble, TX, USA
1400	2017 Miller Big Blue 400 Pro 400 A Mobile Multi-Process Engine Driven Welder S/N: 1R91A1011HA820802 C/W: Kubota 4 Cylinder Diesel Engine Usage: 4,193 Hr Lot closing time: Wed, Sep 16, 03:59 PM CDT Asset located in: Lake Worth, TX, USA	1406	2017 Miller Syncrowave 210 210 A Arc Electric Welder S/N: MH050146L C/W: 115 V / 230 V Input, Welding Leads Usage: Not Available Lot closing time: Wed, Sep 16, 04:01 PM CDT Asset located in: Lake Worth, TX, USA
1402	2016 Miller Trailblazer 325 325 A Multi-Process Engine Driven Welder S/N: MG170601R C/W: 2016 US EPA Label, Kohler 2 Cylinder Gasoline Engine, Welding Leads Not Included, /10.5 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: Not Available Lot closing time: Wed, Sep 16, 04:00 PM CDT Asset located in: Lake Worth, TX, USA	1407	2026 MIG-270 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:01 PM CDT Asset located in: Humble, TX, USA
1402A	2022 Miller Bobcat 260LP 260 A Mobile Multi-Process Engine Driven Welder S/N: NC300269R C/W: Located in Lane 72, 2022 US EPA Label, Kohler CH730LP 725 cc LPG Engine Usage: 916 Hr Lot closing time: Wed, Sep 16, 04:00 PM CDT Asset located in: Lake Worth, TX, USA	1408	2026 MIG-270 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:02 PM CDT Asset located in: Humble, TX, USA
1402B	2021 Lincoln Ranger 260MPX 260 A Mobile Multi-Process Engine Driven Welder S/N: U1210500931 C/W: Located in Lane 72, 2021 US EPA Label, Kohler CH730 2 Cylinder 725 cc Gasoline Engine, /9.5 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: 2,778 Hr Lot closing time: Wed, Sep 16, 04:00 PM CDT Asset located in: Lake Worth, TX, USA	1409	2026 MIG-270 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:02 PM CDT Asset located in: Humble, TX, USA
1403A	2020 Miller Trailblazer 325 325 A Mobile Engine Driven Welder S/N: NA120623R C/W: Located in Lane 53, 2019 US EPA Label, Kubota D902 3 Cylinder 18.2 kW 0.898 L Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, Reversible Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 04:00 PM CDT Asset located in: Humble, TX, USA	1410	2026 MIG-270 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:02 PM CDT Asset located in: Humble, TX, USA
		1411	2026 MIG-270 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:03 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1412	2026 MIG-270 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:03 PM CDT Asset located in: Humble, TX, USA	1418	2026 MIG-250 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:05 PM CDT Asset located in: Humble, TX, USA
1413	2026 MIG-250 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:03 PM CDT Asset located in: Humble, TX, USA	1419	Quantity of (2) Water Pump S/N: Not Available C/W: Located in Lane 54 Spot 1, 12 in Intake, 12 in Discharge, Centrifugal Water Pump Usage: Not Available Lot closing time: Wed, Sep 16, 04:05 PM CDT Asset located in: Humble, TX, USA
1414	2026 MIG-250 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:03 PM CDT Asset located in: Humble, TX, USA	1420	Gorman-Rupp T6A60S-QSB4 Trailer-Mounted Water Pump S/N: 1579283N C/W: Located in Lane 56 Spot 1, 6 in Intake, 6 in Discharge, Self Priming Centrifugal 2011 US EPA Label, Cummins OSB4.5 110 hp 475 L Diesel Engine, Ball Hitch Carrier Trailer Usage: 9,711 Hr Lot closing time: Wed, Sep 16, 04:05 PM CDT Asset located in: Lake Worth, TX, USA
1415	2026 MIG-250 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:04 PM CDT Asset located in: Humble, TX, USA	1420A	2016 Pioneer Pump SAPP88S12L71 Trailer-Mounted Water Pump S/N: 1P9BSJD16GC622628 C/W: 8 in Intake, 9 in Discharge, Centrifugal Water Pump, 2017 US EPA Label, John Deere 4045HF285C 4 Cylinder 4.5 L Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 04:05 PM CDT Asset located in: Lake Worth, TX, USA
1416	2026 MIG-250 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:04 PM CDT Asset located in: Humble, TX, USA	1421	1996 Butterworth Trailer-Mounted Water Pump S/N: SN5501 C/W: 1 in Intake, 2 in Discharge, Triplex Water Pump, Cummins Diesel Engine, Electric Brakes Usage: 9,737 Hr Lot closing time: Wed, Sep 16, 04:06 PM CDT Asset located in: Lake Worth, TX, USA
1417	2026 MIG-250 115 A MIG Electric Welder (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Wed, Sep 16, 04:04 PM CDT Asset located in: Humble, TX, USA	1422	Gardner Denver Mud Pump S/N: Not Available C/W: Located in Lane 58 Spot 0, Triplex Mud Pump, Detroit V8 Diesel Engine, Open Top Skid-Mounted Mud Tank Usage: Not Available Lot closing time: Wed, Sep 16, 04:06 PM CDT Asset located in: Humble, TX, USA
		1423	2010 Stewart-Stevenson Frac Pump S/N: LJRC13277A2016944 C/W: Tier 2, V12 1680 kW Diesel Engine Usage: 4,421 Hr Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 04:06 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1424	2010 Pratt Industries Duplex Frac Pump S/N: 1P9CP4423AB343313 C/W: 2010 US EPA Label, Detroit 6 Cylinder 14 L Diesel Engine Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 04:06 PM CDT Asset located in: Pecos, TX, USA	1428	Quantity of (3) Mr. Heater 80000 BTU Forced Air Space Heater S/N: Not Available C/W: Located in Lane 100 Spot 0, Kerosene Fueled Usage: Not Available Lot closing time: Wed, Sep 16, 04:08 PM CDT Asset located in: Humble, TX, USA
1425	2010 S & S 2250 Frac Pump S/N: LJRC13279A2016976 C/W: MTU 12V 4000S83 V12 1680 kW Diesel Engine Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 04:07 PM CDT Asset located in: Pecos, TX, USA	1429	Quantity of (4) Mr. Heater 60000 BTU Forced Air Space Heater S/N: Not Available C/W: Located in Lane 100 Spot 0, Propane Fueled Usage: Not Available Lot closing time: Wed, Sep 16, 04:08 PM CDT Asset located in: Humble, TX, USA
1426	2008 S 2250 Frac Pump S/N: LJRC1327482012196 C/W: MTU V12 Diesel Engine Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 04:07 PM CDT Asset located in: Pecos, TX, USA	1430	Quantity of (4) Mr. Heater 60000 BTU Forced Air Space Heater S/N: Not Available C/W: Located in Lane 100 Spot 0, Propane Fueled Usage: Not Available Lot closing time: Wed, Sep 16, 04:08 PM CDT Asset located in: Humble, TX, USA
1426A	Dryair 600GTS 140000 BTU Ground Heater S/N: 2DRUS62998S46205 C/W: Furnace oil Fueled, Single Phase, 230 V Input, Lunette Ring Carrier Trailer, Electric Brakes Usage: Not Available Lot closing time: Wed, Sep 16, 04:07 PM CDT Asset located in: Lake Worth, TX, USA	1431	2025 Generac MLTS-4 Light Tower S/N: 7FSBL1015SB572671 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 76 Hr Lot closing time: Wed, Sep 16, 04:09 PM CDT Asset located in: Lake Worth, TX, USA
1427	Ground Heater E3000 360000 BTU Ground Heater S/N: Not Available C/W: Single Phase, 120 V Input, MultiQuip DA-7000SSA Generator, 2014 US EPA Label, Kubota Z482 2 Cylinder 10.3 hp 479 cc Diesel Engine, Lunette Ring Carrier Trailer, Electric Brakes Usage: 10,263 Hr Lot closing time: Wed, Sep 16, 04:07 PM CDT Asset located in: Lake Worth, TX, USA	1432	2025 Generac MLTS-4 Light Tower S/N: 7FSBL1017SB601670 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 136 Hr Lot closing time: Wed, Sep 16, 04:09 PM CDT Asset located in: Lake Worth, TX, USA
1427A	Ground Heater E3000 360000 BTU Ground Heater S/N: Not Available C/W: Single Phase, 120 V Input, MultiQuip DA7000SSA Generator, 2014 US EPA Label, Kubota Z842 2 Cylinder 10.3 hp Diesel Engine, Lunette Ring Carrier Trailer Usage: 17,314 Hr Lot closing time: Wed, Sep 16, 04:07 PM CDT Asset located in: Lake Worth, TX, USA	1433	2025 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL1014SB601674 C/W: Located in Lane 50 Spot 1, 2024 US EPA Label, Mitsubishi MVL2E 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 11 Hr Lot closing time: Wed, Sep 16, 04:09 PM CDT Asset located in: Lake Worth, TX, USA
		1434	2025 Generac MLT-2 2.5 kW Light Tower S/N: 7FSBL1010SB572674 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 868 Hr Lot closing time: Wed, Sep 16, 04:09 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1435	2025 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL1010SB571539 C/W: Located in Lane 50 Spot 1, 2024 US EPA Label, Mitsubishi MVL2E 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 42 Hr Lot closing time: Wed, Sep 16, 04:10 PM CDT Asset located in: Lake Worth, TX, USA	1441	2025 Generac MLT-2 2.5 kW Light Tower S/N: 7FSBL1012SB571543 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 137 Hr Lot closing time: Wed, Sep 16, 04:12 PM CDT Asset located in: Lake Worth, TX, USA
1436	2025 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL1012SB572675 C/W: Located in Lane 50 Spot 2, 2024 US EPA Label, Mitsubishi MVL2E 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 164 Hr Lot closing time: Wed, Sep 16, 04:10 PM CDT Asset located in: Lake Worth, TX, USA	1442	2025 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL1011SB601681 C/W: Located in Lane 50 Spot 2, 2024 US EPA Label, Mitsubishi MVL2E 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 438 Hr Lot closing time: Wed, Sep 16, 04:12 PM CDT Asset located in: Lake Worth, TX, USA
1437	2025 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL101XSB601680 C/W: Located in Lane 50 Spot 1, 2024 US EPA Label, Mitsubishi MVL2E 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 53 Hr Lot closing time: Wed, Sep 16, 04:10 PM CDT Asset located in: Lake Worth, TX, USA	1443	2025 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL1014SB572662 C/W: Located in Lane 50 Spot 1, 2024 US EPA Label, Mitsubishi MVL2E 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 485 Hr Lot closing time: Wed, Sep 16, 04:12 PM CDT Asset located in: Lake Worth, TX, USA
1438	2025 Generac MLT-2 2.5 kW Light Tower S/N: 7FSBL1014SB572676 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 79 Hr Lot closing time: Wed, Sep 16, 04:11 PM CDT Asset located in: Lake Worth, TX, USA	1444	2025 Generac MLT-2 2.5 kW Light Tower S/N: 7FSBL1010SB571542 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 301 Hr Lot closing time: Wed, Sep 16, 04:12 PM CDT Asset located in: Lake Worth, TX, USA
1439	2025 Generac MLT-2 2.5 kW Light Tower S/N: 7FSBL1011SB571551 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 105 Hr Lot closing time: Wed, Sep 16, 04:11 PM CDT Asset located in: Lake Worth, TX, USA	1445	2024 Generac MLTS 2.5 kW Light Tower S/N: 7FSBL1010RB915493 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 30 Hr Lot closing time: Wed, Sep 16, 04:13 PM CDT Asset located in: Lake Worth, TX, USA
1440	2025 Generac MLT-2 2.5 kW Light Tower S/N: 7FSBL1019SB572673 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 131 Hr Lot closing time: Wed, Sep 16, 04:11 PM CDT Asset located in: Lake Worth, TX, USA	1446	2024 Generac MLTS Light Tower S/N: 7FSBL101XRB915470 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 46 Hr Lot closing time: Wed, Sep 16, 04:13 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1447	2024 Generac MLTS 2.5 kW Light Tower S/N: 7FSBL1017RB915488 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 58 Hr Lot closing time: Wed, Sep 16, 04:13 PM CDT Asset located in: Lake Worth, TX, USA	1453	2024 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL1012RB716719 C/W: 2023 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 427 Hr Lot closing time: Wed, Sep 16, 04:15 PM CDT Asset located in: Lake Worth, TX, USA
1448	2024 Generac MLTS 2.5 kW Light Tower S/N: 7FSBL1010RB915476 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 161 Hr Lot closing time: Wed, Sep 16, 04:14 PM CDT Asset located in: Lake Worth, TX, USA	1454	2024 Generac MLT-2 2.5 kW Light Tower S/N: 7FSBL1012RB915477 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 432 Hr Lot closing time: Wed, Sep 16, 04:15 PM CDT Asset located in: Lake Worth, TX, USA
1449	2024 Generac MLTS-4 Light Tower S/N: 7FSBL1017RB346464 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 273 Hr Lot closing time: Wed, Sep 16, 04:14 PM CDT Asset located in: Lake Worth, TX, USA	1455	2024 Generac MLTS Light Tower S/N: 7FSBL1011RB915468 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 600 Hr Lot closing time: Wed, Sep 16, 04:16 PM CDT Asset located in: Lake Worth, TX, USA
1450	2024 Generac MLTS-4 Light Tower S/N: 7FSBL1014RB674344 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 04:14 PM CDT Asset located in: Lake Worth, TX, USA	1456	2024 Generac MLTS-4 2.5 kW Light Tower S/N: 7FSBL1010RB716718 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 619 Hr Lot closing time: Wed, Sep 16, 04:16 PM CDT Asset located in: Lake Worth, TX, USA
1451	2024 Generac MLTS-4 Light Tower S/N: 7FSBL1016RB346469 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 263 Hr Lot closing time: Wed, Sep 16, 04:15 PM CDT Asset located in: Lake Worth, TX, USA	1457	2024 Generac MLTS-4 Light Tower S/N: 7FSBL101XRB674350 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 943 Hr Lot closing time: Wed, Sep 16, 04:16 PM CDT Asset located in: Lake Worth, TX, USA
1452	2024 Generac MLTS Light Tower S/N: 7FSBL1014RB915481 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder .6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 393 Hr Lot closing time: Wed, Sep 16, 04:15 PM CDT Asset located in: Lake Worth, TX, USA	1458	2024 Generac MLTS 2.5 kW Light Tower S/N: 7FSBL101XRB915467 C/W: 2024 US EPA Label, Mitsubishi 2 Cylinder 0.6 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 1,244 Hr Lot closing time: Wed, Sep 16, 04:17 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1459	2023 Wacker LTV6L 6 kW Light Tower S/N: 5XFLV0419PM004953 C/W: 2022 US EPA Label, Kohler 3 Cylinder 1.02 L Diesel Engine, 4 Lamps, LED Lighting, Ball Hitch Carrier Trailer Usage: 5,336 Hr Lot closing time: Wed, Sep 16, 04:17 PM CDT Asset located in: Lake Worth, TX, USA	1468	2019 Trime EL1250 Light Tower S/N: 1F91A0917KC445773 C/W: Located in Lane 54 Spot 0, 2019 US EPA Label, Kubota Z482-D2-EF07e 2 Cylinder 4.5 kW .47 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Hydraulic Raise and Lower, Ball Hitch Carrier Trailer Usage: 16,219 Hr Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 04:20 PM CDT Asset located in: Lake Worth, TX, USA
1459A	2017 Magnum MLT6SK Light Tower S/N: 7FSBL1010HB892487 C/W: Tier 4, 2017 US EPA Label, Kubota 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Ball Hitch Carrier Trailer Usage: 938 Hr Lot closing time: Wed, Sep 16, 04:17 PM CDT Asset located in: Lake Worth, TX, USA	1469	2018 Trime EL1251 Light Tower S/N: 1F91A0919JC445787 C/W: Located in Lane 54 Spot 0, 2018 US EPA Label, Kubota Z482-D2-EF07e 2 Cylinder 4.5 kW .47 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Hydraulic Raise and Lower, Ball Hitch Carrier Trailer Usage: 12,674 Hr Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 04:20 PM CDT Asset located in: Lake Worth, TX, USA
1463	2015 Terex RL4000 Light Tower S/N: 4ZJSA1419F1012338 C/W: Tier 4, 2014 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 4 Lamps Usage: 7,410 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:18 PM CDT Asset located in: Lake Worth, TX, USA	1470	2020 Trime EL1252 Light Tower S/N: 1F91A0917MC445940 C/W: Located in Lane 54 Spot 0, 2019 US EPA Label, Kubota Z482 C-D2-EF07e 2 Cylinder 4.5 kW .47 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Hydraulic Raise and Lower, Ball Hitch Carrier Trailer Usage: 4,490 Hr Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 04:20 PM CDT Asset located in: Lake Worth, TX, USA
1463A	2019 Terex RL4 6 kW Light Tower S/N: 4XJSA1012K1010866 C/W: Located in Lane 54, 2018 US EPA Label, Kohler KDW1003GE 3 Cylinder 1.02 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Ball Hitch Carrier Trailer Usage: 3,221 Hr Lot closing time: Wed, Sep 16, 04:18 PM CDT Asset located in: Lake Worth, TX, USA	1471	2021 Trime EL1253 Light Tower S/N: 1F91A0916MC445931 C/W: Located in Lane 54 Spot 0, 2020 US EPA Label, Kubota Z482-D2-EF07e 2 Cylinder 4.5 kW .47 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Hydraulic Raise and Lower, Ball Hitch Carrier Trailer Usage: 5,525 Hr Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 04:21 PM CDT Asset located in: Lake Worth, TX, USA
1464	2015 Terex RL4 6 kW Light Tower S/N: 4ZJSA141XF1012333 C/W: Kubota D1105-BG-EF01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, Ball Hitch Carrier Trailer Usage: 16,825 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:18 PM CDT Asset located in: Lake Worth, TX, USA		
1466	2010 Terex RL4000 Light Tower S/N: 4ZJSL141XA1003148 C/W: Tier 4, 2010 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 2 Lamps Usage: 13,417 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:19 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
1472	2021 Trime EL1254 Light Tower S/N: 1F91A0912MC445912 C/W: Located in Lane 54 Spot 0, 2019 US EPA Label, Kubota Z482-S2-EF07e 2 Cylinder 4.5 kW .47 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, Hydraulic Raise and Lower, Ball Hitch Carrier Trailer Usage: Not Available Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Wed, Sep 16, 04:21 PM CDT Asset located in: Lake Worth, TX, USA	1478A	2011 Terex AL5000 20 kW Light Tower S/N: 00523 C/W: 2010 US EPA Label, Isuzu BV-4LE2 4 Cylinder 25.6 kW Diesel Engine, 4 Lamps, Power Receptacles, Ball Hitch Carrier Trailer Usage: 9,216 Hr Lot closing time: Wed, Sep 16, 04:23 PM CDT Asset located in: Midland, TX, USA
1472A	2019 Allmand Night-Lite 6 kW Light Tower S/N: 5AEA1DA11KN005047 C/W: Located in Lane 56, 2016 US EPA Label, Isuzu L3E 3 Cylinder 1 L Engine, 4 Lamps, Ball Hitch Carrier Trailer Usage: 8,044 Hr Lot closing time: Wed, Sep 16, 04:21 PM CDT Asset located in: Humble, TX, USA	1479	Warren Power Systems WCW204MH 25 kVA Light Tower (Inoperable) S/N: C07-06-02563 C/W: Perkins 33 hp Diesel Engine, 4 Lamps, Balloon Diffuser, Power Receptacles, Ball Hitch Carrier Trailer Usage: 13,122 Hr Lot closing time: Wed, Sep 16, 04:23 PM CDT Asset located in: Midland, TX, USA
1474	2025 Allmand Night-Lite GR-Series 6 kW Light Tower S/N: 5AEA1NA15SH021015 C/W: Tier 4, 2025 US EPA Label, Kubota 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 04:21 PM CDT Asset located in: Lake Worth, TX, USA	1480	Warren Power Systems WCW204MH 25 kVA Light Tower (Inoperable) S/N: C10-02-04209 C/W: Cat 4 Cylinder Diesel Engine, 4 Lamps, Balloon Diffuser, Power Receptacles, Ball Hitch Carrier Trailer Usage: 701 Hr Lot closing time: Wed, Sep 16, 04:23 PM CDT Asset located in: Midland, TX, USA
1475	2011 Allmand Light Tower S/N: 0309MXL11 C/W: 3 Cylinder Diesel Engine, 2 Lamps Usage: 2,138 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:22 PM CDT Asset located in: Lake Worth, TX, USA	1482	2014 Wanco WTMMB Solar Message Board S/N: 5F12S1616E1003591 C/W: Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: Not Available Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Wed, Sep 16, 04:24 PM CDT Asset located in: Lake Worth, TX, USA
1477	2013 Allmand Night-Lite Pro Light Tower S/N: 2518PRO213 C/W: Kubota D1005-BG-EF02 3 Cylinder 10.8 kW 1 L Diesel Engine, 4 Lamps, Power Receptacles Usage: 8,117 Hr Lot closing time: Wed, Sep 16, 04:22 PM CDT Asset located in: Lake Worth, TX, USA	1485	2015 Wanco WTSP Solar Arrow Board S/N: 5F11S1011F1000684 C/W: Located in Lane 54, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 04:25 PM CDT Asset located in: Lake Worth, TX, USA
1478	GrandWatt 4TN4000XD-1700 7.5 W Light Tower S/N: Not Available C/W: Tier 4, 2014 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 4 Lamps, Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 04:23 PM CDT Asset located in: Humble, TX, USA	1486A	Skyjack SJ843TH Telehandler (Inoperable) S/N: 87113304 C/W: Located in Lane 100 Spot 1, Open Operator Station, 43 ft Max Lift Height, 8000 lb Max Lift Capacity, 2022 US EPA Label, 48 in Forks, 13.00-24 Aperture Tires Usage: 1,131 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:25 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1486B	2014 JLG G12-55A Telehandler (Inoperable) S/N: 0150061177 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Outriggers, 400/75-28 Tires Usage: Not Available Notes: Aerial units require proper safety harness, lanyard, and ppe to function test and load. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:25 PM CDT Asset located in: Lake Worth, TX, USA	1488B	2019 Cat 289D Two-Speed Compact Track Loader (Inoperable) S/N: CAT0289DKTAW13460 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 18 in Track Belts, Hydraulic Coupler Usage: 6,355 Hr Notes: The closing times of lots 149 thru 152 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:26 PM CDT Asset located in: Lake Worth, TX, USA
1486C	2022 Bobcat T770 Compact Track Loader (Inoperable) S/N: AT6334961 C/W: Enclosed Cab, Joystick Steering, 18 in Track Belts, Electric Kit, Hydraulic Coupler, 79 in Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:26 PM CDT Asset located in: Lake Worth, TX, USA	1489	2020 Cat 259D3 Two-Speed Compact Track Loader (Inoperable) S/N: CAT0259DPCW902502 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Tier 4, 2019 US EPA Label, 16 in Track Belts, Manual Quick Coupler, 73 in Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:26 PM CDT Asset located in: Midland, TX, USA
1488	2021 John Deere 317G Compact Track Loader (Inoperable) S/N: 1T0317GJAMJ398347 C/W: Enclosed Cab (Door missing), Ride Control, Joystick Steering, Control Pattern Changer, Rear View Camera, 13 in Track Belts, Electric Kit, Manual Quick Coupler, 72 in Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:26 PM CDT Asset located in: Midland, TX, USA	1489A	2019 Cat 249D Two-Speed Compact Track Loader (Inoperable) S/N: CAT0249DLGWR03478 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Quick Coupler, 72 in Bucket Usage: 3,566 Hr Notes: The closing times of lots 161 thru 162 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:26 PM CDT Asset located in: Lake Worth, TX, USA
1488A	2022 Cat 289D3 Two-Speed Compact Track Loader (Inoperable) S/N: CAT0289DEJX908918 C/W: Located in Lane 100 Spot 1, Open Operator Station, Joystick Steering, Tier 4, 2021 US EPA Label, 17.5 in Track Belts, Manual Quick Coupler, 72 in Forks, Equipment-from-a-Primoris-Services-Corp-company Usage: 5,138 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:26 PM CDT Asset located in: Lake Worth, TX, USA	1491	2013 John Deere 323D Compact Track Loader (Inoperable) S/N: 1T0323DJKDG250104 C/W: Located in Lane 46 Spot 0, Enclosed Cab (Door missing), Joystick Steering, 13 in Track Belts, Manual Quick Coupler Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:27 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1491A	2020 Bobcat T740 Compact Track Loader (Inoperable) S/N: B3CA17372 C/W: Located in Lane 46 Spot 0, Open Operator Station, Joystick Steering, Control Pattern Changer, 2019 US EPA Label, 18 in Track Belts, Electric Kit, Manual Quick Coupler Usage: 2,147 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:27 PM CDT Asset located in: Humble, TX, USA	1495A	2001 Bobcat 773 Skid Steer Loader (Inoperable) S/N: 500K12085 C/W: Located in Lane 46 Spot 0, Open Operator Station, Manual Quick Coupler Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:28 PM CDT Asset located in: Humble, TX, USA
1492	2017 Kubota SVL75-2 Compact Track Loader S/N: JKUC0752P01S31175 C/W: Located in Lane 6 Spot 46, Open Operator Station, Joystick Steering, 15 in Track Belts, Hydraulic Coupler, 72 in Bucket Usage: 2,586 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:27 PM CDT Asset located in: Lake Worth, TX, USA	1496	1991 Bobcat 7753 Skid Steer Loader (Inoperable) S/N: 509611028 C/W: Located in Lane 100 Spot 1, Open Operator Station, 2001 US EPA Label Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:28 PM CDT Asset located in: Lake Worth, TX, USA
1493	2019 John Deere 324G Skid Steer Loader (Inoperable) S/N: 1T0324GKKJJ340636 C/W: Located in Lane 5 Spot 1, Open Operator Station, Joystick Steering, Aperture Tires, Hydraulic Coupler, 78 in Bucket, Counterweight Kit Usage: 1,681 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:27 PM CDT Asset located in: Humble, TX, USA	1496A	2015 Cat 420F 4x4 Backhoe Loader (Inoperable) S/N: CAT0420FTSKR04973 C/W: Located in Lane 100 Spot 1, Open Operator Station, Backhoe Pilot Controls, Powershift Transmission, 2014 US EPA Label, 94 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket Usage: 10,312 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:28 PM CDT Asset located in: Lake Worth, TX, USA
1494	2011 Case SR220 Skid Steer Skid Steer Loader (Inoperable) S/N: NBM431484 C/W: Located in Lane 46 Spot 0, Open Operator Station, Manual Quick Coupler, 72 in Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:27 PM CDT Asset located in: Humble, TX, USA	1496B	2012 John Deere 310K 4x4 Backhoe Loader (Inoperable) S/N: 1T0310EKCCG227352 C/W: Located in Lane 100 Spot 1, Enclosed Cab, Air Conditioner, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 2012 US EPA Label, 84 in Loader Bucket, Extendable Stick, Rear Quick Coupler, 18 in Backhoe Digging Bucket Usage: 5,271 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:28 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1497	2015 Case 580N 4x4 Backhoe Loader (Inoperable) S/N: JJGN580NJFC717387 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 82 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:28 PM CDT Asset located in: Midland, TX, USA	1501	2004 Komatsu WA450-5 Wheel Loader (Inoperable) S/N: KMTWA058H57A36219 C/W: Located in Lane 100 Spot 1, Enclosed Cab, Air Conditioner, Hydraulic Coupler, 125 in Bucket, 26.5R25 Tires Usage: 44,584 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:30 PM CDT Asset located in: Lake Worth, TX, USA
1498	2014 Case 580N 4x4 Backhoe Loader (Inoperable) S/N: JJGN580NJEC701396 C/W: Open Operator Station, 82 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:29 PM CDT Asset located in: Midland, TX, USA	1502	2017 Cat 930M Wheel Loader (Inoperable) S/N: CAT0930MLKTG03469 C/W: Located in Lane 6 Spot 5, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 101 in Bucket, Forks, 20.5R25 Tires Usage: 10,486 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:30 PM CDT Asset located in: Humble, TX, USA
1499	2019 Komatsu WA470-8 Wheel Loader (Inoperable) S/N: KMTWA129KLNA49698 C/W: Enclosed Cab, Air Conditioner, Ride Control, Autoshift, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 125 in Bucket, 26.5R25 Tires Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:29 PM CDT Asset located in: Midland, TX, USA	1502A	2011 Komatsu WA250-6 Wheel Loader (Inoperable) S/N: KMTWA103001076224 C/W: Enclosed Cab, Air Conditioner, 2010 US EPA Label, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:31 PM CDT Asset located in: Lake Worth, TX, USA
1500	2019 John Deere 844K-III Wheel Loader S/N: 1DW844KAJKF695450 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Loadrite On-Board Scale, Requires Diesel Exhaust Fluid, 144 in Bucket, 875/65R29 Tires Usage: 13,301 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:29 PM CDT Asset located in: Waco, TX, USA	1507	1988 Case IH 885 2WD Tractor (Inoperable) S/N: B650219B022787 C/W: Located in Lane 45 Spot 0, 8 Forward 4 Reverse, SynchroShift, 84 hp Engine, Front Weights, 2 Rear Remotes, 540/1000 PTO, 3-Point Hitch, 9.5L-15 Front Tires, 18.4x26 Rear Tires Usage: 2,754 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:31 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1508	2019 Cat D6TLGP Crawler Dozer (Inoperable) S/N: CAT00D6TCMH701009 C/W: Enclosed Cab, Air Conditioner, 159 in Wide PAT Blade, Drawbar, Rear Auxiliary Hydraulics, 30 in Single Grouser Track Shoes Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:32 PM CDT Asset located in: Midland, TX, USA	1511	Broce BW-260 Self-Propelled Broom (Inoperable) S/N: 201706 C/W: Located in Lane 45 Spot 0, Open Operator Station, 8 ft Broom, Water System, Tier 4, 2018 US EPA Label, Kubota V1505-EF01 4 Cylinder 18.2 kW 1.5 L Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:33 PM CDT Asset located in: Humble, TX, USA
1508A	2019 Komatsu D51PXi-24 Crawler Dozer (Inoperable) S/N: KMT0D133JJBB20597 C/W: Located in Lane 45 Spot 0, Enclosed Cab, Air Conditioner, Rear View Camera, Intelligent Machine Control, Requires Diesel Exhaust Fluid, 132 in Wide PAT Blade, 28 in Single Grouser Track Shoes, Drawbar Usage: 6,158 Hr Lot closing time: Wed, Sep 16, 04:32 PM CDT Asset located in: Humble, TX, USA	1512	2011 Lay-Mor 8HC Self-Propelled Broom (Inoperable) S/N: 33213 C/W: Located in Lane 100 Spot 1, Open Operator Station, Water System, Tier 4, 2010 US EPA Label, Kubota V1505-ET04 4 Cylinder 26.5 kW 1.5 L Diesel Engine Usage: 881 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:33 PM CDT Asset located in: Lake Worth, TX, USA
1509	2005 Case 850 K Crawler Dozer (Inoperable) S/N: CAL004632 C/W: Located in Lane 45 Spot 0, Open Operator Station, Sweeps, 110 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:32 PM CDT Asset located in: Humble, TX, USA	1513	Sakai SV400 Padfoot Drum Compactor (Inoperable) S/N: 3SV24-40145 C/W: Located in Lane 100 Spot 1, Open Operator Station, 68 in Drum Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:33 PM CDT Asset located in: Lake Worth, TX, USA
1510	2007 Case 650K Crawler Dozer (Inoperable) S/N: CAL012234 C/W: Located in Lane 100 Spot 1, Enclosed Cab, Air Conditioner, Sweeps, 110 in Wide PAT Blade, 20 in Single Grouser Track Shoes, Drawbar Usage: 2,341 Hr Notes: Inoperable items must be removed from yard by September 4th and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:32 PM CDT Asset located in: Lake Worth, TX, USA	1514	Sakai SV540 Padfoot Drum Compactor (Inoperable) S/N: 3SV53-10342 C/W: Located in Lane 100 Spot 1, Enclosed Cab, Diesel Engine, 84 in Drum Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:33 PM CDT Asset located in: Lake Worth, TX, USA
1510A	2002 Broce RJ350 Self-Propelled Broom (Inoperable) S/N: 402265 C/W: Located in Lane 100 Spot 1, Open Operator Station, 8 ft Broom, Water System, 4 Cylinder Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:32 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
1515	2014 Sakai SV540T Padfoot Drum Compactor (Inoperable) S/N: 3SV53-10265 C/W: Open Operator Station, 4 Cylinder Diesel Engine, 84 in Drum Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:34 PM CDT Asset located in: Lake Worth, TX, USA	1518	2011 Hyundai R290LC-9 Long Reach Tracked Excavator (Inoperable) S/N: HHHQ801JB0000891 C/W: 33 ft 7 in Boom, 25 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 59 in Cleanup Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:35 PM CDT Asset located in: Midland, TX, USA
1516	Wacker Neuson RD11A Double Drum Roller (Inoperable) S/N: 5627923 C/W: Located in Lane 104 Spot 0, Open Operator Station, Tier 3, 2006 US EPA Label, Honda 2 Cylinder Gasoline Engine, 35 in Compaction Width, Water System Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:34 PM CDT Asset located in: Humble, TX, USA	1519	2011 Hyundai R290LC-9 Tracked Excavator (Inoperable) S/N: HHH0801HB0000848 C/W: 2010 US EPA Label, 32 in Triple Grouser Track Shoes Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:35 PM CDT Asset located in: Midland, TX, USA
1516A	Ingersoll Rand PT240R 8 Wheel Pneumatic Roller (Inoperable) S/N: 197405 C/W: Open Operator Station, Dual Controls, Diesel Engine, 67 in Compaction Width Usage: 554 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:34 PM CDT Asset located in: Florence, TX, USA	1520	2019 Cat 336G Tracked Excavator (Inoperable) S/N: CAT00336VDKS00862 C/W: Air Conditioner, Straight Travel Pedal, 9 ft 7 in Stick, 33.5 in Triple Grouser Track Shoes, 71 in Cleanup Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:35 PM CDT Asset located in: Midland, TX, USA
1517	2012 Hyundai R290LC-9 Long Reach Tracked Excavator (Inoperable) S/N: HHKHZ801PC0001437 C/W: 2010 US EPA Label, 32 ft 3 in Boom, 25 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 59 in Cleanup Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:34 PM CDT Asset located in: Midland, TX, USA	1522	2015 John Deere 210G Long Reach Tracked Excavator (Inoperable) S/N: 1FF210GXCF523445 C/W: Air Conditioner, 26 ft 7 in Boom, 20 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 59 in Cleanup Bucket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:36 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
1523	2021 Takeuchi TB290 Mini Excavator (Inoperable) S/N: 185108324 C/W: Located in Lane 100 Spot 1, 2020 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 17.5 in Rubber Tracks, 18 in Digging Bucket, Thumb Bracket Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:36 PM CDT Asset located in: Lake Worth, TX, USA	1524	2023 Dasmesh 731 Track Harvester (Inoperable) S/N: DWM731D2023010 C/W: Located in Lane 45, 19.5 in Rubber Tracks Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:36 PM CDT Asset located in: Humble, TX, USA
1523A	2016 Volvo ECR40D Mini Excavator (Inoperable) S/N: VCECR40DC00014093 C/W: Located in Lane 98 Spot 1, 2016 US EPA Label, Swing Boom, 4 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 16 in Digging Bucket, Hydraulic Thumb Usage: 1,796 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:36 PM CDT Asset located in: Lake Worth, TX, USA	1524A	1997 Allen Triple Roller Tube Concrete Screed (Inoperable) S/N: TRTP979136 C/W: Located in Lane 56, 24 ft Screed, Kubota 4 Cylinder Diesel Engine, Screed Roller Extensions Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:37 PM CDT Asset located in: Lake Worth, TX, USA
1523B	2017 Cat 303E CR Mini Excavator (Inoperable) S/N: CAT0303EHHM02167 C/W: Located in Lane 98 Spot 1, Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 17 in Digging Bucket, Thumb Bracket Usage: 1,430 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:36 PM CDT Asset located in: Lake Worth, TX, USA	1525	1996 Grove AP308 8.5 ton 4x2 Carry Deck Crane (Inoperable) S/N: 83228 C/W: Located in Lane 45 Spot 0, Anti Two-Block, PAT DS150 Load Moment Indicator, 115 hrs Crane Operation, Cummins 4 Cylinder Diesel Engine, 24 ft Maximum Boom Length, 150 lb 7 ton Capacity Overhaul Ball Usage: 115 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:37 PM CDT Asset located in: Humble, TX, USA
1523C	2020 Kubota U17 Mini Excavator (Inoperable) S/N: KBCAZ24CCL3A50053 C/W: Located in Lane 4 Spot 4, Control Pattern Changer, Swing Boom, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 18 in Digging Bucket Usage: 1,506 Hr Notes: The closing times of lots 732 thru 736 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each piece will be the winner. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:36 PM CDT Asset located in: Humble, TX, USA	1526	1990 Grove AP308 8.5 ton 4x2 Carry Deck Crane (Inoperable) S/N: 73009 C/W: Located in Lane 45 Spot 0, Anti Two-Block, 6268 hrs Crane Operation, Cummins 4 Cylinder Diesel Engine, 24 ft Maximum Boom Length, 172 lb 5 ton Capacity Overhaul Ball Usage: 6,268 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:37 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1526A	Con-E-Co Concrete Batch Plant (Inoperable) S/N: C2720 C/W: Located in Lane 56 Spot 0 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:37 PM CDT Asset located in: Humble, TX, USA	1528	2016 JLG 10042 Telehandler (Inoperable) S/N: 0160077758 C/W: Located in Lane 0 Spot 0, Open Operator Station, 42 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 400 /75-28 Foam Filled Tires Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:38 PM CDT Asset located in: Humble, TX, USA
1526B	2010 Terex PR950B Tracked Cold Planer (Inoperable) S/N: 563110 C/W: Canopy, 12 ft 6 in Cutting Width, 15 in Milling Depth, Water System, 41 in Discharge Conveyor, Air Compressor, 14 in Triple Grouser Track Shoes w/Rubber Pads Usage: 995 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:37 PM CDT Asset located in: Oklahoma City, OK, USA	1528A	2014 JLG 8042 Telehandler (Inoperable) S/N: 0160061387 C/W: Located in Lane 0 Spot 0, Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 53 in Forks, Manual Coupler, 370/75-28 Foam Filled Tires Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:38 PM CDT Asset located in: Humble, TX, USA
1526C	Powerscreen Commander Portable Screen Plant (Inoperable) S/N: 403810 C/W: Located in Lane 56 Spot 0, 5 ft x 12 ft Belt Feeder w/Grizzly 28 in Impact Crusher, 35 in Wide Under Screen Conveyor, 32 in Wide End Discharge Conveyor, Deutz BF4L913 4 Cylinder 69 kW Diesel Engine, S/A Carrier Usage: 10,360 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:37 PM CDT Asset located in: Humble, TX, USA	1528B	2016 JCB 541-70 Telehandler (Inoperable) S/N: JCB5TB4HVG2465184 C/W: Enclosed Cab, Air Conditioner, 22 ft 11 in Max Lift Height, 9000 lb Max Lift Capacity, 17.5-25 Tires Usage: 5,376 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:38 PM CDT Asset located in: Lake Worth, TX, USA
1527	2013 JLG 10054 Telehandler (Inoperable) S/N: 160054345 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 5,182 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:37 PM CDT Asset located in: Midland, TX, USA	1529	2018 Skyjack SJ643 TH Telehandler (Inoperable) S/N: 87110862 C/W: Located in Lane 100 Spot 1, Open Operator Station, 43 ft Max Lift Height, 6000 lb Max Lift Capacity, 2017 US EPA Label, 47 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 13.00-24 Aperture Tires Usage: 3,182 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:38 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1530	2006 Lull 644E-42 Telehandler (Inoperable) S/N: 0160020347 C/W: Located in Lane 46 Spot 0, Enclosed Cab, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2006 US EPA Label, 60 in Forks, Tilt Carriage, Manual Coupler, 13.00-24 Aperture Tires Usage: 8,483 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:38 PM CDT Asset located in: Humble, TX, USA	1533	2012 Toyota 7FDAU50 7000 lb Pneumatic Tire Forklift (Inoperable) S/N: 70746 C/W: 2 Stage Mast, 132 in Max Lift Height, 102.5 in Lowered Mast Height, 66 in Forks, Auxiliary Hydraulic Plumbing, Fork Rotation, Fork Positioner, Solid Pneumatic Tires, 2012 US EPA Label, Toyota 15Z 6 Cylinder 5.20 L Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:39 PM CDT Asset located in: Livingston, LA, USA
1530A	2018 JCB 950-4 T4 10000 lb 4x2 Rough Terrain Forklift (Inoperable) S/N: JCB95004VJ2743432 C/W: 3 Stage Mast, 120 in Lowered Mast Height, 48 in Forks, Fork Positioner, Tier 4, EcoMAX 444 T4F 4 Cylinder 74 hp Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:38 PM CDT Asset located in: Lake Worth, TX, USA	1534	Nissan EGH02A30V 6000 lb Pneumatic Tire Forklift (Inoperable) S/N: EGH02-920023 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, Full Free Lift, 130 in Max Lift Height, Fork Rotation, Solid Pneumatic Tires, Nissan SD 25 4 Cylinder Diesel Engine Usage: 3,288 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:39 PM CDT Asset located in: Lake Worth, TX, USA
1531	2017 Hyster H300HD2 28900 lb Pneumatic Tire Forklift (Inoperable) S/N: K019E01751R C/W: Located in Lane 100 Spot 1, Enclosed Cab, 2 Stage Mast, 183.1 in Max Lift Height, 156 in Lowered Mast Height, Solid Pneumatic Tires, Cummins QSB6.7 160 6 Cylinder 160 hp 6.7 L Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:39 PM CDT Asset located in: Lake Worth, TX, USA	1534A	2020 Yale GLP060MXNEAE087 5700 lb Pneumatic Tire Forklift (Inoperable) S/N: A390V13851U C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 182 in Max Lift Height, 85 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2020 US EPA Label, PSI PSIB24LPG 4 Cylinder 2.4 L LPG Engine Usage: 1,953 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:40 PM CDT Asset located in: Lake Worth, TX, USA
1532	2014 Toyota 8FD70U 7000 lb Pneumatic Tire Forklift (Inoperable) S/N: 10139 C/W: 3 Stage Mast, 187.5 in Max Lift Height, 98.5 in Lowered Mast Height, 70 in Forks, Auxiliary Hydraulic Plumbing, Fork Rotation, Fork Positioner, Solid Pneumatic Tires, Toyota 4 Cylinder Diesel Engine Usage: 4,477 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:39 PM CDT Asset located in: Livingston, LA, USA	1534B	2020 Yale GLP060MXNEAE087 5700 lb Pneumatic Tire Forklift (Inoperable) S/N: A390V13308U C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 182 in Max Lift Height, 85 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 2020 US EPA Label, PSI PSIB24LPG 4 Cylinder 2.4 L LPG Engine Usage: 6,555 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:40 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1535	Cat V140 14000 lb Pneumatic Tire Forklift (Inoperable) S/N: 12V459 C/W: Located in Lane 98 Spot 1, 2 Stage Mast, 218 in Max Lift Height, 130 in Lowered Mast Height, 71 in Forks, Side Shift Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:40 PM CDT Asset located in: Lake Worth, TX, USA	1538	2007 JLG 1350SJP 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: 300121639 C/W: 135 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, Onboard Generator, 2008 US EPA Label, Deutz 4 Cylinder 3.6 L Diesel Engine, 445 /50D710 Solid Tires Usage: 8,229 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 04:41 PM CDT Asset located in: Midland, TX, USA
1536	Nissan CPH02A25V 4700 lb Cushion Tire Forklift (Inoperable) S/N: CPH02906703 C/W: Located in Lane 36 Spot 0, 3 Stage Mast, 187 in Max Lift Height, 82 in Lowered Mast Height, Side Shift, Nissan 4 Cylinder LPG Engine Usage: 680 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:40 PM CDT Asset located in: Humble, TX, USA	1540	2018 Skyjack SJ85 AJ 4WD Diesel Articulating Boom Lift (Inoperable) S/N: 95400220 C/W: Located in Lane 72 Spot 19, 85 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625NHS Foam-Filled Tires Usage: 2,751 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading; Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 04:41 PM CDT Asset located in: Humble, TX, USA
1536A	2005 Clark C25L 4500 lb Cushion Tire Forklift (Inoperable) S/N: C23210909592KF C/W: Located in Lane 62, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, NGV1 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:40 PM CDT Asset located in: Humble, TX, USA	1540A	2018 Genie S-65 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: S60H-39014 C/W: Located in Lane 100 Spot 1, 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.92 L Diesel Engine, 355/55D625 Tires Usage: 2,876 Hr Notes: Aerial units require proper safety harness, lanyard, and ppe to function test and load. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:41 PM CDT Asset located in: Lake Worth, TX, USA
1536B	2020 Toyota 8FBE20U 3450 lb Electric Forklift (Inoperable) S/N: 19421 C/W: Located in Lane 53 Spot 1, 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Battery Watering System Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:40 PM CDT Asset located in: Lake Worth, TX, USA		
1537	2023 Toyota 8HBE30 6000 lb Electric Pallet Jack (Inoperable) S/N: 8HBE3054203 C/W: Self-Propelled, 24 V, Battery Charger Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:40 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
1541	2012 Genie S-65 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: S6012-23722 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D2011L03I 3 Cylinder 49 hp 2.332 L Diesel Engine, 355/55D625 Tires Usage: 3,838 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 04:42 PM CDT Asset located in: Livingston, LA, USA	1543A	2018 JLG E300AJP 2WD Electric Articulating Boom Lift (Inoperable) S/N: 0300243080 C/W: Located in Lane 72, 30 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, 25x7-12 Non-Marking Tires Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 04:42 PM CDT Asset located in: Humble, TX, USA
1542	2017 JGL 600S 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: 300224670 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2016 US EPA Label, Deutz 4 Cylinder 2.9 L Diesel Engine, 39-15/22.5 Foam-Filled Tires Usage: 5,547 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. ;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 04:42 PM CDT Asset located in: Midland, TX, USA	1544	2019 JLG T500J Towable Lift (Inoperable) S/N: 0030011130 C/W: Located in Lane 71, 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 394 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:42 PM CDT Asset located in: Humble, TX, USA
1542A	2018 Haulotte HA46RTJO 4WD Diesel Articulating Boom Lift (Inoperable) S/N: 2038846 C/W: Located in Lane 98 Spot 1, 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2018 US EPA Label, Kubota V1505-EF01e 4 Cylinder 18.2 kW 1.5 L Diesel Engine, 850x340 Aperture Tires Usage: Not Available Notes: Aerial units require proper safety harness, lanyard, and ppe to function test and load. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:42 PM CDT Asset located in: Lake Worth, TX, USA	1545	Skyjack SJ7135 4x4 Gasoline Scissor Lift (Inoperable) S/N: 34001465R C/W: Located in Lane 55 Spot 1, 35 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2007 US EPA Label, Kubota DF972-ES 3 Cylinder Dual Fuel Engine Usage: 4,209 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. ; aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 04:43 PM CDT Asset located in: Lake Worth, TX, USA
		1545A	2020 Genie GS-4390 4x4 Diesel Scissor Lift (Inoperable) S/N: GS90F56084 C/W: Located in Lane 55 Spot 1, 43 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2020 US EPA Label, Deutz 4 Cylinder 2.9 L Diesel Engine Usage: Not Available Notes: Aerial units require proper safety harness, lanyard, and ppe to function test and load. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 03:18 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1546	2012 Genie GS3232 Electric Scissor Lift (Inoperable) S/N: GS3212A-111643 C/W: Located in Lane 47 Spot 0, 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: Not Available Notes: ;Aerial units require proper safety harness, lanyard, and ppe to function test and loa; Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:43 PM CDT Asset located in: Humble, TX, USA	1549A	2019 Snorkel TM12E Vertical Mast Lift (Inoperable) S/N: TM12E-11-191100460 C/W: Located in Lane 55 Spot 1, 12 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:44 PM CDT Asset located in: Lake Worth, TX, USA
1547	2007 JLG 2030ES Electric Scissor Lift (Inoperable) S/N: 0200157518 C/W: Located in Lane 47 Spot 0, 20 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 239 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal;;Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Wed, Sep 16, 04:43 PM CDT Asset located in: Humble, TX, USA	1550	Cummins 300DFCB 300 kW Skid-Mounted Generator Set (Inoperable) S/N: B940533648 C/W: Located in Lane 56, Cummins NTA-855-G2 6 Cylinder 465 hp 855 cid Diesel Engine, 375 kVA/300 kW Rated 3 Phase Output Usage: 1,807 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:44 PM CDT Asset located in: Humble, TX, USA
1548	2016 JLG 20MVL Vertical Mast Lift (Inoperable) S/N: 0130024069 C/W: Located in Lane 70, 19 ft 5 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:44 PM CDT Asset located in: Humble, TX, USA	1550A	2018 Multiquip DCA300SSJU4F2 250 kW Mobile Generator Set (Inoperable) S/N: 5SLBG1929JL022328 C/W: Located in Lane 56 Spot 0, 2017 US EPA Label, John Deere 6090HFG06 5 Cylinder 560 kW 9 L Diesel Engine, Requires Diesel Exhaust Fluid, /250 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, Lunette Ring Carrier Trailer, Electric Brakes Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:44 PM CDT Asset located in: Humble, TX, USA
1549	2012 JLG 1230ES Vertical Mast Lift (Inoperable) S/N: 0200211693 C/W: Located in Lane 55 Spot 1, 12 ft Max Platform Height, Solid Non-Marking Tires, Upper Control Box Usage: 554 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:44 PM CDT Asset located in: Lake Worth, TX, USA	1551	Cummins DGEA-3382463 125 kW Skid-Mounted Generator Set (Inoperable) S/N: L990030113 C/W: Located in Lane 54 Spot 0, 1999 US EPA Label, Cummins 6CT8.3-G2 6 Cylinder Diesel Engine, 156.3 kVA/125 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 83.8 kVA, /83.8 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Bottom Mounted Fuel Tank Usage: 321 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:45 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1552	2016 Multiquip DCA-125SSIU4F 100 kW Mobile Generator Set (Inoperable) S/N: 5SLBG1526GL018249 C/W: Located in Lane 56, 2015 US EPA Label, Isuzu BR4HK1X 4 Cylinder 127.4 kW 5.193 L Diesel Engine, Requires Diesel Exhaust Fluid, 125 kVA/100 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 72 kVA,/72 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Lunette Ring Carrier Trailer, Surge Brakes Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:45 PM CDT Asset located in: Humble, TX, USA	1554	2020 Shindaiwa DGK15F 12 kW Mobile Generator Set (Inoperable) S/N: 7KUBB0913LJ089523 C/W: Located in Lane 36 Spot 0, Kubota D902 3 Cylinder Diesel Engine, 15 kVA/ Rated 3 Phase Output, 240 V Rated Voltage, /12 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, Lunette Ring Carrier Trailer Usage: 2,166 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading.**No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Wed, Sep 16, 04:45 PM CDT Asset located in: Humble, TX, USA
1553	2013 Atlas Copco QAS 90 JDS 72 kW Mobile Generator Set (Inoperable) S/N: HOP101343 C/W: Located in Lane 52 Spot 0, John Deere 4045 4 Cylinder 4.5 L Diesel Engine, /72 kW Rated 3 Phase Output, 480 V / 240 V / 208 V Rated Voltage, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading.**No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Wed, Sep 16, 04:45 PM CDT Asset located in: Humble, TX, USA	1555	2014 Kohler 22 kW Skid-Mounted Stand-by Generator Set (Inoperable) S/N: SIM320448 C/W: Located in Lane 56 Spot 0, 2014 US EPA Label, Kohler EKHXX2.48ESM 4 Cylinder 2.48 L Diesel Engine, 22 kVA,/22 kW, Rated Single Phase Output, 240 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Humble, TX, USA
1553A	2015 HiPower HRYW25T6 26 kVA Mobile Generator Set (Inoperable) S/N: 1M9BU0810FN631544 C/W: Located in Lane 56, Yanmar 4 Cylinder Diesel Engine, 26 kVA/ Rated 3 Phase Output, 208 V / 480 V Rated Voltage, 16.5 kVA,/ Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 12,468 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:45 PM CDT Asset located in: Humble, TX, USA	1555A	2020 Doosan P250 Mobile Air Compressor (Inoperable) S/N: 4FVCABBA0LU498504 C/W: 2019 US EPA Label, Doosan 4 Cylinder Diesel Engine, Ball Hitch Carrier Trailer Usage: 988 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership ; Additional Information Available in Office - Manufacture Certificate of Origin. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Lake Worth, TX, USA
		1555B	2019 Sullair 425DH/DPQ/PE4F 425 cfm Mobile Air Compressor (Inoperable) S/N: 201909200026 C/W: Located in Lane 56, 150 bar Working Pressure, Perkins Diesel Engine, Requires Diesel Exhaust Fluid, Lunette Ring Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1555C	2009 Ingersoll Rand 375 Mobile Air Compressor (Inoperable) S/N: 4FVCBBBA59U406485 C/W: John Deere 4 Cylinder Diesel Engine, Lunette Ring Carrier Trailer Usage: 4,734 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Midland, TX, USA	1557	2021 Miller Big Blue 500D Engine Driven Welder (Inoperable) S/N: NB130518R C/W: Located in Lane 53 Spot 0, 4 Cylinder Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, Reversible Hitch Carrier Trailer Usage: 4,896 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Humble, TX, USA
1556	2018 Sullair 185DPQ-KU-T3 185 cfm Mobile Air Compressor (Inoperable) S/N: 201801190049 C/W: 100 psi Working Pressure, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Lake Worth, TX, USA	1558	2013 Hydra Rig HR6100 Injector Equipment (Inoperable) S/N: CC303105 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Wed, Sep 16, 04:47 PM CDT Asset located in: Pecos, TX, USA
1556A	2018 Sullair 185 185 cfm Mobile Air Compressor (Inoperable) S/N: 201810300051 C/W: Located in Lane 56, 2018 US EPA Label, Kubota D1803 3 Cylinder 36.5 kW 1.8 L Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Humble, TX, USA	1559	2012 Loadcraft 2250 Frac Pump S/N: 5ABK44209CB120398 C/W: 2012 US EPA Label, Cummins QSKTA50-CE 16 Diesel Engine Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Wed, Sep 16, 04:47 PM CDT Asset located in: Pecos, TX, USA
1556B	2023 Atlas Copco CPS175 175 cfm Mobile Air Compressor (Inoperable) S/N: YA3C1CA13P0873583 C/W: Located in Lane 54, 7 bar Working Pressure, 2022 US EPA Label, Kubota V1505-CR-T-EW02 4 Cylinder 32.5 kW 1.5 L Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:46 PM CDT Asset located in: Lake Worth, TX, USA	1560	Pioneer Pump PP108S17-0054 Trailer-Mounted Water Pump (Inoperable) S/N: PP31281 C/W: 8 in Intake, 8 in Discharge, John Deere 6 Cylinder Diesel Engine, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:47 PM CDT Asset located in: Lake Worth, TX, USA
		1561	1997 Schwing BPA450 Concrete Pump (Inoperable) S/N: 1S9PD1317VM544113 C/W: Located in Lane 46 Spot 0, Deutz 4 Cylinder Diesel Engine, Schwing BPA 450 Pump, Ball Hitch Carrier Trailer Usage: 336 Hr Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Wed, Sep 16, 04:48 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1562	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0840PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:48 PM CDT Asset located in: Humble, TX, USA	1567	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0556PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: 1,151 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:49 PM CDT Asset located in: Humble, TX, USA
1563	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0810PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 cc Diesel Engine, 4 Lamps, Electric Winch Raise and Lower Usage: 1,962 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:48 PM CDT Asset located in: Humble, TX, USA	1568	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0845PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota S1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: 911 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:50 PM CDT Asset located in: Humble, TX, USA
1564	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0827PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: 1,714 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:48 PM CDT Asset located in: Humble, TX, USA	1569	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0796PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota D1105 12.6 kW 1.1 L Diesel Engine, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: 1,379 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:50 PM CDT Asset located in: Humble, TX, USA
1565	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0558PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Electric Winch Raise and Lower Usage: 1,778 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:49 PM CDT Asset located in: Humble, TX, USA	1570	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0828PRO2V14 C/W: Located in Lane 45 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: 1,619 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:50 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1571	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0811PRO2V14 C/W: Located in Lane 46 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: 1,577 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:51 PM CDT Asset located in: Humble, TX, USA	1575	2018 Wacker Neuson LTV6L 6 kW Light Tower (Inoperable) S/N: Not Available C/W: Located in Lane 46 Spot 0, 2018 US EPA Label, Kohler JKHXL1.37SF1 3 Cylinder 1.028 L Diesel Engine, 4 Lamps, Power Receptacles, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 1,773 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:52 PM CDT Asset located in: Humble, TX, USA
1572	2014 Allmand Night-Lite Pro II 8 kW Light Tower (Inoperable) S/N: 0540PRO2V14 C/W: Located in Lane 46 Spot 0, 2013 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 3 Lamps, Electric Winch Raise and Lower, Reversible Hitch Carrier Trailer Usage: 1,774 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:51 PM CDT Asset located in: Humble, TX, USA	1575A	2018 Wacker Neuson Light Tower (Inoperable) S/N: 5XFLV0413JM003157 C/W: Ball Hitch Carrier Trailer Usage: Not Available Lot closing time: Wed, Sep 16, 04:52 PM CDT Asset located in: Midland, TX, USA
1573	Allmand Light Tower (Inoperable) S/N: Not Available C/W: Located in Lane 46 Spot 0, Reversible Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:51 PM CDT Asset located in: Humble, TX, USA	1576	2020 Allmand Night-lite V Series NLV 6 kW Light Tower (Inoperable) S/N: 5AEA1DA13LH007299 C/W: Located in Lane 46 Spot 0, Perkins 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, Ball Hitch Carrier Trailer Usage: 1,139 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal Lot closing time: Wed, Sep 16, 04:52 PM CDT Asset located in: Humble, TX, USA
1574	2021 Generac MLT4060K 6 kW Light Tower (Inoperable) S/N: 7FSXL1412MB064824 C/W: 2019 US EPA Label, Kubota D1105-BG-EF02 3 Cylinder 10.6 kW 1.0 L Diesel Engine Usage: 1,084 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Wed, Sep 16, 04:51 PM CDT Asset located in: Lake Worth, TX, USA	1577	2018 Wacker Neuson LTV8 8 kW Light Tower (Inoperable) S/N: 5XFLV0417JM001928 C/W: Located in Lane 45 Spot 0, 2018 US EPA Label, Kubota D1105 3 Cylinder 12.4 kW 1.1 L Diesel Engine, 4 Lamps, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 1,053 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:52 PM CDT Asset located in: Humble, TX, USA
		1578	2018 Wacker Neuson LTV8 8 kW Light Tower (Inoperable) S/N: 5XFLV0418JM001923 C/W: Located in Lane 45 Spot 0, 2018 US EPA Label, Kubota D1105 3 Cylinder 12.4 kW 1.1 L Diesel Engine, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 6,361 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:53 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1578A	Wacker Neuson LTV6L Light Tower (Inoperable) S/N: WNCLTV01CPUM01342 C/W: Kohler 3 Cylinder 1.02 L Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:53 PM CDT Asset located in: Lake Worth, TX, USA	1581	2013 Terex AL4 6 kW Light Tower (Inoperable) S/N: 4ZUSB1416D1002165 C/W: Located in Lane 46 Spot 0, 2012 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:54 PM CDT Asset located in: Humble, TX, USA
1579	2015 Terex RL4 6 kW Light Tower (Inoperable) S/N: 4ZJSA1415F1012336 C/W: 2014 US EPA Label, Kubota D1105-BG-EF01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 3 Lamps, Power Receptacles Usage: 10,117 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:53 PM CDT Asset located in: Lake Worth, TX, USA	1582	2013 Terex AL4 6 kW Light Tower (Inoperable) S/N: 4ZJSB1412D1002115 C/W: Located in Lane 46 Spot 0, 2012 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 9,049 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:54 PM CDT Asset located in: Humble, TX, USA
1579A	2015 Terex RL4 6 kW Light Tower (Inoperable) S/N: 4ZJSA1411F102334 C/W: 2014 US EPA Label, Kubota D1105-BG-EF01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, Ball Hitch Carrier Trailer Usage: 7,238 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:53 PM CDT Asset located in: Lake Worth, TX, USA	1583	2013 Terex 6 kW Light Tower (Inoperable) S/N: 4ZJSB141XD1002069 C/W: Located in Lane 46 Spot 0, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 8,711 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:54 PM CDT Asset located in: Humble, TX, USA
1580	2013 Terex AL4 6 kW Light Tower (Inoperable) S/N: 4ZJSB1413D1002060 C/W: Located in Lane 46 Spot 0, 2012 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Single Lamp, Balloon Diffuser, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 1,773 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:53 PM CDT Asset located in: Humble, TX, USA	1584	2013 Terex AL4 6 kW Light Tower (Inoperable) S/N: 4ZJSB1413D1002169 C/W: Located in Lane 46 Spot 0, 2012 US EPA Label, Kubota D1105 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Single Lamp, Balloon Diffuser, Electric Winch Raise and Lower, Ball Hitch Carrier Trailer Usage: 1,917 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:54 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1585	2011 Terex RL4000 6 kW Light Tower (Inoperable) S/N: 4ZJSL1410B1003662 C/W: 2011 US EPA Label, Kubota D1105-BG-ET01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, Ball Hitch Carrier Trailer Usage: 15,685 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:55 PM CDT Asset located in: Lake Worth, TX, USA	1587	2010 Terex RL4000 6 kW Light Tower (Inoperable) S/N: 4ZJSL1412A1003144 C/W: 2010 US EPA Label, Kubota D1105-BG-ET01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, Single Lamp, Power Receptacles, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:55 PM CDT Asset located in: Lake Worth, TX, USA
1586	2011 Terex RL4 6 kW Light Tower (Inoperable) S/N: 4ZJSL1417B1003660 C/W: 2011 US EPA Label, Kubota D1105-BG-ET01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 3 Lamps, Power Receptacles Usage: 9,167 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:55 PM CDT Asset located in: Lake Worth, TX, USA	1588	2005 Genie Light Tower (Inoperable) S/N: 5D8LC14115R001412 C/W: 3 Cylinder Diesel Engine, 4 Lamps, Ball Hitch Carrier Trailer Usage: 11,669 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:56 PM CDT Asset located in: Lake Worth, TX, USA
1586A	2010 Terex RL4000 6 kW Light Tower (Inoperable) S/N: 4ZJSL1410A1003143 C/W: 2010 US EPA Label, Kubota D1105-BG-ET01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 2 Lamps, Power Receptacles, Ball Hitch Carrier Trailer Usage: 10,924 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:55 PM CDT Asset located in: Lake Worth, TX, USA	1588A	2014 Wanco WTLMB Solar Message Board (Inoperable) S/N: 5F12S1613E1002009 C/W: Located in Lane 54, Solar Powered, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Wed, Sep 16, 04:56 PM CDT Asset located in: Lake Worth, TX, USA
1586B	2010 Terex RL4000 6 kW Light Tower (Inoperable) S/N: 4ZJSL1411A1003149 C/W: Kubota D1105-BG-ET01 3 Cylinder 12.6 kW 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, Ball Hitch Carrier Trailer Usage: 11,447 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Wed, Sep 16, 04:55 PM CDT Asset located in: Lake Worth, TX, USA	1589	2004 Yamaha Grizzly 660 4x4 ATV S/N: JY4AM03Y04C038714 C/W: Located in Lane 100 Spot 0, Electric Start, Liquid Cooled, 2 Forward Gears w/ Reverse, 410 Engine Hours, Yamaha 1 Cylinder 660 cc Gasoline Engine Usage: 410 Hr Lot closing time: Thu, Sep 17, 09:00 AM CDT Asset located in: Humble, TX, USA
		1590	2026 Boulder D125 CC 4x2 ATV (Unused) S/N: L9NACFDK0T1302933 C/W: Located in Lane 100 Spot 0, Electric Start, 1 Cylinder Gasoline Engine Usage: Not Available Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Thu, Sep 17, 09:00 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1591	2025 Boulder B110 CC 4x2 ATV (Unused) S/N: A9BABDDDD0S2003307 C/W: Located in Lane 100 Spot 0, Electric Start, 1 Cylinder Gasoline Engine Usage: Not Available Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Thu, Sep 17, 09:00 AM CDT Asset located in: Humble, TX, USA	1596B	2024 Odes Industries Workcross 1000-3 HVAC 4x4 Utility Vehicle S/N: 0D1BRXA0LR0355862 C/W: Located in Lane 63 Spot 0, Enclosed Cab, Air Conditioner, 3 Passenger, Windshield, Rear Screen, Locking Front Differential, Winch, Brush Guard, Hitch Receiver, Manual Dump Bed, 2024 US EPA Label, Lil Pickup RLLPPP202BZD 2 Cylinder 976 cc Gasoline Engine Usage: 3 Mi Lot closing time: Thu, Sep 17, 09:01 AM CDT Asset located in: Humble, TX, USA
1592	2022 Tao Tao 4x2 ATV S/N: L9NACFB34N1402404 C/W: Located in Lane 78 Spot 1, Electric Start, US EPA Label Usage: Not Available Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Thu, Sep 17, 09:00 AM CDT Asset located in: Lake Worth, TX, USA	1597	2023 John Deere 4x4 Utility Vehicle S/N: 1M0855MBVPM060074 C/W: Located in Lane 63 Spot 0, Open Operator Station, 4 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, John Deere 3TNV70-AJUV 3 Cylinder Diesel Engine, Equipment-from-a-Primoris-Services-Corp-company Usage: 1,744 Hr Notes: Off highway use only. Temporary tags will not be issued. Lot closing time: Thu, Sep 17, 09:01 AM CDT Asset located in: Humble, TX, USA
1593	2022 Polaris RZR 4x4 Utility Vehicle S/N: 4XAP4ED45N8128795 C/W: Located in Lane 63 Spot 0, Open Operator Station, 4 Passenger, Hitch Receiver, Manual Dump Bed, Tier 4, 2021 US EPA Label, Kubota D902-EF01 3 Cylinder 18.2 kW 0.898 L Diesel Engine Usage: 1,644 Hr Lot closing time: Thu, Sep 17, 09:00 AM CDT Asset located in: Humble, TX, USA	1598	2023 John Deere Gator 4x4 Utility Vehicle S/N: 1M0855MBPPM060814 C/W: Open Operator Station, 4 Passenger, Windshield, Locking Front Differential, Brush Guard, Hitch Receiver, Manual Dump Bed, 2016 US EPA Label, John Deere 3TNV70-AJUV 3 Cylinder Diesel Engine, Equipment-from-a-Primoris-Services-Corp-company Usage: 7,293 Mi Notes: Off highway use only. Temporary tags will not be issued. Lot closing time: Thu, Sep 17, 09:02 AM CDT Asset located in: Livingston, LA, USA
1594A	2018 Polaris Ranger 570 Crew 4x4 Utility Vehicle S/N: 3NSRDA573JE362032 C/W: Located in Lane 63, Canopy, 6 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, Polaris 1 Cylinder Diesel Engine Usage: 1,687 Hr Notes: Off highway use only. Temporary tags will not be issued. Lot closing time: Thu, Sep 17, 09:01 AM CDT Asset located in: Humble, TX, USA	1599	2022 John Deere 855M 4x4 Utility Vehicle S/N: 1M0855MBTNM051154 C/W: Located in Lane 78 Spot 1, Canopy, 4 Passenger, Windshield, Manual Dump Bed, 2022 US EPA Label, John Deere Diesel Engine, Equipment-from-a-Primoris-Services-Corp-company Usage: 7,098 Hr Lot closing time: Thu, Sep 17, 09:02 AM CDT Asset located in: Lake Worth, TX, USA
1596	2019 Kubota RTV-XG850W-A 4x4 Utility Vehicle S/N: A5KH1PGNHKG017664 C/W: Located in Lane 78 Spot 1, Canopy, 2 Passenger, Locking Front Differential, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kubota .85 L Gasoline Engine Usage: 1,648 Hr Lot closing time: Thu, Sep 17, 09:01 AM CDT Asset located in: Lake Worth, TX, USA	1606	2022 John Deere XUV855MS4 4x4 Utility Vehicle S/N: 1M0855MBHNM051201 C/W: Located in Lane 78 Spot 1, Canopy, 4 Passenger, Windshield, Manual Dump Bed, John Deere 3TNV70-AJUV 3 Cylinder Diesel Engine, Equipment-from-a-Primoris-Services-Corp-company Usage: 4,856 Hr Lot closing time: Thu, Sep 17, 09:03 AM CDT Asset located in: Lake Worth, TX, USA
1596A	2022 Kawasaki Pro-FXR820 4x4 Utility Vehicle S/N: JKBAFSK18NB510859 C/W: Located in Lane 63 Spot 0, Canopy, 3 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2022 US EPA Label, Kawasaki Nkaxpp402b02 3 Cylinder 0.812 L Diesel Engine Usage: 157 Hr Lot closing time: Thu, Sep 17, 09:01 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
1607	2023 John Deere XUV855MS4 4x4 Utility Vehicle S/N: 1M0855MBJPM060024 C/W: Located in Lane 63 Spot 0, Open Operator Station, 4 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, John Deere 3TNV70-AJUV 3 Cylinder Diesel Engine, Equipment-from-a-Primoris-Services-Corp-company Usage: 1,031 Hr Notes: Off highway use only. Temporary tags will not be issued. Lot closing time: Thu, Sep 17, 09:04 AM CDT Asset located in: Humble, TX, USA	1614	2019 Can-Am 6XKA 4x4 Utility Vehicle S/N: 3JBUGAR22KK001706 C/W: Open Operator Station, 3 Passenger, Winch, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, BRP 1 Cylinder 427 cc Gasoline Engine Usage: 1,213 Mi Lot closing time: Thu, Sep 17, 09:05 AM CDT Asset located in: Livingston, LA, USA
1608	2020 John Deere Gator TX 4X2 4x2 Utility Vehicle S/N: 1M04X2XDJLM150210 C/W: Located in Lane 63, Open Operator Station, 2 Passenger, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kawasaki 2 Cylinder Gasoline Engine Usage: 5,523 Hr Lot closing time: Thu, Sep 17, 09:04 AM CDT Asset located in: Humble, TX, USA	1615	2018 Can-Am 6XKA 4x4 Utility Vehicle S/N: 3JBUGAR22KK001589 C/W: Open Operator Station, 3 Passenger, Winch, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, BRP 1 Cylinder 427 cc Gasoline Engine Usage: 2,575 Mi Lot closing time: Thu, Sep 17, 09:06 AM CDT Asset located in: Livingston, LA, USA
1609	2019 John Deere XUV835M 4x4 Utility Vehicle S/N: 1M0835MACKM021854 C/W: Open Operator Station, 3 Passenger, Windshield, Locking Front Differential, Winch, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, John Deere 3 Cylinder Gasoline Engine Usage: 438 Hr Lot closing time: Thu, Sep 17, 09:04 AM CDT Asset located in: Livingston, LA, USA	1616	2018 Can-Am 6XJB 4x4 Utility Vehicle S/N: 3JBUGAR23JK001048 C/W: Open Operator Station, 3 Passenger, Winch, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, BRP 1 Cylinder 427 cc Gasoline Engine Usage: 1,733 Mi Lot closing time: Thu, Sep 17, 09:06 AM CDT Asset located in: Livingston, LA, USA
1611	2019 John Deere Gator TX 4x2 Utility Vehicle S/N: 1M04X2XDCKM143654 C/W: Located in Lane 63, Open Operator Station, 2 Passenger, Hitch Receiver, Manual Dump Bed, 2022 US EPA Label, Kawasaki 2 Cylinder Gasoline Engine Usage: 2,851 Hr Lot closing time: Thu, Sep 17, 09:05 AM CDT Asset located in: Humble, TX, USA	1617	2018 Can-Am 6XJB 4x4 Utility Vehicle S/N: 3JBUGAR21JK000867 C/W: Open Operator Station, 3 Passenger, Winch, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, BRP 1 Cylinder 427 cc Gasoline Engine Usage: 850 Mi Lot closing time: Thu, Sep 17, 09:06 AM CDT Asset located in: Livingston, LA, USA
1612	2018 Can-Am 6XKA 4x4 Utility Vehicle S/N: 3JBUGAR24KK000007 C/W: Open Operator Station, 3 Passenger, Winch, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, BRP 1 Cylinder 427 cc Gasoline Engine Usage: 408 Mi Lot closing time: Thu, Sep 17, 09:05 AM CDT Asset located in: Livingston, LA, USA	1618	2018 Can-Am 6XJB 4x4 Utility Vehicle S/N: 3JBUGAR28JK000462 C/W: Open Operator Station, 3 Passenger, Winch, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, BRP 1 Cylinder 427 cc Gasoline Engine Usage: 2,497 Mi Lot closing time: Thu, Sep 17, 09:06 AM CDT Asset located in: Livingston, LA, USA
1613	2020 Can-Am 4x4 Utility Vehicle S/N: 3JBUGAR28LK000058 C/W: Open Operator Station, 3 Passenger, Locking Front Differential, Winch, Hitch Receiver, Manual Dump Bed, 2020 US EPA Label, BRP 1 Cylinder 427 cc Gasoline Engine Usage: 1,747 Mi Lot closing time: Thu, Sep 17, 09:05 AM CDT Asset located in: Livingston, LA, USA	1619	2016 Can-Am 6WHA 4x4 Utility Vehicle S/N: 3JBUGAN41HK000692 C/W: Enclosed Cab, 3 Passenger, Winch, Hitch Receiver, Manual Dump Bed, 2017 US EPA Label, BRP 1 Cylinder 800 cc Gasoline Engine Usage: 3,687 Mi Lot closing time: Thu, Sep 17, 09:07 AM CDT Asset located in: Livingston, LA, USA

Lot #	Details	Lot #	Details
1620	2017 Can-Am 6WHA 4x4 Utility Vehicle S/N: 3JBUGAN40HK000862 C/W: Enclosed Cab, 3 Passenger, Locking Front Differential, Winch, Hitch Receiver, Manual Dump Bed, 2017 US EPA Label, BRP 1 Cylinder 800 cc Gasoline Engine Usage: 1,948 Mi Lot closing time: Thu, Sep 17, 09:07 AM CDT Asset located in: Livingston, LA, USA	1626	2026 HQ100 Electric White Six-Seater Golf Cart (Unused) S/N: LC10026041223 C/W: Located in Lane 50 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:08 AM CDT Asset located in: Humble, TX, USA
1622	2023 Club Car Carryall 1700 4x4 Utility Vehicle S/N: A5CUAA4EPPA398766 C/W: Canopy, 4 Passenger, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 1,232 Hr Lot closing time: Thu, Sep 17, 09:07 AM CDT Asset located in: San Antonio, TX, USA	1628	2026 HQ100 Electric Quantity of (2) White Six-Seater Golf Cart (Unused) S/N: LC10026050962 C/W: Located in Lane 50 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:09 AM CDT Asset located in: Humble, TX, USA
1623	2020 Club Car Carryall-II 4x4 Utility Vehicle S/N: A5CUAA4ECLA053177 C/W: Located in Lane 78 Spot 1, Canopy, 4 Passenger, Windshield, Manual Dump Bed, Tier 4, US EPA Label, Kubota 3 Cylinder Diesel Engine Usage: 1,048 Hr Notes: No title available, sold with bill of sale only ; Additional Information Available in Office - Manufacture Certificate of Origin Lot closing time: Thu, Sep 17, 09:07 AM CDT Asset located in: Lake Worth, TX, USA	1629	2026 HQ100 Electric Quantity of (3) White Six-Seater Golf Cart (Unused) S/N: LC10026050681 C/W: Located in Lane 50 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:09 AM CDT Asset located in: Humble, TX, USA
1624	2025 IRGC40 3-Wheel Utility Cart S/N: H52ZYF7T3SA014643 C/W: Located in Lane 100 Spot 0, Open Operator Station, 2 Passenger Usage: Not Available Lot closing time: Thu, Sep 17, 09:08 AM CDT Asset located in: Humble, TX, USA	1632	2026 HQ100 Electric Gray Six-Seater Golf Cart (Unused) S/N: LC10026051599 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
1624A	2025 Kawasaki KNT009ASFNN Electric Golf Cart S/N: JK1NTJA1XSB500095 C/W: Located in Lane 63 Spot 0, Battery Charger, 4 Passenger, Canopy Usage: 62 Hr Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Thu, Sep 17, 09:08 AM CDT Asset located in: Humble, TX, USA	1633	2026 HQ100 Electric White Six-Seater Golf Cart (Unused) S/N: SDLC10026051622 C/W: Located in Lane 78 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
1625	SDLANCH HQ100 Electric Golf Cart (Unused) S/N: SDLC10026060367 C/W: Located in Lane 63 Spot 0, Battery Charger, 6 Passenger, Canopy, Windshield Usage: Not Available Lot closing time: Thu, Sep 17, 09:08 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
1634	2026 HQ100 Electric White Six-Seater Golf Cart (Unused) S/N: SDLC10026060195 C/W: Located in Lane 78 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:10 AM CDT Asset located in: Lake Worth, TX, USA	1639	2026 HQ100 Electric White Six-Seater Golf Cart (Unused) S/N: SDLC10026060369 C/W: Located in Lane 78 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:11 AM CDT Asset located in: Lake Worth, TX, USA
1635	2026 HQ100 Electric White Six-Seater Golf Cart (Unused) S/N: SDLC10026051606 C/W: Located in Lane 78 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:10 AM CDT Asset located in: Lake Worth, TX, USA	1640	2026 HQ100 Electric White Six-Seater Golf Cart (Unused) S/N: LC10026050878 C/W: Located in Lane 78 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:11 AM CDT Asset located in: Lake Worth, TX, USA
1636	2026 HQ100 Electric Gray Six-Seater Golf Cart (Unused) S/N: LC10026051425 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:10 AM CDT Asset located in: Lake Worth, TX, USA	1641	2026 HQ100 Electric Quantity of (3) Gray Six-Seater Golf Cart (Unused) S/N: SDLC10026051557 C/W: Located in Lane 50 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:12 AM CDT Asset located in: Humble, TX, USA
1637	2026 HQ100 Electric White Six-Seater Golf Cart (Unused) S/N: LC10026050869 C/W: Located in Lane 78 Spot 1, 48 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:11 AM CDT Asset located in: Lake Worth, TX, USA	1647	2026 HQ100 Electric Quantity of 3 Gray Six-Seater Golf Cart (Unused) S/N: SDLC10026060002 C/W: Located in Lane 50 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:13 AM CDT Asset located in: Humble, TX, USA
1638	2026 HQ100 Electric Gray Six-Seater Golf Cart (Unused) S/N: SDLC10026051524 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:11 AM CDT Asset located in: Lake Worth, TX, USA	1649	2026 HQ100 Electric Quantity of (3) Gray Six-Seater Golf Cart (Unused) S/N: SDLC10026060003 C/W: Located in Lane 50 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:14 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1653	2026 HQ100 Electric Quantity of (3) Gray Six-Seater Golf Cart (Unused) S/N: SDLC10026060933 C/W: Located in Lane 50 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:14 AM CDT Asset located in: Humble, TX, USA	1660	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S261983 C/W: Located in Lane 50 Spot 1, 6 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available Lot closing time: Thu, Sep 17, 09:16 AM CDT Asset located in: Humble, TX, USA
1655	2026 HQ100 Electric Quantity of 3 Gray Six-Seater Golf Cart (Unused) S/N: SDLC10026151763 C/W: Located in Lane 50 Spot 2, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:15 AM CDT Asset located in: Humble, TX, USA	1661	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260745 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:16 AM CDT Asset located in: Humble, TX, USA
1656	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260756 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:15 AM CDT Asset located in: Humble, TX, USA	1662	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260733 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:17 AM CDT Asset located in: Humble, TX, USA
1657	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S261929 C/W: Located in Lane 50 Spot 1, 6 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available Lot closing time: Thu, Sep 17, 09:15 AM CDT Asset located in: Humble, TX, USA	1663	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S261980 C/W: Located in Lane 50 Spot 1, 6 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available Lot closing time: Thu, Sep 17, 09:17 AM CDT Asset located in: Humble, TX, USA
1658	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260759 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:16 AM CDT Asset located in: Humble, TX, USA	1664	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260755 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:17 AM CDT Asset located in: Humble, TX, USA
1659	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XFYYGEF42S261976 C/W: Located in Lane 47 Spot 0, 6 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available Lot closing time: Thu, Sep 17, 09:16 AM CDT Asset located in: Humble, TX, USA	1665	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260750 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:17 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1666	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260758 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:17 AM CDT Asset located in: Humble, TX, USA	1673	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262213 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
1667	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262114 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:18 AM CDT Asset located in: Lake Worth, TX, USA	1674	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S2607234 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
1668	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262120 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:18 AM CDT Asset located in: Lake Worth, TX, USA	1675	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S2607240 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:20 AM CDT Asset located in: Lake Worth, TX, USA
1669	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262115 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:18 AM CDT Asset located in: Lake Worth, TX, USA	1676	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262274 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:20 AM CDT Asset located in: Oklahoma City, OK, USA
1670	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262176 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:18 AM CDT Asset located in: Lake Worth, TX, USA	1677	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262220 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:20 AM CDT Asset located in: Lake Worth, TX, USA
1671	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262168 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:19 AM CDT Asset located in: Lake Worth, TX, USA	1678	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S2607233 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:20 AM CDT Asset located in: Lake Worth, TX, USA
1672	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262171 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:19 AM CDT Asset located in: Lake Worth, TX, USA	1679	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S2607241 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:21 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1680	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S2607235 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:21 AM CDT Asset located in: Lake Worth, TX, USA	1687	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262373 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:22 AM CDT Asset located in: Oklahoma City, OK, USA
1681	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262212 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:21 AM CDT Asset located in: Lake Worth, TX, USA	1688	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262276 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:23 AM CDT Asset located in: Oklahoma City, OK, USA
1682	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S2607242 C/W: Located in Lane 78 Spot 1, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:21 AM CDT Asset located in: Lake Worth, TX, USA	1689	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262269 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:23 AM CDT Asset located in: Oklahoma City, OK, USA
1683	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262264 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:21 AM CDT Asset located in: Oklahoma City, OK, USA	1690	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262273 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:23 AM CDT Asset located in: Oklahoma City, OK, USA
1684	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262265 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:22 AM CDT Asset located in: Oklahoma City, OK, USA	1691	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S261925 C/W: Located in Lane 50 Spot 1, 6 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available Lot closing time: Thu, Sep 17, 09:23 AM CDT Asset located in: Humble, TX, USA
1685	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262263 C/W: Battery Charger, 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:22 AM CDT Asset located in: Oklahoma City, OK, USA	1692	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S261998 C/W: Located in Lane 47 Spot 0, 6 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available Lot closing time: Thu, Sep 17, 09:24 AM CDT Asset located in: Humble, TX, USA
1686	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF42S262371 C/W: 6 Passenger, Canopy Usage: Not Available Lot closing time: Thu, Sep 17, 09:22 AM CDT Asset located in: Oklahoma City, OK, USA	1693	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260751 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:24 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1694	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260752 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:24 AM CDT Asset located in: Humble, TX, USA	1700	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S2606151 C/W: Located in Lane 48 Spot 1, Battery Charger, 4 Passenger, Canopy, Windshield, 60 Volt, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:25 AM CDT Asset located in: Humble, TX, USA
1695	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260754 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:24 AM CDT Asset located in: Humble, TX, USA	1701	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF22S261021 C/W: Located in Lane 46 Spot 0, 4 Passenger, Canopy, Windshield, Lift Kit, Cargo Box Usage: Not Available Lot closing time: Thu, Sep 17, 09:26 AM CDT Asset located in: Humble, TX, USA
1696	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260753 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:24 AM CDT Asset located in: Humble, TX, USA	1702	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF22S261025 C/W: Located in Lane 46 Spot 0, Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit, Cargo Box Usage: Not Available Lot closing time: Thu, Sep 17, 09:26 AM CDT Asset located in: Humble, TX, USA
1697	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260746 C/W: Located in Lane 50 Spot 1, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:25 AM CDT Asset located in: Humble, TX, USA	1703	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S2606147 C/W: Located in Lane 48 Spot 1, Battery Charger, 4 Passenger, Canopy, Windshield, 60 Volt, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:26 AM CDT Asset located in: Humble, TX, USA
1698	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: XF-YYGEF22S261033 C/W: Located in Lane 46 Spot 0, 4 Passenger, Canopy, Windshield, Lift Kit, Cargo Box Usage: 1 Mi Lot closing time: Thu, Sep 17, 09:25 AM CDT Asset located in: Humble, TX, USA	1704	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S2606131 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:26 AM CDT Asset located in: Lake Worth, TX, USA
1699	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S2606156 C/W: Located in Lane 48 Spot 1, Battery Charger, 4 Passenger, Canopy, Windshield, 60 Volt, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:25 AM CDT Asset located in: Humble, TX, USA	1705	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S2606132 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:27 AM CDT Asset located in: Lake Worth, TX, USA
		1706	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S2606140 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:27 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1707	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S2606133 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:27 AM CDT Asset located in: Lake Worth, TX, USA	1716	2026 HQ100 Electric Black Six-Seater Golf Cart (Unused) S/N: LC10026040642 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
1708	2026 HQ100 Electric Black Six-Seater Golf Cart (Unused) S/N: LC10026040395 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:27 AM CDT Asset located in: Lake Worth, TX, USA	1716A	2022 Yamaha DR2E22 Electric Golf Cart S/N: JOS0100743 C/W: Located in Lane 78, 48 Volt 2 Passenger, Canopy, Windshield Usage: Not Available Lot closing time: Thu, Sep 17, 09:30 AM CDT Asset located in: Lake Worth, TX, USA
1710	2026 HQ100 Electric Red Six-Seater Golf Cart (Unused) S/N: LC10026040225 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:28 AM CDT Asset located in: Lake Worth, TX, USA	1720	Trextron Cushman Shuttle Electric Golf Cart S/N: 3449201 C/W: Located in Lane 78 Spot 1, 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield Usage: Not Available Lot closing time: Thu, Sep 17, 09:30 AM CDT Asset located in: Lake Worth, TX, USA
1711	2026 HQ100 Electric Red Six-Seater Golf Cart (Unused) S/N: LC10026040100 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:28 AM CDT Asset located in: Lake Worth, TX, USA	1722	2019 Club Car Electric Golf Cart S/N: BN1945025179 C/W: Located in Lane 63, 48 Volt 4 Passenger, Canopy, Windshield, Lift Kit, Cargo Box, Utility Body Usage: Not Available Lot closing time: Thu, Sep 17, 09:31 AM CDT Asset located in: Humble, TX, USA
1714	2026 HQ100 Electric Black Six-Seater Golf Cart (Unused) S/N: SDLC10026030177 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:29 AM CDT Asset located in: Lake Worth, TX, USA	1723	United 4x2 Pushback Tractor S/N: Not Available C/W: Located in Lane 63 Spot 00, 4 Cylinder Diesel Engine, Automatic Transmission, 7.50-15 Tires Usage: 8,148 Hr Lot closing time: Thu, Sep 17, 09:31 AM CDT Asset located in: Humble, TX, USA
1715	2026 HQ100 Electric Red Six-Seater Golf Cart (Unused) S/N: LC10026040588 C/W: Located in Lane 78 Spot 1, 72 Volt 6 Passenger, Canopy, Windshield, For internal area use only, not licensed for road use ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:29 AM CDT Asset located in: Lake Worth, TX, USA	1724	24 in x 20 ft Portable Transfer Belt Loader S/N: Not Available C/W: Located in Lane 63 Spot 00, 6 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Thu, Sep 17, 09:31 AM CDT Asset located in: Humble, TX, USA
		1728A	2019 Pioneer 32LX Prowler 36 ft T/A Travel Trailer S/N: 5SFPB3620KE390071 C/W: Sleeps 5 People, 9600 lb GVWR, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225 /75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 09:32 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1729	2018 Pioneer 32LX Prowler 36 ft T/A Travel Trailer S/N: 5SFPB3628JE377518 C/W: Sleeps 5 People, 9600 lb GVWR, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225 /75R15 Tires Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 09:32 AM CDT Asset located in: Lake Worth, TX, USA	1733	2026 SDLOOL SL-EC15 Electric Trike (Unused) S/N: NYSLC260739 Usage: Not Available Lot closing time: Thu, Sep 17, 09:33 AM CDT Asset located in: Lake Worth, TX, USA
1730	2018 Pioneer 32LX Prowler 36 ft T/A Travel Trailer S/N: 5SFPB3628JE378782 C/W: Located in Lane 86, Sleeps 5 People, 9600 lb GVWR, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 09:32 AM CDT Asset located in: Lake Worth, TX, USA	1734	2026 SDLOOL SL-EC15 Electric Trike (Unused) S/N: NYSLC260740 Usage: Not Available Lot closing time: Thu, Sep 17, 09:33 AM CDT Asset located in: Lake Worth, TX, USA
1730A	2019 Forest River WCT282KBD 30 ft T/A Travel Trailer S/N: 5ZT2WCTB4KB400977 C/W: Sleeps 3 People, 9570 lb GVWR, Single Slide Out, Outdoor Kitchen, Power Leveling Jacks, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 09:32 AM CDT Asset located in: Lake Worth, TX, USA	1735	2026 SDLOOL SL-EC15 Electric Trike (Unused) S/N: NYSLC260738 Usage: Not Available Lot closing time: Thu, Sep 17, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
1730B	2018 Pioneer 22LX Prowler 25 ft T/A Travel Trailer S/N: 5SFPB2526JE348935 C/W: Located in Lane 87, Sleeps 4 People, 6900 lb GVWR, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 205/75R14 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	1736	2026 SDLOOL SL-EC15 Electric Trike (Unused) S/N: NYSLC260737 Usage: Not Available Lot closing time: Thu, Sep 17, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
1732	1999 Coachman Leprechaun Motor Home S/N: 1FDXE40S2XHB36288 C/W: Located in Lane 43 Spot 6, Air Conditioner, Automatic Transmission, Ford Triton V10 6.8 L Gasoline Engine, 1999 US EPA Label, Sleeps 4 People, 14050 lb GVWR, Power Awning Usage: 56,936 Mi Lot closing time: Thu, Sep 17, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	1737	2026 Quantity of (4) Electric Trike (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:34 AM CDT Asset located in: Humble, TX, USA
		1741	2026 ET13-BLACK Electric Mini Trike (Unused) S/N: KR2026616AMAM4358 Usage: Not Available Lot closing time: Thu, Sep 17, 09:35 AM CDT Asset located in: Lake Worth, TX, USA
		1742	2026 ET13-BLACK Electric Mini Trike (Unused) S/N: KR2026616AMAM4357 Usage: Not Available Lot closing time: Thu, Sep 17, 09:35 AM CDT Asset located in: Lake Worth, TX, USA
		1743	2026 ET13-BLACK Quantity of (4) Electric Trike (Unused) S/N: K9RZYF1SXTA152927 C/W: Located in Lane 50 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:35 AM CDT Asset located in: Humble, TX, USA
		1748	2026 ET13 Quantity of (4) Electric Mini Trike (Unused) S/N: LQST202600139 C/W: Located in Lane 50 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:37 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1749	Quantity Of (4) 2026 ET13-GREEN Electric Mini Trike (Unused) S/N: LQST202600140 C/W: Located in Lane 50 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:37 AM CDT Asset located in: Humble, TX, USA	1758	2026 ET13-GREEN Electric Mini Trike (Unused) S/N: KR2026616AMAM4340 C/W: Located in Lane 78 Usage: Not Available Lot closing time: Thu, Sep 17, 09:39 AM CDT Asset located in: Lake Worth, TX, USA
1752	2026 Quantity of (4) Electric Trike (Unused) S/N: KR2026524AMAM3663 C/W: Located in Lane 50 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:38 AM CDT Asset located in: Humble, TX, USA	1759	2026 ET13-RED Electric Mini Trike (Unused) S/N: KR2026616AMAM4333 Usage: Not Available Lot closing time: Thu, Sep 17, 09:39 AM CDT Asset located in: Lake Worth, TX, USA
1752A	2026 MGC40 Electric Trike S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:38 AM CDT Asset located in: Humble, TX, USA	1760	2026 ET13-RED Electric Mini Trike (Unused) S/N: KR2026616AMAM4368 Usage: Not Available Lot closing time: Thu, Sep 17, 09:39 AM CDT Asset located in: Lake Worth, TX, USA
1752B	2026 MGC40 Electric Trike S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:38 AM CDT Asset located in: Humble, TX, USA	1765	2022 Kawasaki KLR650 652 cid Dual-Sport Bike S/N: ML5KLEG10NDA04462 C/W: 652 cid Engine, Windscreen Usage: 157 Mi Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Thu, Sep 17, 09:41 AM CDT Asset located in: San Antonio, TX, USA
1752C	2026 MGC40 Electric Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:38 AM CDT Asset located in: Humble, TX, USA	1766	2021 Kawasaki KLX230 233 cc Dual-Sport Bike S/N: MH4LXCB15MJP00092 C/W: 233 cc Engine Usage: Not Available Lot closing time: Thu, Sep 17, 09:41 AM CDT Asset located in: Midland, TX, USA
1752D	2026 MGC40 Electric Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:38 AM CDT Asset located in: Humble, TX, USA	1767	Tao RT100 Motocross Bike (Unused) S/N: L9NLTEZC7N1504952 C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:41 AM CDT Asset located in: Humble, TX, USA
1753	2026 ET13-BLUE Electric Mini Trike (Unused) S/N: KR2026616AMAM4320 Usage: Not Available Lot closing time: Thu, Sep 17, 09:38 AM CDT Asset located in: Lake Worth, TX, USA	1768	2026 IRMOTO-BLACK Electric Moped (Unused) S/N: HY202605050202 Usage: Not Available Lot closing time: Thu, Sep 17, 09:41 AM CDT Asset located in: Lake Worth, TX, USA
1754	2026 ET13-BLUE Electric Mini Trike (Unused) S/N: KR2026616AMAM4317 Usage: Not Available Lot closing time: Thu, Sep 17, 09:38 AM CDT Asset located in: Lake Worth, TX, USA	1769	2026 IRMOTO-BLACK Electric Moped (Unused) S/N: HY202605050243 Usage: Not Available Lot closing time: Thu, Sep 17, 09:42 AM CDT Asset located in: Lake Worth, TX, USA
1757	2026 ET13-GREEN Electric Mini Trike (Unused) S/N: KR2026616AMAM4341 Usage: Not Available Lot closing time: Thu, Sep 17, 09:39 AM CDT Asset located in: Lake Worth, TX, USA	1770	2026 IRMOTO-RED Electric Moped (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:42 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1771	2026 IRMOTO-RED Electric Moped (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:42 AM CDT Asset located in: Humble, TX, USA	1780	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F09595 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:44 AM CDT Asset located in: Humble, TX, USA
1773	2026 IRMOTO-WHITE Electric Moped (Unused) S/N: HY202605050329 Usage: Not Available Lot closing time: Thu, Sep 17, 09:42 AM CDT Asset located in: Lake Worth, TX, USA	1781	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F14991 C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:44 AM CDT Asset located in: Humble, TX, USA
1774	2026 IRMOTO-WHITE Electric Moped (Unused) S/N: HY202605050316 Usage: Not Available Lot closing time: Thu, Sep 17, 09:43 AM CDT Asset located in: Lake Worth, TX, USA	1782	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F14992 C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:45 AM CDT Asset located in: Humble, TX, USA
1775	2026 IRMOTO-WHITE Electric Moped (Unused) S/N: HY202605050291 Usage: Not Available Lot closing time: Thu, Sep 17, 09:43 AM CDT Asset located in: Lake Worth, TX, USA	1783	2026 SKLP SK-E48 E-Bikes Scooter (Unused) S/N: F09557 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
1776	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F09598 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:43 AM CDT Asset located in: Humble, TX, USA	1784	2026 SKLP SK-E48 E-bikes Scooter (Unused) S/N: F01361 Usage: Not Available Lot closing time: Thu, Sep 17, 09:45 AM CDT Asset located in: Oklahoma City, OK, USA
1777	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F09597 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:43 AM CDT Asset located in: Humble, TX, USA	1785	2026 SKLP SK-E48 E-Bikes Scooter (Unused) S/N: F09552 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
1778	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F09596 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:44 AM CDT Asset located in: Humble, TX, USA	1786	2026 SKLP SK-E48 E-Bikes Scooter (Unused) S/N: F09554 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
1779	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F09594 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Thu, Sep 17, 09:44 AM CDT Asset located in: Humble, TX, USA	1787	2026 SKLP SK-E48 E-Bikes Scooter (Unused) S/N: F09555 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:46 AM CDT Asset located in: Lake Worth, TX, USA
		1788	2026 SKLP SK-E48 E-bikes Scooter (Unused) S/N: F01358 Usage: Not Available Lot closing time: Thu, Sep 17, 09:46 AM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
1789	2026 SKLP SK-E48 E-Bikes Scooter (Unused) S/N: F09556 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:46 AM CDT Asset located in: Lake Worth, TX, USA	1799	2026 IRGC40 3 TT Green (Volcanic Gray) E-Trike Mini Scooter (Unused) S/N: H52ZYF7T8TA012999 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:49 AM CDT Asset located in: Lake Worth, TX, USA
1790	2026 SKLP SK-E48 E-bikes Scooter (Unused) S/N: F01359 Usage: Not Available Lot closing time: Thu, Sep 17, 09:46 AM CDT Asset located in: Oklahoma City, OK, USA	1800	2026 IRGC40 3 TT Green (Volcanic Gray) E-Trike Mini Scooter (Unused) S/N: H52ZYF7T7TA012914 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:49 AM CDT Asset located in: Lake Worth, TX, USA
1791	2026 SKLP SK-E48 E-bikes Scooter (Unused) S/N: F01360 Usage: Not Available Lot closing time: Thu, Sep 17, 09:47 AM CDT Asset located in: Oklahoma City, OK, USA	1802	2026 IRGC40 3 TT Khaki E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM483 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:49 AM CDT Asset located in: Lake Worth, TX, USA
1792	2026 SKLP SK-E48 E-Bikes Scooter (Unused) S/N: F09553 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	1803	2026 IRGC40 3 TT Khaki E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM493 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:49 AM CDT Asset located in: Lake Worth, TX, USA
1793	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: F01667 C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:47 AM CDT Asset located in: Humble, TX, USA	1804	2026 IRGC40 3 TT Khaki E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM482 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:50 AM CDT Asset located in: Lake Worth, TX, USA
1794	2026 MGC40-BLACK 3 TT E-Trike Mini Scooter (Unused) S/N: LQXHJS26060176 Usage: Not Available Lot closing time: Thu, Sep 17, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	1805	2026 IRGC40 3 TT Khaki E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM494 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:50 AM CDT Asset located in: Lake Worth, TX, USA
1795	2026 IRGC40 3 TT Blue E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM518 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:48 AM CDT Asset located in: Lake Worth, TX, USA	1806	2026 IRGC40 3 TT Khaki E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM486 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:50 AM CDT Asset located in: Lake Worth, TX, USA
1796	2026 IRGC40 3 TT Blue E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM512 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:48 AM CDT Asset located in: Lake Worth, TX, USA	1808	2026 IRGC40 3 TT Purple E-Trike Mini Scooter (Unused) S/N: H52ZYF7T0TA015217 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:51 AM CDT Asset located in: Lake Worth, TX, USA
1797	2026 IRGC40 3 TT Blue E-Trike Mini Scooter (Unused) S/N: KR20260201AMAM515 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:48 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
1809	2026 IRGC40 3 TT Purple E-Trike Mini Scooter (Unused) S/N: H52ZYF7T3TA015258 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:51 AM CDT Asset located in: Lake Worth, TX, USA	1819	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:53 AM CDT Asset located in: Humble, TX, USA
1810	2026 IRGC40 3 TT Red E-Trike Mini Scooter (Unused) S/N: H52ZYF7T3TA012988 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:51 AM CDT Asset located in: Lake Worth, TX, USA	1820	2026 MGC40-GREEN 3 TT E-Trike Mini Scooter (Unused) S/N: LQH202605JS01580 Usage: Not Available Lot closing time: Thu, Sep 17, 09:53 AM CDT Asset located in: Lake Worth, TX, USA
1811	2026 IRGC40 3 TT Red E-Trike Mini Scooter (Unused) S/N: H52ZYF7T8TA012923 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:51 AM CDT Asset located in: Lake Worth, TX, USA	1821	2026 MGC40-GREEN 3 TT E-Trike Mini Scooter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Sep 17, 09:54 AM CDT Asset located in: Lake Worth, TX, USA
1813	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:52 AM CDT Asset located in: Humble, TX, USA	1822	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:54 AM CDT Asset located in: Humble, TX, USA
1814	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:52 AM CDT Asset located in: Humble, TX, USA	1823	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:54 AM CDT Asset located in: Humble, TX, USA
1815	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:52 AM CDT Asset located in: Humble, TX, USA	1824	2026 MGC40-PINK 3 TT E-Trike Mini Scooter (Unused) S/N: LQHJS26060133 Usage: Not Available Lot closing time: Thu, Sep 17, 09:54 AM CDT Asset located in: Lake Worth, TX, USA
1816	2026 MGC40-BLUE 3 TT E-Trike Mini Scooter (Unused) S/N: LQXH2026JS01517 Usage: Not Available Lot closing time: Thu, Sep 17, 09:52 AM CDT Asset located in: Lake Worth, TX, USA	1825	2026 MGC40-RED 3 TT E-Trike Mini Scooter (Unused) S/N: LQH2026JS02066 Usage: Not Available Lot closing time: Thu, Sep 17, 09:55 AM CDT Asset located in: Lake Worth, TX, USA
1817	2026 MGC40-BLUE 3 TT E-Trike Mini Scooter (Unused) S/N: LQXH2026JS01928 Usage: Not Available Lot closing time: Thu, Sep 17, 09:53 AM CDT Asset located in: Lake Worth, TX, USA	1826	2026 MGC40-RED 3 TT E-Trike Mini Scooter (Unused) S/N: LQXHJS26060224 Usage: Not Available Lot closing time: Thu, Sep 17, 09:55 AM CDT Asset located in: Lake Worth, TX, USA
1818	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:53 AM CDT Asset located in: Humble, TX, USA	1827	2026 MGC40-RED 3 TT E-Trike Mini Scooter (Unused) S/N: LQXH2026JS01860 Usage: Not Available Lot closing time: Thu, Sep 17, 09:55 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1828	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:55 AM CDT Asset located in: Humble, TX, USA	1837	2026 ET13-GREEN Electric Mini Trike (Unused) S/N: KR2026423AMAM2614 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:57 AM CDT Asset located in: Lake Worth, TX, USA
1829	2026 MGC40 Electric Mini Trike (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:56 AM CDT Asset located in: Humble, TX, USA	1838	2026 ET13-GREEN Electric Mini Trike (Unused) S/N: H9RZYF1SXTA153599 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
1830	2026 ET13-BLACK Electric Mini Trike (Unused) S/N: H9RZUF1SXTA153607 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:56 AM CDT Asset located in: Lake Worth, TX, USA	1839	2026 ET13-RED Electric Mini Trike (Unused) S/N: KR2026242AMAM2677 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
1831	2026 ET13-BLACK Electric Mini Trike (Unused) S/N: KR2026424AMAM2651 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:56 AM CDT Asset located in: Lake Worth, TX, USA	1840	2026 ET13-RED Electric Mini Trike (Unused) S/N: H9RZYF1SXTA153627 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
1832	2026 ET13-BLACK Electric Mini Trike (Unused) S/N: KR2026423AMAM2631 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:56 AM CDT Asset located in: Lake Worth, TX, USA	1841	2026 ET13-RED Electric Mini Trike (Unused) S/N: KR2026423AMAM2615 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
1833	2026 ET13-BLUE Electric Mini Trike (Unused) S/N: H9RZYF1SXTA153590 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:56 AM CDT Asset located in: Lake Worth, TX, USA	1842	2026 EV-BLACK Electric Scooter (Unused) S/N: HY202605050361 Usage: Not Available Lot closing time: Thu, Sep 17, 09:59 AM CDT Asset located in: Lake Worth, TX, USA
1834	2026 ET13-BLUE Electric Mini Trike (Unused) S/N: KR2026423AMAM2590 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	1843	2026 EV-BLACK Electric Scooter (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:59 AM CDT Asset located in: Humble, TX, USA
1835	2026 ET13-BLUE Electric Mini Trike (Unused) S/N: KR2026424AMAM2640 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	1844	2026 EV-BLACK Electric Scooter (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:59 AM CDT Asset located in: Humble, TX, USA
1836	2026 ET13-GREEN Electric Mini Trike (Unused) S/N: KR2026424AMAM2663 C/W: Located in Lane 78 Spot 1 Usage: Not Available Lot closing time: Thu, Sep 17, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	1845	2026 Electric Moped (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Thu, Sep 17, 09:59 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1846	2026 EV-BLACK Electric Scooter (Unused) S/N: HY202604050670 Usage: Not Available Lot closing time: Thu, Sep 17, 09:59 AM CDT Asset located in: Lake Worth, TX, USA	1855	2017 Chrysler 300 AWD Automobile S/N: 2C3CCARG0HH512640 C/W: Located in Lane 19 Spot 50, V6 3.6 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 126,484 Mi Notes: Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:02 AM CDT Asset located in: Humble, TX, USA
1847	2026 EV-BLACK Electric Scooter (Unused) S/N: HY202505050677 Usage: Not Available Lot closing time: Thu, Sep 17, 10:00 AM CDT Asset located in: Lake Worth, TX, USA	1856	2017 Kia Forte Automobile S/N: 3KPFK4A76HE050329 C/W: Located in Lane 20 Spot 37, 4 cyl 2.0 L Gasoline Engine, 2017 US EPA Label, CARB Compliant, 6 Speed Manual Transmission, Air Conditioner, Power Windows, Power Locks Usage: 93,059 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:02 AM CDT Asset located in: Humble, TX, USA
1852	2025 Hyundai Elantra SEL Sport Automobile S/N: KMHLM4DG8SU965180 C/W: Located in Lane 21 Spot 29, 4 cyl 2.0 L Gasoline Engine, 2025 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 23,777 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:00 AM CDT Asset located in: Humble, TX, USA	1857	2017 Kia Rio Automobile S/N: KNADM4A36H6024928 C/W: Located in Lane 19 Spot 40, 4 cyl 1.6 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 136,324 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:02 AM CDT Asset located in: Humble, TX, USA
1853	2019 Nissan Versa SV Automobile S/N: 3N1CN7AP9KL841424 C/W: Located in Lane 18 Spot 39, 4 cyl 1.6 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 106,273 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:01 AM CDT Asset located in: Humble, TX, USA	1859	2016 BMW 528i xDrive Automobile S/N: WBA5A7C57GG149006 C/W: Located in Lane 20 Spot 16, 4 cyl 2 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 157,481 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:03 AM CDT Asset located in: Humble, TX, USA
1854	2018 Hyundai Sonata Sport Automobile S/N: 5NPE34AF7JH696982 C/W: Located in Lane 20 Spot 34, 4 cyl 2.4 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 117,451 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. This unit is being sold with a rebuilt salvage title. Lot closing time: Thu, Sep 17, 10:01 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
1860	2016 Buick Verano Automobile S/N: 1G4PR5SK0G4101053 C/W: Located in Lane 19 Spot 3, 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 89,834 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:03 AM CDT Asset located in: Humble, TX, USA	1864	2016 Scion iA Automobile S/N: 3MYDLBZVXGY118576 C/W: Located in Lane 19 Spot 16, 4 cyl 1.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 174,369 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:04 AM CDT Asset located in: Humble, TX, USA
1861	2016 Honda Civic Automobile S/N: 19XFC2F71GE049694 C/W: Located in Lane 20 Spot 19, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 102,674 Mi Notes: This unit is being sold with a rebuilt salvage title. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:03 AM CDT Asset located in: Humble, TX, USA	1865	2016 Cadillac XTS Automobile S/N: 2G61M5S35G9159984 C/W: Located in Lane 18 Spot 8, V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 100,857 Mi Notes: This unit is being sold with a rebuilt salvage title; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section ;Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:04 AM CDT Asset located in: Lake Worth, TX, USA
1862	2016 Hyundai Sonata Automobile S/N: 5NPE24AF6GH265478 C/W: Located in Lane 20 Spot 35, 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 138,730 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:03 AM CDT Asset located in: Humble, TX, USA	1866	2016 Subaru Legacy Automobile S/N: 4S3BNBL6XG3007200 C/W: Located in Lane 20 Spot 22, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 158,207 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:04 AM CDT Asset located in: Humble, TX, USA
1863	2016 Toyota Camry Automobile S/N: 4T1BF1FK9GU999576 C/W: Located in Lane 19 Spot 34, 4 cyl 2.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 282,669 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:03 AM CDT Asset located in: Humble, TX, USA	1867	2015 Kia K900 Automobile S/N: KNALW4D40F6022776 C/W: Located in Lane 20 Spot 41, V8 5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 115,894 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:04 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1868	2015 Cadillac ATS Automobile S/N: 1G6AB5RX9F0142628 C/W: Located in Lane 19 Spot 28, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 106,525 Mi Notes: Title not branded but has salvage history. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:05 AM CDT Asset located in: Humble, TX, USA	1872	2014 Chevrolet Cruze LT Automobile S/N: 1G1PC5SB5E7354606 C/W: Located in Lane 20 Spot 23, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 110,991 Mi Notes: This unit is being sold with a rebuilt salvage title. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. The vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:06 AM CDT Asset located in: Humble, TX, USA
1869	2015 Nissan Versa SV Automobile S/N: 3N1CE2CP7FL407217 C/W: Located in Lane 19 Spot 37, 4 cyl 1.6 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 141,825 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:05 AM CDT Asset located in: Humble, TX, USA	1873	2014 Toyota Corolla Automobile S/N: 5YFBURHE5EP088722 C/W: Located in Lane 19 Spot 46, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 102,350 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:06 AM CDT Asset located in: Humble, TX, USA
1870	2015 Dodge Charger Automobile S/N: 2C3CDXHG4FH901795 C/W: Located in Lane 20 Spot 15, 6 cyl 3.6 cc Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 99,599 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:05 AM CDT Asset located in: Humble, TX, USA	1874	2014 Subaru Impreza AWD Automobile S/N: JF1GPAC64E8244975 C/W: Located in Lane 19 Spot 47, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 164,295 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:06 AM CDT Asset located in: Humble, TX, USA
1871	2014 Audi A4 Automobile S/N: WAUFFAFL1EN037453 C/W: Located in Lane 18 Spot 9, 4 cyl 2.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: 89,975 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section ;Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:05 AM CDT Asset located in: Lake Worth, TX, USA	1875	2014 Chevrolet Spark Automobile S/N: KL8CD6S90EC572992 C/W: Located in Lane 20 Spot 20, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 87,948 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:06 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1876	2014 Ford Fiesta Automobile S/N: 3FADP4BJ3EM111002 C/W: Located in Lane 19 Spot 15, 4 cyl 1.6 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 127,424 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:06 AM CDT Asset located in: Humble, TX, USA	1880	2013 Hyundai Veloster Automobile S/N: KMHTC6AEXDU162259 C/W: Located in Lane 19 Spot 44, 4 cyl 1.6 L Gasoline Engine, 2013 US EPA Label, 6 Speed Manual Transmission, Air Conditioner, Power Windows, Power Locks Usage: 92,274 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:07 AM CDT Asset located in: Humble, TX, USA
1877	2013 Mercedes-Benz C250 Automobile S/N: WDDGJ4HB4DF962951 C/W: Located in Lane 21 Spot 44, 4 cyl 1.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 139,930 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:07 AM CDT Asset located in: Humble, TX, USA	1881	2013 Chevrolet Camaro Automobile S/N: 2G1FF1E33D9183657 C/W: Located in Lane 19 Spot 30, V6 3.6 L Gasoline Engine, 2013 US EPA Label, 6 Speed Manual Transmission, Air Conditioner, Power Windows, Power Locks Usage: 83,900 Mi Lot closing time: Thu, Sep 17, 10:08 AM CDT Asset located in: Humble, TX, USA
1878	2013 Cadillac XTS Platinum Automobile S/N: 2G61U5S33D9200513 C/W: Located in Lane 18 Spot 7, V6 3.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 164,778 Mi Notes: This unit is being sold with a rebuilt, loss unknown, flood damage, not actual mileage, salvage title; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section; Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:07 AM CDT Asset located in: Lake Worth, TX, USA	1882	2012 Chrysler 300 Automobile S/N: 2C3CCACG9CH306797 C/W: Located in Lane 18 Spot 7, 3.6 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 191,590 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the document section ; Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:08 AM CDT Asset located in: Lake Worth, TX, USA
1879	2013 Ford Fusion SE Automobile S/N: 3FA6P0HR5DR134958 C/W: Located in Lane 20 Spot 29, 4 cyl 1.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 155,142 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:07 AM CDT Asset located in: Humble, TX, USA	1883	2012 Chevrolet Cruze Automobile S/N: 1G1PC5SH0C7348116 C/W: Located in Lane 19 Spot 32, 4 cyl 1.8 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 120,738 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:08 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1884	2012 Ford Focus SE Automobile S/N: 1FAHP3F28CL428979 C/W: Located in Lane 19 Spot 8, 4 cyl 2.0 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 275,288 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:08 AM CDT Asset located in: Humble, TX, USA	1888	2009 Ford Mustang Automobile S/N: 1ZVHT80N895143649 C/W: Located in Lane 19 Spot 13, V6 4.0 L Gasoline Engine, 2009 US EPA Label, 5 Speed Manual Transmission, Air Conditioner, Power Windows, Power Locks Usage: 192,072 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:09 AM CDT Asset located in: Humble, TX, USA
1884A	2012 BMW 650i Automobile S/N: WBALZ3C53CC397439 C/W: Located in Lane 19 Spot 5, V8 4.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 120,367 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:08 AM CDT Asset located in: Humble, TX, USA	1889	2009 Cadillac CTS Automobile S/N: 1G6DF577590151562 C/W: Located in Lane 20 Spot 36, V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 170,007 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:10 AM CDT Asset located in: Humble, TX, USA
1886	2011 Honda Accord Crosstour Automobile S/N: 5J6TF1H35BL003620 C/W: Located in Lane 19 Spot 25, V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 169,176 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:09 AM CDT Asset located in: Humble, TX, USA	1890	2007 Ford Mustang Automobile S/N: 1ZVFT80N575323479 C/W: Located in Lane 21 Spot 34, 6 cyl 4.0 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 169,776 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:10 AM CDT Asset located in: Humble, TX, USA
1887	2010 Honda Accord Automobile S/N: 1HGCP2F8XAA074587 C/W: Located in Lane 19 Spot 41, 4 cyl 2.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 189,462 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:09 AM CDT Asset located in: Humble, TX, USA	1891	2006 Volkswagen Beetle Automobile S/N: 3VWRF31Y46M308478 C/W: Located in Lane 19 Spot 36, 5 cyl 2.5 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 98,157 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:10 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1892	2024 Toyota Sienna Hybrid Minivan S/N: 5TDKRKEC2RS196031 C/W: 4 cyl Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Wheelchair Accessible Usage: 135,149 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:10 AM CDT Asset located in: Livingston, LA, USA	1896	2015 Airstream Interstate 24 GL 9 Passenger Van S/N: WD3PF4CD4F5978946 C/W: Located in Lane 14 Spot 17, V6 3.0 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear View Camera, Navigation Usage: Not Available Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:11 AM CDT Asset located in: Lake Worth, TX, USA
1893	2016 Dodge Grand Caravan R/T Minivan S/N: 2C4RDGEG7GR361882 C/W: Located in Lane 20 Spot 30, V6 3.6 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 143,651 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:10 AM CDT Asset located in: Humble, TX, USA	1897	2008 Chevrolet Express 3500 Passenger Van S/N: 1GAHG39K181197635 C/W: Located in Lane 20 Spot 21, V8 6 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 75,455 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:11 AM CDT Asset located in: Humble, TX, USA
1894	2009 Toyota Sienna Minivan S/N: 5TDZK22C29S233831 C/W: Located in Lane 20 Spot 32, V6 3.5 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 215,043 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:11 AM CDT Asset located in: Humble, TX, USA	1898	2006 Ford E-350 XLT 14 Passenger Van S/N: 1FBSS31L16DA31552 C/W: Located in Lane 14 Spot 14, V8 5.4 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner Usage: 172,896 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:12 AM CDT Asset located in: Lake Worth, TX, USA
1895	1994 Toyota TownAce Minivan S/N: CR225016852 C/W: Located in Lane 18 Spot 8, 4 cyl Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 97,726 Km Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Lot closing time: Thu, Sep 17, 10:11 AM CDT Asset located in: Humble, TX, USA	1900	2021 GMC Yukon Denali 4WD SUV S/N: 1GKS2DKL0MR258834 C/W: Located in Lane 19 Spot 20, V8 6.2 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 108,872 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:12 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1901	2020 Land Rover Range Rover S AWD SUV S/N: SALYB2EX4LA265316 C/W: Located in Lane 19 Spot 11, 4 cyl 2.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 67,644 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:12 AM CDT Asset located in: Humble, TX, USA	1905	2015 Jeep Grand Cherokee Overland 4WD SUV S/N: 1C4RJFCG8FC652646 C/W: Located in Lane 19 Spot 4, V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 164,852 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:13 AM CDT Asset located in: Humble, TX, USA
1902	2018 Mitsubishi Outlander 4WD SUV S/N: JA4AZ3A33JZ053190 C/W: Located in Lane 19 Spot 51, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 140,277 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:13 AM CDT Asset located in: Humble, TX, USA	1906	2015 Subaru Forrester AWD SUV S/N: JF2SJAHC7FH548504 C/W: Located in Lane 20 Spot 25, 4 cyl 2.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 160,812 Mi Notes: This unit is being sold with a rebuilt salvage title. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:13 AM CDT Asset located in: Humble, TX, USA
1903	2017 Land Rover Discovery 4WD SUV S/N: SALCP2BG7HH661562 C/W: Located in Lane 19 Spot 9, 4 cyl 2.0 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 125,390 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:13 AM CDT Asset located in: Humble, TX, USA	1907	2015 Nissan Rogue SV AWD SUV S/N: 5N1AT2MV1FC787685 C/W: Located in Lane 19 Spot 29, 4 cyl 2.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 141,604 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:14 AM CDT Asset located in: Humble, TX, USA
1904	2015 Land Rover Range Rover Evoque AWD SUV S/N: SALVP2BG3FH013142 C/W: Located in Lane 20 Spot 24, 4 cyl 2.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 110,415 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:13 AM CDT Asset located in: Humble, TX, USA	1908	2013 Land Rover Range Rover Evoque 4WD SUV S/N: SALVP2BG3DH747700 C/W: Located in Lane 19 Spot 6, 4 cyl 2.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 146,637 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:14 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1909	2013 Land Rover Range Rover 4WD SUV S/N: SALSF2D47DA806457 C/W: Located in Lane 20 Spot 18, V8 5.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 162,838 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:14 AM CDT Asset located in: Humble, TX, USA	1914	2009 Ford Explorer Limited 4WD SUV S/N: 1FMEU75829UA26747 C/W: Located in Lane 19 Spot 52, V8 4.6 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row, Towing Hitch Usage: 177,512 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:15 AM CDT Asset located in: Humble, TX, USA
1910	2012 Land Rover LR4 AWD SUV S/N: SALAG2D43CA614718 C/W: Located in Lane 19 Spot 7, V8 5.0 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 103,195 Mi Notes: This unit is being sold with a rebuilt salvage and flood damage title. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:14 AM CDT Asset located in: Humble, TX, USA	1915	2007 Jeep Wrangler 4WD SUV S/N: 1J4FA24197L122879 C/W: Located in Lane 19 Spot 2, V6 3.8 L Gasoline Engine, 2007 US EPA Label, 6 Speed Manual Transmission, Air Conditioner Usage: 143,388 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:16 AM CDT Asset located in: Humble, TX, USA
1911	2011 Infiniti FX35 AWD SUV S/N: JN8AS1MW8BM734114 C/W: Located in Lane 20 Spot 14, V6 3.5 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 225,099 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:15 AM CDT Asset located in: Humble, TX, USA	1915A	2006 BMW X3 AWD SUV S/N: WBXPA93406WD27069 C/W: Located in Lane 21 Spot 42, 6 cyl 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 165,750 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:16 AM CDT Asset located in: Humble, TX, USA
1912	2010 Cadillac Escalade 4x4 Hybrid SUV S/N: 1GYUKFEJ2AR208761 C/W: Located in Lane 19 Spot 31, V8 6 L Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 163,245 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:15 AM CDT Asset located in: Humble, TX, USA	1916	2005 Chevrolet Tahoe Z71 4WD SUV S/N: 1GNEK13T35R261029 C/W: V8 5.3 L Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 164,895 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 10:16 AM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
1920	2021 Volkswagen Atlas 2WD SUV S/N: 1V2WR2CA2MC539562 C/W: Located in Lane 21 Spot 28, V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 120,431 Mi Lot closing time: Thu, Sep 17, 10:17 AM CDT Asset located in: Humble, TX, USA	1926	2019 Chevrolet Trax Lt 2WD SUV S/N: KL7CJLSBKB773508 C/W: Located in Lane 19 Spot 42, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 112,308 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:18 AM CDT Asset located in: Humble, TX, USA
1922	2019 Infiniti QX60 2WD SUV S/N: 5N1DL0MN8KC503366 C/W: Located in Lane 19 Spot 24, V6 3.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 154,666 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:17 AM CDT Asset located in: Humble, TX, USA	1927	2018 Dodge Journey 2WD SUV S/N: 3C4PDCAB3JT445499 C/W: Located in Lane 20 Spot 38, 4 cyl 2.4 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 177,722 Mi Notes: Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:18 AM CDT Asset located in: Humble, TX, USA
1924	2019 Dodge Journey 2WD SUV S/N: 3C4PDCBB3KT867031 C/W: Located in Lane 20 Spot 39, 4 cyl 2.4 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 111,274 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:18 AM CDT Asset located in: Humble, TX, USA	1928	2018 Ford Escape SE 2WD SUV S/N: 1FMCU0GD2JUA96861 C/W: Located in Lane 19 Spot 22, 4 cyl 1.5 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 119,564 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:19 AM CDT Asset located in: Humble, TX, USA
1925	2019 Nissan Pathfinder SUV S/N: 5N1DR2MN4KC601398 C/W: Located in Lane 19 Spot 43, V6 3.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 161,291 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:18 AM CDT Asset located in: Humble, TX, USA	1930	2017 Hyundai Tucson 2WD SUV S/N: KM8J23A4XHU291818 C/W: Located in Lane 19 Spot 25, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 99,165 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:19 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1932	2017 Nissan Rogue SV 2WD SUV S/N: 5N1AT2MT7HC752134 C/W: Located in Lane 20 Spot 40, 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 146,150 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:20 AM CDT Asset located in: Humble, TX, USA	1942	2018 Ram 3500 4x4 Crew Cab 4x4 Crew Cab Pickup S/N: 3C63RRGL8JG339178 C/W: Located in Lane 20 Spot 1, 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Dual Rear Wheel, Spray-On Bed Liner, 14000 lb GVWR, 35x12.50R17 Tires, 8 ft Bed Usage: 284,270 Mi Notes: Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:22 AM CDT Asset located in: Humble, TX, USA
1935	2014 Jeep Cherokee Latitude 2WD SUV S/N: 1C4PJLCB1EW186808 C/W: Located in Lane 20 Spot 26, 4 cyl 2.4 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 151,627 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:20 AM CDT Asset located in: Humble, TX, USA	1943	2019 Chevrolet 3500HD 4x4 Crew Cab Pickup S/N: 1GC4KVCG2KF107973 C/W: 6 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Dual Rear Wheel, Weather Guard Tool Box, Drop-In Bed Liner, 13825 lb GVWR, 235/80-R17 Tires, 8 ft 1 in Bed Usage: 189,856 Mi Lot closing time: Thu, Sep 17, 10:22 AM CDT Asset located in: Midland, TX, USA
1936	2014 Ford Escape 2WD SUV S/N: 1FMCU0F7XEUC75571 C/W: Located in Lane 20 Spot 31, 4 cyl 2.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 98,453 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding Lot closing time: Thu, Sep 17, 10:20 AM CDT Asset located in: Humble, TX, USA	1945	2022 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT7NEC94386 C/W: 6.7 L V8 Diesel Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 11500 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed Usage: 242,305 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:23 AM CDT Asset located in: Oklahoma City, OK, USA
1938	2011 Chevrolet HRR 2WD SUV S/N: 3GCAAFFW8BS549248 C/W: Located in Lane 18 Spot 2, 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 170,423 Mi Notes: This unit is being sold with a rebuilt, salvage, bonded, loss unknown title; Odometer discrepancy-unit shows 170,423, title shows 175,415 Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section. Lot closing time: Thu, Sep 17, 10:21 AM CDT Asset located in: Lake Worth, TX, USA	1946	2023 Chevrolet Silverado 3500HD 4x4 Crew Cab Pickup S/N: 2GC4YSEY7P1701086 C/W: 6.6 L V8 Diesel Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, Spray-On Bed Liner, 12100 lb GVWR, 275/70R18 Tires, 7 ft Bed Usage: 124,231 Mi Lot closing time: Thu, Sep 17, 10:23 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
1949	2017 Ford F-350 4x4 Crew Cab Pickup S/N: 1FT8W3BT8HEF34081 C/W: Located in Lane 18 Spot 27, 6.7 L V8 Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11500 lb GVWR, 265/60R18 Tires, 8 ft 2 in Bed Usage: 290,143 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section ;Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:24 AM CDT Asset located in: Lake Worth, TX, USA	1954	2012 Dodge Ram 3500 4x4 Crew Cab Pickup S/N: 3C63D3GL5CG255804 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10100 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 621,261 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 10:25 AM CDT Asset located in: San Antonio, TX, USA
1950	2015 Ford F-350 4x4 Crew Cab Pickup S/N: 1FT8W3BT9FED14929 C/W: Located in Lane 18 Spot 28, 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, 11500 lb GVWR, 275/65R20 Tires, 8 ft 3 in Bed Usage: 204,363 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:24 AM CDT Asset located in: Lake Worth, TX, USA	1955	2012 Dodge Ram 3500 4x4 Crew Cab Pickup S/N: 3C63D3GL7CG238051 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10100 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 35,726 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 10:25 AM CDT Asset located in: San Antonio, TX, USA
1952	2012 Ram 3500 4x4 Crew Cab Pickup S/N: 3C63D3GL9CG238052 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10100 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed Usage: 509,806 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 10:24 AM CDT Asset located in: San Antonio, TX, USA	1956	2012 Dodge Ram 3500 4x4 Crew Cab Pickup S/N: 3C63D3GL7CG238048 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10100 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 384,717 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 10:25 AM CDT Asset located in: San Antonio, TX, USA
1953	2012 Dodge Ram 3500 4x4 Crew Cab Pickup S/N: 3C63D3GL5CG238050 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10100 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed Usage: 568,792 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 10:24 AM CDT Asset located in: San Antonio, TX, USA	1956A	2012 Ford F-350 XL 4x4 Extended Cab Pickup S/N: 1FT7X3B62CEC67774 C/W: 6.2 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 10000 lb GVWR, 285/70R17 Tires, 6 ft 5 in Bed Usage: 219,590 Mi Lot closing time: Thu, Sep 17, 10:25 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
1960	2022 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B61NEC94383 C/W: 7.2 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 305/70R17 Tires, 6 ft 8 in Bed Usage: 214,654 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:26 AM CDT Asset located in: Oklahoma City, OK, USA	1970	2015 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B6XFEC40839 C/W: Located in Lane 22 Spot 4, 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 178,752 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 10:28 AM CDT Asset located in: Humble, TX, USA
1963	2019 Ford F-250 Platinum 4x4 Crew Cab Pickup S/N: 1FT7W2B62KED91135 C/W: Located in Lane 20 Spot 2, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Spray-On Bed Liner, 10000 lb GVWR, 37x12.50R20 Tires, 7 ft Bed Usage: 70,859 Mi Notes: Additional Components Available In Office - Key; This unit is being sold with a rebuilt salvage-flood damage title. Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	1971	2014 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2BT9EEB36007 C/W: 6.7 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 355,004 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:29 AM CDT Asset located in: Midland, TX, USA
1964A	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63KEC45018 C/W: Located in Lane 19 Spot 18, 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, 10000 lb GVWR, 285/70R17 Tires, 7 ft 4 in Bed Usage: 318,053 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	1972	2013 Ford F-250 Platinum 4x4 Crew Cab Pickup S/N: 1FT7W2BT5DEA07986 C/W: 6.7 L V8 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, 275/65R20 Tires, 8 ft Bed Usage: 325,096 Hr Lot closing time: Thu, Sep 17, 10:29 AM CDT Asset located in: Midland, TX, USA
1968	2017 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2BT6HEE13541 C/W: Located in Lane 19 Spot 25, 6.7 L V8 Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 189,052 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ;Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:28 AM CDT Asset located in: Lake Worth, TX, USA	1973A	2012 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B62CEA50805 C/W: Located in Lane 20 Spot 7, 6.2 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 10900 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 354,600 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:29 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1974	2010 Ford F-250 Lariat 4x4 Crew Cab Pickup S/N: 1FTSW2BR0AEA39965 C/W: Located in Lane 22 Spot 5, 6.4 L V8 Diesel Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 35X12.50R20 Tires, 6 ft 4 in Bed Usage: 105,030 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:29 AM CDT Asset located in: Humble, TX, USA	1983	2014 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HL6EG323059 C/W: Located in Lane 21 Spot 15, 6.7 L 6 Cylinder Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 275/70R18 Tires, 8 ft Bed Usage: 261,471 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:31 AM CDT Asset located in: Humble, TX, USA
1977	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ1MG631270 C/W: Located in Lane 20 Spot 17, 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 10000 lb GVWR, 275/70R16 Tires, 8 ft 1 in Bed, Equipment-from-a-Primoris-Services-Corp-company Usage: 184,544 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:30 AM CDT Asset located in: Lake Worth, TX, USA	1984	2014 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL3EG291565 C/W: 6.7 L 6 Cylinder Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 358,100 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 10:32 AM CDT Asset located in: San Antonio, TX, USA
1981	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HL8JG147416 C/W: Located in Lane 20 Spot 3, 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Drop-In Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft 1 in Bed Usage: 287,392 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control systems or devices as originally equipped. Buyer of this unit must sign acknowledgement form of this notice prior to removal of unit from yard; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:31 AM CDT Asset located in: Lake Worth, TX, USA	1985	2013 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HL6DG563842 C/W: Located in Lane 21 Spot 4, 6.7 L 6 Cylinder Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 285/70R17 Tires, 8 ft Bed Usage: 269,657 Mi Notes: This title is branded as not actual mileage. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control systems or devices as originally equipped. Buyer of this unit must sign acknowledgement form of this notice prior to removal of unit from the yard. Lot closing time: Thu, Sep 17, 10:32 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
1986	2023 Chevrolet Silverado 2500 Custom 4x4 Crew Cab Pickup S/N: 1GC4YME73PF120101 C/W: 6.6 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 10650 lb GVWR, 275/65R20 Tires, 6 ft 8 in Bed Usage: 151,382 Mi Lot closing time: Thu, Sep 17, 10:32 AM CDT Asset located in: Midland, TX, USA	1991	2021 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1YNE76MF227311 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 6 ft 8 in Bed Usage: 138,805 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:33 AM CDT Asset located in: Oklahoma City, OK, USA
1987	2023 Chevrolet Silverado 2500 Custom 4x4 Crew Cab Pickup S/N: 1GC4YME77PF120103 C/W: 6.6 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Decked Tool Box, Spray-On Bed Liner, 10650 lb GVWR, 275/65R20 Tires, 6 ft 8 in Bed Usage: 171,867 Mi Lot closing time: Thu, Sep 17, 10:32 AM CDT Asset located in: Midland, TX, USA	1992	2019 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KREG4KF110977 C/W: Located in Lane 19 Spot 21, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 9500 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 237,594 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
1988	2023 Chevrolet Silverado 2500 4x4 Crew Cab Pickup S/N: 1GC4YME7XPF120094 C/W: 6.6 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, N/A Tool Box, Spray-On Bed Liner, 10650 lb GVWR, 275/65R20 Tires, 6 ft 8 in Bed Usage: 118,302 Mi Lot closing time: Thu, Sep 17, 10:33 AM CDT Asset located in: Midland, TX, USA	1993	2019 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KREG9KF172648 C/W: Located in Lane 19 Spot 16, 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 265/70R17 Tires, 8 ft Bed Usage: 282,115 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
1989	2022 Chevrolet 2500HD Z71 4x4 Crew Cab Pickup S/N: 1GC1YNE76NF198815 C/W: 6.6 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 275/70R18 Tires, 8 ft Bed Usage: 106,392 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:33 AM CDT Asset located in: Oklahoma City, OK, USA		
1990	2022 Chevrolet Silverado 2500HD LT Z71 4x4 Crew Cab Pickup S/N: 1GC4YNEY1NF138222 C/W: Located in Lane 22 Spot 7, 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Spray-On Bed Liner, 11350 lb GVWR, 275/70R18 Tires, 6 ft 9 in Bed Usage: 203,502 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding ; From the Well Maintained Fleet of R Construction Lot closing time: Thu, Sep 17, 10:33 AM CDT Asset located in: Humble, TX, USA	1993A	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12REG2JF267938 C/W: Located in Lane 19 Spot 14, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9900 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 221,496 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:34 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
1994	2022 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B62NEC94390 C/W: 6.2 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed Usage: 161,757 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:34 AM CDT Asset located in: Oklahoma City, OK, USA	1997C	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B63LEC52193 C/W: Located in Lane 19 Spot 30, 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft 6 in Bed Usage: 188,583 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ;Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Lake Worth, TX, USA
1997	2021 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B63MEE06340 C/W: 6.2 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 187,210 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Oklahoma City, OK, USA	1997D	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B62LEC74606 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 192,206 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided.; Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Lake Worth, TX, USA
1997A	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B65LEC90346 C/W: Located in Lane 19 Spot 24, 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft 6 in Bed Usage: 163,911 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ;Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Lake Worth, TX, USA	1997E	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B68LEC90339 C/W: Located in Lane 19 Spot 32, 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, 10000 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 210,772 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Lake Worth, TX, USA
1997B	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B61LEC52192 C/W: Located in Lane 19 Spot 31, 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Drop-In Bed Liner, 10000 kg GVWR, 265 /70R17 Tires, 8 ft 6 in Bed Usage: 181,170 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
1997F	2019 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B62KEG40336 C/W: Located in Lane 19 Spot 4, 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft 6 in Bed Usage: 180,338 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ; Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Lake Worth, TX, USA	2001	2022 Chevrolet Silverado 2500HD Z71 4x4 Extended Cab Pickup S/N: 1GC5YLE7XNF194692 C/W: Located in Lane 19 Spot 15, 6.6 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10500 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 126,240 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
1997G	2019 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B6XKED41533 C/W: Located in Lane 19 Spot 29, 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft 6 in Bed Usage: 191,684 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ;Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Lake Worth, TX, USA	2002	2016 Chevrolet Silverado 2500HD 4x4 Pickup S/N: 1GC2KUEG9GZ139985 C/W: Located in Lane 20 Spot 12, Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 9500 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed Usage: 311,634 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
1998	2019 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B67KEC91044 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 183,509 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Oklahoma City, OK, USA	2004	2003 Ford F-250 XLT 4x4 Extended Cab Pickup S/N: 1FTNX21P83EC00544 C/W: Located in Lane 19 Spot 13, V8 Diesel Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 8800 lb GVWR, 275/65R20 Tires, 8 ft 4 in Bed Usage: 279,848 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. This unit is being sold with a rebuilt salvage title. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
1999	2017 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTEX1EP2HFB29735 C/W: 2.7 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather guard Tool Box, 6500 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 156,263 Mi Lot closing time: Thu, Sep 17, 10:35 AM CDT Asset located in: Midland, TX, USA	2007	2023 Chevrolet Silverado 2500HD 4x4 Pickup S/N: 1GC3YLE77PF233460 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, Spray-On Bed Liner, 10250 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 124,133 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:37 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2008	2023 Chevrolet Silverado 2500HD 4x4 Pickup S/N: 1GC3YLE72PF244740 C/W: 6.6 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 10250 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 128,673 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:37 AM CDT Asset located in: Midland, TX, USA	2014	2020 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A6XLED97641 C/W: Located in Lane 20 Spot 16, 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245 /75R17 Tires, 8 ft 6 in Bed, Equipment-from-a-Primoris-Services-Corp-company Usage: 156,037 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:39 AM CDT Asset located in: Lake Worth, TX, USA
2009	2023 Chevrolet Silverado 2500HD 4x4 Pickup S/N: 1GC3YLE78PF233824 C/W: 6.6 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 10250 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 140,715 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:38 AM CDT Asset located in: Midland, TX, USA	2015	2019 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A64KEE91691 C/W: Located in Lane 19 Spot 22, 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 191,809 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 10:39 AM CDT Asset located in: Lake Worth, TX, USA
2011	2025 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2AA7SEC48896 C/W: Located in Lane 19 Spot 19, 6.8 L V8 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 275/65R20 Tires, 8 ft Bed Usage: 8,220 Mi Notes: This unit is being sold with a not actual mileage-rebuilt salvage-loss unknown title. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:38 AM CDT Asset located in: Lake Worth, TX, USA	2015B	2019 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A62KEC80943 C/W: Located in Lane 19 Spot 33, 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Riki Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 245 /75R17 Tires, 7 ft Bed Usage: 239,677 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided ; Job Completion Fleet Realignment for Heavy Highway Joint Venture;Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:39 AM CDT Asset located in: Lake Worth, TX, USA
2012	2021 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A6XMED50658 C/W: Located in Lane 20 Spot 18, 6.2 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, RKI Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 6 in Bed Usage: 112,478 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:38 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2018	2017 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B66HEF45547 C/W: Located in Lane 19 Spot 26, 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 9 in Bed Usage: 279,263 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ;Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:40 AM CDT Asset located in: Lake Worth, TX, USA	2022	2016 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A67GED30047 C/W: Located in Lane 19 Spot 3, 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Headache Rack, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 158,940 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:41 AM CDT Asset located in: Lake Worth, TX, USA
2019	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A68HEB80709 C/W: Located in Lane 20 Spot 5, 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed Usage: 340,569 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:40 AM CDT Asset located in: Lake Worth, TX, USA	2025	2015 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A63FEC28050 C/W: Located in Lane 19 Spot 10, 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 230,980 Mi Notes: Vehicle history report available in documents section Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:41 AM CDT Asset located in: Lake Worth, TX, USA
2020	2016 Ford F-250 4x2 Crew Cab Pickup S/N: 1FT7W2A68GED02290 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 9 in Bed Usage: 219,217 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:40 AM CDT Asset located in: Lake Worth, TX, USA	2025A	2012 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A60CEC14411 C/W: Located in Lane 21 Spot 17, 6.2 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Weatherguard Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 248,760 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:41 AM CDT Asset located in: Humble, TX, USA
2021	2016 Ford F-250 4x2 Crew Cab Pickup S/N: 1FT7W2A65GEB63140 C/W: Located in Lane 20 Spot 6, 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 10 in Bed Usage: 268,133 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:40 AM CDT Asset located in: Lake Worth, TX, USA	2027	2020 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ2LG280118 C/W: Located in Lane 21 Spot 5, 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 97,655 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:42 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2028	2014 Ram 2500 ST 4x2 Crew Cab Pickup S/N: 3C6UR4HL9EG252918 C/W: Located in Lane 21 Spot 6, 6.7 L 6 Cylinder Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tractor Supply Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 169,406 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Has not actual mileage. Lot closing time: Thu, Sep 17, 10:42 AM CDT Asset located in: Humble, TX, USA	2034	2022 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A63NED47891 C/W: Located in Lane 20 Spot 8, 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 5 in Bed Usage: 137,682 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:43 AM CDT Asset located in: Lake Worth, TX, USA
2029	2021 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC1WLEYXMF159307 C/W: Located in Lane 19 Spot 8, 6.6 L Diesel Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft 2 in Bed Usage: 173,194 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:42 AM CDT Asset located in: Lake Worth, TX, USA	2035	2020 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A6XLEC57859 C/W: Located in Lane 19 Spot 2, 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245 /75R17 Tires, 7 ft Bed Usage: 183,204 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:44 AM CDT Asset located in: Lake Worth, TX, USA
2030	2018 Chevrolet Silverado 2500 4x2 Crew Cab Pickup S/N: 1GC1CUEG1JF231867 C/W: Located in Lane 21 Spot 1, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 182,122 Mi Lot closing time: Thu, Sep 17, 10:42 AM CDT Asset located in: Humble, TX, USA	2039	2019 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A66KEC13372 C/W: Located in Lane 20 Spot 11, 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 6 in Bed Usage: 184,630 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:45 AM CDT Asset located in: Lake Worth, TX, USA
2031	2017 Chevrolet Silverado 2500 4x2 Crew Cab Pickup S/N: 1GC1CUEG1HF223827 C/W: Located in Lane 21 Spot 2, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9500 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 177,598 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding Lot closing time: Thu, Sep 17, 10:43 AM CDT Asset located in: Humble, TX, USA	2040	2018 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A69JEB73013 C/W: 6.2 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Highway Products Tool Box Truck Cap, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 168,482 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:45 AM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
2041	2018 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A67JEC27196 C/W: Located in Lane 20 Spot 9, 6.2 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 240,098 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:45 AM CDT Asset located in: Lake Worth, TX, USA	2045	2009 Chevrolet Silverado 2500 HD LT 4x2 Extended Cab Pickup S/N: 1GCHC59K69E114841 C/W: 6.0 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9200 lb GVWR, 245/75R16 Tires, 6 ft 5 in Bed Usage: 302,632 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:46 AM CDT Asset located in: Lake Worth, TX, USA
2042	2015 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A6XFEC28057 C/W: Located in Lane 19 Spot 5, 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed Usage: 235,819 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 10:45 AM CDT Asset located in: Lake Worth, TX, USA	2046	2020 Chevrolet Silverado 2500 4x2 Pickup S/N: 1GC0WLE7XLF216476 C/W: Located in Lane 22 Spot 1, 6.6 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weatherguard Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 149,599 Mi Lot closing time: Thu, Sep 17, 10:46 AM CDT Asset located in: Humble, TX, USA
2043	2014 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A63EEB30633 C/W: Located in Lane 20 Spot 1, 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/75R17 Tires, 6 ft 8 in Bed Usage: 189,300 Mi Lot closing time: Thu, Sep 17, 10:45 AM CDT Asset located in: Lake Worth, TX, USA	2047	2015 Ram 2500 4x2 Pickup S/N: 3C6LR4AT6FG704900 C/W: Located in Lane 21 Spot 24, 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, BETTER BUILT Tool Box, 9000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 197,136 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:46 AM CDT Asset located in: Humble, TX, USA
2044	2019 Chevrolet Silverado 2500 HD 4x2 Extended Cab Pickup S/N: 2GC2CREG5K1203306 C/W: Located in Lane 22 Spot 6, 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9500 lb GVWR, 275/65R20 Tires, 8 ft Bed Usage: 252,328 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:46 AM CDT Asset located in: Humble, TX, USA	2050	2004 Ford F-250 XL 4x2 Pickup S/N: 1FTNF20S44ED43548 C/W: Located in Lane 21 Spot 12, 6.8 L V10 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Rawson Koenig Tool Box, 8800 lb GVWR, 235/85R16 Tires, 8 ft Bed Usage: 188,958 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:47 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2052	2023 Chevrolet Silverado 1500 4x4 Crew Cab Pickup S/N: 3GCUAED8PG180664 C/W: 5.3 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, Spray-On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 106,420 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:48 AM CDT Asset located in: Midland, TX, USA	2058	2022 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTFW1E54NKD53680 C/W: Located in Lane 22 Spot 4, 5.0 L Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 5 ft 7 in Bed Usage: 167,137 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ;Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:49 AM CDT Asset located in: Lake Worth, TX, USA
2054	2023 Chevrolet Silverado 1500 4x4 Crew Cab Pickup S/N: 3GCUAED9PG180673 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 6 in Bed Usage: 140,783 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:48 AM CDT Asset located in: Midland, TX, USA	2059	2021 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E5XMKD34825 C/W: 5.0 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, ProTech Tool Box, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 164,919 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:49 AM CDT Asset located in: Lake Worth, TX, USA
2056	2022 Ford F-150 Lariat 4x4 Crew Cab Pickup S/N: 1FTFW1E5XNKE82636 C/W: 5.0 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Spray-On Bed Liner, 7050 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 99,817 Mi Lot closing time: Thu, Sep 17, 10:48 AM CDT Asset located in: Livingston, LA, USA	2060	2021 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E5XMFB95790 C/W: 5.0 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, 7150 lb GVWR, 265/70R17 Tires, 5 ft 8 in Bed Usage: 186,321 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:49 AM CDT Asset located in: Oklahoma City, OK, USA
2057	2022 Ford F-150 STX 4x4 Crew Cab Pickup S/N: 1FTEW1EP6NFA66766 C/W: 2.7 L V6 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6600 lb GVWR, 265/60R20 Tires, 5 ft 6 in Bed Usage: 311,411 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:49 AM CDT Asset located in: Midland, TX, USA	2062	2021 Ford F-150 STX 4x4 Crew Cab Pickup S/N: 1FTEW1EP7MFA50669 C/W: 2.7 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6600 lb GVWR, 275/60R20 Tires, 6 ft 6 in Bed Usage: 292,366 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:50 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2063	2021 Ford F-150 STX 4x4 Crew Cab Pickup S/N: 1FTEW1EPXMFB93471 C/W: 2.7 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, 6600 lb GVWR, 275/60-20 Tires, 5 ft 6 in Bed Usage: 369,066 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:50 AM CDT Asset located in: Midland, TX, USA	2067	2024 GMC Sierra 1500 Elevation 4x4 Crew Cab Pickup S/N: 3GTUUCE80RG345723 C/W: Located in Lane 23 Spot 24, 3.0 L 6 Cylinder Diesel Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 7200 lb GVWR, 275/60R20 Tires, 6 ft 6 in Bed Usage: 124,441 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:51 AM CDT Asset located in: Humble, TX, USA
2064	2021 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1E59MFB38223 C/W: Located in Lane 23 Spot 12, 5 L V8 Gasoline Engine, 2021 US EPA Label, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, RKI Tool Box, 7050 lb GVWR, 265/70R18 Tires, 5 ft 6 in Bed Usage: 222,391 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. ; Additional Components Available In Office - Key Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 10:50 AM CDT Asset located in: Lake Worth, TX, USA	2068	2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DET5LG281987 C/W: 3.0 L Diesel Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 7200 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed Usage: 143,608 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:51 AM CDT Asset located in: Lake Worth, TX, USA
2064A	2020 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTEW1E56LKE60285 C/W: Located in Lane 22 Spot 15, 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Better Built Tool Box, 7000 lb GVWR, 265/70R18 Tires, 6 ft 0 in Bed Usage: 131,300 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:50 AM CDT Asset located in: Lake Worth, TX, USA	2069	2019 GMC Sierra 1500 SLE 4x4 Crew Cab Pickup S/N: 1GT12PEGXKF119252 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 9900 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 242,530 Mi Lot closing time: Thu, Sep 17, 10:52 AM CDT Asset located in: Midland, TX, USA
2065	2018 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E56JKF84204 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 129,886 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 10:51 AM CDT Asset located in: Oklahoma City, OK, USA	2070	2019 GMC Sierra 1500 SLE 4x4 Crew Cab Pickup S/N: 1GTU9BED3KZ304145 C/W: 5.3 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 7100 lb GVWR, 275/65R18 Tires, 5 ft 8 in Bed Usage: 165,037 Mi Lot closing time: Thu, Sep 17, 10:52 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2071	2018 GMC Sierra 1500 SLE 4x4 Crew Cab Pickup S/N: 3GTU2MEC5JG453694 C/W: 5.3 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fiberglass Truck Cap, Spray-On Bed Liner, 7200 lb GVWR, 275/70R18 Tires, 6 ft 6 in Bed Usage: 151,734 Mi Lot closing time: Thu, Sep 17, 10:52 AM CDT Asset located in: Midland, TX, USA	2075	2017 Chevrolet 1500 LT Z71 4x4 Crew Cab Texas Edition Pickup S/N: 3GCUKREC2HG164554 C/W: Located in Lane 21 Spot 22, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 7200 lb GVWR, 275/60R20 Tires, 6 ft Bed Usage: 229,802 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:53 AM CDT Asset located in: Lake Worth, TX, USA
2072	2020 Chevrolet Silverado 1500 LT 4x4 Crew Cab Pickup S/N: 3GCPYFEL9LG367847 C/W: Located in Lane 23 Spot 16, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 7000 lb GVWR, 295/55R20 Tires, 6 ft Bed Usage: 195,573 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:52 AM CDT Asset located in: Humble, TX, USA	2076	2014 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU2TEC4EG274451 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 265/70R18 Tires, 5 ft 8 in Bed Usage: 129,498 Mi Lot closing time: Thu, Sep 17, 10:53 AM CDT Asset located in: Midland, TX, USA
2072A	2019 Chevrolet Silverado 1500 4x4 Crew Cab Pickup S/N: 3GCUYAEFXKG102157 C/W: Located in Lane 21 Spot 1, 5.3 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, TrailFX Tool Box, Spray-On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 5 ft 10 in Bed Usage: 208,457 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:52 AM CDT Asset located in: Lake Worth, TX, USA	2076A	2019 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7KTXKS634881 C/W: Located in Lane 23 Spot 29, 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 181,387 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:53 AM CDT Asset located in: Humble, TX, USA
2073	2020 Chevrolet Silverado 4x4 Crew Cab Pickup S/N: 3GCUYAEF1LG310901 C/W: 5.3 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 285/70R17 Tires, 6 ft 8 in Bed Usage: 112,389 Mi Lot closing time: Thu, Sep 17, 10:52 AM CDT Asset located in: Livingston, LA, USA	2077	2015 Dodge Ram 1500 SLT 4x4 Crew Cab Pickup S/N: 1C6RR7TM6FS567791 C/W: Located in Lane 21 Spot 11, 3 L V6 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 6950 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed Usage: 353,940 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 10:53 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2079	2015 Ford F-150 King Ranch 4x4 Crew Cab Pickup S/N: 1FTEW1EG2FFC52662 C/W: Located in Lane 21 Spot 13, 3.5 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Drop-In Bed Liner, 7000 lb GVWR, 33x12.50R20LT Tires, 6 ft Bed Usage: 164,648 Mi Notes: This unit is being sold with a bonded, rebuilt salvage, actual mileage title; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:54 AM CDT Asset located in: Lake Worth, TX, USA	2082	2012 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF5CKD22931 C/W: Located in Lane 26 Spot 27, 5.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Drop-In Bed Liner, 7350 lb GVWR, 275/65R18 Tires, 5 ft 6 in Bed Usage: 288,399 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:55 AM CDT Asset located in: Humble, TX, USA
2080	2013 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1ET4DKD91276 C/W: Located in Lane 23 Spot 4, 3.5 L V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 245/75R17 Tires, 5 ft 6 in Bed Usage: 254,225 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 10:54 AM CDT Asset located in: Humble, TX, USA	2083	2014 Toyota Tundra SR5 4x4 Crew Cab Pickup S/N: 5TFDW5F19EX387241 C/W: Located in Lane 23 Spot 20, 5.7 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 275/55R20 Tires, 5 ft 8 in Bed Usage: 330,228 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:55 AM CDT Asset located in: Humble, TX, USA
2081	2012 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EFXCFB37069 C/W: Located in Lane 23 Spot 28, 5.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Drop-In Bed Liner, 7350 lb GVWR, 265/75R17 Tires, 5 ft 6 in Bed Usage: 319,945 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:54 AM CDT Asset located in: Humble, TX, USA	2084	2009 Dodge Ram 1500 4x4 Crew Cab Pickup S/N: 1D3HV13T59S725067 C/W: Located in Lane 23 Spot 9, 5.7 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 6 in Bed Usage: 182,706 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. This unit is being sold with a rebuilt salvage title Flood Damage. Lot closing time: Thu, Sep 17, 10:55 AM CDT Asset located in: Humble, TX, USA
		2085	2005 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 2GTEK13T051314853 C/W: 5.3 L V8 Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7000 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 342,691 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:55 AM CDT Asset located in: Livingston, LA, USA

Lot #	Details	Lot #	Details
2086	2021 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RRFCG3MN726587 C/W: 3.6 L V6 Gasoline Engine, 2021 US EPA Label, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 275/65R18 Tires, 6 ft 3 in Bed, Equipment-from-a-Primoris-Services-Corp-company Usage: 102,141 Mi Lot closing time: Thu, Sep 17, 10:55 AM CDT Asset located in: Livingston, LA, USA	2092	2020 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C51LKE60729 C/W: 5 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Tonneau Cover, 6800 lb GVWR, 265/60R18 Tires, 5 ft 6 in Bed Usage: 166,418 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:57 AM CDT Asset located in: Lake Worth, TX, USA
2087	2021 Ram 1500 Tradesman 4x4 Dual Cab Pickup S/N: 1C6RRFCG1MN726619 C/W: 3.6 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 275/65R18 Tires, 6 ft 3 in Bed, Equipment-from-a-Primoris-Services-Corp-company Usage: 144,413 Mi Lot closing time: Thu, Sep 17, 10:56 AM CDT Asset located in: Livingston, LA, USA	2093	2020 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTEW1C59LFA99503 C/W: Located in Lane 21 Spot 7, 5 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Riki Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 245/75R17 Tires, 6 ft Bed Usage: 145,864 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 10:57 AM CDT Asset located in: Lake Worth, TX, USA
2088	2021 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RRFCGXMN738199 C/W: 3.6 L V6 Gasoline Engine, 2021 US EPA Label, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 275/65R18 Tires, 6 ft 3 in Bed, Equipment-from-a-Primoris-Services-Corp-company Usage: 152,645 Mi Lot closing time: Thu, Sep 17, 10:56 AM CDT Asset located in: Livingston, LA, USA	2094	2020 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C59LKE12959 C/W: Located in Lane 21 Spot 6, 5 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6950 lb GVWR, 245/70R17 Tires, 7 ft Bed Usage: 237,328 Mi Notes: Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:57 AM CDT Asset located in: Lake Worth, TX, USA
2089	2021 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RRFCG2MN726600 C/W: 3.6 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 275/65R18 Tires, 6 ft 3 in Bed, Equipment-from-a-Primoris-Services-Corp-company Usage: 154,214 Mi Lot closing time: Thu, Sep 17, 10:56 AM CDT Asset located in: Livingston, LA, USA	2095	2019 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C50KKE53074 C/W: Located in Lane 22 Spot 6, 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6950 lb GVWR, 245/70R17 Tires, 7 ft Bed Usage: 164,014 Mi Notes: Additional Components Available In Office - Key Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 10:58 AM CDT Asset located in: Lake Worth, TX, USA
2091	2020 Ford F-150 Lariat 4x2 Crew Cab Pickup S/N: 1FTEW1C46LKD60519 C/W: Located in Lane 23 Spot 19, 3.5 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Headache Rack, Spray-On Bed Liner, 6750 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed Usage: 168,927 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:57 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2096	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C5XJKE03720 C/W: Located in Lane 23 Spot 9, 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6800 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 156,392 Mi Notes: Additional Components Available In Office - Key Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:58 AM CDT Asset located in: Lake Worth, TX, USA	2099	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CFXHKD77932 C/W: Located in Lane 21 Spot 8, 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6800 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 154,600 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:59 AM CDT Asset located in: Lake Worth, TX, USA
2097	2018 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTEW1C59JKF44553 C/W: Located in Lane 23 Spot 7, 5 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Protech Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 245/70R17 Tires, 5 ft 5 in Bed Usage: 150,700 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:58 AM CDT Asset located in: Humble, TX, USA	2100	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF0HKD77924 C/W: Located in Lane 22 Spot 5, 5 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 6800 lb GVWR, 245/70R17 Tires, 5 ft 5 in Bed Usage: 219,778 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:59 AM CDT Asset located in: Lake Worth, TX, USA
2098	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF9HKC08338 C/W: Located in Lane 23 Spot 8, 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 6800 lb GVWR, 245/70R17 Tires, 5 ft 6 in Bed Usage: 274,347 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:58 AM CDT Asset located in: Lake Worth, TX, USA	2101	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF3HKD77920 C/W: Located in Lane 21 Spot 12, 5 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6800 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 266,134 Mi Notes: Additional Components Available In Office - Key; Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 10:59 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2101A	2018 Ram 1500 4x2 Crew Cab Pickup S/N: 3C6RR6KT7JG195591 C/W: Located in Lane 23 Spot 18, 5.7 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 185,829 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 10:59 AM CDT Asset located in: Humble, TX, USA	2105B	2016 Chevrolet Silverado 1500 4x2 Crew Cab Pickup S/N: 3GCPCSECXGG194952 C/W: Located in Lane 21 Spot 4, 5.3 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, 7000 lb GVWR, 35x12.50R22L Tires, 5 ft 11 in Bed Usage: 233,433 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
2101B	2017 Ram 1500 4x2 Crew Cab Pickup S/N: 1C6RR6ST7HS623081 C/W: Located in Lane 23 Spot 30, 5.7 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 2 in Bed Usage: 158,061 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:00 AM CDT Asset located in: Humble, TX, USA	2107	2015 Chevrolet Silverado 1500 4x2 Crew Cab Pickup S/N: 3GCPCREC1FG523481 C/W: Located in Lane 23 Spot 8, 5.3 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 275/55R20 Tires, 6 ft 6 in Bed Usage: 256,040 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:00 AM CDT Asset located in: Humble, TX, USA
2105A	2021 Chevrolet Silverado 1500 Texas Edition 4x2 Crew Cab Pickup S/N: 1GCPWCED2MZ210708 C/W: Located in Lane 23 Spot 23, 5.3 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 6900 lb GVWR, 275/60R20 Tires, 6 ft Bed Usage: 270,702 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:00 AM CDT Asset located in: Humble, TX, USA	2108	2011 Chevrolet Silverado 1500 LT 4x2 Crew Cab Pickup S/N: 3GCPCSE02BG250249 C/W: Located in Lane 23 Spot 14, 5.3 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6800 lb GVWR, 275/65R20 Tires, 6 ft Bed Usage: 182,150 Mi Lot closing time: Thu, Sep 17, 11:01 AM CDT Asset located in: Humble, TX, USA
		2109	2020 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFEY5F16LX267103 C/W: Located in Lane 24 Spot 14, 5.7 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Drop-In Bed Liner, 7000 lb GVWR, 265/70R18 Tires, 5 ft 6 in Bed Usage: 194,195 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:01 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2109A	2010 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTFW1CV0AKB55112 C/W: Located in Lane 22 Spot 13, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 312,465 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	2112	2021 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C5XMKE45662 C/W: Located in Lane 22 Spot 21, 5.0 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 93,712 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report is available in the documents section Lot closing time: Thu, Sep 17, 11:02 AM CDT Asset located in: Lake Worth, TX, USA
2110	2004 Dodge Ram 1500 SLT 4x2 Dual Cab Pickup S/N: 1D7HA18DX4J216182 C/W: Located in Lane 23 Spot 21, 5.7 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6650 lb GVWR, 265/70R15 Tires, 8 ft Bed Usage: 78,287 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 11:01 AM CDT Asset located in: Humble, TX, USA	2113	2021 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1C57MKE45652 C/W: Located in Lane 22 Spot 15, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Truck Cap, Drop-In Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 103,119 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise registration will not be provided. Vehicle history report available in the document section ; Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:02 AM CDT Asset located in: Lake Worth, TX, USA
2111	2021 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C55MKE45665 C/W: Located in Lane 22 Spot 2, 5 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, WeatherGuard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 245/70R17 Tires, 7 ft Bed Usage: 65,407 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Additional Components Available In Office - Key Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	2116	2019 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C52KKC62057 C/W: Located in Lane 21 Spot 9, 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather guard Tool Box, Spray-On Bed Liner, 245/75R17 Tires, 6 ft 4 in Bed Usage: 119,510 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise, registration will not be provided. : Additional Components Available In Office - Key Vehicle history report is available in the document section ;Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:02 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2117	2019 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C57KKE18187 C/W: Located in Lane 22 Spot 17, 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 159,031 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:03 AM CDT Asset located in: Lake Worth, TX, USA	2127	2013 Toyota Tundra SR5 4x2 Extended Cab Pickup S/N: 5TFRM5F14DX053757 C/W: Located in Lane 23 Spot 2, 4.6 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 6700 lb GVWR, 275/55R20 Tires, 6 ft 6 in Bed Usage: 249,483 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:05 AM CDT Asset located in: Humble, TX, USA
2118	2018 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CP9JKF96117 C/W: 2.7 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6400 lb GVWR, 245/75R17 Tires, 6 ft 5 in Bed Usage: 180,113 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 11:03 AM CDT Asset located in: Oklahoma City, OK, USA	2128	2002 Chevrolet Silverado 1500 4x2 Extended Cab Pickup S/N: 1GCEC19R12Z343676 C/W: 5.7 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 245/75R16 Tires, 6 ft 8 in Bed Usage: 288,883 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:05 AM CDT Asset located in: Lake Worth, TX, USA
2123	2017 Chevrolet Silverado 1500 4x2 Crew Cab Pickup S/N: 1GCRNCE9HZ338342 C/W: Located in Lane 23 Spot 26, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 7000 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 257,747 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 11:04 AM CDT Asset located in: Humble, TX, USA	2130	2019 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1C54KKD91951 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6750 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 57,264 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 11:06 AM CDT Asset located in: San Antonio, TX, USA
2125	2014 Chevrolet 1500 Silverado 4x2 Crew Cab Pickup S/N: 1GCRPEC9EZ412883 C/W: Located in Lane 23 Spot 22, 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 6 ft Bed Usage: 386,658 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:05 AM CDT Asset located in: Humble, TX, USA	2133	2011 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1CM4BKD47570 C/W: Located in Lane 22 Spot 9, 6 Cylinder Gasoline Engine, Automatic Transmission, Air Conditioner, RKI Tool Box, Drop-In Bed Liner, 6750 lb GVWR, 235/75R16 Tires, 8 ft 2 in Bed Usage: 280,078 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:06 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2134	2006 Chevrolet Silverado 1500 4x2 Pickup S/N: 3GCEC14X46G255121 C/W: Located in Lane 22 Spot 1, 4.3 L V6 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 114,037 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:07 AM CDT Asset located in: Lake Worth, TX, USA	2138	2021 Chevrolet Colorado 4x2 Crew Cab Pickup S/N: 1GCGSBEA6M1167288 C/W: Located in Lane 23 Spot 11, 2.5 L 4 Cylinder Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 265/60R18 Tires, 5 ft 2 in Bed Usage: 70,448 Mi Notes: This unit is being sold with a rebuilt salvage title. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:08 AM CDT Asset located in: Humble, TX, USA
2137A	2019 Chevrolet Colorado 4x4 Crew Cab Pickup S/N: 1GCGTBEN0K1166182 C/W: Located in Lane 22 Spot 10, 3.6 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6000 lb GVWR, 265/70R16 Tires, 5 ft 6 in Bed Usage: 124,642 Hr Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:07 AM CDT Asset located in: Lake Worth, TX, USA	2139	1998 Toyota Tacoma 4x2 Pickup S/N: 4TANL42N1WZ104820 C/W: Located in Lane 23 Spot 40, 2.4 L 4 Cylinder Gasoline Engine, 1998 US EPA Label, Automatic Transmission, Air Conditioner, 4250 lb GVWR, 215/70R14 Tires, 6 ft Bed Usage: 177,770 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Title brand salvage Lot closing time: Thu, Sep 17, 11:08 AM CDT Asset located in: Humble, TX, USA
2137B	2018 Chevrolet Colorado 4x4 Crew Cab Pickup S/N: 1GCGTBEN9J1102947 C/W: Located in Lane 21 Spot 25, 3.6 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6000 lb GVWR, 265/70R16 Tires, 6 ft 6 in Bed Usage: 264,538 Hr Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:07 AM CDT Asset located in: Lake Worth, TX, USA	2141	2011 Ford E350 4x2 12-Seat Bus S/N: 1FDEE3FL1BDA16919 C/W: Located in Lane 36 Spot 44, Air Conditioner, Automatic Transmission, Wheelchair Lift, V8 5.4 L Gasoline Engine, 2011 US EPA Label, 225/70R19.5, Spring Suspension, 200 in Wheelbase Usage: 141,000 Mi Lot closing time: Thu, Sep 17, 11:08 AM CDT Asset located in: Humble, TX, USA
2137C	2018 Chevrolet Colorado 4x4 Crew Cab Pickup S/N: 1GCGTBEN5J1188211 C/W: Located in Lane 22 Spot 12, 3.6 L V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray-On Bed Liner, 6000 lb GVWR, 265/70R16 Tires, 6 ft 6 in Bed Usage: 327,172 Hr Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:08 AM CDT Asset located in: Lake Worth, TX, USA	2142	2015 Altec L37M 37 ft on 2016 Freightliner M2 106 4x4 Bucket Truck S/N: 1FVDCXCY1GHHD5989 C/W: Located in Lane 47 Spot 9, Cummins ISL9 8.9 L Diesel Engine, Allison Automatic Transmission, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 166 in Wheelbase, PTO, 350 lb Capacity, Center Mounted, One-Person Articulating-Telescopic Boom, Utility Body, A-Outriggers, 14 ft x 94 in Bed, Winch Usage: 166,190 Mi Notes: This unit is being sold with a rebuilt salvage-loss unknown title. Lot closing time: Thu, Sep 17, 11:09 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2143	2005 High Ranger GFC55 55 ft on 2006 Ford F-750 4x2 Bucket Truck S/N: 3FRXF75R56V228933 C/W: Located in Lane 36 Spot 2, Cat C7 6 Cylinder Diesel Engine, 2005 US EPA Label, 5-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulated Boom, Flatbed, A-Outriggers, Rear Outriggers, 16 ft x 94 in Bed Usage: 23,811 Mi Lot closing time: Thu, Sep 17, 11:09 AM CDT Asset located in: Humble, TX, USA	2147	Altec AT200A 300 lb Straight Boom on 2011 Dodge Ram 4500 4x2 Bucket Truck (Inoperable) S/N: 3D6WA6EL5BG517705 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 11408 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225 /70R19.5, Spring Suspension, 146 in Wheelbase, 9 ft x 96 in Bed, Pintle Hitch Usage: 188,959 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 11:10 AM CDT Asset located in: San Antonio, TX, USA
2144	Versalift on 2015 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GTXFEC65092 C/W: Located in Lane 36 Spot 13, Ford V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 166 in Wheelbase, Center Mounted, Insulated Two-Person Articulating-Telescopic Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, 13 ft x 96 in Bed, Pintle Hitch Usage: 132,932 Mi Lot closing time: Thu, Sep 17, 11:09 AM CDT Asset located in: Humble, TX, USA	2150	2011 Ford F-350 XL 4x4 Crew Cab Chipper Truck S/N: 1FD8W3HT3BEC10708 C/W: Located in Lane 36 Spot 45, Ford V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 4 in Long x 4 ft High Steel Body, Split Swing Tailgate, Pintle Hitch Usage: 300,524 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal Lot closing time: Thu, Sep 17, 11:10 AM CDT Asset located in: Humble, TX, USA
2145	Versalift TEL29N-03 29 ft on 2013 Ram 4500 4x2 Bucket Truck S/N: 3C7WRKAL2DG563057 C/W: Cummins 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 938 Engine hrs, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225 /70R19.5, Spring Suspension, 146 in Wheelbase, PTO, 350 lb Capacity, Front Mounted, One-Person Telescopic Boom, Utility Body, Remote Control w/Cord, 9 ft x 96 in Bed Usage: 187,579 Mi Notes: License plates will not be provided. ; Aerial units require proper safety harness, lanyard, and ppe to function test and load Lot closing time: Thu, Sep 17, 11:09 AM CDT Asset located in: San Antonio, TX, USA	2151	2005 Freightliner M2 106 4x2 Leaf Collection Truck S/N: 1FVACXDC85HV32909 C/W: Located in Lane 47 Spot 8, Cat C7 Diesel 230 hp Engine, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 217 in Wheelbase, Hydraulic System Usage: 35,019 Mi Lot closing time: Thu, Sep 17, 11:11 AM CDT Asset located in: Lake Worth, TX, USA
2146	Versalift on 2012 Ram 4500 4x2 Bucket Truck S/N: 3C7WDBKBL5CG200649 C/W: Cummins 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 8627 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 172 in Wheelbase, Center Mounted, One-Person Telescopic Boom, Utility Body, 11 ft x 96 in Bed Usage: 144,809 Mi Lot closing time: Thu, Sep 17, 11:09 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2152	2006 Schwing 58SX 174 ft on 2005 TOR T-63120-2 12x8 Tri-Steer Concrete Pump Truck S/N: 2T9638HC250070058 C/W: Located in Lane 43 Spot 21, Detroit Series 60 12.7 L Diesel 455 hp Engine, 2004 US EPA Label, 7629 Engine hrs, Engine Brake, Allison Automatic Transmission, 64000 lb Front Axle, 68500 lb Rears, 132500 lb GVWR, 425/65R22.5 Front Tires, 12R24.5 Rear Tires, Steerable Air Lift Tag Axle, Air Assist Front Suspension, Air Ride Suspension, 362 in Wheelbase, PTO, 3681 Pump Hours, Cable Remote Controls Usage: 74,234 Mi Lot closing time: Thu, Sep 17, 11:11 AM CDT Asset located in: Lake Worth, TX, USA	2156	2007 Schwing 2525H / S 58 SX 58 m on 2007 Mack MR688S Terrapro 14x6 Tri-Steer Concrete Pump Truck S/N: 1M2K201C37M038977 C/W: Located in Lane 43 Spot 20, 6 Cylinder Diesel Engine, 14682.9 Engine hrs, Engine Brake, Allison 6-Speed Automatic Transmission, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 324 in Wheelbase, 5294 Pump Hours, Cable Remote Controls, Outrigger Pads, Auto Lube, 2007 Schwing 58m Concrete Pump Engine Hours 14682, PTO Hours 5294 Usage: 826,806 Mi Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Thu, Sep 17, 11:12 AM CDT Asset located in: Lake Worth, TX, USA
2153	2020 Sany SY38 on 2020 Mack GR64B 6x4 Concrete Pump Truck S/N: 1M2GR2GC0LM014425 C/W: Located in Lane 43 Spot 23, Mack MP7 6 Cylinder 10.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 3999 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Camelback Spring Suspension, 270 in Wheelbase, PTO, Radio Remote Controls, Outrigger Pads Usage: 34,341 Mi Lot closing time: Thu, Sep 17, 11:11 AM CDT Asset located in: Lake Worth, TX, USA	2156A	2021 Mack GR84F 10x4 Mixer Truck S/N: 1M2GR2NC7MM001692 C/W: Located in Lane 24 Spot 23, Mack MP7 10.8 L Diesel 375 hp Engine, 2020 US EPA Label, 8835 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 59000 lb Rears, 79000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, Double Frame, Camelback Suspension, 243 in Wheelbase, McNeilus 11 cyd Mixer Unit, 1 Removable Chutes, Remote Control w/Cord Usage: 109,395 Mi Lot closing time: Thu, Sep 17, 11:12 AM CDT Asset located in: Humble, TX, USA
2154	2015 Alliance 38R 33 m on 2015 Mack MRU613 6x4 Concrete Pump Truck S/N: 1M2AV04C9FM013191 C/W: Located in Lane 36 Spot 29, Mack MP7 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 8LL Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Camelback Spring Suspension, 220 in Wheelbase, Wet Kit, 2549 Pump Hours, Radio and Cable Remote Controls, Boom Light, Hopper Vibrator Usage: 110,062 Mi Lot closing time: Thu, Sep 17, 11:11 AM CDT Asset located in: Humble, TX, USA	2157	2019 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALMG3DV8KDKK1025 C/W: Located in Lane 46 Spot 14, Detroit DD13 Diesel Engine, Requires Diesel Exhaust Fluid, 10596.0 Engine hrs, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 59200 lb Rears, 79200 lb GVWR, 425/65R22.5, Steerable Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Dual Steering Boxes, Hendrickson Haulmaax Suspension, 252 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Equipment-from-Big-Creek-Construction Usage: 151,806 Mi Lot closing time: Thu, Sep 17, 11:12 AM CDT Asset located in: Lake Worth, TX, USA
2155	2012 BSF 36Z.16H 36 m on 2012 Mack MRU613 8x4 Concrete Pump Truck S/N: 1M2AV04C1CM009468 C/W: Located in Lane 43 Spot 19, Mack MP7 6 Cylinder 10.8 L Diesel 425 hp Engine, 2011 US EPA Label, Mack Maxitorque ES Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Camelback Suspension, 218 in Wheelbase, PTO, Radio Remote Controls Usage: 184,438 Mi Lot closing time: Thu, Sep 17, 11:12 AM CDT Asset located in: Lake Worth, TX, USA	2158	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV3JHJN5381 C/W: Detroit DD13 6 Cylinder Diesel Engine, 15645 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 230 in Wheelbase, PTO, 10.5 cyd Mixer Unit, 2 Removable Chutes, Equipment-from-Big-Creek-Construction Usage: 239,944 Mi Lot closing time: Thu, Sep 17, 11:12 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2159	2015 Peterbilt 567 8x4 Mixer Truck S/N: 1NPCXPEX4FD292236 C/W: Located in Lane 33 Spot 6, Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 682 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, Differential Lock, 20000 lb Front Axle, 57021 lb Rears, 77020 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65 /22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber Suspension, 240 in Wheelbase, Con-Tech 11.5 cyd Mixer Unit, Remote Control w/Cord Usage: 239,160 Mi Lot closing time: Thu, Sep 17, 11:13 AM CDT Asset located in: Humble, TX, USA	2162	2016 Kenworth T880 6x4 Mixer Truck S/N: 1NKZLP0X0GJ498353 C/W: Located in Lane 46 Spot 15, Paccar MX-13 6 Cylinder 12.9 L Diesel 380 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 7874 Engine hrs, Engine Brake, Eaton Fuller RT014908LL 8LL Manual Transmission, Double Differential Locks, 23000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Con-Tech 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 89,945 Mi Lot closing time: Thu, Sep 17, 11:13 AM CDT Asset located in: Lake Worth, TX, USA
2160	2007 Sterling LT9500 8x4 Mixer Truck S/N: 2FZMAZCV27AX71765 C/W: Located in Lane 33 Spot 9, Mercedes-Benz OM460LA 6 Cylinder Diesel 450 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller 9LL Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 57020 lb Rears, 80000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 252 in Wheelbase, Remote Control w/Cord Usage: 314,852 Mi Lot closing time: Thu, Sep 17, 11:13 AM CDT Asset located in: Humble, TX, USA	2163	2013 Peterbilt 365 8x4 Mixer Truck S/N: 1NP5L5EX6DD194219 C/W: Located in Lane 24 Spot 22, Cummins 6 Cylinder Diesel Engine, 14640 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 80000 lb GVWR, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 274 in Wheelbase, Kimble Mixer Unit Usage: 53,226 Mi Lot closing time: Thu, Sep 17, 11:13 AM CDT Asset located in: Humble, TX, USA
2161	2016 Kenworth T880 6x4 Mixer Truck S/N: 1NKZLP0X2GJ498354 C/W: Located in Lane 46 Spot 13, Paccar MX-13 6 Cylinder 12.9 L Diesel 380 hp Engine, 2015 US EPA Label, 6921 Engine hrs, Engine Brake, Eaton Fuller RT014908LL 8LL Manual Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 234 in Wheelbase, PTO, Con-Tech Mixer Unit, 2 Removable Chutes Usage: 79,841 Mi Lot closing time: Thu, Sep 17, 11:13 AM CDT Asset located in: Lake Worth, TX, USA	2164	2015 Kenworth T400 6x4 Mixer Truck S/N: 1NKBLJ0X7FJ421475 C/W: Located in Lane 33 Spot 14, Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18711 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Chalmers Suspension, 235 in Wheelbase, PTO, Beck 10 cyd Mixer Unit, 3 Removable Chutes Usage: 164,490 Mi Lot closing time: Thu, Sep 17, 11:14 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2165	2016 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C7GM031241 C/W: Located in Lane 33 Spot 8, Mack MP7 6 Cylinder Diesel Engine, 170964 Engine hrs, Engine Brake, Allison Automated Transmission, Double Differential Locks, 22800 lb Front Axle, 23000 lb Rears, 68800 lb GVWR, Air Ride Cab, Steel, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Camelback Spring Suspension, 224 in Wheelbase, 3 Removable Chutes Usage: 170,964 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 11:14 AM CDT Asset located in: Humble, TX, USA	2168	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C9HM033955 C/W: Located in Lane 24 Spot 28, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 251 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: Not Available Lot closing time: Thu, Sep 17, 11:15 AM CDT Asset located in: Humble, TX, USA
2166	2015 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C0FM029670 C/W: Located in Lane 33 Spot 18, Mack MP7 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10645 Engine hrs, Eaton Fuller 9LL Manual Transmission, 22800 lb Front Axle, 46000 lb Rears, 68800 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 224 in Wheelbase, 3 Removable Chutes Usage: 208,761 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Previously in accident see report in documents Lot closing time: Thu, Sep 17, 11:14 AM CDT Asset located in: Humble, TX, USA	2169	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C1HM033951 C/W: Located in Lane 24 Spot 29, Mack MP7 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 250 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 151,955 Mi Lot closing time: Thu, Sep 17, 11:15 AM CDT Asset located in: Humble, TX, USA
2167	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C5HM033953 C/W: Located in Lane 33 Spot 16, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 252 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 138,489 Mi Lot closing time: Thu, Sep 17, 11:14 AM CDT Asset located in: Humble, TX, USA	2170	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C3HM033952 C/W: Located in Lane 33 Spot 22, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 251 in Wheelbase, 3 Removable Chutes Usage: Not Available Lot closing time: Thu, Sep 17, 11:15 AM CDT Asset located in: Humble, TX, USA
		2171	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C7HM033954 C/W: Located in Lane 33 Spot 17, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 251 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 160,247 Mi Lot closing time: Thu, Sep 17, 11:15 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2172	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C1HM033948 C/W: Located in Lane 33 Spot 15, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 250 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 168,920 Mi Lot closing time: Thu, Sep 17, 11:16 AM CDT Asset located in: Humble, TX, USA	2176	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C0HM033956 C/W: Located in Lane 24 Spot 31, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 252 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 175,372 Mi Lot closing time: Thu, Sep 17, 11:16 AM CDT Asset located in: Humble, TX, USA
2173	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C4HM033944 C/W: Located in Lane 00 Spot 0, Mack MP7 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 252 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 169,468 Mi Lot closing time: Thu, Sep 17, 11:16 AM CDT Asset located in: Humble, TX, USA	2177	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C0HM033925 C/W: Located in Lane 24 Spot 30, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 251 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 180,200 Mi Lot closing time: Thu, Sep 17, 11:17 AM CDT Asset located in: Humble, TX, USA
2174	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C8HM033946 C/W: Located in Lane 24 Spot 33, Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 250 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 144,598 Mi Lot closing time: Thu, Sep 17, 11:16 AM CDT Asset located in: Humble, TX, USA	2178	2016 Mack CV713 8x4 Mixer Truck S/N: 1M2AX04C6GM027867 C/W: Located in Lane 24 Spot 25, Mack MP7 6 Cylinder 10.8 L Diesel 365 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 20000 lb Front Axle, 38000 lb Rears, Air Ride Cab, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Chalmers Suspension, 250 in Wheelbase, McNeilus Mixer Unit Usage: Not Available Notes: Vehicle has not actual mileage. Lot closing time: Thu, Sep 17, 11:17 AM CDT Asset located in: Humble, TX, USA
2175	2017 Mack GU713 6x4 Mixer Truck S/N: 1M2AX04C5HM033922 C/W: Located in Lane 24 Spot 27, Mack MP7 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 252 in Wheelbase, Beck 10.5 cyd Mixer Unit, 2 Removable Chutes, Remote Control w/Cord Usage: 170,287 Mi Lot closing time: Thu, Sep 17, 11:16 AM CDT Asset located in: Humble, TX, USA	2179	2018 International HX615 6x4 Mixer Truck S/N: 3HTDSSNT4JN441152 C/W: Located in Lane 33 Spot 12, 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18658 Engine hrs, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 226 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available Lot closing time: Thu, Sep 17, 11:17 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2180	2011 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C3BM012615 C/W: Located in Lane 33 Spot 23, Mack 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 2095 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 57280 lb Rears, 77280 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 12R24.5 Rear Tires, Dual Steering Boxes, Camelback Suspension, 250 in Wheelbase, PTO, Continental 12 cyd Mixer Unit, 3 Removable Chutes Usage: 155,800 Mi Lot closing time: Thu, Sep 17, 11:17 AM CDT Asset located in: Humble, TX, USA	2185	2007 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C77M051587 C/W: Located in Lane 33 Spot 24, Mack 6 Cylinder Diesel Engine, 28910 Engine hrs, Manual Transmission, Double Differential Locks, 18740 lb Front Axle, 46000 lb Rears, 64740 lb GVWR, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 315/80R22.5 Rear Tires, Double Frame, Hendrickson Rubber over Walking Beam Suspension, 244 in Wheelbase, 2 Removable Chutes Usage: 317,090 Mi Lot closing time: Thu, Sep 17, 11:19 AM CDT Asset located in: Humble, TX, USA
2182	2007 Peterbilt 357 6x4 Mixer Truck S/N: 1NPAL50X57N699699 C/W: Located in Lane 33 Spot 7, Cummins ISL 330 6 Cylinder 8.9 L Diesel 330 hp Engine, 13601 Engine hrs, Eaton Fuller 8LL Manual Transmission, Differential Lock, 2200 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 223 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 211,450 Mi Lot closing time: Thu, Sep 17, 11:18 AM CDT Asset located in: Humble, TX, USA	2186	2007 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C77M053310 C/W: Located in Lane 33 Spot 21, 6 Cylinder Diesel Engine, 18169 Engine hrs, Eaton Fuller 9LL Manual Transmission, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Spring Suspension, 250 in Wheelbase, Terex Mixer Unit, 3 Removable Chutes Usage: 202,731 Mi Lot closing time: Thu, Sep 17, 11:19 AM CDT Asset located in: Humble, TX, USA
2183	2007 Peterbilt 357 6x4 Mixer Truck S/N: 1NPAL50X37N699698 C/W: Located in Lane 33 Spot 20, Cummins 6 Cylinder Diesel Engine, 14055 Engine hrs, Eaton Fuller 8LL Manual Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber Suspension, 224 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes Usage: 213,376 Mi Lot closing time: Thu, Sep 17, 11:18 AM CDT Asset located in: Humble, TX, USA	2188	2007 International Paystar 5600i 6x4 Mixer Truck S/N: 1HTXHAHT57J563077 C/W: Located in Lane 46 Spot 14, Cummins ISM350V 10.8 L Diesel 335 hp Engine, 2006 US EPA Label, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 215 in Wheelbase, CBMW 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 40,709 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:19 AM CDT Asset located in: Lake Worth, TX, USA
2184	2007 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C77M051556 C/W: Located in Lane 33 Spot 25, Mack 6 Cylinder Diesel Engine, 32815 Engine hrs, Manual Transmission, Double Differential Locks, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Rubber over Walking Beam Suspension, 244 in Wheelbase, 2 Removable Chutes Usage: 327,657 Mi Lot closing time: Thu, Sep 17, 11:18 AM CDT Asset located in: Humble, TX, USA	2189	2007 International Paystar 5600i 6x4 Mixer Truck S/N: 1HTXHAHT17J563075 C/W: Located in Lane 46 Spot 25, Cummins ISM 350V 10.8 L Diesel 335 hp Engine, 2006 US EPA Label, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 215 in Wheelbase, CBMW Mixers 10.5 cyd Mixer Unit, 0 Removable Chutes Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:20 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2190	2007 International Paystar 5600i 6x4 Mixer Truck S/N: 1HTXHAHT57J563080 C/W: Located in Lane 46 Spot 23, Cummins ISM 350V 10.8 L Diesel Engine, 2006 US EPA Label, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 214 in Wheelbase, CBMW Mixers Mixer Unit, 3 Removable Chutes Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	2193	2007 International Paystar 5600i 6x4 Mixer Truck S/N: 1HTXHAHTX7J563074 C/W: Located in Lane 46 Spot 24, Cummins ISM350V 10.8 L Diesel 335 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 215 in Wheelbase, CBMW Mixers 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:20 AM CDT Asset located in: Lake Worth, TX, USA
2191	2007 International Paystar 5600i 6x4 Mixer Truck S/N: 1HTXHAHT97J563079 C/W: Located in Lane 46 Spot 23, Cummins ISM 350V 10.8 L Diesel Engine, 2006 US EPA Label, Eaton Fuller 8LL Manual Transmission, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 214 in Wheelbase, CBMW Mixers 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	2194	2007 International Paystar 5600i 6x4 Mixer Truck S/N: 1HTXHAHT37J563076 C/W: Located in Lane 46 Spot 21, Cummins ISM 350V 10.8 L Diesel Engine, 2006 US EPA Label, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 214 in Wheelbase, CBMW Mixers 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
2192	2007 International Paystar 5600i 6x4 Mixer Truck S/N: 1HTXHAHT77J563078 C/W: Located in Lane 46 Spot 22, Cummins ISM350V 10.8 L Diesel Engine, 2006 US EPA Label, 14062 Engine hrs, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 214 in Wheelbase, CBMW Mixers 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 40,155 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	2195	2004 Peterbilt 357 8x4 Mixer Truck S/N: 1NPAL00X94D813157 C/W: Located in Lane 33 Spot 13, Cummins ISM Diesel Engine, 9085 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Hendrickson Haulmaax Rubber Suspension, 251 in Wheelbase, McNeilus 11 cyd Mixer Unit, Remote Control w/Cord Usage: 236,550 Mi Lot closing time: Thu, Sep 17, 11:21 AM CDT Asset located in: Humble, TX, USA
		2196	2002 International 5500i 8x4 Mixer Truck S/N: 1HTXLAXT82J038281 C/W: Located in Lane 24 Spot 26, Cat C12 6 Cylinder Diesel 355 hp Engine, 9711 Engine hrs, Eaton Fuller 9LL Manual Transmission, Differential Lock, 20000 lb Front Axle, 57020 lb Rears, 80000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Chalmers Rubber Suspension, 248 in Wheelbase, McNeilus 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 270,823 Mi Lot closing time: Thu, Sep 17, 11:21 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2198A	2022 Freightliner 114SD 8x4 Volumetric Mixer Truck S/N: 3ALMG3DV5NDMW5722 C/W: Located in Lane 24 Spot 24, Detroit DD13 12.8 L Diesel 450 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 3553 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 79200 lb GVWR, Air Ride Cab, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 240 in Wheelbase, 2021 ProAll G9500C1 Mixer Unit Usage: 58,249 Mi Lot closing time: Thu, Sep 17, 11:22 AM CDT Asset located in: Humble, TX, USA	2210	2007 Hino 268 4x2 Attenuator Truck S/N: 5PVNE8JTX72S51654 C/W: Located in Lane 36 Spot 37, Hino J08E-TA 6 Cylinder 7.7 L Diesel 220 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 255 in Wheelbase, Stake Side Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 127,339 Mi Lot closing time: Thu, Sep 17, 11:24 AM CDT Asset located in: Humble, TX, USA
2199	Mauldin MPS on 2012 International 7300 4x2 Asphalt Distributor Truck S/N: 1HTZZAAN4CJ655731 C/W: Located in Lane 47 Spot 22, Diesel Engine, 3767 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 180 in Wheelbase, PTO, Hand Spray Wand, Hydraulic Driven Pump Usage: 75,018 Mi Lot closing time: Thu, Sep 17, 11:22 AM CDT Asset located in: Lake Worth, TX, USA	2210A	2005 Freightliner M2 106 4x2 Attenuator Truck S/N: 1FVACWDC45HU55420 C/W: Located in Lane 47 Spot 13, Cat C7 6 Cylinder Diesel 190 hp Engine, 15882.9 Engine hrs, Eaton Fuller FS-5406A 6-Speed Manual Transmission, 8000 lb Front Axle, 19000 lb Rears, Meritor RS-19-144 Drive Axles, 4.11:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 234 in Wheelbase, Stake Side Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 261,341 Mi Lot closing time: Thu, Sep 17, 11:25 AM CDT Asset located in: Lake Worth, TX, USA
2204	2013 International 4300 4x2 Attenuator Truck S/N: 1HTMMAAM2DH100138 C/W: Located in Lane 36 Spot 16, International MaxxForce DT 6 Cylinder 7.6 L Diesel Engine, 5756 Engine hrs, Automatic Transmission, Aluminum Front Wheels, 11R22.5, Spring Suspension, 270 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 150,965 Mi Lot closing time: Thu, Sep 17, 11:23 AM CDT Asset located in: Humble, TX, USA	2210B	2004 International 4300 4x2 Attenuator Truck S/N: 1HTMMAAM44H596852 C/W: Located in Lane 36 Spot 7, International DT466 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, 25550 lb GVWR, 11R22.5, Spring Suspension, 208 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 311,617 Mi Lot closing time: Thu, Sep 17, 11:25 AM CDT Asset located in: Humble, TX, USA
2205	2011 International 4300 4x2 Attenuator Truck S/N: 1HTMMAAM0BH283343 C/W: Located in Lane 36 Spot 14, International 6 Cylinder Diesel 210 hp Engine, 2009 US EPA Label, 10074 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 237 in Wheelbase, Stake Side Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 270,622 Mi Lot closing time: Thu, Sep 17, 11:23 AM CDT Asset located in: Humble, TX, USA	2213	2000 International 4900 4x2 Attenuator Truck S/N: 1HTSDAAN9YH233761 C/W: International DT466 6 Cylinder Diesel Engine, Eaton Fuller 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 10R22.5, Double Frame, Spring Suspension, 237 in Wheelbase, Stake Side Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 19,833 Mi Lot closing time: Thu, Sep 17, 11:25 AM CDT Asset located in: Midland, TX, USA
		2214	2016 Ford F-650 4x2 Attenuator Truck S/N: 1FDNF6AY5GDA00408 C/W: Ford V10 6.8 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Steel, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 218 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 66,068 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:25 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2214A	2000 Chevrolet C7500 4x2 Attenuator Truck S/N: 1GBM7H1C1YJ525051 C/W: Located in Lane 47 Spot 12, Cat 3126 6 Cylinder 7.2 L Diesel Engine, Allison Automatic Transmission, 11000 lb Front Axle, 22000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 195 in Wheelbase, Flatbed Usage: 327,042 Mi Lot closing time: Thu, Sep 17, 11:25 AM CDT Asset located in: Lake Worth, TX, USA	2217	2020 Freightliner Cascadia 113 10x4 Quad/A Dump Truck S/N: 3AKJGBDV9LSLH6757 C/W: Located in Lane 33 Spot 41, Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Double Frame, Airliner Air Ride Suspension, 174 in Wheelbase, 18 ft 8 in Long x 60 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 679,048 Mi Notes: Title brand reconstructed Lot closing time: Thu, Sep 17, 11:26 AM CDT Asset located in: Humble, TX, USA
2215	2018 Kenworth T880 10x4 Quad/A Dump Truck S/N: 1NKZXKTX1JJ222774 C/W: Located in Lane 33 Spot 27, Paccar MX-11 10.8 L Diesel 430 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FO-16E308LL-VCS 8LL Automated Transmission, Double Differential Locks, 20000 lb Front Axle, 66600 lb Rears, Dana D46-170H Drive Axles, 4.10:1 Axle Ratio, 87000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 250 in Wheelbase, Hilark 19 ft Long x 4 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp, High-Lift Tailgate Usage: 161,549 Mi Notes: Being sold with previously salvaged title Lot closing time: Thu, Sep 17, 11:26 AM CDT Asset located in: Humble, TX, USA	2217A	2012 Peterbilt 367 10x4 Quad/A Dump Truck S/N: 1NPTL40X7CD158947 C/W: Located in Lane 33 Spot 36, Cummins ISX15 6 Cylinder Diesel 485 hp Engine, 2011 US EPA Label, 16736 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 270 in Wheelbase, PTO, 20 ft 7 in Long x 5 ft High Steel Body, Electric Roll Tarp Usage: 218,348 Mi Lot closing time: Thu, Sep 17, 11:26 AM CDT Asset located in: Humble, TX, USA
2216	2017 Mack GU713 10x4 Quad/A Dump Truck S/N: 1M2AX04C1HM034811 C/W: Located in Lane 44 Spot 15, Mack MP7 Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 248 in Wheelbase, 16 ft 6 in Long x 4 ft 3 in High Body, Round Bottom, Bed Vibrator, Electric Roll Tarp Usage: 273,350 Mi Lot closing time: Thu, Sep 17, 11:26 AM CDT Asset located in: Lake Worth, TX, USA	2218	2012 Mack CHU613 10x4 Quad/A Dump Truck S/N: 1M1AN07Y5CM009680 C/W: Located in Lane 33 Spot 40, Mack MP8 6 Cylinder 12.8 L Diesel 342 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Coolant Heater, 16205 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 38000 lb Rears, 23732 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Double Frame, Air Ride Suspension, 255 in Wheelbase, PTO, 18 ft Long x 4 ft 10 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: Not Available Lot closing time: Thu, Sep 17, 11:26 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2219	2014 Mack GU713 8x4 Tri/A Dump Truck S/N: 1M2AX07Y2EM020774 C/W: Located in Lane 100 Spot 8, Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack T310 10-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, 11R24.5, Steerable Air Lift Pusher Axle, Camelback Suspension, 220 in Wheelbase, 15 ft Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 712,174 Mi Notes: Selling with a Repossession affidavit and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 11:27 AM CDT Asset located in: Lake Worth, TX, USA	2224B	2017 Peterbilt 579 6x4 T/A Dump Truck S/N: 1XPBA48X0HD428863 C/W: Located in Lane 33 Spot 37, Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, Differential Lock, 12000 lb Front Axle, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 208 in Wheelbase, 15 ft Long x 4 ft 4 in High Steel Body, Manual Roll Tarp Usage: 241,900 Mi Lot closing time: Thu, Sep 17, 11:28 AM CDT Asset located in: Humble, TX, USA
2219A	2018 Mack CXU613 8x4 Tri/A Dump Truck S/N: 1M1AW02Y9JM089065 C/W: Located in Lane 33 Spot 43, 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDRIVE Automated Transmission, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Air Ride Suspension, 214 in Wheelbase, 16 ft Long x 5 ft High Steel Body, Round Bottom, Electric Roll Tarp, Pintle Hitch Usage: 226,155 Mi Lot closing time: Thu, Sep 17, 11:27 AM CDT Asset located in: Humble, TX, USA	2225	2015 Kenworth T680 6x4 T/A Dump Truck S/N: 1XKYDP9X3FJ465783 C/W: Located in Lane 44 Spot 25, Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 886 Engine hrs, Engine Brake, Eaton Fuller ADV Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X3 Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 186 in Wheelbase, PTO, 14 ft 6 in Long x 4 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 424,244 Mi Lot closing time: Thu, Sep 17, 11:28 AM CDT Asset located in: Lake Worth, TX, USA
2223	2011 Mack CXU613 8x4 Tri/A Dump Truck S/N: 1M1AW09YXBM013135 C/W: Located in Lane 33 Spot 45, Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2009 US EPA Label, 2476 Engine hrs, Engine Brake, Eaton Fuller ULTRASHIFT Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Lift Pusher Axle, Air Ride Suspension, 217 in Wheelbase, 17 ft Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 652,446 Mi Lot closing time: Thu, Sep 17, 11:27 AM CDT Asset located in: Humble, TX, USA	2226	2014 Freightliner M2 112 6x4 T/A Dump Truck S/N: 3ALAC4DVXEDFU8599 C/W: Located in Lane 44 Spot 10, Detroit DD13 6 Cylinder 12.8 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 13105 Engine hrs, Engine Brake, Eaton Fuller FRO-13210B 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RT-23-160 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Airliner Air Ride Suspension, 192 in Wheelbase, PTO, 14 ft 4 in Long x 4 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 48,256 Mi Notes: Odometer discrepancy-unit shows 48,256, title shows 425,368 Lot closing time: Thu, Sep 17, 11:28 AM CDT Asset located in: Lake Worth, TX, USA
2224A	2016 Peterbilt 365 6x4 T/A Dump Truck S/N: 1XPSD79XXGD263216 C/W: Located in Lane 33 Spot 38, Cummins ISX12 6 Cylinder Diesel 385 hp Engine, Requires Diesel Exhaust Fluid, 23578 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 158 in Wheelbase, 13 ft Long x 4 ft 5 in High Steel Body, Manual Roll Tarp Usage: 539,155 Mi Lot closing time: Thu, Sep 17, 11:28 AM CDT Asset located in: Humble, TX, USA	2228	2011 International 7400 6x4 T/A Dump Truck S/N: 1HTWGAAR9BJ330860 C/W: Located in Lane 25 Spot 2, Phoenix 6 Cylinder 7.6 L Compressed Natural Gas (CNG) 300 hp Engine, 2010 US EPA Label, 4040 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 198 in Wheelbase, PTO, Galion-Godwin 13 ft 6 in Long x 4 ft 1 in High Steel Body, Manual Roll Tarp, Pintle Hitch Usage: 54,424 Mi Lot closing time: Thu, Sep 17, 11:29 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2230A	2003 Kenworth T300 6x4 T/A Dump Truck S/N: 2NKMLZ9X63M899742 C/W: Located in Lane 33 Spot 44, Cummins ISC 6 Cylinder 8.3 L Diesel Engine, Eaton Fuller 8LL Manual Transmission, Aluminum Front Wheels, 11R22.5, Chalmers Rubber Suspension, 180 in Wheelbase, 14 ft Long x 3 ft 10 in High Steel Body, Electric Roll Tarp Usage: 518,533 Mi Lot closing time: Thu, Sep 17, 11:29 AM CDT Asset located in: Humble, TX, USA	2234	1997 Mack CH613 6x4 T/A Dump Truck S/N: 1M1AA13Y0VW072913 C/W: Located in Lane 33 Spot 39, Mack E7 6 Cylinder 12 L Diesel 350 hp Engine, 5351 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12860 lb Front Axle, 38000 lb Rears, Air Ride Cab, Aluminum Wheels, 11R24.5, Camelback Suspension, 230 in Wheelbase, PTO, Colt 15 ft 4 in Long x 5 ft High Steel Body, Round Bottom, Electric Roll Tarp, Air High-Lift Tailgate, Pintle Hitch Usage: 652,136 Mi Notes: Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 11:30 AM CDT Asset located in: Humble, TX, USA
2231	2007 Mack CV713 6x4 T/A Dump Truck S/N: 1M2AG11C27M059175 C/W: Located in Lane 44 Spot 24, Mack AI 11.9 L Diesel 427 hp Engine, 2000 US EPA Label, 21177 Engine hrs, Engine Brake, Mack Maxitorque T310 10-Speed Manual Transmission, 18000 lb Front Axle, 44000 lb Rears, 62000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Camelback Spring Suspension, 220 in Wheelbase, PTO, OX Bodies 16 ft Long x 4 ft High Body, 19 cyd, Capacity, Electric Roll Tarp, Rear Hydraulics, Pintle Hitch Usage: 282,110 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:29 AM CDT Asset located in: Lake Worth, TX, USA	2235	1984 Mack R686ST 6x4 T/A Dump Truck S/N: 1M2N179Y2EA085991 C/W: Mack Diesel Engine, 817 Engine hrs, Manual Transmission, Aluminum Front Wheels, 11R24.5, Double Frame, Spring Suspension, 190 in Wheelbase, PTO, DAVIS 13 ft Long x 3 ft 10 in High Steel Body, Electric Roll Tarp Usage: 516,235 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 11:30 AM CDT Asset located in: San Antonio, TX, USA
2231A	2004 Mack CV713 6x4 T/A Dump Truck S/N: 1M2AG12C54M014578 C/W: Mack 6 Cylinder Diesel 300 hp Engine, Allison Automatic Transmission, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Camelback Spring Suspension, 190 in Wheelbase, PTO, 13 ft 4 in Long x 3 ft 8 in High Body, Electric Roll Tarp Usage: Not Available Lot closing time: Thu, Sep 17, 11:29 AM CDT Asset located in: Lake Worth, TX, USA	2236	1984 Peterbilt 359 6x4 T/A Dump Truck S/N: 1XP9D29X5EP171931 C/W: Cat 6 Cylinder 12.6 L Diesel Engine, 1989 US EPA Label, 10-Speed Manual Transmission, Aluminum Outer Wheels, 11R24.5, Spring Suspension, PTO, 15 ft Long x 3 ft 8 in High Steel Body, Electric Roll Tarp, Pintle Hitch Usage: 535,481 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 11:30 AM CDT Asset located in: San Antonio, TX, USA
2233	1993 Western Star 4864F 6x4 T/A Dump Truck S/N: 2WLNCCBE8PK930869 C/W: Located in Lane 44 Spot 17, Cat 3306 6 Cylinder 10.5 L Diesel Engine, Eaton Fuller 8-Speed Manual Transmission, 58000 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Hendrickson Rubber over Walking Beam Suspension, 218 in Wheelbase, PTO, 15 ft 8 in Long x 4 ft 2 in High Body Usage: 251,044 Mi Notes: Title is branded: Not actual mileage. Lot closing time: Thu, Sep 17, 11:30 AM CDT Asset located in: Lake Worth, TX, USA	2237	2020 Ram 5500 4x4 S/A Dump Truck S/N: 3C7WRNBLXLG200617 C/W: Located in Lane 44 Spot 2, Cummins B6.7 6.7 L Diesel 360 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10486 Engine hrs, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, CM 11 ft Long x 0 ft 17 in High Steel Body, Manual Roll Tarp, Equipment-from-a-Primoris-Services-Corp-company Usage: 129,702 Mi Lot closing time: Thu, Sep 17, 11:31 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2238	2007 International 7400 SFA 4x2 Crew Cab S /A Dump Truck S/N: 1HTWDAAR47J427190 C/W: Located in Lane 33 Spot 26, International 6 Cylinder 7.6 L Diesel Engine, 10397 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 23000 lb Rears, 36220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Spring Suspension, 221 in Wheelbase, PTO, 10 ft Long x 2 ft 10 in High Aluminium Body, Electric Roll Tarp, Pintle Hitch Usage: Not Available Lot closing time: Thu, Sep 17, 11:31 AM CDT Asset located in: Humble, TX, USA	2242A	2007 Ford F-750 XL 4x2 S/A Dump Truck S/N: 3FRWF75F97V433321 C/W: Located in Lane 24 Spot 20, Cummins ISB 6 Cylinder 5.9 L Diesel 230 hp Engine, 2006 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, Aluminum Outer Wheels, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, 10 ft Long x 3 ft High Body, Manual Roll Tarp Usage: 197,672 Mi Lot closing time: Thu, Sep 17, 11:32 AM CDT Asset located in: Humble, TX, USA
2239	2005 Ford F-750 4x2 S/A Dump Truck S/N: 3FRPF75Y25V112143 C/W: Located in Lane 44 Spot 4, V8 Diesel Engine, 5-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 31000 lb GVWR, 10R22.5, Spring Suspension, 160 in Wheelbase, 10 ft Long x 3 ft 2 in High Body Usage: 123,685 Mi Lot closing time: Thu, Sep 17, 11:31 AM CDT Asset located in: Lake Worth, TX, USA	2244	1996 Ford F800 4x2 S/A Dump Truck S/N: 1FDXF80C6TVA29754 C/W: Located in Lane 45 Spot 2, Cummins B5. 9-230 6 Cylinder 5.9 L Diesel 230 hp Engine, 1996 US EPA Label, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 30000 lb GVWR, 11R22.5, Spring Suspension, 153 in Wheelbase, PTO, 10 ft Long x 3 ft 7 in High Steel Body, Pintle Hitch Usage: 169,195 Mi Lot closing time: Thu, Sep 17, 11:32 AM CDT Asset located in: Lake Worth, TX, USA
2240	1995 International Paystar 5000 4x2 S/A Dump Truck S/N: 1HTSDAAN6SH623806 C/W: Located in Lane 44 Spot 5, Navistar 6 Cylinder 7.6 L Diesel Engine, 1994 US EPA Label, International 6 Plus 7-Speed Manual Transmission, 11R22.5, Air Ride Suspension, 158 in Wheelbase, 10 ft Long x 3 ft 10 in High Body, High-Lift Tailgate Usage: 175,423 Mi Lot closing time: Thu, Sep 17, 11:31 AM CDT Asset located in: Lake Worth, TX, USA	2245	2019 Peterbilt 348 6x4 Flatbed Truck S/N: 2NP3LJ0X2KM618765 C/W: Located in Lane 17 Spot 19, Paccar PX-9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10188 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 14600 lb Front Axle, 44000 lb Rears, Meritor MT-44-14X Drive Axles, 4.88:1 Axle Ratio, 58600 lb GVWR, Aluminum Front Wheels, 315 /80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 278 in Wheelbase, 20 ft x 98 in Bed Usage: 261,033 Mi Lot closing time: Thu, Sep 17, 11:33 AM CDT Asset located in: Humble, TX, USA
2241	2009 Sterling L7500 4x2 S/A Dump Truck S/N: 2FZAATDJ39AAH6045 C/W: Located in Lane 33 Spot 47, Mercedes-Benz MBE-900 6 Cylinder 7.2 L Diesel Engine, 694 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 23000 lb Rears, 35000 lb GVWR, Aluminum Outer Wheels, 12R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 246 in Wheelbase, 10 ft Long x 3 ft 6 in High Steel Body Usage: 99,968 Mi Lot closing time: Thu, Sep 17, 11:32 AM CDT Asset located in: Humble, TX, USA	2246A	2016 Kenworth T400 6x4 Flatbed Truck S/N: 3BKBLJ0X7GF109768 C/W: Located in Lane 17 Spot 28, 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 4564 Engine hrs, Engine Brake, Allison 3000 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 3.58:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Spring Suspension, 252 in Wheelbase, 24 ft x 96 in Bed, Forklift Mount Kit Usage: 139,797 Mi Notes: Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 11:33 AM CDT Asset located in: Humble, TX, USA
2242	2002 Freightliner FL 70 4x2 S/A Dump Truck S/N: 1FVABTBS22HK96162 C/W: Located in Lane 44 Spot 3, Cummins 6 Cylinder Diesel Engine, Automatic Transmission, 11R22.5, Spring Suspension, 153 in Wheelbase, PTO, 10 ft Long x 3 ft 4 in High Body, Manual Roll Tarp Usage: 177,011 Mi Lot closing time: Thu, Sep 17, 11:32 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2249	2014 Kenworth T370 6x4 Flatbed Truck S/N: 2NKHLLJ9X6EM419205 C/W: Paccar PX-9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 14947 Engine hrs, Engine Brake, Allison 3000 Automatic Transmission, 14600 lb Front Axle, 40000 lb Rears, 5.29:1 Axle Ratio, 54600 lb GVWR, Aluminum Front Wheels, 315 /80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Paccar Air Ride Suspension, 295 in Wheelbase, 25 ft x 96 in Bed, Forklift Mount Kit Usage: 323,588 Mi Lot closing time: Thu, Sep 17, 11:34 AM CDT Asset located in: Livingston, LA, USA	2255	2015 Freightliner M2 106 4x2 Flatbed Truck S/N: 1FVACWUDU3FHGA2335 C/W: Located in Lane 17 Spot 20, Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 6335 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, Detroit DA-RS-20.0-4 Drive Axles, 5.88:1 Axle Ratio, 26000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 270 in Wheelbase, 24 ft x 96 in Bed Usage: 186,749 Mi Lot closing time: Thu, Sep 17, 11:35 AM CDT Asset located in: Humble, TX, USA
2250	2009 Freightliner M2 106 6x4 Flatbed Truck S/N: 1FVHCYBS99HAH1500 C/W: Located in Lane 17 Spot 21, Cummins ISC 6 Cylinder Diesel 330 hp Engine, 13286 Engine hrs, Eaton Fuller FRO-12210C 10-Speed Manual Transmission, 14600 lb Front Axle, 36000 lb Rears, Meritor RT-40-145 Drive Axles, 3.73:1 Axle Ratio, 50600 lb GVWR, 295/75R22.5, Spring Suspension, 274 in Wheelbase, 24 ft x 96 in Bed, Forklift Mount Kit Usage: 337,580 Mi Lot closing time: Thu, Sep 17, 11:34 AM CDT Asset located in: Humble, TX, USA	2256	2013 Peterbilt 348 6x4 Sleeper Flatbed Truck S/N: 2NP3LN9X0DM188215 C/W: Located in Lane 36 Spot 41, Paccar PX-8 Diesel Engine, Requires Diesel Exhaust Fluid, 3149 Engine hrs, Engine Brake, Allison 3000 Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 6.17:1 Axle Ratio, 54600 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 425/65R22.5 Super Singles Rear Tires, Double Frame, Air Trac Air Ride Suspension, 293 in Wheelbase, 25 ft x 92 in Bed Usage: 99,078 Mi Lot closing time: Thu, Sep 17, 11:35 AM CDT Asset located in: Humble, TX, USA
2251	2008 Kenworth T-300 6x2 Flatbed Truck S/N: 2NKMHN7X48M225254 C/W: Located in Lane 25 Spot 11, Cummins ISC 6 Cylinder 8.3 L Diesel 260 hp Engine, 2007 US EPA Label, 11993 Engine hrs, Engine Brake, Allison Automatic Transmission, 12000 lb Front Axle, 41000 lb Rears, 53000 lb GVWR, Steel, 11R22.5, Air Lift Pusher Axle, Air Ride Suspension, 168 in Wheelbase, 15 ft 0 in x 92 in Bed, Hydraulic Hoist Usage: 245,477 Mi Lot closing time: Thu, Sep 17, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	2257	2013 Peterbilt 337 4x2 Flatbed Truck S/N: 2NP2HN6X6DM205374 C/W: Paccar PX-8 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-11210C 10-Speed Manual Transmission, 10000 lb Front Axle, 17000 lb Rears, 4.33:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 168 in Wheelbase, 11 ft 5 in x 102 in Bed Usage: 206,150 Mi Lot closing time: Thu, Sep 17, 11:35 AM CDT Asset located in: Midland, TX, USA
2252	2002 Peterbilt 357 6x4 Flatbed Truck S/N: 1NPAXUTX22N585405 C/W: Located in Lane 11 Spot 24, Cat C12 6 Cylinder 11.9 L Diesel 505 hp Engine, 2002 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 18740 lb Front Axle, 63000 lb Rears, 81740 lb GVWR, Air Ride Cab, 385 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring over Walking Beam Suspension, 282 in Wheelbase, 23 ft 9 in x 96 in Bed Usage: 481,137 Mi Lot closing time: Thu, Sep 17, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	2258	2011 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAL1BH325249 C/W: Located in Lane 17 Spot 29, Navistar 7.6 L Diesel 225 hp Engine, 2009 US EPA Label, 6787 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 201 in Wheelbase, 19 ft x 96 in Bed, Winch, Liftgate Usage: 206,345 Mi Lot closing time: Thu, Sep 17, 11:36 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2259	2008 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAL68H552557 C/W: Located in Lane 17 Spot 22, International Diesel Engine, Engine Coolant Heater, Engine Coolant Heater, 10282 Engine hrs, Eaton Fuller 6-Speed Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 228 in Wheelbase, 20 ft 6 in x 100 in Bed, Liftgate Usage: 281,038 Mi Lot closing time: Thu, Sep 17, 11:36 AM CDT Asset located in: Humble, TX, USA	2265A	2019 Ford F-550 XL 4x4 Flatbed Truck S/N: 1FDUF5HT1KDA06327 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 145 in Wheelbase, 9 ft 5 in x 90 in Bed Usage: 204,666 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
2261	2015 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF6HD7FV798563 C/W: Located in Lane 11 Spot 23, V10 6.8 L Gasoline Engine, 2015 US EPA Label, 6788 Engine hrs, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 218 in Wheelbase, 16 ft 2 in x 96 in Bed Usage: 54,050 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:36 AM CDT Asset located in: Lake Worth, TX, USA	2267	2011 Ford F-550 XL 4x4 Extended Cab Flatbed Truck S/N: 1FD0X5HT1BEA74116 C/W: Located in Lane 17 Spot 3, V8 6.7 L Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft 6 in x 96 in Bed Usage: 159,043 Mi Lot closing time: Thu, Sep 17, 11:38 AM CDT Asset located in: Humble, TX, USA
2262	2007 Ford F-650 4x2 Flatbed Truck S/N: 3FRNF65V97V400820 C/W: Located in Lane 11 Spot 26, Cummins ISB 275 6 Cylinder 5.9 L Diesel 275 hp Engine, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 245 /70R19.5, Air Ride Suspension, 158 in Wheelbase, 11 ft 2 in x 97 in Bed Usage: 149,232 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:37 AM CDT Asset located in: Lake Worth, TX, USA	2268	2019 Ford F-450 XL 4x4 Flatbed Truck S/N: 1FDUF4HT6KEF71368 C/W: Located in Lane 17 Spot 6, 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 169 in Wheelbase, 12 ft 7 in x 96 in Bed, Liftgate, Stake Side Usage: 80,433 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:38 AM CDT Asset located in: Humble, TX, USA
2264A	2003 Chevrolet C6500 4x2 Flatbed Truck S/N: 1GBG6E1C83F518950 C/W: Located in Lane 17 Spot 24, Cat 6 Cylinder Diesel Engine, 6-Speed Manual Transmission, 7000 lb Front Axle, 15000 lb Rears, 22000 lb GVWR, 245/70R19.5, Spring Suspension, 153 in Wheelbase, 11 ft 6 in x 86 in Bed Usage: 202,119 Mi Lot closing time: Thu, Sep 17, 11:37 AM CDT Asset located in: Humble, TX, USA	2268A	2018 Ford F-450 XL 4x4 Flatbed Truck S/N: 1FDUF4HY5JEC14225 C/W: Located in Lane 17 Spot 1, Ford V10 6.8 L Gasoline Engine, 2018 US EPA Label, 9828.5 Engine hrs, Automatic Transmission, 6500 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 171 in Wheelbase, 12 ft Body Usage: 190,512 Mi Lot closing time: Thu, Sep 17, 11:38 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2268B	2021 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT2MED56469 C/W: Ford Power stroke V8 6.7 cid Diesel Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Ford 10-Speed Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75-r17, Ford Spring Suspension, 186 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 147,161 Mi Lot closing time: Thu, Sep 17, 11:38 AM CDT Asset located in: Midland, TX, USA	2273A	2022 Ram 2500 4x4 Crew Cab Flatbed Truck S/N: 3C6UR5HJ1NG249564 C/W: Chrysler V8 6.4 L Gasoline Engine, Chrysler Automatic Transmission, 5500 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 275 /70r18 Front Tires, 275/70r18 Rear Tires, Chrysler Spring Suspension, 175 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 191,067 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 11:39 AM CDT Asset located in: Midland, TX, USA
2269	2020 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT4LED98138 C/W: Ford V8 6.7 L Diesel Engine, 2020 US EPA Label, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 179 in Wheelbase, 9 ft x 96 in Bed Usage: 197,856 Mi Lot closing time: Thu, Sep 17, 11:38 AM CDT Asset located in: Midland, TX, USA	2273B	2012 Ford F-250 XL 4x4 Crew Cab Flatbed Truck S/N: 1FT7W2B68CEA96803 C/W: Located in Lane 11 Spot 9, Ford V8 6.2 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 235/70R17, Spring Suspension, 172 in Wheelbase, 8 ft x 86 in Bed, Fuel Tank Usage: 298,328 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:39 AM CDT Asset located in: Lake Worth, TX, USA
2269A	2014 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL2EG298855 C/W: Cummins B 6 Cylinder 6.7 cid Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Chrysler 6-Speed Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, Chrysler Drive Axles, 14000 lb GVWR, 265/70r17 Front Tires, 265/70r17 Rear Tires, Chrysler Spring Suspension, 174 in Wheelbase, 9 ft 4 in x 94 in Bed Usage: 356,735 Mi Lot closing time: Thu, Sep 17, 11:38 AM CDT Asset located in: Midland, TX, USA	2274	2019 Ford F-550 4x2 Crew Cab Flatbed Truck S/N: 1FD0W5GT5KEE76483 C/W: Located in Lane 11 Spot 6, V8 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 203 in Wheelbase, 11 ft 4 in x 96 in Bed, Fuel Tank /w Pump Usage: 234,625 Mi Notes: Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:39 AM CDT Asset located in: Lake Worth, TX, USA
2270	2012 Dodge Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C63DRGL3CG341048 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2012 US EPA Label, Automatic Transmission, 5500 lb Front Axle, 9350 lb Rears, 12300 lb GVWR, 235/80R17, Spring Suspension, 169 in Wheelbase, 8 ft 6 in x 96 in Bed, Ball Hitch Usage: 388,074 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 11:38 AM CDT Asset located in: San Antonio, TX, USA	2274A	2019 Ford F-550 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD0W5GT7KED70813 C/W: Located in Lane 11 Spot 6, Ford Power Stroke V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft 4 in x 91 in Bed, Fuel Tank /w Pump, Receiver, Fifth wheel ball Usage: 185,078 Mi Notes: Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:39 AM CDT Asset located in: Lake Worth, TX, USA
2271	2019 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KVCGL1KF123103 C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 245/75R17, Spring Suspension, 168 in Wheelbase, 9 ft 4 in x 96 in Bed Usage: 246,674 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 11:39 AM CDT Asset located in: San Antonio, TX, USA		

Lot #	Details	Lot #	Details
2275	2013 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT1DEB63807 C/W: V8 6.7 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 164 in Wheelbase, 11 ft x 90 in Bed Usage: 236,231 Mi Lot closing time: Thu, Sep 17, 11:40 AM CDT Asset located in: Lake Worth, TX, USA	2280	2016 Ford F-250 4x2 Flatbed Truck S/N: 1FDBF2A64GEC17999 C/W: Located in Lane 11 Spot 1, V8 6.2 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6290 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 199,092 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. ; Job Completion Fleet Realignment for Heavy Highway Joint Venture. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:41 AM CDT Asset located in: Lake Worth, TX, USA
2277	2008 Chevrolet W5500HD 4x2 Flatbed Truck S/N: J8BE5W16187300105 C/W: Located in Lane 17 Spot 12, Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 200 hp Engine, 2007 US EPA Label, Chevrolet Automatic Transmission, 6830 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5 Front Tires, 255/70R19.5 Rear Tires, Spring Suspension, 138 in Wheelbase, 14 ft x 96 in Bed Usage: 145,999 Mi Lot closing time: Thu, Sep 17, 11:40 AM CDT Asset located in: Humble, TX, USA	2280A	1951 GMC 4x2 Classic Flatbed Truck S/N: 25322P3278 C/W: Located in Lane 46 Spot 0, Chevrolet 6 Cylinder Gasoline 90 hp Engine, Manual Transmission, 8800 lb GVWR, 7.00-18, Spring Suspension, 132 in Wheelbase, 9 ft 4 in x 94 in Bed, Pintle Hitch Usage: 8,132 Mi Lot closing time: Thu, Sep 17, 11:41 AM CDT Asset located in: Humble, TX, USA
2278	2013 Ford F-450 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD0W4GY1DEA43204 C/W: Located in Lane 83 Spot 0, V10 6.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 5200 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 245/70R19.5, Spring Suspension, 176 in Wheelbase, 10 ft x 96 in Bed Usage: 77,224 Mi Notes: This unit is being sold with a bonded title. Buyers in the state of LA -bonded titles will not be accepted in your state. Lot closing time: Thu, Sep 17, 11:40 AM CDT Asset located in: Humble, TX, USA	2281	2018 Ford F-650 4x2 Hooklift Truck S/N: 1FDNF6DC4JDF04763 C/W: Located in Lane 36 Spot 12, V8 6.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Aluminum Outer Wheels, 255/70R22.5, Spring Suspension, 196 in Wheelbase, Titan C series Roll-Off Body, 16 ft Hoist, Winch, Pintle Hitch Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:41 AM CDT Asset located in: Humble, TX, USA
2279	2019 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3G68KEG80082 C/W: Located in Lane 17 Spot 10, V8 6.2 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 5000 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R19.5, Spring Suspension, 182 in Wheelbase, 9 ft x 96 in Bed, Liftgate Usage: 159,798 Mi Lot closing time: Thu, Sep 17, 11:41 AM CDT Asset located in: Humble, TX, USA	2282	2014 Freightliner M2 106 4x2 Hooklift Truck S/N: 1FVACXCY9EHBX6065 C/W: Located in Lane 36 Spot 42, Cummins 6 Cylinder 8.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 17630 Engine hrs, Allison Automatic Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, PTO, 2013 Galbreath Right Hook Roll-Off Body Usage: 360,632 Mi Notes: This unit is being sold with a rebuilt salvage title. Lot closing time: Thu, Sep 17, 11:41 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2283	2007 Mack Granite CV713 6x4 Roll-Off Truck S/N: 1M2AG11C57M067545 C/W: Located in Lane 36 Spot 15, Mack AMI 11.9 L Diesel Engine, 372804 Engine hrs, Mack Maxitorque ES 10-Speed Manual Transmission, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 266 in Wheelbase, PTO, 2007 Galbreath U5-I0-174 Roll-Off Body, Outside Rail, 22 ft 1 in Hoist Usage: 665,868 Mi Lot closing time: Thu, Sep 17, 11:41 AM CDT Asset located in: Humble, TX, USA	2289	2020 Freightliner 114SD 4000 gal 6x4 Fuel Truck S/N: 1FVHG3DV6LHLY4592 C/W: Located in Lane 9 Spot 3, Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12644 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Airliner Air Ride Suspension, 260 in Wheelbase, PTO, Progress A10LS 5000 5000 gal Aluminum Tank, TC406 Code, Hydraulic Driven Pump, 1 Reels Usage: 244,349 Mi Lot closing time: Thu, Sep 17, 11:43 AM CDT Asset located in: Lake Worth, TX, USA
2286	2016 International WorkStar 7500 6x4 Rear Loader Waste Collection Truck S/N: 1HTWGSTR4GH373570 C/W: Located in Lane 36 Spot 9, 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10180 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Chalmers Rubber Suspension, 187 in Wheelbase, McNeilus 25 cyd Capacity Collection Body Usage: 61,290 Mi Lot closing time: Thu, Sep 17, 11:42 AM CDT Asset located in: Humble, TX, USA	2291	2005 Kenworth T800 2000 gal 6x4 Fuel and Lube Truck S/N: 1NKDL50XX5R091489 C/W: Located in Lane 9 Spot 1, Cummins ISL 6 Cylinder 8.8 L Diesel 350 hp Engine, 2004 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 238 in Wheelbase, PTO, 2000 gal Diesel Tank, (8) Hose Reels, Grease Barrel, Hydraulic Air Compressor, Air Hose Reel Usage: 36,217 Mi Lot closing time: Thu, Sep 17, 11:43 AM CDT Asset located in: Lake Worth, TX, USA
2287	2014 International WorkStar 7400 6x4 Rear Loader Waste Collection Truck S/N: 3HAWGAZT0EL060892 C/W: Located in Lane 36 Spot 10, 6 Cylinder Diesel Engine, 2013 US EPA Label, Allison Automatic Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, 11R22.5, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 231 in Wheelbase Usage: 60,324 Mi Lot closing time: Thu, Sep 17, 11:42 AM CDT Asset located in: Humble, TX, USA	2292	2008 Peterbilt 340 6x4 Fuel and Lube Truck S/N: 2NPRLN0X08M755780 C/W: Located in Lane 9 Spot 2, Cummins ISC 6 Cylinder 8.3 L Diesel Engine, Eaton Fuller FR011210C 10-Speed Manual Transmission, Differential Lock, 20000 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 4.88:1 Axle Ratio, 60000 lb GVWR, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 216 in Wheelbase, 1500 gal Diesel Tank, Ingersoll-Rand 2475 Hydraulic Air Compressor Usage: 11,412 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:44 AM CDT Asset located in: Lake Worth, TX, USA
2288	2014 International WorkStar 7400 6x4 Rear Loader Waste Collection Truck S/N: 3HAWGAZT9EL060891 C/W: Located in Lane 36 Spot 8, 6 Cylinder Diesel Engine, 2013 US EPA Label, Allison Automatic Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, 11R22.5, Dual Steering Boxes, Hendrickson Haulmaax Rubber Suspension, 228 in Wheelbase, McNeilus 25 cyd Capacity Collection Body Usage: 65,888 Mi Lot closing time: Thu, Sep 17, 11:43 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2292A	2000 Sterling L7500 4x2 Fuel and Lube Truck S/N: 2FZHAJBB3YAF12846 C/W: Located in Lane 16 Spot 27, Cat 3126 6 Cylinder Diesel 300 hp Engine, 12397 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 23000 lb Rears, 35000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 226 in Wheelbase, 16 ft Body, 1000 gal Diesel Tank, (3) 50 gal Oil Tanks, (4) Hose Reels, Grease Barrel, Central Pneumatic Gasoline Air Compressor, Air Hose Reel Usage: 138,352 Mi Lot closing time: Thu, Sep 17, 11:44 AM CDT Asset located in: Humble, TX, USA	2296	2018 Freightliner Cascadia 125 4000 gal 6x4 Water Truck S/N: 3AKJGEDV4JSJN7059 C/W: Located in Lane 16 Spot 32, Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-OB-1650 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.07:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 200 in Wheelbase, PTO, 4000 gal Steel Tank, Hydraulic Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 553,959 Mi Lot closing time: Thu, Sep 17, 11:44 AM CDT Asset located in: Humble, TX, USA
2293	2001 Sterling M7500 4x2 Fuel and Lube Truck S/N: 2FZAAKAK01AG92379 C/W: Located in Lane 9 Spot 3, Cat 3126 6 Cylinder 7.2 L Diesel Engine, 7645.6 Engine hrs, Eaton Fuller 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 192 in Wheelbase, South West Products 13 ft 6 in Body, Metered Nozzles, Grease Barrel, Mega Gasoline Air Compressor, Air Hose Reel Usage: 164,936 Mi Lot closing time: Thu, Sep 17, 11:44 AM CDT Asset located in: Lake Worth, TX, USA	2297	2018 Freightliner Cascadia 125 6x4 Water Truck S/N: 3AKJGEDV5JSJN7085 C/W: Located in Lane 16 Spot 35, Detroit DD13 12.8 L Diesel 410 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 510151 Engine hrs, 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit Drive Axles, 3.07:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Tiger Steel Tank, Hydraulic Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 510,151 Mi Notes: Water Tank Bodies were installed New in 2024 Lot closing time: Thu, Sep 17, 11:45 AM CDT Asset located in: Humble, TX, USA
2294A	1998 Freightliner FL 70 1200 gal 4x2 Extended Cab Fuel and Lube Truck S/N: 1FV6HJBCXWH946198 C/W: Located in Lane 9 Spot 5, Cat C7 6 Cylinder 7.2 L Diesel 300 hp Engine, 1997 US EPA Label, 9877.1 Engine hrs, Allison Automatic Transmission, 8000 lb Front Axle, 17640 lb Rears, 25640 lb GVWR, 295/75R22.5, Spring Suspension, 176 in Wheelbase, 12 ft Body, 1200 gal Diesel Tank, (2) Hose Reels, Grease Barrel Usage: Not Available Lot closing time: Thu, Sep 17, 11:44 AM CDT Asset located in: Lake Worth, TX, USA	2297A	2011 Peterbilt 384 4000 gal 6x4 Water Truck S/N: 1XPVD09X5BD116346 C/W: Located in Lane 16 Spot 29, Cummins ISM 6 Cylinder 10.8 L Diesel Engine, 12195 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 230 in Wheelbase, PTO, 4000 gal Steel Tank, ATP Hydraulic Driven Pump, 7 ft 9 in, Spray Bar, Rear Spray, Side Spray Usage: 495,621 Mi Lot closing time: Thu, Sep 17, 11:45 AM CDT Asset located in: Humble, TX, USA
2295	2004 Chevrolet C4500 4x2 Fuel and Lube Truck S/N: 1GBE4C1104F502243 C/W: Located in Lane 9 Spot 4, GM 6.6 L Diesel Engine, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 265 /70R19.5, Spring Suspension, 154 in Wheelbase, Royal 12 ft Body, Grease Barrel, Oil Recovery System, Champion Gasoline Air Compressor Usage: 123,070 Mi Lot closing time: Thu, Sep 17, 11:44 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2298	2016 Cat CT660 4000 gal 6x4 Water Truck S/N: 3HTJGKT8GN003452 C/W: Cat A475 6 Cylinder 12.4 L Diesel 475 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4850 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Hendrickson Air Ride Suspension, 207 in Wheelbase, PTO, Mega MOH4 4000 gal Steel Tank, Mega Hydraulic Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 31,398 Mi Lot closing time: Thu, Sep 17, 11:45 AM CDT Asset located in: Lake Worth, TX, USA	2303A	2023 Mack MD624R 4x2 Water Truck S/N: 1M2MDAAB0PS071673 C/W: Located in Lane 10 Spot 22, Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 1113.0 Engine hrs, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 25995 lb GVWR, 11R22.5, Spring Suspension, 150 in Wheelbase, PTO, Valew Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 1,890 Mi Lot closing time: Thu, Sep 17, 11:46 AM CDT Asset located in: Lake Worth, TX, USA
2300	2020 Freightliner M2 106 6x4 Water Truck S/N: 1FVHCYFE6LHLT2479 C/W: Located in Lane 16 Spot 28, Cummins L9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6688 Engine hrs, Allison Automatic Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, TufTrac Spring Suspension, 188 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 7 ft 2 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray, Street Flusher Usage: 41,810 Mi Lot closing time: Thu, Sep 17, 11:45 AM CDT Asset located in: Humble, TX, USA	2304	2021 Freightliner M2 106 2250 gal 4x2 Water Truck S/N: 3ALACXFCXMDMN9947 C/W: Located in Lane 10 Spot 7, Cummins B6.7 6 Cylinder 6.7 L Diesel 280 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 6212 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Detroit DA-RS-21.0-4 Drive Axles, 6.14:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, PTO, Lands 2250 gal Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Self-Loading With Primer Pumps, Lands Unused Powder Coated Usage: 227,862 Mi Notes: The closing times of lots 2304 thru 2305 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Thu, Sep 17, 11:46 AM CDT Asset located in: Lake Worth, TX, USA
2300A	2014 Freightliner M2 106 6x4 Water Truck S/N: 3ALHCYCY7EDFW5751 C/W: Located in Lane 10 Spot 17, Cummins ISL 6 Cylinder 8.9 L Diesel 300 hp Engine, 2014 US EPA Label, 14146 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, TufTrac Spring Suspension, 208 in Wheelbase, PTO, Niece WT 4000 4000 gal Tank, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 107,616 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:46 AM CDT Asset located in: Lake Worth, TX, USA	2305	2019 Freightliner M2 106 2000 gal 4x2 Water Truck S/N: 3ALACXFC4KDLH8015 C/W: Located in Lane 10 Spot 10, Cummins B6.7 260 6 Cylinder 6.7 L Diesel 260 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5436 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Detroit DA-RS-21.0-4 Drive Axles, 5.56:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 156 in Wheelbase, PTO, Lands Used Trucks And Fabrication 2000 gal Tank, PTO Driven Pump, 5 ft 4 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray, Self-Loading w/ Primer Pumps Usage: 176,263 Mi Notes: The closing times of lots 2304 thru 2305 are tied together. If a bid is received, then a time extension will be applied to all lots. Once the time closes, the high bidder on each lot will be the winner. Lot closing time: Thu, Sep 17, 11:47 AM CDT Asset located in: Lake Worth, TX, USA
2301	2011 Freightliner M2 106 6x4 Water Truck S/N: 1FVHCYBS8BDAY9794 C/W: Located in Lane 10 Spot 18, Paccar PX-8 8.3 L Diesel 350 hp Engine, 11437.1 Engine hrs, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 315/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 198 in Wheelbase, PTO, 2011 Iedwell LW4000 WT 4000 gal Steel Tank, PTO Driven Pump, 8 ft 4 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 327,460 Mi Lot closing time: Thu, Sep 17, 11:46 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2306	2020 International MV607 2000 gal 4x2 Water Truck S/N: 3HAEUMMN1LL308384 C/W: Located in Lane 10 Spot 5, Cummins B6. 7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 4043 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Land's Unused Powder Coated 2000 gal Tank, PTO Driven Pump, 5 ft 6 in, Spray Bar, Front Spray, Rear Spray, Side Spray, Self-Loading With Primer Pumps Usage: 169,079 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 11:47 AM CDT Asset located in: Lake Worth, TX, USA	2315	2009 Ford F-750 XL 2000 gal 4x2 Water Truck S/N: 3FRWF75BX9V131097 C/W: Located in Lane 10 Spot 20, Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2008 US EPA Label, 6-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, 2010 Niece WT2000 2000 gal Tank, PTO Driven Pump, 0 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 84,254 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:49 AM CDT Asset located in: Lake Worth, TX, USA
2310	2015 Ford F-750 4x2 Water Truck S/N: 3FRWF7FC4FV667790 C/W: Located in Lane 10 Spot 2, Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, PTO Driven Pump, 0 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 43,061 Mi Lot closing time: Thu, Sep 17, 11:48 AM CDT Asset located in: Lake Worth, TX, USA	2316	2008 Ford F-750 4x2 Water Truck S/N: 3FRNF75N38V658662 C/W: Located in Lane 10 Spot 9, Cat C7 7.2 L Diesel 360 hp Engine, 2007 US EPA Label, 6-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, Poly Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 24,054 Mi Lot closing time: Thu, Sep 17, 11:49 AM CDT Asset located in: Lake Worth, TX, USA
2312	2013 Ford F-750 XL 2000 gal 4x2 Water Truck S/N: 3FRNF7FA4DV775012 C/W: Located in Lane 16 Spot 37, Cummins ISB6.7 6.7 L 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, WT2000 2000 gal Steel Tank, . PTO Driven Pump, 6 ft 9 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 22,622 Mi Lot closing time: Thu, Sep 17, 11:48 AM CDT Asset located in: Humble, TX, USA	2316A	2006 Ford F-750 4x2 Water Truck S/N: 3FRWF75G66V368015 C/W: Located in Lane 10 Spot 26, Cummins ISB 5.9 L Diesel 245 hp Engine, 2006 US EPA Label, 7-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray Usage: 21,937 Mi Lot closing time: Thu, Sep 17, 11:49 AM CDT Asset located in: Lake Worth, TX, USA
2313	2012 Ford F-750 XL 4x2 Water Truck S/N: 3FRWF7FL8CV442414 C/W: Located in Lane 16 Spot 33, Cummins ISB 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 192 in Wheelbase, PTO, Circle D M-2000 2000 gal Steel Tank, Hydraulic Driven Pump, 7 ft 2 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 11,184 Mi Lot closing time: Thu, Sep 17, 11:48 AM CDT Asset located in: Humble, TX, USA	2317	2007 Ford F-650 2000 gal 4x2 Water Truck S/N: 3FRNF65E47V511047 C/W: Located in Lane 10 Spot 10, Cummins 6 Cylinder Diesel Engine, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 10R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, PTO, LW2000 2000 gal Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray Usage: 57,930 Mi Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Thu, Sep 17, 11:49 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2318	2007 Ford F-650 4x2 Water Truck S/N: 3FRNF65997V398151 C/W: Located in Lane 10 Spot 19, Cat Diesel Engine, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 10R22.5, Spring Suspension, 158 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 22,746 Mi Lot closing time: Thu, Sep 17, 11:50 AM CDT Asset located in: Lake Worth, TX, USA	2324	2017 Hino 268A 4x2 Service Truck S/N: 5PVNJ8JL4H4S51988 C/W: Located in Lane 16 Spot 14, Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 187 in Wheelbase, PTO, 16 ft 10 in Body, Hydraulic Stabilizers, Auto Crane 10006H 10000 lb 3 Section Hydraulic Crane Usage: 390,782 Mi Lot closing time: Thu, Sep 17, 11:51 AM CDT Asset located in: Humble, TX, USA
2322	2000 Chevrolet C7500 2000 gal 4x2 Water Truck S/N: 1GBL7H1C2YJ515575 C/W: Located in Lane 16 Spot 31, Cat C7 6 Cylinder Diesel Engine, 6-Speed Manual Transmission, 8100 lb Front Axle, 19000 lb Rears, 27100 lb GVWR, 11R22.5, Spring Suspension, 160 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, Hose Reel Usage: 83,119 Mi Lot closing time: Thu, Sep 17, 11:50 AM CDT Asset located in: Humble, TX, USA	2324A	2011 Ford F-750 4x2 Service Truck S/N: 3FRWF7FC9BV462198 C/W: Located in Lane 9 Spot 21, Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 33741 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, Aluminum Wheels, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Maintainer 10 ft 11 in Body, Hydraulic Stabilizers, Maintainer 10000 10000 lb 3 Section Hydraulic Crane, Ingersoll-Rand VHP40RMH 40 cfm Hydraulic Air Compressor, Air Hose Reel, Miller Bobcat 250 11000 W Gasoline Welder Usage: 352,104 Mi Lot closing time: Thu, Sep 17, 11:51 AM CDT Asset located in: Lake Worth, TX, USA
2323	2026 Kenworth T280 4x2 Service Truck S/N: 2NK3HM6X2TM221252 C/W: Located in Lane 16 Spot 9, Paccar B6.7 260 6 Cylinder 6.7 L Diesel 260 hp Engine, 2025 US EPA Label, Requires Diesel Exhaust Fluid, 4.3 Engine hrs, Engine Brake, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 16000 lb Rears, Dana Spicer P Drive Axles, 5.57:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 156 in Wheelbase, PTO, 8 ft - 13 ft 3 Section Boom, Straight Down Outriggers, Rear Outriggers, Cordless Remote Control, 2025 Roctec RT7500 7634 lb 3 Section Hydraulic Crane, Wireless Remote Control, 10 ft x 96 in Bed Usage: 9 Mi Notes: Odometer discrepancy-unit shows 9, title shows 10 Lot closing time: Thu, Sep 17, 11:51 AM CDT Asset located in: Humble, TX, USA	2325	2006 Chevrolet C5500 4x2 Service Truck S/N: 1GBE5C1296F423419 C/W: Located in Lane 9 Spot 26, 6 Cylinder Diesel Engine, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 152 in Wheelbase, 11 ft Body, Hydraulic Stabilizers, Tiger 6541 6500 lb 2 Section Electric Crane, Wired Remote Control, Hydraulic Air Compressor, Air Hose Reel Usage: 277,501 Mi Lot closing time: Thu, Sep 17, 11:51 AM CDT Asset located in: Lake Worth, TX, USA
2323A	2025 Peterbilt 536 4x2 Service Truck S/N: 2NPKHM6X4SM708683 C/W: Located in Lane 9 Spot 23, Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Ultra Shift Transmission, 10000 lb Front Axle, 21000 lb Rears, 26000 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Stellar TMax 13 ft 9 in Body, Hydraulic Stabilizers, Stellar 12621 12600 lb 3 Section Hydraulic Crane, Wireless Remote Control, Stellar 65R Hydraulic Air Compressor, (2) Product Tanks, Hose Reels Usage: 18,759 Mi Lot closing time: Thu, Sep 17, 11:51 AM CDT Asset located in: Lake Worth, TX, USA	2326	2026 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HT7TEF06290 C/W: Located in Lane 9 Spot 27, V8 6.7 L Diesel Engine, 2026 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 192 in Wheelbase, Stellar TMAX 13 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Stellar 30P Hydraulic Air Compressor, Air Hose Reel, Lincoln Eagle Gasoline Welder Usage: 4 Mi Notes: Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:51 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2328	2019 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HY2KEF25145 C/W: Ford 6.8 V10 6.8 L Gasoline Engine, 2019 US EPA Label, 6437 Engine hrs, 6-Speed Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, Ford Drive Axles, 19500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 196 in Wheelbase, Palfinger 11 ft 1 in Body, Manual Stabilizers, Palfinger Psc-6025-electric 6000 lb 3 Section Hydraulic Crane, Wired Remote Control, Compressor air systems C130geh34hc Gasoline Air Compressor Usage: 89,193 Mi Lot closing time: Thu, Sep 17, 11:52 AM CDT Asset located in: Midland, TX, USA	2333	2017 Ram 5500 4x4 Service Truck S/N: 3C7WRNBL0HG520116 C/W: Located in Lane 9 Spot 25, Cummins ISB6.7 325 6 Cylinder 6.7 L Diesel 325 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 4458 Engine hrs, Automatic Transmission, 225/70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft 1 in Body, Manual Stabilizers, Lift Moore 6036 6000 lb 3 Section Hydraulic Crane, Wireless Remote Control Usage: 182,906 Mi Lot closing time: Thu, Sep 17, 11:53 AM CDT Asset located in: Lake Worth, TX, USA
2329	2017 Ford F-550 4x4 Extended Cab Service Truck S/N: 1FD0X5HY5HEE29406 C/W: Ford V10 6.8 L Gasoline Engine, 2017 US EPA Label, 9225 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, Manual Stabilizers, Palfinger PSC 6025 3 Section Hydraulic Crane, Gasoline Air Compressor Usage: 154,889 Mi Lot closing time: Thu, Sep 17, 11:52 AM CDT Asset located in: Midland, TX, USA	2334	2020 Ford F-450 4x4 Extended Cab Service Truck S/N: 1FD0X4HT1LED87937 C/W: V8 6.7 L Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 8396 Engine hrs, Automatic Transmission, 225 /70R19.5, Spring Suspension, 168 in Wheelbase, 9 ft 1 in Body, LiftMoore 4000X 4000 lb 3 Section Electric Crane, Wired Remote Control, Power Rush GP6500 6500 W Gasoline Generator Set, Gasoline Air Compressor Usage: 157,539 Mi Lot closing time: Thu, Sep 17, 11:53 AM CDT Asset located in: Midland, TX, USA
2331	2015 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HY1FEC62121 C/W: Located in Lane 16 Spot 7, V10 6.8 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 218 in Wheelbase, PTO, 9 ft Body, Hydraulic Stabilizers, Maintainer 4 Section Hydraulic Crane Usage: 171,570 Mi Lot closing time: Thu, Sep 17, 11:53 AM CDT Asset located in: Humble, TX, USA	2336	2023 Chevrolet Silverado 3500HD 4x4 Crew Cab Service Truck S/N: 1GB4YSE7XPF128270 C/W: GM V8 6.6 L Gasoline Engine, 2023 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 176 in Wheelbase, PTO, 2023 Knapheide 6108D54 10 ft 4 in Body, Manual Stabilizers, 2023 Tiger 4016E 8000 lb 3 Section Electric Crane, JM Pressed Air System P8HG13 Gasoline Air Compressor, Air Hose Reel Usage: Not Available Lot closing time: Thu, Sep 17, 11:54 AM CDT Asset located in: Midland, TX, USA
2332	2015 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HT8FEB40994 C/W: Located in Lane 9 Spot 22, Ford Power Stroke V8 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, PTO, 13 ft Body, Manual Stabilizers, Auto Crane 4004EH 4000 lb 3 Section Electric Crane, Wired Remote Control, Miller Wildcat 200 6500 W Gasoline Generator Set, HD6510TH3 16 cfm Gasoline Air Compressor, Miller Wildcat 200 200 A Gasoline Welder Usage: 142,543 Mi Notes: Selling with 3 affidavits of correction and may not be accepted in your state. Verify with your local DMV prior to bidding. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 11:53 AM CDT Asset located in: Lake Worth, TX, USA	2337	2022 Ford F-350 XL 4x4 Crew Cab Service Truck S/N: 1FD8W3HT2NED40645 C/W: V8 6.7 L Diesel Engine, 2021 US EPA Label, Ford 6-Speed Automatic Transmission, 5600 lb Front Axle, 10040 lb Rears, Ford Drive Axles, 14000 lb GVWR, 245/75R17 Front Tires, 245/75R17 Rear Tires, Ford Spring Suspension, 177 in Wheelbase, RKI 9 ft 1 in Body, Manual Stabilizers, Liftmoore 4000X 2 Section Electric Crane, Wired Remote Control Usage: 159,668 Mi Lot closing time: Thu, Sep 17, 11:54 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2339	2019 Ford F-350 XL 4x4 Extended Cab Service Truck S/N: 1FD8X3H6XKED03488 C/W: Ford V8 6.2 L Gasoline Engine, 2019 US EPA Label, Ford 6-Speed Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, Ford Drive Axles, 14000 lb GVWR, 246 /75R17 Front Tires, 245/75R17 Rear Tires, Ford Spring Suspension, 170 in Wheelbase, Knapheide 6108d54 8 ft 11 in Body, Manual Stabilizers, 2018 Auto Crane Ehc4 3 Section Electric Crane, Wireless Remote Control, CAS P80hg13 Gasoline Air Compressor, Air Hose Reel Usage: 145,393 Mi Lot closing time: Thu, Sep 17, 11:55 AM CDT Asset located in: Midland, TX, USA	2344	2022 Ram 3500 4x4 Crew Cab Utility Truck S/N: 3C63R3GL6NG234433 C/W: 6 Cylinder 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 7000 lb Rears, 12300 lb GVWR, 275/70R18, Spring Suspension, 166 in Wheelbase, Knapheide 9 ft Body Usage: 92,460 Mi Lot closing time: Thu, Sep 17, 11:56 AM CDT Asset located in: Midland, TX, USA
2340	2018 Ford F-350 XL 4x4 Extended Cab Service Truck S/N: 1FD8X3HT0JEC27722 C/W: Located in Lane 16 Spot 8, Ford Powerstroke V8 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 169 in Wheelbase, Knapheide 6108D54-S 10 ft Body, Manual Stabilizers, Stellar EC3200 3200 lb 3 Section Electric Crane, Wireless Remote Control, Ingersoll-Rand 2475 Gasoline Air Compressor, Air Hose Reel Usage: 69,108 Mi Notes: Service Records see Documents Lot closing time: Thu, Sep 17, 11:55 AM CDT Asset located in: Humble, TX, USA	2345	2022 Chevrolet Silverado 3500HD 4x4 Crew Cab Utility Truck S/N: 1GB4YSEY5NF318953 C/W: Located in Lane 16 Spot 19, V8 6.6 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 177 in Wheelbase, 9 ft Body Usage: 118,835 Mi Notes: This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control systems or devices as originally equipped. Buyer of this unit must sign acknowledgement form of this notice prior to removal of unit from the yard. Lot closing time: Thu, Sep 17, 11:56 AM CDT Asset located in: Humble, TX, USA
2341	2024 Ford F-550 XL 4x2 Service Truck S/N: 1FDUF5GT3RDA17695 C/W: Ford Power Stroke V8 6.7 L Diesel Engine, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, IMT Dominator 13 ft 0 in Body, Hydraulic Stabilizers, IMT 6000 3 Section Hydraulic Crane, Wireless Remote Control, Hobart Champion 145 4500 W Gasoline Generator Set, Ingersoll-Rand 2475 Gasoline Air Compressor, Air Hose Reel, Hobart 4500 W 145 A Gasoline Welder Usage: 137,011 Mi Notes: This unit is being sold with a rebuilt salvage-loss unknown title. ; Due to Accident that only Shifted Rear Axle Back - Air Bags were replaced, and Rear Springs & Axle Replaced - No Other Damage to the Chassis or Body ; Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:55 AM CDT Asset located in: Lake Worth, TX, USA	2346	2020 Chevrolet Silverado 3500HD 4x4 Extended Cab Utility Truck S/N: 1GB5YSE76LF247965 C/W: GM V8 6.6 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 10500 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 163 in Wheelbase, Knapheide 9 ft Body Usage: 116,372 Mi Lot closing time: Thu, Sep 17, 11:56 AM CDT Asset located in: Midland, TX, USA
		2347	2020 Chevrolet Silverado 3500HD 4x4 Extended Cab Utility Truck S/N: 1GB5YSE78LF253525 C/W: GM 6.6 V8 6.6 L Gasoline Engine, 2020 US EPA Label, GM 6-Speed Automatic Transmission, 4800 lb Front Axle, 10500 lb Rears, 14000 lb GVWR, 235/80R17 Front Tires, 235/80R17 Rear Tires, GM Spring Suspension, 162 in Wheelbase, 2020 Knapheide 696D54 98 ft Body Usage: 138,532 Mi Lot closing time: Thu, Sep 17, 11:56 AM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2348	2018 Chevrolet 3500HD 4x4 Crew Cab Utility Truck S/N: 1GC4KYCG5JF150722 C/W: V8 6 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 9375 lb Rears, 13025 lb GVWR, Dual Rear Wheel, 235/80R17 Front Tires, 235/80R17 Rear Tires, UTB U9656D422152VFW155 Body Usage: 168,144 Mi Lot closing time: Thu, Sep 17, 11:57 AM CDT Asset located in: Midland, TX, USA	2353A	2012 Chevrolet Silverado 2500 4x4 Utility Truck S/N: 1GC0KVCG2CF109352 C/W: GM V8 6.0 L Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9500 lb GVWR, 245/75R17, Spring Suspension, 133 in Wheelbase, Stahl 8 ft 2 in Body Usage: 248,542 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 11:58 AM CDT Asset located in: Oklahoma City, OK, USA
2349	2016 Chevrolet Silverado 3500 HD 4x4 Crew Cab Utility Truck S/N: 1GB4KYC8XGF175279 C/W: Located in Lane 9 Spot 31, GM V8 6.6 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8482.0 Engine hrs, Exhaust Brake, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 172 in Wheelbase, 9 ft Body, Fuel Tank w/ Pump Usage: 172,264 Mi Lot closing time: Thu, Sep 17, 11:57 AM CDT Asset located in: Lake Worth, TX, USA	2353B	2019 Ford F-350 4x2 Crew Cab Utility Truck S/N: 1FD8W3G62KED27109 C/W: Located in Lane 9 Spot 28, Ford V8 6.2 L Gasoline Engine, 2019 US EPA Label, 8488 Engine hrs, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, Knapheide 6108D54-2 9 ft Body Usage: 165,900 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided.;Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:58 AM CDT Asset located in: Lake Worth, TX, USA
2350	2015 Chevrolet Silverado 3500 HD 4x4 Crew Cab Utility Truck S/N: 1GB4KYE88FF558150 C/W: Located in Lane 9 Spot 32, Duramax V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8894.8 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17 Front Tires, 235/80R17 Rear Tires, Spring Suspension, 172 in Wheelbase, Caseco 9 ft Body Usage: 192,261 Mi Lot closing time: Thu, Sep 17, 11:57 AM CDT Asset located in: Lake Worth, TX, USA	2358	2018 Ford F-350 XL 4x2 Crew Cab Utility Truck S/N: 1FD8W3G61JEB34173 C/W: Located in Lane 9 Spot 30, Ford V8 6.2 L Gasoline Engine, 2018 US EPA Label, 10276 Engine hrs, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 245/75R17, Spring Suspension, 179 in Wheelbase, Knapheide 6108D54-2 9 ft Body Usage: 163,693 Mi Notes: Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 11:59 AM CDT Asset located in: Lake Worth, TX, USA
2350A	2011 Ford F-350 XL 4x4 Crew Cab Utility Truck S/N: 1FD8W3HT6BEA55880 C/W: Located in Lane 16 Spot 17, 6.7 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 265/77R17, Spring Suspension, 176 in Wheelbase, 9 ft Body Usage: Not Available Lot closing time: Thu, Sep 17, 11:57 AM CDT Asset located in: Humble, TX, USA	2359	2015 Ford F-350 XL 4x2 Utility Truck S/N: 1FDRF3G6XFED00265 C/W: Located in Lane 16 Spot 1, V8 6.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4250 lb Front Axle, 9750 lb Rears, 13700 lb GVWR, 245/75R17, Spring Suspension, 178 in Wheelbase, 7 ft Body Usage: 311,288 Mi Lot closing time: Thu, Sep 17, 11:59 AM CDT Asset located in: Humble, TX, USA
2351	2010 Ford F-350 XL 4x4 Crew Cab Utility Truck S/N: 1FDWW3HRXAEB40795 C/W: Located in Lane 16 Spot 15, Ford V8 6.4 L Diesel Engine, 2010 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 9750 lb Rears, 13000 lb GVWR, 265/70R17, Spring Suspension, 180 in Wheelbase, 8 ft 6 in Body Usage: 125,908 Mi Lot closing time: Thu, Sep 17, 11:57 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2360	2015 Nissan Frontier 4x2 Extended Cab Sprayer Utility Truck S/N: 1N6AD0CU9FN760217 C/W: Located in Lane 23 Spot 34, Nissan V6 4.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 3296 lb Front Axle, 3331 lb Rears, 5588 lb GVWR, 265/70R16, Spring Suspension, 124 in Wheelbase, 6 ft 8 in Body Usage: 165,221 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 11:59 AM CDT Asset located in: Humble, TX, USA	2366	2013 Peterbilt 388 8x4 Tri/A Day Cab Truck Tractor S/N: 1NPWX4EX7DD173735 C/W: Cummins ISX15 Engine, 2012 US EPA Label, 13087 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 20000 lb Front Axle, 57000 lb Rears, 77000 lb GVWR, Double Differential Locks, 253 in Wheelbase, Air Suspension, Air Lift Pusher Axle, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Air Sliding 5th Wheel, Headache Rack Usage: 155,557 Mi Lot closing time: Thu, Sep 17, 12:01 PM CDT Asset located in: Midland, TX, USA
2361	UNIC UR505-A2 5 ton Straight Boom on 2008 Mack GU813 6x4 Boom Truck S/N: 1M2AX13CX8M001071 C/W: Located in Lane 1 Spot 20, Mack MP7 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 300 in Wheelbase, PTO, 7 ft - 42.9 ft 5 Section Boom, 2 Sheave Hook Block, Dual Controls, Out and Down Outriggers, Rear Outriggers, 21 ft x 102 in Bed Usage: 53,624 Mi Lot closing time: Thu, Sep 17, 12:00 PM CDT Asset located in: Humble, TX, USA	2367	2012 Kenworth T800 8x4 Tri/A Day Cab Truck Tractor S/N: 1XKDP4TX2CJ310912 C/W: Located in Lane 31 Spot 26, Cummins ISX15 485 hp Engine, 2011 US EPA Label, 10005 Engine hrs, Eaton Fuller RTLO-18918B 18-Speed Manual, 14320 lb Front Axle, Dana D46-170HP Drive Axles, 4.30:1 Axle Ratio, 67618 lb Rears, 80440 lb GVWR, Engine Brake, 250 in Wheelbase, Air Suspension, Air Lift Pusher Axle, Aluminum Front Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 382,067 Mi Lot closing time: Thu, Sep 17, 12:01 PM CDT Asset located in: Humble, TX, USA
2362	2002 National 600D 36000 lb Straight Boom on 2003 Sterling L7500 6x4 Boom Truck S/N: 2FZHATAK83AK92610 C/W: Located in Lane 1 Spot 17, Cat 3126 6 Cylinder Diesel Engine, Eaton Fuller 10-Speed Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 264 in Wheelbase, 25 ft - 70 ft 3 Section Boom, 25 ft - 45 ft Jib, 150 lb Overhaul Ball 8400 lb Capacity, Dual Controls, Liftek Load Moment Indicator, A-Outriggers, Rear Outriggers, 20 ft x 96 in Bed Usage: 133,302 Hr Notes: This unit is being sold with a bonded title. Buyers in the state of LA -bonded titles will not be accepted in your state. Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 12:00 PM CDT Asset located in: Humble, TX, USA	2370	2012 Western Star 4900SA 8x4 Tri/A Day Cab Truck Tractor S/N: 5KJJAEDRXCPCM9282 C/W: Located in Lane 30 Spot 2, Detroit DD15 505 hp Engine, 2015 US EPA Label, Eaton Fuller 18-Speed Manual Transmission, 14700 lb Front Axle, 44000 lb Rears, Engine Brake, 230 in Wheelbase, Air Suspension, Air Lift Pusher Axle, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 79,249 Mi Lot closing time: Thu, Sep 17, 12:02 PM CDT Asset located in: Lake Worth, TX, USA
		2371	1999 Mack CH613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M2AA18Y1XW115260 C/W: Located in Lane 31 Spot 49, Mack Engine, 7459 Engine hrs, Mack Maxitorque 13-Speed Manual Transmission, Engine Brake, 252 in Wheelbase, Air Suspension, Air Lift Pusher Axle, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 12:02 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2372	2007 Peterbilt 379 8x4 Tri/A Sleeper Truck Tractor S/N: 1XP5DBEX37N635835 C/W: Located in Lane 29 Spot 3, Cat Engine, 22671 Engine hrs, Eaton Fuller Manual Transmission, 14320 lb Front Axle, 66000 lb Rears, 74600 lb GVWR, Engine Brake, 36 in Flat Top Sleeper Cab, 276 in Wheelbase, Air Suspension, Air Lift Pusher Axle, Aluminum Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 638,975 Mi Lot closing time: Thu, Sep 17, 12:02 PM CDT Asset located in: Humble, TX, USA	2390	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZD49X5GJ115303 C/W: Cummins ISX15 450 hp Engine, 2015 US EPA Label, 19733 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 212 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 537,670 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:06 PM CDT Asset located in: San Antonio, TX, USA
2373	2003 Peterbilt 387 8x4 Tri/A Sleeper Truck Tractor S/N: 1XP7DB9X63D806595 C/W: Located in Lane 34 Spot 1, Cat Engine, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 296 in Wheelbase, Air Suspension, Air Lift Pusher Axle, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 931,237 Mi Lot closing time: Thu, Sep 17, 12:02 PM CDT Asset located in: Lake Worth, TX, USA	2392	2012 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9XXCJ317740 C/W: Located in Lane 31 Spot 40, Paccar MX 455 hp Engine, 2011 US EPA Label, 2959 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 189 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel Usage: 433,227 Mi Lot closing time: Thu, Sep 17, 12:07 PM CDT Asset located in: Humble, TX, USA
2374	2019 Kenworth W900L 6x4 T/A Day Cab Truck Tractor S/N: 1XKWD40X4KJ254377 C/W: Located in Lane 30 Spot 47, Cummins X15 500 hp Engine, 2018 US EPA Label, 17600 Engine hrs, Eaton Fuller RTLO-18913A 13-Speed Manual, 13200 lb Front Axle, 44000 lb Rears, 57200 lb GVWR, Engine Brake, Differential Lock, 240 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 285/75R24.5, Dual Fuel Tanks Usage: 535,566 Mi Lot closing time: Thu, Sep 17, 12:03 PM CDT Asset located in: Humble, TX, USA	2395	2016 Freightliner 122SD 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV2GDHE4680 C/W: Detroit DD13 470 hp Engine, 2015 US EPA Label, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Engine Brake, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 515,750 Mi Lot closing time: Thu, Sep 17, 12:08 PM CDT Asset located in: Lake Worth, TX, USA
2375	2015 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXDP9X0FD275606 C/W: Paccar MX-13 Engine, 2014 US EPA Label, 12183 Engine hrs, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 240 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 327,569 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 12:03 PM CDT Asset located in: Pecos, TX, USA	2396	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY9LM017700 C/W: Located in Lane 31 Spot 37, Mack MP7 425 hp Engine, 2019 US EPA Label, 13814 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 182 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Fuel Tanks Usage: 259,866 Mi Lot closing time: Thu, Sep 17, 12:08 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2398	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY9LM017695 C/W: Located in Lane 30 Spot 3, Mack MP7 Engine, 2020 US EPA Label, Mack mDRIVE Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 177 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Fuel Tanks Usage: 189,973 Mi Lot closing time: Thu, Sep 17, 12:08 PM CDT Asset located in: Humble, TX, USA	2403	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY8LM018210 C/W: Located in Lane 31 Spot 19, Mack MP7 1425 hp Engine, US EPA Label, 11738 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 178 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Dual Fuel Tanks Usage: 372,283 Mi Lot closing time: Thu, Sep 17, 12:09 PM CDT Asset located in: Humble, TX, USA
2399	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GYXLM018449 C/W: Located in Lane 31 Spot 20, Mack MP7 425 hp Engine, 2019 US EPA Label, 9775 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 180 in Wheelbase, Air Suspension, Aluminum Wheels, 12R22.5, Wet Kit, Dual Fuel Tanks Usage: 285,011 Hr Lot closing time: Thu, Sep 17, 12:09 PM CDT Asset located in: Humble, TX, USA	2404	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY6LM017721 C/W: Located in Lane 31 Spot 41, Mack MP7 Engine, 10627 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 180 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Usage: 332,020 Mi Lot closing time: Thu, Sep 17, 12:10 PM CDT Asset located in: Humble, TX, USA
2400	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY3LM017711 C/W: Located in Lane 30 Spot 4, 14044 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 180 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Fuel Tanks Usage: 170,857 Mi Lot closing time: Thu, Sep 17, 12:09 PM CDT Asset located in: Humble, TX, USA	2405	2019 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY6KM010122 C/W: Located in Lane 30 Spot 40, Mack MP7 425 hp Engine, 2018 US EPA Label, 16822 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 180 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Fuel Tanks Usage: 360,118 Mi Lot closing time: Thu, Sep 17, 12:10 PM CDT Asset located in: Humble, TX, USA
2402	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY5LM018553 C/W: Located in Lane 31 Spot 43, Mack MP7 Engine, Mack mDRIVE Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 180 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Dual Fuel Tanks Usage: 344,110 Mi Lot closing time: Thu, Sep 17, 12:09 PM CDT Asset located in: Humble, TX, USA	2406	2019 Mack P164T 6x4 T/A Day Cab Truck Tractor S/N: 1M2PN4GY0KM001322 C/W: Located in Lane 30 Spot 9, Mack MP8 445 hp Engine, 2018 US EPA Label, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, 217 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 633,040 Mi Lot closing time: Thu, Sep 17, 12:10 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2408	2024 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR0RN358288 C/W: Located in Lane 31 Spot 23, Cummins X15 450 hp Engine, 2023 US EPA Label, 7094 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 145,157 Mi Lot closing time: Thu, Sep 17, 12:11 PM CDT Asset located in: Lake Worth, TX, USA	2412	2023 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR1PN190710 C/W: Located in Lane 32 Spot 17, Cummins X15 450 hp Engine, 2022 US EPA Label, 9896 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 247,599 Mi Lot closing time: Thu, Sep 17, 12:12 PM CDT Asset located in: Lake Worth, TX, USA
2409	2024 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR2RN358289 C/W: Located in Lane 30 Spot 28, Cummins X15 Engine, 2023 US EPA Label, 6993 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 199 in Wheelbase, Air Suspension, 11R22.5, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 147,302 Mi Lot closing time: Thu, Sep 17, 12:11 PM CDT Asset located in: Lake Worth, TX, USA	2413	2023 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR0PN452541 C/W: Located in Lane 30 Spot 26, Cummins X15 450 hp Engine, 2022 US EPA Label, 10361 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 213,201 Mi Lot closing time: Thu, Sep 17, 12:12 PM CDT Asset located in: Lake Worth, TX, USA
2410	2024 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR9RN358290 C/W: Located in Lane 31 Spot 19, Cummins X15 450 hp Engine, 2023 US EPA Label, 7080 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 154,940 Mi Lot closing time: Thu, Sep 17, 12:11 PM CDT Asset located in: Lake Worth, TX, USA	2414	2023 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR2PN452542 C/W: Located in Lane 30 Spot 20, Cummins X15 450 hp Engine, 2022 US EPA Label, 10426 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 223,818 Mi Lot closing time: Thu, Sep 17, 12:12 PM CDT Asset located in: Lake Worth, TX, USA
2411	2023 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR5PN190712 C/W: Located in Lane 30 Spot 27, Cummins X15 450 hp Engine, 2022 US EPA Label, 8850 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 185,050 Mi Lot closing time: Thu, Sep 17, 12:11 PM CDT Asset located in: Lake Worth, TX, USA	2415	2022 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR4NN553496 C/W: Located in Lane 30 Spot 6, Cummins X15 450 hp Engine, 2021 US EPA Label, 11439 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 234,487 Mi Lot closing time: Thu, Sep 17, 12:12 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2416	2022 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSPCAPR2NN553495 C/W: Located in Lane 32 Spot 16, Cummins X15 450 hp Engine, 2021 US EPA Label, 10894 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 236,053 Mi Lot closing time: Thu, Sep 17, 12:12 PM CDT Asset located in: Lake Worth, TX, USA	2420	2020 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR0LN149224 C/W: Located in Lane 31 Spot 21, Cummins X15 450 hp Engine, 2019 US EPA Label, 14036 Engine hrs, Eaton Fuller Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 287,869 Mi Lot closing time: Thu, Sep 17, 12:13 PM CDT Asset located in: Lake Worth, TX, USA
2417	2021 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR4MN257766 C/W: Located in Lane 30 Spot 15, Cummins X15 450 hp Engine, 2020 US EPA Label, 11779 Engine hrs, Eaton Fuller Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 253,624 Mi Lot closing time: Thu, Sep 17, 12:13 PM CDT Asset located in: Lake Worth, TX, USA	2420A	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR2JN406719 C/W: Located in Lane 31 Spot 24, Cummins X15 450 hp Engine, 2017 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 205 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Wet Kit, Dual Fuel Tanks Usage: 278,163 Mi Lot closing time: Thu, Sep 17, 12:14 PM CDT Asset located in: Humble, TX, USA
2418	2021 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR2MN257765 C/W: Located in Lane 31 Spot 7, Cummins X15 450 hp Engine, 2020 US EPA Label, 12727 Engine hrs, Eaton Fuller Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 199 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Dual Steering Boxes, Wet Kit, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 254,789 Mi Lot closing time: Thu, Sep 17, 12:13 PM CDT Asset located in: Lake Worth, TX, USA	2421	2024 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X0RD664132 C/W: Located in Lane 30 Spot 41, Paccar MX-13 259.2 hp Engine, 2023 US EPA Label, 3698.5 Engine hrs, 13200 lb Front Axle, 19000 lb Rears, 51200 lb GVWR, 158 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires Usage: 126,088 Mi Lot closing time: Thu, Sep 17, 12:14 PM CDT Asset located in: Humble, TX, USA
2419	2021 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR1MN577868 C/W: Located in Lane 32 Spot 12, Cummins X15 450 hp Engine, 2020 US EPA Label, 12759 Engine hrs, Eaton Fuller Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 200 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Equipment-from-Whitaker-Aggregates Usage: 281,441 Mi Lot closing time: Thu, Sep 17, 12:13 PM CDT Asset located in: Lake Worth, TX, USA	2423	2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9XXLD683696 C/W: Located in Lane 26 Spot 46, Paccar Engine, 2020 US EPA Label, 1161 Engine hrs, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Heater, 238 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 532,511 Mi Notes: *Modified Emissions- Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 12:14 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2424	2019 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBD49X2KD265095 C/W: Located in Lane 31 Spot 1, Cummins X15 450 hp Engine, 2018 US EPA Label, 11775.6 Engine hrs, Paccar Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, Air Suspension, Aluminum Wheels, 295/75R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 175,596 Mi Lot closing time: Thu, Sep 17, 12:14 PM CDT Asset located in: Lake Worth, TX, USA	2428	2019 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHLDV2KSKE1279 C/W: Located in Lane 30 Spot 16, Detroit DD13 435 hp Engine, 2018 US EPA Label, Detroit DT12-1550-OH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 180 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 447,591 Mi Lot closing time: Thu, Sep 17, 12:15 PM CDT Asset located in: Humble, TX, USA
2425	2020 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHLDV6LSLG9574 C/W: Located in Lane 31 Spot 46, Detroit DD13 450 hp Engine, 2020 US EPA Label, Detroit DT12-1550-DH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 174 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel Usage: 363,600 Mi Lot closing time: Thu, Sep 17, 12:15 PM CDT Asset located in: Humble, TX, USA	2429	2022 Freightliner Cascadia 116 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHTDV2NSNP0296 C/W: Located in Lane 31 Spot 15, Detroit DD13 450 hp Engine, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 174 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 669,974 Mi Lot closing time: Thu, Sep 17, 12:16 PM CDT Asset located in: Lake Worth, TX, USA
2426	2019 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHLDV0KSKH7231 C/W: Located in Lane 31 Spot 17, Detroit DD13 450 hp Engine, 2018 US EPA Label, 8930 Engine hrs, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 178 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 413,337 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:15 PM CDT Asset located in: Lake Worth, TX, USA	2430	2021 Freightliner Cascadia 116 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHTDV5MSMH9288 C/W: Located in Lane 30 Spot 21, Detroit DD13 470 hp Engine, 2020 US EPA Label, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 176 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 570,424 Mi Lot closing time: Thu, Sep 17, 12:16 PM CDT Asset located in: Humble, TX, USA
2427	2019 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHLDV0KSKE1278 C/W: Located in Lane 30 Spot 49, Detroit DD13 525 hp Engine, 2018 US EPA Label, 11294 Engine hrs, Detroit DT12-1550-OH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Retarder, 179 in Wheelbase, Air Suspension, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 324,498 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:15 PM CDT Asset located in: Humble, TX, USA	2431	2021 Freightliner Cascadia 116 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHTDV6MSMH9204 C/W: Located in Lane 31 Spot 45, Detroit DD13 470 hp Engine, 2020 US EPA Label, 14500 Engine hrs, Detroit DT12-1650-OH1 12-Speed Automated Transmission, Engine Brake, 176 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 588,450 Mi Lot closing time: Thu, Sep 17, 12:16 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2432	2020 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV9LSLP2620 C/W: Located in Lane 31 Spot 28, Detroit DD13 435 hp Engine, 2019 US EPA Label, Eaton Fuller FAO-16810C-EA 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 178 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 364,424 Mi Lot closing time: Thu, Sep 17, 12:16 PM CDT Asset located in: Humble, TX, USA	2437	2019 International LT625 6x4 T/A Day Cab Truck Tractor S/N: 3HSDZTZR9KN728928 C/W: Located in Lane 30 Spot 25, International A26 Engine, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 179 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 499,080 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:17 PM CDT Asset located in: Lake Worth, TX, USA
2433	2019 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV9KDKL5499 C/W: Located in Lane 32 Spot 2, Detroit DD13 470 hp Engine, 2018 US EPA Label, 7687.4 Engine hrs, Detroit DT12-1650-OH1-8 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 200 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 122,513 Mi Notes: Additional Components located in office - CPC Lot closing time: Thu, Sep 17, 12:16 PM CDT Asset located in: Lake Worth, TX, USA	2438	2019 International LT625 6x4 T/A Day Cab Truck Tractor S/N: 3HSDZTZRXKN725679 C/W: Located in Lane 30 Spot 10, 16196 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 176 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 562,140 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:18 PM CDT Asset located in: Lake Worth, TX, USA
2434	2019 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV1KLKD8141 C/W: Located in Lane 31 Spot 17, Detroit DD13 450 hp Engine, 2019 US EPA Label, Eaton Fuller FAO-16810C-EA 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 171 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 478,130 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:17 PM CDT Asset located in: Humble, TX, USA	2439	2019 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR4KN276623 C/W: Located in Lane 31 Spot 48, 6351 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 171 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 342,411 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:18 PM CDT Asset located in: Humble, TX, USA
2436	2019 International LT625 6x4 T/A Day Cab Truck Tractor S/N: 3HCDZTZR8KL622462 C/W: Located in Lane 30 Spot 7, International A26 430 hp Engine, 2018 US EPA Label, 310 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 182 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 72 Mi Notes: Selling with 2 affidavits of correction and may not be accepted in your state. Verify with your local DMV prior to bidding. Lot closing time: Thu, Sep 17, 12:17 PM CDT Asset located in: Lake Worth, TX, USA	2440	2018 Kenworth T680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYD49XXJJ210961 C/W: Located in Lane 100 Spot 10, Cummins X15 450 hp Engine, 2017 US EPA Label, 14236.0 Engine hrs, Eaton Fuller FAO16810C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 184 in Wheelbase, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 407,689 Mi Lot closing time: Thu, Sep 17, 12:18 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2444	2015 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X1FD299603 C/W: Located in Lane 30 Spot 14, Paccar MX-13 Engine, 16643 Engine hrs, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 206 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 368,730 Mi Notes: Remanufactured Engine Purchased July of 2024 Lot closing time: Thu, Sep 17, 12:19 PM CDT Asset located in: Humble, TX, USA	2455	2013 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y1DM025647 C/W: Mack MP8 445 hp Engine, 2012 US EPA Label, 20100 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 195 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,334 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 12:21 PM CDT Asset located in: Oklahoma City, OK, USA
2445	2012 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X8CD144679 C/W: Located in Lane 31 Spot 22, Paccar 455 hp Engine, 2011 US EPA Label, 1443 Engine hrs, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 198 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Headache Rack, Lowboy Ramps Usage: 686,797 Mi Lot closing time: Thu, Sep 17, 12:19 PM CDT Asset located in: Lake Worth, TX, USA	2456	2013 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y1DM025650 C/W: Mack MP8 Engine, 2012 US EPA Label, 21063 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 196 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 557,330 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 12:21 PM CDT Asset located in: Oklahoma City, OK, USA
2447A	2018 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y8JM089468 C/W: Located in Lane 30 Spot 43, Mack MP8 505 hp Engine, 2017 US EPA Label, 2045 Engine hrs, Automated Transmission, 14320 lb Front Axle, 22700 lb Rears, 27090 lb GVWR, Engine Brake, Differential Lock, 182 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Dual Fuel Tanks Usage: 654,719 Mi Lot closing time: Thu, Sep 17, 12:20 PM CDT Asset located in: Humble, TX, USA	2457	2017 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y1HM025513 C/W: Located in Lane 30 Spot 8, Mack MP8 505 hp Engine, 2016 US EPA Label, 23188 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, Engine Brake, 214 in Wheelbase, Aluminum Outer Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 455,749 Mi Lot closing time: Thu, Sep 17, 12:22 PM CDT Asset located in: Humble, TX, USA
2450	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y6FM047744 C/W: Mack MP8 445 hp Engine, 2015 US EPA Label, 1494 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Engine Brake, Differential Lock, 196 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Dual Fuel Tanks Usage: 643,324 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 12:20 PM CDT Asset located in: Oklahoma City, OK, USA	2458	2016 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y7GM025448 C/W: Located in Lane 30 Spot 27, Mack MP8 445 hp Engine, 2015 US EPA Label, 20899 Engine hrs, Mack Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 220 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 509,996 Mi Lot closing time: Thu, Sep 17, 12:22 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2458A	2016 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y1GM020841 C/W: Located in Lane 30 Spot 10, Mack MP8 445 hp Engine, 2014 US EPA Label, 8 Engine hrs, Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 220 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R24.5, Dual Fuel Tanks Usage: 632,131 Mi Lot closing time: Thu, Sep 17, 12:22 PM CDT Asset located in: Humble, TX, USA	2462	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y6CM008356 C/W: Located in Lane 30 Spot 44, Mack MP8 415 hp Engine, 2011 US EPA Label, 13475 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Engine Brake, 202 in Wheelbase, Camelback, Aluminum Outer Wheels, 11R24.5, Wet Kit, Dual Fuel Tanks Usage: 50,908 Mi Lot closing time: Thu, Sep 17, 12:23 PM CDT Asset located in: Humble, TX, USA
2459	2016 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y4GM025455 C/W: Located in Lane 31 Spot 35, Mack MP8 445 hp Engine, 2015 US EPA Label, 21342 Engine hrs, Mack Maxitorque T310 10-Speed Manual Transmission 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 220 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R24.5, Dual Fuel Tanks Usage: 539,355 Mi Lot closing time: Thu, Sep 17, 12:23 PM CDT Asset located in: Humble, TX, USA	2463	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV8JSJS8230 C/W: Detroit DD13 435 hp Engine, 2017 US EPA Label, 6768 Engine hrs, Detroit FAO-16810C-EA 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 178 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Dual Fuel Tanks Usage: 216,451 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 12:23 PM CDT Asset located in: Oklahoma City, OK, USA
2459B	2015 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y7FM017946 C/W: Located in Lane 31 Spot 47, Mack MP8 322 hp Engine, Engine Coolant Heater, 2014 US EPA Label, 23142 Engine hrs, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission 14320 lb Front Axle, 40000 lb Rears, 24640 lb GVWR, Engine Brake, Differential Lock, 223 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 438,257 Mi Lot closing time: Thu, Sep 17, 12:23 PM CDT Asset located in: Humble, TX, USA	2464	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDVXJSJH2080 C/W: Located in Lane 30 Spot 7, Detroit DD13 435 hp Engine, 2018 US EPA Label, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Retarder, 178 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 447,012 Mi Lot closing time: Thu, Sep 17, 12:24 PM CDT Asset located in: Humble, TX, USA
2460	2014 Mack CHU613 6x4 Pinnacle T/A Day Cab Truck Tractor S/N: 1M1AN07Y6EM015748 C/W: Located in Lane 31 Spot 33, Mack MP8 505 hp Engine, 2013 US EPA Label, 20843 Engine hrs, Mack mDRIVE Automated Transmission, Engine Brake, 222 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 359,962 Mi Lot closing time: Thu, Sep 17, 12:23 PM CDT Asset located in: Humble, TX, USA	2465	2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEBG2HSJG8457 C/W: Located in Lane 30 Spot 17, Cummins ISX 400 hp Engine, 2016 US EPA Label, 12105 Engine hrs, Eaton Fuller FAOM-15810C 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 176 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 631,790 Mi Lot closing time: Thu, Sep 17, 12:24 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2466	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED53GLGT8542 C/W: Located in Lane 32 Spot 7, Detroit DD15 455 hp Engine, 2014 US EPA Label, 13502.5 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 178 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 399,660 Mi Notes: Additional Components Available in Office - CPC Lot closing time: Thu, Sep 17, 12:24 PM CDT Asset located in: Lake Worth, TX, USA	2473	2016 Freightliner M2 112 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJC5DV7GHHF5440 C/W: Located in Lane 65 Spot 0, Detroit DD13 410 hp Engine, 2016 US EPA Label, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 172 in Wheelbase, Air Suspension, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 12:26 PM CDT Asset located in: Humble, TX, USA
2467	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED50GLHA8199 C/W: Located in Lane 30 Spot 14, Detroit DD15 455 hp Engine, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 179 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 436,294 Mi Lot closing time: Thu, Sep 17, 12:24 PM CDT Asset located in: Lake Worth, TX, USA	2474	2018 Volvo VNR 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH2JN898484 C/W: Located in Lane 31 Spot 23, Volvo D13M 425 hp Engine, 2017 US EPA Label, 13511.3 Engine hrs, Volvo ATO2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Suspension, 11R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 12:26 PM CDT Asset located in: Humble, TX, USA
2470	2015 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED51FLGG8441 C/W: Located in Lane 31 Spot 3, Detroit DD15 455 hp Engine, 2014 US EPA Label, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Differential Lock, 183 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 389,598 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 12:25 PM CDT Asset located in: Humble, TX, USA	2475	2019 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR0KN329074 C/W: Located in Lane 31 Spot 12, International A26 Engine, 2018 US EPA Label, Automated Transmission, Engine Brake, 202 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 649,807 Mi Lot closing time: Thu, Sep 17, 12:26 PM CDT Asset located in: Lake Worth, TX, USA
		2476	2018 International LT625 6x4 T/A Day Cab Truck Tractor S/N: 3HSDZTZR2JN213476 C/W: Located in Lane 30 Spot 21, International Engine, 12863 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 177 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 464,551 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:26 PM CDT Asset located in: Lake Worth, TX, USA
2472	2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGBDV1GDGW4676 C/W: Located in Lane 30 Spot 2, 2015 US EPA Label, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Differential Lock, 178 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Dual Fuel Tanks Usage: 555,594 Mi Lot closing time: Thu, Sep 17, 12:26 PM CDT Asset located in: Humble, TX, USA	2479	2018 International LT625 6x4 T/A Day Cab Truck Tractor S/N: 3HSDZAPR0JN533466 C/W: Located in Lane 31 Spot 2, Cummins X15 400 hp Engine, 2017 US EPA Label, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 183 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 632,648 Mi Lot closing time: Thu, Sep 17, 12:27 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2480	2013 International Paystar 5900i 6x4 T/A Day Cab Truck Tractor S/N: 1HSXYSJR9DJ155203 C/W: Located in Lane 31 Spot 38, International MAXXFORCE Engine, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 206 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R24.5, Wet Kit, Dual Fuel Tanks, Headache Rack Usage: 353,231 Mi Lot closing time: Thu, Sep 17, 12:27 PM CDT Asset located in: Humble, TX, USA	2483	2006 Kenworth T800 6x4 Heavy Haul T/A Day Cab Truck Tractor S/N: 1XKDD40X86R137366 C/W: Located in Lane 36 Spot 48, Cummins ISX 500 hp Engine, 2005 US EPA Label, Eaton Fuller RTLO-20918B 18-Speed Manual, 60600 lb GVWR, Engine Brake, 244 in Wheelbase, Spring Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 322,648 Mi Lot closing time: Thu, Sep 17, 12:28 PM CDT Asset located in: Humble, TX, USA
2481	2007 Peterbilt 378 6x4 T/A Day Cab Truck Tractor S/N: 1XPFDU9XX7D669089 C/W: Located in Lane 30 Spot 13, Cat C13 Engine, 26568 Engine hrs, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Engine Brake, 225 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 651,371 Mi Lot closing time: Thu, Sep 17, 12:28 PM CDT Asset located in: Humble, TX, USA	2484	2002 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD60XX2R889138 C/W: Located in Lane 36 Spot 47, Cummins Engine, Eaton Fuller 18-Speed Manual Transmission, Engine Brake, 240 in Wheelbase, Spring Suspension, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 528,760 Mi Lot closing time: Thu, Sep 17, 12:28 PM CDT Asset located in: Humble, TX, USA
2482	2006 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5DU9XX6D899175 C/W: Located in Lane 31 Spot 22, Cat C13 Engine, 30756 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 210 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 851,231 Mi Lot closing time: Thu, Sep 17, 12:28 PM CDT Asset located in: Humble, TX, USA	2486	2001 Freightliner FLD 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJALAV61PH26074 C/W: Located in Lane 30 Spot 13, Cat C15 475 hp Engine, 2000 US EPA Label, Eaton Fuller RTLO-18918B 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 245 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 277,696 Mi Lot closing time: Thu, Sep 17, 12:29 PM CDT Asset located in: Lake Worth, TX, USA
2482A	2003 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5DB9XX3D589351 C/W: Located in Lane 68 Spot 0, Cat Engine, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 273 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 285 /75R24.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 303,730 Mi Lot closing time: Thu, Sep 17, 12:28 PM CDT Asset located in: Humble, TX, USA	2488	1991 Peterbilt 377 6x4 T/A Day Cab Truck Tractor S/N: 1XPCD29X8MN296714 C/W: Located in Lane 30 Spot 16, Cummins ISL Engine, Eaton Fuller 8-Speed Manual Transmission, 12000 lb Front Axle, 36000 lb Rears, 50000 lb GVWR, 214 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 51,373 Mi Lot closing time: Thu, Sep 17, 12:29 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2488A	2009 Mack GU713 6x4 T/A Day Cab Truck Tractor S/N: 1M2AX04Y59M007365 C/W: Mack MP7 370 hp Engine, 2008 US EPA Label, 3639 Engine hrs, Mack 10-Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Engine Brake, 213 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 308,833 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 12:30 PM CDT Asset located in: Oklahoma City, OK, USA	2493A	2008 International 8600 6x4 T/A Day Cab Truck Tractor S/N: 1HSHXHR88J039519 C/W: Located in Lane 31 Spot 15, 27877 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 216 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 615,733 Mi Lot closing time: Thu, Sep 17, 12:31 PM CDT Asset located in: Humble, TX, USA
2492	2006 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJF0DE76LV23525 C/W: Located in Lane 31 Spot 44, Cat C13 335 hp Engine, Eaton Fuller FRLO-15410C-T2 10-Speed Manual Transmission, Engine Brake, 180 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel Usage: 373,504 Km Lot closing time: Thu, Sep 17, 12:30 PM CDT Asset located in: Humble, TX, USA	2496	1992 Volvo Aero WCA 6x4 T/A Day Cab Truck Tractor S/N: 4V1VDBJF0NN649060 C/W: Located in Lane 30 Spot 18, Cummins Engine, Eaton Fuller 10-Speed Manual Transmission, 38000 lb Rears, Differential Lock, 185 in Wheelbase, Spring Suspension, Aluminum Outer Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 12:31 PM CDT Asset located in: Humble, TX, USA
2492A	2007 Freightliner Columbia 112 6x4 T/A Day Cab Truck Tractor S/N: 1FUJF0CV97DX48882 C/W: Located in Lane 31 Spot 29, Mercedes-Benz OM460LA 450 hp Engine, 2006 US EPA Label, 15140 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 192 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 293,174 Mi Lot closing time: Thu, Sep 17, 12:30 PM CDT Asset located in: Humble, TX, USA	2499	2021 Kenworth T880 6x4 T/A Sleeper Truck Tractor S/N: 1XKZD40X6MJ440602 C/W: Located in Lane 26 Spot 21, Cummins X15 525 hp Engine, 2020 US EPA Label, 20967 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Engine Brake, Double Differential Locks, 62 in Flat Top Sleeper Cab, Bunk Heater, 260 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 261,378 Mi Lot closing time: Thu, Sep 17, 12:32 PM CDT Asset located in: Humble, TX, USA
2492B	2007 Freightliner Columbia 112 6x4 T/A Day Cab Truck Tractor S/N: 1FUJF0CV07DX48883 C/W: Located in Lane 30 Spot 6, Mercedes-Benz OM460LA 450 hp Engine, 2006 US EPA Label, 16946 Engine hrs, Eaton Fuller Manual Transmission, Engine Brake, 190 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 284,461 Mi Lot closing time: Thu, Sep 17, 12:30 PM CDT Asset located in: Humble, TX, USA	2500	2021 Kenworth T880 6x4 T/A Sleeper Truck Tractor S/N: 1XKZD40X7MJ440589 C/W: Located in Lane 26 Spot 10, Cummins X15 525 hp Engine, 2020 US EPA Label, 23203 Engine hrs, Eaton Fuller RTLO-1891 18-Speed Manual, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Engine Brake, Double Differential Locks, 50 in Mid Roof Sleeper Cab, Bunk Beds, 268 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 344,253 Mi Lot closing time: Thu, Sep 17, 12:32 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2501	2021 Kenworth T880 6x4 T/A Sleeper Truck Tractor S/N: 1XKZD40X5MJ440610 C/W: Located in Lane 26 Spot 25, Cummins X15 525 hp Engine, 2020 US EPA Label, Eaton Fuller RTLO-1891 18-Speed Manual, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Engine Brake, Double Differential Locks, 62 in Mid Roof Sleeper Cab, Bunk Heater, 264 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 302,156 Mi Lot closing time: Thu, Sep 17, 12:32 PM CDT Asset located in: Humble, TX, USA	2506	2020 Kenworth T880 6x4 T/A Sleeper Truck Tractor S/N: 1XKZDP9X7LJ308290 C/W: Located in Lane 27 Spot 34, Cummins X15 400 hp Engine, 2017 US EPA Label, 9150 Engine hrs, Paccar PO-18F112 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 28 in Flat Top Sleeper Cab, 215 in Wheelbase, 8-Bag Air Suspension, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 516,679 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 12:33 PM CDT Asset located in: Humble, TX, USA
2502	2021 Kenworth T880 6x4 T/A Sleeper Truck Tractor S/N: 1XKZD40X0MJ440577 C/W: Located in Lane 26 Spot 27, Cummins X15 525 hp Engine, Engine Coolant Heater, 2020 US EPA Label, 20688 Engine hrs, Eaton Fuller RTLO-1891 18-Speed Manual, 23000 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Engine Brake, Double Differential Locks, 62 in High Rise Sleeper Cab, 261 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 224,602 Mi Lot closing time: Thu, Sep 17, 12:33 PM CDT Asset located in: Humble, TX, USA	2507	2015 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDD49X6FJ442835 C/W: Located in Lane 29 Spot 43, Cummins ISX 450 hp Engine, 27928 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 62 in Mid Roof Sleeper Cab, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 285/75R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 902,383 Mi Lot closing time: Thu, Sep 17, 12:34 PM CDT Asset located in: Humble, TX, USA
2503	2021 Kenworth T880 6x4 T/A Sleeper Truck Tractor S/N: 1XKZD40X8MJ440570 C/W: Located in Lane 26 Spot 48, Cummins X15 525 hp Engine, 2020 US EPA Label, 20913 Engine hrs, Eaton Fuller RTLO-1891 18-Speed Manual, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Engine Brake, Double Differential Locks, 42 in Mid Roof Sleeper Cab, 268 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 506,057 Mi Lot closing time: Thu, Sep 17, 12:33 PM CDT Asset located in: Humble, TX, USA	2508	2023 Peterbilt 567 6x4 T/A Sleeper Truck Tractor S/N: 1XPCD40X1PD829926 C/W: Located in Lane 27 Spot 23, Cummins X15 525 hp Engine, 2022 US EPA Label, 9572 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Engine Brake, Double Differential Locks, 48 in Mid Roof Sleeper Cab, 265 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Double Frame, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 152,769 Mi Notes: This unit is being sold with a rebuilt salvage title. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 12:34 PM CDT Asset located in: Humble, TX, USA
2504	2021 Kenworth T880 6x4 T/A Sleeper Truck Tractor S/N: 1XKZD40X7MJ440608 C/W: Located in Lane 26 Spot 21, Cummins X15 525 hp Engine, 2020 US EPA Label, Eaton Fuller RTLO-1891 18-Speed Manual, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Engine Brake, Differential Lock, 62 in Mid Roof Sleeper Cab, Bunk Heater, 264 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 349,693 Mi Lot closing time: Thu, Sep 17, 12:33 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2510	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3FD269815 C/W: Cummins ISX15 450 hp Engine, 2014 US EPA Label, 28179 Engine hrs, Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 246 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 555,213 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:34 PM CDT Asset located in: San Antonio, TX, USA	2514	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X4FD269810 C/W: Cummins Engine, 28342 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, 243 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 633,041 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:35 PM CDT Asset located in: San Antonio, TX, USA
2511	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X1FD269814 C/W: Cummins ISX15 450 hp Engine, 2014 US EPA Label, 26486 Engine hrs, Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 246 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 589,455 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:35 PM CDT Asset located in: San Antonio, TX, USA	2515	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X7FD269817 C/W: Cummins ISX15 450 hp Engine, 2014 US EPA Label, 30066 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 246 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 638,056 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:36 PM CDT Asset located in: San Antonio, TX, USA
2512	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X6FD269811 C/W: Cummins ISX15 Engine, 2014 US EPA Label, 26947 Engine hrs, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, 245 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 630,540 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:35 PM CDT Asset located in: San Antonio, TX, USA	2516	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X8FD269812 C/W: Cummins ISX15 450 hp Engine, 2014 US EPA Label, 30813 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Mid Roof Sleeper Cab, 242 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 675,526 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:36 PM CDT Asset located in: San Antonio, TX, USA
2513	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X9FD269818 C/W: Cummins ISX15 450 hp Engine, 2014 US EPA Label, 31230 Engine hrs, Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 246 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 633,389 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:35 PM CDT Asset located in: San Antonio, TX, USA	2517	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X5FD269816 C/W: Cummins ISX15 450 kW Engine, 2014 US EPA Label, 29425 Engine hrs, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Mid Roof Sleeper Cab, 242 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel Usage: 641,943 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:36 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
2518	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49XXFD269813 C/W: Cummins ISX15 Engine, 2014 US EPA Label, 32725 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 246 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 680,569 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 12:36 PM CDT Asset located in: San Antonio, TX, USA	2527	2015 Peterbilt 365 6x4 T/A Sleeper Truck Tractor S/N: 1XPSD79X4FD263727 C/W: Located in Lane 38 Spot 15, Cummins ISX12 425 hp Engine, 2014 US EPA Label, 14820.3 Engine hrs, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 226 in Wheelbase, Air Suspension, 11R22.5, Dual Fuel Tanks, Headache Rack Usage: 263,074 Mi Lot closing time: Thu, Sep 17, 12:38 PM CDT Asset located in: Lake Worth, TX, USA
2521	2014 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X7ED248075 C/W: Located in Lane 27 Spot 36, Cummins ISX15 485 hp Engine, 2013 US EPA Label, 32238 Engine hrs, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 63 in Mid Roof Sleeper Cab, 265 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Wet Kit, Dual Fuel Tanks Usage: 884,539 Mi Lot closing time: Thu, Sep 17, 12:37 PM CDT Asset located in: Humble, TX, USA	2528	2015 Peterbilt 365 6x4 T/A Sleeper Truck Tractor S/N: 1XPSD79X2FD263757 C/W: Located in Lane 38 Spot 8, Cummins ISX12 425 hp Engine, 2014 US EPA Label, 14659 Engine hrs, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 226 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Lowboy Ramps Usage: 239,164 Mi Lot closing time: Thu, Sep 17, 12:39 PM CDT Asset located in: Lake Worth, TX, USA
2523	2011 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXDB9X2BD122366 C/W: Located in Lane 27 Spot 44, Cat C15 Engine, 3858 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, Double Differential Locks, 63 in Mid Roof Sleeper Cab, Bunk Beds, 260 in Wheelbase, Air Suspension, Aluminum Wheels, 285/75R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 1,296,688 Mi Lot closing time: Thu, Sep 17, 12:37 PM CDT Asset located in: Humble, TX, USA	2528A	2021 Mack Pinnacle 6x4 T/A Sleeper Truck Tractor S/N: 1M1PN4GY7MM007870 C/W: Mack MP8 Engine, 2020 US EPA Label, 19765 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 11320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, 36 in Flat Top Sleeper Cab, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 430,901 Mi Lot closing time: Thu, Sep 17, 12:39 PM CDT Asset located in: Midland, TX, USA
2526	2015 Peterbilt 365 6x4 T/A Sleeper Truck Tractor S/N: 1XPSD79X5FD276261 C/W: Cummins ISX12 425 hp Engine, 2014 US EPA Label, 15232.5 Engine hrs, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 48 in Flat Top Sleeper Cab, 226 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Usage: 215,650 Mi Lot closing time: Thu, Sep 17, 12:38 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2530	2014 Freightliner Coronado 122SD 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGND62EDFW3802 C/W: Located in Lane 29 Spot 38, Detroit DD15 505 hp Engine, 2014 US EPA Label, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Engine Brake, Differential Lock, 48 in Flat Top Sleeper Cab, 240 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295 /75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 1,114,087 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 12:39 PM CDT Asset located in: Humble, TX, USA	2536	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7MD765645 C/W: Paccar MX-13 455 hp Engine, 2020 US EPA Label, 21256.7 Engine hrs, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 68 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 699,468 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 12:40 PM CDT Asset located in: Laredo, TX, USA
2533A	2022 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X3ND788663 C/W: Located in Lane 26 Spot 8, Cummins X15 500 hp Engine, 2021 US EPA Label, 4644 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 58 in High Rise Sleeper Cab, 248 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 499,696 Mi Notes: This title is branded as not actual mileage and rebuilt salvage title. Lot closing time: Thu, Sep 17, 12:40 PM CDT Asset located in: Humble, TX, USA	2537	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X0MD765647 C/W: Paccar MX-13 455 hp Engine, 2020 US EPA Label, 12.7 Engine hrs, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 68 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 706,658 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 12:41 PM CDT Asset located in: Laredo, TX, USA
2535	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X2MD765648 C/W: Paccar MX-13 455 hp Engine, 2020 US EPA Label, 20738.7 Engine hrs, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 68 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 584,648 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 12:40 PM CDT Asset located in: Laredo, TX, USA	2538	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X2MD765651 C/W: Paccar MX-13 455 hp Engine, 2020 US EPA Label, 2077.9 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 68 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 824,400 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 12:41 PM CDT Asset located in: Laredo, TX, USA

Lot #	Details	Lot #	Details
2539	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X4MD765652 C/W: Paccar Engine, 22269.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 68 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 869,583 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 12:41 PM CDT Asset located in: Laredo, TX, USA	2542	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7KD489559 C/W: Paccar MX-13 455 hp Engine, 2018 US EPA Label, Automated Transmission, 13200 lb Front Axle, 36000 lb Rears, 51200 lb GVWR, Engine Brake, 68 in Mid Roof Sleeper Cab, Bunk Beds, Bunk Heater, 238 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 12:42 PM CDT Asset located in: Midland, TX, USA
2540	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X5MD765644 C/W: Paccar MX-13 455 hp Engine, 2020 US EPA Label, 21.4 Engine hrs, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 68 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks, On-Board Scale Usage: 1,004,853 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 12:41 PM CDT Asset located in: Laredo, TX, USA	2543	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2KD603823 C/W: Located in Lane 27 Spot 42, Cummins X15 450 hp Engine, 2018 US EPA Label, 19180 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 63 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 234 in Wheelbase, Air Suspension, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 668,489 Mi Lot closing time: Thu, Sep 17, 12:42 PM CDT Asset located in: Humble, TX, USA
2541	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X9KD611466 C/W: Located in Lane 60 Spot 3, Paccar MX-13 455 hp Engine, 2018 US EPA Label, 18842 Engine hrs, 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 68 in Mid Roof Sleeper Cab, 237 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 434,755 Mi Notes: Buyers in the states of AZ, FL, NE, NY, PA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 12:42 PM CDT Asset located in: Humble, TX, USA	2544	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X1KD236141 C/W: Located in Lane 28 Spot 6, Paccar MX-13 455 hp Engine, 2018 US EPA Label, 20388 Engine hrs, Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Engine Brake, 68 in Mid Roof Sleeper Cab, Bunk Beds, 231 in Wheelbase, Air Suspension, Aluminum Wheels, 275/80R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 729,447 Mi Lot closing time: Thu, Sep 17, 12:42 PM CDT Asset located in: Humble, TX, USA
		2544A	2024 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X0RJ369600 C/W: Cummins X15 450 hp Engine, 2023 US EPA Label, 5445 Engine hrs, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 75 in High Rise Sleeper Cab, Bunk Beds, Thermo King Sleeper Air Conditioner, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 231,898 Mi Notes: Temporary tags will not be issued; Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 12:43 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
2546	2024 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X7RJ363860 C/W: Cummins X15 450 hp Engine, 2023 US EPA Label, 5261 Engine hrs, Eaton Fuller EEO-xxF112C 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 76 in High Rise Sleeper Cab, Bunk Beds, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 258,746 Mi Notes: Temporary tags will not be issued; Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 12:43 PM CDT Asset located in: Oklahoma City, OK, USA	2550	2021 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X7MJ470711 C/W: Located in Lane 35 Spot 6, Paccar Engine, 2020 US EPA Label, Paccar PO-16F112C 12-Speed Automated, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 277 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 151,257 Mi Lot closing time: Thu, Sep 17, 12:44 PM CDT Asset located in: Lake Worth, TX, USA
2547	2024 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X9RJ357722 C/W: Cummins X15 450 hp Engine, 2023 US EPA Label, 7778 Engine hrs, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 75 in High Rise Sleeper Cab, Bunk Heater, Auxiliary Power Unit, Thermo King Sleeper Air Conditioner, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 297,516 Mi Notes: Temporary tags will not be issued; Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 12:43 PM CDT Asset located in: Oklahoma City, OK, USA	2551	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X4LJ395237 C/W: Located in Lane 37 Spot 3, Paccar MX-13 455 hp Engine, 2019 US EPA Label, 951 Engine hrs, Paccar PO-16F112C 12-Speed Automated, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295 /75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 544,637 Mi Lot closing time: Thu, Sep 17, 12:44 PM CDT Asset located in: Lake Worth, TX, USA
2547A	2022 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X0NJ473208 C/W: Located in Lane 37 Spot 3, Paccar Engine, 20598.4 Engine hrs, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 75 in High Rise Sleeper Cab, Bunk Beds, 238 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 385,230 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 12:43 PM CDT Asset located in: Lake Worth, TX, USA	2551A	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X4LJ397991 C/W: Located in Lane 27 Spot 16, Paccar MX-13 455 hp Engine, 2019 US EPA Label, Paccar PO-17F112C Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 62 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 228 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295 /75R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 769,246 Mi Lot closing time: Thu, Sep 17, 12:44 PM CDT Asset located in: Humble, TX, USA
		2552	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9XXKJ233014 C/W: Located in Lane 26 Spot 14, Paccar MX-13 Engine, 440 Engine hrs, Paccar PO-16F112 12-Speed Automated, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 52 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, 250 in Wheelbase, 8-Bag Air Suspension, Aluminum Outer Wheels, 295 /75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 654,211 Mi Lot closing time: Thu, Sep 17, 12:44 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2553	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X6KJ280703 C/W: Located in Lane 26 Spot 45, Cummins X15 450 hp Engine, 18423 Engine hrs, Eaton Fuller EEO-17F112C 12-Speed Automated, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 62 in High Rise Sleeper Cab, Auxiliary Power Unit, 231 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 602,501 Mi Lot closing time: Thu, Sep 17, 12:44 PM CDT Asset located in: Humble, TX, USA	2558	2024 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR9RSVC7141 C/W: Located in Lane 26 Spot 20, Detroit DD15 455 hp Engine, 2023 US EPA Label, Detroit DT12-1650-OHE 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Retarder, 58 in High Rise Sleeper Cab, Bunk Beds, 241 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 122,298 Mi Lot closing time: Thu, Sep 17, 12:46 PM CDT Asset located in: Humble, TX, USA
2554	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X9KJ230071 C/W: Cummins X15 400 hp Engine, Engine Coolant Heater, 2018 US EPA Label, Paccar Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 62 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, 229 in Wheelbase, Air Suspension, Aluminum Wheels, 275/80R22.5, Dual Fuel Tanks Usage: 2,123,247 Km Lot closing time: Thu, Sep 17, 12:45 PM CDT Asset located in: Livingston, LA, USA	2560	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5NSNF3732 C/W: Located in Lane 38 Spot 8, Detroit DD15 455 hp Engine, 2021 US EPA Label, 17735 Engine hrs, Detroit DT12-1750-DHE 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 226 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 392,836 Mi Lot closing time: Thu, Sep 17, 12:46 PM CDT Asset located in: Lake Worth, TX, USA
2556	2019 Mack AN64T 6x4 T/A Sleeper Truck Tractor S/N: 1M1AN3GY2KM005604 C/W: Located in Lane 38 Spot 11, Mack MP8 415 hp Engine, 2018 US EPA Label, 21596 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 210 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 584,147 Mi Lot closing time: Thu, Sep 17, 12:45 PM CDT Asset located in: Lake Worth, TX, USA	2561	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8NSNF3725 C/W: Located in Lane 37 Spot 14, Detroit DD15 455 hp Engine, 7016 Engine hrs, Detroit DT12-1750-DHE 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 226 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 415,915 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:46 PM CDT Asset located in: Lake Worth, TX, USA
2557	2024 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8RSUD4496 C/W: Located in Lane 37 Spot 13, Detroit DD15 505 hp Engine, 2023 US EPA Label, 16355 Engine hrs, Detroit DT12-1750-OHE 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 229 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 685,218 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:45 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2562	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3NSNS1379 C/W: Located in Lane 27 Spot 3, Detroit DD15 475 hp Engine, 2021 US EPA Label, 18512 Engine hrs, Detroit DT12-1650-OHE 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Retarder, 60 in High Rise Sleeper Cab, Bunk Beds, 229 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 447,842 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:47 PM CDT Asset located in: Humble, TX, USA	2565	2022 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2NSNF3722 C/W: Located in Lane 27 Spot 18, US EPA Label, Retarder, Aluminum Outer Wheels, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 498,140 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:47 PM CDT Asset located in: Humble, TX, USA
2563	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6NSNX7722 C/W: Located in Lane 26 Spot 18, Detroit DD15 455 hp Engine, 2022 US EPA Label, 19213 Engine hrs, Detroit DT12-1650-OH 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Retarder, 70 in High Rise Sleeper Cab, Bunk Beds, 231 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 483,413 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:47 PM CDT Asset located in: Humble, TX, USA	2566	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR4NSNF3723 C/W: Located in Lane 27 Spot 13, Detroit DD15 455 hp Engine, 2021 US EPA Label, 23110 Engine hrs, Detroit DT12-1750-DHE Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, 58 in High Rise Sleeper Cab, Bunk Beds, 225 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 527,842 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:47 PM CDT Asset located in: Humble, TX, USA
2564	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2NSNF3736 C/W: Located in Lane 27 Spot 17, Detroit DD15 455 hp Engine, 2021 US EPA Label, 20059 Engine hrs, Detroit DT12-1750-DHE 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Engine Brake, 48 in High Rise Sleeper Cab, Bunk Beds, 225 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 486,053 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:47 PM CDT Asset located in: Humble, TX, USA	2567	2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3MSMT5083 C/W: Located in Lane 28 Spot 32, Detroit DD15 505 hp Engine, 2020 US EPA Label, 18746 Engine hrs, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Retarder, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 533,328 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:48 PM CDT Asset located in: Humble, TX, USA
		2569	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR0LSLN9367 C/W: Located in Lane 28 Spot 30, Detroit DD15 475 hp Engine, 2019 US EPA Label, 8756 Engine hrs, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 225 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,312 Mi Lot closing time: Thu, Sep 17, 12:48 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2571	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR4LSMD9265 C/W: Located in Lane 35 Spot 5, Detroit DD15 455 hp Engine, 2019 US EPA Label, Detroit DT12-1750-DH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 229 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 819,578 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:49 PM CDT Asset located in: Lake Worth, TX, USA	2574	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR4KLKL0493 C/W: Detroit DD15 505 hp Engine, 2018 US EPA Label, 23164 Engine hrs, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 220 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel Usage: 960,629 Hr Lot closing time: Thu, Sep 17, 12:49 PM CDT Asset located in: Midland, TX, USA
2572	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR0LSMF1378 C/W: Located in Lane 26 Spot 33, Detroit DD15 Engine, 2020 US EPA Label, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Retarder, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 918,938 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 12:49 PM CDT Asset located in: Humble, TX, USA	2575	2020 Freightliner Cascadia 116 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHPDV7LSLF0023 C/W: Located in Lane 26 Spot 3, Detroit DD13 450 hp Engine, 2019 US EPA Label, Detroit DT12-1550-DH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, Bunk Beds, Bunk Heater, 216 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel Usage: 438,036 Mi Lot closing time: Thu, Sep 17, 12:50 PM CDT Asset located in: Humble, TX, USA
2573	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3KSKJ0532 C/W: Located in Lane 26 Spot 11, Detroit DD15 505 hp Engine, 2018 US EPA Label, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Retarder, 70 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 227 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 795,423 Mi Lot closing time: Thu, Sep 17, 12:49 PM CDT Asset located in: Humble, TX, USA	2576	2020 Freightliner Cascadia 116 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHPDVXLSLM3636 C/W: Located in Lane 27 Spot 21, Detroit DD13 450 hp Engine, 2020 US EPA Label, 18553 Engine hrs, Detroit DT12-1550-OH1 HD 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Retarder, 60 in High Rise Sleeper Cab, Bunk Heater, 227 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 577,182 Mi Lot closing time: Thu, Sep 17, 12:50 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2577A	2021 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2MN271980 C/W: Volvo D13M 455 hp Engine, 2021 US EPA Label, 23178.6 Engine hrs, Volvo AT2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 221 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 841,206 Mi Notes: Item at offsite location must be picked up within 14 days of auction (Sept 4 th) or will be subject to 3rd party storage fees ; The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional titling instructions. License plates will not be provided. Lot closing time: Thu, Sep 17, 12:50 PM CDT Asset located in: Laredo, TX, USA	2584	2022 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9NN426633 C/W: Located in Lane 26 Spot 32, Cummins X15 450 hp Engine, 2021 US EPA Label, 15179 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 232 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 403,223 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:52 PM CDT Asset located in: Humble, TX, USA
2582	2023 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR1PN794811 C/W: Located in Lane 26 Spot 38, Cummins X15 450 hp Engine, 2022 US EPA Label, 21352 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, 226 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 678,422 Mi Lot closing time: Thu, Sep 17, 12:51 PM CDT Asset located in: Humble, TX, USA	2585	2022 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR1NN686802 C/W: Located in Lane 26 Spot 12, Cummins X15 450 hp Engine, 2021 US EPA Label, 13029 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in Sleeper Cab, Bunk Beds, 230 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 448,987 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:52 PM CDT Asset located in: Humble, TX, USA
2583	2023 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR8PN680160 C/W: Located in Lane 27 Spot 1, Cummins X15 450 hp Engine, 2022 US EPA Label, 11853 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, 238 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 646,511 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:51 PM CDT Asset located in: Humble, TX, USA	2586	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR1MN256113 C/W: Located in Lane 27 Spot 24, Cummins X15 400 hp Engine, 2020 US EPA Label, 15263 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Double Differential Locks, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 232 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Dual Fuel Tanks Usage: 663,085 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:52 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2588	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR7MN249487 C/W: Located in Lane 28 Spot 33, Cummins X15 400 hp Engine, Engine Coolant Heater, 2020 US EPA Label, 19881 Engine hrs, Tag not found Automated Transmission, Differential Lock, 51 in High Rise Sleeper Cab, Bunk Beds, 232 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Dual Fuel Tanks Usage: 727,929 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:53 PM CDT Asset located in: Humble, TX, USA	2591	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR2MN247792 C/W: Located in Lane 26 Spot 41, Cummins X15 400 hp Engine, 2020 US EPA Label, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 751,964 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:53 PM CDT Asset located in: Humble, TX, USA
2589	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR9MN247773 C/W: Located in Lane 26 Spot 34, Cummins X15 400 hp Engine, 2020 US EPA Label, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Front Wheels, 275/80R22.5, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 738,876 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:53 PM CDT Asset located in: Humble, TX, USA	2593	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR6MN248184 C/W: Located in Lane 26 Spot 35, Cummins X15 Engine, 2020 US EPA Label, 17060 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 229 in Wheelbase, Air Suspension, Aluminum Front Wheels, 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 775,532 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:54 PM CDT Asset located in: Humble, TX, USA
2590	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR2MN249851 C/W: Located in Lane 26 Spot 43, Cummins X15 400 hp Engine, 2020 US EPA Label, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 749,086 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:53 PM CDT Asset located in: Humble, TX, USA	2594	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR3MN253603 C/W: Located in Lane 26 Spot 39, Cummins X15 400 hp Engine, 2020 US EPA Label, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 779,022 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:54 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2596	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR1MN259173 C/W: Located in Lane 26 Spot 28, Cummins X15 400 hp Engine, 2020 US EPA Label, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 783,739 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:54 PM CDT Asset located in: Humble, TX, USA	2602	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3LN166288 C/W: Located in Lane 36 Spot 2, Cummins X15 400 hp Engine, 2019 US EPA Label, 12319 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 579,265 Mi Lot closing time: Thu, Sep 17, 12:56 PM CDT Asset located in: Lake Worth, TX, USA
2597	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR2MN249316 C/W: Located in Lane 26 Spot 40, Cummins X15 400 hp Engine, 2020 US EPA Label, 877 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Differential Lock, 51 in High Rise Sleeper Cab, Bunk Beds, 233 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Dual Fuel Tanks, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 784,335 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:55 PM CDT Asset located in: Humble, TX, USA	2603	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPRXLN808554 C/W: Cummins X15 450 hp Engine, 2019 US EPA Label, 25466 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 56 in High Rise Sleeper Cab, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 697,015 Mi Lot closing time: Thu, Sep 17, 12:56 PM CDT Asset located in: Livingston, LA, USA
2598	2021 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR4MN254646 C/W: Located in Lane 27 Spot 9, Cummins X15 400 hp Engine, 2020 US EPA Label, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, 230 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Dual Fuel Tanks Usage: 784,982 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 12:55 PM CDT Asset located in: Humble, TX, USA	2604	2020 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPR9LN833498 C/W: Located in Lane 0 Spot 0, Cummins X15 400 hp Engine, 2019 US EPA Label, 20583 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in Mid Roof Sleeper Cab, Bunk Beds, Bunk Heater, 231 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Dual Fuel Tanks Usage: 862,568 Mi Lot closing time: Thu, Sep 17, 12:56 PM CDT Asset located in: Humble, TX, USA
2599	2021 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZTZR7MN194122 C/W: Located in Lane 26 Spot 47, International A450MT 450 hp Engine, 2020 US EPA Label, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 485,408 Mi Lot closing time: Thu, Sep 17, 12:55 PM CDT Asset located in: Humble, TX, USA	2605	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR7KN386368 C/W: Located in Lane 38 Spot 5, Cummins X15 450 hp Engine, 2018 US EPA Label, 30613 Engine hrs, Allison Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 802,460 Mi Notes: Selling with a Repossession affidavit and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 12:57 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2606	2019 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKZAPRXKN391829 C/W: Cummins X15 400 hp Engine, 2018 US EPA Label, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 51 in High Rise Sleeper Cab, Bunk Beds, 229 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5, Dual Fuel Tanks Usage: 762,820 Mi Lot closing time: Thu, Sep 17, 12:57 PM CDT Asset located in: Midland, TX, USA	2612	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X6HD440120 C/W: Located in Lane 35 Spot 9, Cummins ISX15 450 hp Engine, 2016 US EPA Label, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Engine Brake, 68 in High Rise Sleeper Cab, 248 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 324,076 Mi Lot closing time: Thu, Sep 17, 12:58 PM CDT Asset located in: Lake Worth, TX, USA
2607	2019 International LT625 6x2 T/A Sleeper Truck Tractor S/N: 3HSKDZAPR3KN391641 C/W: Cummins 400 hp Engine, 2018 US EPA Label, 17240 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Double Differential Locks, 56 in High Rise Sleeper Cab, Auxiliary Power Unit, 230 in Wheelbase, Air Suspension, Aluminum Front Wheels, 12R22.5 Front Tires, 11R22.5 Rear Tires, Dual Fuel Tanks Usage: 698,086 Mi Lot closing time: Thu, Sep 17, 12:57 PM CDT Asset located in: Midland, TX, USA	2613	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X8GD353416 C/W: Paccar MX-13 Engine, 23026 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 63 in Mid Roof Sleeper Cab, 250 in Wheelbase, Air Suspension, Aluminum Wheels, 285/75R24.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 692,051 Mi Lot closing time: Thu, Sep 17, 12:58 PM CDT Asset located in: Humble, TX, USA
2608	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR1KN112597 C/W: Cummins X15 450 hp Engine, 2018 US EPA Label, 19115 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 56 in Mid Roof Sleeper Cab, 226 in Wheelbase, Air Suspension, 295 /75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 727,795 Mi Lot closing time: Thu, Sep 17, 12:57 PM CDT Asset located in: Midland, TX, USA	2613A	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X0GD362173 C/W: Located in Lane 29 Spot 50, Cummins ISX15 450 hp Engine, 2015 US EPA Label, 21776 Engine hrs, Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, Bunk Beds, 240 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Ballrace 5th Wheel, Dual Fuel Tanks Usage: 920,975 Mi Lot closing time: Thu, Sep 17, 12:59 PM CDT Asset located in: Humble, TX, USA
2609	2018 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X5JD473955 C/W: Located in Lane 27 Spot 51, Cummins X15 450 hp Engine, 2017 US EPA Label, 19109 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Engine Brake, 48 in Mid Roof Sleeper Cab, 198 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 505,472 Mi Lot closing time: Thu, Sep 17, 12:58 PM CDT Asset located in: Humble, TX, USA	2614	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD255359 C/W: Located in Lane 38 Spot 22, Cummins ISX15 Engine, 2014 US EPA Label, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 68 in Mid Roof Sleeper Cab, Bunk Beds, 248 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 766,020 Mi Lot closing time: Thu, Sep 17, 12:59 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2614A	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X0JJ184533 C/W: Located in Lane 28 Spot 34, Cummins X15 450 hp Engine, 2017 US EPA Label, 31627 Engine hrs, Eaton Fuller Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 52 in High Rise Sleeper Cab, Bunk Beds, 224 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Dual Fuel Tanks Usage: 1,023,612 Mi Lot closing time: Thu, Sep 17, 12:59 PM CDT Asset located in: Humble, TX, USA	2618	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X6GJ468758 C/W: Located in Lane 38 Spot 20, Paccar MX-13 Engine, 2015 US EPA Label, 36108.9 Engine hrs, Eaton Fuller FO16E310C 10-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, 230 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,283,804 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 01:00 PM CDT Asset located in: Lake Worth, TX, USA
2616	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X7HJ176200 C/W: Cummins ISX15 450 hp Engine, 2016 US EPA Label, 29978 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 62 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, 234 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Dual Fuel Tanks Usage: 1,089,373 Mi Lot closing time: Thu, Sep 17, 12:59 PM CDT Asset located in: Livingston, LA, USA	2620	2013 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKADP8X8DJ345221 C/W: Located in Lane 26 Spot 17, Paccar 455 hp Engine, 20103 Engine hrs, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Engine Brake, 52 in Flat Top Sleeper Cab, 228 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 285 /75R24.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 553,326 Mi Lot closing time: Thu, Sep 17, 01:00 PM CDT Asset located in: Humble, TX, USA
2617	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X8HJ145149 C/W: Located in Lane 27 Spot 47, Paccar MX-13 Engine, Engine Coolant Heater, 1751 Engine hrs, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 52 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 574,419 Mi Lot closing time: Thu, Sep 17, 12:59 PM CDT Asset located in: Humble, TX, USA	2621	2013 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKADP9X3DJ349255 C/W: Paccar MX-13 431 hp Engine, 2012 US EPA Label, 24541.6 Engine hrs, Eaton Fuller RTLO-18913A 13-Speed Manual, 13200 lb Front Axle, 40000 lb Rears, 53000 lb GVWR, 72 in Mid Roof Sleeper Cab, 238 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,013 Mi Lot closing time: Thu, Sep 17, 01:00 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2621A	2013 Kenworth T600 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X6DJ346056 C/W: Located in Lane 29 Spot 26, Cummins Engine, US EPA Label, 36415 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual, 12350 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Engine Brake, 62 in Mid Roof Sleeper Cab, 230 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 295/75R22.5, Dual Fuel Tanks Usage: 1,053,553 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 01:00 PM CDT Asset located in: Humble, TX, USA	2622	2016 Freightliner Columbia 6x4 T/A Sleeper Truck Tractor (Glider Kit) S/N: 3ALXA7CG4GDHA8530 C/W: Located in Lane 29 Spot 29, Detroit Series 60 Engine, 28413 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 232 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295 /75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Glider Kit Usage: 948,555 Mi Lot closing time: Thu, Sep 17, 01:01 PM CDT Asset located in: Humble, TX, USA
2621B	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW09YXDM027376 C/W: Mack MP8 415 hp Engine, 11780 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 215 in Wheelbase, Air Suspension, 11R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Dual Fuel Tanks Usage: 280,801 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 01:01 PM CDT Asset located in: Oklahoma City, OK, USA	2625	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXJSJX8659 C/W: Located in Lane 29 Spot 41, Detroit Engine, 2018 US EPA Label, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, 60 in High Rise Sleeper Cab, Bunk Beds, 233 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 753,177 Mi Lot closing time: Thu, Sep 17, 01:01 PM CDT Asset located in: Humble, TX, USA
2621C	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW09Y9DM027398 C/W: Mack MP8 415 hp Engine, 2012 US EPA Label, 13259 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 48 in Flat Top Sleeper Cab, 214 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 307,593 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 01:01 PM CDT Asset located in: Oklahoma City, OK, USA	2626	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR1JSHF3980 C/W: Located in Lane 28 Spot 24, Detroit Engine, 21168 Engine hrs, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, 72 in High Rise Sleeper Cab, 232 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 684,778 Mi Lot closing time: Thu, Sep 17, 01:01 PM CDT Asset located in: Humble, TX, USA
		2627	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV6JSJT6380 C/W: Located in Lane 26 Spot 29, Detroit DD13 450 hp Engine, 2018 US EPA Label, Eaton Fuller FAO-16810C-EA 10-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 48 in Mid Roof Sleeper Cab, Bunk Heater, 220 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 672,754 Mi Lot closing time: Thu, Sep 17, 01:02 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2627A	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR1JSJN5504 C/W: Located in Lane 28 Spot 25, Detroit DD15 455 hp Engine, 2018 US EPA Label, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Engine Brake, 70 in Mid Roof Sleeper Cab, 236 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Dual Fuel Tanks Usage: Not Available Notes: Odometer does not match age of machine Lot closing time: Thu, Sep 17, 01:02 PM CDT Asset located in: Humble, TX, USA	2633	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR0JSJD3425 C/W: Located in Lane 26 Spot 30, Detroit DD15 455 hp Engine, 2017 US EPA Label, 7784 Engine hrs, Detroit DT12-OA-1650 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Retarder, 70 in High Rise Sleeper Cab, Bunk Heater, 225 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295 /75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 704,491 Mi Lot closing time: Thu, Sep 17, 01:03 PM CDT Asset located in: Humble, TX, USA
2629	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR6JDKD0634 C/W: Located in Lane 27 Spot 27, Detroit DD15 400 hp Engine, 2018 US EPA Label, 11242 Engine hrs, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Retarder, 70 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 226 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 607,491 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal Lot closing time: Thu, Sep 17, 01:02 PM CDT Asset located in: Humble, TX, USA	2634	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR1HSJA6888 C/W: Located in Lane 26 Spot 19, Detroit DD15 475 hp Engine, 2017 US EPA Label, Detroit DT12-OA-1650 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Retarder, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 228 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 780,208 Mi Notes: Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 01:03 PM CDT Asset located in: Humble, TX, USA
2631	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR1JSJZ3122 C/W: Located in Lane 65 Spot 0, Detroit DD15 455 hp Engine, 2018 US EPA Label, Detroit DT12-OA-1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Retarder, 58 in Mid Roof Sleeper Cab, Bunk Heater, 236 in Wheelbase, Air Suspension, 12R22.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 01:03 PM CDT Asset located in: Humble, TX, USA	2635	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR2HSHR0387 C/W: Located in Lane 100 Spot 8, Detroit DD15 505 hp Engine, 2016 US EPA Label, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 230 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Additional Component in Office - CPC Lot closing time: Thu, Sep 17, 01:04 PM CDT Asset located in: Lake Worth, TX, USA
		2636	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR3HSJD5146 C/W: Located in Lane 27 Spot 25, Detroit DD15 Engine, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Differential Lock, 48 in Mid Roof Sleeper Cab, 235 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Dual Fuel Tanks Usage: 702,353 Mi Lot closing time: Thu, Sep 17, 01:04 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2637	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV5HSHW9546 C/W: Located in Lane 27 Spot 46, Detroit DD15 450 hp Engine, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 60 in Mid Roof Sleeper Cab, 230 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 674,684 Mi Lot closing time: Thu, Sep 17, 01:04 PM CDT Asset located in: Humble, TX, USA	2641	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV6FLGM6346 C/W: Detroit DD13 435 hp Engine, 26176 Engine hrs, Eaton Fuller FO-16E310C-LAS Ultrashift Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 60 in Mid Roof Sleeper Cab, 212 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 743,077 Mi Notes: Additional Components Available in Office - CPC Lot closing time: Thu, Sep 17, 01:05 PM CDT Asset located in: Lake Worth, TX, USA
2638	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD51GLHK3206 C/W: Detroit DD15 455 hp Engine, 2016 US EPA Label, 18682 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, 60 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, 228 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 609,826 Mi Lot closing time: Thu, Sep 17, 01:04 PM CDT Asset located in: Livingston, LA, USA	2642	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG3FSGA3765 C/W: Located in Lane 29 Spot 12, Cummins ISX15 450 hp Engine, 2014 US EPA Label, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 58 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 898,447 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal Lot closing time: Thu, Sep 17, 01:05 PM CDT Asset located in: Humble, TX, USA
2640	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD56GLHM4715 C/W: Located in Lane 27 Spot 28, Detroit DD15 455 hp Engine, 2016 US EPA Label, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, 222 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 452,846 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal Lot closing time: Thu, Sep 17, 01:05 PM CDT Asset located in: Humble, TX, USA	2643	2015 Freightliner Cascadia 125 6x2 T/A Sleeper Truck Tractor S/N: 1FUGGLDV3FLGL0101 C/W: Located in Lane 27 Spot 4, Detroit DD15 Engine, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel Usage: 714,652 Mi Lot closing time: Thu, Sep 17, 01:05 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2644	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD60FSGE7856 C/W: Located in Lane 0 Spot 0, Detroit DD15 Engine, 2014 US EPA Label, 32366.8 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 60 in Mid Roof Sleeper Cab, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Dual Fuel Tanks Usage: 734,450 Mi Lot closing time: Thu, Sep 17, 01:06 PM CDT Asset located in: Humble, TX, USA	2650	2013 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor (Glider Kit) S/N: 3ALXA7CG5DDFD3703 C/W: Located in Lane 28 Spot 44, Detroit 500 hp Engine, Eaton Fuller FR-FRO 10-Speed Manual Transmission, 12000 lb Front Axle, Engine Brake, 60 in High Rise Sleeper Cab, Bunk Heater, 235 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,296,695 Mi Notes: This asset is being sold with a salvage title. No plates.Assets must be hauled off the yard and cannot be driven. Tags will not be issued. Lot closing time: Thu, Sep 17, 01:07 PM CDT Asset located in: Humble, TX, USA
2645	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD68ELFK7348 C/W: Detroit DD15 455 hp Engine, 2013 US EPA Label, 19358 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Differential Lock, 60 in Mid Roof Sleeper Cab, 220 in Wheelbase, Air Suspension, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 717,684 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 01:06 PM CDT Asset located in: Oklahoma City, OK, USA	2651	2018 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH8JN899554 C/W: Located in Lane 26 Spot 44, Volvo D13M Engine, 2017 US EPA Label, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 61 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 224 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 549,746 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 01:07 PM CDT Asset located in: Humble, TX, USA
2646	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD62ESFW1564 C/W: Detroit DD15 455 hp Engine, 2013 US EPA Label, 19836 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Engine Brake, Differential Lock, 72 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, 11R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Dual Fuel Tanks Usage: 693,829 Mi Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 01:06 PM CDT Asset located in: Oklahoma City, OK, USA	2653	2016 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH9GN944283 C/W: Located in Lane 26 Spot 22, Volvo D13 455 hp Engine, 2016 US EPA Label, Volvo ATO2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Engine Brake, 61 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 237 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 898,496 Mi Lot closing time: Thu, Sep 17, 01:08 PM CDT Asset located in: Humble, TX, USA
2647	2017 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGHDXHSHY8798 C/W: Located in Lane 38 Spot 17, Detroit DD13 450 hp Engine, 2018 US EPA Label, 27813 Engine hrs, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 60 in High Rise Sleeper Cab, Bunk Beds, 209 in Wheelbase, Air Suspension, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Lowboy Ramps Usage: 872,836 Mi Notes: Additional Components Available in Office - CPC Lot closing time: Thu, Sep 17, 01:06 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2653A	2015 Volvo VNL670 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6FN926046 C/W: Located in Lane 100 Spot 1, Volvo D13J 455 hp Engine, 2014 US EPA Label, 92838 Engine hrs, Volvo AT2612D 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 979,137 Mi Lot closing time: Thu, Sep 17, 01:08 PM CDT Asset located in: Lake Worth, TX, USA	2656A	2015 International LoneStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSCXAPR0FN650893 C/W: Located in Lane 29 Spot 27, Cummins ISX15 450 hp Engine, 2014 US EPA Label, 20844 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 56 in Mid Roof Sleeper Cab, Bunk Beds, 208 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 753,316 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 01:09 PM CDT Asset located in: Humble, TX, USA
2654	2014 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2EN173727 C/W: Located in Lane 28 Spot 7, Detroit Engine, 8150 Engine hrs, Volvo AT02612D 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Engine Brake, 77 in High Rise Sleeper Cab, Auxiliary Power Unit, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 904,998 Mi Lot closing time: Thu, Sep 17, 01:08 PM CDT Asset located in: Humble, TX, USA	2657	2015 International ProStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR2FN668849 C/W: Located in Lane 29 Spot 28, Cummins ISX15 450 hp Engine, 22989 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 56 in Mid Roof Sleeper Cab, 250 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 350,612 Mi Lot closing time: Thu, Sep 17, 01:09 PM CDT Asset located in: Humble, TX, USA
2655	2012 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6CN534471 C/W: Located in Lane 36 Spot 1, Volvo D13 425 hp Engine, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 214 in Wheelbase, Air Suspension, Aluminum Front Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,332,419 Mi Lot closing time: Thu, Sep 17, 01:08 PM CDT Asset located in: Lake Worth, TX, USA	2658	2011 International ProStar Premium 6x4 T/A Sleeper Truck Tractor S/N: 3HSCUSJR5BN363924 C/W: Located in Lane 29 Spot 39, 19721 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 51 in Mid Roof Sleeper Cab, 230 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 437,376 Mi Lot closing time: Thu, Sep 17, 01:09 PM CDT Asset located in: Humble, TX, USA
2655A	2016 International Prostar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR0GN232132 C/W: Located in Lane 27 Spot 32, Cummins ISX15 450 hp Engine, 2015 US EPA Label, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 56 in High Rise Sleeper Cab, Bunk Heater, 231 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Dual Fuel Tanks Usage: 944,766 Mi Lot closing time: Thu, Sep 17, 01:08 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2659	2007 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5D49X47D742307 C/W: Located in Lane 29 Spot 31, Cummins ISX 565 hp Engine, 6074 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 70 in Mid Roof Sleeper Cab, 271 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,920,522 Mi Lot closing time: Thu, Sep 17, 01:09 PM CDT Asset located in: Humble, TX, USA	2665	2001 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X21N555766 C/W: Located in Lane 0 Spot 0, Cat Engine, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 63 in Mid Roof Sleeper Cab, 260 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 285/75R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 993,345 Mi Lot closing time: Thu, Sep 17, 01:11 PM CDT Asset located in: Humble, TX, USA
2660	2007 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9XX7N664050 C/W: Located in Lane 27 Spot 37, Cat Engine, 17149 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 68 in Mid Roof Sleeper Cab, 261 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,873,865 Mi Lot closing time: Thu, Sep 17, 01:09 PM CDT Asset located in: Humble, TX, USA	2666	1998 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X1WN454886 C/W: Located in Lane 27 Spot 35, Cat Engine, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Engine Brake, 63 in Mid Roof Sleeper Cab, 266 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5 Front Tires, 285 /75R24.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 29,003 Mi Lot closing time: Thu, Sep 17, 01:11 PM CDT Asset located in: Humble, TX, USA
2661	2007 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X97D674560 C/W: Located in Lane 27 Spot 31, Cat C15 Engine, 12640 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, 270 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,309,008 Mi Lot closing time: Thu, Sep 17, 01:10 PM CDT Asset located in: Humble, TX, USA	2667	1997 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB8X6VD429150 C/W: Located in Lane 27 Spot 48, Cat 3406 475 hp Engine, Engine Coolant Heater, Eaton Fuller 10-Speed Manual Transmission, 12001 lb Front Axle, 34004 lb Rears, 46007 lb GVWR, 63 in Mid Roof Sleeper Cab, 246 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 01:11 PM CDT Asset located in: Humble, TX, USA
2661A	2005 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X35N872963 C/W: Located in Lane 27 Spot 30, Cat C15 Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 68 in Mid Roof Sleeper Cab, 270 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 64,543 Mi Lot closing time: Thu, Sep 17, 01:10 PM CDT Asset located in: Humble, TX, USA	2668	2005 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDB9X05J975856 C/W: Located in Lane 27 Spot 12, Cat C15 Engine, Engine Coolant Heater, 1861.8 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, Engine Brake, Differential Lock, 50 in Mid Roof Sleeper Cab, Bunk Beds, 280 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5, Double Frame, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 790,357 Mi Lot closing time: Thu, Sep 17, 01:11 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2669	2002 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDB9X92J891370 C/W: Located in Lane 38 Spot 3, Cat C15 Engine, 2001 US EPA Label, Eaton Fuller 18-Speed Manual Transmission, Engine Brake, 72 in Mid Roof Sleeper Cab, 264 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 731,524 Mi Lot closing time: Thu, Sep 17, 01:12 PM CDT Asset located in: Lake Worth, TX, USA	2672A	2006 Freightliner Columbia 112 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6AV46LV86801 C/W: Cat C15 435 hp Engine, 9216 Engine hrs, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 240 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack, Lowboy Ramps Usage: 1,461,108 Mi Notes: ***Engine overhaul documentation is available and attached for buyer review*** Lot closing time: Thu, Sep 17, 01:12 PM CDT Asset located in: Lake Worth, TX, USA
2670	2007 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDT9X87J187729 C/W: Located in Lane 28 Spot 3, Cat C11 Engine, 21144 Engine hrs, Eaton Fuller Manual Transmission, Engine Brake, 24 in Mid Roof Sleeper Cab, 250 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R24.5, Wet Kit, Dual Fuel Tanks Usage: 237,187 Mi Lot closing time: Thu, Sep 17, 01:12 PM CDT Asset located in: Humble, TX, USA	2675	2018 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48XXJD478286 C/W: Located in Lane 33 Spot 1, Cummins X15 400 hp Engine, 2017 US EPA Label, 21775.8 Engine hrs, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Engine Brake, 157 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,109,889 Mi Lot closing time: Thu, Sep 17, 01:13 PM CDT Asset located in: Lake Worth, TX, USA
2671	2007 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK47LZ12889 C/W: Located in Lane 26 Spot 4, Detroit Series 60 515 hp Engine, 2006 US EPA Label, 23134 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, Engine Brake, 48 in Flat Top Sleeper Cab, 262 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 503,992 Mi Lot closing time: Thu, Sep 17, 01:12 PM CDT Asset located in: Humble, TX, USA	2676	2019 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48XXKD600128 C/W: Located in Lane 68 Spot 0, Cummins X15 400 hp Engine, 2018 US EPA Label, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Engine Brake, 160 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 737,359 Mi Lot closing time: Thu, Sep 17, 01:13 PM CDT Asset located in: Humble, TX, USA
2672	2005 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK85LV43256 C/W: Located in Lane 27 Spot 50, Detroit Series 60 455 hp Engine, 2005 US EPA Label, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 58 in High Rise Sleeper Cab, Bunk Beds, 242 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 962,214 Mi Lot closing time: Thu, Sep 17, 01:12 PM CDT Asset located in: Humble, TX, USA	2677	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X3GD339559 C/W: Located in Lane 33 Spot 4, Cummins ISX15 400 hp Engine, 2015 US EPA Label, 15457.7 Engine hrs, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Engine Brake, 160 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 717,794 Mi Lot closing time: Thu, Sep 17, 01:13 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2679A	2011 Peterbilt 337 4x2 S/A Day Cab Truck Tractor S/N: 2XP2AN8X6BM126369 C/W: Located in Lane 32 Spot 41, Paccar PX-8 300 hp Engine, 2010 US EPA Label, 9916 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Engine Brake, 160 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5 Front Tires, 275/80R22.5 Rear Tires Usage: 181,498 Mi Lot closing time: Thu, Sep 17, 01:14 PM CDT Asset located in: Humble, TX, USA	2687	2018 International Prostar+ 113 4x2 S/A Day Cab Truck Tractor S/N: 3HSDSNN2JN590916 C/W: Located in Lane 33 Spot 11, Navistar N13 390 hp Engine, 2017 US EPA Label, 12081 Engine hrs, Eaton Fuller Ultrashift Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 154 in Wheelbase, Air Suspension, 295/75R22.5, Dual Fuel Tanks Usage: 264,464 Mi Lot closing time: Thu, Sep 17, 01:16 PM CDT Asset located in: Lake Worth, TX, USA
2683	2016 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55GLGY0824 C/W: Located in Lane 32 Spot 46, Detroit DD15 278 hp Engine, Engine Coolant Heater, 2017 US EPA Label, 14631.6 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Engine Brake, 158 in Wheelbase, Air Suspension, 11R22.5 Usage: 732,975 Mi Lot closing time: Thu, Sep 17, 01:15 PM CDT Asset located in: Humble, TX, USA	2688	2018 International LT625 4x2 S/A Day Cab Truck Tractor S/N: 1HSDYAPR7JH698265 C/W: Located in Lane 68 Spot 0, Cummins X15 400 hp Engine, 2017 US EPA Label, Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, 35050 lb GVWR, Engine Brake, 156 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 697,770 Mi Lot closing time: Thu, Sep 17, 01:16 PM CDT Asset located in: Humble, TX, USA
2684	2015 Freightliner Cascadia 113 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGBDV1FLGD8357 C/W: Located in Lane 33 Spot 12, Detroit DD13 410 hp Engine, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Engine Brake, 189 in Wheelbase, Air Suspension, 295/75R22.5, Dual Fuel Tanks Usage: Not Available Notes: Additional Components in Office - CPC Lot closing time: Thu, Sep 17, 01:15 PM CDT Asset located in: Lake Worth, TX, USA	2689	2018 International LT625 4x2 S/A Day Cab Truck Tractor S/N: 1HSDYAPR9JH698266 C/W: Located in Lane 67 Spot 0, Cummins X15 400 hp Engine, 2017 US EPA Label, 16366 Engine hrs, Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, 35050 lb GVWR, Engine Brake, 156 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 705,379 Mi Lot closing time: Thu, Sep 17, 01:16 PM CDT Asset located in: Humble, TX, USA
2685	2018 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCXFE1JDJM7666 C/W: Located in Lane 33 Spot 5, Cummins L9 Engine, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 168 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 289,198 Mi Notes: This unit is being sold with a rebuilt salvage-loss unknown title. Lot closing time: Thu, Sep 17, 01:15 PM CDT Asset located in: Lake Worth, TX, USA	2690	2009 Kenworth T370 4x2 S/A Day Cab Truck Tractor S/N: 2XKHAN8X49M941695 C/W: Located in Lane 32 Spot 49, Paccar PX-8 330 hp Engine, 2008 US EPA Label, 5112 Engine hrs, Allison 3000HS Automatic, 11997 lb Front Axle, 22994 lb Rears, 34991 lb GVWR, Engine Brake, Differential Lock, 126 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 92,224 Mi Lot closing time: Thu, Sep 17, 01:16 PM CDT Asset located in: Humble, TX, USA
		2692	2004 Ottawa 4x2 Spotter Truck S/N: 309592 C/W: Located in Lane 33 Spot 10, 6 Cylinder Engine, 2936.3 Engine hrs, Automatic Transmission, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Double Frame, 115 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 138,727 Mi Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Thu, Sep 17, 01:17 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2693	2017 Autocar 4x2 Spotter Truck S/N: 516H4GB25HH222085 C/W: Located in Lane 32 Spot 47, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10451 Engine hrs, Allison Automatic Transmission, 10R22.5 Front Tires, 295/75R22.5 Rear Tires, 104 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Thu, Sep 17, 01:17 PM CDT Asset located in: Humble, TX, USA	2698	2013 Volvo VAH 6x4 Sleeper Car Carrier Truck S/N: 4V4RC9EJ2DN143372 C/W: Located in Lane 9 Spot 19, Volvo D13H475 12.8 L Diesel 475 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-17210C 10-Speed Manual Transmission, 14600 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 52600 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295/60R22.5 Front Tires, 265/70R19.5 Rear Tires, Air Ride Suspension, 9 Vehicle Capacity, Hydraulic Lift, Soft Tie Downs Usage: 871,064 Mi Lot closing time: Thu, Sep 17, 01:18 PM CDT Asset located in: Humble, TX, USA
2694	2021 Autocar 4x2 Spotter Truck S/N: 516G4GF21MH234864 C/W: Located in Lane 32 Spot 50, Cummins B6.7 6.7 L Diesel 200 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 15440 Engine hrs, Allison Automatic Transmission, 12300 lb Front Axle, 22700 lb Rears, 35000 lb GVWR, 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, 115 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 68,464 Mi Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** Lot closing time: Thu, Sep 17, 01:17 PM CDT Asset located in: Humble, TX, USA	2699	2016 Peterbilt 579 6x2 Sleeper Tow Truck S/N: 1NPBH77X2GD325662 C/W: Located in Lane 46 Spot 2, Cummins ISX12 11.9 cid Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 24299 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 13200 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Steerable Air Lift Pusher Axle, Air Trac Air Ride Suspension, 360 in Wheelbase, Aluminum Wrecker Body, 25000 lb Winch Capacity, Air Compressor Usage: 660,154 Mi Lot closing time: Thu, Sep 17, 01:19 PM CDT Asset located in: Lake Worth, TX, USA
2696	2018 Volvo VAH 6x4 Car Carrier Truck S/N: 4V5RC9DHXJN970543 C/W: Located in Lane 43 Spot 10, Volvo D11M 10.8 L Diesel 425 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F Automated Transmission, 14600 lb Front Axle, 38000 lb Rears, 47000 lb GVWR, Aluminum Wheels, 295/60R22.5, Air Ride Suspension, 253 in Wheelbase, 3 Vehicle Capacity, Soft Tie Downs, SOLD WITH - 2017 Cottrel CX-09LSFA T/A, Trailer S/N - 5E0AA1649JG015302, Soft Ties, Aluminum Wheels, 265/70R19.5 Tires, 47000 lb GVWR Usage: 910,867 Mi Lot closing time: Thu, Sep 17, 01:18 PM CDT Asset located in: Lake Worth, TX, USA	2700	2007 Western Star 4900 8x6 Sleeper Tow Truck S/N: 5KKRALCK97PY60773 C/W: Located in Lane 46 Spot 1, Detroit Series 60 6 Cylinder Diesel Engine, 2006 US EPA Label, 21980.2 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 18740 lb Front Axle, 53000 lb Rears, 71741 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Air Ride Suspension, 312 in Wheelbase, Metro Tow Trucks Wrecker Body Usage: 884,795 Mi Lot closing time: Thu, Sep 17, 01:19 PM CDT Asset located in: Lake Worth, TX, USA
2697	2015 Volvo VAH 6x2 Car Carrier Truck S/N: 4V5R99DG1FN184076 C/W: Located in Lane 43 Spot 11, Volvo D11J405 10.8 L Diesel 405 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 14600 lb Front Axle, 38000 lb Rears, 52600 lb GVWR, Aluminum Wheels, 295/60R22.5 Front Tires, 265/70R19.5 Rear Tires, Air Ride Suspension, 251 in Wheelbase, 3 Vehicle Capacity, Soft Tie Downs, SOLD WITH - 2015 Cottrell CX-09LS2 T/A, Trailer S/N - 5E0AA1443GG713805, Soft Ties, Aluminum Wheels, 265/70R19.5 Tires Usage: 784,378 Mi Lot closing time: Thu, Sep 17, 01:18 PM CDT Asset located in: Lake Worth, TX, USA	2701	1993 Freightliner FLD120 6x4 Tow Truck S/N: 1FUYDCXB4PH496652 C/W: Located in Lane 36 Spot 34, Detroit Series 60 11.1 L Diesel 350 hp Engine, 1992 US EPA Label, Rockwell 9-Speed Manual Transmission, Rockwell Drive Axles, Aluminum Front Wheels, 11R22.5, Spring Suspension, 218 in Wheelbase, Steel Wrecker Body Usage: 715,743 Mi Lot closing time: Thu, Sep 17, 01:19 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2702	2016 Freightliner 114SD 6x4 Equipment Transport Truck S/N: 1FVHG3DVXGHGZ0073 C/W: Located in Lane 11 Spot 33, Detroit DD13 450 hp Engine, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 252 in Wheelbase, Air Suspension, 11R22.5, 28 ft 9 in x 102 in Bed, Winch, Hydraulic Ramps Usage: 352,782 Mi Lot closing time: Thu, Sep 17, 01:19 PM CDT Asset located in: Lake Worth, TX, USA	2706	2022 Ram 5500 4x2 Rollback Truck S/N: 3C7WRMDL6NG239599 C/W: Located in Lane 36 Spot 28, Cummins 6 Cylinder 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 204 in Wheelbase, PTO, Jerrdan 20SRR6T-W-LP Rollback Body, 19 ft x 96 in Bed, Ramsey HD234 8000 lb Winch, Hydraulic Wheel Lift Usage: 92,789 Mi Notes: Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 01:20 PM CDT Asset located in: Humble, TX, USA
2702A	2019 Hino 338 4x2 Rollback Truck S/N: 5PVNV8JV3K4S59285 C/W: Located in Lane 36 Spot 6, Hino 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Aluminum Wheels, 275/70R22.5, Spring Suspension, 110 in Wheelbase, PTO, 19 ft 3 in x 96 in Bed, Ramsey 60 Winch, Hydraulic Wheel Lift Usage: 246,074 Mi Lot closing time: Thu, Sep 17, 01:19 PM CDT Asset located in: Humble, TX, USA	2710	Ledwell LW100 BBL VT - LV on 2018 Freightliner 114SD 8x4 Vacuum Excavator Truck S/N: 1FVHG3DV8JHJY9834 C/W: Located in Lane 47 Spot 25, Detroit DD13 12.8 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 18740 lb Front Axle, 59200 lb Rears, 4.10:1 Axle Ratio, 90000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Spring over Walking Beam Suspension, 252 in Wheelbase, PTO, Front Hose Reel, Hydraulic Lift Tailgate, Boom, 8 in Suction Hose, PTO Driven Pump Usage: 109,657 Mi Lot closing time: Thu, Sep 17, 01:21 PM CDT Asset located in: Lake Worth, TX, USA
2704	2022 Ram 5500 4x2 Rollback Truck S/N: 3C7WRMDL3NG239592 C/W: Located in Lane 36 Spot 27, Cummins 6 Cylinder 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 204 in Wheelbase, PTO, Jerrdan 20SRR6T-W-LP Rollback Body, 19 ft x 96 in Bed, Ramsey HD234 8000 lb Winch, Hydraulic Wheel Lift Usage: 32,323 Mi Notes: Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 01:20 PM CDT Asset located in: Humble, TX, USA	2713	2012 Peterbilt 367 6x4 Vacuum Excavator Truck S/N: 1NPTL70X3CD161278 C/W: Located in Lane 33 Spot 4, Cummins ISX11.9 11.9 L Diesel 425 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 13194 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson RT /RTE Series Spring over Walking Beam Suspension, 286 in Wheelbase, Steel Debris Tank, Hoist, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Boom, 8 in Suction Hose, Blower, Remote Control w/Cord Usage: 85,417 Mi Lot closing time: Thu, Sep 17, 01:22 PM CDT Asset located in: Humble, TX, USA
2705	2022 Ram 5500 4x2 Rollback Truck S/N: 3C7WRMDL1NG238280 C/W: Located in Lane 36 Spot 5, Cummins 6 Cylinder 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 204 in Wheelbase, PTO, Jerrdan 20SRR6T-W-LP Rollback Body, 19 ft x 96 in Bed, Ramsey HD234 8000 lb Winch, Hydraulic Wheel Lift Usage: 73,389 Mi Notes: Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 01:20 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2715	2017 Global 176ET on 2012 Freightliner Coronado 122 6x4 Vacuum Tanker Truck S/N: 1FUJGNDR0CDBK3084 C/W: Located in Lane 33 Spot 3, Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Double Differential Locks, Meritor MT-44-14XP Drive Axles, 3.70:1 Axle Ratio, Air Ride Cab, 11R24.5, Air Ride Suspension, 212 in Wheelbase, Steel 3000 gal Debris Tank, TC412 Code, Hoist, Hydraulic Lift Tailgate, Manual Tailgate Locks Usage: Not Available Lot closing time: Thu, Sep 17, 01:22 PM CDT Asset located in: Humble, TX, USA	2719	2007 Kenworth C500 6x4 Sleeper Winch Truck S/N: 1NKCL49X37R930779 C/W: Located in Lane 36 Spot 20, Cummins ISX 6 Cylinder 15 L Diesel 450 hp Engine, US EPA Label, 30032 Engine hrs, Engine Brake, Allison 4700 Automatic Transmission, Double Differential Locks, 23587 lb GVWR, Flat Top Sleeper Cab, Aluminum Outer Wheels, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Assist Front Suspension, Air Ride Suspension, 246 in Wheelbase, PTO, 12 ft x 98 in Bed, Tail Roll, Tulsa Winch Usage: 1,049,251 Km Lot closing time: Thu, Sep 17, 01:23 PM CDT Asset located in: Humble, TX, USA
2716	Vactor RamJet on 2002 Chevrolet C7500 4x2 Sewer Cleaner Truck S/N: 1GBM7H1C42J503620 C/W: Located in Lane 47 Spot 24, Cat 3126 7.2 L Diesel 230 hp Engine, 2001 US EPA Label, Automatic Transmission, 9000 lb Front Axle, 17850 lb Rears, 26850 lb GVWR, 11R22.5, Spring Suspension, 198 in Wheelbase, PTO, Rear Hose Reel, Hydraulic Driven Pump Usage: 23,737 Mi Lot closing time: Thu, Sep 17, 01:22 PM CDT Asset located in: Lake Worth, TX, USA	2720	2013 Kenworth T800 6x4 Winch Truck S/N: 1XKDD40X3DR963765 C/W: Located in Lane 46 Spot 7, Cummins ISX15 6 Cylinder 15 L Diesel 550 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 44083 Engine hrs, Engine Brake, Eaton Fuller RTLO-20918B 18-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Dana D46-170HPW Drive Axles, 4.10:1 Axle Ratio, 66000 lb GVWR, 50 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Neway Air Ride Suspension, 248 in Wheelbase, PTO, Tail Roll Usage: 708,581 Mi Lot closing time: Thu, Sep 17, 01:23 PM CDT Asset located in: Lake Worth, TX, USA
2717	2013 Spiradrill MHD-100 on 2013 Mack GU713 8x4 Drill Truck S/N: 1M2AX04CXDM015510 C/W: Located in Lane 84 Spot 0, John Deere 6068HF285 6.8 L 6 Cylinder Upper Engine, Out and Down Outriggers, Rear Outriggers, US EPA Label, Requires Diesel Exhaust Fluid, Air Ride Cab, Aluminum Front Wheels, Dual Steering Boxes, Double Frame Usage: 159,257 Mi Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** The buyer will need to obtain a bonded title or complete other registration requirements at their own expense. Lot closing time: Thu, Sep 17, 01:23 PM CDT Asset located in: Humble, TX, USA	2721	2013 Kenworth T800 8x6 Winch Truck S/N: 1XKDP4EX5DJ964544 C/W: Located in Lane 46 Spot 7, Cummins ISX15 6 Cylinder 15 L Diesel 525 hp Engine, 2012 US EPA Label, 32483 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Double Differential Locks, 16000 lb Front Axle, 58002 lb Rears, Dana T69-170HP Drive Axles, 4.30:1 Axle Ratio, 74000 lb GVWR, Air Ride Cab, 50 in Flat Top Sleeper Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Neway Air Ride Suspension, 294 in Wheelbase, PTO, Tail Roll, Rufnek Winch Usage: 512,569 Mi Lot closing time: Thu, Sep 17, 01:24 PM CDT Asset located in: Lake Worth, TX, USA
2718	2004 International 7400 6x4 Drill Truck S/N: 1HTWHAAR74J082138 C/W: Located in Lane 36 Spot 46, 4 Cylinder Upper Engine, Straight Down Outriggers, Eaton Fuller 10-Speed Manual Transmission, 2340 Engine hrs, 12R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 216 in Wheelbase Usage: Not Available Lot closing time: Thu, Sep 17, 01:23 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2722	2012 Kenworth T800 6x4 Winch Truck S/N: 1NKDLP0X5CJ317946 C/W: Located in Lane 36 Spot 43, Paccar MX 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 10685 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 3.91:1 Axle Ratio, 66000 lb GVWR, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Rubber over Walking Beam Suspension, 353 in Wheelbase, PTO, 24 ft 6 in x 98 in Bed, Tail Roll, Tulsa winch 80000 lb Winch Usage: 202,135 Mi Lot closing time: Thu, Sep 17, 01:24 PM CDT Asset located in: Humble, TX, USA	2730	2001 AM General M1123 HMMWV 4 Door Soft Top w/Truck Body S/N: 194550 C/W: Located in Lane 18 Spot 3, Air Conditioning, Automatic Transmission, 10300 LB GVWR, 37x12.50R16.5 Tires Usage: 297 Mi Notes: Selling with a Repossession affidavit and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:26 PM CDT Asset located in: Lake Worth, TX, USA
2723	2012 Peterbilt 367 6x4 Winch Truck S/N: 1NPTD40X2CD147450 C/W: Located in Lane 46 Spot 4, Cummins ISX15 6 Cylinder 15 L Diesel 550 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28685 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 46000 lb Rears, 64000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Air Leaf Air Ride Suspension, 248 in Wheelbase, PTO, 0 ft Bed, Tail Roll, Tulsa Winch Winch Usage: 534,779 Mi Lot closing time: Thu, Sep 17, 01:24 PM CDT Asset located in: Lake Worth, TX, USA	2731	2006 AM General M1165A2 HMMWV 4 Door Hard Top w/Truck Body S/N: 226933 C/W: Located in Lane 18 Spot 6, Air Conditioning, Automatic Transmission, 4x4, 38x13.50R20 Tires Usage: 10,029 Mi Notes: Selling with a Repossession affidavit and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:26 PM CDT Asset located in: Lake Worth, TX, USA
2724	2019 International 7300 4x2 Gin Pole Truck S/N: 3HAZZMML8KL095417 C/W: Located in Lane 46 Spot 2, Cummins B6.7 260 6 Cylinder 6.7 L Diesel 260 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9420 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 187 in Wheelbase, 15 ft x 96 in Bed, Tail Roll, 17 ft Gin Poles Usage: 186,993 Mi Lot closing time: Thu, Sep 17, 01:24 PM CDT Asset located in: Lake Worth, TX, USA	2732	2008 Spartan Gladitor 4x2 Crew Cab Fire Truck S/N: 4S7AT2F918C057572 C/W: Located in Lane 43 Spot 5, 9486 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 24000 lb Rears, 44000 lb GVWR, Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2006 US EPA Label, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 216 in Wheelbase, PTO, Spartan Body, PTO Driven Pump Usage: 100,939 Mi Lot closing time: Thu, Sep 17, 01:26 PM CDT Asset located in: Lake Worth, TX, USA
2726	2006 Mack CV713 6x4 Gin Pole Truck S/N: 1M2AG11Y76M038073 C/W: Located in Lane 36 Spot 25, Mack AI 6 Cylinder 11.9 L Diesel 427 hp Engine, 2005 US EPA Label, 16612 Engine hrs, Engine Brake, Eaton Fuller 9-Speed Manual Transmission, Air Ride Cab, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Central Tire Inflation System, Dual Steering Boxes, Double Frame, Spring Suspension, 285 in Wheelbase, PTO, 15 ft 5 in x 86 in Bed, Tail Roll, 20 ft 6 in Gin Poles, Tulsa Winch Usage: 418,847 Mi Lot closing time: Thu, Sep 17, 01:25 PM CDT Asset located in: Humble, TX, USA	2732A	1987 Duplex 4x2 Fire Truck S/N: 1D91D31E7H1008801 C/W: Automatic Transmission, 16000 lb Front Axle, 34000 lb Rears, 40000 lb GVWR, Detroit Diesel Engine, 12.00R20 Front Tires, 11.00R20 Rear Tires, Spring Suspension, 179 in Wheelbase, Duplex 28 ft Body, Waterous Co. CS Pump Usage: 4,784 Mi Lot closing time: Thu, Sep 17, 01:26 PM CDT Asset located in: Midland, TX, USA
		2733	1989 Ford F800 4x4 Fire Truck S/N: 1FDXK84A6KVA55709 C/W: Located in Lane 36 Spot 49, Automatic Transmission, 6 Cylinder Diesel Engine, 10.00 R20, Spring Suspension, 192 in Wheelbase, PTO, 16 ft Body, Hale OLG100-17S PTO Driven Pump Usage: 103,820 Mi Lot closing time: Thu, Sep 17, 01:26 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2734	2013 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACXDT2DDFE2516 C/W: Located in Lane 35 Spot 48, Cummins ISB 6 Cylinder 6.7 L Diesel 260 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 6969 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 30000 lb GVWR, 275/80R22.5, Spring Suspension, 168 in Wheelbase, Standby Power, 18 ft x 96 in Wide x 83 in High Body Usage: 207,702 Mi Lot closing time: Thu, Sep 17, 01:27 PM CDT Asset located in: Humble, TX, USA	2738	2013 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JP7D4S50674 C/W: Located in Lane 12 Spot 4, Hino J08E-VC 6 Cylinder 7.6 L Diesel 220 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Carrier Transcold Reefer Unit, Standby Power, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Ducted Floor, Walk-Up Ramp Usage: 282,949 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:28 PM CDT Asset located in: Lake Worth, TX, USA
2735	2012 Hino 338 4x2 Refrigerated Truck S/N: 5PVNV8JM9C4S50275 C/W: Located in Lane 35 Spot 49, Hino J08E-VC 6 Cylinder 7.7 L Diesel 260 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 12000 lb Front Axle, 22000 lb Rears, 33000 lb GVWR, 275/80R22.5, Spring Suspension, 207 in Wheelbase, Standby Power, Johnson 18 ft x 96 in Wide x 83 in High Body Usage: 233,145 Mi Lot closing time: Thu, Sep 17, 01:27 PM CDT Asset located in: Humble, TX, USA	2739	2013 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JV2D4S52797 C/W: Located in Lane 13 Spot 4, Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Thermo King Reefer Unit, 30216 Reefer Engine Hours, 41423 Reefer Total Hours, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Walk-Up Ramp Usage: 541,593 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:28 PM CDT Asset located in: Lake Worth, TX, USA
2736	2014 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JT9E4S55907 C/W: Located in Lane 13 Spot 20, Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 255 in Wheelbase, Carrier Reefer Unit, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 410,532 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:27 PM CDT Asset located in: Lake Worth, TX, USA	2740	2012 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JV0C4S52215 C/W: Located in Lane 12 Spot 9, Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Carrier TDB1-FFO-4M Reefer Unit, 28742 Reefer Engine Hours, 33644 Reefer Total Hours, Standby Power, Morgan 24 ft x 96 in Wide x 97 in High Body, Curbside Door, Ducted Floor, Walk-Up Ramp Usage: 281,369 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:28 PM CDT Asset located in: Lake Worth, TX, USA
2737	2013 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JT7D4S55189 C/W: Located in Lane 13 Spot 1, Hino J08E-VC Diesel 220 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Thermo King Supra 660 Reefer Unit, 2439 Reefer Engine Hours, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 394,697 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:27 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2741	2012 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JT2C4S54465 C/W: Located in Lane 13 Spot 8, Hino J08E-VC V6 Diesel 220 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Carrier Supra 600 Reefer Unit, 1027 Reefer Engine Hours:, Morgan 24 ft x 96 in Wide x 97 in High Body, Curbside Door, Ducted Floor, Walk-Up Ramp Usage: 245,374 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:28 PM CDT Asset located in: Lake Worth, TX, USA	2745	2011 International 4300 4x2 Refrigerated Truck S/N: 1HTMMAAN3BH388516 C/W: Located in Lane 34 Spot 41, 6 Cylinder Diesel Engine, 6224 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 22700 lb Rears, 32700 lb GVWR, 295/75R22.5, Spring Suspension, 206 in Wheelbase, Standby Power, Johnson 18 ft x 96 in Wide x 83 in High Body Usage: 240,998 Mi Lot closing time: Thu, Sep 17, 01:29 PM CDT Asset located in: Humble, TX, USA
2742	2012 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JT9C4S54477 C/W: Located in Lane 12 Spot 2, Hino J08E-VC 6 Cylinder 7.6 L Diesel 220 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19500 lb Rears, 25950 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 254 in Wheelbase, Carrier Transicold Reefer Unit, Kidron 26 ft x 102 in Wide x 91 in High Body, Curbside Door, Ducted Floor, Walk-Up Ramp Usage: 240,942 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:29 PM CDT Asset located in: Lake Worth, TX, USA	2746	2009 Ford E-450 Econoline 4x2 Refrigerated Truck S/N: 1FDXE45S79DA67259 C/W: Located in Lane 35 Spot 42, Ford V10 6.8 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, 5000 lb Front Axle, 9500 lb Rears, 14500 lb GVWR, 225/75R16, Spring Suspension, 178 in Wheelbase, Thermo King V-300 Reefer Unit, Standby Power, SUPREME 15 ft x 96 in Wide x 84 in High Body, Curbside Door, Liftgate Usage: 105,550 Mi Notes: This unit is being sold with a bonded title. Buyers in the state of LA -bonded titles will not be accepted in your state. Lot closing time: Thu, Sep 17, 01:29 PM CDT Asset located in: Humble, TX, USA
2743	2012 Hino 268 4x2 Refrigerated Truck S/N: 5PVNE8JT9C4S54446 C/W: Located in Lane 13 Spot 7, Hino J08E-VC V6 Diesel 220 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Thermo King KD-II SR Reefer Unit, Morgan 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Ducted Floor, Walk-Up Ramp Usage: 293,432 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:29 PM CDT Asset located in: Lake Worth, TX, USA	2747	2018 Isuzu NPR-XD 4x2 Refrigerated Truck S/N: JALC4W162J7K00991 C/W: Located in Lane 12 Spot 5, Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 6659.3 Engine hrs, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 151 in Wheelbase, Carrier Transicold Reefer Unit, Morgan 16 ft x 96 in Wide x 85 in High Body, Walk-Up Ramp Usage: 234,352 Mi Lot closing time: Thu, Sep 17, 01:30 PM CDT Asset located in: Lake Worth, TX, USA
2744	2012 International 4300 4x2 Refrigerated Truck S/N: 3HAMMAANXCL148116 C/W: Located in Lane 35 Spot 46, 6 Cylinder Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 22000 lb Rears, 32000 lb GVWR, 295/75R22.5, Spring Suspension, 206 in Wheelbase, Standby Power, 18 ft x 102 in Wide x 83 in High Body Usage: 108,560 Mi Lot closing time: Thu, Sep 17, 01:29 PM CDT Asset located in: Humble, TX, USA	2748	2018 Isuzu NQR 4x2 Refrigerated Truck S/N: JALE5W160J7901390 C/W: Located in Lane 14 Spot 6, Isuzu 4 Cylinder 5.2 L Diesel 210 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9934 Engine hrs, Automatic Transmission, 6830 lb Front Axle, 12980 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 132 in Wheelbase, Thermo King Reefer Unit, Morgan 14 ft x 96 in Wide x 91 in High Body, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 222,726 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 01:30 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2749	2005 Sterling Acterra 6x2 Sleeper Van Truck S/N: 2FZACGDJ15AN75939 C/W: Located in Lane 84 Spot 0, Mercedes-Benz OM926LA 439 cid Diesel Engine, 2006 US EPA Label, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 105 in High Rise Sleeper Cab, Bunk Beds, Briggs & Stratton Auxiliary Power Unit, Aluminum Front Wheels, 295/75R22.5, Air Lift Pusher Axle, Air Ride Suspension, 285 in Wheelbase, 22 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 1,242,305 Mi Notes: This unit is being sold with a bonded title. Buyers in the state of LA -bonded titles will not be accepted in your state. Lot closing time: Thu, Sep 17, 01:30 PM CDT Asset located in: Humble, TX, USA	2754	2016 Kenworth T370 4x2 Van Truck S/N: 2NKHMM6X9GM499349 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 10655 Engine hrs, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 16000 lb Rears, 5.29:1 Axle Ratio, 26000 lb GVWR, Aluminum Outer Wheels, 295 /75R22.5, Reyco Spring Suspension, 270 in Wheelbase, Amh 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 220,671 Mi Notes: License plates will not be provided. *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 01:31 PM CDT Asset located in: San Antonio, TX, USA
2750	2005 Kenworth T300 6x4 Van Truck S/N: 2NKMLD9X55M075009 C/W: Located in Lane 34 Spot 22, Cat 6 Cylinder Diesel Engine, 14449 Engine hrs, Engine Brake, Allison Automatic Transmission, Aluminum Wheels, 285/75R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 259 in Wheelbase, Morgan 24 ft x 102 in Wide x 91 in High Body, Liftgate Usage: 457,187 Mi Lot closing time: Thu, Sep 17, 01:30 PM CDT Asset located in: Humble, TX, USA	2755	2017 Kenworth T270 4x2 Van Truck S/N: 2NKHMM6X4HM165280 C/W: Located in Lane 13 Spot 12, Paccar PX-7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8759.9 Engine hrs, Engine Brake, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 16000 lb Rears, DANASPICER P20060S Drive Axles, 5.29:1 Axle Ratio, 26000 lb GVWR, 255 /70R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Brown 28 ft x 102 in Wide x 106 in High Body Usage: 338,393 Mi Lot closing time: Thu, Sep 17, 01:32 PM CDT Asset located in: Lake Worth, TX, USA
2752	2025 Kenworth T380 4x2 Moving Van Truck S/N: 2NK4HM7X1SM134945 C/W: Located in Lane 100 Spot 1, Paccar PX-7 6 Cylinder 6.7 L Diesel 280 hp Engine, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 3420 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 24 in Sleeper Cab, Aluminum Front Wheels, 285 /75R24.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Air Ride Suspension, 301 in Wheelbase, Smyrna Cargo 26 ft x 102 in Wide x 102 in High Body, Curbside Door Usage: 145,626 Mi Lot closing time: Thu, Sep 17, 01:31 PM CDT Asset located in: Livingston, LA, USA	2756	2022 Freightliner M2106 4x2 Van Truck S/N: 3ALACXFC8NDMZ0020 C/W: Located in Lane 12 Spot 10, Cummins B 6.7 L Diesel 220 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 234,816 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 01:32 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2758	2020 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC1LDME6766 C/W: Located in Lane 13 Spot 25, Cummins B6. 7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6673.8 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 265,614 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 01:32 PM CDT Asset located in: Lake Worth, TX, USA	2763	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC0JDKA6234 C/W: Located in Lane 67 Spot 0, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 7817 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, US Truck Body 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 224,623 Mi Lot closing time: Thu, Sep 17, 01:33 PM CDT Asset located in: Humble, TX, USA
2759	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC4KDKR4419 C/W: Cummins 6 Cylinder Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6197 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 265 in Wheelbase, Morgan 24 ft x 102 in Wide x 92 in High Body, Liftgate Usage: 255,626 Mi Lot closing time: Thu, Sep 17, 01:33 PM CDT Asset located in: Livingston, LA, USA	2765	2018 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWFB7JHJH4769 C/W: Located in Lane 34 Spot 27, Detroit DD5 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8129 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 273 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 226,706 Mi Lot closing time: Thu, Sep 17, 01:34 PM CDT Asset located in: Humble, TX, USA
2760	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB6KDKK6470 C/W: Located in Lane 12 Spot 3, Detroit 5.1 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 1969 Engine hrs, Allison 2100 Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 6.14:1 Axle Ratio, 25500 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Smyrna 26 ft x 102 in Wide x 108 in High Body, Liftgate Usage: 155,105 Mi Lot closing time: Thu, Sep 17, 01:33 PM CDT Asset located in: Lake Worth, TX, USA	2768	2015 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT0FDGD8657 C/W: Located in Lane 12 Spot 17, Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, 26000 lb GVWR, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body Usage: 434,926 Mi Lot closing time: Thu, Sep 17, 01:35 PM CDT Asset located in: Lake Worth, TX, USA
2762	2018 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC9JDJM8564 C/W: Located in Lane 34 Spot 28, Cummins B6. 7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Detroit DA-RS-17.5-4 Drive Axles, 5.22:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 283,492 Mi Lot closing time: Thu, Sep 17, 01:33 PM CDT Asset located in: Humble, TX, USA	2769	2014 Freightliner M2106 4x2 Van Truck S/N: 1FVACXDT6EHFJ8543 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 8582 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 325,855 Mi Lot closing time: Thu, Sep 17, 01:35 PM CDT Asset located in: Lake Worth, TX, USA
		2771	2012 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWU7CHBF6377 C/W: Located in Lane 0 Spot 0, Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2011 US EPA Label, 16876 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, 26000 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 270 in Wheelbase, 22 ft x 96 in Wide x 108 in High Body, Liftgate Usage: 272,231 Mi Lot closing time: Thu, Sep 17, 01:35 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2772	2021 International MV607 4x2 Van Truck S/N: 3HAEUMML5ML197533 C/W: Located in Lane 13 Spot 9, Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 8008 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 256 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 215,600 Mi Lot closing time: Thu, Sep 17, 01:36 PM CDT Asset located in: Lake Worth, TX, USA	2777	2020 International MV 607 4x2 Van Truck S/N: 3HAEUMML8LL323656 C/W: Located in Lane 34 Spot 29, Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5735 Engine hrs, Automatic Transmission, 4535 lb Front Axle, 10000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Smyrna truck and cargo 26 ft x 96 in Wide x 101 in High Body, Liftgate Usage: 207,693 Mi Notes: Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 01:37 PM CDT Asset located in: Humble, TX, USA
2773	2021 International MV 607 4x2 Van Truck S/N: 3HAEUMML1ML179126 C/W: Located in Lane 34 Spot 26, Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 10R22.5, Spring Suspension, 254 in Wheelbase, Mickey 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: Not Available Lot closing time: Thu, Sep 17, 01:36 PM CDT Asset located in: Humble, TX, USA	2779	2019 International 4300 Van Truck S/N: 1HTMMML7KH520480 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 4554 Engine hrs, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 199,456 Mi Lot closing time: Thu, Sep 17, 01:37 PM CDT Asset located in: Livingston, LA, USA
2774	2020 International MV607 4x2 Van Truck S/N: 3HAEUMMLXLL448626 C/W: Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8669 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 266 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 280,475 Mi Lot closing time: Thu, Sep 17, 01:36 PM CDT Asset located in: Livingston, LA, USA	2780	2019 International 4300 4x2 Van Truck S/N: 1HTMMML5KH519814 C/W: Located in Lane 100 Spot 2, Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12551 Engine hrs, Automatic Transmission, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 274 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 304,604 Mi Notes: This unit is being sold with a rebuilt salvage title. Lot closing time: Thu, Sep 17, 01:37 PM CDT Asset located in: Lake Worth, TX, USA
2776	2020 International MV607 4x2 Van Truck S/N: 1HTEUMML3LH134306 C/W: Located in Lane 34 Spot 2, Cummins 6 Cylinder Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 272 in Wheelbase, SUPREME 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 228,709 Mi Lot closing time: Thu, Sep 17, 01:36 PM CDT Asset located in: Humble, TX, USA	2782	2012 Hino 338 4x2 Van Truck S/N: 5PVNV8JT3C4S52191 C/W: Located in Lane 11 Spot 23, Hino J0BE-VB 6 Cylinder 7.7 L Diesel 260 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Morgan 24 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 292,450 Mi Notes: Selling with an affidavit of correction and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 01:38 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2783	2020 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV2L4S77533 C/W: Located in Lane 13 Spot 10, Hino J08E 6 Cylinder 7.7 L Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 5199 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Smyrna 26 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 146,678 Mi Lot closing time: Thu, Sep 17, 01:38 PM CDT Asset located in: Lake Worth, TX, USA	2790	2022 Ford E-350 4x2 Van Truck S/N: 1FDWE3FN1NDC09114 C/W: Located in Lane 13 Spot 2, Ford Motor Company 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4020 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, 225 /70R19.5, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 100,114 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 01:40 PM CDT Asset located in: Lake Worth, TX, USA
2784	2018 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV0J4S67001 C/W: Located in Lane 34 Spot 43, 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 104 in High Body, Liftgate Usage: 294,959 Mi Lot closing time: Thu, Sep 17, 01:38 PM CDT Asset located in: Humble, TX, USA	2791	2021 GMC Savana 3500 4x2 Van Truck S/N: 7GZ37TC79MN003977 C/W: Located in Lane 12 Spot 14, General Motors V8 6.6 L Gasoline Engine, 2021 US EPA Label, 3208.6 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75R16, Spring Suspension, 180 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body, Walk-Up Ramp, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 90,055 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 01:40 PM CDT Asset located in: Lake Worth, TX, USA
2787	2006 International 4300 4x2 Van Truck S/N: 1HTMMAAN66H324878 C/W: International 6 Cylinder Diesel Engine, 2005 US EPA Label, 20865 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 11R22.5, Spring Suspension, 216 in Wheelbase, Marion 18 ft x 102 in Wide x 91 in High Body, Liftgate Usage: 476,043 Mi Lot closing time: Thu, Sep 17, 01:39 PM CDT Asset located in: Lake Worth, TX, USA	2792	2014 Chevrolet Express 3500 4x2 Van Truck S/N: 1GB0G2CG5E1138784 C/W: Located in Lane 35 Spot 45, GM Vortec V8 6.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 139 in Wheelbase, Supreme 10 ft x 79 in Wide x 78 in High Body Usage: 270,482 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Lot closing time: Thu, Sep 17, 01:40 PM CDT Asset located in: Humble, TX, USA
2789	2022 Ford E-350 4x2 Van Truck S/N: 1FDWE3FNXNDC04221 C/W: Located in Lane 12 Spot 19, 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4020 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, Dual Rear Wheel, 225/75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body, Walk-Up Ramp, Professionally-Maintained-Fleet-Vehicle-PAG Usage: 88,663 Mi Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 01:40 PM CDT Asset located in: Lake Worth, TX, USA	2794	2003 Ford E-450 4x2 Van Truck S/N: 1FDXE45S53HC05347 C/W: 6.8 L Gasoline Engine, 2003 US EPA Label, Automatic Transmission, 4600 lb Front Axle, 9450 lb Rears, 14050 lb GVWR, 225 /75R16, Spring Suspension, 158 in Wheelbase, 14 ft x 96 in Wide x 81 in High Body Usage: 300,553 Mi Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 01:41 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
2794A	2017 Chevrolet 3500 4x2 Van Truck S/N: 54DBDW1B7HS801746 C/W: Located in Lane 14 Spot 1, GM 6.0 V8 6.0 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4860 lb Front Axle, 8840 lb Rears, 12000 lb GVWR, Steel, 215 /85R16, Spring Suspension, 134 in Wheelbase, Supreme 14 ft x 96 in Wide x 85 in High Body, Walk-Up Ramp Usage: 129,145 Mi Lot closing time: Thu, Sep 17, 01:41 PM CDT Asset located in: Lake Worth, TX, USA	2800	2016 Chevrolet Express 3500 Cargo Van S/N: 1GCZGHFG3G1211025 C/W: Located in Lane 14 Spot 19, 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 189,212 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 01:42 PM CDT Asset located in: Lake Worth, TX, USA
2797	1993 Ford CF8000 4x2 Van Truck S/N: 1FDXH81A0PVA20285 C/W: Located in Lane 14 Spot 13, 4 Cylinder Diesel Engine, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 189 in Wheelbase, UtiliMaster 20 ft x 96 in Wide x 84 in High Body, Liftgate Usage: 448,521 Mi Lot closing time: Thu, Sep 17, 01:41 PM CDT Asset located in: Lake Worth, TX, USA	2801	2012 Ford E-350 Cargo Van S/N: 1FTSS3EL8CDA58832 C/W: Located in Lane 14 Spot 23, V8 5.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner Usage: 158,412 Mi Lot closing time: Thu, Sep 17, 01:42 PM CDT Asset located in: Lake Worth, TX, USA
2798	2017 Freightliner MT55 4x2 Step Van S/N: 4UZAARDU8HCJB8950 C/W: Located in Lane 34 Spot 24, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 245/70R19.5, Air Ride Suspension, 240 in Wheelbase, Morgan 24 ft x 96 in Wide x 98 in High Body, Curbside Door Usage: 253,481 Mi Lot closing time: Thu, Sep 17, 01:42 PM CDT Asset located in: Humble, TX, USA	2804	2009 Kenworth T800 8x4 Cab and Chassis S/N: 1NKDL49X59J250839 C/W: Cummins ISX Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 20000 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Dana DSP40 Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Aluminum Wheels, 11R22.5, Air Lift Pusher Axle, Double Frame, AG400 Air Ride Suspension, 240 in Wheelbase, PTO, 217 in Cab to Axle, 289 in Cab to End of Frame, Pintle Hitch Usage: 734,717 Mi Lot closing time: Thu, Sep 17, 01:43 PM CDT Asset located in: Lake Worth, TX, USA
2798A	2013 Isuzu NPR 4x2 Step Van S/N: JALB4T176D7W01144 C/W: Located in Lane 35 Spot 52, Isuzu 3.0 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 6251 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 8840 lb Rears, 12000 lb GVWR, 215/85R16, Spring Suspension, 122 in Wheelbase, 18 ft x 96 in Wide x 87 in High Body Usage: 197,070 Mi Lot closing time: Thu, Sep 17, 01:42 PM CDT Asset located in: Humble, TX, USA	2805	2024 Volvo VHD 6x4 Cab and Chassis S/N: 4V5KH9EH0RN656297 C/W: Located in Lane 12 Spot 26, Volvo D13N-425 12.8 L Diesel 425 hp Engine, 2023 US EPA Label, Engine Brake, Eaton Fuller RTO-16908LL Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, 4.89:1 Axle Ratio, 89000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Air Ride Suspension, 222 in Wheelbase, 134 in Cab to Axle, 300 in Cab to End of Frame Usage: 94 Mi Lot closing time: Thu, Sep 17, 01:43 PM CDT Asset located in: Lake Worth, TX, USA
2799	2019 Freightliner Sprinter 3500 Cargo Van S/N: WDYPF0CD8KP040692 C/W: Located in Lane 35 Spot 15, V6 3.0 L Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Towing Hitch Usage: 195,155 Mi Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 01:42 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2807	2014 International 5900i 6x4 Cab and Chassis S/N: 3HTXYSJT8EN768368 C/W: Located in Lane 18 Spot 23, 6 Cylinder Diesel Engine, 13061 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Air Ride Suspension, 242 in Wheelbase, 142 in Cab to Axle, 267 in Cab to End of Frame Usage: 249,260 Mi Lot closing time: Thu, Sep 17, 01:44 PM CDT Asset located in: Humble, TX, USA	2815C	2004 Ford F-650 4x2 Cab and Chassis S/N: 3FRWF65304V616215 C/W: Located in Lane 18 Spot 3, Cat C7 6 Cylinder 7.2 L Diesel Engine, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 156 in Wheelbase, 84 in Cab to Axle, 116 in Cab to End of Frame Usage: Not Available Lot closing time: Thu, Sep 17, 01:46 PM CDT Asset located in: Humble, TX, USA
2809A	2010 International 7400 4x4 Cab and Chassis S/N: 1HTWEAAN9AJ272363 C/W: Located in Lane 12 Spot 22, Navistar 6 Cylinder Diesel Engine, 7835 Engine hrs, Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 202 in Wheelbase, PTO, 126 in Cab to Axle, 220 in Cab to End of Frame, Pintle Hitch Usage: 92,474 Mi Lot closing time: Thu, Sep 17, 01:44 PM CDT Asset located in: Lake Worth, TX, USA	2818	2025 Stallion 24 ft T/A Enclosed Trailer S/N: 7SWBE2425SM007783 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Ramp, Side Door, 225 /75R15 Tires, 9999 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:46 PM CDT Asset located in: Midland, TX, USA
2811	2010 Hino 268 4x2 Cab and Chassis S/N: 5PVNJ8JT2A4S52630 C/W: Located in Lane 0 Spot 0, Hino J08E-TV 7.7 L Diesel 220 hp Engine, 2009 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 254 in Wheelbase, 185 in Cab to Axle, 255 in Cab to End of Frame Usage: 450,046 Mi Lot closing time: Thu, Sep 17, 01:45 PM CDT Asset located in: Humble, TX, USA	2823	2024 Stallion 18 ft T/A Enclosed Trailer S/N: 7SWBE1829RM004089 C/W: Located in Lane 84 Spot 16, Ball Hitch, Spring Suspension, 96 in Deck Width, 102 in Overall Width, Ramp, Side Door, 225/75R15 Tires, 9999 lb GVWR Usage: Not Available Notes: Unit is being sold with a title in transit for 14 days and unit cannot leave the yard until the title is received. Lot closing time: Thu, Sep 17, 01:47 PM CDT Asset located in: Lake Worth, TX, USA
2812	2016 Isuzu NQR 4x2 Crew Cab Cab and Chassis S/N: JALE5J164G7900013 C/W: Located in Lane 18 Spot 2, Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6830 lb Front Axle, 12980 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, 118 in Cab to Axle, 161 in Cab to End of Frame Usage: 146,890 Mi Lot closing time: Thu, Sep 17, 01:45 PM CDT Asset located in: Humble, TX, USA	2824	2018 LGS VWLF85x20E3 20 ft T/A Enclosed Trailer S/N: 53BLTEB24JF023944 C/W: Located in Lane 84 Spot 25, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, Ramp, 225/75R15 Tires, 9900 lb GVWR, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 01:48 PM CDT Asset located in: Lake Worth, TX, USA
2813	2016 Ford F-750 Super Duty 4x2 Cab and Chassis S/N: 1FDWF7DX7GDA02447 C/W: Located in Lane 12 Spot 21, V8 Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10534 Engine hrs, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 23000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 261 in Wheelbase, 185 in Cab to Axle, 305 in Cab to End of Frame Usage: 271,555 Mi Lot closing time: Thu, Sep 17, 01:45 PM CDT Asset located in: Lake Worth, TX, USA	2825	2002 W-W 18 ft T/A Enclosed Trailer S/N: 16WVX229221634256 C/W: Located in Lane 86 Spot 6, Ball Hitch, Torsion Axle, Electric Brakes, 72 in Deck Width, 225/75R15 Tires Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; No title available, sold with bill of sale only. Lot closing time: Thu, Sep 17, 01:48 PM CDT Asset located in: Lake Worth, TX, USA
		2825A	2020 Diamond 17 ft T/A Enclosed Trailer S/N: 53NBE1621L1080937 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, Side Door, 225 /75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 01:48 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
2825B	2019 CMTR 17 ft T/A Enclosed Trailer S/N: 49TCB1623K1029094 C/W: Torsion Axle, Electric Brakes, 78 in Deck Width, Side Door, 235/80R16 Tires, 10160 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 01:48 PM CDT Asset located in: San Antonio, TX, USA	2831B	2014 W-W 16 ft T/A Enclosed Trailer S/N: 11WHC1625EW311177 C/W: Located in Lane 86, Ball Hitch, Torsion Axle, Electric Brakes, 94 in Deck Width, Ramp, Side Door, 225/75R15 Tires, 10000 lb GVWR Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture; Texas buyers must stop in office to sign required documents to process title Lot closing time: Thu, Sep 17, 01:49 PM CDT Asset located in: Lake Worth, TX, USA
2826	2018 Lark 17 ft T/A Enclosed Trailer S/N: 571BE1627JM029600 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, Side Door, 225 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 01:48 PM CDT Asset located in: San Antonio, TX, USA	2834	2009 W-W Trailer 16 ft T/A Enclosed Trailer S/N: 11WHC16239W302984 C/W: Located in Lane 84 Spot 14, Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 01:50 PM CDT Asset located in: Lake Worth, TX, USA
2827	2025 Forest River 16 ft T/A Enclosed Trailer S/N: 5NHUVH626SY053054 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Ramp, Side Door, 225 /75R15 Tires, 9800 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:48 PM CDT Asset located in: Midland, TX, USA	2838	2004 Haulmark 16 ft T/A Enclosed Trailer S/N: 16HPB16224T002769 C/W: Located in Lane 83 Spot 1, Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, Ramp, Side Door, 225/75R15 Tires Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture **Shelving built in cargo area**; Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 01:51 PM CDT Asset located in: Lake Worth, TX, USA
2829	2018 LGS Look EWLC7X14TE2 16 ft T/A Enclosed Trailer S/N: 53BLTEA29JU031194 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 102 in Deck Width, Side Door, 225 /75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:49 PM CDT Asset located in: Midland, TX, USA	2838A	2020 Carry-On 15 ft T/A Enclosed Trailer S/N: 4YMBC162XLG010090 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 76 in Deck Width, Side Door, 225 /75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 01:51 PM CDT Asset located in: San Antonio, TX, USA
2830	2018 Forest River 16 ft T/A Enclosed Trailer S/N: 5NHUNS62XJU119964 C/W: Ball Hitch, Spring Suspension, 80 in Deck Width, Side Door, 225/75R15 Tires, 9800 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 01:49 PM CDT Asset located in: San Antonio, TX, USA	2839A	2015 CM 14 ft T/A Enclosed Trailer S/N: 49TCB1422F1017057 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 76 in Deck Width, Side Door, 235/80R16 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 01:51 PM CDT Asset located in: San Antonio, TX, USA
2831A	2015 CM 16 ft T/A Enclosed Trailer S/N: 49TCB1626F1016085 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 76 in Deck Width, Side Door, 235/80R16 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 01:49 PM CDT Asset located in: San Antonio, TX, USA	2841	1993 Utility 13 ft T/A Enclosed Trailer S/N: 1WC200F2XP2021600 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 205/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 01:52 PM CDT Asset located in: Livingston, LA, USA

Lot #	Details	Lot #	Details
2841A	2014 Forest River 12 ft T/A Enclosed Trailer S/N: 5NHUBL228EY068676 C/W: Located in Lane 43 Spot 28, Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, Ramp, Side Door, 205/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 01:52 PM CDT Asset located in: Humble, TX, USA	2849B	2019 Lark 12 ft T/A Emergency Eye Wash & Shower station Enclosed Trailer S/N: 571BE1226KM033175 C/W: Ball Hitch, Spring Suspension, Side Door, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:54 PM CDT Asset located in: Midland, TX, USA
2843	2019 Lark 12 ft S/A Emergency Eye Wash & Shower Station Enclosed Trailer S/N: 571BE1224KM032462 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Side Door, 205/75R15 Tires, 9999 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:52 PM CDT Asset located in: Midland, TX, USA	2852	2025 Magnamerica 16 ft T/A Food Concession Trailer S/N: 3A91F2205SC316550 C/W: Located in Lane 43 Spot 18, Ball Hitch, Spring Suspension, Electric Brakes, 7.00-15 Tires, 7000 lb GVWR, Air Conditioner, Kitchen Appliances, Fire Suppression System, Anti-Theft Cages, Water Heater, Fresh Water Tank, Grey Water Tank Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 01:54 PM CDT Asset located in: Humble, TX, USA
2844	2019 Lark 12 ft S/A Enclosed Trailer S/N: 571BE1224KM033174 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:52 PM CDT Asset located in: Midland, TX, USA		
2847	2019 Rock Solid Cargo 12 ft S/A Emergency Eye Wash & Shower Station Enclosed Trailer S/N: 7H2BE122XKD007231 C/W: Ball Hitch, Spring Suspension, Side Door, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:53 PM CDT Asset located in: Midland, TX, USA	2853	2017 Lark VT8.5X20TA 20 ft T/A Food Concession Trailer S/N: 5RTBE2026HD060455 C/W: Located in Lane 42 Spot 12, Ball Hitch, Spring Suspension, 205/75R15 Tires, 7000 lb GVWR, Air Conditioner, Fresh Water Tank Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Lot closing time: Thu, Sep 17, 01:54 PM CDT Asset located in: Humble, TX, USA
2848	2019 Rock Solid Cargo 12 ft T/A Emergency Eye Wash & Shower Station Enclosed Trailer S/N: 7H2BE1228KD007230 C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:53 PM CDT Asset located in: Midland, TX, USA	2854	2024 Oma 17 ft 9 in T/A Food Concession Trailer S/N: 3A9M1FE23RS309130 C/W: Located in Lane 87 Spot 1, Ball Hitch, Spring Suspension, Electric Brakes, 7.00-15 Tires, 7000 lb GVWR, Air Conditioner, Kitchen Appliances, Fire Suppression System, Propane Tanks, Grey Water Tank Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 01:55 PM CDT Asset located in: Lake Worth, TX, USA
2849	2019 Lark United 12 ft T/A Emergency Eye Wash & Shower Station Enclosed Trailer S/N: 571BE1222KM031634 C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:54 PM CDT Asset located in: Midland, TX, USA		
2849A	2019 12 ft T/A Emergency Eye Wash & Shower Station Enclosed Trailer S/N: 571BE1227KM032407 C/W: Ball Hitch, Spring Suspension, Side Door, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 01:54 PM CDT Asset located in: Midland, TX, USA	2856	2024 The Fud Trailer 16 ft T/A Food Concession Trailer S/N: 3F9F1AA23RM066178 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 195R15G Tires, 7000 lb GVWR, Air Conditioner, Kitchen Appliances, Anti-Theft Cages Usage: Not Available Lot closing time: Thu, Sep 17, 01:55 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2859	2024 The Fud Trailer 16 ft T/A Food Concession Trailer S/N: 3F9F1AA26RM066661 C/W: Located in Lane 43 Spot 14, Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, Fire Suppression System, Anti-Theft Cages Usage: Not Available Lot closing time: Thu, Sep 17, 01:56 PM CDT Asset located in: Humble, TX, USA	2864	2025 Magnamerica Food vending 14 ft T/A Food Concession Trailer S/N: 3A91F2144SC316477 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 7.00-15 Tires, 7000 lb GVWR, Air Conditioner, Kitchen Appliances Usage: Not Available Notes: The high bidder of this item must contact the Fort Worth site at rb_fortworth@ritchiebros.com for additional payment and titling instructions prior to sending payment. License plates will not be provided. Lot closing time: Thu, Sep 17, 01:57 PM CDT Asset located in: San Antonio, TX, USA
2861	2024 MP Trailers 16 ft T/A Food Concession Trailer S/N: 4M9BE1622RW097488 C/W: Located in Lane 53 Spot 0, Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 7000 lb GVWR, Air Conditioner, Kitchen Appliances, Fire Suppression System, Propane Tanks, Anti-Theft Cages, Water Heater, Fresh Water Tank, Grey Water Tank Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 01:56 PM CDT Asset located in: Humble, TX, USA	2865	2025 Erskine & Sons 14 ft T/A Food Concession Trailer S/N: 1E9BV1423SA253046 C/W: Located in Lane 82 Spot 17, Ball Hitch, Spring Suspension, Electric Brakes, 205/75R14 Tires, 7000 lb GVWR, Air Conditioner Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 01:57 PM CDT Asset located in: Lake Worth, TX, USA
2862	2024 Lone Star 16 ft S/A Food Concession Trailer S/N: 1L9A21C16RM666160 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, Air Conditioner, Kitchen Appliances, Fire Suppression System, Anti-Theft Cages Usage: Not Available Lot closing time: Thu, Sep 17, 01:57 PM CDT Asset located in: Midland, TX, USA	2869	2025 The Fud Trailer 12 ft S/A Food Concession Trailer S/N: 3F9F1A21XSM066805 C/W: Located in Lane 43 Spot 0, Ball Hitch, Spring Suspension, 205/75R15 Tires, 3500 lb GVWR, Air Conditioner, Kitchen Appliances, Fire Suppression System, Anti-Theft Cages, Fresh Water Tank, Grey Water Tank Usage: Not Available Notes: Additional component available at Main Office - Keys Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 01:58 PM CDT Asset located in: Humble, TX, USA
2863	2025 Remolques FTM De Monclova 14 ft T/A Food Concession Trailer S/N: 3E91B2144SE072230 C/W: Located in Lane 42 Spot 0, Ball Hitch, Spring Suspension, 7.00-15 Tires, 7000 lb GVWR, Air Conditioner, Anti-Theft Cages Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 01:57 PM CDT Asset located in: Humble, TX, USA	2870	2026 JRS 12 ft S/A Food Concession Trailer S/N: 1J9RFBF19TM584054 C/W: Ball Hitch, Spring Suspension, 225/75R15 Tires, 5500 lb GVWR, Air Conditioner, Kitchen Appliances, Anti-Theft Cages, Fresh Water Tank, Grey Water Tank Usage: Not Available Lot closing time: Thu, Sep 17, 01:58 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
2871	2026 The Fud Trailer 0 ft T/A Food Concession Trailer S/N: 3F9F1A326TM066177 C/W: Located in Lane 82 Spot 7, Ball Hitch, Spring Suspension, 205/75R15 Tires, 7000 lb GVWR, Air Conditioner Usage: Not Available Notes: Rear Door is broken and will not open Lot closing time: Thu, Sep 17, 01:59 PM CDT Asset located in: Lake Worth, TX, USA	2881	2026 Metalium Industries 40 ft T/A Gooseneck Equipment Trailer S/N: 3NGGF4025T1003350 C/W: Spring Suspension, Electric Brakes, 40 ft Main Deck, 97 in Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 235/85R16 Tires, 15680 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:01 PM CDT Asset located in: Midland, TX, USA
2873	2024 The Fud Trailer 9 ft 10 in S/A Food Concession Trailer S/N: 3F9F1A21XRM066815 C/W: Located in Lane 82 Spot 7, Ball Hitch, Spring Suspension, Electric Brakes, 225/6516 Tires, 7000 lb GVWR, Air Conditioner, Fire Suppression System Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 01:59 PM CDT Asset located in: Lake Worth, TX, USA	2889	2025 East Texas 40 ft T/A Gooseneck Equipment Trailer S/N: 58SGM4024SE042821 C/W: Spring Suspension, Electric Brakes, 36 ft Main Deck, 4 ft Fixed Dovetail, 96 in Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 15680 lb GVWR Usage: Not Available Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 02:03 PM CDT Asset located in: Oklahoma City, OK, USA
2875	2014 Kaufman T/A Lowboy Trailer S/N: 5SHAD3926EB000602 C/W: Located in Lane 37 Spot 0, 22 ft x 102 in Main Deck, Upper Deck, Deck Over Tires, Spring Suspension Usage: Not Available Lot closing time: Thu, Sep 17, 02:00 PM CDT Asset located in: Humble, TX, USA	2890	2025 Trail Maxx MAX27-40 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H402XST002364 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 101 in Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:03 PM CDT Asset located in: San Antonio, TX, USA
2877	2024 East Texas Trailers 40 ft Tri/A Gooseneck Equipment Trailer S/N: 58SGM4032SE043832 C/W: Spring Suspension, Electric Brakes, 36 ft 3 in Main Deck, 3 ft 9 in Fixed Dovetail, 96.5 in Deck Width, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires, 21000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:00 PM CDT Asset located in: Livingston, LA, USA	2891	2025 Horizon FHZGN40MR10K 40 ft T/A Gooseneck Equipment Trailer S/N: 3H7GF4029SR009080 C/W: Located in Lane 37 Spot 7, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:03 PM CDT Asset located in: Humble, TX, USA
2880	2026 Big Tex 40 ft T/A Gooseneck Equipment Trailer S/N: 16V3F482XT6460510 C/W: Located in Lane 26 Spot 5, Spring Suspension, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 102 in Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires, 17000 lb GVWR Usage: Not Available Notes: Selling with a repossession affidavit and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 02:01 PM CDT Asset located in: Lake Worth, TX, USA	2892	2025 Ascend GN40-20 40 ft T/A Gooseneck Equipment Trailer S/N: 3F7BGP403SA002698 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/75R17.5 Tires, 12000 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:04 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
2893	2025 Trailmaxx MAX27-40 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H4027ST000975 C/W: Located in Lane 37 Spot 8, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires, 12000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:04 PM CDT Asset located in: Humble, TX, USA	2899	1998 Boer 40 ft T/A Gooseneck Equipment Trailer S/N: 46ZGF4024WT000162 C/W: Spring Suspension, Electric Brakes, 40 ft Main Deck, 102 in Deck Width, Deck Over Tires, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:05 PM CDT Asset located in: San Antonio, TX, USA
2894	2024 Trailmaxx SD27-40 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H4025RT001410 C/W: Located in Lane 44, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:04 PM CDT Asset located in: Humble, TX, USA	2901	2001 G00S 38 ft T/A Gooseneck Equipment Trailer S/N: 1S9FG40231S683002 C/W: Spring Suspension, Electric Brakes, 33 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:06 PM CDT Asset located in: San Antonio, TX, USA
2894A	2024 HD Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 7LKH3AP26RP001297 C/W: Spring Suspension, Electric Brakes, 40 ft Main Deck, 97 in Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:04 PM CDT Asset located in: Lake Worth, TX, USA	2902	1998 Trailmaster UT 38 ft T/A Gooseneck Equipment Trailer S/N: 1T9FS4027WC023113 C/W: Spring Suspension, Electric Brakes, 33 ft Main Deck, 5 ft Fixed Dovetail, 101 in Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:06 PM CDT Asset located in: San Antonio, TX, USA
2896	2023 Trailmaxx 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H402XPT000539 C/W: Located in Lane 43 Spot 0, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/85R16 Tires, 12000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:04 PM CDT Asset located in: Humble, TX, USA	2903	2026 Horizon FHZ36X102X34GN10K 36 ft T/A Gooseneck Equipment Trailer S/N: 3H7GF3625TR012335 C/W: Located in Lane 37 Spot 7, Spring Suspension, Electric Brakes, 30 ft 6 in Main Deck, 5 ft 6 in Fixed Dovetail, 102 in Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:06 PM CDT Asset located in: Humble, TX, USA
2897	2021 Big Tex 22GN-35BK+5MR 40 ft T/A Gooseneck Equipment Trailer S/N: 16V3F482XM6076955 C/W: Located in Lane 38 Spot 8, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Manual Ramps, Wood Flooring, 235/85R16 Tires, 23900 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:05 PM CDT Asset located in: Humble, TX, USA	2904	2012 PJ Trailers 35 ft T/A Gooseneck Equipment Trailer S/N: 4P5FD3524C1164916 C/W: Located in Lane 81 Spot 28, Spring Suspension, Electric Brakes, 30 ft Main Deck, 5 ft Fixed Dovetail, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:06 PM CDT Asset located in: Lake Worth, TX, USA
2898	2001 PJ Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 4P5GF402311039706 C/W: Located in Lane 81 Spot 18, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:05 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2905A	2019 Big Tex 25GN-25BK+5MR 30 ft T/A Gooseneck Equipment Trailer S/N: 16VGX252XK6099964 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235 /80R16 Tires, 25900 lb GVWR, Smittybilt 9500 lb Winch Usage: Not Available Lot closing time: Thu, Sep 17, 02:07 PM CDT Asset located in: Lake Worth, TX, USA	2916	2021 Interstate 50DLA 30 ft Tri/A Equipment Trailer S/N: 1JKDLA502MM018203 C/W: Located in Lane 82 Spot 28, Lunette Ring Hitch, Spring Suspension, Air Brakes, 24 ft Main Deck, 6 ft Fixed Dovetail, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215 /75R17.5 Tires, 60100 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:09 PM CDT Asset located in: Lake Worth, TX, USA
2908	2026 Double A 8326T7KGN 26 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 71UGN2620TT015046 C/W: Located in Lane 81 Spot 20, Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: Sold with MSO. No Title available. Lot closing time: Thu, Sep 17, 02:07 PM CDT Asset located in: Lake Worth, TX, USA	2917	2016 Interstate 40DLA 33 ft T/A Equipment Trailer S/N: 1JKDLA404GM015177 C/W: Located in Lane 81 Spot 27, Lunette Ring Hitch, Spring Suspension, Air Brakes, 27 ft Main Deck, 6 ft Fixed Dovetail, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215 /75R17.5 Tires, 47600 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:09 PM CDT Asset located in: Lake Worth, TX, USA
2909	2026 Double A 10226T7KGN 26 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 71UGN262XTT015071 C/W: Located in Lane 37 Spot 0, Spring Suspension, Electric Brakes, 23 ft Main Deck, 3 ft Fixed Dovetail, 82 in Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:08 PM CDT Asset located in: Humble, TX, USA	2918	1998 30 ft T/A Equipment Trailer S/N: TR183325 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:10 PM CDT Asset located in: San Antonio, TX, USA
2914	1999 Belshe DT-235 25 ft T/A Gooseneck Equipment Trailer S/N: 16JF02022X1032756 C/W: Located in Lane 42 Spot 17, Spring Suspension, 20 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 7.50 x15 Tires, 23500 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:09 PM CDT Asset located in: Humble, TX, USA	2919	2007 Better Built 18 ft T/A Equipment Trailer S/N: 4MNFB182871002418 C/W: Located in Lane 82 Spot 26, Lunette Ring Hitch, Spring Suspension, 18 ft Main Deck, 102 in Deck Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:10 PM CDT Asset located in: Lake Worth, TX, USA
2915	1998 Trailboss 20 ft T/A Gooseneck Equipment Trailer S/N: 4S0DG2921W1000344 C/W: Located in Lane 37 Spot 0, Spring Suspension, Electric Brakes, 24 ft Main Deck, 5 ft Fixed Dovetail, 96 in Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:09 PM CDT Asset located in: Humble, TX, USA	2920	2019 Hudson HBC10 16 ft T/A Equipment Trailer S/N: 10HHBC101K2000017 C/W: Located in Lane 85 Spot 29, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 82 in Deck Width, Manual Ramps, Wood Flooring, 235/85R16 Tires, 15010 lb GVWR, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:10 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
2925	2026 Double A 8320T7K 20 ft T/A Equipment Trailer (Unused) S/N: 71UBU2025TT015047 C/W: Located in Lane 85 Spot 20, Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Main Deck, 3 ft Fixed Dovetail, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: Sold with MSO. No Title available. Lot closing time: Thu, Sep 17, 02:11 PM CDT Asset located in: Lake Worth, TX, USA	2935	2026 8318T Double A 18 ft T/A Equipment Trailer (Unused) S/N: 71UBU1820TT015049 C/W: Located in Lane 85 Spot 19, Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, Manual Ramps, Wood Flooring, 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Lot closing time: Thu, Sep 17, 02:14 PM CDT Asset located in: Lake Worth, TX, USA
2926	2026 ARC 20 ft T/A Equipment Trailer S/N: 3NGBJ2020T1002779 C/W: Located in Lane 43 Spot 1, Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:11 PM CDT Asset located in: Humble, TX, USA	2939	2001 Road King 18 ft T/A Equipment Trailer S/N: 1R9FS222411093658 C/W: Located in Lane 43 Spot 0, Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:15 PM CDT Asset located in: Humble, TX, USA
2927	2025 Maxey Maxx-D C6X 20 ft T/A Equipment Trailer S/N: 5R8BC2020SM122133 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 02:12 PM CDT Asset located in: Oklahoma City, OK, USA	2940	2026 Double A 8314T 14 ft T/A Equipment Trailer (Unused) S/N: 71UBU142XTT015050 C/W: Located in Lane 85 Spot 18, Ball Hitch, Spring Suspension, Electric Brakes, 14 ft Main Deck, Manual Ramps, 205/75R15 Tires, 7000 lb GVWR, Metal Flooring Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Lot closing time: Thu, Sep 17, 02:15 PM CDT Asset located in: Lake Worth, TX, USA
2928	2022 Road Boss 20 ft T/A Equipment Trailer S/N: 5Z0BP2023NP014261 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 02:12 PM CDT Asset located in: Oklahoma City, OK, USA	2941	2023 MMDI 614SLTD 14 ft T/A Equipment Trailer S/N: 5631F2025PM000407 C/W: Located in Lane 42, Ball Hitch, Spring Suspension, Surge Brakes, 14 ft Main Deck, 74 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:15 PM CDT Asset located in: Humble, TX, USA
2933	2013 Carry-On 20 ft T/A Equipment Trailer S/N: 4YMUE2023DT027047 C/W: Located in Lane 83 Spot 29, Ball Hitch, Spring Suspension, 20 ft Main Deck, Wood Flooring, 235/80R16 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:13 PM CDT Asset located in: Lake Worth, TX, USA	2942	2022 ProHauler 614SLTD 14 ft T/A Equipment Trailer S/N: 5631F2020NM000294 C/W: Located in Lane 42, Ball Hitch, Spring Suspension, Surge Brakes, 14 ft Main Deck, 72 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:15 PM CDT Asset located in: Humble, TX, USA
2934	2026 Double A 8318T 18 ft T/A Equipment Trailer S/N: 71UBU1829TT015048 C/W: Located in Lane 85 Spot 26, Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, Manual Ramps, Wood Flooring, 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Lot closing time: Thu, Sep 17, 02:13 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
2943	2022 MMDI 614SLTD 14 ft T/A Equipment Trailer S/N: 5631F2029NM002237 C/W: Located in Lane 42 Spot 24, Ball Hitch, Torsion Axle, Surge Brakes, 14 ft Main Deck, 72 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:15 PM CDT Asset located in: Humble, TX, USA	2950	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1723MM001714 C/W: Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 63.5 in Deck Width, Storage Compartments, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 4400 lb GVWR Usage: Not Available Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 02:17 PM CDT Asset located in: Oklahoma City, OK, USA
2944	2022 MMDI 614SLTD 14 ft T/A Equipment Trailer S/N: 5631F2020NM001638 C/W: Located in Lane 42 Spot 24, Ball Hitch, Torsion Axle, Surge Brakes, 14 ft Main Deck, 72 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:16 PM CDT Asset located in: Humble, TX, USA	2951	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1722MM000568 C/W: Located in Lane 42 Spot 0, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:17 PM CDT Asset located in: Humble, TX, USA
2945	2022 MMDI T/A 14 ft T/A Equipment Trailer S/N: 5631F2024NM000301 C/W: Ball Hitch, Torsion Axle, Surge Brakes, 14 ft Main Deck, 70 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:16 PM CDT Asset located in: Livingston, LA, USA	2952	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1729MM000907 C/W: Located in Lane 42 Spot 24, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:18 PM CDT Asset located in: Humble, TX, USA
2946	2022 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1721NM000952 C/W: Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 64 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:16 PM CDT Asset located in: Livingston, LA, USA	2953	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1724MM001754 C/W: Located in Lane 42 Spot 26, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, Manual Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:18 PM CDT Asset located in: Humble, TX, USA
2947	2022 MMDI E510H 10 ft T/A Equipment Trailer S/N: 5631F1729NM000374 C/W: Located in Lane 43 Spot 0, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 62 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:16 PM CDT Asset located in: Humble, TX, USA		
2949	2022 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1727NM000969 C/W: Located in Lane 42 Spot 25, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Steel Decking, 225/75R15 Tires, 7990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:17 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
2954	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1725MM002041 C/W: Ball Hitch, Torsion Axle, Surge Brakes, 10 ft 0 in Main Deck, 64 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot Lot closing time: Thu, Sep 17, 02:18 PM CDT Asset located in: Livingston, LA, USA	2959	2020 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1721LM000477 C/W: Located in Lane 42 Spot 23, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 61 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:19 PM CDT Asset located in: Humble, TX, USA
2955	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1723MM002443 C/W: Located in Lane 42 Spot 23, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:18 PM CDT Asset located in: Humble, TX, USA	2960	2020 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1725LM000515 C/W: Located in Lane 42 Spot 24, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 7990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:19 PM CDT Asset located in: Humble, TX, USA
2956	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1720MM001167 C/W: Located in Lane 42, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Main Deck, 62 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:18 PM CDT Asset located in: Humble, TX, USA	2961	2020 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1722LM001315 C/W: Located in Lane 42 Spot 27, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 61 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 4400 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:20 PM CDT Asset located in: Humble, TX, USA
2957	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1723MM000353 C/W: Located in Lane 42 Spot 28, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:19 PM CDT Asset located in: Humble, TX, USA	2962	2020 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1729LM000100 C/W: Located in Lane 42 Spot 30, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 61 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 7990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:20 PM CDT Asset located in: Humble, TX, USA
2958	2021 MMDI 510RCMPH 10 ft T/A Equipment Trailer S/N: 5631F1721MM000139 C/W: Located in Lane 42 Spot 26, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, Manual Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:19 PM CDT Asset located in: Humble, TX, USA	2963	2021 Pratt CP0510 10 ft T/A Equipment Trailer S/N: 1P9UT1727MN343182 C/W: Located in Lane 42 Spot 29, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:20 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2964	2018 Pratt CP0510 10 ft T/A Equipment Trailer S/N: 1P9UT1724JN343507 C/W: Located in Lane 42 Spot 23, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Manual Ramps, Aluminum Flooring, 225/75R15 Tires, 6990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:20 PM CDT Asset located in: Humble, TX, USA	2968	2018 MMDI 10 ft T/A Equipment Trailer S/N: 5631F172XJM001687 C/W: Located in Lane 42 Spot 0, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 8800 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:21 PM CDT Asset located in: Humble, TX, USA
2965	2020 MMDI 410LPT 10 ft S/A Tilt Deck Trailer S/N: 5631F1418LM000004 C/W: Located in Lane 42 Spot 33, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Deck Tilting Length, 52 in Deck Width, 225/75R15 Tires, 4400 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:21 PM CDT Asset located in: Humble, TX, USA	2969	2021 MMDI 7 ft S/A Equipment Trailer S/N: 5631F1414MM001684 C/W: Located in Lane 42 Spot 28, Ball Hitch, Spring Suspension, Surge Brakes, 7 ft Main Deck, 49 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:22 PM CDT Asset located in: Humble, TX, USA
2966	2019 MMDI 47RVX10 7 ft S/A Equipment Trailer S/N: 5631F1418KM000695 C/W: Located in Lane 42 Spot 0, Ball Hitch, Spring Suspension, 7 ft Main Deck, 52 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires, 4400 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:21 PM CDT Asset located in: Humble, TX, USA	2971	2019 MMDI 510RCMPH 7 ft S/A Equipment Trailer S/N: 5631F1412KM003107 C/W: Located in Lane 42 Spot 27, Ball Hitch, Spring Suspension, Manual Ramps, Steel Decking, 225/75R15 Tires, 4400 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:22 PM CDT Asset located in: Humble, TX, USA
2967	2019 MMDI 10 ft T/A Equipment Trailer S/N: 5631F1723KM001872 C/W: Located in Lane 42 Spot 25, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Main Deck, 60 in Deck Width, Steel Decking, 225/75R15 Tires, 8800 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Lot closing time: Thu, Sep 17, 02:21 PM CDT Asset located in: Humble, TX, USA	2972	2018 MMDI 7 ft S/A Equipment Trailer S/N: 5631F1411JM002674 C/W: Located in Lane 42 Spot 24, Ball Hitch, Spring Suspension, Surge Brakes, 7 ft Main Deck, 48 in Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires, 4400 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:22 PM CDT Asset located in: Humble, TX, USA
		2973	2022 Barreto E4X6TBT 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0610NL280072 C/W: Located in Lane 58 Spot 0, Ball Hitch, Torsion Axle, 6 ft 6 in Deck Tilting Length, 48 in Deck Width, ST145R12 Tires, 2200 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:22 PM CDT Asset located in: Humble, TX, USA
		2974	2021 Barreto E4X6TBT 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0611ML280242 C/W: Located in Lane 58 Spot 0, Ball Hitch, Torsion Axle, 6 ft 6 in Deck Tilting Length, 48 in Deck Width, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:23 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2975	2021 Barreto E4X6TBT 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0611ML280239 C/W: Located in Lane 58 Spot 0, Ball Hitch, Torsion Axle, 6 ft 6 in Deck Tilting Length, 48 in Deck Width, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:23 PM CDT Asset located in: Humble, TX, USA	2983	2020 MMDI 12 ft S/A Tilt Deck Trailer S/N: 5631T1610LM001380 C/W: Located in Lane 45 Spot 0, Ball Hitch, Torsion Axle, Surge Brakes, 52 in Deck Width, 235/85R16 Tires, 7700 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:25 PM CDT Asset located in: Humble, TX, USA
2976	2019 Ditch Witch S3C 6 ft S/A Equipment Trailer S/N: 1DSB111F7K1703876 C/W: Located in Lane 58 Spot 0, Ball Hitch, 6 ft Main Deck, 42 in Deck Width, Manual Ramps, Steel Decking, 205/75R15 Tires, 3500 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:23 PM CDT Asset located in: Humble, TX, USA	2984	2020 MMDI 412LPT 12 ft S/A Tilt Deck Trailer S/N: 5631T1614LM001379 C/W: Located in Lane 45 Spot 0, Torsion Axle, Surge Brakes, 12 ft Deck Tilting Length, 50 in Deck Width, 235/85R16 Tires, 7700 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:25 PM CDT Asset located in: Humble, TX, USA
2977	2017 CM 16 ft T/A Landscape Trailer S/N: 5VNB1628HT178917 C/W: Ball Hitch, Spring Suspension, 15 ft Deck Length, 78 in Deck Width, Wood Flooring, 205/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:23 PM CDT Asset located in: Midland, TX, USA	2985	2020 MMDI 410LPT 10 ft S/A Tilt Deck Trailer S/N: 5631F1415LM000011 C/W: Located in Lane 42 Spot 33, Torsion Axle, Surge Brakes, 10 ft Deck Tilting Length, 49 in Deck Width, 225/75R15 Tires, 4300 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:25 PM CDT Asset located in: Humble, TX, USA
2979	2026 X-STAR Tilt Deck Trailer (Unused) S/N: 1X9T7CF29TH039006 C/W: Located in Lane 85 Spot 12, Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Deck Tilting Length, 83 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:24 PM CDT Asset located in: Lake Worth, TX, USA	2986	2020 MMDI 410LPT 10 ft S/A Tilt Deck Trailer S/N: 5631F1419LM000013 C/W: Located in Lane 42 Spot 33, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Deck Tilting Length, 52 in Deck Width, 225/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:25 PM CDT Asset located in: Humble, TX, USA
2980	2026 X-STAR 20 ft T/A Tilt Deck Trailer (Unused) S/N: 1X9T7CF24TH039673 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Deck Tilting Length, 83 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:24 PM CDT Asset located in: Lake Worth, TX, USA	2987	2020 MMDI 410LPT 10 ft S/A Tilt Deck Trailer S/N: 5631F1413LM000010 C/W: Located in Lane 42 Spot 33, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Deck Tilting Length, 48 in Deck Width, 225/75R15 Tires, 4400 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:26 PM CDT Asset located in: Humble, TX, USA
2982	2012 Big Tex 16 ft T/A Tilt Deck Trailer S/N: 16VFX1623C2H20039 C/W: Located in Lane 42 Spot 0, Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Deck Tilting Length, 78 in Deck Width, 225/75R15 Tires Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:25 PM CDT Asset located in: Humble, TX, USA	2988	2019 MMDI 410LPT 3100 lb 10 ft S/A Tilt Deck Trailer S/N: 5631F1417KM000025 C/W: Located in Lane 42 Spot 0, Ball Hitch, Torsion Axle, Surge Brakes, 10 ft Deck Tilting Length, 49 in Deck Width, 225/75R15 Tires, 4300 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:26 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
2989	2022 Barreto E4X6TBT 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0617NL280263 C/W: Located in Lane 42 Spot 34, Ball Hitch, Torsion Axle, 6 ft 6 in Deck Tilting Length, 44 in Deck Width, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:26 PM CDT Asset located in: Humble, TX, USA	2995	2026 Double A 8320T7K 20 ft T/A Equipment Trailer S/N: 71UBU2023TT015077 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Main Deck, 3 ft Fixed Dovetail, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:28 PM CDT Asset located in: Lake Worth, TX, USA
2990	2021 Barreto E4X6TBT 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0615ML280244 C/W: Located in Lane 45 Spot 0, Ball Hitch, Torsion Axle, 6 ft 6 in Deck Tilting Length, 44 in Deck Width, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:26 PM CDT Asset located in: Humble, TX, USA	2996	2022 Road Boss 20 ft T/A Equipment Trailer S/N: 5Z0BP2023NP014244 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 02:28 PM CDT Asset located in: Oklahoma City, OK, USA
2991	2021 Barreto E4X6TBT 1671 lb 6.7 ft S/A Tilt Deck Trailer S/N: 1B9UC0612ML280203 C/W: Located in Lane 58 Spot 0, Ball Hitch, Torsion Axle, 44 in Deck Width, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:27 PM CDT Asset located in: Humble, TX, USA	2998	2011 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2024B1014823 C/W: Located in Lane 82 Spot 22, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 235/85R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:28 PM CDT Asset located in: Lake Worth, TX, USA
2992	2020 Barreto E4X6TBT 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0618LL280527 C/W: Located in Lane 42 Spot 34, Ball Hitch, Torsion Axle, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:27 PM CDT Asset located in: Humble, TX, USA	2999	2011 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2029B1011884 C/W: Located in Lane 83 Spot 34, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 235/80R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:29 PM CDT Asset located in: Lake Worth, TX, USA
2993	2026 Double A 10224T7K 24 ft T/A Equipment Trailer S/N: 71UBU2429TT015076 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 4 ft Fixed Dovetail, Deck Over Tires, Manual Ramps, Wood Flooring, Aluminum Wheels, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:27 PM CDT Asset located in: Lake Worth, TX, USA	3000	2010 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2028A1000552 C/W: Located in Lane 85 Spot 14, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 225/90R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:29 PM CDT Asset located in: Lake Worth, TX, USA
2994	2026 Double A 8320T 20 ft T/A Utility Trailer (Unused) S/N: 71UBU2028TT015074 C/W: Located in Lane 43 Spot 0, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:27 PM CDT Asset located in: Humble, TX, USA	3001	2009 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP202291092656 C/W: Located in Lane 85 Spot 14, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 235/80R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:29 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3002	2006 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP202661062412 C/W: Located in Lane 85 Spot 15, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, mixed Tires, Equipment-from-a-Primoris-Services-Corp-company Ramps Usage: Not Available Lot closing time: Thu, Sep 17, 02:29 PM CDT Asset located in: Lake Worth, TX, USA	3007	2014 Bat 18 ft T/A Utility Trailer S/N: 1B9FB18214A439L19 C/W: Located in Lane 82 Spot 30, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, Wood Flooring, 235/85R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:30 PM CDT Asset located in: Lake Worth, TX, USA
3003	2000 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2026Y1004173 C/W: Located in Lane 82 Spot 23, Ball Hitch, Electric Brakes, 82 in Deck Width, Wood Flooring, 225/90R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:29 PM CDT Asset located in: Lake Worth, TX, USA	3008	1998 Sams 18 ft T/A Utility Trailer S/N: 11YUH2126WT000090 C/W: Located in Lane 82 Spot 25, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, Steel Decking, 235/80R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:31 PM CDT Asset located in: Lake Worth, TX, USA
3004	2010 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2028A1000275 C/W: Located in Lane 83 Spot 27, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, Aluminum Wheels, 235/85R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:30 PM CDT Asset located in: Lake Worth, TX, USA	3009	2026 Double A 7716T 16 ft T/A Utility Trailer (Unused) S/N: 71UBU1624TT015073 C/W: Located in Lane 43 Spot 0, Ball Hitch, Spring Suspension, 77 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:31 PM CDT Asset located in: Humble, TX, USA
3004A	2022 Big Tex 14PI-18BK 18 ft T/A Utility Trailer S/N: 16V1W2227N2138924 C/W: Spring Suspension, 84 in Deck Width, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 02:30 PM CDT Asset located in: Lake Worth, TX, USA	3010	2024 C&B Quality Trailer Works DB4C16-6K RMP 16 ft T/A Utility Trailer S/N: 4JUBF1624RN069904 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 6000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:31 PM CDT Asset located in: Livingston, LA, USA
3005	2007 Shopmade 18 ft T/A Utility Trailer S/N: TR197108 C/W: Located in Lane 85 Spot 24, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 235/85R16 Tires, Ramps Usage: Not Available Lot closing time: Thu, Sep 17, 02:30 PM CDT Asset located in: Lake Worth, TX, USA	3011	2024 C&B Quality trailer works DB4C16-6K RMP 16 ft T/A Utility Trailer S/N: 4JUBF162XRN069888 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 6000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:31 PM CDT Asset located in: Livingston, LA, USA
3006	2007 Big Tex 12PI-18 18 ft T/A Utility Trailer S/N: 16VPX182771343984 C/W: Located in Lane 82 Spot 29, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 235/80R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:30 PM CDT Asset located in: Lake Worth, TX, USA	3012	2021 Road Boss 18 ft T/A Utility Trailer S/N: 5Z0UT1823MP012947 C/W: Located in Lane 83, Ball Hitch Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 02:32 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3012A	2018 Big Tex 16 ft T/A Utility Trailer S/N: 16VPX162061304526 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 8 in Deck Width, Wood Flooring Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Lot closing time: Thu, Sep 17, 02:32 PM CDT Asset located in: Midland, TX, USA	3022	2001 Texas Bragg 12 ft T/A Utility Trailer S/N: 17XFP122X11010769 C/W: Located in Lane 83 Spot 28, Ball Hitch, Spring Suspension, Electric Brakes, 78 in Deck Width, Steel Decking, 7.50R16 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:34 PM CDT Asset located in: Lake Worth, TX, USA
3014	2014 Big Tex 70PI-16XBK 16 ft T/A Utility Trailer S/N: 16VPX1626E2E11883 C/W: Located in Lane 83 Spot 25, Ball Hitch, Spring Suspension, 102 in Deck Width, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 02:32 PM CDT Asset located in: Lake Worth, TX, USA	3024	2026 Double A 7714S 14 ft S/A Utility Trailer (Unused) S/N: 71UBU1415TT015075 C/W: Located in Lane 43 Spot 0, Ball Hitch, Spring Suspension, 77 in Deck Width, Ramp, 205/75R15 Tires, 2995 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:34 PM CDT Asset located in: Humble, TX, USA
3014A	2020 Diamond 16 ft T/A Utility Trailer S/N: 53NBE162XL1080936 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Wood Flooring, 225 /75R15 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:32 PM CDT Asset located in: San Antonio, TX, USA	3025	2020 CM 14 ft S/A Utility Trailer S/N: 5VNBU1414LT216176 C/W: Ball Hitch, Spring Suspension, 77 in Deck Width, Wood Flooring, 205/75R15 Tires, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Thu, Sep 17, 02:35 PM CDT Asset located in: Livingston, LA, USA
3017	2026 Double A 8314T 14 ft T/A Equipment Trailer S/N: 71UBU142XTT015078 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 14 ft Main Deck, Manual Ramps, 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Lot closing time: Thu, Sep 17, 02:33 PM CDT Asset located in: Lake Worth, TX, USA	3026	2024 Carry-On 12 ft S/A Utility Trailer S/N: 4YMBU1217RN002396 C/W: Ball Hitch, Spring Suspension, 75 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 2990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:35 PM CDT Asset located in: Livingston, LA, USA
3019	2024 C&B Quality trailer works DB4C14-6K RMP 14 ft T/A Utility Trailer S/N: 4JUBF1424RN069873 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 6000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:33 PM CDT Asset located in: Livingston, LA, USA	3027	2019 Texas Bragg NA612ST2900 12 ft S/A Utility Trailer S/N: 17XFZ1216K1092268 C/W: Ball Hitch, Spring Suspension, 76.5 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 2900 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:35 PM CDT Asset located in: Livingston, LA, USA
3020	2023 C&B Quality Trailer Works DB4C14-6K RMP 14 ft T/A Utility Trailer S/N: 4JUBF1422PN068539 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 6000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:33 PM CDT Asset located in: Livingston, LA, USA	3028	2018 Texas Bragg 12 ft S/A Utility Trailer S/N: 17XFZ1212J1086207 C/W: Ball Hitch, Spring Suspension, 76.5 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 2900 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:35 PM CDT Asset located in: Livingston, LA, USA
		3029	2018 Texas Bragg LD29 12 ft S/A Utility Trailer S/N: 17XFZ1219J1086205 C/W: Ball Hitch, Spring Suspension, 76.5 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:36 PM CDT Asset located in: Livingston, LA, USA

Lot #	Details	Lot #	Details
3032	2016 East Texas Longhorn Trailers, LLC 10 ft S /A Utility Trailer S/N: 5J2US1019GE016877 C/W: Ball Hitch, Spring Suspension, 76.5 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 3500 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:36 PM CDT Asset located in: Livingston, LA, USA	3039	2024 16 ft T/A Gooseneck Dump Utility Trailer S/N: 4ZEGD1628R3320336 C/W: Located in Lane 85 Spot 7, Spring Suspension, 16 ft Body, 48 in Side Walls, Steel Body, Manual Roll Tarp, 2-Way Tailgate, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:38 PM CDT Asset located in: Lake Worth, TX, USA
3033	2013 East Texas Longhorn Trailers, LLC 7x10 10 ft S/A Utility Trailer S/N: 5J2US1016DE012863 C/W: Ball Hitch, Spring Suspension, 76.5 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 3500 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:36 PM CDT Asset located in: Livingston, LA, USA	3040	2024 Load Trail 16 ft T/A Gooseneck Dump Utility Trailer S/N: 4ZEGD1621R3321067 C/W: Located in Lane 85 Spot 9, Spring Suspension, Electric Brakes, 16 ft Body, 48 in Side Walls, Steel Body, Manual Roll Tarp, Split Swing Tailgate, 235/80R16 Tires, 14000 lb GVWR, Ramps Usage: Not Available Lot closing time: Thu, Sep 17, 02:38 PM CDT Asset located in: Lake Worth, TX, USA
3034	2009 Prime Trailers 10 ft S/A Utility Trailer S/N: 1P9BU10109M460122 C/W: Located in Lane 82 Spot 28, Ball Hitch, Spring Suspension, 76 in Deck Width, Ramp, Wood Flooring, 205/75D15 Tires, 2900 lb GVWR, Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership. Lot closing time: Thu, Sep 17, 02:37 PM CDT Asset located in: Lake Worth, TX, USA	3041	2026 Top Hat DE14-14x83-14EF 14 ft T/A Dump Utility Trailer S/N: 4R7BD1428TC262594 C/W: Located in Lane 43 Spot 0, Ball Hitch, Spring Suspension, Electric Brakes, 14 ft Body, 48 in Side Walls, Steel Body, Manual Roll Tarp, Split Swing Tailgate, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:38 PM CDT Asset located in: Humble, TX, USA
3036	2025 RAWMAXX HDX20GN30KHXD 20 ft T/A Gooseneck Dump Utility Trailer S/N: 3EVGD2021S1116312 C/W: Located in Lane 43 Spot 0, Spring Suspension, Electric Brakes, 20 ft Body, 45 in Side Walls, Steel Body, Manual Roll Tarp, Split Swing Tailgate, 235/75R17.5 Tires, 30000 lb GVWR, 8 ft Upper Deck Usage: Not Available Lot closing time: Thu, Sep 17, 02:37 PM CDT Asset located in: Humble, TX, USA	3042	2025 Northstar 14 ft T/A Dump Utility Trailer S/N: 3EUDB1424S1091911 C/W: Located in Lane 85 Spot 9, Ball Hitch, Spring Suspension, Electric Brakes, 14 ft Body, 48 in Side Walls, Steel Body, Manual Roll Tarp, 2-Way Tailgate, 235/80R16 Tires, 14999 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:39 PM CDT Asset located in: Lake Worth, TX, USA
3037	2024 Load Trail 20 ft T/A Gooseneck Dump Utility Trailer S/N: 4ZEGD2025R1317825 C/W: Located in Lane 44 Spot 0, Torsion Axle, Electric Brakes, 20 ft Body, 48 in Side Walls, Steel Body, Split Swing Tailgate, 215/75R17.5 Tires, 20000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:37 PM CDT Asset located in: Humble, TX, USA	3046	2021 Snake DMP714 13 ft 8 in T/A Dump Utility Trailer S/N: 5PTBD142XM1038861 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 13 ft 8 in Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 235/80R16 Tires, 9990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:39 PM CDT Asset located in: Livingston, LA, USA
3038	2026 ED LPT8316273S-BP 16 ft T/A Dump Utility Trailer S/N: 3LHBS1628T7001123 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Body, 36 in Side Walls, Steel Body, Manual Roll Tarp, Split Swing Tailgate, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:38 PM CDT Asset located in: Livingston, LA, USA		

Lot #	Details	Lot #	Details
3047	2021 Snake DMP714-9.9K HD 14 ft T/A Dump Utility Trailer S/N: 5PTBD142XM1036947 C/W: Located in Lane 25 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 14 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 235/80R16 Tires, 9990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:40 PM CDT Asset located in: Humble, TX, USA	3052	2022 Snake DMP610-7K HD 10 ft T/A Dump Utility Trailer S/N: 5PTBD1024N1039835 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:41 PM CDT Asset located in: Livingston, LA, USA
3048	2021 Snake DMP714-9.9K HD 14 ft T/A Dump Utility Trailer S/N: 5PTBD1426M1036945 C/W: Located in Lane 25 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 14 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 235/80R16 Tires, 9990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:40 PM CDT Asset located in: Humble, TX, USA	3053	2021 Pratt EZD11762 10 ft T/A Dump Utility Trailer S/N: 1P9UT1422MN343448 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 24 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 10000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Lot closing time: Thu, Sep 17, 02:41 PM CDT Asset located in: Livingston, LA, USA
3049	2020 Snake DMP714-9.9K HD 14 ft T/A Dump Utility Trailer S/N: 5PTBD1424L1034934 C/W: Located in Lane 45 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 14 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 235/80R16 Tires, 9990 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:40 PM CDT Asset located in: Humble, TX, USA	3054	2021 Snake DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD1026M1038121 C/W: Located in Lane 45 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:41 PM CDT Asset located in: Humble, TX, USA
3050	2020 MMDI 14 ft T/A Dump Utility Trailer S/N: 5631D1522LM001579 C/W: Located in Lane 25 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 31 in Side Walls, Steel Body, Split Swing Tailgate, 235/80R16 Tires, 8360 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:40 PM CDT Asset located in: Humble, TX, USA	3055	2020 Snake DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD102XL1034877 C/W: Located in Lane 42 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:42 PM CDT Asset located in: Humble, TX, USA
3051	2022 Snake DMP610-7K HD 10 ft T/A Dump Utility Trailer S/N: 5PTBD1027N1040770 C/W: Located in Lane 25 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 31 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:41 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
3056	2020 Snake DMP610-7K HD 10 ft T/A Dump Utility Trailer S/N: 5PTBD1024L1034793 C/W: Located in Lane 45 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:42 PM CDT Asset located in: Humble, TX, USA	3060	2020 Snake DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD1029L1034787 C/W: Located in Lane 44 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:43 PM CDT Asset located in: Humble, TX, USA
3057	2020 Snake DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD1027L1034786 C/W: Located in Lane 42 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:42 PM CDT Asset located in: Humble, TX, USA	3061	2020 Snake DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD1020L1034791 C/W: Located in Lane 45 Spot 0, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:43 PM CDT Asset located in: Humble, TX, USA
3058	2020 Snake DMP610-7K HD 10 ft T/A Dump Utility Trailer S/N: 5PTBD102XL1034782 C/W: Located in Lane 45 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 32 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Lot closing time: Thu, Sep 17, 02:42 PM CDT Asset located in: Humble, TX, USA	3062	2020 Snake River DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD1028L1034912 C/W: Located in Lane 44 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 31 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:43 PM CDT Asset located in: Humble, TX, USA
3059	2020 Snake DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD1022L1034923 C/W: Located in Lane 45 Spot 0, Ball Hitch, Spring Suspension, Surge Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:43 PM CDT Asset located in: Humble, TX, USA	3063	2020 Snake DMP610 10 ft T/A Dump Utility Trailer S/N: 5PTBD1022L1034792 C/W: Located in Lane 45 Spot 0, Ball Hitch, Spring Suspension, Electric Brakes, 10 ft Body, 25 in Side Walls, Steel Body, Split Swing Tailgate, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 02:43 PM CDT Asset located in: Humble, TX, USA
		3064	2021 Barreto E4X6TBT 6 ft S/A Trencher Trailer S/N: 1B9UC0613ML280243 C/W: Located in Lane 42 Spot 34, Ball Hitch, Torsion Axle, 5.30-12 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:44 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3067	2016 Trail King TK110HDG+ 55 ton Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ05330GW119187 C/W: Located in Lane 65 Spot 17, 110000 lb GVWR, Hydraulic Removable Gooseneck, 26 ft x 102 in Main Deck, Deck Over Tires, Side Extensions, Air Ride Suspension, S/A Flip Booster Axle, Gasoline Driven Self Contained Hydraulic System Usage: Not Available Lot closing time: Thu, Sep 17, 02:44 PM CDT Asset located in: Lake Worth, TX, USA	3071A	2026 Witzco Tri/A RG52 Lowboy Trailer (Unused) S/N: 1W8A11E3XTS000212 C/W: Unused RG 52 Lowboy Trailer 122540 lb GVWR, Hydraulic Removable Gooseneck, 48'-6" length x 102" wide, 22' ft Loadwell, 3 axle, Folding Side outriggers, open boom trough tail section, Hutchens H9700 Spring Suspension with EMCO leaf springs, Honda GX390 13HP gas engine Self Contained Hydraulic gooseneck, 2" white oak wood boards, Nucor Steel beams, Sealco wire harness, Peterson lights, high gloss acrylic enamel paint. Usage: Not Available Notes: This item is subject to 12% Federal Excise Tax to be paid by purchaser. Lot closing time: Thu, Sep 17, 02:45 PM CDT Asset located in: Livingston, LA, USA
3068	2015 Choice 355DN Tri/A Removable Gooseneck Lowboy Trailer S/N: 1C9DN4734FK883067 C/W: Located in Lane 64 Spot 35, 131000 lb GVWR, Mechanical Removable Gooseneck, 21 ft 6 in x 102 in Main Deck, Deck Over Tires, Side Extensions, Spring Suspension Usage: Not Available Lot closing time: Thu, Sep 17, 02:45 PM CDT Asset located in: Lake Worth, TX, USA	3071B	2026 Witzco Tri/A RG52 Lowboy Trailer (Unused) S/N: 1W8A11E36TS000210 C/W: Unused RG 52 Lowboy Trailer 122540 lb GVWR, Hydraulic Removable Gooseneck, 48'-6" length x 102" wide, 22' ft Loadwell, 3 axle, Folding Side outriggers, open boom trough tail section, Hutchens H9700 Spring Suspension with EMCO leaf springs, Honda GX390 13HP gas engine Self Contained Hydraulic gooseneck, 2" white oak wood boards, Nucor Steel beams, Sealco wire harness, Peterson lights, high gloss acrylic enamel paint. Usage: Not Available Notes: This item is subject to 12% Federal Excise Tax to be paid by purchaser. Lot closing time: Thu, Sep 17, 02:45 PM CDT Asset located in: Livingston, LA, USA
3069	2013 Fontaine Magnitude 55 55 t Tri/A Removable Gooseneck Lowboy Trailer S/N: 13NE53306D3557290 C/W: Located in Lane 65 Spot 22, Hydraulic Removable Gooseneck, Neck Extension, 26 ft 3 in x 102 in Main Deck, Side Extensions, Air Ride Suspension, S/A Pin-On Booster Axle Usage: Not Available Lot closing time: Thu, Sep 17, 02:45 PM CDT Asset located in: Lake Worth, TX, USA	3071C	2026 Witzco Tri/A RG52 Lowboy Trailer (Unused) S/N: 1W8A11E38TS000211 C/W: Unused RG 52 Lowboy Trailer 122540 lb GVWR, Hydraulic Removable Gooseneck, 48'-6" length x 102" wide, 22' ft Loadwell, 3 axle, Folding Side outriggers, open boom trough tail section, Hutchens H9700 Spring Suspension with EMCO leaf springs, Honda GX390 13HP gas engine Self Contained Hydraulic gooseneck, 2" white oak wood boards, Nucor Steel beams, Sealco wire harness, Peterson lights, high gloss acrylic enamel paint. Usage: Not Available Notes: This item is subject to 12% Federal Excise Tax to be paid by purchaser. Lot closing time: Thu, Sep 17, 02:45 PM CDT Asset located in: Livingston, LA, USA
3070	1995 Kalyn LB-3-60T 60 ton Tri/A Lowboy Trailer S/N: 1K9E16311S1005609 C/W: Located in Lane 44 Spot 0, 136040 lb GVWR, 30 ft x 96 in Main Deck, Walking Beam, Plumbed for Booster Axle Usage: Not Available Lot closing time: Thu, Sep 17, 02:45 PM CDT Asset located in: Humble, TX, USA		
3071	2022 Load King 554SS Quad/A Lowboy Trailer S/N: 5LKL59459N1033154 C/W: Located in Lane 65 Spot 27, 138620 lb GVWR, Hydraulic Removable Gooseneck, 26 ft x 102 in Main Deck, Air Lift Axle(s), Air Ride Suspension, Plumbed for Booster Axle Usage: Not Available Lot closing time: Thu, Sep 17, 02:45 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3072	2006 XL XL80MDE T/A 48 ft Extendable Removable Gooseneck Lowboy Trailer S/N: 4U3J048206L006413 C/W: Located in Lane 38 Spot 0, 99550 lb GVWR, Mechanical Removable Gooseneck, Neck Extension, 29 ft x 102 in Main Deck, Upper Deck, Deck Over Tires, Air Ride Suspension, Plumbed for Booster Axle Usage: Not Available Lot closing time: Thu, Sep 17, 02:46 PM CDT Asset located in: Humble, TX, USA	3077	1998 Fontaine TB50NGB Tri/A Removable Gooseneck Lowboy Trailer S/N: 4LF4S4839W3506263 C/W: 116000 lb GVWR, Hydraulic Removable Gooseneck, 23 ft x 102 in Main Deck, Deck Over Tires, Side Extensions, Spring Suspension Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:47 PM CDT Asset located in: San Antonio, TX, USA
3073	2000 Kalya Siebert Tri/A Removable Gooseneck Lowboy Trailer S/N: 5DDSE2822Y1000451 C/W: Located in Lane 37 Spot 0, Mechanical Removable Gooseneck, 28 ft x 102 in Main Deck, Upper Deck, Deck Over Tires, Air Ride Suspension, S/A Flip Booster Axle, Plumbed for Booster Axle Usage: Not Available Lot closing time: Thu, Sep 17, 02:46 PM CDT Asset located in: Humble, TX, USA	3077A	2020 Trail-Eze TE70XTS 48 ft T/A Hydraulic Tail Trailer S/N: 1DAHFC727LC022915 C/W: Located in Lane 65, Air Ride Suspension, 9 ft 10 in Upper Deck, 38 ft 2 in Main Deck, Winch, Upper Deck Ramps, Deck Over Tires, 10R17.5 Tires, 87010 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:47 PM CDT Asset located in: Lake Worth, TX, USA
3074	1998 Fontaine Tri/A Removable Gooseneck Lowboy Trailer S/N: 4LF4S5134W3506445 C/W: Hydraulic Removable Gooseneck, 22 ft x 102 in Main Deck, Deck Over Tires, Side Extensions, Air Ride Suspension, Gasoline Driven Self Contained Hydraulic System Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:46 PM CDT Asset located in: San Antonio, TX, USA	3079	2014 Trail-Eze TE80HT 48 ft T/A Hydraulic Tail Trailer S/N: 1DAHFC722EC021514 C/W: Located in Lane 64 Spot 36, Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, Winch, Deck Over Tires, 245/70R17.5 Tires, 95760 lb GVWR, 4 ft Hydraulic Flip Tail Usage: Not Available Lot closing time: Thu, Sep 17, 02:47 PM CDT Asset located in: Lake Worth, TX, USA
3075	1978 Clark T/A Lowboy Trailer S/N: 00656 C/W: Located in Lane 66, 27 ft x 96 in Main Deck, Upper Deck, Deck Over Tires, Spring Suspension Usage: Not Available Lot closing time: Thu, Sep 17, 02:46 PM CDT Asset located in: Lake Worth, TX, USA	3080	2000 Trail King T/A Hydraulic Tail Trailer S/N: 1TKA04829YM089548 C/W: Located in Lane 100 Spot 11, Air Ride Suspension, 9 ft 2 in Upper Deck, 30 ft 8 in Main Deck, 11 ft 10 in 2-Position Dovetail, Storage Compartments, Winch, Upper Deck Ramps, Deck Over Tires, 10R17.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:47 PM CDT Asset located in: Lake Worth, TX, USA
3076	1999 DouL T850RG-9 Quad/A Removable Gooseneck Lowboy Trailer S/N: 1EP2U5346X1001336 C/W: Located in Lane 65 Spot 1, 100000 lb GVWR, Hydraulic Removable Gooseneck, Neck Extension, 21 ft 8 in x 102 in Main Deck, Air Ride Suspension, Gasoline Driven Self Contained Hydraulic System Usage: Not Available Lot closing time: Thu, Sep 17, 02:46 PM CDT Asset located in: Lake Worth, TX, USA	3081	2016 Fontaine HCILTX22RSA 53 ft T/A Step Deck Trailer S/N: 13N2532C7G1514270 C/W: Located in Lane 25, Air Ride Suspension, Air Brakes, 20+20 ft - Container Pins, 11 ft Upper Deck, 42 ft Main Deck, 102 in Deck Width, Storage Compartments, Wood Flooring, 245/70R17.5 Tires, 86667 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:48 PM CDT Asset located in: Humble, TX, USA
		3082	2004 Fontaine 53 ft T/A Spread Axle Step Deck Trailer S/N: 13N25330341520339 C/W: Located in Lane 38 Spot 19, Air Ride Suspension, 8 ft 6 in Upper Deck, 44 ft 6 in Main Deck, Deck Over Tires, Wood Flooring, 235 /75R17.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:48 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3083	2015 Manac 13342A000 41 ft Tri/A Step Deck Trailer S/N: 2M5131286F1151263 C/W: Located in Lane 66 Spot 27, Air Ride Suspension, 9 ft Upper Deck, 32 ft Main Deck, Deck Over Tires, Wood Flooring, Aluminum Wheels, 255/70R22.5 Tires, 100849 lb GVWR Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 02:48 PM CDT Asset located in: Lake Worth, TX, USA	3088	2024 Extreme 53 ft T/A Spread Axle Step Deck Trailer S/N: 7VGAB5324R1001416 C/W: Located in Lane 66 Spot 23, Aluminum Frame, Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 96 in Deck Width, Aluminum w /Wood Strips Flooring, Aluminum Wheels, 255 /70R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:49 PM CDT Asset located in: Lake Worth, TX, USA
3084	2015 Manac 13342A000 41 ft Tri/A Step Deck Trailer S/N: 2M5131288F1151264 C/W: Located in Lane 66 Spot 8, Air Ride Suspension, 9 ft Upper Deck, 32 ft Main Deck, 96 in Deck Width, Wood Flooring, Aluminum Wheels, 255/70R22.5 Tires, 100849 lb GVWR Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 02:48 PM CDT Asset located in: Lake Worth, TX, USA	3090	2005 Trail King 53 ft T/A Spread Axle Step Deck Trailer S/N: 1TKBU53275B077732 C/W: Located in Lane 38 Spot 22, Air Ride Suspension, 8 ft 6 in Upper Deck, 44 ft 6 in Rear Deck, Storage Compartments, Deck Over Tires, Wood Flooring, 235/75R17.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:50 PM CDT Asset located in: Humble, TX, USA
3085	2024 Extreme T/A Step Deck Trailer S/N: 7VGAB5325R1001425 C/W: Located in Lane 37 Spot 38, Aluminum Frame, Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 102 in Deck Width, Deck Over Tires, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:49 PM CDT Asset located in: Humble, TX, USA	3090A	2008 XL Specialized XL30DD 52 ft T/A Step Deck Trailer S/N: 4U3J052208L008258 C/W: Located in Lane 37, Air Ride Suspension, 11 ft Upper Deck, 32 ft 6 in Main Deck, 7 ft 6 in Rear Deck, 102 in Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:50 PM CDT Asset located in: Humble, TX, USA
3086	2024 Extreme 53 ft T/A Step Deck Trailer S/N: 7VGAB5320R1001414 C/W: Located in Lane 37 Spot 39, Aluminum Frame, Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 102 in Deck Width, Deck Over Tires, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:49 PM CDT Asset located in: Humble, TX, USA	3091	2006 Transcraft Eagle RS2 52 ft T/A Step Deck Trailer S/N: 1TTE5220861080011 C/W: Located in Lane 44 Spot 13, Air Ride Suspension, 20+20 ft - Container Pins, 11 ft Upper Deck, 41 ft Main Deck, 102 in Deck Width, Storage Compartments, Deck Over Tires, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:50 PM CDT Asset located in: Humble, TX, USA
3087	2024 Extreme 53 ft T/A Step Deck Trailer S/N: 7VGAB5320R1001428 C/W: Located in Lane 37 Spot 40, Aluminum Frame, Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 102 in Deck Width, Deck Over Tires, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:49 PM CDT Asset located in: Humble, TX, USA	3091A	2007 Fontaine EDFT-7-8048WSAWK 48 ft T/A Spread Axle Step Deck Trailer S/N: 13N24830971538686 C/W: Located in Lane 38, Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 102 in Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 69556 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:50 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3092	1989 Utility 48 ft T/A Step Deck Trailer S/N: 1UYFS2486KA192801 C/W: Located in Lane 66 Spot 26, Spring Suspension, 12 ft Upper Deck, 36 ft Main Deck, 0 ft Rear Deck, Deck Over Tires, Wood Flooring, Aluminum Wheels, 255/70R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:50 PM CDT Asset located in: Lake Worth, TX, USA	3098	2019 Fontaine HAICF12WSA 48 ft T/A Spread Axle Flatbed Trailer S/N: 13N148204K1532249 C/W: Located in Lane 38 Spot 1, Air Ride Suspension, 102 in Deck Width, Aluminum w /Wood Strips Flooring, Aluminum Outer Wheels, 11R22.5 Tires, 70540 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:52 PM CDT Asset located in: Humble, TX, USA
3093	2014 Viking VFD46R16F35T 45 ft T/A Step Deck Trailer S/N: 1V9CR4629EN062140 C/W: Spring Suspension, 9 ft Upper Deck, 28 ft 6 in Main Deck, 4 ft 8 in Fixed Dovetail, 102 in Deck Width, Spring Assisted Ramps, Wood Flooring, 255/70R22.5 Tires, 86000 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:50 PM CDT Asset located in: San Antonio, TX, USA	3099	2016 Utility FS2CHA 48 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2488GA460545 C/W: Air Ride Suspension, 96 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 73000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:52 PM CDT Asset located in: Midland, TX, USA
3094	2007 Viking VFD46R16F35T 42 ft T/A Step Deck Trailer S/N: 1V9CR46207NO62160 C/W: Spring Suspension, Air Brakes, 9 ft Upper Deck, 28 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 86000 lb GVWR Usage: 22,870 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:51 PM CDT Asset located in: San Antonio, TX, USA	3100	2008 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B482581166176 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 65000 lb GVWR Usage: 31,756 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:52 PM CDT Asset located in: San Antonio, TX, USA
3095	2006 Viking 43 ft T/A Step Deck Trailer S/N: 1V9CR46256NO62945 C/W: Spring Suspension, Air Brakes, 9 ft Upper Deck, 29 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 86000 lb GVWR Usage: 4,517 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:51 PM CDT Asset located in: San Antonio, TX, USA	3101	2008 Utility FS2CHS 48 ft T/A Flatbed Trailer S/N: 1UYFS24818A330317 C/W: Located in Lane 39 Spot 1, Spring Suspension, 102 in Deck Width, Wood Flooring, Aluminum Outer Wheels, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:52 PM CDT Asset located in: Humble, TX, USA
3096	2000 Doonan 50 ft T/A Step Deck Trailer S/N: 1D9BG502X41208053 C/W: Air Ride Suspension, Air Brakes, 9 ft Upper Deck, 41 ft Main Deck, 102 in Deck Width, Deck Over Tires, Tail Roller, Wood Flooring, 255/70R22.5 Tires, 90000 lb GVWR Usage: 45,845 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:51 PM CDT Asset located in: San Antonio, TX, USA	3102	2008 Utility FS2CHA 48 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS24828A492070 C/W: Located in Lane 38 Spot 2, Air Ride Suspension, Aluminum w/Wood Strips Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:53 PM CDT Asset located in: Humble, TX, USA
3097	1999 Viking 42 ft T/A Step Deck Trailer S/N: 1V9CR4621XN062281 C/W: Spring Suspension, Air Brakes, 7 ft Upper Deck, 30 ft Main Deck, 0 m Rear Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires Usage: 28,517 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:51 PM CDT Asset located in: San Antonio, TX, USA	3103	2007 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820572019320 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, 11R24.5 Tires, 65000 lb GVWR Usage: 62,201 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:53 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
3104	2007 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820972019319 C/W: Spring Suspension, Air Brakes, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 65000 lb GVWR Usage: 61,887 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:53 PM CDT Asset located in: San Antonio, TX, USA	3110	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F5WS457924 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:54 PM CDT Asset located in: San Antonio, TX, USA
3105	2007 Transcraft 48X102 48 ft T/A Flatbed Trailer S/N: 1TTF4820772019321 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 65000 lb GVWR Usage: 23,426 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:53 PM CDT Asset located in: San Antonio, TX, USA	3111	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F2WS448307 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 67,226 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:55 PM CDT Asset located in: San Antonio, TX, USA
3106	2007 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820272018688 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 65000 lb GVWR Usage: 32,692 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:53 PM CDT Asset located in: San Antonio, TX, USA	3112	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F9WS448319 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 145,856 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:55 PM CDT Asset located in: San Antonio, TX, USA
3107	2007 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820072018687 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:54 PM CDT Asset located in: San Antonio, TX, USA	3113	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F8WS457920 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 30,473 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:55 PM CDT Asset located in: San Antonio, TX, USA
3108	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F8WS485314 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 116,722 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:54 PM CDT Asset located in: San Antonio, TX, USA	3114	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482FXWS457921 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 209 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:55 PM CDT Asset located in: San Antonio, TX, USA
3109	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F4WS448311 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 68,310 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:54 PM CDT Asset located in: San Antonio, TX, USA	3115	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F3WS457923 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 68,497 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:56 PM CDT Asset located in: San Antonio, TX, USA

Lot #	Details	Lot #	Details
3116	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F1WS457919 C/W: Spring Suspension, Air Brakes, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 88,087 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:56 PM CDT Asset located in: San Antonio, TX, USA	3123	1985 Lufkin 45 ft T/A Flatbed Trailer S/N: 1L01B4525F1068525 C/W: Located in Lane 65 Spot 25, Spring Suspension, 100 in Deck Width, Wood Flooring, 11R24.5 Tires, 92000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:57 PM CDT Asset located in: Lake Worth, TX, USA
3117	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F4WS485312 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 100,719 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:56 PM CDT Asset located in: San Antonio, TX, USA	3124	1980 Hobbs 40 ft T/A Flatbed Trailer S/N: FHT389903 C/W: Located in Lane 66 Spot 5, Spring Suspension, 98 in Deck Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:58 PM CDT Asset located in: Lake Worth, TX, USA
3118	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482F0WS448306 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 55,919 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:56 PM CDT Asset located in: San Antonio, TX, USA	3125	1977 Lufkin 37 ft T/A Flatbed Trailer S/N: 47990 C/W: Located in Lane 66 Spot 26, Spring Suspension, 96 in Deck Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:58 PM CDT Asset located in: Lake Worth, TX, USA
3119	1998 Fruehauf 48 ft T/A Flatbed Trailer S/N: 1JJF482FXWS485315 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 102 in Deck Width, Wood Flooring, 11R24.5 Tires, 100000 lb GVWR Usage: 11,498 Mi Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 02:57 PM CDT Asset located in: San Antonio, TX, USA	3126	2025 Metalium 40 ft T/A Flatbed Trailer S/N: 3NGGF4028S1001655 C/W: Located in Lane 38 Spot 10, Spring Suspension, Electric Brakes, 102 in Deck Width, Wood Flooring, 235/85R16 Tires, 15680 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:58 PM CDT Asset located in: Humble, TX, USA
3120	2014 Great Dane 45 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM90205M701199 C/W: Located in Lane 38 Spot 3, Air Ride Suspension, Pintle Hitch, 102 in Deck Width, Aluminum w/Wood Strips Flooring, 11R24.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:57 PM CDT Asset located in: Humble, TX, USA	3127	2025 Trailmaxx SD27-40 40 ft T/A Gooseneck Flatbed Trailer S/N: 7WL3H4022ST000804 C/W: Located in Lane 38 Spot 12, Spring Suspension, Electric Brakes, 102 in Deck Width, Wood Flooring, 235/80R16 Tires, 15500 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:58 PM CDT Asset located in: Humble, TX, USA
3121	2007 Lufkin 45 ft T/A Flatbed Trailer S/N: 1L01B452871164540 C/W: Located in Lane 66 Spot 9, Spring Suspension, Forklift Mount Kit, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:57 PM CDT Asset located in: Lake Worth, TX, USA	3128	2013 Big Tex 36 ft T/A Flatbed Trailer S/N: 16VGX3628D2656336 C/W: Spring Suspension, Electric Brakes, 97 in Deck Width, Wood Flooring, 235/80R16 Tires, 22500 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 02:59 PM CDT Asset located in: Midland, TX, USA
		3130	2015 Load Trail 22 ft T/A Flatbed Trailer S/N: 4ZEDK2227F1066954 C/W: Located in Lane 83 Spot 37, Ball Hitch, Spring Suspension, Wood Flooring, 235/85R16 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 02:59 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3133	2004 Holden HMD60 58 ft 5 axle Lowboy Oilfield Trailer S/N: 12HMD58534N609378 C/W: Located in Lane 58 Spot 0, Air Ride Suspension, 108 in Deck Width, 48 ft Main Deck, Pickup Throat, Tail Roller, 255/70R22.5 Tires, 156020 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:00 PM CDT Asset located in: Humble, TX, USA	3146	2026 Kaufman Tri/A Open Car Carrier Trailer S/N: 7UZFL4334TB000861 C/W: Spring Suspension, Electric Brakes, 235 /80R16 Tires, 14800 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:03 PM CDT Asset located in: Midland, TX, USA
3134	2015 Doonan 402DCB1CHFFBT 40 ft Tri/A Step Deck Oilfield Trailer S/N: 1D9BG4032F1609676 C/W: Located in Lane 38 Spot 18, Air Ride Suspension, Lift 1st- Axles, 102 in Deck Width, 10 ft Upper Deck, 30 ft Main Deck, Pickup Throat, Tail Roller, Kicker Rollers, 255/70R22.5 Tires, 110000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:00 PM CDT Asset located in: Humble, TX, USA	3148	2021 Texas Pride CA84724KGN Tri/A 4 Car Open Car Carrier Trailer S/N: 7HCGC4530MB026933 C/W: Located in Lane 81, Spring Suspension, Electric Brakes, 215/75R17.5 Tires, 27000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:03 PM CDT Asset located in: Lake Worth, TX, USA
3136	2012 Texas Pride 36600 lb 52 ft Tri/A Flatbed Oilfield Trailer S/N: 1B9N3UGT0CC624069 C/W: Electric Brakes, Plumbed for Booster Axle, 98 in Deck Width, 7.50R16LT Tires, 36600 lb GVWR Usage: 3,559 Hr Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 03:00 PM CDT Asset located in: Pecos, TX, USA	3150	2025 MP Tri/A Gooseneck Car Carrier Trailer S/N: 4M9BG4438S1144498 C/W: Located in Lane 81 Spot 24, Spring Suspension, 235/80R16 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:04 PM CDT Asset located in: Lake Worth, TX, USA
3142	2009 Trail King Wind Blade and Tower Trailer S/N: 1TKB053249M087578 C/W: Located in Lane 100, Air Ride Suspension, Steering 1st- 2nd- Axle, 245 /70R17.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Lot closing time: Thu, Sep 17, 03:02 PM CDT Asset located in: Lake Worth, TX, USA	3151	2026 Double A 8320T7K 20 ft T/A Equipment Trailer (Unused) S/N: 71UBU2024TT015072 C/W: Located in Lane 38 Spot 21, Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Deck Width, Manual Ramps, Wood Flooring, 205/75R15 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:04 PM CDT Asset located in: Humble, TX, USA
3143	2009 Trail King Wind Blade and Tower Trailer S/N: 1TKB053229M087577 C/W: Located in Lane 100, Air Ride Suspension, Steering 1st- 2nd- Axle, 245 /70R17.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:02 PM CDT Asset located in: Lake Worth, TX, USA	3152	2020 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1921LA801007 C/W: Located in Lane 83 Spot 7, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Seller supplied maintenance record attached in the document section below Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 03:04 PM CDT Asset located in: Lake Worth, TX, USA
3144	2009 Trail King TK70EFX-EFX Wind Blade and Tower Trailer S/N: 1TKB053269M117910 C/W: Located in Lane 62 Spot 50, Air Ride Suspension, Steering 1st- 2nd- Axle, 235 /75R17.5 Tires, 96120 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Lot closing time: Thu, Sep 17, 03:02 PM CDT Asset located in: Lake Worth, TX, USA	3154	2020 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1928LA800887 C/W: Located in Lane 38 Spot 0, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 03:05 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3159	2020 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1929LA801269 C/W: Located in Lane 83 Spot 32, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR, Ramps, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below; Texas residents must stop by title counter to sign required documents for title transfer Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 03:06 PM CDT Asset located in: Lake Worth, TX, USA	3185	2019 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1928KA800712 C/W: Located in Lane 38 Spot 0, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 03:12 PM CDT Asset located in: Humble, TX, USA
3172	2020 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1924LA801194 C/W: Located in Lane 83 Spot 12, Aluminum Frame, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below; Texas residents must stop by title counter to sign required documents for title transfer Vehicle history report available in the document section Lot closing time: Thu, Sep 17, 03:09 PM CDT Asset located in: Lake Worth, TX, USA	3186	2019 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1929KA800492 C/W: Located in Lane 83 Spot 13, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 03:12 PM CDT Asset located in: Lake Worth, TX, USA
3181	2020 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1929LA800946 C/W: Located in Lane 83 Spot 2, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, Ramps, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below; Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 03:11 PM CDT Asset located in: Lake Worth, TX, USA	3191	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR28PG003267 C/W: Located in Lane 38 Spot 26, Spring Suspension, 40 ft - Container Pins, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:13 PM CDT Asset located in: Humble, TX, USA
3181	2020 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1929LA800946 C/W: Located in Lane 83 Spot 2, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, Ramps, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below; Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 03:11 PM CDT Asset located in: Lake Worth, TX, USA	3192	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR26PG003266 C/W: Located in Lane 38 Spot 27, Spring Suspension, 40 ft - Container Pins, Aluminum Outer Wheels, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:14 PM CDT Asset located in: Humble, TX, USA
		3193	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR21PG003269 C/W: Located in Lane 38 Spot 28, Spring Suspension, 40 ft - Container Pins, Aluminum Outer Wheels, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:14 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3194	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR2XPG003268 C/W: Located in Lane 38 Spot 29, Spring Suspension, 40 ft - Container Pins, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:14 PM CDT Asset located in: Humble, TX, USA	3208	2007 Trail King TK22FA-051 S/A Booster Axle S/N: 1TKS005177M078099 C/W: Located in Lane 47 Spot 0, Flip-Up, Air Ride Suspension, Aluminum Wheels, 255 /70R22.5 Tires, 20280 lb GVWR Usage: Not Available Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** If a title is required in the buyer's state, then the buyer is responsible for obtaining a bonded title. Lot closing time: Thu, Sep 17, 03:17 PM CDT Asset located in: Humble, TX, USA
3195	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR24PG003265 C/W: Located in Lane 78 Spot 24, Spring Suspension, 40 ft - Container Pins, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:14 PM CDT Asset located in: Humble, TX, USA	3209	2006 Talbert S/A Booster Axle S/N: 40FAK061561029917 C/W: Located in Lane 65 Spot 1, Steerable, Pin-On, Air Ride Suspension, 275/70R22.5 Tires, 24700 lb GVWR Usage: Not Available Notes: No Title available. Bill of Sale will be provided upon request to transfer ownership Lot closing time: Thu, Sep 17, 03:18 PM CDT Asset located in: Lake Worth, TX, USA
3196	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR24PG001015 C/W: Located in Lane 38 Spot 30, Air Ride Suspension, Air Brakes, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:14 PM CDT Asset located in: Humble, TX, USA	3210	2008 Trail King TK25FA-051 S/A Booster Axle S/N: 1TKS005148B015359 C/W: Located in Lane 25 Spot 0, Flip-Up, Air Ride Suspension, Aluminum Outer Wheels, 295 /75R22.5 Tires, 25000 lb GVWR Usage: Not Available Notes: **No Title available. Bill of Sale will be provided upon request to transfer ownership** If buyer' state requires a title, then the buyer will have to obtain a bonded title at their own cost. Lot closing time: Thu, Sep 17, 03:18 PM CDT Asset located in: Humble, TX, USA
3196B	2007 Dragon TCT440 T/A Roll-Off Trailer S/N: 1UNSH48227C053160 C/W: Air Ride Suspension, 285/75R24.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:15 PM CDT Asset located in: Lake Worth, TX, USA	3210A	2002 Trail King S/A Booster Axle S/N: 1TKS005152B098761 C/W: Located in Lane 25 Spot 0, Flip-Up, Air Ride Suspension, Aluminum Outer Wheels, 295 /75R22.5 Tires Usage: Not Available Notes: **No Title available. A bill of Sale will be provided upon request to transfer ownership. If the buyer's state requires a title, the buyer is responsible for obtaining a bond title at their own cost. Lot closing time: Thu, Sep 17, 03:18 PM CDT Asset located in: Humble, TX, USA
3200	2025 RAWMAXX RDX16GN14K T/A Roll-Off Trailer S/N: 3EVGD1624S1116323 C/W: Located in Lane 85 Spot 1, Spring Suspension, Electric Brakes, Rawmaxx Roll-Off Unit Electric Roll Tarp, 235/80R16 Tires, 14000 lb GVWR, 16 ft Roll-Off Bin, 17500 lb Warrior 175SD12 Electric Winch Usage: Not Available Lot closing time: Thu, Sep 17, 03:15 PM CDT Asset located in: Lake Worth, TX, USA	3211	2006 Trail King 6 Axle Dolly S/N: 1TKS0426X6M024950 C/W: Air Ride Suspension, Aluminum Wheels, 235/75R17.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:18 PM CDT Asset located in: Lake Worth, TX, USA
3201	2025 Texas Pride RO71414KGN T/A Roll-Off Trailer S/N: 7HCGD1422SB067629 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: Selling with a Repossession affidavit and may not be accepted in your state. Verify with your local DMV prior to bidding Lot closing time: Thu, Sep 17, 03:16 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3212	2018 Galyean 130 bbl T/A Vacuum Tanker Trailer S/N: 1G9VT4224JH015144 C/W: Located in Lane 39 Spot 14, Air Ride Suspension, Air Brakes, 11R24.5 Tires, Steel Tank, Catwalk, Equipment-from-R-Construction – 130 BBL Usage: Not Available Notes: From the Well Maintained Fleet of R Construction Lot closing time: Thu, Sep 17, 03:18 PM CDT Asset located in: Humble, TX, USA	3218	2012 Dragon 150 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4225CL109223 C/W: Located in Lane 39 Spot 21, Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Aluminum Tank, Catwalk w/Guardrails, 70000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:20 PM CDT Asset located in: Humble, TX, USA
3213	2018 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4227JL153589 C/W: Located in Lane 39 Spot 17, Air Ride Suspension, Air Brakes, 11R24.5 Tires, Steel Tank, Equipment-from-R-Construction – 130 BBL Usage: Not Available Notes: From the Well Maintained Fleet of R Construction Lot closing time: Thu, Sep 17, 03:18 PM CDT Asset located in: Humble, TX, USA	3219	2010 Dragon 150 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4229AL068639 C/W: Located in Lane 39 Spot 23, Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Aluminum Tank, Catwalk w/Guardrails, 70000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:20 PM CDT Asset located in: Humble, TX, USA
3215	2018 Galyean 130 bbl T/A Vacuum Tanker Trailer S/N: 1G9VT4226JH015145 C/W: Located in Lane 39 Spot 19, Air Ride Suspension, 11R24.5 Tires, Steel Tank, 67800 lb GVWR, Equipment-from-R-Construction Usage: Not Available Notes: From the Well Maintained Fleet of R Construction Lot closing time: Thu, Sep 17, 03:19 PM CDT Asset located in: Humble, TX, USA	3220	2010 Dragon 150 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4226AL068730 C/W: Located in Lane 39 Spot 24, Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Aluminum Tank, Catwalk w/Guardrails, 70000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:20 PM CDT Asset located in: Humble, TX, USA
3215A	2018 Galyean 130 bbl T/A Vacuum Tanker Trailer S/N: 1G9VT422XJH015147 C/W: Located in Lane 39 Spot 18, Air Ride Suspension, Air Brakes, Aluminum Wheels, 11R24.5 Tires, Steel Tank, Catwalk, Equipment-from-R-Construction –130 BBL Usage: Not Available Notes: From the Well Maintained Fleet of R Construction Lot closing time: Thu, Sep 17, 03:19 PM CDT Asset located in: Humble, TX, USA	3221	2009 Dragon 150 bbl T/A Vacuum Tanker Trailer S/N: 1UNST42279L068618 C/W: Located in Lane 39 Spot 25, Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Aluminum Tank, Catwalk w/Guardrails, 70000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:20 PM CDT Asset located in: Humble, TX, USA
3217	2013 Dragon 150 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4226DL109233 C/W: Located in Lane 39 Spot 31, Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Aluminum Tank, Catwalk w/Guardrails, 70000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:19 PM CDT Asset located in: Humble, TX, USA	3228	2013 Brennar 8820 gal T/A Tanker Trailer S/N: 10BFA8235DF0C7321 C/W: Air Ride Suspension, Aluminum Outer Wheels, 11R22.5 Tires, Aluminum Tank, Commerce Hydraulic Powered Pump, 65000 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 03:22 PM CDT Asset located in: San Antonio, TX, USA
		3229	2013 Polar MC407 9210 gal T/A Tanker Trailer S/N: 1PMA34229D5011438 C/W: Located in Lane 39 Spot 0, Air Ride Suspension, Aluminum Wheels, 295/75R22.5 Tires, Aluminum Tank, Roper Hydraulic Powered Pump, 66000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:22 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3230	2013 Polar Tank MC407 8400 gal T/A Tanker Trailer S/N: 1PMA34222D5011457 C/W: Located in Lane 40 Spot 4, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank, Roper Hydraulic Powered Pump, 66000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:22 PM CDT Asset located in: Humble, TX, USA	3234	2011 Stephens MC407 8400 gal T/A Tanker Trailer S/N: 1S9AB15B6BH474240 C/W: Located in Lane 39 Spot 22, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank, Roper Hydraulic Powered Pump, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:23 PM CDT Asset located in: Humble, TX, USA
3231	2012 Polar Tank MC407 8400 gal T/A Tanker Trailer S/N: 1PMA34228C1038040 C/W: Located in Lane 40 Spot 2, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank, Roper Hydraulic Powered Pump, 66000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:23 PM CDT Asset located in: Humble, TX, USA	3236	2011 Polar Tank MC407 8400 gal T/A Tanker Trailer S/N: 1PMA34224B1037515 C/W: Located in Lane 39 Spot 30, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank, 66000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:24 PM CDT Asset located in: Humble, TX, USA
3232	2012 Polar Tank MC407 8400 gal T/A Tanker Trailer S/N: 1PMA34227C1038059 C/W: Located in Lane 34 Spot 10, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank, Roper Hydraulic Powered Pump Usage: Not Available Lot closing time: Thu, Sep 17, 03:23 PM CDT Asset located in: Humble, TX, USA	3237	2011 Stephens MC407 8400 gal T/A Tanker Trailer S/N: 1S9AB15B2BH474106 C/W: Located in Lane 39 Spot 0, Air Ride Suspension, Aluminum Wheels, 11R22.5 Tires, Aluminum Tank, Roper Hydraulic Powered Pump Usage: Not Available Lot closing time: Thu, Sep 17, 03:24 PM CDT Asset located in: Humble, TX, USA
3232A	2012 Polar 8400 gal T/A Tanker Trailer S/N: 1PMA34226C1039025 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank, Hydraulic Powered Pump, 66000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:23 PM CDT Asset located in: San Antonio, TX, USA	3239A	2011 Brenner 8820 gal T/A Crude Oil Tanker Trailer S/N: 10BFA8239BF0C5455 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Aluminum Wheels, 11R22.5 Tires, Aluminum Tank, Roger Hydraulic Powered Pump, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:25 PM CDT Asset located in: Midland, TX, USA
3232B	2012 Tytal 8400 gal T/A Tanker Trailer S/N: 3T1L1T624CC000687 C/W: Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Aluminum Tank, Commerce Hydraulic Powered Pump, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:23 PM CDT Asset located in: San Antonio, TX, USA	3240	2008 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452585G22309 C/W: Located in Lane 39 Spot 28, Air Ride Suspension, 11R24.5 Tires, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:25 PM CDT Asset located in: Humble, TX, USA
3233	2012 Heil 8400 gal T/A Tanker Trailer S/N: 5HTDL4523C5G24066 C/W: Air Ride Suspension, 11R24.5 Tires, Aluminum Tank, Hydraulic Powered Pump, 65000 lb GVWR Usage: Not Available Notes: License plates will not be provided. Lot closing time: Thu, Sep 17, 03:23 PM CDT Asset located in: San Antonio, TX, USA	3241	2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452535G14705 C/W: Located in Lane 40 Spot 1, Spring Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank, . Pump, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:25 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3242	1991 Polar ASTB6 11000 gal T/A Tanker Trailer S/N: 1PMS24527M1011285 C/W: Located in Lane 39 Spot 20, Air Ride Suspension, Aluminum Wheels, 445/50R22.5 Super Single Tires, Stainless Steel Tank, 5 Compartments, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:25 PM CDT Asset located in: Humble, TX, USA	3251	2026 X-STAR 990GL T/A 750 gal Fuel Trailer (Unused) S/N: 1X9T7BA25TH039991 C/W: Located in Lane 86 Spot 25, Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 12000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:27 PM CDT Asset located in: Lake Worth, TX, USA
3243	1985 Stainless Steel Tank MC307 7000 gal T/A Tanker Trailer S/N: 1S9T74221F0017083 C/W: Located in Lane 40 Spot 5, Spring Suspension, 11R22.5 Tires, Stainless Steel Tank, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:25 PM CDT Asset located in: Humble, TX, USA	3253	2026 X-STAR 750GL T/A 750 gal Fuel Trailer (Unused) S/N: 1X9T7B82XTH039989 C/W: Located in Lane 86 Spot 27, Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 12000 lb GVWR, 12 v Pump w/ Nozzle Usage: Not Available Lot closing time: Thu, Sep 17, 03:28 PM CDT Asset located in: Lake Worth, TX, USA
3244	1983 Heil 9000 gal T/A Tanker Trailer S/N: 1HLA3A7B6D7H52345 C/W: Located in Lane 100, Aluminum Frame, Spring Suspension, Air Brakes, 11R22.5 Tires, Aluminum Tank, 5 Compartments, 70000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:26 PM CDT Asset located in: Lake Worth, TX, USA	3254	2026 X-STAR 750GL T/A 990 gal Fuel Trailer (Unused) S/N: 1X9T7B826TH039987 C/W: Located in Lane 86 Spot 28, Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 12000 lb GVWR, 12 v Pump w/ Nozzle Usage: Not Available Lot closing time: Thu, Sep 17, 03:28 PM CDT Asset located in: Lake Worth, TX, USA
3246	2026 X-STAR 1450GL 1450 gal T/A Water Tank Trailer (Unused) S/N: 1X9T7BA25TH039988 C/W: Located in Lane 86 Spot 20, Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, 14000 lb GVWR, Nikata 2 in Water Pump Usage: Not Available Lot closing time: Thu, Sep 17, 03:26 PM CDT Asset located in: Lake Worth, TX, USA	3255	2026 X-STAR 750GL T/A 750 gal Fuel Trailer (Unused) S/N: 1X9T7B826TH039990 C/W: Located in Lane 86 Spot 24, Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 12000 lb GVWR, 12 v Pump w/ Nozzle Usage: Not Available Lot closing time: Thu, Sep 17, 03:28 PM CDT Asset located in: Lake Worth, TX, USA
3247	2023 Multiquip 525 gal T/A Water Tank Trailer S/N: 4GNBM1220PB066506 C/W: Located in Lane 104 Spot 0, Ball Hitch, Spring Suspension, 205/75R14 Tires, Poly Tank, MQ Gasoline Powered Pump, 7000 lb GVWR Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 03:26 PM CDT Asset located in: Humble, TX, USA	3257	2012 Delucin T/A Pneumatic Bulk Trailer S/N: 3BYD6TE29CH005151 C/W: Air Ride Suspension, 11R24.5 Tires, Steel Tank, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Lot closing time: Thu, Sep 17, 03:29 PM CDT Asset located in: Lake Worth, TX, USA
3250	T/A Water Tank Trailer S/N: 400592 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 205/75R15 Tires, Poly Tank, (2) Hose Reels Usage: Not Available Lot closing time: Thu, Sep 17, 03:27 PM CDT Asset located in: Midland, TX, USA	3258	1982 Fruehauf HEBF2J 985 cft T/A Pneumatic Bulk Trailer S/N: 1H4B04120CL005023 C/W: Located in Lane 64 Spot 32, Spring Suspension, 11R24.5 Tires, Steel Tank, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:29 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3260	2012 Overbilt Trailer Company Nitrogen Pump Trailer S/N: 1Z9SD4529C0058381 C/W: MTU V12 Diesel Engine, T/A Carrier, Air Ride Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 03:29 PM CDT Asset located in: Pecos, TX, USA	3264	2010 Atoka Fluid Pumper Trailer S/N: 1A9L8353XAA245883 C/W: Air Ride Suspension, Air Brakes, Aluminum Wheels, 11R22.5 Tires Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 03:30 PM CDT Asset located in: Pecos, TX, USA
3261	2012 Loadcraft LC1-35T-C Nitrogen Pump Trailer S/N: 5ABK49302CB120478 C/W: Deutz 6 Cylinder Diesel Engine, CS&P Technologies 40JLCT Nitrogen Pump, Tri/A Carrier, Air Ride Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 03:30 PM CDT Asset located in: Pecos, TX, USA	3265	2006 Doonan Specialized Trailer Coil Tubing Reel Trailer S/N: 1D9BG453261208010 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 03:31 PM CDT Asset located in: Pecos, TX, USA
3262	2013 Peerless Limited (1) Coil Tubing Reel Trailer S/N: 2PLC05338DBM16656 C/W: Air Ride Suspension, Air Brakes, Aluminum Wheels, 255/70R22.5 Tires, 187392 lb GVWR Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 03:30 PM CDT Asset located in: Pecos, TX, USA	3266	2006 PJ 16 ft x 83 in T/A Manifold Trailer S/N: 4P5C51621L1328240 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:31 PM CDT Asset located in: Midland, TX, USA
3263	2013 Peerless Limited Coil Tubing Reel Trailer S/N: 2PLC0533XDBM16657 C/W: Tri Axle Carrier Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 03:30 PM CDT Asset located in: Pecos, TX, USA	3267	2023 Armor Lite SHD-40/100 40 ft T/A End Dump Trailer S/N: 56EA75K25PA000394 C/W: Spring Suspension, 40 ft Body, 8 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:31 PM CDT Asset located in: Midland, TX, USA
		3268	2023 Armor Lite SHD-40/100 40 ft T/A End Dump Trailer S/N: 56EA75K24PA000421 C/W: Spring Suspension, 40 ft Body, 8 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:31 PM CDT Asset located in: Midland, TX, USA
		3269	2023 Armor Lite SHD-40/100 40 ft T/A End Dump Trailer S/N: 56EA75K26PA000422 C/W: Spring Suspension, 40 ft Body, 8 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:32 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
3269A	2019 Vantage 39 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 4E7AA3920KASA6006 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 39 ft Body, 58 in Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:32 PM CDT Asset located in: Lake Worth, TX, USA	3275	2022 Coras Predator 28 ft T/A End Dump Trailer S/N: 4C9C5D828NS071124 C/W: Located in Lane 66 Spot 12, Spring Suspension, 28 ft Body, 48 in Side Walls, Steel Body, High Lift Tailgate, 11R22.5 Tires, 56000 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:33 PM CDT Asset located in: Lake Worth, TX, USA
3270	2016 Vantage S-76-SS 37 ft T/A Aluminum Frameless End Dump Trailer S/N: 4E7AA3729GASA5429 C/W: Located in Lane 64 Spot 9, Air Ride Suspension, 37 ft Body, 42 in Side Walls, Aluminum Body, Manual Roll Tarp, Air Lift Tailgate, Box Liner, Aluminum Wheels, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:32 PM CDT Asset located in: Lake Worth, TX, USA	3276	2021 Coras Predator 28 ft T/A End Dump Trailer S/N: 4C9C5D822MS071103 C/W: Located in Lane 65 Spot 7, Spring Suspension, 28 ft Body, 48 in Side Walls, Steel Body, High Lift Tailgate, 11R22.5 Tires, 56000 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:33 PM CDT Asset located in: Lake Worth, TX, USA
3271	2019 Travis 35 ft T/A Aluminum Frameless End Dump Trailer S/N: 48XFF3525K1013702 C/W: Located in Lane 66 Spot 7, Air Ride Suspension, 35 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R24.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:32 PM CDT Asset located in: Lake Worth, TX, USA	3277	2013 Mate 30 ft T/A Aluminum End Dump Trailer S/N: 1M9A30325DH036795 C/W: Located in Lane 40 Spot 10, Air Ride Suspension, 30 ft Body, 54 in Side Walls, Manual Roll Tarp, 11R24.5 Tires, Equipment-from-R-Construction Usage: Not Available Notes: From the Well Maintained Fleet of R Construction Lot closing time: Thu, Sep 17, 03:33 PM CDT Asset located in: Humble, TX, USA
3272	2022 Coras Predator 28 ft T/A End Dump Trailer S/N: 4C9C5D829NS071049 C/W: Located in Lane 64 Spot 18, Spring Suspension, 28 ft Body, 48 in Side Walls, Steel Body, High Lift Tailgate, 11R22.5 Tires, 56000 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:32 PM CDT Asset located in: Lake Worth, TX, USA	3279	2007 Vantage S-90 28 ft T/A Aluminum End Dump Trailer S/N: 4E7AA28227ASA1392 C/W: Located in Lane 64 Spot 5, Aluminum /Steel Combination Frame, Air Ride Suspension, 28 ft Body, 60 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:34 PM CDT Asset located in: Lake Worth, TX, USA
3273	2022 Coras Predator 28 ft T/A End Dump Trailer S/N: 4C9C5D827NS071048 C/W: Located in Lane 66 Spot 10, Spring Suspension, 28 ft Body, 48 in Side Walls, Steel Body, High Lift Tailgate, 11R22.5 Tires, 56000 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:32 PM CDT Asset located in: Lake Worth, TX, USA	3280A	2008 Clement HL3750MK2-AIR 37 ft T/A Frameless End Dump Trailer S/N: 5C2BB37B18M006682 C/W: Located in Lane 64, Air Ride Suspension, 37 ft Body, 96 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R22.5 Tires, 70000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:34 PM CDT Asset located in: Lake Worth, TX, USA
3274	2022 Coras Predator 28 ft T/A End Dump Trailer S/N: 4C9C5D826NS071123 C/W: Located in Lane 64 Spot 15, Spring Suspension, 28 ft Body, 48 in Side Walls, Steel Body, High Lift Tailgate, 11R22.5 Tires, 56000 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:33 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3281	2016 Blacksmith 32 ft T/A Frameless End Dump Trailer S/N: 4B9B4D327GX103117 C/W: Located in Lane 66, Spring Suspension, 32 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:34 PM CDT Asset located in: Lake Worth, TX, USA	3289	2021 Trail King TKBD22-40-N 40 ft T/A Belly Dump Trailer S/N: 1TKD04021MW016021 C/W: Located in Lane 65 Spot 31, Air Ride Suspension, Clam Gate, Aluminum Wheels, 11R22.5 Tires, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:36 PM CDT Asset located in: Lake Worth, TX, USA
3282	1999 Travis 32 FT Travis HRS 32 ft T/A End Dump Trailer S/N: 1T97A3229X1247589 C/W: Located in Lane 88 Spot 14, Spring Suspension, 32 ft Body, 40 in Side Walls, Steel Body, Electric Roll Tarp, Air Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:35 PM CDT Asset located in: Lake Worth, TX, USA	3290	2021 Trail King TKBD22-40-N 40 ft T/A Belly Dump Trailer S/N: 1TKD0402XMW016020 C/W: Located in Lane 65 Spot 29, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:36 PM CDT Asset located in: Lake Worth, TX, USA
3284	2007 Vantage S-90 28 ft T/A Aluminum End Dump Trailer S/N: 4E7AA28267ASA1363 C/W: Located in Lane 64 Spot 13, Aluminum /Steel Combination Frame, Air Ride Suspension, 28 ft Body, 60 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 68000 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:35 PM CDT Asset located in: Lake Worth, TX, USA	3291	2021 Trail King TKBD22-40-N 40 ft T/A Belly Dump Trailer S/N: 1TKD04023MW016022 C/W: Located in Lane 65 Spot 30, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:37 PM CDT Asset located in: Lake Worth, TX, USA
3285	2026 EXA B24 42 ft T/A Belly Dump Trailer S/N: 3E9J140G0TT034095 C/W: Located in Lane 39 Spot 13, Spring Suspension, Clam Gate, Electric Roll Tarp, Push Block, 11R24.5 Tires, 79575 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:35 PM CDT Asset located in: Humble, TX, USA	3292	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40238G1029572 C/W: Located in Lane 64 Spot 19, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, 73760 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:37 PM CDT Asset located in: Lake Worth, TX, USA
3286	2026 EXA B-24 40 ft T/A Belly Dump Trailer S/N: 3E9J140G2TT034096 C/W: Located in Lane 54 Spot 0, Spring Suspension, Clam Gate, Electric Roll Tarp, Push Block, 11R24.5 Tires, 79575 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:35 PM CDT Asset located in: Humble, TX, USA	3293	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40232G1029566 C/W: Located in Lane 64 Spot 8, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, 73820 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:37 PM CDT Asset located in: Lake Worth, TX, USA
3288	2021 Trail King TKBD22-40-N 40 ft T/A Belly Dump Trailer S/N: 1TKD04023MW016019 C/W: Located in Lane 65 Spot 28, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:36 PM CDT Asset located in: Lake Worth, TX, USA	3294	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40230G1029565 C/W: Located in Lane 64 Spot 14, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, 73880 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:37 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3295	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40236G1029571 C/W: Located in Lane 64 Spot 12, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, 73640 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:38 PM CDT Asset located in: Lake Worth, TX, USA	3299	1998 Mickey ATNRB 16 Bay Refrigerated T/A Beverage Trailer S/N: 1M9RC1924WH043448 C/W: Located in Lane 64 Spot 21, Air Ride Suspension 39 ft Body, 52 in Bays, 42 in Deep, 82 in / 56 in Door Height, Carrier Supra 950 Refrigeration Unit, Aluminum Wheels, 295 /75R22.5 Tires, 57000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:39 PM CDT Asset located in: Lake Worth, TX, USA
3296A	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40238G1029569 C/W: Located in Lane 66 Spot 35, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, 73660 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:38 PM CDT Asset located in: Lake Worth, TX, USA	3300	1994 Hackney Beverage Trailer S/N: 1HHTRH329RM000368 C/W: Located in Lane 64 Spot 20, Spring Suspension 37 ft Body, 52 in / 52 in Bays, 42 in Deep, 56 in / 84 in Door Height, Carrier Refrigeration Unit, 275/70R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:39 PM CDT Asset located in: Lake Worth, TX, USA
3296B	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40234G1029570 C/W: Located in Lane 66 Spot 33, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:38 PM CDT Asset located in: Lake Worth, TX, USA	3301	1992 Hackney 16 Bay Refrigerated T/A Beverage Trailer S/N: 1HHTRH323NM000649 C/W: Located in Lane 64 Spot 19, Spring Suspension 37 ft Body, 52 in / 52 in Bays, 42 in Deep, 52 in / 82 in Door Height, Carrier Refrigeration Unit, 295/75R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:39 PM CDT Asset located in: Lake Worth, TX, USA
3296C	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40239G1029564 C/W: Located in Lane 66 Spot 34, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, 73860 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:38 PM CDT Asset located in: Lake Worth, TX, USA	3304	2019 Great Dane ECM-1113-31053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0629KE153742 C/W: Located in Lane 63 Spot 21, 2018 Thermo King Refrigeration Unit, Spring Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: 8,887 Hr Lot closing time: Thu, Sep 17, 03:40 PM CDT Asset located in: Lake Worth, TX, USA
3297	2016 Load King 2060-40-2-HD 40 ft T/A Belly Dump Trailer S/N: 5LKD40234G1029567 C/W: Located in Lane 65 Spot 32, Air Ride Suspension, Clam Gate, Push Block, Aluminum Wheels, 11R22.5 Tires, 73840 lb GVWR, Equipment-from-Whitaker-Aggregates Usage: Not Available Lot closing time: Thu, Sep 17, 03:38 PM CDT Asset located in: Lake Worth, TX, USA	3305	2018 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532BXJL046224 C/W: Located in Lane 89 Spot 2, 2017 Thermo King C-600 Refrigeration Unit, Air Ride Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:40 PM CDT Asset located in: Lake Worth, TX, USA
3298	2012 ITI 42 ft x 96 in T/A Open-Top Chip Trailer S/N: 1Z92E422XCT199072 C/W: Located in Lane 40 Spot 22, Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:38 PM CDT Asset located in: Humble, TX, USA	3306	2017 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2530HU615765 C/W: Carrier 7500X4 Refrigeration Unit, Air Ride Sliding Suspension, 295/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 03:40 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
3306A	2016 Utility VS2RA 53 ft x 102 in T/A Multi - Temp Refrigerated Trailer S/N: 1UYVS253XGM449401 C/W: Located in Lane 62 Spot 30, Thermo King Spectrum DE Refrigeration Unit, 30896 Total Hours, 3-Zone, Aluminum/Steel Combination Frame, Air Ride Sliding Suspension, Aluminum Floor, Swing Door, 445/50R22.5 Super Single Tires 65000 lb GVWR Usage: 30,896 Hr Lot closing time: Thu, Sep 17, 03:40 PM CDT Asset located in: Lake Worth, TX, USA	3311	2015 Great Dane ECM-1114-12140 40 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA8022FB708478 C/W: Located in Lane 62 Spot 10, 2014 Thermo King Refrigeration Unit, Air Ride Sliding Suspension, Ducted Floor, Roll-Up Door, Ramp, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:41 PM CDT Asset located in: Lake Worth, TX, USA
3307	2015 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2536FU226237 C/W: Located in Lane 62 Spot 9, 2014 Carrier X4 7300 Refrigeration Unit, 46216 Total Hours, Air Ride Sliding Suspension, Ducted Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: 38,877 Hr Lot closing time: Thu, Sep 17, 03:40 PM CDT Asset located in: Lake Worth, TX, USA	3312	2014 Great Dane FTL-1114-31053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625EE701577 C/W: Located in Lane 62 Spot 29, 2013 Carrier X4 7500 Refrigeration Unit, 40468 Total Hours, Air Ride Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: 35,181 Hr Lot closing time: Thu, Sep 17, 03:42 PM CDT Asset located in: Lake Worth, TX, USA
3308	2015 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2532FM050996 C/W: Located in Lane 54 Spot 36, 2015 Carrier X4 7500 Refrigeration Unit, Air Ride Sliding Suspension, Side Skirts, Aluminum Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:41 PM CDT Asset located in: Humble, TX, USA	3314	2014 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XEM931704 C/W: Located in Lane 62 Spot 31, 2013 Carrier X2 2500APX Refrigeration Unit, 46816 Total Hours, Air Ride Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: 25,838 Hr Lot closing time: Thu, Sep 17, 03:42 PM CDT Asset located in: Lake Worth, TX, USA
3309	2015 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2530FM277314 C/W: Located in Lane 19 Spot 23, 2014 Carrier Refrigeration Unit, Aluminum/Steel Combination Frame, Air Ride Suspension, Side Skirts, Aluminum Floor, Swing Door, 295 /75R22.5 Tires 65000 lb GVWR Usage: 45,885 Hr Lot closing time: Thu, Sep 17, 03:41 PM CDT Asset located in: Lake Worth, TX, USA	3315	2014 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2531EM931736 C/W: Located in Lane 62 Spot 22, 2013 Carrier X2 2500APX Refrigeration Unit, 42362 Total Hours, Air Ride Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: 22,957 Hr Lot closing time: Thu, Sep 17, 03:42 PM CDT Asset located in: Lake Worth, TX, USA
3310	2015 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537FM219538 C/W: Located in Lane 64 Spot 16, 2014 Carrier X4 7500 Refrigeration Unit, 50605 Total Hours, Air Ride Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: 32,430 Hr Lot closing time: Thu, Sep 17, 03:41 PM CDT Asset located in: Lake Worth, TX, USA	3315B	2014 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2531EM050647 C/W: Air Ride Sliding Suspension, Side Skirts, Aluminum Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: 28,157 Hr Lot closing time: Thu, Sep 17, 03:43 PM CDT Asset located in: Lake Worth, TX, USA
		3317	2009 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS25399U582220 C/W: Located in Lane 62 Spot 21, 2008 Thermo King Refrigeration Unit, Air Ride Sliding Suspension, Ducted Floor, Swing Door, 295 /75R22.5 Tires 65000 lb GVWR Usage: 25,625 Hr Lot closing time: Thu, Sep 17, 03:43 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3318	2000 Trailmobile 53 ft x 102 in T/A Refrigerated Trailer S/N: 1PT01ANH1Y9006415 C/W: Located in Lane 41 Spot 0, 1999 Carrier Phoenix Ultra Refrigeration Unit, Spring Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:43 PM CDT Asset located in: Humble, TX, USA	3325	2025 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VC5325ST506719 C/W: Located in Lane 62 Spot 10, Aluminum /Steel Combination Frame, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295 /75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:45 PM CDT Asset located in: Lake Worth, TX, USA
3321	2006 Utility VS2RA 48 ft x 102 in T/A Multi-Temp Refrigerated Trailer S/N: 1UYVS24816M858706 C/W: Located in Lane 63 Spot 11, Thermo King SB 30-2 Refrigeration Unit, Aluminum/Steel Combination Frame, Spring Sliding Suspension, Aluminum Floor, Swing Door, Ramp, Curbside Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:44 PM CDT Asset located in: Lake Worth, TX, USA	3326	2025 Hyundai VC2530152-AJS 53 ft x 102 in T/A Van Trailer S/N: 3H3V532K9SS135127 C/W: Located in Lane 63 Spot 18, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:45 PM CDT Asset located in: Lake Worth, TX, USA
3322	1996 Utility VS2R 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2488TM895943 C/W: Located in Lane 63 Spot 13, Carrier Refrigeration Unit, Aluminum/Steel Combination Frame, Air Ride Sliding Suspension, Ducted Floor, Roll-Up Door, Ramp, Curbside Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:44 PM CDT Asset located in: Lake Worth, TX, USA	3328	2025 Hyundai VC2530152-AJS 53 ft x 102 in T/A Van Trailer S/N: 3H3V532K4SS135231 C/W: Located in Lane 63 Spot 19, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:45 PM CDT Asset located in: Lake Worth, TX, USA
3323	1990 Great Dane 721TZ1B 36 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA9021LB031005 C/W: Located in Lane 62 Spot 20, 2014 Thermo King Refrigeration Unit, Spring Sliding Suspension, Ducted Floor, Roll-Up Door, 295 /75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:44 PM CDT Asset located in: Lake Worth, TX, USA	3329	2025 Hyundai VC2530152-AJS 53 ft x 102 in T/A Van Trailer S/N: 3H3V532K4SS135133 C/W: Located in Lane 63 Spot 19, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:46 PM CDT Asset located in: Lake Worth, TX, USA
3324	1992 Great Dane 28 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA5611NS070901 C/W: Located in Lane 66 Spot 00, Carrier NDA93NN1-CM-A2 Refrigeration Unit, Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Aluminum Floor, Roll-Up Door, 295/75R22.5 Tires 39000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:44 PM CDT Asset located in: Lake Worth, TX, USA	3330	2025 Hyundai VC2530152-AJS 53 ft x 102 in T/A Van Trailer S/N: 3H3V532K0SS135128 C/W: Located in Lane 63 Spot 23, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:46 PM CDT Asset located in: Lake Worth, TX, USA
		3331	2024 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5327RBB46454 C/W: Located in Lane 79 Spot 25, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:46 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3332	2024 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D6RL435813 C/W: Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: Temporary tags will not be issued Lot closing time: Thu, Sep 17, 03:46 PM CDT Asset located in: Oklahoma City, OK, USA	3338	2022 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELDTMS42N6000262 C/W: Located in Lane 41 Spot 0, Air Ride Sliding Suspension, Hardwood Floor, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:48 PM CDT Asset located in: Humble, TX, USA
3333	2023 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D7PL386523 C/W: Located in Lane 63 Spot 8, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:46 PM CDT Asset located in: Lake Worth, TX, USA	3340	2020 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2539L3974501 C/W: Located in Lane 62 Spot 13, Aluminum/Steel Combination Frame, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:48 PM CDT Asset located in: Lake Worth, TX, USA
3334	2023 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D8PL413793 C/W: Located in Lane 63 Spot 4, Aluminum/Steel Combination Frame, Spring Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:47 PM CDT Asset located in: Lake Worth, TX, USA	3341	2019 Hyundai VC2530152-AJS 53 ft x 102 in T/A Van Trailer S/N: 3H3V532C7KT453024 C/W: Located in Lane 42, Air Ride Sliding Suspension, Hardwood Floor, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:48 PM CDT Asset located in: Humble, TX, USA
3335	2022 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2539N3450090 C/W: Located in Lane 54 Spot 33, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:47 PM CDT Asset located in: Humble, TX, USA	3342	2019 Great Dane CCC-3314-01053 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0622KK166283 C/W: Located in Lane 41 Spot 3, Air Ride Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:49 PM CDT Asset located in: Humble, TX, USA
3336	2022 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX20NG001175 C/W: Located in Lane 74 Spot 0, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:47 PM CDT Asset located in: Humble, TX, USA	3344	2019 Great Dane CCC-3314-21053 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0621KJ101818 C/W: Located in Lane 42, Air Ride Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:49 PM CDT Asset located in: Humble, TX, USA
3337	2022 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX23NG001171 C/W: Located in Lane 74 Spot 0, Air Ride Suspension, Sliding Suspension, Side Skirts, Aluminum Wheels, 275/80R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:47 PM CDT Asset located in: Humble, TX, USA	3345	2017 Wabash DVCVHPC 53 ft T/A Van Trailer S/N: 1JJV532D1HL978453 C/W: Located in Lane 63 Spot 1, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:49 PM CDT Asset located in: Lake Worth, TX, USA
		3346	2017 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D7HL912697 C/W: Located in Lane 41 Spot 28, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:49 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3348	2016 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D8GL906955 C/W: Spring Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:50 PM CDT Asset located in: Livingston, LA, USA	3356	2015 Wabash DVCVHPC 53 ft x 102 in Sliding T/A Van Trailer S/N: 1JJV532D7FL833463 C/W: Located in Lane 41 Spot 0, Spring Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:52 PM CDT Asset located in: Humble, TX, USA
3349	2016 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D2GL907003 C/W: Aluminum/Steel Combination Frame, Spring Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:50 PM CDT Asset located in: Livingston, LA, USA	3357	2015 Hyundai V12530152JS 53 ft x 102 in T/A Van Trailer S/N: 3H3V532C2GT106093 C/W: Located in Lane 41 Spot 4, Spring Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:52 PM CDT Asset located in: Humble, TX, USA
3350	2016 Wabash DVCVHPC 53 ft T/A Van Trailer S/N: 1JJV532D7GL907031 C/W: Aluminum/Steel Combination Frame, Spring Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:50 PM CDT Asset located in: Livingston, LA, USA	3358	2014 Great Dane CCC331401053 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0628ET584975 C/W: Located in Lane 41, Air Ride Sliding Suspension, Hardwood Floor, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:52 PM CDT Asset located in: Humble, TX, USA
3352	2016 Great Dane CS1-1314-01053 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0623GK259029 C/W: Located in Lane 41 Spot 24, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:51 PM CDT Asset located in: Humble, TX, USA	3359	2014 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D5EL803232 C/W: Located in Lane 64 Spot 40, Aluminum/Steel Combination Frame, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:53 PM CDT Asset located in: Lake Worth, TX, USA
3353	2016 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2533GG434320 C/W: Located in Lane 88, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:51 PM CDT Asset located in: Lake Worth, TX, USA	3361	2010 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D9AL355748 C/W: Located in Lane 64 Spot 10, Spring Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:53 PM CDT Asset located in: Lake Worth, TX, USA
3355	2015 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2536FP129506 C/W: Located in Lane 42 Spot 1, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:52 PM CDT Asset located in: Humble, TX, USA	3364	1996 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5321TS023009 C/W: Located in Lane 42 Spot 3, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 11R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:54 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3366	2014 Great Dane CLA-1214-02048 48 ft x 102 in T/A Van Trailer S/N: 1GRAA962XEB709034 C/W: Located in Lane 41 Spot 0, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, Lift Gate, 11R22.5 Tires, 68000 lb GVWR, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 03:54 PM CDT Asset located in: Humble, TX, USA	3374	1998 Strick 48 ft x 102 in T/A Van Trailer S/N: 1S12E9485WE428618 C/W: Located in Lane 62 Spot 21, Spring Sliding Suspension, Hardwood Floor, Swing Door, Ramp, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:56 PM CDT Asset located in: Lake Worth, TX, USA
3369	2018 Great Dane FRPVAN 46 ft x 102 in T/A Van Trailer S/N: 1GRAA9224JB703729 C/W: Located in Lane 41, Air Ride Suspension, Ducted Floor, Lift Gate, Curbside Door, 11R22.5 Tires, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 03:55 PM CDT Asset located in: Humble, TX, USA	3375	1998 Strick 48 ft x 102 in T/A Van Trailer S/N: 1S12E9489WE428685 C/W: Located in Lane 62 Spot 8, Spring Sliding Suspension, Hardwood Floor, Swing Door, 295 /75R22.5 Tires 65000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:56 PM CDT Asset located in: Lake Worth, TX, USA
3370	2018 Great Dane CLF300402199 46 ft x 102 in T/A Van Trailer S/N: 1GRAA9224JB703746 C/W: Located in Lane 41 Spot 19, Air Ride Suspension, Hardwood Floor, Roll-Up Door, Lift Gate, Curbside Door, 11R22.5 Tires, 68000 lb GVWR, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 03:55 PM CDT Asset located in: Humble, TX, USA	3376	1989 Trailmobile 011J-1YAL 48 ft x 96 in T/A Van Trailer S/N: 1PT011JH2K9007635 C/W: Located in Lane 63 Spot 14, Aluminum /Steel Combination Frame, Spring Sliding Suspension, Aluminum Floor, Roll-Up Door, Ramp, Curbside Door, 295/75R22.5 Tires 6500 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:56 PM CDT Asset located in: Lake Worth, TX, USA
3371	2018 Great Dane CLF300402199 46 ft x 96 in T/A Van Trailer S/N: 1GRAA9222JB703745 C/W: Located in Lane 41, Air Ride Sliding Suspension, Hardwood Floor, Roll-Up Door, Lift Gate, Curbside Door, 11R22.5 Tires, 68000 lb GVWR, Professionally-Maintained-Fleet-Vehicle-PAG Usage: Not Available Notes: Seller supplied maintenance record attached in the document section below Lot closing time: Thu, Sep 17, 03:55 PM CDT Asset located in: Humble, TX, USA	3378	2011 Wilson DWH-550 T/A Grain Trailer S/N: 1W1MCF8B2BA258055 C/W: Located in Lane 65 Spot 3, Aluminum /Steel Combination Frame, Air Ride Suspension, 2 Hoppers, Manual Traps, 50 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 75000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:57 PM CDT Asset located in: Lake Worth, TX, USA
3372	2015 Great Dane CLA-1304-21048 48 ft x 96 in T/A Van Trailer S/N: 1GRAA9622FB700703 C/W: Located in Lane 64 Spot 35, Aluminum /Steel Combination Frame, Air Ride Sliding Suspension, Side Skirts, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires 68000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:56 PM CDT Asset located in: Lake Worth, TX, USA	3379	2018 J&M TB-6000 Trail-Blazer 45 ft Header Transport Trailer S/N: 1J9BB3038JF297004 C/W: Located in Lane 56 Spot 2 Usage: Not Available Notes: Can move 30-45 ft Any Manufacturer Header From the Fleet of Harvest Time Farms Lot closing time: Thu, Sep 17, 03:57 PM CDT Asset located in: Lake Worth, TX, USA
		3380	2016 Mauldin MT-600 T/A 600 gal Asphalt Distributor Trailer S/N: 4C9PT6025GG229326 C/W: 6 ft Bolt- On Spray Bar, Single Flue w/ Electric Heated, Pump w/ Honda Engine Usage: Not Available Notes: Texas buyers must stop in office to sign required documents to process title Lot closing time: Thu, Sep 17, 03:57 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
3381	2013 Sherman & Reilly T7212 Cable Puller and Tensioner S/N: 123WM3529D1T13088 C/W: Located in Lane 58 Spot 0, 4 Cylinder Diesel Engine Usage: 1,594 Hr Lot closing time: Thu, Sep 17, 03:58 PM CDT Asset located in: Humble, TX, USA	3389	2022 Magnolia Quad/A Coil Chassis S/N: 1M9MK3244N1435275 C/W: Located in Lane 41 Spot 9, Air Ride Suspension, 255/70R22.5 Tires, 100000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 04:00 PM CDT Asset located in: Humble, TX, USA
3383	1973 Miscellaneous COMMLCABLE S/A (1) Reel Trailer S/N: CRTR25732615TEX C/W: Located in Lane 44, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 10.00-20 Tires Usage: Not Available Notes: Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Lot closing time: Thu, Sep 17, 03:58 PM CDT Asset located in: Humble, TX, USA	3390	2020 PJ Trailers T/A 24 ft Water Treatment Trailer S/N: 4P5F82428L1322576 C/W: Ball Hitch, Spring Suspension, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 04:00 PM CDT Asset located in: Midland, TX, USA
3384	1971 Baker CABLE S/A (1) Reel Trailer S/N: 15525 C/W: Located in Lane 44, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 235/75R16 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:58 PM CDT Asset located in: Humble, TX, USA	3391	2020 PJ Trailers T/A 24 ft Water Treatment Trailer S/N: 4P5F82427L1316686 C/W: Ball Hitch, Spring Suspension, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 04:00 PM CDT Asset located in: Midland, TX, USA
3385	2009 General T/A Data Monitoring Trailer S/N: 1C9CK40249A681099 C/W: Located in Lane 43 Spot 36, Air Ride Suspension, 11R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:59 PM CDT Asset located in: Humble, TX, USA	3392	2006 Ameritrail Hydroblasting System S/N: 17YGN24206B033269 C/W: Located in Lane 43 Spot 44, 1 in Intake, 1 in Discharge, Triplex Water Pump, John Deere 6 Cylinder Diesel Engine, Electric Brakes Usage: Not Available Lot closing time: Thu, Sep 17, 04:00 PM CDT Asset located in: Humble, TX, USA
3386	2005 General T/A Data Monitoring Trailer S/N: 1C9CK40255A681073 C/W: Located in Lane 43 Spot 33, Air Ride Suspension, 11R22.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 03:59 PM CDT Asset located in: Humble, TX, USA	3393	2002 Team Fenex F121NP S/A Manhole Support Trailer S/N: 1T9US06142S056678 C/W: Located in Lane 55 Spot 1, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 205 /75R15 Tires, 2750 lb GVWR, Generator Usage: 1,624 Hr Notes: Texas buyers must stop in office to sign required documents to process title Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:00 PM CDT Asset located in: Lake Worth, TX, USA
3387	2010 Utility UT Tri/A Cooling Trailer S/N: 17YBP3030AB044807 C/W: Located in Lane 43 Spot 0, Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, 20000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:59 PM CDT Asset located in: Humble, TX, USA	3396	Yellow Dragon Flat Top S/A Frac Tank S/N: GP54633 C/W: Located in Lane 39 Spot 0, V-Bottom, 4 in Fill Line, 2 Hatches, Access Stairs, Air Brakes Usage: Not Available Lot closing time: Thu, Sep 17, 04:01 PM CDT Asset located in: Humble, TX, USA
3388	2022 Magnolia Coil Chassis Quad/A Coil Chassis S/N: 1M9MN4840N1435276 C/W: Located in Lane 42 Spot 43, Air Ride Suspension, Lift 1st- 4th- Axles, 255/70R22.5 Tires, 100000 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 03:59 PM CDT Asset located in: Humble, TX, USA	3397	Yellow Dragon Flat Top S/A Frac Tank S/N: 87799 C/W: Located in Lane 40 Spot 29, V-Bottom, 4 in Fill Line, 2 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available Lot closing time: Thu, Sep 17, 04:01 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3398	Red Wichita Flat Top S/A Frac Tank S/N: WTM090104 C/W: Located in Lane 39 Spot 0, V-Bottom, 4 in Fill Line, 2 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available Lot closing time: Thu, Sep 17, 04:02 PM CDT Asset located in: Humble, TX, USA	3404	2012 COMMAND Center ATCSS8516TA3 T/A Mobile Office S/N: 5JXME1629CE170601 C/W: Aluminum Frame, Ball Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 9990 lb GVWR Usage: Not Available Lot closing time: Thu, Sep 17, 04:03 PM CDT Asset located in: Midland, TX, USA
3399	(4) Container Locker Room & Shower Camp S/N: Not Available C/W: (2) 40 Ft Containers (Locker rooms), (2) 20 Ft Containers (Shower) Usage: Not Available Notes: ** Please see seller supplied specs /additional information attached in the documentation section below ** Lot closing time: Thu, Sep 17, 04:02 PM CDT Asset located in: Midland, TX, USA	3405	2013 COMMAND Center 16 ft x 8 ft 4 in T/A Mobile Office S/N: 5JXAE1627DE171945 C/W: Aluminum Frame, Ball Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 9990 lb GVWR Usage: 430 Hr Lot closing time: Thu, Sep 17, 04:03 PM CDT Asset located in: Midland, TX, USA
3400	2026 36 ft x 12 ft T/A Mobile Office (Unused) S/N: 748546 C/W: Located in Lane 62 Spot 0, (2) Offices, (1) Bathrooms, Air Conditioner, 240/60D14.5 Tires Usage: Not Available Lot closing time: Thu, Sep 17, 04:02 PM CDT Asset located in: Lake Worth, TX, USA	3406	20 ft x 8 ft Office Container (Unused) S/N: SKIU2474916 C/W: Located in Lane 73 Spot 0, Seller Comments: Heavy Duty Steel Door, Vinyl Frame W/ Low-E Glass Sliding Windows, R19 Wall Insulation, R30 Ceiling Insulation, Vinyl Or Laminate Plank Flooring, Gypsum Board Panels, Trim, Window Blinds, Paint, 9000 BTU Mini-Split AC, LED Ceiling Lights, Electrical Outlets, Exterior Light, Steel Bars On Windows, Puck Lock Usage: Not Available Lot closing time: Thu, Sep 17, 04:03 PM CDT Asset located in: Humble, TX, USA
3401	Ameri-Tech Portable Tri/A Mobile Office S/N: 11-100940 C/W: (2) Offices, (1) Bathrooms, Ball Hitch, Spring Suspension, 205/85D14.5 Tires Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Thu, Sep 17, 04:02 PM CDT Asset located in: Pecos, TX, USA	3407	20 ft x 8 ft Office Container (Unused) S/N: KDCU2251910 C/W: Located in Lane 73 Spot 0, Seller Comments: Heavy Duty Steel Door, Vinyl Frame W/ Low-E Glass Sliding Windows, R19 Wall Insulation, R30 Ceiling Insulation, Vinyl Or Laminate Plank Flooring, Gypsum Board Panels, Trim, Window Blinds, Paint, 9000 BTU Mini-Split AC, LED Ceiling Lights, Electrical Outlets, Exterior Light, Steel Bars On Windows, Puck Lock Usage: Not Available Lot closing time: Thu, Sep 17, 04:04 PM CDT Asset located in: Humble, TX, USA
3402	2013 COMMAND Center 16 ft x 8 ft 4 in T/A Mobile Office S/N: 5JXME1621DE170867 C/W: Aluminum Frame, Ball Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 9990 lb GVWR Usage: 6,473 Hr Lot closing time: Thu, Sep 17, 04:03 PM CDT Asset located in: Midland, TX, USA	3408	20 ft x 8 ft Office Container (Unused) S/N: KDCU2251843 C/W: Located in Lane 73 Spot 0, Seller Comments: Heavy Duty Steel Door, Vinyl Frame W/ Low-E Glass Sliding Windows, R19 Wall Insulation, R30 Ceiling Insulation, Vinyl Or Laminate Plank Flooring, Gypsum Board Panels, Trim, Window Blinds, Paint, 9000 BTU Mini-Split AC, LED Ceiling Lights, Electrical Outlets, Exterior Light, Steel Bars On Windows, Puck Lock Usage: Not Available Lot closing time: Thu, Sep 17, 04:04 PM CDT Asset located in: Humble, TX, USA
3403	2013 COMMAND Center 16 ft x 8 ft 4 in T/A Mobile Office S/N: 5JXAE1625DE171944 C/W: Aluminum Frame, Ball Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 9990 lb GVWR Usage: 4,985 Hr Lot closing time: Thu, Sep 17, 04:03 PM CDT Asset located in: Midland, TX, USA		

Lot #	Details	Lot #	Details
3409	2026 20 ft x 8 ft Office Container (Unused) S/N: TRDU6577592 C/W: Located in Lane 73 Spot 0, (1) Swing-Out Door, (2) Windows w/Security Bars, Fork Pockets, Laminate Flooring, SunScreen, R13 Insulation, (1) Pioneer HVAC Mini-Split, (1) Electric Panel, LED Ceiling Lights, Interior Outlets, Wiring done to National Electric Code (NEC) Usage: Not Available Lot closing time: Thu, Sep 17, 04:04 PM CDT Asset located in: Humble, TX, USA	3414	20 ft Standard Office Storage Container (Unused) S/N: CXIC8014443 C/W: Located in Lane 79 Spot 1, Seller Comments: Heavy Duty Steel Door, Vinyl Frame W/ Low-E Glass Sliding Windows, R19 Wall Insulation, R30 Ceiling Insulation, Vinyl Or Laminate Plank Flooring, Gypsum Board Panels, Trim, Window Blinds, Paint, 9000 BTU Mini-Split AC, LED Ceiling Lights, Electrical Outlets, Exterior Light, Steel Bars On Windows, Puck Lock Usage: Not Available Lot closing time: Thu, Sep 17, 04:05 PM CDT Asset located in: Lake Worth, TX, USA
3410	2026 20 ft x 8 ft Office Container (Unused) S/N: SKYU3823730 C/W: Located in Lane 73 Spot 0, (1) Swing-Out Door, (2) Windows w/Security Bars, Fork Pockets, Laminate Flooring, SunScreen, R13 Insulation, (1) Pioneer HVAC Mini-Split, (1) Electric Panel, LED Ceiling Lights, Interior Outlets, Wiring done to National Electric Code (NEC) Usage: Not Available Lot closing time: Thu, Sep 17, 04:04 PM CDT Asset located in: Humble, TX, USA	3415	20 ft Standard Office Storage Container (Unused) S/N: CXIC2295264 C/W: Located in Lane 79 Spot 1, Seller Comments: Heavy Duty Steel Door, Vinyl Frame W/ Low-E Glass Sliding Windows, R19 Wall Insulation, R30 Ceiling Insulation, Vinyl Or Laminate Plank Flooring, Gypsum Board Panels, Trim, Window Blinds, Paint, 9000 BTU Mini-Split AC, LED Ceiling Lights, Electrical Outlets, Exterior Light, Steel Bars On Windows, Puck Lock Usage: Not Available Lot closing time: Thu, Sep 17, 04:06 PM CDT Asset located in: Lake Worth, TX, USA
3411	2026 20 ft Standard Mobile Office Storage Container (Unused) S/N: NWRU3696237 C/W: Located in Lane 79 Spot 1, Man Door, Two Windows Usage: Not Available Lot closing time: Thu, Sep 17, 04:05 PM CDT Asset located in: Lake Worth, TX, USA	3416	19 ft 2 in x 7 ft 4 in Office Storage Container S/N: Not Available C/W: Located in Lane 73 Spot 0, Man door, 2 windows Usage: Not Available Lot closing time: Thu, Sep 17, 04:06 PM CDT Asset located in: Humble, TX, USA
3412	2025 20 ft Standard Mobile Office Storage Container (Unused) S/N: NWRU3811794 C/W: Located in Lane 79 Spot 1, Man Door, Two Windows Usage: Not Available Lot closing time: Thu, Sep 17, 04:05 PM CDT Asset located in: Lake Worth, TX, USA	3417	20 ft x 8 ft Skid-Mounted Camp (Unused) S/N: CIMU0393162 C/W: Located in Lane 73 Spot 0, Seller Comments: full bathroom, tile shower, custom cabinet with granite countertop, tankless water heater, toilet, Moen fixtures, PEX water lines, 9,000 BTU mini-split A/C, heavy-duty steel door with puck lock, vinyl Low-E windows, spray foam insulation (including floor), laminate flooring, sheetrock and texture, wood trim, window blinds, interior and exterior paint, LED recessed ceiling lights, LED exterior lighting and floodlights, steel security bars on windows, internet/cable port, 32" TV, and exterior hose bib. Usage: Not Available Lot closing time: Thu, Sep 17, 04:06 PM CDT Asset located in: Humble, TX, USA
3413	20 ft Standard Office Storage Container (Unused) S/N: QXIC3843449 C/W: Located in Lane 79 Spot 1, Seller Comments: Heavy Duty Steel Door, Vinyl Frame W/ Low-E Glass Sliding Windows, R19 Wall Insulation, R30 Ceiling Insulation, Vinyl Or Laminate Plank Flooring, Gypsum Board Panels, Trim, Window Blinds, Paint, 9000 BTU Mini-Split AC, LED Ceiling Lights, Electrical Outlets, Exterior Light, Steel Bars On Windows, Puck Lock Usage: Not Available Lot closing time: Thu, Sep 17, 04:05 PM CDT Asset located in: Lake Worth, TX, USA	3418	KJ K2019 20 ft x 19 ft Modular Home S/N: Not Available C/W: Located in Lane 79, (2) Bedrooms w/, (1) Bathrooms Usage: Not Available Lot closing time: Thu, Sep 17, 04:06 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3420	Cushman Hauler 4X4 Diesel Crew Utility Cart (Inoperable) S/N: TY8100050 C/W: Located in Lane 63, Canopy, 6 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2017 US EPA Label, Reading 3C100LF 3 Cylinder 16.4 kW 1.007 L Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:07 PM CDT Asset located in: Humble, TX, USA	3425A	2017 Ford Fiesta Automobile (Inoperable) S/N: 3FADP4CJ1HM139030 C/W: Located in Lane 45 Spot 0, 4 cyl 1.6 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 130,851 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:08 PM CDT Asset located in: Humble, TX, USA
3421	2019 John Deere Gator TX 4X2 4x2 Utility Vehicle (Inoperable) S/N: 1M04X2XDCKM141886 C/W: Located in Lane 63 Spot 0, Open Operator Station, 2 Passenger, Hitch Receiver, Manual Dump Bed, 2022 US EPA Label, Kawasaki 2 Cylinder Gasoline Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:07 PM CDT Asset located in: Humble, TX, USA	3426	2013 Dodge Charger Automobile (Inoperable) S/N: 2C3CDXBG6DH535036 C/W: Located in Lane 19 Spot 48, V6 3.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT ENGINE OVER HEATING - PLEASE SEE INSPECTION REPORT ; Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. This unit is being sold with a rebuilt salvage title. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Odometer reading not actual Lot closing time: Thu, Sep 17, 04:08 PM CDT Asset located in: Humble, TX, USA
3422	2024 Denago Nomad XL Electric Golf Cart (Inoperable) S/N: 7XBABAABXRA000813 C/W: Located in Lane 78 Spot 1, 4 Passenger, Canopy Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:07 PM CDT Asset located in: Lake Worth, TX, USA	3426A	2011 BMW 528i Automobile (Inoperable) S/N: WBAFR1C5XBC744538 C/W: Located in Lane 19 Spot 19, 6 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 138,125 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 04:08 PM CDT Asset located in: Humble, TX, USA
3423	E-Z-Go TXT 48 Electric Golf Cart (Inoperable) S/N: 2716360 C/W: Located in Lane 63 Spot 0, 48 Volt 2 Passenger, Canopy, Windshield Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:07 PM CDT Asset located in: Humble, TX, USA		
3424	2026 SKLP SK-E48 E-bikes Scooter (Inoperable) S/N: E84818 Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA		

Lot #	Details	Lot #	Details
3427	2007 Mercedes-Benz S550 Automobile (Inoperable) S/N: WDDNG71X27A138705 C/W: Located in Lane 45 Spot 0, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Tags will not be issued. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:08 PM CDT Asset located in: Humble, TX, USA	3429	2018 Ford Expedition Max 4WD Platinum SUV (Inoperable) S/N: 1FMJK1MT3JEA22857 C/W: Located in Lane 65 Spot 0, V6 3.5 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row, Towing Hitch Usage: 115,978 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal. This unit is being sold with a salvage title. Assets must be hauled off the yard and cannot be driven. Tags will not be issued. Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Humble, TX, USA
3428	2004 Volkswagen Phaeton AWD Automobile (Inoperable) S/N: WVWAF63D748009080 C/W: V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise registration will not be provided. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Lake Worth, TX, USA	3429A	2011 Ford Flex 2WD SUV (Inoperable) S/N: 2FMGK5BC7BBD06817 C/W: Located in Lane 19 Spot 17, V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch Usage: 268,632 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Tags will not be issued. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT-Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Humble, TX, USA
3428A	2018 Chevrolet Traverse Lt 2WD SUV (Inoperable) S/N: 1GNERGKW4JJ278666 C/W: Located in Lane 21 Spot 39, V6 3.6 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 143,728 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Humble, TX, USA	3429B	2012 Chevrolet Tahoe LS 2WD SUV (Inoperable) S/N: 1GNSCAE03CR187692 C/W: Located in Lane 100 Spot 1, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 214,706 Mi Notes: Inoperable items must be removed from yard by May 29th and cannot be relisted ; Buyer's responsibility for removal. RBA will not be able to assist with loading; Texas residents must sign required documents to process as "title only". Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3430	1998 Toyota Land Cruiser 4WD SUV (Inoperable) S/N: JT3HT05J9W0023222 C/W: V8 4.7 L Gasoline Engine, 1998 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Midland, TX, USA	3432	2018 Ram 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6UR5CJ9JG425309 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 6 ft 4 in Bed Usage: 154,713 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Tags will not be issued. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:10 PM CDT Asset located in: Livingston, LA, USA
3431	2003 Toyota 4 Runner SR5 4WD SUV (Inoperable) S/N: JTEBT14R030024569 C/W: Gasoline Engine, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Midland, TX, USA	3432A	2015 Ram 2500 Laramie 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6UR5FL7FG696485 C/W: Located in Lane 21 Spot 13, 6.7 L 6 Cylinder Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 10000 lb GVWR, 275 /65R20 Tires, 6 ft 6 in Bed Usage: 353,704 Mi Notes: *Modified Emissions - This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control systems or devices as originally equipped. Buyer of this unit must sign acknowledgement form of this notice prior to removal; Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:10 PM CDT Asset located in: Humble, TX, USA
3431A	1999 Ford F-350 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTSX30F7XED43332 C/W: Located in Lane 45 Spot 0, Diesel Engine, Automatic Transmission, Air Conditioner, 9900 lb GVWR, 285/75R16 Tires, 8 ft Bed Usage: 269,883 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Humble, TX, USA		
3431B	2021 Ford F-250 4x2 Crew Cab Pickup (Inoperable) S/N: 1FT7W2A63MED50632 C/W: Located in Lane 100 Spot 1, 6.2 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 2 in Bed Usage: Not Available Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading; Job Completion Fleet Realignment for Heavy Highway Joint Venture. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:09 PM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3432B	2018 Ford F-250 XL 4x2 Crew Cab Pickup (Inoperable) S/N: 1FT7W2A60JEB42090 C/W: Located in Lane 19 Spot 34, 6.2 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/75R17 Tires, 7 ft 0 in Bed Usage: 160,745 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading; Texas residents must sign required documents to process as "title only"; Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Additional Components Available In Office - Key Lot closing time: Thu, Sep 17, 04:10 PM CDT Asset located in: Lake Worth, TX, USA	3435	2015 Chevrolet Silverado 2500 HD 4x2 Dual Cab Pickup (Inoperable) S/N: 1GC2CUE80FZ104689 C/W: Located in Lane 21 Spot 0, 6.6 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275 /65R20 Tires, 8 ft Bed Usage: 405,184 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:10 PM CDT Asset located in: Humble, TX, USA
3433	2015 Ford F-250 XL 4x2 Crew Cab Pickup (Inoperable) S/N: 1FT7W2AT8FEC44878 C/W: Located in Lane 47 Spot 0, 6.7 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: Not Available Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Inoperable items must be removed from yard by September 4th and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:10 PM CDT Asset located in: Humble, TX, USA	3436	2008 Ford F-250 King Ranch 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTSW21R28EA11533 C/W: Located in Lane 45 Spot 0, 6.4 L V8 Diesel Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Spray-On Bed Liner, 275/65R20 Tires, 8 ft Bed Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal Tags will not be issued. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Lot closing time: Thu, Sep 17, 04:10 PM CDT Asset located in: Humble, TX, USA
3434	2017 Chevrolet Silverado 2500HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KUEG0HF143115 C/W: 6 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Spray-On Bed Liner, 9500 lb GVWR, 285/75R17 Tires, 6 ft 5 in Bed Usage: 237,791 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Texas residents must sign required documents to process as "title only". Lot closing time: Thu, Sep 17, 04:10 PM CDT Asset located in: Livingston, LA, USA	3437	2015 Ford F-250 Lariat 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2BT5FEC10296 C/W: Located in Lane 45 Spot 0, 6.7 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 275/65R20 Tires, 8 ft Bed Usage: 268,952 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Tags will not be issued. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:11 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3437A	2015 Ford F-250 XL 4x2 Crew Cab Pickup (Inoperable) S/N: 1FT7W2AT8FEA80953 C/W: Located in Lane 44 Spot 0, 6.7 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 201,524 Mi Notes: Inoperable items must be removed from yard by October 30th and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading; Odometer discrepancy-unit shows 201,524, title shows 95,277. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:11 PM CDT Asset located in: Humble, TX, USA	3439	2009 Chevrolet Silverado 2500HD 4x2 Extended Cab Pickup (Inoperable) S/N: 1GCHC49K49E122219 C/W: Located in Lane 45 Spot 0, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 9200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:11 PM CDT Asset located in: Humble, TX, USA
3437B	2019 Ford F-250 XL 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2B67KEC61996 C/W: Located in Lane 45 Spot 0, 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:11 PM CDT Asset located in: Humble, TX, USA	3440	2021 Ram 1500 Big Horn 4x4 Crew Cab Pickup (Inoperable) S/N: 1C6SRFFM9MN748631 C/W: Located in Lane 100 Spot 10, 3.0 L Diesel Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 7200 lb GVWR, 285/60R20 Tires, 5 ft 7 in Bed Usage: 185,223 Mi Notes: Inoperable items must be removed from yard by September 4th and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Texas residents must sign required documents to process as "title only". Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:11 PM CDT Asset located in: Lake Worth, TX, USA
3438	2003 Ford F-250 XL 4x2 Pickup (Inoperable) S/N: 1FTNF20L53EA74015 C/W: Located in Lane 45 Spot 0, 5.4 L 5 Cylinder Gasoline Engine, 2003 US EPA Label, Automatic Transmission, Air Conditioner, R K Tool Box, Drop-In Bed Liner, 8800 lb GVWR, 235 /85R16 Tires, 8 ft Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Tags will not be issued. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:11 PM CDT Asset located in: Humble, TX, USA	3441	2021 Ford F-150 STX 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTEW1EPXMKD90311 C/W: Located in Lane 46 Spot 0, Automatic Transmission, Air Conditioner, Power Windows, 275/65R20 Tires, 5 ft 6 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Assets must be hauled off the yard and cannot be driven. Tags will not be issued. Lot closing time: Thu, Sep 17, 04:12 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3442	2014 Ford F-150 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTFW1ET7EKF11038 C/W: 3.5 L 6 Cylinder Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Aluminum Truck Cap, 7350 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 113,887 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:12 PM CDT Asset located in: Livingston, LA, USA	3444	2020 Chevrolet Silverado 1500 4x2 Crew Cab Pickup (Inoperable) S/N: 3GCPWAEF7LG151806 C/W: Located in Lane 100 Spot 1, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, Drop-In Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 5 ft 10 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading; Texas residents must sign required documents to process as "title only". Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:12 PM CDT Asset located in: Lake Worth, TX, USA
3442A	2018 Ram 1500 4x2 Crew Cab Pickup (Inoperable) S/N: 1C6RR6KT1JS290706 C/W: Located in Lane 23 Spot 31, 5.7 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 183,457 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:12 PM CDT Asset located in: Humble, TX, USA	3446	2009 GMC Sierra 1500 SLE 4x2 Crew Cab Pickup (Inoperable) S/N: 3GTEC23079G161667 C/W: Located in Lane 45 Spot 0, 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Adjustable Pedals, Power Windows, Drop-In Bed Liner, 6800 lb GVWR, 265/65R17 Tires, 5 ft 8 in Bed Usage: 181,575 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Tags will not be issued. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. This unit is being sold with a bonded title. Buyers in the state of LA -bonded titles will not be accepted in your state. This unit is being sold with a rebuilt salvage title. Lot closing time: Thu, Sep 17, 04:13 PM CDT Asset located in: Humble, TX, USA
3443	2010 Chevrolet Silverado 1500 4x2 Pickup (Inoperable) S/N: 1GCPCEA9AZ225787 C/W: Located in Lane 45 Spot 0, V8 Gasoline Engine, Automatic Transmission, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:12 PM CDT Asset located in: Humble, TX, USA	3448	2012 Toyota Tundra 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 5TFUW5F13CX225926 C/W: V8 5.7 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 4000 lb Front Axle, 4150 lb Rears, 7100 lb GVWR, 275/70R18, Spring Suspension, 143 in Wheelbase, 7 ft x 85 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:13 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
3450	2010 Toyota Tundra 4x4 Extended Cab Pickup (Inoperable) S/N: 5TFUM5F1XAX006979 C/W: V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 6900 lb GVWR, 275/70R18 Tires, 6 ft 5 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:14 PM CDT Asset located in: Midland, TX, USA	3453	2006 Ford F-150 King Ranch 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTPW14596KC85383 C/W: Located in Lane 45 Spot 0, 5.4 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 275/55R18 Tires, 5 ft 6 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Texas residents must sign required documents to process as "title only", Lot closing time: Thu, Sep 17, 04:14 PM CDT Asset located in: Humble, TX, USA
3451	2010 Toyota Tundra 4x4 Crew Cab Pickup (Inoperable) S/N: 5TFCW5F11AX009856 C/W: V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 7200 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:14 PM CDT Asset located in: Midland, TX, USA	3454	2007 Nissan Titan 4x2 Extended Cab Pickup (Inoperable) S/N: 1N6AA06A47N226263 C/W: Located in Lane 23 Spot 1, 5.6 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6244 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 169,692 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:15 PM CDT Asset located in: Humble, TX, USA
3452	2016 Chevrolet Silverado 1500 4x2 Crew Cab Pickup (Inoperable) S/N: 3GCPCREC4GG205954 C/W: Located in Lane 45 Spot 0, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 275/55R20 Tires, 6 ft Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Texas buyers must stop in the office to sign the required documents to process their title if they win the lot. Vehicle history report is available in the document section. Please review before bidding. Lot closing time: Thu, Sep 17, 04:14 PM CDT Asset located in: Humble, TX, USA	3455A	2019 Kenworth T880 6x4 Mixer Truck (Inoperable) S/N: 1NKZXPEX3KJ252550 C/W: Located in Lane 64 Spot 0, Paccar MX-13 6 Cylinder Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison 4700RDS Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-164PEH Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 248 in Wheelbase, PTO, McNeilus 11 cyd Mixer Unit, 0 Removable Chutes Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:15 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3457	2007 International 5600i 6x4 Mixer Truck (Inoperable) S/N: 1HTXHAHT67J411390 C/W: Cummins ISM 350V 6 Cylinder Diesel 350 hp Engine, Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, 222 in Wheelbase, McNeilus Mixer Unit Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:15 PM CDT Asset located in: Livingston, LA, USA	3459	2002 Kenworth W900 10x4 Gunitite Truck (Inoperable) S/N: 1NKWXTEx12J890131 C/W: Located in Lane 100 Spot 1, Cat C10 10.3 L Diesel Engine, 2002 US EPA Label, Manual Transmission, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 252 in Wheelbase, PTO Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:16 PM CDT Asset located in: Lake Worth, TX, USA
3458	2016 Mack GU813 6x4 Mixer Truck (Inoperable) S/N: 1M2AX13C7GM031238 C/W: Located in Lane 66 Spot 0, Mack MP7 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 22800 lb Front Axle, 46000 lb Rears, 66800 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Spring Suspension, 220 in Wheelbase, Putzmeister Mixer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; *Modified Emissions-Auctioneers Announcement This unit has deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply If you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. Lot closing time: Thu, Sep 17, 04:16 PM CDT Asset located in: Humble, TX, USA	3460	1997 Kenworth W900 10x4 Gunitite Truck (Inoperable) S/N: 1NKWXUEx0VR752379 C/W: Located in Lane 100 Spot 1, Cat C12 11.9 L Diesel Engine, 1997 US EPA Label, 37479 Engine hrs, Manual Transmission, 20000 lb Front Axle, 54000 lb Rears, 5.38:1 Axle Ratio, 80000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 253 in Wheelbase, PTO Usage: 438,327 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:16 PM CDT Asset located in: Lake Worth, TX, USA
3458A	1999 Sterling LT9511 8x4 Mixer Truck (Inoperable) S/N: 2FZNNMCB2XAB08023 C/W: Located in Lane 64 Spot 0, 6 Cylinder Diesel Engine, Eaton Fuller 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Hendrickson HN Series Rubber Suspension, 252 in Wheelbase, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:16 PM CDT Asset located in: Humble, TX, USA	3461	2004 Mack CV713 8x4 Gunitite Truck (Inoperable) S/N: 1M2AG11C54M010824 C/W: Located in Lane 100 Spot 12, Mack AMI-370 6 Cylinder 728 cid Diesel 370 hp Engine, 2003 US EPA Label, Mack 8-Speed Manual Transmission, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Tag Axle, Camelback Spring Suspension, 319 in Wheelbase Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:16 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3462	Wilkie Ladder on 2007 International 4400 4x2 Ladder Truck (Inoperable) S/N: 1HTMMAAM67H361812 C/W: Located in Lane 64 Spot 0, 6 Cylinder Diesel Engine, Manual Transmission, 10R22.5, Spring Suspension, 253 in Wheelbase Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:17 PM CDT Asset located in: Humble, TX, USA	3466	2001 Peterbilt 357 6x4 Flatbed Truck (Inoperable) S/N: 1NPAL09X51D566833 C/W: Located in Lane 64 Spot 0, Cummins ISM 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, Air Ride Cab, Aluminum Rear Outside, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 278 in Wheelbase, 22 ft x 96 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:17 PM CDT Asset located in: Humble, TX, USA
3463	Wilkie Ladder on 2018 Ford F-750 4x2 Ladder Truck (Inoperable) S/N: 1FDXF7DC9JDF01839 C/W: Located in Lane 84 Spot 0, 6.7 L Diesel Engine, 2018 US EPA Label, Automatic Transmission, 13200 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 243 in Wheelbase Usage: 219,969 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:17 PM CDT Asset located in: Humble, TX, USA	3466A	2024 Ram 5500 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 3C7WRNFXRG255247 C/W: Cummins 6 Cylinder 6.7 L Diesel 360 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft 5 in x 93 in Bed, Receiver, Fifth wheel ball Usage: 126,530 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:18 PM CDT Asset located in: Lake Worth, TX, USA
3465	2004 Kenworth T300 6x4 T/A Dump Truck S/N: 2NKMHD7X14M056055 C/W: Located in Lane 44 Spot 23, Cat C7 6 Cylinder Engine, 18811 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 6.14:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Double Frame, Hendrickson Rubber over Walking Beam Suspension, 176 in Wheelbase, PTO, Ledwell 13 ft Long x 3 ft High Steel Body, Electric Roll Tarp Usage: 269,786 Mi Lot closing time: Thu, Sep 17, 04:17 PM CDT Asset located in: Lake Worth, TX, USA	3467	2014 Ram 4500 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 3C7WRLEL4EG167407 C/W: Located in Lane 66 Spot 0, Cummins 6 Cylinder 6.7 L Diesel Engine, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 175 in Wheelbase, 10 ft 3 in x 98 in Bed, Winch, Water Tank Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:18 PM CDT Asset located in: Humble, TX, USA
3465A	1996 International 4700 4x2 S/A Dump Truck S/N: 1HTSCAAM2TH263414 C/W: Located in Lane 45 Spot 0, PTO, Manual Roll Tarp, Split Swing Tailgate Usage: 310,998 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:17 PM CDT Asset located in: Humble, TX, USA	3468	2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3H66KED71449 C/W: Located in Lane 47 Spot 0, V8 6.2 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft x 98 in Bed Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:18 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3469	2018 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT5JEB85440 C/W: Located in Lane 47 Spot 0, V8 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 180 in Wheelbase, 9 ft 4 in x 98 in Bed Usage: 95,934 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal Lot closing time: Thu, Sep 17, 04:18 PM CDT Asset located in: Humble, TX, USA	3471A	2007 Chevrolet Silverado 2500HD 4x4 Extended Cab Flatbed Truck S/N: 1GCHK29K87E572993 C/W: Located in Lane 11 Spot 9, GM V8 6.0 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, 4200 lb Front Axle, 6084 lb Rears, 9200 lb GVWR, Steel, 265 /75R16, Spring Suspension, 144 in Wheelbase, 7 ft x 80 in Bed Usage: 154,503 Mi Notes: Texas residents must sign required documents to process as "title only", unless otherwise advised in office & extra charge is paid. Otherwise Vehicle registration will not be provided. Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:19 PM CDT Asset located in: Lake Worth, TX, USA
3470	2015 Chevrolet Silverado 3500HD 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1GB4CYC82FF531672 C/W: 6.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 5200 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 172 in Wheelbase, 9 ft 6 in x 91.5 in Bed Usage: 206,054 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:18 PM CDT Asset located in: Livingston, LA, USA	3472	1998 Ford F800 4x2 Flatbed Truck (Inoperable) S/N: 1FDNF80CXWVA14069 C/W: Located in Lane 64 Spot 0, Cummins B5.9 6 Cylinder 5.9 L Diesel 175 hp Engine, 5-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5 Front Tires, 10R22.5 Rear Tires, Spring Suspension, 237 in Wheelbase, 13 ft 9 in x 96 in Bed Usage: 478,852 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:19 PM CDT Asset located in: Humble, TX, USA
3471	2011 Chevrolet Silverado 2500HD 4x4 Extended Cab Flatbed Truck (Inoperable) S/N: 1GC2KVC85BZ100109 C/W: Located in Lane 100 Spot 1, GM V8 6.6 L Diesel Engine, Automatic Transmission, 5600 lb Front Axle, 6200 lb Rears, 10000 lb GVWR, 245/70R19.5, Spring Suspension, 160 in Wheelbase, 8 ft 5 in x 77 in Bed Usage: 317,641 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted ; Buyer's responsibility for removal. RBA will not be able to assist with loading; Texas residents must sign required documents to process as "title only" Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:19 PM CDT Asset located in: Lake Worth, TX, USA	3474	2001 Mack CH612 6x4 Roll-Off Truck (Inoperable) S/N: 1M1AA08Y01W022042 C/W: Located in Lane 64 Spot 0, Mack E7 Diesel 300 hp Engine, 2000 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Aluminum Front Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Camelback Spring Suspension, 240 in Wheelbase, 2007 Galbreath U750R174 Roll-Off Body, Outside Rail, 23 ft Hoist Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:19 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3476	2011 International 4300 2000 gal 4x2 Water Truck (Inoperable) S/N: 1HTMMAAN0BH388506 C/W: 6 Cylinder Diesel Engine, 110 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 22700 lb Rears, 32700 lb GVWR, 275/80R22.5, 204 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 159,105 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:20 PM CDT Asset located in: Lake Worth, TX, USA	3479B	2020 Chevrolet Silverado 3500HD 4x2 Crew Cab Utility Truck (Inoperable) S/N: 1GB5YSE75LF248069 C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 10500 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 164 in Wheelbase, Knapheide 696D54 8 ft Body, Gasoline Air Compressor, Air Hose Reel Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:21 PM CDT Asset located in: Midland, TX, USA
3476A	2006 International 4300 2000 gal 4x2 Water Truck (Inoperable) S/N: 1HTMMAAMX6H343490 C/W: Located in Lane 66 Spot 0, International 6 Cylinder Diesel Engine, Automatic Transmission, 11R22.5, Spring Suspension, 148 in Wheelbase, PTO, Lands 2000 gal Steel Tank, PTO Driven Pump, 5 ft 8 in, Spray Bar, Rear Spray, Dribble Bar, Side Spray Usage: 220,794 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:20 PM CDT Asset located in: Humble, TX, USA	3480	2008 Chevrolet C4500 4x2 Service Truck (Inoperable) S/N: 1GBE4C1908F414949 C/W: Located in Lane 100 Spot 1, GM Duramax V8 6.6 L Diesel 330 hp Engine, 2007 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225 /70R19.5, Spring Suspension, 154 in Wheelbase, Knapheide 6132D5460J 11 ft 0 in Body, Liftmoore 10000 lb 3 Section Electric Crane, Miller Big 40 Diesel Generator Set Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Texas residents must sign required documents to process as "title only". Vehicle history report available in the documents section Lot closing time: Thu, Sep 17, 04:21 PM CDT Asset located in: Lake Worth, TX, USA
3477	2007 Ford F-750 XL 2000 gal 4x2 Water Truck (Inoperable) S/N: 3FRXF75E97V509423 C/W: Located in Lane 66 Spot 0, Cummins 6 Cylinder Diesel Engine, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Rear Spray Usage: 40,380 Hr Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal Lot closing time: Thu, Sep 17, 04:20 PM CDT Asset located in: Humble, TX, USA	3480A	2016 Ford F-450 XL 4x2 Crew Cab Utility Truck (Inoperable) S/N: 1FD0W4GT5GEA21098 C/W: Located in Lane 45 Spot 0, Ford Powerstroke V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 202 in Wheelbase, 2016 BATTERSON 12 ft Body Usage: 184,013 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:21 PM CDT Asset located in: Humble, TX, USA
3479A	2017 Ford F-550 4x4 Extended Cab Service Truck (Inoperable) S/N: 1FD0X5HY3HEE21952 C/W: Ford Motor Company 6.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 13 ft 4 in Body, Palfinger PSC 6025 6000 lb 3 Section Crane, Gasoline Air Compressor, Air Hose Reel Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:21 PM CDT Asset located in: Midland, TX, USA		

Lot #	Details	Lot #	Details
3482	2013 Dodge Ram 4500 4x4 Crew Cab Utility Truck (Inoperable) S/N: 3C7WRLEL6DG586289 C/W: Located in Lane 100 Spot 1, Cummins 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 5794 Engine hrs, 6-Speed Manual Transmission, 225/70R19.5, Spring Suspension, 174 in Wheelbase, RKI 9 ft Body, North Star 25654REV Air Compressor Usage: 114,727 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Odometer discrepancy Odometer shows 114727 Title shows 175000 Lot closing time: Thu, Sep 17, 04:21 PM CDT Asset located in: Lake Worth, TX, USA	3485	2009 Peterbilt 389 8x4 Tri/A Sleeper Truck Tractor (Inoperable) S/N: 1XPXD4EX99D779824 C/W: Located in Lane 100 Spot 1, 14060 lb Front Axle, 66000 lb Rears, 74600 lb GVWR, 68 in Mid Roof Sleeper Cab, 298 in Wheelbase, Air Suspension, Air Lift Pusher Axle, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Lake Worth, TX, USA
3483	2013 Chevrolet 3500 Utility Truck (Inoperable) S/N: 1GB3CZC8XDF105985 C/W: Located in Lane 100 Spot 1, GM 6.6 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 265/70R17, Spring Suspension, Knapheide 9 ft Body, Ingersoll-Rand SS3 Gasoline Air Compressor Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:21 PM CDT Asset located in: Lake Worth, TX, USA	3486	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPBD40X6PD861878 C/W: Located in Lane 68 Spot 0, Cummins X15 470 hp Engine, 2022 US EPA Label, Eaton Fuller 13-Speed Manual Transmission, 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Engine Brake, Double Differential Locks, 200 in Wheelbase, Air Suspension, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 131,448 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Humble, TX, USA
3484	2019 Western Star 4700 8x4 Cab and Chassis (Inoperable) S/N: 5KKMAVDV7KPKC9295 C/W: Located in Lane 64 Spot 0, Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 13297 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 59500 lb Rears, Air Ride Cab, 11R24.5, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 252 in Wheelbase, 143 in Cab to Axle, 255 in Cab to End of Frame Usage: 92,801 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Humble, TX, USA	3486A	2011 Peterbilt 384 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPVDU9X3BD127854 C/W: Located in Lane 68 Spot 0, Cat C13 Engine, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 181 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Assist Front Suspension Usage: 671,605 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3486B	2020 Mack Anthem AN64T 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1M1AN2GYXLM017687 C/W: Located in Lane 31 Spot 16, 14205 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 152 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Dual Fuel Tanks Usage: 480,902 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Humble, TX, USA	3487C	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGED63GDGZ1016 C/W: Located in Lane 67 Spot 0, Detroit DD15 455 hp Engine, 2015 US EPA Label, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 186 in Wheelbase, Air Suspension, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 947,705 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Humble, TX, USA
3487	2019 Freightliner Cascadia 116 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJHTDVXKSKP3630 C/W: Located in Lane 100 Spot 1, Detroit DD15 450 hp Engine, Detroit DT12-1550-OH1 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Engine Brake, 177 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Selling with a repossession affidavit and may not be accepted in your state. Verify with your local DMV prior to bidding. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Lake Worth, TX, USA	3488	2013 Freightliner M2 112 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJC5DV8DDBW1057 C/W: Located in Lane 100 Spot 1, Detroit DD13 450 hp Engine, 2012 US EPA Label, Allison 4000 Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 180 in Wheelbase, Air Suspension, 295 /75R22.5, Air Sliding 5th Wheel Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Lake Worth, TX, USA
3487A	2013 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9EG6DN131269 C/W: Volvo D13H375 375 hp Engine, 2012 US EPA Label, Volvo ATO2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, 172 in Wheelbase, Air Suspension, 295/75R22.5, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Lake Worth, TX, USA	3488A	2014 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9EG6EN166542 C/W: Volvo Engine, Volvo AT2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Engine Brake, 170 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Dual Fuel Tanks, Headache Rack Usage: Not Available Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Lake Worth, TX, USA
3487B	2013 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9EG3DN131195 C/W: Volvo D13H375 375 hp Engine, 2012 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, 172 in Wheelbase, Air Suspension, 295/75R22.5, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 04:22 PM CDT Asset located in: Lake Worth, TX, USA	3488B	2013 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9EG0DN131235 C/W: Volvo D13H 375 hp Engine, 2012 US EPA Label, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Engine Brake, 172 in Wheelbase, Air Suspension, 11R22.5, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3488C	2009 International ProStar Premium 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 2HSCUAPR29C108712 C/W: Located in Lane 65 Spot 0, Cummins ISX 450 hp Engine, 2008 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 187 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Humble, TX, USA	3493	2011 Peterbilt 389 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPXD49X2BD124713 C/W: Cummins ISX15 485 hp Engine, 2010 US EPA Label, 31528 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 63 in Mid Roof Sleeper Cab, 284 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 503,802 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:24 PM CDT Asset located in: Livingston, LA, USA
3489	2017 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9EH4HN994179 C/W: Located in Lane 65 Spot 0, Volvo D13M 425 hp Engine, 2017 US EPA Label, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 170 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Humble, TX, USA	3494	2011 Peterbilt 367 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPTD49X6BD117049 C/W: 2010 US EPA Label, Cummins ISX15 6 Cylinder 485 hp 15 L Diesel Engine Usage: 54,795 Mi Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees; Lot closing time: Thu, Sep 17, 04:24 PM CDT Asset located in: Pecos, TX, USA
3490A	2001 Sterling LT9500 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 2FWJAZAS71AJ92867 C/W: Located in Lane 100 Spot 1, 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Walking Beam Suspension, 11R24.5 Usage: 360,324 Mi Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Lake Worth, TX, USA	3494A	2015 Peterbilt 365 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPSD79X1FD263748 C/W: Located in Lane 100 Spot 1, Cummins ISX12 425 hp Engine, 2014 US EPA Label, Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Mid Roof Sleeper Cab, 226 in Wheelbase, Air Suspension, 295/75R22.5, Dual Fuel Tanks, Headache Rack Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:24 PM CDT Asset located in: Lake Worth, TX, USA
3491	2017 International ProStar 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDJSNR6HN465216 C/W: Located in Lane 68 Spot 0, Navistar N13 450 hp Engine, 2015 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Heater, Auxiliary Power Unit, 222 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:23 PM CDT Asset located in: Humble, TX, USA	3494C	2014 Kenworth T660 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKAD48X0EJ405797 C/W: Cummins ISX15 450 hp Engine, 17072 Engine hrs, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Engine Brake, 62 in Mid Roof Sleeper Cab, 238 in Wheelbase, Air Suspension, Aluminum Front Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 518,892 Km Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:24 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
3498A	2020 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDZTZRLN132536 C/W: Located in Lane 67 Spot 0, 2020 US EPA Label, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, VCM Sleeper Air Conditioner, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 379,987 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:25 PM CDT Asset located in: Humble, TX, USA	3502A	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR1JSKA6298 C/W: Located in Lane 100 Spot 1, Detroit DD15 455 hp Engine, 2017 US EPA Label, Detroit DT12-OA-1750 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 705,061 Mi Notes: Additional Components Available in Office - CPC. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:26 PM CDT Asset located in: Lake Worth, TX, USA
3499	2019 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGHDV0KDKC4663 C/W: Located in Lane 65 Spot 0, Detroit DD13 450 hp Engine, Eaton Fuller FAO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 48 in Mid Roof Sleeper Cab, 213 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 295/75R22.5, Air Assist Front Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 675,052 Mi Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:25 PM CDT Asset located in: Humble, TX, USA	3503	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLD58GSHD0217 C/W: Located in Lane 67 Spot 0, Detroit DD15 455 hp Engine, 2016 US EPA Label, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 224 in Wheelbase, Air Suspension, Aluminum Wheels, 285/75R24.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:26 PM CDT Asset located in: Humble, TX, USA
3500A	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPBDP9X9HD441540 C/W: Located in Lane 64 Spot 0, Paccar MX-13 485 hp Engine, 2016 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 72 in Mid Roof Sleeper Cab, Bunk Heater, 240 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:26 PM CDT Asset located in: Humble, TX, USA	3504	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD50GLGU1922 C/W: Located in Lane 35 Spot 7, Detroit DD15 455 hp Engine, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Dual Fuel Tanks Usage: 1,018,820 Mi Notes: *Modified Emissions-Auctioneers Announcement This unit runs but may have deficiencies in its pollution control systems with liabilities outlined in Texas administrative code sections 114.20 and 114.50. This may apply if you operate the unit prior to the adequate restoration of all pollution control system or devise as originally equipped. Buyer of this unit must sign and acknowledge form of this notice prior to removal of the unit from yard. ; Additional Components in Office - CPC Lot closing time: Thu, Sep 17, 04:26 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3508	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLD54GSHF9651 C/W: Located in Lane 67 Spot 0, Detroit DD15 455 hp Engine, 2016 US EPA Label, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 228 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:27 PM CDT Asset located in: Humble, TX, USA	3512	2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 4V4NC9EH1FN934152 C/W: Volvo D13J 455 hp Engine, 2014 US EPA Label, Volvo ATO2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 61 in Mid Roof Sleeper Cab, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:28 PM CDT Asset located in: Midland, TX, USA
3509	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1FUJGLD51FLGD7727 C/W: Located in Lane 100 Spot 8, Detroit DD15 455 hp Engine, Detroit DT12-DA-1750 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; No Key Available ; Additional Components Available in Office - CPC Lot closing time: Thu, Sep 17, 04:28 PM CDT Asset located in: Lake Worth, TX, USA	3512A	2000 Mack CH612 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1M1AA08X2YW021069 C/W: Located in Lane 66 Spot 0, Mack E7 300 hp Engine, 17835 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 158 in Wheelbase, Air Suspension, 295/75R22.5, Dual Fuel Tanks Usage: 540,740 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:28 PM CDT Asset located in: Humble, TX, USA
3510	2016 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGHVDV7GSGS5802 C/W: Located in Lane 64 Spot 0, Detroit DD13 450 hp Engine, 2016 US EPA Label, Detroit DT12-OB-1650 12-Speed Automated Transmission, 53220 lb GVWR, Retarder, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 216 in Wheelbase, Air Suspension, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,090,353 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:28 PM CDT Asset located in: Humble, TX, USA	3513	2017 Peterbilt 579 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XPBA48XXHD428952 C/W: Located in Lane 65 Spot 0, Cummins ISX15 400 hp Engine, 2016 US EPA Label, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Engine Brake, 161 in Wheelbase, Air Suspension, 295/75R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:28 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3517	2015 GVS on 2016 Peterbilt 348 6x4 Vacuum Tanker Truck (Inoperable) S/N: 2NP3LJ0X8GM322494 C/W: Located in Lane 64 Spot 0, Paccar PX-9 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 23200 Engine hrs, Engine Brake, Eaton Fuller FRO11210C 10-Speed Manual Transmission, Differential Lock, 20000 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 3.90:1 Axle Ratio, 60000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 224 in Wheelbase, PTO, Steel 3000 gal Debris Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Fruitland PTO Driven Pump Usage: 47,791 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:29 PM CDT Asset located in: Humble, TX, USA	3519	Presvac on 2006 Freightliner M2 106 6x4 Vacuum Tanker Truck (Inoperable) S/N: 1FVHCYDC46DV86835 C/W: Located in Lane 64 Spot 0, Cat C7 Diesel 300 hp Engine, Eaton Fuller 10-Speed Manual Transmission, 16000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.90:1 Axle Ratio, 56000 lb GVWR, Air Ride Cab, 315 /80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, TufTrac Spring Suspension, 209 in Wheelbase, PTO, Steel Debris Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:30 PM CDT Asset located in: Humble, TX, USA
3517A	GVS on 2013 Peterbilt 348 6x4 Vacuum Tanker Truck (Inoperable) S/N: 2NP3LN9X5DM182586 C/W: Located in Lane 64 Spot 0, Paccar PX-8 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FR9210B 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 3.55:1 Axle Ratio, 54600 lb GVWR, Aluminum Front Wheels, 12R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Air Trac Air Ride Suspension, 224 in Wheelbase, PTO, Hydraulic Oil Cooler, Steel Debris Tank, Full Open Tailgate Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:29 PM CDT Asset located in: Humble, TX, USA	3520	2013 Global 178ET on 2006 Freightliner Columbia 120 6x4 Vacuum Tanker Truck S/N: 1FUJA6CK76LV98766 C/W: Located in Lane 67 Spot 0, Detroit Series 60 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 242 in Wheelbase, PTO, Steel 3000 gal Debris Tank, TC412 Code, Hoist, Full Open Tailgate, Fruitland PTO Driven Pump Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:30 PM CDT Asset located in: Humble, TX, USA
3518	2006 Kenworth T800 6x4 Vacuum Tanker Truck (Inoperable) S/N: 1XKDD09X96R135766 C/W: Located in Lane 64 Spot 0, Cummins ISM 6 Cylinder Diesel Engine, 10-Speed Manual Transmission, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 217 in Wheelbase, PTO, Steel Debris Tank, Hoist, Hydraulic Lift Tailgate, Manual Tailgate Locks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Thu, Sep 17, 04:30 PM CDT Asset located in: Humble, TX, USA	3521	1992 Cusco on 1999 Volvo WG64 6x4 Vacuum Tanker Truck (Inoperable) S/N: 4VHJCBJF9XN863471 C/W: Located in Lane 67 Spot 0, Cummins N14 6 Cylinder Diesel 350 hp Engine, Eaton Fuller RTX14709H 9-Speed Manual Transmission, 18000 lb Front Axle, 44000 lb Rears, Meritor MT-44-14X Drive Axles, 4.63:1 Axle Ratio, 62000 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring over Walking Beam Suspension, 230 in Wheelbase, PTO, Steel 3150 gal Debris Tank, Hoist, Hydraulic Lift Tailgate, Manual Tailgate Locks, Fruitland PTO Driven Pump Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:30 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3522	2011 International 4300 4x2 Refrigerated Truck (Inoperable) S/N: 1HTJTSKLXBH358955 C/W: Located in Lane 66 Spot 0, International 6 Cylinder Diesel Engine, 5803 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Carrier Reefer Unit, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 158,112 Mi Notes: This unit is being sold with a bonded title. Buyers in the state of LA -bonded titles will not be accepted in your state. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:31 PM CDT Asset located in: Humble, TX, USA	3523B	2020 International MV607 4x2 Van Truck (Inoperable) S/N: 3HAEUMML7LL548585 C/W: Located in Lane 64 Spot 0, Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7538 Engine hrs, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 295/75R22.5, Spring Suspension, 272 in Wheelbase, Supreme Corporation 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 404,479 Mi Notes: Buyers in the states of AZ, FL, NE, NY, PA, LA & UT- Title is being sold with repossession affidavit and will not be accepted in your state. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:31 PM CDT Asset located in: Humble, TX, USA
3523	2017 Kenworth T270 4x2 Van Truck S/N: 2NKHMM6X7HM137778 C/W: Located in Lane 13 Spot 14, Paccar PX-7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11352.5 Engine hrs, Engine Brake, Allison 2100 6-Speed Automatic Transmission, 10000 lb Front Axle, 16000 lb Rears, Dana P20060S Drive Axles, 4.88:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Paccar Air Ride Suspension, 262 in Wheelbase, Morgan 24 ft x 102 in Wide x 109 in High Body, Liftgate Usage: 392,489 Mi Notes: No Key Available Lot closing time: Thu, Sep 17, 04:31 PM CDT Asset located in: Lake Worth, TX, USA	3524	2018 International 4300 4x2 Van Truck (Inoperable) S/N: 1HTMMMML6JH468726 C/W: Located in Lane 100 Spot 1, Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 274 in Wheelbase, Morgan 26 ft x 102 in Wide x 109 in High Body, Liftgate Usage: Not Available Notes: This unit is being sold with a rebuilt salvage title. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:31 PM CDT Asset located in: Lake Worth, TX, USA
3523A	2021 International MV607 4x2 Van Truck (Inoperable) S/N: 3HAEUMML3ML053964 C/W: Located in Lane 12 Spot 6, Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 8620 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Mickey 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 472,190 Km Lot closing time: Thu, Sep 17, 04:31 PM CDT Asset located in: Lake Worth, TX, USA	3527A	2017 Ford F-650 4x2 Van Truck (Inoperable) S/N: 1FDNF6AY5HDB01126 C/W: Located in Lane 64 Spot 0, Ford Motor Company V10 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 268 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:32 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
3527B	2013 Ford F-650 XLT 4x2 Van Truck (Inoperable) S/N: 3FRWF6FK7DV781376 C/W: Located in Lane 64 Spot 0, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 261 in Wheelbase, 26 ft x 96 in Wide x 96 in High Body, Liftgate Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:32 PM CDT Asset located in: Humble, TX, USA	3531	2013 Isuzu NPR HD 4x2 Van Truck (Inoperable) S/N: 54DC4W1C7DS803102 C/W: Located in Lane 82 Spot 3, GM V8 6.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, 225/70R19.5, Spring Suspension, 174 in Wheelbase, SUPREME 20 ft x 96 in Wide x 91 in High Body, Curbside Door, Liftgate Usage: 269,201 Mi Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Tags will not be issued. This unit is being sold with a bonded title. Buyers in the state of LA -bonded titles will not be accepted in your state. Has not actual mileage Lot closing time: Thu, Sep 17, 04:33 PM CDT Asset located in: Humble, TX, USA
3528	2016 Chevrolet Express 3500 4x2 Van Truck (Inoperable) S/N: 1GB3GSCG0G1144623 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 225/75R16, Spring Suspension, 150 in Wheelbase, Morgan 15 ft x 96 in Wide x 79 in High Body Usage: 153,655 Mi Notes: Temporary tags will not be issued. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading ; No Key Available Lot closing time: Thu, Sep 17, 04:32 PM CDT Asset located in: Oklahoma City, OK, USA	3533	2009 Peterbilt 367 8x4 Coil Tubing Unit Cab and Chassis (Inoperable) S/N: 1XPTD4EX29D777699 C/W: 20000 lb Front Axle, 69000 lb Rears, 80000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Ride Suspension, 270 in Wheelbase Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. or will be subject to 3rd party storage fees ; Lot closing time: Thu, Sep 17, 04:33 PM CDT Asset located in: Pecos, TX, USA
3529	2019 GMC G3500 4x2 Van Truck (Inoperable) S/N: 7GZ37TCG1KN003114 C/W: Located in Lane 67 Spot 0, V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Supreme 16 ft x 96 in Wide x 78 in High Body, Walk-Up Ramp Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:32 PM CDT Asset located in: Humble, TX, USA	3534	2016 Kenworth T440 4x2 Cab and Chassis (Inoperable) S/N: 3BKBH28X6GF125455 C/W: Located in Lane 100 Spot 1, Cummins ISL G 6 Cylinder 8.9 L Compressed Natural Gas (CNG) 300 hp Engine, Allison 3500 Automatic Transmission, 14600 lb Front Axle, 23000 lb Rears, 37600 lb GVWR, Aluminum Wheels, 315 /80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Air Ride Suspension, 239 in Wheelbase, 170 in Cab to Axle, 214 in Cab to End of Frame Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:33 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3535	2013 Kenworth T800 8x4 Cab and Chassis (Inoperable) S/N: 1NKDXP0X5DJ364108 C/W: Located in Lane 64 Spot 0, Paccar MX 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller FRO14210C 10-Speed Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, Dana DSP41 Drive Axles, 3.36:1 Axle Ratio, 66000 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 245 in Wheelbase, PTO, 177 in Cab to Axle, 288 in Cab to End of Frame Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:34 PM CDT Asset located in: Humble, TX, USA	3542	2004 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer (Inoperable) S/N: 1GRAA06284J602676 C/W: Located in Lane 62 Spot 22, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:35 PM CDT Asset located in: Lake Worth, TX, USA
3537	1996 Norsafe 19 ft Rescue Boat (Inoperable) S/N: 13608 C/W: Located in Lane 57 Spot 0, 6 Passenger Usage: Not Available Notes: ASSET SOLD BILL OF SALE ONLY / RBA WILL ASSIST LOADING THIS LOT Lot closing time: Thu, Sep 17, 04:34 PM CDT Asset located in: Humble, TX, USA	3544	1999 Great Dane 7411TJWNA 53 ft x 102 in T /A Van Trailer (Inoperable) S/N: 1GRAA0620XB190803 C/W: Located in Lane 88 Spot 13, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: Inoperable items must be removed from yard by September 4th and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:36 PM CDT Asset located in: Lake Worth, TX, USA
3541A	2014 Great Dane ECM-1114-12140 40 ft x 102 in T/A Multi -Temp Refrigerated Trailer (Inoperable) S/N: 1GRAA8029EB703700 C/W: Located in Lane 63 Spot 11, 2013 Thermo King Spectrum DE Refrigeration Unit, Aluminum/Steel Combination Frame, Air Ride Sliding Suspension, Ducted Floor, Roll-Up Door, Ramp, Curbside Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:35 PM CDT Asset located in: Lake Worth, TX, USA	3545	1990 Falcon 35 ft S/A Equipment Trailer (Inoperable) S/N: 432133518L1001627 C/W: Located in Lane 66 Spot 26, Spring Suspension, Electric Brakes, 11 ft Upper Deck, 12 ft Main Deck, 12 ft Rear Deck, 92 in Deck Width, Deck Over Tires, Wood Flooring, 235 /85R16 Tires, 12000 lb GVWR Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Thu, Sep 17, 04:36 PM CDT Asset located in: Lake Worth, TX, USA
3541B	2016 Utility VS2RAP 53 ft x 102 in T/A Refrigerated Trailer (Inoperable) S/N: 1UYVS253XGM411229 C/W: Carrier 7500 X4 Refrigeration Unit, Air Ride Suspension, Side Skirts, Aluminum Floor, Swing Door, 295/75R22.5 Tires 29500 lb GVWR Usage: Not Available Notes: License plates will not be provided. Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Thu, Sep 17, 04:35 PM CDT Asset located in: San Antonio, TX, USA	3546	Hydra Rig Tri/A Coiled Tubing Unit Trailer (Inoperable) S/N: Not Available C/W: Frame & Parts Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Thu, Sep 17, 04:36 PM CDT Asset located in: Pecos, TX, USA
		3562	2026 GIYI EDM320 39 in Excavator Disc Mulcher - Fits Cat 320 (Unused) S/N: 320YPTHJ260828 Usage: Not Available Lot closing time: Fri, Sep 18, 08:02 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3563	Handy HFB52 52 in Skid Steer Feller Buncher (Unused) S/N: FB202509186 Usage: Not Available Lot closing time: Fri, Sep 18, 08:02 AM CDT Asset located in: Lake Worth, TX, USA	3575	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:04 AM CDT Asset located in: Lake Worth, TX, USA
3564	2026 Wolverine ABC125 46 in Articulating Skid Steer Brush Cutter (Unused) S/N: ZW00003 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:02 AM CDT Asset located in: Lake Worth, TX, USA	3576	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:04 AM CDT Asset located in: Lake Worth, TX, USA
3565	2026 Wolverine ABC125 46 in Articulating Skid Steer Brush Cutter (Unused) S/N: ZW00001 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:02 AM CDT Asset located in: Lake Worth, TX, USA	3577	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:04 AM CDT Asset located in: Lake Worth, TX, USA
3567	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:03 AM CDT Asset located in: Lake Worth, TX, USA	3582	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: ZW02243 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:05 AM CDT Asset located in: Lake Worth, TX, USA
3568	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:03 AM CDT Asset located in: Lake Worth, TX, USA	3583	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: ZW02240 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:05 AM CDT Asset located in: Lake Worth, TX, USA
3569	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:03 AM CDT Asset located in: Lake Worth, TX, USA	3584	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: ZW02242 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:05 AM CDT Asset located in: Lake Worth, TX, USA
3570	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:03 AM CDT Asset located in: Lake Worth, TX, USA	3585	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: ZW02238 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:05 AM CDT Asset located in: Lake Worth, TX, USA
3571	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:03 AM CDT Asset located in: Lake Worth, TX, USA	3586	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: ZW02244 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:05 AM CDT Asset located in: Lake Worth, TX, USA
3574	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:04 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3587	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062803D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:06 AM CDT Asset located in: Lake Worth, TX, USA	3594	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062503B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:07 AM CDT Asset located in: Lake Worth, TX, USA
3588	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062802D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:06 AM CDT Asset located in: Lake Worth, TX, USA	3595	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062505B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:07 AM CDT Asset located in: Lake Worth, TX, USA
3589	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062805D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:06 AM CDT Asset located in: Lake Worth, TX, USA	3596	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062501B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:07 AM CDT Asset located in: Lake Worth, TX, USA
3590	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062804D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:06 AM CDT Asset located in: Lake Worth, TX, USA	3597	2026 Mower King SSEFGC175 77 in Skid Steer Mower (Unused) S/N: SSEFGC17526062802D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:07 AM CDT Asset located in: Lake Worth, TX, USA
3591	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062801D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:06 AM CDT Asset located in: Lake Worth, TX, USA	3598	2026 Mower King SSEFGC175 77 in Skid Steer Mower (Unused) S/N: SSEFGC17526062801D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:07 AM CDT Asset located in: Lake Worth, TX, USA
3592	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062502B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:06 AM CDT Asset located in: Lake Worth, TX, USA	3599	2026 Mower King SSEFGC175 77 in Skid Steer Mower (Unused) S/N: SSEFGC17526062502B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:07 AM CDT Asset located in: Lake Worth, TX, USA
3593	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26062504B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:06 AM CDT Asset located in: Lake Worth, TX, USA	3600	2026 Mower King SSEFGC175 77 in Skid Steer Mower (Unused) S/N: SSEFGC17526062501B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:07 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3600A	72 in Skid Steer Sweeper S/N: Not Available C/W: Located in Lane 71 Usage: Not Available Lot closing time: Fri, Sep 18, 08:08 AM CDT Asset located in: Lake Worth, TX, USA	3612	Agrotk SPA84 84 in Skid Steer Dozer S/N: Not Available C/W: Located in Lane 76 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 08:09 AM CDT Asset located in: Lake Worth, TX, USA
3605A	Cat BA18 84 in Skid Steer Broom S/N: AZN00724 Usage: Not Available Lot closing time: Fri, Sep 18, 08:08 AM CDT Asset located in: Lake Worth, TX, USA	3613	2026 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: ZW00018 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:09 AM CDT Asset located in: Lake Worth, TX, USA
3606	2026 Wolverine PAB-11-72W 72 in Skid Steer Broom (Unused) S/N: ZW02890 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:08 AM CDT Asset located in: Lake Worth, TX, USA	3614	2025 Wig XN-QC01-08 14 in Skid Steer Stump Grinder S/N: XN00164 Usage: Not Available Lot closing time: Fri, Sep 18, 08:10 AM CDT Asset located in: Lake Worth, TX, USA
3607	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:09 AM CDT Asset located in: Lake Worth, TX, USA	3615	2026 Mower King ECSSCT72 60 in Skid Steer Trencher (Unused) S/N: ECSSCT7226062801D C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:10 AM CDT Asset located in: Lake Worth, TX, USA
3608	2026 Wolverine RS72 Manual Angled Skid Steer Broom (Unused) S/N: ZW00021 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:09 AM CDT Asset located in: Lake Worth, TX, USA	3617	2026 LYALS ALSST 60 in Skid Steer Trencher (Unused) S/N: ALS3566 C/W: 6 in Dirt & Rock Chain, Crumbling Shoe Usage: Not Available Lot closing time: Fri, Sep 18, 08:10 AM CDT Asset located in: Lake Worth, TX, USA
3609	2026 Wolverine RS72 Manual Angled Skid Steer Broom (Unused) S/N: ZW00022 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:09 AM CDT Asset located in: Lake Worth, TX, USA	3618	2026 Mower King ECSSCT72 60 in Skid Steer Trencher (Unused) S/N: ECSSCT7226062501B C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:10 AM CDT Asset located in: Lake Worth, TX, USA
3610	2026 Wolverine DB-15-84W 84 in Angle Skid Steer Dozer (Unused) S/N: ZW00244 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:09 AM CDT Asset located in: Lake Worth, TX, USA	3623	2026 TOFT STG74 74 in Skid Steer Landplane (Unused) S/N: STG260430 Usage: Not Available Lot closing time: Fri, Sep 18, 08:11 AM CDT Asset located in: Lake Worth, TX, USA
3611	Bobcat 80 in PAT Skid Steer Dozer S/N: 232111414 Usage: Not Available Lot closing time: Fri, Sep 18, 08:09 AM CDT Asset located in: Lake Worth, TX, USA	3624	2026 TOFT STG74 74 in Skid Steer Landplane (Unused) S/N: STG260402 Usage: Not Available Lot closing time: Fri, Sep 18, 08:11 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3625	2026 TOFT STG74 74 in Skid Steer Landplane (Unused) S/N: STG260434 Usage: Not Available Lot closing time: Fri, Sep 18, 08:11 AM CDT Asset located in: Lake Worth, TX, USA	3653	2026 AGT SSHH680 Skid Steer Breaker (Unused) S/N: Not Available C/W: Located in Lane 71, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:15 AM CDT Asset located in: Lake Worth, TX, USA
3626	2026 TOFT STG74 74 in Skid Steer Landplane (Unused) S/N: STG260427 Usage: Not Available Lot closing time: Fri, Sep 18, 08:11 AM CDT Asset located in: Lake Worth, TX, USA	3654	2026 AGT SSHH680 Skid Steer Breaker (Unused) S/N: SSHH68026062801D C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA
3639	2026 TOFT ST-72 72 in Skid Steer Landscape Rake (Unused) S/N: STR260497 Usage: Not Available Lot closing time: Fri, Sep 18, 08:13 AM CDT Asset located in: Lake Worth, TX, USA	3655	AGT SSHH680 Skid Steer Breaker S/N: Not Available C/W: Located in Lane 76 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA
3640	2026 TOFT ST-72 72 in Skid Steer Landscape Rake (Unused) S/N: STR260470 Usage: Not Available Lot closing time: Fri, Sep 18, 08:13 AM CDT Asset located in: Lake Worth, TX, USA	3656	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA
3641	2025 Kit Containers QT-RR-70 70 in Skid Steer Landscape Rake (Unused) S/N: D28G1301 Usage: Not Available Lot closing time: Fri, Sep 18, 08:14 AM CDT Asset located in: Lake Worth, TX, USA	3657	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA
3642	2026 TOFT TOFT750 Skid Steer Breaker (Unused) S/N: TOFTJW43Z7429 Usage: Not Available Lot closing time: Fri, Sep 18, 08:14 AM CDT Asset located in: Lake Worth, TX, USA	3657A	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: Located in Lane 70 Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA
3649	2026 LYALS ALS680 Skid Steer Breaker (Unused) S/N: ALS3655 Usage: Not Available Lot closing time: Fri, Sep 18, 08:15 AM CDT Asset located in: Lake Worth, TX, USA	3658	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226062803D C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA
3650	2026 LYALS ALS680 Skid Steer Breaker (Unused) S/N: ALS3654 Usage: Not Available Lot closing time: Fri, Sep 18, 08:15 AM CDT Asset located in: Lake Worth, TX, USA	3659	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226062801D C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA
3652	2026 TOFT TOFT680 Skid Steer Breaker (Unused) S/N: TOFTJW40Z19324 Usage: Not Available Lot closing time: Fri, Sep 18, 08:15 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3660	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226062802D C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:16 AM CDT Asset located in: Lake Worth, TX, USA	3673A	LYALS ALSSB Skid Steer Backhoe (Unused) S/N: ALYS2444 C/W: Located in Lane 70, 14 in Digging Bucket Usage: Not Available Lot closing time: Fri, Sep 18, 08:18 AM CDT Asset located in: Lake Worth, TX, USA
3661	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226062501B C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:17 AM CDT Asset located in: Lake Worth, TX, USA	3674	2026 GIYI GY-ZWB Mini Skid Steer Backhoe (Unused) S/N: XZWB260706 C/W: Located in Lane 70, 13 in Digging Bucket Usage: Not Available Lot closing time: Fri, Sep 18, 08:19 AM CDT Asset located in: Lake Worth, TX, USA
3662	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226062502B C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:17 AM CDT Asset located in: Lake Worth, TX, USA	3675	Mini Skid Steer Backhoe S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:19 AM CDT Asset located in: Lake Worth, TX, USA
3666	Landy 72 in Skid Steer Tiller S/N: Not Available C/W: Located in Lane 76 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 08:17 AM CDT Asset located in: Lake Worth, TX, USA	3681	All-Star 80 in Skid Steer Landplane S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:20 AM CDT Asset located in: Lake Worth, TX, USA
3667	2026 Top Cat ECSSSTG200 Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: Located in Lane 70, 3/4 in x 24 in Cutting Wheel ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:18 AM CDT Asset located in: Lake Worth, TX, USA	3682	2026 X-STAR 72 in Skid Steer Landplane S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:20 AM CDT Asset located in: Lake Worth, TX, USA
3671	2026 GIYI GY-SZYMJ Mini Skid Steer Stump Grinder (Unused) S/N: SZYMJ260738 C/W: Located in Lane 70 Usage: Not Available Lot closing time: Fri, Sep 18, 08:18 AM CDT Asset located in: Lake Worth, TX, USA	3683	2026 X-STAR 72 in Skid Steer Landplane (Unused) S/N: Not Available C/W: 3 Point Hitch Usage: Not Available Lot closing time: Fri, Sep 18, 08:20 AM CDT Asset located in: Lake Worth, TX, USA
3672	2026 GIYI GY-SZYMJ Mini Skid Steer Stump Grinder (Unused) S/N: SZYMJ260737 C/W: Located in Lane 70 Usage: Not Available Lot closing time: Fri, Sep 18, 08:18 AM CDT Asset located in: Lake Worth, TX, USA	3684	2026 X-STAR 72 in Skid Steer Landplane (Unused) S/N: Not Available C/W: 3 Point Hitch Usage: Not Available Lot closing time: Fri, Sep 18, 08:20 AM CDT Asset located in: Lake Worth, TX, USA
		3685	X-STAR 72 in Skid Steer Landplane S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:20 AM CDT Asset located in: Lake Worth, TX, USA
		3686	2025 Kit Containers QT-72-LP 72 in Skid Steer Landplane (Unused) S/N: D26F1702 Usage: Not Available Lot closing time: Fri, Sep 18, 08:20 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3687	2025 Kit Containers QT-72-LP 72 in Skid Steer Landplane (Unused) S/N: D18F1709 Usage: Not Available Lot closing time: Fri, Sep 18, 08:21 AM CDT Asset located in: Lake Worth, TX, USA	3703	2026 TOFT ST-72 72 in Skid Steer Root Rake (Unused) S/N: STR260462 Usage: Not Available Lot closing time: Fri, Sep 18, 08:23 AM CDT Asset located in: Lake Worth, TX, USA
3694	All-Star 84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:22 AM CDT Asset located in: Lake Worth, TX, USA	3710	All-Star 80 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:24 AM CDT Asset located in: Lake Worth, TX, USA
3695	All-Star 84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:22 AM CDT Asset located in: Lake Worth, TX, USA	3711	All-Star 78 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:24 AM CDT Asset located in: Lake Worth, TX, USA
3696	All-Star 78 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:22 AM CDT Asset located in: Lake Worth, TX, USA	3712	All-Star 78 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:24 AM CDT Asset located in: Lake Worth, TX, USA
3697	All-Star 74 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:22 AM CDT Asset located in: Lake Worth, TX, USA	3713	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:24 AM CDT Asset located in: Lake Worth, TX, USA
3698	All-Star 72 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:22 AM CDT Asset located in: Lake Worth, TX, USA	3714	All-Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:25 AM CDT Asset located in: Lake Worth, TX, USA
3699	All-Star 68 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:22 AM CDT Asset located in: Lake Worth, TX, USA	3715	All-Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:25 AM CDT Asset located in: Lake Worth, TX, USA
3700	Mid-State 68 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:22 AM CDT Asset located in: Lake Worth, TX, USA	3717	All-Star 68 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:25 AM CDT Asset located in: Lake Worth, TX, USA
3701	Mid-State 60 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:23 AM CDT Asset located in: Lake Worth, TX, USA	3718	Mid-State 60 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:25 AM CDT Asset located in: Lake Worth, TX, USA
3702	All-Star 48 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:23 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3719	Mid-State 68 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:25 AM CDT Asset located in: Lake Worth, TX, USA	3728	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: D07G1600 Usage: Not Available Lot closing time: Fri, Sep 18, 08:27 AM CDT Asset located in: Lake Worth, TX, USA
3720	All-Star 48 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:25 AM CDT Asset located in: Lake Worth, TX, USA	3729	All-Star 72 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:27 AM CDT Asset located in: Lake Worth, TX, USA
3721	All-Star 80 in Rock w/Teeth Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:26 AM CDT Asset located in: Lake Worth, TX, USA	3730	All-Star 72 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:27 AM CDT Asset located in: Lake Worth, TX, USA
3722	All-Star 72 in Rock w/Teeth Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:26 AM CDT Asset located in: Lake Worth, TX, USA	3731	2026 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: ZW01038 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:27 AM CDT Asset located in: Lake Worth, TX, USA
3723	All-Star 72 in E-Series Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:26 AM CDT Asset located in: Lake Worth, TX, USA	3732	2026 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: ZW01066 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:27 AM CDT Asset located in: Lake Worth, TX, USA
3724	All-Star 48 in Rock w/Teeth Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:26 AM CDT Asset located in: Lake Worth, TX, USA	3733	2026 Skyway BSSHG-1720 68 in Skid Steer Grapple Bucket (Unused) S/N: 2026-07-08-JL37 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:27 AM CDT Asset located in: Lake Worth, TX, USA
3725	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: D09G1602 Usage: Not Available Lot closing time: Fri, Sep 18, 08:26 AM CDT Asset located in: Lake Worth, TX, USA	3734	2026 Skyway BSSHG-1720 68 in Skid Steer Grapple Bucket (Unused) S/N: 2026-07-08-JL38 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:28 AM CDT Asset located in: Lake Worth, TX, USA
3726	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: D07G1609 Usage: Not Available Lot closing time: Fri, Sep 18, 08:26 AM CDT Asset located in: Lake Worth, TX, USA	3737	2026 Skyway WSSEG-2100 82 in Rock (Unused) S/N: 2026-06-10-JL33 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:28 AM CDT Asset located in: Lake Worth, TX, USA
3727	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: D10G1602 Usage: Not Available Lot closing time: Fri, Sep 18, 08:27 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3738	2026 Skyway WSSEG-2100 82 in Rock (Unused) S/N: 2026-06-10-JL34 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:28 AM CDT Asset located in: Lake Worth, TX, USA	3750	Quantity of (2) 2026 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:30 AM CDT Asset located in: Lake Worth, TX, USA
3739	All-Star 68 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:28 AM CDT Asset located in: Lake Worth, TX, USA	3751	2026 GIYI GY-SA Skid Steer Auger (Unused) S/N: B-SMLXZ-1207 C/W: (1) 16 in bit, (1) 12 in bit, (1) 8 in bit, One crate Usage: Not Available Lot closing time: Fri, Sep 18, 08:30 AM CDT Asset located in: Lake Worth, TX, USA
3740	All-Star 16 in Grapple Skid Steer Stump Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:28 AM CDT Asset located in: Lake Worth, TX, USA	3752	2026 GIYI GY-SA Skid Steer Auger (Unused) S/N: B-SMLXZ-1209 C/W: (1) 16 in bit, (1) 12 in bit, (1) 8 in bit, One crate Usage: Not Available Lot closing time: Fri, Sep 18, 08:30 AM CDT Asset located in: Lake Worth, TX, USA
3741	All-Star 16 in Grapple Skid Steer Stump Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:29 AM CDT Asset located in: Lake Worth, TX, USA	3753	2026 GIYI GY-SA Skid Steer Auger (Unused) S/N: B-SMLXZ-1206 C/W: (1) 16 in bit, (1) 12 in bit, (1) 8 in bit, One crate Usage: Not Available Lot closing time: Fri, Sep 18, 08:30 AM CDT Asset located in: Lake Worth, TX, USA
3742	All-Star 16 in Skid Steer Stump Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:29 AM CDT Asset located in: Lake Worth, TX, USA	3754	2026 GIYI GY-SA Skid Steer Auger (Unused) S/N: B-SMLXZ-1208 C/W: (1) 16 in bit, (1) 12 in bit, (1) 8 in bit, One crate Usage: Not Available Lot closing time: Fri, Sep 18, 08:31 AM CDT Asset located in: Lake Worth, TX, USA
3743	All-Star 16 in Skid Steer Stump Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:29 AM CDT Asset located in: Lake Worth, TX, USA	3755	2026 GIYI GY-AG70 Alloy Skid Steer Auger (Unused) S/N: B-SMHJLXZ-429 C/W: (1) 16 in bit, (1) 12 in bit, (1) 8 in bit, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 08:31 AM CDT Asset located in: Lake Worth, TX, USA
3744	2025 Kit Containers QT-TS-40 16 in Skid Steer Stump Bucket (Unused) S/N: D28F1907 Usage: Not Available Lot closing time: Fri, Sep 18, 08:29 AM CDT Asset located in: Lake Worth, TX, USA	3764	2026 GIYI GY-VB79 80 in Vibration Skid Steer Screening Bucket (Unused) S/N: D-ZDD260741 Usage: Not Available Lot closing time: Fri, Sep 18, 08:32 AM CDT Asset located in: Lake Worth, TX, USA
3749	Quantity of (2) 2026 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:30 AM CDT Asset located in: Lake Worth, TX, USA	3765	Mid-State 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:32 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3766	2025 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: D08H1605 Usage: Not Available Lot closing time: Fri, Sep 18, 08:32 AM CDT Asset located in: Lake Worth, TX, USA	3775	Mid-State 84 in Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:34 AM CDT Asset located in: Lake Worth, TX, USA
3767	All-Star 80 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:33 AM CDT Asset located in: Lake Worth, TX, USA	3776	Mid-State 84 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:34 AM CDT Asset located in: Lake Worth, TX, USA
3768	Mid-State 78 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:33 AM CDT Asset located in: Lake Worth, TX, USA	3777	All-Star 80 in Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:34 AM CDT Asset located in: Lake Worth, TX, USA
3769	Mid-State 74 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:33 AM CDT Asset located in: Lake Worth, TX, USA	3778	Mid-State 80 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:34 AM CDT Asset located in: Lake Worth, TX, USA
3770	Mid-State 72 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:33 AM CDT Asset located in: Lake Worth, TX, USA	3779	All-Star 78 in Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:34 AM CDT Asset located in: Lake Worth, TX, USA
3771	2026 Skyway WBCT-4IN1 74 in Multi-Purpose Skid Steer Bucket (Unused) S/N: 2026-07-08-JL36 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:33 AM CDT Asset located in: Lake Worth, TX, USA	3780	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:34 AM CDT Asset located in: Lake Worth, TX, USA
3772	2026 Skyway WBCT-4IN1 Multi-Purpose Backhoe Loader Bucket (Unused) S/N: 2026-06-10-JL32 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:33 AM CDT Asset located in: Lake Worth, TX, USA	3781	2025 Kit Containers QT-DB-S78 78 in General Purpose Skid Steer Bucket (Unused) S/N: D03H1615 Usage: Not Available Lot closing time: Fri, Sep 18, 08:35 AM CDT Asset located in: Lake Worth, TX, USA
3773	2026 Wolverine TDB-11-84W Skid Steer Bucket (Unused) S/N: ZW10236 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:33 AM CDT Asset located in: Lake Worth, TX, USA	3782	2026 Wolverine TDB-11-78W Skid Steer Bucket (Unused) S/N: ZW10237 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:35 AM CDT Asset located in: Lake Worth, TX, USA
		3784	Mid-State 74 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:35 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3785	72 in Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:35 AM CDT Asset located in: Lake Worth, TX, USA	3795	60 in Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:37 AM CDT Asset located in: Lake Worth, TX, USA
3786	Mid-State 72 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:35 AM CDT Asset located in: Lake Worth, TX, USA	3796	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:37 AM CDT Asset located in: Lake Worth, TX, USA
3787	2026 Wolverine TDB-11-72W Skid Steer Bucket (Unused) S/N: ZW10234 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:36 AM CDT Asset located in: Lake Worth, TX, USA	3797	2026 GIYI GY-BT67 67 in General Purpose Skid Steer Bucket (Unused) S/N: D CD260711 C/W: Located in Lane 69 Usage: Not Available Lot closing time: Fri, Sep 18, 08:37 AM CDT Asset located in: Lake Worth, TX, USA
3789	Mid-State 68 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 08:36 AM CDT Asset located in: Humble, TX, USA	3799	All-Star 84 in Rock w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:37 AM CDT Asset located in: Lake Worth, TX, USA
3790	Mid-State 68 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:36 AM CDT Asset located in: Lake Worth, TX, USA	3800	All-Star 80 in Rock w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:37 AM CDT Asset located in: Lake Worth, TX, USA
3791	Mid-State 68 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:36 AM CDT Asset located in: Lake Worth, TX, USA	3801	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:38 AM CDT Asset located in: Lake Worth, TX, USA
3792	2026 Wolverine TDB-11-66W 66 in Skid Steer Bucket (Unused) S/N: ZW10227 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:36 AM CDT Asset located in: Lake Worth, TX, USA	3802	All-Star 78 in E-Series Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:38 AM CDT Asset located in: Lake Worth, TX, USA
3793	2025 Kit Containers QT-DB-S66 66 in General Purpose Skid Steer Bucket (Unused) S/N: D15F1628 Usage: Not Available Lot closing time: Fri, Sep 18, 08:36 AM CDT Asset located in: Lake Worth, TX, USA	3803	2026 TOFT LSSB-78 78 in Skeleton Rock Skid Steer Bucket (Unused) S/N: LSSB2601023 Usage: Not Available Lot closing time: Fri, Sep 18, 08:38 AM CDT Asset located in: Lake Worth, TX, USA
		3804	2026 TOFT HSSB-74 74 in Rock Skid Steer Bucket (Unused) S/N: HSSB2601071 Usage: Not Available Lot closing time: Fri, Sep 18, 08:38 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3805	2026 TOFT HSSB-74 74 in Rock Skid Steer Bucket (Unused) S/N: HSSB2601047 Usage: Not Available Lot closing time: Fri, Sep 18, 08:38 AM CDT Asset located in: Lake Worth, TX, USA	3814	2025 Kit Containers QT-SB-L76-V3 76 in Skeleton Skid Steer Bucket (Unused) S/N: D18H1610 Usage: Not Available Lot closing time: Fri, Sep 18, 08:40 AM CDT Asset located in: Lake Worth, TX, USA
3806	2026 TOFT LSSB-78 74 in Rock Skid Steer Bucket (Unused) S/N: LSSB2601062 Usage: Not Available Lot closing time: Fri, Sep 18, 08:38 AM CDT Asset located in: Lake Worth, TX, USA	3815	2025 Kit Containers QT-SB-H72-F 72 in Skeleton Skid Steer Bucket (Unused) S/N: D17H1601 Usage: Not Available Lot closing time: Fri, Sep 18, 08:40 AM CDT Asset located in: Lake Worth, TX, USA
3807	All-Star 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:39 AM CDT Asset located in: Lake Worth, TX, USA	3816	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 08:40 AM CDT Asset located in: Humble, TX, USA
3808	All-Star 72 in E-Series Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:39 AM CDT Asset located in: Lake Worth, TX, USA	3825	All-Star 48 in Hydraulic Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 08:41 AM CDT Asset located in: Lake Worth, TX, USA
3809	All-Star 72 in E-Series Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:39 AM CDT Asset located in: Lake Worth, TX, USA	3826	All-Star 48 in Hydraulic Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 08:41 AM CDT Asset located in: Lake Worth, TX, USA
3810	All-Star 68 in Rock w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:39 AM CDT Asset located in: Lake Worth, TX, USA	3835	Quantity of (10) 2026 Mower King SA 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 68 Usage: Not Available Lot closing time: Fri, Sep 18, 08:43 AM CDT Asset located in: Lake Worth, TX, USA
3811	All-Star 78 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 08:39 AM CDT Asset located in: Humble, TX, USA	3836	Quantity of (8) 2026 Mower King SA 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 68 Usage: Not Available Lot closing time: Fri, Sep 18, 08:43 AM CDT Asset located in: Lake Worth, TX, USA
3812	All-Star 78 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 08:39 AM CDT Asset located in: Humble, TX, USA	3837	Quantity of (4) 2026 Mower King SA 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 68 Usage: Not Available Lot closing time: Fri, Sep 18, 08:43 AM CDT Asset located in: Lake Worth, TX, USA
3813	2025 Kit Containers QT-SB-H76-V3 76 in Skeleton Skid Steer Bucket (Unused) S/N: D18H1623 Usage: Not Available Lot closing time: Fri, Sep 18, 08:39 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3842	Quantity of (2) 2026 LYALS ALSF48 48 in Skid Steer Forks (Unused) S/N: ALS3583 Usage: Not Available Lot closing time: Fri, Sep 18, 08:44 AM CDT Asset located in: Lake Worth, TX, USA	3851	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:45 AM CDT Asset located in: Lake Worth, TX, USA
3843	Quantity of (2) 2026 LYALS ALSF48 48 in Skid Steer Forks (Unused) S/N: ALS3584 Usage: Not Available Lot closing time: Fri, Sep 18, 08:44 AM CDT Asset located in: Lake Worth, TX, USA	3852	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:45 AM CDT Asset located in: Lake Worth, TX, USA
3844	2026 Wolverine FK-11-48W 48 in Skid Steer Forks (Unused) S/N: ZW10200 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:44 AM CDT Asset located in: Lake Worth, TX, USA	3853	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:45 AM CDT Asset located in: Lake Worth, TX, USA
3845	2026 Wolverine FK-11-48W 48 in Skid Steer Forks (Unused) S/N: ZW10199 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:44 AM CDT Asset located in: Lake Worth, TX, USA	3854	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:46 AM CDT Asset located in: Lake Worth, TX, USA
3846	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:44 AM CDT Asset located in: Lake Worth, TX, USA	3855	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:46 AM CDT Asset located in: Lake Worth, TX, USA
3847	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:45 AM CDT Asset located in: Lake Worth, TX, USA	3862	2026 Skyway WSSBF-1150 45 in Skid Steer Forks (Unused) S/N: 2026-07-08-JL40 C/W: Located in Lane 68, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:47 AM CDT Asset located in: Lake Worth, TX, USA
3848	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:45 AM CDT Asset located in: Lake Worth, TX, USA	3863	2026 Skyway WSSBF-1150 45 in Skid Steer Forks (Unused) S/N: 2026-07-08-JL41 C/W: Located in Lane 68, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:47 AM CDT Asset located in: Lake Worth, TX, USA
3849	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:45 AM CDT Asset located in: Lake Worth, TX, USA	3864	2026 Skyway WSSBF-1150 45 in Skid Steer Forks (Unused) S/N: 2026-07-08-JL39 C/W: Located in Lane 68, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:47 AM CDT Asset located in: Lake Worth, TX, USA
3850	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:45 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3865	2026 Skyway WSSBF-1150 45 in Skid Steer Forks (Unused) S/N: 2026-06-10-JL36 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:47 AM CDT Asset located in: Lake Worth, TX, USA	3869	2026 Arteer PF-42L 42 in Skid Steer Forks S/N: 202680171260 C/W: Located in Lane 76 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA
3866	2026 Skyway WSSBF-1150 45 in Skid Steer Forks (Unused) S/N: 2026-06-10-JL35 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:47 AM CDT Asset located in: Lake Worth, TX, USA	3870	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA
3867	2026 Skyway WSSBF-1150 45 in Skid Steer Forks (Unused) S/N: 2026-06-10-JL37 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA	3871	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA
3867A	Kit Containers 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA	3872	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA
3867B	Kit Containers 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA	3873	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA
3867C	Kit Containers 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA	3874	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:49 AM CDT Asset located in: Lake Worth, TX, USA
3867D	Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA	3875	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:49 AM CDT Asset located in: Lake Worth, TX, USA
3868	Blue Diamond 313950-25 42 in Mini Skid Steer Forks S/N: 163759 C/W: Located in Lane 77 Usage: Not Available Lot closing time: Fri, Sep 18, 08:48 AM CDT Asset located in: Lake Worth, TX, USA	3876	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:49 AM CDT Asset located in: Lake Worth, TX, USA
		3878	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:49 AM CDT Asset located in: Lake Worth, TX, USA
		3879	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:49 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3880	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:49 AM CDT Asset located in: Lake Worth, TX, USA	3897	Quantity of (2) 2026 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:52 AM CDT Asset located in: Lake Worth, TX, USA
3881	2026 TOFT TOFT750 Skid Steer Post Driver (Unused) S/N: TOFTJW43Z7543 Usage: Not Available Lot closing time: Fri, Sep 18, 08:50 AM CDT Asset located in: Lake Worth, TX, USA	3901	2026 TOFT TOFT680 Skid Steer Post Driver (Unused) S/N: TOFTJW40Z19231 Usage: Not Available Lot closing time: Fri, Sep 18, 08:53 AM CDT Asset located in: Lake Worth, TX, USA
3890	2026 LYALS ALS680 Skid Steer Post Driver (Unused) S/N: ALS3618 Usage: Not Available Lot closing time: Fri, Sep 18, 08:51 AM CDT Asset located in: Lake Worth, TX, USA	3904	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:53 AM CDT Asset located in: Lake Worth, TX, USA
3891	2026 LYALS ALS680 Skid Steer Post Driver (Unused) S/N: ALS3613 Usage: Not Available Lot closing time: Fri, Sep 18, 08:51 AM CDT Asset located in: Lake Worth, TX, USA	3909	2026 AGT STSD10 3-Point & Skid Steer Seeder (Unused) S/N: STSD10260107987 C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:54 AM CDT Asset located in: Lake Worth, TX, USA
3892	2026 LYALS ALS680 Skid Steer Post Driver (Unused) S/N: ALS3615 Usage: Not Available Lot closing time: Fri, Sep 18, 08:51 AM CDT Asset located in: Lake Worth, TX, USA	3910	2026 AGT STSD10 3-Point & Skid Steer Seeder (Unused) S/N: STSD10260108014 C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:54 AM CDT Asset located in: Lake Worth, TX, USA
3893	2026 LYALS ALS680 Skid Steer Post Driver (Unused) S/N: ALS3622 Usage: Not Available Lot closing time: Fri, Sep 18, 08:51 AM CDT Asset located in: Lake Worth, TX, USA	3911	2026 AGT STSD10 3-Point & Skid Steer Seeder (Unused) S/N: STSD10260107917 C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:54 AM CDT Asset located in: Lake Worth, TX, USA
3894	2026 GIYI GY-AD680 Skid Steer Post Driver (Unused) S/N: ADZC6802607143 C/W: Located in Lane 71 Usage: Not Available Lot closing time: Fri, Sep 18, 08:52 AM CDT Asset located in: Lake Worth, TX, USA	3912	2026 AGT STSD10 3-Point & Skid Steer Seeder (Unused) S/N: STSD10260107969 C/W: Located in Lane 70, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:54 AM CDT Asset located in: Lake Worth, TX, USA
3895	2026 GIYI GY-AD680 Skid Steer Post Driver (Unused) S/N: ADZC6802607142 C/W: Located in Lane 71 Usage: Not Available Lot closing time: Fri, Sep 18, 08:52 AM CDT Asset located in: Lake Worth, TX, USA		
3896	2026 GIYI GY-AD680 Skid Steer Post Driver (Unused) S/N: ADZC6802607141 C/W: Located in Lane 71 Usage: Not Available Lot closing time: Fri, Sep 18, 08:52 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3913	2026 GIYI GY-HLS82 Skid Steer Log Splitter (Unused) S/N: DJYPMQ260780 C/W: Located in Lane 70 Usage: Not Available Lot closing time: Fri, Sep 18, 08:54 AM CDT Asset located in: Lake Worth, TX, USA	3925	2026 GIYI GY-MTS43 Mini Skid Steer Tree Shear (Unused) S/N: X-SMJD260626 C/W: Located in Lane 70 Usage: Not Available Lot closing time: Fri, Sep 18, 08:56 AM CDT Asset located in: Lake Worth, TX, USA
3914	2026 GIYI GY-HLS82 Skid Steer Log Splitter (Unused) S/N: DJYPMQ260781 C/W: Located in Lane 70 Usage: Not Available Lot closing time: Fri, Sep 18, 08:55 AM CDT Asset located in: Lake Worth, TX, USA	3926	2026 GIYI TP25 Skid Steer Post Puller (Unused) S/N: HSLBQ260633 Usage: Not Available Lot closing time: Fri, Sep 18, 08:56 AM CDT Asset located in: Lake Worth, TX, USA
3915	2026 GIYI GY-SLS79 26 in Skid Steer Log Splitter (Unused) S/N: D CYPMJ260723 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:55 AM CDT Asset located in: Lake Worth, TX, USA	3931	All-Star 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:57 AM CDT Asset located in: Lake Worth, TX, USA
3916	2026 Gigi HLS82 14 in Skid Steer Log Splitter S/N: FJYPMQ2602133 C/W: Located in Lane 76 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 08:55 AM CDT Asset located in: Lake Worth, TX, USA	3932	All-Star 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:57 AM CDT Asset located in: Lake Worth, TX, USA
3919	Quantity of (2) 2026 GIYI GY-TB72 Skid Steer Boom (Unused) S/N: SMDG260752 Usage: Not Available Lot closing time: Fri, Sep 18, 08:55 AM CDT Asset located in: Lake Worth, TX, USA	3933	All-Star 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: Located in Lane 77 Usage: Not Available Lot closing time: Fri, Sep 18, 08:57 AM CDT Asset located in: Lake Worth, TX, USA
3922	2026 LYALS ALSHSBP 108 in Hydraulic Skid Steer Boom (Unused) S/N: ALS3651 Usage: Not Available Lot closing time: Fri, Sep 18, 08:56 AM CDT Asset located in: Lake Worth, TX, USA	3933A	Kit Containers QT-TM 2 in Skid Steer Hitch Receiver (Unused) S/N: D20G1428 Usage: Not Available Lot closing time: Fri, Sep 18, 08:57 AM CDT Asset located in: Lake Worth, TX, USA
3923	Gigi TB72 Skid Steer Boom S/N: CSMDG260121 C/W: Located in Lane 76 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 08:56 AM CDT Asset located in: Lake Worth, TX, USA	3933B	Kit Containers QT-TM 2 in Skid Steer Hitch Receiver (Unused) S/N: D23G1921 Usage: Not Available Lot closing time: Fri, Sep 18, 08:58 AM CDT Asset located in: Lake Worth, TX, USA
3924	Danuser Intimidator Tree Puller S/N: 7191 C/W: Located in Lane 56 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 08:56 AM CDT Asset located in: Lake Worth, TX, USA	3934	2026 Wolverine PHA-15-02C Skid Steer 3-Point Adapter (Unused) S/N: ZW03258 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:58 AM CDT Asset located in: Lake Worth, TX, USA
		3935	2026 Wolverine PHA-15-02C Skid Steer 3-Point Adapter (Unused) S/N: ZW03266 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:58 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3938	2026 Wolverine PT-16-02C Skid Steer 3-Point Adapter (Unused) S/N: ZW00265 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 08:58 AM CDT Asset located in: Lake Worth, TX, USA	3947	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
3939	Arteer PHA-2C Skid Steer 3-Point Adapter S/N: 202680171279 C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 08:58 AM CDT Asset located in: Lake Worth, TX, USA	3948	2026 Wolverine QMP2-16-12T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10581 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
3940	Kit Containers 2YFT-SST 2 Cyd Skid Steer Dump Hopper (Unused) S/N: D16G1208 Usage: Not Available Lot closing time: Fri, Sep 18, 08:58 AM CDT Asset located in: Lake Worth, TX, USA	3949	2026 Wolverine QMP2-16-12T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10539 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
3941	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:59 AM CDT Asset located in: Lake Worth, TX, USA	3950	2026 Wolverine QMP3-16-6T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10482 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
3942	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:59 AM CDT Asset located in: Lake Worth, TX, USA	3951	2026 Wolverine QMP3-16-6T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10483 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
3943	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:59 AM CDT Asset located in: Lake Worth, TX, USA	3952	2026 Wolverine QMP1-16-10T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10584 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
3944	All-Star Skid Steer Attachment Mounting Plate S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:59 AM CDT Asset located in: Lake Worth, TX, USA	3953	2026 Wolverine QMP1-16-10T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10595 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:00 AM CDT Asset located in: Lake Worth, TX, USA
3945	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:59 AM CDT Asset located in: Lake Worth, TX, USA		
3946	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 08:59 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
3954	Skid Steer Fork Frame S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:01 AM CDT Asset located in: Lake Worth, TX, USA	3963	Belltec 20 in Telephone Pole Grinder Auger Bit S/N: Not Available Usage: Not Available Notes: MADE IN USA : Texas Manufacturer Overstock Units Lot closing time: Fri, Sep 18, 09:02 AM CDT Asset located in: Lake Worth, TX, USA
3955	2026 Wolverine TAP-16-4200G Skid Steer Rotating Conversion Hanger (Unused) S/N: ZW00022 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:01 AM CDT Asset located in: Lake Worth, TX, USA	3964	Belltec 18 in Auger Bit (Unused) S/N: Not Available Usage: Not Available Notes: MADE IN USA : Texas Manufacturer Overstock Units Lot closing time: Fri, Sep 18, 09:02 AM CDT Asset located in: Lake Worth, TX, USA
3956	2026 Wolverine TAP-16-4200G Skid Steer Rotating Conversion Hanger (Unused) S/N: ZW00023 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:01 AM CDT Asset located in: Lake Worth, TX, USA	3968	2026 GIYI EDM320 39 in Excavator Disc Mulcher (Unused) S/N: 320YPTGJ250406 Usage: Not Available Lot closing time: Fri, Sep 18, 09:03 AM CDT Asset located in: Lake Worth, TX, USA
3956A	2026 GIYI WS43 Mini Skid Steer Wood Splitter (Unused) S/N: BXPMQ260101 C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:01 AM CDT Asset located in: Lake Worth, TX, USA	3970A	2026 AGT EXFLM115 45 in Excavator Flail Mower (Unused) S/N: EXFLM11526020701D Usage: Not Available Lot closing time: Fri, Sep 18, 09:03 AM CDT Asset located in: Lake Worth, TX, USA
3959	2026 LYALS ALSDP320 Demolition Pulverizer (Unused) S/N: ALS3199 Usage: Not Available Lot closing time: Fri, Sep 18, 09:01 AM CDT Asset located in: Lake Worth, TX, USA	3971	2026 VICSEC VCHTM 60 in Mini Excavator Hedge Trimmer (Unused) S/N: E84756 Usage: Not Available Lot closing time: Fri, Sep 18, 09:03 AM CDT Asset located in: Lake Worth, TX, USA
3960	2026 TOFT TOFT08P Demolition Pulverizer - Fits Excavator 20 - 30 ton (Unused) S/N: TOFTHP26052303 Usage: Not Available Lot closing time: Fri, Sep 18, 09:01 AM CDT Asset located in: Lake Worth, TX, USA	3972	2026 VICSEC VCHTM 60 in Mini Excavator Hedge Trimmer (Unused) S/N: E84754 Usage: Not Available Lot closing time: Fri, Sep 18, 09:03 AM CDT Asset located in: Lake Worth, TX, USA
3962	Auger Bit S/N: Not Available C/W: 22 in wide Usage: Not Available Lot closing time: Fri, Sep 18, 09:02 AM CDT Asset located in: Lake Worth, TX, USA	3973	2026 VICSEC VCHTM 60 in Mini Excavator Hedge Trimmer (Unused) S/N: E84755 Usage: Not Available Lot closing time: Fri, Sep 18, 09:03 AM CDT Asset located in: Lake Worth, TX, USA
3962A	Quantity of (4) Assorted Auger Bit S/N: Not Available C/W: Located in Lane 56, (2) 36 in, (1) 30 in, (1) 16 in Usage: Not Available Lot closing time: Fri, Sep 18, 09:02 AM CDT Asset located in: Lake Worth, TX, USA	3980	2026 LYALS ALSEWG60 Rotating Excavator Grapple (Unused) S/N: ALS3315 Usage: Not Available Lot closing time: Fri, Sep 18, 09:04 AM CDT Asset located in: Lake Worth, TX, USA
		3981	2026 LYALS ALSEWG60 Rotating Excavator Grapple (Unused) S/N: ALS3311 Usage: Not Available Lot closing time: Fri, Sep 18, 09:05 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
3982	2026 LYALS ALSERG60 20 in Rotating Excavator Grapple (Unused) S/N: ALS3216 Usage: Not Available Lot closing time: Fri, Sep 18, 09:05 AM CDT Asset located in: Lake Worth, TX, USA	3996	2026 LYALS ALS1000 Hydraulic Breaker (Unused) S/N: ALS3283 Usage: Not Available Lot closing time: Fri, Sep 18, 09:07 AM CDT Asset located in: Lake Worth, TX, USA
3983	2026 LYALS ALSEWG60 16 in Rotating Excavator Grapple (Unused) S/N: ALS3024 Usage: Not Available Lot closing time: Fri, Sep 18, 09:05 AM CDT Asset located in: Lake Worth, TX, USA	3999	2026 TOFT TOFT1000 Hydraulic Breaker - Fits Excavator 10-18 ton (Unused) S/N: TOFTJW50Z2476 Usage: Not Available Lot closing time: Fri, Sep 18, 09:07 AM CDT Asset located in: Lake Worth, TX, USA
3987	2026 TOFT TOFT04G Rotating Excavator Grapple - Fits 4-8 ton excavator (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:06 AM CDT Asset located in: Lake Worth, TX, USA	4003	2026 TOFT TOFT750 Hydraulic Breaker - Fits 7-9 ton excavator (Unused) S/N: TOFTJW43Z7417 Usage: Not Available Lot closing time: Fri, Sep 18, 09:08 AM CDT Asset located in: Lake Worth, TX, USA
3988	2026 TOFT TOFT04G 54 in Rotating Excavator Grapple - Fits 4-8 ton excavator (Unused) S/N: TOFTHLG260508 Usage: Not Available Lot closing time: Fri, Sep 18, 09:06 AM CDT Asset located in: Lake Worth, TX, USA	4004	2026 TOFT TOFT750 Hydraulic Breaker - Fits 7-9 ton excavator (Unused) S/N: TOFTJW43Z7514 Usage: Not Available Lot closing time: Fri, Sep 18, 09:08 AM CDT Asset located in: Lake Worth, TX, USA
3989	2026 TOFT TOFT04G Rotating Excavator Grapple - Fits 4-8 ton excavator (Unused) S/N: TOFTHLG260513 Usage: Not Available Lot closing time: Fri, Sep 18, 09:06 AM CDT Asset located in: Lake Worth, TX, USA	4005	2026 LYALS ALS680 Hydraulic Breaker (Unused) S/N: ALS3572 Usage: Not Available Lot closing time: Fri, Sep 18, 09:08 AM CDT Asset located in: Lake Worth, TX, USA
3990	2023 FRD FX770QTV Q/C Hydraulic Breaker S/N: FX77001023 Usage: Not Available Lot closing time: Fri, Sep 18, 09:06 AM CDT Asset located in: Lake Worth, TX, USA	4006	2026 LYALS ALS680 Hydraulic Breaker (Unused) S/N: ALS3623 Usage: Not Available Lot closing time: Fri, Sep 18, 09:08 AM CDT Asset located in: Lake Worth, TX, USA
3990A	2013 Atlas Copco RX38 Hydraulic Breaker S/N: DEQ130656 C/W: Located in Lane 67 Usage: Not Available Lot closing time: Fri, Sep 18, 09:06 AM CDT Asset located in: Lake Worth, TX, USA	4007	2026 VICSEC VCH35 Hydraulic Breaker (Unused) S/N: E84741 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA
3991	2008 NPK E220 Q/C Hydraulic Breaker S/N: NP02116 C/W: Located in Lane 67 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 09:06 AM CDT Asset located in: Lake Worth, TX, USA	4008	2026 VICSEC VCH35 Mini Hydraulic Breaker (Unused) S/N: E84740 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA
3995	2026 TOFT TOFT1400 Hydraulic Breaker (Unused) S/N: TOFTJW81Z3758 Usage: Not Available Lot closing time: Fri, Sep 18, 09:07 AM CDT Asset located in: Lake Worth, TX, USA	4011	2021 Epiroc SB1102 Hydraulic Breaker S/N: C13418 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4011A	2021 Paladin SFB350 Hydraulic Breaker S/N: SFB03502100107 C/W: Located in Lane 67 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA	4015	2026 GIYI Excavator Auger - Fits Cat 305 (Unused) S/N: B-305TZYLXZ-019 C/W: 16 in Bit, Extension Rod Usage: Not Available Lot closing time: Fri, Sep 18, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
4011B	Paladin SFB350 Hydraulic Breaker S/N: SFB3502100116 C/W: Located in Lane 67 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA	4016	2026 Warrior WBMCC12-1550 61 in Q/C Cleanup Excavator Bucket - Fits Cat 312 / 12 - 14 ton (Unused) S/N: 2026-07-08-JL27 C/W: 65 mm Diameter Pins, 407 mm Center of Pin Boss to Center of Pin Boss, 220 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
4011C	Paladin SFB350 Hydraulic Breaker S/N: SFB3502100107 C/W: Located in Lane 67 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA	4017	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-07-08-JL11 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
4012	2020 Epiroc HAMMER Hydraulic Breaker S/N: BES134894 C/W: Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA	4018	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-07-08-JL12 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
4012A	2014 Atlas Copco RX-54 Hydraulic Breaker S/N: DE0133198 C/W: Located in Lane 67 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA	4019	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL04 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:10 AM CDT Asset located in: Lake Worth, TX, USA
4012B	Chicago Pneumatic RX26 Hydraulic Breaker S/N: Not Available C/W: Located in Lane 67 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA		
4012C	Hydraulic Breaker S/N: Not Available C/W: Located in Lane 67 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA		
4013	Gorilla Hydraulic Breaker S/N: DH22CH75 C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:09 AM CDT Asset located in: Lake Worth, TX, USA		
4014	2026 GIYI Excavator Auger - Fits Cat 305 (Unused) S/N: B-305TZYLXZ-014 C/W: 16 in Bit, Extension Rod Usage: Not Available Lot closing time: Fri, Sep 18, 09:10 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4020	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL09 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:10 AM CDT Asset located in: Lake Worth, TX, USA	4025	2026 Warrior WBMCC7-1500 59 in Cleanup Excavator Bucket - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-07-08-JL25 C/W: 50 mm Diameter Pins, 300 mm Center of Pin Boss to Center of Pin Boss, 190 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:11 AM CDT Asset located in: Lake Worth, TX, USA
4021	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL06 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:11 AM CDT Asset located in: Lake Worth, TX, USA	4026	2026 Warrior WBMCC7-1500 59 in Cleanup Excavator Bucket - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-06-10-JL20 C/W: 50 mm Diameter Pins, 300 mm Center of Pin Boss to Center of Pin Boss, 190 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:11 AM CDT Asset located in: Lake Worth, TX, USA
4022	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL05 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:11 AM CDT Asset located in: Lake Worth, TX, USA	4027	2026 Warrior WBMCC7-1500 59 in Cleanup Excavator Bucket - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-06-10-JL21 C/W: 50 mm Diameter Pins, 300 mm Center of Pin Boss to Center of Pin Boss, 190 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:12 AM CDT Asset located in: Lake Worth, TX, USA
4023	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL03 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:11 AM CDT Asset located in: Lake Worth, TX, USA	4028	2026 Warrior WBMCC7-1500 59 in Cleanup Excavator Bucket - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-07-08-JL26 C/W: 50 mm Diameter Pins, 300 mm Center of Pin Boss to Center of Pin Boss, 190 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:12 AM CDT Asset located in: Lake Worth, TX, USA
4024	2026 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL07 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:11 AM CDT Asset located in: Lake Worth, TX, USA	4029	2026 Warrior WBMCC5-1220 48 in Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL24 C/W: 45 mm Diameter Pins, 360 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:12 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4030	2026 Warrior WBMCC5-1220 48 in Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL23 C/W: 45 mm Diameter Pins, 360 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:12 AM CDT Asset located in: Lake Worth, TX, USA	4035	48 in Cleanup Excavator Bucket S/N: 17196911 Usage: Not Available Lot closing time: Fri, Sep 18, 09:13 AM CDT Asset located in: Lake Worth, TX, USA
4031	2026 Warrior WBMCC5-1220 48 in Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL22 C/W: 45 mm Diameter Pins, 360 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:12 AM CDT Asset located in: Lake Worth, TX, USA	4036	2026 LYALS ALSECB08 47 in Cleanup Excavator Bucket (Unused) S/N: ALS3604 Usage: Not Available Lot closing time: Fri, Sep 18, 09:13 AM CDT Asset located in: Lake Worth, TX, USA
4032	2026 Warrior WBMCC5-1220 48 in Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL17 C/W: 45 mm Diameter Pins, 360 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:12 AM CDT Asset located in: Lake Worth, TX, USA	4037	2026 LYALS ALSECB08 47 in Cleanup Excavator Bucket (Unused) S/N: ALS3605 Usage: Not Available Lot closing time: Fri, Sep 18, 09:13 AM CDT Asset located in: Lake Worth, TX, USA
4033	2026 Warrior WBMCC5-1220 48 in Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL18 C/W: 45 mm Diameter Pins, 360 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:12 AM CDT Asset located in: Lake Worth, TX, USA	4043	2025 D5T 36 in Hydraulic Tilting Excavator Bucket (Unused) S/N: 5TQXD251212 C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:14 AM CDT Asset located in: Lake Worth, TX, USA
4034	2026 Warrior WBMCC5-1220 48 in Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL19 C/W: 45 mm Diameter Pins, 360 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:13 AM CDT Asset located in: Lake Worth, TX, USA	4044	2025 GIYI D3T 33 in Hydraulic Tilting Excavator Bucket (Unused) S/N: 3TQXD251216 C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:14 AM CDT Asset located in: Lake Worth, TX, USA
		4045	2025 D3T 33 in Hydraulic Tilting Excavator Bucket (Unused) S/N: 3RQXD251217 C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:14 AM CDT Asset located in: Lake Worth, TX, USA
		4047	2026 Warrior WBMCR20-1500 59 in Q/C Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-07-08-JL14 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:15 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4048	2026 Warrior WBMCR20-1500 59 in Q/C Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-07-08-JL13 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:15 AM CDT Asset located in: Lake Worth, TX, USA	4055	2026 Warrior WBSC30-1600 62 in Skeleton Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: 2026-06-10-JL02 C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:16 AM CDT Asset located in: Lake Worth, TX, USA
4049	2026 Warrior WBSRC30-1500 59 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: 2026-07-08-JL17 C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:15 AM CDT Asset located in: Lake Worth, TX, USA	4056	2026 Warrior WBRC20-1400 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL13 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:16 AM CDT Asset located in: Lake Worth, TX, USA
4050	2026 LYALS ALSEB336 59 in Digging Excavator Bucket (Unused) S/N: ALS3276 Usage: Not Available Lot closing time: Fri, Sep 18, 09:15 AM CDT Asset located in: Lake Worth, TX, USA	4057	2026 Warrior WBRC20-1400 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL11 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:16 AM CDT Asset located in: Lake Worth, TX, USA
4053	2026 Warrior WBSRC30-1500 59 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: 2026-06-10-JL01 C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:15 AM CDT Asset located in: Lake Worth, TX, USA	4058	2026 Warrior WBRC20-1400 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL12 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:16 AM CDT Asset located in: Lake Worth, TX, USA
4054	2026 Warrior WBSRC30-1500 59 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: 2026-06-10-JL08 C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:16 AM CDT Asset located in: Lake Worth, TX, USA	4059	2026 Warrior WBRC20-1400 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-07-08-JL07 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:16 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4060	2026 Warrior WBRC20-1400 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-07-08-JL06 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:16 AM CDT Asset located in: Lake Worth, TX, USA	4074	John Deere 24 in Q/C Digging Excavator Bucket S/N: PXBU7KG001328 Usage: Not Available Lot closing time: Fri, Sep 18, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
4061	2026 KJ AM2048 48 in 1.2 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: 241009 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:17 AM CDT Asset located in: Lake Worth, TX, USA	4075	John Deere 12 in Q/C Digging Excavator Bucket S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
4062	2026 KJ AM2048 48 in 1.2 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: 241013 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:17 AM CDT Asset located in: Lake Worth, TX, USA	4076	2026 LYALS ALSTB05 16 in Trapezoid Excavator Bucket (Unused) S/N: ALS1423 Usage: Not Available Lot closing time: Fri, Sep 18, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
4063	2026 LYALS ALS EB320 48 in Digging Excavator Bucket (Unused) S/N: ALS3072 Usage: Not Available Lot closing time: Fri, Sep 18, 09:17 AM CDT Asset located in: Lake Worth, TX, USA	4077	2026 LYALS ALSTB08 16 in Trapezoid Excavator Bucket (Unused) S/N: ALS1339 Usage: Not Available Lot closing time: Fri, Sep 18, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
4064	2026 LYALS ALS EB320 48 in Digging Excavator Bucket (Unused) S/N: ALS3065 Usage: Not Available Lot closing time: Fri, Sep 18, 09:17 AM CDT Asset located in: Lake Worth, TX, USA	4078	39 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Lot closing time: Fri, Sep 18, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
4065	2026 LYALS ALS EB320 48 in Digging Excavator Bucket (Unused) S/N: ALS3132 Usage: Not Available Lot closing time: Fri, Sep 18, 09:17 AM CDT Asset located in: Lake Worth, TX, USA	4079	2019 Geith H11-0990-4230 35 in Q/C Digging Excavator Bucket S/N: 1009388 Usage: Not Available Lot closing time: Fri, Sep 18, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
4073A	Felco 36 in Compaction Excavator Bucket S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture ; Lot closing time: Fri, Sep 18, 09:18 AM CDT Asset located in: Lake Worth, TX, USA	4080	24 in Digging Excavator Bucket S/N: Not Available C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:19 AM CDT Asset located in: Lake Worth, TX, USA
		4081	19 in Q/C Digging Excavator Bucket (Unused) S/N: Not Available C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:20 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4082	2026 Warrior WBSC30-1600 62 in Skeleton Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: 2026-07-08-JL18 C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:20 AM CDT Asset located in: Lake Worth, TX, USA	4087	2026 Warrior WBMCS5-1320 52 in Skeleton Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL20 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:21 AM CDT Asset located in: Lake Worth, TX, USA
4083	2026 Warrior WBSC20-1500 60 in Skeleton Excavator Bucket - Fits 20 - 25 ton (Unused) S/N: 2026-07-08-JL09 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:20 AM CDT Asset located in: Lake Worth, TX, USA	4088	2026 Warrior WBMCS5-1320 52 in Skeleton Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL14 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:21 AM CDT Asset located in: Lake Worth, TX, USA
4084	2026 Warrior WBSC20-1500 60 in Skeleton Excavator Bucket - Fits 20 - 25 ton (Unused) S/N: 2026-07-08-JL10 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:20 AM CDT Asset located in: Lake Worth, TX, USA	4089	2026 Warrior WBMCS5-1320 52 in Skeleton Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL16 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:21 AM CDT Asset located in: Lake Worth, TX, USA
4085	2026 Warrior WBMCS5-1320 52 in Skeleton Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL21 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:20 AM CDT Asset located in: Lake Worth, TX, USA	4090	2026 Warrior WBMCS5-1320 52 in Skeleton Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL15 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:21 AM CDT Asset located in: Lake Worth, TX, USA
4086	2026 Warrior WBMCS5-1320 52 in Skeleton Cleanup Excavator Bucket - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL19 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:20 AM CDT Asset located in: Lake Worth, TX, USA	4092	2026 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:21 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4093	2026 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:21 AM CDT Asset located in: Lake Worth, TX, USA	4102	2026 TOFT TOFT06ER Excavator Ripper - Fits 10-15 ton excavator (Unused) S/N: TOFTERP2512059 Usage: Not Available Lot closing time: Fri, Sep 18, 09:23 AM CDT Asset located in: Lake Worth, TX, USA
4094	2026 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:22 AM CDT Asset located in: Lake Worth, TX, USA	4103	2026 Warrior WR05-06 Q/C Excavator Ripper - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL04 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:23 AM CDT Asset located in: Lake Worth, TX, USA
4097	2026 LYALS ALSER20 48in Excavator Ripper (Unused) S/N: ALS3576 Usage: Not Available Lot closing time: Fri, Sep 18, 09:22 AM CDT Asset located in: Lake Worth, TX, USA	4104	2026 Warrior WR05-06 Q/C Excavator Ripper - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL03 C/W: 45 mm Diameter Pins, 260 mm Center of Pin Boss to Center of Pin Boss, 156 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:23 AM CDT Asset located in: Lake Worth, TX, USA
4098	2026 LYALS ALSER20 48 in Excavator Ripper (Unused) S/N: ALS3577 Usage: Not Available Lot closing time: Fri, Sep 18, 09:22 AM CDT Asset located in: Lake Worth, TX, USA	4105	2026 TOFT TOFT04ER Excavator Ripper - Fits 4-8 ton excavator (Unused) S/N: ERP260323 Usage: Not Available Lot closing time: Fri, Sep 18, 09:23 AM CDT Asset located in: Lake Worth, TX, USA
4099	2026 TOFT TOFT08ER Excavator Ripper - Fits 20-30 ton excavator (Unused) S/N: TOFTERP260139 Usage: Not Available Lot closing time: Fri, Sep 18, 09:22 AM CDT Asset located in: Lake Worth, TX, USA	4107	2026 Warrior WBRC12-1620-1 64 in Excavator Rake - Fits Cat 312 / 10 - 12 ton (Unused) S/N: 2026-07-08-JL29 C/W: 65 mm Diameter Pins, 405 mm Center of Pin Boss to Center of Pin Boss, 220 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:24 AM CDT Asset located in: Lake Worth, TX, USA
4100	2026 Warrior WRC12 Q/C Excavator Ripper - Fits Cat 312 / 12 - 14 ton (Unused) S/N: Not Available C/W: 65 mm Diameter Pins, 407 mm Center of Pin Boss to Center of Pin Boss, 220 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:22 AM CDT Asset located in: Lake Worth, TX, USA	4108	2026 Warrior WBRC12-1620-1 64 in Excavator Rake - Fits Cat 312 / 10 - 12 ton (Unused) S/N: 2026-06-10-JL31 C/W: 65 mm Diameter Pins, 405 mm Center of Pin Boss to Center of Pin Boss, 220 mm Inside to Inside Pin Boss Spacing, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:24 AM CDT Asset located in: Lake Worth, TX, USA
4101	2026 TOFT TOFT06ER Excavator Ripper - Fits 10-15 ton excavator (Unused) S/N: TOFTERP2512061 Usage: Not Available Lot closing time: Fri, Sep 18, 09:23 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4109	2026 Warrior WBRC20-1620 Excavator Rake - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-07-08-JL28 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:24 AM CDT Asset located in: Lake Worth, TX, USA	4116	2026 Warrior WBRC07-1200 47 in Excavator Rake - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-06-10-JL27 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:25 AM CDT Asset located in: Lake Worth, TX, USA
4110	2026 Warrior WBRC20-1620 Excavator Rake - Fits Cat 320 / 20 - 25 ton (Unused) S/N: 2026-06-10-JL30 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:24 AM CDT Asset located in: Lake Worth, TX, USA	4117	2026 Warrior WBRC05-1000 39 in Excavator Rake - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL26 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:25 AM CDT Asset located in: Lake Worth, TX, USA
4111	2026 Warrior WBRC07-1200 47 in Excavator Rake - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-07-08-JL35 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:24 AM CDT Asset located in: Lake Worth, TX, USA	4118	2026 Warrior WBRC05-1000 39 in Excavator Rake - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL24 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:25 AM CDT Asset located in: Lake Worth, TX, USA
4112	2026 Warrior WBRC07-1200 47 in Excavator Rake - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-07-08-JL34 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:24 AM CDT Asset located in: Lake Worth, TX, USA	4119	2026 Warrior WBRC05-1000 39 in Excavator Rake - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-06-10-JL25 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:25 AM CDT Asset located in: Lake Worth, TX, USA
4113	2026 Warrior WBRC07-1200 47 in Excavator Rake - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-07-08-JL33 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:24 AM CDT Asset located in: Lake Worth, TX, USA	4120	2026 Warrior WBRC05-1000 39 in Excavator Rake - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL30 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:25 AM CDT Asset located in: Lake Worth, TX, USA
4114	2026 Warrior WBRC07-1200 47 in Excavator Rake - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-06-10-JL28 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:25 AM CDT Asset located in: Lake Worth, TX, USA	4121	2026 Warrior WBRC05-1000 39 in Excavator Rake - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL31 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:26 AM CDT Asset located in: Lake Worth, TX, USA
4115	2026 Warrior WBRC07-1200 47 in Excavator Rake - Fits Cat 307 / 6 - 8 ton (Unused) S/N: 2026-06-10-JL29 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:25 AM CDT Asset located in: Lake Worth, TX, USA	4122	2026 Warrior WBRC05-1000 39 in Excavator Rake - Fits Cat 305 / 5 - 6 ton (Unused) S/N: 2026-07-08-JL32 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:26 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4123	2026 TOFT TW072 72 in Excavator Rake - Fits 15-30 Ton Excavator (Unused) S/N: TWOR2610978 Usage: Not Available Lot closing time: Fri, Sep 18, 09:26 AM CDT Asset located in: Lake Worth, TX, USA	4131	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26062801D C/W: Located in Lane 68, (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:27 AM CDT Asset located in: Lake Worth, TX, USA
4124	2026 TOFT TW072 72 in Excavator Rake - Fits 15-30 ton excavator (Unused) S/N: TWOR2610982 Usage: Not Available Lot closing time: Fri, Sep 18, 09:26 AM CDT Asset located in: Lake Worth, TX, USA	4132	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26062802D C/W: (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:27 AM CDT Asset located in: Lake Worth, TX, USA
4125	2026 GIYI GY-PC291 Mini Excavator Vibratory Plate Compactor (Unused) S/N: HW PBH260708 C/W: Located in Lane 68 Usage: Not Available Lot closing time: Fri, Sep 18, 09:26 AM CDT Asset located in: Lake Worth, TX, USA	4133	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26062503B C/W: (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:27 AM CDT Asset located in: Lake Worth, TX, USA
4126	2026 TOFT TOFT08T 36 in Hydraulic Excavator Thumb - Fits 20-30 ton excavator (Unused) S/N: TOFTHT260319 Usage: Not Available Lot closing time: Fri, Sep 18, 09:26 AM CDT Asset located in: Lake Worth, TX, USA	4134	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26062502B C/W: (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:28 AM CDT Asset located in: Lake Worth, TX, USA
4127	KBKC Asphalt Cutter - Fits Cat 307/308 (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:27 AM CDT Asset located in: Lake Worth, TX, USA	4135	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26062501B C/W: (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:28 AM CDT Asset located in: Lake Worth, TX, USA
4128	Quantity of (8) Mini Excavator Attachments - Fits Cat 301 (Unused) S/N: Not Available C/W: Located in Lane 73, (3) Buckets (2) Auger Bits (2) Grapples (1) Ripper Usage: Not Available Lot closing time: Fri, Sep 18, 09:27 AM CDT Asset located in: Lake Worth, TX, USA		
4129	2026 GIYI GY-PC291 Mini Excavator Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 68 Usage: Not Available Lot closing time: Fri, Sep 18, 09:27 AM CDT Asset located in: Lake Worth, TX, USA		
4130	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26062803D C/W: Located in Lane 68, (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:27 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4136	Quantity of (8) 2026 GIYI Cat 301 GYA-8 Mini Excavator Attachments - Fits Cat 301 (Unused) S/N: C-301SJB-1735 C/W: Located in Lane 68, (3) Buckets, (1) Rake, (1) Quick Coupler, (1) Grapple, (1) Auger w/Bit, (1) Auger Bit, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:28 AM CDT Asset located in: Lake Worth, TX, USA	4142	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526062803D C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
4137	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6557 C/W: Located in Lane 68, (3) Buckets, (1) Rake, (1) Quick Coupler, (1) Grapple, (1) Auger w/Bit, (1) Auger Bit, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:28 AM CDT Asset located in: Lake Worth, TX, USA	4143	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526062801D C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
4138	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6556 C/W: Located in Lane 68, (3) Buckets, (1) Rake, (1) Quick Coupler, (1) Grapple, (1) Auger w/Bit, (1) Auger Bit, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:28 AM CDT Asset located in: Lake Worth, TX, USA	4144	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526062802D C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
4139	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6948 C/W: Located in Lane 68, (3) Buckets, (1) Rake, (1) Quick Coupler, (1) Grapple, (1) Auger w/Bit, (1) Auger Bit, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:28 AM CDT Asset located in: Lake Worth, TX, USA	4145	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526062503B C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
4140	Quantity of (6) 2026 AGT 12EX-SET6 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET626062801D C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake, (1) Auger w/ 8 in Bit ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:28 AM CDT Asset located in: Lake Worth, TX, USA	4146	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526062502B C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:29 AM CDT Asset located in: Lake Worth, TX, USA
4141	Quantity of (6) 2026 AGT 12EX-SET6 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET626062501B C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake, (1) Auger w/ 8 in Bit ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:29 AM CDT Asset located in: Lake Worth, TX, USA	4147	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526062501B C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4148	96 in Wheel Loader Forks - Fits John Deere 744K S/N: DWEHTC1060015 Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	4155	JRB 71 in Q/C Wheel Loader Forks S/N: J000136999-1 Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:31 AM CDT Asset located in: Lake Worth, TX, USA
4149	94 in Wheel Loader Forks - Fits John Deere 744K S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	4156	Q/C Wheel Loader Forks - Fits John Deere 644K S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:31 AM CDT Asset located in: Lake Worth, TX, USA
4150	94 in Wheel Loader Forks - Fits John Deere 744K S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	4157	JRB 70 in 70 in Wheel Loader Forks S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:31 AM CDT Asset located in: Lake Worth, TX, USA
4151	Cat 72 in Q/C Wheel Loader Forks - Fits Cat 924 /930/938 S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	4158	Paladin 70 in Q/C Wheel Loader Forks - Fits John Deere 644K S/N: J0001438841 Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:31 AM CDT Asset located in: Lake Worth, TX, USA
4152	Cat 72 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	4159	JRB 69 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:31 AM CDT Asset located in: Lake Worth, TX, USA
4153	Cat 72 in Q/C Wheel Loader Forks - Fits Cat 838M S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	4160	68 in Wheel Loader Forks - Fits John Deere S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:31 AM CDT Asset located in: Lake Worth, TX, USA
4153A	Paladin 69 in Wheel Loader Forks - Fits John Deere 644K/724K S/N: J000115930-1 Usage: Not Available Lot closing time: Fri, Sep 18, 09:30 AM CDT Asset located in: Lake Worth, TX, USA	4161	60 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:32 AM CDT Asset located in: Lake Worth, TX, USA
4154	John Deere 71 in Q/C Wheel Loader Forks S/N: PXEHSC0960438 Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:31 AM CDT Asset located in: Lake Worth, TX, USA	4162	54 in Wheel Loader Forks - Fits Cat 950H S/N: Not Available Usage: Not Available Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:32 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4163	51 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:32 AM CDT Asset located in: Lake Worth, TX, USA	4173	2014 Amadas RMH1000 98 in 3-Point Round Cotton Module - Round Hay Bale Stacker Bale Forks S/N: 520799 C/W: Located in Lane 56 Spot 2, Side Shift Usage: Not Available Notes: From the Fleet of Harvest Time Farms ; Stacker is Operational Lot closing time: Fri, Sep 18, 09:33 AM CDT Asset located in: Lake Worth, TX, USA
4165	Cat 113 in Q/C General Purpose Wheel Loader Bucket S/N: ARN03686 Usage: Not Available Lot closing time: Fri, Sep 18, 09:32 AM CDT Asset located in: Lake Worth, TX, USA	4174	DR Power Pro XL30 32 in Brush Cutter S/N: 3007342825 C/W: 2020 US EPA Label, Briggs & Stratton 656 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
4166	Cat 108 in 2275 lb Q/C General Purpose Wheel Loader Bucket S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:32 AM CDT Asset located in: Lake Worth, TX, USA	4175	2026 AGT TS-50X 50 in 3-Point Rotary Tiller (Unused) S/N: TS-50X26062801D C/W: Located in Lane 56 Spot 2, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
4167	102 in General Purpose Crawler Loader Bucket - Fits Cat 963 S/N: Not Available C/W: Located in Lane 72 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	4175A	RT84 84 in 3-Point Rotary Tiller S/N: Not Available C/W: Located in Lane 56 Spot 2, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
4167A	100 in General Purpose Crawler Loader Bucket - Fits Cat 963 S/N: Not Available C/W: Located in Lane 72 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	4176	Land Pride RGR1250 50 in 3-Point Rotary Tiller S/N: 1856383 C/W: Located in Lane 56 Spot 2, 540 PTO, Reverse-Tine Gear Drive w/Slip Clutch Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
4170	2026 LYALS ALSCTD6R 84 in Single BBL Multi Shank Crawler Tractor Ripper (Unused) S/N: ALS3565 Usage: Not Available Lot closing time: Fri, Sep 18, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	4177	MowerKing TAS-81 72 in 3-Point Rotary Tiller (Unused) S/N: TAS8125112201E C/W: Located in Lane 56 Spot 2, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
4171	Loftless 60 in Skid Steer Mulcher S/N: 93-1019 Usage: Not Available Lot closing time: Fri, Sep 18, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	4178A	Land Pride 3-Point Auger Attachment S/N: Not Available C/W: Located in Lane 56 Spot 2, 10 in Auger Bit Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA
4172	2007 FAE UML/SSL50 50 in Skid Steer Mulcher S/N: 07-239 Usage: Not Available Lot closing time: Fri, Sep 18, 09:33 AM CDT Asset located in: Lake Worth, TX, USA	4179	42 in 3-Point Auger Attachment S/N: 1A2210974 C/W: 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4179A	Land Pride 72 in 3 Point Hitch Box Blade S/N: 485523 C/W: Located in Lane 56 Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA	4187A	42 in 3-Point Seed Spreader S/N: Not Available C/W: Located in Lane 56 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4179B	King Kutter BB72YK 72 in 3 Point Hitch Box Blade S/N: 1001693590 C/W: Located in Lane 56 Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA	4188	MowerKing BX52G 3-Point Hitch Wood Chipper (Unused) S/N: BX52G23110201F C/W: Located in Lane 56 Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4180	Land Pride BB2572 72 in Box Blade S/N: 1389452 Usage: Not Available Lot closing time: Fri, Sep 18, 09:34 AM CDT Asset located in: Lake Worth, TX, USA	4189	Backhoe Hydraulic Breaker S/N: Not Available C/W: Equipment-from-a-Primoris-Services-Corp-company Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4181	John Deere HX15 15 ft Flex Wing Rotary Cutter S/N: Not Available C/W: Located in Lane 58 Spot 0, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 09:35 AM CDT Asset located in: Humble, TX, USA	4190	92 in Material Handling Arm S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4183	2026 AGT EF-M175 72 in 3-Point Flail Mower (Unused) S/N: EF-M17526062801D C/W: Located in Lane 56 Spot 2, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 09:35 AM CDT Asset located in: Lake Worth, TX, USA	4190A	2006 Star Industries 1320IR 144 in Telehandler Jib S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4184	Kubota M1066 72 in Front Loader Attachment S/N: 11700 C/W: Located in Lane 73 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 09:35 AM CDT Asset located in: Humble, TX, USA	4191	National Crane 30 ft Crane Boom S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4185	2026 Wolverine TR-26-02C Class 2 Tractors Quick Hitch (Unused) S/N: ZW00380 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:35 AM CDT Asset located in: Lake Worth, TX, USA	4192	Quantity of (15) 2026 FPM Ground Protection (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4186	2021 Hughes H-20 20 ft Stubble Roller S/N: 226883 C/W: Located in Lane 56 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 09:35 AM CDT Asset located in: Lake Worth, TX, USA	4193	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA
4187	72 in 3 Point Hitch Tractor Blade S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:36 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4194	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:37 AM CDT Asset located in: Lake Worth, TX, USA	4206	Quantity of Forks S/N: Not Available C/W: 3 Pairs of 48 in 1 Pair of 72 in 1 60 in Fork Usage: Not Available Lot closing time: Fri, Sep 18, 09:38 AM CDT Asset located in: Lake Worth, TX, USA
4195	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:37 AM CDT Asset located in: Lake Worth, TX, USA	4207	Quantity of (4) Pairs of 48 in Forks S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:39 AM CDT Asset located in: Lake Worth, TX, USA
4196	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:37 AM CDT Asset located in: Lake Worth, TX, USA	4211	Star Industries 1396C Fork Attachment S/N: 1176933 Usage: Not Available Lot closing time: Fri, Sep 18, 09:39 AM CDT Asset located in: Lake Worth, TX, USA
4197	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:37 AM CDT Asset located in: Lake Worth, TX, USA	4212	Quantity of (2) Sets of Fork Extensions S/N: Not Available C/W: (1) 8 ft (1) 6 ft Usage: Not Available Lot closing time: Fri, Sep 18, 09:39 AM CDT Asset located in: Lake Worth, TX, USA
4199	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:37 AM CDT Asset located in: Lake Worth, TX, USA	4214	DP Manufacturing Inc Hydraulic Truck Winch S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:40 AM CDT Asset located in: Lake Worth, TX, USA
4203	Quantity of (3) Overhaul Ball S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:38 AM CDT Asset located in: Lake Worth, TX, USA	4215	Quantity of (2) Hydraulic Braden Truck Winch's S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:40 AM CDT Asset located in: Lake Worth, TX, USA
4204	Caldwell 32-10 4/6 Spreader Bar S/N: 56135 Usage: Not Available Lot closing time: Fri, Sep 18, 09:38 AM CDT Asset located in: Lake Worth, TX, USA	4216	Braden Hydraulic Winch S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:40 AM CDT Asset located in: Lake Worth, TX, USA
4205	Quantity of (3) Hook Blocks & (1) Overhaul Ball S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:38 AM CDT Asset located in: Lake Worth, TX, USA	4217	Braden Hydraulic Winch S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:40 AM CDT Asset located in: Lake Worth, TX, USA
		4218	Quantity of (4) Pallets of Assorted Rubber Tracks S/N: Not Available C/W: (2) Pallets of 350x52.5, (2) Pallets of 450x100 Usage: Not Available Lot closing time: Fri, Sep 18, 09:40 AM CDT Asset located in: Lake Worth, TX, USA
		4219	Quantity of (1) Pallets of Skatewheel Conveyor Sections S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:40 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4220	Hagglunds CA 140 SAON.00 00 Hydraulic Motor S/N: K14P 02165 Usage: Not Available Lot closing time: Fri, Sep 18, 09:40 AM CDT Asset located in: Lake Worth, TX, USA	4231	Hydraulic Concrete Forms S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:42 AM CDT Asset located in: Lake Worth, TX, USA
4221	Radiator S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:41 AM CDT Asset located in: Lake Worth, TX, USA	4232	Compton Triple Roller Concrete Screed S/N: Not Available C/W: Located in Lane 56, 17 ft Screed, 4 Cylinder Diesel Engine, (1) 14 ft Frame, (1) 22 ft Frame, (1) 29 ft Frame, (5) Assorted Size Rollers Usage: 8,109 Hr Notes: Job Completion Fleet Realignment for Heavy Highway Joint Venture Lot closing time: Fri, Sep 18, 09:42 AM CDT Asset located in: Lake Worth, TX, USA
4221A	Pipe Handler S/N: Not Available C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:41 AM CDT Asset located in: Lake Worth, TX, USA	4233	Quantity of (3) 5 ft Screed Truss S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:42 AM CDT Asset located in: Lake Worth, TX, USA
4222	Wheel Loader Boom - Fits John Deere 824K S/N: Not Available C/W: Part #AT496524 Usage: Not Available Lot closing time: Fri, Sep 18, 09:41 AM CDT Asset located in: Lake Worth, TX, USA	4234	Honda 55-1-2G Hydraulic Power Pack S/N: 223836 C/W: 2015 US EPA Label, Honda GX 160 Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA
4223	Quantity of (4) Wheels S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:41 AM CDT Asset located in: Lake Worth, TX, USA	4235	2018 ChemGrout Grout Pump S/N: 1814912550051AGT Usage: Not Available Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA
4224	Triple S Dynamics S-40-60A Electric 36 in x 48 in Separator S/N: ST-2011-02 C/W: Marathon 10 hp 3 Phase Motor Usage: Not Available Lot closing time: Fri, Sep 18, 09:41 AM CDT Asset located in: Lake Worth, TX, USA	4236	ChemGrout Dual Grout Pump S/N: 15124345003C6A Usage: Not Available Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA
4226	Husqvarna FS520 Walk-Behind Saw S/N: Not Available C/W: 20 in Max Blade Diameter, 7.7 in Max Cutting Depth, Water Hose Connection, Manual Blade Raise / Lower, 2017 US EPA Label, Honda 2 Cylinder 688 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 09:41 AM CDT Asset located in: Lake Worth, TX, USA	4237	2020 Wacker Neuson RTSC3 Trench Compactor S/N: 24535241 C/W: Located in Lane 72 Spot 1, 2019 US EPA Label, Kohler 1.02 L Diesel Engine, 22 in Drums, Remote Control w/ Cord Usage: 627 Hr Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA
4229	Gar-Bro Concrete Bucket S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:42 AM CDT Asset located in: Lake Worth, TX, USA	4238	2020 Wacker Neuson RTSC3 Trench Compactor S/N: 24535293 C/W: Located in Lane 72 Spot 1, 2020 US EPA Label, Kohler 1.02 L Diesel Engine, 22 in Drums, Cordless Remote Control Usage: 748 Hr Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA
4230	Quantity of (3) Concrete Forms S/N: Not Available C/W: 8 ft Long 8 ft Wide Usage: Not Available Lot closing time: Fri, Sep 18, 09:42 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4239	2017 Wacker Neuson RTXSC3 Trench Compactor S/N: 24351062 C/W: Located in Lane 72, 2016 US EPA Label, Kubota D902-EF04 3 Cylinder 15.5 kW 0.89 L Diesel Engine, 22 in Drums, Remote Control w/ Cord, Articulated Steering Usage: 289 Hr Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA	4250	Quantity of (2) 2025 Kit Containers Steel 5 ft x 7 ft (1 in Thick) Steel Plates (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
4239A	Wacker Neuson RTKX-SC3 Trench Compactor S/N: Not Available C/W: Open Operator Station, Tier 4, 2018 US EPA Label, Kubota 3 Cylinder .89 L Diesel Engine, 22 in Drums, Remote Control w/ Cord Usage: Not Available Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA	4251	Quantity of (2) 2025 Kit Containers Steel 6 ft x 6 ft 3 in (1 in Thick) Steel Plates (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
4240	2015 Bomag BMP 8500 Trench Compactor S/N: 101720113243 C/W: Located in Lane 72 Spot 1, 2014 US EPA Label, Kubota D1005 3 Cylinder Diesel Engine, / 32 in Drums, Remote Control w/ Cord, Articulated Steering Usage: Not Available Lot closing time: Fri, Sep 18, 09:43 AM CDT Asset located in: Lake Worth, TX, USA	4252	Quantity of (2) 2025 Kit Containers Steel 6 ft x 7 ft 4 in (1 in Thick) Steel Plates (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
4242	Mustang LF88D Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin 1 Cylinder 196 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 09:44 AM CDT Asset located in: Lake Worth, TX, USA	4253	24 ft Truck Flatbed Body S/N: Not Available C/W: Located in Lane 75, Steel, 24 ft Body Length Usage: Not Available Lot closing time: Fri, Sep 18, 09:45 AM CDT Asset located in: Lake Worth, TX, USA
4247	Quantity of (2) 2026 SKLP 5 ft x 10 ft (.4 in Thick) Steel Plates (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:45 AM CDT Asset located in: Lake Worth, TX, USA	4254	Van Body S/N: 31873 C/W: Side Doors Usage: Not Available Lot closing time: Fri, Sep 18, 09:46 AM CDT Asset located in: Lake Worth, TX, USA
4248	Quantity of (2) 2025 Kit Containers Steel 5 ft x 7 ft 6 in (1 in Thick) Steel Plates (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 09:45 AM CDT Asset located in: Lake Worth, TX, USA	4255	2026 Neks Fifth Wheel Wrecker Attachment (Unused) S/N: 1607 Usage: Not Available Lot closing time: Fri, Sep 18, 09:46 AM CDT Asset located in: Lake Worth, TX, USA
4249	Quantity of (2) 2025 Kit Containers Steel 5 ft x 8 ft 4 in (1 in Thick) Steel Plates (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 09:45 AM CDT Asset located in: Lake Worth, TX, USA	4256	2026 Neks Fifth Wheel Wrecker Attachment (Unused) S/N: UL002 Usage: Not Available Lot closing time: Fri, Sep 18, 09:46 AM CDT Asset located in: Lake Worth, TX, USA
		4257	2026 Neks Fifth Wheel Wrecker Attachment (Unused) S/N: 1594 Usage: Not Available Lot closing time: Fri, Sep 18, 09:46 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4258	2025 Neks Fifth Wheel Wrecker Attachment (Unused) S/N: 002B Usage: Not Available Lot closing time: Fri, Sep 18, 09:46 AM CDT Asset located in: Lake Worth, TX, USA	4271	2000 gal Skid Mounted Steel Diesel Fuel Tank S/N: ORT2000177D Usage: Not Available Lot closing time: Fri, Sep 18, 09:48 AM CDT Asset located in: Humble, TX, USA
4259	2026 GIYI GY-TE780 Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC2607148 Usage: Not Available Lot closing time: Fri, Sep 18, 09:46 AM CDT Asset located in: Lake Worth, TX, USA	4283	2026 X-STAR 250GL 250 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Lot closing time: Fri, Sep 18, 09:50 AM CDT Asset located in: Lake Worth, TX, USA
4260	2026 GIYI GY-TE780 Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC2607145 C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 09:46 AM CDT Asset located in: Lake Worth, TX, USA	4284	2026 X-STAR 250GL 250 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Lot closing time: Fri, Sep 18, 09:50 AM CDT Asset located in: Lake Worth, TX, USA
4261	2026 GIYI GY-TE780 Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260795 Usage: Not Available Lot closing time: Fri, Sep 18, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	4284A	Quantity of (2) Fuel Tank S/N: Not Available C/W: (1)Delta Consolidated 465000 50 Gal (1) Better Built 36 Gal C/W Platform Usage: Not Available Lot closing time: Fri, Sep 18, 09:50 AM CDT Asset located in: Lake Worth, TX, USA
4262	2026 GIYI GY-TE780 Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260794 C/W: Located in Lane 75 Usage: Not Available Lot closing time: Fri, Sep 18, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	4290	Steel Hot Oil Tank S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:51 AM CDT Asset located in: Lake Worth, TX, USA
4263	2026 GIYI TE31 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260767 Usage: Not Available Lot closing time: Fri, Sep 18, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	4290A	Quantity of (6) Fruitland Truck Blower/Vacuum Pumps S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:51 AM CDT Asset located in: Lake Worth, TX, USA
4264	2026 GIYI TE31 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260768 Usage: Not Available Lot closing time: Fri, Sep 18, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	4291	Tuthill T850 LS Electric Cement Blower S/N: Not Available C/W: Located in Lane 56 Usage: Not Available Lot closing time: Fri, Sep 18, 09:51 AM CDT Asset located in: Lake Worth, TX, USA
4265	2026 PROMECH FW80 Fifth Wheel Wrecker Attachment (Unused) S/N: FWWA26278 Usage: Not Available Lot closing time: Fri, Sep 18, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	4292	Radiator S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:51 AM CDT Asset located in: Lake Worth, TX, USA
4266	PROMECH Hydraulic Fifth Wheel Wrecker Attachment S/N: FWWA26006 Usage: Not Available Lot closing time: Fri, Sep 18, 09:47 AM CDT Asset located in: Lake Worth, TX, USA	4293	Detroit Engine S/N: Not Available C/W: 6 Cylinder Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 09:51 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4294	Cat CX31-F600 Transmission S/N: PFW100346 Usage: Not Available Lot closing time: Fri, Sep 18, 09:52 AM CDT Asset located in: Lake Worth, TX, USA	4303	Quantity of (4) STA Rock service 17.5-25 Tires - Fits Loader S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:53 AM CDT Asset located in: Lake Worth, TX, USA
4295	Unknown or N/A Carraro DriveTech TLB2 CD Transmission S/N: 1003882 Usage: Not Available Lot closing time: Fri, Sep 18, 09:52 AM CDT Asset located in: Lake Worth, TX, USA	4304	Quantity of (3) American Contractors Tires S/N: Not Available C/W: All Tires with Wheels, (2) 17.5-25 E2/02 /L2, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:53 AM CDT Asset located in: Lake Worth, TX, USA
4296	Eaton Fuller EED-18F112C Truck Transmission S/N: Z0154659 Usage: Not Available Lot closing time: Fri, Sep 18, 09:52 AM CDT Asset located in: Lake Worth, TX, USA	4305	Quantity of (4) Solideal 14-00-24 Aperture Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:53 AM CDT Asset located in: Lake Worth, TX, USA
4298	Quantity of (2) John Deere 250/50R32 Tires - Fits Combine S/N: Not Available Usage: Not Available Notes: From the Fleet of Harvest Time Farms Lot closing time: Fri, Sep 18, 09:52 AM CDT Asset located in: Lake Worth, TX, USA	4306	Quantity of (4) Solid AEL Solid Air 14.00-24 Aperture Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:53 AM CDT Asset located in: Lake Worth, TX, USA
4299	Quantity of (2) Cooper 225/70R19.5 Tires S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 09:52 AM CDT Asset located in: Lake Worth, TX, USA	4307	Quantity of (4) E-Z Load 13.00-24/8.5 Aperture Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA
4300	Quantity of (4) Constellation Super Traction 17.5-25 Tires S/N: Not Available C/W: All Tires with Wheels, TA American, Tubeless Loader, Ine pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:52 AM CDT Asset located in: Lake Worth, TX, USA	4308	Quantity of (3) Tires S/N: Not Available C/W: All Tires with Wheels, Assorted Sizes, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA
4301	Quantity of (4) STA American Contractor 17.5-25 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:53 AM CDT Asset located in: Lake Worth, TX, USA	4309	Quantity of (2) 480/70R34 Tires S/N: Not Available Usage: Not Available Notes: From the Fleet of Harvest Time Farms Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA
4302	Quantity of (4) Dynamo DynaGrip 17.5-25 E2IG2IL Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:53 AM CDT Asset located in: Lake Worth, TX, USA	4310	Quantity of (16) 215/60-8 Tires S/N: Not Available C/W: All Tires with Wheels, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4311	Quantity of (16) 215/60-8 Tires S/N: Not Available C/W: All Tires with Wheels, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	4318	Quantity of (4) Sumitomo 11R22.5 146/143L4 Tires S/N: Not Available C/W: All Tires with Wheels, 11R22.5 146 /143L4 Semi Trailer Wheels and Tires Usage: Not Available Lot closing time: Fri, Sep 18, 09:55 AM CDT Asset located in: Lake Worth, TX, USA
4312	Quantity of (16) 215/60-8 Tires S/N: Not Available C/W: All Tires with Wheels, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	4319	Quantity of (2) Fortune 235/75R17.5 & (2) Super Steel RY103 Tires S/N: Not Available C/W: One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:55 AM CDT Asset located in: Lake Worth, TX, USA
4312A	Quantity of (16) 215/60-80 Tires S/N: Not Available C/W: All Tires with Wheels, One Pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	4320	Quantity of (4) Bridgestone 295/75R22.5 Tires S/N: Not Available C/W: All Tires with Aluminum Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:55 AM CDT Asset located in: Lake Worth, TX, USA
4313	Quantity of 4 Unknown or N/A Michelin XZE2 11R22.5 Radial Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:54 AM CDT Asset located in: Lake Worth, TX, USA	4321	Quantity of (4) Bridgestone 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:56 AM CDT Asset located in: Lake Worth, TX, USA
4314	Quantity of (4) Michelin XZE2 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:55 AM CDT Asset located in: Lake Worth, TX, USA	4322	Quantity of (4) Firestone 11R24.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:56 AM CDT Asset located in: Lake Worth, TX, USA
4315	Quantity of (4) Yokohama Super Steel RY103 255/70R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:55 AM CDT Asset located in: Lake Worth, TX, USA	4323	Quantity of (2) SteelMark ADP Radial 10.00R20 Tires S/N: Not Available C/W: All Tires with Wheels, (2) Tires, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:56 AM CDT Asset located in: Lake Worth, TX, USA
4316	Quantity of 4 Unknown or N/A Yokohama Super steel 793R 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:55 AM CDT Asset located in: Lake Worth, TX, USA	4324	Quantity of (4) Firestone F5560 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:56 AM CDT Asset located in: Lake Worth, TX, USA
4317	Quantity of (4) Yokohama Super Steel RY103 255/70R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:55 AM CDT Asset located in: Lake Worth, TX, USA	4325	Quantity of (4) Firestone F5560 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:56 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4326	Quantity of (4) Firestone F5560 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:56 AM CDT Asset located in: Lake Worth, TX, USA	4335	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202606003175 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
4327	Quantity of (4) Firestone F5560 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	4336	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202606003176 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
4328	Quantity of 4 Unknown or N/A Firestone F5560 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Lot closing time: Fri, Sep 18, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	4337	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202606003172 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
4329	Quantity of (4) Kelly KTSA 11R22.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	4338	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202606003174 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
4330	Quantity of (2) Ironman 235/75R17.5 Tires S/N: Not Available C/W: All Tires with Wheels, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	4339	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600455 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
4331	Quantity of Mixed (1) Ironman & (3) Westlake Tires S/N: Not Available C/W: All Tires with Wheels, 235/75R17.5 & 11R/22.5, One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	4340	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600455 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:58 AM CDT Asset located in: Lake Worth, TX, USA
4332	Quantity of ST215/60-8 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Lot closing time: Fri, Sep 18, 09:57 AM CDT Asset located in: Lake Worth, TX, USA	4341	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600452 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:59 AM CDT Asset located in: Lake Worth, TX, USA
4333	Quantity of ST215/60-8 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Lot closing time: Fri, Sep 18, 09:57 AM CDT Asset located in: Lake Worth, TX, USA		
4334	Quantity of ST215/60-8 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Lot closing time: Fri, Sep 18, 09:58 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4342	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600450 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:59 AM CDT Asset located in: Lake Worth, TX, USA	4349	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600461 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:00 AM CDT Asset located in: Lake Worth, TX, USA
4343	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600477 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:59 AM CDT Asset located in: Lake Worth, TX, USA	4350	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202500469 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:00 AM CDT Asset located in: Lake Worth, TX, USA
4344	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600475 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:59 AM CDT Asset located in: Lake Worth, TX, USA	4351	2026 AGT ATK-B1000 (Unused) S/N: GYSJE320903260261 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:00 AM CDT Asset located in: Lake Worth, TX, USA
4345	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600484 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:59 AM CDT Asset located in: Lake Worth, TX, USA	4352	2026 AGT ATK-B1000 (Unused) S/N: GYSJE320903260260 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:00 AM CDT Asset located in: Lake Worth, TX, USA
4346	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600481 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 09:59 AM CDT Asset located in: Lake Worth, TX, USA	4353	2026 AGT ATK-B1000 (Unused) S/N: GYSJE320903260263 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:00 AM CDT Asset located in: Lake Worth, TX, USA
4347	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202700455 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:00 AM CDT Asset located in: Lake Worth, TX, USA	4354	2026 AGT ATK-B1000 (Unused) S/N: GYSJE320903260262 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:01 AM CDT Asset located in: Lake Worth, TX, USA
4348	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: LQHRF202600466 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:00 AM CDT Asset located in: Lake Worth, TX, USA	4355	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK202606344 C/W: 110V, 2 HP Electric Motor ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:01 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4356	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATKTC242026060151 C/W: 110V, 2 HP Electric Motor ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:01 AM CDT Asset located in: Lake Worth, TX, USA	4367	2026 X-STAR 40 ft x 101 in Bridge (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
4357	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK202606343 C/W: 110V, 2 HP Electric Motor ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:01 AM CDT Asset located in: Lake Worth, TX, USA	4368	2026 X-STAR 40 ft x 101 in Bridge (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
4358	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATKTC242026060046 Usage: Not Available Lot closing time: Fri, Sep 18, 10:01 AM CDT Asset located in: Lake Worth, TX, USA	4369	2026 X-STAR 20 ft x 101 in Loading Ramp (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
4359	2026 AGT ATK-TC24 Automatic Tire Changer (Unused) S/N: ATK202604539 Usage: Not Available Lot closing time: Fri, Sep 18, 10:01 AM CDT Asset located in: Lake Worth, TX, USA	4370	2026 X-STAR 20 ft x 101 in Loading Ramp (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
4360	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK202604538 Usage: Not Available Lot closing time: Fri, Sep 18, 10:01 AM CDT Asset located in: Lake Worth, TX, USA	4371	2026 BLUESEA L100FT x W50 FTx H18FT Steel Frame Only Storage Building (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
4361	2026 SKLP SK-BTJ10 Tire Changer (Unused) S/N: BTJ10260411 Usage: Not Available Lot closing time: Fri, Sep 18, 10:02 AM CDT Asset located in: Lake Worth, TX, USA	4372	2026 KJ K5100 103 ft x 49 ft Prefabricated Metal Frame Storage Building (Unused) S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Prefabricated Metal Frame ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
4362	2026 SKLP SK-BTJ10 Tire Changer (Unused) S/N: 10BTJ260712 Usage: Not Available Lot closing time: Fri, Sep 18, 10:02 AM CDT Asset located in: Lake Worth, TX, USA	4373	2026 Hills Industrial 306022 30 ft x 60 ft x 22 ft Storage Building (Unused) S/N: Not Available C/W: Two crates Usage: Not Available Lot closing time: Fri, Sep 18, 10:03 AM CDT Asset located in: Lake Worth, TX, USA
4365	2026 AGT ATK-WB24A Wheel Balancer (Unused) S/N: ATKWB24A2026060025 Usage: Not Available Lot closing time: Fri, Sep 18, 10:02 AM CDT Asset located in: Lake Worth, TX, USA	4374	2026 KJ K0039 39 ft x 39 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:04 AM CDT Asset located in: Lake Worth, TX, USA
4366	Quantity of (5) John Bean Wheel Balancer S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:02 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4375	2026 KJ KS3040 30 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: 20 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:04 AM CDT Asset located in: Lake Worth, TX, USA	4382	2026 KJ K2223 23 ft x 22 ft Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: 13 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:05 AM CDT Asset located in: Lake Worth, TX, USA
4376	2026 KJ KS3040 30 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: Located in Lane 73, 20 ft Total Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:04 AM CDT Asset located in: Lake Worth, TX, USA	4383	2026 KJ K2223 23 ft x 22 ft Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: 13 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:05 AM CDT Asset located in: Lake Worth, TX, USA
4377	2026 KJ KS3040 30 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: 20 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:04 AM CDT Asset located in: Lake Worth, TX, USA	4384	2026 KJ K2223G 23 ft x 22 ft Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: 13 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:05 AM CDT Asset located in: Lake Worth, TX, USA
4378	2026 KJ KS3040 30 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: Located in Lane 73, 20 ft Total Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:04 AM CDT Asset located in: Lake Worth, TX, USA	4385	2026 KJ K2223G 23 ft x 22 ft Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: 13 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:05 AM CDT Asset located in: Lake Worth, TX, USA
4379	2026 KJ K2545G 25 ft x 45 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: 15 ft Total Height, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:04 AM CDT Asset located in: Lake Worth, TX, USA	4389	2026 KJ K4036 Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Container Shelter ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:06 AM CDT Asset located in: Humble, TX, USA
4381	2026 KJ K2545G 25 ft x 45 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 73, 15 ft Total Height, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:05 AM CDT Asset located in: Lake Worth, TX, USA	4390	2026 KJ K4036 Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Container Shelter ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:06 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
4391	2026 KJ KC2040 20 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:06 AM CDT Asset located in: Lake Worth, TX, USA	4399	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 73, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:07 AM CDT Asset located in: Lake Worth, TX, USA
4396	2026 KJ K4230G Triple Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:07 AM CDT Asset located in: Lake Worth, TX, USA	4400	2026 KJ K4525 Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:07 AM CDT Asset located in: Lake Worth, TX, USA
4397	2026 KJ K4230W Triple Garage Metal Storage Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:07 AM CDT Asset located in: Lake Worth, TX, USA	4401	2026 KJ K4525 Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:08 AM CDT Asset located in: Lake Worth, TX, USA
4397A	2026 KJ K4230W Triple Garage Metal Storage Shed (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:07 AM CDT Asset located in: Lake Worth, TX, USA	4402	2026 KJ K4525G Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:08 AM CDT Asset located in: Lake Worth, TX, USA
4398	2026 KJ K4230W Triple Garage Metal Storage Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:07 AM CDT Asset located in: Humble, TX, USA	4403	2026 KJ K3325 Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:08 AM CDT Asset located in: Lake Worth, TX, USA
4398A	2026 KJ K4525G Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 73, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:07 AM CDT Asset located in: Lake Worth, TX, USA	4404	2026 KJ K3325 Double Garage Metal (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:08 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4405	2026 KJ K3325 Double Garage Metal (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:08 AM CDT Asset located in: Lake Worth, TX, USA	4414	2026 KJ K3325G Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:10 AM CDT Asset located in: Lake Worth, TX, USA
4407	2026 KJ K3325G Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:09 AM CDT Asset located in: Lake Worth, TX, USA	4415	2026 KJ K2346 Metal Garage Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:10 AM CDT Asset located in: Lake Worth, TX, USA
4408	2026 SDL2533DGMS Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:09 AM CDT Asset located in: Lake Worth, TX, USA	4416	2026 KJ K2346 Metal Garage Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:10 AM CDT Asset located in: Lake Worth, TX, USA
4409	2026 SDL2533DGMS Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:09 AM CDT Asset located in: Lake Worth, TX, USA	4417	2026 KJ K2346 Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 73, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:10 AM CDT Asset located in: Lake Worth, TX, USA
4412	2026 KJ K3325G Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:09 AM CDT Asset located in: Lake Worth, TX, USA	4418	2026 SKLP SK-S2012 Shed (Unused) S/N: F16459 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:10 AM CDT Asset located in: Lake Worth, TX, USA
4413	2026 KJ K3325G Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:09 AM CDT Asset located in: Lake Worth, TX, USA	4419	2026 SKLP SK-S2012 Shed (Unused) S/N: F16461 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:10 AM CDT Asset located in: Lake Worth, TX, USA
		4420	2026 SKLP SK-S2012 Shed (Unused) S/N: F16458 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:10 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4421	2026 SKLP SK-S2012 Shed (Unused) S/N: F16462 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	4430	2026 SUNTOP SC1220 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:12 AM CDT Asset located in: Lake Worth, TX, USA
4422	2026 SKLP SK-S2012 Shed (Unused) S/N: F16460 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	4433	2026 SKLP SK-SC40 20 ft x 40 ft All-Steel Carport (Unused) S/N: F09559 C/W: 14 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:12 AM CDT Asset located in: Lake Worth, TX, USA
4423	2026 SKLP SK-S2012 Shed (Unused) S/N: F15731 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	4434	2026 SKLP SK-SC40 20 ft x 40 ft All-Steel Carport (Unused) S/N: F09558 C/W: 14 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:13 AM CDT Asset located in: Lake Worth, TX, USA
4424	2026 SKLP SK-S2012 Shed (Unused) S/N: F13462 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	4435	2026 SKLP SK-SC40 20 ft x 40 ft All-Steel Carport (Unused) S/N: F09560 C/W: 14 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:13 AM CDT Asset located in: Lake Worth, TX, USA
4425	2026 SKLP SK-S2012 12 ft x 20 ft Livestock Shelter (Unused) S/N: F13461 C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:11 AM CDT Asset located in: Lake Worth, TX, USA	4436	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F14738 Usage: Not Available Lot closing time: Fri, Sep 18, 10:13 AM CDT Asset located in: Lake Worth, TX, USA
4428	2026 KJ K1220 Metal Garage (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:12 AM CDT Asset located in: Lake Worth, TX, USA	4437	2026 SUNTOP SC2040B 20 ft x 40 ft Enclosed Carport (Unused) S/N: Not Available C/W: 14 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:13 AM CDT Asset located in: Lake Worth, TX, USA
4429	2026 SUNTOP SC1220 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:12 AM CDT Asset located in: Lake Worth, TX, USA	4438	2026 SUNTOP SC2040B 20 ft x 40 ft Enclosed Carport (Unused) S/N: Not Available C/W: 14 ft Total Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:13 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4439	2026 SUNTOP SC2040A 20 ft x 40 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:13 AM CDT Asset located in: Lake Worth, TX, USA	4446	2026 KJ K4020 20 ft x 40 ft (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:14 AM CDT Asset located in: Lake Worth, TX, USA
4440	2026 SUNTOP SC2040A 20 ft x 40 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:13 AM CDT Asset located in: Lake Worth, TX, USA	4447	2026 KJ K2030 20 ft x 30 ft Enclosed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:15 AM CDT Asset located in: Lake Worth, TX, USA
4441	2026 SDLC2040FT Multi-Use Metal Shed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:14 AM CDT Asset located in: Lake Worth, TX, USA	4448	2026 KJ K2030 20 ft x 30 ft Enclosed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:15 AM CDT Asset located in: Lake Worth, TX, USA
4442	2026 SDLC2040FT Multi-Use Metal Shed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:14 AM CDT Asset located in: Lake Worth, TX, USA	4449	2026 KJ K2030 20 ft x 30 ft Enclosed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:15 AM CDT Asset located in: Lake Worth, TX, USA
4443	2026 SDLC2040FT Multi-Use Metal Shed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:14 AM CDT Asset located in: Lake Worth, TX, USA	4450	2026 KJ K2030 20 ft x 30 ft Enclosed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:15 AM CDT Asset located in: Lake Worth, TX, USA
4444	2026 SDLC2040FT Multi-Use Metal Shed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:14 AM CDT Asset located in: Lake Worth, TX, USA	4451	2026 KJ K2030 20 ft x 30 ft Enclosed (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:15 AM CDT Asset located in: Lake Worth, TX, USA
4445	2026 KJ K4020 20 ft x 40 ft (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:14 AM CDT Asset located in: Lake Worth, TX, USA	4453	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:15 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4454	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:16 AM CDT Asset located in: Lake Worth, TX, USA	4461	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:17 AM CDT Asset located in: Lake Worth, TX, USA
4455	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:16 AM CDT Asset located in: Lake Worth, TX, USA	4462	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:17 AM CDT Asset located in: Lake Worth, TX, USA
4456	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:16 AM CDT Asset located in: Lake Worth, TX, USA	4464	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:17 AM CDT Asset located in: Lake Worth, TX, USA
4457	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:16 AM CDT Asset located in: Lake Worth, TX, USA	4472	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:18 AM CDT Asset located in: Lake Worth, TX, USA
4458	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:16 AM CDT Asset located in: Lake Worth, TX, USA	4473	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:18 AM CDT Asset located in: Lake Worth, TX, USA
4460	2026 SDLC2030FT 20 ft x 30 ft Enclosed Sidewalls Carport (Unused) S/N: Not Available C/W: 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:16 AM CDT Asset located in: Lake Worth, TX, USA	4474	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:19 AM CDT Asset located in: Lake Worth, TX, USA
		4475	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:19 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4477	2026 SKLP SK-ZP20 0 m x 0 ft All-Steel Carport (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:19 AM CDT Asset located in: Lake Worth, TX, USA	4486	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:20 AM CDT Asset located in: Lake Worth, TX, USA
4478	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Sidewalls Carport (Unused) S/N: F15730 Usage: Not Available Lot closing time: Fri, Sep 18, 10:19 AM CDT Asset located in: Lake Worth, TX, USA	4487	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:21 AM CDT Asset located in: Lake Worth, TX, USA
4479	2026 SKLP SK-ZP20 20 ft x 20 ft All-Steel Carport (Unused) S/N: F15728 Usage: Not Available Lot closing time: Fri, Sep 18, 10:19 AM CDT Asset located in: Lake Worth, TX, USA	4488	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:21 AM CDT Asset located in: Lake Worth, TX, USA
4480	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Sidewalls Carport (Unused) S/N: F15729 Usage: Not Available Lot closing time: Fri, Sep 18, 10:19 AM CDT Asset located in: Lake Worth, TX, USA	4489	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:21 AM CDT Asset located in: Lake Worth, TX, USA
4481	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F14718 Usage: Not Available Lot closing time: Fri, Sep 18, 10:20 AM CDT Asset located in: Lake Worth, TX, USA	4490	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:21 AM CDT Asset located in: Lake Worth, TX, USA
4482	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F14735 Usage: Not Available Lot closing time: Fri, Sep 18, 10:20 AM CDT Asset located in: Lake Worth, TX, USA	4491	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:21 AM CDT Asset located in: Lake Worth, TX, USA
4483	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F14736 Usage: Not Available Lot closing time: Fri, Sep 18, 10:20 AM CDT Asset located in: Lake Worth, TX, USA	4492	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:21 AM CDT Asset located in: Lake Worth, TX, USA
4484	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F14719 Usage: Not Available Lot closing time: Fri, Sep 18, 10:20 AM CDT Asset located in: Lake Worth, TX, USA	4493	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:21 AM CDT Asset located in: Lake Worth, TX, USA
4485	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F15714 Usage: Not Available Lot closing time: Fri, Sep 18, 10:20 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4494	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	4502	2026 SUNTOP SC1120 11 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:23 AM CDT Asset located in: Lake Worth, TX, USA
4495	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	4503	2026 KJ K1119 11 ft x 19 ft (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:23 AM CDT Asset located in: Lake Worth, TX, USA
4496	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	4507	2026 SUNTOP SC2712 27 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
4497	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	4508	2026 SUNTOP SC2712 27 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
4498	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	4509	2026 SUNTOP SC2712 27 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
4499	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	4510	2026 SUNTOP SC2712 27 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
4500	2026 SUNTOP SC1120 11 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:22 AM CDT Asset located in: Lake Worth, TX, USA	4511	2026 SUNTOP SC2712 27 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:24 AM CDT Asset located in: Lake Worth, TX, USA
4501	2026 SUNTOP SC1120 11 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:23 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4512	2026 KJ K2512 12 ft x 25 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:24 AM CDT Asset located in: Lake Worth, TX, USA	4518	2026 KJ K1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:25 AM CDT Asset located in: Lake Worth, TX, USA
4513	2026 SUNTOP SC2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:24 AM CDT Asset located in: Lake Worth, TX, USA	4519	2026 SKLP SK-LS20 11 ft x 20 ft Metal Livestock Shelter (Unused) S/N: F14732 C/W: Located in Lane 74 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 10:25 AM CDT Asset located in: Lake Worth, TX, USA
4514	2026 SUNTOP SC2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:25 AM CDT Asset located in: Lake Worth, TX, USA	4520	2026 SKLP SK-LS20 11 ft x 20 ft Metal Livestock Shelter (Unused) S/N: F14731 C/W: Located in Lane 74 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 10:25 AM CDT Asset located in: Lake Worth, TX, USA
4515	2026 SUNTOP SC2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:25 AM CDT Asset located in: Lake Worth, TX, USA	4521	2026 SKLP SK-LS20 11ft x 20 ft Metal Livestock Shelter (Unused) S/N: F14733 C/W: Located in Lane 74 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 10:26 AM CDT Asset located in: Lake Worth, TX, USA
4516	2026 SUNTOP SC2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:25 AM CDT Asset located in: Lake Worth, TX, USA	4522	2026 SDLGM1220F 12 ft x 20 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:26 AM CDT Asset located in: Lake Worth, TX, USA
4517	2026 KJ K1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:25 AM CDT Asset located in: Lake Worth, TX, USA	4523	2026 SDLGM1220F 12 ft x 20 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:26 AM CDT Asset located in: Lake Worth, TX, USA
		4524	2026 KJ K2039 39 ft x 20 ft Module Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:26 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4525	2026 KJ K2424 24 ft x 24 ft Module Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:26 AM CDT Asset located in: Lake Worth, TX, USA	4531	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:27 AM CDT Asset located in: Lake Worth, TX, USA
4526	2026 KJ K2424 24 ft x 24 ft Module Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:26 AM CDT Asset located in: Lake Worth, TX, USA	4532	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:27 AM CDT Asset located in: Lake Worth, TX, USA
4527	2026 KJ K2424 24 ft x 24 ft Module Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	4533	2026 KJ K4080 80 ft x 40 ft Prefabricated Metal Frame Storage Building (Unused) S/N: Not Available C/W: Located in Lane 74 Spot 1, Quantity of (2) Boxes - Builds (1) Prefabricated Metal Frame ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:27 AM CDT Asset located in: Lake Worth, TX, USA
4528	2026 KJ K2424 24 ft x 24 ft Module Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	4534	2026 KJ K4080 80 ft x 40 ft Prefabricated Metal Frame Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Prefabricated Metal Frame ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:28 AM CDT Asset located in: Lake Worth, TX, USA
4529	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	4535	2026 KJ K1522 7 ft 4 in x 5 ft x 8 ft Portable Toilet (Unused) S/N: Not Available C/W: (1) Sinks, (1) Showers, (1) Toilets, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:28 AM CDT Asset located in: Lake Worth, TX, USA
4530	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:27 AM CDT Asset located in: Lake Worth, TX, USA	4536	2026 KJ K1522 7 ft 4 in x 5 ft x 8 ft Portable Toilet (Unused) S/N: Not Available C/W: (1) Sinks, (1) Showers, (1) Toilets, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:28 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4537	2026 SDLMT Skid-Mounted Portable Toilet (Unused) S/N: 2026001 C/W: Located in Lane 78 Spot 1, (1) Sinks, (1) Showers, (1) Toilets, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:28 AM CDT Asset located in: Lake Worth, TX, USA	4553	2025 Kit Containers TB4096 40 in x 96 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:30 AM CDT Asset located in: Lake Worth, TX, USA
4538	2026 SDLMT 7 ft x 6 ft 8 in Portable Toilet (Unused) S/N: 20260017 C/W: (1) Sinks, (1) Showers, (1) Toilets, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:28 AM CDT Asset located in: Lake Worth, TX, USA	4554	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:31 AM CDT Asset located in: Lake Worth, TX, USA
4541	Portable Toilet S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:29 AM CDT Asset located in: Lake Worth, TX, USA	4555	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:31 AM CDT Asset located in: Lake Worth, TX, USA
4542	KJ K1522 7 ft 4 in x 5 ft Portable Portable Toilet S/N: Not Available C/W: Sink,Toilet,Stand Up Shower Usage: Not Available Lot closing time: Fri, Sep 18, 10:29 AM CDT Asset located in: Lake Worth, TX, USA	4556	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:31 AM CDT Asset located in: Lake Worth, TX, USA
4543	KJ K1522 7 ft 4 in x 5 ft Portable Portable Toilet S/N: Not Available C/W: Sink,Toilet,Stand Up Shower Usage: Not Available Lot closing time: Fri, Sep 18, 10:29 AM CDT Asset located in: Lake Worth, TX, USA	4557	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:31 AM CDT Asset located in: Lake Worth, TX, USA
4550	2025 Kit Containers TB4096 40 in x 96 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:30 AM CDT Asset located in: Lake Worth, TX, USA	4558	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:31 AM CDT Asset located in: Lake Worth, TX, USA
4551	2025 Kit Containers TB4096 40 in x 96 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:30 AM CDT Asset located in: Lake Worth, TX, USA	4559	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:31 AM CDT Asset located in: Lake Worth, TX, USA
4552	2025 Kit Containers TB4096 40 in x 96 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:30 AM CDT Asset located in: Lake Worth, TX, USA	4560	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:31 AM CDT Asset located in: Lake Worth, TX, USA
		4561	2025 Kit Containers WB-90-243 90 in x 26 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:32 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4567	2025 Kit Containers ST-57 29 in x 57 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	4574	Quantity of (32) 2026 SUNTOP S0608-32 8 ft x 6 ft Powder Coated Wrought Iron Fencing (Unused) S/N: Not Available C/W: (32) Fence Panels, (33) Post w /Connectors ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
4568	2025 Kit Containers ST-57 29 in x 57 in Steel Workbench (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	4575	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
4569	2026 Neks 12 ft Livestock Squeeze Chute (Unused) S/N: TG002 Usage: Not Available Lot closing time: Fri, Sep 18, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	4576	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
4570	Quantity of (56) 2026 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 75 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	4577	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
4571	Quantity of (30) 2026 KJ K0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	4578	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
4572	Quantity of (30) 2026 KJ K0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	4579	2026 SKLP SK-N20 10 ft x 7 ft Fencing (Unused) S/N: F15713 Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA
4573	Quantity of (32) 2026 SUNTOP S0608-32 8 ft x 6 ft Powder Coated Wrought Iron Fencing (Unused) S/N: Not Available C/W: (32) Fence Panels, (33) Post w /Connectors ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:33 AM CDT Asset located in: Lake Worth, TX, USA	4579A	2026 KJ K1640 Galvanized Farm Fencing (Unused) S/N: Not Available C/W: Located in Lane 74, Quantity of (10) Rolls 5 ft x 164 ft, Total Length 1640 ft Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4579B	2026 KJ K1640 Galvanized Farm Fencing (Unused) S/N: Not Available C/W: Quantity of (10) Rolls 5 ft x 164 ft, Total Length 1640 ft Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA	4586	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available C/W: (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:35 AM CDT Asset located in: Lake Worth, TX, USA
4580	Quantity of Betafence 8 ft x 6 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:34 AM CDT Asset located in: Lake Worth, TX, USA	4587	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available C/W: (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
4581	Quantity of Betafence 8 ft x 6 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:35 AM CDT Asset located in: Lake Worth, TX, USA	4588	Quantity of 2026 KJ K0520 66 ft x 5 ft Hot-dip Galvanized Welded Wire Mesh Fencing (Unused) S/N: Not Available C/W: Located in Lane 74, Quantity of (21) Rolls 5 ft x 66 ft, Total Length 1386 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
4582	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available C/W: (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:35 AM CDT Asset located in: Lake Worth, TX, USA	4589	Quantity of (33) 2026 Skyway SFS33-330TF 10 ft x 7 ft Wrought Iron Site Fence (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
4583	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available C/W: (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:35 AM CDT Asset located in: Lake Worth, TX, USA	4590	Quantity of (33) 2026 Skyway SFS33-330TF 10 ft x 7 ft Wrought Iron Site Fence (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
4584	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available C/W: (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:35 AM CDT Asset located in: Lake Worth, TX, USA	4591	Quantity of (33) 2026 Skyway F10 10 ft x 7 ft Wrought Iron Site Fence (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:36 AM CDT Asset located in: Lake Worth, TX, USA
4585	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available C/W: (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:35 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4592	Quantity of (33) 2026 Skyway SFS33-330TF 10 ft x 7 ft Wrought Iron Site Fence (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:36 AM CDT Asset located in: Lake Worth, TX, USA	4598	Quantity of (12) 2026 KJ K1222 86 in x 47 in Polyethylene Board Roadbed Protection Pad (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:37 AM CDT Asset located in: Lake Worth, TX, USA
4593	Quantity of (32) 2026 SUNTOP S0610-32 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:36 AM CDT Asset located in: Lake Worth, TX, USA	4599	Quantity of (12) 2026 KJ K1222 86 in x 47 in Polyethylene Board Roadbed Protection Pad (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:37 AM CDT Asset located in: Lake Worth, TX, USA
4594	Quantity of (32) 2026 SUNTOP S0610-32 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:37 AM CDT Asset located in: Lake Worth, TX, USA	4600	Quantity of (12) 2026 KJ K1222 86 in x 47 in Polyethylene Board Roadbed Protection Pad (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:37 AM CDT Asset located in: Lake Worth, TX, USA
4595	Quantity of (32) 2026 SUNTOP S0610-32 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:37 AM CDT Asset located in: Lake Worth, TX, USA	4601	Quantity of (12) 2026 KJ K1222 86 in x 47 in Polyethylene Board Roadbed Protection Pad (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:38 AM CDT Asset located in: Lake Worth, TX, USA
4596	Quantity of (32) 2026 SUNTOP S0610-32 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:37 AM CDT Asset located in: Lake Worth, TX, USA	4602	Quantity of (15) 2026 LYALS ALSRM1 48 in x 94 in Ground Protection Mats (Unused) S/N: R-FW260819003 C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:38 AM CDT Asset located in: Lake Worth, TX, USA
4597	Quantity of (12) 2026 KJ K1222 86 in x 47 in Polyethylene Board Roadbed Protection Pad (Unused) S/N: Not Available C/W: Located in Lane 74, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:37 AM CDT Asset located in: Lake Worth, TX, USA	4603	Quantity of (15) 2026 LYALS ALSRM1 48 in x 94 in Ground Protection Mats (Unused) S/N: R-FW260819002 C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:38 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4604	Quantity of (15) 2026 LYALS ALSRM1 48 in x 94 in Ground Protection Mats (Unused) S/N: R-FW260819001 C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:38 AM CDT Asset located in: Lake Worth, TX, USA	4612	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:39 AM CDT Asset located in: Lake Worth, TX, USA
4605	Quantity of (12) 2026 SKLP SK-LJB12 47 in x 95 in (Unused) S/N: F16663 C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:38 AM CDT Asset located in: Lake Worth, TX, USA	4613	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:39 AM CDT Asset located in: Lake Worth, TX, USA
4606	Quantity of (12) 2026 SKLP SK-LJB12 47 in x 95 in (Unused) S/N: F1661 C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:38 AM CDT Asset located in: Lake Worth, TX, USA	4614	Quantity of (6) 2026 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:40 AM CDT Asset located in: Lake Worth, TX, USA
4607	Quantity of (12) 2026 SKLP SK-LJB12 47 in x 95 in (Unused) S/N: F16662 C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:39 AM CDT Asset located in: Lake Worth, TX, USA	4615	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:40 AM CDT Asset located in: Lake Worth, TX, USA
4608	Quantity of (250) 2026 KJ K2250 28 in Traffic Cones (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:39 AM CDT Asset located in: Lake Worth, TX, USA	4616	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:40 AM CDT Asset located in: Lake Worth, TX, USA
4610	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 73, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:39 AM CDT Asset located in: Lake Worth, TX, USA	4617	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:40 AM CDT Asset located in: Lake Worth, TX, USA
4611	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 73, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:39 AM CDT Asset located in: Lake Worth, TX, USA	4618	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:40 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4619	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:40 AM CDT Asset located in: Lake Worth, TX, USA	4631	2026 AGT YC32-G Band Saw Portable Sawmill (Unused) S/N: YC-32G202605299 Usage: Not Available Lot closing time: Fri, Sep 18, 10:42 AM CDT Asset located in: Lake Worth, TX, USA
4620	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:40 AM CDT Asset located in: Lake Worth, TX, USA	4632	2026 AGT YC32-G Band Saw Portable Sawmill (Unused) S/N: YC-32G202605448 Usage: Not Available Lot closing time: Fri, Sep 18, 10:42 AM CDT Asset located in: Lake Worth, TX, USA
4621	2026 SKLP SK-HLM20 20 ft Bi-Parting Driveway Gate (Unused) S/N: F15710 Usage: Not Available Lot closing time: Fri, Sep 18, 10:41 AM CDT Asset located in: Lake Worth, TX, USA	4633	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202606005 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:42 AM CDT Asset located in: Lake Worth, TX, USA
4622	2026 SKLP SK-HLM20 20 ft Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:41 AM CDT Asset located in: Lake Worth, TX, USA	4634	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202606003 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:43 AM CDT Asset located in: Lake Worth, TX, USA
4623	2026 SKLP SK-HLM20 20 ft Bi-Parting Driveway Gate (Unused) S/N: F15709 Usage: Not Available Lot closing time: Fri, Sep 18, 10:41 AM CDT Asset located in: Lake Worth, TX, USA	4635	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202605391 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:43 AM CDT Asset located in: Lake Worth, TX, USA
4624	2026 SKLP SK-HLM20 20 ft Bi-Parting Driveway Gate (Unused) S/N: F15711 Usage: Not Available Lot closing time: Fri, Sep 18, 10:41 AM CDT Asset located in: Lake Worth, TX, USA	4636	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202605389 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:43 AM CDT Asset located in: Lake Worth, TX, USA
4625	Quantity of (4) 2026 SUNTOP S0714-4 14 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:41 AM CDT Asset located in: Lake Worth, TX, USA	4637	2026 AGT YC32-G Band Saw Portable Sawmill (Unused) S/N: YC-32G202605430 Usage: Not Available Lot closing time: Fri, Sep 18, 10:43 AM CDT Asset located in: Lake Worth, TX, USA
4630	Scotchman DO8514-20M Electric 85 ton Ironworker Machine S/N: 1013M0204 Usage: Not Available Lot closing time: Fri, Sep 18, 10:42 AM CDT Asset located in: Lake Worth, TX, USA	4638	2026 AGT YC32-G Band Saw Portable Sawmill (Unused) S/N: YC-32G202605492 Usage: Not Available Lot closing time: Fri, Sep 18, 10:43 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4639	Rockwell 14 Band Saw S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:43 AM CDT Asset located in: Lake Worth, TX, USA	4650	2026 HDMS6 Heavy Duty Metal Shelving (Unused) S/N: Not Available C/W: 6 Sections, 800 lb Shelf Capacity ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:45 AM CDT Asset located in: Lake Worth, TX, USA
4640	2026 SDLBBS800 Basketball Hoop (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:43 AM CDT Asset located in: Lake Worth, TX, USA	4651	2026 HDMS6 Heavy Duty Metal Shelving (Unused) S/N: Not Available C/W: 6 Sections, 800 lb Shelf Capacity ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:45 AM CDT Asset located in: Lake Worth, TX, USA
4641	2026 SDLBBS800 Basketball Hoop (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:44 AM CDT Asset located in: Lake Worth, TX, USA	4652	2026 HDMS6 2 ft x 40 ft Heavy Duty Metal Shelving (Unused) S/N: Not Available C/W: 6 Sections, 800 lb Shelf Capacity ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:45 AM CDT Asset located in: Lake Worth, TX, USA
4642	2026 SDLBBS800 Basketball Hoop (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:44 AM CDT Asset located in: Lake Worth, TX, USA	4653	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: F13578 Usage: Not Available Lot closing time: Fri, Sep 18, 10:45 AM CDT Asset located in: Lake Worth, TX, USA
4643	2026 SDLBBS800 Basketball Hoop (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:44 AM CDT Asset located in: Lake Worth, TX, USA	4654	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: F06176 Usage: Not Available Lot closing time: Fri, Sep 18, 10:46 AM CDT Asset located in: Lake Worth, TX, USA
4644	Cincinnati Fan RBE - 17 Fan S/N: 1205684 C/W: Siemens 25 hp Electric Motor Usage: Not Available Lot closing time: Fri, Sep 18, 10:44 AM CDT Asset located in: Lake Worth, TX, USA	4659	Quantity of (64) 2x12x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber Lumber (Unused) S/N: Not Available C/W: Two bundles Usage: Not Available Lot closing time: Fri, Sep 18, 10:46 AM CDT Asset located in: Lake Worth, TX, USA
4645	2016 Caps PCTV-500TN-0NN0NN-5E5-0-N 500 ton Air Conditioner S/N: 15F-0664-2-002 C/W: Located in Lane 25 Spot 0, 460 V Usage: Not Available Lot closing time: Fri, Sep 18, 10:44 AM CDT Asset located in: Humble, TX, USA	4660	Quantity of (96) 2x12x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber Lumber (Unused) S/N: Not Available C/W: Three Bundles Usage: Not Available Lot closing time: Fri, Sep 18, 10:46 AM CDT Asset located in: Lake Worth, TX, USA
4647	2026 KJ K015 Pallet Racking (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:45 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4661	Quantity of (96) 2x12x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber Lumber (Unused) S/N: Not Available C/W: Three Bundles Usage: Not Available Lot closing time: Fri, Sep 18, 10:47 AM CDT Asset located in: Lake Worth, TX, USA	4670	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:48 AM CDT Asset located in: Lake Worth, TX, USA
4662	Quantity of (96) 2x12x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber Lumber (Unused) S/N: Not Available C/W: Three Bundles Usage: Not Available Lot closing time: Fri, Sep 18, 10:47 AM CDT Asset located in: Lake Worth, TX, USA	4671	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:48 AM CDT Asset located in: Lake Worth, TX, USA
4663	Quantity of (64) 2 in x 12 in x 18 ft SYP #2 BTR Lumber (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:47 AM CDT Asset located in: Lake Worth, TX, USA	4672	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:48 AM CDT Asset located in: Lake Worth, TX, USA
4664	Quantity of (2) Bundles of Lumber S/N: Not Available C/W: (1) Bundle of 1 in x 10 in x 16 ft, (1) Bundle of Assorted Size Usage: Not Available Lot closing time: Fri, Sep 18, 10:47 AM CDT Asset located in: Lake Worth, TX, USA	4673	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:48 AM CDT Asset located in: Lake Worth, TX, USA
4665	Quantity of Pine Lumber S/N: Not Available C/W: Assorted Size, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:47 AM CDT Asset located in: Lake Worth, TX, USA	4674	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:49 AM CDT Asset located in: Lake Worth, TX, USA
4666	Quantity of Knotty Pine Lumber S/N: Not Available C/W: Assorted Size, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:47 AM CDT Asset located in: Lake Worth, TX, USA	4675	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:49 AM CDT Asset located in: Lake Worth, TX, USA
4667	Quantity of Assorted Lumber S/N: Not Available C/W: Assorted Size, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:48 AM CDT Asset located in: Lake Worth, TX, USA	4676	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:49 AM CDT Asset located in: Lake Worth, TX, USA
4668	Quantity of (100) 2026 KJ K0311 Galvalume Corrugated Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:48 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4677	Quantity of (150) 2026 KJ K084 12 ft Galvalume Corrugated Steel Sheets (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:49 AM CDT Asset located in: Lake Worth, TX, USA	4684	Quantity of (200) 2026 SUNTOP S840C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:50 AM CDT Asset located in: Lake Worth, TX, USA
4678	Quantity of (200) 2026 SUNTOP S2134C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:49 AM CDT Asset located in: Lake Worth, TX, USA	4685	Quantity of (200) 2026 SUNTOP S840C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:50 AM CDT Asset located in: Lake Worth, TX, USA
4679	Quantity of (200) 2026 SUNTOP S2134C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:49 AM CDT Asset located in: Lake Worth, TX, USA	4686	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Steel Sheets (Unused) S/N: F06175 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:50 AM CDT Asset located in: Lake Worth, TX, USA
4680	Quantity of (200) 2026 SUNTOP S3048B-200 Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:49 AM CDT Asset located in: Lake Worth, TX, USA	4687	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Steel Sheets (Unused) S/N: F06172 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:51 AM CDT Asset located in: Lake Worth, TX, USA
4681	Quantity of (200) 2026 SUNTOP S3048B-200 Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:50 AM CDT Asset located in: Lake Worth, TX, USA	4688	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Steel Sheets (Unused) S/N: F06173 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:51 AM CDT Asset located in: Lake Worth, TX, USA
4682	Quantity of (200) 2026 SUNTOP S3048C Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:50 AM CDT Asset located in: Lake Worth, TX, USA	4689	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Steel Sheets (Unused) S/N: F06174 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:51 AM CDT Asset located in: Lake Worth, TX, USA
4683	Quantity of (200) 2026 SUNTOP S3048C Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 10:50 AM CDT Asset located in: Lake Worth, TX, USA	4690	Quantity of (50) Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:51 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4691	Quantity of (50) 2026 SKLP SK-XH50 3 Ft x 10 Ft Galvalume Steel Sheets (Unused) S/N: F13480 C/W: One Bumdle Usage: Not Available Lot closing time: Fri, Sep 18, 10:51 AM CDT Asset located in: Lake Worth, TX, USA	4699	Quantity of (50) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:52 AM CDT Asset located in: Lake Worth, TX, USA
4692	Quantity of (50) 2026 SKLP SK-XH50 3 Ft x 10 Ft Galvalume Steel Sheets (Unused) S/N: F13481 C/W: One Bumdle Usage: Not Available Lot closing time: Fri, Sep 18, 10:51 AM CDT Asset located in: Lake Worth, TX, USA	4700	Quantity of (50) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:52 AM CDT Asset located in: Lake Worth, TX, USA
4693	Quantity of (50) 2026 SKLP SK-XH50 3 Ft x 10 Ft Galvalume Steel Sheets (Unused) S/N: F13482 C/W: One Bumdle Usage: Not Available Lot closing time: Fri, Sep 18, 10:51 AM CDT Asset located in: Lake Worth, TX, USA	4701	Quantity of (50) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA
4694	Quantity of (50) 2026 SKLP SK-XH50 10 ft Galvalume Steel Siding Roofing (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:52 AM CDT Asset located in: Oklahoma City, OK, USA	4702	Quantity of (50) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA
4695	Quantity of (50) SKLP SK-XH50 10 ft Galvalume Steel Siding Roofing (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:52 AM CDT Asset located in: Oklahoma City, OK, USA	4703	Quantity of (50) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA
4696	Quantity of (50) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:52 AM CDT Asset located in: Lake Worth, TX, USA	4704	Quantity of (19) Pallets of 48 in x 96 in Polyiso Insulation S/N: Not Available C/W: Five Stacks Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA
4697	Quantity of (75) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:52 AM CDT Asset located in: Lake Worth, TX, USA	4705	Quantity of (7) Pallets of 48 in x 96 in Polyiso Insulation S/N: Not Available C/W: Two Stacks Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA
4698	Quantity of (50) 2025 Kit Containers 12 ft Steel R Panel (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:52 AM CDT Asset located in: Lake Worth, TX, USA	4706	Quantity of (16) Pallets of 48 in x 96 in Polyiso Insulation S/N: Not Available C/W: Five Stacks Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4706A	Quantity of (8) Pallets of 48 in x 96 in Polyiso Insulation S/N: Not Available C/W: Four Stacks Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA	4713	Quantity of (6) GE TPR5616NRHC 1600 Amp Breaker S/N: V30366 C/W: One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 10:54 AM CDT Asset located in: Lake Worth, TX, USA
4706B	Quantity of (8) Pallets of 48 in x 96 in Polyiso Insulation S/N: Not Available C/W: Four Stacks Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA	4714	Quantity of (6) GE 1600 Amp Breakers S/N: Not Available C/W: One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
4706C	Quantity of (8) Pallets of 48 in x 96 in Polyiso Insulation S/N: Not Available C/W: Four Stacks Usage: Not Available Lot closing time: Fri, Sep 18, 10:53 AM CDT Asset located in: Lake Worth, TX, USA	4715	Quantity of (7) GE 1600 Amp Breakers S/N: Not Available C/W: One pallet Usage: Not Available Lot closing time: Fri, Sep 18, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
4707	Quantity of (4) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8 ft 3 in x 4 ft x 4 ft 4 in Usage: Not Available Lot closing time: Fri, Sep 18, 10:54 AM CDT Asset located in: Midland, TX, USA	4716	Quantity of (14) 3-1/2 in Drill Pipe S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
4708	Quantity of (4) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 10:54 AM CDT Asset located in: Midland, TX, USA	4717	Quantity of (2) 18 ft Pipe Stands S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
4709	Quantity of (4) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 10:54 AM CDT Asset located in: Midland, TX, USA	4718	Quantity of (2) 18 ft Steel Saw Horses/Pipe Racks (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
4710	Quantity of (4) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 10:54 AM CDT Asset located in: Midland, TX, USA	4719	Quantity of (6) 6 in x 6 in x 3/16 in x 17 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
4711	Quantity of (4) Pallets of Polyiso Insulation S/N: Not Available C/W: Each pallet is 8 ft 3 in x 4 ft x 4 ft 4 in Usage: Not Available Lot closing time: Fri, Sep 18, 10:54 AM CDT Asset located in: Midland, TX, USA	4720	Quantity of 6 in x 6 in x 3/16 in x 12 ft Square Tubing (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 10:55 AM CDT Asset located in: Lake Worth, TX, USA
4712	Quantity of (4) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8 ft 3 in x 4 ft x 4 ft 4 in Usage: Not Available Lot closing time: Fri, Sep 18, 10:54 AM CDT Asset located in: Midland, TX, USA	4721	Quantity of (6) 6 in x 6 in x 3/16 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:56 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4722	Quantity of (6) 6 in x 6 in x 3/16 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:56 AM CDT Asset located in: Lake Worth, TX, USA	4730	Quantity of (6) 6 in x 6 in x 3/16 in x 12 ft Square Tubing (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:57 AM CDT Asset located in: Lake Worth, TX, USA
4723	Quantity of (6) 6 in x 6 in x 3/16 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:56 AM CDT Asset located in: Lake Worth, TX, USA	4731	Quantity of (6) 6 in x 6 in x 3/16 in x 10 ft Square Tubing (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:57 AM CDT Asset located in: Lake Worth, TX, USA
4724	Quantity of (6) 6 in x 6 in x 3/16 in x 12 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:56 AM CDT Asset located in: Lake Worth, TX, USA	4732	Quantity of (6) 6 in x 6 in x 3/16 in x 8 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:57 AM CDT Asset located in: Lake Worth, TX, USA
4725	Quantity of (6) 6 in x 6 in x 3/16 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:56 AM CDT Asset located in: Lake Worth, TX, USA	4733	Quantity of (9) 5 in x 4 in x 19 ft 11 GA Rectangle Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:57 AM CDT Asset located in: Lake Worth, TX, USA
4726	Quantity of (6) 6 in x 6 in x 3/16 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:56 AM CDT Asset located in: Lake Worth, TX, USA	4734	Quantity of (9) 5 in x 4 in x 20 ft 11 GA Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:58 AM CDT Asset located in: Lake Worth, TX, USA
4727	Quantity of (6) 6 in x 6 in x 3/16 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:57 AM CDT Asset located in: Lake Worth, TX, USA	4735	Quantity of (9) 5 in x 4 in x 20 ft 11 GA Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:58 AM CDT Asset located in: Lake Worth, TX, USA
4728	Quantity of (6) 6 in x 6 in x 3/16 in x 8 ft Square Tubing (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:57 AM CDT Asset located in: Lake Worth, TX, USA	4736	Quantity of (9) 5 in x 4 in x 19 ft 11 GA Rectangle Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:58 AM CDT Asset located in: Lake Worth, TX, USA
4729	Quantity of (6) 6 in x 6 in x 3/16 in x 10 ft Square Tubing (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:57 AM CDT Asset located in: Lake Worth, TX, USA	4737	Quantity of (9) 5 in x 4 in x 19 ft 11 GA Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:58 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4738	Quantity of (9) 5 in x 4 in x 20 ft 11 GA Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:58 AM CDT Asset located in: Lake Worth, TX, USA	4746	Quantity of (4) Kit Containers 2 in x 2 in x 23 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:59 AM CDT Asset located in: Lake Worth, TX, USA
4739	Quantity of (9) Kit Containers 3 in x 3 in x 19 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:58 AM CDT Asset located in: Lake Worth, TX, USA	4747	Quantity of (12) Kit Containers 2 in x 2 in x 23 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
4740	Quantity of (9) Kit Containers 3 in x 3 in x 18 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:58 AM CDT Asset located in: Lake Worth, TX, USA	4748	Quantity of (12) Kit Containers 2 in x 2 in x 22 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
4741	Quantity of (4) Kit Containers 2 1/2 in x 2 1/2 in x 24 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:59 AM CDT Asset located in: Lake Worth, TX, USA	4749	Quantity of (8) Kit Containers 2 in x 2 in x 22 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
4742	Quantity of (9) Kit Containers 2 1/2 in x 2 1/2 in x 23 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:59 AM CDT Asset located in: Lake Worth, TX, USA	4750	Quantity of (3) Kit Containers 2 in x 2 in x 19 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
4743	Quantity of (9) Kit Containers 2 1/2 in x 2 1/2 in x 23 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:59 AM CDT Asset located in: Lake Worth, TX, USA	4751	Quantity of (12) Kit Containers 2 in x 2 in x 19 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
4744	Quantity of (9) Kit Containers 2 1/2 in x 2 1/2 in x 22 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:59 AM CDT Asset located in: Lake Worth, TX, USA	4752	Quantity of (16) Kit Containers 2 in x 2 in x 18 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:00 AM CDT Asset located in: Lake Worth, TX, USA
4745	Quantity of (9) Kit Containers 2 1/2 in x 2 1/2 in x 22 ft Square Tubing (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 10:59 AM CDT Asset located in: Lake Worth, TX, USA	4753	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:00 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4754	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	4763	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:02 AM CDT Asset located in: Lake Worth, TX, USA
4755	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	4764	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:02 AM CDT Asset located in: Lake Worth, TX, USA
4756	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	4765	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:02 AM CDT Asset located in: Lake Worth, TX, USA
4757	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	4766	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:02 AM CDT Asset located in: Lake Worth, TX, USA
4758	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	4767	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:03 AM CDT Asset located in: Lake Worth, TX, USA
4759	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	4768	Quantity of Corten Weathering Steel Forms S/N: Not Available C/W: Assortment of Sizes Usage: Not Available Lot closing time: Fri, Sep 18, 11:03 AM CDT Asset located in: Lake Worth, TX, USA
4760	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:01 AM CDT Asset located in: Lake Worth, TX, USA	4770	2026 KJ AM4000P Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, 250 gal Water Supply, Hose, Spray Wand, 1 Cylinder 429 cc Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:03 AM CDT Asset located in: Lake Worth, TX, USA
4761	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:02 AM CDT Asset located in: Lake Worth, TX, USA		
4762	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:02 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4771	2026 KJ AM4000P Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, 250 gal Water Supply, Hose, Spray Wand, 1 Cylinder 429 cc Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:03 AM CDT Asset located in: Lake Worth, TX, USA	4778	2026 AC60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601263331 C/W: Located in Lane 76, 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:04 AM CDT Asset located in: Lake Worth, TX, USA
4772	2026 KJ AM4000 Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 420 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:03 AM CDT Asset located in: Lake Worth, TX, USA	4779	2026 S60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601263326 C/W: 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:04 AM CDT Asset located in: Lake Worth, TX, USA
4773	2026 KJ AM4000 Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 420 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:03 AM CDT Asset located in: Lake Worth, TX, USA	4780	2026 AC60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601225357 C/W: Located in Lane 76, 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:04 AM CDT Asset located in: Lake Worth, TX, USA
4774	2026 AGT HPW3000-1 Pressure Washer (Unused) S/N: HPW3000-126062802D C/W: 3000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 6.5 hp 208 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:04 AM CDT Asset located in: Lake Worth, TX, USA	4781	2026 AC60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601225333 C/W: Located in Lane 76, 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:05 AM CDT Asset located in: Lake Worth, TX, USA
4775	2026 AGT HPW3000-1 Pressure Washer (Unused) S/N: HPW3000-126062801D C/W: 3000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 6.5 hp 208 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:04 AM CDT Asset located in: Lake Worth, TX, USA	4782	2026 S60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601263346 C/W: 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:05 AM CDT Asset located in: Lake Worth, TX, USA
4777	2026 AC60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601263344 C/W: Located in Lane 76, 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:04 AM CDT Asset located in: Lake Worth, TX, USA	4783	2026 AC60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601225366 C/W: Located in Lane 76, 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:05 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4784	2026 S60GAL Skid-Mounted 60 gal Air Compressor (Unused) S/N: A2601363339 C/W: 1 Cylinder Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:05 AM CDT Asset located in: Lake Worth, TX, USA	4794	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26062502B C/W: Located in Lane 73, 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:07 AM CDT Asset located in: Lake Worth, TX, USA
4785	2026 KJ AMAC60 18.5 cfm Skid-Mounted 60 gal Air Compressor (Unused) S/N: Not Available C/W: 175 psi Working Pressure, 1 Cylinder 420 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:05 AM CDT Asset located in: Lake Worth, TX, USA	4797	2026 Topcon RL-H5B Rotary Laser Level (Unused) S/N: 1B027299 C/W: w/ Receiver, Batteries and 5 Year Warranty Usage: Not Available Lot closing time: Fri, Sep 18, 11:07 AM CDT Asset located in: Lake Worth, TX, USA
4786	2026 KJ AMAC40 14.5 cfm Skid-Mounted 40 gal Air Compressor (Unused) S/N: Not Available C/W: 12.5 bar Working Pressure, 1 Cylinder 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:05 AM CDT Asset located in: Lake Worth, TX, USA	4800	Quantity of 2026 KJ KG43 Chains & Ratchet Binders (Unused) S/N: Not Available C/W: (5) 3/4 in Ratchet Binders, (10) 10 mm / 3/8 in x 10 ft Chains ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:07 AM CDT Asset located in: Lake Worth, TX, USA
4791	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26062801D C/W: Located in Lane 73, 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:06 AM CDT Asset located in: Lake Worth, TX, USA	4801	Quantity of 2026 KJ KG43 Chains & Ratchet Binders (Unused) S/N: Not Available C/W: (5) 3/4 in Ratchet Binders, (10) 10 mm / 3/8 in x 10 ft Chains ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:08 AM CDT Asset located in: Lake Worth, TX, USA
4792	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26062802D C/W: Located in Lane 73, 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:06 AM CDT Asset located in: Lake Worth, TX, USA	4802	Quantity of 2026 KJ KG43 Chains & Ratchet Binders (Unused) S/N: Not Available C/W: (5) 3/4 in Ratchet Binders, (10) 10 mm / 3/8 in x 10 ft Chains ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:08 AM CDT Asset located in: Lake Worth, TX, USA
4793	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26062501B C/W: Located in Lane 73, 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:06 AM CDT Asset located in: Lake Worth, TX, USA	4803	Quantity of 2026 KJ KG43 Chains & Ratchet Binders (Unused) S/N: Not Available C/W: (5) 3/4 in Ratchet Binders, (10) 10 mm / 3/8 in x 10 ft Chains ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:08 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4804	2026 KJ K1824 18 ft x 24 ft Basketball Court w /Adjustable Backboard (Unused) S/N: Not Available C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:08 AM CDT Asset located in: Lake Worth, TX, USA	4814	Quantity of (2) Soft Drink Vending Machine S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:10 AM CDT Asset located in: Lake Worth, TX, USA
4806	2026 SKLP SK-S13 Massage Chair (Unused) S/N: Not Available C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 11:08 AM CDT Asset located in: Lake Worth, TX, USA	4815	Park Industries Fastback Electric Flat-Edge Polisher S/N: 114659 C/W: Baldor 1 hp 3 Phase Motor, extensions Usage: Not Available Lot closing time: Fri, Sep 18, 11:10 AM CDT Asset located in: Lake Worth, TX, USA
4807	2026 SKLP SK-S13 Massage Chair (Unused) S/N: Not Available C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 11:09 AM CDT Asset located in: Lake Worth, TX, USA	4816	Quantity of (3) Pallets of Solar Panels (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:10 AM CDT Asset located in: Lake Worth, TX, USA
4808	2026 SKLP SK-S13 Massage Chair (Unused) S/N: Not Available C/W: Located in Lane 76 Usage: Not Available Lot closing time: Fri, Sep 18, 11:09 AM CDT Asset located in: Lake Worth, TX, USA	4817	Quantity of Checkers GD5X75-ST Cable Protectors S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:10 AM CDT Asset located in: Lake Worth, TX, USA
4809	2026 SKLP SK-S13 Massage chair (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:09 AM CDT Asset located in: Lake Worth, TX, USA	4818	Platform S/N: Not Available C/W: 800 lb Usage: Not Available Lot closing time: Fri, Sep 18, 11:10 AM CDT Asset located in: Lake Worth, TX, USA
4810	2026 SKLP SK-S13 Massage chair (Unused) S/N: E84739 Usage: Not Available Lot closing time: Fri, Sep 18, 11:09 AM CDT Asset located in: Lake Worth, TX, USA	4819	Kelly Bar S/N: Not Available C/W: 19 in wide x 209 in long Usage: Not Available Lot closing time: Fri, Sep 18, 11:10 AM CDT Asset located in: Lake Worth, TX, USA
4811	2026 SKLP SK-SYLJ100 Hand-Use Hydraulic Track Pin Press Machine (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:09 AM CDT Asset located in: Lake Worth, TX, USA	4820	Delta Wood Shaper S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:10 AM CDT Asset located in: Lake Worth, TX, USA
4812	2026 SKLP SK-SYLJ100 Hand-Use Hydraulic Track Pin Press Machine (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:09 AM CDT Asset located in: Lake Worth, TX, USA	4820A	46 in Router Table S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:11 AM CDT Asset located in: Lake Worth, TX, USA
4813	2026 SKLP SK-SYLJ100 Hand-Use Hydraulic Track Pin Press Machine (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:09 AM CDT Asset located in: Lake Worth, TX, USA	4821	Dremel 1800 Scroll Saw S/N: 585251103 Usage: Not Available Lot closing time: Fri, Sep 18, 11:11 AM CDT Asset located in: Lake Worth, TX, USA
		4822	Central Machinery 599 6 in Jointer S/N: 65006444 Usage: Not Available Lot closing time: Fri, Sep 18, 11:11 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4823	Enkohs Drill Press S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:11 AM CDT Asset located in: Lake Worth, TX, USA	4837	2026 SDLOOL SL-LM1000Q Remote Control Crawler Lawn Mower (Unused) S/N: 1000QYGCJ2607113 C/W: Hydrostatic Drive, 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:13 AM CDT Asset located in: Lake Worth, TX, USA
4824	Hitachi C10FCE2 Miter Saw S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:11 AM CDT Asset located in: Lake Worth, TX, USA	4838	2026 SDLOOL SL800 Remote Control Crawler Lawn Mower (Unused) S/N: 800YS2606184 C/W: Hydrostatic Drive, 20 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:13 AM CDT Asset located in: Lake Worth, TX, USA
4830	Ridgid TS3612 Table Saw S/N: 02338P0292 C/W: Fence, Push Stick Usage: Not Available Lot closing time: Fri, Sep 18, 11:12 AM CDT Asset located in: Lake Worth, TX, USA	4839	2026 SDLOOL SL800 Remote Control Crawler Lawn Mower (Unused) S/N: 800YS2606185 C/W: Hydrostatic Drive, 20 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:13 AM CDT Asset located in: Lake Worth, TX, USA
4831	Rockwell 34-338 Table Saw S/N: EZ6698 Usage: Not Available Lot closing time: Fri, Sep 18, 11:12 AM CDT Asset located in: Lake Worth, TX, USA	4840	2026 SDLOOL SL800 Remote Control Crawler Lawn Mower (Unused) S/N: 800YS260701 C/W: Located in Lane 101 Spot 1, Hydrostatic Drive, 20 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:13 AM CDT Asset located in: Lake Worth, TX, USA
4832	Jet EHVS-80CS Horizontal/Vertical Edge Sander S/N: 6062851 Usage: Not Available Lot closing time: Fri, Sep 18, 11:12 AM CDT Asset located in: Lake Worth, TX, USA	4840A	Country Clipper 1842KAT-A125 Zero-Turn Lawn Mower (Unused) S/N: 25037005 C/W: Located in Lane 78 Spot 1, Hydrostatic Drive, 2023 US EPA Label, 13x5.00 Front Tires, 18x8.50-8 Rear Tires, Country Clipper 42 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:14 AM CDT Asset located in: Lake Worth, TX, USA
4833	Central Machinery 6 in Belt & 9 in Disc Sander S/N: 03139600850 Usage: Not Available Lot closing time: Fri, Sep 18, 11:12 AM CDT Asset located in: Lake Worth, TX, USA	4841	Toro 74274 Zero-Turn Lawn Mower S/N: 404539413 C/W: Located in Lane 78 Spot 1, Hydrostatic Drive, 2018 US EPA Label, 13x6.50x6 Front Tires, 24x12.00x12 Rear Tires, 72 in Mower Usage: 105 Hr Lot closing time: Fri, Sep 18, 11:14 AM CDT Asset located in: Lake Worth, TX, USA
4834	2026 SDLOOL SL-LM1000Q Remote Control Crawler Lawn Mower (Unused) S/N: 1000QYGCJ2607115 C/W: Hydrostatic Drive, 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:13 AM CDT Asset located in: Lake Worth, TX, USA	4842	2026 SKLP SK-QSJ32 Walk-Behind Snow Sweeper (Unused) S/N: SFQSJ260714 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 11:14 AM CDT Asset located in: Lake Worth, TX, USA
4835	2026 SDLOOL SL-LM1000Q Remote Control Crawler Lawn Mower (Unused) S/N: 1000QYGCJ260771 C/W: Hydrostatic Drive, 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:13 AM CDT Asset located in: Lake Worth, TX, USA		
4836	2026 SDLOOL SL-LM1000Q Remote Control Crawler Lawn Mower (Unused) S/N: 1000QYGCJ2607114 C/W: 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 11:13 AM CDT Asset located in: Lake Worth, TX, USA		

Lot #	Details	Lot #	Details
4843	2026 SKLP SK-QSJ32 Walk-Behind Snow Sweeper (Unused) S/N: SFQSJ260722 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 11:14 AM CDT Asset located in: Lake Worth, TX, USA	4853	2026 SKLP SK-E48 E-Bikes Bicycle (Unused) S/N: F14826 Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Lake Worth, TX, USA
4844	2026 SKLP SK-QSJ32 Walk-Behind Snow Sweeper (Unused) S/N: SFQSJ260721 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 11:14 AM CDT Asset located in: Lake Worth, TX, USA	4853A	Quantity of (7) Kit Containers CFX-90 Livestock Feeder S/N: Not Available C/W: Located in Lane 74 Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Lake Worth, TX, USA
4845	Quantity of (20) Auto Darkening Welding Helmets (Unused) S/N: Not Available C/W: One Box Usage: Not Available Lot closing time: Fri, Sep 18, 11:14 AM CDT Asset located in: Lake Worth, TX, USA	4853B	Quantity of (7) Kit Containers CFX-90 Livestock Feeder S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Lake Worth, TX, USA
4846	Quantity of (4) Coxreels SLP-5100 Hose Reels S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:14 AM CDT Asset located in: Lake Worth, TX, USA	4853C	Quantity of (7) Kit Containers CFX-90 Livestock Feeder S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA
4847	25 GPM Fuel Pump (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Humble, TX, USA	4854	2025 Kit Containers AR500ATBOAR Shooting Target (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA
4848	50 ft. Diesel Fuel Reel w/ HD 12v pump (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Lake Worth, TX, USA	4855	2025 Kit Containers AR500ATBOAR Shooting Target (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA
4849	Quantity of (10) 14 in Premium Diamond Blades (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Lake Worth, TX, USA	4856	2025 Kit Containers AR500ATDEER Shooting Target (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA
4850	Quantity of (5) 25 ft 800 amp Extra HD Booster Cables (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Lake Worth, TX, USA	4857	2025 Kit Containers AR500ATDEER Shooting Target (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA
4851	2026 SKLP SL-L450 Off-Road Electric Bicycle (Unused) S/N: F06171 Usage: Not Available Lot closing time: Fri, Sep 18, 11:15 AM CDT Asset located in: Lake Worth, TX, USA	4858	Quantity of (2) 2025 Kit Containers DT14 Targets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4859	Quantity of (2) 2025 Kit Containers DT14 Targets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA	4866	KitContainers 2YFT-SDH 5 ft 8 in 2 cyd Self-Dumping Hopper (Unused) S/N: D21G1111 C/W: 5 ft 8 in Long x 4 ft 3 in Wide x 3 ft 10 in High Usage: Not Available Lot closing time: Fri, Sep 18, 11:17 AM CDT Asset located in: Lake Worth, TX, USA
4860	KitContainers 2YFT-SDH 5 ft 8 in 2 cyd Self-Dumping Hopper (Unused) S/N: D29G1103 C/W: 5 ft 8 in Long x 4 ft 3 in Wide x 3 ft 10 in High Usage: Not Available Lot closing time: Fri, Sep 18, 11:16 AM CDT Asset located in: Lake Worth, TX, USA	4867	Kit Containers 2YFT-SDH Self-Dumping Hopper S/N: D23C1112 Usage: Not Available Lot closing time: Fri, Sep 18, 11:18 AM CDT Asset located in: Lake Worth, TX, USA
4861	KitContainers 2YFT-SDH 5 ft 8 in 2 cyd Self-Dumping Hopper (Unused) S/N: D02H1100 C/W: 5 ft 8 in Long x 4 ft 3 in Wide x 3 ft 10 in High Usage: Not Available Lot closing time: Fri, Sep 18, 11:17 AM CDT Asset located in: Lake Worth, TX, USA	4868	Kit Containers SMLD Self-Dumping Hopper S/N: D23V1109 Usage: Not Available Lot closing time: Fri, Sep 18, 11:18 AM CDT Asset located in: Lake Worth, TX, USA
4862	KitContainers 2YFT-SDH 5 ft 8 in 2 cyd Self-Dumping Hopper (Unused) S/N: D06H1103 C/W: 5 ft 8 in Long x 4 ft 3 in Wide x 3 ft 10 in High Usage: Not Available Lot closing time: Fri, Sep 18, 11:17 AM CDT Asset located in: Lake Worth, TX, USA	4871	Snyder Flowmaster Plastic Hopper S/N: 2303382096 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:18 AM CDT Asset located in: Lake Worth, TX, USA
4863	KitContainers 2YFT-SDH 5 ft 8 in 2 cyd Self-Dumping Hopper (Unused) S/N: D07H1107 C/W: 5 ft 8 in Long x 4 ft 3 in Wide x 3 ft 10 in High Usage: Not Available Lot closing time: Fri, Sep 18, 11:17 AM CDT Asset located in: Lake Worth, TX, USA	4872	Snyder Flowmaster Plastic Hopper S/N: 2209322709 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:18 AM CDT Asset located in: Lake Worth, TX, USA
4864	KitContainers 2YFT-SDH 5 ft 8 in 2 cyd Self-Dumping Hopper (Unused) S/N: D21G1102 C/W: 5 ft 8 in Long x 4 ft 3 in Wide x 3 ft 10 in High Usage: Not Available Lot closing time: Fri, Sep 18, 11:17 AM CDT Asset located in: Lake Worth, TX, USA	4874	Snyder Flowmaster Plastic Hopper S/N: 2107388136 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:19 AM CDT Asset located in: Lake Worth, TX, USA
4865	KitContainers 2YFT-SDH 5 ft 8 in 2 cyd Self-Dumping Hopper (Unused) S/N: D05H1105 C/W: 5 ft 8 in Long x 4 ft 3 in Wide x 3 ft 10 in High Usage: Not Available Lot closing time: Fri, Sep 18, 11:17 AM CDT Asset located in: Lake Worth, TX, USA	4875	Snyder Flowmaster Plastic Hopper S/N: 2407329412 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:19 AM CDT Asset located in: Lake Worth, TX, USA
		4876	Snyder Flowmaster Plastic Hopper S/N: 2407329618 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:19 AM CDT Asset located in: Lake Worth, TX, USA
		4877	Snyder Flowmaster Plastic Hopper S/N: 2209322706 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:19 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4878	Snyder Flowmaster Plastic Hopper S/N: 2005339812 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:19 AM CDT Asset located in: Lake Worth, TX, USA	4887	Snyder Flowmaster Plastic Hopper S/N: 2410339393 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
4879	Snyder Flowmaster Plastic Hopper S/N: 2209322697 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:19 AM CDT Asset located in: Lake Worth, TX, USA	4888	Snyder Flowmaster Plastic Hopper S/N: 2105316140 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
4880	Snyder Flowmaster Plastic Hopper S/N: 2203822707 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:19 AM CDT Asset located in: Lake Worth, TX, USA	4889	Snyder Flowmaster Plastic Hopper S/N: 220032702 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
4881	Snyder Flowmaster Plastic Hopper S/N: 2105316142 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	4890	Snyder Flowmaster Plastic Hopper S/N: 2007344790 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
4882	Snyder Flowmaster Plastic Hopper S/N: 2005339154 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	4891	Snyder Flowmaster Plastic Hopper S/N: 2107388137 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
4883	Snyder Flowmaster Plastic Hopper S/N: 2008375747 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	4892	Snyder Flowmaster Plastic Hopper S/N: 2005338186 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
4884	Snyder Flowmaster Plastic Hopper S/N: 2208322705 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	4893	Snyder Flowmaster Plastic Hopper S/N: 2105316155 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:21 AM CDT Asset located in: Lake Worth, TX, USA
4885	Snyder Flowmaster Plastic Hopper S/N: 2210326685 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	4894	Snyder Flowmaster Plastic Hopper S/N: 2007344789 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:22 AM CDT Asset located in: Lake Worth, TX, USA
4886	Snyder Flowmaster Plastic Hopper S/N: 2407329849 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:20 AM CDT Asset located in: Lake Worth, TX, USA	4895	Snyder Flowmaster Plastic Hopper S/N: 2007344784 C/W: 80 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:22 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4896	Snyder Flowmaster Plastic Hopper S/N: 2105316151 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:22 AM CDT Asset located in: Lake Worth, TX, USA	4905	Snyder Flowmaster Plastic Hopper S/N: 2105316161 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:23 AM CDT Asset located in: Lake Worth, TX, USA
4897	Snyder Flowmaster Plastic Hopper S/N: 2005338189 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:22 AM CDT Asset located in: Lake Worth, TX, USA	4906	Snyder Flowmaster Plastic Hopper S/N: 2407329604 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:23 AM CDT Asset located in: Lake Worth, TX, USA
4898	Snyder Flowmaster Plastic Hopper S/N: 2005339810 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:22 AM CDT Asset located in: Lake Worth, TX, USA	4907	Snyder Flowmaster Plastic Hopper S/N: 2105316141 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:24 AM CDT Asset located in: Lake Worth, TX, USA
4899	Snyder Flowmaster Plastic Hopper S/N: 2209322708 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:22 AM CDT Asset located in: Lake Worth, TX, USA	4908	Snyder Flowmaster Plastic Hopper S/N: 2105316149 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:24 AM CDT Asset located in: Lake Worth, TX, USA
4900	Snyder Flowmaster Plastic Hopper S/N: 2005338170 C/W: 65 Cubic Ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:22 AM CDT Asset located in: Lake Worth, TX, USA	4909	Snyder Flowmaster Plastic Hopper S/N: 2209322700 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:24 AM CDT Asset located in: Lake Worth, TX, USA
4901	Snyder Flowmaster Plastic Hopper S/N: 2105316153 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:23 AM CDT Asset located in: Lake Worth, TX, USA	4910	Snyder Flowmaster Plastic Hopper S/N: 2303382095 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:24 AM CDT Asset located in: Lake Worth, TX, USA
4902	Snyder Flowmaster Plastic Hopper S/N: 2209322711 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:23 AM CDT Asset located in: Lake Worth, TX, USA	4911	Snyder Flowmaster Plastic Hopper S/N: 2005338183 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:24 AM CDT Asset located in: Lake Worth, TX, USA
4903	Snyder Flowmaster Plastic Hopper S/N: 2005338180 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:23 AM CDT Asset located in: Lake Worth, TX, USA	4913	2026 40 ft High Cube Multi-Door Storage Container S/N: LSJU1702492 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:24 AM CDT Asset located in: Lake Worth, TX, USA
4904	Snyder Flowmaster Plastic Hopper S/N: 2005338178 C/W: 65 Cubic ft Usage: Not Available Lot closing time: Fri, Sep 18, 11:23 AM CDT Asset located in: Lake Worth, TX, USA	4914	2026 40 ft High Cube Storage Container S/N: HPCU4936009 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:25 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4915	2026 40 ft High Cube Storage Container S/N: HPCU4936020 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:25 AM CDT Asset located in: Lake Worth, TX, USA	4924	2026 40 ft High Cube Multi-Door Storage Container S/N: DPXU1689271 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:26 AM CDT Asset located in: Lake Worth, TX, USA
4916	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4200777 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:25 AM CDT Asset located in: Lake Worth, TX, USA	4925	2026 40 ft High Cube Multi-Door Storage Container S/N: ZNCU4012102 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:26 AM CDT Asset located in: Lake Worth, TX, USA
4917	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4199260 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:25 AM CDT Asset located in: Lake Worth, TX, USA	4926	2026 40 ft High Cube Multi-Door Storage Container S/N: BTNU4056708 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:26 AM CDT Asset located in: Lake Worth, TX, USA
4919	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2582006 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:25 AM CDT Asset located in: Lake Worth, TX, USA	4928	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015653 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:27 AM CDT Asset located in: Lake Worth, TX, USA
4920	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2582114 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:25 AM CDT Asset located in: Lake Worth, TX, USA	4929	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015355 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:27 AM CDT Asset located in: Lake Worth, TX, USA
4921	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2584462 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:26 AM CDT Asset located in: Lake Worth, TX, USA	4930	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU0253758 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:27 AM CDT Asset located in: Lake Worth, TX, USA
4922	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2582120 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:26 AM CDT Asset located in: Lake Worth, TX, USA	4931	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU0253362 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:27 AM CDT Asset located in: Lake Worth, TX, USA
4923	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4199531 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:26 AM CDT Asset located in: Lake Worth, TX, USA	4932	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU0253629 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:27 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4933	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU0254137 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:27 AM CDT Asset located in: Lake Worth, TX, USA	4940	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2560347 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA
4935	2026 40 ft High Cube Multi-Door Storage Container (Unused) S/N: AARU2021585 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	4941	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2560310 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA
4936	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015632 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	4941	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2560310 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA
4937	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015951 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	4943	40 ft High Cube Multi-Door Storage Container S/N: CICU4761386 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA
4938	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5013223 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	4943	40 ft High Cube Multi-Door Storage Container S/N: CICU4761386 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA
4939	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2560352 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	4944	40 ft High Cube Multi-Door Storage Container S/N: DFCU1699189 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA
4939	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2560352 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	4944	40 ft High Cube Multi-Door Storage Container S/N: DFCU1699189 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA
4940	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2560347 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:28 AM CDT Asset located in: Lake Worth, TX, USA	4945	40 ft High Cube Storage Container S/N: LCGU8332870 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA
		4945	40 ft High Cube Storage Container S/N: LCGU8332870 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4946	40 ft High Cube Storage Container S/N: LCGU8320057 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA	4950	2004 40 ft High Cube Storage Container S/N: TRLU6929422 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Humble, TX, USA
4946	40 ft High Cube Storage Container S/N: LCGU8320057 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:29 AM CDT Asset located in: Lake Worth, TX, USA	4953	40 ft Standard Open Top Storage Container S/N: TCLU7016500 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Humble, TX, USA
4947	40 ft High Cube Storage Container S/N: LCGU8334507 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Lake Worth, TX, USA	4953	40 ft Standard Open Top Storage Container S/N: TCLU7016500 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Humble, TX, USA
4947	40 ft High Cube Storage Container S/N: LCGU8334507 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Lake Worth, TX, USA	4956	40 ft High Cube Storage Container S/N: TCNU8065338 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA
4948	40 ft High Cube Storage Container S/N: LCGU8335709 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Lake Worth, TX, USA	4956	40 ft High Cube Storage Container S/N: TCNU8065338 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA
4948	40 ft High Cube Storage Container S/N: LCGU8335709 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Lake Worth, TX, USA	4958	40 ft Standard Open Top Storage Container S/N: TCLU7025755 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA
4949	40 ft Standard Storage Container S/N: 00LU523355 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Lake Worth, TX, USA	4958	40 ft Standard Open Top Storage Container S/N: TCLU7025755 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA
4949	40 ft Standard Storage Container S/N: 00LU523355 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Lake Worth, TX, USA	4959	40 ft High Cube Storage Container S/N: LCGU8113743 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA
4950	2004 40 ft High Cube Storage Container S/N: TRLU6929422 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:30 AM CDT Asset located in: Humble, TX, USA	4959	40 ft High Cube Storage Container S/N: LCGU8113743 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
4960	40 ft High Cube Storage Container S/N: LCGU8087747 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA	4965	40 ft High Cube Storage Container S/N: LCGU8334805 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA
4960	40 ft High Cube Storage Container S/N: LCGU8087747 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:31 AM CDT Asset located in: Humble, TX, USA	4966	40 ft High Cube Storage Container S/N: LCGU8320381 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA
4961	2021 40 ft High Cube Storage Container S/N: LCGU8099305 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Humble, TX, USA	4966	40 ft High Cube Storage Container S/N: LCGU8320381 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA
4961	2021 40 ft High Cube Storage Container S/N: LCGU8099305 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Humble, TX, USA	4967	40 ft High Cube Storage Container S/N: LCGU8016492 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA
4962	40 ft High Cube Storage Container S/N: LCGU8144641 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Humble, TX, USA	4967	40 ft High Cube Storage Container S/N: LCGU8016492 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA
4962	40 ft High Cube Storage Container S/N: LCGU8144641 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Humble, TX, USA	4972	20 ft Standard Storage Container S/N: TCLU6183822 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:33 AM CDT Asset located in: Lake Worth, TX, USA
4964	40 ft High Cube Storage Container S/N: LCGU8343200 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA	4972	20 ft Standard Storage Container S/N: TCLU6183822 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:33 AM CDT Asset located in: Lake Worth, TX, USA
4964	40 ft High Cube Storage Container S/N: LCGU8343200 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA	4973	20 ft Standard Storage Container S/N: TDTU3223650 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:33 AM CDT Asset located in: Lake Worth, TX, USA
4965	40 ft High Cube Storage Container S/N: LCGU8334805 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:32 AM CDT Asset located in: Lake Worth, TX, USA	4973	20 ft Standard Storage Container S/N: TDTU3223650 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:33 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4974	20 ft Standard Storage Container S/N: TCKU2332324 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	4978	20 ft Standard Storage Container S/N: TRIU9286947 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Humble, TX, USA
4974	20 ft Standard Storage Container S/N: TCKU2332324 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	4979	20 ft Standard Storage Container S/N: TRLU8826064 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA
4975	2025 20 ft Standard Storage Container S/N: LCGU1125779 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Humble, TX, USA	4979	20 ft Standard Storage Container S/N: TRLU8826064 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA
4975	2025 20 ft Standard Storage Container S/N: LCGU1125779 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Humble, TX, USA	4980	20 ft Standard Storage Container S/N: TRLU9618337 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA
4976	20 ft Standard Storage Container S/N: TCLU4847136 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	4980	20 ft Standard Storage Container S/N: TRLU9618337 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA
4976	20 ft Standard Storage Container S/N: TCLU4847136 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	4981	20 ft High Cube Storage Container S/N: LLTU209560 C/W: Located in Lane 79 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA
4976A	20 ft Standard Storage Container S/N: TCLU1402701 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	4981	20 ft High Cube Storage Container S/N: LLTU209560 C/W: Located in Lane 79 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA
4976A	20 ft Standard Storage Container S/N: TCLU1402701 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Lake Worth, TX, USA	4982	2026 12 ft Storage Container S/N: ST092 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA
4978	20 ft Standard Storage Container S/N: TRIU9286947 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:34 AM CDT Asset located in: Humble, TX, USA	4982	2026 12 ft Storage Container S/N: ST092 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4983	2026 12 ft Storage Container S/N: FHYU1200585 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4987	2026 12 ft Storage Container S/N: YLEU2630758 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA
4983	2026 12 ft Storage Container S/N: FHYU1200585 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4987	2026 12 ft Storage Container S/N: YLEU2630758 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA
4984	2026 12 ft Storage Container S/N: FHYU1200543 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4988	2026 11 ft Storage Container S/N: CTTN1100235 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA
4984	2026 12 ft Storage Container S/N: FHYU1200543 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4988	2026 11 ft Storage Container S/N: CTTN1100235 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA
4985	2026 12 ft Storage Container S/N: CTTN1200219 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4989	2026 11 ft Storage Container S/N: FHYU1100544 C/W: One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA
4985	2026 12 ft Storage Container S/N: CTTN1200219 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4989	2026 11 ft Storage Container S/N: FHYU1100544 C/W: One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA
4986	2026 12 ft Storage Container S/N: YLEU2630819 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4990	2026 11 ft Storage Container S/N: FHYU1100586 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA
4986	2026 12 ft Storage Container S/N: YLEU2630819 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:35 AM CDT Asset located in: Lake Worth, TX, USA	4990	2026 11 ft Storage Container S/N: FHYU1100586 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4991	2026 11 ft Storage Container S/N: YLEU2620744 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA	4995	2026 10 ft Storage Container S/N: FHYU1000587 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
4991	2026 11 ft Storage Container S/N: YLEU2620744 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA	4995	2026 10 ft Storage Container S/N: FHYU1000587 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
4992	2026 11 ft Storage Container S/N: YLEU2620739 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA	4996	2026 10 ft Storage Container S/N: FHYU1000545 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
4992	2026 11 ft Storage Container S/N: YLEU2620739 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA	4996	2026 10 ft Storage Container S/N: FHYU1000545 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
4993	2026 10 ft Storage Container S/N: CTTN0003180 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA	4997	2026 10 ft Storage Container S/N: CTTN0001384 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
4993	2026 10 ft Storage Container S/N: CTTN0003180 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:36 AM CDT Asset located in: Lake Worth, TX, USA	4997	2026 10 ft Storage Container S/N: CTTN0001384 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
4994	2026 10 ft Storage Container S/N: CTTN1000225 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA	4998	2026 10 ft Storage Container S/N: YLEU2610772 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA
4994	2026 10 ft Storage Container S/N: CTTN1000225 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA	4998	2026 10 ft Storage Container S/N: YLEU2610772 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
4999	2026 10 ft Storage Container S/N: YLEU2610860 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA	5005	2005 Rayco C100 48 in Skid Steer Mulcher S/N: 104-CE-2005 C/W: Located in Lane 50 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:39 AM CDT Asset located in: Humble, TX, USA
4999	2026 10 ft Storage Container S/N: YLEU2610860 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA	5006	2026 Wolverine DUM-26-73W Drum Skid Steer Mulcher (Unused) S/N: ZW00041 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:39 AM CDT Asset located in: Humble, TX, USA
5000	2026 9 ft Storage Container S/N: CTTN0900220 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA	5007	2026 Wolverine DUM-26-73W Drum Skid Steer Mulcher (Unused) S/N: ZW00046 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:39 AM CDT Asset located in: Humble, TX, USA
5000	2026 9 ft Storage Container S/N: CTTN0900220 C/W: Located in Lane 79 Spot 1, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 11:37 AM CDT Asset located in: Lake Worth, TX, USA	5008	2026 GIYI GY-DM59 60 in Disc Skid Steer Mulcher (Unused) S/N: D-YPTHJ260740 C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:39 AM CDT Asset located in: Humble, TX, USA
5001	MFC Concrete Screed (Inoperable) S/N: 2122950915 C/W: 2015 US EPA Label, Honda GX390 Gasoline Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 11:38 AM CDT Asset located in: Lake Worth, TX, USA	5009	Handy HFDM72-60" 60 in Disc Skid Steer Mulcher (Unused) S/N: DM202604113 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:40 AM CDT Asset located in: Humble, TX, USA
5001	MFC Concrete Screed (Inoperable) S/N: 2122950915 C/W: 2015 US EPA Label, Honda GX390 Gasoline Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 11:38 AM CDT Asset located in: Lake Worth, TX, USA	5010	ARTEER RK-5014W 50 in Drum Skid Steer Mulcher (Unused) S/N: 202680173957 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:40 AM CDT Asset located in: Humble, TX, USA
5004	2026 Raytree RMBD50 50 in Drum Skid Steer Mulcher (Unused) S/N: LM202606051823 C/W: Located in Lane 55 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:39 AM CDT Asset located in: Humble, TX, USA	5011	2026 GIYI FB77 Skid Steer Feller Buncher (Unused) S/N: FMGDJ260715 C/W: Located in Lane 52 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:40 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5012	2026 Wolverine ABC125 46 in Articulating Skid Steer Brush Cutter (Unused) S/N: 202600007 C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:40 AM CDT Asset located in: Humble, TX, USA	5019	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:41 AM CDT Asset located in: Humble, TX, USA
5013	2026 Wolverine ABC125 46 in Articulating Skid Steer Brush Cutter (Unused) S/N: 202600005 C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:40 AM CDT Asset located in: Humble, TX, USA	5020	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: 202600102 C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:41 AM CDT Asset located in: Humble, TX, USA
5014	All-Star 76 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:40 AM CDT Asset located in: Humble, TX, USA	5023	All-Star 68 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:42 AM CDT Asset located in: Humble, TX, USA
5015	All-Star 76 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:40 AM CDT Asset located in: Humble, TX, USA	5024	All-Star 68 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:42 AM CDT Asset located in: Humble, TX, USA
5016	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: 202600094 C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:41 AM CDT Asset located in: Humble, TX, USA	5025	All-Star 68 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:42 AM CDT Asset located in: Humble, TX, USA
5017	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:41 AM CDT Asset located in: Humble, TX, USA	5026	All-Star 68 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:42 AM CDT Asset located in: Humble, TX, USA
5018	2026 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:41 AM CDT Asset located in: Humble, TX, USA	5027	All-Star 68 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:42 AM CDT Asset located in: Humble, TX, USA
		5028	2026 GIYI GY-BC63 60 in Skid Steer Brush Cutter (Unused) S/N: D-GGJ260572 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:42 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5029	2015 Bradco BC72GS Skid Steer Brush Cutter S/N: 420555 C/W: Located in Lane 50 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 11:43 AM CDT Asset located in: Humble, TX, USA	5038	2026 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:44 AM CDT Asset located in: Humble, TX, USA
5030	TMG SFM72 72 in Skid Steer Flail Mower (Unused) S/N: 2501SFM72152 C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:43 AM CDT Asset located in: Humble, TX, USA	5039	2026 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:44 AM CDT Asset located in: Humble, TX, USA
5031	72 in Skid Steer Sickle Bar Mower S/N: 124060708 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:43 AM CDT Asset located in: Humble, TX, USA	5040	2026 Wolverine DB-15-84W 84 in Angle Skid Steer Dozer (Unused) S/N: 202600063 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:44 AM CDT Asset located in: Humble, TX, USA
5034	2026 Wolverine RS72 Angled Skid Steer Sweeper (Unused) S/N: 202600002 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:43 AM CDT Asset located in: Humble, TX, USA	5040A	2026 Raytree RSWD96 94 in PAT Skid Steer Dozer (Inoperable) S/N: SW20260603378 C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: Damaged Lot closing time: Fri, Sep 18, 11:44 AM CDT Asset located in: Humble, TX, USA
5035	2026 Wolverine RS72 Angled Skid Steer Sweeper (Unused) S/N: 202600001 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:43 AM CDT Asset located in: Humble, TX, USA	5041	2026 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:44 AM CDT Asset located in: Humble, TX, USA
5036	2026 Wolverine PAB-11-72W 72 in Skid Steer Broom (Unused) S/N: 202600001 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:44 AM CDT Asset located in: Humble, TX, USA	5042	2026 GIYI GY-D39 39 in Skid Steer Trencher (Unused) S/N: F-DKGJ2605009 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:45 AM CDT Asset located in: Humble, TX, USA
5037	2026 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:44 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5043	2026 GIYI GY-D39 39 in Skid Steer Trencher (Unused) S/N: F-DKGJ2605008 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:45 AM CDT Asset located in: Humble, TX, USA	5055	2026 Wolverine CB-11-750F Skid Steer Breaker (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:46 AM CDT Asset located in: Humble, TX, USA
5044	2026 GIYI GY-D39 39 in Skid Steer Trencher (Unused) S/N: F-DKGJ2605010 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:45 AM CDT Asset located in: Humble, TX, USA	5060	2026 GIYI GY-XGJ 40 in Mini Skid Steer Tiller (Unused) S/N: XGJ260707 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:47 AM CDT Asset located in: Humble, TX, USA
5045	Skid Steer Trencher S/N: Not Available C/W: Located in Lane 52 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 11:45 AM CDT Asset located in: Humble, TX, USA	5061	2026 Wolverine SG-13-08D 26 in Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:47 AM CDT Asset located in: Humble, TX, USA
5050	Arteer 72 in Skid Steer Power Rake S/N: ART2025CK888005268 C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:46 AM CDT Asset located in: Humble, TX, USA	5062	2026 Wolverine SG-13-08D 26 in Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:48 AM CDT Asset located in: Humble, TX, USA
5051	All-Star 84 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:46 AM CDT Asset located in: Humble, TX, USA	5063	2026 Wolverine SG-13-08D 26 in Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:48 AM CDT Asset located in: Humble, TX, USA
5053	Cat H65 Skid Steer Breaker S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:46 AM CDT Asset located in: Humble, TX, USA	5064	2026 GIYI GY-SZYMJ 16 in Mini Skid Steer Stump Grinder (Unused) S/N: SZYMJ260748 C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:48 AM CDT Asset located in: Humble, TX, USA
5054	2026 Wolverine CB-11-750F Skid Steer Breaker (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:46 AM CDT Asset located in: Humble, TX, USA	5065	2026 GIYI GY-SZYMJ 16 in Mini Skid Steer Stump Grinder (Unused) S/N: SZYMJ260747 C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:48 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5066	2026 GIYI GY-ZWB Mini Skid Steer Backhoe (Unused) S/N: XZWB260727 C/W: Located in Lane 48 Spot 1, 12 in bucket Usage: Not Available Lot closing time: Fri, Sep 18, 11:48 AM CDT Asset located in: Humble, TX, USA	5079	2025 Kit Containers QT-RR-70 70 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:50 AM CDT Asset located in: Humble, TX, USA
5069	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:49 AM CDT Asset located in: Humble, TX, USA	5083	All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:51 AM CDT Asset located in: Humble, TX, USA
5070	2025 Kit Containers QT-LP 72 in Skid Steer Landplane (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:49 AM CDT Asset located in: Humble, TX, USA	5084	All-Star 72 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:51 AM CDT Asset located in: Humble, TX, USA
5071	2025 Kit Containers QT-LP 72 in Skid Steer Landplane (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:49 AM CDT Asset located in: Humble, TX, USA	5085	Mid-State 68 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:51 AM CDT Asset located in: Humble, TX, USA
5072	2026 Handy HLL78 72 in Skid Steer Landplane (Unused) S/N: LL202603147 C/W: Located in Lane 55 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:49 AM CDT Asset located in: Humble, TX, USA	5086	All-Star 68 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:51 AM CDT Asset located in: Humble, TX, USA
5076	All-Star 98 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:50 AM CDT Asset located in: Humble, TX, USA	5087	Mid-State 60 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:51 AM CDT Asset located in: Humble, TX, USA
5077	All-Star 98 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:50 AM CDT Asset located in: Humble, TX, USA	5088	All-Star 48 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:51 AM CDT Asset located in: Humble, TX, USA
5078	All-Star 84 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:50 AM CDT Asset located in: Humble, TX, USA	5092	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:52 AM CDT Asset located in: Humble, TX, USA
		5093	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:52 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5094	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:52 AM CDT Asset located in: Humble, TX, USA	5102	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:54 AM CDT Asset located in: Humble, TX, USA
5095	2025 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:52 AM CDT Asset located in: Humble, TX, USA	5103	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:54 AM CDT Asset located in: Humble, TX, USA
5096	2026 Wolverine SBG-13-72W 72 in Brush Skid Steer Grapple (Unused) S/N: ZW00011 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:53 AM CDT Asset located in: Humble, TX, USA	5104	All-Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:54 AM CDT Asset located in: Humble, TX, USA
5097	2026 Wolverine SBG-13-72W 72 in Brush Skid Steer Grapple (Unused) S/N: ZW00010 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:53 AM CDT Asset located in: Humble, TX, USA	5105	All-Star 48 in Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:54 AM CDT Asset located in: Humble, TX, USA
5098	All-Star 80 in Heavy Duty Root Skid Steer Grapple S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:53 AM CDT Asset located in: Humble, TX, USA	5106	All-Star 80 in Heavy Duty Rock Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:54 AM CDT Asset located in: Humble, TX, USA
5099	All-Star 78 in Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:53 AM CDT Asset located in: Humble, TX, USA	5107	All-Star 80 in Heavy Duty Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:54 AM CDT Asset located in: Humble, TX, USA
5100	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:53 AM CDT Asset located in: Humble, TX, USA	5108	All-Star 78 in Rock Skid Steer Grapple S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:54 AM CDT Asset located in: Humble, TX, USA
5101	All-Star 74 in Heavy Duty Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:53 AM CDT Asset located in: Humble, TX, USA	5109	All-Star 72 in Rock Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 11:55 AM CDT Asset located in: Humble, TX, USA
		5110	All-Star 72 in Rock Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:55 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5111	All-Star 68 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:55 AM CDT Asset located in: Humble, TX, USA	5118	2026 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00075 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:56 AM CDT Asset located in: Humble, TX, USA
5112	All-Star 48 in Rock Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:55 AM CDT Asset located in: Humble, TX, USA	5119	2026 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00076 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:56 AM CDT Asset located in: Humble, TX, USA
5113	All-Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:55 AM CDT Asset located in: Humble, TX, USA	5120	2026 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00074 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:56 AM CDT Asset located in: Humble, TX, USA
5114	2026 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: ZW01538 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:55 AM CDT Asset located in: Humble, TX, USA	5122	2026 Wolverine TD-13-36R Skid Steer Tree Spade (Unused) S/N: ZW10278 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:57 AM CDT Asset located in: Humble, TX, USA
5115	2026 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: ZW01525 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:55 AM CDT Asset located in: Humble, TX, USA	5123	2026 Wolverine TD-13-36R Skid Steer Tree Spade (Unused) S/N: ZW10282 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:57 AM CDT Asset located in: Humble, TX, USA
5116	All-Star 72 in General Purpose Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:56 AM CDT Asset located in: Humble, TX, USA	5124	2026 Wolverine TD-13-36R Skid Steer Tree Spade (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:57 AM CDT Asset located in: Humble, TX, USA
5117	2026 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: 260600077 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:56 AM CDT Asset located in: Humble, TX, USA	5125	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:57 AM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5126	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 11:57 AM CDT Asset located in: Humble, TX, USA	5133	2026 STARVOX SV-AG42 Skid Steer Auger (Unused) S/N: SV2026SA010184 C/W: Located in Lane 48 Spot 3, (1) 8 in, (1) 12 in & (1) 18 in Auger Bits ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:58 AM CDT Asset located in: Humble, TX, USA
5127	Kit Containers QT-15-40 Skid Steer Stump Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 11:57 AM CDT Asset located in: Humble, TX, USA	5134	2026 STARVOX SV-AG42 Skid Steer Auger (Unused) S/N: SV2026SA010185 C/W: Located in Lane 48 Spot 3, (1) 8 in, (1) 12 in & (1) 18 in Auger Bits ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:58 AM CDT Asset located in: Humble, TX, USA
5128	Quantity of (2) 2026 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, (1) 12 in, (1) 18 in Auger Bits ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:57 AM CDT Asset located in: Humble, TX, USA	5135	2026 STARVOX SV-AG42 Skid Steer Auger (Unused) S/N: SV2026SA010186 C/W: Located in Lane 48 Spot 3, (1) 8 in, (1) 12 in & (1) 18 in Auger Bits ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:58 AM CDT Asset located in: Humble, TX, USA
5129	Quantity of (2) 2026 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, (1) 12 in, (1) 18 in Auger Bits ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:58 AM CDT Asset located in: Humble, TX, USA	5136	2026 GIYI GY-VB79 72 in Skid Steer Screening Bucket (Unused) S/N: D-ZDD260748 C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 11:59 AM CDT Asset located in: Humble, TX, USA
5130	2026 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: ZW01070 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:58 AM CDT Asset located in: Humble, TX, USA	5139	2026 Wolverine SB-12-72W Skid Steer Screening Bucket (Unused) S/N: 260600046 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:59 AM CDT Asset located in: Humble, TX, USA
5131	2026 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: 260600014 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:58 AM CDT Asset located in: Humble, TX, USA	5140	2026 Wolverine SB-12-72W Skid Steer Screening Bucket (Unused) S/N: 260600045 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:59 AM CDT Asset located in: Humble, TX, USA
5132	2026 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: 260600015 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:58 AM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5141	2026 Wolverine SB-12-72W Skid Steer Screening Bucket (Unused) S/N: 260600047 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 11:59 AM CDT Asset located in: Humble, TX, USA	5148	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00028 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:00 PM CDT Asset located in: Humble, TX, USA
5142	All-Star 100 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:00 PM CDT Asset located in: Humble, TX, USA	5149	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00066 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:01 PM CDT Asset located in: Humble, TX, USA
5143	2025 Kit Containers QT-SNB-84 84 in Snow /Litter Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:00 PM CDT Asset located in: Humble, TX, USA	5150	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00065 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:01 PM CDT Asset located in: Humble, TX, USA
5144	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00057 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:00 PM CDT Asset located in: Humble, TX, USA	5151	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00027 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:01 PM CDT Asset located in: Humble, TX, USA
5145	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00011 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:00 PM CDT Asset located in: Humble, TX, USA	5152	2026 Wolverine TDB-11-84W Skid Steer Bucket (Unused) S/N: ZW10356 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:01 PM CDT Asset located in: Humble, TX, USA
5146	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00013 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:00 PM CDT Asset located in: Humble, TX, USA	5153	2026 Wolverine TDB-11-84W Skid Steer Bucket (Unused) S/N: ZW10373 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:01 PM CDT Asset located in: Humble, TX, USA
5147	2026 Wolverine MCB-11-48W 48 in Multi-Purpose Mini Skid Steer Bucket (Unused) S/N: ZW00012 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:00 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5154	2026 Wolverine TDB-11-84W Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:01 PM CDT Asset located in: Humble, TX, USA	5164	All-Star 78 in Skid Steer Bucket S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:03 PM CDT Asset located in: Humble, TX, USA
5155	2026 Wolverine TDB-11-84W Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:01 PM CDT Asset located in: Humble, TX, USA	5165	2025 Kit Containers QT-DB-S78 78 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:03 PM CDT Asset located in: Humble, TX, USA
5158	Mid-State 84 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:02 PM CDT Asset located in: Humble, TX, USA	5168	2026 Wolverine TDB-11-78W Skid Steer Bucket (Unused) S/N: ZW10375 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:03 PM CDT Asset located in: Humble, TX, USA
5159	Mid-State 84 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:02 PM CDT Asset located in: Humble, TX, USA	5169	2026 Wolverine TDB-11-78W Skid Steer Bucket (Unused) S/N: ZW10361 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:04 PM CDT Asset located in: Humble, TX, USA
5160	All-Star 80 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 12:02 PM CDT Asset located in: Humble, TX, USA	5170	2026 Wolverine TDB-11-78W Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:04 PM CDT Asset located in: Humble, TX, USA
5161	Mid-State 80 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:02 PM CDT Asset located in: Humble, TX, USA	5171	2026 Wolverine TDB-11-78W Skid Steer Bucket (Unused) S/N: ZW10374 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:04 PM CDT Asset located in: Humble, TX, USA
5162	All-Star 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 12:03 PM CDT Asset located in: Humble, TX, USA		
5163	Mid-State 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:03 PM CDT Asset located in: Humble, TX, USA	5173	All-Star 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:04 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5174	Mid-State 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:04 PM CDT Asset located in: Humble, TX, USA	5184	2026 Wolverine TDB-11-72W Skid Steer Bucket (Unused) S/N: ZW10389 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:06 PM CDT Asset located in: Humble, TX, USA
5175	All-Star 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:04 PM CDT Asset located in: Humble, TX, USA	5185	Mid-State 72 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:06 PM CDT Asset located in: Humble, TX, USA
5176	72 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 12:05 PM CDT Asset located in: Humble, TX, USA	5186	All-Star 68 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:06 PM CDT Asset located in: Humble, TX, USA
5177	All-Star 72 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:05 PM CDT Asset located in: Humble, TX, USA	5189	2026 Wolverine TDB-11-66W 66 in Skid Steer Bucket (Unused) S/N: ZW10403 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA
5178	All-Star 72 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:05 PM CDT Asset located in: Humble, TX, USA		
5181	2026 Wolverine TDB-11-72W Skid Steer Bucket (Unused) S/N: ZW10364 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:05 PM CDT Asset located in: Humble, TX, USA	5190	2026 Wolverine TDB-11-66W 66 in Skid Steer Bucket (Unused) S/N: ZW10369 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA
5182	2026 Wolverine TDB-11-72W Skid Steer Bucket (Unused) S/N: ZW10366 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:06 PM CDT Asset located in: Humble, TX, USA	5191	2026 Wolverine TDB-11-66W 66 in Skid Steer Bucket (Unused) S/N: ZW10357 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA
5183	2026 Wolverine TDB-11-72W Skid Steer Bucket (Unused) S/N: ZW10379 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:06 PM CDT Asset located in: Humble, TX, USA	5192	2026 Wolverine TDB-11-66W 66 in Skid Steer Bucket (Unused) S/N: ZW10360 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5193	2025 Kit Containers QT-DB-S66 66 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA	5200	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 12:08 PM CDT Asset located in: Humble, TX, USA
5194	All-Star 60 in Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA	5201	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Teeth Usage: Not Available Lot closing time: Fri, Sep 18, 12:08 PM CDT Asset located in: Humble, TX, USA
5194A	65 in Q/C General Purpose Skid Steer Bucket - Fits Bobcat T770 S/N: Not Available C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA	5202	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:09 PM CDT Asset located in: Humble, TX, USA
5195	2026 GIYI 67 in Skid Steer Bucket (Unused) S/N: D CD260713 C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:07 PM CDT Asset located in: Humble, TX, USA	5203	2026 Greatbear 78 in Rock Skid Steer Bucket (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 4, Operating Width: 1980mm Usage: Not Available Lot closing time: Fri, Sep 18, 12:09 PM CDT Asset located in: Humble, TX, USA
5196	2026 Greatbear 84 in Rock Skid Steer Bucket (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:08 PM CDT Asset located in: Humble, TX, USA	5204	2026 Greatbear 78 in Rock Skid Steer Bucket (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 2, Operating Width: 1980mm Usage: Not Available Lot closing time: Fri, Sep 18, 12:09 PM CDT Asset located in: Humble, TX, USA
5197	2026 Greatbear 84 in Skeleton Skid Steer Bucket (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:08 PM CDT Asset located in: Humble, TX, USA	5205	2026 Wolverine RSB78 78 in Rock Skid Steer Bucket (Unused) S/N: ZW10048 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:09 PM CDT Asset located in: Humble, TX, USA
5198	2026 Wolverine RSB84 84 in Rock Skid Steer Bucket (Unused) S/N: ZW10045 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:08 PM CDT Asset located in: Humble, TX, USA	5206	2026 Wolverine RSB78 78 in Rock Skid Steer Bucket (Unused) S/N: ZW10052 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:09 PM CDT Asset located in: Humble, TX, USA
5199	2026 Wolverine RSB84 84 in Rock Skid Steer Bucket (Unused) S/N: ZW10049 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:08 PM CDT Asset located in: Humble, TX, USA	5207	2025 Kit Containers QT-SB-H76-V3 76 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 55 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:09 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5208	2026 Greatbear 72 in Rock Skid Steer Bucket (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 2, Operating Width: 1830mm Usage: Not Available Lot closing time: Fri, Sep 18, 12:09 PM CDT Asset located in: Humble, TX, USA	5215	2026 Greatbear 66 in Rock Skid Steer Bucket (Unused) S/N: 69032602 C/W: Located in Lane 48 Spot 4, Operating Width: 1676mm Usage: Not Available Lot closing time: Fri, Sep 18, 12:10 PM CDT Asset located in: Humble, TX, USA
5209	2026 Greatbear 72 in Rock Skid Steer Bucket (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 4, Operating Width: 1830mm Usage: Not Available Lot closing time: Fri, Sep 18, 12:10 PM CDT Asset located in: Humble, TX, USA	5216	2026 Wolverine RSB66 66 in Rock Skid Steer Bucket (Unused) S/N: ZW10067 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:11 PM CDT Asset located in: Humble, TX, USA
5210	2026 Wolverine RSB72 72 in Rock Skid Steer Bucket (Unused) S/N: ZW10059 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:10 PM CDT Asset located in: Humble, TX, USA	5217	2026 Wolverine RSB66 66 in Rock Skid Steer Bucket (Unused) S/N: ZW10063 C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:11 PM CDT Asset located in: Humble, TX, USA
5211	2026 Wolverine RSB72 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:10 PM CDT Asset located in: Humble, TX, USA	5218	2025 Kit Containers QT-SB-H76-V3 76 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:11 PM CDT Asset located in: Humble, TX, USA
5212	All-Star 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:10 PM CDT Asset located in: Humble, TX, USA	5219	2025 Kit Containers QT-SB-L76-V3 76 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:11 PM CDT Asset located in: Humble, TX, USA
5213	All-Star 68 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:10 PM CDT Asset located in: Humble, TX, USA	5220	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:11 PM CDT Asset located in: Humble, TX, USA
5214	2026 Greatbear 66 in Rock Skid Steer Bucket (Unused) S/N: 69032602 C/W: Located in Lane 48 Spot 2, Operating Width: 1676mm Usage: Not Available Lot closing time: Fri, Sep 18, 12:10 PM CDT Asset located in: Humble, TX, USA	5221	2025 Kit Containers QT-SB-H72-F 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:11 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5230	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 12:13 PM CDT Asset located in: Humble, TX, USA	5238	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:14 PM CDT Asset located in: Humble, TX, USA
5231	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2, Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 12:13 PM CDT Asset located in: Humble, TX, USA	5239	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:14 PM CDT Asset located in: Humble, TX, USA
5232	2026 Wolverine FK-11-48W 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:13 PM CDT Asset located in: Humble, TX, USA	5240	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:14 PM CDT Asset located in: Humble, TX, USA
5233	2026 Wolverine FK-11-48W 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:13 PM CDT Asset located in: Humble, TX, USA	5241	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:14 PM CDT Asset located in: Humble, TX, USA
5234	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:13 PM CDT Asset located in: Humble, TX, USA	5242	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA
5235	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:13 PM CDT Asset located in: Humble, TX, USA	5243	Quantity of (2) 2026 GIYI GY-DHC 60 in Skid Steer Forks (Unused) S/N: DHC2607163 C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA
5236	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:14 PM CDT Asset located in: Humble, TX, USA	5243A	2025 Kit Containers MUFF-36-42 42 in Mini Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA
5237	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:14 PM CDT Asset located in: Humble, TX, USA	5243B	2025 Kit Containers QT-45-FF-42 42 in Mini Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5243C	2025 Kit Containers QT-45-FF-42 42 in Mini Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA	5250	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:16 PM CDT Asset located in: Humble, TX, USA
5243D	2025 Kit Containers QT-45-FF-42 42 in Mini Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA	5251	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:16 PM CDT Asset located in: Humble, TX, USA
5243E	2025 Kit Containers QT-45-FF-42 42 in Mini Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA	5252	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:16 PM CDT Asset located in: Humble, TX, USA
5245	Quantity of (2) 2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2607282 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA	5253	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:16 PM CDT Asset located in: Humble, TX, USA
5246	Quantity of (2) 2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2607284 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA	5254	Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:16 PM CDT Asset located in: Humble, TX, USA
5247A	2025 Kit Containers MUFF-36-36 36 in Mini Skid Steer Forks (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA	5255	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:16 PM CDT Asset located in: Humble, TX, USA
5248	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:15 PM CDT Asset located in: Humble, TX, USA	5256	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:17 PM CDT Asset located in: Humble, TX, USA
5249	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:16 PM CDT Asset located in: Humble, TX, USA	5257	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:17 PM CDT Asset located in: Humble, TX, USA
		5258	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:17 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5259	2026 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:17 PM CDT Asset located in: Humble, TX, USA	5277	2026 GIYI GY-TB72 Skid Steer Tree Boom (Unused) S/N: SMDG260723 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:20 PM CDT Asset located in: Humble, TX, USA
5260	2026 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:17 PM CDT Asset located in: Humble, TX, USA	5278	2026 GIYI GY-TB72 Skid Steer Tree Boom (Unused) S/N: SMDG260722 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:20 PM CDT Asset located in: Humble, TX, USA
5267	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:18 PM CDT Asset located in: Humble, TX, USA	5279	2026 GIYI GY-STB47 131 in Skid Steer Telescopic Boom (Unused) S/N: SX-HYSSDB260607 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:20 PM CDT Asset located in: Humble, TX, USA
5270	2026 GIYI GY-HLS82 Skid Steer Log Splitter (Unused) S/N: DJYPMQ260787 C/W: Located in Lane 48 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:19 PM CDT Asset located in: Humble, TX, USA	5280	2026 GIYI GY-MTS43 Mini Skid Steer Tree Shear (Unused) S/N: X-SMJD260707 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:20 PM CDT Asset located in: Humble, TX, USA
5271	2026 GIYI GY-HLS82 Skid Steer Log Splitter (Unused) S/N: DJYPMQ260790 C/W: Located in Lane 48 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:19 PM CDT Asset located in: Humble, TX, USA	5281	2026 GIYI GY-MTS43 Skid Steer Tree Shear (Unused) S/N: XSMJD260706 C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:20 PM CDT Asset located in: Humble, TX, USA
5272	2026 GIYI GY-HLS82 Skid Steer Log Splitter (Unused) S/N: DJYPMQ260786 C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:19 PM CDT Asset located in: Humble, TX, USA	5282	2026 GIYI GY-TP25 Skid Steer Post Puller (Unused) S/N: HS-LBQ260716 C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:21 PM CDT Asset located in: Humble, TX, USA
5276	Quantity of (2) 2026 GIYI GY-TB72 Skid Steer Tree Boom (Unused) S/N: SMDG260721 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:20 PM CDT Asset located in: Humble, TX, USA	5283	2026 GIYI GY-TP45 Skid Steer Post Puller (Unused) S/N: HS-LBQ260711 C/W: Located in Lane 48 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:21 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5286	All-Star 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:21 PM CDT Asset located in: Humble, TX, USA	5291A	2025 Kit Containers 2.0YFT-SST 2 cyd Skid Steer Dump Hopper (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA
5287	All-Star 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:21 PM CDT Asset located in: Humble, TX, USA	5292	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA
5287A	2025 Kit Containers QT-TM Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:21 PM CDT Asset located in: Humble, TX, USA	5293	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA
5287B	2025 Kit Containers QT-TM Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:21 PM CDT Asset located in: Humble, TX, USA	5294	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA
5289	2026 Wolverine PHA-15-02C Skid Steer 3-Point Adapter (Unused) S/N: ZW03250 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA	5295	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA
5290	2026 Wolverine PHA-15-02C Skid Steer 3-Point Adapter (Unused) S/N: ZW03254 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA	5296	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:23 PM CDT Asset located in: Humble, TX, USA
5291	2026 Wolverine PT-16-02C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:22 PM CDT Asset located in: Humble, TX, USA	5297	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:23 PM CDT Asset located in: Humble, TX, USA
		5298	2026 Wolverine QMP1-16-10T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10615 C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:23 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5299	2026 Wolverine QMP1-16-10T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10604 C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:23 PM CDT Asset located in: Humble, TX, USA	5306	2021 Cuts SS2600 Skid Steer Rock Saw S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:24 PM CDT Asset located in: Humble, TX, USA
5300	2026 Wolverine QMP1-16-10T Skid Steer Attachment Mounting Plate S/N: Not Available C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:23 PM CDT Asset located in: Humble, TX, USA	5307	2026 GIYI GY-TD27 Skid Steer Tree Spade (Unused) S/N: WSGJ260719 C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:24 PM CDT Asset located in: Humble, TX, USA
5301	2026 Wolverine QMP1-16-10T Skid Steer Attachment Mounting Plate S/N: Not Available C/W: Located in Lane 48 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:23 PM CDT Asset located in: Humble, TX, USA	5308	2026 Wolverine TAP-16-4200G Skid Steer Rotating Conversion Hanger (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:24 PM CDT Asset located in: Humble, TX, USA
5302	2026 Wolverine QMP2-16-12T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW11083 C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:24 PM CDT Asset located in: Humble, TX, USA	5309	2026 Wolverine TAP-16-4200G Skid Steer Rotating Conversion Hanger (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:25 PM CDT Asset located in: Humble, TX, USA
5303	2026 Wolverine QMP2-16-12T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW11074 C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:24 PM CDT Asset located in: Humble, TX, USA	5310	All-Star Skid Steer Wire Fence Winder (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:25 PM CDT Asset located in: Humble, TX, USA
5304	2026 Wolverine QMP3-16-6T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10842 C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:24 PM CDT Asset located in: Humble, TX, USA	5311	All-Star Skid Steer Wire Fence Winder (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:25 PM CDT Asset located in: Humble, TX, USA
5305	2026 Wolverine QMP3-16-6T Skid Steer Attachment Mounting Plate (Unused) S/N: ZW10862 C/W: Located in Lane 48 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:24 PM CDT Asset located in: Humble, TX, USA	5311A	Kinshofer DSP Demolition Pulverizer S/N: Not Available C/W: Located in Lane 77, Lane 78 spot 22 Usage: Not Available Lot closing time: Fri, Sep 18, 12:25 PM CDT Asset located in: Humble, TX, USA
		5320	2026 GIYI GY-ML61 33 in Excavator Mulcher (Unused) S/N: 308THJ260708 C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:26 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5326	2024 Elephant EPB2200T-E Hydraulic Breaker S/N: 2410138 C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:27 PM CDT Asset located in: Humble, TX, USA	5347	CF 60 in Cleanup Excavator Bucket S/N: Not Available C/W: Located in Lane 50 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:30 PM CDT Asset located in: Humble, TX, USA
5330	2024 TOFT TOFT1000 Hydraulic Breaker (Unused) S/N: TOFTJW50Z2160 C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:28 PM CDT Asset located in: Humble, TX, USA	5348	Gannon 60 in Cleanup Excavator Bucket S/N: T1025 C/W: Located in Lane 50 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:30 PM CDT Asset located in: Humble, TX, USA
5331	2024 Elephant EPB900B-E Hydraulic Breaker (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:28 PM CDT Asset located in: Humble, TX, USA	5350	70 in Q/C Excavator Bucket - Fits Cat 330CL, 330DL S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:31 PM CDT Asset located in: Humble, TX, USA
5335	Kent 8G Hydraulic Breaker S/N: Not Available C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:28 PM CDT Asset located in: Humble, TX, USA	5352	60 in Excavator Bucket - Fits Cat 336EL, 330DL S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:31 PM CDT Asset located in: Humble, TX, USA
5337	Tramac 140 Hydraulic Breaker S/N: Not Available C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:29 PM CDT Asset located in: Humble, TX, USA	5355	70 in Excavator Bucket - Fits Cat 330B S/N: E34334 C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:31 PM CDT Asset located in: Humble, TX, USA
5338	2017 C & P RX14 Hydraulic Breaker S/N: DEQ171515 C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:29 PM CDT Asset located in: Humble, TX, USA	5357	54 in Q/C Excavator Bucket - Fits Cat 330BL, 330CL, 330DL S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:32 PM CDT Asset located in: Humble, TX, USA
5341	2026 GIYI Excavator Auger - Fits Cat 303 (Unused) S/N: B-303TZLXZ-462 C/W: Located in Lane 46 Spot 0, 16 in bit Usage: Not Available Lot closing time: Fri, Sep 18, 12:29 PM CDT Asset located in: Humble, TX, USA	5365	48 in Excavator Bucket - Fits Cat 336DL, 336EL S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:33 PM CDT Asset located in: Humble, TX, USA
5342	2026 GIYI Excavator Auger - Fits Cat 303 (Unused) S/N: B-303TZYLXZ-020 C/W: Located in Lane 47 Spot 0, 16 in bit Usage: Not Available Lot closing time: Fri, Sep 18, 12:30 PM CDT Asset located in: Humble, TX, USA	5366	Cat 46 in Excavator Bucket - Fits Cat 325CL, 325DL S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:33 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5368	42 in Digging Excavator Bucket - Fits John Deere 230 S/N: Not Available C/W: Located in Lane 50 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:33 PM CDT Asset located in: Humble, TX, USA	5389	Vacuworx RC10 Pipe Vacuum Lifter S/N: RC10000020 C/W: Located in Lane 52 Spot 0, Hatz 1 Cylinder Diesel Engine Usage: 317 Hr Lot closing time: Fri, Sep 18, 12:37 PM CDT Asset located in: Humble, TX, USA
5369	38 in Excavator Bucket - Fits Cat 330CL, 330DL S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:34 PM CDT Asset located in: Humble, TX, USA	5390	Quantity of (8) 2026 GIYI Cat 301 GYA-8 Mini Excavator Attachments - Fits Cat 301 (Unused) S/N: C-301SJB-1707 C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:37 PM CDT Asset located in: Humble, TX, USA
5370	38 in Q/C Excavator Bucket - Fits Cat 325CL, 325DL S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:34 PM CDT Asset located in: Humble, TX, USA	5391	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6770 C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:37 PM CDT Asset located in: Humble, TX, USA
5371	TAG 36 in Digging Excavator Bucket - Fits Hitachi ZX300 S/N: Not Available C/W: Located in Lane 50 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:34 PM CDT Asset located in: Humble, TX, USA	5392	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6762 C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:37 PM CDT Asset located in: Humble, TX, USA
5372	Rockland 24 in Digging Excavator Bucket - Fits Volvo EC300E S/N: 137857 C/W: Located in Lane 50 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:34 PM CDT Asset located in: Humble, TX, USA	5393	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6771 C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:37 PM CDT Asset located in: Humble, TX, USA
5374	24 in Digging Excavator Bucket S/N: Not Available C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:34 PM CDT Asset located in: Humble, TX, USA	5394	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: F06276 C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:37 PM CDT Asset located in: Humble, TX, USA
5375	Excavator Bucket - Fits Link-Belt 210 S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:34 PM CDT Asset located in: Humble, TX, USA	5395	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:37 PM CDT Asset located in: Humble, TX, USA
5376	Digging Excavator Bucket S/N: Not Available C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:35 PM CDT Asset located in: Humble, TX, USA	5396	Quantity of (10) 2026 Mini Excavator Attachments (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:38 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5397	Quantity of (8) 2025 VICSEC VCA -8 Mini Excavator Attachments S/N: Not Available C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:38 PM CDT Asset located in: Humble, TX, USA	5405	90 in Motor Grader Ripper - Fits Cat 12H, 120H, 135H, 140H, 143H S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:39 PM CDT Asset located in: Humble, TX, USA
5398	Cat 71 in Q/C Wheel Loader Forks S/N: Not Available C/W: Located in Lane 73 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:38 PM CDT Asset located in: Humble, TX, USA	5406	90 in Motor Grader Ripper - Fits Cat 12H, 120H, 135H, 140H, 143H S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:39 PM CDT Asset located in: Humble, TX, USA
5398A	72 in Wheel Loader Forks - Fits Cat 938 S/N: Not Available C/W: Located in Lane 51 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:38 PM CDT Asset located in: Humble, TX, USA	5406A	Cat 192 in Angle Dozer Blade - Fits Cat D6 S/N: Not Available C/W: Located in Lane 73 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:39 PM CDT Asset located in: Humble, TX, USA
5399	Cat 72 in Wheel Loader Forks S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 12:38 PM CDT Asset located in: San Antonio, TX, USA	5408	88 in Crawler Tractor Ripper - Fits Cat D6H, D6R, D6T S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:39 PM CDT Asset located in: Humble, TX, USA
5400	Cat 126 in Q/C Wheel Loader Bucket S/N: Not Available C/W: Located in Lane 52 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:38 PM CDT Asset located in: Humble, TX, USA	5409	88 in Crawler Tractor Ripper - Fits Cat D6H, D6R, D6T S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA
5401	120 in General Purpose Wheel Loader Bucket - Fits Cat 966F, 966G S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:38 PM CDT Asset located in: Humble, TX, USA	5410	Land Pride 70 in 3-Point Rotary Tiller S/N: 700401 C/W: Located in Lane 51 Spot 0, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA
5403	Balderson 118 in General Purpose Wheel Loader Bucket - Fits Cat 966F, 966G S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:39 PM CDT Asset located in: Humble, TX, USA	5410	Land Pride 70 in 3-Point Rotary Tiller S/N: 700401 C/W: Located in Lane 51 Spot 0, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA
5404	90 in Motor Grader Ripper - Fits Cat 12H, 120H, 135H, 140H, 143H S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:39 PM CDT Asset located in: Humble, TX, USA	5411	80 in 3-Point Disc Harrow S/N: Not Available C/W: Located in Lane 51 Spot 0, 19 in Notched Front Discs, 19 in Notched Rear Discs, 7 in Spacing Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5411	80 in 3-Point Disc Harrow S/N: Not Available C/W: Located in Lane 51 Spot 0, 19 in Notched Front Discs, 19 in Notched Rear Discs, 7 in Spacing Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA	5417	2026 Wolverine QC10-26-15G Quick Coupler 10 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:41 PM CDT Asset located in: Humble, TX, USA
5412	2026 Wolverine QC9-26-21G Quick Coupler 9 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA	5418	2026 Wolverine QC6-26-15G Quick Coupler 6 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:41 PM CDT Asset located in: Humble, TX, USA
5413	2026 Wolverine QC5-26-20G Quick Coupler 5 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA	5419	2026 Wolverine QC3-26-14G Quick Coupler 3 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:41 PM CDT Asset located in: Humble, TX, USA
5414	2026 Wolverine QC1-26-20G Quick Coupler 1 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA	5420	2026 Wolverine QC7-26-12.5G Quick Coupler 7 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:41 PM CDT Asset located in: Humble, TX, USA
5415	2026 Wolverine QC2-26-18G Quick Coupler 2 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:40 PM CDT Asset located in: Humble, TX, USA	5421	2026 Wolverine QC8-26-12G Quick Coupler 8 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:41 PM CDT Asset located in: Humble, TX, USA
5416	2026 Wolverine QC4-26-15.7G Quick Coupler 4 3-Point Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 48 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:41 PM CDT Asset located in: Humble, TX, USA	5422	2026 Wolverine TR-26-01C Class 1 Tractors Quick Hitch 3-Point Hitch (Unused) S/N: 202600029 C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:42 PM CDT Asset located in: Humble, TX, USA
		5423	Rhino 4155-4 15 ft Flex Wing Rotary Cutter S/N: 40525 C/W: Located in Lane 52 Spot 0, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 12:42 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5424	Land Pride 6 ft 3-Point Hitch Rotary Cutter S/N: 1628803 C/W: Located in Lane 53 Spot 1, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 12:42 PM CDT Asset located in: Humble, TX, USA	5430	Quantity of (20) 2026 STARVOX PPP-20 Polyethylene Board Road Bed Protection Mats (Unused) S/N: STV2026PPP01085 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA
5424A	5 ft 3-Point Hitch Rotary Cutter S/N: Not Available C/W: Located in Lane 51 Spot 1, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 12:42 PM CDT Asset located in: Humble, TX, USA	5430	Quantity of (20) 2026 STARVOX PPP-20 Polyethylene Board Road Bed Protection Mats (Unused) S/N: STV2026PPP01085 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA
5424B	John Deere 6 ft 3-Point Hitch Rotary Cutter S/N: Not Available C/W: Located in Lane 51 Spot 1, 540 PTO Usage: Not Available Lot closing time: Fri, Sep 18, 12:42 PM CDT Asset located in: Humble, TX, USA	5431	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA
5426	2026 Wolverine QC11-26-10G Quick Coupler 11 Drawbar Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:42 PM CDT Asset located in: Humble, TX, USA	5431	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA
5426	2026 Wolverine QC11-26-10G Quick Coupler 11 Drawbar Hitch (Unused) S/N: ZW10137 C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:42 PM CDT Asset located in: Humble, TX, USA	5432	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA
5429	Quantity of (20) 2026 STARVOX PPP-20 Polyethylene Board Road Bed Protection Mats (Unused) S/N: STV2026PPP01089 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5432	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA
5429	Quantity of (20) 2026 STARVOX PPP-20 Polyethylene Board Road Bed Protection Mats (Unused) S/N: STV2026PPP01089 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5432	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5433	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5436	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA
5433	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5436	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA
5434	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5437	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA
5434	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5437	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA
5435	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5438	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA
5435	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:43 PM CDT Asset located in: Humble, TX, USA	5438	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5439	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5442	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5439	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5443	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5440	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5443	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5440	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5444	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5440	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5444	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5441	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5445	Quantity of (30) Heavy-Duty Shackle (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5441	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5445	Quantity of (30) Heavy-Duty Shackle (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5441	Quantity of (15) 2026 FPM Ground Protection Mats (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:44 PM CDT Asset located in: Humble, TX, USA	5446	Quantity of (30) Heavy-Duty Shackle (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 0, 4400 LB-10PCS, 10500 LB-10PCS, 14500 LB-10PCS Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA
5442	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA	5446	Quantity of (30) Heavy-Duty Shackle (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 0, 4400 LB-10PCS, 10500 LB-10PCS, 14500 LB-10PCS Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5447	Quantity of (100) 2026 3.5M Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA	5449B	Quantity of 2026 Greatbear 5/16 in 7ft G80 Double Legs Lifting Chain Sling (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Material: Alloy Steel Usage: Lifting Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA
5447	Quantity of (100) 2026 3.5M Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA	5449B	Quantity of 2026 Greatbear 5/16 in 7ft G80 Double Legs Lifting Chain Sling (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Material: Alloy Steel Usage: Lifting Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA
5448	Quantity of (100) 2026 5M Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA	5451	Quantity of Sling S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA
5448	Quantity of (100) 2026 5M Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:45 PM CDT Asset located in: Humble, TX, USA	5451	Quantity of Sling S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA
5449	Quantity of (100) 2026 2M Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 47 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA	5452	Quantity of Sling S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA
5449	Quantity of (100) 2026 2M Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 47 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA	5452	Quantity of Sling S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA
5449A	Quantity of (22) 2026 Greatbear 2-5 Ton Webbling Sling (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA	5454	Quantity of (20) 1.2 in x 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA
5449A	Quantity of (22) 2026 Greatbear 2-5 Ton Webbling Sling (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA	5454	Quantity of (20) 1.2 in x 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5455	Quantity of (20) 1.2 in x 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA	5460	Quantity of (2) Dragline Buckets S/N: Not Available C/W: Located in Lane 53 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA
5455	Quantity of (20) 1.2 in x 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:46 PM CDT Asset located in: Humble, TX, USA	5460	Quantity of (2) Dragline Buckets S/N: Not Available C/W: Located in Lane 53 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA
5456	Quantity of (20) 2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA	5463	2026 Greatbear 005-03-6325-01 Extendable Forklift Jib (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:48 PM CDT Asset located in: Humble, TX, USA
5456	Quantity of (20) 2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA	5464	2026 Greatbear 005-03-6325-01 Extendable Forklift Jib (Unused) S/N: 69032606 C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 12:48 PM CDT Asset located in: Humble, TX, USA
5458	Quantity of Sling S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA	5465	2026 GIYI GY-TB47 132 in 3300 lb Forklift Telescopic Boom (Unused) S/N: SX-CCSSDB2605116 C/W: Located in Lane 48 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:48 PM CDT Asset located in: Humble, TX, USA
5458	Quantity of Sling S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA	5466	Quantity of (4) Steel Pallets Fork Attachment S/N: Not Available C/W: Located in Lane 51 Spot 4, Fork pockets Usage: Not Available Lot closing time: Fri, Sep 18, 12:48 PM CDT Asset located in: Humble, TX, USA
5459	Quantity of (2) Crates of Steel Wire Sling S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA	5467	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:48 PM CDT Asset located in: Humble, TX, USA
5459	Quantity of (2) Crates of Steel Wire Sling S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:47 PM CDT Asset located in: Humble, TX, USA	5468	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:48 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5469	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:49 PM CDT Asset located in: Humble, TX, USA	5475	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:49 PM CDT Asset located in: Humble, TX, USA
5470	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:49 PM CDT Asset located in: Humble, TX, USA	5476	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:50 PM CDT Asset located in: Humble, TX, USA
5471	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:49 PM CDT Asset located in: Humble, TX, USA	5477	2026 Wolverine EX-66-78L 78 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:50 PM CDT Asset located in: Humble, TX, USA
5472	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:49 PM CDT Asset located in: Humble, TX, USA	5478	2026 Wolverine EX-66-78L 78 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:50 PM CDT Asset located in: Humble, TX, USA
5473	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:49 PM CDT Asset located in: Humble, TX, USA	5479	2026 Wolverine EX-66-78L 78 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:50 PM CDT Asset located in: Humble, TX, USA
5474	2026 Wolverine EX-66-84L 84 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:49 PM CDT Asset located in: Humble, TX, USA	5480	2026 Wolverine EX-66-78L 78 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:50 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5481	2026 Wolverine EX-66-78L 78 in Fork Extensions (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:50 PM CDT Asset located in: Humble, TX, USA	5489	Quantity of (2) Cat Track Groups (Unused) - Fits Cat D8T S/N: Not Available C/W: Located in Lane 46 Spot 0, 28 in Single Grouser Track Shoes Usage: Not Available Lot closing time: Fri, Sep 18, 12:52 PM CDT Asset located in: Humble, TX, USA
5482	2026 Greatbear 78 in Skid Steer Root Rake (Unused) S/N: 69032512 C/W: Located in Lane 48 Spot 3, Operating Pressure: 16Mpa Usage: Not Available Lot closing time: Fri, Sep 18, 12:51 PM CDT Asset located in: Humble, TX, USA	5490	Quantity of (2) Cat Track Groups (Unused) - Fits Cat D7R S/N: Not Available C/W: Located in Lane 46 Spot 0, 24 in Single Grouser Track Shoes Usage: Not Available Lot closing time: Fri, Sep 18, 12:52 PM CDT Asset located in: Humble, TX, USA
5483	2026 Greatbear 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 4, Operating Pressure: 16Mpa Usage: Not Available Lot closing time: Fri, Sep 18, 12:51 PM CDT Asset located in: Humble, TX, USA	5491	Quantity of (2) Cat Track Groups (Unused) - Fits Cat D7R S/N: Not Available C/W: Located in Lane 46 Spot 0, 24 in Single Grouser Track Shoes Usage: Not Available Lot closing time: Fri, Sep 18, 12:52 PM CDT Asset located in: Humble, TX, USA
5484	2026 Greatbear 78 in Skid Steer Root Rake (Unused) S/N: 001809599 C/W: Located in Lane 48 Spot 4, Operating Pressure: 16Mpa Usage: Not Available Lot closing time: Fri, Sep 18, 12:51 PM CDT Asset located in: Humble, TX, USA	5492	Quantity of (8) Cat Tilt Cylinder - Fits Cat D7R S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:52 PM CDT Asset located in: Humble, TX, USA
5485	AGT JD470G Hydraulic Quick Coupler - Fits John Deere 470G (Unused) S/N: Not Available C/W: Located in Lane 51 Usage: Not Available Lot closing time: Fri, Sep 18, 12:51 PM CDT Asset located in: Humble, TX, USA	5493	Quantity of (14) Cat Cylinder - Fits Cat D7R S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:52 PM CDT Asset located in: Humble, TX, USA
5487	Cat Cab - Fits Cat D8T S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:51 PM CDT Asset located in: Humble, TX, USA	5494	Quantity of (13) Cat Lift Cylinder (Unused) - Fits Cat D5 S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:52 PM CDT Asset located in: Humble, TX, USA
5488	Cat Cab - Fits Cat D7R S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:51 PM CDT Asset located in: Humble, TX, USA	5495	Cat 730 Articulated Dump Truck Bed S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:52 PM CDT Asset located in: Humble, TX, USA
		5496	Bell Articulated Dump Truck Bed S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:53 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5497	John Deere Articulated Dump Truck Bed S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 12:53 PM CDT Asset located in: Humble, TX, USA	5508	Quantity of Misc Parts - Fits Cat D6T / GC S/N: Not Available C/W: Located in Lane 46 Spot 0, Pump housing, hub Usage: Not Available Lot closing time: Fri, Sep 18, 12:54 PM CDT Asset located in: Humble, TX, USA
5500	Quantity of Final Drive - Fits Cat D5 S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:53 PM CDT Asset located in: Humble, TX, USA	5509	Quantity of (3) Cat T10 Air Conditioners S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:55 PM CDT Asset located in: Humble, TX, USA
5501	Quantity of Cat Hydraulic Pumps S/N: Not Available C/W: Located in Lane 47 Spot 0, Control valve Usage: Not Available Lot closing time: Fri, Sep 18, 12:53 PM CDT Asset located in: Humble, TX, USA	5510	Quantity of (200) Cat 457-1527 Fuel/Water Separator Filters (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:55 PM CDT Asset located in: Humble, TX, USA
5502	Quantity of Cat Hydraulic Pumps S/N: Not Available C/W: Located in Lane 47 Spot 0, Control valve Usage: Not Available Lot closing time: Fri, Sep 18, 12:54 PM CDT Asset located in: Humble, TX, USA	5511	JLG Telescopic Boom For Telehandler S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:55 PM CDT Asset located in: Humble, TX, USA
5503	Quantity of Cat Hydraulic Pumps S/N: Not Available C/W: Located in Lane 47 Spot 0, Control valve, oil cooler Usage: Not Available Lot closing time: Fri, Sep 18, 12:54 PM CDT Asset located in: Humble, TX, USA	5512	JLG Telescopic Boom For Telehandler S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:55 PM CDT Asset located in: Humble, TX, USA
5504	Quantity of Hydraulic Pumps S/N: Not Available C/W: Located in Lane 47 Spot 0, Control valve Usage: Not Available Lot closing time: Fri, Sep 18, 12:54 PM CDT Asset located in: Humble, TX, USA	5514	Kubota RCK60B23BX 60 in Mower Deck S/N: 15492 Usage: Not Available Lot closing time: Fri, Sep 18, 12:55 PM CDT Asset located in: Lake Worth, TX, USA
5505	Quantity of Cat Misc Parts (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Base Edge Shrouds, Rims, Driveshaft Usage: Not Available Lot closing time: Fri, Sep 18, 12:54 PM CDT Asset located in: Humble, TX, USA	5515	Closing Unit S/N: Not Available C/W: Located in Lane 36 Spot 0, 1 Cylinder Gasoline Engine, Accumulators Usage: Not Available Lot closing time: Fri, Sep 18, 12:55 PM CDT Asset located in: Humble, TX, USA
5506	Quantity of Misc Parts S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:54 PM CDT Asset located in: Humble, TX, USA	5515	Closing Unit S/N: Not Available C/W: Located in Lane 36 Spot 0, 1 Cylinder Gasoline Engine, Accumulators Usage: Not Available Lot closing time: Fri, Sep 18, 12:55 PM CDT Asset located in: Humble, TX, USA
5507	Quantity of Cat Oil Coolers (Unused) - Fits Cat D6T S/N: Not Available C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:54 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5516	Closing Unit S/N: Not Available C/W: Located in Lane 36 Spot 0, Kohler Magnum 1 Cylinder 16 hp Gasoline Engine, Accumulators Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5518A	Quantity of (50) Atlas Copco 3-7/8 in Drill Bit (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0, 2-3/8 in F91 Connection Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA
5516	Closing Unit S/N: Not Available C/W: Located in Lane 36 Spot 0, Kohler Magnum 1 Cylinder 16 hp Gasoline Engine, Accumulators Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5519	Quantity of (3) Hydraulic Rod Tongs S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA
5516A	Closing Unit S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5519	Quantity of (3) Hydraulic Rod Tongs S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA
5516A	Closing Unit S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5520	96 in Elevator Links (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0, 10 in Straight, Center Latch Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA
5517	Skid Steer Auger S/N: Not Available C/W: Located in Lane 48 Spot 2, (3) Augers, Telescopic Belling Tool, Extension Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5520	96 in Elevator Links (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0, 10 in Straight, Center Latch Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA
5518	Quantity of (8) Pallets of Well Service Rig Parts & Components S/N: Not Available C/W: Located in Lane 54 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5521	96 in Elevator Links (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0, 10 in Straight, Center Latch Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA
5518	Quantity of (8) Pallets of Well Service Rig Parts & Components S/N: Not Available C/W: Located in Lane 54 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5521	96 in Elevator Links (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0, 10 in Straight, Center Latch Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA
5518A	Quantity of (50) Atlas Copco 3-7/8 in Drill Bit (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0, 2-3/8 in F91 Connection Usage: Not Available Lot closing time: Fri, Sep 18, 12:56 PM CDT Asset located in: Humble, TX, USA	5522	Husqvarna FS4800D Walk-Behind Saw S/N: 0012746140 C/W: 36 in Max Blade Diameter, 15 in Max Cutting Depth, Water Hose Connection, Hydraulic Blade Raise / Lower, 2010 US EPA Label, Yanmar 3NND4 4 Cylinder 36.4 kW 2.199 L Diesel Engine Usage: 1,518 Hr Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5522	Husqvarna FS4800D Walk-Behind Saw S/N: 0012746140 C/W: 36 in Max Blade Diameter, 15 in Max Cutting Depth, Water Hose Connection, Hydraulic Blade Raise / Lower, 2010 US EPA Label, Yanmar 3NND4 4 Cylinder 36.4 kW 2.199 L Diesel Engine Usage: 1,518 Hr Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA	5525	Canycon SC75 Stand-On Mini Crawler Concrete Buggy S/N: 7306203 C/W: Located in Lane 0 Spot 0, Hydrostatic Drive, Honda 2 Cylinder Gasoline Engine, 8 in Rubber Tracks Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA
5522A	Columetric Portable Concrete Mixer (Unused) S/N: CV0323 AM-202010H C/W: Chemical Tank, Chute, Spare Parts Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA	5525	Canycon SC75 Stand-On Mini Crawler Concrete Buggy S/N: 7306203 C/W: Located in Lane 0 Spot 0, Hydrostatic Drive, Honda 2 Cylinder Gasoline Engine, 8 in Rubber Tracks Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA
5522A	Columetric Portable Concrete Mixer (Unused) S/N: CV0323 AM-202010H C/W: Chemical Tank, Chute, Spare Parts Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA	5526	2020 Mud Hog MH20 Mortar and Grout Mixer S/N: Not Available C/W: Located in Lane 51 Spot 1, 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA
5523	Gar-Bro Concrete Bucket S/N: 10479B C/W: Located in Lane 53 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA	5526	2020 Mud Hog MH20 Mortar and Grout Mixer S/N: Not Available C/W: Located in Lane 51 Spot 1, 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA
5523	Gar-Bro Concrete Bucket S/N: 10479B C/W: Located in Lane 53 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA	5530	Quantity of (30) 2026 KJ K0204 Steel Frame Concrete Forms (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:58 PM CDT Asset located in: Humble, TX, USA
5524	Canycon SC75 Stand-On Mini Crawler Concrete Buggy S/N: 7303563 C/W: Located in Lane 0 Spot 0, Hydrostatic Drive, Honda 2 Cylinder Gasoline Engine, 7 in Rubber Tracks Usage: 623 Hr Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA	5530	Quantity of (30) 2026 KJ K0204 Steel Frame Concrete Forms (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:58 PM CDT Asset located in: Humble, TX, USA
5524	Canycon SC75 Stand-On Mini Crawler Concrete Buggy S/N: 7303563 C/W: Located in Lane 0 Spot 0, Hydrostatic Drive, Honda 2 Cylinder Gasoline Engine, 7 in Rubber Tracks Usage: 623 Hr Lot closing time: Fri, Sep 18, 12:57 PM CDT Asset located in: Humble, TX, USA	5531	Quantity of (30) 2026 KJ K0204 Steel Frame Concrete Forms (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:58 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5531	Quantity of (30) 2026 KJ K0204 Steel Frame Concrete Forms (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:58 PM CDT Asset located in: Humble, TX, USA	5540A	2020 Wacker Neuson RTLSC3 Trench Compactor S/N: 24522217 C/W: Located in Lane 51, 2019 US EPA Label, 3 Cylinder 10.28 L Diesel Engine, 24 in / 33 in Drums, Remote Control w/ Cord Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA
5536	2026 SDLOOL SL90B Power Trowel (Unused) S/N: SFMGJ2605108 C/W: 35 in, Loncin 6 hp Gas Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA	5540A	2020 Wacker Neuson RTLSC3 Trench Compactor S/N: 24522217 C/W: Located in Lane 51, 2019 US EPA Label, 3 Cylinder 10.28 L Diesel Engine, 24 in / 33 in Drums, Remote Control w/ Cord Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA
5536	2026 SDLOOL SL90B Power Trowel (Unused) S/N: SFMGJ2605108 C/W: 35 in, Loncin 6 hp Gas Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA	5542	Bomag BVP 18/45 Vibratory Plate Compactor S/N: 101630161475 C/W: Located in Lane 51 Spot 1, 2019 US EPA Label, Honda GX 160 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA
5538	Atlas Copco LP13-30 P Hydraulic Power Pack S/N: Not Available C/W: Located in Lane 53 Spot 0, 2018 US EPA Label, Honda GX 390 1 Cylinder 389 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA	5542	Bomag BVP 18/45 Vibratory Plate Compactor S/N: 101630161475 C/W: Located in Lane 51 Spot 1, 2019 US EPA Label, Honda GX 160 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA
5538	Atlas Copco LP13-30 P Hydraulic Power Pack S/N: Not Available C/W: Located in Lane 53 Spot 0, 2018 US EPA Label, Honda GX 390 1 Cylinder 389 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA	5543	2026 Powertek MS160 Reversible Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, 1 Cylinder 9 hp 270 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA
5539	Enerpac ZE2 Hydraulic Electric Water Pump S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA	5543	2026 Powertek MS160 Reversible Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, 1 Cylinder 9 hp 270 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA
5539	Enerpac ZE2 Hydraulic Electric Water Pump S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 12:59 PM CDT Asset located in: Humble, TX, USA	5544	2026 ATS POWER ATS-PC90 Heavy Duty Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5544	2026 ATS POWER ATS-PC90 Heavy Duty Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA	5547	Quantity of (4) 2026 STARVOX HCR-110 Jumping Jack Tamper (Unused) S/N: STV2026JT02585 C/W: Located in Lane 47 Spot 0, 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA
5545	2026 ATS POWER ATS-PC90 Heavy Duty Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA	5548	Quantity of (4) 2026 STARVOX HCR-110 Jumping Jack Tamper (Unused) S/N: STV2026JT02621 C/W: Located in Lane 47 Spot 0, 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA
5545	2026 ATS POWER ATS-PC90 Heavy Duty Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA	5548	Quantity of (4) 2026 STARVOX HCR-110 Jumping Jack Tamper (Unused) S/N: STV2026JT02621 C/W: Located in Lane 47 Spot 0, 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA
5546	Mustang LF88D Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Loncin 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA	5549	2015 Bomag BT65 Jumping Jack Tamper S/N: 10154135660 C/W: Located in Lane 51 Spot 1, 2014 US EPA Label, Honda GX100 Gasoline Engine Usage: 124 Hr Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA
5546	Mustang LF88D Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Loncin 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA	5549	2015 Bomag BT65 Jumping Jack Tamper S/N: 10154135660 C/W: Located in Lane 51 Spot 1, 2014 US EPA Label, Honda GX100 Gasoline Engine Usage: 124 Hr Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA
5547	Quantity of (4) 2026 STARVOX HCR-110 Jumping Jack Tamper (Unused) S/N: STV2026JT02585 C/W: Located in Lane 47 Spot 0, 1 Cylinder 6.5 hp Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:00 PM CDT Asset located in: Humble, TX, USA	5552A	Quantity of (2) 2025 Kit Containers 5 ft 4 in x 8 ft 10 in (1 in Thick) Road Steel Plates S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA
		5552A	Quantity of (2) 2025 Kit Containers 5 ft 4 in x 8 ft 10 in (1 in Thick) Road Steel Plates S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5552B	Quantity of (2) 2025 Kit Containers 5 ft x 7 ft 7 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA	5552F	Hydraulic Live Bottom Bed S/N: Not Available C/W: Located in Lane 52 Spot 0, Steel, Hydraulic 22 ft 3 in Body Length Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA
5552B	Quantity of (2) 2025 Kit Containers 5 ft x 7 ft 7 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA	5553	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: 1629 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA
5552C	2025 Kit Containers 6 ft 1 in x 6 ft 11 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA	5554	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: 1628 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA
5552C	2025 Kit Containers 6 ft 1 in x 6 ft 11 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA	5555	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: 1630 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA
5552D	Quantity of (2) 2025 Kit Containers 6 ft x 8 ft 2 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA	5556	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: 1631 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:02 PM CDT Asset located in: Humble, TX, USA
5552D	Quantity of (2) 2025 Kit Containers 6 ft x 8 ft 2 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA	5557	2025 Neks Pneumatic Fifth Wheel Wrecker Attachment (Unused) S/N: 004B C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:02 PM CDT Asset located in: Humble, TX, USA
5552E	Quantity of (2) 2025 Kit Containers 5 ft x 7 ft 8 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA	5558	2026 GIYI GY-TE780 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260693 C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:02 PM CDT Asset located in: Humble, TX, USA
5552E	Quantity of (2) 2025 Kit Containers 5 ft x 7 ft 8 in (1 in Thick) Road Steel Plates (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:01 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5559	2026 GIYI GY-TE31 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260701 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:02 PM CDT Asset located in: Humble, TX, USA	5562C	Waste Container S/N: Not Available C/W: Located in Lane 53 Spot 1, Polyethylene Spill Container, 73 in x 29 in x 80 in, 3,000 gal Usage: Not Available Lot closing time: Fri, Sep 18, 01:03 PM CDT Asset located in: Humble, TX, USA
5560	2026 GIYI GY-TE31 Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260703 C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:02 PM CDT Asset located in: Humble, TX, USA	5562C	Waste Container S/N: Not Available C/W: Located in Lane 53 Spot 1, Polyethylene Spill Container, 73 in x 29 in x 80 in, 3,000 gal Usage: Not Available Lot closing time: Fri, Sep 18, 01:03 PM CDT Asset located in: Humble, TX, USA
5561	2026 GIYI GY-TE31 Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC260702 C/W: Located in Lane 52 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 01:02 PM CDT Asset located in: Humble, TX, USA	5569	Quantity of (4) 4000 Gallon Vertical Steel Storage Tank S/N: 19120 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA
5562	PROMECH Hydraulic Fifth Wheel Wrecker Attachment (Unused) S/N: FWWA26525 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:03 PM CDT Asset located in: Humble, TX, USA	5569	Quantity of (4) 4000 Gallon Vertical Steel Storage Tank S/N: 19120 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA
5562A	2026 X-STAR 300 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Lot closing time: Fri, Sep 18, 01:03 PM CDT Asset located in: Humble, TX, USA	5570	125 lbs Hitch mounted Salt Spreader (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA
5562A	2026 X-STAR 300 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Lot closing time: Fri, Sep 18, 01:03 PM CDT Asset located in: Humble, TX, USA	5570	125 lbs Hitch mounted Salt Spreader (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA
5562B	200 gal Skid Mounted Steel Diesel Fuel Tank S/N: Not Available C/W: Spill Containment Usage: Not Available Lot closing time: Fri, Sep 18, 01:03 PM CDT Asset located in: Humble, TX, USA	5571	125 lbs Hitch mounted Salt Spreader (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA
5562B	200 gal Skid Mounted Steel Diesel Fuel Tank S/N: Not Available C/W: Spill Containment Usage: Not Available Lot closing time: Fri, Sep 18, 01:03 PM CDT Asset located in: Humble, TX, USA	5571	125 lbs Hitch mounted Salt Spreader (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5572	J & J Truck Vacuum Tank S/N: TS008530 C/W: Located in Lane 51 Spot 0, Steel, 20 ft Body Length Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA	5580	Quantity of Trailer Ramps (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 01:05 PM CDT Asset located in: Humble, TX, USA
5573	Morgan Van Truck Body S/N: MPA05VB82094001 C/W: Located in Lane 51 Spot 0, 20 ft Body Length, Liftgate Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA	5581	Etnyre 3 ft Flip-Up Neck Extension S/N: Not Available C/W: Located in Lane 25 Spot 0, Steel Usage: Not Available Lot closing time: Fri, Sep 18, 01:05 PM CDT Asset located in: Humble, TX, USA
5574	Supreme Refrigerated Truck Body S/N: 50250049 C/W: Located in Lane 52 Spot 1, 16 ft Body Length, Carrier Reefer Unit, Liftgate, Curbside Door Usage: Not Available Notes: BILL OF SALE ONLY Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA	5581A	Cummins Engine S/N: Not Available C/W: Located in Lane 56, Cummins 6 Cylinder Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:05 PM CDT Asset located in: Humble, TX, USA
5575	Quantity of Peterbilt Cab, Sleeper, Truck Frame & Axle S/N: D558296 C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:04 PM CDT Asset located in: Humble, TX, USA	5582	Quantity of (5) BMW Motorcycle Engine S/N: Not Available C/W: Located in Lane 46 Spot 0, 2 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:06 PM CDT Asset located in: Humble, TX, USA
5576	650 hp PTO Driven Concrete Pump Truck Pump S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:05 PM CDT Asset located in: Humble, TX, USA	5583	Cummins NTC-400 Engine S/N: 17159 C/W: Located in Lane 54 Spot 3, 1985 US EPA Label, NTC-400 6 Cylinder 400 hp 855 cid Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 01:06 PM CDT Asset located in: Humble, TX, USA
5577	T/A Assembly S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 01:05 PM CDT Asset located in: Humble, TX, USA	5584	Cat (Used) Transmission - Fits Cat D5 S/N: 1CF05270 C/W: Located in Lane 46 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:06 PM CDT Asset located in: Humble, TX, USA
5578	Trailer Landing Gear S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:05 PM CDT Asset located in: Humble, TX, USA	5585	Quantity of (4) Trailquest 205/75R15 Tires (Unused) S/N: Not Available C/W: Located in Lane 36 Spot 0, All Tires with Wheels Usage: Not Available Lot closing time: Fri, Sep 18, 01:06 PM CDT Asset located in: Humble, TX, USA
5579	Trailer Landing Gear S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:05 PM CDT Asset located in: Humble, TX, USA	5586	Quantity of (4) Trailquest 235/80R16 Tires (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, All Tires with Wheels, ST205X75R-15 6-PL RADIAL TIRE 5 ON 5 SILVER MODULAR WHEEL (T) Usage: Not Available Lot closing time: Fri, Sep 18, 01:06 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5588	2026 STARVOX JL830 2 Post 10000 lb Vehicle Lift (Unused) S/N: STV2026TC02221 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:06 PM CDT Asset located in: Humble, TX, USA	5591	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262280 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA
5588	2026 STARVOX JL830 2 Post 10000 lb Vehicle Lift (Unused) S/N: STV2026TC02221 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:06 PM CDT Asset located in: Humble, TX, USA	5591	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262280 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA
5589	2026 STARVOX JL830 2 Post 10000 lb Vehicle Lift (Unused) S/N: STV2026TC02223 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5592	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA
5589	2026 STARVOX JL830 2 Post 10000 lb Vehicle Lift (Unused) S/N: STV2026TC02223 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5592	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA
5590	2026 STARVOX JL830 2 Post 10000 lb Vehicle Lift (Unused) S/N: STV2026TC02222 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5593	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262055 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA
5590	2026 STARVOX JL830 2 Post 10000 lb Vehicle Lift (Unused) S/N: STV2026TC02222 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5593	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262055 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5594	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5597	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA
5594	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5597	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA
5595	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5598	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA
5595	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:07 PM CDT Asset located in: Humble, TX, USA	5598	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA
5596	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA	5599	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA
5596	2026 TPL-BLUE 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA	5599	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5600	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA	5603	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA
5600	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA	5603	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA
5601	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262273 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA	5604	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA
5601	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262273 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:08 PM CDT Asset located in: Humble, TX, USA	5604	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA
5602	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262057 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5605	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA
5602	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262057 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5605	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5606	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5609	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262278 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA
5606	2026 TPL-RED 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5609	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: 100Y20262278 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA
5607	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5610	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA
5607	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5610	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA
5608	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5611	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA
5608	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:09 PM CDT Asset located in: Humble, TX, USA	5611	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5612	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5615	2026 Powertek PT620 Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA
5612	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5616	2026 Powertek PT620 Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA
5613	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5616	2026 Powertek PT620 Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA
5613	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5617	2026 Powertek PT620 Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA
5613	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5617	2026 Powertek PT620 Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA
5614	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5618	2026 TC-GRAY Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA
5614	2026 TPL-GRAY 2 Post 10000 lb Vehicle Lift (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5618	2026 TC-GRAY Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA
5615	2026 Powertek PT620 Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:10 PM CDT Asset located in: Humble, TX, USA	5619	2026 TC-GRAY Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5619	2026 TC-GRAY Tire Changer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA	5623	2026 TBM-RED Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA
5620	2026 Powertek PT99 Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA	5624	2026 TBM-BLUE Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA
5620	2026 Powertek PT99 Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA	5624	2026 TBM-BLUE Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA
5621	2026 TBM-RED Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA	5625	2026 TBM-GRAY Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA
5621	2026 TBM-RED Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:11 PM CDT Asset located in: Humble, TX, USA	5625	2026 TBM-GRAY Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA
5622	2026 TBM-RED Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA	5626	2026 TBM-GRAY Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA
5622	2026 TBM-RED Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA	5626	2026 TBM-GRAY Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA
5623	2026 TBM-RED Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5627	2026 TBM Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA	5631	Ingersoll Rand SP20058 Electric 1/2 ton Material Hoist S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA
5627	2026 TBM Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA	5631	Ingersoll Rand SP20058 Electric 1/2 ton Material Hoist S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA
5628	2026 TBM Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA	5632	2026 KJ K3156 31 ft x 56 ft Heavy Duty Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA
5628	2026 TBM Wheel Balancer (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:12 PM CDT Asset located in: Humble, TX, USA	5632	2026 KJ K3156 31 ft x 56 ft Heavy Duty Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA
5629	Ingersoll Rand SP20058 Electric 1/2 ton Material Hoist S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA	5635	2026 MTO A2545G 25 ft x 46 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA
5629	Ingersoll Rand SP20058 Electric 1/2 ton Material Hoist S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA	5635	2026 MTO A2545G 25 ft x 46 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA
5630	Ingersoll Rand SP20058 Electric 1/2 ton Material Hoist S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA		
5630	Ingersoll Rand SP20058 Electric 1/2 ton Material Hoist S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:13 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5636	2026 KJ K2545G 25 ft x 45 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 04, 15 ft Total Height, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:14 PM CDT Asset located in: Humble, TX, USA	5649	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA
5636	2026 KJ K2545G 25 ft x 45 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 04, 15 ft Total Height, Quantity of (2) Boxes - Builds (1) Storage Building ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:14 PM CDT Asset located in: Humble, TX, USA	5649	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA
5643	2026 Gold Mountain 304015R-300g PE 30 ft x 40 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 15 ft Total Height, Comes With: Dome roof frame, snow rating: 180kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:15 PM CDT Asset located in: Humble, TX, USA	5649A	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA
5643	2026 Gold Mountain 304015R-300g PE 30 ft x 40 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 15 ft Total Height, Comes With: Dome roof frame, snow rating: 180kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:15 PM CDT Asset located in: Humble, TX, USA	5649A	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA
5646	2026 KJ K5100 49 ft x 103 ft Prefabricated Metal Frame Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 22 ft Total Height, 16 ft Sidewall Height, Quantity of (3) Boxes - Builds (1) Storage Building Usage: Not Available Lot closing time: Fri, Sep 18, 01:15 PM CDT Asset located in: Humble, TX, USA	5649B	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA
5646	2026 KJ K5100 49 ft x 103 ft Prefabricated Metal Frame Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 22 ft Total Height, 16 ft Sidewall Height, Quantity of (3) Boxes - Builds (1) Storage Building Usage: Not Available Lot closing time: Fri, Sep 18, 01:15 PM CDT Asset located in: Humble, TX, USA	5649B	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5651	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA	5658A	KJ K4036 36 ft x 40 ft Container Shelter (Unused) S/N: Not Available C/W: 17 ft Top of Container to Peak Height, 13 ft Sidewall Height, Quantity of (2) Boxes - Builds (1) Container Shelter ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:17 PM CDT Asset located in: Lake Worth, TX, USA
5651	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA	5658A	KJ K4036 36 ft x 40 ft Container Shelter (Unused) S/N: Not Available C/W: 17 ft Top of Container to Peak Height, 13 ft Sidewall Height, Quantity of (2) Boxes - Builds (1) Container Shelter ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:17 PM CDT Asset located in: Lake Worth, TX, USA
5651A	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA	5658B	KJ K4036 36 ft x 40 ft Container Shelter (Unused) S/N: Not Available C/W: 17 ft Top of Container to Peak Height, 13 ft Sidewall Height, Quantity of (2) Boxes - Builds (1) Container Shelter ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:17 PM CDT Asset located in: Lake Worth, TX, USA
5651A	2026 Gold Mountain 203012R-300gsm PE 20 ft x 30 ft Dome Shelter Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, Comes With: Dome roof frame, snow rating: 200kg/#. Usage: Not Available Lot closing time: Fri, Sep 18, 01:16 PM CDT Asset located in: Humble, TX, USA	5658B	KJ K4036 36 ft x 40 ft Container Shelter (Unused) S/N: Not Available C/W: 17 ft Top of Container to Peak Height, 13 ft Sidewall Height, Quantity of (2) Boxes - Builds (1) Container Shelter ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:17 PM CDT Asset located in: Lake Worth, TX, USA
5658	2026 KJ K0039 39 ft x 39 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, 13 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:17 PM CDT Asset located in: Humble, TX, USA	5671	Gold Mountain 20 ft x 40 ft Single-Truss Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA
5658	2026 KJ K0039 39 ft x 39 ft Metal Garage Storage Building (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, 13 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:17 PM CDT Asset located in: Humble, TX, USA	5671	Gold Mountain 20 ft x 40 ft Single-Truss Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5673A	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA	5674B	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA
5673A	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA	5674B	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA
5673B	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA	5680	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA
5673B	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA	5680	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA
5674A	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA	5680A	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA
5674A	2026 Gold Mountain C2040-300gsm PE 20 ft x 40 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:19 PM CDT Asset located in: Humble, TX, USA	5680A	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5680B	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA	5681B	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:21 PM CDT Asset located in: Humble, TX, USA
5680B	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA	5681B	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:21 PM CDT Asset located in: Humble, TX, USA
5681	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA	5696	2026 KJ K4230W Triple Garage Metal Storage Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA
5681	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:20 PM CDT Asset located in: Humble, TX, USA	5696	2026 KJ K4230W Triple Garage Metal Storage Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA
5681A	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:21 PM CDT Asset located in: Humble, TX, USA	5697	2026 KJ K4230G Triple Garage Metal Storage Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA
5681A	2026 Gold Mountain C2020-300gsm PE 20 ft x 20 ft Dome Container Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Comes with: PE fabric galvanized tube ,UV-resistance & fire-retardant. Usage: Not Available Lot closing time: Fri, Sep 18, 01:21 PM CDT Asset located in: Humble, TX, USA	5697	2026 KJ K4230G Triple Garage Metal Storage Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Metal Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5698	2026 MTO A4230G Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA	5701A	2026 SKLP SK-S5030 50 ft x 30 ft Double Garage Metal Shed (Unused) S/N: F18945 C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA
5698	2026 MTO A4230G Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA	5701A	2026 SKLP SK-S5030 50 ft x 30 ft Double Garage Metal Shed (Unused) S/N: F18945 C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA
5699	2026 SDLanch C4230FT Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA	5702	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA
5699	2026 SDLanch C4230FT Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA	5702	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA
5701	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 47, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA	5703	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA
5701	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 47, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:23 PM CDT Asset located in: Humble, TX, USA	5703	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5704	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA	5711	2026 MTO A4525 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA
5704	2026 SDL4230TGMS Triple Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA	5711	2026 MTO A4525 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA
5705	2026 MTO A0039 Metal Barn Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA	5713	2026 KJ K4525 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA
5705	2026 MTO A0039 Metal Barn Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:24 PM CDT Asset located in: Humble, TX, USA	5713	2026 KJ K4525 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA
5710	2026 MTO A4525G Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA	5714	2026 MTO A3325 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA
5710	2026 MTO A4525G Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA	5714	2026 MTO A3325 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5715	2026 MTO A3325 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA	5718	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA
5715	2026 MTO A3325 Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:25 PM CDT Asset located in: Humble, TX, USA	5718	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA
5716	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA	5719	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA
5716	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA	5719	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA
5717	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA	5720	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA
5717	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA	5720	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5721	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA	5746	2026 MTO A1220 Single Garage Metal (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:30 PM CDT Asset located in: Humble, TX, USA
5721	2026 SDL2533DGMS Double Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Shed ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:26 PM CDT Asset located in: Humble, TX, USA	5746	2026 MTO A1220 Single Garage Metal (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:30 PM CDT Asset located in: Humble, TX, USA
5736	2026 MTO A2223 Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:29 PM CDT Asset located in: Humble, TX, USA	5747	2026 MTO A1220 Single Garage Metal (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:30 PM CDT Asset located in: Humble, TX, USA
5736	2026 MTO A2223 Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:29 PM CDT Asset located in: Humble, TX, USA	5747	2026 MTO A1220 Single Garage Metal (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:30 PM CDT Asset located in: Humble, TX, USA
5740	2026 MTO A2223G Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:29 PM CDT Asset located in: Humble, TX, USA	5752	2026 KJ K4120 20 ft x 41 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA
5740	2026 MTO A2223G Double Garage Metal Storage Building (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:29 PM CDT Asset located in: Humble, TX, USA	5752	2026 KJ K4120 20 ft x 41 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5753	2026 KJ K4120 20 ft x 41 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA	5756	2026 MTO A4020 20 ft x 40 ft (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA
5753	2026 KJ K4120 20 ft x 41 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA	5756	2026 MTO A4020 20 ft x 40 ft (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA
5754	2026 SDLC2040FT 20 ft x 40 ft Multi-Use Metal Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 04, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA	5756A	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA
5754	2026 SDLC2040FT 20 ft x 40 ft Multi-Use Metal Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 04, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA	5756A	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA
5755	2026 SDLC2040FT 20 ft x 40 ft Multi-Use Metal Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA	5756B	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA
5755	2026 SDLC2040FT 20 ft x 40 ft Multi-Use Metal Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA	5756B	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA
5755	2026 SDLC2040FT 20 ft x 40 ft Multi-Use Metal Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:31 PM CDT Asset located in: Humble, TX, USA	5756C	2026 SKLP SK-ZP20 20 ft x 30 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5756C	2026 SKLP SK-ZP20 20 ft x 30 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA	5762	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA
5756D	2026 SKLP SK-ZP20 20 ft x 30 ft Carport (Unused) S/N: F09602 C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 17 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA	5763	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14799 C/W: Located in Lane 50 Spot 4, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA
5756D	2026 SKLP SK-ZP20 20 ft x 30 ft Carport (Unused) S/N: F09602 C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 17 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA	5763	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14799 C/W: Located in Lane 50 Spot 4, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA
5761	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14798 C/W: Located in Lane 50 Spot 4, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA	5764	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14801 C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA
5761	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14798 C/W: Located in Lane 50 Spot 4, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:32 PM CDT Asset located in: Humble, TX, USA	5764	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14801 C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA
5762	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA	5765	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport S/N: Not Available C/W: Located in Lane 47 Spot 0, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5765	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport S/N: Not Available C/W: Located in Lane 47 Spot 0, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA	5770	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA
5766	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14800 C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA	5771	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA
5766	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Enclosed Carport (Unused) S/N: F14800 C/W: Located in Lane 50 Spot 3, 12 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:33 PM CDT Asset located in: Humble, TX, USA	5771	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA
5769	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA	5772	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA
5769	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA	5772	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA
5770	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA	5774	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5774	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA	5777	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA
5775	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA	5778	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA
5775	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:34 PM CDT Asset located in: Humble, TX, USA	5778	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA
5776	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA	5779	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA
5776	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA	5779	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA
5777	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA	5780	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5780	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA	5789	Veikous 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA
5781	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA	5790	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA
5781	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA	5790	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA
5781	2026 SDLC2030FT 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 12 ft 6 in Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:35 PM CDT Asset located in: Humble, TX, USA	5791	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA
5784	2026 KJ K3020 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:36 PM CDT Asset located in: Humble, TX, USA	5791	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA
5784	2026 KJ K3020 20 ft x 30 ft Enclosed Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, 14 ft Total Height, 10 ft Sidewall Height, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:36 PM CDT Asset located in: Humble, TX, USA	5792	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA
5789	Veikous 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA	5792	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5793	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA	5796	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA
5793	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA	5797	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA
5794	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA	5797	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA
5794	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA	5798	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA
5795	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA	5798	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA
5795	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:37 PM CDT Asset located in: Humble, TX, USA	5799	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA
5796	2026 SDLC2020 20 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA	5799	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5800	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA	5803	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA
5800	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA	5804	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA
5801	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA	5804	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA
5801	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:38 PM CDT Asset located in: Humble, TX, USA	5805	2026 SDLANCH SDLG1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA
5802	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA	5805	2026 SDLANCH SDLG1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA
5802	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA	5806	2026 SDLANCH SDLG1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA
5803	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA	5806	2026 SDLANCH SDLG1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5807	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA	5810	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:40 PM CDT Asset located in: Humble, TX, USA
5807	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA	5811	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:40 PM CDT Asset located in: Humble, TX, USA
5808	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA	5811	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:40 PM CDT Asset located in: Humble, TX, USA
5808	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:39 PM CDT Asset located in: Humble, TX, USA	5817	2026 MTO A1119 11 ft x 19 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA
5809	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:40 PM CDT Asset located in: Humble, TX, USA	5817	2026 MTO A1119 11 ft x 19 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA
5809	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:40 PM CDT Asset located in: Humble, TX, USA	5818	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01747 C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA
5810	2026 SDLC1220 12 ft x 20 ft Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:40 PM CDT Asset located in: Humble, TX, USA	5818	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01747 C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5819	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01748 C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA	5822	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01627 C/W: Located in Lane 50 Spot 4, 168 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA
5819	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01748 C/W: Located in Lane 50 Spot 4, 14 ft Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA	5823	2026 SKLP SK-SC40 All-Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA
5820	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01626 C/W: Located in Lane 50 Spot 4, 168 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA	5823	2026 SKLP SK-SC40 All-Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA
5820	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01626 C/W: Located in Lane 50 Spot 4, 168 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA	5824	2026 SKLP SK-SC40 All-Steel Carport S/N: F09603 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA
5821	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01554 C/W: Located in Lane 50 Spot 4, 168 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA	5824	2026 SKLP SK-SC40 All-Steel Carport S/N: F09603 C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA
5821	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01554 C/W: Located in Lane 50 Spot 4, 168 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:41 PM CDT Asset located in: Humble, TX, USA	5825	2026 SKLP SK-SC40 All-Steel Carport (Unused) S/N: E86597 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA
5822	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F01627 C/W: Located in Lane 50 Spot 4, 168 in Total Height Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA	5825	2026 SKLP SK-SC40 All-Steel Carport (Unused) S/N: E86597 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5826	2026 SKLP SK-SC40 All-Steel Carport (Unused) S/N: F09604 C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA	5843	2026 MTO A1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA
5826	2026 SKLP SK-SC40 All-Steel Carport (Unused) S/N: F09604 C/W: Located in Lane 50 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:42 PM CDT Asset located in: Humble, TX, USA	5843	2026 MTO A1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA
5835	2026 KJ K2512 12 ft x 25 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:43 PM CDT Asset located in: Humble, TX, USA	5844	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14796 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA
5835	2026 KJ K2512 12 ft x 25 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:43 PM CDT Asset located in: Humble, TX, USA	5844	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14796 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA
5841	2026 MTO A2512 25 ft x 12 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:44 PM CDT Asset located in: Humble, TX, USA	5845	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14794 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA
5841	2026 MTO A2512 25 ft x 12 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:44 PM CDT Asset located in: Humble, TX, USA	5845	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14794 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5846	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14792 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA	5849	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14793 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA
5846	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14792 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA	5849	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14793 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA
5847	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14795 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA	5849A	SDLANCH SDLG1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA
5847	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14795 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA	5849A	SDLANCH SDLG1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA
5848	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14797 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA	5849B	2026 KJ K2039 39 ft x 20 ft Module Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA
5848	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14797 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA	5849B	2026 KJ K2039 39 ft x 20 ft Module Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA
5848	2026 SKLP SK-LS20 20 ft x 12 ft Metal Livestock Shelter (Unused) S/N: F14797 C/W: Located in Lane 50 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:45 PM CDT Asset located in: Humble, TX, USA	5854	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5854	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA	5856A	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5855	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA	5856A	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5855	2026 SDLGM1310F 13 ft x 10 ft Galvanized Metal Livestock Shelter (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:46 PM CDT Asset located in: Humble, TX, USA	5856B	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5855A	20 ft x 8 ft Skid-Mounted Portable Office Building (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 0, (1) Offices, Air Conditioner Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856B	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5855A	20 ft x 8 ft Skid-Mounted Portable Office Building (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 0, (1) Offices, Air Conditioner Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856C	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856	20 ft x 8 ft Office Building (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 0, Air Conditioner Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856C	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856	20 ft x 8 ft Office Building (Unused) S/N: Not Available C/W: Located in Lane 73 Spot 0, Air Conditioner Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856D	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
		5856D	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5856E	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856J	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856E	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856J	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856F	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856K	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856F	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856K	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856G	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856L	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856G	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5856L	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856H	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5857	2026 KJ K4080 80 ft x 40 ft Prefabricated Metal Frame (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Prefabricated Metal Frame ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA
5856H	Guard Shack S/N: Not Available C/W: Located in Lane 73 Spot 0, Pre-wired Electrical Outlets, Insulated Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5857	2026 KJ K4080 80 ft x 40 ft Prefabricated Metal Frame (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, Quantity of (2) Boxes - Builds (1) Prefabricated Metal Frame ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:47 PM CDT Asset located in: Humble, TX, USA	5873	2026 Gold Mountain M202010 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, (1.525m Arch space) Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA
5866	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:48 PM CDT Asset located in: Humble, TX, USA	5873	2026 Gold Mountain M202010 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, (1.525m Arch space) Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA
5866	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:48 PM CDT Asset located in: Humble, TX, USA	5874	2026 Gold Mountain M122009 12 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, (1.525m Arch space) Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA
5867	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:48 PM CDT Asset located in: Humble, TX, USA	5874	2026 Gold Mountain M122009 12 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 4, (1.525m Arch space) Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA
5867	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:48 PM CDT Asset located in: Humble, TX, USA	5875	2026 Gold Mountain M122009 12 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 04, (1.525m Arch space) Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA
5871	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA	5875	2026 Gold Mountain M122009 12 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 04, (1.525m Arch space) Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA
5871	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA	5875A	2026 Bastone 110V 7 ft x 5 ft Type A1 Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA
5872	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03 Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA		
5872	2026 Single Garage Metal Shed (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 03 Usage: Not Available Lot closing time: Fri, Sep 18, 01:49 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5875A	2026 Bastone 110V 7 ft x 5 ft Type A1 Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA	5885	Wokin 6-Drawer 163 pcs. Rolling Tool Cabinet (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA
5875B	2026 Bastone 110V 7 ft x 5 ft Type A1 Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA	5886	WATERLOO W500 SERIES 8-Drawer 52 in Tool Cabinet (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA
5875B	2026 Bastone 110V 7 ft x 5 ft Type A1 Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA	5886	WATERLOO W500 SERIES 8-Drawer 52 in Tool Cabinet (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA
5875C	2026 Bastone 110V 7 ft x 4 ft Double Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA	5887	Tool Pro 8-Drawer 42 in Tool Cabinet S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA
5875C	2026 Bastone 110V 7 ft x 4 ft Double Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA	5887	Tool Pro 8-Drawer 42 in Tool Cabinet S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA
5879	2026 Bastone 110V 4 ft 2 in x 3 ft 7 in Single Type C Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Size: L1300*W1080*H2360mm Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA	5888	2026 10FT-15D-2 10 ft 15-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 112 in x 26 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA
5879	2026 Bastone 110V 4 ft 2 in x 3 ft 7 in Single Type C Portable Toilet (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Size: L1300*W1080*H2360mm Usage: Not Available Lot closing time: Fri, Sep 18, 01:50 PM CDT Asset located in: Humble, TX, USA	5888	2026 10FT-15D-2 10 ft 15-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 112 in x 26 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA
5885	Wokin 6-Drawer 163 pcs. Rolling Tool Cabinet (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 01:51 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5889	2026 10FT-15D-2 10 ft 15-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 112 in x 26 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5892	2026 H9.5FT-30D-01B 9 ft 6 in 30-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel table top. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA
5889	2026 10FT-15D-2 10 ft 15-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 112 in x 26 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5892	2026 H9.5FT-30D-01B 9 ft 6 in 30-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel table top. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA
5890	2026 10FT-18D-2B 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5893	2026 9FT-34D 9 ft 34-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA
5890	2026 10FT-18D-2B 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5893	2026 9FT-34D 9 ft 34-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA
5891	2026 10FT-18D-2B 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5894	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA
5891	2026 10FT-18D-2B 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5894	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5895	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5898	2026 7FT-18D 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 86*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA
5895	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:52 PM CDT Asset located in: Humble, TX, USA	5898	2026 7FT-18D 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 86*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA
5896	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87 in x 23 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA	5899	2026 7FT-20D 7 ft 20-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA
5896	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87 in x 23 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA	5899	2026 7FT-20D 7 ft 20-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA
5897	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87 in x 23 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA	5900	2026 7FT-20D 7 ft 20-Drawer Stainless Steel Workbench S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA
5897	2026 7FT-10D 7 ft 10-Drawer Stainless Steel Workbench (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, 87 in x 23 in x 39 in. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA	5900	2026 7FT-20D 7 ft 20-Drawer Stainless Steel Workbench S/N: Not Available C/W: Located in Lane 51 Spot 3, 87*23*39 inch. Packed in Plastics. Drawers with lock and Anti-slip inners. Using new 3 rail sliding. Stainless steel. Usage: Not Available Lot closing time: Fri, Sep 18, 01:53 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5913	Quantity of (24) Rolls of Chicken Stucco Wire S/N: Not Available C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 01:55 PM CDT Asset located in: Humble, TX, USA	5918	Quantity of (10) 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Galvanized Round Tube,Diameter 38mm Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA
5913	Quantity of (24) Rolls of Chicken Stucco Wire S/N: Not Available C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 01:55 PM CDT Asset located in: Humble, TX, USA	5919	Quantity of (5) 8 ft x 4 ft Corral Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA
5917	Quantity of (28) 2026 STARVOX SV0510-28 10 ft x 5 ft Powder Coated Livestock Panel (Unused) S/N: SV2026LTP01006 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA	5919	Quantity of (5) 8 ft x 4 ft Corral Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA
5917	Quantity of (28) 2026 STARVOX SV0510-28 10 ft x 5 ft Powder Coated Livestock Panel (Unused) S/N: SV2026LTP01006 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA	5920	Quantity of (5) 8 ft x 4 ft Galvanized Corral Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Diameter 38mm 10 Accessories/5Pcs Set Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA
5917A	Quantity of (56) 2026 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA	5920	Quantity of (5) 8 ft x 4 ft Galvanized Corral Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Diameter 38mm 10 Accessories/5Pcs Set Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA
5917A	Quantity of (56) 2026 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA	5921	Quantity of (30) 2026 MTO A0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA
5918	Quantity of (10) 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Galvanized Round Tube,Diameter 38mm Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA	5921	Quantity of (30) 2026 MTO A0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:56 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5922	Quantity of (30) 2026 MTO A0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:57 PM CDT Asset located in: Humble, TX, USA	5929	Quantity of (18) 10 ft x 7 ft 6 in Galvanized Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Fencing Kits Upgraded - Wider & Thicker for Extra Strength and Stability - Cross Beam: 3.15 in, Vertical Pipe:1.58 in, 18 PCS Fence Panels 19 PCS Posts w/ Connectors, Lead Free Powder Coated Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5922	Quantity of (30) 2026 MTO A0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:57 PM CDT Asset located in: Humble, TX, USA	5929	Quantity of (18) 10 ft x 7 ft 6 in Galvanized Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Fencing Kits Upgraded - Wider & Thicker for Extra Strength and Stability - Cross Beam: 3.15 in, Vertical Pipe:1.58 in, 18 PCS Fence Panels 19 PCS Posts w/ Connectors, Lead Free Powder Coated Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5923	Quantity of (30) 2026 STARVOX SV0810-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: SV2026CSF010051 C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:57 PM CDT Asset located in: Humble, TX, USA	5930	Quantity of (18) 10 ft x 7 ft 6 in Galvanized Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Fencing Kits Upgraded - Wider & Thicker for Extra Strength and Stability - Cross Beam: 3.15 in, Vertical Pipe:1.58 in, 18 PCS Fence Panels 19 PCS Posts w/ Connectors, Lead Free Powder Coated Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5923	Quantity of (30) 2026 STARVOX SV0810-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: SV2026CSF010051 C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:57 PM CDT Asset located in: Humble, TX, USA	5930	Quantity of (18) 10 ft x 7 ft 6 in Galvanized Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Fencing Kits Upgraded - Wider & Thicker for Extra Strength and Stability - Cross Beam: 3.15 in, Vertical Pipe:1.58 in, 18 PCS Fence Panels 19 PCS Posts w/ Connectors, Lead Free Powder Coated Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5924	Quantity of (30) 2026 STARVOX SV0810-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: SV2026CSF010060 C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:57 PM CDT Asset located in: Humble, TX, USA	5930A	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5930A	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA	5930D	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5930B	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA	5931	Quantity of Betafence 8 ft x 6 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5930B	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA	5931	Quantity of Betafence 8 ft x 6 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5930C	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA	5932	Quantity of Betafence 8 ft x 6 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5930C	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA	5932	Quantity of Betafence 8 ft x 6 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA
5930C	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA	5941	Quantity of (10) 7.9 ft x 3.8 ft Galvanized Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:59 PM CDT Asset located in: Humble, TX, USA
5930D	Quantity of (30) 2026 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, (30) Fence Panels, (31) Post's w/Connectors ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 01:58 PM CDT Asset located in: Humble, TX, USA	5941	Quantity of (10) 7.9 ft x 3.8 ft Galvanized Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 01:59 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5942	Quantity of (10) Galvanized 7.9 ft x 3.3 ft Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5943B	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA
5942	Quantity of (10) Galvanized 7.9 ft x 3.3 ft Steel Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5943B	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA
5943	Quantity of 2026 STARVOX SV0566-21 66 ft x 5 ft Hot-dip Galvanized Welded Wire Mesh Fencing (Unused) S/N: SV2026GWM010013 C/W: Located in Lane 49 Spot 2, Quantity of (21) Rolls 5 ft x 66 ft, Total Length 1386 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5943C	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA
5943	Quantity of 2026 STARVOX SV0566-21 66 ft x 5 ft Hot-dip Galvanized Welded Wire Mesh Fencing (Unused) S/N: SV2026GWM010013 C/W: Located in Lane 49 Spot 2, Quantity of (21) Rolls 5 ft x 66 ft, Total Length 1386 ft ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5943C	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA
5943A	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5943D	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA
5943A	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
5943D	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5943G	Quantity of 2026 MTO A500 50 ft x 6 ft Galvanized Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:01 PM CDT Asset located in: Humble, TX, USA
5943E	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5956	Quantity of 8 ft x 3 ft 3 in Galvanized Fencing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA
5943E	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:00 PM CDT Asset located in: Humble, TX, USA	5956	Quantity of 8 ft x 3 ft 3 in Galvanized Fencing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA
5943F	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:01 PM CDT Asset located in: Humble, TX, USA	5959	Quantity of (12) 2026 KJ K1222 86 in x 47 in Polyethylene Board Roadbed Protection Pad (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA
5943F	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:01 PM CDT Asset located in: Humble, TX, USA	5959	Quantity of (12) 2026 KJ K1222 86 in x 47 in Polyethylene Board Roadbed Protection Pad (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA
5943F	2026 SUNTOP G500 500 ft x 7 ft Galvanized Chain Link Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, (10) Rolls of 50 ft x 7 ft Fencing, (2) Gates, (2) Rolls of 750 ft Barbed Wire, Total Length 516 ft ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:01 PM CDT Asset located in: Humble, TX, USA	5960	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96699 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA
5943G	Quantity of 2026 MTO A500 50 ft x 6 ft Galvanized Fencing (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:01 PM CDT Asset located in: Humble, TX, USA	5960	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96699 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5961	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96696 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA	5964	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96692 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA
5961	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96696 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:02 PM CDT Asset located in: Humble, TX, USA	5964	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96692 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA
5962	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96694 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5965	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96691 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA
5962	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96694 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5965	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96691 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA
5963	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96695 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5966	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96698 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA
5963	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96695 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5966	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96698 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5967	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: F14791 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5970	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: F07721 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA
5967	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: F14791 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5970	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: F07721 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA
5968	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: F14790 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5971	Quantity of (2) Crates of Traffic Barrel Tire Rings S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA
5968	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: F14790 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:03 PM CDT Asset located in: Humble, TX, USA	5971	Quantity of (2) Crates of Traffic Barrel Tire Rings S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA
5969	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96693 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5972	Quantity of (250) 2026 Greatbear Safety Highway Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA
5969	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96693 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5972	Quantity of (250) 2026 Greatbear Safety Highway Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA
5969	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Ground Protection Mats (Unused) S/N: E96693 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5973	Quantity of (250) 2026 Greatbear Safety Highway Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5973	Quantity of (250) 2026 Greatbear Safety Highway Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5977	Quantity of (250) 2026 STARVOX TC-250P 28 in PVC Safety Traffic Cones (Unused) S/N: STV2026TC03095 C/W: Located in Lane 51 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:05 PM CDT Asset located in: Humble, TX, USA
5974	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5977	Quantity of (250) 2026 STARVOX TC-250P 28 in PVC Safety Traffic Cones (Unused) S/N: STV2026TC03095 C/W: Located in Lane 51 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:05 PM CDT Asset located in: Humble, TX, USA
5974	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5982	Quantity of (100) 2026 STARVOX DB-100P 44 in Delineators & Bases (Unused) S/N: STV2026DB02058 C/W: Located in Lane 51 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5975	Quantity of (250) 2026 Greatbear Safety Highway Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5982	Quantity of (100) 2026 STARVOX DB-100P 44 in Delineators & Bases (Unused) S/N: STV2026DB02058 C/W: Located in Lane 51 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5975	Quantity of (250) 2026 Greatbear Safety Highway Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:04 PM CDT Asset located in: Humble, TX, USA	5983	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5976	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:05 PM CDT Asset located in: Humble, TX, USA	5983	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5976	Quantity of (250) 2026 TSC 28 in Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:05 PM CDT Asset located in: Humble, TX, USA	5983A	Quantity of (250) 2026 MTO A2250 Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5983A	Quantity of (250) 2026 MTO A2250 Traffic Cones (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA	5985B	Quantity of (3) 2026 SUNTOP S0720-1 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5984	Quantity of Road Signs S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA	5985B	Quantity of (3) 2026 SUNTOP S0720-1 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5984	Quantity of Road Signs S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA	5985C	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5985	Quantity of Road Signs S/N: Not Available C/W: Located in Lane 54 Spot 0, w/ Hose Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA	5985C	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5985	Quantity of Road Signs S/N: Not Available C/W: Located in Lane 54 Spot 0, w/ Hose Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA	5985D	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5985A	Quantity of (6) 2026 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA	5985D	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA
5985A	Quantity of (6) 2026 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA	5985D	2026 SUNTOP S0720-1 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, Deer Motif ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:06 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
5996	Quantity of (2) 2026 Greatbear 16 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, With artwork "Star" in the Middle of Gate Frame. Corner Protection Cable Tie. Usage: Not Available Lot closing time: Fri, Sep 18, 02:08 PM CDT Asset located in: Humble, TX, USA	6006	Quantity of (3) 2026 SKLP SK-HLM14 14 ft x 6 ft 6 in Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:09 PM CDT Asset located in: Humble, TX, USA
5996	Quantity of (2) 2026 Greatbear 16 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, With artwork "Star" in the Middle of Gate Frame. Corner Protection Cable Tie. Usage: Not Available Lot closing time: Fri, Sep 18, 02:08 PM CDT Asset located in: Humble, TX, USA	6006	Quantity of (3) 2026 SKLP SK-HLM14 14 ft x 6 ft 6 in Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, Product images displayed are stock photos. item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:09 PM CDT Asset located in: Humble, TX, USA
6001	Quantity of (4) 2026 Greatbear 14 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, With artwork "Deer" in the Middle of Gate Frame. Corner Protection Cable Tie. Usage: Not Available Lot closing time: Fri, Sep 18, 02:08 PM CDT Asset located in: Humble, TX, USA	6007	Quantity of (4) 2026 SKLP SK-HLM14 14 ft x 6 ft 6 in Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: E86580 C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:09 PM CDT Asset located in: Humble, TX, USA
6001	Quantity of (4) 2026 Greatbear 14 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, With artwork "Deer" in the Middle of Gate Frame. Corner Protection Cable Tie. Usage: Not Available Lot closing time: Fri, Sep 18, 02:08 PM CDT Asset located in: Humble, TX, USA	6007	Quantity of (4) 2026 SKLP SK-HLM14 14 ft x 6 ft 6 in Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: E86580 C/W: Located in Lane 47 Spot 0, Product images displayed are stock photos. item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:09 PM CDT Asset located in: Humble, TX, USA
6004	Quantity of (3) 2026 Greatbear 14 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, With artwork "Deer" in the Middle of Gate Frame, Corner Protection Cable Tie Usage: Not Available Lot closing time: Fri, Sep 18, 02:09 PM CDT Asset located in: Humble, TX, USA	6013	2025 AGT YC32-G Portable Sawmill (Unused) S/N: YC-32GZ202510025 Usage: Not Available Lot closing time: Fri, Sep 18, 02:10 PM CDT Asset located in: Humble, TX, USA
6004	Quantity of (3) 2026 Greatbear 14 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 3, With artwork "Deer" in the Middle of Gate Frame, Corner Protection Cable Tie Usage: Not Available Lot closing time: Fri, Sep 18, 02:09 PM CDT Asset located in: Humble, TX, USA	6013	2025 AGT YC32-G Portable Sawmill (Unused) S/N: YC-32GZ202510025 Usage: Not Available Lot closing time: Fri, Sep 18, 02:10 PM CDT Asset located in: Humble, TX, USA
		6014	2025 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202503114 Usage: Not Available Lot closing time: Fri, Sep 18, 02:10 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6014	2025 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202503114 Usage: Not Available Lot closing time: Fri, Sep 18, 02:10 PM CDT Asset located in: Humble, TX, USA	6018	Knaack 4830 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6014A	Northstar Power Auger S/N: 06041207 C/W: Located in Lane 47 Spot 0, 2005 US EPA Label, Honda GX270 1 Cylinder 9 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:10 PM CDT Asset located in: Humble, TX, USA	6019	Knaack Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6015	Quantity of (2) Knaack 109 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 01 Usage: Not Available Lot closing time: Fri, Sep 18, 02:10 PM CDT Asset located in: Humble, TX, USA	6019	Knaack Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6015	Quantity of (2) Knaack 109 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 01 Usage: Not Available Lot closing time: Fri, Sep 18, 02:10 PM CDT Asset located in: Humble, TX, USA	6019A	Quantity of (3) Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Miscellaneous Contractor Supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6016	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA	6019A	Quantity of (3) Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Miscellaneous Contractor Supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6016	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA	6019B	Quantity of (3) Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Miscellaneous Contractor Supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6017	Knaack Jobmaster 60 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA	6019B	Quantity of (3) Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Miscellaneous Contractor Supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6017	Knaack Jobmaster 60 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA	6021	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA
6018	Knaack 4830 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA	6021	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:11 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6022	Quantity of Knaack Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6027	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA
6022	Quantity of Knaack Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6027	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA
6024	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6029	Quantity of (4) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Pipe stands Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA
6024	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6029	Quantity of (4) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Pipe stands Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA
6025	Quantity of Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6030	Quantity of (4) Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA
6025	Quantity of Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6030	Quantity of (4) Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA
6026	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6031	Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA
6026	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:12 PM CDT Asset located in: Humble, TX, USA	6031	Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6032	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA	6039	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:14 PM CDT Asset located in: Humble, TX, USA
6032	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA	6043	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA
6033	Quantity of (4) Knaack Field Office Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA	6043	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA
6033	Quantity of (4) Knaack Field Office Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:13 PM CDT Asset located in: Humble, TX, USA	6045	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 2, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA
6036	Quantity of (4) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Pipe stands Usage: Not Available Lot closing time: Fri, Sep 18, 02:14 PM CDT Asset located in: Humble, TX, USA	6045	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 2, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA
6036	Quantity of (4) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Pipe stands Usage: Not Available Lot closing time: Fri, Sep 18, 02:14 PM CDT Asset located in: Humble, TX, USA	6046	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA
6037	Quantity of Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:14 PM CDT Asset located in: Humble, TX, USA	6046	Quantity of (2) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA
6037	Quantity of Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:14 PM CDT Asset located in: Humble, TX, USA	6047	2025 Kit Containers ST-57 29 in x 57 in Workbench S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA
6039	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Located in Lane 53 Spot 0, Misc contractor supplies Usage: Not Available Lot closing time: Fri, Sep 18, 02:14 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6048	2025 Kit Containers ST-57 29 in x 57 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA	6052	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA
6048	2025 Kit Containers ST-57 29 in x 57 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:15 PM CDT Asset located in: Humble, TX, USA	6052	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA
6049	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA	6053	2025 Kit Containers WB-90-243 40 in x 90 in Workbench S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA
6049	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA	6054	2025 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA
6050	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA	6055	2025 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA
6050	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA	6056	2025 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA
6051	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA	6057	2025 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA
6051	2025 Kit Containers TB4096 40 in x 96 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:16 PM CDT Asset located in: Humble, TX, USA	6058	2025 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6058A	2025 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA	6063	Manitowoc QD1002A Ice Machine S/N: 030961364 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA
6059	2025 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA	6063	Manitowoc QD1002A Ice Machine S/N: 030961364 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA
6060	Quantity of (2) 2026 Powertek CD-265ES Battery Charger (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA	6064	Manitowoc SD0422A Ice Machine S/N: 110134374 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA
6060	Quantity of (2) 2026 Powertek CD-265ES Battery Charger (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA	6064	Manitowoc SD0422A Ice Machine S/N: 110134374 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA
6061	Manitowoc ID0502A-161D Ice Machine S/N: 1120038621 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA	6065	Manitowoc SY1004A Ice Machine S/N: 110562019 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA
6061	Manitowoc ID0502A-161D Ice Machine S/N: 1120038621 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:17 PM CDT Asset located in: Humble, TX, USA	6065	Manitowoc SY1004A Ice Machine S/N: 110562019 C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA
6062	Hoshizaki KM515MAH Ice Machine S/N: D03447A C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA	6066	2026 KJ K377 Outdoor Barbecue Grill House (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA
6062	Hoshizaki KM515MAH Ice Machine S/N: D03447A C/W: Located in Lane 54 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA	6066	2026 KJ K377 Outdoor Barbecue Grill House (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6067	2022 Karcher B75/110 Ride-On Electric Floor Scrubber S/N: 010071 C/W: Located in Lane 53 Spot 1, 36 in Working Width, Water System, Rear Squeegee, 24 Volt Operating System Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA	6071	Kelco Sand Blaster S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
6067	2022 Karcher B75/110 Ride-On Electric Floor Scrubber S/N: 010071 C/W: Located in Lane 53 Spot 1, 36 in Working Width, Water System, Rear Squeegee, 24 Volt Operating System Usage: Not Available Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA	6072	Quantity of Fire Extinguisher S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
6068	2016 Tennant 5680 Walk-Behind Electric Floor Scrubber S/N: 1568692 C/W: Located in Lane 61 Spot 0, 30 in Working Width, Water System, Rear Squeegee, 36 Volt Operating System Usage: 124 Hr Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA	6072	Quantity of Fire Extinguisher S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
6068	2016 Tennant 5680 Walk-Behind Electric Floor Scrubber S/N: 1568692 C/W: Located in Lane 61 Spot 0, 30 in Working Width, Water System, Rear Squeegee, 36 Volt Operating System Usage: 124 Hr Lot closing time: Fri, Sep 18, 02:18 PM CDT Asset located in: Humble, TX, USA	6073	Quantity of (4) Work Lights S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
6069A	2020 MMLJ Inc DB500 Sand Blaster S/N: 1M9BU1821LH774298 C/W: Located in Lane 43 Spot 0, 2019 US EPA Label, Kohler KKHXL2.48TCR 3 Cylinder 37 kW 1.861 L Diesel Engine Usage: 310 Hr Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA	6074	Eaton Transformer S/N: J15E21495 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
6069A	2020 MMLJ Inc DB500 Sand Blaster S/N: 1M9BU1821LH774298 C/W: Located in Lane 43 Spot 0, 2019 US EPA Label, Kohler KKHXL2.48TCR 3 Cylinder 37 kW 1.861 L Diesel Engine Usage: 310 Hr Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA	6074	Eaton Transformer S/N: J15E21495 C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
6071	Kelco Sand Blaster S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA	6074B	2022 Carrier 38AUDA16A0A6-0A0A0 15 ton Air Conditioner (Unused) S/N: 4622P83747 C/W: Located in Lane 53 Spot 0, 460 V Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
		6074B	2022 Carrier 38AUDA16A0A6-0A0A0 15 ton Air Conditioner (Unused) S/N: 4622P83747 C/W: Located in Lane 53 Spot 0, 460 V Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA
		6074C	2022 Carrier 24ABB360A062011 5 ton Air Conditioner (Unused) S/N: 1522E04751 C/W: Located in Lane 53 Spot 0, 460 V Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6074C	2022 Carrier 24ABB360A062011 5 ton Air Conditioner (Unused) S/N: 1522E04751 C/W: Located in Lane 53 Spot 0, 460 V Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA	6078	Quantity of (1) Keystone 10000 BTU & (1) TCL 12000 BTU Air Conditioner S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA
6075	Quantity of (2) Window Air Conditioner (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA	6079	Quantity of (7) Air Conditioner S/N: Not Available C/W: Located in Lane 54 Spot 0, (6) Frigidaire (1) Tripp-lite Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA
6075	Quantity of (2) Window Air Conditioner (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:19 PM CDT Asset located in: Humble, TX, USA	6079	Quantity of (7) Air Conditioner S/N: Not Available C/W: Located in Lane 54 Spot 0, (6) Frigidaire (1) Tripp-lite Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA
6076	Quantity of (2) Keystone 18000 BTU Air Conditioner S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA	6080	Quantity of (4) 2026 Powertek 2 in x 300 Ft Water Hose (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA
6076	Quantity of (2) Keystone 18000 BTU Air Conditioner S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA	6080	Quantity of (4) 2026 Powertek 2 in x 300 Ft Water Hose (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA
6077	Quantity of (2) Window Air Conditioner (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA	6081	Quantity of (3) 2026 Powertek 3 in x 300 Ft Water Hose (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA
6077	Quantity of (2) Window Air Conditioner (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA	6081	Quantity of (3) 2026 Powertek 3 in x 300 Ft Water Hose (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA
6078	Quantity of (1) Keystone 10000 BTU & (1) TCL 12000 BTU Air Conditioner S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:20 PM CDT Asset located in: Humble, TX, USA	6082	2026 KJ K015 Pallet Racking (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6082	2026 KJ K015 Pallet Racking (Unused) S/N: Not Available C/W: Located in Lane 46 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA	6086	Quantity of (4) (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA
6083	Quantity of 148 in. Long Bars Pallet Racking S/N: Not Available C/W: Located in Lane 53 Spot 0, 148 in Beams Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA	6086	Quantity of (4) (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA
6083	Quantity of 148 in. Long Bars Pallet Racking S/N: Not Available C/W: Located in Lane 53 Spot 0, 148 in Beams Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA	6087	Quantity of (4) Pallets of (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA
6084	Quantity of (4) Pallets of (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA	6087	Quantity of (4) Pallets of (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA
6084	Quantity of (4) Pallets of (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA	6088	Quantity of (2) Pallets of (96 Pcs Total) 2x8x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 48 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA
6085	Quantity of (4) Pallets of (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA	6088	Quantity of (2) Pallets of (96 Pcs Total) 2x8x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 48 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA
6085	Quantity of (4) Pallets of (256 Pcs Total) 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:21 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6089	Quantity of (3) Pallets of (144 Pcs Total) 2x8x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 48 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA	6092	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
6089	Quantity of (3) Pallets of (144 Pcs Total) 2x8x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 48 pieces per pallet Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA	6092	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
6090	Quantity of (3) Pallets of 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet, (192 Pcs Total) Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA	6093	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
6090	Quantity of (3) Pallets of 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet, (192 Pcs Total) Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA	6093	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
6091	Quantity of (3) Pallets of 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet, (192 Pcs Total) Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA	6094	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
6091	Quantity of (3) Pallets of 2x6x16 SYP #2 Prime Grade Kiln Dried-Heat Treated S4S Lumber (Unused) S/N: Not Available C/W: Located in Lane 56 Spot 0, 64 pieces per pallet, (192 Pcs Total) Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA	6094	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
		6095	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
		6095	Quantity of Lumber S/N: Not Available C/W: Located in Lane 52 Spot 0, Misc sizes Usage: Not Available Lot closing time: Fri, Sep 18, 02:22 PM CDT Asset located in: Humble, TX, USA
		6096	Quantity of (27) Boxes of 48 in x 7.2 in SPC-Click-Lock Vinyl Plank Flooring Flooring (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6096	Quantity of (27) Boxes of 48 in x 7.2 in SPC-Click-Lock Vinyl Plank Flooring Flooring (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6098B	Quantity of (200) 2026 SUNTOP S2134C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA
6097	Quantity of (27) Boxes of 48 in x 7.2 in SPC-Click-Lock Vinyl Plank Flooring Flooring (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6098B	Quantity of (200) 2026 SUNTOP S2134C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA
6097	Quantity of (27) Boxes of 48 in x 7.2 in SPC-Click-Lock Vinyl Plank Flooring Flooring (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6098C	Quantity of (200) 2026 SUNTOP S840C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA
6098	Quantity of (27) Boxes of 48 in x 7.2 in SPC-Click-Lock Vinyl Plank Flooring Flooring (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6098C	Quantity of (200) 2026 SUNTOP S840C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA
6098	Quantity of (27) Boxes of 48 in x 7.2 in SPC-Click-Lock Vinyl Plank Flooring Flooring (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6098D	Quantity of (200) 2026 SUNTOP S840C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA
6098A	Quantity of (200) 2026 SUNTOP S2134C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6098D	Quantity of (200) 2026 SUNTOP S840C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA
6098A	Quantity of (200) 2026 SUNTOP S2134C-200 Corrugated Galvalume Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6100	Quantity of (70) 20 ft x 3 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6104	Quantity of (30) 16 ft x 3 ft White Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA
6100	Quantity of (70) 20 ft x 3 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6104	Quantity of (30) 16 ft x 3 ft White Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA
6101	Quantity of (20) 20 ft x 3 ft Black Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6105	Quantity of (30) 16 ft x 3 ft Black Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA
6101	Quantity of (20) 20 ft x 3 ft Black Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:23 PM CDT Asset located in: Humble, TX, USA	6105	Quantity of (30) 16 ft x 3 ft Black Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA
6102	Quantity of (20) 20 ft x 3 ft White Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA	6106	Quantity of (30) 16 ft x 3 ft Gray Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA
6102	Quantity of (20) 20 ft x 3 ft White Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA	6106	Quantity of (30) 16 ft x 3 ft Gray Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA
6103	Quantity of (20) 20 ft x 3 ft Brown Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA	6107	Quantity of (30) 16 ft x 3 ft Brown Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA
6103	Quantity of (20) 20 ft x 3 ft Brown Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA	6107	Quantity of (30) 16 ft x 3 ft Brown Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6108	Quantity of (100) 12 ft x 3 ft White Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA	6112	Quantity of (50) 12 ft x 3 ft White Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA
6108	Quantity of (100) 12 ft x 3 ft White Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:24 PM CDT Asset located in: Humble, TX, USA	6112	Quantity of (50) 12 ft x 3 ft White Corrugated Tin Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA
6109	Quantity of (70) 12 ft x 3 ft Black Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA	6113	Quantity of (100) 12 ft x 3 ft Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA
6109	Quantity of (70) 12 ft x 3 ft Black Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA	6113	Quantity of (100) 12 ft x 3 ft Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA
6110	Quantity of (70) 12 ft x 3 ft Brown Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA	6114	Quantity of (30) 12 ft x 3 ft Corrugated Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA
6110	Quantity of (70) 12 ft x 3 ft Brown Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA	6114	Quantity of (30) 12 ft x 3 ft Corrugated Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA
6111	Quantity of (70) 12 ft x 3 ft Gray Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA	6115	Quantity of (30) 12 ft x 3 ft Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA
6111	Quantity of (70) 12 ft x 3 ft Gray Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA	6115	Quantity of (30) 12 ft x 3 ft Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:25 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6116	Quantity of (70) 8 ft x 3 ft Black Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA	6120	Quantity of (30) 8 ft x 3 ft Corrugated Polycarbonate Roof Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA
6116	Quantity of (70) 8 ft x 3 ft Black Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA	6120	Quantity of (30) 8 ft x 3 ft Corrugated Polycarbonate Roof Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA
6117	Quantity of (30) 8 ft x 3 ft Grey Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA	6123	Quantity of (50) 19.69 ft x 35 in Corrugated Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:27 PM CDT Asset located in: Humble, TX, USA
6117	Quantity of (30) 8 ft x 3 ft Grey Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA	6123	Quantity of (50) 19.69 ft x 35 in Corrugated Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:27 PM CDT Asset located in: Humble, TX, USA
6118	Quantity of (100) 8 ft x 3 ft Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA	6138	Quantity of (100) 2026 MTO A0311 Galvalume Corrugated Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA
6118	Quantity of (100) 8 ft x 3 ft Polycarbonate Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA	6138	Quantity of (100) 2026 MTO A0311 Galvalume Corrugated Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA
6119	Quantity of (30) 8 ft x 3 ft Corrugated Polycarbonate Roof Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA	6139	Quantity of (100) 2026 MTO A0311 Galvalume Corrugated Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA
6119	Quantity of (30) 8 ft x 3 ft Corrugated Polycarbonate Roof Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:26 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6139	Quantity of (100) 2026 MTO A0311 Galvalume Corrugated Steel Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA	6143	Quantity of (20) 3 ft x 4 ft Black Steel Diamond Plates (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA
6140	Quantity of (30) 20 ft x 17.7 in Gray Metal Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Thickness: 0.4 mm Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA	6143	Quantity of (20) 3 ft x 4 ft Black Steel Diamond Plates (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA
6140	Quantity of (30) 20 ft x 17.7 in Gray Metal Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Thickness: 0.4 mm Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA	6144	Quantity of (40) 3 ft x 6 ft Gray Metal Rail Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1, 6-Gauge welded 4 in, 4 in Mesh Pattern Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA
6141	Quantity of (30) 20 ft x 17.7 in Gray Metal Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Thickness: 0.4 mm Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA	6144	Quantity of (40) 3 ft x 6 ft Gray Metal Rail Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1, 6-Gauge welded 4 in, 4 in Mesh Pattern Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA
6141	Quantity of (30) 20 ft x 17.7 in Gray Metal Roof Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Thickness: 0.4 mm Usage: Not Available Lot closing time: Fri, Sep 18, 02:29 PM CDT Asset located in: Humble, TX, USA	6145	Quantity of (40) 3 ft x 6 ft Black Metal Rail Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1, 6-Gauge welded 4 in, 4 in Mesh Pattern Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA
6142	Quantity of (20) 3 ft x 4 ft Yellow Steel Diamond Plates (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA	6145	Quantity of (40) 3 ft x 6 ft Black Metal Rail Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1, 6-Gauge welded 4 in, 4 in Mesh Pattern Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA
6142	Quantity of (20) 3 ft x 4 ft Yellow Steel Diamond Plates (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA	6146	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6146	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA	6150	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA
6147	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA	6151	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA
6147	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA	6151	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA
6148	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA	6152	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA
6148	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:30 PM CDT Asset located in: Humble, TX, USA	6152	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA
6149	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA	6153	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA
6149	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA	6153	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA
6150	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA	6154	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6154	Quantity of (50) 2025 Kit Containers 12 ft Corrugated Tin (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 2 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA	6158	6.6 ft, 49.2 ft Artificial Grass Turf S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA
6155	Quantity of (40) 35 in x 8 ft Multi-wall Polycarbonate Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA	6159	6.6 ft, 49.2 ft Artificial Grass Turf Drainage Holes with Rubber Backing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA
6155	Quantity of (40) 35 in x 8 ft Multi-wall Polycarbonate Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:31 PM CDT Asset located in: Humble, TX, USA	6159	6.6 ft, 49.2 ft Artificial Grass Turf Drainage Holes with Rubber Backing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA
6156	Quantity of (20) 27 in x 8 ft Multi-wall Polycarbonate Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA	6160	3.3 ft, 49.2 ft Artificial Grass Turf Drainage Holes with Rubber Backing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA
6156	Quantity of (20) 27 in x 8 ft Multi-wall Polycarbonate Panels (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA	6160	3.3 ft, 49.2 ft Artificial Grass Turf Drainage Holes with Rubber Backing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA
6157	Quantity of (5) Rolls of 6.6 ft x 49.2 ft Artificial Grass Turf (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA	6161	Quantity of (5) Rolls of 3.3 ft x 49.2 ft Artificial Grass Turf (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA
6157	Quantity of (5) Rolls of 6.6 ft x 49.2 ft Artificial Grass Turf (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA	6161	Quantity of (5) Rolls of 3.3 ft x 49.2 ft Artificial Grass Turf (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA
6158	6.6 ft, 49.2 ft Artificial Grass Turf S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:32 PM CDT Asset located in: Humble, TX, USA	6162	3.3 ft, 49.2 ft Artificial Grass Turf Drainage Holes with Rubber Backing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6162	3.3 ft, 49.2 ft Artificial Grass Turf Drainage Holes with Rubber Backing S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6165A	Quantity of (40) 3 ft x 6 ft Gray Metal Rail Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA
6163	Quantity of (2) Rolls of 3.2 ft x 49.2 ft Artificial Grass Turf (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Rolls (Coverage 1299sq.ft.) Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6166	Quantity of (40) 3 ft x 6 ft Galvanized Garden Mesh Steel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1, 12-Gauge Welded 2 in, 2 in Mesh Pattern Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA
6163	Quantity of (2) Rolls of 3.2 ft x 49.2 ft Artificial Grass Turf (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Rolls (Coverage 1299sq.ft.) Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6166	Quantity of (40) 3 ft x 6 ft Galvanized Garden Mesh Steel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1, 12-Gauge Welded 2 in, 2 in Mesh Pattern Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA
6164	Quantity of (50) 3 ft x 6 ft Metal Steel Wire Mesh Sheet (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6167	6.89 ft x 3.38 ft Grey Steel Security Door with Frame and Hardware (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA
6164	Quantity of (50) 3 ft x 6 ft Metal Steel Wire Mesh Sheet (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6167	6.89 ft x 3.38 ft Grey Steel Security Door with Frame and Hardware (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA
6165	Quantity of (50) 3 ft x 6 ft Galvanized Steel Garden Mesh (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6168	6.89 ft x 3.38 ft White Steel Security Door with Frame and Hardware (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA
6165	Quantity of (50) 3 ft x 6 ft Galvanized Steel Garden Mesh (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6168	6.89 ft x 3.38 ft White Steel Security Door with Frame and Hardware (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA
6165A	Quantity of (40) 3 ft x 6 ft Gray Metal Rail Panel (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:33 PM CDT Asset located in: Humble, TX, USA	6169	Quantity of (2) Rolls of 6.6 ft x 164 ft Bubble Aluminum Foil Reflective Insulation (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6169	Quantity of (2) Rolls of 6.6 ft x 164 ft Bubble Aluminum Foil Reflective Insulation (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA	6173	Quantity of (8) Pallets of Polyiso Insulation (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA
6170	Quantity of (3) Rolls of 3.3 ft x 164 ft Bubble Aluminum Foil Reflective Insulation (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA	6173	Quantity of (8) Pallets of Polyiso Insulation (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA
6170	Quantity of (3) Rolls of 3.3 ft x 164 ft Bubble Aluminum Foil Reflective Insulation (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA	6174	Quantity of (8) Pallets of Polyiso Insulation (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA
6171	Quantity of (20) 12 ft x 15 in Wood Grain Insulated Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Thickness: 15 mm (0.6 in) Coverage: 296sq.ft Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA	6174	Quantity of (8) Pallets of Polyiso Insulation (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA
6171	Quantity of (20) 12 ft x 15 in Wood Grain Insulated Panels (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, Thickness: 15 mm (0.6 in) Coverage: 296sq.ft Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA	6177	Quantity of (23) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA
6172	Quantity of (8) Pallets of Polyiso Insulation (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA	6177	Quantity of (23) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA
6172	Quantity of (8) Pallets of Polyiso Insulation (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0, Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 02:34 PM CDT Asset located in: Humble, TX, USA	6178	Quantity of (17) Pallets of (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA
		6178	Quantity of (17) Pallets of (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6179	Quantity of (12) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA	6184	General Electric Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA
6179	Quantity of (12) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA	6184	General Electric Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA
6180	Quantity of (20) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA	6185	Square D Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA
6180	Quantity of (20) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA	6185	Square D Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA
6181	Quantity of (23) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA	6186	Eaton Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA
6181	Quantity of (23) Pallets of Aluminum Trays (Unused) S/N: Not Available C/W: Located in Lane 86 Usage: Not Available Lot closing time: Fri, Sep 18, 02:35 PM CDT Asset located in: Humble, TX, USA	6186	Eaton Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA
6183	Eaton Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA	6187	General Electric Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA
6183	Eaton Distribution Panel S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA	6188	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04451 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6188	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04451 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:36 PM CDT Asset located in: Humble, TX, USA	6191	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04452 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA
6189	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04453 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6192	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets S/N: F07593 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA
6189	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04453 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6192	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets S/N: F07593 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA
6190	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04456 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6193	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets (Unused) S/N: F08000 C/W: Located in Lane 49 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA
6190	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04456 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6193	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets (Unused) S/N: F08000 C/W: Located in Lane 49 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA
6191	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets (Unused) S/N: F04452 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6194	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets (Unused) S/N: F07594 C/W: Located in Lane 49 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6194	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets (Unused) S/N: F07594 C/W: Located in Lane 49 Spot 1, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6198	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA
6195	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets (Unused) S/N: F07595 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6199	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA
6195	Quantity of (50) 2026 SKLP SK-XH50 Galvalume Steel Sheets (Unused) S/N: F07595 C/W: Located in Lane 49 Spot 2, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:37 PM CDT Asset located in: Humble, TX, USA	6199	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA
6196	Quantity of (27) Spy Calibration Meters S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA	6200	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA
6196	Quantity of (27) Spy Calibration Meters S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA	6200	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA
6197	Quantity of (2) Pallets of Pipe Stand S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA	6201	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA
6197	Quantity of (2) Pallets of Pipe Stand S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA	6201	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA
6198	Quantity of (48) 4 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:38 PM CDT Asset located in: Humble, TX, USA	6202	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA
		6202	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6203	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6207	Quantity of (9) 5 in x 4 in x 19 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA
6203	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6208	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA
6204	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6208	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA
6204	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6209	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA
6205	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6209	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA
6205	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6210	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA
6206	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6210	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA
6206	Quantity of (16) 8 in x 20 ft C- Purlin (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA	6211	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA
6207	Quantity of (9) 5 in x 4 in x 19 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:39 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6211	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6215	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA
6212	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6216	Quantity of (6) 6 in x 6 in Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA
6212	Quantity of (9) 5 in x 4 in x 20 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6216	Quantity of (6) 6 in x 6 in Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA
6213	Quantity of (6) 5 in x 4 in x 19 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6217	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA
6213	Quantity of (6) 5 in x 4 in x 19 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6217	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA
6214	Quantity of (9) 5 in x 4 in x 19 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6218	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA
6214	Quantity of (9) 5 in x 4 in x 19 ft Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6218	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA
6215	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:40 PM CDT Asset located in: Humble, TX, USA	6219	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6219	Quantity of (6) 6 in x 6 in x 20 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA	6223	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA
6220	Quantity of (6) 6 in x 6 in x 15 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA	6224	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA
6220	Quantity of (6) 6 in x 6 in x 15 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA	6224	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA
6221	Quantity of (6) 6 in x 6 in x 16 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA	6225	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA
6221	Quantity of (6) 6 in x 6 in x 16 ft Square Tubing (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One Bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:41 PM CDT Asset located in: Humble, TX, USA	6225	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA
6222	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA	6226	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA
6222	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA	6226	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA
6223	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA	6227	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6227	Quantity of (5) 18 in x 20 ft Metal Trusses (Unused) S/N: Not Available C/W: Located in Lane 57 Spot 0, One bundle Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA	6231	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA
6228	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA	6232	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA
6228	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:42 PM CDT Asset located in: Humble, TX, USA	6232	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA
6229	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA	6233	Quantity of (4) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA
6229	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA	6233	Quantity of (4) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA
6230	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA	6234	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA
6230	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA	6234	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA
6231	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA	6235	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6235	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:43 PM CDT Asset located in: Humble, TX, USA	6239	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA
6236	Quantity of (3) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA	6240	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA
6236	Quantity of (3) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA	6240	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA
6237	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA	6241	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA
6237	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA	6241	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA
6238	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA	6242	Quantity of (6) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA
6238	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA	6242	Quantity of (6) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA
6239	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:44 PM CDT Asset located in: Humble, TX, USA	6243	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6243	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6247	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA
6244	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6248	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA
6244	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6248	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA
6245	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6249	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA
6245	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6249	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA
6246	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6250	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA
6246	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6250	Quantity of (6) 2025 Kit Containers 2 in x 6 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA
6247	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:45 PM CDT Asset located in: Humble, TX, USA	6251	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6251	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6255	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA
6252	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6256	Quantity of (12) 2025 Kit Containers 1.5 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA
6252	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6256	Quantity of (12) 2025 Kit Containers 1.5 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA
6253	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6257	Quantity of (12) 2025 Kit Containers 1.5 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA
6253	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6257	Quantity of (12) 2025 Kit Containers 1.5 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA
6254	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6258	Quantity of (4) 2025 Kit Containers 1.5 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA
6254	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6258	Quantity of (4) 2025 Kit Containers 1.5 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA
6255	Quantity of (9) 2025 Kit Containers 2 in x 3 in Rectangle Tubing (Unused) S/N: Not Available C/W: Located in Lane 25 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:46 PM CDT Asset located in: Humble, TX, USA	6259	Quantity of (2) Bundles of 6 in x 6 in x 40 Ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6259	Quantity of (2) Bundles of 6 in x 6 in x 40 Ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA	6262	Quantity of (2) Bundles of Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0, (1) 2 in x 2 in x 40 ft, (1) 6 in x 6 in x 40 ft Usage: Not Available Lot closing time: Fri, Sep 18, 02:48 PM CDT Asset located in: Humble, TX, USA
6260	Quantity of (5) Bundles of 2 in x 2 in x 40 ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA	6263	2022 Northern Tool 157597 Pressure Washer S/N: 4K1BP1622NF002848 C/W: Water Heater, 525 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler Ch730 2 Cylinder 23.5 hp 725 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:48 PM CDT Asset located in: Humble, TX, USA
6260	Quantity of (5) Bundles of 2 in x 2 in x 40 ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA	6263	2022 Northern Tool 157597 Pressure Washer S/N: 4K1BP1622NF002848 C/W: Water Heater, 525 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler Ch730 2 Cylinder 23.5 hp 725 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:48 PM CDT Asset located in: Humble, TX, USA
6261	Quantity of (5) Bundles of 2 in x 2 in x 40 ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA	6266	2026 MTO A4000P Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 420 cc Gasoline Engine, 4.0 gpm ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:48 PM CDT Asset located in: Humble, TX, USA
6261	Quantity of (5) Bundles of 2 in x 2 in x 40 ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA	6266	2026 MTO A4000P Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 420 cc Gasoline Engine, 4.0 gpm ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:48 PM CDT Asset located in: Humble, TX, USA
6261A	Quantity of (3) Bundles 1 1/2 in x 1 1/2 in x 40 ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA	6270	2026 MTO A4000 Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 420 cc Gasoline Engine, 4.0 gpm ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA
6261A	Quantity of (3) Bundles 1 1/2 in x 1 1/2 in x 40 ft Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 02:47 PM CDT Asset located in: Humble, TX, USA	6270	2026 MTO A4000 Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 420 cc Gasoline Engine, 4.0 gpm ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA
6262	Quantity of (2) Bundles of Angle Iron S/N: Not Available C/W: Located in Lane 57 Spot 0, (1) 2 in x 2 in x 40 ft, (1) 6 in x 6 in x 40 ft Usage: Not Available Lot closing time: Fri, Sep 18, 02:48 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6273	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 2620154 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA	6276	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 2620157 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA
6273	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 2620154 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA	6277	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263129 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA
6274	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263126 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA	6277	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263129 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA
6274	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263126 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA	6278	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263130 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA
6275	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 2620153 C/W: 4000 psi Rating, Hose, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA	6278	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263130 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA
6275	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 2620153 C/W: 4000 psi Rating, Hose, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:49 PM CDT Asset located in: Humble, TX, USA	6279	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263170 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA
6276	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 2620157 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA	6279	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263170 C/W: 4000 psi Rating, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6280	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263327 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA	6283	Campbell Hausfeld Skid-Mounted Electric 80 gal Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 230 Volt, 1 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA
6280	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 263327 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA	6284	Campbell Hausfeld Skid-Mounted Electric 60 gal Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 230 Volt Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA
6281	Quantity of (4) Simpson 2800 PSI Pressure Washer S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA	6284	Campbell Hausfeld Skid-Mounted Electric 60 gal Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 230 Volt Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA
6281	Quantity of (4) Simpson 2800 PSI Pressure Washer S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 02:50 PM CDT Asset located in: Humble, TX, USA	6285	11.5 cfm Skid-Mounted 60 gal Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 90 psi Working Pressure, 208/230 Volt, 3.7 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA
6282	MaxAir 30 cfm Skid-Mounted Electric 80 gal Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 100 psi Working Pressure, 115/230/460, 7.5 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA	6285	11.5 cfm Skid-Mounted 60 gal Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 90 psi Working Pressure, 208/230 Volt, 3.7 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA
6282	MaxAir 30 cfm Skid-Mounted Electric 80 gal Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 100 psi Working Pressure, 115/230/460, 7.5 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA	6286	Iron Horse 11.2 cfm Skid-Mounted 60 gal Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 150 psi Working Pressure, 208/230 Volt, 6.5 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA
6283	Campbell Hausfeld Skid-Mounted Electric 80 gal Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 230 Volt, 1 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA	6286	Iron Horse 11.2 cfm Skid-Mounted 60 gal Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 150 psi Working Pressure, 208/230 Volt, 6.5 hp Motor Usage: Not Available Lot closing time: Fri, Sep 18, 02:51 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6293	PowerTrain PT-14G30TRKE-V2 18.5 cfm 30 gal Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 175 psi Working Pressure, Power train 14 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:52 PM CDT Asset located in: Humble, TX, USA	6296	A.O. Smith AT25004 250 Hp Electric Motor S/N: 06455514 C/W: 230 / 460 Volt, 550 / 275 Amp, 3 Phase, 60 HZ, 1784 RPM Usage: Not Available Notes: Units Can Be Loaded Onsite with a High Capacity Gantry Crane Post Auction ; Motor Does Turn, Video Attached - Fits Universal 3254 Jaw Crusher in Auction or Other Crushers; Item at offsite location must be picked up within 14 days of auction (October 2nd) or will be subject to 3rd party storage fees ; Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Georgetown, TX, USA
6293	PowerTrain PT-14G30TRKE-V2 18.5 cfm 30 gal Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 175 psi Working Pressure, Power train 14 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:52 PM CDT Asset located in: Humble, TX, USA	6296	A.O. Smith AT25004 250 Hp Electric Motor S/N: 06455514 C/W: 230 / 460 Volt, 550 / 275 Amp, 3 Phase, 60 HZ, 1784 RPM Usage: Not Available Notes: Units Can Be Loaded Onsite with a High Capacity Gantry Crane Post Auction ; Motor Does Turn, Video Attached - Fits Universal 3254 Jaw Crusher in Auction or Other Crushers; Item at offsite location must be picked up within 14 days of auction (October 2nd) or will be subject to 3rd party storage fees ; Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Georgetown, TX, USA
6294	Eagle TT55G-ND 12.5 cfm 10 gal Twin Tank Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 150 psi Working Pressure, Honda GX160 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:52 PM CDT Asset located in: Humble, TX, USA	6297	Quantity of (2) 2026 Powertek PT80C Water Pump (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 3 in Intake, 3 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA
6294	Eagle TT55G-ND 12.5 cfm 10 gal Twin Tank Air Compressor S/N: Not Available C/W: Located in Lane 100 Spot 0, 150 psi Working Pressure, Honda GX160 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:52 PM CDT Asset located in: Humble, TX, USA	6297	Quantity of (2) 2026 Powertek PT80C Water Pump (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 3 in Intake, 3 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA
6295	PowerTrain 11.2 cfm 10 gal Twin Tank Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 90 psi Working Pressure, 2 Cylinder 7 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:52 PM CDT Asset located in: Humble, TX, USA	6298	Quantity of (2) 2026 Powertek PT50C Water Pump (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 2 in Intake, 2 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA
6295	PowerTrain 11.2 cfm 10 gal Twin Tank Air Compressor (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 90 psi Working Pressure, 2 Cylinder 7 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:52 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6298	Quantity of (2) 2026 Powertek PT50C Water Pump (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 2 in Intake, 2 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA	6302	Quantity of (2) Water Pump S/N: Not Available C/W: Located in Lane 54 Spot 0, (2) Simpson Pressure Washer (1) Generac Generator Usage: Not Available Lot closing time: Fri, Sep 18, 02:54 PM CDT Asset located in: Humble, TX, USA
6299	2026 SDLP600 Water Pump (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, 1 Cylinder 212 cc Gasoline Engine, Product images displayed are stock photos. item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA	6302	Quantity of (2) Water Pump S/N: Not Available C/W: Located in Lane 54 Spot 0, (2) Simpson Pressure Washer (1) Generac Generator Usage: Not Available Lot closing time: Fri, Sep 18, 02:54 PM CDT Asset located in: Humble, TX, USA
6299	2026 SDLP600 Water Pump (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, 1 Cylinder 212 cc Gasoline Engine, Product images displayed are stock photos. item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA	6303	2026 Powertek D2000iN 2.0 kW Generator Set (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 1 Cylinder 79 cc Gasoline Engine, 2.0 kVA, 1.6 kW, Rated Single Phase Output, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Lot closing time: Fri, Sep 18, 02:54 PM CDT Asset located in: Humble, TX, USA
6300	2026 SDLP600 Water Pump (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, 1 Cylinder 212 cc Gasoline Engine, Product images displayed are stock photos. item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA	6303	2026 Powertek D2000iN 2.0 kW Generator Set (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 1 Cylinder 79 cc Gasoline Engine, 2.0 kVA, 1.6 kW, Rated Single Phase Output, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Lot closing time: Fri, Sep 18, 02:54 PM CDT Asset located in: Humble, TX, USA
6300	2026 SDLP600 Water Pump (Unused) S/N: Not Available C/W: Located in Lane 47 Spot 0, 1 Cylinder 212 cc Gasoline Engine, Product images displayed are stock photos. item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA	6304	Champion 4.65 kW Portable Generator Set S/N: Not Available C/W: Located in Lane 54 Spot 0, Dual Fuel Engine, 120 V Receptacles, Quantity of Electrical Cords, (1) Duct Rodder Usage: Not Available Lot closing time: Fri, Sep 18, 02:54 PM CDT Asset located in: Humble, TX, USA
6301	Quantity of (6) Water Pump S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA	6304	Champion 4.65 kW Portable Generator Set S/N: Not Available C/W: Located in Lane 54 Spot 0, Dual Fuel Engine, 120 V Receptacles, Quantity of Electrical Cords, (1) Duct Rodder Usage: Not Available Lot closing time: Fri, Sep 18, 02:54 PM CDT Asset located in: Humble, TX, USA
6301	Quantity of (6) Water Pump S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:53 PM CDT Asset located in: Humble, TX, USA	6309	Quantity of (5) Generac Portable Generator Set S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6309	Quantity of (5) Generac Portable Generator Set S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA	6314	Kohler JKHXL1.37SF1 Generator Set S/N: Not Available C/W: Located in Lane 52, Kohler 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA
6311	Kohler JKHXL1.37SF1 Generator Set S/N: Not Available C/W: Located in Lane 52, 2018 US EPA Label, 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA	6315	2026 SKLP Laser Level (Unused) S/N: F12871 C/W: Located in Lane 100 Spot 0, Grade rod, tripod Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA
6311	Kohler JKHXL1.37SF1 Generator Set S/N: Not Available C/W: Located in Lane 52, 2018 US EPA Label, 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA	6315	2026 SKLP Laser Level (Unused) S/N: F12871 C/W: Located in Lane 100 Spot 0, Grade rod, tripod Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA
6312	Kohler JKHXL1.37SF1 Generator Set S/N: 4817900366 C/W: Located in Lane 52, 2018 US EPA Label, 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA	6316	Trimble GCS900 GPS GNSS Full Grade Control System S/N: 0412J543SY C/W: Located in Lane 103 Spot 0, Trimble MS980 Smart GPS Antenna ; Trimble CB430 Cab Display ; Dozer Mast Trimble Coil Cords ; Cab Interior Connection Cords ; Trimble SNR Radio Usage: Not Available Notes: Operational GPS System - fits 2018 D6T LGP in Auction. Fits any manufacturer Dozer, Motor Grader, Scraper, Excavators Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA
6312	Kohler JKHXL1.37SF1 Generator Set S/N: 4817900366 C/W: Located in Lane 52, 2018 US EPA Label, 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA	6316	Trimble GCS900 GPS GNSS Full Grade Control System S/N: 0412J543SY C/W: Located in Lane 103 Spot 0, Trimble MS980 Smart GPS Antenna ; Trimble CB430 Cab Display ; Dozer Mast Trimble Coil Cords ; Cab Interior Connection Cords ; Trimble SNR Radio Usage: Not Available Notes: Operational GPS System - fits 2018 D6T LGP in Auction. Fits any manufacturer Dozer, Motor Grader, Scraper, Excavators Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA
6313	Kohler JKHXL1.37SF1 Generator Set S/N: 4817100526 C/W: Located in Lane 52, 2018 US EPA Label, 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA	6317	Trimble Grade Control System S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA
6313	Kohler JKHXL1.37SF1 Generator Set S/N: 4817100526 C/W: Located in Lane 52, 2018 US EPA Label, 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA		
6314	Kohler JKHXL1.37SF1 Generator Set S/N: Not Available C/W: Located in Lane 52, Kohler 3 Cylinder 19 kW 1.028 L Diesel Engine Usage: Not Available Lot closing time: Fri, Sep 18, 02:55 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6317	Trimble Grade Control System S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA	6321	20 ft Heavy-Duty Ratchet Load Binders and Chains Set (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA
6318	Quantity of (5) Sets of 20 ft Heavy Duty Chain Sets (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks, 7000 lbs Working Strength for Truck, Tie Down, Hauling, Towing. Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA	6321	20 ft Heavy-Duty Ratchet Load Binders and Chains Set (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA
6318	Quantity of (5) Sets of 20 ft Heavy Duty Chain Sets (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks, 7000 lbs Working Strength for Truck, Tie Down, Hauling, Towing. Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA	6322	Quantity of Ratchet Binder and Chain (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, (5) 9200 lbs Ratchet Binder, (10) 3/8 in 20 ft G70 Chain Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA
6319	Quantity of (5) 20 ft Heavy-Duty Chain Sets (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks, 7000 lbs Working Strength for Truck, Tie Down, Hauling, Towing. Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA	6322	Quantity of Ratchet Binder and Chain (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, (5) 9200 lbs Ratchet Binder, (10) 3/8 in 20 ft G70 Chain Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA
6319	Quantity of (5) 20 ft Heavy-Duty Chain Sets (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks, 7000 lbs Working Strength for Truck, Tie Down, Hauling, Towing. Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA	6323	Quantity of Ratchet Binder and Chain (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, (5) 5400 lbs Ratchet Binder, (10) 5/16 in 20 ft G70 Chain Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA
6320	20 ft Heavy-Duty Ratchet Load Binders and Chains Set (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA	6323	Quantity of Ratchet Binder and Chain (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, (5) 5400 lbs Ratchet Binder, (10) 5/16 in 20 ft G70 Chain Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA
6320	20 ft Heavy-Duty Ratchet Load Binders and Chains Set (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, with G70 Hooks Usage: Not Available Lot closing time: Fri, Sep 18, 02:56 PM CDT Asset located in: Humble, TX, USA	6324	Quantity of (10) 5.5 in x 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA
		6324	Quantity of (10) 5.5 in x 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6325	Quantity of (10) 5.5 in, 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA	6330	Quantity of (20) 2.4 in x 33 ft Yellow Heavy Duty Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:58 PM CDT Asset located in: Humble, TX, USA
6325	Quantity of (10) 5.5 in, 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA	6331	Quantity of (10) 2.4 in x 33 ft Yellow Heavy Duty Ratchet Straps S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:58 PM CDT Asset located in: Humble, TX, USA
6326	Quantity of (10) 3.9 in, 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA	6332	Quantity of (10) 2.4 in x 33 ft Blue Heavy Duty Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:58 PM CDT Asset located in: Humble, TX, USA
6326	Quantity of (10) 3.9 in, 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA	6333	Quantity of (10) 2.4 in x 33 ft Blue Heavy Duty Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:58 PM CDT Asset located in: Humble, TX, USA
6327	Quantity of (10) 3.9 in, 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA	6334	Quantity of (10) 2.4 in x 33 ft Blue Heavy Duty Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:58 PM CDT Asset located in: Humble, TX, USA
6327	Quantity of (10) 3.9 in, 13 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA	6335	Quantity of (10) 2.4 in x 33 ft Blue Heavy Duty Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:58 PM CDT Asset located in: Humble, TX, USA
6328	Quantity of (10) 2.4 in x 33 ft Yellow Heavy Duty Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:57 PM CDT Asset located in: Humble, TX, USA	6336	Quantity of (20) 2 in x 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA
6329	Quantity of (10) 2.4 in x 33 ft Yellow Heavy Duty Ratchet Straps (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:58 PM CDT Asset located in: Humble, TX, USA	6336	Quantity of (20) 2 in x 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6337	Quantity of (20) 2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6342	2026 SKLP SK-YLJ100 Electric/Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA
6337	Quantity of (20) 2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6342	2026 SKLP SK-YLJ100 Electric/Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA
6338	Quantity of (20) 2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6343	2026 SKLP SK-SYLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA
6338	Quantity of (20) 2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6343	2026 SKLP SK-SYLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA
6339	Quantity of (20) 1.2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6344	2026 SKLP SK-SYLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA
6339	Quantity of (20) 1.2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6344	2026 SKLP SK-SYLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA
6340	Quantity of (20) 1.2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6345	2026 SKLP SK-SYLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA
6340	Quantity of (20) 1.2 in, 9.8 ft Heavy Duty Industrial Polyester Lifting Sling (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 02:59 PM CDT Asset located in: Humble, TX, USA	6345	2026 SKLP SK-SYLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: Not Available C/W: Located in Lane 48 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6347	Quantity of 2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: E97367 C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA	6350	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: E86585 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA
6347	Quantity of 2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: E97367 C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA	6351	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01751 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA
6348	Quantity of 2026 SKLP SK-HJ6 Metal Storage Shelf Shelving (Unused) S/N: E97368 C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA	6351	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01751 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA
6348	Quantity of 2026 SKLP SK-HJ6 Metal Storage Shelf Shelving (Unused) S/N: E97368 C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:00 PM CDT Asset located in: Humble, TX, USA	6352	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01750 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA
6349	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: E86584 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA	6352	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01750 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA
6349	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: E86584 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA	6353	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01749 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA
6350	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: E86585 C/W: Located in Lane 51 Spot 3, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA	6353	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01749 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6354	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01752 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA	6359A	Quantity of (2) Pallets of Igloo 5 gal Beverage Cooler S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA
6354	2026 SKLP SK-S13 Massage Chair (Unused) S/N: F01752 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA	6360	Quantity of (10) Kobalt Fixed Shade Auto Darkening Welding Helmet (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA
6355	Quantity of 110 v String Lights S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:01 PM CDT Asset located in: Humble, TX, USA	6361	Quantity of (2) 55 in Propane Fire Pit Table (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA
6356	Quantity of Vapor Proof String Lights S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA	6361	Quantity of (2) 55 in Propane Fire Pit Table (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA
6357	Quantity of Vapor Proof String Lights S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA	6362	Quantity of (2) 76 in Propane Fire Pit Table (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA
6358	Quantity of (2) Rolls of 5/8 in x 328 ft High Strenght Polyester Rope (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, 20 mm Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA	6362	Quantity of (2) 76 in Propane Fire Pit Table (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA
6358	Quantity of (2) Rolls of 5/8 in x 328 ft High Strenght Polyester Rope (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4, 20 mm Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA	6363	Quantity of (4) 1 Gauge 25 ft Heavy Duty Booster Cable S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA
6359	Shop Vacuum S/N: Not Available C/W: Located in Lane 100 Spot 0, 20 US Gallon, 75.7L, 6.5HP Usage: Not Available Lot closing time: Fri, Sep 18, 03:02 PM CDT Asset located in: Humble, TX, USA	6363	Quantity of (4) 1 Gauge 25 ft Heavy Duty Booster Cable S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6364	Quantity of (4) First Alert 2087FA Fire & Water Proof Safe (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA	6369	Quantity of (5) 2026 STARVOX VD-2-3-5 Heavy-Duty 3-6m Hand Chain Hoist Set (Unused) S/N: SV2026CHS01036 C/W: Located in Lane 47 Spot 0, (1) 5 ton - 3 m, (1) 3 ton - 6 m, (1) 3 ton - 3 m, (1) 2 ton - 6 m & (1) 2 ton - 3 m ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA
6364	Quantity of (4) First Alert 2087FA Fire & Water Proof Safe (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA	6369	Quantity of (5) 2026 STARVOX VD-2-3-5 Heavy-Duty 3-6m Hand Chain Hoist Set (Unused) S/N: SV2026CHS01036 C/W: Located in Lane 47 Spot 0, (1) 5 ton - 3 m, (1) 3 ton - 6 m, (1) 3 ton - 3 m, (1) 2 ton - 6 m & (1) 2 ton - 3 m ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA
6367	Quantity of 2026 STARVOX SV-RBC58 Rigging /Binding & Chain/Suspension Equipment (Unused) S/N: SV2026RBC04079 C/W: Located in Lane 47 Spot 0, (5) 9200 lb & (8) 5400 lb Ratchet Binders, (10) 3/8 in x 20 ft & (16) 5/16 in x 20 ft Chains, (8) 5/16 in Lifting Chain Sling ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA	6370	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA
6367	Quantity of 2026 STARVOX SV-RBC58 Rigging /Binding & Chain/Suspension Equipment (Unused) S/N: SV2026RBC04079 C/W: Located in Lane 47 Spot 0, (5) 9200 lb & (8) 5400 lb Ratchet Binders, (10) 3/8 in x 20 ft & (16) 5/16 in x 20 ft Chains, (8) 5/16 in Lifting Chain Sling ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA	6370	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA
6368	Quantity of (5) 2026 STARVOX VD-2-3-5 Heavy-Duty 3-6m Hand Chain Hoist Set (Unused) S/N: SV2026CHS01035 C/W: Located in Lane 47 Spot 0, (1) 5 ton - 3 m, (1) 3 ton - 6 m, (1) 3 ton - 3 m, (1) 2 ton - 6 m & (1) 2 ton - 3 m ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA	6371	Quantity of (4) Quantity of 4 Soap Dispensers S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Midland, TX, USA
6368	Quantity of (5) 2026 STARVOX VD-2-3-5 Heavy-Duty 3-6m Hand Chain Hoist Set (Unused) S/N: SV2026CHS01035 C/W: Located in Lane 47 Spot 0, (1) 5 ton - 3 m, (1) 3 ton - 6 m, (1) 3 ton - 3 m, (1) 2 ton - 6 m & (1) 2 ton - 3 m ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:03 PM CDT Asset located in: Humble, TX, USA	6371	Quantity of (4) Quantity of 4 Soap Dispensers S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Midland, TX, USA
		6373	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA
		6373	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6374	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA	6378	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA
6374	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA	6378	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA
6375	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA	6379	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA
6375	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:04 PM CDT Asset located in: Humble, TX, USA	6379	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA
6376	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA	6380	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA
6376	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA	6380	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA
6377	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA	6381	Quantity of (58) 3 in x 20 ft Grey UPVC Rigid Non-Metallic Conduit (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA
6377	Quantity of (24) 61 in x 32.5 in x 2 in 41 Amp Solar Panels (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA	6381	Quantity of (58) 3 in x 20 ft Grey UPVC Rigid Non-Metallic Conduit (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:05 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6382	Quantity of (24) 40 ft x 6 in Channel S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6386	Ingersoll Rand GT200-12-10 20 ton Geared Trolley (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA
6382	Quantity of (24) 40 ft x 6 in Channel S/N: Not Available C/W: Located in Lane 57 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6387	Quantity of (2) Propane Heaters S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA
6383	Quantity of Flux Core Welding Wire S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6387	Quantity of (2) Propane Heaters S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA
6383	Quantity of Flux Core Welding Wire S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6388	Industrial Motors & Equipment S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA
6384	Quantity of Flux Core Welding Wire S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6388	Industrial Motors & Equipment S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA
6384	Quantity of Flux Core Welding Wire S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6389	Industrial Parts & Seals S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA
6385	Ingersoll Rand GT200-12-10 20 ton Geared Trolley (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6389	Industrial Parts & Seals S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA
6385	Ingersoll Rand GT200-12-10 20 ton Geared Trolley (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6390	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA
6386	Ingersoll Rand GT200-12-10 20 ton Geared Trolley (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:06 PM CDT Asset located in: Humble, TX, USA	6390	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6391	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grates (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6395	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA
6391	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grates (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6395	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA
6392	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6396	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA
6392	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6396	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA
6393	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6397	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA
6393	Quantity of (8) 58 in x 39 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6397	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA
6394	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6398	American Steel Line Co Electric Double Sided Decoiler S/N: 6958 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA
6394	Quantity of (8) 47.5 in x 39.5 in x 1 ½ in Hot Dipped Galvanized Grate (Unused) S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:07 PM CDT Asset located in: Humble, TX, USA	6398	American Steel Line Co Electric Double Sided Decoiler S/N: 6958 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6399	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA	6403	Quantity of (5) Loading Ramps S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6399	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA	6404	Quantity of (2) Loading Ramps S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6400	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA	6404	Quantity of (2) Loading Ramps S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6400	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA	6405	Jobsite PS600 Purlin Machine S/N: Not Available C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6401	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA	6405	Jobsite PS600 Purlin Machine S/N: Not Available C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6401	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:08 PM CDT Asset located in: Humble, TX, USA	6406	2026 Powertek PT9500 Magnetic Drill (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6402	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA	6406	2026 Powertek PT9500 Magnetic Drill (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6402	Quantity of Cable S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA	6407	Quantity of Concrete Finishing Tools S/N: Not Available C/W: Located in Lane 36 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA
6403	Quantity of (5) Loading Ramps S/N: Not Available C/W: Located in Lane 52 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA	6408	Quantity of Dewalt Cordless Power Tools S/N: Not Available C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:09 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6409	Quantity of Techimpex IFT-2 2 Ton Machinery Skates S/N: Not Available C/W: Located in Lane 51 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6415	Quantity of (2) Crates of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Quantity of Straps, Rope, Face Shields, Electrical Cables, Hoses Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA
6410	Techimpex IFT-2 2 Ton Machinery Skates S/N: Not Available C/W: Located in Lane 53 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6415	Quantity of (2) Crates of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Quantity of Straps, Rope, Face Shields, Electrical Cables, Hoses Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA
6411	Cub Cadet 6 pc Tool Kit S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6416	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Slings, Traffic Cones Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA
6412	Quantity of (3) Wokin 132 pc Tool Chest Set (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6416	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Slings, Traffic Cones Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA
6412	Quantity of (3) Wokin 132 pc Tool Chest Set (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6417	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Dry Wall Cart, Dolly, Pipe Stands, U-Line Metal Shelves, Tools Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA
6413	Cub Cadet 6 pc Tool Kit S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6417	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Dry Wall Cart, Dolly, Pipe Stands, U-Line Metal Shelves, Tools Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA
6414	Makita 20 pcs Air Nail Gun & 18 volt Cordless Tool Set with Makita Mower S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6418	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA
6414	Makita 20 pcs Air Nail Gun & 18 volt Cordless Tool Set with Makita Mower S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:10 PM CDT Asset located in: Humble, TX, USA	6419	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6420	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA	6427	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Lanyards, Traffic Cones Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA
6421	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:11 PM CDT Asset located in: Humble, TX, USA	6428	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA
6422	Quantity of (2) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA	6428	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA
6423	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA	6429	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA
6424	Quantity of (2) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA	6429	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA
6425	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, (2) Carts, (1) Flammables Storage Locker Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA	6430	Quantity of (2) Boxes of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA
6426	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA	6430	Quantity of (2) Boxes of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA
6426	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA	6431	Quantity of (2) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Rain Jackets, Bags Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA
6427	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Lanyards, Traffic Cones Usage: Not Available Lot closing time: Fri, Sep 18, 03:12 PM CDT Asset located in: Humble, TX, USA	6431	Quantity of (2) Pallets of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, Rain Jackets, Bags Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6432	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA	6437	Quantity of (4) Flammable Storage Cabinets S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA
6432	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA	6437	Quantity of (4) Flammable Storage Cabinets S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA
6433	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA	6438	Quantity of Tie Down Equipment S/N: Not Available C/W: Located in Lane 52 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA
6433	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA	6439	Quantity of Hack Saws S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA
6434	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, (1) Tool Box (2) Bins with Wheel Chocks(1) Set of Ramps (2) Collapsible Bulk Containers, (4) 10 ton Hydraulic Ram System, Quantity of Wire Rope Sling Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA	6440	Quantity of Tools S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA
6434	Quantity of Contractor Supplies S/N: Not Available C/W: Located in Lane 54 Spot 0, (1) Tool Box (2) Bins with Wheel Chocks(1) Set of Ramps (2) Collapsible Bulk Containers, (4) 10 ton Hydraulic Ram System, Quantity of Wire Rope Sling Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA	6440A	Quantity of Misc Tools S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA
6435	Quantity of (2) Storage Cabinets S/N: Not Available C/W: Located in Lane 54 Spot 0, C/W Right Angle Rollers Usage: Not Available Lot closing time: Fri, Sep 18, 03:13 PM CDT Asset located in: Humble, TX, USA	6441	Quantity of Construction Hoist S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA
6436	Durham Pesticides Storage Cabinet (Unused) S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:14 PM CDT Asset located in: Humble, TX, USA	6442	Quantity of (2) Pallets of Metal Shelving S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6443	Quantity of Fire Extinguisher S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6447A	Flame Resistant Storage Cabinets S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA
6443	Quantity of Fire Extinguisher S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6447A	Flame Resistant Storage Cabinets S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA
6444	Quantity of (11) Werner 6ft Ladders S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6447B	Current Tools 503 Wire Rack S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA
6445	Quantity of Ladders S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6447B	Current Tools 503 Wire Rack S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA
6446	Quantity of (25) 4ft Ladders S/N: Not Available C/W: Located in Lane 54 Spot 0, (2) Pallet Jacks, Ladders Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6458	Preston-Eastin RHTSDE-10 Robotic Welding Cell Enclosure and Positioning System S/N: RHTSDE1015 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:17 PM CDT Asset located in: Humble, TX, USA
6446	Quantity of (25) 4ft Ladders S/N: Not Available C/W: Located in Lane 54 Spot 0, (2) Pallet Jacks, Ladders Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6458	Preston-Eastin RHTSDE-10 Robotic Welding Cell Enclosure and Positioning System S/N: RHTSDE1015 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:17 PM CDT Asset located in: Humble, TX, USA
6446A	Quantity of (3) Pallets of Fiberglass Ladder S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6461	1985 Mazak M4 1500 Lathe S/N: 61926 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:17 PM CDT Asset located in: Humble, TX, USA
6446B	Quantity of (3) Pallets of Ladders S/N: Not Available C/W: Located in Lane 52 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6461	1985 Mazak M4 1500 Lathe S/N: 61926 C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:17 PM CDT Asset located in: Humble, TX, USA
6447	Quantity of Power Drills, Grinders, & Chargers S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:15 PM CDT Asset located in: Humble, TX, USA	6462	Shop Press S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6462	Shop Press S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA	6466	Edco CD-5 Pneumatic Concrete Grinder S/N: 161010359 C/W: 12 in Grinding Width Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA
6463	Chicago Dreis & Krump Shop Press S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA	6467	2026 Powertek PT8208D Concrete Saw (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 1 Cylinder 1.2 hp 52 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA
6463	Chicago Dreis & Krump Shop Press S/N: Not Available C/W: Located in Lane 54 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA	6467	2026 Powertek PT8208D Concrete Saw (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, 1 Cylinder 1.2 hp 52 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA
6464	2026 ATS POWER ATS-SP50 50 ton Hydraulic Shop Press (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA	6468	Quantity of (4) 2026 Powertek 20T lifter 20 Ton Air/Hydraulic Bottle Jack (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA
6464	2026 ATS POWER ATS-SP50 50 ton Hydraulic Shop Press (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA	6468	Quantity of (4) 2026 Powertek 20T lifter 20 Ton Air/Hydraulic Bottle Jack (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA
6465	2026 ATS POWER ATS-SP50 50 ton Hydraulic Shop Press (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA	6469	Quantity of (4) 2026 Powertek 20T lifter 20 Ton Air/Hydraulic Bottle Jack (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA
6465	2026 ATS POWER ATS-SP50 50 ton Hydraulic Shop Press (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:18 PM CDT Asset located in: Humble, TX, USA	6469	Quantity of (4) 2026 Powertek 20T lifter 20 Ton Air/Hydraulic Bottle Jack (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA
		6470	Quantity of (3) Valley 4 ft Farm Jack (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6471	Quantity of (2) Valley HJA-22 22 ton Air /Hydraulic Service Jack S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6475	Armor 64 Gun Safe S/N: Not Available C/W: Located in Lane 100 Spot 0, 40 in Wide x 55 in High x 25 in Deep Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA
6471	Quantity of (2) Valley HJA-22 22 ton Air /Hydraulic Service Jack S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6476	Armor 64 Gun Safe S/N: Not Available C/W: Located in Lane 100 Spot 0, 40 in Wide x 55 in High x 25 in Deep Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA
6471A	2026 STARVOX JB80T-2 80 ton Pneumatic /Hydraulic Floor Jack (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6476	Armor 64 Gun Safe S/N: Not Available C/W: Located in Lane 100 Spot 0, 40 in Wide x 55 in High x 25 in Deep Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA
6471A	2026 STARVOX JB80T-2 80 ton Pneumatic /Hydraulic Floor Jack (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6477	Quantity of (2) Makita HM1307CB 35 lb Demolition Breaker S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA
6472	Transmission Jack S/N: Not Available C/W: Located in Lane 53 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6477	Quantity of (2) Makita HM1307CB 35 lb Demolition Breaker S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA
6473	Quantity of (2) 2026 Powertek WW13000 13008 lb Electric Winch (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6478	Quantity of (2) Makita HM1307CB 35 lb Demolition Breaker S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA
6474	2026 Greatbear 20000 lb Electric Winch (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6478	Quantity of (2) Makita HM1307CB 35 lb Demolition Breaker S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA
6475	Armor 64 Gun Safe S/N: Not Available C/W: Located in Lane 100 Spot 0, 40 in Wide x 55 in High x 25 in Deep Usage: Not Available Lot closing time: Fri, Sep 18, 03:19 PM CDT Asset located in: Humble, TX, USA	6479	Quantity of Pneumatic Demolition Breaker S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6480	Troy-Bilt Colt Front Tine Rototiller (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA	6483	2023 Exmark Turf Tracer S-Series Walk-Behind Lawn Mower S/N: 414932290 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2023 US EPA Label, 48 in Mower Usage: 142 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6480	Troy-Bilt Colt Front Tine Rototiller (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA	6483	2023 Exmark Turf Tracer S-Series Walk-Behind Lawn Mower S/N: 414932290 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2023 US EPA Label, 48 in Mower Usage: 142 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6480A	Troy-Bilt Colt Rototiller (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA	6485	2026 Ariens Ikon 60 Zero-Turn Lawn Mower (Unused) S/N: 135931 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2026 US EPA Label, 11x6.00-5 Front Tires, 20x10.00-8 Rear Tires, 60 in Mower Usage: 9 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6480A	Troy-Bilt Colt Rototiller (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0, Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA	6485	2026 Ariens Ikon 60 Zero-Turn Lawn Mower (Unused) S/N: 135931 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2026 US EPA Label, 11x6.00-5 Front Tires, 20x10.00-8 Rear Tires, 60 in Mower Usage: 9 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6481	Troy-Bilt Colt Front Tine Rototiller (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA	6486	2024 Ariens Ikon 60 Zero-Turn Lawn Mower (Unused) S/N: 036805 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2024 US EPA Label, 11x6.00-5 Front Tires, 20x10.00-8 Rear Tires, 60 in Mower Usage: 1 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6481	Troy-Bilt Colt Front Tine Rototiller (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:20 PM CDT Asset located in: Humble, TX, USA	6486	2024 Ariens Ikon 60 Zero-Turn Lawn Mower (Unused) S/N: 036805 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2024 US EPA Label, 11x6.00-5 Front Tires, 20x10.00-8 Rear Tires, 60 in Mower Usage: 1 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6482	2023 Exmark Walk-Behind Lawn Mower S/N: 415103345 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2023 US EPA Label, 48 in Mower Usage: 181 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA		
6482	2023 Exmark Walk-Behind Lawn Mower S/N: 415103345 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2023 US EPA Label, 48 in Mower Usage: 181 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6486A	2025 Bad Boy BRG72RD385KA Zero-Turn Lawn Mower S/N: BRG72RD385KA09250004 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2025 US EPA Label, 15x6.00-6/4.50 Front Tires, 26x12.00-12 Rear Tires, 72 in Mower Usage: 12 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA	6488	2023 Craftsman 33ABA7PS793 Electric Lawn Mower (Unused) S/N: 1L09NH40068 C/W: Located in Lane 100 Spot 0, 15x6.00-6 Front Tires, 20x8.00-8 Rear Tires, 42 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6486A	2025 Bad Boy BRG72RD385KA Zero-Turn Lawn Mower S/N: BRG72RD385KA09250004 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2025 US EPA Label, 15x6.00-6/4.50 Front Tires, 26x12.00-12 Rear Tires, 72 in Mower Usage: 12 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA	6488	2023 Craftsman 33ABA7PS793 Electric Lawn Mower (Unused) S/N: 1L09NH40068 C/W: Located in Lane 100 Spot 0, 15x6.00-6 Front Tires, 20x8.00-8 Rear Tires, 42 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA
6486B	2025 Bad Boy BRG61385KA Zero-Turn Lawn Mower S/N: BRG61385KA08250024 C/W: Located in Lane 100 Spot 0, Canopy, Hydrostatic Drive, 2025 US EPA Label, 16x5.00-6/4.50 Front Tires, 26-12N12 Rear Tires, 61 in Mower Usage: 79 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA	6489	Troybuilt Ride-On Lawn Mower S/N: Not Available C/W: Located in Lane 100 Spot 0, 2015 US EPA Label, 15X6.00-6 Front Tires, 20X8.00-8 Rear Tires Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6486B	2025 Bad Boy BRG61385KA Zero-Turn Lawn Mower S/N: BRG61385KA08250024 C/W: Located in Lane 100 Spot 0, Canopy, Hydrostatic Drive, 2025 US EPA Label, 16x5.00-6/4.50 Front Tires, 26-12N12 Rear Tires, 61 in Mower Usage: 79 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Humble, TX, USA	6489	Troybuilt Ride-On Lawn Mower S/N: Not Available C/W: Located in Lane 100 Spot 0, 2015 US EPA Label, 15X6.00-6 Front Tires, 20X8.00-8 Rear Tires Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6487	John Deere L110A 4x2 Ride-On Lawn Mower S/N: GXL110A013797 C/W: Hydrostatic Drive, 2004 US EPA Label, 15x6.00-6 NHS Front Tires, 20x8-8 Rear Tires, 42 in Mower Usage: 623 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Lake Worth, TX, USA	6489A	2026 Bad Boy BBY25FJ180 Walk-Behind Lawn Mower S/N: BBY25FJ18011250020 C/W: Located in Lane 100 Spot 0, 2023 US EPA Label, 25 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6487	John Deere L110A 4x2 Ride-On Lawn Mower S/N: GXL110A013797 C/W: Hydrostatic Drive, 2004 US EPA Label, 15x6.00-6 NHS Front Tires, 20x8-8 Rear Tires, 42 in Mower Usage: 623 Hr Lot closing time: Fri, Sep 18, 03:21 PM CDT Asset located in: Lake Worth, TX, USA	6489A	2026 Bad Boy BBY25FJ180 Walk-Behind Lawn Mower S/N: BBY25FJ18011250020 C/W: Located in Lane 100 Spot 0, 2023 US EPA Label, 25 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
		6489B	2026 Bad Boy BBY25FJ180 Walk-Behind Lawn Mower S/N: BBY25FJ18011250028 C/W: Located in Lane 100 Spot 0, 2023 US EPA Label, 25 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6489B	2026 Bad Boy BBY25FJ180 Walk-Behind Lawn Mower S/N: BBY25FJ18011250028 C/W: Located in Lane 100 Spot 0, 2023 US EPA Label, 25 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA	6493	2026 SDLOOL SL750 Remote Control Lawn Mower (Unused) S/N: 750GCJ260703 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6490	2026 SDLOOL SL-LM1200Q Remote Control Lawn Mower (Unused) S/N: 1200QYGCJ260570 C/W: Located in Lane 48 Spot 0, 40 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA	6493	2026 SDLOOL SL750 Remote Control Lawn Mower (Unused) S/N: 750GCJ260703 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6490	2026 SDLOOL SL-LM1200Q Remote Control Lawn Mower (Unused) S/N: 1200QYGCJ260570 C/W: Located in Lane 48 Spot 0, 40 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA	6494	2026 SDLOOL SL750 Remote Control Lawn Mower (Unused) S/N: 750GCJ260705 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6491	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ260786 C/W: Located in Lane 48 Spot 0, 40 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA	6494	2026 SDLOOL SL750 Remote Control Lawn Mower (Unused) S/N: 750GCJ260705 C/W: Located in Lane 100 Spot 0, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6491	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ260786 C/W: Located in Lane 48 Spot 0, 40 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA	6495	Ryobi Ride-On Electric Lawn Mower S/N: Not Available C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 13x5.00-6 Front Tires, 18x8.50-8 Rear Tires, 54 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6492	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower S/N: 1000QYGCJ260622 C/W: Located in Lane 48 Spot 3, 40 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA	6495	Ryobi Ride-On Electric Lawn Mower S/N: Not Available C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 13x5.00-6 Front Tires, 18x8.50-8 Rear Tires, 54 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA
6492	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower S/N: 1000QYGCJ260622 C/W: Located in Lane 48 Spot 3, 40 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 03:22 PM CDT Asset located in: Humble, TX, USA	6496	Quantity of (8) Ryobi 18 in Chain Saw S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6496	Quantity of (8) Ryobi 18 in Chain Saw S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6500	Quantity of (8) Rolls of 5.9 ft x 164 ft Galvanized Field Fence (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA
6497	Quantity of (12) Assorted Landscaping Tools (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6501	Quantity of (3) Rolls of 13 ft x 300 ft Woven Landscape Fabric (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA
6497	Quantity of (12) Assorted Landscaping Tools (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6501	Quantity of (3) Rolls of 13 ft x 300 ft Woven Landscape Fabric (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA
6498	Quantity of (2) Landscaping Tools S/N: Not Available C/W: Located in Lane 100 Spot 0, Lawn Mower, Weedeater Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6502	Quantity of (7) Rolls of 6 ft x 300 ft Woven Landscape Fabric (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA
6498	Quantity of (2) Landscaping Tools S/N: Not Available C/W: Located in Lane 100 Spot 0, Lawn Mower, Weedeater Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6502	Quantity of (7) Rolls of 6 ft x 300 ft Woven Landscape Fabric (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA
6499	Quantity of (16) 5.5 gal Multi-Purpose Utility Jug S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6503	Yardforce 24 in Snow Blower (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA
6499	Quantity of (16) 5.5 gal Multi-Purpose Utility Jug S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6503	Yardforce 24 in Snow Blower (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA
6500	Quantity of (8) Rolls of 5.9 ft x 164 ft Galvanized Field Fence (Unused) S/N: Not Available C/W: Located in Lane 51 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:23 PM CDT Asset located in: Humble, TX, USA	6504	Yardforce 24 in Snow Blower (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6504	Yardforce 24 in Snow Blower (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA	6508	General Gen-Ear LE Water Leak Location System S/N: GRLEK0428 C/W: Located in Lane 103 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA
6505	2026 SKLP SK-QSJ32 Snow Sweeper (Unused) S/N: SFQSJ260728 C/W: Located in Lane 100 Spot 0, 1 Cylinder 6.5 hp 196 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA	6509	Quantity of (2) Pallets of Safety Vision Pro Camera Systems S/N: Not Available C/W: Located in Lane 55 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6505	2026 SKLP SK-QSJ32 Snow Sweeper (Unused) S/N: SFQSJ260728 C/W: Located in Lane 100 Spot 0, 1 Cylinder 6.5 hp 196 cc Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA	6510	Quantity of (40) Zebra ET55BE-G15E-00US Tablet Computers (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6506	2026 SKLP SK-QSJ32 Walk-Behind Snow Sweeper (Unused) S/N: SFQSJ260724 C/W: Located in Lane 48 Spot 3, 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA	6510	Quantity of (40) Zebra ET55BE-G15E-00US Tablet Computers (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6506	2026 SKLP SK-QSJ32 Walk-Behind Snow Sweeper (Unused) S/N: SFQSJ260724 C/W: Located in Lane 48 Spot 3, 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA	6511	Quantity of (20) Zebra ET55BE-G15E-00US Tablet Computers (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6507	2026 SKLP SK-QSJ32 Walk-Behind Snow Sweeper (Unused) S/N: SFQSG260723 C/W: Located in Lane 48 Spot 3, 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA	6511	Quantity of (20) Zebra ET55BE-G15E-00US Tablet Computers (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6507	2026 SKLP SK-QSJ32 Walk-Behind Snow Sweeper (Unused) S/N: SFQSG260723 C/W: Located in Lane 48 Spot 3, 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA	6512	Quantity of (173) Panasonic (170) CF-VEBU05BU Mini Port Replicator, (1) CF-VEBU06W Mini-Dock, (1) CF-WCMU11R, (1) CF-WGP192R-NOB GPS Receiver module Computer Accessories (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6508	General Gen-Ear LE Water Leak Location System S/N: GRLEK0428 C/W: Located in Lane 103 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:24 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6512	Quantity of (173) Panasonic (170) CF-VEBU05BU Mini Port Replicator, (1) CF-VEBU06W Mini-Dock, (1) CF-WCMU11R, (1) CF-WGP192R-NOB GPS Receiver module Computer Accessories (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA	6515	2020 Caps PCHH-230TC-0NN0 230 ton Water Chiller S/N: 20F0063005 C/W: Located in Lane 25 Spot 5, 460 V Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6513	Quantity of (42) Zebra CF-VEB522M Desktop Port Replicator and Docking Station Computer Accessories (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA	6515	2020 Caps PCHH-230TC-0NN0 230 ton Water Chiller S/N: 20F0063005 C/W: Located in Lane 25 Spot 5, 460 V Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA
6513	Quantity of (42) Zebra CF-VEB522M Desktop Port Replicator and Docking Station Computer Accessories (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA	6516	Osaki Massage Chair (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA
6514	Quantity of DRIEAZ 4-PRO Dehumidifier Filters S/N: Not Available C/W: Located in Lane 53 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA	6516	Osaki Massage Chair (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA
6514	Quantity of DRIEAZ 4-PRO Dehumidifier Filters S/N: Not Available C/W: Located in Lane 53 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA	6517	Osaki Massage Chair (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA
6514A	2026 Nationwide Coils CD38S04S14-66X95.75-LH Custom Coil (Unused) S/N: J0000069971 C/W: Located in Lane 67 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA	6517	Osaki Massage Chair (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA
6514A	2026 Nationwide Coils CD38S04S14-66X95.75-LH Custom Coil (Unused) S/N: J0000069971 C/W: Located in Lane 67 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:25 PM CDT Asset located in: Humble, TX, USA	6518	Quantity of (2) Fire Pit 55 In. Adjustable Height Propane Table W/ Table Top Lid (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA
		6518	Quantity of (2) Fire Pit 55 In. Adjustable Height Propane Table W/ Table Top Lid (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6519	60 in x 30 in Table S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA	6527	2026 SKLP SL-L450 Off-Road Electric Bicycle (Unused) S/N: F06277 C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA
6519	60 in x 30 in Table S/N: Not Available C/W: Located in Lane 53 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA	6528	Quantity of (7) 2025 Kit Containers CF-90-V2025 Livestock Feeder (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA
6520	26 in x 78 in Work Table S/N: Not Available C/W: Located in Lane 53 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA	6528	Quantity of (7) 2025 Kit Containers CF-90-V2025 Livestock Feeder (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA
6520	26 in x 78 in Work Table S/N: Not Available C/W: Located in Lane 53 Spot 4 Usage: Not Available Lot closing time: Fri, Sep 18, 03:26 PM CDT Asset located in: Humble, TX, USA	6529	Quantity of (7) 2025 Kit Containers CF-90-V2025 Livestock Feeder (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA
6522	2026 Greatbear 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA	6529	Quantity of (7) 2025 Kit Containers CF-90-V2025 Livestock Feeder (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA
6522	2026 Greatbear 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA	6530	Quantity of (7) 2025 Kit Containers CF-90-V2025 Livestock Feeder (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA
6523	2026 Greatbear 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA	6530	Quantity of (7) 2025 Kit Containers CF-90-V2025 Livestock Feeder (Unused) S/N: Not Available C/W: Located in Lane 49 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA
6523	2026 Greatbear 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA	6532	2025 Kit Containers AR500ATBOAR Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA
6527	2026 SKLP SL-L450 Off-Road Electric Bicycle (Unused) S/N: F06277 C/W: Located in Lane 50 Spot 3 Usage: Not Available Lot closing time: Fri, Sep 18, 03:27 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6532	2025 Kit Containers AR500ATBOAR Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6535A	2026 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA
6533	2025 Kit Containers AR500ATDEER Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6535B	2026 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6533	2025 Kit Containers AR500ATDEER Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6535B	2026 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6534	2025 Kit Containers AR500ATDEER Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6535C	2025 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6534	2025 Kit Containers AR500ATDEER Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6535C	2025 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6535	2025 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6536	Kit Containers AR500ATBOAR Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6535	2025 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6536	Kit Containers AR500ATBOAR Shooting Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6535A	2026 Kit Containers DT14 Target (Unused) S/N: Not Available C/W: Located in Lane 100 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:28 PM CDT Asset located in: Humble, TX, USA	6537	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6537	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA	6541	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6538	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA	6541	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA
6538	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA	6542	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:30 PM CDT Asset located in: Humble, TX, USA
6539	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA	6542	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:30 PM CDT Asset located in: Humble, TX, USA
6539	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA	6543	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:30 PM CDT Asset located in: Humble, TX, USA
6540	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA	6543	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:30 PM CDT Asset located in: Humble, TX, USA
6540	2025 Kit Containers 2.0YFT-SDH 5 ft 3 in 2 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 2 in Wide x 3 ft 9 in High Usage: Not Available Lot closing time: Fri, Sep 18, 03:29 PM CDT Asset located in: Humble, TX, USA	6546	Quantity of (2) 2026 Greatbear 3 ft 7 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 3 ft 7 in Long x 3 ft 7 in Wide x 3 ft 4 in High, Fork Pockets Usage: Not Available Lot closing time: Fri, Sep 18, 03:30 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6546	Quantity of (2) 2026 Greatbear 3 ft 7 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 3 ft 7 in Long x 3 ft 7 in Wide x 3 ft 4 in High, Fork Pockets Usage: Not Available Lot closing time: Fri, Sep 18, 03:30 PM CDT Asset located in: Humble, TX, USA	6555	2026 40 ft High Cube Multi-Door Storage Container S/N: ZNCU4014614 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA
6549	Quantity of (2) 2026 Greatbear 3 ft 7 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 3 ft 7 in Long x 3 ft 7 in Wide x 3 ft 5 in High, Fork pockets Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA	6555	2026 40 ft High Cube Multi-Door Storage Container S/N: ZNCU4014614 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA
6549	Quantity of (2) 2026 Greatbear 3 ft 7 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 3 ft 7 in Long x 3 ft 7 in Wide x 3 ft 5 in High, Fork pockets Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA	6556	2026 40 ft High Cube Multi-Door Storage Container S/N: ZNCU4014595 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA
6550	Quantity of (2) 2026 Greatbear 3 ft 7 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 3 ft 7 in Long x 3 ft 7 in Wide x 3 ft 4 in High, Fork pockets Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA	6556	2026 40 ft High Cube Multi-Door Storage Container S/N: ZNCU4014595 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA
6550	Quantity of (2) 2026 Greatbear 3 ft 7 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 3 ft 7 in Long x 3 ft 7 in Wide x 3 ft 4 in High, Fork pockets Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA	6557	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2570263 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA
6554	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2571146 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA	6557	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2570263 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA
6554	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2571146 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:31 PM CDT Asset located in: Humble, TX, USA	6558	2026 40 ft High Cube Multi-Door Storage Container S/N: FHYU1700770 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA
		6558	2026 40 ft High Cube Multi-Door Storage Container S/N: FHYU1700770 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6559	40 ft High Cube Multi-Door Storage Container S/N: CIMU2176192 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA	6566	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4193826 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA
6559	40 ft High Cube Multi-Door Storage Container S/N: CIMU2176192 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA	6566	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4193826 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA
6560	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4197098 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA	6567	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4192270 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA
6560	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4197098 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:32 PM CDT Asset located in: Humble, TX, USA	6567	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4192270 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA
6562	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4199450 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA	6571	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4199932 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:34 PM CDT Asset located in: Humble, TX, USA
6562	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4199450 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA	6571	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4199932 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:34 PM CDT Asset located in: Humble, TX, USA
6563	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4194015 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA	6572	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4191778 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:34 PM CDT Asset located in: Humble, TX, USA
6563	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4194015 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:33 PM CDT Asset located in: Humble, TX, USA	6572	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4191778 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:34 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6575	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4200648 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:34 PM CDT Asset located in: Humble, TX, USA	6579	2026 40 ft High Cube Multi-Door Storage Container S/N: CIMU2021919 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA
6575	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4200648 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:34 PM CDT Asset located in: Humble, TX, USA	6579	2026 40 ft High Cube Multi-Door Storage Container S/N: CIMU2021919 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA
6576	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4194334 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA	6580	2026 40 ft High Cube Open-Sided Storage Container S/N: YLEU2572380 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA
6576	2026 40 ft High Cube Multi-Door Storage Container S/N: LYGU4194334 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA	6580	2026 40 ft High Cube Open-Sided Storage Container S/N: YLEU2572380 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA
6577	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5022626 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA	6583	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242087 C/W: Located in Lane 59, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA
6577	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5022626 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA	6583	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242087 C/W: Located in Lane 59, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA
6578	2026 40 ft High Cube Multi-Door Storage Container S/N: CIMU2021930 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA	6584	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242092 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA
6578	2026 40 ft High Cube Multi-Door Storage Container S/N: CIMU2021930 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:35 PM CDT Asset located in: Humble, TX, USA	6584	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242092 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6585	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2579300 C/W: Located in Lane 102, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6589	2026 20 ft Standard Multi-Door Storage Container S/N: XHCU3047840 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA
6585	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2579300 C/W: Located in Lane 102, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6589	2026 20 ft Standard Multi-Door Storage Container S/N: XHCU3047840 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA
6586	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2579342 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6590	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5011540 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA
6586	2026 40 ft High Cube Multi-Door Storage Container S/N: YLEU2579342 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6590	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5011540 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA
6587	2026 40 ft High Cube Storage Container S/N: LSJU1701449 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6591	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5013898 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA
6587	2026 40 ft High Cube Storage Container S/N: LSJU1701449 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6591	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5013898 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA
6588	2026 20 ft Standard Multi-Door Storage Container S/N: XHCU3047584 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6592	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5013938 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA
6588	2026 20 ft Standard Multi-Door Storage Container S/N: XHCU3047584 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:36 PM CDT Asset located in: Humble, TX, USA	6592	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5013938 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6592A	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242087 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA	6600	40 ft High Cube Storage Container S/N: LCGU8173906 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA
6592A	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242087 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:37 PM CDT Asset located in: Humble, TX, USA	6600A	2026 40 ft High Cube Storage Container S/N: LSJU1701351 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA
6592B	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242092 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA	6600A	2026 40 ft High Cube Storage Container S/N: LSJU1701351 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA
6592B	40 ft High Cube Multi-Door Storage Container S/N: LYPU0242092 C/W: Located in Lane 59 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA	6601	40 ft Standard Multi-Door Storage Container S/N: XHCU3001536 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA
6598	2025 40 ft High Cube Storage Container S/N: HPCU4936610 C/W: Located in Lane 59 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA	6601	40 ft Standard Multi-Door Storage Container S/N: XHCU3001536 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA
6598	2025 40 ft High Cube Storage Container S/N: HPCU4936610 C/W: Located in Lane 59 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA	6602	2010 40 ft High Cube Storage Container S/N: CMAU5673380 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA
6599	2010 40 ft High Cube Storage Container S/N: TCLU5316427 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA	6602	2010 40 ft High Cube Storage Container S/N: CMAU5673380 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA
6599	2010 40 ft High Cube Storage Container S/N: TCLU5316427 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA	6603	2010 40 ft High Cube Storage Container S/N: TCLU5275755 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Lake Worth, TX, USA
6600	40 ft High Cube Storage Container S/N: LCGU8173906 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:38 PM CDT Asset located in: Humble, TX, USA	6603	2010 40 ft High Cube Storage Container S/N: TCLU5275755 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Lake Worth, TX, USA

Lot #	Details	Lot #	Details
6604	2010 40 ft High Cube Storage Container S/N: TCLU5426419 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6608	40 ft High Cube Storage Container S/N: CMAU5446535 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Lake Worth, TX, USA
6604	2010 40 ft High Cube Storage Container S/N: TCLU5426419 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6609	40 ft High Cube Storage Container S/N: TCLU5652566 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:40 PM CDT Asset located in: Lake Worth, TX, USA
6605	2007 40 ft Standard Open Top Storage Container S/N: TRLU6429788 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6609	40 ft High Cube Storage Container S/N: TCLU5652566 C/W: Located in Lane 80 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:40 PM CDT Asset located in: Lake Worth, TX, USA
6605	2007 40 ft Standard Open Top Storage Container S/N: TRLU6429788 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6610	2007 40 ft High Cube Storage Container S/N: APHU6627870 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:40 PM CDT Asset located in: Humble, TX, USA
6606	40 ft Standard Open Top Storage Container S/N: TCLU7022150 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6610	2007 40 ft High Cube Storage Container S/N: APHU6627870 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:40 PM CDT Asset located in: Humble, TX, USA
6606	40 ft Standard Open Top Storage Container S/N: TCLU7022150 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6611	2021 40 ft High Cube Storage Container S/N: LCGU8149237 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:40 PM CDT Asset located in: Humble, TX, USA
6607	40 ft Standard Open Top Storage Container S/N: TRIU0496608 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6611	2021 40 ft High Cube Storage Container S/N: LCGU8149237 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:40 PM CDT Asset located in: Humble, TX, USA
6607	40 ft Standard Open Top Storage Container S/N: TRIU0496608 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Humble, TX, USA	6617	40 ft Standard Storage Container S/N: ZCSU252582-6 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA
6608	40 ft High Cube Storage Container S/N: CMAU5446535 C/W: Located in Lane 80 Spot 1, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:39 PM CDT Asset located in: Lake Worth, TX, USA	6617	40 ft Standard Storage Container S/N: ZCSU252582-6 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6618	40 ft Standard Storage Container S/N: KKFU1098950 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6622	20 ft Standard Multi-Door Storage Container S/N: YLEU2566915 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6618	40 ft Standard Storage Container S/N: KKFU1098950 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6623	20 ft Standard Multi-Door Storage Container S/N: XHCU3049186 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6619	40 ft Standard Storage Container S/N: HCGU4716942 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6623	20 ft Standard Multi-Door Storage Container S/N: XHCU3049186 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6619	40 ft Standard Storage Container S/N: HCGU4716942 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6624	20 ft Standard Multi-Door Storage Container S/N: XHCU3049340 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6620	40 ft Standard Storage Container S/N: TGHU4884340 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6624	20 ft Standard Multi-Door Storage Container S/N: XHCU3049340 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6620	40 ft Standard Storage Container S/N: TGHU4884340 C/W: Located in Lane 102 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6625	20 ft Standard Multi-Door Storage Container S/N: XHCU3001541 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6621	20 ft Standard Multi-Door Storage Container S/N: YLEU2566860 C/W: Located in Lane 36 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6625	20 ft Standard Multi-Door Storage Container S/N: XHCU3001541 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6621	20 ft Standard Multi-Door Storage Container S/N: YLEU2566860 C/W: Located in Lane 36 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:41 PM CDT Asset located in: Humble, TX, USA	6626	2026 20 ft Standard Storage Container (Unused) S/N: XHCU3063142 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA
6622	20 ft Standard Multi-Door Storage Container S/N: YLEU2566915 C/W: Located in Lane 102 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA	6626	2026 20 ft Standard Storage Container (Unused) S/N: XHCU3063142 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:42 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6631	2026 20 ft Standard Storage Container S/N: VSLU3250685 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6636	2011 20 ft Standard Storage Container S/N: TRHU2106644 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6631	2026 20 ft Standard Storage Container S/N: VSLU3250685 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6637	2006 20 ft Standard Storage Container S/N: TCLU1401074 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6632	2026 20 ft Standard Storage Container S/N: VSLU3250812 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6637	2006 20 ft Standard Storage Container S/N: TCLU1401074 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6632	2026 20 ft Standard Storage Container S/N: VSLU3250812 C/W: Located in Lane 101 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6638	2007 20 ft Standard Storage Container S/N: TCKU2951545 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6632A	2026 20 ft Standard Multi-Door Storage Container S/N: XHCU3001449 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6638	2007 20 ft Standard Storage Container S/N: TCKU2951545 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6632A	2026 20 ft Standard Multi-Door Storage Container S/N: XHCU3001449 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6639	20 ft Standard Storage Container S/N: MSKU4030890 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6635	8 ft x 20 ft Office Storage Container S/N: Not Available C/W: Located in Lane 73 Spot 0, A/C & Electrical Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6639	20 ft Standard Storage Container S/N: MSKU4030890 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6635	8 ft x 20 ft Office Storage Container S/N: Not Available C/W: Located in Lane 73 Spot 0, A/C & Electrical Usage: Not Available Lot closing time: Fri, Sep 18, 03:43 PM CDT Asset located in: Humble, TX, USA	6640	2006 20 ft Standard Storage Container S/N: TCLU7697997 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA
6636	2011 20 ft Standard Storage Container S/N: TRHU2106644 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA	6640	2006 20 ft Standard Storage Container S/N: TCLU7697997 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6641	2013 20 ft Standard Storage Container S/N: TRHU2794640 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Lake Worth, TX, USA	6645	2008 20 ft Standard Storage Container S/N: APZU3759221 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA
6641	2013 20 ft Standard Storage Container S/N: TRHU2794640 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:44 PM CDT Asset located in: Lake Worth, TX, USA	6646	20 ft Standard Storage Container S/N: CMAU0054887 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA
6642	2017 20 ft Standard Storage Container S/N: TLLU2132810 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA	6646	20 ft Standard Storage Container S/N: CMAU0054887 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA
6642	2017 20 ft Standard Storage Container S/N: TLLU2132810 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA	6647	2026 12 ft Storage Container S/N: YLEU2630932 C/W: Located in Lane 56 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA
6643	2012 20 ft Standard Storage Container S/N: TRHU2717469 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Lake Worth, TX, USA	6647	2026 12 ft Storage Container S/N: YLEU2630932 C/W: Located in Lane 56 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA
6643	2012 20 ft Standard Storage Container S/N: TRHU2717469 C/W: Located in Lane 79 Spot 1 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Lake Worth, TX, USA	6649	2026 12 ft Storage Container S/N: CTTN1200204 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6644	2008 20 ft Standard Storage Container S/N: TCKU3508378 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA	6649	2026 12 ft Storage Container S/N: CTTN1200204 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6644	2008 20 ft Standard Storage Container S/N: TCKU3508378 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA	6650	2026 11 ft Storage Container S/N: YLEU2621165 C/W: Located in Lane 56 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6645	2008 20 ft Standard Storage Container S/N: APZU3759221 C/W: Located in Lane 101 Spot 0 Usage: Not Available Lot closing time: Fri, Sep 18, 03:45 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6650	2026 11 ft Storage Container S/N: YLEU2621165 C/W: Located in Lane 56 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA	6653	2026 9 ft Storage Container S/N: CTTN0900199 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6651	2026 11 ft Storage Container S/N: CTTN1100193 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA	6654	2026 9 ft Storage Container S/N: GMPU9084023 C/W: Located in Lane 73 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6651	2026 11 ft Storage Container S/N: CTTN1100193 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA	6654	2026 9 ft Storage Container S/N: GMPU9084023 C/W: Located in Lane 73 Spot 0, One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6652	2026 10 ft Storage Container S/N: CTTN1000188 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA	6655	2026 8 ft Storage Container S/N: GMPU9085293 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window, Outer size: L 2489 mm x W 1970 mm x H 2184 mm Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6652	2026 10 ft Storage Container S/N: CTTN1000188 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA	6655	2026 8 ft Storage Container S/N: GMPU9085293 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window, Outer size: L 2489 mm x W 1970 mm x H 2184 mm Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA
6652A	2026 10 ft Storage Container S/N: YLEU2611172 C/W: Located in Lane 56 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA	6656	2026 8 ft Storage Container S/N: GMPU9078205 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6652A	2026 10 ft Storage Container S/N: YLEU2611172 C/W: Located in Lane 56 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA	6656	2026 8 ft Storage Container S/N: GMPU9078205 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6653	2026 9 ft Storage Container S/N: CTTN0900199 C/W: Located in Lane 73 Spot 0, One-Way, Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 03:46 PM CDT Asset located in: Humble, TX, USA		

Lot #	Details	Lot #	Details
6656A	Bad Boy Pro Series Zero-Turn Lawn Mower (Inoperable) S/N: BBZ6027K003111629 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2023 US EPA Label, 13X6.50-6 Front Tires, 20X10.00-8 Rear Tires, 5 ft Mower Usage: 745 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6658	Canycorn SC-75 Stand-On Concrete Buggy (Inoperable) S/N: 7302597 C/W: Located in Lane 52 Spot 4, Honda Predator 2 Cylinder Gasoline Engine, 8 in Rubber Tracks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6656A	Bad Boy Pro Series Zero-Turn Lawn Mower (Inoperable) S/N: BBZ6027K003111629 C/W: Located in Lane 100 Spot 0, Hydrostatic Drive, 2023 US EPA Label, 13X6.50-6 Front Tires, 20X10.00-8 Rear Tires, 5 ft Mower Usage: 745 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6658A	2014 Bomag BT65 Jumping Jack Tamper (Inoperable) S/N: 101541313834 C/W: Located in Lane 100 Spot 0, Honda GX100 1 Cylinder Gasoline Engine Usage: 48 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6657	Canycorn SC-75 Stand-On Concrete Buggy (Inoperable) S/N: 7303736 C/W: Located in Lane 36 Spot 0, Hydrostatic Drive, 2 Cylinder Gasoline Engine, 8 in Rubber Tracks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6658B	2020 Bomag BT65 Jumping Jack Tamper (Inoperable) S/N: 101541377618 C/W: Located in Lane 100 Spot 0, Honda GXR120 1 Cylinder Gasoline Engine Usage: 12 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6657	Canycorn SC-75 Stand-On Concrete Buggy (Inoperable) S/N: 7303736 C/W: Located in Lane 36 Spot 0, Hydrostatic Drive, 2 Cylinder Gasoline Engine, 8 in Rubber Tracks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6658C	Bomag BT65 Jumping Jack Tamper (Inoperable) S/N: 10154137616 C/W: Located in Lane 36 Spot 0, 2019 US EPA Label, Honda GXR120 Gasoline Engine Usage: 19 Hr Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6658	Canycorn SC-75 Stand-On Concrete Buggy (Inoperable) S/N: 7302597 C/W: Located in Lane 52 Spot 4, Honda Predator 2 Cylinder Gasoline Engine, 8 in Rubber Tracks Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6659	Husqvarna K770 Cut-Off Saw (Inoperable) S/N: 20215000595 C/W: Located in Lane 100 Spot 0 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted ; Buyer's responsibility for removal ; Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6660	Quantity of Thermoplastic & Type II Roadway Paint Striping Equipment (Inoperable) S/N: Not Available C/W: Located in Lane 53 Spot 1, Gasoline Engine Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6660B	Quantity of (10) Portable Generator Set (Inoperable) S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6660	Quantity of Thermoplastic & Type II Roadway Paint Striping Equipment (Inoperable) S/N: Not Available C/W: Located in Lane 53 Spot 1, Gasoline Engine Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6660C	Quantity of (8) Portable Generator Set (Inoperable) S/N: Not Available C/W: Located in Lane 54 Spot 3, (2) pressure washers (4) Demolition hammers Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6660A	Quantity of (14) Generator Sets S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6660C	Quantity of (8) Portable Generator Set (Inoperable) S/N: Not Available C/W: Located in Lane 54 Spot 3, (2) pressure washers (4) Demolition hammers Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6660A	Quantity of (14) Generator Sets S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6660D	Quantity of (7) Portable Generator Set (Inoperable) S/N: Not Available C/W: Located in Lane 54 Spot 1 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA
6660B	Quantity of (10) Portable Generator Set (Inoperable) S/N: Not Available C/W: Located in Lane 54 Spot 3 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA	6660D	Quantity of (7) Portable Generator Set (Inoperable) S/N: Not Available C/W: Located in Lane 54 Spot 1 Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6661	2009 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TCLU1073252 C/W: Located in Lane 80 Spot 1, 2010 Star Cool SCI-40 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Lake Worth, TX, USA	6663	2008 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8229758 C/W: Located in Lane 102 Spot 0, 2008 Carrier 69NT40-541-329 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA
6661	2009 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TCLU1073252 C/W: Located in Lane 80 Spot 1, 2010 Star Cool SCI-40 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:47 PM CDT Asset located in: Lake Worth, TX, USA	6664	2007 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8849358 C/W: Located in Lane 102 Spot 2, 2007 Carrier 69NT40 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA
6662	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRLU1612395 C/W: Located in Lane 102 Spot 0, 2003 Carrier 69NT40-511-354 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6664	2007 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8849358 C/W: Located in Lane 102 Spot 2, 2007 Carrier 69NT40 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA
6662	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRLU1612395 C/W: Located in Lane 102 Spot 0, 2003 Carrier 69NT40-511-354 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6664A	2007 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: APRU5727961 C/W: Located in Lane 102 Spot 0, 2007 Carrier 69NT40-551-510 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA
6663	2008 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8229758 C/W: Located in Lane 102 Spot 0, 2008 Carrier 69NT40-541-329 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6664A	2007 40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: APRU5727961 C/W: Located in Lane 102 Spot 0, 2007 Carrier 69NT40-551-510 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA

Lot #	Details	Lot #	Details
6665	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8653658 C/W: Located in Lane 102 Spot 0, 2009 Carrier 69NT40-541-320 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6668	Portable Concrete Mixer (Inoperable) S/N: Not Available C/W: Honda GX240 1 Cylinder Gasoline Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA
6665	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8653658 C/W: Located in Lane 102 Spot 0, 2009 Carrier 69NT40-541-320 Reefer Unit Usage: Not Available Notes: Inoperable items must be removed from yard October 2nd and cannot be relisted; Buyer's responsibility for removal; Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6669	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526062303A C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:49 PM CDT Asset located in: Midland, TX, USA
6667	Whiteman WC91h Mortar and Grout Mixer (Inoperable) S/N: LK26740 C/W: Located in Lane 46 Spot 0, Honda 1 Cylinder Gasoline Engine, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6670	Quantity of (6) 2026 AGT 12EX-SET6 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET626062302A C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake, (1) Auger w/ 8 in Bit ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:49 PM CDT Asset located in: Midland, TX, USA
6667	Whiteman WC91h Mortar and Grout Mixer (Inoperable) S/N: LK26740 C/W: Located in Lane 46 Spot 0, Honda 1 Cylinder Gasoline Engine, Ball Hitch Carrier Trailer Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6671	Quantity of (6) 2026 AGT 12EX-SET6 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET626062303A C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake, (1) Auger w/ 8 in Bit ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:49 PM CDT Asset located in: Midland, TX, USA
6668	Portable Concrete Mixer (Inoperable) S/N: Not Available C/W: Honda GX240 1 Cylinder Gasoline Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:48 PM CDT Asset located in: Humble, TX, USA	6672	Quantity of (3) Excavator Bucket S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:49 PM CDT Asset located in: Midland, TX, USA
		6673	Quantity of (2) Excavator Bucket S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:49 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
6674	CNH Industrial 89 in 1 m3 General Purpose Wheel Loader Bucket (Unused) S/N: 47352251 C/W: 2.5 in Pin Diameter, 36.5 in Center of Pin Boss to Center of Pin Boss, 31 in Inside to Inside Pin Boss Spacing Usage: Not Available Lot closing time: Fri, Sep 18, 03:49 PM CDT Asset located in: Midland, TX, USA	6681	Load"N" Go Truck Flatbed Body S/N: 13121061-LB C/W: Steel, 7 ft 10 in Body Length Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA
6675	CNH Industrial 89 in 1 m3 General Purpose Wheel Loader Bucket (Unused) S/N: 47352252 C/W: 2.5 in Pin Diameter, 36.5 in Center of Pin Boss to Center of Pin Boss, 31 in Inside to Inside Pin Boss Spacing Usage: Not Available Lot closing time: Fri, Sep 18, 03:49 PM CDT Asset located in: Midland, TX, USA	6682	CM RD-02845842 Truck Flatbed Body S/N: MB00377191 C/W: Steel, To Fit 43 in Outside to Outside Frame, 102 ft Body Length Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA
6676	144 in 6000 lb Wheel Loader Material Handling Arm S/N: 120381 Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA	6683	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment - Fits Truck S/N: 1626 Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA
6677	144 in 6000 lb Wheel Loader Material Handling Arm S/N: 106593 Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA	6684	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment - Fits Truck S/N: 1616 Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA
6678	144 in 6000 lb Wheel Loader Material Handling Arm S/N: 10293491 Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA	6685	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment - Fits Truck S/N: 1627 Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA
6679	Quantity of (2) Cat Wheel Loader Counterweight S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA	6686	2026 Neks Hydraulic Fifth Wheel Wrecker Attachment - Fits Truck S/N: 1617 Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA
6679	Quantity of (2) Cat Wheel Loader Counterweight S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA	6688	2026 X-STAR 20 ft x 101 in Loading Ramp (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA
6680	Knapheide AL-PGNB-96 Truck Flatbed Body S/N: 0630261 C/W: Aluminum, To Fit 34 in Outside to Outside Frame, 114 ft Body Length Usage: Not Available Lot closing time: Fri, Sep 18, 03:50 PM CDT Asset located in: Midland, TX, USA	6688	2026 X-STAR 20 ft x 101 in Loading Ramp (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
6688A	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA	6688D	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6688A	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA	6688D	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6688B	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA	6688E	X-STAR 750 gal Portable Steel Fuel Tank (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6688B	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:51 PM CDT Asset located in: Midland, TX, USA	6688E	X-STAR 750 gal Portable Steel Fuel Tank (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6688C	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6691	2021 Wylie Pressure Washer S/N: 5VUTJ2225MP000009 C/W: Water Heater, 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 1,777 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6688C	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6691	2021 Wylie Pressure Washer S/N: 5VUTJ2225MP000009 C/W: Water Heater, 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 1,777 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6688C	2026 X-STAR 250GL 250 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, 20 GPM, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6691A	2021 Wylie Pressure Washer S/N: 5VUTJ2220MP000001 C/W: 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 1,166 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA

Lot #	Details	Lot #	Details
6691A	2021 Wylie Pressure Washer S/N: 5VUTJ2220MP000001 C/W: 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 1,166 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6695	2021 Wylie Water Tank Trailer S/N: 5VUTY1325MP000001 C/W: Honda Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6692	2021 Wylie Pressure Washer S/N: 5VUTJ2228MP000005 C/W: Water Heater, 1250 gal Water Supply, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 1,253 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6695	2021 Wylie Water Tank Trailer S/N: 5VUTY1325MP000001 C/W: Honda Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA
6692	2021 Wylie Pressure Washer S/N: 5VUTJ2228MP000005 C/W: Water Heater, 1250 gal Water Supply, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 1,253 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6696	2018 Wylie Pressure Washer S/N: 5VUTJ2226JP000001 C/W: Water Heater, 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:53 PM CDT Asset located in: Midland, TX, USA
6693	2021 Wylie SP0499 Pressure Washer S/N: 5VUTJ2223MP000008 C/W: Water Heater, 1250 gal Water Supply, Spray Wand, Trailer Mounted, Honda 2 Cylinder 688 cc Gasoline Engine Usage: 1,067 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6696	2018 Wylie Pressure Washer S/N: 5VUTJ2226JP000001 C/W: Water Heater, 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 03:53 PM CDT Asset located in: Midland, TX, USA
6693	2021 Wylie SP0499 Pressure Washer S/N: 5VUTJ2223MP000008 C/W: Water Heater, 1250 gal Water Supply, Spray Wand, Trailer Mounted, Honda 2 Cylinder 688 cc Gasoline Engine Usage: 1,067 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6697	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26061702J C/W: 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:54 PM CDT Asset located in: Livingston, LA, USA
6694	2021 Wylie Pressure Washer S/N: 5VUTJ2221MP000007 C/W: Water Heater, 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 726 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6697	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26061702J C/W: 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:54 PM CDT Asset located in: Livingston, LA, USA
6694	2021 Wylie Pressure Washer S/N: 5VUTJ2221MP000007 C/W: Water Heater, 1250 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda Gasoline Engine Usage: 726 Hr Lot closing time: Fri, Sep 18, 03:52 PM CDT Asset located in: Midland, TX, USA	6698	Quantity of (8) 96 in x 48 in Polyiso Insulation S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:54 PM CDT Asset located in: Livingston, LA, USA
		6699	Quantity of (8) 96 in x 48 in Polyiso Insulation S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:54 PM CDT Asset located in: Livingston, LA, USA

Lot #	Details	Lot #	Details
6700	Quantity of (8) 96 in x 48 in Polyiso Insulation S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:54 PM CDT Asset located in: Livingston, LA, USA	6706	2026 Mower King SSEFGC175 77 in Skid Steer Flail Mower (Unused) S/N: SSEFGC17526071702L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:55 PM CDT Asset located in: Oklahoma City, OK, USA
6701	2015 NLB 10145DC Water Blaster (Inoperable) S/N: U515011-4 C/W: 40000 psi Rating, Cat C4.4 4 Cylinder Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:54 PM CDT Asset located in: Livingston, LA, USA	6707	2026 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC7226071703L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:55 PM CDT Asset located in: Oklahoma City, OK, USA
6701	2015 NLB 10145DC Water Blaster (Inoperable) S/N: U515011-4 C/W: 40000 psi Rating, Cat C4.4 4 Cylinder Diesel Engine Usage: Not Available Notes: Inoperable items must be removed from yard by October 2nd and cannot be relisted; Buyer's responsibility for removal. RBA will not be able to assist with loading. Lot closing time: Fri, Sep 18, 03:54 PM CDT Asset located in: Livingston, LA, USA	6708	2026 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC7226071704L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:55 PM CDT Asset located in: Oklahoma City, OK, USA
6702	2026 GIYI GY-MDM50 33 in Mini Disc Skid Steer Mulcher (Unused) S/N: XHYYPHJ260714 Usage: Not Available Lot closing time: Fri, Sep 18, 03:55 PM CDT Asset located in: Oklahoma City, OK, USA	6709	2026 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC7226071702L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:56 PM CDT Asset located in: Oklahoma City, OK, USA
6703	2026 GIYI GYx-DM43 43 in Disc Skid Steer Mulcher (Unused) S/N: XYPTHJ260783 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:55 PM CDT Asset located in: Oklahoma City, OK, USA	6710	2026 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC7226071701L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:56 PM CDT Asset located in: Oklahoma City, OK, USA
6704	2026 GIYI GYx-DM43 43 in Disc Skid Steer Mulcher (Unused) S/N: XYPTHJ260782 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:55 PM CDT Asset located in: Oklahoma City, OK, USA	6711	2026 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC7226071705L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:56 PM CDT Asset located in: Oklahoma City, OK, USA
6705	2026 Mower King SSEFGC175 77 in Skid Steer Flail Mower (Unused) S/N: SSEFGC17526071701L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:55 PM CDT Asset located in: Oklahoma City, OK, USA	6712	2026 Mower King ECSSCT72 60 in Skid Steer Trencher (Unused) S/N: ECSSCT7226071701L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:56 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6713	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226071701L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:56 PM CDT Asset located in: Oklahoma City, OK, USA	6721	2026 GIYI GY-HWG72 72 in Q/C Skeleton Skeleton Skid Steer Grapple (Unused) S/N: C-XXLKZMQ2607077 Usage: Not Available Lot closing time: Fri, Sep 18, 03:57 PM CDT Asset located in: Oklahoma City, OK, USA
6714	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226071702L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:56 PM CDT Asset located in: Oklahoma City, OK, USA	6722	2026 GIYI GY-RB44 44 in Q/C Skeleton Mini Skid Steer Bucket (Unused) S/N: ZT-X YSCD2607174 Usage: Not Available Lot closing time: Fri, Sep 18, 03:58 PM CDT Asset located in: Oklahoma City, OK, USA
6715	2026 GIYI GY-BSG45 4 in Skid Steer Stump Grinder (Unused) S/N: D-SZYMJ2607104 Usage: Not Available Lot closing time: Fri, Sep 18, 03:56 PM CDT Asset located in: Oklahoma City, OK, USA	6723	2026 GIYI GY-RB44 44 in Skeleton Mini Skid Steer Bucket (Unused) S/N: ZT-X YSCD2607172 Usage: Not Available Lot closing time: Fri, Sep 18, 03:58 PM CDT Asset located in: Oklahoma City, OK, USA
6716	2026 GIYI GY-BSG45 Skid Steer Stump Grinder (Unused) S/N: D-SZYMJ2607103 Usage: Not Available Lot closing time: Fri, Sep 18, 03:57 PM CDT Asset located in: Oklahoma City, OK, USA	6724	2026 GIYI GY-RB66 66 in Q/C Skeleton Skid Steer Bucket (Unused) S/N: C-D YSCD2607235 Usage: Not Available Lot closing time: Fri, Sep 18, 03:58 PM CDT Asset located in: Oklahoma City, OK, USA
6717	2026 AGT STSD10 66 in 3-Point & Skid Steer Seeder (Unused) S/N: STSD10260108280 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:57 PM CDT Asset located in: Oklahoma City, OK, USA	6725	2026 GIYI GY-RB66 66 in Q/C Skeleton Skid Steer Bucket (Unused) S/N: C-D YSCD2607234 Usage: Not Available Lot closing time: Fri, Sep 18, 03:58 PM CDT Asset located in: Oklahoma City, OK, USA
6718	2026 AGT STSD10 66 in 3-Point & Skid Steer Seeder (Unused) S/N: STSD10260108284 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:57 PM CDT Asset located in: Oklahoma City, OK, USA	6726	2026 GIYI GY-P680 Q/C Skid Steer Breaker (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 03:58 PM CDT Asset located in: Oklahoma City, OK, USA
6719	2026 GIYI GY-CLG72 72 in Q/C Log Skid Steer Grapple (Unused) S/N: C-HXZMQ2607286 Usage: Not Available Lot closing time: Fri, Sep 18, 03:57 PM CDT Asset located in: Oklahoma City, OK, USA	6727	2026 GIYI GY-P680 Q/C Skid Steer Breaker (Unused) S/N: PSC680260794 Usage: Not Available Lot closing time: Fri, Sep 18, 03:58 PM CDT Asset located in: Oklahoma City, OK, USA
6720	2026 GIYI GY-CLG72 72 in Q/C Log Skid Steer Grapple (Unused) S/N: C-HXZMQ2607287 Usage: Not Available Lot closing time: Fri, Sep 18, 03:57 PM CDT Asset located in: Oklahoma City, OK, USA	6728	2026 GIYI GY-D680 8 in Skid Steer Post Driver (Unused) S/N: DZC680260733 Usage: Not Available Lot closing time: Fri, Sep 18, 03:58 PM CDT Asset located in: Oklahoma City, OK, USA
		6729	2026 GIYI GY-D680 8 in Skid Steer Post Driver (Unused) S/N: DZC680260772 Usage: Not Available Lot closing time: Fri, Sep 18, 03:59 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6730	2026 GIYI GY-MTB87 Mini Telescopic Skid Steer Boom (Unused) S/N: ZT-X HYSSDB260708 Usage: Not Available Lot closing time: Fri, Sep 18, 03:59 PM CDT Asset located in: Oklahoma City, OK, USA	6738	2026 GIYI GY-SF60 60 in Skid Steer Forks (Unused) S/N: DCYHC2607287 C/W: Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 04:00 PM CDT Asset located in: Oklahoma City, OK, USA
6731	2026 GIYI GY-MTB87 Mini Telescopic Skid Steer Boom (Unused) S/N: ZT-X HYSSDB260723 Usage: Not Available Lot closing time: Fri, Sep 18, 03:59 PM CDT Asset located in: Oklahoma City, OK, USA	6739	2026 GIYI GY-SF60 60 in Skid Steer Forks (Unused) S/N: DCYHC2607286 C/W: Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 04:00 PM CDT Asset located in: Oklahoma City, OK, USA
6732	2026 GIYI GY-STB47 131 in Skid Steer Telescopic Boom (Unused) S/N: ZTHYSSDB2607168 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:59 PM CDT Asset located in: Oklahoma City, OK, USA	6740	Quantity of (10) 2026 Mower King SAIL100 48 in Skid Steer Forks (Unused) S/N: SA26071702L-10L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:00 PM CDT Asset located in: Oklahoma City, OK, USA
6733	2026 GIYI GY-STB47 131 in Skid Steer Telescopic Boom (Unused) S/N: ZTHYSSDB2607166 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:59 PM CDT Asset located in: Oklahoma City, OK, USA	6741	Quantity of (4) 2026 Mower King SAIL100 48 in Skid Steer Forks (Unused) S/N: SA26071713L-14L C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:00 PM CDT Asset located in: Oklahoma City, OK, USA
6734	2026 GIYI GY-STB47 131 in Skid Steer Telescopic Boom (Unused) S/N: ZTHYSSDB2607165 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:59 PM CDT Asset located in: Oklahoma City, OK, USA	6742	2026 GIYI GY-DHC 60 in Skid Steer Forks (Unused) S/N: DHC2607663 Usage: Not Available Lot closing time: Fri, Sep 18, 04:01 PM CDT Asset located in: Oklahoma City, OK, USA
6735	2026 GIYI GY-STB47 131 in Skid Steer Telescopic Boom (Unused) S/N: ZTHYSSDB2607167 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 03:59 PM CDT Asset located in: Oklahoma City, OK, USA	6743	2026 GIYI GY-DHC 60 in Skid Steer Forks (Unused) S/N: DHC2607706 Usage: Not Available Lot closing time: Fri, Sep 18, 04:01 PM CDT Asset located in: Oklahoma City, OK, USA
6736	2026 GIYI GY-SF60 60 in Skid Steer Forks (Unused) S/N: DCYHC2607285 C/W: Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 04:00 PM CDT Asset located in: Oklahoma City, OK, USA	6744	2026 GIYI GY-DHC 60 in Skid Steer Forks (Unused) S/N: DHC2607705 Usage: Not Available Lot closing time: Fri, Sep 18, 04:01 PM CDT Asset located in: Oklahoma City, OK, USA
6737	2026 GIYI GY-SF60 60 in Skid Steer Forks (Unused) S/N: DCYHC2607198 C/W: Fork Positioner Usage: Not Available Lot closing time: Fri, Sep 18, 04:00 PM CDT Asset located in: Oklahoma City, OK, USA	6745	2026 GIYI GY-DHC 60 in Skid Steer Forks (Unused) S/N: DHC2607704 Usage: Not Available Lot closing time: Fri, Sep 18, 04:01 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6746	2026 GIYI GY-DHC 60 in Skid Steer Forks (Unused) S/N: DHC2607664 Usage: Not Available Lot closing time: Fri, Sep 18, 04:01 PM CDT Asset located in: Oklahoma City, OK, USA	6755	2026 GIYI 16 in Cat 305 Excavator Auger (Unused) S/N: B-305TZLXZ-583 Usage: Not Available Lot closing time: Fri, Sep 18, 04:02 PM CDT Asset located in: Oklahoma City, OK, USA
6747	2026 GIYI GY-DHC 60 in Skid Steer Forks (Unused) S/N: DHC2607662 Usage: Not Available Lot closing time: Fri, Sep 18, 04:01 PM CDT Asset located in: Oklahoma City, OK, USA	6756	2026 GIYI 16 in Cat 305 Excavator Auger (Unused) S/N: B-305TZLXZ-579 Usage: Not Available Lot closing time: Fri, Sep 18, 04:03 PM CDT Asset located in: Oklahoma City, OK, USA
6748	2026 GIYI GY-HF47 47 in Skid Steer Bale Spear (Unused) S/N: C-YKC2606072 Usage: Not Available Lot closing time: Fri, Sep 18, 04:01 PM CDT Asset located in: Oklahoma City, OK, USA	6757	2026 GIYI 16 in Cat 305 Excavator Auger (Unused) S/N: B-305TZLXZ-535 Usage: Not Available Lot closing time: Fri, Sep 18, 04:03 PM CDT Asset located in: Oklahoma City, OK, USA
6749	2026 GIYI GY-HF47 47 in Skid Steer Bale Spear (Unused) S/N: C-YKC2606073 Usage: Not Available Lot closing time: Fri, Sep 18, 04:02 PM CDT Asset located in: Oklahoma City, OK, USA	6758	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26071702L C/W: (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:03 PM CDT Asset located in: Oklahoma City, OK, USA
6750	2026 GIYI GY-BF47 47 in Skid Steer Bale Spear (Unused) S/N: C-YKEC2607246 Usage: Not Available Lot closing time: Fri, Sep 18, 04:02 PM CDT Asset located in: Oklahoma City, OK, USA	6759	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26071701L C/W: (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:03 PM CDT Asset located in: Oklahoma City, OK, USA
6751	2026 GIYI GY-BF47 47 in Skid Steer Bale Spear (Unused) S/N: C-YKEC2607247 Usage: Not Available Lot closing time: Fri, Sep 18, 04:02 PM CDT Asset located in: Oklahoma City, OK, USA	6760	Quantity of (9) 2026 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA26071703L C/W: (1) 8 in Bucket, (1) 20 in Bucket, (1) 32 in Bucket, (1) Quick Coupler, (1) Ripper, (1) Grapple, (1) Rake, (1) 8 in Auger, (1) 12 in Auger ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:03 PM CDT Asset located in: Oklahoma City, OK, USA
6752	2026 GIYI GY-BF39 39 in Mini Skid Steer Bale Spear (Unused) S/N: C-X YKEC2606049 Usage: Not Available Lot closing time: Fri, Sep 18, 04:02 PM CDT Asset located in: Oklahoma City, OK, USA		
6753	2026 GIYI GY-BF39 39 in Mini Skid Steer Bale Spear (Unused) S/N: C-X YKEC2606048 Usage: Not Available Lot closing time: Fri, Sep 18, 04:02 PM CDT Asset located in: Oklahoma City, OK, USA		
6754	2026 GIYI GY-EDM320 39 in Excavator Disc Mulcher (Unused) S/N: 320YPHJ260720 Usage: Not Available Lot closing time: Fri, Sep 18, 04:02 PM CDT Asset located in: Oklahoma City, OK, USA		

Lot #	Details	Lot #	Details
6761	Quantity of (8) 2026 GIYI Cat 301 GYA-8 Mini Excavator Attachments (Unused) S/N: C-301SJB-1726 C/W: (1) Rake, (1) Ripper, (1) Grapple, (1) Auger w/ 12 in & 16 in Auger Bits, (1) 8 in Narrow Bucket, (1) 24 in Bucket, (1) 32 in Bucket ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:03 PM CDT Asset located in: Oklahoma City, OK, USA	6767	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6912 C/W: Buckets, Augers, and Rakes Usage: Not Available Lot closing time: Fri, Sep 18, 04:04 PM CDT Asset located in: Oklahoma City, OK, USA
6762	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526071701L C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:04 PM CDT Asset located in: Oklahoma City, OK, USA	6768	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6913 C/W: Buckets, Rakes, and Augers Usage: Not Available Lot closing time: Fri, Sep 18, 04:04 PM CDT Asset located in: Oklahoma City, OK, USA
6763	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526071703L C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:04 PM CDT Asset located in: Oklahoma City, OK, USA	6769	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6914 C/W: Buckets, Rakes, and Augers Usage: Not Available Lot closing time: Fri, Sep 18, 04:05 PM CDT Asset located in: Oklahoma City, OK, USA
6764	Quantity of (5) 2026 AGT 12EX-SET5 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET526071702L C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:04 PM CDT Asset located in: Oklahoma City, OK, USA	6770	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6911 C/W: Buckets, Rakes, and Augers Usage: Not Available Lot closing time: Fri, Sep 18, 04:05 PM CDT Asset located in: Oklahoma City, OK, USA
6765	Quantity of (6) 2026 AGT 12EX-SET6 Mini Excavator Attachment Set (Unused) S/N: 12EX-SET626071701L C/W: (1) 10 in Digging Bucket, (1) 24 in Cleanup Bucket, (1) Quick Coupler, (1) Ripper, (1) Rake, (1) Auger w/ 8 in Bit ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:04 PM CDT Asset located in: Oklahoma City, OK, USA	6771	2026 GIYI GY-FLA79 126 in Forklift Extendable Boom (Unused) S/N: ZT-KTJCCDB2606235 Usage: Not Available Lot closing time: Fri, Sep 18, 04:05 PM CDT Asset located in: Oklahoma City, OK, USA
6766	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-6915 C/W: Buckets, Rakes, and Augers Usage: Not Available Lot closing time: Fri, Sep 18, 04:04 PM CDT Asset located in: Oklahoma City, OK, USA	6772	2026 GIYI GY-FLA79 126 in Forklift Extendable Boom (Unused) S/N: ZT-KTJCCDB260694 Usage: Not Available Lot closing time: Fri, Sep 18, 04:05 PM CDT Asset located in: Oklahoma City, OK, USA
		6773	2026 GIYI GY-TB47 132 in Forklift Extendable Boom (Unused) S/N: ZT-CCSSDB2607138 Usage: Not Available Lot closing time: Fri, Sep 18, 04:05 PM CDT Asset located in: Oklahoma City, OK, USA
		6774	2026 GIYI GY-TB47 132 in Forklift Extendable Boom (Unused) S/N: ZT-CCSSDB2607137 Usage: Not Available Lot closing time: Fri, Sep 18, 04:05 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6775	2026 GIYI GY-TB47 132 in Forklift Extendable Boom (Unused) S/N: ZT-CCSSDB2607140 Usage: Not Available Lot closing time: Fri, Sep 18, 04:05 PM CDT Asset located in: Oklahoma City, OK, USA	6785	Topcon FC-5000 Data Collection System S/N: 182673 Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6776	2026 GIYI GY-TB47 132 in Forklift Extendable Boom (Unused) S/N: ZT-CCSSDB2607139 Usage: Not Available Lot closing time: Fri, Sep 18, 04:06 PM CDT Asset located in: Oklahoma City, OK, USA	6785	Topcon FC-5000 Data Collection System S/N: 182673 Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6777	2018 Hernco Chemical Body S/N: H1767 Usage: Not Available Notes: Buyer's responsibility for removal. RBA will not be able to assist with loading Lot closing time: Fri, Sep 18, 04:06 PM CDT Asset located in: Oklahoma City, OK, USA	6786	Topcon FC-5000 Data Collection System S/N: 235636 Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6779	2026 Neks Fifth Wheel Wrecker Attachment S/N: 1603 Usage: Not Available Lot closing time: Fri, Sep 18, 04:06 PM CDT Asset located in: Oklahoma City, OK, USA	6786	Topcon FC-5000 Data Collection System S/N: 235636 Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6780	2026 Neks Fifth Wheel Wrecker Attachment S/N: 1653 Usage: Not Available Lot closing time: Fri, Sep 18, 04:06 PM CDT Asset located in: Oklahoma City, OK, USA	6787	2026 SDLOOL SL90 Vibratory Plate Compactor S/N: 90PBH260777 C/W: 2026 US EPA Label, 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6781	2026 Neks Fifth Wheel Wrecker Attachment S/N: 1601 Usage: Not Available Lot closing time: Fri, Sep 18, 04:06 PM CDT Asset located in: Oklahoma City, OK, USA	6787	2026 SDLOOL SL90 Vibratory Plate Compactor S/N: 90PBH260777 C/W: 2026 US EPA Label, 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6782	2026 Neks Fifth Wheel Wrecker Attachment S/N: 1602 Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA	6788	2026 SDLOOL SL90 Vibratory Plate Compactor (Unused) S/N: 90PBH260776 C/W: 2026 US EPA Label, 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6783	2026 GIYI TE31 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC2607190 Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA	6788	2026 SDLOOL SL90 Vibratory Plate Compactor (Unused) S/N: 90PBH260776 C/W: 2026 US EPA Label, 1 Cylinder Gasoline Engine Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA
6784	2026 GIYI TE31 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC2607189 Usage: Not Available Lot closing time: Fri, Sep 18, 04:07 PM CDT Asset located in: Oklahoma City, OK, USA		

Lot #	Details	Lot #	Details
6789	2026 SKLP SK-S5030 30 ft x 50 ft Large Scale Storage Building (Unused) S/N: F01381 C/W: 17 ft Total Height, 12 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA	6792	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01364 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA
6789	2026 SKLP SK-S5030 30 ft x 50 ft Large Scale Storage Building (Unused) S/N: F01381 C/W: 17 ft Total Height, 12 ft Sidewall Height, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA	6793	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01363 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA
6790	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01367 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA	6793	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01363 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA
6790	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01367 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA	6794	2026 SKLP SK-S2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: F01380 Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA
6791	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01366 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA	6794	2026 SKLP SK-S2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: F01380 Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA
6791	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01366 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA	6795	2026 SKLP SK-S2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: F01353 Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA
6792	2026 SKLP SK-ZP20 20 ft x 30 ft All-Steel Carport (Unused) S/N: F01364 C/W: 12 ft Total Height, 10 ft Sidewall Height Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA	6795	2026 SKLP SK-S2012 20 ft x 12 ft Livestock Shelter (Unused) S/N: F01353 Usage: Not Available Lot closing time: Fri, Sep 18, 04:08 PM CDT Asset located in: Oklahoma City, OK, USA
		6796	2026 SKLP SK-S2012 20FT X 12FT Livestock Shelter (Unused) S/N: F01354 Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6796	2026 SKLP SK-S2012 20FT X 12FT Livestock Shelter (Unused) S/N: F01354 Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA	6800	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26071701L C/W: 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA
6797	2026 SKLP 5 ft x 10 ft (0.4 In Thick) Steel Plate (Unused) S/N: E91124 Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA	6801	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003601 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA
6797	2026 SKLP 5 ft x 10 ft (0.4 In Thick) Steel Plate (Unused) S/N: E91124 Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA	6801	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003601 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA
6798	2026 SKLP 5 ft x 10 ft (0.4 In Thick) Steel Plate (Unused) S/N: E91125 Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA	6802	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003600 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA
6798	2026 SKLP 5 ft x 10 ft (0.4 In Thick) Steel Plate (Unused) S/N: E91125 Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA	6802	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003600 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA
6799	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26071702L C/W: 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA	6803	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003598 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA
6800	2026 AGT AC 40 gal Air Compressor (Unused) S/N: AC26071701L C/W: 175 psi Working Pressure, RATO 1 Cylinder 7.46 kW 302 cc Gasoline Engine, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:09 PM CDT Asset located in: Oklahoma City, OK, USA	6803	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003598 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6804	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003599 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA	6807	2026 AGT ATK-WB24A Wheel Balancer (Unused) S/N: ATK202606259 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA
6804	2026 AGT ATK-B1000 2 Post 10000 lb Vehicle Lift (Unused) S/N: XHYZ202607003599 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA	6808	2026 AGT ATK-WB24A Wheel Balancer (Unused) S/N: ATK202606260 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA
6805	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATKTC242026060053 C/W: 110V, 2 HP Electric Motor ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA	6808	2026 AGT ATK-WB24A Wheel Balancer (Unused) S/N: ATK202606260 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA
6805	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATKTC242026060053 C/W: 110V, 2 HP Electric Motor ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA	6809	Quantity of (50) 2026 SKLP SKH50 12' Long Galvalume Steel Sheets (Unused) S/N: F01368 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA
6806	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK202606349 C/W: 110V, 2 HP Electric Motor ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA	6809	Quantity of (50) 2026 SKLP SKH50 12' Long Galvalume Steel Sheets (Unused) S/N: F01368 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA
6806	2026 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK202606349 C/W: 110V, 2 HP Electric Motor ; Product images displayed are stock photos. Item is new /unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA	6810	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets 12' Long (Unused) S/N: F01535 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA
6807	2026 AGT ATK-WB24A Wheel Balancer (Unused) S/N: ATK202606259 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:10 PM CDT Asset located in: Oklahoma City, OK, USA	6810	Quantity of (50) 2026 SKLP SKH50 Galvalume Steel Sheets 12' Long (Unused) S/N: F01535 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6811	Quantity of (50) 2026 SKLP SKH50 12' Long Galvalume Steel Sheets (Unused) S/N: F01534 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6815	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA
6811	Quantity of (50) 2026 SKLP SKH50 12' Long Galvalume Steel Sheets (Unused) S/N: F01534 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6815	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA
6812	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6816	Quantity of (4) Pallets of Polyiso Insulation S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA
6812	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6816	Quantity of (4) Pallets of Polyiso Insulation S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA
6812	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6817	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA
6813	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6817	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA
6813	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6818	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 4 ft x 4ft x 4 ft Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA
6814	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6818	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 4 ft x 4ft x 4 ft Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA
6814	Quantity of (50) 2026 SKLP SK-XH50 3 ft x 10 ft Galvalume Steel Sheets (Unused) S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:11 PM CDT Asset located in: Oklahoma City, OK, USA	6819	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA

Lot #	Details	Lot #	Details
6819	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 8'3"W x 4'L x 4'4"H Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA	6824	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01373 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6820	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 4 ft x 4 ft x 4 ft Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA	6824	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01373 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6820	Quantity of (8) Polyiso Insulation S/N: Not Available C/W: Each pallet is 4 ft x 4 ft x 4 ft Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA	6825	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01375 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6821	2026 SKLP SK-HJ6 Metal Storage (Unused) S/N: E86251 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA	6825	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01375 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6821	2026 SKLP SK-HJ6 Metal Storage (Unused) S/N: E86251 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:12 PM CDT Asset located in: Oklahoma City, OK, USA	6826	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01376 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6822	2026 SKLP SK-HJ6 Metal Storage (Unused) S/N: E86250 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA	6826	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01376 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6822	2026 SKLP SK-HJ6 Metal Storage (Unused) S/N: E86250 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA	6827	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202605437 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6823	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01374 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA	6827	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202605437 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA
6823	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F01374 Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA		

Lot #	Details	Lot #	Details
6828	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202605438 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA	6832	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ2607177 C/W: 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA
6828	2026 AGT YC-26G Portable Sawmill (Unused) S/N: YC-26G202605438 C/W: Gasoline Powered, 26 in Max Log Diameter, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Lot closing time: Fri, Sep 18, 04:13 PM CDT Asset located in: Oklahoma City, OK, USA	6833	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ2607178 C/W: 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA
6829	2026 AGT YC32-G Portable Sawmill (Unused) S/N: YC-32G202606072 Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA	6833	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ2607178 C/W: 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA
6829	2026 AGT YC32-G Portable Sawmill (Unused) S/N: YC-32G202606072 Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA	6834	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015334 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA
6830	2026 AGT YC32-G Portable Sawmill (Unused) S/N: YC-32G202606071 Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA	6834	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015334 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA
6830	2026 AGT YC32-G Portable Sawmill (Unused) S/N: YC-32G202606071 Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA	6835	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015340 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA
6831	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ2607179 C/W: 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA	6835	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5015340 C/W: One-Way Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA
6831	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ2607179 C/W: 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA	6836	2026 10 ft Standard Storage Container (Unused) S/N: CTTN0001386 C/W: Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 04:15 PM CDT Asset located in: Oklahoma City, OK, USA
6832	2026 SDLOOL SL-LM1000Q Remote Control Lawn Mower (Unused) S/N: 1000QYGCJ2607177 C/W: 2026 US EPA Label, 39 in Mower Usage: Not Available Lot closing time: Fri, Sep 18, 04:14 PM CDT Asset located in: Oklahoma City, OK, USA		

Lot #	Details	Lot #	Details
6836	2026 10 ft Standard Storage Container (Unused) S/N: CTTN0001386 C/W: Man Door, Window Usage: Not Available Lot closing time: Fri, Sep 18, 04:15 PM CDT Asset located in: Oklahoma City, OK, USA	6842	Ingersoll Rand Air Compressor S/N: CBV126926 Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA
6837	Cat 48 in Wheel Loader Forks S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA	6842	Ingersoll Rand Air Compressor S/N: CBV126926 Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA
6838	Pemberton 68 in Wheel Loader Forks S/N: 82630198 Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA	6843	Ingersoll Rand Skid-Mounted Electric Air Compressor S/N: PX4272U04328 Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA
6838A	JRB 58 in Q/C Wheel Loader Forks - Fits Case 621G S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA	6843	Ingersoll Rand Skid-Mounted Electric Air Compressor S/N: PX4272U04328 Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA
6839	96 in Material Handling Arm S/N: Not Available Usage: Not Available Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA	6845	Hydra Rig Wet Kit Assembly S/N: C011098 Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA
6840	2025 Kubota Z232KW Zero-Turn Lawn Mower S/N: KBGHER0PPGG13325 C/W: Hydrostatic Drive, 2023 US EPA Label, 11x4.00-5 Front Tires, 18x7.50-10 Rear Tires, Kubota RCK42P-122Z 3 ft 6 in Mower Usage: 3 Hr Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA	6846	Quantity of (8) Coil Tubing Guide Arms S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA
6840	2025 Kubota Z232KW Zero-Turn Lawn Mower S/N: KBGHER0PPGG13325 C/W: Hydrostatic Drive, 2023 US EPA Label, 11x4.00-5 Front Tires, 18x7.50-10 Rear Tires, Kubota RCK42P-122Z 3 ft 6 in Mower Usage: 3 Hr Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA	6846	Quantity of (8) Coil Tubing Guide Arms S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA
6841	Quincy QSI 235 Skid-Mounted Electric Air Compressor S/N: QSI235WCW231607 Usage: 1,444 Hr Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA	6847	Quantity of Coil Tubing Reels & Stands S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA
6841	Quincy QSI 235 Skid-Mounted Electric Air Compressor S/N: QSI235WCW231607 Usage: 1,444 Hr Lot closing time: Fri, Sep 18, 04:16 PM CDT Asset located in: San Antonio, TX, USA		

Lot #	Details	Lot #	Details
6847	Quantity of Coil Tubing Reels & Stands S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA	6851	Quantity of (5) Tool Stands S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:18 PM CDT Asset located in: Pecos, TX, USA
6848	Quantity of Cables, Frames & Lifting Devices S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA	6852	Quantity of (9) Tool Stands S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:18 PM CDT Asset located in: Pecos, TX, USA
6848	Quantity of Cables, Frames & Lifting Devices S/N: Not Available Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA	6853	2008 Canquip Hydraulic Power Pack (Inoperable) S/N: S156B-LES Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:18 PM CDT Asset located in: Pecos, TX, USA
6849	Quantity of Engines, Transmissions, Engine Heads, (2) Radiators, & Gear Box Cores S/N: Not Available C/W: (21) Pallets Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA		
6850	Quantity of Oilfield Components & Parts S/N: Not Available C/W: Cummins Engine, Pac Units Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA		
6850	Quantity of Oilfield Components & Parts S/N: Not Available C/W: Cummins Engine, Pac Units Usage: Not Available Notes: Item is located offsite and must be removed within 14 days of the auction (by October 2nd). License plates will not be provided. Lot closing time: Fri, Sep 18, 04:17 PM CDT Asset located in: Pecos, TX, USA		