



Manitoba Regional Auction, CAN - Jul 23, 2026

Lot #	Details	Lot #	Details
1	2017 Gleaner S96 4x4 Combine Harvester S/N: AGCRS9600HHTV6127 C/W: Located in Lane 3 Spot 6, 1199 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, Rear View Camera, Gleaner Tyton Display, Trimble AG-482 Antenna/ Receiver, Autosteer, Requires Diesel Exhaust Fluid, Pickup S/N - AG3G42000EM041534 -, SwathMaster 4200 Pickup, Hydraulic Windrow Compressor, Rock Trap, Single Rotor, 23 ft Auger, Lateral Tilt Feederhouse, Power Folding Grain Tank Extensions, Chaff Spreader, 900 /60R32 Front Tires, 520/80R26 Rear Tires Usage: 1,807 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available - see Supporting Documents - Lot closing time: Thu, Jul 23, 09:00 AM CDT Asset located in: Brandon, MB, CAN	3	2016 New Holland CR9.90 Elevation Combine Harvester S/N: 751971003 C/W: Located in Lane 3 Spot 2, 1896 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, Rear View Camera, IntelliView IV Display, New Holland 372 Antenna/ Receiver, IntelliSteer Autosteer, WAAS Activation, 2016 US EPA Label, CARB Compliant, Twin Rotor, 26 ft Auger, Pivoting Spout, Lateral Tilt Feederhouse, Grain Tank Extensions, Self-Leveling Sieves, Chaff Spreader, Fine Cut Chopper, LED Lights, 580/85R42 Dual Front Tires, 750/65R26 Rear Tires Usage: 2,573 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:06 AM CDT Asset located in: Brandon, MB, CAN
2	2017 Gleaner S96 4x4 Combine Harvester S/N: AGCRS9600HHTV6122 C/W: Located in Lane 3 Spot 7, 1328 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, Rear View Camera, Gleaner Tyton Display, Trimble AG-482 Antenna/ Receiver, Autosteer, Requires Diesel Exhaust Fluid, Pickup S/N - AG3G42000EM041529 -, SwathMaster 4200 Pickup, Hydraulic Windrow Compressor, Rock Trap, Single Rotor, 23 ft Auger, Lateral Tilt Feederhouse, Power Folding Grain Tank Extensions, Chaff Spreader, 900 /60R32 Front Tires, 520/80R26 Rear Tires Usage: 2,072 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available - see Supporting Documents - Lot closing time: Thu, Jul 23, 09:03 AM CDT Asset located in: Brandon, MB, CAN	4	2015 John Deere S690 Combine Harvester S/N: 1H0S690SKF0775045 C/W: Located in Lane 3 Spot 8, 1723 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, GS3 2630 Display, StarFire 3000 Antenna/ Receiver, AutoTrac Autosteer, SF2 Activation, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Rock Trap, 26 ft Auger, Lateral Tilt Feederhouse, Power Folding Grain Tank Extensions, Fine Cut Chopper, Advanced PowerCast Tailboard, 650 /85R38 Dual Front Tires, 750/65R26 Rear Tires Usage: 2,537 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:09 AM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
5	2014 John Deere S680 Combine Harvester S/N: 1H0S680SCD0765559 C/W: Located in Lane 3 Spot 4, 3235 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, GS3 2630 Display, StarFire 3000 Antenna/ Receiver, AutoTrac Autosteer, SF1 Activation, 2013 US EPA Label, CARB Compliant, Rock Trap, 26 ft Auger, Lateral Tilt Feederhouse, Power Folding Grain Tank Extensions, Fine Cut Chopper, PowerCast Tailboard, LED Lights, 650/85R38 Dual Front Tires, 750/65R26 Rear Tires Usage: 4,654 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:12 AM CDT Asset located in: Brandon, MB, CAN	8	2010 Case IH 8120 4x4 Combine Harvester S/N: YAG210479 C/W: Located in Lane 3 Spot 3, 4393 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, AFS Pro 600 Display, 2010 US EPA Label, CARB Compliant, Rock Trap, AFX Rotor, 23 ft Auger, Grain Tank Extensions, Chaff Spreader, Chopper, HID Lights, 36 in Tracks, 540/65R30 Rear Tires Usage: 5,537 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:21 AM CDT Asset located in: Brandon, MB, CAN
6	2012 New Holland CR8090 4x4 Combine Harvester S/N: YCG115298 C/W: 2720 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, IntelliView IV Display, New Holland Antenna/ Receiver, IntelliSteer Autosteer, WAAS Activation, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 23 ft Auger, Lateral Tilt Feederhouse, Grain Tank Extensions, Chaff Spreader, Fine Cut Chopper, 520/85R42 Dual Front Tires, 750/65R26 Rear Tires Usage: 3,592 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:15 AM CDT Asset located in: Ste Agathe, MB, CAN	9	2007 New Holland CR9060 Combine Harvester S/N: HAJ110164 C/W: 2319 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, IntelliView Plus II Display, Rock Trap, Twin Rotor, 19 ft Auger, Lateral Tilt Feederhouse, Grain Tank Extensions, Chaff Spreader, Chopper, 900/60R32 Front Tires, 540/65R30 Rear Tires Usage: 3,111 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:24 AM CDT Asset located in: Brandon, MB, CAN
7	2013 Case IH 8230 4x4 Combine Harvester S/N: YDG222727 C/W: Located in Lane 3 Spot 1, 2875 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, AFS Pro 700 Display, AFS 372 Antenna/ Receiver, Tier 4, Rock Trap, 25 ft Auger, Pivoting Spout, Power Folding Grain Tank Extensions, Chaff Spreader, 620/70R42 Dual Front Tires, 750/65R26 Rear Tires Usage: 3,784 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:18 AM CDT Asset located in: Brandon, MB, CAN	10	2004 New Holland CX840 Combine Harvester S/N: 301385011 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:27 AM CDT Asset located in: Brandon, MB, CAN
		11	2002 New Holland CX840 Combine Harvester S/N: 301385014 C/W: 2943 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Fore & Aft, Harvest Monitor System, Yield & Moisture Sensor, IntelliView Display, 2004 US EPA Label, Rock Trap, Twin Rotor, 20 ft Auger, Lateral Tilt Feederhouse, Grain Tank Extensions, Chopper, 900/60R32 Front Tires, 600/65R28 Rear Tires Usage: 3,678 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:30 AM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
12	2000 John Deere 9650 STS Combine Harvester S/N: H09650S686337 C/W: Located in Lane 3 Spot 5, 3603 Separator Hours Showing, Air Conditioner, Air Ride Seat, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, Harvest Monitor System, Yield & Moisture Sensor, GreenStar Display, Rock Trap, Bullet Rotor, 22 ft Auger, Grain Tank Extensions, Fine Cut Integrated Chopper, 30.5-32 Front Tires, 480 /70R30 Rear Tires Usage: 5,135 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:33 AM CDT Asset located in: Brandon, MB, CAN	16	2013 John Deere 9560R Articulated 4WD Tractor S/N: 1RW9560RVDPO06981 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, PowerShift, Forward/ Reverse Shuttle, GS3 CommandCenter Display, 2013 US EPA Label, CARB Compliant, 5 Rear Remotes, ISOBUS, Drawbar, Dual 800/70R38 Tires, Rear Wheel Weights Usage: 3,364 Hr Notes: Deleted emissions - For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:44 AM CDT Asset located in: Ste Agathe, MB, CAN
13	1999 Case IH 2388 Combine Harvester S/N: JJ00265595 C/W: 4051 Separator Hours Showing, Hydrostatic Drive, Reverser, Variable Speed Reel, Auto Header Height Control, AFS Display, Pickup S/N - JJC0311727 -, Case IH 1015 Pickup, Rock Trap, 20 ft Auger, Grain Tank Extensions, Chaff Spreader, Chopper, 800 /65R32 Front Tires, 14.9-24 Rear Tires Usage: 5,095 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:36 AM CDT Asset located in: Ste Agathe, MB, CAN	17	2007 John Deere 9530 Articulated 4WD Tractor S/N: RW9530P001493 C/W: Located in Lane 4 Spot 11, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, PowerShift, 475 hp Engine, 2007 US EPA Label, CARB Compliant, 4 Rear Remotes, ISOBUS, Exterior 3-Point Hitch Controls, 3-Point Hitch, Drawbar, Dual 800 /70R38 Tires, Rear Wheel Weights, Front Wheel Weights Usage: 7,599 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:46 AM CDT Asset located in: Brandon, MB, CAN
14	2023 Versatile 620DT Track Tractor S/N: 708655 C/W: Located in Lane 4 Spot 1, Enclosed Cab, Air Conditioner, Air Ride Seat, 16 Forward 4 Reverse, Powershift, Cab Suspension, Trimble TMX-2050 Display, Outback Antenna/ Receiver, Outback Autosteer, WAAS Activation, 615 hp Engine, 2024 US EPA Label, LED Lights, High Flow Hydraulics, 6 Rear Remotes, Power Beyond, Load Sensing, ISOBUS, Big 1000 PTO, Drawbar, 36 in Tracks, Tow Cable, Leather Seating & Heated/Cooled Op Seat, Rear Camera, Qty 2- 3/4 couplers Usage: 97 Hr Notes: Primary Warranty coverage until May 1, 2028 or 3000 hours - For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:40 AM CDT Asset located in: Brandon, MB, CAN	18	2000 John Deere 9400 Articulated 4WD Tractor S/N: RW9400P030723 C/W: Located in Lane 4 Spot 10, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 12 Forward 2 Reverse, PowerShift, GS2 1800 Display, ATU 200 Autosteer, 425 hp Engine, 2000 US EPA Label, CARB Compliant, Degelman 6900 16 ft 4-Way Dozer, 4 Rear Remotes, Big 1000 PTO, Drawbar, Dual 710 /70R42 Tires, Rear Wheel Weights Usage: Not Available Notes: Cannot verify hours - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:48 AM CDT Asset located in: Brandon, MB, CAN
15	2003 John Deere 9520T Track Tractor S/N: RW9520T902093 C/W: Located in Lane 4 Spot 4, Enclosed Cab, Air Conditioner, 18 Forward, PowerShift, 450 hp Engine, Front Weights, 4 Rear Remotes, ISOBUS, Swing Drawbar, 36 in Tracks Usage: 6,989 Hr Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:42 AM CDT Asset located in: Brandon, MB, CAN	19	2010 Versatile 2335 Articulated 4WD Tractor S/N: 334043 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 12 Forward 4 Reverse, QuadShift III, 335 hp Engine, 2009 US EPA Label, CARB Compliant, Front Weights, 4 Rear Remotes, Power Beyond, Drawbar, Rear Weights, Dual 20.8x42 Tires Usage: Not Available Lot closing time: Thu, Jul 23, 09:50 AM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
20	2006 Case IH STX330 Articulated 4WD Tractor S/N: Z6F100474 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Power Shift, 330 hp Engine, LED Lights, 4 Rear Remotes, Power Beyond, Drawbar, LSW1100/45R46 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 09:52 AM CDT Asset located in: Brandon, MB, CAN	23	2016 John Deere 8345R 4WD Tractor S/N: 1RW8345RCFD108727 C/W: Located in Lane 4 Spot 6, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, IVT, Forward/ Reverse Shuttle, 4600 CommandCenter Display, StarFire 3000 Antenna/ Receiver, AutoTrac Autosteer, 345 hp Engine, Requires Diesel Exhaust Fluid, Front Weights, Suspended Front Axle, HID Lights, 6 Rear Remotes, ISOBUS, Exterior 3-Point Hitch Controls, Big 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar, Dual 420/85R34 Front Tires, Dual 480/80R50 Rear Tires, Rear Wheel Weights Usage: 4,769 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available, see supporting documents - Lot closing time: Thu, Jul 23, 09:58 AM CDT Asset located in: Brandon, MB, CAN
21	1983 John Deere 8450 Articulated 4WD Tractor S/N: RW8450H002199 C/W: Located in Lane 4 Spot 9, Enclosed Cab, Air Ride Seat, Differential Lock, 16 Forward 6 Reverse, Partial Power Shift, Forward/ Reverse Shuttle, 3 Rear Remotes, 1000 PTO, Drawbar, Dual 18.4x38 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available, see supporting documents - Lot closing time: Thu, Jul 23, 09:54 AM CDT Asset located in: Brandon, MB, CAN	24	2014 New Holland T8.410 SmartTrax 4WD Tractor S/N: ZERE00751 C/W: Located in Lane 4 Spot 16, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 4 Reverse, Power Shift, Forward/ Reverse Shuttle, Cab Suspension, IntelliView IV Display, IntelliSteer Autosteer, WAAS Activation, Tier 4, 340 hp Engine, 2021 US EPA Label, Front PTO, Front 3-Point Hitch, Suspended Front Axle, HID Lights, 6 Rear Remotes, Power Beyond, Load Sensing, ISOBUS, Exterior 3-Point Hitch Controls, 1000 PTO, 3-Point Hitch, Drawbar, 380/85R42 Front Tires, 18 In Tracks Rear Tires, 73 gpm, Driveline 1323 hours Usage: 2,092 Hr Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:00 AM CDT Asset located in: Brandon, MB, CAN
22	2018 John Deere 8345R 4WD Tractor S/N: 1RW8345RCJS132683 C/W: Located in Lane 4 Spot 5, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 23 Forward 11 Reverse, PowerShift, Left Hand Reverser, 4600 CommandCenter Display, 345 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, LED Lights, High Flow Hydraulics, 5 Rear Remotes, Power Beyond, Load Sensing, ISOBUS, Exterior 3-Point Hitch Controls, Big 1000 PTO, 3-Point Hitch w/ Quick Hitch, Hydraulic Top Link, Drawbar, Dual 380/80R38 Front Tires, Front Wheel Weights, Dual 480/80R50 Rear Tires Usage: 3,550 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available, see supporting documents - Lot closing time: Thu, Jul 23, 09:56 AM CDT Asset located in: Brandon, MB, CAN	25	2013 John Deere 8310R 4WD Tractor S/N: 1RW8310RKDD077129 C/W: Located in Lane 4 Spot 7, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 2 Forward 1 Reverse, IVT, Forward/ Reverse Shuttle, GS3 CommandCenter Display, 310 hp Engine, Front Weights, Suspended Front Axle, 5 Rear Remotes, Power Beyond, Load Sensing, ISOBUS, Exterior 3-Point Hitch Controls, Big 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar, Dual 380/80R38 Front Tires, Dual 380/90R54 Rear Tires, Rear Wheel Weights Usage: 5,390 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available, see supporting documents - Lot closing time: Thu, Jul 23, 10:02 AM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
26	2019 Claas Axion 820 4WD Tractor S/N: A5100051 C/W: Located in Lane 4 Spot 17, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Reverse Drive Mode, CVT, Forward/ Reverse Shuttle, Cab Suspension, 215 hp Engine, Requires AdBlue, Claas CL500 Loader w /Joystick, Quick Coupler, Miller GFE4X 102 in Grapple Bucket, 4 Rear Remotes, ISOBUS, Exterior 3-Point Hitch Controls, 540/1000 PTO, 3-Point Hitch, Drawbar, 480/70/R34 Front Tires, 650/85/R38 Rear Tires Usage: 3,099 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available, see supporting documents - Lot closing time: Thu, Jul 23, 10:04 AM CDT Asset located in: Brandon, MB, CAN	31	1980 John Deere 2140 2WD Tractor S/N: 352728L C/W: Located in Lane 4 Spot 15, 7 Forward, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, 7.5x16 Front Tires, 18.4x30 Rear Tires Usage: 4,975 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:14 AM CDT Asset located in: Brandon, MB, CAN
27	2019 Claas Axion 820 4WD Tractor S/N: A6100962 C/W: Located in Lane 4 Spot 18, Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 24 Forward 24 Reverse, Hexashift, Forward/ Reverse Shuttle, Cab Suspension, 215 hp Engine, Requires Diesel Exhaust Fluid, Claas CL500 Loader w/Joystick, Quick Coupler, GPL-GFE4X 102 in Grapple Bucket, LED Lights, 4 Rear Remotes, ISOBUS, Exterior 3-Point Hitch Controls, 540/1000 PTO, 3-Point Hitch, Drawbar, 480/70R34 Front Tires, 650/85R38 Rear Tires Usage: 3,417 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available, see supporting documents - Lot closing time: Thu, Jul 23, 10:06 AM CDT Asset located in: Brandon, MB, CAN	32	1947 John Deere A 2WD Narrow Front Antique Tractor S/N: 582281 C/W: 540 PTO, Trailer Hitch, 6.00-16 Front Tires, 13.6x38 Rear Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:16 AM CDT Asset located in: Ste Agathe, MB, CAN
29	1974 Case 1370 2WD Tractor S/N: 8738131 C/W: Enclosed Cab, 12 Forward 3 Reverse, Partial Powershift, 158 hp Engine, Front Weights, 2 Rear Remotes, 1000 PTO, Swing Drawbar, 11.00x16 Front Tires, Dual 18.4x38 Rear Tires Usage: 9,563 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:10 AM CDT Asset located in: Brandon, MB, CAN	33	2014 Case WD1203 36 ft Swather Windrower S/N: YDG867930 C/W: 860 Machine Hours Showing, Enclosed Cab, Air Conditioner, Air Ride Seat, Hydrostatic Drive, 2012 US EPA Label, 18.4-26 Front Tires, 14L-16.1SL Rear Tires, Header S/N - YDZB02004, 2013 Case IH DH362 36 ft Draper Header, P/U Reel, Hydraulic Fore & Aft, Double Knife Drive Usage: 860 Hr Notes: For more information, please contact Scott Tilbury 204-522-5601 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 10:18 AM CDT Asset located in: Melita, MB, CAN
30	1967 International 806 2WD Tractor S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 10:12 AM CDT Asset located in: Ste Agathe, MB, CAN	34	2013 Case WD1203 36 ft Swather Windrower S/N: YDG667928 C/W: 766 Machine Hours Showing, Enclosed Cab, Air Conditioner, Air Ride Seat, Hydrostatic Drive, 2012 US EPA Label, 18.4-26 Front Tires, 14L-16.1SL Rear Tires, Header S/N - YDZB03009, 2013 Case IH DX362 36 ft Draper Header, P/U Reel, Hydraulic Fore & Aft, Double Knife Drive Usage: 766 Hr Notes: For more information, please contact Scott Tilbury 204-522-5601 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 10:20 AM CDT Asset located in: Melita, MB, CAN

Lot #	Details	Lot #	Details
35	2000 Premier 2940 36 ft Swather Windrower S/N: 135844 C/W: Located in Lane 1 Spot 14, 2223 Machine Hours Showing, Enclosed Cab, Air Conditioner, Hydrostatic Drive, 21.5-16.1 Front Tires, 16.5-16.1 Rear Tires, Header S/N - 147597, 2002 MacDon 962 36 ft Draper Header, Split P/U Reel, Hydraulic Fore & Aft, Single Knife Drive, Center Delivery, Gauge Wheels Usage: 2,223 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:22 AM CDT Asset located in: Brandon, MB, CAN	38	2018 Case IH Patriot 4440 120 ft 4x4 High Clearance Self-Propelled Sprayer S/N: JFGYS444LJT046770 C/W: Located in Lane 5 Spot 18, Hydrostatic, Air Conditioner, Air Ride Seat, Radar, Auto Rate Control Raven Viper 4 Display, Raven RS1 Antenna/ Receiver, Raven Autosteer, AIM Command FLEX, Requires Diesel Exhaust Fluid, Automatic Boom Height Control, Hydraulic Driven Pump, 1200 gal Stainless Steel Tank, Chemical Mix Tank, Direct Chemical Injection, Rinse Tank, 5 Nozzle Bodies, Fence Row Nozzles, 7 Section Control, LED Lights, 380/90R46, 380/90R46 Rear Tires, Hydraulic Axle Adjustment, 3 in Front Fill, 20 in Nozzle spacing, Active Suspension, Luxury Cab Usage: 2,633 Hr Notes: DEF tank replaced June 5, 2026 - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Additional information available, see supporting documents Lot closing time: Thu, Jul 23, 10:28 AM CDT Asset located in: Brandon, MB, CAN
36	2021 John Deere R4045 120 ft 4x4 High Clearance Self-Propelled Sprayer S/N: 1N04045RVM0216445 C/W: Located in Lane 4 Spot 19, 1550 Machine Hours Showing, Hydrostatic, Air Conditioner, Air Ride Seat, Radar, Auto Rate Control 4600 CommandCenter Display, StarFire 7000 Antenna/ Receiver, AutoTrac Autosteer, SF1 Activation, Automatic Boom Height Control, 1200 gal Stainless Steel Tank, Rinse Tank, 5 Nozzle Bodies, Fence Row Nozzles, 11 Section Control, LED Lights, 380/105R50, Hydraulic Axle Adjustment, Auto Prime, Boom Air Purge, BoomTrac Pro, In-Field Data Sharing, Row Sense, Front Fill, 20 In Spacing, Hi-Flow Meter, Simon Meter Usage: 1,550 Hr Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:24 AM CDT Asset located in: Brandon, MB, CAN	39	2011 Apache AS1020 100 ft 4x2 High Clearance Self-Propelled Sprayer S/N: 9120151 C/W: Located in Lane 5 Spot 18, 1585 Machine Hours Showing, ZF PowerShift 6-speed w/ Lockup Torque Converter, Air Conditioner, Air Ride Seat, Auto Rate Control Trimble FM-750 Display, Trimble Antenna/ Receiver, Trimble EZ-Steer Autosteer, Automatic Boom Height Control, Hydraulic Driven Pump, 1000 gal Poly Tank, Triple Nozzle Bodies, 6 Section Control, 380/80R38, 520/85R42 Rear Tires, Hydraulic Axle Adjustment Usage: 1,589 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:30 AM CDT Asset located in: Brandon, MB, CAN
37	2019 John Deere R4044 132 ft 4x4 High Clearance Self-Propelled Sprayer S/N: 1N04044REK0195245 C/W: Located in Lane 5 Spot 16, 3300 Machine Hours Showing, Hydrostatic, Air Conditioner, Air Ride Seat, Radar, Auto Rate Control 4600 CommandCenter Display, StarFire 6000 Antenna/ Receiver, AutoTrac Autosteer, SF1 Activation, Automatic Boom Height Control, 1200 gal Stainless Steel Tank, Chemical Mix Tank, Rinse Tank, 5 Nozzle Bodies, 11 Section Control, 320/125R54, Hydraulic Axle Adjustment, RTK Ready, Boom Air Purge & Auto Prime, 20 In Spacing, Front Fill, (3) Cameras Usage: 3,300 Hr Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:26 AM CDT Asset located in: Brandon, MB, CAN	40	2009 Rogator SS884 100 ft 4x4 High Clearance Self-Propelled Sprayer S/N: LAGCA0SS8JNUS81041 C/W: Located in Lane 5 Spot 21, Hydrostatic, Air Conditioner, Auto Rate Control Raven Viper Pro Display, Automatic Boom Height Control, 865 gal Stainless Steel Tank, Chemical Mix Tank, Rinse Tank, Double Boom, 4 Nozzle Bodies, 5 Section Control, 320/90R50, Rear Tires Usage: 2,914 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:32 AM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
41	2005 Case SPX3150 90 ft 4x4 High Clearance Self-Propelled Sprayer S/N: JFG0007051 C/W: Located in Lane 5 Spot 17, Hydrostatic, Air Conditioner, Air Ride Seat, Radar, Auto Rate Control Outback MVRX Display, Hemisphere A631 Antenna/ Receiver, Outback eDriveM1 Autosteer, SBAS Activation, Hydraulic Driven Pump, 700 gal Poly Tank, Foam Markers, 5 Nozzle Bodies, 6 Section Control, 18.4R38, Hydraulic Axle Adjustment, Raven AutoBoom G1 Usage: 2,989 Hr Notes: Steering Issues - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:34 AM CDT Asset located in: Brandon, MB, CAN	45	2025 DJI AGRAS T50 Sprayer Drone (Unused) S/N: 7TNWNF70030PK6 C/W: Remote Controller, T50 drone with spraying system Usage: Not Available Notes: Batteries and charger not included - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: June 25 - Lot closing time: Thu, Jul 23, 10:42 AM CDT Asset located in: Brandon, MB, CAN
42	2004 Rogator 1254 95 ft 4x4 High Clearance Self-Propelled Sprayer S/N: 125037101 C/W: Located in Lane 5 Spot 20, 4969 Machine Hours Showing, Hydrostatic, Air Conditioner, GS2 2600 Display, StarFire 3000 Antenna/ Receiver, Automatic Boom Height Control, Hydraulic Driven Pump, 1125 L Stainless Steel Tank, 4 Nozzle Bodies, 380/90R46, Crop Dividers Usage: 4,968 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:36 AM CDT Asset located in: Brandon, MB, CAN	46	2025 DJI AGRAS T50 Sprayer Drone (Unused) S/N: 7TNWNF70030PKW C/W: Remote Controller, T50 drone with spraying system Usage: Not Available Notes: Batteries and charger not included - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:44 AM CDT Asset located in: Brandon, MB, CAN
43	1998 Rogator 854 90 ft 4x4 High Clearance Self-Propelled Sprayer S/N: 8517856 C/W: Located in Lane 5 Spot 19, 4681 Machine Hours Showing, Hydrostatic, Air Conditioner, Auto Rate Control Trimble EZ-Guide 250 Display, Ez-steer Autosteer, Automatic Boom Height Control, 750 L Stainless Steel Tank, Double Nozzle Bodies, 23.1-26, Hydraulic Axle Adjustment Usage: 4,681 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:38 AM CDT Asset located in: Brandon, MB, CAN	47	2025 DJI AGRAS T50 Sprayer Drone (Unused) S/N: 7TNWNFS003PQD C/W: Remote Controller, T50 drone with spraying system Usage: Not Available Notes: Batteries and charger not included - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: June 25 - Lot closing time: Thu, Jul 23, 10:46 AM CDT Asset located in: Brandon, MB, CAN
44	2025 DJI AGRAS T50 Sprayer Drone (Unused) S/N: 7TNWNF60030PHA C/W: Remote Controller, T50 drone with spraying system Usage: Not Available Notes: Batteries and charger not included - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: June 25 - Lot closing time: Thu, Jul 23, 10:40 AM CDT Asset located in: Brandon, MB, CAN	48	2025 DJI AGRAS T50 Sprayer Drone (Unused) S/N: 7TNWNFT0030PRG C/W: Remote Controller, T50 drone with spraying system Usage: Not Available Notes: Batteries and charger not included - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: June 25 - Lot closing time: Thu, Jul 23, 10:48 AM CDT Asset located in: Brandon, MB, CAN
		49	Case IH 730 Pull Type Swather Windrower S/N: CCC0003636 C/W: 30 ft Draper Header, Batt Reel, Single Knife Drive, 540 PTO Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:55 AM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
50	Handi Navigator 95 ft S/A High Clearance Pull-Type Sprayer S/N: Not Available C/W: Located in Lane 9 Spot 11, 1000 PTO, PTO Driven Pump, 1200 gal Poly Tank, Chemical Mix Tank, Triple Nozzle Bodies, 5 Section Control, 320/90R46 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:56 AM CDT Asset located in: Brandon, MB, CAN	54	2013 John Deere 1890C 60 ft Combination Air Drill S/N: 1A81890CADF750511 C/W: Located in Lane 10 Spot 3, 7.5 in Spacing, Single Shoot, Variable Rate Control, Full Blockage Sensors, Rubber 5 in Packer, 15.5 in Discs, John Deere 1910H 550 bu 3 Compartment Tow-Behind Air Cart, Tank S/N 1A81910HVDJ750756 Single Fan, 10 in Auger Loading System, Tank Variable Rate Control, 21.5Lx16.1SL Front Tires Dual 520/85R42 Rear Tires Usage: Not Available Notes: For more information, please contact the Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:00 AM CDT Asset located in: Brandon, MB, CAN
51	6 ton Turntable NH3 Tank S/N: Not Available C/W: Located in Lane 9 Spot 3, 21.5-16.1 Tires, Steel Tank, 3 Compartments, Catwalk, Electric Safety Switch, Clevis Hitch Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:57 AM CDT Asset located in: Brandon, MB, CAN	55	2006 John Deere 1820 60 ft Air Drill S/N: A01820X715400 C/W: Located in Lane 10 Spot 2, 12 in Spacing, Single Shoot, Blockage Sensors, Pneumatic 5 in Packer, John Deere 1910 430 bu 3 Compartment Tow-Behind Air Cart, Tank S/N A01910H715457 Single Fan, Variable Rate Metering System, John Deere GreenStar Display, 16.5-16 Front Tires 710/70R38 Rear Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:01 AM CDT Asset located in: Brandon, MB, CAN
52	Kuhn 2044 T/A Manure Spreader S/N: E0067 C/W: Located in Lane 9 Spot 7, 15 ft Box Length, Hydraulic Push Unload, Hydraulic End Gate, 1000 PTO, Vertical Beater, 16.5-16.1 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: June 25 - Lot closing time: Thu, Jul 23, 10:58 AM CDT Asset located in: Brandon, MB, CAN	56	Bourgault 8800 27 ft Air Seeder S/N: Not Available C/W: 9 in Spacing, Single Shoot, Liquid Fertilizer Kit, Rubber 3 in Packer, Bourgault 2130 2 Compartment Tow-Behind Air Cart, Single Fan, 6 in Auger Loading System, Loading Auger, 12.5-16 Front Tires 12.5-16 Rear Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:02 AM CDT Asset located in: Brandon, MB, CAN
53	2017 Bourgault 3720 PCD HF 60 ft Combination Air Drill S/N: 42816AC04 C/W: Located in Lane 10 Spot 4, 10 in Spacing, Double Shoot, Seed Monitor, Full Blockage Sensors, On-Row 4.5 in Packer, 14 in Discs, 2017 Bourgault 7700 700 bu 5 Compartment Tow-Behind Air Cart, Tank S/N 42761AS09 Double Fan, Bag Lift Loading System, 16 in Loading Conveyor, Tank Auto-Rate Sectional Variable Rate Control, TopCon X30 Display, Dual Rear Tires, Rear Hitch, Pro PDM, 18.5 Seed Disc, Set of New Discs & Misc Parts, Wireless Remote, In-Cab Control & Harness Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 10:59 AM CDT Asset located in: Brandon, MB, CAN	57	2008 John Deere DB60 36 Row No-Till Planter S/N: PABB00X725150 C/W: Located in Lane 9 Spot 4, Pin Hitch, Central Commodity System, 20 in Spacing, Center Delivery, Hydraulic Variable Rate Drive, Row Cleaners, Hydraulic Markers, Pneumatic Down Pressure, 20/20 Seed Sense Monitor, Liquid Fertilizer Kit, Seed Firmers, ISO Bus, Precision eSet Meter, John Deere Rate Controller, 3 in Rear Fill, Seed Discs 15 in Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:03 AM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
58	44 ft Deep Tillage Cultivator S/N: Not Available C/W: C-Shanks 12 in Spacing, Rear Harrow, Rear Hitch Usage: Not Available Notes: For more information, please contact Brandon Basler- 306.630.5171 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 11:04 AM CDT Asset located in: Antler, SK, CAN	64	John Deere 28 ft Chisel Plow S/N: Not Available C/W: 28 C-Shanks 12 in Spacing, Rear Spring Tine Bar Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:10 AM CDT Asset located in: Ste Agathe, MB, CAN
59	2012 Summers 2510DT 47 ft Tandem Disc S/N: M0042 C/W: 24 in Notched Front Discs, 24 in Notched Rear Discs, 10 in Spacing, Rear Harrow Tines Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:05 AM CDT Asset located in: Brandon, MB, CAN	65	12 in Fork Type Custom Built Digger Rock Picker S/N: Not Available C/W: Hydraulic Drive Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:11 AM CDT Asset located in: Ste Agathe, MB, CAN
60	2018 Degelman SM 7000 82 ft Heavy Harrow S/N: SM7950 C/W: Located in Lane 9 Spot 8, Hydraulic Tine Adjustment, 5 Bar, 5/8 in x 25 in Tines, Carbide Tips Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:06 AM CDT Asset located in: Brandon, MB, CAN	66	Kuhn GMD 700Gii HD 8 ft 3-Point Hitch Disc Mower S/N: M2363 C/W: 540 PTO, Swath Discs Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:12 AM CDT Asset located in: Brandon, MB, CAN
61	2005 Bourgault 7200 72 ft Heavy Harrow S/N: 38435HH10 C/W: 5 Bar, 9/16 in x 20 in Tines Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:07 AM CDT Asset located in: Ste Agathe, MB, CAN	67	Kuhn GMD 280 HD 8 ft 3-Point Hitch Disc Mower S/N: KSAA1025L80D01837 C/W: 540 PTO, Swath Discs Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:13 AM CDT Asset located in: Brandon, MB, CAN
62	Western 63 Harrow S/N: 85121 C/W: Applicator Usage: Not Available Notes: For more information, please contact Brandon Basler- 306.630.5171 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 11:08 AM CDT Asset located in: Antler, SK, CAN	68	2004 Krone Swadro 421/13 3-Point 1 Rotor Hay Rake S/N: 569735 C/W: 540 PTO Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:14 AM CDT Asset located in: Ste Agathe, MB, CAN
63	Western 56 ft Harrow S/N: Not Available C/W: x 16 in Tines Usage: Not Available Notes: For more information, please contact Brandon Basler- 306.630.5171 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 11:09 AM CDT Asset located in: Antler, SK, CAN		

Lot #	Details	Lot #	Details
69	2017 Kuhn MM700 24 ft 2-Point Windrow Merger S/N: C0227 C/W: Located in Lane 9 Spot 5, 1000 PTO, Discharge Left/Right & 50/50 Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:15 AM CDT Asset located in: Brandon, MB, CAN	74	2007 Brent 1194 S/A Grain Cart S/N: B23840109 C/W: 22 in PTO Driven Hydraulic Folding Hydraulic Pivoting Auger, Clean Out Doors, Roll Tarp, 1000 PTO, Walking Beam Suspension, Duals 320/85R38 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:20 AM CDT Asset located in: Ste Agathe, MB, CAN
70	2017 Krone Big Pack 1290 HDP High Speed Big Square Baler S/N: BP2Z955082 C/W: Big 1000 PTO, Hydraulic Parking Jack, 90 in Pickup Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:16 AM CDT Asset located in: Ste Agathe, MB, CAN	75	Convey-All 1645-TL 16 in x 45 ft Grain Conveyor S/N: Not Available C/W: Located in Lane 7 Spot 4, Kohler 999 cc Gasoline Engine, Electric Start, Reverser, Hydraulic Winch, Mover Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:21 AM CDT Asset located in: Brandon, MB, CAN
71	2004 John Deere 567 Round Baler S/N: E00567X301493 C/W: Located in Lane 9 Spot 10, Big 1000 PTO, Clevis Pin Hitch, Megawide Pickup, Cutter, Twine Tie, Push Bar Ejector, Bale Monitor, New Belt Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:17 AM CDT Asset located in: Brandon, MB, CAN	76	Batco 1335 13 in x 35 ft Grain Conveyor S/N: 13072 C/W: Honda GX 390 Gasoline Engine, Hydraulic Winch, Mover Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:22 AM CDT Asset located in: Brandon, MB, CAN
72	Kubota WR1100C 3-Point Hitch Hydraulic Bale Wrapper S/N: ZPMWRP000LKD00479 C/W: Located in Lane 13 Spot 16 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:18 AM CDT Asset located in: Brandon, MB, CAN	77	Convey-All TC 1035 10 in x 35 ft Grain Conveyor S/N: 2811066437 C/W: Electric Motor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:23 AM CDT Asset located in: Brandon, MB, CAN
73	2015 J&M 1501 1500 bu Tracked Grain Cart S/N: 1402051 C/W: 22 in PTO Driven Hydraulic Folding Hydraulic Pivoting Auger, Hydraulic Spout, Roll Tarp, 1000 PTO, Walking Beam Suspension, 36 in Tracks Usage: Not Available Notes: For more information, please contact Scott Tilbury 204-522-5601 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 11:19 AM CDT Asset located in: Melita, MB, CAN	78	2021 Brandt 13110-HP+ 13 in x 110 ft Swing Grain Auger S/N: 143174 C/W: Located in Lane 7 Spot 7, 1000 PTO, Reverser, Double Flight Hopper, Hydraulic Winch, Mover Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:24 AM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
79	2016 Westfield MKX 130-94 13 in x 94 ft Swing Grain Auger S/N: 279335 C/W: Located in Lane 7 Spot 6, 540 PTO, Double Flight Hopper, Westfield Transfer Auger, Hydraulic Drive 37 in 66 in Hopper Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:25 AM CDT Asset located in: Brandon, MB, CAN	85	2012 Genie GTH-844 Telehandler S/N: GTH081216045 C/W: Located in Lane 5 Spot 7, Open Operator Station, 44 ft Max Lift Height, 8000 lb Max Lift Capacity, 2012 US EPA Label, 48 in Forks, 13.00-24 Tires Usage: 6,508 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:31 AM CDT Asset located in: Brandon, MB, CAN
80	2025 Westfield MK130-81 Plus Flex 13 in x 81 ft Swing Grain Auger S/N: WF02A362599846 C/W: Located in Lane 7 Spot 5, Double Flight Hopper, Hydraulic Winch, Mover Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:26 AM CDT Asset located in: Brandon, MB, CAN	86	2023 Bobcat T770 Two-Speed Compact Track Loader S/N: AT6340600 C/W: Located in Lane 5 Spot 10, Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 17 in Track Belts, Hydraulic Coupler, 79 in Bucket Usage: 3,177 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:32 AM CDT Asset located in: Brandon, MB, CAN
81	Farm King 1070 10 in x 70 ft Swing Grain Auger S/N: Not Available C/W: 540 PTO, Reverser, Double Flight Hopper Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:27 AM CDT Asset located in: Ste Agathe, MB, CAN	87	2023 Bobcat T770 Two-Speed Compact Track Loader S/N: AT6340597 C/W: Located in Lane 5 Spot 11, Enclosed Cab, Creep Mode, Joystick Steering, Control Pattern Changer, Self Leveling, Requires Diesel Exhaust Fluid, 17 in Track Belts, Hydraulic Coupler, 79 in Bucket Usage: 3,565 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:33 AM CDT Asset located in: Brandon, MB, CAN
82	Convey-All 1418 14 in x 18 ft Transfer Grain Conveyor S/N: 1310183 C/W: Honda GX340 Gasoline Engine Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:28 AM CDT Asset located in: Ste Agathe, MB, CAN	88	2019 Vermeer S450TX Compact Track Loader S/N: 1VRD060B1K1001063 C/W: Open Operator Station, Joystick Steering, 2019 US EPA Label, 7 in Track Belts, Manual Quick Coupler, 48 in Bucket Usage: 392 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:34 AM CDT Asset located in: Ste Agathe, MB, CAN
83	Wheatheart 8 in x 9 ft Transfer Grain Auger S/N: WH19483 C/W: 2 hp Electric Motor Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:29 AM CDT Asset located in: Ste Agathe, MB, CAN	89	2005 JCB Robot 190 Skid Steer Loader S/N: SLP190WS5U1134256 C/W: Enclosed Cab, US EPA Label, Manual Quick Coupler Usage: 785 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:35 AM CDT Asset located in: Ste Agathe, MB, CAN
84	AGI TA 08-E 8 in x 9 ft Transfer Grain Auger S/N: AG02A142145618 C/W: 2 hp Electric Motor Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:30 AM CDT Asset located in: Ste Agathe, MB, CAN		

Lot #	Details	Lot #	Details
90	2012 Case 580 Super N 4x4 Backhoe Loader S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 11:36 AM CDT Asset located in: Longbow Lake, ON, CAN	95	1997 Cat D6R LGP Crawler Dozer S/N: 4TR00445 C/W: Enclosed Cab, Air Conditioner, 2000 US EPA Label, CARB Compliant, 150 in Wide Angle Blade w/ Single Tilt, 36 in Single Grouser Track Shoes Usage: 20,748 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:41 AM CDT Asset located in: Ste Agathe, MB, CAN
91	1995 Case 580 Super L 4x4 Backhoe Loader S/N: JJG0190081 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Auxiliary Hydraulics, Manual Quick Coupler, 80 in Loader Bucket, Extendable Stick, Quick Coupler, 23 in Backhoe Digging Bucket Usage: 9,978 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:37 AM CDT Asset located in: Ste Agathe, MB, CAN	96	2006 Moxy MT31 Articulated Dump Truck S/N: 710756 C/W: Air Conditioner, Steel Body Liner, 23.5R25 Tires Usage: Not Available Notes: For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 11:42 AM CDT Asset located in: Kenora, ON, CAN
92	2021 Wrangler 4500 Wheel Loader S/N: 200752 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Autoshift, 2020 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.3 cyd 78 in Bucket, 405/70R20 Tires Usage: 1,038 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Additional information available - see Supporting Documents - Lot closing time: Thu, Jul 23, 11:38 AM CDT Asset located in: Ste Agathe, MB, CAN	97	2006 Moxy MT31 Articulated Dump Truck S/N: 710725 C/W: Air Conditioner, Steel Body Liner, 23.5R25 Tires Usage: Not Available Notes: For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 11:43 AM CDT Asset located in: Kenora, ON, CAN
93	New Holland G170 Motor Grader S/N: J1040DJ231 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 2007 US EPA Label, 14 ft / 4.27 m Moldboard, Front Auxiliary Hydraulics, Front Scarifier, 14.00R24 Tires Usage: 873 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:39 AM CDT Asset located in: Ste Agathe, MB, CAN	98	1987 Bomag BW 213 D Smooth Drum Compactor S/N: 101400250231 C/W: Open Operator Station, Air Ride Seat, Deutz 6 Cylinder Diesel Engine, 82 in Drum Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:44 AM CDT Asset located in: Ste Agathe, MB, CAN
94	Champion D-600 Motor Grader S/N: Not Available C/W: Located in Lane 5 Spot 5, Enclosed Cab, 14 ft / 4.27 m Moldboard, Mid Mount Scarifier, 14.00-24 Tires Usage: 2,419 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:40 AM CDT Asset located in: Brandon, MB, CAN	99	2005 John Deere 450C LC Tracked Excavator S/N: FF450CX091641 C/W: Air Conditioner, Hydraulic Cab Riser, 12 ft 6 in Stick, 36 in Triple Grouser Track Shoes, High and Wide Undercarriage, Rock Guards, 74 in Digging Bucket, Catwalks Usage: Not Available Notes: For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 11:45 AM CDT Asset located in: Kenora, ON, CAN

Lot #	Details	Lot #	Details
100	2015 John Deere 210G LC Tracked Excavator S/N: 1FF210GXHFD523101 C/W: Air Conditioner, Rear View Camera, 2015 US EPA Label, Engine Coolant Heater, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 57 in Cleanup Bucket Usage: 7,926 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:46 AM CDT Asset located in: Ste Agathe, MB, CAN	105	JLG 450AJ Series II 4WD Diesel Articulating Boom Lift S/N: 0300090089 C/W: Located in Lane 5 Spot 9, 500 lb Max Weight Capacity, Jib, Power to Platform, 4 Cylinder Diesel Engine, 33x16.5 Tires Usage: 6,776 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:51 AM CDT Asset located in: Brandon, MB, CAN
101	2004 Tanguay WL350 Wheel Excavator S/N: 6A17950157 C/W: Air Conditioner, Air Ride Seat, Hydraulic Cab Riser, Cab Screens, Auxiliary Hydraulic Plumbing, Front and Rear Stabilizers, 20.5R25 Tires, Rototilt Coupler, Rotating Grapple, Catwalks Usage: 40,366 Hr Lot closing time: Thu, Jul 23, 11:47 AM CDT Asset located in: Winnipeg, MB, CAN	106	2000 JLG 40 E 2WD Electric Articulating Boom Lift S/N: 300051904 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, G78-15 Tires Usage: 2,650 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:52 AM CDT Asset located in: Ste Agathe, MB, CAN
102	2013 Cat M316D Wheel Excavator S/N: CATM316DCD6W00993 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2013 US EPA Label, 8 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Stabilizers, 10.00x20 Tires, Manual Quick Coupler, 66 in Hydraulic Tilting Bucket Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:48 AM CDT Asset located in: Ste Agathe, MB, CAN	107	Skyjack SJII3220 Electric Scissor Lift S/N: Not Available C/W: Located in Lane 5 Spot 8, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:53 AM CDT Asset located in: Brandon, MB, CAN
103	Kolberg 271 Portable Incline Screen Plant S/N: 401809 C/W: Located in Lane 10 Spot 7, Kolberg 4 ft x 8 ft Vibratory Grizzly Feeder 8 ft x 4 ft Double Deck Screen, 35 in Wide Under Crusher Conveyor, 30 in Crusher to Screen Conveyor, 30 in Wide Under Screen Conveyor, John Deere 4 Cylinder Engine, S/A Carrier, Hydraulic Leveling Usage: 4,599 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:49 AM CDT Asset located in: Brandon, MB, CAN	108	2018 MacDon FD145 45 ft Flex Draper Combine Header S/N: 32802518 C/W: Located in Lane 8 Spot 2, To Fit Claas Lexion 500/600/700 Series, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Double Knife Drive, Row Dividers, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:54 AM CDT Asset located in: Brandon, MB, CAN
104	2000 Ditch Witch JT2720 Directional Drill S/N: 213219 C/W: Open Operator Station, 6 Cylinder Diesel Engine, Drill Rod Loading System, 12 in Rubber Tracks Usage: 9,564 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:50 AM CDT Asset located in: Ste Agathe, MB, CAN		

Lot #	Details	Lot #	Details
109	2013 MacDon FD75-D 45 ft Flex Draper Combine Header S/N: 235091 C/W: To Fit John Deere S Series, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Double Knife Drive, Row Dividers, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: Equipment from Schiewe Farms Ltd - For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:55 AM CDT Asset located in: Rosenfeld, MB, CAN	113	2012 John Deere 640FD 40 ft Flex Draper Combine Header S/N: 1H0640FDKC0746328 C/W: Located in Lane 8 Spot 9, To Fit S Series, Split P/U Reel, Hydraulic Fore & Aft, Double Knife Drive, Poly Skid Plates, AHHC Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:59 AM CDT Asset located in: Brandon, MB, CAN
110	2012 MacDon FD70 45 ft Flex Draper Combine Header S/N: 227857-12 C/W: To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Double Knife Drive, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:56 AM CDT Asset located in: Ste Agathe, MB, CAN	114	2011 MacDon FD70 40 ft Flex Draper Combine Header S/N: 207132 C/W: To Fit Case IH AFX and 2009 & Newer Midrange, All New Holland CR/CX, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Double Knife Drive, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:00 PM CDT Asset located in: Ste Agathe, MB, CAN
111	2017 John Deere 645FD 45 ft Flex Draper Combine Header S/N: 1H0645FDCH0795049 C/W: Located in Lane 8 Spot 9, To Fit S Series, Split P/U Reel, Hydraulic Fore & Aft, Double Knife Drive, Row Dividers, Poly Skid Plates Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:57 AM CDT Asset located in: Brandon, MB, CAN	115	2011 MacDon FD70 40 ft Flex Draper Combine Header S/N: 209084 C/W: Located in Lane 8 Spot 1, To Fit Case IH AFX and 2009 & Newer Midrange, All New Holland CR/CX, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Double Knife Drive, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:01 PM CDT Asset located in: Brandon, MB, CAN
112	2013 Case IH 2152 40 ft Flex Draper Combine Header S/N: YDZN09390 C/W: Located in Lane 8 Spot 7, To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Single Knife Drive, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 11:58 AM CDT Asset located in: Brandon, MB, CAN	116	2009 MacDon FD70 38 ft Flex Draper Combine Header S/N: Y9ZN11970 C/W: Located in Lane 8 Spot 5, To Fit Case IH AFX and 2009 & Newer Midrange, All New Holland CR/CX, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Double Knife Drive, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:02 PM CDT Asset located in: Brandon, MB, CAN
		117	2016 Honey Bee 236 Combine Header S/N: 526036AF16 Usage: Not Available Lot closing time: Thu, Jul 23, 12:03 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
118	2012 Claas 1200 MaxFlex 40 ft Flex Combine Header S/N: 53500409 C/W: To Fit 500/600/700 Series, Split P/U Reel, Hydraulic Fore & Aft, Full Finger Auger, Double Knife Drive, AWS Air Assist Bar Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:04 PM CDT Asset located in: Ste Agathe, MB, CAN	123	2008 John Deere 635F 35 ft Flex Combine Header S/N: H00635F725164 C/W: Located in Lane 8 Spot 10, To Fit 60/70 Series, P/U Reel, Electric Fore & Aft, Full Finger Auger, Single Knife Drive, AWS Air Assist Bar, Row Dividers, Poly Skid Plates Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:09 PM CDT Asset located in: Brandon, MB, CAN
119	Crary C36 36 ft Flex Draper Combine Header S/N: 400719 C/W: Located in Lane 8 Spot 8, To Fit John Deere 50 Series, Air Reel, Hydraulic Fore & Aft, Double Knife Drive, Poly Skid Plates Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:05 PM CDT Asset located in: Brandon, MB, CAN	124	2005 John Deere 635F 35 ft Flex Combine Header S/N: H00635F711480 C/W: Located in Lane 8 Spot 10, To Fit 60/70 Series, P/U Reel, Electric Fore & Aft, Full Finger Auger, Single Knife Drive, AWS Air Assist Bar, Row Dividers, Poly Skid Plates Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:10 PM CDT Asset located in: Brandon, MB, CAN
120	2014 Case IH 3020 35 ft Flex Combine Header S/N: YEH230109 C/W: To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, P/U Reel, Hydraulic Fore & Aft, Full Finger Auger, Double Knife Drive, AWS Air Assist Bar Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:06 PM CDT Asset located in: Ste Agathe, MB, CAN	125	2005 John Deere 635F 35 ft Flex Combine Header S/N: 1H00635F706356 C/W: To Fit 60/70 Series, P/U Reel, Hydraulic Fore & Aft, Full Finger Auger, Single Knife Drive, Poly Skid Plates, Elmers Header Transport Trailer Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:11 PM CDT Asset located in: Ste Agathe, MB, CAN
121	2014 Case IH 3020 TerraFlex 35 ft Flex Combine Header S/N: YEH230107 C/W: To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, P/U Reel, Hydraulic Fore & Aft, Full Finger Auger, Double Knife Drive Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:07 PM CDT Asset located in: Brandon, MB, CAN	126	2004 John Deere 635F 35 ft Flex Combine Header S/N: H00635F706593 C/W: To Fit 60/70 Series, P/U Reel, Hydraulic Fore & Aft, Full Finger Auger, Single Knife Drive, Row Dividers, New Cross Auger Installed PIP, "Header Transport - sold separately" Usage: Not Available Notes: "Header Transport - sold separately" - Equipment from Schiewe Farms Ltd - For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:12 PM CDT Asset located in: Rosenfeld, MB, CAN
122	2014 New Holland 740CF-35 DD 35 ft Flex Combine Header S/N: YEH430025 C/W: To Fit Case IH AFX and 2009 & Newer Midrange, All New Holland CR/CX, Air Reel, Electric Fore & Aft, Full Finger Auger, Double Knife Drive, Poly Skid Plates Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:08 PM CDT Asset located in: Ste Agathe, MB, CAN		

Lot #	Details	Lot #	Details
127	2003 John Deere 930 30 ft Flex Combine Header S/N: H00930F702572 C/W: Located in Lane 8 Spot 8, To Fit 50 Series, P/U Reel, Hydraulic Fore & Aft, Double Knife Drive, AWS Air Assist Bar, Poly Skid Plates Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:13 PM CDT Asset located in: Brandon, MB, CAN	132	2010 MacDon D60-D 40 ft Draper Combine Header S/N: 199804 C/W: Located in Lane 8 Spot 6, To Fit Claas Lexion 500/600/700 Series, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Double Knife Drive, Poly Skid Plates, Gauge Wheels, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:18 PM CDT Asset located in: Brandon, MB, CAN
128	2001 Case IH 1020 30 ft Flex Combine Header S/N: JJC0326818 C/W: To Fit 88 Series, P/U Reel, Hydraulic Fore & Aft, Single Knife Drive, Header Transport Trailer Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:14 PM CDT Asset located in: Ste Agathe, MB, CAN	133	2016 MacDon D65 35 ft Draper Combine Header S/N: 296482 C/W: Located in Lane 8 Spot 3, To Fit Case IH AFX and 2009 & Newer Midrange, All New Holland CR/CX, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Single Knife Drive, Poly Skid Plates, Gauge Wheels, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:19 PM CDT Asset located in: Brandon, MB, CAN
129	2014 Case IH 3152 40 ft Draper Combine Header S/N: YEH040221 C/W: To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Single Knife Drive, Poly Skid Plates, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:15 PM CDT Asset located in: Ste Agathe, MB, CAN	134	2012 John Deere 635D 35 ft Draper Combine Header S/N: 1H00635DACR745300 C/W: To Fit 60/70/S Series, P/U Reel, Hydraulic Fore & Aft, Double Knife Drive, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:20 PM CDT Asset located in: Ste Agathe, MB, CAN
130	2013 John Deere 640D 40 ft Draper Combine Header S/N: 1H00640DTDR755265 C/W: To Fit 60/70/S Series, Split P/U Reel, Hydraulic Fore & Aft, Double Knife Drive, Poly Skid Plates, Gauge Wheels Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:16 PM CDT Asset located in: Brandon, MB, CAN	135	2011 New Holland 94C 30 ft Draper Combine Header S/N: 30GR121123 C/W: To Fit Case IH AFX and 2009 & Newer Midrange, All New Holland CR/CX, P/U Reel, Hydraulic Fore & Aft, Single Knife Drive, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:21 PM CDT Asset located in: Brandon, MB, CAN
131	2013 John Deere 640D 40 ft Draper Combine Header S/N: 1H00640DCDR755264 C/W: To Fit 60/70/S Series, Split P/U Reel, Hydraulic Fore & Aft, Double Knife Drive, Gauge Wheels Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:17 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
136	2004 Case IH 2042 36 ft Draper Combine Header S/N: Not Available C/W: To Fit 88 Series, Split P/U Reel, Hydraulic Fore & Aft, Upper Cross Auger, Single Knife Drive, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:22 PM CDT Asset located in: Ste Agathe, MB, CAN	141	Massey Ferguson 1183 8 Row 20 ft Corn Combine Header S/N: 2739120345 C/W: To Fit 700/800 Series, 30 in Row Spacing Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:27 PM CDT Asset located in: Ste Agathe, MB, CAN
137	1993 MacDon 960 36 ft Draper Combine Header S/N: 84284 C/W: Located in Lane 8 Spot 4, To Fit John Deere 50 Series, Split P/U Reel, Manual Fore & Aft, Upper Cross Auger, Single Knife Drive, Gauge Wheels, Slow Speed Transport Wheel Package Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:23 PM CDT Asset located in: Brandon, MB, CAN	142	1988 John Deere 843 8 Row 20 ft Corn Combine Header S/N: H00843X625692 C/W: To Fit 50/60/70 Series, 30 in Row Spacing Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:28 PM CDT Asset located in: Ste Agathe, MB, CAN
138	1989 John Deere 924 24 ft Combine Header S/N: H00924F631381 C/W: Located in Lane 8 Spot 10, To Fit 50 Series, Hydraulic Fore & Aft, Single Knife Drive Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:24 PM CDT Asset located in: Brandon, MB, CAN	143	2022 Case IH 3016 Series II 15 ft Combine Pickup Header S/N: YNS100776 C/W: Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:29 PM CDT Asset located in: Ste Agathe, MB, CAN
139	2008 Case IH 2612 12 Row 30 ft Corn Combine Header S/N: 686546009 C/W: To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, 30 in Row Spacing, Knife Rolls, c/w Stalk Stompers Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:25 PM CDT Asset located in: Ste Agathe, MB, CAN	144	2022 Case IH 3016 15 ft Combine Pickup Header S/N: YMS00050 C/W: Located in Lane 8 Spot 12, To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:30 PM CDT Asset located in: Brandon, MB, CAN
140	1998 New Holland 996 8 Row 15 ft Corn Combine Header S/N: 620527 C/W: To Fit Case IH AFX and 2009 & Newer Midrange, All New Holland CR/CX, 22 in Row Spacing, Knife Rolls Usage: Not Available Notes: Calmer Knife Rollers as per owner - For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:26 PM CDT Asset located in: Ste Agathe, MB, CAN	145	2011 Case IH 3016 15 ft Combine Pickup Header S/N: YBS026723 C/W: Located in Lane 8 Spot 11, To Fit Case 8120/9120, Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:31 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
146	2013 Case 3016 15 ft Combine Pickup Header S/N: YCS036008 C/W: Located in Lane 8 Spot 11, Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:32 PM CDT Asset located in: Brandon, MB, CAN	151	Claas Lexion P516 15 ft Combine Pickup Header S/N: 43341019 C/W: Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:37 PM CDT Asset located in: Ste Agathe, MB, CAN
147	2011 Case IH 2016 16 ft Combine Pickup Header S/N: CCC0024829 C/W: Located in Lane 8 Spot 12, To Fit Case 8120/9120, Hydraulic Windrow Compressor, Crop Catcher Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:33 PM CDT Asset located in: Brandon, MB, CAN	152	Claas Lexion P514 14 ft Combine Pickup Header S/N: 43340736 C/W: Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:38 PM CDT Asset located in: Ste Agathe, MB, CAN
148	2010 Case 2016 14 ft Combine Header S/N: CCC0023750 C/W: Located in Lane 8 Spot 11, To Fit AFX and 2009 & Newer Midrange, All New Holland CR/CX, Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:34 PM CDT Asset located in: Brandon, MB, CAN	153	2014 New Holland 970CP 16 ft Combine Pickup Header S/N: YES048772 C/W: Located in Lane 8 Spot 12, Hydraulic Windrow Compressor, Hydraulic Folding Gauge Wheels Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:39 PM CDT Asset located in: Brandon, MB, CAN
149	2014 John Deere 615P 15 ft Combine Pickup Header S/N: 1H00615PAD0765308 C/W: Located in Lane 8 Spot 13, To Fit 60/70/S Series, Hydraulic Windrow Compressor, Crop Catcher Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:35 PM CDT Asset located in: Brandon, MB, CAN	154	Agco Swath Master 13 ft Combine Pickup Header S/N: SL41143 C/W: Located in Lane 8 Spot 13, To Fit Gleaner Combine, Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:40 PM CDT Asset located in: Brandon, MB, CAN
150	2015 John Deere 615P 15 ft Combine Pickup Header S/N: 1H00615PLF0775745 C/W: Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:36 PM CDT Asset located in: Brandon, MB, CAN	155	2004 New Holland 76C 14 ft Combine Pickup Header S/N: PMN0024777 C/W: Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:41 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
156	2009 New Holland 760 14 ft Combine Pickup Header S/N: PPP004054 C/W: Hydraulic Windrow Compressor Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:42 PM CDT Asset located in: Brandon, MB, CAN	160	2008 Heartland Cyclone 4012 40 ft Tri/A Toy Hauler Travel Trailer S/N: 5SFGF40398E006440 C/W: Located in Lane 6 Spot 2, Sleeps 9 People, 18000 lb GVWR, 3 Slide Outs, Exterior Entertainment, Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 225 /75R15 Tires Usage: Not Available Notes: Water damage - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 12:50 PM CDT Asset located in: Brandon, MB, CAN
157	2004 John Deere 914P 14 ft Combine Pickup Header S/N: H00914W705741 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:43 PM CDT Asset located in: Ste Agathe, MB, CAN	161	2012 Jayco Eagle 31 ft 6 in T/A Travel Trailer S/N: 1UJCJ0BS5C1PH0052 C/W: Located in Lane 6 Spot 3, Sleeps 9 People, 11200 lb GVWR, 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 12:51 PM CDT Asset located in: Brandon, MB, CAN
158	2000 John Deere 914P 14 ft Combine Pickup Header S/N: H00914W685680 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:44 PM CDT Asset located in: Ste Agathe, MB, CAN	162	Party Barge 27 27 ft Pontoon Boat S/N: Not Available C/W: Located in Lane 6 Spot 1, 16 Passenger, Outboard Mercury Mercruiser Engine, Reverse, Fish Finder Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:51 PM CDT Asset located in: Brandon, MB, CAN
159	2005 Dynamax Isata 5 30FW Motor Home S/N: 1FDAF56Y65EC54153 C/W: Air Conditioner, Automatic Transmission, Ford Triton V10 6.8 L Gasoline Engine, 2005 US EPA Label, CARB Compliant, Sleeps 4 People, 17950 lb GVWR, 2 Slide Outs, Power Entrance Step, Power Leveling Jacks, Power Awning, Onan Marquis Gold 7000 7 kVA Generator w/ 129 hrs, Class C Usage: 19,332 Mi Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until April 30, 2027 - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:50 PM CDT Asset located in: Ste Agathe, MB, CAN	163	2011 John Deere Gator 625i 4x4 Utility Vehicle S/N: 1M0625GSEBM015713 C/W: Canopy, 2 Passenger, Windshield, Rear Screen, Locking Front Differential, Hitch Receiver, Manual Dump Bed, 2011 US EPA Label, John Deere 22.5 hp Gasoline Engine Usage: 1,925 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:52 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
164	2017 Polaris Ranger XP 900 4x4 Side By Side S/N: 3NSRTE877HG955929 C/W: Canopy, 3 Passenger, Rear Screen, Winch, Brush Guard, Hitch Receiver, Manual Dump Bed, 2 Cylinder 900 cc Gasoline Engine Usage: 653 Hr Notes: See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:52 PM CDT Asset located in: Brandon, MB, CAN	168	2010 Ford E-350 E-Series 14 Passenger Van S/N: 1FBSS3BL6ADA03110 C/W: Located in Lane 1 Spot 11, V8 5.4 L Gasoline Engine, 2010 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 345,679 Km Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:54 PM CDT Asset located in: Brandon, MB, CAN
165	2007 Yamaha Grizzly 700 4x4 ATV S/N: JY4AM09W67C001628 C/W: Located in Lane 1 Spot 2, Electric Start, Liquid Cooled, Fuel Injection, Forward Gears w/ Reverse, 868 Engine Hours, Yamaha Gasoline Engine Usage: 3,995 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 12:53 PM CDT Asset located in: Brandon, MB, CAN	169	2018 GMC Terrain SLE AWD SUV S/N: 3GKALTEV5JL369205 C/W: Located in Lane 1 Spot 5, 4 cyl 1.5 L Gasoline Engine, 2018 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 172,577 Km Notes: Engine Issues - See deficiencies - For more information, please contact Brad Werk PH: 639.994.2885 - AB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:55 PM CDT Asset located in: Brandon, MB, CAN
166	2001 Honda Civic Automobile S/N: 2HGES16681H934665 C/W: Located in Lane 1 Spot 4, 4 cyl 1.7 L Gasoline Engine, 2001 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 254,269 Km Notes: Complete dispersal for Brandon Bus Lines Ltd - See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:53 PM CDT Asset located in: Brandon, MB, CAN	170	2009 Jeep Compass Sport North Edition 4WD SUV S/N: 1J4FF47B59D175092 C/W: 4 cyl 2.4 L Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 134,647 Km Notes: Previous Damage exceeds 10K as per Carfax on file - For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:55 PM CDT Asset located in: Ste Agathe, MB, CAN
167	2015 Ford Transit 350 XLT 11 Passenger Van S/N: 1FBAX2ZV0FKA85661 C/W: Located in Lane 1 Spot 10, 5 cyl 3.2 L Diesel Engine, 2015 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Towing Hitch Usage: 336,897 Km Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:54 PM CDT Asset located in: Brandon, MB, CAN	171	2015 Ram 3500 4x4 Crew Cab Pickup S/N: 3C63RRGL3FG690264 C/W: Located in Lane 1 Spot 20, 6.7 L 6 Cylinder Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Dual Rear Wheel, 14000 lb GVWR, 235/80R17 Tires, 8 ft Bed Usage: 501,394 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Recalls as per Carfax on file - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:56 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
172	2012 Ford F-350 FX4 4x4 Crew Cab Pickup S/N: 1FT8W3DT8CEB26881 C/W: Located in Lane 1 Spot 17, 6.7 L Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Dual Rear Wheel, 13300 lb GVWR, 255/80R17 Tires, 8 ft Bed Usage: 451,563 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:56 PM CDT Asset located in: Brandon, MB, CAN	175	2015 GMC Sierra 2500HD SLE 4x4 Crew Cab Pickup S/N: 1GT12YEG4FF564355 C/W: Located in Lane 1 Spot 12, V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 104,517 Km Notes: See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - SK Title/Registration May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:58 PM CDT Asset located in: Brandon, MB, CAN
173	2011 Chevrolet Silverado 3500HD 4x4 Crew Cab Pickup S/N: 1GC4K1C84BF161891 C/W: 6.6 L 6 Cylinder Diesel Engine, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Dual Rear Wheel, 235/80R17 Tires, 8 ft Bed Usage: 366,242 Km Notes: See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:57 PM CDT Asset located in: Brandon, MB, CAN	176	2011 GMC Sierra 2500 SLT 4x4 Crew Cab Pickup S/N: 1GT121E88BF179410 C/W: Located in Lane 1 Spot 19, 6.6 L V8 Diesel Engine, 2011 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R18 Tires, 6 ft 7 in Bed Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:58 PM CDT Asset located in: Brandon, MB, CAN
174	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5GL5JG102788 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 275 /65R20 Tires, 6 ft 6 in Bed Usage: 150,985 Km Notes: Recalls as per Carfax on file -For more information, please contact Mike Maneluk- 204.557.0805 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:57 PM CDT Asset located in: Winnipeg, MB, CAN	177	1996 Mazda Scrum 4x4 Pickup S/N: DK51T395014 C/W: Located in Lane 1 Spot 3, Gasoline Engine, 4 Speed Manual Transmission, Air Conditioner, 145R12 Tires, 6 ft 6 in Bed Usage: 132,760 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:59 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
178	2002 International 3800 Blue Bird 4x2 2-Seat School Bus S/N: 1HVBBABP02H521396 C/W: Located in Lane 1 Spot 34, Automatic Transmission, 6846 hrs Carrier Engine, International T444E 6 Cylinder Diesel Engine, 255/70R22.5, Spring Suspension, 276 in Wheelbase Usage: 287,816 Km Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 12:59 PM CDT Asset located in: Brandon, MB, CAN	181	2012 Van Hool C2045 6x2 46-Seat Coach S/N: YE2CC2BB3C2046306 C/W: Located in Lane 1 Spot 39, Air Conditioner, Allison Automatic Transmission, Lavatory, Cummins ISX 6 Cylinder 11.9 L Diesel 425 hp Engine, Aluminum Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: 432,352 Mi Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:01 PM CDT Asset located in: Brandon, MB, CAN
179	1999 Thomas/International 3800 4x2 Bus S/N: 1HVBBABM7XH679277 C/W: Located in Lane 1 Spot 33, Spicer 5 Speed Manual Transmission, 11571 hrs Carrier Engine, International B190 V6 Diesel 190 hp Engine, 1999 US EPA Label, CARB Compliant, 10R22.5, Spring Suspension, 255 in Wheelbase Usage: 469,756 Km Notes: See deficiencies - Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:00 PM CDT Asset located in: Brandon, MB, CAN	182	1999 Prevost H3-45 6x2 56-Seat Bus S/N: 2PCH33496X1012723 C/W: Located in Lane 1 Spot 40, Air Conditioner, Allison Automatic Transmission, Lavatory, Detroit Series 60 6 Cylinder Diesel Engine, Sphero Engine Coolant Heater, Aluminum Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: 619,995 Km Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:01 PM CDT Asset located in: Brandon, MB, CAN
180	2014 Van Hool CX45 6x2 56-Seat Coach S/N: YE2XC21B4E3048405 C/W: Located in Lane 1 Spot 38, Air Conditioner, Allison Automatic Transmission, Lavatory, Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Aluminum Rear Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: 546,292 Mi Notes: See deficiencies - Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:00 PM CDT Asset located in: Brandon, MB, CAN	183	1999 Prevost H3-45 6x2 56-Seat Bus S/N: 2PCH33494X1012932 C/W: Located in Lane 1 Spot 41, Air Conditioner, Allison Automatic Transmission, Lavatory, Detroit Series 60 6 Cylinder Diesel Engine, Engine Coolant Heater, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 340 in Wheelbase Usage: 863,880 Km Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:02 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
184	1997 Prevost H3-45 6x2 56-Seat Coach S/N: 2PCH33492V1011808 C/W: Located in Lane 1 Spot 37, Air Conditioner, Allison Automatic Transmission, Lavatory, Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, Webasto Engine Coolant Heater, Aluminum Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:02 PM CDT Asset located in: Brandon, MB, CAN	187	1996 Prevost H3-45 6x2 56-Seat Coach S/N: 2PCH33494T1011516 C/W: Located in Lane 1 Spot 43, Air Conditioner, Allison Automatic Transmission, Lavatory, Detroit 60 Series 6 Cylinder Diesel Engine, Spheros Engine Coolant Heater, Aluminum Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:04 PM CDT Asset located in: Brandon, MB, CAN
185	1997 Prevost H3-45 6x2 58-Seat Bus S/N: 2PCH33494V1011860 C/W: Located in Lane 1 Spot 36, Air Conditioner, Allison Automatic Transmission, Lavatory, Detroit 60 Series 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Assist Front Suspension, Air Ride Suspension, 340 in Wheelbase Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:03 PM CDT Asset located in: Brandon, MB, CAN	188	2007 International 9400i 6x4 T/A Dump Truck S/N: 2HSCNSCR17C425256 C/W: 6 Cylinder Diesel Engine, 23771 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 181 in Wheelbase, PTO, Cascade 14 ft Long x 4 ft High Steel Body, Manual Roll Tarp, Pintle Hitch Usage: 1,199,579 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until April 30, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:04 PM CDT Asset located in: Ste Agathe, MB, CAN
186	1997 Prevost H3-45 6x2 56-Seat Coach S/N: 2PCH33491V1011816 C/W: Located in Lane 1 Spot 42, Air Conditioner, Allison Automatic Transmission, Lavatory, Detroit 60 series 6 Cylinder Diesel Engine, Engine Coolant Heater, Spheros Engine Coolant Heater, Aluminum Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:03 PM CDT Asset located in: Brandon, MB, CAN	189	2000 Peterbilt 379 6x4 T/A Dump Truck S/N: 1XP5D09X7YN520834 C/W: 6 Cylinder Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 210 in Wheelbase, PTO, 15 ft Long x 4 ft High Steel Body, Manual Roll Tarp, Pintle Hitch Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:05 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
190	1998 Ford Louisville 6x4 T/A Dump Truck S/N: 1FDYS86F0WVA05357 C/W: Cat 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 203 in Wheelbase, PTO, 15 ft Long x 3 ft 6 in High Steel Body, Pintle Hitch Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until July 31, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:05 PM CDT Asset located in: Ste Agathe, MB, CAN	193	2012 Ford F-250 XL 4x4 Crew Cab Utility Truck S/N: 1FT7W2B68CEC19919 C/W: V8 6.2 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 5940 lb Front Axle, 6100 lb Rears, 9900 lb GVWR, 225/70R19.5, Spring Suspension, 159 in Wheelbase, 7 ft Body Usage: 305,332 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - ON Title /Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:07 PM CDT Asset located in: Brandon, MB, CAN
191	2011 Ford F-350 4x4 Extended Cab Utility Truck S/N: 1FT7X3B61BED10130 C/W: Located in Lane 1 Spot 15, V8 6.2 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, 5940 lb Front Axle, 6290 lb Rears, 9900 lb GVWR, 245/75R17, Spring Suspension, 150 in Wheelbase, 8 ft 6 in Body Usage: 377,043 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - ON Title /Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:06 PM CDT Asset located in: Brandon, MB, CAN	194	2008 Peterbilt 330 4x2 Flatbed Truck S/N: 2NPNHM6HX8M760995 C/W: Paccar PX-6 6 Cylinder 6.7 L Diesel 300 hp Engine, 2007 US EPA Label, 22154 Engine hrs, Automatic Transmission, 3629 kg Front Axle, 8165 kg Rears, 11794 kg GVWR, 11R22.5, Spring Suspension, 209 in Wheelbase, 18 ft x 102 in Bed Usage: 519,266 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:07 PM CDT Asset located in: Ste Agathe, MB, CAN
192	2010 Ford F-350 XL 4x4 Extended Cab Utility Truck S/N: 1FTSX3B56AEA71920 C/W: Located in Lane 1 Spot 18, V8 5.4 L Gasoline Engine, 2010 US EPA Label, 16755 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 6262 lb Rears, 9900 lb GVWR, 225/70R19.5, Spring Suspension, 160 in Wheelbase, General 8 ft 5 in Body Usage: 440,703 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - ON Title /Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:06 PM CDT Asset located in: Brandon, MB, CAN	195	2002 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAP02H535151 C/W: Diesel Engine, 18655 Engine hrs, Automatic Transmission, 11R22.5, Air Ride Suspension, 194 in Wheelbase, PTO Usage: 203,661 Mi Notes: MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:08 PM CDT Asset located in: Stony Mountain, MB, CAN
		196	2005 GMC Sierra 3500 SLT 4x4 Crew Cab Flatbed Truck S/N: 1GTJK33255F898449 C/W: Duramax 6 Cylinder 6.6 L Diesel Engine, Automatic Transmission, 2179 kg Front Axle, 3882 kg Rears, 11400 lb GVWR, 215/85R16, Spring Suspension, 144 in Wheelbase, 8 ft 2 in x 92 in Bed, Aluminum Frame Usage: 686,128 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: June 25 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents - The closing time of Lots 159 - 160 are tied together, any time extensions will be applied to all lots Lot closing time: Thu, Jul 23, 01:08 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
197	2012 Freightliner FM2 4x2 Water Truck S/N: 1FVACYBS7CHBW2844 C/W: Cummins 6 Cylinder 8.3 cid Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 7095 Engine hrs, Engine Brake, Allison Automatic Transmission, 23000 lb Rears, 37600 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 188 in Wheelbase, Hutchinson Industries 6561 Aluminum Tank, Pump w/ Honda GX 1 Cylinder Engine, 8 ft, Spray Bar, Rear Spray, Side Spray Usage: 267,045 Km Notes: For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 01:09 PM CDT Asset located in: Kenora, ON, CAN	199	2014 Ram 5500 4x2 Crew Cab Service Truck S/N: 3C7WRNFJ3EG297154 C/W: HEMI 6.4L V8 6.4 L Diesel Engine, 2014 US EPA Label, 4316 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 20500 lb GVWR, Aluminum Outer Wheels, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 198 in Wheelbase, 11 ft Body, IMT 3016 2 Section Hydraulic Crane, Honda GX380 Gasoline Air Compressor, Air Hose Reel Usage: 36,829 Km Notes: Recalls as per Carfax on file - For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:10 PM CDT Asset located in: Kenora, ON, CAN
198	2023 Ford F550XL XL 4x4 Crew Cab Service Truck S/N: 1FD0W5HT9PEC38514 C/W: Located in Lane 1 Spot 13, V8 6.7 L Diesel Engine, 2023 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 1935 Engine hrs, Exhaust Brake, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 203 in Wheelbase, General Body and Equipment 11 ft Body, Manual Stabilizers, Cobra Maxilift 5500 5100 lb 3 Section Hydraulic Crane, Sincro SW-E250 8 kVA Diesel Generator Set, VMAC Raptair-MF Diesel Air Compressor, Air Hose Reel Usage: 94,031 Km Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Recalls as per Carfax on file - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:09 PM CDT Asset located in: Brandon, MB, CAN	200	2008 Hino 268 4x2 Landscape Truck S/N: 2AYNE8JT383S15173 C/W: Hino J08E-TV 6 Cylinder 469 cid Diesel 220 hp Engine, 2007 US EPA Label, CARB Compliant, Automatic Transmission, 4540 kg Front Axle, 8620 kg Rears, 25950 kg GVWR, 11R22.5, Spring Suspension, 217 in Wheelbase, 12 ft 10 in x 96 in Bed, Pintle Hitch Usage: 360,744 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until June 30, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:10 PM CDT Asset located in: Ste Agathe, MB, CAN
		201	2024 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXRSVA6413 C/W: Located in Lane 2 Spot 3, Detroit DD15 505 hp Engine, 2023 US EPA Label, 13317 Engine hrs, Eaton Fuller 12-Speed Automatic Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Engine Brake, Double Differential Locks, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 791,519 Km Notes: Truck is off-site for ABS repairs, contact Brandon site to view; See deficiencies - Contact Brandon site for viewing details - For more information, please contact the Brandon office PH: 204.441.1079 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:11 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
202	2023 Peterbilt 375 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2PD875098 C/W: Cummins X15 Engine, 2021 US EPA Label, 15664 Engine hrs, Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 249 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Lot closing time: Thu, Jul 23, 01:11 PM CDT Asset located in: Brandon, MB, CAN	205	2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2MSMC9514 C/W: Detroit DD15 505 hp Engine, 2020 US EPA Label, 18352 Engine hrs, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 70 in High Rise Sleeper Cab, Bunk Heater, 233 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,037,900 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Proof of Ownership /TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:13 PM CDT Asset located in: Ste Agathe, MB, CAN
203	2023 International LT62F 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPRXP439278 C/W: Located in Lane 2 Spot 7, Cummins X15 Engine, 2022 US EPA Label, 13269 Engine hrs, Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 231 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 915,663 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:12 PM CDT Asset located in: Brandon, MB, CAN	206	2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR3MLLX1509 C/W: Located in Lane 2 Spot 4, Detroit DD15 505 hp Engine, 2020 US EPA Label, 24315 Engine hrs, Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 60 in High Rise Sleeper Cab, Bunk Beds, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Auto Lube, Dual Fuel Tanks Usage: 1,306,034 Km Notes: See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - AB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:13 PM CDT Asset located in: Brandon, MB, CAN
204	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3NSNG6110 C/W: Detroit DD15 Engine, 2021 US EPA Label, Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Double Differential Locks, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: ON Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:12 PM CDT Asset located in: Brandon, MB, CAN	207	2020 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X3LR969432 C/W: Cummins ISX15 500 hp Engine, 2019 US EPA Label, 21517 Engine hrs, 18-Speed Manual Transmission, 5988 kg Front Axle, 18144 kg Rears, 24132 lb GVWR, Engine Brake, Double Differential Locks, 72 in Mid Roof Sleeper Cab, Bunk Beds, 244 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,045,120 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: June 25 - MB Proof of Ownership /TOD - Previous Damage exceeds 60K as per Carfax on file - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:14 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
208	2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9XXLD668549 C/W: Paccar MX-13 455 hp Engine, Automatic Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 232 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 957,098 Km Notes: MB Safety valid until November 30, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:14 PM CDT Asset located in: Ste Agathe, MB, CAN	211	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8LSLV4496 C/W: Detroit DD15 505 hp Engine, 16105 Engine hrs, Detroit DT12-1650-DH1 12-Speed Automatic Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Engine Brake, 70 in High Rise Sleeper Cab, Bunk Beds, 229 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Blower Usage: 922,938 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until July 31, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:16 PM CDT Asset located in: Ste Agathe, MB, CAN
209	2020 Mack Anthem 6x4 T/A Sleeper Truck Tractor S/N: 1M1AN4GYXLM014770 C/W: Located in Lane 2 Spot 8, Mack MP8 Engine, 2019 US EPA Label, 969 Engine hrs, Mack mDRIVE 12-Speed Automated Transmission 5997 kg Front Axle, 20800 kg Rears, 26797 kg GVWR, Engine Brake, Differential Lock, 60 in Mid Roof Sleeper Cab, 232 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks, Headache Rack Usage: 975,206 Km Notes: Stuck in derate mode - See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:15 PM CDT Asset located in: Brandon, MB, CAN	212	2020 Freightliner Cascadia T/A Sleeper Truck Tractor S/N: 3AKJHHDR0LSKW3108 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:16 PM CDT Asset located in: Ste Agathe, MB, CAN
210	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9LN673325 C/W: Cummins X15 450 hp Engine, 2019 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 56 in High Rise Sleeper Cab, Bunk Beds, 228 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 918,432 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until January 31, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:15 PM CDT Asset located in: Ste Agathe, MB, CAN	213	2019 Peterbilt 579 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7KD200244 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:17 PM CDT Asset located in: Ste Agathe, MB, CAN
		214	2018 Peterbilt 579 T/A Sleeper Truck Tractor S/N: 1XPBDP9X2JD483599 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:17 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
215	2018 Peterbilt 579 T/A Sleeper Truck Tractor S/N: 1XPBDP9X3JD485037 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:18 PM CDT Asset located in: Ste Agathe, MB, CAN	219	2015 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 1FUJGLD51FLGE1616 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: June 25 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:20 PM CDT Asset located in: Ste Agathe, MB, CAN
216	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6JSJM0538 C/W: Detroit DD15 505 hp Engine, 20837 Engine hrs, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 70 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 229 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,291,936 Km Notes: AB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:18 PM CDT Asset located in: Ste Agathe, MB, CAN	220	2014 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH4EN163085 C/W: Volvo D13 425 hp Engine, 2013 US EPA Label, Volvo ATO2612D 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, Differential Lock, 61 in High Rise Sleeper Cab, Bunk Beds, 216 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,621,335 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: June 25 - Buyer responsible for load out and all associated costs - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:20 PM CDT Asset located in: Ste Agathe, MB, CAN
217	2018 Freightliner Cascadia 132 T/A Day Cab Truck Tractor S/N: 1FUJGH5JLJY4929 Usage: Not Available Notes: MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 01:19 PM CDT Asset located in: Ste Agathe, MB, CAN	221	2013 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDD49X1DJ962857 C/W: Located in Lane 2 Spot 5, Cummins ISX15 485 hp Engine, Engine Coolant Heater, 2012 US EPA Label, 21412 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Double Differential Locks, 62 in Mid Roof Sleeper Cab, 236 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,012,645 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Safety valid until January 31, 2027 - MB Title /Registration - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:21 PM CDT Asset located in: Brandon, MB, CAN
218	2016 Western Star 5700 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDV6GLHM8799 C/W: Detroit Engine, 22522 Engine hrs, Eaton Fuller Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, Differential Lock, 60 in Mid Roof Sleeper Cab, Bunk Beds, Bunk Heater, 231 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,279,798 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: June 25 - Buyer responsible for load out and all associated costs - Additional Information available - See supporting documents - The closing time of Lots 207 - 208 are tied together, any time extensions will be applied to all lots Lot closing time: Thu, Jul 23, 01:19 PM CDT Asset located in: Ste Agathe, MB, CAN		

Lot #	Details	Lot #	Details
222	2012 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49X1CD144473 C/W: Located in Lane 2 Spot 2, Cummins ISX15 Engine, 2011 US EPA Label, 24006 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 70 in Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 236 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,230,700 Hr Notes: Mechanical Issues - See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:21 PM CDT Asset located in: Brandon, MB, CAN	224	2011 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKADP9X5BJ947697 C/W: Paccar MX 360T 485 hp Engine, 2010 US EPA Label, 9408 Engine hrs, Eaton Fuller FO-16E318B-MXP 18-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Double Differential Locks, 50 in Flat Top Sleeper Cab, 218 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 544,644 Km Notes: See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:22 PM CDT Asset located in: Brandon, MB, CAN
223	2012 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49X2CD165963 C/W: Cummins ISX15 450 hp Engine, Engine Coolant Heater, 2011 US EPA Label, 27123 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Differential Lock, 68 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 238 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R24.5, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,402,747 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until August 31, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:22 PM CDT Asset located in: Ste Agathe, MB, CAN	225	2010 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49X7AD106100 C/W: Located in Lane 2 Spot 1, Cummins ISX15 Engine, 2009 US EPA Label, 31260 Engine hrs, 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 70 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 236 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,505,670 Km Notes: See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:23 PM CDT Asset located in: Brandon, MB, CAN
		226	2006 International 9900i 6x4 T/A Sleeper Truck Tractor S/N: 2HSCCHAPR56C165194 C/W: Cummins ISX 435 hp Engine, 2005 US EPA Label, 26023 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 72 in Mid Roof Sleeper Cab, Bunk Beds, 243 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 656,883 Mi Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:23 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
227	2006 International 9900i 6x4 T/A Sleeper Truck Tractor S/N: 2HSCCHAPR46C320379 C/W: Cummins ISX 475 hp Engine, 2005 US EPA Label, 31472 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 72 in Mid Roof Sleeper Cab, 244 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,788,768 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:24 PM CDT Asset located in: Ste Agathe, MB, CAN	230	2002 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DU9X72D584313 C/W: Cat C12 505 hp Engine, 2002 US EPA Label, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Engine Brake, 58 in Mid Roof Sleeper Cab, 244 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 648,249 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:25 PM CDT Asset located in: Ste Agathe, MB, CAN
228	2003 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CG43LK32495 C/W: Detroit Series 60 500 hp Engine, 2002 US EPA Label, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 46000 lb Rears, 58000 lb GVWR, Engine Brake, Differential Lock, 48 in Mid Roof Sleeper Cab, 219 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:24 PM CDT Asset located in: Ste Agathe, MB, CAN	231	2002 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDB9X72J884983 C/W: Cat C15 475 hp Engine, 41603 Engine hrs, Eaton Fuller RTLO-16913A 13-Speed Manual, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, Condo Sleeper Cab, Auxiliary Power Unit, Sleeper Air Conditioner, 351 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Assist Front Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks, 150 in Bunk Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Proof of Ownership /TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:26 PM CDT Asset located in: Ste Agathe, MB, CAN
229	2003 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CG23LK32494 C/W: Detroit Series 60 500 hp Engine, 2002 US EPA Label, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 46000 lb Rears, 58000 lb GVWR, Engine Brake, Differential Lock, 48 in Mid Roof Sleeper Cab, 219 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:25 PM CDT Asset located in: Ste Agathe, MB, CAN	232	2000 Volvo T/A Sleeper Truck Tractor S/N: 4V4ND4JJXYN257095 Usage: Not Available Notes: MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 01:26 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
233	1998 Freightliner FLD 120 6x4 T/A Sleeper Truck Tractor S/N: 2FUPDDYBXWA912558 C/W: Cummins N14 500 hp Engine, 1997 US EPA Label, Eaton Fuller RTLO-18718B 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, 60 in Flat Top Sleeper Cab, Bunk Beds, 244 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Air Sliding 5th Wheel, Dual Fuel Tanks, 40 Rockwell 390, New PDI ECM module Usage: 649,008 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until June 30, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:27 PM CDT Asset located in: Ste Agathe, MB, CAN	236	2015 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDVXFLGP1440 C/W: Detroit 500 hp Engine, 2014 US EPA Label, 14195 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 52000 lb GVWR, Engine Brake, Double Differential Locks, 196 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 895,431 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Safety valid until June 30, 2027 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:28 PM CDT Asset located in: Ste Agathe, MB, CAN
234	2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV9GLGW8952 C/W: Detroit DD13 410 hp Engine, 24948 Engine hrs, Allison 4000 Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 175 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Proof of Ownership /TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:27 PM CDT Asset located in: Ste Agathe, MB, CAN	237	2013 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD49X9DJ960841 C/W: Located in Lane 2 Spot 15, Cummins ISX15 500 hp Engine, 2012 US EPA Label, 21318 Engine hrs, Eaton Fuller FO-18E318B MXP 18-Speed Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Engine Brake, Double Differential Locks, 194 in Wheelbase, 8-Bag Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 977,495 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:29 PM CDT Asset located in: Brandon, MB, CAN
235	2015 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED53FLGL3596 C/W: Detroit DD15 Engine, 3541 Engine hrs, Eaton Fuller FO-18E313A-MHP Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 178 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 681,147 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Proof of Ownership /TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:28 PM CDT Asset located in: Ste Agathe, MB, CAN	238	2013 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTDP0XXDD211954 C/W: Paccar MX 485 hp Engine, 2012 US EPA Label, 20373 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Engine Brake, Double Differential Locks, 244 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Dual Fuel Tanks, Headache Rack Usage: 686,222 Km Notes: Altered emissions - - Previous Damage exceeds 80K as per Carfax on file - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:29 PM CDT Asset located in: Kakabeka Falls, ON, CAN

Lot #	Details	Lot #	Details
239	2013 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTDP0X8DD211953 C/W: Paccar MX 485 hp Engine, 2012 US EPA Label, 24810 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Engine Brake, Double Differential Locks, 244 in Wheelbase, Air Suspension, Aluminum Wheels, 11R24.5, Dual Fuel Tanks, Headache Rack Usage: 840,490 Km Notes: Altered emissions - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:30 PM CDT Asset located in: Kakabeka Falls, ON, CAN	242	2012 International 8600 6x4 T/A Day Cab Truck Tractor S/N: 1HSHXSJR7CH550204 C/W: International MaxxForce 13 410 hp Engine, 2011 US EPA Label, 14262 Engine hrs, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 188 in Wheelbase, Air Suspension, Aluminum Outer Wheels, 11R24.5 Front Tires, 285/75R24.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 475,261 Km Notes: For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 01:31 PM CDT Asset located in: Kenora, ON, CAN
240	2012 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHD49X7CD155770 C/W: Located in Lane 2 Spot 16, Cummins ISX15 Engine, 2011 US EPA Label, 24161 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 218 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 741,447 Km Notes: See deficiencies - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Safety valid until November 30, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:30 PM CDT Asset located in: Brandon, MB, CAN	243	1997 Volvo WG 6x4 T/A Day Cab Truck Tractor S/N: 4V4JDBRF1VN855798 C/W: Detroit Series 60 365 hp Engine, 1996 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 168 in Wheelbase, Air Suspension, 11R22.5, Dual Fuel Tanks Usage: 650,987 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:32 PM CDT Asset located in: Ste Agathe, MB, CAN
241	2012 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHD49X1CD155778 C/W: Cummins ISX15 500 hp Engine, 2015 US EPA Label, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Engine Brake, Differential Lock, 218 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,196,721 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:31 PM CDT Asset located in: Ste Agathe, MB, CAN	244	2013 Peterbilt 348 8x4 Rollback Truck S/N: 2NP3LN0X9DM202447 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 350 hp Engine, Requires Diesel Exhaust Fluid, 14867 Engine hrs, Engine Brake, Eaton Fuller FRO-12210C 10-Speed Manual Transmission, Differential Lock, 9072 kg Front Axle, 26989 lb Rears, Spicer DSP41 Drive Axles, 4.88:1 Axle Ratio, 36061 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 295/75R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Paccar Air Ride Suspension, 284 in Wheelbase, PTO, 24 ft x 102 in Bed, Winch Usage: 396,570 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:32 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
245	2014 Hino 268 4x2 Rollback Truck S/N: 2AYNE8JTXE3S21080 C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 218 in Wheelbase, PTO, Miller SP8000 Rollback Body, 21 ft x 102 in Bed, Warn Series 12 12000 lb Winch, Hydraulic Wheel Lift Usage: 437,972 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 01:33 PM CDT Asset located in: Ste Agathe, MB, CAN	248	1999 Freightliner FL112 6x4 Grain Truck S/N: 1FVXTEDB0XHA02560 C/W: Located in Lane 1 Spot 30, Cat 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Automatic Transmission, Differential Lock, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Rubber Suspension, 232 in Wheelbase, PTO, Cancade 20 ft Long x 4 ft 10 in High Steel Body, Electric Roll Tarp, Split Swing Tailgate, Rear Hydraulics, Tailgate Chute, Pintle Hitch Usage: 185,874 Km Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Safety valid until July 31, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:34 PM CDT Asset located in: Brandon, MB, CAN
246	1998 International 4700 4x2 Rollback Truck S/N: 1HTSLABM8WH561565 C/W: Navistar BH210 V8 7.3 L Diesel 210 hp Engine, 1997 US EPA Label, CARB Compliant, International 6-Speed Manual Transmission, 255/70R22.5, Air Ride Suspension, 218 in Wheelbase, PTO, 21 ft x 96 in Bed, Winch, Hydraulic Wheel Lift Usage: 286,566 Km Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until November 30, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:33 PM CDT Asset located in: Ste Agathe, MB, CAN	249	1998 Freightliner FL80 6x4 Grain Truck S/N: 1FVXJJB4WH898360 C/W: Located in Lane 1 Spot 31, Cat 6 Cylinder Diesel Engine, 1997 US EPA Label, 4814 Engine hrs, Automatic Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, PTO, Cancade 20 ft Long x 5 ft 4 in High Steel Body, Manual Roll Tarp, Tailgate Chute Usage: Not Available Notes: Equipment from Gaston Farms Ltd - For more information, please contact David PH: 204.797.5048 - Item removal deadline: August 7 - MB Safety valid until June 30, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:35 PM CDT Asset located in: Brandon, MB, CAN
247	2006 Western Star 4900SA 8x6 Vacuum Excavator Truck S/N: 5KKPALAV16PV13618 C/W: Cat 6 Cylinder Diesel 475 hp Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Triple Differential Locks, 20000 lb Front Axle, 54000 lb Rears, 74000 lb GVWR, Aluminum Wheels, 445/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 270 in Wheelbase, PTO, Steel Debris Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, 18 ft Boom, 6 in Suction Hose, Blower, Waterblast WB9450 Boiler Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:34 PM CDT Asset located in: Ste Agathe, MB, CAN	250	2005 Freightliner M2106 4x2 Van Truck S/N: 1FVACYDC65HV53683 C/W: Cat C7 6 Cylinder 7.2 L Diesel 230 hp Engine, 2005 US EPA Label, 3216 Engine hrs, Allison Automatic Transmission, Differential Lock, 14600 lb Front Axle, 23000 lb Rears, 37600 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 280 in Wheelbase, PTO, Commercial Babcock 24 ft x 102 in Wide x 96 in High Body, Mezzanine Floor, Liftgate Usage: 514,468 Km Notes: MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:35 PM CDT Asset located in: Stony Mountain, MB, CAN

Lot #	Details	Lot #	Details
251	2009 Rainbow Summit 13 ft S/A Enclosed Trailer S/N: 2R9C6121X91625099 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 69 in Deck Width, Bulkhead, Side Door, 205 /75R15 Tires, 2990 lb GVWR Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:36 PM CDT Asset located in: Brandon, MB, CAN	255	2008 Trailtech 32 ft T/A Equipment Trailer S/N: 2CU4CETN882024411 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 26 ft Main Deck, 6 ft Fixed Dovetail, 8 in Deck Width, Manual Ramps, 255/70R22.5 Tires, 46000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:38 PM CDT Asset located in: Ste Agathe, MB, CAN
252	2008 Atlas 9 ft S/A Enclosed Trailer S/N: 5HCKC081X8E013023 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 57 in Deck Width, Side Door, 205/75R15 Tires, 2000 lb GVWR Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:36 PM CDT Asset located in: Brandon, MB, CAN	256	24 ft T/A Equipment Trailer S/N: 710048089 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 24 ft Main Deck, Manual Ramps, 235 /80R16 Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:38 PM CDT Asset located in: Ste Agathe, MB, CAN
253	2009 H & H 30 ft Tri/A Gooseneck Equipment Trailer S/N: 4J6HD30389B109441 C/W: Located in Lane 6 Spot 42, Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:37 PM CDT Asset located in: Brandon, MB, CAN	257	2005 Gerrys 53 ft Tri/A Folding Neck Trailer S/N: 2K9LB35375L052115 C/W: Air Ride Suspension, 48 ft Main Deck, 4 ft 2-Position Dovetail, 120 in Deck Width, Full Width Pickup Throat, Center Roller, Tail Roller Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - AB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 01:39 PM CDT Asset located in: Ste Agathe, MB, CAN
254	2016 Big Tex 22G 31 ft T/A Gooseneck Equipment Trailer S/N: 16VGX2529G6044946 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 6 ft Dovetail, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235 /80R16 Tires, 23900 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - ON Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:37 PM CDT Asset located in: Ste Agathe, MB, CAN	258	2019 J & J 54 ton Tri/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 2J9GEN3K8KT011084 C/W: 49359 kg GVWR, Mechanical Removable Gooseneck, 27 ft 6 in x 108 in Main Deck, Upper Deck, Air Ride Suspension, Plumbed for Booster Axle, 11'6" upper deck, pick-up throat, 4' beaver tail, 11R24.5 tires, 1' deck extenders Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:39 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
259	1999 Arne's DHR Tri/A Removable Gooseneck Lowboy Trailer S/N: 2A9105335XA003678 C/W: Hydraulic Removable Gooseneck, 23 ft x 102 in Main Deck, Folding Side Extensions, Air Ride Suspension Usage: Not Available Notes: ON Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:40 PM CDT Asset located in: Devlin, ON, CAN	263	2020 Lode King 53 ft T/A Flatbed Trailer S/N: 2LDPF5326LL068940 C/W: Located in Lane 6 Spot 31, Air Ride Suspension, Sliding Suspension, 102 in Deck Width, Wood Flooring, Aluminum Wheels, 11R22.5 Tires, 77160 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title /Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:42 PM CDT Asset located in: Brandon, MB, CAN
260	2012 Fontaine 53 ft T/A Spread Axle Step Deck Trailer S/N: 13N2532C5C1553398 C/W: Air Ride Suspension, 20+20 ft - Container Pins, 10 ft Upper Deck, 43 ft Main Deck, Deck Over Tires, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 255/70R22.5 Tires Usage: Not Available Notes: Bill of Sale - No Title/Registration - Cannot be Exported - For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 01:40 PM CDT Asset located in: Ste Agathe, MB, CAN	264	1986 Trailmobile 40 ft T/A Flatbed Trailer S/N: 2TCP402B2GA449801 C/W: Located in Lane 6 Spot 41, Spring Suspension, Sliding Suspension, 96 in Deck Width, Wood Flooring, 11R22.5 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:42 PM CDT Asset located in: Brandon, MB, CAN
261	2007 Lode King 32 ft Super B-Train Flatbed Trailer S/N: 2LDPF32307J046061 C/W: Located in Lane 6 Spot 45, Air Ride Suspension, 102 in Deck Width, Wood Flooring, Aluminum Wheels, 11R22.5 Tires, 83775 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title /Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:41 PM CDT Asset located in: Brandon, MB, CAN	265	T/A Trailer Chassis S/N: Not Available C/W: Located in Lane 6 Spot 42, Lunette Ring Hitch, Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:43 PM CDT Asset located in: Brandon, MB, CAN
262	2005 Load King 32 ft Super B-Train Lead Flatbed Trailer S/N: 2LDPF323656041169 C/W: Located in Lane 6 Spot 46, Air Ride Suspension, 102 in Deck Width, Wood Flooring, Aluminum Wheels, 11R24.5 Tires, 38000 kg GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Safety valid until February 28, 2027 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:41 PM CDT Asset located in: Brandon, MB, CAN	266	S/A Dolly S/N: Not Available C/W: Located in Lane 6 Spot 41, Spring Suspension, 11R22.5 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - No Manufacturer label - Cannot verify serial number - Will require Government issued VIN to register/export - May require inspection prior to registering - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:43 PM CDT Asset located in: Brandon, MB, CAN
		267	2006 Ditch Witch FX30 500 gal T/A Vacuum Tanker Trailer S/N: CMWFX30SC60000119 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 215/85R16 Tires, Steel Tank, Diesel Powered Blower, Dust Recovery System Usage: 994 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:44 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
268	1990 Arnes Tri/A End Dump Trailer S/N: 2A9073533LA003259 Usage: Not Available Notes: May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:44 PM CDT Asset located in: Ste Agathe, MB, CAN	272	2018 Cross Country 48 ft Tri/A Live Bottom Trailer S/N: 2C9LSR3W5JB183112 C/W: Located in Lane 6 Spot 37, Air Ride Suspension, 48 ft Body, 64 in Side Walls, Steel Body, Electric Roll Tarp, Aluminum Wheels, 11R24.5 Tires, 48000 kg GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:46 PM CDT Asset located in: Brandon, MB, CAN
269	2008 Midland SL2000 30 ft T/A End Dump Trailer S/N: 2MFB2R6C28R004958 C/W: Air Ride Suspension, 30 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, 11R22.5 Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until October 31, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 01:45 PM CDT Asset located in: Ste Agathe, MB, CAN	273	2014 Fericar 28 ft x 102 in Tri/A Lead Chip Trailer S/N: 2F9TCA5C3EC020002 C/W: Air Ride Suspension, Aluminum Wheels, 11R22.5 Tires, 39700 kg GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:47 PM CDT Asset located in: Brandon, MB, CAN
270	2007 Cross Country 27 ft T/A End Dump Trailer S/N: 2C9ESR2227M183119 C/W: Air Ride Suspension, Air Brakes, 27 ft Body, 48 in Side Walls, Steel Body, Manual Roll Tarp, 11R22.5 Tires, 28000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 01:45 PM CDT Asset located in: Ste Agathe, MB, CAN	274	2023 Vanguard 53 ft x 102 in T/A Refrigerated Trailer S/N: 2SHSR5328PS002236 C/W: Located in Lane 6 Spot 5, Carrier 7300 X4 Refrigeration Unit, 4837 Total Hours, Aluminum Frame, Air Ride Sliding Suspension, Side Skirts, Ducted Floor, 11R22.5 Tires, 30840 kg GVWR Usage: 6,510 Hr Notes: For more information, please contact the Brandon office PH: 204.441.1079 - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:47 PM CDT Asset located in: Brandon, MB, CAN
271	Renn 17 ft Tri/A Pup Dump Trailer S/N: Not Available C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 17 ft Body, 41 in Side Walls, Steel Body, Manual Roll Tarp, 11R24.5 Tires, 21000 kg GVWR Usage: Not Available Notes: For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 01:46 PM CDT Asset located in: Kenora, ON, CAN	275	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0629CW704165 C/W: 2012 Thermo King Smart Reefer 3 Refrigeration Unit, Air Ride Sliding Suspension, Pintle Hitch, Side Skirts, Ducted Floor, Swing Door, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:48 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
276	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0627CW704164 C/W: 2012 Thermo King Smart Reefer 3 Refrigeration Unit, Air Ride Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 295 /75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:48 PM CDT Asset located in: Ste Agathe, MB, CAN	280	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0624CW704168 C/W: 2012 Thermo King Smart Reefer 3 Refrigeration Unit, Air Ride Sliding Suspension, Pintle Hitch, Side Skirts, Ducted Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration- May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:50 PM CDT Asset located in: Ste Agathe, MB, CAN
277	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0624CW704171 C/W: 2012 Thermo King Smart Reefer 3 Refrigeration Unit, Air Ride Sliding Suspension, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:49 PM CDT Asset located in: Ste Agathe, MB, CAN	281	2011 Trailercraft TL-2000 48 ft T/A Curtain Side Trailer S/N: 1TTF482S4B1088323 C/W: Air Ride Suspension, Swing Door, 275 /80R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until November 30, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:51 PM CDT Asset located in: Ste Agathe, MB, CAN
278	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0622CW704167 C/W: 2012 Thermo King Smart Reefer 3 Refrigeration Unit, Air Ride Suspension, Pintle Hitch, Side Skirts, Ducted Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:49 PM CDT Asset located in: Ste Agathe, MB, CAN	282	2023 Vanguard VXP 53 ft x 102 in T/A Van Trailer S/N: 5V8VC5324PM307937 C/W: Located in Lane 6 Spot 28, Aluminum /Steel Combination Frame, Air Ride Sliding Suspension, Pintle Hitch, Side Skirts, Hardwood Floor, Swing Door, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:51 PM CDT Asset located in: Brandon, MB, CAN
279	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625CW704163 C/W: 2012 Thermo King Smart Reefer 3 Refrigeration Unit, Air Ride Sliding Suspension, Pintle Hitch, Side Skirts, Ducted Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:50 PM CDT Asset located in: Ste Agathe, MB, CAN	283	Vanguard Trailer 53 ft x 102 in T/A Van Trailer S/N: 5V8VA5328PM307459 C/W: Air Ride Suspension, Pintle Hitch, Side Skirts, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:52 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
284	2019 Utility 4000D-X 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2539K3498135 C/W: Aluminum/Steel Combination Frame, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 65000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until September 30, 2026 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:52 PM CDT Asset located in: Ste Agathe, MB, CAN	288	2017 Vanguard Van Trailer S/N: 5V8VC5322HM700398 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:54 PM CDT Asset located in: Ste Agathe, MB, CAN
285	2019 Utility Van Trailer S/N: 1UYVS2532K3498137 Usage: Not Available Notes: MB Safety valid until September 30, 2026 - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:53 PM CDT Asset located in: Ste Agathe, MB, CAN	289	2016 Vanguard VXP 53 ft x 102 in T/A Van Trailer S/N: 5V8VC532XGM603142 C/W: Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until May 31, 2027 - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents - Lot closing time: Thu, Jul 23, 01:55 PM CDT Asset located in: Ste Agathe, MB, CAN
286	2018 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5328JBA00259 C/W: Located in Lane 6 Spot 24, Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 11R22.5 Tires, 70000 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Safety valid until July 31, 2026 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: June 25 - Additional information available, see supporting documents Lot closing time: Thu, Jul 23, 01:53 PM CDT Asset located in: Brandon, MB, CAN	290	2013 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532B5DL765398 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Pintle Hitch, Ducted Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:55 PM CDT Asset located in: Ste Agathe, MB, CAN
287	2017 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0622HD468928 C/W: Located in Lane 6 Spot 11, Aluminum /Steel Combination Frame, Air Ride Suspension, Hardwood Floor, Swing Door, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:54 PM CDT Asset located in: Brandon, MB, CAN	291	2009 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53239S109320 C/W: Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 11R22.5 Tires, 70000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting documents Lot closing time: Thu, Jul 23, 01:56 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
292	2008 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06228W703236 C/W: Aluminum/Steel Combination Frame, Sliding Suspension, Pintle Hitch, Ducted Floor, Swing Door, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:56 PM CDT Asset located in: Ste Agathe, MB, CAN	296	1999 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5322XS261523 C/W: Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 11R22.5 Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:58 PM CDT Asset located in: Ste Agathe, MB, CAN
293	2008 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA06258W703473 C/W: Aluminum/Steel Combination Frame, Air Ride Sliding Suspension, Pintle Hitch, Ducted Floor, Swing Door, 11R22.5 Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:57 PM CDT Asset located in: Ste Agathe, MB, CAN	297	1995 Fruehauf 53 ft x 102 in T/A Van Trailer S/N: 1H2V05328SE032904 C/W: Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 30845 kg GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:59 PM CDT Asset located in: Ste Agathe, MB, CAN
294	2001 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53201S419316 C/W: Air Ride Sliding Suspension, Hardwood Floor, Swing Door, 295/75R22.5 Tires 68000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:57 PM CDT Asset located in: Ste Agathe, MB, CAN	298	2/Axle Drawbar Tender Trailer S/N: Not Available C/W: Located in Lane 9 Spot 2, Lunette Ring Hitch, 15 ft 9 in Steel Box, 80 in, Side Walls, Manual Roll Tarp, 12.5L-15 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 01:59 PM CDT Asset located in: Brandon, MB, CAN
295	1999 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5326XS261511 C/W: Air Ride Suspension, Hardwood Floor, Swing Door, 11R22.5 Tires, 30836 kg GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 01:58 PM CDT Asset located in: Ste Agathe, MB, CAN	299	2021 Lode King 28 ft Tri/A Super B-Train Lead Hopper Grain Trailer S/N: 2LDAH283XMV069787 C/W: Air Ride Suspension, 2 Hoppers, Manual Traps, 28 ft Aluminum Box, 80 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 83775 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:00 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
301	2010 Doecker Legacy Super B-Train Grain Trailer S/N: 2DELBSA30A1026114 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Lift 1st- 3rd- Axles, 2 Hoppers, Manual Traps, 30 ft Aluminum Box, 76 in, Side Walls, Open Ended, Manual Roll Tarp, Air Scales, Aluminum Wheels, 11R24.5 Tires, 77200 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Safety valid until June 30, 2027 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:01 PM CDT Asset located in: Ste Agathe, MB, CAN	305	2012 Load Line 37 ft Tri/A End Dump Grain Trailer S/N: 2D9ED3726C1012002 C/W: Located in Lane 6 Spot 38, Air Ride Suspension, Lift 1st- 3rd- Axles, Manual Traps, 37 ft Steel Box, 62 in, Side Walls, Electric Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 92100 lb GVWR Usage: Not Available Notes: For more information, please contact Brandon Office PH: 204.441.1079 - MB Safety valid until January 1, 2027 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:03 PM CDT Asset located in: Brandon, MB, CAN
302	2012 Lode King 28 ft Super B-Train Lead Hopper Grain Trailer S/N: 2LDAH2832CV054165 C/W: Located in Lane 6 Spot 47, Aluminum Frame, Air Ride Suspension, 2 Hoppers, Manual Traps, 28 ft Aluminum Box, 80 in, Side Walls, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 38000 kg GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Safety valid until January 31, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:01 PM CDT Asset located in: Brandon, MB, CAN	306	2001 Doecker 40 ft Tri/A Grain Trailer S/N: 2DEGBSZ3511013011 C/W: Located in Lane 6 Spot 36, Air Ride Suspension, 3 Hoppers, Manual Traps, 40 ft Steel Box, 80 in, Side Walls, 11R24.5 Tires, 37500 kg GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title /Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:03 PM CDT Asset located in: Brandon, MB, CAN
304	1997 Lode King Super B-Train Grain Trailer S/N: 2LDHG2836VT028524 C/W: Located in Lane 6 Spot 48, Air Ride Suspension, 2 Hoppers, Manual Traps, 28 ft Steel Box, 77 in, Side Walls, Manual Roll Tarp, Air Scales, 11R24.5 Tires, 38000 kg GVWR Usage: Not Available Notes: SK Salvage VIN Status - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:02 PM CDT Asset located in: Brandon, MB, CAN	307	2001 Wilson 48 ft T/A Hopper Grain Trailer S/N: 1W1MCFYA21B234001 C/W: Air Ride Suspension, 2 Hoppers, Manual Traps, 48 ft Aluminum Box, 80 in, Side Walls, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - MB Safety valid until June 30, 2027 - MB Title/Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:04 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
308	2001 Wilson 42 ft T/A Grain Trailer S/N: 1W1MCFYA91B233010 C/W: Located in Lane 6 Spot 39, Aluminum /Steel Combination Frame, Air Ride Suspension, 2 Hoppers, Manual Traps, 41 ft Aluminum Box, 79 in, Side Walls, Air Scales, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Safety valid until June 30, 2027 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:04 PM CDT Asset located in: Brandon, MB, CAN	312	2002 Trailtech CT220PH 22 ft Sprayer Transport Trailer S/N: CUECE8N522010986 C/W: Located in Lane 6 Spot 43, Lunette Ring Hitch, Spring Suspension, Air Brakes, 255 /70R22.5 Tires, 46000 lb GVWR Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:06 PM CDT Asset located in: Brandon, MB, CAN
309	2002 Timppte Super Hopper 40 ft T/A Grain Trailer S/N: 1TDH400272B100354 C/W: Air Ride Suspension, Air Brakes, Manual Traps, 62 in, Side Walls, Manual Roll Tarp, Air Scales, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Safety valid until March 31, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:05 PM CDT Asset located in: Ste Agathe, MB, CAN	313	1998 Elmers 35 ft Windrower Transport Trailer S/N: 981485 C/W: 225/75R15 Tires Usage: Not Available Notes: For more information, please contact Scott Tilbury 204-522-5601 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 02:07 PM CDT Asset located in: Melita, MB, CAN
310	1998 Cancade 22 ft Tri/A Pup Grain Trailer S/N: 2C92322EXW1086339 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, Manual Traps, Steel Box, Manual Roll Tarp, 11R24.5 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Safety valid until July 31, 2027 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:05 PM CDT Asset located in: Brandon, MB, CAN	314	13 ft Windrower Transport Trailer S/N: Not Available C/W: Located in Lane 8 Spot 16, Ball Hitch, 235 /85R16 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:07 PM CDT Asset located in: Brandon, MB, CAN
311	2002 Norberts 20 ft T/A Livestock Trailer S/N: 2N9C7S7292G017069 C/W: Located in Lane 6 Spot 49, Divide Gates, 1 Decks, 235/80R16 Tires, 6347 lb GVWR Usage: Not Available Notes: Title/Registration in Transit - Cannot not leave the yard - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:06 PM CDT Asset located in: Brandon, MB, CAN	315	2003 J & M Mfg TB-6000H 44 ft Header Transport Trailer S/N: 1J9BB47343F297306 C/W: Torsion Axle, 235/85R16 Tires, 19200 lb GVWR Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:08 PM CDT Asset located in: Ste Agathe, MB, CAN
		316	Arc Fab 36 ft Header Transport Trailer S/N: 17505 C/W: 225/75R15 Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:08 PM CDT Asset located in: Ste Agathe, MB, CAN

Lot #	Details	Lot #	Details
317	2004 Elmers HT36 35 ft Header Transport Trailer S/N: 042563 Usage: Not Available Notes: Equipment from Schiewe Farms Ltd - For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:09 PM CDT Asset located in: Rosenfeld, MB, CAN	322	Yakta YXR720 Zero-Turn Lawn Mower (Unused) S/N: 199094 C/W: Located in Lane 11 Spot 25, Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, Yakta 72 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:15 PM CDT Asset located in: Brandon, MB, CAN
318	35 ft Drawbar Header Transport Trailer S/N: Not Available C/W: Lunette Ring Hitch, 225/75R15 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:09 PM CDT Asset located in: Brandon, MB, CAN	323	Yakta YXR710 Zero-Turn Lawn Mower (Unused) S/N: 198886 C/W: Located in Lane 11 Spot 24, Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, Yakta 72 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:15 PM CDT Asset located in: Brandon, MB, CAN
319	Golden Bell 21 ft Header Transport Trailer S/N: 1256 C/W: Located in Lane 8 Spot 15, 235/75R15 Tires Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:10 PM CDT Asset located in: Brandon, MB, CAN	324	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 197014 C/W: Located in Lane 11 Spot 24, Hydrostatic Drive, 2024 US EPA Label, 13x6.50-6/4.50 Front Tires, 24X12.00-12 Rear Tires, Yakta 54 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:15 PM CDT Asset located in: Brandon, MB, CAN
320	T/A (3) Reel Trailer S/N: 6708924 C/W: Lunette Ring Hitch, Torsion Axle, 235 /80R16 Tires Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - MB Title/Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:10 PM CDT Asset located in: Ste Agathe, MB, CAN	325	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 197058 C/W: Located in Lane 11 Spot 23, Hydrostatic Drive, 2024 US EPA Label, 13X6.5-6/4.5 Front Tires, 24X12.00-12 Rear Tires, Yakta 54 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:15 PM CDT Asset located in: Brandon, MB, CAN
321	2012 Rainbow Summit 11 ft x 8 ft 1 Person S /A Washcar S/N: 2RNBC1017C1000461 C/W: Self Contained, (2) Bathrooms, Ball Hitch, Torsion Axle, 205/75R15 Tires, 2990 lb GVWR Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - MB Safety valid until July 31, 2026 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 02:11 PM CDT Asset located in: Brandon, MB, CAN	326	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 198386 C/W: Located in Lane 11 Spot 23, Hydrostatic Drive, 2024 US EPA Label, 13X6.50-6/4.50 Front Tires, 24X12.00-12 Rear Tires, Yakta 54 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:16 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
327	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 197152 C/W: Located in Lane 11 Spot 23, Hydrostatic Drive, 2024 US EPA Label, 13X6.50-6/4.50 Front Tires, 24X12.00-12 Rear Tires, Yakta 54 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:16 PM CDT Asset located in: Brandon, MB, CAN	332	2025 Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 197057 C/W: Located in Lane 11 Spot 24, Hydrostatic Drive, 2024 US EPA Label, 13x6.50-6/4.5 Front Tires, 240/65-12 Rear Tires, Yakta 48 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:17 PM CDT Asset located in: Brandon, MB, CAN
328	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 199253 C/W: Located in Lane 11 Spot 23, Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, Yakta 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:16 PM CDT Asset located in: Brandon, MB, CAN	333	2025 Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 197077 C/W: Located in Lane 11 Spot 24, Hydrostatic Drive, 2024 US EPA Label, 13x6.50-6/4.50 Front Tires, 24x12.00-12 Rear Tires, Yakta 54 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:17 PM CDT Asset located in: Brandon, MB, CAN
329	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 199215 C/W: Located in Lane 11 Spot 22, Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, Yakta 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:16 PM CDT Asset located in: Brandon, MB, CAN	334	Yakta YFR 410 Zero-Turn Lawn Mower (Unused) S/N: 197011 C/W: Located in Lane 11 Spot 22, Hydrostatic Drive, 2024 US EPA Label, 13X6.50-6/4.50 Front Tires, 22X11.00-10 Rear Tires, Yakta 61 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:18 PM CDT Asset located in: Brandon, MB, CAN
330	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 199212 C/W: Located in Lane 11 Spot 22, Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, Yakta 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:17 PM CDT Asset located in: Brandon, MB, CAN	335	Yakta YFR 410 Zero-Turn Lawn Mower (Unused) S/N: 197140 C/W: Located in Lane 11 Spot 21, Hydrostatic Drive, 2024 US EPA Label, 13X6.50-6/4.50 Front Tires, 22x11.00-10 Rear Tires, Yakta 54 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:18 PM CDT Asset located in: Brandon, MB, CAN
331	Yakta YFR 610 Zero-Turn Lawn Mower (Unused) S/N: 198163 C/W: Located in Lane 11 Spot 22, Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, Yakta 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:17 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
336	Yakta YFR 410 Zero-Turn Lawn Mower (Unused) S/N: 197019 C/W: Located in Lane 11 Spot 21, 2024 US EPA Label, 13X6.50-6/4.50 Front Tires, 22X11.00-10 Rear Tires, Yakta 61 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:18 PM CDT Asset located in: Brandon, MB, CAN	341	Yakta YXR320 Zero-Turn Lawn Mower (Unused) S/N: 199083 C/W: Located in Lane 11 Spot 20, Hydrostatic Drive, 13.5x6.5 Front Tires, 23x10.5 Rear Tires, Yakta 48 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:19 PM CDT Asset located in: Brandon, MB, CAN
337	Yakta YFR 410 Zero-Turn Lawn Mower (Unused) S/N: 197136 C/W: Located in Lane 11 Spot 21, Hydrostatic Drive, 2024 US EPA Label, 13X6.50-6/4.50 Front Tires, 22X11.00-10 Rear Tires, Yakta 61 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:18 PM CDT Asset located in: Brandon, MB, CAN	342	Yakta YXR320 Zero-Turn Lawn Mower (Unused) S/N: 198906 C/W: Located in Lane 11 Spot 20, Hydrostatic Drive, 13.5x6.5 Front Tires, 23x10.5 Rear Tires, Yakta 48 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:20 PM CDT Asset located in: Brandon, MB, CAN
338	Yakta YFR 410 Zero-Turn Lawn Mower (Unused) S/N: 197137 C/W: Located in Lane 11 Spot 21, Hydrostatic Drive, 2024 US EPA Label, 13X6.50-6/4.50 Front Tires, 22X11.00-10 Rear Tires, Yakta 61 in Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:19 PM CDT Asset located in: Brandon, MB, CAN	343	Yakta YXR320 Zero-Turn Lawn Mower (Unused) S/N: 198907 C/W: Located in Lane 11 Spot 19, Hydrostatic Drive, 13x6.5 Front Tires, 23x10.5 Rear Tires, Yakta 48 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:20 PM CDT Asset located in: Brandon, MB, CAN
339	Yakta YXR320 Zero-Turn Lawn Mower (Unused) S/N: 198706 C/W: Located in Lane 11 Spot 20, Hydrostatic Drive, 13x6.5 Front Tires, 23x10.5 Rear Tires, Yakta 48 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:19 PM CDT Asset located in: Brandon, MB, CAN	344	Yakta YXR320 Zero-Turn Lawn Mower (Unused) S/N: 198827 C/W: Located in Lane 11 Spot 19, Hydrostatic Drive, 13.5x6.5 Front Tires, 23x10.5 Rear Tires, 48 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:20 PM CDT Asset located in: Brandon, MB, CAN
340	Yakta YXR320 Zero-Turn Lawn Mower (Unused) S/N: 198888 C/W: Located in Lane 11 Spot 20, Hydrostatic Drive, 13x6.5 Front Tires, 23x10.5 Rear Tires, Yakta 48 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:19 PM CDT Asset located in: Brandon, MB, CAN	345	Yakta YXR320 Zero-Turn Lawn Mower (Unused) S/N: 198925 C/W: Located in Lane 11 Spot 27, Hydrostatic Drive, 13.5x6.5 Front Tires, 23x10.5 Rear Tires, Yakta 48 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:20 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
346	Yakta Y FF YXR120 Zero-Turn Lawn Mower (Unused) S/N: 197888 C/W: Located in Lane 11 Spot 19, Hydrostatic Drive, 13.5x6.5 Front Tires, 22x11 Rear Tires, Yakta 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:21 PM CDT Asset located in: Brandon, MB, CAN	351	2026 SDLOOL SL-LM1000Q 40 in Remote Control Flail Mower (Unused) S/N: 1000QYGCJ260597 C/W: Located in Lane 11 Spot 17, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:22 PM CDT Asset located in: Brandon, MB, CAN
347	Yakta Y FF YXR120 Zero-Turn Lawn Mower (Unused) S/N: 198767 C/W: Located in Lane 11 Spot 18, Hydrostatic Drive, 13.5x6.5 Front Tires, 22x11 Rear Tires, Yakta 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:21 PM CDT Asset located in: Brandon, MB, CAN	352	2026 SDLOOL SL800 Remote Control Lawn Mower (Unused) S/N: 800YS2605183 C/W: Located in Lane 11 Spot 17, 22 in Mower, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:22 PM CDT Asset located in: Brandon, MB, CAN
348	Yakta YXR120 Zero-Turn Lawn Mower (Unused) S/N: 198791 C/W: Located in Lane 11 Spot 18, Hydrostatic Drive, 13.5x6.5 Front Tires, 22x11 Rear Tires, Yakta 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:21 PM CDT Asset located in: Brandon, MB, CAN	353	2026 SDLOOL SL800 Remote Control Lawn Mower (Unused) S/N: 800YS2605184 C/W: Located in Lane 11 Spot 17, 22 in Mower, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:22 PM CDT Asset located in: Brandon, MB, CAN
349	Yakta YXR120 Zero-Turn Lawn Mower (Unused) S/N: 198792 C/W: Located in Lane 11 Spot 18, Hydrostatic Drive, 13.5x6.5 Front Tires, 22x11 Rear Tires, 54 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:21 PM CDT Asset located in: Brandon, MB, CAN	354	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: E88648 C/W: Located in Lane 11 Spot 16, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:23 PM CDT Asset located in: Brandon, MB, CAN
350	Yakta YXR120 Zero-Turn Lawn Mower (Unused) S/N: 198824 C/W: Located in Lane 11 Spot 18, Hydrostatic Drive, 13.6x6.5 Front Tires, 22x11 Rear Tires, Yakta 61 in Front Mower Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:22 PM CDT Asset located in: Brandon, MB, CAN	355	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: E88649 C/W: Located in Lane 11 Spot 16, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:23 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
356	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: E96929 C/W: Located in Lane 11 Spot 16, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:23 PM CDT Asset located in: Brandon, MB, CAN	361	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S260588 C/W: Located in Lane 11 Spot 15, Battery Charger, 4 Passenger, Canopy, Windshield, 60 Volt, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:24 PM CDT Asset located in: Brandon, MB, CAN
357	2026 SKLP SK-E48 Electric Scooter (Unused) S/N: E96928 C/W: Located in Lane 11 Spot 16, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:23 PM CDT Asset located in: Brandon, MB, CAN	362	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S260584 C/W: Located in Lane 11 Spot 14, Battery Charger, 4 Passenger, Canopy, Windshield, 60 Volt, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:25 PM CDT Asset located in: Brandon, MB, CAN
358	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260598 C/W: Located in Lane 11 Spot 15, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:24 PM CDT Asset located in: Brandon, MB, CAN	363	2026 SDLOOL SL-GC22S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF22S260585 C/W: Located in Lane 11 Spot 14, Battery Charger, 4 Passenger, Canopy, Windshield, 60 Volt, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:25 PM CDT Asset located in: Brandon, MB, CAN
359	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260599 C/W: Located in Lane 11 Spot 15, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:24 PM CDT Asset located in: Brandon, MB, CAN	364	2026 SDLOOL SL-M1300 Stand-On Mini Dumper (Unused) S/N: LSFD2604103 C/W: Located in Lane 11 Spot 14, Hydrostatic Drive, 2026 US EPA Label, 420 cc Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:25 PM CDT Asset located in: Brandon, MB, CAN
360	2026 SDLOOL SL-GC42S Electric Off-Road Golf Cart (Unused) S/N: JK-YYGEF42S260583 C/W: Located in Lane 11 Spot 15, Battery Charger, 6 Passenger, Canopy, Windshield, 60 Volt ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:24 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
365	2026 SDLOOL SL-M1300 Stand-On Mini Dumper (Unused) S/N: LSFD2604102 C/W: Located in Lane 11 Spot 13, Hydrostatic Drive, 2026 US EPA Label, 420 cc Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:25 PM CDT Asset located in: Brandon, MB, CAN	369	2026 SDLOOL SL-323TZ Skid Steer Loader (Unused) S/N: 323TZ260317 C/W: Located in Lane 11 Spot 11, Open Operator Station, Joystick Steering, 2026 US EPA Label, Manual Quick Coupler, 42 in Bucket Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:26 PM CDT Asset located in: Brandon, MB, CAN
366	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2604117 C/W: Located in Lane 11 Spot 13, Open Operator Station, 2025 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 38 in Bucket, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:26 PM CDT Asset located in: Brandon, MB, CAN	370	2026 CFG MH12RX Mini Excavator (Unused) S/N: 217K26 C/W: 2025 US EPA Label, 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, Manual Quick Coupler, 14 in Digging Bucket, Manual Thumb Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:27 PM CDT Asset located in: Brandon, MB, CAN
367	2026 SDLOOL SL36C Mini Compact Track Loader (Unused) S/N: 36CJ2604118 C/W: Located in Lane 11 Spot 12, Open Operator Station, Joystick Steering, 2025 US EPA Label, 6 in Track Belts, Manual Quick Coupler, 38 in Bucket, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:26 PM CDT Asset located in: Brandon, MB, CAN	371	2026 CFG MH12RX Mini Excavator (Unused) S/N: 217K27 C/W: 2025 US EPA Label, 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, Manual Quick Coupler, 14 in Digging Bucket, Manual Thumb Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:27 PM CDT Asset located in: Brandon, MB, CAN
368	2026 SDLOOL SL360T Skid Steer Loader (Unused) S/N: 360TJ2604187 C/W: Located in Lane 11 Spot 12, Open Operator Station, Joystick Steering, 2026 US EPA Label, Manual Quick Coupler, 42 in Bucket Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:26 PM CDT Asset located in: Brandon, MB, CAN	372	2026 CFG H15R Mini Excavator (Unused) S/N: 181822 C/W: 2025 US EPA Label, 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, Manual Quick Coupler, 14 in Digging Bucket, Manual Thumb Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:27 PM CDT Asset located in: Brandon, MB, CAN
		373	2026 CFG H15R Mini Excavator (Unused) S/N: 181818 C/W: 2025 US EPA Label, 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:27 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
374	2026 CFG H15R Mini Excavator (Unused) S/N: 181824 C/W: 2025 US EPA Label, 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:28 PM CDT Asset located in: Brandon, MB, CAN	380	Quantity of (3) Pallets of Chairs and Tables S/N: Not Available C/W: 60 Folding Chairs, 4 Plastic Chairs & 8 Tables. Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:29 PM CDT Asset located in: Brandon, MB, CAN
375	2026 CFG H15R Mini Excavator (Unused) S/N: 181815 C/W: 2025 US EPA Label, 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:28 PM CDT Asset located in: Brandon, MB, CAN	381	Quantity of Miscellaneous Batteries and Battery Tools S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:29 PM CDT Asset located in: Brandon, MB, CAN
376	John Deere ITC GNSS Receiver S/N: CGT01C324453 C/W: John Deere GreenStar Display Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:28 PM CDT Asset located in: Brandon, MB, CAN	382	Quantity of (3) Boxes of Glass for Buses (Unused) S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:30 PM CDT Asset located in: Brandon, MB, CAN
377	2026 SKLP Laser Level (Unused) S/N: E85240 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:28 PM CDT Asset located in: Brandon, MB, CAN	383	Techsew 2900L Sewing Machine S/N: 18C4139 Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:30 PM CDT Asset located in: Brandon, MB, CAN
378	2026 SKLP Laser Level (Unused) S/N: E85239 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:29 PM CDT Asset located in: Brandon, MB, CAN	384	Quantity of (2) Weatherhead Hydraulic Hose Crimpers S/N: Not Available C/W: T400 Bench Model, T460 Portable Model, C/W U-series Dies, Brand New Set of Z-Series Dies, Cabinet with Assorted Z-series Crimp Fittings, and Boxes of Extra Fittings Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:30 PM CDT Asset located in: Brandon, MB, CAN
379	Quantity of (4) Pallets of Assorted Varieties And Sizes Of Fabric Used As Seat Coverings S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:29 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
385	Quantity of Miscellaneous Hand Tools S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:30 PM CDT Asset located in: Brandon, MB, CAN	390	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-3074 C/W: Quick Coupler, Rake, Grabber, (1) 8 in Bucket, (1) 32 in Bucket, Auger w/ (1) 8 in & (1) 12 in Bit, Ripper ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:32 PM CDT Asset located in: Brandon, MB, CAN
386	Quantity of Electronics S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:31 PM CDT Asset located in: Brandon, MB, CAN	391	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-3082 C/W: Quick Coupler, Rake, Grabber, (1) 8 in Bucket, (1) 32 in Bucket, Auger w/ (1) 8 in & (1) 12 in Bit, Ripper ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:32 PM CDT Asset located in: Brandon, MB, CAN
387	Quantity of (2) Boxes of REI DVD Player (Unused) S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:31 PM CDT Asset located in: Brandon, MB, CAN	392	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-3083 C/W: Quick Coupler, Rake, Grabber, (1) 8 in Bucket, (1) 32 in Bucket, Auger w/ (1) 8 in & (1) 12 in Bit, Ripper ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:32 PM CDT Asset located in: Brandon, MB, CAN
388	REI 710213 19 in Flip Screen Monitor (Unused) S/N: 6112300030 C/W: remote Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:31 PM CDT Asset located in: Brandon, MB, CAN	393	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-3086 C/W: Quick Coupler, Rake, Grabber, (1) 8 in Bucket, (1) 32 in Bucket, Auger w/ (1) 8 in & (1) 12 in Bit, Ripper ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:32 PM CDT Asset located in: Brandon, MB, CAN
389	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-3075 C/W: Quick Coupler, Rake, Grabber, (1) 8 in Bucket, (1) 32 in Bucket, Auger w/ (1) 8 in & (1) 12 in Bit, Ripper ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:31 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
394	Quantity of (8) 2026 VICSEC VCA-8 Mini Excavator Attachments (Unused) S/N: C-10SJB-2860 C/W: Quick Coupler, Rake, Grabber, (1) 8 in Bucket, (1) 32 in Bucket, Auger w/ (1) 8 in & (1) 12 in Bit, Ripper ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:33 PM CDT Asset located in: Brandon, MB, CAN	399	2026 GIYI GY-SA Skid Steer Auger (Unused) S/N: C-SMLXZ-703 C/W: (1) 8 in, (1) 12 in & (1) 16 in Auger Bits ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:34 PM CDT Asset located in: Brandon, MB, CAN
395	Quantity of (8) 2026 GIYI Cat 301 GYA-8 Mini Excavator Attachment (Unused) S/N: C-301SJB-1151 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:33 PM CDT Asset located in: Brandon, MB, CAN	400	2026 GIYI Excavator Auger - Fits Cat 303 (Unused) S/N: B-303TJLXZ-242 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:34 PM CDT Asset located in: Brandon, MB, CAN
396	Quantity of (8) 2026 GIYI Cat 301 GYA-8 Mini Excavator Attachment (Unused) S/N: C-301SJB-1086 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:33 PM CDT Asset located in: Brandon, MB, CAN	401	2026 GIYI Excavator Auger - Fits Cat 303 (Unused) S/N: B-303TZLXZ-241 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:34 PM CDT Asset located in: Brandon, MB, CAN
397	2026 GIYI GY-SA Skid Steer Auger (Unused) S/N: C-SMLXZ-701 C/W: (1) 8 in, (1) 12 in & (1) 16 in Auger Bits ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:33 PM CDT Asset located in: Brandon, MB, CAN	402	2026 GIYI Excavator Auger - Fits Cat 303 (Unused) S/N: B-303TZLXZ-245 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:35 PM CDT Asset located in: Brandon, MB, CAN
398	2026 GIYI GY-SA Skid Steer Auger (Unused) S/N: C-SMLXZ-704 C/W: (1) 8 in, (1) 12 in & (1) 16 in Auger Bits ; Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:34 PM CDT Asset located in: Brandon, MB, CAN	403	2026 GIYI Excavator Ripper (Unused) S/N: C-305STQ-659 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:35 PM CDT Asset located in: Brandon, MB, CAN
		404	Cat 50 in Excavator Ripper - Fits Komatsu PC200LC-8 S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: June 25 - Lot closing time: Thu, Jul 23, 02:35 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
405	2026 GIYI Excavator Rake - Fits Cat 305 (Unused) S/N: C-305MCPZ44-572 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:35 PM CDT Asset located in: Brandon, MB, CAN	411	2026 GIYI GY-ML45 32 in Mini Skid Steer Mulcher (Unused) S/N: X-THJ260497 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:37 PM CDT Asset located in: Brandon, MB, CAN
406	2026 GIYI 32 in Excavator Rake - Fits Cat 305 (Unused) S/N: C-305PZ32-663 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:36 PM CDT Asset located in: Brandon, MB, CAN	412	2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2604538 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:37 PM CDT Asset located in: Brandon, MB, CAN
407	2026 GIYI GY-BK 24 in Digging Excavator Bucket (Unused) S/N: C-305WD24-656 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:36 PM CDT Asset located in: Brandon, MB, CAN	413	2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2604541 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:37 PM CDT Asset located in: Brandon, MB, CAN
408	2026 GIYI GY-BK 12 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: C-305WD12-703 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:36 PM CDT Asset located in: Brandon, MB, CAN	414	2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2604390 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:38 PM CDT Asset located in: Brandon, MB, CAN
409	2026 GIYI GY-EDM320 39 in Excavator Disc Mulcher - Fits Cat 320 (Unused) S/N: 320YPTHJ260437 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:36 PM CDT Asset located in: Brandon, MB, CAN	415	2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2604389 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:38 PM CDT Asset located in: Brandon, MB, CAN
410	2026 GIYI GY-MDM50 33 in Mini Skid Steer Mulcher (Unused) S/N: X YPTHJ260423 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:37 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
416	2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2604540 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:38 PM CDT Asset located in: Brandon, MB, CAN	421	2026 GIYI GY-RB66 66 in Rock Skid Steer Bucket (Unused) S/N: C-D YSCD2604194 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:39 PM CDT Asset located in: Brandon, MB, CAN
417	2026 GIYI GY-DHC 59 in Skid Steer Forks (Unused) S/N: DHC2604539 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:38 PM CDT Asset located in: Brandon, MB, CAN	422	2026 GIYI GY-RB66 66 in Rock Skid Steer Bucket (Unused) S/N: C-D YSCD2604197 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:40 PM CDT Asset located in: Brandon, MB, CAN
418	Quantity of (5) 2026 Mower King SA-100 48 in Heavy Duty Skid Steer Forks (Unused) S/N: SA-10026032302A C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:39 PM CDT Asset located in: Brandon, MB, CAN	423	2026 AGT STSD10 45 in 3-Point & Skid Steer Seeder (Unused) S/N: STSD10260106838 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:40 PM CDT Asset located in: Brandon, MB, CAN
419	2026 GIYI GY-BF47 47 in Skid Steer Bale Spear (Unused) S/N: C-YKEC2605014 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:39 PM CDT Asset located in: Brandon, MB, CAN	424	2026 GIYI GY-SF60 60 in Skid Steer Forks (Unused) S/N: DCYHC2604275 C/W: Fork Positioner, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:40 PM CDT Asset located in: Brandon, MB, CAN
420	2026 GIYI GY-BF47 47 in Skid Steer Bale Spear (Unused) S/N: C-YKEC2605013 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:39 PM CDT Asset located in: Brandon, MB, CAN	425	2026 GIYI GY-SF60 60 in Skid Steer Forks (Unused) S/N: DCYHC2604276 C/W: Fork Positioner, Product images displayed are stock photos. Item is new /unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:40 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
426	2026 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 69032512 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Product images displayed are stock photos. Item is new /unused. Lot closing time: Thu, Jul 23, 02:41 PM CDT Asset located in: Brandon, MB, CAN	432	2026 GIYI GY-RP72 72 in Skid Steer Rock Picker (Unused) S/N: DSSJ260425 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:42 PM CDT Asset located in: Brandon, MB, CAN
427	2026 GIYI GY-CLG72 72 in Log Skid Steer Grapple (Unused) S/N: C-HXZMQ2604265 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:41 PM CDT Asset located in: Brandon, MB, CAN	433	2026 Suihe SSD-V 72 in Skid Steer Snow Blade (Unused) S/N: 69032511 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Product images displayed are stock photos. Item is new /unused. Lot closing time: Thu, Jul 23, 02:42 PM CDT Asset located in: Brandon, MB, CAN
428	2026 GIYI GY-CLG72 72 in Log Skid Steer Grapple (Unused) S/N: C-HXZMQ2604264 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:41 PM CDT Asset located in: Brandon, MB, CAN	434	2026 Suihe SSD-A 72 in Angle Skid Steer Dozer (Unused) S/N: 015100162 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Applicable taxes will apply - Item removal deadline: August 7- Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 02:43 PM CDT Asset located in: Brandon, MB, CAN
429	2026 GIYI GY-HWG72 72 in Log Skid Steer Grapple (Unused) S/N: C-XXLKZMQ2604115 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:41 PM CDT Asset located in: Brandon, MB, CAN	435	2026 Mower King SPA84 84 in 4-Way Skid Steer Dozer (Unused) S/N: SPA8426032301B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:43 PM CDT Asset located in: Brandon, MB, CAN
430	2026 Suihe SSRGB-72 72 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: 001403759 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Product images displayed are stock photos. Item is new /unused. Lot closing time: Thu, Jul 23, 02:42 PM CDT Asset located in: Brandon, MB, CAN	436	2026 Top Cat SSSCR72 72 in Skid Steer Power Rake (Unused) S/N: SSSCR7226032302A C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:43 PM CDT Asset located in: Brandon, MB, CAN
431	2026 GIYI GY-VB79 79 in Vibrating Skid Steer Screening Bucket (Unused) S/N: D-ZDD260483 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:42 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
437	2026 GIYI GY-BD98 47 in Skid Steer Backhoe (Unused) S/N: DFCXW250417 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:43 PM CDT Asset located in: Brandon, MB, CAN	442	2026 GIYI GY-AD680 Skid Steer Post Driver (Unused) S/N: ADZC6802604157 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:45 PM CDT Asset located in: Brandon, MB, CAN
438	2026 GIYI GY-P680 Skid Steer Breaker (Unused) S/N: PSC680260393 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:44 PM CDT Asset located in: Brandon, MB, CAN	443	2026 GIYI GY-D680 Skid Steer Post Driver (Unused) S/N: DZC680260392 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:45 PM CDT Asset located in: Brandon, MB, CAN
439	2026 GIYI GY-P680 Skid Steer Breaker (Unused) S/N: PSC680260392 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:44 PM CDT Asset located in: Brandon, MB, CAN	444	2026 GIYI GY-D680 Skid Steer Post Driver (Unused) S/N: DZC680260393 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:45 PM CDT Asset located in: Brandon, MB, CAN
440	2026 GIYI GY-AD680 Skid Steer Post Driver (Unused) S/N: ADZC6802604159 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:44 PM CDT Asset located in: Brandon, MB, CAN	445	2026 GIYI GY-TMP45 Skid Steer Attachment Mounting Plate (Unused) S/N: D CXAZB260419 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:45 PM CDT Asset located in: Brandon, MB, CAN
441	2026 GIYI GY-AD680 Skid Steer Post Driver (Unused) S/N: ADZC6802604158 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:44 PM CDT Asset located in: Brandon, MB, CAN	446	2026 GIYI GY-FB77 Skid Steer Feller Buncher (Unused) S/N: FMGDJ2604106 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:46 PM CDT Asset located in: Brandon, MB, CAN
		447	2026 GIYI GY-FB77 32 in Skid Steer Feller Buncher (Unused) S/N: FMGDJ260576 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:46 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
448	2026 GIYI GY-TP45 Skid Steer Post Puller (Unused) S/N: HS-LBQ260450 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:46 PM CDT Asset located in: Brandon, MB, CAN	454	2026 GIYI GY-HLS82 25 in Skid Steer Log Splitter (Unused) S/N: DJYPMQ260456 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:48 PM CDT Asset located in: Brandon, MB, CAN
449	Skid steer Bale Grabber S/N: 225738 C/W: 2500 lb Capacity Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:46 PM CDT Asset located in: Brandon, MB, CAN	455	2026 GIYI GY-SS52 45 in Skid Steer Salt Spreader (Unused) S/N: D SYJ260501 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:48 PM CDT Asset located in: Brandon, MB, CAN
450	2026 GIYI GY-CW70 45 in Skid Steer Compaction Wheel (Unused) S/N: KTYSL260444 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:47 PM CDT Asset located in: Brandon, MB, CAN	456	2026 GIYI GY-BSG45 Skid Steer Stump Grinder (Unused) S/N: D-SZYMJ2603133 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:48 PM CDT Asset located in: Brandon, MB, CAN
451	2026 Mower King ECSSCT72 60 in Skid Steer Trencher (Unused) S/N: ECSSCT7226032302A C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:47 PM CDT Asset located in: Brandon, MB, CAN	457	2026 GIYI GY-SG45 Skid Steer Stump Grinder (Unused) S/N: D-SZYMJ260492 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:48 PM CDT Asset located in: Brandon, MB, CAN
452	2026 GIYI GY-HLS82 25 in Skid Steer Log Splitter (Unused) S/N: DJYPMQ260455 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:47 PM CDT Asset located in: Brandon, MB, CAN	458	2026 GIYI GY-BSG45 Skid Steer Stump Grinder (Unused) S/N: D-SZYMJ2603134 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:49 PM CDT Asset located in: Brandon, MB, CAN
453	2026 GIYI GY-HLS82 25 in Skid Steer Log Splitter (Unused) S/N: DJYPMQ260450 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:47 PM CDT Asset located in: Brandon, MB, CAN	459	2026 Mower King ECSSTR072 72 in Skid Steer Tiller (Unused) S/N: ECSSTR07226032303B C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:49 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
460	2026 AGT SSDH72 72 in Skid Steer Disc Harrow (Unused) S/N: SSDH7226032301A C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:49 PM CDT Asset located in: Brandon, MB, CAN	465	2026 GIYI GY-X DM43 43 in Disc Skid Steer Mulcher (Unused) S/N: XYPTHJ2604232 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:50 PM CDT Asset located in: Brandon, MB, CAN
461	2026 Suihe SSFM Skid Steer Mulcher (Unused) S/N: 69032512 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Product images displayed are stock photos. Item is new /unused. Lot closing time: Thu, Jul 23, 02:49 PM CDT Asset located in: Brandon, MB, CAN	466	2026 GIYI GYx-DM43 43 in Disc Skid Steer Mulcher (Unused) S/N: XYPTHJ2604233 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:51 PM CDT Asset located in: Brandon, MB, CAN
462	2026 Mower King SSAB72 72 in Skid Steer Broom (Unused) S/N: SSAB7226032301A C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:50 PM CDT Asset located in: Brandon, MB, CAN	467	2026 GIYI GY-X DM43 43 in Disc Skid Steer Mulcher (Unused) S/N: XYPTHJ2604231 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:51 PM CDT Asset located in: Brandon, MB, CAN
463	2026 AGT SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y26032304B C/W: (1) 6 in, (1) 12 in & (1) 14 in Auger Bits, Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:50 PM CDT Asset located in: Brandon, MB, CAN	468	2026 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC26032304B Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:51 PM CDT Asset located in: Brandon, MB, CAN
464	2026 Suihe SSA 42 in Skid Steer Auger (Unused) S/N: 69032512 C/W: (1) 9 in, (1) 12 in & (1) 18 in Auger Bits Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Product images displayed are stock photos. Item is new /unused. Lot closing time: Thu, Jul 23, 02:50 PM CDT Asset located in: Brandon, MB, CAN	469	54 in Bucket S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:51 PM CDT Asset located in: Brandon, MB, CAN
		470	65 in Bucket S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:52 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
471	2026 PROMECH FW80 Fifth Wheel Wrecker Attachment (Unused) S/N: FWWA26157 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:52 PM CDT Asset located in: Brandon, MB, CAN	476	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 262533 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:53 PM CDT Asset located in: Brandon, MB, CAN
472	2026 PROMECH FW80 Fifth Wheel Wrecker Attachment (Unused) S/N: FWWA26159 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:52 PM CDT Asset located in: Brandon, MB, CAN	477	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 262537 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:53 PM CDT Asset located in: Brandon, MB, CAN
473	2026 GIYI GY-TE780 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC2605154 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:52 PM CDT Asset located in: Brandon, MB, CAN	478	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 262534 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:54 PM CDT Asset located in: Brandon, MB, CAN
474	2026 GIYI GY-TE780 Fifth Wheel Wrecker Attachment (Unused) S/N: KCTC2605155 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:53 PM CDT Asset located in: Brandon, MB, CAN	479	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 262531 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:54 PM CDT Asset located in: Brandon, MB, CAN
475	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 262535 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:53 PM CDT Asset located in: Brandon, MB, CAN	480	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 262532 C/W: 4000 psi Rating, Water Heater, Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:54 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
481	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 262536 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Gasoline Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:54 PM CDT Asset located in: Brandon, MB, CAN	486	2026 SKLP SK-SYLJ100 Hand-Use Hydraulic Track Pin Press Machine (Unused) S/N: SDYLJ1002604164 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:56 PM CDT Asset located in: Brandon, MB, CAN
482	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: F02149 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:55 PM CDT Asset located in: Brandon, MB, CAN	487	2026 SKLP SK-YLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: YLJ100260467 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:56 PM CDT Asset located in: Brandon, MB, CAN
483	2026 SKLP SK-HJ6 Metal Storage Shelving (Unused) S/N: F02150 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: Shipping damage - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:55 PM CDT Asset located in: Brandon, MB, CAN	488	2026 SKLP SK-YLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: YLJ100260571 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:56 PM CDT Asset located in: Brandon, MB, CAN
484	Quantity of (12) 2026 BYT FLOJK035 3.5 t Floor Jack (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:55 PM CDT Asset located in: Brandon, MB, CAN	489	2026 SKLP SK-YLJ100 Hydraulic Track Pin Press Machine (Unused) S/N: YLJ100260562 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:56 PM CDT Asset located in: Brandon, MB, CAN
485	Quantity of (12) 2026 BYT FLOJK035 3.5 t Floor Jack (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:55 PM CDT Asset located in: Brandon, MB, CAN	490	Quantity of (2) 2026 BYT BDF412 4 ft x 12 ft Aluminum Boat Dock Section Kit (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:57 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
491	Quantity of (2) 2026 BYT BDF412 4 ft x 12 ft Aluminum Boat Dock Section Kit (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:57 PM CDT Asset located in: Brandon, MB, CAN	497	2026 SKLP SK-ZP20 20 ft x 30 ft Carport (Unused) S/N: F02147 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:58 PM CDT Asset located in: Brandon, MB, CAN
492	Quantity of (2) 2026 BYT BDF412 4 ft x 12 ft Aluminum Boat Dock Section Kit (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:57 PM CDT Asset located in: Brandon, MB, CAN	498	2026 SKLP SK-ZP20 20 ft x 30 ft Carport (Unused) S/N: F02146 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:59 PM CDT Asset located in: Brandon, MB, CAN
493	Quantity of (2) 2026 BYT BDF412 4 ft x 12 ft Aluminum Boat Dock Section Kit (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:57 PM CDT Asset located in: Brandon, MB, CAN	499	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F02148 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:59 PM CDT Asset located in: Brandon, MB, CAN
494	Quantity of (2) 2026 BYT BDF412 4 ft x 12 ft Aluminum Boat Dock Section Kit (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:58 PM CDT Asset located in: Brandon, MB, CAN	500	2026 SKLP SK-SC40 20 ft x 40 ft Carport (Unused) S/N: F02153 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:59 PM CDT Asset located in: Brandon, MB, CAN
495	Quantity of (2) 2026 BYT BDF6 6 ft x 8 ft Aluminum Boat Dock Section Kit (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:58 PM CDT Asset located in: Brandon, MB, CAN	501	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F02160 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:59 PM CDT Asset located in: Brandon, MB, CAN
496	Quantity of (3) 2026 BYT BDF6 6 ft x 8 ft Aluminum Boat Dock Section Kit (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 02:58 PM CDT Asset located in: Brandon, MB, CAN	502	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: F02159 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:00 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
503	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: E88522 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:00 PM CDT Asset located in: Brandon, MB, CAN	508	Quantity of (50) 2026 SKLP SK-XH50 9 ft 10 in Galvalume Steel Sheets (Unused) S/N: F02151 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:01 PM CDT Asset located in: Brandon, MB, CAN
504	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: E88523 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:00 PM CDT Asset located in: Brandon, MB, CAN	509	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Sheets (Unused) S/N: F02157 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:01 PM CDT Asset located in: Brandon, MB, CAN
505	Quantity of (12) 2026 SKLP SK-LJB12 94 in x 47 in Polyethylene Traffic Plates (Unused) S/N: E88525 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:00 PM CDT Asset located in: Brandon, MB, CAN	510	2026 SKLP SKH50 12 ft Galvalume Sheets (Unused) S/N: F02158 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:02 PM CDT Asset located in: Brandon, MB, CAN
506	Quantity of (50) 2026 SKLP SK-XH50 9 ft 10 in Galvalume Steel Sheets (Unused) S/N: F02152 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:01 PM CDT Asset located in: Brandon, MB, CAN	511	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Sheets (Unused) S/N: F02156 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:02 PM CDT Asset located in: Brandon, MB, CAN
507	Quantity of (50) 2026 SKLP SKL50 9 ft 10 in Galvalume Steel Sheets (Unused) S/N: F02151 C/W: Product images displayed are stock photos. Item is new/unused. Usage: Not Available Notes: Shipping damage - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:01 PM CDT Asset located in: Brandon, MB, CAN	512	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Sheets (Unused) S/N: F02157 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:02 PM CDT Asset located in: Brandon, MB, CAN
		513	Quantity of (50) 2026 SKLP SKH50 12 ft Galvalume Sheets (Unused) S/N: F02156 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:02 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
514	2026 SKLP 5 ft x 9 ft 10 in (0.4 in Thick) Steel Plates (Unused) S/N: E91475 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:03 PM CDT Asset located in: Brandon, MB, CAN	522	Quantity of (50) 5/8 in x 4 ft x 8 ft CSP/DFP No Stamp Plywood Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:05 PM CDT Asset located in: Brandon, MB, CAN
515	2026 SKLP 5 ft x 9 ft 10 in (0.4 in Thick) Steel Plates (Unused) S/N: E91476 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:03 PM CDT Asset located in: Brandon, MB, CAN	523	Quantity of (40) 3/4 in x 4 ft x 8 ft CSP/DFP No Stamp Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:05 PM CDT Asset located in: Brandon, MB, CAN
516	Quantity of (80) 3/8 in x 4 ft x 8 ft CSP/DFP No Stamp Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:03 PM CDT Asset located in: Brandon, MB, CAN	524	Quantity of (40) 3/4 in x 4 ft x 8 ft CSP/DFP No Stamp Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:05 PM CDT Asset located in: Brandon, MB, CAN
517	Quantity of (80) 3/8 in x 4 ft x 8 ft CSP/DFP No Stamp Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:03 PM CDT Asset located in: Brandon, MB, CAN	525	2026 BYT CC003 Squeeze Chute (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:05 PM CDT Asset located in: Brandon, MB, CAN
518	Quantity of (69) 1/2 in x 4 ft x 7 ft 11 1/4 in G2S With Smooth Overlay 2 Sides Douglas Fir 5 Ply No Stamp Formply Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:04 PM CDT Asset located in: Brandon, MB, CAN	526	Quantity of (2) 2026 BYT MGFF84 Funnel Livestock Feeder (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:06 PM CDT Asset located in: Brandon, MB, CAN
519	Quantity of (69) 1/2 in x 4 ft x 7 ft 11 1/4 in G2S With Smooth Overlay 2 Sides Douglas Fir 5 Ply No Stamp Formply Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:04 PM CDT Asset located in: Brandon, MB, CAN	527	Quantity of (2) 2026 BYT MGFF84 Funnel Livestock Feeder (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:06 PM CDT Asset located in: Brandon, MB, CAN
520	Quantity of (50) 5/8 in x 4 ft x 8 ft CSP/DFP No Stamp Plywood Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:04 PM CDT Asset located in: Brandon, MB, CAN	528	Quantity of (27) 2026 BYT WBF016 16 ft x 6 ft 5 in Wind Fence (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:06 PM CDT Asset located in: Brandon, MB, CAN
521	Quantity of (50) 5/8 in x 4 ft x 8 ft CSP/DFP No Stamp Plywood Plywood (Unused) S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:04 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
529	Quantity of (27) 2026 BYT WBF016 16 ft x 6 ft 5 in Wind Fence (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:06 PM CDT Asset located in: Brandon, MB, CAN	535	Quantity of (18) 2026 BYT RP76 7 ft 6 in Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 9 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:08 PM CDT Asset located in: Brandon, MB, CAN
530	Quantity of (34) 2026 BYT MSPP07 7 ft Mesh Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 7 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:07 PM CDT Asset located in: Brandon, MB, CAN	536	Quantity of (12) 2026 BYT RP76 7 ft 6 in Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 9 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:08 PM CDT Asset located in: Brandon, MB, CAN
531	Quantity of (34) 2026 BYT MSPP07 7 ft x 4 ft 3 in Mesh Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 8 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:07 PM CDT Asset located in: Brandon, MB, CAN	537	Quantity of (20) 2026 BYT RG1010 10 ft x 4 ft Ranch Livestock Gate (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:08 PM CDT Asset located in: Brandon, MB, CAN
532	Quantity of (34) 2026 BYT MSPP07 7 ft x 4 ft 3 in Mesh Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 8 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:07 PM CDT Asset located in: Brandon, MB, CAN	538	Quantity of (16) 2026 BYT MRG100 10 ft x 4 ft Magnum Livestock Gate (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:09 PM CDT Asset located in: Brandon, MB, CAN
533	Quantity of (24) 2026 BYT MSPP07 7 ft x 4 ft 3 in Mesh Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 8 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:07 PM CDT Asset located in: Brandon, MB, CAN	539	Quantity of (9) 2026 BYT RP96 9 ft 6 in x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 9 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:09 PM CDT Asset located in: Brandon, MB, CAN
534	Quantity of (34) 2026 BYT MSPP07 7 ft Mesh Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 8 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:08 PM CDT Asset located in: Brandon, MB, CAN	540	Quantity of (22) 2025 BYT MDRP96 9 ft 6 in Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 10 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:09 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
541	Quantity of (31) 2026 BYT RP96 9 ft 6 in x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 10 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:09 PM CDT Asset located in: Brandon, MB, CAN	547	Quantity of (23) 2025 BYT MDRP96 9 ft 6 in Livestock Panel (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:11 PM CDT Asset located in: Brandon, MB, CAN
542	Quantity of (24) 2025 BYT MDRP96 9 ft 6 in Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 10 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:10 PM CDT Asset located in: Brandon, MB, CAN	548	Quantity of (24) 2025 BYT MDRP96 9 ft 6 in Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 11 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:11 PM CDT Asset located in: Brandon, MB, CAN
543	Quantity of (24) 2025 BYT MDRP96 9 ft 6 in Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 10 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:10 PM CDT Asset located in: Brandon, MB, CAN	549	Quantity of (24) 2026 BYT RG12 12 ft Steel Livestock Gate (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:11 PM CDT Asset located in: Brandon, MB, CAN
544	Quantity of (26) 2026 BYT RP96 9 ft 6 in x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 10 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:10 PM CDT Asset located in: Brandon, MB, CAN	550	Quantity of (16) 2026 BYT MRG120 12 ft Steel Livestock Gate (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:12 PM CDT Asset located in: Brandon, MB, CAN
545	Quantity of (22) 2025 BYT MDRP96 9 ft 6 in Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 10 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:10 PM CDT Asset located in: Brandon, MB, CAN	551	Quantity of (24) 2026 BYT RG12 12 ft Steel Livestock Gate (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:12 PM CDT Asset located in: Brandon, MB, CAN
546	Quantity of (31) 2026 BYT RP96 9 ft 6 in x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 11 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:11 PM CDT Asset located in: Brandon, MB, CAN	552	Quantity of (20) 2026 BYT RG5012 12 ft Steel Heavy Duty Livestock Gate (Unused) S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:12 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
553	Quantity of (22) 2025 BYT RP120 12 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 12 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:12 PM CDT Asset located in: Brandon, MB, CAN	559	Steel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:14 PM CDT Asset located in: Brandon, MB, CAN
554	Quantity of (24) 2025 BYT RP120 12 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 12 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:13 PM CDT Asset located in: Brandon, MB, CAN	560	460 L Tank S/N: Not Available C/W: Pump Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:14 PM CDT Asset located in: Brandon, MB, CAN
555	Quantity of (24) 2025 BYT RP120 12 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 12 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:13 PM CDT Asset located in: Brandon, MB, CAN	561	Quantity of (7) Pallets of Paints, Grease, Oils, Fluids, Fire Extinguishers S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:14 PM CDT Asset located in: Brandon, MB, CAN
556	Quantity of (22) 2025 BYT RP120 12 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 12 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:13 PM CDT Asset located in: Brandon, MB, CAN	562	9 ft 2 in x 23.5 in Horizontal Aeration Tube S/N: Not Available C/W: Located in Lane 13 Spot 14, 23.5 in internal diameter, 26.5 in external diameter Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:15 PM CDT Asset located in: Brandon, MB, CAN
557	Quantity of (24) 2025 BYT RP120 12 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 12 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:13 PM CDT Asset located in: Brandon, MB, CAN	563	Caldwell 15 hp 8 ft Aeration Fan S/N: 10F0013 C/W: Located in Lane 13 Spot 14 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:15 PM CDT Asset located in: Brandon, MB, CAN
558	Quantity of (24) 2025 BYT RP120 12 ft Livestock Panel (Unused) S/N: Not Available C/W: Located in Lane 13 Spot 12 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:14 PM CDT Asset located in: Brandon, MB, CAN	564	Quantity of (2) Pallets of Bean Ladders S/N: Not Available C/W: Located in Lane 13 Spot 14 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:15 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
565	5 ft Honey Extractor S/N: Not Available C/W: Located in Lane 13 Spot 16 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:15 PM CDT Asset located in: Brandon, MB, CAN	571	8 ft 3 in Swather mount Swath Roller S/N: FF0018SR15 C/W: Located in Lane 9 Spot 9 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:17 PM CDT Asset located in: Brandon, MB, CAN
566	Quantity of (4) Tridekon 16 in Crop Dividers S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:16 PM CDT Asset located in: Brandon, MB, CAN	572	AWS 40 ft Air Bar S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:17 PM CDT Asset located in: Brandon, MB, CAN
567	Quantity of (4) 13 in Crop Dividers S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:16 PM CDT Asset located in: Brandon, MB, CAN	573	Quantity of (2) Air Conditioning Condensers S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:17 PM CDT Asset located in: Brandon, MB, CAN
568	Quantity of (3) Pallets of Combine Concave S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:16 PM CDT Asset located in: Brandon, MB, CAN	574	48 in Riding Mower Deck S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:18 PM CDT Asset located in: Brandon, MB, CAN
569	Quantity of Air Drill Parts S/N: Not Available C/W: Located in Lane 13 Spot 18 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:16 PM CDT Asset located in: Brandon, MB, CAN	575	2018 Bitimec Wash-Bots 101 BB Electric Fixed Bay Washing Unit S/N: 130289003 Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:18 PM CDT Asset located in: Brandon, MB, CAN
570	7 ft 6 in Swath Roller S/N: Not Available C/W: Located in Lane 9 Spot 9 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:17 PM CDT Asset located in: Brandon, MB, CAN	576	Wheel Lift S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:18 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
577	2 ton Hoist S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:18 PM CDT Asset located in: Brandon, MB, CAN	583	Quantity of Parts and Supplies S/N: Not Available C/W: 2 ton Transmission Jack, Pallet jack, Various Hand Cart, Stools Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:20 PM CDT Asset located in: Brandon, MB, CAN
578	Quantity of (4) 1987 Transpo Lift System WL-TLS4-6-60M 2 Post 6 ton Vehicle Lift S/N: Not Available C/W: 3 phase, 240/120V, sn 533131, 533132, 533133, 533134 Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:19 PM CDT Asset located in: Brandon, MB, CAN	584	Quantity of (4) Pallets of Miscellaneous Parts S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:20 PM CDT Asset located in: Brandon, MB, CAN
579	Quantity of (2) Pallets of Miscellaneous Parts S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:19 PM CDT Asset located in: Brandon, MB, CAN	585	Quantity of (6) Pallets of Miscellaneous Parts S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:20 PM CDT Asset located in: Brandon, MB, CAN
580	Hydraulic Shop Press S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:19 PM CDT Asset located in: Brandon, MB, CAN	586	Quantity of (4) Pallets of Miscellaneous Parts S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:21 PM CDT Asset located in: Brandon, MB, CAN
581	Quantity of Parts & Work Tables S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:19 PM CDT Asset located in: Brandon, MB, CAN	587	Quantity of (3) Pallets of Tools and Supplies S/N: Not Available C/W: Miscellaneous Bus Parts, shop tools, safety supplies Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:21 PM CDT Asset located in: Brandon, MB, CAN
582	Miscellaneous Ladders, Dollies, Work Platform S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:20 PM CDT Asset located in: Brandon, MB, CAN	588	Quantity of (2) Pallets of Tool Carts, Various Tools, Cords S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:21 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
589	Quantity of (3) Pallets of Tools and Parts S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:21 PM CDT Asset located in: Brandon, MB, CAN	595	Giant Mig-250 Electric Welder S/N: Not Available C/W: Welding Leads Not Included, Shop Cart, Parts and Supplies Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:23 PM CDT Asset located in: Brandon, MB, CAN
590	Quantity of (2) Pallets of Jacks, Jack Stands, and misc shop equipment. S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:22 PM CDT Asset located in: Brandon, MB, CAN	596	Quantity of (2) Pallets of Miscellaneous Toolboxes S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:23 PM CDT Asset located in: Brandon, MB, CAN
591	Quantity of (2) Pallets of Shop Supplies S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:22 PM CDT Asset located in: Brandon, MB, CAN	597	Husky Tool Box S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:23 PM CDT Asset located in: Brandon, MB, CAN
592	Shop Stand & Shelf S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:22 PM CDT Asset located in: Brandon, MB, CAN	598	Quantity of (6) Part Bins and Parts Bolt Bin S/N: Not Available C/W: Bins with various sized bolts, washers, nuts and various small things. Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:24 PM CDT Asset located in: Brandon, MB, CAN
593	Quantity of (3) Pallets of Shelves/Cabinets S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:22 PM CDT Asset located in: Brandon, MB, CAN	599	6 ft 2-Drawer Workbench S/N: Not Available C/W: Vise Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:24 PM CDT Asset located in: Brandon, MB, CAN
594	Quantity of (9) Office Supplies S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:23 PM CDT Asset located in: Brandon, MB, CAN	600	Symtech IsoColour Headlamp Alignment System S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:24 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
601	2016 CPS FA1000B A/C Recharge Machine S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:24 PM CDT Asset located in: Brandon, MB, CAN	607	Quantity of Tools S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:26 PM CDT Asset located in: Brandon, MB, CAN
602	Quantity of (2) Pallets of 2023 Hotsy 560SS Pressure Washer S/N: 11090340163636 C/W: 1500 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:25 PM CDT Asset located in: Brandon, MB, CAN	608	Ingersoll Rand 2475 24 cfm Electric 80 gal Air Compressor S/N: NAR10113827 C/W: 175 psi Working Pressure, 3 Phase, 7.5 hp Motor Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:26 PM CDT Asset located in: Brandon, MB, CAN
603	Quantity of (2) Pallets of Shop Vacs S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:25 PM CDT Asset located in: Brandon, MB, CAN	609	Herd Moose Grill Bumper S/N: Not Available C/W: to fit Freightliner, Tool Box (72 inches wide, 21 inches deep, 14 inches tall) x2 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:26 PM CDT Asset located in: Brandon, MB, CAN
604	2017 Clarke BSW 28 Walk-Behind Floor Sweeper S/N: 3510172705107 C/W: 24 in Working Width Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:25 PM CDT Asset located in: Brandon, MB, CAN	610	Moose Grill Bumper S/N: Not Available C/W: to fit Peterbilt, Tool Box (72 inches wide, 27 inches deep, 19 inches tall) Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:27 PM CDT Asset located in: Brandon, MB, CAN
605	Quantity of Shop Equipment S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:25 PM CDT Asset located in: Brandon, MB, CAN	611	Truck Flatbed Body S/N: Not Available C/W: 92 in Body Length, 98 in Width Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:27 PM CDT Asset located in: Brandon, MB, CAN
606	Parts Washer S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:26 PM CDT Asset located in: Brandon, MB, CAN	612	Quantity of Pumps S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:27 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
613	Allison Transmission S/N: 08301 Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:27 PM CDT Asset located in: Brandon, MB, CAN	619	Grain Master Grain Truck Dump Body S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:29 PM CDT Asset located in: Brandon, MB, CAN
614	Quantity of (3) Pallets of Miscellaneous Plastic Parts For Buses S/N: Not Available Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:28 PM CDT Asset located in: Brandon, MB, CAN	620	Quantity of (5) Mixed Tires S/N: Not Available C/W: Some Tires with Wheels Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:29 PM CDT Asset located in: Brandon, MB, CAN
615	Quantity of (4) Fenders - Fits John Deere R4004 S/N: Not Available Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:28 PM CDT Asset located in: Brandon, MB, CAN	621	Quantity of (4) Goodyear 320/85R38 Tires - Fits Case SPX3150 S/N: Not Available C/W: To Fit Case SPX3150 Sprayer, All Tires with Wheels Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:29 PM CDT Asset located in: Brandon, MB, CAN
616	Quantity of (8) Wheels S/N: Not Available C/W: Steel, 11R22.5 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: June 25 - Lot closing time: Thu, Jul 23, 03:28 PM CDT Asset located in: Brandon, MB, CAN	622	Quantity of (4) 600/65R38 Tires S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:30 PM CDT Asset located in: Brandon, MB, CAN
617	Quantity of Rims and Tires S/N: Not Available C/W: (2) Bus Rims, Shop Cart, (4) 265/65R18 Tires. Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:28 PM CDT Asset located in: Brandon, MB, CAN	623	Quantity of (4) 24.5R32 Tires - Fits Rogator SS884 S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:30 PM CDT Asset located in: Brandon, MB, CAN
618	Quantity of (2) Pallets of Parts and Supplies S/N: Not Available C/W: Cargo Bars, Rims, Tires, Hubcaps, Shop Carts Usage: Not Available Notes: Complete dispersal for Brandon Bus Lines Ltd - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:29 PM CDT Asset located in: Brandon, MB, CAN	624	Quantity of (4) 320/90R46 Tires S/N: Not Available Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:30 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
625	Quantity of (4) BKT 620/70R46 620/70R46 Tires - Fits John Deere R4044 S/N: Not Available C/W: To Fit High-Clearance Sprayer, All Tires with Wheels Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:30 PM CDT Asset located in: Brandon, MB, CAN	631	Quantity of (4) Galaxy 32 x 15.5-16.5SL Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:32 PM CDT Asset located in: Ste Agathe, MB, CAN
626	Quantity of (4) 710/70R42 Tires - Fits John Deere R4045 S/N: Not Available Usage: Not Available Notes: For more information, please contact Kurt Cormier PH: 204.918.0613 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:31 PM CDT Asset located in: Brandon, MB, CAN	632	Quantity of (2) Michelin 16.9R24 Tires - Fits Westward Swather S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:32 PM CDT Asset located in: Ste Agathe, MB, CAN
627	Kwik Kleen 9 ft 30 ton Grain Cleaner S/N: 0334 C/W: Electric Motor Engine, Screen Size - 10 /64 Inch Round Hole Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:31 PM CDT Asset located in: Ste Agathe, MB, CAN	633	Bibeau BFL Truck Dump Body S/N: B47781 C/W: Steel, 14 ft Body Length Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:32 PM CDT Asset located in: Ste Agathe, MB, CAN
628	Kwik Kleen 9 ft 30 ton Grain Cleaner S/N: 1147 C/W: Electric Motor Engine Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:31 PM CDT Asset located in: Ste Agathe, MB, CAN	634	Quantity of (2) Headache Rack S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:33 PM CDT Asset located in: Ste Agathe, MB, CAN
629	Mustang RH16 Q/C Rotating Demolition Pulverizer - Fits 200 Series S/N: AH201223 Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:31 PM CDT Asset located in: Ste Agathe, MB, CAN	635	Water Tank S/N: Not Available Usage: Not Available Lot closing time: Thu, Jul 23, 03:33 PM CDT Asset located in: Ste Agathe, MB, CAN
630	Quantity of (4) Galaxy 32 x 15.5-16.5SL Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:32 PM CDT Asset located in: Ste Agathe, MB, CAN	636	Rammer G100 24 in Q/C Hydraulic Breaker S/N: Not Available Usage: Not Available Notes: For more information, please contact James Nicholls - 807.708.1383 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 03:33 PM CDT Asset located in: Kenora, ON, CAN
		637	NM 25SK-668 64 in Skeleton Bucket - Fits Case 300 S/N: 25SK2214 Usage: Not Available Lot closing time: Thu, Jul 23, 03:33 PM CDT Asset located in: Kenora, ON, CAN

Lot #	Details	Lot #	Details
638	AMI 8450 84 in Q/C Excavator Chuck Blade S/N: 1371582 Usage: Not Available Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO ONTARIO SALES TAX., COMES WITH IRONCLAD ASSURANCE. SUBJECT TO ONTARIO SALES TAX. Lot closing time: Thu, Jul 23, 03:34 PM CDT Asset located in: Kenora, ON, CAN	643	2025 40 ft High Cube Storage Container S/N: DDDU5040501 C/W: One-Way Usage: Not Available Notes: For more information, please contact Mike Maneluk- 204.557.0805 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 03:35 PM CDT Asset located in: Rosser, MB, CAN
639	LMC 3560 Grain Leg S/N: 170000766 C/W: 2-way Valve, All White Tubing, Clamps, Discharge Right or Left" & "Easy Dump, Seed Flow Reducer Usage: Not Available Notes: For more information, please contact Glenn PH: 204.856.6633 - Item removal deadline: August 6 - Seller can assist buyer with load out - Additional information please visit www.lmcarter.com/elevator - Lot closing time: Thu, Jul 23, 03:34 PM CDT Asset located in: Bloom, MB, CAN	644	2026 40 ft High Cube Storage Container S/N: CAIU8934588 C/W: One-Way Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:35 PM CDT Asset located in: Brandon, MB, CAN
640	Grain Handler 1614 Continuous Grain Dryer S/N: 161401 C/W: 6000000 BTU, Liquefied Petroleum Gas, 3 phase 600 Volt, 7 Ft Frame Support Legs Usage: Not Available Notes: Capacity 1500 bu/he at 21% corn as per owner - For more information, please contact Glenn PH: 204.856.6633 - Item removal deadline: August 6 - Seller can assist buyer with load out - Lot closing time: Thu, Jul 23, 03:34 PM CDT Asset located in: Bloom, MB, CAN	645	2026 40 ft High Cube Storage Container S/N: SICU7011077 C/W: One-Way Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:35 PM CDT Asset located in: Brandon, MB, CAN
641	Baldor 450 HP 4160V Air Compressor Motor Electric Motor S/N: K1206140006 Usage: Not Available Notes: For more information, please contact Mike Maneluk- 204.557.0805 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 03:34 PM CDT Asset located in: Winnipeg, MB, CAN	646	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU1096554 C/W: One-Way Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:36 PM CDT Asset located in: Brandon, MB, CAN
642	2026 40 ft High Cube Multi-Door Storage Container S/N: DDDU9001925 C/W: One-Way Usage: Not Available Notes: For more information, please contact Mike Maneluk- 204.557.0805 - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Lot closing time: Thu, Jul 23, 03:35 PM CDT Asset located in: Rosser, MB, CAN	647	2026 40 ft High Cube Multi-Door Storage Container S/N: MMPU5010013 C/W: Located in Lane 14 Spot 4, One-Way Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:36 PM CDT Asset located in: Brandon, MB, CAN
		648	2025 20 ft Standard 20GP Storage Container (Unused) S/N: CIMU0424031 C/W: Located in Lane 14 Spot 5 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:36 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
649	2025 20 ft Standard 20GP Storage Container (Unused) S/N: CIMU0423992 C/W: Located in Lane 14 Spot 6 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:36 PM CDT Asset located in: Brandon, MB, CAN	654	MacDon 580 12 ft Mower Conditioner Header (Inoperable) S/N: 188961 C/W: Located in Lane 7 Spot 10, Hydraulic Driven, Conditioner Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:38 PM CDT Asset located in: Brandon, MB, CAN
650	2025 20 ft Standard 20GP Storage Container (Unused) S/N: CIMU0423987 C/W: Located in Lane 14 Spot 7 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:37 PM CDT Asset located in: Brandon, MB, CAN	655	2008 Toyota Tundra Limited 4x4 Crew Cab Pickup (Inoperable) S/N: 5TBDV581X8S500892 C/W: 5.7 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, 3265 kg GVWR, 305/55R20 Tires, 5 ft 6 in Bed Usage: Not Available Notes: For more information, please contact Stan- 204.955.8423 - Recall as per Carfax on file - Bill of Sale only - No Title/Registration - Cannot be exported - May require inspection prior to registering - Item removal deadline: August 7 - Buyer responsible for load out and all associated costs - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:38 PM CDT Asset located in: Manitoba, MB, CAN
651	2025 20 ft Standard 20GP Storage Container (Unused) S/N: CIMU0424279 C/W: Located in Lane 14 Spot 8 Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:37 PM CDT Asset located in: Brandon, MB, CAN	656	2006 Lincoln Mark LT 4x4 Crew Cab Pickup (Inoperable) S/N: 5LTPW18516FJ02252 C/W: Located in Lane 7 Spot 13, 5.4 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 275/65R18 Tires, 5 ft 6 in Bed Usage: 400,671 Mi Notes: SK rebuilt VIN Status - Recalls as per Carfax on file - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Title /Registration - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:38 PM CDT Asset located in: Brandon, MB, CAN
652	2026 10 ft Storage Container S/N: CTTN0001181 C/W: Located in Lane 14 Spot 15, Man Door, Window Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:37 PM CDT Asset located in: Brandon, MB, CAN		
653	2026 Steamy Escapes Hudson 7 ft X 10 ft Sauna (Unused) S/N: Not Available C/W: This Custom-Built Hudson Sauna Seats 4-6 People and Features an 8 ft Sauna Room with a 2 ft Porch. Fully Insulated and Built on Skids for Easy Moving. The Interior is Finished Entirely in Cedar, Including the Floor, Walls, Ceiling, Benches, and Backrest, with LED Lighting Installed Under the Benches and Behind the Backrest. Wired for 110V lighting and 220V for a heater. The exterior is finished with metal siding and roofing, and includes a tempered glass door and windows, along with an exterior pot light with two settings. Built for year-round use Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:37 PM CDT Asset located in: Brandon, MB, CAN		

Lot #	Details	Lot #	Details
657	2005 Ford F-150 XLT 4x4 Extended Cab Pickup (Inoperable) S/N: 1FTPX04595KE90594 C/W: Located in Lane 7 Spot 14, 5.4 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, 275/65R18 Tires, 6 ft 6 in Bed, ladder rack Usage: 562,852 Km Notes: SK rebuilt VIN status - Previous Damage exceeds 40K as per Carfax on file - For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:38 PM CDT Asset located in: Brandon, MB, CAN	660	2022 Western Star 5700 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 5KJJBHDR5NLNN0843 C/W: Located in Lane 7 Spot 19, Detroit Engine, Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Engine Brake, Double Differential Locks, 60 in Mid Roof Sleeper Cab, Bunk Beds, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:39 PM CDT Asset located in: Brandon, MB, CAN
658	2006 Freightliner M2 106 4x2 Versatile Hauler Truck (Inoperable) S/N: 1FVACXCS16HW16306 C/W: Mercedes-Benz 6 Cylinder Diesel Engine, 2005 US EPA Label, CARB Compliant, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 27500 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 202 in Wheelbase Usage: 313,822 Km Notes: For more information, please contact Doug Kerr PH: 204.528.3293 - MB Safety valid until December 31, 2026 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:39 PM CDT Asset located in: Brandon, MB, CAN	661	2019 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDZAPR6KN118878 C/W: Cummins X15 Engine, 2018 US EPA Label, Automatic Transmission, 12320 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Engine Brake, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 230 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,094,512 Hr Notes: For more information, please contact Brad Werk PH: 639.994.2885 - Item removal deadline: August 7 - SK Safety valid until September 30, 2026 - SK Cab Card - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:39 PM CDT Asset located in: Ste Agathe, MB, CAN
659	2023 International LT62F 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDZAPR4PN492655 C/W: Located in Lane 7 Spot 16, Cummins X15 Engine, 2022 US EPA Label, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 223 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5 Front Tires, 275/70R22.5 Rear Tires, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:39 PM CDT Asset located in: Brandon, MB, CAN	662	2017 Kenworth T880 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKZDP9X8HJ987414 C/W: Located in Lane 7 Spot 23, Paccar MX-13 455 hp Engine, 2016 US EPA Label, 5670 kg Front Axle, 17236 kg Rears, 22907 kg GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 244 in Wheelbase, Air Suspension, Aluminum Wheels, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Proof of Ownership/TOD - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 03:40 PM CDT Asset located in: Brandon, MB, CAN

Lot #	Details	Lot #	Details
663	2013 Peterbilt 386 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPHDP9X1DD168260 C/W: Located in Lane 7 Spot 15, Eaton Fuller 13-Speed 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Differential Lock, 70 in Mid Roof Sleeper Cab, Bunk Beds, 236 in Wheelbase, Air Suspension, 11R22.5, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:40 PM CDT Asset located in: Brandon, MB, CAN	666	2008 Kenworth T800 6x4 Vacuum Excavator Truck (Inoperable) S/N: 1NKDL50X98J937470 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, 18-Speed Manual Transmission, Double Differential Locks, 9072 kg Front Axle, 19958 kg Rears, 29938 kg GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 256 in Wheelbase, Steel Debris Tank, Full Open Tailgate, Manual Tailgate Locks Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:41 PM CDT Asset located in: Brandon, MB, CAN
664	2007 Peterbilt 378 8x4 Twin-Steer Bed Truck (Inoperable) S/N: 1NPFLT0X17N655869 C/W: Cat C11 Aceert 6 Cylinder Diesel Engine, 2006 US EPA Label, 16000 lb Front Axle, 46000 lb Rears, 62000 lb GVWR, 12R22.5, Dual Steering Boxes, Spring over Walking Beam Suspension, 348 in Wheelbase, 28 ft x 100 in Bed, Tail Roll Usage: Not Available Notes: MB Proof of Ownership/TOD - May require inspection prior to registering - Additional information available - See Supporting Document Lot closing time: Thu, Jul 23, 03:40 PM CDT Asset located in: Stony Mountain, MB, CAN	667	Carrier Comfort Pro APU (Inoperable) S/N: Not Available C/W: Kubota Diesel Engine Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - Item removal deadline: August 7 - Lot closing time: Thu, Jul 23, 03:41 PM CDT Asset located in: Brandon, MB, CAN
665	2010 Kenworth T800 6x4 Vacuum Excavator Truck (Inoperable) S/N: 1NKDL50X5AJ942865 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, 18-Speed Manual Transmission, Double Differential Locks, 9072 kg Front Axle, 20866 kg Rears, 29938 kg GVWR, Air Ride Cab, Aluminum Wheels, 445/65R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 256 in Wheelbase, Steel Debris Tank, Full Open Tailgate, Manual Tailgate Locks, PTO Driven Pump Usage: Not Available Notes: For more information, please contact the Brandon office PH: 204.441.1079 - MB Title /Registration - May require inspection prior to registering - Item removal deadline: August 7 - Additional information available - See Supporting Documents Lot closing time: Thu, Jul 23, 03:40 PM CDT Asset located in: Brandon, MB, CAN		