

Fort Worth, TX, USA - Dec 10, 2024

Lot #	Details	Lot #	Details
	2014 Big Country 36 ft T/A Travel Trailer S/N: 5SFBG3629EE280670 C/W: Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	З	E OF 2 - Lot #'s: 3, 4 2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380435 C/W: Open Operator Station, 2006 US EPA Label, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 2,597 Hr
-	2014 Heartland Wilderness 28 ft T/A Travel	-	Asset located in: Lake Worth, TX
	Trailer S/N: 5SFNB3127EE271422 C/W: 2 Slide Outs, Bumper Pull, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE.	4	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380358 C/W: Open Operator Station, 2006 US EPA Label, 82 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 4,932 Hr Asset located in: Lake Worth, TX
	VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	5	2015 John Deere 210L EP 4x4 Landscape Loader S/N: 1T8210ELEFJ892655
	2013 Heartland 37QB Bighorn 41 ft T/A Travel Trailer S/N: 5SFBG4123DE255887 C/W: Sleeps 2 People, 4 Slide Outs, Power Leveling Jacks, Power Awning, 5th Wheel,		C/W: Open Operator Station, 2015 US EPA Label, 84 in Bucket, 89 in Box Blade, Rear Wheel Weights, with Rippers Usage: 4,261 Hr Asset located in: Lake Worth, TX
	Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO	6	2006 Case 570 MXT 4x4 Landscape Loader S/N: JJG0380343 C/W: Enclosed Cab, 83 in Bucket, 83 in Hydraulic Tilting Box Blade Usage: 2,554 Hr Asset located in: Lake Worth, TX
	BIDDING Asset located in: Lake Worth, TX	6A	2018 Cat 415F2 IL 4x4 Landscape Loader
1	2017 Case 570 N EP 4x4 Landscape Loader S/N: JJGN570NEHC739167 C/W: Open Operator Station, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Weight Box Usage: 4,852 Hr		S/N: 0PF400836 C/W: Open Operator Station, 89 in Bucket, 89 Hydraulic Tilting Box Blade w/ Hydraulic Scarifier Usage: 2,540 Hr Asset located in : Lake Worth, TX
-	Asset located in: Lake Worth, TX		
2	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380199 C/W: Open Operator Station, 2006 US EPA Label, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 7,966 Hr Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7	2022 Cat 420 IT 4x4 Backhoe Loader S/N: CAT00420TH8T02368 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Forks, Quick Coupler, 24 in Backhoe Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 66 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	13	2017 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FAHWD01616 C/W: Open Operator Station, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92.5 in Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420CH8T00232 C/W: Open Operator Station, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 12 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,244 Hr Asset located in: Lake Worth, TX	14	2017 Cat 420F2 IT 4x4 Backhoe Loader S/N: CAT0420FHHWD01618 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92 in Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420AH8T00225 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 96 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,803 Hr Asset located in: Lake Worth, TX	15	Asset located in: Humble, TX 2016 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FKHWD00461 C/W: Open Operator Station, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 96 in Loader Bucket, 25 in Backhoe Digging Bucket Usage: 5,256 Hr Asset located in: Lake Worth, TX
CHOICE	CHOICE OF 4 - Lot #'s: 10, 11, 8, 9 10 2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420AH8T00287 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in		2016 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FCHWD01301 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket Usage: 4,376 Hr Asset located in: Lake Worth, TX
11	Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 5,611 Hr Asset located in: Lake Worth, TX 2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420JH8T00303 C/W: Open Operator Station, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket	17	2016 Cat 420 F2 4x4 Backhoe Loader S/N: CAT0420FEHWC01679 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, 86 in Multi-Purpose Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, (2) Rear Auxiliary Hydraulics Usage: 2,720 Hr Asset located in: Lake Worth, TX
12	Usage: 5,904 Hr Asset located in: Lake Worth, TX 2017 Cat 420F2 4x4 Backhoe Loader S/N: CAT0420FJHWC02726 C/W: Open Operator Station, Backhoe Pilot Controls, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 15 in Backhoe Cleanup Bucket, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,487 Hr Asset located in: Lake Worth, TX	18	2015 Cat 420F2 IT 4x4 Backhoe Loader S/N: CAT0420FAHWD00353 C/W: Open Operator Station, Backhoe Pilot Controls, Control Pattern Changer, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 94 in Loader Bucket, Forks, 23 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,443 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
19	2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FVHWD00240 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket Usage: 5,953 Hr Asset located in: Humble, TX	27	2017 Cat 416F2 4x4 Backhoe Loader S/N: CAT0416FTHWB01148 C/W: Open Operator Station, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 88 in Loader Bucket, 10 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	7.000 Todato III. Trambio, 17.	28	2022 Cat 415 4x4 Backhoe Loader
CHOIC 20	CHOICE OF 2 - Lot #'s: 20, 21 20		S/N: CAT00415HH8A00347 C/W: Open Operator Station, Air Ride Seat, 2022 US EPA Label, 89 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 41 Hr
	C/W: Open Operator Station, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 5,886 Hr		Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	30	2017 Cat 415F2 4x4 Backhoe Loader
21	2014 Cat 420FIT 4x4 Backhoe Loader S/N: CAT0420FKJWJ02630 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-		S/N: CAT0415FCHWA00473 C/W: Open Operator Station, 88 in Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,258 Hr
	PRIMORIS-ŠĒRVICES-CORP-COMPANY		Asset located in: Lake Worth, TX
	Usage: 5,652 Hr Asset located in : Lake Worth, TX	31	2016 John Deere 410L 4x4 Backhoe Loader
22	2015 Cat 420F 4x4 Backhoe Loader S/N: CAT0420FVSKR04978 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, 2014 US EPA Label, 92 in Loader		S/N: 1T0410LXPGF298786 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid, 94 in Loader Bucket, 25 in Backhoe Digging Bucket Usage: 7,966 Hr Asset located in: Lake Worth, TX
	Bucket, Quick Coupler, 22 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,681 Hr Asset located in : Lake Worth, TX		2018 John Deere 310L EP 4x2 Backhoe Loader S/N: 1T0310ELEJG337511 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket
24	2012 Cat 420E 4x4 Backhoe Loader		Usage: 3,151 Hr Asset located in: Lake Worth, TX
	S/N: CAT0420EHDJL03428 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, 86 in Loader Bucket, 24 in Backhoe Digging Bucket, Manual Thumb Usage: 4,236 Hr Asset located in: Lake Worth, TX	34	2018 John Deere 310L EP 4x2 Backhoe Loader S/N: 1T0310ELCJG334570 C/W: Open Operator Station, 2018 US EPA Label, 84 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 3,480 Hr
25	2011 Cat 420E IT 4x4 Backhoe Loader		Asset located in: Lake Worth, TX
	S/N: CAT0420EPDAN01657 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 90 in Multi-Purpose Loader Bucket, 30 in Backhoe Digging Bucket, Thumb Bracket Usage: 6,276 Hr Asset located in: Lake Worth, TX	CHOIC 35	E OF 2 - Lot #'s: 35, 36 2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKKEE263557
26	2020 Cat 416F2 4x4 Backhoe Loader	1	C/W: Open Operator Station, 86 in Loader
20	S/N: CAT0416FTHWB02400 C/W: Open Operator Station, Air Ride Seat, Requires Diesel Exhaust Fluid, 89 in Loader Bucket, 20 in Backhoe Cleanup Bucket Usage: 2,510 Hr		Bucket, 24 in Backhoe Digging Bucket Usage: 4,207 Hr Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
36	2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKAEE263368 C/W: Open Operator Station, 90 in Loader Bucket, 16 in Backhoe Digging Bucket Usage: 2,948 Hr Asset located in: Lake Worth, TX	43	2005 Cat 430D 4x4 Backhoe Loader S/N: CAT0430DKBML05163 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Hydraulic Coupler, 92 in Loader Bucket, 24 in Backhoe Cleanup Bucket Usage: 7,018 Hr
37	2012 John Deere 310SJ 4x4 Backhoe Loader		Asset located in: Lake Worth, TX
	S/N: 1T0310SJABD210971 C/W: Enclosed Cab, Air Conditioner, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 92 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,804 Hr	44	2005 Cat 420D 4x4 Backhoe Loader S/N: CAT0420DJFDP23675 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 89 in Loader Bucket, 26 in Backhoe Digging Bucket Usage: 5,495 Hr
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE		Asset located in: Lake Worth, TX
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	45	2008 John Deere 310SJ 4x4 Backhoe Loader S/N: T0310SJ156742 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, Tier 2, 2007 US EPA Label, 92 in Loader Bucket,
38	2016 Case 580N 4x4 Backhoe Loader S/N: JJGN580NJFC717602 C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,827 Hr		Extendable Stick, 36 in Backhoe Digging Bucket Usage: 4,508 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO
	Asset located in: Lake Worth, TX	_	3RD PARTY STORAGE FEES.
39	2014 Case 580 Super N 4x4 Backhoe Loader		Asset located in: Lahoma, OK
	S/N: JJGN58SNAEC705935 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 2014 US EPA Label, 82 in Loader Bucket, Extendable Stick, 23 in Backhoe Digging Bucket Usage: 3,941 Hr	46	2005 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX945350 C/W: Enclosed Cab, Air Conditioner, 86 in Loader Bucket, 18 in Backhoe Digging Bucket Usage: 7,887 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	47	
40	2013 Case 580N 4x4 Backhoe Loader S/N: JJGN580NLDC581006 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 82 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,697 Hr	47	2001 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX895009 C/W: Open Operator Station, 2000 US EPA Label, 84 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 7,556 Hr Asset located in: Lake Worth, TX
	Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	48	2008 Case 580 Super M Series 3 4x4 Backhoe Loader S/N: N8C504007
	Asset located in: Lake Worth, TX		C/W: Enclosed Cab, 82 in Loader Bucket,
41	2018 JCB 3CX 4x4 Backhoe Loader S/N: JCB3CXTTCJ2667099 C/W: Open Operator Station, 2018 US EPA	49	Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 9,616 Hr Asset located in : Lake Worth, TX
	Label, 86 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 1,433 Hr Asset located in: Humble, TX		2003 Case 580M 4x4 Backhoe Loader S/N: JJG0312663 C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket,
42	2012 New Holland B95C 4x4 Backhoe Loader S/N: FNH0B95CNCHH02653 C/W: Open Operator Station, 88 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,544 Hr Asset located in: Lake Worth, TX		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,258 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
49A	2018 Case 580SN 4x2 Backhoe Loader S/N: JJGN58SNPJC75003 C/W: Open Operator Station, 81 in, Quick Coupler Usage: 2,055 Hr Asset located in: Lake Worth, TX	56	2019 John Deere 844K-III Wheel Loader S/N: 1DW844KACJF692631 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick Steering, Loadrite On-Board Scale, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9.3 cyd 144 in Bucket, Auto Lube, 875/65R29 Tires
49B	2018 Case 580SN 4x2 Backhoe Loader S/N: JGN58SNCJC753046 C/W: Open Operator Station, Backhoe Pilot	57	Usage: 9,476 Hr Asset located in: Lake Worth, TX
	Controls, 81 in Loader Bucket, Quick Coupler, 30 in Backhoe Digging Bucket Usage: 3,537 Hr Asset located in: Lake Worth, TX		2015 Cat 980M High Lift Wheel Loader S/N: LKRS00731 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Joystick Steering,
50	2006 Cat 416E 4x2 Backhoe Loader S/N: CAT0416EVSHA00900 C/W: Open Operator Station, Air Ride Seat, 89 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 12,955 Hr Asset located in: Lake Worth, TX		loadrite On-Board Scale, 7.5 cyd 135 in Bucket, 29.5R25 Tires Usage: 20,599 Hr Notes: PLEASE SEE SELLER SUPPLIED ENGINE REBUILD INFORMATION IN THE SUPPORTING DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
51	2008 John Deere 310J 4x2 Backhoe Loader S/N: T0310JX159493 C/W: Open Operator Station, Manual Coupler, 84 in Loader Bucket Usage: 2,804 Hr Asset located in: Lake Worth, TX	58	2018 Case 1121G Wheel Loader S/N: JEEN1121KJF246039 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Joystick Steering, 6.1 cyd 126 in Bucket, 26.5R25 Tires Usage: 6,569 Hr
52	2007 John Deere 310J 4x4 Backhoe Loader S/N: T0310JX149906 C/W: Open Operator Station, Manual Coupler, 86 in Loader Bucket, 25 in Backhoe Usage: 2,809 Hr Asset located in: Lake Worth, TX	59 CHOICI —61	Asset located in: Lake Worth, TX 2022 Komatsu WA475-10 Wheel Loader S/N: KMTWA142VNNA40104 C/W: Enclosed Cab, Air Conditioner, Rear Vic Camera, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4.4 m3 124 in
53	2005 Case 590 Super M 4x2 Backhoe Loader S/N: N5C394910 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 93 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 4,876 Hr		Bucket, Auto Lube, 26.5-25 Tires Usage: 7,012 Hr Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 61, 9606A
54	Asset located in: Lake Worth, TX 2004 Case 580M 4x2 Backhoe Loader S/N: N4C303573 C/W: Open Operator Station, 2004 US EPA Label, 83 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,191 Hr		2017 Cat 966M Wheel Loader S/N: CAT0966MPKJP02589 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 26.5-25 Tires, Auxiliary Hydraulics, Pipe Grapple Usage: 4,818 Hr Asset located in: Bridgeport, NJ
 55	Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2016 Kubota L47TLB 4x4 Backhoe Loader		2021 Cat 950GC Wheel Loader S/N: CAT00950TM5T04416 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 23.5-25 Tires, 4.5 cyd 114 in Bucket Usage: 1,455 Hr
55	S/N: 50136 C/W: Open Operator Station, Manual Coupler, 71 in Loader Bucket, 11 in Backhoe Digging Bucket Usage: 671 Hr Asset located in: Lake Worth, TX	63	Asset located in: Baton Rouge, LA 2020 Cat 950GC Wheel Loader S/N: CAT00950AM5T03307 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 3.30 m3 116 in Bucket, 23.5-25 Tires Usage: 4,902 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
64	2019 Cat 950 M Wheel Loader S/N: CAT0950MVJ1S02214 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 116 in Bucket, Auto Lube, 23.5R25 Tires Usage: 9,296 Hr Asset located in: Lake Worth, TX	71	2023 John Deere 644P Wheel Loader S/N: 1DW644PAVPLZ17531 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 23.5R25 Tires, Hydraulic Coupler, 4 cyd 120 in Bucket Usage: 3,296 Hr Asset located in: St. Rose, LA
СНОІС	E OF 2 - Lot #'s: 65, 66	сноіс	E OF 2 - Lot #'s: 73, 74
65	2017 Cat 950MZ Wheel Loader S/N: CAT0950MCHE810302 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 3.40 m3 117 in Bucket, 23.5R25 Tires Usage: 6,932 Hr	73	2014 John Deere 644 K Wheel Loader S/N: 1DW644KZLED661608 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2014 US EPA Label, Forks, 23.5R25 Tires Usage: 15,623 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	74	2013 John Deere 644 K Wheel Loader
66	2016 Cat 950M Wheel Loader S/N: CAT0950MKEMB02486 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 114 in Bucket, 23.5		S/N: 1DW644KZKCE650141 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, 102 in Bucket, 23.5 R25 Tires Usage: 16,918 Hr Asset located in: Lake Worth, TX
	R25 Tires, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,168 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	76	2019 Volvo L90H Wheel Loader S/N: VCEOL90HL0S624993 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket,
67	2014 Cat 950 K Wheel Loader		20.5R25 Tires Usage: 6,927 Hr
07	S/N: CAT0950KTR4A02440		Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Traction Control, 2017 US EPA Label, 118 in Bucket, 23.5-25 Tires Usage: 20,054 Hr Asset located in: Lake Worth, TX	77	2015 Volvo L90G Wheel Loader S/N: VCE0L90GT0S617667 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2014 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 108 in Bucket,
68	2011 Cat 950H Wheel Loader		20.5R25 Tires
	S/N: CAT0950HEJAD00705 C/W: Enclosed Cab, Air Conditioner, Air Ride		Usage: 12,859 Hr Asset located in: Lake Worth, TX
	Seat, Hydraulic Coupler, 114 in Bucket, 23.5 R25 Tires Usage: 23,037 Hr Asset located in: Lake Worth, TX	78	2016 Cat 938M Wheel Loader S/N: CAT0938MTJ3R02448 C/W: Enclosed Cab, Air Conditioner, 2016 US
69	2013 Komatsu WA380-7 Wheel Loader S/N: KMTWA118L36A64146 C/W: Enclosed Cab, Air Conditioner, Rear View		EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 19,902 Hr Asset located in: Lake Worth, TX
	Camera, 2012 US EPA Label, Hydraulic Coupler, 23.5R25 Tires	70	
70	Usage: 23,049 Hr Asset located in: Lake Worth, TX 2018 Volvo L110H Wheel Loader	79 -	2014 Cat 938K Wheel Loader S/N: CAT0938KPSWL02223 C/W: Enclosed Cab, Rear View Camera, 2013 US EPA Label, 20.5R25 Tires
, 3	S/N: VCEL110HT0S631498 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 118 in Bucket, Forks, 23.5R25 Tires Usage: 6,898 Hr Asset located in: Lake Worth, TX		Usage: 21,033 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
79A	2018 Case 621G Wheel Loader S/N: JEEN0621HJF243666 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 102 in Bucket, 20.5x25 Tires Usage: 5,236 Hr Asset located in: Lake Worth, TX	89	2014 Cat 930K Wheel Loader S/N: CAT0930KTRHN03712 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 101 in Bucket, Forks, 20.5 R25 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 10,745 Hr Asset located in: Livingston, LA
CHOIC	E OF 1 - Lot #'s: 81	90	2012 Cat 930K Wheel Loader
81	2020 Hyundai HL955 Wheel Loader S/N: HHKHW500AL0000844 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 20.5		S/N: CAT0930KHRHN00708 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 110 in Bucket, Forks, 20.5R25 Tires Usage: 12,980 Hr Asset located in: Lake Worth, TX
	R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 4,328 Hr Notes: . Asset located in: Lake Worth, TX	91	2012 Cat 930 H Wheel Loader S/N: CAT0930HEDHC03679 C/W: Enclosed Cab, Air Ride Seat, Auxiliary Hydraulics, Hydraulic Coupler, 101 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT-FROM-A-
82	2023 John Deere 544P Wheel Loader S/N: 1DW544PALPLX19742 C/W: Enclosed Cab, Air Conditioner, Rear View	92	PRIMORIS-SERVICES-CORP-COMPANY Usage: 12,460 Hr Asset located in : Lake Worth, TX
	Camera, Air Ride Seat, Autoshift, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 20.5R25 Tires, Auxiliary Hydraulics, Hydraulic Coupler, 3.5 cyd 106 in Bucket Usage: 1,546 Hr Asset located in: Greenville, TX		2012 Volvo L70G Wheel Loader S/N: VCE0L70GC00002431 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires
85	2007 John Deere 544J Wheel Loader	93	Usage: 33,042 Hr Asset located in: Lake Worth, TX
	S/N: DW544JZ610127 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, Traction Control, 2006 US EPA Label, CARB Compliant, 3.0 cyd 103 in Bucket, 20.5R25 Tires Usage: 7,496 Hr Asset located in: Midland, TX		2017 Komatsu WA320-8 Wheel Loader S/N: KMTWA135JHA085240 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 108 in Bucket, 20.5R25 Tires Usage: 15,207 Hr
87	2020 Hitachi ZW180-6 Wheel Loader		Asset located in: Lake Worth, TX
	S/N: RYUPD860CH8405515 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid,	сноіс	E OF 2 - Lot #'s: 95, 96
	Hydraulic Coupler, 104 in Bucket, 23.5R25 Tires Usage: 12,123 Hr Asset located in : Lake Worth, TX	95	2014 Komatsu WA270-7 Wheel Loader S/N: KMTWA122C01080092 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, 2013 US EPA Label,
CHOICE OF 2 - Lot #'s: 88, 89			Hydraulic Coupler, 104 in Bucket, 60 in Forks, 20.5R25 Tires Usage: 8,531 Hr
88	2015 Cat 930M Wheel Loader S/N: CAT0930MKKTG00791 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 11,259 Hr Asset located in: Lake Worth, TX	96	Asset located in: Lake Worth, TX 2013 Komatsu WA270-7 Wheel Loader S/N: KMTWA122C01080021 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Hydraulic Coupler, 104 in Bucket, 60 in Forks, Auto Lube, 20.5R25 Tires Usage: 11,558 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
CHOICE OF 1 - Lot #'s: 98 98 2013 Cat 924K Wheel Loader		107	2017 Cat 906M Wheel Loader S/N: CAT0906MKH6602101 C/W: Open Operator Station, 2011 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.6 cyd 82 in Bucket, 340/80R18 Tires	
	S/N: CAT0924KLPWR01641 C/W: Enclosed Cab, Air Conditioner, Air Ride		Usage: 3,249 Hr Asset located in : Midland, TX	
	Seat, Ride Control, Autoshift, 2012 US EPA Label, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires Usage: 8,775 Hr Asset located in: Lake Worth, TX	108	2006 Volvo L110E Wheel Loader S/N: L110EV61151 C/W: Enclosed Cab, 2006 US EPA Label, Hydraulic Coupler, 112 in Bucket, 23.5R25 Tires Usage: 9,676 Hr	
99	2012 Volvo L60G Wheel Loader S/N: VCE0L60GH00001263	100	Asset located in: Lake Worth, TX	
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 11,335 Hr Asset located in: Lake Worth, TX	109	2005 Cat 924G Wheel Loader S/N: CAT0924GJDDA02066 C/W: Enclosed Cab, Air Conditioner, Autoshift, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: 14,142 Hr	
100	2014 Cat IT14G2 Wheel Loader	110	Asset located in: Lake Worth, TX 1990 Cat 980C Wheel Loader	
	S/N: CATIT14GLERP00499 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.40 m3 94 in Bucket, Forks, 17.5-25 Tires Usage: 2,976 Hr	110	S/N: 63X09341 C/W: Enclosed Cab, Air Conditioner, 29.5R25 Tires Usage: Not Available Asset located in: Lake Worth, TX	
101	Asset located in: Lake Worth, TX	111	2000 Cat 966G Wheel Loader	
101	2022 Bobcat L85 Wheel Loader S/N: B53C11128 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 405/70R18 Tires Usage: 1,595 Hr		S/N: 3SW00657 C/W: Enclosed Cab, 128 in Bucket, 26.5-25 Tires Usage: 23,327 Hr Asset located in : Lake Worth, TX	
	Asset located in: Lake Worth, TX	112	2000 Cat 938G Wheel Loader S/N: 4YS01303	
103	2018 Cat 908M Wheel Loader S/N: CAT0908MEH8803041 C/W: Enclosed Cab, Air Conditioner, 78 in Grapple Bucket, Solid Tires Usage: 10,102 Mi	C/W: Enclosed Cab, Air Conditioner,	C/W: Enclosed Cab, Air Conditioner, 2000 US EPA Label, 110 in Bucket, Forks, 20.5R25 Tires Usage: 12,027 Hr	
	Asset located in: Lake Worth, TX	113	1985 Cat 966D Wheel Loader	
СНОІС	E OF 2 - Lot #'s: 105, 106		S/N: 99Y04055 C/W: Enclosed Cab, Manual Coupler, Forks, 26.5-25 Tires Usage: 5,678 Hr Asset located in : Lake Worth, TX	
105	2023 Cat 906 Wheel Loader (Unused) S/N: CAT00906HHZ600672 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2023 US EPA Label, Hydraulic Coupler, 70 in Forks, 405/70R18 Tires, 25 MPH Machine Usage: 27 Hr Asset located in: Humble, TX	114	114 1989 Cat 950 E Wheel Loader S/N: 22Z04456 C/W: Open Operator Station, Hydraulic C 110 in Bucket, Forks, 23.5-25 Tires, EQUIPMENT-FROM-WATKINS-CONSTRU Usage: 5,198 Hr Notes: LOT 5887 FITS THIS MACHINE - N	1989 Cat 950 E Wheel Loader S/N: 22Z04456 C/W: Open Operator Station, Hydraulic Coupler, 110 in Bucket, Forks, 23.5-25 Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,198 Hr Notes: LOT 5887 FITS THIS MACHINE - WHEEL
106	2023 Cat 906 Wheel Loader (Unused) S/N: CAT00906CHZ601041 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2023 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 74 in Bucket, Forks, 405/70R18 Tires, 25 MPH Machine Usage: 3 Hr Asset located in: Humble, TX		LOADER FORKS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
114A 115	1998 Cat IT28G Wheel Loader S/N: 8CR01014 C/W: Enclosed Cab, Air Conditioner, Ride Control, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5-25 Tires Usage: 18,294 Hr Asset located in: Lake Worth, TX 1998 Case 621B Wheel Loader	126	2016 Cat 140M3 Motor Grader S/N: CAT0140MHN9M00322 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Ripper, 17.5R25 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 9,287 Hr
113	S/N: JEE0055157		Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, 1997 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: Not Available Asset located in : Lake Worth, TX	127	2015 Cat 140M3 Motor Grader S/N: CAT0140MLN9D00447 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for
123	2011 John Deere 872GP AWD Motor Grader	1	Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper
	S/N: 1DW872GPCBE636116 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 2011 US EPA Label, 16 ft / 4.88 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 7,669 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX		/Scarifier, 17.5R25 Tires Usage: 5,571 Hr Asset located in : Lake Worth, TX
		128	2015 Cat 140M3 Motor Grader S/N: CAT0140MQN9D00463
			C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Pre-Wired for Grade Control, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper /Scarifier, Rear Auxiliary Hydraulics, 17.5R25 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 11,666 Hr Asset located in: Lake Worth, TX
		132	2011 Cat 140M2 VHP Plus Motor Grader S/N: CAT0140MEM9D00692 C/W: Enclosed Cab, Air Conditioner, Air Ride
			Seat, Joystick Steering, Rear View Camera, Differential Lock, 2011 US EPA Label, 14 ft /
124			4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 14.00-24 Tires, Topcon GX-60 Display, Topcon 3D MC-R3 Radio Receiver, Topcon MC2 Sensors with Masts Usage: 9,084 Hr Asset located in: Lake Worth, TX
	Fluid, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 6,884 Hr Asset located in : Lake Worth, TX		2015 John Deere 772GP AWD Motor Grader S/N: 1DW772GPLFF667809 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Carrena, Pre-Wired for Grade
125	2017 Cat 140M3 Motor Grader S/N: CAT0140MJN9D00717 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires Usage: 10,845 Hr Asset located in: Lake Worth, TX		Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 6,172 Hr Asset located in : Lake Worth, TX
		134	2019 John Deere 672G Motor Grader S/N: 1DW672GXCKF693988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Differential Lock, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 5,387 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
135	2015 John Deere 672G AWD Motor Grader S/N: 1DW672GXHEF665845 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Differential Lock, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5-25 Tires	CHOIC	E OF 2 - Lot #'s: 144, 145 2020 Cat 745 Articulated Dump Truck S/N: CAT00745P3T602347
	Usage: 6,673 Hr Asset located in : Lake Worth, TX		C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel
136	2013 John Deere 672GP AWD Motor Grader S/N: 1DW672GPHDE651559 C/W: Enclosed Cab, Air Conditioner, 14 ft /		Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 5,300 Hr Asset located in : Humble, TX
	4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 7,517 Hr Asset located in: Lake Worth, TX	145	2018 Cat 745 Articulated Dump Truck S/N: CAT00745V3T600426 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2017 US EPA Label,
137	2012 John Deere 672G AWD Motor Grader S/N: 1DW672GPKCE643998 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires		Tailgate, Steel Body Liner, Auto Lube, 29.5R25 Tires Usage: 6,080 Hr Asset located in : Humble, TX
	Usage: 12,634 Hr Asset located in: Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 146, 147, 148
139	2012 Case 865B Motor Grader S/N: HBZN0865TCAF01360 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 2,653 Hr	146	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CVTFK00176 C/W: Air Conditioner, Retarder, Engine Brake, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner, 29.5R25 Tires Usage: 14,026 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
140	2013 LeeBoy 785 Motor Grader S/N: 413760-141 C/W: Enclosed Cab, Front Scarifier, 15.5-25 Tires Usage: 3,051 Hr Asset located in: Lake Worth, TX	147	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CATFK00437 C/W: 29.5R25 Tires Usage: 13,799 Hr Asset located in: Lake Worth, TX
142	1991 Cat 120G Motor Grader S/N: 87V09411 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, 14.00-24 Tires Usage: Not Available Asset located in: Lake Worth, TX	148	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CHTFK00280 C/W: Air Conditioner, Engine Brake, Air Ride Seat, 2015 US EPA Label, 29.5R25 Tires Usage: 13,904 Hr Asset located in: Lake Worth, TX
142A	1991 Champion 740A Motor Grader S/N: 21849 C/W: Enclosed Cab, 1991 US EPA Label, 14 ft / 4.27 m Moldboard, Front Auxiliary Hydraulics, 14.00R24 Tires Usage: 4,668 Hr Asset located in: Lake Worth, TX	149	2017 Bell B50E Articulated Dump Truck S/N: B93A650EA01105727 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Steel Body Liner, 875 /65R29 Tires Usage: 9,289 Hr Asset located in: Lake Worth, TX
143	2022 John Deere 460E-II Articulated Dump	CHOIC	E OE 2 Lot #a: 150 151 152
	Truck S/N: 1DW460EBJNF713715 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Tailgate, 29.5R25 Tires Usage: 4,497 Hr Asset located in: Lake Worth, TX	150	2022 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016JMD012108 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 4,566 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
151	2021 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016HMD011998 C/W: Air Conditioner, Engine Brake, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 4,217 Hr	157	2015 Terex TA300 Articulated Dump Truck S/N: A11861065 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Steel Body Liner, 23.5R25 Tires Usage: 8,896 Hr Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	158	2014 Terex TA300 Articulated Dump Truck	
152	2021 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016LMD011997 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires			S/N: A11001282 C/W: Air Conditioner, Retarder, Rear View Camera, Steel Body Liner, 23.5R25 Tires Usage: 8,693 Hr Asset located in: Lake Worth, TX 2014 Terex TA300 Articulated Dump Truck
	Usage: 4,708 Hr Asset located in : Lake Worth, TX	159	S/N: A11001278	
152A	2022 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016KMD012141	160	C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 23.5R25 Tires Usage: 8,343 Hr Asset located in : Lake Worth, TX	
	C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 29.5R25 Tires Usage: 3,235 Hr Asset located in : Lake Worth, TX		2007 Terex TA30 Articulated Dump Truck S/N: A8941541 C/W: Air Conditioner, 23.5R25 Tires Usage: 11,471 Hr Asset located in: Lake Worth, TX	
153	2017 Bell B40E Articulated Dump Truck S/N: B93A640EJ01105751 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 29.5R25 Tires Usage: 7,600 Hr Asset located in: Humble, TX		2006 Terex TA27 Articulated Dump Truck S/N: A8681159 C/W: Air Conditioner, Steel Body Liner, 23.5R25 Tires Usage: 5,855 Hr Asset located in: Lake Worth, TX	
CHOIC	CHOICE OF 2 - Lot #'s: 154, 155		2019 John Deere 260E Articulated Dump Truck S/N: 1DW260ETCKF697666 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Heated Body,	
104	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BHT4R01959 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2013 US EPA Label, 29.5R25 Tires		Tailgate, 23.5R25 Tires Usage: 4,508 Hr Asset located in : Lake Worth, TX	
	Usage: 10,492 Hr Asset located in : Lake Worth, TX	163	2007 John Deere 250D Articulated Dump Truck S/N: DW250DT611160 C/W: Air Conditioner, 23.5R25 Tires	
155	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BKT4R01967 C/W: Air Conditioner, Rear View Camera, Air		Usage: 14,753 Hr Asset located in: Lake Worth, TX	
	Ride Seat, 2017 US EPA Label, CARB Compliant, 29.5R25 Tires Usage: 10,336 Hr Asset located in : Lake Worth, TX	164	2007 Cat 725 Articulated Dump Truck S/N: CAT00725HB1L01150 C/W: Air Conditioner, 2007 US EPA Label, Tailgate, 23.5R25 Tires Usage: 9,403 Hr	
CHOIC	E OF 4 - Lot #'s: 156, 157, 158, 159		Asset located in: Lake Worth, TX	
156	2015 Terex TA300 Articulated Dump Truck S/N: A11861079 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Steel Body Liner, 23.5R25 Tires Usage: 7,974 Hr Asset located in: Lake Worth, TX	165	2007 Cat 735 Articulated Dump Truck S/N: CAT00735AB1N01005 C/W: Air Conditioner, Retarder, Steel Body Liner, 26.5R25 Tires Usage: 22,553 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
166	Cat D35C Articulated Dump Truck S/N: Not Available C/W: Air Conditioner, Air Ride Seat, 26.5R25 Tires Usage: 9,124 Hr Asset located in: Lake Worth, TX	175	2016 John Deere 9570R Articulated Tractor S/N: 1RW9570RCGP052988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, Autosteer, Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade,
167	Cat D250E Articulated Dump Truck S/N: 5TN01384 C/W: Air Conditioner, 23.5R25 Tires Usage: 13,304 Hr Asset located in: Lake Worth, TX		LED Lights, 5 Rear Remotes, Auxiliary Hydraulics, ISOBUS, Dual IF800/70R38 Tires, Rear Wheel Weights, Front Wheel Weights Usage: 7,520 Hr Asset located in: Lake Worth, TX
168	2017 Cat 631K Motor Scraper S/N: CAT0631KVWTR00117 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 37.25R35 Tires Usage: 8,898 Hr Asset located in: Midland, TX	176	2014 Case IH Steiger 580S Scraper Tractor S/N: ZEF300648 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 2 Reverse, Requires Diesel Exhaust Fluid, 6 Rear Remotes, ISOBUS, Scraper Hitch, Dual 710/70R42 Front Tires, Front Wheel Weights, Dual 710/70R42 Rear Tires Usage: 3,479 Hr
CHOIC 169	E OF 2 - Lot #'s: 169, 170 2006 Cat 621G Motor Scraper S/N: CAT0621GPDBB00312	177	Notes: FEBRUARY 2023 - COMPLETE DEALER INSTALLED LONG BLOCK ENGINE; UNIT WAS PULLING K-TEC 1233 SCRAPER - ALSO IN THE AUCTION LOT 176; NEW PTO DRIVEN WATER PUMP; NEW BOOM HOSES AND CLAMPS Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, 33.25R29 Tires Usage: 17,540 Hr Asset located in: Lake Worth, TX		2017 MTS MT42LGP 4 Tire Hydraulic Pull Scraper S/N: MT42LGP00287 C/W: 29.5R29, Rear Hydraulic Outlets
170	2006 Cat 621G Motor Scraper S/N: CAT0621GTDBB00311		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, 33.25-29 Tires Usage: 18,093 Hr Asset located in : Lake Worth, TX	S/N: KS2538 C/W: 33 cyd Capacity, Lead Scraper, 26.5 Tires, Rear Hydraulic Outlets Usage: Not Available Notes: UNIT WAS BEING PULLED BY CAS STEIGER 580S - ALSO IN AUCTION LOT NEW PTO DRIVEN WATER PUMP; NEW I HOSES AND CLAMPS	C/W: 33 cyd Capacity, Lead Scraper, 26.5R25
171	2004 Cat 615C Series II Elevating Motor Scraper S/N: CAT0615CE9XG01708 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 29.5R29 Tires Usage: 7,020 Hr		Usage: Not Ávailable Notes: UNIT WAS BEING PULLED BY CASE STEIGER 580S - ALSO IN AUCTION LOT 178; NEW PTO DRIVEN WATER PUMP; NEW BOOM
173	2016 John Deere 9620R Articulated Tractor S/N: 1RW9620RPGE052942 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, Autosteer, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade, 6 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Rear Wheel Weights Usage: 5,943 Hr Asset located in: Lake Worth, TX	179	1994 Cat 621F 4x4 Water Wagon S/N: 4SK00164 C/W: Enclosed Cab, Air Conditioner, In-Cab Remote Controlled Water Cannon, Rear Spray, Side Spray, 83.25-29 Tires Usage: 8,377 Hr Asset located in: Lake Worth, TX
		181	2023 Cat D8 Crawler Dozer S/N: CAT000D8AAW800429 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 153 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank Ripper w/Hydraulic Pin Puller Usage: 1,311 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
182	2012 Cat D8T Crawler Dozer S/N: CAT00D8TKMLN01612 C/W: Enclosed Cab, Air Conditioner, 153 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank Ripper Usage: 11,995 Hr Asset located in: Lake Worth, TX	189	2022 Cat D6 XL Crawler Dozer S/N: CAT000D6TRBP01067 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweep 137 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTIO Usage: 1,538 Hr
185	2006 Cat D7R LGP Crawler Dozer S/N: CAT00D7RLABJ01502 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2006 US EPA Label, 192 in Wide Angle Blade w/ Dual Tilt, 36 in Single Grouser Track Shoes, Allied Winch Usage: 7,907 Hr Asset located in: Lake Worth, TX		Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 190, 191, 192
186	2023 Cat D6 LGP Crawler Dozer		C 01 0 COt # 3. 130, 131, 132
100	S/N: CAT000D6LRDC01363 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 156 in Wide PAT Blade, 36 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 627 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH NOVEMBER 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	190 191	2020 Cat D6 Crawler Dozer S/N: CAT000D6ESA900371 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide Semi-U Blade w/ Single Tilt, 23 in Single Grouser Track Shoes, Rear Auxiliary Hydraulic Usage: 2,769 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2020 Cat D6 Crawler Dozer
187	Asset located in: Lake Worth, TX 2022 Cat D6 XE Crawler Dozer S/N: CAT000D6KD5M01006 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diese Exhaust Flud, Sweeps, 144 in Wide PAT Blade, 24 in Single		S/N: CAT000D6CSA900372 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes
			Usage: 3,462 Hr
		100	Asset located in: Bridgeport, NJ
	Ripper Usage: 811 Hr Asset located in: Lake Worth, TX	192 -	2019 Cat D6 Crawler Dozer S/N: CAT000D6KHNK00387 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, GRADE with 3D, 2019 US EPA Label,
CHOICE OF 2 - Lot #'s: 188, 189 188 2022 Cat D6 XL Crawler Dozer			Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes Usage: 4,017 Hr
100	S/N: CAT000D6CRBP01052		Asset located in: North East, MD
	C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 144 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,172 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	193	2019 Cat D6T XW Crawler Dozer S/N: CAT00D6TEJNM00566 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 160 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,211 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
194	2019 Cat D6T XL Crawler Dozer S/N: CAT00D6TCNDY00513 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, US EPA Label, Requires Diesel Exhaust Fluid, 125 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 4,082 Hr Asset located in: Lake Worth, TX	200	2013 Cat D6T XL Crawler Dozer S/N: CAT00D6TCDTD01184 C/W: Enclosed Cab, Air Conditioner, Sweeps, 150 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,275 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
195	2019 Cat D6T XL Crawler Dozer	201	Asset located in: Lake Worth, TX
	S/N: CAT00D6THHYT00409 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 152 in Wide PAT Blade, 22 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 4,693 Hr Asset located in: Lake Worth, TX	201	2013 Cat D6T XL Crawler Dozer S/N: CAT00D6TAGMK01351 C/W: Enclosed Cab, Air Conditioner, Sweeps, 127 in Wide Semi-U Blade w/ Single Tilt, 22 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 8,504 Hr Asset located in: Lake Worth, TX
196	2018 Cat D6T XL Crawler Dozer	202	2012 Cat D6T XL Crawler Dozer
	S/N: CAT00D6TJ2B300199 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,831 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS		S/N: CAT00D6TCDTD00253 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Sweeps, 152 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,059 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	SECTION BELOW	303	Asset located in: Lake Worth, TX
197	Asset located in: Lake Worth, TX 2018 Cat D6T XL Crawler Dozer S/N: CAT00D6TCNDY00387 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,768 Hr Notes: NEW RAILS, TRACK PADS, SPROCKET SEGMENTS, AND TOP ROLLERS INTALLED	203	2011 Cat D6T XL Crawler Dozer S/N: CAT00D6TCGMK00352 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2011 US EPA Label, Sweeps, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,782 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	DECEMBER 3RD 2024 ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE	204	2023 Cat D5 LGP Crawler Dozer
	DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		S/N: CAT000D5KZ6A01796 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel
198	2018 Cat D6T XW Crawler Dozer S/N: CAT00D6TVJNM00416 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 163 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 8,360 Hr Asset located in: Lake Worth, TX		Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 160 in Wide PAT Blade, 33 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 878 Hr
			Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH APRIL 2026 OR 5,000 HOURS ; DECEMBER 9TH EGR REPLACED
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
205	2022 Cat D5 Crawler Dozer S/N: CAT000D5AZ2K01218 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 127 in Wide PAT Blade, 22.5 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 1,409 Hr Asset located in: Lake Worth, TX	212	2014 Komatsu D155AX-7 Crawler Dozer S/N: KMT0D118L02090176 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, 2013 US EPA Label, 156 in Wide Sigmadozer w/ Dual Tilt, 2 Cylinder Single-Shank Ripper, Sweeps, 24 in Single Grouser Track Shoes Usage: 9,795 Hr
206	2019 Cat D6N XL Crawler Dozer S/N: CAT00D6NENJN00388 C/W: Enclosed Cab, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 8,394 Hr Asset located in: Lake Worth, TX	213	Asset located in: Poteau, OK 2018 John Deere 950K LGP Crawler Dozer S/N: 1T0950KPPJF332504 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 185 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Carco Winch Usage: 5,936 Hr
207	2015 Cat D6N LGP Crawler Dozer S/N: PBA02428 C/W: Enclosed Cab, Air Conditioner, 2014 US EPA Label, Sweeps, 160 in Wide PAT Blade, 9 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 10,608 Hr Asset located in: Livingston, LA	214 215	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 214, 215 2019 John Deere 850L LGP Crawler Dozer S/N: 1T0850LXJKF360852 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 194 in
208	2012 Cat D6N XL Crawler Dozer S/N: CAT00D6NALJR00640 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 132 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 10,669 Hr Asset located in: Lake Worth, TX		Wide Angle Blade w/ Dual Tilt, Carco Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 1,640 Hr Asset located in: Robstown, TX 2019 John Deere 850L LGP Crawler Dozer S/N: 1T0850LXTKF359972 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 195 in Wide Straight Blade w/ Dual Tilt,
209	2011 Cat D6N XL Crawler Dozer S/N: CAT00D6NELJR00562 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 126 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1		Carco H85-178V Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 2,054 Hr Asset located in: Baytown, TX
	Cylinder Multi-Shank Ripper Usage: 18,107 Hr Asset located in: Lake Worth, TX	сноіс	E OF 3 - Lot #'s: 216, 217, 218
210	2008 Cat D6N LGP Crawler Dozer S/N: DJY01194 C/W: Open Operator Station, 2008 US EPA Label, 160 in Wide PAT Blade, 24 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, Rear Auxiliary Hydraulics, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,289 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	216	2019 Komatsu D65WX-18 Crawler Dozer S/N: KMT0D127PKA091866 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Carco Winch, 30 in Single Grouser Track Shoes, PLUS Undercarriage Usage: 1,389 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK
211	2007 Cat D6R XL Series III Crawler Dozer S/N: CAT00D6RCGJB00986 C/W: Enclosed Cab, Air Conditioner, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 9,162 Hr Asset located in: Lake Worth, TX		

2019 Komatsu D65WX-18 Crawler Dozer S/N: 91854 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Carco H85-178VKOMD65-17/18 Winch, 30 in Single Grouser Track Shoes Usage: 1,872 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK 2018 Komatsu D65WX-18 Crawler Dozer S/N: 91248 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Allied H6H Winch, 30 in Single Grouser Track Shoes Usage: 2,060 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	222	2019 John Deere 750K LGP Crawler Dozer S/N: 1T0750KXAKF365020 C/W: Enclosed Cab, Air Conditioner, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 5,330 Hr Asset located in: Lake Worth, TX 2017 John Deere 700K Crawler Dozer S/N: 1T0700KXCHF313276 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 2 Cylinder Multi-Shank Ripper, 560 mm Single Grouser Track Shoes Usage: 4,035 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK 2013 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US EPA Label, 142 in Wide PAT Blade, 30 in Single
SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK 2018 Komatsu D65WX-18 Crawler Dozer S/N: 91248 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Allied H6H Winch, 30 in Single Grouser Track Shoes Usage: 2,060 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	225	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 2 Cylinder Multi-Shank Ripper, 560 mm Single Grouser Track Shoes Usage: 4,035 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK 2013 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US
S/N: 91248 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Allied H6H Winch, 30 in Single Grouser Track Shoes Usage: 2,060 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	225	124 in Wide PAT Blade, 2 Cylinder Multi-Shank Ripper, 560 mm Single Grouser Track Shoes Usage: 4,035 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK 2013 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US
Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	225	2013 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US
ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	225	S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US
	4	Grouser Track Shoes
2015 Komatsu D65WX-17 Crawler Dozer S/N: KMT0D117E01002551		Usage: 2,583 Hr Asset located in : Lake Worth, TX
EPA Label, 159 in Wide PAT Blade, 30 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 13,875 Hr Asset located in : Lake Worth, TX	226	2012 Cat D6K XL Crawler Dozer S/N: CAT00D6KHFBH02165 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 132 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper
2008 Komatsu D65EX-15E0 Crawler Dozer S/N: 70954 C/W: Enclosed Cab. Air Conditioner, 135 in		Usage: 4,856 Hr Asset located in: Lake Worth, TX
Wide Semi-U Blade w/ Single Tilt, Winch, Sweeps, 24 in Single Grouser Track Shoes Usage: 6,584 Hr Asset located in : Poteau, OK	227	2022 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKCNF421869 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 27.5 in Single Grouser Trac
2022 John Deere 750L Crawler Dozer S/N: 1T0750LXCNF415326 C/W: Enclosed Cab, Air Conditioner, Air Ride		Shoes Usage: 1,047 Hr Asset located in: Beaumont, TX
Exhaust Fluid, 155 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,349 Hr	CHOIC	E OF 2 - Lot #'s: 228, 229
Asset located in: Lake Worth, TX	228	2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKTMF401153 C/W: Open Operator Station, US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide 18 in Single Grouser Track Shoes Usage: 469 Hr Asset located in: Lake Worth, TX
2022 John Deere 750L Crawler Dozer S/N: 1T0750LXJNF417535 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 5,287 Hr		
	C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 159 in Wide PAT Blade, 30 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 13,875 Hr Asset located in: Lake Worth, TX 2008 Komatsu D65EX-15E0 Crawler Dozer S/N: 70954 C/W: Enclosed Cab, Air Conditioner, 135 in Wide Semi-U Blade w/ Single Tilt, Winch, Sweeps, 24 in Single Grouser Track Shoes Usage: 6,584 Hr Asset located in: Poteau, OK 2022 John Deere 750L Crawler Dozer S/N: 1T0750LXCNF415326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 155 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 5,349 Hr Asset located in: Lake Worth, TX 2022 John Deere 750L Crawler Dozer S/N: 1T0750LXJNF417535 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper	C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 159 in Wide PAT Blade, 30 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 13,875 Hr Asset located in: Lake Worth, TX 2008 Komatsu D65EX-15E0 Crawler Dozer S/N: 70954 C/W: Enclosed Cab, Air Conditioner, 135 in Wide Semi-U Blade w/ Single Tilt, Winch, Sweeps, 24 in Single Grouser Track Shoes Usage: 6,584 Hr Asset located in: Poteau, OK 2022 John Deere 750L Crawler Dozer S/N: 1T0750LXCNF415326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 155 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 5,349 Hr Asset located in: Lake Worth, TX 2022 John Deere 750L Crawler Dozer S/N: 1T0750LXJNF417535 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 5,287 Hr

Lot #	Details	Lot #	Details
229	2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKPMF392830 C/W: Enclosed Cab, Air Conditioner, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper	235	2012 Cat D5K2 XL Crawler Dozer S/N: CAT0D5K2VKWW00232 C/W: Open Operator Station, 2012 US EPA Label, 106 in Wide PAT Blade, 20 in Single Grouser Track Shoes Usage: 7,645 Hr Asset located in: Lake Worth, TX
	Usage: 1,549 Hr Asset located in : Lake Worth, TX	236	2016 Cat D5K2 LGP Crawler Dozer
230	2019 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKKKF349894 C/W: Enclosed Cab, Air Conditioner, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,283 Hr Asset located in: Lake Worth, TX		S/N: CAT00D5KKKY202228 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 124 in Wide PAT Blade, 26 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 12,759 Hr Asset located in: Humble, TX
231	2017 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKAHF307207 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics	237	2012 Cat D5K2 LGP Crawler Dozer S/N: CAT0D5K2HKYY00309 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 125 in Wide PAT Blade, 26 in Single Grouser Track Shoes Usage: 9,847 Hr Asset located in: Lake Worth, TX
	Usage: 8,434 Hr		2019 John Deere 450K LGP Crawler Dozer
Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 232, 233			S/N: 1T0450KXKKF347727 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 114 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 2,420 Hr
232	2017 John Deere 650KLGP Crawler Dozer	000	Asset located in: Humble, TX
	S/N: 1T0650KKTHF316190 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 7,369 Hr Asset located in: Humble, TX	240	2021 Cat D2 Crawler Dozer S/N: CAT000D2TXKM00230 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 116 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 2,453 Hr Asset located in: Lake Worth, TX
233	2017 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKHHF316153 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 8,590 Hr Asset located in: Humble, TX		2016 Cat D4K2 LGP Crawler Dozer S/N: CAT00D4KJKR202288 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 121 in Wide PAT Blade, 25 in Single Grouser Track Shoes, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 5,218 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT
234	2013 Komatsu D61PX-23 Crawler Dozer S/N: 30310 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2013 US EPA Label, 156 in Wide PAT Blade, Allied H6H Winch, 34 in Single Grouser Track Shoes Usage: 5,210 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX

Lot #	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 241, 242		247	2004 Cat D5G LGP Crawler Dozer S/N: CAT00D5GARKG01013 C/W: Open Operator Station, Sweeps, 120 in Wide DAT Blade, 18 in Single Crouser Track
241	2012 Cat D4K2 XL Crawler Dozer S/N: CAT0D4K2CKMM00228 C/W: Open Operator Station, Air Ride Seat,		Wide PAT Blade, 18 in Single Grouser Track Shoes Usage: 5,087 Hr Asset located in : Lake Worth, TX
	2012 US EPA Label, Sweeps, 114 in Wide PAT Blade, 18 in Single Grouser Track Shoes, SystemOne Undercarriage, 2 Cylinder Multi- Shank Ripper Usage: 3,515 Hr Asset located in : Lake Worth, TX	249	1996 Cat D6E Crawler Dozer S/N: 2MJ02195 C/W: Open Operator Station, 146 in Wide Straight Blade w/ Dual Tilt, Winch, 560 mm Single Grouser Track Shoes Usage: 10,574 Hr
242	2011 Cat D4K XL Crawler Dozer S/N: CAT00D4KHMMM00764 C/W: Open Operator Station, Air Ride Seat, 2015 US EPA Label, 109 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper		Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	Usage: 2,915 Hr	250	1994 Cat D6E Tack Tractor
243	Asset located in: Lake Worth, TX 2008 Cat D4K XL Crawler Dozer S/N: CAT00D4KLMMM00181 C/W: Open Operator Station, Air Ride Seat, Sweeps, 115 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 3,155 Hr Asset located in: Lake Worth, TX		S/N: 2MJ1574 C/W: Open Operator Station, Air Compressor, 22 in Single Grouser Track Shoes, (2) Lincoln Arc Welders, Front-Mounted Air Compressor Usage: 37,271 Hr
			Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO
244	2021 Cat D1 Crawler Dozer		3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	S/N: CAT000D1EXKF00156 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 115 in Wide PAT Blade, 16 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,144 Hr Asset located in: Lake Worth, TX	251	2008 John Deere 700J Combination Pipelayer w/ 2008 Midwestern M540 Conversion S/N: T0700JX156344 C/W: Canopy, 3 Lever Boom Control, 2007 US EPA Label, Hydraulic Hoists, 30 in Single Grouser Track Shoes
245	2005 John Deere 700J XLT Crawler Dozer S/N: T0700JX110023 C/W: Enclosed Cab, Air Conditioner, 2005 US EPA Label, 120 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics, EQUIPMENT- FROM-PULICE-CONSTRUCTION		Usage: 6,999 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	Usage: Not Available Asset located in : Humble, TX		F OF 2 Let #0: 052 052 054
	•	HOIC	E OF 3 - Lot #'s: 252, 253, 254
CHOIC	E OF 2 - Lot #'s: 246, 247	252	1977 Cat 561C Pipelayer w/ 2007 Conversion
246	2005 Cat D5G LGP Crawler Dozer S/N: CAT00D5GVRKG01267 C/W: Open Operator Station, 127 in Wide PAT Blade, 24 in Single Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX		S/N: 92J776 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft 0 in Side Boom, Hydraulic Hoists Usage: 997 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.

This catalog was created at December 10, 2024 03:25:22 PM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
253	1975 Cat 561C Pipelayer S/N: 92J593 C/W: 3 Lever Boom Control, 18 in Single Grouser Track Shoes, 25 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 539 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK		E OF 2 - Lot #'s: 258, 259 1971 Cat D4D Pipelayer w/ Midwestern D4D Conversion S/N: 60J2695 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft 0 in Side Boom, Hydraulic Hoists, Winch Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
254	1973 Cat 561C Pipelayer S/N: 92J413 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom, Hydraulic Hoists Usage: 903 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.	259	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK 1966 Cat D4D Pipelayer w/ Midwestern 0D4D Conversion S/N: 86A1705 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft Side Boom,
CHOIC 255	Asset located in: Lahoma, OK E OF 2 - Lot #'s: 255, 256 1969 Cat 561C Pipelayer w/ Midwestern		Hydraulic Hoists Usage: 6,536 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	M561C Conversion S/N: 92J233 C/W: 3 Lever Boom Control, 510 mm Single Grouser Track Shoes, 20 ft 0 in Side Boom, Mechanical Hoists Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	260	1956 Cat D7C Pipelayer w/ Conversion S/N: 17A4488 C/W: 560 mm Single Grouser Track Shoes, 20 ft Side Boom, Mechanical Hoists Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
256	1969 Cat 561C Pipelayer S/N: 92J238 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom, Hydraulic Hoists Usage: 1,795 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	261	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF402857 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 101 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper
257	1982 Cat D5B Pipelayer S/N: 44X01116 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 17 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 52 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	262	Usage: Not Available Asset located in: Lake Worth, TX 2021 John Deere 755K Crawler Loader S/N: 1T0755KXPMF399113 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,525 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
263	2021 John Deere 755K Crawler Loader S/N: 1T0755KXKMF400262 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Manual Coupler, 94 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 6,008 Hr	271	2009 Cat 939C Crawler Loader S/N: CAT0939CC6DS02032 C/W: Open Operator Station, 84 in Multi- Purpose Bucket, 18 in Double Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 2,351 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	272	2007 Cat 815F Soil Compactor
264	2021 John Deere 755K Crawler Loader S/N: 1T0755KXVMF409838 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, 95 in Bucket, 22 in Double Grouser Track Shoes, Multi-Shank Ripper Usage: 5,530 Hr Asset located in: Lake Worth, TX		S/N: CAT0815FCBYN00307 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, 38 in Compaction Wheel Width, 146 in Straight Blade w/ Single Tilt, Fast Fuel Usage: 10,824 Hr Asset located in: Lake Worth, TX
265	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF411719 C/W: Enclosed Cab, Requires Diesel Exhaust Fluid, 99 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,012 Hr Asset located in: Lake Worth, TX	273	2013 Hamm 3410P Padfoot Drum Compactor S/N: H1791920 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Deutz TCD2012L042V 134 hp 4.03 L Diesel Engine, 84 in Drum Usage: 6,559 Hr Asset located in: Lake Worth, TX
		274	2016 Dynapac CA2500PD Padfoot Drum
CHOICE 266	2017 John Deere 605K Crawler Loader S/N: 1T0605KXCHE310174 C/W: Open Operator Station, Air Ride Seat, 88 in Bucket, 18 in Double Grouser Track Shoes, 2	274A	Compactor S/N: 10000167PHA020589 C/W: Open Operator Station, 2017 US EPA Label, Cummins QSF 4 Cylinder 89 kW 3.8 L Diesel Engine, 84 in Drum Usage: 2,102 Hr Asset located in: Lake Worth, TX
	Cylinder Multi-Shank Ripper Usage: 1,822 Hr Asset located in: Lake Worth, TX		Vibromax 1106 Padfoot Drum Compactor S/N: JKC8305502 C/W: Enclosed Cab, Diesel Engine, 82 in Drum
267	2017 John Deere 605K Crawler Loader S/N: 1T0605KXPHE310856 C/W: Open Operator Station, Air Ride Seat, 88	275	Usage: 2,512 Hr Asset located in: Lake Worth, TX
	in Bucket, 18 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,632 Hr Asset located in: Lake Worth, TX		2008 Dynapac CA250PD Padfoot Drum Compactor S/N: 6582US5658 C/W: Open Operator Station, 4 Cylinder Diese Engine, 84 in Drum Usage: 3,598 Hr Asset located in: Lake Worth, TX
268	2015 Cat 963D Crawler Loader S/N: CAT0963DTLCS02294		
	C/W: Enclosed Cab, Air Conditioner, 101 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,156 Hr Asset located in : Lake Worth, TX	276	2007 Cat CP563E Padfoot Drum Compactor S/N: CATCP563ACNT01503 C/W: Open Operator Station, Cat 6 Cylinder Diesel Engine, 84 in Drum, Leveling Blade
269	2005 Cat 963C Crawler Loader		Usage: 755 Hr Asset located in : Lake Worth, TX
	S/N: CAT0963CCBBD01372 C/W: Enclosed Cab, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 24,275 Hr Asset located in: Lake Worth, TX	277	2003 Cat CP-433E Padfoot Drum Compactor S/N: CATCP433JCFK00238 C/W: Open Operator Station, 2003 US EPA Label, Perkins 3PKXLO3.9AKI 4 Cylinder 74.5 kW 3.99 L Diesel Engine, 66 in Drum, Leveling
269A	2004 Cat 963C Crawler Loader S/N: CAT0963CPBBD00676 C/W: Enclosed Cab, Air Conditioner, Manual Coupler, 100 in Bucket, 22 in Double Grouser Track Shoes Usage: 11,701 Hr Asset located in: Lake Worth, TX		Blade Usage: 1,105 Hr Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
278	2014 Bomag BW145PDH Padfoot Drum Compactor S/N: 101586021003 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2014 US EPA Label, Kubota v3307 4 Cylinder 37 kW 3.3 L Diesel Engine, 60 in Drum Usage: Not Available Asset located in: Lake Worth, TX	286	2013 Bomag BW211D-50 Smooth Drum Compactor S/N: 901583531097 C/W: Open Operator Station, 2013 US EPA Label, Duetz 4 Cylinder 121 hp 3.6 L Diesel Engine, 84 in Drum Usage: 3,618 Hr Asset located in: Lake Worth, TX
279	2007 Bomag BW145PDH-3 Padfoot Drum Compactor S/N: 901581491236 C/W: Open Operator Station, Diesel Engine, 58 in Drum Usage: 616 Hr Asset located in: Lake Worth, TX	287	2013 Dynapac CA2500D Smooth Drum Compactor S/N: 10000138C0A012121 C/W: Open Operator Station, 2013 US EPA Label, Cummins 4 Cylinder 130 hp 4.5 L Diesel Engine, 84 in Drum Usage: Not Available Asset located in: Lake Worth, TX
280	Sakai SV201TB-1 Padfoot Drum Compactor S/N: LSV2720110 C/W: Open Operator Station, Tier 4, 2008 US EPA Label, Kubota V3307-D1-T-ET04 4 Cylinder 55.4 kW 3.3 L Diesel Engine, 55 in Drum, Leveling Blade Usage: 1,882 Hr Asset located in: Lake Worth, TX	288	2006 Cat CS563E Smooth Drum Compactor S/N: CATCS563PCNG01830 C/W: Open Operator Station, Cat 6 Cylinder Diesel Engine, 84 in Drum Usage: 4,090 Hr Asset located in: Lake Worth, TX
281	289 281 Volvo SD45 Padfoot Drum Compactor S/N: VCE00S45L0S229308 C/W: Open Operator Station, Kubota Diesel Engine, 54 in Drum Usage: 833 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	- 289	2005 Ingersoll Rand SD122DX Smooth Drum Compactor S/N: 183705 C/W: Open Operator Station, 4 Cylinder Diesel Engine, 84 in Drum Usage: Not Available Asset located in: Lake Worth, TX
		290	2019 Volvo SD75B Padfoot Drum Compactor S/N: VCE0S75BK0S241348 C/W: Open Operator Station, Tier 4, Volvo Diesel Engine, 66 in Drum Usage: 1,190 Hr
283	Asset located in: Fort Smith, AR 2021 XCMG CV123PDU Smooth Drum Compactor S/N: XUG01231CMJE04323 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Cummins 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum, Padfoot Shell Kit		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR
	Usage: 692 Hr Asset located in : Lake Worth, TX	291	2019 Dynapac CA1500D Smooth Drum Compactor
284	2018 Volvo SD115B Smooth Drum Compactor S/N: VCES115BA0S236505 C/W: Open Operator Station, Air Ride Seat, 2018 US EPA Label, Volvo D4J 4 Cylinder 148 hp 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 85 in Drum, Padfoot Shell Kit	S/N: 10000160AKA024661 C/W: Open Operator Station, Swivel Controls, 2021 US EPA Label, Deutz Cylinder 3.6 L Diesel Engine, 66 in D Usage: 749 Hr Asset located in: Lake Worth, TX 292 2015 Dynapac CA1500D Padfoot Dr Compactor S/N: 10000156CFA016214 C/W: Open Operator Station, 2014 U Label, Cummins QSB3.3 100 hp 3.20 Engine, 66 in D Drum, Leveling Blade, EQUIPMENT-FROM-SUNSTATE-EQU Usage: 1,459 Hr Notes: SUNSTATE EQUIPMENT CO. PEOPLE YOU CAN DEPEND ON	C/W: Open Operator Station, Swivel Operator Controls, 2021 US EPA Label, Deutz TD3.6L4 4 Cylinder 3.6 L Diesel Engine, 66 in Drum Usage: 749 Hr
	Usage: 2,594 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 10000156CFA016214 C/W: Open Operator Station, 2014 US EPA
285	2015 Volvo SD115 Padfoot Drum Compactor S/N: VCES115BL0S236313 C/W: Open Operator Station, 2017 US EPA Label, Volvo D4J 4 Cylinder 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 1,488 Hr Asset located in: Lake Worth, TX		Engine, 66 in Drum, Leveling Blade, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,459 Hr Notes: SUNSTATE EQUIPMENT CO. RENTAL

Lot #	Details	Lot #	Details
293	2015 Bomag BW177DH-5 Smooth Drum Compactor S/N: 101586041089 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 66 in Drum Usage: Not Available	298	2011 Cat CB54 Double Drum Roller S/N: CAT0CB54VJLM00434 C/W: Open Operator Station, Swivel Operator Controls, Cat C4.4 4 Cylinder Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	299	2006 Cat CB-534D XW Double Drum Roller S/N: CATCB534KEAA00412 C/W: Open Operator Station, Swivel Operator
294	2010 Volvo SD70D Smooth Drum Compactor S/N: VC500670A00225225 C/W: Open Operator Station, Tier 3, 2009 US EPA Label, Kubota V3800-DI-T-ET02 4 Cylinder 74 kW Diesel Engine, 66 in Drum Usage: 2,841 Hr		Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	300	2005 Cat CB-534D XW Double Drum Roller
294A	2007 Ingersoll Rand SD70D-TF Smooth Drum Compactor S/N: 196662 C/W: Open Operator Station, 2007 US EPA Label, Cummins b4.5 4 Cylinder 78 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM-	301A	S/N: CATCB534AEAA00397 C/W: Open Operator Station, Swivel Operator Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	WATKINS-CONSTRUCTION Usage: 3,215 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		2015 Case DV210C Double Drum Roller S/N: DDDD210CNENTL2010 C/W: Open Operator Station, Swivel Operator Controls, 2014 US EPA Label, Deutz 100 hp 3.62 L Diesel Engine, 66 in Compaction Width, Water System
294B	2004 Ingersoll Rand SD70D-TF Smooth Drum		Usage: 1,004 Hr Asset located in: Lake Worth, TX
	Compactor S/N: 177760 C/W: Open Operator Station, 2004 US EPA Label, Cummins B4.5 4 Cylinder 79 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Notes: THE AGE AND CONDITION OF THE	302	2016 Cat CB36B Double Drum Roller S/N: CATCB36BAM3600111 C/W: Open Operator Station, Cat 4 Cylinder Diesel Engine, 55 in Compaction Width, Water System, Edge Cutter Usage: Not Available Asset located in: Lake Worth, TX
	MACHINE INDICATES MORE HOURS THAN SHOWN ON THE HOUR METER; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	303	2013 Hamm HD13VV Double Drum Roller S/N: H2011675 C/W: Open Operator Station, Kubota V2203 4 Cylinder 2.2 L Diesel Engine, 51 in Compactio
295	2015 Hamm H5i Smooth Drum Compactor S/N: H2220266		Width, Edge Cutter Usage: 1,104 Hr Asset located in : Lake Worth, TX
	C/W: Open Operator Station, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 54 in Drum Usage: 220 Hr Asset located in: Lake Worth, TX	СНОІСІ	E OF 2 - Lot #'s: 304, 305
296	2018 Bomag BW124DH-5 Smooth Drum Compactor S/N: 861586571071 C/W: Open Operator Station, 2018 US EPA Label, Kubota V2403-CR-EF04 4 Cylinder 33.6 kW 2.4 L Diesel Engine, 47.5 in Drum Usage: Not Available Asset located in: Lake Worth, TX	304	2023 Hamm HD12VV Double Drum Roller (Unused) S/N: WGH0H230CHAA06595 C/W: Open Operator Station, E-Stops, Tier 4, 2020 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 22 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
305	2022 Hamm HD12VV Double Drum Roller S/N: WGH0H230KHAA05864 C/W: Open Operator Station, E-Stops, Tier 4, 2022 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 63 Hr	315	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072138 C/W: Open Operator Station, Honda 2 Cylinder Gasoline Engine, 35.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	316	Wacker Neuson RD11A Double Drum Roller
305A	2019 Hamm HD12VV Double Drum Roller S/N: WGH0H230AHAA02985 C/W: Open Operator Station, Kubota 3 Cylinder 1.7 hp Engine, 47 in Compaction Width, Water System Usage: 3,656 Hr Asset located in: Lake Worth, TX	310	S/N: 5613749 C/W: Open Operator Station, 2014 US EPA Label, Honda GX 630 2 Cylinder Gasoline Engine, 35 in Compaction Width Usage: 594 Hr Asset located in: Humble, TX
307	Volvo DD24 Double Drum Roller S/N: 196371 C/W: Open Operator Station, 3 Cylinder Diesel Engine, 47.25 in Compaction Width, Water System Usage: 2,886 Hr Asset located in: Lake Worth, TX	316A	Elgin Crosswind on 2013 Freightliner M2 106 Sweeper Truck S/N: 1FVACXDT5DHFB1562 C/W: Cummins 6.7 L Diesel 200 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 11R22.5, Spring Suspension, Auxiliary Engine, Under Body Broom Usage: 44,365 Mi
СНОІС	E OF 2 - Lot #'s: 308, 309		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; RITCHIE-BROSENERGY
308	2021 Hamm HD10CVV Double Drum Roller	017	Asset located in: Lake Worth, TX
309	S/N: WGH0H263LHHAA00855 C/W: Open Operator Station, Tier 4, 2021 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 39 in Compaction Width, Water System Usage: 148 Hr Asset located in: Lake Worth, TX 2021 Hamm HD10CVV Double Drum Roller	317	S/N: JALE5B16267903657 C/W: Isuzu 4 Cylinder Diesel 190 hp Engine, 2005 US EPA Label, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 134 ir Wheelbase, Kubota Auxiliary Engine, Vacuum Sweeper, Under Body Broom, Gutter Brooms Usage: 93,999 Mi Asset located in: Lake Worth, TX
	S/N: WGH0H263THAA00778 C/W: Open Operator Station, Kubota D1105 Diesel Engine, 39 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX		
310	2017 Hamm HD10C VV Double Drum Roller S/N: H1994782 C/W: Open Operator Station, Tier 4, 2016 US		
	EPA Label, Kubota D1005-EF05 3 Cylinder 14.8 kW 1.0 L Diesel Engine, 39 in Compaction Width, Water System Usage: 892 Hr Asset located in : Lake Worth, TX		2019 Broce RJT-350 Self-Propelled Broom S/N: 411566 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2018 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine
CHOIC	CHOICE OF 2 - Lot #'s: 314, 315		Usage: Not Available Asset located in: Lake Worth, TX
314	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072137 C/W: Open Operator Station, Honda 2 Cylinder Gasoline Engine, 36 in Compaction Width Usage: Not Available Asset located in: Lake Worth, TX		

Lot#	Details	Lot #	Details
СНОІС	CHOICE OF 2 - Lot #'s: 320, 321		2014 Superior DT80J Self-Propelled Broom S/N: 814869 C/W: Enclosed Cab, Air Conditioner, 8 ft
S/N: 409370 C/W: Enclose Broom, Water	C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label,		Broom, Water System, 2014 US EPA Label, John Deere 4045TF290 4 Cylinder 4.5 L Diese Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,536 Hr
	Kubota V3600-T-ET03 4 Cylinder 55.4 kW 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,930 Hr Asset located in : Lake Worth, TX	СНОІС	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 329, 330
321	2015 Broce KR350 Self-Propelled Broom S/N: 409369 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder 55.4 kW 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 698 Hr Asset located in: Lake Worth, TX	330 330A	2001 Broce BB250B Self-Propelled Broom S/N: 304993 C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 18.5 kW 1.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
322	2015 Broce KR-350 Self-Propelled Broom S/N: 409307		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2001 Broce BB250B Self-Propelled Broom S/N: 304910 C/W: Open Operator Station, 8 ft Broom, Wate System, Tier 4, 2015 US EPA Label, Kubota V1505-EF01 4 Cylinder 18.5 kW 1.5 L Diesel
	C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, Kubota 4 Cylinder Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,522 Hr Asset located in: Oklahoma City, OK		
323	2015 Broce KR350 Self-Propelled Broom S/N: 409308 C/W: Enclosed Cab, Air Conditioner, 8 ft		Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 100 Hr Asset located in : Lake Worth, TX
	Broom, Water System, 2015 US EPA Label, Kubota V3600-T-ET03 4 Cylinder 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,137 Hr Asset located in: Lake Worth, TX		2001 Broce BB250B Self-Propelled Broom S/N: 305062 C/W: Open Operator Station, 8 ft Broom, Wate System, Tier 4, 2018 US EPA Label, Kubota V1505 18.2 kW 1.5 L Diesel Engine Usage: 663 Hr Asset located in: Lake Worth, TX
324	2015 Broce KR350 Self-Propelled Broom S/N: 409371		
	C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder Diesel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 1,187 Hr Asset located in: Lake Worth, TX	333	2000 Rosco RB48 Self-Propelled Broom S/N: 36730 C/W: Enclosed Cab, Air Conditioner, 7 ft Broom, Water System, Cummins 4 Cylinder Diesel Engine Usage: 1,635 Hr Asset located in: Lake Worth, TX
325A	2014 Broce CRT350 Self-Propelled Broom S/N: 408677 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, 2013 US EPA Label, Cat 4 Cylinder 60.5 kW 4.4 L Diesel Engine Usage: 5,095 Hr Asset located in: Lake Worth, TX	334	2021 John Deere 870G LC Tracked Excavator S/N: 1FF870GXJMF890112 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, 9 ft 8 in Stick, 36 in Double Grouser Track Shoes, 96 in Digging Bucket, Counterweight Removal System
326	2014 Superior DT80J Self-Propelled Broom S/N: 814877 C/W: Enclosed Cab, Air Conditioner, 8 ft 7 in Broom, Water System, 2014 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 691 Hr Asset located in: Lake Worth, TX		Usage: 5,764 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
334A	2015 Komatsu PC650LC-8E0 Tracked Excavator S/N: 65343 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 10 ft Stick, 36 in Triple Grouser Track Shoes, 80 in Digging Bucket, Counterweight Removal System Usage: 18,316 Hr	340A	2014 John Deere 470GLC Tracked Excavator S/N: 1FF470GXTCE470692 C/W: Requires Diesel Exhaust Fluid, 13 ft 5 in Stick, 35.5 in Triple Grouser Track Shoes, 72 in Digging Bucket Usage: 12,526 Hr Asset located in: Lake Worth, TX
		341	2013 Hitachi ZX470LC-5B Tracked Excavator
335	Asset located in: Lake Worth, TX 2015 Kobelco SK500LC-9 Tracked Excavator S/N: YS1203617 C/W: Air Conditioner, 11 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 8,275 Hr		S/N: HCMJAA70A00030283 C/W: Air Ride Seat, Tier 4, US EPA Label, 9 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 68 in Digging Bucket, Catwalks Usage: 11,455 Hr Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	342	2016 John Deere 380G LC Tracked Excavator
CHOICI 337	OICE OF 2 - Lot #'s: 337, 338 2017 Cat 349FL Tracked Excavator S/N: CAT0349FCHPD10110 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Hydraulic Quick Coupler,		S/N: 1FF380GXTGF900147 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 10,290 Hr Asset located in: Lake Worth, TX
		343	2019 Cat 336 Tracked Excavator
	30 in V-Bottom Bucket Usage: 13,440 Hr Asset located in : Lake Worth, TX	343	S/N: CAT00336PDKS00399 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA
338	2017 Cat 349F L Tracked Excavator S/N: CAT0349FAHPD10053 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2016 US EPA Label, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Manual Quick Coupler, 30 in V-		Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 12,251 Hr Asset located in: Lake Worth, TX 2019 Cat 336 Tracked Excavator
	Bottom Bucket Usage: 13,635 Hr		S/N: CAT00336LDKS01786
339	Asset located in: Lake Worth, TX 2013 Cat 349E Tracked Excavator S/N: CAT0349EPMPZ00695		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, 33.5 in Triple Grouser Track Shoes, 43 in Digging Bucket Usage: Not Available
	C/W: Air Conditioner, Straight Travel Pedal, Rear View Camera, 2013 US EPA Label, 12 ft 4		Asset located in: Lake Worth, TX
	in Stick, Auxiliary Hydraulic Plumbing, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket Usage: 10,831 Hr	СНОІС	E OF 4 - Lot #'s: 345, 346, 347, 348
	Asset located in: San Antonio, TX	345	2018 Cat 336FL Tracked Excavator
340	2021 Hyundai HX480L Tracked Excavator S/N: HHKHKB01JL0000163 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 72 in Digging Bucket, Auto Lube Usage: 6,810 Hr Asset located in: Humble, TX		S/N: CAT0336FARKB21335 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 44 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,625 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
346	2018 Cat 336FL Tracked Excavator S/N: TZA20175 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 43 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,883 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	351	2016 Cat 336FL Tracked Excavator S/N: CAT0336FCTZA00440 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 56 in Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 12,821 Hr Asset located in: Lake Worth, TX	
347	2018 Cat 336FL Tracked Excavator	-сноіс	E OF 2 - Lot #'s: 352, 353	
34 7	S/N: CAT0336FKTZA20109 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 46 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,561 Hr Notes:; PLEASE SEE A PERSONAL NOTE	352	2015 Cat 336FL Tracked Excavator S/N: CAT0336FJRKB00903 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2014 US EPA Label, 12 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 31 in Digging Bucket, Hydraulic Thumb Usage: 7,433 Hr Asset located in: Midland, TX	
	FROM THE SELLER IN THE DOCUMENTS	252		
	SECTION BELOW Asset located in: Lake Worth, TX	353	2015 Cat 336FL Tracked Excavator S/N: RKB00900	
348	2018 Cat 336FL Tracked Excavator S/N: CAT0336FKRKB21071 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 42 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,613 Hr		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Rock Guards, 39 in Digging Bucket Usage: 6,370 Hr Asset located in: Midland, TX	
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	сноіс	E OF 2 - Lot #'s: 354, 355	
	Asset located in: Lake Worth, TX			
349	2017 Cat 336F L Tracked Excavator S/N: CAT0336FLTZA10137 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 13,138 Hr Asset located in: Lake Worth, TX	354	S/N: CAT0336EJRZA00234 C/W: Air Conditioner, Straight Trave Ride Seat, Control Pattern Changer, Camera, 2013 US EPA Label, 12 ft 1 34 in Triple Grouser Track Shoes, 44 Cleanup Bucket, EQUIPMENT-FROM CONSTRUCTION Usage: 5,605 Hr	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 12 ft 10 in Stick, 34 in Triple Grouser Track Shoes, 48 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION
350	2016 Cat 336FL Tracked Excavator S/N: CAT0336FJSSN00477 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Cab Screens, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 10,564 Hr Asset located in: Humble, TX		FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
355	2013 Cat 336 EL Tracked Excavator S/N: CAT0336EEFJH00483 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 45 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 7,199 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	361 361A	2017 Komatsu PC360LC 11 Tracked Excavator S/N: KMTPC256HHWA35865 C/W: Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 60 in Digging Bucket Usage: 15,343 Hr Asset located in: Lake Worth, TX 2017 Komatsu PC360LC-11 Tracked Excavator S/N: KMTPC256AHWA35992 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4,
356	2013 Cat 336EL Tracked Excavator S/N: CAT0336ECFJH00355 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, 33.5 in Triple Grouser Track Shoes, 50 in Digging Bucket Usage: 8,712 Hr Asset located in: Midland, TX		2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 13 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 63 in Digging Bucket, Manual Thumb, Nye 516541, PC 360 Grapple Usage: 5,789 Hr Asset located in: Midland, TX
357	2012 Cat 336 EL Tracked Excavator S/N: CAT0336EKBZY01618 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 34 in Triple Grouser Track Shoes, 42 in Digging Bucket,	362	2012 Komatsu PC360LC-10 Tracked Excavator S/N: KMTPC24202070045 C/W: Air Conditioner, 2011 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 56 in Digging Bucket, Hydraulic Thumb Usage: 12,043 Hr Asset located in: Lake Worth, TX
	EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 9,409 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	363	2017 XCMG XE360U Tracked Excavator S/N: XUG03600KHKA00061 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, US EPA Label, 8 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 823 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	E OF 2 - Lot #'s: 358, 359		THE INSPECTION REPORT Asset located in: Humble, TX
358	2012 Cat 336E L Tracked Excavator S/N: CAT0336EVBZY01509 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 58 in Digging Bucket Usage: 12,654 Hr Asset located in: Lake Worth, TX	364	·
359	2012 Cat 336E L Tracked Excavator S/N: CAT0336EKBZY00808 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2011 US EPA Label, 10 ft 6		Usage: 5,806 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	in Stick, 33.5 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 14,076 Hr Asset located in : Lake Worth, TX	365	2010 Komatsu PC350LC-8 Tracked Excavator S/N: KMTPC19IJ54A10246 C/W: Air Conditioner, Rear View Camera, 2010 US EPA Label, 10 ft 6 in Stick, 33.5 in Triple
360	2010 Cat 336D Tracked Excavator S/N: CAT0336DKW3K01214 C/W: Air Conditioner, 2010 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 34 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: 89,205 Hr Asset located in: Lake Worth, TX		Grouser Track Shoes, 56 in Digging Bucket Usage: 11,202 Hr Asset located in: Lake Worth, TX

			r age 20 01 301
Lot #	Details	Lot #	Details
366	2012 John Deere 350G LC Tracked Excavator S/N: 1FF350GXCCE808325 C/W: Air Conditioner, Air Ride Seat, 2011 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic		E OF 2 - Lot #'s: 370, 371
	Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: Not Available	370	2020 Cat 330 Tracked Excavator S/N: CAT00330TWCH10651 C/W: Air Conditioner, Straight Travel Pedal, Air
СНОІС	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 367, 368		Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-
367	2022 Cat 330 Tracked Excavator S/N: CAT00330/WCH30051		WATKINS-CONSTRUCTION Usage: 3,428 Hr
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control,		Notes: COMES WITH UNUSED HYDRAULIC THUMB
	2022 US EPA Label, Requires Diesel Exhaust		Asset located in: Lake Worth, TX
	Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,104 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS;	371	2020 Cat 330 TC Tracked Excavator S/N: CAT00330JWCH10654 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging
	PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,072 Hr
368	2021 Cat 330 Tracked Excavator S/N: CAT00330AWCH20489		Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-		Asset located in: Lake Worth, TX
	Wired for Grade Control, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket,	СНОІСІ	E OF 3 - Lot #'s: 372, 373, 374
	Tool Control; Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,395 Hr	372	2020 Cat 330GC Tracked Excavator S/N: CAT00330CGDW10069
	Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket,
	Asset located in: Lake Worth, TX	_	Tool Control; EQUIPMENT-FROM-WATKINS-
369	2020 Cat 330 Tracked Excavator S/N: CAT00330JWCH10184 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Surround View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,590 Hr	THROUGH MARCH 2026 OR 3000 PLEASE SEE A PERSONAL NOTE F	Usage: 1,885 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW

Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW

Lot #	Details	Lot #	Details
373	2020 Cat 330GC Tracked Excavator S/N: CAT00330CSCZ10029 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,443 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE	de	2020 Cat 330GC Tracked Excavator S/N: CAT00330LGDW10049 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Cleanup Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,882 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
	SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	378	2019 Cat 330 Tracked Excavator S/N: CAT00330TLHW00257 C/W: Air Conditioner, Rear & Side View
374	2020 Cat 330GC Tracked Excavator S/N: CAT00330VGDW10047 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US		Cameras, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 5,554 Hr Asset located in : Lake Worth, TX
	EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick	379	2019 Cat 330F L Tracked Excavator
	Check Valve, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,462 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX		S/N: CAT0330FJHCK20408 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,557 Hr
СНОІС	E OF 3 - Lot #'s: 375, 376, 377		Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
375	2020 Cat 330GC Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT00330KGDW10058 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft	СНОІС	E OF 3 - Lot #'s: 380, 381, 382
	8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 38 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,503 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	380	2018 Cat 330F L Tracked Excavator S/N: MBX20638 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT-FROM-WATKINS-
376	2020 Cat 330GC Tracked Excavator S/N: CAT00330ESCZ10028 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 35 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,558 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		CONSTRUCTION Usage: 3,586 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
381	2018 Cat 330F L Tracked Excavator S/N: CAT0330FEMBX20643 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 3,732 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	386	2017 John Deere 300G LC Tracked Excavator S/N: 1FF300GXKHF730514 C/W: Air Conditioner, 2017 US EPA Label, CARB Compliant, 13 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 28 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 43 in Digging Bucket, Hydraulic Thum Usage: 6,335 Hr Asset located in: Lake Worth, TX 2017 Volvo ECR305CL Tracked Excavator S/N: VCECR305V00110701	
	Asset located in: Lake Worth, TX		C/W: Air Conditioner, Straight Travel Pedal,	
382	2018 Cat 330F L Tracked Excavator S/N: CAT0330FCMBX20666 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control;		Control Pattern Changer, 2016 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 6,005 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: El Paso, TX	
	EQUIPMENT-FRÖM-WATKINS-CONSTRUCTION Usage: 3,894 Hr	388	Hyundai R300LC-9A Tracked Excavator	
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		S/N: HHKHZ803ED0000030 C/W: Air Conditioner, Rear View Camera, 2012 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket	
			Usage: 4,396 Hr	
CHOIC	E OF 2 - Lot #'s: 383, 384		Asset located in: Lake Worth, TX	
383	2018 Cat 330F L Tracked Excavator S/N: CAT0330FTHCK20095 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION	389	2018 Volvo EC250ELR Tracked Excavator S/N: VCEC250EK00310554 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 25 ft 6 in Boom, 26 ft Stick, 36 in Triple Grouser Track Shoes, 60 in Cleanup Bucket Usage: 4,986 Hr Asset located in: Lake Worth, TX	
	Usage: 4,836 Hr Notes : COMES WITH UNUSED HYDRAULIC THUMB	СНОІС	CHOICE OF 6 - Lot #'s: 390, 391, 392, 393, 394, 395	
	Asset located in: Lake Worth, TX	390	2019 Komatsu PC290LC-11 Tracked Excavator	
384	2018 Cat 330F L Tracked Excavator S/N: CAT0330FPMBX20257 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,485 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		S/N: JKK73093 C/W: Air Conditioner, Rear View Camera, 10 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 42 in Cleanup Bucket Usage: 3,632 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
	Asset located in: Lake Worth, TX	-	Accel located in Michigan, OK	
385	2012 Volvo EC300DL Tracked Excavator S/N: VCEC300DC00210349 C/W: Straight Travel Pedal, 2012 US EPA Label, 10 ft Stick, 36 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 9,162 Hr Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
391	2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27915 C/W: Air Conditioner, Control Pattern Changer, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 5 in Stick, 31.5 in Triple Grouser Track Shoes Usage: 4,248 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	396	2009 Cat 329DL Tracked Excavator S/N: CAT0329DLJHJ00330 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Manual Thumb, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 10,025 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
392	2019 Komatsu PC290LC-11 Tracked Excavator S/N: KMTPC255AJKK73097 C/W: Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 0	CHOICE	E OF 2 - Lot #'s: 397, 398
	ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31.5 in Triple Grouser Track Shoes, Rock Guards, 48 in Digging Bucket Usage: 4,542 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	397	2019 Cat 326F L Tracked Excavator S/N: CAT0326FPFBR20575 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 34 in Digging Bucket, Hydraulic Thumb, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 3,230 Hr
393	2018 Komatsu PC290LC-11 Tracked Excavator	1	Notes: COMES WITH UNUSED HYDRAULIC THUMB
393	S/N: A27917		Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Control Pattern Changer, 2018 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 43 in Cleanup Bucket Usage: 4,865 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	398	2019 Cat 326F L Tracked Excavator S/N: CAT0326FLFBR20679 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,973 Hr
394	2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27916 C/W: Air Conditioner, Air Ride Seat, Tier 4, 2018		Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,473 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	399	2019 Cat 326F L Tracked Excavator S/N: CAT0326FEFBR20653 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 9,619 Hr Asset located in: Lake Worth, TX
395	2018 Komatsu PC290LC-11 Tracked Excavator	400	2015 Cat 326FL Tracked Excavator S/N: CAT0326FVWGL00317
	S/N: KMTPC255CJWA27918 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 5,920 Hr Asset located in: Lake Worth, TX		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 54 in Digging Bucket Usage: 9,061 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
401	2020 LiuGong 888925E Tracked Excavator S/N: 888925EZJLU004037 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 2,191 Hr Asset located in: Humble, TX	407	2023 Cat 323 Tracked Excavator S/N: CAT00323LNDL20614 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION
402	2016 John Deere 245G LC Tracked Excavator S/N: 1FF245GXJGF800123 C/W: Air Conditioner, Control Pattern Changer, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket		Usage: 490 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Usage: 6,879 Hr Asset located in: Lake Worth, TX	408	2023 Cat 323 Tracked Excavator
404	2012 Cat 324 EL Tracked Excavator S/N: CAT0324EPPNW00408 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 8,469 Hr		S/N: CAT00323JNDL20736 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 866 Hr
	Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
405	2012 Cat 324E L Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT0324EHPNW00497 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA Label, 9 ft 5 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Manual Thumb Usage: 10,768 Hr	CHOIC	E OF 2 - Lot #'s: 409, 410 2022 Cat 323 Tracked Excavator S/N: CAT00323CNDL20262
	Asset located in: Lake Worth, TX	4	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat Control Pattern Changer Rear & Side

CHOICE OF 2 - Lot #'s: 406, 407

406 2023 Cat 323 Tracked Excavator

S/N: CAT00323ENDL20616 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 240 Hr

Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW

Asset located in: Lake Worth, TX

Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION

Usage: 120 Hr

Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW

Lot #	Details	Lot #	Details
410	2022 Cat 323 Tracked Excavator S/N: CAT00323CNDL20219 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Surround View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 34 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 156 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	414	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ11197 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,958 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
411	2022 Cat 323 Tracked Excavator S/N: NDL20218 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Aprillers Hydroulis Dlumbing, 32 in Triple	CHOICI 415	E OF 3 - Lot #'s: 415, 416, 417 2019 Cat 323 Tracked Excavator S/N: CAT00323CRAZ11070 C/W: Air Conditioner, Straight Travel Pedal, Air
	Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 814 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	_	Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,062 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS
CHOIC	E OF 3 - Lot #'s: 412, 413, 414		SECTION BELOW Asset located in: Lake Worth, TX
412	2019 Cat 323 Tracked Excavator S/N: CAT00323ARAZ10687 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,393 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	416	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10972 C/W: Air Conditioner, Straight Travel Pedal, Rear & Side View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.25 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,205 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	417	2019 Cat 323 Tracked Excavator
413	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10552 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,527 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		S/N: CAT00323KRAZ11087 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,253 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
418	2019 Cat 323 Tracked Excavator S/N: RAZ10628 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 4,636 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	422	2018 Cat 323 Tracked Excavator S/N: CAT00323JRAZ00303 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,641 Hr Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
CHOIC	E OF 4 - Lot #'s: 419, 420, 421, 422	СНОІСІ	E OF 3 - Lot #'s: 424, 425, 426
419	2018 Cat 323 Tracked Excavator S/N: CAT00323LRAZ00176 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, ; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,439 Hr Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	424	2018 Cat 323 Tracked Excavator S/N: CAT00323ARAZ00290 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,808 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
420	2018 Cat 323 Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT00323ERAZ00293 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,103 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	425	2018 Cat 323 Tracked Excavator S/N: CAT00323KRAZ00266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,852 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
421	2018 Cat 323 Tracked Excavator	426	2018 Cat 323 Tracked Excavator
	S/N: CAT00323HRAZ00227 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,498 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	420	S/N: CAT00323LRAZ00288 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,063 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
427	2018 Cat 323 Tracked Excavator S/N: CAT00323HRAZ01166 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 48 in Digging Bucket, Thumb Bracket Usage: 4,053 Hr Asset located in: Lake Worth, TX	432	2018 John Deere 210G LC Tracked Excavator S/N: 1FF210GXPJF526258 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 700 mm Triple Grouser Track Shoes 42 in Digging Bucket Usage: 5,427 Hr Notes: COMES WITH IRONCLAD ASSURANCE.
428	2017 Cat 323F L Tracked Excavator S/N: CAT0323FTXCF10375 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,557 Hr Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	434	SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK 2012 Hitachi ZX210LC-5N Tracked Excavator S/N: 1FFDCJ70TCE330100 C/W: Air Conditioner, 2012 US EPA Label, 9 ft 7 in Stick, 32 in Triple Grouser Track Shoes, 38 in Digging Bucket Usage: 8,923 Hr Asset located in: Lake Worth, TX
429	Asset located in: Lake Worth, TX 2015 Cat 323FL Tracked Excavator S/N: CAT0323FCXCF00606 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2014 US EPA Label, 10 ft Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket	435	2017 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257CGTC80149 C/W: Air Conditioner, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 34 in Digging Bucket Usage: 15,090 Hr Asset located in: Lake Worth, TX
430	Usage: 10,595 Hr Asset located in: Lake Worth, TX 2022 John Deere 210GLC Tracked Excavator S/N: 1FF210GXENF529761 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, 9 ft 7 in Stick, 27.5 in Triple Grouser Track Shoes, 24 in Digging Bucket	436	2020 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257KKWA12903 C/W: Air Conditioner, Rear View Camera, 2019 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Breaker Usage: 5,171 Hr Asset located in: Lake Worth, TX
СНОІС	Usage: 2,416 Hr Asset located in: Lake Worth, TX OICE OF 2 - Lot #'s: 431, 432		2013 Komatsu PC210LC-10 Tracked Excavator S/N: KMTPC243C02450042 C/W: Air Conditioner, Cab Screens, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple
431	2018 John Deere 210G LC Tracked Excavator S/N: 1FF210GXLJF526477 C/W: Air Conditioner, Straight Travel Pedal, Air		Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, Auto Lube Usage: 14,738 Hr Asset located in: Lake Worth, TX
	Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 4,374 Hr Asset located in: Lake Worth, TX	438	2013 Komatsu PC210LC-10 Tracked Excavator S/N: KMTPC243H02450734 C/W: Air Conditioner, 2013 US EPA Label, 10 ft 2 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 8,296 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
439	2019 XCMG XE210U Tracked Excavator S/N: XUGA210BVKKA00083 C/W: Air Conditioner, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 1 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 23 in Digging Bucket Usage: 721 Hr Asset located in: Humble, TX	444	2020 Cat 320 Tracked Excavator S/N: CAT00320CHEX20219 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 42 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION
440A	2018 Hitachi ZX210LC-5N Tracked Excavator S/N: 1FFDCJ70JEE330489 C/W: Air Conditioner, Cab Screens, 8 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket Usage: 11,575 Hr Asset located in: Lake Worth, TX	сноіс	Usage: 1,582 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 445, 446
441	2022 Cat 320GC Tracked Excavator S/N: CAT00320HLKS20318 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera, 2022 US EPA Label, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 1,075 Hr Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH DECEMBER 2025 OR 5,000 HOURS Asset located in: Lake Worth, TX	445	2020 Cat 320 Tracked Excavator S/N: CAT00320KHEX20265 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 37 in Digging Bucket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,321 Hr
	E OF 3 - Lot #'s: 442, 443, 444		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	2020 Cat 320 Tracked Excavator S/N: CAT00320JHEX20266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 30 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,298 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2025 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	446	2020 Cat 320 Tracked Excavator S/N: CAT00320AHEX20207 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,462 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
443	2020 Cat 320 Tracked Excavator S/N: CAT00320HHEX20212 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,419 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
СНОІС	CHOICE OF 4 - Lot #'s: 447, 448, 449, 450		2019 Cat 320 Tracked Excavator S/N: CAT00320LHEX11329 C/W: Rear & Side View Cameras, 2018 US EPA	
S/N: CAT00320CHEX C/W: Air Conditioner, Ride Seat, Rear & Side Wired for Grade Contr Requires Diesel Exhau Auxiliary Hydraulic Plu Grouser Track Shoes, Tool Control; EQUIPM CONSTRUCTION	2019 Cat 320 Tracked Excavator S/N: CAT00320CHEX12081		Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 3,617 Hr	
	C/W: Air Conditioner, Straight Travel Pedal, Air		Asset located in: Lake Worth, TX	
	Usage: 1,445 Hr	452	2018 Cat 320 Tracked Excavator S/N: CAT00320THEX01650 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 2,890 Hr	
	Notes: EMISSIONS SYSTEM WARRANTY		Asset located in: Lake Worth, TX	
	THROUGH FEBRUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	453	2017 Cat 320FL Tracked Excavator S/N: CAT0320FKYBM10403 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 9 ft 7 in Stick,	
448	2019 Cat 320 Tracked Excavator S/N: CAT00320VHEX11425		31.5 in Triple Grouser Track Shoes, 27 in Cleanup Bucket Usage: 6,755 Hr	
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for		Asset located in: Midland, TX	
	Grade Control, 2018 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION	СНОІС	E OF 2 - Lot #'s: 454, 455	
	Usage: 1,539 Hr	454	2014 Cat 320EL Tracked Excavator	
	Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	S/N: CAT0320EEWBK01967 C/W: Air Conditioner, Straight Travel Peda Ride Seat, Rear & Side View Cameras, 20° EPA Label, 9 ft 7 in Stick, 31 in Triple Grou Track Shoes, 31 in Digging Bucket, Hydra Thumb, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 4,345 Hr	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2012 US EPA Label, 9 ft 7 in Stick, 31 in Triple Grouser	
449	Asset located in: Lake Worth, TX 2019 Cat 320 Tracked Excavator		Thumb, EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
	S/N: HEX11857 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31 in		Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION	
			Asset located in: Lake Worth, TX	
	Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,702 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	455	S/N: CAT0320EAWBK02595 C/W: Air Conditioner, Straight Travel Pe Ride Seat, Control Pattern Changer, Rea Camera, Tier 4, 2013 US EPA Label, 9 ft Stick, 32 in Triple Grouser Track Shoes, Digging Bucket, EQUIPMENT-FROM-WA CONSTRUCTION	S/N: CAT0320EAWBK02595 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-
450	2019 Cat 320 Tracked Excavator S/N: CAT00320KHEX12604 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side		Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	
	View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Cleanup Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,129 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	456	2014 Cat 320 EL Tracked Excavator S/N: CAT0320ECWBK02652 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Cab Screens, Rear View Camera, 2013 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb Usage: 10,473 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
457	2014 Cat 320 EL Tracked Excavator S/N: CAT0320EPWBK02668 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US	CHOICE OF 2 - Lot #'s: 461, 462	
	EPA Label, 8 ft 6 in Stick, 31 in Triple Grouser Track Shoes, Hydraulic Breaker Usage: 18,583 Hr Asset located in: Lake Worth, TX	461	2012 Cat 320 EL Tracked Excavator S/N: CAT0320EKWBK00212 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging
CHOIC	E OF 3 - Lot #'s: 458, 459, 460		Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,775 Hr
458	58 2013 Cat 320 EL Tracked Excavator S/N: CAT0320ELWBK01626 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,381 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
		462	2012 Cat 320E L Tracked Excavator S/N: CAT0320EJWBK00387 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION
	Asset located in: Lake Worth, TX	_	Usage: 7,386 Hr
459	2013 Cat 320 EL Tracked Excavator S/N: CAT0320EKREE00514 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,468 Hr		Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
		СНОІС	E OF 2 - Lot #'s: 463, 464
	Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	463	2006 Komatsu PC200-LC-7 Tracked Excavator S/N: C50926 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in
460	2013 Cat 320 EL Tracked Excavator		Stick, 31 in Triple Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX
	S/N: CAT0320EHWBK02230 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,019 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM	464	2006 Komatsu PC200LC-8 Tracked Excavator S/N: KMTPC180J54A88082 C/W: 2006 US EPA Label, 9 ft 8 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 17,098 Hr Asset located in: Lake Worth, TX
	THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	465	2006 John Deere 200C LC Tracked Excavator S/N: FF200CX507611 C/W: Air Conditioner, Control Pattern Changer, Tier 2, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 800 mm Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 8,607 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.

Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
466	2019 Cat 316FL Tracked Excavator S/N: CAT0316FKYDL21033 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 24 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 3,683 Hr Asset located in: Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 473, 474
		473	2019 Cat 313F L GC Tracked Excavator S/N: ZGS00152 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 10 ft Stick, 27.5 in Track Shoes, Hydraulic
467	2013 Cat 316E L Tracked Excavator S/N: CAT0316EJDZW00889 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2012 US EPA Label, 9 ft 6 in Stick,		Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 2,826 Hr Asset located in : Lake Worth, TX
	Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 40 in Digging Bucket, Manual Thumb Usage: 14,360 Hr Asset located in: Lake Worth, TX	474	2019 Cat 313F L GC Tracked Excavator S/N: ZGS00141 C/W: Air Conditioner, Rear & Side View Cameras, 2018 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple
468	2020 Cat 315FLCR Tracked Excavator S/N: CAT0315FJTDY14173 C/W: Air Conditioner, Rear & Side View		Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,843 Hr Asset located in: Lake Worth, TX
	Cameras, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Boom Check Valves, 27.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 1,758 Hr		E OF 4 - Lot #'s: 475, 476, 477, 478
	Asset located in: St. Rose, LA	475	2019 Sany SY135C Tracked Excavator S/N: SY013JBJM3218 C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 48 in Cleanup Bucket Usage: 6,558 Hr Asset located in: Lake Worth, TX
469	2019 Kobelco SK140SRLC-5 Tracked Excavator S/N: YH08015117 C/W: Air Conditioner, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 2,068 Hr Asset located in: Baton Rouge, LA		
		476	2019 Sany SY135C Tracked Excavator S/N: SY013JBJL6958
470	2012 Kobelco SK140SRLC Tracked Excavator S/N: YH0608690 C/W: 2011 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, 31 in Digging Bucket		C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 6,291 Hr Asset located in: Lake Worth, TX
	Usage: 6,456 Hr Asset located in : Humble, TX		2018 Sany SY135C Tracked Excavator
471	2019 Cat 313F L GC Tracked Excavator S/N: CAT0313FEHDK10481 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, CARB Compliant, 10 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 19.5 in		S/N: SY013EBJL6208 C/W: Air Conditioner, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 4,154 Hr Asset located in: Lake Worth, TX
		478	2018 Sany SY135C Tracked Excavator S/N: SY013JBJL2718 C/W: Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 43 in Cleanup Bucket Usage: 5,357 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
478A	2017 Case CX130D Tracked Excavator S/N: DAC130K7NHS7D1310 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 34 in Digging Bucket, Manual Thumb Usage: 934 Hr Asset located in: Lake Worth, TX	485	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88H00215332 C/W: Air Conditioner, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Boom Check Valves, Backfill Blade, 17.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,792 Hr Asset located in: Lake Worth, TX
479	2004 Kobelco SK480LC Tracked Excavator	486	2021 Bobcat E85 Tracked Excavator
	S/N: YS06U0308 C/W: US EPA Label, 11 ft 6 in Stick, 36 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 15,245 Hr Asset located in : Lake Worth, TX	400	S/N: B48414957 C/W: 2020 US EPA Label, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, 24 in Digging Bucket, Thumb Bracket Usage: 1,865 Hr
480	1996 Cat 350L Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: 3ML00899 C/W: Air Conditioner, Cab Screens, 10 ft 6 in Stick, 29.5 in Double Grouser Track Shoes, Catwalks, EQUIPMENT-FROM-PULICE- CONSTRUCTION		E OF 2 - Lot #'s: 488, 489
	Usage: Not Available Asset located in : Humble, TX	488	2022 Cat 308 CR Tracked Excavator S/N: CAT00308HGG805305
480A	2004 Komatsu PC200LC-7L Tracked Excavator S/N: A86747 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 51 in Digging Bucket Usage: 11,171 Hr Asset located in: Lake Worth, TX		C/W: Air Ride Seat, Rear View Camera, 2021 US EPA Label, Swing Boom, 7 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 22 in Digging Bucket, Manual Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,546 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE
CHOIC	E OF 4 - Lot #'s: 482, 483, 484, 485		SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
482	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88H00215346 C/W: Air Conditioner, Swing Boom, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,742 Hr Asset located in: Lake Worth, TX	489	2021 Cat 308 CR Tracked Excavator S/N: CAT00308VGG803324 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, Tier 4, 2020 US EPA Label, Swing Boom, 6 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Track Shoes w/Rubber Inserts, 21 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,093 Hr
483	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88K00215385 C/W: Air Conditioner, Tier 4, 2019 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in		Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Rubber Tracks, 22 in Digging Bucket, Hydraulic Thumb Usage: 2,972 Hr Asset located in : Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 490, 491
484	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88J00215338 C/W: Air Conditioner, 2019 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 901 Hr Asset located in: Lake Worth, TX	490	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETMC500734 C/W: Air Conditioner, 2018 US EPA Label, CARB Compliant, 5 ft 5 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 38 in Digging Bucket Usage: 1,492 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
491	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308EVPC800527 C/W: Air Conditioner, 2018 US EPA Label, 5 ft 5 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 28 in Digging Bucket Usage: 1,694 Hr	CHOICE 496	E OF 2 - Lot #'s: 496, 497 2015 Cat 308E2 CR Tracked Excavator S/N: CAT0308EKFJX02698 C/W: Air Conditioner, Air Ride Seat, Control	
СНОІС	Asset located in: Lake Worth, TX E OF 4 - Lot #'s: 492, 493, 494, 495		Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb	
492	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELFJX10405 C/W: Air Ride Seat, Rear View Camera, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.75 in Triple Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 36 in Digging Bucket,	497	Bracket, EQUIPMENT-FROM-WATKIN CONSTRUCTION Usage: 3,281 Hr Notes : PLEASE SEE A PERSONAL NO THE SELLER IN THE DOCUMENTS SI BELOW	Usage: 3,281 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION
	Hydraulic Thumb Usage: 3,681 Hr Asset located in: Lake Worth, TX		2014 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETFJX00852 C/W: Air Conditioner, Control Pattern Changer,	
493	2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELFJX07584 C/W: Air Conditioner, Air Ride Seat, 2016 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, 35.5 in Digging Bucket, Hydraulic Thumb Usage: 3,891 Hr		2013 US EPA Label, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Double Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,625 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION	
494	Asset located in: Lake Worth, TX 2017 Cat 308E2 CR Tracked Excavator		BELOW Asset located in: Lake Worth, TX	
	S/N: CAT0308ETFJX07574 C/W: Air Conditioner, 2016 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 4,033 Hr Asset located in: Lake Worth, TX	498	2014 Cat 308E2 CR Mini Excavator S/N: CAT0308ELFJX00151 C/W: Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, 36 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Lake Worth, TX	
495	2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308EEFJX08253 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Single Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb, Strickland ZX85 MK2 Hydraulic Thumb	499	2020 John Deere 75G Tracked Excavator S/N: 1FF075GXTKJ017240 C/W: 2019 US EPA Label, 6 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Track Shoes w/Rubber Pads, 30 in Bucket Usage: 2,121 Hr Asset located in: Lake Worth, TX	
	Usage: 4,117 Hr Asset located in: Lake Worth, TX	500	2021 Bobcat E60R2 Mini Excavator S/N: B4GR11148 C/W: Enclosed Cab, Air Conditioner, 2020 US EPA Label, Swing Boom, 6 ft 4 in Stick, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,271 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
	E OF 15 - Lot #'s: 501, 502, 503, 504, 505, 506, 507, 99, 510, 511, 512, 513, 514, 515 2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55HPAJAL584 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb	Changer, 2023 US EPA Label, 5 ft 5 in Stic	(Unused) S/N: YMRVIO55CPAJAL420 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb, Yanmar A-T30-V55BKP Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS
	Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	507	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55KPAJAL429 C/W: Control Pattern Changer, 2023 US EPA
502			Label, Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	508 2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55APAJAL461 C/W: 2023 US EPA Label, Swing Boom Stick, Auxiliary Hydraulic Plumbing, 16 Rubber Tracks, Hydraulic Quick Coupl Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX 509 2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55KPAJAL415 C/W: US EPA Label, Swing Boom, 5 ft Auxiliary Hydraulic Plumbing, 16 in Ru Tracks, Hydraulic Plumbing, 16 in Ru Tracks, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX 510 2023 Yanmar VIO55 Yanmar ViO 55 M Excavator (Unused) S/N: YMRVIO55KPAJAK958 C/W: 5 ft 5 in Stick, Auxiliary Hydraulic	S/N: YMRVIO55APAJAL461 C/W: 2023 US EPA Label, Swing Boom, 5 ft 6 in
503	<u> </u>		Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS
	15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO55KPAJAL415 C/W: US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber
504	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55EPAJAL456 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Backfill		Bucket, Hýdraulic Thumb Usage: 3 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS
	Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO55KPAJAK958 C/W: 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber
505	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55JPAJAL786 C/W: Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		Bucket, Hydraulic Thumb Usage: 4 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS

Lot #	Details	Lot #	Details
511	S/N: YMRVIO55LPAJAL848 C/W: 2023 US EPA Label, 5 ft 5 in Stick,	СНОІС	E OF 3 - Lot #'s: 516, 517, 518
		516	2019 Cat 305.5E2 Mini Excavator S/N: CAT3055EPWE209294 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 5 ft Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 863 Hr
512	2023 Yanmar ViO55-6A Mini Excavator		Asset located in: Lake Worth, TX
512	(Unused) S/N: YMRVI055VPAJAL846 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr	517	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055EVWE205445 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 5 ft Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 792 Hr Asset located in: Lake Worth, TX
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS	518	
	Asset located in: Lake Worth, TX	518	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055ETWE204417
513 2023 Yanmar (Unused) S/N: YMRVIO5 C/W: 2023 US Stick, Auxiliary Rubber Tracks	S/N: YMRVIO55EPAJAL702 C/W: 2023 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in		C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 4 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.75 in Triple Grouser Track Shoes, Manual Quick Coupler, 28 in Digging Bucket Usage: 910 Hr Asset located in: Lake Worth, TX
	Digging Bucket, Hydraulic Thumb Usage: 2 Hr	518A	2018 Cat 305E2 CR Mini Excavator
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	0104	S/N: CAT0305EPH5M06269 C/W: Swing Boom, 5 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, 18 in Digging Bucket
514	2023 Yanmar ViO55-6A Mini Excavator (Unused)		Usage: 3,912 Hr Asset located in: Lake Worth, TX
	S/N: YMRVIO55LPAJAL454 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 15.5 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE	520	2019 Sany SY50U Mini Excavator S/N: SY005CBJZ2158 C/W: Enclosed Cab, Swing Boom, 4 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 18 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX
	DOCUMENTS	522	2017 John Deere 50G Mini Excavator
515	2023 Yanmar VIO55-6A Mini Excavator (Unused) S/N: YMRVIO55HPAJAL553 C/W: 2016 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 17 in Rubber Tracks, Hydraulic Quick Coupler, Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	022	S/N: 1FF050GXCGH285257 C/W: Control Pattern Changer, 2016 US EPA Label, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 4,712 Hr Asset located in: Lake Worth, TX
		523	2016 John Deere 50G Mini Excavator S/N: 1FF050GXPGH284631 C/W: Control Pattern Changer, 2016 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 19 in Digging Bucket, Thumb Bracket Usage: 6,107 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
	CHOICE OF 10 - Lot #'s: 525, 526, 527, 528, 529, 530, 531, 532, 533, 534		2023 Yanmar VIO35-6A Mini Excavator (Unused) S/N: YMRVIO35VPAJAT865 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in
525	2023 Yanmar VIO35-6A Mini Excavator (Unused) S/N: YMRVIO35APAJAT785 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in		Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE
	Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick		DOCUMENTS Asset located in: Lake Worth, TX
	Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr	531	2023 Yanmar VIO35 Mini Excavator (Unused)
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO35VAPJAT722 C/W: 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging
526	2023 Yanmar VIO35 Mini Excavator		Bucket, Hydraulic Thumb Usage: Not Available
020	S/N: YMRVIO35APAJAT947 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading		Notes : WARRANTY AVAILABLE - SEE DOCUMENTS
			Asset located in: Lake Worth, TX
		532	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35KPAJAT868
			C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket,
	Asset located in: Lake Worth, TX	-	Hydraulic Thumb Usage: 4 Hr
527	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35JPAJAT581 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS
			Asset located in: Lake Worth, TX
		533	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35LPAJAT232 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks,
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS		
528	Asset located in: Lake Worth, TX 2023 Yanmar VIO35 Mini Excavator (Unused)		Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb
	S/N: YMRVIO35HPAJAT989 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket,		Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS
			Asset located in: Lake Worth, TX
	Hydraulic Thumb Usage: 3 Hr	534	2023 Yanmar ViO35-6A Mini Excavator
	Notes : WARRANTY AVAILABLE - SEE DOCUMENTS		(Unused) S/N: YMRVIO35HPAJAU091
	Asset located in: Lake Worth, TX		C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick
529	2023 Yanmar ViO35-6A Mini Excavator (Unused)		Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr
	S/N: YMRVIO35LPAJAT772		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS
	C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr		Asset located in: Lake Worth, TX
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS		
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
	CHOICE OF 10 - Lot #'s: 535, 536, 537, 538, 539, 540, 541, 542, 543, 544 535 2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35LPAJAU087 C/W: Swing Boom, 4 ft 6 in Stick, Backfill	540	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35JPAJAT970 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE	
	Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: Not Available	541	DOCUMENTS Asset located in: Lake Worth, TX 2023 Yanmar ViO35-6A Mini Excavator	
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		(Unused) S/N: YMRVIO35TPAJAT700 C/W: Swing Boom, 4 ft 6 in Stick, Backfill	
536	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35EPAJAT671 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	
	Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	542	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35PPAJAT794 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill	
537	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35VPAJAT851 C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr		Blade, 12 in Rubber Tracks, H Coupler, 24 in Digging Bucke Usage: 3 Hr Notes : WARRANTY AVAILAB DOCUMENTS	Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	543	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35LPAJAS623 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks,	
538	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35CPAJAT808 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE		Hydraulic Quick Coupler, 24 in Digg Hydraulic Thumb Usage: 3 Hr Notes : WARRANTY AVAILABLE - SE	Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading
	DOCUMENTS Asset located in: Lake Worth, TX	544	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35APAJAT625 C/W: Swing Boom, 4 ft 6 in Stick, Backfill	
539	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35VPAJAU322 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr		Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	
N D	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX	545	Yanmar V1035-5B Mini Excavator S/N: YMRVI035J8YY53169 C/W: 2008 US EPA Label, Swing Boom, 4 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket, Thumb Bracket Usage: 7,897 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
546	2021 John Deere 35G Mini Excavator S/N: 1FF035GXLLK291536 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 10 in Digging Bucket Usage: 1,292 Hr Asset located in: Lake Worth, TX	553	2007 John Deere 35D Mini Excavator S/N: FF035DX237345 C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket Usage: 8,759 Hr Asset located in: Lake Worth, TX	
СНОІС	CHOICE OF 4 - Lot #'s: 547, 548, 549, 550		2016 Bobcat E35l Mini Excavator S/N: AUYM13355 C/W: Enclosed Cab, Control Pattern Changer,	
547	2021 John Deere 35G Mini Excavator S/N: 1FF035GXVMK293316 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in		Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket Usage: 2,462 Hr Asset located in: Midland, TX	
	Rubber Tracks, Manual Quick Coupler, 18 in Bucket Usage: 466 Hr Asset located in : Lake Worth, TX	555	2012 Komatsu PC35MR Mini Excavator S/N: KMTPC201C04018745 C/W: 2012 US EPA Label, Swing Boom, 5 ft 6 in Stick, Backfill Blade, 12 in Track Shoes w	
548	2021 John Deere 35G Mini Excavator S/N: 1FF035GXCMK292861 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary		/Rubber Pads, 24 in Cleanup Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Lake Worth, TX	
	Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 729 Hr Asset located in: Lake Worth, TX	556	2016 Hitachi ZX35U-5N Mini Excavator S/N: HCMADG60E00273351 C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in	
549	2021 John Deere 35G Mini Excavator S/N: 1FF035GXVMK292537 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary		Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 6,514 Hr Asset located in: Humble, TX	
	Hydraulic Plumbing, 11.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 922 Hr Asset located in : Lake Worth, TX	558	558 2018 Cat 303E CR Mini Excavator S/N: CAT0303EAHHM02733 C/W: Tier 4, 2017 US EPA Label, Swing Bool	
550	2021 John Deere 35G Mini Excavator S/N: 1FF035GXCMK292536 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 12 in		Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 590 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS	
	Bucket Usage: 1,134 Hr Asset located in : Lake Worth, TX		SECTION BELOW Asset located in: Lake Worth, TX	
CHOIC	E OF 2 - Lot #'s: 551, 9623C	сноіс	E OF 2 - Lot #'s: 559, 560	
551	2017 John Deere 35G Mini Excavator S/N: 1FF035GXEHK279948 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 24 in	559	2016 Cat 303E CR Mini Excavator S/N: CAT0303EVHHM01984 C/W: Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-	

Digging Bucket, Thumb Bracket Usage: Not Available

Asset located in: Lake Worth, TX

FROM-WATKINS-CONSTRUCTION Usage: 2,021 Hr

Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION **BELOW**

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
560	S/N: CAT0303EAHHM01212 C/W: Control Pattern Changer, Tier 4, 2015 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	568	2021 John Deere 17G Mini Excavator S/N: 1FF017GXLMK231337 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 473 Hr Asset located in: Lake Worth, TX	
	Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	569	2021 John Deere 17G Mini Excavator S/N: 1FF017GXTMK231117 C/W: Control Pattern Changer, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing,	
563	2017 Bobcat E26 Mini Excavator S/N: B3JE13055 C/W: Swing Boom, 3 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket		Backfill Blade, Manual Quick Coupler, 12 in Digging Bucket Usage: 479 Hr Asset located in : Lake Worth, TX	
	Usage: 2,327 Hr Asset located in: Lake Worth, TX	569A	2018 Yanmar SV08-1B Mini Excavator S/N: YMRSV08YEJBJBF106 C/W: 2017 US EPA Label, Swing Boom, 2 ft 3 in	
564	2017 Takeuchi TB260 Mini Excavator S/N: 126102065 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Swing Boom, 5 ft 6 in Stick,	571	Stick, Auxiliary Hydraulic Plumbing, B Blade, 7 in Rubber Tracks, Expandabl Tracks, 14 in Digging Bucket Usage: 1,259 Hr	Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Expandable Width Tracks, 14 in Digging Bucket Usage: 1,259 Hr
	Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Thumb Bracket, EQUIPMENT FROM UNITED RENTALS Usage: 3,025 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX JCB HD110W Wheel Excavator S/N: JCBW11CFEN3148944 C/W: Air Conditioner, Air Ride Seat, Control	
565	2021 Bobcat E20 Mini Excavator S/N: B3BL19286 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in		Pattern Changer, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9-20 Tires, Steelwrist X12 650-650 GR FPL Tiltrotator Attachment Usage: 202 Hr Asset located in: Lake Worth, TX	
	Digging Bucket Usage: 753 Hr Asset located in : Lake Worth, TX	572	2004 Cat M318C Wheel Excavator S/N: CATM318CPBCZ00846 C/W: 2 Piece Hyd. Boom, 9 ft 4 in Stick,	
СНОІС	E OF 4 - Lot #'s: 566, 567, 568, 569	<i>A</i> S	Auxiliary Hydraulic Plumbing, Front and Rear Stabilizers, 10.00x20 Tires, 78 in Hydraulic Tilting Bucket Usage: Not Available	
566	2022 John Deere 17G Mini Excavator		Asset located in: Lake Worth, TX	
	S/N: 1FF017GXJNK232661 C/W: Control Pattern Changer, 2022 US EPA Label, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 401 Hr Asset located in: Lake Worth, TX	574	2003 Mantis 3612 18 ton Telescopic Crawler Crane S/N: 36250 C/W: Anti Two-Block, PAT DS160 Load Moment Indicator, 2002 US EPA Label, 29 ft Minimum 71 ft Maximum Boom Length, Rooster Sheave, Overhaul Ball, Counterweight Removal System, 30 in Triple Grouser Track	
567	2021 John Deere 17G Mini Excavator S/N: 1FF017GXPMK231345 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Bucket Usage: 467 Hr Asset located in: Lake Worth, TX		Shoes, Expandable Width Tracks Usage: 7,472 Hr Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
575	2011 Link-Belt HTC8675 75 ton 8x4 Series II Hydraulic Truck Crane S/N: 1F9P9K221CL028751 C/W: Air Conditioner, 13310 hrs Carrier Engine, Cat C13 8 Cylinder Diesel Carrier Engine, Air Conditioner, Anti Two-Block, Hirschmann Load Moment Indicator, 34 ft Minimum 113 ft Maximum Boom Length, Rooster Sheave, Bifold Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 356 lb Overhaul Ball, 18400 lb Counterweight, Counterweight Removal System Usage: 1,190 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	579	2012 Grove RT765E-2 65 ton 4x4x4 Rough Terrain Crane S/N: 232495 C/W: Air Conditioner, Anti Two-Block, Hirschmann iScout Load Moment Indicator, 7421 hrs Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 240 hp 6.7 L Diesel Engine, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 56 ft Bifold Swingaway Offset Jib, 1252 lb 66 ton Capacity Johnson 5 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball, Counterweight Removal System Usage: 7,421 Hr Asset located in: Humble, TX 2008 Link-Belt RTC 8050 II 50 ton 4x4x4 Rough
576	2001 Link-Belt RTC-8075 70 ton 4x4x4 Rough Terrain Crane S/N: D7J1-5709LB C/W: Air Conditioner, Anti Two-Block, Microguard 534 Load Moment Indicator, 4994 hrs Crane Operation, Cummins 6 Cylinder 215 hp 8.3 L Diesel Engine, 41 ft Minimum 127 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 39.5 ft to 67 ft Bifold Swingaway Offset Jib, 1502 lb 65 ton Capacity Johnson 5 Sheave Hook Block, Overhaul Ball, 15000 lb Counterweight, EQUIPMENT-FROM-	582	Terrain Crane S/N: J6J8-9992 C/W: Microguard 534 Load Moment Indicator, 12354 hrs Crane Operation, Cummins B5.9C 6 Cylinder 173 hp 5.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 33 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Bifold Swingaway Offset Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, Overhaul Ball Usage: 12,353 Hr Asset located in: Humble, TX 2011 Grove RT600E 50 ton 4x4x4 Rough
	PULICE-CONSTRUCTION Usage: 4,994 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	583	Terrain Crane S/N: 231622 C/W: Air Conditioner, Anti Two-Block, PAT iFlex5 Load Moment Indicator, 11660 hrs
577A	2008 Link-Belt 8065 65 ton 4x4x4 Rough Terrain Crane S/N: J9J80231 C/W: Air Conditioner, Anti Two-Block, Link Belt MicroGuard 534 Load Moment Indicator, 11225 hrs Crane Operation, Cat C6.6 Acert 6 Cylinder 6.6 L Diesel Engine, 38 ft Minimum 115 ft Maximum Boom Length, Auxiliary Hoist,		Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball Usage: 11,660 Hr Asset located in: Humble, TX
	Rooster Sheave, 35 ft to 58 ft Bifold Swingaway Offset Jib, 1154 lb 70 ton Capacity Johnson 5 Sheave Hook Block, 347 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 11,225 Hr Asset located in: Humble, TX		2009 Grove RT600E 50 ton 4x4x4 Rough Terrain Crane S/N: 229898 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, 10124 hrs Crane Operation, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, Overhaul Ball Usage: 10,124 Hr Asset located in: Humble, TX
578	2001 Link-Belt RTC-8065 65 ton 4x4x4 Rough Terrain Crane S/N: D7J1-5707 C/W: Air Conditioner, Anti Two-Block, Link Belt MicroGuard 534 Load Moment Indicator, 6824 hrs Crane Operation, Cummins C8.3C 6 Cylinder 215 hp 8.3 L Diesel Engine, 38 ft Minimum 115 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 36.5 ft to 61 ft Bifold Swingaway Offset Jib, 1103 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 350 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 6,828 Hr		

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
584	1998 Grove RT880 160000 lb 4x4 Rough Terrain Crane S/N: 87272 C/W: PAT Load Moment Indicator, 13418 hrs Crane Operation, Cummins 6 Cylinder 249 hp B.3 L Diesel Engine, 36 ft Minimum 114 ft Maximum Boom Length, 30 ft Swingaway Jib,	590	Barreto 912 Walk Behind Trencher S/N: M2913 C/W: Honda GX270 1 Cylinder Gasoline Engine, 4 in Wide x 39 in Long Combination Trencher Chain, Crumbling Shoe Usage: 73 Hr Asset located in: Lake Worth, TX
	1390 lb 70 ton Capacity Johnson 4 Sheave Hook Block, 404 lb 12 ton Capacity Overhaul Ball, 14000 lb Counterweight Usage: 13,420 Hr Asset located in : Hot Springs, AR	591	2018 Barreto E1324STK-4MS Walk Behind Trencher S/N: STK202 C/W: 2021 US EPA Label, Honda GX390 1
585	1996 Grove RT528C 28 ton 4x4x4 Rough Terrain Crane S/N: 83337 C/W: Anti Two-Block, PAT DS 350 GW Load		Cylinder Gasoline Engine, Hydrostatic Drive, 5 in Wide x 24 in Long Combination Trencher Chain, 7 in Rubber Tracks Usage: 303 Hr Asset located in: Lake Worth, TX
	Moment Indicator, Cummins cbd126 6 Cylinder 128 hp Diesel Engine, 28 ft Minimum 70 ft Maximum Boom Length, 566 lb 30 ton Capacity McKissick 3 Sheave Hook Block Usage: 511 Hr Asset located in: Lake Worth, TX	592	2007 Ditch Witch RT36 4x4 Trencher S/N: CMWRT36XJ70000141 C/W: Deutz Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Combination Trencher Chain, Angle Blade Usage: 1,182 Hr
585A	P & H Century 122 22 ton 4x4 Rough Terrain Crane		Asset located in: Lake Worth, TX
	S/N: 32R1032 C/W: Anti Two-Block, PAT Load Moment Indicator, 8653 hrs Crane Operation, Detroit 4087-7100 V8 8.2 L Diesel Engine, 29 ft Minimum 72 ft Maximum Boom Length, 25 ft Swingaway Jib, Overhaul Ball Usage: 8,653 Hr Asset located in: Midland, TX	593	2004 Charles Machine Works 3700DD 4x4 Trencher S/N: 3Y0864 C/W: Canopy, Diesel Engine, 5 in Wide x 87 in Long Dirt Trencher Chain, A322 Backhoe Attachment, Straight Blade Usage: 1,924 Hr Asset located in: Lake Worth, TX
587		504	2007 Ditch Witch RT155H 4x4 Trencher
307	2007 International 4200 4x2 Boom Truck S/N: 1HTMPAFN37H426012 C/W: International A215 4 Cylinder 6.0 L Diesel 200 hp Engine, 2006 US EPA Label, 11193 Engine hrs, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring Suspension, 236 in Wheelbase, PTO, 34000 lb Capacity, Center Mounted, 27 ft - 70 ft 3 Section Boom,	394	S/N: CMWRT115E70000255 C/W: Canopy, US EPA Label, John Deere 4 Cylinder 82 kW 4.5 L Diesel Engine, Hydrostatic Drive, 10 in Wide x 80 in Long Dirt Trencher Chain, Crumbling Shoe Usage: 452 Hr Asset located in: Lake Worth, TX
	McKissick 170 lb 1 Sheave 7 ton Capacity Hook Block, Dual Controls, A-Outriggers, Rear Outriggers, 20 ft 0 in x 96 in Bed Usage: 103,701 Mi Asset located in : Lake Worth, TX	595	2001 Vermeer V120 4x4 Trencher S/N: 1VRT1124411000207 C/W: Canopy, Cummins 3 Cylinder Diesel Engine, Hydrostatic Drive, 6 in Wide x 9 ft 3 in Long Dirt Trencher Chain, Straight Blade
588	Ditch Witch C99 Walk Behind Trencher		Usage: 2,431 Hr Asset located in: Lake Worth, TX
	S/N: 116761 C/W: Gasoline Engine, 6 in Wide x 3 ft Long Dirt Trencher Chain, Discharge Conveyor Usage: Not Available Asset located in : Lake Worth, TX	596	2015 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XEF0002812 C/W: Deutz Diesel Engine, Hydrostatic Drive, 6 in Wide x 64 in Long Rock Trencher Chain,
589	·		Straight Blade, Side Shift Usage: 996 Hr Asset located in : Lake Worth, TX
		597	2018 Vermeer RTX450 4x4 Trencher S/N: 1VR4092U0J1003787 C/W: 2017 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Hydrostatic Drive, 6 in Wide x 4 ft 8 in Long Combination Trencher Chain, Angle Blade, Side Shift Usage: 417 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
		604	1997 Trencor 960HD Tracked Trencher	
CHOIC	CHOICE OF 2 - Lot #'s: 599, 600		S/N: 136 C/W: Enclosed Cab, Air Conditioner, 6 Cylinder	
599	2014 Vermeer T755III Tracked Trencher S/N: 1VR2160RXE1000550 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Cat C9 6 Cylinder 746 hp 8.8 L Diesel Engine, 16 in Wide x 11 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab Usage: 2,792 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, 6 Cylinder Engine, Trencor Cable Plow, 26 in Trenching Width, 84 in Trenching Depth, Discharge Conveyor, 24 in Triple Grouser Track Shoes Usage: 5,333 Hr Asset located in: Lake Worth, TX	
		Bucket Wheel Trencher S/N: 325300 C/W: Enclosed Cab, Cat D330 4 Cylinder I Engine, Manual Transmission, 27 in Trenc Width, Discharge Conveyor, 24 in Single Grouser Track Shoes	S/N: 325300 C/W: Enclosed Cab, Cat D330 4 Cylinder Diesel Engine, Manual Transmission, 27 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available	
600	2012 Vermeer T755III Tracked Trencher	1	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	
000	S/N: 1VR2160R3C1000516		SUBJECT TO 3RD PARTY STORAGE FEES	
	C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C9 375 hp Diesel Engine, 12 ft		Asset located in: Lahoma, OK	
	Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,066 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		E OF 2 - Lot #'s: 606, 607	
		606	1974 Cleveland S320 Tracked Bucket Wheel Trencher S/N: K427 C/W: Canopy, Diesel Engine, Manual Transmission, 26 in Trenching Width,	
	Asset located in: Lake Worth, TX			
601	2007 Vermeer T755III Tracked Trencher S/N: 1VR2190S371000123 C/W: Enclosed Cab, Air Conditioner, 2007 US EPA Label, Cat C9 6 Cylinder 480 hp 8.8 L Diesel Engine, 16 in Wide x 12 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab	Discharge Conveyor, 24 in Sing Track Shoes Usage: Not Available Notes : ITEM AT OFFSITE LOCA PICKED UP BY JANUARY 3RD (SUBJECT TO 3RD PARTY STOR		
		607 1969 Cleveland 320	1969 Cleveland 320 Tracked Bucket Wheel	
	Usage: 5,025 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		Trencher S/N: K414 C/W: Enclosed Cab, Cat D333 6 Cylinder Diese Engine, Manual Transmission, 25.5 in	
	Asset located in: Lake Worth, TX	-	Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes	
602	2009 Tesmec TRS975 Tracked Trencher S/N: 975-111 C/W: Enclosed Cab, Air Conditioner, Cat C9DI 6 Cylinder 300 hp Diesel Engine, Hydrostatic Drive, 23 in Wide x 186 in Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: 4,256 Hr Asset located in: Midland, TX		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUS PICKED UP BY JANUARY 3RD OR WILL B	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.
603	2000 Tesmec 1075 Tracked Trencher	1		
	S/N: 15211 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Hydrostatic Drive, 24 in Trenching Width, 160 in Trenching Depth, Discharge Conveyor, Side Shift, Hydraulic Leveling, 22 in Single Grouser Track Shoes Usage: 185 Hr Asset located in: Midland, TX			

Lot #	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 609, 610		614	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XLE0002319 C/W: 2004 US EPA Label, Deutz D2011 3
609	1959 (unverified) Cleveland 320 Tracked Bucket Wheel Trencher S/N: K328		Cylinder 42 hp 2.33 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 3 in Long Dirt Trencher Chain Usage: 2,034 Hr
	C/W: Enclosed Cab, Cat 4 Cylinder Diesel		Asset located in: Lake Worth, TX
	Engine, Manual Transmission, 21 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	615	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XHE0002029 C/W: US EPA Label, Deutz 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 5 in Long Dirt Trencher Chain, Straight Blade Usage: 989 Hr Asset located in: Lake Worth, TX
610	Cleveland 350 Tracked Bucket Wheel Trencher	616	<u> </u>
	S/N: 3514110 C/W: Canopy, Cat 3304 4 Cylinder 165 hp Diesel Engine, Manual Transmission, 42 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	616	2011 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XJC0001226 C/W: 2011 US EPA Label, Deutz D2011L03 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Combination Trencher Chain, Straight Blade Usage: 2,614 Hr
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Asset located in: Lake Worth, TX
		617	2014 Ditch Witch RT45 4x4 Trencher Cable Plow
			S/N: CMWRT45XLE0002028 C/W: Canopy, 2011 US EPA Label, CARB Compliant, Deutz D2011L03 3 Cylinder 42 hp
610A	Cleveland 320 Tracked Bucket Wheel Trencher S/N: K280 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 42 in Trenching Width, 84 in Trenching Depth, 18 in Single Grouser Track Shoes		2.3 L Diesel Engine, Hydrostatic Drive, 5 ft 4 in Cable Plow, 6 in Wide x 6 ft 4 in Long Combination Trencher Chain, Discharge Conveyor, H314 Traversing Trencher Attachment s/n: CMWH314XCD0002861 Usage: 2,993 Hr Asset located in: Lake Worth, TX
	Usage: Not Available	618	2016 Vermeer D100X140S3 Directional Drill
610B	Asset located in: Lahoma, OK Cleveland 320 Tracked Bucket Wheel Trencher S/N: K364 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes		Cylinder Diesel Engine, Drill Rod Loadir
	Usage: Not Available	619	2019 Vermeer D23x30III Directional Drill
610C	Asset located in: Lahoma, OK Cleveland 350S Tracked Bucket Wheel Trencher S/N: 3512290 C/W: Canopy, Cat 3304PC 4 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching Width, 72 in Trenching Depth, Discharge		S/N: 1VRN20074K1001288 C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Drill Rod Loading System 22 Drill Rods, 12 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX
	Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Asset located in : Lahoma, OK	620	2017 Vermeer 20X22III Directional Drill S/N: 1VRA170V3H1000764 C/W: 2016 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, Drill Rod Loading System 31 Drill Rods, 11 in Rubber Tracks Usage: 2,859 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
621	2019 Ditch Witch JT20 Directional Drill S/N: DWPJT20BAK0000234 C/W: Open Operator Station, 2019 US EPA Label, Deutz 4 Cylinder Diesel Engine, Drill Rod Loading System 39 Drill Rods, 11 in Rubber Tracks Usage: 3,005 Hr Asset located in: Lake Worth, TX	630	2022 Ditch Witch HX30G 500 gal T/A Vacuum Excavation Unit S/N: 1DST522N2N1701879 C/W: Spring Suspension, Electric Brakes, Steel Debris Tank, 500 gal Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Blower, 235/80R16 Tires, 2022 US EPA Label, Vanguard NBSXS.9932VB 2 Cylinder 31
622	2017 Ditch Witch JT20 Directional Drill w/2016 Felling FT24 Trailer S/N: CMWJT20XKH0000950 C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, 30 Drill Rods, 11 in Rubber Tracks, T/A Trailer w/ S/N- 5FTEE2923G1003458, Lunette Ring, Electric Brakes, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		hp 896 cc Ğasoline Engine Usage: 162 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2011 Ditch Witch FX30 800 gal T/A Vacuum
CHOIC	Asset located in: Lake Worth, TX CHOICE OF 1 - Lot #'s: 625		Excavation Unit S/N: 1DSB202S5B1702339 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Rear Hose
625	2020 Vermeer Lp573xdt T/A Vacuum Excavation Unit S/N: 5HZJ16235LK002140 C/W: Aluminum Frame, Lunette Ring Hitch, 2019 Vermeer Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate,		Reel, 800 gal Fresh Water Tank, Manual Tailgate Locks, 8 ft Telescopic Boom, 4 in Suction Hose, Engine Driven Pump, 215/75R17. 5 Tires, 18000 lb GVWR, Kubota D1105-T 3 Cylinder 1.1 L Diesel Engine Usage: 2,095 Hr Asset located in: Lake Worth, TX
	Manual Tailgate Locks, 235/80R16 Tires, 1200 lb GVWR, 2019 US EPA Label, Kohler 8 kW Diesel Engine Usage: 475 Hr Asset located in: Lake Worth, TX	632	2011 Vermeer VX50500 Vacuum Excavation Unit S/N: 1M9FE122XBS284256 C/W: Ball Hitch, Spring Suspension, Electric Brakes, McLaughlin Mfg Steel Debris Tank,
CHOICE OF 1 - Lot #'s: 627			Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Engine Driven Pump, 235/80R16 Tires, 12000 lb GVWR, 3 Cylinder Diesel Engine Usage: Not Available
627	2015 Vermeer Vac-tron T/A Vacuum Excavation Unit		Asset located in: Lake Worth, TX
	S/N: 5HZBF1929FLCF2113 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Rear Hose Reel, 200 gal Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, 235/85R16 Tires, 14000 lb GVWR, 2014 US EPA Label, CARB Compliant, Yanmar 4TNV88C-DYEM 4 Cylinder 2.2 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	4	2000 Vermeer Vac-tron Vacuum Excavation Unit S/N: 1A9AF152XYF495615 C/W: Lunette Ring Hitch, Spring Suspension, Steel Debris Tank, Fresh Water Tank, Full Open Tailgate, Manual Tailgate Locks, 235/85R16 Tires, Kohler 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 628, 9628A	635	1998 Nordberg LTC1416 Tracked Impact
628	2017 L0KT T/A Vacuum Excavation Unit S/N: 4M9E2TG23HE015031 C/W: Lunette Ring Hitch, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Drop Down Tailgate, Engine Driven Pump, 215/75R17.5 Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Crusher Plant S/N: 1291 C/W: Vibratory Pan Feeder 48 in Wide Under Crusher Conveyor, Radio Remote Control, 1997 US EPA Label, Cat 3406 6 Cylinder 328 kW Diesel Engine, 21.75 in Triple Grouser Track Shoes Usage: 2,847 Hr Notes: THIS UNIT MOVES ON ITS OWN WHEN IDLED UP. LOADING ASSISTANCE UNAVAILABLE ON THIS ITEM. BUYER WILL NEED TO SET UP OUTSIDE ASSISTANCE. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
636	2012 Powerscreen XH250 Impact Crusher S/N: PIDXH250A0MC55102 C/W: Terex 7 ft Belt Feeder Terex CR004 Jaw Crusher, 2012 US EPA Label, Cat 6.6 L Diesel Engine, 16 in Triple Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX	642	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409547 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
637	2023 Ark K-JC503 Jaw Crusher S/N: 323878 C/W: 1 ft 4 in x 6 ft 6 in Belt Feeder 12 in Rubber Tracks		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: 186 Hr Asset located in : Lake Worth, TX	643	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused)
638	2020 Screen Machine 621ST Tracked Trommel Screen S/N: 621ST1603 C/W: 5 ft 8 in x 14 ft 6 in Belt Feeder w/Grizzly		S/N: M202409550 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
	Trommel Screen, 42 in Wide Feed Conveyor, 42 in Wide Under Screen Conveyor, 41 in Wide Left Discharge Conveyor, Cat 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 15.75 in		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Triple Grouser Track Shoes Usage: 307 Hr		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	644	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused)
639	2020 Terex/Finlay 883 Tracked Screen Plant S/N: TRX883M4CDGLB3827 C/W: 8 ft 7 in x 16 ft Apron Feeder 16 ft x 5 ft Double Deck Screen, 35 in Wide Fines Discharge Conveyor, 47 in Wide Under Screen Conveyor, 31 in Wide Left Discharge Conveyor, 2020 US EPA Label, Cat C4.4 4 Cylinder 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Hydraulic Leveling, 15.75 in Triple Grouser Track Shoes Usage: 1,040 Hr Asset located in: Lake Worth, TX		S/N: M202409549 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available
			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
		6.45	Asset located in: Lake Worth, TX
		645	JCT Separator Magnet (Unused) S/N: Not Available
640	2004 McCloskey 621RE Portable Trommel		Usage: Not Available Asset located in : Lake Worth, TX
	Screen S/N: 11915	646	2012 Klein KPT-120 12000 gal S/A Water
	C/W: 21 ft x 6 ft Trommel Screen, 35 in Wide Feed Conveyor, 40 in Wide Under Crusher Conveyor, Cat 6 Cylinder Diesel Engine, T/A Carrier, Spring Suspension, Hydraulic Leveling Usage: 525 Hr Asset located in: Lake Worth, TX		Tower S/N: 40797 C/W: Hydraulic Raise, Gasoline Engine Driven Hydraulic Power Pack, 12 in Downspout, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY
СНОІС	CHOICE OF 4 - Lot #'s: 641, 642, 643, 644		Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY
	. , ,		Asset located in: Lake Worth, TX
641	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409548	648	2020 RoadHog RH60250 60" Wheel Loader Cold Planer Attachment S/N: 2009026
	C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available		C/W: Cat C7.1, 250hp, Diesel, Diesel Exhaust Fluid, Q/C, Side Shift, 80 Gallon Water Tank Usage: 37 Hr
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	648A	16 Ft Trimmer Head - Fits Gomaco 9500 S/N: Not Available Usage: Not Available
		1	Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
649	2018 Bomag RS460 Wheel Soil Stabilizer Reclaimer S/N: 101590161008 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires AdBlue, 96 in Rotor, Water /Emulsion Application System, 19.7 in Cutting Depth Usage: 1,584 Hr Asset located in: Baytown, TX	657	2000 Cat AP-650B Track Asphalt Paver S/N: 9DN00414 C/W: 8 ft 4 in - Screed, 14 in Track Shoes w /Rubber Inserts Usage: 6,827 Hr Asset located in: Lake Worth, TX
		658	Roadtec RP195 Track Asphalt Paver S/N: 10950808
650	2016 Cat RM300 Wheel Soil Stabilizer Reclaimer S/N: CATRM300HBWR00791		C/W: Dual Controls, Carlson Electric Heated 10 ft - 19 ft Screed, 18 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Canopy, 96 in Soil Rotor, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: 4,284 Hr Asset located in : Humble, TX	659	2007 Mauldin 1750C Track Asphalt Paver S/N: 879G75TJS6Y201879 C/W: Dual Controls, Propane Heated 7 ft 6 in - 16 ft Screed, 12 in Track Shoes w/Rubber Pads
651	Bomag MPH364R-2 Wheel Soil Stabilizer Reclaimer S/N: Not Available C/W: Canopy, 2013 US EPA Label, 84 in	660	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Combination Rotor, 14 in Cutting Depth, Water /Emulsion Application System Usage: 3,562 Hr Asset located in : Poteau, OK		Mauldin 690G Track Asphalt Paver S/N: 459Q69TKS8Y203459 C/W: Dual Controls, Propane Heated 8 ft 1 in - 13 ft 3 in Screed, 12 in Rubber Tracks
652	2021 Vogele S2100-31 Track Asphalt Paver S/N: 08192375		Usage: 934 Hr Asset located in : Lake Worth, TX
	C/W: Canopy, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in - 9 ft 8 in Screed, 12 in Rubber Tracks Usage: 2,345 Hr Asset located in: Humble, TX		S/N: 956003 C/W: Open Operator Station, John Deere Engine, Automatic Transmission, 10 " Spread
653	2011 Cat AP1055E Track Asphalt Paver S/N: CATAP105CTJF00111 C/W: Dual Controls, CAT AS3301C 10 ft 4 in - Screed, On Board Generator, 17 in Rubber Tracks		Width, Truck Hitch, Open Operator Station, Dual Controls, John Deere 4 Cylinder Diesel Engine, Hydrostatic Drive, - 10 ft Spreading Width, Truck Hitch, 20 in Conveyor Usage: 430 Hr Asset located in: Poteau, OK
	Usage: 17,079 Hr Asset located in : Lake Worth, TX	663	2016 Crafco 125D Asphalt Kettle S/N: 1C9SV1221G1418015
655	2005 Cat AP-655C Track Asphalt Paver S/N: CATAP655PAYP00240 C/W: Dual Controls, Carlson Electric Heated 8 ft - 13 ft 6 in Screed, 16 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX		C/W: 125 gal Capacity Tank, Diesel Fired Heater, Hydraulic Agitator, Hydraulic Driven Pump, Hose & Wand, Air Compressor, T/A Trailer Mounted Usage: 554 Hr Asset located in: Lake Worth, TX
CHOICE OF 2 - Lot #'s: 656, 657		664	Etnyre 2000 gal on 2002 GMC C7500 4x2 Asphalt Distributor Truck S/N: 1GDM7H1C82J513848
656	2001 Cat AP-650B Track Asphalt Paver S/N: 9DN00434 C/W: Fume Extractor, Cat 7MR02145, 8-16B Diesel Heated 8 ft 4 in - 15 ft 8 in Screed, 13.5 in Single Grouser Track Shoes w/Rubber Inserts Usage: Not Available Asset located in: Lake Worth, TX		C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 h Engine, 2002 US EPA Label, 5-Speed Manua Transmission, 11000 lb Front Axle, 22000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 13 ft 2 Folding Spray Bar, Diesel Burners, In-Cab Controls Usage: 50,865 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
664A	2001 International 4900 6x4 Hot Patch Truck S/N: 1HTSHAAR91H370891 C/W: International DT466 6 Cylinder 7.6 L Diesel 250 hp Engine, 2000 US EPA Label, 1719 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 52220 lb GVWR, 11R22.5, Double Frame, Hendrickson RT /RTE Series Suspension, 188 in Wheelbase, PTO, Arrow Board Usage: 15,865 Mi Asset located in: Lake Worth, TX	674	74 Demco Model HP 60 ft T/A Pull-Type Sprayer S/N: Not Available C/W: 540 PTO, ISOBUS, PTO Driven Pump, 500 gal Poly Tank, Chemical Mix Tank, Rinse Tank, Single Nozzle Bodies, Fence Row Nozzles, 111 15, Hydraulic Fold Booms, Guidance and Auto Steer Ready, Section Control, 29 In. Ground Clearance, Dual Agitators, Front Tank Walkway Usage: Not Available Notes: PERSONAL SPRAYER FOR LONGTIME CUSTOMER - FULLY OPERATIONAL
665	2016 Cimline 410 Magma Pothole Patcher S/N: 1G9441622GM119018 C/W: Isuzu 3cj1 4 Cylinder .99 L Diesel Engine, 225/75R15, Spring Suspension, Diesel Heating System Usage: 1,838 Hr		Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 675, 676
	Asset located in: Lake Worth, TX	675	2023 Bell TC7A Crawler Carrier S/N: AEBK607AA01000128
667	2008 (unverified) Valmet 430FXL Track Feller Buncher S/N: AT4K-2992-052108 C/W: Air Conditioner, Hydraulic Tilting Cab, US EPA Label, Quadco OFH 22 in Feller Buncher, 27.5 in Single Grouser Track Shoes, Rock Guards Usage: 969 Hr Asset located in: St. Rose, LA		C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High Flatbed Dump Body, 27 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 30 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
669	2003 Cat 525B 4x4 Line Skidder	676	Asset located in: Lake Worth, TX
670	S/N: CAT0525BK3KZ00929 C/W: Air Conditioner, Blade, Single Arch, cat Single Drum Winch, 30.5x32 Tires Usage: Not Available Asset located in: Lake Worth, TX 2013 John Deere 2954D Log Loader S/N: 1FF2954DED0290150 C/W: Air Conditioner, Air Ride Seat, Cab Screens, Hydraulic Tilting Cab, 31.5 in Triple Grouser Track Shoes, Rock Guards, ROTOBEC Log Grapple	676	2022 Bell TC7A Crawler Carrier S/N: AEBK607AC01000118 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High Flatbed Dump Body, 27 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 26 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Usage: 9,719 Hr Asset located in : Lake Worth, TX		
671	Finn T-30 Hydroseeder S/N: RUA730 C/W: Ball Hitch, Spring Suspension, ST8-14.5 Tires, Aluminum Tank, Gasoline Powered Pump, T/A Utility Trailer Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX	-CHOIC 677	2018 Terramac RT-14 Crawler Carrier S/N: 14G0060 C/W: Enclosed Cab, Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13 ft 6 in Long x 2 ft High Flatbed Dump Body, 31 in Rubber Tracks, Stake Sides; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,183 Hr Notes:; PLEASE SEE A PERSONAL NOTE
672	2011 Barko 930B 4x4 Mulcher Tractor S/N: 11293023740 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, Fecon 225 7 ft, Mulcher Usage: 628 Hr Asset located in: Lake Worth, TX		FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
678	2017 Terramac RT-14 Crawler Carrier S/N: 14C0040 C/W: 13 ft 6 in Long x 2 ft High Dump Body, 32 in Rubber Tracks, EQUIPMENT-FROM-	СНОІСІ	E OF 2 - Lot #'s: 684, 685
	WATKINS-CONSTRUCTION Usage: 1,912 Hr	684	2014 Morooka MST-2200VD Crawler Carrier S/N: 223666
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Cat C7 6 Cylinder 7.2 L Diesel Engine, 30 in Rubber Tracks, 9 ft 2 in Wide x 13 ft 4 in Long Flatbed
670	Asset located in: Lake Worth, TX 2017 Terramac RT-14 Crawler Carrier	_	Usage: 4,082 Hr
679	S/N: 14C0036 C/W: Enclosed Cab, Air Conditioner, 13 ft 6 in Long Flatbed Dump Body, 32 in Rubber Tracks,		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS
	EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,703 Hr	685	2011 Morooka MST-2200VD Crawler Carrier
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		S/N: 223442 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C7 6 Cylinder 7.2 L Diesel
	Asset located in: Lake Worth, TX	-	Engine, 30 in Rubber Tracks, 13 ft 4 in Long Flatbed Dump Body Usage: 6,040 Hr
	E OF 2 - Lot #'s: 680, 681		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
680	2019 Morooka MST2200VD Crawler Dumper S/N: A2202131		Asset located in: Louisville, MS
	C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive Usage: 2,294 Hr	CHOICE	E OF 2 - Lot #'s: 687, 688
	Asset located in: Baytown, TX	687	2019 Morooka MST1500VD Crawler Carrier
681	2019 Morooka MST2200VD Crawler Carrier S/N: A2202124 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2018 US EPA Label, Cat 6 Cylinder Diesel Engine, 29.5 in Rubber Tracks, 9 ft Wide x 12 ft 9 in Long Flatbed	S/N: A1505075 C/W: Enclosed Cab, Air Conditioner, Rear Vie Camera, Cat C 7.1 Diesel Engine, Requires Diesel Exhaust Fluid, 27 in Rubber Tracks, 105 in Long Flatbed Dump Body Usage: 864 Hr	
	Usage: 2,393 Hr Asset located in: Baytown, TX	688	Asset located in: Beaumont, TX
CHOIC	CHOICE OF 2 - Lot #'s: 682, 683		2019 Morooka MST1500VD Crawler Carrier S/N: A1505077 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Cat C 7.1 Diesel Engine, Requires Diesel Exhaust Fluid, 27.5 in Rubber Tracks, 10
682	2015 Morooka MST-2200VD Crawler Carrier S/N: A220291		ft 5 in Long Flatbed Dump Body Usage: 1,005 Hr
	C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 13 ft Long Flatbed Dump Body, 30	690	Asset located in: Beaumont, TX
	in Rubber Tracks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 679 Hr	090	2019 Morooka MST1000VD Crawler Carrier S/N: A1001007 C/W: Enclosed Cab, Air Conditioner, Rear View
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		Camera, Diesel Engine, Requires Diesel Exhaust Fluid, 23.5 in Rubber Tracks, 10 ft Long Flatbed Dump Body
	Asset located in: Lake Worth, TX		Usage: 1,115 Hr Asset located in : Beaumont, TX
683	2015 Morooka MST-2200VD Crawler Carrier S/N: A220247 C/W: Enclosed Cab, Air Conditioner, 13 ft Long Flatbed Dump Body, 30 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,659 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
691	Morooka MST1500 Crawler Carrier S/N: 151791 C/W: Canopy, 9 ft 10 in Long Flatbed Dump Body, 26 in Rubber Tracks, Lincoln 300D Welder w/ Leads; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 8,681 Hr Notes:; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 692, 693	695	IHI IC45-2 Crawler Carrier Aerial Lift w/2001 Terex HI-Ranger HR46M S/N: CE000831 C/W: Canopy, 2007 US EPA Label, Mitsubishi S6S-DTDP 6 Cylinder 99 hp 5.0 L Diesel Engine, 26250 lb Capacity, Rear Mounted, One-Person Articulated Boom, Flatbed, Turret Mounted Winch, X-Type Outriggers, Rear Outriggers, Bumper Mounted Winch, Hydraulic Hose Reel, 24 in Rubber Tracks Usage: 2,407 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS
692	2018 Canycom S25A Crawler Carrier S/N: 9161386 C/W: Canopy, US EPA Label, Kubota V2203-M-ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 1 ft 2 in High Dump Body Usage: 194 Hr Notes: ITEMS AT OFFSITE LOCATION MUST	696	2018 Cat 272D2XHP Two-Speed Skid Steer Loader S/N: CAT0272DTMD200939 C/W: Air Ride Seat, Joystick Steering, Rear View Camera, 9 Pin Electric Kit, Hydraulic Coupler, 80 in Bucket, Counterweight Kit Usage: 6,905 Hr Asset located in: Lake Worth, TX
	BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS	697A 697B	2016 Cat 272D2 Two-Speed High Flow XPS Skid Steer Loader S/N: CAT0272DABL200550
693	2018 Canycom S25A Crawler Carrier S/N: 9161385 C/W: Canopy, US EPA Label, Kubota V2203-M- ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 2 ft 2 in High		C/W: Open Operator Station, Joystick Steering, Rear View Camera, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket Usage: 6,097 Hr Asset located in: Lake Worth, TX
	Dump Body Usage: 1,799 Hr Notes : ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in : Louisville, MS		2016 Cat 272D2 Two-Speed Skid Steer Loader S/N: CAT0272DLBL200551 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket Usage: 6,474 Hr
694	IHI IC45-2 Crawler Carrier Digger Derrick		Asset located in: Lake Worth, TX
	S/N: CE000842 C/W: Enclosed Cab, Tier 2, 2018 US EPA Label, Mitsubishi 6 Cylinder Diesel Engine, 44 ft Sheave Height, 26250 lb Capacity, Rear Mounted, 33 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Turret Mounted Winch, One-Man Basket, 10 ft 0 in Body, X-Type Outriggers, Rear Outriggers, Bumper Mounted Winch, Hydraulic Hose Reel, 24 in Rubber Tracks	698A	2014 Cat 272D Two-Speed Skid Steer Loader S/N: CAT0272DHB5W00695 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 9 Pin Electric Kit, Manual Coupler, 72 in Bucket Usage: 6,717 Hr Asset located in: Lake Worth, TX
	Usage: 3,193 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS	699	2021 Bobcat S66 Two-Speed Skid Steer Loader S/N: B4SA12489 C/W: Open Operator Station, Joystick Steering, Manual Coupler Usage: 985 Hr Asset located in: Lake Worth, TX
		700	2015 Bobcat S630 Skid Steer Loader S/N: AHGL11719 C/W: Open Operator Station, 2014 US EPA Label, Manual Coupler, 66 in Bucket Usage: 9,891 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
701	2019 Cat 262D Skid Steer Loader S/N: CAT0262DKDTB09532 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Tier 4, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 1,988 Hr Asset located in: Lake Worth, TX	709	2014 Cat 246D Skid Steer Loader S/N: CAT0246DHBYF01000 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2014 US EPA Label, 9 Pin Electric Kit, Electric Coupler, 68 in Bucket Usage: 6,328 Hr Asset located in: Lake Worth, TX
СНОІС	E OF 4 - Lot #'s: 702, 703, 704, 705	710	2021 John Deere 318G Skid Steer Loader S/N: 1T0318GKCMJ407875
702	2020 Bobcat S570 Skid Steer Loader S/N: ALM429836 C/W: Open Operator Station, Creep Mode, Joystick Steering, Control Pattern Changer, Self Leveling, 2019 US EPA Label, Aperture		C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2021 US EPA Label, Aperture Tires, 9 Pin Electric Kit, Hydraulic Coupler, Counterweight Kit Usage: 1,521 Hr Asset located in: Lake Worth, TX
	Tires, Manual Coupler, 74 in Bucket Usage: 932 Hr Asset located in : Lake Worth, TX	711	2020 Cat 242D3 Two-Speed Skid Steer Loader S/N: CAT0242DAHSX00818
703	2020 Bobcat S570 Skid Steer Loader S/N: ALM429810 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 67 in Bucket Usage: 1,237 Hr		C/W: Open Operator Station, Joystick Steering, Tier 4, 2019 US EPA Label, Manual Coupler, 74 in Bucket Usage: 2,764 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		E OF 2 - Lot #'s: 712, 713
704	2020 Bobcat S570 Skid Steer Loader	Choic	E OF 2 - LOT # 8. 712, 713
	S/N: ALM429670 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 66 in Bucket Usage: 1,759 Hr Asset located in : Lake Worth, TX	712 2014 Cat 242D Skid Steer Loader S/N: CAT0242DTDZT00301 C/W: Open Operator Station, Joystick Steeri Tier 4, 2013 US EPA Label, Manual Coupler, in Bucket Usage: 2,904 Hr Asset located in: Midland, TX	S/N: CAT0242DTDZT00301 C/W: Open Operator Station, Joystick Steerin
705	2017 Bobcat S570 Skid Steer Loader S/N: ALM418117		
	C/W: Open Operator Station, 2017 US EPA Label, Manual Coupler, 66 in Bucket Usage: 751 Hr Asset located in : Lake Worth, TX	713	2015 Cat 242D Skid Steer Loader S/N: CAT0242DEDZT01204 C/W: Enclosed Cab, Air Conditioner, Air Ride
СНОІС	CHOICE OF 2 - Lot #'s: 706, 707		Seat, Ride Control, Joystick Steering, Tier 4, 2014 US EPA Label, Hydraulic Coupler, 74 in Bucket Usage: 1,273 Hr Asset located in: Midland, TX
706	2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BCTNK01891 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket Usage: 13,461 Hr	718	2012 Bobcat S150 Skid Steer Loader S/N: A3L485751 C/W: Enclosed Cab, Manual Coupler, 70 in Usage: 2,765 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	720	2006 Bobcat S205 Skid Steer Loader
707	2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BHTNK01905 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 73 in Bucket Usage: 11,292 Hr Asset located in: Lake Worth, TX	720	S/N: 530512291 C/W: Open Operator Station, Tier 2, 2006 US EPA Label, Aperture Tires, Manual Coupler, 66 in Grapple Bucket, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 2,830 Hr
708	Gehl R165 Skid Steer Loader		Asset located in: Lake Worth, TX
	S/N: GHL0R165E00197514 C/W: Open Operator Station, 2015 US EPA Label, Manual Coupler Usage: 2,245 Hr Asset located in: Lake Worth, TX	721	Case 1845C Skid Steer Loader S/N: 4810330 C/W: Enclosed Cab, Manual Coupler, 73 in Bucket Usage: 335 Hr
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICI 722	2020 Cat 299D3 Two-Speed Compact Track Loader S/N: CAT0299DADY902326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Rear View Camera, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 3,301 Hr Asset located in: Lake Worth, TX	728 728A	2017 Takeuchi TL12R2-CR Compact Track Loader S/N: 412100427 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Coupler, 81 in Bucket Usage: 1,197 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2020 Cat 289D3 Two-Speed High Flow XPS Compact Track Loader
724	2019 Cat 299D3XE Two-Speed Compact Track Loader S/N: CAT0299DCBX901368 C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, 17 in Track Belts, Manual Coupler Usage: 2,412 Hr	731	S/N: CAT0289DCJX903131 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2020 US EPA Label, 18 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 5,426 Hr Asset located in: Lake Worth, TX 2020 Cat 279D3 Compact Track Loader
725	Asset located in: Lake Worth, TX 2019 Cat 299D2XHP Two-Speed High Flow Compact Track Loader S/N: CAT0299DEDX204437 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Rear View Camera, 15 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit	731A	S/N: CAT0279DTRB901084 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2019 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler, 86 in Bucket, Counterweight Kit Usage: 2,944 Hr Asset located in: Beaumont, TX 2019 Bobcat T770 Two-Speed Compact Track
Usage: 2,589 Hr Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 726, 727		- -	Loader (Inoperable) S/N: AT6321914 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 66 in Bucket, EQUIPMENT-FROM-SUNSTATE-
726	2019 Cat 299D2 Two-Speed Compact Track Loader S/N: CAT0299DCFD205903 C/W: Enclosed Cab, Air Ride Seat, Joystick Steering, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 78 in Bucket Usage: 2,224 Hr	CHOIC	EQUIPMENT Usage: 3,269 Hr Notes: UNIT STARTS AND RUNS, HYDRAULICS FUNCTIONAL Asset located in: Lake Worth, TX
727	Asset located in: Lake Worth, TX 2019 Cat 299D2 Two-Speed Compact Track Loader S/N: CAT0299DHFD205803 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 80 in Bucket Usage: 2,733 Hr Asset located in: Lake Worth, TX	732 -733	2017 Bobcat T770 Compact Track Loader S/N: AT6314655 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 66 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,422 Hr Asset located in: Lake Worth, TX
727A	2020 Takeuchi TL12V2 Two-Speed High Flow Compact Track Loader S/N: 412002791 C/W: Enclosed Cab, Control Pattern Changer, Rear View Camera, 17.5 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 79 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,813 Hr Asset located in: Lake Worth, TX	- /33	2016 Bobcat T770 Compact Track Loader S/N: AT6312284 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 17.5 in Track Belts, 7 Pin Electric Kit, Manual Coupler, 80 in Bucket Usage: 3,647 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 734, 735	сноіс	E OF 3 - Lot #'s: 741, 742, 743
734	2022 Bobcat T76 Compact Track Loader S/N: B4CE19605 C/W: Open Operator Station, Joystick Steering, 2021 US EPA Label, Manual Coupler, 72 in Bucket Usage: 1,897 Hr Asset located in: Lake Worth, TX	741	2016 John Deere 329E Compact Track Loader S/N: 1T0329EKHGE294140 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Control Pattern Changer, 17 in Track Belts, Manual Coupler, 83 in Bucket Usage: 2,760 Hr Asset located in: Lake Worth, TX
735	2022 Bobcat T76 Compact Track Loader S/N: B4CE17367 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, Manual Coupler, 79 in Bucket Usage: 2,765 Hr Asset located in: Lake Worth, TX	742	2014 John Deere 329E Compact Track Loader S/N: 1T0329EMCEE255596 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 17.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 3,794 Hr
736	2020 Bobcat T76 R-Series Compact Track		Asset located in: Lake Worth, TX
	Loader S/N: B4CE11296 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2019 US EPA Label, 12.5 in Track Belts, Manual Coupler, 80 in Bucket Usage: 1,481 Hr Asset located in: Lake Worth, TX	743	2021 John Deere 325G Two-Speed Compact Track Loader S/N: 1T0325GKEMJ407899 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, 15.5 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, Counterweight
737	2015 Bobcat T750 Compact Track Loader S/N: ATF614726 C/W: Open Operator Station, 18 in Track Belts, Manual Coupler, 76 in Bucket Usage: 4,848 Hr Asset located in: Lake Worth, TX		Kit Usage: 1,692 Hr Asset located in : Lake Worth, TX
		743A	43A Case TV380 Two-Speed Compact Track Load S/N: JAFTV380AJM452078 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust
738	2012 Bobcat T750 Compact Track Loader S/N: ANKA12005		Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available
	C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Manual Coupler Usage: 4,888 Hr Asset located in : Lake Worth, TX	744	Asset located in: Lake Worth, TX 2015 Case TV380 Compact Track Loader S/N: JAFTV380HEM482982 C/W: Open Operator Station, Joystick Steering,
738A	2012 Bobcat T750 Compact Track Loader S/N: ANKA11840		16 in Track Belts, Manual Coupler, 86 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Joystick Steering, 18 in Track Belts, Hydraulic Coupler, 78 in Bucket Usage: 5,692 Hr Asset located in : Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 745, 746
739	2019 Bobcat T740 Two-Speed Compact Track Loader S/N: B3CA15269 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Hydraulic Coupler, 78 in Bucket Usage: 3,052 Hr Asset located in: Lake Worth, TX	745	2020 Kubota SVL95-2S Compact Track Loader S/N: KBCZ063CJL1F51637 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 17 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 1,986 Hr Asset located in: Lake Worth, TX
740	2022 John Deere 333G Compact Track Loader S/N: 1T0333GMCNF420256 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Hydraulic Coupler, 83 in Bucket Usage: 726 Hr Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
746	2019 Kubota SVL95-2HFC Compact Track Loader S/N: KBCC0953LK1E47027 C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, 9 Pin Electric Kit,	757	2019 Kubota SVL75-2 Compact Track Loader S/N: KBCC0752VK1J46375 C/W: Open Operator Station, Joystick Steering, 13 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,369 Hr Asset located in: Lake Worth, TX
	Hydraulic Coupler Usage: 1,501 Hr Asset located in : Lake Worth, TX	758	2018 Kubota SVL75-2 Compact Track Loader S/N: JKUC0752L01S38233
749	2017 Kubota SVL95-2SHF Compact Track Loader S/N: JKU00953001S34806 C/W: Open Operator Station, Joystick Steering,		C/W: Open Operator Station, Joystick Steering, 15.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,370 Hr Asset located in : Lake Worth, TX
	Tier 4, 2017 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler Usage: 4,389 Hr Asset located in: Lake Worth, TX	760	2021 Wacker Neuson ST45 LF CTL Vert Compact Track Loader S/N: WNCS0606TPUM00800
750	Kubota SVL95-2S Compact Track Loader S/N: 1024968 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 70 in Bucket		C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Control Pattern Changer, 2023 US EPA Label, 16.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 1,666 Hr Asset located in: Lake Worth, TX
	Usage: 1,813 Hr	761	2018 Wacker Neuson ST45 Compact Track
751	Asset located in: Lake Worth, TX 2012 Kubota SVL90 Compact Track Loader S/N: 1003128 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2011 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler Usage: 1,052 Hr		Loader S/N: WNCS0404PPUM01126 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 2018 US EPA Label, 18 in Track Belts, Manual Coupler, 66 in Bucket Usage: 499 Hr Asset located in: Lake Worth, TX
752	Asset located in: Lake Worth, TX 2023 Kubota SVL75-3 Compact Track Loader S/N: KBCZ053CTP1E12118 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manual Coupler Usage: 388 Hr Asset located in: Humble, TX	762	2019 LiuGong 388B Compact Track Loader S/N: LGZ388BZCKZ010679 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Coupler, 82 in Bucket Usage: 4,737 Hr Asset located in: Lake Worth, TX
754	2019 Kubota SVL95-2S Compact Track Loader S/N: KBCC0953PK1E47374 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: 318 Hr Asset located in: Midland, TX	CHOIC 763	E OF 3 - Lot #'s: 763, 764, 765 2021 Bobcat T64 Compact Track Loader S/N: B4SD13020 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,018 Hr Asset located in: Lake Worth, TX
CHOIC	CHOICE OF 3 - Lot #'s: 756, 757, 758		2021 Bobcat T64 Compact Track Loader S/N: B4SD12133 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, 12 in Track Belts, Manual
756	2019 Kubota SVL75-2 Compact Track Loader S/N: KBCC0752TK1J46403 C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, Manual Coupler, 72 in Bucket Usage: 1,718 Hr Asset located in: Lake Worth, TX		Coupler, 67 in Bucket Usage: 1,051 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
765	2021 Bobcat T64 R-Series Compact Track Loader S/N: B4SD12149 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,494 Hr Asset located in: Lake Worth, TX	773	2017 Bobcat T590 Compact Track Loader S/N: ALJU23698 C/W: Open Operator Station, Joystick Steering, 2017 US EPA Label, 12 in Track Belts, Manual Coupler, 57 in Bucket, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,084 Hr Asset located in: Lake Worth, TX E OF 1 - Lot #'s: 775
CHOIC	E OF 2 - Lot #'s: 766, 767	011010	E 01 1 L01 # 3. 770
766	2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506CPUM01235 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts,	775	2015 Bobcat T590 Compact Track Loader S/N: ALJU14338 C/W: Open Operator Station, 2014 US EPA Label, 12.5 in Track Belts, Manual Coupler Usage: 3,479 Hr Asset located in: Lake Worth, TX
	Hydraulic Coupler, 76 in Bucket Usage: 513 Hr Asset located in : Humble, TX	776	2019 Bobcat T550 Compact Track Loader S/N: AJZV23563 C/W: Open Operator Station, 2019 US EPA
767	2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506HPUM01189	778	Label, 12 in Track Belts, Manual Coupler, Forks Usage: 1,453 Hr Asset located in: Lake Worth, TX
	C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts, Manual Coupler Usage: 491 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2019 Takeuchi TL10V2 Compact Track Loader S/N: 410002668 C/W: Open Operator Station, Joystick Steering, Tier 4, 2019 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,355 Hr
769	2018 Case TR310 Compact Track Loader		Asset located in: Lake Worth, TX
	S/N: JAFTR310VJM449341 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 76 in Bucket Usage: 3,253 Hr Asset located in: Lake Worth, TX	779	2017 Takeuchi TL10V-2 Compact Track Loader S/N: 410000884 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 62 in Bucket Usage: 2,690 Hr
			Asset located in: Lake Worth, TX
771	2019 Bobcat T590 Compact Track Loader S/N: ALJU31295 C/W: Open Operator Station, 2019 US EPA Label, CARB Compliant, 13 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,490 Hr Asset located in: Lake Worth, TX	780	2022 ASV RT-135 Two-Speed Compact Track Loader S/N: ASVRT135ANDS00237 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, 17 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, 80 in Bucket Usage: 460 Hr Asset located in: Lake Worth, TX
CLICIC	E.O.E.2. Lot #0: 770, 770	CHOIC	E OF 3 - Lot #'s: 781, 782, 783
772	2017 Bobcat T590 Compact Track Loader S/N: ALJU23267 C/W: Open Operator Station, 2017 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,715 Hr Asset located in: Oklahoma City, OK	781	2021 Cat 259D3 Two-Speed Compact Track Loader S/N: CAT0259DECW912426 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 1,011 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
782	2021 Cat 259D3 Compact Track Loader S/N: CAT0259DJCW914734 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Tier 4, 2021 US EPA Label, 12 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,523 Hr Asset located in: Lake Worth, TX	789	2011 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BPYYZ00856 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 12.5 in Track Belts, Manual Coupler, 72 in Bucket Usage: 4,736 Hr
783	2021 Cat 259D3 Two-Speed Compact Track		Asset located in: Lake Worth, TX
	Loader S/N: CAT0259DCCW907770 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2020 US EPA Label, 16 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,817 Hr Asset located in: Lake Worth, TX	790 	2018 Takeuchi TL8 Two-Speed Compact Track Loader S/N: 200806258 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 12.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler Usage: 2,652 Hr Asset located in: Lake Worth, TX
784	2018 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DLFTL16672 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 13 in Track Belts, Manual Coupler Usage: 3,619 Hr Asset located in: Lake Worth, TX	792	2020 Gehl RT165 Compact Track Loader S/N: GHLRT165G0D302276 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, Manual Coupler Usage: 397 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 785, 786, 787	800 CHOIC	E OF 8 - Lot #'s: 793, 794, 795, 796, 797, 798, 799,
785	2017 Cat 259D Compact Track Loader S/N: CAT0259DLFTL12430 C/W: Open Operator Station, Joystick Steering, Tier 4, 2021 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in Bucket Usage: 7,140 Hr	793	2020 Bobcat T450 Compact Track Loader S/N: AUVP16938 C/W: Open Operator Station, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 675 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	794	2020 Bobcat T450 Compact Track Loader
786	2016 Cat 259D Compact Track Loader S/N: CAT0259DLFTL07339 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Self Leveling, Tier 4, 2022 US EPA Label, 12.5 in Track Belts, Manual Coupler, 75 in Bucket	_ /94	S/N: AUVP16950 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 802 Hr Asset located in : Lake Worth, TX
	Usage: 6,778 Hr Asset located in: Lake Worth, TX	795	2020 Bobcat T450 Compact Track Loader S/N: AUVP16939
787	2016 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DEFTL08493 C/W: Open Operator Station, Joystick Steering,		C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 910 Hr Asset located in : Lake Worth, TX
	Tier 4, 2016 US EPA Label, 16 in Track Belts, Manual Coupler, 79 in Bucket Usage: 4,493 Hr Asset located in : Lake Worth, TX	796	2020 Bobcat T450 Compact Track Loader S/N: AUVP17085 C/W: Open Operator Station, Joystick Steering,
788	2012 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BCYYZ02661		2019 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 1,387 Hr Asset located in: Lake Worth, TX
	C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 66 in Bucket Usage: 3,600 Hr Asset located in: Lake Worth, TX	797	2019 Bobcat T450 Compact Track Loader S/N: AUVP15801 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 571 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
798	2019 Bobcat T450 Compact Track Loader S/N: AUVP16910 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 73 in Bucket Usage: 636 Hr Asset located in: Lake Worth, TX	806	1988 John Deere 2955 2WD Tractor S/N: L02955T626188 C/W: Enclosed Cab, 16 Forward 8 Reverse, John Deere Loader, Quick Coupler, 72 in Bucket, 540 PTO, 3-Point Hitch, Drawbar, 10.00- 16 Front Tires, 18.4-38 Rear Tires Usage: 3,219 Hr
799	2019 Bobcat T450 Compact Track Loader		Asset located in: Lake Worth, TX
	S/N: AUVP15804 C/W: Open Operator Station, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 772 Hr Asset located in: Lake Worth, TX	807	1979 John Deere 4440 2WD Tractor S/N: 025940R C/W: Enclosed Cab, Air Ride Seat, Differential Lock, 16 Forward 6 Reverse, Quad Range, Front Weights, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, 38x11 Front Tires, 18.4x38
800	2019 Bobcat T450 All-Wheel Steer Compact Track Loader S/N: AUVP16039 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket		Rear Tires, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 966 Hr Notes: JERRY WATKINS PERSONAL RANCH TRACTOR Asset located in: Lake Worth, TX
	Usage: 954 Hr Asset located in : Lake Worth, TX	808	1983 John Deere 4450 2WD Tractor
801	2009 Bobcat T180 Compact Track Loader S/N: A3LL30017 C/W: Open Operator Station, 2008 US EPA Label, 12.5 in Track Belts, Manual Coupler, 67 in Bucket Usage: 3,840 Hr Asset located in: Lake Worth, TX	808	S/N: RW4450P005964 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 15 Forward 4 Reverse, Front Weights, 3 Rear Remotes, 540 PTO, Drawbar, 14L16.1-10 Front Tires, 20.8x38 Rear Tires Usage: 753 Hr Notes: COMES WITH IRONCLAD ASSURANCE.
802	2003 Cat 277 Compact Track Loader		SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
302	S/N: CAT00277LCNC02031 C/W: Open Operator Station, Joystick Steering, 18 in Track Belts, Manual Coupler, 79 in Bucket Usage: 6,389 Hr		
	Asset located in: Lake Worth, TX		
802A	John Deere 5203 2WD Utility Tractor S/N: PY5203U004017 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, SyncReverser, 2005 US EPA Label, 540 PTO, 3-Point Hitch, Drawbar, 7.50-16 Front Tires, 14.9x28 Rear Tires Usage: 119 Hr Asset located in: Lake Worth, TX	809 810	2017 Case IH Magnum 310 4WD Tractor S/N: JJAM0310THRF01144 C/W: Enclosed Cab, Air Conditioner, Front Weights, Rear Remotes, 540 PTO, Drawbar, 3 /85R34 Front Tires, Dual 480/80r46 Rear Tire Usage: 2,635 Hr
803	2010 John Deere 5045E 4WD Utility Tractor S/N: PY5045E000742 C/W: Differential Lock, Forward/ Reverse Shuttle, John Deere 553 Loader w/Joystick, Quick Coupler, John Deere 68 in Bucket, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Pickup Hitch, 9.5x24 Front Tires, 14.9x28 Rear Tires Usage: 3,181 Hr Asset located in: Humble, TX		Asset located in: Robstown, TX 2017 Case MAGNUM 310 4WD Tractor S/N: JJAM0310KHRF01180 C/W: Enclosed Cab, Air Conditioner, CVT, Forward/ Reverse Shuttle, Front Weights, 5 Rear Remotes, 1000 PTO, 3-Point Hitch, Dual 380/85R34 Front Tires, Dual 380/90r50 Rear Tires Usage: 2,810 Hr
804	2003 Kubota MX5000E 2WD Utility Tractor S/N: 11584 C/W: 4 Forward 4 Reverse, Manual Transmission, 38.0 kW Engine, 2003 US EPA Label, TAS ML280 Loader, 61 in Bucket, 3-Point Hitch, 29x12.50-15 Front Tires, 44x18.00-20 Rear Tires Usage: 481 Hr Asset located in: Lake Worth, TX		Notes: TODAY'S PRICE: 14% OFF \$123,419 (\$106,000) Asset located in: Baytown, TX

Lot #	Details	Lot #	Details
811	John Deere 8320R 4WD Tractor S/N: R0H8NBR611453 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 16 Forward 4 Reverse, PowerShift, Front Weights, 5 Rear Remotes, Auxiliary Hydraulics, ISOBUS, 380/80R38 Front Tires, Dual 480 /80R50 Rear Tires, Rear Wheel Weights Usage: 12,160 Hr Asset located in: Lake Worth, TX	816	2012 Kubota M7040D 4WD Tractor S/N: 87373 C/W: Enclosed Cab, Air Conditioner, 8 Forward 8 Reverse, Powershift, Kubota Loader w /Joystick, Quick Coupler, Pallet Forks, 4 Mid- Mount Remotes, 2 Rear Remotes Usage: 561 Hr Notes: **Bucket included in sale** Asset located in: Lake Worth, TX
СНОІС	E OF 2 - Lot #'s: 812, 813	817	2013 Mahindra 6110ST 4WD Tractor S/N: 61GCF00632 C/W: Enclosed Cab, Air Conditioner, Air Ride
812	2024 John Deere 6155M 4WD Tractor (Unused) S/N: 1L06155MTRG423600 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse, PowrQuad Plus, Left Hand Reverser, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Front 3-Point Quick Hitch, 3 Rear Remotes, Air Brake System, Exterior 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420 /70R28 Front Tires, 520/70R38 Rear Tires Usage: 4 Hr Asset located in: Lake Worth, TX		Seat, Differential Lock, Powershift, Forward/ Reverse Shuttle, 60 hp Engine, Mahindra ML161 Loader w/Joystick, Quick Coupler, 79 in Bucket, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, Rhino Turbo 96 96 in Mower, 10.5/80-18 Front Tires, 18.4x24 Rear Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 738 Hr Notes: JERRY WATKINS PERSONAL RANCH TRACTOR; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
		_	Asset located in: Lake Worth, TX
813	S/N: 1L06155MLRG423350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse, PowrQuad Plus, Left Hand Reverser, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Front 3-Point Quick Hitch, 3 Rear Remotes, Air Brake System, Exterior 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420	818	2012 Kubota M9960D 4WD Tractor S/N: 53487 C/W: Enclosed Cab, Air Conditioner, 8 Forward 8 Reverse, Powershift, 100 hp Engine, LA1353 Loader w/Joystick, Quick Coupler, 83 in Bucket, 4 Mid-Mount Remotes, 6 Rear Remotes Usage: 2,003 Hr Asset located in: Lake Worth, TX
	/70R28 Front Tires, 520/70R38 Rear Tires Usage: 1 Hr Asset located in : Lake Worth, TX	820	1998 Kubota L3600DT 4WD Tractor S/N: 56376
814	2013 John Deere 6105D 4WD Tractor S/N: 1P06105DADM050351 C/W: Enclosed Cab, Air Conditioner, 3 Forward 3 Reverse, Hydrostatic Drive, Forward/ Reverse Shuttle, 130 kW Engine, 2013 US EPA Label, CARB Compliant, 4 Rear Remotes, 540 PTO, 3-	822	C/W: 4 Forward 4 Reverse, Manual Transmission, Forward/ Reverse Shuttle, Kubota LA680 Loader w/Joystick, 1 Mid-Mount Remotes, HID Lights, 540 PTO, 3-Point Hitch, 8- 16 Front Tires, 14.9x24 Rear Tires Usage: 790 Hr Asset located in: Lake Worth, TX
015	Point Hitch, Hydraulic Top Link, 340/85R24 Front Tires, 18.4x34 Rear Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 4,107 Hr Asset located in: Humble, TX		Kioti LB1914 4WD Tractor S/N: 04000837 C/W: 8 Forward 4 Reverse, Manual Transmission, 3-Point Hitch, 6-12 Front Tires, 12.4-16 Rear Tires Usage: 667 Hr Asset located in: Lake Worth, TX
815	2022 John Deere 5100M 4WD Tractor S/N: 1LV5100MLNM104106 C/W: Canopy, Differential Lock, 16 Forward 16 Reverse, PowrReverser, Forward/ Reverse Shuttle, 2022 US EPA Label, Requires Diesel Exhaust Fluid, John Deere 540M Loader w /Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, 320/85R24 Front Tires, 460/85R30 Rear Tires Usage: 2,124 Hr	822A	2010 John Deere 9530 Articulated Tractor S/N: 1RW9530PCAP018006 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Grouser 16 ft Blade, 4 Rear Remotes, Auxiliary Hydraulics, Rear Weights, Dual 800/70R38 Tires Usage: 11,887 Hr Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	822B	2019 Shelbourne CVS16 16 ft Stripper Combine Header S/N: CVS16193113 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
823	2016 Manitou MRT2550 High Reach Rotating 4x4x4 Telehandler S/N: 769939	сноіс	CHOICE OF 4 - Lot #'s: 827, 828, 829, 830	
	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Load Moment Indicator, 81 ft Max Lift Height, 11000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 71 in Forks, Outriggers, Auxiliary Hydraulic Plumbing, 445 /65R22.5 Tires, Parked Idle Hours 265 Usage: 3,059 Hr Asset located in: Lake Worth, TX	827	2015 JLG 1255 Telehandler S/N: 0160070550 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,988 Hr	
823A	2012 JCB 512-56 Telehandler		Asset located in: Oklahoma City, OK	
	S/N: 512-56 P01403134 C/W: Enclosed Cab, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 3,236 Hr Asset located in: Lake Worth, TX	828	2015 JLG 1255 Telehandler S/N: 0160070536 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT	
824	24 2019 JLG 1255 Telehandler S/N: 0160096252 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75- 28 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 3,852 Hr Asset located in: Lake Worth, TX		Usage: 5,626 Hr Asset located in: Lake Worth, TX	
		829	2015 JLG G12-55A Telehandler S/N: 0160065521 C/W: Open Operator Station, Air Ride Seat, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Hydraulic Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,930 Hr	
СНОІС	E OF 2 - Lot #'s: 825, 826		Asset located in: Lake Worth, TX	
825	2018 JLG 1255 Telehandler S/N: 0160084208 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 12,673 Hr Asset located in: Humble, TX	830	2014 JLG G12-55A Telehandler S/N: 0160061321 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,775 Hr Asset located in: Lake Worth, TX	
826	2019 JLG 1255 Telehandler S/N: 0160091605 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 360/85-28 Solid Tires Usage: 9,502 Hr Asset located in: Lake Worth, TX	831	2014 JLG G12-55A Telehandler S/N: 0160060643 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 6,716 Hr Asset located in: Lake Worth, TX	
		832	2011 JLG G12-55A Telehandler S/N: 0160042364 C/W: Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2011 US EPA Label, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: Not Available	

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
833	2019 Skytrack 12054 Telehandler S/N: 0160092640 C/W: Enclosed Cab, Air Ride Seat, 12000 lb Max Lift Capacity, 48 in Forks, Hydraulic Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 3,148 Hr Asset located in: Lake Worth, TX	CHOIC 843	CE OF 2 - Lot #'s: 843, 844 2018 JLG 1055 Telehandler S/N: 0160083964 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires
834	2006 Dieci Pegasus 40.25 Telehandler S/N: 1560587 C/W: Enclosed Cab, 69 ft Max Lift Height, 8800 Ib Max Lift Capacity, 2006 US EPA Label, Crane Attachment, 18-22.5 Tires Usage: 5,470 Hr Asset located in: Lake Worth, TX		Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,300 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 1 - Lot #'s: 838	844	2017 JLG 1055 Telehandler S/N: 160082583 C/W: Enclosed Cab, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2017 US EPA
838	2017 Skyjack SJ1056TH Telehandler S/N: 8730578 C/W: Open Operator Station, 56 ft Max Lift Height, 2017 US EPA Label, 48 in Forks,		Label, Requires Diesel Exhaust Fluid, 59 in Forks, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 7,542 Hr Asset located in : Lake Worth, TX
	Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 4,532 Hr Asset located in : Midland, TX	845	2014 JLG G10-55A Telehandler S/N: 0160058853 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US
839	2018 Genie GTH-1056 Telehandler S/N: GTH10E12290 C/W: Open Operator Station, Air Ride Seat, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks,		EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Foam Filled Tires Usage: Not Available Asset located in: Lake Worth, TX
	Manual Coupler, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 2,530 Hr Asset located in : Humble, TX	846	2015 Gehl RS10-55 Telehandler S/N: RS1055CG90781 C/W: Open Operator Station, 55 ft Max Lift
840	2013 JCB 510-56 Telehandler S/N: JCB5CGXGK01403372 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 4,527 Hr	847	Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,609 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2018 JLG 10054 Telehandler
841	2007 Genie GTH-1056 Telehandler S/N: GTH1007A-11371 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Tilt Carriage, Outriggers, 14.00-24 Tires Usage: 8,632 Hr		S/N: 0160086824 C/W: Open Operator Station, 53 ft Max Lift Height, 10000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 3,294 Hr Asset located in: Humble, TX
0.40	Asset located in: Lake Worth, TX	-	Asset located III. Fluirible, TA
842	2017 Gehl RS10-55 Telehandler S/N: RS1055CH90900 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 3,546 Hr Asset located in: Humble, TX	CHOIC 848	2016 JLG 10054 Telehandler S/N: 0160076446 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 47 in Forks, Manual Coupler, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 4,051 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
849	2015 JLG 10054 Telehandler S/N: 0160065420 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 8,383 Hr Asset located in: Lake Worth, TX 2015 JLG 1055 Telehandler	853	2007 SkyTrak 10054 Telehandler S/N: 0160029235 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Tier 3, 2007 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing Usage: 1,666 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM	
	S/N: 0160070447 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing,		AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	
	14.00-24 Tires, EQUIPMÉNŤ-FROM-SUNSTAŤE- EQUIPMENT Usage: 5,727 Hr Asset located in : Lake Worth, TX	854	2018 Haulotte HTL9055 Telehandler S/N: 2030718 C/W: Enclosed Cab, Air Conditioner, Load Moment Indicator, 55 ft Max Lift Height, 9000 lb Max Lift Capacity, Manual Coupler	
851	2015 JLG 10054 Telehandler S/N: 0160064214 C/W: Open Operator Station, 42 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Manual Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 5,103 Hr Asset located in: Lake Worth, TX		Usage: 635 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
OE1 A	·	-	Asset located in: Fort Smith, AR	
851A	2015 JLG 10054 Telehandler S/N: 0160071104 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 47 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires Usage: 5,288 Hr	855 856	E OF 3 - Lot #'s: 855, 856, 857 2017 JLG 943 Telehandler S/N: 160079731	
852	Asset located in: Lake Worth, TX 2014 JLG 10054 Telehandler S/N: 0160062880 C/W: Open Operator Station, 54 ft Max Lift		Capacity, 2016 US EPA Label, Req Exhaust Fluid, 59 in Forks, Frame /75-28 Tires Usage: 5,224 Hr	
	Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, Manual Coupler, Outriggers, Frame Leveling, 17.5-25 Tires Usage: 5,424 Hr Asset located in: Lake Worth, TX		2017 JLG 943 Telehandler S/N: 160079732 C/W: Open Operator Station, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 2016 US	
852A	2013 JLG 8042 Telehandler S/N: 0160052932 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,413 Hr Asset located in: Lake Worth, TX		EPA Label, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 7,159 Hr Asset located in: Lake Worth, TX	
		857	2016 JLG 943 Telehandler S/N: 160078141 C/W: Enclosed Cab, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Foam Filled Tires Usage: 6,476 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
CHOIC 859	2014 Genie GTH-844 Telehandler S/N: GTH081419083 C/W: Open Operator Station, 44 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 24 Aperture Tires Usage: Not Available Asset located in: Midland, TX	866	Gehl RS8-42 Telehandler S/N: RS842JE0917426 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,721 Hr Asset located in: Lake Worth, TX 2017 Gehl RS8-42 Telehandler S/N: RS842CJ18031 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks,
859A	JCB 509.42 Telehandler S/N: JCB5CF7GPJ2755050 C/W: Open Operator Station, 42 ft Max Lift Height, 9000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 2,174 Hr Asset located in: Lake Worth, TX	СНОІС	Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,714 Hr Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 868, 869
860	2016 SkyTrak 8042 Telehandler S/N: 0160077066 C/W: Open Operator Station, 42 ft Max Lift Height, 4000 lb Max Lift Capacity, 47.5 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,626 Hr Asset located in: Lake Worth, TX	868	2013 Gehl RS8-42 Telehandler S/N: RS842JE0617386 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,087 Hr Asset located in: Oklahoma City, OK
СНОІС	E OF 2 - Lot #'s: 861, 862	869	2013 Gehl RS8-42 Telehandler S/N: RS842JF0517510 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks,
861	2015 JLG 8042 Telehandler S/N: 0160069747 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary	870	Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,342 Hr Asset located in: Oklahoma City, OK
	Hydraulic Plumbing, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		2006 Mustang 944L Telehandler S/N: 944LJX0635018 C/W: Open Operator Station, 44 ft Max Lift Height, 9000 lb Max Lift Capacity, 48 in Forks,
862	2015 JLG 8042 Telehandler S/N: 0160070986 C/W: Open Operator Station, 42 ft Max Lift		Frame Leveling, 14.00-24 Tires Usage: 2,580 Hr Asset located in : Lake Worth, TX
965	Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Solid Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,470 Hr Asset located in: Lake Worth, TX	873	2006 SkyTrak 8042 Telehandler S/N: 0160024470 C/W: Enclosed Cab, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2006 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 2,478 Hr
865	2013 JLG 8042 Telehandler S/N: 0160054404 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, Frame Leveling, 15.5-25 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,889 Hr Asset located in: Lake Worth, TX	874	Asset located in: Lake Worth, TX 2012 Genie GTH-644 Telehandler S/N: GTH061215400 C/W: Open Operator Station, 44 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, 13.00-24 Tires Usage: 4,133 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
874A	2017 JLG Skytrak 6042 Telehandler S/N: 0160079780 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing Usage: 1,949 Hr Asset located in: Lake Worth, TX E OF 4 - Lot #s: 875, 876, 877, 878	882	2013 SkyTrak 6042 Telehandler S/N: 0160054643 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,159 Hr Notes: . Asset located in: Oklahoma City, OK
875	2014 JLG 6042 Telehandler S/N: 0160056200 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 47 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-	883	2013 SkyTrak 6042 Telehandler S/N: 0160047623 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
	24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,631 Hr Asset located in : Lake Worth, TX		Usage: 5,052 Hr Notes : . Asset located in : Oklahoma City, OK
876	2014 JLG 6042 Telehandler S/N: 0160058949 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 47 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,476 Hr	884	2013 JLG G6-42A Telehandler S/N: 0160051054 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2012 US EPA Label, 47 in Forks, Frame Leveling, 370/75- 28 Tires Usage: 4,609 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	_сноіс	E OF 2 - Lot #'s: 885, 886
877	2015 SkyTrak 6042 Telehandler S/N: 0160070308 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,236 Hr Asset located in: Lake Worth, TX	885	2014 Gehl RS6-42 Telehandler S/N: RS642JF0814891 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2014 US EPA Label, Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT
878	2015 SkyTrak 6042 Telehandler S/N: 0160067892		Usage: 2,499 Hr Asset located in: Lake Worth, TX
	C/W: Open Operator Station, 42 ft Max Lift Height, 6000 kg Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,160 Hr Asset located in: Lake Worth, TX	886	2014 Gehl RS6-42 Telehandler S/N: RS642JF0814899 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 47 in Forks, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,177 Hr
CHOIC	E OF 3 - Lot #'s: 881, 882, 883	887	Asset located in: Lake Worth, TX 2018 JLG 6036 Telehandler
881	2013 SkyTrak 6042 Telehandler S/N: 0160055011 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,040 Hr Asset located in: Lake Worth, TX		S/N: 0160083772 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 315/95-28 Solid Tires Usage: 1,190 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
	E OF 12 - Lot #'s: 888, 889, 890, 891, 892, 893, 894, 66, 897, 898, 899 2014 Gehl RS6-34 Telehandler S/N: RS634JF0822387 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US	894	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921979 C/W: Open Operator Station, 35 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,678 Hr Asset located in: Oklahoma City, OK
	EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,160 Hr Asset located in: Lake Worth, TX	895	2012 Gehl RS6-34 Telehandler S/N: RS634JD0121707 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2011 US EPA Label, 48 in Forks, Manual Coupler, Frame
889	2014 Gehl RS6-34 Telehandler S/N: RS634JF0522222 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US		Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,712 Hr Asset located in: Oklahoma City, OK
	EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,001 Hr Asset located in : Lake Worth, TX	896	2012 Gehl RS6-34 Telehandler S/N: RS634JD0321723 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 72 in Forks, Manual Coupler, Frame
890	2014 Gehl RS6-34 Telehandler S/N: RS634DF1022527 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks,		Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,973 Hr Asset located in: Lake Worth, TX
	Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,227 Hr Asset located in : Lake Worth, TX	897	97 Gehl RS6-34 Telehandler S/N: RS634DG22553 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks Frame Leveling, Foam Filled Tires, EQUIPMEN FROM-SUNSTATE-EQUIPMENT Usage: 4,136 Hr Asset located in: Lake Worth, TX
891	2014 Gehl RS6-34 Telehandler S/N: RS634DF1022506 C/W: Open Operator Station, 34 ft Max Lift		
	Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 15-9.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,025 Hr Asset located in: Lake Worth, TX	898	Gehl RS6-34 Telehandler S/N: RS634JE1122021 C/W: Open Operator Station, Air Ride Seat, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 60 in Forks, Frame Leveling, 15-19.5 Tires,
892	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921970 C/W: Open Operator Station, 34 ft Max Lift		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,296 Hr Asset located in : Lake Worth, TX
	Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,144 Hr Asset located in: Oklahoma City, OK		Gehl RS6-34 Telehandler S/N: RS634DF1022514 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-
893	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921972 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,418 Hr Asset located in: Lake Worth, TX		EQUIPMENT Usage: 3,338 Hr Asset located in : Lake Worth, TX
		900	Gehl RS6-34 Telehandler S/N: RS634JF0722333 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,642 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
901	Gehl RS6-34 Telehandler S/N: RS634DF0922487 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 47.5 in Forks, Manual Coupler, 15-19.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,389 Hr Asset located in: Lake Worth, TX	909	2007 Genie GTH-5519 Telehandler S/N: 17897 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2007 US EPA Label, 48 in Forks, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 1,676 Hr Asset located in: Lake Worth, TX	
CHOIC	E OF 3 - Lot #'s: 904, 905, 906	910	2015 Genie GTH-5519 Telehandler S/N: GTH5515B2885 C/W: Open Operator Station, 19 ft Max Lift	
904	2013 Gehl RS5-19 Telehandler S/N: RS519YF0851124 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US		Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Frame Leveling, 12-16.5 Tires Usage: 1,522 Hr Asset located in : Lake Worth, TX	
	EPA Label, 47 in Forks, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,272 Hr Asset located in : Lake Worth, TX	910A ——911	2020 JLG 3013 Telehandler S/N: H160000215 C/W: Open Operator Station, Air Ride Seat, 13 ft Max Lift Height, 2360 lb Max Lift Capacity, Tier 4, 2020 US EPA Label, 46 in Forks,	
905	2013 Gehl RS5-19 Telehandler S/N: RS519YF0251049 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 48 in Forks,		Hydraulic Coupler, 11.0/65-12 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 667 Hr Asset located in : Lake Worth, TX	
	Manual Coupler, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,838 Hr Asset located in: Lake Worth, TX		11 Cat R80 8000 lb 4x2 Rough Terrain Forklift S/N: 49A01169 C/W: 3 Stage Mast, 192 in Max Lift Height, 11 in Lowered Mast Height, 48 in Forks, 4 Cylind	
906	Gehl RS5-19 Telehandler S/N: RS519YE1050991 C/W: Open Operator Station, 19 ft Max Lift	911B	Diesel Engine Usage: Not Available Asset located in : Lake Worth, TX	Diesel Engine Usage: Not Available
	Height, 5500 lb Max Lift Capacity, US EPA Label, 46 in Forks, Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		Forklift S/N: JCB95004H02364093 C/W: 3 Stage Mast, 127 in Lowered Mast	S/N: JCB95004H02364093
СНОІС	E OF 2 - Lot #'s: 907, 908		Label, JCB Power Sources 4 Cylinder 56 kW Diesel Engine Usage: 5,199 Hr Asset located in: Lake Worth, TX	
907	2020 Manitou MT625 Telehandler	012		
	S/N: MAN00000J01033352 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 5500 lb Max Lift Capacity, Hydraulic Coupler, Auxiliary Hydraulic Plumbing, 12x16.5 Tires Usage: 2,764 Hr Asset located in: Lake Worth, TX	912	Sellick S80J4I-2 8000 lb 4x4 Rough Terrain Forklift S/N: 10015609S8J4I C/W: 3 Stage Mast, 264 in Max Lift Height, 126 in Lowered Mast Height, 69 in Forks, JCB Diesel Engine Usage: 3,868 Hr	
908	2019 Manitou MT625 Telehandler S/N: MAN00000J01021296 C/W: Enclosed Cab, 19 ft 1 in Max Lift Height, 5500 lb Max Lift Capacity, Tier 4, 2019 US EPA Label, Hydraulic Coupler, Auxiliary Hydraulic Plumbing, 12-16.5 Tires		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
	Usage: 2,832 Hr Asset located in : Lake Worth, TX		Asset located in: Fort Smith, AR	

Lot #	Details	Lot #	Details
914	S/N: 1FD0X5HT8RED27006 C/W: Ford V8 6.7 L Diesel Engine, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 11 Engine	CHOICE OF 1 - Lot #'s: 917 917 2019 Ford F-550 4x4 Service Truck	
hrs, Engine Brake, Automatic Transm 6500 lb Front Axle, 14706 lb Rears, 1 GVWR, 225/70R19.5, Spring Suspens in Wheelbase, PTO, Caseco MM238 Hydraulic Stabilizers, Stellar 7621 75 Section Hydraulic Crane, Wireless Re Control, American Eagle SHD-60 Hyd Compressor, Air Hose Reel Usage: 241 Mi	hrs, Engine Brake, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, PTO, Caseco MM238 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Wireless Remote Control, American Eagle SHD-60 Hydraulic Air Compressor, Air Hose Reel Usage: 241 Mi Asset located in: Lake Worth, TX		S/N: 1FDUF5HT3KEC14526 C/W: Power Stroke V8 6.7 L 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245 /70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 2018 Stellar TMAX1-11AL 11 ft 1 in Body, Hydraulic Stabilizers, Stellar 7621 3 Section Hydraulic Crane, Wireless Remote Control, American Eagle 30P Piston Series
915	2023 Ford F-550 4x4 Extended Cab Service Truck		Hydraulic Air Compressor, Miller Bobcat 250 250 A Gasoline Welder Usage: 190,847 Mi
	S/N: 1FD0X5HTXPED24749 C/W: 6.7 L Diesel Engine, 2023 US EPA Label,		Asset located in: Midland, TX
	Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 2017 Altec 10 ft 3 in Body, Hydraulic Stabilizers, Auto Crane HC-5 5000 lb 2 Section Electric Crane, Wired Remote Control, Boss BA435 Hydraulic Air Compressor, Air Hose Reel, Miller Bluestar 185 Welder	919	2018 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HY3JDA01060 C/W: Ford V10 6.8 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft Body, Vanair Air N Arc All-In- One Power System, Product Tanks, Hose Reels Usage: 182,415 Mi
	Usage: 95 Mi Asset located in : Lake Worth, TX		Notes: EQUIPMENT FROM UNITED RENTALS
916	2023 Ford F-550 XL 4x4 Extended Cab Service	-	Asset located in: Lake Worth, TX
910	Truck S/N: 1FD0X5HT3PEC87656 C/W: V8 6.7 L Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 30 Engine hrs, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 11 ft Body, Hydraulic Stabilizers, Auto Crane HC-5 5000 lb 3 Section Hydraulic Crane, Tomahawk TWG120A Gasoline Generator Set, Boss BA435 Hydraulic Air Compressor, Air Hose Reel Usage: 308 Mi	920	2017 Ford F-550 XL 4x2 Service Truck S/N: 1FDUF5GT5HDA09578 C/W: Ford Powerstroke V8 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 114706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, Auto Crane Titan 38K 11 ft Body, Hydraulic Stabilizers, Auto Crane HC6 6000 lb 3 Section Hydraulic Crane, Wired Remote Control, Gasoline Air Compressor, Lincoln Bobcat 225 Gasoline Welder Usage: 69,562 Mi Notes: PTO HAS BEEN REPAIRED
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
916A	Truck S/N: 1FD0X5HT7PED26877 C/W: Ford 6 Cylinder 6.7 L Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, PTO, Palfinger Pro 43 11 ft Body, Hydraulic Stabilizers, 2012 Palfinger PSC4329 8000 lb 2 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC35 Hydraulic Air Compressor, Air Hose Reel Usage: 143 Mi Asset located in: Lake Worth, TX	920B	2016 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT4GEA46341 C/W: Ford 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, IMT 11 ft Body, 55 gal Oil Tanks, (5) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, Vanair Air N Arc 150 Gasoline Air Compressor, Air Hose Reel, Vanair Air N Arc 150 Welder, Rear View Camera; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 230,316 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 1 - Lot #'s: 923	сноіс	E OF 1 - Lot #'s: 925
923	2012 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HY9CEB86563 C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 162 in Wheelbase, PTO, Knaphiede 9 ft 2 in Body, Hydraulic Stabilizers, Auto Crane 5005H 5000 lb 3 Section Hydraulic Crane, Wired Remote Control, Speedair 4LW38 Gasoline Air Compressor, Air Hose Reel Usage: 193,733 Mi Asset located in: Midland, TX	925	2023 Chevrolet 4500 4x2 Service Truck S/N: 1HTKHPVH4PH293943 C/W: International 350 V8 6.6 L Diesel 350 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 10 Engine hrs, Allison Automatic Transmission, 7000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 141 in Wheelbase, PTO, Knapheide 9 ft Body, Manual Stabilizers, Liftmoore 4000X 4000 lb 3 Section Electric Crane, Wired Remote Control, Land Honor LHR- GAC40T Gasoline Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 54 Mi Asset located in: Lake Worth, TX
923A	2008 Ford F-550 4x2 Utility Truck S/N: 1FDAF56R08EE06327 C/W: V8 6.4 L Diesel Engine, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, United Truck Bodies 108UTB 12 ft 4 in Body, Northstar Gasoline Air Compressor, Air Hose Reel Usage: 211,927 Mi Asset located in: Lake Worth, TX	928 2023 Ram 4500HD 4x2 Service S/N: 3C7WRKBL5PG620080 C/W: Cummins B6.7 360 6 Cy Diesel 360 hp Engine, 2023 U Requires Diesel Exhaust Fluice Exhaust Brake, Automatic Tra Ib Front Axle, 12000 lb Rears, 225/70R19.5, Spring Suspens Wheelbase, PTO, Hydraulic Si Palfinger PSC 6025 6000 lb 3 Hydraulic Crane, Wireless Rei Palfinger PRC45V Hydraulic A Air Hose Reel, Lincoln Eagle 1 Gasoline Welder Usage: 302 Mi Notes: 3 YEAR 36,000 MILE - BUMPER TO BUMPER WARR, 60,000 MILE - FACTORY POW WARRANTY	2023 Ram 4500HD 4x2 Service Truck S/N: 3C7WRKBL5PG620080 C/W: Cummins B6.7 360 6 Cylinder 6.7 L Diesel 360 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 16 Engine hrs, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, Hydraulic Stabilizers,
923B	2015 Ram 5500 4x2 Fuel and Lube Truck S/N: 3C7WRMBL0FG594935 C/W: Cummins V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, Iowa Mold Tooling DSS K187525 11 ft Body, Air And Arc 150 Welder, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 302 Mi Notes: 3 YEAR 36,000 MILE - FACTORY BUMPER TO BUMPER WARRANTY; 5 YEAR 60,000 MILE - FACTORY POWERTRAIN
924	Usage: 205,310 Mi Asset located in: Lake Worth, TX 2012 Dodge Ram 5500 4x2 Service Truck S/N: 3C7WDMBL1CG197440 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Wireless Remote	930	2013 Ford F-450 4x4 Crew Cab Service Truck S/N: 1FD0W4HY5DEB45653 C/W: Ford V8 6.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500.0 lb GVWR, 225/70R19.5, Spring Suspension, 202 in Wheelbase, PTO, 2007 11 ft Body, Manual Stabilizers, Stahl 3200 LRX 3200 lb 3 Section Electric Crane, Wired Remote Control Usage: 215,755 Mi Asset located in: Lake Worth, TX
	Control Usage: 296,712 Mi Asset located in : Lake Worth, TX	931	2017 Ford F-250 XL 4x2 Utility Truck S/N: 1FDBF2A62HED60788 C/W: Gasoline Engine, Automatic Transmission, 3800 lb Front Axle, 6340 lb Rears, 9900 lb GVWR, Steel, 245/75R17, Spring Suspension, 142 in Wheelbase, Knapheide 8 ft Body Usage: 190,429 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
932	2012 Ford F-550 XL 4x2 Crew Cab Utility Truck S/N: 1FD0W5GT8CEC42968 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 202 in Wheelbase, Knapheide 6132D54 11 ft Body Usage: 319,591 Mi Asset located in: Lake Worth, TX	938 939	E OF 2 - Lot #'s: 938, 939 2021 Chevrolet Silverado 2500 HD 4x2 Crew Cab Utility Truck S/N: 1GB2WLE77MF235677 C/W: V8 6.6 L Gasoline Engine, 2021 US EPA Label, 2137 Engine hrs, Automatic Transmission, 4400 lb Front Axle, 6390 lb
933	2012 Ford F-550 4x2 Utility Truck S/N: 1FDUF5GT7CEB42748 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 163 in Wheelbase, 10 ft 11 in Body, Manual Stabilizers, Liftmoore 3200 lb Hydraulic Crane, Wired Remote Control, Miller Wildcat 200 6500 W Gasoline Generator Set,		Rears, 10000 İb GVWR, 245/75R17, Spring Suspension, 162 in Wheelbase, 2021 Harbor 8 ft 2 in Body Usage: 75,339 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX 2021 Chevrolet Silverado 2500 HD 4x2 Utility
	Gasoline Air Compressor Usage: 296,236 Mi Asset located in: Lake Worth, TX		Truck S/N: 1GB0WLE72MF189165 C/W: V8 6.6 L Gasoline Engine, 2021 US EPA Label, 2015 Engine hrs, Automatic
935	2017 Ram 3500 4x2 Crew Cab Utility Truck S/N: 3C7WRSCL3HG632261 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 170 in Wheelbase, Knapheide 9 ft Body, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Asset located in: Lake Worth, TX 2017 Ram 3500 4x2 Crew Cab Utility Truck S/N: 3C7WRSCL5HG632262 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 4102 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235 /80R17, Spring Suspension, 172 in Wheelbase, Knapheide 6108D54J1 9 ft Body, vanair Viper		Transmission, 4400 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 140 in Wheelbase, Scelzi 8 ft 2 in Body Usage: 109,730 Km Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX
		939A	2016 GMC 2500HD 4x4 Crew Cab Utility Truck S/N: 1GT12REG1GF303868
936			C/W: GM V8 6.0 L Gasoline Engine, 2016 US EPA Label, 8880 Engine hrs, Automatic Transmission, 4800 lb Front Axle, 6200 lb Rears, 9900 lb GVWR, 265/70R17, Spring Suspension, Reading 9 ft Body Usage: 214,244 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
			TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY	941	2015 Chevrolet Silverado 2500 HD 4x2 Utility
	Usage: 104,083 Mi Asset located in: Lake Worth, TX		Truck S/N: 1GC0CUEG1FZ528560 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9300 lb GVWR, 245/75R17, Spring Suspension, 130 in Wheelbase Usage: 230,081 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS
			MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPANCY-UNIT SHOWS 230,081, TITLE SHOWS 232,270

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
942	2014 Ford F-250 XL 4x4 Extended Cab Utility Truck S/N: 1FT7X2B68EEB70690 C/W: Ford V8 6.2 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 225 /70R19.5, Spring Suspension, 142 in Wheelbase, 6 ft 10 in Body Usage: 421,371 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	947	2008 Ford F-250 XL 4x4 Utility Truck S/N: 1FTNF21548EE41543 C/W: V8 5.4 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 9000 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, Knapheide 8 ft Body Usage: 195,357 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
0424	Asset located in: Lake Worth, TX	948	2006 Chevrolet 2500 4x2 Utility Truck
942A	2015 GMC Sierra 3500HD 4x2 Utility Truck S/N: 1GD311CG4FZ538631 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4400 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235 /80R17, Spring Suspension, 10 ft Body Usage: 97,811 Mi		S/N: 1GBHC24U76E153672 C/W: V8 6.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, 245/75R16, Spring Suspension, 8 ft 2 in Body Usage: 33,621 Mi Asset located in: Lake Worth, TX
0.40	Asset located in: Lake Worth, TX	сноісі	E OF 2 - Lot #'s: 950, 951
943	2014 Chevrolet 2500HD 4x2 Crew Cab Utility Truck S/N: 1GC1CVCG7EF160110 C/W: V8 6.0 L Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9500 lb GVWR, 265/70R17, Spring Suspension, 167 in Wheelbase, Omaha 8 ft Body, Air Hose Reel Usage: 161,768 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	950	2020 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 1NP3LJ0X8LD732020 C/W: Paccar L9 6 Cylinder 8.9 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8871 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 18740 lb Front Axle, 40000 lb Rears, 58740 lb GVWR, Steel, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Suspension, 210 in Wheelbase, PTO, Niece WT-4K 4000 gal Tank, 8 ft, Spray Bar, Front Spray, Rear Spray,
944	2012 Ford F-250 XL 4x2 Extended Cab Utility Truck		Side Spray Usage: 100,644 Mi Asset located in : Lake Worth, TX
	S/N: 1FD7X2A6XCEC57999 C/W: Ford 6.2 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 4250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 245 /75R17, Spring Suspension, 158 in Wheelbase, Knapheide 696J 8 ft Body Usage: 215,738 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	951	2019 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 2NP3LJ0XXKM624300 C/W: Paccar PX-9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 18180 lb Front Axle, 40000 lb Rears, 4.11:1 Axle Ratio, 58180 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking
946	2009 Ford F-250 XL 4x2 Utility Truck S/N: 1FDNF20569EA84459 C/W: Ford 5.4 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, 3950 lb Front Axle, 5892 lb Rears, 8800 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, 2009 Omaha 8 ft Body Usage: 152,394 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		Beam Suspension, 210 in Wheelbase, PTO, 2018 Niece Tank, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 92,315 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
952	2015 Peterbilt 348 6x4 Water Truck S/N: 2NP3LJ0XXFM280411 C/W: Paccar PX-9 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9583 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 44000 lb Rears, Dana DSH44 Drive Axles, 4.88:1 Axle Ratio, 64000 lb GVWR, Aluminum Wheels, 315 /80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Air Trac 4-Bag Air Ride Suspension, 209 in Wheelbase, PTO, 2008 curry supply Steel Tank, PTO Driven Pump, 6 ft 5 in, Spray Bar, Hose Reel, In-Cab Remote Controlled Water Cannon, Front Spray, Rear Spray Usage: 118,261 Mi Asset located in: Lake Worth, TX	956 956A	2012 Freightliner M2 106 4000 gal 6x4 Water Truck S/N: 1FVHCYBS3CHBS9418 C/W: Cummins ISB 6 Cylinder 8.3 L Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 4544.0 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 315 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Double Frame, Airliner Air Ride Suspension, 200 in Wheelbase, PTO, 2012 Ledwell 4000 gal Steel Tank, BERKELEY PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 35,988 Mi Asset located in: Midland, TX 2008 Peterbilt 340 6x4 Water Truck
953	2018 Kenworth T370 6x4 Water Truck S/N: 2NKHLJ9X7JM189233 C/W: Paccar 6 Cylinder Diesel Engine, US EPA Label, 4518.8 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 14600 lb Front Axle, 20000 lb Rears, 54600 lb GVWR, 12R22.5 Front Tires, 11R22.5 Rear Tires, 228 in Wheelbase, PTO Driven Pump, Front Spray, Rear Spray, Side Spray, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 30,539 Mi Asset located in: Lake Worth, TX		S/N: 2NPRLN9X48M764601 C/W: Paccar PX-8 6 Cylinder Diesel Engine, 13743 Engine hrs, Exhaust Brake, Allison 3000 Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, Spicer DSP41P Drive Axles, 5.57:1 Axle Ratio, 54600 lb GVWR, Aluminum Front Wheels, 11R22.5, Hendrickson Spring over Walking Beam Suspension, 196 in Wheelbase, PTO, Steel Tank, ARMS PTO Driven Pump, 5 ft, Spray Bar, Hose Reel, Rear Spray, Side Spray Usage: 53,003 Mi Asset located in: Lake Worth, TX
954	2014 International 5900I 4000 gal 6x4 Water Truck S/N: 3HSXYSNR9EN795890 C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 476 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 14777 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 285/75R24.5, Dual Steering Boxes, Air Ride Suspension, 214 in Wheelbase, Fiberglass Reinforced Plastic Tank Usage: 382,841 Mi Asset located in: Lake Worth, TX	957	2003 International 5600i 4500 gal 6x4 Water Truck S/N: 1HTXHAHT13J068496 C/W: Cummins ISM 320V 6 Cylinder Diesel 305 hp Engine, 19509 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 212 in Wheelbase, 2013 United Truck & Equipment 4500 gal Steel Tank, Franklin Electric Hydraulic Driven Pump, 6 ft 8 in, Spray Bar, In-Cab Remote Controlled Water Cannon, Rear Spray, Side Spray Usage: 159,456 Mi Asset located in: Lake Worth, TX
CHOIC 955	2014 Freightliner M2 106 4000 gal 6x4 Water Truck S/N: 1FVHCYCYOEHFN9171 C/W: Cummins ISL 6 Cylinder Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, 7676 Engine hrs, Eaton Fuller FRO-11210C 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.11:1 Axle Ratio, 58000 lb GVWR, 315/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 196 in Wheelbase, PTO, Ledwell LW4000 WT 4000 gal Steel Tank, PTO Driven Pump, 0 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 49,100 Mi Asset located in: Lake Worth, TX	960	1995 International 8200 6x4 Water Truck S/N: 1HSHGAER3SH682251 C/W: Cummins 6 Cylinder Diesel Engine, 31586 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Steel, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 164 in Wheelbase, 1 Compartments, PTO Driven Pump, Rear Spray Usage: 658,690 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
СНОІС	E OF 4 - Lot #'s: 961, 962, 963, 964	сноіс	E OF 2 - Lot #'s: 965, 966
961	2021 International MV607 2000 gal 4x2 Water Truck S/N: 3HAEUMMN0ML087250 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6485 Engine hrs, Automatic Transmission, 12350 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 151 in Wheelbase, PTO, Unused Lands Powder Coated 2000 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray	965	2014 International 4300 4x2 Water Truck S/N: 1HTMMAAM8EH467675 C/W: International 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 177,213 Mi Asset located in: Humble, TX
	Usage: 44,002 Mi	966	2013 International 4300 2000 gal 4x2 Water Truck
962	Asset located in: Lake Worth, TX 2019 International 4300 2500 gal 4x2 Water Truck S/N: 1HTMMMML3KH515096 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4450 Engine hrs, Automatic Transmission, 10000 lb Front Axle,		S/N: 1HTMMAAL4DH202404 C/W: 6 Cylinder Diesel Engine, 7386 Engine hrs, Automatic Transmission, Steel, 11R22.5, Air Ride Suspension, 156 in Wheelbase, PTO, 2000 gal Tank, 1 Compartments, 7 ft 6 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 238,027 Mi Asset located in: Lake Worth, TX
	17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 164 in Wheelbase, PTO, Unused Lands Powder Coated 2500 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 191,161 Mi Asset located in: Lake Worth, TX	968	2005 International 4200 2000 gal 4x2 Water Truck S/N: 1HTMPAFP95H166536 C/W: International VT365 6 Cylinder Diesel 215 hp Engine, 2004 US EPA Label, 5463 Engine hrs, 5-Speed Manual Transmission, 10000 lb
963	2019 International MA025 2500 gal 4x2 Water Truck S/N: 1HTMMMML4KH515138 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4769 Engine hrs,		Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5 Front Tires, 22.5 MIX Rear Tires, Spring Suspension, 152 in Wheelbase, PTO, Ledwell LW2000WT 2000 gal Steel Tank, Berkeley PTO Driven Pump, 6 ft 2 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 15,846 Mi
	Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 168 in Wheelbase, PTO, Unused Lands Powder Coated 2500 gal Steel Tank, PTO Driven Pump, Front Spray, Rear		Asset located in: Humble, TX E OF 2 - Lot #'s: 969, 970
	Spray, Side Spray Usage: 197,374 Mi	969	2013 Ford F-750 4x2 Water Truck
964	Asset located in: Lake Worth, TX 2018 International MA025 2000 gal 4x2 Water Truck S/N: 1HTMMMML0JH351983 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 6760 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 157 in Wheelbase, PTO, Unused Lands Powder Coated 2000 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 223,707 Mi		S/N: 3FRXF7FA1DV026323 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diese Exhaust Fluid, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 14,173 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
970	2013 Ford F-750 4x2 Water Truck S/N: 3FRXF7FA8DV026450 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 3997 Engine hrs, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 12,250 Mi Asset located in: Lake Worth, TX	975	2005 Ford F-650 XL 2000 gal 4x2 Water Truck S/N: 3FRNF65905V181715 C/W: Cat C7 6 Cylinder 7.2 L Diesel 350 hp Engine, 2005 US EPA Label, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 10R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, PTO, Niece 2000 gal Steel Tank, PTO Driven Pump, 7 ft, Spray Bar, Front Spray, Rear Spray Usage: 45,392 Mi Asset located in: Lake Worth, TX
971	2007 Ford F-750 XL 4x2 Water Truck S/N: 3FRWF75RX7V441258 C/W: Cat C7 6 Cylinder 7.2 L Diesel 230 hp Engine, 2006 US EPA Label, 5138.2 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, Aluminum Front Wheels, 11R22.5, Spring Suspension, 178 in Wheelbase, PTO, Tiger Steel Tank, Hydraulic Driven Pump, 7 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray		2001 International 4700 4x2 Water Truck S/N: 1HTSCAAM31H382229 C/W: International 6 Cylinder Diesel Engine, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, Steel, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, Hose Reel, Rear Spray Usage: 138,204 Mi Asset located in: Lake Worth, TX
972	Usage: 176,955 Mi Asset located in: Lake Worth, TX 2007 Ford F-750 4x2 Water Truck S/N: 3FRXF75N07V509486 C/W: Caterpillar C7 7.2 L Diesel Engine, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 162 in Wheelbase, PTO, Steel Tank, Berkeley PTO Driven Pump, 5 ft 5 in, Spray Bar, Rear Spray, Side Spray	977	2000 Sterling A9513 4x2 Water Truck S/N: 2FWWJWDBXYAB94058 C/W: Cat C12 6 Cylinder 12 L Diesel Engine, 5610 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 12000 lb Front Axle, 22000 lb Rears, 34000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 23,621 Mi Asset located in: Lake Worth, TX
	Usage: 19,377 Mi Asset located in: Lake Worth, TX		1998 International 4700 4x2 Water Truck
973	73 2003 Ford F-650 XL 4x2 Water Truck S/N: 3FDNF65AX3MB00757 C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 hp Engine, 2002 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, Steel Tank, Berkeley PTO		S/N: 1HTSCABN9WH510827 C/W: International T444E V8 7.3 L Diesel Engine, US EPA Label, 1166 Engine hrs, Spicer 6-Speed Manual Transmission, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft 8 in, Spray Bar, Front Spray, Rear Spray Usage: 15,286 Hr Asset located in: Lake Worth, TX
	Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 21,069 Mi Asset located in : Lake Worth, TX	979	1996 International 4700 4x2 Water Truck S/N: 1HTSCABN1TH276159 C/W: 6 Cylinder Diesel Engine, 9393 Engine hrs,
974	2008 Ford F-650 2000 gal 4x2 Water Truck S/N: 3FRNF65A88V660849 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2007 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 11R22. 5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 17,325 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 17,325, TITLE SHOWS 40,000 Asset located in: Lake Worth, TX		Automatic Transmission, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 182 in Wheelbase, Steel Tank, Pump w/ Engine, 8 ft, Spray Bar, Dribble Bar Usage: 233,739 Mi Asset located in: Lake Worth, TX
		980	1990 Ford L8000F 2000 gal 4x2 Water Truck S/N: 1FTXR82A2LVA15969 C/W: Ford 6 Cylinder 7.8 L Diesel 210 hp Engine, Manual Transmission, 9000 lb Front Axle, 21000 lb Rears, 30000 lb GVWR, Steel, 11R22.5, Spring Suspension, 150 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 6 ft 6 in, Spray Bar, Water Cannon, Front Spray, Rear Spray Usage: 457,293 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
981	2014 Freightliner M2 106 4x2 Propane Tanker Truck S/N: 3ALACXDT3EDFV6933	СНОІС	E OF 2 - Lot #'s: 986, 987
	C/W: Cummins ISB 6.7 L Diesel 280 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Allison 3500 6-Speed Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 6.14:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 207 in Wheelbase, Westmor 3200 gal Steel Tank, 2 Reels Usage: 302,437 Mi Asset located in: Lake Worth, TX 2019 Hino 338 2600 gal 4x2 Fuel Truck S/N: 5PVNV8JV1K4S58832 C/W: Hino J08E-VB 6 Cylinder 469 cid 260 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12537 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 197 in Wheelbase, PTO, 2600 gal Aluminum Tank, 3	S/I C/' EP Au 14 Sp in I	2015 Ford F-550 4x4 Fuel and Lube Truck S/N: 1FDUF5HT8FEB16131 C/W: V8 6.7 L Diesel 309 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 162 in Wheelbase, 10 ft 10 in Body, (2) Oil Tanks, (5) Hose Reels, Metered Nozzles, Oil Recovery System, AirnArc
982			150 Gasoline Generator Set, Ingersoll-Rand Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 172,086 Mi Asset located in : Lake Worth, TX
		СНОІС	E OF 1 - Lot #'s: 987
	Compartments, 2 Reels Usage: 274,979 Mi Notes : SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		2015 Ford F-550 4x4 Fuel and Lube Truck S/N: 1FDUF5HT5FEA45745 C/W: V8 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR,
	Asset located in: Lake Worth, TX		225/70R19.5, Spring Suspension, 165 in Wheelbase, CTEC 12 ft Body, (2) Oil Tanks, (6) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, NAPA 82133GTH 20 cfm Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM SUNSTATE-EQUIPMENT Usage: 129,968 Mi Asset located in: Lake Worth, TX
983	Parameter System (Color Power System (Color Po		
		СНОІС	E OF 2 - Lot #'s: 988, 989
		988	2014 Ford F-550 4x2 Fuel and Lube Truck
984			S/N: 1FDUF5GT4EEB70543 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft Body, (4) Hose Reels, Metered Nozzles, Vanair Gasoline Air Compressor, Air Hose Reel, Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 163,834 Mi Asset located in: Lake Worth, TX
	Wheelbase, PTO, 2008 1000 gal Steel Tank, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-	989	2013 Ford F-550 4x2 Fuel and Lube Truck
	CORP-COMPANY Usage: 269,399 Mi Notes: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Asset located in: Lake Worth, TX	לסלן 	S/N: 1FDUF5GT9DEA86667 C/W: 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 14 ft 4 in Body, (1) Diesel Tank, Metered Nozzles, Ingersoll-Rand Air Compressor, Air Hose Reel, Miller Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 120,748 Mi

Details Lot # **Details** Lot # 989A 992 2013 Ford F-550 XL 4x2 Fuel and Lube Truck 2013 Kenworth T800 8x4 Heavy Haul Tri/A Day S/N: 1FDUF5GT8DEB37379 **Cab Truck Tractor** C/W: Ford V8 6.7 L Diesel 300 hp Engine, 2013 S/N: 1XKDP4EX0DJ358004 US EPA Label, Requires Diesel Exhaust Fluid. C/W: Cummins ISX15 6 Cylinder 15 L Diesel 550 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18818 Engine hrs, Engine Brake, Eaton Fuller 8-Speed Manual Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, IMT 11 ft Body, (3) Oil Tanks, (4) Hose Reels, Transmission, Double Differential Locks, 20000 Metered Nozzles, Air Hose Reel, Vanair Air N Ib Front Axle, 66000 lb Rears, 4.10:1 Axle Ratio, Arc 150 All-In-One Power System, EQUIPMENT-80000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 FROM-SUNSTATE-EQUIPMENT Usage: 211,871 Mi Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Double Frame, 8-Bag Asset located in: Lake Worth, TX Air Ride Suspension, 258 in Wheelbase, PTO, 990 2024 Peterbilt 567 8x4 Heavy Haul Tri/A Day Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,162 Mi Cab Truck Tractor S/N: 1XPCP4EX2RD669008 Asset located in: Lake Worth, TX C/W: Cummins X15 6 Cylinder 15 L Diesel 565 993 2013 Peterbilt 579 8x4 Tri/A Day Cab Truck hp Engine, 2023 US EPÁ Label, Requires Diesel Tractor Exhaust Fluid, Eaton Fuller 18-Speed Manual Transmission, 20000 lb Front Axle, 66280 lb S/N: 1XPBD49X9DD193833 Rears, 80000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20865.5 Engine hrs, Engine 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Brake, Eaton Fuller Manual Transmission, Suspension, 273 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks 13200 lb Front Axle, 38000 lb Rears, 51200.0 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Lift Pusher Axle, Paccar Air Ride Usage: 696 Mi Asset located in: Lake Worth, TX Suspension, 244 in Wheelbase, PTO, Air Sliding 2013 Peterbilt 389 8x4 Heavy Haul Tri/A Day 991 5th Wheel, Headache Rack, Dual Fuel Tanks **Cab Truck Tractor** Usage: 585,366 Mi S/N: 1XPXP4EX8DD177786 Asset located in: Lake Worth, TX C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 600 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20678.2 Engine hrs, 994 2001 Peterbilt 379 8x4 Tri/A Day Cab Truck Tractor Engine Brake, Eaton Fuller 18-Speed S/N: 1XP5PBEXX1D567716 Transmission, Double Differential Locks, 20000 C/W: Cat C15 6 Cylinder 15.2 L Diesel 475 hp Ib Front Axle, 60400 lb Rears, 80000 lb GVWR, Engine, Engine Brake, Eaton Fuller RTLO-Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher 16918B 18-Speed Manual Transmission, 14060 lb Front Axle, 63000 lb Rears, Spicer DS463P Drive Axles, 3.90:1 Axle Ratio, 77060 lb GVWR, Air Ride Cab, 385/65R22.5 Front Axle, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 265 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Tires, 315/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 461,474 Mi Usage: 656,865 Mi Notes: JUNE 2023 - COMPLETE LONG BLOCK Asset located in: Lake Worth, TX ENGINE REPLACEMENT; THIS UNIT RUNS 995 2009 Mack CHU613 8x4 Tri/A Day Cab Truck BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS Tractor S/N: 1M2AN07Y39N003780 **ADMINISTRATIVE CODE SECTIONS 114.20** C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 16784 Engine AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE hrs, Mack MAXITORQUE 18-Speed Manual Transmission, 11R24.5, Air Lift Tag Axle, RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN

Camelback Spring Suspension, Air Sliding 5th Wheel, Rolling Tailboard, Dual Fuel Tanks Usage: 258,896 Mi

Asset located in: Lake Worth, TX

ACKNOWLEDGEMENT FORM OF THIS NOTICE

PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW

Details Lot # **Details** Lot # 995A 997 2008 Mack CHU613 8x4 Tri/A Day Cab Truck 2021 Peterbilt 389 8x4 Tri/A Sleeper Truck **Tractor** Tractor S/N: 1M1AN07Y98N002197 S/N: 1XPXP4EX9MD740781 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 C/W: Cummins X15 6 Cylinder 15 L Diesel 605 hp Engine, 2007 US EPA Label, 6242 Engine hrs, Engine Brake, Eaton Fuller 18-Speed hp Engine, 2020 US EPÁ Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Manual Transmission, 13220 lb Front Axle, Speed Manual Transmission, 20000 lb Front 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Axle, 66000 lb Rears, 80000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Aluminum Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, 243 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Steering Boxes, Air Ride Suspension, Air Sliding Rack 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 591,040 Mi Usage: 290,846 Mi Asset located in: Lake Worth, TX Notes: THIS UNIT RUNS BUT MAY HAVE 996 2007 Mack CHN613 8x4 Heavy Haul Tri/A Day **DEFICIENCIES IN ITS POLLUTION CONTROL** Cab Truck Tractor SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS S/N: 1M1AJ07Y57N007228 114.20 AND 114.50. THIS MAY APPLY IF YOU C/W: Mack AC 6 Cylinder 11.9 L Diesel 460 hp Engine, 2005 US EPA Label, 13255 Engine hrs, OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY Engine Brake, Mack Maxitorque 18-Speed Manual Transmission, Differential Lock, 20000 EQUIPPED. BUYER OF THIS UNIT MUST SIGN Ib Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, ACKNOWLEDGEMENT FORM OF THIS NOTICE 11R24.5 Rear Tires, Air Lift Pusher Axle, Twin Y PRIOR TO REMOVAL OF UNIT FROM YARD Air Ride Suspension, 254 in Wheelbase, PTO, Asset located in: Lake Worth, TX Wet Kit, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION 997A 2021 Western Star 4900EX 8x4 Heavy Haul Tri /A Sleeper Truck Tractor Usage: 272,150 Mi S/N: 5KJNABD18MPMG3713 **Notes**: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2020 US EPA Label, Requires Diesel SECTION BELOW Exhaust Fluid, 13055.3 Engine hrs, Eaton Fuller RTLO-20918B 18-Speed Manual Transmission, Asset located in: Lake Worth, TX 18000 lb Front Axle, 66000 lb Rears, Meritor RT-46-160P Drive Axles, 3.73:1 Axle Ratio, 83300 996A 2000 Western Star 4964EX 8x4 Tri/A Day Cab lb GVWR, 82 in Mid Roof Sleeper Cab, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Truck Tractor S/N: 2WKEDDCJ2YK963807 Steerable Air Lift Pusher Axle, Airliner Air Ride C/W: Cat 3406 6 Cylinder 14.6 L Diesel 475 hp Suspension, 291 in Wheelbase, Air Sliding 5th Engine, Engine Brake, Eaton Fuller 18-Speed Wheel, Dual Fuel Tanks Manual Transmission, Differential Lock, 12000 Usage: 295,587 Mi lb Front Axle, 58000 lb GVWR, Air Ride Cab, Notes: LOCATED-IN-FORT-WORTH-TX PER Aluminum Outer Wheels, 11R24.5, Air Lift THE DEALER ACTUAL MILEAGE IS HIGHER Pusher Axle, Air Lift Tag Axle, Air over Walking THAN SHOWING ON ODO AND ECM - TRUE Beam Suspension, 222 in Wheelbase, Air MILEAGE IS UNKNOWN Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 594,259 Mi 997B 2012 Peterbilt 367 8x6 Heavy Haul Tri/A Asset located in: Lake Worth, TX Sleeper Truck Tractor S/N: 1XPTP4EX7CD136935 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 20857 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual

485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 20857 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 18000 lb Front Axle, 66000 lb Rears, 87000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 260 in Wheelbase, PTO

Usage: 528,928 Mi

Details Lot # **Details** Lot # 998 2015 Kenworth T800 Wide Hood 8x4 Tri/A Sleeper Truck Tractor CHOICE OF 6 - Lot #'s: 1002, 1003, 1004, 1005, 1006, 100 S/N: 1XKDP4TX3FJ427032 C/W: Cummins ISX15 15.0 L 550 hp Engine, 1002 2018 Peterbilt 389 6x4 T/A Day Cab Truck 2014 US EPA Label, Requires Diesel Exhaust Fluid, 9997 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 18-Speed Manual Tractor S/N: 1XPXD49X0JD468877 Transmission, 20000 lb Front Axle, 46000 lb C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11115 Engine hrs, Engine Rears, Dana D46-170H Drive Axles, 3.91:1 Axle Ratio, 86000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 425 Brake, Eaton Fuller 10-Speed Manual /65R22.5 Front Tires, 285/75R24.5 Rear Tires, Transmission, Differential Lock, 13200 lb Front Air Lift Pusher Axle, Dual Steering Boxes, Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, Paccar Air Ride Double Frame, Hendrickson Primaax EX Air Ride Suspension, 278 in Wheelbase, Air Sliding Suspension, 218 in Wheelbase, Air Sliding 5th 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-A-Wheel Usage: 239,179 Mi PRIMORIS-SERVICES-CORP-COMPANY Asset located in: Lake Worth, TX Usage: 356,920 Mi **Notes: EQUIPMENT FROM A PRIMORIS** 1003 2018 Peterbilt 389 6x4 T/A Day Cab Truck SERVICES CORP COMPANY Tractor Asset located in: Midland, TX S/N: 1XPXD49X3JD468940 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 999 2008 Western Star 4900 8x4 Tri/A Sleeper 450 hp Engine, 2017 US EPA Label, Requires **Truck Tractor** Diesel Exhaust Fluid, 12339 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual S/N: 5KJNALAV48PZ19813 C/W: Cat C15 6 Cylinder 14.6 L Diesel 550 hp Transmission, 13200 lb Front Axle, 40000 lb Engine, Engine Brake, Eaton Fuller RTLO-Rears, 53200 lb GVWR, Air Ride Cab, Aluminum 22918B 18-Speed Manual Transmission, Wheels, 11R24.5, Paccar Air Ride Suspension, 20000 lb Front Axle, 66000 lb Rears, 4.56:1 216 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Axle Ratio, 78150 lb GVWR, Air Ride Cab, 40 in Wheel Mid Roof Sleeper Cab, Aluminum Wheels, 425 Usage: 251,546 Mi /65R22.5 Front Tires, 11R22.5 Rear Tires, Air Asset located in: Lake Worth, TX Lift Pusher Axle, Dual Steering Boxes, Airliner Air Ride Suspension, 265 in Wheelbase, Air 1004 2018 Peterbilt 389 6x4 T/A Day Cab Truck Sliding 5th Wheel, Headache Rack, Lowboy Tractor Ramps, Dual Fuel Tanks S/N: 1XPXD49X1JD468922 Usage: 777,671 Mi C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12890 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Asset located in: Lake Worth, TX 1000 2020 Peterbilt 389 6x4 T/A Day Cab Truck Tractor Transmission, Differential Lock, 13200 lb Front S/N: 1XPXD49X4LD636684 Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride C/W: Cummins X15 6 Cylinder 15 L Diesel 500 Cab, Aluminum Wheels, 11R24.5, Paccar Air hp Engine, 2019 US EPA Label, Requires Diesel Ride Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 254,950 Mi Exhaust Fluid, 13970 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Asset located in: Lake Worth, TX Aluminum Wheels, 11R24.5, Air Trac Air Ride 1005 2018 Peterbilt 389 6x4 T/A Day Cab Truck Suspension, 240 in Wheelbase, Headache Tractor Rack, Dual Fuel Tanks S/N: 1XPXD49X0JD468958 Usage: 391,604 Mi C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11932.4 Engine hrs, Asset located in: Lake Worth, TX 1001 2019 Peterbilt 389 6x4 T/A Day Cab Truck Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, Tractor S/N: 1XPXD49X0KD266266 C/W: Cummins X15 6 Cylinder 15 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel 11R24.5 Rear Tires, Paccar Air Ride Exhaust Fluid, 17028 Engine hrs, 18-Speed Suspension, 216 in Wheelbase, PTO, Wet Kit, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 11R24.5, Air Hydraulic Oil Cooler, Air Sliding 5th Wheel Usage: 261,845 Mi Ride Suspension, 238 in Wheelbase, Air Sliding Asset located in: Lake Worth, TX 5th Wheel Usage: 470,871 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1006	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X0JD468930 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12410.3 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Paccar Air Ride Suspension, 242 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: Not Available Asset located in: Lake Worth, TX	1010	2012 Peterbilt 388 6x4 T/A Day Cab Truck Tractor S/N: 1XPWDP0X1CD140235 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18806.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, 11R24.5, Air Trac Air Ride Suspension, 214 in Wheelbase, Dual Fuel Tanks Usage: 306,786 Mi Asset located in: Lake Worth, TX	
1007	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X4JD468879 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12212 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 292,060 Mi Asset located in: Lake Worth, TX	1011 2 3 5 6 7 8 8 8 8	Tractor S/N: 1XPTD40X3GD334935 C/W: Cummins ISX15 6 Cylinder 15 485 hp Engine, 2015 US EPA Label, Compliant, Requires Diesel Exhaust 5172.2 Engine hrs, Engine Brake, Ea Manual Transmission, Double Differ Locks, 14320 lb Front Axle, 46000 lb 60320 lb GVWR, Air Ride Cab, Alumi Wheels, 11R24.5, Air Trac Air Ride S	S/N: 1XPTD40X3GD334935 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5172.2 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel,
1009	2012 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXDP9X2CD158752 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 17118.9 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Trac Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 350,526 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	1012	Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 181,470 Mi Notes: Asset located in: Humble, TX 2016 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTD40X5GD334936 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 99,798 Mi Notes: Asset located in: Humble, TX	
		1013	2016 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTD40X7GD334940 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7220.5 Engine hrs, Engine Brake, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, 11R24.5, Air Trac Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 131,902 Mi	

Asset located in: Humble, TX

Details Lot # **Details** Lot # 1014 1022 2016 Peterbilt 367 6x6 T/A Day Cab Truck 2020 Kenworth T800 6x4 T/A Day Cab Truck **Tractor Tractor** S/N: 1XPTD40X7GD334937 S/N: 1XKDD40X1LR369030 C/W: Cummins ISX15 6 Cylinder 15 L Diesel C/W: Cummins X15 6 Cylinder 15 L Ultra Low 485 hp Engine, 2015 US EPA Label, CARB Sulfur Diesel 450 hp Engine, 2019 US EPA Compliant, Requires Diesel Exhaust Fluid, 5526.6 Engine hrs, Engine Brake, Eaton Fuller Label, Requires Diesel Exhaust Fluid, 19464 Engine hrs, Engine Brake, Automatic 18-Speed Manual Transmission, Double Transmission, 14320 lb Front Axle, 46000 lb Rears, 60321 lb GVWR, Air Ride Cab, Aluminum Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Suspension, 224 in Wheelbase, Air Sliding 5th Tanks Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-Usage: 305,184 Mi Asset located in: Lake Worth, TX CORP-COMPANY Usage: 208,518 Mi 1023 2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor Notes: . S/N: 1XKDD40X2LR369036 Asset located in: Humble, TX C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10215 Engine hrs, Engine CHOICE OF 6 - Lot #'s: 1017, 1020, 1021, 1022, 1023, 1024 Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 1017 2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor 5, 8-Bag Air Ride Suspension, 215 in S/N: 3WKDD40X9LF369053 Wheelbase, Air Sliding 5th Wheel, Dual Fuel C/W: Cummins X15 6 Cylinder 15 L Ultra Low Tanks Sulfur Diesel 450 hp Engine, 2019 US EPA Usage: 112,632 Mi Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 14320 lb Front Asset located in: Lake Worth, TX Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride 1024 Cab, Aluminum Wheels, 11R24.5, Air Ride Tractor Suspension, 217 in Wheelbase, Air Sliding 5th S/N: 3WKDD40XXLF369059 Wheel, Dual Fuel Tanks Usage: 525,807 Mi Asset located in: Lake Worth, TX 1020 2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X8LF369044

C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 21597.7 Engine hrs, Eaton Fuller FAO-16810C 10-Speed Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, Dana D46-170 Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 216 in Wheelbase, PTO, Blower, Dual Fuel Tanks

Usage: 363,166 Mi

Asset located in: Lake Worth, TX

1021 2020 Kenworth T800 6x4 T/A Day Cab Truck **Tractor**

S/N: 3WKDD40X2LF369055 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 18503.8 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 243 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 262,049 Mi

Asset located in: Lake Worth, TX

2020 Kenworth T800 6x4 T/A Day Cab Truck

C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9057 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, 8-Bag Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 100,288 Mi

Asset located in: Lake Worth, TX

CHOICE OF 6 - Lot #'s: 1025, 1026, 1027, 1028, 1029, 103

1025 2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor

S/N: 3WKDD40X7KF257267 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23462.2 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 243 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 358,214 Mi

Details Lot# **Details** Lot # 1026 1030 2019 Kenworth T800 6x4 T/A Day Cab Truck 2019 Kenworth T800 6x4 T/A Day Cab Truck **Tractor** Tractor S/N: 3WKDD40X9KF257268 S/N: 3WKDD40XXKF369089 C/W: Cummins X15 6 Cylinder Diesel Engine, C/W: Cummins X15 6 Cylinder 15 L Diesel 450 Requires Diesel Exhaust Fluid, 23630.9 Engine hrs, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19786 Engine hrs, Engine Brake, Automatic Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, Dana D46-172 Drive Axles, 3.73:1 Axle Ratio, Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Wheel, Dual Fuel Tanks Usage: 279,656 Mi Tires, Air Ride Suspension, 216 in Wheelbase, Asset located in: Lake Worth, TX PTO, Air Sliding 5th Wheel, Blower, Dual Fuel 1027 Tanks 2019 Kenworth T800 6x4 T/A Day Cab Truck Usage: 325,018 Mi Tractor Asset located in: Lake Worth, TX S/N: 3WKDD40X7KF369101 C/W: Cummins ISX15 6 Cylinder 15 L 450 hp 1031 2014 Kenworth T800 6x4 T/A Day Cab Truck Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19647 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, Tractor S/N: 1XKDDP9X7EJ387103 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb C/W: Paccar MX 6 Cylinder 12.9 L Engine, 2012 GVWR, Aluminum Outer Wheels, 11R24.5, Air US EPA Label, Requires Diesel Exhaust Fluid, Ride Suspension, 215 in Wheelbase, Air Sliding 15503 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential 5th Wheel, Dual Fuel Tanks Usage: 338,611 Mi Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Asset located in: Lake Worth, TX Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel 2019 Kenworth T800 6x4 T/A Day Cab Truck 1028 Usage: 324,545 Mi **Tractor** Asset located in: Lake Worth, TX S/N: 3WKDD40X6KF257275 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 1032 2014 Kenworth T800 6x4 T/A Day Cab Truck Engine, 16403.1 Engine hrs, Engine Brake, Eaton UltraShift Plus Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb Tractor S/N: 1XKDDP9X9EJ404502 GVWR, Air Ride Cab, Aluminum Wheels, 11R24. C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11282 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed 5, AG400 8-Bag Air Ride Suspension, 243 in Wheelbase, Blower, Dual Fuel Tanks Usage: 237,353 Mi Manual Transmission, Differential Lock, 12350 Asset located in: Lake Worth, TX Ib Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 3.70:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, 1029 2019 Kenworth T800 6x4 T/A Day Cab Truck **Tractor** Airglide Suspension, 185 in Wheelbase, PTO, S/N: 3WKDD40X7KF369082 Wet Kit, Air Sliding 5th Wheel, Headache Rack, C/W: Cummins X15 V10 15 L 450 hp Engine, **Dual Fuel Tanks** 2018 US EPA Label, CARB Compliant, 19985 Usage: 282,261 Mi Engine hrs, Eaton Fuller UltraShift Plus 18-Asset located in: Lake Worth, TX Speed Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, 1033 2014 Kenworth T800 6x4 T/A Day Cab Truck Aluminum Wheels, 11R24.5, AG400 8-Bag Air Tractor Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Blower S/N: 1XKDDP9XXEJ367542 Usage: 298,935 Mi C/W: Paccar 6 Cylinder 12.9 L 455 hp Engine, 2012 US EPA Label, 13028 Engine hrs, Eaton Asset located in: Lake Worth, TX Fuller FO-16E313A-MHP ULT Automatic Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 52000 lb GVWR. Aluminum Wheels. 295/75R22.

Asset located in: Humble, TX

Fuel Tanks Usage: 297,728 Mi

5, 8-Bag Air Ride Suspension, 194 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual

Lot #	Details	Lot #	Details
СНОІСІ	E OF 2 - Lot #'s: 1035, 1036	СНОІСІ	E OF 6 - Lot #'s: 1038, 1039, 1040, 1041, 1042, 104
1035	2012 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9X2CJ335276 C/W: Paccar MX 6 Cylinder 12.9 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18030 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.55:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 343,666 Mi Asset located in: Lake Worth, TX	Tractor S/N: 1XKZDP9 C/W: EQUIPMENT Usage: 241,49 Asset located 1039 2016 Kenwort Tractor S/N: 1XKZDP9 C/W: Paccar N 430 hp Engine Diesel Exhaus 10-Speed Man Front Axle, 400 3.70:1 Axle Ra Aluminum Fro Suspension, 1 Wheel, Headaus SUNSTATE-E0 Usage: 293,72	S/N: 1XKZDP9XXGJ495370 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 241,499 Mi Asset located in: Lake Worth, TX 2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X2GJ495377 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FR015210C 10-Speed Manual Transmission, 13200 lb
1036	2012 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9X0CJ335275 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 181 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed		Front Axle, 40000 lb Rears, Detroit Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 293,721 Mi Asset located in: Lake Worth, TX
Manual Transmissio 40000 lb Rears, Dan Ratio, 52350 lb GVW Front Wheels, 11R22 Suspension, 187 in V Air Sliding 5th Whee Usage: 297,724 Mi	Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, Dana Drive Axles, 3.55:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Suspension, 187 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 297,724 Mi Asset located in: Lake Worth, TX	1040	2016 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X1GJ495371 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 276,776 Mi Asset located in: Lake Worth, TX
1037	2012 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD40X4CR298390 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 500 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 17475 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.89:1 Axle Ratio, 60321 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Neway Air Ride Suspension, 209 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: 324,740 Mi	1041	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9XXGJ486765 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 269,329 Mi Asset located in: Lake Worth, TX
1037A	2018 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X1JJ215858 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8375 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel Usage: 237,444 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1042	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X0GJ495376 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Double Frame, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 280,242 Mi Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 1043 2016 Kenworth T880 6x4 T/A Day Cab Truck **Tractor** CHOICE OF 3 - Lot #'s: 1046, 1047, 1048 S/N: 1XKZDP9X3GJ495372 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires 1046 2022 Peterbilt 567 6x4 T/A Day Cab Truck Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Tractor FRO-15210C Manual Transmission, 13200 lb S/N: 1XPCD49X8ND788534 Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2021 US EPA Label, Requires Diesel 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase, Air Sliding 5th Wheel, Headache Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Rack, EQUIPMENT-FROM-SUNSTATE-Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 226 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks **EQUIPMENT** Usage: 352,092 Mi Asset located in: Lake Worth, TX Usage: 140,650 Mi 1043A 2016 Kenworth T880 6x4 T/A Day Cab Truck Asset located in: Lake Worth, TX Tractor 1047 2022 Peterbilt 567 6x4 T/A Day Cab Truck S/N: 1XKZDP9X6GJ486763 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Tractor 430 hp Engine, 2015 US EPA Label, Requires S/N: 1XPCD49X4ND788532 Diesel Exhaust Fluid, 16144.0 Engine hrs, C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, US EPA Label, Requires Diesel Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, 8-Bag Air Ride Suspension, 186 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-Aluminum Wheels, 11R24.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks SUNSTATE-EQUIPMENT Usage: 152,789 Mi Usage: 282,982 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1048 2022 Peterbilt 567 6x4 T/A Day Cab Truck Tractor CHOICE OF 2 - Lot #'s: 1044, 1045 S/N: 1XPCD49X6ND788533 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2021 US EPA Label, Requires Diesel 1044 2015 Kenworth T880 6x4 T/A Day Cab Truck Exhaust Fluid, 4410 Engine hrs, Engine Brake, Tractor Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. S/N: 1XKZDP9XXFJ445423 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2014 US EPA Label, Requires 5, Air Trac Air Ride Suspension, 226 in Diesel Exhaust Fluid, 15520 Engine hrs, Engine Wheelbase, Air Sliding 5th Wheel, Dual Fuel Brake, Eaton Fuller FRO-15210C 10-Speed Tanks Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb Usage: 106,800 Mi Asset located in: Lake Worth, TX GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-CHOICE OF 2 - Lot #'s: 1049, 1050 **EQUIPMENT** Usage: 376,184 Mi 1049 2020 Peterbilt 567 6x4 T/A Day Cab Truck Asset located in: Lake Worth, TX **Tractor** S/N: 1NPCD40X8LD649153 1045 2015 Kenworth T880 6x4 T/A Day Cab Truck C/W: Cummins X15 6 Cylinder 15 L Diesel 500 **Tractor** hp Engine, 2019 US EPÁ Label, Requires Diesel S/N: 1XKZDP9X8FJ425865 Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2014 US EPA Label, Requires 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Aluminum Wheels, 11R24.5, Dual Steering FRO-15210C 10-Speed Manual Transmission, Boxes, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Fuel Tanks

Usage: 198,766 Mi

Asset located in: Lake Worth, TX

Aluminum Front Wheels, 11R22.5, Air Ride

Suspension, 187 in Wheelbase, Air Sliding 5th

Wheel, Headache Rack, EQUIPMENT-FROM-

SUNSTATE-EQUIPMENT Usage: 316,151 Mi

			1 age 07 01 301
Lot #	Details	Lot #	Details
1050	2019 Peterbilt 567 6x4 T/A Day Cab Truck Tractor	1055	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor
	S/N: 1XPCD40X7KD611272 C/W: Cummins X15 6 Cylinder 15 L Diesel 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 239,603 Mi Asset located in: Lake Worth, TX		S/N: 1XPSD79X3FD262701 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 27922 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, Blower, Dual Fuel Tanks Usage: 719,738 Mi Asset located in: Lake Worth, TX
	Asset located III. Lake Worth, TA	1056	
1051	Tractor S/N: 1XPSD79X6GD332564 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27335.9 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual		2014 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X7ED225682 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2013 US EPA Label, 35544 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 203 in Wheelbase, Auto Lube Usage: 620,451 Mi Asset located in: Lake Worth, TX
	Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube Usage: 596,995 Mi Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - MAIN KEY Asset located in: Lake Worth, TX	10564	
		485 hp Engine, 2011 US EPA Label, Compliant, Requires Diesel Exhaust 17714 Engine hrs, Engine Brake, Eate 8LL Manual Transmission, 14600 lb 46000 lb Rears, 60600 lb GVWR, Air Aluminum Outer Wheels, 11R24.5, A Suspension, 206 in Wheelbase, Air S Wheel, Headache Rack, Dual Fuel Ta Usage: 344,254 Mi Asset located in: Lake Worth, TX	Tractor S/N: 2XPTD40X9CM137840 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid,
1053	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X4GD332529 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24210 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission,		8LL Manual Transmission, 14600 lb Front Axle, 46000 lb Rears, 60600 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 344,254 Mi
	13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 206 in Wheelbase, PTO, Blower, Auto Lube Usage: 565,546 Mi		E OF 8 - Lot #'s: 1058, 1059, 1060, 1061, 1062,
	Asset located in: Lake Worth, TX	1058	2020 Freightliner SD122 6x4 T/A Day Cab
1054	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X9FD262699 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20820 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 206 in Wheelbase, PTO, Blower, Auto Lube Usage: 553,424 Mi	Truck Tractor S/N: 3AKJGNDV2LDLZ5581 C/W: Detroit DD13 6 Cylinder 12 hp Engine, 2019 US EPA Label, I Exhaust Fluid, 6973 Engine hrs, Allison 4700 RDS Automatic Tra 13300 lb Front Axle, 46000 lb Ro 46-160P Drive Axles, 4.30:1 Axlo lb GVWR, Air Ride Cab, Steel, 11 Hendrickson Air Ride Suspension	Truck Tractor S/N: 3AKJGNDV2LDLZ5581 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6973 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, 13300 lb Front Axle, 46000 lb Rears, Meritor RT- 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, Steel, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 109,108 Mi

Details Lot # **Details** Lot # 1059 2020 Freightliner SD122 6x4 T/A Day Cab 1063 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor Truck Tractor** S/N: 3AKJGNDV3LDMF6934 S/N: 3AKJGNDV4LDLZ5582 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8183 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7090.33 Engine hrs, Engine Brake, Allison Automatic Transmission, 13300 Engine hrs, Engine Brake, Allison 4700 RDS Ib Front Axle, 46000 lb Rears, Air Ride Cab, All Automatic Transmission, Differential Lock, Steel, 11R24.5, Hendrickson Air Ride 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Suspension, 196 in Wheelbase, Air Sliding 5th Whėel Air Ride Suspension, 196 in Wheelbase, Air Usage: 109,592 Mi Sliding 5th Wheel Usage: 139,306 Mi Asset located in: Lake Worth, TX 1060 2020 Freightliner SD122 6x4 T/A Day Cab Asset located in: Lake Worth, TX **Truck Tractor** 1064 2020 Freightliner SD122 6x4 T/A Day Cab S/N: 3AKJGNDV6LDLZ5583 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel **Truck Tractor** S/N: 3AKJGNDV5LDMF6935 Exhaust Fluid, 8086 Engine hrs, Engine Brake, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Allison 4700 RDS Automatic Transmission, hp Engine, 2019 US EPA Label, Requires Diesel Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Exhaust Fluid, 7764 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Axle Ratio, 59300 lb GVWR, Air Ride Cab, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 114,295 Mi 11R24.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 144,087 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1061 2020 Freightliner SD122 6x4 T/A Day Cab 1065 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor Truck Tractor** S/N: 3AKJGNDV8LDMF6945 S/N: 3AKJGNDV0LDMF6938 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7577 Engine hrs, Engine Brake, hp Engine, 2019 US EPA Label, Requires Diesel Allison 4700 RDS Automatic Transmission, Exhaust Fluid, 8251.39 Engine hrs, Engine 13300 lb Front Axle, 46000 lb Rears, Meritor RT-Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 Ib GVWR, Air Ride Cab, All Steel, 11R24.5, Hendrickson Air Ride Suspension, 196 in Axles, 4.30:1 Axle Ratio, Air Ride Cab, All Steel, Wheelbase, Air Sliding 5th Wheel Usage: 125,283 Mi 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Asset located in: Lake Worth, TX Usage: 146,736 Mi 2020 Freightliner SD122 6x4 T/A Day Cab 1062 Asset located in: Lake Worth, TX **Truck Tractor** S/N: 3AKJGNDV6LDMF6944 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 CHOICE OF 8 - Lot #'s: 1066, 1067, 1068, 1069, 1070, hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7652 Engine hrs, Engine Brake, 1071, 1072, 1073 Allison 4700 RDS Automatic Transmission,

S/N: 3AKJGNDV6LDMF6944 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7652 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 137,436 Mi

Asset located in: Lake Worth, TX

1066 2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGNDV2LDMF6942 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6915 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 149,353 Mi

Details Lot # **Details** Lot # 1067 2020 Freightliner SD122 6x4 T/A Day Cab 1071 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor Truck Tractor** S/N: 3AKJGNDVXLDMF6946 S/N: 3AKJGNDV2LDMF6939 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8294 Engine hrs, Engine Brake, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7122.12 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Allison 4700 RDS Automatic Transmission, Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 59300 Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24. lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air 5 Rear Tires, Hendrickson Air Ride Suspension, Sliding 5th Wheel 196 in Wheelbase, Air Sliding 5th Wheel Usage: 182,995 Mi Usage: 158,266 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1072 2020 Freightliner SD122 6x4 T/A Day Cab 1068 2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor **Truck Tractor** S/N: 3AKJGNDV4LDMF6943 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8575.57 Engine hrs, Engine S/N: 3AKJGNDV7LDMF6936 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Brake, Allison 4700 RDS Automatic Exhaust Fluid, 8247 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, Air Ride Cab, 11R24.5, Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Hendrickson Air Ride Suspension, 196 in Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Wheelbase, Air Sliding 5th Wheel Usage: 206,153 Mi Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 159,984 Mi Asset located in: Lake Worth, TX 1073 2020 Freightliner SD122 6x4 T/A Day Cab Asset located in: Lake Worth, TX Truck Tractor 1069 2020 Freightliner SD122 6x4 T/A Day Cab S/N: 3AKJGNDV9LDMF6937 **Truck Tractor** C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel S/N: 3AKJGNDV0LDMF6941 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8897.09 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Exhaust Fluid, 7204 Engine hrs, Engine Brake, Allison 4700 RDS 6-Speed Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24. 5 Rear Tires, Hendrickson Air Ride Suspension, Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5, Hendrickson Air 196 in Wheelbase, Air Sliding 5th Wheel Ride Suspension, 196 in Wheelbase, Air Sliding Usage: 212,117 Mi 5th Wheel Asset located in: Lake Worth, TX Usage: 163,146 Mi 1074 2019 Freightliner Coronado 122SD 6x4 T/A Asset located in: Lake Worth, TX **Day Cab Truck Tractor** 1070 2020 Freightliner SD122 6x4 T/A Day Cab S/N: 3AKJGNDR5KDKK3918 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Truck Tractor S/N: 3AKJGNDV9LDMF6940 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Exhaust Fluid, 12990 Engine hrs, Engine Brake,

S/N: 3AKJGNDV9LDMF6940 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7512.45 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel

Usage: 166,473 Mi

Asset located in: Lake Worth, TX

S/N: 3AKJGNDR5KDKK3918 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12990 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.58:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks

Usage: 497,607 Mi

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 1075, 1076	сноіс	E OF 2 - Lot #'s: 1079, 1080
1075	2014 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV4EDFU3235 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 9972 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.91:1 Axle Ratio, 52000 lb GVWR, 275 /80R22.5, Airliner Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 210,817 Mi Asset located in: Lake Worth, TX	1079	2015 Western Star 4700 6x4 T/A Day Cab Truck Tractor S/N: 5KJJAVDV9FPGC9066 C/W: Detroit DD13 12.8 L Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 220 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 537,904 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
1076	2014 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGND64EDFT1921 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 18532 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner 4-Bag Air Ride Suspension, 224 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 394,360 Mi	1080	2015 Western Star 4700 6x4 T/A Day Cab Truck Tractor S/N: 5KJJAVDV4FLGW9017 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 hp Engine, Requires Diesel Exhaust Fluid, 13494 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 3.91:1 Axle Ratio, 58000 lb GVWR, Air Ride Cab, 11R24.5, Airliner Air Ride Suspension, 210 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 325,533 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1082	2012 Cat CT660S 6x4 T/A Day Cab Truck
СНОІС 1077	2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 1FVXFB00XBDBC0203 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb		Tractor S/N: 1HTJGTKT7CJ635078 C/W: Cat CT13 6 Cylinder 13 L Diesel Engine, 2011 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 70000 lb GVWR, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, 241 in Wheelbase Usage: 123,545 Mi Asset located in: Humble, TX
	Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks Usage: 669,379 Mi	СНОІС	E OF 2 - Lot #'s: 1083, 1084
	Asset located in: Lake Worth, TX	1083	2017 International 8600 6x4 T/A Day Cab
1078	2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 1FVXFB008BDBC0202 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 709,338 Mi	1000	Truck Tractor S/N: 3HSHXSNRXHN412325 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 430 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8150 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295 /75R22.5, Air Ride Suspension, 176 in Wheelbase, Dual Fuel Tanks Usage: 355,024 Mi Asset located in: Lake Worth, TX

			Page 93 of 581
Lot #	Details	Lot #	Details
1084	2014 International 8600 6x4 T/A Day Cab Truck Tractor S/N: 1HSHXSJR4EH754607 C/W: Navistar N13 6 Cylinder 13 L Diesel Engine, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 169 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available Asset located in: Humble, TX	1088	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X6PD875834 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2323 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Air Leaf Air Ride Suspension, 190 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 72,678 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1085	2013 International 7500 6x4 T/A Day Cab Truck Tractor		THE INSPECTION REPORT .
	S/N: 1HSWPAZR8DJ239297		Asset located in: Humble, TX
CHOIC 1086	C/W: International International 570 6 Cylinder 9.3 L Diesel Engine, 2012 US EPA Label, 5501 Engine hrs, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, PTO, Wet Kit Usage: 28,123 Mi Asset located in: Lake Worth, TX E OF 4 - Lot #'s: 1086, 1087, 1088, 1089 2023 Peterbilt 579 6x4 T/A Day Cab Truck	1089	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X8PD875835 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3195 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Leaf Air Ride Suspension, 189 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 77,420 Mi Notes: Asset located in: Humble, TX
	Tractor S/N: 1XPBDP9X2PD889441	1089A	
	C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2693 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 186 in Wheelbase, Wet Kit, Air Sliding 5th Wheel Usage: 54,153 Mi Notes: . Asset located in: Humble, TX		Tractor S/N: 1XPBAK9X2ND758793 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 5233.9 Engine hrs, Engine Brake, Paccar Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 150 in Wheelbase, Air Sliding 5th Wheel Usage: 231,143 Mi Asset located in: Lake Worth, TX
1087	2023 Peterbilt 579 6x4 T/A Day Cab Truck	1090	2020 Peterbilt 579 6x2 T/A Day Cab Truck
	Tractor S/N: 1XPBDP9X4PD889442 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3278 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 192 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 62,819 Mi		Tractor S/N: 1XPBAK9X6LD656295 C/W: Paccar MX11 6 Cylinder 10.8 L Diesel Engine, 2019 US EPA Label, 9406 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Rear Tires, Paccar 4-Bag Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,689 Mi

Asset located in: Lake Worth, TX

Notes: .

Asset located in: Humble, TX

Details Lot # **Details** Lot # 1091 2019 Peterbilt 579 6x4 T/A Day Cab Truck 1095 2019 Mack Pinnacle 6x4 T/A Day Cab Truck **Tractor** Tractor S/N: 1XPBD49X5KD619305 S/N: 1M1PN4GY4KM002736 C/W: Cummins ISX15 6 Cylinder Diesel Engine, C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10474.6 Engine hrs, Engine Brake, hp Engine, 2018 US ÉPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Automated Transmission, 12000 lb Front Axle, 19000 lb Rears, 50000 lb GVWR, Air Ride Cab, Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Aluminum Wheels, 11R22.5 Front Tires, 11R22. Wheels, 11R24.5, Air Ride Suspension, 227 in 5 Rear Tires, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Tanks Usage: 429,136 Mi Usage: 153,131 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1096 2019 Freightliner Cascadia 126 6x4 T/A Day 1092 2022 Mack PI64T 6x4 T/A Day Cab Truck **Cab Truck Tractor Tractor** S/N: 1FUJHLDR2KLKW2362 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel S/N: 1M1PN4GY9NM010092 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Exhaust Fluid, Engine Brake, Mack MDrive 12-Transmission, Differential Lock, 13300 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 53300 Speed Automated Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5 Front Tires, 275/80R22.5 Rear Tires, Wheels, 11R24.5, Neway Air Ride Suspension, Airliner 4-Bag Air Ride Suspension, 183 in 225 in Wheelbase, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available **Tanks** Usage: 621,528 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX Asset located in: Humble, TX 1098 2021 Freightliner Cascadia 116 6x4 T/A Day 1093 2019 Mack AN64T 6x4 T/A Day Cab Truck Cab Truck Tractor S/N: 3AKJHTDV3MSMF5488 Tractor C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 S/N: 1M1AN2GY6KM008144 hp Engine, 2020 US EPA Label, CARB C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Compliant, Requires Diesel Exhaust Fluid, 9731 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Exhaust Fluid, 11664 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 184 in Wheelbase Suspension, 174 in Wheelbase Usage: 356,606 Mi Usage: 517,765 Mi Notes: THIS UNIT RUNS BUT MAY HAVE Asset located in: Lake Worth, TX **DEFICIENCIES IN ITS POLLUTION CONTROL** SYSTEMS WITH LIABILITIES OUTLINED IN 1094 2019 Mack AN64T 6x4 T/A Day Cab Truck TEXAS ADMINISTRATIVE CODE SECTIONS Tractor 114.20 AND 114.50. THIS MAY APPLY IF YOU S/N: 1M1AN4GY6KM003456 OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2018 US EPA Label, Requires Diesel SYSTEMS OR DEVICES AS ORIGINALLY Exhaust Fluid, 15036 Engine hrs, Engine Brake, EQUIPPED. BUYER OF THIS UNIT MUST SIGN Mack mDrive Automatic Transmission, 12500 ACKNOWLEDGEMENT FORM OF THIS NOTICE lb Front Axle, 40000 lb Rears, 52500.0 lb PRIOR TO REMOVAL OF UNIT FROM YARD GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 189 in Wheelbase, Air Sliding Asset located in: Lake Worth, TX 5th Wheel, Dual Fuel Tanks 1100 2019 International LT625 6x4 T/A Day Cab Usage: 743,483 Mi **Truck Tractor** Asset located in: Humble, TX S/N: 3HCDZAPR8KL194089 C/W: Cummins X15 505 6 Cylinder 15.0 L Diesel 505 hp Engine, 2018 ÚS EPA Label, Requires Diesel Exhaust Fluid, 10422 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 199 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, **Dual Fuel Tanks**

Usage: 171,523 Mi

Lot #	Details	Lot #	Details
1101	2018 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X1JD490933 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 455/50R22.5 Rear Tires, Paccar Air Ride Suspension, 168 in Wheelbase Usage: Not Available Asset located in: Lake Worth, TX	1105	2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X9DD190443 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Leaf Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel Usage: 346,321 Mi Asset located in: Humble, TX
1102	2017 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X1HD387523 C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19516 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 11R24.5, Paccar Air Ride Suspension, 192 in Wheelbase, PTO, Blower Usage: 731,511 Mi Asset located in: Lake Worth, TX	1106	2012 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHD49X2CD135202 C/W: Cummins ISX15 15.0 L Diesel 500 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 20630 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Trac Air Ride Suspension, 212 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 372,724 Mi
CHUIC	CHOICE OF 3 - Lot #'s: 1103, 1104, 1105		Asset located in: Lake Worth, TX
1103	2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X5DD190441 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Leaf Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel	1108	2015 Kenworth T680 6x2 T/A Day Cab Truck Tractor S/N: 1XKYAP9X7FJ437901 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 34000 lb Rears, 3.42:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22. 5, Flex Air Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: 575,781 Mi Asset located in: Lake Worth, TX
1104	Usage: 783,395 Mi Asset located in: Humble, TX 2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X7DD190442 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20012 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Leaf 4-Bag Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel Usage: 382,740 Mi Asset located in: Humble, TX	1111	2015 Kenworth T370 T/A Day Cab Truck Tractor S/N: 2XKHAJ8XXFM458197 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 212,393 Hr Asset located in: Lake Worth, TX 2017 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1HM081245 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 4592 Engine hrs, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 204 in Wheelbase Usage: 569,651 Mi

Asset located in: Humble, TX

			Page 96 of 581
Lot #	Details	Lot #	Details
CHOIC 1113	Tractor S/N: 1M1AW09YXGM056302 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual	1117	2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y3EM036867 C/W: Mack 6 Cylinder 10.8 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, Air Ride Suspension, 222 in Wheelbase Usage: 384,415 Mi Asset located in: Lake Worth, TX
	Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 174,528 Mi Asset located in: Lake Worth, TX	1118	2012 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y8CM017308 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 11235 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 12000
1114	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW09Y6GM056281 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 7091 Engine hrs, Engine Brake,	Ib Front Axle, 38000 lb Rears, 5000 Air Ride Cab, Aluminum Wheels, 11 Y Air Ride Suspension, 182 in Wheel Wet Kit, Air Sliding 5th Wheel Usage: 300,710 Mi Asset located in: Lake Worth, TX 1119 2018 Mack CHU613 6x4 T/A Day O Tractor S/N: 1M1AN07YXJM027640 C/W: Mack MP8 6 Cylinder 12.8 L I hp Engine, 2017 US EPA Label, Rec Exhaust Fluid, Engine Brake, Eaton Speed Manual Transmission, 1200 Axle, 40000 lb Rears, 52000 lb GVV Cab, Aluminum Wheels, 11R24.5, A Suspension, 220 in Wheelbase, PT Air Sliding 5th Wheel, Dual Fuel Tai Usage: 590,377 Mi Notes: DEFICIENCIES NOTED - PLE THE INSPECTION REPORT Asset located in: Humble, TX	lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Twin Y Air Ride Suspension, 182 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 300,710 Mi
	Mack 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, 4-Bag Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 192,351 Mi Asset located in: Lake Worth, TX		S/N: 1M1AN07YXJM027640 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front
1115	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y7FM048675 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26801 Engine hrs, Engine Brake, Mack MDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR,		Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 590,377 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	295/75R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 271,385 Mi		E OF 5 - Lot #'s: 1121, 1122, 1123, 1125, 1126
	Asset located in: Lake Worth, TX	1121	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor
СНОІС 1116	E OF 2 - Lot #'s: 1116, 1117 2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y4EM043164 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Eyhaust Fluid Engine Brake, Faton Fuller 13-		S/N: 1M2AN07Y0EM015773 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 32141 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Hendrickson Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks Usage: 731,351 Mi

Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 190 in Wheelbase Usage: 484,651 Mi

Asset located in: Humble, TX

Usage: 731,351 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1122	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07YXEM016719		E OF 2 - Lot #'s: 1127, 1128
	C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 478,839 Mi Asset located in: Lake Worth, TX	1127	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y8DM011473 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum
1123	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y5EM015669		Outer Wheels, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 536,413 Mi
	C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel		Asset located in: Lake Worth, TX
	Exhaust Fluid, Mack Automatic Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, 11R24.5, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 569,098 Mi Asset located in: Lake Worth, TX	1128	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y5DM014492 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack
1125	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y0DM013475 C/W: Mack MP8 6 Cylinder 12.7 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 22679 lb GVWR, 11R24.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 847,795 Mi		MAXITORQUE 13-Speed Manual Transmissio 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheelbal Fuel Tanks Usage: 488,617 Mi Asset located in: Humble, TX
		1129	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y1DM014095
1126	Asset located in: Lake Worth, TX 2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y5DM014066 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 31299 Engine hrs, Engine Brake, Mack 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks		
	Fuel Tanks Usage: 767,495 Mi Asset located in : Lake Worth, TX	1130	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y1DM013920 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack MaxiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, 11P24 5 Spring over Walking Ream

11R24.5, Spring over Walking Beam Suspension, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: 211,417 Mi

		_	
Lot #	Details	Lot #	Details
1132	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07YXCM010660 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MultiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 97,753 Mi Asset located in: Lake Worth, TX	1138	2011 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y6BM006995 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 963 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Twin Y Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 333,241 Mi
CHOICE	E OF 3 - Lot #'s: 1133, 1136, 1137		Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN
1133	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y8CM008989 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Mack maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 511,996 Mi Asset located in: Lake Worth, TX		TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
1136	2012 Mack CHU613 6x4 T/A Day Cab Truck	сноісі	E OF 1 - Lot #'s: 1139
	Tractor S/N: 1M1AN07Y3CM009662 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28676 Engine hrs, Mack 8-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Mack Drive Axles, 50000 lb GVWR, Air Ride Cab, 11R24.5, Twin Y Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 732,133 Mi Asset located in: Lake Worth, TX	1139	2019 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDR8KSKM6301 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16826 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer
1137	·	Wheels, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding S Wheel, Dual Fuel Tanks Usage: 760,027 Mi	Wheels, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 760,027 Mi
	Requires Diesel Exhaust Fluid, 18044 Engine hrs, Engine Brake, Mack 8-Speed Manual	1141	Asset located in: Lake Worth, TX
	Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, 4-Bag Air Ride Suspension, 219 in Wheelbase, Dual Fuel Tanks Usage: 710,969 Mi Asset located in: Lake Worth, TX	1141	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV7JSJK4542 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10452 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 393,960 Mi

Lot # Details Lot # Details

CHOICE OF 3 - Lot #'s: 1142, 1143, 1144

1142 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV6JDJN8606 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Brake, Detroit DT12-OB-1650 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Air Assist Front Suspension, Airliner Air Ride Suspension, 183 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 870,330 Mi

Asset located in: Lake Worth, TX

1143 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV0JDJN8598 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OB-1650HD 12-Speed Automated Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22. 5, Air Assist Front Suspension, Air Ride Suspension, 183 in Wheelbase, PTO Usage: 852,283 Mi

Asset located in: Lake Worth, TX

1144 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDR1JDJW5319 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 9924 Engine hrs, Engine Brake, Detroit DT12-OA-1650 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,742 Mi

Asset located in: Lake Worth, TX

1145 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV7JSJH2022 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 520,949 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1146, 1147

1146 2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV9HSJB4181 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 550,503 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

1147 2017 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor

S/N: 1FUGGEDV1HLJF1652 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 485,070 Mi

Asset located in: Humble, TX

CHOICE OF 2 - Lot #'s: 1149, 1150

1149 2016 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor

S/N: 3AKGGEDV4GDHC4943 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.50:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 850,687 Mi

Page 100 of 581 **Details** Lot # **Details** Lot # 1150 2015 Freightliner Cascadia 125 6x4 T/A Day 1152 2013 Freightliner Cascadia 125 6x4 T/A Day **Cab Truck Tractor Cab Truck Tractor** S/N: 1FUJGED63FLGD5692 S/N: 1FUJGEDV1DSBV1048 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15861 Engine hrs, Engine Brake, Engine, Requires Diesel Exhaust Fluid, 7413 Engine hrs, Engine Brake, Eaton Fuller FRO-Eaton Fuller 10-Speed Manual Transmission, 15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, Spicer DS404 Drive Axles, 3.70:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, PTO, Wet Kit, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel **Dual Fuel Tanks** Tanks Usage: 570,528 Mi Usage: 675,354 Mi Asset located in: Lake Worth, TX Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - CPC 1150A 2015 Freightliner Cascadia 125 6x2 T/A Day Asset located in: Lake Worth, TX Cab Truck Tractor 1153 2012 Freightliner Cascadia 125 6x4 T/A Day S/N: 3AKGGEDV8FSGK3449 C/W: Detroit 6 Cylinder Engine, 2015 US EPA **Cab Truck Tractor** Label, Requires Diesel Exhaust Fluid, 21446 S/N: 1FUJGEDR3CSBM7925 Engine hrs, Eaton Fuller 10-Speed Manual C/W: Detroit 6 Cylinder Diesel Engine, 1828.42 Engine hrs, Automated Transmission, 13300 lb Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Front Axle, 46000 lb Rears, 59300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tanks Suspension, 151 in Wheelbase, Air Sliding 5th Usage: 512,461 Mi Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-Asset located in: Lake Worth, TX YELLOW-CORP Usage: Not Available Notes: SELLING WITH A BANKRUPTCY CHOICE OF 2 - Lot #'s: 1154, 1155 DOCUMENTS AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; ALL INOPERABLE ITEMS 1154 2019 Freightliner Cascadia 113 6x4 T/A Day NEED TO BE REMOVED FROM THE YARD BY **Cab Truck Tractor** SEPTEMBER 20th CAN NOT BE RECONSIGNED S/N: 1FUJGBDV3KLKT7979 BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, INSPECTION REPORT 13571 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 5.25:1 Axle Ratio, 52000 lb GVWR, Air Asset located in: Livingston, LA 1150B 2015 Freightliner Cascadia 125 6x2 T/A Day Ride Cab, Aluminum Wheels, 275/80R22.5 Cab Truck Tractor Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 184 in Wheelbase, PTO, Air Sliding 5th Wheel S/N: 3AKGGEDV8FSGK3628 C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp Engine, 2022 US EPA Label, Requires Diesel Usage: 535,686 Mi Exhaust Fluid, 8724 Engine hrs, Engine Brake, Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 176 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP

Usage: 912,917 Mi

Notes: CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; DEFICIENCIES NOTED - PLEASE

SEE THE INSPECTION REPORT Asset located in: Humble, TX

1155 2019 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor

Asset located in: Humble, TX

S/N: 1FUJGBDV5KLKT7983 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 12590 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275 /80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Ride Suspension, 184 in Wheelbase, Air Sliding 5th Wheel

Usage: 484,854 Mi

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 1156, 1157	1160	2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1ELLIGRDV/4RSRR6320
1156	2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGBDV7GDHA6151 C/W: Detroit DD13 6 Cylinder 12.8 L 380 hp Engine, Requires Diesel Exhaust Fluid, 17605 Engine hrs, Retarder, Detroit DT12-DB-1450 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Dual Fuel Tanks Usage: 520,442 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1161	S/N: 1FUJGBDV4BSBB6320 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 8206 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, Air Ride Cab, 275/80R22.5, Airliner Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 856,222 Mi Asset located in: Lake Worth, TX 2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV6BSBB6321 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 29567 Engine hrs, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission,
1157	Asset located in: Humble, TX 2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDVXGLGS4295 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel		12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 869,100 Mi Asset located in: Lake Worth, TX
	Exhaust Fluid, 11444 Engine hrs, Engine Brake, Detroit DT12-OB-1450 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 355,568 Mi Asset located in: Lake Worth, TX	CHOIC 1162	E OF 2 - Lot #'s: 1162, 1163 2015 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1911 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 500 hp Engine, 15249 Engine hrs, Engine Brake,
CHOIC 1158	E OF 3 - Lot #'s: 1158, 1159, 1160 2011 Freightliner Cascadia 113 6x4 T/A Day	Eaton Fuller 10-Speed Manual Trai 12000 lb Front Axle, 3.73:1 Axle Ra GVWR, Air Ride Cab, Aluminum Fro 295/75R22.5, Airliner Air Ride Sus in Wheelbase, PTO, Wet Kit, Air Slie Wheel, Headache Rack, Dual Fuel Kit Usage: 697,934 Mi Asset located in: Lake Worth, TX 1163 2015 Freightliner Columbia 120 6x Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1908 C/W: Detroit Series 60 6 Cylinder 1 500 hp Engine, 17818 Engine hrs, I Eaton Fuller 10-Speed Manual Trai 3.73:1 Axle Ratio, Air Ride Cab, Alu Outer Wheels, 295/75R22.5, Airline	Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 3.73:1 Axle Ratio, 12000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider
1136	Cab Truck Tractor S/N: 1FUJGBDV5BSBB6309 C/W: Detroit 6 Cylinder Diesel Engine, Requires		Kit Usage: 697,934 Mi
	Diesel Exhaust Fluid, 2153 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 861,133 Mi Asset located in: Lake Worth, TX		•
1159	2011 Freightliner Cascadia 113 6x4 S/A Day Cab Truck Tractor S/N: 1FUJGBDV9BSAX2724 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 1001 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 36576 lb Rears, 48546 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 884,817 Mi		Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider Kit Usage: 333,663 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1163A	2021 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EG1MN286031 C/W: Volvo D13 6 Cylinder Diesel 405 hp Engine, 7784 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50000 lb GVWR, 275/80R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 286,472 Mi Asset located in: Lake Worth, TX	СНОІСІ	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPRXJN404541 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11699 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb
CHOICE	E OF 2 - Lot #'s: 1164, 1165 2016 Volvo VNM T/A Day Cab Truck Tractor		Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 274,941 Mi Asset located in: Lake Worth, TX
	S/N: 4V4MC9EG8GN967797 Usage: Not Available Asset located in : Lake Worth, TX	1169	2018 International HX620 6x4 T/A Day Cab Truck Tractor
1165	2016 Volvo VNM T/A Day Cab Truck Tractor S/N: 4V4MC9EGXGN972144 Usage: Not Available Asset located in: Lake Worth, TX	450 hp Engine, 2017 US EPA Lab Diesel Exhaust Fluid, 14368 Eng Brake, Eaton Fuller 10-Speed Ma	C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14368 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual
1166	2016 Volvo VNL 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG4GN973794 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2358 Engine hrs, Engine Brake, Volvo Automatic Transmission, 12350	Rears, 53200 lb GVWR, Air Rider Wheels, 11R24.5, Hendrickson A Suspension, 205 in Wheelbase, I Hydraulic Oil Cooler, Dual Fuel T Usage: 277,391 Mi Asset located in: Lake Worth, TX 1700 2018 International HX620 6x4 T 1700 2018 International HX620	Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminu Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 277,391 Mi Asset located in : Lake Worth, TX
	lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 805,146 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3HSDTAPR4JN405670 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12721 Engine hrs, Engi Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb
1167	2016 Volvo VNL300 6x2 T/A Day Cab Truck Tractor S/N: 4V4NC9EH7GN941916 C/W: Volvo D13J435 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires		Wheels, 11R24.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks
	Diesel Exhaust Fluid, Volvo ATO2612D 12- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 503,664 Mi Asset located in: Lake Worth, TX		S/N: 3HSDTAPR8JN406076 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12523 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks

Lot #	Details	Lot #	Details
1172	2018 International HX620 6x4 T/A Day Cab Truck Tractor	1176	2018 International HX620 6x4 T/A Day Cab Truck Tractor
	S/N: 3HSDTAPR9JN404529 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13473 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 208 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: Not Available		S/N: 3HSDTAPR6JN405671 C/W: Cummins X15 6 Cylinder 15 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 40000 kg Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson 4-Bag Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 375,019 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1177	2016 International Prostar+122 6x4 T/A Day
1173	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR3JN405675 C/W: Cummins X15 6 Cylinder 15 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15260 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5 Front Tires, 11R24.5 Rear Tires, Hendrickson 4-Bag Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 329,456 Mi		Cab Truck Tractor S/N: 3HSDJSNR4GN748793 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 13825 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 390,546 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX
1174	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR2JN405652 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14783 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 206 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 330,024 Mi Asset located in: Lake Worth, TX	1178	2011 International Prostar 6x2 T/A Day Cab Truck Tractor S/N: 3HSCUAPRXBN346408 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2009 US EPA Label, 15012 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 148 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 28,954 Mi Notes: THE AGE AND CONDITION OF THE TRUCK INDICATES MORE MILES THAN SHOWN ON THE ODOMETER Asset located in: Lake Worth, TX
1175	2018 International HX620 6x4 T/A Day Cab Truck Tractor	-	Asset located III. Lake WORIN, 1X
	S/N: 3HSDTAPR5JN404544 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15215 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 331,216 Mi	CHOIC	2006 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5DB9X16D644337 C/W: Cat C15 6 Cylinder 15.2 L Diesel 435 hp Engine, 2005 US EPA Label, CARB Compliant, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb

S/N: 1XP5DB9X16D644337 C/W: Cat C15 6 Cylinder 15.2 L Diesel 435 hp Engine, 2005 US EPA Label, CARB Compliant, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 1,086,784 Mi

Notes: ENGINE REBUILD NOVEMBER 2024

Asset located in: Humble, TX

Usage: 331,216 Mi

Lot #	Details	Lot #	Details
1182	2006 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5DB9X56D648777 C/W: Cat C15 6 Cylinder 15 L Diesel Engine, Engine Brake, Eaton Fuller 15-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 652,502 Mi Asset located in: Lake Worth, TX	1187	2005 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X45R086045 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Manual Transmission, 3.70: 1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 675,236 Mi Asset located in: Lake Worth, TX
	Asset located III. Lake Worth, 1A	1189	1990 Peterbilt 379 6x4 T/A Day Cab Truck
CHOICI	E OF 2 - Lot #'s: 1183, 1184		Tractor S/N: 1XP5D29X1LN295315
			C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 9-Speed
1183	2009 Kenworth T800 T/A Day Cab Truck Tractor S/N: 1XKDD49X49J255212 Usage: Not Available Asset located in: Lake Worth, TX		Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 11R24.5, Air Trac Air Ride Suspension, 227 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 211,059 Mi
1184	2008 Kenworth T800 6x4 T/A Day Cab Truck		Asset located in: Humble, TX
	Tractor S/N: 1XKDD49X38J237363 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2007 US EPA Label, CARB Compliant, 17065 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 162 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 508,579 Mi Asset located in: Lake Worth, TX	1190	2009 Peterbilt 384 6x4 T/A Day Cab Truck Tractor S/N: 1XPVD09X29D784986 C/W: Cummins 6 Cylinder Diesel 425 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 191 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	The state of the s	1	Usage: 310,703 Mi Asset located in: Lake Worth, TX
CHOICI	E OF 3 - Lot #'s: 1185, 1186, 1187		Addet located III. Lake Worth, TX
0110101	2 01 0 201 // 01 1100, 1100,	СНОІС	E OF 2 - Lot #'s: 1191, 1193
1185	2007 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X37R154046 C/W: Cat C13 6 Cylinder 12.5 L Diesel 430 hp Engine, 2006 US EPA Label, 19630 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 81,923 Mi	1191 2008 Mack CHU613 6x4 T/A Day 0 Tractor S/N: 1M1AN09Y98N001127 C/W: Mack MP8 6 Cylinder 12.8 L hp Engine, 2006 US EPA Label, Eng Manual Transmission, 12000 lb Fr 38000 lb Rears, 50000 lb GVWR, A Aluminum Front Wheels, 11R24.5, Spring Suspension, 218 in Wheelb	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y98N001127 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 485 hp Engine, 2006 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks
	Asset located in: Lake Worth, TX	4	Notes: DEFICIENCIES NOTED - PLEASE SEE
1186	2006 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X46R114993 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.70:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 202 in Wheelbase, Dual Fuel Tanks Usage: 566,399 Mi Asset located in: Lake Worth, TX	THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
1193	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y58N003666 C/W: Mack MP8 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 60,062 Mi Asset located in: Lake Worth, TX	1199	2003 Mack CX613 Vision 6x4 T/A Day Cab Truck Tractor S/N: 1M1AE07Y23W014985 C/W: Mack AC 6 Cylinder 12.0 L Diesel Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 285/75 /24.5, Air Lift Pusher Axle, Air Ride Suspension, 242 in Wheelbase, PTO, Wet Kit, Hydraulic System, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,917 Mi Asset located in: Humble, TX	
CHOIC	E OF 3 - Lot #'s: 1194, 1195, 1196	1200	2009 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor	
1194	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y68N001683 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2006 US EPA Label, 11687 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 206 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 437,607 Mi	Engine, 2008 US EPA Label, Requires Exhaust Fluid, 15762.4 Engine hrs, Ea 10-Speed Manual Transmission, 1200 Front Axle, 40000 lb Rears, 52000.0 lb Air Ride Cab, Aluminum Front Wheels Airliner Air Ride Suspension, 178 in W Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 225,283 Mi	C/W: Detroit Series 60 6 Cylinder 14 L Diesel Engine, 2008 US EPA Label, Requires Diesel Exhaust Fluid, 15762.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 225,283 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	Asset located in: Lake Worth, TX	CHOIC	CHOICE OF 2 - Lot #'s: 1201, 1202	
1195	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y48N001827 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 37,316 Mi Asset located in: Lake Worth, TX	1201 2007 Freightliner Columbia 120 6: Cab Truck Tractor S/N: 1FUJA6CK97DZ42349 C/W: Detroit Series 60 6 Cylinder 515 hp Engine, 2006 US EPA Labe Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 12000 lb Fi 40000 lb Rears, 3.73:1 Axle Ratio, GVWR, Air Ride Cab, 11R22.5, Airli Suspension, 174 in Wheelbase, Ai Wheel, Dual Fuel Tanks Usage: 901,926 Mi Asset located in: Lake Worth, TX 1202 2006 Freightliner Columbia 120 6: Cab Truck Tractor S/N: 1FUJA6CK36LX13895 C/W: Detroit Series 60 6 Cylinder 455 hp Engine, 8563 Engine hrs, E Eaton Fuller FRO-15210C 10-Speet Transmission, Meritor RT-40-145 4.11:1 Axle Ratio, Air Ride Cab, 11 Airliner Air Ride Suspension, 182 i	S/N: 1FUJA6CK97DZ42349 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride	
1196	2007 Mack CHU613 6x4 T/A Day Cab Truck Tractor		Wheel, Dual Fuel Tanks Usage: 901,926 Mi	
	S/N: 1M1AJ06Y47N008341 C/W: Mack 6 Cylinder Diesel Engine, 14078 Engine hrs, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, 11R24.5, Camelback Suspension, 207 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 85,326 Mi Asset located in: Lake Worth, TX		S/N: 1FUJA6CK36LX13895 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 8563 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 182 in Wheelbase,	
1198	2006 Mack CV713 6x4 Cab and Chassis S/N: 1M2AG11Y96M034378 C/W: Mack AI 6 Cylinder 12.0 L Diesel Engine, 20885 Engine hrs, Manual Transmission, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Hendrickson Air Ride Suspension, 215 in Wheelbase Usage: 282,800 Mi Asset located in: Lake Worth, TX		Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 174,408 Mi Asset located in : Lake Worth, TX	

			Page 106 of 581
Lot #	Details	Lot #	Details
1204	2009 Volvo VNL300 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG89N270007 C/W: Volvo D13F405 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 1272 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50000 lb GVWR, Steel, 295/75R22.5, Air Ride Suspension, 168 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 607,811 Mi Asset located in: Lake Worth, TX	1210	2017 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDP9X6HR157986 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 500 hp Engine, 2016 US EPA Label, Engine Brake, Eaton Fuller FRO-18210C 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, 3.55: 1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 28 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 232 in Wheelbase, Dual Fuel Tanks Usage: 626,873 Mi
СНОІС	E OF 2 - Lot #'s: 1206, 9694A		Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU
1206	2008 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG98N498365 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 375 hp Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, Aluminum	OPERATE THE UNIT PRIOR TO THE RESTORATION OF ALL POLLUTION SYSTEMS OR DEVICES AS ORIGINA EQUIPPED. BUYER OF THIS UNIT MI ACKNOWLEDGEMENT FORM OF TH PRIOR TO REMOVAL OF UNIT FROM	OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX
	Wheels, 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 167 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,449,683 Mi		E OF 6 - Lot #'s: 1212, 1213, 1214, 1215, 1216, 121
	Asset located in: Lake Worth, TX	1212	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor
1209	2019 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X1KJ257014 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15624 Engine hrs, Engine Brake,		S/N: 1XPXD49XXLD648550 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 40155 Engine hrs, Engine Brake, 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb

Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, 75 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275 /80R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 286 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 662,371 Mi

Asset located in: Lake Worth, TX

Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 259 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 306,491 Mi

Asset located in: Lake Worth, TX

1213 2020 Peterbilt 389 6x4 T/A Sleeper Truck **Tractor**

S/N: 1XPXD49X3LD648549 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 39980 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 266,350 Mi

Lot #	Details	Lot #	Details
1214	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor	1218	2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor
	S/N: 1XPXD49X1LD702883 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 261 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 273,148 Mi		S/N: 1XPXD49X3KD273048 C/W: Cummins X15 6 Cylinder 14.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 24049 Engine hrs, Engine Brake, Eaton Fuller RTLO 189-18B 18-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 78 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Paccar Air Ride Suspension, 281 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 582,536 Mi
1215	Asset located in: Lake Worth, TX	1219	Asset located in: Humble, TX
	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X5LD648553 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, 266 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 276,137 Mi Asset located in: Lake Worth, TX		2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3GD369706 C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 57373 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 5320 lb GVWR, 63 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 261 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,399 Mi
1216	2019 Peterbilt 389 6x4 T/A Sleeper Truck	1000	Asset located in: Humble, TX
	Tractor S/N: 1XPXD49X6KD612210 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39162 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 259 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 330,281 Mi	1220	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X2FD291241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 23876 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Wet Kit, Dual Fuel Tanks Usage: 402,552 Mi
1017	Asset located in: Lake Worth, TX	_	Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT .
1217	2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor		Asset located in: Humble, TX
	S/N: 1XPXD49X9KD611195 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39138 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Suspension, 259 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 313,841 Mi Asset located in: Lake Worth, TX	1220A	Tractor S/N: 1XPXD49X9FD268605 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26545 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 260 in Wheelbase, Dual Fuel Tanks Usage: 573,398 Mi

This catalog was created at December 10, 2024 03:25:22 PM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Midland, TX

Lot #	Details	Lot #	Details
1221	2012 Peterbilt 388 6x4 T/A Sleeper Truck Tractor S/N: 1XPWD40X9CD164118 C/W: Cummins 6 Cylinder Diesel Engine, 15073.9 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 273 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 326,225 Mi Asset located in: Lake Worth, TX 2015 Peterbilt 567 6x4 T/A Sleeper Truck	1225 1225A	2011 Freightliner Coronado 122 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGNDR6BDBB8157 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 391 Engine hrs, Engine Brake, Eaton Fuller RTLO- 16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.90:1 Axle Ratio, Air Ride Cab, 34 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 11R24.5 Rear Tires, Airliner Air Ride Suspension, 245 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	Tractor		Usage: 6,330 Mi Asset located in: Lake Worth, TX
1223	S/N: 1XPCDP9X2FD297265 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21748.4 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 39000 lb Rears, 52200 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,572 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT . Asset located in: Humble, TX 2013 Kenworth T800 6x4 T/A Sleeper Truck		·
1224	Tractor S/N: 1XKDD49X1DJ346141 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 62 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Headache Rack Usage: 637,776 Mi Asset located in: Lake Worth, TX 2018 Freightliner Coronado 122SD 6x4 T/A	1226	2019 Western Star 4900FA 6x4 T/A Sleeper Truck Tractor S/N: 5KJJAEDRXKPKC9060 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Eaton Fuller RTLO 13-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,054 Mi Notes: SELLING WITH A REPOSESSION
	Sleeper Truck Tractor S/N: 3AKJGNDR7JDJV8925 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automated Transmission, 52350.0 lb GVWR, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 264 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	сноіс	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX E OF 4 - Lot #'s: 1230, 1231, 1232, 1233
	Usage: 485,348 Mi Asset located in : Lake Worth, TX	1230	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X2LJ317474
			C/W: Paccar 6 Cylinder Engine, 12173 Engine

S/N: 1XKYDP9X2LJ317474 C/W: Paccar 6 Cylinder Engine, 12173 Engine hrs, Paccar P016F112C Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Paccar Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, 75 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Sliding 5th Wheel Usage: 523,545 Mi

Lot #	Details	Lot #	Details
1231	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 3WKYD49X5LF407169 C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10333 Engine hrs, Engine Brake, Eaton Fuller 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 53200 lb GVWR, 76 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 481,871 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1233A	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X7LJ344640 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 340 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15907 Engine hrs, Engine Brake, Paccar 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT4014x3 Drive Axles, 2.79:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 474,515 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
1232	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X4LJ348287 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15421 Engine hrs, Engine Brake, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52500.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 589,051 Mi Asset located in: Humble, TX	1234	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X2KJ220594 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 25999 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 295/75R22.5, Paccar Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 608,021 Mi
1233	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3LJ357819 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16890.8 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 660,370 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	1235	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X6KJ236748 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23865 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks Usage: 632,548 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

			C
Lot #	Details	Lot #	Details
1236	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X3KJ239771 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 13393 Engine hrs, Engine Brake, Paccar PO-16F112 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 2.79:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 75 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 581,308 Mi Asset located in: Humble, TX	1240	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X5MD741828 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 8557.7 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 461,648 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
1237	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor		Asset located in: Lake Worth, TX
1238	S/N: 1XKYDP9X2KJ257324 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar P0- 16F112 Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, TriPac evolution Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,832 Km Asset located in: Humble, TX 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3KJ247254	1241	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7MD755875 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 19042 Engine hrs, Engine Brake, Paccar Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	C/W: Cummins X15 15 L 450 hp Engine, 2018		Asset located in: Lake Worth, TX
CHOIC	US EPA Label, Requires Diesel Exhaust Fluid, 14976.3 Engine hrs, Engine Brake, Eaton Fuller EED-16F112C 12-Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.79: 1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 692,453 Mi Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1239, 1240, 1241	1242	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2KD263251 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23729 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Paccar Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 671,185 Mi Asset located in: Midland, TX
1239	2022 Peterbilt 579 6x4 T/A Sleeper Truck Tractor	1243	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7KD601681 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel

S/N: 1XPBD49X7ND782896 C/W: Cummins X15 6 Cylinder 15.0 L 500 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 8204 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 359,739 Mi

Asset located in: Lake Worth, TX

S/N: 1XPBDP9X7KD601681 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15553 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Bunk Heater, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 245 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 756,792 Mi

Asset located in: Humble, TX

Details Lot # **Details** Lot # 1244 2019 Peterbilt 579 6x4 T/A Sleeper Truck 1248 2022 Freightliner Cascadia 126 6x4 T/A Tractor Sleeper Truck Tractor S/N: 1XPBDP9X9KD607207 S/N: 3AKJHHDV6NSMY0047 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-HL 12-Speed Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, 12000 lb Front Axle, 40000 lb Automated Transmission, 12350 lb Front Axle, Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid 40000 lb Rears, Meritor RT-40-145 Drive Axles, Roof Sleeper Cab, Aluminum Front Wheels, 275 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding /80R22.5 Front Tires, 11R22.5 Rear Tires, AG210 Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual 5th Wheel, Dual Fuel Tanks **Fuel Tanks** Usage: 488,776 Mi Usage: 298,212 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Asset located in: Lake Worth, TX THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH 1248A 2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor YOUR LOCAL DMV PRIOR TO BIDDING S/N: 1FUJHHDR4MLMN0476 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Asset located in: Midland, TX hp Engine, US EPA Label, Requires Diesel 1245 2019 Peterbilt 579 6x4 T/A Sleeper Truck Exhaust Fluid, 8554 Engine hrs, Engine Brake, Detroit DT12-1750-OH 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Tractor S/N: 1XPBDP9X6KD604443 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 80 in Rear Tires, Airliner Air Ride Suspension, 237 in Condo Sleeper Cab, Bunk Beds, Bunk Heater, Wheelbase, Air Sliding 5th Wheel, Dual Fuel Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Tanks Usage: 321,498 Mi Wheel, Dual Fuel Tanks Asset located in: North East, MD Usage: 565,195 Mi Notes: ODOMETER DISCREPENCY -**ODOMETER SHOWS 565195 TITLE SHOWS** CHOICE OF 4 - Lot #'s: 1249, 1250, 1251, 1252 565852 Asset located in: Humble, TX 1249 2020 Freightliner Cascadia 126 6x4 T/A 1246 2022 Mack AN64T 6x4 T/A Sleeper Truck Sleeper Truck Tractor Tractor S/N: 3AKJHHDR9LSLR4781 S/N: 1M1AN4GYXNM023469 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 Engine, 2019 US EPA Label, Requires Diesel hp Engine, Requires Diesel Exhaust Fluid, Exhaust Fluid, 14419.45 Engine hrs, Engine 19021 Engine hrs, Engine Brake, Mack Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Brake, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Sliding 5th Wheel, Dual Fuel Tanks Usage: 534,026 Mi Usage: 409,839 Mi Asset located in: Lake Worth, TX Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 1247 2022 Mack Anthem T/A Sleeper Truck Tractor S/N: 1M1AN4GY3NM023250 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1250	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR1LSMG6164 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16808 Engine hrs, Engine Brake, Detroit DT12-1650 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 449,805 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	CHOICI 1254	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSME9795 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 423,637 Mi Asset located in: Lake Worth, TX
1251	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSLY5486 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16924 Engine hrs, Engine Brake, Detroit Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,619 Mi Asset located in: Lake Worth, TX	1255 2020 Freightliner Cascadia Sleeper Truck Tractor S/N: 1FUJHHDR2LLLL3459 C/W: Detroit DD15 6 Cylinde hp Engine, 2019 US EPA Lak Exhaust Fluid, 16366 Engine Detroit DT12-1650-0H1 12-5 Transmission, 13220 lb From Rears, Detroit DA-RT-40.0-4 Axle Ratio, 53220 lb GVWR, High Rise Sleeper Cab, Bunk King TriPac Evolution Auxilis Steel, 11R22.5, Airliner Air R 229 in Wheelbase, Air Slidin	S/N: 1FUJHHDR2LLLL3459 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16366 Engine hrs, Engine Brake, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-
1252	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSLT5963 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13413 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 466,120 Mi Notes: COLL B37639 LOT 871 (P53-46) \$45K NON PYMT 2024221 PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Asset located in: Lake Worth, TX	1256	FLEET-VEHICLE-PAG Usage: 549,606 Mi Asset located in: Lake Worth, TX 2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8LSMC8947 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, 72 in Condo Sleeper Cab, Bunk Beds, ParkSmart Electric Sleeper Air Conditioner, Aluminum Wheels, 11R22.5, 228 in Wheelbase, Air Sliding 5th Wheel, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 552,948 Mi

			Page 113 of 581	
Lot #	Details	Lot #	Details	
СНОІС	E OF 4 - Lot #'s: 1259, 1263, 1264, 1265	1265	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7KSKE1407	
1259	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR9KSLG7882 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19617 Engine hrs, Engine Brake, Detroit DT12 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED- FLEET-VEHICLE-PAG Usage: 527,337 Mi		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit Automated Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 609,505 Mi	
		1266	Asset located in: Lake Worth, TX 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2KSKE4277	
1263	Asset located in: Lake Worth, TX 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7KSLG7847 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks,		hp Exl De Tra Rea Ax Hiç He Un Air Sliu	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17458 Engine hrs, Engine Brake, Detroit DT12-V 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 634,187 Mi Asset located in: Lake Worth, TX
	PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 570,587 Mi Asset located in : Lake Worth, TX		2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3KSKH0824	
1264	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXKSKF0425 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18430 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3, 08:1		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Requires Diesel Exhaust Fluid, 10620 Engine hrs, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 233 in	

13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-

VEHICLE-PAG Usage: 588,359 Mi

Asset located in: Lake Worth, TX

Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 477,320 Mi

Asset located in: Humble, TX

CHOICE OF 3 - Lot #'s: 1268, 1269, 1270

1268 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJHHDR3KSKJ2880 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 684,650 Mi

Page 114 of 581 **Details** Lot # **Details** Lot # 1269 2019 Freightliner Cascadia 126 6x4 T/A 1273 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJHHDR5KSKJ2878 S/N: 3AKJHHDR3KSJY3462 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 Engine, 2018 US EPA Label, Requires Diesel hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Beds, 275/80R22.5, Airliner Air Ride Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 223 in Wheelbase, Air Suspension, 232 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 544,147 Mi 1270 2019 Freightliner Cascadia 126 6x4 T/A Asset located in: Lake Worth, TX **Sleeper Truck Tractor** 1274 2019 Freightliner Cascadia 126 6x4 T/A S/N: 3AKJHHDR1KSKJ2876 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Sleeper Truck Tractor S/N: 3AKJHHDR5KSKA2508 Exhaust Fluid, 17776 Engine hrs, Engine Brake, C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Detroit 12-Speed Automated Transmission, Engine, 2018 US EPA Label, Requires Diesel 12350 lb Front Axle, 40000 lb Rears, Meritor Exhaust Fluid, Engine Brake, Detroit 12-Speed MT-40-14X Drive Axles, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, Sleeper Cab, Bunk Beds, Thermo King TriPac 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Suspension, Usage: 718,586 Mi 225 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 677,092 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV CHOICE OF 9 - Lot #'s: 1271, 1272, 1273, 1274, 1275, 1276, 1277, 1278, 1280 PRIOR TO BIDDING Asset located in: Lake Worth, TX 1271 2019 Freightliner Cascadia 126 6x4 T/A 1275 2019 Freightliner Cascadia 126 6x4 T/A **Sleeper Truck Tractor** Sleeper Truck Tractor S/N: 1FUJHHDR3KLKM1453 S/N: 3AKJHHDR5KSKK8191 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel C/W: Detroit DD15 14.8 L Diesel Engine, 2018 Engine, 2018 US EPA Label, Requires Diesel

Exhaust Fluid, 8310 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 579,939 Mi

Asset located in: Lake Worth, TX

1272 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJHHDR7KSKB3770 C/W: Detroit DD15 6 Cylinder 14.8 L Engine, 2017 US EPA Label, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 701,338 Mi

Asset located in: Lake Worth, TX

US EPA Label, Requires Diesel Exhaust Fluid, 22547.51 Engine hrs, Engine Brake, Detroit DT12-1650-OH 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 727,804 Mi

Lot #	Details	Lot #	Details
1276	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDV5KSKJ2974 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Eaton Fuller FAO- 16810C 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 445,195 Mi Asset located in: Humble, TX	1281	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR0KLLJ6173 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23298 Engine hrs, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 685,332 Mi Asset located in: Lake Worth, TX
1277	2019 Freightliner Cascadia 126 6x4 T/A	1282	2018 Freightliner Cascadia 126 6x4 T/A
	Sleeper Truck Tractor S/N: 3AKJHHDR2KSKP1628 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15930 Engine hrs, Engine Brake, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,964 Mi Asset located in: Lake Worth, TX	-	Sleeper Truck Tractor S/N: 3AKJHHDR3JSJW9253 C/W: Detroit DD15 6 Cylinder 14.7 L 455 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-1650-OHI HD 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
1278	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor		Asset located in: Lake Worth, TX
	S/N: 3AKJHHDR4KSKS9784 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 20138.21 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 256 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 593,973 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Asset located in: Lake Worth, TX	1283	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXJSJW4146 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 550,012 Mi Asset located in: Lake Worth, TX
1280	2019 Freightliner Cascadia 126 T/A Sleeper		Asset located III. Lake WORTH, TA
	Truck Tractor S/N: 3AKJHHDRXKSKL3824 C/W: Detroit DD15 Diesel 455 hp Engine, Engine Brake, Detroit DT-12 12-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 72 in High Rise Sleeper Cab, Aluminum Outer Wheels, 275 /80R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 784,000 Mi		

			Page 116 of 581
Lot #	Details	Lot #	Details
1283A	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHFGXJSJW1596 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 25160 Engine hrs, Engine Brake, Eaton Fuller FAOM-15810S-EC Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 830,526 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1286	2022 Volvo VNL880 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6NN600794 C/W: Volvo D13H455 6 Cylinder 13.0 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 21619.0 Engine hrs, Engine Brake, Volvo AT02612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 789,122 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1284A	2023 Volvo VNL860 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2PN605221 C/W: Volvo D13N425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 12528 Engine hrs, Engine Brake, Volvo ATO2612F 12- Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.47:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 274,809 Mi Notes: Asset located in: Lake Worth, TX	CHOIC	2021 Volvo VNL860 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH8MN600892 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, 8277 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1285	2022 Volvo VNL860 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6NN603923 C/W: Volvo 6 Cylinder 12.8 L Diesel 425 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	1288	Usage: 374,829 Mi Notes: PER THE DEALER ACTUAL MILEAGE IS HIGHER THAN SHOWING ON ODO AND ECM - TRUE MILEAGE IS UNKNOWN Asset located in: Lake Worth, TX 2020 Volvo VNL860 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EG7LN223199 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 19723 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air

Brake, Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 511,249 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Usage: 283,601 Mi

Lot #	Details	Lot #	Details
1289	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN249446 C/W: Volvo 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,184 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1293	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3LN245807 C/W: Volvo D13M 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 16978.1 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50500 lb GVWR, Air Ride Cab, 70 in Flat Top Sleeper Cab, 11R22.5, Volvo Air Ride Suspension, 254 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 366,216 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
1290	2020 Volvo VNL860 6x4 T/A Sleeper Truck	1293A	Asset located in: Lake Worth, TX
	Tractor S/N: 4V4NC9TJ8LN253794 C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18160 Engine hrs, Engine Brake, Eaton Fuller FO- 18E313A MHP Automatic Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/70R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 540,590 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2LN265207 C/W: Volvo 6 Cylinder Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 9030 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 379,291 Mi Asset located in: North East, MD
1292	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH0LN249443 C/W: Volvo D13M 6 Cylinder 12.8 L 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 22710.9 Engine hrs, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 611,970 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN	1294	2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN221498 C/W: Volvo 6 Cylinder 12.8 L 425 hp Engine, Requires Diesel Exhaust Fluid, 19160 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 739,489 Mi Asset located in: Lake Worth, TX
	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1295	2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN249009 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 387,288 Mi

Lot #	Details	Lot #	Details
1296	2019 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6KN195791 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12- Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel Usage: 412,464 Mi Asset located in: Lake Worth, TX	S/N: 4V4NC9TJ3KN204274 C/W: Cummins X15 500ST 6 Cylinder Diesel 500 hp Engine, 2018 US EPA La Requires Diesel Exhaust Fluid, Engine Eaton Fuller RTLO-20913A 13-Speed N Transmission, 13200 lb Front Axle, 38 Rears, Meritor MT-40-14X Drive Axles, Axle Ratio, 51200 lb GVWR, Air Ride C High Rise Sleeper Cab, Bunk Beds, Alu Wheels, 295/75R22.5, Air Assist Front Suspension, Air Ride Suspension, 239 Wheelbase, Air Sliding 5th Wheel, Dua Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSIO AFFIDAVIT AND MAY NOT BE ACCEP YOUR STATE. VERIFY WITH YOUR LOU PRIOR TO BIDDING Asset located in: Lake Worth, TX 1300 2019 Volvo VNL 6x4 T/A Sleeper Truc S/N: 4V4NC9EH1KN232987 C/W: Volvo D13M 6 Cylinder 12.8 L 45 Engine, 2018 US EPA Label, Requires I Exhaust Fluid, Engine Brake, Eaton Ful 18210C 10-Speed Automated Transm 13200 lb Front Axle, 38000 lb Rears, 3 Axle Ratio, 51200 lb GVWR, Air Ride C High Rise Sleeper Cab, Bunk Beds, 295 5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dua Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSIO AFFIDAVIT AND MAY NOT BE ACCEP	C/W: Cummins X15 500ST 6 Cylinder 15.0 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-20913A 13-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Assist Front Suspension, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel
1297	2020 Volvo VNL64T740 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH8LN258469 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14884 Engine hrs, Automatic Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, 295 /75R22.5, Air Ride Suspension, 238 in Wheelbase Air Sliding 5th Wheel Dual Evel		Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH1KN232987 C/W: Volvo D13M 6 Cylinder 12.8 L 455 hp
СНОІС	Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,732 Hr Asset located in: Humble, TX HOICE OF 3 - Lot #'s: 1298, 1299, 1300		Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 18210C 10-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel
1298	Tractor S/N: 4V4NC9EH1KN206101 C/W: Volvo D13H455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
		1300A	2019 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH7KN193984 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb

S/N: 4V4NC9EH/KN193984
C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel
455 hp Engine, 2018 US EPA Label, Requires
Diesel Exhaust Fluid, Engine Brake, Volvo
AT02612F 12-Speed Automated Transmission,
Differential Lock, 13200 lb Front Axle, 40000 lb
Rears, 53200 lb GVWR, 70 in High Rise Sleeper
Cab, Bunk Beds, Aluminum Wheels, 295/75R22.
5, Air Ride Suspension, 224 in Wheelbase, Air
Sliding 5th Wheel, Dual Fuel Tanks
Usage: 480,468 Mi

Asset located in: Lake Worth, TX

Usage: Not Available

			Page 119 01 381	
Lot #	Details	Lot #	Details	
1301	2020 Volvo VNR 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DH1LN270436 C/W: Volvo 6 Cylinder Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8942 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 251,927 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1306	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR5LN854650 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12492 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 351,096 Mi Asset located in: Lake Worth, TX	
1303	Asset located in: Humble, TX 2022 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR0NN285693 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 12- Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 73 in Sleeper	_ 1307	2020 International LT625 4x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR7LN854651 C/W: Cummins X15 6 Cylinder Diesel 450 hp Engine, 2019 US EPA Label, Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, Air Ride Cab, 51 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Sliding 5th Wheel Usage: 471,259 Mi Asset located in: Lake Worth, TX	
	Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 450,017 Mi Asset located in: Lake Worth, TX	1308 2019 International Truck Tractor S/N: 3HSDZAPR8K C/W: Cummins X1: Diesel 450 hp Engir Requires Diesel Ext Automated Transm 40000 lb Rears, 53: 72 in High Rise Sle Aluminum Wheels, Suspension, 228 in Wheel, Dual Fuel Ti Usage: Not Availab	1308 2019 International LT625 6x4 T/A S Truck Tractor S/N: 3HSDZAPR8KN122995 C/W: Cummins X15 450SA 6 Cylind Diesel 450 hp Engine, 2018 US EPA	2019 International LT625 6x4 T/A Sleeper Truck Tractor
1304	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3LN800182 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16079 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air		Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	
	Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 484,652 Mi Asset located in: Lake Worth, TX	1309	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR8KN566457 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Ayle, 40000 lb Rears, 52350 lb	

CHOICE OF 3 - Lot #'s: 1305, 1306, 1307

1305 2020 International LT625 6x4 T/A Sleeper Truck Tractor

S/N: 3HSDZTZR3LN684488 C/W: International A26 6 Cylinder 12.4 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16142 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: Not Available

Asset located in: Lake Worth, TX

S/N: 3HSDZAPR8KN566457 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Lot #	Details	Lot #	Details
СНОІС	E OF 3 - Lot #'s: 1310, 1311, 1312	1314	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR5KN284342
1310	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR0KN070889 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15367 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22. 5, Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 467,363 Mi Asset located in: Lake Worth, TX	сноіс	C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19700 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 603,242 Mi Notes: . Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 1317, 1318
1311	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9KN748748 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19547 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 73 in Condo Sleeper Cab, Bunk Beds, Steel, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 467,585 Mi Asset located in: Lake Worth, TX	1317	2018 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7JD457743 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15889 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 685,817 Mi
1312	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3KN350628 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 73 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 561,974 Mi Asset located in: Lake Worth, TX	1318	Asset located in: Lake Worth, TX 2018 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X6JD488661 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 22731.5 Engine hrs, Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, 295 /75R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 623,951 Mi
1313	2019 International LT 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3KN319055 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 73 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 459,002 Mi Asset located in: Humble, TX		Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS; ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Lot #	Details	Lot #	Details
CHOIC	E OF 1 - Lot #'s: 1319	сноіс	E OF 2 - Lot #'s: 1323, 1324
1319	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X6HD423821 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 23493.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 730,143 Mi Asset located in: Lake Worth, TX	1323	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD262361 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 37998 lb Rears, 50000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Flex Air Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 893,094 Mi Asset located in: Lake Worth, TX
011010	F.O.F.O. J. a.t. #2: 1001 1000	1324	2015 Peterbilt 579 6x4 T/A Sleeper Truck
1321	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X0GD330582 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19825 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		Tractor S/N: 1XPBD49X7FD285266 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Coolant Heater, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 80 in High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel Usage: 862,250 Mi Asset located in: Lake Worth, TX
	Usage: 908,570 Mi Asset located in: Lake Worth, TX	сноіс	E OF 2 - Lot #'s: 1326, 1328
1322	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9XXGD298189 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 20896 Engine hrs, Engine Brake, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 635,966 Mi	1326	2013 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49XXDD206468 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller 8-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Low Air Leaf Air Ride Suspension, 246 in Wheelbase, Dual Fuel Tanks

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Midland, TX

Lot# **Details** Lot # **Details** 1327 2013 Peterbilt 386 6x4 T/A Sleeper Truck **Tractor** CHOICE OF 2 - Lot #'s: 1330, 1331 S/N: 1XPHD49X8DD173180 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 1330 2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor Automated Transmission, 12000 lb Front Axle, S/N: 1XKYD49X2JJ216429 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB 58 in Mid Roof Sleeper Cab, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Low Air Compliant, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, Differential Leaf Air Ride Suspension, 231 in Wheelbase, Lock, 12500 lb Front Axle, 40000 lb Rears, Air Sliding 5th Wheel, Dual Fuel Tanks Paccar Drive Axles, 2.93:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Usage: 820,824 Mi Notes: THIS UNIT IS BEING SOLD WITH A Cab, Bunk Beds, Aluminum Wheels, 295/75R22. **BONDED TITLE** 5, Paccar 4-Bag Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Asset located in: Humble, TX 1328 2012 Peterbilt 386 6x4 T/A Sleeper Truck Usage: Not Available Tractor Asset located in: Midland, TX S/N: 1XPHD49X0CD142424 1331 2018 Kenworth T680 6x4 T/A Sleeper Truck C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2011 US EPA Label, Requires Diesel Tractor Exhaust Fluid, 28592 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb S/N: 1XKYD49X3JJ185028 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Front Wheels, 295/75R22.5 Front Automated Transmission, 13200 lb Front Axle, Tires, 295/75R22.5 Rear Tires, Air Leaf Air Ride 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb Suspension, 225 in Wheelbase, Air Sliding 5th GVWR, Air Ride Cab, 76 in High Rise Sleeper Wheel, Dual Fuel Tanks Cab, Bunk Beds, Aluminum Front Wheels, 295 Usage: 778,429 Mi 5R22.5, Paccar Air Ride Suspension, 222 in Wheelbase, Dual Fuel Tanks Notes: THIS UNIT IS BEING SOLD WITH A Usage: 630,153 Mi **BONDED TITLE** Notes: SELLING WITH A REPOSESSION Asset located in: Lake Worth, TX AFFIDAVIT AND MAY NOT BE ACCEPTED IN 1329 YOUR STATE. VERIFY WITH YOUR LOCAL DMV 2011 Peterbilt 387 6x4 T/A Sleeper Truck PRIOR TO BIDDING **Tractor** S/N: 1XP7D49X7BD121337 Asset located in: Lake Worth, TX C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, CHOICE OF 4 - Lot #'s: 1333, 1334, 1335, 1336

C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Asset located in: Lake Worth, TX

1333 2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor

S/N: 1XKYDP9XXHJ144648 C/W: Paccar MX-13 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 24355 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 901,856 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Dataile	Lot #	Detaile
Lot #	Details 2017 Kenworth T680 6x4 T/A Sleeper Truck	Lot #	Details 2016 Kenworth T680 6x4 T/A Sleeper Truck
	Tractor S/N: 1XKYDP9X2HJ146961 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 25916 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT40- 14X3 Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 643,846 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKYD49X4GJ118091 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 2504 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 38 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 827,511 Mi Asset located in: Lake Worth, TX
1335	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor	сноіс	E OF 5 - Lot #'s: 1339, 1340, 1341, 1342, 1343
	S/N: 1XKYDP9X3HJ145768 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 26851 Engine hrs, Engine Brake, Eaton Fuller Eaton Advantage 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,016 Mi Asset located in: Livingston, LA	1339	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X7FJ430257 C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: 866,880 Mi
1336	2017 Kenworth T680 6x4 T/A Sleeper Truck		Asset located in: Lake Worth, TX
	Tractor S/N: 1XKYD49X0HJ153938 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19893 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 76 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 238 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 631,336 Mi	1340	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X9FJ449653 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 23432 Engine hrs, Engine Brake, Automatic Transmission, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, 295/75R22.5, 8-Bag Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 810,190 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	1341	2015 Kenworth T680 6x4 T/A Sleeper Truck
1337	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP8X6GJ121464 C/W: Paccar 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2310 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Differential Lock, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 60,967 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKYD48XXFJ420758 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810C 10-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 3.36:1 Axle Ratio, 46350 lb GVWR, Air Ride Cab, 75 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,063,376 Mi Asset located in: Humble, TX

Details Lot # **Details** Lot # 1342 2015 Kenworth T680 6x4 T/A Sleeper Truck **Tractor** CHOICE OF 3 - Lot #'s: 1346, 1347, 1348 S/N: 1XKYD48X2FJ420768 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 30258 Engine hrs, Engine 1346 2016 Kenworth T660 6x4 T/A Sleeper Truck Tractor Brake, Eaton Fuller 10-Speed Manual S/N: 1XKAD49X2GJ481393 Transmission, 12350 lb Front Axle, 34000 lb C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Rears, 46350 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride 485 hp Engine, 31744 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Suspension, 230 in Wheelbase, Air Sliding 5th Axle, 38000 lb Rears, Spicer DSP40 Drive Axles, Wheel, Dual Fuel Tanks 3.55:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, Usage: 1,080,201 Mi 52 in Mid Roof Sleeper Cab, Aluminum Wheels, Notes: DEFICIENCIES NOTED - PLEASE SEE 295/75R22.5, Air Ride Suspension, 244 in THE INSPECTION REPORT Wheelbase, Dual Fuel Tanks Usage: 908,066 Mi Asset located in: Humble, TX Notes: THIS UNIT RUNS BUT MAY HAVE 1343 2015 Kenworth T680 6x4 T/A Sleeper Truck **DEFICIENCIES IN ITS POLLUTION CONTROL** SYSTEMS WITH LIABILITIES OUTLINED IN Tractor TEXAS ADMINISTRATIVE CODE SECTIONS S/N: 1XKYDP9X1FJ450926 114.20 AND 114.50. THIS MAY APPLY IF YOU C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN Diesel Exhaust Fluid, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Asset located in: Lake Worth, TX Suspension, 231 in Wheelbase, Dual Fuel Tanks 1347 2016 Kenworth T660 6x4 T/A Sleeper Truck Usage: 809,582 Mi Tractor Asset located in: Humble, TX S/N: 1XKAD49X4GJ481394

CHOICE OF 1 - Lot #'s: 1345

1345 2012 Kenworth T700 6x4 T/A Sleeper Truck

S/N: 1XKFDP9X9CJ325479 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210B 10-Speed Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, 11R22.5, Paccar Air Ride Suspension, 231 in Wheelbase, Dual Fuel Tanks Usage: Not Available

Asset located in: Midland, TX

S/N: 1XKAD49X4GJ481394 C/W: Cummins ISX 6 Cylinder 14.9 L Diesel 500 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4526 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, Flat Top Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 244 in Wheelbase,

Dual Fuel Tanks Usage: 1,002,171 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

1348 2014 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1YKADAQYYE 1307601

Details

Lot #

S/N: 1XKAD49XXEJ397691 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 35718 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Dual Fuel Tanks Usage: 970,194 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

1349 2014 Kenworth T600 6x4 T/A Sleeper Truck Tractor

S/N: 1XKAD48X8EJ414196 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17145 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Air Ride Cab, 50 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, 11R24.5, Air Assist Front Suspension, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel

Usage: 555,466 Mi

Asset located in: Lake Worth, TX

1350 2013 Kenworth T660 6x4 T/A Sleeper Truck Tractor

S/N: 1XKADP9X3DJ353712 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 340 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTOC16909A Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Dana DSP41 Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 128 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks

Usage: 554,558 Mi

Notes: UNIT HAS NO THROTTLE Asset located in: Lake Worth, TX

Lot # Details

1351A 2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor

S/N: 1XKAD49X6CJ297018 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 24434 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 809,118 Mi

Asset located in: Lake Worth, TX

1351B 2012 Kenworth T660 T/A Sleeper Truck Tractor

S/N: 1XKAD49X6CJ297052 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 34000 lb Rears, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in Mid Roof Sleeper Cab, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Paccar Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Asset located in: Lake Worth, TX

1351C 2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor

S/N: 1XKADP9X9CJ336573 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 14246 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 121 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 481,647 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Lake Worth, TX

1351D 2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor

S/N: 1XKAD49X9CJ297000 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 22628 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 724,564 Mi

Details	Lot #	Details
2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X8CJ297036 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 23687 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 34000 lb Rears, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 800,369 Mi	1356	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM040890 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R22.5, Air Ride Suspension, 214 in Wheelbase Usage: 773,925 Mi Asset located in: Lake Worth, TX
Asset located in: Lake Worth, TX	1357	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor
CHOICE OF 2 - Lot #'s: 1353, 1354 1353 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3FM051337 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22586 Engine Brake, 13 Speed Manual Transmission, 13250 lb		S/N: 1M1AW02Y1EM036897 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 25651 Engine hrs, Engine Brake, Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 836,651 Mi Asset located in: Lake Worth, TX
Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 607,391 Mi Asset located in: Lake Worth, TX	1358	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM042227 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel
2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM049326 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: Not Available		Exhaust Fluid, 22893 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R22.5 Rear Tires, 4-Bag Air Ride Suspension, 219 in Wheelbase, PTO Usage: 822,170 Mi Asset located in: Lake Worth, TX
	1359	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor
Asset located in: Lake Worth, TX CHOICE OF 7 - Lot #'s: 1355, 1356, 1357, 1358, 1359, 1360, 1361 1355 2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor		S/N: 1M1AW02Y1EM042263 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tank Usage: 778,799 Mi Asset located in: Lake Worth, TX
C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 897,867 Mi Asset located in: Lake Worth, TX	1360	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXEM040902 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 222 in Wheelbase Usage: 805,702 Mi
	Tractor S/N: 1XKAD49X8CJ297036 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 23687 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 34000 lb Rears, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 800,369 Mi Asset located in: Lake Worth, TX EOF 2 - Lot #s: 1353, 1354 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3FM051337 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22586 Engine hrs, Engine Brake, 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 607,391 Mi Asset located in: Lake Worth, TX 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM049326 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: Not Available Asset located in: Lake Worth, TX	Tractor S/N: 1XKAD49X8CJ297036 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 23687 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 34000 lb Rears, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 800,369 Mi Asset located in: Lake Worth, TX 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3FM051337 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22586 Engine hrs, Engine Brake, 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 607,391 Mi Asset located in: Lake Worth, TX 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM049326 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: Not Available Asset located in: Lake Worth, TX 2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y2EM036889 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 897,867 Mi

Lot #	Details	Lot #	Details
1361	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM036877 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9682 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, 285/75R24.5, Air Ride Suspension, 217 in Wheelbase Usage: 794,371 Mi Asset located in: Lake Worth, TX	1365	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM042243 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 791,657 Mi Asset located in: Lake Worth, TX
CHOIC 1362	Tractor S/N: 1M1AW02Y9EM042236 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum	1366	Tractor S/N: 1M1AW02Y7EM040887 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 690,857 Mi Asset located in: Lake Worth, TX
1363	Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 675,329 Mi Asset located in: Lake Worth, TX 33 2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4EM042225 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper	1367	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM042244 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Wheels, 285 /75R24.5, Air Ride Suspension, 222 in Wheelbase Usage: 741,289 Mi Asset located in: Lake Worth, TX
1364	Cab, Aluminum Wheels, 285/75R24.5, mRide Air Ride Suspension, 218 in Wheelbase Usage: 730,061 Mi Asset located in: Lake Worth, TX 2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM033793 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 31248 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 218 in Wheelbase Usage: 755,801 Mi Asset located in: Lake Worth, TX	1368	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW07Y6EM042008 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 6600 kg Front Axle, 20800 kg Rears, 27400 kg GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 707,937 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
CHOICE	E OF 6 - Lot #'s: 1369, 1370, 1371, 1372, 1373, 1374	1373	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3DM029500 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395
1369	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM036878 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, 26792 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 217 in Wheelbase Usage: 871,001 Mi	1374	hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 3225 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension, 220 in Wheelbase Usage: 674,399 Mi Asset located in: Lake Worth, TX 2013 Mack CXU613 6x4 T/A Sleeper Truck
	Asset located in: Humble, TX		Tractor
1370	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7DM024736 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 214 in Wheelbase Usage: 701,446 Mi	СНОІСІ	S/N: 1M1AW21Y6DM034381 C/W: Mack MP8 6 Cylinder 12.7 L Diesel Engine, 30700 Engine hrs, Mack Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase Usage: 813,858 Mi Asset located in: Lake Worth, TX E OF 6 - Lot #'s: 1375, 1376, 1377, 1378, 1379, 138
	Asset located in: Lake Worth, TX		
1371	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8DM029525 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension Usage: 643,699 Mi Asset located in: Lake Worth, TX	1375	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXDM029512 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 24261 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase Usage: 648,076 Mi Asset located in: Lake Worth, TX
1372	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6DM029524 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 13523 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 756,971 Mi Asset located in: Lake Worth, TX	1376	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y2DM024739 C/W: Mack MP7 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 26124 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 218 in Wheelbase Usage: 690,603 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1377	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033782 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20338 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase Usage: 658,728 Mi Asset located in: Lake Worth, TX	Tractor S/N: 1M1AN07Y2FM019667 C/W: Mack MP8 6 Cylinder Diesel 44 Engine, 2014 US EPA Label, Requires Exhaust Fluid, Engine Brake, Mack 10 Manual Transmission, 12000 lb Fron 40000 lb Rears, 52000.0 lb GVWR, Ai Cab, 48 in Flat Top Sleeper Cab, Alun Wheels, 11R24.5, Air Ride Suspensio Wheelbase, PTO, Wet Kit, Air Sliding Blower, Dual Fuel Tanks Usage: 510,043 Mi Notes: Asset located in: Humble, TX 1383 2014 Mack CHU613 6x4 T/A Sleeper Tractor S/N: 1M1AN07Y1EM015852 C/W: Mack MP8 6 Cylinder 12.8 L Die hp Engine, 2013 US EPA Label, Requi Exhaust Fluid, 2950 Engine hrs, Engir Eaton Fuller Manual Transmission, 1 Front Axle, 40000 lb Rears, 52000 lb Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, PTO, Wet Kit, Air Sliding Wheel, Dual Fuel Tanks Usage: 462,432 Mi	2015 Mack CHU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AN07Y2FM019667 C/W: Mack MP8 6 Cylinder Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride
1378	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033751 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-		Wheels, 11R24.5, Air Ride Suspension, 237 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 510,043 Mi
	Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 783,814 Mi Asset located in: Lake Worth, TX		S/N: 1M1AN07Y1EM015852 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 2950 Engine hrs, Engine Brake,
1379	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033748 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase Usage: 624,802 Mi		Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 462,432 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	CHOICI	E OF 2 - Lot #'s: 1385, 1386
1380	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8DM031484 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 216 in Wheelbase Usage: Not Available Asset located in: Humble, TX	Sleeper Truck Tractor S/N: 3AKJGLDR6KSKS1465 C/W: Detroit DD15 6 Cylinder 14.8 L Die hp Engine, 2018 US EPA Label, Require Exhaust Fluid, 19541.1 Engine hrs, Detr DT12-1550 OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 400 Rears, Detroit DA-RT-40.0-4 Drive Axles Axle Ratio, 53220 lb GVWR, Air Ride Ca High Rise Sleeper Cab, Bunk Beds, 11R Airliner Air Ride Suspension, 228 in Wh Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 723,931 Mi Notes: ; SELLER MAINTENANCE RECO	S/N: 3AKJGLDR6KSKS1465 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19541.1 Engine hrs, Detroit DT12-1550 OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase,
1381	2011 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW07Y3BM015005 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, Mack MDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 295 /75R22.5, Air Ride Suspension, 226 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,133,741 Mi		Usage: 723,931 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED

Details Lot # **Details** Lot # 1386 2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor CHOICE OF 2 - Lot #'s: 1392, 9711A S/N: 3AKJGLDV6KSKH9486 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 1392 2018 US EPA Label, Requires Diesel Exhaust 2018 Freightliner Cascadia 125 6x4 T/A Fluid, 23543 Engine hrs, Detroit DT12-1550-Sleeper Truck Tractor OH1 HD 12-Speed Automated Transmission, S/N: 3AKJGLDR0JSHF3632 12000 lb Front Axle, 40000 lb Rears, Detroit DA-C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Exhaust Fluid, Retarder, Detroit DT12-DA-1750 HD 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-Ride Suspension, 212 in Wheelbase, Air Sliding 14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper 5th Wheel, Dual Fuel Tanks Usage: 720,855 Mi Cab, Bunk Beds, Exo Air Sleeper Air Notes: DEFICIENCIES NOTED - PLEASE SEE Conditioner, Aluminum Outer Wheels, 295 THE INSPECTION REPORT /75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Asset located in: Humble, TX Tanks Usage: 614,080 Mi 1387 2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Asset located in: Humble, TX S/N: 3AKJGLDR3KDKM9521 1393 2018 Freightliner Cascadia 125 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Sleeper Truck Tractor hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-15210B 10-S/N: 1FUJGLDV4JLJV0967 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Exhaust Fluid, 8996 Engine hrs, Engine Brake, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Eaton Fuller FAO-16810C-EA Automated Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Suspension, 226 in Wheelbase, Air Sliding 5th Mid Roof Sleeper Cab, Thermo King TriPac Usage: 512,155 Mi **Evolution Auxiliary Power Unit, Aluminum** Wheels, 11R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Asset located in: Lake Worth, TX 1388 2019 Freightliner Cascadia 125 6x4 T/A **Fuel Tanks** Usage: 373,961 Mi **Sleeper Truck Tractor** Asset located in: Lake Worth, TX S/N: 3AKJGLDR9KDKM9524 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, CHOICE OF 4 - Lot #'s: 1394, 1395, 1396, 1397 Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in Mid 1394 2018 Freightliner Cascadia 125 6x4 T/A Roof Sleeper Cab, Aluminum Outer Wheels, Sleeper Truck Tractor 11R22.5, Airliner Air Ride Suspension, 252 in S/N: 3AKJGLDR8JSHF3927 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, 2017 US EPA Wheelbase, Air Sliding 5th Wheel Usage: 525,435 Mi Asset located in: Humble, TX

Label, Requires Diesel Exhaust Fluid, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 604,042 Mi

Details Lot # **Details** Lot # 1395 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor CHOICE OF 5 - Lot #'s: 1398, 1399, 1401, 1402, 1403 S/N: 1FUJGLDV2JLJP4880 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 1398 hp Engine, Requires Diesel Exhaust Fluid, 2018 Freightliner Cascadia 125 6x4 T/A 21109 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Sleeper Truck Tractor S/N: 1FUJGLDR4JLJV0566 Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Ride Cab, 70 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 295/75R22. Exhaust Fluid, 12180 Engine hrs, Engine Brake, Detroit DT12-1650-OA 12-Speed Automated 5, Airliner Air Ride Suspension, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Transmission, 13300 lb Front Axle, 40000 lb Tanks Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in Usage: 890,800 Mi Condo Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Steel, 295/75R22.5, Airliner Air Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Asset located in: Humble, TX 1396 2018 Freightliner Cascadia 125 6x4 T/A Usage: 420,575 Mi Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 1FUJGLFG9JLJN0560 C/W: Cummins X15 6 Cylinder 15 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel 2018 Freightliner Cascadia 125 6x4 T/A 1399 Sleeper Truck Tractor Exhaust Fluid, 21765 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual S/N: 1FUJGLDR2JLJV0565 Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in Exhaust Fluid, Engine Brake, Detroit 12-Speed High Rise Sleeper Cab, Bunk Beds, Thermo Automated Transmission, 13300 lb Front Axle, King TriPac Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier Comfort Pro Auxiliary Wheel, Dual Fuel Tanks Power Unit, Aluminum Front Wheels, 295 Usage: 665,249 Mi /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Asset located in: Lake Worth, TX 1397 2018 Freightliner Cascadia 125 6x4 T/A Usage: 442.347 Mi **Sleeper Truck Tractor** S/N: 1FUJGLDV0JLJK2888 Asset located in: Lake Worth, TX C/W: Detroit DD13 12.8 L Diesel Engine, 1401 2018 Freightliner Cascadia 125 6x4 T/A Requires Diesel Exhaust Fluid, Engine Brake, Sleeper Truck Tractor Eaton Fuller 10-Speed Automated

S/N: 1FUJGLDV0JLJK2888
C/W: Detroit DD13 12.8 L Diesel Engine,
Requires Diesel Exhaust Fluid, Engine Brake,
Eaton Fuller 10-Speed Automated
Transmission, Differential Lock, 12000 lb Front
Axle, 40000 lb Rears, Meritor MT-40-14X Drive
Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air
Ride Cab, 72 in Mid Roof Sleeper Cab,
Aluminum Wheels, 11R22.5, Air Ride
Suspension, 240 in Wheelbase, Air Sliding 5th
Wheel, Dual Fuel Tanks

Usage: 408,806 Mi

Asset located in: Lake Worth, TX

S/N: 1FUJGLDR5JLJV0558
C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455
hp Engine, 2017 US EPA Label, Requires Diesel
Exhaust Fluid, 12958 Engine hrs, Engine Brake,
Detroit 12-Speed Automated Transmission,
13300 lb Front Axle, 40000 lb Rears, Detroit DART-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300
lb GVWR, Air Ride Cab, 72 in High Rise Sleeper
Cab, Bunk Beds, Carrier ComfortPro Auxiliary
Power Unit, Aluminum Front Wheels, 295
/75R22.5, Airliner Suspension, 234 in
Wheelbase, Air Sliding 5th Wheel, Dual Fuel
Tanks, PROFESSIONALLY-MAINTAINED-FLEET-

VEHICLE-PAG Usage: 479,989 Mi

Details Lot # **Details** Lot # 1402 2018 Freightliner Cascadia 125 6x4 T/A 1406 2017 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** Sleeper Truck Tractor S/N: 1FUJGLDR3JLJV0560 S/N: 3AKJGLDR1HSHY7691 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 24671 Engine hrs, Engine Brake, C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OA-1750 12-Speed Automated Transmission, 13300 lb Front Axle, Eaton Fuller 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.42:1 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Suspension, 224 in Wheelbase, Dual Fuel Tanks Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 879,236 Mi PROFESSIONALLY-MAINTAINED-FLEÉT-Notes: THIS UNIT RUNS BUT MAY HAVE VEHICLE-PAG DEFICIENCIES IN ITS POLLUTION CONTROL Usage: 506,969 Mi SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU Asset located in: Lake Worth, TX 1403 2018 Freightliner Cascadia 125 6x4 T/A OPERATE THE UNIT PRIOR TO THE ADEQUATE **Sleeper Truck Tractor** RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY S/N: 1FUJGLDR7JLJV0576 EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Requires Diesel PRIOR TO REMOVAL OF UNIT FROM YARD Exhaust Fluid, 20205 Engine hrs, Engine Brake, Detroit DT12-OA-1750 12-Speed Automated Asset located in: Lake Worth, TX Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Auxiliary CHOICE OF 5 - Lot #'s: 1407, 1408, 1409, 1410, 1411 Power Unit, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in

CHOICE OF 2 - Lot #'s: 1405, 1406

Usage: 528.613 Mi

VEHICLE-PAG

1405 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

Asset located in: Lake Worth, TX

S/N: 3AKJGLDR0HSHY7696 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, Requires Diesel Exhaust Fluid, 24725.4 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor RT-40-145A Drive Axles, 3.42:1 Axle Ratio, 53300 lb GVWR, 58 in Flat Top Sleeper Cab, 295 /75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks

Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-

Usage: 695,017 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

1407 2017 Freightliner Cascadia 125 6x4 T/A

Sleeper Truck Tractor

S/N: 1FUJGLDR6HLHW3673 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1650 12-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 713,350 Mi

Asset located in: Lake Worth, TX

1408 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR5HLHF2174 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1750 HD 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 813.536 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Details Lot# **Details** Lot # 1409 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor CHOICE OF 7 - Lot #'s: 1412, 1413, 1414, 1415, 1416, S/N: 3AKJGLDR6HSHF0874 1417, 1421 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1750 12-Speed 1412 2016 Freightliner Cascadia 125 6x4 T/A Automated Transmission, 12500 lb Front Axle, Sleeper Truck Tractor 40000 lb Rears, Meritor MT-40-14X Drive Axles, S/N: 3AKJGLD57GSHV4416 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Engine, Requires Diesel Exhaust Fluid, 27284 Engine hrs, Engine Brake, Detroit DT12-DA-1550 HD 12-Speed Automated Transmission, Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 12000 lb Front Axle, 40000 lb Rears, Detroit DA-Usage: 720,617 Mi RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 Asset located in: Lake Worth, TX 1410 2017 Freightliner Cascadia 125 6x4 T/A /75R22.5, Airliner Suspension, 224 in Sleeper Truck Tractor Wheelbase, Air Sliding 5th Wheel, Dual Fuel S/N: 3AKJGLBG4HSJE6318 Tanks C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, CARB Usage: 873,575 Mi Notes: SELLING WITH A REPOSESSION Compliant, Requires Diesel Exhaust Fluid, 2448 AFFIDAVIT AND MAY NOT BE ACCEPTED IN Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 48 in Mid YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 208 in Wheelbase, Air Sliding 1413 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor 5th Wheel, Dual Fuel Tanks S/N: 3AKJGLBG0GSGY9123 Usage: 785,075 Mi C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 3793 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Asset located in: Lake Worth, TX 1411 2017 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** Manual Transmission, 12000 lb Front Axle, S/N: 1FUJGLDR0HLHX4331 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-/75R22.5, Airliner Air Ride Suspension, 228 in Speed Manual Transmission, 12350 lb Front Wheelbase, Air Sliding 5th Wheel, Dual Fuel Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Tanks Cab, 60 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Usage: 666,327 Mi Notes: . Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 610,011 Mi

Asset located in: Humble, TX

1414 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLBG2GSHB0517 C/W: Cummins ISX15 450ST2 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 29538 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 772,091 Mi

Details Lot # **Details** Lot # 1415 2016 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** CHOICE OF 5 - Lot #'s: 1422, 1423, 1424, 1425, 1426 S/N: 3AKJGLD52GSGU0419 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 1422 hp Engine, Engine Brake, Detroit DT12-DA 12-2016 Freightliner Cascadia 125 6x4 T/A Speed Automated Transmission, 12000 lb Sleeper Truck Tractor Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-S/N: 1FUJGLD59GLGU1997 4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 GVWR, Air Ride Cab, 72 in High Rise Sleeper hp Engine, Requires Diesel Exhaust Fluid, Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 230 in Engine Brake, 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.53:1 Wheelbase, Air Sliding 5th Wheel, Dual Fuel Axle Ratio, 52000 lb GVWR, Air Ride Cab, High Tanks Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Airliner Air Usage: 1,114,394 Mi Asset located in: Lake Worth, TX Ride Suspension, 230 in Wheelbase, Dual Fuel 1416 2016 Freightliner Cascadia 125 6x4 T/A Usage: 880,832 Mi Sleeper Truck Tractor Asset located in: Humble, TX S/N: 3AKJGLBG3GSGX0680 2016 Freightliner Cascadia 125 6x4 T/A 1423 C/W: Cummins ISX 6 Cylinder Diesel 450 hp Engine, Engine Brake, Automated Sleeper Truck Tractor Transmission, 12350 lb Front Axle, 40000 lb S/N: 3AKJGLBGXGSHT7100 Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Airliner Suspension, 231 in Wheelbase, Air Diesel Exhaust Fluid, 24362 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Sliding 5th Wheel, Dual Fuel Tanks Usage: 790,465 Mi Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, Air Asset located in: Lake Worth, TX 1417 2016 Freightliner Cascadia 125 6x4 T/A Ride Cab, 70 in High Rise Sleeper Cab, Bunk Sleeper Truck Tractor Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride S/N: 3AKJGLD50GSHA9524 Suspension, 228 in Wheelbase, Air Sliding 5th C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Wheel, Dual Fuel Tanks Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Usage: 606,456 Mi Asset located in: Lake Worth, TX Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 72 1424 2016 Freightliner Cascadia 125 6x4 T/A in High Rise Sleeper Cab, Bunk Beds, Thermo Sleeper Truck Tractor King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th S/N: 1FUJGLD56GLGU2007 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Wheel, Dual Fuel Tanks Exhaust Fluid, 27811 Engine hrs, Engine Brake, Usage: 778,378 Mi Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air YOUR STATE. VERIFY WITH YOUR LOCAL DMV Ride Cab, 60 in High Rise Sleeper Cab, Bunk PRIOR TO BIDDING Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Asset located in: Lake Worth, TX **Fuel Tanks** 1421 2016 Freightliner Cascadia 125 6x2 T/A Usage: 812,953 Mi **Sleeper Truck Tractor** Asset located in: Livingston, LA S/N: 3AKGGLD55GSGC5502 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 25874 Engine hrs, Engine Brake, Detroit DT12 Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, 295 /75R22.5, Airliner Air Ride Suspension, 230 in

Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Asset located in: Lake Worth, TX

Tanks

Usage: 618,196 Mi

Details Lot # **Details** Lot # 1425 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor CHOICE OF 7 - Lot #'s: 1428, 1429, 1430, 1432, 1433, S/N: 3AKJGLDR6GSHD7573 1434, 1435 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1750 12-Speed 1428 2015 Freightliner Cascadia 125 6x4 T/A Automated Transmission, 12350 lb Front Axle, Sleeper Truck Tractor 40000 lb Rears, Detroit DA-RT-40.0-4 Drive S/N: 1FUJGLD57FLGE5847 Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air C/W: Detroit 6 Cylinder 14.8 L Diesel Engine, Ride Cab, 60 in Condo Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner 2014 US EPA Label, Engine Brake, Detroit DT12-DA 12-Speed Automated Transmission, 12000 Air Ride Suspension, 222 in Wheelbase, Air lb Front Axle, 40000 lb Rears, Meritor MT-40-Sliding 5th Wheel, Dual Fuel Tanks 14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb Usage: 669,139 Mi GVWR, Air Ride Cab, 72 in High Rise Sleeper Notes: THIS UNIT IS BEING SOLD WITH A Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, **BONDED TITLE** Airliner Air Ride Suspension, 228 in Wheelbase, Asset located in: Lake Worth, TX Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 834,687 Mi 1426 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 1FUJGLD50GLHF0201 1429 2015 Freightliner Cascadia 125 6x4 T/A C/W: Detroit Remanufactured 1/19/23 6 Cylinder Ultra Low Sulfur Diesel Engine, 2023 Sleeper Truck Tractor US EPA Label, Requires Diesel Exhaust Fluid, S/N: 3AKJGLBG3FSGU4319 Engine Brake, Detroit DT12-OA-1750 12-Speed C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Automated Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-Low Sulfur Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 29056 RT-40.0-4HT Drive Axles, 3.23:1 Axle Ratio, Engine hrs, Engine Brake, Eaton Fuller FO-16E310C Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 232 in Wheelbase, Air Sliding Drive Axles, 3.36:1 Axle Ratio, Air Ride Cab, 70 5th Wheel, Dual Fuel Tanks in High Rise Sleeper Cab, Bunk Beds, 295 Usage: Not Available /75R22.5, Airliner Air Ride Suspension, 228 in Notes: . Wheelbase, Air Sliding 5th Wheel, Dual Fuel Asset located in: Lake Worth, TX Usage: 832,290 Mi 1427 2015 Freightliner Cascadia 125 6x4 T/A Asset located in: Lake Worth, TX Sleeper Truck Tractor 1430 2015 Freightliner Cascadia 125 6x4 T/A S/N: 1FUJGLDV4FLGM6667 Sleeper Truck Tractor C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, S/N: 3AKJGLBG5FSGC7243 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2014 US EPA Label, Requires Diesel 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18642 Engine hrs, Eaton Fuller 10-Speed Automated Transmission, 12000 lb Front Axle, Exhaust Fluid, 23900 Engine hrs, Engine Brake, 40000 lb Rears, 3.23:1 Axle Ratio, 52000 lb Eaton Fuller FRO-16210C 10-Speed Manual GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 212 in Wheelbase. Air Sliding 5th Wheel, Dual Fuel Tanks Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Usage: 632,880 Mi Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Asset located in: Humble, TX Airliner Air Ride Suspension, 216 in Wheelbase Usage: 742,719 Mi 1427A 2015 Freightliner Cascadia 125 6x4 T/A **Notes**: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN Sleeper Truck Tractor S/N: 3AKJGLD66FSGL9720 YOUR STATE. VERIFY WITH YOUR LOCAL DMV C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2014 US EPA Label, Requires Diesel PRIOR TO BIDDING Exhaust Fluid, Automated Transmission, 12000 Asset located in: Lake Worth, TX lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 843,243 Mi Asset located in: Humble, TX

Details Lot # **Details** Lot # 1432 1436 2015 Freightliner Cascadia 125 6x4 T/A 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJGLD55FSGB5654 S/N: 3AKJGLBG1FSGN2970 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 33891 Engine hrs, Engine Brake, Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FO-16E313A-MHP ULT 13-Speed Automated Detroit DT12-OA-1650 HD 12-Speed Transmission, 13220 lb Front Axle, 40000 lb Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.58:1 Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Axle Ratio, 53220 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Beds, 11R22.5, Airliner Air Ride Suspension, Wheels, 11R22.5, Airliner Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual 228 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks Fuel Tanks** Usage: 986,645 Mi Usage: 921,108 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Asset located in: Lake Worth, TX THE INSPECTION REPORT 1437 2015 Freightliner Cascadia 125 6x4 T/A Asset located in: Humble, TX Sleeper Truck Tractor 1433 2015 Freightliner Cascadia 125 6x4 T/A S/N: 3AKJGLD52FSGK9029 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Sleeper Truck Tractor S/N: 1FUJGLD54FLGE3862 Exhaust Fluid, 24896 Engine hrs, Engine Brake, C/W: Detroit 6 Cylinder 14.8 L Diesel 505 hp Detroit 12-Speed Automated Transmission, Engine, 2014 US EPA Label, Requires Diesel 12000 lb Front Axle, 40000 lb Rears, Detroit DA-Exhaust Fluid, Engine Brake, Automated RT-40.0-4 Drive Axles, 52000 lb GVWR, Air Ride Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, High Rise Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Suspension, 230 in Wheelbase, Air Sliding 5th Wheelbase, Air Sliding 5th Wheel, Headache Wheel, Dual Fuel Tanks Rack, Dual Fuel Tanks Usage: 697,727 Mi Usage: 724,909 Mi Asset located in: Lake Worth, TX Asset located in: Midland, TX 1438 2015 Freightliner Cascadia 125 6x4 T/A 1434 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJGLD54FSFK4749 S/N: 3AKJGLD53FSGH9952 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Engine, Requires Diesel Exhaust Fluid, 22930 Engine hrs, Engine Brake, Detroit 12-Speed Exhaust Fluid, 45413 Engine hrs, Engine Brake, Automated Transmission, Detroit DA-RT-40.0-4 Eaton Fuller 10-Speed Manual Transmission, Drive Axles, 2.53:1 Axle Ratio, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 12350 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in /75R22.5, Airliner Air Ride Suspension, 227 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 588,173 Mi Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 882,767 Mi Asset located in: Midland, TX Asset located in: Humble, TX CHOICE OF 2 - Lot #'s: 1439, 1442 1435 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor 1439 2015 Freightliner Cascadia 125 6x4 T/A S/N: 3AKJGHDV8FSGL7536 Sleeper Truck Tractor C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel S/N: 3AKJGLD53FSGM5613 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Exhaust Fluid, 17707 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Cab, Bunk Beds, Aluminum Wheels, 275/80R22. Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 724,691 Mi Usage: 664,589 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT Asset located in: Humble, TX Asset located in: Humble, TX

Details Lot# **Details** Lot # 1442 2014 Freightliner Cascadia 125 6x4 T/A 1445 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor **Sleeper Truck Tractor** S/N: 3AKJGLD50ESFY3229 S/N: 1FUJGLD5XELFM3669 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLOhp Engine, Requires Diesel Exhaust Fluid, 24797 Engine hrs, Engine Brake, Detroit DT12-16913A 13-Speed Manual Transmission, OA-1550 12-Speed Automated Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Rears, Meritor MT-40-14X Drive Axles, 3.20:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Axle Ratio, 52500 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Conditioner, 295/75R22.5, Airliner Air Ride Heater, Aluminum Outer Wheels, 11R22.5 Front Suspension, 228 in Wheelbase, Air Sliding 5th Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Wheel, Dual Fuel Tanks Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 733,766 Mi Usage: 816,732 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Asset located in: Humble, TX 1446 2014 Freightliner Cascadia 125 6x4 T/A CHOICE OF 4 - Lot #'s: 1443, 1444, 1445, 1446 Sleeper Truck Tractor S/N: 3AKJGLD52ESFR3485 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 1443 2014 Freightliner Cascadia 125 6x4 T/A hp Engine, US EPA Label, Requires Diesel **Sleeper Truck Tractor** Exhaust Fluid, 22596 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, S/N: 1FUJGLDV0ELFK3902 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Automated Transmission, 13220 lb Front Axle, Ride Suspension, 238 in Wheelbase, Air Sliding 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 899,662 Mi GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Notes: DEFICIENCIES NOTED - PLEASE SEE Wheelbase, Air Sliding 5th Wheel, Dual Fuel THE INSPECTION REPORT; SELLING WITH A Tanks REPOSESSION AFFIDAVIT AND MAY NOT BE Usage: 542,197 Mi ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Humble, TX Asset located in: Lake Worth, TX 1446A 2014 Freightliner Cascadia 125 6x4 T/A 1444 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGLBG8ELBY9400 S/N: 3AKJGLD58ESFK2646 C/W: Cummins ISX15 450 6 Cylinder 15.0 L C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 23297 Engine hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 27101 Engine hrs, Engine Brake, Eaton Fuller RTOCM-16909A 13-Speed Manual Speed Manual Transmission, 12000 lb Front Transmission, 12350 lb Front Axle, 34000 lb Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1

Axle Ratio, 46350 lb GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 191,299 Mi

Asset located in: Humble, TX

hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 803,269 Mi

Lot # Details Lot # Details

CHOICE OF 3 - Lot #'s: 1447, 1448, 1449

1447 2013 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR8DLBV8807 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel Usage: 1,278,392 Mi

Asset located in: Lake Worth, TX

1448 2013 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLBG4DSBZ8339 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks Usage: Not Available

Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE

Asset located in: Lake Worth, TX

1449 2013 Freightliner Cascadia 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLDR7DSBB5155 C/W: 6 Cylinder Diesel 455 hp Engine, 27508.2 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Rear Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 799,106 Mi

Notes: ODOMETER DISCREPANCY-PLEASE SEE INSPECTION REPORT DEFICIENCIES

NOTED

Asset located in: Humble, TX

CHOICE OF 3 - Lot #'s: 1450, 1451, 1452

1450 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR8CSBT4009 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 497,836 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

1451 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLBG4CSBP1768
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
450 hp Engine, 2011 US EPA Label, Requires
Diesel Exhaust Fluid, Engine Brake, Eaton Fuller
FRO-15210C 10-Speed Manual Transmission,
12000 lb Front Axle, 40000 lb Rears, Meritor
MT-40-14X Drive Axles, 3.55:1 Axle Ratio,
52000 lb GVWR, Air Ride Cab, 72 in High Rise
Sleeper Cab, Bunk Beds, Auxiliary Power Unit,
Aluminum Front Wheels, 295/75R22.5, Airliner
Air Ride Suspension, 230 in Wheelbase, PTO,
Hydraulic Oil Cooler, Air Sliding 5th Wheel, Dual
Fuel Tanks

Usage: 592,035 Mi

Asset located in: Humble, TX

1452 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLBG1CSBM5211 C/W: Cummins ISX 15 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 3.42: 1 Axle Ratio, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 899,518 Mi

Details Lot # **Details** Lot # 1453 2010 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** CHOICE OF 2 - Lot #'s: 1457, 1458 S/N: 1FUJGLDR0ASAS4603 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 12000 lb Front 1457 2016 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGHDV9GLGS0046 Axle, 35268 lb Rears, Meritor RT-40-145 Drive C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Axles, 2.64:1 Axle Ratio, 47268 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Eaton Fuller 10-Speed Manual Transmission. Ride Suspension, 228 in Wheelbase, Air Sliding 13200 lb Front Axle, 40000 lb Rears, 53200 lb 5th Wheel, Dual Fuel Tanks GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Usage: 836,813 Mi Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 250 in Wheelbase, Asset located in: Lake Worth, TX Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 762,092 Mi CHOICE OF 2 - Lot #'s: 1454, 1455 Asset located in: Humble, TX 2016 Freightliner Cascadia 113 6x4 T/A 1458 1454 2018 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGHDV2GLGS0048 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel S/N: 3AKJGHDV8JSJX1807 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.31:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650-OH 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Axle Ratio, 52000 lb GVWR, Air Mid Roof Sleeper Cab, Aluminum Wheels, 295 Ride Cab, 72 in Condo Sleeper Cab, Aluminum /75R22.5, Airliner Air Ride Suspension, 225 in Wheels, 11R22.5, Airliner Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual Wheelbase, Hydraulic Oil Cooler, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 634,517 Mi **Fuel Tanks** Usage: 815,447 Mi Asset located in: Humble, TX Asset located in: Lake Worth, TX 1459 2014 Freightliner Cascadia 113 6x4 T/A 1455 2018 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJGHDV1ESFN7414 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2013 US EPA Label, CARB S/N: 3AKJGHDV9JSJJ2300 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, Requires Diesel Compliant, Requires Diesel Exhaust Fluid, Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, Exhaust Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12300 lb Front 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, Air Assist Front Suspension, Airliner 4-Bag Air Ride Ride Suspension, 209 in Wheelbase, Air Sliding Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available 5th Wheel

Asset located in: Midland, TX 1460 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

> S/N: 3AKJGLD55ESFN2395 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 32691 Engine hrs, Engine Brake, Eaton Fuller FRO-16210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Bunk Beds, RigMaster Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 717,423 Mi

Asset located in: Lake Worth, TX

Usage: 649,665 Mi

Asset located in: Midland, TX

			1 age 140 of 301
Lot #	Details	Lot #	Details
CHOICE 1461	HOICE OF 2 - Lot #'s: 1461, 1462 461 2018 Western Star 5700 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR2JLJZ0716 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, Requires Diesel Exhaust Fluid, 27535 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40009 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 653,881 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1466	2017 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH4HN971537 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 29 /75R22.5, Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks
			Usage: 838,421 Mi Asset located in : Lake Worth, TX
		1468	2017 Volvo VNL630 6x4 T/A Sleeper Truck
			Tractor S/N: 4V4NC9EG2HN990322 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 405 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT02612D 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 50350 lb GVWR, 61 in Mid Roof Sleeper Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 645,246 Mi
1462	462 2017 Western Star 5700 XE 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDRXHLJE5495 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 27690 Engine hrs, Retarder, Detroit DT12-OA-1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 54 in Mid Roof Sleeper Cab, 11R22.5, Airliner Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,491 Mi Asset located in: Lake Worth, TX		
			Asset located in: Lake Worth, TX
			2016 Volvo VNL 64T 630 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EJ3GN946212 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 500 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 61 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Volvo Air Ride Suspension, 136 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1463	2020 Volvo VNR400 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DH8LN270434 C/W: Volvo D11 6 Cylinder 10.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10991 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Volvo Air Ride Suspension, 197 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 304,892 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		
1464	2018 Volvo VNL300 6x4 T/A Sleeper Truck	1	
	Tractor S/N: 4V4NC9EH1JN899041 C/W: Volvo D13M425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12-Speed Automated Transmission, 12500 lb Front Axle,		

Usage: 568,767 Mi

Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Details Lot # **Details** Lot # 1470 1473A 2012 Volvo VNL64T 6x4 T/A Sleeper Truck 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TH2FN912681 Tractor C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2011 US EPA Label, CARB S/N: 4V4NC9EJ9CN542468 C/W: Volvo D13H475 6 Cylinder 12.8 L Diesel Compliant, Requires Diesel Exhaust Fluid, 475 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 5946 Engine hrs, Engine Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Brake, Eaton Fuller FRO-16210C 10-Speed Rears, 51200 lb GVWR, Air Ride Cab, 42 in High Manual Transmission, 12350 lb Front Axle, Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air 38000 lb Rears, Meritor MT-40-14X Drive Axles, Ride Suspension, 226 in Wheelbase, Air Sliding 3.42:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 5th Wheel, Dual Fuel Tanks 61 in Mid Roof Sleeper Cab, Aluminum Front Usage: 480,143 Mi Wheels, 295/75R22.5, Air Ride Suspension, 238 in Wheelbase, PTO, Hydraulic Oil Cooler, Air Notes: ODOMETER DISCREPANCY-UNIT Sliding 5th Wheel, Dual Fuel Tanks Usage: 567,803 Mi SHOWS 480,143, TITLE SHOWS 485,418; THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH Asset located in: Lake Worth, TX LIABILITIES OUTLINED IN TEXAS 1473B ADMINISTRATIVE CODE SECTIONS 114.20 2017 International Lonestar 6x4 T/A Sleeper AND 114.50. THIS MAY APPLY IF YOU **Truck Tractor** OPERATE THE UNIT PRIOR TO THE ADEQUATE S/N: 3HSCXAPRXHN752298 RESTORATION OF ALL POLLUTION CONTROL C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 475 hp Engine, 2016 US EPA Label, Requires SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN Diesel Exhaust Fluid, 22842 Engine hrs, Eaton ACKNOWLEDGEMENT FORM OF THIS NOTICE Fuller 13-Speed Manual Transmission, 12350 PRIOR TO REMOVAL OF UNIT FROM YARD lb Front Axle, 40000 lb Rears, 52350 lb GVWR, **DEFICIENCIES NOTED - PLEASE SEE THE** Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk INSPECTION REPORT Beds, 295/75R22.5, Air Ride Suspension, 247 Asset located in: Humble, TX in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 1471 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor Usage: 736,300 Mi S/N: 4V4NC9EH3FN916526 C/W: Volvo D13J425 6 Cylinder 12.8 L 425 hp Engine, 2014 US EPA Label, Requires Diesel Notes: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, CANNOT BE DRIVEN. TEMP TAGS WILL NOT Exhaust Fluid, Engine Brake, Volvo ATO2612D BE ISSUED 12-Speed Automated Transmission, 12350 lb Asset located in: Lake Worth, TX Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk CHOICE OF 2 - Lot #'s: 1474, 1476 Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 1474 2018 International LT625 6x4 T/A Sleeper Usage: 763,465 Mi **Truck Tractor** Asset located in: Lake Worth, TX S/N: 3HSDZAPR4JN524544 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel 1472 2013 Volvo VNL T/A Sleeper Truck Tractor S/N: 4V4NC9TG2DN142504 Exhaust Fluid, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Usage: Not Available Asset located in: Lake Worth, TX Rise Sleeper Cab, Aluminum Front Wheels, 295 /75R22.5 Front Tires, 275/80R22.5 Rear Tires, 1473 2012 Volvo VNL 6x4 T/A Sleeper Truck Tractor Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 433,846 Mi S/N: 4V4NC9EH0CN543487 C/W: Volvo D13H425 6 Cylinder 12.8 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 3279 Engine hrs, Volvo ATO2612D Automated Transmission, 12350 lb Asset located in: Lake Worth, TX 1476 2018 International LT625 6x4 T/A Sleeper Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GVWR, Air Ride Cab, 61 in Truck Tractor High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 214 in Wheelbase, Air Sliding 5th S/N: 3HSDZAPR2JN247098 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11639 Engine hrs, Engine Wheel, Dual Fuel Tanks Usage: 937,793 Mi

S/N: 3HSDZAPR2JN247098 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11639 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 429,685 Mi

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1476A	Truck Tractor S/N: 3HSDZAPR4JN233073 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 16277 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 507,109 Mi Asset located in: Humble, TX 2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9JN326333 C/W: Cummins X15 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel	1479	2017 International ProStar T/A Sleeper Truck Tractor S/N: 3HSDJAPR1HN693549 Usage: Not Available Asset located in: Humble, TX
		1480	2017 International ProStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR1HN204325 C/W: Cummins ISX 450ST 6 Cylinder 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 73 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, 267 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 505,833 Mi Asset located in: Humble, TX
	•		C/W: International N13 6 Cylinder 12.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 12350

CHOICE OF 4 - Lot #'s: 1477, 1478, 1479, 1480

1477 2017 International Prostar 6x4 T/A Sleeper **Truck Tractor**

S/N: 3HSDJAPR8HN284030 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14712 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks**

Usage: 644,916 Mi

Notes: .

Asset located in: Lake Worth, TX

1478 2017 International Prostar+ 122 6x4 T/A **Sleeper Truck Tractor**

S/N: 3HSDJSNR2HN447862 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19396 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 542,861 Mi

Asset located in: Lake Worth, TX

eeper

4 L Diesel Engine Brake, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Dual Fuel Tanks Usage: 842,762 Mi

Asset located in: Lake Worth, TX 1482 2016 International Prostar+ 122 6x4 T/A

S/N: 3HSDJAPR2GN428556 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 16496 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks

Usage: 614.573 Mi

Sleeper Truck Tractor

Details Lot# **Details** Lot # 1483 2015 International ProStar 6x4 T/A Sleeper **Truck Tractor** CHOICE OF 2 - Lot #'s: 1486, 1487 S/N: 3HSDJAPR3FN676250 C/W: Cummins ISX15 15 L Engine, 2014 US 1486 EPA Label, Requires Diesel Exhaust Fluid, 2014 International Prostar+ 122 6x4 T/A 19816 Engine hrs, Engine Brake, 9-Speed Sleeper Truck Tractor Manual Transmission, 12350 lb Front Axle, S/N: 3HSDJAPR7EN796955 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17185 Engine hrs, Engine 73 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Brake, Automated Transmission, 12350 lb Wheel, Dual Fuel Tanks Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Usage: 654,586 Hr Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN Air Ride Suspension, 230 in Wheelbase, Air TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE Sliding 5th Wheel, Dual Fuel Tanks Usage: 658,173 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE RESTORATION OF ALL POLLUTION CONTROL THE INSPECTION REPORT SYSTEMS OR DEVICES AS ORIGINALLY Asset located in: Humble, TX EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE 1487 2014 International Prostar+ 122 6x4 T/A PRIOR TO REMOVAL OF UNIT FROM YARD Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 3HSDJSJR7EN759578 C/W: International MaxxForce 13 6 Cylinder 1484 2015 International Prostar+ 122 6x4 T/A 12.4 L Diesel 450 hp Engine, 2013 US EPA Sleeper Truck Tractor Label, Requires Diesel Exhaust Fluid, 17281 S/N: 3HSDJAPR9FN526675 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front C/W: Cummins ISX 400ST 6 Cylinder Diesel 218 hp Engine, 2014 US EPA Label, CARB Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Compliant, Requires Diesel Exhaust Fluid, Engine Brake, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Suspension, 230 in Wheelbase, Dual Fuel Tanks Roof Sleeper Cab, Aluminum Wheels, 275 /80R22.5, 252 in Wheelbase, Air Sliding 5th Usage: 549,311 Mi Asset located in: Lake Worth, TX Wheel, Dual Fuel Tanks Usage: 676,438 Mi Asset located in: Humble, TX CHOICE OF 2 - Lot #'s: 1490, 1491 1485 2015 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor 1490 2012 International Prostar 6x4 T/A Sleeper S/N: 3HSDJAPR3FN668830 **Truck Tractor** C/W: Cummins ISX 400ST 6 Cylinder Diesel

S/N: 3HSDJAPR3FN668830 C/W: Cummins ISX 400ST 6 Cylinder Diesel 218 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 19195 Engine hrs, Engine Brake, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 658,953 Mi

Asset located in: Humble, TX

S/N: 3HSDJSJR7CN094078 C/W: 6 Cylinder Diesel Engine, 34209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 11R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 689,264 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT

Asset located in: Humble, TX

	Detaile	1 0+ #	Dataila
Lot #	Details	Lot #	Details
1491	2012 International Prostar 6x4 T/A Sleeper Truck Tractor	1495	2000 Peterbilt 379 6x4 T/A Sleeper Truck Tractor
	S/N: 3HSDJSJR1CN094075 C/W: 6 Cylinder Diesel Engine, 27815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 798,884 Mi		S/N: 1XP5DR9X3YD506553 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 450 hp Engine, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 58 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Leaf 4-Bag Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 455,326 Mi
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE
	Asset located in: Humble, TX		Asset located in: Humble, TX
1492	2005 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X55R076276 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, 13-Speed Manual Transmission, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 106,655 Mi Asset located in: Lake Worth, TX	1497	2005 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDB9X95J099229 C/W: Cat C15 6 Cylinder 15 L Diesel 475 hp Engine, 30565 Engine hrs, Engine Brake, Eaton Fuller 10-Speed hybrid, automatic with clutch Transmission, 40000 lb Rears, Dana DSP40 Drive Axles, 3.36:1 Axle Ratio, 62 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, 4- Bag Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 161,706 Mi
2007 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X87N667738 C/W: Cat C15 6 Cylinder Diesel 550 hp Engine, 35138.1 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, COLEMAN MACK Electric Sleeper Air Conditioner, 3cyl KUBOTA Auxiliary Power Unit, 315/80R22.5 Front Tires, 285/75R24.5 Rear Tires, Low Air Leaf Air Ride Suspension, 312 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, Custom	2007 Peterbilt 379 6x4 T/A Sleeper Truck	1	Asset located in: Lake Worth, TX
	1498	1996 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDR9XXTR729761 C/W: Detroit/series60 6 Cylinder 12.7 L Diesel 470 hp Engine, 1996 US EPA Label, Engine Brake, Manual Transmission, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 258 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 310,988 Mi Asset located in: Lake Worth, TX	
	Condo Sleeper Equipped with Shower/Toilet Combo, Convection Oven and Refrigerator	1499	2005 Freightliner Coronado 132 6x4 T/A
	Usage: 1,479,428 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		Sleeper Truck Tractor S/N: 1FUJCRCK65PU90416 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2004 US EPA Label, Engine Brake, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.58:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295/75R22.5, Air Assist Front Suspension, Airliner Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,885,684 Mi Asset located in: Lake Worth, TX
1494	2003 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X43D802164 C/W: Cat C15 6 Cylinder 14.6 L Diesel 475 hp Engine, 2001 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Aluminum Wheels, 285/75R24.5, Low Air Leaf Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 93,811 Mi		

Lot #	Details	Lot #	Details
1499A	2007 Western Star 4900SA 6x4 T/A Sleeper Truck Tractor S/N: 5KJJALCK77PX38561 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2006 US EPA Label, 24734 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 4.11:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 34 in Flat Top Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 210 in Wheelbase, PTO, Dual Fuel Tanks Usage: 258,812 Mi Asset located in: Lake Worth, TX	1503	2005 Kenworth T2000 6x4 T/A Sleeper Truck Tractor S/N: 1XKTDB9X15J058198 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, Spicer DSP40 Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
1500	2006 International 9400L 6x4 T/A Sleeper Truck Tractor S/N: 2HSCNSCR46C195887	СНОІСІ	E OF 2 - Lot #'s: 1505, 1506
	C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 72 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,001,440 Mi Asset located in: Lake Worth, TX	1505	2006 Mack CXN613 8x4 Tri/A Sleeper Truck Tractor S/N: 1M1AK07YX6N011822 C/W: Mack 6 Cylinder Diesel Engine, 2005 US EPA Label, 23598 Engine hrs, Engine Brake, Mack 18-Speed Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Lift
1501	2006 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7DB9X16D896274 C/W: Cat C15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, Low Air Leaf Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,814,828 Mi Asset located in: Lake Worth, TX 2007 Kenworth T600 6x4 T/A Sleeper Truck Tractor S/N: 1XKADB9X57J158461 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller RTLOC16909AT2 Manual Transmission, Dana DSP40 Drive		Pusher Axle, Air Ride Suspension, 233 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: 414,912 Mi Asset located in: Lake Worth, TX
		1506	2006 Mack CXN613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AK06Y86N014932 C/W: Mack AC 6 Cylinder Diesel 380 hp Engine, 2005 US EPA Label, 23678 Engine hrs, Engine Brake, Mack T310 10-Speed Manual
1502			Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Flat Top Sleeper Cab, Bunk Heater, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 214 in Wheelbase, PTO, Headache Rack Usage: 549,542 Mi Asset located in: Humble, TX
	Axles, 3.55:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk	1507	2005 Mack CX613 6x4 T/A Sleeper Truck
	Beds, Aluminum Wheels, 11R22.5, Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,098,883 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1M1AE05Y75N021491 C/W: Mack 6 Cylinder Diesel Engine, 2004 US EPA Label, 15393 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 211 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 517,922 Hr

Details Lot # **Details** Lot # 1508 1514 2008 International ProStar Premium 6x4 T/A 2001 Freightliner ST120 6x4 T/A Sleeper Truck **Sleeper Truck Tractor** Tractor S/N: 2HSCUAPR48C686955 S/N: 1FUJBBBD91LH91702 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, C/W: Cummins N14 6 Cylinder 14.0 L Diesel 435 hp Engine, 2000 US EPA Label, Meritor MO-14G10A-M14 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb 12000 lb Front Axle, 40000 lb Rears, Meritor RT-GVWR, Air Ride Cab, 56 in Mid Roof Sleeper 40-145 Drive Axles, 3.73:1 Axle Ratio, 52000 lb Cab, Aluminum Outer Wheels, 295/75R22.5, Air GVWR, Air Ride Cab, 72 in High Rise Sleeper Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Usage: 1,049,713 Mi Airliner Suspension, 226 in Wheelbase, Dual **Fuel Tanks** Asset located in: Lake Worth, TX Usage: 854,362 Mi 1509 2006 International 9400i 6x4 T/A Sleeper Asset located in: Lake Worth, TX **Truck Tractor** 1515 2000 Freightliner FLD 120 6x4 T/A Sleeper S/N: 2HSCNAPR16C228106 **Truck Tractor** C/W: Cummins ISX 14.9 L Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air S/N: 1FUPCSEB4YDF85578 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, 1999 US EPA Label, Engine Ride Cab, 51 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Brake, Eaton Fuller 13-Speed Manual Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,412,255 Mi Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Asset located in: Lake Worth, TX Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 1510 2009 Freightliner Columbia 120 6x4 T/A Usage: 972,743 Mi **Sleeper Truck Tractor** Asset located in: Midland, TX S/N: 1FUJA6CK19LAD2685 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 1516 1995 Freightliner FLD 120 6x4 T/A Sleeper 455 hp Engine, Engine Brake, Eaton Fuller RTO-16910B-DM 10-Speed Automated Truck Tractor Transmission, 12000 lb Front Axle, 40000 lb S/N: 1FUPDZYB7SH718722 C/W: Detroit 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Rears, Dana DS404 Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, 11R22.5 Front Tires, 295 Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum /75R22.5 Rear Tires, Airliner Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheels, 11R24.5, Air Ride Suspension, 246 in Wheel, Dual Fuel Tanks Usage: 587,873 Mi Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX Usage: 687,717 Mi 1511 2007 Freightliner Century Class CST120 6x4 T Asset located in: Humble, TX /A Sleeper Truck Tractor 1517 1996 Freightliner USF-E1 6x4 T/A Sleeper S/N: 1FUJBBAV37LX21774 **Truck Tractor** C/W: Cat C15 6 Cylinder Diesel Engine, 18993 Engine hrs, Engine Brake, Eaton Fuller Manual S/N: 1FUYDDYBXTP613588 C/W: 6 Cylinder Diesel Engine, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 285/75R24.5 Front Tires, 11R24. Transmission, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Áluminum Outer Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Dual **Fuel Tanks** Usage: 955,175 Mi 5 Rear Tires, Airliner Air Ride Suspension, Air Asset located in: Humble, TX Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available 1512 2006 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 1FUJA6CK86LV66960 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2005 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front CHOICE OF 2 - Lot #'s: 1518, 1519 Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, 295/75R22.5, 1518 2023 Capacity TJ5000 Spotter Truck Airliner Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks S/N: 4LMBF5111PL041353

Usage: Not Available Asset located in: Lake Worth, TX

Wheel

C/W: Allison Automatic Transmission, 295

/75R22.5, 130 in Wheelbase, Hydraulic Lift 5th

Usage: 1,027,381 Mi

Lot #	Details	Lot #	Details
1519	2023 Capacity 4x2 Spotter Truck S/N: 4LMBF5119PL041360 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 11R22.5, 132 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Asset located in: Humble, TX	1524	2015 Ottawa Sabre 5 4x2 Spotter Truck S/N: 335984 C/W: Cummins QSB 6.7 L 165 hp Engine, 2014 US EPA Label, Allison Transmission, 295 /75R22.5, 118 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: TITLE IS BRANDED AS NOT ACTUAL
1520	2021 Capacity 4x2 Spotter Truck S/N: 4LMBF2115ML029314		MILEAGE Asset located in: Lake Worth, TX
	C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb	СНОІС	E OF 5 - Lot #'s: 1525, 1526, 1527, 1528, 1529
	Rears, 36000 lb GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, 116 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 30,689 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	1525	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2110BL022565 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2014 US EPA Label, Allison Automatic Transmission, 12000 lb Front Axle, 23000 lb Rears, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available
СНОІС	E OF 2 - Lot #'s: 1521, 1522		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
1521	2019 Ottawa 6x4 Spotter Truck S/N: 4LMDB7136KL027975 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 173 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5750 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Steel, 11R22.5 Front Tires, 255/70R22.5 Rear Tires, 154 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 8,516 Mi Asset located in: Lake Worth, TX	1526	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2112BL022566 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2014 US EPA Label, Automatic Transmission, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
1522	2019 Ottawa 4x2 Spotter Truck S/N: 4LMSB2114KL031788 C/W: Cummins QSB4.5 4 Cylinder 5.4 L Diesel 173 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 24000 lb Rears, Steel, 11R22.5, 115 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 10,626 Mi Asset located in: Lake Worth, TX	1527	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2113BL022611 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2021 US EPA Label, 2649 Engine hrs, Allison Automatic Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 87,798 Mi
1523	2017 Ottawa T2 4x2 Spotter Truck		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	S/N: 343984 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, 7207 Engine		Asset located in: Lake Worth, TX
	hrs, Allison Transmission, Steel, 11R22.5, Spring Suspension, 116 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 30,805 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY	1528	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2118BL022569 C/W: Cummins 6 Cylinder Diesel Engine, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available
	Asset located in: Lake Worth, TX		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;

-			
Lot #	Details	Lot #	Details
1529	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR211XBL022573 C/W: Cummins 6.7 L Diesel Engine, Allison Automatic Transmission, 275/80R22.5, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 25,696 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	1536 1537	2003 Sherman Reily T/A Tensioner S/N: 123WM212831T16188 C/W: Honda 2 Cylinder Gasoline Engine Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2011 Wagner-Smith T-5DP-120 Hydraulic Cable Puller
	Asset located in: Lake Worth, TX		S/N: 1W9DP4321BA161085
1530	2008 Ottawa TY30 4x2 Spotter Truck S/N: 318992 C/W: Cummins QSB 6 Cylinder 6.7 L Diesel Engine, Allison Automatic Transmission, 275 /80R22.5, 111 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available		C/W: 2010 US EPA Label, John Deere 4 Cylinder Diesel Engine, (5) Reels; EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	1538	Altec AT235P 35 ft on 2015 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GT5FED59378 C/W: Ford 6.7 L Diesel 300 hp Engine, 2015 US
1531	2006 Ottawa TY30 4x2 Spotter Truck S/N: 314014 C/W: Cummins USB 6 Cylinder 5.9 L 155 hp Engine, Automatic Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX	1539	EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 165 in Wheelbase, 300 lb Capacity, Front Mounted, One-Person Articulating-Telescopic Boom, Utility Body, 11 ft x 94 in Bed Usage: 75,582 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX Tornado F4SL on 2015 Western Star 4900 8x6
1532	CRC PB Pipe Bending Machine S/N: 20-267 C/W: Bends 6 in to 20 in Pipe, Tow Behind, Winch, Kubota Diesel Engine Usage: 1,103 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	Vacuum Excavator Truck S/N: 5KKPALD10FPGA1440 C/W: Detroit DD16 6 Cylinder 15. hp Engine, 2014 US EPA Label, Re Exhaust Fluid, 35902 Engine hrs, Eaton Fuller 18-Speed Manual Tr Triple Differential Locks, 20000 II 57000 Ib Rears, 4.30:1 Axle Ratio	Vacuum Excavator Truck
	RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK		/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Airliner
1534	2012 Sauber 1570-B Portable Tensioner S/N: 1F9UZ1313CV048037 C/W: Kawasaki FD731V 2 Cylinder Gasoline Engine Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	Sus Deb Tele Hyd 564 Con Usa Not e	Suspension, 303 in Wheelbase, Steel 2150 gal Debris Tank, Hydraulic Tailgate Locks, Telescopic Boom, 8 in Suction Hose, Cat Hydraulic Driven Pump, Robuschi Blower w/ 5642 hrs, Hotshot Boiler, Cordless Remote Control, 77000 lb GVWR Usage: 10,861 Km Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
1535	2008 TSE DPT40B T/A Tensioner S/N: 1T92C15238S268017 C/W: 2007 US EPA Label, John Deere 4024TF270C 36 kW 2.4 L Diesel Engine Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		

1540 Foremost on 2013 Western Star 4900 8x6 Vacuum Excavator Truck

Details

Lot #

S/N: 5KKPALDR6DPBH7992
C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 530
hp Engine, Requires Diesel Exhaust Fluid, 8104
Engine hrs, Engine Brake, Eaton Fuller RTLO18918B Manual Transmission, Double
Differential Locks, 20000 lb Front Axle, 56700
lb Rears, Meritor RZ-166 Drive Axles, 4.56:1
Axle Ratio, 76700 lb GVWR, Air Ride Cab,
Aluminum Front Wheels, 445/65R22.5 Front
Tires, 11R24.5 Rear Tires, Dual Steering Boxes,
Double Frame, Airliner Air Ride Suspension,
318 in Wheelbase, PTO, Hydraulic Oil Cooler,
Steel Debris Tank, Hydraulic Lift Tailgate,
Hydraulic Tailgate Locks, Telescopic Boom, 8
in Suction Hose, Cat Hydraulic Driven Pump,
Robuschi Blower, Cordless Remote Control,

76700 lb GVWR Usage: 105,864 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX

1540A Vactor Guzzler on 2014 Kenworth T800 8x4 Vacuum Excavator Truck

S/N: 1NKDX4EX4EJ386464
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
485 hp Engine, 2012 US EPA Label, Requires
Diesel Exhaust Fluid, 19129 Engine hrs, Engine
Brake, Eaton Fuller FRO-16210C 10-Speed
Manual Transmission, 20000 lb Front Axle,
58350 lb Rears, 4.10:1 Axle Ratio, 78350 lb
GVWR, Air Ride Cab, Aluminum Outer Wheels,
425/65R22.5 Front Tires, 11R22.5 Rear Tires,
Steerable Air Lift Pusher Axle, Dual Steering
Boxes, Double Frame, Hendrickson RT/RTE
Series Suspension, 307 in Wheelbase, PTO,
Steel Debris Tank, Hoist, Fresh Water Tank,
Hydraulic Lift Tailgate, Hydraulic Tailgate
Locks, Telescopic Boom, 8 in Suction Hose,
Cat Hydraulic Driven Pump, Ingersoll-Rand
SIAV 8702 Blower w/ 13367 hrs, 49786 Boiler,
78350 lb GVWR

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Usage: 203,514 Mi

1540B 2013 Kenworth T800 8x4 Vacuum Excavator Truck

S/N: 1NKDX4EX6DJ352704
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
485 hp Engine, 2012 US EPA Label, Requires
Diesel Exhaust Fluid, 19700 Engine hrs, Engine
Brake, Eaton Fuller FRO-16210C 10-Speed
Manual Transmission, 20000 lb Front Axle,
58350 lb Rears, 4.10:1 Axle Ratio, 78350 lb
GVWR, Air Ride Cab, Aluminum Outer Wheels,
425/65R22.5 Front Tires, 11R22.5 Rear Tires,
Steerable Air Lift Pusher Axle, Dual Steering
Boxes, Double Frame, Hendrickson RT/RTE
Series Suspension, 307 in Wheelbase, PTO,
Steel Debris Tank, Hoist, Fresh Water Tank,
Hydraulic Lift Tailgate, Hydraulic Tailgate
Locks, Telescopic Boom, 8 in Suction Hose,
Cat Hydraulic Driven Pump, Ingersoll-Rand
SIAV 8702 Blower w/ 3004 hrs, 78350 lb GVWR
Usage: 251,604 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

1540C 2013 Kenworth T800 8x4 Vacuum Excavator

Lot #

Details

Truck

S/N: 1NKDX4EX3DJ334497 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21666 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 20000 lb Front Axle, 58350 lb Rears, 4.10:1 Axle Ratio, 78350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Suspension, 307 in Wheelbase, PTO, Steel Debris Tank, Hoist, Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Telescopic Boom, 8 in Suction Hose, Cat Hydraulic Driven Pump, Ingersoll-Rand SIAV 8702 Blower w/ 13716 hrs, Water Pro-Tech 47390L Boiler, 78350 lb GVWR Usage: 262,312 Mi Notes: RITCHIE-BROS-ENERGY

Asset located in: Lake Worth, TX

1540D 2013 Kenworth T800 8x4 Vacuum Excavator Truck

S/N: 1NKDX4EX1DJ334496
C/W: Cummins ISX 6 Cylinder 15.0 L Diesel
Engine, Requires Diesel Exhaust Fluid, 1616
Engine hrs, Eaton Fuller 10-Speed Manual
Transmission, 20000 lb Front Axle, 46000 lb
Rears, 78350 lb GVWR, Aluminum Outer
Wheels, 425/65R22.5 Front Tires, 11R22.5
Rear Tires, Steerable Air Lift Pusher Axle, Dual
Steering Boxes, Double Frame, Hendrickson RT
/RTE Series Spring over Walking Beam
Suspension, 305 in Wheelbase, PTO, Steel
Debris Tank, Hydraulic Lift Tailgate, Hydraulic
Tailgate Locks, 12 ft Boom, 8 in Suction Hose,
Cat PTO Driven Pump, Blower w/ 11961 hrs,
Boiler, 78350 lb GVWR
Usage: 222,254 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

1542 Gap-Vac on 2002 Volvo VHD 6x4 Vacuum Excavator Truck

S/N: 4V5KC9UF92N321981 C/W: Cummins ISM 10.8 L Diesel 325 hp Engine, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring over Walking Beam Suspension, 254 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, PTO Driven Pump, 64000 lb GVWR Usage: Not Available

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT ; RITCHIE-BROSENERGY

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1543	Vactor 2100 Series on 2002 Sterling L9500 6x4 Vacuum Excavator Truck S/N: 2FZHAZAS02AK42561 C/W: Cat C12 6 Cylinder Diesel 355 hp Engine, 8023 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Steel, 425 /65R22.5, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 252 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Boom, 8 in Suction Hose, PTO Driven Pump, Roots 824RSCV18 Blower, 66000 lb GVWR Usage: 134,573 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	1547	2014 International 7600 6x4 Vacuum Tanker Truck S/N: 1HTGSSNTXEH029640 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 46000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Air Ride Suspension, 228 in Wheelbase, 2000 gal Debris Tank, 64000 lb GVWR Usage: 240,009 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2013 International 7400 4x2 Pressure Truck
			S/N: 1HTWCAZN2DJ200547 C/W: 6 Cylinder Diesel Engine, Eaton Fuller 8LL
1544	2001 Ford F-550 XL 4x2 Vacuum Excavator Truck S/N: 1FDAF56F71EC85002 C/W: Ford 7.3 V8 7.3 L Diesel Engine, 978 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 201 in Wheelbase, 100 gal Debris Tank, Rear Hose		Manual Transmission, 10000 lb Front Axle, 23000 lb Rears, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Spring Suspension, 222 in Wheelbase, PTO, weatherford Triplex Pump, Fiberglass Reinforced Plastic Tank Usage: 221,859 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Reel, 4 in Suction Hose, 17500 lb GVWR	1549A	2008 Mack CHU613 8x4 Winch Truck
CHOICI 1545	Usage: 233,622 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX HOICE OF 2 - Lot #'s: 1545, 1546	1550	S/N: 1M2AN07Y08N003038 C/W: Mack MP8 6 Cylinder 12.8 L 338 hp Engine, 2007 US EPA Label, 8203 Engine hrs, Mack Manual Transmission, Air Ride Cab, 11R24.5, Air Lift Pusher Axle, Camelback Spring Suspension, 252 in Wheelbase, PTO, Tail Roll, Tulsa Winch RN65WM-RFO 65000 lb Winch Usage: 168,363 Mi Notes: LOCATED-IN-FORT-WORTH-TX RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2000 International 9900 6x4 Winch Truck
	Exhaust Fluid, 27175 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 38000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 268 in Wheelbase, Aluminum 3800 gal Debris Tank, Non Code Code, Manual Tailgate Locks, PTO Driven Pump, 38000 lb GVWR Usage: 402,799 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		S/N: 2HSFTAER6YC050198 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 435 hp Engine, Eaton Fuller 8LL Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Steel, 11R22.5, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, Tail Roll, Tulsa Winch Usage: 540,116 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
1546	2012 Mack GU713 8x4 Vacuum Tanker Truck S/N: 1M2AX07C8CM012213 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, Air Ride Cab, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Ride Suspension, 272 in Wheelbase, Aluminum Debris Tank, 64000 lb GVWR Usage: 469,818 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	1551	1995 International 9200 6x4 Winch Truck S/N: 2HSFMAHR6SC052503 C/W: Cummins 6 Cylinder 10.8 L Diesel 370 hp Engine, 1995 US EPA Label, Spicer 10-Speed Manual Transmission, 295/75R22.5, Air Ride Suspension, 190 in Wheelbase, Tulsa Winch, Air sliding fifth wheel Usage: 691,448 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
Lot #_ 1551A	2012 Kenworth T300 6x4 Wireline Logging Truck S/N: 2NKHLN9X6CM298275 C/W: Cummins ISC 6 Cylinder Diesel Engine, 6734 Engine hrs, Engine Brake, Eaton Fuller FRO-11210C 10-Speed Manual Transmission, Double Differential Locks, 14600 lb Front Axle, 40000 lb Rears, Meritor RT-41-145 Drive Axles, 4.63:1 Axle Ratio, 54600 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 249 in Wheelbase, PTO Usage: 57,977 Mi Notes: RITCHIE-BROS-ENERGY	1556 1557	Texoma 270 on 1984 International 1954 4x2 Drill Truck S/N: 1HTLDUXP6EHA31702 C/W: John Deere 4045DF 6.8 L 4 Cylinder Upper Engine, Straight Down Outriggers, Rear Outriggers, 6 Cylinder Diesel Engine, Manual Transmission, 11R22.5, Spring Suspension, 170 in Wheelbase Usage: 280,022 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2019 Thunder Vermeer R250C Mud Mixing System
1552	Asset located in: Lake Worth, TX Texoma 500-15 on 2004 International 7400 6x4 Pressure Digger S/N: 1HTWGADT34J083149 C/W: Detroit 4 Cylinder Upper Engine, Winch, Straight Down Outriggers, Rear Outriggers, Bumper Mounted Winch, International 6		S/N: 56ZL2UZ20KP000069 C/W: (4) Shale Shakers, John Deere 4045 4 Cylinder 4.5 L Diesel Engine Usage: 1,607 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Cylinder Diesel Engine, 10013 Engine hrs, Allison Automatic Transmission, Differential Lock, 16000 lb Front Axle, 53120 lb Rears, 56000 lb GVWR, Air Ride Cab, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 205 in Wheelbase Usage: 91,448 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	Steer Drill Truck S/N: 907835 C/W: PTO Driven, Rotary Air Dri Changer, Winch, Straight Down Detroit Series 60 6 Cylinder 14 Engine, 2007 US EPA Label, En Eaton Fuller 18-Speed Manual 44000 lb Front Axle, 74240 lb F GVWR, Aluminum Wheels, 425, Tires, 12R22.5 Rear Tires, Air L Walking Beam Suspension, 298 PTO, EQUIPMENT-FROM-GASO Usage: 8,461 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, V 1576 Star 150K on 2006 Gefco Star Steer Drill Truck S/N: 907730 C/W: PTO Driven, Rotary Air Dri Changer, Winch, Straight Down Detroit Series 60 6 Cylinder 14. hp Engine, 2006 US EPA Label, Eaton Fuller 18-Speed Manual 44000 lb Front Axle, 54240 lb F GVWR, 425/65R22.5 Front Tire Tires, Air Lift Pusher Axle, Walk Suspension, 298 in Wheelbase EQUIPMENT-FROM-GASCO-DR Usage: 3,356 Hr Notes: RITCHIE-BROS-ENERGY AVAILABLE, SOLD WITH BILL 0	
1554	Texoma 3301500 on 1993 Mack RD690S 4x2 Drill Truck S/N: 1M2P264Y0PM013308 C/W: Cummins 4BTA3.9-C 3.9 L 4 Cylinder Upper Engine, Mack EM7 6 Cylinder Diesel 300 hp Engine, 1993 US EPA Label, 16469 Engine		Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC
	hrs, Eaton Fuller 9-Speed Manual Transmission, Steel, 11R24.5, Camelback Spring Suspension, 212 in Wheelbase Usage: 273,655 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		S/N: 907730 C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder 14.0 L Diesel 665
1555	Texoma 600 on 1985 International F-1954 6x4 Drill Truck S/N: 1HTLKTVR9FHA26144 C/W: Deutz TCD2012L042V 4.0 L 4 Cylinder Upper Engine, Winch, Out and Down Outriggers, Rear Outriggers, 6 Cylinder Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 11R22.5, Double Frame, Hendrickson RT/RTE Series Suspension, 206 in Wheelbase Usage: 164,298 Mi Notes: RITCHIE-BROS-ENERGY		hp Engine, 2006 US ÉPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 44000 lb Front Axle, 54240 lb Rears, 98240 lb GVWR, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 3,356 Hr Notes: RITCHIE-BROS-ENERGY; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details	
1577	tar 150 on 2004 Gefco Star 150K 10x4 Twin- iteer Drill Truck ic/N: 907612 ic/W: PTO Driven, Rotary Air Drill, Auto Rod changer, Winch, Straight Down Outriggers, itetroit Series 60 6 Cylinder Diesel Engine, ingine Brake, Eaton Fuller 18-Speed Manual iransmission, 42000 lb Front Axle, 74240 lb itears, 116240 lb GVWR, 425/65R22.5 Front ires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Valking Beam Suspension, 294 in Wheelbase, ivon, EQUIPMENT-FROM-GASCO-DRILLING-INC ilsage: Not Available	1583	(Rig#24) 3-Pit Mud System Mud Tank S/N: Not Available C/W: shopbuilt 8'W x 6'h x 20'L 220-BBL premix tank mud agitator, shopbuilt 8'W x 6'H x 30'L 206-BBL suction tank mud agitators, Shopbuilt 8'W x 6'H x 30'L 206-BBL shaker tank, Vortex Orbital 3000M single screen linear motion shale shaker, all skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1584	(Rig#24) Fuel Tank & Parts House S/N: Not Available	
1578	(Rig#24) Lee C Moore 133 ft Cantilever Mast S/N: T1728 C/W: 470,000 Lb Static Hook Load, Crown Block, w/ Sheave Cluster, Fastline Sheave, Racking Board, Tong Counter Weights, Ladder, Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, qty 4 (2) sets of 40"H x 30'L triangular pipe racks, block hook combo, drill line spool; EQUIPMENT-FROM-TPI-	C/W: 7'W x 12'L round top flat steel house w/ 4'L covered porch extens fluorescent lighting skidded, 8'W x 8 10,000 gallon fuel tank, w/ 8'L porc (2) 110V pumps, skidded; EQUIPM TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	house w/ 4'L covered porch extension, shelving fluorescent lighting skidded, 8'W x 8'H x 21'L 10,000 gallon fuel tank, w/ 8'L porch extension, (2) 110V pumps, skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC Usage: Not Available	
	COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1585	(Rig#24) Quantity of (2) Cat Containerized Generator Set S/N: Not Available C/W: Cat 3406 Diesel Engine, Electrical panels,	
1579	(Rig#24) 28 ft x 16 ft x 46 ft 9 in Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	1586	Fluorescent lighting, Storage area, Sullivan Palatek compressor; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX (Rig#24) National 55 S/D Drawworks	
1580	(Rig#24) 10 ft x 32 ft Doghouse S/N: Not Available C/W: knowledge box, bench storage, lockers, parts bins, fluorescent lighting, skidded;; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX		Drawworks S/N: T1890 C/W: 1,000 Hp, Lebus Grooved for 1-1/8" line, FOSTER Makeup & Breakout Catheads,2- Engine in line compound, (2) National c300185 torque converters, 2-stage air compressor, radiators, air start, muffler, master skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
1581	(Rig#24) 8 ft x 31 ft Mud House S/N: Not Available C/W: shelving, misc rig parts, skidded, Parts /Change House, Bench Storage, Parts Room; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX		1587 (Rig S/N C/W end mud air s mas COL	Asset located in: Coleman, TX (Rig#24) Triplex Mud Pump S/N: Not Available C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/ screw in caps, pulsation dampener, mud gauge, cent pump, Cat 12V Diesel engine, air start, radiator, muffler, air and fuel tanks, master skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available
1582	(Rig#24) Quantity of (2) 10 ft x 33 ft 500 bbl Water Tank S/N: Not Available C/W: cent pump, ladder, skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX		Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	

Lot #	Details	Lot #	Details
1588	2010 (Rig#24) RS-F1000 Triplex Mud Pump S/N: RS11012 C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/screw in caps, pulsation dampener, mud gauge, cent pump, bull wheel, belt guard, Cat 12V Diesel engine, air start, radiator, muffler, air volume tank, fuel tank, master skidded; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available	1594	(Rig#24) Quantity of Drill Collars S/N: Not Available C/W: 6" OD Drill Collars w/4-1/25" XH Connections (3) 8" OD Drill Collars w/ 6-¾" REG Connections, (1) Hex Kelley; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
	Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1595	(Rig#25) Lee C Moore 131 ft Cantilever Mast S/N: T3067
1589	(Rig#24) 10 ft x 40 ft Toolpusher's House S/N: Not Available C/W: office area, bedroom, bathroom area, kitchen area (gutted) skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX		C/W: 440,000 Lb Static Hook Load, Crown, Block w/ (4) 36" Cluster, 54" Fastline Sheave, Racking Board, Tong Counter Weights, Ladder, Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, spool of 1-1/8" drill line, racking board 'EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
1590	(Rig#24) Quantity of Closing Unit, Choke		Asset located in: Coleman, TX
	Manifold, Lubester, Swivel, Catwalk, Basket S/N: Not Available C/W: 5,000# choke manifold, 8'x 10' x 5' junk basket skidded w/contents, 5-station closing unit, 4-compartment lubester; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1596	(Rig#25) 26 ft 1 in x 16 ft x 47 ft Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp, Stairs, Safety Rails, Emsco type 17-1/2" rotary table, Ingeraoll Rand Air hoist, weight indicator, wireline measuring device, National deadman anchor, air volume tank, fold doghouse supports, pony subs, skidded 'EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available
1591	(Rig#24) 27-½ in Rotary Table S/N: Not Available C/W: w/ Kelly drive bushing housing, chain		Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
	guard; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1597	(Rig#25) 8 ft x 32 ft Doghouse S/N: Not Available C/W: Doghouse, 8'L Covered Porch, Lockers, Knowledge Box, Bench Storage, Cabinets; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-
1592	(Rig#24) 6 ft x 3 ft - 6 ft x 28 ft Catwalk S/N: Not Available C/W: assorted gates Usage: Not Available		LLC Usage: Not Available Notes : RITCHIE-BROS-ENERGY Asset located in : Coleman, TX
	Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1598	(Rig#25) 10 ft x 5 ft 10 in x 30 ft 300 bbl Mud Tank
1593	(Rig#24) Junk Basket S/N: Not Available C/W: air hoist, elevator links, tongs, closing unit remote panel, mud bucket, drill pipe slips, drill collar slips and misc drilling equipment; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available		S/N: Not Available C/W: VORTEX Orbital 3000M Single, Single Screen, Linear Motion Shale Shaker, mud house, skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
	Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1599	(Rig#25) Quantity of (2) 500 bbl Water Tank S/N: Not Available C/W: skidded, w/water pump, (4) cent pumps; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX

Lot #	Details	Lot #	Details	
1600	(Rig#25) 8000 gal Fuel Tank S/N: Not Available C/W: (2) transfer pumps, ladder; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1606	(Rig#25) Toolpushers House S/N: Not Available C/W: (1) office, (1) bedroom, (1) bathroom, skidded (doors locked could not access); EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
1601	(Rig#25) Skidded Parts house S/N: Not Available		Asset located in: Coleman, TX	
	C/W: shelving, lockers, bench storage, fluorescent lighting, skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	S/N: Not Available C/W: (2) WTM 4- ¼" - 6 ¾" Rotary Tongs elevator links, elevator, drill pipe slips, d collar slips, lift subs, and bit breaker; EQUIPMENT-FROM-TPI-COLEMAN-PRO	C/W: (2) WTM 4- ¼" - 6 ¾" Rotary Tongs, elevator links, elevator, drill pipe slips, drill	
1602	Parts House		Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
	S/N: Not Available C/W: flat steel, round top, shelving, bench		Asset located in: Coleman, TX	
	storage, fluorescent lighting, misc rig parts, skidded; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1608	(Rig#25) 4-Station Accumulator Closing Unit S/N: Not Available C/W: Parkersburg brake, (3) suitcases, stairs, tong and misc drilling equipment; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available	
1603	Cat (Rig#25) Containerized Generator Set S/N: Not Available C/W: Cat SR4B generator p/b Cat 6-cylinder		Notes: RITCHIE-BROS-ENERGY	
			Asset located in: Coleman, TX	
	diesel engine, generator p/b 6-cylinder diesel engine, skidded, electrical control panel, Curtis 30HP air compressor, all mud in 10'W x 40'L generator house, skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1609	S/N: Not Available C/W: Steel Deck, Ideco swivel, hex Kelly, mouse hole, hex Kelly drive bushing, jun basket w/lift subs and misc, water pum door ramp; EQUIPMENT-FROM-TPI-COL PROJECT-LLC Usage: Not Available	S/N: Not Available C/W: Steel Deck, Ideco swivel, hex Kelly, mouse hole, hex Kelly drive bushing, junk basket w/lift subs and misc, water pump, v- door ramp; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available
1604	(Rig#25) National 50-CA S/D Drawworks	1	Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	
	S/N: Not Available C/W: w/ (2) Cat D353 Diesel Engines, (2) National C-245-80 Torque Converters, 2-Engine inline compound, Quincy type air compressor, Air start, radiators, Foster makeup and breakout catheads, Levi's grooved f/1-1/8" drill line; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	1610	(Rig#25) Junk Box S/N: Not Available C/W: EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	
	Asset located in: Coleman, TX	CHOIC	E OF 2 - Lot #'s: 1611, 1612	
1605	(Rig#25) Quantity of (2) Bomco 3NB1300C		2. 2 20. 70. 1011, 1012	
	Triplex Mud Pump S/N: Not Available C/W: each with forged fluid ends w/ screw in caps, cent pump, Hydril pulsation dampeners, mud gauges, p/b (1) Cat D398, (1) Cat D399PC 12-Cylinder & 16-Cylinder Diesel engines, radiators, master skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1611	2006 Bomco 3NB1000C Triplex Mud Pump S/N: 1060917 C/W: Cat 12 Cylinder Diesel Engine, pulsation dampener, bolt on caps, mud gauge, bull wheel, skidded, Parkersburg torque converter, radiator, skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	

Lot #	Details	Lot #	Details
1612	2006 Bomco 3NB1000C Triplex Mud Pump S/N: 1060919 C/W: Cat 12 Cylinder Diesel Engine, bolt on caps, pulsation dampener, mud gauge, cent pump, manifold, torque converter, radiator, air and fuel tanks, master skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1619 1620	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 378088 C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC
1613	2008 NLB Skid Mounted Triplex Test Pump S/N: P4012901 C/W: Triplex Cummins N14 6 Cylinder Diesel Engine, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: RITCHIE-BROS-ENERGY; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE		Usage: 8,391 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA 2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 380841ULQB78 C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-
1614	DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX Pai PAI70HP3250 Mud Pump S/N: 1025666	_	FROM-GASCO-DRILLING-INC Usage: 8,256 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine Usage: 168 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	1621 2007 Ingersoll Rand XHP1170 11 Mounted Air Compressor S/N: 378089 C/W: 365 psi Working Pressure, C	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor
1615	Tulsa Rig Iron Mud Pump S/N: TT150-52 C/W: Triplex 2014 US EPA Label, Cummins 6 Cylinder Diesel Engine Usage: 642 Hr		FROM-GASCO-DRILLING-INC Usage: 9,385 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	1622	2007 Ingersoll Rand XHP1170 Skid-Mounted Air Compressor S(N): 380840111 OR78
1616	1998 Triplex Mud Pump S/N: 160 TP 6L C/W: 4 in Intake, 3 in Discharge, Mud Pump, Cat 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available		C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 11,640 Hr Notes: RITCHIE-BROS-ENERGY
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	сноісі	E OF 2 - Lot #'s: 1623, 1624
1617	Wheatley HP-250H Skid Mounted Triplex Test Pump S/N: Not Available C/W: 1 in Intake, 1 in Discharge, Triplex Detroit 8W-71 8 Cylinder Diesel Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: RITCHIE-BROS-ENERGY; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	1623	2004 Sullair 1170 Skid-Mounted Air Compressor S/N: 006-04011489 C/W: Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1618	Asset located in: Lake Worth, TX 2012 Keystone Skid-Mounted Booster Air Compressor S/N: MCW02262 C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 1,899 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Compressor S/N: 006-04011490 C/W: 365 psi Working Pressure, Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
CHOIC	CHOICE OF 3 - Lot #'s: 1625, 1626, 1627		Quantity of Approximately 12114 ft of 3.5 in Drill Pipe S/N: Not Available
1625	2008 Ariel JGQ/2 Skid-Mounted Booster Air Compressor		C/W: Approximately 12114 ft; EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available
	S/N: KB102 C/W: Cat C7 6 Cylinder 250 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC		Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	Usage: 4,357 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1632	Quantity of Approximately 5767 ft of 4 in Drill Pipe S/N: Not Available
1626	2003 Ariel Skid-Mounted Booster Air Compressor		C/W: Approximately 5767 ft; EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
	S/N: KB-10 C/W: Cat 3126 6 Cylinder 309 hp 7.2 L Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-		Asset located in: Cedar Bluff, VA
	INC Usage: 3,541 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		E OF 10 - Lot #'s: 1633, 1634, 1635, 1636, 1637, 639, 1640, 1641, 1642
1627	2003 Ariel Skid-Mounted Booster Air Compressor S/N: BEJ02783 C/W: Cat 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 906 Hr Notes: RITCHIE-BROS-ENERGY	1633	Quantity of (7) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	Asset located in: Cedar Bluff, VA	1634	Quantity of (5) 4.5 in Drill Collars S/N: Not Available
1628	Quantity of (152 joints)(4,712') 4-1/2 in Range 2 Drill Pipe S/N: Not Available C/W: (4,712 ft), w/ 4-1/2" FH conns, w/(6) 3		C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	sets of 40"H x 30'L triangular pipe racks; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1635 Quantity of S/N: Not A' C/W: EQUII Usage: Not	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
1629	Quantity of (144) 3-1/2 in Range 2 (4,464') Drill Pipe	1636	Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars
	S.N: Not Available C/W: (4,464 ft), w/3-1/2"IF conns, HB, w/(4) (2) sets of 40"H x 30'L trainagular pipe racks; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1637	Quantity of (5) 4.5 in Drill Collars S/N: Not Available
S/N: Not Av C/W: Appro FROM-GAS Usage: Not Notes : RITC	Quantity of Approximately 6353 ft 4 in Drill Pipe S/N: Not Available C/W: Approximately 6353 ft, EQUIPMENT- FROM-GASCO-DRILLING-INC		C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1638	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
1639	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1646	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
1640	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	1647	RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC
1641	Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1648	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars
1642	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	_ 1048	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	E OF 10 - Lot #'s: 1643, 1644, 1645, 1646, 1647, 649, 1650, 1651, 1652	1649	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC
1643	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1650	Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC
1644	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	1651	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC
1645	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details	
1652	Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	1660	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA E OF 10 - Lot #'s: 1653, 1654, 1655, 1656, 1657,	1661	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
	659, 1660, 1661, 1662		Asset located in: Cedar Bluff, VA	
1653	Quantity of (4) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1662	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
1654	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		E OF 10 - Lot #'s: 1663, 1664, 1665, 1666, 1667, 669, 1670, 1671, 1672	
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1663	Quantity of (3) 6 in Drill Collars S/N: Not Available	
1655	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1664	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC	
1656	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1665	Quantity of (3) 6 in Drill Collars S/N: Not Available	
1657	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	Notes: RITCHIE-BROS-ENERGY
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1666 Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DI Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA 1667 Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DI Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	S/N: Not Available	
1658	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		S/N: Not Available	
1659	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Notes: RITCHIE-BROS-ENERGY	

Lot #	Details	Lot #	Details
1668	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1676	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1669	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1677	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1670	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1678	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1671	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1679	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1672	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1680	Quantity of (2) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	CHOICE OF 9 - Lot #'s: 1673, 1674, 1675, 1676, 1677, 1678, 1679, 1680, 1681		Quantity of (2) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		E OF 8 - Lot #'s: 1682, 1683, 1684, 1685, 1686, 688, 1689
1674	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1682	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1675	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1683	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
1684	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1691	2014 Kenworth T800 8x4 Cab and Chassis S/N: 1NKDX4EXXEJ404952 C/W: Cummins ISX15 15.0 L 525 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20872.4 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000
1685	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Ib Rears, 71340 lb GVWR, Air Ride Cab, 11R24. 5 Front Tires, 11R24.5 Rear Tires, Hendrickson Primaax EX Air Ride Suspension, 229 in Wheelbase, 103 in Cab to Axle, 286 in Cab to End of Frame, Pintle Hitch Usage: 514,573 Mi Notes: THIS UNIT RUNS BUT MAY HAVE
1686	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN
1687	Quantity of (1) 7.5 in Drill Collars S/N: Not Available		ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD
	C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC		Asset located in: Lake Worth, TX
	Usage: Not Available Notes: RITCHIE-BROS-ENERGY	1692	2018 Mack GU713 6x4 Cab and Chassis
	Asset located in: Cedar Bluff, VA		S/N: 1M1AX07YXJM038681 C/W: Mack MP8 6 Cylinder 12.7 L Diesel
1688	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Engine, Requires Diesel Exhaust Fluid, 189 Engine hrs, Engine Brake, Mack Automated Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Double Frame, Rubber Suspension, 206 in Wheelbase Usage: 463,795 Mi Asset located in: Lake Worth, TX
1689	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA Drill Collars	1692A	2011 International 4400 6x4 Cab and Chassis S/N: 1HTMSAZR3BH340351 C/W: International MaxxForce 9 6 Cylinder 9.3 L Diesel Engine, Engine Brake, Allison Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires,
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes : RITCHIE-BROS-ENERGY		Air Ride Suspension, 271 in Wheelbase, 208 in Cab to Axle, 315 in Cab to End of Frame Usage: 198,057 Mi Asset located in: Humble, TX
	Asset located in: Cedar Bluff, VA	1693	2011 Kenworth T370 4x2 Cab and Chassis S/N: 2NKHHN7X2BM296249 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8574 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Spring Suspension, 229 in Wheelbase, 164 in Cab to Axle, 216 in Cab to End of Frame Usage: 163,110 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1694	2020 Freightliner M2 106 4x2 Cab and Chassis S/N: 3ALACWFC1LDMA1987 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller EDCO-6F107A Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 204 in Wheelbase, 140 in Cab to Axle, 212 in Cab to End of Frame Usage: 221,672 Mi Asset located in: Humble, TX	1699 1700	2018 Hino 268 4x2 Cab and Chassis S/N: 5PVNJ8JV8J4S68672 C/W: J08E 6 Cylinder 7.6 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6352 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 205 in Cab to Axle, 319 in Cab to End of Frame Usage: 234,436 Mi Asset located in: Lake Worth, TX
1695	2019 International 4300 4x2 Cab and Chassis S/N: 3HAMMMN5KL559225 C/W: Cummins B6.7 260 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12755 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 254 in Wheelbase, 186 in Cab to Axle, 278 in Cab to End of Frame Usage: 193,556 Mi		S/N: 1FVACXDT6EHFY9046 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 7129 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 270 in Wheelbase, 204 in Cab to Axle, 300 in Cab to End of Frame Usage: 200,956 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1701	2014 Hino 268 4x2 Cab and Chassis
1696	2018 International 8600 4x2 Cab and Chassis S/N: 3HTHWSNNXJN626104 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 370 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9390 Engine hrs, Eaton Fuller Automated Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 12R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 264 in Wheelbase, 204 in Cab to Axle, 300 in Cab to End of Frame Usage: 393,327 Mi Asset located in: Lake Worth, TX		S/N: 5PVNJ8JL5E4S51770 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, 102 in Cab to Axle, 162 in Cab to End of Frame Usage: 263,506 Mi Asset located in: Lake Worth, TX
		1702	2013 Peterbilt 337 4x2 Cab and Chassis S/N: 2NP2HN7X2DM190208 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel
1697	2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV9J4S57961 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10275 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Spring Suspension, 272 in Wheelbase, 206 in Cab to Axle, 283 in Cab to End of Frame Usage: 284,232 Mi		Engine, Requires Diesel Exhaust Fluid, 10775 Engine hrs, Allison 3500 Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, Dana Drive Axles, 5.29:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Double Frame, Reyco Spring Suspension, 238 in Wheelbase, 168 in Cab to Axle, 222 in Cab to End of Frame Usage: 204,502 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	1703A	2012 International 4300 4x2 Cab and Chassis
1698	2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV0J4S58139 C/W: Hino J08E-VB 6 Cylinder Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9483 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 204 in Cab to Axle, 284 in Cab to End of Frame Usage: 301,522 Mi Asset located in: Lake Worth, TX		S/N: 3HAMMAAN5CL562842 C/W: 6 Cylinder Diesel Engine, 6570 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 23000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 255 in Wheelbase, 188 in Cab to Axle, 298 in Cab to End of Frame Usage: 205,283 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
1704A	2018 Isuzu NPR-XD 4x2 COE Cab and Chassis S/N: JALC4W161J7K00299 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, 159 in Cab to Axle, 204 in Cab to End of Frame Usage: 316,607 Mi Asset located in: Humble, TX	1709	2016 Ram 5500 4x2 Cab and Chassis S/N: 3C7WRMDL1GG283996 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 255/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 204 in Wheelbase, 120 in Cab to Axle, 173 in Cab to End of Frame Usage: 185,092 Mi Asset located in: Lake Worth, TX	
1706	2019 Ford F-550 XL 4x4 Extended Cab Cab and Chassis S/N: 1FD0X5HT1KEF25139 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 134 in Cab to End of Frame Usage: Not Available Asset located in: Midland, TX	1709A	2012 Ford F-550 4x2 Extended Cab Cab and Chassis S/N: 1FD0X5GT5CEC83751 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 183 in Wheelbase, 80 in Cab to Axle, 130 in Cab to End of Frame Usage: 204,360 Mi Asset located in: Lake Worth, TX	
CHOICE	E OF 2 - Lot #'s: 1707, 1708	1711	2009 Peterbilt 335 4x2 Cab and Chassis S/N: 2NPLHN7X19M788656 C/W: Paccar 6 Cylinder Diesel Engine, Engine	
1707	2017 Ford F-550 4x4 Extended Cab Cab and Chassis S/N: 1FD0X5HT8HEE59326 C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 86 in Cab to Axle, 128 in Cab to End of Frame Usage: 141,292 Mi Asset located in: Lake Worth, TX		Brake, Allison 3500 Automatic Transmission, 10000 lb Front Axle, 23000 lb Rears, Dana S23-170 Drive Axles, 6.14:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, 134 in Cab to Axle, 171 in Cab to End of Frame Usage: 102,359 Mi Asset located in: Humble, TX	
		1713	2007 Hino 258 4x2 Cab and Chassis S/N: 5PVND8JT672S50164 C/W: Hino 6 Cylinder Diesel 220 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust	
1708	2017 Ford F-550 4x2 Extended Cab Cab and Chassis S/N: 1FDOX5GT0HEE87879 C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8271 Engine hrs, Automatic Transmission, 7000 lb Front Axle,		;	Fluid, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 255 /70R22.5, Spring Suspension, 219 in Wheelbase, 150 in Cab to Axle, 183 in Cab to End of Frame Usage: 329,692 Mi Asset located in: Lake Worth, TX
	14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 134 in Cab to End of Frame Usage: 204,811 Mi Asset located in: Lake Worth, TX		S/N: 2NPLHD6X45M857023 C/W: Cat C7 6 Cylinder 7.2 L Diesel Engine, 2006 US EPA Label, 15489	C/W: Cat C7 6 Cylinder 7.2 L Diesel 250 hp Engine, 2006 US EPA Label, 15489 Engine hrs, Allison Automatic Transmission, 10000 lb
1708A	2017 Ford F-550 XL 4x2 Extended Cab Cab and Chassis S/N: 1FD0X5GT9HEC48136 C/W: V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 65000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 122 in Cab to End of Frame Usage: 131,502 Mi Asset located in: Lake Worth, TX		Front Axle, 20000 lb Rears, 4.88:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22 5, Low Air Leaf Suspension, 191 in Wheelbase, PTO, 120 in Cab to Axle, 195 in Cab to End of Frame Usage: 459,210 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
1715A	2007 GMC C7500 4x2 Cab and Chassis S/N: 1GDK7C1C67F900371 C/W: Cat C7 6 Cylinder 7.2 L Diesel 210 hp Engine, 2006 US EPA Label, Automatic Transmission, 8001 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, 192 in Cab to Axle, 228 in Cab to End of Frame Usage: 226,533 Mi Asset located in: Lake Worth, TX	1721	2003 Mack RD688S 6x4 Flatbed Truck S/N: 1M2P267C93M065482 C/W: Mack E7 6 Cylinder Diesel 350 hp Engine, 2002 US EPA Label, 28682 Engine hrs, Eaton Fuller 8LL Manual Transmission, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Camelback Spring Suspension, 252 in Wheelbase, PTO, 20 ft 6 in x 92 in Bed Usage: Not Available Asset located in: Lake Worth, TX
1716	1998 Peterbilt 330 4x2 Cab and Chassis S/N: 3BPNHD7X1WF459167 C/W: Cat 3126B 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 274 in Wheelbase, PTO, 200 in Cab to Axle, 329 in Cab to End of Frame Usage: 912,630 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE	-1721A	2018 International 4300 4x2 Flatbed Truck S/N: 1HTMMMMMXJH632780 C/W: Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11497 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 10R22.5, Spring Suspension, 181 in Wheelbase, 14 ft 5 in x 96 in Bed Usage: 148,134 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1722	2016 Freightliner M2 106 4x2 Flatbed Truck
1718	1990 International 4600 4x2 Cab and Chassis S/N: 1HTSAZRN0MH332118 C/W: International 7.3 L Diesel 155 hp Engine, Steel, 255/70R22.5, Double Frame, Spring Suspension, 152 in Wheelbase, 84 in Cab to Axle, 147 in Cab to End of Frame Usage: 218,680 Mi Asset located in: Lake Worth, TX		S/N: 1FVACXDT0GHHR9676 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 13474 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.56:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 96 in Bed, Aluminum Frame, Liftgate Usage: 206,090 Mi
1719	2019 Freightliner M2 106 6x4 Flatbed Truck S/N: 3ALHCYFE7KDKU9146 C/W: Cummins L9 6 Cylinder 8.9 L Diesel 350	1723	Asset located in: Lake Worth, TX 2014 Freightliner M2 106 6x4 Flatbed Truck
	hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6627 Engine hrs, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.33:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 28 ft x 102 in Bed, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 288,102 Mi		S/N: 1FVHCYCY5EHFV7934 C/W: Cummins ISL9 6 Cylinder Diesel 350 hp Engine, Requires Diesel Exhaust Fluid, 9346 Engine hrs, Allison Automatic Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 274 in Wheelbase, 24 ft x 91 in Bed, Forklift Mount Kit Usage: 158,702 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	1724	2019 Isuzu NPR HD 4x2 COE Crew Cab Flatbed
1720	2014 International 7600 6x4 Flatbed Truck S/N: 1HTGSSJT6EH786752 C/W: International 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Ride Suspension, 261 in Wheelbase, 20 ft 10 in x 97 in Bed Usage: 323,203 Mi Asset located in: Lake Worth, TX		Truck S/N: 54DC4J1B6KS801218 C/W: 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225/70R19.5, Spring Suspension, 181 in Wheelbase, 19 ft x 93 in Bed, Dovetail, Manual Ramps Usage: 138,503 Mi Asset located in: Lake Worth, TX

	Details	Lot #	Details
1724B	2007 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAM17H382700 C/W: International DT466 6 Cylinder 7.6 L Diesel 210 hp Engine, 2006 US EPA Label, 7485 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, 18 ft x 92 in Bed, Poly Tank, MultiQuip Concrete Mixer, Usage: 238,996 Mi Asset located in: Lake Worth, TX	CHOIC	2009 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF65C79V065767 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2008 US EPA Label, 2379 Engine hrs, Eaton Fuller Automated Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 194 in
1725	2006 Hino 268 4x2 Flatbed Truck S/N: 5PVNE8JT462S12363 C/W: Hino 6 Cylinder Diesel Engine, Automatic		Wheelbase, 13 ft x 94 in Bed, Winch Usage: 14,420 Mi Asset located in : Lake Worth, TX
	Transmission, 11R22.5, Spring Suspension, 245 in Wheelbase, 23 ft 8 in x 94 in Bed Usage: 672,876 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	S/N: 3FRNF65H89V10965 C/W: Cummins 6 Cylinder Automatic Transmission, 11R22.5 Front Tires, 11R2	2009 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF65H89V109657 C/W: Cummins 6 Cylinder Diesel Engine, Automatic Transmission, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 195 in Wheelbase, 8 ft x 96
1725B	2007 International 4400 4x2 Flatbed Truck S/N: 1HTMRAAL97H464165]	in Bed Usage: 74,757 Mi Asset located in : Lake Worth, TX
	C/W: 6 Cylinder Diesel Engine, Allison Automatic Transmission, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 207 in Wheelbase, 14 ft x 90 in Bed Usage: 215,347 Mi	CHOICE OF 2 - Lot #'s: 1729, 1730	
	Asset located in: Humble, TX	1729	2001 Stewart and Stevenson M1078 4x4
1725C	1999 Volvo VN 4x2 Flatbed Truck S/N: 4VG7DBUF5XN768395 C/W: Cummins ISM 6 Cylinder 10.8 L Ultra Low Sulfur Diesel 330 hp Engine, 1998 US EPA Label, Eaton Fuller Automatic Transmission, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Spring Suspension, 237 in Wheelbase, 10 ft 4 in x 96 in Bed Usage: 834,602 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV		Flatbed Truck S/N: 14619G C/W: cat 3126 6 Cylinder 7.2 L Diesel 246 hp Engine, 1999 US EPA Label, Automatic Transmission, 395/85R20, Spring Suspension, 154 in Wheelbase, 12 ft 6 in x 96 in Bed, Diesel, Allison Auto, Central Tire Inflation; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 196 Mi Notes:; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	PRIOR TO BIDDING	1730	1998 Stewart and Stevenson M1079 4x4 COE
1726	Asset located in: Lake Worth, TX 2019 Ford F-750 4x2 Flatbed Truck	-	Flatbed Truck S/N: V011285EDKG
1/20	S/N: 1FDXF7DE5KDF11884 C/W: 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 260 in Wheelbase, 18 ft x 92 in Bed, Pintle Hitch Usage: 34,747 Mi	C/W: Cat 6 Cylinder Diesel Eng Automatic Transmission, 395/ Suspension, 154 in Wheelbase in Bed, Pintle Hitch, EQUIPMEN WATKINS-CONSTRUCTION Usage: 4,949 Mi Notes: ; PLEASE SEE A PERSO	C/W: Cat 6 Cylinder Diesel Engine, Allison Automatic Transmission, 395/85R20, Spring Suspension, 154 in Wheelbase, 12 ft 6 in x 94 in Bed, Pintle Hitch, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 4,949 Mi Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
сноіс 1731	E OF 2 - Lot #'s: 1731, 1732 1998 Stewart and Stevenson M1078 4x4 COE Flatbed Truck S/N: AT9310EDEG C/W: Diesel Engine, Automatic Transmission, 395/85R20, Spring Suspension, 152 in	1738	2022 Ford F-550 XL 4x4 Flatbed Truck S/N: 1FDUF5HT4NEE52440 C/W: power stroke V8 6.7 L Diesel Engine, 2022 US EPA Label, 1589 Engine hrs, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, 12 ft x 96 in Bed, Aluminum Frame Usage: 46,064 Mi Asset located in: Lake Worth, TX
	Wheelbase, 12 ft 7 in x 96 in Bed, Diesel, Allison Automatic, Central Tire Inflation; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 7,226 Mi Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	1739 2019 Ford F-550 XL 4x4 Crew Garden Truck S/N: 1FD0W5HT9KED42817 C/W: V8 6.7 L Diesel Engine, 20 Label, Requires Diesel Exhaust Automatic Transmission, 7000 14706 lb Rears, 19500 lb GVW Front Tires, 225/70R19.5 Rear Suspension, 204 in Wheelbase in Bed, Fuel Tank /w Pump, EQ A-PRIMORIS-SERVICES-CORP- Usage: 141,518 Mi	2019 Ford F-550 XL 4x4 Crew Cab Flatbed Truck
1732	1995 Stewart and Stevenson M1078 COE 4x4 Flatbed Truck S/N: AT0761BEC C/W: Allison Automatic Transmission, 395 /85R20, 155 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch, Diesel, Allison Auto, Central Tire		Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 204 in Wheelbase, 11 ft 3 in x 98 in Bed, Fuel Tank /w Pump, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY
	Inflation ; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,055 Mi	СНОІС	E OF 2 - Lot #'s: 1740, 1741
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	1740	2019 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT5KEF71138
	E OF 3 - Lot #'s: 1734, 1735, 1736		C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 206 in Wheelbase, 9 ft 6 in
1734	2006 GMC 4500 4x2 Flatbed Truck S/N: 1GDE4C12X6F431782 C/W: V8 6.6 L Diesel 300 hp Engine, 2006 US EPA Label, Automatic Transmission, 225		x 56 in Bed, Pintle Hitch Usage: 199,717 Mi Asset located in : Lake Worth, TX
	/70R19.5, Spring Suspension, 179 in Wheelbase, 14 ft 4 in x 93 in Bed Usage: 214,436 Mi Asset located in: Lake Worth, TX	1741	2019 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT9KEF71160 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US
1735	2006 GMC 4500 4x2 Flatbed Truck S/N: 1GDE4C1256F431754 C/W: Chevy V8 6.6 L Diesel Engine, US EPA Label, Allison 4 Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 177 in Wheelbase, 14 ft x 92 in Bed, Receiver	EPA Label, Requires Diesel Exhaus Automatic Transmission, 7000 lb 14706 lb Rears, 19500 lb GVWR, 2 Spring Suspension, 204 in Wheelb in x 96 in Bed, Pintle Hitch, EQUIPI	EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 204 in Wheelbase, 11 ft 4 in x 96 in Bed, Pintle Hitch, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available
	Usage: 182,782 Mi Asset located in: Lake Worth, TX	1742	2018 Ford F-550 XL 4x4 Crew Cab Flatbed Truck
1736	2006 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBE4C1226F434247 C/W: V8 6.6 L Diesel Engine, Allison Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225/70R19.5, Spring Suspension, 190 in Wheelbase, 13 ft x 96 in Bed, Hitch Receiver Usage: 179,635 Mi Asset located in: Lake Worth, TX		S/N: 1FD0W5HT6JEC24738 C/W: 6 Cylinder 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 203 in Wheelbase, 10 ft 6 in x 89 in Bed, Fuel Tank Usage: 160,056 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
CHOIC	CHOICE OF 2 - Lot #'s: 1743, 1744		2016 Ford F-550 XL 4x4 Extended Cab Flatbed Truck S/N: 1FD0X5HT8GEC75339	
1743	2018 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL1JG157387 C/W: Cummins ISB6.7 325 6.7 L 325 hp Engine, 2018 US EPA Label, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500.0 lb GVWR, 225/70R19. 5, Spring Suspension, 197 in Wheelbase, 12 ft x 96 in Bed, Fuel Tank /w Pump, Pintle Hitch Usage: 81,063 Mi Asset located in: Lake Worth, TX	4754	C/W: 6.7 L 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8438 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft x 91 in Bed, Fuel Tank Usage: 191,492 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	
1744	2018 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL8JG207251 C/W: Cummins 6.7 L Diesel Engine, 6818 Engine hrs, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 194 in Wheelbase Usage: 114,766 Mi Asset located in: Lake Worth, TX	-1751 -	2016 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL3GG329797 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Bunk Beds, 225/70R19. 5, Spring Suspension, 198 in Wheelbase, 12 ft x 55 in Bed, Pintle Hitch Usage: 158,301 Mi Asset located in: Lake Worth, TX	
1746	2017 Ford F-550 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT4HEC85077 C/W: V8 6.7 L 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 187 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch Usage: 147,936 Mi Asset located in: Lake Worth, TX	1753 2015 Ford F-550 XL 4x2 Flatbed To S/N: 1FDUF5GT2FEC27629 C/W: Ford Power Stroke 6.7 L Dies Engine, 2015 US EPA Label, Require Exhaust Fluid, Automatic Transmis Ib Front Axle, 14706 Ib Rears, 1950 225/70R19.5, Spring Suspension, Wheelbase, 11 ft 6 in x 96 in Bed, Fifth wheel ball, EQUIPMENT-FROI PRIMORIS-SERVICES-CORP-COMF Usage: 150,132 Mi Notes: Asset located in: Lake Worth, TX 1754 2013 Ford F-550 XL 4x4 Crew Cab Truck S/N: 1FD0W5HT9DEB58125 C/W: V8 6.7 L Diesel 300 hp Engin EPA Label, Requires Diesel Exhaus Automatic Transmission, 7000 Ib I 14706 Ib Rears, 19500 Ib GVWR, 2 Spring Suspension, 200 in Wheelb in x 88 in Bed Usage: 301,436 Mi Asset located in: Midland, TX 1757 2013 Ford F-450 4x2 Flatbed Truck S/N: 1FDUF4GY5DEA18226 C/W: Ford V10 6.8 L Gasoline Enging EPA Label, 5-Speed Automatic Trafe 6000 Ib Front Axle, 12000 Ib Rears GVWR, 225/70R19.5 Front Tires, 2 Rear Tires, Spring Suspension, 201 Wheelbase, 17 ft 5 in x 96 in Bed, I Usage: 204,057 Mi	1753 2015 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT2FEC27629 C/W: Ford Power Stroke 6.7 L Diesel 300 h Engine, 2015 US EPA Label, Requires Diese Exhaust Fluid, Automatic Transmission, 65 lb Front Axle, 14706 lb Rears, 19500 lb GV 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft 6 in x 96 in Bed, Receiver Fifth wheel ball, EQUIPMENT-FROM-A-	2015 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT2FEC27629 C/W: Ford Power Stroke 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft 6 in x 96 in Bed, Receiver, Fifth wheel ball, EQUIPMENT-FROM-A-
1747	2017 Ford F-450 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W4HY8HEC86836		Usage: 150,132 Mi Notes : .	
	C/W: 6 Cylinder 6.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 205 in Wheelbase, 11 ft 6 in x 60 in Bed, Fuel Tank, Pintle Hitch Usage: 45,366 Mi Asset located in: Lake Worth, TX		1754	2013 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT9DEB58125 C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5,
1749	2016 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT2GEB95778		Usage: 301,436 Mi	
	C/W: Power Stroke V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft 6 in x 96 in Bed, Liftgate, Rear View Camera; EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 120,695 Mi Asset located in: Lake Worth, TX		C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, 5-Speed Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 201 in Wheelbase, 17 ft 5 in x 96 in Bed, Liftgate	

Lot #	Details	Lot #	Details
1758	2013 Ford F-450 XL 4x2 Flatbed Truck S/N: 1FDUF4GT4DEB86573 C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft x 94 in Bed Usage: 201,329 Mi Asset located in: Lake Worth, TX	1764	764 2022 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3GN1NEC44542 C/W: Ford V8 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 24 /75R17, 9 ft x 93 in Bed Usage: 111,959 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
1759	2011 Ford F-450 XL 4x4 Crew Cab Flatbed Truck		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	S/N: 1FD0W4HT0BEC98605 C/W: Ford Power Stroke V8 6.7 L Ultra Low Sulfur Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, 8 ft 9 in x 94 in Bed Usage: 290,111 Mi Asset located in: Lake Worth, TX	1765 1767	Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1765, 1766, 1767 2020 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3G6XLEE32269 C/W: V8 6.2 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4700 lb Front
1760	2003 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBC4E1E93F503492 C/W: V8 8.1 L Gasoline Engine, Automatic Transmission, 6000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 13 ft 4 in x 97 in Bed Usage: 281,996 Mi		Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 90 in Bed Usage: 121,378 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
1762	2021 GMC Sierra 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GD49SE76MF148113 C/W: V8 6.6 L Gasoline Engine, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 182 in Wheelbase, 9 ft x 96 in Bed, Fuel Tank /w Pump, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 116,066 Mi		2020 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT5LED87360 C/W: V8 6.7 L Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 245:75R17, Spring Suspension, 181 in Wheelbase, 108 m x 89 in Bed Usage: 115,425 Mi Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT3KEF22298 C/W: 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle,
1763	2021 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT2MED56469 C/W: Ford 6.7 L Diesel Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 3975 Engine hrs, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 179 in Wheelbase, 9 ft 2 in x 92 in Bed Usage: 100,601 Mi Asset located in: Lake Worth, TX		10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 181 in Wheelbase, 9 ft 6 in x 98 in Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1768	2019 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3G63KEC30873 C/W: V8 6.2 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase, 9 ft 5 in x 90 in Bed Usage: 93,217 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	1774	2018 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT5JEC95579 C/W: V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 8284 Engine hrs, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 3 in x 98 in Bed Usage: 221,150 Mi Asset located in: Humble, TX
	PROCESS TITLE Asset located in: Lake Worth, TX	1775	2017 Ford F-350 XL 4x4 Crew Cab Flatbed
CHOICE 1769	E OF 3 - Lot #'s: 1769, 1770, 1771 2019 Ford F-350 4x4 Crew Cab Flatbed Truck		Truck S/N: 1FD8W3H6XHEE85592 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 162,002 Mi Asset located in: Lake Worth, TX
	S/N: 1FT8W3DT6KEG85635 C/W: Ford Power Stroke 6.7 L Diesel Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5246 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 9900 lb Rears, Ford-Factory Drive Axles, 14000 lb GVWR, Aluminum Wheels, 245/75R17, Ford- Factory Spring Suspension, 178 in Wheelbase, 9 ft x 98 in Bed, Receiver hitch, Fifth wheel ball Usage: 194,430 Mi Asset located in: Midland, TX	1776	2017 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3H62HEE73498 C/W: Ford V8 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 5200 lb Front Axle, 10040 lb Rears, 14000.0 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 92 in Bed, Pintle Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY
1770	2019 Ford F-350 4x4 Crew Cab Flatbed Truck		Usage: 119,438 Mi Asset located in: Lake Worth, TX
	S/N: 1FD8W3HT5KEE24230 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75/17, Spring Suspension, 180 in Wheelbase, 9 ft x 89 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 134,504 Mi Asset located in: Lake Worth, TX	1777	2016 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT6GEA98185 C/W: Ford V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, 11342 Engine hrs, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 265/70R17, Spring Suspension, 176 in Wheelbase, 9 ft 4 in x 92 in Bed
1771	2019 Ford F-350 4x4 Crew Cab Flatbed Truck		Usage: 279,994 Mi Asset located in: Lake Worth, TX
	S/N: 1FD8W3HT6KEG06521 Usage: Not Available Asset located in : Midland, TX	CHOIC	E OF 2 - Lot #'s: 1778, 1779
1773	2019 Ford F-550 XL 4x2 Flatbed Truck		_ 5 5
	S/N: 1FDUF5GT6KDA03912 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 5452 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 245/70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft 6 in x 96 in Bed Usage: 176,902 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1778	2018 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL7JG325302 C/W: Cumins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 640 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80/17, Spring Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in Bed Usage: 90,276 Mi Asset located in: Lake Worth, TX

1 - 1 "	Davile	l	Parette.
Lot #	Details	Lot #	Details
1779	2017 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL9HG759022 C/W: 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 173 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 382,795 Mi Asset located in: Midland, TX	1783	2017 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY0HF162509 C/W: V8 6.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 12354 Engine hrs, Automatic Transmission, 5600 lb GVWR, 255/80R17, Spring Suspension, 172 in Wheelbase, 9 ft 4 in x 86 in Bed Usage: 113,385 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
1779A	2017 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL9HG684368		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: Cummins V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle,	1783A	2014 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck
	9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 171 in Wheelbase, 9 ft 6 in x 90 in Bed Usage: 343,489 Mi Asset located in: Lake Worth, TX	1784	S/N: 1GB4KZCGXEF154345 C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 245/75R17 Front Tires, 235/80R17 Rear Tires, Spring Suspension, 171 in Wheelbase, 9 ft 4 in x 92 in Bed
1780	2019 GMC Sierra 3500HD 4x4 Crew Cab Flatbed Truck		Usage: 244,091 Mi Asset located in: Lake Worth, TX
	S/N: 1GD42TCG9KF236339 C/W: V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 9375 lb Rears, 13025 lb GVWR, 265 /70R17, Spring Suspension, 168 in Wheelbase, 8 ft x 92 in Bed, Fuel Tank Usage: 112,708 Mi Notes: NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX		2012 Dodge Ram 3500HD 4x2 Crew Cab Flatbed Truck S/N: 3C7WDSCLXCG193793 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 17228 Engine hrs, Automatic Transmission, 5500 lb Front Axle, 9350 lb Rears, 13000 lb GVWR, 265 /79R17 Front Tires, 265/70R17 Rear Tires, Spring Suspension, 171 in Wheelbase, 9 ft x 93
1780A	2019 GMC 3500HD 4x4 Crew Cab Flatbed Truck		in Bed, Receiver, Fifth wheel ball Usage: 329,146 Mi
	S/N: 1GB4KVCG5KF127400 C/W: V8 6.0 L Gasoline Engine, 11709 Engine		Asset located in: Lake Worth, TX
	hrs, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235 /80R17, Spring Suspension, 171 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 178,678 Mi Asset located in: Lake Worth, TX	1785	2011 Chevrolet 3500 HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4K1CL3BF151507 C/W: General Motors V8 6.6 L Diesel Engine, 2011 US EPA Label, Automatic Transmission, 245/70R17, Spring Suspension, 175 in Wheelbase, 8 ft 6 in x 84 in Bed, Better Built 50
СНОІСЕ	E OF 2 - Lot #'s: 1782, 1783		gallons Fuel Tank Usage: 264,873 Mi
1782	2017 Chevrolet Silverado 3500HD 4x4 Crew		Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; Asset located in: Lake Worth, TX
	Cab Flatbed Truck	17051	,
	S/N: 1GB4KYCY3HF162424 C/W: V8 6.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 8853 Engine hrs, Exhaust Brake, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 172 in Wheelbase, 9 ft 4 in x 92 in Bed Usage: 113,083 Mi	1785A	2019 Ram 2500 4x2 Crew Cab Flatbed Truck S/N: 3C6UR4HJ5KG590150 C/W: V8 6.4 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 5500 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 275 /70R18, Spring Suspension, 170 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 158,739 Mi
	Asset located in: Lake Worth, TX	I	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth TX

Lot #	Details	Lot #	Details
1786	2017 Ford F-250 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD7W2B67HED35955 C/W: Ford V8 6.2 L Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 6340 lb Rears, 10000.0 lb GVWR, 285/70R17, Spring Suspension, 176 in Wheelbase, 8 ft 6 in x 80 in Bed, Fuel Tank /w Pump Usage: 105,808 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	1790 	2015 Chevrolet Silverado 1500 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYC84FF512267 C/W: V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 174 in Wheelbase, 9 ft 6 in x 87 in Bed Usage: 117,117 Mi Asset located in: Lake Worth, TX 1971 Ford F100 4x2 Flatbed Truck
1787	2015 Ford F-250 XL 4x2 Crew Cab Flatbed Truck S/N: 1FT7W2AT3FEB68857 C/W: V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 265/70R17, Spring Suspension, 171 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 288,298 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: F10YRM02564 C/W: V8 Gasoline Engine, Automatic Transmission, 4500 lb GVWR, 7.00-15, Spring Suspension, 131 in Wheelbase, 8 ft x 78 in Bed, Pintle Hitch, Goodall Start-All Jumpstart Pack, Ingersoll-Rand T30 Air Compressor; EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: CANNOT VERIFY ODOMETER READING- VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE;TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX
1788 1788A	2011 Ford F-250 4x4 Crew Cab Flatbed Truck S/N: 1FT7W2B6XBED03559 C/W: Gasoline Engine, 2011 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 154 in Wheelbase, 7 ft x 84 in Bed Usage: Not Available Asset located in: Lake Worth, TX	1794	2012 Peterbilt 388 6x4 Sleeper Car Carrier Truck S/N: 1NPWD49X2CD134987 C/W: Cummins ISX15 6 Cylinder 15.0 L 525 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 44842 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 58 in Flat Top Sleeper Cab, Aluminum Wheels, 295/60R22.5 Front Tires, 255/70R22.5 Rear Tires, Low Low Air Leaf Air Ride Suspension, 264 in Wheelbase, PTO,
	S/N: 1FTBF2A67BEC16567 C/W: Ford V8 6.2 L Gasoline Engine, US EPA Label, Automatic Transmission, 3950 lb Front Axle, 9800 lb Rears, 9800 lb GVWR, LT245 /75R17, Spring Suspension, 136 in Wheelbase, 8 ft 3 in x 79 in Bed, Receiver, Fifth wheel ball Usage: 318,291 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Hydraulic Lift, Soft Tie Downs, SOLD WITH - Cottrell CX-11HCSI T/A, Trailer S/N - 5E0AJ144XCG335301, Soft Ties, Aluminum Wheels, 225/70R22.5 Tires Usage: 1,087,566 Mi Asset located in: Lake Worth, TX 2012 Kenworth T800 14x4 Five Axle Dump Truck S/N: 1NKDL40X0CJ335866 C/W: Cummins 6 Cylinder 15 L Diesel 248 hp
1789	2015 Chevrolet Silverado 1500 4X4 Crew Cab Flatbed Truck S/N: 1GB4KYC87FF132971 C/W: V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 173 in Wheelbase, 9 ft 5 in x 86 in Bed Usage: 61,854 Mi Asset located in: Lake Worth, TX		Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 24448.6 Engine hrs, Engine Brake, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.91:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Trailing Tag Axle, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, PTO, 14 ft 8 in Long x 5 ft 8 in High Steel Body, Electric Roll Tarp Usage: 259,946 Mi

Lot# **Details** Lot# **Details** 1797 2012 Freightliner Cascadia 125 10x4 Quad/A 1800A 2010 Freightliner M2 106 8x4 Tri/A Dump Truck **Dump Truck** S/N: 1FVHCYBS4ADAR3923 C/W: 6 Cylinder Diesel Engine, 10275 Engine hrs, Engine Brake, Allison Automatic S/N: 1FUJGEDV2CSBM1515 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 226 in Wheelbase, PTO, 17 ft Axle, 40000 lb Rears, Dana DS404 Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 6 in Long x 3 ft 6 in High Steel Body, Electric Aluminum Outer Wheels, 315/80R22.5, Steerable Air Lift Tag Axle, Double Frame, Roll Tarp Usage: 242,980 Mi Airliner Air Ride Suspension, 312 mm Wheelbase, PTO, 21 ft Long x 4 ft High Steel Asset located in: Lake Worth, TX Body, Manual Roll Tarp 1800B 2009 Freightliner Cascadia 125 8x4 Tri/A Usage: 520,916 Mi **Dump Truck** Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION S/N: 1FUJGLCK89LAF1778 C/W: Detroit Series 60 14.0 L Diesel 515 hp Engine, 2008 US EPA Label, Engine Brake, **REPORT** Eaton Fuller 13-Speed Manual Transmission, Asset located in: Humble, TX 12000 lb Front Axle, 40000 lb Rears, 3.58:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 1798 2014 Kenworth T440 6x4 Dump Truck Aluminum Outer Wheels, 11R22.5, Air Lift S/N: 1NKBLJ9X0EJ389440 Pusher Axle, Airliner Air Ride Suspension, 230 C/W: Paccar 6 Cylinder Diesel Engine, Requires in Wheelbase, 16 ft Long x 4 ft High Body, Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Electric Roll Tarp 10-Speed Manual Transmission, 14600 lb Usage: Not Available Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, 2 Asset located in: Lake Worth, TX Steerable Air Lift Pusher Axle, Spring 1801 2007 Sterling LT9500 8x4 Tri/A Dump Truck Suspension, 233 in Wheelbase, PTO, OX Bodies 17 ft 9 in Long x 4 ft 3 in High Steel Body, S/N: 2FZMAZCV87AX38981 Round Bottom, Electric Roll Tarp C/W: Mercedes-Benz MBE4000 6 Cylinder 12.8 L Diesel Engine, 2006 US EPA Label, Engine Brake, Allison 6-Speed Automatic Usage: 376,489 Mi Asset located in: Humble, TX Transmission, Differential Lock, 20000 lb Front 1799 2014 Freightliner 114SD 8x4 Tri/A Dump Truck Axle, 66000 lb Rears, 86000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 S/N: 3AKJG3DV2EDGA1049 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Rubber over Walking Beam Suspension, 202 in Wheelbase, PTO, OX Bodies 16 ft Long x 4 ft Exhaust Fluid, Eaton Fuller RTO-16908LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb High Steel Body, Flat Bed, Electric Roll Tarp, Pintle Hitch GVWR, Aluminum Wheels, 11R24.5, Steerable Usage: 528,890 Mi Air Lift Pusher Axle, Airliner Air Ride Suspension, 202 in Wheelbase, 16 ft 5 in Long Asset located in: Lake Worth, TX x 2 ft 6 in High Steel Body, Electric Roll Tarp 1802 2003 Mack CHU613 8x4 Tri/A Dump Truck Usage: 525,886 Mi S/N: 1M1AA12Y23W149926 Asset located in: Lake Worth, TX C/W: 6 Cylinder Diesel Engine, 22935 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb 1800 2015 Freightliner Cascadia 113 8x4 Tri/A **Dump Truck** Rears, 52000 lb GVWR, Air Ride Cab, Aluminum S/N: 1FUJGHDVXFLGF1087 Front Wheels, 315/80R22.5 Front Tires, 11R22. C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 5 Rear Tires, Air Lift Pusher Axle, Air Ride Suspension, 196 in Wheelbase, PTO, 16 ft 5 in hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW-15210B 10-Long x 5 ft 6 in High Steel Body, Flat Bed, Speed Manual Transmission, 12000 lb Front Electric Roll Tarp Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 Usage: 706,035 Mi lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Asset located in: Humble, TX Rear Tires, Air Lift Pusher Axle, Airliner Air Ride Suspension, 207 in Wheelbase, PTO, 16 ft 8 in Long x 4 ft 3 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 816,761 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1803	1999 Mack RD600 8x4 Tri/A Dump Truck S/N: 1M2P270C4XM046117 C/W: Mack E7 6 Cylinder 11.9 L Diesel 400 hp Engine, 1999 US EPA Label, 34470 Engine hrs, Manual Transmission, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Camelback Spring Suspension, 234 in Wheelbase, PTO, 16 ft Long x 3 ft 2 in High Steel Body, Flat Bed, Electric Roll Tarp, Split Swing Tailgate, Pintle Hitch Usage: 654,884 Mi Asset located in: Lake Worth, TX	1807	2013 Cat CT660S 6x4 T/A Dump Truck S/N: 1HSJGTKR3DJ301284 C/W: Cat CT13 13 L Diesel Engine, 23623 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Air Ride Suspension, 199 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Body, Bed Vibrator, Electric Roll Tarp, High-Lift Tailgate Usage: 250,468 Mi Asset located in: Lake Worth, TX
1804	2015 Peterbilt 365 6x4 T/A Dump Truck S/N: 1XPSD79X9FD262718 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trans Air Bide Suppopoint 205 in	1808	2012 International 7500 6x4 T/A Dump Truck S/N: 1HTWNAZR5CJ587087 C/W: International MaxxForce 10 6 Cylinder 9.3 L Diesel 310 hp Engine, 2011 US EPA Label, 7272 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb
1805	Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, 14 ft Long x 4 ft 3 in High Steel Body, Electric Roll Tarp Usage: 598,800 Mi Asset located in: Humble, TX		Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Hendrickson Haulmaax Suspension, 171 in Wheelbase, PTO, Warren 13 ft Long x 4 ft High Steel Body, 14 cyd, Capacity Usage: 157,181 Mi Asset located in: Lake Worth, TX
1805	2018 Kenworth T370 4x2 S/A Dump Truck S/N: 2NKHHM7X3JM183693 C/W: Paccar px7 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 6-Speed Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 5.29:1 Axle Ratio, 33000 lb GVWR, Aluminum Outer Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Reyco Spring Suspension, 165 in Wheelbase, PTO, 11 ft Long x 3 ft 10 in High Steel Body, Electric Roll Tarp, Pintle Hitch	1808A	2011 International 7400 6x4 T/A Dump Truck S/N: 1HTWGAZR5BJ399579 C/W: International MaxxForce 9 9.3 L Diesel Engine, 4726 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, 11R24.5, Spring over Walking Beam Suspension, PTO, Godwin 14 ft 8 in Long x 3 ft 4 in High Steel Body, Electric Roll Tarp Usage: 95,655 Mi Asset located in: Lake Worth, TX
1806	Usage: 80,967 Mi Asset located in: Lake Worth, TX 2016 Volvo VHD 8x4 T/A Dump Truck S/N: 4V5KC9EH4GN923100 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Volvo Automatic Transmission, Differential Lock, 20000 lb Front Axle, 40000 lb Rears, 53500 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 286 in Wheelbase, PTO, Strong Inc. 16 ft Long x 4 ft 8 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 408,393 Mi Asset located in: Lake Worth, TX	1809	2006 International 7600 6x4 T/A Dump Truck S/N: 1HTWYAHT76J239980 C/W: 6 Cylinder Diesel Engine, Engine Brake, Automated Transmission, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 248 in Wheelbase, PTO, 18 ft Long x 6 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 1,054,079 Km Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		1811	2005 Mack CH613 6x4 T/A Dump Truck S/N: 1M2AA18Y65N157393 C/W: Mack 6 Cylinder Diesel Engine, 29778 Engine hrs, Manual Transmission, Differential Lock, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 223 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 10 in High Steel Body, Pintle Hitch Usage: 637,484 Mi Asset located in: Lake Worth, TX

	Detaile	l c+ #	Details
Lot #	Details Total Control of the Control	Lot #	
1812	2002 Volvo VHD 8x4 T/A Dump Truck S/N: 4V5K99GH02N332959 C/W: Volvo 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Double Frame, TufTrac Suspension, PTO, 16 ft 6 in Long x 4 ft 2 in High Steel Body, Electric Roll Tarp Usage: 587,078 Mi Asset located in: Lake Worth, TX	1816	1991 International 2574 6x4 T/A Dump Truck S/N: 1HSGGGRRXMH360976 C/W: Cummins NTC-350 6 Cylinder 14.0 L Diesel 350 hp Engine, Eaton Fuller 13-Speed Manual Transmission, Aluminum Front Wheels, 11R24.5, Double Frame, Hendrickson RT/RTE Series Suspension, 197 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Body, Manual Roll Tarp Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE
1814	1998 Mack CH613 6x4 T/A Dump Truck	1017	Asset located in: Lake Worth, TX
1014	S/N: 1M2AA18Y6WW094985 C/W: Mack E7 6 Cylinder Diesel 427 hp Engine, 1999 US EPA Label, 20507 Engine hrs, Mack 13-Speed Manual Transmission, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Double Frame, Camelback Suspension, 216 in Wheelbase, PTO, Warren 15 ft Long x 3 ft 6 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 37,076 Mi Asset located in: Lake Worth, TX	1817	1981 Kenworth W900 6x4 T/A Dump Truck S/N: 1XKWDB9X3BK188647 C/W: Cat 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller RTO12513 Manual Transmission, 10600 lb Front Axle, 38000 lb Rears, 4.11:1 Axle Ratio, 48600 lb GVWR, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Galion 14 ft Long x 4 ft High Steel Body, Manual Roll Tarp Usage: 316,268 Mi
10144		1	Asset located in: Lake Worth, TX
1814A	1998 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUYDCYB2WP980791 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 370 hp Engine, 1998 US EPA Label, Engine Brake, Eaton Fuller RTLO-14610B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 192 in Wheelbase, PTO, OX Bodies 14 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Manual Roll Tarp, Ball hitch Usage: 864,969 Mi	1818	2016 Freightliner M2 106 4x2 S/A Dump Truck S/N: 1FVACXDU3GHGZ0167 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 152 in Wheelbase, PTO, Ledwell 10 ft Long x 3 ft High Body, Manual Roll Tarp, Double Tailgate Chutes Usage: 33,240 Mi Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	1819	2013 Kenworth T300 4x2 S/A Dump Truck
1815	1996 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUYDDYB6TH854798 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Rockwell 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 210 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 8 in High Body, Electric Roll Tarp, Pintle Hitch Usage: 647,766 Mi Asset located in: Lake Worth, TX		S/N: 2NKHHM7XXDM348014 C/W: Paccar PX6 6 Cylinder 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 6897 Engine hrs, Engine Brake, Allison 6-Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 6.17:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 178 in Wheelbase, 12 ft Long x 0 ft 32 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 96,126 Mi Asset located in: Lake Worth, TX
1815A	1992 Ford LT8000F 6x4 T/A Dump Truck	1000	
1013A	S/N: 1FDYU82A8NVA25956 C/W: Ford 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 54600 lb GVWR, 11R24.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 236 in Wheelbase, PTO, 17 ft Long x 3 ft High Steel Body, Flat Bed, Manual Roll Tarp, Pintle Hitch Usage: 336,571 Mi Asset located in: Midland, TX	1820	2008 International 4300 4x2 S/A Dump Truck S/N: 1HTMMAAN28J688226 C/W: International 6 Cylinder Diesel Engine, 2007 US EPA Label, 8057 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 19000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 153 in Wheelbase, PTO, 8 ft Long x 3 ft High Steel Body, Manual Roll Tarp, Pintle Hitch Usage: 188,392 Mi Asset located in: Lake Worth, TX

			Page 174 01 381
Lot #	Details	Lot #	Details
1821	2005 Ford F-750 XL 4x2 S/A Dump Truck S/N: 3FRNF75Y05V169058 C/W: International V8 6.0 L Diesel 200 hp Engine, 2004 US EPA Label, Allison Automatic Transmission, 9080 lb Front Axle, 17200 lb Rears, 25999 lb GVWR, 10R22.5, Spring Suspension, 158 in Wheelbase, PTO, Heil 10 ft Long x 3 ft 8 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 52,237 Mi	1823	2017 Altec DB37 Tracked Digger Derrick S/N: 0817FT1063 C/W: Kubota 3 Cylinder Diesel Engine, 3800 lb Capacity, 30 ft Reach, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Remote Control w/ Cord, 12 in Rubber Tracks, T/A Trailer, Lunette Ring, Electric Brakes Usage: 368 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1824	2017 Altec L42M 42 ft on 2017 Freightliner M2
1821A	S/N: 1FD0W4HTXCEB65433 C/W: Ford V8 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft Long x 1 ft 3 in High Body, Pintle Hitch Usage: 188,303 Mi Asset located in: Lake Worth, TX		106 4x2 Bucket Truck S/N: 3ALACXDT9HDJE9096 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 280 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8165 Engine hrs, Allison 3500 Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, 154 in Wheelbase, PTO, 400 lb Capacity, Center Mounted, Insulated One- Person Articulating-Telescopic Boom, Material Handling Jib, A-Outriggers, Rear Outriggers, 12 ft 6 in x 48 in Bed, Pintle Hitch
1821B	2017 International 4300 4x2 Flatbed Dump Truck		Usage: 137,691 Mi
	S/N: 3HAMMMN4HL489029 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9826 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 223 in Wheelbase, 20 ft Long Steel Body Usage: 275,502 Mi Asset located in: Humble, TX	4x2 Bucket Truck S/N: 1HTMMMMN2HH474504	E OF 4 - Lot #'s: 1825, 1826, 1827, 1828 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck
1821C	2015 International 4300 4x2 Flatbed Dump Truck S/N: 3HAMMAAN7FL683988 C/W: 6 Cylinder 7.6 L Diesel 230 hp Engine, 2014 US EPA Label, 8701 Engine hrs, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring Suspension, 238 in Wheelbase, PTO, OX Bodies 20 ft Long Steel Body Usage: 269,403 Mi Asset located in: Lake Worth, TX		Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9996 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 65,169 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1822	Altec on 2016 Freightliner M2 106 4x2 Digger		THE INSPECTION REPORT Asset located in: Humble, TX
	Derrick Truck S/N: 1FVACXDT4GHHL5754 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5611 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 46 ft Sheave Height, Rear Mounted, 18 in Auger, Pole Guide, Auxiliary Hydraulics, One- Man Basket, 14 ft 6 in Body, Straight Down Outriggers, Rear Outriggers Usage: 75,001 Mi Asset located in: Lake Worth, TX	1826	2017 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH161930 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8422 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 72,652 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1827	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH474542 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11175 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, 700 lb Capacity, Rear Mounted, Insulated One-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 16 ft 3 in x 94 in Bed, Pintle Hitch	1831	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH474556 C/W: Cummins Engine, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 330000 lb GVWR, 11R22.5, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, Pintle Hitch Usage: 76,812 Mi Asset located in: Lake Worth, TX
	Usage: 76,773 Mi Asset located in: Humble, TX	1832	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck
1828	2016 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN3HH161820 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8357 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 196 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14		S/N: 1HTMMMMN3HH474544 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8552 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two- Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 16 ft x 94 in Bed, Pintle Hitch Usage: 80,587 Mi Asset located in: Lake Worth, TX
	ft x 94 in Bed Usage: 82,950 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE	CHOICE	E OF 3 - Lot #'s: 1833, 1834, 1835
	THE INSPECTION REPORT	1833	2016 Altec AA55 56 ft on 2017 International
CHOIC	Asset located in: Humble, TX CHOICE OF 4 - Lot #'s: 1829, 1830, 1831, 1832 1829 2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN0HH474565 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 7992 Engine hrs, Allison Automatic Transmission, 11R22.5, 192 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib,		4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH452529 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 13023 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 96 in Bed, Pintle Hitch Usage: 133,654 Mi Asset located in: Lake Worth, TX
	Straight Down Outriggers, Rear Outriggers, Pintle Hitch	1834	2017 Altec AA55 56 ft on 2017 International
	Usage: 61,145 Mi Asset located in : Lake Worth, TX		4300 4x2 Bucket Truck S/N: 1HTMMMMN0HH161936
1830	2017 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN5HH161964 C/W: Cummins ISB 6 Cylinder 6.7 L 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8818 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 92 in Bed, Pintle Hitch Usage: 53,675 Mi		C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8428 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 66000 lb Rears, 11R22.5, 194 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulating-Telescopic Boom, Utility Body, A-Outriggers, Rear Outriggers, Remote Control w/Cord, 16 ft x 60 in Bed, Pintle Hitch Usage: 89,264 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1835	2016 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH474515 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 260	CHOICE OF 2 - Lot #'s: 1838, 1839	
	hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8241 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, A-Outriggers, Rear Outriggers, 17 ft x 96 in Bed, Pintle Hitch Usage: 65,063 Mi Asset located in: Lake Worth, TX	1838	2019 Altec AT41M 41 ft on 2019 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GTXKED88465 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7500 Ib Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, Insulated One-Person Articulating- Telescopic Boom, Utility Body, Material Handling Jib, Straight Down Outriggers,
1836	2012 Altec AA755 55 ft on 2013 Freightliner 4x4 Bucket Truck S/N: 1FVDCXDTXDHBY0785		Bumper Mounted Winch, 13 ft 6 in x 94 in Bed Usage: 190,407 Mi Asset located in: Lake Worth, TX
	C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300	1839	2019 Altec AT41M 40 ft on 2019 Ford F-550 4x2 Bucket Truck S/N: 1FDUF5GT7KED57111 C/W: Ford V8 6.7 L 330 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 7500 lb Front Axle, 19500 lb GVWR, 225/70R19.5, PTO, 400 lb Capacity, Center Mounted, Insulated One-Person Articulating-Telescopic Boom, Material Handling Jib, Straight Down Outriggers, Bumper Mounted Winch, 13 ft 6 in x 96 in Bed
1837	2011 Terex Hi Ranger TL41-51 51 ft on 2011 Freightliner M2 4x2 Bucket Truck S/N: 1FVACXDT1BHBB4508 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 260 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 7733 Engine hrs, Eaton Fuller EH- 8EX06A Automated Transmission, Differential Lock, 13220 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 6.14:1 Axle Ratio, 32220 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 177 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, One-Person Articulating-Telescopic Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 9 ft x 94 in Bed, Pintle Hitch Usage: 95,253 Mi Asset located in: Lake Worth, TX		Usage: 149,980 Mi Asset located in : Lake Worth, TX
		1840	2012 Altec LRV55 55 ft on 2011 Freightliner M2 106 4x2 Forestry Bucket Truck S/N: 1FVACXDU3BDAU8449 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2009 US EPA Label, Requires Diesel Exhaust Fluid, 15196 Engine hrs, Eaton Fuller FS-6406A 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 21-145 Drive Axles, 4.88:1 Axle Ratio, 33000 lb GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 187 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, Insulated One-Person Articulating- Telescopic Boom, Chip Body, A-Outriggers, 11 ft x 92 in Bed Usage: 84,033 Mi
			Notes: ODOMETER DISCREPANCY-UNIT SHOWS 84,033, TITLE SHOWS 999,999, TITLE BRANDED NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX
		1841	2006 International 4300 Bucket Truck S/N: 1HTMMAAL16H341098 Usage: Not Available Asset located in: Humble, TX
		1842	2005 GMC C8500 Bucket Truck S/N: 1GDP8C1C75F512565 Usage: Not Available

Asset located in: Humble, TX

Details Lot # **Details** Lot # 1843 Versalift on 1999 Ford F-450 4x2 Crew Cab **Bucket Truck** CHOICE OF 2 - Lot #'s: 1849, 1850 S/N: 1FDXW46F9XEA93643 C/W: V8 7.3 L Diesel Engine, Automatic Transmission, 5790 lb Front Axle, 10880 lb Rears, 15000 lb GVWR, 225/70R19.5, Spring 1849 2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV5JDJL7485 Suspension, 176 in Wheelbase, Center C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Mounted, Insulated One-Person Articulating-Telescopic Boom, Utility Body, Out and Down Exhaust Fluid, 14464 Engine hrs, Engine Brake, Outriggers, 13 ft 9 in x 96 in Bed Usage: 143,468 Mi Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Asset located in: Lake Worth, TX Axle Ratio, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, 1844 2011 Ford F-550 XL 4x2 Chipper Truck Steerable Air Lift Pusher Axle, Trailing Tag S/N: 1FDUF5GT2BEB53610 Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, PTO, Beck 11 cyd Mixer C/W: 6 Cylinder 6.7 L 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, Unit, 3 Removable Chutes 14704 lb Rears, 19500 lb GVWR, 225/70R19.5. Usage: 51,410 Mi Spring Suspension, 165 in Wheelbase, 11 ft x x 78 in High Body, Pintle Hitch Asset located in: Lake Worth, TX 1850 2018 Freightliner 114 SD 10x4 Mixer Truck Usage: 101.174 Mi S/N: 3ALHG3DV7JDJM2090 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Exhaust Fluid, 12913 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential 1846 2009 Peterbilt 340 6x4 Volumetric Mixer Truck Lock, Air Ride Cab, 425/65R22.5 Front Tires, S/N: 2NPRLN0X69M771130 11R22.5 Rear Tires, Steerable Air Lift Pusher C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 315 Axle, Trailing Tag Axle, Dual Steering Boxes, hp Engine, 2008 US EPA Label, 15485 Engine hrs, Eaton Fuller RTO-11908LL 8LL Manual TufTrac Spring Suspension, 238 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Transmission, 20000 lb Front Axle, 46000 lb Usage: 107,793 Mi Rears, Dana D46-170HP Drive Axles, 4.56:1 Asset located in: Lake Worth, TX Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring over Walking Beam CHOICE OF 3 - Lot #'s: 1851, 1852, 1853 Suspension, 240 in Wheelbase, PTO, 2008 Cemen Tech MCD8-130 8 cyd Mixer Unit 1851 2018 Freightliner 114 SD 10x4 Mixer Truck Usage: 141,364 Mi S/N: 3ALHG3DV0JDJM2089 Asset located in: Lake Worth, TX C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 1847 2005 Mack CV713 8x4 Volumetric Mixer Truck Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, S/N: 1M2AG11C65M015628 Differential Lock, 20000 lb Front Axle, 46000 lb C/W: Mack 6 Cylinder Diesel Engine, 12565 Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Engine hrs, Engine Brake, Manual Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Transmission, 16540 lb Front Axle, 44000 lb Rears, 60540 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24. Trailing Tag Axle, Dual Steering Boxes, Double 5 Rear Tires, Steerable Air Lift Pusher Axle, Frame, TufTrac Spring Suspension, 249 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Double Frame, Camelback Spring Suspension, 252 in Wheelbase, PTO, 2005 Cemen Tech Removable Chutes, Remote Control w/Cord MCD10-150 Mixer Unit Usage: 175,339 Mi Usage: 265,336 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1852 2018 Freightliner 114SD 10x4 Mixer Truck 1848 2004 Kenworth T800 8x4 Volumetric Mixer S/N: 3ALHG3DV7JDJM2087 Truck C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 13808 Engine hrs, Engine S/N: 1NKDXUTX94J051508 Brake, Allison Automatic Transmission, Double C/W: Cat C12 6 Cylinder 11.9 L Diesel 380 hp Differential Locks, 20000 lb Front Axle, 46000 Engine, 2003 US ÉPA Label, 13738 Engine hrs, lb Rears, 66000 lb GVWR, Air Ride Cab, Eaton Fuller 8LL Manual Transmission, 4.33:1 Aluminum Wheels, 425/65R22.5 Front Tires, Axle Ratio, Aluminum Front Wheels, 425 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes,

TufTrac Suspension, 248 in Wheelbase, Beck

11 cyd Mixer Unit, 3 Removable Chutes

Asset located in: Lake Worth, TX

Usage: 176,719 Mi

/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double

Frame, Hendrickson RT/RTE Series Suspension, 224 in Wheelbase, PTO

Asset located in: Lake Worth, TX

Usage: 52,449 Mi

Details Lot # **Details** Lot # 1853 2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV9JDJM2088 CHOICE OF 2 - Lot #'s: 1857, 1858 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14895 Engine hrs, Engine Brake, 1857 2014 Kenworth W900 8x4 Mixer Truck Allison 4500 Automatic Transmission, Double S/N: 1NKWL70X3EJ387392 Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, C/W: Cummins 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 11R22.5 Rear Tires, Steerable Air Lift Pusher lb Rears, 66000 lb GVWR, Aluminum Wheels, Axle, Trailing Tag Axle, Dual Steering Boxes, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, TufTrac Suspension, 248 in Wheelbase, 11 cyd Trailing Tag Axle, Dual Steering Boxes, Double Mixer Unit, 3 Removable Chutes Frame, Hendrickson Haulmaax Rubber over Usage: 198,768 Mi Walking Beam Suspension, 3 Removable Asset located in: Lake Worth, TX Usage: Not Available Asset located in: Lake Worth, TX CHOICE OF 3 - Lot #'s: 1854, 1855, 1856 1858 2014 Kenworth W900 8x4 Mixer Truck S/N: 1NKWL70X1EJ387391 1854 2018 Freightliner 114SD 10x4 Mixer Truck C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires S/N: 3ALHG3DV7JDJL7486 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Diesel Exhaust Fluid, 17553 Engine hrs, Allison 4500 Automatic Transmission, 20000 lb Front Exhaust Fluid, 17360 Engine hrs, Engine Brake, Axle, 46000 lb Rears, Meritor RT-46-160 Drive Allison 4500 Automatic Transmission, Double Axles, 4.89:1 Axle Ratio, 66000 lb GVWR, Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber Aluminum Wheels, 425/65R22.5 Front Tires, over Walking Beam Suspension, 250 in 11R22.5 Rear Tires, Steerable Air Lift Pusher Wheelbase, PTO, 2 Removable Chutes, Remote Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck Control w/Cord Usage: 182,221 Mi 11 cvd Mixer Unit. 3 Removable Chutes Asset located in: Lake Worth, TX Usage: 205,429 Mi Asset located in: Lake Worth, TX CHOICE OF 3 - Lot #'s: 1859, 1860, 1861 1855 2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV3JDJL7484 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 1859 2019 Freightliner 114 SD 6x4 Mixer Truck hp Engine, Requires Diesel Exhaust Fluid, S/N: 1FVHG3DV5KHJS0956 Engine Brake, Allison 4500 Automatic C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Exhaust Fluid, Engine Brake, Allison 4500 Ride Cab, Aluminum Wheels, 425/65R22.5, Automatic Transmission, Differential Lock, Steerable Air Lift Pusher Axle, Trailing Tag 20000 lb Front Axle, 46000 lb Rears, 66000 lb Axle, Dual Steering Boxes, Double Frame, GVWR, Air Ride Cab, Aluminum Wheels, 425 TufTrac Suspension, 248 in Wheelbase, PTO, /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Beck 11 cyd Mixer Unit, 3 Removable Chutes Steering Boxes, TufTrac Spring Suspension, Usage: 208,663 Mi 234 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Asset located in: Lake Worth, TX Removable Chutes, Remote Control w/Cord Usage: 133,211 Mi 1856 2018 Freightliner 114SD 10x4 Mixer Truck Asset located in: Lake Worth, TX S/N: 3ALHG3DV0JDJM2092 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15416 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 Ib Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes,

TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord

Usage: 184,716 Mi

Lot #	Details	Lot #	Details
1860	2019 Freightliner 114SD 6x4 Mixer Truck S/N: 1FVHG3DV7KHJS0957 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15048 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 232 in Wheelbase, PTO, 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 147,481 Mi Asset located in: Lake Worth, TX	1864	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV6JDJW4873 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 16397 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Spring Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 171,963 Mi Asset located in: Lake Worth, TX
1861	2019 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV9KHKF4834 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, CARB	СНОІСЕ	E OF 3 - Lot #'s: 1865, 1866, 1867
	Compliant, Requires Diesel Exhaust Fluid, 14290 Engine hrs, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 232 in Wheelbase, PTO, 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 167,132 Mi Asset located in: Lake Worth, TX	1865	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV8JDJW4874 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15138 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Spring Suspension, 216 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote
CHOIC	E OF 3 - Lot #'s: 1862, 1863, 1864		Control w/Cord Usage: 174,579 Mi
1862	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV4JDJW4872 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13917 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Spring Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord	1866	Asset located in: Lake Worth, TX 2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV1JDJW4876 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14061 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit Usage: 139,282 Mi Asset located in: Lake Worth, TX
	Usage: 143,981 Mi Asset located in : Lake Worth, TX	1867	2017 Freightliner 114 SD 6x4 Mixer Truck
1863	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DVXJDJW4875 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14693 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Spring Suspension, 232 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 159,856 Mi Asset located in: Lake Worth, TX		S/N: 3ALHG3DV6HDJG5267 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, Requires Diesel Exhaust Fluid, 13679 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 36,162 Mi Asset located in: Lake Worth, TX

Lot # **Details** Lot # Details 1872 2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV6FHGC6641 CHOICE OF 3 - Lot #'s: 1868, 1869, 1870 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19288.9 Engine hrs, Engine 1868 2015 Freigthliner 114SD 6x4 Mixer Truck Brake, Allison 4000 Automatic Transmission, S/N: 1FVHG3DV9FHGD2918 Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, CARB Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, Compliant, Requires Diesel Exhaust Fluid. 20129 Engine hrs, Allison Automatic 11R22.5 Rear Tires, Dual Steering Boxes, Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Double Frame, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Usage: 225.694 Mi Double Frame, TufTrac Suspension, 230 in Asset located in: Lake Worth, TX Wheelbase, PTO, 10.5 cyd Mixer Unit, 3 Removable Chutes 1873 2015 Freightliner 114 SD 6x4 Mixer Truck Usage: 242,364 Mi S/N: 1FVHG3DV0FHGD3309 Asset located in: Lake Worth, TX C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 1869 2015 Freightliner 114SD 6x4 Mixer Truck 20105.7 Engine hrs, Engine Brake, Allison 4500 S/N: 3ALHG3DV8FDGP8010 Automatic Transmission, Differential Lock, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425 Exhaust Fluid, 15144 Engine hrs, Engine Brake, Allison Automatic Transmission, Double /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Differential Locks, 22000 lb Front Axle, 46000 Steering Boxes, Double Frame, Rubber over lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable 11R22.5 Rear Tires, Dual Steering Boxes, Chutes, Remote Control w/Cord Double Frame, TufTrac Suspension, 231 in Usage: Not Available Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Asset located in: Lake Worth, TX Removable Chutes Usage: 162,097 Mi Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1874, 1875 1870 2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DVXFHGC6643 1874 2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DVXFDGK8256

C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes

Úsage: 186,822 Mi

Asset located in: Lake Worth, TX

CHOICE OF 3 - Lot #'s: 1871, 1872, 1873

1871 2015 Freightliner 114 SD 6x4 Mixer Truck

S/N: 3ALHG3DV8FDGK8255 C/W: Detroit DD13 6 Cylinder Diesel Engine, 18450 Engine hrs, Engine Brake, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 234 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes

Usage: 204,227 Mi

Asset located in: Lake Worth, TX

C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 5810 Engine hrs, Engine Brake, Allison 6-Speed Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.86:1 Axle Ratio, 68000.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 10.5 cvd Mixer Unit, 3 Removable Chutes Usage: 204,689 Mi

Lot #	Details	Lot #	Details
1875	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV7FHGD2917 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19762.9 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 201,518 Mi Asset located in: Lake Worth, TX	1879	2015 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C9FM028775 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14199 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5, Dual Steering Boxes, Camelback Suspension, 234 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes Usage: 133,877 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	E OF 2 - Lot #'s: 1876, 1877	1880	2008 Mack GU813 Mixer Truck S/N: 1M2AX13C98M001689 Usage: Not Available Asset located in: Lake Worth, TX
1876	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DVXFHGS0264 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 222 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w /Cord Usage: 34,426 Mi	1881	2007 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C07M061944 C/W: Mack AMI 6 Cylinder Diesel 325 hp Engine, 10175 Engine hrs, Mack 10-Speed Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Camelback Spring Suspension, 227 in Wheelbase, CBMW 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 38,616 Mi Asset located in: Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX	1882	2007 Mack CPT713 Mixer Truck S/N: 1M2AT04C27M006297 Usage: Not Available
1877	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV2FHGN1430 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 350 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 222 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 36,664 Mi Notes: ADDITIONAL INFORMATION	1884	Asset located in: Lake Worth, TX 2005 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C75M034222 C/W: Mack 6 Cylinder Diesel Engine, 28940 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 229 in Wheelbase, 3 Removable Chutes Usage: 337,303 Mi Asset located in: Lake Worth, TX
	AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX	1885	2006 Peterbilt 357 6x4 Mixer Truck S/N: 1NPALT0X46D890572
1878	2014 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV7EHFW3536 C/W: Detroit DD15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18254 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, Composite Water Tank Usage: 185,216 Mi Asset located in: Lake Worth, TX		C/W: Cat 6 Cylinder Diesel Engine, 9701 Engine hrs, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Aluminum Wheels, 445/65R22.5 Front Tires, 12R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Suspension, 216 in Wheelbase, PTO, 3 Removable Chutes, Remote Control w/Cord Usage: 267,072 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1886	2003 Peterbilt 357 6x4 Mixer Truck S/N: 1NPALT0X53D802186 C/W: Cat C10 6 Cylinder Diesel 305 hp Engine, 7071 Engine hrs, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, 3 Removable Chutes Usage: 266,861 Mi Notes: LOCATED-IN-HOUSTON-TX	1892	2017 Freightliner M2 106 4x2 Attenuator Truck S/N: 3ALACWDT6HDJE8126 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 4774 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, 5.13:1 Axle Ratio, 26000 lb GVWR, 10R22.5, Airliner Suspension, 282 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 84,841 Mi Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	1893	2012 International 4300 4x2 Attenuator Truck
1888	2002 Kenworth T800 6x4 Mixer Truck S/N: 1NKDLU0X12J703485 C/W: Cat C-12 6 Cylinder 11.9 L Diesel 505 hp Engine, 2002 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 425/65R22. 5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 3 Removable Chutes Usage: 159,586 Mi		S/N: 3HAJTSKL8CL606518 C/W: International 6 Cylinder Diesel Engine, 11142 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 214 in Wheelbase, Flatbed Usage: 157,339 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1894A	2017 Ford F-650 4x2 Attenuator Truck
1889	1999 Mack DMM6906S 6x4 Mixer Truck S/N: 1M2E178CXXM002704 C/W: Mack EM7 6 Cylinder 728 cid Diesel Engine, 1998 US EPA Label, 47454 Engine hrs, 8LL Manual Transmission, Aluminum Front Wheels, 445/65R22.5, Walking Beam Suspension, 180 in Wheelbase, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 89,880 Mi Asset located in: Lake Worth, TX		S/N: 1FDNF6DC7HDB04478 C/W: V8 6.7 L Diesel 270 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 218 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 91,813 Mi Asset located in: Lake Worth, TX
1890	2009 GMC T8500 4x2 COE Extended Cab Rear	1895	2008 Hino 338 4x2 Attenuator Truck
	Loader Waste Collection Truck S/N: 1GDP8F1B29F405423 C/W: Isuzu 6HK1X 6 Cylinder 7.8 L Diesel 260 hp Engine, 2008 US EPA Label, Allison Automatic Transmission, 13220 lb Front Axle, 23360 lb Rears, 36580 lb GVWR, 11R22.5 Front Tires, 445/65R22.5 Rear Tires, Spring Suspension, 171 in Wheelbase, PTO, McNelius 1710 17 cyd Capacity Collection Body Usage: 68,923 Mi	1895 t	S/N: 5PVNV8JT682S50910 C/W: J08-TW 6 Cylinder Diesel 260 hp Engine, 2007 US EPA Label, 684 Engine hrs, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 196 in Wheelbase, Flatbed, Arrow Board, In-Cab Arrow Board Controller Usage: 194,141 Mi Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	1896	2007 Hino 268 4x2 Attenuator Truck
1891	1997 Freightliner FL70 4x2 Attenuator Truck S/N: 1FV3HLAA4VH739867 C/W: Cummins C8.3 8.3 L Diesel Engine, 1996 US EPA Label, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 216 in Wheelbase, Flatbed Usage: Not Available Asset located in: Humble, TX		S/N: 5PVNJ8JP872S50064 C/W: Hino Motors JO8E-TA 6 Cylinder 7.7 L Diesel Engine, 2008 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 218 in Wheelbase, Flatbed, In-Cab Attenuator Controller Usage: 343,850 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1897	2007 International 8000 4x2 Toter Truck S/N: 1HSHWAHN67J535045 C/W: 6 Cylinder Diesel Engine, 21882 Engine hrs, Eaton Fuller Manual Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 156 in Wheelbase Usage: 239,028 Mi Asset located in: Midland, TX 2020 Peterbilt 567 6x4 Roll-Off Truck	1901	1901 2022 Chevrolet Silverado 5500HD 4x2 Rollbac Truck S/N: 1HTKHPVM6NH675305 C/W: Navistar Duramax V8 6.6 L Diesel 350 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7940 lb Front Axle, 15000 lb Rears, 4.10:1 Axle Ratio 22940 lb GVWR, 225/70R19.5, Spring Suspension, 232 in Wheelbase, PTO, Century Steel Wrecker Body, 5000 lb Winch Capacity, Tow Dollies Usage: 60,704 Mi
	S/N: 1NPCL40X3LD650696 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10547 Engine hrs, Engine Brake, 10-Speed Manual Transmission, Triple		Notes: X2-CNV Dash Vin from photo; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 276 in Wheelbase, PTO, 2019 Galbreath U5-OR-174 Roll-Off Body, 23 ft 4 in Hoist, Winch Usage: 285,990 Mi Asset located in: Lake Worth, TX	US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 20 in Wheelbase, PTO, Danco 12SR20 Rollback Body, 20 ft x 96 in Bed, Ramsey 8000 lb Wind	S/N: 3C7WRNDL4LG136586 C/W: Cummins 6 Cylinder 6.7 L Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 205 in Wheelbase, PTO, Danco 12SR20 Rollback
1899	2013 Freightliner 114 6x4 Roll-Off Truck S/N: 3ALHG3DV8DDFF1962 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission,		Hydraulic Wheel Lift, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 70,701 Mi
	16000 lb Front Axle, 44000 lb Rears, 60000 lb GVWR, Air Ride Cab, 295/75R22.5, Double Frame, TufTrac Suspension, 23 ft 4 in Hoist Usage: 472,556 Mi Asset located in: Lake Worth, TX	1904	2019 Isuzu NRR 4x2 COE Rollback Truck S/N: JALE5W160K7304175 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5916 Engine hrs, Automatic
1899A	2007 Volvo VHD 6x4 Roll-Off Truck S/N: 4V5KC9GG07N427019 C/W: Volvo D12D395 6 Cylinder 12.1 L Diesel 395 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller 8LL Manual Transmission, 18740 lb Front Axle, 44000 lb Rears, 4.11:1 Axle Ratio, 62740 lb GVWR, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 285/75R24.5 Rear Tires, Double Frame, Hendrickson RT/RTE Series Suspension, 240 in Wheelbase, PTO, 23 ft Hoist Usage: 727,039 Mi		Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500.0 lb GVWR, 225/70R19.5, Spring Suspension, 178 in Wheelbase, PTO, Wet Kit, 21 ft 6 in x 96 in Bed, Aluminum Frame, 18000 lb Winch Usage: 196,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	Notes: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, CANNOT BE DRIVEN. TEMP TAGS WILL NOT BE ISSUED Asset located in: Lake Worth, TX		2005 Freightliner M2 106 4x2 Sleeper Tow Truck S/N: 1FVAC2DC35HV14126 C/W: Cat C7 6 Cylinder Diesel 250 hp Engine, 12717 Engine hrs, Eaton Fuller RT8709B 9-
1900	2005 Peterbilt 357 6x4 Roll-Off Truck S/N: 1NPALT0XX5N857701 C/W: Cat C11 6 Cylinder Diesel Engine, 1888 Engine hrs, Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 266 in Wheelbase, PTO, GH 1560 Roll-Off Body, 23 ft Hoist Usage: Not Available Asset located in: Lake Worth, TX		Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS21145 Drive Axles, 3.90:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 178 in Wheelbase, PTO, Steel Wrecker Body Usage: 262,313 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1904A 1904B	2009 Forest River Georgetown Motor Home S/N: 1F6NF53Y590A00112 C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2009 US EPA Label, 3 Slide Outs, Power Entrance Step, Power Leveling Jacks, Power Awning, Onan RV QG 5500 LP 5.5 kW Generator, Rear View Camera Usage: 23,619 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2007 Gulf Stream Independence Motor Home S/N: 4UZACLBW57CZ34853 C/W: Air Conditioner, Automatic Transmission, 1899.5 hrs Carrier Engine, Cummins 6 Cylinder Diesel Engine, 2007 US EPA Label, 3 Slide Outs,	CHOICE 1908	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JV1H4S66305 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, Thermo King T-1080R Whisper Reefer Unit, 8637 Reefer Engine Hours:, 8637 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 293,547 Mi
	Power Entrance Step, Power Leveling Jacks, Power Awning, Generator w/ 266 hrs Usage: 82,082 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1909	Asset located in: Lake Worth, TX 2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT8H4S57955 C/W: Hino 6 Cylinder Diesel Engine, 2016 US
1905	2002 Prevost H3-45 Motor Home S/N: 2PCV33491X1013393 C/W: Air Conditioner, Allison Automatic Transmission, Detroit 6 Cylinder 12.7 L 500 hp Engine, Sleeps 2 People, Clothes Washer & Dryer, Power Awning, Power Tech 25 kW Generator Usage: 142,465 Mi Asset located in: Lake Worth, TX		EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 254 in Wheelbase, Thermo King T-1080R Reefer Unit, 9481 Reefer Engine Hours:, 9481 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 297,803 Mi Asset located in: Lake Worth, TX
1906	2018 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JV5J4S67771 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9282 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Carrier Reefer Unit, 8457 Reefer Total Hours:, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 171,017 Mi Notes: SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	1910	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT2H4S57952 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 254 in Wheelbase, Thermo King T-1080R Whisper Reefer Unit, 5965 Reefer Engine Hours:, 5965 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 322,392 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
1907	2018 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JL0J4S52089 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Hendrickson Air Ride Suspension, 188 in Wheelbase, Carrier Reefer Unit, 9213 Reefer Total Hours:, Morgan 16 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 184,843 Mi Asset located in: Lake Worth, TX	1911	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JTXH4S57455 C/W: Hino 6 Cylinder Diesel Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, Carrier Transicold Reefer Unit, 12952 Reefer Engine Hours:, 16707 Reefer Total Hours:, Supreme 24 ft x 102 in Wide x 98 in High Body, Curbside Door Usage: 237,435 Mi Asset located in: Lake Worth, TX

			Page 185 of 581		
Lot #	Details	Lot #	Details		
1912	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT1H4S57439 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 252 in Wheelbase, Carrier Reefer Unit, Supreme 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Walk-Up Ramp, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 284,077 Mi Asset located in: Lake Worth, TX	1915	1915	Truck S/N: 3ALACWD C/W: Cummins Engine hrs, Aut Front Axle, 175 Steel, 11R22.5, Wheelbase, Car Total Hours:, Kir High Body Usage: 297,043 Notes: THIS UN DEFICIENCIES	S/N: 3ALACWDT5GDHE5396 C/W: Cummins 6 Cylinder Diesel Engine, 11342 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 256 in Wheelbase, Carrier Reefer Unit, 13046 Reefer Total Hours:, Kidron 24 ft x 102 in Wide x 97 in High Body Usage: 297,043 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL
1913	2019 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFC0KDKL2452 C/W: Cummins B 6 Cylinder 6.7 L Diesel 250 hp Engine, 2018 US EPA Label, 9375 Engine hrs, Eaton Fuller 3 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Thermo King T-680R Reefer Unit, Morgan 24 ft x 102 in Wide x 96 in High Body, Curbside Door, Liftgate Usage: 332,255 Mi		SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX 2015 Freightliner M2 106 4x2 Refrigerated Truck		
	Asset located in: Lake Worth, TX		S/N: 3ALACXDT1FDGF1570		
1914	2016 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWDT5GDGV8814 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 2114 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, Carrier Supra S8 Reefer Unit, 5377 Reefer Engine Hours:, Morgan 26 ft x 102 in Wide x 98 in High Body, Curbside Door, Liftgate Usage: 278,090 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD		C/W: Cummins ISB 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10137 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 5.88:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, steel, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Carrier Transicold Reefer Unit, 11638 Reefer Total Hours:, Morgan 22 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 313,978 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
1917	Truck S/N: 1FVACWDT0CHBS3944 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11946 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Thermo King Reefer Unit, Morgan 26 ft x 96 in Wide x 97 in High Body, Liftgate Usage: 324,437 Hr Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	1922	2016 International 4300 4x2 Beverage Truck S/N: 1HTMMMML3GH225609 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 6-Speed Automatic Transmission, 8618 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 235 in Wheelbase, Mickey 21 ft Body, 36 in Wide Bays, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 343,147 Mi Asset located in: Lake Worth, TX
		1923	2018 Peterbilt 337 4x2 Van Truck S/N: 2NP2HM7X2JM491941 C/W: Paccar B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7218 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 6.17:1 Axle Ratio, 32000 lb GVWR, 275/80R22.5, Spring Suspension, 275 in Wheelbase, Wabash 24 ft x 102 in Wide x 88 in High Body, Liftgate, EQUIPMENT-FROM-
1918	2018 International 4300 4x2 Refrigerated Truck S/N: 3HAMMMML4JL736540 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp		YELLOW-CORP Usage: 110,293 Mi Asset located in : Lake Worth, TX
	Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5440 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 156,143 Mi Asset located in: Lake Worth, TX	hp Engine, 2016 US EPA Label, Require Exhaust Fluid, 9288 Engine hrs, Allisor Automatic Transmission, 10000 lb Fro 20000 lb Rears, Dana S21170 Drive Ax 1 Axle Ratio, 26000 lb GVWR, Aluminu Wheels, 11R22.5, Air Ride Suspension Wheelbase, Morgan 24 ft x 102 in Wid in High Body, Curbside Door, Liftgate Usage: 312,144 Mi Asset located in: Humble, TX 1925 2015 Peterbilt 337 4x2 Van Truck S/N: 2NP2HJ7X9FM275736 C/W: Paccar ISL 6 Cylinder 8.9 L Diese Engine, Requires Diesel Exhaust Fluid, 3000 Automatic Transmission, 12000 Axle, 21000 lb Rears, 4.11:1 Axle Ratio 33000.0 lb GVWR, Aluminum Outer Wl /75R22.5, Paccar Air Ride Suspension	S/N: 2NP2HM6X2HM409086 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9288 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, Dana S21170 Drive Axles, 4.56: 1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 260 in
1920	2019 Isuzu NQR 4x2 COE Refrigerated Truck S/N: JALE5W167K7900576 C/W: Isuzu 4 Cylinder Diesel Engine, 2018 US		in High Body, Curbside Door, Liftgate Usage: 312,144 Mi
	EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6830 lb Front Axle, 12980 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 150 in Wheelbase, Thermo King T-680R Reefer Unit, supreme 18 ft x 102 in Wide x 92 in High Body, Curbside Door, Liftgate Usage: 179,717 Mi Asset located in: Lake Worth, TX		2015 Peterbilt 337 4x2 Van Truck
1921	2017 Chevrolet G3500 4x2 Refrigerated Truck S/N: 1GB0GRFF4H1344050 C/W: V8 Gasoline Engine, 8673 Engine hrs, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, Aluminum Wheels, 245/75R16, Spring Suspension, 139 in Wheelbase, Thermo King V-520 NM Max Reefer Unit, GCE 11 ft x 88 in Wide x 72 in High		in High Body, Liftgate Usage: 287,399 Mi Asset located in : Lake Worth, TX
			E OF 2 - Lot #'s: 1926, 1927
	Body, Curbside Door Usage: 328,694 Mi Asset located in : Lake Worth, TX	1926	2020 Hino 268 Van Truck S/N: 5PVNJ8JV3L4S75936 Usage: 223,964 Mi Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details	
1927	C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel	СНОІС	E OF 5 - Lot #'s: 1932, 1933, 1934, 1935, 1936	
СНОІС	Exhaust Fluid, 5949 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 237,576 Mi Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 1928, 1929	1932	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S74135 C/W: Hino 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 7853 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 252,005 Mi	
1928	2020 Hino 268 4x2 Van Truck	1000	Asset located in: Lake Worth, TX	
	S/N: 5PVNE8JVXL4S57650 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 5054 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 243,455 Mi Asset located in: Lake Worth, TX	1933	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3K4S70413 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6861 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hino Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body Usage: 195,635 Mi	
1929	2020 Hino 268 4x2 Van Truck		Asset located in: Lake Worth, TX	
	S/N: 5PVNE8JV0L4S57611 C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 274,702 Mi Asset located in: Lake Worth, TX	1934	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S70473 C/W: Hino Motors J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7082 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 199,209 Mi	
CHOIC	E OE 2 at #a: 1020 1021		Asset located in: Lake Worth, TX	
СПОІС	E OF 2 - Lot #'s: 1930, 1931	1935	2019 Hino 268 4x2 Van Truck	
1930	2019 Hino 268 Van Truck S/N: 5PVNJ8JV9K4S70786 Usage: 241,223 Mi Asset located in: Lake Worth, TX 2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV9K4S72697	_	Exhaust Fluid, Automatic Transmiss lb Front Axle, 19000 lb Rears, 25950 Aluminum Wheels, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in W in High Body Usage: 220,034 Mi	C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 Ib Front Axle, 19000 Ib Rears, 25950 Ib GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in Wide x 103 in High Body
	C/W: Hino 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid,	1936	2019 Hino 268 4x2 Van Truck	
	11873 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, Supreme 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 311,559 Mi Asset located in: Lake Worth, TX	1900	S/N: 5PVNJ8JV1K4S70474 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8646 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 227,375 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
CHOIC	E OF 4 - Lot #'s: 1937, 1938, 1939, 1940	СНОІС	E OF 2 - Lot #'s: 1943, 1944
1937	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV5K4S71661 C/W: Hino 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7844 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 264,419 Mi Asset located in: Lake Worth, TX	1943	2017 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0H4S55963 C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 302,562 Mi Asset located in: Lake Worth, TX
1938	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV7K4S70785 C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11645 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 394,055 Mi	-1944 	2016 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXG4S61134 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX
1020	Asset located in: Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 1945, 1946, 1947
1939	2018 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV9J4S67062 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, Mickey 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 226,779 Mi Asset located in: Lake Worth, TX	1945	2016 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0G4S54665 C/W: J08E-VC 6 Cylinder Diesel 220 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate
1940	2018 Hino 268 4x2 Van Truck		Usage: 779,914 Mi Asset located in: Lake Worth, TX
СНОІС	S/N: 5PVNJ8JV5J4S67334 C/W: 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 1941, 1942	1946	2015 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV7F4S58836 C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 999 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 762,239 Mi
	L O1 2 - LO(π 3. 12+1, 12+2	1047	Asset located in: Lake Worth, TX
1941	2018 Hino 268 Van Truck S/N: 5PVNJ8JV7J4S70011 Usage: 239,327 Mi Asset located in: Lake Worth, TX	Engine, 2013 US EPA Label, Requires Exhaust Fluid, Automatic Transmiss Ib Front Axle, 19000 lb Rears, 25950 11R22.5, Spring Suspension, 254 in	S/N: 5PVNE8JT3E4S55904 C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR,
1942	2018 Hino 268 Van Truck S/N: 5PVNJ8JV6J4S70016 Usage: 335,947 Mi Asset located in: Lake Worth, TX		11R22.5, Spring Suspension, 254 in Wheelbase, Supreme Corp 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 665,898 Mi

Lot #	Details	Lot #	Details
1948	2013 Hino 268 4x2 Van Truck S/N: 5PVNE8JVXD4S52658 C/W: Hino Motors J08E-VC 6 Cylinder 7.7 L Diesel 220 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 239 in Wheelbase, Morgan	CHOICE 1952	CE OF 2 - Lot #'s: 1952, 1953 2010 Hino 165 4x2 Van Truck S/N: 5PVNJ8JV5A4S52235 C/W: Hino Motors J08E-TV 6 Cylinder 7.7 L
1948A	20 ft x 102 in Wide x 93 in High Body Usage: 163,671 Mi Asset located in: Lake Worth, TX 2013 Hino 268 4x2 Van Truck S/N: 5PVNE8JT8D4S54925 C/W: 6 Cylinder 7.6 L Diesel Engine, Requires	Allison Automatic Transmi Front Axle, 19000 lb Rears, Steel, 11R22.5, Hendrickso Suspension, 272 in Wheelb	•
	Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb	1953	Asset located in: Lake Worth, TX 2010 Hino 268 4x2 Van Truck
	GVWR, 11R22.5, Spring Suspension, 251 in Wheelbase, Reading 24 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 733,693 Mi Asset located in : Lake Worth, TX		S/N: 5PVNE8JV3A4S51573 C/W: Hino J08E-TV 6 Cylinder Diesel 220 hp Engine, 2009 US EPA Label, 999 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR,
	CHOICE OF 2 - Lot #'s: 1949, 1950		11R22.5, Spring Suspension, 269 in Wheelbase Morgan 26 ft x 102 in Wide x 103 in High Body Curbside Door, Liftgate Usage: 542,329 Mi Asset located in: Lake Worth, TX
1949	S/N: 5PVNE8JV8H4S55600 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5,	1954	2016 Hino 155 Van Truck S/N: JHHXDM1H2GK003847 Usage: 206,947 Mi Asset located in: Lake Worth, TX
		Truck S/N: 3ALAC4DV3LDME8608 C/W: Detroit DD13 6 Cylinder 12.8 Engine, 2019 US EPA Label, 9094 Engine Brake, Eaton Fuller FAO-1- Automated Transmission, 12000 21000 lb Rears, Meritor RS-21-16 3.07:1 Axle Ratio, 33000 lb GVWF Front Tires, 11R22.5 Rear Tires, A	S/N: 3ALAC4DV3LDME8608 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2019 US EPA Label, 9094 Engine hrs,
1950	2016 Hino 165 Van Truck S/N: 5PVNE8JV7G4S54761 Usage: Not Available Asset located in : Lake Worth, TX		Automated Transmission, 12000 lb F 21000 lb Rears, Meritor RS-21-160 D 3.07:1 Axle Ratio, 33000 lb GVWR, 11 Front Tires, 11R22.5 Rear Tires, Airlir
1951	2013 Hino 165 4x2 Van Truck S/N: 5PVNE8JT2D4S55035 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11P22 5 Spring Supposion, 254 in Wheelbase		Ride Suspension, 234 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 533,064 Mi Asset located in: Lake Worth, TX
	11R22.5, Spring Suspension, 254 in Wheelbase, READING 24 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 791,274 Mi Asset located in: Lake Worth, TX	1956	2020 Freightliner M2 106 4x2 Van Truck S/N: 3ALACXFC5LDMA4042 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, MARION 26 ft x 102 in Wide x 109 in High Body, Liftgate Usage: 294,302 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1961	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC8KDKK6432 C/W: Cummins 6 Cylinder 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, Smyrna 26 ft x 96 in Wide x Body, Liftgate Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC1JDJZ7466 C/W: Cummins 6 Cylinder 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17000 lb Rears, 26000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, Morgan 24 ft x x Body, Curbside Door, Liftgate Usage: 397,493 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
1962	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB3KDKH7131 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2018 US EPA Label, 5566 Engine hrs, Allison 2200 4 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19- 14X Drive Axles, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 214,259 Mi Asset located in: Lake Worth, TX	1966	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFCXJDJZ7465 C/W: Cummins B 6 Cylinder 6.7 L 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10762.9 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 256 in Wheelbase, Morgan 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 379,528 Mi Notes: SELLING WITH A REPOSESSION	
1963	3 2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB4KDKH7137 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp		AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
	Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,942 Mi Asset located in: Lake Worth, TX	1967 2 S C 2 F T R 5	1967 2018 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWFB4JHJH4986 C/W: Detroit DD5 4 Cylinder Diesel Engine 2018 US EPA Label, Requires Diesel Exhau Fluid, 7569.8 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 Rears, 26000.0 lb GVWR, Air Ride Cab, 111 5, Airliner Air Ride Suspension, 270 in	S/N: 1FVACWFB4JHJH4986 C/W: Detroit DD5 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7569.8 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000.0 lb GVWR, Air Ride Cab, 11R22. 5, Airliner Air Ride Suspension, 270 in Wheelbase, PTO, AMH 26 ft x 102 in Wide x 97
1964	4 2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC5JDJH4350 C/W: Cummins 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Automatic		in High Body, Liftgate, Asset includes a 2.5Ton pallet jack and straps Usage: 288,869 Mi Notes: . Asset located in: Livingston, LA	
		1968	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC6JDJK7266 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7811 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Steel, 295 /75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, AMH 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 259,719 Mi	

			r age 191 01 381
Lot #	Details	Lot #	Details
1969	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC1JDJS4825 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17126 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 28 ft x 102 in Wide x Body, Liftgate Usage: 431,154 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	1973	2016 Freightliner M2 4x2 Van Truck S/N: 3ALACWDT2GDHN0995 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2018 US EPA Label, 7610 Engine hrs, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 589,467 Mi Asset located in: Lake Worth, TX E OF 5 - Lot #'s: 1974, 1975, 1976, 1977, 1978
	Asset located in: Midland, TX	 -	E OF 3 - Lot # 5. 1974, 1973, 1970, 1977, 1976
1970	2017 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWCY4HDJF0552 C/W: Cummins ISL 6 Cylinder Diesel 270 hp Engine, Requires Diesel Exhaust Fluid, 8157 Engine hrs, Engine Brake, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 215 in Wheelbase, MORGAN 18 ft x 102 in Wide x 97 in High Body, Liftgate	1974	2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACXDT2GDHA4391 C/W: Cummins ISB 6 Cylinder 6.7 L 280 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 271 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 in High Body, Liftgate Usage: Not Available
	Usage: 305,761 Mi Asset located in : Humble, TX		Asset located in: Lake Worth, TX
1971	2017 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT8HDJA1678 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 316,107 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN	1975	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDU2GHGW9627 C/W: Cummins ISB 6 Cylinder 6.7 L 200 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8376 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 6.14:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 294,823 Mi Asset located in: Lake Worth, TX
	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	1976	2016 Freightliner M2 106 4x2 Van Truck
CHOIC 1972	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 1972, 1973 2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT8GDHM0083 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220	-	S/N: 1FVACWDT7GHHG9662 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 374,343 Mi Notes: SELLING WITH A REPOSESSION
	hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 5608 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb		Accet leasted in: Lake Worth TY

Exhaust Fluid, 5608 Engine hrs, Allison 2100
Automatic Transmission, 10000 lb Front Axle,
19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb
GVWR, Steel, 11R22.5, Spring Suspension, 252
in Wheelbase, Morgan 24 ft x 102 in Wide x
103 in High Body, Liftgate, PROFESSIONALLYMAINTAINED-FLEET-VEHICLE-PAG
Usage: 180 227 Mi Usage: 180,227 Mi

Asset located in: Lake Worth, TX

			Page 192 of 581
Lot #	Details	Lot #	Details
1977	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT6GHHK2059 C/W: Cummins ISB6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8186 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 234 in Wheelbase, Morgan 22 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 170,085 Mi Asset located in: Lake Worth, TX	1980A	2020 International MV607 SBA 4x2 Van Truck S/N: 1HTEUMML4LH377008 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7035 Engine hrs, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 275 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 248,149 Mi Asset located in: Lake Worth, TX
 1978		1001	2019 International MV607 4x2 Van Truck
1976	2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT3GDHM9628 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11463 Engine hrs, 6-Speed Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 334,137 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A	1981	S/N: 3HAEUMML6KL437363 C/W: Cummins B 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, 7555 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 271 in Wheelbase, AMH 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 250,820 Mi Asset located in: Lake Worth, TX
	REPOSESSION AFFIDAVIT AND MAY NOT BE	1982	2020 International MV607LP 4x2 Moving Van
	ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		Truck
1979	Asset located in: Humble, TX 2015 Freightliner M2 106 4x2 Moving Van Truck S/N: 1FVACXDT1FHGJ9796 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 7175.8 Engine hrs, Eaton Fuller FO-6406B Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, 295/75R22.5 Front Tires, 275		Diesel 220 hp Engine, 2019 ÚS EPA L Requires Diesel Exhaust Fluid, 6412 E Allison Automatic Transmission, 900 Axle, 17500 lb Rears, 25999 lb GVWR /70R19.5, Air Ride Suspension, 187 ir
	/80R22.5 Rear Tires, Spring Suspension, 270 in Wheelbase, Wabash 22 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 191,299 Mi	CHOICE	E OF 4 - Lot #'s: 1983, 1984, 1985, 1986
	Asset located in: Lake Worth, TX	1002	2010 International 4200 Av2 Maying Van Trusk
1980	2020 International MV607 4x2 Van Truck S/N: 3HAEUMML2LL115482 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 552 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 54,274 Mi Notes: ODOMETER REPLACED AT 171,023 MILES -PLEASE SEE INSPECTION REPORT, ACTUAL MILEAGE IS 225,297 Asset located in: Lake Worth, TX	-1983 	2019 International 4300 4x2 Moving Van Truck S/N: 1HTMMMML5KH382549 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3964 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.57:1 Axle Ratio, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Ball Hitch Usage: Not Available Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1984	34 2019 International 4300 4x2 Van Truck S/N: 1HTMMMML5KH519554 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 4381 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.29:1 Axle Ratio, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 202,297 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX	1988	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML8KL382233 C/W: Cummins ISB6.7 6.7 L Diesel Engine, 2019 US EPA Label, 3703 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, Ball Usage: 150,368 Mi Asset located in: Lake Worth, TX
		1989	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML2KH518412 C/W: Cummins B6.7 220 6.7 L Diesel Engine, 2018 US EPA Label, 4610 Engine hrs, Automatic Transmission, 10000 lb Front Axle,
1985	2019 International 4300 4x2 Dry Van Van Truck S/N: 1HTMMMML6KH382477 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3654 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.57:1 Axle Ratio,		17500 lb Rears, 25999.0 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Ball Usage: 190,917 Mi
		1990	Asset located in: Lake Worth, TX 2019 International 4300 4x2 Moving Van Truck
	11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Ball Hitch Usage: 155,349 Mi Asset located in : Lake Worth, TX	1990 - -	S/N: 3HAMMML7KL383325 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3819 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor
1986	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML2KL519280 C/W: Cummins B6.7 220 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, International IROS Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x Body, Walk-Up Ramp, Ball Usage: Not Available		MS-17-14X-3DFL Drive Axles, 5.57:1 Axle Ratio 11783 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 156,125 Mi Asset located in: Lake Worth, TX
		сноіс	E OF 4 - Lot #'s: 1991, 1992, 1993, 1994
СНОІС	Asset located in: Lake Worth, TX CHOICE OF 4 - Lot #'s: 1987, 1988, 1989, 1990		2019 International 4300 4x2 Van Truck S/N: 3HAMMMML4KL382553 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra
1987	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML1KH382497 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3778 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension,		Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3570 Engine hrs, Allison 2200 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x Body, Ball Hitch Usage: 165,388 Mi Asset located in: Lake Worth, TX
	272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in High Body, Pintle Hitch Usage: 146,547 Mi Asset located in: Lake Worth, TX	1992	2019 International 4300 4x2 Van Truck S/N: 3HAMMML0KL382789 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4077 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body Usage: 180,545 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1993	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML6KH514928 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4766 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.29:1 Axle Ratio, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Walk-Up Ramp, Ball Hitch Usage: 211,781 Mi Asset located in: Lake Worth, TX	1998	2019 International 4300 4x2 Moving Van Truck S/N: 3HAMMMMLXKL383447 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4243 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body Usage: 188,842 Mi Asset located in: Lake Worth, TX 2019 International 4300 4x2 Van Truck
1994	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML3KL382012 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3995 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in High Body, Walk-Up Ramp Usage: 162,399 Mi Asset located in: Lake Worth, TX		S/N: 1HTMMMML8KH514655 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4722 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.29:1 Axle Ratio, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 207,720 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX
CHOIC	E OF 5 - Lot #'s: 1995, 1996, 1997, 1998, 1999	2000	2019 International 4300 SBA 4x2 Van Truck
1995	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML8KH514851 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Walk-Up Ramp Usage: 169,750 Mi		S/N: 3HAMMMML3KL559187 C/W: Cummins B6.7 6 Cylinder 6.7 L 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5636 Engine hrs, Allison 2500 5- Speed Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 4.63:1 Axle Ratio, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, SMYRNA TRUCK 26 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 147,079 Mi
1996	Asset located in: Lake Worth, TX 2019 International 4300 4x2 Van Truck	_	Asset located in: Lake Worth, TX
1997	S/N: 3HAMMMMLXKL382265 C/W: Cummins ISB 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4095 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25000 lb GVWR, 11R22.5, International IROS Air Ride Suspension, 272 in Wheelbase, Supreme Corp 26 ft x 102 in Wide x 98 in High Body, Walk-Up Ramp Usage: 173,191 Mi Asset located in: Lake Worth, TX 2019 International 4300 4x2 Van Truck	2001	2018 International Durastar 4300 SBA 4x2 Van Truck S/N: 1HTMMMML9JH589637 C/W: Cummins 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x
177/	S/N: 1HTMMMMLXKH519808 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4042 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 175,179 Mi Asset located in: Lake Worth, TX		102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 233,934 Mi Asset located in : Humble, TX

			1 450 175 01 501	
Lot #	Details	Lot #	Details	
2002	S/N: 3HAMMMML9JL589552 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8327 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Spring Suspension, 256 in Wheelbase, 26 ft x x 104 in High Body, Liftgate Usage: 262,670 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	2006	2016 International 4300 4x2 Van Truck S/N: 3HAMMMML4GL740046 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17251 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 260 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 222,929 Mi Asset located in: Lake Worth, TX	
		2007	2016 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML9GH012776	
2003			C/W: Cummins ISB V6 6.7 L 240 hp Engine, 2015 US EPA Label, 7922 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 15999 lb Rears, 25999.0 lb GVWR, 295/75R22. 5, Supreme 26 ft x 96 in Wide x 102 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 247,400 Mi Asset located in: Lake Worth, TX	
	Suspension, Morgan 28 ft x 102 in Wide x 109 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,961 Mi Asset located in: Lake Worth, TX	2008	2015 International 4300 4x2 Van Truck S/N: 1HTMMMMLXFH710991 C/W: Cummins 6 Cylinder 6.7 L Diesel 240 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb	
	HOICE OF 2 - Lot #'s: 2004, 2005		Rears, 25999 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 28 ft x 96 in Wide x Body, Liftgate	
2004	2018 International 4300 4x2 Van Truck 6/N: 1HTMMMML6JH350045 6/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9004 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 7500 lb Rears, 25999 lb GVWR, 11R22.5, Air		Usage: 491,297 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
	Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 275,971 Mi Asset located in : Lake Worth, TX	2009	2015 International Durstar 4300 4x2 Van Truck S/N: 3HAMMML2FL040069 C/W: Cummins B6.7 220 6 Cylinder 6.7 L	
2005	2017 International 4300 4x2 Van Truck S/N: 1HTMMMML2HH654807 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 6442 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 179,428 Mi		Di Ti Ri Si 1(U: M A Yi Pl	Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	2010	2008 Hino 268 4x2 Van Truck S/N: 5PVNE8JV582S50883 C/W: Hino J08E-TV 6 Cylinder 469 cid Diesel 220 hp Engine, 2007 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 112,668 Mi Asset located in: Lake Worth TX	

Lot #	Details	Lot #	Details	
2011	2008 International 4300 4x2 Van Truck S/N: 1HTMMAAL38H572202 C/W: International MaxxForce DT 7.6 L Diesel 225 hp Engine, 2007 US EPA Label, CARB Compliant, 9586 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 226 in Wheelbase, Morgan 26 ft x 102 in Wide x 93 in High Body, Liftgate Usage: 245,473 Mi Asset located in: Lake Worth, TX	2017	2021 Chevrolet 4500 4x2 COE Van Truck S/N: 54DCDW1D5MS205390 C/W: Isuzu V8 Gasoline Engine, 2021 US EPA Label, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Morgan 20 ft x 96 in Wide x 91 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX	
		2018	2018 Chevrolet 4500 4x2 COE Van Truck S/N: 54DCDW1B6JS807385	
2012	2005 International 4300 SBA 4x2 Van Truck S/N: 1HTMMAAN05H119538 C/W: International D226 6 Cylinder 7.6 L Diesel 225 hp Engine, 2004 US EPA Label, 10254 Engine hrs, Eaton Fuller Manual Transmission, Aluminum Wheels, 295/75R22.5, Spring Suspension, Morgan 26 ft x 102 in Wide x 104		Label, Automatic Transmissic Axle, 11020 lb Rears, 14500 lb /70R19.5, Spring Suspension, Wheelbase, Smyrna 16 ft x 10 in High Body, Liftgate Usage: 174,853 Mi	
	in High Body, Curbside Door, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: 196,863 Mi	2019	2019 Hino 195 4x2 COE Van Truck S/N: JHHRDM2H6KK007187	
	Asset located in: Lake Worth, TX	_	C/W: Hino J05E-TP 4 Cylinder Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel	
2013	2003 International 4300 SBA 4x2 Van Truck S/N: 1HTMMAAM63H583373 C/W: International DT466 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, Aluminum Wheels, 295/75R22.5, Spring Suspension, 256 in Wheelbase, Morgan 24 ft x 102 in Wide x 96 in High Body, Liftgate Usage: 503,203 Mi	Exhaust Fluid, Automatic lb Front Axle, 13660 lb Re 225/70R19.5, Spring Sus Wheelbase, Morgan 16 ft High Body, Liftgate x Usage: 203,811 Mi	Exhaust Fluid, Automatic Transmission, 7270 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 152 in Wheelbase, Morgan 16 ft x 96 in Wide x 91 in High Body, Liftgate	
	Notes: DEFICIENCIES NOTED - PLEASE SEE			
	THE INSPECTION REPORT Asset located in: Humble, TX		E UF 3 - Lot #'s: 2020, 2021, 2022	
2014	1998 International 4700 4x2 Moving Van Truck S/N: 1HTSCABM3WH533169 C/W: International V8 7.3 L Diesel Engine, US EPA Label, Spicer 5-Speed Manual Transmission, Spring Suspension, 188 in Wheelbase, Timpte 16 ft x 96 in Wide x 84 in High Body Usage: 41,973 Mi Asset located in: Lake Worth, TX	2020	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B2KS806624 C/W: GM V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, 150 in Wheelbase, Morgan 16 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 187,646 Mi	
2015	2007 GMC C5500 4x2 Van Truck	Ī	Asset located in: Lake Worth, TX	
	S/N: 1GDE5C1207F411068 C/W: GM Duramax 6.6 L Diesel Engine, 2006 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 285/70R19.5, Spring Suspension, 208 in Wheelbase, 18 ft x 96 in Wide x 90 in High Body, Liftgate Usage: 292,010 Mi Notes: **Shelving built in box area** Asset located in: Humble, TX	2021	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W168K7008461 C/W: Isuzu 4HK1TC 4 Cylinder 5.2 L Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6880 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, Steel, 215/85R16, Spring Suspension, 151 in Wheelbase, Morgan 16 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 236,438 Mi Asset located in: Lake Worth, TX	
2016	2006 Nissan 4x2 COE Van Truck S/N: JNAPA80H66AS55788 C/W: Hino J08E-UJ 6 Cylinder 469 cid Diesel 230 hp Engine, 2007 US EPA Label, Automatic Transmission, 9480 lb Front Axle, 18000 lb Rears, 25995 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 259,568 Mi Asset located in: Lake Worth, TX		TOTAL	

Lot #	Details	Lot #	Details
2022	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W16XK7009739 C/W: Isuzu 4HK1TC 4 Cylinder Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, 215/85R16, Spring Suspension, 151 in Wheelbase, 16 ft x 96 in Wide x 94 in High Body, Liftgate Usage: 271,219 Mi Asset located in: Lake Worth, TX	2030	2019 Ford E350 4x2 Van Truck S/N: 1FDWE3FS8KDC22914 C/W: Ford 6.8 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, Steel, 225 /75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 78,825 Mi Asset located in: Humble, TX 2019 Ford E350 4x2 Van Truck
2023	2018 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B9JS802729 C/W: V8 6.0 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, Supreme 16 ft x 96 in Wide x 94 in High Body, Liftgate Usage: 105,477 Mi		S/N: 1FDWE3FS4KDC15555 C/W: Gasoline Engine, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, 225/75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 81,416 Mi Asset located in: Lake Worth, TX
2024	Asset located in: Lake Worth, TX 2016 Isuzu NPR 4x2 COE Extended Cab Van Truck S/N: 54DC4J1B8GS803916 C/W: Isuzu Gasoline Engine, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Supreme 16 ft	2038 2015 Ford E-350 4x2 14-Sea S/N: 1FDEE3FS2FDA21995 C/W: Air Conditioner, Autom V10 6.8 L Gasoline Engine, 2 225/75R16, Spring Suspensi Wheelbase Usage: Not Available Asset located in: Lake Worth S/N: 5WEASSKP5DH416814 C/W: Air Conditioner, Allison Transmission, 5483 hrs Carr International MaxxForce 7 V hp Engine, 2012 US EPA Lab Outer Wheels, 255/70R22.5, Suspension, 305 in Wheelba Usage: 173,055 Mi	C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2014 US EPA Label, 225/75R16, Spring Suspension, 156 in Wheelbase
	x 102 in Wide x 85 in High Body, Curbside Door, Liftgate Usage: 137,402 Mi Asset located in : Lake Worth, TX		2013 International PC505 4x2 Bus S/N: 5WEASSKP5DH416814 C/W: Air Conditioner, Allison Automatic
2025	2012 Mitsubishi Fuso 4x2 COE Van Truck S/N: JL6BNG1A5CK002630 C/W: Fuso F1C 3.0 L Engine, 2011 US EPA Label, Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 15995 lb GVWR, 215 /75R17.5, Spring Suspension, 153 in		International MaxxForce 7 V8 6.4 L Diesel 260 hp Engine, 2012 US EPA Label, Aluminum Outer Wheels, 255/70R22.5, Air Ride Suspension, 305 in Wheelbase
	Wheelbase, 16 ft x 102 in Wide x 94 in High Body, Liftgate Usage: 169,508 Mi Notes : LOCATED-IN-LAKE WORTH-TX Asset located in : Lake Worth, TX	2040	2011 BlueBird 4x2 36-Seat School Bus S/N: 1BAKGC5A2CF286372 C/W: Air Conditioner, Automatic Transmission, V8 Liquid Propane Gas (LPG) Engine, 11R22.5, Spring Suspension, 275 in Wheelbase
2027	2015 Ram 5500 4x2 Van Truck S/N: 3C7WRMDL6FG506015		Usage: 105,391 Mi Asset located in : Humble, TX
	C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, Morgan 16 ft x 96 in Wide x 80 in High Body, Curbside Door, Liftgate Usage: 169,865 Mi Asset located in: Lake Worth, TX	2041	2012 BlueBird 4x2 47-Seat School Bus S/N: 1BAKGC5A8CF286375 C/W: Air Conditioner, Automatic Transmission, V8 Liquid Propane Gas (LPG) Engine, 2010 US EPA Label, 11R22.5, Spring Suspension, 274 in Wheelbase Usage: 118,477 Mi Asset located in: Humble, TX
2029A	2020 GMC Savana G3500 4x2 Van Truck S/N: 1GD07RFP9L1182263 C/W: V6 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 74 in High Body Usage: 89,341 Mi Notes: TITLE SHOWS NOT ACTUAL MILEAGE Asset located in: Humble, TX	2042	2007 Chevrolet C5500 4x2 26-Seat Transit Bus S/N: 1GBE5V1G67F425251 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, GM V8 8.1 L Gasoline Engine, 2007 US EPA Label, 225/70R19.5, Spring Suspension, 232 in Wheelbase, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 80,972 Mi Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2043	2021 Nissan NV200 4x2 Cargo Van S/N: 1N6BF0KY5MN807503 C/W: V6 4.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 3825 lb Front Axle, 5875 lb Rears, 9100 lb GVWR, 245/70R17, Spring Suspension, 146 in Wheelbase, 9 ft x x 50 in High Body Usage: 80,655 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	(Inoperable) S/N: 3C6TRVDG2KE531385 C/W: V6 3.6 L Gasoline 280 hp Ene EPA Label, Automatic Transmissic Front Axle, 5291 lb Rears, 3.86:1 A 8900 lb GVWR, 225/75R16, Spring 159 in Wheelbase, 11 ft x 80 in Wi High Body, Curbside Door Usage: Not Available Notes: TEXAS BUYERS MUST STOTO SIGN REQUIRED DOCUMENTS PROCESS TITLE Asset located in: Lake Worth, TX 2050 2019 Ram ProMaster 2500 4x2 Ca S/N: 3C6TRVDGXKE557829 C/W: V6 3.6 L Gasoline Engine, 20 Label, Automatic Transmission, 40 Axle, 5291 lb Rears, 8900.0 lb GVW/75R16, Spring Suspension, 159 ir 11 ft x x 76 in High Body, Curbside Usage: 44,182 Mi Notes: DEFICIENCIES NOTED - PL THE INSPECTION REPORT; TEXAS	2019 Ram ProMaster 2500 4x2 Cargo Van (Inoperable) S/N: 3C6TRVDG2KE531385 C/W: V6 3.6 L Gasoline 280 hp Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 3.86:1 Axle Ratio, 8900 lb GVWR, 225/75R16, Spring Suspension,
2044	Asset located in: Midland, TX 2016 Ford Transit 350 Passenger Van S/N: 1FBZX2ZM3GKA06205 C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch, EQUIPMENT-FROM-A-PRIMORIS-		High Body, Curbside Door Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	SERVIČES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX		C/W: V6 3.6 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 8900.0 lb GVWR, 225 /75R16, Spring Suspension, 159 in Wheelbase,
2045	2014 Freightliner Sprinter 3500 4x2 Van Truck S/N: WDPPF4CC7E9564671 C/W: V6 3.0 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 4080 lb Front Axle, 7720 lb Rears, 11030 lb GVWR, 215/85R16, Spring Suspension, 16 ft x 86 in Wide x 78 in High Body, Curbside Door, Walk-		Usage: 44,182 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	Up Ramp Usage: 313,155 Mi Asset located in : Lake Worth, TX	2051	2019 GMC Savana 1500 Cargo Van S/N: 1GTW7BFP3K1277096 C/W: V6 4.3 L Gasoline Engine, 2019 US EPA
2046	2024 Chevrolet Express 2500 Cargo Van S/N: 1GCWGAF70R1101434 C/W: V8 6.6 L Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera, Towing Hitch		Label, Automatic Transmission, Air Conditioner, Power Windows, Powe Usage: 91,916 Hr
	Usage: 131 Mi Asset located in : Lake Worth, TX	2052	2007 Chevrolet 2500 Express 4x2 Cargo Van
2047	2016 Ford Transit 250 4x2 Cargo Van S/N: 1FTYR2ZM4GKA77642 C/W: Ford V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5515 lb Rears, 9000 lb GVWR, 235 /65R16, Spring Suspension, 138 in Wheelbase, 9 ft x 78 in Wide x 56 in High Body Usage: 214,134 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED; DOCUMENTS TO PROCESS TITLE; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; Asset located in: Humble, TX		S/N: 1GCGG25V471223513 C/W: Chevy V8 4.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245 /75R16, Spring Suspension, 139 in Wheelbase, 9 ft x 72 in Wide x 54 in High Body, Curbside Door Usage: 135,450 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
2048	2020 Ram Promaster Cargo Van S/N: ZFBHRFAB3L6R54595 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 2053, 2054	5001	2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: Not Available
2053	2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E25M1496971 C/W: 4 Cylinder 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 215 /55R16, 121 in Wheelbase, 6 ft x x 44 in High Body Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	PROCESS TITLE	5002	2024 Raytree RMC72 72 in Skid Steer Brush Cutter (Unused)
2054	Asset located in: Midland, TX 2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E27M1496972 C/W: ford 4 Cylinder 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 205/55R16, 121 in Wheelbase, 6 ft x 72 in Wide x 44 in High Body		S/N: C20241007112 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	in Wide x 44 in High Body Usage: 46,847 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	5003	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	5004	All-Star 80 in Skid Steer Brush Cutter (Unused)
2055	2016 Ford Transit 150 4x2 Cargo Van S/N: 1FTYE1YM9GKB48843 C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5070 lb Rears, 8600 lb GVWR, 235/65R16, Spring Suspension, 132 in Wheelbase, 9 ft x 96 in Wide x 55 in High Body, Curbside Door Usage: 144,833 Mi		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
		5005	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	5006	All-Star 80 in Skid Steer Brush Cutter (Unused)
	Asset located in: Lake Worth, TX		S/N: Not Available
2056	2020 Mercedes-Benz 135 WB 4x2 Cargo Van		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: W1YV0CEY3L3688564 C/W: Mercedes-Benz 2.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 3307 lb Front Axle, 3307 lb Rears, 6614.0 lb GVWR, 225/55R17, Spring Suspension, 136 in Wheelbase	5007	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 74,107 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	5008	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5000	Asset located in: Lake Worth, TX 2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: HL00249 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5009	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5010	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5011	2023 Mower King SSRC 72 in Skid Steer Brush Cutter S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESENT THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESENT THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5018 2024 Wolverine BC-13-72W 72 in Ski Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESENT THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESENT	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5012	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC20240919 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		5010	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5013	Asset located in: Lake Worth, TX 2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5014	2024 Wolverine BC-13-72W 72 in Skid Steer		Asset located in: Lake Worth, TX	
	Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5019	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		5020	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5015	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Wolverine BC-13-72W 72 in Skid Steer Pruch Cutter (Uppeed)	5021	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5022	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		5023	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	5024	All-Star 72 in Skid Steer Brush Cutter (Unused)	
5016	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5025	2021 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC21092604 Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5026	Wolverine 70 in Pallet Skid Steer Brush Cutter S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	5031	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202409114 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5027	THESE Asset located in: Corsicana, TX 2024 Suihe SSBC 66 in Skid Steer Brush Cutter	5032	2023 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW02312 Usage: Not Available
3027	(Unused)		Asset located in: Lake Worth, TX
	S/N: 001602498 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5033	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5034	2024 Handy HAB72 72 in Skid Steer Broom
5028	2024 Suihe SSBC 0 ft 66 in Skid Steer Brush Cutter (Unused) S/N: 001602505 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		(Unused) S/N: AB202409111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5035	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409110 Usage: Not Available
5029	Quantity of (2) 2024 Wolverine SBM-12-72W 72 in Sickle Bar Skid Steer Mower (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5036	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5037	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available
5030	2024 Handy HSBM72 72 in Sickle Bar Skid		Asset located in: Lake Worth, TX
	Steer Mower (Unused) S/N: SBM202409115 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5038	JCT 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5039	Bobcat 84 in Skid Steer Angle Broom S/N: 231412786 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5040	2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5047	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202406543 Usage: Not Available Asset located in: Lake Worth, TX	
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5048	5048 2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202409560 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5041	2024 Wolverine BBS-11-72W 72 in Skid Steer		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Sweeper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5049	2024 Raytree RMH680 Skid Steer Breaker (Unused) S/N: HH20241012180 Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHEOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRESTHE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHEOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRESTHE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5051 2024 Jisan JSB400SL Skid Steen (Unused) S/N: 2404298 Usage: Not Available Notes: THE PRODUCT IMAGES SHEOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRESTHE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5052 2024 Jisan JSB400SL Skid Steen (Unused) S/N: 2404295 Usage: Not Available Notes: THE PRODUCT IMAGES SHEOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRESTHE ACTUAL PRODUCT IMAGES SHOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRESTHE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5053 2024 Elephant EPB400SL Skid Stid Stid Stid Stid Stid Stid Stid St	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5042	2024 Wolverine PBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW00289 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: 2404298	
5043	2024 Wolverine MBS-11-48W 48 in Mini Skid Steer Sweeper (Unused) S/N: ZW00327 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: 2404295 Usage: Not Available Notes : THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5045	2024 TOFT TOFT750 Skid Steer Post Driver (Unused)			
	S/N: JW43Z5685 Usage: Not Available Asset located in : Lake Worth, TX		2024 Elephant EPB400SL Skid Steer Breaker	
5046	2024 TOFT TOFT680 Skid Steer Post Driver (Unused) S/N: JW40Z17058 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5054	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: CP2406092 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5062	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409144 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5055	2024 Trojan TH35SSL Skid Steer Breaker (Unused) S/N: SB30YOM20247065 Usage: Not Available Asset located in: Lake Worth, TX	5063	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00017 Usage: Not Available Asset located in: Lake Worth, TX	
5056	Mini Skid Steer Breaker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5065	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00018 Usage: Not Available Asset located in: Lake Worth, TX	
5057	2024 TOFT TOFT750 Skid Steer Breaker (Unused) S/N: JW43Z5799 Usage: Not Available Asset located in: Lake Worth, TX		2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5058	2024 TOFT TOFT680 Skid Steer Breaker (Unused) S/N: JW40Z17265 Usage: Not Available Asset located in: Lake Worth, TX 2024 Handy HPD680 Skid Steer Post Driver		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	(Unused) S/N: PD202409143 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES O MAY NOT BE AN EXACT REPRES	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused)
5060	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409145 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241009192	
5061	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409142 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5068	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241012196 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5075	2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused) S/N: VR202409472 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused)	
5069	Asset located in: Lake Worth, TX 2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241012195 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE		S/N: VR202409474 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Roller (Unused) S/N: VR202409473 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY A	Roller (Unused) S/N: VR202409473
5070	2024 Jisan JSB400SLT Skid Steer Post Driver (Unused) S/N: CP2407183 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5078	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Raytree RMVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR20241012184 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5071	Asset located in: Lake Worth, TX 2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00381		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5079	2024 Suihe SSVR-72 72 in Skid Steer Vibratory Roller (Unused)	
5072	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00384 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 001300876 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
5073	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00382		FC M/ TH	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Usage: Not Available Asset located in: Lake Worth, TX	5080	Asset located in: Lake Worth, TX 2024 Wolverine VR-11-66W 66 in Skid Steer	
5074	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00383 Usage: Not Available Asset located in: Lake Worth, TX		Vibratory Roller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5081	TMC 72 in Skid Steer Vibratory Roller S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5087	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES
5082	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused) S/N: T20241008159 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	-5088	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5083	2024 Handy HST48 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: 8 In Dirt & Rock Chain, Crumbling Shoe Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5084	2024 Handy HST48 48 in Skid Steer Trencher (Unused)		Asset located in: Lake Worth, TX
	S/N: TR202409613 C/W: 8 In Dirt & Rock Chain, Crumbling Shoe Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5090	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5085	2024 Suihe SST-1000/200 Skid Steer Trencher (Unused) S/N: 001702343 C/W: Crumbing Shoe THE PRODUCT IMAGES		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5086	2024 Suihe SST-1000/200 Skid Steer Trencher (Unused) S/N: 001702342 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
		5091	Asset located in: Lake Worth, TX 2024 Handy HSD96 96 in 6 Way Skid Steer Dozer (Unused) S/N: SD202409302 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5092	2024 Handy HSD96 96 in 6 Way dozer Skid Steer Dozer (Unused) S/N: SD202409300 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HSD96 96 in 6 Way dozer Skid	5097	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused) S/N: 031789880 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
0070	Steer Dozer (Unused) S/N: SD202409301 Usage: Not Available	5098	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Wolverine DB-15-84W 84 in Angle Skid
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	0030	Steer Dozer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5094	2024 Raytree RSWD96 94 in Six Way Skid Steer Dozer (Unused)	5099	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	S/N: SW20241012042 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		All-Star 72 in Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5100	Mid-State 72 in Skid Steer Dozer (Unused)
5095	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 031789472 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5101	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202409595 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5096	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer	5102	2024 Handy HSGB96 96 in Skid Steer Grader
3090	Dozer (Unused) S/N: 031789296 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		(Unused) S/N: GB202409594 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5103	2024 Handy HGB86 96 in Skid Steer Grader (Unused) S/N: GB86202409217 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5104	2024 Handy HGB86 96 in Heavy Duty Skid Steer Grader (Unused) S/N: GB86202409216 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5111	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5105	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available	5112	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Wolverine TL-12-72W 72 in Skid Steer
5106	Asset located in: Lake Worth, TX 72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5112	Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5107	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5108	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5113	2024 Suihe SSTL 72 in Skid Steer Tiller (Unused) S/N: 002402687 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
5109	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5114	2024 Suihe SSTL 72 in Skid Steer Tiller (Unused) S/N: 002402685 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5110	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5115	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5116	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Details	Lot #	Details
All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5124	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409391 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate
All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409392 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5125	Asset located in: Lake Worth, TX Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409390 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5126	2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR
2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Wolverine ADB-13-1218R Skid Steer
Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409389 C/W: (1) 10 in bit, (1) 12 in bit, (1) 18 in bit, one crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	012/	Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409392 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409390 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409389 C/W: (1) 10 in bit, (1) 12 in bit, (1) 18 in bit, one crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409392 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409390 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409389 C/W: (1) 10 in bit, (1) 12 in bit, (1) 18 in bit, one crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5128	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5133	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503502 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5129	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20241012230 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR	5134	S/N: L09284 C/W: Quick Attach 2 in Hex Head Auger Usage: Not Available Asset located in: Lake Worth, TX
	PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5135	2018 Bobcat 15C Skid Steer Auger S/N: 944261257 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
5130	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20241012229 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5136	16 in Mini Skid Steer Auger (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5137	Quantity of (3) Mini Skid Steer Augers (Unused) S/N: Not Available C/W: (1) 16 in, (1) 12 in, (1) 8 in Bits Usage: Not Available Asset located in: Lake Worth, TX
5131	2024 Suihe SSA Skid Steer Auger (Unused) 6/N: 002503461 6/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR LLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5138	Pengo 10-2500 Auger Bit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5139	2024 Raytree RMSC78 72 in Skid Steer Soil Conditioner S/N: SC20241010053 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5132	5132 2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503471 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
		5140	Level Best LBSS6 72 in Skid Steer Laser Grading Box Blade S/N: 1187 Usage: Not Available Asset located in: Lake Worth, TX
		5141	Raytree 28 in Skid Steer Hyd Pole Jack (Unused) S/N: 20231025031 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5142	2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409146 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HBC72 Concrete Crusher (Unused)	5149	2024 Handy HSRC12 Rotating Skid Steer Pole Clamp (Unused) S/N: RC202409627 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
3143	S/N: CC202409147 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5150	2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5144	2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5151	Asset located in: Lake Worth, TX 2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: RP202409465 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5145	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20241010172 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5152	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhonor FW-13-15000G 15000 lb Skid Steer Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5146	2024 Landhonor CC-11-08V 24 in Skid Steer Concrete Crusher (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5153	2024 Industrias America Post/Tree Puller (Unused) S/N: HPOST202421670 Usage: Not Available Asset located in: Lake Worth, TX
5147	2024 Handy HFB52 Skid Steer Feller Buncher (Unused) S/N: FB202409119 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5154 5155	2024 Industrias America Post/Tree Puller (Unused) S/N: POST202421749 Usage: Not Available Asset located in: Lake Worth, TX 2024 Industrias America Post/Tree Puller (Unused) S/N: POST202421748 Usage: Not Available
5148	2024 Handy HSRC12 Rotating Skid Steer Pole Clamp (Unused) S/N: RC202409626 Usage: Not Available	5156	Asset located in: Lake Worth, TX All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5157	Asset located in: Lake Worth, TX All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5158	All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5165	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: HL01192 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5159	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5160	Kubota PS2086 84 in Skid Steer Grain Planter S/N: 1064217K C/W: 3 Pt Hitch Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5166	2024 Landhonor PR-12-72W 72 in Skid Steer
5161	2024 Handy HSNC78 72 in Skid Steer Power Rake (Unused) S/N: SC202409110 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Power Rake (Unused) S/N: HL01193 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
5162	2024 Handy HSNC78 72 in Skid Steer Power		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Rake (Unused) S/N: SC202409112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5167	2024 Raytree RTSG30 31 in Transverse Skid Steer Stump Grinder (Unused) S/N: TS20241012241 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5163	2024 Handy HSNC78 72 in Skid Steer Power	5168	Asset located in: Lake Worth, TX
	Rake (Unused) S/N: SC202409111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Raytree RMSG29 29 in Skid Steer Stump Grinder (Unused) S/N: SG20241010315 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5164	2024 Landhonor PR-12-72W 72 in Skid Steer		Asset located in: Lake Worth, TX
	S/N: HL01191 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5169	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409926 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5170	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409924 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	THE ACTUAL PRODUCT	5170	2024 Handy HSSG27 27 in S Grinder (Unused) S/N: SG202409924 Usage: Not Available Notes: THE PRODUCT IMAG FOR ILLUSTRATION PURPO

Lot #	Details	Lot #	Details
5171	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409925 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5179	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012450 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5172	Quantity of (2) 2024 Landhonor BH-11-06H Big Arm Skid Steer Backhoe (Unused) S/N: Not Available C/W: 18 In Bucket, One Crate Usage: Not Available Asset located in: Lake Worth, TX	5180	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012447 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5173	All-Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX	5181	Asset located in: Lake Worth, TX 2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused)
5174	All Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX		S/N: DRM20241008440 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5175	Bobcat 709FDS Skid Steer Backhoe S/N: 270020062 C/W: NO BUCKET Usage: Not Available Asset located in: Lake Worth, TX	5182	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409470 Usage: Not Available
5176	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused) S/N: HM20241012049 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5177	2024 Raytree RMDM72A 72 in Skid Steer Mulcher (Unused) S/N: HM20241009048 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409469 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5178	Asset located in: Lake Worth, TX 2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012445 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5184	2024 Handy HSDM70 Skid Steer Mulcher (Unused) S/N: DM202409332 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		'5185	2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124060901E Usage: Not Available Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
5186	2024 Raytree RMDM70 60 in Skid Steer Mulcher (Unused) S/N: DM20241012194 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5194	All-Star 72 In Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5195	2024 Landhonor RG-11-5000G Rotating Skid Steer Grapple (Unused) S/N: HL00372 Usage: Not Available
5187	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused)		Asset located in: Lake Worth, TX
	S/N: LM20241009067 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5196	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5188	Asset located in: Lake Worth, TX 2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241010069 C/W: THE PRODUCT IMAGES SHOWN ARE	5197	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5198	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5189	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241009068 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5199	72 in Skid Steer Grapple Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
<u></u>	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5200	Kit Containers 48 in Skeleton Mini Skid Steer Grapple (Unused) S/N: B14E1606 Usage: Not Available
5190	All-Star 78 in E-Series Rock Skid Steer Grapple Bucket (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5201	All-Star 80 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5191	All-Star 78 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5202	All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5192	All-Star 72 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5203	All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5193	All-Star 72 In E-Series Rock Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5204	All Star 78 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5205	All Star 74 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5216	36 in Q/C Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5206	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5217	All-Star 40 in Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5207	All-Star 72 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5218	All-Star 40 in Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5208	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5219	All-Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5209	All Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5220	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5210	All-Star E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5211	All Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5221	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe SSRGB-82 82 in Skid Steer Grapple
5212	All-Star 68 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5213	All-Star 68 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5214	Mid-State 60 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5222	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5215	All Star 48 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5223	All-Star 80 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5231	Raptor 72 in Skid Steer Grapple Bucket (Unused) S/N: 23400249 Usage: Not Available Asset located in: Lake Worth, TX
5224	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5232	All-Star 68 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5225	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5233	Cat 66 in Skid Steer Grapple Bucket S/N: A4164CB50022 Usage: Not Available Asset located in: Lake Worth, TX
5226	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available	5234	30 in Mini Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5227	Asset located in: Lake Worth, TX All-Star 74 in Skid Steer Grapple Bucket (Unused) S/N: Not Available	5235	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
 5228	Usage: Not Available Asset located in: Lake Worth, TX All Star 72 in E-Series Skid Steer Grapple	5236	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available
0220	ucket (Unused) /N: Not Available sage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
5229	Asset located in: Lake Worth, TX 2024 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: Not Available	5237	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5238	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5239	2024 Suihe SSRGB-72 72 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available
5230	2024 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5240	All-Star 68 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5241	All Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5248	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808738 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5242	All-Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5243	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	5249	Asset located in: Lake Worth, TX 2024 Suihe SSR-78 78 in Skid Steer Root Rake
5244	Asset located in: Lake Worth, TX All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available		(Unused) S/N: 001808746 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5245	Asset located in: Lake Worth, TX All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5246	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808766 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5250	ASSET located in: Lake Worth, TX All-Star 78 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5251	All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5247	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808741 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	- 5252	All-Star 78 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5253	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5254	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5255	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5256	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5257	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	5269	84 in Skid Steer Ripper Scarifier (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	F070	<u> </u>
5258	Mid-State 68 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5270	2024 Handy HVSB72 72 in Screening Skid Steer Bucket (Unused) S/N: VSB202409688 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5259	Mid-State 68 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5271	2024 Handy HVSB72 72 in Screening Skid
5260	All-Star 68 in E-Series Skid Steer Root Rake (Unused)		Steer Bucket (Unused) S/N: VSB202409689 Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5261	Mid-State 60 In E-Series Skid Steer Root Rake (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5272	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: Not Available
5262	Mid-State 60 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5263	Mid-State 48 In Skid Steer Root Rake (Unused)	5273	2024 Skyway WBCT-4IN1 Backhoe Loader
	S/N: Not Available Usage: Not Available		Bucket (Unused) S/N: Not Available
	Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE
5264	All-Star 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5265	All-Star 68 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5274	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5266	All-Star 72 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	5275	2024 Raytree RMVB78F 70 in (Unused)
5267	All-Star 60 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: SB20241009346 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5268	All-Star 84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5276	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241009347 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5286	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5287	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available
5277	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241012354 C/W: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		2024 Kit Containers QT-DB-S78 78 in Skid Steer Bucket (Unused) S/N: B28J1613 Usage: Not Available Asset located in: Lake Worth, TX
5278 	Mid-State General Purpose 84 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Mid-State General Purpose 80 in Skid Steer	5289	Teran BKT26278 78 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 1220 C/W: 0.5m3 with 8HD Tips for CAT 226 - 299 Usage: Not Available
	Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5290	Asset located in: Lake Worth, TX Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5280	Mid-State 84 in Low Profile Skid Steer Bucket (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5291	Kit Containers 78 in Skid Steer Bucket (Unused) S/N: B26J1610 Usage: Not Available Asset located in: Lake Worth, TX
5281	Mid-State 84 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5292	78 in General Purpose Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5282	All-Star 80 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5293	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5283	All-Star 80 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5294	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5284	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5295	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5285	Mid-State General Purpose 78 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5296	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5306	Teran BKT26272 72 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 3142 C/W: 0.45m3 with 8 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5307	Mid-State 72 In Low Profile Skid Steer Bucket (Unused)
5297	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5308	All Star 72 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5298	Mid-State 74 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5309	All Star 68 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5299	Mid-State 74 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5310	All-Star 68 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5300	72 in Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5311	Mid-State 68 In Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5301	72 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5312	Mid-State 68 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5302	72 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5315	2024 Kit Containers QT-DB-T66 66 in Skid Steer Bucket (Unused) S/N: B23J1617 Usage: Not Available Asset located in: Lake Worth, TX
5303	Mid-State General Purpose 72 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5316	2024 Kit Containers QT-DB-S66 66 in Skid Steer Bucket (Unused) S/N: B23J1632 Usage: Not Available Asset located in: Lake Worth, TX
5304	72 in General Purpose Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5317	Mid-State 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5305	2020 Bobcat 7326129/Teeth Skid Steer Bucket S/N: 004164 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5318	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5319	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5331	Mid-State 68 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5320	Teran BKT26260 60 in C Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 3119 C/W: 0.35m3 with 7 HD Tips to fit Cat 226 - 299 Usage: Not Available	5332	All Star 68 in Snow & Litter Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5321	Asset located in: Lake Worth, TX Bobcat 80 in General Purpose Skid Steer Bucket S/N: 6726344 Usage: Not Available	5333	All-Star 80 In Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5322	Asset located in: Lake Worth, TX Arrow 2307206BUN 74 in Skid Steer Bucket S/N: YB12397 Usage: Not Available	5334	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: With Teeth Usage: Not Available Asset located in: Lake Worth, TX
5324	Asset located in: Lake Worth, TX 67 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5335	All-Star 84 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5325	61 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5336	All-Star 84 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5326	2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: B30J1625 Usage: Not Available Asset located in: Lake Worth, TX	5337	Asset located in: Lake Worth, TX Kit Containers 82 in Rock Skid Steer Bucket (Unused) S/N: B22J1604 Usage: Not Available
5327	2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: B29J1617 Usage: Not Available Asset located in: Lake Worth, TX	5338	Asset located in: Lake Worth, TX All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5328	Mid-State 78 In Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5339	ASSET IOCATED III: Lake Worth, TX All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5329	All-Star 74 In Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5340	Kit Containers 72 in Rock Skid Steer Bucket (Unused) S/N: B21J1615 Usage: Not Available Asset located in: Lake Worth, TX
5330	Mid-State 80 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5341	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5342	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5349	2024 Landhonor RB-14-72W 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5344	2024 Landhonor RB-14-84W 84 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5350	Asset located in: Lake Worth, TX All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5351	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5345	2024 Landhonor RB-14-78W 78 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5352	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		5353	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5346	Asset located in: Lake Worth, TX Kit Containers 76 in Skeleton Skid Steer Bucket (Unused) S/N: B17J1620 Usage: Not Available	(U i S/I Us	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5347	Asset located in: Lake Worth, TX Kit Containers 76 in Skeleton Skid Steer Bucket (Unused) S/N: B16J1620 Usage: Not Available Asset located in: Lake Worth, TX	5355	5355	2024 Landhonor RB-14-66W 66 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5348	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
		5356	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5357 5358	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX All-Star 40 in Stump Skid Steer Bucket	5364	2024 Kit Containers 2YFT-SST 5 ft 7 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 7 in Long x 4 ft 7 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5368	2024 Kit Containers 2YFT-SST 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in
5359	2024 Kit Containers QT-TS-40 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		High Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers 1.5YFT-SST Skid Steer
5360	2024 Kit Containers QT-RD 36 in Skeleton Stump Skid Steer Bucket (Unused) S/N: B28J1958 Usage: Not Available		Dump Hopper (Unused) S/N: B29E1207 Usage: Not Available Asset located in: Lake Worth, TX
5361	Asset located in: Lake Worth, TX 2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5362	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: 005500748 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 72 in Skid Steer Landplane (Unused)
5363	2024 Suihe SSM 56 in Skid Steer Concrete Mixer (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 008000909 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5370	42 in Mini Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5371	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202409282 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HLS35 Skid Steer Log Splitter	5379	Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION C THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
3372	(Unused) S/N: LS202409283		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5380	2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409139 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5373	2024 Handy HLS35 Skid Steer Log Splitter (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: LS202409281 Usage: Not Available	5381	Asset located in: Lake Worth, TX 2024 Handy HSSB72 72 in Skid Steer
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5381	2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409138 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5374	2024 Raytree RMLS18T 18 ton Skid Steer Log Splitter (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: LS20241012044 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409137 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5375	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5383	2024 Kit Containers QT-RR-70 70 in Skid Steer
5376	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Ripper Scarifier S/N: B24J1305 Usage: Not Avai Asset located in 5384 84 in Skid Steer S/N: Not Availab Usage: Not Avai	Ripper Scarifier (Unused) S/N: B24J1305 Usage: Not Available Asset located in: Lake Worth, TX
5377	2024 Handy HSP24 24 in Skid Steer Planer (Unused) S/N: SP202409130 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		84 in Skid Steer Ripper Scarifier (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5378	2024 Handy HSP24 Skid Steer Planer (Unused) S/N: SP202404110 Usage: Not Available Notes: . Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
5385	2024 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	(Unused) S/N: HF202409299 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRE THE ACTUAL PRODUCT Asset located in: Lake Worth, T 5393 2024 Handy HF2T 48 in Skid St (Unused) S/N: HF202409300 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRE	(Unused) S/N: HF202409299 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5393 2024 Handy HF2T 48 in Skid Steer For	S/N: HF202409299 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HF2T 48 in Skid Steer Forks
5386	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: Fork Positioner	
5387	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset Joseph Jacks Worth TV	5394	Asset located in: Lake Worth, TX 2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409298	
5388	Asset located in: Lake Worth, TX 2024 Landhonor HRB-11-127A Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00018 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available Asset located in: Lake Worth, TX		C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5389	2024 Landhonor HRB-11-127A Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00017 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available Asset located in: Lake Worth, TX	5395	Quantity of (4) 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: (4) Universal Adapter Plates, One Crate Usage: Not Available Asset located in: Lake Worth, TX	
5390	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409301 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HF2T 48 in Skid Steer Forks (Unused)	5396	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	S/N: HF202409297 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5397	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5398	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5406	2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5407	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5408	2024 Kit Containers QT-45-FF-42 42 in Skid
5399	<u>·</u>		Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5409	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5410	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused)
5400	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Fork Positioner Usage: Not Available Asset located in : Lake Worth, TX		2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available
5401	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5412	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available
5402	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5413	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available
5403	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner	Usage: Not Available	
	Usage: Not Available Asset located in: Lake Worth, TX	5414	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused)
5404	Handy HSRF48 48 in Rotating Skid Steer Forks (Unused) S/N: RF202401136		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5415	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
5405	2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
		5416	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5417	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5430	Trojan SPF15 48 in Skid Steer Forks (Unused) S/N: 124438 Usage: Not Available Asset located in: Lake Worth, TX
5418	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5431	48 in Skid Steer Forks S/N: Not Available Usage: Not Available
5419	Asset located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5432	Asset located in: Lake Worth, TX 38 in Skid Steer Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5420	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5433	All Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5421	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5434	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5422	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5435	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5423	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5436	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5424	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5437	48 in Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5425	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5438	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5426	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5439	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5427	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5440	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5428	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5441	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5429	Land Pride 48 in Skid Steer Forks S/N: 999569 Usage: Not Available Asset located in: Lake Worth, TX	5442	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5443	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5453	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5444	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5445	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5446	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5455 2 6 7 8 7 8 9 9 1	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5447	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5448	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhonor BS-12-2500G 45 in Skid Steer
5449	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
5450	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5451	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5456	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5457	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5458	All-Star 44 in Skid Steer Bale Spear (Unused)
5452	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear Frame (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5459	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5460	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5461	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available	5471	32 in Skid Steer Tree Spade (Unused) S/N: Not Available
	Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX
5462	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5472	2 2024 Landhonor HAG-12-24Q 88 in Skid Steel Bale Accumulator Grapple (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5463	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5464	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused)		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5473	2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused)
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
	Asset located in: Lake Worth, TX		
5465	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		
			Asset located in: Lake Worth, TX
		5474	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00018 Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5475	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00017
5466	32 in Skid Steer Tree Spade (Unused) S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	5476	2024 Landhonor DPC-21-13W Skid Steer Pole
	Asset located in: Lake Worth, TX	_	Clamp (Unused)
5467	32 in Skid Steer Tree Spade (Unused)		S/N: HL00009 Usage: Not Available
	S/N: Not Available Usage: Not Available		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5477	2024 Kit Containers QT-TM Receiver Hitch
5468	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available	_ 34//	(Unused) S/N: B06J1903 Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5469	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5478	2024 Kit Containers QT-TM Skid Steer Receiver Hitch (Unused) S/N: B06J1913 Usage: Not Available
5470	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5479	Hitch Receiver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5485 5486 5487	Titan SSJ2.5 Extendable Skid Steer Material Handling Arm S/N: Not Available Usage: Not Available Asset located in: Midland, TX Set of Grouser Steel Skid Steer Tracks S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX Set of McLaren Steel Skid Steer Tracks
5480	Asset located in: Lake Worth, TX 2024 Landhonor UHA-16-3000G 2 in Skid Steer	\dashv	S/N: Not Available Usage: Not Available
	Hitch Receiver (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5488	Set of OTT Tracks for Skid Steer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5489	2024 Handy HSTS12 Skid Steer Tree Shear (Unused) S/N: TS202409117 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5481	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available	5490	Asset located in: Lake Worth, TX Quantity of (4) All-Star Quick Attach Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5491	Quantity of (10) 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available
5482	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available		C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE ACTUAL PRODUCT.	:	Quantity of (10) 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5493	Quantity of 2024 Kit Containers QT-F-BLANK
5483	All-Star Receiver Hitch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5484	All-Star Receiver Hitch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5494	Quantity of (10) 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available	5503	All-Star E35 40 in Q/C Excavator Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5504	All-Star 40 in Excavator Brush Cutter (Unused) S/N: Not Available
5495	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available		C/W: No Coupler Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	5505	Paladin Hydraulic Breaker S/N: Not Available
5496	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5506	Cat Misc. attachment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5497	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
5498	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Usage: Not Available Asset located in : Lake Worth, TX	5507	Quantity of (2) Pallets of Okada Padding
5499	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Bucket Screens S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
5500	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5501	2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused) S/N: DM20241009163 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5509	Contech 2200 Excavator Plate Compactor S/N: 7800220A1191132 Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5510	Volvo ARM-EC380E-9FT6IN BARE Excavator stick S/N: Not Available
5502	Quantity of (9) Agrotek Mini Excavator		Usage: Not Available Asset located in : Lake Worth, TX
	Attachments (Unused) S/N: 12EXATA24042002A C/W: (3) Buckets, Quick Coupler, Grapple, Auger, Two Bits, Rake, Ripper, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	5511	KBKC 72 in Excavator Rake - Fits Cat 320 (Unused) S/N: RR240122 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5512	KBKC 48 in Excavator Rake - Fits Cat 305-306 (Unused) S/N: RR240103 Usage: Not Available Asset located in: Lake Worth, TX	5520	2024 JESON HM3150 Hydraulic Breaker (Unused) S/N: JQ HM 015 Usage: Not Available Asset located in: Lake Worth, TX
5513	Excavator Ripper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5521	2024 JQ POWER JQB3000STB Hydraulic Breaker (Unused) S/N: 814075918 Usage: Not Available
5514	2018 John Deere Excavator Auger - Fits John Deere 310SJ S/N: Not Available C/W: 45 mm Diameter Pins, 340 mm Center of Pin Boss to Center of Pin Boss, 205 mm Inside to Inside Pin Boss Spacing, 10 in & 12 in Auger Bits	5522	Asset located in: Lake Worth, TX 2024 JESON HM3070 Hydraulic Breaker (Unused) S/N: JQ HM 014 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	5523	2024 JESON HM3070SL Skid Steer Breaker (Unused) S/N: JQHM010 Usage: Not Available Asset located in: Lake Worth, TX
5515	Digga PDI-13-13-DDS Excavator Auger - Fits John Deere 210 S/N: 1804110013 C/W: 75 mm Diameter Pins, 470 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, 16 in & 20 in Auger Bits Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	5524	2024 Jisan JSB2200B 144 mm Hydraulic Breaker (Unused) S/N: 2404338 Usage: Not Available Asset located in: Lake Worth, TX
		5525	2024 Jisan JSB2200B 140 mm Hydraulic Breaker (Unused) S/N: 2404339 Usage: Not Available Asset located in: Lake Worth, TX
5516	2019 Stanley MB/XP4035 Hydraulic Breaker S/N: XP40350054 C/W: 8000 lb class, 5.6 in Tool / Chisel, Fits Excavators Usage: Not Available	5526 	2024 TOFT TOFT1550 Hydraulic Breaker (Unused) S/N: JW121Z0715 Usage: Not Available Asset located in: Lake Worth, TX
5517	Asset located in: Lake Worth, TX 2024 JESON HM3300 Hydraulic Breaker (Unused) S/N: JQ HM 012 Usage: Not Available Asset located in: Lake Worth, TX		2024 TOFT TOFT1400 Hydraulic Breaker (Unused) S/N: JW81Z3340 Usage: Not Available Asset located in: Lake Worth, TX
5518	2024 Jisan JSB3200B Hydraulic Breaker (Unused) S/N: CP2404445 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Jisan JSB2200B Hydraulic Breaker (Unused) S/N: CP2404401 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5519	2024 JESON HM3200 Hydraulic Breaker (Unused) S/N: JQ HM 011 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5529	2024 Jisan JSB2200T Hydraulic Breaker (Unused) S/N: CP2406139 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5536	2024 Elephant EPB430BL Hydraulic Breaker (Unused) S/N: CP2406079 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5530	2024 Elephant EPB2200B Hydraulic Breaker S/N: CP2407167 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5537	2024 Jisan JSB430B Hydraulic Breaker (Unused) S/N: CP2408266 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5531	2024 Elephant EPB2200T Hydraulic Breaker S/N: CP2406053 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Elephant EPB430BL Hydraulic Breaker S/N: CP2406081 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5532	Teran THH2000B Hydraulic Breaker - Fits Cat 320 (Unused) S/N: CEH715D14HZ C/W: B Linkage For all 18-25 Ton Excavators - With Auto - Lubrication Pre-Disposition. Box Type - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual. Usage: Not Available	5540 5541 5542	Asset located in: Lake Worth, TX 2024 Elephant EPB400T Hydraulic Breaker (Unused) S/N: CP2406114 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Elephant EPB400T Hydraulic Breaker
5533	Asset located in: Lake Worth, TX 2024 TOFT TOFT1000 Hydraulic Breaker (Unused) S/N: JW50Z2170 Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: CP2406112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5534	2024 Jisan JSB800B Hydraulic Breaker (Unused) S/N: CP2406128 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Jisan JSB400B Hydraulic Breaker (Unused) S/N: CP2403154 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5535	2024 Elephant EPB800T Hydraulic Breaker (Unused) S/N: CP2406101 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5543	2024 Jisan JSB400B Hydraulic Breaker (Unused)	5547	Teran THH400B-SSL Skid Steer Breaker - Fits Cat 226 (Unused)
	S/N: CP2403166 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	=	S/N: Not Available C/W: For Skid Steer Loader Cat 226-299 With Mounting Plate included -68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box
5544	2024 Jisan JSB400BL Hydraulic Breaker (Unused) S/N: CP2404523 Usage: Not Available		with Maintenance Tools and Operations Manual Usage: Not Available Asset located in : Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5548	Teran THH400BT Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAA3496B54HR C/W: For Backhoe Loaders CAT 416, 428, 444 -68mm Tool With Auto - Lubrication Pre-
5545	Teran THH400B-CAT308 Hydraulic Breaker - Fits Cat 307 (Unused) S/N: Not Available C/W: For Mini Excavators CAT 307/308 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX Teran THH400BH Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAB00398C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX		Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX
		5549	Trojan 50CL Hydraulic Breaker - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: SB40YOM20246073
5546			Usage: Not Available Asset located in: Lake Worth, TX
		5550	Trojan 35CL Hydraulic Breaker - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: SB30YOM20246119 Usage: Not Available Asset located in: Lake Worth, TX
		5551	Teledyne TB8309X Hydraulic Breaker S/N: 9991991983 Usage: Not Available Asset located in : Lake Worth, TX
		5553	2017 Okada 100A Hydraulic Breaker S/N: 3160R C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
		5554	Kelly Hydraulic Breaker - Fits Kelly CB7500 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5555	Kent 5 in Hydraulic Breaker - Fits John Deere 200C LC S/N: F272749 C/W: 80 mm Diameter Pins, 440 mm Center of Pin Boss to Center of Pin Boss, 325 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	5563	Remu CAT C/EX140 48 in Padding Excavator Bucket - Fits REMU EX140 S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
5556	Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5564	B&D Fab CAT C/EX140 48 in Padding Excavator Bucket - Fits CAT EX140 S/N: B93283 Usage: Not Available
5557	Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
5558	2024 TOFT TOFT280R Rotating Demolition Shear (Unused)		Asset located in: McAlester, OK
	S/N: TOFT280R24032 Usage: Not Available Asset located in: Lake Worth, TX	5564A	Rockland 84 in Excavator Bucket S/N: 9757101 Usage: Not Available Asset located in: Lake Worth, TX
5559	2019 Hammer GRP150 15 in Excavator Grapple S/N: H183515GRP Usage: Not Available Asset located in: Lake Worth, TX	5565	2024 Jisan BKT32078DB 78 in Cleanup Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused)
5560	Viper Metal VPH 3-1700 68 in Padding Excavator Bucket (Unused) S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		C/W: TH FOR ILLU MAY NO THE ACT Usage: N Notes: T BE FOR ILLU MAY NO THE ACT
	Asset located in: McAlester, OK	5566	2024 JESON BKT 345-78 78 in Digging
5561	Viper Metal VPH 4-1500 57 in Padding Excavator Bucket (Unused) S/N: Not Available Usage: Not Available		Excavator Bucket (Unused) S/N: JQ BKT 059 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5567	2024 JESON BKT 345-78 78 in Digging Excavator Bucket (Unused) S/N: JQ BKT 049 Usage: Not Available Asset located in: Lake Worth, TX
5562	2019 Remu EX140 48 in Screening Excavator Bucket S/N: 14000062 Usage: Not Available Asset located in: Lake Worth, TX	5568	2024 Jisan BKT34572HD 72 in Excavator Bucket (Unused) S/N: 24072902536 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5569	2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 058 Usage: Not Available Asset located in: Lake Worth, TX	5578	2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 052 Usage: Not Available Asset located in: Lake Worth, TX	
5570	2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 040 Usage: Not Available Asset located in: Lake Worth, TX	5579	2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 028 Usage: Not Available Asset located in: Lake Worth, TX	
5571	2024 Jisan BKT336D72HD 72 in Excavator Bucket (Unused) S/N: 24062202043 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5580	2024 Jisan BKT36066HD 66 in 2.2 cyd Digging Excavator Bucket - Fits Komatsu PC360 (Unused) S/N: 24072902567 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
5572	Teran BKT336D72HD 72 in Digging Excavator Bucket - Fits Cat 336D (Unused) S/N: 0838 C/W: DB Linkage - 2.00m3 for Cat 336D,		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	336D2, 336E, 336F, 340D2, 340F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips - DB Linkage Usage: Not Available Asset located in: Lake Worth, TX	5581	2022 Werk-Brau 480-66-VO-HC 66 in Digging Excavator Bucket S/N: 48834 Usage: Not Available Asset located in: Lake Worth, TX	
5573	2024 JESON BKT 336-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 053 Usage: Not Available Asset located in: Lake Worth, TX	5582	2024 BTTL CAT345 60 in Digging Excavator Bucket (Unused) S/N: TOFTEB24581 Usage: Not Available Asset located in: Lake Worth, TX	
5574	2024 Warrior WBRC40-1700 72 in Digging 40- 45T 1700mm to fit CAT349 Rock Excavator Bucket (Unused) S/N: 2024-09-20-JL01 Usage: Not Available Asset located in: Lake Worth, TX	5583	5583 2024 Elephant BKT336D60HD 6 Bucket (Unused) S/N: 24062200411 Usage: Not Available Notes: THE PRODUCT IMAGES	2024 Elephant BKT336D60HD 60 in Excavator Bucket (Unused) S/N: 24062200411 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5575	2024 JESON BKT 345-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 039		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	5584	2024 Jisan BKT336D60HD 60 in Excavator Bucket (Unused)	
5576	2024 JESON BKT 345-66 66 in Excavator Bucket (Unused) S/N: JQBKT037 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 24062202027 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5577	2024 JESON BKT 345-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 057 Usage: Not Available Asset located in: Lake Worth, TX	5585	Asset located in: Lake Worth, TX 2024 JESON BKT 336-60 60 in Digging Excavator Bucket (Unused) S/N: JQ BKT 020 Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5586	2024 JESON BKT 336-60 60 in Digging Excavator Bucket (Unused) S/N: JQ BKT 023 Usage: Not Available Asset located in: Lake Worth, TX	5594	56 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: 1844 Usage: Not Available Asset located in: Lake Worth, TX	
5587	Esco 58 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: RH80487 Usage: Not Available Asset located in: Lake Worth, TX	5595 5596 5597 5598	2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
5588	Teran BKT325D54HD 54 in Digging Excavator Bucket - Fits Cat 329D (Unused) S/N: 3655 C/W: CB Linkage - 1.22m3 for Cat 325D, 324D,		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6RC Tips Usage: Not Available Asset located in: Lake Worth, TX		2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
5589	2024 Jisan BKT32054HD 54 in Excavator Bucket (Unused) S/N: 2406220204 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2024 Elephant BKT32048HD 48 in Excavator Bucket (Unused) S/N: 24151503617 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OTHE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5590	Asset located in: Lake Worth, TX Teran BKT32054HD 54 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 1847 C/W: B Linkage - 1.02m3 for Cat 320, 319D,			
	320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 6HD Tips Usage: Not Available Asset located in: Lake Worth, TX		2024 JESON BKT 320-48 48 in Digging Excavator Bucket (Unused) S/N: JQ BKT 054 Usage: Not Available	
5591	2024 Elephant BKT22054HD 54 in Excavator Bucket (Unused) S/N: 2407280051 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5599	Asset located in: Lake Worth, TX 2024 JESON BKT 320-48 48 in Digging Excavator Bucket (Unused) S/N: JQ BKT 055 Usage: Not Available Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5600	Trojan 200CL 48 in Digging Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210	
5592	2024 Jisan BKT22054HD 54 in Excavator Bucket (Unused) S/N: 24062300918 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		•	S/N: Not Available Usage: Not Available
5593	C & P 60 in Digging Excavator Bucket S/N: NHK50615 Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
5601	Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225	5610	2020 Cat A 42 BU 42 in Excavator Bucket S/N: 0XC702965 Usage: Not Available Asset located in: Lake Worth, TX
		5611	Komatsu 42 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5602	Teran 48 in .88 cyd Digging Excavator Bucket - Fits Cat 312 S/N: BKT31248 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	5612	Teran BKT31236 36 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 5583 C/W: 312 Linkage - 0.48m3 for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 5HD Tips
5603	Teran 48 in 1.16 cyd Digging Excavator Bucket - Fits Cat 320		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: BKT32048HD C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	5613	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available
5604	48 in Q/C Digging Excavator Bucket S/N: 804560244191		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5614	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140
5605	Paladin 48 in Digging Excavator Bucket - Fits John Deere 350G S/N: J000094897-1 Usage: Not Available Asset located in: Lake Worth, TX		Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5606	2024 BTTL CAT320 42 in Excavator Bucket (Unused) S/N: TOFTEB24553 Usage: Not Available Asset located in: Lake Worth, TX	5615	Trojan 120CL 36 cyd Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available
5607	Trojan 120CL 42 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140		Usage: Not Available Asset located in: Lake Worth, TX
	Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available	5616	36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5608	Asset located in: Lake Worth, TX Trojan 120CL 42 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused)	5617	Esco 36 in Excavator Bucket - Fits Komatsu PC220 S/N: 56553 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		32 in Digging Excavator Bucket S/N: Not Available Usage: Not Available
5609	Teran BKT30742 42 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 1208 C/W: 0.41m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 7HD Tips Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5619	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5628	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5620	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5629	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5621	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5630	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5622	Teran BKT30730 30 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 1205 C/W: 0.27m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX		Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available
5623	2014 Tag 30 in Digging Excavator Bucket S/N: 102177-41 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Oklahoma City, OK	5632	Asset located in: Lake Worth, TX Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case,
5624	30 in Q/C Digging Excavator Bucket S/N: 60941C Usage: Not Available Asset located in : Lake Worth, TX		New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5625	Tooth Pro 26 in V-Ditching Excavator Bucket S/N: 2360 Usage: Not Available Asset located in: Lake Worth, TX	5633	Teran BKT305C24 24 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2941 C/W: 0.16m3 with Side Cutters Reinforcement
5626	Teran BKT31224 24 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 0171	5634	Plates and 5HD Tips Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 312 Linkage - 0.32m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in: Lake Worth, TX		Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available
5627	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5635	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5644 5645	Tooth Pro 15 in Mini Excavator Bucket S/N: 5707 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX Trojan 50CL 12 in Digging Excavator Bucket -
5636	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5637	24 in Digging Excavator Bucket S/N: 3181 Usage: Not Available Asset located in: Lake Worth, TX 2018 Cat B 24 BU 24 in Digging Excavator Bucket S/N: B-24-MHJ74545	5646	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available
	Usage: Not Available Asset located in: Lake Worth, TX	5647	Asset located in: Lake Worth, TX Trojan 50CL 12 in Digging Excavator Bucket -
5639	24 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available
5640	24 in Digging Excavator Bucket S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5648	Trojan 35CL 12 in Digging Excavator Bucket Fits 40mm Cat 303, 303.5, 304 Case, New
5641	Bobcat 24 in Q/C Digging Mini Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	5649	Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5642	Asset located in: Lake Worth, TX 2023 Kubota K7874A-18 18 in Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available		Trojan 35CL 12 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5650	Trojan 35CL 12 cyd Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New
5643	Rockland 18 in V-Ditching Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5643A	Adco 16 in V-Ditching Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5651	Teran BKT305C12 12 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2920 C/W: 0.08m3 With Side Cutters Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5652	Tooth Pro 12 in Mini Excavator Bucket S/N: 5480 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5661	2024 JESON BKT 336-66 SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: JQ BKT 050 Usage: Not Available Asset located in: Lake Worth, TX
5653	12 in Q/C Digging Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5662	2024 Warrior WBSC30-1600 62 in Skeleton Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside
5654	Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available C/W: (1) 7 in, (1) 23 in Usage: Not Available Asset located in: Lake Worth, TX		Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5655	Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available C/W: (1) 7 in, (1) 23 in Usage: Not Available Asset located in: Lake Worth, TX	5663	Teran BKT325D60SKEL 60 in Skeleton Excavator Bucket - Fits Cat 329D (Unused) S/N: 2220 C/W: CB Linkage - 1.14m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E,
5656	2024 Jisan BKT34572SKEL 72 in Skeleton Excavator Bucket (Unused) S/N: 24072903037 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5664 2024 Jisan BKT32060SKEL 60 in Sk Excavator Bucket (Unused) S/N: 24072903014 Usage: Not Available	S/N: 24072903014 Usage: Not Available
5657	2024 Elephant BKT336D72SKEL 72 in Skeleton Excavator Bucket (Unused) S/N: 2407290019 Usage: Not Available	5665	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Teran BKT32054SKEL 54 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 2159 C/W: B Linkage - 1.02m3 for Cat 320, 319D,
5658	2024 JESON BKT 336-72 SKEL 78 in Skeleton Excavator Bucket (Unused) S/N: JQBKT051 Usage: Not Available Asset located in: Lake Worth, TX		320D, 320E, 321D, 323E, 323F, 325F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6HD Tips 80mm Pins Usage: Not Available Asset located in: Lake Worth, TX
5659	2024 Jisan BKT336D66SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: 2409040117 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5666	2024 Jisan BKT32048SKEL 48 in Skeleton Excavator Bucket (Unused) S/N: 2407290301 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5660	Asset located in: Lake Worth, TX 2024 JESON BKT 336-66 SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: JQ BKT 056 Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5667	Teran BKT31248SKEL 48 in Skeleton Excavator Bucket - Fits Cat 312 (Unused) S/N: 3112 C/W: 312 Linkage - 0.77m3 for CAT 312, 311D, 311F, 312D, 312D2, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5672	5672 2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN
5668	2024 TOFT CAT336 48 in Skeleton Excavator Bucket (Unused) S/N: TOFTEB24674 Usage: Not Available		EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5669	Asset located in: Lake Worth, TX 2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available		Teran BKT30742SKEL 42 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 0573 C/W: 0.39m3 for Cat 307, 308 with 5 HD Tips Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5674	Teran BKT30736SKEL 36 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 1126 C/W: 0.34m3 for Cat 307/308 with 6HD Tips Usage: Not Available Asset located in: Lake Worth, TX
5670	Usage: Not Available Asset located in: Lake Worth, TX 2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT	5675	Trojan 200CL 72 in Tilting Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5671	IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Warrior WBSC20-1100 47 in Skeleton	5676	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL	5677	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	PRODUCT Usage: Not Available Asset located in : Lake Worth, TX	5678	Trojan 80CL 48 in Tilting Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5679	Trojan 80CL 48 in Tilting Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5687	Teran BKT32060CLN 60 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 1319 C/W: B Linkage - 0.54m3 for CAT 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available Asset located in: Lake Worth, TX	
5680	Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5688	2024 Warrior WBRC30-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT	
5681	Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341		REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Warrior WBRC30-1500 59 in Cleanup Excavator Bucket - Fits Cat 320/ 20 - 25 ton (Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link	
5682	Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available		Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSE ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODU Usage: Not Available	
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
5683	Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5690	2024 Warrior WBMCC20-1500 60 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5684	Trojan 200CL 72 in Ditch Cleaning Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai		Usage: Not Available Asset located in: Lake Worth, TX	
	R210 Komatsu PC200/220, Deere 160/200 /225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5691	Excavator Bucket - Fits Cat 320 / 20 - 2 (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Co	S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside
5685	Teran BKT32072CLN 72 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 4843 C/W: B Linkage - 0.66m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available Asset located in: Lake Worth, TX		to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
5686	72 in Excavator Bucket - Fits Mobile Excavator S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
5692	2024 Warrior WBMCC20-1500 60 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5700	Teran BKT30448CLN 48 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 2301 C/W: 0.15m3 Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5701	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D
5693	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available		/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5702	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu
5694	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available		PC45/50/55 Hyundai R55, Hitachi/Deere 50D /G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5695	Asset located in: Lake Worth, TX Teran BKT31260CLN 60 in Cleanup Excavator Bucket - Fits Cat 312 (Unused) S/N: 0183 C/W: 312 Linkage - 0.38m3 for Cat 312,311D,	5703	Teran BKT30742CLN 42 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3032 C/W: 0.20m3 for Cat 307/308 Usage: Not Available
	311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Lake Worth, TX	5704	Asset located in: Lake Worth, TX Trojan 35CL 42 in Ditch Cleaning Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D
5696	Trojan 80CL 48 in Ditch Cleaning Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused)		/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5705	Trojan 35CL 42 in Ditch Cleaning Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D
5697	Trojan 80CL 48 in Ditch Cleaning Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused)		/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5706	Teran BKT30342CLN 42 in Cleanup Excavator Bucket - Fits Cat 303 (Unused) S/N: 2836
5698	Teran BKT30748CLN 48 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3045	5707	C/W: 0.13m3 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 0.23m3 for Cat 307/308 Usage: Not Available Asset located in : Lake Worth, TX		Teran BKT30436CLN 36 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 01063
5699	Teran BKT305C48CLN 48 in Cleanup Excavator Bucket - Fits Cat 305 (Unused) S/N: 01071 C/W: 0.15m3 Usage: Not Available Asset located in: Lake Worth, TX		C/W: 0.12m3 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5708	Teran BKT30136CLN 36 in Cleanup Excavator Bucket - Fits Cat 301 (Unused) S/N: 2645 C/W: 0.07m3 30mm Pins Usage: Not Available Asset located in: Lake Worth, TX	5715	REMU EX140 48 in Padding Bucket - Fits Cat S/N: 14270 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY;	
5709	Bobcat 36 in Q/C Mini Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: .		ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
	Asset located in: Lake Worth, TX	_5716	REMU EX140 48 in Padding Bucket - Fits Cat	
5710	84 in Bucket S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		S/N: 14268 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available	
5711	2019 Viper 3-1700 67.5 in Padding Shaker Bucket - Fits Komatsu PC200 S/N: 3-17001714 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside to Inside Pin Boss Spacing	5717	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	
	Usage: Not Available		Asset located in: McAlester, OK	
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		19.5 in Digging Bucket - Fits Hitachi 160 S/N: 779435681 C/W: 80 mm Diameter Pins, 392 mm Center of Pin Boss to Center of Pin Boss, 307 mm Inside to Inside Pin Boss Spacing Usage: Not Available	
	Asset located in: McAlester, OK		Notes: ITEMS AT OFFSITE LOCATION MUST	
5712	2019 Viper 4-1100 48 in Padding Shaker Bucket S/N: 4-1100218 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside to Inside Pin Boss Spacing Usage: Not Available		AUCTION (JANUARY 3RD) OR WILL SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOU NOT BE ABLE TO ASSIST WITH LOA THESE	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Notes: LOADOUT BY APPOINTMENT ONLY;		· · · · · · · · · · · · · · · · · · ·	
	ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5718	Tooth Pro 25 in Digging Bucket S/N: 3333 C/W: 80 mm Diameter Pins, 390 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing Usage: Not Available	
		-	Notes: ITEMS AT OFFSITE LOCATION MUST	
5713	2018 Viper 4-1100 48 in Padding Shaker Bucket - Fits Komatsu PC-200 S/N: 4-1100214 C/W: 80 mm Diameter Pins, 415 mm Center of Pin Boss to Center of Pin Boss, 328 mm Inside to Inside Pin Boss Spacing Usage: Not Available		de	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	5719	82 in Q/C Wheel Loader Bucket S/N: CH031182522 Usage: Not Available Asset located in : Lake Worth, TX	
	Asset located in: McAlester, OK	5720	Bobcat Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5721	61 in Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX American Compaction DC18S 18 in Q/C	5730	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 031012020 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	Excavator Compaction Wheel S/N: 100711104		Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX	5731	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 041212819 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5723	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 0801012007	5732	Usage: Not Available Asset located in: Lake Worth, TX Entek 36 in Excavator Compaction Wheel
	C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		S/N: 8420 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5724	American Compaction DC24BLWP 24 in Excavator Compaction Wheel		Asset located in: Lake Worth, TX
	S/N: 121817519 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5733	Rockland WE36-4 36 in Excavator Compaction Wheel S/N: 7921501 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY
5725	Rockland 24 in Excavator Compaction Wheel		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 9412601 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5734	Entek 18 in Excavator Compaction Wheel S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5726	American Compaction DC18S 18 in Excavator Compaction Wheel		Asset located in: Lake Worth, TX
	S/N: 111012261 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5735	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 080710899 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5727	American Compaction DC24BLWP 24 in	1	Usage: Not Available Asset located in: Lake Worth, TX
	Excavator Compaction Wheel S/N: 041212842 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	5736	2015 Vacuworx RC12 Vacuum Lifter S/N: RC1200144 Usage: 413 Hr Asset located in: Sulphur, LA
	Asset located in: Lake Worth, TX	5737	2007 Superior SVL90 Pipe Vacuum Lifter
5728	Tooth Pro 24 in Excavator Compaction Wheel S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-	5738	S/N: VL153 Usage: Not Available Asset located in : Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX		2024 Jisan QCCAT336D Excavator Coupler (Unused)
5729	Rockland 24 in Excavator Compaction Wheel		S/N: 24042900759 Usage: Not Available
	S/N: 7102601 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Asset located in: Lake Worth, TX	l	Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5739	2024 Jisan QCCAT320 Excavator Coupler (Unused) S/N: 24042900737 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5744	5744 Quantity of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
5740	2024 Elephant QCCAT320 Excavator Coupler (Unused) S/N: 2407290022		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Cat Excavator Coupler S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
5741	Teran QCCAT305 Excavator Coupler - Fits Cat 305 (Unused) S/N: 2014 C/W: For Cat 305 - 45mm Pins Usage: Not Available Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WI NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5742	Quantity of (2) Pallets of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	5746	Simex SM3-17 84 in Excavator Crusher Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5747	2024 Elephant JXJMQC345 51 in Excavator Grapple (Unused) S/N: 24072900212 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5743	Quantity of (3) Pallets of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5748 5749	2024 Elephant JXJMQC336 46 in Excavator Grapple (Unused) S/N: 2406220032 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan JXJMQC320 44 in Excavator Grapple (Unused) S/N: 2407290131 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
			S/N: 2407290131 Usage: Not Available Notes : THE PRODUCT IMAGES SHOWN

Lot #	Details	Lot #	Details
5750 5752	(Unused) S/N: TOFTHG24110 Usage: Not Available Asset located in: Lake Worth, TX	5758	2024 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5759	2024 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available
5753	Tysea 60 in Hydraulic Excavator Grapple S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	C/ Pi to IM Pl EX PI	C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5754	2024 Elephant RAKE32065 65 in Excavator Rake (Unused) S/N: 24072900230 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5760	Teran RIPPER307 Excavator Ripper - Fits Cat 307 (Unused) S/N: 1307 C/W: For Cat 307/308 50mm Pin Usage: Not Available Asset located in: Lake Worth, TX
5755	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan RIPPER336D Excavator Ripper (Unused)	5761	2024 TOFT TOFT08R Excavator Ripper (Unused) S/N: TOFTERP24117 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 24072903240 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5762	2024 TOFT TOFT04R Excavator Ripper (Unused) S/N: TOFTERP24073147 Usage: Not Available Asset located in: Lake Worth, TX
5756	2024 Elephant RIPPER320 Excavator Ripper (Unused) S/N: 24072900226 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5763	Trojan 200CL 72 in Excavator Screening Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200 /225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5757	Asset located in: Lake Worth, TX 2024 Jisan RIPPER320 Excavator Ripper (Unused)	5764	REMU PD3150 69 in Q/C Screening Excavator Screening Bucket - Fits CAT C/EX140 S/N: B99434
	S/N: 24072903228 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5765	REMU EX140 48 in Q/C Screening Excavator Screening Bucket S/N: 14000061 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5772	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903054 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5766	REMU EX140 48 in Q/C Screening Excavator Screening Bucket S/N: 14000058 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5773	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903057 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5767	Okada TMB70 Excavator Screening Bucket S/N: 508 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE	5774	Quantity of (2) Cat Excavator Thumb - Fits Cat 320 S/N: Not Available C/W: (1) 28 In Hydraulic, (1) 24 In Manual Usage: Not Available Asset located in: Lake Worth, TX	
5768	Asset located in: Lake Worth, TX Okada TMB70 Trommel Excavator Screening Bucket S/N: 262 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	5775	5775	Teran THUMB30-35 M 40 in Excavator Thum Fits Cat 336D (Unused) S/N: Not Available C/W: 4 Tines - For Cat 330,336D and 30-36 T Excavators Usage: Not Available Asset located in: Lake Worth, TX
5769	Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX Okada TMB70 Excavator Screening Bucket S/N: 7050 C/W: EQUIPMENT-FROM-WATKINS-	5776	Trojan 200CL Excavator Thumb - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5770	CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX Okada TMB70 Excavator Screening Bucket S/N: 569	5777	Trojan 200CL Excavator Thumb - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5778	Teran THUMB20-25 M 30 in Excavator Thumb - Fits Cat 320 (Unused) S/N: Not Available C/W: 4 Tines - For Cat 320,325 and 20 - 25 Ton Excavators Usage: Not Available	
5771	Okada TMB70 Excavator Screening Bucket S/N: 351 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5779	Asset located in: Lake Worth, TX Teran THUMB12 - 15 M 26 in Excavator Thumb - Fits Cat 312 (Unused) S/N: 3188 C/W: For Cat 312, 315 and all 12-15 Ton Excavators 4 Tines Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5780	Teran THUMB5M 11 in Excavator Thumb - Fits Cat 305 (Unused) S/N: 3177 C/W: Manual Thumb for Cat 305 and 5 Ton Mini Excavators Usage: Not Available Asset located in: Lake Worth, TX	5788	Quantity of (4) Cat Excavator Thumb - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	
5781	Teran THUMB2-3.5M 8 in Excavator Thumb - Fits Cat 303 (Unused) S/N: Not Available C/W: Manual Thumb for all 2-3.5 Ton Mini Excavators Usage: Not Available	5789	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of (4) Cat Excavator Thumb	
5782	Asset located in: Lake Worth, TX Trojan 120CL Excavator Thumb - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere /Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5790 5791 5792 5793	S/N: C/W: CONS Usag Note: BE PI AUCT SUBJ	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
5783	Trojan 120CL Excavator Thumb - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere /Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Trojan 80CL Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75 /85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused)	
5784	Gentec HT1035 30 in Excavator Thumb S/N: Not Available C/W: Hydraulic - Fits loader-backhoes & excavators from 10000 to 20000 lbs Usage: Not Available		305, 305.5 Komatsu PC45/50/55 H Hitachi/Deere 50D/G Case, New H	Usage: Not Available
5785	Asset located in: Lake Worth, TX Trojan 80CL Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75 /85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused)			Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		Trojan 50CL Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland,	
5786	Diesel Equipment 80CL 16 in Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80		Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Diesel Equipment 50CL 15 in Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case,	
5787	2022 Rockland BTH-CL Excavator Thumb - Fits Rockland BTHCL S/N: 238845 Usage: Not Available Asset located in: Lake Worth, TX		New Holland, Kobelco SK50 Bobcat E50/341 /337 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5794 5795	Gentec HT830 25 in Excavator Thumb S/N: Not Available C/W: Fits loader-backhoes & excavators from 6000 - 10000 lbs Usage: Not Available Asset located in: Lake Worth, TX Gentec MT830 Excavator Thumb (Unused) S/N: Not Available	5802	2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused) S/N: DM20241009164 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5803	Asset located in: Lake Worth, TX Edge TH4800 48 in Skid Steer Mulcher S/N: TH0226	
5796	Gentec MT824 - Fits mini excavators from 4000 - 9000 lbs Excavator Thumb (Unused) S/N: Not Available	5004	Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX Train 250L Everyster Thumb. Fite 40mm Cet	5804	Fecon 90 in Mulcher Attachment S/N: Not Available Usage: Not Available	
5797	Trojan 35CL Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5805	Asset located in: Lake Worth, TX 2024 Jisan JSV765S Demolition Pulverizer (Unused) S/N: 24072903210 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
5798	Trojan 35CL Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available		its 40mm Cat d, Kobelco ed) FOR ILLUSTRATION MAY NOT BE AN EX THE ACTUAL PRODU	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2024 TOFT TOFT08P Demolition Pulverizer (Unused)	
5799	Diesel Equipment 35CL 14 in Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G		S/N: TOFTHP24107 Usage: Not Available Asset located in : Lake Worth, TX	
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5807	Bodine 200 Demolition Pulverizer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5800	Gentec HT618 16 in Excavator Thumb - Fits Gentec S/N: Not Available C/W: Fits mini excavators up to 4000 lbs Usage: Not Available Asset located in: Lake Worth, TX	5808	Quantity of (4) Crawler Pipelayer Side Booms S/N: Not Available C/W: (2) 20 ft, (1) 18 ft, (1) 13 ft Usage: Not Available Asset located in: Lake Worth, TX	
5801	Asset located in: Lake Worth, TX 5801 Excavator Thumb S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5809	Hill 144 in Dozer Rake S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		5810	Cat Light brackets - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
5811	Cat Radiator - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5815	Quantity of (3) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5812	Cat Scarifier S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5816	Quantity of (3) Pallets of Trunnion ball - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
5813	Quantity of Cat Misc. Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5817	Asset located in: Corsicana, TX Quantity of (4) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5814	Cat Pipelayer hook and block - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5818	Quantity of (4) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
5819	System One Undercarriage Chain / Rails - Fits Cat D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5827	Rear Screen Dozer Attachment - Fits John Deere 700K S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
	Asset located in: Corsicana, TX	5828	Allied W6G Crawler Tractor Winch	
5820	Cat Crawler Tractor Counterweight (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX	
	·	5829	Paccar PA56 Crawler Tractor Winch	
5821	Cat Crawler Tractor Counterweight (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX		FROM-WATKINS- FROM-WATKINS- C/W: EQUIPMENT-FROM-WATKING CONSTRUCTION Usage: Not Available Notes: TO FIT CAT D6T/D6 - CAMI	
5822	Cat Crawler Tractor Drawbar - Fits Cat D6		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5830	Paccar PA56 Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX	
		5831	Paccar PA56 Crawler Tractor Winch	
5823	Asset located in: Corsicana, TX Carco Crawler Tractor Winch - Fits Cat D8 S/N: 12608 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WAT CONSTRUCTION Usage: Not Available Notes : ITEM OPERATIONAL W FROM MACHINE; TO FIT CAT OFF WATKINS DOZERS IN TH	
5824	Carco Crawler Tractor Winch - Fits Cat D8	5022	<u>·</u>	
5826	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 2012 Midwestern M 530C Winch Pipe Laying System: Fits Cat D5 Dozer Attachment S/N: 13A12187 C/W: 15 Ft Folding Boom Usage: Not Available Asset located in: Lake Worth, TX	5832	Paccar PA56 Crawler Tractor Winch S/N: 1300340 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5833	Allied W6G Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX	5843	164 in Angle Dozer Blade - Fits Cat D6T XL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
5834	Cat Crawler Tractor Winch - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Corsicana, TX
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		162 in U-Blade Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
5835	198 in Angle Dozer Blade - Fits Cat D6 LGP S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	ONSTRUCTION	5846	162 in Angle Dozer Blade - Fits Cat D6TXL
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	S/N: Not Available C/W: EQUIPMENT-FROM- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITI BE PICKED UP WITHIN 14 AUCTION (JANUARY 3RD SUBJECT TO 3RD PARTY BUYER RESPONSIBLE FO NOT BE ABLE TO ASSIST THESE Asset located in: Corsicar 5851 160 in Angle Dozer Blade S/N: Not Available C/W: EQUIPMENT-FROM- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITI BE PICKED UP WITHIN 14 AUCTION (JANUARY 3RD SUBJECT TO 3RD PARTY BUYER RESPONSIBLE FO NOT BE ABLE TO ASSIST THESE Asset located in: Corsicar	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
	Asset located in: Corsicana, TX		BUYER RESPONSIBLE FOR LOADOUT. RB WILL
5836	194 in Angle Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
5842	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
5852	160 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5856	148 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5853	152 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	5857	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5854	150 in Angle Dozer Blade - Fits Cat D6DT S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5858	128 in PAT Dozer Blade - Fits Cat D6M S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5855	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5859	Bobcat 96 in PAT Skid Steer Dozer S/N: 224403408 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5860	24 in single grouser Tracks - Fits Cat D6 S/N: Not Available C/W: System 1; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
		5861	Ditch Witch Drill Rubber Tracks S/N: Not Available C/W: 300x52.5x98, 12 in Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5862	Mini Excavator 280x72x56 Rubber Tracks S/N: Not Available C/W: 12 in, one set Usage: Not Available Asset located in: Lake Worth, TX	5872	2022 Cat 908 1.4YD E ISO 82 in Q/C General Purpose Wheel Loader Bucket S/N: CH031183322 Usage: Not Available Asset located in: Lake Worth, TX
5863	Bobcat Mini Excavator 12 In All Purpose Rubber Tracks S/N: Not Available C/W: (1) 300x 52.5x74, (1) 300x52.5x98 Usage: Not Available Asset located in: Lake Worth, TX	5873	2022 Cat 908 1.4YD E ISO 82 in Q/C Wheel Loader Bucket S/N: CH021139822 Usage: Not Available Asset located in: Lake Worth, TX
5864	4 Cat scarifier, drawbars, trench box - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5875	JRB 102 in Q/C Wheel Loader Bucket - Fits Case 621D/ New Holland LW130B S/N: 0106-172069-211 Usage: Not Available Asset located in: Lake Worth, TX
		5876	2018 Volvo L150H4.7POSPN 35 m3 Digging Wheel Loader Bucket S/N: 18599 Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Corsicana, TX	5877	KA Fabrication 164 in Q/C Wheel Loader Forks
5867	90 in Multi-Shank Motor Grader Ripper - Fits Cat 140G S/N: RP125 Usage: Not Available Asset located in: Lake Worth, TX		- Fits Hyundai HL955 S/N: KA3246 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5867A	Motor Grader Scarifier - Fits Cat 140M S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5878	96 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5868	AMI JRB416 108 in 3.5 cyd Q/C Grapple Wheel Loader Bucket - Fits Hyundai HL955 S/N: 21041840101 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5879	2021 BR Co 84 in Q/C Wheel Loader Forks - Fits Hyundai HL955 S/N: 63782 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5869	102 in Q/C Wheel Loader Bucket S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	5881	Cat 72 in Q/C Wheel Loader Forks - Fits Cat 950 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5870	2022 Cat IT 1.5YD BU 96 in Q/C Wheel Loader Bucket S/N: CY220505839 Usage: Not Available	5882	JRB 60 in Q/C Wheel Loader Forks S/N: J458821 Usage: Not Available Asset located in: Lake Worth, TX
5871	Asset located in: Lake Worth, TX 2022 Cat 908 1.4YD E ISO 82 in Q/C General Purpose Wheel Loader Bucket S/N: CH031182822	-5883	Pemberton 60 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5883A	60 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5884	60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5889	Teran THH400BH Backhoe Hydraulic Breaker Fits Cat 416 (Unused) S/N: CAB00407C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Dispositior - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2
5885	60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST		Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5890	Teran THH400BT Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAA2730B54HR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	5890A	
5885A	56 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	5891	2018 Stanley MBX15E09 Q/C Backhoe
5886 5887	53 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Balderson BF9360 59 in Q/C Wheel Loader		Hydraulic Breaker S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Forks - Fits Cat 950 S/N: 3WL1826 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: FITS LOT 114 - CAT 950E Asset located in: Lake Worth, TX	5892	Construction Tools RX8-11 Backhoe Hydraulic Breaker S/N: BES062129 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5888	68 in Wheel Loader Quick Coupler S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5893	FRD F6 Q/C Backhoe Hydraulic Breaker S/N: 12453 Usage: Not Available Asset located in: Lake Worth, TX
		5894	Kent F6 Backhoe Hydraulic Breaker S/N: 6137 Usage: Not Available Asset located in: Lake Worth, TX
		5895	Tooth Pro 46 in Cleanup Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5896	2013 Woods Wainroy 30 in Backhoe Rear Bucket S/N: 102344430 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	5906	Strickland 12 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available
			Asset located in: Lake Worth, TX
		5907	12 in Backhoe Rear Bucket
	Asset located in: Oklahoma City, OK		S/N: Not Available
5897	28 in Digging Backhoe Rear Bucket S/N: Not Available Usage: Not Available		C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	5908	16 in Backhoe Rear Bucket
5898	24 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5899	Tooth Pro 18 in Backhoe Rear Bucket		Asset located in: Lake Worth, TX
	S/N: 2382 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5909	12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5900	Geith 18 in Backhoe Rear Bucket	5010	Hensley 16 in V-Ditching Backhoe Rear Bucket
	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5910	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5901	Tooth Pro 18 in Backhoe Rear Bucket		Asset located in: Lake Worth, TX
0,01	S/N: 5108 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5911	Quantity of (2) 18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5902	· · · · · · · · · · · · · · · · · · ·		Asset located in: Lake Worth, TX
5902	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5912	Bobcat 18 in Q/C Digging Backhoe Rear Bucket S/N: 1720020 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5903	17 in Backhoe Rear Bucket		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5913	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5904	Hensley 13 in Backhoe Rear Bucket		Asset located in: Lake Worth, TX
	S/N: 19943 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5914	24 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5905	12 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5915	John Deere 18 in Backhoe Rear Bucket S/N: 1852831 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5916	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5924	24 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5917	Tag 12 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	5925 	WB 12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5918	Notes: . Asset located in: Lake Worth, TX Tooth Pro 18 in V-Ditching Backhoe Rear Bucket S/N: 2611 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	5926	Quantity of (2) 60 in Backhoe Forks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
5919	Notes: . Asset located in: Lake Worth, TX 24 in Digging Backhoe Rear Bucket		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX		42 in Backhoe Forks - Fits Terex 760 S/N: Not Available C/W: accessories Usage: Not Available Asset located in: Lake Worth, TX
5920	Hensley 16 in V-Ditching Backhoe Rear Bucket S/N: 33666 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5928	Quantity of (3) 48 in Backhoe Forks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
5921	Hensley 12 in Digging Backhoe Rear Bucket S/N: 19884 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5922	Tooth Pro 18 in V-Ditching Backhoe Rear Bucket S/N: 4933 C/W: EQUIPMENT-FROM-A-PRIMORIS-	5929	48 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5930	44 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5923	Tooth Pro 12 in Backhoe Rear Bucket S/N: 2916 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5931	Cat 96 in Backhoe Loader Bucket S/N: 190300052 Usage: Not Available Asset located in: Lake Worth, TX
		5932	Cat 96 in Backhoe Loader Bucket S/N: 190300048 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5933	Cat 96 in Backhoe Loader Bucket S/N: 190300051 Usage: Not Available Asset located in: Lake Worth, TX	5939	39 Quantity of (8) 40 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
5934	Cat 96 in Backhoe Loader Bucket S/N: 190500058 Usage: Not Available Asset located in: Lake Worth, TX		
5935	96 in Forks S/N: Not Available Usage: Not Available		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Asset located in: Lake Worth, TX	5941	Quantity of (2) 48 ln x 56 ln Screens
5936	Quantity of (6) 72 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	5942	Post Driver Guide S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5943	Quantity of Forks (Unused) S/N: Not Available C/W: (1) 48 in set, (1) 42 in set Usage: Not Available
	<u> </u>		Asset located in: Lake Worth, TX
5937	Quantity of (4) 72 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5944	Post Driver Guide S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5945	38 In x 98 In Material Basket S/N: Not Available C/W: fork pockets Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	5946	Post Driver Guide
5938	Quantity of (4) 48 in Fork tines S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5947	44 in Misc. attachment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
			Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
		 5948	American Compaction DC18S 18 in Q/C
		J 24 0	Excavator Compaction DC18S 18 in Q/C Excavator Compaction Wheel S/N: 04038094 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5949	30 in Auger Bit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5965	Volvo 48 in L50-L120 Fork Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5949A	Quantity of (2) System One Idlers - Fits Cat D6T S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5966	42 in Fork Attachment S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5950 	2024 Mower King SSECAGY Skid Steer Auger (Unused) S/N: SSECAG-Y24060902F C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits Usage: Not Available Asset located in: Oklahoma City, OK CXI 44 in Excavator Grapple	5967	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
	S/N: ZZA1398 Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5953	Quantity of (2) 2024 Landhonor BA-22-09W 105 in Tractor Rear Blade Blade Attachment (Unused) S/N: HL00018/HL00017 C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	5968	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5954	Frontier LL1410 119 in Land Leveler Box Blade S/N: XFLL14X000009 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5955	Gannon HD244 Box Blade S/N: HD24484HXDFNG Usage: Not Available Asset located in: Lake Worth, TX	5969	2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5956	2024 Industrias America F10T 10 ft Box Scraper (Unused) S/N: F10T202435760 Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5957	2024 Industrias America F08T 96 in Box Scraper (Unused) S/N: F08T202537998 Usage: Not Available Asset located in: Lake Worth, TX	5970	Asset located in: Lake Worth, TX 2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5958	2005 ICON 18D 4 Tire Hydraulic Pull Scraper S/N: 5075A C/W: Lead Scraper, 20.5x25 Tires Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5959	Level Best PL 72D Box Scraper S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5961	Asset located in: Lake Worth, TX Volvo 72 in Wheel Loader Forks S/N: 15200002 Usage: Not Available Asset located in: Lake Worth, TX	5971	Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 78 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5972	Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 84 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX	5981	2024 Elephant EPC50 Excavator Plate Compactor (Unused) S/N: 24072900219 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5973	96 in Fork Extensions S/N: Not Available C/W: Vise Stand		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5983	Teran QCCAT336D Quick Coupler - Fits Cat 336D (Unused)
5974	Volvo Wheel Loader Material Handling Arm S/N: 252 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 5704 C/W: DB Linkage for Cat 330D, 336D Usage: Not Available Asset located in : Lake Worth, TX
5976	Caldwell 8000 lb Material Handling Arm - Fits Forklift S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	5984	Teran QCCAT320 Quick Coupler - Fits Cat 320 (Unused) S/N: 5311 C/W: B Linkage - 80mm Pins Usage: Not Available Asset located in: Lake Worth, TX
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	5985	Teran QCCAT312 Quick Coupler - Fits Cat 312 (Unused) S/N: 6159 C/W: 312 Linkage for Cat 311, 312, 314 - 65mm Pins Usage: Not Available
5976A	2013 Arrow 1000100-12-152 140 in Material		Asset located in: Lake Worth, TX
	Handling Arm S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	5986	Quantity of (4) 16 In Trench Compactor Drums S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5987	23 in Excavator Compaction Wheel
5979	2024 Jisan JSC160 Excavator Plate Compactor (Unused) S/N: 24072903224		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5988	66 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5989	66 in Padfoot Shell Kit - Fits Padfoot Shell Kit
5980	2024 Jisan JSC50 Excavator Plate Compactor (Unused) S/N: 2404290048 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: 32598 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: FITS LOT 294A AND 294B OR INGERSOLL RAND 66IN ROLLER Asset located in: Lake Worth, TX
		5990	2018 Cat CS34 50 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5991	Quantity of (4) 48 In x 48 In Steel Crane Pads S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5992	Quantity of (4) 48 In x 50 In Steel Crane Pads S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6002	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available
5993	Quantity of (3) Crane Caps		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6003	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available
5994	Johnson 4 Sheave Hook Block S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6004	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available
5995	60 ton 5 Sheave Hook Block		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6005	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available
5996	Crane Ball S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6006	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available
5997	Quantity of (2) Material Handling Arm		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: (1) Arrow CE60TH 6000 lb 80 in boom, (1) 116 in boom Usage: Not Available Asset located in: Lake Worth, TX	6007	2025 Double A 18 ft Bale Mover (Unused) S/N: 1UFBU182XST012578 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
5998	40 ft Crane Boom - Fits Grove S/N: Not Available		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: 23 Ft Swimg Away Job Usage: Not Available Asset located in : Lake Worth, TX	6008	2024 Landhonor UC-22-60W Bale Unroller (Unused)
5999	60 ton 5 Sheave Hook Block S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	6009	2024 Landhonor UC-22-60W Bale Unroller
6000	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available C/W: Assorted Size, One Pallet		(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	6010	1999 Rome TAW20S 10 ft Disc
6001	Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available C/W: Assorted Size, One Pallet		S/N: 10TAW3237R C/W: 25 in Notched Front Discs, 26 in Notched Rear Discs, 11 in Spacing, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Livingston, LA
	Usage: Not Available	6011	International 5100 13 ft 16 ft Pull-Type Air Drill
	Asset located in: Lake Worth, TX	10011	S/N: 0390213C003164 C/W: 7 in Spacing, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6012	Case 12 ft Seed Drill S/N: 0419636 C/W: 4 in Spacing, 13 in Discs Usage: Not Available Asset located in: Lake Worth, TX	6018	Steel Fluid Filter Tank S/N: Not Available C/W: 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX
6012A	SKLP 60 in 3-Point 9 Row No Till Drill (Unused) S/N: BZJ9240617 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs Usage: Not Available	6019	Scherer 28 In Kernel Processor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6012B	Asset located in: Lake Worth, TX SKLP 60 in 3-Point 9 Row No Till Drill (Unused)	6020	Quantity of Ratchet Binders S/N: Not Available
33.25	S/N: BZJ9240616 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs	6021	Usage: Not Available Asset located in: Lake Worth, TX Land Pride PD15 10 in 3-Point 15 Series Utility
	Usage: Not Available Asset located in: Lake Worth, TX		Post Hole Digger S/N: 1747822
6013	Scherer 28 In Kernel Processor S/N: W0602106010 Usage: Not Available		C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6022	Land Pride RCR1260 60 in 3-Point Brush Cutter S/N: 1820706
6013A	Strauss Clipper 20 ft Offset Sickle Bar Mower S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: 540 PTO, 3 hp Standard Duty w/Shear Bolt Usage: Not Available
6014	2012 Rhino SE8 15 ft 0 in Batwing Brush Cutter	6024	Asset located in: Lake Worth, TX Cat Bale Spear
	Attachment - Fits Tractor Drawbar S/N: 11278 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK	6024	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
6015	60 in Rotary Brush Cutter S/N: Not Available Usage: Not Available Asset located in: Midland, TX		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
6016	Land Pride RCF2060 60 in 3-Point Brush Cutter S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX	6025	Euro Double 42 in Bale Spear S/N: Not Available C/W: c/w: 2 prongs and stabilizer prong Usage: Not Available Asset located in: Lake Worth, TX
6017	60 in 3-Point Brush Cutter S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX	6025A	Quantity of (3) Auger Bit S/N: Not Available C/W: (1) 15 in, (1) 22 ln, (1) 30 ln Usage: Not Available Asset located in: Lake Worth, TX
6017A	6 ft 3-Point Hitch Rotary Mower S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX	6027	2024 Landhonor SMS-64-40G Skid-Mounted Screen (Unused) S/N: Not Available C/W: 4 ft 9 in x 4 ft 2 in Double Deck Screen Usage: Not Available Asset located in: Lake Worth, TX
6017B	John Deere MX15 15 ft Batwing Brush Cutter S/N: W0MX15E001181 C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX		ASSEL IOUGIEU III. LANE WOLLII, TA

Lot #	Details	Lot #	Details	
(Unused) S/N: Not Available C/W: 5 ft x 4 ft 6 i	S/N: Not Available C/W: 5 ft x 4 ft 6 in Double Deck Screen, THE	6035	Storage Container S/N: 2-682990-01 Usage: Not Available Asset located in: Midland, TX	
	PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	6036	16 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (0) Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6037	20 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (4) 96 in Spreader Bars Usage: Not Available	
6029	Burcham Ultimate Bagger Electric Sandbag		Asset located in: Lake Worth, TX	
	Filling Machine S/N: Not Available C/W: 12 in Conveyor, DeWalt 4 Gal Air Compressor, 12 in Conveyor & Accessories Usage: Not Available Asset located in: Lake Worth, TX	6038	8 ft x 18 ft Trench Shield S/N: 982669 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	
6030	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6039	20 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (4) 96 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	
6031	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6040	16 ft x 8 ft Trench Shield S/N: 982678 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	
6032	2024 Genius GSM-66IN Separator Magnet (Unused) S/N: GSM09112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6041	(Unused) S/N: Not Available C/W: THE PRODUCT IMA FOR ILLUSTRATION PURI MAY NOT BE AN EXACT THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IM	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6033	2024 Genius GSM-66IN Separator Magnet (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	S/N: GSM09111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6042	S/N: Not Available C/W: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOS	2024 Suihe BX-9 9 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6034	2024 Paladin SM-66-3206E 32 in x 6 ft Separator Magnet (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
6043	2024 Suihe BX-7 7 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6051	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor LHR-PC90 Vibratory Plate	
	Asset located in: Lake Worth, TX	_	Compactor (Unused) S/N: Not Available	
6044	2024 Suihe BX-5 5 cyd Bedding Box (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6053	2024 Landhonor LHR-PC90 Vibratory Plate	
6045	Quantity of (2) 2024 Kit Containers Steel 5 ft 4 in x 8 ft 2 in (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
6046	Quantity of (2) 2024 Kit Containers Steel 5 ft x	6054	2024 Landhonor LHR-PC90 Vibratory Plate	
6047	8 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	6055	Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
0047	Quantity of (2) 2024 Kit Containers Steel 5 ft x 8 ft (.75 in Thick) Steel Plates			
	S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX		6055 Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPM FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MU BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	Quantity of (4) Vibratory Plate Compactor S/N: Not Available
6048	Quantity of (2) 2024 Kit Containers Steel 6 ft x 8 ft 3 in (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX			FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
6049	Quantity of (2) 2024 Kit Containers Steel 5 ft x 10 ft (.75 in Thick) Steel Plates		NOT BE ABLE TO ASSIST WITH LOADING THESE	
	S/N: Not Available C/W: One Bundle	6056	Asset located in: Corsicana, TX Quantity of (4) Vibratory Plate Compactor	
	Usage: Not Available Asset located in: Lake Worth, TX	S/N: Not Available	S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT-	
6050	Quantity of (2) 5 ft x 10 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB W NOT BE ABLE TO ASSIST WITH LOADING THESE	

Lot #	Details	Lot #	Details
6057	Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	6064	Wacker Neuson Vibroplate BPS2050B Vibratory Plate Compactor (Unused) S/N: 11862553 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX Wacker Neuson BPS1550B Vibratory Plate
			Compactor (Unused) S/N: 11728975 C/W: Briggs & Stratton 1 Cylinder Gasoline
6058	Asset located in: Corsicana, TX Quantity of (3) Vibratory Plate Compactor	\dashv	Engine Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available	6066	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733549 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	6067	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733550
6059	Quantity of Mustang & Wacker Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine		C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6068	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused)
6060	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705481 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine		S/N: 11738243 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6069	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused)
6061	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815555 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine		S/N: 11738734 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6070	Wacker Neuson Vibroplate BPS2050BW Vibratory Plate Compactor (Unused)
6062	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705482 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine		S/N: 11666297 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	Vibratory Plate Compactor (Unus S/N: 11743232 C/W: Briggs & Stratton 1 Cylinder Engine	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused)
6063	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11743231 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		S/N: 11743232 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available

Lot #	Details	Lot #	Details
6072	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11738234 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6080	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738240 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6073	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738225 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6081	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738224 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6074	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815554 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6082	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738235 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6075	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11662551 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6083	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666300 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6076	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11737833 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6084	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666298 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6077	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728974 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6085	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815550 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6078	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728979 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6086	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815551 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6079	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705489 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6087	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815553 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6088	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11705485 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6095	Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Open Operator Station, Tier 4, 2013 US EPA Label, CARB Compliant, Kubota D1005- EF06 3 Cylinder 14.5 kW 1.0 L Diesel Engine, 24 in / 33 in Drums, Articulated Steering,
6089	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815552 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
6090	Asset located in: Lake Worth, TX Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11728978 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6096	2016 Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Kubota 3 Cylinder Diesel Engine, 24 in / 33 in Drums, Cordless Remote Control, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
6091	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666299 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6097	Asset located in: Lake Worth, TX Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Kubota 3 Cylinder Diesel Engine, 24 in / 33 in Drums, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
6092	2015 Wacker Neuson RT Trench Compactor S/N: 24250030 C/W: 2024 US EPA Label, Kohler 3 Cylinder Diesel Engine, / 32 in Drums, Remote Control w/ Cord Usage: 305 Hr Asset located in: Lake Worth, TX		
6093	Wacker Neuson RT Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA Label, CARB Compliant, Lombardini 6LBDL1. 37SFO:IFI 3 Cylinder 15.5 kW 1028 cc Diesel Engine, 33 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available	6099	Bomag BMP8500 Trench Compactor S/N: 101720134167 C/W: Open Operator Station, Tier 4, 2019 US EPA Label, Kubota D1005-EF06 3 Cylinder 14.3 kW 1.0 L Diesel Engine, 25 in / 35 in Drums, Remote Control w/ Cord, Articulated Steering Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	6100	2011 Wacker Neuson RTSC2 Trench Compactor S/N: Not Available C/W: Open Operator Station, 2011 US EPA
6094	Wacker Neuson Articulating Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA		Label, 3 Cylinder Diesel Engine, 32 in Drums, Articulated Steering Usage: Not Available Asset located in : Lake Worth, TX
	Label, CARB Compliant, Lombardini 6LBD1. 37SFO:IFI 3 Cylinder 15.5 kW 1023 cc Diesel Engine, 32 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	6101	Wacker Neuson Trench Compactor S/N: 24540169 C/W: Tier 4, 2020 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in Drums, Cordless Remote Control, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 512 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6102	S/N: 24498021 C/W: 2019 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in Drums, Remote Control w/ Cord, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 520 Hr Asset located in: Lake Worth, TX	6113	Quantity of (3) Pneumatic Chipping Hammers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		6114	Quantity of (3) Pneumatic Breakers S/N: Not Available Usage: Not Available
6103			Asset located in: Lake Worth, TX
0100	Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6115	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6104	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine	6116	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6117	Toro 23135 Mini Skid Steer Breaker S/N: 313000111 Usage: Not Available
6105	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	6118	2024 Gar-Bro Concrete Bucket S/N: 427-R DWG 14-11 Usage: Not Available Asset located in: Lake Worth, TX
6106	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6119	2014 Toro MB-1600 Walk-Behind Concrete Buggy S/N: 314000161 C/W: Hydrostatic Drive, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available
6107	2024 Landhonor LHR-RM90 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available	6120	Asset located in: Lake Worth, TX Bad Boy Electric Utility Vehicle S/N: BBE514B3785006557 C/W: Canopy, 2 Passenger, Winch, Brush Guard
	Asset located in: Lake Worth, TX		Usage: Not Available Asset located in : Lake Worth, TX
6109	Bomag Jumping Jack Tamper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6121	Mortar and Grout Mixer S/N: Not Available C/W: 2013 US EPA Label, Honda GX240 Gasoline Engine, S/A Trailer, Ball Hitch,
6110	Quantity of Concrete Hoppers & Stand S/N: Not Available Usage: Not Available		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6122	2024 Landhonor LHR-CM300 Portable
6111	2007 Starind 1550 Concrete Chute S/N: Not Available C/W: Fork Pockets; EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available		Concrete Mixer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6123	2024 Landhonor LHR-CM400 Portable Concrete Mixer (Unused)
6112	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details	
6124	Quantity of (2) Walk-Behind Saws S/N: 2800003 / 3A9S46M10G1168026 C/W: Water Hose Connection, Manual Blade Raise / Lower, Honda GX390 1 Cylinder Gasoline Engine, (1) Husqvarna FS513 Walk- Behind Saw s/n: 2800003 & (1) Tiger MSM Walk-Behind Saw s/n: 3A9S46M10G1168026	6137	2010 Whiteman WRS-5200 Concrete Screed S/N: WG1800464 C/W: 7 ft Screed, 41 ft Boom Length, 2009 US EPA Label, Daihatsu 3 Cylinder Diesel Engine Usage: 24 Hr Asset located in: Lake Worth, TX	
	(Inoperable) Usage: Not Available Asset located in: Lake Worth, TX	6138	Forms S/N: Not Available C/W: 16 in Wide, (1) 7 ft 6 in, (1) 8 ft, (1) 7 Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MI BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES BUYER RESPONSIBLE FOR LOADOUT. RE	
6126	2024 Landhonor LHR-Q300 Heavy Duty Concrete Floor Walk-Behind Saw (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX			Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
6129	2019 Core Cut Walk-Behind Saw S/N: 162276 C/W: 30 in Max Blade Diameter, 15 in Max		THESE Asset located in: Lahoma, OK	
	Cutting Depth, Hydraulic Blade Raise / Lower, 2019 US EPA Label, Kubota 4 Cylinder 2.6 L Diesel Engine Usage: 1,607 Hr	6139	8 ft Man Guard S/N: Not Available Usage: Not Available	
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
6130	2012 Hsqvarna 4000 Walk-Behind Saw S/N: 001309168002 C/W: 13 in Max Blade Diameter, 6.5 in Max Cutting Depth, Manual Blade Raise / Lower, Kohler 20 hp 624 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6140	8 ft Man Guard S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	
		6141	NTS 52-88 in Trench Shield S/N: Not Available Usage: Not Available	
6131	Merit 600.62DR4 Walk-Behind Saw S/N: 10002020 C/W: 4 Cylinder Diesel Engine, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 780 Hr Asset located in: Lake Worth, TX	6142	Asset located in: Lake Worth, TX 2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	
6133	Quantity of (3) 2018 Multiquip B46H11H Power Trowel S/N: MG0112140/MF0111393/MG0112160 C/W: Honda Gas Engine, (2) 42 In, (1) 36 In Usage: Not Available Asset located in: Lake Worth, TX	6143	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	
6134	Wacker Electric Concrete Vibrator S/N: 1782595 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6144	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	
6136	2013 Edco 2EC-NG-1.5 Electric Concrete Grinder S/N: 130910129 C/W: 22 in Grinding Width, 2 Grinding Discs, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6145	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6146	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	6154	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6147	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates	6155	
	Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6148	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available	6156	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6149	Asset located in: Lake Worth, TX 2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX		2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6150	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6158	Asset located in: Lake Worth, TX 2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6151	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6152	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6153	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6160	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6166	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6161	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	6167	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6162	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6168	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6163	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6169	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6164	Asset located in: Lake Worth, TX 2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	6170	Asset located in: Lake Worth, TX 2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6171	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport Shed (Unused) S/N: Not Available
6165	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6172	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6173	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6179	2024 SUNTOP S1220 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6174	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)		THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6180	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6175	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6181	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION C THE ACTUAL PRODUCT
6176	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)	6182	Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
6177	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6183	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6178	2024 SUNTOP S1220 Metal Shed (Unused) S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6184	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6185	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6192	2024 Landhonor LHR-CP1119 11 ft x 19 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6193	2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available
6186	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6194	2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6195	2024 Landhonor PLD-MS0608 6 ft x 8 ft
6187	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Galvanized Metal Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6196	2024 Landhonor PLD-MS0608 6 ft x 8 ft Galvanized Metal Shed (Unused) S/N: Not Available
6188	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)		C/W: Two Boxes Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6197	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6189	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available	6198	2024 Landhonor PLD-MS0604P 6 ft x 4 ft
	Asset located in: Lake Worth, TX	4	Galvanized Metal Pent Shed (Unused) S/N: Not Available
6190	KJ K1220 12 Ft x 20 Ft Single Garage Metal Shed S/N: Not Available	6199	C/W: Two Boxes Usage: Not Available Asset located in : Lake Worth, TX
	C/W: one crate Usage: Not Available Asset located in : Lake Worth, TX		Quantity of (2) 4 Ft x 6 Ft Metal Shed S/N: Not Available C/W: two boxes
6191	2024 Landhonor LHR-CP1119 11 ft x 19 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6201	Cummins 200DGFC-5199 200 kW Skid-Mounted Stand-By Generator Set S/N: D050767149 C/W: US EPA Label, Cummins 6CTAA8.3G3 6 Cylinder 8.3 L Diesel Engine, 250 kVA/200 kW Rated 3 Phase Output, 134 kVA,/134 kW, Rated Single Phase Output, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, E-Stops Usage: Not Available Asset located in: Lake Worth, TX	6210	2019 Magnum Pro MMG45IF4 38 kW Mobile Generator Set S/N: 3004557276 C/W: 2019 US EPA Label, Isuzu BQ4IE2X 19 kW 2.2 L Diesel Engine, 33 kVA/ Rated 3 Phase Output, 480 V / 208 V Rated Voltage, 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes, EQUIPMENT FROM UNITED RENTALS Usage: 13,399 Hr Asset located in: Lake Worth, TX
6205A	Cat Mobile Generator Set S/N: C11-12-05372 C/W: 2011 US EPA Label, CARB Compliant, Perkins 3362 4 Cylinder 116.9 kW 4.4 L Diesel Engine, 100 kVA/80 kW Rated 3 Phase Output, 480 V / 208 V / 120 V Rated Voltage, 100 kVA, /80 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: Not Available Asset located in: Midland, TX	6212	2013 Wacker Neuson G50 38 kW Mobile Generator Set S/N: 4TCSU1851DH189075 C/W: 2013 US EPA Label, John Deere 4045Tf290B 4 Cylinder 4.5 L Diesel Engine, 48 kVA/38 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Lunette Ring Usage: Not Available Asset located in: Lake Worth, TX
6206	2016 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 7353339 C/W: Isuzu BR-4JJ1X 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 12,507 Hr Notes: Asset located in: Lake Worth, TX	6214	2014 Multiquip DCA-45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1222EL014135 C/W: 2014 US EPA Label, Isuzu 4LE2X 4 Cylinder 56 kW 2.1 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,121 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; SUNSTATE EQUIPMENT CO.
6208	2005 Katolight 50 kW Mobile Stand-By Generator Set S/N: 5FTGE102051024328 C/W: 2004 US EPA Label, John Deere 5030TF270C 5 Cylinder 60 kW 3.0 L Diesel Engine, 50 kVA,/50 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 20,410 Hr Asset located in: Lake Worth, TX		RENTAL PEOPLE YOU CAN DEPEND Asset located in: Lake Worth, TX 6214 2012 Multiquip DCA-45SSIU4 36 kW Generator Set S/N: 4GNBG1221CB030860 C/W: Isuzu 4JJ1T 4 Cylinder 2.99 L Engine, 45 kVA/36 kW Rated 3 Phase 240 V / 480 V Rated Voltage, 26 kW Rated Single Phase Output, 240 V / Rated Voltage, 240 V & 120 V Receptors
6209	Allmand MP45-8E1 45 kVA Mobile Generator Set S/N: 1338E10446		T/A Trailer, Lunette Ring, Surge Brakes Usage: 24,512 Hr Asset located in: Lake Worth, TX
	C/W: 2018 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 120 V Rated Voltage, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: 2,301 Hr Asset located in: Lake Worth, TX	6215	Cat Mobile Generator Set S/N: 1JG110206N1606402 C/W: Cat 4 Cylinder Diesel Engine, T/A Trailer, Ball Hitch, Electric Brakes Usage: 1,300 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6217	Allmand MP25 25 kVA Skid-Mounted Generator Set S/N: 1238E12204 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 9,942 Hr Asset located in: Lake Worth, TX Allmand MP25 25 kVA Skid-Mounted Generator Set	6223	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 7152111 C/W: 2015 US EPA Label, Isuzu 4LE2T 4 Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14 kVA,/14 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 2,725 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	S/N: 1238E12050 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 10,981 Hr Asset located in: Lake Worth, TX	6224 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 7154328 C/W: Isuzu 4LE2T 4 Cylinder 2.17 L Diese Engine, 25 kVA/20 kW Rated 3 Phase Out 240 V / 480 V Rated Voltage, 14.4 kVA,/14 kW, Rated Single Phase Output, 240 V / 14 Rated Voltage, 240 V & 120 V Receptacles Trailer Usage: 1,822 Hr Asset located in: Lake Worth, TX 6225 Multiquip DCA45SSIU4F 45 kW Mobile Generator Set S/N: 7252100 C/W: US EPA Label, Isuzu BP-4LE2X 4 Cyl 49 kW Diesel Engine, 45 kVA/36 kW Rated Phase Output, 240 V / 480 V Rated Voltage kVA,/26 kW, Rated Single Phase Output, 2 / 120 V Rated Voltage, 240 V & 120 V Receptacles, T/A Trailer, Lunette Ring, Sur Brakes Usage: 10,993 Hr Asset located in: Lake Worth, TX 6226 2016 Atlas Copco 20 kW Mobile Generato S/N: 4500G1111GR121222 C/W: 4 Cylinder Diesel Engine, 25 kVA/20	Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 7154328 C/W: Isuzu 4LE2T 4 Cylinder 2.17 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4
6219	Allmand MP25 25 kVA Skid-Mounted Generator Set S/N: 1238E12221 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 20 kW Discapl Engine 120 V (240 V (Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer Usage: 1,822 Hr
	Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 11,249 Hr Asset located in : Lake Worth, TX		Generator Set S/N: 7252100 C/W: US EPA Label, Isuzu BP-4LE2X 4 Cylinder
6220	Airman SDG25S 25 kVA Skid-Mounted Generator Set S/N: 1238E13551 C/W: 2022 US EPA Label, Isuzu 4 Cylinder 30 kW Diesel Engine, 25 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank		Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, T/A Trailer, Lunette Ring, Surge Brakes Usage: 10,993 Hr
6221	Usage: 13,453 Hr Asset located in: Lake Worth, TX 2017 Multiquip DCA-25SSIU4F 20 kW Mobile		2016 Atlas Copco 20 kW Mobile Generator Set S/N: 4500G1111GR121222 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated
0221	Generator Set S/N: 4GNBG0918HB044057 C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 2.1 L Diesel Engine, 25 kVA/20 kW		Voltage, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 1,895 Hr Asset located in: Lake Worth, TX
	Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 768 Hr Asset located in: Lake Worth, TX	6228	2006 MMD SDG25S 20 kVA Mobile Generator Set S/N: 5UABU09196V000009 C/W: 2006 US EPA Label, Isuzu 4LE1 4 Cylinder 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output,
6222	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0910GB043032 C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 37 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 7,983 Hr Asset located in: Lake Worth, TX		240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 5,460 Hr Asset located in: Lake Worth, TX
		6233	Generac Guardian 24 kW Stand-By Generator Set S/N: Not Available C/W: Natural Gas Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6234	1997 Kohler 40RZ Electric Transfer Switch S/N: 384987 Usage: Not Available Asset located in : Lake Worth, TX	6243	3 2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0410PM003593 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 2 Lamps, Power Receptacles, S/A Trailer, Ball Hitch
6235	2018 Allmand 7 kW Light Tower S/N: 5AEA1AC17JH000125		Usage: 1 Hr Asset located in: Humble, TX
	C/W: Tier 4, 2015 US EPA Label, Kubota d1105 3 Cylinder 12 kW 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,070 Hr Asset located in: Lake Worth, TX	6244	2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416PM003596 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, S /A Trailer, Ball Hitch
6236	2018 Allmand 7 kW Light Tower S/N: 5AEA1AC19JH000334 C/W: Tier 4, 2017 US EPA Label, Kubota d1005		Usage: 1 Hr Asset located in: Humble, TX
	3 Cylinder 10 kW 1 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,493 Hr Asset located in: Lake Worth, TX	6245	2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0414PM003595 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps,
6237	2018 Allmand NLV-P Light Tower S/N: 5AEA1DA16KH003245		Power Receptacles, S/A Trailer, Ball Hitch Usage: 8 Hr Asset located in : Humble, TX
	C/W: Perkins 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,502 Hr Asset located in : Lake Worth, TX	6246	2023 Wacker Neuson 6 kW Light Tower S/N: 5XFLV0416PM000889 C/W: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch
6238	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07-001037 C/W: Tier 4, 2017 US EPA Label, CARB		Usage: 9 Hr
		6047	Asset located in: Humble, TX
	Compliant, Kubota D1005-BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Balloon Diffuser, S/A Trailer, Ball Hitch Usage: 4,887 Hr Asset located in : Midland, TX	6247	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0417JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr
6239	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07000969 C/W: 2015 US EPA Label, Kubota 3 Cylinder 1.1		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: 4,827 Hr Asset located in: Midland, TX	6248	Asset located in: Lake Worth, TX 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19
6240	2016 Allmand 8KWNLP 1250 W Light Tower S/N: 07-000162 C/W: Cat c1.1 3 Cylinder Diesel Engine, 4		kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes : ADDITIONAL INFORMATION
	Lamps, S/A Trailer, Ball Hitch Usage: 2,815 Hr Asset located in : Lake Worth, TX		AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
6241	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA4LU497838 C/W: Tier 4, 2019 US EPA Label, Kubota D1005-BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 300 Hr Asset located in: Lake Worth, TX	6249	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
6242	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA2LU497952 C/W: Tier 4, 2019 US EPA Label, Kubota D1005-BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 294 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6250	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0413JM003840 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,346 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	6259	2017 Generac MLT6SMD Light Tower S/N: 3001517568 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 803 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
6251	2019 Magnum Pro MLT6SM 6 kW Light Tower S/N: 7FSBL1012KB834551 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,483 Hr Asset located in: Lake Worth, TX	6261	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1016HB880618 C/W: US EPA Label, Mitsubishi 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,312 Hr Notes: ADDITIONAL INFORMATION	
6252	2019 Magnum MLT6SMD Light Tower		AVAILABLE IN OFFICE - MSO ; Asset located in : Lake Worth, TX	
	S/N: 7FSBL1013JB992752 C/W: US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 673 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX	6262	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1013HB568871 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 3,886 Hr	
6253	2018 Magnum MLT6SMD 6 kW Light Tower S/N: 7FSBL1010JB983099 C/W: 2018 US EPA Label, Mitsubishi L3E 3		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO ;	
			Asset located in: Lake Worth, TX	
	Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6263	S/N: 7FSBL1011HB880896 C/W: 2017 US EPA Label, Mitsubishi Li Cylinder 1.0 L Diesel Engine, 4 Lamps, Lighting, Power Receptacles, S/A Trail Hitch	S/N: 7FSBL1011HB880896 C/W: 2017 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch
6254	2018 Magnum Pro MLT6SM 6 kW Light Tower S/N: 7FSBL1010JB586914 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power		Usage: 6,613 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	
	Receptacles, S/A Trailer, Ball Hitch Usage: 8,910 Hr Asset located in: Lake Worth, TX	6264	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1011HB880607 C/W: 2017 US EPA Label, Mitsubishi L3E-	
6256	2018 Magnum MLT6SK Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		W464MLD 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch, Electric Brakes Usage: 6,831 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; 3001880607 Asset located in: Lake Worth, TX	
6257	2018 Wacker Neuson LTV6K Light Tower	6265	2019 Terex RL4 6 kW Light Tower	
	S/N: WNCLTV02CPUM04886 Usage: 9,720 Hr Asset located in : Lake Worth, TX		S/N: 4ZJSA1015J1009757 C/W: 2018 US EPA Label, Deutz 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: Not Available	
6258	2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,788 Hr Asset located in: Lake Worth, TX		Asset located in: Midland, TX	

Lot #	Details	Lot #	Details	
6266	2016 Terex RL4 6 kW Light Tower S/N: RL416J-1024 C/W: 2015 US EPA Label, Kohler FKHXL1.3 3 Cylinder 8 kW 1.3 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8,753 Mi Notes: LOCATED-IN-HOUSTON-TX; EQUIPMENT FROM SUNBELT RENTALS; Asset located in: Humble, TX	6276	2012 Sullair 900H Mobile Air Compressor S/N: 201202150037 C/W: Air Dryer, 250 psi Working Pressure, Cat C9 6 Cylinder Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: CERTIFICATE OF ORIGIN AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX	
6267	2011 Magnum MLT3060M Light Tower	6277	2015 Doosan XP825WCU Mobile Air	
	S/N: 5AJLS1614BB006243 C/W: 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,275 Hr Asset located in: Lake Worth, TX	02//	Compressor S/N: 4FVCBBFB3FU46608 C/W: 250 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, T/A Trailer, Lunette Ring, Electric	
6268	2014 Allmand PAL1250W2 Light Tower S/N: 0202PAL14 C/W: Single Lamp, EQUIPMENT-FROM-		Brakes Usage: 3,198 Hr Asset located in : Lake Worth, TX	
	SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6278	2012 Atlas Copco XAS750JD7T3 Mobile Air Compressor S/N: 4500B1611CR080883	
6269	2014 Allmand PAL1250W2 Light Tower S/N: 0203PAL14 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available		C/W: 261 psi Working Pressure, John Deere 6 Cylinder 6.8 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 468 Hr Asset located in : Lake Worth, TX	
	Asset located in: Lake Worth, TX	6280	•	
6270	2012 Allmand Light Tower S/N: 0229PAL12 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available		S/N: C16B10076 C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 6,172 Hr Asset located in : Lake Worth, TX	
	Asset located in: Lake Worth, TX	6281	Airman PDS400S Mobile Air Compressor	
6271	2012 Allmand Light Tower S/N: 0224PAL12 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available		Trailer, Ball Hitch Usage: 3,252 Hr	C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch
	Asset located in: Lake Worth, TX	6282	2018 Doosan HP375WCU-T4F Mobile Air	
6273	2018 Doosan HP1600WCU-T4F 1600 cfm Mobile Air Compressor S/N: 4FVCCBPB8JU483256 C/W: 150 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, T/A Trailer, Lunette Ring, Electric Brakes Usage: 1,806 Hr		Compressor S/N: Not Available C/W: 250 psi Working Pressure, 2018 US EPA Label, Cummins QSB4.5 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch, Electric Brakes Usage: 4,337 Hr Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6283	2017 Doosan P425/HP375 Mobile Air	
6275	2011 Doosan HP1600 Mobile Air Compressor S/N: 419233UJUB83 C/W: 200 psi Working Pressure, 2019 US EPA Label, Cummins QSX15 6 Cylinder 344 hp 15 L Diesel Engine, T/A Trailer, Lunette Ring Usage: 9,344 Hr Asset located in: Lake Worth, TX		Compressor S/N: Not Available C/W: 2017 US EPA Label, Cummins 6 Cylinder 130 hp 4.8 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes Usage: 1,709 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6284	2017 Doosan P425/HP375WCU-T4F Mobile Air Compressor S/N: Not Available C/W: 2017 US EPA Label, Cummins 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes Usage: 3,099 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2016 Atlas Copco XATS400PEJD7 Mobile Air	6294	2021 Kaeser M55 PE 185 cfm Mobile Air Compressor S/N: WKA0N1000M8357329 C/W: 125 psi Working Pressure, Kubota D1803- CR-EF01 3 Cylinder 1.8 L Diesel Engine, S/A Trailer Usage: Not Available Asset located in: Lake Worth, TX 2021 Kaeser M55 PE 185 cfm Mobile Air Compressor S/N: WKA0N1000M8357356 C/W: 125 psi Working Pressure, 2019 US EPA
0200	Compressor S/N: 4500B1315GR076376 C/W: 175 psi Working Pressure, John Deere 4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,560 Hr		Label, Kubota D1803-CR-T-EF01 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,054 Hr Asset located in: Lake Worth, TX 2020 Kaesar M58 210 cfm Skid-Mounted Air
6286	Asset located in: Lake Worth, TX 2013 Atlas Copco XATS400JD7 Mobile Air Compressor S/N: 4500B1310DR074160 C/W: 175 psi Working Pressure, John Deere 4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring		Compressor S/N: 10627593833 C/W: 100 psi Working Pressure, Kubota V2403- CR-EF08 4 Cylinder 36 kW 2.4 L Diesel Engine Usage: 3,987 Hr Asset located in: Lake Worth, TX
	Usage: 2,323 Hr Asset located in: Lake Worth, TX	6296	2020 Kaeser M58 210 cfm Skid-Mounted Air Compressor S/N: 10607586681
6287	2011 Atlas Copco XAVS375 Mobile Air Compressor S/N: 4500B1312BR071984 C/W: 2011 US EPA Label, John Deere 4045HF285 4 Cylinder 4.5 L Diesel Engine	6297	C/W: 100 psi Working Pressure, 2018 US EPA Label, Kubota V2403-CR-EF08 3 Cylinder 36 kW 2.4 L Diesel Engine Usage: 4,335 Hr Asset located in: Lake Worth, TX
	Usage: 889 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lahoma, OK		2015 Atlas Copco XAS185KD7PE 185 cfm Mobile Air Compressor S/N: 4500A1013FR049103 C/W: 123 psi Working Pressure, 2014 US EPA Label, Kubota V2403-CR-EF02 3 Cylinder 36.8 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 976 Hr
6290	2021 Atlas Copco XAS188 KD8 Air Compressor S/N: UVC200482		Asset located in: Lake Worth, TX
	Usage: 13 Hr Asset located in: Lake Worth, TX	6298	2021 Chicago Pneumatic CPS 185 KD8 Air Compressor
6291	2021 Atlas Copco XAS188 KD8 Mobile Air Compressor		S/N: HOP030934 Usage: 7 Hr Asset located in : Lake Worth, TX
	S/N: 4500A1017MR200473 C/W: 125 psi Working Pressure, Kubota D1803- T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in : Lake Worth, TX	6299	2021 Airman PDS185S Mobile Air Compressor S/N: 7H6BY11A6MA002935 C/W: 200 psi Working Pressure, 2021 US EPA Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 185 Hr
6292	2021 Atlas Copco XAS188 KD8 Mobile Air Compressor S/N: 4500A1012MR200476 C/W: 125 psi Working Pressure, Kubota D1803- T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6300	Airman PDS185S 185 cfm Skid-Mounted Air Compressor S/N: B4-6811098 C/W: 150 psi Working Pressure, 2003 US EPA Label, Isuzu NE2 4 Cylinder 2.17 L Diesel Engine Usage: 1,840 Hr Asset located in: Lake Worth, TX	6306	2017 Doosan C185WDZ Mobile Air Compressor S/N: 4FVCABAA8HU479739 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,131 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
6301	2019 Allmand Maxi-Air 185 Mobile Air		Asset located in: Lake Worth, TX
0301	Compressor S/N: 5AEA1KF10KH000628 C/W: 200 psi Working Pressure, 2018 US EPA Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 9,961 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6307	2017 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 479354UAABG07 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,381 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE -MSO Asset located in: Lake Worth, TX
6302	2019 Allmand MA185-5E1 185 cfm Mobile Air Compressor S/N: 5AEA1KF15KH000737 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 6,855 Hr Asset located in: Lake Worth, TX	6308	2017 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 4FVCABAA2HU479803 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,825 Hr Notes: ADDITIONAL INFORMATION
6303	2020 Allmand MA185-6E1 185 cfm Mobile Air	6309	AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
6304	Compressor S/N: 5AEA1KF16LH000831 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 8,456 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; CERTIFICATE OF ORIGIN AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX 2018 Sullair 185DPQ-KU-T3 185 cfm Mobile Air		2012 Doosan C185WJD-T4I Mobile Air Compressor S/N: 4314506UIVE43 C/W: 200 psi Working Pressure, 2011 US EPA Label, CARB Compliant, John Deere 4024TF281C 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,197 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Compressor S/N: 201801250011 C/W: 200 psi Working Pressure, 2017 US EPA Label, Kubota D1803 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT FROM UNITED RENTALS Usage: 2,460 Hr Asset located in: Lake Worth, TX		Asset located in: Humble, TX 2010 Doosan C185 185 cfm Mobile Air Compressor S/N: Not Available C/W: 2010 US EPA Label, Kubota V2403 36.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,140 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
6305	2018 Doosan P185WDOU-T4F 185 cfm Skid-		THE INSPECTION REPORT
	Mounted Air Compressor S/N: 486622UFAGF89	6311	Asset located in: Humble, TX
	C/W: 185 psi Working Pressure, 2018 US EPA Label, CARB Compliant, Doosan 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Midland, TX	0311	Ingersoll Rand 185 Mobile Air Compressor S/N: 151780U85957 C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine Usage: 3,697 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK

Lot #	Details	Lot #	Details
6312	2013 Sullivan D185PJDSB Mobile Air Compressor S/N: 31811 C/W: 100 psi Working Pressure, John Deere 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,438 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6318	2017 Atlas Copco XAS185KD7PET4F Mobile Air Compressor S/N: 4500A1012HR055090 C/W: Kubota 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 947 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX
6313	2013 Sullivan Palatek 185 cfm Mobile Air Compressor S/N: 101343 C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF231A 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,018 Hr Asset located in: Lake Worth, TX	-6319	2017 Atlas Copco XAS185KD7PET4F Mobile Air Compressor S/N: 4500A1012HR055414 C/W: 2017 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
6314	2018 Sullair 185DPQ Mobile Air Compressor S/N: 201802270074 C/W: 185 psi Working Pressure, 2017 US EPA Label, Kubota 4 Cylinder 36 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,685 Hr Asset located in: Lake Worth, TX	6320	2013 Ingersoll Rand 185 cfm Mobile Air Compressor S/N: 4FVCABAAXDU454478 C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF281C 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-
6315	2011 Sullair 185DPQJD Skid-Mounted Air Compressor S/N: 201107210060 C/W: 185 psi Working Pressure, 2011 US EPA Label, John Deere 4024TF 4 Cylinder 37 kW 2.4 L Diesel Engine Usage: 2,365 Hr	6321	CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 2011 Atlas Copco XAS185JDRSC Mobile Air Compressor S/N: 4500A1019BR038617 C/W: 2011 US EPA Label, John Deere
6316	Asset located in: Lake Worth, TX 2004 Sullair 250DPQ-JDD Mobile Air Compressor S/N: 2004100085 C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine		4024TF281A 4 Cylinder 2.4 L Diesel Engine Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
6317	Usage: 3,195 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK 2017 Atlas Copco XAS185KD Mobile Air Compressor	6322	2007 Airman PDS185S 185 cfm Mobile Air Compressor S/N: B46B44752 C/W: 150 psi Working Pressure, 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 1,309 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY
	S/N: 4500A1014HR055415 C/W: 185 psi Working Pressure, 2017 US EPA Label, Kubota 3 Cylinder 1.8 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 1,075 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6324	Asset located in: Lake Worth, TX 2021 Rotair D400T4F 150 cfm Mobile Air Compressor S/N: 16MBB1319MD081696 C/W: 150 psi Working Pressure, 2021 US EPA Label, Cummins QSF3.8 4 Cylinder 3.8 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch Usage: 1,709 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6325A	Sullair Skid-Mounted Air Compressor S/N: 5AEA1KF15KH000737 C/W: 185 psi Working Pressure, 2011 US EPA Label, John Deere 4024TF 4 Cylinder 37 kW 2.4 L Diesel Engine Usage: 979 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	6332	2015 Miller Trailblazer 251 Multi-Process Engine Driven Welder S/N: MF500520R C/W: 2015 US EPA Label, Kohler CH730 725 cc Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 2,736 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6333	2016 Miller Bobcat 250 Mobile Multi-Process Engine Driven Welder
6325B	Genaer Skid-Mounted Air Compressor S/N: 1611 C/W: 15 hp Motor, 2014 US EPA Label, Kubota V3800 4 Cylinder 3.8 L Diesel Engine Usage: Not Available Asset located in: Midland, TX		S/N: MG310150R C/W: 2016 US EPA Label, Kohler 3 Cylinder 725 cc Engine, 240 V / 208 V Rated Voltage, 120 V Rated Voltage Usage: 619 Hr Asset located in: Lake Worth, TX
6325C	Smith Mobile Air Compressor	6224	·
	S/N: 100510361 C/W: 125 psi Working Pressure, Ford 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX	6334	Lincoln Vantage 500 Multi-Process Engine Driven Welder S/N: U11400 C/W: Diesel Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 1,576 Hr
6327	2006 Miller Bobcat 250 Multi-Process Engine		Asset located in: Lake Worth, TX
6328	Driven Welder S/N: LG076841 C/W: Kohler Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 213 Hr Asset located in: Lake Worth, TX 2013 Lincoln Vantage 300 400 A Skid-Mounted Multi-Process Engine Driven Welder		2005 Miller Bobcat 250 Skid-Mounted Multi- Process Engine Driven Welder S/N: LF041958 C/W: 2005 US EPA Label, Kohler CH20S 624 cc Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 1,686 Hr Asset located in: Lake Worth, TX
	S/N: U1130305650 C/W: Tier 4, 2012 US EPA Label, CARB Compliant, Kohler V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 4,763 Hr Asset located in: Lake Worth, TX		Lincoln Vantage 520SD 520 A Mobile Stick Engine Driven Welder S/N: Not Available C/W: 2015 US EPA Label, Deutz d2.9I 4 Cylinder 40 hp 2.9 L Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available
6329	2013 Lincoln Vantage 300 400 A Skid-Mounted Multi-Process Engine Driven Welder		Asset located in: Lake Worth, TX
	S/N: U1130301883 C/W: 2012 US EPA Label, CARB Compliant, Kubota V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 5,080 Hr Asset located in: Lake Worth, TX	6338	Quantity of (2) Miller Millermatic 255 Wire Electric Welder S/N: NA168518N/NB358903N C/W: Single Phase, 200 V/ 240 V Input, Welding Leads, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: .
6330	2020 Miller Bobcat 260 Multi-Process Engine		Asset located in: Lake Worth, TX
	Driven Welder S/N: NA300101R C/W: Kohler Engine, Welding Leads, 120 V / 240 V Rated Voltage, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 496 Hr Notes: . Asset located in: Lake Worth, TX	6339	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder S/N: Not Available C/W: 2013 US EPA Label, Kubota v1505 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage Usage: 4,301 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6340	2012 Gorman-Rupp PA6C60-4045T Trailer- Mounted Water Pump S/N: 1493129N C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 8,350 Hr Asset located in: Lake Worth, TX Gorman-Rupp Mobile Centrifugal Pump S/N: Not Available C/W: US EPA Label, John Deere 4 Cylinder Diesel Engine	6346	Quantity of (3) Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6347	Quantity of (3) Water Pump
6342	Slanzi Skid-Mounted Water Pump S/N: 249606 C/W: 4 in Intake, 3 in Discharge, Centrifugal Water Pump, Slanzi 4 Cylinder Diesel Engine Usage: 183 Hr	6348	S/N: Not Available C/W: 3 in Intake, 2 in Discharge Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Water Pump
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL		S/N: Not Available C/W: 2 in Intake, 3 in Discharge Usage: Not Available Asset located in : Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	6349	Quantity of (3) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available
6343	2022 Stealth Trailer-Mounted Water Pump S/N: 1R9RBUAA7NS723142 C/W: 6 in Intake, 6 in Discharge, Centrifugal		C/W: Trash Pump, 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Water Pump, 2021 US EPA Label, CARB Compliant, Deutz TD2.9L4 4 Cylinder 55.4 kW 2.92 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,064 Hr Asset located in: Midland, TX		Quantity of (2) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Trash Pump Usage: Not Available
6344	6 In Water Pump S/N: Not Available	6352	Asset located in: Lake Worth, TX Cornell 25WHRPPF86 Electric Skid-Mounted
6345	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Water Pump S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Water Pump, EQUIPMENT-FROM-WATKINS-CONSTRUCTION	Water Pump S/N: 2530458 C/W: 3 in Intake, 2.5 in Disc WEC 25 Hp Electric Motor; US-AUTO-RECYCLING Usage: Not Available	S/N: 2530458 C/W: 3 in Intake, 2.5 in Discharge, Centrifugal, WEC 25 Hp Electric Motor; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	6353	Asset located in: Lake Worth, TX Skid-Mounted Water Pump S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal Trash Pump, 2014 US EPA Label, Honda 270 cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
6354	Quantity of Pump & PTO S/N: Not Available C/W: MC L0614SC Triplex pump, Muncie PTO, (2) Tanks, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	6361A	2015 Toyota 8FG35U 7300 lb Cushion Tire Forklift S/N: 10863 C/W: 3 Stage Mast, 159.5 in Max Lift Height, 106 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 2015 US EPA Label, Toyota 4 Cylinder 63 kW 3.6 L LPG Engine
6356	Taylor Y-23WOF 23000 lb Dual Front Tires Pneumatic Tire Forklift		Usage: 1,917 Hr Asset located in: Lake Worth, TX
	S/N: S2113943 C/W: 2 Stage Mast, 24 in Lowered Mast Height, 93 in Forks, Solid Pneumatic Tires, Detroit 4 Cylinder Diesel Engine Usage: 6,519 Hr	6362	2007 TCM FD70-9 12980 lb Pneumatic Tire Forklift S/N: A30K00809 C/W: 2 Stage Mast, 157 in Max Lift Height, 96
6357	Asset located in: Lake Worth, TX 2005 Hyster H155XL2 12700 lb Pneumatic Tire		in Lowered Mast Height, 94 in Forks, Fork Positioner, 4 Cylinder Diesel Engine Usage: 5,357 Hr
	145 in Lowered Mast Height, 47 in Forks, Side Shift, V6 LPG Engine	6363	Asset located in: Lake Worth, TX 2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001161 C/W: 3 Stage Mast, 189 in Max Lift Height, 89
6358	Usage: 4,200 Hr Asset located in: Lake Worth, TX Doosan GC55C-9 11850 lb Pneumatic Tire	6364	in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 22 Hr
	Forklift		Asset located in: Lake Worth, TX
	S/N: FGB1C256000013 C/W: 2 Stage Mast, 162 in Max Lift Height, 82 in Lowered Mast Height, 59 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 3 Cylinder LPG Engine Usage: 7,819 Hr Asset located in: Lake Worth, TX		2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001163 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 2 Hr
6359	2017 Toyota 8FG45U 9300 lb Pneumatic Tire Forklift		Asset located in: Lake Worth, TX
	S/N: 11419 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 92 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4 Cylinder 3.6 L LPG Engine Usage: 1,152 Hr Asset located in: Lake Worth, TX	6365	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001164 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1 Hr
6360	1998 Mitsubishi FD35 8000 lb Pneumatic Tire	6066	Asset located in: Lake Worth, TX
	Forklift S/N: AF19B00320 C/W: 2 Stage Mast, 148 in Max Lift Height, 97 in Lowered Mast Height, 48 in Forks, Side Shift, Mitsubishi 6 Cylinder Diesel Engine Usage: 9,917 Hr Asset located in: Lake Worth, TX	6366	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001157 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX
6361	2001 Hyster H80XM 7700 lb Pneumatic Tire Forklift S/N: K005A04243Y C/W: 2 Stage Mast, 122 in Max Lift Height, 57 in Forks, Fork Positioner, Solid Pneumatic Tires, V6 LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6367	2014 Toyota 8FD35U 6500 lb Pneumatic Tire Forklift S/N: 8FD35U-10678 C/W: 3 Stage Mast, 187 in Max Lift Height, 72 in Forks, Fork Positioner, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4 Cylinder Diesel Engine Usage: 5,597 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6367A	2004 Toyota 7FGU32 6500 lb Pneumatic Tire Forklift S/N: 65549 C/W: 3 Stage Mast, Full Free Lift, 171 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Solid Pneumatic Tires, LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6374	Cat 2PD6000 6000 lb Pneumatic Tire Forklift S/N: AT14E30364 C/W: 2 Stage Mast, 147 in Max Lift Height, 96 in Lowered Mast Height, 53 in Forks, Side Shift, Solid Pneumatic Tires, 2010 US EPA Label, 4 Cylinder 3.3 L Diesel Engine Usage: 18,085 Hr Asset located in: Lake Worth, TX
6368	2019 Toyota 8FD35U 7000 lb Pneumatic Tire Forklift S/N: 8FD35U13204	6375	Mitsubishi FG30 Pneumatic Tire Forklift S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 3 Stage Mast, 187 in Max Lift Height, 78 in Lowered Mast Height, 48 in Forks, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4 Cylinder 2.9 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	6376	2015 Toyota 8FGU30 5820 lb Pneumatic Tire Forklift S/N: 65650 C/W: 2 Stage Mast, 159 in Max Lift Height, 102 in Lowered Mast Height, 40 in Forks, Side Shift,
6369	2005 Toyota 7FGU32 6020 lb Pneumatic Tire Forklift S/N: 68341 C/W: 3 Stage Mast, Full Free Lift, 187 in Max		Solid Pneumatic Tires, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 3,750 Hr Asset located in: Lake Worth, TX
	Lift Height, 88 in Lowered Mast Height, 48 in Forks, Side Shift, 2006 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 8,373 Hr Asset located in: Lake Worth, TX	6377	Forklift S/N: 69901 C/W: 3 Stage Mast, Full Free Lift, 171 in Max
6370	2004 Tailift FD30 4270 lb Pneumatic Tire Forklift S/N: 318920B C/W: 3 Stage Mast, 196 in Max Lift Height, 85 in Lowered Mast Height, 72 in Forks, Solid	Forks, Side Pneumatic Cylinder 2 Usage: No Asset loca 6378 2015 Cat I S/N: AT14 C/W: 3 Sta 59 in Fork Cylinder D Usage: 11 Asset loca 6379 2017 Cat 2 S/N: AT83 C/W: 3 Sta Lift Height Forks, Side GCT 4 Cyli Usage: No Asset loca 6380 2017 Toyo Forklift S/N: 6998 C/W: 3 Sta Lift Height Forks, Side Label, Toyo LPG Engin Usage: 4,4	Lift Height, 83 in Lowered Mast Height, 45 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2006 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Pneumatic Tires, 2005 US EPA Label, Isuzu 4JG2 4 Cylinder 3.1 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		8 2015 Cat DP30N Pneumatic Tire Forklift S/N: AT14G00200 C/W: 3 Stage Mast, 84 in Lowered Mast Heig 59 in Forks, Side Shift, Solid Pneumatic Tires
6371	Doosan G30P-5 5550 lb Pneumatic Tire Forklift S/N: FGA0C-1330-02057 C/W: 3 Stage Mast, Full Free Lift, 186 in Max		Cylinder Diesel Engine Usage: 11,524 Hr Asset located in: Lake Worth, TX
	Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, GM Vortec 4 Cylinder Dual Fuel Engine Usage: 6,566 Hr Asset located in : Lake Worth, TX		2017 Cat 2C6000 5750 lb Cushion Tire Forklift S/N: AT83F42214 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 52 in Forks, Side Shift, Tier 2, 2017 US EPA Label,
6372	2017 Hyundai 30L-7A 5900 lb Pneumatic Tire Forklift S/N: HHKHHF09CH001849		GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 86 in Lowered Mast Height, 45 in Forks, Side Shift, 2017 US EPA Label, CARB Compliant, Hyundai E Controls 4 Cylinder 20.6 kW 2.4 L LPG Engine Usage: 4,100 Hr		2017 Toyota 8FGU30 5750 lb Pneumatic Tire
6373	Asset located in: Lake Worth, TX 2016 Hyundai 301-7A Pneumatic Tire Forklift S/N: HHKHHF009CH0001849K Usage: Not Available Asset located in: Lake Worth, TX		Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 4,420 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6381	2017 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift S/N: 8FDU30-62078 C/W: 3 Stage Mast, 187 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 3 Cylinder 1.7 L Diesel Engine	6386A	Doosan D30G 5467 lb Pneumatic Tire Forklift S/N: K360403 C/W: 3 Stage Mast, Full Free Lift, 185.6 in Max Lift Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: 8,465 Hr Asset located in : Lake Worth, TX	6387	2018 Toyota 8FDU25 4800 lb Pneumatic Tire Forklift	
6382	2014 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift S/N: 60256 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 88 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 2,134 Hr Asset located in: Lake Worth, TX		S/N: 8FDU25-62405 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Toyota Diesel Engine Usage: 2,362 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	
6383	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift		NOT BE ABLE TO ASSIST WITH LOADING THESE	
	S/N: 69985 C/W: 2 Stage Mast, Full Free Lift, 187 in Max		Asset located in: Fort Smith, AR	
	Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4Y ECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 3,920 Hr Asset located in: Lake Worth, TX	6388	2007 Cat P6000LP 5050 lb Pneumatic Tire Forklift S/N: AT13F10861 C/W: 3 Stage Mast, 186 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Block Forks, Solid Pneumatic Tires, Tier 2, 2007 US EPA Label, Nissan K25 L 4 Cylinder	
6384	2015 Toyota 8FGU30 5820 lb Cushion Tire Forklift S/N: 65668		2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: 2 Stage Mast, 159 in Max Lift Height, 100 in Lowered Mast Height, 42 in Forks, 2016 US EPA Label, Toyota 4Y ECS 4 Cylinder 42 hp 2.23 L LPG Engine Usage: 4,257 Hr Asset located in: Lake Worth, TX		6389 2019 Toyota 8FDU25 5000 lb Pneuma Forklift S/N: 62836 C/W: Enclosed Cab, 2 Stage Mast, Ful Lift, 131.5 in Max Lift Height, 84 in Lov	
6384A	Forklift		Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 1,127 Hr	
	S/N: 68413 C/W: 3 Stage Mast, Full Free Lift, 187 in Max	6390	Asset located in: Lake Worth, TX 2016 Cat GP25N2-LE 5000 lb Pneumatic Tire	
	Lift Height, 24 in Lowered Mast Height, 45 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.3 L Dual Fuel Engine Usage: 6,167 Hr Asset located in: Lake Worth, TX	0390	Forklift S/N: AT35A02417 C/W: 3 Stage Mast, 83 in Lowered Mast Height 60 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2016 US EPA Label, 4 Cylinder 2.5 L LPG	
6385	2000 Toyota 7FGU30 Pneumatic Tire Forklift S/N: 61163		Engine Usage: 4,117 Hr Asset located in: Midland, TX	
	C/W: 3 Stage Mast, 47 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6391	2004 Cat P5000 Pneumatic Tire Forklift S/N: AT3500741 C/W: 3 Stage Mast, Full Free Lift, 46 in Forks, Side Shift, Solid Pneumatic Tires, 2004 US EPA	
6386	Cat 2PD6000 5500 lb Pneumatic Tire Forklift S/N: AT14E30407 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 58 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 11,707 Hr Asset located in: Lake Worth, TX		Label, Nissan 4NSXB02.5 4 Cylinder 61.5 hp 2.5 L LPG Engine, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6391A	Hyundai G25SP-3 5000 lb Pneumatic Tire Forklift S/N: D201409 C/W: 3 Stage Mast, 186 in Max Lift Height, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, Daewoo G430-LP 4 Cylinder LPG Engine Usage: 9,190 Hr Asset located in: Lake Worth, TX	6397	2016 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift S/N: 72494 C/W: 2 Stage Mast, Full Free Lift, 131.5 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, CARB Compliant, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
6392	2020 Cat Gp25N 4500 lb Pneumatic Tire Forklift S/N: AT35A09092 C/W: 3 Stage Mast, 188 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2020 US EPA Label, CARB Compliant, GCT 4 Cylinder 20.6 kW 2.5 L LPG Engine Usage: 1,558 Hr Asset located in: Lake Worth, TX	6398	2024 Viper FY30T 4795 lb Pneumatic Tire Forklift (Unused) S/N: 23L3000549 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Hyundai 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX
6393	2018 Doosan G25N7 4600 lb Pneumatic Tire Forklift S/N: FGA14-1290-00939 C/W: 2 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Tier 2, 2018 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 2,390 Hr	6398A	Heli 4600 lb Pneumatic Tire Forklift S/N: 25025117944 C/W: 3 Stage Mast, 75 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder 3.0 L Dual Fuel Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6399	2014 Komatsu FG25HT-16 4650 lb Pneumati
6393A	2011 Doosan G25P-5 Pneumatic Tire Forklift S/N: FGA0B133001275 C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, 2011 US EPA Label, GM 4 Cylinder 46 kW 2.4 L LPG Engine Usage: 3,885 Hr Asset located in: Lake Worth, TX		Tire Forklift S/N: A260155 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2014 US EPA Label, GCT 4 Cylinder 2.5 L Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,436 Hr
6395	2019 Toyota 8FGU25 4900 lb Pneumatic Tire		Asset located in: Humble, TX
	Forklift S/N: 94056 C/W: 3 Stage Mast, 131 in Max Lift Height, 24 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 11,841 Hr Asset located in: Lake Worth, TX	6399A	2016 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 78142 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 87 in Lowered Mast Height, 48 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L Dual Fuel Engine Usage: 4,861 Hr Asset located in: Lake Worth, TX
6396	2015 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift	6400	2015 Toyota 8FGU25 4500 lb Pneumatic Tire
	S/N: 8FGU25-67336 C/W: 2 Stage Mast, 131.5 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 10,669 Hr Asset located in: Lake Worth, TX		Forklift S/N: 67140 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 81 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4YECS 2.2 L Dual Fuel Engine, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6401	2019 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 94048 C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 28,396 Mi Asset located in: Lake Worth, TX	6405	2024 Viper FY25BCS 3900 lb Pneumatic Tire Forklift (Unused) S/N: 222010033 C/W: 3 Stage Mast, 189 in Max Lift Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Mitsubishi 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX
6401A	2015 Doosan D253-7 4200 lb Pneumatic Tire Forklift S/N: FDA00193000440 C/W: 2 Stage Mast, 163 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, 4 Cylinder 45 kW 2.4 L Diesel Engine Usage: 3,385 Hr Asset located in: Lake Worth, TX	-6406	2024 Viper FY25C 3900 lb Pneumatic Tire Forklift (Unused) S/N: 222011086 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Kubota WG2503 4 Cylinder 41 kW 2.5 L LPG Engine Usage: 3 Hr Asset located in: Lake Worth, TX
6401B	2016 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 78039 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 1,247 Hr	6406A	2004 Toyota 7FGU25 4500 lb Pneumatic Tire Forklift S/N: 72616 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 24 in Lowered Mast Height, 41 in Forks, Solid Pneumatic Tires, 2004 US EPA Label, 4 Cylinder 2.2 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX Heli CPYD25 3900 lb Pneumatic Tire Forklift
6402	Asset located in: Lake Worth, TX 1994 Hyster H40XM 4000 lb Pneumatic Tire Forklift S/N: D177G9392R C/W: 3 Stage Mast, 153 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Isuzu 4 Cylinder Diesel Engine	6407A 6407A	S/N: 2302574499 C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
6403	Usage: 2,238 Hr Asset located in: Lake Worth, TX Komatsu FG25 3990 lb Pneumatic Tire Forklift S/N: 144043A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 24 in Lowered Mast Height, 46 in Forks, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine		1997 Mitsubishi FG30 5300 lb Pneumatic Tire Forklift S/N: AF13D30869 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 83 in Lowered Mast Height, 41 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: 2,369 Hr Asset located in: Lake Worth, TX
	Usage: 4,607 Hr Asset located in: Lake Worth, TX		1989 Hyster H30XL 3500 lb Pneumatic Tire
6404	Nissan PJ02A25PV 3975 lb Pneumatic Tire Forklift S/N: PJ029H3529 C/W: 3 Stage Mast, 188 in Max Lift Height, 86 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 13,012 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Forklift S/N: C001B08966K C/W: 3 Stage Mast, Full Free Lift, 174 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: 5,094 Hr Asset located in: Lake Worth, TX
		6408	1989 Clark GPS25MB 3800 lb Pneumatic Tire Forklift S/N: GP138MB03476968K0F C/W: 2 Stage Mast, 196 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1,200 Hr

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6409A	2015 Doosan D25S-7 3650 lb Pneumatic Tire Forklift S/N: FDA0Q-1930-01126 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 2,689 Hr	6415	2017 Cat 2C6000 5750 lb Cushion Tire Forklift S/N: AT83F42218 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6416	2017 Cat 2C6000 5750 lb Cushion Tire Forklift
6410	2002 Komatsu FG15HC-16 2500 lb Pneumatic Tire Forklift S/N: 652910A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan 4 Cylinder Gasoline Engine Usage: 9,201 Hr		S/N: AT83F42219 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 53 in Forks, Side Shift, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6416A	2019 Toyota 8FGCU30 2450 lb Cushion Tire Forklift
6410A	Crown Cushion Tire Forklift S/N: Not Available C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, John Deere 4 Cylinder LPG Engine Usage: 6,624 Hr Asset located in: Lake Worth, TX		S/N: 74094 C/W: 4 Stage Mast, Full Free Lift, 259.5 in Max Lift Height, 79 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Paper Roll Clamp, 2019 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 5,355 Hr Asset located in: Lake Worth, TX
6412	2021 Yale GLC155VX 10000 lb Cushion Tire	6419	2015 Toyota 8FGCU30 5820 lb Cushion Tire
	Forklift S/N: F879V02837V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX		Forklift S/N: 62544 C/W: 2 Stage Mast, 147 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Side Shift, 2017 US EPA Label, Toyota 37 kW 1.79 L Diesel Engine Usage: 5,361 Hr
6413	2021 Yale GLC155VX 10000 lb Cushion Tire		Asset located in: Lake Worth, TX
	Forklift S/N: F879V02836V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6420	2011 Toyota 8FGCU25 7500 lb Cushion Tire Forklift S/N: 31741 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 36 kW 2.23 L
6414	2013 Toyota 7FGCU45 Cushion Tire Forklift S/N: 72832 C/W: 3 Stage Mast, Full Free Lift, 47 in Forks,		LPG Engine Usage: 2,786 Hr Asset located in : Lake Worth, TX
	Auxiliary Hydraulic Plumbing, LPG Engine	6421	Toyota 2600 lb Cushion Tire Forklift
	Usage: 7,006 Hr Notes: . Asset located in: Lake Worth, TX		S/N: 74438 C/W: 3 Stage Mast, 258 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift,
6414A	2018 Toyota 8FGC35U 7250 lb Cushion Tire Forklift		Toyota 4YECS LPG Engine Usage: 5,098 Hr Asset located in: Lake Worth, TX
	S/N: 13300 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 48 in Forks, Side Shift, 2018 US EPA Label, Toyota 4 Cylinder 3.6 L LPG Engine Usage: 2,828 Hr Asset located in: Lake Worth, TX	6422	2021 Mitsubishi FGC25N 5000 lb Cushion Tire Forklift S/N: AF82F50153 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Load Weigh System, 2021 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,245 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6423	2021 Mitsubishi FGC25N4 5000 lb Cushion Tire Forklift S/N: AF82F50026 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 56 in Forks, Load Weigh System, 2022 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,534 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6428	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19408W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6424	2021 Mitsubishi FGC25N 5000 lb Cushion Tire Forklift S/N: AF82F49734 C/W: 2 Stage Mast, Full Free Lift, 80 in Max Lift Height, 58 in Lowered Mast Height, 60 in Forks, Side Shift, Tier 2, 2021 US EPA Label, CARB Compliant, 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 3,757 Hr Asset located in: Lake Worth, TX	- 6429	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19417W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6424B	Komatsu FG25C-11 5000 lb Pneumatic Tire Forklift S/N: 463417A C/W: 2 Stage Mast, 128 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, Nissan 4 Cylinder Gasoline Engine Usage: 5,084 Hr Asset located in: Lake Worth, TX	6430	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19410W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6425	2022 Hyster S50FT 4800 lb Cushion Tire		Asset located in: Humble, TX
	Forklift S/N: H187V19416W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6431	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19409W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6426	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19413W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6432	Asset located in: Humble, TX 2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19415W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6427	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19411W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: Asset located in: Humble, TX	6433	Asset located in: Humble, TX 2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19412W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
6434	2020 Yale GLC050VX 4750 lb Cushion Tire Forklift S/N: C910V14422U C/W: 3 Stage Mast, 189 in Max Lift Height, 58 in Lowered Mast Height, 56 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6440	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19414W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available	
6435	2020 Yale GC050VX 4750 lb Cushion Tire Forklift S/N: C910V14424U C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 58 in Forks, Side Shift,	6441	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2022 Hyster S50FT 4650 lb Cushion Tire Forklift	
	2020 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX		S/N: H187V19400W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, PSI 4 Cylinder 2.4 L LPG	
6436	2006 Yale GLC050VXNVSE083 4700 lb Cushion Tire Forklift S/N: A910V06226D C/W: 3 Stage Mast, 189 in Max Lift Height, 80 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: Not Available	Engine Usage: Not Available	Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	Asset located in: Lake Worth, TX	6442	2022 Hyster S50FT 4650 lb Cushion Tire	
6437	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19418W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		Forklift S/N: H187V19406W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	THE INSPECTION REPORT	6443	Asset located in: Humble, TX 2022 Hyster S50FT 4650 lb Cushion Tire	
6438	Asset located in: Humble, TX 2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19419W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes:	6443		Forklift S/N: H187V19407W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: . Asset located in: Humble, TX
	Asset located in: Humble, TX	6443A	2017 Toyota 8FGCU25 4600 lb Cushion Tire	
6439	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19401W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: Asset located in: Humble, TX		Forklift S/N: 85179 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 87 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 1,226 Hr Asset located in: Lake Worth, TX	

Lot #	Dotoilo	Lot#	Detaile
Lot # 6443B	Details 2017 Toyota 8FGCU25 4500 lb Cushion Tire	Lot # 6446D	Details 2015 Toyota 8FGCU25 4500 lb Cushion Tire
3 - 10 D	Forklift	0-7-700	Forklift
	S/N: 84139 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		S/N: 72623 C/W: 3 Stage Mast, Full Free Lift, 189 in Max
	Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, US EPA		Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota
	Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine		4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 3,747 Hr
	Usage: 7,442 Hr Asset located in : Lake Worth, TX		Asset located in: Lake Worth, TX
6443C	2021 Toyota 8FGCU25 4500 lb Cushion Tire	6447	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift
	Forklift		S/N: 70241
	S/N: C0242 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in
	Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2020 US EPA Label, Toyota		Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine
	4YECS 4 Cylinder 2.2 L LPG Engine Usage: Not Available		Usage: 6,085 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6447A	2014 Toyota 8FGCU25 4500 lb Cushion Tire
6444	2017 Toyota 8FGCU25 4500 lb Cushion Tire Forklift		Forklift
	S/N: 83017		S/N: 62161 C/W: 3 Stage Mast, Full Free Lift, 189 in Max
	C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, 2017 US EPA Label, Toyota		Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Toyota
	4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 5,739 Hr		4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 5,663 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6444A	2016 Toyota 8FGCU25 4500 lb Cushion Tire Forklift	6447B	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift
	S/N: 80050		S/N: 69963
	C/W: 3 Stage Mast, 189 in Max Lift Height, 76 in Lowered Mast Height, 42 in Forks, Side Shift,		C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in
	Fork Positioner, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine		Forks, Side Shift, Toyota 4YECS 4 Cylinder LPG Engine
	Usage: 5,987 Hr Asset located in: Lake Worth, TX		Usage: 6,922 Hr Asset located in: Lake Worth, TX
6446B	2015 Toyota 8FGCU25 4500 lb Cushion Tire	6447C	2011 Toyota 8FGCU25 4500 lb Cushion Tire
	Forklift S/N: 72871		Forklift S/N: 32218
	C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift,		C/W: 3 Stage Mast, Full Free Lift, 189 in Max
	2015 US EPA Label, Toyota 4YECS 4 Cylinder		Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, 2011 US EPA Label, Toyota
	38 kW 2.3 L LPG Engine Usage: 1,944 Hr		4yECS 4 Cylinder 2.2 L LPG Engine Usage: 6,731 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6446C	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift	6448	2007 Toyota 8FGCU25 4500 lb Cushion Tire Forklift
	S/N: 67976 C/W: 3 Stage Mast, 189 in Max Lift Height, 24		S/N: 12090 C/W: 3 Stage Mast, Full Free Lift, 189 in Max
	in Lowered Mast Height, 42 in Forks, Side Shift,		Lift Height, 83 in Lowered Mast Height, 42 in
	2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine		Forks, Side Shift, Fork Positioner, 2007 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L
	Usage: 6,206 Hr Asset located in: Lake Worth, TX		LPG Engine Usage: 4,459 Hr
	- · · · · · · · · · · · · · · · · · · ·	1	Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6448B	2015 Doosan GC25E-5 4300 lb Cushion Tire Forklift S/N: FGA0L179001251 C/W: 3 Stage Mast, Full Free Lift, 76 in Max Lift Height, 189 in Lowered Mast Height, 40 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2015 US EPA Label, Woodward 4 Cylinder 2.4 L LPG Engine Usage: 6,001 Hr Asset located in: Lake Worth, TX	6453B 6454	2013 Cat Cushion Tire Forklift S/N: AU2187 C/W: 3 Stage Mast, Full Free Lift, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2013 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 3,851 Hr Asset located in: Lake Worth, TX 2005 Komatsu FG20ST-14R 4000 lb Cushion
6449	Heli CPYD25C-KU1H 4190 lb Cushion Tire Forklift S/N: 23025N7358 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available		Tire Forklift S/N: 587879A C/W: 2 Stage Mast, 72 in Max Lift Height, 55 in Lowered Mast Height, 48 in Forks, Load Weigh System, 2006 US EPA Label, Nissan 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW- CORP Usage: 19,433 Hr Asset located in: El Paso, TX
6450	Asset located in: Lake Worth, TX Heli CPYD25C-KU1H Cushion Tire Forklift S/N: 230252P8451 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6454A	2002 Daewoo GC15S-2 2550 lb Cushion Tire Forklift S/N: D100192 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, 2002 US EPA Label, DAEWOO G420 4 Cylinder LPG Engine Usage: 9,145 Hr Asset located in: Lake Worth, TX
6451	Heli CPYD25C-KU1H 4080 lb Cushion Tire Forklift S/N: 230252P8453 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6454B	
6452	Heli CPYD25C-KU1H 4080 lb Cushion Tire Forklift S/N: 230252P8452 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX 2014 Toyota 8FGCU20 4000 lb Cushion Tire Forklift		Asset located in: Lake Worth, TX 2017 Toyota 8FGCU25 1700 lb Cushion Tire Forklift S/N: 83746 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 94 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 6,964 Hr Asset located in: Lake Worth, TX
	S/N: 8FGCU25-64619 C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in Lowered Mast Height, 36 in Forks, Side Shift, Toyota 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6457	2012 Toyota 7FGCU35 4900 lb Pneumatic Tire Forklift S/N: 72810 C/W: 4 Stage Mast, Full Free Lift, 230 in Max Lift Height, 24 in Lowered Mast Height, 47 in
6453A	2018 Cat DP25N 3700 lb Pneumatic Tire Forklift S/N: AT18E00601 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		Forks, Solid Pneumatic Tires, PSI 4 Cylinder LPG Engine Usage: 9,584 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6458	2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36479 C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available	6466	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482051 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6467	2024 JQ POWER JQ2T-MAX 4409 lb Electric	
6459	2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36483 C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available		Forklift (Unused) S/N: 24482008 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6468	2024 JQ POWER JQ2T-MAX 2000 kg Electric	
6460	2013 Raymond 960-CSR30TT 3000 lb Order Picker S/N: 9601302364 C/W: 2 Stage Mast, 250 in Max Lift Height, 130 in Lowered Mast Height, 24 V Usage: Not Available		Forklift (Unused) S/N: 24482052 C/W: 2 Stage Mast, 120 in in Forks, Side Shift, 64 V, B. Usage: Not Available	S/N: 24482052 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 64 V, Battery Charger
	Asset located in: Lake Worth, TX	6469	2024 STL Industrial STL2TN Electric Forklift	
6461	2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36471 C/W: 2 Stage Mast, Full Free Lift, 240 in Max Lift Height, 106 in Lowered Mast Height, 42 in Forks, 24 V, Battery Watering System Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: DM202401A06213 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 29 Hr Asset located in: Lake Worth, TX	
		6470	2024 STL Industrial STL1TN Electric Forklift (Unused)	
6462	2024 STL Industrial STL3TN Electric Forklift (Unused) S/N: 01A06131 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift			S/N: 24A0235 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 5 Hr Asset located in: Lake Worth, TX	6471 2025 STL Industrial Electric Forklift S/N: DM202401A06206	2025 STL Industrial Electric Forklift S/N: DM202401A06206	
6463	2017 Raymond 4750C50 4850 lb Electric Forklift S/N: 4751710850		C/W: 2 Stage Mast, 48 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 26 Hr Asset located in : Lake Worth, TX	
	C/W: 3 Stage Mast, Full Free Lift, 188 in Max	C 471 A		
	Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V, Battery Watering System Usage: 5,947 Hr Asset located in : Lake Worth, TX	6471A	2018 Toyota 8FBCU25 4400 lb Electric Forklift S/N: 77312 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 47 in Forks, Side Shift, 36 V, Battery Charger	
6464	2024 JQ POWER JQ2T-MAX 4400 lb Electric		Usage: 1,972 Hr	
	Forklift (Unused) S/N: 24482054	6.47.4	Asset located in: Lake Worth, TX	
	C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available	6474	2011 Toyota 7FBCU18 2900 lb Electric Forklift S/N: Not Available Usage: Not Available	
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX	
6465	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482026 C/W: 2 Stage Mast, 118 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: 3 Km Asset located in: Lake Worth, TX	6475	Cat R80 2800 lb Electric Forklift S/N: 4SM01049 C/W: 3 Stage Mast, Full Free Lift, 191 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: 69 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
6476	Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused) S/N: Not Available C/W: One crate Usage: Not Available Asset located in: Lake Worth, TX	6484	2013 Moffett M50 Lite 5000 lb 3x3 Truck Mounted Forklift S/N: M220415A C/W: Single Stage Mast 144 in Max Lift Height, 48 in Forks, Side Shift, Kubota V1505-T-ET03 4 Cylinder 1.5 L Diesel Engine	
6477	Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused)		Usage: 3,850 Hr Asset located in : Lake Worth, TX	
	S/N: PHT6206139 C/W: 610 lb Capacity, 24 V, One Crate Usage: Not Available	6484A	2001 Moffett M5000 5000 lb 3x3 Truck Mounted Forklift S/N: A05171R C/W: 2 Stage Mast, 98 in Lowered Mast Height,	
6478	Asset located in: Lake Worth, TX 2012 Raymond 960-CSR30TT 3000 lb Electric Reach Truck		45 in Forks, Side Shift, 1999 US EPA Label, Kubota V2203-E 4 Cylinder 36.1 kW 2.2 L Diesel Engine Usage: 4,353 Hr	
	S/N: 9601202198 C/W: 2 Stage Mast, 250 in Max Lift Height, 130		Asset located in: Lake Worth, TX	
	in Lowered Mast Height, 24 V Usage: Not Available Asset located in : Lake Worth, TX	6486	2013 Genie S125 4WD Diesel Telescopic Boom Lift	
6479	2016 Jungheinrich ETR340 4000 lb Electric Reach Truck S/N: 82820438 C/W: 2 Stage Mast, 302 in Max Lift Height, 130 in Lowered Mast Height, 42 in Forks, 36 V, Battery Charger, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 5,032 Hr Notes:		S/N: S12513D505 C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, Deutz td2011 4 Cylinder 74 hp 3.6 L Diesel Engine, 445 /50D710 Tires Usage: 3,738 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
6481	2012 Moffett P6000 6000 lb 3x3 Truck Mounted Forklift S/N: L270049 C/W: 3 Stage Mast, 124 in Max Lift Height, 78 in Lowered Mast Height, 74 in Forks, Fork Rotation, Tier 4, 2012 US EPA Label, Kubota V2203 4 Cylinder 2.2 L Diesel Engine Usage: 1,732 Hr Asset located in: Humble, TX	6487	Boom Lift S/N: S125123373 C/W: 125 ft Max Platform Height, 500 lb Weight Capacity, Jib, Extendable Axles, I to Platform, 2012 US EPA Label, Deutz TD2011L04 4 Cylinder 3.6 L Diesel Engir Usage: 4,191 Hr Notes: AERIAL UNITS REQUIRE PROPER	S/N: S125123373 C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, Deutz TD2011L04 4 Cylinder 3.6 L Diesel Engine
6482	2013 Navigator RT5500 5500 lb 3x3 Truck Mounted Forklift		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	S/N: 413847 C/W: 2 Stage Mast, 144 in Max Lift Height, 93 in Lowered Mast Height, 48 in Forks, Side Shift, Kubota 4 Cylinder 2.0 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	6488	2002 Genie S-125 Telescopic Boom Lift S/N: S125525 C/W: 125 m Max Lift Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine, 445/65D22.5 Tires Usage: 5,200 Hr	
6483	2013 Princeton PB50X 5000 lb 3x3 Truck Mounted Forklift S/N: M480268C C/W: Single Stage Mast 24 in Lowered Mast Height, 47 in Forks, Tier 4, 2012 US EPA Label, Kubota v2203 4 Cylinder 35 kW 2.2 L Diesel Engine Usage: 2,060 Hr Asset located in: Lake Worth, TX		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX	

Lot #	Details	Lot #	Details
6489	2018 Genie S-85 XC 4WD Diesel Telescopic Boom Lift S/N: S85XCH-262 C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Tires Usage: 3,157 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6495	2015 Snorkel TB85J 4WD Diesel Telescopic Boom Lift S/N: TB85J-04-000049 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Kubota V2403 4 Cylinder 44 kW 2.4 L Diesel Engine, 15-625 Tires Usage: 4,173 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6490	2018 Genie S85XC 4WD Diesel Telescopic	6497	2014 Genie S-80X 4WD Diesel Telescopic Boom Lift
0430	Boom Lift S/N: S85XCH260 C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2017 US EPA Label, Deutz TD 2.9 LP 4 Cylinder 2.95 L Diesel Engine, 18-625NHS Tires Usage: 4,567 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: S80X1412022 C/W: 80 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,562 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6498	2012 JLG 800S 4WD Diesel Telescopic Boom
6491	2011 Genie S85 4WD Diesel Telescopic Boom Lift S/N: S85118854 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2011 US EPA Label, Deutz 4 Cylinder 74 hp 3.6 L Diesel Engine, 18-625 Tires Usage: 2,485 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX		Lift S/N: 0300158033 C/W: 80 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2011 US EPA Label, Deutz D2011L04 4 Cylinder 3.6 L Diesel Engine Usage: 2,352 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6493	2018 Haulotte HT85RT 4WD Diesel Telescopic	6499	2018 Haulotte HT67RTJ 4WD Diesel
	Boom Lift S/N: 2030133 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 4 Cylinder Diesel Engine Usage: 1,938 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Telescopic Boom Lift S/N: TD500215 C/W: 67 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2017 US EPA Label, Kubota V2403-CR-TI-EF02 4 Cylinder 47 kW 2.4 L Diesel Engine, 385/65- 22.5 Tires Usage: 3,522 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6494	2017 Haulotte HT85RTJ PRO 4WD Diesel	6500	2017 JLG 660SJ 4WD Diesel Telescopic Boom
	Telescopic Boom Lift S/N: 2021508 C/W: 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2016 US EPA Label, Kubota V2607 4 Cylinder 2.6 L Diesel Engine Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Lift S/N: 0300236291 C/W: 65 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 748 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6502	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift	6506	2015 Genie S60X 4WD Diesel Telescopic Boom Lift
	S/N: 0300233965 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		S/N: S60X15A-29654 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D 2.9 L4 49 hp 2.92 L Diesel Engine, 355/55D625 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,781 Hr
	Usage: 5,192 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6503	2016 Genie S-65 4WD Dual Fuel Telescopic Boom Lift S/N: S6016H-35454 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, CARB Compliant, 4 Cylinder 64.3 kW 2.5 L Dual Fuel Engine, 355/55D625 NHS Tires Usage: 3,590 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	-6507	Lift S/N: 300236812 C/W: 59 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,026 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	6540	<u></u>
6504	2012 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S6012-23502 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2011 US EPA Label, Deutz D2011L03I 4 Cylinder 49 hp 2.3 L Diesel Engine, 355/55D625 Tires Usage: 4,624 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6510	2006 Genie S60 4WD Diesel Telescopic Boom Lift S/N: S600614228 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Diesel Engine, 355/55D625 Tires Usage: 973 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	6510A	• • • • • • • • • • • • • • • • • • •
6505	2017 Genie S60X 4WD Diesel Telescopic Boom Lift S/N: S60XH-37752 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, CARB Compliant, Deutz D2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355 /55D625 NHS Tires Usage: 2,105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX		Lift S/N: 0300236779 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, Deutz D 2.9 L4 36.4 kW 2.9 L Diesel Engine, 1417.5 NHS Tires Usage: 3,690 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6511	2019 Skyjack SJ45T 4WD Diesel Telescopic Boom Lift S/N: 98003735 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Deutz Diesel Engine Usage: 2,136 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	6515	2017 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300236550 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Fort Smith, AR	6516	2016 JLG 400S 4WD Diesel Telescopic Boom
6511A	2019 Genie S45 4WD Diesel Telescopic Boom Lift S/N: S45H-26957 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Tires Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Lift S/N: 0300211074 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,626 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6511B	Asset located in: Lake Worth, TX 2018 Genie S-45 4WD Diesel Telescopic Boom	6517	Asset located in: Lake Worth, TX 2016 JLG 400S 4WD Diesel Telescopic Boom
	Lift S/N: S45H-26987 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Tires Usage: 2,186 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Lift S/N: 0300210880 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 4,719 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6513	2007 Snorkel TB42DZ 4WD Diesel Telescopic	6518	2015 JLG 400S 4WD Diesel Telescopic Boom
6514	Boom Lift S/N: MR07088RBLT C/W: 42 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2008 US EPA Label, Deutz F3L2011 3 Cylinder 48 hp 2.33 L Diesel Engine, 12.16.5N Tires Usage: 3,176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2015 Genie S40 4WD Diesel Telescopic Boom	_	Lift S/N: 0300209072 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,731 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Lift	6519	2015 JLG 400S 4WD Telescopic Boom Lift
	S/N: S4015-20737 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,771 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0019	S/N: 0300204969 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, Deutz 4 Cylinder Diesel Engine, 12-16.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,775 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
6521	2015 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300208881 C/W: 40 ft Max Platform Height, 600 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 4,536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6525	2015 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300198551 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Tires Usage: 3,975 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6522	2014 JLG 400S 4WD Diesel Telescopic Boom		Asset located in: Humble, TX
	Lift S/N: 0300191770 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,228 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6526	2018 JLG 600AJ 4WD Diesel Articulating Boom Lift S/N: 0300239502 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz 2.9l4 4 Cylinder 67 hp 2.9 L Diesel Engine Usage: 1,081 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6523	2014 JLG 400S 4WD Diesel Telescopic Boom	6527	2011 JLG 600AJ 4WD Diesel Articulating
	Lift S/N: 0300192112 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,661 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Boom Lift S/N: 0300143499 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2010 US EPA Label, Deutz D2011L4 4 Cylinder 3.1 L Diesel Engine, 355/55D625 Tires Usage: 4,083 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6524	2016 Haulotte HA130RTJPRO 4WD Diesel Articulating Boom Lift	6528	2015 Snorkel AB60J Articulating Boom Lift S/N: AB60J-04-000082 Usage: Not Available
	S/N: AD127595 C/W: 129 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Perkins Engine Usage: 3,370 Hr		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6529	2014 Genie Z-60/34 4WD Diesel Articulating Boom Lift S/N: Z601414246 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Deutz D2011L03I 4 Cylinder 49 hp Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,716 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6531	2015 Snorkel A46JRT 4WD Diesel Articulating Boom Lift S/N: A46JRT-04-000348 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505 4 Cylinder 18.5 kW 1.5 L Diesel Engine, 355/55D62.5 Tires Usage: 1,226 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6537	2014 Genie Z45/25 2WD Electric Articulating Boom Lift S/N: Z452514A52188 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam- Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6532	Skyjack SJ46AJ 4WD Diesel Articulating Boom Lift S/N: 95000588 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine Usage: 2,493 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6538	2012 Genie Z40/23NRJ 2WD Electric Articulating Boom Lift S/N: Z40N12-1774 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 25.6 X7 Non-Marking Tires Usage: 1,120 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6534	2012 JLG 450AJ 4WD Articulating Boom Lift	6539	2012 Genie Z40/23NRJ 2WD Electric
	S/N: 0300161279 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D2011 3 Cylinder 49 hp 2.3 L Diesel Engine, 33X15.50 Tires Usage: 3,162 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Articulating Boom Lift S/N: Z40N12-1683 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22X7X17 Non-Marking Tires Usage: 1,393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6535	2015 Genie Z-45/25J 2WD Electric Articulating	6540	2012 Genie Z40/23NRJ Articulating Boom Lift
	Boom Lift S/N: Z452515A54948 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam- Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,406 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6541	S/N: Z40N12-1786 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2012 Genie Z40/23NRJ Articulating Boom Lift S/N: Z40N12-1775 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
6536	2015 Genie Z45/25J 4WD Diesel Articulating	7	SAFETY HARNESS, LANYARD, AND PPE TO
2300	Boom Lift		FUNCTION TEST AND LOAD
	S/N: Z452515A-53530	6540	Asset located in: Lake Worth, TX
	C/W: 24 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz U2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 315/55D20 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,249 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	6542	2012 Genie Z40/23NRJ 2WD Electric Articulating Boom Lift S/N: Z40N12-1797 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Solid Tires Usage: 1,230 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6543	2017 Genie Z-33/18 2WD Electric Articulating Boom Lift S/N: Z3318M1589 C/W: 32 ft Max Platform Height, 440 lb Max Weight Capacity, Power to Platform, 22X9 Solid Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 619 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6550	2017 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40002479 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,620 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6544	2015 JLG E300 AJP 2WD Electric Articulating		Asset located in: Lake Worth, TX
	Boom Lift S/N: 0300203331 C/W: 30 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 823 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6551 2017 Skyjack SJ8841 RT 4x4 Lift S/N: 40002473 C/W: 41 ft Max Platform Hei Weight Capacity, Platform Ex Platform, Stabilizers, Foam F Control Box, 2017 US EPA La WG972-GL-ET 3 Cylinder 962 Engine, EQUIPMENT-FROM-S EQUIPMENT Usage: 3,292 Hr Notes: AERIAL UNITS REQUI SAFETY HARNESS, LANYAR FUNCTION TEST AND LOAD	S/N: 40002473 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-
6545	2018 JLG T500J Electric Towable Lift S/N: 0030009466 C/W: 50 ft Max Platform Height, 500 lb Max		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	Weight Capacity, Jib, Power to Platform Usage: 37 Hr		Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6552	2015 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40001765 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2015 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,788 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6546	2018 JLG T500J Electric Towable Lift S/N: 5DYACJ1J3JF009464 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 50 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		
6547	2018 JLG T500J Electric Towable Lift	6552	Asset located in: Lake Worth, TX
	S/N: 5DYACJ1J5JF009465 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 55 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6553	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40001309 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, Kubota WG972 3 Cylinder Dual Fuel Engine Usage: 2,649 Hr Notes: AERIAL UNITS REQUIRE PROPER
6548	2014 JLG T500J Towable Lift S/N: 0030008920 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 182 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
6553A	2013 JLG M4069 4x4 Diesel Scissor Lift S/N: 0200217745 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2012 US EPA Label, Kubota 1 Cylinder 0.2 L Diesel Engine Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX	6558	2017 Skyjack SJ6832RT 4x4 Dual Fuel Scissor Lift S/N: 37010203 C/W: 32 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2016 US EPA Label, Kubota WG752-GL-ET 3 Cylinder 740 cc Dual Fuel Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,144 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6554	2007 JLG 3394RT 4x4 Dual Fuel Scissor Lift		
	S/N: 0200164159 C/W: 33 ft Max Platform Height, 2250 lb Max	4540	Asset located in: Lake Worth, TX
	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 4 Cylinder Dual Fuel Engine Usage: 998 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6560	2015 Genie GS-2669RT 4x4 LPG Scissor Lift S/N: GS6915-7055 C/W: 26 m Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2014 US EPA Label, Kubota WG972-GL-ET 3 Cylinder LPG Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,044 Hr
6555	2017 Genie GS3390RT 4x4 Dual Fuel Scissor Lift S/N: GS90F-54078 C/W: 2500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, 2017 US EPA Label, 4 Cylinder 64.3 kW 2.5 L LPG Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,011 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
			Asset located in: Oklahoma City, OK
		6561	2017 Skyjack SJ6826 RT Scissor Lift S/N: 37010550 Usage: 1,397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6556	2015 Genie GS-3369RT Scissor Lift S/N: GS6915-7051 Usage: 1,360 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2015 Genie GS-3369RT Scissor Lift S/N: GS6915-7099 Usage: 1,738 Hr	-6562 -	2017 Skyjack SJ6826 RT Dual Fuel Scissor Lift S/N: 37010717 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Foam Filled Tires, Upper Control Box, Kubota WG752-GL - ET 3 Cylinder 740.5 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,991 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER	6562A	2000 Skyjack SJ8841RT 4x4 Dual Fuel Scissor
	SAFETY HARNESS, LANYÅRD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	JUDUZA	Lift S/N: 42378 C/W: 41 ft Max Platform Height, 1700 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Dual Fuel Engine Usage: 1,676 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6563	2014 JLG M4069LE Scissor Lift S/N: 0200238747 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6569	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1734 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 502 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6564	2013 JLG M4069LE 4x4 Diesel Scissor Lift S/N: 0200217747 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Power Inverter, Solid Non-Marking Tires, Upper Control Box, Tier 4, 2012 US EPA Label, Kubota 0C60-ET01 1 Cylinder 0.27 L Diesel Engine Usage: 276 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX	6570	Asset located in: Oklahoma City, OK 2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1802 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 504 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6565	2013 JLG 4069LE Electric Scissor Lift S/N: 0200219769 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 694 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2017 Genie GS-4047 Electric Scissor Lift	6571	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P1430 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 509 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6568	S/N: GS47P-1728 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK 2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P1715	6572	Asset located in: Lake Worth, TX 2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1824 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 594 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 479 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6573	Asset located in: Lake Worth, TX 2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P1822 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 628 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot#	Details	Lot #	Details
6575	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1678 C/W: 39 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 615 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6580	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-3104 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 500 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6576	2017 Genie GS-4047 Electric Scissor Lift	6582	2016 Genie GS-4047 Electric Scissor Lift
	S/N: GS47D6070 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS4716D1580 C/W: 40 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 590 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6577	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P2225 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6583	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-2977 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 627 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6584	2016 Genie GS-4047 Electric Scissor Lift
6578	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-1545 C/W: 20 ft Max Platform Height, 550 lb Max Weight Capacity, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 498 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset Joseph Dirich also Worth. TX		S/N: GS4716D-1511 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 633 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	650-	Asset located in: Lake Worth, TX
6579	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1620 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 499 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6585	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1286 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6586	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1278 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 534 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6591	Skyjack SJIII-4740 Electric Scissor Lift S/N: Not Available C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 349 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6587	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1054	6592	2017 MEC 4046SE Electric Scissor Lift
	C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 788 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6392	S/N: 16700245 C/W: 38 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
<u></u>	Asset located in: Oklahoma City, OK	\dashv	SAFETY HARNESS, LANYARD, AND PPE TO
6588	2018 Skyjack SJIII-4740 Electric Scissor Lift S/N: 70202991		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to	6593	2017 MEC 4046SE Electric Scissor Lift
	Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	S/N: 16700250 C/W: 38 ft 7 in Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 6594 2015 JLG 3248RS Electric Scissor Lift S/N: 0200237506 C/W: 32 ft Max Platform Height, 705 lb Ma Weight Capacity, Platform Extension, Power Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTAT	C/W: 38 ft 7 in Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT
6589	89 2018 Skyjack SJIII-4740 Electric Scissor Lift S/N: 70202542 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity Platform Extension Power to		SAFETY HARNESS, LANYARD, AND PPE TO
			Asset located in: Lake Worth, TX
			S/N: 0200237506 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-
6590	2017 Skyjack SJIII4740 Electric Scissor Lift S/N: 70201795		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to		Asset located in: Lake Worth, TX
	Platform, Onboard Generator, Stabilizers, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6595	2015 JLG 3248RS Electric Scissor Lift S/N: 0200243786 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 538 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

		•	
Lot #	Details	Lot #	Details
6597	2017 Snorkel S4732E Electric Scissor Lift S/N: S4732E-04-900112 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT FROM UNITED RENTALS Usage: 180 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6603	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P143966 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 337 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6598	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P-143973 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6604	2017 Genie GS3246 Electric Scissor Lift S/N: GS46P143806 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 297 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6599	2017 Genie GS-3246 Electric Scissor Lift S/N: 143969 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 114 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6604A	2017 Genie GS3246 Electric Scissor Lift S/N: GS46P143724 C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6600	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P-143947 C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 290 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6606	2015 Genie GS-3246 Electric Scissor Lift S/N: GS4615A137584 C/W: 33 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 484 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6601	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P143978 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 335 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6607	Asset located in: Lake Worth, TX 2017 JLG 3246ES Electric Scissor Lift S/N: 0200263928 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 59 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6608	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266401 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 81 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6615	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266205 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6610	2017 JLG 3246ES Electric Scissor Lift S/N: 0200263931 C/W: 31 ft Max Platform Height, 750 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 206 Hr Notes: AERIAL UNITS REQUIRE PROPER	6616	2015 JLG 3246ES Electric Scissor Lift S/N: M200001109 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 413 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6612	2017 JLG 3246ES Electric Scissor Lift S/N: M200013247 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 401 Hr Notes: 401 Hr	6617	2017 JLG 3246ES Electric Scissor Lift S/N: M200013175 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 425 Hr Notes: 425 Hr
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6613	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266207 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 402 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6618	2017 JLG 3246ES Electric Scissor Lift S/N: M200013211 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6614	2017 JLG 3246ES Electric Scissor Lift	6619	2017 JLG 3246ES Electric Scissor Lift
	S/N: M200013176 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 0200266209 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6620	2017 JLG 3246ES Electric Scissor Lift S/N: M200013245 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6625	2015 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70022067 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6621	Asset located in: Lake Worth, TX 2016 JLG 3246ES Electric Scissor Lift S/N: M200000621 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 492 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6626	2015 Skyjack SJIII-4632 Electric Scissor Lift S/N: 70022705 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 368 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6622	Asset located in: Lake Worth, TX 2017 Skyjack SJIII-4632 Electric Scissor Lift	6627	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70019200 C/W: 32 ft Max Platform Height, 700 lb Max
	S/N: 80180032 C/W: 32 ft Max Platform Height, 750 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available		Weight Capacity, Platform Extension Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	S/N: 70019482 C/W: 32 ft Max Platform Height, 700 lb Ma Weight Capacity, Platform Extension, Pow Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE T FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 6629 2014 Skyjack SJIII 4632 Electric Scissor L S/N: 70019116 C/W: 32 ft Max Platform Height, 700 lb Ma Weight Capacity, Platform Extension, Pow	C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to
6623	·		Control Box Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to
6624	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70017904 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 289 Hr Notes: AERIAL UNITS REQUIRE PROPER	6630	Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2014 Skyjack SJIII4632 Electric Scissor Lift
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 70017856 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 339 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6631	Skyjack SJIII 4632 Electric Scissor Lift S/N: Not Available C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 325 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6636	2017 Genie GS-3232 Electric Scissor Lift S/N: GS32P-148830 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 509 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6637	2017 Genie GS-3232 Electric Scissor Lift
6632	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70018708 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension Usage: 358 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS32P148756 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6633	2014 Skyjack SJIII 4632 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 70018805 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 358 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6638	2017 Genie GS3232 Electric Scissor Lift S/N: GS32P-149344 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6640	2015 Genie GS3232 Electric Scissor Lift
6634	2018 Genie GS3232 Electric Scissor Lift S/N: GS32P-157610 C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	00-10	S/N: GS3215A141191 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 465 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6635	2017 Genie GS3232 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS32P-154160 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	6641	2015 Genie GS-3232 Electric Scissor Lift S/N: 141232 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 398 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6642	2014 Genie GS-3232 Electric Scissor Lift S/N: 135791 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6647	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70022572 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 200 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6643	2018 Snorkel S4726E Electric Scissor Lift S/N: S4726E-04-180500837	6648	2015 Skyjack SJIII4626 Electric Scissor Lift S/N: 70022293 C/W: 26 ft Max Platform Height, 1000 lb Max
	C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 109 Hr		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 240 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6644	2017 JLG 2646ES Electric Scissor Lift	6649	2015 Skyjack SJIII4626 Electric Scissor Lift
	S/N: M200007467 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 291 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6650	S/N: 70022355 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 260 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6645	2015 JLG 2646ES Electric Scissor Lift S/N: M200001100 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 477 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	-6650	2015 Skyjack SJIII4626 Electric Scissor Lift S/N: 70021519 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 282 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6651	2014 Skyjack SJIII4626 Electric Scissor Lift
6646	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70026601 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: 70021343 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 410 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6652	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263898 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 328 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6657	2015 JLG 2646ES Electric Scissor Lift S/N: M200000271 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6653	2017 JLG 2646ES Electric Scissor Lift	6658	2015 Genie GS2646 Electric Scissor Lift
	S/N: 0200263463 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 375 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: 137357 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 246 Hr Notes : AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6654	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263458 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr Notes: AERIAL UNITS REQUIRE PROPER	6659	2015 Genie GS2646 Electric Scissor Lift S/N: GS4615A136705 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 362 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6655	2016 JLG 2646ES Electric Scissor Lift	6660	2015 Genie GS-2646 Electric Scissor Lift
	S/N: M200001128 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 227 Hr		S/N: GS4615A137346 C/W: 25 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
	Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6656	2015 JLG 2646ES Electric Scissor Lift S/N: M200001101 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 373 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6661	2015 Genie GS-2646 Electric Scissor Lift S/N: GS4615A137130 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6662	2016 Genie GS-2632 Electric Scissor Lift S/N: GS3216P-145511 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 489 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6668	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-138165 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 343 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6663	2016 Genie GS-2632 Electric Scissor Lift	6669	2015 Genie GS-2632 Electric Scissor Lift
	S/N: GS3216P145971 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 540 Hr		S/N: GS3215A-140139 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 404 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6664	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140574 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 28 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6670	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A138159 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 424 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Oklahoma City, OK	6672	2015 Genie GS-2632 Scissor Lift
6665	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140508 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 245 Hr Notes: AERIAL UNITS REQUIRE PROPER	0072	S/N: GS3215A-139149 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 497 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6673	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A138162 C/W: 26 ft Max Platform Height, 700 lb Max
6667	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A140092 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6674	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A137939 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6679	2014 Genie GS-2632 Electric Scissor Lift S/N: GS3214A136069 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 396 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6675	2015 Genie GS-2632 Electric Scissor Lift	6680	2014 Genie GS-2632 Electric Scissor Lift
	S/N: GS3215A140581 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 380 Hr Notes : AERIAL UNITS REQUIRE PROPER		S/N: GS3214A-118609 C/W: 26 ft Max Platform Height, 26 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	+	Asset located in: Lake Worth, TX
6676	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A-139158 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6681	2013 Genie GS-2632 Electric Scissor Lift S/N: GS3213A116224 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	Asset located in: Lake Worth, TX		FUNCTION TEST AND LOAD
6677	2015 Genie GS-2632 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS3215A-140565 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6682	2016 JLG 2632ES Electric Scissor Lift S/N: 200252535 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 339 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6677A	2015 Genie GS-2632 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS3215A139156 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 525 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6683	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252837 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6684	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252763 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6688A	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252564 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6685	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252494 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6689	2015 JLG 2632ES Electric Scissor Lift S/N: M200000541 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6686	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252789 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	-6690	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244222 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6687	Asset located in: Lake Worth, TX 2016 JLG 2632ES Electric Scissor Lift S/N: M200002023 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 435 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6691	2015 JLG 2632ES Electric Scissor Lift S/N: 0200246996 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 444 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6688	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252492 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 482 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	-6692	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244228 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 470 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6693	2015 JLG 2632ES Electric Scissor Lift S/N: 0200243900 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6698	2015 Skyjack SJ III 3226 Electric Scissor Lift S/N: 27023528 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6699	2014 Skyjack SJIII 3226 Electric Scissor Lift S/N: 27020188	
6694	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244546 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 471 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 299 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	FUNCTION TEST AND LOAD	6700	2014 Skyjack SJIII-3226 Electric Scissor Lift	
	Asset located in: Lake Worth, TX	_	S/N: 27017585 C/W: 26 ft Max Platform Height, 500 lb Max	
6695	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244248 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 421 Hr Notes: AERIAL UNITS REQUIRE PROPER		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 251 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6701	2016 JLG 2630ES Electric Scissor Lift	
			S/N: 0200252795	
6696	2015 JLG 2632ES Electric Scissor Lift S/N: 0200247096 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		Weight Capacity, Platform Exten Platform, Solid Non-Marking Tire Control Box, EQUIPMENT-FROM EQUIPMENT Usage: 388 Hr Notes : AERIAL UNITS REQUIRE I SAFETY HARNESS, LANYARD, A FUNCTION TEST AND LOAD;	Usage: 388 Hr Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD	6702	2011 JLG 2630ES Electric Scissor Lift	
	Asset located in: Lake Worth, TX	_	S/N: 0200200580 C/W: 25 ft 4 in Max Platform Height, 500 lb	
6697	2015 JLG 2632ES Electric Scissor Lift S/N: 0200251446 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 370 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 369 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
6703	2017 Snorkel S3220E Electric Scissor Lift S/N: S3220E-04-900021 C/W: 20 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6709	2018 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22135992 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 284 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
6704	2013 Genie GS2032 Electric Scissor Lift S/N: GS3213A113424 C/W: 20 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 144 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6711	Skyjack SJIII-3219 Electric Scissor Lift S/N: 1000025 C/W: 19 m Max Platform Height, 600 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 161 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
6705	Hangcha 81XE-II Electric Scissor Lift S/N: Not Available C/W: 400 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22063947 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 218 Hr Notes: AERIAL UNITS REQUIRE PROPER	
6706	2016 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22104289 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2016 Skyjack SJIII-3219 Electric Scissor Lift		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 6712 2014 Skyjack SJIII-3219 Electric S S/N: 22060591 C/W: 19 ft Max Platform Height, S Weight Capacity, Platform Extens Platform, Solid Non-Marking Tires Control Box, EQUIPMENT-FROM-S EQUIPMENT Usage: 258 Hr Notes: AERIAL UNITS REQUIRE P SAFETY HARNESS, LANYARD, AN FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 6713 2019 JLG 1932R Electric Scissor S/N: M200029543 C/W: 19 ft Max Platform Height, S Weight Capacity, Platform Extens Platform, Solid Non-Marking Tires	Asset located in: Lake Worth, TX 2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22060591 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 258 Hr
0/0/	S/N: 22104294 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box Usage: 279 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX			SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2019 JLG 1932R Electric Scissor Lift
6708	2017 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22104310 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 391 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Usage: 83 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6715	2015 JLG 1932RS Electric Scissor Lift S/N: 0200244480 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 383 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6721	S/N: 0200244472 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 505 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	4	S/N: 0200243354 C/W: 19 ft Max Platform Height, 500 lb Max
6716	2015 JLG 1932RS Electric Scissor Lift S/N: 0200243353 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6723	2014 JLG 1932RS Electric Scissor Lift
	Asset located in: Oklahoma City, OK		S/N: 200235081
6717	2015 JLG 1932RS Electric Scissor Lift S/N: 0200251219 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 158 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6724	2014 JLG 1932RS Electric Scissor Lift
	Asset located in: Lake Worth, TX		S/N: 0200236585
6718	2015 JLG 1932RS Electric Scissor Lift S/N: 0200247820 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 409 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		C/W: 19 ft Max Platform Height, Weight Capacity, Platform Extens Platform, Solid Non-Marking Tire Control Box, EQUIPMENT-FROM- EQUIPMENT Usage: 373 Hr Notes: AERIAL UNITS REQUIRE F SAFETY HARNESS, LANYARD, AI FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6725	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234422
6719	2015 JLG 1932RS Electric Scissor Lift S/N: 0200244479 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6725A	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236594 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 623 Hr Asset located in: Lake Worth, TX	6734	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234070 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr Notes: AERIAL UNITS REQUIRE PROPER
6726	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234817		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 423 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		2014 JLG 1932RS Electric Scissor Lift S/N: 200234879 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 594 Hr
6731	Asset located in: Lake Worth, TX JLG 1932RS Electric Scissor Lift S/N: 0200234825		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 520 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6736	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236058 C/W: 19 m Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
6732	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235386		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6737	2016 Snorkel S3219E Electric Scissor Lift S/N: S3219E-04-001508 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 1,362 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6733	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235121		Asset located in: Lake Worth, TX
	C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6738	2018 Snorkel S3129E Electric Scissor Lift S/N: S3219E-04-181006644 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6739	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P168879 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	6744	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P-167041 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 438 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6740	2017 Genie GS-1930 Electric Scissor Lift	6745	2016 Genie GS-1930 Electric Scissor Lift
	S/N: GS30P166134 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 65 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	07.10	S/N: GS3016A-150796 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 64 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6741	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166091 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6746	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156688 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 312 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6742	2017 Genie GS-1930 Electric Scissor Lift	6747	2016 Genie GS-1930 Electric Scissor Lift
0742	S/N: GS30P168863 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	0,4,	S/N: GS3016A-151099 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 381 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6743	2017 Genie GS-1930 Electric Scissor Lift	6749	2016 Genie GS-1930 Electric Scissor Lift
	S/N: GS30P166082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3016P159321 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 399 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6750	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P153060 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6757	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-150674 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 471 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6751	2016 Genie GS-1930 Electric Scissor Lift	6757A	2016 Genie GS-1930 Electric Scissor Lift
0,01	S/N: GS3016A-151109 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr		S/N: GS3016P159322 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 544 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	 	Asset located in: Lake Worth, TX
6752	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A150812 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER	6759	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159736 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6753	2016 Genie GS-1930 Electric Scissor Lift	6760	2016 Genie GS-1930 Electric Scissor Lift
0,00	S/N: GS3016P156662 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr	0700	S/N: GS3016P-159631 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 552 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lake Worth, TX
6755	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156684 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6761	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156681 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 603 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

	Details	Lot #	Details
Lot #		+	
6762	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159764 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6767	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149270 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6763	2016 Genie GS-1930 Electric Scissor Lift	6768	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3016P159709 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3015A-146342 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 329 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6764	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P-159326 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 622 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6772	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-148159 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 360 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX		2015 Genie GS-1930 Electric Scissor Lift
6765	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A150748 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 450 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset Joseph In: Lake Worth, TY		S/N: GS3015A146154 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2015 Genie GS-1930 Electric Scissor Lift
	Asset located in: Lake Worth, TX	-	S/N: GS3015A149284
6766	2016 Genie GS-1930 Scissor Lift S/N: GS3016P- 154550 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6774	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3016159299 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6779	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145103 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6775	2015 Genie GS-1930 Electric Scissor Lift	6780	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A-149399 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 400 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	0,00	S/N: GS3015A148246 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER
	FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6776	Asset located in: Lake Worth, TX 2015 Genie GS-1930 Electric Scissor Lift		Asset located in: Lake Worth, TX
0//0	S/N: GS3015A146310	6781	2015 Genie GS-1930 Electric Scissor Lift
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: GS3015A146258 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 424 Hr
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
6777	2015 Genie GS-1930 Electric Scissor Lift	6782	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A-146331 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6782	S/N: GS3015A145084 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6778	2015 Genie GS-1930 Electric Scissor Lift	_	Asset located in: Lake Worth, TX
0776	S/N: GS3015A-142980 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 410 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6783	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146435 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6784	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149417 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6789	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-148249 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 448 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX	6790	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146319
6785	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149321 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6791	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 449 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2015 Genie GS-1930 Electric Scissor Lift
6786	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145121 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 439 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: GS3015A149351 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6792	2015 Genie GS-1930 Electric Scissor Lift
6787	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145117 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 442 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		C/W: 19 ft Max Platform Weight Capacity, Platforn Platform, Solid Non-Mark Control Box, EQUIPMENT EQUIPMENT Usage: Not Available Notes: AERIAL UNITS RE SAFETY HARNESS, LANY FUNCTION TEST AND LO Asset located in: Lake We
	Asset located in: Lake Worth, TX	6793	2015 Genie GS-1930 Electric Scissor Lift
6788	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146104 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 443 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: GS3015A-145141 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6794	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015149276 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 445 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6798	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149413 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 491 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6795	2015 Genie GS-1930 Electric Scissor Lift	6799	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A-149414 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr		S/N: GS3015A-149349 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 493 Hr
	Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6795A	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148197 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr	6800	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148168 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	ļ	Asset located in: Lake Worth, TX
6796	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149305 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 466 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6801	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146325 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6797	2015 Genie GS-1930 Electric Scissor Lift	6802	2015 Genie GS-1930 Electric Scissor Lift
5, 5,	S/N: GS3015A149397 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 468 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	3302	S/N: GS3015A149391 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 504 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6803	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146335 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 408 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6809	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A138418 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 412 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
6804	2015 Genie GS-1930 Electric Scissor Lift	6810	2014 Genie GS-1930 Electric Scissor Lift	
	S/N: GS3015A149262 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 543 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6810	S/N: GS3014A-138412 C/W: 19 ft Max Platform Height, Platform Extension, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6812	2014 Genie GS-1930 Electric Scissor Lift	
6805	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146282 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Weight Capacity, Platform Extens Platform, Solid Non-Marking Tires Control Box, EQUIPMENT-FROM-S EQUIPMENT Usage: 429 Hr Notes: AERIAL UNITS REQUIRE P	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 429 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		2014 Genie GS-1930 Electric Scissor Lift	
6806	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A142971 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		C/W: 19 ft Max Platform Weight Capacity, Platforn Platform, Solid Non-Marl Control Box, EQUIPMENT EQUIPMENT Usage: 453 Hr Notes: AERIAL UNITS RE SAFETY HARNESS, LANT	Usage: 453 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6813	2014 Genie GS-1930 Electric Scissor Lift	
6808	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138135 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3014A-138417 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 459 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6814	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138080 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6819	2017 JLG 1930ES Electric Scissor Lift S/N: M200012853 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 324 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6815	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 464 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6820	2017 JLG 1930ES Electric Scissor Lift S/N: 0200264250 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 392 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6816	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A136467 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 561 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6821	2017 JLG 1930ES Electric Scissor Lift S/N: M200012778 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6817	2013 Genie GS-1930 Electric Scissor Lift S/N: GS3013A124360 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 367 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6822	2017 JLG 1930ES Electric Scissor Lift S/N: M200006460 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 488 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6818	2013 Genie GS-1930 Scissor Lift S/N: GS3013A124169 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6823	2017 JLG 1930ES Electric Scissor Lift S/N: 0200264246 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 525 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6824	2017 JLG 1930ES Electric Scissor Lift S/N: M200006500 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6828	2016 JLG 1930 ES Electric Scissor Lift S/N: 0200256735 C/W: 18 ft 8 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6825	2017 JLG 1930 ES Electric Scissor Lift	6829	2017 JLG 1930 ES Electric Scissor Lift
	S/N: M200006381 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 521 Hr		S/N: M200006299 C/W: 18 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 382 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Oklahoma City, OK
6826	2017 JLG 1930 ES Electric Scissor Lift S/N: 0200264702 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 379 Hr	6830	2016 JLG 1930 ES Electric Scissor Lift S/N: M200003881 C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr
	Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6827	2017 JLG 1930 ES Electric Scissor Lift S/N: M200005469 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6830A	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006461 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6827A	2017 JLG 1930 ES Electric Scissor Lift	6832	2016 JLG 1930ES Electric Scissor Lift
302/A	S/N: M200006504 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 447 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0002	S/N: M200003701 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 446 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6834	2015 JLG 1930 ES Electric Scissor Lift S/N: 0200248756 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 236 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6839	2018 MEC 1330SE Electric Scissor Lift S/N: 16301468 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 24 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6835	2015 JLG 1930 ES Electric Scissor Lift	6840	2018 MEC 1330SE Electric Scissor Lift
	S/N: 0200246003 C/W: 18 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 402 Hr		S/N: 16301584 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	-	Asset located in: Lake Worth, TX
6836	2015 JLG 1930ES Electric Scissor Lift S/N: 0200246832 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 425 Hr	6841	2018 MEC 1330SE Electric Scissor Lift S/N: 16301583 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6837	2012 JLG 1930 ES Electric Scissor Lift S/N: B200004837 C/W: 18 ft 10 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 496 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6842	2018 MEC 1330SE Electric Scissor Lift S/N: 16301451 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 256 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6838	2020 MEC MICRO 19 Electric Scissor Lift	7	Asset located in: Lake Worth, TX
-	S/N: 16907444 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 88 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6843	2018 MEC 1330SE Electric Scissor Lift S/N: 16301467 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6844	2018 MEC 1330SE Electric Scissor Lift S/N: 16301460 C/W: 13 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6849	MEC 1330SE Electric Scissor Lift S/N: 16301456 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6845	2018 MEC 1330SE Electric Scissor Lift S/N: 16301603 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6850	2017 MEC 1330SE Electric Scissor Lift S/N: 16301120 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6846	2017 MEC 1330SE Scissor Lift S/N: 16301230 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 19 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	-6851	2017 Genie AWP-30S Vertical Mast Lift S/N: AWPG89720 C/W: 29 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6847	2017 MEC 1330SE Scissor Lift S/N: 16301591 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 88 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6852	2017 Snorkel MB26J Vertical Mast Lift S/N: MB26J-01-170700055 C/W: 26 ft Max Platform Height, 475 lb Max Weight Capacity, Power to Platform, Upper Control Box Usage: 258 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6848	2017 MEC 1330SE Electric Scissor Lift S/N: 16301447 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6853	2018 Genie IWP-25S Vertical Mast Lift S/N: IWPG-12193 C/W: 24 ft 11 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
6854	2017 Genie AWP-25S Vertical Mast Lift S/N: AWPG-90308 C/W: 24 ft 11 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6860	2016 Genie GR-20 Vertical Mast Lift S/N: GR16P-40894 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 6 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6855	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-49588 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6861	2016 Genie GR-20 Vertical Mast Lift S/N: GR16P-43838 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 640 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6856	2017 Genie GR20 Vertical Mast Lift	6062	2015 Genie GR-20 Vertical Mast Lift
	S/N: GRP-50131 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 342 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6862	S/N: GR15-39295 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 487 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6857	2017 Genie GR-20 Vertical Mast Lift		Asset located in: Oklahoma City, OK
	S/N: GRP-50133 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 419 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6863	2015 Genie GR-20 Vertical Mast Lift S/N: GR1538516 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 448 Hr Asset located in: Lake Worth, TX
6858	2017 Genie GR-20 Vertical Mast Lift	6864	2015 Genie GR-20 Vertical Mast Lift
3000	S/N: GRP48660 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 448 Hr		S/N: GR1539023 C/W: 20 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 435 Hr Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6865	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539233 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 452 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6865A 6865B	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539281 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 498 Hr Asset located in: Lake Worth, TX 2015 Genie GR-20 Vertical Mast Lift	6869	2019 Haulotte STAR 20 Vertical Mast Lift S/N: 2062580 C/W: 19 ft Max Platform Height, 580 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box Usage: 400 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	S/N: GR1538466 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 410 Hr Asset located in: Lake Worth, TX	6870	Asset located in: Lake Worth, TX 2023 Ballymore DVML-18 Vertical Mast Lift (Unused) S/N: DBA2302163 C/W: 19 ft 7 in Max Platform Height, 350 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box Usage: Not Available
6865C	2014 Genie GR-20 Vertical Mast Lift S/N: GR1430574 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	SÜNSTATE-EQUIPMENT Usage: 361 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6871	2017 Genie GR-12 Vertical Mast Lift S/N: GRP-49699 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-
6866	2013 Genie GR-20 Vertical Mast Lift S/N: GR13-27800 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-		SÜNSTATE-EQUIPMENT Usage: 214 Hr Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in : Lake Worth, TX
	EQUIPMENT Usage: 495 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2017 Genie GR-12 Vertical Mast Lift S/N: GRP-49754 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-
6867	2013 Genie GR-20 Vertical Mast Lift S/N: GR1328800 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box		SUNSTATE-EQUIPMENT Usage: 301 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	6873	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41021
6868	2013 JLG 20MVL Vertical Mast Lift S/N: 0130019279 C/W: 19 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 319 Hr
			Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6874	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41028 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 476 Hr Notes: AERIAL UNITS REQUIRE PROPER	6880	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P21140 C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket Usage: 208 Hr Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6881	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P20643
6875	S/N: GR1539738 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension,		C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket Usage: 455 Hr Asset located in: Lake Worth, TX
	Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 367 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6881A	2016 Bobcat MT55 Mini Compact Track Loader S/N: B38T12812 C/W: Open Operator Station, Tier 4, 2016 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,344 Hr Asset located in: Lake Worth, TX
6876	2015 Genie GR-12 Vertical Mast Lift S/N: GR1538757 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 433 Hr Notes: ARRIAL UNITS REQUIRE PROPER	6882	2019 Vermeer S925TX Mini Compact Track Loader S/N: 1VRL07056J1000534 C/W: Open Operator Station, Tier 4, 2018 US EPA Label, 7 in Track Belts, Manual Coupler, 42 in Bucket Usage: 2,318 Hr Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6883	2014 Ditch Witch SK755 Tracked Trencher Cable Plow S/N: CMWZ57NLCE0000057 C/W: Tier 4, 2012 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, Hydrostatic Drive, 7 in Wide x 48 in Long Combination Trencher Chain, 9 in Rubber Tracks Usage: 3,874 Hr Asset located in: Lake Worth, TX
6878	2014 Genie GR-12 Vertical Mast Lift S/N: GR1436093 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT		
	Usage: 544 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6884	2024 Eingp SCL850 Mini Compact Track Loader (Unused) S/N: SCL8500125 C/W: Open Operator Station, 9 in Track Belts, Manual Coupler, 40 in Bucket
6879	2014 Genie GR-12 Vertical Mast Lift S/N: GR14-35973 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6885	Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket Usage: 2 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6886	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6894	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178498 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6887	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: 1 Hr Asset located in: Lake Worth, TX	6895	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409073142 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6888	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178459 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6896	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409043138 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6889	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404163371 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6897	2024 Machpro MP-S300 Mini Compact Track Loader S/N: SLP2403080620 C/W: Open Operator Station, 2023 US EPA Label, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: 37 Hr Asset located in: Lake Worth, TX
6890	2024 JQ POWER JQ400 Mini Compact Track Loader S/N: 2404178462 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6898	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409043137 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6891	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404163356 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6899	2024 BTTL ST25M-6 Mini Compact Track Loader (Unused) S/N: A2407158825 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6892	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409073147 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6900	2024 BTTL ST25M-6 Mini Compact Track Loader (Unused) S/N: A2407158835 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6893	2024 AGT CRT23 Mini Compact Track Loader (Unused) S/N: CRT232024060000006 C/W: Open Operator Station, 2024 US EPA Label, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6901	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT232024052200230 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6902	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT23202408010005 C/W: Open Operator Station, Joystick Steering, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	6910	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044073 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6903	2024 AGT CH904 Wheel Loader	6911	2024 FF Industrial FF18R Mini Excavator
0300	S/N: CH9042024L0618005 C/W: Open Operator Station, 38 in Bucket, 23X8.5-12 Tires Usage: Not Available		S/N: 2408069186 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6904	2007 Ditch Witch R300 Wheel Loader S/N: CMW1D4XK70000069 C/W: Open Operator Station, Auxiliary Hydraulics, Manual Coupler, 36 in Bucket, 20x100-8 Tires Usage: Not Available Asset located in: Lake Worth, TX	6912	2024 Landhero LDH-KV16 Mini Excavator (Unused) S/N: Not Available C/W: 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, 15 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6905	2024 Digmaster DM200 Mini Excavator (Unused) S/N: DM24080305 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket Usage: Not Available	6913	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515624 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6914	2024 Machpro MP15 Mini Excavator (Unused)
6906	2024 Digmaster DM200 Mini Excavator (Unused) S/N: DM24080303 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket Usage: Not Available	S/N: SLP241515549 C/W: 2 ft 7 in Stick, Auxili Plumbing, Backfill Blade, 12 in Digging Bucket, Mar Usage: Not Available	S/N: SLP241515549 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb
	Asset located in: Lake Worth, TX	6915	2024 Machpro MP15 Mini Excavator (Unused)
6907	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408069118 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb		S/N: SLP241515621 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	6916	2024 Machpro MP15 Mini Excavator (Unused)
6908	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408043843 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available	6917	S/N: SLP241515538 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX 2024 Machpro MP15 Mini Excavator (Unused)
6909	Asset located in: Lake Worth, TX 2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044079 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX		S/N: SLP241515589 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX

	D 1 1	I	B
Lot #	Details	Lot #	Details
6918	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515609 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6925	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423105139 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available
6919	2024 Machpro MP15 Mini Excavator (Unused)		Asset located in: Lake Worth, TX
6920	S/N: SLP241515546 C/W: 2 ft 7 in Stick, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX 2024 Machpro MP15 Mini Excavator (Unused)	6926	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423123854 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb
0920	S/N: SLP241515626		Usage: Not Available
	C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Lake Worth, TX	6927	Asset located in: Lake Worth, TX 2024 VICSEC VC13 Mini Excavator (Unused) S/N: VC13240617 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Thumb Bracket
6921	2024 VICSEC VC15P Mini Excavator (Unused) S/N: VA15P240703		Usage: Not Available Asset located in: Humble, TX
	C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Manual Quick Coupler, 17 in Digging Bucket, Manual Thumb Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6928	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136819 C/W: 2024 US EPA Label, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6922	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423032738 C/W: Straight Travel Pedal, Tier 2, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	6929	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136832 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6923	2024 FF Industrial FF-13 Mini Excavator	6930	2024 FF Industrial FF-12 Mini Excavator
0723	(Unused) S/N: 423032626 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: 66 Hr Asset located in: Lake Worth, TX		(Unused) S/N: 423136824 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6924	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423050691 C/W: Enclosed Cab, 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX	6931	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136840 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6932	2024 BTTL ET12M-6 700718 Mini Excavator (Unused) S/N: ET12M-6 700718 C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6938	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
6933	2024 BTTL ET12M-6 Mini Excavator (Unused) S/N: ET12M-6700717 C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6939	Quantity of (56) 2024 Suihe SP10-S-56 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6934	Quantity of (5) 2024 Landhonor LHR-SG64 6 ft x 4 ft Livestock Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6935	Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6940	Quantity of (56) 2024 Suihe SP10-G-56 10 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6936	Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6941	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6937	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6942	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6943	Quantity of (12) 2024 Landhonor LHR-SP07 7 ft Sheep Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6951	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O	
6944	Quantity of (24) 2024 Landhonor LHR-SP07 7 ft Sheep Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	
6945	Quantity of (4) Bundles of 10 Ft Livestock Panel S/N: Not Available		Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	6952	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused)	
6946	2024 Industrias America R820 20 Ft Loading Ramp (Unused) S/N: R82020242517 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
6947	20 ft Loading Ramp (Unused) S/N: Not Available C/W: 30,000 lb. Capacity Usage: Not Available	_	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6953	2024 Agriquip LS1220 12 ft x 20 ft Metal	
6948	2024 Landhonor LHR-CSC10 Cattle Squeeze Chute (Unused) S/N: HL00009 Usage: Not Available Asset located in: Lake Worth, TX		Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
6949	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused)		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	6954	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6955	2024 Agriquip LS1220 12 ft x 20 ft Metal	
6950	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available			Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6956	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6957 6958	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: M12S224202 Usage: Not Available Asset located in: Lake Worth, TX Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX Eingp MSC1220F 20 ft x 12 ft Livestock Shelter	6964	Quantity of (3) 2024 Suihe NFG-20FB-3 Bi- Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
	(Unused) S/N: M12S225549 Usage: Not Available Asset located in: Lake Worth, TX	6965	Asset located in: Lake Worth, TX Quantity of (3) 2024 Suihe NFG-20FC-3 20 ft Bi- Parting Farm Driveway Gate (Unused) S/N: Not Available
6960	Quantity of (50) 12 ft Corral Livestock Panel S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX	6966	C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6961	2024 SUNTOP S0720 Qty of (6) 20FT Bi- Parting Wrought Iron Driveway Gate (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		2024 Suihe NFG-20FGP-D 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6962	Quantity of (6) 2024 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		2024 Suihe NFG-20FGP-E 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6963	Quantity of (6) 2024 SUNTOP S207 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6968	Quantity of (8) 2024 Suihe NG-20D-8 20 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6974	ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6969	Quantity of (8) 2024 Suihe SG-20D-8 20 ft Bi-		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	Parting Driveway Gate (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Rectangle Deer Motif Usage: Not Available	6975	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6970	2024 Suihe SG 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	FOR ILLUSTRATION PURPOSES ONLY AND		Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6976	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
6971	Quantity of (2) 2024 Suihe NG-14D -2 14 ft Bi-		Asset located in: Lake Worth, TX
	Parting Driveway Gate (Unused) S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6977	2024 SUNTOP S0610 Qty of (20) 10FT Portable Construction Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
6972	Quantity of (2) 2024 Suihe NG-14Eu-2 14 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	Usage: Not Available		Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6978	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6973	Quantity of (6) 2024 SUNTOP S07020 20 ft x 7		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
37,0	ft Driveway Gate S/N: Not Available C/W: 20 ft x 7 ft Wrought Iron Bi Parting Driveway Gate Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details		
6979	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6988	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		
		6989	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6990	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle		
6980	Quantity of (26) 2024 Suihe SF-D-26 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX		
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6991	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6992	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		
6981	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6993	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
6982	Quantity of (20) 8 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHE FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT Usage: Not Available	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		
6983	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		
6984	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		
	Usage: Not Available Asset located in: Lake Worth, TX	6005	Asset located in: Lake Worth, TX		
6985	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	6995	F S C F M T U N F	6995 	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6986	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
6987	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
6996	Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7004	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		7005	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors Usage: Not Available
6997	Asset located in: Lake Worth, TX Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7006	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6998	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused)	7007	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	S/N: Not Available C/W: One Rack Usage: Not Available Asset located in : Lake Worth, TX		Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w
6999	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX		/Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7000	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused)
7001	Asset located in: Lake Worth, TX Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7002	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
7003	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
7009	Quantity of (20) 2024 FENS FEN20 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: B44823 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7016	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Humble, TX	7017	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing
7010	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	OWN ARE	(Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7018	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused)
7011	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available		S/N: Not Available C/W: One Rack Usage: Not Available Asset located in : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7019 Quantity of (24) 2024 HUNTER PR 24P 10 ft x 7 ft Powder Coated Fe (Unused) S/N: Not Available Usage: Not Available	S/N: Not Available Usage: Not Available
7012	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7020	Asset located in: Lake Worth, TX Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7013	Asset located in: Lake Worth, TX Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	24P 10 ft x 7 ft Powder (Unused) S/N: Not Available C/W: One Rack Usage: Not Available	S/N: Not Available C/W: One Rack
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7022	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused)
7014	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7023	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused)
7015	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7024	Quantity of (44) 7 ft 10 in x 7 ft Powder Coated Fencing S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

			1 age 344 of 301
Lot #	Details	Lot #	Details
7025	Quantity of (2) Pallets of 78 In x 10 Ft Site Fence S/N: Not Available C/W: Accessories Usage: Not Available Asset located in: Lake Worth, TX	7033	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY AND AN EXACT REPRESENTATION OF
7026	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTATE ACTUAL PRODUCT.
7027	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7034	2024 SUNTOP S4200 Qty of (21) 200ft x 40in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7028	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7029	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused)		THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available
7030	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available) () () () ()
7031	Asset located in: Lake Worth, TX Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused)		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	S/N: Not Available Usage: Not Available	7036	Asset located in: Lake Worth, TX 2024 SUNTOP G500 500 ft x 7 ft Chain Link
7032	Asset located in: Lake Worth, TX Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7037	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7042	Quantity of (8) Fencing S/N: Not Available C/W: Braces Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7038	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	7043	Quantity of (4) Fencing S/N: Not Available C/W: Braces Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7039	Asset located in: Lake Worth, TX Quantity of (36) Rolls of Field Fence 47 In x 330 Ft Fencing (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX Quantity of Fencing S/N: Not Available Usage: 5 Hr	7044	Quantity of Fencing S/N: Not Available C/W: 36 in. Silt Fence With Additional Wooden Stakes Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7041	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (16) Fencing S/N: Not Available C/W: Braces. Rack Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	7045	Asset located in: Lahoma, OK 2024 Agriquip GLHP100 100 ton Air/Hydraulic Shop Press (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		7046	Quantity of (4) Portable Generator Set S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7047	Quantity of (2) Portable Generator Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7058	2020 Ingersoll Rand RS22N 115 cfm Skid- Mounted Electric Air Compressor S/N: CBV699949 C/W: 3 Phase, 30 hp Motor, EQUIPMENT-
7048	Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available		FROM-US-AUTO-RECYCLING Usage: 5 Hr Notes: . Asset located in: Lake Worth, TX 2020 Ingersoll Rand RS22N 114.6 cfm Skid-
	Asset located in: Lake Worth, TX		Mounted Electric Air Compressor
7049	Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		S/N: CBV703202 C/W: 3 Phase, 30 hp Motor, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 7,397 Hr Notes: . Asset located in: Lake Worth, TX
7050	Quantity of (2) Dewalt DXGNR6500 Portable Generator Set S/N: Not Available C/W: 2021 US EPA Label, Generac 389 cc Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7060	2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor S/N: CBV713664 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 7,936 Hr Notes: . Asset located in: Lake Worth, TX
7051	Quantity of (2) Generac GP8000E 8 kW Portable Generator Set S/N: Not Available C/W: 2023 US EPA Label, Generac 420 cc Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7061	2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor S/N: CBV710808 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 2,281 Hr Notes: .
7052	Quantity of (3) Generac GP3600 3.6 kW	7	Asset located in: Lake Worth, TX
	Quantity of (1) Generac GP3500i Portable Generator Set S/N: Not Available C/W: Generac 212 cc Gasoline Engine, 120 V Receptacles Usage: Not Available	7062	2024 Landhonor LHR-GAC60Y 60 Gallon 2- Stage Truck Mounted Air Compressor (Unused S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7053	Asset located in: Lake Worth, TX Quantity of Ryobi 3400 Watt & Champion 3500 Watt Portable Generator Set S/N: Not Available C/W: Dual Fuel Engine, 120 V Receptacles,	7063	Iron Horse Electric 60 gal Shop Air Compressor S/N: Not Available C/W: 150 psi Working Pressure, 6 hp Motor Usage: Not Available Asset located in: Lake Worth, TX
	Gasoline Usage: Not Available Asset located in: Lake Worth, TX	7064	2024 Landhonor LHR-GAC60 Skid-Mounted 60 gal Air Compressor (Unused)
7056	Quantity of (3) Pallets of Portable Generator Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
7057	Multiquip GAW-180H 3 kW Skid-Mounted Portable Generator Set S/N: 5682943 C/W: Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7065	gal Air Compressor (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7074	Jenny Skid-Mounted Air Compressor S/N: Not Available C/W: 2008 US EPA Label, Honda 1 Cylinder 270 cc Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
		7075	2024 Suihe PW Skid-Mounted Pressure Washer (Unused)
7066	Coltec Industries OSI370WNW41A Skid- Mounted Electric Air Compressor S/N: 94897 C/W: 175 psi Working Pressure, 230/460 volts Usage: 2,363 Hr Asset located in: Lake Worth, TX		S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7067	Skid-Mounted Air Compressor S/N: 380091		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	C/W: 2013 US EPA Label, Kohler Command Pro 1 Cylinder 429 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7075A	Northstar Pressure Washer S/N: 4K1BP1625FF001307 C/W: Water Heater, 500 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler 2
7068	Skid-Mounted 30 gal Air Compressor S/N: Not Available C/W: Predator 1 Cylinder 420 cc Gasoline		Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Engine Usage: 88 Hr Asset located in : Lake Worth, TX	7076	Easy-Kleen Magnum 3600 Pressure Washer (Unused)
7069	Eagle 30 Gal Truck Mount Air Compressor S/N: Not Available Usage: Not Available		S/N: 2440130 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
7070	PowerTrain 18.5 cfm 30 gal Air Compressor (Unused) S/N: Not Available C/W: 175 psi Working Pressure, Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7077	Easy-Kleen Magnum 3600 Pressure Washer (Unused) S/N: 243819 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Asset located in: Lake Worth, TX
7071	PowerTrain 11.2 cfm 10 gal Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7078	Easy-Kleen Magnum 3600 Pressure Washer (Unused) S/N: 2440131 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated
7072	Quantity of (5) Electric Air Compressor S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 120V, (2) Goodyear 20 gal, (1) Goodyear 10 gal, (1) Campbell Hausfeld 6 gal, (1) Hyper Tough 6 gal Usage: Not Available Asset located in : Lake Worth, TX	7079	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243888 C/W: 4000 psi Rating, Water Heater, Hose,
7073	Mi-T-M 13.1 cfm Skid-Mounted Air Compressor S/N: 20175543 C/W: 100 psi Working Pressure, 2013 US EPA Label, Honda GX200 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
7080	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244614 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available	7087	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243887 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
7081	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244615 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine	7089	Aladin 8430-C Pressure Washer S/N: Not Available C/W: Water Heater, Electric Operated Usage: 1,411 Hr Asset located in: Midland, TX
	Usage: Not Ávailable	7090	All American 8357L Skid Mounted Pressure Washer (Inoperable)
7082	Asset located in: Lake Worth, TX Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244617 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		S/N: 105855 C/W: Water Heater, Kubota D1105 3 Cylinder Diesel Engine Usage: 1,058 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
7083	Easy-Kleen Magnum Gold Pressure Washer	7091	Landa PGDC5-3500 Pressure Washer
	(Unused) S/N: 244542 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine	7031	S/N: 11100510101372 C/W: 3500 psi Rating, Water Heater, Honda GX630 Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Ávailable Asset located in : Lake Worth, TX	7092	2020 Hotsy 1075SSE Pressure Washer
7084	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243899 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available		
	Asset located in: Lake Worth, TX	7094	2018 Mi-T-M HS-3505-0MDK Pressure Washer S/N: 15119001
7085	Easy-Kleen Magnum Gold Pressure Washer (Unused)		Usage: 404 Hr Asset located in: Lake Worth, TX
	S/N: 244616 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7095	2016 Mi-T-M CW-3504-5MGH Pressure Washer S/N: Not Available C/W: 3500 psi Rating, Honda GX390 1 Cylinder Gasoline Engine Usage: Not Available
7086	Easy-Kleen Magnum Gold Pressure Washer	7096	Asset located in: Lake Worth, TX 2018 Mi-T-M CW25054MGH Pressure Washer
	(Unused) S/N: 244541 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7090	S/N: 11041408 C/W: 2500 psi Rating, Honda GX390 Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7097	2017 Mi-T-M HSP-2503-0MMH Pressure Washer S/N: 15111154 C/W: 2500 psi Rating, Water Heater, Honda GX200 196 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7104	Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, Hose, Spray Wand, Briggs & Stratton CR950 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
7000	·	7105	2019 Mi-T-M HSP-3504-3MGH Pressure	
7098	Quantity of (2) Pressure Washer S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Washer S/N: 15132271 C/W: 3500 psi Rating, Water Heater, Hose, Spray Wand, Honda GX390 Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Corsicana, TX	7106	Quantity of (4) Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine Usage: Not Available	
7099	Simpson MS61219 Pressure Washer		Asset located in: Lake Worth, TX	
	S/N: 05235011741 C/W: 3400 psi Rating, Hose, Spray Wand, Simpson CRX225 1 Cylinder 224 cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7107	Landa PGDC5-3500 Pressure Washer S/N: 11100500101087 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton Vanguard 18 hp 570 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	S/N: 1P9HT1S2321293177 C/W: 3000 psi Rating, Water Heate Water Supply, Hose, Spray Wand, T Mounted, Kohler Command Pro 2 (Gasoline Engine, EQUIPMENT-FRO PRIMORIS-SERVICES-CORP-COMP Usage: 1,068 Hr	S/N: 1P9HT1S2321293177 C/W: 3000 psi Rating, Water Heater, 500 ga	
7100	Simpson Pressure Washer S/N: Not Available C/W: 4000 psi Rating, Honda 1 Cylinder Gasoline Engine		Mounted, Kohler Command Pro 2 Cylinder Gasoline Engine, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY	
	Usage: Not Available Asset located in: Lake Worth, TX	7109	40 ft High Cube Office Storage Container	
7101	Quantity of (4) Boxes of Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7109	(Unused) S/N: KDCU5211968 C/W: Seller Comments: Single W Dual Pane Windows w/ sun scre Insulation in roof, R19 Insulation w/ heat, vinyl flooring, Electric P Ceiling Lights, Interior Outlets, for	(Unused) S/N: KDCU5211968 C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED Ceiling Lights, Interior Outlets, forklift pockets
7102	Quantity of (4) Simpson Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Honda GCV160 Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7110 20 ft Office Storage Containe S/N: SKYU2652356 C/W: Seller Comments: Singl Dual Pane Windows w/ sun s Insulation in roof, R19 Insulat w/ heat, vinyl flooring, Electri Ceiling Lights, Interior Outlets Usage: Not Available	C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED	
7103	Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, Hose, Spray Wand, Briggs & Stratton CR950 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Ceiling Lights, Interior Outlets, forklift pockets	

Lot #	Details	Lot #	Details
7111	2024 LEVE LE20 19 ft 5 in x 20 ft Expandable House (Unused) S/N: A0282 C/W: (2) Bedrooms w/, (1) Bathrooms, (1) Living Room Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7116	2024 Suihe GS2322 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7112	2024 Suihe GS2533 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7117	2024 Suihe M202010P Light Steel Carport (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7113	Asset located in: Lake Worth, TX 2024 Suihe 2040P 40 ft x 20 ft Commercial	7118	2024 Suihe M122009P Light Steel Carport (Unused) S/N: Not Available
	Party Tent (Unused) S/N: Not Available C/W: (18) Removable Side Walls w/PVC Clear Windows, (2) Zipper Doors, 500 gsm PVC Coated Fabrics, Waterproof, Fire & UV Resistant, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 4 2024 SUNTOP S2119 19 ft x 21 ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		7119	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7114			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7120	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7115	2024 Suihe GS2119 21ft x 19ft Portable Metal Shed (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7121	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

This catalog was created at December 10, 2024 03:25:22 PM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7122	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (200) 2024 Machpro S3048C 10 ft Corrugated PPGI Steel Panels (Unused) S/N: 2408070018 C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	7130	2024 Suihe S408020R-300gPE 80 ft x 40 ft x 20 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
7124	Quantity of (200) 2024 Machpro S3048C 10 ft	1	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	7131	2024 Landhonor LHR-ST3085 85 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
7125	2024 Suihe S5010023DP-750gPVC 100 ft x 50 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (4) Boxes - Builds (1) Storage Building Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN A FOR ILLUSTRATION PURPOSES ONLY A	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Suihe S406423DP-610gPVC 64 ft x 40 ft x 23 ft Storage Building (Unused) S/N: Not Available	
7126	2024 Hills Industrial 805026 80 Ft x 50 Ft x 26 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Hills Industrial 504026 50 Ft x 40 Ft x 26		C/W: Quantity of (3) Boxes - Builds (1) Storage Building Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
, 12,	Ft Storage Building (Unused)		Asset located in: Lake Worth, TX	
7128	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Hills Industrial 804024 80 Ft x 40 Ft x 24 Et Storage Building (Unused)	7133	2024 HIlls Industrial 604024 60 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7134	2024 Suihe S308515R-300gPE 85 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available	
7129	2024 Suihe S408023DP-610gPVC 80 ft x 40 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7135	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7142	2024 Hills Industrial 403022 40 Ft x 30 Ft x 22 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Suihe S304015R-300gPE 40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available
7136	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7137	2024 Suihe S306020DP-610gPVC 60 ft x 30 ft x 20 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7144	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7138	2024 Landhonor LHR-ST3040 40 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7145 2024 Suih ft Storage S/N: Not / C/W: Dom Estimated SHOWN A ONLY ANI REPRESE Usage: No Notes: TH FOR ILLUS MAY NOT THE ACTU Asset loca 7146 2024 Suih ft Storage S/N: Not / C/W: Dom Estimated SHOWN A ONLY ANI REPRESE Usage: No Notes: TH FOR ILLUS MAY NOT THE ACTU	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7139	2024 Hills Industrial 604024 60 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES
7140	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7141	2024 HIlls Industrial 603022 60 Ft x 30 Ft x 22 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
7147	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7153	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused)	
			S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7154	2024 Suihe C404013-300gPE x 13 ft Container	
7148	2023 HOS HF2N1 19 ft x 21 ft Folding Storage Building S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7154	Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
7149	Pole Barn Package 16 ft x 24 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: 2 x 6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	Usage: Not Available	7155	Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7155	2024 Suihe C404013-300gPE x 13 ft Container Storage Canopy (Unused)	
7150	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: 2 x 6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	Assembly Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
7151	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused)		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: 2 x 6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX	7156	7156	2024 Suihe C2040-300gPE 20 ft x 40 ft Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7152	16 ft x 24 ft x 40 ft Pole Barn Package Storage Building (Unused) S/N: Not Available C/W: 2x6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details	
7157	2024 Suihe C2040-300gPE 20 ft x 40 ft Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7162	2024 Suihe NWB-H35DS-7 7 ft 35-Drawer Tool Cabinet (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
7158	58 2024 Suihe C2020-300gPE 20 ft x 20 ft Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7163	18 In x 24 In Tool Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		7164	Quantity of Tool Box S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	
7159	2024 Suihe C504017DR-610gPVC 50 ft x 40 ft x 17 ft Container Shelter Storage Canopy (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (2) Conveyor Belts - Fits Tractor S/N: Not Available C/W: (1) 55 In, (1) 42 In; EQUIPMENT-FROM-US-AUTO-RECYCLING		THESE Asset located in: Lahoma, OK	
		7165	UWS TBC60N Tool Box S/N: Not Available C/W: 60 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	
7160			BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK	
	Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7166	S/N: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7161	Quantity of (3) Uline Tool Cabinet S/N: Not Available C/W: (1) 42 In 11 Drawer, (1) 29 In 5 Drawer, (1) 29 In 7 Drawer; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7167	Quantity of (3) Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7172	2024 Suihe NWB-25DB-10 10 ft 25-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7168	Quantity of (3) Truck Toolboxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7173	2024 Suihe NWB-H40DB-10 10 ft 40-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
7169	2024 Suihe NWB-30DS-10 10 ft 30-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7175	Can Industrial 10 ft 40 Drawer Workbench (Unused) S/N: Not Available Usage: Not Available
7170	2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7176	Asset located in: Lake Worth, TX 2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30-
7171	Asset located in: Lake Worth, TX 2024 Suihe NWB-15DR-2-10 10 ft 15-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7177	Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7179	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused)	7184	2024 Suihe NWB-H18DR-7 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available		Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7185	2024 Suihe NWB-10DS-2-7 7 ft 10-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7181	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30- Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT	7187	6 ft 7 in Workbench
7182	Asset located in: Lake Worth, TX 2024 Suihe NWB-H18DB-7 7 ft 18-Drawer Workbench (Unused)		S/N: Not Available C/W: 4 doors, 16 drawers Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7188	U. S. General 72 In 18 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		7189	Yukon 46 In 9 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart;
7183	2024 Suihe NWB-20DS-7 7 ft 20-Drawer Workbench (Unused)		EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7190	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		7191	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		7192	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7193	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7203	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S.General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
7194	Quantity of (2) Milwaukee 40 in 6-Drawer Workbench S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7204 7205	U. S. General 44 in 13-Drawer Workbench S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX U. S. General 44 In 13 Drawer Workbench	
7195	Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: U.S.General 34 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX	
7196	Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7206	Quantity of (4) U. S. General Service Carts S/N: Not Available C/W: (3) 4 Drawer, (1) 5 Drawer; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
7197	Milwaukee 40 In 5 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7207	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7198	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7208	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers WB-90-243 7 ft 6 in	
7199	Asset located in: Lake Worth, TX Quantity of (3) U. S. General 30 In Tech Carts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7209 7210	Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers WB-90-243 7 ft 6 in	
7200	Asset located in: Lake Worth, TX U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 7211 2024 Kit Containers WB-90-243 7 Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 7211 2024 Kit Containers WB-90-243 Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 7212 2024 Kit Containers WB-90-243	Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers WB-90-243 7 ft 6 in
7201	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available			S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers WB-90-243 7 ft 6 in
7202	Asset located in: Lake Worth, TX U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available	

Lot #	Details	Lot #	Details
7213 7214	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers WB-90-243 7 ft 6 in	7225	Quantity of (2) 2024 Suihe N-1CY -2 1 cyd Self- Dumping Hopper (Unused) S/N: Not Available C/W: Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7215	2024 Kit Containers WB-60-190 5 ft Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7226	Asset located in: Lake Worth, TX 2024 Kit Containers 2YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available
7216	2024 Kit Containers WB-60-190 26 In x 60 In Workbench (Unused) S/N: Not Available Usage: Not Available		C/W: 5 ft 6 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available Asset located in : Lake Worth, TX
7217	Asset located in: Lake Worth, TX 2024 Kit Containers ST-57 29 In x 57.5 In Workbench (Unused) S/N: Not Available Usage: Not Available		2024 Kit Containers 2YFT-SDH Skid Steer Dump Hopper (Unused) S/N: B21J1204 Usage: Not Available Asset located in: Lake Worth, TX
7218	Asset located in: Lake Worth, TX 2024 Kit Containers ST-57 4 ft 10 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Kit Containers 2YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 10 in High Usage: Not Available
7220	Quantity of (4) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX	7229	Asset located in: Lake Worth, TX 2024 Kit Containers 1.5YFT-SDH Skid Steer Dump Hopper (Unused)
7221	2024 Kit Containers 4Y-DH Debris Box (Unused)		S/N: B21J1206 Usage: Not Available Asset located in : Lake Worth, TX
	S/N: B12I407 Usage: Not Available Asset located in : Lake Worth, TX	7230	2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available
7222	2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: B191402 Usage: Not Available		C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	7231	2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self-
7223	Quantity of (5) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in: Lake Worth, TX
7224	Quantity of (4) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7232	Quantity of (5) 4 ft 6 in Self-Dumping Hopper S/N: Not Available C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7233	Quantity of (4) 4 ft 6 in Self-Dumping Hopper S/N: Not Available C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7242	Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7234	Quantity of (2) 2024 Suihe N-1.5CY-2 1.5 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7243	Quantity of (3) Bundles of Standard Beam 4" 7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44 ft S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Square Bar 5/8 A-36 20'	
7235	Asset located in: Lake Worth, TX 25 ft Loading Ramp (Unused) S/N: Not Available	72 4 5 -	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7236	Usage: Not Available Asset located in: Humble, TX Quantity of (5) Abell-Howe 1 Ton Electric Shop Pedestal Crane S/N: Not Available	7246	Quantity of (1) Bundle of 4 In x 36 Ft Wide Flange Beam S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7247 Quain 1	Quantity of (1) Bundle of Wide Flange Beam 10 in 15.0 A992/A572-50 40 ft S/N: Not Available Usage: Not Available	
7237	Quantity of (5) Abell-Howe 1Ton Electric Shop Pedestal Crane S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7248	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7238	Quantity of (5) 2020 Abell-Howe 1 Ton Electric Shop Pedestal Cranes S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7249 7250	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Bundles of Hex Netting Mazel Co 22	
7240	Quantity of (2) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44'	1	S/N: Not Available Usage: Not Available	
7241	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Bundles Of Standard Beam 4"	7251	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black C40 12.0-12.5 S/N: Not Available Usage: Not Available	
	7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7252	Asset located in: Lake Worth, TX Quantity of (6) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7253	Quantity of (5) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available	7263	Quantity of (1) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 96" 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7254	Asset located in: Lake Worth, TX Quantity of (6) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX	7265 7266	Quantity of (1) Bundle Of Sheep/Goat Fence 10- 12.5 4 In x 48 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles of Chainlink Xtreme 2
7255	Quantity of (2) Bundles of Horse Fence Xtreme Black 12.5-12.5 2 in x 48 in x 200 ft S/N: Not Available Usage: Not Available	7267	In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles of Chainlink Xtreme NC
7256	Asset located in: Lake Worth, TX Quantity of (3) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available Usage: Not Available		2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7257	Asset located in: Lake Worth, TX Quantity of (3) Bundles of Horse Fence Xtreme Black 12.5-12.5 2 in x 48 in x 200 ft S/N: Not Available Usage: Not Available	7268	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7258	Asset located in: Lake Worth, TX Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200' S/N: Not Available	7269	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7259	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200' S/N: Not Available	7270	Quantity of Bundles of Chainlink Xtreme NC 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7260	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available Usage: Not Available	7271	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7261	Asset located in: Lake Worth, TX Quantity of (2) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7272 7273	Quantity of (4) Bundles of Horse Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles of 9 Gauge 20 in 48 in,
7262	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		50 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		7274	Quantity of Magnum 3 in 16d Nails S/N: Not Available C/W: One Pallet Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7275	Quantity of Horse Fence Xtreme Black S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7286	Quantity of (3) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7276	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7287	Quantity of (2) Bundles of Welded Utility Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7277	Quantity of (2) Bundles of Chainlink Xtreme Fence S/N: Not Available Usage: Not Available	7288	Quantity of (4) Bundles of Horse Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7278	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black C40 S/N: Not Available Usage: Not Available	7289	Quantity of (4) Bundles of Galvanized Welded Fence 1 in x2 in 48 in 100 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7279	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available	7290	Bundle of Galvanized Welded Fence 2 in x4 in 60 in 100 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7280	Asset located in: Lake Worth, TX Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black	7291 7292	Quantity of (3) Bundles of Galvanized Welded Fence 1"x2" 48" 100' S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		Asset located in: Lake Worth, TX Quantity of (2) Bundles of Mazel Hex Netting 2" x 60" x 150'
7281	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available	7000	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
7282	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available	7293	Quantity of (2) Bundles of EZ Rol Chainlink PVC 1 1/2" 60" 50' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7283	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles of Mazel 2 in x 36 in x 150 ft Hex Netting S/N: Not Available	7294	Quantity of (1) Bundle Of Game Fence Stay Lock 12.5-12.5 6 In x 96 In x 330 Ft Fencing S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7284	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles of Welded Utility Fence S/N: Not Available Usage: Not Available	7295	Quantity of (1) Bundle of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7285	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7296	Quantity of (2) Bundles of Chainlink Fence (1) C3 11.5 2-3/8" 72" 50ft KT (1) C3 11.5 2-3/8" 48" 50ft KK S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7297	Quantity of (2) Bundles of Game Fence Stay Lock C3 12.5-12.5 6 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7308	Quantity of (4) Tool Carts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7298	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Bundles of Fencing	7309	Quantity of (4) Pallets of Eye Wash Stations & Spill Kits S/N: Not Available C/W: (1) Pallet of Absorbent Socks, (1) Pallet of Spill Kits, (2) Pallets of Eye Wash Stations; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
	S/N: Not Available C/W: (2) Fixed Knot Xtreme Black 96 In x 330 Ft, (1) Game Fixed Knot Stay Lock 96 In x 330 Ft Usage: Not Available Asset located in : Lake Worth, TX	7310	Asset located in: Lake Worth, TX Electric Pump S/N: Not Available C/W: MT 1/3 Hp Electric Motor, Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7300	Quantity of (3) Bundles of Game Fence Stay Lock C3 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7311	Asset located in: Lake Worth, TX Sipco Hydraulic Drive Notor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7301	Quantity of (1) Bundle of Game Fence Stay Lock 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7312	Asset located in: Lake Worth, TX Enerpac MSFP10 Hydraulic Pump S/N: P392 C/W: Sheet Metal Pieces, (2) 10 Ton Jack Stands; EQUIPMENT-FROM-US-AUTO-
7302	Quantity of High-Tensile Galvanized 15.5 Gauge Barbed Wire S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7314	RECYCLING Usage: Not Available Asset located in : Lake Worth, TX
7303	Quantity of Magnum 3 in 16d Nails S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE
7304	Quantity of (2) Pallets of Magnum 3" 16d Nails S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7315	AVAILABLE Asset located in: McAlester, OK Quantity of (5) Spy Pipeline Detectors & (1) Recorder
7305	Quantity of (2) Pallets of 3 1/2" 16d Bright Common Nails S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available Notes : LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
7306	Quantity of (2) Bundles of Barbed Wire High Tensile C3 15.5 8 Rod S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
7307	Quantity of Conveyor Belt S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7316	Quantity of Assorted Construction parts S/N: Not Available C/W: Hydraulic Hoses, Tool Box, Caution Tape, Heavy Duty Rack, Sand Bags, and Misc Parts Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	7322	Quantity of Suction Hose S/N: Not Available C/W: 2 in., 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7317	Quantity of (4) Pro-Start 25 ft Booster Cables S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7323	Quantity of Hose S/N: Not Available C/W: 2 in. Discharge Hose Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
7317A	2023 Zetech Hydraulic drive motor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7317B	2023 Zetech Hydraulic drive motor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7324	Asset located in: Lahoma, OK Quantity of Water Hose S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7318	General EP8 Manhole Blower S/N: 33313 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7319	Quantity of (2) Discharge/Suction Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	- 7326	2015 Wanco WTMMB Solar Message Board S/N: 5F12S1611F1000499 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Lunette Ring Usage: Not Available Asset located in: Lake Worth, TX
7320	Quantity of (4) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7327	2015 Wanco WTMMB Solar Message Board S/N: 5F12S161XF10005003 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch
7321	Quantity of Hose S/N: Not Available		Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 3 in. Discharge Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7328	2012 Solar Signal Message Board S/N: 1B9ST1012CL657441 C/W: 6 Lamps, Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX
		7329	2012 HORIZON SIGNAL TECH SQ3TS Traffic Signal S/N: 1B9ST1010CL657471 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7330	2021 Wanco WTMMB Solar Arrow Board S/N: 5F12S1614M005001 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX	7340	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7331	2016 Wanco WTSP Solar Arrow Board S/N: 5F11S1016G1006322 C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	7341	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (250) 2024 HUNTER PRO C-75 Traffic Cones Traffic Cones (Unused)
7332	2016 Wanco WTSP Solar Arrow Board S/N: 5F11S1016G1006319 C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available	7343	S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX Quantity of (250) 2024 HUNTER PRO C-75
7333	Asset located in: Humble, TX 2015 Wanco WTMMB Solar Arrow Board S/N: 5F12S161XF1000503 C/W: LED Lighting, Electric Winch Raise and	7344	Traffic Cones Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
	Lower, S/A Trailer, Lunette Ring Usage: Not Available Asset located in : Lake Worth, TX		Quantity of (250) 2024 Agriquip GL28TC Traffic Cones (Unused)
7334	Truck Mount Arrow Board S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7335	Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused)	7345	Asset located in: Lake Worth, TX
	S/N: Not Available C/W: One Rack Usage: Not Available Asset located in : Lake Worth, TX		Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7336	Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	7346	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7337	Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available	7347	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7338	Asset located in: Lake Worth, TX Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	7348	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7339	Quantity of (50) Traffic Barrier S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7349	Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7357	2008 Milstead 4000 gal Skid Mounted Steel Fuel Tank S/N: 1818-C881958 Usage: Not Available Asset located in: Lake Worth, TX 2024 AM Tank 2300N 2376 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82443 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available
7350	Quantity of (250) 2024 Suihe TC-250 Traffic		Asset located in: Lake Worth, TX
7550	Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7359	2024 AM Tank 2300N 2376 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82442 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7360	2024 4-Fuel.com 4F2330 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005579
7351	2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available		C/W: 120V Pump, 13 ft Hose, Fuel Meter, Auto Nozzle, Spill Containment Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available	7261	2024 4-Fuel.com 4F2330 Gal Skid Mounted
7352	Asset located in: Lake Worth, TX 2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7361	Diesel Fuel Tank (Unused) S/N: 000005580 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX
7353	Quantity of (100) 2024 HUNTER PRO RB-100	7362	2024 4-Fuel.com 4F1100 Gal Skid Mounted
	Traffic Delineators & Bases (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	-	Diesel Fuel Tank (Unused) S/N: 000005581 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX
7354	Quantity of (100) 2024 HUNTER PRO RB-100 Traffic Delineators & Bases (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7363	2000 gal Steel Gasoline Fuel Tank S/N: ST5376 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7355	Quantity of (130) Traffic Barrels S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7364	2000 gal Steel Diesel Fuel Tank S/N: ST5384 C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7356	Quantity of (13) 7 Ft x 4 Ft Crowd Control Barriers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7365	Asset located in: Lake Worth, TX 1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000364 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7366	1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000427 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7375	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005582 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX
7367	2000 gal Skid Mounted Steel Single Wall Fuel	7076	·
	Tank S/N: ORP2000468 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7376	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005583 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available
7368	1000 gal Skid Mounted Steel Fuel Tank		Asset located in: Lake Worth, TX
	S/N: ORT1000343 C/W: Spill Containment Usage: Not Available Asset located in : Lake Worth, TX	7377	750 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available
7369	1000 gal Skid Mounted Steel Single Wall Fuel Tank		Asset located in: Lake Worth, TX
	S/N: ORT1000313 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7378	2024 AM Tank 600 655 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82446 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment
7370	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000310 C/W: Spill Containment		Usage: Not Available
		7070	Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	7379	2024 AM Tank 600 655 gal Skid Mounted Stee Fuel Tank (Unused)
7371	2000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT2000127 C/W: Spill Containment		S/N: 82447 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	7380	500 gal Skid Mounted Steel Fuel Tank
7372	1000 gal Skid Mounted Steel Single Wall Fuel Tank		S/N: ORT5005289 Usage: Not Available Asset located in : Lake Worth, TX
	S/N: ORT1000350 C/W: Spill Containment Usage: Not Available Asset located in : Lake Worth, TX		1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000332 C/W: Spill Containment Usage: Not Available
7373	2024 AM Tank 800 838 gal Skid Mounted Steel		Asset located in: Lake Worth, TX
	Fuel Tank (Unused) S/N: 82445 C/W: 120 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available	7382	500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005280 Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	7383	500 gal Skid Mounted Steel Fuel Tank
7374	2024 AM Tank 800 838 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82444		S/N: ORT5005362 Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 120 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7384	Morrison Bros Co. FTBDS-0500 Skid Mounted Steel Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
7385	300 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Asset located in: Lake Worth, TX Wen Industries Diesel Buggy Portable Steel	7393	2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL
	Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Agriquip GLDP480 116 gal Portable Poly
7387	2024 AM Tank 116 gal Portable Poly Tank (Unused) S/N: 57066L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX		Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
7388	2024 AM Tank 116 gal Portable Poly Tank (Unused) S/N: 57067L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7395	2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN
7389	2024 AM Tank 116 116 gal Portable Poly Fuel Tank (Unused) S/N: 57068L		EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX	7396	2022 Teran TDT116GL 116 gal Fuel Tank (Unused) S/N: 46570L C/W: Polyethylene tank for diesel fuel transpo
7390	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005586 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks		equipped with a fuel transfer unit, 116 gal with 12V Pump (12GPM), 13ft Hose, Auto-Nozzle, Top Covering Lid. Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	7397	Quantity of (2) 100 gal Steel Diesel Fuel Tank S/N: Not Available
7391	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005584 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
7392	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005585 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks Usage: Not Available Asset located in: Lake Worth, TX		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Corsicana, TX

Lot #	Details	Lot #	Details
7398	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: DEEZEE tool box; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7406	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7407	Quantity of (7) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7399	DeeZee 92 gal Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB W NOT BE ABLE TO ASSIST WITH LOADING THESE
7400	DeeZee 92 gal Portable Steel Diesel Fuel Tank		Asset located in: Corsicana, TX
	S/N: Not Available Usage: Not Available Asset located in : Midland, TX	7408	Quantity of (3) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7401	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7402	Weather Guard 92 gal Steel Diesel Fuel Tank		Asset located in: Corsicana, TX
	S/N: 1915613344 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7409	Quantity of (2) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7403	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: ITEMS AT OFFSITE LOCAT BE PICKED UP WITHIN 14 DAYS O AUCTION (JANUARY 3RD) OR WIL SUBJECT TO 3RD PARTY STORAG BUYER RESPONSIBLE FOR LOADO
7404	Asset located in: Midland, TX	_	Asset located in: Corsicana, TX
7404	DeeZee 92 gal Portable Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump, 11 ft Hose Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7410	Quantity of Steel Truck Bed Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7405	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7411	Steel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	7419	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005589 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		2024 4-Fuel.com 4F58 Gal Portable Poly Diesel
7412	2024 AM Tank 58 gal Portable Poly Tank (Unused) S/N: 57172A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available		Fuel Tank (Unused) S/N: 000005588 C/W: 12 v transfer pump, 13 ft hose, autonozzle Usage: Not Available Asset located in: Lake Worth, TX
7413	Asset located in: Lake Worth, TX 2024 AM Tank 58 58 gal Portable Poly Fuel Tank (Unused) S/N: 57170A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	7421	2013 Transcube 30TCG 792 gal Skid Mounted Steel Fuel Tank S/N: D871188 C/W: 12 V Transfer Pump Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7422	2024 AM Tank 29 gal Portable Poly Fuel Tank
7414	2024 AM Tank 58 gal Portable Poly Tank (Unused) S/N: 57171A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle	7423	(Unused) S/N: 15160E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2024 AM Tank 29 gal Portable Poly Fuel Tank
7415	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005593 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available		(Unused) S/N: 15158E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7424	2016 Transcube 20TCG 528 gal Skid Mounted
7416	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005591 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available		Steel Fuel Tank S/N: A61281755 C/W: 12 V Transfer Pump Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7417	7417 2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005592 C/W: 12 V Transfer Pump, 13 ft Hose,	7426	Quantity of (3) 100 Gal Transfer Fuel Tanks S/N: Not Available C/W: (2) L-Shaped, (1) Rectangle Usage: Not Available
		7427	Asset located in: Lake Worth, TX Skid Mounted Steel Fuel Tank S/N: Not Available Usage: Not Available
7418	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel		Asset located in: Humble, TX
	Fuel Tank (Unused) S/N: 000005590 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7428	2000 gal Steel Gasoline Tank S/N: ST5369 C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7429	2000 gal Steel Oil Tank S/N: ST5383 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX 2000 gal Steel Coolant Tank S/N: ST5374 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7437	Steel Hydraulic Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX
7431	300 gal Steel Windshield Wash Tank S/N: ST5329 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7439	2024 Agriquip GLDP20 Fuel Pump (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
7432	2024 AM Tank 29 gal Portable Poly NH3 Tank (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7440	2024 GLDP20 12V Diesel Transfer Fuel Pump (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7/22		7441	2024 Agriquip GLDP20 Fuel Pump (Unused)
7433	2024 AM Tank AM-SPRAYER 14 14 gal Portable Poly NH3 Tank (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15159E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	7441	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7442	Quantity of (2) 2024 Agriquip GLGP20 Fuel
7435	2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15157E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX		Pump (Unused) S/N: Not Available C/W: Hose, Nozzle THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
7436	Ace Roto-Mold 300 gal Poly Holding Tank S/N: LP00300BHSS Usage: Not Available Asset located in: Lake Worth, TX	7443	2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused) S/N: Not Available C/W: 49 ft Hose Reel, 12v DC, 10 gpm Usage: Not Available Asset located in: Lake Worth, TX
		7444	2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused) S/N: Not Available C/W: 49 ft Hose Reel, 12v DC, 10 gpm Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7445	Quantity of (2) Fuel Boss 12 V DC Fuel Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7465	Quantity of (4) Freightliner Fuel Tanks; (2) Tanks-100gal, (1)-120gal, (1) Unknown - Fits Truck S/N: Not Available
7446	Quantity of (2) Fuel Boss 12 v Fuel Pump S/N: Not Available Usage: Not Available		C/W: Aluminum Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	7466	Quantity of Truck Parts
7447	Fuel Boss 1 in Hose Reel W/ 110 V Pump, 50 ft. Deliver Hose Fuel Pump S/N: Not Available C/W: Fuel Pump		S/N: Not Available C/W: Mud Flaps, Belts, Filter, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7467	HTM Model 5 Fifth Wheel Wrecker (Unused)
7448	2012 IMT 30/217 Truck Mounted Boom S/N: 771397		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 54 ft reach, 5 section knuckle boom, 3 pallets of hydraulic fluid tank, stabilizers, rear bumper Usage: Not Available Asset located in: Lake Worth, TX	7468	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7449	Knapheide 8 Ft Flatbed S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7469	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7450	Caseco MM225 11 Ft Service Body S/N: 70628170 C/W: Auto Crane 6406H 6000 LB Crane Usage: Not Available Asset located in: Lake Worth, TX	7473	HMT Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7460	L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump Usage: Not Available	7474	Quantity of (4) Seats & (2) Consoles S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7 461	Asset located in: Lake Worth, TX L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump Usage: Not Available	7475	Quantity of Truck Toolbox & Ladder Rack S/N: Not Available C/W: Rawson Koenig tool box Usage: Not Available Asset located in: Lake Worth, TX
7462	Asset located in: Lake Worth, TX Quantity of (25) Hendrickson S-34446-L Brake Chambers S/N: Not Available C/W: One Pallet	7476	Quantity of (2) Pallets of Dock Bumper (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7477	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 256 Usage: Not Available
7463	Quantity of (2) Pallets of Trailer sub frame complete assembly S/N: 2017045964 C/W: Steel Usage: Not Available Asset located in: Lake Worth, TX	7478	Asset located in: Lake Worth, TX 2024 Neks Fifth Wheel Wrecker (Unused) S/N: 260 Usage: Not Available Asset located in: Lake Worth, TX
7464	Quantity of (4) Freightliner Fuel Tanks S/N: Not Available C/W: 100 gal Aluminum Usage: Not Available Asset located in: Lake Worth, TX	7479	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 255 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7480	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 259 Usage: Not Available Asset located in: Lake Worth, TX	7488	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7481	ProTech Aluminum Headache Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WIL NOT BE ABLE TO ASSIST WITH LOADING
7482	Truck Hood S/N: Not Available C/W: Fiberglass, To Fit Peterbilt Usage: Not Available	7489	THESE Asset located in: Corsicana, TX Enclosed Cab & ROPS Structure - Fits Cat D6R
7484	Asset located in: Lake Worth, TX Peterbilt Truck Cab S/N: 67741 Usage: Not Available Asset located in: Lake Worth, TX		/ D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
7485	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7490	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7486	Asset located in: Corsicana, TX Cat Cab - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7491	Cat Truck Dump Body S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length Usage: Not Available Asset located in: Lake Worth, TX
7487 Enclosed Cab & ROPS / D6T S/N: Not Available	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T	_ 7492	Cat Truck Dump Body S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length Usage: Not Available Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7493	Cat To Fit CAT 745 Truck Dump Body S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
BI N TI	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7494	John Deere To Fit Deere 410E Truck Dump Body S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7495	Cat To Fit CAT 740B Truck Dump Body S/N: Not Available C/W: Lift Cylinders, Tailgate Usage: Not Available	7505	Quantity of (27) Brake chambers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7497	Asset located in: Lake Worth, TX Quantity of (2) Transmission S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7506	Quantity of (2) Paccar 75 &100 gal 24.5 in dia Fuel Tanks (Unused) S/N: K424-0457N0102K075 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7507	Volvo D13H Engine S/N: Not Available C/W: 6 Cylinder 425 hp Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
7498	Quantity of (2) Transmission S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7508	Quantity of (6) 19.5 steel rims (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7499	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX 2012 Hanco 20 ft Flatbed	7509	Quantity of (2) Aluminum Fuel Tanks - Fits Freightliner Cascadia S/N: Not Available C/W: (1) 150 Gallon & (1) 125 Gallon Usage: Not Available
	S/N: 107585 C/W: 2 storage boxes Usage: Not Available Asset located in : Lake Worth, TX	7510	Asset located in: Lake Worth, TX Detroit DD15AT Engine S/N: Not Available
7500	Cat Radiator - Fits Truck S/N: Not Available		C/W: 6 Cylinder 505 hp 14.8 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes : ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7511	Quantity of (12) 22.5 Rims S/N: Not Available C/W: (9) Aluminum, (3) Steel, One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7504	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7512	Quantity of (12) 24.5 In Steel Rims S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7501 	Quantity of Quarter Fenders S/N: 50567 Usage: Not Available Asset located in: Humble, TX	7513	Quantity of (16) 22.5 In Aluminum Rims S/N: Not Available C/W: One Pallet
7502	Truck Hood S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7515	Usage: Not Available Asset located in: Lake Worth, TX International DT466 Engine with Spicer Transmission
7503	Thermaflow Wet Kit S/N: Not Available C/W: Hoses, PTO, One Pallet Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
7504	Asset located in: Lake Worth, TX Quantity of (16) 22.5 Aluminum Rims S/N: Not Available C/W: One Pallet Usage: Not Available	7516	5 Truck Hood S/N: Not Available C/W: To Fit Peterbilt 387 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7517	Quantity of (2) Air ride seats S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7532	Merritt Saddle Box Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7526	Quantity of (6) Truck Toolboxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7533	Quantity of (2) Merritt Saddle Box Truck Tractor Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7527	Truck Toolbox S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7534	Quantity of (2) ProTech Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION
7528	Quantity of (3) Truck Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7557 Truck Flatbed Body S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	Truck Flatbed Body S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7529	Truck Toolbox S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE		CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7573	Synder Tank Corp Truck Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7530	Quantity of (3) Truck Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	PICKED UP BY JANUARY 3RD OR SUBJECT TO 3RD PARTY STORAGE Asset located in: Corsicana, TX 7574 Quantity of (2) CNG Fuel Tanks S/N: Not Available C/W: EQUIPMENT-FROM-WATKIN CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION PICKED UP BY JANUARY 3RD OR	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7531	Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BI PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES

Lot #	Details	Lot #	Details
7575	Quantity of Truck Fuel Tanks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7594	Quantity of (6) PowerTrain PT240 Engine S/N: Not Available C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7595	Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available
7576	Wet Kit Pump and Hydraulic Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		C/W: Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7596	Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7577	Asset located in: Corsicana, TX Water Pump Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7597 (Quantity of (6) PowerTrain PTG2500XCS Engine (Unused) S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
 7578	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Truck Blower Parts	7598	Quantity of (6) PTTP300 Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available
, , , ,	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7599 Quantity of (6) PTWP400 Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX 7600 Detroit 50435001 DD 453 Engine S/N: 4D0131900 C/W: 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	Quantity of (6) PTWP400 Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available
7579	Asset located in: Corsicana, TX Drive Axle S/N: Not Available		S/N: 4D0131900 C/W: 4 Cylinder Diesel Engine
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
7580	4.10 Axle S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	 7601	Isuzu Engine S/N: Not Available C/W: 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	LL BE S/N: 5EK385 FEES C/W: 6 Cylin Usage: Not A	1996 Cat 3406E Engine S/N: 5EK38572 C/W: 6 Cylinder Diesel Engine Usage: Not Available
7592	Trailing Tag Axle S/N: Not Available C/W: Air Ride Suspension, 11R22.5, Aluminum Rims Usage: Not Available Asset located in: Lake Worth, TX	7603	Asset located in: Lake Worth, TX Cummins N14 Engine S/N: 11849308 C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
7593	Cat 3306 Engine S/N: 08Z32520 C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7604	BMW Engine S/N: Not Available C/W: 6 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX 19 In x 71 In Loading Ramps S/N: Not Available Usage: Not Available	7612	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX
7606	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX	7613	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7607	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7608	Quantity of (4) Salvation Trailers (4)Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX	7614	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7609	Quantity of (4) Salvation Trailers (4) Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7610	Quantity of (4) Salvation Trailers (4) Heavy		Asset located in: Corsicana, TX
7611	Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Mercury Boat Engine S/N: Not Available	7615	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
7616	Quantity of hydraulic hoses Hydraulic Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	7625	Quantity of (48) 205x75x15 Radial Tires & 5 Lug Wheels (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7626	Quantity of (4) 6-PLY RADIAL TIRE 5 ON 5 SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX	
7617	Quantity of (9) 11R24.5 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX	7627	Quantity of (4) 235/80R16 10-PLY RADIAL TRAILQUEST 16" 8-HOLE SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels	
7618	Alliance 700/40-22.5 Flotation Tire S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX	
7619	Asset located in: Lake Worth, TX Quantity of (2) 480/80R42 Tires S/N: Not Available	7628	Quantity of (2) Armour 11.00-16 Tires S/N: Not Available C/W: All Tires with Wheels, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available	
	C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	
7620	Quantity of (2) 1300x530x508 Tires		Asset located in: Corsicana, TX	
	S/N: Not Available C/W: Some Tires with Wheels Usage: Not Available Asset located in : Lake Worth, TX	7629	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7621	Quantity of (2) Hubs & Tires S/N: Not Available C/W: 18x8.50x10 Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7630	2024 Agriquip GLTC24 Tire Changer (Unused)	
7622	Quantity of John Bean Tire Balancer & Tire Changer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
7623	Quantity of John Bean Tire Balancer & Tire		Asset located in: Lake Worth, TX	
	Changer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7631	Quantity of (2) 2020 Weaver W-898XS Semi- Automatic Tire Changer S/N: 820052876/820052872 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING	
7624	Quantity of (32) 235x80x16 10 Ply Radial Trailer Tires on Dial Wheels (Unused) S/N: Not Available		Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
		7635	Quantity of (2) Weaver W-898XS Semi Automatic Tire Changer S/N: 820052875/820052871 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7636	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042601H C/W: 110V, 2 HP Electric Motor, Bead Blaster System Usage: Not Available Asset located in: Humble, TX	7644	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050639 Usage: Not Available Asset located in: Lake Worth, TX
7637	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7645	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050640 Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7646	ARI Hetra HDML8 Electric 150000 Lbs Vehicle Lift S/N: 01050638 Usage: Not Available
7638	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7647	Asset located in: Lake Worth, TX 2024 Agriquip GLTP4500 10000 lb Two-Post Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7639	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Agriquip GLTP4500 10000 lb Two-Post Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7640	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7649	Asset located in: Lake Worth, TX Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7641	Asset located in: Lake Worth, TX Cuda H20-4860 Parts Washer - Fits CUDA H20- 4860 S/N: 10434450-100210 Usage: Not Available Asset located in: Midland, TX	7650	Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7642	Cuda H20-4860 Parts Washer - Fits CUDA H20-4860 S/N: 10434450-100209 Usage: Not Available Asset located in: Midland, TX	7651	Quantity of (5) 2020 Weaver 10N000DWRD 10000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
7643	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050641 Usage: Not Available Asset located in: Lake Worth, TX		Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7652	Quantity of (2) 2020 Weaver F12N300BBL 12000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7659	Quantity of 2024 Landhero UBP-65-80 Universal Bucket Pin (Unused) S/N: Not Available C/W: (4) 65 mm x 475 mm & (4) 70 mm x 475 mm & (4) 80 mm x 550 mm,; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7653	Transmission Stand S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhero UBP-90-100 Universal Bucket
	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		Pin (Unused)
7654	Graco Grease Injection Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES		S/N: Not Available C/W: (4) 90 mm x 650 mm, (2)100 mm x 750 mm, ;THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	Asset located in: Corsicana, TX	_	THE ACTUAL PRODUCT
7655	Quantity of (3) Bolt Bin		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7661	Quantity of Engines and Generators S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7656	Greenlee 24 In x 48 In Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7662	Excavator Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7657	Greenlee 24 In x 48 In Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7658	2024 Landhero UBP-25-60 Universal Bucket Pin (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7663	Quantity of Parts & Tools S/N: Not Available C/W: (2) Seats, Mud Flap, Sockets, Barbed Wire, (2) Pallets Usage: Not Available Asset located in: Lake Worth, TX
		7664	Pro Tech Aluminum Headache Rack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		7665	Quantity of PVC Fittings S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7666	Master MH190T-KFA 190000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX	7680	25' Steel Floor Ramp (Unused) S/N: Not Available C/W: 25'x101" Loading ramp, 12"x14Lbs I- beam frame, 6" channel in the middle, 3" Channel crossmembers, Smooth plate floor with expanded metal welded on, 18' long angled ramp with 7' flat surface, 3-10K	
7667	Quantity of (4) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		adjustable jacks. Usage: Not Available Asset located in: Lake Worth, TX Quantity of Parts	
7668	Quantity of Parts S/N: Not Available Usage: Not Available	7681 	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	
7670	Asset located in: Lake Worth, TX Quantity of Parts & Tools S/N: Not Available C/W: Bosch Drill, Wrenches, Wheels, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7682 	Quantity of (2) Zato Hydraulic Pumps S/N: Not Available C/W: Linde HPV280; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
7671	NVE 607 Challenger Vacuum Pump S/N: 36777 Usage: Not Available Asset located in: Lake Worth, TX	7683	Quantity of (2) Schaeffler Roller Bearings S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
7672	Quantity of Hydraulic Pump & Crusher Blades S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7684	Star Industries 1210 4 ft x 8 ft Work Platform S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7673	Quantity of Contractor Supplies S/N: Not Available C/W: Hose, Poulan Pro Chain Saw, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7685	JLG 3248RS Parts S/N: Not Available C/W: Deck, Boom Arms, Cylinders Usage: Not Available Asset located in: Lake Worth, TX	
7674	Quantity of Truck Parts S/N: Not Available C/W: Exhausts/Pipes, Headlights Usage: Not Available Asset located in: Lake Worth, TX	7686	Skyjack SJ8841 RT Parts S/N: Not Available C/W: Deck, Tires, Outriggers, Hyd Cylinders, Transfer Case, Drive Shaft, Engine, Fuel & Hydraulic Tank Box Usage: Not Available	
7677	Quantity of (2) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7687	Asset located in: Lake Worth, TX Quantity of Parts - Fits Chevrolet 3500 HD 6.0L S/N: Not Available C/W: Intake, Transfer Case, Wiring Harness	
7678	Quantity of Sheet Metal Parts S/N: Not Available C/W: assorted size & type Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION M BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEE	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
7679	Quantity of (2) Hydraulic Pumps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
7688	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7692	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7689	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7693	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7690	Crawler tractor drive motor teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7694	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7691	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7695	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7696	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7700	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7697	Quantity of Parts	7701	Quantity of (4) Teran 0860523 Bucket Pins
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		(Unused) - Fits Cat 311/314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available Asset located in: Lake Worth, TX
		7702	Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311/314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available Asset located in: Lake Worth, TX
7698	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7703	Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available Asset located in: Lake Worth, TX
		7704	Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available
7699	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7705	Asset located in: Lake Worth, TX Quantity of (4) Teran 1066878 Bucket Pins (Unused) - Fits Cat 315 S/N: Not Available C/W: 70mm X 508mm for Komatsu PC160 Front & Rear - 315 Linkage Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7706	Quantity of (2) Teran 2357636 Bucket Pins (Unused) - Fits Cat 349 S/N: Not Available C/W: 110mm X 705mm (Long total W/Flange) TB Linkage Front for Cat 345,345C,336DL, 352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349D2, 324D, 349DLVG, 336D2L, 349EL, 330DL, 345DL, 349FLXE, 336D2XE, 340FL, 340FLLRE, 336FLNXE, 336FL, 336DLN, 336ELN, 336D2LXE, 336FLN, 336D2, 349D2L, 336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH, 330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7707	Quantity of (2) Teran 2357642 Bucket Pins (Unused) - Fits Cat 349 S/N: Not Available C/W: 100mm X 695mm (Long total W/Flange) TB Linkage Rear for Cat 345,345C,336DL, 352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349D2, 324D, 349DLVG, 336D2L, 349EL, 330DL, 345DL, 349FLXE, 336D2XE, 340FL, 340FLLRE, 336FLNXE, 336FL, 336DLN, 336ELN, 336D2LXE, 336FLN, 336D2, 349D2L, 336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH, 330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F Usage: Not Available Asset located in: Lake Worth, TX	7711	Quantity of (4) Teran 7Y3549 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 80mm X 630mm D Linkage - Rear Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Teran 7Y3550 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 90mm X 650mm D Linkage - Front Usage: Not Available Asset located in: Lake Worth, TX Excavator compartment doors - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	
7708	Quantity of (2) Teran 2512552 Bucket Pins (Unused) - Fits Cat 336D S/N: Not Available C/W: 100mm X 640mm (Long total) DB LinkageFront W/Flange for Cat 336D,330D, 385CL, 336FLN, 340FL, 329DL, 324D, 325DL, 329EL, 336FLNXE, 324DL, 330FLN, 336EL, 330FL, 324ELN, 385COEM, 329D2L, 326D2, 326FL, 349ELVG, 336FLXE, 340D2L, 324DLN, 326D2L, 329DLN, 349EL, 325DLOEM, 336E, 385C, 336FL, 340DL, 325DLN, 329FL, 324EL, 329D2, 336ELH, 324E, 329E, 325D, 336EHVGOEM, 336EH, 336ELN, 329D, 326DL, 345CLVG, 336FLNH, 336EOEM, 329ELN, 326FLN, 336FLH, 340FLLRE, 340FUHD, 336FXE, 340F, 336F, 328DLCR Usage: Not Available Asset located in: Lake Worth, TX	7715	CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION BE PICKED UP WITHIN 14 DAYS OF AUCTION (JANUARY 3RD) OR WILL SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADON NOT BE ABLE TO ASSIST WITH LOW THESE Asset located in: Corsicana, TX 7715 Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION BE PICKED UP WITHIN 14 DAYS OF AUCTION (JANUARY 3RD) OR WILL SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADON NOT BE ABLE TO ASSIST WITH LOW THESE Asset located in: Corsicana, TX 7716 Quantity of (2) Pallets of Trencher of S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION USAGE: TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADON NOT BE ABLE TO ASSIST WITH LOW	CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7709	Quantity of (2) Teran 2512558 Bucket Pins (Unused) - Fits Cat 336D S/N: Not Available C/W: 90mm X 635mm (Long total W/Flange) DB Linkage Rear for Cat 336D,330D,324E, 336ELH, 325D, 329E, 336FL, 325DLOEM, 330FL, 329DLN, 336EL, 336EH, 336ELN, 336EHVGOEM, 330CL, 324DL, 340FLLRE, 325DL, 324EL, 336FLXE, 329ELN, 385COEM, 329EL, 324ELN, 329D2L, 326D2, 329DL, 326FL, 340D2L, 326D2L, 324DLN, 324D, 336FLN, 336E, 385C, 340DL, 385CL, 325DLN, 329FL, 340FL, 329D2, 336FLNXE, 330FLN, 329D, 326DL, 345CLVG, 336ELNH, 336EOEM, 326FLN, 336FLH, 340FUHD, 336FXE, 340F, 336F, 328DLCR Usage: Not Available Asset located in: Lake Worth, TX			SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7710	Quantity of (2) Teran 4I5015 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 80mm X 735mm F Linkage for CAT 330,330B, 345B, 345C, 350, Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7717	Quantity of (2) Pallets of engine bay doors S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7721	Quantity Of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7718	Quantity of (2) Pallets of Bucket pins S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7722	Quantity of Track Idlers - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7719	Quantity of (2) Pallets of Misc. parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7723	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7720	Quantity of (2) Pallets of Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7724	Quantity of (2) Excavator components box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7725	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7729	Shovel holders S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7726	Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7730	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7727	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7731	Quantity of (2) Pallets of Hand rails - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7728	Hood - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7732	Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7733	Quantity Of Hydraulic Parts S/N: Not Available C/W: Hydraulic Hoses, Hydraulic Tank, Hydraulic Pump EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7737	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7734	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	-7738	Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7735	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7739	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7736	Quantity of (2) Pallets of Crawler tractor parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7740	Quantity of (2) Pallets of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

	B : 1	I	B : 11
Lot #	Details	Lot #	Details
7741	Quantity of (3) Track idlers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7745	Track Idlers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7742	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7746	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7743	Quantity of (2) Pallets of Crawler tractor parts	7747	Dozer Sweeps - Fits Cat D6
,,,,,	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	,,,,,,	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7744	Bucket Cutting Edges S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7748	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7749	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7762	Quantity of Assorted Truck & Trailer Parts S/N: Not Available C/W: used tires, (3) Wheel barrows, air, fuel and hyd filters, banding machine, folding chairs, trash can, truck tractor seat, hyd hoses mud flaps, brake pads, mirrors, a/c compressors, cat injectors, Denso Protal 7200 2 part resin, Black Beauty Abrasive, and misc parts Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
7749A	Asset located in: Corsicana, TX Walking Beam - Fits Cat 740B S/N: Not Available		FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Usage: Not Available Asset located in : Lake Worth, TX	7763	Quantity of (3) Rims S/N: Not Available
7749B	Middle & Front Frame - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
7749C	Quantity of (2) Stair/Fender Assemblies - Fits Cat 740B		SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7764	Quantity of Equipment and Vehicle Lights S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7750	Quantity of Shredder Teeth (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7751	Quantity of (2) Pallets of Shredder Teeth S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (3) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7758	Quantity of (6) Wheels - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7759	Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7766	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7760	Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7761	Quantity of Exhaust Stacks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7767	Quantity of (2) 22.5 x 8.25 Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7768	Quantity of 2 5/16 in Ball Hitches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7774	Quantity of Radiators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7769	Quantity of Mack Front Grills S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7775	Quantity of (2) 16 x 24 Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7770	Quantity of (4) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7776	Quantity of Truck Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7771	Quantity of Truck Side Panels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7777	Quantity of (2) Pallets of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7772	Quantity of Truck Metal Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7778	Quantity of Truck Tactor Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7773	Quantity of 2 5/16 in Ball Hitches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7779	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
		7780	Quantity of (5) Portable Electrical Distribution Boxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7781	Power Distribution Unit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	7790	Quantity of (2) Stainless Steel Brewing Vats S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7791	Quantity of (2) Workshop Work Table
7782	Quantity of (8) Intertek Lighting Fixtures S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Midland, TX
	Asset located in: Lake Worth, TX	7792	Quantity of (2) Workshop Work Table
7783	Quantity of (2) Stantion 3 Ft x 12 Ft Truck Undercarriage Wash System S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in: Midland, TX
7784	Usage: Not Available Asset located in: Lake Worth, TX 101 in x 25 Ft Loading Ramp	7793	Quantity of (3) Workshop Work Table S/N: Not Available Usage: Not Available
//U -	S/N: Not Available		Asset located in: Midland, TX
	C/W: 45,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in : Lake Worth, TX	7794	Quantity of (3) 30 In x 42 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7784A	X-STAR 40 ft x 100 in Bridge (Unused)	7705	Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 14,000 lb. Usage: Not Available Asset located in : Lake Worth, TX	7795	Quantity of (3) 30 In x 42 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7785	101 in x 25 ft Bridge Platform Bridge		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in : Lake Worth, TX	7796	Quantity of (3) 31 In x 72 In Metal Shop Tables S/N: Not Available C/W: Wilton Vise; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7786	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX	7797	Quantity of (2) Metal Tables S/N: Not Available C/W: (1) 20.5 in x 60 in, (1) 30 in x 72 in; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7787	101 in x 25 ft Bridge Platform Bridge	7700	Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in : Lake Worth, TX	7798	Quantity of (5) Shop Supplies S/N: Not Available C/W: Engine Hoist, Shop Fan, (2) Dollies, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7788	101 in x 25 ft Bridge Platform Bridge - Fits xstar S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX	7799	Quantity of (2) Hydraulic Hose Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7789	101"x40' 14k Rated Bridge (Unused) S/N: Not Available C/W: 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7800	Quantity of (200) 2024 Suihe LCSS-200 Corrugated Structural Steel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7808	31.5 In Rubber Belt S/N: Not Available C/W: Blue Rack; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
		7809	2020 Weg W21 Electric Motor S/N: 1053815288 C/W: 315 KW, 3 Phase, 467 Amp ; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available
7801	Quantity of (200) 2024 Suihe LCSS-200 Corrugated Structural Steel (Unused)		Notes: . Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7810	Blue Diamond 1 1/4 In Sch 40 HDPE Conduit S/N: Not Available C/W: One Spool Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7811	Quantity of (3) Pallets of Shop Fans S/N: Not Available C/W: (4) 42 in, (11) 24 in, (1) Air Mover; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
7802	Quantity of (4) 2024 4-Fuel.com PFFF- ARLHALTO Safety Cabinets (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: DIMENSIONS 78" H x 39" W x 17" D Usage: Not Available Asset located in : Lake Worth, TX	7813	Quantity of (3) Pallets of Shop Supplies S/N: Not Available C/W: (1) Pallet of Banders & Strapping, (1) Pallet of Shop Vacs & Mop Kits, (1) Table W
7803	Quantity of Contractor Supplies S/N: Not Available C/W: Floor Jacks, Sockets, Bit Sets, Bottle Jack, Trolley Jack, One Pallet; EQUIPMENT- FROM-US-AUTO-RECYCLING	7815	/Roadmags; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Quantity of (3) Pallets of S/N: Not Available Usage: Not Available
7804	Quantity of (3) Pallets of Rolling Service Carts S/N: Not Available		Notes: . Asset located in: Lake Worth, TX
	C/W: Uline, U.S. General, (11) Carts; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7817	Quantity of (5) Pallets of Parts & Tools S/N: Not Available C/W: Hose, Wire, Pumps, Bolt Bins/Racks; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
7805	Quantity of (7) Pallets of Tools & Parts S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: Hose, Assorted Parts, Electrical Supplies; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7818	Quantity of (5) Hand Trucks S/N: Not Available C/W: (4) Martins 1000 lb capacity, one pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7807	Royal Gourmet 8 Burner Propane Grill S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7820	Quantity of (2) 30 In x 96 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7830	Quantity of (4) 30 in x 96 in Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7822	Quantity of (3) Pallets of Belt Material	7831	Modular Cage System
	S/N: Not Available C/W: Assorted Size/Type; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: Two Pallets; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7823	Quantity of (2) Pallets of Tools	7832	Quantity of Bolt Bins
	S/N: Not Available C/W: Wrenches, Sockets, Drills, Impacts; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: Contents, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7824	Quantity of (16) 48 In x 48 In Wheeled Drain Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7833	Quantity of (7) Pallets of Misc S/N: Not Available C/W: Air Tanks, Tables, Power Strips, Cables, Misc EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7825	Quantity of (4) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:	7835	47.25 In Rubber Belt S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7826	Asset located in: Lake Worth, TX GenMega G6000 Series ATM S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .	7836	47 In x 47 In Platform Scale S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	_ 7838	Quantity of (3) Bundles of Cardboard Boxes
7827	300 Gallon Air Tank S/N: Not Available C/W: Ingersoll Rand PSG30 Separator System; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .		S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7839	Quantity of (4) Misc Supplies
7828	20 ton Air Press S/N: 193562011 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .		S/N: Not Available C/W: (1) Pallet of Assorted Tools/Jacks, (1) Pallet of Assorted Filters, (1) Pallet of Misc, (1) Pallet of Assorted Parts/Fittings; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
	Asset located in: Lake Worth, TX		Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7841	Quantity of (2) Pallets of Misc Supplies S/N: Not Available C/W: Rakes/Shovels, Chains; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes:	7849	Quantity of (5) Pallets of Assorted Filters S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7850	36 In x 44 In Steel Storage Cabinet
7842	Quantity of (8) Trash Cans S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: Contents; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7843	U. S. General 72 in 18-Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7853	Quantity of (13) Pallets of Fluid Recovery Bay Protective Screens S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7844	Quantity of (3) Pallets of Misc Supplies S/N: Not Available C/W: (1) Pallet of Assorted Wire, (1) Pallet of Assorted Office Supplies, (1) Pallet of Chairs; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .	7855	Quantity of (3) Pallets of Parts, Mats & Trays S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7856	Quantity of Tool Bins & Cabinet
7845	Quantity of (4) 30 In x 96 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: (1) 36 In x 24 In x 78 In Cabinet W /Contents, Rolling Pegboard, Bolt Bins; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7846	Quantity of (3) Hopper Extensions S/N: Not Available C/W: (2) 69 In, (1) 74 In; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7857	Quantity of (10) Wen Industries 6 x 3 Ft Fluid Drain Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7847	Quantity of (3) 4 Ft x 4 Ft Storage Boxes S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7858	Quantity of (2) Pallets of Warehouse Supplies S/N: Not Available C/W: Assorted Hose, Safety Supplies; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
7848	Quantity of (4) Metal Shop Tables S/N: Not Available C/W: (2) 30 In x 72 In, (1) 36 In x 72 In, vise, saw; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7860	Asset located in: Lake Worth, TX Modular Cage System S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7862	Gates GC32TSI Crimper Machine S/N: TSI0980E21 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7871	Quantity of Oils, Service Fluids S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
7863	JET JDP-15F 15" Drill Press S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7872	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (22) Wagner HPLV Paint Sprayer
7864	Superwrap Taping Machine S/N: Not Available C/W: To Fit Superwrap Taping machine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7873	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of Air Hose & Accessories
	Asset located in: Lahoma, OK		S/N: Not Available Usage: Not Available
7865	Binks Pneumatic Paint Pot S/N: 316637 C/W: Hose, Hood Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
		7874	Entry Steps S/N: Not Available C/W: 36 in W, 18 in H
7866	Carport Kit - 18 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
7867	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused)	1	NOT BE ABLE TO ASSIST WITH LOADING THESE
	S/N: Not Available Usage: Not Available		Asset located in: Lahoma, OK
7868	Asset located in: Lake Worth, TX Carport Kit - 24 ft W x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7875	Quantity of (3) Piusi 017945010 DEF Pump S/N: Not Available C/W: Fits 55 Gal Drum Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
7869	Carport Kit - 18 ft w x 25 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7870	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
7876	Wheeler 4160 Pipe Threading Tripod S/N: Not Available C/W: Tools. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7881	Centech Battery Charger S/N: Not Available C/W: Shop-Vac, Oil Pump, Oil, Fencing Supplies. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
7877	Napa, Carlyle 7915070B Engine Stand S/N: Not Available C/W: To Fit Carlyle 7915070B, Geared Rotation Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7882	Quantity of Contractor Supplies S/N: Not Available C/W: Vice, Extension Cords, Bolts, Pillow Block Bearings, Track Link for JOHN Deere 2106, Trailer Parts Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
7878	Napa, Carlyle 7916021A Engine Hoist S/N: Not Available C/W: To Fit Carlyle 7916021A Engine Hoist, With Spreader Bar Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	7883	Asset located in: Lahoma, OK Quantity of (3) Crates of PVC Fittings 4"-12" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of Power Washers and Generators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	
7879	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Napa, Carlyle 7917170A Transmission Jack S/N: Not Available C/W: To Fit Carlyle 7917170A Transmission Jack, 1 Ton Capacity Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	7885	Usage: Not Available Notes: ITEMS AT OFFSITE LOCA' BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WI SUBJECT TO 3RD PARTY STORA BUYER RESPONSIBLE FOR LOAD NOT BE ABLE TO ASSIST WITH L THESE	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
7000	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	
7880	Graco Line Lazer IV Walk Behind Paint Striper S/N: Not Available C/W: 2008 US EPA Label, Honda 163 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7886	Quantity of Pressure Washer and Concrete Saw S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7890	Quantity of (4) Airless paint sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Corsicana, TX		Asset located in: Corsicana, TX
7887	Quantity of Weed Eater, Tools, Sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7891	Quantity of Construction Suppiles S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7888	Misc. shop supplies	7892	Generator, plate compactor, water pump
7000	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7.052	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7000	Asset located in: Corsicana, TX	7000	Asset located in: Corsicana, TX
7889	Quantity of Generators and Water Pumps S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7893	mail box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7894	Quantity of (8) Torque Wrenches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7895	shop tools S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7899	Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7896	Quantity of Vibratory Plate Compactor, Generator, Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7900	Quantity of Shop Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7897	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	-7901	Misc Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7898	Quantity of Shop Tools S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	-7902	Misc. shop supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
7903	Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7909	FS400ASK oil skimmer S/N: A2968 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
		7910	misc firefighting accessories S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		7911	Miller Bobcat 225NT Stick Engine Driven Welder (Inoperable)	
7904	Quantity of Power Washers, Battery Charger, Air Compressor S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST		S/N: KJ029548 C/W: Onan 2 Cylinder Gasoline Eng Usage: 763 Hr Notes: INOPERABLE ITEM MUST E FROM YARD BY JANUARY 10TH A BE RELISTED; BUYER'S RESPONSII REMOVAL	S/N: KJ029548 C/W: Onan 2 Cylinder Gasoline Engine Usage: 763 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7912		
7905	7905 Quantity of Shop Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE			
		7913	Quantity of (7) Pneumatic Concrete Breakers S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	
7906	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	7914	Quantity of Napa Oil Filters (Unused) S/N: Not Available C/W: Assorted Size/Type Usage: Not Available Asset located in: Lake Worth, TX	
		7916	100 Ft Galvanized Chain S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	
		7917	Scotsman C05305A-1E Ice Machine S/N: 19051320014944 Usage: Not Available	
7907	Quantity of chlorine recovery boxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7918	Asset located in: Lake Worth, TX Ice-O-Matic CIM0430FA Commercial Ice maker w/ collection bin S/N: 23011280011235	
7908	SCBA packs S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7919	Comfortmaker NXA660GKA100 Air Conditioner S/N: E160802838 Usage: Not Available Asset located in: Lake Worth, TX	7926	Quantity of Metal Grating S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7921	Reelcraft Compressor Cart S/N: Not Available C/W: Hose Reel; EQUIPMENT-FROM-WATKINS- CONSTRUCTION		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7927	Quantity of Safety Air Masks S/N: Not Available C/W: Tank Holders, Regulators Usage: Not Available
7922	Quantity of Assorted Shop Tools and Supplies		Asset located in: Lake Worth, TX
	(Inoperable) S/N: Not Available C/W: (1) Craftsman Weed Eater, (2) Generators, (1) Pressure Washer, (5) Trash Pumps, Ladders, Bolt Bin with Contents, Pressure Washer and Air Hoses, Spill Kits,	7928	Suihe Mens/Womens Portable Restroom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Electrical Wire, Misc Shop Tools, Electrical Supplies and Misc Shop/Warehouse Equipment Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE	7929	Greatbear 2 Ton Magnetic Lifter & 5 Ton Scale (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	7930	Quantity of (4) Pallets of Chains and Clevises (Unused)
7923	Asset located in: McAlester, OK Haul Master 5-Ton Crane Hoist S/N: Not Available	-	S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	7931	Quantity of (9) Thermal Arc Suitcase Welders S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
		7932	Big Daddy Targets Large AR500 Shooting
7924	Asset located in: McAlester, OK Quantity of Assorted Shop Tools and Parts S/N: Not Available C/W: Hammer Wrenches, 1 in Torque Wrenches, Micro Tester, Valves, Filing Cabinet,	7932	Target (Unused) S/N: Not Available C/W: Bigfoot W/Fish Motif Usage: Not Available Asset located in: Lake Worth, TX
	Shop Fan, Heavy Duty Rack, Brake Bands, Pipe Benders, Caulking Guns, Misc Shop Tools Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Big Daddy Targets Large AR500 Shooting Target (Unused) S/N: Not Available C/W: T-Rex Motif Usage: Not Available Asset located in: Lake Worth, TX
	FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		Big Daddy Targets Small AR500 Shooting Target (Unused)
7925	Quantity of Bolts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		S/N: Not Available C/W: Birds & Raccoons Motif Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
7935	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available	7945	Steel Shooting Target (Unused) S/N: Not Available C/W: Bigfoot Motif Usage: Not Available Asset located in: Lake Worth, TX
7936	Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Raccoons Motif Usage: Not Available	7946	Steel Shooting Target (Unused) S/N: Not Available C/W: Gunfighter Motif Usage: Not Available Asset located in: Lake Worth, TX
7937	Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting Target (Unused)	7947	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
 7938	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting	7948	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
,,,,,	Target (Unused) S/N: Not Available C/W: Birds & Turkey Motif Usage: Not Available Asset located in: Lake Worth, TX	7949	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7939	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif	7950	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7940	Usage: Not Available Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting	7951	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX		Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available
7941	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX	7953	Asset located in: Lake Worth, TX Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7942	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX	7954	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7943	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available C/W: Coyote & Deer Motif Usage: Not Available Asset located in: Lake Worth, TX	7955	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7944	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available C/W: Hogs & Sheep Motif Usage: Not Available Asset located in: Lake Worth, TX	7956	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7957	Big Daddy Feeders Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7968	Big Daddy Fire Pits 24 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available
7958	Big Daddy Feeders Deer Feeder (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7969	Quantity of Sand Bags S/N: Not Available Usage: Not Available
7959	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7960	Big Daddy Feeders 500 LB Stand & Fill Solar		Asset located in: Lahoma, OK
	Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7970	Quantity of (2) Bundles of 40 Ft Angle Iron S/N: Not Available C/W: (1) 1 1/2 In, (1) 2 In Usage: Not Available
7961	Big Daddy Feeders 500 LB Stand & Fill Solar		Asset located in: Lake Worth, TX
	Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7971	Quantity of (5) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available
7962	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused)		C/W: One Stack Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7972	Quantity of (2) Bundles Of Channels 4 in x 5.4 A36/529-50 20 ft
7963	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7973	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available
7964	Big Daddy Targets Small AR500 Shooting Target (Unused)		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in : Lake Worth, TX	7974	Quantity of (1) Bundle of Cattle Fence Stay Lock 12.5-12.5 S/N: Not Available Usage: Not Available
7965	Big Daddy Fire Pits 30 Inch. Decorative Metal		Asset located in: Lake Worth, TX
	Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7975	Quantity of (2) Bundles Of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available
7966	Big Daddy Fire Pits 30 Inch. Decorative Metal		Asset located in: Lake Worth, TX
	Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7976	Manitowoc SY0324A Ice Machine S/N: 110558398 Usage: Not Available
7967	Big Daddy Fire Pits 24 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7977	Manitowoc QY0454A Ice Machine S/N: 040262489 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	7987	Hillman 15 Ton Rollers S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	REMOVAL Asset located in: Lake Worth, TX	7988	Quantity of (6) Pipe Racks
7978	Dust Collector S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Assorted Sizes Usage: Not Available Asset located in : Lake Worth, TX
7979	Park Indistries Fastback Electric Stone Polisher S/N: Not Available C/W: extensions Usage: Not Available Asset located in: Lake Worth, TX	7989	Quantity of Contractor Supplies S/N: Not Available C/W: Lockout Tags, Marking Paint, Measuring Wheel, Hitch Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST
7980	Supershear Hydraulic Catalytic Converter Cutter S/N: 1411 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	7000	·
7981	Supershear Hydraulic Catalytic Converter Cutter S/N: 1409 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7990	Quantity of (3) Fuel Cans & (1) Lifting Strap S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WIL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7982	Quantity of Conveyer Belts & Rollers S/N: Not Available C/W: (1) 10 In Belt, (1) 24 In Belt, (1) 47 In Vinyl, (3) 84 In Rollers; EQUIPMENT-FROM-US-		
	AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX	7991	Quantity of (4) Gas Monitors S/N: Not Available Usage: 5 Hr
7983	Quantity of HWI MC25 Plus Fireclay Based Cement S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7984	Quantity of (8) Reelcraft HD76100 Hose Reels S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7992	Quantity of (10) Pallets of Shelving Guardrails & Accessories S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7985	Quantity of (3) Donaldson Torit MM1200 Electric Mist Collectors S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7993	Quantity of (2) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7994	Quantity of (2) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	8004	Quantity of (6) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7995	Asset located in: Lake Worth, TX Quantity of (2) Dayton 170000 BTU Space	8005	Quantity (3) Commercial (Car Wash) Vacuum System
	Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available	2006	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	8006	Quantity of (5) Pallets of Generators & Pressure Washers
7996	Quantity of (2) Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase, (1) Koehring B150D, (1) Porta Heat 97 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac, Titan, North Star, Simpson, Ex-Cell, Mi-T-M, Power Ease Usage: Not Available Asset located in : Humble, TX
7997	Quantity of (2) Dayton 170000 BTU Space	8007	10 ft x 10 ft Canopy
	Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX	8007	S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
7998	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
			Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	8010	2017 Tennant T20 Ride-On Floor Sweeper S/N: T20-9225
7999	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available		C/W: 56 in Working Width, Water System, Rear Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 2,922 Hr
	C/W: Kerosene Fueled, Single Phase Usage: Not Available	8011	Asset located in: Lake Worth, TX 2016 Tennant T20 Ride-On Floor Sweeper
8000	Asset located in: Lake Worth, TX Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		S/N: T20-6540 C/W: 48 in Working Width, Water System, Rear Squeegee, PSI 4 Cylinder 2.0 L Dual Fuel Engine Usage: 1,348 Hr Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	8012	2015 Tennant T20 Ride-On Floor Sweeper
8001	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		S/N: T20-6442 C/W: 56 in Working Width, Water System, Rear Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 566 Hr Asset located in : Lake Worth, TX
8002		8013	2019 Tennant M17 Ride-On Electric Floor
8002	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Sweeper S/N: M17-11001 C/W: 52 in Working Width, Water System, Rear Squeegee, 36 Volt Operating System Usage: 4,574 Hr
8003	Quantity of (10) Storage Crates	L	Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8014	2019 Tennant T17 Ride-On Floor Sweeper S/N: T17-13185 C/W: 44 in Working Width, 36 Volt Operating System Usage: 2,013 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8015	2016 Tennant T17 Ride-On Electric Floor Sweeper S/N: T17-11025 C/W: 44 in Working Width, Water System, 36 Volt Operating System Usage: 2,098 Hr	8024	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8025	Quantity of (19) 2 7/8 In OD Pipe
8016	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available		S/N: Not Available C/W: 21 ft, one bundle Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	8026	Quantity of (19) 2-7/8 in OD Schedule 10 Steel
8017	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available		Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8027	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused)
8018	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle		S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8028	Quantity of (19) 2-7/8 in OD Schedule 10 Steel
8019	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available		Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8029	Quantity of (25) 19 ft 2 in x 2 3/4 in Square 12
8020	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle		Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8030	Quantity of (25) 2-3/4 in Square 12 Gauge
8021	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available	0030	Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8031	Quantity of (25) 2-3/4 in Square 12 Gauge
8022	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available		Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8032	Quantity of (25) 2-3/4 in Square 12 Gauge
8023	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8033	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8042	Quantity of (61) 21 ft x 1 5/8 in OD Schedule- 10 Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8034	Quantity of (25) 19 ft x 2 in x 2 3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8043	Quantity of (2) Water Pumps S/N: Not Available C/W: Diaphragm, (1) Wilden 2 In, (1) 2.5 In Water Pumps Usage: Not Available Asset located in: Lake Worth, TX
8035	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8044	Quantity of Safety Supplies S/N: Not Available C/W: (4) Fall Protection Harnesses Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (IANUARY 3RD) OR WILL BE
8036	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WI NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
8037	Quantity of (25) 20 ft x 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8045	Quantity of Safety Supplies S/N: Not Available C/W: Vests, Hard Hats, Safety Glasses, Latcl Kits Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
8038	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
8039	Asset located in: Lake Worth, TX Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8046	Quantity of Safety Supplies S/N: Not Available C/W: Assorted Truck and Safety supplies Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
8040	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK
	C/W: (1) Bundle Usage: Not Available Asset located in : Lake Worth, TX	8047	Quantity of Chain Construction Hoist S/N: Not Available Usage: Not Available
8041	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8048	Asset located in: Lake Worth, TX 60 in x 565 ft Rubber Conveyor Belt S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8049	42 in x 570 ft Rubber Conveyor Belt S/N: Not Available Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8050	Bridgestone 60 in x 525 ft Conveyor Belt S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8060	Sawmill (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8051 32 in Discharge Conveyor Belt - F Trencher S/N: Not Available C/W: EQUIPMENT-FROM-WATKII CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCA BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WI SUBJECT TO 3RD PARTY STORA	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	TION MUST OF THE ILL BE AGE FEES; DOUT. RB WILL	
	THESE Asset located in: Corsicana, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8054	Quantity of (2) 2020 Ludlum Radiation Detectors S/N: 348035 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - GEIGER COUNTER		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9062	· · · · · · · · · · · · · · · · · · ·
8055	Vortex Hydraulic Catalytic Converter Decanner S/N: Not Available C/W: 10 hp hydraulic power unit, 2014 P & J Dust Extraction LTD PJB175-4.8-8-1E2-1-JMC- 60 dust collector s/n 98468, work platform; EQUIPMENT-FROM-US-AUTO-RECYCLING	8062 8063	2020 Mcintyre 600 HD Metal Shear S/N: 765 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		3 2020 JET Electric Band Saw S/N: 081337 C/W: 1 Hp Electric, .75 blade, Milwaukee 40 in
8056	Quantity of (3) 2021 Vortex PFS Gas De- Pollution Systems S/N: 139/041 C/W: (2) Gas Tank Tower System Punch; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		work station; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8064	2023 MMLJ DB500 Mobile System Sand
8057	Quantity of (4) 2020 Vortex UHPC Fluid De- Pollution System Pump S/N: Not Available C/W: 3 Fluid Distraction, oil, coolant, washer fluid; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available		Blaster S/N: 1M9BU1828PH774174 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9890 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	8065	2019 Allegro Ambient Air Pump Sand Blaster S/N: 336581 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8066	Quantity of Assorted Steel Cable Cable S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8073	2008 Tempest PAL30 Electric Fan S/N: 6030820400225 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
		8074	Quantity of (3) 24 In Shop Fan S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
8067	Asset located in: Lahoma, OK Ouantity of (6) Ladder		Asset located in: Lake Worth, TX
0007	Quantity of (6) Ladder S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	8075	Quantity of (2) J & D Mfg VPRF36 36 in Fan S/N: 0621 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	D UP WITHIN 14 DAYS OF THE (JANUARY 3RD) OR WILL BE TO 3RD PARTY STORAGE FEES; ESPONSIBLE FOR LOADOUT. RB WILL BLE TO ASSIST WITH LOADING ated in: Corsicana, TX gheinrich ECR327 6000 lb Electric k 8076 Quantity of (4) Pallets of 24 ln x Racking S/N: Not Available C/W: 24 ln x 48 ln Wire Racks, 9 Crossarms; EQUIPMENT-FROM- RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, T)	S/N: Not Available C/W: 24 In x 48 In Wire Racks, 96 In Crossarms; EQUIPMENT-FROM-US-AUTO-
8068	2014 Jungheinrich ECR327 6000 lb Electric Pallet Jack S/N: 82800864		Usage: Not Available
	C/W: 6000 lb Capacity, 24 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8077	Quantity of Industrial Pallet Racking S/N: Not Available C/W: (10) Pallets of 42 In x 25 Ft Uprights, (7) Pallets of 96 In Crossarms, (2) Pallets of 144 In Crossarms, (54) Pallets of 43 In x 46 In Wire Racks; EQUIPMENT-FROM-US-AUTO-
8069	Jungheinrich EJE120 Electric Pallet Jack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	8078	Quantity of Uline 36 In x 72 In Shelving
8070	Toyota 8HBW23 4500 lb Electric Pallet Jack S/N: 8HBW2322023 C/W: 4500 lb Capacity, 24 V Usage: Not Available		S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	8079	Quantity of 2 3/8 In Pipe
8071	2012 Rico PWH-DD-300 Electric Pallet Jack S/N: R-14544 C/W: 30000 lb Capacity, 24 V, Battery Charger Usage: Not Available	S/N: Not Available C/W: One Bundle Usage: Not Available	C/W: One Bundle
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	8080	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle
8072	2008 Tempest PAL30 Electric Fan S/N: 6050820402234		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8081	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8082	Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available	8092	Quantity of 4X3X1/4 Angle Iron S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8083	Asset located in: Lake Worth, TX Quantity of 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8093	Quantity of 4X3X1/4 Angle Iron S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available Asset located in: Lake Worth, TX
3084	Quantity of (6) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available	8094	Quantity of (3) 1/4 in Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
3085	Asset located in: Lake Worth, TX Quantity of (6) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle	8095	Quantity of (5) 3/16 Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8086	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft	8096	Quantity of (4) Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
 3087	S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX Quantity of (9) 5X4X11 GA Rectangle Tube	8097	Quantity of (8) Diamond Plate Steel S/N: Not Available C/W: Assorted Size Usage: Not Available
	17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8098	Asset located in: Lake Worth, TX Quantity of (6) Diamond Plate Steel S/N: Not Available C/W: Assorted Size Usage: Not Available Asset located in: Lake Worth, TX
3088	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8099	Quantity of (3) Diamond Plate S/N: Not Available C/W: Assorted Size, One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8089	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8100 ——8101	Quantity of (2) 8GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
3090	Quantity of (6) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available		Quantity of (8) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8091	Asset located in: Lake Worth, TX Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8102	Quantity of (7) 10GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

		•		
Lot #	Details	Lot #	Details	
8103	Quantity of (7) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX Quantity of (6) 10 GA Steel Plate S/N: Not Available	8112	Quantity of (100) 2024 SUNTOP S2134C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	
8105	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle	8113	Asset located in: Lake Worth, TX Quantity of (100) 2024 SUNTOP S2134C 7 ft x	
	Usage: Not Available Asset located in: Lake Worth, TX	0110	35 in Corrugated PPGI Steel Panels (Unused) S/N: Not Available	
8106	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available	_	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
8106A	Asset located in: Lake Worth, TX Quantity of Corrugated Sheet Metal S/N: Not Available C/W: Assorted Length Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	8114	Quantity of (100) 2024 SUNTOP S3048	
8107	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
8108	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES (MAY NOT BE AN EXACT REPRES	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
8109	4 Ft x 6 Ft Tornado Shelter (Unused)		THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	8115	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels	
8110	38 ft x 40 ft Shipping Container Roof Cover Kit (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shipping Container Roof Cover Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SIFOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRETHE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOSES	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8111	38 ft x 40 ft Shipping Container Roof Cover Kit (Unused) S/N: Not Available C/W: Quantity of (2) Crates - Builds (1) Container Roof Cover Kit. Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8116	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	8122	Quantity of Concrete Mix S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	8123	Quantity of Mohawk -20 Sand S/N: Not Available
8117	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		C/W: (7) 80 lbs bags Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8128	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available
8118	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	8129	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8130	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available
8119	·	8131	Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8132	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8120	Quantity of Assorted Brackets S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8133	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8121	Quantity of Filters S/N: Not Available C/W: Assorted Size/Type, One Crate Usage: Not Available Asset located in: Lake Worth, TX	8134	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8135	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8140	Quantity of (26) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8136	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8141	Quantity of (23) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8137	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8142	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8138	Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8143	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8139	Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8144	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
		8145	2019 KwiKool KP05-21H Air Conditioner S/N: 1014321 Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8146	2019 KwiKool KPO5-21H Air Conditioner S/N: 1014318 Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8159	AXH 42VVF Air Cooler S/N: 149606 E Usage: Not Available Asset located in: Midland, TX
8147	Quantity of (3) Air Conditioner S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8160 8161	AXH 42VVF Air Cooler S/N: 149491E Usage: Not Available Asset located in: Midland, TX AXH 42VVF Air Cooler
8148	Quantity of (2) GE Window Air Conditioner S/N: Not Available C/W: 99 sqft, 230v, 17,600 BTU Usage: Not Available	8162	S/N: 149491 P Usage: Not Available Asset located in: Midland, TX AXH 42VVF Air Cooler
8149	Asset located in: Lake Worth, TX AXH 42VVF Air Cooler S/N: 149606G Usage: Not Available		S/N: 149606J Usage: Not Available Asset located in : Midland, TX
8150	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149491K	8163	AXH 42VVF Air Cooler S/N: 149491 J Usage: Not Available Asset located in: Midland, TX
8151	Usage: Not Available Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149491 D	8164	AXH 42VVF Air Cooler S/N: 149606 H Usage: Not Available Asset located in: Midland, TX
8152	Usage: Not Available Asset located in: Midland, TX AXH 42VVF Air Cooler	8165	AXH 42VVF Air Cooler S/N: 149491 I Usage: Not Available
	S/N: 149606 F Usage: Not Available Asset located in : Midland, TX	8166	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149491 G
8153	AXH 42VVF Air Cooler S/N: 149491 L Usage: Not Available	8167	Usage: Not Available Asset located in: Midland, TX AXH 42VVF Air Cooler
8154	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149491 Q Usage: Not Available		S/N: 149491 N Usage: Not Available Asset located in: Midland, TX
8155	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 119084 C	8168	AXH 42VVF Air Cooler S/N: 119084 A Usage: Not Available Asset located in: Midland, TX
8156	Usage: Not Available Asset located in: Midland, TX AXH 42VVF Air Cooler	8169	AXH 42VVF Air Cooler S/N: 149491 F Usage: Not Available
	S/N: 119084B Usage: Not Available Asset located in : Midland, TX	8170	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149491 M
8157	AXH 42VVF Air Cooler S/N: 1494910 Usage: Not Available	04.74	Usage: Not Available Asset located in: Midland, TX
8158	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149606I Usage: Not Available Asset located in: Midland, TX	8171	AXH 42VVF Air Cooler S/N: 149491 H Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
8172	AXH 36VVF Air Cooler S/N: 89463E Usage: Not Available Asset located in: Midland, TX	8185	2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1794 Usage: Not Available Notes: .
8173	AXH 36VVF Air Cooler		Asset located in: Lake Worth, TX
	S/N: 89463 C Usage: Not Available Asset located in : Midland, TX	8186	2018 Dri-Eaz DRITEC 4000l Dehumidifier S/N: 1797 Usage: Not Available
8174	AXH 36VVF Air Cooler S/N: 89463 D Usage: Not Available	8187	Notes: . Asset located in: Lake Worth, TX Quantity of (4) Heaters
8175	Asset located in: Midland, TX AXH 36VVF Air Cooler S/N: 89509A Usage: Not Available Asset located in: Midland, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
8176	AXH 36VVF Air Cooler S/N: 89509B Usage: Not Available Asset located in: Midland, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
8177	AXH 36VVF Air Cooler S/N: 89416E Usage: Not Available Asset located in: Midland, TX	8187A	Asset located in: Corsicana, TX Allmand MH1000 Maxi-Heat 1000000 BTU Space Heater S/N: 0039MXH3
8178	AXH 36VVF Air Cooler S/N: 89463 F Usage: Not Available Asset located in: Midland, TX		C/W: Furnace oil Fueled, Single Phase, 115 V Input, Isuzu 3 Cylinder Diesel Engine Usage: 3,316 Hr Asset located in: Lake Worth, TX
8179	AXH 36VVF Air Cooler S/N: 89416 C Usage: Not Available Asset located in: Midland, TX	8188	2018 Campo EB400D 400000 BTU Space Heater S/N: B400-17-9254 C/W: Diesel Fueled Usage: Not Available
8180	AXH 36VVF Air Cooler S/N: 89509 C Usage: Not Available	8189	Notes: . Asset located in: Lake Worth, TX 2018 Campo EB400D 400000 BTU Space
8181	Asset located in: Midland, TX AXH 36VVF Air Cooler S/N: 89463 B Usage: Not Available Asset located in: Midland, TX	8189	Heater S/N: B400-18-8975 C/W: Diesel Fueled, 120 V Input Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8182	AXH 36VVF Air Cooler S/N: 89463 A Usage: Not Available Asset located in: Midland, TX		Heat star HS3500DF 361439 BTU Space Heater S/N: 27901109 C/W: Kerosene Fueled, 120 V Input Usage: Not Available
8183	2015 Air Comman AC1600 Hydraulic Oil Cooler	8191	Asset located in: Lake Worth, TX
	S/N: AC29 Usage: 124 Hr Notes : . Asset located in : Lake Worth, TX		Mi-T-M 375000 BTU Space Heater S/N: Not Available C/W: Propane Fueled, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT
8184	2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1798 Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8192	Quantity of (4) Mr. Heater 60,000 BTU Forced Air Space Heater S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8202	2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8193	Quantity of (4) Mr. Heater 60000 BTU Space Heater S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8203	2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8194	Mr. Heater 30000 BTU Space Heater S/N: Not Available C/W: Propane Fueled, (3) Space Heaters, (9) Tanks, (1) Burner Wand. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	8204	Quantity of Human Touch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8205	2024 Landhonor LHR-MC766 Massage Chair Sofa (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8196	THESE Asset located in: Lahoma, OK Innovatech Terminator 2000El Electric Ride-On	8206	BarcaLounger (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Floor Scraper S/N: T200E302IB Usage: 1,733 Hr Asset located in: Lake Worth, TX	8207	Osaki 3D Prestige Massage Chair S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8197	Karcher Chariot 2 iVac 24 ATV Electric Ride-On Vacuum Cleaner (Unused) S/N: 10090690000894 Usage: Not Available Asset located in: Lake Worth, TX	8208	Osaki 3D Prestige Massage Chair S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8198	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240913 Usage: Not Available Asset located in: Lake Worth, TX	8209	Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8199	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240915 Usage: Not Available Asset located in: Lake Worth, TX	8210	Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8200	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240914 Usage: Not Available	8211	GE Front Load Washer & Dryer Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8201	Asset located in: Lake Worth, TX 2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240916 Usage: Not Available Asset located in: Lake Worth, TX	– 8212	Frigidaire Freezer S/N: AA15240684 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		8214	True 3-Door Commercial Refrigerator S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8215	Quantity of (3) Meat Slicers S/N: Not Available C/W: (2) Bizerba, (1) Hobart Usage: Not Available Asset located in: Lake Worth, TX Quantity of (7) Pallets of Landscape Sandstone Boulders S/N: Not Available C/W: assorted size, shape Usage: Not Available Asset located in: Lake Worth, TX	8224	Quantity of (3) Hand Held Pump Sprayers S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
8217	Quantity of (7) Pallets of Landscape Sandstone S/N: Not Available C/W: assorted size, shape Usage: Not Available Asset located in: Lake Worth, TX	8225	Quantity of Chainsaws S/N: Not Available C/W: String Trimmer, Accessories Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WILL BE
8218	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
8219	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Legend Walk Behind 20 in Garden Tiller S/N: Not Available C/W: Legend Force 212 cc Gasoline Engine Usage: Not Available	8226	Predator Power Auger S/N: 44FAPL24013877 C/W: 2024 US EPA Label, Predator 1 Cylinder 52 cc Gasoline Engine, (1) 8 in Auger, (1) 6 in Auger Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
8221	Asset located in: Lake Worth, TX Legend Walk Behind 20 in Garden Tiller S/N: Not Available		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK
8222	C/W: Legend Force 212 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX Quantity of (18) Rhino Rugged Landscaping Tools W/ Fiberglass Handles S/N: Not Available C/W: (3) # 12 Aluminum Scoop, (3) 16 in Drain	8227	Quantity of (4) Kubota Mower Decks S/N: Not Available C/W: (3) 60 in & (1) 72 in Mower Decks Usage: Not Available Asset located in: Lake Worth, TX Crary 75060 Lawn Vacuum S/N: 103825
	Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10 in Hoe, (3) Square Pt Shovel Usage: Not Available Asset located in: Lake Worth, TX		C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
Tools W/ Fiberglass Handles S/N: Not Available C/W: (3) # 12 Aluminum Scoop, (3)	S/N: Not Available C/W: (3) # 12 Aluminum Scoop, (3) 16 in Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10	8229	Craftsman Walk-Behind Leaf Vacuum S/N: 1H01NK10291 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	8230	Quantity of Rhino Rugged Landscaping Hand Tools S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8231	Cat Engine (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	8238	Pipe handler S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
8232	Quantity of Truck Parts S/N: Not Available C/W: Hubs, Fenders, One Pallet		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8239	Quantity of (3) Cat Weights S/N: Not Available
8233	72 in Forks S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
8234	Cat 48 in Q/C Wheel Loader Forks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
0005	Asset located in: Lake Worth, TX	8240	Grieve 333 Industrial Oven
8235	Quantity of (2) Dolly Bars S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available		S/N: 104626A1111 Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	8241	Grieve 3330 Electric Airless oven S/N: 114490A0315
8236	Pearl Abrasive 15 In Floor Preparation Disc S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX Quantity of Cat Final Drive Sprocket Segments - Fits Cat D6 S/N: Not Available C/W: To Fit Cat D6M, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL		C/W: To Fit Grieve 333 Electric Industrial Oven Grieve .33 hp 3 Phase Motor Usage: Not Available Asset located in: Midland, TX
		8242	2018 Bomag BMP8500 Trench Compactor S/N: 101720129533 C/W: 2018 US EPA Label, Kubota D1005 3 Cylinder 14.3 kW 1.0 L Diesel Engine, 32 in drums w/extensions, remote; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
8237			
		8243	Mobydick Kitflex 400C Wheel Washing System S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE	8244	Quantity of (2) Pallets of engine bay doors
	Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
8245	bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8254	2014 Sokkia 7383-40 w/ Grade Rod Laser Level S/N: 270612 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
		8255	Trimble EM410 Antenna Mount S/N: 2599J501CN Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	8256	Topcon GP-3
8246	JLG Man Basket S/N: 2017920 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Topcon GR-3 RTK GPS GNSS, SN#442- 0693, Topcon GR-3 RTK GPS GNSS, SN#442- 0485, Topcon FC-2600 Data Collector, SN#55802743 Usage: Not Available Asset located in : Lake Worth, TX
8246A	Hydraulic Scrap Metal Baler S/N: 1676784 C/W: 3 ph Usage: Not Available Asset located in: Oklahoma City, OK	8257	Topcon Hiper Lite RTK S/N: Not Available C/W: Topcon Hiper Lite RTK GPS, SN#263- 1167, Topcon Hiper Lite RTK GPS, SN#296- 0181, Topcon FC-120 Data Collector, SN#A30665
8247	2024 Machpro MP-MS100 Sofa (Unused) S/N: SLP2707080862 Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8258	Topcon GR-5 RTK
8248	2024 Machpro MP-MS100 Sofa (Unused) S/N: SLP2707080861 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Topcon GR-5 RTK GPS GNSS Rover, SN#800-10190 Topcon FC-2600 Data Collector, Magnet Field, SN#556-06832 Usage: Not Available Asset located in: Lake Worth, TX
8251	Quantity of Fire Extinguisher S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	8259	Quantity of Laser Equipment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8260 2024 Suihe A40 (Unused) S/N: Not Availa C/W: THE PROE FOR ILLUSTRAT MAY NOT BE AI THE ACTUAL PI Usage: Not Ava Notes: THE PROE FOR ILLUSTRAT MAY NOT BE AI THE ACTUAL PI Asset located in 8261 2024 Landhono Anvil (Unused) S/N: Not Availa	2024 Suihe A400 400 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8252	Quantity of (15) Assorted Sized Fire Extinguisher S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available
8253	2024 Topcon RL-H5B Rotary Laser Level		Asset located in: Lake Worth, TX
	(Unused) S/N: 1B019363 C/W: Receiver Usage: Not Available Asset located in: Lake Worth, TX	8262	2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8263	2024 Suihe A200 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8270	Quantity of (3) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 28 In x 50 In Metal Table
8264	2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available	8272	S/N: Not Available C/W: Vise Usage: Not Available Asset located in: Lake Worth, TX Lifting Strap, Sockets
8265	Asset located in: Lake Worth, TX 2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8272	S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
8266	Quantity of Floor Jacks & Parts S/N: Not Available C/W: (4) Floor Jacks, Receiver Hitch, Scissor		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK
	Jack, Lights, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Quantity of Electric Grease Guns S/N: Not Available C/W: Tools Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST
8268	Quantity of (4) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		E
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8274	Quantity of Tools S/N: Not Available C/W: 1 in Socket Set & Misc. Tools Usage: 5 Hr
8269	Quantity of (4) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK	8275	Quantity of Shovels, Post Hole Diggers. S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
8276	Quantity of (16) 2024 Agriquip GLWH16 Auto Darkening Welding Helmets (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8296	Quantity of (2) Battery Charger S/N: Not Available C/W: Die Hard DH0168, DSR Pro Series DSR121; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8297	Quantity of (4) Midtronics GR8 Commercial Battery Charger
8278	48" Frontier Job Box W/ 25 PC Makita Power Tool Set S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8298	2024 Suihe WW 20000 lb Winch (Unused)
8279	Wokin 158 PC Standard & Metric Tool Set W/ 42" Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
8280	Wokin/Valley 8 PC Hydraulic Jack & Jack Stand Kit W/ 42" Job Site Box S/N: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Usage: Not Available Asset located in: Lake Worth, TX	8299	Asset located in: Lake Worth, TX 2024 Landhonor LHR-EW20000 20000 lb
8281	2008 Sokkia C22 Builders Level W/Tripod S/N: 004062 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8299	Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
8282	Wood Tuff Tow 48" Job Site Box W/ 7 PC Cub		Asset located in: Lake Worth, TX
	Cadet Tool Kit S/N: Not Available C/W: HT24E- Hedge Trimmer - CS160E- Cordless Chainsaw - LB600E- Leaf Blower - ST15E- String Trimmer - Battery - Charger Usage: Not Available Asset located in: Lake Worth, TX	8300	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8289	Quantity of (5) 2024 Landhonor LDH-FPR36 36		Usage: Not Available Asset located in: Lake Worth, TX
	in Fire Pit Ring S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8301	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available
8290	2024 Landhonor LHR-AIW1 Pneumatic 1 in Impact Wrench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8294	Quantity of (3) Battery Charger S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8302	2024 Landhonor LHR-EW20000 20000 lb Winch (Unused) S/N: Not Available Usage: Not Available
8295	GNB GTC12-600T1 Battery Charger S/N: Not Available C/W: Skid Mounted Basket Usage: Not Available Asset located in: Lake Worth, TX	8303	Asset located in: Lake Worth, TX Wood WW15000V12 15000 lb Winch S/N: Not Available C/W: 4.5hp, Remote Control Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8305	Quantity of (8) 3 in OD Fire Water Hose S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8311	Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
8306	Quantity of Bottle Cart & Torches		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	S/N: Not Available C/W: Gauges ; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8312	Asset located in: Lake Worth, TX Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available	
8307	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	8313	C/W: THE PRODUCT IMAGE FOR ILLUSTRATION PURPO MAY NOT BE AN EXACT REI THE ACTUAL PRODUCT Usage: Not Available	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available	
8308	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
8309	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8314	Quantity of 2024 Landhonor LHR-RC5400 5400 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-RC5400 5400	
8310	Asset located in: Lake Worth, TX Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		S/N: N C/W: (Usage	Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8316	Quantity of (48) 2024 SKLP SK003 Ratchet Straps (Unused) S/N: B31577 C/W: (32) 2 in x 27 ft, (16) 1.5 in x 27 ft Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8317	Quantity of 2024 Landhonor LHR-RF24 1.5 In x 27 Ft Ratchet Straps (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8328	Sunex Transmission Jack S/N: Not Available C/W: Under Hoist Stands, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
8318	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION	8329	Quantity of (3) Boxes of Wokin 3 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8330	Quantity of (3) Boxes of 10 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8319	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUST RETURN	8331	Semi-Trailer Landing Gear S/N: Not Available C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available Asset located in: Lake Worth, TX
	PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8332	Semi-Trailer Landing Gear S/N: Not Available C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available Asset located in: Lake Worth, TX
8320	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8333	Electric Submersible Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
8321	Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor LHR-LB8850 Leaf Blower (Unused) S/N: Not Available C/W: 1 Cylinder 3.1 kW 75.6 cc Gasoline Engine Usage: Not Available	8334	Armor Titanium Series 64 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digita Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available
8322	Asset located in: Lake Worth, TX Little Wonder Optimax Walk-Behind Leaf Blower S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	8335	Asset located in: Lake Worth, TX Armor Titanium Series 40 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts
8324	Quantity of (3) Arcan Farm Jack S/N: Not Available Usage: Not Available	Usage: Not Available Asset located in: Lake Worth, TX 8336 2024 Agriquip GLGS40 40 Gun S S/N: Not Available C/W: THE PRODUCT IMAGES SH FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT Usage: Not Available	Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX		
8325	Quantity of (5) 2024 Powertek 20 Ton Pneumatic Bottle Jack (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT

Lot #	Details	Lot #	Details	
8337	Armor Titanium Series 24 Gun Safe S/N: Not Available C/W: 24 in Wide x 56 in High x 24 in Deep, 1400 Degree Fire Rating, Digital Combination key pad, 5 live action locking bolts Usage: Not Available Asset located in: Lake Worth, TX Armor Titanium Series 24 Gun Safe (Unused)	8345	8345	2019 Morbark Boxer X7 Tow-Behind Wood Chipper S/N: 4S8SZ1010KW006193 C/W: 2018 US EPA Label, CARB Compliant, Kohler ech740 2 Cylinder 747 cc Gasoline Engine, 36 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Ball Hitch Usage: 110 Hr
0000	S/N: Not Available		Asset located in: Lake Worth, TX	
	C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available	8346	2024 Landhonor LHR-PWC6 Wood Chipper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available	
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
8339	Armor Titanium Series 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX	8347	2024 LANM LAM750 Electric Remote Control Crawler Lawn Mower (Unused) S/N: LAM750240707 C/W: 22 in Mower Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
8340	2024 Agriquip GLGS14 14 Gun Safe (Unused)	0040		
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8348	2024 Landhero LHR-HT550 Remote Control Lawn Mower (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	8349	2024 Landhero LHR-HT550 REMOTE	
8341	2024 Raccoon RC-G1.5 Electric Bicycle (Unused) S/N: Not Available Usage: Not Available	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Usage: Not Available	
	Asset located in: Lake Worth, TX	8350	2024 Machpro MP-M500 Tracked Lawn Mower	
8342	2024 Raccoon RC-G1.5 Electric Bicycle (Unused) S/N: RC2405310 Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: MP20240711180 C/W: Remote Control Usage: Not Available Asset located in: Lake Worth, TX	
8343	2024 Landhonor LHR-GLS34 Gasoline Tow Behind Log Splitter (Unused) S/N: Not Available C/W: Ball Hitch, Kohler 7 hp Engine Usage: Not Available Asset located in: Lake Worth, TX	8351	2024 Machpro MP-M500 Tracked Lawn Mower (Unused) S/N: MP20240711182 C/W: Remote Control Usage: Not Available Asset located in: Lake Worth, TX	
8344	2024 Landhonor LS-13-36D Skid Steer Log Splitter (Unused) S/N: Not Available C/W: Skid Steer Carpet Pole, One Crate Usage: Not Available Asset located in: Lake Worth, TX	8353	Hustler Dash XD 34 Zero-Turn Lawn Mower S/N: 23100864 C/W: Hydrostatic Drive, 2023 US EPA Label, 11x4.00-5 Front Tires, 18x6.5/8 Rear Tires, Hustler 34 in Mower Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8355	2018 Kubota Z725KH Zero-Turn Lawn Mower S/N: 23133 C/W: Hydrostatic Drive, 2017 US EPA Label, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 180 Hr Asset located in: Lake Worth, TX	8381	2012 Polaris 800 EFI Crew Cab 6 Passenger Utility Vehicle S/N: 4XAWH76AXDE646836 C/W: Canopy, 6 Passenger, Manual Dump Bed, Diesel Engine, Gas Engine Usage: Not Available
		_	Asset located in: Lake Worth, TX
8356	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX	8381A	Utility Vehicle S/N: 1B9AC2110PA284014 C/W: Canopy, 4 Passenger, Windshield, 4 Cylinder Gasoline Engine Usage: 2,637 Mi Asset located in: Lake Worth, TX
8357	Quantity of (6) Yard Force Walk-Behind Lawn	8382	2012 Polaris Ranger XP Utility Vehicle
	Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX		S/N: 4XATH7EA1CE289808 C/W: Canopy, 2 Passenger, Windshield, Hitch Receiver, Manual Dump Bed Usage: 1,799 Hr Asset located in: Lake Worth, TX
8358	White Outdoor 17BK2ACK090 Zero-Turn Lawn Mower S/N: 1B208G90011 C/W: Hydrostatic Drive, 13x5.00x6 Front Tires, 20x10.00x8 Rear Tires, 54 in Mower Usage: 631 Hr	8383	Bobcat UV34XL Utility Vehicle S/N: B53721117 C/W: Canopy, 4 Passenger, Windshield, Manual Dump Bed, Polaris Gasoline Engine Usage: 1,521 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8384	2021 John Deere Gator XUV 855M Utility
8359	2016 Kubota Z725KH Zero-Turn Lawn Mower S/N: 21339 C/W: Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 2,329 Hr Asset located in: Lake Worth, TX	0004	Vehicle S/N: 1M0855MBPMM040235 C/W: Canopy, 4 Passenger, Windshield, Manual Dump Bed, 2021 US EPA Label, John Deere 3tnv70 Gasoline Engine Usage: 3,905 Hr
8360	Quantity of (3) Yard Force 22 in Walk Behind	—	Asset located in: Lake Worth, TX
	String Trimmer S/N: Not Available C/W: Briggs & Stratton Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	8387	2020 Club Car Carryall 1700D Utility Vehicle S/N: SD2011054694 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 1,055 Hr
8362	Quantity of (3) Yard Force 9 in Edger S/N: Not Available C/W: 79 cc Gasoline Engine		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	Usage: Not Available	8388	2019 Club Car Carryall 1700G Utility Vehicle
	Asset located in: Lake Worth, TX		S/N: SC1919-968737
8367	2021 Polaris 500 Utility Vehicle S/N: 3NSRM2504ME534422 C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 500 cc Gasoline Engine Usage: Not Available		C/W: Canopy, 4 Passenger, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 936 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8391	2019 Club Car Carryall 1700D Utility Vehicle
8371	2018 Kubota RTVX1140WH Utility Vehicle S/N: A5KD2GDBTJG027894 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,192 Hr		S/N: SD1919970463 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota 3 Cylinder Diesel Engine Usage: 967 Hr
	Asset located in: Lake Worth, TX		Notes : ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO ;
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8393	2019 Club Car Carryall 1700D Utility Vehicle S/N: SD1919969371 C/W: Open Operator Station, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 1,237 Hr	8406	2017 Taylor Dunn SS5-36 Utility Cart S/N: 205453 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 177 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8407	Tao Motor Boulder 4x2 ATV (Unused)
8394	2019 Club Car Carryall 1700D Utility Vehicle S/N: SD1920-970849 C/W: Canopy, 4 Passenger, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 1,305 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		S/N: L9NACFB30N1604821 C/W: 2022 US EPA Label, Tao 107 cc Gasoline Engine Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY Asset located in: Lake Worth, TX
8396	2017 Club Car Carryall 1700 Utility Vehicle S/N: A5CUAA4FTHA840664 C/W: Canopy, 4 Passenger, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,294 Hr Asset located in: Lake Worth, TX	8408	Tao Motor Boulder 4x2 ATV (Unused) S/N: L9NACFB34N1402404 C/W: Electric Start, 2022 US EPA Label, Tao 107 cc Gasoline Engine Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY Asset located in: Lake Worth, TX
8397	2017 Club Car Carryall 1700 Utility Vehicle S/N: A5CUAA4FTHA841104 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,674 Hr Asset located in: Lake Worth, TX	8409	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0112975 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit Usage: 9 Hr Asset located in: Lake Worth, TX
8400	2019 Club Car Carryall 1500G Utility Vehicle S/N: RC1918967773 C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 912 Hr	8410	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140193 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit Usage: 12 Hr Asset located in: Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8411	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140519 C/W: Battery Charger, 4 Passenger, Canopy,
8403	2007 John Deere TX Turf Gator Utility Vehicle S/N: Not Available		Windshield, Lift Kit Usage: 7 Hr Asset located in : Lake Worth, TX
0.00	C/W: Open Operator Station, 2 Passenger, Hitch Receiver, Manual Dump Bed Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	8412	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409051 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8404	1998 E-Z-Go 898445 Club Car Utility Vehicle S/N: C98004700 C/W: Canopy, 2 Passenger, Windshield, Rear Screen, 3 Cylinder Diesel Engine, Diesel Engine Usage: 2,184 Hr Asset located in: Lake Worth, TX	8413	2024 HUNTER PRO GFE-4.0 Electric Golf Cart S/N: 202409097 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8405	2017 Taylor Dunn Bigfoot 48V N/M Utility Cart S/N: 205477 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 560 Hr Asset located in: Lake Worth, TX	8414	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409072 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8415	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409071 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8424	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409115 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8416	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409096 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8425	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409114 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8417	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409061 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8426	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 3702020241243 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8418	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409062 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8427	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 3702020241242 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8419	2024 HUNTER PRO GFE-4.0 Electric Golf Cart	8428	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart
	(Unused) S/N: 202409098 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available		(Unused) S/N: 37020241100 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8420	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409100 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8429	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409116 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8421	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409099 C/W: 4 Passenger, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8430	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused) S/N: 37020241241 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8422	2024 HUNTER PRO GFX-4.0 Electric Golf Cart (Unused) S/N: 202409069 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8431	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused) S/N: 37020241240 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8423	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 37020241084 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8433	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8CPC001632 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield Usage: Not Available	8437	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8EPC001671 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8434	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001670 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8438	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8TPC001673 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8435	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)	8439	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)
	S/N: A07DE5W8HPC001636 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8EPC001606 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
0.406	Asset located in: Lake Worth, TX	0.4.40	Asset located in: Lake Worth, TX
8436	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8KPC001613 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8440	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8VPC001633 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8441	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001605 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8445	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8PPC001593 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8442	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8LPC001604 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE	8446	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8JPC001662 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE
	CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8443	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused)	8447	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)
	S/N: A07DE5W8TPC001656 C/W: 48 Volt Battery Charger, 4 Passenger, 5 kW Engine Usage: Not Available		S/N: A07DE5W8TPC001687 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX	0.440	Asset located in: Lake Worth, TX
8444	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8HPC001653 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8448	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8CPC001646 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8449	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8JPC001600 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine	8453	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8VPC001602 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine
	Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
-	Asset located in: Lake Worth, TX	-	Asset located in: Lake Worth, TX
8450	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8JPC001676 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN	8454	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8APC001679 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN
	WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
8451	Asset located in: Lake Worth, TX 2023 Kandi KS4PSLR-W Electric Golf Cart	8455	Asset located in: Lake Worth, TX 2023 Kandi KS4PSLR-W Electric Golf Cart
0431	(Unused)	0433	(Unused)
	S/N: A07DE5W8KPC001689 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8PPC001688 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8452	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8CPC001677 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8456	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8PPC001691 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8457	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8TPC001690 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED	S	45 ft High Cube Storage Container S/N: HDHM94691473 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8464	2024 40 ft High Cube Multi-Door Storage Container S/N: CICU6930839 C/W: One-Way
8458	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: A07DE5W8VPC001678 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING	8465	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0174629 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8466	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0174613
8459	Electric Golf Cart S/N: JW9-200800 C/W: Battery Charger, 2 Passenger, Canopy, Windshield, Utility Body Usage: Not Available Asset located in: Lake Worth, TX		C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8460	2024 RCcar Electric 3 Person Scooter S/N: SLP2413080202 Usage: Not Available Asset located in: Lake Worth, TX	8467	Container S/N: LYPU0173793
8461	Quantity of (4) Synergy DP209 285/75R24.5 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX		C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8462	53 ft High Cube Storage Container S/N: GTJU968067 Usage: Not Available Asset located in: Lake Worth, TX	8468	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU0101019 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8469	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU0101003 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8478	2024 40 ft Multi-Door Storage Container S/N: LYPU0173772 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8470	2024 40 ft Multi-Door Storage Container S/N: XHCU5647588 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8479 	2024 40 ft Multi-Door Storage Container S/N: LYPU0173807 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8471	2024 40 ft High Cube Multi-Door Storage Container		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: JPCU0101024 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8480	2024 40 ft Multi-Door Storage Container S/N: XHCU5647593 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8472	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0026300 Usage: Not Available Asset located in: Lake Worth, TX	8481 - 8482	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0173788 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
8473	2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0026260 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage
8474	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0025562 Usage: Not Available		Container S/N: MMPU1045114 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8475	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212025 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8483	2024 40 ft Multi-Door Storage Container S/N: LYGU0185801 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8476	2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212046 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8484	2024 40 ft High Cube Storage Container S/N: DFCU1640658 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8477	40 ft High Cube Multi-Door Storage Container S/N: HHXU3309737 Usage: Not Available Asset located in: Lake Worth, TX	8485	2024 40 ft High Cube Storage Container S/N: DFCU1640663 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8486	2024 40 ft High Cube Multi-Door Storage Container S/N: LYGU4159586 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8497	20 ft Standard Multi-Door Storage Container S/N: SPRU2808250 Usage: Not Available Asset located in: Humble, TX
		8498	20 ft Standard Multi-Door Storage Container
8487	2024 40 ft High Cube Multi-Door Storage Container		S/N: SPRU2807871 Usage: Not Available Asset located in : Humble, TX
	S/N: LYGU4159436 C/W: One-Way Usage: Not Available Asset located in : Lake Worth, TX	8499	20 ft Standard Multi-Door Storage Container S/N: SPRU2808266 Usage: Not Available Asset located in: Humble, TX
8488	2024 40 ft High Cube Multi-Door Storage Container S/N: ZXJU0152117 C/W: One-Way Usage: Not Available	8500	2024 SHANG 20 ft One-Way Storage Container S/N: MCCU1088835 Usage: Not Available Asset located in: Lake Worth, TX
8489	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: ZXJU0151928	8501	2024 20 ft Storage Container S/N: HYJU1077876 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: One-Way Usage: Not Available Asset located in : Lake Worth, TX	8502	2024 20 ft Storage Container S/N: VSLU3245246 Usage: Not Available
8490	2024 40 ft High Cube Storage Container S/N: DFCU1640679 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8503	Asset located in: Lake Worth, TX 2024 20 ft Standard Storage Container S/N: MCCU1088917 Usage: Not Available
8491	2024 40 ft High Cube Storage Container S/N: SPRU9037160 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8504	Asset located in: Lake Worth, TX 2024 20 ft Standard Double-Ended Storage Container S/N: SPRU2611786 Usage: Not Available
8492	20 ft Standard Open-Sided Storage Container S/N: SPRU2813703 Usage: Not Available Asset located in: Lake Worth, TX	8505	Asset located in: Lake Worth, TX 20 ft Standard Storage Container S/N: SPRU3086580 Usage: Not Available Asset located in: Lake Worth, TX
8493	20 ft Standard Open-Sided Storage Container S/N: SPRU2813880 Usage: Not Available Asset located in: Lake Worth, TX	8506	20 ft Standard Storage Container S/N: SPRU3086189 Usage: Not Available Asset located in: Lake Worth, TX
8494	2024 20 ft Multi-Door Storage Container S/N: XHCU2623751 Usage: Not Available Asset located in: Lake Worth, TX	8507	2024 20 ft Standard Storage Container S/N: SPRI3098791 Usage: Not Available Asset located in: Lake Worth, TX
8495	2024 20 ft Multi-Door Storage Container S/N: XHCU2626766 Usage: Not Available Asset located in: Lake Worth, TX	8508	20 ft Standard Multi-Door Storage Container S/N: SPRU280883 Usage: Not Available
8496	20 ft Standard Multi-Door Storage Container S/N: SPRU2807634 Usage: Not Available Asset located in: Humble, TX	8509	Asset located in: Humble, TX 2024 20 ft Standard Storage Container S/N: SPRU3078970 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8510	20 ft Standard Multi-Door Storage Container S/N: SPRU2812287 Usage: Not Available Asset located in: Humble, TX	8522	2024 12 ft Storage Container S/N: GMPU9027419 C/W: Man Door, Window Usage: Not Available
8511	2024 20 ft Standard Double-Ended Storage Container S/N: SPRU2611575 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8512	20 ft Standard Multi-Door Storage Container S/N: SPRU2810812 Usage: Not Available Asset located in: Humble, TX	– 8523	2024 12 ft Storage Container S/N: GMPU9027430 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
8513	20 ft Standard Multi-Door Storage Container S/N: SPRU2810833 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8514	Asset located in: Humble, TX 20 ft Standard Storage Container S/N: SPRU3063223 Usage: Not Available Asset located in: Lake Worth, TX	8524	2024 9 ft Storage Container S/N: GMPU9002935 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
8515	20 ft Standard Storage Container S/N: SPRU3064493 Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8516	20 ft Standard Storage Container S/N: APZU3578440 Usage: Not Available Asset located in: Lake Worth, TX	8525 8526	2024 9 ft Storage Container S/N: GMPU9026027 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
8517	20 ft Standard Storage Container S/N: ECMU1513031 Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8518	2006 20 ft Storage Container S/N: HDMU2493989 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2024 9 ft Storage Container S/N: GMPU9026285 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8519	20 ft Standard Storage Container	1	Asset located in: Lake Worth, TX
	S/N: AXIU2245734 C/W: Man Door, AC Unit Usage: Not Available Asset located in : Lake Worth, TX	8527	2024 8 ft Storage Container S/N: GMPU9027893 C/W: Man Door, Window Usage: Not Available
8520	20 ft Storage Container S/N: TCKU2807327 Usage: Not Available Asset located in: Humble, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8521	20 ft Standard Storage Container S/N: CBHU3069110 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8528	2024 8 ft Storage Container S/N: GMPU9026520 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	8535	40 ft High Cube Storage Container S/N: NYKU7937152 C/W: 2007 Carrier Transicold Reefer Unit Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8536	Quantity of (6) 2022 Box Gang 22 ft 30 YD Roll-Off Container S/N: Not Available
8529	2022 Suihe Storage Container S/N: LYPU00109 Usage: Not Available Notes:		C/W: 22 ft Long x 8 ft Wide x 5 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8530	Asset located in: Lake Worth, TX 7 ft Storage Container S/N: LYP710660 C/W: Window Usage: Not Available Asset located in: Lake Worth, TX	8537	Quantity of (4) 22 ft 30 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 5 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
8531	2024 7 ft Storage Container S/N: GMPU9027851 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8538	Asset located in: Lake Worth, TX Quantity of (2) 2022 Box Gang 22 ft 40 YD Roll- Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 6 ft 9 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
8532	2004 40 ft Storage Container S/N: 749036 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Huntsville, TX	8539	Quantity of (2) 22 ft 20 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 4 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8533	2002 40 ft Storage Container S/N: KKFU72268889 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	8540	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 5 in Wide x 4 ft 11 in High Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8541	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 4 in Wide x 5 ft 8 in High Usage: Not Available Asset located in: Lake Worth, TX
8534	Asset located in: Huntsville, TX 2002 Storage Container S/N: XAH318284 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Huntsville, TX	8542	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 6 in Wide x 5 ft 8 in High Usage: Not Available Asset located in: Lake Worth, TX
		8543	18 ft Roll-Off Container (Unused) S/N: C202461 C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8544	18 ft Roll-Off Container (Unused) S/N: C202462 C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available Asset located in: Lake Worth, TX	8554	2011 Dodge Caravan SE Minivan S/N: 2D4RN5DG0BR682712 C/W: V6 3.6 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 169,386 Mi
8545	17 ft Roll-Off Container (Unused) S/N: Not Available C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available Asset located in: Lake Worth, TX	9555	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX 2021 Nissan Sentra Automobile
8546	17 ft Roll-Off Container (Unused) S/N: C202462 C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available Asset located in: Lake Worth, TX	- 8555	S/N: 3N1AB8BV5MY267560 C/W: 4 cyl 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 54,098 Mi
8547	Quantity of (2) Waste Container S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX
8548	Asset located in: Lake Worth, TX 1956 Chevrolet Bel Air Classic Car S/N: VC56S103217 C/W: V8 5.7 L Gasoline Engine, Automatic Transmission, Air Conditioner Usage: 9,673 Mi	8556	2019 Ford Fusion Automobile S/N: 3FA6P0HD8KR223201 C/W: 4 cyl 1.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 41,980 Mi
	Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8549	Asset located in: Lake Worth, TX 1976 Chevrolet Corvette Stingray Classic Car S/N: 1Z37L6S414551 C/W: V8 Gasoline Engine, Automatic Transmission, Power Windows Usage: 45,448 Mi Notes: ADDITIONAL INFORMATION	8557	2019 Kia Optima Automobile S/N: 5XXGT4L3XKG357335 C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 61,987 Mi Asset located in: Lake Worth, TX
	AVAILABLE IN OFFICE - KEY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8558	2018 Chevrolet Malibu Automobile S/N: 1G1ZF5SU0JF291884 C/W: 4 cyl 1.8 L Gasoline Engine, 2018 US EPA
8551	2015 Ford E350 4x2 14-Seat Passenger Van S/N: 1FDEE3FL1FDA16098 C/W: Air Conditioner, Automatic Transmission, Wheelchair Ramp, Wheelchair Lift, V8 5.4 L Gasoline Engine, 2014 US EPA Label, 225 /75R16, Spring Suspension, 158 in Wheelbase Usage: 103,717 Mi		Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 50,772 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	8558A	
8552	2019 Mercedes-Benz Sprinter Van Passenger Van S/N: WD3PF0CD3KT003689 C/W: 3.0 L Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 167,464 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 3FA6P0HD1JR180576 C/W: 4 cyl 1.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 83,930 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8559	2017 Nissan Altima Automobile S/N: 1N4AL3AP5HN317978 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: 67,245 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	8564	2014 Toyota Camry Automobile S/N: 4T4BF1FK5ER408856 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 138,538 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8560 8561	2016 Dodge Challenger Automobile S/N: 2C3CDZAG7GH256566 C/W: V6 3.6 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows Usage: 55,445 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A FLOODED BRAND ON THE TITLE Asset located in: Humble, TX 2016 Kia Optima Automobile	-8565 -	2013 Nissan Sentra RS Automobile S/N: 3N1AB7AP4DL790448 C/W: 4 cyl 1.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, sunroof Usage: 127,946 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	S/N: 5XXGT4L38GG043240 C/W: 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 176,089 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8566 8566A	2013 Mini Cooper Automobile S/N: WMWSS5C53DWN49392 C/W: 4 cyl 1.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 137,997 Mi Asset located in: Lake Worth, TX 2012 Subaru Outback AWD Automobile S/N: 4S4BRBLC3C3303630
8562	Asset located in: Lake Worth, TX 2015 Nissan Juke Automobile S/N: JN8AF5MR0FT505833 C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 147,550 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	8567	C/W: 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 209,226 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2011 Mercedes-Benz E350 Automobile S/N: WDDGF5GB0BR142256 Usage: Not Available Asset located in: Lake Worth, TX
8563	2015 Chevrolet Impala Automobile S/N: 2G11Y5SN8F9263766 C/W: 6 cyl 3.6 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 92,389 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8568	2011 Toyota Camry Automobile S/N: 4T4BF3EK3BR115028 C/W: 4 cyl 2.4 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8569 8570	2008 Saab 9-3 Aero Automobile S/N: YS3FH41U081156520 C/W: V6 2.8 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 160,781 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2007 BMW 328I Automobile S/N: WBAVC535X7FZ77345 C/W: 6 cyl Gasoline Engine, Automatic	8574	2017 Ford Escape S 2WD SUV S/N: 1FMCU0F70HUB26560 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 134,079 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	Transmission, Air Conditioner, Power Windows, Power Locks Usage: 138,111 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	8575	2017 Ford Escape 2WD SUV S/N: 1FMCU0GD9HUE71445 C/W: 3 cyl 1.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 175,892 Mi
8571	2013 Jeep Wrangler 4WD 6-Door SUV S/N: 1C4HJWEG2DL570305 C/W: V6 3.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 57,484 Mi Notes: COMPLETE CUSTOM BUILD IN UTAH - COMES WITH BLUE OX AVENTA LX MOTORHOME/COACH CUSHION TOW BAR; ALL DOORS AND TOPS ARE REMOVEABLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
		8576	2017 Chevrolet Traverse LS 2WD SUV S/N: 1GNKRFKDXHJ203590 C/W: 6 cyl 3.6 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 187,718 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8572	Asset located in: Lake Worth, TX 2018 Ford Expedition 4x4 SUV S/N: 1FMJU2ATXJEA25730 C/W: V6 3.5 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 130,626 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8577	2017 Chevrolet Trax 2WD SUV S/N: 3GNCJKSB6HL220642 C/W: 1.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 131,519 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8573	Asset located in: Lake Worth, TX 2018 Nissan Pathfinder SV 2WD SUV S/N: 5N1DR2MN0JC605382 C/W: V6 3.5 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear View Camera Usage: 134,053 Mi	8578	2017 Chevrolet Tahoe 4WD SUV S/N: 1GNSKFEC1HR217144 C/W: V8 5.3 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera Usage: 152,407 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8579	2016 Chevrolet Tahoe 4WD SUV S/N: 1GNSKFEC8GR440859 C/W: V8 5.3 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 145,373 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8580	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC5GR437584 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 155,738 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8586	2015 Infiniti QX60 2WD SUV S/N: 5N1AL0MN6FC525522 C/W: V6 3.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 132,145 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; SELLING WITH A
8581	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC6GR252511 C/W: V8 5.3 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,		REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX 2015 Land Rover Range Rover 4WD SUV
	Rear View Camera, Towing Hitch Usage: 202,310 Mi Asset located in : Lake Worth, TX		S/N: SALVP2BG7FH957087 C/W: 4 cyl Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,
8582	2016 Nissan Rogue 2WD SUV S/N: JN8AT2MT0GW019414 C/W: 4 cyl 2.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 143,099 Mi		Rear View Camera Usage: 144,024 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	8588	2015 Dodge Durango SUV
8583	2016 Nissan Rogue SV SUV S/N: KNMAT2MT6GP624673 C/W: 4 cyl 2.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air		S/N: 1C4RDHDG1FC702143 Usage: Not Available Asset located in : Lake Worth, TX
8584	Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 159,117 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX 2016 Dodge Journey SUV	8589	2015 Chevrolet Tahoe LS 2WD SUV S/N: 1GNSCAKC2FR521634 C/W: V8 5.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: 144,233 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
0004	S/N: 3C4PDCAB6GT219191 C/W: 4 cyl 2.4 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 3rd Row Usage: 88,015 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE	8590	Asset located in: Lake Worth, TX 2014 Chevrolet Tahoe 2WD SUV S/N: 1GNLC2E03ER162966 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 197,207 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8592	2012 Ford Expedition 2WD SUV
8585	2016 Kia Soul Automobile S/N: KNDJP3A52G7276905 C/W: 4 cyl 2.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 134,403 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX		S/N: 1FMJK1K58CEF12802 C/W: V8 5.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 131,092 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; NTHIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8593	2011 Jeep Grand Cherokee 2WD SUV S/N: 1J4RS4GGXBC513599 C/W: V6 3.6 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 168,573 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8602	2019 Chevrolet Silverado 3500HD 4x4 Crew Cab Pickup S/N: 1GC4KVCG9KF138086 C/W: V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11000 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 79,152 Mi Asset located in: Lake Worth, TX
		8605	2018 Ford F-350 XL 4x4 Crew Cab Pickup
8594	2009 Chevrolet Suburban LT SUV S/N: 1GNFC26J89R299573 C/W: 6 cyl 5.3 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Towing Hitch Usage: 301,880 Mi		S/N: 1FT8W3BT1JEC94927 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11500 lb GVWR, 275/65R18 Tires, 8 ft Bed Usage: 44,439 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
1	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8596	2007 Cadillac Escalade 2WD SUV S/N: 1GYEC63867R384531 C/W: 6.2 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row, Towing Hitch Usage: 137,706 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8607	2018 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT2JEC44330 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, Drop-In Bed Liner, 11500 lb GVWR, 275/70R16 Tires, 8 ft Bed
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Usage: 186,195 Mi Asset located in : Humble, TX
	Asset located in: Lake Worth, TX	_8608B	2016 Ford F-350 XLT 4x4 Crew Cab Pickup
8598	2006 BMW X5 4WD SUV S/N: 5UXFA13596LY40272 C/W: V6 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 189,977 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	_60066	S/N: 1FT8W3BT4GED37892 C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Spray-On Bed Liner, 11500 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 252,228 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8599	2006 Chevrolet Suburban LT 4WD SUV	1	Asset located in: Lake Worth, TX
	S/N: 1GNFK16Z86J170794 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Brush Guard and Rear Bumper., Towing Hitch Usage: 193,404 Mi Asset located in: Midland, TX	8609	2011 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT0BEC51343 C/W: 6.7 L V8 Diesel Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Drop-In Bed Liner, 11200 lb GVWR, 35x12.50R22 Tires, 8 ft Bed Usage: 106,357 Mi
8600	2006 Chevrolet Tahoe Z71 4WD SUV		Notes: TITLE IS BRANDED AS NOT ACTUAL
	S/N: 1GNEK13Z26R125089 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA		MILEAGE Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 229,606 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	8611	1999 Ford F-350 4x4 Crew Cab Pickup S/N: 1FTSW31F2XEA09050 C/W: Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, 9900 lb GVWR, 295/60R20 Tires, 8 ft Bed Usage: 263,566 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8612	2013 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3CT8DEB22137 C/W: 6.7 L Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Dual Rear Wheel, Spray-On Bed Liner, 14000.0 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 386,746 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8620	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ8MG631265 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 122,390 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
8614	2009 Chevrolet Silverado 3500HD 4x2 Crew Cab Pickup S/N: 1GCJC83619F178424 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Dual Rear Wheel, Spray-On Bed Liner, 11400 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 368,242 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8622	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ2MG631262 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 275/70R18 Tires, 8 ft 1 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 176,662 Mi Asset located in: Lake Worth, TX	
8614A	Asset located in: Lake Worth, TX 2012 Ford F-350 4x4 Extended Cab Pickup S/N: 1FT8X3BT4CEA06351 C/W: 6.7 L Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 275 /70R18 Tires, 8 ft 3 in Bed Usage: 252,510 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2021 Ram 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6UR5HJ5MG631241 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	
8618	2023 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5DL0PG517224 C/W: 6.7 L V8 Diesel Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 10000.0 lb GVWR, 37X12.50R20 Tires, 6 ft 4 in Bed Usage: 12,741 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		REMOVAL; TEXAS BUYERS M OFFICE TO SIGN REQUIRED DO EQUIPMENT FROM A PRIMOR CORP COMPANY Asset located in: Lake Worth, 7 8623 2018 Ram 2500 4x4 Crew Cab S/N: 3C6UR5CJ3JG404410 C/W: 6.4 L V8 Gasoline Engine Label, Automatic Transmission Conditioner, Power Windows, 9 Liner, 10000 lb GVWR, 275/701	REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; EQUIPMENT FROM A PRIMORIS SERVICES CORP COMPANY Asset located in: Lake Worth, TX 2018 Ram 2500 4x4 Crew Cab Pickup
8619	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ7MG630043 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 65,623 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		Usage: 96,524 Mi Notes: TEXAS BUYERS MUST STOP IN OFFIC TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8623A	S/N: 3C6UR5HJOJG327360 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Fuel Tank /w Pump, WeatherGuard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 122,776 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8628	2017 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL9HG570121 C/W: 6.7 L 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 35X12.50R20 Tires, 6 ft 2 in Bed Usage: 133,929 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8624	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ6JG354370 C/W: 6.4 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000.0 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 167,897 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8629	2021 Ford F-250 King Ranch 4x4 Crew Cab Pickup S/N: 1FT7W2BT9MEC11318 C/W: 6.7 L V8 Diesel Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 10000 lb GVWR, 275 /65R20 Tires, 7 ft Bed Usage: 16,533 Mi
8625	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL8JG274920 C/W: 6.7 L Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/65R18 Tires, 6 ft 4 in Bed Usage: 197,428 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8630	Asset located in: Lake Worth, TX 2020 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63LEE12818 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, PROTECH Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed Usage: 140,719 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8626	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL3JG148321 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 2 in Bed Usage: 159,765 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2017 Ram 2500 4x4 Crew Cab Pickup	8631	2020 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B66LEE12831 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 153,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	S/N: 3C6UR5CL0HG589107 C/W: 6.7 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 6 ft 4 in Bed Usage: 196,427 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8632	2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2B68KED41291 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 139,607 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8633	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63KEF04896 C/W: 6.2 L V8 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 6 ft 6 in Bed Usage: 142,484 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8638	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19ME73MF197398 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 104,683 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	
8634	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B6XKEF04796		Asset located in: Lake Worth, TX	
	C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 176,645 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	S/N: 1GT19LE75MF221517 C/W: 6.6 L V8 Gasoline Engine, Automati Transmission, Air Conditioner, Power Wir Headache Rack, Fuel Tank /w Pump, RKI Box, 10000 lb GVWR, 265/70R17 Tires, 8 Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 119,305 Mi Notes: TEXAS BUYERS MUST STOP IN O TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSON NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 8640 2021 GMC Sierra 2500HD 4x4 Crew Cab S/N: 1GT19ME74MF197121 C/W: 6.6 L V8 Gasoline Engine, Automati Transmission, Air Conditioner, Power Wir RKI Tool Box, 10000 lb GVWR, 265/70R1 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 106,361 Mi Notes: TITLE IS BRANDED AS NOT ACTU MILEAGE; TEXAS BUYERS MUST STOP II OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 SELLER IN THE DOCUMENTS SECTION E Asset located in: Lake Worth, TX 8641 2021 GMC Sierra 2500HD 4x4 Crew Cab S/N: 1GT19LE72MF223676 C/W: 6.6 L V8 Gasoline Engine, Automati Transmission, Air Conditioner, Power Wir RKI Tool Box, 10000 lb GVWR, 265/70R1 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 109,870 Mi Notes: TITLE IS BRANDED AS NOT ACTU MILEAGE; TEXAS BUYERS MUST STOP II OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE TO SIGN REQUIRED DOCUMENTS PLEASE SEE A PERSONAL NOTE FROM 1 OFFICE T	C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 119,305 Mi	
8635	2019 Ford F-250 XLT 4x4 Crew Cab Pickup		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	
0033	S/N: 1FT7W2BT1KEE55378 C/W: 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Sunroof, Better Built 100 gal Fuel Tank /w Pump, Drop-In Bed		PROCESS TITLE ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	
			<u>·</u> _	
	Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 8 in Bed Usage: 145,565 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX		S/N: 1GT19ME74MF197121 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Win RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION	C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION
8636	2016 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2BT2GEA52971 C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 7 ft Bed Usage: 121,086 Mi		Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		C/W: 6.6 L V8 Gasoline Engine, Automatic	
8637	2013 Ford F-250 Lariat 4x4 Crew Cab Pickup S/N: 1FT7W2BT3DEA48102 C/W: 6.7 L V8 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 35x12.5R20 Tires, 6 ft 10 in Bed Usage: 226,784 Mi Asset located in: Lake Worth, TX		RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 109,870 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	

Lot #	Details	Lot #	Details
8642	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE73MF131055 C/W: 6.6 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 112,785 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8646	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE79MF223755 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 131,224 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8643	Asset located in: Lake Worth, TX 2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223689 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 115,084 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	-8647	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF135301 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 105,910 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL
	PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8648	NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup
8644	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF222266 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,468 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	0040	S/N: 1GT12NEG8KF128147 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 103,405 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8649	2019 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF172137
8645	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223837 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Rawson Koenig Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 117,114 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8650	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG9KF243775 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 121,440 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8654	2018 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12REG3JF174233 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 128,754 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8651	2019 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12NEG7KF143089 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, Tool Box, 265 /70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 130,846 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8655	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12REG6JF173030 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 156,754 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8656	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12REG5JF173486
8652	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEGXKF172537 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 121,433 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL		C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 158,292 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX
	MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8657	2016 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12RE87GF259741 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power
8653	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF273565 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 245 /75R17 Tires, 8 ft Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 121,235 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8658	Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 169,025 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2014 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12ZCG9EF123876 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 9900 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 162,483 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8659	2019 Chevrolet Silverado 2500HD LT 4x4 Crew Cab Pickup S/N: 1GC1KSEY0KF118493 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fuel Tank, 10000.0 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8664	2012 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KVCG5CF145928 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 322,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8660	Asset located in: Lake Worth, TX 2019 Chevrolet Silverado 2500 HD 4x4 Crew	8667	2019 Ford F-250 XL 4x2 Crew Cab Pickup
	Cab Pickup S/N: 1GC1KSEG2KF213547 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 245 /75R17 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 138,145 Mi Asset located in: Lake Worth, TX	8667A	S/N: 1FT7W2A66KED56261 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 122,599 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8661	2019 Chevrolet 2500HD Z71 4x4 Crew Cab Pickup		Asset located in: Humble, TX
	S/N: 1GC1KTEG8KF220198 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 9500 lb GVWR, 275/65R18 Tires, 6 ft Bed, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 144,285 Mi Asset located in: Lake Worth, TX		2019 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A65KEC11406 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, 10000 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 204,188 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8662	2017 Chevrolet Silverado 2500 HD 4x4 Crew		TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Cab Pickup S/N: 1GC1KUEG5HF192312 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 128,022 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8668	2018 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A69JEC58484 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weatherguard Tool Box, 10000 lb GVWR, 265/70R15 Tires, 8 ft Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 157,129 Mi Asset located in: Humble, TX
	PROCESS TITLE ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8669	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A61HEE08405
	Asset located in: Lake Worth, TX	4	C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air
8663	2017 Chevrolet Silverado 2500 HD LT Z71 4x4 Crew Cab Pickup S/N: 1GC1KVEG8HF198725 C/W: 6.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 6 ft Bed, Wireless Charging Usage: 149,617 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 176,168 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8669A	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A66HEC56637 C/W: 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, WeatherGuard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 205,176 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8676	2019 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ7KG631829 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 180,148 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
8670	2015 Ford F-250 4x2 Crew Cab Pickup S/N: 1FT7W2A64FEC22645 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 268,869 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8677	2018 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ1JG188981 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires Usage: 204,579 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8678	2018 Ram 2500 4x2 Crew Cab Pickup
8671	2014 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A69EEB42367 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear Power Lift Gate, Aluminum Truck Cap, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed Usage: 173,752 Hr Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		S/N: 3C6UR4HJ8JG287331 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Fuel Tank, Weather Guard Tool Box, 10000 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 175,042 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	8670	·
8672	2021 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ6MG648396 C/W: 6.4 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 166,144 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8679	2015 Chevrolet 2500HD 4x4 Crew Cab Pickup S/N: 1GC1KWE89FF640746 C/W: 6.6 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 7 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD
8674	2019 Ram 2500 4x2 Crew Cab Pickup		WITH A BONDED TITLE;
	S/N: 3C6UR4HJ6KG603858 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA		Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, 6800.0 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 170,384 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8680	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B68LEC63951 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 166,422 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8680A	2016 Ford F-250 4x4 Extended Cab Pickup S/N: 1FT7X2BT8GEC22330 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 8 ft Bed Usage: 154,291 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8686	2017 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A64HEF24694 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 192,889 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8681	2015 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B61FEB25480 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Fuel Tank /w Pump, Tractor Supply Co Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 2 in Bed Usage: 111,775 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8687	2017 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A65HEB28242 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 238,717 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8682	2015 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B61FEC04213 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 320,450 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8688	2016 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A69GEC19075 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 10000.0 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 199,413 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8683	Asset located in: Lake Worth, TX 2018 Chevrolet Silverado 2500 HD 4x4 Dual Cab Pickup S/N: 1GC2KWEG9JZ193614 C/W: 6.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 162,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8689	2016 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A69GEB70864 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 10 in Bed Usage: 201,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8684	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2016 Chevrolet 2500HD 4x4 Extended Cab Pickup S/N: 1GC2KUEG4GZ109955 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 9500.0 lb GVWR, 8 ft Bed Usage: 355,555 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8690	2014 Ford F-250 4x2 Extended Cab Pickup S/N: 1FT7X2A66EEB24227 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, GPI Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 195,848 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8691	2014 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A6XEEA58748 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, WeatherGuard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 312,914 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8695	2020 Ram 2500 4x4 Pickup S/N: 3C6MR5AJ5LG164010 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 107,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8692	2014 Ford F-250 4x2 Extended Cab Pickup S/N: 1FT7X2A67EEB17769 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed	8696 8697	2017 Chevrolet Silverado 2500 HD 4x4 Pickup S/N: 1GC0KUEG2HZ225955 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 99,657 Mi Asset located in: Lake Worth, TX
	Usage: 191,870 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2015 Ram 2500 4x2 Pickup S/N: 3C6LR4AT0FG649313 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 9000 lb GVWR, 275/70R18
8693	Extended Cab Pickup S/N: 1GC2VC83CZ320119 C/W: 6.6 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed		Tires, 8 ft 2 in Bed Usage: 106,565 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 7 in Bed Usage: 279,928 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8697A	2015 Ford F-250 4x2 Pickup S/N: 1FTBF2ATXFEA40769 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8693A	2008 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FTSX20578EE54529 C/W: 5.4 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, 9200 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 331,802 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8698	Asset located in: Lake Worth, TX 2013 Ford F-250 4x2 Pickup S/N: 1FTBF2A60DEB82104 C/W: 6.2 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Truck Cap, 10000 lb GVWR, 245/70R17 Tires Usage: 81,563 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8694	2020 Ram 2500 4x4 Pickup S/N: 3C6MR5AJ9LG164012 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 102,553 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8699	2012 Chevrolet Silverado 2500 HD LS 4x2 Pickup S/N: 1GC0CVCG6CF138379 C/W: 6.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 8 ft 3 in Bed Usage: 223,391 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8700	2022 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTU9DED3NZ162699 C/W: 5.3 L V8 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 275/65R18 Tires, 6 ft Bed Usage: 102,807 Mi Asset located in: Lake Worth, TX	8704A	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED2MG205545 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 109,324 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8701	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED4MG242107 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7100 lb GVWR, 275		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8702	/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 97,407 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2021 GMC Sierra 1500 4x4 Crew Cab Pickup	8704B 8705	2021 GMC Sierra 1500 Crew Cab 4x4 Pickup S/N: 3GTU9BED7MG203323 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	S/N: 3GTU9DEDXMG239485 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7100 lb GVWR, 275 /60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 107,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2020 GMC Sierra 1500 4x4 Crew Cab Denali Pickup S/N: 1GTU9FEL4LZ152697 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Spray-On Bed Liner, 7100 lb GVWR, 5 ft 7 in Bed Usage: 98,858 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8703	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED3MG200127 C/W: 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 255/70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 117,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8705A	Asset located in: Lake Worth, TX 2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTP9EEL1LZ336096 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Drop-In Bed Liner, 7000 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 113,313 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
8704	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED6MG240892 Usage: Not Available Asset located in: Lake Worth, TX	8706	Asset located in: Lake Worth, TX 2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED0LG267777 C/W: 5.3 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 130,184 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8707	2014 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU2TECXEG385182 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 265/70R17 Tires, 5 ft 9 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 127,548 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8711	2019 Ram 1500 Big Horn 4x4 Crew Cab Pickup S/N: 1C6SRFFT3KN739606 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100.0 lb GVWR, 285/65R18 Tires, 5 ft 3 in Bed Usage: 196,574 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8712	2019 Ram 1500 Laramie 4x4 Crew Cab Pickup
8708	2016 Chevrolet Silverado 1500 LT 4x4 Crew Cab Pickup S/N: 1GCUKREC4GF141714 C/W: 5.3 L V8 Gasoline Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Decked Tool Box, Drop-In Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed	8713	S/N: 1C6SRFJT8KN822441 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 265/60R18 Tires, 5 ft 7 in Bed Usage: 165,533 Mi Asset located in: Lake Worth, TX 2017 Ram 1500 4x4 Crew Cab Pickup
	Usage: 263,036 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		S/N: 1C6RR7LT4HS620059 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	8714	2016 Ram 1500 4x4 Crew Cab Pickup
8709	2020 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFLT1LN227445 C/W: 5.7 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Tonneau Cover, 7100 lb GVWR, 265/65R18 Tires, 5 ft 7 in Bed Usage: 123,133 Mi	8/1 4	S/N: 1C6RR7MT0GS416856 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 6900 lb GVWR, 6 ft 5 in Bed, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 88,711 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8709A	•		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	S/N: 1C6SRFLT1LN333989 Usage: Not Available		Asset located in: Lake Worth, TX
8710	Asset located in: Lake Worth, TX 2019 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFFT7KN714613 C/W: 5.7 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 7100.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 129,734 Mi	8715	2018 Toyota Tundra 4x4 Crew Cab Pickup S/N: 5TFDW5F19JX740667 C/W: 5.7 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 275/70R18 Tires, 5 ft 7 in Bed Usage: 260,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2017 Toyota Tundra SR5 4x4 Crew Cab Pickup S/N: 5TFUW5F16HX610386 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Spray-On Bed Liner, 7100 lb GVWR, 275 /55R20 Tires, 6 ft Bed Usage: 262,750 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8717	2016 Toyota Tundra 4x4 Crew Cab Pickup S/N: 5TFDW5F12GX506041 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 285/65R18 Tires, 5 ft 6 in Bed Usage: 276,601 Mi Asset located in: Lake Worth, TX	8722	2020 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1E53LKD47734 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Protech Tool Box, Spray-On Bed Liner, 7000 lb GVWR, 265 /70R17 Tires, 5 ft 6 in Bed Usage: 121,047 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8718	2016 Toyota Tundra SR5 4x4 Crew Cab Pickup S/N: 5TFDW5F17GX526706		TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray- On Bed Liner, 7200.0 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 323,409 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8723	2020 Ford F-150 Lariat 4x4 Crew Cab Pickup S/N: 1FTEW1E52LKE45508 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 119,650 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8724	2019 Ford F-150 STX 4x4 Crew Cab Pickup
8719	2018 Nissan Titan Platinum Reserve 4x4 Crew Cab Pickup S/N: 1N6AA1E55JN509451 C/W: 5.6 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Tool Box, Spray-On Bed Liner, 7300 lb GVWR, 275/60R20 Tires, 5 ft 7 in Bed Usage: 2,600 Mi		S/N: 1FTEW1E56KKC96325 C/W: 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed Usage: 90,968 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; ODOMETER DISCREPENCY - ODOMETER SHOWS 2600 TITLE SHOWS 105570 Asset located in: Lake Worth, TX	8724A 8725	S/N: 1FTFW1E40KKD90146 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 275/65R18 Tires, 6
8720	2021 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E55MKD34831 C/W: 5.0 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed		6 in Bed Usage: 147,441 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Liner, 7050.0 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 96,289 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2019 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E49KKC43100 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 140,907 Mi
8721	2020 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1E58LKD34168 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 245/70R17 Tires, 5 ft 7 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 96,164 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICITO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8726	2018 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1EG1JKD95560 C/W: 3.5 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 245/75R17 Tires, 7 ft Bed Usage: 124,873 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8730	2014 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF3EFA28438 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7350 lb GVWR, 275/65R18 Tires, 5 ft 6 in Bed Usage: 167,074 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8727	2017 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTEW1EP9HFB20551 C/W: 2.7 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air	8731	2013 Ford F-150 Raptor 4x4 Crew Cab Pickup S/N: 1FTFW1R66DFA62527 C/W: 5.4 L V8 Gasoline Engine, 2010 US EPA
	Conditioner, Drop-In Bed Liner, 6500 lb GVWR, 33x12.50R18 Tires, 6 ft Bed Usage: 96,312 Mi Notes : SELLING WITH A REPOSESSION		Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, 7450 lb GVWR, 315/70R17 Tires, 5 ft 6 in Bed Usage: 80,237 Mi
	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV		Asset located in: Lake Worth, TX
	PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8732	2013 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1ET9DKF21987 C/W: 3.5 L V6 Gasoline Engine, 2013 US EPA
	Asset located in: Lake Worth, TX	_	Label, Automatic Transmission, Air Conditioner, Power Windows, Better Built Tool
8727A	A 2017 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTFW1EF7HKD98738 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed		Box, 7200 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 100,112 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Usage: 100,730 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8735	2011 Dodge Ram 1500 4x4 Crew Cab Pickup
	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 1D7RV1GT9BS552169 C/W: V8 Gasoline Engine, 2011 US EPA Label,
8728	2016 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1EF5GFA47779 C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 155,109 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6700 lb GVWR, 275/65R20 Tires, 6 ft 8 in Bed Usage: 154,689 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPENCY - ODOMETER SHOWS 154689 TITLE SHOWS 155742 Asset located in: Lake Worth, TX
	PROCESS TITLE	8736	2018 Ford F-150 XLT 4x2 Crew Cab Pickup
8729	Asset located in: Lake Worth, TX 2014 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF4EKF62314 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7350 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 99,175 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 1FTEW1CP5JKD52645 C/W: 2.7 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, 6360 lb GVWR, 265 /60R18 Tires, 5 ft 8 in Bed Usage: 121,549 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPANCY- UNIT SHOWS 121,549, TITLE SHOWS 139,907 Asset located in: Humble, TX

		I	
Lot #	Details	Lot #	Details
8737	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C56JKC10769 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 ft Bed, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 145,418 Hr Asset located in: Humble, TX	8742	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CFXHKE23730 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 86,433 Mi Asset located in: Humble, TX
8738	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C52JKC10770 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 146,917 Mi Asset located in: Humble, TX	8743	2017 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTEW1CF5HKC49971 C/W: 5.0 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, Spray-On Bed Liner, 6800 lb GVWR, 245/70R17 Tires, 5 ft 6 in Bed Usage: 119,231 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8739	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1C54JKC10768 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Weatherguard Tool Box, Drop-In Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 120,300 Mi Asset located in: Humble, TX	8744	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF0HKE23722 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 4 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 119,473 Mi Asset located in: Humble, TX
8740	2018 Ford F-150 Lariat 4x4 Crew Cab Pickup S/N: 1FTEW1E52JKE26129 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7000 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 109,847 Mi Asset located in: Lake Worth, TX	8745	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF2HKE53076 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 7 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 140,099 Mi
8741	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1E58JFD71503 C/W: V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 121,466 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8746	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF6HKE23725 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 5 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 142,764 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8747	2017 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1CP8HKD86640 C/W: 2.7 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6260 lb GVWR, 275/55R20 Tires, 5 ft 5 in Bed Usage: 199,080 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8752	2019 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFRM5F17KX141585 C/W: 4.6 L V8 Gasoline Engine, 2019 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Craftsman Tool Box, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 195,476 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8748	2016 Ford F-150 XL 4x2 Crew Cab Pickup	8753	2019 Toyota Tundra SR5 4x2 Crew Cab Pickup
	S/N: 1FTEW1CF9GKF65372 C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 6950 lb GVWR, 255/70R17 Tires, 6 ft 5 in Bed Usage: 196,241 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		S/N: 5TFRM5F18KX141630 C/W: 4.6 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 6 ft 2 in Bed Usage: 291,346 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
8749	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF4EKG33790 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 6 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 129,930 Mi Asset located in: Humble, TX	8754	2016 Ram 1500 SLT 4x2 Crew Cab Pickup S/N: 1C6RR6GG7GS403918 C/W: 3.6 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6800 lb GVWR, 275/55R20 Tires, 6 ft 3 in Bed Usage: 67,066 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8750	2014 Ford F-150 XLT 4x2 Crew Cab Pickup		TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	S/N: 1FTFW1CF3EKG33800 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 133,616 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8755	2014 Ram 1500 4x2 Crew Cab Pickup S/N: 1C6RR6KM8ES408801 C/W: 3.0 L V6 Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6800 lb GVWR, 265/70R17 Tires, 5 ft 10 in Bed Usage: 266,474 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8751	2014 Ford F-150 XL 4x2 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FTFW1CFXEKG11583 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Tool Box, Spray- On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 322,798 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8756	2014 GMC Sierra 1500 4x2 Crew Cab Pickup S/N: 3GTP1UEC6EG110768 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7000 lb GVWR, 275/55R20 Tires, 6 ft 7 in Bed Usage: 216,631 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8757	2010 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFTM5F17AX001055 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 255/70R18 Tires, 8 ft Bed Usage: 244,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2021 GMC Sierra 1500 4x4 Crew Cab Pickup	8761	2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC3HZ107938 C/W: 5.3 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 7200 lb GVWR, 295/55R20 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-HERC-RENTALS Usage: 63,030 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT EQUIPMENT FROM HERC RENTALS; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
0730	S/N: 1GTR9AEHXMZ203075 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 107,212 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8762	Asset located in: Humble, TX 2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC6HZ350529 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 189,063 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8759	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTR9AEH4MZ201452 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 113,431 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8763 8764	2015 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKPEH5FZ173329 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, Drop-In Bed Liner, 7100.0 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 91,050 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX 2015 Chevrolet Silverado 1500 4x4 Extended
8760	2019 Chevrolet Silverado 1500 LT 4x4 Dual Cab Pickup S/N: 1GCRYDED9KZ191418 C/W: 5.3 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 265/65R18 Tires, 6 ft 8 in Bed Usage: 148,223 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8765	Cab Pickup S/N: 1GCVKREC2FZ382091 C/W: 5.3 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 231,215 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2018 GMC Sierra 1500 4x4 Extended Cab Pickup S/N: 1GTV2LEC5JZ370765 C/W: 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 7200 lb GVWR, 265/70R17 Tires, 6 ft 9 in Bed, EQUIPMENT-FROM-5J-GROUP Usage: 227,149 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8766	2016 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7FT9GS207693 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 285/70R17 Tires, 6 ft Bed Usage: 177,486 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8768C	2023 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTFX1E54PKE88612 C/W: 5.0 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, Spray-On Bed Liner, 7150 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 35,130 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8767	2015 Ram 1500 4x4 Dual Cab Pickup S/N: 1C6RR7GMXFS671274 C/W: 3.0 L V6 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6950 lb GVWR, 35x12.5R20 Tires, 6 ft 3 in Bed Usage: 137,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8769	2018 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E53JKE13763 C/W: 5.0 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 149,967 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8768	2015 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7GT4FS643767 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6900 lb GVWR, 275/60R20 Tires, 6 ft 3 in Bed Usage: 118,037 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8770	2016 Ford F-150 XLT 4x4 Extended Cab Pickup S/N: 1FTFX1EF6GFB81556 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7050 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 127,639 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8768A	2023 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E52PKE72666 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 7150 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 25,106 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8771	2012 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTEX1EM1CFC36807 C/W: 3.7 L V6 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 275/65R18 Tires, 6 ft 10 in Bed Usage: 84,649 Mi Asset located in: Lake Worth, TX
8768B	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2023 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E52PKE96014 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7150 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 29,947 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8772	2006 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V36Z259882 C/W: 4.8 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 129,610 Mi Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8773	2004 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V84Z272706 C/W: 4.8 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6400 lb GVWR, 245/75R16 Tires, 6 ft 10 in Bed Usage: 172,966 Mi Asset located in: Lake Worth, TX

	- · ·	1	
Lot #	Details	Lot #	Details
8774	2021 Chevrolet Silverado 4x2 Extended Cab Pickup S/N: 1GCRWAEH8MZ261016 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 kg GVWR, 255/70R17 Tires, 7 ft Bed Usage: 164,523 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8780	2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C89HKC50152 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 5 in Bed Usage: 169,011 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8775	2014 Chevrolet Silverado 1500 4x2 Extended	8781	2015 Ford F-150 XL 4x2 Extended Cab Pickup
	Cab Pickup S/N: 1GCRCPEC8EZ211055 C/W: V8 Gasoline Engine, Air Conditioner, Power Windows, Tonneau Cover, Spray-On Bed Liner, 7000 lb GVWR, 37x13.5R24LT Tires, 6 ft 8 in Bed Usage: 26,768 Mi		S/N: 1FTEX1CFXFKE52008 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 199,497 Mi
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8776	2019 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C43KKE83254 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 255/70R18 Tires, 6 ft 6 in Bed Usage: 139,472 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8782	2015 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1CF9FKE51996 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 219,104 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
	PROCESS TITLE		TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8783	2014 Ford F-150 4x2 Extended Cab Pickup
8777	2018 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C56JKF84490 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 4 in Bed Usage: 135,767 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	6766	S/N: 1FTFX1CF8EKF95610 C/W: 5.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 7 in Bed Usage: 209,297 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
0770	·	8785	2005 Chevrolet Silverado 1500 4x4 Pickup
8778	2018 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C55JKF84478 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 172,916 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 1GCEK14V55Z288807 C/W: 4.8 L V8 Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft 5 in Bed Usage: 99,043 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8786	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH3FZ285656 C/W: 4.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 125,012 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8792	2017 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1CF4HKD34876 C/W: 5.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, protech Tool Box, Spray-On Bed Liner, 6750 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 117,485 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8788	2014 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH7EZ346442 C/W: 4.3 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 114,136 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	 - - - -	2010 Ford F-150 4x2 Pickup S/N: 1FTMF1CW8AKE17930 C/W: 4.7 L V6 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6750 lb GVWR, 235/75R17 Tires, 8 ft 5 in Bed Usage: 126,592 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8789	2013 Chevrolet 1500 4x2 Pickup S/N: 1GCNCPEA5DZ356873 C/W: 4.8 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 74,650 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; ODOMETER DISCREPANCY-UNIT SHOWS 74,650, TITLE SHOWS 145,093; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8794 8795	2003 Ford F-150 4x2 Pickup S/N: 2FTRF17L83CB00193 C/W: 5.4 L V8 Gasoline Engine, 2003 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6050 lb GVWR, 235/75R16 Tires, 8 ft 4 in Bed Usage: 94,369 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 1989 GMC Sierra 2500 4x2 Pickup S/N: 1GTFC24C1KE543722 C/W: V8 Diesel Engine, 4 Speed Manual Transmission, Drop-In Bed Liner, 72000 lb GVWR, 225/75R16 Tires, 8 ft Bed, EQUIPMENT-
8790	Asset located in: Lake Worth, TX 2020 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1C50LKD46068		FROM-YELLOW-CORP Usage: 113,113 Mi Asset located in : Midland, TX
8791	C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6750 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 124,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8796	2022 Ford Ranger 4x2 Crew Cab Pickup S/N: 1FTER4EH5NLD35536 C/W: 2.3 L 4 Cylinder Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 3500 lb GVWR, 265/70R16 Tires, 5 ft Bed Usage: 20,876 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
8/91	2018 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1E55JKF44493 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA		PROCESS TITLE Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray- On Bed Liner, 6950 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 140,414 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8797	2021 Chevrolet Colorado 4x2 Crew Cab Pickup S/N: 1GCGSCEN1M1296032 C/W: 2.5 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 5800 lb GVWR, 255/65R17 Tires, 5 ft Bed Usage: 47,944 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8798	2022 Chevrolet Colorado 4x2 Extended Cab Pickup S/N: 1GCHSBEA4N1311703 C/W: Automatic Transmission, Air Conditioner, Power Windows, 5400 lb GVWR, 255/65R17 Tires, 6 ft 2 in Bed Usage: 34,661 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8804	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN721807 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012.0 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 111,655 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8799	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN724934 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Stainless Steel Truck Cap, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 84,482 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8805	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE9LN721892 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012.0 lb GVWR, 265/75R16 Tires, 6 ft Bed Usage: 116,183 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8800	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE5LN721727 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012.0 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 103,120 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8806	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT1HN724360 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft 6 in Bed Usage: 103,998 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
8801	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN719166 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 100,824 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8807	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CTXHN757261 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 118,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8802	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE1LN721059 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 101,844 Mi Asset located in: Lake Worth, TX	8808	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT3HN721511 C/W: 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 127,844 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
8803	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE1LN721210 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 109,927 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		PROCESS TITLE; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8809	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19CNC000009 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 2 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8815	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19ANC000014 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8810	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000010 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 4 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8816	2022 Kandi K32S-R Utility Vehicle (Unused) S/N: A074EA19KNC000007 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 9 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8811	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000024 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8817	2022 Kandi K32S-R Utility Vehicle (Unused) S/N: A074EA19LNC000015 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 15 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8812	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19PNC000006 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 12 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8818	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19CNC000021 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi Notes: ***FOR OFF ROAD USE ONLY***; PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8813	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19JNC000011 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 13 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8819	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19TNC000005 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8814	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19PNC000023 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8820	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19TNC000022 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch, Charger Usage: 16 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX

821 Subaru Sambar 4x4 COE Flatbed Truck 3/N: T12096235 S/N: T12096	Lot #	Details	Lot #	Details
Tractor S/N: 1XPBAP8X1ND759335 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4478 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Ardie, 22700 lb Rears, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 200,027 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 200,027, TITLE SHOWS 201,000 Asset located in: Lake Worth, TX 8824 2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X0ND759228 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GWR, Air Ride Cab, 275 //80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY- ODOMETER SHOWS 213663 TITLE SHOWS 213700 Asset located in: Lake Worth, TX 8825 2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAA8X0BD339556 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 227200 lb Rears, 34700 lb GWR, Air Ride Cab, 275 //80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY- ODOMETER SHOWS 213663 TITLE SHOWS 213700 Asset located in: Lake Worth, TX 8825 2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAA8X0HD428751 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GWR, Air Ride Cab, 275/80R25. Front Tires, 295/75R22. 5 Rear Tires, Air Ride Cab, 275/80R25. Front Tires, 295/75R22. 5 Rear Tires, Air Ride Cab, 275/80R25. Front Tires, 295/75R22. 5 Rear Tires, Air Ride Cab, 275/80R25. Front Tires, 2	8821	S/N: TT2096235 C/W: Subaru Clover4 4 Cylinder Gasoline Engine, 5-Speed Manual Transmission, 145R12, Spring Suspension, 74 in Wheelbase, 77 ft x 55 in Bed Usage: 98,817 Mi Notes : THIS ITEM IS RIGHT HAND DRIVE; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY	8826	Tractor S/N: 1XPBA48X2HD428752 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel Usage: 933,275 Mi
Brake, Automated Transmission, 12000 ib Front Aske, 22700 ib Rears, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 200,027 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 200,027, TITLE SHOWS 201,000 Asset located in: Lake Worth, TX 8824 2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X0ND759228 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 ib Front Axle, 22700 ib Rears, 34700 ib GVWR, Air Ride Cab, 275 //80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 313,663 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 213663 TITLE SHOWS 213700 Asset located in: Lake Worth, TX 8825 2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 ib Front Axle, 22700 ib Rears, 34700 ib GVWR, Air Ride Cab, 275 //80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 896,378 Mi Asset located in: Lake Worth, TX 8826 2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 ib Front Axle, 22700 lb Rears, 34700 ib GVWR, Air Ride Cab, 295/75R22.5 Rear Tires, Air Ride Cab, 295/75R22.5 Rear Tires, Air Ride Suspension, 161 in Wheelbase, Air Silding 5th Wheel, Dual Fuel Tanks Usage: 896,378 Mi Asset located in: Lake Worth, TX 8827 2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X6D339491 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel A05 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 ib Front Axle, 22	8823	Tractor S/N: 1XPBAP8X1ND759335 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires		S/N: 1NP3A28X9HD409487 Usage: Not Available Asset located in : Lake Worth, TX
Tractor S/N: 1XPBAP8X0ND759228 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 //80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY- ODOMETER SHOWS 213663 TITLE SHOWS 213700 Asset located in: Lake Worth, TX 8825 2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000 Asset located in: Lake Worth, TX 8829 2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339556 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Automated Transmission, 12000 lb Rears, 34700 lb GVWR, Air Ride Cab, 297 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339451 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Bears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000		Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 200,027 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 200,027, TITLE SHOWS 201,000	8828	Tractor S/N: 1XPBA48X0HD428751 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 16727 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GWWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 213663 TITLE SHOWS 213700 Asset located in: Lake Worth, TX 8825 2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 S Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000 ASSET located in: Lake Worth, TX Ride Cab, 275/80R22.5 Front Tires, 295/75R22. S Rear Tires, 295/75R22.5 S Rear Tires, 295/75R22. S Rear Tires,	8824	Tractor		
2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000 Tractor S/N: 1XPBA48X6GD339491 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21591 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 808,551 Mi Asset located in: Lake Worth, TX		C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 213663 TITLE SHOWS 213700	8829	Tractor S/N: 1XPBA48X8GD339556 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 896,378 Mi
Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000 S/N: 1XPBA48X6GD339491 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21591 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 808,551 Mi Asset located in: Lake Worth, TX			8830	
	8825	Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS		S/N: 1XPBA48X6GD339491 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21591 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 808,551 Mi
·				

			1 age 401 01 381	
Lot #	Details	Lot #	Details	
8831	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339671 C/W: Cummins ISX15 6 Cylinder 15.0 L 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17898.4 Engine hrs, Engine Brake, Eaton Fuller UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Trac Air Ride Suspension, 159 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 888,673 Mi	8836	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X5FD286314 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	8837	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X7FD286248 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel	
8832			Exhaust Fluid, 19447 Engine hrs, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 839,056 Mi Asset located in: Lake Worth, TX	
	160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 672,222 Mi Asset located in : Lake Worth, TX	8838	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8FD286307	
8833	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X6GD339555 C/W: Cummins X15 6 Cylinder 15.0 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel		C/W: Cummins ISX15 6 Cylinder 15 400 hp Engine, 2014 US EPA Label, Diesel Exhaust Fluid, Automated Ti 12000 lb Front Axle, 22701 lb Rears GVWR, 295/75R22.5 Front Tires, 22 Rear Tires, Air Ride Suspension, 16	C/W: Cummins ISX15 6 Cylinder 15 L Petrol 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available
	Usage: 919,106 Mi Asset located in: Lake Worth, TX	8839	2016 Kenworth T-680 4x2 S/A Day Cab Truck	
8834	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X6FD286306 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18127 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Trac Air Ride		Tractor S/N: 1XKYA48XXGJ119241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	

275/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 883,053 Mi

Lot #	Details	Lot #	Details
8840	2016 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X9GJ496496 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17916 Engine hrs, Engine Brake, Eaton Fuller ADV Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, 4-Bag Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 912,222 Mi	8844	2015 Kenworth T-680 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYD49X7FJ466031 C/W: Cummins ISX15 6 Cylinder 15 L Diesel Engine, 2014 US EPA Label, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, Differential Lock, 2.64:1 Axle Ratio, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, AG400 8-Bag Air Ride Suspension, 179 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 338,458 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8845	2015 Kenworth T680 4x2 S/A Day Cab Truck
8841	2015 Kenworth T680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXFJ403449 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22634 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, 4-Bag Air Ride Suspension, 168 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		Tractor S/N: 1XKYA48XXFJ403435 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53 1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 973,817 Mi Asset located in: Lake Worth, TX
	Usage: 1,009,300 Mi	8846	2014 Kenworth T-680 4x2 S/A Day Cab Truck
8842	Asset located in: Lake Worth, TX 2015 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X0FJ443782 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 990,189 Mi		Tractor S/N: 1XKYA48X9EJ402288 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM- 15E310B-LAS Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airglide Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel Usage: 323,990 Mi Asset located in: Lake Worth, TX
	Notes: X2-No frame stamp vin pic		2014 Kenworth T680 S/A Day Cab Truck
8843	Asset located in: Lake Worth, TX 2015 Kenworth T-680 4x2 S/A Day Cab Truck Tractor		Tractor S/N: 1XKYA48X7EJ402287 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1XKYA48X6FJ443771 C/W: Cummins ISX 6 Cylinder 15 L Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 17203 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Airglide 4-Bag Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel Usage: 732,450 Mi Asset located in: Lake Worth, TX	8848	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X3EJ402450 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5 Front Tires, 275/80R22.5 Rear Tires, AG400 4-Bag Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 696,531 Mi

Lot #	Details	Lot #	Details
8849	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X0EJ403264 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 16967.1 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 157 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 538,940 Mi Asset located in: Lake Worth, TX	8853	2013 Kenworth T660 4x2 S/A Day Cab Truck Tractor S/N: 1XKAA48X1DJ354916 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 769,223 Mi Asset located in: Humble, TX 2013 Kenworth T660 6x4 T/A Day Cab Truck
8850	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXEJ402851 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Eaton Fuller FM-15E310B-LAS Automatic Transmission, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700.0 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,154,795 Mi Asset located in: Lake Worth, TX	0001	Tractor S/N: 1XKAD48X1DJ367527 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 11435.7 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Differential Lock, 12000 lb Front Axle, 34000 lb Rears, 2.64:1 Axle Ratio, 46000 lb GVWR, 275/80R22.5, 8- Bag Air Ride Suspension, 210 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 744,800 Mi Asset located in: Lake Worth, TX
8851	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X4EJ403168 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 767,305 Mi Asset located in: Lake Worth, TX	8855	2013 Kenworth T660 4x2 S/A Day Cab Truck Tractor S/N: 1XKAA48X8DJ354945 C/W: Cummins ISX15 6 Cylinder 15 L 400 hp Engine, Requires Diesel Exhaust Fluid, 22347.6 Engine hrs, Engine Brake, Eaton Fuller FM- 15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 4-Bag Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 888,882 Mi Asset located in: Lake Worth, TX
8852	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X9EJ403215 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19302.4 Engine hrs, Engine Brake, Eaton Fuller FM-15E310B 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, AG200 4-Bag Air Ride Suspension, 159 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 937,106 Mi Asset located in: Lake Worth, TX	8856	2013 Peterbilt 337 4x2 S/A Day Cab Truck Tractor S/N: 2XP2AN7X0DM211082 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 6874 Engine hrs, Engine Brake, Allison 6- Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 5.38:1 Axle Ratio, 33000 lb GVWR, Aluminum Front Wheels, 11R22.5, Paccar Air Ride Suspension, 156 in Wheelbase Usage: 213,485 Mi Asset located in: Lake Worth, TX 2019 Mack AN42T 4x2 S/A Day Cab Truck Tractor S/N: 1M1AN2AY6KM001154 C/W: Mack MP7 6 Cylinder Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab,
			Automated Transmission, 12000 lb Front Ax

Lot #	Details	Lot #	Details
8858	2019 Mack Anthem 4x2 S/A Day Cab Truck Tractor	8862	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1M1AN2AY2KM001152 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4523 Engine hrs, Engine Brake, Mack 12-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase Usage: 476,581 Mi Asset located in: Lake Worth, TX	S/N: 3AKBGDDV1HDHY5841 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12543 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS 23-161 Drive Axles, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	
8859	2017 Mack CXU612 4x2 S/A Day Cab Truck Tractor		Usage: 553,773 Mi Asset located in: Lake Worth, TX
	S/N: 1M1AW01Y9HM010179 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 477,424 Mi	8863	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV4HDHY5848 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 569,326 Mi
	Asset located in: Lake Worth, TX	4	
8860	2017 Mack CXU612 4x2 S/A Day Cab Truck Tractor		
	S/N: 1M1AW01Y7HM010164 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14979 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 548,175 Mi Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
		8864	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV6HDHY5849 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 52 hp Engine, 2016 US EPA Label, Requires Diese Exhaust Fluid, 15402 Engine hrs, Engine Brake Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-161 Drive Axles, 2.50:1
8861		Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5t Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 620,515 Mi Asset located in: Lake Worth, TX	
	Detroit 12-Speed Automated Transmission,	8865	2017 Freightliner Cascadia 125 4x2 S/A Day
	12000 lb Front Axle, 23000 lb Rears, 3.08:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 244,661 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 3AKBGDDV5HDHY5843 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 588,024 Mi

Lot #	Details	Lot #	Details
8866	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0385 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17775 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 920,721 Mi Asset located in: Lake Worth, TX	8870	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 20941 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 984,115 Mi Asset located in: Lake Worth, TX
8867	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0401 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18682 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,203 Mi Asset located in: Lake Worth, TX	8871	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGJ1241 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 2052 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 703,022 Mi
8868	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0164 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18936 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor MFS-12-143A Drive Axles, 3.42:1 Axle Ratio, 33000 kg GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 871,985 Mi Asset located in: Lake Worth, TX	8872	Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0245 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19950 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,022 Mi Asset located in: Lake Worth, TX
8869	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0206 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19010 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 865,103 Mi Asset located in: Lake Worth, TX	8873	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0459 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17399 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 802,794 Mi Asset located in: Lake Worth, TX

Details Lot# **Details** Lot # 8874 2015 Freightliner Cascadia 125 4x2 S/A Day 8878 2015 Freightliner Cascadia 125 4x2 S/A Day **Cab Truck Tractor Cab Truck Tractor** S/N: 1FUBGDD56FLGB0324 S/N: 1FUBGDD55FLGB0301 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18129 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Transmission, 12000 lb Front Axle, 21000 lb Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 Rears, Meritor RS-23-186 Drive Axles, 3.42:1 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Axle Ratio, 33000 lb GVWR, Air Ride Cab, 10R22.5 Front Tires, 11R22.5 Rear Tires, Usage: 818,368 Mi Airliner Air Ride Suspension, 158 in Wheelbase, **Dual Fuel Tanks** Asset located in: Lake Worth, TX Usage: 771,423 Mi 8875 2015 Freightliner Cascadia 125 4x2 S/A Day Asset located in: Lake Worth, TX **Cab Truck Tractor** 8880 2015 Freightliner Cascadia 125 4x2 S/A Day S/N: 1FUBGDD55FLGJ1193 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Cab Truck Tractor S/N: 1FUBGDD50FLGJ1327 Exhaust Fluid, 19725 Engine hrs, Engine Brake, C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Exhaust Fluid, 20282 Engine hrs, Engine Brake, Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, Dual Fuel Tanks Airliner Suspension, 158 in Wheelbase, Dual **Fuel Tanks** Usage: 871,783 Mi Usage: 896,379 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 8876 2015 Freightliner Cascadia 125 4x2 S/A Day 8881 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor Cab Truck Tractor S/N: 1FUBGDD51FLGJ1322 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 S/N: 1FUBGDD52FLGJ1233 hp Engine, 2014 US EPA Label, Requires Diesel C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, CARB Exhaust Fluid, 16251 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Compliant, Requires Diesel Exhaust Fluid, 21113 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride 12000 lb Front Axle, 21000 lb Rears, 33000 lb Suspension, 158 in Wheelbase, Dual Fuel Tanks GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,874 Mi Asset located in: Lake Worth, TX Usage: 927,772 Mi 8877 2015 Freightliner Cascadia 125 4x2 S/A Day Asset located in: Lake Worth, TX **Cab Truck Tractor** 8882 2015 Freightliner Cascadia 125 4x2 S/A Day S/N: 1FUBGDD56FLGJ1204 **Cab Truck Tractor** C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel S/N: 1FUBGDD50FLGB0254 Exhaust Fluid, 20437 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14024 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Transmission, 12000 lb Front Axle, 21000 lb 11R22.5, Airliner Air Ride Suspension, 158 in

Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, **Dual Fuel Tanks**

Usage: 1,066,619 Mi

Asset located in: Lake Worth, TX

Wheelbase, Dual Fuel Tanks Usage: 882,971 Mi

		_	
Lot #	Details	Lot #	Details
8883	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1297 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 847,972 Mi Asset located in: Lake Worth, TX	8887	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0200 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 840,242 Mi Asset located in: Lake Worth, TX
8884	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGJ1248 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 853,850 Mi Asset located in: Lake Worth, TX	8888	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGB0420 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21049 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 971,468 Mi Asset located in: Lake Worth, TX
0005	<u> </u>	0000	<u> </u>
8885	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0455 C/W: 21346 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23- 186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner II Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 978,516 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT Asset located in: Lake Worth, TX	8889	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0084 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21221 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,002,152 Mi Asset located in: Lake Worth, TX
8886	2015 Freightliner Cascadia 125 4x2 S/A Day	8890	2015 Freightliner Cascadia 125 4x2 S/A Day
	Cab Truck Tractor S/N: 1FUBGDD58FLGB0423 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 870,847 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 1FUBGDD59FLGJ1150 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor Drive Axles, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 844,869 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8891	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGJ1217 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18209 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,386 Mi Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8895	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0266 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 910,815 Mi Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDD53FLGB0278 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20497 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 954,240 Mi Asset located in: Lake Worth, TX	-8897	S/N: 1FUBGDD58FLGB0227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22008 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,012,404 Mi Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
8893	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1249 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 995,766 Mi Asset located in: Lake Worth, TX	70097	Cab Truck Tractor S/N: 1FUBGDD54FLGB0161 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19325 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 889,925 Mi Asset located in: Lake Worth, TX
8894	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0247 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19933 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 926,620 Mi Asset located in: Lake Worth, TX	8898	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0351 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19389 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 867,504 Mi Asset located in: Lake Worth, TX

-		1	
Lot #	Details	Lot #	Details
8899	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8903	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDD57FLGB0283 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18643 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 985,816 Mi		S/N: 1FUBGDD52FLGJ1328 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4695 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 862,038 Mi Asset located in: Lake Worth, TX
8900	Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day	8904	2015 Freightliner Cascadia 125 4x2 S/A Day
8900	Cab Truck Tractor S/N: 1FUBGDD54FLGB0208 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 19799 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks Usage: 922,423 Mi		Cab Truck Tractor S/N: 1FUBGDD56FLGB0145 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19762 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,268 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8905	2015 Freightliner Cascadia 125 4x2 S/A Day
8901	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGJ1223 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19901 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 851,964 Mi Asset located in: Lake Worth, TX	-6905	Cab Truck Tractor S/N: 1FUBGDD57FLGJ1227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17987 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 859,845 Mi Asset located in: Lake Worth, TX
8902	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0173 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 842,483 Mi Asset located in: Lake Worth, TX	8906	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGB0153 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR0-15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,039,845 Mi Asset located in: Lake Worth, TX

			Page 470 of 581
Lot #	Details	Lot #	Details
8907	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0120 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19024 Engine hrs, Engine Brake, Eaton Fuller FR0-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 874,425 Mi Asset located in: Lake Worth, TX	8911	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0347 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1735 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 940,040 Mi Asset located in: Lake Worth, TX
8908	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0339 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19629 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 766,317 Mi Asset located in: Lake Worth, TX	8912	Cab Truck Tractor S/N: 1FUBGDD55ELFL7286 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 777,001 Mi Asset located in: Lake Worth, TX
8909	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0314 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19888 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 854,701 Mi Asset located in: Lake Worth, TX	8913	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XELFL7283 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20475 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 868,356 Mi Asset located in: Lake Worth, TX 2014 Freightliner Cascadia 125 4x2 S/A Day
8910	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0176 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 792,126 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 1FUBGDD50ELFL7275 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19027 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 783,595 Mi Asset located in: Lake Worth, TX

This catalog was created at December 10, 2024 03:25:22 PM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8915	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58ELFL7265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 730,348 Mi Asset located in: Lake Worth, TX	8920	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBX1102 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19727 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 662,005 Mi Asset located in: Lake Worth, TX
8916	2014 Freightliner Cascadia 125 4x2 S/A Day	8921	2013 Freightliner Cascadia 125 4x2 S/A Day
	Cab Truck Tractor S/N: 1FUBGEBG0ELFT4306 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-14E310B Automated Transmission, Meritor RS-23-160 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 552,293 Mi Asset located in: Humble, TX	-	Cab Truck Tractor S/N: 1FUBGDDR0DLBX1156 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18326 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 422,808 Mi Asset located in: Lake Worth, TX
8918	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8922	2013 Freightliner Cascadia 125 4x2 S/A Day
9010	S/N: 1FUBGDDRXDLBX1004 C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 748,352 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 1FUBGDDR4DLBX0897 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20167 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 812,847 Mi Asset located in: Lake Worth, TX
8919	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8923	2013 Freightliner Cascadia 125 4x2 S/A Day
	S/N: 1FUBGDDR6DLBX1162 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 16476 Engine hrs, Engine Brake, Eaton Fuller FR0-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 647,254 Mi		Cab Truck Tractor S/N: 1FUBGDDR4DLBX1080 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 515,155 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8924	2013 Freightliner Cascadia 125 4x2 S/A Day
		•	Cab Truck Tractor S/N: 1FUBGDDR1DLBX0906 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19497 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 724,603 Mi

Asset located in: Lake Worth, TX

		_	
Lot #	Details	Lot #	Details
8925	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR7DLBX1185 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21125 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 790,333 Mi Asset located in: Lake Worth, TX	8929	2014 Freightliner M2 112 6x4 T/A Day Cab Truck Tractor S/N: 1FUJC5DV2EHFX4554 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.62:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 698,878 Mi Asset located in: Lake Worth, TX
8926	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR1DLBX0985 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21973 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 802,200 Mi	8930	2015 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCYCY6FDGJ1937 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8522 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Detroit DA-RS-23.0-4 Drive Axles, 5.22:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Spring Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 147,777 Mi Asset located in: Lake Worth, TX
8927	Asset located in: Lake Worth, TX 27 2012 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR9CLBF2891 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 19508 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 712,633 Mi	8931 8932	2015 Freightliner M2 106 S/A Day Cab Truck Tractor S/N: 3AKBCYCY2FDGJ1949 Usage: Not Available Asset located in: Lake Worth, TX 2014 Freightliner M2 106 S/A Day Cab Truck Tractor S/N: 3AKBCYCY3EDFY1228
		8933	Usage: Not Available Asset located in: Lake Worth, TX 2014 Freightliner M2 106 S/A Day Cab Truck Tractor
8928	Asset located in: Lake Worth, TX 2018 Freightliner Cascadia 113 4x2 S/A Day Cab Truck Tractor		S/N: 3AKBCYCY3EDFY1164 Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 3AKBGBDV9JSJR3316 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, 13472 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 22700 lb Rears, 3.08:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 623,326 Mi Asset located in: Lake Worth, TX	8934	2014 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCYCY4EDFX5745 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9009 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 5.38:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, steel, 295/75R22.5, Spring Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 120,247 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8935	2022 Volvo VNR300 4x2 S/A Day Cab Truck	8940	2019 Volvo VNR300 4x2 S/A Day Cab Truck
0933	Tractor	0940	Tractor
	S/N: 4V4W19EG7NN285618		S/N: 4V4W39EGXKN226147
	C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2021 US EPA Label, Requires		C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires
	Diesel Exhaust Fluid, 7146 Engine hrs, Engine		Diesel Exhaust Fluid, 15950 Engine hrs, Engine
	Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb		Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 23000 lb
	Rears, Meritor RS-23-160 Drive Axles, 32000 lb		Rears, Meritor RS23-160 Drive Axles, 35350 lb
	GVWR, 275/80R22.5, Volvo Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks		GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 156 in Wheelbase, Air
	Usage: 295,698 Mi		Sliding 5th Wheel, Dual Fuel Tanks
	Asset located in: Lake Worth, TX	_	Usage: 730,594 Mi Asset located in: Lake Worth, TX
8936	2022 Volvo VNR 4x2 S/A Day Cab Truck Tractor	8941	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor
	S/N: 4V4W19EG7NN285540 C/W: Volvo D13N405 6 Cylinder 12.8 L 405 hp	0,41	S/N: 4V4W19EGXKN907544
	Engine, 2021 US EPA Label, Requires Diesel		C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires
	Exhaust Fluid, 8483 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated		Diesel Exhaust Fluid, Engine Brake, Automated
	Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, R22.5 Front Tires, 295		Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000.0 lb GVWR, 275/80R22.5 Front
	/75R22.5 Rear Tires, Air Ride Suspension, 152		Tires, 295/75R22.5 Rear Tires, Volvo Air Ride
	in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP		Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP
	Usage: 347,925 Mi		Usage: 680,054 Mi
	Asset located in: Midland, TX		Asset located in: Lake Worth, TX
8937	2021 Volvo VNR300 4x2 S/A Day Cab Truck	8942	2019 Volvo VNR 4x2 S/A Day Cab Truck Tracto
	Tractor S/N: 4V4W19EG7MN285326		S/N: 4V4W19EG1KN907528 C/W: Volvo D13M-405 6 Cylinder 12.8 L 405 hp
	C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel		Engine, 2018 US EPA Label, Requires Diesel
	405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 7976 Engine hrs, Engine		Exhaust Fluid, Engine Brake, Volvo AT2612F Automated Transmission, 12000 lb Front Axle,
	Brake, Volvo AT2612F 12-Speed Automated		20000 lb Rears, Meritor RS23-160/161 Drive
	Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb		Axles, 32000 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride
	GVWR, 295/75R22.5, Volvo Air Ride		Suspension, 153 in Wheelbase, Dual Fuel
	Suspension, 151 in Wheelbase, Dual Fuel Tanks Usage: 322,314 Mi		Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 706,546 Mi
	Notes: ODOMETER DISCREPANCY-UNIT		Asset located in: Lake Worth, TX
	SHOWS 322,314, TITLE SHOWS 322,500 Asset located in: Lake Worth, TX	8943	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor
8939	2019 Volvo VNR300 4x2 S/A Day Cab Truck		S/N: 4V4W19EG3KN901925 C/W: Volvo D13M405 6 Cylinder 12.8 L 405 hp
0,0,	Tractor		Engine, 2018 US EPA Label, Requires Diesel
	S/N: 4V4W39EG8KN226146		Exhaust Fluid, 17551 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated
	C/W: Volvo 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel		Transmission, 12000 lb Front Axle, 20000 lb
	Exhaust Fluid, Volvo ATO2612F 12-Speed		Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride
	Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, 35350 lb GVWR, Air Ride Cab,		Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP
	Aluminum Wheels, 11R22.5, Air Ride		Usage: 754,359 Mi
	Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		Asset located in: Midland, TX
	Usage: 664,493 Mi		
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8944	2018 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG1JN901758 C/W: Volvo D13M405 6 Cylinder 12.8 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP	8948	2012 Volvo VNL300 4x2 S/A Day Cab Truck Tractor S/N: 4V4N19EG6CN560842 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 32350.0 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 311,531 Mi Asset located in: Humble, TX
	Usage: Not Available	8949	2014 International ProStar 4x2 S/A Day Cab
	Asset located in: Lake Worth, TX	400 hp Engine, 2013 US Diesel Exhaust Fluid, En Automated Transmissi 20000 lb Rears, 32350 Aluminum Outer Rear N Ride Suspension, 173 i 5th Wheel, Dual Fuel Ta Usage: 360,386 Mi	
8945	Tractor S/N: 4V4M19EG1HN985095 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 22474 Engine hrs, Volvo AT2612D 12-Speed Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, VOLVO Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks		C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, Aluminum Outer Rear Wheels, 11R22.5, Air Ride Suspension, 173 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 360,386 Mi Asset located in: Lake Worth, TX
	Usage: 876,316 Mi	8950	2015 International 4400 4x2 S/A Day Cab
8946	Asset located in: Lake Worth, TX 2015 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH4FN184666 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15123 Engine hrs, Engine Brake, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32350 lb GVWR, Air Ride Cab, 295/75R22.5, Volvo Air Ride Suspension, 156 in Wheelbase,	Engine, Requires Diesel Exhaust F Engine hrs, Engine Brake, Allison Transmission, 12000 lb Front Axl Rears, 32000 lb GVWR, Aluminum	S/N: 1HSMTSTN8FH726444 C/W: Navistar N9 6 Cylinder 9.3 L Diesel Engine, Requires Diesel Exhaust Fluid, 3580 Engine hrs, Engine Brake, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 152 in Wheelbase, PTO Usage: 85,797 Mi
		8951	2012 International 4400 4x2 S/A Day Cab
8947	Notes: TITLE COMES WITH A CORRECTION OF AFFIDAVIT Asset located in: Humble, TX 2013 Volvo VNL200 4x2 S/A Day Cab Truck Tractor S/N: 4V4N39EG8DN142388 C/W: Volvo D13H405 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D Automated Transmission, 12350 lb		S/N: 1HSMTAAN4CH561985 C/W: International MaxxForce 7.6 L Diesel 300 hp Engine, 20 4407 Engine hrs, Eaton Fuller 1 Transmission, 12000 lb Front / Rears, 32000 lb GVWR, Air Ride Air Ride Suspension, 148 in Wh Fuel Tanks Usage: 136,823 Mi
	Front Axle, 23000 lb Rears, 35350 lb GVWR, 11R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel Usage: 535,477 Mi Asset located in: Lake Worth, TX	8952	2009 International ProStar Premium 4x2 S/A Day Cab Truck Tractor S/N: 2HSCSAPN49C045678 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, 275 /80R22.5, Air Ride Suspension, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 610,101 Mi

Asset located in: Lake Worth, TX

			1 age 473 01 301	
Lot #	Details	Lot #	Details	
8953	2008 International TranStar 8600 4x2 S/A Day Cab Truck Tractor S/N: 1HSHWAHN68J673895 C/W: Cummins 6 Cylinder Engine, 22559 Engine hrs, Eaton Fuller 10-Speed Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 148 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 582,442 Mi Asset located in: Midland, TX	8957	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GF32N335289 C/W: Volvo DT12C345 6 Cylinder 12.1 L Diesel 345 hp Engine, 2001 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 2.93:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 344,373 Mi Asset located in: Lake Worth, TX	
8953A	2005 International 8600 4x2 S/A Day Cab Truck Tractor S/N: 1HSHWAHN55J029493 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel Engine, 2084 Engine hrs, Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 169 in Wheelbase, Dual Fuel Tanks Usage: 495,481 Mi Asset located in: Lake Worth, TX	8958	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19RF72N324549 C/W: Detroit 6 Cylinder 12.7 L Diesel 470 hp Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 32000 lb GVWR, 295/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 154 mm Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 1,393,840 Mi	
8955	2003 Freightliner FLD 112 4x2 S/A Day Cab Truck Tractor		Asset located in: Midland, TX	
8956	S/N: 1FUBACA873DK79061 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel 370 hp Engine, 2002 US EPA Label, Meritor 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 2.93:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 919,458 Mi Asset located in: Lake Worth, TX	8961	2017 Peterbilt 579 4x2 (CNG) S/A Day Cab Truck Tractor S/N: 1NPBAH8X7HD421460 C/W: Cummins ISX12 6 Cylinder 11.9 L Compressed Natural Gas (CNG) 400 hp Engine, 2016 US EPA Label, Engine Brake, Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, 35050 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel Usage: 549,140 Mi	
	Tractor S/N: 4V4M19EH28N498237		Asset located in: Lake Worth, TX	
	C/W: Volvo 6 Cylinder 12.8 L Diesel Engine, 2007 US EPA Label, Engine Coolant Heater, 10- Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 295 /75R22.5, Paccar Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 1,428,300 Mi Asset located in: Midland, TX	8962	8962 2017 Freightliner Cascadia 113 CNG Day Cab Truck Tractor S/N: 1FUBGBD98HLGV4596 C/W: Cummins ISX12G 11.9 L Com Natural Gas (CNG) 400 hp Engine, 2 EPA Label, Allison 4000 HS Automa Transmission, 12500 lb Front Axle, 3 Rears, Meritor RS-23-160 Drive Axle	2017 Freightliner Cascadia 113 CNG 4x2 S/A Day Cab Truck Tractor
8956A	2007 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GFX7N451743 C/W: Volvo 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Engine Brake, Eaton Fuller FR13210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-186 Drive Axles, 2.93:1 Axle Ratio, 32000 lb GVWR, Aluminum Front Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 144 in Wheelbase, Dual Fuel Tanks Usage: 1,551,805 Mi Asset located in: Lake Worth, TX		/75R22.5, Airliner Air Ride Suspension, 182 in Wheelbase Usage: 23,705 Mi Asset located in : Lake Worth, TX	

Lot #	Details	Lot #	Details	
8963	2008 Trail King TK140MDG-693 70 ton Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ069368B045330 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, Tri/A Jeep, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 30 ft Main Deck, 108 in Usable Deck Width, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275/70R22.5 Tires, 175300 lb GVWR Usage: Not Available Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED Asset located in: Lake Worth, TX	8968	2007 Trail King TK110HDG 55 t Tri/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533X7M051363 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 102 in Usable Deck Width, 12 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 132800 lb GVWR, EQUIPMENT FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED;	
8964	2008 Etnyre RTN65TD3-RA 3+1+1 Lowboy		PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	
	Trailer S/N: 1E92980888E111025		Asset located in: Lake Worth, TX	
	C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 25 ft 7 in Main Deck, 98 in Usable Deck Width, 108 in Overall Deck Width, 275/70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	8969	2007 Trail King TK55T 55 ton Quad/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ053347B051452 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, S/A Flip Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 10 in Usable Deck Width, Folding Side Extensions Gas Powered Self Contained Hydraulic Syster	
8965	2006 Trail King TK130HDG-573 Tri/A	1	Aluminum Wheels, 275/70R22.5 Tires, 110000 lb GVWR	
	Removable Gooseneck Lowboy Trailer S/N: 1TKJ057386M014661		Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 28 ft Main Deck, 120 in Overall Deck Width, Honda Gas Powered Self Contained Hydraulic System, 235/75R17.5 Tires, 161280 lb GVWR, Spreader Bar Usage: Not Available Asset located in: Humble, TX	8970	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E32RS000472 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self	
8966	2016 Etnyre RTN60TD4-PS Quad/A Removable Gooseneck Lowboy Trailer S/N: 1E9320301GE111172		Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available	
	C/W: Air Ride Suspension, Lift 4th- Axles, Hydraulic Removable Gooseneck, 26 ft Main	0074	Asset located in: Lake Worth, TX	
	Déck, 16 ft Rear Deck, 102 in Usable Deck Width, Folding Side Extensions, Deck Over Tires, Manual Ramps, 275/70R22.5 Tires, 66842 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Humble, TX	8971	Removable Gooseneck Lowboy Tra (Unused) S/N: 1W8A11E36RS000474 C/W: Spring Suspension, Mechanica Removable Gooseneck, 22 ft Main I Usable Deck Width, 102 in Overall D 126 in Widening Width, Folding Side	S/N: 1W8A11E36RS000474 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side
8967	2015 XL Specialized 120SDE Tri/A 53 ft Extendable Lowboy Trailer S/N: 4U3B05337FL014387 C/W: Air Ride Suspension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 42 ft Main Deck, 97 in Overall Deck Width, 102 in Widening Width, 235/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	

		I	
Lot #	Details	Lot #	Details
8972	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E34RS000473 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2015 XL Specialized 120SDE Tri/A 40 ft	8976	2013 Trail King TK110HDG 55 t Tri/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533XDM109113 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in Usable Deck Width, 126 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 134660 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED; PLEASE SEE A PERSONAL NOTE FROM THE
	Extendable Lowboy Trailer		SELLER IN THE DOCUMENTS SECTION BELOW
	S/N: 4U3B05330FL014621 C/W: Air Ride Suspension, Plumbed for	0077	Asset located in: Lake Worth, TX
	Booster Axle, 40 ft Main Deck, 102 in Usable Deck Width, Aluminum Outer Wheels, 235 /75R17.5 Tires, 143575 lb GVWR Usage: Not Available	89//	2010 Trail King TK110HDG533 55 ton Tri/A Single Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ05330AM109858 C/W: Air Ride Suspension, Hydraulic
0074	Asset located in: Lake Worth, TX		Removable Gooseneck, Plumbed for Booster
8974	2013 Trail King TK110HDG533 55 t Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ05333DM041625 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 26 ft Main Deck, 102 in Usable Deck Width, Folding Side Extensions, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, 275/70R22.5 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX		Axle, 26 ft Main Deck, 13 ft 7 in Rear Deck, 1 in Usable Deck Width, 24 in Widening Width, Folding Side Extensions, Boom Recess, Hon Gas Powered Self Contained Hydraulic Syste Aluminum Wheels, 255/70R22.5 Tires, 1338 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELGASSET located in: Lake Worth, TX
8975	2013 Trail King TK110HDG 55 t Tri/A Double Drop Removable Gooseneck Lowboy Trailer	8978	2022 Pitts LB51-22 51 ton Tri/A Single Drop Lowboy Trailer
	S/N: 1TKJ05334DM109110 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in Usable Deck Width, 126 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 134820 lb GVWR, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED;		S/N: 5JYLB5137NPP24054 C/W: Air Ride Suspension, Air Brakes, Lift 3rd-Axles, Hydraulic Removable Gooseneck, 26 ft Main Deck, 16 ft Rear Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Deck Over Tires, Aluminum Outer Wheels, 255/70R22.5 Tires, 121500 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8980	2010 Witzco Challenger RG50 Tri/A Removable
	Asset located in: Lake Worth, TX		Gooseneck Lowboy Trailer S/N: 1W8A11F37AS000227 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 25 ft Main Deck, 102 in Usable Deck Width, Deck Over Tires, Gas Powered Self Contained Hydraulic System, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8982	2019 Fontaine T/A Removable Gooseneck Lowboy Trailer S/N: 57J348208K3575771 C/W: Air Ride Suspension, Air Brakes, 255 /70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	8988	1981 Nuttall 225-E T/A Lowboy Trailer S/N: NMC50296 C/W: Spring Suspension, 9 ft 4 in Upper Deck, 23 ft 5 in Main Deck, 5 ft 4 in Fixed Dovetail, 90 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Manual Ramps, 10.00R15 Tires Usage: Not Available
8983	2004 Fontaine 552-2MWNGB 55 ton 2+2		Asset located in: Lake Worth, TX
	Removable Gooseneck Lowboy Trailer S/N: 4LFE7640943523624 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, 29 ft Main Deck, 96 in Usable Deck Width, 120 in Widening Width, Folding Side Extensions, Gas Powered Self Contained Hydraulic System, 275 /70R22.5 Tires, 147500 lb GVWR	8989	1990 Talbert TJ-11R22.5 35 ton T/A Heavy-Haul Jeep S/N: 40FJK2725L1008821 C/W: Air Ride Suspension, 275/70R22.5 Tires, 67079 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8992	2018 Liddell C55 S/A Booster Axle S/N: 1L93J0517JB564012
8984	2000 Fontaine T/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 13ND48291Y1590100		C/W: Flip-Up, Air Ride Suspension, 255/70R22. 5 Tires Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Air Ride Suspension, Mechanical Removable Gooseneck, 9 ft 7 in Upper Deck, 29 ft 2 in Main Deck, 7 ft 8 in Rear Deck, 102 in Usable Deck Width, Deck Over Tires, 255 /70R22.5 Tires, 70000 lb GVWR Usage: Not Available	8994	1989 Fontaine S/A Booster Axle S/N: 13NM04107K1547671 C/W: Pin-On, Air Ride Suspension, 255/70R22. 5 Tires, 18160 lb GVWR Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
Lowboy Trailer S/N: 1C9B48207E1167105 C/W: Walking Beam Suspension Removable Gooseneck, Plumber Axle, 30 ft Main Deck, 102 in Usa Width, Dropside Deck, 11R24.5 1 Cozad 16 Wheel Expando Jeep v /n 1C9H24204E11677104. 1984 Booster s/n: 1C9B48207E11671 Pin-On Booster, 70R22.5 Tires;	S/N: 1C9B48207E1167105 C/W: Walking Beam Suspension, Mechanical Removable Gooseneck, Plumbed for Booster	8995	2020 Wabash TCD/CDC-CDH S/A Dolly S/N: 1JJD061X6LL222455 C/W: Spring Suspension, 275/80R22.5 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	8996	1994 Pines S/A Dolly S/N: 1PNA09101RK056464 C/W: Spring Suspension, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8986	Asset located in: Humble, TX 2008 Viking VFDD46R18F35T T/A Double Drop Lowboy Trailer S/N: 1V9CR46288N062389 C/W: Spring Suspension, 9 ft Upper Deck, 21 ft 5 in Main Deck, 9 ft 2 in Rear Deck, 4 ft Fixed Dovetail, 102 in Usable Deck Width, Upper Deck Ramps, Deck Over Tires, Spring Assisted Ramps, 255/70R22.5 Tires, 87000 lb GVWR Usage: Not Available Asset located in: Midland, TX	8996A	1987 Fruehauf ELF-1 S/A Dolly S/N: 1H2E00617HH031475 C/W: 295/75R22.5 Tires, 20000 lb GVWR Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX
		8998	2019 Trail King TK70HT T/A Hydraulic Tail Trailer
8987	2002 Kalyn Siebert LB0353T Quad/A Lowboy Trailer S/N: 5DDKE404221000577 C/W: Walking Beam Suspension, 39 ft Main Deck, 98 in Usable Deck Width, 102 in Overall Deck Width, Tail Roller, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1TKA04828KM102376 C/W: 84800 lb GVWR, Spring Suspension, 9 ft Upper Deck, 38 ft 8 in Main Deck, 9 ft 2- Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8999	2018 Fontaine Traverse HT T/A Hydraulic Tail Trailer S/N: 57JV482DXJ3574695 C/W: Air Ride Suspension, 6 ft 10 in Upper Deck, 38 ft 5 in Main Deck, 4 ft 3 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, 10R17.5 Tires, 83200 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9006	2023 Maxey YHX T/A Gooseneck Hydraulic Tail Trailer S/N: 5R8GF4023PM106833 C/W: Spring Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, 40000 lb GVWR, Hydraulic Jacks Usage: Not Available Asset located in: Lake Worth, TX	
9000	2016 Trail King TK80HT T/A Hydraulic Tail Trailer S/N: 1TKA04823GM031272 C/W: Air Ride Suspension, 7 ft 8 in Upper Deck, 38 ft 10 in Main Deck, 7 ft 8 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R-17.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9007	1996 Trail-Eze DHT7048 T/A Hydraulic Tail Trailer S/N: 1DA72C7D9TM012261 C/W: Air Ride Suspension, 9 ft 9 in Upper Deck, 30 ft 2 in Main Deck, 8 ft 2-Position Dovetail, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 83520 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
9001	2016 Trail-Eze TE70XT T/A Hydraulic Tail Trailer S/N: 1DAHFC727GP022069 C/W: Air Ride Suspension, Sliding Suspension, 7 ft Upper Deck, 38 ft 1 in Main Deck, 4 ft 10 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, 10R17.5 Tires, 86720 lb GVWR, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9008	2014 Landoll 930C T/A Sliding Axle Trailer S/N: 1LH930UHXE1C20991 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 4 ft Upper Deck, 23 ft Main Deck, 13 ft Rear Deck, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10r17.5 Tires, 86300 lb GVWR, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
9002	2016 Trail-Eze TE70XT 28983 lb T/A Hydraulic Tail Trailer S/N: 1DAHFC725GC021848 C/W: Aluminum Frame, Spring Suspension, Air Brakes, 6 ft 6 in Upper Deck, 25 ft Main Deck, 2-Position Dovetail, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Hydraulic Ramps, 10r17.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9008A 9009 9010	9008A 2011 Landoll 48 ft T/A Sliding Axle Tr S/N: 1LH317UHXB1D18600 C/W: Air Ride Suspension, 9 ft 6 in Up 37 ft Main Deck, 102 in Usable Deck V Winch, Deck Over Tires, 10R17.5 Tires Ib GVWR Usage: Not Available Asset located in: Lake Worth, TX 9009 2012 Lucon 44 ft T/A Sliding Axle Tra S/N: 1L9SC5322CG423002 C/W: Lunette Ring Hitch, Spring Suspendir Brakes, 44 ft Main Deck, 97 in Usa Width, 99 in Overall Deck Width, 215/7 Tires, 25900 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 9010 2025 Maxey 40 ft T/A Sliding Axle Tra (Unused) S/N: 5R8GF4025SM118166	2011 Landoll 48 ft T/A Sliding Axle Trailer S/N: 1LH317UHXB1D18600 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck, 37 ft Main Deck, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 87000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2012 Lucon 44 ft T/A Sliding Axle Trailer S/N: 1L9SC5322CG423002 C/W: Lunette Ring Hitch, Spring Suspension,
9004	2007 Ledwell LW48 T/A Hydraulic Tail Trailer S/N: 1L9GA72A37L033118 C/W: Spring Suspension, 7 ft Upper Deck, 28 ft Main Deck, 8 ft 2-Position Dovetail, 102 in Overall Deck Width, Winch, Deck Over Tires, Hydraulic Ramps, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX			Usage: Not Available Asset located in: Lake Worth, TX 2025 Maxey 40 ft T/A Sliding Axle Trailer (Unused) S/N: 5R8GF4025SM118166 C/W: Spring Suspension, Electric Brakes, Fixed
9005	2006 Ledwell T/A Hydraulic Tail Trailer S/N: 1L9GA72A96L033669 C/W: Air Ride Suspension, 8 ft Upper Deck, 29 ft 2 in Main Deck, 8 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Winch, 255/70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Dovetail, 93 in Usable Deck Width, 97 in Overa Deck Width, 235/80R16 Tires, 25990 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	

Lot #	Details	Lot #	Details
9011	2023 Great Dane 53 ft T/A Single Drop Step Deck Trailer S/N: 1GR4M0629PH443585 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck, 43 ft Main Deck, 96 in Usable Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9017	2018 Trail King 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB04825JY067453 C/W: Air Ride Suspension, 9 ft 10 in Upper Deck, 37 ft Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Aluminum Flooring, 255/70R22.5 Tires, 90420 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9012	2022 Brazo 80000 lb 53 ft T/A Single Drop Step Deck Trailer S/N: 4B9BKFS23NH054914 C/W: 80000 lb GVWR, Air Ride Suspension, Aluminum w/Wood Strips Flooring, 255/70R22. 5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9018	2014 Direct Trailers 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 5UJDS4829EE002311 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, 255/70R22. 5 Tires, 70852 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9013	2017 Trail King TK80ACS-40 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB05326HY082695 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 10 ft 4 in Upper Deck, 42 ft 2 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires, 90930 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9019	2013 Fontaine 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N248206D1557385 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Center Roller, Tail Roller, Wood Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX
9014	2013 Utility FS2CDHA 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1UYFS2534DA605126 C/W: Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes:	9020	2013 Transcraft 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE482S6D3756769 C/W: Air Ride Suspension, 11 ft Upper Deck, 37 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9015	Asset located in: Oklahoma City, OK 2012 Manac 14353A000 Tri/A 53 ft - 73 ft Extendable Single Drop Step Deck Trailer S/N: 2M5131611C1130362 C/W: Air Ride Suspension, 10 ft 6 in Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Extendable Deck, Tail Roller, Wood Flooring, Aluminum Outer Wheels, 255/70R22. 5 Tires, 45360 lb GVWR	9021	2006 Transcraft 48 ft T/A Single Drop Step Deck Trailer S/N: 1TTE4820861081701 C/W: Air Ride Suspension, Lift 1st- Axles, 10 ft 3 in Upper Deck, 36 ft Main Deck, 92 in Usable Deck Width, 102 in Overall Deck Width, 255 /70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9016	Usage: Not Available Asset located in: Humble, TX	9022	2005 Fontaine DFT-5-8048WSAWK 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N24830851529149
סוטע	2006 Transcraft DTL-2100 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE5320061080090 C/W: Air Ride Suspension, 10 ft Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, Aluminum Outer Wheels, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 8 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, 255/70R22.5 Tires, 69556 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9023	2000 Pro-Trak 53 ft T/A Step Deck Trailer S/N: 5BNDG5322YC001797 C/W: Spring Suspension, Electric Brakes, 9 ft Upper Deck, 39 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 225/75R16 Tires Usage: Not Available Asset located in: Humble, TX	9032A	2020 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GR4M9624LH151129 C/W: Air Ride Suspension, Air Brakes, 97 in Deck Width, 102 in Overall Width, Aluminum w /Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9027	2016 Fontaine 53 ft T/A Step Deck Curtain Side Trailer S/N: 13N2532C2G1512734 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, Ramp, Roll-Up Door, Aluminum Outer Wheels, 225/70R22.5 Tires, 66667 lb GVWR Usage: Not Available Asset located in: Humble, TX	9033	2019 Manac 10248K001L 48 ft T/A Flatbed Trailer S/N: 5MC124811K3181128 C/W: Air Ride Suspension, 92 in Deck Width, 102 in Overall Width, Wood Flooring, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
9028	2013 Utility FS2CHS 53 ft T/A Flatbed Trailer		PRIOR TO BIDDING Asset located in: Lake Worth, TX
	S/N: 1UYFS253XDA605017 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9033A	2018 Fontaine HCVSF12WSA 80000 lb 48 ft T /A Spread Axle Flatbed Trailer S/N: 13N14820XJ1525028 C/W: Air Ride Suspension, 97.5 in Deck Width 101.5 in Overall Width, Wood Flooring, 11R24.
9029	2012 Great Dane 53 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM0625CH715673		Tires, 70543 lb GVWR Usage: Not Available Asset located in : Humble, TX
	C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9034	2016 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM9622GH729220 C/W: Aluminum/Steel Combination Frame, Ai Ride Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead,
9030	2005 Benson 53 ft Tri/A Flatbed Trailer S/N: 5DMFABTC85M000235 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width,		Aluminum Flooring, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
	Aluminum Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9035	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A22FR032303 C/W: Aluminum Frame, Air Ride Suspension,
9031	2007 Chaparral 50 ft T/A Spread Axle Flatbed Trailer S/N: 1C92F50257M949174 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width,	9036	97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
	Bulkhead, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		2015 Benson 524 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A1F3882259 C/W: Aluminum Frame, Air Ride Suspension,
9032	2023 Transcraft 40000 lb 48 ft T/A Spread Axle Flatbed Trailer (Unused) S/N: 1TTF482C2P3354782 C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9037	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A29FR032427 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9044	2012 Utility 48 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2481CA431530 C/W: Air Ride Suspension, 79.5 in Deck Width, 100.5 in Overall Width, Aluminum w/Wood Strips Flooring, 285/75R24.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9038	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A26FR032336 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9045	2012 Utility FS2CHA 48 ft T/A Flatbed Trailer S/N: 1UYFS2483CA431528 C/W: Air Ride Suspension, 97.5 in Deck Width, 100.5 in Overall Width, Aluminum w/Wood Strips Flooring, 285/75R24.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2009 Wade WH1-48FT T/A Extendable Flatbed
9039	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A26FR032319 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9046	Trailer S/N: 1W9FH48289E285033 C/W: Spring Suspension, Sliding Suspension, 11R22.5 Tires, 80000 lb GVWR, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: BENT FRAME PER SELLER Asset located in: Lake Worth, TX
9040	2015 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A8F3882257 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available	9047A	1996 Fontaine FL120 48 ft T/A Flatbed Trailer S/N: 13N1482C4T1573640 C/W: Spring Suspension, Sliding Suspension, 96 in Deck Width, Bulkhead, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9041	Asset located in: Lake Worth, TX 2015 Fontaine 48 ft T/A Spread Axle Flatbed Trailer S/N: 13N148202F1571993 C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 11R22.5 Tires, 70543 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9048	2007 Lufkin 45 ft T/A Flatbed Trailer S/N: 1L01B452471164518 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2006 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B482761159825 C/W: Spring Suspension, Sliding Suspension, 96 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires, 80000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTIOUsage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
9042	2013 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482S7D3749530 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Wood Flooring, Aluminum Wheels, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX		
9043	2012 Manac 48 ft T/A 48 ft - 80 ft Extendable Flatbed Trailer S/N: 2M5121463C1128632 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 91 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 73855 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9050	2006 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820961078665 C/W: Spring Suspension, Sliding Suspension, 95 in Deck Width, 102 in Overall Width, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9051	2008 Transcraft TL-2000N 45 ft T/A Flatbed Trailer S/N: 1TTF4520082021315 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9058	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH29SG000349 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9052	2005 Fontaine T/A 35 ft Extendable Flatbed Trailer S/N: 13N43620651527739 C/W: Spring Suspension, 87 in Deck Width, 91 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9059	2025 Atro T/A End Dump Trailer S/N: 3ELA6EH25SG000347 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls, Aluminum Body, Electric Roll Tarp, 11R24.5 Tires, 74957 lb GVWR, Aluminum Lead Body, 4 ft Lead Side Walls, Electric Lead Tarp Usage: Not Available
9053	1999 Fontaine T/A Extendable Flatbed Trailer S/N: 13N548209X1586994 C/W: Air Ride Suspension, 98 in Deck Width, 98 in Overall Width, 11R22.5 Tires, 75074 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9060	Asset located in: Lake Worth, TX 2025 Atro T/A End Dump Trailer S/N: 3ELA6EH25SG000350 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls Usage: Not Available
9054	1999 Fontaine 48 ft T/A Spread Axle Flatbed Trailer S/N: 1R1F94820XK990187 C/W: Aluminum Frame, Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 11R24.5 Tires, 79600 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9061	Asset located in: Lake Worth, TX 2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000382 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9055	1988 Fontaine FTW-3-8045SL 45 ft T/A Flatbed Trailer S/N: 13N1452CXJ1544459 C/W: Spring Suspension, Sliding Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9062	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH24SG000386 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9056	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000351 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9063	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH22SG000385 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9057	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000348 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9064	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH29SG000383 C/W: Spring Suspension, 34 ft Body, 49 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH20SG000384 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2015 MAC 40 ft T/A Aluminum Frameless End Dump Trailer S/N: 5MADN4020FC033902 C/W: Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2015 MAC 40 ft T/A Frameless End Dump Trailer S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR	9074	2004 Midland MG34ST2400 34 ft T/A Quarter Frame End Dump Trailer S/N: 2MFB2R5CX4R002967 C/W: Spring Suspension, 34 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, Aluminum Outer Wheels, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX 2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515423AP011370 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer
Dump Trailer S/N: 5MADN4020FC033902 C/W: Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2015 MAC 40 ft T/A Frameless End Dump Trailer S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR	_	BONDED TITLE Asset located in: Lake Worth, TX 2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515423AP011370 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer
C/W: Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2015 MAC 40 ft T/A Frameless End Dump Trailer S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR	_	Dump Trailer S/N: 5MC515423AP011370 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer
Trailer S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR	9075	Asset located in: Lake Worth, TX 2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer
S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR	9075	Dump Trailer
Usage: Not Available Asset located in : Lake Worth, TX	9075	
2022 Discount Dumps 36 ft T/A End Dump		
Trailer S/N: 1D91A3925N1865007 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 36 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9076	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515420AP011374 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available
2016 Dragon 34 ft Tri/A Quarter Frame End		Asset located in: Lake Worth, TX
Dump Trailer S/N: 1UNSD3431GS128862 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 34 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available Notes: .	9077	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515429AP011373 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
<u> </u>	9078	2021 Mate 30 ft Tri/A Aluminum Quarter
Dump Trailer S/N: 591SD3429GR136697 C/W: Spring Suspension, 34 ft Body, 44 in Side Walls, Steel Body, Electric Roll Tarp, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Frame End Dump Trailer S/N: 1M9A30333MH036271 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes: Asset located in: Humble, TX
7 SCAANU A 2 E SCLA7U N A 2 E SCN7U	Grailer S/N: 1D91A3925N1865007 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 36 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires Jsage: Not Available Asset located in: Lake Worth, TX 2016 Dragon 34 ft Tri/A Quarter Frame End Dump Trailer S/N: 1UNSD3431GS128862 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 34 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Fires, 70000 lb GVWR Jsage: Not Available Notes: Asset located in: Humble, TX 2016 Ranco ED 26-34 34 ft T/A Frameless End Dump Trailer S/N: 591SD3429GR136697 C/W: Spring Suspension, 34 ft Body, 44 in Side Walls, Steel Body, Electric Roll Tarp, 11R24.5 Fires, 70000 lb GVWR Jsage: Not Available	S/N: 1D91A3925N1865007 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 36 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires Jsage: Not Available Asset located in: Lake Worth, TX 2016 Dragon 34 ft Tri/A Quarter Frame End Dump Trailer S/N: 1UNSD3431GS128862 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 34 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Fires, 70000 lb GVWR Jsage: Not Available Notes: . Asset located in: Humble, TX 2016 Ranco ED 26-34 34 ft T/A Frameless End Dump Trailer S/N: 591SD3429GR136697 C/W: Spring Suspension, 34 ft Body, 44 in Side Walls, Steel Body, Electric Roll Tarp, 11R24.5 Fires, 70000 lb GVWR Jsage: Not Available

Lot #	Details	Lot #	Details
9079	2018 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A30332JH036175 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available	9086	1983 Fontaine 12 ft T/A Pup Dump Trailer S/N: 1A1V2920XD16PT113 C/W: Spring Suspension, 12 ft Body, 46 in Side Walls, Steel Body, Manual Roll Tarp, 10.00-22 Tires, 47500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: . Asset located in: Humble, TX		S/N: 5TU114021HS000432 C/W: Air Ride Suspension, Clam Gate Electric
9080	2021 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A3033XMH036270 C/W: Aluminum Frame, Air Ride Suspension,		Roll Tarp Push Block, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes: Asset located in: Humble, TX	9088	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114021GS000512 C/W: Air Ride Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9081	2018 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A30339JH036173 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available Notes:	9089	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114028GS000197 C/W: Spring Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9091	2016 Construction Trailer Specialist BDT-40 T /A Belly Dump Trailer
9082	2001 Travis 39 ft T/A Frameless End Dump Trailer S/N: 48X1F392911001782 C/W: Air Ride Suspension, 39 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 275/80R24.5 Tires Usage: Not Available		S/N: 5TU114024GS000021 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9092	2014 Armor Lite SBD-40 40 ft T/A Belly Dump Trailer
9083	2003 Ranco 36 ft T/A Frameless End Dump Trailer S/N: 1R9ESD5073L008627 C/W: Spring Suspension, 36 ft Body, 46 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 56EA53K23EA000188 C/W: Spring Suspension, Cross Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
9084	2002 Vantage 37 ft T/A Aluminum Frameless End Dump Trailer		Asset located in: Lake Worth, TX
	S/N: 4EPAA37292ATA4342 C/W: Air Ride Suspension, 37 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9093	2013 Manac 40 ft T/A Belly Dump Trailer S/N: 5MC424017D3133810 C/W: Air Ride Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
9085	1999 Smithco T/A Side Dump Trailer S/N: 1S9SS4022XL476665 C/W: Spring Suspension, Dumps to Both Sides, 36 in Side Walls, Steel Body, 425/66R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

	T.	
Details	Lot #	Details
2007 CTS BDT-40 42 ft T/A Belly Dump Trailer S/N: 5TU1140287S000202 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Clam Gate, Push Block, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9100	2012 Western 53 ft T/A Spread Axle Curtain Side Trailer S/N: 5DN115323CB000814 C/W: Air Ride Suspension, Aluminum Wheels, 295/75R22.5 Tires, 69000 lb GVWR Usage: Not Available
2003 Trail King BD237 T/A Belly Dump Trailer		Asset located in: Humble, TX
C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9101	1999 Nu Van NVSS 53 ft 53 ft x 102 in T/A Curtain Side Trailer S/N: 1N9F532P7X1045092 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, 295/75R22.5 Tires, 66000 lb GVWR Usage: Not Available
		Asset located in: Humble, TX
S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9102	1998 Raven 48 ft T/A Spread Axle Curtain Side Trailer S/N: 1R1F04823WK980200 C/W: Aluminum Frame, Air Ride Suspension, 285/75R24.5 Tires Usage: Not Available
1997 Schaller Manufacturing Roadmaster		Asset located in: Lake Worth, TX
G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS	9103	2024 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX22RG000079 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	9104	2023 Atro 53 ft x 102 in Van Trailer
2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX	9104	S/N: 3ELA6RX28PG000052 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
1999 Timpte 42 ft T/A Belly Dump Grain Trailer		Asset located in: Lake Worth, TX
S/N: 1TDH42224XB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9105	2023 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX24PG003157 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Outer Wheels, 295 /75R22.5 Tires, 68000 lb GVWR Usage: Not Available
2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	S/N: 5TU1140287S000202 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Clam Gate, Push Block, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2003 Trail King BD237 T/A Belly Dump Trailer S/N: 1TKSC40213W101924 C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 1999 Midland MG36CLAM T/A Belly Dump Trailer S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 1997 Schaller Manufacturing Roadmaster G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX 1999 Timpte 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42224KB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 Ib GVWR Usage: Not Available	2007 CTS BDT-40 42 ft T/A Belly Dump Trailer S/N: 5TU1140287S000202 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Clam Gate, Push Block, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2003 Trail King BD237 T/A Belly Dump Trailer S/N: 1TKSC40213W101924 C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GWWR Usage: Not Available Asset located in: Lake Worth, TX 1999 Midland MG36CLAM T/A Belly Dump Trailer S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GWWR Usage: Not Available Asset located in: Lake Worth, TX 1997 Schaller Manufacturing Roadmaster G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GWWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX 1999 Timpte 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42224XB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available

Lot #	Details	Lot #	Details
9106	2023 Vanguard REM VXP 53 53 ft x 102 in T/A Van Trailer S/N: 5V8VC5324PT305207 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	9109	2022 Hyundai VC2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532K6NS852024 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: FRAME IS DAMAGED; Asset located in: Lake Worth, TX 2022 Inland IN53-DPA-HK40 53 ft x 102 in T/A
9106A	2023 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D1PL364744 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires		Van Trailer S/N: 3T9S372N5NM180012 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
2125	Usage: Not Available Notes: . Asset located in: Lake Worth, TX	9111	2021 Inland 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N9MM180044 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof,
9106B	2023 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D7PL364750 C/W: 68000 lb GVWR, Air Ride Suspension, Air		Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Asset located in : Lake Worth, TX
	Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Notes : . Asset located in : Lake Worth, TX	9112	2021 Inland 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N0MM180045 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door Usage: Not Available
9106C	2023 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D3PL364745 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX	9113	Asset located in: Lake Worth, TX 2021 Inland IN53-DPA-HK40 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N7MM180124 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9107	2022 Vanguard MaxCube 53 ft x 102 in T/A Van Trailer S/N: 5V8VA5321NM211220 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9119	2020 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D4LL162426 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275 /80R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN
9108	2022 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX21NG001704 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		YOUR STATE. VERIFY WITH YOUR LOCAL DI PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9120	2019 Great Dane CCC-3314-21053 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0621KJ137637 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9128	2015 Wabash DVHDHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D9FL880526 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Notes:
9121	2019 Utility 53 ft x 102 in T/A Van Trailer	2422	Asset located in: Lake Worth, TX
	S/N: 1UYVS2539K3560164 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN	9129	2015 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D1FL799987 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9130	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer
9122	Asset located in: Lake Worth, TX 2018 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9JR390021 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood		S/N: 1JJV532D3FL845934 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Floor, Swing Door Usage: Not Available	9131	2015 Wabash DVCVHPC 53 ft x 102 in T/A Van
9123	Asset located in: Lake Worth, TX 2018 Stoughton ZGPVW-535T-S-C 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5320JSA09456 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Poof Hardwood Floor Polly In Door		Trailer S/N: 1JJV532DXFL833585 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available	9132	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer
9126	Asset located in: Lake Worth, TX 2015 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D5FL877087 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension,		S/N: 1JJV532DXFL842528 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9136	2012 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9CT100009 C/W: Air Ride Suspension, Sliding Suspension,
9127	2015 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2531FG241727 C/W: 65000 lb GVWR, Aluminum/Steel Combination Frame, Air Ride Suspension, Air	Aluminum Roof, Hardwood Floor, Sw 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
Braki Hard Tires Usag Note AFFII YOUI PRIO	Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9137	2012 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0628CT566670 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9137A	2012 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0628CT567767 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR, Right Weigh Load Scale Usage: Not Available Asset located in: Lake Worth, TX	9145	2008 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS253X8P320087 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06287T539717 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door,
9139	2009 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VA53269M903270 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9147	
9140	2009 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VA532X9M903272 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires		295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2007 Great Dane 7411TP-SA 53 ft x 102 in T/A
	Usage: Not Available Asset located in: Humble, TX		Van Trailer S/N: 1GRAA06247G341628 C/W: Air Ride Suspension, Sliding Suspension,
9141	2008 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53208B027611 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb		Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	GVWR Usage: Not Available Asset located in: Humble, TX		2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06277J622907 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9142	2008 Hyundai 53 ft x 102 in T/A Van Trailer S/N: 3H3V532C18T249117 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, Mixed Tires		
	Usage: Not Available Notes: THE CLOSING TIME OF LOTS 8674 TO 8675 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER OF LOTS 8674 TO 8675 IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS.	9149	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06217J618769 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER Asset located in: Lake Worth, TX	9150	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer
9143	2008 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E95388E520408 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available		S/N: 1GRAA06277D423628 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 30845 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
9144	Asset located in: Lake Worth, TX 2008 Utility 53 ft Van Trailer S/N: 1UYVS25338U340103 Usage: Not Available Asset located in: Lake Worth, TX		THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9151	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06227D423651 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445 /50R22.5 Super Single Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9158	2007 Lufkin TFV-CL-SP 53 ft x 102 in T/A Van Trailer S/N: 1L01A532071163667 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9152	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06287D426747 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 68000 lb GVWR Usage: Not Available	9159	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W07L048317 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door Usage: Not Available Asset located in: Lake Worth, TX
9153	2007 Great Dane 7411TP 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06237D423576 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445	9160	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W37L094904 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	/50R22.5 Super Single Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9161	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W07L051279 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwoor Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9154			
	Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9162	2007 Wabash DVLHHSA 53 ft x 102 in T/A Var Trailer S/N: 1JJV532W37L064138
9155	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06217D423608 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445/50R22.5 Super		C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Single Tires Usage: Not Available Asset located in: Humble, TX		2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W97L079985 C/W: Air Ride Suspension, Sliding Suspension,
9157	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06207J623042		Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	C/W: Air Ride Suspension, Sliding Suspension,	9164	2007 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W27L080010 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9165	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W97L080022 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9173	2006 Lufkin TFV-CL-110 53 ft T/A Van Trailer S/N: 1L01A532461161032 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9167	2006 Wabash 53 ft x 102 in Van Trailer S/N: 1JJV532W76L978391 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9174	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532X61161066 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9167A	2006 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W36L985340 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9175	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Var Trailer S/N: 1L01A532261161062 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR
9168	2006 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS25386G753257 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension,		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9170	Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX 2006 Lufkin TFC-CL-110 53 ft x 102 in T/A Van	9177	2006 Great Dane 7411T-SSL 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06206J610192 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
	Trailer S/N: 1L01A532361161071 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9178	Asset located in: Lake Worth, TX 2006 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532468871342 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9171	2006 Lufkin TFVCL110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532261160929 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9179	2006 Stoughton AVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53266E813926 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available
9172	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532661160948 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9180	Asset located in: Lake Worth, TX 2005 Hyundai 53 ft Van Trailer S/N: 3H3V532C05T169027 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9180A 9181	2005 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W95L938795 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2005 Trailmobile 53 ft x 102 in T/A Van Trailer S/N: 2MN01JAH751003219 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available	9187	2004 Wabash JWHDHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W44L873952 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2004 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W74L873251 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Lake Worth, TX
9182	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06224G332275 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9189	2003 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W23L815529 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
9183	2004 Great Dane 7311TP-S 53 ft x 102 in T/A		Asset located in: Lake Worth, TX
9184	Van Trailer S/N: 1GRAA06274G332238 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2004 Great Dane 7311TP-S 53 ft x 102 in T/A	9191	2003 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06203G327168 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9185	Van Trailer S/N: 1GRAA06244G332231 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2004 Great Dane 7311TP-S 53 ft x 102 in T/A	9191A 9192	2001 Great Dane 53 ft x 102 in T/A Van Traile S/N: 1GRAA06291B078413 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
9100	Van Trailer S/N: 1GRAA06274G332286 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Notes: EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2001 Wabash Unknown 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W41L763639
9186	86 2004 Wabash DVLHHSA 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W74L875727 C/W: Air Ride Suspension, Sliding Suspension,		C/W: Air Ride Suspension, Sliding Suspension, Hardwood Floor, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
	Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX	9193	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W9YL723387 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9194	2000 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0626YB016106 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX 2000 Strick 53 ft x 102 in T/A Van Trailer	9212	2016 Wabash DVCVHPC 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D9GL957237 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1S12E953XYD455230 C/W: 65000.0 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9213	2016 Wabash DVCVHPC 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D1GL957202 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available
9196	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W6YL657722		Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: .	9219	2004 Great Dane 48 ft x 102 in T/A Van Trailer S/N: 1GRAA962X4K262283 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9220	2004 Great Dane 7311TPS 40 ft x 102 in T/A
9197	1998 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532Y4WL427465 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	9220	Van Trailer S/N: 1GRAA80234K262726 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
9199	1997 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532YX4VL387234 C/W: Air Ride Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9221	2001 Great Dane 7311 T S 48 ft x 102 in T/A Van Trailer S/N: 1GRAA96281G318316 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP
9200	1997 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E953XVD412521		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	9222	2000 Trailmobile 48 ft x 102 in T/A Van Trailer S/N: 1PT01JPH0Y8002343 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP
9201	1996 Lufkin TFV-IPST 53 ft x 102 in T/A Van Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1L01A5322T1120913 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9223	2001 Fruehauf 40 ft T/A Van Trailer S/N: 1JJV402F81F732037 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9224	2001 Fruehauf Unknown 40 ft x 102 in T/A Van Trailer S/N: 1JJV402F31F732060 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Lift Gate, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX 1999 Fruehauf 45 ft x 102 in T/A Van Trailer	9239	2020 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281DXLL216433 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Aluminum Roof, Wood and Aluminum Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: 1JJV452FXXF543251 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX		2020 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D5LL216422 C/W: 40000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP	
9231	1995 Strick 48 ft x 102 in T/A Van Trailer S/N: 1S12E9489SD398829 C/W: Air Ride Suspension, Sliding Suspension,		Usage: Not Available Asset located in: Lake Worth, TX	
	Aluminum Roof, hardwood floors with steel plate on top, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9241	2017 Stoughton 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2812HB720243 C/W: Spring Suspension, Pintle Hitch, Hardwood Floor, Side Skirts, Roll-Up Door, R22. 5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	
9232	1995 Pines 48 ft x 102 in T/A Van Trailer S/N: 1PNV482N3SKB67178 C/W: Aluminum Frame, Spring Suspension, Air Brakes, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9243	Asset located in: Rosharon, TX 2017 Wabash DVDBHPC 28 ft x 102 in S/A Variabler S/N: 1JJV281D9HL987165 C/W: Aluminum/Steel Combination Frame,	
9233	1993 Wabash 48 ft x 102 in T/A Van Trailer S/N: 1JJV482Y1PL197966 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires		Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	
	Usage: Not Available Notes: . Asset located in: Humble, TX		S/N: 1DW1A2819EB457745 C/W: Spring Suspension, Air Brakes, Pintle	
9235	1988 Lufkin 48 ft T/A Van Trailer S/N: 1L01A4828J1078828 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, 295/75R22.5 Tires, 65000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-		Hitch, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Trailer	S/N: 1JJV281W29L286194
9236	1985 Budd 45 ft x 102 in T/A Van Trailer S/N: 1BK10W925FE217508 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires		C/W: Spring Suspension, Air Brakes, Pintle Hitch, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in : Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	9245	2008 Great Dane Unknown 28 ft x 102 in S/A Van Trailer S/N: 1GRAA56178K295814 C/W: Spring Suspension, Pintle Hitch, Translucent Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX	

Lot #	Details	Lot #	Details
9251	2002 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F32F778964 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	9259	1988 Trailmobile 28 ft x 102 in S/A Van Trailer S/N: 1PT071NE4J9002630 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Aluminum Floor, Ducted Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9252	1990 Stoughton FRPD-323S 32 ft S/A Generator Trailer	9264	2020 Wabash 53 ft x 102 in T/A Spread Axle Refrigerated Trailer
	S/N: 1DW1A3217LS669202 C/W: Spring Suspension, Pintle Hitch, 295 /75R22.5 Tires, 68080 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1JJV532B4LL218265 C/W: 68000 lb GVWR, Aluminum/Steel Combination Frame, Air Ride Suspension, Air Brakes, Sliding Suspension, Front/Rear Vents, Swing Door, 2008 Thermo King TK486V
9253	1999 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F7XF625530 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available		Refrigeration Unit, Aluminum Wheels, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9265	2020 Utility VS2RA 53 ft x 102 in T/A
9254	1998 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F4WF456405 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Ramp, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX		Refrigerated Trailer S/N: 1UYVS2539L2821820 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Thermo King Precedent Refrigeration Unit, Serial Number 6001278644,, 295/75R22.5 Tires Usage: Not Available
9256	1990 Trailmobile 28 ft x 96 in S/A Van Trailer S/N: 1PT071NE8L9001242 C/W: Aluminum/Steel Combination Frame,		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb		Asset located in: Lake Worth, TX
	GVWR Usage: Not Available	9265A	2019 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer
9257	Asset located in: Lake Worth, TX 1988 TRMO 28 ft x 96 in S/A Van Trailer S/N: 1PT071NE8J9009726 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available		S/N: 1JJV532B6KL090898 C/W: Spring Suspension, Air Brakes, Side Skirts, Ducted Floor, Swing Door, Carrier X4 7500 Refrigeration Unit, Serial Number SAW91536396,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9267	2018 Utility 53 ft x 102 in T/A Spread Axle
9258	1988 Trim 28 ft x 102 in S/A Van Trailer S/N: 1PT071NE1J9006327 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Aluminum Floor, Ducted Floor, Roll-Up Door, 295/75R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Refrigerated Trailer S/N: 1UYVS2536J2076912 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 11R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9268	2018 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XJ6106924 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, Carrier 7300 Refrigeration Unit, Serial Number SAL91508417,, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9274	2016 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2532GU723903 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2016 Thermo King S600 Refrigeration Unit, Serial Number 6001214678,, Aluminum Outer Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: 14,614 Hr Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	9275	2016 Utility VS2RA 53 ft x 102 in T/A	
9269	2018 Utility 53 ft x 102 in T/A Spread Axle Multi-Temp Refrigerated Trailer S/N: 1UYVS2536J2130709 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN			Refrigerated Trailer S/N: 1UYVS2538GU451907 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, 2015 Thermo King 3000R Refrigeration Unit, Serial Number 6001196770,, 295/75R22.5 Tires Usage: 15,487 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9276	2015 Utility Multi Temp 53 ft T/A Refrigerated	
9270	Asset located in: Lake Worth, TX 2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2530HU891122 C/W: Air Ride Suspension, Sliding Suspension,		Trailer S/N: 1UYVS2488FU171108 C/W: 65000 lb GVWR, Aluminum Frame, Spring Suspension Usage: Not Available Asset located in: Lake Worth, TX	
	Side Skirts, Ducted Floor, Swing Door, Thermo King S-600 Refrigeration Unit, Serial Number 6001220977, Aluminum Wheels, 295/75R22.5 Tires Usage: 19,620 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9277	2015 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XFM838425 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Swing Door, Carrier Refrigeration Unit, 295/75R22.5 Tires Usage: 5,800 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV	
9271	2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer		PRIOR TO BIDDING Asset located in: Humble, TX	
	S/N: 1UYVS2538HU767213 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2016 Carrier 7300 X4 Refrigeration Unit, Serial Number RAV91457566,, 275/80R22.5 Tires, 65000 lb GVWR	9278	2015 Great Dane 53 ft Refrigerated Trailer S/N: 1GRAA0625FE701757 Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available	9279	2015 Great Dane ETL-1114-11053 53 ft x 102	
9272	2017 Great Dane FTL-1114-31053 Refrigerated Trailer S/N: 1GRAA0627HB700016 Usage: 14,488 Hr Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; Asset located in: Humble, TX		in T/A Refrigerated Trailer S/N: 1GRAA0624FB702447 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier Vector 6500 Refrigeration Unit, Serial Number NAN9127382,, 295/75R22. 5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9280	2014 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B0EL788928 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2013 Carrier X2 2500APX Refrigeration Unit, Serial Number PAM91348526,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9290	2013 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C5DT512008 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King SB230 Refrigeration Unit, Serial Number 6001128461, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
9281	2014 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532BXEL817674 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Ducted Floor, Swing Door, Thermo King Refrigeration Unit, Serial Number 6001144127, 295/75R22.5 Tires, 68000 lb GVWR Usage: 9,279 Hr Asset located in: Lake Worth, TX	9291	Asset located in: Lake Worth, TX 2012 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537CM264524 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2013 Carrier 2500R Refrigeration Unit, Serial Number NAB91209850,, 295/75R22.5 Tires, 65000 lb GVWR Usage: 13,798 Hr Asset located in: Humble, TX
9282	2014 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B9EL817679 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King Precedent Refrigeration Unit, Serial Number 6001144132,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 29,942 Hr Asset located in: Lake Worth, TX	9292	2012 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C4CT436005 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Roll-Up Door, Thermo King SB230 Refrigeration Unit, Serial Number 6001103448,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
9284	2014 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2533EM974720 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2013 Thermo King SB-230 Refrigeration Unit, Serial Number 6001139179,, 295/75R22.5 Tires, 65000 lb GVWR Usage: 24,105 Hr Asset located in: Lake Worth, TX	9293	Asset located in: Lake Worth, TX 2012 Hyundai 53 ft x 102 in T/A Refrigerated Trailer S/N: 3H3V532C7CT436001 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001103459,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 23,320 Hr Asset located in: Lake Worth, TX
9285	2013 Utility 48 ft Refrigerated Trailer S/N: 1UYVS2481DM771708 Usage: Not Available Asset located in: Lake Worth, TX 2013 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer	9294	2012 Wabash 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B7CL718324 C/W: Spring Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial
	S/N: 3H3V532C3DT256001 Usage: 17,316 Hr Asset located in: Lake Worth, TX		Number NAM91270893,, 295/75R22.5 Tires Usage: 16,367 Hr Asset located in: Lake Worth, TX
9289	2013 Hyundai 53 ft x 102 in T/A Refrigerated Trailer S/N: 3H3V532C8DT512004 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001128459,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 20,603 Hr Asset located in: Lake Worth, TX	9299	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV53CB1CL718268 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial Number NAN91272008,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9302	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0622CW703603 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Side Skirts, Swing Door, Carrier 2100A Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9310	2013 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS248XDM771710 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 6001128316,, 11R22.5 Tires, 65000 lb GVWR Usage: 42,743 Hr Asset located in: Lake Worth, TX
9303	2011 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B7BL330878 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2010 Carrier X2 2500A Refrigeration Unit, Serial Number NAA91203262, Usage: 32,464 Hr Notes: . Asset located in: Lake Worth, TX	9311	2014 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2483EU771503 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001133500,, 11R22.5 Tires, 65000 lb GVWR Usage: 31,576 Hr Asset located in: Lake Worth, TX
9306	2006 Wabash 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532W86L980540 C/W: Spring Suspension, Sliding Suspension, Swing Door, Carrier Refrigeration Unit, 295 /75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9312	2012 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2483CU463504 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2011 Thermo King Smart Reefer 2 Refrigeration Unit, 11R22.5 Tires, 65000 lb GVWR Usage: 48,492 Hr Asset located in: Lake Worth, TX
9307	2015 Great Dane ECM-113 48 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA9622FE702031 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Whisper Refrigeration Unit, Serial Number 6001178338,, 295/75R22.5 Tires Usage: 27,626 Hr Asset located in: Lake Worth, TX		2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2489CU248709 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2013 Thermo King Refrigeration Unit, Serial Number 6001133500,, 295/75R22.5 Tires, 65000 lb GVWR
9308	2014 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2480EU771507 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King Refrigeration Unit, Serial Number 600133514,, 11R22.5 Tires, 65000 lb GVWR Usage: 27,250 Hr Asset located in: Lake Worth, TX		9314
9309	2013 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2480DM567319 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 60011112528,, 11R22.5 Tires, 65000 lb GVWR Usage: 48,998 Hr Asset located in: Lake Worth, TX	9315	Usage: 49,586 Hr Asset located in: Lake Worth, TX 2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS248XCU463502 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2011 Thermo King Refrigeration Unit, Serial Number 6001103816,, 65000 lb GVWR Usage: 50,063 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9316	2001 Great Dane Refrigerated Trailer S/N: 1GRAA06221W001925 Usage: Not Available Asset located in: Lake Worth, TX	9324	2022 20 ft x 8 ft Mobile Office S/N: TJCC22122989 C/W: 12000 BTU Heat and AC Split System, Indoor Breaker Box, R-13 Insulation, 2
9317	1996 Trailmobile 28 ft x 96 in S/A Refrigerated Trailer S/N: 1PT071NE2T9002371 C/W: Spring Suspension, Air Brakes, Ducted Floor, Roll-Up Door, Thermo King Sentry II Max Refrigeration Unit, Serial Number 1145AL6026,, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		windows, Metal Front Door, Security Bars, Security Locks on all Doors, LED Lighting, Wood Trim, Laminated Flooring Storage Room for High Value Tools and Equipment, Charging Dock for Power Tools, Wire Shelving in Store Room Usage: Not Available Asset located in: Lake Worth, TX 28 ft x 8 ft Portable S/A Mobile Office
9318	1995 Trailmobile 28 ft S/A Refrigerated Trailer S/N: 1PT071NE6S9012996 C/W: Spring Suspension, Roll-Up Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available		S/N: Not Available C/W: (2) Offices, Spring Suspension, Sliding Suspension, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9326	28 ft x 8 ft Portable S/A Mobile Office
9319	1993 Great Dane 7011Z-1 28 ft x 102 in S/A Refrigerated Trailer S/N: 1GRAA5614PB081703 C/W: Spring Suspension, Air Brakes, Pintle		S/N: Not Available C/W: (2) Offices, Air Conditioner, Spring Suspension, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	Hitch, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 0132822805,, 11R22.5 Tires, 39000 lb GVWR Usage: Not Available	0007	Asset located in: Lake Worth, TX
		9327	2024 Garper GP8-24 19 ft 8 in x 8 ft 3 in Portable S/A Mobile Office
9320	Asset located in: Lake Worth, TX 1993 Great Dane 7011Z-1 28 ft x 102 in S/A	_	S/N: 3ECG24C1XRGEP0174 C/W: (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 225/75R15 Tires
9020	Refrigerated Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1GRAA5615PB081709 C/W: Spring Suspension, Air Brakes, Roll-Up Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 39000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9328Z 9329	2024 Garper GP8-24 19 ft 9 in x 8 ft 3 in Portable S/A Mobile Office (Unused) S/N: 3ECG24C1XRGEP0175 C/W: (1) Bathrooms, Air Conditioner, Ball
9321	1992 TRMB 28 ft x 96 in S/A Refrigerated Trailer		Hitch, Spring Suspension, 225/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1PT071NE4N9012595 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Thermo King SII-50 MAX Refrigeration Unit, Serial Number 0322628122,, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		36 ft x 12 ft 1 in Portable T/A Mobile Office S/N: 135369 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, 8-14.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9322	2019 Holcombe HM12H Tri/A Volumetric	9330	2025 Atro 40 ft T/A Quantity of (5) Container
	Mixer Trailer S/N: 16MBB3132KF078754 C/W: Spring Suspension, 255/70R22.5 Tires, 75000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 3ELA6CR29SG000287 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 9330 THRU 9335 ARE TIED TOGETHER. IF A BID IS
9323	2024 44 ft x 12 ft 1 in Portable Tri/A Mobile Office S/N: 102410 C/W: (2) Offices, (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 8- 14.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9330A	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR21SG000302 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 9330 THRU 9335 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER	9351	2023 Kerr-Bilt 40 ft Container Trailer S/N: 1J9GC402XPB253228 C/W: Aluminum Frame, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
		9352	2011 Dragon T/A Roll-Off Trailer S/N: 1D9SH4824BC661799 C/W: 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9353	2008 Dragon TCT440 T/A Roll-Off Trailer
9334	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR21SG000297 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR	S/N: 1UNSH48288C066531 C/W: Air Ride Suspension, Alu 285/75R24.5 Tires, 80000 lb G Usage: Not Available	C/W: Air Ride Suspension, Aluminum Wheels, 285/75R24.5 Tires, 80000 lb GVWR
	Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 9330 THRU 9335 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER	9354	2000 ESPM TCT1101 T/A Roll-Off Trailer S/N: 1E9RS4823Y1229101 C/W: Air Ride Suspension, Aluminum Wheels, 285/75R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9356	2023 MaxxD RPX8316G T/A Roll-Off Trailer
9335	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR22SG000292 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available		(Unused) S/N: 5R8GR1625PM105017 C/W: Spring Suspension, Electric Brakes, 215 /75R17.5 Tires, 19200 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE CLOSING TIMES OF LOTS 9330 THRU 9335 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX	9357	2023 Texas Pride RO71618KGN T/A Roll-Off Trailer S/N: 7HCGD1626PB039384 C/W: 18000 lb GVWR, Spring Suspension, Electric Brakes, Electric Roll Tarp, 215/75R17.5 Tires Usage: Not Available
9346	2024 Atro 53 ft T/A Container Trailer (Unused)		Asset located in: Lake Worth, TX
	S/N: 3ELA6CX24RG000212 C/W: Spring Suspension, Sliding Suspension, 53 ft - Container Pins, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9358	2016 Texas Pride Tri/A Gooseneck Roll-Off Trailer S/N: 1B973HGD9GB624110 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 7.50R16 Tires, 24000 lb GVWR
9347	2023 Horizon 40 ft T/A Container Trailer (Unused)		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 3H7KC402XPR000334 C/W: Spring Suspension, 40 ft - Container Pins, 11R22.5 Tires, 50000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9359 2016 Texas Pride T/A Roll-Off S/N: 1B9G2DGD1GB624162 C/W: Spring Suspension, Elect Electric Roll Tarp, 235/80R16	2016 Texas Pride T/A Roll-Off Trailer
9350	2023 GRUPO 15 ft 8 in T/A Container Trailer S/N: 3BZPN402XPC008328		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 65000 lb GVWR, Air Ride Suspension, 295 /75R22.5 Tires Usage: Not Available Asset located in: Midland, TX	9360	1996 T/A Roll-Off Trailer S/N: 1B9B14526TB183122 C/W: Air Ride Suspension, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9361	1987 G & H T/A Roll-Off Trailer S/N: 87080757 C/W: Spring Suspension, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9372	S/A BBQ trailer S/N: Not Available C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, Two benches with storage Usage: Not Available
9362	2023 Diamond Cargo T/A 20' Concession Trailer S/N: 53NBE2020P1101295 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9990 lb GVWR, Side Entry Door Usage: Not Available		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9373	2018 Wylie EXP500S Water Tank Trailer S/N: 63510 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9375	2016 CZ Engineering Pole Trailer S/N: 4CZPR2717G113G030 C/W: Lunette Ring Hitch, Air Ride Suspension,
9365	2022 FUD Concessions Trailer S/N: 3F9F1A329NM066595 C/W: Ball Hitch, Spring Suspension, 195R15C Tires	9376	Electric Brakes, 2 Stanchions, 215/75R17.5 Tires Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2014 Bat 35TA Pole Trailer S/N: 1B9FB35264A439L69 C/W: 22400 lb GVWR Lunette Ring Hitch, Spring Suspension, Electric Brakes, 4 Stanchions, 235/80R16 Tires
9367	2023 Freedom 8.5x28TA4G T/A Graco Spray Foam Trailer S/N: 5WKGE2829P1078616 C/W: 14000 lb GVWR, Torsion Axle, Electric	9376A	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Brakes, 235/80R16 Tires Usage: Not Available Asset located in : Lake Worth, TX		2007 Butler Pole Trailer S/N: 1BUP3020871003684 C/W: Lunette Ring Hitch, Spring Suspension,
9369	2018 ED Trailers T/A Cooling Trailer S/N: 3A9BD1829J7266191 C/W: Ball Hitch, Walking Beam Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb		Electric Brakes, 3 Stanchions, 9.50x16.5 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	GVWR Usage: Not Available Asset located in : Lake Worth, TX	9376B	2001 Pole Trailer S/N: 1U9CL47401A001680 C/W: Lunette Ring Hitch, Torsion Axle, Electric
9370	2012 Texas Bragg T/A Cooling Trailer S/N: 17XFT162XC1026523 C/W: Ball Hitch, Walking Beam Suspension,		Brakes, 3 Stanchions, 235/85R16 Tires Usage: Not Available Asset located in : Lake Worth, TX
	Electric Brakes, 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9379	2024 Silverback 45CHGN3 Tri/A 3 Car Open Car Carrier Trailer S/N: 4S9GC4535RH623425 C/W: Spring Suspension, 235/85R16 Tires Usage: Not Available
9371	2019 Cargo Craft T/A Splicing Trailer S/N: 4D6EB1225KC054750 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9380	Asset located in: Humble, TX 2025 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2121ST012579 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9383	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1920HA988585 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX	9389	2024 MaxxD DTX8316 16 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1620RM116972 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 215/75R17.5 Tires, 16000 lb GVWR
9384	2017 Demco AT7000P T/A 1 Car Open Car		Usage: Not Available Asset located in : Lake Worth, TX
	Carrier Trailer S/N: 15DPC1927HA989006 C/W: Spring Suspension, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9390	2024 STL Industrial 16 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1629RM336009 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 12800 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9385	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1927HA988910 C/W: Aluminum Frame, Ball Hitch, Surge Brakes, Soft Ties, 225/75R15 Tires, 5000 lb GVWR, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	9391	2024 MaxxD D9X9616 16 ft Tri/A Dump Utility Trailer (Unused) S/N: 5R8BD1637RM116735 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 21000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	PROCESS TITLE Asset located in: Lake Worth, TX	9392	2022 Big Tex 16 ft T/A Dump Utility Trailer
9386	2017 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1926HA989031 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: 16V1D2122N5116206 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 98 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9386A	· · · · · · · · · · · · · · · · · · ·	9393	2016 Texas Made DT71616KBP 16 ft T/A
	Utility Trailer S/N: 4P5DD2029K1311819 C/W: Spring Suspension, 97 in Deck Width, Steel Decking, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Asset located in: Midland, TX	Dump Utility Trailer S/N: 59JT1DG22GD595839 C/W: Ball Hitch, Spring Susp Brakes, 81 in Deck Width, 86 Steel Decking, 235/85R16 Ti GVWR, EQUIPMENT-FROM-A SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTEI THE INSPECTION REPORT Asset located in: Humble, TX 9394 2025 Southland SL714-14K ** Utility Trailer (Unused) S/N: 2SFJL3362S1120875 C/W: Ball Hitch, Spring Susp Brakes, 82 in Deck Width, 87 Steel Decking, 235/80R16 Ti GVWR Usage: Not Available	S/N: 59JT1DG22GD595839 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 86 in Overall Width, Steel Decking, 235/85R16 Tires, 12000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
9387	2016 Texas Made 22 ft T/A Dump Utility Trailer S/N: 59JT1DG22GD595842 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 85 in Overall		Notes: DEFICIENCIES NOTED - PLEASE SEE
	Width, Steel Decking, 215/75R17.5 Tires, 12000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		· · · · · · · · · · · · · · · · · · ·
9388	2024 East Texas 16 ft T/A Dump Utility Trailer S/N: 58SBD1625RE038870 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX		Steel Decking, 235/80R16 Tires, 15432 lb GVWR

Lot #	Details	Lot #	Details
9395	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1120873 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9402	2025 Southland SL714-14K 14 ft S/A Dump Utility Trailer (Unused) S/N: 2SFJL3361S1120883 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9396	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1116826 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9403	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3364S1120876 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9397	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL336XS1120655 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9404	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1116823 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9398	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116824 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9405	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1118976 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9399	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3363S1120884 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9406	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1120405 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9400	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3360S1116825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9407	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118932 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9401	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3366S1120877 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9408	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3360S1115257 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9409	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3366S1118924 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9415	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118980 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9410	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3364S1118923 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9416	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer S/N: 2SFKL4368S1113438 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9411	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3368S1118925 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9417	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4366S1113437 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 88 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9412	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4364S1113436 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9418	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1116854 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9413	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4362S1113435 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9419	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116855 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9414	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3367S1118981 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9420	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3360S1116856 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	 Details
9421	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3365S1116853 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9427	2024 Maxey Maxx-D DKX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1420RM116473 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9422	2025 Industrias America 7014R 14 ft T/A Dump Utility Trailer S/N: 3EZBTC14XSA003766 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9428	2024 MaxxD D9X9614 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1428RM116057 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9429	2024 MaxxD DKX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1424RM116489 C/W: Ball Hitch, Spring Suspension, Electric
9423	2025 MaxxD DTX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1421SM118478 C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum		Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in : Lake Worth, TX
9424	Flooring, 215/75R17.5 Tires, 17500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2025 Maxey MaxxD 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1420SM117659 C/W: Ball Hitch, Spring Suspension, Electric	9432	2025 MaxxD DTX8312 T/A Utility Trailer (Unused) S/N: 5R8BD1221SM118015 C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		2025 Industrias America FT510 10 ft T/A Dump Utility Trailer S/N: 3EZBTC10XSA004056 C/W: Ball Hitch, Spring Suspension, Electric
9425	2024 MaxxD DTX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD142XRM116741 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR		Brakes, 59 in Deck Width, 78 in Overall Width, Steel Decking, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9434	2025 Industrias America FT510 10 ft T/A Dump Utility Trailer
9426	2024 ED Trailers 14 ft T/A Dump Utility Trailer S/N: 3LHBS1423R7000182 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 84 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 3EZBTC105SA004059 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 59 in Deck Width, 77 in Overall Width, Steel Decking, 235/75R16 Tires, 7000 lb GVWF Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9437 9437A	2014 Interstate 40 ft T/A Tilt Deck Trailer S/N: 1JKGTL605EM012923 C/W: Spring Suspension, Deck Over Tires, 24 ft 5 in Deck Tilting Length, 102 in Deck Width, 245 /70R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX Maxey T/A Gooseneck Hydraulic Tail Trailer	9443	9443 2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP225SA004019 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Spring Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, Hydraulic Jacks Usage: Not Available Asset located in: Lake Worth, TX		2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP223SA004021 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available
9438	2023 HD 30 ft T/A Tilt Deck Trailer S/N: 7LKH3AL2XPP001032 C/W: 16500 lb GVWR, Spring Suspension, Electric Brakes, Storage Compartments, Deck Over Tires, 97 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9445	Asset located in: Lake Worth, TX 2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP221SA004020 C/W: Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires,
9439	2021 Delco 24 ft T/A Tilt Deck Trailer S/N: 5WWGC2422M6016631 C/W: Torsion Axle, Electric Brakes, 24 ft Deck	9446	14000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
0440	Tilting Length, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP225SA004022 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9440	2019 Big Tex 22 ft T/A Tilt Deck Trailer S/N: 16VEX222XK2093519 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft 9 in Deck Tilting Length, 75 in Deck Width, 215/75R17.5 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9447	2023 Big Tex 20 ft T/A Tilt Deck Trailer S/N: 16V1C252XP2271331 C/W: Ball Hitch, Spring Suspension, 16 ft Deck Tilting Length, 72 in Deck Width, 235/80R16 Tires Usage: Not Available
9441	2017 Felling 22 ft T/A Tilt Deck Trailer S/N: 5FTCE2923H1002738 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Deck Tilting Length, 82 in Deck Width, 215/75R17.5 Tires, 19120 lb GVWR	9448	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2015 Butler 20 ft T/A Tilt Deck Trailer S/N: 1BUD18202F1007915
9442	2025 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2125ST012570 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 78 in Deck Width, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9449	2015 Towmaster 16 ft T/A Tilt Deck Trailer S/N: 4KNTT162XFL160923 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Winch, 16 ft Deck Tilting Length, 82 in Deck Width, 235/85R16 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2025 Double A 12 ft S/A Tilt Deck Trailer	9454	2019 Interstate 50DLA 30 ft Tri/A Equipment Trailer S/N: 1JKDLA500KM016883 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 24 ft Main Deck, 6 ft 2 in Fixed Dovetail, 96 in Usable Deck Width, 101 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires, 60100 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: 1UFBU1219ST012572 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 12 ft Deck Tilting Length, 79 in Deck Width, 225/75R15 Tires, 5200 lb GVWR, 2" Adjustable Bulldog Style Coupler, 2000# Set Back Jack, 7 Way Plug And Wiring, Sealed LED Lights, Diamond Plate Fenders, 6 Stake pockets, 2" Treated Lumber Floor, Safety Chains, Spare Rack Usage: Not Available	9455	2001 Phelan 25TA-D 25 ton 29 ft Tri/A Equipment Trailer S/N: 40FR0303113020550 C/W: Lunette Ring Hitch, Spring Suspension, 24 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 60540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9456	2008 Towmaster 25 ft T/A Equipment Trailer S/N: 4NKTF20298L163620 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail,
9450A	S/N: 16982 C/W: Lunette Ring Hitch, Walking Beam Suspension, Deck Over Tires, 18 ft Deck Tilting Length, 96 in Deck Width, 8.25R15 Tires Usage: Not Available		101 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235 /85R16 Tires Usage: Not Available Asset located in : Lake Worth, TX
		9457	2016 Load Trail 42 ft Tri/A Gooseneck Equipment Trailer
9451	2018 PJ Trailers 20 ft T/A Equipment Trailer S/N: 4P5L52025J1284500 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 101.5 in Usable Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE		S/N: 4ZEGC4031G1100325 C/W: Spring Suspension, Electric Brakes, 40 ft 4 in Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, 101.5 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 235/80R16 Tires, 24990 lb GVWR Usage: Not Available Asset located in: Midland, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX	9458	2025 X-STAR 40 ft T/A Gooseneck Equipment Trailer (Unused)
9452	2007 B.A.T. Custom Trailers 35 ft T/A Gooseneck Equipment Trailer S/N: 1B9E???267A439M49		S/N: 1X9T3GS28SH039957 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available
	C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 96 in Usable Deck Width, 102 in	0.450	Asset located in: Lake Worth, TX
	Overall Deck Width, Deck Over Tires, Wood Flooring, 215/75R17.5 Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9459	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4025SM119348 C/W: Air Ride Suspension, Electric Brakes, 34 ft 11 in Main Deck, 5 ft 9 in Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted
9453	1995 Norris 40 ft T/A Gooseneck Flatbed Trailer S/N: 1N9FS4023SC007555 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Ramps, Wood Flooring, 215/75R17.5 Tires, 25990 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9460	2024 RAWMAXX FDX-40-27K 40 ft T/A Gooseneck Equipment Trailer S/N: 3EVGF4027R1109090 C/W: Spring Suspension, Electric Brakes, 34 ft 6 in Main Deck, 6 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/85R16 Tires, 14000 lb GVWR	9467A	2022 PJ Trailers 3F492 40 ft T/A Equipment Trailer S/N: 4P53F4924N1364159 C/W: 25900 lb GVWR, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Midland, TX
	Usage: Not Available Asset located in : Midland, TX	9469	2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer
9461	2024 Horizon 40 ft T/A Gooseneck Equipment Trailer S/N: 3H7GF4022RR001350 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235		S/N: 4ZEGH4023J1155164 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 101 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available
	/85R16 Tires		Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Midland, TX	9470	2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer S/N: 4ZEGH4021J1162680
9464	2023 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4025PM101424 C/W: Spring Suspension, Electric Brakes, 34 ft 11 in Main Deck, 5 ft 9 in Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires, 25990 lb GVWR Usage: Not Available		C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		9471	2009 Maxey 40 ft T/A Gooseneck Equipment Trailer
9465	Asset located in: Lake Worth, TX 2023 Delco 40 ft T/A Gooseneck Equipment Trailer S/N: 5WWGF4023P6029756 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires Usage: Not Available		C/W: Spring Suspension, El Main Deck, 5 ft Fixed Dovet Deck Width, 102 in Overall I Ramps, Wood Flooring, 225 20000 lb GVWR Usage: Not Available
	Asset located in: Midland, TX	9472	2017 Texline 35' GNI/D 35 ft T/A Gooseneck
9466	2023 HD Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 7LKH3AP29PP000996 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available] - 112	Equipment Trailer S/N: 5HNGN352XH1000107 C/W: Spring Suspension, Electric Brakes, 30 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9473	2012 Texas Bragg 35 ft T/A Gooseneck
9467	2023 Trailmaxx 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H4027TM000406 C/W: 12000 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Midland, TX		Equipment Trailer S/N: 17XFG3528C1024464 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

	Dataila	1 0+ #	Detaile
Lot # 9474	Details 2009 Texas Bragg 35 ft T/A Gooseneck	Lot # 9479	Details 2001 HaWN 30 ft T/A Gooseneck Equipment
	Equipment Trailer S/N: 17XFG352791093459 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 92 in Usable Deck Width, 102 in Overall Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 1H9GN302911176001 C/W: Spring Suspension, Electric Brakes, 25 f Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Spring Assisted Ramps, Wood Flooring, 215/75R17. Tires Usage: Not Available Notes: SELLING WITH AN SPI (FORM VTR-27 AND MAY NOT BE ACCEPTED IN YOUR STAT VERIFY WITH YOUR LOCAL DMV PRIOR TO
9475	2025 MaxxD LDX10232 32 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 5R8GF3227SM117723		BIDDING Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 6 ft 1 in Fixed Dovetail, 93 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9480	2015 Kearney 28 ft Tri/A Gooseneck Equipment Trailer S/N: 5LCFT2830F1037125 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 4 ft Fixed Dovetail, 82 in Usable Deck Width, Hydraulic Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available
9476	2023 Big Tex 16GN-25BK+5MR 30 ft T/A Gooseneck Equipment Trailer		Asset located in: Lake Worth, TX
	S/N: 16V3F3828P6255347 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9481	2025 Double A 26 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1UFGN2624ST012569 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available
9477	2020 Sure-Pull 30 ft T/A Gooseneck Equipment Trailer		Asset located in: Lake Worth, TX
	S/N: 1J9DG3024LJ143049 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 101 in Usable Deck Width, 101 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9482	2024 Golden Arm 25 ft T/A Gooseneck Equipment Trailer S/N: 7S8GF2526RM000313 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft 6 in Fixed Dovetail, 94 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9483	2012 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer
9478	2013 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer S/N: 16VGX2527D2674032 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22400 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		S/N: 16VGX2521C2632812 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22500 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9484	2009 Starlite 25TAGN 25 ft T/A Gooseneck Equipment Trailer S/N: 13YFS25269C113505 C/W: Spring Suspension, 20 ft Main Deck, 5 ft 2- Position Dovetail, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Lake Worth, TX	9489	2020 Sure-Trac 23 ft T/A Equipment Trailer (Inoperable) S/N: 5JW2U2320L3262538 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 7 ft 6 in Upper Deck, 12 ft 4 in Main Deck, 3 ft 6 in Fixed Dovetail, 79 in Usable Deck Width, 79 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
9485	2023 East Texas 24 ft T/A Gooseneck Equipment Trailer S/N: 58SGM2424PE036183 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 102 in Usable Deck Width, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9490	THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX 2014 Kaufman 23 ft T/A Equipment Trailer S/N: 5SHFP2329EB001257 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 5 ft Fixed
9486	2025 Salvation 20 ft T/A Equipment Trailer (Unused) S/N: 7GG1U2022SW023510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Main Deck, 3 ft Fixed Dovetail, 82 in Usable Deck Width, 102 in Overall Deck		Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9487	Width, Manual Ramps, Wood Flooring, 225 /75R15 Tires, 10400 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2023 Maxey XX-D 26 ft T/A Equipment Trailer	9491	2025 Southland LBATR7-22 22 ft Tri/A Equipment Trailer (Unused) S/N: 2SFHL4463S1120662 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 2 ft Fixed Dovetail, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 21043 lb GVWR Usage: Not Available
	S/N: 5R8BC2627PM106865 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9492	Asset located in: Lake Worth, TX 2023 Maxey T/A 40 Ft Tilt Deck Trailer S/N: 5R8BC2226PM099011 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Electric Powered Self Contained Hydraulic System, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9488	2002 Parker 24 ft T/A Equipment Trailer S/N: 13ZPF242121003713 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 18 ft 10 in Main Deck, 5 ft 2 in Fixed Dovetail, 85 in Usable Deck Width, 91 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/85R16 Tires, 22000 lb GVWR	9493	2022 Norstar 22 ft T/A Equipment Trailer S/N: 3EUGB2221N1011572 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Fixed Dovetail, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9494	2025 Southland LBATR7-20 20 ft Tri/A Equipment Trailer S/N: 2SFHL4464S1120265 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9495	2025 Southland LBATR7-20 20 ft Tri/A Equipment Trailer S/N: 2SFHL4462S1120264 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9501	2018 Big Tex 14ET-20BK-MR 20 ft T/A Equipment Trailer S/N: 16VEX2024J2005825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft 6 in Main Deck, 3 ft 6 in Fixed Dovetail, 84 in Usable Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Midland, TX
9496	2025 Salvation Trailers 20 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 7GG3U2022SW023483 C/W: Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 82 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9502	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC331XS1121177 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9497	2025 X-STAR 20 ft T/A Equipment Trailer (Unused) S/N: 1X9T7GF21SH039958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 97 in Usable Deck Width, 101 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR, 2 in x 8 in Treated Lumber Floor, 7k Axles Usage: Not Available Asset located in: Lake Worth, TX	9503	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3318S1121176 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9498	O25 Double A 20 ft T/A Equipment Trailer Inused) (N: 1UFBU2029ST012573 (W: Ball Hitch, Spring Suspension, Electric rakes, 20 ft Main Deck, 0 ft Dovetail, 83 in sable Deck Width, 102 in Overall Deck Width, anual Ramps, Wood Flooring, 235/85R16 res, 14000 lb GVWR, 6" Channel Frame, 6" rap Tng, 3" Channel Cross Members, 2- 000# Axles, 1 Brake 2-5/16 Coupler, 5' Slide in	9504	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3313S1121179 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Ramps, 2' Dovetail, All LED Lighting, 10-Ply on 8 Hole Silver Mod, 12k Drop Leg Jack, Diamond Plate Fenders Usage: Not Available Asset located in: Lake Worth, TX	9505	2025 Double A 18 ft T/A Equipment Trailer (Unused) S/N: 1UFBU1827ST012571 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 77 in Usable Deck
9499	2025 Double A 20 ft T/A Equipment Trailer (Unused) S/N: 1UFBU2026ST012580 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Width, 96 in Overall Deck Width, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR, 2" Bulldog Style Coupler, Brake and EBA, 5' Slide In Ramps Out Back, 2' Diamond Plate Dovetail, 2000# Set Back Jack, Safety Chains, Wiring and Flush Mount LED lights, ST205/75R15 5 on 5 silver mod, Diamond Plate Fenders, 2" Treated Lumber Floor, Stake pockets and Rub rail, Spare Rack Usage: Not Available
9500	2022 East Texas 20 ft T/A Equipment Trailer S/N: 58SBM202XNE030305 C/W: Spring Suspension, 20 ft Main Deck, 96 in Usable Deck Width, 101 in Overall Deck Width, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9506	2025 Double A 18 ft T/A Equipment Trailer (Unused) S/N: 1UFBU1822ST012574 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 77 in Usable Deck Width, 96 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR, HDCH, 6" Channel Frame, 6" Wrap Tng, 3" Channel Cross Members, 2-7000# Axles, 1 Brake 2-5/16 Coupler, 5' Slide in Ramps, 2' Dovetail, All LED Lighting, 10-Ply on 8 Hole Silver Mod, 12k Drop Leg Jack, Diamond Plate Fenders Usage: Not Available	9512 9513	2018 MMDI 614SLTD 14 ft T/A Equipment Trailer S/N: 5631F2024JM001703 C/W: Torsion Axle, 14 ft Main Deck, 5 ft 2 in Dovetail, 70 in Usable Deck Width, 97 in Overall Deck Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2017 MMDI 7 ft S/A Equipment Trailer	
	Asset located in: Lake Worth, TX		S/N: 5631F1419HM017255 C/W: Ball Hitch, Spring Suspension, Surge	
9508	2025 Southland LBAT7-16 16 ft T/A Equipment Trailer S/N: 2SFJL336XS1116038 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, 102 in Overall		Brakes, 7 ft Main Deck, 48 in Usable Deck Width, Manual Ramps, Steel Decking, 225 /75R15 Tires Usage: Not Available Asset located in : Lake Worth, TX	
	Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9514	2016 Pratt CP0510 10 ft T/A Equipment Trailer S/N: 1P9UT1722GN343532 C/W: Torsion Axle, Surge Brakes, 60 in Usable Deck Width, Deck Over Tires, Manual Ramps, Steel Decking, 205/75R15 Tires	
9509	2024 MaxxD H5X10216 16 ft T/A Equipment Trailer (Unused) S/N: 5R8BC1625RM116789 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Main Deck, 2 ft 2 in Fixed		Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	
	Dovetail, 82 in Usable Deck Width, 97 in Overall Deck Width, Manual Ramps, Wood Flooring, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9515	1998 Interstate 18 ft T/A Equipment Trailer S/N: 1JK0DT202WA001000 C/W: Spring Suspension, Air Brakes, 18 ft 9 in Main Deck, 5 ft Fixed Dovetail, 91 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available	
9510	2021 Buck Dandy 16 ft T/A Equipment Trailer	9516	Asset located in: Lake Worth, TX	
9511	S/N: 4DHCS2028MS047369 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 225/75R15 Tires, 10400 Ib GVWR Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 1N9FS2 C/W: Spring 9 Main Deck, 5 Deck Width, 9	S/N: 1N9FS252XSC007758 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 91 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood
9511	2013 Felling FT-10P 16 ft T/A Equipment Trailer S/N: 5FTPH1626D1042166 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 79 in Usable Deck Width, Manual Ramps, Steel Decking, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Flooring, 235/85R16 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
		9516A	1991 Belshe 20 ft T/A Equipment Trailer S/N: 16JF01827M1021861 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Decking, 225/90R16 Tires Usage: Not Available Asset located in: Midland, TX	
		9517	1998 SHIRLEY FB 12 ft T/A Utility Trailer S/N: 4XMFS1220WL000008 C/W: Ball Hitch, Spring Suspension, 77 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 10000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9520	2022 Salvation Trailers 20 ft T/A Utility Trailer S/N: 7GG1U2021NW019503 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 88 in Deck Width, Wood Flooring, 235 /80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9525	2013 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2029DB053351 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	
9521	2018 Texline 20 ft T/A Utility Trailer S/N: 7HACU2025J1000949 C/W: Spring Suspension, Electric Brakes, 79 in Deck Width, 102 in Overall Width, Wood Flooring, 215/75R17.5 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9525A	2012 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFT2026C1020393 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 97 in Overall Width, Wood Flooring, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	
9522	2018 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2021JB069894 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	9526	Asset located in: Lake Worth, TX 2011 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2026B1014824 C/W: Ball Hitch, Spring Suspension, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 225 /90R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
9523	Asset located in: Lake Worth, TX 2018 Kearney 20 ft T/A Utility Trailer S/N: 5LCLB2023J1047150 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 101 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS	9527	2025 Double A 18 ft T/A Utility Trailer (Unused) S/N: 1UFBU1828ST012577 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Wood Flooring, 225 /75R15 Tires, 9995 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
9524	SECTION BELOW Asset located in: Lake Worth, TX 2018 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2029JB069898 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION	9528	S/N: 5RVUT1823EM017580 C/W: Ball Hitch, Spring Suspension Brakes, 82 in Deck Width, 102 in Ov Wood Flooring, 235/80R16 Tires, E FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS
	Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		SECTION BELOW Asset located in: Lake Worth, TX 2014 CM 18 ft T/A Tilt Deck Trailer S/N: 5VNBU1821ET121130	
9524A	2014 PJ 20 ft T/A Utility Trailer S/N: 4P5P82022E1215956 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 235/85R16 Tires		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in : Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	9530	2008 Big Tex 18 ft T/A Utility Trailer S/N: 16VPX182381320591 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, 90 in Overall Width, Wood Flooring, 235/85R16 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available	

Lot #	Details	Lot #	Details
9532	2005 Cortex 18 ft T/A Utility Trailer S/N: WCC108217 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Wood Flooring, 235 /85R16 Tires, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE	9541	2020 Pratt EZ-1480S 14 ft T/A Tilt Deck Trailer S/N: 1P9UT1425LN343409 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Electric Powered Self Contained Hydraulic System, 14 ft 10 in Deck Tilting Length, 79 in Deck Width, 235/85R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		2024 STL Industrial 12 ft Hydraulic Drop Deck Ground Load Trailer (Unused)
9533	2004 Cortex 18 ft T/A Utility Trailer S/N: WCC108200 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available		S/N: 4B9BZ1220SM336008 C/W: Ball Hitch, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	9543	2018 Barreto 6 ft S/A Trencher Trailer S/N: 1B9UC0616DL280544 C/W: Torsion Axle, 5.30-12 Tires Usage: Not Available Asset located in: Lake Worth, TX
9534	2002 Diamond Pacesetter 18 ft T/A Utility Trailer S/N: 46UFU182721078242 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes:	9544	2018 Barreto 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0612JL280312 C/W: Aluminum Frame, Ball Hitch, 6 ft 3 in Deck Tilting Length, 45 in Deck Width, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9535	Asset located in: Lake Worth, TX 2017 Top Hat 16 ft T/A Utility Trailer S/N: 4R7BU1625HT167477 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Wood Flooring, 205 /75R15 Tires, 6000 lb GVWR, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9545	2019 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA29KU036221 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Side Door 225 /75R15 Tires, 7000 lb GVWR, Interior Racking Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	9546	2015 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA23FA018790
9537	2025 Double A 14 ft S/A Utility Trailer (Unused) S/N: 1UFBU1418ST012575 C/W: Ball Hitch, Spring Suspension, 83 in Deck Width, 102 in Overall Width, Ramp, Wood Flooring, 205/75R15 Tires, 2995 lb GVWR, Pipe	9547	C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Midland, TX
	Top, 2" BD Coupler, All LED Lighting, 2k Set Back Jack, Diamond Plate Fenders, Treated Lumber Floor, Stake Pockets, Spare Rack, 2' Exp Dovetail, 2' Gate Usage: Not Available Asset located in: Lake Worth, TX		2015 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA21FA018786 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR
9540	2019 Pratt EZ-1980 19 ft T/A Tilt Deck Trailer S/N: 1P9UT1929KN343758 C/W: Ball Hitch, Electric Brakes, Electric Powered Self Contained Hydraulic System, 19 ft Deck Tilting Length, 69 in Deck Width, 225 /90R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
9548	2025 Southland LARCT52-826V-86 26 ft T/A Enclosed Trailer (Unused) S/N: 2SFPL636XS1120196 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9554	2025 Southland LARCT52-820F-86 20 ft T/A Enclosed Trailer S/N: 2SFFK4310S1118271 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9549 9550	2025 Southland LARCT52-826V-86 25 ft T/A Enclosed Trailer S/N: 2SFPK5313S1118257 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2017 Forest River 24 ft T/A Enclosed Trailer	9555	2017 Cargo Craft Expedition 20 ft T/A Enclosed Trailer S/N: 4D6EB2021HC046825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 102 in Overall Width, 235/80R16 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX
3000	S/N: 5NHUVHZ24HY029016 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 98 in Deck Width, 101 in Overall Width, Side Door 225/75R16 Tires, 9800 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Midland, TX		2025 Southland LCHT35-718V-86 18 ft T/A Enclosed Trailer S/N: 2SFFL4367S1120950 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9551	2025 Southland LARCT52-822V-86 22 ft T/A	9557	Asset located in: Lake Worth, TX
	Enclosed Trailer S/N: 2SFPK4318S1120466 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2014 Haulmark 18 ft T/A Enclosed Trailer S/N: 575GB1821ET265892 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9552	2025 Southland LARCT52-822V-86 21 ft T/A Enclosed Trailer S/N: 2SFPK4310S1118274 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Ramp, Side Door Aluminum Wheels, 225 /75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2014 Haulmark 18 ft T/A Enclosed Trailer S/N: 575GB1823ET265909 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9553	2025 Southland LARCT52-820F-86 20 ft T/A Enclosed Trailer S/N: 2SFPK5365S1118272 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9559	Asset located in: Lake Worth, TX 2014 Haulmark 18 ft T/A Cooling/Heating station Enclosed Trailer S/N: 575GB1826ET265922 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: 8,663 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9560	2014 Haulmark 18 ft T/A Cooling/Heating station Enclosed Trailer S/N: 575GB1828ET265923 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/85R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9566	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3365S1112775 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR
9561	2018 Lark 17 ft T/A Enclosed Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 571BE1626JM030477 C/W: Ball Hitch, Spring Suspension, 80 in Deck Width, 102 in Overall Width, Ramp, Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9567	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer S/N: 2SFFH3313S1118418 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7815 lb GVWR Usage: Not Available
9562	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer (Unused)		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	S/N: 2SFFH331XS1120960		Asset located in: Lake Worth, TX
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 84 in Overall Width, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9569	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer S/N: 2SFFL4368S1120956 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR
9563	2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3363S1118428 C/W: Ball Hitch, Spring Suspension, Electric		Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2022 Rock Solid Cargo 16 ft T/A Enclosed Trailer S/N: 7H2BE1626ND044095 C/W: 7000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 84 in Overall Width, Side Door 205/75R15 Tires Usage: Not Available
9564	2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3365S1118429		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2020 Carry-On 7X16 16 ft T/A Enclosed Trailer S/N: 4YMBC1621LT010101 C/W: Walking Beam Suspension, Electric Brakes, 74 in Deck Width, 83 in Overall Width, 225/75R15 Tires, 9990 lb GVWR, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
9565	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL336XS1120371 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11709 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9571	2020 Carry-On 16 ft T/A Enclosed Trailer S/N: 4YMBC1627LT038050 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 78 in Deck Width, 86 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7000 lb GVWR, Interior Racking; EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Humble, TX	9577	9577 2025 Southland LCHT35-614V-78 14 ft Enclosed Trailer S/N: 2SFFL2369S1120937 C/W: Ball Hitch, Torsion Axle, Electric B 69 in Deck Width, 92 in Overall Width, R Side Door 205/75R15 Tires, 7716 lb GV Usage: Not Available	S/N: 2SFFL2369S1120937 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 69 in Deck Width, 92 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9572	2013 CM Trailers 16 ft T/A Enclosed Trailer		Asset located in: Lake Worth, TX	
	S/N: 49TCB1621D1009364 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 79 in Deck Width, 80 in Overall Width, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; Asset located in: Lake Worth, TX	9578	2018 Interstate 14.5 ft T/A Enclosed Trailer S/N: 1UK500F28J1095011 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	
9573	2013 Lark United 7X16 16 ft T/A Enclosed	1	TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	Trailer S/N: 5RTBE1628DD034600 C/W: Walking Beam Suspension, 78 in Deck Width, 80 in Overall Width, Side Door 205 /75R15 Tires, 7000 lb GVWR, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9579	2017 Doolittle 15 ft T/A Enclosed Trailer S/N: 1DGCS1428HM021181 C/W: Lunette Ring Hitch, Spring Suspension, 80 in Deck Width, 84 in Overall Width, 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
9574	2013 Contract 16 ft T/A Enclosed Trailer	9580	2018 Cargo Mate 14 ft T/A Enclosed Trailer	
	S/N: 49TCB1624D1009164 C/W: Ball Hitch, Torsion Axle, 78 in Deck Width, 98 in Overall Width, 235/80R16 Tires, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Midland, TX	9360	Deck Width, 78 in Overall Width, 7 Tires, Bumper Pull with Plywood Walls. Wooden Shelving.; EQUIPI PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - P THE INSPECTION REPORT; TEXAMUST STOP IN OFFICE TO SIGN	C/W: Spring Suspension, Electric Brakes, 78 in Deck Width, 78 in Overall Width, 205/75R15 Tires, Bumper Pull with Plywood Decking and Walls. Wooden Shelving.; EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: Not Available
9575	2017 Doolittle 16 ft T/A Enclosed Trailer S/N: 1DGCS1422HM022245 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 84 in Overall Width, 205/75R15 Tires			Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
	Usage: Not Available	9581	2016 Lark United MFG VT6X14SA 14 ft S/A	
	Asset located in: Lake Worth, TX	4	Enclosed Trailer S/N: 571BE1417GM017644	
9576	2025 Southland LCHT35-716V-86 15 ft T/A Enclosed Trailer S/N: 2SFFH3311S1120958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7815 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, Ramp, 225/75R15 Tires, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFI TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9582	2009 Mongoose 15 ft T/A Enclosed Trailer S/N: 5SMFL142091005960 C/W: Spring Suspension, Electric Brakes, 80 in Deck Width, 225/75R15 Tires, 10000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9590	S/N: 571BE1228KM031668 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, 425 gal Poly Tank Usage: Not Available Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9583	2015 Wells Cargo TW101 10 ft S/A Enclosed Trailer		PROCESS TITLE Asset located in: Lake Worth, TX
	S/N: 575200D14FT278094 C/W: Ball Hitch, Spring Suspension, 72 in Deck Width, 205/75R15 Tires, Honda EM6000SX Generator; EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	9591	2012 Atlas AU712SA 12 ft S/A Enclosed Trailer S/N: 5HCKU1219CE025510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width, Ramp, Side Door 205/75R15 Tires, 3500 lb GVWR Usage: Not Available
9585	2017 Lark 12 ft T/A Enclosed Trailer		Asset located in: Lake Worth, TX
9363	S/N: 571BE1226HM022380 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 92 in Deck Width, 101 in Overall Width, Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9592	2012 Arising 8 ft S/A Enclosed Trailer S/N: 5YCBE0817CH005074 C/W: Spring Suspension, 205/75R15 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9593	Gooseneck Enclosed Trailer S/N: 1WC200R24S2028367 C/W: Spring Suspension, Electric Brakes, 95 ir Deck Width, 97 in Overall Width, Side Door 22! /90/16 Tires, 12000 lb GVWR, Interior Racking EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
9586	2017 Lark VT712TA 13 ft T/A Enclosed Trailer S/N: 5RTBE122XHD058103 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available		
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX	9594	
9587	2015 Arising 7X12VTDW 12 ft T/A Enclosed Trailer		
	S/N: 5YCBE1228FH021263 C/W: Walking Beam Suspension, Electric Brakes, 76 in Deck Width, 80 in Overall Width,		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-		Asset located in: Lake Worth, TX
	CORP-COMPANY Usage: Not Available	9595	2016 Heartland Cyclone 44 ft Tri/A Toy Hauler Travel Trailer
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		S/N: 5SFCG4436GE301886 C/W: Sleeps 2 People, 2 Slide Outs, Power Leveling Jacks, Cummins 5.5 kW Generator, 5th Wheel, Spring Suspension, Electric Brakes
0500	12 ft T/A Enclosed Trailer		235/85R16 Tires Usage: Not Available
9589	S/N: Not Available C/W: Ball Hitch, Spring Suspension, Electric Brakes, 69 in Deck Width, 71 in Overall Width, Side Door 205/75R15 Tires, 11000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9595A	2015 Gateway 3900SE 42 ft T/A Travel Trailer S/N: 5SFSG4129FE293059 C/W: Sleeps 8 People, 3 Slide Outs, Exterior Entertainment, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 7.5/16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9598A 	2012 Keystone Alpine 34 ft T/A Travel Trailer S/N: 4YDF34927CE780709 C/W: Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires, 5 Slide Outs Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
9596	Asset located in: Lake Worth, TX 2015 Kuntry Kustom 34 ft Tri/A Travel Trailer S/N: 1K9BU3933F1236485 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX		2011 Forest River Wildcat 34 ft T/A Travel Trailer S/N: 4X4FWCK28BV024670 C/W: 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	
9597	2014 Rich Kuntry Kustom 34 ft Tri/A Travel Trailer S/N: 1K9BU3934E1236252 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in : Lake Worth, TX	9599	2008 McKenzie Starwood LX 33 ft T/A Travel Trailer	
9597A	·		S/N: 4K03B1M278E176497 C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX	
	Receiver, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9599A	S/N: 4YDF3102XGA740309 C/W: 14285 lb GVWR, 3 Slide Outs, F Leveling Jacks, Power Awning, 5th V Spring Suspension, Electric Brakes, 2 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSI AFFIDAVIT AND MAY NOT BE ACCE	C/W: 14285 lb GVWR, 3 Slide Outs, Power Leveling Jacks, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN
9598	2012 Keystone Fuzion 37 ft Tri/A Toy Hauler Travel Trailer		YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
	S/N: 4YDF37527CF811331 C/W: 7000 lb GVWR, 2 Slide Outs, 5th Wheel, Spring Suspension, Electric Brakes, 235/80/16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9599B	2011 Heartland Sundance 26 ft T/A Travel Trailer S/N: 5SFSG3427BE213855 C/W: 3 Slide Outs, Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235 /80 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9600	2021 Forest River Alpha Wolf 29 ft T/A Travel Trailer S/N: 5ZT2CKUB5M2001919 C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9601	2015 Gulf Stream Trailmaster 27 ft T/A Travel Trailer S/N: 1NL1GTM21F1117001 C/W: 7860 lb GVWR, Single Slide Out, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
9600A	2015 Keystone 30 ft T/A Travel Trailer	9601A	2012 Forest River 3006W 30 ft T/A Travel
	S/N: 4YDT30R26F7207465 C/W: 2 Slide Outs, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH	9601A	Trailer S/N: 4X4TRLF22C1843526 C/W: Sleeps 10 People, Single Slide Out, Power Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9601B	2016 Keystone Outback 32 ft T/A Travel Trailer S/N: 4YDT32429GB451256
9600B	2014 Forest River 31 ft T/A Travel Trailer S/N: 4X4TRLG28E1853494 C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Leveling Jacks, Power Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH		C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: THIS UNIT IT BEING SOLD WITH A BONDED TITLE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9601C	2016 Shadow Cruiser 28 ft T/A Travel Trailer S/N: 5RXTD2821G1033089
9600C 2014 Forest River La Trailer S/N: 5ZT2LCYB9EBG C/W: Air Conditioned Leveling Jacks, Pow Spring Suspension, I Tires Usage: Not Available Notes: TEXAS BUYE TO SIGN REQUIRED	2014 Forest River Lacrosse 33 ft T/A Travel Trailer S/N: 5ZT2LCYB9EB004792 C/W: Air Conditioner, 3 Slide Outs, Power Leveling Jacks, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 205/75R15		C/W: Sleeps 2 People, Single Slide Out, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	REPOSESSION AFFIDAVIT AND MAY NOT BE	9602	2009 Case 590 Super M 4x2 Backhoe Loader
	ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		(Inoperable) S/N: N9C529033 C/W: Enclosed Cab, Air Conditioner, 94 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

			1 age 321 01 301
Lot #	Details	Lot #	Details
(Inoperable) S/N: JJG0172373 C/W: Enclosed Cab, Loader Bucket Usage: 6,290 Hr Notes: INOPERABLE	S/N: JJG0172373 C/W: Enclosed Cab, Air Conditioner, 82 in Loader Bucket Usage: 6,290 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	9604B	Massey Ferguson 471 2WD Tractor (Inoperable) S/N: 9363BL18041 C/W: Canopy, Manual Transmission, 2 Rear Remotes, 540 PTO, 3-Point Hitch, 7.50-16 Front Tires, 16.9/14-30 Rear Tires Usage: Not Available Asset located in: Lake Worth, TX
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL ;	9605	Ford 2WD Tractor (Inoperable)
	Asset located in: Lake Worth, TX		S/N: Not Available C/W: 4 Forward 1 Reverse, Manual
9603A	O3A 2012 John Deere 410K 4x4 Backhoe Loader (Inoperable) S/N: 1T0410KXKCE223394 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Control Pattern Changer, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics		Transmission, 540 PTO, 4.00-19 Front Tires, 11.2x28 Rear Tires Usage: 126 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
		9605A	1959 Allis Chalmers D17 Antique Tractor
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Midland, TX	, 5000A	(Inoperable) S/N: D1726103 C/W: 8 Forward 2 Reverse, Partial Powershift, Gasoline Engine, Electric Start, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar,
9604	2016 John Deere 8245R 4WD Tractor	1	6.00-16 Front Tires, 16.9-28 Rear Tires Usage: Not Available
	(Inoperable) S/N: 1RW8245RCGP110724 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 4 Reverse, PowerShift, Forward/ Reverse Shuttle, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, HID Lights, 4 Rear Remotes, Exterior 3-Point Hitch Controls, 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar, 420/85R34 Front Tires, 480/80R50 Rear Tires Usage: Not Available Notes: ENGINE RUNS BUT SMOKES, HYDRAULICS AND DRIVETRAIN ARE OPERATIONAL; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Asset located in: Lake Worth, TX
		9606	2021 MacDon M1240 16 ft Windrower (Inoperable) S/N: 40219921 C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive, Requires Diesel Exhaust Fluid, 580/70R26 Front Tires, 16.5-16.1 Rear Tires, Header S/N - 43062222, 2022 MacDon R216 16 ft Rotary Header Usage: Not Available Notes: 2018 ENGINE HOURS; 1207 HEADER
			HOURS; LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. UNIT HAS A BAD ENGINE, DRIVETRAIN, HYDRAULIC SYSTEM AND HEADER ARE COMPLETE; INOPERABLE ITEM MUST BE
06044	Asset located in: Lake Worth, TX	1	REMOVED FROM YARD BY JANUARY 10TH
9604A	LS XU6168 4WD Utility Tractor (Inoperable) S/N: 2273000807		AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	C/W: Enclosed Cab, Air Conditioner, 16		Asset located in: Lake Worth, TX
	Forward 16 Reverse, Power Shuttle, Forward/ Reverse Shuttle, Tier 4, 68 hp Engine, Loader, Quick Coupler, Auxiliary Hydraulics, 72 in Scraper Blade, 9.5x24 Front Tires, 16.9-28 Rear Tires Usage: Not Available	9606A	2017 Cat 966M Wheel Loader (Inoperable) S/N: CAT0966MJKJP02417 C/W: Enclosed Cab, Air Ride Seat, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, Log Grapple, 26.5-25 Tires

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR

REMOVAL

Asset located in: Lake Worth, TX

Huid, Log Grapple, 26.5-25 Tires Usage: 6,530 Hr

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR **REMOVAL**

Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9606B	2011 Volvo L110F Wheel Loader (Inoperable) S/N: VCEL110FP00005039 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Hydraulic Coupler, 114 in Bucket, 23.5R25 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9609	2001 Terex S17E Motor Scraper (Inoperable) S/N: S8311020 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE	
9608	1999 Volvo L90C Wheel Loader (Inoperable)	1	FOR LOADOUT. Asset located in: Lake Worth, TX	
	S/N: L90CV63189 C/W: Enclosed Cab, Hydraulic Coupler, 20.5 R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9610	2000 Terex S17E Motor Scraper (Inoperable) S/N: S8031011 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
9608A	2013 Volvo L70G Wheel Loader (Inoperable)	0644	Asset located in: Lake Worth, TX	
	S/N: VCE0L70GK00002765 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires Usage: 24,316 Hr Notes: ENGINE RUNS BUT SMOKES; DRIVETRAIN AND HYDRAULICS ARE OPERATIONAL; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	S/N: 1RW9570RLGE054151 C/W: Enclosed Cab, Air Cond Seat, Differential Lock, 18 Fo e18 PowerShift, 2016 US EPA Diesel Exhaust Fluid, Front W Remotes, ISOBUS, Dual 710/ Wheel Weights Usage: Not Available Notes: LOADING ASSISTANG ON THIS UNIT. OUTSIDE LOA ASSISTANCE WILL NEED TO DRIVETRAIN IS COMPLETE E REAR END, HYDRAULICS ARI INOPERABLE ITEM MUST BE YARD BY JANUARY 10TH AN RELISTED; BUYER'S RESPON REMOVAL Asset located in: Lake Worth 9612 2016 Cat D6K2 LGP Crawler S/N: CAT00D6KVJTR00286 C/W: Enclosed Cab, Air Cond for Grade Control, Requires D Fluid, Sweeps, 144 in Wide P Single Grouser Track Shoes, Auxiliary Hydraulics, EQUIPN PULICE-CONSTRUCTION Usage: 10,000 Hr Notes: DEFICIENCIES NOTED THE INSPECTION REPORT IN MUST BE REMOVED FROM Y 10TH AND CANNOT BE RELI RESPONSIBILITY FOR REMO	Articulated Tr S/N: 1RW957 C/W: Enclose Seat, Differen e18 PowerShi Diesel Exhaus Remotes, ISO Wheel Weight Usage: Not Av	Articulated Tractor (Inoperable) S/N: 1RW9570RLGE054151 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, 4 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Front Wheel Weights Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING
9608B	2012 Cat 140M2 VHP Plus Motor Grader (Inoperable) S/N: CAT0140MAM9D01207 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2012 US EPA Label, 14 ft / 4.27 m Moldboard, Push Block, Accumulators		Asset located in: Lake Worth, TX 2016 Cat D6K2 LGP Crawler Dozer (Inoperable)	
	AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		PULICE-CONSTRUCTION	

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9612A	(Inoperable) S/N: 1T0750JXKBD203024 C/W: Enclosed Cab, Air Conditioner, Sweeps, 152 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 8,566 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM	9615	1998 Cat CP433C Padfoot Drum Compactor (Inoperable) S/N: 2JM00524 C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, 66 in Drum, Leveling Blade Usage: 5,226 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
		9615A	Bomag BW124PDH-40 Padfoot Drum Compactor (Inoperable) S/N: 901581401027 C/W: Open Operator Station, 2011 US EPA Label, Deutz 3 Cylinder 45 hp 2.3 L Diesel Engine, 48 in Drum
9613	2016 Cat D5K2 LGP Crawler Dozer (Inoperable) S/N: CAT00D5KCKY202614 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 124 in Wide PAT Blade, 26 in Single Grouser Track Shoes, SystemOne		Usage: 1,423 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Undercarriage, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 6,365 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9616	2017 Bomag BW 124 Smooth Drum Compactor (Inoperable) S/N: 861832121160 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
1		9616Δ	2011 Cat CD54 Double Drum Roller (Inoperable)
9613A	2001 Cat 963C LGP Crawler Loader (Inoperable) S/N: 2DS01267 C/W: Open Operator Station, 86 in Bucket, 21 in Double Grouser Track Shoes, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP.	9616A 9616B	S/N: CATOCD54HJ5R00162 C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, 67 in Offsetting Compaction Width, Water System Usage: 4,502 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		2018 Bomag BW900-50 Double Drum Roller (Inoperable) S/N: 881834072563 C/W: Open Operator Station, Honda GX 630 2
	Asset located in: Lake Worth, TX	1	Cylinder Gasoline Engine, 35 in Compaction Width
9614	Dynapac CA2500 Padfoot Drum Compactor (Inoperable) S/N: 10000138K0A011328 C/W: Enclosed Cab, 2013 US EPA Label, Cummins 4.5 L Diesel Engine, 74 in Drum Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9616C	2018 Bomag BW900-50 Double Drum Roller (Inoperable) S/N: 861834072457 C/W: Open Operator Station, Honda GX 630 2 Cylinder Gasoline Engine, 36 in Compaction Width, Edge Cutter Usage: 685 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9621	2013 Komatsu PC360LC-10 Tracked Excavato (Inoperable) S/N: KMTPC242A54A32676 C/W: Air Conditioner, Rear View Camera, US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 56 in Digging Bucket, Thumb Bracket Usage: 13,098 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM
9617	2006 Ingersoll Rand DD-34HF Double Drum Roller (Inoperable) S/N: 188489 C/W: Open Operator Station, 2005 US EPA Label, Kubota V2203-M-ES 4 Cylinder 36.4 kW 2.2 L Diesel Engine, 54 in Compaction Width, Water System Usage: 5,526 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX 2016 Cat 330F L Tracked Excavator (Inoperable) S/N: CAT0330FCMBX00322 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION
9617A	2016 Bomag BMP8500 Trench Compactor S/N: 101720125102 C/W: Tier 4, 2015 US EPA Label, Kubota D1005 3 Cylinder 14.5 kW 1.0 L Diesel Engine, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		Usage: 10,017 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEI MUST BE REMOVED FROM YARD BY JANUA 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
9618	2011 Lay-Mor 8HC Self-Propelled Broom (Inoperable) S/N: 33225 C/W: Open Operator Station, 7 ft 9 in Broom, Water System, 2019 US EPA Label, Kubota 3 Cylinder 26 kW 1.5 L Diesel Engine Usage: 854 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	_9622A	2001 Komatsu PC200-6 Tracked Excavator (Inoperable) S/N: C10758 C/W: 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 96 in Cleanup Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9620	1999 Broce BB250 Self-Propelled Broom (Inoperable) S/N: 981111 C/W: Open Operator Station, 6 ft 3 in Broom, Water System, 4 Cylinder Diesel Engine Usage: 542 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9623	2020 Cat 320 Tracked Excavator (Inoperable) S/N: CAT00320KHEX20346 C/W: Air Conditioner, Straight Travel Pedal, Cab Screens, Rear & Side View Cameras, 2019 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, Manual Quick Coupler, Thumb Bracket Usage: 4,956 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9623A	2014 John Deere 135G Tracked Excavator (Inoperable) S/N: 1FF135GXJEE400550 C/W: Air Conditioner, Air Ride Seat, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 24 in Double Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 24 in Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9624B 9625	2018 Wacker Neuson EZ53 Mini Excavator (Inoperable) S/N: WNCE0510TPAL00649 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,989 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOBE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2018 Case CX37C Mini Excavator (Inoperable) S/N: NSUC37CRNZLN55583 C/W: 2017 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill
9623B	2018 Bobcat E50 Mini Excavator (Inoperable) S/N: AJ1814335 C/W: Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 4,351 Hr		Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9623C	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2016 John Deere 35G Mini Excavator (Inoperable) S/N: 1FF035GXTGK276310		2014 Terex TC16 Mini Excavator (Inoperable) S/N: TC00163259 C/W: Swing Boom, 3 ft 8 in Stick, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 8 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
	C/W: Swing Boom, 4 ft 4 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	REMOVAL OF THIS ITEM Asset located in: Lake Worth, T 9625A Simon-Ro TC-120-4 10 ton Stra 1998 International 9100 6x4 Be (Inoperable) S/N: 2HSFRAHR5WC056727 C/W: Cummins M11-330E+ 6 C 330 hp Engine, 1998 US EPA La Speed Manual Transmission, 1 Frame, International IROS Air R 207 in Wheelbase, 10 ton Capa Mounted, 20 ft - 48 ft 3 Section Controls, Straight Down Outrige Outriggers, 15 ft x 94 in Bed Usage: 185,516 Mi Notes: INOPERABLE ITEM MUS FROM YARD BY JANUARY 10T BE RELISTED; BUYER'S RESPO REMOVAL; ADDITIONAL INFO AVAILABLE IN OFFICE - KEY	REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX Simon-Ro TC-120-4 10 ton Straight Boom on 1998 International 9100 6x4 Boom Truck (Inoperable)
9624	2006 Komatsu PC27MR-2 Mini Excavator (Inoperable) S/N: KMTPC120A05016215 C/W: Control Pattern Changer, Swing Boom, 3 ft 8 in Stick, Backfill Blade, 12 in Rubber Tracks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		
		9625B	2006 Gradall XL3100 Wheel Excavator (Inoperable) S/N: 210018006 C/W: Air Conditioner, 2006 US EPA Label, 385 /65R22.5 Tires, Cleanup Bucket, Eaton fuller 9 speed manual transmission, Usage: Not Available

Lot #	Details	Lot #	Details
9625C	2005 Gradall XL3300 Wheel Excavator (Inoperable) S/N: 0210017540 C/W: Backfill Blade, Stabilizers, 60 in Cleanup Bucket, Additional 30 in Digging Bucket Usage: 2,899 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9629A	4x4 Articulated Water Truck (Inoperable) S/N: Not Available C/W: Open Operator Station, 23.1-26 Tires Usage: 2,976 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9627	S/N: 1VRT112P2W1000109 C/W: Canopy, Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Rock Trencher Chain, Straight Blade Usage: 1,406 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM	9629B	1995 Etnyre K Series Chip Spreader (Inoperable) S/N: K5706 C/W: Open Operator Station, Diesel Engine, Hydrostatic Drive, 11 ft - Spreader Usage: Not Available Notes: UNIT STARTS AND RUNS, DRIVETRAIN IS INOPERABLE Asset located in: Lake Worth, TX
	YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9629C	Cat BG-260C Wheel Asphalt Paver S/N: CATBG260C8GN00575 C/W: 2001 US EPA Label, 10 ft - Screed, On
9628	1998 Vermeer V4150A 4x4 Trencher (Inoperable) S/N: 1VRP082R0W1000592 C/W: Deutz 4 Cylinder Diesel Engine, 8.5 in Wide x 7 ft Long Rock Trencher Chain, Crumbling Shoe, 8600 Backhoe Attachment, Angle Blade, Side Shift Usage: 349 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		Board Generator Usage: Not Available Asset located in : Lake Worth, TX
		9630	Weiler P355 Track Asphalt Paver (Inoperable) S/N: P355-1010 C/W: Dual Controls, 8 ft - Screed, 12 in Rubber Tracks Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED
9628A	2016 L0KT T/A Vacuum Excavation Unit		Asset located in: Lake Worth, TX
	(Inoperable) S/N: 4M9E2TG22GE015001 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Front Hose Reel, 320 L Fresh Water Tank, Drop Down Tailgate, Manual Tailgate Locks, 3.5 in Suction Hose, Engine Driven Pump, 235/80R16 Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9630A	2014 John Deere 648H 4x4 Skidder (Inoperable) S/N: 1DW648HXKED658603 C/W: Air Conditioner, Air Ride Seat, Sweeps, Screens, Blade, John Deere Grapple, Single Arch, John Deere Single Drum Winch, 30.5L32 Tires, Floatation Tires Usage: 9,491 Hr Notes: ENGINE RUNS, HYDRAULICS OPERATIONAL, DRIVETRAIN WORKS ONLY IN FORWARD - NO REVERSE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details
9630B	2014 Cat 242D Skid Steer Loader (Inoperable) S/N: CAT0242DJDZT00366 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Tier 4, 2013 US EPA Label, CARB Compliant, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: 689 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Midland, TX	9633	2017 Cat 299D2 High Flow XPS Compact Track Loader (Inoperable) S/N: CAT0299DHFD202254 C/W: Enclosed Cab (Door missing), Joystick Steering, Tier 4, 2017 US EPA Label, 16 in Track Belts, Hydraulic Coupler Usage: 3,440 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9631	2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DLDTB05827 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Manual Coupler Usage: 6,509 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9633A 9634	2014 Cat 289D Two-Speed High Flow XPS Compact Track Loader (Inoperable) S/N: TAW01012 C/W: Enclosed Cab (Door missing), Air Conditioner, Air Ride Seat, Ride Control,
9632	Asset located in: Lake Worth, TX 2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DPDTB05818 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Manual Coupler, 74 in Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Joystick Steering, Self Leveling, Tier 4, 2014 USEPA Label, 18 in Track Belts, Hydraulic Coupler 74 in Bucket, Counterweight Kit Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOBE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Midland, TX 2018 Cat 289D Two-Speed Compact Track Loader (Inoperable)
9632A	2018 Cat 226D Skid Steer Loader (Inoperable) S/N: CAT0226DJHRD03498 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket Usage: 1,238 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;		Rear View Camera, Tier 4, 2017 US EF 18 in Track Belts, 9 Pin Electric Kit, M Coupler, 78 in Bucket Usage: 4,582 Hr Notes: INOPERABLE ITEM MUST BE F
9632B	Asset located in: Lake Worth, TX 2016 Kubota SSV65 Skid Steer Loader (Inoperable) S/N: JKUS0651L01S12051 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Aperture Tires, Manual Coupler, 66 in Bucket Usage: 2,937 Hr Asset located in: Lake Worth, TX	9634A	2014 Cat 289D Compact Track Loader (Inoperable) S/N: CAT0289DVTAW00650 C/W: Enclosed Cab, Joystick Steering, 18 in Track Belts, Manual Coupler, 74 in Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9632C	2021 Bobcat S510 Skid Steer Loader (Inoperable) S/N: B4RE11047 C/W: Open Operator Station, 2020 US EPA Label, Aperture Tires, Manual Coupler,	9634B	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2017 Kubota SVL75-2 Compact Track Loader
	EQUIPMENT FROM UNITED RENTALS Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		(Inoperable) S/N: JKUC0752T01S29876 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 15 in Track Belts, Hydraulic Coupler, 74 in Bucket Usage: 799 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9635 9635A	2019 Kubota SVL95-2S Compact Track Loader (Inoperable) S/N: KBCC0953CK1D46350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available Asset located in: Midland, TX 2020 Bobcat T590 Compact Track Loader	9637	9637	2017 John Deere 317G Compact Track Loader (Inoperable) S/N: 1T0317GJPHJ308175 C/W: Open Operator Station, Joystick Steering, 13 in Track Belts, Hydraulic Coupler, 72 in Bucket, EQUIPMENT FROM UNITED RENTALS Usage: 2,121 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9033A	(Inoperable)		REMOVAL Asset located in: Lake Worth, TX	
	S/N: ALJU32175 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,749 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	9637A 2	2017 Kubota SVL95-2S Two-Speed Compact Track Loader (Inoperable) S/N: JKUC0953L01S34123 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler	
	REMOVAL		Usage: 2,023 Hr	
9635B	Asset located in: Humble, TX 2019 Case TR310 Compact Track Loader		Notes: UNIT STARTS AND RUNS, ENGINE IS DERATED, POWERTRAIN IS DERATED Asset located in: Lake Worth, TX	
	(Inoperable) S/N: JAFTR310JJM450180 C/W: Enclosed Cab (Door missing), Joystick Steering, 16 in Track Belts, Electric Coupler, 72 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	9639	2010 Bobcat T190 Compact Track Loader (Inoperable) S/N: A3LN36903 C/W: Open Operator Station, 12.5 in Track Belts, Manual Coupler Usage: 5,228 Hr	
9636	2018 Case TR310 Compact Track Loader (Inoperable) S/N: JAFTR310AJM449342 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2018 US EPA Label, 15.5 in Track Belts, Manual Coupler, 77 in		Notes: UNIT STARTS AND RUNS, PARKING BRAKE INOPERABLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
	Bucket Usage: 3,405 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9639A	2012 Takeuchi TL230 Compact Track Loader (Inoperable) S/N: 223101077 C/W: Open Operator Station, Joystick Steering, 2012 US EPA Label, 12.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 67 in Bucket	
9636A	2018 Case TR270 Compact Track Loader (Inoperable) S/N: NJM448663 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manual		Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	Coupler, 68 in Bucket Usage: 2,404 Hr	9640	2019 Toro 22322 Mini Compact Track Loader	
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		(Inoperable) S/N: 405588028 C/W: Open Operator Station, 2019 US EPA Label, 9 in Track Belts, Manual Coupler, 14 in Bucket Usage: 1,147 Hr	
			Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
			Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9641	2015 JLG 10054 Telehandler (Inoperable) S/N: 0160070159 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9643A	2007 Ford F-550 XL 4x2 Extended Cab Utility Truck (Inoperable) S/N: 1FDAX56P57EA34588 C/W: Ford V8 Diesel Engine, Automatic Transmission, 225/70R19.5, Spring Suspension, 166 in Wheelbase, Knapheide 9 ft Body Usage: 296,251 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Crown RR5700 Order Picker (Inoperable) S/N: 1A388576
9642	Asset located in: Humble, TX 2013 JCB 9404 8000 lb Rough Terrain Forklift (Inoperable) S/N: JCB94004A02228045 C/W: 3 Stage Mast, 72 in Forks, 2012 US EPA Label, JCB tc-55 4 Cylinder 4.4 L Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available		C/W: 3 Stage Mast, 240 in Max Lift Height, 107 in Lowered Mast Height, 42 in Forks, Side Shift, Push/Pull Attachment Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
		9643B	1980 Hyster Cushion Tire Forklift (Inoperable) S/N: F006V02094A C/W: 2 Stage Mast, 146 in Lowered Mast Height, 96 in Forks, 4 Cylinder Diesel Engine Usage: 5,119 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9642A	1999 Mack RB688S 6x4 85 in Tree Spade Truck (Inoperable)		REMOVAL Asset located in: Lake Worth, TX
	S/N: 1M2AM08C9XM004800 C/W: Mack 6 Cylinder Diesel Engine, 1998 US EPA Label, Aluminum Front Wheels, 385 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 258 in Wheelbase Usage: 216,359 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9644	Mitsubishi FG50K 11000 lb Pneumatic Tire Forklift (Inoperable) S/N: AF33B50068 C/W: 2 Stage Mast, 148 in Max Lift Height, Solid Pneumatic Tires, 5 Cylinder LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
06 400	Asset located in: Lake Worth, TX	9644A	2021 Yale GLC155VX 10000 lb Cushion Tire
9642B	2003 Ford F-250 XL 4x2 Extended Cab Utility Truck (Inoperable) S/N: 1FDNX20L13EC09631 C/W: V8 5.4 L Gasoline Engine, 2003 US EPA Label, Automatic Transmission, 4250 lb Front Axle, 6084 lb Rears, 8800 lb GVWR, 235/80R16 Front Tires, 235/85R16 Rear Tires, Spring Suspension, 159 in Wheelbase, 2003 Knapheide 696FJ 8 ft 2 in Body Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Forklift (Inoperable) S/N: F879V02835V C/W: 3 Stage Mast, 221 in Max Lift Height, 111 in Lowered Mast Height, Paper Roll Clamp, 2021 US EPA Label, PSI 6 Cylinder 4.3 L Dual Fuel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

			C
Lot #	Details	Lot #	Details
9645	2009 Toyota 7FGAU50 7550 lb Pneumatic Tire Forklift (Inoperable) S/N: 70256 C/W: 3 Stage Mast, 219 in Max Lift Height, 84 in Lowered Mast Height, 84 in Forks, Side Shift, 2009 US EPA Label, IMPCO 6 Cylinder 4.3 L LPG Engine Usage: 6,371 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Bryan, TX	9646C	2013 Linde H25CT 5000 lb Cushion Tire Forklift (Inoperable) S/N: A1131D00241 C/W: 2 Stage Mast, Full Free Lift, 180 in Max Lift Height, 81 in Lowered Mast Height, 41 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 10,212 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9646	•	9647	1990 Cat T50D 5000 lb Cushion Tire Forklift
9040	2010 Toyota 7FGAU50 5950 lb Pneumatic Tire Forklift (Inoperable) S/N: 70533 C/W: 3 Stage Mast, 219 in Max Lift Height, 109 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, Vortec LPG Engine Usage: 8,220 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		(Inoperable) S/N: 8EB09438 C/W: 3 Stage Mast, 173 in Max Lift Height, 83 in Lowered Mast Height, 36 in Forks, Side Shift, Cat 4 Cylinder LPG Engine Usage: 20,099 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Asset located in: Elmendorf, TX	9648	2004 Hyundai HLF25-5 5000 lb Pneumatic Tire
9646A	2012 Toyota 8FGCU30 5120 lb Cushion Tire Forklift (Inoperable) S/N: 17847 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, Toyota 4Y ECS 4 Cylinder 2.23 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		Forklift (Inoperable) S/N: FU0211429 C/W: Single Stage Mast 130 in Max Lift Height, 86 in Lowered Mast Height, 47 in Forks, 2004 US EPA Label, CARB Compliant, IMPCO 6Z9XB02.4MPN 4 Cylinder 2.4 L LPG Engine Usage: 1,363 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	REMOVAL Asset located in: Lake Worth, TX	9649	2012 Cat 2EPC5000 4870 lb Electric Forklift (Inoperable)
9646B 2014 Toyota 8FGCU30 502 Forklift (Inoperable) S/N: 60401 C/W: 3 Stage Mast, 198 in I in Lowered Mast Height, 42 2014 US EPA Label, Toyota 2.2 L LPG Engine Usage: 3,999 Hr	2014 Toyota 8FGCU30 5020 lb Cushion Tire Forklift (Inoperable) S/N: 60401 C/W: 3 Stage Mast, 198 in Max Lift Height, 91 in Lowered Mast Height, 42 in Forks, Side Shift, 2014 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 3,999 Hr		S/N: FN459381 C/W: 3 Stage Mast, 86 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 80 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
	Notes : INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	9649A	1995 Hyster S50XL 4750 lb Pneumatic Tire
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Forklift (Inoperable) S/N: C187V157475S C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Fork Positioner, LPG Engine Usage: 9,483 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

1 "	Detelle	1 "	Dataila	
Lot #	Details	Lot #	Details	
9650	2012 Doosan G25P-5 4600 lb Pneumatic Tire Forklift (Inoperable)	9652	2013 Nissan CF40LP 4000 lb Pneumatic Tire Forklift (Inoperable)	
	S/N: FGA0B133002925 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, 4 Cylinder 46.8 kW 2.4 L LPG Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available		S/N: CP1F2-9W1966 C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2013 US EPA Label, 4 Cylinder 2.1 L LPG Engine Usage: 10,133 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9653	2000 Toyota 52-6FGCU45 8600 lb Cushion Tire	
	Asset located in: Humble, TX]9033	Forklift (Inoperable)	
9651	<u> </u>		S/N: 62206 C/W: 3 Stage Mast, Full Free Lift, 218.5 in Max Lift Height, 106 in Lowered Mast Height, 72 in Forks, Side Shift, V6 LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
	Usage: 3,439 Hr	0654	Asset located in: Lake Worth, TX	
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	82 in Lowered Mast Height, 42 in Forks, So Pneumatic Tires, 2011 US EPA Label, 4 Cylinder 2.0 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMO FROM YARD BY JANUARY 17TH AND CAN BE RELISTED; BUYER'S RESPONSIBILITY F	Pneumatic Tire Forklift (Inoperable) S/N: C810V04664J C/W: 2 Stage Mast, 127.2 in Max Lift Height,	
9651A	Tusk 500CG-14 4480 lb Cushion Tire Forklift (Inoperable) S/N: 590948A C/W: 3 Stage Mast, 188 in Max Lift Height, 42 in Forks, Side Shift, Tier 1, 2005 US EPA Label,		Pneumatic Tires, 2011 US EPA Label, Cylinder 2.0 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE R	Pneumatic Tires, 2011 US EPA Label, 4 Cylinder 2.0 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED
	Nissan 4 Cylinder 55 hp 2.1 L LPG Engine Usage: Not Available		BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL	
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		Asset located in: Lake Worth, TX	
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9655	9655 2014 Toyota 8FGCU20 4000 lb Cushion Tire Forklift (Inoperable)	
9651B	2010 Doosan GC25P-5 4450 lb Cushion Tire Forklift (Inoperable) S/N: MW00736 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift, 2010 US EPA Label, Woodward 4 Cylinder 46.8 kW 2.4 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		S/N: 62727 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Load Weigh System, 2014 US EPA Label, CARB Compliant, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9655A	2012 TCM FG25T3 3700 lb Pneumatic Tire Forklift (Inoperable) S/N: 2H507316 C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, Tier 2, 2012 US EPA Label, Nissan 4 Cylinder 2.1 L Dual Fuel Engine Usage: 3,696 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9657A	1995 Toyota 5FBE18 Electric Forklift (Inoperable) S/N: 15611 C/W: 3 Stage Mast, Full Free Lift, 82 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9655B	2012 Toyota 7FBEU20 3050 lb Electric Forklift	9657C	2017 Toyota 8FGCU25 1700 lb Cushion Tire
	(Inoperable) S/N: 7FBEU2020440 C/W: 3 Stage Mast, 218 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Forklift (Inoperable) S/N: 88346 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 95 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 7,554 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9655C	1992 Cat T50E 3600 lb Cushion Tire Forklift (Inoperable)	9657D	1989 Nissan CPF02A25V 5000 lb Cushion Tire
	S/N: 2ND00404 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 82 in Lowered Mast Height, 43 in Forks, Side Shift, 4 Cylinder Dual Fuel Engine Usage: 4,569 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	965/D	Forklift (Inoperable) S/N: CPH02026383 C/W: 106 in Max Lift Height, 68 in Lowered Mast Height, Nissan 4 Cylinder Dual Fuel Engine, EQUIPMENT FROM CENTRAL FREIGHT LINES INC Usage: 8,015 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9656	2003 Linde E30C 3060 lb Electric Forklift		REMOVAL; NO LPG TANK Asset located in: Lake Worth, TX
9657	(Inoperable) S/N: A1X347P00155 C/W: 3 Stage Mast, 24 in Lowered Mast Height, 36 in Forks, 48 V, Battery Charger Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 1998 Toyota 5FBE18 2800 lb Electric Forklift	9658 9658A	Toyota Cushion Tire Forklift (Inoperable) S/N: Not Available C/W: 2 Stage Mast, 77 in Lowered Mast Height, 42 in Forks, 4 Cylinder Gasoline Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX 2021 Combilift COMBI-RT 3000 lb 3x3 Rough
	(Inoperable) S/N: 24164 C/W: 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 93 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	PODGA	Terrain Forklift S/N: 55866 C/W: 2 Stage Mast, 124 in Max Lift Height, 24 in Lowered Mast Height, 72 in Forks, Side Shift, 2020 US EPA Label, Deutz TD2.9L4 4 Cylinder 55 kW 2.9 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9658B	2010 Genie S85 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: S85108432 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, 2010 US EPA Label, Deutz TD 2011L04I 4 Cylinder 3.61 L Diesel Engine, 18-625NHS Tires Usage: 5,544 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	9659B	2016 Genie GS-3232 Electric Scissor Lift (Inoperable) S/N: GS3216P-144587 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9659C	2017 JLG 600S 4WD Diesel Telescopic Boom
9658C	2015 JLG 400S 2WD Diesel Telescopic Boom Lift (Inoperable) S/N: 0300210976 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, 2015 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 14-17.5 NHS Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,245 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		Lift (Inoperable) S/N: 300229396 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 5,530 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
9659	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift (Inoperable) S/N: 40001322 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2014 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, LP Tank is not included Usage: 1,512 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED;		2016 Skyjack SJ3226 Electric Scissor Lift (Inoperable) S/N: 27028952 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Onboard Generator, Solid Non-Marking Tires Usage: 285 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	BUYER'S RESPONSIBILITY FOR REMOVAL	9660A	2017 JLG 600S 4WD Diesel Telescopic Boom
9659A	Asset located in: Lake Worth, TX 2000 UpRight RT27 4x4 Gasoline Scissor Lift (Inoperable) S/N: 2922 C/W: 27 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Upper Control Box, 2000 US EPA Label, Kubota 3 Cylinder 740 cc Gasoline Engine Usage: 4,028 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-	Lift (Inoperable) S/N: 0300233241 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 6,286 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9660B	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: 0300236292 C/W: 65 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,928 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	9661A 9661B	2017 Generac MLT6SMD Light Tower (Inoperable) S/N: 7FSBL1018HB880619 C/W: 2017 US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,155 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; 3001880619; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2017 Magnum Pro MLT6SM 6 kW Light Tower (Inoperable)
9660C	2016 Genie GS-4047 Electric Scissor Lift (Inoperable) S/N: GS4716D1543 C/W: 39 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		S/N: 3001715479 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,347 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	9661C	Husqvarna FS6600D Walk-Behind Saw (Inoperable) S/N: 001298383001 C/W: Water Hose Connection, Electric Blade Raise / Lower, US EPA Label, John Deere
9660D	2015 Genie GS-1930 Electric Scissor Lift (Inoperable) S/N: GS3015A146318 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		4024HF295 4 Cylinder Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	9662	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: Tier 4, 2013 US EPA Label, Kubota V1505 16 kW 1.5 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,620 Hr
9661	2016 Snorkel S3219E Electric Scissor Lift (Inoperable) S/N: S3219E04001808 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box Usage: 47 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9663	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: Tier 4, 2013 US EPA Label, Kubota v1505 4 Cylinder 16 kW 1.5 L Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 4,216 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9665A	2009 Drash 23 kW Mobile Generator Set (Inoperable) S/N: 610 C/W: 2009 US EPA Label, Perkins 4 Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 4,337 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9664	Lincoln RA-250-V1903 300 A Skid-Mounted Engine Driven Welder (Inoperable) S/N: C1080500072 C/W: Tier 4, 2008 US EPA Label, CARB Compliant, Kubota V2003-M-BG-ET02e 4 Cylinder 24.3 kW 2.0 L Diesel Engine, Welding Leads Not Included, 40 V Rated Voltage Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9665B	Drash 20 kW Mobile Generator Set (Inoperable) S/N: 359 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V Receptacles, S/A Trailer, Lunette Ring Usage: 737 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9664A	2019 Wacker Neuson G25 20 kW Mobile Generator Set (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, 24.4 kVA/19.5 kW Rated 3 Phase Output, 240 V / 480 V / 120 V Rated Voltage, 16 kVA,/16 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 661 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9665C	2008 Drash 20 kW Mobile Generator Set (Inoperable) S/N: 346 C/W: Perkins 4 Cylinder 33 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, Sound Attenuated, S/A Trailer, Lunette Ring Usage: 265 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Cummins 682F9R7032 640 kW Skid-Mounted
9665	1992 Onan 37DGBA 37 kW Skid-Mounted Generator Set (Inoperable) S/N: 1910419145 C/W: Cummins 4B3.9G 4 Cylinder 66 hp 3.9 L Diesel Engine, /37 kW Rated 3 Phase Output Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX	9666A	Generator Set (Inoperable) S/N: C9M0682005 C/W: 2008 US EPA Label, Volvo TWD1643GE 6 Cylinder 1800 kW 16.2 L Diesel Engine, 800 kVA /640 kW Rated 3 Phase Output, 440 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Humble, TX Redco Skid-Mounted Generator Set (Inoperable) S/N: Not Available C/W: Cummins 6 Cylinder Diesel Engine Usage: 269 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9666B	2006 Ingersoll Rand G25 Mobile Generator Set (Inoperable) S/N: 4FVGCBAA06U374217 C/W: Ingersoll-Rand 3 Cylinder Diesel Engine, 480 V Rated Voltage, S/A Trailer, Lunette Ring Usage: 34,921 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9670	Sullivan Palatek Skid-Mounted Electric Air Compressor (Inoperable) S/N: 11F046 C/W: 200 psi Working Pressure, 230, 75 hp Motor Usage: 18,303 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9666C	2016 Multiquip DCA220SSJU4F Generator Set (Inoperable) S/N: 5SLBG1825GL018612 C/W: 2016 US EPA Label, John Deere 6 Cylinder 6.8 L Diesel Engine, 220 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 10,985 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9671	(Inoperable) S/N: 16MPF0922AD056753 C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, 2010 US EPA Label, John Deere 4 Cylinder 60 kW 4.5 L Diesel Engine, T/A Trailer, Lunette Ring, Surge Brakes Usage: 4,558 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9672	MMDI Trailer-Mounted Water Pump
9667	Gardner-Denver EAUSPG Skid-Mounted Electric Air Compressor (Inoperable) S/N: FACP8X0 C/W: 3 Phase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		(Inoperable) S/N: Not Available C/W: 5 in Intake, 6 in Discharge, Centrifugal Water Pump, Kohler KD11903TCR 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9668	2018 Tsurumi TPG4-4500HDX 4.5 kW Portable Generator Set (Inoperable) S/N: 051272 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX 2019 Tsurumi TPG4-4500HDX 4.5 kW Portable Generator Set (Inoperable)	9673	2011 Magnum MAG MTP 4000D Trailer-Mounted Water Pump (Inoperable) S/N: 1105549 C/W: 4 in Intake, 4 in Discharge, Centrifugal 2013 US EPA Label, CARB Compliant, John Deere 4024TF281A 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,333 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
	S/N: 051460 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/		REMOVAL Asset located in: Lake Worth, TX
	Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9673A	2018 Atlas Copco XAS440JDT4F Mobile Air Compressor (Inoperable) S/N: HOP077169 C/W: John Deere 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch, Electric Brakes Usage: 3,319 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9673B	9673B 2001 Sullivan 185DPQ Mobile Air Compressor (Inoperable) S/N: 4135193 C/W: 200 psi Working Pressure, 2001 US EPA Label, John Deere 4045DP150B 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 1,078 Hr Notes: INOPERABLE ITEM MUST BE REMOVED	9677	Ingersoll Rand 20VX15 Air Compressor (Inoperable) S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9673C	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2017 Atlas Copco XAS110KD 110 cfm Mobile Air Compressor (Inoperable) S/N: YA3064283H0480254	9678	Pneumatic Skid Mounted Lube Pan - Fits Truck (Inoperable) S/N: Not Available C/W: Kohler Command Pro 14 429 cc Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	C/W: 2017 US EPA Label, Kubota D902-EF01 3 Cylinder 0.89 L Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX	9679 9680 9680A	Gardner-Denver Air Compressor (Inoperable) S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9674	(Inoperable) S/N: Not Available C/W: 3 Phase, 20 hp Motor Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
			Quantity of (2) Water Pump (Inoperable) S/N: Not Available C/W: Trash Pump, 1 Cylinder Gasoline Engine, (1) Tsurumi 4 In, (1) 3 In, One Pallet Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM JARD BY JANUARY 10TH AND CANNOT
9675			BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		2019 Cub Cadet Pro Z 500 Zero-Turn Lawn Mower (Inoperable) S/N: 1C089H70016 C/W: 2019 US EPA Label, 24x12.00-14 Rear Tires, 54 in Mower Usage: 105 Hr
9676	Gardner-Denver Air Compressor (Inoperable) S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9681	2016 Airrex Air Conditioner (Inoperable) S/N: 161010989L Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9681A	1954 Chris-Craft 33 ft Wood Cabin Crew Boat (Inoperable) w/ Custom Built Trailer S/N: Not Available C/W: T/A Trailer, Ball Hitch Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9684A	2020 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD2013059325 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 758 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9682	Landa PGDC5-3500 Pressure Washer (Inoperable)		Asset located in: Lake Worth, TX
	S/N: 11100500101088 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton 570 cc Gasoline Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9684B	2020 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD2010053177 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2019 US EPA Label, Kubota D722-EF01 3 Cylinder 14.7 kW Diesel Engine Usage: 1,029 Hr Notes: INOPERABLE ITEM MUST BE REMOVED
06004	Asset located in: Lake Worth, TX	1	FROM YARD BY JANUARY 10TH AND CANNOT
9682A	2022 Kubota RTV-X1140 Utility Vehicle (Inoperable)		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION
	S/N: A5KD2GDBVNG053697 C/W: Open Operator Station, 4 Passenger,		AVAILABLE IN OFFICE - MSO ; Asset located in : Lake Worth, TX
	Windshield, Electric Dump Bed, Tier 4, 2022 US EPA Label, Kubota d1105 3 Cylinder 8 kW 1.1 L Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9684C	2019 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD1919970458 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2018 US EPA Label, Kubota D722-EF01 3 Cylinder 14.7 kW Diesel Engine Usage: 964 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
9682B	2021 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBCMG044293		
	C/W: Canopy, 4 Passenger, Electric Dump Bed, Tier 4, 2021 US EPA Label, Kubota d1105 3		Asset located in: Lake Worth, TX
	Cylinder 8 kW 1.1 L Diesel Engine Usage: 1,144 Hr	9684D	2019 Club Car Carryall 1700D Utility Vehicle
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		(Inoperable) S/N: SD1919969449 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2018 US EPA Label, Kubota D722-EF01 3 Cylinder 14.7 kW Diesel Engine
9684	2017 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBLHG019685 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX		Usage: 1,308 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9684E 9685	2019 Club Car Carryall 1700G Utility Vehicle (Inoperable) S/N: SC1918-968334 C/W: Canopy, 4 Passenger, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2019 Club Car Carryall 1500G Utility Vehicle (Inoperable) S/N: RC1918-967901	9687	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X2GD332545 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 22171.7 Engine hrs, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, PTO, Auto Lube Usage: 693,335 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
	C/W: Canopy, 2 Passenger, Brush Guard, Hitch	9687A	2016 Peterbilt 365 6x4 T/A Day Cab Truck	
	Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 668 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	9687A	Tractor (Inoperable) S/N: 1XPSD79X0GD263208 C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 202 in Wheelbase, PTO	
9685A	Club Car Carryall 1500 Utility Vehicle		Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED	
	(Inoperable) S/N: 104027428 C/W: Canopy, 2 Passenger, Brush Guard, Manual Dump Bed, 2 Cylinder 1500 cc Gasoline Engine Usage: 610 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
		9688	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X2FD262706 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires	
060ED	Asset located in: Lake Worth, TX	1	Diesel Exhaust Fluid, 21970 Engine hrs, Eaton Fuller Manual Transmission, 13201 lb Front	
9685B	2018 Club Car Carryall 1500G Utility Vehicle (Inoperable) S/N: RC1918967726 C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 482 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE DELICITED IN BUST BE REMOVED.		Axle, 40000 lb Rears, 53200 lb GV Cab, 11R22.5, Air Trac Air Ride Su 206 in Wheelbase, PTO, Auto Lube Usage: 745,623 Mi Notes : INOPERABLE ITEM MUST I FROM YARD BY JANUARY 10TH A BE RELISTED; BUYER'S RESPONS REMOVAL;	Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 206 in Wheelbase, PTO, Auto Lube Usage: 745,623 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL ; ADDITIONAL INFORMATION	9689	2015 Peterbilt 365 6x4 T/A Day Cab Truck	
	AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX		Tractor (Inoperable)	
9686	John Deere Gator XUV Utility Vehicle (Inoperable) S/N: 1M0835EAPMM040361 C/W: Canopy, 2 Passenger, Manual Dump Bed, John Deere 3 Cylinder Engine Usage: 1,574 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		S/N: 1XPSD79X0FD263191 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 7302 Engine hrs, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube Usage: 539,809 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	

Details Lot # **Details** Lot # 2012 Peterbilt 365 6x4 T/A Day Cab Truck 9693 2013 Freightliner Cascadia 125 6x4 T/A Day 9689A Tractor (Inoperable) Cab Truck Tractor (Inoperable) S/N: 1FUJGEDV1DLBV2601 S/N: 1XPSD79X8CD166896 C/W: Cummins ISX11.9 385V 6 Cylinder 11.9 L C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW15210C 10-Speed Diesel 385 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 26030 Engine hrs, Eaton Fuller 8LL Manual Transmission, Manual Transmission, 12000 lb Front Axle, 12000 lb Front Axle, 40000 lb Rears, 52000 lb 40000 lb Rears, Meritor MT-40-14X4 Drive GVWR, Air Ride Cab, Aluminum Wheels, 11R22. Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air 5, Air Trac Suspension, 202 in Wheelbase, PTO Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 195 in Wheelbase, Usage: 656,774 Mi **Dual Fuel Tanks** Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Usage: 588,339 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVAL REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -Asset located in: Lake Worth, TX PLEASE SEE THE INSPECTION REPORT 9690 2013 Kenworth T800 6x4 T/A Day Cab Truck Asset located in: Humble, TX Tractor (Inoperable) 9694 2014 Freightliner Cascadia 113 6x4 T/A Day S/N: 1XKDDP9X9DJ369135 C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel Cab Truck Tractor (Inoperable) 455 hp Engine, Requires Diesel Exhaust Fluid, S/N: 3AKJGBDV6ESFU4154 Engine Brake, Eaton Fuller 10-Speed Manual C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 199 in Wheelbase, Air Sliding 5th Exhaust Fluid, Engine Brake, Eaton Fuller FRO-14210c 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-Wheel, EQUIPMENT-FROM-A-PRIMORIS-145 Drive Axles, 3.42:1 Axle Ratio, 46000 lb SERVICES-CORP-COMPANY GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 200 in Usage: Not Available Wheelbase, PTO, Blower Notes: INOPERABLE ITEM MUST BE REMOVED Usage: Not Available FROM THE YARD BY JANUARY 10TH AND **CANNOT BE RELISTED** Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT Asset located in: Lake Worth, TX BE RELISTED; BUYER'S RESPONSIBILITY FOR 9691 2019 Peterbilt 567 6x4 T/A Day Cab Truck REMOVAL; Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 1XPCD79X0KD612896 9694A 2009 Volvo VNM 6x4 T/A Day Cab Truck C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Tractor (Inoperable) Diesel 385 hp Engine, 2018 US ÉPA Label, Requires Diesel Exhaust Fluid, 13200 lb Front S/N: 4V4MC9EG39N283601 Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air C/W: Volvo D13 6 Cylinder 375 hp Engine, Eaton Fuller FR-14210B 10-Speed Manual Ride Suspension, 202 in Wheelbase Transmission, 12000 lb Front Axle, 18739 lb Rears, 49478 lb GVWR, 275/80R22.5, Air Ride Usage: Not Available Suspension, 168 in Wheelbase, Lowboy Notes: INOPERABLE ITEM MUST BE REMOVED Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-FROM YARD BY OCTOBER 18TH AND CANNOT YELLOW-CORP BE RELISTED; BUYER'S RESPONSIBILITY FOR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Asset located in: Lake Worth, TX FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR 9691A 2016 Freightliner Cascadia 125 6x4 T/A Day REMOVAL Cab Truck Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 3AKJGEDVXGSGV9490 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 596,350 Mi **Notes**: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT

BE RELISTED; BUYER'S RESPONSIBILITY FOR

Asset located in: Lake Worth, TX

REMOVAL

Lot #	Details	Lot #	Details
9695	2007 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9GF47N449500 C/W: Volvo D12D365 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Manual Transmission, 275/80R22.5, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,615,127 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9697	2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPBD49X1LD655901 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 23259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 5200 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 752,578 Mi
9696	2003 Volvo VNL 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4NC9GH93N350140 C/W: Volvo 6 Cylinder Diesel Engine, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX
	Rears, Meritor RT-40-145 Drive Axles, 3.58:1 Axle Ratio, 50000 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9698	2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPBD49X6LD655909 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front
9696A	2004 Peterbilt 379 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XP5DB9X74D827027 C/W: Cat C15 6 Cylinder 14.6 L 475 hp Engine, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, PTO, Hydraulic System, Air Sliding 5th Wheel, Winch, Headache Rack, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: Not Available	9700	Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX 2016 Peterbilt 579 6x4 T/A Sleeper Truck
	Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM; LOCATED-IN-FORT- WORTH-TX Asset located in: Lake Worth, TX		Tractor (Inoperable) S/N: 1XPBD49X1GD326444 C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential
9696B	2014 Mack GU713 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1M2AX04Y5EM019283 C/W: Mack 6 Cylinder Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Mack Maxitorque 10-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, 11R24.5, Air Ride Suspension, 219 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM; LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 245 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX

Page 542 of 581 **Details** Lot# **Details** Lot # 9701 2016 Peterbilt 579 6x4 T/A Sleeper Truck 9703 2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable) Tractor (Inoperable) S/N: 1XKYDP9X0FJ437603 S/N: 1XPBD49X2GD346556 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp C/W: Cummins ISX15 6 Cylinder 15.0 L 485 hp Engine, 2015 US EPA Label, Requires Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 24608.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Exhaust Fluid, Engine Brake, 12000 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper 52000.0 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 249 in Wheelbase, Air Paccar Air Ride Suspension, 228 in Wheelbase, **Dual Fuel Tanks** Sliding 5th Wheel, Headache Rack, Dual Fuel Usage: Not Available Tanks Notes: DEFICIENCIES NOTED - PLEASE SEE Usage: 707,094 Mi THE INSPECTION REPORT INOPERABLE ITEM Asset located in: Lake Worth, TX MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S 9701A 2019 Kenworth T680 6x4 T/A Sleeper Truck RESPONSIBILITY FOR REMOVAL: Tractor Asset located in: Humble, TX S/N: 1XKYD49X5KJ310239 9704 2015 Kenworth T680 6x4 T/A Sleeper Truck C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Tractor (Inoperable) Diesel Exhaust Fluid, Engine Brake, Paccar S/N: 1XKYDP9X0FJ464641 Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, Paccar C/W: Paccar 6 Cylinder Diesel 455 hp Engine, Requires Diesel Éxhaust Fluid, 19664 Engine Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk hrs, Engine Brake, Eaton Fuller FO-16E310C-LAS Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, Air Ride Suspension, 233 in Wheelbase, PTŎ, 36 in Mid Roof Sleeper Cab, Aluminum Wheels, Dual Fuel Tanks 295/75R22.5, Paccar Air Ride Suspension, 204 Usage: Not Available in Wheelbase, Dual Fuel Tanks Usage: 683,198 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT Notes: INOPERABLE ITEM MUST BE REMOVED BE RELISTED; BUYER'S RESPONSIBILITY FOR FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH REMOVAL; A REPOSESSION AFFIDAVIT AND MAY NOT BE Asset located in: Lake Worth, TX ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING 9704A 2013 Kenworth T660 6x2 T/A Sleeper Truck Asset located in: Midland, TX Tractor (Inoperable) S/N: 1XKAA48X9DJ365291 9702 2016 Kenworth T680 6x4 T/A Sleeper Truck C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Tractor (Inoperable) Diesel 400 hp Engine, 20304 Engine hrs, Engine S/N: 1XKYD49X6GJ463607 Brake, Eaton Fuller Automated Transmission, C/W: Cummins ISX15 450ST2 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, 12000 lb Front Axle, 34000 lb Rears, 2.53:1 Axle Ratio, 46000 lb GVWR, Air Ride Cab, 52 in Requires Diesel Exhaust Fluid, 23925 Engine Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride

hrs, Engine Brake, Eaton Fuller 12-Speed Automated Transmission, 12350 lb Front Axle, 36000 lb Rears, 2.64:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Flex Air Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 793,933 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR

REMOVAL;

Asset located in: Lake Worth, TX

Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 914,459 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR RFMOVAL

Asset located in: Lake Worth, TX

Details Lot# **Details** Lot # 9704B 2019 International LoneStar 6x4 T/A Sleeper 9707 2020 Freightliner Cascadia 126 6x4 T/A **Truck Tractor (Inoperable)** Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR5LSKS3557 S/N: 3HSLGAPR6KN527657 C/W: Cummins X15 500 6 Cylinder 15.0 L C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Diesel 500 hp Engine, 2018 ÚS EPA Label, Engine, 2019 US EPA Label, Requires Diesel Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13200 lb Front Axle, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Air Ride 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Suspension, 225 in Wheelbase, Air Sliding 5th Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Wheel, Dual Fuel Tanks Usage: 718,536 Mi Usage: 608,756 Mi Asset located in: Lake Worth, TX Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND 2011 Mack CHU613 6x2 T/A Sleeper Truck 9705 CANNOT BE RELISTED Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 1M1AN07Y2BM006847 2020 Freightliner Cascadia 125 6x4 T/A 9707A C/W: Mack MP8 6 Cylinder Engine, Engine Brake, Eaton Fuller 10-Speed Manual Sleeper Truck Tractor (Inoperable) Transmission, 12000 lb Front Axle, 40000 lb S/N: 3AKJGLDR6LDLX1078 Rears, Mack Drive Axles, 52000 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650-Suspension, 248 in Wheelbase, Air Sliding 5th OH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor Wheel, Dual Fuel Tanks Usage: Not Available MT-40-14X Drive Axles, 3.08:1 Axle Ratio, Notes: INOPERABLE ITEM MUST BE REMOVED 53300 lb GVWR, Air Ride Cab, 72 in High Rise FROM THE YARD BY JANUARY 10TH AND Sleeper Cab, Bunk Beds, Carrier ComfortPro CANNOT BE RELISTED Auxiliary Power Unit, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 230 in Asset located in: Lake Worth, TX Wheelbase, Air Sliding 5th Wheel, Dual Fuel 9706 **Tanks** 2021 Freightliner Cascadia 126 6x4 T/A Usage: Not Available Sleeper Truck Tractor (Inoperable) Notes: INOPERABLE ITEM MUST BE REMOVED S/N: 3AKJHHDR2MSMU7290 FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2020 US EPA Label, Requires Diesel REMOVAL Exhaust Fluid, Engine Brake, Automated Transmission, 13300 lb Front Axle, 40000 lb Asset located in: Lake Worth, TX Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 11R22.5 Front Tires, 295 9709 2019 Freightliner Cascadia 126 6x4 T/A /75R22.5 Rear Tires, Airliner Suspension, 235 Sleeper Truck Tractor (Inoperable) in Wheelbase, Air Sliding 5th Wheel, Dual Fuel S/N: 3AKJHHDR0KSKC2651 Tanks C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 27034 Engine hrs, Engine Brake, Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Detroit DT12-1750-HD1 12-Speed Automated FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.16:1 REMOVAL Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Asset located in: Lake Worth, TX High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL:

Asset located in: Lake Worth, TX

Usage: 623,235 Mi

Details Lot # **Details** Lot # 9710 2018 Freightliner Cascadia 126 6x4 T/A 9712 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR5JSJK6667 S/N: 3AKJHHDR3JSJW8538 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low C/W: 6 Cylinder Diesel Engine, Detroit 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12-Speed 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Automated Transmission, 13300 lb Front Axle, Cab, 72 in High Rise Sleeper Cab, 295/75R22.5, 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb Airliner Air Ride Suspension, Air Sliding 5th GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Wheel Usage: Not Available Sliding 5th Wheel, Headache Rack, Dual Fuel Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV Tanks Usage: Not Available PRIOR TO BIDDING; INOPERABLE ITEM MUST Notes: INOPERABLE ITEM MUST BE REMOVED BE REMOVED FROM THE YARD BY JANUARY FROM THE YARD BY JANUARY 10TH AND 10TH AND CANNOT BE RELISTED CANNOT BE RELISTED Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 2018 Freightliner Cascadia 125 6x4 T/A 9713 2017 Freightliner Cascadia 125 6x4 T/A 9711 Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR0JSJR7937 S/N: 3AKJGLDR9HSJC5723 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 C/W: Detroit DD15 14.8 L Engine, Requires hp Engine, 2018 US EPA Label, Requires Diesel Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Exhaust Fluid, Retarder, Detroit DT12-OA-1650 10-Speed Manual Transmission, Differential 12-Speed Automated Transmission, 12350 lb Lock, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5 Front Tires, 425/65R22.5 Super Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Singles Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Wheel, Dual Fuel Tanks **Fuel Tanks** Usage: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Notes: SELLING WITH A REPOSESSION FROM YARD BY JANUARY 10TH AND CANNOT AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV BE RELISTED; BUYER'S RESPONSIBILITY FOR PRIOR TO BIDDING; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH REMOVAL; Asset located in: Humble, TX AND CANNOT BE RELISTED; BUYER'S 2018 Freightliner Cascadia 125 6x4 T/A RESPONSIBILITY FOR REMOVAL 9711A Sleeper Truck Tractor (Inoperable) Asset located in: Midland, TX S/N: 3AKJGLDR7JSJU3695 9713A 2017 Freightliner Cascadia 125 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 Sleeper Truck Tractor hp Engine, 2017 US EPA Label, Requires Diesel S/N: 3AKJGLDR2HSGV8021 Exhaust Fluid, Engine Brake, Detroit 12-Speed C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Exhaust Fluid, Engine Brake, Eaton Fuller 12-Ride Cab, 72 in High Rise Sleeper Cab, Bunk Speed Automatic Transmission, 12500 lb Front Beds, Thermo King TriPac Evolution Auxiliary Power Unit, 11R22.5, Airliner Suspension, 228 Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Sleeper Air Conditioner, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 224 in Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: 484,584 Mi Tanks Notes: INOPERABLE ITEM MUST BE REMOVED

Usage: 742,975 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Asset located in: Lake Worth, TX

FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR

Asset located in: Lake Worth, TX

REMOVAL

Details Lot # **Details** Lot # 9714 2016 Freightliner Cascadia 125 6x4 T/A 9719 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR4ESFD3920 S/N: 1FUJGLD5XGLGU2219 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel hp Engine, 2015 US EPA Label, Requires Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 24994 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Exhaust Fluid, 10571 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Transmission, Differential Lock, 12350 lb Front 12000 lb Front Axle, 40000 lb Rears, Detroit DA-Axle, 40000 lb Rears, Planetary Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, MIXED, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Sliding 5th Wheel, Dual Fuel Tanks Usage: 730,665 Mi Usage: 1,029,912 Mi Notes: INOPERABLE ITEM MUST BE REMOVED Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND FROM YARD BY JANUARY 10TH AND CANNOT CANNOT BE RELISTED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL: NOTED - PLEASE SEE THE INSPECTION Asset located in: Lake Worth, TX REPORT 9720 2014 Freightliner Cascadia 125 6x4 T/A Asset located in: Humble, TX Sleeper Truck Tractor (Inoperable) 9715 2016 Freightliner Cascadia 125 6x4 T/A S/N: 1FUJGLD61ELFM1902 Sleeper Truck Tractor (Inoperable) C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel S/N: 3AKJGLDV4GSHD4846 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 Exhaust Fluid, Engine Brake, Eaton Fuller FROhp Engine, Requires Diesel Exhaust Fluid, 16210C 10-Speed Manual Transmission, Engine Brake, Detroit 12-Speed Automated 12000 lb Front Axle, 40000 lb Rears, Meritor Transmission, 12500 lb Front Axle, 40000 lb MT-40-14X Drive Axles, 3.25:1 Axle Ratio, Rears, Meritor RT-40-145 Drive Axles, 2.64:1 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 244 in /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Headache Rack, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available Tanks Notes: INOPERABLE ITEM MUST BE REMOVED Usage: Not Available FROM YARD BY OCTOBER 18TH AND CANNOT **Notes**: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL RECONSIGNED DEFICIENCIES NOTED Asset located in: Midland, TX PLEASE SEE THE INSPECTION REPORT 9721 INOPERABLE ITEM MUST BE REMOVED FROM 2012 Freightliner Cascadia 125 6x4 T/A YARD BY JANUARY 10TH AND CANNOT BE Sleeper Truck Tractor (Inoperable) RELISTED; BUYER'S RESPONSIBILITY FOR S/N: 1FUJGLBG8CSBM1768 REMOVAL: C/W: Cummins ISX 6 Cylinder 450 hp Engine, Asset located in: Lake Worth, TX Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DS404 Drive Axles, 3.55:1 Axle 9716A 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Ratio, 53200 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride S/N: 3AKJGLDR8GSGV0892 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Suspension, 228 in Wheelbase, Air Sliding 5th hp Engine, Requires Diesel Exhaust Fluid, Whėel 21275 Engine hrs, Engine Brake, Detroit DT12-Usage: Not Available OH-1650 12-Speed Automated Transmission, Notes: INOPERABLE ITEM MUST BE REMOVED 13300 lb Front Axle, 40000 lb Rears, Meritor FROM YARD BY JANUARY 10TH AND CANNOT MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5 Front Tires, 445/50R22.5 Super Asset located in: Lake Worth, TX Singles Rear Tires, Airliner Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 873,267 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT

BE RELISTED; BUYER'S RESPONSIBILITY FOR

Asset located in: Lake Worth, TX

REMOVAL

Details Lot# **Details** Lot # 9722 2018 Volvo VNL 6x4 T/A Sleeper Truck Tractor 9725 2019 International LT625 6x4 T/A Sleeper (Inoperable) Truck Tractor (Inoperable) S/N: 4V4NC9EH1JN961795 S/N: 3HSDZAPR7KN110756 C/W: Volvo D13M455 6 Cylinder 12.8 L 455 hp C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Exhaust Fluid, Engine Brake, Automatic Speed Automated Transmission, 12350 lb Transmission, Differential Lock, 12350 lb Front Front Axle, 38000 lb Rears, Meritor MT-40-14X Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Drive Axles, 2.47:1 Axle Ratio, 50350.0 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, /80R22.5, Air Ride Suspension, 224 in Air Sliding 5th Wheel, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Usage: 1,015,854 Mi FROM THE YARD BY JANUARY 10TH AND Notes: INOPERABLE ITEM MUST BE REMOVED CANNOT BE RELISTED FROM YARD BY JANUARY 10TH AND CANNOT Asset located in: Lake Worth, TX BE RELISTED; BUYER'S RESPONSIBILITY FOR RFMOVAL 9726 2019 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 3HSDZAPR0KN110761 9723 2017 Volvo VNL670 6x4 T/A Sleeper Truck C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Tractor (Inoperable) S/N: 4V4NC9THXHN983209 Exhaust Fluid, Engine Brake, Automatic C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 10-Speed Manual Transmission, 12350 lb Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Usage: Not Available Beds, 11R22.5, Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP Usage: Not Available INOPERABLE ITEM MUST BE REMOVED FROM Notes: INOPERABLE ITEM MUST BE REMOVED THE YARD BY JANUARY 10TH AND CANNOT FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE Asset located in: Lake Worth, TX SEE THE INSPECTION REPORT 9727 2019 International LT625 6x4 T/A Sleeper Asset located in: Humble, TX Truck Tractor (Inoperable) S/N: 3HSDZAPR5KN098185 2016 Volvo VNL 780 6x2 T/A Sleeper Truck 9724 C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Tractor (Inoperable) S/N: 4V4N99EH7GN950842 Exhaust Fluid, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, C/W: Volvo D13 6 Cylinder 12.8 L Diesel 425 hp Engine, Requires Diésel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Air Ride Suspension, 224 in Wheelbase, Air 61 in High Rise Sleeper Cab, Bunk Beds, Sliding 5th Wheel, Dual Fuel Tanks Aluminum Wheels, 295/75R22.5, Volvo Usage: Not Available Corporate Air Air Ride Suspension, 228 in Notes: LOADING ASSISTANCE UNAVAILABLE Wheelbase, Air Sliding 5th Wheel, Dual Fuel ON THIS UNIT. OUTSIDE LOADING Tanks ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM Usage: 826,608 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT

BE RELISTED; BUYER'S RESPONSIBILITY FOR

Asset located in: Lake Worth, TX

REMOVAL

THE YARD BY JANUARY 10TH AND CANNOT

Asset located in: Lake Worth, TX

BE RELISTED

Details Lot # **Details** Lot # 9728 2019 International LT625 6x4 T/A Sleeper 9731 2006 Volvo VT 880 6x4 T/A Sleeper Truck **Truck Tractor (Inoperable)** Tractor (Inoperable) S/N: 3HSDZAPRXKN109682 S/N: 4V4LC9KL86N419522 C/W: Volvo D16D600 6 Cylinder 16.1 L Diesel C/W: Cummins X15 6 Cylinder 15 L 450 hp 600 hp Engine, 2006 US EPA Label, Eaton Fuller 18-Speed Manual Transmission, 12500 Ib Front Axle, 38000 lb Rears, 50500 lb GVWR, Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 256 in Wheelbase, Air Sliding 5th Usage: Not Available Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING Notes: INOPERABLE ITEM MUST BE REMOVED ASSISTANCE WILL NEED TO BE SET UP. FROM YARD BY JANUARY 10TH AND CANNOT INOPERABLE ITEM MUST BE REMOVED FROM BE RELISTED; BUYER'S RESPONSIBILITY FOR THE YARD BY JANUARY 10TH AND CANNOT REMOVAL **BE RELISTED** Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 9732 2000 Freightliner Columbia 120 6x4 T/A 9729 2018 International LT625 6x4 T/A Sleeper Sleeper Truck Tractor (Inoperable) **Truck Tractor (Inoperable)** S/N: 1FUYSSZB1YLF32067 S/N: 3HSDZAPR2JN438729 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Engine Brake, Eaton Fuller 10-Speed C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 73 in Aluminum Outer Wheels, 295/75R22.5, Airliner Suspension, 234 in Wheelbase, Air Sliding 5th High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 244 in Wheelbase, Air Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Sliding 5th Wheel, Dual Fuel Tanks FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED **REMOVAL:** FROM YARD BY JANUARY 10TH AND CANNOT Asset located in: Lake Worth, TX BE RELISTED; BUYER'S RESPONSIBILITY FOR 9733 1999 Volvo VNL 6x4 T/A Sleeper Truck Tractor Asset located in: Lake Worth, TX (Inoperable) S/N: 4VG7DAJJ8XN788188 9730 2018 International LT625 6x4 T/A Sleeper C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller FRO-16210C Manual Transmission, 12350 lb Front Axle, 38000 lb Truck Tractor (Inoperable) S/N: 3HSDZTZR4JN416241 C/W: Navistar A26 6 Cylinder 13 L Diesel Rears, Eaton Drive Axles, 3.7:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in Mid Roof Engine, Requires Diesel Exhaust Fluid, 6691 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 73 in Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 212 in Wheelbase, Lowboy Ramps, Dual Fuel Tanks Mid Roof Sleeper Cab, Thermo King TriPac Usage: Not Available Evolution Auxiliary Power Unit, Aluminum Notes: INOPERABLE ITEM MUST BE REMOVED Wheels, 295/75R22.5 Front Tires, 445/50R22.5 FROM THE YARD BY JANUARY 10TH AND Super Singles Rear Tires, Hendrickson Air Ride CANNOT BE RELISTED Suspension, 228 in Wheelbase, Air Sliding 5th Asset located in: Lake Worth, TX Wheel, Dual Fuel Tanks Usage: 671,789 Mi 9734 1998 Freightliner FLD 120 6x4 T/A Sleeper Notes: UNIT STARTS AND RUNS, ENGINE Truck Tractor (Inoperable) SEVERELY DERATED; INOPERABLE ITEM S/N: 1FUYDDYB5WPA02987 MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S C/W: 12000 lb Front Axle, 38000 lb Rears, 48000 lb GVWR, Air Ride Cab, 48 in Flat Top RESPONSIBILITY FOR REMOVAL; Sleeper Cab, 285/75R24.5, Air Ride Asset located in: Lake Worth, TX Suspension, 211 in Wheelbase, Dual Fuel Tanks Usage: 535,289 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT

BE RELISTED; BUYER'S RESPONSIBILITY FOR

Asset located in: Lake Worth, TX

REMOVAL

Lot #	Details	Lot #	Details
9734A	2012 Ford F-550 XL 4x2 Extended Cab Service Truck (Inoperable) S/N: 1FD0X5GT6CEC35272 C/W: V8 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 186 in Wheelbase, 14 ft Body, Hydraulic Stabilizers, Liberator 6HYD-LS 6000 lb 3 Section Hydraulic Crane Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9737	2013 International 7600 6x4 Vacuum Excavator Truck (Inoperable) S/N: 1HTGSSJT1DJ167340 C/W: International 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 385 /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 263 in Wheelbase, 58000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9734B	2019 Nissan Frontier 4x2 Extended Cab Utility Truck (Inoperable) S/N: 1N6AD0CU5KN753789 C/W: Nissan V6 4.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 3296 lb Front Axle, 3331 lb Rears, 5588 lb GVWR, 265 /70R16, Spring Suspension, 126 in Wheelbase, 6 ft 8 in Body Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9738	1988 International 1954 4x2 Vacuum Excavator Truck (Inoperable) S/N: 1HTLDTVN5JH610926 C/W: 6 Cylinder Diesel Engine, 5809 Engine hrs, Manual Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 188 in Wheelbase, PTO, Dual Fuel Tanks Usage: 326,151 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2008 International 4400 4x2 Pressure Truck
9735	Asset located in: Lake Worth, TX 2011 Capacity TJ5000 4x2 Spotter Truck (Inoperable) S/N: 4LMBR2118BL022572 C/W: Cummins 6 Cylinder 6.7 L Diesel 173 hp Engine, Allison Automatic Transmission, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available	9739	(Inoperable) S/N: 1HTMKAAN08H535972 C/W: 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 208 in Wheelbase, Dual PTO, Triplex Pump, Steel Tank Usage: Not Available Asset located in: Lake Worth, TX
9736	Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2012 Peterbilt 367 6x4 Winch Truck (Inoperable) S/N: 1XPTD40X4CD146614 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 15245 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 225 in Wheelbase, PTO, Tail Roll, Ramsey Winch, Lowboy Ramps Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9740	2010 Mack 6x4 Cab and Chassis (Inoperable) S/N: 1M2AN09C3AN006300 C/W: Mack MP8 6 Cylinder 12.8 L 425 hp Engine, 2008 US EPA Label, Engine Brake, Allison Automatic Transmission, Mack Drive Axles, Air Ride Cab, 11R24.5, Camelback Spring Suspension, 220 in Wheelbase, 130 in Cab to Axle, 180 in Cab to End of Frame Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, CANNOT BE DRIVEN. TEMP TAGS WILL NOT BE ISSUED; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9741	2012 Freightliner M2 106 4x2 Cab and Chassis (Inoperable) S/N: 1FVACWDT5CDBD9009 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 5.29:1 Axle Ratio, 10R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 252 in Wheelbase, 90 in Cab to Axle, 139 in Cab to End of Frame Usage: 151,346 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX	9743A	2004 Ford F-550 4x2 Cab and Chassis (Inoperable) S/N: 1FDAF56P64EC24687 C/W: V8 6.0 L Diesel 325 hp Engine, 2004 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 19000 lb GVWR, Aluminum Outer Wheels, 245/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 165 in Wheelbase, 84 in Cab to Axle, 132 in Cab to End of Frame Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
9742	1999 Volvo VN 4x2 Cab and Chassis (Inoperable) S/N: 4VA7BBRF8XN784017 C/W: Detroit Series 60 6 Cylinder 11.1 L Diesel 365 hp Engine, 1998 US EPA Label, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 152 in Wheelbase, 89 in Cab to Axle, 121 in Cab to End of Frame, Pintle Hitch Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; LOCATED-IN-JUSTIN-TX; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Lake Worth, TX	9744 9745A	2006 International 4300 SBA 4x2 Flatbed Truck (Inoperable) S/N: 1HTMMAAM46H186863 C/W: International D210CFF 6 Cylinder 7.6 L Diesel 210 hp Engine, 2005 US EPA Label, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, 153 in Wheelbase, Arrow Board Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2010 Mitsubishi Fuso 4x2 COE Extended Cab Flatbed Truck (Inoperable) S/N: JL6CCG1S4AK009133 C/W: Mitsubishi 4 Cylinder Diesel Engine,	
9742A	2012 Chevrolet 3500 4x2 Crew Cab Cab and Chassis (Inoperable) S/N: 1GB4CZCL2CF161801 C/W: GM 6.6 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5200 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 265/70R17, Spring Suspension, 172 in Wheelbase, 60 in Cab to Axle, 112 in Cab to End of Frame Usage: Not Available		Automatic Transmission, 6390 lb Fi 12700 lb Rears, 17995 lb GVWR, 21 Spring Suspension, 153 in Wheelba in x 91 in Bed Usage: 162,766 Mi Notes: INOPERABLE ITEM MUST BI FROM YARD BY JANUARY 10TH AN BE RELISTED; BUYER'S RESPONSIE REMOVAL Asset located in: Humble, TX	Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 17995 lb GVWR, 215/75R17.5, Spring Suspension, 153 in Wheelbase, 14 ft 3 in x 91 in Bed Usage: 162,766 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		1998 International 4900 6x4 Flatbed Truck (Inoperable) S/N: 1HTSHAAR5WH533334 C/W: 6 Cylinder Diesel Engine, International 6- Speed Manual Transmission, 11R22.5,	
9743	2016 Chevrolet Express G3500 4x2 Cab and Chassis (Inoperable) S/N: 1GB3GRCG1G1277688 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225 /75R16, Spring Suspension, 142 in Wheelbase, 81 in Cab to Axle, 139 in Cab to End of Frame Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX		Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 226 in Wheelbase 23 ft x 94 in Bed, Dovetail, Hydraulic Ramps Usage: 58,070 Mi Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNOBE RELISTED; BUYER'S RESPONSIBILITY FOIREMOVAL Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9745B 9746	2011 Dodge Ram 5500 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 3D6WA7CL0BG612391 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 196 in Wheelbase, 12 ft x 102 in Bed Usage: Not Available Asset located in: Lake Worth, TX 2018 Ram 4500 4x2 Crew Cab Flatbed Truck (Inoperable)	9748	2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT7KEC83810 C/W: Ford Power Stroke V8 6.7 L Diesel 330 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 2 in x 92 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
	S/N: 3C7WRKEL5JG259100 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 325		Asset located in: Lake Worth, TX	
	hp Engine, 2018 US EPÁ Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 175 in Wheelbase, 9 ft 5 in x 93 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9748A	2018 Ford F-350 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT7JEC67900 C/W: Ford Power Stroke V8 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 3.73:1 Axle Ratio, 140000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 2 in x 90 in Bed, Receiver hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY	
	Asset located in: Lake Worth, TX		Usage: Not Available	
9747	2006 Ford F-450 XL 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1FDXW46P46EB71060 C/W: V8 6.0 L Diesel Engine, 2008 US EPA Label, Automatic Transmission, 6500 lb Front		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	Axle, 12000 lb Rears, 16000 lb GVWR, 245 /70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft x 93 in Bed Usage: 170,254 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9749	9749	2018 Ford F-250 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FT7W2BT4JEB73055 C/W: V8 6.7 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 6340 lb Rears, 10000 lb GVWR, 33X12. 50R18, Spring Suspension, 176 in Wheelbase, 8
9747A	2022 Ram 3500 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 3C7WRTCL3NG365057 C/W: 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic		ft 6 in x 80 in Bed, Fuel Tank /w Pump Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	
	Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; PLEASE SEE DEFICIENCIES, TRANSMISSION IS IN VERY BAD CONDITION	9750	2007 Ford F-550 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1FDAW56PX7EA92103 C/W: Automatic Transmission, 6500 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225-70R19.5, Spring Suspension, 12 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	

Asset located in: Lake Worth, TX

			Page 551 of 581
Lot #	Details	Lot #	Details
9750A	2016 Ford F-350 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT1GED26318 C/W: Ford Power Stroke 6.2 L Diesel Engine, 2016 US EPA Label, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, Aluminum Wheels, 245/75R17, Spring Suspension, 178 in Wheelbase, 9 ft 4 in x 93 in Bed, Receiver, Fifth wheel ball Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9753	2015 Freightliner 114SD 6x4 Mixer Truck (Inoperable) S/N: 1FVHG3DV3FHGC6645 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17826 Engine hrs, Engine Brake, Allison 4000 Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 208,567 Mi
9751	2017 GMC 3500 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1GT42VCY6HF232993 C/W: V8 Diesel Engine, Automatic Transmission, 5600 lb Front Axle, 7050 lb Rears, 11600 lb GVWR, 275/65R18, Spring Suspension, 166 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX 2015 Freightliner 114 SD 6x4 Mixer Truck (Inoperable) S/N: 1FVHG3DV7FHGD3310 C/W: Detroit 6 Cylinder 12.8 L Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, 425/65R22.5, Double Frame, Rubber over Walking Beam
9751A	2012 Peterbilt 388 6x4 Sleeper Car Carrier Truck (Inoperable) S/N: 1NPWD49X3CD134979 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 45000 lb GVWR, 48 in Mid Roof Sleeper Cab, 295/60R22.5, Air Leaf Air Ride Suspension, 254 in Wheelbase, PTO, Hydraulic Lift, Soft Tie Downs, SOLD WITH - 2011 Cottrell CX-11HCSD T/A, Trailer S/N - 5E0AJ1445CG349901, Soft Ties, 255/70R22.5 Tires, 45000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Suspension, 229 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX 1999 Peterbilt 357 8x4 Mixer Truck (Inoperable) S/N: 1NPALTOX7XD494329 C/W: Cat C10 6 Cylinder Ultra Low Sulfur Diesel Engine, 21033 Engine hrs, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 53200 lb Rears, 60000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Trailing Tag Axle, Hendrickson Walking Beam Suspension, 250 in Wheelbase, PTO, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 212,655 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9756	2019 International 4300 4x2 Rollback Truck (Inoperable) S/N: 3HAEUMML5KL556456 C/W: Cummins B 6 Cylinder 6.7 L 300 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7063 Engine hrs, Allison Automatic Transmission, 8000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 255/70R22.5, Air Ride Suspension, 210 in Wheelbase, PTO, Miller Rollback Body, 19 ft 4 in x 102 in Bed, Ramsey HD234 8000 lb Winch Usage: 142,777 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9759	2020 GMC G3500 4x2 Van Truck (Inoperable) S/N: 7GZ37TCG1LN010503 C/W: GM V8 6.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225 /75R16, Spring Suspension, 178 in Wheelbase, 17 ft x 96 in Wide x 76 in High Body, Curbside Door Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9761A	2006 MCI J4500 6x2 56-Seat Coach
9757	2016 International 4300 4x2 Van Truck (Inoperable) S/N: 1HTMNAAL1GH031595 C/W: Navistar 6 Cylinder Engine, 2016 US EPA Label, Automatic Transmission, 9000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 8002 Engine hrs, 11R22.5, Spring Suspension, 254 in Wheelbase, 24 ft x 96 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 149,593 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR		(Inoperable) S/N: 2M93JMPA76W063464 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 362 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
	REMOVAL OF THIS ITEM	9761B	2006 MCI J4500 6x2 56-Seat Coach
9758	Asset located in: Lake Worth, TX 2012 Isuzu NPR 4x2 COE Van Truck (Inoperable) S/N: JALE5W163C7301062 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 177 in Wheelbase, Morgan 18 ft x 96 in Wide x 85 in High Body, Curbside Door, Liftgate Usage: Not Available		(Inoperable) S/N: 2M93JMPA46W063454 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit 6 Cylinder Diesel Engine, 315 /80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9761C	2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPA26W063548 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Asset located in: Humble, TX

		1		
Lot #	Details	Lot #	Details	
9761D	2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPA06W063547 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9762C	Tractor (Inoperable) S/N: 1XPBA48X5FD286278 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 12-Speed Automated Transmission, 12000 lb Front Axi 22701 lb Rears, 34700 lb GVWR, 295/75R22. Air Trac Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOV FROM YARD BY JANUARY 10TH AND CANN	Tractor (Inoperable) S/N: 1XPBA48X5FD286278 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 12-Speed Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Trac Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9762	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor (Inoperable)		REMOVAL Asset located in: Lake Worth, TX	
07604	S/N: 1XPBA48X4GD339490 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21678.6 Engine hrs, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 862,236 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9763	2018 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYAP8X5JJ207624 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Lov Sulfur Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11R22.5, Air Ride Suspension, EQUIPMENT-FROM-YELLOW CORP Usage: 490,446 Mi Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
9762A	2005 MCI J4500 6x2 56-Seat Coach (Inoperable)		Asset located in: Lake Worth, TX	
	S/N: 2M93JMDA45W062954 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9764	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYA48X2EJ355427 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2019 US EPA Label, 16235 Engine hrs, Eaton Fuller FM-15E310B-LAS Automated Transmission, 12700 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 155 in Wheelbase, Air Sliding 5th Wheel	
9762B	2005 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMDA65W063118 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX		Usage: 723,788 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9764A	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBGDD55FLGB0203 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9766	2015 Freightliner M2 112 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBC5CY4FHGK0774 C/W: Cummins ISL9 Diesel 330 hp Engine, Eaton Fuller FO-10E310C-VAS Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 4.56:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 158 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9767	2009 International TranStar 8600 4x2 S/A Day Cab Truck Tractor (Inoperable)
9764B	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3AKBGDDV3ESFV6407 C/W: Detroit DD13 6 Cylinder 12.8 L Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 15959 Engine hrs, Engine Brake, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-161 Drive Axles, 3.58:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 542,172 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		S/N: 1HSHWAHN59J674277 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel Engine, 24234 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 151 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 615,671 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9767A	2009 International 4400 4x2 S/A Day Cab
			Truck Tractor (Inoperable) S/N: 1HSMKAAN99J696805
9765			C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel Engine, 16364 Engine hrs, Allison 6- Speed Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 295 /75R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 153 in Wheelbase Usage: 236,461 Mi Asset located in: Lake Worth, TX
		9768	2005 International 9400i 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HSCPSBN35N049230 C/W: Cat 6 Cylinder Engine, Eaton Fuller Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9768A	2005 International 9400i 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HSCPAPN05N049267 C/W: Cummins ISX 6 Cylinder 400 hp Engine, 2004 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 835,214 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; CANNOT VERIFY ODOMETER READING - VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE Asset located in: Lake Worth, TX	9771 9772 9773	2019 Chevrolet 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KSEY4KF119050 C/W: 6.6 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Fuel Tank, 10000 lb GVWR, 265/70R17 Tires, 4 ft 11 in B Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2019 Ford F-250 XL 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2BT9KEE68282 C/W: Automatic Transmission, Air Conditione
9769	2002 International 9200i 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 2HSCDAMN82C032078 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, 2001 US EPA Label, Eaton Fuller 9-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED		Power Windows, Fuel Tank, RKI Tool Box, Drop- In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2017 Ford F-250 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2B65HEF24902 C/W: 6.7 L V8 Diesel Engine, 2017 US EPA Label, Automatic Transmission, Power
9769A	Asset located in: Lake Worth, TX 2019 Chevrolet 3500HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC4KVCG2KF227899 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 11000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		Windows, Weather Guard Fuel Tank /w Pump, Tool Box, 10000 lb GVWR, 285/70R17 Tires, 6 ft 10 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2015 GMC 2500 4x4 Crew Cab Pickup
9770	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2019 Chevrolet 2500 LT 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KSEY4KF120067 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, 275/70R18 Tires, 7 ft 11 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		(Inoperable) S/N: 1GT12XE87FF109762 C/W: 6.6 L Diesel Engine, 2015 US EPA Labe Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVER FROM YARD BY JANUARY 10TH AND CANDER RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9775	2014 Ford F-250 XL 4x2 Crew Cab Pickup (Inoperable) S/N: 1FT7W2A63EEB14161 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 6 ft 8 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9777B	2011 Ford F-150 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTFW1EF8BKD94995 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 221,657 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9775A	2012 Dodge Ram 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6TD5JT7CG347856 C/W: 5.7 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, 8000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 218,934 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	-9777C	(Inoperable) S/N: 3C6UR4HJXKG643411 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 224,960 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9776	2013 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KVCG2DF243378 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9777D	2015 GMC 2500 4x4 Extended Cab Pickup (Inoperable) S/N: 1GT22XEG0FZ106115 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
9777A	Asset located in: Lake Worth, TX 2011 GMC Sierra 2500HD 4x4 Extended Cab Pickup (Inoperable) S/N: 1GT22ZCG7BZ412902 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 154,930 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9778	2014 Ford F-150 XLT 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTEX1CM5EKG46930 C/W: 3.7 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, UWS Tool Box, 6700 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 177,206 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9778A 9778B	2012 Chevrolet 1500 4x2 Extended Cab Pickup (Inoperable) S/N: 1GCRCPE00CZ144809 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2014 Chevrolet Silverado 1500 4x4 Crew Cab Plug-In Hybrid Pickup (Inoperable)	9780	1997 Ford F-150 XL 4x4 Pickup (Inoperable) S/N: 1FTDF1823VNC21842 C/W: 4.2 L V6 Gasoline Engine, Automatic Transmission, Air Conditioner, 6000 lb GVWR, 255/70R16 Tires, 8 ft Bed, EQUIPMENT-FROM- YELLOW-CORP Usage: 191,594 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
9779	S/N: 3GCUKPEH6EG534447 C/W: 4.3 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, BetterBuilt Tool Box, Drop-In Bed Liner, 7600 lb GVWR, 265 /70R17 Tires, 6 ft Bed Usage: 19,155 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 1994 Dodge Ram 2500 4x2 Pickup (Inoperable) S/N: 1B7KC26C5RS655611	9781	2021 Ford Ranger XL 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTER1EH0MLD55223 C/W: 2.3 L 4 Cylinder Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Northern Tool Equipment Tool Box, 255/70R16 Tires, 6 ft Bed Usage: 32,412 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	C/W: 5.9 L 6 Cylinder Diesel Engine, 5 Speed Manual Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 245/75R16 Tires, 8 ft Bed, EQUIPMENT-FROM-YELLOW-CORP Usage: 184,458 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2015 Chevrolet Spark Automobile (Inoperable) S/N: KL8CD6S93FC709764 C/W: 4 cyl 1.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 94,644 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9779A	2011 Chevrolet Silverado 1500 4x2 Extended Cab Pickup (Inoperable) S/N: 1GCRCPE04BZ255670 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Headache Rack, RKI Tool Box, 6800 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9783	Asset located in: Humble, TX 2017 Jaguar F-Pace AWD SUV (Inoperable) S/N: SADCJ2BN8HA089275 C/W: 4 cyl 2.0 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 77,696 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9783A 9783B	S/N: WA1LGAFE6ED011693 C/W: V6 3.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2003 Lincoln Aviator 2WD SUV (Inoperable) S/N: 5LMEU68H33ZJ43427 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 218,683 Mi	9787	2015 Wabash RFALHSA 53 ft T/A Refrigerated Trailer (Inoperable) S/N: 1JJV532B4FL840000 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		Asset located in: Humble, TX
	PROCESS TITLE Asset located in: Lake Worth, TX	9788	2013 Great Dane 48 ft x 96 in T/A Refrigerated
9784	1995 Fontaine 352J 70000 lb T/A Heavy-Haul Jeep (Inoperable) S/N: 4LF3N2625S3503582 C/W: Sliding 5th Wheel, Air Ride Suspension, 275/70R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		Trailer (Inoperable) S/N: 1GRAA9625DB711787 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Swing Door, Carrier Transcd Refrigeration Unit, Serial Number JAV90746822,, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX
	REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX	9788A	2016 Lucon T-125 S/A (1) Reel Trailer
9786	Asset located in: Lake Worth, TX 2005 Wilson 42 ft T/A Belly Dump Grain Trailer (Inoperable) S/N: 1W1MCF1A35B240910 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 2 Hoppers, Manual Traps, 9 ft Aluminum Box, 72 in, Side Walls, Manual Roll Tarp, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP.		(Inoperable) S/N: 1L9PU1012GG423949 C/W: 225/75R15 Tires, 4260 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE	9789	2014 Sauber 1570-B Hydraulic Cable Puller
	RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		and Tensioner S/N: 1F9UZ1310EV048032 C/W: 2013 US EPA Label, Honda 1 Cylinder .68 L Gasoline Engine Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
		9790	Cat Engine S/N: Not Available C/W: Cat 3116 6 Cylinder 6.6 L Diesel Engine, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY

Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
9791	Quantity of (2) Electric Motor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9797	McElroy PitBull 618 Tracked Fusion Machine S/N: C29981 C/W: 18 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 397 Hr
9792	Quantity of (2) Electric Motor S/N: Not Available C/W: Electrico, Sew-Eurodrive; EQUIPMENT- FROM-US-AUTO-RECYCLING		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
	Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9798	McElroy PitBull 412 Tracked Fusion Machine S/N: C22603 C/W: 13 in Clamp Size On Board Congretor
9793	Quantity of Electric Motor S/N: Not Available C/W: Assorted Size, One Pallet; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		C/W: 13 in Clamp SIze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW Diesel Engine, 7 in Rubber Tracks Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9794	2005 McElroy Roller Fusion Machine (Inoperable) S/N: C11420 C/W: 8 in Clamp SIze, Pipe Cutter Usage: 606 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; RITCHIE-BROS-ENERGY	9799	McElroy PitBull 618 Tracked Fusion Machine S/N: C32754 C/W: 18 in Clamp SIze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 444 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9795	Asset located in: Lahoma, OK McElroy Roller Fusion Machine S/N: C14830 C/W: 8 in Clamp Slze, Pipe Cutter Usage: 352 Hr	9800	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
9796	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK McElroy PitBull 412 Tracked Fusion Machine S/N: C15330	9801	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	C/W: 13 in Clamp SIze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 2,119 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	9802	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9803	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
9804	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9813	Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
9805	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA Quantity of Tongs	9814	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9815	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Sioux S195667 Pipe Stands
9807	Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9816	S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
9808	Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK
	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks
9809	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION M BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEE BUYER RESPONSIBLE FOR LOADOUT. RI
9810	Regan Torus Blowout Preventer S/N: Not Available		THESE ; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
	C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9817	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
9811	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9812	Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9818	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9823	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	1	Asset located in: Lahoma, OK
9819	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9824	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	<u> </u>	Asset located in: Lahoma, OK
9820	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	9825	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	ļ	Asset located in: Lahoma, OK
9821	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9826	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	ļ	Asset located in: Lahoma, OK
9822	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9827	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9828	Quantity of Sioux \$180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9833	Quantity of Sioux \$180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9829	Quantity of Sioux \$180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	9834	Quantity of Sioux \$180201 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
	THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		THESE; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK
9830	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9835	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9831	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9836	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9832	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9837	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9838	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9843	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	<u> </u>	Asset located in: Lahoma, OK
9839	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9844	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9840	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	9845	Quantity of Pipe Stands S/N: Not Available C/W: 2 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK
9841	Quantity of Pipe Stands	9846	Quantity of Pipe Stands
70-11	S/N: Not Available C/W: 6 Stacks Usage: Not Available	3040	S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	ļ	Asset located in: Lahoma, OK
9842	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9847	Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9848	Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9853	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9849	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9854	Quantity of (610) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9850	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9855	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in, There are some 4x4 in mixed in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9851	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9856	Asset located in: Lahoma, OK Quantity of (600) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9852	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9857	Quantity of (580) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9858	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9863	Pipeline Cradle S/N: Not Available C/W: Single Head, Double Roller Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	<u> </u>	Asset located in: Lahoma, OK
9859	Quantity of (10) Approximately 16 ft x 4 ft Skids (10) Stacks & Misc Pieces Pipeline Skids S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE; RITCHIE-BROS-ENERGY Asset located in: McAlester, OK	9864	Darby Pipeline Cradle S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9860	Pipeline Cradle	9865	Asset located in: Lahoma, OK DMH RO Pipeline Cradle
	S/N: Not Available C/W: Double Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		S/N: 485 C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9861	Pipeline Cradle S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9866	2013 Mcclain 28 ft Mobile Flare System S/N: 4LYUS2223DH000570 C/W: T/A, Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, (2) Tool Boxes, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	9866A	Quantity of Assorted Drill Bit
9862	Pipeline Cradle S/N: Not Available C/W: Single Head, Single Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9867	2009 MacElroy LT0048 T/A Hydraulic Line Tamer S/N: C30327 C/W: To Fit McElroy Manufacturing, Inc LineTamer poly pipe straightener, 2002 US EPA Label, Honda GXV160 1 Cylinder 163 cc Gasoline Engine Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9872 9873	Quantity of (102) Rolls of PipelineRock Guard Mesh S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE; RITCHIE-BROS-ENERGY Asset located in: McAlester, OK Sand Silo
9868	Asset located in: Lahoma, OK Quantity of (3) Vaculifter S/N: LT30-000101 C/W: To Fit lift technology LT36 pipe vac lift, Tier 1, 2012 US EPA Label, Hatz CHZXL 445V42 1 Cylinder 6.4 kW .44 L Diesel Engine Usage: 1,278 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE		S/N: Not Available C/W: Seller Supplied Info: Approximate dimensions 8ft x 20ft. Buyer responsible for load-out and transport. Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
9869	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Mathey Dearman 20 in Pipe Beveling Machine	9874	Quantity of (4) 15 Ft Pipe Cartridges S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	S/N: M68048 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	9874A	Quantity of (4) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9870	THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Mathey Dearman 12 in Beveling Machine S/N: CE106814 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	9875	Quantity of (3) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 All Terrain S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
BE PICKED UP WITH AUCTION (JANUAR' SUBJECT TO 3RD P BUYER RESPONSIBI NOT BE ABLE TO AS THESE; RITCHIE-BF	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9876	Quantity of (2) 10 ft Pipe Cartridges - Fits Ditch Wtich JT30 & JT3020 S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9871	Quantity of Denso Protal 7200 Liquid Epoxy Coating & Brushes S/N: Not Available C/W: Part A & B Coating Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9877 9877A	Quantity of (2) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 Mach I S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX Quantity of (2) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9878	Quantity of (3) Pipe Elevators S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX Pipe Elevator S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9884	Quantity of (8) Foam Pigs S/N: Not Available C/W: (7) 16 in, (1) 18 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9880	·	_	Asset located in: Lahoma, OK
9000	Quantity of (15) 10 in Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9885	Quantity of (2) Pipeline Cleaners Plate Sizing Pigs S/N: H582, P615 C/W: (1) 16 in, (1) 10 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
9881	Quantity of (20) Crates of 8 in Foam Pigs		THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
	S/N: Not Available Usage: Not Available	0006	Quantity of (7) Stringing Cables
9882	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (13) Assorted Pigs	9886	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9883	S/N: Not Available C/W: (8) 8 in Bull nose, (1) 8 in Brush, (1) 8 in Bidirectional, (1) 10 in Bidirectional Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		Quantity of (12) Boxes of Tape & Primer S/N: Not Available C/W: 3M Tape, RD-6 Tape & Primer Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9003	Quantity of 8 In Foam Pigs S/N: Not Available	9888	Quantity of Wax Tape, Primer
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	7000	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot#	Details	Lot #	Details
9889	Quantity of Assorted Night Caps S/N: Not Available C/W: 4 in - 16 in gg Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9894	Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: 4 in, 6 in, 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9890	Quantity of (2) Rock Shield S/N: Not Available C/W: (1) 36 in, (1-60) in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9895	Quantity of Dies - Fits McElroy 618 Poly Pipe Welding Machine S/N: Not Available C/W: 16 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
9891	Quantity of (6) Felt Lined Rock Shield S/N: Not Available		THESE; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK
	C/W: (5) 60 in, (1) 36 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9896	Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: To Fit McElroy 412 Dies, (4) 6 in, (4) 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
9892	Quantity of Dies S/N: Not Available		THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9893	C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (9) 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Balon Valves S/N: Not Available C/W: One Pallet Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9897	Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: To Fit McElroy 412 Dies, 10 in, 12 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9898	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Dies, Poly PipeWelding Machine 6 in, 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9902	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Poly Pipe Welding Machine, 6 in., 8 in. dies Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9899	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, 7-8 in, 4-6 in. Incomplete Sets. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9903	Quantity of McElroy Poly Pipe Welding Machine Parts S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9900	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in, (8)12 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		Quantity of Extension Hydraulic Hoses S/N: Not Available C/W: To Fit McElroy Poly Pipe Welding Machines Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9901	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, (12)10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9905	Quantity of Flange Gaskets S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available C/W: To Fit McElroy 618 Poly Pipe Welding Mchine, (8) 16 in., (8) 12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9907	Heater - Fits S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9912	Bending Shoe S/N: Not Available C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9908	Quantity of Dies S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, (4) 2 in., (4) 3 in., (7) 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9913	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9909	McElroy 848701 Electric Heater S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	-9914	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9910	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 618 Poly Pipe Welding Machine, 12 in., 16 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9915	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9911	Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, 2 in., 3 in., 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	-9916	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
9917	MMI Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9922	Bending Shoe Bucket S/N: Not Available C/W: 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	
9918	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	-9923	Bending Shoe Bucket S/N: 015M C/W: 6 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	
9919	Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8) 6 in, (8) 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9924	Bending Shoe Bucket S/N: Not Available C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Remco Bending Shoe S/N: Not Available	
9920	Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in., (8)12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9926	C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION BE PICKED UP WITHIN 14 DAYS OF TAUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOUT NOT BE ABLE TO ASSIST WITH LOAN THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK 9926 Quantity of (2) Roller Stands S/N: Not Available	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe
9921	Quantity of (2) Bending Shoe S/N: 3040918 C/W: (1) 8 in., (1) 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9927	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9931	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9928	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9932	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9929	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9933	McElroy 1242112 Heater S/N: Not Available C/W: To Fit McElroy Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9930	MMI Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9934	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
9935	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9940	Quantity of McElroy Pitt Bull 14 Hot Plate, Facer S/N: C147848 C/W: 1-4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	
9936	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	7741	Quantity of (5) Calipers S/N: 29897, 52770 C/W: 6 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	
	Asset located in: Lahoma, OK	9942	Quantity of (5) Calipers	
9937	Rigid BF86C Electric Tie In Machine S/N: 086C03820A46 C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9943	S/N: 55693, 1708, 51799, 56642. 77426 C/W: 12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	
9938	Mustang DBG60 Polyethylene Pipe Squeeze Tool S/N: Not Available C/W: To Fit Poly Pipe, 4 in & 6 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9943	C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOC. BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR V SUBJECT TO 3RD PARTY STOR BUYER RESPONSIBLE FOR LOA NOT BE ABLE TO ASSIST WITH THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK 9944 Quantity of (3) Calipers S/N: 84426, 82563, 84437	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (3) Calipers S/N: 84426, 82563, 84437
9939	Quantity of McElroy Pitt Bull 14 Electric Facer S/N: C20800 C/W: Hester not included Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		C/W: 16 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9945	Quantity of (3) Calipers S/N: 53951, 32791 C/W: 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	PRIMORIS-SERVICES-CORP-COMP Usage: Not Available Asset located in: Lake Worth, TX 9954 Quantity of (4) Spy Model 780 Pipe Detectors S/N: Not Available C/W: (2) Spy Model 670 wet spong Fisher TW-6 Pipe and cable locator Usage: Not Available Notes: LOADOUT BY APPOINTMEN ITEM AT OFFSITE LOCATION MUS PICKED UP BY DECEMBER 31ST O SUBJECT TO 3RD PARTY STORAG FORKLIFT ASSISTANCE WILL NOT AVAILABLE; RITCHIE-BROS-ENERG Asset located in: McAlester, OK 9955 Quantity of (6) Assorted Pipeline D S/N: Not Available C/W: (4) Spy Detectors, (2) Vivax N Detectors, misc parts and batteries Usage: Not Available Notes: LOADOUT BY APPOINTMEN ITEM AT OFFSITE LOCATION MUS PICKED UP BY DECEMBER 31ST O SUBJECT TO 3RD PARTY STORAG FORKLIFT ASSISTANCE WILL NOT AVAILABLE; RITCHIE-BROS-ENERGO	S/N: Not Available C/W: (1) 16 ft, (3) 20 ft; EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY, Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Spy Model 780 Pipeline Detectors S/N: Not Available C/W: (2) Spy Model 670 wet sponge detectors,
9946	Quantity of (4) Calipers S/N: Not Available C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE; RITCHIE-BROS-ENERGY Asset located in: McAlester, OK Quantity of (6) Assorted Pipeline Detectors S/N: Not Available
9947	THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (2) Calipers S/N: 57397 C/W: 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE		Detectors, misc parts and batteries
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9956	Quantity of (4) Pipeline Recorders w/plastic tubs S/N: Not Available C/W: 150 degrees x 3000 PSI Usage: Not Available
9948	Pipe Fittings S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE; RITCHIE-BROS-ENERGY Asset located in: McAlester, OK
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	9957	32 ft x 8 ft Mobile Test Unit S/N: DCS489-196 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
9949	Quantity of Pipelayer Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	9958	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-07 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX

Lot #	Details	Lot #	Details
9959	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-09 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	9966	Quantity of (4) Fisher Research Labs Gemini 3 Metal & Mineral Detector S/N: 102201652 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
9960	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-10		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	C/W: To Fit FMC Technologies FM100300 Usage: Not Available		Asset located in: Lahoma, OK
	Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	9967	Quantity of (3) Metrotech 810DX Line Locator S/N: 004314 Usage: Not Available
9961	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-03 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9962	2015 Kaymore FM100300 Pneumatic Grease	9968	Radiodetection Cat4+ Locator
	Hose Reel Skid S/N: 58240-05 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		S/N: 10C4EN144291
			Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9963	Quantity of (8) Reelcraft CA3319L Grease Hose Reel Skid		
	S/N: 230508-004		Asset located in: Lahoma, OK
	Usage: Not Available Notes: RITCHIE-BROS-ENERGY	9969	Quantity of (41) Mats S/N: Not Available
	Asset located in: Midland, TX		Usage: Not Available
9964	Quantity of (14) Spy 780 Jeep Detector S/N: 7804998 C/W: To Fit Spy 780 Jeep Detector, 4", 6", 8", 10", 12", 16" springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES ;	9970	Evans HBM Horizontal Boring Machine
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		S/N: 016 C/W: 2002 US EPA Label, Deutz BF4L913 4 Cylinder 99 hp Diesel Engine
0065	Asset located in: Lahoma, OK	\dashv	Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST
9965	Quantity of (7) Spy 780 Jeep Detector S/N: 7805001 C/W: 4 in, 6 in, 8 in, 10 in, 12 in, 16 in Springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9971	Machine S/N: 1504 C/W: 16 in Boring Auger, Wisconsin VH4D1A 4 Cylinder Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9975A	2022 Reelstrong CLD20 Tri/A (1) Reel Trailer S/N: 1R9BU1636N1626315 C/W: Honda GX390 Gasoline Engine, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Hydraulic Reel Hoist, 215/75R17.5 Tires, 12451 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
		9975B	2022 Reelstrong CLD20 Tri/A (1) Reel Trailer S/N: 1R9BU163XN1626267 C/W: Honda GX390 Gasoline Engine, Lunette Ring Hitch, Torsion Axle, Electric Brakes, 215
9971A	2008 Lufkin Tri/A Lowboy Trailer S/N: 1L01D513181166341 C/W: Air Ride Suspension, 28 ft Main Deck, 102 in Usable Deck Width, Pickup Throat, Tail		/75R17.5 Tires, 12451 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Roller, 255/70R22.5 Tires, 90000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9976	2012 Drake T/A (3) Reel Trailer S/N: 1D9BU1410CP472777 C/W: Spring Suspension, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available
9972	2014 Dynacorp TL1280 Tri/Axle HS Separator Trailer S/N: 2C9T3DFA1E3161480 C/W: 9.9 Mpa/1440psi Usage: Not Available		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	9977	2020 Pro Fabrication S/A Reel Trailer S/N: 1P9BR101XLC495135 C/W: Lunette Ring Hitch, Torsion Axle, Electric
9973	2013 Wyatt's Trailer Sales 24 ft T/A Spooling Trailer S/N: 1W9GU24253L364589 C/W: 24000 lb GVWR, Spring Suspension, Electric Brakes, Deck Over Tires, Kubota Diesel Powered Self Contained Hydraulic System, 235		Brakes, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	/80R16 Tires Usage: Not Available Notes : RITCHIE-BROS-ENERGY Asset located in : El Reno, OK	9977A	2020 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK18N6L1000160 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/75R17.5 Tires, 9950 lb GVWR
9974	1988 Big Tex 18 Ft T/A Gooseneck Chemical Trailer S/N: 16VGB1622J1416669 C/W: Spring Suspension, Electric Brakes, Deck		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Over Tires, 235/85R16 Tires, 19400 lb GVWR, 4 Cylinder Diesel, Triplex Pump, (2) - 500 gallon tanks; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,660 Hr Notes: RITCHIE-BROS-ENERGY; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	9979	2016 John Evans 3TSLR S/A (1) Reel Trailer S/N: 1J9T112A4G0003908 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 6000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9975	Asset located in: Lake Worth, TX 2005 C & S Trailer World Tri/A (3) Reel Trailer S/N: 44Z255LKX5T014462 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	- 9979A	2016 Mobile Tech S/A (1) Reel Trailer S/N: 1M9BR1013GA859016 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9980	2014 Brindle T/A (4) Reel Trailer S/N: 1L9OR2626EG085221 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires, 21000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9987	2011 Heil 9500 gal T/A Tanker Trailer S/N: 5HTDL4529B5H23926 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 73000 lb GVWR, Roper Hydraulic Powered Pump, 73000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX
9981	2012 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK18N3C1000066 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/75R17.5 Tires, 10000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9988A	2011 Stephens T/A Tanker Trailer S/N: 1S9AB15B9BH474104 C/W: 68000 lb GVWR, Air Ride Suspension, 11R22.5 Tires, Steel Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9982	2011 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK16N6B1000015 C/W: Lunette Ring Hitch, 12-16.5 Tires, 7500 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY	 9989	2010 Galyean 130 BBL T/A Tanker Trailer S/N: 1G9VT4020AH017248 C/W: Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Steel Tank, 3 Compartments, CHALLENGER Hydraulic Powered Pump Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX
9982A	Asset located in: Lake Worth, TX 1999 Butler S/A (1) Reel Trailer S/N: 1BUC10105X1001719 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 8000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY	9990 9990A	2005 Polar SRJH 3800 gal T/A Tanker Trailer S/N: 1PMS1452X51028313 C/W: Air Ride Suspension, Air Brakes, Aluminum Wheels, 445/50R22.5 Super Single Tires, 68000 lb GVWR, Insulated Stainless Steel Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Livingston, LA
9984	Asset located in: Lake Worth, TX 1995 Redi-Haul S/A Reel Trailer S/N: 47SZ041T5S1010806 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Hydraulic Reel Hoist, 235/75R17.5 Tires Usage: Not Available		S/N: 5HTDL452X35G14702 C/W: Spring Suspension, 11R24.5 Tires, Stainless Steel Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9986	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2011 Dragon 8400 gal T/A Tanker Trailer S/N: 1UNST4422BS082564 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Whools, 11824 5 Tiron, 70000 lb	9991	2025 X-STAR 990 gal T/A Tanker Trailer S/N: 1X9T7BA22SH039932 C/W: Aluminum Frame, Ball Hitch, 235/80R16 Tires, 14000 lb GVWR, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Aluminum Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 70000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	2025 X-STAR 990 gal T/A Tanker Trailer S/N: 1X9T7BA20SH039931 C/W: Ball Hitch, Spring Suspension, 235/80R16 Tires, 14000 lb GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9993	2025 Industrias America 750 gal Trailer Mounted Fuel Tank S/N: 3EZBTT088SA003625 C/W: 12 V Transfer Pump, DEF Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10000	1973 Trim T/A Tanker Trailer S/N: K40092 C/W: Spring Suspension, Aluminum Wheels, 11R22.5 Tires, Stainless Steel Tank, Catwalk, Gasoline Powered Pump Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
9994	2025 X-STAR 750 gal T/A Tanker Trailer		Asset located in: Lake Worth, TX	
	S/N: 1X9T7B829SH039934 C/W: Ball Hitch, Spring Suspension, 225/75R15 Tires, 10400 lb GVWR, Steel Tank, (1) Reels Electric Powered Pump, 10400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10001	2020 Troxell 5460 gal T/A Vacuum Tanker Trailer S/N: 1T9TA4320L1867597 C/W: Spring Suspension, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Challenger 607 Hydraulic Blower, 50000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
9995	2025 X-STAR 750 gal T/A Tanker Trailer		Asset located in: Humble, TX	
9996	S/N: 1X9T7B827SH039933 C/W: Ball Hitch, 225/75R15 Tires, 10400 lb GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 10400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2024 DNJ 750 T/A Tanker Trailer	10002	2019 Southern 150 bbl T/A Vacuum Tanker Trailer S/N: 4T9V6TA27KJ329225 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 63700 lb GVWR, 63700 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
9990	S/N: 1D9D7B927RH870580	10003	Asset located in: Lake Worth, TX	
9997	C/W: Spring Suspension, Electric Brakes, 225 /75R15 Tires, 12000 lb GVWR, Steel Tank, FILL- RITE Electric Powered Pump, 12000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 1998 Comptank 6250 gal Tri/A FRP Tanker		2018 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA25JG347005 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	
9998	Trailer S/N: 2C9LTA3C3WB075132 C/W: Spring Suspension, Lift 1st- Axles, 11R24. 5 Tires, FRP Tank, Catwalk w/Guardrails Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 1997 Trailmaster 8400 gal T/A Tanker Trailer	10004	10004 2017 Southern 150 gal T/A Vacuum Tanker Trailer S/N: 4S9V6TA26HG347007 C/W: Air Ride Suspension, 11R24.5 Tires, 10000 lb GVWR, Aluminum Tank, 10000 lb GVWR Usage: Not Available	
,,,,	S/N: 190DL4428V3G13006		Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	
	C/W: Aluminum Frame, Spring Suspension, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10005	10005 2016 Southern 150 bbl T/A Vacuum Trailer S/N: 4S9V6TA24GG347036 C/W: Aluminum Frame, Air Ride Susp	2016 Southern 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA24GG347036 C/W: Aluminum Frame, Air Ride Suspension,
9999	99 1995 Polar 4400 gal 4/Axle Tanker Trailer S/N: 1R9212339SL040301 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		11R24.5 Tires, 10000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	
		10006	2016 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA29GG347047 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
10007	2016 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA27GG347032 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2015 Keith Huber 5500 gal T/A Vacuum	10013	2011 Dragon 150 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4225BL068770 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Catwalk w /Guardrails Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX
	Tanker Trailer S/N: 1K9TS5522F1077001 C/W: Spring Suspension, 11R24.5 Tires, 45000 lb GVWR, Steel Tank, Catwalk w/Guardrails, Fruitland Diesel Powered Pump, 45000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; RITCHIE-BROS- ENERGY	10014	2007 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST42277L063710 C/W: Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Steel Tank, Catwalk w/Guardrails Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 1979 Reliable 8400 gal T/A Vacuum Tanker
10009	Asset located in: Humble, TX 2014 Dragon 150 BBL 6300 gal T/A Vacuum Tanker Trailer S/N: 1UNST4224ES128600 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Challenger 607SV Blower	10013	Trailer S/N: 2316 C/W: Air Ride Suspension, 295/75R22.5 Tires, 60000 lb GVWR, Aluminum Tank, 60000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	10016	2008 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGFT473888506205 C/W: 2 Hatches, Access Stairs, Spring Suspension, Air Brakes
10010	2013 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4223DL130024 C/W: Spring Suspension, 11R24.5 Tires, Steel		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10017	1999 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGSB471XXS249824 C/W: Manifold, 1 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available
10011	2012 Troxell 140 BBL 5880 gal T/A Vacuum Tanker Trailer S/N: 1T9TA4320C1867101 C/W: Spring Suspension, 11R24.5 Tires, 50000		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; RITCHIE-BROS- ENERGY Asset located in: Lake Worth, TX
	lb GVWR, Steel Tank, Catwalk w/Guardrails, 50000 lb GVWR, 45 ft Pup Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10018	VE Enterprises 435 bbl Flat Top S/A Frac Tank S/N: FTI1298115FT C/W: 3 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available
10012	2011 Troxell 140 BBL 5880 gal T/A Vacuum Tanker Trailer S/N: 1T9TA432XB1867783 C/W: Spring Suspension, Aluminum Outer		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; RITCHIE-BROS- ENERGY Asset located in: Lake Worth, TX
	Wheels, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Catwalk w/Guardrails, 50000 lb GVWR, 45 ft Pup Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10019	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR27KP104096 C/W: Air Ride Suspension, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
10020	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR29KP104097 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, Aluminum Tank, 68000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10028	8 2015 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3228FN374020 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY
10022	2001 Heil 1000 cft T/A Pneumatic Bulk Trailer S/N: 5JLSN422415T05772 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 295/75R22.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10029	Asset located in: Midland, TX 2015 Intech 32 ft x 102 ft Portable T/A Lab Trailer S/N: 1Z9GG3228FN374017 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235 /80R16 Tires, 14400 lb GVWR Usage: Not Available
10023	1998 LBT 1000 cft T/A Pneumatic Bulk Trailer S/N: 4J8B04229WT00303 C/W: Spring Suspension, 11R22.5 Tires, 68000 lb GVWR, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10030	Notes: RITCHIE-BROS-ENERGY Asset located in: Oklahoma City, OK 2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG322XFN374018 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
10024	1996 Heil 1040 cft T/A Pneumatic Bulk Trailer S/N: 5HTSN4223T9T07318 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY	10001	
10025	Asset located in: Lake Worth, TX 1994 Heil 1600 cft T/A Pneumatic Bulk Trailer S/N: 1HLS5N8B8R9W07014 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Aluminum Tank, 4 Compartments, 70000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10031	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3226FN374016 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
10026	1994 Polar 1000 cft T/A Pneumatic Bulk Trailer S/N: 1PMB14225R2013531 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 11R24.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10032	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3221FN374019 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY
10027	1984 Fruehauf 1000 cft T/A Pneumatic Bulk Trailer S/N: 1H4B04121EK004312 C/W: Aluminum Frame, Spring Suspension, Aluminum Wheels, 285/75R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10033	Asset located in: Midland, TX 2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3222FN374014 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX

Lot #	Details	Lot #	Details
10034	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG322XFN374021 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available	10040	2007 William Scotsman 52 ft x 11 ft 11 in Portable Tri/A Crew House S/N: 24348 C/W: To Fit SPACE MASTERS 40440 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	11013A 	2011 Overland 5460 gal T/A Vacuum Tanker Trailer
10035	5 2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3224FN374015 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle,		S/N: 1Z9241528B1258322 C/W: Spring Suspension, 11R24.5 Tires, 64500 lb GVWR, Steel Tank, Catwalk, Fruitland Hydraulic Blower, 64500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	95070	2015 Cat 16T 36 BU Excavator Bucket S/N: 316-36-MHJ06857 Usage: Not Available Asset located in: Lake Worth, TX
10036	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG2820EN374917 C/W: (1) Offices, Air Conditioner, Aluminum	95073	smooth Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	/Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	95081	2018 Arrow 4' Block Forks Telehandler S/N: L19846 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
10037	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG2827EN374915 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle,	95146	2025 MaxxD D7X7212 End Dump Trailer S/N: 117643 Usage: Not Available Asset located in: Lake Worth, TX
	Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	95147	2025 MaxxD DTX8314 End Dump Trailer S/N: 118238 Usage: Not Available Asset located in: Lake Worth, TX
10038	2014 Intech 28 ft x 102 ft Portable T/A Lab Trailer S/N: 1Z9GG2822EN374918 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235	95160	Pressure Testing Unit On 1995 Talbert Lowboy Trailer S/N: 40FWK5239S1012196 Usage: Not Available Asset located in: Midland, TX
	/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Oklahoma City, OK	95290	2007 K-Z Montego Bay 36 ft T/A Travel Trailer S/N: 4EZFM372X7S052451 C/W: Sleeps 2 People, Dish Washer, 15400 lb GVWR, 4 Slide Outs, Power Awning, 5th Wheel,
10039	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG2829EN374916 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX