

Fort Worth, TX, USA - Dec 10, 2024

Lot #	Details	Lot #	Details
	2018 Case 621G Wheel Loader S/N: JEEN0621HJF243666 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 102 in Bucket, 20.5x25 Tires Usage: 5,236 Hr	5	2015 John Deere 210L EP Landscape Loader S/N: 1T8210ELEFJ892655 C/W: Open Operator Station, Multi-Purpose Bucket, Box Blade, with Rippers Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6	2006 Case 570 MXT 4x4 Landscape Loader
	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR21SG000302 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available		S/N: JJG0380343 C/W: Enclosed Cab, 83 in Bucket, 83 in Hydraulic Tilting Box Blade Usage: 2,554 Hr Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	7	2022 Cat 420 IT 4x4 Backhoe Loader
1	2017 Case 570 N EP 4x4 Landscape Loader S/N: JJGN570NEHC739167 C/W: Open Operator Station, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Weight Box Usage: 4,852 Hr Asset located in: Lake Worth, TX	8	S/N: CAT00420TH8T02368 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Forks, Quick Coupler, 24 in Backhoe Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION
2	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380199 C/W: Open Operator Station, 2006 US EPA Label, 84 in Bucket, 84 in Hydraulic Tilting Box		Usage: 66 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS Asset located in: Lake Worth, TX
	Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 7,966 Hr Asset located in : Lake Worth, TX		2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420CH8T00232 C/W: Open Operator Station, Backhoe Pilot
CHOIC	E OF 2 - Lot #'s: 3, 4		Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 12 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,244 Hr
3	2006 Case 570MXT 4x2 Landscape Loader		Asset located in: Lake Worth, TX
	S/N: JJG0380435 C/W: Open Operator Station, 2006 US EPA Label, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 2,597 Hr Asset located in: Lake Worth, TX	9	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420AH8T00225 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 96 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket
4	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380358 C/W: Open Operator Station, 2006 US EPA Label, 82 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 4,932 Hr Asset located in: Lake Worth, TX		Usage: 4,803 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
CHOICE OF 4 - Lot #'s: 10, 11, 8, 9		15	2016 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FKHWD00461 C/W: Open Operator Station, 2015 US EPA	
10	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420AH8T00287 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, Tier 4, 2020 US EPA		Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 96 in Loader Bucket, 25 in Backhoe Digging Bucket Usage: 5,256 Hr Asset located in: Lake Worth, TX	
	Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 5,611 Hr Asset located in : Lake Worth, TX	16	S/N: CAT0420FCHWD01301 C/W: Open Operator Station, Backhoe Pil Controls, Requires Diesel Exhaust Fluid,	S/N: CAT0420FCHWD01301 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid,
11	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420JH8T00303 C/W: Open Operator Station, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires	17	Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket Usage: 4,376 Hr Asset located in: Lake Worth, TX	
	Diesel Exhaust Fluid, 95 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket Usage: 5,904 Hr Asset located in : Lake Worth, TX		2016 Cat 420 F2 4x4 Backhoe Loader S/N: CAT0420FEHWC01679 C/W: Enclosed Cab, Air Conditioner, Air Ride	
12	2017 Cat 420F2 4x4 Backhoe Loader S/N: CAT0420FJHWC02726 C/W: Open Operator Station, Backhoe Pilot Controls, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 15 in Backhoe Cleanup Bucket, EQUIPMENT-FROM-		Seat, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, 86 in Multi-Purpose Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, (2) Rear Auxiliary Hydraulics Usage: 2,720 Hr Asset located in: Lake Worth, TX	
	A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,487 Hr Asset located in : Lake Worth, TX	18 2015 Cat 420F2 IT 4x4 Backhoe Loader S/N: CAT0420FAHWD00353	S/N: CAT0420FAHWD00353	
CHOICE OF 2 - Lot #'s: 13, 14 2017 Cat 420F2IT 4x4 Backhoe Loader			C/W: Open Operator Station, Backhoe Pilot Controls, Control Pattern Changer, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 94 in Loader Bucket, Forks, 23 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,443 Hr	
	S/N: CAT0420FAHWD01616 C/W: Open Operator Station, 2016 US EPA		Asset located in: Humble, TX	
	Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92.5 in Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	19	2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FVHWD00240 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket Usage: 5,953 Hr	
14	2017 Cat 420F2 IT 4x4 Backhoe Loader S/N: CAT0420FHHWD01618		Asset located in: Humble, TX	
	C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92 in	сноіс	E OF 2 - Lot #'s: 20, 21	
Loa EQU Usa Not THI	Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	20	2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FCHWD00205 C/W: Open Operator Station, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 5,886 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
21	2014 Cat 420FIT 4x4 Backhoe Loader S/N: CAT0420FKJWJ02630 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 5,652 Hr Asset located in: Lake Worth, TX	30	2017 Cat 415F2 4x4 Backhoe Loader S/N: CAT0415FCHWA00473 C/W: Open Operator Station, 88 in Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,258 Hr Asset located in: Lake Worth, TX
22	2015 Cat 420F 4x4 Backhoe Loader S/N: CAT0420FVSKR04978 Usage: Not Available Asset located in: Lake Worth, TX	-31 -	2016 John Deere 410L 4x4 Backhoe Loader S/N: 1T0410LXPGF298786 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid, 94 in Loader Bucket, 25 in Backhoe Digging Bucket Usage: 7,966 Hr
24	2012 Cat 420E 4x4 Backhoe Loader S/N: CAT0420EHDJL03428 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, 86 in Loader Bucket, 24 in Backhoe Digging Bucket, Manual Thumb Usage: 4,236 Hr Asset located in: Lake Worth, TX	32	Asset located in: Lake Worth, TX 2012 John Deere 410K 4x4 Backhoe Loader S/N: 1T0410KXKCE223394 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Control Pattern Changer, Auxiliary Hydraulics, Hydraulic Coupler, 94 in
25	2011 Cat 420E IT 4x4 Backhoe Loader S/N: CAT0420EPDAN01657 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 90 in Multi-Purpose Loader Bucket, 30		Loader Bucket, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Asset located in: Midland, TX 2018 John Deere 310L EP 4x2 Backhoe Loader
	in Backhoe Digging Bucket, Thumb Bracket Usage: 6,276 Hr Asset located in : Lake Worth, TX		S/N: 1T0310ELEJG337511 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket
26	2020 Cat 416F2 4x4 Backhoe Loader S/N: CAT0416FTHWB02400 C/W: Open Operator Station, Air Ride Seat,		Usage: 3,151 Hr Asset located in: Lake Worth, TX
	Requires Diesel Exhaust Fluid, 89 in Loader Bucket, 20 in Backhoe Cleanup Bucket Usage: 2,510 Hr Asset located in: Lake Worth, TX	34	2018 John Deere 310L EP 4x2 Backhoe Loader S/N: 1T0310ELCJG334570 C/W: Open Operator Station, 2018 US EPA Label, 84 in Loader Bucket, 23 in Backhoe Digging Bucket
27	2017 Cat 416F2 4x4 Backhoe Loader S/N: CAT0416FTHWB01148		Usage: 3,480 Hr Asset located in: Lake Worth, TX
	C/W: Open Operator Station, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 88 in Loader Bucket, 10 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY	СНОІС	E OF 2 - Lot #'s: 35, 36
	Usage: Not Available Asset located in: Lake Worth, TX	35	2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKKEE263557 C/W: Open Operator Station, 86 in Loader
28	2022 Cat 415 4x4 Backhoe Loader S/N: CAT00415HH8A00347 C/W: Open Operator Station, Air Ride Seat,		Bucket, 24 in Backhoe Digging Bucket Usage: 4,207 Hr Asset located in: Lake Worth, TX
	2022 US EPA Label, 89 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 41 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS	36	2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKAEE263368 C/W: Open Operator Station, 90 in Loader Bucket, 16 in Backhoe Digging Bucket Usage: 2,948 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
29	2018 Cat 415F2 IL Backhoe Loader S/N: 0PF400836 Usage: 2,538 Hr Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
37	2012 John Deere 310SJ 4x4 Backhoe Loader S/N: 1T0310SJABD210971 C/W: Enclosed Cab, Air Conditioner, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 92 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,804 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	45	S/N: CAT0420DJFDP23675 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 89 in Loader Bucket 26 in Backhoe Digging Bucket Usage: 5,495 Hr Asset located in: Lake Worth, TX 45 2008 John Deere 310SJ 4x4 Backhoe Loade S/N: T0310SJ156742 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Patter Changer, Powershift Transmission, Tier 2,	S/N: CAT0420DJFDP23675 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 89 in Loader Bucket, 26 in Backhoe Digging Bucket Usage: 5,495 Hr Asset located in: Lake Worth, TX 2008 John Deere 310SJ 4x4 Backhoe Loader S/N: T0310SJ156742 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern
38	Asset located in: McAlester, OK 2016 Case 580N 4x4 Backhoe Loader S/N: JJGN580NJFC717602 C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,827 Hr Asset located in: Lake Worth, TX		Extendable Stick, 36 in Backhoe Digging Bucket Usage: 4,508 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	
39	2014 Case 580 Super N 4x4 Backhoe Loader S/N: JJGN58SNAEC705935 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 2014 US EPA Label, 82 in Loader Bucket, Extendable Stick, 23 in	46	2005 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX945350 C/W: Enclosed Cab, Air Conditioner, 86 in Loader Bucket, 18 in Backhoe Digging Bucket Usage: 7,887 Hr Asset located in: Lake Worth, TX	
	Backhoe Digging Bucket Usage: 3,941 Hr Asset located in : Lake Worth, TX		2001 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX895009 C/W: Open Operator Station, 2000 US EPA	
40	2013 Case 580N 4x4 Backhoe Loader S/N: JJGN580NLDC581006 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 82 in Loader Bucket,		Label, 84 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 7,556 Hr Asset located in : Lake Worth, TX	
	24 in Backhoe Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,697 Hr Asset located in: Lake Worth, TX	48	2008 Case 580 Super M Series 3 4x4 Backhoe Loader S/N: N8C504007 C/W: Enclosed Cab, 82 in Loader Bucket,	
41	2018 JCB 3CX 4x4 Backhoe Loader S/N: JCB3CXTTCJ2667099 C/W: Open Operator Station, 2018 US EPA Label, 86 in Loader Bucket, Quick Coupler, 24		Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 9,616 Hr Asset located in : Lake Worth, TX	
	in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 1,433 Hr Asset located in : Humble, TX		S/N: JJG0312663 C/W: Open Operator Station, 83 in Loader	S/N: JJG0312663 C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket,
42	2012 New Holland B95C 4x4 Backhoe Loader S/N: FNH0B95CNCHH02653 C/W: Open Operator Station, 88 in Loader		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,258 Hr Asset located in: Lake Worth, TX	
	Bucket, 24 in Backhoe Digging Bucket Usage: 2,544 Hr Asset located in : Lake Worth, TX	49A	2018 Case 580SN 4x2 Backhoe Loader S/N: JJGN58SNPJC75003 C/W: Open Operator Station, 81 in, Quick	
43	2005 Cat 430D 4x4 Backhoe Loader S/N: CAT0430DKBML05163 C/W: Enclosed Cab, Air Conditioner, Backhoe		Coupler Usage: 2,055 Hr Asset located in: Lake Worth, TX	
	Pilot Controls, Hydraulic Coupler, 92 in Loader Bucket, 24 in Backhoe Cleanup Bucket Usage: 7,018 Hr Asset located in : Lake Worth, TX	49B	2018 Case 580SN 4x2 Backhoe Loader S/N: JGN58SNCJC753046 C/W: Open Operator Station, Backhoe Pilot Controls, 81 in Loader Bucket, Quick Coupler, 30 in Backhoe Digging Bucket Usage: 3,537 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
50	2006 Cat 416E 4x2 Backhoe Loader S/N: CAT0416EVSHA00900 C/W: Open Operator Station, Air Ride Seat, 89 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 12,955 Hr Asset located in: Lake Worth, TX	59	2022 Komatsu WA475-10 Wheel Loader S/N: KMTWA142VNNA40104 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4.4 m3 124 in Bucket, Auto Lube, 26.5-25 Tires Usage: 7,012 Hr
51	2008 John Deere 310J Backhoe Loader S/N: T0310JX159493 C/W: Open Operator Station, Manual Coupler, 84 in Loader Bucket Usage: 2,804 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 61, 9606A
53	2005 Case 590 Super M 4x2 Backhoe Loader S/N: N5C394910 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 93 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 4,876 Hr Asset located in: Lake Worth, TX	- 61	2017 Cat 966M Wheel Loader S/N: CAT0966MPKJP02589 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 26.5-25 Tires, Auxiliary Hydraulics, Pipe Grapple Usage: 4,818 Hr Asset located in: Bridgeport, NJ
54	2004 Case 580M 4x2 Backhoe Loader S/N: N4C303573 C/W: Open Operator Station, 2004 US EPA Label, 83 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,191 Hr	62	2021 Cat 950GC Wheel Loader S/N: CAT00950TM5T04416 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 23.5-25 Tires, 4.5 cyd 114 in Bucket Usage: 1,455 Hr Asset located in: Baton Rouge, LA
	Asset located in: Lake Worth, TX	63	2020 Cat 950GC Wheel Loader
55	2016 Kubota L47TLB 4x4 Backhoe Loader S/N: 50136 C/W: Open Operator Station, Manual Coupler, 71 in Loader Bucket, 11 in Backhoe Digging Bucket Usage: 671 Hr Asset located in: Lake Worth, TX		S/N: CAT00950AM5T03307 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 3.30 m3 116 in Bucket, 23.5-25 Tires Usage: 4,902 Hr Asset located in: Lake Worth, TX
56	2019 John Deere 844K-III Wheel Loader S/N: 1DW844KACJF692631 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick Steering, Loadrite On-Board Scale, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9.3 cyd 144 in Bucket, Auto Lube, 875/65R29 Tires Usage: 9,476 Hr Asset located in: Lake Worth, TX	- 64	2019 Cat 950 M Wheel Loader S/N: CAT0950MVJ1S02214 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 116 in Bucket, Auto Lube, 23.5R25 Tires Usage: 9,296 Hr Asset located in: Lake Worth, TX
57	2015 Cat 980M High Lift Wheel Loader	СНОІСІ	E OF 2 - Lot #'s: 65, 66
	S/N: LKRS00731 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Joystick Steering, loadrite On-Board Scale, Manual Coupler, 7.5 cyd 135 in Bucket, 29.5R25 Tires Usage: 20,599 Hr Asset located in: Lake Worth, TX	65 2017 Cat 950MZ Wheel Loader S/N: CAT0950MCHE810302 C/W: Enclosed Cab, Air Conditioner Camera, Air Ride Seat, 2017 US EPA	S/N: CAT0950MCHE810302 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 3.40 m3 117 in
58	2018 Case 1121G Wheel Loader S/N: JEEN1121KJF246039 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Joystick Steering, 6.1 cyd 126 in Bucket, 26.5R25 Tires Usage: 6,569 Hr Asset located in: Lake Worth, TX		Bucket, 23.5R25 Tires Usage: 6,932 Hr

Lot #	Details	Lot #	Details	
66	2016 Cat 950M Wheel Loader S/N: CAT0950MKEMB02486 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 114 in Bucket, 23.5 R25 Tires, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,168 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	СНОІС	E OF 2 - Lot #'s: 73, 74	
		73	2014 John Deere 644 K Wheel Loader S/N: 1DW644KZLED661608 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2014 US EPA Label, Forks, 23.5R25 Tires Usage: 15,623 Hr Asset located in: Lake Worth, TX	
	Asset located in: Humble, TX	74	2013 John Deere 644 K Wheel Loader	
67	2014 Cat 950 K Wheel Loader S/N: CAT0950KTR4A02440 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Traction Control, 2017 US EPA Label, 118 in Bucket, 23.5-25 Tires Usage: 20,054 Hr		S/N: 1DW644KZKCE650141 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, 102 in Bucket, 23.5 R25 Tires Usage: 16,918 Hr Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	75	2021 LiuGong CLG848H Wheel Loader	
68	2011 Cat 950 H High Lift Wheel Loader S/N: CAT0950HEJAD00705 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 114 in Bucket, 23.5 R25 Tires Usage: 23,037 Hr Asset located in: Lake Worth, TX		S/N: CLG848HZJML691727 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 3 cyd 115 in Bucket, Forks, 20.5R25 Tires Usage: 2,486 Hr Asset located in: Lake Worth, TX	
69		76	76 2019 Volvo L90H Wheel Loader S/N: VCEOL90HL0S624993 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary	
	S/N: KMYWA118L36A64146 Usage: Not Available Asset located in : Lake Worth, TX			
70	2018 Volvo L110H Wheel Loader S/N: VCEL110HT0S631498 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift,		Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 6,927 Hr Asset located in: Lake Worth, TX	
	2018 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 118 in Bucket, Forks, 23.5R25 Tires Usage: 6,898 Hr Asset located in : Lake Worth, TX	77	S/N: VCE0L90GT0S617667 C/W: Enclosed Cab, Air Conditioner, Rear Camera, 2014 US EPA Label, Auxiliary	S/N: VCE0L90GT0S617667 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2014 US EPA Label, Auxiliary
70A	2011 Volvo L110F Wheel Loader (Inoperable) S/N: VCEL110FP00005039 Usage: Not Available		Hydraulics, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires Usage: 12,859 Hr Asset located in : Lake Worth, TX	
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	78	2016 Cat 938M Wheel Loader S/N: CAT0938MTJ3R02448 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid,	
	Asset located in: Lake Worth, TX	_	Auxiliary Hydraulics, Hydraulic Coupler, 106 in	
71	2023 John Deere 644P Wheel Loader S/N: 1DW644PAVPLZ17531 C/W: Enclosed Cab, Air Conditioner, Rear View		Bucket, 20.5R25 Tires Usage: 19,902 Hr Asset located in: Lake Worth, TX	
	Camera, Air Ride Seat, Ride Control, Autoshift, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 23.5R25 Tires, Hydraulic Coupler, 4 cyd 120 in Bucket Usage: 3,296 Hr Asset located in: St. Rose, LA	79	2014 Cat 938K Wheel Loader S/N: CAT0938KPSWL02223 C/W: Enclosed Cab, Rear View Camera, 2013 US EPA Label, 20.5R25 Tires Usage: 21,033 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
CHOIC	E OF 1 - Lot #'s: 81	90	2012 Cat 930K Wheel Loader S/N: CAT0930KHRHN00708 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 110 in Bucket, Forks,
81	2020 Hyundai HL955 Wheel Loader S/N: HHKHW500AL0000844 C/W: Enclosed Cab, Air Conditioner, Rear View		20.5R25 Tires Usage: 12,980 Hr
			Asset located in: Lake Worth, TX
	Camera, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 20.5 R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 4,328 Hr Notes: . Asset located in: Lake Worth, TX	Hydraulics, Hydraulic Coupler, 101 in Bu Forks, 20.5R25 Tires, EQUIPMENT-FROM PRIMORIS-SERVICES-CORP-COMPANY	S/N: CAT0930HEDHC03679 C/W: Enclosed Cab, Air Ride Seat, Auxiliary Hydraulics, Hydraulic Coupler, 101 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT-FROM-A-
82	2023 John Deere 544P Wheel Loader		Asset located in: Lake Worth, TX
	S/N: 1DW544PALPLX19742 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Autoshift, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 20.5R25 Tires, Auxiliary Hydraulics, Hydraulic Coupler, 3.5 cyd 106 in Bucket Usage: 1,546 Hr	92	2012 Volvo L70G Wheel Loader S/N: VCE0L70GC00002431 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires Usage: 33,042 Hr Asset located in: Lake Worth, TX
	Asset located in: Greenville, TX		
85	2007 John Deere 544J Wheel Loader S/N: DW544JZ610127 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, Traction Control, 2006 US EPA Label, CARB Compliant, 3.0 cyd 103 in Bucket, 20.5R25 Tires Usage: 7,496 Hr	93	2017 Komatsu WA320-8 Wheel Loader S/N: KMTWA135JHA085240 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 108 in Bucket, 20.5R25 Tires Usage: 15,207 Hr Asset located in: Lake Worth, TX
	Asset located in: Midland, TX		
87	2020 Hitachi ZW180-6 Wheel Loader S/N: RYUPD860CH8405515 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 104 in Bucket, 23.5R25 Tires Usage: 12,123 Hr Asset located in: Lake Worth, TX	95	2014 Komatsu WA270-7 Wheel Loader S/N: KMTWA122C01080092 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, 2013 US EPA Label, Hydraulic Coupler, 104 in Bucket, 60 in Forks, 20.5R25 Tires Usage: 8,531 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 88, 89		
88	2015 Cat 930M Wheel Loader S/N: CAT0930MKKTG00791 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 11,259 Hr Asset located in: Lake Worth, TX	96	2013 Komatsu WA270-7 Wheel Loader S/N: KMTWA122C01080021 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Hydraulic Coupler, 104 in Bucket, 60 in Forks, Auto Lube, 20.5R25 Tires Usage: 11,558 Hr Asset located in: Lake Worth, TX
89	2014 Cat 930K Wheel Loader		E OF 2 - Lot #'s: 97, 98
	S/N: CAT0930KTRHN03712 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 101 in Bucket, Forks, 20.5 R25 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 10,745 Hr Asset located in: Livingston, LA	97	2014 Cat 924K Wheel Loader S/N: CAT0924KJPWR03464 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
98	2013 Cat 924K Wheel Loader S/N: CAT0924KLPWR01641 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2012 US EPA Label, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires Usage: 8,775 Hr Asset located in: Lake Worth, TX	106	2023 Cat 906 Wheel Loader (Unused) S/N: CAT00906CHZ601041 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2023 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 74 in Bucket, Forks, 405/70R18 Tires, 25 MPH Machine Usage: 3 Hr Asset located in: Lake Worth, TX
99	2012 Volvo L60G Wheel Loader S/N: VCE0L60GH00001263 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 11,335 Hr Asset located in: Lake Worth, TX	107	2017 Cat 906M Wheel Loader S/N: CAT0906MKH6602101 C/W: Open Operator Station, 2011 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.6 cyd 82 in Bucket, 340/80R18 Tires Usage: 3,249 Hr Asset located in: Midland, TX
100	2014 Cat IT14G2 Wheel Loader S/N: CATIT14GLERP00499 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.40 m3 94 in Bucket, Forks, 17.5-25 Tires Usage: 2,976 Hr	108	2006 Volvo L110E Wheel Loader S/N: L110EV61151 C/W: Enclosed Cab, 2006 US EPA Label, Hydraulic Coupler, 112 in Bucket, 23.5R25 Tires Usage: 9,676 Hr Asset located in: Lake Worth, TX
101	Asset located in: Lake Worth, TX 2022 Bobcat L85 Wheel Loader S/N: B53C11128 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 405/70R18 Tires Usage: 1,595 Hr	109	2005 Cat 924G Wheel Loader S/N: CAT0924GJDDA02066 C/W: Enclosed Cab, Air Conditioner, Autoshift, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: 14,142 Hr Asset located in: Lake Worth, TX
102	Asset located in: Lake Worth, TX 2023 Cat 910 Wheel Loader (Unused) S/N: CAT00910KJW201852 Usage: 5 Hr Asset located in: Lake Worth, TX	110	1990 Cat 980C Wheel Loader S/N: 63X09341 C/W: Enclosed Cab, Air Conditioner, 29.5R25 Tires Usage: Not Available Asset located in: Lake Worth, TX
103	2018 Cat 908M Wheel Loader S/N: CAT0908MEH8803041 C/W: Enclosed Cab, Air Conditioner, 78 in Grapple Bucket, Solid Tires Usage: 10,102 Mi	111	2000 Cat 966G Wheel Loader S/N: 3SW00657 Usage: 23,326 Hr Asset located in: Lake Worth, TX
104	Asset located in: Lake Worth, TX 2022 Cat 907M Wheel Loader S/N: CAT0907MKK5700489 Usage: 600 Hr Asset located in: Lake Worth, TX		2000 Cat 938G Wheel Loader S/N: 4YS01303 C/W: Enclosed Cab, Air Conditioner, 2000 US EPA Label, 110 in Bucket, Forks, 20.5R25 Tires Usage: 12,027 Hr Asset located in: Lake Worth, TX
CHOICE OF 2 - Lot #'s: 105, 106 105		113	1985 Cat 966D Wheel Loader S/N: 99Y04055 C/W: Enclosed Cab, Manual Coupler, Forks, 26.5-25 Tires Usage: 5,678 Hr Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2023 US EPA Label, Hydraulic Coupler, 70 in Forks, 405/70R18 Tires, 25 MPH Machine Usage: 27 Hr Asset located in: Lake Worth, TX	114	1989 Cat 950 E Wheel Loader S/N: 22Z04456 C/W: Open Operator Station, Hydraulic Coupler, 110 in Bucket, Forks, 23.5-25 Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,198 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
114A	1998 Cat IT28G High Lift Wheel Loader S/N: 8CR01014 C/W: Enclosed Cab, Air Conditioner, Ride Control, Auxiliary Hydraulics, 100 in, 20.5-25 Tires Usage: 18,294 Hr Asset located in: Lake Worth, TX	123	2011 John Deere 872GP AWD Motor Grader S/N: 1DW872GPCBE636116 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 2011 US EPA Label, 16 ft / 4.88 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 7,669 Hr
115	1998 Case 621B Wheel Loader S/N: JEE0055157 C/W: Enclosed Cab, Air Conditioner, 1997 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE
117	2016 Cat 14M Motor Grader S/N: R9J01751 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX		RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX
118	2015 Cat 14M Motor Grader S/N: R9J01362 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	124	2019 Cat 140M3 Motor Grader S/N: CAT0140MKN9D01607 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block,
119	2012 Cat 14M Motor Grader S/N: R9J00660 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available		Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 6,884 Hr Asset located in: Lake Worth, TX 2017 Cat 140M3 Motor Grader
120	Asset located in: Humble, TX 2011 Cat 14M Motor Grader S/N: R9J00286 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX		S/N: CAT0140MJN9D00717 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires
121	2009 Cat 14M Motor Grader S/N: B9J00952 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	126	Usage: 10,845 Hr Asset located in: Lake Worth, TX 2016 Cat 140M3 Motor Grader S/N: CAT0140MHN9M00322 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Requires Diesel
122	2008 Cat 14M Motor Grader S/N: B9J00654 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available		Exhaust Fluid, 14 ft / 4.27 m Moldboard, Ripper, 17.5R25 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 9,287 Hr Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	127	2015 Cat 140M3 Motor Grader S/N: CAT0140MLN9D00447 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires Usage: 5,571 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
128	2015 Cat 140M3 Motor Grader S/N: CAT0140MQN9D00463 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Pre- Wired for Grade Control, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper /Scarifier, Rear Auxiliary Hydraulics, 17.5R25 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	134	2019 John Deere 672G Motor Grader S/N: 1DW672GXCKF693988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Differential Lock, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 5,387 Hr Asset located in: Lake Worth, TX
	Usage: 11,666 Hr Asset located in: Lake Worth, TX	135	2015 John Deere 672G AWD Motor Grader S/N: 1DW672GXHEF665845 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Differential Lock, 14 ft /
CHOIC 129	E OF 2 - Lot #'s: 129, 130		4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 6,673 Hr
	2013 Cat 140M2 Motor Grader S/N: M9J00716 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	136	Asset located in: Lake Worth, TX 2013 John Deere 672GP AWD Motor Grader S/N: 1DW672GPHDE651559 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Accumulators Combination Ripper/Scarifier, 17.5R25 Tires
130	2012 Cat 140M2 Motor Grader S/N: M9J00680 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-	137	Usage: 7,517 Hr Asset located in: Lake Worth, TX
131	INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX 2012 Cat 140M2 VHP Plus Motor Grader		2012 John Deere 672G AWD Motor Grader S/N: 1DW672GPKCE643998 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires
131	S/N: CAT0140MAM9D01207 C/W: Enclosed Cab, Air Conditioner, Low		Usage: 12,634 Hr Asset located in: Lake Worth, TX
	Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2012 US EPA Label, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 8,784 Hr Asset located in: Lake Worth, TX	138	2007 Cat 140H Motor Grader S/N: CCA03626 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
132	2011 Cat 140M2 VHP Plus Motor Grader S/N: M9D00692 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 14.00-24 Tires,	139	2012 Case 865B Motor Grader S/N: HBZN0865TCAF01360 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 2,653 Hr Asset located in: Lake Worth, TX
	Topcon GX-60 Display, Topcon 3D MC-R3 Radio Receiver, Topcon MC2 Sensors with Masts Usage: 9,083 Hr Asset located in : Lake Worth, TX	140	2013 LeeBoy 785 Motor Grader S/N: 413760-141 C/W: Enclosed Cab, Front Scarifier, 15.5-25 Tires
133	2015 John Deere 772GP AWD Motor Grader S/N: 1DW772GPLFF667809		Usage: 3,051 Hr Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 6,172 Hr Asset located in: Lake Worth, TX	141	1993 Cat 12G Motor Grader S/N: 61M15367 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
142	1991 Cat 120G Motor Grader S/N: 87V09411 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, 14.00-24 Tires Usage: Not Available Asset located in: Lake Worth, TX	149	2017 Bell B50E Articulated Dump Truck S/N: B93A650EA01105727 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Steel Body Liner, 875 /65R29 Tires Usage: 9,289 Hr
142A	1991 Champion 740A Motor Grader S/N: 21849		Asset located in: Lake Worth, TX
	4.27 m Moldboard, Front Auxiliary Hydraulics, 14.00R24 Tires	150	E OF 3 - Lot #'s: 150, 151, 152 2022 Komatsu HM400-5 Articulated Dump
	Asset located in: Lake Worth, TX		Truck
143	2022 John Deere 460E-II Articulated Dump Truck S/N: 1DW460EBJNF713715 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Tailgate, 29.5R25 Tires		S/N: KMTHM016JMD012108 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 4,566 Hr Asset located in: Lake Worth, TX
	Usage: 4,497 Hr Asset located in : Lake Worth, TX	151	2021 Komatsu HM400-5 Articulated Dump
CHOIC	E OF 2 - Lot #'s: 144, 145 2020 Cat 745 Articulated Dump Truck	Truck S/N: C/W: Came Exha	Truck S/N: KMTHM016HMD011998 C/W: Air Conditioner, Engine Brake, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 4,217 Hr
	S/N: CAT00745P3T602347 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 5,300 Hr		Asset located in: Lake Worth, TX
		152	2021 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016LMD011997 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 4,708 Hr
	Asset located in: Humble, TX		
145	2018 Cat 745 Articulated Dump Truck S/N: CAT00745V3T600426 C/W: Air Conditioner, Retarder, Rear View		
	Camera, Air Ride Seat, 2017 US EPA Label, Tailgate, Steel Body Liner, Auto Lube, 29.5R25	152A	Asset located in: Lake Worth, TX 2022 Komatsu HM400-5 Articulated Dump
	Tires Usage: 6,080 Hr		Truck
	Asset located in: Humble, TX		S/N: KMTHM016KMD012141 Usage: Not Available
			Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 146, 147, 148	153	2017 Bell B40E Articulated Dump Truck
146	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CVTFK00176 C/W: Air Conditioner, Retarder, Engine Brake, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner, 29.5R25 Tires	S/N: B93A640EJ01105751 C/W: Air Conditioner, Rear View Camera	C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 29.5R25 Tires Usage: 7,600 Hr
	Usage: 14,026 Hr Asset located in: Lake Worth, TX	0	
147	·	Чсноіс	E OF 2 - Lot #'s: 154, 155
14/	2015 Cat 745C Articulated Dump Truck S/N: TFK00437 C/W: 29.5R25 Tires Usage: 13,799 Hr Asset located in: Lake Worth, TX	S/N: CAT0740BHT4R01959 C/W: Air Conditioner, Rear View Ca	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BHT4R01959 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2013 US EPA Label, 29.5R25 Tires
148	2015 Cat 745C Articulated Dump Truck S/N: TFK00280 Usage: Not Available Asset located in: Lake Worth, TX		Usage: 10,492 Hr

Lot #	Details	Lot #	Details
155	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BKT4R01967 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2017 US EPA Label, CARB Compliant, 29.5R25 Tires Usage: 10,336 Hr	164	2007 Cat 725 Articulated Dump Truck S/N: CAT00725HB1L01150 C/W: Air Conditioner, 2007 US EPA Label, Tailgate, 23.5R25 Tires Usage: 9,403 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	165	2007 Cat 735 Articulated Dump Truck S/N: CAT00735AB1N01005
	E OF 4 - Lot #'s: 156, 157, 158, 159		C/W: Air Conditioner, Retarder, Steel Body Liner, 26.5R25 Tires Usage: 22,553 Hr
156	2015 Terex TA300 Articulated Dump Truck S/N: A11861079	166	Asset located in: Lake Worth, TX Cat D35C Articulated Dump Truck
	C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Steel Body Liner, 23.5R25 Tires Usage: 7,974 Hr Asset located in: Lake Worth, TX		S/N: Not Available C/W: Air Conditioner, Air Ride Seat, 26.5R25 Tires Usage: 9,124 Hr
157	2015 Terex TA300 Articulated Dump Truck		Asset located in: Lake Worth, TX
107	S/N: A11861065 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Steel Body Liner, 23.5R25 Tires Usage: 8,896 Hr	167	Cat D250E Articulated Dump Truck S/N: 5TN01384 C/W: Air Conditioner, 23.5R25 Tires Usage: 13,304 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
158	2014 Terex TA300 Articulated Dump Truck S/N: A11001282 C/W: Air Conditioner, Retarder, Rear View Camera, Steel Body Liner, 23.5R25 Tires Usage: 8,693 Hr Asset located in: Lake Worth, TX	— 168 	2017 Cat 631K Motor Scraper S/N: CAT0631KVWTR00117 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 37.25R3 Tires Usage: 8,898 Hr Asset located in: Midland, TX
159	2014 Terex TA300 Articulated Dump Truck		·
103	S/N: A11001278 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 23.5R25 Tires Usage: 8,343 Hr Asset located in: Lake Worth, TX	CHOIC	OICE OF 2 - Lot #'s: 169, 170 2006 Cat 621G Elevating Motor Scraper S/N: CAT0621GPDBB00312
160	2007 Terex TA30 Articulated Dump Truck S/N: A8941541 C/W: Air Conditioner, 23.5R25 Tires Usage: 43,274 Mi		C/W: Enclosed Cab, Air Conditioner, 33.25R29 Tires Usage: 175,403 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	170	2006 Cat 621G Motor Scraper
161	2006 Terex TA27 Articulated Dump Truck S/N: A8681159		S/N: CAT0621GTDBB00311 Usage: 18,091 Hr Asset located in : Lake Worth, TX
	C/W: Air Conditioner, Steel Body Liner, 23.5R25 Tires Usage: 5,855 Hr Asset located in : Lake Worth, TX	171	2004 Cat 615C Series II Motor Scraper S/N: CAT0615CE9XG01708 C/W: Enclosed Cab, Air Conditioner, Air Ride
162	2019 John Deere 260E Articulated Dump Truck S/N: 1DW260ETCKF697666		Seat, 29.5R29 Tires Usage: 7,020 Hr Asset located in : Lake Worth, TX
	C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Heated Body, Tailgate, 23.5R25 Tires Usage: 4,508 Hr Asset located in: Lake Worth, TX	172	1998 Cat 615C Series II Motor Scraper S/N: 09XG01112 Usage: Not Available Asset located in: Lake Worth, TX
163	2007 John Deere 250D Articulated Dump Truck S/N: DW250DT611160 Usage: 60,390 Mi Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
173	2016 John Deere 9620R Articulated Tractor S/N: 1RW9620RPGE052942 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, Autosteer, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade, 6 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Rear Wheel Weights Usage: 5,943 Hr Asset located in: Lake Worth, TX	181	2023 Cat D8 Crawler Dozer S/N: CAT000D8AAW800429 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 153 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank Ripper w/Hydraulic Pin Puller Usage: 1,311 Hr Asset located in: Lake Worth, TX
175	2016 John Deere 9570R Articulated Tractor S/N: 1RW9570RCGP052988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, Autosteer, Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade, LED Lights, 5 Rear Remotes, Auxiliary Hydraulics, ISOBUS, Dual IF800/70R38 Tires, Rear Wheel Weights, Front Wheel Weights Usage: 7,520 Hr Asset located in: Lake Worth, TX	182	2012 Cat D8T Crawler Dozer S/N: CAT00D8TKMLN01612 Usage: Not Available Asset located in: Lake Worth, TX 2010 Cat D8T Crawler Dozer S/N: KPZ03583 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
176	2014 Case IH Steiger 580S Scraper Tractor S/N: ZEF300648 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 2 Reverse, Requires Diesel Exhaust Fluid, 6 Rear Remotes, ISOBUS, Scraper Hitch, Dual 710/70R42 Front Tires, Front Wheel Weights, Dual 710/70R42 Rear Tires Usage: 3,479 Hr Notes: FEBRUARY 2023 - COMPLETE DEALER INSTALLED LONG BLOCK ENGINE; UNIT WAS PULLING K-TEC 1233 SCRAPER - ALSO IN THE	184	2008 Cat D8T Crawler Dozer S/N: KPZ03026 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX 2006 Cat D7R LGP Series II Crawler Dozer S/N: CAT00D7RLABJ01502 C/W: 192 in Wide Angle Blade Usage: 7,903 Hr Asset located in: Lake Worth, TX
177	AUCTION LOT 176; NEW PTO DRIVEN WATER PUMP; NEW BOOM HOSES AND CLAMPS Asset located in: Lake Worth, TX 2017 MTS MT42LGP 4 Tire Hydraulic Pull Scraper S/N: MT42LGP00287 C/W: 29.5R29, Rear Hydraulic Outlets Usage: Not Available Asset located in: Lake Worth, TX	186	2023 Cat D6 LGP Crawler Dozer S/N: CAT000D6LRDC01363 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 156 in Wide PAT Blade, 36 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 627 Hr Notes: EMISSIONS SYSTEM WARRANTY
178	2015 K-TEC 1233 4 Tire Ejector Pull Scraper S/N: KS2538 C/W: 33 cyd Capacity, Lead Scraper, 26.5R25 Tires, Rear Hydraulic Outlets Usage: Not Available Notes: UNIT WAS BEING PULLED BY CASE STEIGER 580S - ALSO IN AUCTION LOT 178; NEW PTO DRIVEN WATER PUMP; NEW BOOM HOSES AND CLAMPS Asset located in: Lake Worth, TX 1994 Cat 621F 4x4 Water Wagon S/N: 4SK00164 C/W: Enclosed Cab, Air Conditioner, In-Cab Remote Controlled Water Cannon, Rear Spray, Side Spray, 83.25-29 Tires Usage: 8,377 Hr	187	THROUGH NOVEMBER 2028 OR 3000 HOURS Asset located in: Lake Worth, TX 2022 Cat D6 XE Crawler Dozer S/N: CAT000D6KD5M01006 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 144 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 811 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 188, 189		193	2019 Cat D6T XW Crawler Dozer S/N: CAT00D6TEJNM00566 C/W: Enclosed Cab, Air Conditioner, Rear View
188	2022 Cat D6 XL Crawler Dozer S/N: CAT000D6CRBP01052 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 144 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION		Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps 160 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,211 Hr Asset located in: Lake Worth, TX
	Usage: 1,172 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS Asset located in: Lake Worth, TX	194	2019 Cat D6T XL Crawler Dozer S/N: CAT00D6TCNDY00513 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, US EPA Label, Requires Diesel Exhaust Fluid, 125
189	2022 Cat D6 XL Crawler Dozer S/N: CAT000D6TRBP01067 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps,		in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 4,082 Hr Asset located in : Lake Worth, TX
	137 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,538 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS Asset located in: Lake Worth, TX	195	2019 Cat D6T XL Crawler Dozer S/N: CAT00D6THHYT00409 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 152 in Wide PAT Blade, 22 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics
			Usage: 4,693 Hr Asset located in: Lake Worth, TX
CHOICE	E OF 3 - Lot #'s: 190, 191, 192	196	2018 Cat D6T XL Crawler Dozer
190	2020 Cat D6 Crawler Dozer S/N: CAT000D6ESA900371 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide Semi-U Blade w/ Single Tilt, 23 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics Usage: 2,769 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	196	S/N: CAT00D6TJ2B300199 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,831 Hr Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	197	2018 Cat D6T XL Crawler Dozer
191	2020 Cat D6 Crawler Dozer S/N: CAT000D6CSA900372 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes Usage: 3,462 Hr Asset located in: Bridgeport, NJ		S/N: CAT00D6TCNDY00387 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,768 Hr
192	2019 Cat D6 Crawler Dozer	_	Notes: NEW RAILS, TRACK PADS, SPROCKET SEGMENTS, AND TOP ROLLERS INTALLED
	S/N: CAT000D6KHNK00387		DECEMBER 3RD 2024 Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, GRADE with 3D, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes Usage: 4,017 Hr Asset located in: North East, MD	198	2018 Cat D6T XW Crawler Dozer S/N: CAT00D6TVJNM00416 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 163 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 8,360 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
200	2013 Cat D6T XL Crawler Dozer S/N: CAT00D6TCDTD01184 C/W: Enclosed Cab, Air Conditioner, Sweeps, 150 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 4,275 Hr Asset located in: Lake Worth, TX	207	2015 Cat D6N LGP Crawler Dozer S/N: PBA02428 C/W: Enclosed Cab, Air Conditioner, 2014 US EPA Label, Sweeps, 160 in Wide PAT Blade, 9 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY
201	2013 Cat D6T XL Crawler Dozer	208	Usage: 10,608 Hr Asset located in: Livingston, LA
	S/N: CAT00D6TAGMK01351 C/W: Enclosed Cab, Air Conditioner, Sweeps, 127 in Wide Semi-U Blade w/ Single Tilt, 22 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 8,504 Hr Asset located in: Lake Worth, TX		2012 Cat D6N XL Crawler Dozer S/N: CAT00D6NALJR00640 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 132 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 10,669 Hr
202	2012 Cat D6T XL Crawler Dozer S/N: CAT00D6TCDTD00253		Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Sweeps, 152 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,059 Hr Asset located in: Lake Worth, TX	209	2011 Cat D6N XL Crawler Dozer S/N: CAT00D6NELJR00562 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 126 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 18,107 Hr
203	2011 Cat D6T XL Crawler Dozer		Asset located in: Lake Worth, TX
	S/N: CAT00D6TCGMK00352 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2011 US EPA Label, Sweeps, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,782 Hr Asset located in: Lake Worth, TX	210	2008 Cat D6N LGP Crawler Dozer S/N: DJY01194 C/W: Open Operator Station, 2008 US EPA Label, 160 in Wide PAT Blade, 24 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, Rear Auxiliary Hydraulics, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,289 Hr
204	2023 Cat D5 LGP Crawler Dozer	7	Asset located in: Lake Worth, TX
	S/N: CAT000D5KZ6A01796 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 160 in Wide PAT Blade, 33 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 878 Hr	211	2007 Cat D6R XL Series III Crawler Dozer S/N: CAT00D6RCGJB00986 C/W: Enclosed Cab, Air Conditioner, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 9,162 Hr Asset located in: Lake Worth, TX
	Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH APRIL 2026 OR 5,000 HOURS	212	2014 Komatsu D155AX-7 Crawler Dozer S/N: KMT0D118L02090176
	Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Rear View
205	2022 Cat D5 Crawler Dozer S/N: CAT000D5AZ2K01218 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 127 in Wide PAT Blade, 22.5 in Single Grouser Track Shoes,		Camera, Pre-Wired for Grade Control, 2013 US EPA Label, 156 in Wide Sigmadozer w/ Dual Tilt, 2 Cylinder Single-Shank Ripper, Sweeps, 24 in Single Grouser Track Shoes Usage: 9,795 Hr Asset located in: Poteau, OK
	1 Cylinder Multi-Shank Ripper Usage: 1,409 Hr	213	2018 John Deere 950K LGP Crawler Dozer S/N: 1T0950KPPJF332504 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 185 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Carco Winch Usage: 5,936 Hr Asset located in: Lake Worth, TX
206	Asset located in: Lake Worth, TX 2019 Cat D6N XL Crawler Dozer S/N: CAT00D6NENJN00388 C/W: Enclosed Cab, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 8,394 Hr Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 214, 215		219	2015 Komatsu D65WX-17 Crawler Dozer S/N: KMT0D117E01002551 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 159 in Wide PAT Blade, 30 in Single
214	S/N: 1T0850LXJKF360852 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 194 in		Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 13,875 Hr Asset located in : Lake Worth, TX
	Wide Angle Blade w/ Dual Tilt, Carco Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 1,640 Hr Asset located in : Robstown, TX	220	2008 Komatsu D65EX-15E0 Crawler Dozer S/N: 70954 C/W: Enclosed Cab, Air Conditioner, 135 in Wide Semi-U Blade w/ Single Tilt, Winch,
215	2019 John Deere 850L LGP Crawler Dozer S/N: 1T0850LXTKF359972 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 195 in Wide Straight Blade w/ Dual Tilt,		Sweeps, 24 in Single Grouser Track Shoes Usage: 6,584 Hr Asset located in : Poteau, OK
	Carco H85-178V Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 2,054 Hr Asset located in: Baytown, TX	221	2022 John Deere 750L Crawler Dozer S/N: 1T0750LXCNF415326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 155 in Wide PAT Blade, 28 in Single Grouser Track Shoes 2 Cylinder Multi-
	E OF 3 - Lot #'s: 216, 217, 218		Single Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,349 Hr Asset located in : Lake Worth, TX
216	2019 Komatsu D65WX-18 Crawler Dozer S/N: KMT0D127PKA091866 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT	221A	2022 John Deere 750L Crawler Dozer S/N: 1T0750LXJNF417535 Usage: Not Available Asset located in: Lake Worth, TX
	Blade, Carco Winch, 30 in Single Grouser Track Shoes, PLUS Undercarriage Usage: 1,389 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	222	2019 John Deere 750K LGP Crawler Dozer S/N: 1T0750KXAKF365020 C/W: Enclosed Cab, Air Conditioner, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 5,330 Hr Asset located in: Lake Worth, TX
217	2019 Komatsu D65WX-18 Crawler Dozer S/N: 91854 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Carco H85-178VKOMD65-17/18 Winch, 30 in Single Grouser Track Shoes Usage: 1,872 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	224	2017 John Deere 700K Crawler Dozer S/N: 1T0700KXCHF313276 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 2 Cylinder Multi-Shank Ripper, 560 mm Single Grouser Track Shoes Usage: 4,035 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
218	2018 Komatsu D65WX-18 Crawler Dozer S/N: 91248 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Allied H6H Winch, 30 in Single Grouser Track	225	2013 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US EPA Label, 142 in Wide PAT Blade, 30 in Single Grouser Track Shoes Usage: 2,583 Hr Asset located in: Lake Worth, TX
	Shoes Usage: 2,060 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	226	2012 Cat D6K XL Crawler Dozer S/N: CAT00D6KHFBH02165 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
227	2022 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKCNF421869 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 27.5 in Single Grouser Track Shoes Usage: 1,047 Hr Asset located in: Beaumont, TX	233	2017 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKHHF316153 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 8,590 Hr Asset located in: Humble, TX
CHOIC	E OF 2 - Lot #'s: 228, 229	234	2013 Komatsu D61PX-23 Crawler Dozer
228	228 2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKTMF401153 C/W: Open Operator Station, US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide 18 in Single Grouser Track Shoes Usage: 469 Hr Asset located in: Lake Worth, TX		S/N: 30310 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2013 US EPA Label, 156 in Wide PAT Blade, Allied H6H Winch, 34 in Single Grouser Track Shoes Usage: 5,210 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE
229	2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKPMF392830		SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK
	C/W: Enclosed Cab, Air Conditioner, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,549 Hr Asset located in: Lake Worth, TX	235	2012 Cat D5K2 XL Crawler Dozer S/N: CAT0D5K2VKWW00232 C/W: Open Operator Station, 2012 US EPA Label, 106 in Wide PAT Blade, 20 in Single Grouser Track Shoes Usage: 7,645 Hr
230	2019 John Deere 650K XLT Crawler Dozer		Asset located in: Lake Worth, TX
	S/N: 1T0650KKKKF349894 C/W: Enclosed Cab, Air Conditioner, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,283 Hr Asset located in: Lake Worth, TX	236	2016 Cat D5K2 LGP Crawler Dozer S/N: CAT00D5KKKY202228 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 124 in Wide PAT Blade, 26 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 12,759 Hr
231	2017 John Deere 650K LGP Crawler Dozer		Asset located in: Humble, TX
	S/N: 1T0650KKAHF307207 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics Usage: 8,434 Hr Asset located in: Lake Worth, TX	237	2012 Cat D5K2 LGP Crawler Dozer S/N: CAT0D5K2HKYY00309 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 125 in Wide PAT Blade, 26 in Single Grouser Track Shoes Usage: 9,847 Hr Asset located in: Lake Worth, TX
		238	2019 John Deere 450K LGP Crawler Dozer
CHOIC	CHOICE OF 2 - Lot #'s: 232, 233		S/N: 1T0450KXKKF347727 C/W: Open Operator Station, Requires Diesel
232	2017 John Deere 650KLGP Crawler Dozer S/N: 1T0650KKTHF316190 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2017 US EPA Label,		Exhaust Fluid, 114 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 2,420 Hr Asset located in : Humble, TX
		220	
Requires Diesel Exhaust Fluid, 124 in N Blade, 24 in Single Grouser Track Sho	Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 7,369 Hr	239	2021 Cat D2 Crawler Dozer S/N: CAT000D2TXKM00230 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
240	2016 Cat D4K2 LGP Crawler Dozer S/N: CAT00D4KJKR202288 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 121 in Wide PAT Blade, 25 in Single Grouser Track Shoes, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 5,218 Hr	246	E OF 2 - Lot #'s: 246, 247 2005 Cat D5G LGP Crawler Dozer S/N: CAT00D5GVRKG01267 C/W: Open Operator Station, 127 in Wide PAT Blade, 24 in Single Grouser Track Shoes
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	247	Usage: Not Available Asset located in: Lake Worth, TX 2004 Cat D5G LGP Crawler Dozer
	Asset located in: Humble, TX		S/N: CAT00D5GARKG01013 C/W: Open Operator Station, Sweeps, 120 in Wide PAT Blade, 18 in Single Grouser Track
	E OF 2 - Lot #'s: 241, 242		Shoes Usage: 5,087 Hr Asset located in : Lake Worth, TX
241	2012 Cat D4K2 XL Crawler Dozer S/N: CAT0D4K2CKMM00228 C/W: Open Operator Station, Air Ride Seat, 2012 US EPA Label, Sweeps, 114 in Wide PAT Blade, 18 in Single Grouser Track Shoes, SystemOne Undercarriage, 2 Cylinder Multi- Shank Ripper Usage: 3,515 Hr Asset located in: Lake Worth, TX	249	1996 Cat D6E Crawler Dozer S/N: 2MJ02195 C/W: Open Operator Station, 146 in Wide Straight Blade w/ Dual Tilt, Winch, 560 mm Single Grouser Track Shoes Usage: 10,574 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
242	2011 Cat D4K XL Crawler Dozer S/N: CAT00D4KHMMM00764		SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
	C/W: Open Operator Station, Air Ride Seat, 2015 US EPA Label, 109 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 2,915 Hr Asset located in: Lake Worth, TX	250	1994 Cat D6E Tack Tractor S/N: 2MJ1574 C/W: Open Operator Station, 560 mm Single Grouser Track Shoes, (2) Lincoln Arc Welders, Front-Mounted Air Compressor Usage: 37,271 Hr
243	2008 Cat D4K XL Crawler Dozer S/N: CAT00D4KLMMM00181 C/W: Open Operator Station, Air Ride Seat, Sweeps, 115 in Wide PAT Blade, 18 in Single		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
	Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 3,155 Hr Asset located in : Lake Worth, TX	251	2008 John Deere 700J Combination Pipelaye w/ 2008 Midwestern M540 Conversion S/N: T0700JX156344 C/W: Canopy, 3 Lever Boom Control, 2007 US
244	2021 Cat D1 Crawler Dozer S/N: CAT000D1EXKF00156 C/W: Enclosed Cab, Air Conditioner, Air Ride		EPA Label, Hydraulic Hoists, 30 in Single Grouser Track Shoes Usage: 6,999 Hr
	Seat, Requires Diesel Exhaust Fluid, 115 in Wide PAT Blade, 16 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,144 Hr		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX		·
245	2005 John Deere 700J XLT Crawler Dozer S/N: T0700JX110023 C/W: Enclosed Cab, Air Conditioner, 2005 US	сноіс	E OF 3 - Lot #'s: 252, 253, 254
	Ericlosed Cab, All Conditioner, 2005 05 EPA Label, 120 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: Not Available Asset located in: Humble, TX	252	1977 Cat 561C Pipelayer w/ 2007 Conversion S/N: 92J776 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft 0 in Side Boom, Hydraulic Hoists Usage: 997 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE
			PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
253	1975 Cat 561C Pipelayer S/N: 92J593 C/W: 3 Lever Boom Control, 18 in Single Grouser Track Shoes, 25 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 539 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK		E OF 2 - Lot #'s: 258, 259 1971 Cat D4D Pipelayer w/ Midwestern D4D Conversion S/N: 60J2695 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft 0 in Side Boom, Hydraulic Hoists, Winch Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
254	1973 Cat 561C Pipelayer S/N: 92J413 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom, Hydraulic Hoists Usage: 903 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.	259	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK 1966 Cat D4D Pipelayer w/ Midwestern 0D4D Conversion S/N: 86A1705 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft Side Boom,
CHOIC 255	Asset located in: Lahoma, OK CHOICE OF 2 - Lot #'s: 255, 256		Hydraulic Hoists Usage: 6,536 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	M561C Conversion S/N: 92J233 C/W: 3 Lever Boom Control, 510 mm Single Grouser Track Shoes, 20 ft 0 in Side Boom, Mechanical Hoists Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	260	1956 Cat D7C Pipelayer w/ Conversion S/N: 17A4488 C/W: 560 mm Single Grouser Track Shoes, 20 ft Side Boom, Mechanical Hoists Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
256	1969 Cat 561C Pipelayer S/N: 92J238 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom, Hydraulic Hoists Usage: 1,795 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	S/N: 1T0755KXAMF402857 C/W: Enclosed Cab, Air Conditioner, Camera, 2021 US EPA Label, Require Exhaust Fluid, 101 in Bucket, 22 in D Grouser Track Shoes, 2 Cylinder Mu Ripper	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF402857 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 101 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper
257	1982 Cat D5B Pipelayer S/N: 44X01116 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 17 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 52 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	262	Usage: Not Available Asset located in: Lake Worth, TX 2021 John Deere 755K Crawler Loader S/N: 1T0755KXPMF399113 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,525 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
263	2021 John Deere 755K Crawler Loader S/N: 1T0755KXKMF400262 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Manual Coupler, 94 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 6,008 Hr	271	2009 Cat 939C Crawler Loader S/N: CAT0939CC6DS02032 C/W: Open Operator Station, 84 in Multi- Purpose Bucket, 18 in Double Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 2,351 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	272	2007 Cat 815F Soil Compactor
264	2021 John Deere 755K Crawler Loader S/N: 1T0755KXVMF409838 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, 95 in Bucket, 22 in Double Grouser Track Shoes, Multi-Shank Ripper Usage: 5,530 Hr Asset located in: Lake Worth, TX	—272	S/N: CAT0815FCBYN00307 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, 38 in Compaction Wheel Width, 146 in Straight Blade w/ Single Tilt, Fast Fuel Usage: 10,824 Hr Asset located in: Lake Worth, TX
265	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF411719 C/W: Enclosed Cab, Requires Diesel Exhaust Fluid, 99 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,012 Hr	273	2013 Hamm 3410P Padfoot Drum Compactor S/N: H1791920 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Deutz TCD2012L042V 134 hp 4.03 L Diesel Engine, 84 in Drum Usage: 6,559 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
CHOIC 266	E OF 2 - Lot #'s: 266, 267 2017 John Deere 605K Crawler Loader S/N: 1T0605KXCHE310174 C/W: Open Operator Station, Air Ride Seat, 88 in Bucket, 18 in Double Grouser Track Shoes, 2	274	2016 Dynapac CA2500PD Padfoot Drum Compactor S/N: 10000167PHA020589 C/W: Open Operator Station, 2017 US EPA Label, Cummins QSF 4 Cylinder 89 kW 3.8 L Diesel Engine, 84 in Drum Usage: 2,102 Hr Asset located in: Lake Worth, TX
	Cylinder Multi-Shank Ripper Usage: 1,822 Hr	274A	Vibromax 1106 Padfoot Drum Compactor S/N: JKC8305502
267	Asset located in: Lake Worth, TX 2017 John Deere 605K Crawler Loader S/N: 1T0605KXPHE310856 C/W: Open Operator Station, Air Ride Seat, 88 in Product 18 in Parkhalo Cray and Track Shape 2		C/W: Enclosed Cab, Air Conditioner, Diesel Engine, 82 in Drum Usage: 2,512 Hr Asset located in : Lake Worth, TX
	in Bucket, 18 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,632 Hr Asset located in : Lake Worth, TX	275	2008 Dynapac CA250PD Padfoot Drum Compactor S/N: 6582US5658
268	2015 Cat 963D Crawler Loader S/N: CAT0963DTLCS02294 C/W: Enclosed Cab, Air Conditioner, 101 in Bucket, 22 in Double Grouser Track Shoes, 2	276	C/W: Open Operator Station, 4 Cylinder Diesel Engine, 84 in Drum Usage: 3,598 Hr Asset located in : Lake Worth, TX
	Cylinder Multi-Shank Ripper Usage: 4,156 Hr Asset located in: Lake Worth, TX		2007 Cat CP563E Padfoot Drum Compactor S/N: CATCP563ACNT01503 C/W: Open Operator Station, Cat 6 Cylinder
269	2005 Cat 963C Crawler Loader S/N: CAT0963CCBBD01372 C/W: England Cab. 102 in Bucket. 23 in		Diesel Engine, 84 in Drum, Leveling Blade Usage: 755 Hr Asset located in : Lake Worth, TX
	C/W: Enclosed Cab, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 24,275 Hr Asset located in : Lake Worth, TX	S/N: CATCP433JCFK00238 C/W: Open Operator Station, 20 Label, Perkins 3PKXL03.9AKI 4 kW 3.99 L Diesel Engine, 66 in l Blade Usage: 1,105 Hr	C/W: Open Operator Station, 2003 US EPA Label, Perkins 3PKXLO3.9AKI 4 Cylinder 74.5
269A	2004 Cat 963C Crawler Loader S/N: AT0963CPBBD00676 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
278	2014 Bomag BW145PDH Padfoot Drum Compactor S/N: 101586021003 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2014 US EPA Label, Kubota v3307 4 Cylinder 37 kW 3.3 L Diesel Engine, 60 in Drum Usage: Not Available Asset located in: Lake Worth, TX	284	2018 Volvo SD115B Smooth Drum Compactor S/N: VCES115BA0S236505 C/W: Open Operator Station, Air Ride Seat, 2018 US EPA Label, Volvo D4J 4 Cylinder 148 hp 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 85 in Drum, Padfoot Shell Kit Usage: 2,594 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
2/9	2007 Bomag BW145PDH-3 Padfoot Drum Compactor		Asset located in: Humble, TX
	S/N: 901581491236 C/W: Open Operator Station, Diesel Engine, 58 in Drum Usage: 616 Hr Asset located in : Lake Worth, TX	285	2015 Volvo SD115 Padfoot Drum Compactor S/N: VCES115BL0S236313 C/W: Open Operator Station, 2017 US EPA Label, Volvo D4J 4 Cylinder 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 1,488 Hr
280	Sakai SV201TB-1 Padfoot Drum Compactor		Asset located in: Lake Worth, TX
281	S/N: LSV2720110 C/W: Open Operator Station, Tier 4, 2008 US EPA Label, Kubota V3307-D1-T-ET04 4 Cylinder 55.4 kW 3.3 L Diesel Engine, 55 in Drum, Leveling Blade Usage: 1,882 Hr Asset located in: Lake Worth, TX Volvo SD45 Padfoot Drum Compactor	286	2013 Bomag BW211D-50 Smooth Drum Compactor S/N: 901583531097 C/W: Open Operator Station, 2013 US EPA Label, Duetz 4 Cylinder 121 hp 3.6 L Diesel Engine, 84 in Drum Usage: 3,618 Hr Asset located in: Lake Worth, TX
	S/N: VCE00S45L0S229308 C/W: Open Operator Station, Kubota Diesel Engine, 54 in Drum Usage: 833 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	287	2013 Dynapac CA2500D Smooth Drum Compactor S/N: 10000138C0A012121 C/W: Open Operator Station, 2013 US EPA Label, Cummins 4 Cylinder 130 hp 4.5 L Diesel Engine, 84 in Drum Usage: Not Available Asset located in: Lake Worth, TX
		288	2006 Cat CS563E Smooth Drum Compactor
282	Asset located in: Fort Smith, AR Bomag BW124PDH-40 Padfoot Drum Compactor (Inoperable) S/N: 901581401027	289	S/N: CATCS563PCNG01830 C/W: Open Operator Station, Cat 6 Cylinder Diesel Engine, 84 in Drum Usage: 4,090 Hr Asset located in : Lake Worth, TX
	C/W: Open Operator Station, 2011 US EPA Label, Deutz 3 Cylinder 45 hp 2.3 L Diesel Engine, 48 in Drum Usage: 1,423 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		2005 Ingersoll Rand SD122DX Smooth Drum Compactor S/N: 183705 C/W: Open Operator Station, 84 in Drum Usage: Not Available Asset located in: Lake Worth, TX
	REMOVAL; Asset located in: Lake Worth, TX	290	2019 Volvo SD75B Padfoot Drum Compactor
283	2021 XCMG CV123PDU Smooth Drum Compactor S/N: XUG01231CMJE04323 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Cummins 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum, Padfoot Shell Kit Usage: 692 Hr Asset located in: Lake Worth, TX		S/N: VCE0S75BK0S241348 C/W: Open Operator Station, Tier 4, Volvo Diesel Engine, 66 in Drum Usage: 1,190 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR

Lot #	Details	Lot #	Details	
291	2019 Dynapac CA1500D Smooth Drum Compactor S/N: 10000160AKA024661 C/W: Open Operator Station, Swivel Operator Controls, 2021 US EPA Label, Deutz TD3.6L4 4 Cylinder 3.6 L Diesel Engine, 66 in Drum Usage: 749 Hr	295	2015 Hamm H5i Smooth Drum Compactor S/N: H2220266 C/W: Open Operator Station, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 54 in Drum Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	 296	2018 Bomag BW124DH-5 Smooth Drum	
292	2015 Dynapac CA1500D Padfoot Drum Compactor S/N: 10000156CFA016214 C/W: Open Operator Station, 2014 US EPA Label, Cummins QSB3.3 100 hp 3.26 L Diesel Engine, 66 in Drum, Leveling Blade, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT		Compactor S/N: 861586571071 C/W: Open Operator Station, 2018 US EPA Label, Kubota V2403-CR-EF04 4 Cylinder 33.6 kW 2.4 L Diesel Engine, 47.5 in Drum Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: 1,459 Hr Notes: SUNSTATE EQUIPMENT CO. RENTAL PEOPLE YOU CAN DEPEND ON Asset located in: Oklahoma City, OK	297	2017 Bomag BW 124 Smooth Drum Compactor S/N: 861832122115 Usage: Not Available Asset located in: Humble, TX	
293	2015 Bomag BW177DH-5 Smooth Drum Compactor S/N: 101586041089 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 66 in Drum Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	298	2011 Cat CB54 Double Drum Roller S/N: CAT0CB54VJLM00434 C/W: Open Operator Station, Swivel Operator Controls, Cat C4.4 4 Cylinder Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX	
	THE INSPECTION REPORT Asset located in: Humble, TX		2006 Cat CB-534D XW Double Drum Roller S/N: CATCB534KEAA00412	
294	2010 Volvo SD70D Smooth Drum Compactor S/N: VC500670A00225225 C/W: Open Operator Station, Tier 3, 2009 US EPA Label, Kubota V3800-DI-T-ET02 4 Cylinder 74 kW Diesel Engine, 66 in Drum Usage: 2,841 Hr		C/W: Open Operator Station, Controls, 2005 US EPA Label, kW 4.4 L Diesel Engine, 78.5 i Width, Water System Usage: Not Available	C/W: Open Operator Station, Swivel Operator Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2005 Cat CB-534D XW Double Drum Roller	
294A	2007 Ingersoll Rand SD70D-TF Smooth Drum Compactor S/N: 196662 C/W: Open Operator Station, 2007 US EPA Label, Cummins b4.5 4 Cylinder 78 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM- WATKINS-CONSTRUCTION		S/N: CATCB534AEAA00397 C/W: Open Operator Station, Swivel Operator Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: 3,215 Hr Asset located in: Lake Worth, TX	301A	2015 Case DV210C Double Drum Roller S/N: DDDD210CNENTL2010	
294B	2004 Ingersoll Rand SD70D-TF Smooth Drum Compactor S/N: 177760 C/W: Open Operator Station, 2004 US EPA Label, Cummins B4.5 4 Cylinder 79 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Notes: THE AGE AND CONDITION OF THE MACHINE INDICATES MORE HOURS THAN SHOWN ON THE HOUR METER Asset located in: Lake Worth, TX		C/W: Open Operator Station, Swivel Operator Controls, 2014 US EPA Label, Deutz 100 hp 3.62 L Diesel Engine, 66 in Compaction Width, Water System Usage: 1,004 Hr Asset located in: Lake Worth, TX	
		302	2016 Cat CB36B Double Drum Roller S/N: CATCB36BAM3600111 C/W: Open Operator Station, Cat 4 Cylinder Diesel Engine, 55 in Compaction Width, Water System, Edge Cutter Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
303	2013 Hamm HD13VV Double Drum Roller S/N: H2011675 C/W: Open Operator Station, Kubota V2203 4 Cylinder 2.2 L Diesel Engine, 51 in Compaction Width, Edge Cutter Usage: 1,104 Hr	311	2018 Bomag BW900-50 Double Drum Roller S/N: 861834072457 C/W: Open Operator Station, Honda GX 630 2 Cylinder Gasoline Engine, 36 in Compaction Width, Edge Cutter Usage: 685 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
CHOICE OF 2 - Lot #'s: 304, 305 304 2023 Hamm HD12VV Double Drum Roller		312	2018 Bomag BW900-50 Double Drum Roller S/N: 881834072563 C/W: Open Operator Station, Honda GX 630 2 Cylinder Gasoline Engine, 35 in Compaction Width Usage: Not Available
	(Unused) S/N: WGH0H230CHAA06595		Asset located in: Lake Worth, TX
	C/W: Open Operator Station, E-Stops, Tier 4, 2020 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 22 Hr Asset located in: Lake Worth, TX	CHOIC	E OF 3 - Lot #'s: 313, 314, 315 2016 Bomag BW900-50 Double Drum Roller
305	2022 Hamm HD12VV Double Drum Roller S/N: WGH0H230KHAA05864		S/N: 861834072133 Usage: 239 Hr Asset located in : Lake Worth, TX
	C/W: Open Operator Station, E-Stops, Tier 4, 2022 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 63 Hr Asset located in : Lake Worth, TX	314	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072137 C/W: Open Operator Station, Honda 2 Cylinder Gasoline Engine, 36 in Compaction Width Usage: Not Available Asset located in: Lake Worth, TX
307	Volvo DD24 Double Drum Roller	-	
	S/N: 196371 C/W: Open Operator Station, 3 Cylinder Diesel Engine, 47.25 in Compaction Width, Water System Usage: 2,886 Hr Asset located in : Lake Worth, TX	315	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072138 C/W: Open Operator Station, Honda 2 Cylinder Gasoline Engine, 35.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 308, 309	316	Wacker Neuson RD11A Double Drum Roller S/N: 5613749
308	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263LHHAA00855 C/W: Open Operator Station, Tier 4, 2021 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel		C/W: Open Operator Station, 2014 US EPA Label, Honda GX 630 2 Cylinder Gasoline Engine, 35 in Compaction Width Usage: 594 Hr Asset located in : Humble, TX
	Engine, 39 in Compaction Width, Water System Usage: 148 Hr Asset located in : Lake Worth, TX	317	2006 Isuzu NQR Sweeper Truck S/N: JALE5B16267903657
309	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263THAA00778 C/W: Open Operator Station, Kubota D1105 Diesel Engine, 39 in Compaction Width, Water System Usage: Not Available		C/W: Isuzu 4 Cylinder Diesel 190 hp Engine, 2005 US EPA Label, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 134 in Wheelbase, Kubota Auxiliary Engine, Vacuum Sweeper, Under Body Broom, Gutter Brooms Usage: 93,999 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	318	2019 LeeBoy CB95 Self-Propelled Broom
310	2017 Hamm HD10C VV Double Drum Roller S/N: H1994782 C/W: Open Operator Station, Tier 4, 2016 US EPA Label, Kubota D1005-EF05 3 Cylinder 14.8 kW 1.0 L Diesel Engine, 39 in Compaction Width, Water System Usage: 892 Hr Asset located in: Lake Worth, TX		S/N: 242550 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2019 US EPA Label, Hatz 4H50TIC 4 Cylinder 55 kW 1.9 L Diesel Engine Usage: 359 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
319	2019 Broce RJT-350 Self-Propelled Broom S/N: 411566 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2018 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	326	2014 Superior DT80J Self-Propelled Broom S/N: 814877 C/W: Enclosed Cab, Air Conditioner, 8 ft 7 in Broom, Water System, 2014 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 691 Hr Asset located in: Lake Worth, TX
СНОІС	CHOICE OF 2 - Lot #'s: 320, 321		2014 Superior DT80J Self-Propelled Broom S/N: 814869
320	2015 Broce KR350 Self-Propelled Broom S/N: 409370 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota V3600-T-ET03 4 Cylinder 55.4 kW 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, John Deere 4045TF290 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,536 Hr Asset located in: Lake Worth, TX
	Usage: 1,930 Hr Asset located in : Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 329, 330
321	2015 Broce KR350 Self-Propelled Broom S/N: 409369 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder 55.4 kW 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 698 Hr Asset located in: Lake Worth, TX	329	2001 Broce BB250B Self-Propelled Broom S/N: 304993 C/W: Open Operator Station, 8 ft Broom, Wate System, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 18.5 kW 1.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available
322	2015 Broce KR-350 Self-Propelled Broom S/N: 409307 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, Kubota 4 Cylinder Diesel		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,522 Hr Asset located in: Oklahoma City, OK	330	2001 Broce BB250B Self-Propelled Broom S/N: 304910 C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2015 US EPA Label, Kubota
323	2015 Broce KR350 Self-Propelled Broom S/N: 409308 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2015 US EPA Label, Kubota V3600-T-ET03 4 Cylinder 3.6 L Diesel		V1505-EF01 4 Cylinder 18.5 kW 1.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 100 Hr Asset located in : Lake Worth, TX
	Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,137 Hr Asset located in: Lake Worth, TX	330A	2001 Broce BB250B Self-Propelled Broom S/N: 305062 C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2018 US EPA Label, Kubota V1505 18.2 kW 1.5 L Diesel Engine
324	2015 Broce KR350 Self-Propelled Broom S/N: 409371		Usage: 663 Hr Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder Diesel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 1,187 Hr Asset located in: Lake Worth, TX	333	2000 Rosco RB48 Self-Propelled Broom S/N: 36730 Usage: Not Available Asset located in: Lake Worth, TX
325A	2014 Broce CRT350 Self-Propelled Broom S/N: 408677 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, 2013 US EPA Label, Cat 4 Cylinder 60.5 kW 4.4 L Diesel Engine Usage: 5,095 Hr Asset located in: Lake Worth, TX	334	2021 John Deere 870G LC Tracked Excavator S/N: 1FF870GXJMF890112 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, 9 ft 8 in Stick, 36 in Double Grouser Track Shoes, 96 in Digging Bucket, Counterweight Removal System Usage: 5,764 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
334A	2015 Komatsu PC650LC-8E0 Tracked Excavator S/N: KMTPC233CFC065343 C/W: Air Conditioner, Air Ride Seat, 10 ft Stick, 36 in Triple Grouser Track Shoes, 80 in Digging Bucket Usage: 18,316 Hr Asset located in: Lake Worth, TX	341	2013 Hitachi ZX470LC-5B Tracked Excavator S/N: HCMJAA70A00030283 C/W: Air Ride Seat, Tier 4, US EPA Label, 9 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 68 in Digging Bucket, Catwalks Usage: 11,455 Hr Asset located in: Humble, TX
335 CHOIC	2015 Kobelco SK500LC-9 Tracked Excavator S/N: YS1203617 Usage: Not Available Asset located in: Lake Worth, TX	342	2016 John Deere 380G LC Tracked Excavator S/N: 1FF380GXTGF900147 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket
337	2017 Cat 349FL Tracked Excavator		Usage: 10,290 Hr Asset located in : Lake Worth, TX
	S/N: CAT0349FCHPD10110 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 30 in V-Bottom Bucket Usage: 13,440 Hr Asset located in: Lake Worth, TX	343	2019 Cat 336 Tracked Excavator S/N: CAT00336PDKS00399 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 12,251 Hr
338	2017 Cat 349F L Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT0349FAHPD10053 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2016 US EPA Label, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Manual Quick Coupler, 30 in V- Bottom Bucket Usage: 13,635 Hr Asset located in: Lake Worth, TX	344	2019 Cat 336 Tracked Excavator S/N: CAT00336LDKS01786 C/W: Air Conditioner, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, 33.5 in Triple Grouser Track Shoes, 43 in Digging Bucket Usage: Not Available
339	2013 Cat 349E Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT0349EPMPZ00695 C/W: Air Conditioner, Straight Travel Pedal, Rear View Camera, 2013 US EPA Label, 12 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket Usage: 10,831 Hr Asset located in: San Antonio, TX	S/N: CAT0336FARKB21335 C/W: Air Conditioner, Straight Tra Ride Seat, Control Pattern Chang Camera, 2018 US EPA Label, Req Exhaust Fluid, 12 ft 6 in Stick, Au: Hydraulic Plumbing, 33 in Triple of Shoes, 44 in Digging Bucket, EQU FROM-WATKINS-CONSTRUCTION Usage: 4,625 Hr Asset located in: Lake Worth, TX 346 2018 Cat 336FL Tracked Excavat S/N: TZA20175 C/W: Air Conditioner, Straight Tra Ride Seat, Rear View Camera, 20 Label, Requires Diesel Exhaust Fl Stick, Auxiliary Hydraulic Plumbir Grouser Track Shoes, 43 in Diggi EQUIPMENT-FROM-WATKINS-CO	2018 Cat 336FL Tracked Excavator S/N: CAT0336FARKB21335 C/W: Air Conditioner, Straight Travel Pedal, Ride Seat, Control Pattern Changer, Rear Vie
340	2021 Hyundai HX480L Tracked Excavator S/N: HHKHKB01JL0000163 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in		Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 44 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION
	Triple Grouser Track Shoes, 72 in Digging Bucket, Auto Lube Usage: 6,810 Hr Asset located in : Humble, TX		2018 Cat 336FL Tracked Excavator S/N: TZA20175 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA
340A	2014 John Deere 470GLC Tracked Excavator S/N: 1FF470GXTCE470692 C/W: Requires Diesel Exhaust Fluid, 13 ft 5 in Stick, 35.5 in Triple Grouser Track Shoes, 72 in Digging Bucket Usage: 12,526 Hr Asset located in: Lake Worth, TX		Label, Requires Diesel Exhaust Fluid, 12 ft 6 Stick, Auxiliary Hydraulic Plumbing, 33 in Tri Grouser Track Shoes, 43 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCT

Lot #	Details	Lot #	Details
347	2018 Cat 336FL Tracked Excavator S/N: CAT0336FKTZA20109 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 46 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 5,561 Hr Asset located in: Lake Worth, TX	352	2015 Cat 336FL Tracked Excavator S/N: CAT0336FJRKB00903 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2014 US EPA Label, 12 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 31 in Digging Bucket, Hydraulic Thumb Usage: 7,433 Hr
348	2018 Cat 336FL Tracked Excavator S/N: CAT0336FKRKB21071 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 42 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,613 Hr Asset located in: Lake Worth, TX		Asset located in: Midland, TX 2015 Cat 336FL Roadbuilder Tracked Excavator S/N: RKB00900 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 33.5
349	2017 Cat 336F L Tracked Excavator S/N: CAT0336FLTZA10137 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 13,138 Hr		in Triple Grouser Track Shoes, Rock Guards, 3 in Digging Bucket Usage: 6,370 Hr Asset located in : Midland, TX E OF 2 - Lot #'s: 354, 355
350	Asset located in: Lake Worth, TX 2016 Cat 336FL Tracked Excavator S/N: CAT0336FJSSN00477 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Cab Screens, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, EQUIPMENT-FROM-PULICE-	354	2013 Cat 336 EL Tracked Excavator S/N: CAT0336EJRZA00234 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 12 ft 10 in Stick, 34 in Triple Grouser Track Shoes, 48 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,605 Hr Asset located in: Lake Worth, TX
351	CONSTRUCTION Usage: 10,564 Hr Asset located in: Humble, TX 2016 Cat 336FL Tracked Excavator S/N: CAT0336FCTZA00440 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 56 in Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 12,821 Hr Asset located in: Lake Worth, TX	355	2013 Cat 336 EL Tracked Excavator S/N: CAT0336EEFJH00483 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 45 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 7,199 Hr Asset located in: Lake Worth, TX
		356	2013 Cat 336EL Tracked Excavator S/N: CAT0336ECFJH00355 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, 33.5 in Triple Grouser Track Shoes, 50 in Digging Bucket Usage: 8,712 Hr Asset located in: Midland, TX

Lot #	Details	Lot #	Details
357	2012 Cat 336 EL Tracked Excavator S/N: CAT0336EKBZY01618 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 34 in Triple Grouser Track Shoes, 42 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 9,409 Hr	362	2012 Komatsu PC360LC-10 Tracked Excavator S/N: KMTPC24202070045 C/W: Air Conditioner, 2011 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 56 in Digging Bucket, Hydraulic Thumb Usage: 12,043 Hr Asset located in: Lake Worth, TX
		363	2017 XCMG XE360U Tracked Excavator
CHOIC	Asset located in: Lake Worth, TX DICE OF 2 - Lot #'s: 358, 359		S/N: XUG03600KHKA00061 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, US EPA Label, 8 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 823 Hr
358	2012 Cat 336E L Tracked Excavator S/N: CAT0336EVBZY01509 C/W: Air Conditioner, Straight Travel Pedal, Air		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Ride Seat, Rear View Camera, 2012 US EPA	06.4	<u>·</u>
	Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 58 in Digging Bucket Usage: 12,654 Hr Asset located in : Lake Worth, TX	364	2018 Cat 335F LCR Tracked Excavator S/N: SGJ20006 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 4 in Stick, Auxiliary
359	2012 Cat 336E L Tracked Excavator S/N: CAT0336EKBZY00808 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2011 US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 14,076 Hr Asset located in: Lake Worth, TX		Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 43 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 5,806 Hr Asset located in: Lake Worth, TX
		365	S/N: KMTPC19IJ54A10246 C/W: Air Conditioner, Rear View Camera, 2010
360	2010 Cat 336D Tracked Excavator S/N: CAT0336DKW3K01214 C/W: Air Conditioner, 2010 US EPA Label, 10 ft		US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 56 in Digging Bucket Usage: 11,202 Hr Asset located in : Lake Worth, TX
	6 in Stick, Auxiliary Hydraulic Plumbing, 34 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: 89,205 Hr Asset located in : Lake Worth, TX	366	2012 John Deere 350G LC Tracked Excavator S/N: 1FF350GXCCE808325 C/W: Air Conditioner, Air Ride Seat, 2011 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic
361	2017 Komatsu PC360LC 11 Tracked Excavator S/N: KMTPC256HHWA35865		Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: Not Available
	C/W: Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid,		Asset located in: Lake Worth, TX
	10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 60 in Digging Bucket Usage: 15,343 Hr	сноіс	E OF 2 - Lot #'s: 367, 368
	Asset located in: Lake Worth, TX	367	2022 Cat 330 Tracked Excavator
361A	2017 Komatsu PC360LC-11 Roadbuilder Tracked Excavator S/N: KMTPC256AHWA35992 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 13 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 63 in Digging Bucket, Manual Thumb, Nye 516541, PC 360 Grapple Usage: 5,789 Hr Asset located in: Midland, TX		S/N: CAT00330VWCH30051 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,104 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
368	2021 Cat 330 Tracked Excavator S/N: CAT00330AWCH20489 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,395 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	СНОІС 372	2020 Cat 330GC Tracked Excavator S/N: CAT00330CGDW10069 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,885 Hr
369	2020 Cat 330 Tracked Excavator S/N: CAT00330JWCH10184		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
СНОІС	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Surround View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,590 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 370, 371	373	2020 Cat 330GC Tracked Excavator S/N: CAT00330CSCZ10029 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,443 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
370	2020 Cat 330 Tracked Excavator S/N: CAT00330TWCH10651 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,428 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB	374	2020 Cat 330GC Tracked Excavator S/N: CAT00330VGDW10047 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,462 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
371	2020 Cat 330 TC Tracked Excavator S/N: CAT00330JWCH10654 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,072 Hr Asset located in: Lake Worth, TX	375	2020 Cat 330GC Tracked Excavator S/N: CAT00330KGDW10058 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 38 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,503 Hr

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
376	2020 Cat 330GC Tracked Excavator S/N: CAT00330ESCZ10028 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 35 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,558 Hr	381	2018 Cat 330F L Tracked Excavator S/N: CAT0330FEMBX20643 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 3,732 Hr Asset located in: Lake Worth, TX
	Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	382	2018 Cat 330F L Tracked Excavator S/N: CAT0330FCMBX20666 C/W: Air Conditioner, Straight Travel Pedal, Air
377	2020 Cat 330GC Tracked Excavator S/N: CAT00330LGDW10049 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track		Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,894 Hr Asset located in: Lake Worth, TX
	Shoes, 36 in Cleanup Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION		
	Usage: 2,882 Hr Notes: EMISSIONS SYSTEM WARRANTY	383	E OF 2 - Lot #'s: 383, 384
	THROUGH APRIL 2026 OR 3000 HOURS Asset located in : Lake Worth, TX		2018 Cat 330F L Tracked Excavator
378	2019 Cat 330 Tracked Excavator S/N: CAT00330TLHW00257 C/W: Air Conditioner, Rear & Side View Cameras, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 5,554 Hr Asset located in: Lake Worth, TX		S/N: CAT0330FTHCK20095 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,836 Hr Notes: COMES WITH UNUSED HYDRAULIC
379	2019 Cat 330F L Tracked Excavator S/N: CAT0330FJHCK20408		THUMB Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,557 Hr Asset located in: Lake Worth, TX	384	2018 Cat 330F L Tracked Excavator S/N: CAT0330FPMBX20257 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,485 Hr
CHOIC	E OF 3 - Lot #'s: 380, 381, 382	205	Asset located in: Lake Worth, TX
380	2018 Cat 330F L Tracked Excavator S/N: MBX20638 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,586 Hr Asset located in: Lake Worth, TX	385	2012 Volvo EC300DL Tracked Excavator S/N: VCEC300DC00210349 C/W: Straight Travel Pedal, 2012 US EPA Label, 10 ft Stick, 36 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 9,162 Hr Asset located in: Lake Worth, TX
		386	2017 John Deere 300G LC Tracked Excavator S/N: 1FF300GXKHF730514 C/W: Air Conditioner, 2017 US EPA Label, CARB Compliant, 13 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 28 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 43 in Digging Bucket, Hydraulic Thumb Usage: 6,335 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
387	2017 Volvo ECR305CL Tracked Excavator S/N: VCECR305V00110701 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, 2016 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 6,005 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: El Paso, TX	392	2 2019 Komatsu PC290LC-11 Tracked Excavator S/N: KMTPC255AJKK73097 C/W: Air Conditioner, Air Ride Seat, Tier 4, 201 US EPA Label, Requires Diesel Exhaust Fluid, Offt Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31.5 in Triple Grouser Track Shoes, Rock Guards, 48 in Digging Bucket Usage: 4,542 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE
388	Hyundai R300LC-9A Tracked Excavator S/N: HHKHZ803ED0000030 C/W: Air Conditioner, Rear View Camera, 2012		AVAILABLE Asset located in: McAlester, OK
	US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 4,396 Hr Asset located in: Lake Worth, TX	393	2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27917 C/W: Air Conditioner, Control Pattern Changer, 2018 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 43 in Cleanup Bucket
389	2018 Volvo EC250ELR Tracked Excavator S/N: VCEC250EK00310554 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 25 ft 6 in Boom, 26 ft Stick, 36 in Triple Grouser Track Shoes, 60 in Cleanup Bucket		Usage: 4,865 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK
	Usage: 4,986 Hr Asset located in: Lake Worth, TX	394	2018 Komatsu PC290LC-11 Tracked Excavator
CHOICE	CE OF 6 - Lot #'s: 390, 391, 392, 393, 394, 395 2019 Komatsu PC290LC-11 Tracked Excavator S/N: JKK73093 C/W: Air Conditioner, Rear View Camera, 10 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 42 in Cleanup Bucket Usage: 3,632 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE		S/N: A27916 C/W: Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,473 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
			PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	PICKED UP BY DECEMBER 31ST OR WILL BE	395	2018 Komatsu PC290LC-11 Tracked Excavator
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	333	S/N: KMTPC255CJWA27918 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label,
391	Asset located in: McAlester, OK 2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27915 C/W: Air Conditioner, Control Pattern Changer,		Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 5,920 Hr
	Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 5 in Stick, 31.5 in Triple		Asset located in: Lake Worth, TX
	Grouser Track Shoes Usage: 4,248 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	396	2009 Cat 329DL Tracked Excavator S/N: CAT0329DLJHJ00330 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Manual Thumb, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 10,025 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICI	CHOICE OF 2 - Lot #'s: 397, 398		2015 John Deere 245G LC Tracked Excavator S/N: 1FF245GXLFE600773 C/W: Air Conditioner, Air Ride Seat, 10 ft 7 in
397	Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,230 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB Asset located in: Lake Worth, TX 2019 Cat 326F L Tracked Excavator S/N: CAT0326FLFBR20679		Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler 46 in Digging Bucket Usage: Not Available Asset located in: Humble, TX
		404	2012 Cat 324 EL Tracked Excavator S/N: CAT0324EPPNW00408 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION
398			Usage: 8,469 Hr Asset located in : Lake Worth, TX
		405	2012 Cat 324 EL Tracked Excavator S/N: CAT0324EHPNW00497 Usage: Not Available Asset located in: Lake Worth, TX
	Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,973 Hr Asset located in : Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 406, 407
399	2019 Cat 326F L Tracked Excavator S/N: CAT0326FEFBR20653 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 9,619 Hr Asset located in: Lake Worth, TX	406	2023 Cat 323 Tracked Excavator S/N: CAT00323ENDL20616 C/W: Air Conditioner, Straight Travel Pedal, Ride Seat, Control Pattern Changer, Rear & S View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaus Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-
400	2015 Cat 326FL Tracked Excavator S/N: CAT0326FVWGL00317 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel		CONSTRUCTION Usage: 240 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS Asset located in: Lake Worth, TX
	Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 54 in Digging Bucket Usage: 9,061 Hr Asset located in : Lake Worth, TX		2023 Cat 323 Tracked Excavator S/N: CAT00323LNDL20614 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side
401	2020 LiuGong 888925E Tracked Excavator S/N: 888925EZJLU004037 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket		View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 490 Hr
	Usage: 2,191 Hr		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS
402	Asset located in: Humble, TX 2016 John Deere 245G LC Tracked Excavator	\dashv	Asset located in: Lake Worth, TX
702	S/N: 1FF245GXJGF800123 C/W: with JRB coupler and bucket Usage: Not Available		
	Asset located in: Lake Worth, TX	1	

Lot #	Details	Lot #	Details
408	2023 Cat 323 Tracked Excavator S/N: CAT00323JNDL20736 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 866 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS Asset located in: Lake Worth, TX	412	2019 Cat 323 Tracked Excavator S/N: CAT00323ARAZ10687 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,393 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 409, 410	413	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10552 C/W: Air Conditioner, Straight Travel Pedal, Air
409	2022 Cat 323 Tracked Excavator S/N: CAT00323CNDL20262 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool		Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,527 Hr Asset located in: Lake Worth, TX
	Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 120 Hr Notes : EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS Asset located in : Lake Worth, TX		2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ11197 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust
410	2022 Cat 323 Tracked Excavator S/N: CAT00323CNDL20219 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Surround View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick,		Fluid, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,958 Hr Asset located in: Lake Worth, TX
	Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 34 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION	СНОІС	E OF 3 - Lot #'s: 415, 416, 417
	Usage: 156 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS Asset located in: Lake Worth, TX	S/N: CAT00323CRAZ1107 C/W: Air Conditioner, Strai Ride Seat, Control Pattern View Cameras, Pre-Wired 1 2019 US EPA Label, Requii Fluid, 9 ft 6 in Stick, Auxilia Plumbing, 32 in Triple Groi in Digging Bucket, Thumb Control; EQUIPMENT-FROI CONSTRUCTION Usage: 3,062 Hr	2019 Cat 323 Tracked Excavator S/N: CAT00323CRAZ11070 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side
411	2022 Cat 323 Tracked Excavator S/N: NDL20218 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 814 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS Asset located in: Lake Worth, TX		View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION

Lot #	Details	Lot #	Details
416	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10972 C/W: Air Conditioner, Straight Travel Pedal, Rear & Side View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.25 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,205 Hr Asset located in: Lake Worth, TX	421	2018 Cat 323 Tracked Excavator S/N: CAT00323HRAZ00227 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,498 Hr Asset located in: Lake Worth, TX
417	2019 Cat 323 Tracked Excavator S/N: CAT00323KRAZ11087 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,253 Hr Asset located in: Lake Worth, TX	422	2018 Cat 323 Tracked Excavator S/N: CAT00323JRAZ00303 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,641 Hr Asset located in: Lake Worth, TX
418	2019 Cat 323 Tracked Excavator S/N: RAZ10628 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 4,636 Hr Asset located in: Lake Worth, TX	423	2018 Cat 323 Tracked Excavator S/N: CAT00323PRAZ00282 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, Tier 4, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,757 Hr Asset located in: Lake Worth, TX
419	2018 Cat 323 Tracked Excavator S/N: CAT00323LRAZ00176 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, ; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,439 Hr Asset located in: Lake Worth, TX	424	2018 Cat 323 Tracked Excavator S/N: CAT00323ARAZ00290 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,808 Hr Asset located in: Lake Worth, TX
420	2018 Cat 323 Tracked Excavator S/N: CAT00323ERAZ00293 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,103 Hr Asset located in: Lake Worth, TX	425	2018 Cat 323 Tracked Excavator S/N: CAT00323KRAZ00266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,852 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
426	2018 Cat 323 Tracked Excavator S/N: CAT00323LRAZ00288 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,063 Hr Asset located in: Lake Worth, TX 2018 Cat 323 Tracked Excavator	432	2018 John Deere 210G LC Tracked Excavator S/N: 1FF210GXPJF526258 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 700 mm Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 5,427 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	S/N: CAT00323HRAZ01166 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 48 in Digging Bucket, Thumb Bracket Usage: 4,053 Hr Asset located in: Lake Worth, TX	433	2012 John Deere 210GLC Tracked Excavator S/N: 1FF210GXACE520458 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
428	2017 Cat 323F L Tracked Excavator S/N: CAT0323FTXCF10375 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View	434	2012 Hitachi ZX210LC-5N Tracked Excavator S/N: 1FFDCJ70TCE330100 Usage: 8,921 Hr Asset located in: Lake Worth, TX
	Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,557 Hr Asset located in: Lake Worth, TX	435	2017 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257CGTC80149 C/W: Air Conditioner, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 34 in Digging Bucket
429	2015 Cat 323FL Tracked Excavator S/N: CAT0323FCXCF00606		Usage: 15,090 Hr Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2014 US EPA Label, 10 ft Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 10,595 Hr Asset located in: Lake Worth, TX	436	2020 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257KKWA12903 C/W: Air Conditioner, Rear View Camera, 2019 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Breaker Usage: 5,171 Hr Asset located in: Lake Worth, TX
430	2022 John Deere 210GLC Tracked Excavator S/N: 1FF210GXENF529761 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, 9 ft 7 in Stick, 27.5 in Triple Grouser Track Shoes, 24 in Digging Bucket Usage: 2,416 Hr Asset located in: Lake Worth, TX		2013 Komatsu PC210LC-10 Tracked Excavator S/N: KMTPC243C02450042 C/W: Air Conditioner, Cab Screens, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, Auto Lube Usage: 14,738 Hr
CHOICE OF 2 - Lot #'s: 431, 432		420	Asset located in: Lake Worth, TX
431	2018 John Deere 210G LC Tracked Excavator S/N: 1FF210GXLJF526477 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 4,374 Hr Asset located in: Lake Worth, TX	438	2013 Komatsu PC210LC-10 Tracked Excavator S/N: KMTPC243H02450734 C/W: Air Conditioner, 2013 US EPA Label, 10 ft 2 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 8,296 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
439	2019 XCMG XE210U Tracked Excavator S/N: XUGA210BVKKA00083 C/W: Air Conditioner, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 1 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 23 in Digging Bucket Usage: 721 Hr Asset located in: Humble, TX	444	2020 Cat 320 Tracked Excavator S/N: CAT00320CHEX20219 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 42 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,582 Hr
440	2014 Cat 321D LCR Tracked Excavator S/N: CAT0321DLMPG01100 Usage: Not Available Asset located in: Lake Worth, TX		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
440A	2018 Hitachi ZX210LC-5N Tracked Excavator S/N: 1FFDCJ70JEE330489 Usage: Not Available	сноіс	E OF 2 - Lot #'s: 445, 446
	Asset located in: Lake Worth, TX	445	2020 Cat 320 Tracked Excavator
441	2022 Cat 320GC Tracked Excavator S/N: CAT00320HLKS20318 Usage: 1,073 Hr Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH DECEMBER 2025 OR 5,000 HOURS Asset located in: Lake Worth, TX		S/N: CAT00320KHEX20265 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Sid View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 3 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,321 Hr
CHOIC	CHOICE OF 3 - Lot #'s: 442, 443, 444		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
442	2020 Cat 320 Tracked Excavator	446	·
	S/N: CAT00320JHEX20266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 30 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,298 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2025 OR 3000 HOURS	446	2020 Cat 320 Tracked Excavator S/N: CAT00320AHEX20207 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,462 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
443	2020 Cat 320 Tracked Excavator S/N: CAT00320HHEX20212 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1 419 Hr	CHOIC	E OF 4 - Lot #'s: 447, 448, 449, 450 2019 Cat 320 Tracked Excavator S/N: CAT00320CHEX12081 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label,

S/N: CAT00320CHEX12081 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION

Usage: 1,445 Hr

Notes: EMISSIONS SYSTEM WARRANTY THROUGH FEBRUARY 2026 OR 3000 HOURS

Asset located in: Lake Worth, TX

Usage: 1,419 Hr

Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
448	2019 Cat 320 Tracked Excavator S/N: CAT00320VHEX11425 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for	СНОІС	E OF 2 - Lot #'s: 454, 455
	Grade Control, 2018 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,539 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	454	2014 Cat 320EL Tracked Excavator S/N: CAT0320EEWBK01967 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2012 US EPA Label, 9 ft 7 in Stick, 31 in Triple Grouser Track Shoes, 31 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 4,345 Hr
449	2019 Cat 320 Tracked Excavator	455	Asset located in: Lake Worth, TX 2014 Cat 320 EL Tracked Excavator
	S/N: HEX11857 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 1,702 Hr	433	S/N: CAT0320EAWBK02595 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,912 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	456	2014 Cat 320 EL Tracked Excavator
450	2019 Cat 320 Tracked Excavator S/N: CAT00320KHEX12604 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Cleanup Bucket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,129 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS		S/N: CAT0320ECWBK02652 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb Usage: 10,473 Hr Asset located in: Lake Worth, TX
		457	2014 Cat 320 EL Tracked Excavator S/N: CAT0320EPWBK02668 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US
	Asset located in: Lake Worth, TX		EPA Label, 8 ft 6 in Stick, 31 in Triple Grouser Track Shoes, Hydraulic Breaker
451	2019 Cat 320 Tracked Excavator S/N: CAT00320LHEX11329 C/W: Rear & Side View Cameras, 2018 US EPA		Usage: 18,583 Hr Asset located in: Lake Worth, TX
	Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 3,617 Hr Asset located in: Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 458, 459, 460
452	2018 Cat 320 Tracked Excavator	458	2013 Cat 320 EL Tracked Excavator
	S/N: CAT00320THEX01650 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 2,890 Hr Asset located in: Lake Worth, TX		S/N: CAT0320ELWBK01626 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,381 Hr
453	2017 Cat 320FL Tracked Excavator S/N: CAT0320FKYBM10403 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 9 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 27 in Cleanup Bucket Usage: 6,755 Hr Asset located in: Midland, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
459	2013 Cat 320 EL Tracked Excavator S/N: CAT0320EKREE00514 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,468 Hr Asset located in: Lake Worth, TX	465	2006 John Deere 200C LC Tracked Excavator S/N: FF200CX507611 C/W: Air Conditioner, Control Pattern Changer, Tier 2, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 800 mm Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 8,607 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.
460	2013 Cat 320 EL Tracked Excavator S/N: CAT0320EHWBK02230 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,019 Hr Asset located in: Lake Worth, TX		Asset located in: Lahoma, OK 2019 Cat 316FL Tracked Excavator S/N: CAT0316FKYDL21033 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 24 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 3,683 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 461, 462	467	2013 Cat 316E L Tracked Excavator S/N: CAT0316EJDZW00889 C/W: Air Conditioner, Straight Travel Pedal, Air
461	2012 Cat 320 EL Tracked Excavator S/N: CAT0320EKWBK00212 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 32 in Triple Craver Track Shape, 26 in Digging	468	Ride Seat, 2012 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 40 in Digging Bucket, Manual Thumb Usage: 14,360 Hr Asset located in : Lake Worth, TX
	in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,775 Hr Asset located in : Lake Worth, TX		2020 Cat 315FLCR Tracked Excavator S/N: CAT0315FJTDY14173 C/W: Air Conditioner, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft 6
462	2012 Cat 320E L Tracked Excavator S/N: CAT0320EJWBK00387 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Craver Track Shape, 36 in Digging	469	in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Boom Check Valves, 27.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 1,758 Hr Asset located in : St. Rose, LA
	in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 7,386 Hr Asset located in : Lake Worth, TX		S/N: YH08015117 C/W: Air Conditioner, Control Pattern Chang 2019 US EPA Label, Requires Diesel Exhaus
CHOIC	E OF 2 - Lot #'s: 463, 464		Fluid, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 2,068 Hr Asset located in : Baton Rouge, LA
463	2006 Komatsu PC200-LC-7 Tracked Excavator S/N: C50926 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX	470	2012 Kobelco SK140SRLC Tracked Excavator S/N: YH0608690 C/W: 2011 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, 31 in Digging Bucket Usage: 6,456 Hr
464	2006 Komatsu PC200LC-8 Tracked Excavator S/N: KMTPC180J54A88082 C/W: 2006 US EPA Label, 9 ft 8 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 17,098 Hr Asset located in: Lake Worth, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
471	2019 Cat 313F L GC Tracked Excavator S/N: CAT0313FEHDK10481 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, CARB Compliant, 10 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 19.5 in Digging Bucket Usage: 3,746 Hr Asset located in: Lake Worth, TX	478	2018 Sany SY135C Tracked Excavator S/N: SY013JBJL2718 C/W: Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 43 in Cleanup Bucket Usage: 5,357 Hr Asset located in: Lake Worth, TX
	Asset located III. Lake Worth, 17	− 478A	2017 Case CX130D Tracked Excavator
CHOIC 473	E OF 2 - Lot #'s: 473, 474 2019 Cat 313F L GC Tracked Excavator S/N: ZGS00152		S/N: DAC130K7NHS7D1310 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 34 in Digging Bucket, Manual Thumb Usage: 934 Hr
	C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras,		Asset located in: Lake Worth, TX
474	10 ft Stick, 27.5 in Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 2,826 Hr Asset located in: Lake Worth, TX 2019 Cat 313F L GC Roadbuilder Tracked	479	2004 Kobelco SK480LC Tracked Excavator S/N: YS06U0308 C/W: US EPA Label, 11 ft 6 in Stick, 36 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 15,245 Hr
4/4	Excavator		Asset located in: Lake Worth, TX
	S/N: ZGS00141 C/W: Air Conditioner, Rear & Side View Cameras, 2018 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,843 Hr Asset located in: Lake Worth, TX	480	1996 Cat 350L Tracked Excavator S/N: 3ML00899 C/W: Air Conditioner, Cab Screens, 10 ft Stick, 29.5 in Double Grouser Track Shoes, 46 in Digging Bucket, Catwalks, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 17,997 Hr Asset located in: Humble, TX
	7,000 100 atou iii. Lake Werdi, 17	480A	2004 Komatsu PC200 LC-7L Tracked Excavator
СНОІС 475	2019 Sany SY135C Tracked Excavator S/N: SY013JBJM3218 C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4		S/N: A86747 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 51 in Digging Bucket Usage: 11,171 Hr Asset located in: Lake Worth, TX
	in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 48 in Cleanup Bucket Usage: 6,558 Hr Asset located in: Lake Worth, TX	481	2001 Komatsu PC200 Tracked Excavator S/N: Not Available C/W: 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 96 in Cleanup Bucket
476	2019 Sany SY135C Tracked Excavator		Usage: Not Available
	S/N: SY013JBJL6958 C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 6,291 Hr Asset located in: Lake Worth, TX	482	Asset located in: Lake Worth, TX E OF 4 - Lot #'s: 482, 483, 484, 485 2019 Volvo ECR88D Tracked Excavator
477	2018 Sany SY135C Tracked Excavator S/N: SY013EBJL6208 C/W: Air Conditioner, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 4,154 Hr Asset located in: Lake Worth, TX		S/N: VCE00E88H00215346 C/W: Air Conditioner, Swing Boom, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,742 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
483	2019 Volvo ECR88D Tracked Excavator S/N: 215385 C/W: Air Conditioner, Tier 4, 2019 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, 22 in Digging Bucket, Hydraulic Thumb Usage: 2,972 Hr	CHOICI 490	CE OF 2 - Lot #'s: 490, 491 2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETMC500734 C/W: Air Conditioner, 2018 US EPA Label,
	Asset located in: Lake Worth, TX		CARB Compliant, 5 ft 5 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber
484	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88J00215338 C/W: Air Conditioner, 2019 US EPA Label,		Inserts, 38 in Digging Bucket Usage: 1,492 Hr Asset located in : Lake Worth, TX
	Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 901 Hr Asset located in: Lake Worth, TX	491	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308EVPC800527 C/W: Air Conditioner, 2018 US EPA Label, 5 ft 5 in Stick, Backfill Blader, 18 in Triple Grouser
485	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88H00215332		Track Shoes w/Rubber Inserts, 28 in Digging Bucket Usage: 1,694 Hr Asset located in : Lake Worth, TX
	C/W: Air Conditioner, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Boom Check Valves, Backfill Blade, 17.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,792 Hr		E OF 4 - Lot #'s: 492, 493, 494, 495
	Asset located in: Lake Worth, TX	492	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELFJX10405
486	2021 Bobcat E85 Tracked Excavator S/N: B48414957 C/W: 2020 US EPA Label, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, 24 in Digging Bucket, Thumb Bracket Usage: 1,865 Hr		C/W: Air Ride Seat, Rear View Camera, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.75 in Triple Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,681 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	 493	
CHOIC	CHOICE OF 2 - Lot #'s: 488, 489		2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELFJX07584 C/W: Air Conditioner, Air Ride Seat, 2016 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, 35.5 in Digging Bucket, Hydraulic Thumb Usage: 3,891 Hr Asset located in: Lake Worth, TX
	Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber	494	2017 Cat 308E2 CR Tracked Excavator
	Inserts, 22 in Digging Bucket, Manual Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,546 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2027 OR 3000 HOURS Asset located in: Lake Worth, TX	774	S/N: CAT0308ETFJX07574 C/W: Air Conditioner, 2016 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 4,033 Hr
489	2021 Cat 308 CR Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT00308VGG803324 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, Tier 4, 2020 US EPA Label, Swing Boom, 6 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Track Shoes w/Rubber Inserts, 21 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,093 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	495	2017 Cat 308E2 CR Roadbuilder Tracked Excavator S/N: CAT0308EEFJX08253 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Single Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb, Strickland ZX85 MK2 Hydraulic Thumb Usage: 4,117 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
сноіс	E OF 2 - Lot #'s: 496, 497		E OF 15 - Lot #'s: 501, 502, 503, 504, 505, 506, 507 19, 510, 511, 512, 513, 514, 515
496	2015 Cat 308E2 CR Tracked Excavator S/N: CAT0308EKFJX02698 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,281 Hr Asset located in: Lake Worth, TX	501	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55HPAJAL584 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
497	2014 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETFJX00852 C/W: Air Conditioner, Control Pattern Changer, 2013 US EPA Label, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Double Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,625 Hr Asset located in: Lake Worth, TX	502	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55PPAJAL520 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
498	2014 Cat 308E2 CR Mini Excavator S/N: CAT0308ELFJX00151 C/W: Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, 36 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Lake Worth, TX	503	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55PPAJAL422 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr
499	2020 John Deere 75G Tracked Excavator S/N: 1FF075GXTKJ017240 C/W: 2019 US EPA Label, 6 ft 11 in Stick,		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Track Shoes w/Rubber Pads, 30 in Bucket Usage: 2,121 Hr Asset located in : Lake Worth, TX	504	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55EPAJAL456 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Backfill
500	2021 Bobcat E60R2 Mini Excavator S/N: B4GR11148 C/W: Enclosed Cab, Air Conditioner, 2020 US EPA Label, Swing Boom, 6 ft 4 in Stick, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,271 Hr		Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	505	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55JPAJAL786 C/W: Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE
			DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
506		511	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55LPAJAL848 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	512	2023 Yanmar ViO55-6A Mini Excavator
507	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55KPAJAL429 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr		S/N: YMRVIO55VPAJAL846 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS	513	2023 Yanmar ViO55-6A Mini Excavator
	Asset located in: Lake Worth, TX		S/N: YMRVI055EPAJAL702
508	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55APAJAL461 C/W: 2023 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr		C/W: 2023 US EPA Label, Swing Boom, 5 ft 6 i Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Notes : WARRANTY AVAILABLE - SEE DOCUMENTS	514	2023 Yanmar ViO55-6A Mini Excavator
	Asset located in: Lake Worth, TX		S/N: YMRVIO55LPAJAL454
509	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55KPAJAL415 C/W: US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS		C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 15.5 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	515	2023 Yanmar VIO55-6A Mini Excavator
510	2023 Yanmar VIO55 Yanmar ViO 55 Mini Excavator S/N: YMRVIO55KPAJAK958 C/W: 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO55HPAJAL553 C/W: 2016 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 17 in Rubber Tracks, Hydraulic Quick Coupler, Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 3 - Lot #'s: 516, 517, 518	CHOIC 532, 53	E OF 10 - Lot #'s: 525, 526, 527, 528, 529, 530, 531 33, 534
516	2019 Cat 305.5E2 Mini Excavator S/N: CAT3055EPWE209294 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 5 ft Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 863 Hr Asset located in: Lake Worth, TX	525	2023 Yanmar VIO35-6A Mini Excavator S/N: YMRVIO35APAJAT785 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE
517	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055EVWE205445		DOCUMENTS Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 5 ft Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 792 Hr Asset located in: Lake Worth, TX	526	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35APAJAT947 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket,
518	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055ETWE204417 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 4 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.75 in Triple Grouser Track Shoes, Manual Quick		Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX
	Coupler, 28 in Digging Bucket Usage: 910 Hr Asset located in: Lake Worth, TX	527	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35JPAJAT581 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
518A	2018 Cat 305E2 CR Mini Excavator S/N: CAT0305EPH5M06269 C/W: Swing Boom, 5 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, 18 in Digging Bucket		
	Usage: 3,912 Hr Asset located in: Lake Worth, TX	528	2023 Yanmar VIO35 Mini Excavator
520	2019 Sany SY50U Mini Excavator S/N: SY005CBJZ2158 C/W: Enclosed Cab, Swing Boom, 4 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 18 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX	528	S/N: YMRVIO35HPAJAT989 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
522	2017 John Deere 50G Mini Excavator S/N: 1FF050GXCGH285257 C/W: Control Pattern Changer, 2016 US EPA Label, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 4,712 Hr Asset located in: Lake Worth, TX		2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35LPAJAT772 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE
523	2016 John Deere 50G Mini Excavator S/N: 1FF050GXPGH284631 C/W: Control Pattern Changer, 2016 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 19 in Digging Bucket, Thumb Bracket Usage: 6,107 Hr Asset located in: Lake Worth, TX		DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
530	2023 Yanmar VIO35-6A Mini Excavator S/N: YMRVIO35VPAJAT865 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr		
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO35LPAJAU087 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: Not Available
531	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35VAPJAT722 C/W: 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Bucket, Hýdraulic Thumb Usage: Not Available Notes : WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in : Lake Worth, TX	536	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35EPAJAT671 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks,
532	32 2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35KPAJAT868 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb	Hydraulic Quick Coupler, 24 in Digging Bu Hydraulic Thumb Usage: 2 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in : Lake Worth, TX	Hýdraulic Thumb Usage: 2 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS
	Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	537	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35VPAJAT851 C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber
533	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35LPAJAT232 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	S/N: YMRVIO35CPAJAT808 C/W: Swing Boom, 4 ft 6 in Stick, Back	C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick
534			Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	539	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35VPAJAU322 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
540	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35JPAJAT970 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS	546	2021 John Deere 35G Mini Excavator S/N: 1FF035GXLLK291536 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 10 in Digging Bucket Usage: 1,292 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	_сноіс	E OF 4 - Lot #'s: 547, 548, 549, 550
541	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35TPAJAT700 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	547	2021 John Deere 35G Mini Excavator S/N: 1FF035GXVMK293316 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 18 in Bucket Usage: 466 Hr Asset located in: Lake Worth, TX
	<u> </u>	548	2021 John Deere 35G Mini Excavator
542	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35PPAJAT794 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr	040	S/N: 1FF035GXCMK292861 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 729 Hr
	Notes: WARRANTY AVAILABLE - SEE		Asset located in: Lake Worth, TX
543	DOCUMENTS Asset located in: Lake Worth, TX 2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35LPAJAS623 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb	549	S/N: 1FF035GXVMK292537 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 11.5 in Rubber Tracks,
			Manual Quick Coupler, 24 in Digging Bucket Usage: 922 Hr Asset located in : Lake Worth, TX
	Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX	550	2021 John Deere 35G Mini Excavator S/N: 1FF035GXCMK292536 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 12 in Bucket Usage: 1,134 Hr Asset located in: Lake Worth, TX
544	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35APAJAT625 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		
	Usage: 3 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS	сноіс	E OF 2 - Lot #'s: 551, 9623C
	Asset located in: Lake Worth, TX	551	2017 John Deere 35G Mini Excavator
545	Yanmar V1035-5B Mini Excavator S/N: YMRVI035J8YY53169 C/W: 2008 US EPA Label, Swing Boom, 4 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket, Thumb Bracket Usage: 7,897 Hr		S/N: 1FF035GXEHK279948 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
553 554	2007 John Deere 35D Mini Excavator S/N: FF035DX237345 C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket Usage: 8,759 Hr Asset located in: Lake Worth, TX 2016 Bobcat E35I Mini Excavator S/N: AUYM13355	560	2015 Cat 303E CR Mini Excavator S/N: CAT0303EAHHM01212 C/W: Control Pattern Changer, Tier 4, 2015 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX 2018 Case CX37C Mini Excavator (Inoperable) S/N: NSUC37CRNZLN55583 C/W: 2017 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket
	C/W: Enclosed Cab, Control Pattern Changer, Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket Usage: 2,462 Hr Asset located in: Midland, TX		
555	2012 Komatsu PC35MR Mini Excavator S/N: KMTPC201C04018745 C/W: 2012 US EPA Label, Swing Boom, 5 ft 6 in Stick, Backfill Blade, 12 in Track Shoes w /Rubber Pads, 24 in Cleanup Bucket, Hydraulic Thumb		Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	562	2006 Komatsu PC27MR-2 Mini Excavator S/N: 16215 Usage: Not Available
556	Hitachi ZX35U-5N Mini Excavator S/N: HCMADG60E00273351		Asset located in: Lake Worth, TX
	C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 6,514 Hr Asset located in: Humble, TX	563	2017 Bobcat E26 Mini Excavator S/N: B3JE13055 C/W: Swing Boom, 3 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 2,327 Hr Asset located in: Lake Worth, TX
558	2018 Cat 303E CR Mini Excavator S/N: CAT0303EAHHM02733 C/W: Tier 4, 2017 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket, Thumb Bracket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 590 Hr Asset located in: Lake Worth, TX	564	2017 Takeuchi TB260 Mini Excavator S/N: 126102065 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Thumb Bracket, EQUIPMENT FROM UNITED RENTALS Usage: 3,025 Hr Asset located in: Lake Worth, TX
CHOIC	CHOICE OF 2 - Lot #'s: 559, 560		2021 Bobcat E20 Mini Excavator S/N: B3BL19286 C/W: Control Pattern Changer, 2021 US EPA
559	2016 Cat 303E CR Mini Excavator S/N: CAT0303EVHHM01984 C/W: Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,021 Hr Asset located in: Lake Worth, TX		Label, Swing Boom, 4 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 753 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 4 - Lot #'s: 566, 567, 568, 569	572	2004 Cat M318C Wheel Excavator S/N: CATM318CPBCZ00846 C/W: 2 Piece Hyd. Boom, 9 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Front and Rear
566	2022 John Deere 17G Mini Excavator S/N: 1FF017GXJNK232661 C/W: Control Pattern Changer, 2022 US EPA Label, Swing Boom, 3 ft Stick, Auxiliary		Stabilizers, 10.00x20 Tires, 78 in Hydraulic Tilting Bucket Usage: Not Available Asset located in : Lake Worth, TX
	Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 401 Hr Asset located in : Lake Worth, TX	573	Gradall XL3300 Wheel Excavator S/N: 0210017540 C/W: Backfill Blade, Stabilizers, 60 in Cleanup Bucket, Additional 30 in Digging Bucket Usage: 2,899 Hr
567	2021 John Deere 17G Mini Excavator S/N: 1FF017GXPMK231345		Asset located in: Lake Worth, TX
	C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Bucket Usage: 467 Hr Asset located in: Lake Worth, TX	574	Crane S/N: 36250 C/W: Anti Two-Block, PAT DS160 Load Moment Indicator, 2002 US EPA Label, 29 ft Minimum 71 ft Maximum Boom Length, Rooster Sheave, Overhaul Ball, Counterweight Removal System, 30 in Triple Grouser Track
568	2021 John Deere 17G Mini Excavator S/N: 1FF017GXLMK231337 C/W: Control Pattern Changer, 2021 US EPA		Shoes, Expandable Width Tracks Usage: 7,472 Hr Asset located in: Humble, TX
	Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 473 Hr Asset located in: Lake Worth, TX	575	2011 Link-Belt HTC8675 75 ton 8x4 Series II Hydraulic Truck Crane S/N: 1F9P9K221CL028751 C/W: Air Conditioner, 13310 hrs Carrier Engine Cat C13 8 Cylinder Diesel Carrier Engine, Air
569	2021 John Deere 17G Mini Excavator S/N: 1FF017GXTMK231117 C/W: Control Pattern Changer, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Manual Quick Coupler, 12 in Digging Bucket Usage: 479 Hr		Conditioner, Anti Two-Block, Hirschmann Load Moment Indicator, 34 ft Minimum 113 ft Maximum Boom Length, Rooster Sheave, Bifold Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 356 lb Overhaul Ball, 18400 lb Counterweight, Counterweight Removal System Usage: 1,190 Mi
569A	Asset located in: Lake Worth, TX 2018 Yanmar SV08-1B Mini Excavator		Notes: NO TITLE AVAILABLE, SOLD WITH BI OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	S/N: YMRSV08YEJBJBF106 C/W: 2017 US EPA Label, Swing Boom, 2 ft 3 in		Asset located in: Lake Worth, TX
	Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Expandable Width Tracks, 14 in Digging Bucket Usage: 1,259 Hr Asset located in : Lake Worth, TX	576	2001 Link-Belt RTC-8075 70 ton 4x4x4 Rough Terrain Crane S/N: D7J1-5709LB C/W: Air Conditioner, Anti Two-Block, Microguard 534 Load Moment Indicator, 4994
571	JCB HD110W Wheel Excavator S/N: JCBW11CFEN3148944 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9-20 Tires, Steelwrist X12 650-650 GR FPL Tiltrotator Attachment Usage: 202 Hr Asset located in: Lake Worth, TX		hrs Crane Operation, Cummins 6 Cylinder 215 hp 8.3 L Diesel Engine, 41 ft Minimum 127 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 39.5 ft to 67 ft Bifold Swingaway Offset Jib, 1502 lb 65 ton Capacity Johnson 5 Sheave Hook Block, Overhaul Ball, 15000 lb Counterweight, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 4,994 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
577 577A	2008 Link-Belt RTC-8065 Rough Terrain Crane S/N: J8J815707 C/W: EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 11,117 Hr Asset located in: Humble, TX 2008 Link-Belt 8065 65 ton 4x4x4 Rough Terrain Crane S/N: J9J80231 C/W: Air Conditioner, Anti Two-Block, Link Belt	581	2008 Link-Belt RTC 8050 II 50 ton 4x4x4 Rough Terrain Crane S/N: J6J8-9992 C/W: Microguard 534 Load Moment Indicator, 12354 hrs Crane Operation, Cummins B5.9C 6 Cylinder 173 hp 5.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 33 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Bifold Swingaway Offset Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, Overhaul Ball
	MicroGuard 534 Load Moment Indicator,		Usage: 12,353 Hr
	11140 hrs Crane Operation, Cat C6.6 Acert 6 Cylinder 6.6 L Diesel Engine, 38 ft Minimum		Asset located in: Humble, TX
	115 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 35 ft to 58 ft Bifold Swingaway Offset Jib, 1154 lb 70 ton Capacity Johnson 5 Sheave Hook Block, 347 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 11,225 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED	582	2011 Grove RT600E 50 ton 4x4x4 Rough Terrain Crane S/N: 231622 C/W: Air Conditioner, Anti Two-Block, PAT iFlex5 Load Moment Indicator, 11660 hrs Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball
	Asset located in: Humble, TX	_	Usage: 11,660 Hr Asset located in: Humble, TX
578	2001 Link-Belt RTC-8065 65 ton 4x4x4 Rough Terrain Crane S/N: D7J1-5707 C/W: Air Conditioner, Anti Two-Block, Link Belt MicroGuard 534 Load Moment Indicator, 6824 hrs Crane Operation, Cummins C8.3C 6 Cylinder 215 hp 8.3 L Diesel Engine, 38 ft Minimum 115 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 36.5 ft to 61 ft Bifold Swingaway Offset Jib, 1103 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 350 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 6,828 Hr	583	2009 Grove RT600E 50 ton 4x4x4 Rough Terrain Crane S/N: 229898 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, 10124 hrs Crane Operation, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, Overhaul Ball Usage: 10,124 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	584	1998 Grove RT880 Rough Terrain Crane S/N: 87272
579	2012 Grove RT765E-2 65 ton 4x4x4 Rough		Usage: Not Available
	Terrain Crane S/N: 232495		Asset located in: Hot Springs, AR
	C/W: Air Conditioner, Anti Two-Block, Hirschmann iScout Load Moment Indicator, 7421 hrs Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 240 hp 6.7 L Diesel Engine, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 56 ft Bifold Swingaway Offset Jib, 1252 lb 66 ton Capacity Johnson 5 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball, Counterweight Removal System Usage: 7,421 Hr	585	1996 Grove RT528C 28 ton 4x4x4 Rough Terrain Crane S/N: 83337 C/W: Anti Two-Block, PAT DS 350 GW Load Moment Indicator, Cummins cbd126 6 Cylinder 128 hp Diesel Engine, 28 ft Minimum 70 ft Maximum Boom Length, 566 lb 30 ton Capacity McKissick 3 Sheave Hook Block Usage: 511 Hr Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	585A	P & H Century II 22 ton 4x4 Rough Terrain
580	2006 Grove RT760E Rough Terrain Crane S/N: 226196 Usage: Not Available Asset located in: Humble, TX		Crane S/N: 32R1032 C/W: Anti Two-Block, PAT Load Moment Indicator, 8653 hrs Crane Operation, Detroit 4087-7100 V8 Diesel Engine, 29 ft Minimum 72 ft Maximum Boom Length, Swingaway Jib, Overhaul Ball Usage: Not Available Asset located in: Midland, TX

Arreto E1324STK-4MS Walk Behind ET K202 121 US EPA Label, Honda GX390 1 T Gasoline Engine, Hydrostatic Drive, 5 x 24 in Long Combination Trencher T in Rubber Tracks 303 Hr Ocated in: Lake Worth, TX
tch Witch RT36 4x4 Trencher MWRT36XJ70000141 eutz Diesel Engine, Hydrostatic Drive, 6 x 5 ft 6 in Long Combination Trencher Angle Blade 1,182 Hr ocated in: Lake Worth, TX
narles Machine Works 3700DD 4x4 er 0864 anopy, Diesel Engine, 5 in Wide x 87 in rt Trencher Chain, A322 Backhoe
nent, Straight Blade 1,924 Hr o cated in : Lake Worth, TX
tch Witch RT155H 4x4 Trencher MWRT115E70000255 Anopy, US EPA Label, John Deere 4 R 82 kW 4.5 L Diesel Engine, Hydrostatic D in Wide x 80 in Long Dirt Trencher Crumbling Shoe 452 Hr Decated in: Lake Worth, TX
ermeer V120 4x4 Trencher
S/N: 1VRT1124411000207 C/W: Canopy, Hydrostatic Drive, 6 in Wide x 9 t 3 in Long Dirt Trencher Chain, Straight Blade Usage: 2,431 Hr Asset located in : Lake Worth, TX
tch Witch RT45 4x4 Trencher
MWRT45XEF0002812 eutz Diesel Engine, Hydrostatic Drive, 6 x 64 in Long Rock Trencher Chain, Blade, Side Shift 996 Hr pcated in: Lake Worth, TX
ermeer RTX450 Trencher
R4092U0J1003787 Not Available ocated in: Lake Worth, TX

Lot #	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 599, 600	605	1978 (unverified) Cleveland H320 Tracked Bucket Wheel Trencher S/N: 325300
599	2014 Vermeer T755III Tracked Trencher S/N: 1VR2160RXE1000550 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Cat C9 6 Cylinder 746 hp 8.8 L Diesel Engine, 16 in Wide x 11 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab Usage: 2,792 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Cat D330 4 Cylinder Diesel Engine, Manual Transmission, 27 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
600	2012 Vermeer T755III Tracked Trencher	Сноіс	E OF 2 - Lot #'s: 606, 607
	S/N: 1VR2160R3C1000516 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C9 375 hp Diesel Engine, 12 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,066 Hr Asset located in: Lake Worth, TX	606	1974 Cleveland S320 Tracked Bucket Wheel Trencher S/N: K427 C/W: Canopy, Diesel Engine, Manual Transmission, 26 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available
601	2007 Vermeer T755III Tracked Trencher S/N: 1VR2190S371000123 C/W: Enclosed Cab, Air Conditioner, 2007 US EPA Label, Cat C9 6 Cylinder 480 hp 8.8 L	607	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	Diesel Engine, 16 in Wide x 12 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab Usage: 5,025 Hr Asset located in: Lake Worth, TX		1969 Cleveland 320 Tracked Bucket Wheel Trencher S/N: K414 C/W: Enclosed Cab, Cat D333 6 Cylinder Diese Engine, Manual Transmission, 25.5 in
602	2009 Tesmec TRS975 Tracked Trencher S/N: 975-111 C/W: Enclosed Cab, Air Conditioner, Cat C9DI 6 Cylinder 300 hp Diesel Engine, Hydrostatic Drive, 23 in Wide x 186 in Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Single Grouser Track Shoes		Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK
	Usage: 4,256 Hr	608	1962 Cleveland 320 Trencher
603	Asset located in: Midland, TX 2000 Tesmec 1075 Tracked Trencher S/N: 15211 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Hydrostatic Drive, 24 in Trenching Width, 160 in Trenching Depth,		S/N: K364 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK
	Discharge Conveyor, Side Shift, Hydraulic Leveling, 22 in Single Grouser Track Shoes Usage: 185 Hr Asset located in : Midland, TX	сноіс	E OF 2 - Lot #'s: 609, 610
604	1997 Trencor 960HD Tracked Trencher S/N: 136 C/W: Enclosed Cab, Air Conditioner, 6 Cylinder Engine, Trencor Cable Plow, 26 in Trenching Width, 84 in Trenching Depth, Discharge Conveyor, 24 in Triple Grouser Track Shoes Usage: 5,333 Hr Asset located in: Lake Worth, TX	609	1959 (unverified) Cleveland 320 Tracked Bucket Wheel Trencher S/N: K328 C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, Manual Transmission, 21 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.

Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
S/N: 3514110 C/W: Canopy, Cat 330 Diesel Engine, Manual Trenching Width, Disc Single Grouser Track S Usage: Not Available	C/W: Canopy, Cat 3304 4 Cylinder 165 hp Diesel Engine, Manual Transmission, 42 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	614	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XLE0002319 C/W: 2004 US EPA Label, Deutz D2011 3 Cylinder 42 hp 2.33 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 3 in Long Dirt Trencher Chain Usage: 2,034 Hr Asset located in: Lake Worth, TX	
610A	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	615	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XHE0002029 C/W: US EPA Label, Deutz 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 5 in Long Dirt Trencher Chain, Straight Blade Usage: 989 Hr	
	Tracked Bucket Wheel Trencher S/N: K280 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 42 in Trenching Width, 84 in Trenching Depth, 18 in Single Grouser Track Shoes Usage: Not Available Asset located in: Oklahoma City, OK	616	Asset located in: Lake Worth, TX 2011 Ditch Witch RT45 4x4 Trencher Cable Plow S/N: CMWRT45XJC0001226 C/W: Canopy, 2011 US EPA Label, Deutz d2011 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, Ditch Witch 5 ft 6 in Cable Plow, 6 in Wide x 5 ft 6 in Long Dirt Trencher	
610B	Tracked Bucket Wheel Trencher S/N: K364 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching	617	Chain Usage: 2,614 Hr Asset located in : Lake Worth, TX	
	Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Asset located in : Oklahoma City, OK		2014 Ditch Witch RT45 4x4 Trencher Cable Plow S/N: CMWRT45XLE0002028 C/W: Canopy, 2011 US EPA Label, CARB	
610C	Cleveland 350S Tracked Bucket Wheel Trencher S/N: 3512290 C/W: Canopy, Cat 3304PC 4 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available		Compliant, Deutz D2011L03 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 5 ft 4 in Cable Plow, 6 in Wide x 6 ft 4 in Long Combination Trencher Chain, Discharge Conveyor, H314 Traversing Trencher Attachment s/n: CMWH314XCD0002861 Usage: 2,993 Hr Asset located in: Lake Worth, TX	
611	Asset located in: Oklahoma City, OK 1957 Cleveland 320 Trencher S/N: K280	618	S/N: 1VRB360W5G1000135 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Drill Rod Loading	C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Drill Rod Loading
	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.		System 8 Drill Rods, 18 in Triple Grouser Track Shoes Usage: 4,790 Hr Asset located in : Lake Worth, TX	
612	Asset located in: Lahoma, OK Cleveland 320 Trencher S/N: K285 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	619	2019 Vermeer D23x30III Directional Drill S/N: 1VRN20074K1001288 C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Drill Rod Loading System 22 Drill Rods, 12 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX	
613	1979 Cleveland 350S Trencher S/N: 3512290 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	620	2017 Vermeer 20X22III Directional Drill S/N: 1VRA170V3H1000764 C/W: 2016 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, Drill Rod Loading System 31 Drill Rods, 11 in Rubber Tracks Usage: 2,859 Hr Asset located in: Lake Worth, TX	

			Page 51 of 567		
Lot #	Details	Lot #	Details		
621	2019 Ditch Witch JT20 Directional Drill S/N: DWPJT20BAK0000234 C/W: Open Operator Station, 2019 US EPA Label, Deutz 4 Cylinder Diesel Engine, Drill Rod Loading System 39 Drill Rods, 11 in Rubber Tracks Usage: 3,005 Hr Asset located in: Lake Worth, TX	627	2015 Vermeer Vac-tron T/A Vacuum Excavation Unit S/N: 5HZBF1929FLCF2113 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Rear Hose Reel, 200 gal Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, 235/85R16 Tires, 14000 lb GVWR, 2014 US EPA Label, CARB Compliant, Yanmar 4TNV88C-DYEM 4 Cylinder 2.2 L Diesel Engine		
622	2017 Ditch Witch JT20 Directional Drill w/2016		Usage: Not Available		
	Felling FT24 Trailer S/N: CMWJT20XKH0000950		Asset located in: Lake Worth, TX		
	C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, 30 Drill Rods, 11 in Rubber Tracks, T/A Trailer w/ S/N-	сноіс	E OF 2 - Lot #'s: 628, 9628A		
	5FTEE2923G1003458, Lunette Ring, Electric Brakes, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	628	2017 LOKT T/A Vacuum Excavation Unit S/N: 4M9E2TG23HE015031 C/W: Lunette Ring Hitch, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Drop Down Tailgate, Engine Driven Pump, 215/75R17.5		
СНОІС	E OF 2 - Lot #'s: 624, 625		Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available		
624	2020 Vermeer LP573XDT T/A Vacuum		Asset located in: Lake Worth, TX		
	Excavation Unit S/N: 5HZJ16231LK002166 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 2020 Vermeer LP573XDT Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Wash Down System, 3 in Suction Hose, Vac-Tron Engine Driven Pump, Vac-Tron 200257 Blower, Remote Control w/ Cord, 235/80R16 Tires, 12000 lb GVWR, 2019 US EPA Label, CARB Compliant, Kohler KKHXL1.37SF1 3 Cylinder 23.4 hp 1.02 L Diesel Engine Usage: Not Available Asset located in: Midland, TX	630	630	Excavation Unit S/N: 1DST522N2N1701879 C/W: Spring Suspension, Ele Debris Tank, 500 gal Fresh V Hydraulic Lift Tailgate, Hydra Locks, Blower, 235/80R16 T Label, Vanguard NBSXS.993 hp 896 cc Gasoline Engine Usage: 162 Hr Notes: DEFICIENCIES NOTE THE INSPECTION REPORT; S REPOSESSION AFFIDAVIT A	S/N: 1DST522N2N1701879 C/W: Spring Suspension, Electric Brakes, Steel Debris Tank, 500 gal Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Blower, 235/80R16 Tires, 2022 US EPA Label, Vanguard NBSXS.9932VB 2 Cylinder 31 hp 896 cc Gasoline Engine Usage: 162 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE
625	2020 Vermeer Lp573xdt T/A Vacuum Excavation Unit S/N: 5HZJ16235LK002140 C/W: Aluminum Frame, Lunette Ring Hitch,			ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	2019 VERMEER Debris Tank, Fresh Water Tank, 235/80R16 Tires, 1200 lb GVWR, 2019 US EPA Label, Kohler 8 kW Diesel Engine Usage: 475 Hr Asset located in: Lake Worth, TX		2011 Ditch Witch FX30 800 gal T/A Vacuum Excavation Unit S/N: 1DSB202S5B1702339 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Rear Hose		
CHOIC	E OF 2 - Lot #'s: 626, 627		Reel, 800 gal Fresh Water Tank, Manual Tailgate Locks, 8 ft Telescopic Boom, 4 in		

626 2016 Vermeer T/A Vacuum Excavation Unit

S/N: 5HZBF1924GLBG2112 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Steel Debris Tank, Rear Hose Reel, 200 gal Fresh Water Tank, Hydraulic Lift Tailgate, 235/85R16 Tires, Kohler 3 Cylinder 1.02 L

Diesel Engine Usage: 2,634 Hr

Asset located in: Lake Worth, TX

Tailgate Locks, 8 ft Telescopic Boom, 4 in Suction Hose, Engine Driven Pump, 215/75R17. 5 Tires, 18000 lb GVWR, Kubota D1105-T 3 Cylinder 1.1 L Diesel Engine Usage: 2,095 Hr

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
632	2011 Vermeer VX50500 Vacuum Excavation Unit S/N: 1M9FE122XBS284256 C/W: Ball Hitch, Spring Suspension, Electric Brakes, McLaughlin Mfg Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Engine Driven Pump, 235/80R16 Tires, 12000.0 lb GVWR, 3 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	638	2020 Screen Machine 621ST Tracked Trommel Screen S/N: 621ST1603 C/W: 5 ft 8 in x 14 ft 6 in Belt Feeder w/Grizzly Trommel Screen, 42 in Wide Feed Conveyor, 42 in Wide Under Screen Conveyor, 41 in Wide Left Discharge Conveyor, Cat 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 15.75 in Triple Grouser Track Shoes Usage: 307 Hr Asset located in: Lake Worth, TX
633	Vermeer Air 573 SDT Vacuum System S/N: 181403 C/W: Torsion Axle, Electric Brakes, Vermeer Air573SDT Steel Debris Tank, Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Wash Down System, 3.5 in Suction Hose, Aanovi reverberi Engine Driven Pump, Vactron 59URAI Blower, Remote Control w/ Cord, 235/80R16 Tires, 20000 lb GVWR, 4 Cylinder Diesel Engine, Vermeer Vactron System, 4 Cylinder Diesel, Control Panel w/ Display, Rear Lift Door, Rear Hydraulic Hose Reels, Poly Water Tanks; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 316 Hr Asset located in: Lake Worth, TX	640	2020 Terex/Finlay 883 Tracked Screen Plant S/N: TRX883M4CDGLB3827 C/W: 8 ft 7 in x 16 ft Apron Feeder 16 ft x 5 ft Double Deck Screen, 35 in Wide Fines Discharge Conveyor, 47 in Wide Under Screen Conveyor, 31 in Wide Left Discharge Conveyor, 2020 US EPA Label, Cat C4.4 4 Cylinder 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Hydraulic Leveling, 15.75 in Triple Grouser Track Shoes Usage: 1,040 Hr Asset located in: Lake Worth, TX 2009 McCloskey 621RE Screen Plant S/N: 11915 Usage: Not Available
634	2000 Vermeer Vac-tron Vacuum Excavation Unit S/N: 1A9AF152XYF495615 C/W: Lunette Ring Hitch, Spring Suspension, Steel Debris Tank, Fresh Water Tank, Full Open Tailgate, Manual Tailgate Locks, 235/85R16 Tires, Kohler 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	Conveyor (Unused) S/N: M202409548 C/W: Lattice Frame, Folding End Se Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOTE FOR ILLUSTRATION PURPOSES ON MAY NOT BE AN EXACT REPRESED THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 642 2024 Vickwest PRS36-60 Portable Conveyor (Unused) S/N: M202409547 C/W: Lattice Frame, Folding End Se Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOTE FOR ILLUSTRATION PURPOSES ON	E OF 4 - Lot #'s: 641, 642, 643, 644 2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409548
635	1998 Nordberg LTC1416 Tracked Impact Crusher Plant S/N: 1291 C/W: Vibratory Pan Feeder 48 in Wide Under Crusher Conveyor, Radio Remote Control, 1997 US EPA Label, Cat 3406 6 Cylinder 328 kW Diesel Engine, 21.75 in Triple Grouser Track Shoes Usage: 2,847 Hr Notes: THIS UNIT MOVES ON ITS OWN WHEN IDLED UP. LOADING ASSISTANCE UNAVAILABLE ON THIS ITEM. BUYER WILL NEED TO SET UP OUTSIDE ASSISTANCE. Asset located in: Lake Worth, TX		Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409547 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available
636	2012 Powerscreen XH250 Impact Crusher S/N: PIDXH250A0MC55102 C/W: Terex 7 ft Belt Feeder Terex CR004 Jaw Crusher, 2012 US EPA Label, Cat 6.6 L Diesel Engine, 16 in Triple Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
637	2023 Ark K-JC503 Jaw Crusher S/N: 323878 C/W: 1 ft 4 in x 6 ft 6 in Belt Feeder 12 in Rubber Tracks Usage: 186 Hr Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
643	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409550 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	Bomag MPH364R-2 Wheel Soil Stabilizer Reclaimer S/N: Not Available C/W: Canopy, 2013 US EPA Label, 84 in Combination Rotor, 14 in Cutting Depth, Water /Emulsion Application System Usage: 3,562 Hr Asset located in: Poteau, OK	
		652	2021 Vogele S2100-31 Track Asphalt Paver S/N: 08192375
644	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409549 C/W: Lattice Frame, Folding End Section,		C/W: Canopy, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in - 9 ft 8 in Screed, 12 in Rubber Tracks Usage: 2,345 Hr Asset located in : Humble, TX
	Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	653	2011 Cat AP1055E Asphalt Paver S/N: TJF00111 Usage: 17,076 Hr Asset located in: Lake Worth, TX
6.45	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	654	Cat BG-260C Wheel Asphalt Paver S/N: CATBG260C8GN00575 Usage: Not Available
645	JCT Separator Magnet (Unused) S/N: Not Available Usage: Not Available		Asset located in: Lake Worth, TX
646	Asset located in: Lake Worth, TX 2012 Klein KPT-120 12000 gal S/A Water	655	2005 Cat AP-655C Track Asphalt Paver S/N: CATAP655PAYP00240 C/W: Dual Controls, Carlson Electric Heated 8 ft - 13 ft 6 in Screed, 16 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX
	Tower S/N: 40797 C/W: Hydraulic Raise, Gasoline Engine Driven Hydraulic Power Pack, 12 in Downspout, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available		
		СНОІС	E OF 2 - Lot #'s: 656, 657
	Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	656	2001 Cat AP-650B Track Asphalt Paver S/N: 9DN00434
648	2020 RoadHog RH60250 60" Wheel Loader Cold Planer Attachment S/N: 2009026 C/W: Cat C7.1, 250hp, Diesel, Diesel Exhaust Fluid, Q/C, Side Shift, 80 Gallon Water Tank		C/W: Fume Extractor, Cat 7MRO2145, 8-16B Diesel Heated 8 ft 4 in - 15 ft 8 in Screed, 13.5 in Single Grouser Track Shoes w/Rubber Inserts Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 37 Hr Asset located in : Lake Worth, TX	657	2000 Cat AP-650B Track Asphalt Paver S/N: 9DN00414
649	2018 Bomag RS460 Wheel Soil Stabilizer Reclaimer S/N: 101590161008		C/W: 8 ft 4 in - Screed, 14 in Track Shoes w /Rubber Inserts Usage: 6,827 Hr Asset located in : Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires AdBlue, 96 in Rotor, Water /Emulsion Application System, 19.7 in Cutting Depth Usage: 1,584 Hr Asset located in: Baytown, TX	658	Roadtec RP195 Track Asphalt Paver S/N: 10950808 C/W: Dual Controls, Carlson Electric Heated 10 ft - 19 ft Screed, 18 in Rubber Tracks Usage: Not Available
650	2016 Cat RM300 Wheel Soil Stabilizer Reclaimer S/N: CATRM300HBWR00791 C/W: Canopy, 96 in Soil Rotor, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: 4,284 Hr Asset located in: Humble, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
659	2007 Mauldin 1750C Track Asphalt Paver S/N: 879G75TJS6Y201879 C/W: Dual Controls, Propane Heated 7 ft 6 in - 16 ft Screed, 12 in Track Shoes w/Rubber Pads Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	667	2008 (unverified) Valmet 430FXL Track Feller Buncher S/N: AT4K-2992-052108 C/W: Air Conditioner, Hydraulic Tilting Cab, US EPA Label, Quadco OFH 22 in Feller Buncher, 27.5 in Single Grouser Track Shoes, Rock Guards Usage: 969 Hr Asset located in: St. Rose, LA
660	Mauldin 690G Track Asphalt Paver S/N: 459Q69TKS8Y203459 C/W: Dual Controls, Propane Heated 8 ft 1 in - 13 ft 3 in Screed, 12 in Rubber Tracks Usage: 934 Hr Asset located in: Lake Worth, TX	668	2014 John Deere 648H 4x4 Skidder S/N: 1DW648HXKED658603 C/W: Air Conditioner, Air Ride Seat, Sweeps, Screens, Blade, John Deere Grapple, Single Arch, John Deere Single Drum Winch, 30.5L32 Tires, Floatation Tires
661	1982 Blaw-Knox RW100 Road Widener S/N: 956003		Usage: 9,491 Hr Asset located in : Lake Worth, TX
	C/W: Open Operator Station, John Deere Engine, Automatic Transmission, 10 " Spreader Width, Truck Hitch, Open Operator Station, Dual Controls, John Deere 4 Cylinder Diesel Engine, Hydrostatic Drive, - 10 ft Spreading Width, Truck Hitch, 20 in Conveyor	669	2003 Cat 525B 4x4 Line Skidder S/N: CAT0525BK3KZ00929 C/W: Air Conditioner, Blade, Single Arch, cat Single Drum Winch, 30.5x32 Tires Usage: Not Available
	Usage: 430 Hr Asset located in: Poteau, OK		Asset located in: Lake Worth, TX
662	1995 Etnyre K Series Chip Spreader S/N: K5706 C/W: Open Operator Station, Diesel Engine, 11 ft - Spreader Usage: Not Available Asset located in: Lake Worth, TX	—670	2013 John Deere 2954D Log Loader S/N: 1FF2954DED0290150 C/W: Air Conditioner, Air Ride Seat, Cab Screens, Hydraulic Tilting Cab, 31.5 in Triple Grouser Track Shoes, Rock Guards, ROTOBEC Log Grapple Usage: 9,719 Hr
663	2016 Crafco 125D Asphalt Kettle		Asset located in: Lake Worth, TX
	S/N: 1C9SV1221G1418015 C/W: 125 gal Capacity Tank, Diesel Fired Heater, Hydraulic Agitator, Hydraulic Driven Pump, Hose & Wand, Air Compressor, T/A Trailer Mounted Usage: 554 Hr Asset located in: Lake Worth, TX	671	Finn T-30 Hydroseeder S/N: RUA730 C/W: Ball Hitch, Spring Suspension, ST8-14.5 Tires, Aluminum Tank, Gasoline Powered Pump, T/A Utility Trailer Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL
664	Etnyre 2000 gal on 2002 GMC C7500 4x2		OF SALE ONLY ; Asset located in: Lake Worth, TX
	Asphalt Distributor Truck S/N: 1GDM7H1C82J513848 C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 hp Engine, 2002 US EPA Label, 5-Speed Manual Transmission, 11000 lb Front Axle, 22000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 13 ft 2 in Folding Spray Bar, Diesel Burners, In-Cab Controls		2011 Barko 930B 4x4 Mulcher Tractor S/N: 11293023740 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Fecon Mulcher, Winch Usage: 5,000 Hr Asset located in: Lake Worth, TX
	Usage: 50,865 Mi	674	Demco Model HP 60 ft T/A Pull-Type Sprayer
665	Asset located in: Lake Worth, TX 2016 Cimline 410 Magma Pothole Patcher S/N: 1G9441622GM119018 C/W: Isuzu 3cj1 4 Cylinder .99 L Diesel Engine, 225/75R15, Spring Suspension, Diesel Heating System Usage: 1,838 Hr Asset located in: Lake Worth, TX		S/N: Not Available C/W: 540 PTO, ISOBUS, PTO Driven Pump, 500 gal Poly Tank, Chemical Mix Tank, Rinse Tank, Single Nozzle Bodies, Fence Row Nozzles, 11l- 15, Hydraulic Fold Booms, Guidance and Auto Steer Ready, Section Control, 29 In. Ground Clearance, Dual Agitators, Front Tank Walkway Usage: Not Available Notes: PERSONAL SPRAYER FOR LONGTIME CUSTOMER - FULLY OPERATIONAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICI	E OF 2 - Lot #'s: 675, 676	681	2019 Morooka MST2200VD Crawler Carrier S/N: A2202124 C/W: Enclosed Cab, Air Conditioner, Rear View
675	2023 Bell TC7A Crawler Carrier S/N: AEBK607AA01000128 C/W: Enclosed Cab, Air Conditioner, Rear View		Camera, 2018 US EPA Label, Cat 6 Cylinder Diesel Engine, 29.5 in Rubber Tracks, 9 ft Wide x 12 ft 9 in Long Flatbed Usage: 2,393 Hr
	Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High Flatbed Dump Body, 27 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 30 Hr	СНОІС	Asset located in: Baytown, TX E OF 2 - Lot #'s: 682, 683
	Asset located in: Lake Worth, TX	692	2015 Morooka MST-2200VD Crawler Carrier
676	2022 Bell TC7A Crawler Carrier S/N: AEBK607AC01000118 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High Flatbed Dump Body, 27 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 26 Hr	- 682	S/N: A220291 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 13 ft Long x 0 ft High Swivel Dump Body, 30 in Rubber Tracks, Bed Dump Cylinders; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 679 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
CHOICI	E OF 3 - Lot #'s: 677, 678, 679 2018 Terramac RT-14 Crawler Carrier	-683	2015 Morooka MST-2200VD Crawler Carrier S/N: A220247 C/W: Enclosed Cab, Air Conditioner, 13 ft Long Flatbed Dump Body, 30 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,659 Hr
	S/N: 14G0060 C/W: Enclosed Cab, Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13 ft 6 in Long x 2 ft High Flatbed Dump Body, 31 in Rubber Tracks, Stake Sides; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,183 Hr		Asset located in: Lake Worth, TX
		СНОІС	E OF 3 - Lot #'s: 684, 685, 686
		684	2014 Morooka MST-2200VD Crawler Carrier
678	Asset located in: Lake Worth, TX 2017 Terramac RT-14 Crawler Carrier S/N: 14C0040 C/W: 13 ft 6 in Long x 2 ft High Dump Body, 32 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION		EPA Label, Cat C7 6 Cylinder 7.2 L Dies Engine, 30 in Rubber Tracks, 9 ft 2 in W ft 4 in Long Flatbed Usage: 4,082 Hr
	Usage: 1,912 Hr Asset located in: Lake Worth, TX		BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
679	2017 Terramac RT-14 Crawler Carrier		Asset located in: Louisville, MS
	S/N: 14C0036 C/W: Enclosed Cab, Air Conditioner, 13 ft 6 in Long Flatbed Dump Body, 32 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,703 Hr Asset located in: Lake Worth, TX	685	2011 Morooka MST-2200VD Crawler Carrier S/N: 223442 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C7 6 Cylinder 7.2 L Diesel Engine, 30 in Rubber Tracks, 13 ft 4 in Long Flatbed Dump Body Usage: 6,040 Hr
CHOICE OF 2 - Lot #'s: 680, 681			Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
680	2019 Morooka MST2200VD Crawler Dumper		Asset located in: Louisville, MS
	S/N: A2202131 C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive Usage: 2,294 Hr Asset located in : Baytown, TX	686	2013 Morooka MST-2200VD Crawler Carrier S/N: 223553 Usage: 2,407 Hr Asset located in: Louisville, MS

Lot #	Details	Lot #	Details
CHOICI	CHOICE OF 2 - Lot #'s: 687, 688		IHI IC45-2 Crawler Carrier Digger Derrick S/N: CE000842 C/W: Enclosed Cab, Tier 2, 2018 US EPA Label,
687	2019 Morooka MST1500VD Crawler Carrier S/N: A1505075 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Cat C 7.1 Diesel Engine, Requires Diesel Exhaust Fluid, 27 in Rubber Tracks, 10 ft 5 in Long Flatbed Dump Body Usage: 864 Hr Asset located in: Beaumont, TX		Mitsubishi 6 Cylinder Diesel Engine, 44 ft Sheave Height, 26250 lb Capacity, Rear Mounted, 33 ft Reach, Insulated Upper Boom 18 in Auger, Pole Guide, Auxiliary Hydraulics, Turret Mounted Winch, One-Man Basket, 10 f 0 in Body, X-Type Outriggers, Rear Outriggers Bumper Mounted Winch, Hydraulic Hose Ree 24 in Rubber Tracks Usage: 3,193 Hr
688	2019 Morooka MST1500VD Crawler Carrier S/N: A1505077		BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Cat C 7.1 Diesel Engine, Requires		Asset located in: Louisville, MS
	Diesel Exhaust Fluid, 27.5 in Rubber Tracks, 10 ft 5 in Long Flatbed Dump Body Usage: 1,005 Hr Asset located in: Beaumont, TX	695	IHI IC45-2 Crawler Carrier Aerial Lift w/2001 Terex HI-Ranger HR46M S/N: CE000831 C/W: Canopy, 2007 US EPA Label, Mitsubishi S6S-DTDP 6 Cylinder 99 hp 5.0 L Diesel Engine,
690	2019 Morooka MST1000VD Crawler Carrier S/N: A1001007 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Diesel Engine, Requires Diesel Exhaust Fluid, 23.5 in Rubber Tracks, 10 ft Long Flatbed Dump Body Usage: 1,115 Hr		26250 lb Capacity, Rear Mounted, One-Person Articulated Boom, Flatbed, Turret Mounted Winch, X-Type Outriggers, Rear Outriggers, Bumper Mounted Winch, Hydraulic Hose Reel, 24 in Rubber Tracks Usage: 2,407 Hr Notes: ITEMS AT OFFSITE LOCATION MUST
691	Asset located in: Beaumont, TX Morooka MST1500 Crawler Carrier	_	BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
051	S/N: 151791 C/W: Canopy, 9 ft 10 in Long Flatbed Dump Body, 26 in Rubber Tracks, Lincoln 300D Welder w/ Leads; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 8,681 Hr	606	Asset located in: Louisville, MS
		696	2018 Cat 272D2 XHP Skid Steer Loader S/N: CAT0272DTMD200939 Usage: Not Available
			Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	697A	2016 Cat 272D2 Two-Speed High Flow XPS Skid Steer Loader
CHOICI	E OF 2 - Lot #'s: 692, 693 2018 Canycom S25A Crawler Carrier		S/N: CAT0272DABL200550 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket
092	S/N: 9161386		Usage: 6,097 Hr Asset located in : Lake Worth, TX
	C/W: Canopy, US EPA Label, Kubota V2203-M-ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 1 ft 2 in High Dump Body Usage: 194 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	697B	2016 Cat 272D2 Two-Speed Skid Steer Loader S/N: CAT0272DLBL200551 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket Usage: 6,474 Hr Asset located in: Lake Worth, TX
602	Asset located in: Louisville, MS 2018 Capycom S25A Crawler Carrier	698A	2014 Cat 272D Two-Speed Skid Steer Loader
693	2018 Canycom S25A Crawler Carrier S/N: 9161385 C/W: Canopy, US EPA Label, Kubota V2203-M- ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 2 ft 2 in High Dump Body Usage: 1,799 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS		S/N: CAT0272DHB5W00695 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 9 Pin Electric Kit, Manual Coupler, 72 in Bucket Usage: 6,717 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
699	2021 Bobcat S66 Two-Speed Skid Steer Loader S/N: B4SA12489 C/W: Open Operator Station, Joystick Steering, Manual Coupler Usage: 985 Hr Asset located in: Lake Worth, TX	707	2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BHTNK01905 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 73 in Bucket Usage: 11,292 Hr Asset located in: Lake Worth, TX
700	2015 Bobcat S630 Skid Steer Loader S/N: AHGL11719 C/W: Open Operator Station, 2014 US EPA Label, Manual Coupler, 66 in Bucket Usage: 9,891 Hr	708	Gehl R165 Skid Steer Loader S/N: GHL0R165E00197514 C/W: Open Operator Station, 2015 US EPA Label, Manual Coupler Usage: 2,245 Hr
701	Asset located in: Lake Worth, TX 2019 Cat 262D Skid Steer Loader S/N: CAT0262DKDTB09532 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Tier 4, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 1,988 Hr Asset located in: Lake Worth, TX	709	Asset located in: Lake Worth, TX 2014 Cat 246D Skid Steer Loader S/N: CAT0246DHBYF01000 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2014 US EPA Label, 9 Pin Electric Kit, Electric Coupler, 68 in Bucket Usage: 6,328 Hr Asset located in: Lake Worth, TX
CHOIC 702	E OF 4 - Lot #'s: 702, 703, 704, 705 2020 Bobcat S570 Skid Steer Loader S/N: ALM429836 C/W: Open Operator Station, Creep Mode, Joystick Steering, Control Pattern Changer,	710	2021 John Deere 318G Skid Steer Loader S/N: 1T0318GKCMJ407875 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2021 US EPA Label, Aperture Tires, 9 Pin Electric Kit, Hydraulic Coupler, Counterweight Kit Usage: 1,521 Hr
	Self Leveling, 2019 US EPA Label, Aperture Tires, Manual Coupler, 74 in Bucket Usage: 932 Hr Asset located in : Lake Worth, TX		Asset located in: Lake Worth, TX 2020 Cat 242D3 Two-Speed Skid Steer Loads S/N: CAT0242DAHSX00818
703	2020 Bobcat S570 Skid Steer Loader S/N: ALM429810 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 67 in Bucket Usage: 1,237 Hr		C/W: Open Operator Station, Joystick Steering, Tier 4, 2019 US EPA Label, Manual Coupler, 74 in Bucket Usage: 2,764 Hr Asset located in: Lake Worth, TX
704	Asset located in: Lake Worth, TX 2020 Bobcat S570 Skid Steer Loader	-сноіс	E OF 3 - Lot #'s: 712, 713, 714
704	S/N: ALM429670 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 66 in Bucket Usage: 1,759 Hr Asset located in: Lake Worth, TX 2017 Bobcat S570 Skid Steer Loader	712	2014 Cat 242D Two-Speed Skid Steer Loader S/N: CAT0242DTDZT00301 C/W: Tier 4, 2013 US EPA Label, CARB Compliant, Manual Coupler, 68 in Bucket Usage: Not Available Asset located in: Midland, TX
	S/N: ALM418117 C/W: Open Operator Station, 2017 US EPA Label, Manual Coupler, 66 in Bucket Usage: 751 Hr Asset located in : Lake Worth, TX	713 201 S/N C/W Seat	2015 Cat 242D Skid Steer Loader S/N: CAT0242DEDZT01204 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Tier 4, 2014 US EPA Label, CARB Compliant,
CHOICE OF 2 - Lot #'s: 706, 707			Hydraulic Coupler, 74 in Bucket Usage: Not Available Asset located in : Midland, TX
706	2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BCTNK01891 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket Usage: 13,461 Hr Asset located in: Lake Worth, TX	714	2014 Cat 242D Skid Steer Loader S/N: CAT0242DJDZT00366 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Tier 4, 2013 US EPA Label, CARB Compliant, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
715	2016 Kubota SSV65 Skid Steer Loader S/N: JKUS0651L01S12051 Usage: Not Available Asset located in: Lake Worth, TX	725	2019 Cat 299D2XHP Two-Speed High Flow Compact Track Loader S/N: CAT0299DEDX204437 C/W: Enclosed Cab, Air Conditioner, Air Ride
717	2021 Bobcat S510 Skid Steer Loader S/N: B4RE11047 C/W: EQUIPMENT FROM UNITED RENTALS Usage: 1,258 Hr Asset located in: Lake Worth, TX		Seat, Ride Control, Joystick Steering, Rear View Camera, 15 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 2,589 Hr Asset located in : Lake Worth, TX
718	2012 Bobcat S150 Skid Steer Loader S/N: A3L485751 Usage: Not Available Asset located in: Lake Worth, TX	726	E OF 2 - Lot #'s: 726, 727 2019 Cat 299D2 Two-Speed Compact Track
719	2015 Gehl V270 Two-Speed Skid Steer Loader S/N: GHL00270H00023697 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Manual Coupler, 79 in Bucket Usage: 1,653 Hr Asset located in: Lake Worth, TX		Loader S/N: CAT0299DCFD205903 C/W: Enclosed Cab, Air Ride Seat, Joystick Steering, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 78 in Bucket Usage: 2,224 Hr Asset located in: Lake Worth, TX
720	2006 Bobcat S205 Skid Steer Loader S/N: 530512291 C/W: Open Operator Station, Tier 2, 2006 US EPA Label, Aperture Tires, Manual Coupler, 66 in Grapple Bucket, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 2,830 Hr Asset located in: Lake Worth, TX	727	2019 Cat 299D2 Two-Speed Compact Track Loader S/N: CAT0299DHFD205803 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 80 in Bucket
721	Case 1845C Skid Steer Loader S/N: 4810330		Usage: 2,733 Hr Asset located in : Lake Worth, TX
	C/W: Enclosed Cab, Manual Coupler, 73 in Bucket Usage: 335 Hr Asset located in : Lake Worth, TX	727A	2020 Takeuchi TL12V2 Two-Speed High Flow Compact Track Loader S/N: 412002791 C/W: Enclosed Cab, Control Pattern Changer,
CHOICE OF 2 - Lot #'s: 722, 723			Rear View Camera, 17.5 in Track Belts, 14 P Electric Kit, Hydraulic Coupler, 79 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMEN Usage: 1,813 Hr
722	2020 Cat 299D3 Two-Speed Compact Track		Asset located in: Lake Worth, TX
	Loader S/N: CAT0299DADY902326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Rear View Camera, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 3,301 Hr Asset located in: Lake Worth, TX	728	2017 Takeuchi TL12R2-CR Compact Track Loader S/N: 412100427 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Coupler, 81 in Bucket Usage: 1,197 Hr Notes: ADDITIONAL INFORMATION
723	2020 Cat 299D3 Compact Track Loader S/N: 0DY901742 Usage: 3,515 Hr		AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	728A 	2020 Cat 289D3 Compact Track Loader S/N: CAT0289DCJX903131 C/W: Enclosed Cab. Air Conditioner, Joystick
724	2019 Cat 299D3XE Two-Speed Compact Track Loader S/N: CAT0299DCBX901368 C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, 17 in Track Belts, Manual Coupler Usage: 2,412 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 18 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 5,426 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICE 729	CHOICE OF 2 - Lot #'s: 729, 9634A 729 2014 Cat 289D Compact Track Loader S/N: TAW01012 C/W: Enclosed Cab (Door missing), Air		2022 Bobcat T76 Compact Track Loader S/N: B4CE17367 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, Manual Coupler, 79 in Bucket Usage: 2,765 Hr Asset located in: Lake Worth, TX
	Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Self Leveling, Tier 4, 2014 US EPA Label, CARB Compliant, 18 in Track Belts, Hydraulic Coupler, 74 in Bucket, Counterweight Kit Usage: Not Available Asset located in: Midland, TX	736	2020 Bobcat T76 R-Series Compact Track Loader S/N: B4CE11296 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2019 US EPA Label, 12.5 in Track Belts, Manual Coupler, 80 in Bucket
731	2020 Cat 279D3 Compact Track Loader S/N: CAT0279DTRB901084 C/W: Enclosed Cab, Air Conditioner, Air Ride		Usage: 1,481 Hr Asset located in : Lake Worth, TX
	Seat, Joystick Steering, Rear View Camera, Tier 4, 2019 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler, 86 in Bucket, Counterweight Kit Usage: 2,944 Hr Asset located in : Beaumont, TX	Manual Coupler, 76 in Bucket Usage: 4,848 Hr	S/N: ATF614726 C/W: Open Operator Station, 18 in Track Belts, Manual Coupler, 76 in Bucket
731A		738	2012 Bobcat T750 Compact Track Loader S/N: ANKA12005 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Manual Coupler Usage: 4,888 Hr Asset located in: Lake Worth, TX
	EQUIPMENT Usage: 3,269 Hr Asset located in: Lake Worth, TX	738A	2011 Bobcat T750 Compact Track Loader S/N: ANKA11840 Usage: Not Available Asset located in: Lake Worth, TX
732	2017 Bobcat T770 Compact Track Loader S/N: AT6314655 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 66 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,422 Hr	739	2019 Bobcat T740 Two-Speed Compact Track Loader S/N: B3CA15269 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Hydraulic Coupler, 78 in Bucket Usage: 3,052 Hr Asset located in: Lake Worth, TX
733	Asset located in: Lake Worth, TX 2016 Bobcat T770 Compact Track Loader S/N: AT6312284 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 17.5 in Track Belts, 7 Pin Electric Kit, Manual Coupler, 80 in Bucket		2022 John Deere 333G Compact Track Loader S/N: 1T0333GMCNF420256 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Hydraulic Coupler, 83 in Bucket Usage: 726 Hr Asset located in: Lake Worth, TX
	Usage: 3,647 Hr Asset located in: Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 741, 742, 743
CHOICE 734	2022 Bobcat T76 Compact Track Loader S/N: B4CE19605 C/W: Open Operator Station, Joystick Steering, 2021 US EPA Label, Manual Coupler, 72 in Bucket Usage: 1,897 Hr Asset located in: Lake Worth, TX	741	2016 John Deere 329E Compact Track Loader S/N: 1T0329EKHGE294140 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Control Pattern Changer, 17 in Track Belts, Manual Coupler, 83 in Bucket Usage: 2,760 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
742	2014 John Deere 329E Compact Track Loader S/N: 1T0329EMCEE255596 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 17.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 3,794 Hr Asset located in: Lake Worth, TX	749	2017 Kubota SVL95-2SHF Compact Track Loader S/N: JKU00953001S34806 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler Usage: 4,389 Hr Asset located in: Lake Worth, TX
743	2021 John Deere 325G Two-Speed Compact	750	Kubota SVL95-2S Compact Track Loader
743	Track Loader S/N: 1T0325GKEMJ407899 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, 15.5 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, Counterweight	750	S/N: 1024968 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 70 in Bucket Usage: 1,813 Hr
	Kit Usage: 1,692 Hr		Asset located in: Lake Worth, TX
743A	Asset located in: Lake Worth, TX Case TV380 Two-Speed Compact Track Loader S/N: JAFTV380AJM452078 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available	751	2012 Kubota SVL90 Compact Track Loader S/N: 1003128 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2011 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler Usage: 1,052 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	752	2023 Kubota SVL75-3 Compact Track Loader
744	2015 Case TV380 Compact Track Loader S/N: JAFTV380HEM482982 C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, Manual Coupler, 86 in Bucket Usage: Not Available		S/N: KBCZ053CTP1E12118 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manual Coupler Usage: 388 Hr Asset located in : Humble, TX
	Asset located in: Lake Worth, TX	753	2022 Kubota SVL75-2 Two-Speed Compact
 CHOICE OF 2 - Lot #'s: 745, 746 745 2020 Kubota SVL95-2S Compact Track Loader S/N: KBCZ063CJL1F51637 C/W: Enclosed Cab, Air Conditioner, Joystick 			Track Loader S/N: 66119 C/W: Open Operator Station, Joystick Steering, 12.5 in Track Belts, Manual Coupler, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 677 Hr Asset located in: Lake Worth, TX
	Steering, US EPA Label, 17 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 1,986 Hr	754	2020 Kubota SVL75 Compact Track Loader S/N: KBCC0953PK1E47374
746	Asset located in: Lake Worth, TX 2019 Kubota SVL95-2HFC Compact Track Loader S/N: KBCC0953LK1E47027 C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, 9 Pin Electric Kit,		C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: 318 Hr Asset located in: Midland, TX
	Hydraulic Coupler Usage: 1,501 Hr Asset located in : Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 756, 757, 758
748	2017 Kubota SVL95-2S Two-Speed Compact Track Loader S/N: JKUC0953L01S34123 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler Usage: 2,023 Hr Asset located in: Lake Worth, TX	756	2019 Kubota SVL75-2 Compact Track Loader S/N: KBCC0752TK1J46403 C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, Manual Coupler, 72 in Bucket Usage: 1,718 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
757	2019 Kubota SVL75-2 Compact Track Loader S/N: KBCC0752VK1J46375 C/W: Open Operator Station, Joystick Steering, 13 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,369 Hr Asset located in: Lake Worth, TX	765	2021 Bobcat T64 R-Series Compact Track Loader S/N: B4SD12149 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in Bucket	
758	2018 Kubota SVL75-2 Compact Track Loader S/N: JKUC0752L01S38233 C/W: Open Operator Station, Joystick Steering,		Usage: 1,494 Hr Asset located in: Lake Worth, TX	
	15.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,370 Hr Asset located in : Lake Worth, TX	CHOICE OF 2 - Lot #'s: 766, 767		
759	2017 Kubota SVL75-2 Compact Track Loader S/N: 29876 Usage: Not Available Asset located in: Lake Worth, TX	766	2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506CPUM01235 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts,	
760	2021 Wacker Neuson ST45 LF CTL Vert Compact Track Loader S/N: WNCS0606TPUM00800		Hydraulic Coupler, 76 in Bucket Usage: 513 Hr Asset located in : Humble, TX	
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Control Pattern Changer, 2023 US EPA Label, 16.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 1,666 Hr Asset located in: Lake Worth, TX	767	2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506HPUM01189 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts, Manual Coupler Usage: 491 Hr	
761	2018 Wacker Neuson ST45 Compact Track Loader S/N: WNCS0404PPUM01126 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 2018 US EPA Label, 18 in Track Belts, Manual Coupler, 66 in Bucket Usage: 499 Hr		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
		768	2019 Case TR310 Compact Track Loader S/N: JAFTR310JJM450180 Usage: Not Available Asset located in: Lake Worth, TX	
762	Asset located in: Lake Worth, TX 2019 LiuGong 388B Compact Track Loader S/N: LGZ388BZCKZ010679 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Coupler, 82 in Bucket Usage: 4,737 Hr Asset located in: Lake Worth, TX	769	2018 Case TR310 Compact Track Loader S/N: JAFTR310VJM449341 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 76 in Bucket Usage: 3,253 Hr Asset located in: Lake Worth, TX	
CHOIC	E OF 3 - Lot #'s: 763, 764, 765	сноіс	E OF 2 - Lot #'s: 771, 9635A	
763	2021 Bobcat T64 Compact Track Loader S/N: B4SD13020 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,018 Hr Asset located in: Lake Worth, TX	771	2019 Bobcat T590 Compact Track Loader S/N: ALJU31295 C/W: Open Operator Station, 2019 US EPA Label, CARB Compliant, 13 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,490 Hr Asset located in: Lake Worth, TX	
764	2021 Bobcat T64 Compact Track Loader S/N: B4SD12133 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,051 Hr Asset located in: Lake Worth, TX		Accel located III. Lake Worth, TA	

Lot #	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 772, 773		780 2022 ASV RT-135 Two-Speed Compact T Loader S/N: ASVRT135ANDS00237	
772	2017 Bobcat T590 Compact Track Loader S/N: ALJU23267 C/W: Open Operator Station, 2017 US EPA Label, 12.5 in Track Belts, Manual Coupler, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,715 Hr Asset located in: Oklahoma City, OK	СНОІС	C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, 17 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, 80 in Bucket Usage: 460 Hr Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 781, 782, 783
773	2017 Bobcat T590 Compact Track Loader S/N: ALJU23698 C/W: Open Operator Station, Joystick Steering, 2017 US EPA Label, 12 in Track Belts, Manual Coupler, 57 in Bucket, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,084 Hr Asset located in: Lake Worth, TX	781	2021 Cat 259D3 Two-Speed Compact Track Loader S/N: CAT0259DECW912426 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 1,011 Hr Asset located in: Lake Worth, TX
	E OF 1 - Lot #'s: 775	782	2021 Cat 259D3 Compact Track Loader S/N: CAT0259DJCW914734 C/W: Open Operator Station, Joystick Steering,
775	2015 Bobcat T590 Compact Track Loader S/N: ALJU14338 C/W: Open Operator Station, 2014 US EPA Label, 12.5 in Track Belts, Manual Coupler Usage: 3,479 Hr		Rear View Camera, Tier 4, 2021 US EPA Label, 12 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,523 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	783	2021 Cat 259D3 Two-Speed Compact Track
776	2019 Bobcat T550 Compact Track Loader S/N: AJZV23563 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, Forks Usage: Not Available Asset located in: Lake Worth, TX		Loader S/N: CAT0259DCCW907770 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2020 US EPA Label, 16 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,817 Hr
777	2024 Takeuchi TL10V2 Compact Track Loader	<u> </u>	Asset located in: Lake Worth, TX
	S/N: 410007722 Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	784	2018 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DLFTL16672 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 13 in Track Belts, Manual Coupler Usage: 3,619 Hr Asset located in: Lake Worth, TX
778	2019 Takeuchi TL10V2 Compact Track Loader	CHOIC	E OE 2 - Lat #a: 795 796 797
	S/N: 410002668 C/W: Open Operator Station, Joystick Steering, Tier 4, 2019 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,355 Hr Asset located in: Lake Worth, TX	S/N: CAT0259DLFTL C/W: Open Operator Tier 4, 2021 US EPA Manual Coupler, 74 i Usage: 7,140 Hr	2017 Cat 259D Compact Track Loader S/N: CAT0259DLFTL12430 C/W: Open Operator Station, Joystick Steering, Tier 4, 2021 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in Bucket
779	2017 Takeuchi TL10V2R Compact Track Loader S/N: 410000884 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
786	2016 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DLFTL07339 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Self Leveling, Tier 4, 2022 US EPA Label, CARB Compliant, 12.5 in Track Belts, Manual Coupler, 75 in Bucket Usage: 6,778 Hr Asset located in: Lake Worth, TX	CHOICI 800 793	
787	2016 Cat 259D Two-Speed Compact Track Loader		Usage: 675 Hr Asset located in : Lake Worth, TX
	S/N: CAT0259DEFTL08493 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, 16 in Track Belts, Manual Coupler, 79 in Bucket Usage: 4,493 Hr Asset located in: Lake Worth, TX	794	2020 Bobcat T450 Compact Track Loader S/N: AUVP16950 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 802 Hr
788	2012 Cat 259B3 Two-Speed Compact Track		Asset located in: Lake Worth, TX
	Loader S/N: CAT0259BCYYZ02661 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 66 in Bucket Usage: 3,600 Hr Asset located in: Lake Worth, TX	795	2020 Bobcat T450 Compact Track Loader S/N: AUVP16939 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 910 Hr Asset located in: Lake Worth, TX
789	2011 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BPYYZ00856 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 12.5 in Track Belts, Manual Coupler, 72 in Bucket Usage: 4,736 Hr Asset located in: Lake Worth, TX	796	2020 Bobcat T450 Compact Track Loader S/N: AUVP17085 C/W: Open Operator Station, Joystick Steering, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 1,387 Hr Asset located in: Lake Worth, TX
790	2018 Takeuchi TL8 Two-Speed Compact Track Loader S/N: 200806258 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 12.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler Usage: 2,652 Hr	797	2019 Bobcat T450 Compact Track Loader S/N: AUVP15801 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 571 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	798	2019 Bobcat T450 Compact Track Loader
791	2012 Takeuchi TL230 Compact Track Loader S/N: 223101077 Usage: Not Available Asset located in: Lake Worth, TX		S/N: AUVP16910 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 73 in Bucket Usage: 636 Hr Asset located in : Lake Worth, TX
792	2020 Gehl RT165 Compact Track Loader S/N: GHLRT165GOD302276 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, Manual Coupler Usage: 397 Hr Asset located in: Lake Worth, TX	799	2019 Bobcat T450 Compact Track Loader S/N: AUVP15804 C/W: Open Operator Station, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 772 Hr Asset located in: Lake Worth, TX
		800	2019 Bobcat T450 All-Wheel Steer Compact Track Loader S/N: AUVP16039 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 954 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
801	2009 Bobcat T180 Compact Track Loader S/N: A3LL30017 C/W: Open Operator Station, 2008 US EPA Label, 12.5 in Track Belts, Manual Coupler, 67 in Bucket Usage: 3,840 Hr Asset located in: Lake Worth, TX	807 808 CHOIC	7 1979 John Deere 4440 2WD Tractor S/N: 025940R C/W: Enclosed Cab, Air Ride Seat, Differentia Lock, 16 Forward 6 Reverse, Quad Range, Fr Weights, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, 38x11 Front Tires, 18.4x38 Rear Tires, EQUIPMENT-FROM-WATKINS- CONSTRUCTION
802	2003 Cat 277 Compact Track Loader S/N: CAT00277LCNC02031 C/W: Open Operator Station, Joystick Steering, 18 in Track Belts, Manual Coupler, 79 in Bucket Usage: 6,389 Hr		Usage: 966 Hr Notes: JERRY WATKINS PERSONAL RANCH TRACTOR Asset located in: Lake Worth, TX 1983 John Deere 4450 2WD Tractor
802A	Asset located in: Lake Worth, TX John Deere 5203 2WD Utility Tractor S/N: PY5203U004017 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, SyncReverser, 2005 US EPA Label, 540 PTO, 3-Point Hitch, Drawbar, 7.50-16 Front Tires, 14.9x28 Rear Tires Usage: 119 Hr Asset located in: Lake Worth, TX		S/N: RW4450P005964 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 15 Forward 4 Reverse, Front Weights, 3 Rear Remotes, 540 PTO, Drawbar, 14L16.1-10 Front Tires, 20.8x38 Rear Tires Usage: 753 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
803	2010 John Deere 5045E 4WD Utility Tractor S/N: PY5045E000742 C/W: Differential Lock, Forward/ Reverse Shuttle, John Deere 553 Loader w/Joystick, Quick Coupler, John Deere 68 in Bucket, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Pickup Hitch,		SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK ICE OF 2 - Lot #'s: 809, 810
	9.5x24 Front Tires, 14.9x28 Rear Tires Usage: 3,181 Hr Asset located in: Humble, TX	809	2017 Case IH Magnum 310 4WD Tractor S/N: JJAM0310THRF01144 C/W: Enclosed Cab, Air Conditioner, Front
804	2003 Kubota MX5000E 2WD Utility Tractor S/N: 11584 C/W: 4 Forward 4 Reverse, Manual Transmission, 38.0 kW Engine, 2003 US EPA		Weights, Rear Remotes, 540 PTO, Drawbar, /85R34 Front Tires, Dual 480/80r46 Rear Tir Usage: 2,635 Hr Asset located in : Robstown, TX
	Label, TAS ML280 Loader, 61 in Bucket, 3-Point Hitch, 29x12.50-15 Front Tires, 44x18.00-20 Rear Tires Usage: 481 Hr Asset located in : Lake Worth, TX	810	2017 Case MAGNUM 310 4WD Tractor S/N: JJAM0310KHRF01180 C/W: Enclosed Cab, Air Conditioner, CVT, Forward/ Reverse Shuttle, Front Weights, 5 Rear Remotes, 1000 PTO, 3-Point Hitch, Dual
805	Massey Ferguson 2WD Tractor (Inoperable) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		380/85R34 Front Tires, Dual 380/90r50 Rear Tires Usage: 2,810 Hr Notes : TODAY'S PRICE: 14% OFF \$123,419 (\$106,000)
806	1988 John Deere 2955 2WD Tractor S/N: L02955T626188 C/W: Enclosed Cab, 16 Forward 8 Reverse, John Deere Loader, Quick Coupler, 72 in Bucket, 540 PTO, 3-Point Hitch, Drawbar, 10.00- 16 Front Tires, 18.4-38 Rear Tires Usage: 3,219 Hr Asset located in: Lake Worth, TX	811	Asset located in: Baytown, TX John Deere 8320R 4WD Tractor S/N: R0H8NBR611453 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	CHOICE OF 2 - Lot #'s: 812, 813		2013 Mahindra 6110ST 4WD Tractor S/N: 61GCF00632 C/W: Enclosed Cab, Air Conditioner, Air Ride
812	2024 John Deere 6155M 4WD Tractor (Unused) S/N: 1L06155MTRG423600 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse, PowrQuad Plus, Left Hand Reverser, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Front 3-Point Quick Hitch, 3 Rear Remotes, Air Brake System, Exterior 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420 /70R28 Front Tires, 520/70R38 Rear Tires Usage: 4 Hr	010	Seat, Differential Lock, Powershift, Forward/ Reverse Shuttle, 60 hp Engine, Mahindra ML161 Loader w/Joystick, Quick Coupler, 79 in Bucket, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, Rhino Turbo 96 96 in Mower, 10.5/80-18 Front Tires, 18.4x24 Rear Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 738 Hr Notes: JERRY WATKINS PERSONAL RANCH TRACTOR Asset located in: Lake Worth, TX
813	Asset located in: Lake Worth, TX 2024 John Deere 6155M 4WD Tractor (Unused) S/N: 1L06155MLRG423350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse, PowrQuad Plus, Left Hand Reverser, 2024 US	818	2012 Kubota M7040 4WD Tractor S/N: 53487 C/W: Enclosed Cab, Air Conditioner, 4 Forward, Quick Coupler, 83 in Bucket, 4 Mid-Mount Remotes, 6 Rear Remotes Usage: 2,003 Hr Asset located in: Lake Worth, TX
	EPA Label, Requires Diesel Exhaust Fluid, Front 3-Point Quick Hitch, 3 Rear Remotes, Air Brake System, Exterior 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420 /70R28 Front Tires, 520/70R38 Rear Tires Usage: 1 Hr Asset located in: Lake Worth, TX	819	Challenger MT665B 4WD Tractor S/N: S206014 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
814	2013 John Deere 6105D 4WD Tractor S/N: 1P06105DADM050351 C/W: Enclosed Cab, Air Conditioner, 3 Forward 3 Reverse, Hydrostatic Drive, Forward/ Reverse Shuttle, 130 kW Engine, 2013 US EPA Label, CARB Compliant, 4 Rear Remotes, 540 PTO, 3- Point Hitch, Hydraulic Top Link, 340/85R24 Front Tires, 18.4x34 Rear Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY	820	1998 Kubota L3600DT 4WD Tractor S/N: 56376 C/W: 4 Forward 4 Reverse, Manual Transmission, Forward/ Reverse Shuttle, Kubota LA680 Loader w/Joystick, 1 Mid-Mount Remotes, HID Lights, 540 PTO, 3-Point Hitch, 8- 16 Front Tires, 14.9x24 Rear Tires Usage: 790 Hr Asset located in: Lake Worth, TX
815	Usage: 4,107 Hr Asset located in: Humble, TX 2022 John Deere 5100M 4WD Tractor S/N: 1LV5100MLNM104106 C/W: Canopy, Differential Lock, 16 Forward 16 Reverse, PowrReverser, Forward/ Reverse Shuttle, 2022 US EPA Label, Requires Diesel		Kioti LB1914 4WD Tractor S/N: 04000837 C/W: 8 Forward 4 Reverse, Manual Transmission, 3-Point Hitch, 6-12 Front Tires, 12.4-16 Rear Tires Usage: 667 Hr Asset located in: Lake Worth, TX
	Exhaust Fluid, John Deere 540M Loader w /Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, 320/85R24 Front Tires, 460/85R30 Rear Tires Usage: 2,124 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	822A	2010 John Deere 9530 Articulated Tractor S/N: 1RW9530PCAP018006 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Grouser 16 ft Blade, 4 Rear Remotes, Auxiliary Hydraulics, Rear Weights, Dual 800/70R38 Tires Usage: 11,887 Hr Asset located in: Lake Worth, TX
816	2012 Kubota M9960 4WD Tractor S/N: 87373 C/W: Enclosed Cab, Air Conditioner, 4 Forward, Loader, Quick Coupler, Pallet Forks, 4 Mid- Mount Remotes, 2 Rear Remotes Usage: 561 Hr Asset located in: Lake Worth, TX	822B	2019 Shelbourne CVS16 16 ft Stripper Combine Header S/N: CVS16193113 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
823	2016 Manitou MRT2550 High Reach Rotating 4x4x4 Telehandler S/N: 769939 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Load Moment Indicator, 81 ft Max Lift Height, 11000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 71 in Forks, Outriggers, Auxiliary Hydraulic Plumbing, 445 /65R22.5 Tires Usage: 3,059 Hr	828	2015 JLG 1255 Telehandler S/N: 0160070536 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,626 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	829	2015 JLG G12-55A Telehandler
824	2019 JLG 1255 Telehandler S/N: 0160096252 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75- 28 Tires, EQUIPMENT-FROM-A-PRIMORIS-		S/N: 0160065521 C/W: Open Operator Station, Air Ride Seat, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Hydraulic Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,930 Hr Asset located in: Lake Worth, TX
	SERVICÉS-CORP-COMPANY	830	· · · · · · · · · · · · · · · · · · ·
СНОІС	Usage: 3,852 Hr Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 825, 826	830	2014 JLG G12-55A Telehandler S/N: 0160061321 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires,
825	2018 JLG 1255 Telehandler S/N: 0160084208 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 12,673 Hr Asset located in: Humble, TX		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,775 Hr Asset located in: Lake Worth, TX
		831	2014 JLG G12-55A Telehandler S/N: 0160060643 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US
826	2019 JLG 1255 Telehandler S/N: 0160091605 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel		EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 6,716 Hr Asset located in : Lake Worth, TX
	Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 360/85-28 Solid Tires Usage: 9,502 Hr Asset located in : Lake Worth, TX	832	2011 JLG G12-55A Telehandler S/N: 0160042364 C/W: Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2011 US EPA Label, Outriggers, Frame Leveling,
CHOIC	E OF 4 - Lot #'s: 827, 828, 829, 830		Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: Not Available Asset located in : Humble, TX
827	2015 JLG 1255 Telehandler S/N: 0160070550 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,988 Hr	833	2019 Skytrack 12054 Telehandler S/N: 0160092640 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 0 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Hydraulic Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 3,148 Hr Asset located in: Lake Worth, TX
	Asset located in: Oklahoma City, OK	834	2006 Dieci Pegasus 40.25 Telehandler S/N: 1560587 C/W: Enclosed Cab, 69 ft Max Lift Height, 8800 Ib Max Lift Capacity, 2006 US EPA Label, Crane Attachment, 18-22.5 Tires Usage: 5,470 Hr

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 3 - Lot #'s: 836, 837, 838	сноіс	E OF 2 - Lot #'s: 843, 844
836	2018 Skyjack SJ1056TH Telehandler S/N: 87311173 Usage: 2,541 Hr Asset located in: Lake Worth, TX	843	2018 JLG 1055 Telehandler S/N: 0160083964 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires
837	2018 Skyjack SJ1056TH Telehandler S/N: 87310698 C/W: Open Operator Station, 56 ft 0 in Max Lift Height, 10000 lb Max Lift Capacity, Outriggers, 14.00-24 Tires Usage: 2,041 Hr		Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,300 Hr Asset located in: Lake Worth, TX
838	Asset located in: Midland, TX 2017 Skyjack SJ1056TH Telehandler S/N: 8730578 C/W: Open Operator Station, 56 ft Max Lift Height, 2017 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 4,532 Hr Asset located in: Midland, TX	844	2017 JLG 1055 Telehandler S/N: 160082583 C/W: Enclosed Cab, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 59 in Forks, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 7,542 Hr Asset located in: Lake Worth, TX
839	2018 Genie GTH-1056 Telehandler S/N: GTH10E12290 C/W: Open Operator Station, Air Ride Seat, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 2,530 Hr Asset located in: Humble, TX	845	2014 JLG G10-55A Telehandler S/N: 0160058853 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Foam Filled Tires Usage: Not Available Asset located in: Lake Worth, TX
840	2013 JCB 510-56 Telehandler S/N: JCB5CGXGK01403372 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 4,527 Hr Asset located in: Lake Worth, TX	846	2015 Gehl RS10-55 Telehandler S/N: RS1055CG90781 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,609 Hr
841	2007 Genie GTH-1056 Telehandler S/N: GTH1007A-11371 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Tilt Carriage, Outriggers, 14.00-24 Tires Usage: 8,632 Hr Asset located in: Lake Worth, TX	847	Asset located in: Lake Worth, TX 2018 JLG 10054 Telehandler S/N: 0160086824 C/W: Open Operator Station, 53 ft Max Lift Height, 10000 lb Max Lift Capacity, 48 in Forks Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24
842	2017 Gehl RS10-55 Telehandler S/N: RS1055CH90900 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 3,546 Hr Asset located in: Humble, TX		Aperture Tires Usage: 3,294 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
CHOIC	CHOICE OF 5 - Lot #'s: 848, 849, 850, 851, 852		2007 SkyTrak 10054 Telehandler S/N: 0160029235 C/W: Open Operator Station, 54 ft Max Lift	
848	2016 JLG 10054 Telehandler S/N: 160076446 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 47 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Solid Tires Usage: 4,051 Hr		US EPA Label, 48 in Fo Outriggers, Frame Leve Plumbing Usage: 1,666 Hr Notes : ITEM AT OFFSI PICKED UP BY JANUA SUBJECT TO 3RD PAR	
849	Asset located in: Lake Worth, TX 2015 JLG 10054 Telehandler S/N: 0160065420 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 8,383 Hr Asset located in: Lake Worth, TX	854	2018 Haulotte HTL9055 Telehandler S/N: 2030718 C/W: Enclosed Cab, Air Conditioner, Load Moment Indicator, 55 ft Max Lift Height, 9000 lb Max Lift Capacity, Manual Coupler Usage: 635 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	
850	2015 JLG 1055 Telehandler S/N: 0160070447 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing,		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR	
	14.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,727 Hr		E OF 3 - Lot #'s: 855, 856, 857	
851	Asset located in: Lake Worth, TX 2015 JLG 10054 Telehandler S/N: 0160064214 C/W: Open Operator Station, 42 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Manual Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 5,103 Hr	855	2017 JLG 943 Telehandler S/N: 160079731 C/W: Open Operator Station, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 59 in Forks, Frame Leveling, 370 /75-28 Tires Usage: 5,224 Hr Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	856	2017 JLG 943 Telehandler	
852	2014 JLG 10054 Telehandler S/N: 0160062880 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, Manual Coupler, Outriggers, Frame Leveling, 17.5-25 Tires Usage: 5,424 Hr Asset located in: Lake Worth, TX		S/N: 160079732 C/W: Open Operator Station, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 7,159 Hr Asset located in: Lake Worth, TX	
852A	2013 SkyTrak 10054 Telehandler S/N: 0160052932 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,413 Hr Asset located in: Lake Worth, TX	857	2016 JLG 943 Telehandler S/N: 160078141 C/W: Enclosed Cab, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Foam Filled Tires Usage: 6,476 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
CHOIC			2013 JLG 8042 Telehandler S/N: 0160054404 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, Frame Leveling, 15.5-25 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
	S/N: GTH081419083 C/W: Open Operator Station, 44 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US		Usage: 1,889 Hr Asset located in: Lake Worth, TX
	EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: Not Available Asset located in : Midland, TX	866	Gehl RS8-42 Telehandler S/N: RS842JE0917426 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US
859A	JCB 509.42 Telehandler S/N: JCB5CF7GPJ2755050 C/W: Open Operator Station, 42 ft Max Lift Height, 9000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing,		EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,721 Hr Asset located in: Lake Worth, TX
	14.00-24 Tires Usage: 2,174 Hr Asset located in : Lake Worth, TX	867	2017 Gehl RS8-42 Telehandler S/N: RS842CJ18031 C/W: Open Operator Station, 42 ft Max Lift
860	2016 SkyTrak 8042 Telehandler S/N: 0160077066 C/W: Open Operator Station, 42 ft Max Lift Height, 4000 lb Max Lift Capacity, 47.5 in	сноіс	Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,714 Hr
	Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,626 Hr		Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 868, 869
	Asset located in: Lake Worth, TX	_	
CHOIC 861	1 2015 JLG 8042 Telehandler S/N: 0160069747 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary	868	2013 Gehl RS8-42 Telehandler S/N: RS842JE0617386 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,087 Hr Asset located in: Oklahoma City, OK
	Hydraulic Plumbing, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	869	2013 Gehl RS8-42 Telehandler S/N: RS842JF0517510 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks,
862	2015 JLG 8042 Telehandler S/N: 0160070986 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary		Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,342 Hr Asset located in: Oklahoma City, OK
	Hydraulic Plumbing, 13.00-24 Solid Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,470 Hr	870 2006 Mustang 944L Telehandler S/N: 944LJX0635018	S/N: 944LJX0635018
863	Asset located in: Lake Worth, TX 2014 SkyTrak 8042L Telehandler S/N: 0160060584 C/W: EQUIPMENT-FROM-SUNSTATE-		C/W: Open Operator Station, 44 ft Max Lift Height, 9000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 14.00-24 Tires Usage: 2,580 Hr Asset located in : Lake Worth, TX
	EQUIPMENT Usage: 5,289 Hr Asset located in : Lake Worth, TX	873	2006 SkyTrak 8042 Telehandler S/N: 0160024470 C/W: Enclosed Cab, 42 ft Max Lift Height, 8000 Ib Max Lift Capacity, 2006 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 2,478 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
874	2012 Genie GTH-644 Telehandler S/N: GTH061215400 C/W: Open Operator Station, 44 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, 13.00-24 Tires Usage: 4,133 Hr Asset located in: Lake Worth, TX	CHOIC 881	OF 3 - Lot #'s: 881, 882, 883 2013 SkyTrak 6042 Telehandler S/N: 0160055011
874A	2017 JLG Skytrak 6042 Telehandler S/N: 0160079780 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing Usage: 1,949 Hr		C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,040 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	882	2013 SkyTrak 6042 Telehandler
CHOICE OF 4 - Lot #'s: 875, 876, 877, 878 875 2014 JLG 6042 Telehandler S/N: 0160056200 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 47 in Forks, Manual Coupler, Fran	2014 JLG 6042 Telehandler S/N: 0160056200 C/W: Open Operator Station, 42 ft Max Lift	662	S/N: 0160054643 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,159 Hr Notes: . Asset located in: Oklahoma City, OK
	24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,631 Hr Asset located in : Lake Worth, TX	883	2013 SkyTrak 6042 Telehandler S/N: 0160047623 C/W: Open Operator Station, 42 ft Max Lift Height, Coupler Frame Leveling, 12,00,24
876	2014 JLG 6042 Telehandler S/N: 0160058949 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 47 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,476 Hr Asset located in: Lake Worth, TX 2015 SkyTrak 6042 Telehandler S/N: 0160070308 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,236 Hr Asset located in: Lake Worth, TX		Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,052 Hr Notes: . Asset located in: Oklahoma City, OK
		884	2013 JLG G6-42A Telehandler S/N: 0160051054 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2012 US
877			EPA Label, 47 in Forks, Frame Leveling, 370/75- 28 Tires Usage: 4,609 Hr Asset located in : Lake Worth, TX
		сноіс	E OF 2 - Lot #'s: 885, 886
878	2015 SkyTrak 6042 Telehandler S/N: 0160067892 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 kg Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,160 Hr Asset located in: Lake Worth, TX	885	2014 Gehl RS6-42 Telehandler S/N: RS642JF0814891 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2014 US EPA Label, Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,499 Hr Asset located in: Lake Worth, TX
		886	2014 Gehl RS6-42 Telehandler S/N: RS642JF0814899 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 47 in Forks, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,177 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
887	2018 JLG 6036 Telehandler S/N: 0160083772 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 315/95-28 Solid Tires Usage: 1,190 Hr Asset located in: Humble, TX	893	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921972 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,418 Hr Asset located in: Lake Worth, TX
		894	2013 Gehl RS6-34 Telehandler
	E OF 12 - Lot #'s: 888, 889, 890, 891, 892, 893, 894, 96, 897, 898, 899		S/N: RS634JE0921979 C/W: Open Operator Station, 35 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame
888	2014 Gehl RS6-34 Telehandler S/N: RS634JF0822387 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US		Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,678 Hr Asset located in: Oklahoma City, OK
	EPA Label, 48 in Forks, Manual Coupler, Frame	895	2012 Gehl RS6-34 Telehandler
	Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,160 Hr Asset located in: Lake Worth, TX	S/N: RS634JD0121707 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2011 US EPA Label, 48 in Forks, Manual Coupler, Fra Leveling, 15-19.5 Tires, EQUIPMENT-FROM SUNSTATE-EQUIPMENT Usage: 3,712 Hr Asset located in: Oklahoma City, OK 896 2012 Gehl RS6-34 Telehandler S/N: RS634JD0321723 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 72 in Forks, Manual Coupler, Fra Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMEN Usage: 3,973 Hr	S/N: RS634JD0121707 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2011 US EPA Label, 48 in Forks, Manual Coupler, Frame
889	2014 Gehl RS6-34 Telehandler S/N: RS634JF0522222 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US		SUNSTÅTE-EQUIPMENT Usage: 3,712 Hr
	EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,001 Hr Asset located in: Lake Worth, TX		S/N: RS634JD0321723 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US
890	·		
	Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,227 Hr	897	Asset located in: Lake Worth, TX Gehl RS6-34 Telehandler S/N: RS634DG22553 C/W: Open Operator Station, 34 ft Max Lift
	Asset located in: Lake Worth, TX		Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, Foam Filled Tires, EQUIPMENT
891	2014 Gehl RS6-34 Telehandler S/N: RS634DF1022506		FROM-SUNSTATE-EQUIPMENT Usage: 4,136 Hr Asset located in: Lake Worth, TX
	C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 15-9.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,025 Hr Asset located in: Lake Worth, TX	898	Gehl RS6-34 Telehandler S/N: RS634JE1122021 C/W: Open Operator Station, Air Ride Seat, 34 ft Max Lift Height, 6000 lb Max Lift Capacity,
892		-	60 in Forks, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
092	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921970 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,144 Hr Asset located in: Oklahoma City, OK		Usage: 3,296 Hr Asset located in : Lake Worth, TX
		899	Gehl RS6-34 Telehandler S/N: RS634DF1022514 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,338 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
900	Gehl RS6-34 Telehandler S/N: RS634JF0722333 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,642 Hr Asset located in: Lake Worth, TX	CHOICI 907	S/N: MAN00000J01033352 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 5500 lb Max Lift Capacity, Hydraulic
901	Gehl RS6-34 Telehandler S/N: RS634DF0922487 C/W: Open Operator Station, 34 ft Max Lift		Coupler, Auxiliary Hydraulic Plumbing, 12x16.5 Tires Usage: 2,764 Hr Asset located in : Lake Worth, TX
CHOIC	Height, 6000 lb Max Lift Capacity, 47.5 in Forks, Tilt Carriage, 15-19.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,389 Hr Asset located in: Lake Worth, TX E OF 4 - Lot #'s: 903, 904, 905, 906	908	2019 Manitou MT625 Telehandler S/N: MAN00000J01021296 C/W: Enclosed Cab, 19 ft 1 in Max Lift Height, 5500 lb Max Lift Capacity, Tier 4, 2019 US EPA Label, Hydraulic Coupler, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 2,832 Hr Asset located in: Lake Worth, TX
	. , ,	909	2007 Genie GTH-5519 Telehandler
903	2013 Gehl RS5-19 Telehandler S/N: RS519YF0251046 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,565 Hr Asset located in: Lake Worth, TX	909	S/N: 17897 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2007 US EPA Label, 48 in Forks, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 1,676 Hr
904	2013 Gehl RS5-19 Telehandler	<u> </u>	Asset located in: Lake Worth, TX
	S/N: RS519YF0851124 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,272 Hr Asset located in: Lake Worth, TX	910	2015 Genie GTH-5519 Telehandler S/N: GTH5515B2885 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Frame Leveling, 12-16.5 Tires Usage: 1,522 Hr Asset located in: Lake Worth, TX
905	2013 Gehl RS5-19 Telehandler S/N: RS519YF0251049 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 48 in Forks, Manual Coupler, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,838 Hr Asset located in: Lake Worth, TX	910A	2020 JLG 3013 Telehandler S/N: H160000215 C/W: Open Operator Station, Air Ride Seat, 13 ft Max Lift Height, 2360 lb Max Lift Capacity, Tier 4, 2020 US EPA Label, 46 in Forks, Hydraulic Coupler, 11.0/65-12 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 667 Hr
906	Gehl RS5-19 Telehandler	<u> </u>	Asset located in: Lake Worth, TX
	S/N: RS519YE1050991 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, US EPA Label, 46 in Forks, Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	911	Cat R80 8000 lb 4x2 Rough Terrain Forklift S/N: 49A01169 C/W: 3 Stage Mast, 192 in Max Lift Height, 117 in Lowered Mast Height, 48 in Forks, 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
		911A	2000 Case 580G 8000 lb 4x2 Rough Terrain Forklift

S/N: JJG0291451 C/W: 2 Stage Mast, 180 in Max Lift Height, 127 in Lowered Mast Height, 44 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 10,539 Hr

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
911B	2014 JCB 9504 4700 kg 4x4 Rough Terrain Forklift S/N: JCB95004H02364093 C/W: 3 Stage Mast, 127 in Lowered Mast Height, 47 in Forks, Side Shift, 2010 US EPA Label, JCB Power Sources 4 Cylinder 56 kW Diesel Engine Usage: 5,199 Hr Asset located in: Lake Worth, TX	Truck S/N: 1FD0X5HT3PEC87656 C/W: V8 6.7 L Diesel Engine, 2 Label, Requires Diesel Exhaust Brake, Automatic Transmissio Axle, 14706 lb Rears, 19500 lb Engine hrs, 225/70R19.5, Sprir 192 in Wheelbase, 11 ft Body, Stabilizers, Auto Crane HC-5 5 Hydraulic Crane, Tomahawk T Gasoline Generator Set, Boss I Air Compressor, Air Hose Reel Usage: 308 Mi	S/N: 1FD0X5HT3PEC87656 C/W: V8 6.7 L Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 30 Engine hrs, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 11 ft Body, Hydraulic
912	Sellick S80J4I-2 8000 lb 4x4 Rough Terrain Forklift S/N: 10015609S8J4I C/W: 3 Stage Mast, 264 in Max Lift Height, 126 in Lowered Mast Height, 69 in Forks, JCB Diesel Engine		Hydraulic Crane, Tomahawk TWG120A Gasoline Generator Set, Boss BA435 Hydraulic Air Compressor, Air Hose Reel
	Usage: 3,868 Hr Notes: ITEMS AT OFFSITE LOCATION MUST	сноіс	E OF 2 - Lot #'s: 917, 918
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR	917	2019 Ford F-550 4x4 Service Truck S/N: 1FDUF5HT3KEC14526 C/W: Power Stroke V8 6.7 L 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front
913	2015 Ford F-750 Service Truck S/N: 3FRWF7FL6FV730422 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	Wheelbase, PTO, 2018 Stellar TM ft 1 in Body, Hydraulic Stabilizers 3 Section Hydraulic Crane, Wirele Control, American Eagle 30P Pist	/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 2018 Stellar TMAX1-11AL 11 ft 1 in Body, Hydraulic Stabilizers, Stellar 7621 3 Section Hydraulic Crane, Wireless Remote Control, American Eagle 30P Piston Series Hydraulic Air Compressor, Miller Bobcat 250 250 A Gasoline Welder
914	2024 Ford F-550 XL 4x4 Extended Cab Service Truck		Usage: 190,847 Mi Asset located in : Midland, TX
	S/N: 1FD0X5HT8RED27006 C/W: Ford V8 6.7 L Diesel Engine, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 11 Engine hrs, Engine Brake, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, PTO, Caseco MM238 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Wireless Remote Control, American Eagle SHD-60 Hydraulic Air Compressor, Air Hose Reel Usage: 241 Mi Asset located in: Lake Worth, TX	918	2019 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HT0KEE24254 C/W: Ford Power Stroke Turbo Diesel V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 193 in Wheelbase, PTO, 2019 Auto Crane 772101 13 ft 4 in Body, Hydraulic Stabilizers, 2019 Auto Crane F79200160 7000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Miller Bobcat
915	2023 Ford F-550 4x4 Extended Cab Service Truck S/N: 1FD0X5HTXPED24749 C/W: 6.7 L Diesel Engine, 2023 US EPA Label,		11000 W Gasoline Generator Set, Auto Crane 250 cfm PTO Air Compressor, Air Hose Reel, Miller Bobcat 11000 W 250 A Gasoline Welder Usage: Not Available
	Requires Diesel Exhaust Fluid, Automatic	010	Asset located in: Midland, TX
	Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 2017 Altec 10 ft 3 in Body, Hydraulic Stabilizers, Auto Crane HC-5 5000 lb 2 Section Electric Crane, Wired Remote Control, Boss BA435 Hydraulic Air Compressor, Air Hose Reel, Miller Bluestar 185 Welder Usage: 95 Mi Asset located in: Lake Worth, TX	919	2018 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HY3JDA01060 C/W: Ford V10 6.8 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft Body, Vanair Air N Arc All-In- One Power System, Product Tanks, Hose Reels Usage: 182,415 Mi Notes: EQUIPMENT FROM UNITED RENTALS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
920	2017 Ford F-550 XL 4x2 Service Truck S/N: 1FDUF5GT5HDA09578 C/W: Ford Powerstroke V8 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 114706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, Auto Crane Titan 38K 11 ft Body, Hydraulic Stabilizers, Auto Crane HC6 6000 lb 3 Section Hydraulic Crane, Wired Remote Control, Gasoline Air Compressor, Lincoln Bobcat 225 Gasoline Welder Usage: 69,562 Mi Asset located in: Lake Worth, TX	923	2012 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HY9CEB86563 C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 162 in Wheelbase, PTO, Knaphiede 9 ft 2 in Body, Hydraulic Stabilizers, Auto Crane 5005H 5000 lb 3 Section Hydraulic Crane, Wired Remote Control, Speedair 4LW38 Gasoline Air Compressor, Air Hose Reel Usage: 193,733 Mi Asset located in: Midland, TX
920A	2017 Ford F-550 XL 4x2 Service Truck S/N: 1FDUF5GT1HEB70066 C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, Knapheide 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 2 Section Crane, Wireless Remote Control, Boss Hydraulic Air Compressor, Air Hose Reel Usage: 228,233 Mi Asset located in: Lake Worth, TX	923A 924	2008 Ford F-550 4x2 Service Truck S/N: 1FDAF56R08EE06327 C/W: V8 Diesel Engine, 2008 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, United Truck Bodies 108UTB 12 ft 4 in Body, Northsta Gasoline Air Compressor Usage: 211,927 Mi Asset located in: Lake Worth, TX 2012 Dodge Ram 5500 4x2 Service Truck
920B	2016 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT4GEA46341 C/W: Ford 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, IMT 11 ft Body, 55 gal Oil Tanks, (5) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, Vanair Air N Arc 150 Gasoline Air Compressor, Air Hose Reel, Vanair Air N Arc 150 Welder, Rear View Camera; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 230,316 Mi	сноіс	S/N: 3C7WDMBL1CG197440 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Wireless Remote Control Usage: 296,712 Mi Asset located in: Lake Worth, TX
СНОІС	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 922, 923	925	2023 Chevrolet 4500 4x2 Service Truck S/N: 1HTKHPVH4PH293943 C/W: International 350 V8 6.6 L Diesel 350 hp

922 2014 Ford F-550 XL 4x4 Crew Cab Service Truck

S/N: 1FD0W5HT0EEB12698
C/W: V8 6.7 L Diesel 300 hp Engine, 2014 US
EPA Label, Requires Diesel Exhaust Fluid,
Automatic Transmission, 7000 lb Front Axle,
14706 lb Rears, 19500 lb GVWR, 225/70R19.5,
Spring Suspension, 202 in Wheelbase,
Knaphiede 11 ft 2 in Body, Manual Stabilizers,
Auto Crane 6006EH 3 Section Electric Crane,
Wired Remote Control, Compressor air
systems c140gec34hc Gasoline Air
Compressor, Air Hose Reel
Usage: Not Available

Asset located in: Midland, TX

S/N: 1HTKHPVH4PH293943 C/W: International 350 V8 6.6 L Diesel 350 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 10 Engine hrs, Allison Automatic Transmission, 7000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 141 in Wheelbase, PTO, Knapheide 9 ft Body, Manual Stabilizers, Liftmoore 4000X 4000 lb 3 Section Electric Crane, Wired Remote Control, Land Honor LHR-GAC40T Gasoline Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 54 Mi

Lot #	Details	Lot #	Details	
927	2019 Chevrolet 4500 4x4 Crew Cab Service Truck S/N: 1HTKJPVK0KH619357 C/W: NAVISTAR 350 6 Cylinder 6.6 L Diesel 350 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Allison P,R,N,D,L,1 Automatic Transmission, 7500 lb Front Axle, 13500 lb Rears, Factory-GM Drive Axles, 19500 lb GVWR, 245/70R19.5, Factory-GM Spring Suspension, 199 in Wheelbase, 2019 Auto Crane 13 ft 6 in Body, Manual Stabilizers, Auto Crane EHC 6 6000 lb 2 Section Hydraulic Crane Usage: 120,371 Mi Asset located in: Midland, TX	931 2017 Ford F-250 Utility Truck S/N: 1FDBF2A62HED60788 C/W: 6.2 Gasoline Engine, Automatic Transmission, 3800 lb Front Axle, 634 Rears, 9900 lb GVWR, Steel, 245/75R1 Suspension, 142 in Wheelbase, Knaph Body Usage: 190,429 Mi Notes: TEXAS BUYERS MUST STOP IN TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 932 2012 Ford F-550 XL 4x2 Crew Cab Util S/N: 1FD0W5GT8CEC42968 C/W: V8 6.7 L Diesel 300 hp Engine, 20 EPA Label, Requires Diesel Exhaust Fl Automatic Transmission, 6500 lb Fron 14706 lb Rears, 19500 lb GVWR, Steel /70R19.5, Spring Suspension, 202 in Wheelbase, Knapheide 6132D54 11 ft Usage: 319,591 Mi	931 2017 Ford F-250 Utility Truck S/N: 1FDBF2A62HED60788 C/W: 6.2 Gasoline Engine, Automatic Transmission, 3800 lb Front Axle, 6340 lb Rears, 9900 lb GVWR, Steel, 245/75R17, Spr Suspension, 142 in Wheelbase, Knapheide 8 Body Usage: 190,429 Mi Notes: TEXAS BUYERS MUST STOP IN OFFI TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 932 2012 Ford F-550 XL 4x2 Crew Cab Utility Tru S/N: 1FD0W5GT8CEC42968	S/N: 1FDBF2A62HED60788 C/W: 6.2 Gasoline Engine, Automatic Transmission, 3800 lb Front Axle, 6340 lb Rears, 9900 lb GVWR, Steel, 245/75R17, Spring Suspension, 142 in Wheelbase, Knapheide 8 ft Body Usage: 190,429 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2012 Ford F-550 XL 4x2 Crew Cab Utility Truck S/N: 1FD0W5GT8CEC42968 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US
928	28 2023 Ram 4500HD 4x2 Service Truck S/N: 3C7WRKBL5PG620080 C/W: Cummins B6.7 360 6 Cylinder 6.7 L Diesel 360 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 16 Engine hrs, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR,		EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 202 in Wheelbase, Knapheide 6132D54 11 ft Body	
		933	2012 Ford F-550 4x2 Utility Truck S/N: 1FDUF5GT7CEB42748 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 163 in Wheelbase, 10 ft 11 in Body, Manual Stabilizers, Liftmoore 3200 lb Hydraulic Crane, Wired Remote Control, Miller Wildcat 200 6500 W Gasoline Generator Set, Gasoline Air Compressor Usage: 296,236 Mi	
	Asset located in: Lake Worth, TX	-	Asset located in: Lake Worth, TX	
929	2019 Ford F-450 4x4 Extended Cab Service Truck S/N: 1FD0X4HT2KED48305 C/W: Ford V8 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 6500 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, Royal Truck Body 12 ft Body, Manual Stabilizers, Liftmoore 10000 lb 3 Section Electric Crane Usage: Not Available Asset located in: Lake Worth, TX	934	2019 Ford F-350 XL 4x4 Crew Cab Utility Truck S/N: 1FD8W3HT2KEF96442 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 179 in Wheelbase, Knapheide 9 ft Body Usage: 121,763 Mi Asset located in: Lake Worth, TX 2017 Ram 3500 4x2 Crew Cab Utility Truck	
930	2013 Ford F-450 4x4 Crew Cab Service Truck S/N: 1FD0W4HY5DEB45653 C/W: Ford V8 6.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500.0 lb GVWR, 225/70R19.5, Spring Suspension, 202 in Wheelbase, PTO, 2007 11 ft Body, Manual Stabilizers, Stahl 3200 LRX 3200 lb 3 Section Electric Crane, Wired Remote Control Usage: 215,755 Mi Asset located in: Lake Worth, TX		S/N: 3C7WRSCL3HG632261 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 170 in Wheelbase, Knapheide 9 ft Body, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
936	2017 Ram 3500 4x2 Crew Cab Utility Truck S/N: 3C7WRSCL5HG632262 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 4102 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235 /80R17, Spring Suspension, 172 in Wheelbase, Knapheide 6108D54J1 9 ft Body, Vanair Viper Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 104,083 Mi	940	2015 Chevrolet 2500HD 4x4 Crew Cab Utility Truck S/N: 1GC1KUE87FF581426 C/W: Chevy duramax V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2003 Engine hrs, Exhaust Brake, Allison Automatic Transmission, 5600 lb Front Axle, 6200 lb Rears, 10000 lb GVWR, 285/70/R18, Spring Suspension, 2015 Coseco 8 ft Body Usage: 258,913 Mi Asset located in: Lake Worth, TX 2015 Chevrolet Silverado 2500 HD 4x2 Utility
937	Asset located in: Lake Worth, TX 2015 Ford F-350 4x4 Crew Cab Utility Truck S/N: 1FD8W3HT5FEB51666 C/W: V8 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, Dual Rear Wheel, Spring Suspension, 7 ft Body		Truck S/N: 1GC0CUEG1FZ528560 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9300 lb GVWR, 245/75R17 Spring Suspension, 130 in Wheelbase Usage: 230,081 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETEI DISCREPANCY-UNIT SHOWS 230,081, TITLE SHOWS 232,270 Asset located in: Humble, TX
CHOIC	Usage: 167,166 Mi Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 938, 939	_	
938	2021 Chevrolet Silverado 2500 HD 4x2 Crew	942	2014 Ford F-250 XL 4x4 Extended Cab Utility
	Cab Utility Truck 6/N: 1GB2WLE77MF235677 6/W: V8 6.6 L Gasoline Engine, 2021 US EPA Cabel, 2137 Engine hrs, Automatic Fransmission, 4400 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 162 in Wheelbase, 2021 Harbor 8 t 2 in Body Usage: 75,339 Mi	943	Truck S/N: 1FT7X2B68EEB70690 C/W: Ford V8 6.2 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 225 /70R19.5, Spring Suspension, 142 in Wheelbase, 6 ft 10 in Body Usage: 421,371 Mi
939	Asset located in: Midland, TX 2021 Chevrolet Silverado 2500 HD 4x2 Utility		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
939A	Truck S/N: 1GB0WLE72MF189165 C/W: V8 6.6 L Gasoline Engine, 2021 US EPA Label, 2015 Engine hrs, Automatic Transmission, 4400 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 140 in Wheelbase, Scelzi 8 ft 2 in Body Usage: 109,730 Km Asset located in: Midland, TX 2016 GMC 2500HD 4x4 Crew Cab Utility Truck		943 2014 Chevrolet 2500HD 4x2 Crew C Truck S/N: 1GC1CVCG7EF160110 C/W: GM Gasoline Engine, Automat Transmission, 4400 lb Front Axle, 6 Rears, 9500 lb GVWR, 265/70R17, S Suspension, 167 in Wheelbase, Om Body, Air Hose Reel Usage: 161,768 Mi Notes: TEXAS BUYERS MUST STOR
909A	S/N: 1GT12REG1GF303868 C/W: GM V8 6.0 L Gasoline Engine, 2016 US		PROCESS TITLE Asset located in: Lake Worth, TX
	EPA Label, 8880 Engine hrs, Automatic Transmission, 4800 lb Front Axle, 6200 lb Rears, 9900 lb GVWR, 265/70R17, Spring Suspension, Reading 9 ft Body Usage: 214,244 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	944	2012 Ford F-250 XL 4x2 Extended Cab Utility Truck S/N: 1FD7X2A6XCEC57999 C/W: Ford 6.2 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 4250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 245 /75R17, Spring Suspension, 158 in Wheelbase, Knapheide 696J 8 ft Body Usage: 215,738 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

	2	1	2
Lot #	Details	Lot #	Details
945	2003 Ford F-250 4x2 Extended Cab Utility Truck S/N: 1FDNX20L13EC09631 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	CHOICI 950	ICE OF 2 - Lot #'s: 950, 951 2020 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 1NP3LJ0X8LD732020 C/W: Paccar L9 6 Cylinder 8.9 L Diesel 330 hp
946	2009 Ford F-250 XL 4x2 Utility Truck S/N: 1FDNF20569EA84459 C/W: Ford 5.4 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, 3950 lb Front Axle, 5892 lb Rears, 8800 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, 2009 Omaha 8 ft Body Usage: 152,394 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8871 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 18740 lb Front Axle, 40000 lb Rears, 58740 lb GVWR, Steel, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Suspension, 210 in Wheelbase, PTO, Niece WT-4K 4000 gal Tank, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 100,644 Mi Asset located in: Lake Worth, TX
947	2008 Ford F-250 XL 4x4 Utility Truck S/N: 1FTNF21548EE41543 C/W: V8 5.4 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 9000 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, Knapheide 8 ft Body Usage: 195,357 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	951	2019 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 2NP3LJ0XXKM624300 C/W: Paccar PX-9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 18180 lb Front Axle, 40000 lb Rears, 4.11:1 Axle Ratio, 58180 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 210 in Wheelbase, PTO, 2018 Niece Tank, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray
948	2006 Chevrolet 2500 4x2 Utility Truck		Usage: 92,315 Mi
	S/N: 1GBHC24U76E153672 C/W: V8 6.0 L Gasoline Engine, 2006 US EPA		Asset located in: Lake Worth, TX
	Label, Automatic Transmission, 245/75R16, Spring Suspension, 8 ft 2 in Body Usage: 33,621 Mi Asset located in : Lake Worth, TX	S/ C/ Re En Dit Re Ra /8/ Do Su cu 5 i Co Sp Us	2015 Peterbilt 348 6x4 Water Truck S/N: 2NP3LJ0XXFM280411 C/W: Paccar PX-9 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9583 Engine hrs,
949	2019 Nissan Frontier 4x2 Extended Cab Utility Truck S/N: 1N6AD0CU5KN753789 C/W: Nissan V6 4.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 3296 Ib Front Axle, 3331 lb Rears, 5588 lb GVWR, 265 /70R16, Spring Suspension, 126 in Wheelbase, 6 ft 8 in Body Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		Differential Lock, 20000 lb Front Axle Rears, Dana DSH44 Drive Axles, 4.88 Ratio, 64000 lb GVWR, Aluminum WI /80R22.5 Front Tires, 11R22.5 Rear Double Frame, Air Trac 4-Bag Air Rid Suspension, 209 in Wheelbase, PTO, curry supply Steel Tank, PTO Driven 5 in, Spray Bar, Hose Reel, In-Cab Re
		'953	2018 Kenworth T370 6x4 Water Truck S/N: 2NKHLJ9X7JM189233 C/W: Paccar 6 Cylinder Diesel Engine, US EPA Label, 4518.8 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 14600 lb Front Axle, 20000 lb Rears, 54600 lb GVWR, 12R22.5 Front Tires, 11R22.5 Rear Tires, 228 in Wheelbase, PTO Driven Pump, Front Spray, Rear Spray, Side Spray, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 30,539 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
954	2014 International 5900I 4000 gal 6x4 Water Truck S/N: 3HSXYSNR9EN795890 C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 476 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 14777 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 285/75R24.5, Dual Steering Boxes, Air Ride Suspension, 214 in Wheelbase, Fiberglass Reinforced Plastic Tank Usage: 382,841 Mi Asset located in: Lake Worth, TX	957	2003 International 5600i 4500 gal 6x4 Water Truck S/N: 1HTXHAHT13J068496 C/W: Cummins ISM 320V 6 Cylinder Diesel 305 hp Engine, 19509 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 212 in Wheelbase, 2013 United Truck & Equipment 4500 gal Steel Tank, Franklin Electric Hydraulic Driven Pump, 6 ft 8 in, Spray Bar, In-Cab Remote Controlled Water Cannon, Rear Spray, Side Spray Usage: 159,456 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 955, 956	958	1999 International 8100 Vacuum Tanker Truck S/N: 1HSHCAHR2XH630060 Usage: Not Available
955	2014 Freightliner M2 106 4000 gal 6x4 Water		Asset located in: Lake Worth, TX
	Truck S/N: 1FVHCYCYOEHFN9171 C/W: Cummins ISL 6 Cylinder Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-11210C 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.11:1 Axle Ratio, 58000 lb GVWR, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 196 in Wheelbase, PTO, Ledwell LW4000 WT 4000 gal Steel Tank, PTO Driven Pump, 0 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: Not Available	959	1998 Oshkosh FF-115 6x6 Water Truck S/N: 10TDCKY32WS064147 C/W: Cummins L10 6 Cylinder 10 L Diesel 260 hp Engine, 1997 US EPA Label, 4536 Engine hrs, Eaton Fuller 9-Speed Manual Transmission, Differential Lock, 23000 lb Front Axle, 45000 lb Rears, 69000 lb GVWR, Air Ride Cab, Steel, 445/65R22.5 Front Tires, 12R22.5 Rear Tires, Hendrickson Rubber over Walking Beam Suspension, 212 in Wheelbase, Housby Tank, Rear Spray, Side Spray Usage: 105,114 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	960	1995 International 8200 6x4 Water Truck
956	2012 Freightliner M2 106 Business Class M2 6x4 4000 Gallon 6x4 Water Truck S/N: 1FVHCYBS3CHBS9418 C/W: Cummins ISB 6 Cylinder 8.3 L Diesel 300 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4544.0 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Double Frame, Airliner 4-Bag Air Ride Suspension, 200 in Wheelbase, PTO, 2012 Ledwell LW4000WT, AND STAN AMERICAN BENEVILLEY BASE		S/N: 1HSHGAER3SH682251 C/W: Cummins 6 Cylinder Diesel Engine, 31586 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Steel, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 164 in Wheelbase, 1 Compartments, PTO Driven Pump, Rear Spray Usage: 658,690 Mi Asset located in: Lake Worth, TX E OF 4 - Lot #'s: 961, 962, 963, 964
	BERKELEY PTO Driven Pump, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray		
	Usage: Not Available	961	2021 International MV607 Water Truck
	Asset located in: Midland, TX	_	S/N: 3HAEUMMN0ML087250 C/W: Lands Unused Powder Coated 2000 gal
956A	2008 Peterbilt 340 6x4 Water Truck S/N: 2NPRLN9X48M764601 C/W: Paccar PX-8 6 Cylinder Diesel Engine, 13743 Engine hrs, Exhaust Brake, Allison 3000 Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, Spicer DSP41P Drive Axles, 5.57:1 Axle Ratio, 54600 lb GVWR, Aluminum Front Wheels, 11R22.5, Hendrickson Spring over Walking Beam Suspension, 196 in Wheelbase, PTO, Steel Tank, ARMS PTO Driven Pump, 5 ft, Spray Bar, Hose Reel, Rear Spray, Side Spray Usage: 53,003 Mi		Steel Tank Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
962	2 2019 International 4300 2500 gal 4x2 Water Truck S/N: 1HTMMMML3KH515096 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4450 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 164 in Wheelbase, PTO,	967	2011 International 4400SBA Water Truck S/N: 1HSMKAAN8BH358390 C/W: International 6 Cylinder Diesel Engine, 10838 Engine hrs, 10000 lb Front Axle, 20000 lb Rears, Air Ride Suspension, PTO, PTO Driven Pump, Rear Spray, Side Spray Usage: Not Available Asset located in: Humble, TX
	Lands 2500 gal Steel Tank, PTO Driven Pump, 7 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 191,161 Mi Asset located in : Lake Worth, TX	Truck S/N: 1HTMPAFP95H166536 C/W: International VT365 6 Cylinder II hp Engine, 2004 US EPA Label, 5463 Inrs, 5-Speed Manual Transmission, 1 Front Axle, 21000 lb Rears, 31000 lb In 11R22.5 Front Tires, 22.5 MIX Rear To Spring Suspension, 152 in Wheelbase Ledwell LW2000WT 2000 gal Steel Taberkeley PTO Driven Pump, 6 ft 2 in, Septime Steel, Front Spray, Rear Spray, Septime Sylvage: 15,846 Mi	S/N: 1HTMPAFP95H166536 C/W: International VT365 6 Cylinder Diesel 215 hp Engine, 2004 US EPA Label, 5463 Engine
963	2019 International MA025 2500 gal 4x2 Water Truck S/N: 1HTMMMML4KH515138 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4769 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air		Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5 Front Tires, 22.5 MIX Rear Tires, Spring Suspension, 152 in Wheelbase, PTO, Ledwell LW2000WT 2000 gal Steel Tank, Berkeley PTO Driven Pump, 6 ft 2 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray
	Ride Suspension, 168 in Wheelbase, PTO, LANDS 2500 gal Steel Tank, PTO Driven Pump, In-Cab Remote Controlled Water Cannon, Front Spray, Rear Spray, Side Spray, Lands Unused Powder Coated 2000 gal Steel Tank		E OF 2 - Lot #'s: 969, 970
	Usage: 197,374 Mi Asset located in: Lake Worth, TX	969	2013 Ford F-750 4x2 Water Truck S/N: 3FRXF7FA1DV026323
964 CHOIC	2018 International MA025 Water Truck S/N: 1HTMMMML0JH351983 Usage: Not Available Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 965, 966		C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 14,173 Mi
065	2014 International 4200 Av2 Water Truck		Asset located in: Lake Worth, TX
965	2014 International 4300 4x2 Water Truck S/N: 1HTMMAAM8EH467675 C/W: International 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 177,213 Mi Asset located in: Humble, TX	S/N: 3FRXF7FA8DV02 C/W: Cummins ISB 6 hp Engine, 2013 US EF Exhaust Fluid, 3997 E Manual Transmission 21000 lb Rears, 33000 Spring Suspension, 15 Steel Tank, PTO Drive Spray, Rear Spray, Sid	2013 Ford F-750 4x2 Water Truck S/N: 3FRXF7FA8DV026450 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 3997 Engine hrs, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray, EQUIPMENT- FROM SUNSTATE-EQUIPMENT
966	2013 International 4300 2000 gal 4x2 Water Truck		Usage: 12,250 Mi Asset located in : Lake Worth, TX
	S/N: 1HTMMAAL4DH202404 C/W: 6 Cylinder Diesel Engine, 7386 Engine hrs, Automatic Transmission, Steel, 11R22.5, Air Ride Suspension, 156 in Wheelbase, PTO, 2000 gal Tank, 1 Compartments, 7 ft 6 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 238,027 Mi Asset located in: Lake Worth, TX	971	2007 Ford F-750 XL 4x2 Water Truck S/N: 3FRWF75RX7V441258 C/W: Cat C7 6 Cylinder 7.2 L Diesel 230 hp Engine, 2006 US EPA Label, 5138.2 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, Aluminum Front Wheels, 11R22.5, Spring Suspension, 178 in Wheelbase, PTO, Tiger Steel Tank, Hydraulic Driven Pump, 7 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 176,955 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
972	2007 Ford F-750 4x2 Water Truck S/N: 3FRXF75N07V509486 C/W: Caterpillar 6 Cylinder Diesel Engine, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 162 in Wheelbase, PTO, Steel Tank, Berkeley PTO Driven Pump, 5 ft 5 in, Spray Bar, Rear Spray, Side Spray Usage: 19,377 Mi Asset located in: Lake Worth, TX	977	2000 Sterling A9513 4x2 Water Truck S/N: 2FWWJWDBXYAB94058 C/W: Cat C12 6 Cylinder 12 L Diesel Engine, 5610 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 12000 lb Front Axle, 22000 lb Rears, 34000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 23,621 Mi Asset located in: Lake Worth, TX	
973	2003 Ford F-650 XL 4x2 Water Truck S/N: 3FDNF65AX3MB00757 C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 hp Engine, 2002 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, Steel Tank, Berkeley PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 21,069 Mi Asset located in: Lake Worth, TX	978	1998 International 4700 4x2 Water Truck S/N: 1HTSCABN9WH510827 C/W: International T444E V8 7.3 L Diesel Engine, US EPA Label, 1166 Engine hrs, Spicer 6-Speed Manual Transmission, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft 8 in, Spray Bar, Front Spray, Rear Spray Usage: 15,286 Hr Asset located in: Lake Worth, TX	
974	2008 Ford F-650 2000 gal 4x2 Water Truck S/N: 3FRNF65A88V660849 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2007 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 11R22. 5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 17,325 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 17,325, TITLE SHOWS 40,000 Asset located in: Lake Worth, TX	980	1996 International 4700 4x2 Water Truck S/N: 1HTSCABN1TH276159 C/W: 6 Cylinder Diesel Engine, 9393 Engine h Automatic Transmission, 11R22.5 Front Tires 295/75R22.5 Rear Tires, Spring Suspension, 182 in Wheelbase, Steel Tank, Pump w/ Engir 8 ft, Spray Bar, Dribble Bar Usage: 233,739 Mi Asset located in: Lake Worth, TX 1990 Ford L8000F 2000 gal 4x2 Water Truck S/N: 1FTXR82A2LVA15969 C/W: Ford 6 Cylinder 7.8 L Diesel 210 hp Engine, Manual Transmission, 9000 lb Front	
975	2005 Ford F-650 XL 2000 gal 4x2 Water Truck S/N: 3FRNF65905V181715 C/W: Cat C7 6 Cylinder 7.2 L Diesel 350 hp Engine, 2005 US EPA Label, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 10R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, PTO, Niece 2000 gal Steel Tank, PTO Driven Pump, 7 ft, Spray Bar, Front Spray, Rear Spray Usage: 45,392 Mi Asset located in: Lake Worth, TX		11R22.5, Spring Suspension, PTO, Steel Tank, PTO Driven Spray Bar, Water Cannon, From Spray Usage: 457,293 Mi Asset located in: Lake Worth Suspension, On gal Steel ay Bar, Front P81 2014 Freightliner M2 106 4x2 Truck S/N: 3ALACXDT3EDFV6933 C/W: Cummins ISB 6.7 L Dies	Usage: 457,293 Mi Asset located in: Lake Worth, TX 2014 Freightliner M2 106 4x2 Propane Tanker Truck S/N: 3ALACXDT3EDFV6933 C/W: Cummins ISB 6.7 L Diesel 280 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust
976	2001 International 4700 4x2 Water Truck S/N: 1HTSCAAM31H382229 C/W: International 6 Cylinder Diesel Engine, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, Steel, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, Hose Reel, Rear Spray Usage: 138,204 Mi Asset located in: Lake Worth, TX		Fluid, Allison 3500 6-Speed Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 6.14:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 207 in Wheelbase, Westmor 3200 gal Steel Tank, 2 Reels Usage: 302,437 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
982	2019 Hino 338 2600 gal 4x2 Fuel Truck S/N: 5PVNV8JV1K4S58832 C/W: Hino J08E-VB 6 Cylinder 469 cid 260 hp	СНОІС	E OF 2 - Lot #'s: 986, 987
	Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12537 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 197 in Wheelbase, PTO, 2600 gal Aluminum Tank, 3 Compartments, 2 Reels Usage: 274,979 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	986	2015 Ford F-550 4x4 Fuel and Lube Truck S/N: 1FDUF5HT8FEB16131 C/W: V8 6.7 L Diesel 309 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 162 in Wheelbase, 10 ft 10 in Body, (2) Oil Tanks, (5) Hose Reels, Metered Nozzles, Oil Recovery System, AirnArc 150 Gasoline Generator Set, Ingersoll-Rand Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 172,086 Mi
983	2014 Ram 5500 4x2 Lube Truck		Asset located in: Lake Worth, TX
	S/N: 3C7WRMBL1EG241604 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb		E OF 1 - Lot #'s: 987
	GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, 11 ft Body, (3) Oil Tanks, (4) Hose Reels, Metered Nozzles, Air Hose Reel, Vanair Air N Arc 150 All-In-One Power System; EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 202,597 Mi Asset located in: Lake Worth, TX	987	2015 Ford F-550 4x4 Fuel and Lube Truck S/N: 1FDUF5HT5FEA45745 C/W: V8 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in
984	2016 Freightliner M2 106 1000 gal 4x2 Fuel and Lube Truck S/N: 3ALACXDT1GDGY4896 C/W: Cummins ISB 6 Cylinder 6.7 L 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 14852 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.00:1 Axle Ratio, 33000.0 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 2008 1000 gal Steel Tank, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY		Wheelbase, CTEC 12 ft Body, (2) 0il Tanks, (6) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, NAPA 82133GTH 20 cfm Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROMSUNSTATE-EQUIPMENT Usage: 129,968 Mi Asset located in: Lake Worth, TX
			E OF 2 - Lot #'s: 988, 989
	Usage: 269,399 Mi Notes: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Asset located in: Lake Worth, TX	S/N: 1FDUF5GT4EEB705 C/W: V8 Diesel Engine, R Exhaust Fluid, Automatic lb Front Axle, 14706 lb Ro Steel, 225/70R19.5, Sprin Wheelbase, 11 ft Body, (Metered Nozzles, Vanair Compressor, Air Hose Re EQUIPMENT-FROM-SUN Usage: 163,834 Mi	2014 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT4EEB70543 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR,
985	2011 Peterbilt 337 1000 gal 4x2 Fuel and Lube Truck S/N: 2NP2HN7X5BM119419 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 300 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 19886 Engine hrs, Eaton Fuller		Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft Body, (4) Hose Reels, Metered Nozzles, Vanair Gasoline Air Compressor, Air Hose Reel, Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
	Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 4.33:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 16 ft 6 in Body, (2) 1000 gal Diesel Tank, (9) Oil Tanks, (10) Hose Reels, Metered Nozzles, Grease Barrel, Hydraulic Air Compressor, Air Hose Reel Usage: 203,370 Mi Asset located in: Lake Worth, TX	989	2013 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT9DEA86667 C/W: 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 14 ft 4 in Body, (1) Diesel Tank, Metered Nozzles, Ingersoll-Rand Air Compressor, Air Hose Reel, Miller Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 120,748 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
990	2024 Peterbilt 567 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1XPCP4EX2RD669008 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 18-Speed Manual Transmission, 20000 lb Front Axle, 66280 lb Rears, 80000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 273 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 696 Mi	994	2001 Peterbilt 379 8x4 Tri/A Day Cab Truck Tractor S/N: 1XP5PBEXX1D567716 C/W: Cat C15 6 Cylinder 15.2 L 475 hp Engine, Engine Brake, Eaton Fuller RTLO-16918B 18- Speed Manual Transmission, Differential Lock, 14060 lb Front Axle, 63000 lb Rears, Spicer DS463P Drive Axles, 3.90:1 Axle Ratio, 77060 lb GVWR, Air Ride Cab, 385/65R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 656,865 Mi Asset located in: Lake Worth, TX
991	Asset located in: Lake Worth, TX 2013 Peterbilt 389 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1XPXP4EX8DD177786 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 600 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20678.2 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Transmission, Double Differential Locks, 20000 lb Front Axle, 60400 lb Rears, 80000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5	995	2009 Mack CHU613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M2AN07Y39N003780 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 16784 Engine hrs, Mack MAXITORQUE 18-Speed Manual Transmission, 11R24.5, Air Lift Tag Axle, Camelback Spring Suspension, Air Sliding 5th Wheel, Rolling Tailboard, Dual Fuel Tanks Usage: 258,896 Mi Asset located in: Lake Worth, TX
	Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 265 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 461,474 Mi Asset located in: Lake Worth, TX	995A 996	2008 Mack CHU613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M1AN07Y98N002197 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, 6242 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle,
992	2013 Kenworth T800 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1XKDP4EX0DJ358004 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 550 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18818 Engine hrs, Engine Brake, Eaton Fuller 8-Speed Manual		44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, 243 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 591,040 Mi Asset located in: Lake Worth, TX
	Transmission, Double Differential Locks, 20000 lb Front Axle, 66000 lb Rears, 4.10:1 Axle Ratio, 80000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Double Frame, 8-Bag Air Ride Suspension, 258 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,162 Mi Asset located in: Lake Worth, TX		2007 Mack CHN613 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1M1AJ07Y57N007228 C/W: Mack AC 6 Cylinder 11.9 L Diesel 460 hp Engine, 2005 US EPA Label, 13255 Engine hrs, Engine Brake, Mack Maxitorque 18-Speed Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Twin Y
993	2013 Peterbilt 579 8x4 Tri/A Day Cab Truck Tractor S/N: 1XPBD49X9DD193833 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20865.5 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Lift Pusher Axle, Paccar Air Ride Suspension, 244 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 585,366 Mi		Air Ride Suspension, 254 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT FROM-WATKINS-CONSTRUCTION Usage: 272,150 Mi Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 997 2021 Peterbilt 389 8x4 Tri/A Sleeper Truck 999 2008 Western Star 4900 8x4 Tri/A Sleeper Tractor **Truck Tractor** S/N: 1XPXP4EX9MD740781 S/N: 5KJNALAV48PZ19813 C/W: Cat C15 6 Cylinder 14.6 L Diesel 550 hp C/W: Cummins X15 6 Cylinder 15 L Diesel 605 Engine, Engine Brake, Eaton Fuller RTLOhp Engine, 2020 US EPÁ Label, Requires Diesel 22918B 18-Speed Manual Transmission, 20000 lb Front Axle, 66000 lb Rears, 4.56:1 Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 20000 lb Front Axle Ratio, 78150 lb GVWR, Air Ride Cab, 40 in Axle, 66000 lb Rears, 80000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Mid Roof Sleeper Cab, Aluminum Wheels, 425 Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual /65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Airliner Steering Boxes, Air Ride Suspension, Air Sliding Air Ride Suspension, 265 in Wheelbase, Air 5th Wheel, Headache Rack, Dual Fuel Tanks Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: Not Available Usage: 777,671 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 997A 2021 Western Star 4900EX 8x4 Heavy Haul Tri 1000 2020 Peterbilt 389 6x4 T/A Day Cab Truck /A Sleeper Truck Tractor Tractor S/N: 5KJNABD18MPMG3713 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 S/N: 1XPXD49X4LD636684 hp Engine, 2020 US EPA Label, Requires Diesel C/W: Cummins X15 6 Cylinder 15 L Diesel 500 Exhaust Fluid, 13055.3 Engine hrs, Eaton Fuller hp Engine, 2019 US EPA Label, Requires Diesel RTLO-20918B 18-Speed Manual Transmission, 18000 lb Front Axle, 66000 lb Rears, Meritor RT-Exhaust Fluid, 13970 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 46-160P Drive Axles, 3.73:1 Axle Ratio, 83300 Double Differential Locks, 12000 lb Front Axle, lb GVWR, 82 in Mid Roof Sleeper Cab, 425 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 240 in Wheelbase, Headache /65R22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Airliner Air Ride Rack, Dual Fuel Tanks Suspension, 291 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 391,604 Mi Usage: 295,587 Mi Asset located in: Lake Worth, TX Notes: LOCATED-IN-FORT-WORTH-TX PER 1001 2019 Peterbilt 389 6x4 T/A Day Cab Truck THE DEALER ACTUAL MILEAGE IS HIGHER THAN SHOWING ON ODO AND ECM - TRUE Tractor MILEAGE IS UNKNOWN S/N: 1XPXD49X0KD266266 C/W: Cummins X15 6 Cylinder 15 L Diesel 485 Asset located in: Lake Worth, TX hp Engine, 2012 US EPÁ Label, Requires Diesel 998 2015 Kenworth T800 Wide Hood 8x4 Tri/A Exhaust Fluid, 17028 Engine hrs, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Sleeper Truck Tractor 11R24.5, Air Ride Suspension, 238 in S/N: 1XKDP4TX3FJ427032 Wheelbase, Air Sliding 5th Wheel C/W: Cummins ISX15 15.0 L Ultra Low Sulfur Usage: 470,871 Mi Diesel 550 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 9997 Engine hrs, Asset located in: Lake Worth, TX Engine Brake, Eaton Fuller RTLO-18918B 18-Speed Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, Dana D46-170H Drive CHOICE OF 6 - Lot #'s: 1002, 1003, 1004, 1005, 1006, 100 Axles, 3.91:1 Axle Ratio, 86000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 1002 2018 Peterbilt 389 6x4 T/A Day Cab Truck 285/75R24.5 Rear Tires, Air Lift Pusher Axle, **Tractor** Dual Steering Boxes, Double Frame, S/N: 1XPXD49X0JD468877

C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11115 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, Paccar Air Ride Suspension, 218 in Wheelbase, Air Sliding 5th Wheel

Usage: 239,179 Mi

Asset located in: Lake Worth, TX

Hendrickson Primaax EX Air Ride Suspension, 278 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FRÓM-A-PRIMORIS-SERVICES-CORP-COMPANY

Usage: 356,920 Mi

Notes: EOUIPMENT FROM A PRIMORIS

SERVICES CORP COMPANY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1003	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X3JD468940 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12339 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 216 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 251,546 Mi	1007	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X4JD468879 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12212 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 292,060 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1009	2012 Peterbilt 389 6x4 T/A Day Cab Truck
1004	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X1JD468922 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12890 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 254,950 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XPXDP9X2CD158752 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 17118.9 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Trac Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 350,526 Mi Asset located in: Lake Worth, TX
1005	2018 Peterbilt 389 6x4 T/A Day Cab Truck	1010	·
	Tractor S/N: 1XPXD49X0JD468958 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11930 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 216 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Air Sliding 5th Wheel Usage: 261,844 Mi Asset located in: Lake Worth, TX	1010	2012 Peterbilt 388 6x4 T/A Day Cab Truck Tractor S/N: 1XPWDP0X1CD140235 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18806.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, 11R24.5, Air Trac Air Ride Suspension, 214 in Wheelbase, Dual Fuel Tanks Usage: 306,786 Mi Asset located in: Lake Worth, TX
1006	2018 Peterbilt 389 6x4 T/A Day Cab Truck		E OF 4 - Lot #'s: 1011, 1012, 1013, 1014
	Tractor S/N: 1XPXD49X0JD468930 C/W: Cummins X15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 12410.3 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel Usage: 282,762 Mi Asset located in: Lake Worth, TX	1011	2016 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTD40X3GD334935 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5172.2 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 181,470 Mi

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1012	2016 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTD40X5GD334936 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 99,798 Mi Notes: .		E OF 9 - Lot #'s: 1016, 1017, 1018, 1019, 1020, 022, 1023, 1024 2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD40X5LR369029 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 268 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1013	Asset located in: Humble, TX 2016 Peterbilt 367 6x4 T/A Day Cab Truck Tractor	1017	Usage: 282,374 Mi Asset located in: Lake Worth, TX 2020 Kenworth T800 6x4 T/A Day Cab Truck
	S/N: 1XPTD40X7GD334940 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7220.5 Engine hrs, Engine Brake, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, 11R24.5, Air Trac Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 131,902 Mi Asset located in: Humble, TX		Tractor S/N: 3WKDD40X9LF369053 C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 525,807 Mi Asset located in: Lake Worth, TX
1014	2016 Peterbilt 367 6x6 T/A Day Cab Truck Tractor S/N: 1XPTD40X7GD334937 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5526.6 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th	1018	2020 Kenworth T800 T/A Day Cab Truck Tractor
			S/N: 1XKDD40X2LR369022 Usage: Not Available Asset located in: Lake Worth, TX
		1019	2020 Kenworth T800 T/A Day Cab Truck Tractor S/N: 3WKDD40X4LF369042 Usage: Not Available Asset located in: Lake Worth, TX
	Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 208,518 Mi Notes: . Asset located in: Humble, TX	1020	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X8LF369044 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 21597.7 Engine hrs, Eaton Fuller
1015	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X1LF369046 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 268 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 297,971 Mi Asset located in: Lake Worth, TX		FAO-16810C 10-Speed Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, Dana D46-170 Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 216 in Wheelbase, PTO, Blower, Dual Fuel Tanks Usage: 363,166 Mi Asset located in: Lake Worth, TX

			r age 80 01 307
Lot #	Details	Lot #	Details
1021	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X2LF369055 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 18503.8 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 243 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 262,049 Mi Asset located in: Lake Worth, TX	CHOICE 1025	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X7KF257267 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23462.2 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 243 in
1022	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD40X1LR369030		Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 358,214 Mi Asset located in : Lake Worth, TX
	C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 19464 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 305,184 Mi Asset located in: Lake Worth, TX	1026	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X9KF257268 C/W: Cummins X15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 23630.9 Engine hrs, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 279,656 Mi
1023	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor		Asset located in: Lake Worth, TX
1024	S/N: 1XKDD40X2LR369036 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10215 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, 8-Bag Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 112,632 Mi Asset located in: Lake Worth, TX		2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X7KF369101 C/W: Cummins ISX15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19647 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 338,611 Mi Asset located in: Lake Worth, TX
. 02 1	Tractor	1028	2019 Kenworth T800 6x4 T/A Day Cab Truck
	S/N: 3WKDD40XXLF369059 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9057 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, 8-Bag Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		Tractor S/N: 3WKDD40X6KF257275 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 16403.1 Engine hrs, Engine Brake, Eaton UltraShift Plus Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, AG400 8-Bag Air Ride Suspension, 243 in Wheelbase, Blower, Dual Fuel Tanks Usage: 237,353 Mi

Usage: 100,288 Mi

Lot #	Details	Lot #	Details
1029	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor	1032	2014 Kenworth T800 6x4 T/A Day Cab Truck Tractor
	S/N: 3WKDD40X7KF369082 C/W: Cummins X15 V10 15 L 450 hp Engine, 2018 US EPA Label, CARB Compliant, 19985 Engine hrs, Eaton Fuller UltraShift Plus 18- Speed Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Aluminum Wheels, 11R24.5, AG400 8-Bag Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Blower Usage: 298,935 Mi Asset located in: Lake Worth, TX		S/N: 1XKDDP9X9EJ404502 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11282 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Differential Lock, 12350 Ib Front Axle, 40000 Ib Rears, Spicer DSP41 Drive Axles, 3.70:1 Axle Ratio, 52350 Ib GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airglide Suspension, 185 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks
1030	2019 Kenworth T800 6x4 T/A Day Cab Truck		Usage: 282,261 Mi
	Tractor S/N: 3WKDD40XXKF369089		Asset located in: Lake Worth, TX
	C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19786 Engine hrs, Engine Brake, Automatic Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, Dana D46-172 Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 325,018 Mi Asset located in: Lake Worth, TX	1033	2014 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9XXEJ367542 C/W: Paccar 6 Cylinder 12.9 L 455 hp Engine, 2012 US EPA Label, 13028 Engine hrs, Eaton Fuller FO-16E313A-MHP ULT Automatic Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 295/75R22. 5, 8-Bag Air Ride Suspension, 194 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 297,728 Mi Asset located in: Humble, TX
1030A	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor	1034	2013 Kenworth T800 T/A Day Cab Truck
	S/N: 3WKDD40X5KF369100 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 6495 kg Front Axle, 20866 lb Rears, 27361 kg GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride		Tractor S/N: 1XKDD40X9DJ345459 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
	Suspension, 189 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 336,440 Mi		
		CHOICI	E OF 2 - Lot #'s: 1035, 1036
1021	Asset located in: Lake Worth, TX 2014 Kenworth T900 6v4 T/A Day Cab Truck	1035	2012 Kenworth T800 6x4 T/A Day Cab Truck
1031	2014 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9X7EJ387103 C/W: Paccar MX 6 Cylinder 12.9 L Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 15503 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 324,545 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKDDP9X2CJ335276 C/W: Paccar MX 6 Cylinder 12.9 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18030 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.55:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 343,666 Mi

Lot #	Details	Lot #	Details
1036	2012 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9X0CJ335275 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 181 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, Dana Drive Axles, 3.55:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Suspension, 187 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 297,724 Mi Asset located in: Lake Worth, TX	1039	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X2GJ495377 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Detroit Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 293,721 Mi Asset located in: Lake Worth, TX
1037		1040	2016 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X1GJ495371 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 276,776 Mi Asset located in: Lake Worth, TX
	46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.89:1 Axle Ratio, 60321 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Neway Air Ride Suspension, 209 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: 324,740 Mi Asset located in: Lake Worth, TX	1041	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9XXGJ486765 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR,
1037A	Tractor S/N: 1XKZDP9X1JJ215858 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8375 Engine hrs, Engine		Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 269,329 Mi Asset located in: Lake Worth, TX
	Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel Usage: 237,444 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1042	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X0GJ495376 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Double
CHOICE	E OF 6 - Lot #'s: 1038, 1039, 1040, 1041, 1042, 1043		Frame, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 280,242 Mi
1038	2016 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9XXGJ495370 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 241,499 Mi Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 1043 2016 Kenworth T880 6x4 T/A Day Cab Truck **Tractor** CHOICE OF 3 - Lot #'s: 1046, 1047, 1048 S/N: 1XKZDP9X3GJ495372 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires 1046 2022 Peterbilt 567 6x4 T/A Day Cab Truck Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Tractor FRO-15210C Manual Transmission, 13200 lb S/N: 1XPCD49X8ND788534 Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2021 US EPA Label, Requires Diesel 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase, Air Sliding 5th Wheel, Headache Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Rack, EQUIPMENT-FROM-SUNSTATE-Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride **EQUIPMENT** Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 226 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 352,092 Mi Asset located in: Lake Worth, TX Usage: 140,650 Mi Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1044, 1045 1047 2022 Peterbilt 567 6x4 T/A Day Cab Truck Tractor 1044 2015 Kenworth T880 6x4 T/A Day Cab Truck S/N: 1XPCD49X4ND788532 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, US EPA Label, Requires Diesel S/N: 1XKZDP9XXFJ445423 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller 430 hp Engine, 2014 US EPA Label, Requires Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Diesel Exhaust Fluid, 15520 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Aluminum Wheels, 11R24.5, Air Ride Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks GVWR, Air Ride Cab, Aluminum Front Wheels, Usage: 152,789 Mi 11R22.5, 8-Bag Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Headache Asset located in: Lake Worth, TX Rack, EQUIPMENT-FROM-SUNSTATE-2022 Peterbilt 567 6x4 T/A Day Cab Truck 1048 **EQUIPMENT** Tractor Usage: 376,184 Mi S/N: 1XPCD49X6ND788533 Asset located in: Lake Worth, TX C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2021 US EPA Label, Requires Diesel 1045 2015 Kenworth T880 6x4 T/A Day Cab Truck Exhaust Fluid, 4410 Engine hrs, Engine Brake, Tractor Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. S/N: 1XKZDP9X8FJ425865 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2014 US EPA Label, Requires 5, Air Trac Air Ride Suspension, 226 in Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Wheelbase, Air Sliding 5th Wheel, Dual Fuel FRO-15210C 10-Speed Manual Transmission, Tanks 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Usage: 106,800 Mi Axle Ratio, 53200 lb GVWR, Air Ride Cab, Asset located in: Lake Worth, TX Aluminum Front Wheels, 11R22.5, Air Ride

Suspension, 187 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT

Usage: 316,151 Mi Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1049, 1050

1049 2020 Peterbilt 567 6x4 T/A Day Cab Truck **Tractor**

S/N: 1NPCD40X8LD649153 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2019 US EPÁ Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Dual Steering Boxes, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks

Usage: 198,766 Mi

Lot #	Details	Lot #	Details
1050	2019 Peterbilt 567 6x4 T/A Day Cab Truck Tractor S/N: 1XPCD40X7KD611272 C/W: Cummins X15 6 Cylinder 15 L Diesel 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 239,603 Mi Asset located in: Lake Worth, TX	1055	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X3FD262701 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 27922 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, Blower, Dual Fuel Tanks Usage: 719,738 Mi Asset located in: Lake Worth, TX
СНОІС	E OF 4 - Lot #'s: 1051, 1053, 1054, 1055	1056	2014 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X7ED225682
1051	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X6GD332564 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27335.9 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube Usage: 596,995 Mi Notes: ADDITIONAL COMPONENTS		C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2013 US EPA Label, 35544 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 203 in Wheelbase, Auto Lube Usage: 620,451 Mi Asset located in: Lake Worth, TX
		1056A	2012 Peterbilt 367 T/A Day Cab Truck Tractor S/N: 2XPTD40X9CM137840 Usage: 344,254 Mi Asset located in: Lake Worth, TX
	AVAILABLE IN OFFICE - MAIN KEY		
1053	Asset located in: Lake Worth, TX 2016 Peterbilt 365 6x4 T/A Day Cab Truck	CHOICE OF 8 - Lot #'s: 1058, 1059, 1060, 1061, 10 1063, 1064, 1065	
	Tractor S/N: 1XPSD79X4GD332529 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24210 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 206 in Wheelbase, PTO, Blower, Auto Lube Usage: 565,546 Mi Asset located in: Lake Worth, TX	1058 2020 Freigh Truck Tracto S/N: 3AKJG C/W: Detroit hp Engine, 2 Exhaust Flui Allison 4700 13300 lb Fro 46-160P Dri lb GVWR, Ai	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV2LDLZ5581 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6973 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, 13300 lb Front Axle, 46000 lb Rears, Meritor RT- 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, Steel, 11R24.5, Hendrickson Air Ride Suspension, 196 in
1054	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X9FD262699 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20820 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 206 in Wheelbase, PTO, Blower, Auto Lube Usage: 553,424 Mi Asset located in: Lake Worth, TX		Wheelbase, Air Sliding 5th Wheel Usage: 109,108 Mi Asset located in: Lake Worth, TX
		1059	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV4LDLZ5582 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7090.33 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 109,592 Mi

Lot #	Details	Lot #	Details
1060	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV6LDLZ5583 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8086 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 114,295 Mi Asset located in: Lake Worth, TX	1064	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV5LDMF6935 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7764 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 144,087 Mi Asset located in: Lake Worth, TX
1061	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV8LDMF6945 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7577 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, 13300 lb Front Axle, 46000 lb Rears, Meritor RT- 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 125,283 Mi Asset located in: Lake Worth, TX	1003	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV0LDMF6938 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8251.39 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 146,736 Mi Asset located in: Lake Worth, TX
1062	2020 Freightliner SD122 6x4 T/A Day Cab		Asset Isolated III. Lake Worth, TA
	Truck Tractor S/N: 3AKJGNDV6LDMF6944 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7652 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 137,436 Mi Asset located in: Lake Worth, TX		E OF 8 - Lot #'s: 1066, 1067, 1068, 1069, 1070, 072, 1073 2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV2LDMF6942 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6915 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab,
1063	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor		11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 149,353 Mi
	S/N: 3AKJGNDV3LDMF6934 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525		Asset located in: Lake Worth, TX
	hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8183 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT- 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 139,306 Mi Asset located in: Lake Worth, TX	1067	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDVXLDMF6946 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7122.12 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 158,266 Mi

Details Lot # **Details** Lot # 1068 2020 Freightliner SD122 6x4 T/A Day Cab 1072 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor Truck Tractor** S/N: 3AKJGNDV4LDMF6943 S/N: 3AKJGNDV7LDMF6936 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8575.57 Engine hrs, Engine Brake, Allison 4700 RDS Automatic C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8247 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Axles, 4.30:1 Axle Ratio, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Wheelbase, Air Sliding 5th Wheel Usage: 206,153 Mi Usage: 159,984 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1073 2020 Freightliner SD122 6x4 T/A Day Cab 1069 2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor **Truck Tractor** S/N: 3AKJGNDV9LDMF6937 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel S/N: 3AKJGNDV0LDMF6941 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8897.09 Engine hrs, Engine Exhaust Fluid, 7204 Engine hrs, Engine Brake, Brake, Allison 4700 RDS Automatic Allison 4700 RDS 6-Speed Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24. Ride Cab, All Steel, 11R24.5, Hendrickson Air 5 Rear Tires, Hendrickson Air Ride Suspension, Ride Suspension, 196 in Wheelbase, Air Sliding 196 in Wheelbase, Air Sliding 5th Wheel 5th Wheel Usage: 212,117 Mi Usage: 163,146 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1074 2019 Freightliner Coronado 122SD 6x4 T/A 1070 2020 Freightliner SD122 6x4 T/A Day Cab **Day Cab Truck Tractor** Truck Tractor S/N: 3AKJGNDR5KDKK3918 S/N: 3AKJGNDV9LDMF6940 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7512.45 Engine hrs, Engine hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12990 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Rears, 3.58:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 210 in Wheelbase, PTO, Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride Wet Kit, Dual Fuel Tanks Suspension, 196 in Wheelbase, Air Sliding 5th Usage: 497,607 Mi Wheel Asset located in: Lake Worth, TX Usage: 166,473 Mi Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1075, 1076 1071 2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor 1075 2014 Freightliner Coronado 122 6x4 T/A Day S/N: 3AKJGNDV2LDMF6939 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 **Cab Truck Tractor** hp Engine, 2019 US EPA Label, Requires Diesel S/N: 3AKJGNDV4EDFU3235 Exhaust Fluid, 8294 Engine hrs, Engine Brake, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 Allison 4700 RDS Automatic Transmission, hp Engine, Requires Diesel Exhaust Fluid, 9972 Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 59300 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, lb GVWR, Air Ride Cab, 11R24.5, Hendrickson 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Air Ride Suspension, 196 in Wheelbase, Air Axles, 3.91:1 Axle Ratio, 52000 lb GVWR, 275 Sliding 5th Wheel Usage: 182,995 Mi /80R22.5, Airliner Air Ride Suspension, 202 in

Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Tanks

Usage: 210,817 Mi

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1076	2014 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGND64EDFT1921 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 18532 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner 4-Bag Air Ride Suspension, 224 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 394,360 Mi Asset located in: Lake Worth, TX	1080	2015 Western Star 4700 6x4 T/A Day Cab Truck Tractor S/N: 5KJJAVDV4FLGW9017 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 hp Engine, Requires Diesel Exhaust Fluid, 13494 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 3.91:1 Axle Ratio, 58000 lb GVWR, Air Ride Cab, 11R24.5, Airliner Air Ride Suspension, 210 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 325,533 Mi Asset located in: Lake Worth, TX
		1081	2016 Cat CT680L 6x4 T/A Day Cab Truck Tractor
1077	2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 1FVXFB00XBDBC0203 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks		S/N: 3HSKBTKTXGN379223 C/W: Cat CT13 6 Cylinder 12.4 L 475 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8172 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Hendrickson Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,040 Mi
	Usage: 669,379 Mi Asset located in : Lake Worth, TX	1082	2012 Cat CT660S 6x4 T/A Day Cab Truck Tractor
1078	2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 1FVXFB008BDBC0202 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 709,338 Mi		S/N: 1HTJGTKT7CJ635078 C/W: Cat CT13 6 Cylinder 13 L Diesel Engine, 2011 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 70000 lb GVWR, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, 241 in Wheelbase Usage: 123,545 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	СНОІСІ	E OF 2 - Lot #'s: 1083, 1084
CHOIC 1079	E OF 2 - Lot #'s: 1079, 1080 2015 Western Star 4700 6x4 T/A Day Cab Truck Tractor	1083	2017 International TranStar 8600 T/A Day Cab Truck Tractor S/N: 3HSHXSNRXHN412325 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 5KJJAVDV9FPGC9066 C/W: Detroit DD13 12.8 L Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 220 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 537,904 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	1084	2014 International 8600 6x4 T/A Day Cab Truck Tractor S/N: 1HSHXSJR4EH754607 C/W: Navistar N13 6 Cylinder 13 L Diesel Engine, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 169 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1085	2013 International 7500 6x4 T/A Day Cab Truck Tractor S/N: 1HSWPAZR8DJ239297 C/W: International International 570 6 Cylinder 9.3 L Diesel Engine, 2012 US EPA Label, 5501 Engine hrs, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, PTO, Wet Kit Usage: 28,123 Mi Asset located in: Lake Worth, TX E OF 4 - Lot #'s: 1086, 1087, 1088, 1089	1089	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X8PD875835 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3195 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Leaf Air Ride Suspension, 189 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 77,420 Mi Notes: . Asset located in: Humble, TX
1086	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X2PD889441 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2693 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 186 in Wheelbase, Wet Kit, Air Sliding 5th Wheel Usage: 54,153 Mi Notes:	1090	2020 Peterbilt 579 6x2 T/A Day Cab Truck Tractor S/N: 1XPBAK9X6LD656295 C/W: Paccar mx11 6 Cylinder 10.8 L Diesel Engine, 2019 US EPA Label, 9406 Engine hrs, Engine Brake, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,689 Mi Asset located in: Lake Worth, TX 2019 Peterbilt 579 6x4 T/A Day Cab Truck
1087	Asset located in: Humble, TX 2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X4PD889442 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3278 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 192 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 62,819 Mi	1091	Tractor S/N: 1XPBD49X5KD619305 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10474.6 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 19000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 153,131 Mi Asset located in: Lake Worth, TX
	Notes: . Asset located in: Humble, TX	1092	2022 Mack PI64T 6x4 T/A Day Cab Truck Tractor
1088	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X6PD875834 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2323 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Air Leaf Air Ride Suspension, 190 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 72,678 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT.		S/N: 1M1PN4GY9NM010092 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MDrive 12- Speed Automated Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Neway Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Asset located in: Humble, TX

Details Lot # **Details** Lot # 1093 2019 Mack AN64T 6x4 T/A Day Cab Truck 1098 2021 Freightliner Cascadia 116 6x4 T/A Day **Tractor Cab Truck Tractor** S/N: 1M1AN2GY6KM008144 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 S/N: 3AKJHTDV3MSMF5488 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US ÉPA Label, Requires Diesel hp Engine, 2020 US EPA Label, CARB Exhaust Fluid, 11664 Engine hrs, Engine Brake, Compliant, Requires Diesel Exhaust Fluid, 9731 Automated Transmission, 12000 lb Front Axle, Engine hrs, Engine Brake, Automated 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Transmission, 12000 lb Front Axle, 40000 lb Aluminum Outer Wheels, 295/75R22.5, Air Ride Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Suspension, 174 in Wheelbase Usage: 517,765 Mi Front Wheels, 295/75R22.5, Air Ride Suspension, 184 in Wheelbase Usage: 356,606 Mi Asset located in: Lake Worth, TX Notes: THIS UNIT RUNS BUT MAY HAVE 1094 2019 Mack AN64T 6x4 T/A Day Cab Truck DEFICIENCIES IN ITS POLLUTION CONTROL Tractor SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS S/N: 1M1AN4GY6KM003456 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2018 US EPA Label, Requires Diesel RESTORATION OF ALL POLLUTION CONTROL Exhaust Fluid, 15036 Engine hrs, Engine Brake, Mack mDrive Automatic Transmission, 12500 SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE lb Front Axle, 40000 lb Rears, 52500.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air PRIOR TO REMOVAL OF UNIT FROM YARD Ride Suspension, 189 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 743,483 Mi 1099 2019 Volvo VNL760 6x4 T/A Sleeper Truck Asset located in: Humble, TX **Tractor** 1095 2019 Mack Pinnacle 6x4 T/A Day Cab Truck S/N: 4V4NC9EH7KN193984 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires **Tractor** S/N: 1M1PN4GY4KM002736 Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2018 US ÉPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 70 in High Rise Sleeper Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 224 in Wheelbase, Air Wheels, 11R24.5, Air Ride Suspension, 227 in Sliding 5th Wheel, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: 480,468 Mi Tanks Usage: 429,136 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1100 2019 International LT625 6x4 T/A Day Cab 1096 2019 Freightliner Cascadia 126 6x4 T/A Day Truck Tractor **Cab Truck Tractor** S/N: 3HCDZAPR8KL194089 C/W: Cummins X15 505 6 Cylinder 15.0 L Diesel 505 hp Engine, 2018 US EPA Label, S/N: 1FUJHLDR2KLKW2362 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Requires Diesel Exhaust Fluid, 10422 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb Transmission, Differential Lock, 13300 lb Front GVWR, Air Ride Cab, Aluminum Wheels, 11R22. Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 53300 5, Air Ride Suspension, 199 in Wheelbase, PTO, lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Wet Kit, Air Sliding 5th Wheel, Headache Rack, **Dual Fuel Tanks** Airliner 4-Bag Air Ride Suspension, 183 in Usage: 171,523 Mi Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 621,528 Mi 1101 2018 Peterbilt 579 6x4 T/A Day Cab Truck Asset located in: Lake Worth, TX Tractor 1097 2019 Freightliner Cascadia 126 T/A Day Cab S/N: 1XPBDP9X1JD490933 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 Truck Tractor hp Engine, 2017 US ÉPA Label, Requires Diesel S/N: 3AKJHLDV5KSKE1227 Exhaust Fluid, Engine Brake, Paccar Automated C/W: PROFESSIONALLY-MAINTAINED-FLEET-Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 455/50R22.5 **VEHICLE-PAG** Usage: 460,195 Mi Asset located in: Lake Worth, TX Rear Tires, Paccar Air Ride Suspension, 168 in Wheelbase Usage: Not Available

Lot #	Details	Lot #	Details
1102	2017 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X1HD387523 C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19516 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 11R24.5, Paccar Air Ride Suspension, 192 in Wheelbase, PTO, Blower Usage: 731,511 Mi Asset located in: Lake Worth, TX	1106	2012 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHD49X2CD135202 C/W: Cummins ISX15 15.0 L Diesel 500 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 20630 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Trac Air Ride Suspension, 212 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 372,724 Mi Asset located in: Lake Worth, TX
СНОІС	E OF 3 - Lot #'s: 1103, 1104, 1105	1107	2018 Kenworth T680 6x4 T/A Day Cab Truck Tractor
1103	2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X5DD190441 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Leaf Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel		S/N: 1XKYD49X1JJ198747 C/W: Cummins X15 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19006 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, 8- Bag Air Ride Suspension, 187 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower Usage: 633,908 Mi Asset located in: Lake Worth, TX
	Usage: 783,395 Mi Asset located in : Humble, TX	1108	2015 Kenworth T680 6x2 T/A Day Cab Truck
1104	2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X7DD190442 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20012 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Leaf 4-Bag Air Ride Suspension, 186 in		Tractor S/N: 1XKYAP9X7FJ437901 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 34000 lb Rears, 3.42:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22. 5, Flex Air Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: 575,781 Mi Asset located in: Lake Worth, TX
	Wheelbase, Air Sliding 5th Wheel Usage: 382,740 Mi	1109	2012 Kenworth T660 T/A Day Cab Truck Tractor
1105	Asset located in: Humble, TX 2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor	_	S/N: 1XKAD49X8CJ297036 Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 1XPHDP9X9DD190443 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Leaf Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel Usage: 346,321 Mi Asset located in: Humble, TX	1110	2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X9CJ297000 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 22628 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 724,564 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1111	2015 Kenworth T370 T/A Day Cab Truck Tractor S/N: 2XKHAJ8XXFM458197 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		CHOICE OF 2 - Lot #'s: 1116, 1117 1116 2014 Mack CXU613 6x4 T/A Day Cab Truck	
1112	Usage: 212,393 Hr Asset located in: Lake Worth, TX		Tractor S/N: 1M1AW02Y4EM043164	
	112 2017 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1HM081245 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 4592 Engine hrs, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 204 in Wheelbase Usage: 569,651 Mi Asset located in: Humble, TX		C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diese Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 190 in Wheelbase Usage: 484,651 Mi Asset located in: Humble, TX	
		1117	2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y3EM036867 C/W: Mack 6 Cylinder 10.8 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission,	
	E OF 3 - Lot #'s: 1113, 1114, 1115	12350 lb Front Axl GVWR, Air Ride Ca Ride Suspension, 2 Usage: 384,415 Mi	12350 lb Front Axle, 20000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, Air Ride Suspension, 222 in Wheelbase Usage: 384,415 Mi	
1113	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor		Asset located in: Lake Worth, TX	
	S/N: 1M1AW09YXGM056302 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 174,528 Mi Asset located in: Lake Worth, TX	1118	2012 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y8CM017308 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 11235 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Twin Y Air Ride Suspension, 182 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel	
1114	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor		Usage: 300,710 Mi Asset located in: Lake Worth, TX	
	S/N: 1M1AW09Y6GM056281 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 7091 Engine hrs, Engine Brake, Mack 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, 4-Bag Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 192,351 Mi Asset located in: Lake Worth, TX	1119	2018 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07YXJM027640 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 590,377 Mi	
1115	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y7FM048675 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26801 Engine hrs, Engine Brake, Mack MDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295/75R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 271 385 Mi		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Usage: 271,385 Mi

			1 age 76 of 307
Lot #	Details	Lot #	Details
CHOICE 1121	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y0EM015773 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 32141 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Hendrickson Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks Usage: 731,351 Mi	1126 CHOIC	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y5DM014066 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 31299 Engine hrs, Engine Brake, Mack 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks Usage: 767,495 Mi Asset located in: Lake Worth, TX
1122	Asset located in: Lake Worth, TX 2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07YXEM016719 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 478,839 Mi Asset located in: Lake Worth, TX	1127	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y8DM011473 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 536,413 Mi
1123	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y5EM015669 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Mack Automatic Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, 11R24.5, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 569,098 Mi Asset located in: Lake Worth, TX 2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor	1128	Asset located in: Lake Worth, TX 2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y5DM014492 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MAXITORQUE 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 488,617 Mi
	S/N: 1M1AN07Y0DM013475 C/W: Mack MP8 6 Cylinder 12.7 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 22679 lb GVWR, 11R24.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 847,795 Mi Asset located in: Lake Worth, TX	1129	Asset located in: Humble, TX 2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y1DM014095 C/W: Mack MP8 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 29537 Engine hrs, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 747,931 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

			Page 99 of 567
Lot #	Details	Lot #	Details
1130	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y1DM013920 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack MaxiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, 11R24.5, Spring over Walking Beam Suspension, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: 211,417 Mi Asset located in: Lake Worth, TX	1137	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y7CM011172 C/W: Mack MP8 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18044 Engine hrs, Engine Brake, Mack 8-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, 4-Bag Air Ride Suspension, 219 in Wheelbase, Dual Fuel Tanks Usage: 710,969 Mi Asset located in: Lake Worth, TX
1132	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07YXCM010660 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MultiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 97,753 Mi Asset located in: Lake Worth, TX	-1138	2011 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y6BM006995 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 963 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Twin Y Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 333,241 Mi Asset located in: Lake Worth, TX
1133	E OF 3 - Lot #'s: 1133, 1136, 1137 2012 Mack CHU613 6x4 T/A Day Cab Truck	СНОІСІ	E OF 2 - Lot #'s: 1139, 1140
	Tractor S/N: 1M1AN07Y8CM008989 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Mack maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 511,996 Mi Asset located in: Lake Worth, TX	1139	2019 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDR8KSKM6301 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16826 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Suspension, 178
1136	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y3CM009662 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 455		in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 760,027 Mi Asset located in: Lake Worth, TX
	hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28676 Engine hrs, Mack 8-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Mack Drive Axles, 50000 lb GVWR, Air Ride Cab, 11R24.5, Twin Y Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 732,133 Mi	1140	2018 Freightliner Cascadia 125 T/A Day Cab Truck Tractor S/N: 1FUGGEDV1JLJN6683 Usage: 583,000 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1141	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV7JSJK4542 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10452 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 393,960 Mi	1145	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV7JSJH2022 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 520,949 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
		СНОІС	E OF 3 - Lot #'s: 1146, 1147, 1148
CHOIC 1142	E OF 3 - Lot #'s: 1142, 1143, 1144 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV6JDJN8606	1146	2017 Freightliner Cascadia 125 T/A Day Cab Truck Tractor S/N: 3AKJGEDV9HSJB4181 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Brake, Detroit DT12-OB-1650 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Air Assist Front Suspension, Airliner Air Ride Suspension, 183 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 870,330 Mi Asset located in: Lake Worth, TX	1147	2017 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 1FUGGEDV1HLJF1652 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel
1143	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor		Usage: 485,070 Mi Asset located in : Humble, TX
	S/N: 3AKJGEDV0JDJN8598 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OB- 1650HD 12-Speed Automated Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22. 5, Air Assist Front Suspension, Air Ride Suspension, 183 in Wheelbase, PTO Usage: 852,283 Mi Asset located in: Lake Worth, TX	1148	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDVXGSGV9490 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 596,350 Mi
1144	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDR1JDJW5319 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 9924 Engine hrs, Engine Brake, Detroit DT12-OA- 1650 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks		Asset located in: Lake Worth, TX

Dual Fuel Tanks Usage: 667,742 Mi

Details Lot # **Details** Lot # CHOICE OF 2 - Lot #'s: 1149, 1150 CHOICE OF 2 - Lot #'s: 1154, 1155 1154 1149 2016 Freightliner Cascadia 125 6x2 T/A Day 2019 Freightliner Cascadia 113 6x4 T/A Day **Cab Truck Tractor Cab Truck Tractor** S/N: 3AKGGEDV4GDHC4943 S/N: 1FUJGBDV3KLKT7979 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Fluid, Engine Brake, Eaton Fuller FR-13571 Engine hrs, Engine Brake, Automated 14210B 10-Speed Manual Transmission. Transmission, 12000 lb Front Axle, 40000 lb 12000 lb Front Axle, 40000 lb Rears, 2.50:1 Rears, 5.25:1 Axle Ratio, 52000 lb GVWR, Air Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 184 in Wheelbase, PTO, Air Sliding 5th Wheel Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 850,687 Mi Usage: 535,686 Mi Asset located in: Lake Worth, TX Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 2015 Freightliner Cascadia 125 6x4 T/A Day 1150 Asset located in: Humble, TX **Cab Truck Tractor** 1155 2019 Freightliner Cascadia 113 6x4 T/A Day S/N: 1FUJGED63FLGD5692 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 Cab Truck Tractor hp Engine, 2014 US EPA Label, Requires Diesel S/N: 1FUJGBDV5KLKT7983 Exhaust Fluid, 15861 Engine hrs, Engine Brake, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 Eaton Fuller 10-Speed Manual Transmission, hp Engine, Requires Diesel Exhaust Fluid, Meritor MT-40-14X Drive Axles, 3.55:1 Axle 12590 Engine hrs, Engine Brake, Eaton Fuller Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum FAO-16810C Automated Transmission, 12000 Wheels, 11R22.5, Airliner Suspension, 178 in lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb Wheelbase, Air Sliding 5th Wheel, Dual Fuel GVWR, Air Ride Cab, Aluminum Wheels, 275 Usage: 570,528 Mi /80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Ride Suspension, 184 in Asset located in: Lake Worth, TX Wheelbase, Air Sliding 5th Wheel 1152 2013 Freightliner Cascadia 125 6x4 T/A Day Usage: 484,854 Mi Cab Truck Tractor Asset located in: Humble, TX S/N: 1FUJGEDV1DSBV1048 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp Engine, Requires Diesel Exhaust Fluid, 7413 CHOICE OF 2 - Lot #'s: 1156, 1157 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Spicer DS404 Drive Axles, 3.70:1 Axle Ratio, Air 1156 2016 Freightliner Cascadia 113 6x4 T/A Day Ride Cab, 11R22.5, Airliner Air Ride **Cab Truck Tractor** Suspension, 178 in Wheelbase, PTO, Wet Kit, S/N: 3AKJGBDV7GDHA6151 Dual Fuel Tanks C/W: Detroit DD13 6 Cylinder 12.8 L 380 hp Usage: 675,354 Mi Engine, Requires Diesel Exhaust Fluid, 17605 Engine hrs, Retarder, Detroit DT12-DB-1450 HD Notes: ADDITIONAL COMPONENTS **AVAILABLE IN OFFICE - CPC** 12-Speed Automated Transmission, 12000 lb Asset located in: Lake Worth, TX

1153 2012 Freightliner Cascadia 125 6x4 T/A Day **Cab Truck Tractor**

S/N: 1FUJGEDR3CSBM7925

C/W: Detroit 6 Cylinder Diesel Engine, 1828.42 Engine hrs, Automated Transmission, 13300 lb Front Axle, 46000 lb Rears, 59300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tanks Usage: 512,461 Mi

Asset located in: Lake Worth, TX

Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Dual Fuel Tanks

Usage: 520,442 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1157	2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDVXGLGS4295 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 11444 Engine hrs, Engine Brake, Detroit DT12-OB-1450 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 355,568 Mi Asset located in: Lake Worth, TX	1161	2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV6BSBB6321 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 29567 Engine hrs, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 869,100 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 1158, 1159, 1160	1162	2015 Freightliner Columbia 120 6x4 T/A Day
1158	2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV5BSBB6309 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 2153 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 275/80R22.5 Front Tires, 445 /50R22.5 Super Singles Rear Tires, Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 861,133 Mi		Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1911 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 500 hp Engine, 15249 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 3.73:1 Axle Ratio, 12000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider Kit Usage: 697,934 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1163	2015 Freightliner Columbia 120 6x4 T/A Day
1159	2011 Freightliner Cascadia 113 6x4 S/A Day Cab Truck Tractor S/N: 1FUJGBDV9BSAX2724 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 1001 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 36576 lb Rears, 48546 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 884,817 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1908 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 500 hp Engine, 17818 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.73:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider Kit Usage: 333,663 Mi Asset located in: Lake Worth, TX
1160	2011 Freightliner Cascadia 113 6x4 T/A Day		
	Cab Truck Tractor S/N: 1FUJGBDV4BSBB6320 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 8206 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, Air Ride Cab, 275/80R22.5, Airliner Suspension, 162 in	1164	E OF 2 - Lot #'s: 1164, 1165 2016 Volvo VNM T/A Day Cab Truck Tractor S/N: 4V4MC9EG8GN967797 Usage: Not Available Asset located in: Lake Worth, TX
Wheelb Usage:	heelbase, Dual Fuel Tanks sage: 856,222 Mi s set located in : Lake Worth, TX	1165	2016 Volvo VNM T/A Day Cab Truck Tractor S/N: 4V4MC9EGXGN972144 Usage: Not Available Asset located in: Lake Worth, TX

		_	
Lot #	Details	Lot #	Details
1166	2016 Volvo VNL 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG4GN973794 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2358 Engine hrs, Engine Brake, Volvo Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 805,146 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1170	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR4JN405670 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12721 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 286,193 Mi Asset located in: Lake Worth, TX
1167	2016 Volvo VNL300 6x2 T/A Day Cab Truck Tractor S/N: 4V4NC9EH7GN941916 C/W: Volvo D13J435 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D 12- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 503,664 Mi Asset located in: Lake Worth, TX	-1171	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR8JN406076 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12523 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 294,702 Mi Asset located in: Lake Worth, TX
		1172	2018 International HX620 6x4 T/A Day Cab
	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPRXJN404541 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11699 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Hydraulic	1173	Truck Tractor S/N: 3HSDTAPR9JN404529 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13473 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 208 in Wheelbase, PTO, Dual Fuel Tanks Usage: 314,141 Mi Asset located in: Lake Worth, TX 2018 International HX620 6x4 T/A Day Cab
	Oil Cooler, Dual Fuel Tanks Usage: 274,941 Mi Asset located in: Lake Worth, TX		Truck Tractor S/N: 3HSDTAPR3JN405675 C/W: Cummins X15 6 Cylinder 15 L Diesel Engine, 2017 US EPA Label, Requires Diesel
1169	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR0JN406699 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14368 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 277,391 Mi		Exhaust Fluid, 15260 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5 Front Tires, 11R24.5 Rear Tires, Hendrickson 4-Bag Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 329,456 Mi Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 1174 1178 2018 International HX620 6x4 T/A Day Cab 2011 International Prostar 6x2 T/A Day Cab **Truck Tractor Truck Tractor** S/N: 3HSDTAPR2JN405652 S/N: 3HSCUAPRXBN346408 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2009 US EPA Label, 15012 Engine hrs, Engine Brake, Eaton Fuller 10-C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14783 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Speed Manual Transmission, 12000 lb Front Transmission, 13200 lb Front Axle, 40000 lb Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Cab, 295/75R22.5, Air Ride Suspension, 148 in Wheels, 11R24.5, Hendrickson Air Ride Wheelbase, Air Sliding 5th Wheel, Dual Fuel Suspension, 206 in Wheelbase, PTO, Wet Kit, **Tanks** Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 28,954 Mi Usage: 330,024 Mi Notes: THE AGE AND CONDITION OF THE TRUCK INDICATES MORE MILES THAN Asset located in: Lake Worth, TX SHOWN ON THE ODOMETER 1175 2018 International HX620 6x4 T/A Day Cab Asset located in: Lake Worth, TX Truck Tractor 1179 2011 International 7400 6x4 T/A Dump Truck S/N: 3HSDTAPR5JN404544 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires S/N: 1HTWGAZR5BJ399579 C/W: International MaxxForce 9 9.3 L Diesel Diesel Exhaust Fluid, 15215 Engine hrs, Engine Engine, 4726 Engine hrs, Eaton Fuller 10-Speed Brake, Eaton Fuller 10-Speed Manual Manual Transmission, 14000 lb Front Axle. Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum 40000 lb Rears, 54000 lb GVWR, 11R24.5, Spring over Walking Beam Suspension, PTO, Wheels, 11R24.5, Hendrickson Air Ride Godwin 14 ft 8 in Long x 3 ft 4 in High Steel Suspension, 205 in Wheelbase, PTO, Wet Kit, Body, Electric Roll Tarp Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 95,655 Mi Usage: 331,216 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1180 2007 Western Star 4900EX 6x4 T/A Day Cab 1176 2018 International HX620 6x4 T/A Day Cab **Truck Tractor Truck Tractor** S/N: 5KJJABAV07PV66073 S/N: 3HSDTAPR6JN405671 C/W: Cat C15 6 Cylinder 15.2 L Diesel 475 hp Engine, 2006 US EPA Label, 25128 Engine hrs, C/W: Cummins X15 6 Cylinder 15 L Diesel Engine, 2017 US EPA Label, Requires Diesel Engine Brake, Eaton Fuller 18-Speed Manual Exhaust Fluid, Engine Brake, Eaton Fuller 10-Transmission, Double Differential Locks, 16000 lb Front Axle, 46000 lb Rears, 62000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Speed Manual Transmission, 13200 lb Front Axle, 40000 kg Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires. Airliner Suspension, 224 in Wheelbase, Air 11R24.5 Rear Tires, Hendrickson 4-Bag Air Sliding 5th Wheel, Dual Fuel Tanks Ride Suspension, 210 in Wheelbase, PTO, Wet Usage: 671,173 Mi Kit, Dual Fuel Tanks Usage: 375,019 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1181, 1182 1177 2016 International Prostar+122 6x4 T/A Day **Cab Truck Tractor** S/N: 3HSDJSNR4GN748793 1181 2006 Peterbilt 379 6x4 T/A Day Cab Truck C/W: 6 Cylinder Diesel Engine, Requires Diesel Tractor Exhaust Fluid, 13825 Engine hrs, Engine Brake, S/N: 1XP5DB9X16D644337 Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, C/W: Cat C15 6 Cylinder 15.2 L Diesel 435 hp Engine, 2005 US ÉPA Label, CARB Compliant, Aluminum Front Wheels, 295/75R22.5, Air Ride Engine Brake, Eaton Fuller 10-Speed Manual Suspension, 183 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 390,546 Mi Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, Notes: DEFICIENCIES NOTED - PLEASE SEE 230 in Wheelbase, Air Sliding 5th Wheel, Dual THE INSPECTION REPORT **Fuel Tanks**

Asset located in: Humble, TX

Usage: 1,086,784 Mi

Asset located in: Humble, TX

Notes: ENGINE REBUILD NOVEMBER 2024

			1 age 103 of 307
Lot #	Details	Lot #	Details
1182	2006 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5DB9X56D648777 C/W: Cat C15 6 Cylinder 15 L Diesel Engine, Engine Brake, Eaton Fuller 15-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 652,502 Mi	1187	2005 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X45R086045 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Manual Transmission, 3.70 1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 675,236 Mi Asset located in: Lake Worth, TX
CHOIC 1183	Tractor S/N: 1XKDD49X49J255212 Usage: Not Available		2000 Western Star 4964EX 8x4 Tri/A Day Cab Truck Tractor S/N: 2WKEDDCJ2YK963807 C/W: Cat 3406 6 Cylinder 14.6 L Diesel 475 hp Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 58000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Lift Pusher Axle, Air Lift Tag Axle, Air over Walking Beam Suspension, 222 in Wheelbase, Air
1184	Asset located in: Lake Worth, TX 2008 Kenworth T800 T/A Day Cab Truck Tractor S/N: 1XKDD49X38J237363		Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 594,259 Mi Asset located in : Lake Worth, TX
CHOIC 1185	Usage: Not Available Asset located in: Lake Worth, TX CHOICE OF 3 - Lot #'s: 1185, 1186, 1187 1185 2007 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X37R154046 C/W: Cat C13 6 Cylinder 12.5 L Diesel 430 hp Engine, 2006 US EPA Label, 19630 Engine hrs,		1990 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5D29X1LN295315 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 9-Speed Transmission, Differential Lock, 12000 lb Fro Axle, 40000 lb Rears, 52000 lb GVWR, 11R24 Air Trac Air Ride Suspension, 227 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 211,059 Mi Asset located in: Humble, TX
	Engine Brake, Eaton Fuller FRO-16210C 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 81,923 Mi Asset located in: Lake Worth, TX	1190	2009 Peterbilt 384 6x4 T/A Day Cab Truck Tractor S/N: 1XPVD09X29D784986 C/W: Cummins 6 Cylinder Diesel 425 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 191 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 310,703 Mi Asset located in: Lake Worth, TX
1186	2006 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X46R114993 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.70:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 202 in Wheelbase, Dual Fuel Tanks Usage: 566,399 Mi Asset located in: Lake Worth, TX		

Lot#	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 1191, 1193		1196	2007 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AJ06Y47N008341
1191	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y98N001127 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 485 hp Engine, 2006 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: 299,016 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		C/W: Mack 6 Cylinder Diesel Engine, 14078 Engine hrs, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, 11R24.5 Camelback Suspension, 207 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 85,326 Mi Asset located in: Lake Worth, TX
		1198	2006 Mack CV713 T/A Day Cab Truck Tractor S/N: 1M2AG11Y96M034378 Usage: Not Available Asset located in: Lake Worth, TX
	THE INSPECTION REPORT	1199	· · · · · · · · · · · · · · · · · · ·
1193	Asset located in: Humble, TX 2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y58N003666 C/W: Mack MP8 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks		2003 Mack CX613 Vision 6x4 T/A Day Cab Truck Tractor S/N: 1M1AE07Y23W014985 C/W: Mack AC 6 Cylinder 12.0 L Diesel Engir Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 285/75/24.5, Air Lift Pusher Axle, Air Ride Suspensi 242 in Wheelbase, PTO, Wet Kit, Hydraulic System, Air Sliding 5th Wheel, Dual Fuel Tani Usage: 576,917 Mi Asset located in: Humble, TX
	Usage: 60,062 Mi	1200	2009 Freightliner Columbia 120 6x4 T/A Day
CHOIC	Asset located in: Lake Worth, TX HOICE OF 3 - Lot #'s: 1194, 1195, 1196 2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y68N001683 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2006 US EPA Label, 11687 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 206 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 437,607 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 1FUJA6CK79LAH0941 C/W: Detroit Series 60 6 Cylinder 14 L Diesel Engine, 2008 US EPA Label, Requires Diesel Exhaust Fluid, 15762.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5 Airliner Air Ride Suspension, 178 in Wheelbase Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 225,283 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		сноіс	E OF 2 - Lot #'s: 1201, 1202
1195	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y48N001827 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 37,316 Mi Asset located in: Lake Worth, TX	1201	2007 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CK97DZ42349 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 901,926 Mi

			Page 107 01 307
Lot #	Details	Lot #	Details
1202	2006 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CK36LX13895 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 8563 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 174,408 Mi Asset located in: Lake Worth, TX	1206	2008 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG98N498365 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 375 hp Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, Aluminum Wheels, 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 167 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,449,683 Mi Asset located in: Lake Worth, TX
1203	2007 Freightliner Columbia 112 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CVX7LU42622 C/W: Mercedes-Benz MBE4000 6 Cylinder 12.8 L Diesel 370 hp Engine, 2006 US EPA Label, 16998 Engine hrs, Engine Brake, Meritor MO- 15Z12A 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT- 40-145 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Steel, 295/75R22.5, Airliner Air Ride Suspension, 165 in Wheelbase Usage: 664,314 Mi Notes: Asset located in: Lake Worth, TX	1209	2019 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X1KJ257014 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15624 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, 75 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275 /80R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 286 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 662,371 Mi
1204	2009 Volvo VNL300 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG89N270007 C/W: Volvo D13F405 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 1272 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50000 lb GVWR, Steel, 295/75R22.5, Air Ride Suspension, 168 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 607,811 Mi Asset located in: Lake Worth, TX	1210	Asset located in: Lake Worth, TX 2017 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDP9X6HR157986 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 500 hp Engine, 2016 US EPA Label, Engine Brake, Eaton Fuller FRO-18210C 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, 3.55: 1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 28 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 232 in Wheelbase, Dual Fuel Tanks
CHOIC 1205	E OF 2 - Lot #'s: 1205, 1206 2009 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG39N283601 C/W: Volvo D13 6 Cylinder 375 hp Engine, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 18739 lb		Usage: 626,873 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE

S/N: 4V4MC9EG39N283601 C/W: Volvo D13 6 Cylinder 375 hp Engine, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 18739 lb Rears, 49478 lb GVWR, 275/80R22.5, Air Ride Suspension, 168 in Wheelbase, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP

Usage: Not Available

Asset located in: Lake Worth, TX

ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX

Lot # **Details** Lot # **Details** 1216 2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor CHOICE OF 6 - Lot #'s: 1212, 1213, 1214, 1215, 1216, 1217 S/N: 1XPXD49X6KD612210 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39162 Engine hrs, Engine 1212 2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor Brake, Eaton Fuller 10-Speed Manual S/N: 1XPXD49XXLD648550 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 40155 Engine hrs, Engine Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, Brake, 10-Speed Manual Transmission. 259 in Wheelbase, Air Sliding 5th Wheel, Dual Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid **Fuel Tanks** Usage: 330,281 Mi Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 259 in Asset located in: Lake Worth, TX Wheelbase, Air Sliding 5th Wheel, Dual Fuel 1217 2019 Peterbilt 389 6x4 T/A Sleeper Truck Tanks Usage: 306,491 Mi S/N: 1XPXD49X9KD611195 Asset located in: Lake Worth, TX C/W: Cummins X15 6 Cylinder 15.0 L Diesel 1213 2020 Peterbilt 389 6x4 T/A Sleeper Truck 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39138 Engine hrs, Engine Tractor Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid S/N: 1XPXD49X3LD648549 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Exhaust Fluid, 39980 Engine hrs, Engine Brake, Air Trac Suspension, 259 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 313,841 Mi Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Asset located in: Lake Worth, TX Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel 1218 2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor Usage: 266,350 Mi S/N: 1XPXD49X3KD273048 C/W: Cummins X15 6 Cylinder 14.9 L Diesel Asset located in: Lake Worth, TX Engine, Requires Diesel Exhaust Fluid, 24049 1214 Engine hrs, Engine Brake, Eaton Fuller RTLO 189-18B 18-Speed Manual Transmission, 2020 Peterbilt 389 6x4 T/A Sleeper Truck **Tractor** 12350 lb Front Axle, 40000 lb Rears, 52350 lb S/N: 1XPXD49X1LD702883 GVWR, 78 in Mid Roof Sleeper Cab, Aluminum C/W: Cummins X15 6 Cylinder 15 L Diesel 450 Wheels, 285/75R24.5, Paccar Air Ride hp Engine, 2019 US EPA Label, Requires Diesel Suspension, 281 in Wheelbase, Air Sliding 5th Exhaust Fluid, Engine Brake, Eaton Fuller Wheel, Dual Fuel Tanks Manual Transmission, 13200 lb Front Axle, Usage: 582,536 Mi 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Asset located in: Humble, TX 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 261 in 1219 2016 Peterbilt 389 6x4 T/A Sleeper Truck Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tractor Tanks Usage: 273,148 Mi S/N: 1XPXD49X3GD369706

Asset located in: Lake Worth, TX

1215 2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor

S/N: 1XPXD49X5LD648553 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPÁ Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, 266 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 276,137 Mi

Asset located in: Lake Worth, TX

C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 57373 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 5320 lb GVWR, 63 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 261 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks**

Usage: 423,399 Mi

Asset located in: Humble, TX

L ot #	Dataile	Lot #	Details
Lot #	Details	Lot #	Details
1220	O 2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X2FD291241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 23876 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Wet Kit, Dual Fuel Tanks Usage: 402,552 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble, TX	1223	2013 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDD49X1DJ346141 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 62 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Headache Rack Usage: 637,776 Mi Asset located in: Lake Worth, TX 2018 Freightliner Coronado 122SD 6x4 T/A
			Sleeper Truck Tractor
1220A	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X9FD268605 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26545 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb		S/N: 3AKJGNDR7JDJV8925 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automated Transmission, 52350.0 lb GVWR, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 264 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 485,348 Mi Asset located in: Lake Worth, TX
	GVWR, Air Ride Cab, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air	1225	2011 Freightliner Coronado 122 T/A Sleeper
	Ridé Suspension, 260 in Wheelbase, Dual Fuel Tanks		Truck Tractor S/N: 1FUJGNDR6BDBB8157
	Usage: 573,398 Mi		Usage: Not Available
	Asset located in: Midland, TX		Asset located in: Lake Worth, TX
1221	2012 Peterbilt 388 6x4 T/A Sleeper Truck Tractor S/N: 1XPWD40X9CD164118 C/W: Cummins 6 Cylinder Diesel Engine, 15073.9 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 273 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 326,225 Mi Asset located in: Lake Worth, TX	1225A	2021 Western Star 4900EX 6x4 T/A Sleeper Truck Tractor S/N: 5KJJABD14MPMU5583 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2020 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7129 Engine hrs, Engine Brake, 18-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 60 in Flat Top Sleeper Cab, 285/75R24.5, Airliner Air Ride Suspension, 286 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 258,341 Mi
1222	2015 Peterbilt 567 6x4 T/A Sleeper Truck Tractor		Asset located in: Lake Worth, TX
	S/N: 1XPCDP9X2FD297265 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21748.4 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 39000 lb Rears, 52200 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,572 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble, TX	1226	2019 Western Star 4900FA 6x4 T/A Sleeper Truck Tractor S/N: 5KJJAEDRXKPKC9060 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Eaton Fuller RTLO 13-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,054 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Lot # **Details** Lot # Details 1232 2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor CHOICE OF 1 - Lot #'s: 1227 S/N: 1XKYDP9X4LJ348287 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15421 Engine hrs, Engine 1227 2023 Kenworth T680 6x4 T/A Sleeper Truck Tractor Brake, Automated Transmission, 12500 lb S/N: 1XKYDP9X0PJ248970 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 12344 Engine hrs, Engine Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52500.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Paccar Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Beds, Bunk Heater, Aluminum Wheels, 295 /75R22.5, Paccar Air Ride Suspension, 228 in Usage: 589,051 Mi Wheelbase, Air Sliding 5th Wheel, Dual Fuel Asset located in: Humble, TX Tanks Usage: 343,012 Mi 1233 2020 Kenworth T680 6x4 T/A Sleeper Truck Notes: DEFICIENCIES NOTED - PLEASE SEE Tractor THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION S/N: 1XKYD49X3LJ357819 C/W: Cummins X15 6 Cylinder 15.0 L Diesel REPORT 450 hp Engine, 2019 US EPA Label, Requires Asset located in: Humble, TX Diesel Exhaust Fluid, 16890.8 Engine hrs. Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb CHOICE OF 4 - Lot #'s: 1230, 1231, 1232, 1233 Rears, 2.64:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar 1230 2020 Kenworth T680 6x4 T/A Sleeper Truck Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks S/N: 1XKYDP9X2LJ317474 Usage: 660,370 Mi C/W: Paccar 6 Cylinder Engine, 12173 Engine hrs, Paccar P016F112C Automated Asset located in: Humble, TX Transmission, 12350 lb Front Axle, 20000 lb 2020 Kenworth T680 6x4 T/A Sleeper Truck 1233A Rears, Paccar Drive Axles, 2.79:1 Axle Ratio, Tractor 52350 lb GVWR, 75 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Sliding 5th Wheel Usage: 523,545 Mi S/N: 1XKYDP9X7LJ344640 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 340 hp Engine, 2019 US EPA Asset located in: Lake Worth, TX Label, Requires Diesel Exhaust Fluid, 15907 Engine hrs, Engine Brake, Paccar 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT4014x3 Drive Axles, 1231 2020 Kenworth T680 6x4 T/A Sleeper Truck **Tractor** 2.79:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, S/N: 3WKYD49X5LF407169 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10333 Engine hrs, Engine Brake, Eaton Fuller 12-Speed Automated Tanks Transmission, 13200 lb Front Axle, 40000 lb Usage: 474,515 Mi Rears, 2.79:1 Axle Ratio, 53200 lb GVWR, 76 in Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, Air Sliding 5th

Wheel, Dual Fuel Tanks Usage: 481,871 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Asset located in: Lake Worth, TX

Lot # **Details** Lot # Details 1237 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor CHOICE OF 5 - Lot #'s: 1234, 1235, 1236, 1237, 1238 S/N: 1XKYDP9X2KJ257324 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 1234 2019 Kenworth T680 6x4 T/A Sleeper Truck 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar P0-Tractor 16F112 Automated Transmission, 12350 lb S/N: 1XKYD49X2KJ220594 Front Axle, 38000 lb Rears, Paccar Drive Axles, C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Bunk Exhaust Fluid, 25999 Engine hrs, Engine Brake, Heater, TriPac evolution Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Air Ride Eaton Fuller Automated Transmission, 12350 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 295/75R22.5, Paccar Air Ride Suspension, 229 in Wheelbase, Air Sliding Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,832 Km 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX Usage: 608,021 Mi 1238 2019 Kenworth T680 6x4 T/A Sleeper Truck Notes: SELLING WITH A REPOSESSION Tractor AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING S/N: 1XKYD49X3KJ247254 C/W: Cummins X15 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Asset located in: Lake Worth, TX 14976.3 Engine hrs, Engine Brake, Eaton Fuller EED-16F112C 12-Speed Automatic Transmission, Differential Lock, 12000 lb Front 1235 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor Axle, 40000 lb Rears, Paccar Drive Axles, 2.79: S/N: 1XKYD49X6KJ236748 1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Aluminum Outer Wheels, 295/75R22.5 Front Exhaust Fluid, 23865 Engine hrs, Engine Brake, Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Automated Transmission, 13200 lb Front Axle, Suspension, 228 in Wheelbase, Air Sliding 5th 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb Wheel, Dual Fuel Tanks GVWR, Air Ride Cab, 76 in High Rise Sleeper Usage: 692,453 Mi Cab, Bunk Beds, Aluminum Wheels, 295/75R22. Asset located in: Lake Worth, TX 5, Air Ride Suspension, 224 in Wheelbase, Dual **Fuel Tanks** Usage: 632,548 Mi CHOICE OF 3 - Lot #'s: 1239, 1240, 1241 Notes: SELLING WITH A REPOSESSION

1236 2019 Kenworth T680 6x4 T/A Sleeper Truck **Tractor**

Asset located in: Lake Worth, TX

PRIOR TO BIDDING

S/N: 1XKYDP9X3KJ239771 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 13393 Engine hrs, Engine Brake, Paccar PO-16F112 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 2.79:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 75 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 581,308 Mi

AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

Asset located in: Humble, TX

1239 2022 Peterbilt 579 6x4 T/A Sleeper Truck Tractor

S/N: 1XPBD49X7ND782896 C/W: Cummins X15 6 Cylinder 15.0 L 500 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 8204 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Asset located in: Lake Worth, TX

Usage: 359,739 Mi

Lot #	Details	Lot #	Details
1240	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X5MD741828 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 8557.7 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 461,648 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1244	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X9KD607207 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 275 /80R22.5 Front Tires, 11R22.5 Rear Tires, AG210 Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 488,776 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	Tractor S/N: 1XPBDP9X7MD755875		Asset located in: Midland, TX
	C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 19042 Engine hrs, Engine Brake, Paccar Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1245	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X6KD604443 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 80 in Condo Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 565,195 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 565195 TITLE SHOWS 565852
1242	2019 Peterbilt 579 6x4 T/A Sleeper Truck		Asset located in: Humble, TX
	Tractor S/N: 1XPBD49X2KD263251 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23729 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Paccar Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 671,185 Mi Asset located in: Midland, TX	1246	2022 Mack AN64T 6x4 T/A Sleeper Truck Tractor S/N: 1M1AN4GYXNM023469 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, Requires Diesel Exhaust Fluid, 19021 Engine hrs, Engine Brake, Mack Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 409,839 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1243	2019 Peterbilt 579 6x4 T/A Sleeper Truck		THE INSPECTION REPORT
	Tractor S/N: 1XPBDP9X7KD601681		Asset located in: Humble, TX
	C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15553 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Bunk Heater, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 245 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 756,792 Mi Asset located in: Humble, TX	1247	2022 Mack Anthem T/A Sleeper Truck Tractor S/N: 1M1AN4GY3NM023250 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1248 CHOIC	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDV6NSMY0047 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-HL 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 298,212 Mi Asset located in: Lake Worth, TX	1252	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSLT5963 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13413 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 466,120 Mi Notes: COLL B37639 LOT 871 (P53-46) \$45K NON PYMT 2024221 PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Asset located in: Lake Worth, TX
1249	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR9LSLR4781 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14419.45 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner	CHOICE OF 5 - Lot #'s: 1253, 1254, 1255, 12 1253 2020 Freightliner Cascadia 126 T/A Truck Tractor S/N: 3AKJHHDRXLSME9797 C/W: PROFESSIONALLY-MAINTAIN VEHICLE-PAG Usage: 399,946 Mi Asset located in: Lake Worth, TX 1254 2020 Freightliner Cascadia 126 6x4 Sleeper Truck Tractor S/N: 3AKJHHDR6LSME9795 C/W: Detroit DD15 6 Cylinder 14.8 hp Engine, 2019 US EPA Label, Rec Exhaust Fluid, Automated Transmi lb Front Axle, 40000 lb Rears, 5235 Air Ride Cab, 60 in High Rise Sleep Beds, Aluminum Outer Wheels, 295 Airliner Air Ride Suspension, Air Sli Wheel, Dual Fuel Tanks, PROFESSI MAINTAINED-FLEET-VEHICLE-PAG Usage: 423,637 Mi Asset located in: Lake Worth, TX 1255 2020 Freightliner Cascadia 126 6x4 Sleeper Truck Tractor S/N: 1FUJHHDR2LLLL3459 C/W: Detroit DD15 6 Cylinder 14.8 hp Engine, 2019 US EPA Label, Rec Exhaust Fluid, 16366 Engine hrs, Ei	S/N: 3AKJHHDRXLSME9797 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 399,946 Mi
1250	Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 534,026 Mi Asset located in: Lake Worth, TX 2020 Freightliner Cascadia 126 6x4 T/A		2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor
1200	Sleeper Truck Tractor S/N: 3AKJHHDR1LSMG6164 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16808 Engine hrs, Engine Brake, Detroit DT12-1650 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum		hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 423,637 Mi
	Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 449,805 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		•
1251	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSLY5486 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16924 Engine hrs, Engine Brake, Detroit Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,619 Mi Asset located in: Lake Worth, TX		Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 549,606 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1256	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8LSMC8947 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, 72 in Condo Sleeper Cab, Bunk Beds, ParkSmart Electric Sleeper Air Conditioner, Aluminum Wheels, 11R22.5, 228 in Wheelbase, Air Sliding 5th Wheel, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 552,948 Mi Asset located in: Lake Worth, TX	1264	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXKSKF0425 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18430 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 588,359 Mi Asset located in: Lake Worth, TX	
1257	2020 Freightliner Cascadia 126 T/A Sleeper Truck Tractor	1265	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor	
	S/N: 3AKJHHDR2LSLJ9064 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 661,770 Mi Asset located in : Lake Worth, TX		S/N: 3AKJHHDR7KSKE1407 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit Automated Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive	
CHOIC	E OF 5 - Lot #'s: 1259, 1260, 1263, 1264, 1265		Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual	
1259	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR9KSLG7882		Fuel Tanks, PROFESSIONALLY-MAINTAINED- FLEET-VEHICLE-PAG Usage: 609,505 Mi Asset located in: Lake Worth, TX	
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel	1266	2019 Freightliner Cascadia 126 6x4 T/A	
	Exhaust Fluid, 19617 Engine hrs, Engine Brake, Detroit DT12 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 527,337 Mi Asset located in: Lake Worth, TX	1266	Sleeper Truck Tractor S/N: 3AKJHHDR2KSKE4277 C/W: Detroit DD15 6 Cylinder 14.8 L Die hp Engine, 2018 US EPA Label, Require: Exhaust Fluid, 17458 Engine hrs, Engine Detroit DT12-V 12-Speed Automated Transmission, 12500 lb Front Axle, 400 Rears, Detroit DA-RT-40.0-4 Drive Axles Axle Ratio, 52350 lb GVWR, Air Ride Cal High Rise Sleeper Cab, Bunk Beds, Bunl Heater, Sleeper Air Conditioner, Auxiliar Unit, Aluminum Wheels, 295/75R22.5, A	Sleeper Truck Tractor S/N: 3AKJHHDR2KSKE4277 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17458 Engine hrs, Engine Brake, Detroit DT12-V 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner
1260	2019 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSLG7832		Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 634,187 Mi	
	Usage: 534,097 Mi	2019 Freightliner Case Sleeper Truck Tractor S/N: 3AKJHHDR3KSK C/W: Detroit DD15 6 C hp Engine, Requires D 10620 Engine hrs, Aut 13300 lb Front Axle, 4 Axle Ratio, 53300 lb G High Rise Sleeper Cab Wheels, 275/80R22.5 Rear Tires, Airliner Air Wheelbase, Air Sliding Tanks Usage: 477,320 Mi	Asset located in: Lake Worth, TX 2019 Freightliner Cascadia 126 6x4 T/A	
1263	Asset located in: Lake Worth, TX 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7KSLG7847 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 570,587 Mi Asset located in: Lake Worth, TX		Sleeper Truck Tractor S/N: 3AKJHHDR3KSKH0824 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 50 hp Engine, Requires Diesel Exhaust Fluid, 10620 Engine hrs, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 it High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22 Rear Tires, Airliner Air Ride Suspension, 233 it Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	

Lot # **Details** Lot # Details CHOICE OF 10 - Lot #'s: 1271, 1272, 1273, 1274, 1275, CHOICE OF 3 - Lot #'s: 1268, 1269, 1270 1276, 1277, 1278, 1279, 1280 1268 2019 Freightliner Cascadia 126 6x4 T/A 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor 1271 S/N: 3AKJHHDR3KSKJ2880 Sleeper Truck Tractor C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel S/N: 1FUJHHDR3KLKM1453 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Exhaust Fluid, Detroit 12-Speed Automated Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8310 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab. Aluminum Wheels, 295/75R22.5, Airliner Air 72 in High Rise Sleeper Cab, Bunk Beds, Ride Suspension, 231 in Wheelbase, Air Sliding Aluminum Front Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner 4-Bag 5th Wheel, Dual Fuel Tanks Usage: 684,650 Mi Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 579,939 Mi 2019 Freightliner Cascadia 126 6x4 T/A 1269 Asset located in: Lake Worth, TX Sleeper Truck Tractor 1272 2019 Freightliner Cascadia 126 6x4 T/A S/N: 3AKJHHDR5KSKJ2878 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Sleeper Truck Tractor Engine, 2018 US EPA Label, Requires Diesel S/N: 3AKJHHDR7KSKB3770 Exhaust Fluid, Automated Transmission, 12350 C/W: Detroit DD15 6 Cylinder 14.8 L Engine, lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 2017 US EPA Label, Automated Transmission, Air Ride Cab, High Rise Sleeper Cab, Bunk 12500 lb Front Axle, 40000 lb Rears, 52000 lb Beds, 275/80R22.5, Airliner Air Ride GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 225 in Suspension, 232 in Wheelbase, Air Sliding 5th Wheel Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available **Tanks** Usage: 701,338 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1270 2019 Freightliner Cascadia 126 6x4 T/A 1273 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR1KSKJ2876 Sleeper Truck Tractor

C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17776 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,586 Mi

Asset located in: Lake Worth, TX

S/N: 3AKJHHDR3KSJY3462 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 544,147 Mi

/80R22.5 Front Tires, 275/80R22.5 Rear Tires,

Air Ride Suspension, 230 in Wheelbase, Air

Sliding 5th Wheel, Dual Fuel Tanks Usage: 784,000 Mi **Asset located in**: Lake Worth, TX

Details Lot # **Details** Lot # 1274 2019 Freightliner Cascadia 126 6x4 T/A 1277 2019 Freightliner Cascadia 126 6x4 T/A **Sleeper Truck Tractor** Sleeper Truck Tractor S/N: 3AKJHHDR5KSKA2508 S/N: 3AKJHHDR2KSKP1628 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15930 Engine hrs, Engine Brake, Detroit DT12-1650-OH1 12-Speed Automated C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, Transmission, 13300 lb Front Axle, 40000 lb 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Rears, Meritor MT-40-14X Drive Axles, 3.08:1 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Wheels, 295 Tires, 11R22.5 Rear Tires, Airliner Suspension, /75R22.5, Airliner Air Ride Suspension, 235 in 225 in Wheelbase, Air Sliding 5th Wheel. Wheelbase, Air Sliding 5th Wheel, Dual Fuel Lowboy Ramps, Dual Fuel Tanks Tanks Usage: 677,092 Mi Usage: 625,964 Mi **Notes**: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN Asset located in: Lake Worth, TX 1278 2019 Freightliner Cascadia 126 6x4 T/A YOUR STATE. VERIFY WITH YOUR LOCAL DMV Sleeper Truck Tractor PRIOR TO BIDDING S/N: 3AKJHHDR4KSKS9784 Asset located in: Lake Worth, TX C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 20138.21 Engine hrs, Engine 1275 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor Brake, Automated Transmission, 13220 lb S/N: 3AKJHHDR5KSKK8191 Front Axle, 40000 lb Rears, 53220 lb GVWR, Air C/W: Detroit DD15 14.8 L Diesel Engine, 2018 Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, US EPA Label, Requires Diesel Exhaust Fluid, 22547.51 Engine hrs, Engine Brake, Detroit 11R22.5 Rear Tires, Airliner Air Ride DT12-1650-OH 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in Suspension, 256 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 593,973 Mi High Rise Sleeper Cab, Bunk Beds, Aluminum Notes: PROFESSIONALLY-MAINTAINED-FLEET-Wheels, 295/75R22.5, Airliner Air Ride VEHICLE-PAG Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 727,804 Mi 1279 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 3AKJHHDR2KSKW8471 1276 2019 Freightliner Cascadia 126 6x4 T/A Usage: 610,972 Mi Sleeper Truck Tractor Notes: PROFESSIONALLY-MAINTAINED-FLEET-S/N: 3AKJHHDV5KSKJ2974 **VEHICLE-PAG** C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Asset located in: Lake Worth, TX Exhaust Fluid, Retarder, Eaton Fuller FAO-1280 2019 Freightliner Cascadia 126 T/A Sleeper 16810C 10-Speed Manual Transmission, **Truck Tractor** 12500 lb Front Axle, 40000 lb Rears, 3.08:1 S/N: 3AKJHHDRXKSKL3824 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, C/W: Detroit DD15 Diesel 455 hp Engine, Engine Brake, Detroit DT-12 12-Speed 11R22.5, Airliner Air Ride Suspension, 241 in Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 72 in High Wheelbase, Air Sliding 5th Wheel, Blower, Dual **Fuel Tanks** Rise Sleeper Cab, Aluminum Outer Wheels, 275 Usage: 445,195 Mi

Details Lot # **Details** Lot # 1281 2019 Freightliner Cascadia 126 6x4 T/A 1286 2022 Volvo VNL880 6x4 T/A Sleeper Truck Sleeper Truck Tractor **Tractor** S/N: 1FUJHHDR0KLLJ6173 S/N: 4V4NC9EH6NN600794 C/W: Volvo D13H455 6 Cylinder 13.0 L Diesel C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Fluid, 23298 Engine hrs, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual 21619.0 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Åxle, 38000 lb Rears, Meritor Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Axle Ratio, 53200 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 216 in Suspension, 239 in Wheelbase, Air Sliding 5th Wheelbase, Air Sliding 5th Wheel Usage: 685,332 Mi Wheel, Dual Fuel Tanks Usage: 789,122 Mi Asset located in: Lake Worth, TX Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV 2018 Freightliner Cascadia 126 6x4 T/A 1282 Sleeper Truck Tractor PRIOR TO BIDDING S/N: 3AKJHHDR3JSJW9253 Asset located in: Lake Worth, TX C/W: Detroit DD15 6 Cylinder 14.7 L 455 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-1650-OHI HD 12-Speed Automated CHOICE OF 4 - Lot #'s: 1287, 1288, 1289, 1290 Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in 1287 2021 Volvo VNL860 6x4 T/A Sleeper Truck High Rise Sleeper Cab, Bunk Beds, 295/75R22. Tractor 5, Airliner Air Ride Suspension, 235 in S/N: 4V4NC9EH8MN600892 Wheelbase, Air Sliding 5th Wheel, Dual Fuel C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, 8277 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Usage: Not Available Notes: SELLING WITH A REPOSESSION Automated Transmission, 13200 lb Front Axle, AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, PRIOR TO BIDDING 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Asset located in: Lake Worth, TX 1283 2018 Freightliner Cascadia 126 6x4 T/A Wheel, Dual Fuel Tanks Sleeper Truck Tractor Usage: 374,829 Mi S/N: 3AKJHHDRXJSJW4146 Notes: PER THE DEALER ACTUAL MILEAGE IS C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 HIGHER THAN SHOWING ON ODO AND ECM hp Engine, 2017 US EPA Label, Requires Diesel TRUE MILEAGE IS UNKNOWN Exhaust Fluid, Engine Brake, Detroit DT12-1650-Asset located in: Lake Worth, TX OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-1288 2020 Volvo VNL860 6x4 T/A Sleeper Truck RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 Tractor lb GVWR, Air Ride Cab, 72 in High Rise Sleeper S/N: 4V4NC9EG7LN223199 Cab, Bunk Beds, 11R22.5, Airliner Air Ride C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2019 US EPA Label, Requires Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-Diesel Exhaust Fluid, 19723 Engine hrs, Engine MAINTAINED-FLEET-VÉHICLE-PAG Brake, Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Usage: 550,012 Mi Asset located in: Lake Worth, TX Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride 1285 2022 Volvo VNL860 6x4 T/A Sleeper Truck Suspension, 230 in Wheelbase, Dual Fuel Tanks Tractor Usage: 511,249 Mi S/N: 4V4NC9EH6NN603923 **Notes**: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT C/W: Volvo 6 Cylinder 12.8 L Diesel 425 hp Engine, 2021 US EPA Label, Requires Diesel Asset located in: Humble, TX Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 283,601 Mi

Lot #	Details	Lot #	Details
1289	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN249446 C/W: Volvo 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,184 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1293	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3LN245807 C/W: Volvo D13M 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 16978.1 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50500 lb GVWR, Air Ride Cab, 70 in Flat Top Sleeper Cab, 11R22.5, Volvo Air Ride Suspension, 254 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 366,216 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
1290	2020 Volvo VNL860 6x4 T/A Sleeper Truck		Asset located in: Lake Worth, TX
1290	Tractor S/N: 4V4NC9TJ8LN253794 C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18160 Engine hrs, Engine Brake, Eaton Fuller FO- 18E313A MHP Automatic Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/70R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 540,590 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	CHOICI 1294	2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN221498 C/W: Volvo 6 Cylinder 12.8 L 425 hp Engine, Requires Diesel Exhaust Fluid, 19160 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 739,489 Mi Asset located in: Lake Worth, TX
1292	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH0LN249443 C/W: Volvo D13M 6 Cylinder 12.8 L 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 22710.9 Engine hrs, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 611,970 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1295	2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN249009 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 387,288 Mi Asset located in: Lake Worth, TX 2019 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6KN195791 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12- Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel Usage: 412,464 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1297 CHOIC	2020 Volvo VNL64T740 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH8LN258469 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14884 Engine hrs, Automatic Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, 295 /75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,732 Hr Asset located in: Humble, TX	1300	2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH1KN232987 C/W: Volvo D13M 6 Cylinder 12.8 L 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-18210C 10-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1298	2019 Volvo VNL64T760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH1KN206101 C/W: Volvo D13H455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Volvo Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available	1301	2020 Volvo VNR 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DH1LN270436 C/W: Volvo 6 Cylinder Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8942 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 251,927 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Lake Worth, TX	1000	Asset located in: Humble, TX
1299	2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TJ3KN204274 C/W: Cummins X15 500ST 6 Cylinder 15.0 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-20913A 13-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Assist Front Suspension, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available	_1302	2019 International LoneStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSLGAPR6KN527657 C/W: Cummins X15 500 6 Cylinder 15.0 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,536 Mi Asset located in: Lake Worth, TX
		1303	2022 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR0NN285693 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 73 in Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 450,017 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1304	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3LN800182 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16079 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 484,652 Mi Asset located in: Lake Worth, TX	1308	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR8KN122995 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 1305, 1306, 1307	1309	2019 International LT625 6x4 T/A Sleeper Truck Tractor
1305	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZTZR3LN684488 C/W: International A26 6 Cylinder 12.4 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16142 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	сноіс	S/N: 3HSDZAPR8KN566457 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1310, 1311, 1312
	Usage: Not Available Asset located in: Lake Worth, TX		
1306	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR5LN854650 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12492 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 351,096 Mi Asset located in: Lake Worth, TX	-1310	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR0KN070889 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15367 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22. 5, Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 467,363 Mi Asset located in: Lake Worth, TX
1307	2020 International LT625 4x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR7LN854651 C/W: Cummins X15 6 Cylinder Diesel 450 hp Engine, 2019 US EPA Label, Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, Air Ride Cab, 51 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Sliding 5th Wheel Usage: 471,259 Mi Asset located in: Lake Worth, TX	1311	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9KN748748 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19547 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 73 in Condo Sleeper Cab, Bunk Beds, Steel, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 467,585 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1312	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3KN350628	СНОІС	E OF 2 - Lot #'s: 1317, 1318
	C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 73 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 561,974 Mi Asset located in: Lake Worth, TX	1317	17 2018 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7JD457743 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15889 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds,
1313	2019 International LT 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3KN319055 C/W: Cummins X15 6 Cylinder 15.0 L Diesel		Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 685,817 Mi
	450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller	1318	Asset located in: Lake Worth, TX 2019 Peterbilt 570 6v4 T/A Sleeper Truck
	10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 73 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 459,002 Mi Asset located in: Humble, TX	-	2018 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X6JD488661 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 22729.8 Engine hrs, Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, 295/75R22.5, Air Ride
1314	2019 International LT625 6x4 T/A Sleeper Truck Tractor		Suspension, 237 in Wheelbase, Dual Fuel Tanks Usage: 623,949 Mi
	S/N: 3HSDZAPR5KN284342 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19700 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 603,242 Mi Notes: . Asset located in: Lake Worth, TX		Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS; ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO
CHOIC	E OF 2 - Lot #'s: 1315, 1316		BIDDING Asset located in: Lake Worth, TX
1315	2019 International LT62F T/A Sleeper Truck Tractor	СНОІС	E OF 2 - Lot #'s: 1319, 1320
	S/N: 3HSDZAPR6KN290893 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 510,647 Mi Asset located in: Lake Worth, TX	Tractor S/N: 1XPBD49X6HD423821 C/W: Cummins ISX15 6 Cylinder 1 Engine, 2016 US EPA Label, Requi Exhaust Fluid, 23493.8 Engine hrs Brake, Eaton Fuller Automated Tra 13200 lb Front Axle, 40000 lb Rea GVWR, Air Ride Cab, 78 in High Ris Cab, 295/75R22.5, Paccar Air Ride	S/N: 1XPBD49X6HD423821 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
1316	2019 International RH613 T/A Sleeper Truck Tractor S/N: 3HSDWTZR6KN106957 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 379,633 Mi Asset located in: Lake Worth, TX		Exhaust Fluid, 23493.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 730,143 Mi

			Page 122 of 56/
Lot #	Details	Lot #	Details
1320	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X0HD422634	сноіс	E OF 2 - Lot #'s: 1323, 1324
	C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 15184 Engine hrs, Engine Brake, Eaton Fuller Automatic Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Paccar Air Ride Suspension, 237 in Wheelbase, PTO, Hydraulic System, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 373,658 Mi Asset located in: Midland, TX	1323	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD262361 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 37998 lb Rears, 50000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Flex Air Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
CHOIC	E OF 2 - Lot #'s: 1321, 1322		Usage: 893,094 Mi Asset located in: Lake Worth, TX
1321	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X0GD330582 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19825 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 908,570 Mi	1324	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD285266 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Coolant Heater, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, 80 in High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel Usage: 862,250 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1325	2017 Peterbilt 367 6x4 T/A Sleeper Truck
1322	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9XXGD298189 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 20896 Engine hrs, Engine Brake, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 635,966 Mi		Tractor S/N: 1XPBDP9X0HD357509 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 402,192 Mi

Lot #	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 1326, 1328	сноісі	E OF 2 - Lot #'s: 1330, 1331
1326	2013 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49XXDD206468 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Low Air Leaf Air Ride Suspension, 246 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: Asset located in: Midland, TX	1330	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X2JJ216429 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.93:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Paccar 4-Bag Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Midland, TX
1328	2012 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49X0CD142424 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28592 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Front Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Leaf Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 778,429 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX	1331	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3JJ185028 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5, Paccar Air Ride Suspension, 222 in Wheelbase, Dual Fuel Tanks Usage: 630,153 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1329	2011 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7D49X7BD121337 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	CHOICI 1333	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9XXHJ144648 C/W: Paccar MX-13 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 24355 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Aluminum

High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 901,856 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Dataile	Lot #	Detaile
Lot #	Details 2017 Kenworth T680 6x4 T/A Sleeper Truck	Lot #	Details 2016 Kenworth T680 6x4 T/A Sleeper Truck
	Tractor S/N: 1XKYDP9X2HJ146961 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 25916 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT40- 14X3 Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 643,846 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKYD49X4GJ118091 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 2504 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 38 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 827,511 Mi Asset located in: Lake Worth, TX
1335	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor	сноіс	E OF 5 - Lot #'s: 1339, 1340, 1341, 1342, 1343
	S/N: 1XKYDP9X3HJ145768 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 26851 Engine hrs, Engine Brake, Eaton Fuller Eaton Advantage 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,016 Mi Asset located in: Livingston, LA	1339	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X7FJ430257 C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: 866,880 Mi
1336	2017 Kenworth T680 6x4 T/A Sleeper Truck		Asset located in: Lake Worth, TX
	Tractor S/N: 1XKYD49X0HJ153938 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19893 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 76 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 238 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 631,336 Mi	1340	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X9FJ449653 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 23432 Engine hrs, Engine Brake, Automatic Transmission, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, 295/75R22.5, 8-Bag Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 810,190 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	1341	2015 Kenworth T680 6x4 T/A Sleeper Truck
1337	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP8X6GJ121464 C/W: Paccar 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2310 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Differential Lock, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 60,967 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKYD48XXFJ420758 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810C 10-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 3.36:1 Axle Ratio, 46350 lb GVWR, Air Ride Cab, 75 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,063,376 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1342	2015 Kenworth T680 6x4 T/A Sleeper Truck		
	Tractor	CHOIC	E OF 3 - Lot #'s: 1346, 1347, 1348
	S/N: 1XKYD48X2FJ420768 C/W: Cummins X15 6 Cylinder 15.0 L Diesel		
	450 hp Engine, 2014 US EPA Label, Requires	1346	2016 Kenworth T660 6x4 T/A Sleeper Truck
	Diesel Exhaust Fluid, 30258 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual		Tractor
	Transmission, 12350 lb Front Axle, 34000 lb		S/N: 1XKAD49X2GJ481393 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
	Rears, 46350 lb GVWR, Air Ride Cab, 62 in High		485 hp Engine, 31744 Engine hrs, Engine Brake
	Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride		Eaton Fuller FRO-16210C 10-Speed Manual
	Suspension, 230 in Wheelbase, Air Sliding 5th		Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, Spicer DSP40 Drive Axles,
	Wheel, Dual Fuel Tanks		3.55:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab,
	Usage: 1,080,201 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		52 in Mid Roof Sleeper Cab, Aluminum Wheels,
	THE INSPECTION REPORT		295/75R22.5, Air Ride Suspension, 244 in Wheelbase, Dual Fuel Tanks
	Asset located in: Humble, TX		Usage: 908,066 Mi
1343	2015 Kenworth T680 6x4 T/A Sleeper Truck	7	Notes: THIS UNIT RUNS BUT MAY HAVE
	Tractor		DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN
	S/N: 1XKYDP9X1FJ450926		TEXAS ADMINISTRATIVE CODE SECTIONS
	C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires		114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE
	Diesel Exhaust Fluid, Engine Brake, Manual		RESTORATION OF ALL POLLUTION CONTROL
	Transmission, 12000 lb Front Axle, 40000 lb		SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN
	Rears, 52000 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater,		ACKNOWLEDGEMENT FORM OF THIS NOTICE
	Aluminum Outer Wheels, 275/80R22.5 Front		PRIOR TO REMOVAL OF UNIT FROM YARD
	Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 231 in Wheelbase, Dual Fuel Tanks		Asset located in: Lake Worth, TX
	Usage: 809,582 Mi	1347	2016 Kenworth T660 6x4 T/A Sleeper Truck
	Asset located in: Humble, TX		Tractor
			S/N: 1XKAD49X4GJ481394 C/W: Cummins ISX 6 Cylinder 14.9 L Diesel
CHOIC	E OF 2 - Lot #'s: 1344, 1345		500 hp Engine, 2015 US EPA Label, Requires
	·		Diesel Exhaust Fluid, 4526 Engine hrs, Engine
1344	2013 Kenworth T700 T/A Sleeper Truck Tractor		Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front
1044	S/N: 1XKFDP9X7DJ348972		Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride
	Usage: Not Available		Cab, Flat Top Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear
	Asset located in: Lake Worth, TX	_	Tires, Air Ride Suspension, 244 in Wheelbase,
1345	2012 Kenworth T700 6x4 T/A Sleeper Truck		Dual Fuel Tanks Usage: 1,002,171 Mi
	Tractor		Notes: THIS UNIT RUNS BUT MAY HAVE
	S/N: 1XKFDP9X9CJ325479		DEFICIENCIES IN ITS POLLUTION CONTROL
	C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455		SYSTEMS WITH LIABILITIES OUTLINED IN

S/N: 1XKFDP9X9CJ325479 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210B 10-Speed Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, 11R22.5, Paccar Air Ride Suspension, 231 in Wheelbase, Dual Fuel Tanks Usage: Not Available

Asset located in: Midland, TX

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

1348 2014 Kenworth T660 6x4 T/A Sleeper Truck Tractor

Details

Lot #

S/N: 1XKAD49XXEJ397691 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 35718 Engine hrs, Eaton Fuller Manual Transmission, Differential Lock, 12000 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, Flat Top Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Dual Fuel Tanks

Usage: 970,194 Mi
Notes: THIS UNIT RUNS BUT MAY HAVE
DEFICIENCIES IN ITS POLLUTION CONTROL
SYSTEMS WITH LIABILITIES OUTLINED IN
TEXAS ADMINISTRATIVE CODE SECTIONS
114.20 AND 114.50. THIS MAY APPLY IF YOU
OPERATE THE UNIT PRIOR TO THE ADEQUATE
RESTORATION OF ALL POLLUTION CONTROL
SYSTEMS OR DEVICES AS ORIGINALLY
EQUIPPED. BUYER OF THIS UNIT MUST SIGN
ACKNOWLEDGEMENT FORM OF THIS NOTICE

PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

1349 2014 Kenworth T600 6x4 T/A Sleeper Truck Tractor

S/N: 1XKAD48X8EJ414196 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17145 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Air Ride Cab, 50 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, 11R24.5, Air Assist Front Suspension, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel

Usage: 555,466 Mi

Asset located in: Lake Worth, TX

1350 2013 Kenworth T660 6x4 T/A Sleeper Truck Tractor

S/N: 1XKADP9X3DJ353712 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 340 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTOC16909A Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Dana DSP41 Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 128 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks

Usage: 554,558 Mi

Asset located in: Lake Worth, TX

Lot # Details

1350A 2013 Kenworth T660 6x2 T/A Sleeper Truck Tractor

S/N: 1XKAA48X9DJ365291 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 20304 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 34000 lb Rears, 2.53:1 Axle Ratio, 46000 lb GVWR, Air Ride Cab, 52 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 914,459 Mi

Asset located in: Lake Worth, TX

1351A 2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor

S/N: 1XKAD49X6CJ297018
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 24434 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 809,118 Mi

Asset located in: Lake Worth, TX

1352 2016 Mack CXU613 6x4 T/A Sleeper Truck Tractor

S/N: 1M1AW21Y4GM077413 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 15300 Engine hrs, Engine Brake, Mack Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 450,360 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1353, 1354

1353 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor

S/N: 1M1AW02Y3FM051337 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22586 Engine hrs, Engine Brake, 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 607,391 Mi

Lot #	Details	Lot #	Details
1354	2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM049326 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: Not Available Asset located in: Lake Worth, TX	1358	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM042227 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 22893 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285 /75R24.5 Front Tires, 275/80R22.5 Rear Tires, 4-Bag Air Ride Suspension, 219 in Wheelbase, PTO Usage: 822,170 Mi Asset located in: Lake Worth, TX
CHOIC 1360, 1	E OF 7 - Lot #'s: 1355, 1356, 1357, 1358, 1359, 1361	1359	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor
1355	Tractor S/N: 1M1AW02Y2EM036889 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 897,867 Mi		S/N: 1M1AW02Y1EM042263 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tanks Usage: 778,799 Mi Asset located in: Lake Worth, TX
		1360	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXEM040902
1356	Asset located in: Lake Worth, TX 2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM040890 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride	1361	C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 222 in Wheelbase Usage: 805,702 Mi Asset located in: Lake Worth, TX
	Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R22.5, Air Ride Suspension, 214 in Wheelbase Usage: 773,925 Mi Asset located in : Lake Worth, TX		2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM036877 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel
1357	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y1EM036897 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 25651 Engine hrs, Engine Brake, Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 836,651 Mi Asset located in: Lake Worth, TX		Exhaust Fluid, 9682 Engine hrs, Engine Brake Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, 285/75R24.5, Air Ride Suspension, 217 Wheelbase Usage: 794,371 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICE	CHOICE OF 6 - Lot #'s: 1362, 1363, 1364, 1365, 1366, 1367		2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM040887
1362	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y9EM042236 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum		C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 690,857 Mi Asset located in: Lake Worth, TX
	Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 675,329 Mi	1367	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor
	Asset located in: Lake Worth, TX		S/N: 1M1AW02Y8EM042244
1363	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4EM042225 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, mRide	C/W: Mack MP7 6 Cylinder 1 hp Engine, 2013 US EPA Lab Exhaust Fluid, Eaton Fuller N Transmission, 12000 lb Fror Rears, 52000 lb GVWR, Air R Rise Sleeper Cab, Aluminum /75R24.5, Air Ride Suspension Wheelbase Usage: 741,289 Mi	
	Air Ride Suspension, 218 in Wheelbase Usage: 730,061 Mi	1368	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor
1364	Asset located in: Lake Worth, TX 2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM033793 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 31248 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front		S/N: 1M1AW07Y6EM042008 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18- Speed Manual Transmission, 6600 kg Front Axle, 20800 kg Rears, 27400 kg GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 707,937 Mi Asset located in: Humble, TX
	Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 218 in Wheelbase Usage: 755,801 Mi Asset located in : Lake Worth, TX	CHOIC	E OF 6 - Lot #'s: 1369, 1370, 1371, 1372, 1373, 137
1365	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM042243 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 791,657 Mi	1369	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM036878 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, 26792 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 217 in Wheelbase Usage: 871,001 Mi

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1370	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7DM024736 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395	CHOIC	E OF 6 - Lot #'s: 1375, 1376, 1377, 1378, 1379, 138
	hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 214 in Wheelbase Usage: 701,446 Mi Asset located in: Lake Worth, TX	1375	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXDM029512 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 24261 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper
1371	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8DM029525		Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase Usage: 648,076 Mi Asset located in : Lake Worth, TX
	C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension Usage: 643,699 Mi	1376 2013 Mack CXU613 6x4 T/A Sleeper T Tractor S/N: 1M1AW02Y2DM024739 C/W: Mack MP7 10.8 L Diesel 395 hp I 2012 US EPA Label, Requires Diesel Ex Fluid, 26124 Engine hrs, Engine Brake, Fuller 13-Speed Manual Transmission,	S/N: 1M1AW02Y2DM024739 C/W: Mack MP7 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 26124 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb
1372	Asset located in: Lake Worth, TX 2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor		Rears, 52350 lb GVWR, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 218 in Wheelbase Usage: 690,603 Mi
	S/N: 1M1AW02Y6DM029524 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 13523 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 756,971 Mi Asset located in: Lake Worth, TX 2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor		Asset located in: Lake Worth, TX
		1377	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033782 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20338 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase Usage: 658,728 Mi
1373			
	S/N: 1M1AW02Y3DM029500 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395		Asset located in: Lake Worth, TX
	hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 3225 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension, 220 in Wheelbase Usage: 674,399 Mi Asset located in: Lake Worth, TX	1378	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033751 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension,
1374	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor		220 in Wheelbase Usage: 783,814 Mi
	S/N: 1M1AW21Y6DM034381 C/W: Mack MP8 6 Cylinder 12.7 L Diesel Engine, 30700 Engine hrs, Mack Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase Usage: 813,858 Mi		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1379	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033748 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase Usage: 624,802 Mi Asset located in: Lake Worth, TX	1383	2014 Mack CHU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AN07Y1EM015852 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 2950 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 462,432 Mi
1381	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8DM031484		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT . Asset located in: Humble, TX
	C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 216 in Wheelbase Usage: Not Available Asset located in: Humble, TX	1384	2020 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR6LDLX1078 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650 OH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio,
	2011 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW07Y3BM015005 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, Mack MDrive Automated Transmission, 12000 lb Front Axle, 40000 lb		53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
	Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 295 /75R22.5, Air Ride Suspension, 226 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,133,741 Mi Asset located in: Lake Worth, TX	CHOIC 1385	E OF 2 - Lot #'s: 1385, 1386 2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

CHOICE OF 2 - Lot #'s: 1382, 1383

1382 2015 Mack CHU613 6x4 T/A Sleeper Truck Tractor

S/N: 1M1AN07Y2FM019667 C/W: Mack MP8 6 Cylinder Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 237 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 510,043 Mi

Notes: . Asset located in: Humble, TX

Sleeper Truck Tractor

S/N: 3AKJGLDR6KSKS1465 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19541.1 Engine hrs, Detroit DT12-1550 OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 723,931 Mi

Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION

BELOW SUPPLIED

			1 age 131 01 307
Lot #	Details	Lot #	Details
1386	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV6KSKH9486 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23543 Engine hrs, Detroit DT12-1550- OH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 720,855 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	CHOIC	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR7JSJU3695 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, 11R22.5, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1387	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR3KDKM9521 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-15210B 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel Usage: 512,155 Mi Asset located in: Lake Worth, TX	1391	Usage: 484,584 Mi Asset located in: Lake Worth, TX 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR5JDHF7017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR- 15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel Usage: 495,548 Mi Asset located in: Lake Worth, TX
	Sleeper Truck Tractor S/N: 3AKJGLDR9KDKM9524 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Air Sliding 5th Wheel Usage: 525,435 Mi Asset located in: Humble, TX	1392	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR0JSHF3632 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-DA-1750 HD 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40- 14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Exo Air Sleeper Air Conditioner, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 614,080 Mi

			Page 132 of 567
Lot #	Details	Lot #	Details
1393	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV4JLJV0967 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8996 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C-EA Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 373,961 Mi Asset located in: Lake Worth, TX	1396	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLFG9JLJN0560 C/W: Cummins X15 6 Cylinder 15 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 21765 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 665,249 Mi Asset located in: Lake Worth, TX
CHOICE	E OF 4 - Lot #'s: 1394, 1395, 1396, 1397	1397	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV0JLJK2888
1394	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR8JSHF3927 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit 12- Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 604,042 Mi	сноісі	C/W: Detroit DD13 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 408,806 Mi Asset located in: Lake Worth, TX E OF 6 - Lot #'s: 1398, 1399, 1400, 1401, 1402, 140
1395	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV2JLJP4880 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 21109 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 890,800 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1398	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR4JLJV0566 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12180 Engine hrs, Engine Brake, Detroit DT12-1650-0A 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Steel, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 420,575 Mi

Asset located in: Humble, TX

Details Lot # **Details** Lot # 1399 2018 Freightliner Cascadia 125 6x4 T/A 1403 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGLDR2JLJV0565 S/N: 1FUJGLDR7JLJV0576 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 20205 Engine hrs, Engine Brake, Detroit DT12-OA-1750 12-Speed Automated hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13300 lb Front Axle, Transmission, 13300 lb Front Axle, 40000 lb 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Cab, Bunk Beds, Carrier Comfort Pro Auxiliary Power Unit, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Power Unit, Aluminum Front Wheels, 295 Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel VEHICLE-PAG Tanks, PROFESSIONÄLLY-MAINTAINED-FLEET-Usage: 442,347 Mi VEHICLE-PAG Usage: 528.613 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1400 2018 Freightliner Cascadia 125 T/A Sleeper 1404 2017 Freightliner Cascadia 125 T/A Sleeper Truck Tractor Truck Tractor S/N: 1FUJGLDR0JLJV0564 S/N: 3AKJGLBG6HSJE6319 C/W: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: Not Available Usage: 479,762 Mi Notes: THIS UNIT RUNS BUT MAY HAVE Asset located in: Lake Worth, TX DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN 1401 2018 Freightliner Cascadia 125 6x4 T/A TEXAS ADMINISTRATIVE CODE SECTIONS **Sleeper Truck Tractor** 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE S/N: 1FUJGLDR5JLJV0558 RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12958 Engine hrs, Engine Brake, ACKNOWLEDGEMENT FORM OF THIS NOTICE Detroit 12-Speed Automated Transmission,

RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX 1402 2018 Freightliner Cascadia 125 6x4 T/A

VEHICLE-PAG

Usage: 479,989 Mi

Sleeper Truck Tractor S/N: 1FUJGLDR3JLJV0560 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OA-1750 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEÉT-

13300 lb Front Axle, 40000 lb Rears, Detroit DA-

Power Unit, Aluminum Front Wheels, 295

/75R22.5, Airliner Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-

VEHICLE-PAG Usage: 506,969 Mi

Asset located in: Lake Worth, TX

1405 2017 Freightliner Cascadia 125 T/A Sleeper **Truck Tractor**

PRIOR TO REMOVAL OF UNIT FROM YARD

S/N: 3AKJGLDR0HSHY7696

CHOICE OF 2 - Lot #'s: 1405, 1406

Usage: Not Available

Notes: THIS UNIT RUNS BUT MAY HAVE **DEFICIENCIES IN ITS POLLUTION CONTROL** SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Lot #	Details	Lot #	Details
1406	Truck Tractor S/N: 3AKJGLDR1HSHY7691 Usage: Not Available Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD	1409 	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR6HSHF0874 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 720,617 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2017 Freightliner Cascadia 125 6x4 T/A
CHOIC	CHOICE OF 5 - Lot #'s: 1407, 1408, 1409, 1410, 1411		Sleeper Truck Tractor S/N: 3AKJGLBG4HSJE6318 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, CARB

1407 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR6HLHW3673 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1650 12-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Asset located in: Lake Worth, TX

Usage: 713,350 Mi

1408 2017 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor**

S/N: 1FUJGLDR5HLHF2174 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1750 HD 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 813,536 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Lake Worth, TX

x4 T/A

.0 L Diesel el. CARB Compliant, Requires Diesel Exhaust Fluid, 2448 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 785,075 Mi

Asset located in: Lake Worth, TX

1411 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR0HLHX4331 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 610,011 Mi

			Page 135 of 567
Lot #	Details	Lot #	Details
CHOICE OF 9 - Lot #'s: 1412, 1413, 1414, 1415, 1416, 1417, 1418, 1419, 1421		1415	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD52GSGU0419 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel
1412	Sleeper Truck Tractor S/N: 3AKJGLD57GSHV4416 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 27284 Engine hrs, Engine Brake, Detroit DT12-DA- 1550 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 873,575 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 413 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor		Engine, Engine Brake, Detroit DT12-DA 12-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,114,394 Mi Asset located in: Lake Worth, TX
1413		1416	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG3GSGX0680 C/W: Cummins ISX 6 Cylinder Diesel 450 hp Engine, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 790,465 Mi
	S/N: 3AKJGLBG0GSGY9123 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel		Asset located in: Lake Worth, TX
	450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 3793 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 666,327 Mi Notes: . Asset located in: Lake Worth, TX	1417	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD50GSHA9524 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th
1414	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG2GSHB0517 C/W: Cummins ISX15 450ST2 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 29538 Engine		Wheel, Dual Fuel Tanks Usage: 778,378 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in	1418	2016 Freightliner Cascadia 125 T/A Sleeper Truck Tractor

Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 772,091 Mi

Asset located in: Lake Worth, TX

1419 2016 Freightliner Cascadia 125 T/A Sleeper **Truck Tractor**

Asset located in: Lake Worth, TX

S/N: 1FUJGLD54GLHB1188 Usage: Not Available

S/N: 1FUJGLD53GLHH3522 Usage: Not Available

Lot #	Details	Lot #	Details
1421	1421 2016 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKGGLD55GSGC5502 C/W: Detroit DD15 Engine, Detroit DT12 Automatic Transmission, Air Ride Cab, Air Ride Suspension Usage: 618,196 Mi Asset located in: Lake Worth, TX CHOICE OF 5 - Lot #'s: 1422, 1423, 1424, 1425, 1426		2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR6GSHD7573 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in Condo Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 669,139 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid,	1426	2016 Freightliner Cascadia 125 6x4 T/A
	Engine Brake, 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 880,832 Mi Asset located in: Humble, TX	1420	Sleeper Truck Tractor S/N: 1FUJGLD50GLHF0201 C/W: Detroit Remanufactured 1/19/23 6 Cylinder Ultra Low Sulfur Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OA-1750 12-Speed Automated Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4HT Drive Axles, 3.23:1 Axle Ratio,
1423	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBGXGSHT7100 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24362 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed		53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: Asset located in: Lake Worth, TX
1424	Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 606,456 Mi Asset located in: Lake Worth, TX 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor	1427	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV4FLGM6667 C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18642 Engine hrs, Eaton Fuller 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	S/N: 1FUJGLD56GLGU2007 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455		Usage: 632,880 Mi Asset located in : Humble, TX
	hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27811 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 812,953 Mi Asset located in: Livingston, LA	1427A	

		1		
Lot #	Details	Lot #	Details	
CHOIC 1434, 1	E OF 7 - Lot #'s: 1428, 1429, 1430, 1432, 1433, 435	1432	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD55FSGB5654 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455	
1428	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD57FLGE5847 C/W: Detroit 6 Cylinder 14.8 L Diesel Engine, 2014 US EPA Label, Engine Brake, Detroit DT12- DA 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40- 14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 834,687 Mi		hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 33891 Engine hrs, Engine Brake, Detroit DT12-OA-1650 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 986,645 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Asset located in: Lake Worth, TX	1433	2015 Freightliner Cascadia 125 6x4 T/A	
1429	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG3FSGU4319 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 29056 Engine hrs, Engine Brake, Eaton Fuller FO- 16E310C Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 295		Sleeper Truck Tractor S/N: 1FUJGLD54FLGE3862 C/W: Detroit 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 724,909 Mi	
	/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel		Asset located in: Midland, TX	
	Tanks Usage: 832,290 Mi Asset located in : Lake Worth, TX	1434	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD53FSGH9952	
1430	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG5FSGC7243 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 23900 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires,		hj Ex 12 A: H H Fi R: 51	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 45413 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 882,767 Mi Asset located in: Humble, TX
	Airliner Air Ride Suspension, 216 in Wheelbase Usage: 742,719 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1435	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGHDV8FSGL7536 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17707 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Usage: 664,589 Mi

Lot #	Details	Lot #	Details
1436	2015 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLBG1FSGN2970 Usage: Not Available Asset located in: Lake Worth, TX	1442	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD5XELFM3669 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO- 16913A 13-Speed Manual Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.20:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 733,766 Mi Asset located in: Humble, TX
1437	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD52FSGK9029 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 24896 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Suspension, 230 in Wheelbase, Air Sliding 5th		
	Wheel, Dual Fuel Tanks Usage: 697,727 Mi	CHOIC	E OF 4 - Lot #'s: 1443, 1444, 1445, 1446
1438	Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor	1443	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV0ELFK3902
	S/N: 3AKJGLD54FSFK4749 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 22930 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 588,173 Mi Asset located in: Midland, TX		C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 542,197 Mi Asset located in: Lake Worth, TX
СНОІСІ	E OF 3 - Lot #'s: 1439, 1440, 1442	1444	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD58ESFK2646
1439	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD53FSGM5613 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 724,691 Mi Asset located in: Humble, TX		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 27101 Engine hrs, Engine Brake, Eaton Fuller RTOCM-16909A 13-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 46350 lb GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 191,299 Mi Asset located in: Humble, TX
1440	2015 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLD54FSGG3288 Usage: Not Available		

Details Lot # **Details** Lot # 1445 2014 Freightliner Cascadia 125 6x4 T/A 1448 2013 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** Sleeper Truck Tractor S/N: 3AKJGLD50ESFY3229 S/N: 1FUJGLBG4DSBZ8339 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 2.53:1 Axle Ratio, hp Engine, Requires Diesel Exhaust Fluid, 24797 Engine hrs, Engine Brake, Detroit DT12-OA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 52000 lb GVWR, Air Ride Cab, 72 in High Rise Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Sleeper Cab, Bunk Beds, Aluminum Outer Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Conditioner, 295/75R22.5, Airliner Air Ride Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks Suspension, 228 in Wheelbase, Air Sliding 5th Usage: Not Available Wheel, Dual Fuel Tanks Notes: THIS UNIT IS BEING SOLD WITH A Usage: 816,732 Mi **BONDED TITLE** Notes: DEFICIENCIES NOTED - PLEASE SEE Asset located in: Lake Worth, TX THE INSPECTION REPORT 1449 2013 Freightliner Cascadia 6x4 T/A Sleeper Asset located in: Humble, TX **Truck Tractor** 1446 2014 Freightliner Cascadia 125 6x4 T/A S/N: 3AKJGLDR7DSBB5155 Sleeper Truck Tractor C/W: 6 Cylinder Diesel 455 hp Engine, 27508.2 S/N: 3AKJGLD52ESFR3485 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, hp Engine, US EPA Label, Requires Diesel 12000 lb Front Axle, 40000 lb Rears, Meritor Exhaust Fluid, 22596 Engine hrs, Engine Brake, MT-40-14X Drive Axles, 52000 lb GVWR, Air Eaton Fuller 10-Speed Manual Transmission, Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Rear Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Tanks Ride Suspension, 238 in Wheelbase, Air Sliding Usage: 128,090 Mi 5th Wheel, Headache Rack, Dual Fuel Tanks Notes: ODOMETER DISCREPANCY-PLEASE Usage: 899,662 Mi SEE INSPECTION REPORT DEFICIENCIES Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Asset located in: Humble, TX

CHOICE OF 3 - Lot #'s: 1447, 1448, 1449

1447 2013 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR8DLBV8807 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel

Usage: 1,278,392 Mi

Asset located in: Lake Worth, TX

CHOICE OF 3 - Lot #'s: 1450, 1451, 1452

1450 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR8CSBT4009 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Details Lot # **Details** Lot # 1451 2012 Freightliner Cascadia 125 6x4 T/A 1455 2018 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJGHDV9JSJJ2300 S/N: 1FUJGLBG4CSBP1768 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 209 in Wheelbase, Air Sliding Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, PTO, Hydraulic Oil Cooler, Air Sliding 5th Wheel, Dual 5th Wheel Usage: 649,665 Mi **Fuel Tanks** Asset located in: Midland, TX Usage: 592,035 Mi Asset located in: Humble, TX CHOICE OF 2 - Lot #'s: 1457, 1458 1452 2012 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** S/N: 1FUJGLBG1CSBM5211 1457 2016 Freightliner Cascadia 113 6x4 T/A C/W: Cummins ISX 15 L Diesel 450 hp Engine, Sleeper Truck Tractor 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C S/N: 1FUJGHDV9GLGS0046 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 10-Speed Manual Transmission, Differential hp Engine, 2015 US EPA Label, CARB Lock, 12350 lb Front Axle, 40000 lb Rears, 3.42: Compliant, Requires Diesel Exhaust Fluid, 1 Axle Ratio, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Wheel, Dual Fuel Tanks Usage: 899,518 Mi Asset located in: Lake Worth, TX Usage: 762,092 Mi 1453 2010 Freightliner Cascadia 125 6x4 T/A Asset located in: Humble, TX Sleeper Truck Tractor S/N: 1FUJGLDR0ASAS4603 1458 2016 Freightliner Cascadia 113 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Sleeper Truck Tractor hp Engine, Requires Diesel Exhaust Fluid, S/N: 1FUJGHDV2GLGS0048 Engine Brake, Eaton Fuller FR-15210B 10-C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-Speed Manual Transmission, 12000 lb Front Axle, 35268 lb Rears, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, 47268 lb GVWR, Air 16210C 10-Speed Manual Transmission, Ride Cab, 72 in Condo Sleeper Cab, Bunk Beds, 13300 lb Front Axle, 40000 lb Rears, 3.31:1 Aluminum Wheels, 295/75R22.5, Airliner Air Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 225 in Usage: 836,813 Mi Wheelbase, Hydraulic Oil Cooler, Air Sliding 5th Asset located in: Lake Worth, TX Wheel, Blower, Dual Fuel Tanks Usage: 634,517 Mi Asset located in: Humble, TX

CHOICE OF 2 - Lot #'s: 1454, 1455

1454 2018 Freightliner Cascadia 113 6x4 T/A **Sleeper Truck Tractor**

S/N: 3AKJGHDV8JSJX1807 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650-OH 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks**

Usage: 815,447 Mi

Asset located in: Lake Worth, TX

1459 2014 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGHDV1ESFN7414 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2013 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12300 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, Air Assist Front Suspension, Airliner 4-Bag Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Asset located in: Midland, TX

			Page 141 of 567
Lot #	Details	Lot #	Details
1460	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD55ESFN2395 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 32691 Engine hrs, Engine Brake, Eaton Fuller FRO-16210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Bunk Beds, RigMaster Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 717,423 Mi Asset located in: Lake Worth, TX	1463	2020 Volvo VNR400 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DH8LN270434 C/W: Volvo D11 6 Cylinder 10.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10991 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Volvo Air Ride Suspension, 197 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 304,892 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
1461	CHOICE OF 2 - Lot #'s: 1461, 1462 1461 2018 Western Star 5700 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR2JLJZ0716 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, Requires Diesel Exhaust Fluid, 27535 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40009 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab,	1464	2018 Volvo VNL300 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH1JN899041 C/W: Volvo D13M425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12-Speed Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 568,767 Mi Asset located in: Lake Worth, TX
	Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding	1466	2017 Volvo VNL 6x4 T/A Sleeper Truck Tractor
1462	5th Wheel, Dual Fuel Tanks Usage: 653,881 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2 2017 Western Star 5700 XE 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDRXHLJE5495 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2017 US EPA Label, Requires Diesel		S/N: 4V4NC9EH4HN971537 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 838,421 Mi Asset located in: Lake Worth, TX
	Exhaust Fluid, 27690 Engine hrs, Retarder, Detroit DT12-0A-1650 12-Speed Automated	1468	2017 Volvo VNL630 6x4 T/A Sleeper Truck
	Transmission, 13300 lb Front Axle, 40000 lb	300	Tractor

Rears, 3.23:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 54 in Mid Roof Sleeper Cab, 11R22.5, Airliner Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,491 Mi

Asset located in: Lake Worth, TX

Tractor

S/N: 4V4NC9EG2HN990322 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 405 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612D 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 505750 bb GVWR, 61 in Mid Roof Sleeper Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 645,246 Mi

Lot #	Details	Lot #	Details
1469	2016 Volvo VNL 64T 630 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EJ3GN946212 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 500 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 61 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Volvo Air Ride Suspension, 136 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TH2FN912681 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 42 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 480,143 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 480,143, TITLE SHOWS 485,418; THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1473	2012 Volvo VNL T/A Sleeper Truck Tractor S/N: 4V4NC9EH0CN543487 Usage: Not Available Asset located in: Lake Worth, TX
		CHOICE OF 3 - Lot #'s: 1474, 1475, 1476	
		1474	2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR4JN524544 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Front Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 433,846 Mi Asset located in: Lake Worth, TX
1470			
		1475	2018 International LT62F T/A Sleeper Truck Tractor S/N: 3HSDZAPR3JN532604 Usage: Not Available Asset located in: Lake Worth, TX
		1476A	2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR2JN247098 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11639 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 429,685 Mi Asset located in: Lake Worth, TX 2018 International LT625 T/A Sleeper Truck
1471	Asset located in: Humble, TX 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor		Tractor S/N: 3HSDZAPR4JN233073 Usage: Not Available
	S/N: 4V4NC9EH3FN916526 C/W: Volvo D13J425 6 Cylinder 12.8 L 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 763,465 Mi Asset located in: Lake Worth, TX	1476B	Asset located in: Humble, TX 2018 International LT625 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9JN326333 Usage: Not Available Asset located in: Humble, TX
1472	2013 Volvo VNL T/A Sleeper Truck Tractor S/N: 4V4NC9TG2DN142504 Usage: Not Available Asset located in: Lake Worth, TX		

Page 143 of 567 Lot # **Details** Lot # Details CHOICE OF 4 - Lot #'s: 1477, 1478, 1479, 1480 CHOICE OF 5 - Lot #'s: 1481, 1482, 1483, 1484, 1485 1477 2017 International Prostar 6x4 T/A Sleeper 1481 2016 International Prostar 6x2 T/A Sleeper Truck Tractor Truck Tractor S/N: 3HSDJAPR8HN284030 S/N: 3HSDJSNR0GN058653 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp C/W: International N13 6 Cylinder 12.4 L Diesel Engine, 2016 US EPA Label, Requires Diesel Engine, Requires Diesel Exhaust Fluid, Engine Exhaust Fluid, 14712 Engine hrs, Automated Brake, Allison Automatic Transmission, 12350 Transmission, 13200 lb Front Axle, 40000 lb lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Front Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Dual Fuel Tanks Super Singles Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Usage: 842,762 Mi **Fuel Tanks** Asset located in: Lake Worth, TX Usage: 644,916 Mi 1482 2016 International Prostar+ 122 6x4 T/A Notes: . Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 3HSDJAPR2GN428556 1478 2017 International Prostar+ 122 6x4 T/A C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Sleeper Truck Tractor Exhaust Fluid, 16496 Engine hrs, Engine Brake, S/N: 3HSDJSNR2HN447862 Automated Transmission, 12350 lb Front Axle, C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, Exhaust Fluid, 19396 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 224 in Wheelbase, Dual Fuel Tanks Usage: 614,573 Mi Aluminum Wheels, 295/75R22.5 Front Tires, Asset located in: Lake Worth, TX 445/50R22.5 Super Singles Rear Tires, Air Ride

Usage: 542,861 Mi Asset located in: Lake Worth, TX

Wheel, Dual Fuel Tanks

1479 2017 International ProStar T/A Sleeper Truck Tractor

Suspension, 226 in Wheelbase, Air Sliding 5th

S/N: 3HSDJAPR1HN693549 Usage: Not Available

Asset located in: Humble, TX

1480 2017 International ProStar 6x4 T/A Sleeper Truck Tractor

S/N: 3HSDJAPR1HN204325 C/W: Cummins ISX 450ST 6 Cylinder 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 73 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, 267 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 505,833 Mi

Asset located in: Humble, TX

1483 2015 International ProStar 6x4 T/A Sleeper **Truck Tractor**

S/N: 3HSDJAPR3FN676250 C/W: Cummins ISX15 15 L Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19816 Engine hrs, Engine Brake, 9-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 73 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 654,586 Hr

Notes: THIS UNIT RUNS BUT MAY HAVE **DEFICIENCIES IN ITS POLLUTION CONTROL** SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

			1 age 144 of 307
Lot #	Details	Lot #	Details
1484	2015 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR9FN526675 C/W: Cummins ISX 400ST 6 Cylinder Diesel 218 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 275 /80R22.5, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 676,438 Mi Asset located in: Humble, TX	1488 CHOIC	2014 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR8EN418495 C/W: International MaxxForce 13 6 Cylinder 13 L Diesel Engine, Automatic Transmission Usage: Not Available Asset located in: Lake Worth, TX E OF 2 - Lot #s: 1490, 1491 2012 International Prostar 6x4 T/A Sleeper
1485	2015 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR3FN668830 C/W: Cummins ISX 400ST 6 Cylinder Diesel 218 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 19195 Engine hrs, Engine Brake, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 658,953 Mi		Truck Tractor S/N: 3HSDJSJR7CN094078 C/W: 6 Cylinder Diesel Engine, 34209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 11R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 689,264 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	1491	2012 International Prostar 6x4 T/A Sleeper
CHOIC 1486	E OF 3 - Lot #'s: 1486, 1487, 1488 2014 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR7EN796955 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17185 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires,		Truck Tractor S/N: 3HSDJSJR1CN094075 C/W: 6 Cylinder Diesel Engine, 27815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 798,884 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1487	Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 658,173 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR7EN759578 C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17281 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 549,311 Mi	1492	2005 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X55R076276 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, 13-Speed Manual Transmission, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 106,655 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
1493	2007 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X87N667738 C/W: Cat C15 6 Cylinder Diesel 550 hp Engine, 35138.1 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, COLEMAN MACK Electric Sleeper Air Conditioner, 3cyl KUBOTA Auxiliary Power Unit, 315/80R22.5 Front Tires, 285/75R24.5 Rear Tires, Low Air Leaf Air Ride Suspension, 312 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, Custom Condo Sleeper Equipped with Shower/Toilet	1497	2005 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDB9X95J099229 C/W: Cat C15 6 Cylinder 15 L Diesel 475 hp Engine, 30565 Engine hrs, Engine Brake, Eaton Fuller 10-Speed hybrid, automatic with clutch Transmission, 40000 lb Rears, Dana DSP40 Drive Axles, 3.36:1 Axle Ratio, 62 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, 4- Bag Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 161,706 Mi Asset located in: Lake Worth, TX
	Combo, Convection Oven and Refrigerator Usage: 1,479,428 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	1498	1996 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDR9XXTR729761 C/W: Detroit/series60 6 Cylinder 12.7 L Diesel 470 hp Engine, 1996 US EPA Label, Engine Brake, Manual Transmission, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 258 in Wheelbase, Air Sliding
1494	2003 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X43D802164		5th Wheel, Dual Fuel Tanks Usage: 310,988 Mi Asset located in : Lake Worth, TX
	C/W: Cat C15 6 Cylinder 14.6 L Diesel 475 hp Engine, 2001 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Aluminum Wheels, 285/75R24.5, Low Air Leaf Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 93,811 Mi	1499	2005 Freightliner Coronado 132 6x4 T/A Sleeper Truck Tractor S/N: 1FUJCRCK65PU90416 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2004 US EPA Label, Engine Brake, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles,
1495	Asset located in: Lake Worth, TX 2000 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DR9X3YD506553 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 450 hp Engine, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride	1500	3.58:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295/75R22.5, Air Assist Front Suspension, Airliner Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,885,684 Mi Asset located in: Lake Worth, TX
	Cab, 58 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Leaf 4-Bag Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 455,326 Mi Asset located in: Humble, TX		2006 International 9400L 6x4 T/A Sleeper Truck Tractor S/N: 2HSCNSCR46C195887 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission,
1496	2007 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDD40X17R994789 C/W: Cummins ISX 6 Cylinder 15 L Diesel 475 hp Engine, 2005 US EPA Label, 10738 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, 4.30:1 Axle Ratio, 59220 lb GVWR, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel Usage: 276,651 Mi Asset located in: Midland, TX		12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 72 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,001,440 Mi Asset located in: Lake Worth, TX
		1501	2006 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7DB9X16D896274 C/W: Cat C15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, Low Air Leaf Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,814,828 Mi

Lot #	Details	Lot #	Details
1502	2007 Kenworth T600 6x4 T/A Sleeper Truck Tractor S/N: 1XKADB9X57J158461 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller RTLOC16909AT2 Manual Transmission, Dana DSP40 Drive Axles, 3.55:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,098,883 Mi Asset located in: Lake Worth, TX	1507	2005 Mack CX613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AE05Y75N021491 C/W: Mack 6 Cylinder Diesel Engine, 2004 US EPA Label, 15393 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 211 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 517,922 Hr Asset located in: Lake Worth, TX
1503	2005 Kenworth T2000 6x4 T/A Sleeper Truck Tractor S/N: 1XKTDB9X15J058198 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, Spicer DSP40 Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	1508	2008 International ProStar Premium 6x4 T/A Sleeper Truck Tractor S/N: 2HSCUAPR48C686955 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,049,713 Mi Asset located in: Lake Worth, TX
1504	2009 Mack CXU613 Pinnacle 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW09Y49N006962 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available	-1509	2006 International 9400i 6x4 T/A Sleeper Truck Tractor S/N: 2HSCNAPR16C228106 C/W: Cummins ISX 14.9 L Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,412,255 Mi Asset located in: Lake Worth, TX
СНОІС	Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1505, 1506		2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK19LAD2685 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel
1505	2006 Mack CXN613 T/A Sleeper Truck Tractor S/N: 1M1AK07YX6N011822 Usage: Not Available Asset located in: Lake Worth, TX	Rears, Dana DS404 Drive Axles, 3.55 Ratio, 52000 lb GVWR, Air Ride Cab, 1 Roof Sleeper Cab, 11R22.5 Front Tire	
1506	Tractor S/N: 1M1AK06Y86N014932 C/W: Mack AC 6 Cylinder Diesel 380 hp Engine,		Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 587,873 Mi Asset located in : Humble, TX
		1511	2007 Freightliner Century Class CST120 6x4 T /A Sleeper Truck Tractor S/N: 1FUJBBAV37LX21774 C/W: Cat C15 6 Cylinder Diesel Engine, 18993 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks Usage: 955,175 Mi Asset located in: Humble, TX

1510		Lot #	Details
1512	2006 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor	1517	1996 Freightliner USF-E1 6x4 T/A Sleeper Truck Tractor
	S/N: 1FUJA6CK86LV66960 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2005 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, 295/75R22.5, Airliner Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,027,381 Mi		S/N: 1FUYDDYBXTP613588 C/W: 6 Cylinder Diesel Engine, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 285/75R24.5 Front Tires, 11R24. 5 Rear Tires, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
1514	2001 Freightliner ST120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJBBBD91LH91702 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 435 hp Engine, 2000 US EPA Label, Meritor MO- 14G10A-M14 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT- 40-145 Drive Axles, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Suspension, 226 in Wheelbase, Dual	СНОІС	E OF 2 - Lot #'s: 1518, 1519
		1518	2023 Capacity TJ5000 Spotter Truck S/N: 4LMBF5111PL041353 C/W: Allison Automatic Transmission, 295 /75R22.5, 130 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Asset located in: Lake Worth, TX
		1519	2023 Capacity 4x2 Spotter Truck S/N: 4LMBF5119PL041360 C/W: Cummins 6 Cylinder Diesel Engine,
1515	2000 Freightliner FLD 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUPCSEB4YDF85578 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, 1999 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 972,743 Mi Asset located in: Midland, TX 1995 Freightliner FLD 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUPDZYB7SH718722 C/W: Detroit 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R24.5, Air Ride Suspension, 246 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 687,717 Mi Asset located in: Humble, TX		Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 11R22.5, 132 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Asset located in : Humble, TX
		1520	2021 Capacity 4x2 Spotter Truck S/N: 4LMBF2115ML029314 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, 116 in Wheelbase, PTO, Hydraulic Lift 5th Wheel
1516			Usage: 30,689 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX
		СНОІС	E OF 2 - Lot #'s: 1521, 1522
		1521	2019 Ottawa 6x4 Spotter Truck S/N: 4LMDB7136KL027975 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 173 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5750 Engine hrs, Allison

40000 lb Rears, 60000 lb GVWR, Steel, 11R22.5 Front Tires, 255/70R22.5 Rear Tires, 154 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 8,516 Mi

Lot #	Details	Lot #	Details
1522	2019 Ottawa 4x2 Spotter Truck S/N: 4LMSB2114KL031788 C/W: Cummins QSB4.5 4 Cylinder 5.4 L Diesel 173 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 24000 lb Rears, Steel, 11R22.5, 115 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 10,626 Mi Asset located in: Lake Worth, TX	1527	
1523	2017 Ottawa T2 4x2 Spotter Truck S/N: 343984 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200		OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	hp Engine, 2016 US EPA Label, 7207 Engine hrs, Allison Transmission, Steel, 11R22.5, Spring Suspension, 116 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 30,805 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	1528	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2118BL022569 C/W: Cummins 6 Cylinder Diesel Engine, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
1524	2015 Ottawa Sabre 5 4x2 Spotter Truck S/N: 335984		Asset located in: Lake Worth, TX
	C/W: Cummins QSB 6.7 L 165 hp Engine, 2014 US EPA Label, Allison Transmission, 295 /75R22.5, 118 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX	1529	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR211XBL022573 C/W: Cummins 6.7 L Diesel Engine, Allison Automatic Transmission, 275/80R22.5, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 25,696 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
CHOIC	E OF 5 - Lot #'s: 1525, 1526, 1527, 1528, 1529	1530	2008 Ottawa TY30 4x2 Spotter Truck
1525	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2110BL022565 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2014 US EPA Label, Allison Automatic Transmission, 12000 lb Front Axle, 23000 lb Rears, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL		S/N: 318992 C/W: Cummins QSB 6 Cylinder 6.7 L Diesel Engine, Allison Automatic Transmission, 275 /80R22.5, 111 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	1531	2006 Ottawa TY30 4x2 Spotter Truck S/N: 314014
1526	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2112BL022566 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2014 US EPA Label, Automatic Transmission, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		C/W: Cummins USB 6 Cylinder 5.9 L 155 hp Engine, Automatic Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1532	CRC PB Pipe Bending Machine S/N: 20-267 C/W: Bends 6 in to 20 in Pipe, Tow Behind, Winch, Kubota Diesel Engine Usage: 1,103 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	1539	Tornado F4SL on 2015 Western Star 4900 8x6 Vacuum Excavator Truck S/N: 5KKPALD10FPGA1440 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2014 US EPA Label, Requires Diese Exhaust Fluid, 35902 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Triple Differential Locks, 20000 lb Front Axle, 57000 lb Rears, 4.30:1 Axle Ratio, 77000 lb GVWR, Air Ride Cab, Aluminum Wheels, 445 /65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Airliner Suspension, 303 in Wheelbase, Steel 2150 gal Debris Tank, Hydraulic Tailgate Locks, Telescopic Boom, 8 in Suction Hose, Cat Hydraulic Driven Pump, Robuschi Blower w/ 5642 hrs, Hotshot Boiler, Cordless Remote Control, 77000 lb GVWR Usage: 10,861 Km
1534	2012 Tensioner S/N: 1F9UZ1313CV048037 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		
1535	2008 TSE T/A Tensioner S/N: 1T92C15238S268017		Asset located in: Lake Worth, TX
	C/W: 2007 US EPA Label, John Deere 4024TF270C 4 Cylinder Diesel Engine Usage: Not Available Asset located in : Lake Worth, TX	1540	2013 Western Star 4900 Vacuum Excavator Truck S/N: 5KKPALDR6DPBH7992 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 530
1536	2003 Sherman Reily T/A Tensioner S/N: 123WM212831T16188 C/W: Honda 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		hp Engine, Requires Diesel Exhaust Fluid, 810 Engine hrs, Engine Brake, Eaton Fuller RTLO- 18918B Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 56700 lb Rears, Meritor RZ-166 Drive Axles, 4.56:1 Axle Ratio, 76700 lb GVWR, Air Ride Cab,
1537	2011 Wagner-Smith T-5DP-120 Hydraulic Cable Puller S/N: 1W9DP4321BA161085 C/W: 2010 US EPA Label, John Deere 4 Cylinder Diesel Engine, (5) Reels; EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Tires, 11R24.5 Rear Tires, Dual Ste Double Frame, Airliner Air Ride Sus 318 in Wheelbase, PTO, Hydraulic Steel Debris Tank, Hydraulic Lift T Hydraulic Tailgate Locks, Telesco in Suction Hose, Cat Hydraulic Dri Robuschi Blower, Cordless Remot 76700 lb GVWR Usage: 105,864 Mi
1538	Altec AT235P 35 ft on 2015 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GT5FED59378 C/W: Ford 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 165 in Wheelbase, 300 lb Capacity, Front Mounted, One-Person Articulating-Telescopic Boom, Utility Body, 11 ft x 94 in Bed Usage: 75,582 Mi Asset located in: Lake Worth, TX	1541	Hi-Vac X-10 on 2015 Peterbilt 367 Vacuum Excavator Truck S/N: 1NPTL40X1FD270583 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
		1542	Gap-Vac on 2002 Volvo VHD 6x4 Vacuum Excavator Truck S/N: 4V5KC9UF92N321981 C/W: Cummins ISM 10.8 L Diesel 325 hp Engine, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000.0 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring over Walking Beam Suspension, 254 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, PTO Driven Pump, 64000.0 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

L at #	Details	Lot #	Details
Lot # 1543	Vactor 2100 Series on 2002 Sterling L9500 6x4 Vacuum Excavator Truck S/N: 2FZHAZAS02AK42561 C/W: Cat C12 6 Cylinder Diesel 355 hp Engine, 8023 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Steel, 425 /65R22.5, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 252 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Boom, 8 in Suction Hose, PTO Driven Pump, Roots 824RSCV18 Blower, 66000 lb GVWR Usage: 134,573 Mi		1547 2014 International 7600 6x4 Vacuum Tanker Truck S/N: 1HTGSSNTXEH029640 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 46000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Air Ride Suspension, 228 in Wheelbase, 2000 gal Debris Tank, 64000 lb GVWR Usage: 240,009 Mi Asset located in: Lake Worth, TX
1544	Asset located in: Lake Worth, TX 2001 Ford F-550 XL 4x2 Vacuum Excavator Truck S/N: 1FDAF56F71EC85002 C/W: Ford 7.3 V8 7.3 L Diesel Engine, 978 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR,		S/N: 1HTWCAZN2DJ200547 C/W: 6 Cylinder Diesel Engine, Eaton Fuller 8LL Manual Transmission, 10000 lb Front Axle, 23000 lb Rears, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Spring Suspension, 222 in Wheelbase, PTO, weatherford Triplex Pump, Fiberglass Reinforced Plastic Tank Usage: 221,859 Mi Asset located in: Lake Worth, TX
CHOICI	Steel, 225/70R19.5, Spring Suspension, 201 in Wheelbase, 100 gal Debris Tank, Rear Hose Reel, 4 in Suction Hose, 17500 lb GVWR Usage: 233,622 Mi Asset located in: Lake Worth, TX IOICE OF 2 - Lot #'s: 1545, 1546	1549	Elgin Crosswind on 2013 Freightliner M2 106 Sweeper Truck S/N: 1FVACXDT5DHFB1562 C/W: Cummins 6.7 L Diesel 200 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 11R22.5, Spring Suspension, Auxiliary Engine, Under Body Broom Usage: 44,365 Mi
1545	2013 Mack GU713 3800 gal 6x4 Vacuum Tanker Truck S/N: 1M2AX07C0DM014703		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 27175 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 38000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 268 in Wheelbase, Aluminum 3800 gal Debris Tank, Non Code Code, Manual Tailgate Locks, PTO Driven Pump, 38000 lb GVWR	1550	2000 International 9900 6x4 Winch Truck S/N: 2HSFTAER6YC050198 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 435 hp Engine, Eaton Fuller 8LL Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Steel, 11R22.5, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, Tail Roll, Tulsa Winch Usage: 540,116 Mi Asset located in: Lake Worth, TX
	Usage: 402,799 Mi Asset located in : Lake Worth, TX	1551	1995 International 9200 6x4 Winch Truck
1546	2012 Mack GU713 8x4 Vacuum Tanker Truck S/N: 1M2AX07C8CM012213 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, Air Ride Cab, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Ride Suspension, 272 in Wheelbase, Aluminum Debris Tank, 64000 lb GVWR Usage: 469,818 Mi Asset located in: Lake Worth, TX		S/N: 2HSFMAHR6SC052503 C/W: Cummins 6 Cylinder 10.8 L Diesel 370 hp Engine, 1995 US EPA Label, Spicer 10-Speed Manual Transmission, 295/75R22.5, Air Ride Suspension, 190 in Wheelbase, Tulsa Winch, Air sliding fifth wheel Usage: 691,448 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1552	Texoma 500-15 on 2004 International 7400 6x4 Pressure Digger S/N: 1HTWGADT34J083149 C/W: Detroit 4 Cylinder Upper Engine, Winch, Straight Down Outriggers, Rear Outriggers, Bumper Mounted Winch, International 6 Cylinder Diesel Engine, 10013 Engine hrs, Allison Automatic Transmission, Differential Lock, 16000 lb Front Axle, 53120 lb Rears, 56000 lb GVWR, Air Ride Cab, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 205 in Wheelbase	1559	Quantity of (2) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
		1560	2011 Vermeer D100X120II Directional Drill S/N: 1VRZ33046B1000486 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
	Usage: 91,448 Mi Asset located in : Lake Worth, TX	1561	2008 Vermeer D100X120II Directional Drill
1554	Texoma 3301500 on 1993 Mack RD690S 4x2 Drill Truck S/N: 1M2P264Y0PM013308 C/W: Cummins 4BTA3.9-C 3.9 L 4 Cylinder		S/N: 1VRZ3304781000182 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Asset located in : Humble, TX
	Upper Engine, Mack EM7 6 Cylinder Diesel 300 hp Engine, 1993 US EPA Label, 16469 Engine hrs, Eaton Fuller 9-Speed Manual Transmission, Steel, 11R24.5, Camelback Spring Suspension, 212 in Wheelbase Usage: 273,655 Mi Asset located in: Lake Worth, TX	1562	2007 Vermeer D100X120II Directional Drill S/N: 1VRZ3304471000168 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
1555	Texoma 600 on 1985 International F-1954 6x4 Drill Truck S/N: 1HTLKTVR9FHA26144 C/W: Deutz TCD2012L042V 4.0 L 4 Cylinder Upper Engine, Winch, Out and Down Outriggers, Rear Outriggers, 6 Cylinder Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 11R22.5, Double Frame, Hendrickson RT/RTE Series Suspension, 206 in Wheelbase Usage: 164,298 Mi Asset located in: Lake Worth, TX	1575	Star 185K on 2008 Gefco Star 185K 10x4 Tw Steer Drill Truck S/N: 907835 C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder 14 L Diesel 665 h Engine, 2007 US EPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 44000 lb Front Axle, 74240 lb Rears, 118240 GVWR, Aluminum Wheels, 425/65R22.5 Fron Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle
1556	Texoma 270 on 1984 International 1954 4x2 Drill Truck S/N: 1HTLDUXP6EHA31702	1576	Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 8,461 Hr Asset located in : Cedar Bluff, VA
	C/W: John Deere 4045DF 6.8 L 4 Cylinder Upper Engine, Straight Down Outriggers, Rear Outriggers, 6 Cylinder Diesel Engine, Manual Transmission, 11R22.5, Spring Suspension, 170 in Wheelbase Usage: 280,022 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		Star 150K on 2006 Gefco Star 150K 10x4 Twin- Steer Drill Truck S/N: 907730 C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder 14.0 L Diesel 665 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission,
1557	2019 Thunder Vermeer R250C Mud Mixing System S/N: 56ZL2UZ20KP000069 C/W: (4) Shale Shakers, John Deere 4045 4 Cylinder 4.5 L Diesel Engine Usage: 1,607 Hr Asset located in: Lake Worth, TX		44000 lb Front Axle, 54240 lb Rears, 98240 lb GVWR, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 3,356 Hr Asset located in: Cedar Bluff, VA
1558	Quantity of (4) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
1577	Star 150 on 2004 Gefco Star 150K 10x4 Twin- Steer Drill Truck S/N: 907612 C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 42000 lb Front Axle, 74240 lb Rears, 116240 lb GVWR, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 294 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC	1583	(Rig#24) 3-Pit Mud System Mud Tank S/N: Not Available C/W: shopbuilt 8'W x 6'h x 20'L 220-BBL premix tank mud agitator, shopbuilt 8'W x 6'H x 30'L 206-BBL suction tank mud agitators, Shopbuilt 8'W x 6'H x 30'L 206-BBL shaker tank, Vortex Orbital 3000M single screen linear motion shale shaker, all skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
	Usage: Not Available Asset located in: Cedar Bluff, VA	1584	(Rig#24) Fuel Tank & Parts House S/N: Not Available	
1578	(Rig#24) Lee C Moore 133 ft Cantilever Mast S/N: T1728 C/W: 470,000 Lb Static Hook Load, Crown Block, w/ Sheave Cluster, Fastline Sheave, Racking Board, Tong Counter Weights, Ladder, Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, qty 4 (2) sets of 40"H x		C/W: 7'W x 12'L round top flat steel parts house w/ 4'L covered porch extension, shelving fluorescent lighting skidded, 8'W x 8'H x 21'L 10,000 gallon fuel tank, w/ 8'L porch extension, (2) 110V pumps, skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
	30'L triangular pipe racks, block hook combo, drill line spool ; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1585	(Rig#24) Quantity of (2) Cat Containerized Generator Set S/N: Not Available C/W: Cat 3406 Diesel Engine, Electrical panels,	
1579	(Rig#24) 28 ft x 16 ft x 46 ft 9 in Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC	1586	Fluorescent lighting, Storage area, Sullivan Palatek compressor ; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
	Usage: Not Available Asset located in: Coleman, TX		(Rig#24) National 55 S/D Drawworks Drawworks	
1580	(Rig#24) 10 ft x 32 ft Doghouse S/N: Not Available C/W: knowledge box, bench storage, lockers, parts bins, fluorescent lighting, skidded;; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX		C/W: 1,000 Hp, Lebus Grooved for FOSTER Makeup & Breakout Catle Engine in line compound, (2) Nat torque converters, 2-stage air convariations, air start, muffler, maste EQUIPMENT-FROM-TPI-COLEMALLC	S/N: T1890 C/W: 1,000 Hp, Lebus Grooved for 1-1/8" line, FOSTER Makeup & Breakout Catheads,2- Engine in line compound, (2) National c300185 torque converters, 2-stage air compressor, radiators, air start, muffler, master skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available
1581	(Rig#24) 8 ft x 31 ft Mud House		Asset located in: Coleman, TX	
1582	S/N: Not Available C/W: shelving, misc rig parts, skidded, Parts /Change House, Bench Storage, Parts Room; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Asset located in: Coleman, TX (Rig#24) Quantity of (2) 10 ft x 33 ft 500 bbl	1587	S/N: Not Available C/W: Cat 12 Cylinder Diesel Engine, ends w/ screw in caps, pulsation da mud gauge, cent pump, Cat 12V Die air start, radiator, muffler, air and fue master skidded; EQUIPMENT-FRON COLEMAN-PROJECT-LLC	S/N: Not Available C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/ screw in caps, pulsation dampener, mud gauge, cent pump, Cat 12V Diesel engine, air start, radiator, muffler, air and fuel tanks, master skidded; EQUIPMENT-FROM-TPI-
1302	Water Tank		Asset located in: Coleman, TX	
	S/N: Not Available C/W: cent pump, ladder, skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in : Coleman, TX	1588	2010 (Rig#24) RS-F1000 Triplex Mud Pump S/N: RS11012 C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/screw in caps, pulsation dampener, mud gauge, cent pump, bull wheel, belt guard, Cat 12V Diesel engine, air start, radiator, muffler, air volume tank, fuel tank, master skidded; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	

Lot #	Details	Lot #	Details
1589	(Rig#24) 10 ft x 40 ft Toolpusher's House S/N: Not Available C/W: office area, bedroom, bathroom area, kitchen area (gutted) skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1596	596 (Rig#25) 26 ft 1 in x 16 ft x 47 ft Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp, Stairs, Safety Rails, Emsco type 17-1/2" rotary table, Ingeraoll Ran Air hoist, weight indicator, wireline measuring device, National deadman anchor, air volume tank, fold doghouse supports, pony subs,
1590	(Rig#24) Quantity of Closing Unit, Choke Manifold, Lubester, Swivel, Catwalk, Basket S/N: Not Available C/W: 5,000# choke manifold, 8'x 10' x 5' junk		skidded 'EQŪIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in : Coleman, TX
	basket skidded w/contents, 5-station closing unit, 4-compartment lubester; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1597	(Rig#25) 8 ft x 32 ft Doghouse S/N: Not Available C/W: Doghouse, 8'L Covered Porch, Lockers, Knowledge Box, Bench Storage, Cabinets; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-
1591	(Rig#24) 27-½ in Rotary Table S/N: Not Available C/W: w/ Kelly drive bushing housing, chain		LLC Usage: Not Available Asset located in : Coleman, TX
	guard ; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in : Coleman, TX	1598	(Rig#25) 10 ft x 5 ft 10 in x 30 ft 300 bbl Mud Tank S/N: Not Available C/W: VORTEX Orbital 3000M Single, Single
1592	(Rig#24) 6 ft x 3 ft - 6 ft x 28 ft Catwalk S/N: Not Available C/W: assorted gates Usage: Not Available Asset located in: Coleman, TX		Screen, Linear Motion Shale Shaker, mud house, skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX
1593	(Rig#24) Junk Basket S/N: Not Available C/W: air hoist, elevator links, tongs, closing unit remote panel, mud bucket, drill pipe slips, drill collar slips and misc drilling equipment; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC	1599	(Rig#25) Quantity of (2) 500 bbl Water Tank S/N: Not Available C/W: skidded, w/water pump, (4) cent pumps; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Asset located in: Coleman, TX
	Usage: Not Available Asset located in: Coleman, TX	1600	(Rig#25) 8000 gal Fuel Tank S/N: Not Available
1594	(Rig#24) Quantity of Drill Collars S/N: Not Available C/W: 6" OD Drill Collars w/4-1/25" XH Connections (3) 8" OD Drill Collars w/ 6-34" REG	1601	C/W: (2) transfer pumps, ladder; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX
	Connections, (1) Hex Kelley; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX		(Rig#25) Skidded Parts house S/N: Not Available C/W: shelving, lockers, bench storage, fluorescent lighting, skidded; EQUIPMENT-
1595	(Rig#25) Lee C Moore 131 ft Cantilever Mast S/N: T3067 C/W: 440,000 Lb Static Hook Load, Crown,		FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX
	Block w/ (4) 36" Cluster, 54" Fastline Sheave, Racking Board, Tong Counter Weights, Ladder, Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, spool of 1-1/8" drill line, racking board ' EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	ave, idder, and	Parts House S/N: Not Available C/W: flat steel, round top, shelving, bench storage, fluorescent lighting, misc rig parts, skidded; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX

Lot #	Details	Lot #	Details	
1603	Cat (Rig#25) Containerized Generator Set S/N: Not Available C/W: Cat SR4B generator p/b Cat 6-cylinder diesel engine, generator p/b 6-cylinder diesel engine, skidded, electrical control panel, Curtis 30HP air compressor, all mud in 10'W x 40'L generator house, skidded; ; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1609	(Rig#25) 2-Section Catwalk S/N: Not Available C/W: Steel Deck, Ideco swivel, hex Kelly, mouse hole, hex Kelly drive bushing, junk basket w/lift subs and misc, water pump, v- door ramp; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
1604	<u>`</u>	1610	(Rig#25) Junk Box	
1604	(Rig#25) National 50-CA S/D Drawworks S/N: Not Available C/W: w/ (2) Cat D353 Diesel Engines, (2) National C-245-80 Torque Converters, 2-Engine inline compound, Quincy type air compressor, Air start, radiators, Foster makeup and		S/N: Not Available C/W: EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in : Coleman, TX	
	breakout catheads, Levi's grooved f/1-1/8" drill line; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available	СНОІС	E OF 2 - Lot #'s: 1611, 1612	
	Asset located in: Coleman, TX	1611	2006 Bomco 3NB1000C Triplex Mud Pump	
1605	(Rig#25) Quantity of (2) Bomco 3NB1300C Triplex Mud Pump S/N: Not Available C/W: each with forged fluid ends w/ screw in caps, cent pump, Hydril pulsation dampeners, mud gauges, p/b (1) Cat D398, (1) Cat D399PC 12-Cylinder & 16-Cylinder Diesel engines, radiators, master skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX		S/N: 1060917 C/W: Cat 12 Cylinder Diesel Engine, pulsation dampener, bolt on caps, mud gauge, bull wheel skidded, Parkersburg torque converter, radiator, skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
		1612	2006 Bomco 3NB1000C Triplex Mud Pump S/N: 1060919	
1606	(Rig#25) Toolpushers House S/N: Not Available C/W: (1) office, (1) bedroom, (1) bathroom, skidded (doors locked could not access); EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC		caps, pulsation damper pump, manifold, torque and fuel tanks, master : FROM-TPI-COLEMAN-P Usage: Not Available	C/W: Cat 12 Cylinder Diesel Engine, bolt on caps, pulsation dampener, mud gauge, cent pump, manifold, torque converter, radiator, air and fuel tanks, master skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX
	Usage: Not Available Asset located in: Coleman, TX (Rig#25) Sowa Block Hook Combination S/N: Not Available C/W: (2) WTM 4-1/4" - 6 3/4" Rotary Tongs, elevator links, elevator, drill pipe slips, drill collar slips, lift subs, and bit breaker;	1613	2008 NLB Skid Mounted Triplex Test Pump	
1607			S/N: P4012901 C/W: Triplex Cummins N14 6 Cylinder Diesel Engine, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in : Lake Worth, TX	
	EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Asset located in: Coleman, TX	1614	Pai PAI70HP3250 Mud Pump S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine	
1608	(Rig#25) 4-Station Accumulator Closing Unit S/N: Not Available		Usage: 168 Hr Asset located in: Humble, TX	
	S/N: Not Available C/W: Parkersburg brake, (3) suitcases, stairs, tong and misc drilling equipment; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1615	Tulsa Rig Iron Mud Pump S/N: TT150-52 C/W: Triplex 2014 US EPA Label, Cummins 6 Cylinder Diesel Engine Usage: 642 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1616	1998 Triplex Mud Pump S/N: 160 TP 6L C/W: 4 in Intake, 3 in Discharge, Mud Pump, Cat 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1623 2004 Com S/N: C/W EQU Usas Asse 1624 2004 Com S/N: C/W 60 6 FRO Usas Asse	E OF 2 - Lot #'s: 1623, 1624 2004 Sullair 1170 Skid-Mounted Air Compressor
1617	Wheatley HP-250H Skid Mounted Triplex Test Pump S/N: Not Available C/W: 1 in Intake, 1 in Discharge, Triplex Detroit 8W-71 8 Cylinder Diesel Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available		S/N: 006-04011489 C/W: Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA 2004 Sullair 1170 1170 cfm Skid-Mounted Air Compressor
1618	Asset located in: Lake Worth, TX 2012 Keystone Skid-Mounted Booster Air Compressor S/N: MCW02262 C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 1,899 Hr Asset located in: Cedar Bluff, VA		S/N: 006-04011490 C/W: 365 psi Working Pressure, Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
СНОІС	CHOICE OF 4 - Lot #'s: 1619, 1620, 1621, 1622		2008 Ariel JGQ/2 Skid-Mounted Booster Air Compressor S/N: KB102
1619	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 378088 C/W: 365 psi Working Pressure, Cat C15 6		C/W: Cat C7 6 Cylinder 250 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 4,357 Hr Asset located in: Cedar Bluff, VA
	Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 8,391 Hr Asset located in: Cedar Bluff, VA	1626	2003 Ariel Skid-Mounted Booster Air Compressor S/N: KB-10 C/W: Cat 3126 6 Cylinder 309 hp 7.2 L Diesel
1620	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 380841ULQB78 C/W: 365 psi Working Pressure, Cat C15 6		Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 3,541 Hr Asset located in: Cedar Bluff, VA
	Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 8,256 Hr Asset located in: Cedar Bluff, VA	1627 2003 A Comp S/N: E	2003 Ariel Skid-Mounted Booster Air Compressor S/N: BEJ02783 C/W: Cat 6 Cylinder Diesel Engine, EQUIPMENT-
1621	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 378089		FROM-GASCÓ-DRILLING-INC Usage: 906 Hr Asset located in : Cedar Bluff, VA
	C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 9,385 Hr Asset located in: Cedar Bluff, VA	1628	Quantity of (152 joints)(4,712') 4-1/2 in Range 2 Drill Pipe S/N: Not Available C/W: (4,712 ft), w/ 4-1/2" FH conns, w/(6) 3 sets of 40"H x 30'L triangular pipe racks;
1622	2007 Ingersoll Rand XHP1170 Skid-Mounted Air Compressor S/N: 380840ULQB78 C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 11,640 Hr Asset located in: Cedar Bluff, VA		EQUIPMENT-FROM-TPI-COLEMAN-PROJEC LLC Usage: Not Available Asset located in: Coleman, TX

Lot #	Details	Lot #	Details
1629	Quantity of (144) 3-1/2 in Range 2 (4,464') Drill Pipe S/N: Not Available C/W: (4,464 ft), w/3-1/2"IF conns, HB, w/(4) (2) sets of 40"H x 30'L trainagular pipe racks; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-	1638	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	LLC Usage: Not Available Asset located in : Coleman, TX	1639	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available
1630	Quantity of Approximately 6353 ft 4 in Drill Pipe S/N: Not Available C/W: Approximately 6353 ft, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1640	Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available
1631	Quantity of Approximately 12114 ft of 3.5 in Drill Pipe S/N: Not Available C/W: Approximately 12114 ft; EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available	1641	Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1632	Asset located in: Cedar Bluff, VA Quantity of Approximately 5767 ft of 4 in Drill Pipe S/N: Not Available C/W: Approximately 5767 ft; EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available	1642	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Asset located in: Cedar Bluff, VA		E OF 10 - Lot #'s: 1643, 1644, 1645, 1646, 1647, 649, 1650, 1651, 1652
	E OF 10 - Lot #'s: 1633, 1634, 1635, 1636, 1637, 639, 1640, 1641, 1642	1643	Quantity of (5) 4.5 in Drill Collars S/N: Not Available
1633	Quantity of (7) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA
1634	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1644	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
1635	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available	SUBJECT TO 3RD PARTY Asset located in: Cedar E	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars
1636	Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	_	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA
1637	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		Access in occur bian, va

Lot #	Details	Lot #	Details
1646	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		E OF 10 - Lot #'s: 1653, 1654, 1655, 1656, 1657, 659, 1660, 1661, 1662
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA	1653	Quantity of (4) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available
1647	Quantity of (5) 4.5 in Drill Collars		Asset located in: Cedar Bluff, VA
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	1654	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Asset located in: Cedar Bluff, VA	1655	Quantity of (3) 6 in Drill Collars
1648	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in : Cedar Bluff, VA
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA	1656	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available
1649	Quantity of (5) 4.5 in Drill Collars		Asset located in: Cedar Bluff, VA
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	1657	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Asset located in: Cedar Bluff, VA	1658	Quantity of (3) 6 in Drill Collars
1650	Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-GASC Usage: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA	1659	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available
1651	Quantity of (4) 4.5 in Drill Collars S/N: Not Available		Asset located in: Cedar Bluff, VA
	C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	1660	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Asset located in: Cedar Bluff, VA	1661	Quantity of (3) 6 in Drill Collars
1652	Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA	1662	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details	
	CHOICE OF 10 - Lot #'s: 1663, 1664, 1665, 1666, 1667, 1668, 1669, 1670, 1671, 1672		CHOICE OF 9 - Lot #'s: 1673, 1674, 1675, 1676, 1677, 1678, 1679, 1680, 1681	
1663	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1673	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1664	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1674	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1665	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1675	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1666	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1676	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1667	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1677	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1668	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1678	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1669	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1679	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1670	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1680	Quantity of (2) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1671	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1681	Quantity of (2) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1672	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA			

Lot #	Details	Lot #	Details
CHOICE OF 8 - Lot #'s: 1682, 1683, 1684, 1685, 1686, 1687, 1688, 1689		1691	2014 Kenworth T800 8x4 Cab and Chassis S/N: 1NKDX4EXXEJ404952 C/W: Cummins ISX15 15.0 L 525 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust
1682	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1692 2	Fluid, 20872.4 Engine hrs, Engine Brake, Eator Fuller 8LL Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 71340 lb GVWR, Air Ride Cab, 11R24 5 Front Tires, 11R24.5 Rear Tires, Hendrickson Primaax EX Air Ride Suspension, 229 in Wheelbase, 103 in Cab to Axle, 286 in Cab to End of Frame, Pintle Hitch
1683	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		Usage: 514,573 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS
1684	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUA RESTORATION OF ALL POLLUTION CONTRO SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTIC
1685	Quantity of (1) 7.5 in Drill Collars		PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		2018 Mack GU713 6x4 Cab and Chassis S/N: 1M1AX07YXJM038681 C/W: Mack MP8 6 Cylinder 12.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 189
1686	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		Engine hrs, Engine Brake, Mack Automated Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Double Frame, Rubber Suspension, 206 in Wheelbase Usage: 463,795 Mi
1687	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	Asset located in: Lake Wort 1692A 2011 International 4400 6x4 S/N: 1HTMSAZR3BH34035 C/W: International MaxxFor L Diesel Engine, Engine Bral Automatic Transmission, 14 40000 lb Rears, 54000 lb GV 315/80R22.5 Front Tires, 17 Air Ride Suspension, 271 in	S/N: 1HTMSAZR3BH340351 C/W: International MaxxForce 9 6 Cylinder 9.3
1688	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 271 in Wheelbase, 208 in Cab to Axle, 315 in Cab to End of Frame
1689	Quantity of (1) 7.5 in Drill Collars		Asset located in: Humble, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in : Cedar Bluff, VA	S/N: 2NKHHN7X2BM296249 C/W: Paccar 6 Cylinder Diesel E Diesel Exhaust Fluid, 8574 Eng Automatic Transmission, 1200 20000 lb Rears, 32000 lb GVWI Outer Wheels, 11R22.5, Spring 229 in Wheelbase, 164 in Cab t Cab to End of Frame Usage: 163,110 Mi	C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8574 Engine hrs, Allison
1690	Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Spring Suspension, 229 in Wheelbase, 164 in Cab to Axle, 216 in Cab to End of Frame

Lot #	Details	Lot #	Details
1694	2020 Freightliner M2 106 4x2 Cab and Chassis S/N: 3ALACWFC1LDMA1987 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller EDCO-6F107A Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 204 in Wheelbase, 140 in Cab to Axle, 212 in Cab to End of Frame Usage: 221,672 Mi	1699	2018 Hino 268 4x2 Cab and Chassis S/N: 5PVNJ8JV8J4S68672 C/W: J08E 6 Cylinder 7.6 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6352 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 205 in Cab to Axle, 319 in Cab to End of Frame Usage: 234,436 Mi Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	1700	2014 Freightliner M2 106 4x2 Cab and Chassis S/N: 1FVACXDT6EHFY9046
1695	2019 International 4300 4x2 Cab and Chassis S/N: 3HAMMMN5KL559225 C/W: Cummins B6.7 260 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12755 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 254 in Wheelbase, 186 in Cab to Axle, 278 in Cab to End of Frame Usage: 193,556 Mi		C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 7129 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 270 in Wheelbase, 204 in Cab to Axle, 300 in Cab to End of Frame Usage: 200,956 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1701	2014 Hino 268 4x2 Cab and Chassis
1696	2018 International 8600 4x2 Cab and Chassis S/N: 3HTHWSNNXJN626104 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 370 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9390 Engine hrs, Eaton Fuller Automated Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 12R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 264 in Wheelbase, 204 in Cab to Axle, 300 in Cab to		S/N: 5PVNJ8JL5E4S51770 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, 102 in Cab to Axle, 162 in Cab to End of Frame Usage: 263,506 Mi Asset located in: Lake Worth, TX
	End of Frame Usage: 393,327 Mi Asset located in: Lake Worth, TX	1702	2013 Peterbilt 337 4x2 Cab and Chassis S/N: 2NP2HN7X2DM190208 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel
1697	2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV9J4S57961 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10275 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Spring Suspension, 272 in Wheelbase, 206 in Cab to Axle, 283 in Cab to End of Frame		
	Usage: 284,232 Mi Asset located in : Lake Worth, TX	1703	2012 International 7500 Work Star Cab and
1698	2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV0J4S58139 C/W: Hino J08E-VB 6 Cylinder Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9483 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 204 in Cab to Axle, 284 in Cab to End of Frame Usage: 301,522 Mi Asset located in: Lake Worth, TX	17004	Chassis S/N: 1HTWPAZRXCJ641719 C/W: Navistar 6 Cylinder 9.3 L 310 hp Engine, 2011 US EPA Label, Allison Automated Transmission, 14000 lb Front Axle, Air Ride Cab, Air Ride Suspension, 256 in Wheelbase, PTO Usage: Not Available Asset located in: Humble, TX
		1703A 	2012 International 4300 Cab and Chassis S/N: 3HAMMAAN5CL562842 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1704 1704A	2011 Kenworth T370 Cab and Chassis S/N: 2NKHLN9X8BM285610 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 300 hp Engine, Engine Brake, Allison 3500 Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, 252 in Wheelbase, PTO Usage: Not Available Asset located in: Humble, TX 2018 Isuzu NPR-XD Cab and Chassis S/N: JALC4W161J7K00299 Usage: Not Available	1709	2016 Ram 5500 4x2 Cab and Chassis S/N: 3C7WRMDL1GG283996 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 255/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 204 in Wheelbase, 120 in Cab to Axle, 173 in Cab to End of Frame Usage: 185,092 Mi Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	1709A	2012 Ford F-550 4x2 Extended Cab Cab and
1705	2007 Mack CXP613 Cab and Chassis S/N: 1M1AP02YX7N001530 Usage: Not Available Asset located in: Lake Worth, TX	- C S C E F 7.7 W E U A A C S C R T R S A U U	Chassis S/N: 1FD0X5GT5CEC83751 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225
1706	2019 Ford F-550 XL 4x4 Extended Cab Cab and Chassis S/N: 1FD0X5HT1KEF25139 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid,		/70R19.5, Spring Suspension, 183 in Wheelbase, 80 in Cab to Axle, 130 in Cab to End of Frame Usage: 204,360 Mi Asset located in: Lake Worth, TX
	Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 134 in Cab to End of Frame Usage: Not Available Asset located in: Midland, TX		2012 Chevrolet 3500 4x2 Crew Cab Cab and Chassis S/N: 1GB4CZCL2CF161801 C/W: GM 6.6 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5200 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 265/70R17, Spring
	OICE OF 2 - Lot #'s: 1707, 1708		Suspension, 172 in Wheelbase, 60 in Cab to Axle, 112 in Cab to End of Frame Usage: Not Available
1707	2017 Ford F-550 4x4 Extended Cab Cab and Chassis S/N: 1FD0X5HT8HEE59326 C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 86 in Cab to Axle, 128 in Cab to End of Frame Usage: 141,292 Mi Asset located in: Lake Worth, TX	1711	Asset located in: Lake Worth, TX 2009 Peterbilt 335 4x2 Cab and Chassis S/N: 2NPLHN7X19M788656 C/W: Paccar 6 Cylinder Diesel Engine, Engine Brake, Allison 3500 Automatic Transmission, 10000 lb Front Axle, 23000 lb Rears, Dana S23- 170 Drive Axles, 6.14:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, 134 in Cab to Axle, 171 in Cab to End of Frame Usage: 102,359 Mi Asset located in: Humble, TX
1708	2017 Ford F-550 4x2 Extended Cab Cab and Chassis S/N: 1FDOX5GT0HEE87879 C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8271 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 134 in Cab to End of Frame Usage: 204,811 Mi Asset located in: Lake Worth, TX	1712	2007 Mack CTP713 Cab and Chassis S/N: 1M2AT04Y27M006909 Usage: Not Available Asset located in: Lake Worth, TX
		1713	2007 Hino 258 4x2 Cab and Chassis S/N: 5PVND8JT672S50164 C/W: Hino 6 Cylinder Diesel 220 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 255 /70R22.5, Spring Suspension, 219 in Wheelbase, 150 in Cab to Axle, 183 in Cab to End of Frame Usage: 329,692 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1714	2006 International 4300 Cab and Chassis S/N: 1HTMMAAM46H186863 Usage: Not Available Asset located in: Lake Worth, TX 2005 Peterbilt 335 4x2 Cab and Chassis S/N: 2NPLHD6X45M857023 C/W: Cat C7 6 Cylinder 7.2 L Diesel 250 hp Engine, 2006 US EPA Label, 15489 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 4.88:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22. 5, Low Air Leaf Suspension, 191 in Wheelbase, PTO, 120 in Cab to Axle, 195 in Cab to End of Frame	1719	2019 Freightliner M2 106 6x4 Flatbed Truck S/N: 3ALHCYFE7KDKU9146 C/W: Cummins L9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6627 Engine hrs, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.33:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 28 ft x 102 in Bed, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 288,102 Mi Asset located in: Lake Worth, TX	
	Usage: 459,210 Mi Asset located in: Lake Worth, TX	1720	2014 International 7600 6x4 Flatbed Truck S/N: 1HTGSSJT6EH786752	
1715A	2007 GMC C7500 4x2 Cab and Chassis S/N: 1GDK7C1C67F900371 C/W: Cat C7 6 Cylinder 7.2 L Diesel 210 hp Engine, 2006 US EPA Label, Automatic Transmission, 8001 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, 192 in Cab to Axle, 228 in Cab to End of Frame Usage: 226,533 Mi		Requires Diesel Exhaust Fluid, Engine Eaton Fuller Manual Transmission, 20 Front Axle, 40000 lb Rears, 60000 lb Ride Cab, 315/80R22.5 Front Tires, 1 Rear Tires, Dual Steering Boxes, Doub	Usage: 323,203 Mi
	Asset located in: Lake Worth, TX	1721	2003 Mack RD688S 6x4 Flatbed Truck	
1716	6 1998 Peterbilt 330 4x2 Cab and Chassis S/N: 3BPNHD7X1WF459167 C/W: Cat 3126B 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 274 in Wheelbase, PTO, 200 in Cab to Axle, 329 in Cab to End of Frame Usage: 912,630 Mi		S/N: 1M2P267C93M065482 C/W: Mack E7 6 Cylinder Diesel 350 hp Engine, 2002 US EPA Label, 28682 Engine hrs, Eaton Fuller 8LL Manual Transmission, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Camelback Spring Suspension, 252 in Wheelbase, PTO, 20 ft 6 in x 92 in Bed Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX	1721A	2018 International 4300 4x2 Flatbed Truck S/N: 1HTMMMMMXJH632780	
1717	1992 Ford LT8000F 6x4 T/A Dump Truck S/N: 1FDYU82A8NVA25956 C/W: Ford 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 54600 lb GVWR, 11R24.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Spring over Walking Beam Suspension, 236 in Wheelbase, PTO, 17 ft Long x 3 ft High Steel Body, Flat Bed,	Di Re hr Fr Ri W Us	C/W: Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11497 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 10R22.5, Spring Suspension, 181 in Wheelbase, 14 ft 5 in x 96 in Bed Usage: 148,134 Mi Asset located in: Lake Worth, TX	
	Manual Roll Tarp, Pintle Hitch Usage: 336,571 Mi	1722	2016 Freightliner M2 106 4x2 Flatbed Truck	
1718	Asset located in: Midland, TX 1990 International 4600 4x2 Cab and Chassis S/N: 1HTSAZRN0MH332118 C/W: International 7.3 L Diesel 155 hp Engine, Steel, 255/70R22.5, Double Frame, Spring Suspension, 152 in Wheelbase, 84 in Cab to Axle, 147 in Cab to End of Frame Usage: 218,680 Mi Asset located in: Lake Worth, TX	C/W: Cummins IS hp Engine, 2015 U Exhaust Fluid, 13 Automatic Transi 21000 lb Rears, 5 GVWR, Air Ride C Suspension, 252 Bed, Aluminum F Usage: 206,090 N	S/N: 1FVACXDT0GHHR9676 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 13474 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.56:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 96 in Bed, Aluminum Frame, Liftgate Usage: 206,090 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
1723	2014 Freightliner M2 106 6x4 Flatbed Truck S/N: 1FVHCYCY5EHFV7934 C/W: Cummins ISL9 6 Cylinder Diesel 350 hp Engine, Requires Diesel Exhaust Fluid, 9346 Engine hrs, Allison Automatic Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 274 in Wheelbase, 24 ft x 91 in Bed, Forklift Mount Kit Usage: 158,702 Mi Asset located in: Humble, TX 2019 Isuzu NPR HD 4x2 COE Crew Cab Flatbed	CHOICI 1727	2009 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF65C79V065767 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2008 US EPA Label, 2379 Engine hrs, Eaton Fuller Automated Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, 13 ft x 94 in Bed, Winch Usage: 14,420 Mi Asset located in: Lake Worth, TX
	Truck S/N: 54DC4J1B6KS801218 C/W: 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225/70R19.5, Spring Suspension, 181 in Wheelbase, 19 ft x 93 in Bed, Dovetail, Manual Ramps Usage: 138,503 Mi Asset located in: Lake Worth, TX	1728	2009 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF65H89V109657 C/W: Cummins 6 Cylinder Diesel Engine, Automatic Transmission, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 195 in Wheelbase, 8 ft x 96 in Bed Usage: 74,757 Mi
1724B	2007 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAM17H382700 C/W: International DT466 6 Cylinder 7.6 L Diesel 210 hp Engine, 2006 US EPA Label, 7485 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, 18 ft x 92 in Bed, Poly Tank, MultiQuip Concrete Mixer, Usage: 238,996 Mi Asset located in: Lake Worth, TX 2006 Hino 268 4x2 Flatbed Truck	Flatbed Truck S/N: 14619G C/W: cat 3126 6 Cylinder 7.2 L Die Engine, 1999 US EPA Label, Autor Transmission, 395/85R20, Spring 154 in Wheelbase, 12 ft 6 in x 96 i Allison Auto, Central Tire Inflation EQUIPMENT-FROM-WATKINS-CO Usage: 196 Mi Asset located in: Lake Worth, TX 1730 1998 Stewart and Stevenson M10 Flatbed Truck S/N: V011285EDKG C/W: Cat 6 Cylinder Diesel Engine Automatic Transmission, 395/85I Suspension, 154 in Wheelbase, 12 in Bed, Pintle Hitch, EQUIPMENT-I WATKINS-CONSTRUCTION Usage: 4,949 Mi	E OF 2 - Lot #'s: 1729, 1730 2001 Stewart and Stevenson M1078 4x4 Flatbed Truck
1725	S/N: 5PVNE8JT462S12363 C/W: Hino 6 Cylinder Diesel Engine, Automatic Transmission, 11R22.5, Spring Suspension, 245 in Wheelbase, 23 ft 8 in x 94 in Bed Usage: 672,876 Mi		Allison Auto, Central Tire Inflation; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 196 Mi
1725A	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2004 International 4300 Flatbed Truck S/N: 1HTMMAAL54H662588 Usage: Not Available Asset located in: Humble, TX		S/N: V011285EDKG C/W: Cat 6 Cylinder Diesel Engine, Allison Automatic Transmission, 395/85R20, Spring Suspension, 154 in Wheelbase, 12 ft 6 in x 94 in Bed, Pintle Hitch, EQUIPMENT-FROM- WATKINS-CONSTRUCTION
1725B	2007 International 4400 Flatbed Truck S/N: 1HTMRAAL97H464165 Usage: Not Available Asset located in: Humble, TX	СНОІСІ	E OF 2 - Lot #'s: 1731, 1732
1726	2019 Ford F-750 4x2 Flatbed Truck S/N: 1FDXF7DE5KDF11884 C/W: 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 260 in Wheelbase, 18 ft x 92 in Bed, Pintle Hitch Usage: 34,747 Mi Asset located in: Lake Worth, TX	1731	1998 Stewart and Stevenson M1078 4x4 COE Flatbed Truck S/N: AT9310EDEG C/W: Diesel Engine, Automatic Transmission, 395/85R20, Spring Suspension, 152 in Wheelbase, 12 ft 7 in x 96 in Bed, Diesel, Allison Automatic, Central Tire Inflation; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 7,226 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1732	1995 Stewart and Stevenson M1078 COE 4x4 Flatbed Truck S/N: AT0761BEC C/W: Allison Automatic Transmission, 395 /85R20, 155 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch, Diesel, Allison Auto, Central Tire Inflation; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,055 Mi	CHOIC	E OF 3 - Lot #'s: 1739, 1740, 1741 2019 Ford F-550 4x4 Crew Cab Flatbed Truck
			S/N: 1FD0W5HT9KED42817 Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	1740	2019 Ford F-550 XL 4x4 Crew Cab Flatbed
CHOIC	E OF 3 - Lot #'s: 1734, 1735, 1736		Truck S/N: 1FD0W5HT5KEF71138 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Require Diesel Exhaust Fluid,
1734	2006 GMC 4500 4x2 Flatbed Truck S/N: 1GDE4C12X6F431782 C/W: V8 6.6 L Diesel 300 hp Engine, 2006 US EPA Label, Automatic Transmission, 225 /70R19.5, Spring Suspension, 179 in Wheelbase, 14 ft 4 in x 93 in Bed	Spring Suspension, 206 in Wheelb x 56 in Bed, Pintle Hitch Usage: 199,717 Mi	14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 206 in Wheelbase, 9 ft 6 in x 56 in Bed, Pintle Hitch
	Usage: 214,436 Mi Asset located in: Lake Worth, TX	1741	2019 Ford F-550 XL 4x4 Crew Cab Flatbed Truck
1735	2006 GMC 4500 4x2 Flatbed Truck S/N: 1GDE4C1256F431754 C/W: Chevy V8 6.6 L Diesel Engine, US EPA Label, Allison 4 Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 177 in Wheelbase, 14 ft x 92 in Bed, Receiver Usage: 182,782 Mi	_	S/N: 1FD0W5HT9KEF71160 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 204 in Wheelbase, 11 ft 4 in x 96 in Bed, Pintle Hitch, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1742	2018 Ford F-550 XL 4x4 Crew Cab Flatbed
1736	2006 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBE4C1226F434247 C/W: V8 6.6 L Diesel Engine, Allison Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225/70R19.5, Spring Suspension, 190 in Wheelbase, 13 ft x 96 in Bed, Hitch Receiver Usage: 179,635 Mi Asset located in: Lake Worth, TX	71/42	Truck S/N: 1FD0W5HT6JEC24738 C/W: 6 Cylinder 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 203 in Wheelbase, 10 ft 6 in x 89 in Bed, Fuel Tank Usage: 160,056 Mi
1737	2023 Ford F-550 4x4 Extended Cab Flatbed		Asset located in: Lake Worth, TX
	Truck S/N: 1FD0X5HT7PED26877 Usage: Not Available	СНОІС	E OF 2 - Lot #'s: 1743, 1744
	Asset located in: Lake Worth, TX	1743	2018 Ram 5500 4x4 Crew Cab Flatbed Truck
1738	2022 Ford F-550 XL 4x4 Flatbed Truck S/N: 1FDUF5HT4NEE52440 C/W: power stroke V8 6.7 L Diesel Engine, 2022 US EPA Label, 1589 Engine hrs, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500.0 lb GVWR, 225/70R19. 5, Spring Suspension, 169 in Wheelbase, 12 ft x 96 in Bed, Aluminum Frame Usage: 46,064 Mi Asset located in: Lake Worth, TX	1/40	S/N: 3C7WRNFL1JG157387 C/W: Cummins ISB6.7 325 6.7 L 325 hp Engine, 2018 US EPA Label, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500.0 lb GVWR, 225/70R19. 5, Spring Suspension, 197 in Wheelbase, 12 ft x 96 in Bed, Fuel Tank /w Pump, Pintle Hitch Usage: 81,063 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1744	2018 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL8JG207251 C/W: Cummins 6.7 L Diesel Engine, 6818 Engine hrs, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 194 in Wheelbase Usage: 114,766 Mi Asset located in: Lake Worth, TX	1749	2016 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT2GEB95778 C/W: Power Stroke V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft 6 in x 96 in Bed, Liftgate, Rear View Camera; EQUIPMENT-FROM-SUNSTATE-	
1745	2011 Dodge Ram 5500 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 3D6WAFCLOBG612391		EQUIPMENT Usage: 120,695 Mi Asset located in: Lake Worth, TX	
	C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 196 in Wheelbase, 12 ft x 102 in Bed Usage: Not Available Asset located in: Lake Worth, TX	1751	2016 Ford F-550 XL 4x4 Extended Cab Flatbed Truck S/N: 1FD0X5HT8GEC75339 C/W: 6.7 L 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8438 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft x	
1746	2017 Ford F-550 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT4HEC85077 C/W: V8 6.7 L 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5,		91 in Bed, Fuel Tank Usage: 191,492 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	
	Spring Suspension, 187 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch Usage: 147,936 Mi Asset located in: Lake Worth, TX			
1747	2017 Ford F-450 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W4HY8HEC86836 C/W: 6 Cylinder 6.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225			
	/70R19.5, Spring Suspension, 205 in Wheelbase, 11 ft 6 in x 60 in Bed, Fuel Tank, Pintle Hitch Usage: 45,366 Mi Asset located in : Lake Worth, TX		2015 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT2FEC27629 C/W: Ford Power Stroke 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel	
1748	2017 Ford F-550 XL 4x2 Extended Cab Cab and Chassis S/N: 1FD0X5GT9HEC48136 C/W: V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 65000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 122 in Cab to			
	End of Frame Usage: 131,502 Mi Asset located in: Lake Worth, TX	1754	2013 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT9DEB58125 C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft 2 in x 88 in Bed Usage: 301,436 Mi	

Asset located in: Midland, TX

Lot #	Details	Lot #	Details
1756	2012 Ford F-550 4x2 Extended Cab Flatbed Truck S/N: 1FD0X5GT6CEC35272 Usage: Not Available Asset located in: Lake Worth, TX 2013 Ford F-450 4x2 Flatbed Truck S/N: 1FDUF4GY5DEA18226 C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, 5-Speed Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 201 in Wheelbase, 17 ft 5 in x 96 in Bed, Liftgate Usage: 204,057 Mi	1762	2021 GMC Sierra 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GD49SE76MF148113 C/W: V8 6.6 L Gasoline Engine, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 182 in Wheelbase, 9 ft x 96 in Bed, Fuel Tank /w Pump, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 116,066 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
1758	Asset located in: Lake Worth, TX 2013 Ford F-450 XL 4x2 Flatbed Truck S/N: 1FDUF4GT4DEB86573	1763	2021 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT2MED56469 Usage: Not Available
	C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft x 94 in Bed Usage: 201,329 Mi Asset located in: Lake Worth, TX	1764	Asset located in: Lake Worth, TX 2022 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3GN1NEC44542 C/W: Ford V8 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 245
1759	2011 Ford F-450 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W4HT0BEC98605 C/W: Ford Power Stroke V8 6.7 L Ultra Low Sulfur Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring		/75R17, 9 ft x 93 in Bed Usage: 111,959 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Suspension, 176 in Wheelbase, 8 ft 9 in x 94 in Bed Usage: 290,111 Mi	1765	E OF 3 - Lot #'s: 1765, 1766, 1767 2020 Ford F-350 XL 4x4 Crew Cab Flatbed
1760	Asset located in: Lake Worth, TX 2003 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBC4E1E93F503492 C/W: V8 8.1 L Gasoline Engine, Automatic Transmission, 6000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 13 ft 4 in x 97 in Bed Usage: 281,996 Mi Asset located in: Lake Worth, TX		Truck S/N: 1FD8W3G6XLEE32269 C/W: V8 6.2 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 90 in Bed Usage: 121,378 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
1761	2022 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL3NG365057 C/W: 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in Bed Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; PLEASE SEE DEFICIENCIES, TRANSMISSION IS IN VERY BAD CONDITION Asset located in: Lake Worth, TX	1766	Asset located in: Lake Worth, TX 2020 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT5LED87360 C/W: V8 6.7 L Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 245:75R17, Spring Suspension, 181 in Wheelbase, 108 m x 89 in Bed Usage: 115,425 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1767	2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT3KEF22298 C/W: 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 181 in Wheelbase, 9 ft 6 in x 98 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	1773	2019 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT6KDA03912 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 5452 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 245/70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft 6 in x 96 in Bed Usage: 176,902 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
1768	2019 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3G63KEC30873 C/W: V8 6.2 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase, 9 ft 5 in x 90 in Bed Usage: 93,217 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	1774	2018 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT5JEC95579 C/W: V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 8284 Engine hrs, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 3 in x 98 in Bed Usage: 221,150 Mi Asset located in: Humble, TX	
CHOIC	Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1769, 1770, 1771	1775	2017 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3H6XHEE85592 Usage: Not Available Asset located in: Lake Worth, TX	
1769	2019 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FT8W3DT6KEG85635 C/W: Ford Power Stroke 6.7 L Diesel Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5246 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 9900 lb Rears, Ford-Factory Drive Axles, 14000 lb GVWR, Aluminum Wheels, 245/75R17, Ford- Factory Spring Suspension, 178 in Wheelbase, 9 ft x 98 in Bed, Receiver hitch, Fifth wheel ball Usage: 194,430 Mi	1776	2017 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3H62HEE73498 C/W: Ford V8 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 5200 lb Front Axle, 10040 lb Rears, 14000.0 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 92 in Bed, Pintle Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 119,438 Mi Asset located in: Lake Worth, TX	
1770	Asset located in: Midland, TX 2019 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT5KEE24230 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75/17, Spring Suspension, 180 in Wheelbase, 9 ft x 89 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 134,504 Mi Asset located in: Lake Worth, TX	1777	Truck S/N: 1FD8W3HT6GEA98185 C/W: Ford V8 6.7 L Diesel 300 hp Ei US EPA Label, 11342 Engine hrs, Au Transmission, 5940 lb Front Axle, 9 Rears, 14000 lb GVWR, 265/70R17,	S/N: 1FD8W3HT6GEA98185 C/W: Ford V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, 11342 Engine hrs, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 265/70R17, Spring Suspension, 176 in Wheelbase, 9 ft 4 in x 92 in Bed Usage: 279,994 Mi
1771	2019 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT6KEG06521 Usage: Not Available Asset located in: Midland, TX			
1772	2018 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT7JEC67900 Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 1778, 1779	CHOIC	E OF 2 - Lot #'s: 1782, 1783
1778	2018 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL7JG325302 C/W: Cumins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 640 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80/17, Spring Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in Bed	1782 1783	2017 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY3HF162424 C/W: Duramax 6.6 L Diesel Engine, Automatic Transmission, 9 ft 4 in Bed Usage: 113,083 Mi Asset located in: Lake Worth, TX 2017 Chevrolet Silverado 3500HD 4x4 Crew
1779	Usage: 90,276 Mi Asset located in: Lake Worth, TX 2017 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL9HG759022 C/W: 6 Cylinder 6.7 L Diesel Engine, 2017 US	_	Cab Flatbed Truck S/N: 1GB4KYCY0HF162509 C/W: Duramax 6.6 L Diesel Engine, Automatic Transmission, 9 ft 4 in Bed Usage: 113,384 Mi
	EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 173 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 382,795 Mi	1784	Asset located in: Lake Worth, TX 2012 Dodge Ram 3500 Flatbed Truck S/N: 3C7WDSCLXCG193793 Usage: 329,146 Mi Asset located in: Lake Worth, TX
1780	Asset located in: Midland, TX 2019 GMC Sierra 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GD42TCG9KF236339 C/W: V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 9375 lb Rears, 13025 lb GVWR, 265 /70R17, Spring Suspension, 168 in Wheelbase, 8 ft x 92 in Bed, Fuel Tank Usage: 112,708 Mi Notes: NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX	_1785	Truck S/N: 1GB4K1CL3BF151507 C/W: General Motors V8 6.6 L Diesel Engine, 2011 US EPA Label, Automatic Transmission, 245/70R17, Spring Suspension, 175 in Wheelbase, 8 ft 6 in x 84 in Bed, Better Built 50 gallons Fuel Tank Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; Asset located in: Lake Worth, TX
1780A 1781		1786	2017 Ford F-250 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD7W2B67HED35955 C/W: Ford V8 6.2 L Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 6340 lb Rears, 10000.0 lb GVWR, 285/70R17, Spring Suspension, 176 in Wheelbase, 8 ft 6 in x 80 in Bed, Fuel Tank /w Pump Usage: 105,808 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Truck S/N: 1GB3KYCY1HF207209 C/W: GM Duramax 6.6 L Diesel Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Allison Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 163 in Wheelbase, 11 ft 4 in x 98 in Bed, Aluminum/Steel Combination Frame, Better Built 100 Gallons Fuel Tank /w Pump Usage: 100,497 Mi Asset located in: Midland, TX	1787	2015 Ford F-250 XL 4x2 Crew Cab Flatbed Truck S/N: 1FT7W2AT3FEB68857 C/W: V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 265/70R17, Spring Suspension, 171 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 288,298 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1788	2011 Ford F-250 4x4 Crew Cab Flatbed Truck S/N: 1FT7W2B6XBED03559 C/W: Gasoline Engine, 2011 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 154 in Wheelbase, 7 ft x 84 in Bed Usage: Not Available	1793 1794	2012 Peterbilt 388 T/A Sleeper Car Carrier Truck S/N: 1NPWD49X3CD134979 Usage: Not Available Asset located in: Lake Worth, TX 2012 Peterbilt 388 6x4 Sleeper Car Carrier Truck
	Asset located in: Lake Worth, TX		S/N: 1NPWD49X2CD134987
1788A	2011 Ford F-250 4x2 Flatbed Truck S/N: 1FTBF2A67BEC16567 C/W: Ford V8 6.2 L Gasoline Engine, US EPA Label, Automatic Transmission, 3950 lb Front Axle, 9800 lb Rears, 9800 lb GVWR, LT245 /75R17, Spring Suspension, 136 in Wheelbase, 8 ft 3 in x 79 in Bed, Receiver, Fifth wheel ball Usage: 318,291 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		C/W: Cummins ISX15 6 Cylinder 15.0 L 525 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 44842 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 58 in Flat Top Sleeper Cab, Aluminum Wheels, 295/60R22.5 Front Tires, 255/70R22.5 Rear Tires, Low Low Air Leaf Air Ride Suspension, 264 in Wheelbase, PTO, Hydraulic Lift, Soft Tie Downs, SOLD WITH -
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Cottrell CX-11HCSI T/A, Trailer S/N - 5E0AJ144XCG335301, Soft Ties, Aluminum
	Asset located in: Lake Worth, TX		Wheels, 225/70R22.5 Tires Usage: 1,087,566 Mi
1789	2015 Chevrolet Silverado 1500 4X4 Crew Cab Flatbed Truck		Asset located in: Lake Worth, TX
	S/N: 1GB4KYC87FF132971 C/W: V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 173 in Wheelbase, 9 ft 5 in x 86 in Bed Usage: 61,854 Mi Asset located in: Lake Worth, TX	1796	2012 Kenworth T800 14x4 Five Axle Dump Truck S/N: 1NKDL40X0CJ335866 C/W: Cummins 6 Cylinder 15 L Diesel 248 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 24448.6 Engine hrs, Engine Brake, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears,
1790	2015 Chevrolet Silverado 1500 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYC84FF512267 C/W: V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 174 in Wheelbase, 9 ft 6 in		3.91:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Trailing Tag Axle, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, PTO, 14 ft 8 in Long x 5 ft 8 in High Steel Body, Electric Roll Tarp Usage: 259,946 Mi Asset located in: Lake Worth, TX
	x 87 in Bed Usage: 117,117 Mi	1797	2012 Freightliner Cascadia 125 10x4 Quad/A
1791	Asset located in: Lake Worth, TX 1971 Ford F100 4x2 Flatbed Truck S/N: F10YRM02564 C/W: V8 Gasoline Engine, Automatic Transmission, 4500 lb GVWR, 7.00-15, Spring Suspension, 131 in Wheelbase, 8 ft x 78 in Bed, Pintle Hitch, Goodall Start-All Jumpstart Pack, Ingersoll-Rand T30 Air Compressor; EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: CANNOT VERIFY ODOMETER READING- VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE;TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Dump Truck S/N: 1FUJGEDV2CSBM1515 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Dana DS404 Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5, Steerable Air Lift Tag Axle, Double Frame, Airliner Air Ride Suspension, 312 mm Wheelbase, PTO, 21 ft Long x 4 ft High Steel Body, Manual Roll Tarp Usage: 520,916 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION
1700	Asset located in: Midland, TX	-	REPORT
1792	2019 Western Star Car Carrier Truck S/N: 2WKDD40X2KF369099 Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1798	2014 Kenworth T440 6x4 Dump Truck S/N: 1NKBLJ9X0EJ389440 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, 2 Steerable Air Lift Pusher Axle, Spring Suspension, 233 in Wheelbase, PTO, OX Bodies 17 ft 9 in Long x 4 ft 3 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 376,489 Mi Asset located in: Humble, TX	1802	2003 Mack CHU613 8x4 Tri/A Dump Truck S/N: 1M1AA12Y23W149926 C/W: 6 Cylinder Diesel Engine, 22935 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22. 5 Rear Tires, Air Lift Pusher Axle, Air Ride Suspension, 196 in Wheelbase, PTO, 16 ft 5 in Long x 5 ft 6 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 706,035 Mi Asset located in: Humble, TX
1799	2014 Freightliner 114SD 8x4 Tri/A Dump Truck S/N: 3AKJG3DV2EDGA1049 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller RTO-16908LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Steerable Air Lift Pusher Axle, Airliner Air Ride Suspension, 202 in Wheelbase, 16 ft 5 in Long x 2 ft 6 in High Steel Body, Electric Roll Tarp Usage: 525,886 Mi Asset located in: Lake Worth, TX	1803	1999 Mack RD600 8x4 Tri/A Dump Truck S/N: 1M2P270C4XM046117 C/W: Mack E7 6 Cylinder 11.9 L Diesel 400 hp Engine, 1999 US EPA Label, 34470 Engine hrs, Manual Transmission, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Camelback Spring Suspension, 234 in Wheelbase, PTO, 16 ft Long x 3 ft 2 in High Steel Body, Flat Bed, Electric Roll Tarp, Split Swing Tailgate, Pintle Hitch Usage: 654,884 Mi Asset located in: Lake Worth, TX
1800	2015 Freightliner Cascadia 113 8x4 Tri/A Dump Truck S/N: 1FUJGHDVXFLGF1087 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW-15210B 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Airliner Air Ride Suspension, 207 in Wheelbase, PTO, 16 ft 8 in Long x 4 ft 3 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 816,761 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1804	2015 Peterbilt 365 6x4 T/A Dump Truck S/N: 1XPSD79X9FD262718 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, 14 ft Long x 4 ft 3 in High Steel Body, Electric Roll Tarp Usage: 598,800 Mi Asset located in: Humble, TX
		1805	2018 Kenworth T370 T/A Dump Truck S/N: 2NKHHM7X3JM183693 Usage: Not Available Asset located in: Lake Worth, TX
1801	2007 Sterling LT9500 8x4 Tri/A Dump Truck S/N: 2FZMAZCV87AX38981 C/W: Mercedes-Benz MBE4000 6 Cylinder 12.8 L Diesel Engine, 2006 US EPA Label, Engine Brake, Allison 6-Speed Automatic Transmission, Differential Lock, 20000 lb Front Axle, 66000 lb Rears, 86000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 202 in Wheelbase, PTO, OX Bodies 16 ft Long x 4 ft High Steel Body, Flat Bed, Electric Roll Tarp, Pintle Hitch Usage: 528,890 Mi Asset located in: Lake Worth, TX	1806	2016 Volvo VHD 8x4 T/A Dump Truck S/N: 4V5KC9EH4GN923100 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Volvo Automatic Transmission, Differential Lock, 20000 lb Front Axle, 40000 lb Rears, 53500 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, 286 in Wheelbase, PTO, Strong Inc. 16 ft 0 in Long x 4 ft 8 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 408,393 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1807	2013 Cat CT660S 6x4 T/A Dump Truck S/N: 1HSJGTKR3DJ301284 C/W: Cat CT13 13 L Diesel Engine, 23623 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Air Ride Suspension, 199 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Body, Bed Vibrator, Electric Roll Tarp, High-Lift Tailgate Usage: 250,468 Mi Asset located in: Lake Worth, TX	1814	1998 Mack CH613 6x4 T/A Dump Truck S/N: 1M2AA18Y6WW094985 C/W: Mack E7 6 Cylinder Diesel 427 hp Engine, 1999 US EPA Label, 20507 Engine hrs, Mack 13-Speed Manual Transmission, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Double Frame, Camelback Suspension, 216 in Wheelbase, PTO, Warren 15 ft Long x 3 ft 6 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 37,076 Mi Asset located in: Lake Worth, TX
		1814A	1998 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUYDCYB2WP980791
1808	2012 International 7500 6x4 T/A Dump Truck S/N: 1HTWNAZR5CJ587087 C/W: International MaxxForce 10 6 Cylinder 9.3 L Diesel 310 hp Engine, 2011 US EPA Label, 7272 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Hendrickson Haulmaax Suspension, 171 in Wheelbase, PTO, Warren 13 ft Long x 4 ft High Steel Body, 14 cyd, Capacity Usage: 157,181 Mi		C/W: Cummins N14 6 Cylinder 14.0 L Diesel 370 hp Engine, 1998 US EPA Label, Engine Brake, Eaton Fuller RTLO-14610B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 192 in Wheelbase, PTO, OX Bodies 14 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Manual Roll Tarp, Ball hitch Usage: 864,969 Mi Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	1815	1996 Freightliner FLD 120 6x4 T/A Dump Truck
1809	2006 International 7600 6x4 T/A Dump Truck S/N: 1HTWYAHT76J239980 C/W: 6 Cylinder Diesel Engine, Engine Brake, Automated Transmission, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 248 in Wheelbase, PTO, 18 ft Long x 6 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 1,054,079 Km		S/N: 1FUYDDYB6TH854798 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Rockwell 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 210 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 8 in High Body, Electric Roll Tarp, Pintle Hitch Usage: 647,766 Mi
			Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1816	1991 International 2574 6x4 T/A Dump Truck S/N: 1HSGGGRRXMH360976 C/W: Cummins NTC-350 6 Cylinder 14.0 L Diesel 350 hp Engine, Eaton Fuller 13-Speed Manual Transmission, Aluminum Front Wheels 11R24.5, Double Frame, Hendrickson RT/RTE Series Suspension, 197 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Body, Manual Roll Tarp Usage: Not Available
1811	2005 Mack CH613 T/A Dump Truck S/N: 1M2AA18Y65N157393 Usage: Not Available Asset located in: Lake Worth, TX		
1812	2002 Volvo VHD T/A Dump Truck		Asset located in: Lake Worth, TX
	S/N: 4V5K99GH02N332959 Usage: Not Available Asset located in : Lake Worth, TX	1817	1981 Kenworth W900 6x4 T/A Dump Truck S/N: 1XKWDB9X3BK188647 C/W: Cat 6 Cylinder Diesel Engine, Engine
1813	2000 International 8100 6x4 T/A Dump Truck S/N: 1HTHCADR0YH332934 C/W: International Diesel Engine, Manual Transmission, 11R22.5, 179 in Wheelbase, 13 ft Long x 4 ft High Steel Body, Electric Roll Tarp Usage: 258,544 Mi Asset located in: Lake Worth, TX		Brake, Eaton Fuller RTO12513 Manual Transmission, 10600 lb Front Axle, 38000 lb Rears, 4.11:1 Axle Ratio, 48600 lb GVWR, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Galion 14 ft Long x 4 ft High Steel Body, Manual Roll Tarp Usage: 316,268 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1818	2016 Freightliner M2 106 4x2 S/A Dump Truck S/N: 1FVACXDU3GHGZ0167 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 152 in Wheelbase, PTO, Ledwell 10 ft Long x 3 ft High Body, Manual Roll Tarp, Double Tailgate Chutes Usage: 33,240 Mi Asset located in: Lake Worth, TX	1821C	2015 International 4300 4x2 Flatbed Dump Truck S/N: 3HAMMAAN7FL683988 C/W: 6 Cylinder 7.6 L Diesel 230 hp Engine, 2014 US EPA Label, 8701 Engine hrs, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring Suspension, 238 in Wheelbase, PTO, OX Bodies 20 ft Long Steel Body Usage: 269,403 Mi Asset located in: Lake Worth, TX
1819	2013 Kenworth T300 4x2 S/A Dump Truck S/N: 2NKHHM7XXDM348014 C/W: Paccar PX6 6 Cylinder 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 6897 Engine hrs, Engine Brake, Allison 6-Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 6.17:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 178 in Wheelbase, 12 ft Long x 0 ft 32 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 96,126 Mi Asset located in: Lake Worth, TX 2008 International 4300 4x2 S/A Dump Truck	1822	Altec on 2016 Freightliner M2 106 4x2 Digger Derrick Truck S/N: 1FVACXDT4GHHL5754 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5611 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 46 ft Sheave Height, Rear Mounted, 18 in Auger, Pole Guide, Auxiliary Hydraulics, One-Man Basket, 14 ft 6 in Body, Straight Down Outriggers, Rear Outriggers Usage: 75,001 Mi Asset located in: Lake Worth, TX
1020	S/N: 1HTMMAAN28J688226 C/W: International 6 Cylinder Diesel Engine, 2007 US EPA Label, 8057 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 19000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 153 in Wheelbase, PTO, 8 ft Long x 3 ft High Steel Body, Manual Roll Tarp, Pintle Hitch Usage: 188,392 Mi Asset located in: Lake Worth, TX	1823	2017 Altec DB37 Tracked Digger Derrick S/N: 0817FT1063 C/W: Kubota 3 Cylinder Diesel Engine, 3800 lb Capacity, 30 ft Reach, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Remote Control w/ Cord, 12 in Rubber Tracks, T/A Trailer, Lunette Ring, Electric Brakes Usage: 368 Hr Asset located in: Lake Worth, TX
1821	2005 Ford F-750 XL 4x2 S/A Dump Truck S/N: 3FRNF75Y05V169058 C/W: International V8 6.0 L Diesel 200 hp Engine, 2004 US EPA Label, Allison Automatic Transmission, 9080 lb Front Axle, 17200 lb Rears, 25999 lb GVWR, 10R22.5, Spring Suspension, 158 in Wheelbase, PTO, Heil 10 ft Long x 3 ft 8 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 52,237 Mi Asset located in: Lake Worth, TX	1824	2017 Altec L42M 42 ft on 2017 Freightliner Mit 106 4x2 Bucket Truck S/N: 3ALACXDT9HDJE9096 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 280 hp Engine, 2017 US EPA Label, Requires Diese Exhaust Fluid, 8165 Engine hrs, Allison 3500 Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, 154 in Wheelbase, PTO, 400 l Capacity, Center Mounted, Insulated One-Person Articulating-Telescopic Boom, Materia Handling Jib, A-Outriggers, Rear Outriggers, 12
1821A	2012 Ford F-450 XL 4x4 Crew Cab Dump Truck S/N: 1FD0W4HTXCEB65433 C/W: Ford V8 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft Long x 1 ft 3 in High Body, Pintle Hitch Usage: 188,303 Mi Asset located in: Lake Worth, TX		ft 6 in x 48 in Bed, Pintle Hitch Usage: 137,691 Mi Asset located in: Lake Worth, TX
1821B	2017 International 4300 Flatbed Dump Truck S/N: 3HAMMMMN4HL489029 Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
CHOICE OF 4 - Lot #'s: 1825, 1826, 1827, 1828		1828	2016 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN3HH161820
1825	Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN2HH474504 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9996 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 65,169 Mi		C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8357 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 196 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed Usage: 82,950 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	СНОІС	E OF 4 - Lot #'s: 1829, 1830, 1831, 1832
1826	Asset located in: Humble, TX 2017 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck	1829	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck
	S/N: 1HTMMMMNXHH161930 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8422 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 72,652 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 27 2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH474542 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11175 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, 700 lb Capacity, Rear Mounted, Insulated One-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers,		S/N: 1HTMMMMN0HH474565 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 7992 Engine hrs, Allison Automatic Transmission, 11R22.5, 192 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, Pintle Hitch Usage: 61,145 Mi Asset located in: Lake Worth, TX
		1830	2017 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN5HH161964 C/W: Cummins ISB 6 Cylinder 6.7 L 260 hp
1827			Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8818 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 92 in Bed, Pintle Hitch Usage: 53,675 Mi Asset located in: Lake Worth, TX
		1831	2016 Altec AA55 56 ft on 2017 International
	16 ft 3 in x 94 in Bed, Pintle Hitch Usage: 76,773 Mi Asset located in : Humble, TX		4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH474556 C/W: Cummins Engine, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 330000 lb GVWR, 11R22.5, PTO, 700 lb Capacity, Center Mounted, Insulated Two- Person Articulated Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, Pintle Hitch Usage: 76,812 Mi

Lot #	Details	Lot #	Details
1832	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN3HH474544 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8552 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 16 ft x 94 in Bed, Pintle Hitch Usage: 80,587 Mi Asset located in: Lake Worth, TX	1836	2012 Altec AA755 55 ft on 2013 Freightliner 4x4 Bucket Truck S/N: 1FVDCXDTXDHBY0785 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10422 Engine hrs, Eaton Fuller 6: Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor MS-21-14X Drive Axles, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Spring Suspension, 190 in Wheelbase 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Winch, Pintle Hitch Usage: 66,347 Mi Asset located in: Lake Worth, TX
СНОІС	E OF 3 - Lot #'s: 1833, 1834, 1835	1837	2011 Terex Hi Ranger TL41-51 51 ft on 2011 Freightliner M2 4x2 Bucket Truck
1833	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH452529 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 13023 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 96 in Bed, Pintle Hitch Usage: 133,654 Mi		S/N: 1FVACXDT1BHBB4508 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 260 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 7733 Engine hrs, Eaton Fuller EH 8EX06A Automated Transmission, Differential Lock, 13220 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 6.14:1 Axle Ratio, 32220 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 177 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, One-Person Articulating-Telescopic Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 9 ft x 94 in Bed, Pintle Hitch Usage: 95,253 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
1834	2017 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN0HH161936 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8428 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 66000 lb Rears, 11R22.5, 194 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulating-Telescopic Boom, Utility Body, A-Outriggers, Rear Outriggers, Remote Control w/Cord, 16 ft x 60 in Bed, Pintle Hitch Usage: 89,264 Mi Asset located in: Lake Worth, TX	1838	2019 Altec AT41M 41 ft on 2019 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GTXKED88465 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, Insulated One-Person Articulating-Telescopic Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Bumper Mounted Winch, 13 ft 6 in x 94 in Bed Usage: 190,407 Mi
1000	2016 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH474515 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8241 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, A-Outriggers, Rear Outriggers, 17 ft x 96 in Bed, Pintle Hitch Usage: 65,063 Mi Asset located in: Lake Worth, TX	1839	Asset located in: Lake Worth, TX 2019 Altec AT41M 40 ft on 2019 Ford F-550 4x2 Bucket Truck S/N: 1FDUF5GT7KED57111 C/W: Ford V8 6.7 L 330 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 7500 lb Front Axle, 19500 lb GVWR, 225/70R19.5, PTO, 400 lb Capacity, Center Mounted, Insulated One-Person Articulating-Telescopic Boom, Material Handling Jib, Straight Down Outriggers, Bumper Mounted Winch, 13 ft 6 in x 96 in Bed Usage: 149,980 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1840	2012 Altec LRV55 55 ft on 2011 Freightliner M2 106 4x2 Forestry Bucket Truck S/N: 1FVACXDU3BDAU8449 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2009 US EPA Label, Requires Diesel Exhaust Fluid, 15196 Engine hrs, Eaton Fuller FS-6406A 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 21-145 Drive Axles, 4.88:1 Axle Ratio, 33000 lb GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 187 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, Insulated One-Person Articulating- Telescopic Boom, Chip Body, A-Outriggers, 11 ft x 92 in Bed Usage: 84,033 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 84,033, TITLE SHOWS 999,999, TITLE BRANDED NOT ACTUAL MILEAGE	1846	2009 Peterbilt 340 6x4 Volumetric Mixer Truck S/N: 2NPRLN0X69M771130 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 315 hp Engine, 2008 US EPA Label, 15485 Engine hrs, Eaton Fuller RTO-11908LL 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, Dana D46-170HP Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring over Walking Beam Suspension, 240 in Wheelbase, PTO, 2008 Cemen Tech MCD8-130 8 cyd Mixer Unit Usage: 141,364 Mi Asset located in: Lake Worth, TX 2005 Mack CV713 8x4 Volumetric Mixer Truck S/N: 1M2AG11C65M015628 C/W: Mack 6 Cylinder Diesel Engine, 12565
1841	Asset located in: Lake Worth, TX 2006 International 4300 Bucket Truck S/N: 1HTMMAAL16H341098 Usage: Not Available Asset located in: Humble, TX		Engine hrs, Engine Brake, Manual Transmission, 16540 lb Front Axle, 44000 lb Rears, 60540 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24. 5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Camelback Spring Suspension,
1842	2005 GMC C8500 Bucket Truck S/N: 1GDP8C1C75F512565 Usage: Not Available		252 in Wheelbase, PTO, 2005 Cemen Tech MCD10-150 Mixer Unit Usage: 265,336 Mi Asset located in : Lake Worth, TX
	Asset located in: Humble, TX	1848	2004 Kenworth T800 8x4 Volumetric Mixer
1843	Versalift on 1999 Ford F-450 4x2 Crew Cab Bucket Truck S/N: 1FDXW46F9XEA93643 C/W: V8 Diesel Engine, Automatic Transmission, 5790 lb Front Axle, 10880 lb Rears, 15000 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Center Mounted, Insulated One-Person Articulating- Telescopic Boom, Utility Body, Out and Down Outriggers, 13 ft 9 in x 96 in Bed Usage: 143,468 Mi		Truck S/N: 1NKDXUTX94J051508 C/W: Cat C12 6 Cylinder 11.9 L Diesel 380 hp Engine, 2003 US EPA Label, 13738 Engine hr Eaton Fuller 8LL Manual Transmission, 4.33: Axle Ratio, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Suspension, 224 in Wheelbase, PTO Usage: 52,449 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	_	The state of the s
1844	2011 Ford F-550 XL 4x2 Chipper Truck S/N: 1FDUF5GT2BEB53610 C/W: 6 Cylinder 6.7 L 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14704 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft x x 78 in High Body, Pintle Hitch Usage: 101,174 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	CHOICE 1849	2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV5JDJL7485 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14464 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Aluminum Wheels,
1845	2017 Putzmeister BSF42-5.16H on 2018 Mack MRU613 8x6 Concrete Pump Truck S/N: 1M2AV04C0JM018451 C/W: Mack 6 Cylinder Engine, Manual Transmission, 20000 lb Front Axle, 23000 lb Rears, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, Hydraulic System, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 72,820 Mi Asset located in: Humble, TX		425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 51,410 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
		LOC #	Details
1850	2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJM2090 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, CARB	СНОІС	E OF 3 - Lot #'s: 1854, 1855, 1856
	Compliant, Requires Diesel Exhaust Fluid, 12913 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 238 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 107,793 Mi Asset located in: Lake Worth, TX	1854	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJL7486 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17360 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires,
CHOIC	CHOICE OF 3 - Lot #'s: 1851, 1852, 1853		11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 205,429 Mi
1851	51 2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV0JDJM2089 C/W: DD13, Allison 4500 Automatic, 11 Yard Beck Mixer Usage: 175,338 Mi Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
		1855	2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV3JDJL7484 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, Double Frame, TufTrac Suspension, 248 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 208,663 Mi Asset located in: Lake Worth, TX 2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV0JDJM2092
1852	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJM2087 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 13808 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes		
		1856	
	Usage: 176,719 Mi Asset located in : Lake Worth, TX		C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel
1853	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV9JDJM2088 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14895 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, 11 cyd Mixer Unit, 3 Removable Chutes Usage: 198,768 Mi		Exhaust Fluid, 15416 Engine hrs, Engine Brake Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 184,716 Mi Asset located in: Lake Worth, TX

Lot # **Details** Lot # Details 1860 2019 Freightliner 114SD 6x4 Mixer Truck S/N: 1FVHG3DV7KHJS0957 CHOICE OF 2 - Lot #'s: 1857, 1858 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15048 Engine hrs, Engine Brake, 1857 2014 Kenworth W900 8x4 Mixer Truck Allison Automatic Transmission, 20000 lb S/N: 1NKWL70X3EJ387392 Front Axle, 46000 lb Rears, 66000 lb GVWR, Air C/W: Cummins 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Exhaust Fluid, Automatic Transmission, Double Boxes, TufTrac Suspension, 232 in Wheelbase, Differential Locks, 20000 lb Front Axle, 46000 11 cyd Mixer Unit, 3 Removable Chutes, lb Rears, 66000 lb GVWR, Aluminum Wheels, Remote Control w/Cord 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Usage: 147,480 Mi Trailing Tag Axle, Dual Steering Boxes, Double Asset located in: Lake Worth, TX Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 3 Removable 1861 2019 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV9KHKF4834 Usage: Not Available C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Asset located in: Lake Worth, TX hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 1858 2014 Kenworth W900 8x4 Mixer Truck 14290 Engine hrs, Allison Automatic S/N: 1NKWL70X1EJ387391 Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17553 Engine hrs, Allison Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, 4500 Automatic Transmission, 20000 lb Front TufTrac Suspension, 232 in Wheelbase, PTO, Axle, 46000 lb Rears, Meritor RT-46-160 Drive 10.5 cyd Mixer Unit, 3 Removable Chutes, Axles, 4.89:1 Axle Ratio, 66000 lb GVWR Remote Control w/Cord Aluminum Wheels, 385/65R22.5 Front Tires, Usage: 167,132 Mi 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber Asset located in: Lake Worth, TX over Walking Beam Suspension, 250 in Wheelbase, PTO, 2 Removable Chutes, Remote Control w/Cord CHOICE OF 3 - Lot #'s: 1862, 1863, 1864 Usage: 182,221 Mi Asset located in: Lake Worth, TX 1862 2018 Freightliner 114 SD 6x4 T/A Mixer Truck S/N: 3ALHG3DV4JDJW4872 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 CHOICE OF 3 - Lot #'s: 1859, 1860, 1861 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13917 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, 1859 2019 Freightliner 114 SD 6x4 T/A Mixer Truck Differential Lock, 22000 lb Front Axle. 46000 lb S/N: 1FVHG3DV5KHJS0956

C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automated Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Rubber over Walking Beam Suspension, 234 in Wheelbase, PTO, Hydraulic System, Beck Mixer Unit, 3 Removable Chutes, Remote Control w /Cord, DD13, Allison 4500 Automatic, Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote

Usage: 133,211 Mi Asset located in: Lake Worth, TX

Rears, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Rubber over Walking Beam Suspension, 234 in Wheelbase, PTO, Hydraulic System, Beck Mixer Unit, 3 Removable Chutes, Remote Control w/Cord, DD13, Allison 4500 Automatic, Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote Usage: 143,981 Mi

Lot #	Details	Lot #	Details
1863	2018 Freightliner 114 SD 6x4 T/A Mixer Truck S/N: 3ALHG3DVXJDJW4875 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14693 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Hydraulic System, Beck Mixer Unit, 3 Removable Chutes, Remote Control w/Cord, DD13, Allison 4500 Automatic, Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote Usage: 159,856 Mi Asset located in: Lake Worth, TX	1867 CHOICI	2017 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV6HDJG5267 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, Requires Diesel Exhaust Fluid, 13679 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 36,162 Mi Asset located in: Lake Worth, TX
1864	2018 Freightliner 114 SD 6x4 T/A Mixer Truck S/N: 3ALHG3DV6JDJW4873 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 16397 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Hydraulic System, Beck Mixer Unit, 3 Removable Chutes, Remote Control w/Cord, DD13, Allison 4500 Automatic, Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote	1868	2015 Freigthliner 114SD 6x4 Mixer Truck S/N: 1FVHG3DV9FHGD2918 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 20129 Engine hrs, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, PTO, 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 242,364 Mi Asset located in: Lake Worth, TX
	Usage: 171,963 Mi Asset located in : Lake Worth, TX	1869	2015 Freightliner 114SD 6x4 Mixer Truck S/N: 3ALHG3DV8FDGP8010
СНОІСІ	E OF 3 - Lot #'s: 1865, 1866, 1867		C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15144 Engine hrs, Engine Brake, Allison Automatic Transmission, Double
1865	2018 Freightliner 114 SD T/A Mixer Truck S/N: 3ALHG3DV8JDJW4874 C/W: DD13, Allison 4500 Automatic, Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote Usage: 174,579 Mi Asset located in: Lake Worth, TX		Differential Locks, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 231 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 162,097 Mi
1866	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV1JDJW4876 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14061 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit Usage: 139,282 Mi Asset located in: Lake Worth, TX	1870	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DVXFHGC6643 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 186,822 Mi Asset located in: Lake Worth, TX

Lot # **Details** Lot # Details CHOICE OF 3 - Lot #'s: 1871, 1872, 1873 CHOICE OF 2 - Lot #'s: 1874, 1875 1871 1874 2015 Freightliner 114 SD 6x4 Mixer Truck 2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV8FDGK8255 S/N: 3ALHG3DVXFDGK8256 C/W: Detroit DD13 6 Cylinder Diesel Engine, 18450 Engine hrs, Engine Brake, Allison C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 5810 Automatic Transmission, 22000 lb Front Axle. Engine hrs. Engine Brake, Allison 6-Speed Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.86:1 Axle Ratio, 68000 lb GVWR, Air 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 234 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Ride Cab, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Removable Chutes Boxes, Double Frame, Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 204,227 Mi Asset located in: Lake Worth, TX Usage: 204,689 Mi 1872 2015 Freightliner 114SD 6x4 Mixer Truck Asset located in: Lake Worth, TX S/N: 1FVHG3DV6FHGC6641 1875 2015 Freightliner 114SD 6x4 Mixer Truck C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel S/N: 1FVHG3DV7FHGD2917 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19288.9 Engine hrs. Engine Brake, Allison 4000 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Exhaust Fluid, 19761.8 Engine hrs, Allison 4500 Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam 11R22.5 Rear Tires, Dual Steering Boxes, Suspension, 230 in Wheelbase, PTO, Beck Double Frame, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes Usage: 21,980 Mi Mixer Unit, 3 Removable Chutes Usage: 225,694 Mi Asset located in: Lake Worth, TX

1873 2015 Freightliner 114 SD 6x4 Mixer Truck

S/N: 1FVHG3DV0FHGD3309 C/W: 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 8.03 m3 Mixer Unit, 3 Removable Chutes, Remote Control w/Cord

Usage: 220,173 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1876, 1877

1876 2015 Freightliner 114 SD 6x4 Mixer Truck

Asset located in: Lake Worth, TX

S/N: 1FVHG3DVXFHGS0264 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 222 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w /Cord

Usage: 34,426 Mi

Notes: ADDITIONAL INFORMATION

AVAILABLE IN OFFICE;

Lot #	Details	Lot #	Details
1877	S/N: 1FVHG3DV2FHGN1430 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 350 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 222 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 36,664 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE;	1882	2007 Mack CPT713 Mixer Truck S/N: 1M2AT04C27M006297 Usage: Not Available Asset located in: Lake Worth, TX
		1883	2008 Mack CHU613 Mixer Truck S/N: 1M1AN09Y38N003147 Usage: Not Available Asset located in: Lake Worth, TX
		1884	2005 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C75M034222 C/W: Mack 6 Cylinder Diesel Engine, 28940 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 229 in Wheelbase, 3 Removable Chutes Usage: 337,303 Mi Asset located in: Lake Worth, TX 2006 Peterbilt 357 6x4 Mixer Truck S/N: 1NPALT0X46D890572 C/W: Cat 6 Cylinder Diesel Engine, 9701 Engine hrs, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Aluminum Wheels, 445/65R22.5 Front Tires,
1878	Asset located in: Lake Worth, TX 2014 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV7EHFW3536 C/W: Detroit DD15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18254 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Aluminum Front Wheels, 425	_	
	/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, Composite Water Tank Usage: 185,216 Mi Asset located in: Lake Worth, TX	1885	
1879	879 2015 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C9FM028775 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14199 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5, Dual Steering Boxes, Camelback Suspension, 234 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes Usage: 133,877 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		12R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Suspension, 216 in Wheelbase, PTO, 3 Removable Chutes, Remote Control w/Cord Usage: 267,072 Mi Asset located in : Lake Worth, TX
			2003 Peterbilt 357 6x4 Mixer Truck S/N: 1NPALT0X53D802186 C/W: Cat C10 6 Cylinder Diesel 305 hp Engine, 7071 Engine hrs, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, 3 Removable Chatter
1880	2008 Mack GU813 Mixer Truck S/N: 1M2AX13C98M001689 Usage: Not Available		Usage: 266,861 Mi Notes: LOCATED-IN-HOUSTON-TX Asset located in: Humble, TX
1881	Asset located in: Lake Worth, TX 2007 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C07M061944 C/W: Mack AMI 6 Cylinder Diesel 325 hp Engine, 10175 Engine hrs, Mack Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5	1887	2007 Western Star 4900 SA T/A Sleeper Truck Tractor S/N: 5KJJALCK77PX38561 Usage: Not Available Asset located in: Lake Worth, TX 2002 Kenworth T800 6x4 Mixer Truck
	Rear Tires, Dual Steering Boxes, Double Frame, Camelback Spring Suspension, 227 in Wheelbase, PTO, CBMW 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 38,616 Mi Asset located in: Lake Worth, TX		S/N: 1NKDLU0X12J703485 C/W: Cat C-12 6 Cylinder 11.9 L Diesel 505 hp Engine, 2002 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 425/65R22. 5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 3 Removable Chutes Usage: 159,586 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1889	1999 Mack DMM6906S 6x4 Mixer Truck S/N: 1M2E178CXXM002704 C/W: Mack EM7 6 Cylinder 728 cid Diesel Engine, 1998 US EPA Label, 47454 Engine hrs, 8LL Manual Transmission, Aluminum Front Wheels, 445/65R22.5, Walking Beam Suspension, 180 in Wheelbase, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 89,880 Mi Asset located in: Lake Worth, TX	1896	5 2007 Hino 268 4x2 Attenuator Truck S/N: 5PVNJ8JP872S50064 C/W: Hino Motors J08E-TA 6 Cylinder 7.7 L Diesel Engine, 2008 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 218 in Wheelbase, Flatbed, In-Cab Attenuator Controller Usage: 343,850 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	
1890	2009 GMC T8500 4x2 COE Extended Cab Rear Loader Waste Collection Truck S/N: 1GDP8F1B29F405423 C/W: Isuzu 6HK1X 6 Cylinder 7.8 L Diesel 260 hp Engine, 2008 US EPA Label, Allison Automatic Transmission, 13220 lb Front Axle, 23360 lb Rears, 36580 lb GVWR, 11R22.5 Front Tires, 445/65R22.5 Rear Tires, Spring Suspension, 171 in Wheelbase, PTO, McNelius 1710 17 cyd Capacity Collection Body Usage: 68,923 Mi Asset located in: Humble, TX		THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 International 8000 4x2 Toter Truck S/N: 1HSHWAHN67J535045 C/W: 6 Cylinder Diesel Engine, 21882 Engine hrs, Eaton Fuller Manual Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 156 in Wheelbase	
1891	1997 Freightliner FL70 4x2 Attenuator Truck S/N: 1FV3HLAA4VH739867 C/W: Cummins C8.3 8.3 L Diesel Engine, 1996		Usage: 239,028 Mi Asset located in: Midland, TX	
	US EPA Label, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 216 in Wheelbase, Flatbed Usage: Not Available Asset located in: Humble, TX	1898	2020 Peterbilt 567 6x4 Roll-Off Truck S/N: 1NPCL40X3LD650696 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10547 Engine hrs, Engine Brake, 10-Speed Manual Transmission, Triple	
1892	2017 Freightliner M2 106 4x2 Attenuator Truck S/N: 3ALACWDT6HDJE8126 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 4774 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, 5.13:1 Axle Ratio, 26000 lb GVWR, 10R22.5, Airliner Suspension, 282 in	1899	Differential Locks, 20000 lb From lb Rears, 66000 lb GVWR, Alumin 425/65R22.5 Front Tires, 11R22. Dual Steering Boxes, Double Fran Air Ride Suspension, 276 in Whee 2019 Galbreath U5-OR-174 Roll-C4 in Hoist, Winch Usage: 285,990 Mi	Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 276 in Wheelbase, PTO, 2019 Galbreath U5-OR-174 Roll-Off Body, 23 ft 4 in Hoist, Winch Usage: 285,990 Mi Asset located in: Lake Worth, TX
	Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 84,841 Mi Asset located in : Lake Worth, TX		S/N: 3ALHG3DV8DDFF1962 C/W: Detroit 6 Cylinder Diesel Engine, R Diesel Exhaust Fluid, Automatic Transm	C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission,
1894	·		16000 lb Front Axle, 44000 lb Rears, 60000 lb GVWR, Air Ride Cab, 295/75R22.5, Double Frame, TufTrac Suspension, 23 ft 4 in Hoist Usage: 472,556 Mi Asset located in : Lake Worth, TX	
		1900	2005 Peterbilt 357 6x4 Roll-Off Truck S/N: 1NPALT0XX5N857701 C/W: Cat C11 6 Cylinder Diesel Engine, 1888 Engine hrs, Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 266 in Wheelbase, PTO, GH 1560 Roll-Off Body, 23 ft Hoist Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
1901	2022 Chevrolet Silverado 5500HD 4x2 Rollback Truck S/N: 1HTKHPVM6NH675305 C/W: Navistar Duramax V8 6.6 L Diesel 350 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7940 Ib Front Axle, 15000 Ib Rears, 4.10:1 Axle Ratio, 22940 Ib GVWR, 225/70R19.5, Spring Suspension, 232 in Wheelbase, PTO, Century Steel Wrecker Body, 5000 Ib Winch Capacity, Tow Dollies Usage: 60,704 Mi Notes: X2-CNV Dash Vin from photo; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	1904A 1904B	2009 Forest River Georgetown Motor Home S/N: 1F6NF53Y590A00112 C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2009 US EPA Label, 3 Slide Outs, Power Entrance Step, Power Leveling Jacks, Power Awning, Onan RV QG 5500 LP 5.5 kW Generator, Rear View Camera Usage: 23,619 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2007 Gulf Stream Independence Motor Home S/N: 4UZACLBW57CZ34853 C/W: Air Conditioner, Automatic Transmission, 1899.5 hrs Carrier Engine, Cummins 6 Cylinder Diesel Engine, 2007 US EPA Label, 3 Slide Outs, Power Entrance Step Power Leveling Lacks
	Asset located in: Lake Worth, TX	_	Power Entrance Step, Power Leveling Jacks, Power Awning, Generator w/ 266 hrs
1902	2020 Ram 5500 4x4 Rollback Truck S/N: 3C7WRNDL4LG136586		Usage: 82,082 Mi Notes: LOCATED-IN-FORT-WORTH-TX
	C/W: Cummins 6 Cylinder 6.7 L Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid,		Asset located in: Lake Worth, TX
		1905	2002 Prevost H3-45 Motor Home S/N: 2PCV33491X1013393 C/W: Air Conditioner, Allison Automatic Transmission, Detroit 6 Cylinder 12.7 L 500 hp Engine, Sleeps 2 People, Clothes Washer & Dryer, Power Awning, Power Tech 25 kW Generator Usage: 142,465 Mi Asset located in: Lake Worth, TX
1903	2019 Isuzu NRR 4x2 COE Rollback Truck	1906	
	S/N: JALE5W160K7304175 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5916 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500.0 lb GVWR, 225/70R19.5, Spring Suspension, 178 in Wheelbase, PTO, Wet Kit, 21 ft 6 in x 96 in Bed, Aluminum Frame, 18000 lb Winch Usage: 196,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	0061	2018 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JV5J4S67771 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9282 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Carrier Reefer Unit, 8457 Reefer Total Hours:, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 171,017 Mi Notes: SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
1904	2005 Freightliner M2 106 4x2 Sleeper Tow	105-	Asset located in: Lake Worth, TX
	Truck S/N: 1FVAC20C35HV14126 C/W: Cat C7 6 Cylinder Diesel 250 hp Engine, 12717 Engine hrs, Eaton Fuller RT8709B 9- Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS21145 Drive Axles, 3.90:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 178 in Wheelbase, PTO, Steel Wrecker Body Usage: 262,313 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1907	2018 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JL0J4S52089 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Hendrickson Air Ride Suspension, 188 in Wheelbase, Carrier Reefer Unit, 9213 Reefer Total Hours:, Morgan 16 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 184,843 Mi Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 1912 2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT1H4S57439 CHOICE OF 3 - Lot #'s: 1908, 1909, 1910 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb 1908 2017 Hino 268 4x2 Refrigerated Truck Rears, 25950 lb GVWR, 11R22.5, Hendrickson S/N: 5PVNJ8JV1H4S66305 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Air Ride Suspension, 252 in Wheelbase, Carrier Reefer Unit, Supreme 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Walk-Up Ramp, Exhaust Fluid, Automatic Transmission, 10000 PROFESSIONALLY-MAINTAINED-FLEETlb Front Axle, 19000 lb Rears, 25950 lb GVWR, VEHICLE-PAG Steel, 11R22.5, Air Ride Suspension, Thermo King T-1080R Whisper Reefer Unit, 8637 Reefer Usage: 284,077 Mi Asset located in: Lake Worth, TX Engine Hours:, 8637 Reefer Total Hours: Morgan 24 ft x 102 in Wide x 103 in High Body, 1913 2019 Freightliner M2 106 4x2 Refrigerated Walk-Up Ramp, Liftgate Usage: 293,547 Mi S/N: 3ALACWFC0KDKL2452 Asset located in: Lake Worth, TX C/W: Cummins B 6 Cylinder 6.7 L Diesel 250 hp 1909 2017 Hino 268 4x2 Refrigerated Truck Engine, 2018 US EPA Label, 9375 Engine hrs, Eaton Fuller 3 Automatic Transmission, 10000 S/N: 5PVNJ8JT8H4S57955 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride C/W: Hino 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 254 in Suspension, 252 in Wheelbase, Thermo King T-680R Reefer Unit, Morgan 24 ft x 102 in Wide x 96 in High Body, Curbside Door, Liftgate Wheelbase, Thermo King T-1080R Reefer Unit, 9481 Reefer Engine Hours:, 9481 Reefer Total Usage: 332,255 Mi Asset located in: Lake Worth, TX Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 297,803 Mi 1914 2016 Freightliner M2 106 Refrigerated Truck S/N: 3ALACWDT5GDGV8814 Usage: Not Available Asset located in: Lake Worth, TX Notes: THIS UNIT RUNS BUT MAY HAVE 1910 2017 Hino 268 4x2 Refrigerated Truck DEFICIENCIES IN ITS POLLUTION CONTROL S/N: 5PVNJ8JT2H4S57952 SYSTEMS WITH LIABILITIES OUTLINED IN C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, RESTORATION OF ALL POLLUTION CONTROL Steel, 11R22.5, Air Ride Suspension, 254 in Wheelbase, Thermo King T-1080R Whisper Reefer Unit, 5965 Reefer Engine Hours, 5965 SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE Reefer Total Hours:, Morgan 24 ft x 102 in PRIOR TO REMOVAL OF UNIT FROM YARD Wide x 103 in High Body, Walk-Up Ramp, Asset located in: Lake Worth, TX Liftgate Usage: 322,392 Mi 1915 2016 Freightliner M2 106 4x2 Refrigerated Asset located in: Lake Worth, TX S/N: 3ALACWDT5GDHE5396 CHOICE OF 2 - Lot #'s: 1911, 1912 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR,

1911 2017 Hino 268 4x2 Refrigerated Truck

S/N: 5PVNJ8JTXH4S57455 C/W: Hino 6 Cylinder Diesel Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, Carrier Transicold Reefer Unit, 12952 Reefer Engine Hours:, 16707 Reefer Total Hours:, Supreme 24 ft x 102 in Wide x 98 in High Body, Curbside Door Usage: 237,435 Mi

Asset located in: Lake Worth, TX

C/W: Cummins 6 Cylinder Diesel Engine, 11342 Steel, 11R22.5, Air Ride Suspension, 256 in Wheelbase, Carrier Reefer Unit, 13046 Reefer Total Hours:, Kidron 24 ft x 102 in Wide x 97 in High Body Usage: 297,043 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Lot #	Details	Lot #	Details
1916	2015 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACXDT1FDGF1570 C/W: Cummins ISB 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10137 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 5.88:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, steel, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Carrier Transicold Reefer Unit, 11638 Reefer Total Hours:, Morgan 22 ft x 102 in Wide x 97 in High Body Liftgate	1921	2017 Chevrolet G3500 4x2 Refrigerated Truck S/N: 1GB0GRFF4H1344050 C/W: V8 Gasoline Engine, 8673 Engine hrs, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, Aluminum Wheels, 245/75R16, Spring Suspension, 139 in Wheelbase, Thermo King V-520 NM Max Reefer Unit, GCE 11 ft x 88 in Wide x 72 in High Body, Curbside Door Usage: 328,694 Mi Asset located in: Lake Worth, TX
	in Wide x 97 in High Body, Liftgate Usage: 313,978 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	1922	2016 International 4300 4x2 Beverage Truck S/N: 1HTMMMML3GH225609 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 6-Speed Automatic Transmission, 8618 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 235 in Wheelbase, Mickey 21 ft Body, 36 in Wide Bays, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 343,147 Mi
1917	2012 Freightliner M2 106 Refrigerated Truck S/N: 1FVACWDT0CHBS3944 Usage: Not Available Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	1923	2018 Peterbilt 337 4x2 Van Truck S/N: 2NP2HM7X2JM491941 C/W: Paccar B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7218 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 6.17:1 Axle Ratio, 32000 lb GVWR, 275/80R22.5, Spring Suspension, 275 in Wheelbase, Wabash 24 ft x 102 in Wide x 88 in High Body, Liftgate, EQUIPMENT-FROM- YELLOW-CORP Usage: 110,293 Mi Asset located in: Lake Worth, TX 2017 Peterbilt 337 4x2 Van Truck S/N: 2NP2HM6X2HM409086
1918	2018 International 4300 4x2 Refrigerated Truck S/N: 3HAMMML4JL736540 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5440 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 156,143 Mi Asset located in: Lake Worth, TX	1925	C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9288 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, Dana S21170 Drive Axles, 4.56: 1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 260 in Wheelbase, Morgan 24 ft x 102 in Wide x 101 in High Body, Curbside Door, Liftgate Usage: 312,144 Mi Asset located in: Humble, TX 2015 Peterbilt 337 4x2 Van Truck S/N: 2NP2HJ7X9FM275736
1920	2019 Isuzu NQR 4x2 COE Refrigerated Truck S/N: JALE5W167K7900576 C/W: Isuzu 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6830 lb Front Axle, 12980 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 150 in Wheelbase, Thermo King T-680R Reefer Unit, supreme 18 ft x 102 in Wide x 92 in High Body, Curbside Door, Liftgate Usage: 179,717 Mi Asset located in: Lake Worth, TX		C/W: Paccar ISL 6 Cylinder 8.9 L Diesel 260 h Engine, Requires Diesel Exhaust Fluid, Allison 3000 Automatic Transmission, 12000 lb Fron Axle, 21000 lb Rears, 4.11:1 Axle Ratio, 33000.0 lb GVWR, Aluminum Outer Wheels, 2' /75R22.5, Paccar Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 287,399 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
СНОІС	HOICE OF 2 - Lot #'s: 1926, 1927		1931 2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV9K4S72697 C/W: Hino 6 Cylinder Diesel Engine, 2018 US	
1926	2020 Hino 268 Van Truck S/N: 5PVNJ8JV3L4S75936 Usage: 223,964 Mi Asset located in: Lake Worth, TX	10000 lb Front Axle, 19000 lb Rears, 2595 GVWR, 295/75R22.5 Front Tires, 11R22.5 Tires, Air Ride Suspension, Supreme 26 ft 102 in Wide x 103 in High Body, Walk-Up F	11873 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, Supreme 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 311,559 Mi	
1927	2020 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV4L4S75931		Asset located in: Lake Worth, TX	
	C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5949 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 237,576 Mi	CHOICE OF 5 - Lot #'s: 1932, 1933, 1934, 1935, 1936 1932 2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S74135 C/W: Hino 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 7853 Engine h Automatic Transmission, 10000 lb Front Axle 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Hendrickson Air Ride	E OF 5 - Lot #'s: 1932, 1933, 1934, 1935, 1936 2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S74135	
	Asset located in: Lake Worth, TX ICE OF 2 - Lot #'s: 1928, 1929 3 2020 Hino 268 4x2 Van Truck S/N: 5PVNE8JVXL4S57650		19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, PROFESSIONALLY-MAINTAINED-FLEET-	
1928			Usage: 252,005 Mi	
	C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel	1000	Asset located in: Lake Worth, TX	
	Exhaust Fluid, 5054 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 243,455 Mi Asset located in: Lake Worth, TX	1933	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3K4S70413 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6861 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hino Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x	
1929	2020 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0L4S57611 C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp		102 in Wide x 103 in High Body Usage: 195,635 Mi Asset located in : Lake Worth, TX	
CHOIC	Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 274,702 Mi Asset located in: Lake Worth, TX	1934	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S70473 C/W: Hino Motors J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7082 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp	
CHOICE OF 2 - Lot #'s: 1930, 1931			Usage: 199,209 Mi Asset located in: Lake Worth, TX	
1930	2019 Hino 268 Van Truck S/N: 5PVNJ8JV9K4S70786 Usage: 241,223 Mi Asset located in: Lake Worth, TX	1935	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3K4S70475 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in Wide x 103 in High Body Usage: 220,034 Mi	

Lot #	Details	Lot #	Details
1936	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV1K4S70474 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8646 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 227,375 Mi	1941 1942	E OF 2 - Lot #'s: 1941, 1942 2018 Hino 268 Van Truck S/N: 5PVNJ8JV7J4S70011 Usage: 239,327 Mi Asset located in: Lake Worth, TX 2018 Hino 268 Van Truck
	Asset located in: Lake Worth, TX	_	S/N: 5PVNJ8JV6J4S70016 Usage: 335,947 Mi
CHOICI	E OF 4 - Lot #'s: 1937, 1938, 1939, 1940		Asset located in: Lake Worth, TX
1937	2019 Hino 268 4x2 Van Truck	сноісі	E OF 2 - Lot #'s: 1943, 1944
	S/N: 5PVNJ8JV5K4S71661 C/W: Hino 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7844 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 264,419 Mi Asset located in: Lake Worth, TX	1943	2017 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0H4S55963 C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 302,562 Mi Asset located in: Lake Worth, TX
1938	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV7K4S70785 C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11645 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 394,055 Mi Asset located in: Lake Worth, TX	1944	2016 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXG4S61134 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX
1939	2018 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV9J4S67062	СНОІСІ	E OF 3 - Lot #'s: 1945, 1946, 1947
1940	C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, Mickey 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 226,779 Mi Asset located in: Lake Worth, TX 2018 Hino 268 4x2 Van Truck	1945	2016 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0G4S54665 C/W: J08E-VC 6 Cylinder Diesel 220 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 779,914 Mi
	S/N: 5PVNJ8JV5J4S67334 C/W: 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1946	2015 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV7F4S58836 C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 999 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 762,239 Mi Asset located in: Lake Worth, TX	1951	2013 Hino 165 4x2 Van Truck S/N: 5PVNE8JT2D4S55035 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, READING 24 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 791,274 Mi Asset located in: Lake Worth, TX
1947	2014 Hino 268 4x2 Van Truck S/N: 5PVNE8JT3E4S55904 C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase,	CHOIC 1952	2010 Hino 165 4x2 Van Truck S/N: 5PVNJ8JV5A4S52235 C/W: Hino Motors J08E-TV 6 Cylinder 7.7 L
 1948	Supreme Corp 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 665,898 Mi Asset located in: Lake Worth, TX 2013 Hino 268 4x2 Van Truck		Diesel 220 hp Engine, 2009 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate
1940	S/N: 5PVNE8JVXD4S52658		Usage: 413,815 Mi Asset located in : Lake Worth, TX
	C/W: Hino Motors J08E-VC 6 Cylinder 7.7 L Diesel 220 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 239 in Wheelbase, Morgan 20 ft x 102 in Wide x 93 in High Body Usage: 163,671 Mi Asset located in: Lake Worth, TX 2013 Hino 268 4x2 Van Truck	1953	2010 Hino 268 4x2 Van Truck S/N: 5PVNE8JV3A4S51573 C/W: Hino J08E-TV 6 Cylinder Diesel 220 hp Engine, 2009 US EPA Label, 999 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 269 in Wheelbase Morgan 26 ft x 102 in Wide x 103 in High Body Curbside Door, Liftgate
1940A	S/N: 5PVNE8JT8D4S54925		Usage: 542,329 Mi Asset located in: Lake Worth, TX
	C/W: 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 251 in Wheelbase, Reading 24 ft x 102 in Wide x 102 in High Body, Liftgate	1954	2016 Hino 155 Van Truck S/N: JHHXDM1H2GK003847 Usage: 206,947 Mi Asset located in : Lake Worth, TX
	Usage: 733,693 Mi Asset located in : Lake Worth, TX	1955	2020 Freightliner M2 112 4x2 Moving Van Truck
CHOICE	E OF 2 - Lot #'s: 1949, 1950		S/N: 3ALAC4DV3LDME8608 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2019 US EPA Label, 9094 Engine hrs, Engine Brake, Eaton Fuller FAO-14810C
1949	2017 Hino 165 4x2 Van Truck S/N: 5PVNE8JV8H4S55600 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 235 in Wheelbase, Supreme 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 691,347 Mi Asset located in: Lake Worth, TX		Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-21-160 Drive Axles, 3.07:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 533,064 Mi Asset located in: Lake Worth, TX
1950	2016 Hino 165 Van Truck S/N: 5PVNE8JV7G4S54761 Usage: Not Available		

Lot #	Details	Lot #	Details
1956	2020 Freightliner M2 106 4x2 Van Truck S/N: 3ALACXFC5LDMA4042 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, MARION 26 ft x 102 in Wide x 109 in High Body, Liftgate Usage: 294,302 Mi Asset located in: Lake Worth, TX	1963	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB4KDKH7137 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,942 Mi Asset located in: Lake Worth, TX
1960	2020 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWD29LDLW1690 C/W: Detroit DD8 6 Cylinder 7.7 L Diesel 260 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 10R22.5, Air Ride Suspension, 283 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Liftgate Usage: 327,840 Mi Asset located in: Lake Worth, TX	1964	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC5JDJH4350 C/W: Cummins 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 312,803 Mi Asset located in: Lake Worth, TX
1961	2019 Freightliner M2 106 4x2 Van Truck		
	S/N: 3ALACWFC8KDKK6432 C/W: Cummins 6 Cylinder 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, Smyrna 26 ft x 96 in Wide x Body, Liftgate Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1965	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC1JDJZ7466 C/W: Cummins 6 Cylinder 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17000 lb Rears, 26000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, Morgan 24 ft x x Body, Curbside Door, Liftgate Usage: 397,493 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
CHOIC	E OF 2 - Lot #'s: 1962, 1963		PRIOR TO BIDDING Asset located in: Lake Worth, TX
1962	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB3KDKH7131 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2018 US EPA Label, 5566 Engine hrs, Allison 2200 4 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 214,259 Mi Asset located in: Lake Worth, TX	1966	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFCXJDJZ7465 C/W: Cummins B 6 Cylinder 6.7 L 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10762.9 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 256 in Wheelbase, Morgan 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 379,528 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 1967 2018 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWFB4JHJH4986 CHOICE OF 2 - Lot #'s: 1972, 1973 C/W: Detroit DD5 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7569.8 Engine hrs, Automatic 1972 2016 Freightliner M2 106 4x2 Van Truck Transmission, 10000 lb Front Axle, 19000 lb S/N: 3ALACWDT8GDHM0083 Rears, 26000.0 lb GVWR, Air Ride Cab, 11R22. C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel 5, Airliner Air Ride Suspension, 270 in Wheelbase, PTO, AMH 26 ft x 102 in Wide x 97 Exhaust Fluid, 5608 Engine hrs. Allison 2100 in High Body, Liftgate, Asset includes a 2.5Ton Automatic Transmission, 10000 lb Front Axle, pallet jack and straps 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Steel, 11R22.5, Spring Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-Usage: 288,869 Mi Notes: . Asset located in: Livingston, LA MAINTAINED-FLÉET-VEHICLE-PAG 1968 2018 Freightliner M2 106 4x2 Van Truck Usage: 180,227 Mi S/N: 3ALACWFC6JDJK7266 Asset located in: Lake Worth, TX C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires 1973 2016 Freightliner M2 4x2 Van Truck Diesel Exhaust Fluid, 7811 Engine hrs, S/N: 3ALACWDT2GDHN0995 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2018 US EPA Label, 7610 Engine hrs, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Steel, 295 /75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, AMH 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 259,719 Mi Suspension, 270 in Wheelbase, supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINÉD-FLEET-Asset located in: Lake Worth, TX VEHICLE-PAG 1969 2018 Freightliner M2 106 4x2 Van Truck Usage: 589,467 Mi S/N: 3ALACWFC1JDJS4825 Asset located in: Lake Worth, TX C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17126 Engine hrs, Eaton Fuller Automatic CHOICE OF 5 - Lot #'s: 1974, 1975, 1976, 1977, 1978 Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 1974 2016 Freightliner M2 106 4x2 Van Truck 28 ft x 102 in Wide x Body, Liftgate S/N: 3ALACXDT2GDHA4391 Usage: 431,154 Mi C/W: Cummins ISB 6 Cylinder 6.7 L 280 hp Engine, 2015 US EPA Label, Requires Diesel Asset located in: Midland, TX Exhaust Fluid, Allison 2500 Automatic 1970 2017 Freightliner M2 106 4x2 Van Truck Transmission, 12000 lb Front Axle, 21000 lb S/N: 3ALACWCY4HDJF0552 Rears, 33000 lb GVWR, 11R22.5, Spring C/W: Cummins ISL 6 Cylinder Diesel 270 hp Suspension, 271 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 in High Body, Liftgate Engine, Requires Diesel Exhaust Fluid, 8157 Engine hrs, Engine Brake, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, Usage: Not Available Asset located in: Lake Worth, TX Aluminum Wheels, 295/75R22.5 Front Tires, 1975 2016 Freightliner M2 106 4x2 Van Truck 275/80R22.5 Rear Tires, Airliner Air Ride S/N: 1FVACWDU2GHGW9627 Suspension, 215 in Wheelbase, MORGAN 18 ft C/W: Cummins ISB 6 Cylinder 6.7 L 200 hp Engine, 2015 US EPA Label, Requires Diesel x 102 in Wide x 97 in High Body, Liftgate Usage: 305,761 Mi Exhaust Fluid, 8376 Engine hrs, Allison 2200 Asset located in: Humble, TX Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 6.14:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Spring Suspension, 272 1971 2017 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT8HDJA1678 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 C/W: Cummins 6 Cylinder Diesel Engine, in High Body, Curbside Door, Liftgate Requires Diesel Exhaust Fluid, Automatic Usage: 294,823 Mi Transmission, 10000 lb Front Axle, 19000 lb Asset located in: Lake Worth, TX Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 316,107 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Lot #	Details	Lot #	Details
1976	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT7GHHG9662 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 374,343 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1980	2020 International MV607 4x2 Van Truck S/N: 3HAEUMML2LL115482 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 552 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 54,274 Mi Notes: ODOMETER REPLACED AT 171,023 MILES -PLEASE SEE INSPECTION REPORT, ACTUAL MILEAGE IS 225,297 Asset located in: Lake Worth, TX
1977	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT6GHHK2059 C/W: Cummins ISB6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8186 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 234 in Wheelbase, Morgan 22 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 170,085 Mi Asset located in: Lake Worth, TX	1981	2019 International MV607 4x2 Van Truck S/N: 3HAEUMML6KL437363 C/W: Cummins B 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, 7555 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 271 in Wheelbase, AMH 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 250,820 Mi Asset located in: Lake Worth, TX
1978	2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT3GDHM9628 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11463 Engine hrs, 6-Speed Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 334,137 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	1982 CHOICI	2020 International MV607LP 4x2 Moving Van Truck S/N: 1HTEWMML1LH870977 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6412 Engine hrs, Allison Automatic Transmission, 9000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 245 /70R19.5, Air Ride Suspension, 187 in Wheelbase, Morgan 16 ft x 102 in Wide x 97 in High Body Usage: 292,284 Mi Asset located in: Lake Worth, TX
1979	2015 Freightliner M2 106 4x2 Van Truck S/N: 1FVACXDT1FHGJ9796 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller F0-6406B Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Spring Suspension, 270 in Wheelbase, wabash 22 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 191,299 Mi Asset located in: Lake Worth, TX	1983	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML5KH382549 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3964 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.57:1 Axle Ratio, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Ball Hitch Usage: 165,232 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1984	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML5KH519554 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 4381 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.29:1 Axle Ratio, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 202,297 Mi	1988	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML8KL382233 C/W: Cummins ISB6.7 6.7 L Diesel Engine, 2019 US EPA Label, 3703 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, Ball Usage: 150,368 Mi Asset located in: Lake Worth, TX
	Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX		2019 International 4300 4x2 Van Truck S/N: 1HTMMMML2KH518412 C/W: Cummins B6.7 220 6.7 L Diesel Engine, 2018 US EPA Label, Automatic Transmission,
1985	1985 2019 International 4300 4x2 Dry Van Van Truck S/N: 1HTMMMML6KH382477 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3654 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DEL Drive Axles, 5,57:1 Axle Ratio		10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Ball Usage: Not Available Asset located in: Lake Worth, TX
		1990 2019 International 4300 4x2 Moving Van S/N: 3HAMMMML7KL383325 C/W: Cummins B6.7 220 6 Cylinder 6.7 L hp Engine, Requires Diesel Exhaust Fluid, Engine hrs, Allison Automatic Transmissi 10000 lb Front Axle, 17500 lb Rears, Meri MS-17-14X-3DFL Drive Axles, 5.57:1 Axle 11783 lb GVWR, 11R22.5 Front Tires, 11F Rear Tires, Air Ride Suspension, 272 in	C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3819 Engine hrs, Allison Automatic Transmission,
1986	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML2KL519280 C/W: Cummins B6.7 220 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, International IROS Air Ride Suspension, 272 in		MS-17-14X-3DFL Drive Axles, 5.57:1 Axle Ratio, 11783 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 156,125 Mi
	Wheelbase, Morgan 26 ft x 96 in Wide x Body, Walk-Up Ramp, Ball Usage: Not Available Asset located in : Lake Worth, TX		E OF 4 - Lot #'s: 1991, 1992, 1993, 1994
CHOIC	F OF 4 - Lot #'s: 1987 1988 1989 1990	1991	2019 International 4300 4x2 Van Truck S/N: 3HAMMMMI 4KI 382553

CHOICE OF 4 - Lot #'s: 1987, 1988, 1989, 1990

1987 2019 International 4300 4x2 Van Truck

S/N: 1HTMMMML1KH382497 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3778 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in High Body, Pintle Hitch Usage: 146,547 Mi

Asset located in: Lake Worth, TX

S/N: 3HAMMML4KL382553 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3570 Engine hrs, Allison 2200 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x Body, Ball Hitch Usage: 165,388 Mi

Asset located in: Lake Worth, TX

1992 2019 International 4300 4x2 Van Truck

S/N: 3HAMMMML0KL382789 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4077 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body Usage: 180,545 Mi

Lot #	Details	Lot #	Details
1993	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML6KH514928 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4766 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.29:1 Axle Ratio, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Walk-Up Ramp, Ball Hitch Usage: 211,781 Mi Asset located in: Lake Worth, TX	1999	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML8KH514655 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4722 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.29:1 Axle Ratio, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 207,720 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW
1994	2019 International 4300 4x2 Van Truck		Asset located in: Lake Worth, TX
СНОІС	S/N: 3HAMMMML3KL382012 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3995 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in High Body, Walk-Up Ramp Usage: 162,399 Mi Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1997, 1998, 1999	2000	2019 International 4300 SBA 4x2 Van Truck S/N: 3HAMMMML3KL559187 C/W: Cummins B6.7 6 Cylinder 6.7 L 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5636 Engine hrs, Allison 2500 5- Speed Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 4.63:1 Axle Ratio, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, SMYRNA TRUCK 26 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 147,079 Mi Asset located in: Lake Worth, TX
		СНОІС	E OF 2 - Lot #'s: 2001, 2002
1997	2019 International 4300 4x2 Van Truck S/N: 1HTMMMMLXKH519808 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4042 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 175,179 Mi Asset located in: Lake Worth, TX 2019 International 4300 4x2 Moving Van Truck S/N: 3HAMMMMLXKL383447	2001	2018 International Durastar 4300 SBA 4x2 Van Truck S/N: 1HTMMMML9JH589637 C/W: Cummins 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 233,934 Mi Asset located in: Humble, TX
	C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine 2018 US EPA Label Requires Diesel	2002	<u>`</u>
	hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4243 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body Usage: 188,842 Mi Asset located in: Lake Worth, TX	2002	2018 International 4300 4x2 Van Truck S/N: 3HAMMMML9JL589552 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8327 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Spring Suspension, 256 in Wheelbase, 26 ft x x 104 in High Body, Liftgate Usage: 262,670 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Lot #	Details	Lot #	Details
2003	2018 International 4300 4x2 Van Truck S/N: 3HAMMMML2JL544906 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in Wide x 109 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,961 Mi Asset located in: Lake Worth, TX	2008	2015 International 4300 4x2 Van Truck S/N: 1HTMMMMLXFH710991 C/W: Cummins 6 Cylinder 6.7 L Diesel 240 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 28 ft x 96 in Wide x Body, Liftgate Usage: 491,297 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
2004	2018 International 4300 4x2 Van Truck S/N: 1HTMMMML6JH350045 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9004 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 275,971 Mi Asset located in: Lake Worth, TX	2010	2015 International Durstar 4300 4x2 Van Truck S/N: 3HAMMMML2FL040069 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN
2005	2017 International 4300 4x2 Van Truck S/N: 1HTMMMML2HH654807 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 6442 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 179,428 Mi Asset located in: Lake Worth, TX 2016 International 4300 4x2 Van Truck		YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 2008 Hino 268 4x2 Van Truck S/N: 5PVNE8JV582S50883 C/W: Hino J08E-TV 6 Cylinder 469 cid Diesel 220 hp Engine, 2007 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 112,668 Mi
	S/N: 3HAMMML4GL740046 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17251 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 260 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 222,929 Mi Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2008 International 4300 4x2 Van Truck S/N: 1HTMMAAL38H572202 C/W: International MaxxForce DT 7.6 L Diesel 225 hp Engine, 2007 US EPA Label, CARB Compliant, 9586 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 226 in Wheelbase, Morgan 26 ft x 102 in Wide x 93 in High Body, Liftgate Usage: 245,473 Mi
2007	2016 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML9GH012776 C/W: Cummins ISB V6 6.7 L 240 hp Engine, 2015 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 15999 lb Rears, 25999 lb GVWR, 295/75R22.5, Supreme 26 ft x 96 in Wide x 102 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 247,400 Mi Asset located in: Lake Worth, TX	2012	Asset located in: Lake Worth, TX 2005 International 4300 SBA 4x2 Van Truck S/N: 1HTMMAAN05H119538 C/W: International D226 6 Cylinder 7.6 L Diesel 225 hp Engine, 2004 US EPA Label, 10254 Engine hrs, Eaton Fuller Manual Transmission, Aluminum Wheels, 295/75R22.5, Spring Suspension, Morgan 26 ft x 102 in Wide x 104 in High Body, Curbside Door, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: 196,863 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2013	2003 International 4300 SBA 4x2 Van Truck S/N: 1HTMMAAM63H583373 C/W: International DT466 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, Aluminum Wheels, 295/75R22.5, Spring Suspension, 256 in Wheelbase, Morgan 24 ft x 102 in Wide x 96 in High Body, Liftgate Usage: 503,203 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	2019	2019 Hino 195 4x2 COE Van Truck S/N: JHHRDM2H6KK007187 C/W: Hino J05E-TP 4 Cylinder Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7270 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 152 in Wheelbase, Morgan 16 ft x 96 in Wide x 91 in High Body, Liftgate Usage: 203,811 Mi Asset located in: Lake Worth, TX
2014	1998 International 4700 4x2 Moving Van Truck	1	
	S/N: 1HTSCABM3WH533169 C/W: International V8 7.3 L Diesel Engine, US EPA Label, Spicer 5-Speed Manual Transmission, Spring Suspension, 188 in Wheelbase, Timpte 16 ft x 96 in Wide x 84 in High Body Usage: 41,973 Mi Asset located in: Lake Worth, TX	2020	CE OF 3 - Lot #'s: 2020, 2021, 2022 2019 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B2KS806624 C/W: GM V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 22
2015	2007 GMC C5500 4x2 Van Truck S/N: 1GDE5C1207F411068 C/W: GM Duramax 6.6 L Diesel Engine, 2006 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR,		/70R19.5, Spring Suspension, 150 in Wheelbase, Morgan 16 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 187,646 Mi Asset located in : Lake Worth, TX
	285/70R19.5, Spring Suspension, 208 in Wheelbase, 18 ft x 96 in Wide x 90 in High Body, Liftgate Usage: 292,010 Mi Notes: **Shelving built in box area** Asset located in: Humble, TX	2021	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W168K7008461 C/W: Isuzu 4HK1TC 4 Cylinder 5.2 L Diesel 210 hp Engine, 2018 US EPA Label, Requires Diese Exhaust Fluid, 6880 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, Steel, 215/85R16, Spring Suspension, 151 in Wheelbase, Morgan 16 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 236,438 Mi Asset located in: Lake Worth, TX
2016	·		
	Transmission, 9480 lb Front Axle, 18000 lb Rears, 25995 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 259,568 Mi Asset located in : Lake Worth, TX		2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W16XK7009739 C/W: Isuzu 4HK1TC 4 Cylinder Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, 215/85R16, Spring
2017	2021 Chevrolet 4500 4x2 COE Van Truck S/N: 54DCDW1D5MS205390 C/W: Isuzu V8 Gasoline Engine, 2021 US EPA Label, 225/70R19.5, Spring Suspension, 176 in		Suspension, 151 in Wheelbase, 16 ft x 96 in Wide x 94 in High Body, Liftgate Usage: 271,219 Mi Asset located in : Lake Worth, TX
	Wheelbase, Morgan 20 ft x 96 in Wide x 91 in High Body, Liftgate Usage: Not Available Asset located in : Lake Worth, TX		2018 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B9JS802729 C/W: V8 6.0 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, Supreme 16 ft x 96 in Wide x 94 in High Body, Liftgate Usage: 105,477 Mi Asset located in: Lake Worth, TX
2018	2018 Chevrolet 4500 COE Van Truck S/N: 54DCDW1B6JS807385 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
2024	2016 Isuzu NPR 4x2 COE Extended Cab Van Truck S/N: 54DC4J1B8GS803916 C/W: Isuzu Gasoline Engine, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Supreme 16 ft x 102 in Wide x 85 in High Body, Curbside Door, Liftgate Usage: 137,402 Mi Asset located in: Lake Worth, TX	2030	2019 Ford E350 4x2 Van Truck S/N: 1FDWE3FS8KDC22914 C/W: Ford 6.8 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, Steel, 225 /75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 78,825 Mi Asset located in: Humble, TX
2025	2012 Mitsubishi Fuso 4x2 COE Van Truck S/N: JL6BNG1A5CK002630 C/W: Fuso F1C 3.0 L Engine, 2011 US EPA Label, Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 15995 lb GVWR, 215 /75R17.5, Spring Suspension, 153 in Wheelbase, 16 ft x 102 in Wide x 94 in High Body, Liftgate Usage: 169,507 Mi	_2031	2019 Ford E350 4x2 Van Truck S/N: 1FDWE3FS4KDC15555 C/W: Gasoline Engine, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, 225/75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 81,416 Mi Asset located in: Lake Worth, TX
	Notes: LOCATED-IN-LAKE WORTH-TX Asset located in: Lake Worth, TX	2038	2015 Ford E-350 4x2 14-Seat Transit Bus S/N: 1FDEE3FS2FDA21995 C/W: Air Conditioner, Automatic Transmission,
2027	2015 Ram 5500 4x2 Van Truck S/N: 3C7WRMDL6FG506015 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 7000 lb Front Axle,		V10 6.8 L Gasoline Engine, 2014 US EPA Label, 225/75R16, Spring Suspension, 156 in Wheelbase Usage: Not Available Asset located in: Lake Worth, TX
	13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, Morgan 16 ft x 96 in Wide x 80 in High Body, Curbside Door, Liftgate Usage: 169,865 Mi Asset located in : Lake Worth, TX	2039	2013 International PC505 4x2 Bus S/N: 5WEASSKP5DH416814 C/W: Air Conditioner, Allison Automatic Transmission, 5483 hrs Carrier Engine, International MaxxForce 7 V8 6.4 L Diesel 260 hp Engine, 2012 US EPA Label, Aluminum
2028	2022 GMC G3500 4x2 Van Truck S/N: 7GZ37TC76NN001010 C/W: GM V8 6.6 L Gasoline Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3838		Outer Whéels, 255/70R22.5, Air Ride Suspension, 305 in Wheelbase Usage: 173,055 Mi Asset located in : Lake Worth, TX
	Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225/75R16 Front Tires, 224/75R16 Rear Tires, Spring Suspension, 176 in Wheelbase, 16 ft x 96 in Wide x 80 in High Body, Curbside Door Usage: 109,545 Mi Asset located in: Lake Worth, TX	2040	2011 BlueBird 4x2 36-Seat School Bus S/N: 1BAKGC5A2CF286372 C/W: Air Conditioner, Automatic Transmission, 11R22.5, Spring Suspension, 275 in Wheelbase Usage: 105,391 Mi Asset located in: Humble, TX
2029	2020 GMC Savana 3500 4x2 Van Truck S/N: 7GZ37TCG8LN010465 C/W: GMC Vortec V8 6.0 L Gasoline Engine, 7655 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75R16, Curbside Door Usage: 150,248 Mi Asset located in: Lake Worth, TX	2041	2012 BlueBird 4x2 47-Seat School Bus S/N: 1BAKGL5A8CF286375 C/W: Air Conditioner, Automatic Transmission, V8 8.1 L Liquefied Natural Gas (LNG) Engine, 2010 US EPA Label, 11R22.5, Spring Suspension, 274 in Wheelbase Usage: 118,477 Mi Asset located in: Humble, TX
2029A	2020 GMC Savana G3500 4x2 Van Truck S/N: 1GD07RFP9L1182263 C/W: V6 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 74 in High Body Usage: 89,341 Mi Notes: TITLE SHOWS NOT ACTUAL MILEAGE Asset located in: Humble, TX	2042	2007 Chevrolet C5500 4x2 26-Seat Transit Bus S/N: 1GBE5V1G67F425251 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, GM V8 8.1 L Gasoline Engine, 2007 US EPA Label, 225/70R19.5, Spring Suspension, 232 in Wheelbase, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 80,972 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2043	2021 Nissan NV200 4x2 Cargo Van S/N: 1N6BF0KY5MN807503 C/W: V6 4.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 3825 lb Front Axle, 5875 lb Rears, 9100 lb GVWR, 245/70R17, Spring Suspension, 146 in Wheelbase, 9 ft x x 50 in High Body Usage: 80,655 Mi Asset located in: Midland, TX 2016 Ford Transit 350 Passenger Van S/N: 1FBZX2ZM3GKA06205 C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch, EQUIPMENT-FROM-A-PRIMORIS-	2049	2019 Ram ProMaster 2500 4x2 Cargo Van S/N: 3C6TRVDG2KE531385 C/W: V6 3.6 L Gasoline 280 hp Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 3.86:1 Axle Ratio, 8900 lb GVWR, 225/75R16, Spring Suspension, 159 in Wheelbase, 11 ft x 80 in Wide x 76 in High Body, Curbside Door Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX	2050	PROCESS TITLE Asset located in: Lake Worth, TX 2019 Ram ProMaster 2500 4x2 Cargo Van S/N: 3C6TRVDGXKE557829 C/W: V6 3.6 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front
2045	2014 Freightliner Sprinter 3500 4x2 Van Truck S/N: WDPPF4CC7E9564671 C/W: V6 3.0 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 4080 lb Front Axle, 7720 lb Rears, 11030 lb GVWR, 215/85R16, Spring Suspension, 16 ft x 86 in Wide x 78 in High Body, Curbside Door, Walk- Up Ramp Usage: 313,155 Mi	2051	Axle, 5291 lb Rears, 8900.0 lb GVWR, 225 /75R16, Spring Suspension, 159 in Wheelbase, 11 ft x x 76 in High Body, Curbside Door Usage: 44,182 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
2046	Asset located in: Lake Worth, TX 2024 Chevrolet Express 2500 Cargo Van S/N: 1GCWGAF70R1101434 C/W: V8 6.6 L Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera, Towing Hitch Usage: 131 Mi Asset located in: Lake Worth, TX		2019 GMC Savana 1500 Cargo Van S/N: 1GTW7BFP3K1277096 C/W: V6 4.3 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 91,916 Hr Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
2047	2016 Ford Transit 250 4x2 Cargo Van S/N: 1FTYR2ZM4GKA77642 C/W: Ford V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5515 lb Rears, 9000 lb GVWR, 235 /65R16, Spring Suspension, 138 in Wheelbase, 9 ft x 78 in Wide x 56 in High Body Usage: 214,134 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED; DOCUMENTS TO PROCESS TITLE; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	2052 CHOIC	2007 Chevrolet 2500 Express 4x2 Cargo Van S/N: 1GCGG25V471223513 C/W: Chevy V8 4.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245 /75R16, Spring Suspension, 139 in Wheelbase, 9 ft x 72 in Wide x 54 in High Body, Curbside Door Usage: 135,450 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
2048	Asset located in: Humble, TX 2020 Ram Promaster Cargo Van S/N: ZFBHRFAB3L6R54595 Usage: Not Available Asset located in: Lake Worth, TX	2053	2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E25M1496971 C/W: 4 Cylinder 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 215 /55R16, 121 in Wheelbase, 6 ft x x 44 in High Body Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
2054	2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E27M1496972 C/W: ford 4 Cylinder 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 205/55R16, 121 in Wheelbase, 6 ft x 72 in Wide x 44 in High Body Usage: 46,847 Mi Asset located in: Midland, TX	5002	2024 Raytree RMC72 72 in Skid Steer Brush Cutter (Unused) S/N: C20241007112 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
2055	2016 Ford Transit 150 4x2 Cargo Van S/N: 1FTYE1YM9GKB48843 C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5070 lb Rears, 8600 lb GVWR, 235/65R16,	5003	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Spring Suspension, 132 in Wheelbase, 9 ft x 96 in Wide x 55 in High Body, Curbside Door Usage: 144,833 Mi Asset located in: Lake Worth, TX	5004	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
2056	2020 Mercedes-Benz 135 WB 4x2 Cargo Van S/N: W1YV0CEY3L3688564 C/W: Mercedes-Benz 2.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 3307 lb Front Axle, 3307 lb Rears, 6614 lb GVWR, 225/55R17, Spring Suspension, 136 in Wheelbase Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	5005	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5006	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5000	PROCESS TITLE Asset located in: Lake Worth, TX 2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: HL00249 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5007	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5008	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5009	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5001	Asset located in: Lake Worth, TX 2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	_5010	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5011	2023 Mower King SSRC 72 in Skid Steer Brush Cutter S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5012	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC20240919 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5013	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Wolverine BC-13-72W 72 in Skid Steer	5018	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	Brush Cutter (Unused) S/N: Not Available		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5019	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5020	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5015	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5021	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5022	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5023	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5016	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5024	ASSET IOCATED III: Lake Worth, TX All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2021 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC21092604 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5026	Wolverine 70 in Pallet Skid Steer Brush Cutter S/N: Not Available
5017	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
5027	2024 Suihe SSBC 66 in Skid Steer Brush Cutter (Unused) S/N: 001602498 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5033	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5034	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409111
5028	2024 Suihe SSBC 0 ft 66 in Skid Steer Brush Cutter (Unused) S/N: 001602505 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5035	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5000	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409110 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5029	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Asset located in: Lake Worth, TX
		5036	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5037	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5030	Asset located in: Lake Worth, TX 2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202409115	5038	JCT 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Llagger Net Aveilable	5039	Bobcat 84 in Skid Steer Angle Broom S/N: 231412786 Usage: Not Available Asset located in: Lake Worth, TX
5031	Asset located in: Lake Worth, TX 2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202409114 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2023 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW02312 Usage: Not Available Asset located in: Lake Worth, TX	5040	2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5041	2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5048	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202409560 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Raytree RMH680 Skid Steer Breaker (Unused) S/N: HH20241012180
5042	2024 Wolverine PBS-11-72W 72 in Skid Steer Sweeper (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: ZW00289 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5050	2024 Wolverine CB-11-750F Skid Steer Breaker (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5043	2024 Wolverine MBS-11-48W 48 in Mini Skid Steer Sweeper (Unused) S/N: ZW00327		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
			Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5051	2024 Jisan JSB400SL Skid Steer Breaker (Unused) S/N: 2404298 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5044	2014 Bobcat 144 Skid Steer Sweeper S/N: 714428587 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX 2024 TOFT TOFT750 Skid Steer Post Driver	5052	2024 Jisan JSB400SL Skid Steer Breaker (Unused) S/N: 2404295 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	(Unused) S/N: JW43Z5685		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5053	2024 Elephant EPB400SL Skid Steer Breaker (Unused)
5046	2024 TOFT TOFT680 Skid Steer Post Driver (Unused) S/N: JW40Z17058 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 2406091 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5047	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202406543 Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5054	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: CP2406092 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5062	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409144 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5055	2024 Trojan TH35SSL Skid Steer Breaker (Unused) S/N: SB30YOM20247065 Usage: Not Available Asset located in: Lake Worth, TX	5063	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00017 Usage: Not Available Asset located in: Lake Worth, TX
5056	Mini Skid Steer Breaker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5064	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00018 Usage: Not Available Asset located in: Lake Worth, TX
5057	2024 TOFT TOFT750 Skid Steer Breaker (Unused) S/N: JW43Z5799 Usage: Not Available Asset located in: Lake Worth, TX	5065	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5058	2024 TOFT TOFT680 Skid Steer Breaker (Unused) S/N: JW40Z17265 Usage: Not Available Asset located in: Lake Worth, TX 2024 Handy HPD680 Skid Steer Post Driver		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	(Unused)		Asset located in: Lake Worth, TX
	S/N: PD202409143 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5066	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5060	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409145 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241009192
5061	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409142 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5068	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241012196 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5075	2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused) S/N: VR202409472 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HVR76 72 in Skid Steer Vibratory
	Asset located in: Lake Worth, TX		Roller (Unused) S/N: VR202409474
5069	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241012195 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE	5077	<u> </u>
	PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5077	2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused) S/N: VR202409473 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5070	2024 Jisan JSB400SLT Skid Steer Post Driver (Unused) S/N: CP2407183		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
			Asset located in: Lake Worth, TX
5071	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhonor TP2-13-08D Skid Steer Post	5078	2024 Raytree RMVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR20241012184 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Puller (Unused) S/N: HL00381 Usage: Not Available		Asset located in: Lake Worth, TX
		5079	2024 Suihe SSVR-72 72 in Skid Steer Vibratory
5072	Asset located in: Lake Worth, TX 2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00384 Usage: Not Available Asset located in: Lake Worth, TX		Roller (Unused) S/N: 001300876 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5073	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00382		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Usage: Not Available		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5080	2024 Wolverine VR-11-66W 66 in Skid Steer Vibratory Roller (Unused)
5074	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00383 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5081	TMC 72 in Skid Steer Vibratory Roller S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5087	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES	
5082	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused) S/N: T20241008159 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	-5088	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY A	ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5083	2024 Handy HST48 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: 8 In Dirt & Rock Chain, Crumbling Shoe Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5084	2024 Handy HST48 48 in Skid Steer Trencher (Unused)		Asset located in: Lake Worth, TX	
	S/N: TR202409613 C/W: 8 In Dirt & Rock Chain, Crumbling Shoe Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5089	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
5085	2024 Suihe SST-1000/200 Skid Steer Trencher (Unused) S/N: 001702343 C/W: Crumbing Shoe THE PRODUCT IMAGES	5090	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		5090 2024 Wolverine TCR-12-48H 48 in S Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUC' SHOWN ARE FOR ILLUSTRATION P ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL Usage: Not Available	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5086	2024 Suihe SST-1000/200 Skid Steer Trencher (Unused)		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	S/N: 001702342 C/W: Crumbing Shoe THE PRODUCT IMAGES		Asset located in: Lake Worth, TX	
	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5091	2024 Handy HSD96 96 in 6 Way Skid Steer Dozer (Unused) S/N: SD202409302 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5092	2024 Handy HSD96 96 in 6 Way dozer Skid Steer Dozer (Unused) S/N: SD202409300 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HSD96 96 in 6 Way dozer Skid	5097	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused) S/N: 031789880 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
0070	Steer Dozer (Unused) S/N: SD202409301 Usage: Not Available	5098	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Wolverine DB-15-84W 84 in Angle Skid
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	0030	Steer Dozer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5094	2024 Raytree RSWD96 94 in Six Way Skid Steer Dozer (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	S/N: SW20241012042 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5099	All-Star 72 in Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5100	Mid-State 72 in Skid Steer Dozer (Unused)
5095	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 031789472 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5101	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202409595 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5096	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer	5102	2024 Handy HSGB96 96 in Skid Steer Grader
3090	Dozer (Unused) S/N: 031789296 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		(Unused) S/N: GB202409594 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5103	2024 Handy HGB86 96 in Skid Steer Grader (Unused) S/N: GB86202409217 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5104 5105	2024 Handy HGB86 96 in Heavy Duty Skid Steer Grader (Unused) S/N: GB86202409216 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused)	5111	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available Usage: Not Available	5112	Asset located in: Lake Worth, TX 2024 Wolverine TL-12-72W 72 in Skid Steer
5106	Asset located in: Lake Worth, TX 72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5107	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5113	2024 Suihe SSTL 72 in Skid Steer Tiller
5108	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Wolverine TL-12-72W 72 in Skid Steer	(Unused) S/N: 002402687 C/W: THE PRODUCT IMAGES SHOWN AR FOR ILLUSTRATION PURPOSES ONLY AN MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN AF FOR ILLUSTRATION PURPOSES ONLY AN MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5114 2024 Suihe SSTL 72 in Skid Steer Tiller (Unused) S/N: 002402685 C/W: THE PRODUCT IMAGES SHOWN AF FOR ILLUSTRATION PURPOSES ONLY AN	S/N: 002402687 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: 002402685 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5110	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5115	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5116	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5117	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5124	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409391 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Net Applied In	
5118	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5119	2024 Handy SSA18 Skid Steer Auger (Unused)	Ī	Asset located in: Lake Worth, TX	
	S/N: SSA2409392 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5125	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
5120	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409390 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	Usage: Not Available		Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR	
	Asset located in: Lake Worth, TX			
5121	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	5127	2024 Wolverine ADB-13-1218R Skid Steer	
5122	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		PRODÙCT IMAĞÉS SHOWÑ ARE FO ILLUSTRATION PURPOSES ONLY A NOT BE AN EXACT REPRESENTATI ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES ON MAY NOT BE AN EXACT REPRESEN	S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5123	2024 Handy SSA18 Skid Steer Auger (Unused)	1	Asset located in: Lake Worth, TX	
	S/N: SSA2409389 C/W: (1) 10 in bit, (1) 12 in bit, (1) 18 in bit, one crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Accel located in. Lake Worth, TA	

Lot #	Details	Lot #	Details
5128	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TY	5133	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503502 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5129	Asset located in: Lake Worth, TX 2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20241012230 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	_5134	Belltec LC350 Skid Steer Auger (Unused) S/N: L09284 C/W: Quick Attach 2 in Hex Head Auger Usage: Not Available Asset located in: Lake Worth, TX
		5135	2018 Bobcat 15C Skid Steer Auger S/N: 944261257 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
5130	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20241012229 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5136	16 in Mini Skid Steer Auger (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5137	Quantity of (3) Mini Skid Steer Augers (Unused) S/N: Not Available C/W: (1) 16 in, (1) 12 in, (1) 8 in Bits Usage: Not Available Asset located in: Lake Worth, TX
5131	S/N: 002503461 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5138	Pengo 10-2500 Auger Bit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
		5139	9 2024 Raytree RMSC78 72 in Skid Steer Soil Conditioner S/N: SC20241010053 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
5132	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503471 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Lake Worth, TX
		5140	Level Best LBSS6 72 in Skid Steer Laser Grading Box Blade S/N: 1187 Usage: Not Available Asset located in: Lake Worth, TX
		5141	Raytree 28 in Skid Steer Hyd Pole Jack (Unused) S/N: 20231025031 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5142	2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409146 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HBC72 Concrete Crusher (Unused)	5149 5150 5151	5149 2024 Handy HSRC12 Rotating Skid Steer Pole Clamp (Unused) S/N: RC202409627 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: CC202409147 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5144	2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: RP202409465 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5145	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20241010172 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5152	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhonor FW-13-15000G 15000 lb Skid Steer Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5146	2024 Landhonor CC-11-08V 24 in Skid Steer Concrete Crusher (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5153	2024 Industrias America Post/Tree Puller (Unused) S/N: HPOST202421670 Usage: Not Available Asset located in: Lake Worth, TX
5147	· · · · · · · · · · · · · · · · · · ·	5154 5155	2024 Industrias America Post/Tree Puller (Unused) S/N: POST202421749 Usage: Not Available Asset located in: Lake Worth, TX 2024 Industrias America Post/Tree Puller (Unused) S/N: POST202421748
5148	2024 Handy HSRC12 Rotating Skid Steer Pole Clamp (Unused) S/N: RC202409626 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5156	Usage: Not Available Asset located in: Lake Worth, TX All-Star Skid Steer Tree Shear (Unused)
			S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
		5157	All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5158	All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5165	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: HL01192 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5159	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5160	Kubota PS2086 84 in Skid Steer Grain Planter S/N: 1064217K C/W: 3 Pt Hitch Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5166	2024 Landhonor PR-12-72W 72 in Skid Steer
5161	2024 Handy HSNC78 72 in Skid Steer Power Rake (Unused) S/N: SC202409110 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Power Rake (Unused) S/N: HL01193 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
5162	2024 Handy HSNC78 72 in Skid Steer Power		Asset located in: Lake Worth, TX
	Rake (Unused) S/N: SC202409112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5167	2024 Raytree RTSG30 31 in Transverse Skid Steer Stump Grinder (Unused) S/N: TS20241012241 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5163	2024 Handy HSNC78 72 in Skid Steer Power		Asset located in: Lake Worth, TX
	Rake (Unused) S/N: SC202409111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5168	2024 Raytree RMSG29 29 in Skid Steer Stump Grinder (Unused) S/N: SG20241010315 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5164	2024 Landhonor PR-12-72W 72 in Skid Steer		Asset located in: Lake Worth, TX
	Power Rake (Unused) S/N: HL01191 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5169	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409926 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5170	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409924 Usage: Not Available
			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5171	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409925 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5179	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012450 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5172	Quantity of (2) 2024 Landhonor BH-11-06H Big Arm Skid Steer Backhoe (Unused) S/N: Not Available C/W: 18 In Bucket, One Crate Usage: Not Available Asset located in: Lake Worth, TX	5180	Mulcher (Unused) S/N: DRM20241012447 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
5173	All-Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX	5181	Usage: Not Available Asset located in: Lake Worth, TX 2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused)
5174	All Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX		S/N: DRM20241008440 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5175	Bobcat 709FDS Skid Steer Backhoe S/N: 270020062 C/W: NO BUCKET Usage: Not Available Asset located in: Lake Worth, TX	5182	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409470 Usage: Not Available
5176	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused) S/N: HM20241012049 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5177	2024 Raytree RMDM72A 72 in Skid Steer Mulcher (Unused) S/N: HM20241009048 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409469 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5178	Asset located in: Lake Worth, TX 2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012445 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5184	2024 Handy HSDM70 Skid Steer Mulcher (Unused) S/N: DM202409332 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		'5185	2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124060901E Usage: Not Available Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
5186	2024 Raytree RMDM70 60 in Skid Steer Mulcher (Unused) S/N: DM20241012194 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5194	All-Star 72 In Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5187	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Raytree RMBD50 Drum Skid Steer	5195	2024 Landhonor RG-11-5000G Rotating Skid Steer Grapple (Unused) S/N: HL00372 Usage: Not Available
3107	Mulcher (Unused)		Asset located in: Lake Worth, TX
	S/N: LM20241009067 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5196	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5197	All-Star 48 in Rock W/Teeth Skid Steer Grapple
5188	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241010069 C/W: THE PRODUCT IMAGES SHOWN ARE		Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5198	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5189	2024 Raytree RMBD50 Drum Skid Steer	5199	<u> </u>
	Mulcher (Unused) S/N: LM20241009068 C/W: THE PRODUCT IMAGES SHOWN ARE		72 in Skid Steer Grapple Bucket S/N: Not Available
			Usage: Not Available
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Kit Containers 48 in Skeleton Mini Skid Steer Grapple (Unused) S/N: B14E1606
5190	All-Star 78 in E-Series Rock Skid Steer Grapple		Usage: Not Available
	Bucket (Unused) S/N: Not Available Usage: Not Available		Asset located in: Lake Worth, TX
		5201	All-Star 80 in Root Skid Steer Grapple (Unused) S/N: Not Available
	Asset located in: Lake Worth, TX		Usage: Not Available
5191	All-Star 78 in Skeleton Skid Steer Grapple	5000	Asset located in: Lake Worth, TX
	Bucket (Unused) S/N: Not Available	5202	All-Star 78 In E-Series Root Skid Steer Grapple (Unused)
	Usage: Not Available		S/N: Not Available
	Asset located in: Lake Worth, TX	4	Usage: Not Available Asset located in: Lake Worth, TX
5192		5203	All-Star 78 In E-Series Root Skid Steer Grapple
	S/N: Not Available	3203	(Unused)
	Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available
5193	<u> </u>	\dashv	Asset located in: Lake Worth, TX
J 1 7 J	All-Star 72 In E-Series Rock Skid Steer Grapple Bucket (Unused)	5204	All Star 78 in E-Series Root Skid Steer Grapple
	S/N: Not Available		(Unused)
	Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available
		1	Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5205	All Star 74 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5216	36 in Q/C Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
-	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5206	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5217	All-Star 40 in Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5207	All-Star 72 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5218	All-Star 40 in Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5208	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5219	All-Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5209	All Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5220	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5210	All-Star E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5211	All Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5221	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe SSRGB-82 82 in Skid Steer Grapple
5212	All-Star 68 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5213	All-Star 68 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	J	<u>`</u>
5214	Mid-State 60 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5222	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5215	All Star 48 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5223	All-Star 80 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5231	Raptor 72 in Skid Steer Grapple Bucket (Unused) S/N: 23400249 Usage: Not Available Asset located in: Lake Worth, TX
5224	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5232	All-Star 68 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5225	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available	5233	Cat 66 in Skid Steer Grapple Bucket S/N: A4164CB50022 Usage: Not Available Asset located in: Lake Worth, TX
5226	Asset located in: Lake Worth, TX All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available	5234	30 in Mini Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5227	Asset located in: Lake Worth, TX All-Star 74 in Skid Steer Grapple Bucket (Unused) S/N: Not Available	5235	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
<u></u> 5228	Usage: Not Available Asset located in: Lake Worth, TX All Star 72 in E-Series Skid Steer Grapple	5236	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available
	Bucket (Unused) S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
5229	Asset located in: Lake Worth, TX 2024 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: Not Available	5237	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5238	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5239	2024 Suihe SSRGB-72 72 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available
5230	Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5240	All-Star 68 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5241	All Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5248	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808738 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5242	All-Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5243	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	5249	Asset located in: Lake Worth, TX 2024 Suihe SSR-78 78 in Skid Steer Root Rake
5244	Asset located in: Lake Worth, TX All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available		(Unused) S/N: 001808746 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5245	Asset located in: Lake Worth, TX All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5246	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808766 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5250	Asset located in: Lake Worth, TX All-Star 78 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5251	All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5247	Asset located in: Lake Worth, TX 2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808741 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5253 5254 5256	- 5252	All-Star 78 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5253	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5254	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5255	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5256	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5257	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5269	84 in Skid Steer Ripper Scarifier (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5258	Mid-State 68 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5270	2024 Handy HVSB72 72 in Screening Skid Steer Bucket (Unused) S/N: VSB202409688 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5259	Mid-State 68 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5260	Asset located in: Lake Worth, TX All-Star 68 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5271	2024 Handy HVSB72 72 in Screening Skid Steer Bucket (Unused) S/N: VSB202409689 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5261	Mid-State 60 In E-Series Skid Steer Root Rake (Unused)		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5272	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: Not Available
5262	Mid-State 60 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5272	2024 Skyway WBCT-4IN1 Backhoe Loader
5263	Mid-State 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5273	Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5264	All-Star 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5265	ASSET located in: Lake Worth, TX All-Star 68 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5274	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5266	All-Star 72 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5275	2024 Raytree RMVB78F 70 in (Unused)
5267	All-Star 60 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: SB20241009346 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5268	All-Star 84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

			1 450 210 01 307
Lot #	Details	Lot #	Details
5276	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241009347 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5286	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5287	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5277	· · · · · · · · · · · · · · · · · · ·		
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5288	2024 Kit Containers QT-DB-S78 78 in Skid Steer Bucket (Unused) S/N: B28J1613 Usage: Not Available Asset located in: Lake Worth, TX
5278 	Mid-State General Purpose 84 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Mid-State General Purpose 80 in Skid Steer	5289	Teran BKT26278 78 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 1220 C/W: 0.5m3 with 8HD Tips for CAT 226 - 299 Usage: Not Available Asset located in: Lake Worth, TX
5280	Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Mid-State 84 in Low Profile Skid Steer Bucket	5290	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5291	Kit Containers 78 in Skid Steer Bucket (Unused) S/N: B26J1610 Usage: Not Available Asset located in: Lake Worth, TX
5281	Mid-State 84 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5292	78 in General Purpose Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5282	All-Star 80 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5293	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5283	All-Star 80 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5294	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5284	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5295	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5285	Mid-State General Purpose 78 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5296	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5306	Teran BKT26272 72 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 3142 C/W: 0.45m3 with 8 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5307	Mid-State 72 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available
5297	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused) S/N: Not Available		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5308	All Star 72 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5309	All Star 68 in General Purpose Skid Steer
5298	Mid-State 74 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	5309	Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5310	All-Star 68 in General Purpose Skid Steer
5299	Mid-State 74 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	66.6	Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5300	72 in Low Pro W/Teeth Skid Steer Bucket	5311	Mid-State 68 In Low Pro w/Teeth Skid Steer
3300	(Unused) S/N: Not Available		Bucket (Unused) S/N: Not Available Usage: Not Available
	Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5301	72 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5312	Mid-State 68 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5302	72 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5313	2018 Takeuchi 68" Smooth Skid Steer Bucket S/N: VG1708386 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
5303	Mid-State General Purpose 72 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5315	2024 Kit Containers QT-DB-T66 66 in Skid Steer Bucket (Unused) S/N: B23J1617 Usage: Not Available Asset located in: Lake Worth, TX
5304	72 in General Purpose Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5316	2024 Kit Containers QT-DB-S66 66 in Skid Steer Bucket (Unused) S/N: B23J1632 Usage: Not Available
5305	2020 Bobcat 7326129/Teeth Skid Steer Bucket S/N: 004164 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5317	Mid-State 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5328	Mid-State 78 In Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5318	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5329	All-Star 74 In Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5319	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5330	Mid-State 80 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5320	Teran BKT26260 60 in C Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 3119 C/W: 0.35m3 with 7 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Lake Worth, TX	5331	Mid-State 68 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5321	Bobcat 80 in General Purpose Skid Steer Bucket S/N: 6726344 Usage: Not Available	5332 	All Star 68 in Snow & Litter Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5322	Asset located in: Lake Worth, TX Arrow 2307206BUN 74 in Skid Steer Bucket S/N: YB12397 Usage: Not Available Asset located in: Lake Worth, TX	5333	All-Star 80 In Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5323	2018 Bobcat 68 67 in General Purpose Skid Steer Bucket S/N: BS77771 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	5334	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: With Teeth Usage: Not Available Asset located in: Lake Worth, TX All-Star 84 in Rock W/Teeth Skid Steer Bucket
5324	Asset located in: Oklahoma City, OK 67 in Skid Steer Bucket S/N: Not Available Usage: Not Available		(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5325	Asset located in: Lake Worth, TX 61 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5336	All-Star 84 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5326	2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: B30J1625 Usage: Not Available	5337	Kit Containers 82 in Rock Skid Steer Bucket (Unused) S/N: B22J1604 Usage: Not Available Asset located in: Lake Worth, TX
5327	Asset located in: Lake Worth, TX 2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: B29J1617 Usage: Not Available Asset located in: Lake Worth, TX	5338	All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5339	All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5347	Kit Containers 76 in Skeleton Skid Steer Bucket (Unused) S/N: B16J1620 Usage: Not Available Asset located in: Lake Worth, TX	
5340	Kit Containers 72 in Rock Skid Steer Bucket (Unused) S/N: B21J1615 Usage: Not Available Asset located in: Lake Worth, TX	5348	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5341	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5349	2024 Landhonor RB-14-72W 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5342	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWI FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTA	THE ACTUAL PRODUCT
5343	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available	
5344	2024 Landhonor RB-14-84W 84 in Skeleton	1	Usage: Not Available Asset located in : Lake Worth, TX	
	Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5351	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5352	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5345	2024 Landhonor RB-14-78W 78 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5353 5354	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5346	Asset located in: Lake Worth, TX Kit Containers 76 in Skeleton Skid Steer Bucket (Unused) S/N: B17J1620			
	Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
5355	2024 Landhonor RB-14-66W 66 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5362	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5356	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5363	2024 Suihe SSM 56 in Skid Steer Concrete Mixer (Unused) S/N: 008000909 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5357	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5358	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5364	Asset located in: Lake Worth, TX 2024 Kit Containers 2YFT-SST 5 ft 7 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 7 in Long x 4 ft 7 in Wide x 3 ft 10 in
5359	2024 Kit Containers QT-TS-40 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available		High Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers 2YFT-SST 5 ft 6 in Self-
5360	Asset located in: Lake Worth, TX 2024 Kit Containers QT-RD 36 in Skeleton Stump Skid Steer Bucket (Unused) S/N: B28J1958 Usage: Not Available Asset located in: Lake Worth, TX		Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in: Lake Worth, TX
5361	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5366	2024 Kit Containers 1.5YFT-SST Skid Steer Dump Hopper (Unused) S/N: B29E1207 Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	3307	2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5368	2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: 005500748 C/W: THE PRODUCT IMAGES SHOWN ARE	5375	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5376	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5377	2024 Handy HSP24 24 in Skid Steer Planer (Unused) S/N: SP202409130
5369	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5370	42 in Mini Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5378	Asset located in: Lake Worth, TX 2024 Handy HSP24 Skid Steer Planer (Unused) S/N: SP202404110 Usage: Not Available
5371	2024 Handy HLS35 Skid Steer Log Splitter (Unused)		Notes: . Asset located in: Lake Worth, TX
	S/N: LS202409282 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Landhonor VPC-11-72W 72 in Skid Steer Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5372	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202409283 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5380	2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409139
5373	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202409281 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5381	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409138
5374	2024 Raytree RMLS18T 18 ton Skid Steer Log Splitter (Unused) S/N: LS20241012044 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5382	2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409137 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5390	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409301 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5383	2024 Kit Containers QT-RR-70 70 in Skid Steer Ripper Scarifier (Unused) S/N: B24J1305 Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409297 C/W: Fork Positioner Usage: Not Available
5384	84 in Skid Steer Ripper Scarifier (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5385	2024 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5392	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409299 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5393	2024 Handy HF2T 48 in Skid Steer Forks
5386 	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers QT-TB-60 Skid Steer Boom		(Unused) S/N: HF202409300 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	(Unused) S/N: Not Available		Asset located in: Lake Worth, TX
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5394	2024 Handy HF2T 48 in Skid Steer Forks (Unused)
5388	2024 Landhonor HRB-11-127A Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00018 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available Asset located in: Lake Worth, TX		S/N: HF202409298 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5389	2024 Landhonor HRB-11-127A Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00017 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available Asset located in: Lake Worth, TX	5395	Quantity of (4) 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: (4) Universal Adapter Plates, One Crate Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5396	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5402	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX
		5403	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5404	Handy HSRF48 48 in Rotating Skid Steer Forks (Unused)
5397	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available		S/N: RF202401136 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5405	2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5406	2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
5398	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Asset located in: Lake Worth, TX
		5407	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5408	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
5399	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5409	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5410	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5411	2024 Kit Containers QT-45-FF-42 42 in Skid
5400	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available		Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5412	2024 Kit Containers QT-45-FF-42 42 in Skid
5401	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX		Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5413	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5426	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5414	Asset located in: Lake Worth, TX 2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available	<u> </u>	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
 5415	Usage: Not Available Asset located in: Lake Worth, TX All Stor 49 in Skid Stort Forks (Upwood)	5428	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
5 4 15	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5429	Asset located in: Lake Worth, TX Land Pride 48 in Skid Steer Forks
5416	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available		S/N: 999569 Usage: Not Available Asset located in : Lake Worth, TX
5417	Asset located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available	5430	Trojan SPF15 48 in Skid Steer Forks (Unused) S/N: 124438 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5431	48 in Skid Steer Forks S/N: Not Available
5418	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
5419	Asset located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available	5432	38 in Skid Steer Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5433	All Star Skid Steer Fork Frame (Unused) S/N: Not Available
5420	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
 5421	Asset located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused)	5434	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5435	Asset located in: Lake Worth, TX Skid Steer Fork Frame (Unused)
5422	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
E422	Usage: Not Available Asset located in: Lake Worth, TX All Stor 49 in Skid Story Forks (Upwood)	5436	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available
5423	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5437	Asset located in: Lake Worth, TX 48 in Skid Steer Fork Frame (Unused)
5424	Asset located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5438	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available
5425	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5439	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5451	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5440	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5441	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5442	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5452 	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear Frame (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5443	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5444	All-Star Skid Steer Fork Frame (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available Usage: Not Available		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5453	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused)
5445	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5446	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5447	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available	5454	Asset located in: Lake Worth, TX 2024 Landhonor BS-12-2500G 45 in Skid Ste Bale Spear (Unused)
5448	Asset located in: Lake Worth, TX All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5449	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5450	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5455	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5465	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5456	All-Star 44 in Skid Steer Bale Spear (Unused)	5466	32 in Skid Steer Tree Spade (Unused)
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5457	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5467	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5458	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5468	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5459	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5469	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5460	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5470	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5461	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5471	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
5462	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5472	2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5463	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5464	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5473	2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5480	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5474	2024 Landhonor RP-12-72W 72 in Skid Steer	5481	2024 Landhonor UHA-16-3000G 2 in Skid Steer
	Rock Picker (Unused) S/N: HL00018 Usage: Not Available Asset located in: Lake Worth, TX	5481	Hitch Receiver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5475	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00017 Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5476	2024 Landhonor DPC-21-13W Skid Steer Pole		Asset located in: Lake Worth, TX
	Clamp (Unused) S/N: HL00009 Usage: Not Available Asset located in: Lake Worth, TX	5482	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5477	2024 Kit Containers QT-TM Receiver Hitch (Unused) S/N: B06J1903 Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5478	2024 Kit Containers QT-TM Skid Steer Receiver Hitch (Unused) S/N: B06J1913		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5479	Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor UHA-16-3000G 2 in Skid Steer	5483	All-Star Receiver Hitch (Unused) S/N: Not Available Usage: Not Available
	Hitch Receiver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5484	Asset located in: Lake Worth, TX All-Star Receiver Hitch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5485	Titan 47 in ADJUSTABLE INDUSTRIAL SKID STEER JIB BOOM CRANE - Fits Skid Steer/CTL S/N: Not Available Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	5486	Set of Grouser Steel Skid Steer Tracks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5487	Set of McLaren Steel Skid Steer Tracks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5488	Set of OTT Tracks for Skid Steer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5497	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available	
5489	2024 Handy HSTS12 Skid Steer Tree Shear (Unused) S/N: TS202409117 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5498 5499 5500	Asset located in: Lake Worth, TX Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) All-Star Skid Steer Attachment	
5490	Asset located in: Lake Worth, TX Quantity of (4) All-Star Quick Attach Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available		Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) All-Star Skid Steer Attachment	
5491	Asset located in: Lake Worth, TX Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate (Unused)		Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX	5501	2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused) S/N: DM20241009163 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5492	Quantity of (10) 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX	5502	Att	Quantity of (9) Agrotek Mini Excavator Attachments (Unused) S/N: 12EXATA24042002A
5493	Quantity of 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available		C/W: (3) Buckets, Quick Coupler, Grapple, Auger, Two Bits, Rake, Ripper, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in : Lake Worth, TX	5503	All-Star E35 40 in Q/C Excavator Brush Cutter (Unused)	
5494	Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	
	S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX	5504	All-Star 40 in Excavator Brush Cutter (Unused) S/N: Not Available C/W: No Coupler Usage: Not Available	
5495	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5505	Asset located in: Lake Worth, TX Paladin Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5496	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5506	Cat Misc. attachment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
5507	Quantity of (2) Pallets of Okada Padding Bucket Screens S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5515	John Deere 210 S/N: 1804110013 C/W: 75 mm Diameter Pins, 470 mm Center Pin Boss to Center of Pin Boss, 310 mm Insi to Inside Pin Boss Spacing, 16 in & 20 in Aug Bits
5508	Quantity of (9) 2024 AGT 12EX-ATA Mini Excavator Attachment (Unused) S/N: 12EX-ATA24042002A C/W: Quick Coupler, Rake, Ripper, Grapple,		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
	Auger, 12 in Auger Bit, 8 in Bucket, 20 in Bucket, 32 in Bucket Usage: Not Available Notes: Asset located in: Lake Worth, TX	5516	2019 Stanley MB/XP4035 Hydraulic Breaker S/N: XP40350054 C/W: 8000 lb class, 5.6 in Tool / Chisel, Fits Excavators Usage: Not Available
5509	Contech 2200 Excavator Plate Compactor S/N: 7800220A1191132 Usage: Not Available Asset located in: Lake Worth, TX	5517	Asset located in: Lake Worth, TX 2024 JESON HM3300 Hydraulic Breaker (Unused) S/N: JQ HM 012
5510	Volvo ARM-EC380E-9FT6IN BARE Excavator stick S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5518	5518 2024 Jisan JSB3200B Hydraulic Breaker (Unused) S/N: CP2404445
5511	KBKC 72 in Excavator Rake - Fits Cat 320 (Unused) S/N: RR240122 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5512	KBKC 48 in Excavator Rake - Fits Cat 305-306 (Unused) S/N: RR240103 Usage: Not Available Asset located in: Lake Worth, TX	5519	Asset located in: Lake Worth, TX 2024 JESON HM3200 Hydraulic Breaker (Unused) S/N: JQ HM 011 Usage: Not Available Asset located in: Lake Worth, TX
5513	Excavator Ripper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5520	2024 JESON HM3150 Hydraulic Breaker (Unused) S/N: JQ HM 015 Usage: Not Available
5514	2018 John Deere Excavator Auger - Fits John Deere 310SJ S/N: Not Available C/W: 45 mm Diameter Pins, 340 mm Center of Pin Boss to Center of Pin Boss, 205 mm Inside to Inside Pin Boss Spacing, 10 in & 12 in Auger Bits Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK		Asset located in: Lake Worth, TX
		5521	2024 JQ POWER JQB3000STB Hydraulic Breaker (Unused) S/N: 814075918 Usage: Not Available Asset located in: Lake Worth, TX
		5522	2024 JESON HM3070 Hydraulic Breaker (Unused) S/N: JQ HM 014 Usage: Not Available Asset located in: Lake Worth, TX
		5523	2024 JESON HM3070SL Skid Steer Breaker (Unused) S/N: JQHM010 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5524	2024 Jisan JSB2200B 144 mm Hydraulic Breaker (Unused) S/N: 2404338 Usage: Not Available Asset located in: Lake Worth, TX 2024 Jisan JSB2200B 140 mm Hydraulic Breaker (Unused) S/N: 2404339 Usage: Not Available Asset located in: Lake Worth, TX	5532	Teran THH2000B Hydraulic Breaker - Fits Cat 320 (Unused) S/N: CEH715D14HZ C/W: B Linkage For all 18-25 Ton Excavators - With Auto - Lubrication Pre-Disposition. Box Type - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual. Usage: Not Available
5526	2024 TOFT TOFT1550 Hydraulic Breaker (Unused) S/N: JW121Z0715 Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 TOFT TOFT1000 Hydraulic Breaker (Unused) S/N: JW50Z2170 Usage: Not Available
5527	2024 TOFT TOFT1400 Hydraulic Breaker (Unused) S/N: JW81Z3340 Usage: Not Available Asset located in: Lake Worth, TX	er N ARE AND TION OF	Asset located in: Lake Worth, TX 2024 Jisan JSB800B Hydraulic Breaker (Unused) S/N: CP2406128 Usage: Not Available
5528	2024 Jisan JSB2200B Hydraulic Breaker (Unused) S/N: CP2404401 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Elephant EPB800T Hydraulic Breaker (Unused) S/N: CP2406101 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5529	2024 Jisan JSB2200T Hydraulic Breaker (Unused) S/N: CP2406139 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5536	2024 Elephant EPB430BL Hydraulic Breaker (Unused) S/N: CP2406079 Usage: Not Available
5530	2024 Elephant EPB2200B Hydraulic Breaker S/N: CP2407167 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5537	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Jisan JSB430B Hydraulic Breaker (Unused) S/N: CP2408266
5531	2024 Elephant EPB2200T Hydraulic Breaker S/N: CP2406053 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5538	2024 Elephant EPB430BL Hydraulic Breaker S/N: CP2406081 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2016 C & P RX8-11 Hydraulic Breaker S/N: BES062122 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	5545	Teran THH400B-CAT308 Hydraulic Breaker - Fits Cat 307 (Unused) S/N: Not Available C/W: For Mini Excavators CAT 307/308 - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5546	Teran THH400BH Hydraulic Breaker - Fits Cat 416 (Unused)
5540	2024 Elephant EPB400T Hydraulic Breaker (Unused) S/N: CP2406114 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5547	S/N: CAB00398C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition
5541	2024 Elephant EPB400T Hydraulic Breaker (Unused) S/N: CP2406112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		- All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Teran THH400B-SSL Skid Steer Breaker - Fi Cat 226 (Unused)
5542	2024 Jisan JSB400B Hydraulic Breaker (Unused) S/N: CP2403154 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: Not Available C/W: For Skid Steer Loader Cat 226-299 With Mounting Plate included -68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available
5543	2024 Jisan JSB400B Hydraulic Breaker (Unused)		Asset located in: Lake Worth, TX
5544	S/N: CP2403166 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan JSB400BL Hydraulic Breaker (Unused) S/N: CP2404523	416 (Unused) S/N: CAA3496B54HR C/W: For Backhoe Loaders CAT -68mm Tool With Auto - Lubrica Disposition - All New Teran Hydr Hammers are supplied with 2 Cl Point M Type, 2 Hoses, 1 Set of Charging Kit with N2 Bottle and Gauge, 1 Spare Seal Kit, Tool Bo Maintenance Tools and Operatio	S/N: CAA3496B54HR C/W: For Backhoe Loaders CAT 416, 428, 444 -68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5549	Trojan 50CL Hydraulic Breaker - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: SB40YOM20246073 Usage: Not Available Asset located in: Lake Worth, TX	5560	Viper Metal VPH 3-1700 68 in Padding Excavator Bucket (Unused) S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
5550	Trojan 35CL Hydraulic Breaker - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused)		FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	S/N: SB30YOM20246119 Usage: Not Available Asset located in: Lake Worth, TX	5561	Viper Metal VPH 4-1500 57 in Padding Excavator Bucket (Unused) S/N: Not Available
5551	Teledyne TB8309X Hydraulic Breaker S/N: 9991991983 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
5553	2017 Okada 100A Hydraulic Breaker S/N: 3160R C/W: EQUIPMENT-FROM-A-PRIMORIS-		FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5562	2019 Remu EX140 48 in Screening Excavator Bucket S/N: 14000062 Usage: Not Available Asset located in: Lake Worth, TX
5554	Kelly Hydraulic Breaker - Fits Kelly CB7500 S/N: Not Available		
	Usage: Not Available Asset located in: Lake Worth, TX	5563	Remu CAT C/EX140 48 in Padding Excavator Bucket - Fits REMU EX140
5555	Kent 5 in Hydraulic Breaker - Fits John Deere 200C LC S/N: F272749 C/W: 80 mm Diameter Pins, 440 mm Center of Pin Boss to Center of Pin Boss, 325 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in : Lahoma, OK	5564	B&D Fab CAT C/EX140 48 in Padding Excavator Bucket - Fits CAT EX140
5556	Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: B93283 Usage: Not Available Notes : LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
5557	Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
5558	2024 TOFT TOFT280R Rotating Demolition Shear (Unused) S/N: TOFT280R24032 Usage: Not Available Asset located in: Lake Worth, TX	5564A	Rockland 84 in Excavator Bucket S/N: 9757101 Usage: Not Available Asset located in: Lake Worth, TX
5559	2019 Hammer GRP150 15 in Excavator Grapple S/N: H183515GRP Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5565	2024 Jisan BKT32078DB 78 in Cleanup Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: 24072902553 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5572 5573	Teran BKT336D72HD 72 in Digging Excavator Bucket - Fits Cat 336D (Unused) S/N: 0838 C/W: DB Linkage - 2.00m3 for Cat 336D, 336D2, 336E, 336F, 340D2, 340F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips - DB Linkage Usage: Not Available Asset located in: Lake Worth, TX 2024 JESON BKT 336-72 72 in Digging
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Excavator Bucket (Unused) S/N: JQ BKT 053 Usage: Not Available
5566	2024 JESON BKT 345-78 78 in Digging Excavator Bucket (Unused) S/N: JQ BKT 059 Usage: Not Available Asset located in: Lake Worth, TX	5574	Asset located in: Lake Worth, TX 2024 Warrior WBRC40-1700 72 in Digging 40- 45T 1700mm to fit CAT349 Rock Excavator Bucket (Unused) S/N: 2024-09-20-JL01
5567	2024 JESON BKT 345-78 78 in Digging Excavator Bucket (Unused) S/N: JQ BKT 049		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5575	2024 JESON BKT 345-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 039
5568	2024 Jisan BKT34572HD 72 in Excavator Bucket (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 24072902536 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5576	2024 JESON BKT 345-66 66 in Excavator Bucket (Unused) S/N: JQBKT037 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5577	2024 JESON BKT 345-66 66 in Digging
5569	2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 058 Usage: Not Available	5577 5578	Excavator Bucket (Unused) S/N: JQ BKT 057 Usage: Not Available Asset located in: Lake Worth, TX
5570	Asset located in: Lake Worth, TX 2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 040 Usage: Not Available		2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 052 Usage: Not Available Asset located in: Lake Worth, TX
5571	Asset located in: Lake Worth, TX 2024 Jisan BKT336D72HD 72 in Excavator Bucket (Unused) S/N: 24062202043 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5579	2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 028 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5580	2024 Jisan BKT36066HD 66 in 2.2 cyd Digging Excavator Bucket - Fits Komatsu PC360 (Unused) S/N: 24072902567 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5588	Teran BKT325D54HD 54 in Digging Excavator Bucket - Fits Cat 329D (Unused) S/N: 3655 C/W: CB Linkage - 1.22m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6RC Tips Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5589	2024 Jisan BKT32054HD 54 in Excavator Bucket (Unused) S/N: 2406220204
5581	2022 Werk-Brau 480-66-VO-HC 66 in Digging Excavator Bucket S/N: 48834 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5582	2024 BTTL CAT345 60 in Digging Excavator Bucket (Unused) S/N: TOFTEB24581 Usage: Not Available Asset located in: Lake Worth, TX	5590	Teran BKT32054HD 54 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 1847 C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip
5583	2024 Elephant BKT336D60HD 60 in Excavator Bucket (Unused) S/N: 24062200411		Protectors, Reinforcement Plates and 6HD Tips Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5591	Bucket (Unused) S/N: 2407280051 Usage: Not Available Notes : THE PRODUCT IMAGES SHOWN ARE
5584	2024 Jisan BKT336D60HD 60 in Excavator Bucket (Unused) S/N: 24062202027	5592	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Jisan BKT22054HD 54 in Excavator Bucket (Unused) S/N: 24062300918 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5585	2024 JESON BKT 336-60 60 in Digging Excavator Bucket (Unused) S/N: JQ BKT 020		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
 5586	Usage: Not Available Asset located in: Lake Worth, TX 2024 JESON BKT 336-60 60 in Digging	5593	C & P 60 in Digging Excavator Bucket S/N: NHK50615 Usage: Not Available
3000	Excavator Bucket (Unused) S/N: JQ BKT 023 Usage: Not Available Asset located in: Lake Worth, TX	5594	Asset located in: Lake Worth, TX 56 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: 1844
5587	Esco 58 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: RH80487 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5595	2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5602	Teran 48 in .88 cyd Digging Excavator Bucket - Fits Cat 312 S/N: BKT31248 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
		5603	Teran 48 in 1.16 cyd Digging Excavator Bucket - Fits Cat 320
5596	2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available		S/N: BKT32048HD C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5604	48 in Q/C Digging Excavator Bucket S/N: 804560244191 Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	5605	Paladin 48 in Digging Excavator Bucket - Fits
5597	2024 Elephant BKT32048HD 48 in Excavator Bucket (Unused) S/N: 24151503617 Usage: Not Available		John Deere 350G S/N: J000094897-1 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5606	2024 BTTL CAT320 42 in Excavator Bucket (Unused) S/N: TOFTEB24553 Usage: Not Available
5598	2024 JESON BKT 320-48 48 in Digging		Asset located in: Lake Worth, TX
5599	Excavator Bucket (Unused) S/N: JQ BKT 054 Usage: Not Available Asset located in: Lake Worth, TX 2024 JESON BKT 320-48 48 in Digging	5607	Trojan 120CL 42 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available
	Excavator Bucket (Unused) S/N: JQ BKT 055		Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5608	Trojan 120CL 42 in Digging Excavator Bucke Fits 65mm Cat 311/312/313/314 Kobelco 1
5600	Trojan 200CL 48 in Digging Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused)		Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5609	Teran BKT30742 42 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 1208
5601	Trojan 200CL 48 in Digging Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: 0.41m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 7HD Tips Usage: Not Available Asset located in : Lake Worth, TX
		5610	2020 Cat A 42 BU 42 in Excavator Bucket S/N: 0XC702965 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in. Lake Worth, 1A	5611	Komatsu 42 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

This catalog was created at December 8, 2024 01:25:38 AM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5612	Teran BKT31236 36 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 5583 C/W: 312 Linkage - 0.48m3 for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available	5621	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5622	Teran BKT30730 30 in Digging Excavator
5613	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available		Bucket - Fits Cat 307 (Unused) S/N: 1205 C/W: 0.27m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5623	2014 Tag 30 in Digging Excavator Bucket
5614	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused)		S/N: 102177-41 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in : Oklahoma City, OK
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5624	30 in Q/C Digging Excavator Bucket S/N: 60941C Usage: Not Available
5615	Trojan 120CL 36 cyd Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available		Asset located in: Lake Worth, TX
		5625	Tooth Pro 26 in V-Ditching Excavator Bucket S/N: 2360 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5626	Teran BKT31224 24 in Digging Excavator
5616	36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Esco 36 in Excavator Bucket - Fits Komatsu		Bucket - Fits Cat 312 (Unused) S/N: 0171 C/W: 312 Linkage - 0.32m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 3HD Tips Usage: Not Available
	PC220 S/N: 56553		Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5627	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland,
5618	32 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5619	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5628	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5620	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5629	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5630	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused)	5638	2018 Cat B 24 BU 24 in Digging Excavator Bucket S/N: B-24-MHJ74545 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5639	24 in Digging Excavator Bucket S/N: Not Available Usage: Not Available
5631	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available	5640	Asset located in: Lake Worth, TX 24 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5641	Bobcat 24 in Q/C Digging Mini Excavator Bucket S/N: Not Available
5632	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341		S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5642	2023 Kubota K7874A-18 18 in Excavator Bucket S/N: Not Available
5633 Tera Buck S/N: C/W: Plate Usag	Teran BKT305C24 24 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2941 C/W: 0.16m3 with Side Cutters Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX
		5643	Rockland 18 in V-Ditching Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5634	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New		Usage: Not Available Asset located in: Lake Worth, TX
	Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available	5643A	Adco 16 in V-Ditching Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5635	Asset located in: Lake Worth, TX Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available	5644	Tooth Pro 15 in Mini Excavator Bucket S/N: 5707 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	5645	Trojan 50CL 12 in Digging Excavator Bucket Fits 45mm Cat 305, 305.5 Komatsu PC45/50
5636	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5637	24 in Digging Excavator Bucket S/N: 3181 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5646	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused)	5654	Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available C/W: (1) 7 in, (1) 23 in Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5655	Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available C/W: (1) 7 in, (1) 23 in
5647	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50		Usagè: Ńot Ávailable Asset located in : Lake Worth, TX
	/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5656	2024 Jisan BKT34572SKEL 72 in Skeleton Excavator Bucket (Unused) S/N: 24072903037 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5648	Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT
		5657	Asset located in: Lake Worth, TX 2024 Elephant BKT336D72SKEL 72 in Skeletor Excavator Bucket (Unused) S/N: 2407290019 Usage: Not Available
5649			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		Excavator Bucket (S/N: JQBKT051 Usage: Not Availab Asset located in: L 5659 2024 Jisan BKT33 Excavator Bucket (S/N: 2409040117 Usage: Not Availab Notes: THE PRODU FOR ILLUSTRATIO MAY NOT BE AN E THE ACTUAL PRODU Asset located in: L 5660 2024 JESON BKT 3 Excavator Bucket (
5650	Trojan 35CL 12 cyd Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New		Usage: Not Available Asset located in: Lake Worth, TX
	Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Jisan BKT336D66SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: 2409040117 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5651	Teran BKT305C12 12 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2920 C/W: 0.08m3 With Side Cutters Reinforcement		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Plates and 3HD Tips Usage: Not Available Asset located in: Lake Worth, TX		2024 JESON BKT 336-66 SKEL 66 in Skeleton Excavator Bucket (Unused)
5652	Tooth Pro 12 in Mini Excavator Bucket		S/N: JQ BKT 056 Usage: Not Available
	S/N: 5480 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	5661	Asset located in: Lake Worth, TX 2024 JESON BKT 336-66 SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: JQ BKT 050
	Asset located in: Lake Worth, TX 12 in O/C Digging Executor Pucket	_	Usage: Not Available
5653	12 in Q/C Digging Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	Asset located in: Lake	Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5662	2024 Warrior WBSC30-1600 62 in Skeleton Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link	5668	2024 TOFT CAT336 48 in Skeleton Excavator Bucket (Unused) S/N: TOFTEB24674 Usage: Not Available Asset located in: Lake Worth, TX
	Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5669	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5663	Teran BKT325D60SKEL 60 in Skeleton Excavator Bucket - Fits Cat 329D (Unused) S/N: 2220 C/W: CB Linkage - 1.14m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips Usage: Not Available	5670	
5664	Asset located in: Lake Worth, TX 2024 Jisan BKT32060SKEL 60 in Skeleton Excavator Bucket (Unused) S/N: 24072903014 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		
5665	Teran BKT32054SKEL 54 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 2159 C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6HD Tips 80mm Pins Usage: Not Available Asset located in: Lake Worth, TX	5671 2024 Warrior WBSC20-1100 47 Excavator Bucket - Fits Cat 320 (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 Pin Boss to Center of Pin Boss, to Inside Pin Boss Spacing, THE IMAGES SHOWN ARE FOR ILLU PURPOSES ONLY AND MAY NO EXACT REPRESENTATION OF T PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 5672 2024 Warrior WBSC20-1100 47 Excavator Bucket - Fits Cat 320 (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 Pin Boss to Center of Pin Boss, to Inside Pin Boss Spacing, THE	S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5666	2024 Jisan BKT32048SKEL 48 in Skeleton Excavator Bucket (Unused) S/N: 2407290301 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT
5667	Teran BKT31248SKEL 48 in Skeleton Excavator Bucket - Fits Cat 312 (Unused) S/N: 3112 C/W: 312 Linkage - 0.77m3 for CAT 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX		IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
		5673	Teran BKT30742SKEL 42 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 0573 C/W: 0.39m3 for Cat 307, 308 with 5 HD Tips Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5674	Teran BKT30736SKEL 36 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 1126 C/W: 0.34m3 for Cat 307/308 with 6HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5681	Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available
5675	Trojan 200CL 72 in Tilting Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210		Usage: Not Available Asset located in: Lake Worth, TX
	Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5676	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5683	Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available
5677	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5684	Asset located in: Lake Worth, TX Trojan 200CL 72 in Ditch Cleaning Excavator Bucket - Fits 80mm Cat 320/321/323, Hyund R210 Komatsu PC200/220, Deere 160/200 /225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available
5678	Trojan 80CL 48 in Tilting Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88		Usage: Not Available Asset located in: Lake Worth, TX
5679	Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Trojan 80CL 48 in Tilting Excavator Bucket -	5685 5686 5687	Teran BKT32072CLN 72 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 4843 C/W: B Linkage - 0.66m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available
	Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available		Asset located in: Lake Worth, TX 72 in Excavator Bucket - Fits Mobile Excavator S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5680	Asset located in: Lake Worth, TX Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Teran BKT32060CLN 60 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 1319 C/W: B Linkage - 0.54m3 for CAT 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5688	Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES	5693	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		5694	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available	
5689	2024 Warrior WBRC30-1500 59 in Cleanup Excavator Bucket - Fits Cat 320/ 20 - 25 ton		Usage: Not Available Asset located in: Lake Worth, TX	
	(Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5695	Teran BKT31260CLN 60 in Cleanup Excavator Bucket - Fits Cat 312 (Unused) S/N: 0183 C/W: 312 Linkage - 0.38m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Lake Worth, TX	
5690	Usage: Not Available Asset located in: Lake Worth, TX 2024 Warrior WBMCC20-1500 60 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	5696	Trojan 80CL 48 in Ditch Cleaning Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5697		
5691	2024 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused)		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL	5698	Teran BKT30748CLN 48 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3045 C/W: 0.23m3 for Cat 307/308 Usage: Not Available Asset located in: Lake Worth, TX	
	PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5699	Excavator Bucket - Fits Cat 305 (Unused	Excavator Bucket - Fits Cat 305 (Unused)
5692	2024 Warrior WBMCC20-1500 60 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused)		S/N: 01071 C/W: 0.15m3 Usage: Not Available Asset located in : Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5700	Teran BKT30448CLN 48 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 2301 C/W: 0.15m3 Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5701	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D /G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available	5709	Bobcat 36 in Q/C Mini Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	5710	84 in Bucket	
5702	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu		S/N: Not Available Usage: Not Available	
	PC45/50/55 Hyundai R55, Hitachi/Deere 50D		Asset located in: Lake Worth, TX	
	/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5711	2019 Viper 3-1700 67.5 in Padding Bucket - Fits Komatsu PC200 S/N: 3-17001714 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside	
5703	Teran BKT30742CLN 42 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3032 C/W: 0.20m3 for Cat 307/308 Usage: Not Available Asset located in: Lake Worth, TX		to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	
5704	Trojan 35CL 42 in Ditch Cleaning Excavator		Asset located in: McAlester, OK	
	Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D /G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5712	2019 Viper 4-1100 48 in Padding Shaker Bucket S/N: 4-1100218 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside to Inside Pin Boss Spacing Usage: Not Available	
5705	Trojan 35CL 42 in Ditch Cleaning Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D /G (Unused) S/N: Not Available Usage: Not Available		ITEM AT OFFSITE LOCATION MUST E PICKED UP BY DECEMBER 31ST OR I SUBJECT TO 3RD PARTY STORAGE F FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Asset located in: Lake Worth, TX	5713	2018 Viper 4-1100 48 in Padding Shaker	
5706	Teran BKT30342CLN 42 in Cleanup Excavator Bucket - Fits Cat 303 (Unused) S/N: 2836 C/W: 0.13m3 Usage: Not Available Asset located in: Lake Worth, TX		Bucket - Fits Komatsu PC-200 S/N: 4-1100214 C/W: 80 mm Diameter Pins, 415 mm C Pin Boss to Center of Pin Boss, 328 m to Inside Pin Boss Spacing Usage: Not Available	Bucket - Fits Komatsu PC-200 S/N: 4-1100214 C/W: 80 mm Diameter Pins, 415 mm Center of Pin Boss to Center of Pin Boss, 328 mm Inside to Inside Pin Boss Spacing
5707	Teran BKT30436CLN 36 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 01063 C/W: 0.12m3 Usage: Not Available Asset located in: Lake Worth, TX		ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
5708	Teran BKT30136CLN 36 in Cleanup Excavator Bucket - Fits Cat 301 (Unused) S/N: 2645 C/W: 0.07m3 30mm Pins Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
5714	REMU EX140 49 in Padding Bucket S/N: Not Available C/W: 80 mm Diameter Pins, 465 mm Center of Pin Boss to Center of Pin Boss, 340 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5718	Tooth Pro 25 in Digging Bucket S/N: 3333 C/W: 80 mm Diameter Pins, 390 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
5715	REMU EX140 48 in Padding Bucket - Fits Cat	T	Asset located in: Lahoma, OK
	S/N: 14270 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available	5719	82 in Q/C Wheel Loader Bucket S/N: CH031182522 Usage: Not Available Asset located in : Lake Worth, TX
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE	5720	Bobcat Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	AVAILABLE Asset located in: McAlester, OK	5721	61 in Bucket S/N: Not Available Usage: Not Available
5716	REMU EX140 48 in Padding Bucket - Fits Cat S/N: 14268 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Asset located in: Lake Worth, TX
		5722	American Compaction DC18S 18 in Q/C Excavator Compaction Wheel S/N: 100711104 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
		5723	American Compaction DC24BLWP 24 in Excavator Compaction Wheel
5717	Asset located in: McAlester, OK 19.5 in Digging Bucket - Fits Hitachi 160 S/N: 779435681 C/W: 80 mm Diameter Pins, 392 mm Center of Pin Boss to Center of Pin Boss, 307 mm Inside		S/N: 0801012007 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX
	to Inside Pin Boss Spacing Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	5724	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 121817519 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Lahoma, OK	5725	Rockland 24 in Excavator Compaction Wheel S/N: 9412601 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
		5726	American Compaction DC18S 18 in Excavator Compaction Wheel S/N: 111012261 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5727	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 041212842 C/W: EQUIPMENT-FROM-A-PRIMORIS-	5736	2015 Vacuworx RC12 Vacuum Lifter S/N: RC1200144 Usage: 413 Hr Asset located in: Sulphur, LA
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5737	2007 Superior SVL90 Pipe Vacuum Lifter S/N: VL153
5728	Tooth Pro 24 in Excavator Compaction Wheel S/N: Not Available		Usage: Not Available Asset located in : Lake Worth, TX
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5738	2024 Jisan QCCAT336D Excavator Coupler (Unused) S/N: 24042900759 Usage: Not Available
5729	Rockland 24 in Excavator Compaction Wheel S/N: 7102601 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5739	2024 Jisan QCCAT320 Excavator Coupler
5730	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 031012020 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: 24042900737 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN AR FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT
 5731	<u> </u>		Asset located in: Lake Worth, TX
3/31	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 041212819 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5740	(Unused) S/N: 2407290022 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5732	Entek 36 in Excavator Compaction Wheel S/N: 8420		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5741	Teran QCCAT305 Excavator Coupler - Fits Cat 305 (Unused) S/N: 2014
5733	Rockland WE36-4 36 in Excavator Compaction Wheel		C/W: For Cat 305 - 45mm Pins Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 7921501 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5742 Quantity of (2) Pallets of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX 5743 Quantity of (3) Pallets of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	Quantity of (2) Pallets of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5734	Entek 18 in Excavator Compaction Wheel S/N: Not Available		Usage: Not Available
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX		Coupler - Fits Cat S/N: Not Available
5735	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 080710899 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available

Lot #	Details	Lot #	Details
5744	Quantity of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5753	Tysea 60 in Hydraulic Excavator Grapple S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED
5745	Cat Excavator Coupler S/N: Not Available		FROM MACHINE Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5754	2024 Elephant RAKE32065 65 in Excavator Rake (Unused) S/N: 24072900230 Usage: Not Available
5746	Simex SM3-17 84 in Excavator Crusher Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
 5747	2024 Elephant JXJMQC345 51 in Excavator	-	Asset located in: Lake Worth, TX
0 , 4,	Grapple (Unused) S/N: 24072900212 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5755	2024 Jisan RIPPER336D Excavator Ripper (Unused) S/N: 24072903240 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Asset located in: Lake Worth, TX	4	Asset located in: Lake Worth, TX
5748	2024 Elephant JXJMQC336 46 in Excavator Grapple (Unused) S/N: 2406220032 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5756	2024 Elephant RIPPER320 Excavator Ripper (Unused) S/N: 24072900226 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5749	2024 Jisan JXJMQC320 44 in Excavator Grapple (Unused) S/N: 2407290131 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5757	2024 Jisan RIPPER320 Excavator Ripper (Unused) S/N: 24072903228 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5750	2024 TOFT TOFT04G Excavator Grapple (Unused) S/N: TOFTHG24110 Usage: Not Available Asset located in: Lake Worth, TX	5758	2024 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside
5752	Tysea 60 in Q/C Clamshell Style Q/C Hydraulic Excavator Grapple S/N: TY14465 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX		to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5759	2024 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5766 5767	REMU EX140 48 in Q/C Screening Excavator Screening Bucket S/N: 14000058 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX Okada TMB70 Excavator Screening Bucket	
	Asset located in: Lake Worth, TX	-	S/N: 508 C/W: EQUIPMENT-FROM-WATKINS-	
5760	Teran RIPPER307 Excavator Ripper - Fits Cat 307 (Unused) S/N: 1307 C/W: For Cat 307/308 50mm Pin Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
5761	2024 TOFT TOFT08R Excavator Ripper (Unused) S/N: TOFTERP24117 Usage: Not Available Asset located in: Lake Worth, TX	5768	Okada TMB70 Trommel Excavator Screening Bucket S/N: 262 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	
5762	2024 TOFT TOFT04R Excavator Ripper (Unused) S/N: TOFTERP24073147		Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	5769	Okada TMB70 Excavator Screening Bucket S/N: 7050 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVE FROM MACHINE Asset located in: Lake Worth, TX	
5763	Trojan 200CL 72 in Excavator Screening Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200 /225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused)			
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5770	S/N: 569	
5764	REMU PD3150 69 in Q/C Screening Excavator Screening Bucket - Fits CAT C/EX140 S/N: B99434 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN FFROM MACHINE Asset located in: Lake Worth, TX	CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE
	Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5771	Okada TMB70 Excavator Screening Bucket S/N: 351 C/W: EQUIPMENT-FROM-WATKINS-	
5765	REMU EX140 48 in Q/C Screening Excavator Screening Bucket S/N: 14000061 C/W: EQUIPMENT-FROM-WATKINS-		CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
	CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5772	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903054 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5773	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903057 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5781	Teran THUMB2-3.5M 8 in Excavator Thumb - Fits Cat 303 (Unused) S/N: Not Available C/W: Manual Thumb for all 2-3.5 Ton Mini Excavators Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5782	Trojan 120CL Excavator Thumb - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere
5774	Quantity of (2) Cat Excavator Thumb - Fits Cat 320 S/N: Not Available C/W: (1) 28 In Hydraulic, (1) 24 In Manual Usage: Not Available Asset located in: Lake Worth, TX		/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5775	Teran THUMB30-35 M 40 in Excavator Thumb - Fits Cat 336D (Unused) S/N: Not Available C/W: 4 Tines - For Cat 330,336D and 30-36 Ton Excavators Usage: Not Available Asset located in: Lake Worth, TX	- 5783	Trojan 120CL Excavator Thumb - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere /Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5776	Trojan 200CL Excavator Thumb - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available	5784	Gentec HT1035 30 in Excavator Thumb S/N: Not Available C/W: Hydraulic - Fits loader-backhoes & excavators from 10000 to 20000 lbs Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5785	Trojan 80CL Excavator Thumb - Fits 50mm Co 307/308, Komatsu PC78/88 Deere/Hitachi 75
5777	Trojan 200CL Excavator Thumb - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available		/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5778	Asset located in: Lake Worth, TX Teran THUMB20-25 M 30 in Excavator Thumb - Fits Cat 320 (Unused) S/N: Not Available C/W: 4 Tines - For Cat 320,325 and 20 - 25 Ton Excavators Usage: Not Available		- Fits 50mm Cat 307/308, Komat
	Asset located in: Lake Worth, TX	5787	2022 Rockland BTH-CL Excavator Thumb - Fits
5779	Teran THUMB12 - 15 M 26 in Excavator Thumb - Fits Cat 312 (Unused) S/N: 3188 C/W: For Cat 312, 315 and all 12-15 Ton		Rockland BTHCL S/N: 238845 Usage: Not Available Asset located in: Lake Worth, TX
	Excavators 4 Tines Usage: Not Available Asset located in: Lake Worth, TX	5788	Quantity of (4) Cat Excavator Thumb - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5780	Teran THUMB5M 11 in Excavator Thumb - Fits Cat 305 (Unused) S/N: 3177		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	C/W: Manual Thumb for Cat 305 and 5 Ton Mini Excavators Usage: Not Available Asset located in : Lake Worth, TX	5789	Quantity of (4) Cat Excavator Thumb S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
5790	Trojan 80CL Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75 /85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: XD202408201 Usage: Not Available Asset located in: Lake Worth, TX	5799	Diesel Equipment 35CL 14 in Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5791	Trojan 50CL Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5800	Gentec HT618 16 in Excavator Thumb - Fits Gentec S/N: Not Available C/W: Fits mini excavators up to 4000 lbs Usage: Not Available Asset located in: Lake Worth, TX Excavator Thumb
5792	Trojan 50CL Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available	5801 5802	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX 2024 Raytree REDM50 50 in Excavator Mulcher
5793	Asset located in: Lake Worth, TX Diesel Equipment 50CL 15 in Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 S/N: Not Available Usage: Not Available		Attachment - Fits 12 - 20 ton (Unused) S/N: DM20241009164 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5794	Asset located in: Lake Worth, TX Gentec HT830 25 in Excavator Thumb	5803	Edge TH4800 48 in Skid Steer Mulcher S/N: TH0226 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Fits loader-backhoes & excavators from 6000 - 10000 lbs Usage: Not Available Asset located in : Lake Worth, TX		Fecon 90 in Mulcher Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5795	Gentec MT830 Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5805	2024 Jisan JSV765S Demolition Pulverizer (Unused) S/N: 24072903210 Usage: Not Available
5796	Gentec MT824 - Fits mini excavators from 4000 - 9000 lbs Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5797	Trojan 35CL Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5806	2024 TOFT TOFT08P Demolition Pulverizer (Unused) S/N: TOFTHP24107 Usage: Not Available Asset located in: Lake Worth, TX
5798	Trojan 35CL Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5807	Bodine 200 Demolition Pulverizer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5808	Quantity of (4) Crawler Pipelayer Side Booms S/N: Not Available C/W: (2) 20 ft, (1) 18 ft, (1) 13 ft Usage: Not Available Asset located in: Lake Worth, TX	5818	Quantity of (4) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5809	Hill 144 in Dozer Rake S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5819	Asset located in: Corsicana, TX System One Undercarriage Chain / Rails - Fits Cat D6T S/N: Not Available
5810	Cat Light brackets - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5820	C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX Cat Crawler Tractor Counterweight (Unused)
5811	Asset located in: Corsicana, TX Cat Radiator - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX
5812	Cat Scarifier S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5821	Cat Crawler Tractor Counterweight (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
5813	Quantity of Cat Misc. Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5822	Cat Crawler Tractor Drawbar - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5814	Cat Pipelayer hook and block - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5823	Carco Crawler Tractor Winch - Fits Cat D8 S/N: 12608 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5815	Quantity of (3) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5824	Carco Crawler Tractor Winch - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5816	Quantity of (3) Pallets of Trunnion ball - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5826	2012 Midwestern M 530C Winch Pipe Laying System: Fits Cat D5 Dozer Attachment S/N: 13A12187 C/W: 15 Ft Folding Boom Usage: Not Available Asset located in: Lake Worth, TX
5817	Quantity of (4) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		

Lot #	Details	Lot #	Details
5827	Rear Screen Dozer Attachment - Fits John Deere 700K S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	5834	Cat Crawler Tractor Winch - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
		5835	198 in Angle Dozer Blade - Fits Cat D6 LGP S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5828	Allied W6G Crawler Tractor Winch		Asset located in: Corsicana, TX
0020	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE	5836	194 in Angle Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Asset located in: Lake Worth, TX	5837	174 in Angle Dozer Blade - Fits Cat D6XW
5829	Paccar Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in : Corsicana, TX
	Asset located in: Lake Worth, TX	5838	174 in Angle Dozer Blade - Fits Cat D6TXW
5830	Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE	5839	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX 174 in Angle Dozer Blade - Fits Cat D6XW
5831	Asset located in: Lake Worth, TX Crawler Tractor Winch S/N: Not Available	5840	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in : Corsicana, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		174 in Angle Dozer Blade - Fits Cat D6TXW
	Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5832	Paccar PA56 Crawler Tractor Winch S/N: 1300340 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE	5841	174 in Angle Dozer Blade - Fits CatXW D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Asset located in: Lake Worth, TX	5842	164 in Angle Dozer Blade - Fits Cat D7
5833	Allied W6G Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5843	164 in Angle Dozer Blade - Fits Cat D6T XL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5852	160 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5844	162 in U-Blade Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5853	152 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5845	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5854	150 in Angle Dozer Blade - Fits Cat D6DT S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5846	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5855	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5847	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5856	148 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5848	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5857	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5849	160 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5858	128 in PAT Dozer Blade - Fits Cat D6M S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5850	160 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5859	Bobcat 96 in PAT Skid Steer Dozer S/N: 224403408 Usage: Not Available Asset located in: Lake Worth, TX
5851	Asset located in: Corsicana, TX 160 in Angle Dozer Blade - Fits Cat D6T XL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	5860	24 in single grouser Tracks - Fits Cat D6 S/N: Not Available C/W: System 1; EQUIPMENT-FROM-WATKINS CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Usage: Not Available Asset located in: Corsicana, TX	5861	Ditch Witch Drill Rubber Tracks S/N: Not Available C/W: 300x52.5x98, 12 in

C/W: 300x52.5x98, 12 in Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5862	Mini Excavator 280x72x56 Rubber Tracks S/N: Not Available C/W: 12 in, one set Usage: Not Available Asset located in: Lake Worth, TX	5873	2022 Cat 908 1.4YD E ISO 82 in Q/C Wheel Loader Bucket S/N: CH021139822 Usage: Not Available Asset located in: Lake Worth, TX
5863	Bobcat Mini Excavator 12 In All Purpose Rubber Tracks S/N: Not Available C/W: (1) 300x 52.5x74, (1) 300x52.5x98 Usage: Not Available	5874	2022 Cat 908 1.4YD E ISO Wheel Loader Bucket S/N: K5803211BU Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5875	JRB 102 in Q/C Wheel Loader Bucket - Fits Case 621D/ New Holland LW130B
5864	Cat scarifier, drawbars, trench box - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		S/N: 0106-172069-211 Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Corsicana, TX	5876	2018 Volvo L150H4.7POSPN 35 m3 Digging Wheel Loader Bucket
5867	90 in Multi-Shank Motor Grader Ripper - Fits Cat 140G S/N: RP125		S/N: 18599 Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	5877	KA Fabrication 164 in Q/C Wheel Loader Forks - Fits Hyundai HL955
5867A	Motor Grader Scarifier - Fits Cat 140M S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: KA3246 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5868	AMI JRB416 108 in 3.5 cyd Q/C Grapple Wheel Loader Bucket - Fits Hyundai HL955 S/N: 21041840101 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	5878	96 in Wheel Loader Forks
			S/N: Not Available Usage: Not Available
			Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	5879	2021 BR Co 84 in Q/C Wheel Loader Forks - Fits Hyundai HL955
5869	102 in Q/C Wheel Loader Bucket S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		S/N: 63782 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5870	2022 Cat IT 1.5YD BU 96 in Q/C Wheel Loader	5881	Cat 72 in Q/C Wheel Loader Forks - Fits Cat
	Bucket S/N: CY220505839 Usage: Not Available		950 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
 5871	Asset located in: Lake Worth, TX 2022 Cat 908 1.4YD E ISO 82 in Q/C General	 5882	JRB 60 in Q/C Wheel Loader Forks
3671	Purpose Wheel Loader Bucket S/N: CH031182822 Usage: Not Available		S/N: J458821 Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	5883	Pemberton 60 in Wheel Loader Forks
5872	2022 Cat 908 1.4YD E ISO 82 in Q/C General Purpose Wheel Loader Bucket		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	S/N: CH031183322 Usage: Not Available Asset located in : Lake Worth, TX	5883A	60 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5884	60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5891	2018 Stanley MBX15E09 Q/C Backhoe Hydraulic Breaker S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
5885	60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5892	Construction Tools RX8-11 Backhoe Hydraulic Breaker S/N: BES062129 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5885A 5886	56 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 53 in Wheel Loader Forks		Usage: Not Available Asset located in: Lake Worth, TX FRD F6 Q/C Backhoe Hydraulic Breaker S/N: 12453 Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5894	Asset located in: Lake Worth, TX Kent F6 Backhoe Hydraulic Breaker S/N: 6137 Usage: Not Available
5887	Balderson BF9360 59 in Q/C Wheel Loader Forks - Fits Cat 950 S/N: 3WL1826 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	5895	Asset located in: Lake Worth, TX Tooth Pro 46 in Cleanup Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5888	68 in Wheel Loader Quick Coupler S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Teran THH400BH Backhoe Hydraulic Breaker -	5896	2013 Woods Wainroy 30 in Backhoe Rear Bucket S/N: 102344430 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
	Fits Cat 416 (Unused) S/N: CAB00407C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil	5896A	Asset located in: Oklahoma City, OK 30 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition	5897	28 in Digging Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	- All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual	5898	24 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5899	Tooth Pro 18 in Backhoe Rear Bucket S/N: 2382
5890	Teran THH400BT Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAA2730B54HR		C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX
5890A	Usage: Not Available Asset located in: Lake Worth, TX Stanley Q/C Backhoe Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5900	Geith 18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5901	Tooth Pro 18 in Backhoe Rear Bucket S/N: 5108 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5911	Quantity of (2) 18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5902	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5912	Bobcat 18 in Q/C Digging Backhoe Rear Bucket S/N: 1720020 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5903	17 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5913	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5904	Hensley 13 in Backhoe Rear Bucket S/N: 19943 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5914	24 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5905	12 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5915	John Deere 18 in Backhoe Rear Bucket S/N: 1852831 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5906	Strickland 12 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5916	Asset located in: Lake Worth, TX 18 in Backhoe Rear Bucket S/N: Not Available
5907	12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY		C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5908	Usage: Not Available Asset located in: Lake Worth, TX 16 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5917	Tag 12 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5909	12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5918 —	Tooth Pro 18 in V-Ditching Backhoe Rear Bucket S/N: 2611 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes:
5910	Hensley 16 in V-Ditching Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5919	Asset located in: Lake Worth, TX 24 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5920	Hensley 16 in V-Ditching Backhoe Rear Bucket S/N: 33666 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5929	48 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5930	44 in Backhoe Forks S/N: Not Available Usage: Not Available
5921	Hensley 12 in Digging Backhoe Rear Bucket S/N: 19884 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5931	Asset located in: Lake Worth, TX Cat 96 in Backhoe Loader Bucket S/N: 190300052 Usage: Not Available Asset located in: Lake Worth, TX
5922	Tooth Pro 18 in V-Ditching Backhoe Rear Bucket S/N: 4933 C/W: EQUIPMENT-FROM-A-PRIMORIS-	5932	Cat 96 in Backhoe Loader Bucket S/N: 190300048 Usage: Not Available Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5933	Cat 96 in Backhoe Loader Bucket S/N: 190300051 Usage: Not Available Asset located in: Lake Worth, TX
5923	Tooth Pro 12 in Backhoe Rear Bucket S/N: 2916 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5934	Cat 96 in Backhoe Loader Bucket S/N: 190500058 Usage: Not Available Asset located in: Lake Worth, TX
5924	24 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-	5935	96 in Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5936	Quantity of (6) 72 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5925	WB 12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5937	Quantity of (4) 72 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5926	Quantity of (2) 60 in Backhoe Forks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	CONSTRUCTION Usage: Not Available Asset located in : Corsicana, TX	5938	Quantity of (4) 48 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5927	42 in Backhoe Forks - Fits Terex 760 S/N: Not Available C/W: accessories		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5939	Quantity of (8) 40 in Fork tines S/N: Not Available
5928	Quantity of (3) 48 in Backhoe Forks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in : Corsicana, TX
	Usage: Not Available Asset located in: Corsicana, TX	5941	Quantity of (2) 48 In x 56 In Screens S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5942	Post Driver Guide S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5953	Quantity of (2) 2024 Landhonor BA-22-09W 105 in Tractor Rear Blade Blade Attachment (Unused) S/N: HL00018/HL00017
5943	Quantity of Forks (Unused) S/N: Not Available C/W: (1) 48 in set, (1) 42 in set		C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5954	Frontier LL1410 119 in Land Leveler Box Blade S/N: XFLL14X000009 Usage: Not Available
5944	Post Driver Guide S/N: Not Available Usage: Not Available	5955	Asset located in: Lake Worth, TX Gannon HD244 Box Blade
5945	Asset located in: Lake Worth, TX 38 In x 98 In Material Basket S/N: Not Available	1	S/N: HD24484HXDFNG Usage: Not Available Asset located in : Lake Worth, TX
	C/W: fork pockets Usage: Not Available Asset located in: Lake Worth, TX	5956	2024 Industrias America F10T 10 ft Box Scraper (Unused) S/N: F10T202435760
5946	Post Driver Guide S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5957	2024 Industrias America F08T 96 in Box Scraper (Unused)
5947	44 in Misc. attachment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		S/N: F08T202537998 Usage: Not Available Asset located in : Lake Worth, TX
	CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5958	2005 ICON 18D 4 Tire Hydraulic Pull Scraper S/N: 5075A C/W: Lead Scraper, 20.5x25 Tires
5948	American Compaction DC18S 18 in Q/C Excavator Compaction Wheel S/N: 04038094		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5959	Level Best PL 72D Box Scraper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5949	30 in Auger Bit S/N: Not Available Usage: Not Available	5961	Volvo 72 in Wheel Loader Forks S/N: 15200002 Usage: Not Available Asset located in: Lake Worth, TX
5949A	Asset located in: Lake Worth, TX Quantity of (2) System One Idlers - Fits Cat D6T S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5965	Volvo 48 in L50-L120 Fork Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5950	2024 Mower King SSECAGY Skid Steer Auger (Unused) S/N: SSECAG-Y24060902F C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits Usage: Not Available Asset located in: Oklahoma City, OK	5966	42 in Fork Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5952	CXI 44 in Excavator Grapple S/N: ZZA1398 Usage: Not Available Asset located in: Lake Worth, TX		

Details	Lot #	Details
967 2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5973 5974	96 in Fork Extensions S/N: Not Available C/W: Vise Stand Usage: Not Available Asset located in: Lake Worth, TX Volvo Wheel Loader Material Handling Arm
Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	3974	S/N: 252 Usage: Not Available Asset located in: Lake Worth, TX
Asset located in: Lake Worth, TX	5976	Caldwell 8000 lb Material Handling Arm - Fits
2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Forklift S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
Asset located in: Lake Worth, TX	5976A	2013 Arrow 1000100-12-152 140 in Material
2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Handling Arm S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5979	2024 Jisan JSC160 Excavator Plate Compactor (Unused) S/N: 24072903224 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Jisan JSC50 Excavator Plate Compactor (Unused) S/N: 2404290048 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
Quantity of (5) 2024 Wolverine EX-66-78L/84L	E001	·
S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 84 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles	5981	2024 Elephant EPC50 Excavator Plate Compactor (Unused) S/N: 24072900219 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 78 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 84 In Fork Extensions (Unused) S/N: Not Available	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT ASset located in: Lake Worth, TX Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 78 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 84 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available C/W: Two Bundles Usage: Not Available C/W: Two Bundles Usage: Not Available

Lot #	Details	Lot #	Details
5983	Teran QCCAT336D Quick Coupler - Fits Cat 336D (Unused) S/N: 5704 C/W: DB Linkage for Cat 330D, 336D Usage: Not Available Asset located in: Lake Worth, TX	5994	Johnson 4 Sheave Hook Block S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5984	Teran QCCAT320 Quick Coupler - Fits Cat 320 (Unused) S/N: 5311 C/W: B Linkage - 80mm Pins Usage: Not Available Asset located in: Lake Worth, TX	5995	60 ton 5 Sheave Hook Block S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5985	Teran QCCAT312 Quick Coupler - Fits Cat 312 (Unused) S/N: 6159 C/W: 312 Linkage for Cat 311, 312, 314 - 65mm Pins Usage: Not Available Asset located in: Lake Worth, TX	5996 5997	Crane Ball S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5986	Quantity of (4) 16 In Trench Compactor Drums S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (2) Material Handling Arm S/N: Not Available C/W: (1) Arrow CE60TH 6000 lb 80 in boom, (1) 116 in boom Usage: Not Available Asset located in: Lake Worth, TX
5987	23 in Excavator Compaction Wheel S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5998	40 ft Crane Boom - Fits Grove S/N: Not Available C/W: 23 Ft Swimg Away Job Usage: Not Available
5988	66 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5999	Asset located in: Lake Worth, TX 60 ton 5 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5989	66 in Padfoot Shell Kit - Fits Padfoot Shell Kit (Unused) S/N: 32598 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	6000	Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX
5990 5991	2018 Cat CS34 50 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6001	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available
J 7 7 1	Quantity of (4) 48 In x 48 In Steel Crane Pads S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6002	Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused)
5992	Quantity of (4) 48 In x 50 In Steel Crane Pads S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5993	Asset located in: Lake Worth, TX Quantity of (3) Crane Caps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6003	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6004	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6012B	SKLP 60 in 3-Point 9 Row No Till Drill (Unused) S/N: BZJ9240616 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX
6005	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	6013	Scherer 28 In Kernel Processor S/N: W0602106010 Usage: Not Available Asset located in: Lake Worth, TX
6006	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available	_6013A	Strauss Clipper 20 ft Offset Sickle Bar Mower S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Assorted Size, One Pallet Usage: Not Available Asset located in : Lake Worth, TX	6014	2012 Rhino SE8 15 ft 0 in Batwing Brush Cutter Attachment - Fits Tractor Drawbar S/N: 11278
6007	2025 Double A 18 ft Bale Mover (Unused) S/N: 1UFBU182XST012578 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	6015	60 in Rotary Brush Cutter S/N: Not Available
6008	2024 Landhonor UC-22-60W Bale Unroller (Unused)		Usage: Not Available Asset located in : Midland, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6016	Land Pride RCF2060 60 in 3-Point Brush Cutt S/N: Not Available C/W: 540 PTO
6009	2024 Landhonor UC-22-60W Bale Unroller (Unused)		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6017 60 in 3-Point Brush Cutter S/N: Not Available C/W: 540 PTO	S/N: Not Available C/W: 540 PTO
6010	1999 Rome TAW20S 10 ft Disc S/N: 10TAW3237R		Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 25 in Notched Front Discs, 26 in Notched Rear Discs, 11 in Spacing, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Livingston, LA	6017A	6 ft 3-Point Hitch Rotary Mower S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX
6011	International 5100 13 ft 16 ft Pull-Type Air Drill S/N: 0390213C003164 C/W: 7 in Spacing, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX	6017B	John Deere MX15 15 ft Batwing Brush Cutter S/N: W0MX15E001181 C/W: 540 PTO Usage: Not Available
6012	Case 12 ft Seed Drill	6018	Asset located in: Lake Worth, TX Steel Fluid Filter Tank
	S/N: 0419636 C/W: 4 in Spacing, 13 in Discs Usage: Not Available Asset located in : Lake Worth, TX	0018	S/N: Not Available C/W: 3 Compartments Usage: Not Available
6012A		 	Asset located in: Lake Worth, TX
OUIZA	SKLP 60 in 3-Point 9 Row No Till Drill (Unused) S/N: BZJ9240617 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX	6019	Scherer 28 In Kernel Processor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6020	Quantity of Ratchet Binders S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6028	2024 Suihe VG Skid-Mounted Vibratory Screen (Unused) S/N: Not Available C/W: 5 ft x 4 ft 6 in Double Deck Screen, THE
6021	Land Pride PD15 10 in 3-Point 15 Series Utility Post Hole Digger S/N: 1747822 C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX		PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6022	Land Pride RCR1260 60 in 3-Point Brush Cutter S/N: 1820706 C/W: 540 PTO, 3 hp Standard Duty w/Shear		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Bolt Usage: Not Available Asset located in: Lake Worth, TX	6029	Burcham Ultimate Bagger Electric Sandbag Filling Machine S/N: Not Available C/W: 12 in Conveyor, DeWalt 4 Cal Air
6024	Cat Bale Spear S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		C/W: 12 in Conveyor, DeWalt 4 Gal Air Compressor, 12 in Conveyor & Accessories Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Corsicana, TX	6030	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused)
6025	Euro Double 42 in Bale Spear S/N: Not Available C/W: c/w: 2 prongs and stabilizer prong	6031	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused)
6025A	Quantity of (3) Auger Bit S/N: Not Available C/W: (1) 15 in, (1) 22 ln, (1) 30 ln		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6032	2024 Genius GSM-66IN Separator Magnet (Unused)
6026	1959 Allis Chalmers D17 Antique Tractor (Inoperable) S/N: D1726103 C/W: 8 Forward 2 Reverse, Partial Powershift, Gasoline Engine, Electric Start, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, 6.00-16 Front Tires, 16.9-28 Rear Tires		S/N: GSM09112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6033	2024 Genius GSM-66IN Separator Magnet (Unused)
6027	2024 Landhonor SMS-64-40G Skid-Mounted Screen (Unused) S/N: Not Available C/W: 4 ft 9 in x 4 ft 2 in Double Deck Screen Usage: Not Available Asset located in: Lake Worth, TX		S/N: GSM09111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		6034	2024 Paladin SM-66-3206E 32 in x 6 ft Separator Magnet (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6035	Storage Container S/N: 2-682990-01 Usage: Not Available Asset located in: Midland, TX	6043	2024 Suihe BX-7 7 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6036	16 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (0) Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6037	8 ft x 20 ft Trench Shield S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: 4 in Thick Panels, (4) 96 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	6044	2024 Suihe BX-5 5 cyd Bedding Box (Unused) S/N: Not Available Usage: Not Available
6038	8 ft x 18 ft Trench Shield S/N: 982669 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6039	Asset located in: Lake Worth, TX 8 ft x 20 ft Trench Shield	6045	Quantity of (2) 2024 Kit Containers Steel 5 ft 4
	S/N: Not Available C/W: 4 in Thick Panels, (4) 96 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX		in x 8 ft 2 in (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
6040	8 ft x 16 ft Trench Shield S/N: 982678 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	6046	Quantity of (2) 2024 Kit Containers Steel 5 ft x 8 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available
6041	2024 Suihe BX-12 12 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6047	Asset located in: Lake Worth, TX Quantity of (2) 2024 Kit Containers Steel 5 ft x 8 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6048	Quantity of (2) 2024 Kit Containers Steel 6 ft x 8 ft 3 in (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available
6042	2024 Suihe BX-9 9 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6049	Asset located in: Lake Worth, TX Quantity of (2) 2024 Kit Containers Steel 5 ft x 10 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
		6050	Quantity of (2) 5 ft x 10 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6051	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6059	Quantity of Mustang & Wacker Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6060	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused)
6052	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		S/N: 11705481 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6061	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815555 C/W: Briggs & Stratton 1 Cylinder Gasoline
6053	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available		Engine Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6062	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705482 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available
6054	2024 Landhonor LHR-PC90 Vibratory Plate		Asset located in: Lake Worth, TX
	Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6063	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11743231 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6055	Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	6064	Wacker Neuson Vibroplate BPS2050B Vibratory Plate Compactor (Unused) S/N: 11862553 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6056	Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	6065	Wacker Neuson BPS1550B Vibratory Plate Compactor (Unused) S/N: 11728975 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available
6057	Quantity of (4) Vibratory Plate Compactor		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	6066	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733549 C/W: Briggs & Stratton 1 Cylinder Gasoline
6058	Quantity of (3) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6067	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733550 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6075	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11662551 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6068	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738243 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6076	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11737833 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6069	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738734 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6077	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728974 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6070	Wacker Neuson Vibroplate BPS2050BW Vibratory Plate Compactor (Unused) S/N: 11666297 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6078	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728979 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6071	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11743232 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6079	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705489 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6072	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11738234 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6080	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738240 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6073	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738225 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6081	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738224 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6074	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815554 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6082	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738235 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6083	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666300 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6091	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666299 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6084	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666298 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6092	2015 Wacker Neuson RT Trench Compactor S/N: 24250030 C/W: 2024 US EPA Label, Kohler 3 Cylinder Diesel Engine, / 32 in Drums, Remote Control w/ Cord Usage: 305 Hr Asset located in: Lake Worth, TX
6085	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815550 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6093	Wacker Neuson RT Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA Label, CARB Compliant, Lombardini 6LBDL1. 37SFO:IFI 3 Cylinder 15.5 kW 1028 cc Diesel Engine, 33 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available
6086	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815551 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Wacker Neuson Articulating Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA Label, CARB Compliant, Lombardini 6LBD1. 37SFO:IFI 3 Cylinder 15.5 kW 1023 cc Diesel Engine, 32 in Drums, Articulated Steering,
6087	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815553		EQŬIPMENT-FROM-WATKINS-CONSTRŬCTION Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6095	Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Open Operator Station, Tier 4, 2013 US
6088	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11705485 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available		EPA Label, CARB Compliant, Kubota D1005- EF06 3 Cylinder 14.5 kW 1.0 L Diesel Engine, 24 in / 33 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6096	2016 Bomag BMP 8500 Articulating Trench
6089	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815552 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available		Compactor S/N: Not Available C/W: Kubota 3 Cylinder Diesel Engine, 24 in / 33 in Drums, Cordless Remote Control, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
6090	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11728978 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6097	Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Kubota 3 Cylinder Diesel Engine, 24 in / 33 in Drums, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6098	2016 Bomag BMP8500 Trench Compactor S/N: 101720125102 C/W: Tier 4, 2015 US EPA Label, Kubota D1005 3 Cylinder 14.5 kW 1.0 L Diesel Engine, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available	6106	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2024 Landhonor LHR-RM90 Jumping Jack
6099	Bomag BMP8500 Trench Compactor S/N: 101720134167 C/W: Open Operator Station, Tier 4, 2019 US EPA Label, Kubota D1005-EF06 3 Cylinder 14.3 kW 1.0 L Diesel Engine, 25 in / 35 in Drums,		Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Remote Control w/ Cord, Articulated Steering Usage: Not Available Asset located in: Lake Worth, TX	6109	Bomag Jumping Jack Tamper S/N: Not Available Usage: Not Available
6100	2011 Wacker Neuson RTSC2 Trench		Asset located in: Lake Worth, TX
	Compactor S/N: Not Available C/W: Open Operator Station, 2011 US EPA Label, 3 Cylinder Diesel Engine, 32 in Drums, Articulated Steering	6110	Quantity of Concrete Hoppers & Stand S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6111	2007 Starind 1550 Concrete Chute S/N: Not Available
6101	Wacker Neuson Trench Compactor S/N: 24540169 C/W: Tier 4, 2020 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in		C/W: Fork Pockets; EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX
	Drums, Cordless Remote Control, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 512 Hr Asset located in: Lake Worth, TX	6112	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6102	Wacker Neuson Trench Compactor S/N: 24498021 C/W: 2019 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in Drums, Remote Control w/ Cord, EQUIPMENT-	6113	Quantity of (3) Pneumatic Chipping Hammers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FROM-SUNSTATE-EQUIPMENT Usage: 520 Hr Asset located in: Lake Worth, TX	6114	Quantity of (3) Pneumatic Breakers S/N: Not Available Usage: Not Available
6103	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available	6115	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6104	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine	6116	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6117	Toro 23135 Mini Skid Steer Breaker S/N: 313000111
6105	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	6118	2024 Gar-Bro Concrete Bucket S/N: 427-R DWG 14-11 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6119	2014 Toro MB-1600 Walk-Behind Concrete Buggy S/N: 314000161 C/W: Hydrostatic Drive, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6129	2019 Core Cut Walk-Behind Saw S/N: 162276 C/W: 30 in Max Blade Diameter, 15 in Max Cutting Depth, Hydraulic Blade Raise / Lower, 2019 US EPA Label, Kubota 4 Cylinder 2.6 L Diesel Engine Usage: 1,607 Hr Asset located in: Lake Worth, TX
6100	·	6130	2012 Hsqvarna 4000 Walk-Behind Saw
6120	Bad Boy Electric Utility Vehicle S/N: BBE514B3785006557 C/W: Canopy, 2 Passenger, Winch, Brush Guard Usage: Not Available Asset located in: Lake Worth, TX	6130	S/N: 001309168002 C/W: 13 in Max Blade Diameter, 6.5 in Max Cutting Depth, Manual Blade Raise / Lower, Kohler 20 hp 624 cc Gasoline Engine Usage: Not Available
6121	Mortar and Grout Mixer		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 2013 US EPA Label, Honda GX240 Gasoline Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6131	Merit 600.62DR4 Walk-Behind Saw S/N: 10002020 C/W: 4 Cylinder Diesel Engine, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 780 Hr
6122	2024 Landhonor LHR-CM300 Portable		Asset located in: Lake Worth, TX
	Concrete Mixer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6133	Quantity of (3) 2018 Multiquip B46H11H Power Trowel S/N: MG0112140/MF0111393/MG0112160 C/W: Honda Gas Engine, (2) 42 In, (1) 36 In
6123	2024 Landhonor LHR-CM400 Portable Concrete Mixer (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6134	Wacker Electric Concrete Vibrator S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE-
6124	Quantity of (2) Walk-Behind Saws S/N: 2800003 / 3A9S46M10G1168026 C/W: Water Hose Connection, Manual Blade		EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Raise / Lower, Honda GX390 1 Cylinder Gasoline Engine, (1) Husqvarna FS513 Walk- Behind Saw s/n: 2800003 & (1)Tiger MSM Walk-Behind Saw s/n: 3A9S46M10G1168026 (Inoperable) Usage: Not Available		2007 Wacker M3000 Concrete Vibrator S/N: 1782595 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6125	Husqvarna FS6600D Walk-Behind Saw (Inoperable) S/N: 001298383001 C/W: Water Hose Connection, Electric Blade Raise / Lower, US EPA Label, John Deere 4024HF295 4 Cylinder Diesel Engine Usage: Not Available	6136	2013 Edco 2EC-NG-1.5 Electric Concrete Grinder S/N: 130910129 C/W: 22 in Grinding Width, 2 Grinding Discs, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	6137	2010 Whiteman WRS-5200 Concrete Screed S/N: WG1800464 C/W: 7 ft Screed, 41 ft Boom Length, 2009 US EPA Label, Daihatsu 3 Cylinder Diesel Engine Usage: 24 Hr
6126	2024 Landhonor LHR-Q300 Heavy Duty Concrete Floor Walk-Behind Saw (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6138	Quantity of (3) 16 in Sono-Tube Concrete Forms S/N: Not Available C/W: 16 in Wide, (1) 7 ft 6 in, (1) 8 ft, (1) 10 ft Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	6147	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	
		6148	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	
6139	8 ft Man Guard S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6149	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates	
6140	8 ft Man Guard S/N: Not Available Usage: Not Available	6150	Usage: Not Available Asset located in: Lake Worth, TX 2024 Agriquip CP2030 30 ft x 20 ft Steel	
6141	Asset located in: Lake Worth, TX NTS 52-88 in Trench Shield S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
6142	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused)		Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in : Lake Worth, TX	6151	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6143	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6152	2024 Agriquip CP2030 30 ft x 20 ft Steel	
6144	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT Usage: Not Available	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6145	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	6153	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
6146	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6154	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6160	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6155	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6161	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6156	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6162	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6157	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6163	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6158	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6164	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6159	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6165	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6166	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6173	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6167	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6174	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6168	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6175	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6169	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6176	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6170	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6177	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6171	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 SUNTOP S1220 Metal Shed (Unused)
6172	Asset located in: Lake Worth, TX 2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

	Detaile	1 4	Dataila	
Lot #	Details	Lot #	Details	
6179	2024 SUNTOP S1220 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6185	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6186	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)	
6180	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	6187	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)	
6181	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6188	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX		2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)	
6182	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available	6189	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)	
6183	Asset located in: Lake Worth, TX 2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES O	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Usage: Not Available	6190	KJ K1220 12 Ft x 20 Ft Single Garage Metal	
6184	Asset located in: Lake Worth, TX 2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available		Shed S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6191	2024 Landhonor LHR-CP1119 11 ft x 19 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6192	2024 Landhonor LHR-CP1119 11 ft x 19 ft All-Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6200	Cummins CXL855GP200 270 kW Mobile Generator Set S/N: 1080210013 C/W: Cummins 6 Cylinder Diesel Engine, 337.5 kVA/270 kW Rated 3 Phase Output, / 347 V / 600 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, E-Stops, T/A Trailer, Lunette Ring Usage: Not Available Asset located in: Lake Worth, TX
6194	2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6201	Cummins 200DGFC-5199 200 kW Skid-Mounted Stand-By Generator Set S/N: D050767149 C/W: US EPA Label, Cummins 6CTAA8.3G3 6 Cylinder 8.3 L Diesel Engine, 250 kVA/200 kW Rated 3 Phase Output, 134 kVA,/134 kW, Rated Single Phase Output, 240 V 8 130 V
6195	2024 Landhonor PLD-MS0608 6 ft x 8 ft Galvanized Metal Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available		Single Phase Output, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, E-Stops Usage: Not Available Asset located in: Lake Worth, TX
6196	Asset located in: Lake Worth, TX 2024 Landhonor PLD-MS0608 6 ft x 8 ft Galvanized Metal Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available Asset located in: Lake Worth, TX	6202	Sdmo J230 240 kW Mobile Generator Set S/N: J23031607497801 C/W: John Deere 6 Cylinder Diesel Engine, 240 V / 480 V Rated Voltage, T/A Trailer, Lunette Ring Usage: 2,753 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY
6197	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed		Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6205	2014 Magnum MMG100D Generator Set S/N: 1408172 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 14,441 Hr Asset located in: Lake Worth, TX
		6205A	Cat Generator Set S/N: C11-12-05372 C/W: 2011 US EPA Label, CARB Compliant, Perkins 3362 4 Cylinder 116.9 kW 4.4 L Diesel Engine, 100 kVA/80 kW Rated 3 Phase Output 480 V / 208 V / 120 V Rated Voltage, 100 kVA
6198	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Galvanized Metal Pent Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available Asset located in: Lake Worth, TX		/80 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: Not Available Asset located in: Midland, TX
6199	Quantity of (2) 4 Ft x 6 Ft Metal Shed S/N: Not Available C/W: two boxes Usage: Not Available Asset located in: Lake Worth, TX	6206	2016 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 7353339 C/W: Isuzu BR-4JJ1X 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 12,507 Hr Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6208	2005 Katolight 50 kW Mobile Stand-By Generator Set S/N: 5FTGE102051024328 C/W: 2004 US EPA Label, John Deere 5030TF270C 5 Cylinder 60 kW 3.0 L Diesel Engine, 50 kVA,/50 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 20,410 Hr Asset located in: Lake Worth, TX	6214	2012 Multiquip DCA-45SSIU4 36 kW Mobile Generator Set S/N: 4GNBG1221CB030860 C/W: Isuzu 4JJ1T 4 Cylinder 2.99 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 24,512 Hr Asset located in: Lake Worth, TX
6209		6215	Cat Mobile Generator Set S/N: 1JG110206N1606402 C/W: Cat 4 Cylinder Diesel Engine, T/A Trailer, Ball Hitch, Electric Brakes Usage: 1,300 Hr Asset located in: Lake Worth, TX
	Usage: 2,301 Hr Asset located in: Lake Worth, TX	6216	2019 Wacker Neuson G25 20 kW Mobile Generator Set (Inoperable)
6210	2019 Magnum Pro MMG45IF4 38 kW Mobile Generator Set S/N: 3004557276 C/W: 2019 US EPA Label, Isuzu BQ4IE2X 19 kW 2.2 L Diesel Engine, 33 kVA/ Rated 3 Phase Output, 480 V / 208 V Rated Voltage, 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes, EQUIPMENT FROM UNITED RENTALS Usage: 13,399 Hr		S/N: Not Available C/W: 4 Cylinder Diesel Engine, 24.4 kVA/19.5 kW Rated 3 Phase Output, 240 V / 480 V / 120 V Rated Voltage, 16 kVA,/16 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 661 Hr Notes: INOPERABLE ITEM MUST BE REMOVED
			FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6217	Allmand MP25 25 kVA Skid-Mounted
6212	2013 Wacker Neuson G50 38 kW Mobile Generator Set S/N: 4TCSU1851DH189075 C/W: 2013 US EPA Label, John Deere 4045Tf290B 4 Cylinder 4.5 L Diesel Engine, 48 kVA/38 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Lunette Ring	6217	Generator Set S/N: 1238E12204 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 9,942 Hr Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6218	Allmand MP25 25 kVA Skid-Mounted Generator Set
6213	Asset located in: Lake Worth, TX 2014 Multiquip DCA-45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1222EL014135 C/W: 2014 US EPA Label, Isuzu 4LE2X 4 Cylinder 56 kW 2.1 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,121 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; SUNSTATE EQUIPMENT CO. RENTAL PEOPLE YOU CAN DEPEND ON Asset located in: Lake Worth, TX		S/N: 1238E12050 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 10,981 Hr Asset located in: Lake Worth, TX
		6219	Allmand MP25 25 kVA Skid-Mounted Generator Set S/N: 1238E12221 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 11,249 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6220	Airman SDG25S 25 kVA Skid-Mounted Generator Set S/N: 1238E13551 C/W: 2022 US EPA Label, Isuzu 4 Cylinder 30 kW Diesel Engine, 25 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 13,453 Hr	6226	2016 Atlas Copco 20 kW Mobile Generator Set S/N: 4500G1111GR121222 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 1,895 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6228	2006 MMD SDG25S 20 kVA Mobile Generator Set
6221	2017 Multiquip DCA-25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0918HB044057 C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 768 Hr		S/N: 5UABU09196V000009 C/W: 2006 US EPA Label, Isuzu 4LE1 4 Cylind 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Outp 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 5,460 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6233	Generac Guardian 24 kW Stand-By Generator
6222	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0910GB043032 C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 37 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT		Set S/N: Not Available C/W: Natural Gas Engine Usage: Not Available Asset located in: Lake Worth, TX
		6234	1997 Kohler 40RZ Electric Transfer Switch S/N: 384987 C/W: To Fit Kohler Usage: Not Available Asset located in: Lake Worth, TX
6223	Usage: 7,983 Hr Asset located in: Lake Worth, TX 2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 7152111 C/W: 2015 US EPA Label, Isuzu 4LE2T 4	6235	2018 Allmand 7 kW Light Tower S/N: 5AEA1AC17JH000125 C/W: Tier 4, 2015 US EPA Label, Kubota d1105 3 Cylinder 12 kW 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,070 Hr Asset located in: Lake Worth, TX
	Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14 kVA,/14 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 2,725 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2018 Allmand 7 kW Light Tower S/N: 5AEA1AC19JH000334 C/W: Tier 4, 2017 US EPA Label, Kubota d1005 3 Cylinder 10 kW 1 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,493 Hr Asset located in: Lake Worth, TX
6224	Multiquip DCA25SSIU4F Generator Set S/N: 7154328 Usage: Not Available Asset located in: Lake Worth, TX	6237	2018 Allmand NLV-P Light Tower S/N: 39-003469 Usage: 3,471 Hr Asset located in: Lake Worth, TX
6225	Multiquip DCA45SSIU4F Generator Set S/N: 7252100 Usage: Not Available Asset located in: Lake Worth, TX	6238	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07-001037 C/W: Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D1005-BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Balloon Diffuser, S/A Trailer, Ball Hitch Usage: 4,887 Hr Asset located in: Midland, TX

Lot #	Details	Lot #	Details
6239	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07000969 C/W: 2015 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: 4,827 Hr Asset located in: Midland, TX	6247	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0417JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr Notes: ADDITIONAL INFORMATION
6240	2016 Allmand 8KWNLP 1250 W Light Tower		AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	S/N: 07-000162 C/W: Cat c1.1 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 2,815 Hr Asset located in: Lake Worth, TX	6248	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power
6241	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA4LU497838 C/W: Tier 4, 2019 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch		Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes : ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in : Lake Worth, TX
	Usage: 300 Hr Asset located in: Lake Worth, TX	6249	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847
6242	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA2LU497952 C/W: Tier 4, 2019 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 294 Hr	6250	C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2018 Wacker Neuson LTV6 6 kW Light Tower
6243	2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0410PM003593 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 2 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1 Hr Asset located in: Humble, TX		S/N: 5XFLV0413JM003840 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,346 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
6244	2023 Wacker Neuson LTV6 6 kW Light Tower		Asset located in: Lake Worth, TX
	S/N: 5XFLV0416PM003596 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, S /A Trailer, Ball Hitch Usage: 1 Hr Asset located in: Humble, TX	6251	2019 Magnum Pro MLT6SM 6 kW Light Tower S/N: 7FSBL1012KB834551 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,483 Hr
6245	2023 Wacker Neuson LTV6 6 kW Light Tower		Asset located in: Lake Worth, TX
02.10	S/N: 5XFLV0414PM003595 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8 Hr Asset located in: Humble, TX	6252	2019 Magnum MLT6SMD Light Tower S/N: 7FSBL1013JB992752 C/W: US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 673 Hr Notes: ADDITIONAL INFORMATION
6246	2023 Wacker Neuson 6 kW Light Tower	7	AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX
	S/N: 5XFLV0416PM000889 C/W: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX	6253	2018 Magnum MLT6SMD 6 kW Light Tower S/N: 7FSBL1010JB983099 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: Not Available Notes: ADDITIONAL INFORMATION
			AVAILABLE IN OFFICE - MSO ; Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
6254	2018 Magnum Pro MLT6SM 6 kW Light Tower S/N: 7FSBL1010JB586914 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8,910 Hr Asset located in: Lake Worth, TX	6262	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1013HB568871 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 3,886 Hr Notes: ADDITIONAL INFORMATION
6255	2017 Magnum Pro MLT6SM 6 kW Light Tower (Inoperable)		AVAILABLE IN OFFICE - MSO ; Asset located in : Lake Worth, TX
	S/N: 3001715479 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,347 Hr	6263	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1011HB880896 C/W: 2017 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Hitch Usage: 6,613 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6256	2018 Magnum MLT6SK Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6264	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1011HB880607 C/W: 2017 US EPA Label, Mitsubishi L3E- W464MLD 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch, Electric Brakes Usage: 6,831 Hr
6257	<u> </u>		Notes: ADDITIONAL INFORMATION
0237	2018 Wacker Neuson LTV6K Light Tower S/N: WNCLTV02CPUM04886 Usage: 9,715 Hr		AVAILABLE IN OFFICE - MSO ; 3001880607 Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6265	2019 Terex RL4 6 kW Light Tower
6258	2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,788 Hr		S/N: 4ZJSA1015J1009757 C/W: 2018 US EPA Label, Deutz 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	6266	2016 Terex RL4 6 kW Light Tower
6259	2017 Generac MLT6SMD Light Tower S/N: 3001517568 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 803 Hr Notes: ADDITIONAL INFORMATION		S/N: RL416J-1024 C/W: 2015 US EPA Label, Kohler FKHXL1.3 3 Cylinder 8 kW 1.3 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8,753 Mi Notes: LOCATED-IN-HOUSTON-TX; EQUIPMENT FROM SUNBELT RENTALS; Asset located in: Humble, TX
	AVAILABLE IN OFFICE - MSO;	6267	2011 Magnum MLT3060M Light Tower
6261	Asset located in: Lake Worth, TX 2017 Generac MLT6SMD Light Tower S/N: 7FSBL1016HB880618 C/W: US EPA Label, Mitsubishi 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,312 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	0207	S/N: 5AJLS1614BB006243 C/W: 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,275 Hr Asset located in: Lake Worth, TX
		6268	2014 Allmand PAL1250W2 Light Tower S/N: 0202PAL14 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6269	2014 Allmand PAL1250W2 Light Tower S/N: 0203PAL14 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6278	2012 Atlas Copco XAS750JD7T3 Mobile Air Compressor S/N: 4500B1611CR080883 C/W: 261 psi Working Pressure, John Deere 6 Cylinder 6.8 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 468 Hr
6270	2012 Allmand Light Tower S/N: 0229PAL12 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6280	Asset located in: Lake Worth, TX Airman PDS400S Mobile Air Compressor S/N: C16B10076 C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 6,172 Hr
6271	2012 Allmand Light Tower S/N: 0224PAL12 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Airman PDS400S Mobile Air Compressor S/N: C16B10484 C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch
6272	1997 Amida AL4075D-4MH Light Tower S/N: 971044029 Usage: Not Available	6282	Usage: 3,252 Hr Asset located in: Lake Worth, TX 2018 Doosan HP375WCU-T4F Mobile Air
6273	Asset located in: Lake Worth, TX 2018 Doosan HP1600WCU-T4F 1600 cfm Mobile Air Compressor S/N: 4FVCCBPB8JU483256 C/W: 150 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, T/A Trailer, Lunette Ring, Electric Brakes	6283	Compressor S/N: Not Available C/W: 250 psi Working Pressure, 2018 US EPA Label, Cummins QSB4.5 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch, Electric Brakes Usage: 4,337 Hr Asset located in: Lake Worth, TX
	Usage: 1,806 Hr Asset located in : Lake Worth, TX		2017 Doosan P425/HP375 Mobile Air Compressor
6275	2011 Doosan HP1600 Mobile Air Compressor S/N: 419233UJUB83 C/W: 200 psi Working Pressure, 2019 US EPA Label, Cummins QSX15 6 Cylinder 344 hp 15 L Diesel Engine, T/A Trailer, Lunette Ring Usage: 9,344 Hr Asset located in: Lake Worth, TX		S/N: Not Available C/W: 2017 US EPA Label, Cummins 6 Cylinder 130 hp 4.8 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes Usage: 1,709 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION
6276	2012 Sullair 900H Mobile Air Compressor		AVAILABLE IN OFFICE - MSO ; Asset located in : Lake Worth, TX
6277	S/N: 201202150037 C/W: Air Dryer, 250 psi Working Pressure, Cat C9 6 Cylinder Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: CERTIFICATE OF ORIGIN AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX 2015 Doosan XP825WCU Mobile Air	6284	2017 Doosan P425/HP375WCU-T4F Mobile Air Compressor S/N: Not Available C/W: 2017 US EPA Label, Cummins 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes Usage: 3,099 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION
	Compressor S/N: 4FVCBBFB3FU46608 C/W: 250 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, T/A Trailer, Lunette Ring, Electric Brakes Usage: 3,198 Hr Asset located in: Lake Worth, TX		AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX
Cylir Exha Brak Usa		6285	2016 Atlas Copco XATS400PEJD7 Mobile Air Compressor S/N: 4500B1315GR076376 C/W: 175 psi Working Pressure, John Deere 4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,560 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6286	2013 Atlas Copco XATS400JD7 Mobile Air Compressor S/N: 4500B1310DR074160 C/W: 175 psi Working Pressure, John Deere	6294	Kaeser M55 PE Air Compressor S/N: 1383-8357356 Usage: Not Available Asset located in: Lake Worth, TX	
	4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,323 Hr Asset located in : Lake Worth, TX	6295	Kaesar M58 Air Compressor S/N: 1062-7593833 Usage: Not Available	
6287	2011 Atlas Copco XAVS375 Mobile Air Compressor S/N: 4500B1312BR071984 C/W: 2011 US EPA Label, John Deere 4045HF285 4 Cylinder 4.5 L Diesel Engine	6296	Asset located in: Lake Worth, TX Kaeser M58 Air Compressor S/N: 1060-7586681 Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: 889 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lahoma, OK	6297	2015 Atlas Copco XAS185KD7PE 185 cfm Mobile Air Compressor S/N: 4500A1013FR049103 C/W: 123 psi Working Pressure, 2014 US EPA Label, Kubota V2403-CR-EF02 3 Cylinder 36.8 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 976 Hr	
6288	2018 Doosan P250 Air Compressor S/N: 4FVCABBA2JU483872 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	6298	Asset located in: Lake Worth, TX 2021 Chicago Pneumatic CPS 185 KD8 Air Compressor S/N: H0P030934 Usage: 7 Hr	
6289	Sullair 250Q Air Compressor	_	Asset located in: Lake Worth, TX	
	S/N: 004-100085 Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	6299	2021 Airman PDS185S Mobile Air Compressor S/N: 7H6BY11A6MA002935 C/W: 200 psi Working Pressure, 2021 US EPA Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 185 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	
6290	2021 Atlas Copco XAS188 KD8 Air Compressor S/N: UVC200482 Usage: 13 Hr Asset located in: Lake Worth, TX	6300	Airman PDS185S 185 cfm Skid-Mounted Air Compressor S/N: B4-6811098 C/W: 150 psi Working Pressure, 2003 US EPA	
6291	2021 Atlas Copco XAS188 KD8 Mobile Air Compressor S/N: 4500A1017MR200473 C/W: 125 psi Working Pressure, Kubota D1803-			Label, Isuzu NE2 4 Cylinder 2.17 L Diesel Engine Usage: 1,840 Hr
	T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX		2019 Allmand Maxi-Air 185 Mobile Air Compressor S/N: 5AEA1KF10KH000628 C/W: 200 psi Working Pressure, 2018 US EPA	
6292	2021 Atlas Copco XAS188 KD8 Mobile Air Compressor S/N: 4500A1012MR200476 C/W: 125 psi Working Pressure, Kubota D1803- T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX		Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 9,961 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	
6293	2021 Kaeser M55 PE Air Compressor S/N: WKA0N1000M8357329 Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
6302	2019 Allmand MA185-5E1 185 cfm Mobile Air Compressor S/N: 5AEA1KF15KH000737 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 6,855 Hr Asset located in: Lake Worth, TX	6308	2017 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 4FVCABAA2HU479803 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,825 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
6303	2020 Allmand MA185-6E1 185 cfm Mobile Air Compressor S/N: 5AEA1KF16LH000831 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 8,456 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; CERTIFICATE OF ORIGIN AVAILABLE IN OFFICE;	6309	Asset located in: Lake Worth, TX 2012 Doosan C185WJD-T4I Mobile Air Compressor S/N: 4314506UIVE43 C/W: 200 psi Working Pressure, 2011 US EPA Label, CARB Compliant, John Deere 4024TF281C 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,197 Hr
6304	Asset located in: Lake Worth, TX 2018 Sullair 185DPQ-KU-T3 185 cfm Mobile Air		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Compressor S/N: 201801250011 C/W: 200 psi Working Pressure, 2017 US EPA Label, Kubota D1803 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT FROM UNITED RENTALS Usage: 2,460 Hr Asset located in: Lake Worth, TX	6310	2010 Doosan C185 185 cfm Mobile Air Compressor S/N: Not Available C/W: 2010 US EPA Label, Kubota V2403 36.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,140 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
6305	2018 Doosan P185WDOU-T4F 185 cfm Skid- Mounted Air Compressor		THE INSPECTION REPORT Asset located in: Humble, TX
6306	S/N: 486622UFAGF89 C/W: 185 psi Working Pressure, 2018 US EPA Label, CARB Compliant, Doosan 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Midland, TX 2017 Doosan C185WDZ Mobile Air Compressor S/N: 4FVCABAA8HU479739	6311 Ingersoll R S/N: 15178 C/W: 120 p Cylinder Di Usage: 3,6 Notes: LOA ITEM AT O PICKED UF SUBJECT FORKLIFT AVAILABLI Asset loca 6312 2013 Sulliv Compress S/N: 3181 C/W: 100 p Cylinder 2. Lunette Rin Usage: 1,4 Notes: DEF THE INSPE	Ingersoll Rand 185 Mobile Air Compressor S/N: 151780U85957 C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine Usage: 3,697 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
	C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring		FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Usage: 2,131 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		2013 Sullivan D185PJDSB Mobile Air Compressor S/N: 31811
6307	2017 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 479354UAABG07 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,381 Hr		C/W: 100 psi Working Pressure, John Deere 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,438 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		6313	2013 Sullivan Palatek 185 cfm Mobile Air Compressor S/N: 101343 C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF231A 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,018 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6314	2018 Sullair 185DPQ Mobile Air Compressor S/N: 201802270074 C/W: 185 psi Working Pressure, 2017 US EPA Label, Kubota 4 Cylinder 36 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,685 Hr Asset located in: Lake Worth, TX	6320	2013 Ingersoll Rand 185 cfm Mobile Air Compressor S/N: 4FVCABAAXDU454478 C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF281C 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-
6315	2011 Sullair 185DPQJD Skid-Mounted Air Compressor		CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 201107210060 C/W: 185 psi Working Pressure, 2011 US EPA Label, John Deere 4024TF 4 Cylinder 37 kW 2.4 L Diesel Engine Usage: 2,365 Hr Asset located in: Lake Worth, TX	6321	2011 Atlas Copco XAS185JDRSC Mobile Air Compressor S/N: 4500A1019BR038617 C/W: 2011 US EPA Label, John Deere 4024TF281A 4 Cylinder 2.4 L Diesel Engine Usage: Not Available
6316	2004 Sullair 250DPQ-JDD Mobile Air Compressor S/N: 2004100085		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine		Asset located in: Lahoma, OK
	Usage: 3,195 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	6322	2007 Airman PDS185S 185 cfm Mobile Air Compressor S/N: B46B44752 C/W: 150 psi Working Pressure, 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY
	Asset located in: McAlester, OK		Usage: 1,309 Hr
6317	2017 Atlas Copco XAS185KD Mobile Air Compressor		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX
	S/N: 4500A1014HR055415 C/W: 185 psi Working Pressure, 2017 US EPA Label, Kubota 3 Cylinder 1.8 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 1,075 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6324	2021 Rotair D400T4F 150 cfm Mobile Air Compressor S/N: 16MBB1319MD081696 C/W: 150 psi Working Pressure, 2021 US EPA Label, Cummins QSF3.8 4 Cylinder 3.8 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch Usage: 1,709 Hr
6318	2017 Atlas Copco XAS185KD7PET4F Mobile		Asset located in: Lake Worth, TX
	Air Compressor S/N: 4500A1012HR055090 C/W: Kubota 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 947 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	6325A	Sullair Skid-Mounted Air Compressor S/N: 5AEA1KF15KH000737 C/W: 185 psi Working Pressure, 2011 US EPA Label, John Deere 4024TF 4 Cylinder 37 kW 2.4 L Diesel Engine Usage: 979 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION
6319	2017 Atlas Copco XAS185KD7PET4F Mobile Air Compressor		AVAILABLE IN OFFICE - MSO ; Asset located in : Lake Worth, TX
	S/N: 4500A1012HR055414 C/W: 2017 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6325B	Genaer Air Compressor S/N: 1611 C/W: 15 hp Motor, 2014 US EPA Label, Kubota V3800 4 Cylinder 3.8 L Diesel Engine Usage: Not Available Asset located in: Midland, TX
	, took looked in Lake Worth, 17	6326	Smith Mobile Air Compressor
			S/N: 100510361 C/W: 125 psi Working Pressure, Ford 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details	
6327	2014 Lincoln Vantage 500 Multi-Process Engine Driven Welder S/N: U1140846332 C/W: Kohler Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 213 Hr	6335	2005 Miller Bobcat 250 Engine Driven Welder S/N: LF041958 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
1	Asset located in: Lake Worth, TX	6336	2005 Miller Bobcat 250 Skid-Mounted Multi-	
6328	2013 Lincoln Vantage 300 400 A Skid-Mounted Multi-Process Engine Driven Welder S/N: U1130305650 C/W: Tier 4, 2012 US EPA Label, CARB Compliant, Kohler V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 4,763 Hr			Process Engine Driven Welder S/N: LF041958 C/W: 2005 US EPA Label, Kohler CH20S 624 cc Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 1,686 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6337	Lincoln Vantage 520SD 520 A Mobile Stick	
6329	2013 Lincoln Vantage 300 400 A Skid-Mounted Multi-Process Engine Driven Welder S/N: U1130301883 C/W: 2012 US EPA Label, CARB Compliant, Kubota V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage		Engine Driven Welder S/N: Not Available C/W: 2015 US EPA Label, Deutz d2.9l 4 Cylinder 40 hp 2.9 L Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: 5,080 Hr Asset located in : Lake Worth, TX	6338	Quantity of (2) Miller Millermatic 255 Wire Electric Welder	
6330	2020 Miller Bobcat 260 Multi-Process Engine Driven Welder S/N: NA300101R C/W: Kohler Engine, Welding Leads, 120 V / 240 V Rated Voltage, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 496 Hr		S/N: NA168518N/NB358903N C/W: Single Phase, 200 V/ 240 V Inp Welding Leads, EQUIPMENT-FROM-I RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	C/W: Single Phase, 200 V/ 240 V Input, Welding Leads, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes : .
	Notes: . Asset located in: Lake Worth, TX	6339	6339 Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder	
6332	2015 Miller Trailblazer 251 Multi-Process Engine Driven Welder S/N: MF500520R C/W: 2015 US EPA Label, Kohler CH730 725 cc Gasoline Engine, 240 V / 120 V Rated Voltage,		Cylinder Diesel Engine, Welding Lo	C/W: 2013 US EPA Label, Kubota v1505 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage Usage: 4,301 Hr
	120 V Rated Voltage Usage: 2,736 Hr Asset located in : Lake Worth, TX	6340	2012 Gorman-Rupp PA6C60-4045T Trailer- Mounted Water Pump	
6333	2016 Miller Bobcat 250 Mobile Multi-Process Engine Driven Welder S/N: MG310150R C/W: 2016 US EPA Label, Kohler 3 Cylinder 725 cc Engine, 240 V / 208 V Rated Voltage, 120 V	6341	S/N: 1493129N C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 8,350 Hr Asset located in: Lake Worth, TX	
	Rated Voltage Usage: 619 Hr Asset located in : Lake Worth, TX		Gorman-Rupp Mobile Centrifugal Pump S/N: Not Available	
6334	Miller Multi-Process Engine Driven Welder S/N: LG076841 C/W: Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 1,576 Hr Asset located in: Lake Worth, TX		C/W: US EPA Label, John Deere 4 Cylinder Diesel Engine Usage: Not Available Asset located in : Lake Worth, TX	

Lot #	Details	Lot #	Details
6342	Slanzi Skid-Mounted Water Pump S/N: 249606 C/W: 4 in Intake, 3 in Discharge, Centrifugal Water Pump, Slanzi 4 Cylinder Diesel Engine Usage: 183 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	6352 6353	Cornell 25WHRPPF86 Electric Skid-Mounted Water Pump S/N: 2530458 C/W: 3 in Intake, 2.5 in Discharge, Centrifugal, WEC 25 Hp Electric Motor; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Skid-Mounted Water Pump
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal Trash Pump, 2014 US EPA Label, Honda 270
6343	2022 Stealth Trailer-Mounted Water Pump S/N: 1R9RBUAA7NS723142 C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, 2021 US EPA Label, CARB Compliant, Deutz TD2.9L4 4 Cylinder 55.4 kW 2.92 L Diesel Engine, S/A Trailer, Ball Hitch, 85 Gallon Skid Usage: Not Available Asset located in: Midland, TX		cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
6344	6 In Water Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6354	Quantity of Pump & PTO S/N: Not Available C/W: MC L0614SC Triplex pump, Muncie PTO, (2) Tanks, One Pallet Usage: Not Available
6345	Quantity of (4) Water Pump S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Water Pump, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	6356	Asset located in: Lake Worth, TX Taylor Y-23WOF 23000 lb Dual Front Tires Pneumatic Tire Forklift S/N: S2113943 C/W: 2 Stage Mast, 24 in Lowered Mast Hei
6346	Quantity of (3) Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		93 in Forks, Solid Pneumatic Tire Cylinder Diesel Engine Usage: 6,519 Hr
6347	Usage: Not Available Asset located in: Corsicana, TX Quantity of (3) Water Pump	6357	2005 Hyster H155XL2 Pneumatic Tire Forklift S/N: G006V03382C Usage: Not Available
	S/N: Not Available C/W: 3 in Intake, 2 in Discharge Usage: Not Available Asset located in : Lake Worth, TX	6358	Asset located in: Lake Worth, TX Doosan GC55C-9 11850 lb Pneumatic Tire Forklift S/N: FGB1C256000013
6348	Quantity of (3) Water Pump S/N: Not Available C/W: 2 in Intake, 3 in Discharge Usage: Not Available Asset located in: Lake Worth, TX	C/W: 2 Stage Mast, 162 in Max Li in Lowered Mast Height, 59 in For	Usage: 7,819 Hr
6349	Quantity of (3) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: Trash Pump, 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6359	2017 Toyota 8FG45U 9300 lb Pneumatic Tire Forklift S/N: 11419 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 92 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid
6350	Quantity of (2) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Trash Pump Usage: Not Available Asset located in: Lake Worth, TX		Usage: 1,152 Hr

Lot #	Details	Lot #	Details
6360	1998 Mitsubishi FD35 8000 lb Pneumatic Tire Forklift S/N: AF19B00320 C/W: 2 Stage Mast, 148 in Max Lift Height, 97 in Lowered Mast Height, 48 in Forks, Side Shift, Mitsubishi 6 Cylinder Diesel Engine Usage: 9,917 Hr Asset located in: Lake Worth, TX	6366	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001157 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX
6361	2001 Hyster H80XM 7700 lb Pneumatic Tire Forklift S/N: K005A04243Y C/W: 2 Stage Mast, 122 in Max Lift Height, 57 in Forks, Fork Positioner, Solid Pneumatic Tires, V6 LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6367	2014 Toyota 8FD35U 6500 lb Pneumatic Tire Forklift S/N: 8FD35U-10678 C/W: 3 Stage Mast, 187 in Max Lift Height, 72 in Forks, Fork Positioner, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4 Cylinder Diesel Engine Usage: 5,597 Hr Asset located in: Lake Worth, TX
6361A 6362	2015 Toyota 8FG35U 7300 lb Cushion Tire Forklift S/N: 10863 C/W: 3 Stage Mast, 159.5 in Max Lift Height, 106 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 2015 US EPA Label, Toyota 4 Cylinder 63 kW 3.6 L LPG Engine Usage: 1,917 Hr Asset located in: Lake Worth, TX 2007 TCM FD70-9 12980 lb Pneumatic Tire	6368	2019 Toyota 8FD35U 7000 lb Pneumatic Tire Forklift S/N: 8FD35U13204 C/W: 3 Stage Mast, 187 in Max Lift Height, 78 in Lowered Mast Height, 48 in Forks, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4 Cylinder 2.9 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
6363	Forklift S/N: A30K00809 C/W: 2 Stage Mast, 157 in Max Lift Height, 96 in Lowered Mast Height, 94 in Forks, Fork Positioner, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 5,357 Hr Asset located in: Lake Worth, TX 2024 Viper FY30T 6600 lb Pneumatic Tire	6369	2005 Toyota 7FGU32 6020 lb Pneumatic Tire Forklift S/N: 68341 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Side Shift, 2006 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 8,373 Hr
0000	Forklift (Unused) S/N: 23L3001161 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 22 Hr	6370	Asset located in: Lake Worth, TX 2004 Tailift FD30 Pneumatic Tire Forklift S/N: 318920B Usage: Not Available Asset located in: Lake Worth, TX
6364	Asset located in: Lake Worth, TX 2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001163 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine	6371	Doosan G30P-5 5550 lb Pneumatic Tire Forklift S/N: FGA0C-1330-02057 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, GM Vortec 4 Cylinder Dual Fuel Engine Usage: 6,566 Hr Asset located in: Lake Worth, TX
6365	Usage: 2 Hr Asset located in: Lake Worth, TX 2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001164 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1 Hr	6372	2017 Hyundai 30L-7A 5900 lb Pneumatic Tire Forklift S/N: 3HHKHH09CH8001849 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 86 in Lowered Mast Height, 45 in Forks, Side Shift, 2017 US EPA Label, Hyundai 4 Cylinder 2.4 L LPG Engine Usage: 4,100 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6373	2016 Hyundai 301-7A Pneumatic Tire Forklift S/N: HHKHHF009CH0001849K Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6374	Cat 2PD6000 6000 lb Pneumatic Tire Forklift S/N: AT14E30364 C/W: 2 Stage Mast, 147 in Max Lift Height, 96 in Lowered Mast Height, 53 in Forks, Side Shift, Solid Pneumatic Tires, 2010 US EPA Label, 4 Cylinder 3.3 L Diesel Engine Usage: 18,085 Hr Asset located in: Lake Worth, TX Mitsubishi FG30 Pneumatic Tire Forklift	6381	2017 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift S/N: 8FDU30-62078 C/W: 3 Stage Mast, 187 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 3 Cylinder 1.7 L Diesel Engine Usage: 8,465 Hr Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6382	2014 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift S/N: 60256
6376	2015 Toyota 8FGU30 5820 lb Pneumatic Tire Forklift S/N: 65650 C/W: 2 Stage Mast, 159 in Max Lift Height, 102 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG	C/W: 3 Stage Mast, Full Lift Height, 83 in Lower Forks, Side Shift, Solid I US EPA Label, Toyota 3 Engine Usage: 2,134 Hr Asset located in: Lake Notes 1	
	Engine Usage: 3,750 Hr Asset located in: Lake Worth, TX		S/N: 69985
6377	2006 Toyota 7FGU30 5750 lb Pneumatic Tire Forklift S/N: 69901 C/W: 3 Stage Mast, Full Free Lift, 171 in Max Lift Height, 83 in Lowered Mast Height, 45 in Forks, Side Shift, Fork Positioner, Solid		C/W: 2 Stage Mast, Full Free Lift, 187 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4Y ECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 3,920 Hr Asset located in: Lake Worth, TX
	Pneumatic Tires, 2006 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6384 6385 6386	2015 Toyota 8FGU30 5820 lb Cushion Tire Forklift S/N: 65668
6378	2015 Cat DP30N Pneumatic Tire Forklift S/N: AT14G00200 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 11,524 Hr		C/W: 2 Stage Mast, 159 in Max Lift Height, 100 in Lowered Mast Height, 42 in Forks, 2016 US EPA Label, Toyota 4Y ECS 4 Cylinder 42 hp 2.23 L LPG Engine Usage: 4,257 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2000 Toyota 7FGU30 Pneumatic Tire Forklift
6379	2017 Cat 2C6000 5750 lb Cushion Tire Forklift S/N: AT83F42214 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 52 in		S/N: 61163 C/W: 3 Stage Mast, 47 in Forks, Solid Pneumatic Tires, LPG Engine Usage: Not Available Asset located in : Lake Worth, TX
	Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in : Lake Worth, TX		Cat 2PD6000 5500 lb Pneumatic Tire Forklift S/N: AT14E30407 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 58 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Dioxel Engine
6380	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift		Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 11,707 Hr Asset located in : Lake Worth, TX
	S/N: 69980 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 4,420 Hr Asset located in: Lake Worth, TX	6386A	Doosan D30G 5467 lb Pneumatic Tire Forklift S/N: K360403 C/W: 3 Stage Mast, Full Free Lift, 185.6 in Max Lift Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6387	2018 Toyota 8FDU25 4800 lb Pneumatic Tire Forklift S/N: 8FDU25-62405 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Toyota Diesel Engine Usage: 2,362 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR	6392	2020 Cat Gp25N 4500 lb Pneumatic Tire Forklift S/N: AT35A09092 C/W: 3 Stage Mast, 188 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 1,558 Hr Asset located in: Lake Worth, TX 2018 Doosan G25N7 4600 lb Pneumatic Tire Forklift
			S/N: FGA14-1290-00939 C/W: 2 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Tier 2, 2018 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine
6388	2007 Cat P6000LP 5050 lb Pneumatic Tire		Usage: 2,390 Hr Asset located in: Lake Worth, TX
	Forklift S/N: AT13F10861 C/W: 3 Stage Mast, 186 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Block Forks, Solid Pneumatic Tires, Tier 2, 2007 US EPA Label, Nissan K25 L 4 Cylinder 2.5 L LPG Engine Usage: Not Available	6393A	2011 Doosan G25P-5 Pneumatic Tire Forklift S/N: FGA0B133001275 C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, 2011 US EPA Label, GM 4 Cylinder 46 kW 2.4 L LPG Engine Usage: 3,885 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6395	2019 Toyota 8FGU25 4900 lb Pneumatic Tire
6389	2019 Toyota 8FDU25 5000 lb Pneumatic Tire Forklift S/N: 62836 C/W: Enclosed Cab, 2 Stage Mast, Full Free Lift, 131.5 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2019 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 1,127 Hr	Forklift S/N: 94056 C/W: 3 Stage Mast, 131 in Max Lift in Lowered Mast Height, 41 in For Fork Positioner, Solid Pneumatic US EPA Label, Toyota 4Y 4 Cylinded L LPG Engine Usage: 11,841 Hr Asset located in: Lake Worth, TX 6396 2015 Toyota 8FGU25 4900 lb Pne Forklift S/N: 8FGU25-67336 C/W: 2 Stage Mast, 131.5 in Max I 81 in Lowered Mast Height, 42 in Shift, Solid Pneumatic Tires, 2015 Label, Toyota 4 Cylinder 38 kW 2.2 Engine Usage: 10,669 Hr Asset located in: Lake Worth, TX 6397 2016 Toyota 8FGU25 4900 lb Pne Forklift S/N: 72494 C/W: 2 Stage Mast, Full Free Lift, Lift Height, 81 in Lowered Mast He Forks, Side Shift, Solid Pneumatic US EPA Label, CARB Compliant, T 4 Cylinder 38 kW 2.23 L LPG Engine	S/N: 94056 C/W: 3 Stage Mast, 131 in Max Lift Height, 24 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 11,841 Hr
	Asset located in: Lake Worth, TX		
6390	2016 Cat GP25N2-LE 5000 lb Pneumatic Tire Forklift S/N: AT35A02417 C/W: 3 Stage Mast, 83 in Lowered Mast Height, 60 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2016 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 4,117 Hr Asset located in: Midland, TX		S/N: 8FGU25-67336 C/W: 2 Stage Mast, 131.5 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 10,669 Hr
6391	2004 Cat P5000 Pneumatic Tire Forklift S/N: AT3500741 C/W: 3 Stage Mast, Full Free Lift, 46 in Forks, Side Shift, Solid Pneumatic Tires, 2004 US EPA Label, Nissan 4NSXB02.5 4 Cylinder 61.5 hp 2.5 L LPG Engine, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		
6391A	Hyundai G25SP-3 5000 lb Pneumatic Tire Forklift S/N: D201409 C/W: 3 Stage Mast, 186 in Max Lift Height, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, Daewoo G430-LP 4 Cylinder LPG Engine Usage: 9,190 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6398	2024 Viper FY30T 4795 lb Pneumatic Tire Forklift (Unused) S/N: 23L3000549 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Hyundai 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX	6401A	2015 Doosan D25S-7 4200 lb Pneumatic Tire Forklift S/N: FDA00193000440 C/W: 2 Stage Mast, 163 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, 4 Cylinder Engine Usage: 3,385 Hr Asset located in: Lake Worth, TX
6398A	Heli 4600 lb Pneumatic Tire Forklift S/N: 25025117944 C/W: 3 Stage Mast, 75 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder 3.0 L Dual Fuel Engine Usage: Not Available Asset located in: Lake Worth, TX	6402	1994 Hyster H40XM 4000 lb Pneumatic Tire Forklift S/N: D177G9392R C/W: 3 Stage Mast, 153 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Isuzu 4 Cylinder Diesel Engine Usage: 2,238 Hr
6399	2014 Komatsu FG25HT-16 4650 lb Pneumatic Tire Forklift S/N: A260155 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2014 US EPA Label, GCT 4 Cylinder 2.5 L Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,436 Hr	6403	Asset located in: Lake Worth, TX Komatsu FG25 3990 lb Pneumatic Tire Forklift S/N: 144043A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 24 in Lowered Mast Height, 46 in Forks, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 4,607 Hr Asset located in: Lake Worth, TX
6399A	Asset located in: Humble, TX 2016 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 78142 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 87 in Lowered Mast Height, 48 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L Dual Fuel Engine Usage: 4,861 Hr Asset located in: Lake Worth, TX	6404	Nissan PJ02A25PV 3975 lb Pneumatic Tire Forklift S/N: PJ029H3529 C/W: 3 Stage Mast, 188 in Max Lift Height, 86 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 13,012 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6400	2015 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 67140 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 81 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4YECS 2.2 L Dual Fuel Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	6405	2024 Viper FY25BCS 3900 lb Pneumatic Tire Forklift (Unused) S/N: 222010033 C/W: 3 Stage Mast, 189 in Max Lift Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Mitsubishi 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX 2024 Viper FY25C 3900 lb Pneumatic Tire
6401	Notes: . Asset located in: Lake Worth, TX 2019 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 94048 C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2 2 L LPG Engine		Forklift (Unused) S/N: 222011086 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Kubota WG2503 4 Cylinder 41 kW 2.5 L LPG Engine Usage: 3 Hr Asset located in: Lake Worth, TX Heli CPYD25 3900 lb Pneumatic Tire Forklift
	4 Cylinder 38 kW 2.2 L LPG Engine Usage: 28,396 Mi Asset located in : Lake Worth, TX	6407	S/N: 2302574499 C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6407A	1997 Mitsubishi FG30 5300 lb Pneumatic Tire Forklift S/N: AF13D30869 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 83 in Lowered Mast Height, 41 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: 2,369 Hr	6414	2013 Toyota 7FGCU45 Cushion Tire Forklift S/N: 72832 C/W: 3 Stage Mast, Full Free Lift, 47 in Forks, Auxiliary Hydraulic Plumbing, LPG Engine Usage: 7,006 Hr Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6415	2017 Cat 2C6000 5750 lb Cushion Tire Forklift
6408	1989 Clark GPS25MB 3800 lb Pneumatic Tire Forklift S/N: GP138MB03476968K0F C/W: 2 Stage Mast, 196 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1,200 Hr		S/N: AT83F42218 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6416	2017 Cat 2C6000 5750 lb Cushion Tire Forklift
6409A	2015 Doosan D25S-7 3650 lb Pneumatic Tire Forklift S/N: FDA0Q-1930-01126 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Solid Pneumatic Tires, 4 Cylinder Diesel		S/N: AT83F42219 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 53 in Forks, Side Shift, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Engine	6419	2015 Toyota 8FGCU30 5820 lb Cushion Tire
	Usage: 2,689 Hr Asset located in: Lake Worth, TX		Forklift
6410	2002 Komatsu FG15HC-16 2500 lb Pneumatic Tire Forklift S/N: 652910A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan		S/N: 62544 C/W: 2 Stage Mast, 147 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Side Shift, 2017 US EPA Label, Toyota 37 kW 1.79 L Diesel Engine Usage: 5,361 Hr Asset located in: Lake Worth, TX
	4 Cylinder Gasoline Engine Usage: 9,201 Hr Asset located in : Lake Worth, TX	6420	2011 Toyota 8FGCU25 7500 lb Cushion Tire Forklift
6410A	Crown Cushion Tire Forklift S/N: Not Available C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, John Deere 4 Cylinder LPG Engine Usage: 6,624 Hr Asset located in: Lake Worth, TX		S/N: 31741 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 36 kW 2.23 L LPG Engine Usage: 2,786 Hr Asset located in: Lake Worth, TX
6412	2021 Yale GLC155VX 10000 lb Cushion Tire Forklift S/N: F879V02837V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available	6421	Toyota 2600 lb Cushion Tire Forklift S/N: 74438 C/W: 3 Stage Mast, 258 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Toyota 4YECS LPG Engine Usage: 5,098 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6422	2021 Mitsubishi FGC25N 5000 lb Cushion Tire
6413	2021 Yale GLC155VX 10000 lb Cushion Tire Forklift S/N: F879V02836V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX		Forklift S/N: AF82F50153 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Load Weigh System, 2021 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,245 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6423	2021 Mitsubishi FGC25N4 5000 lb Cushion Tire Forklift S/N: AF82F50026 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 56 in Forks, Load Weigh System, 2022 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,534 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6427	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19411W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: . Asset located in: Humble, TX 2022 Hyster S50FT 4800 lb Cushion Tire
6424	2021 Mitsubishi FGC25N 5000 lb Cushion Tire Forklift S/N: AF82F49734 C/W: 2 Stage Mast, Full Free Lift, 80 in Max Lift Height, 58 in Lowered Mast Height, 60 in Forks, Side Shift, Tier 2, 2021 US EPA Label, CARB Compliant, 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 3,757 Hr Asset located in: Lake Worth, TX	6429	Forklift S/N: H187V19408W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2022 Hyster S50FT 4800 lb Cushion Tire
6424A	2013 Linde H25CT 5000 lb Cushion Tire Forklift S/N: A1131D00241 C/W: 2 Stage Mast, Full Free Lift, 180 in Max Lift Height, 81 in Lowered Mast Height, 41 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 10,212 Hr Asset located in: Lake Worth, TX		Forklift S/N: H187V19417W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6424B	Komatsu FG25C-11 5000 lb Cushion Tire	1	Asset located in: Humble, TX
6425	Forklift S/N: 463417A C/W: 2 Stage Mast, 128 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Nissan 4 Cylinder Gasoline Engine Usage: 5,084 Hr Asset located in: Lake Worth, TX	6430	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19410W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available
6425	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19416W		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6426	C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2022 Hyster S50FT 4800 lb Cushion Tire	6431	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19409W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
0420	Forklift S/N: H187V19413W		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6432	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19415W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6433	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19412W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6439	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19401W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: Asset located in: Humble, TX
6434	2020 Yale GLC050VX 4750 lb Cushion Tire Forklift S/N: C910V14422U C/W: 3 Stage Mast, 189 in Max Lift Height, 58 in Lowered Mast Height, 56 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX 2020 Yale GC050VX 4750 lb Cushion Tire	6440	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19414W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
0400	Forklift S/N: C910V14424U C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 58 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6441	THE INSPECTION REPORT Asset located in: Humble, TX 2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19400W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in
6436	2006 Yale GLC050VXNVSE083 4700 lb Cushion Tire Forklift S/N: A910V06226D C/W: 3 Stage Mast, 189 in Max Lift Height, 80 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: Not Available		Forks, Side Shift, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6437	Asset located in: Lake Worth, TX 2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19418W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19406W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6438	Asset located in: Humble, TX 2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19419W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: Asset located in: Humble, TX	6443	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19407W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6443A	2017 Toyota 8FGCU25 4600 lb Cushion Tire Forklift S/N: 85179 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 87 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 1,226 Hr Asset located in: Lake Worth, TX	6446D	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 72623 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 3,747 Hr Asset located in: Lake Worth, TX
6443B	2017 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 84139 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 7,442 Hr	-6447	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 70241 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 6,085 Hr Asset located in: Lake Worth, TX
6444	Asset located in: Lake Worth, TX 2017 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 83017 C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 5,739 Hr Asset located in: Lake Worth, TX	6447A	2014 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 62161 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 5,663 Hr Asset located in: Lake Worth, TX
6444A	2016 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 80050 C/W: 3 Stage Mast, 189 in Max Lift Height, 76 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 5,987 Hr Asset located in: Lake Worth, TX	-6448	2007 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 12090 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2007 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 4,459 Hr Asset located in: Lake Worth, TX
6446B	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 72871 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.3 L LPG Engine Usage: 1,944 Hr Asset located in: Lake Worth, TX	6448A	2010 Doosan GC25P-5 4450 lb Cushion Tire Forklift S/N: MW00736 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift, 2010 US EPA Label, Woodward 4 Cylinder 2.4 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
6446C	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 67976 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 6,206 Hr Asset located in: Lake Worth, TX	6448B	2015 Doosan GC25E-5 4300 lb Cushion Tire Forklift S/N: FGA0L179001251 C/W: 3 Stage Mast, Full Free Lift, 76 in Max Lift Height, 189 in Lowered Mast Height, 40 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2015 US EPA Label, Woodward 4 Cylinder 2.4 L LPG Engine Usage: 6,001 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6449	Heli CPYD25C-KU1H 4190 lb Cushion Tire Forklift S/N: 23025N7358 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6454B	2015 Toyota 8FGCU15 2500 lb Cushion Tire Forklift S/N: 31743 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4Y ECS 4 Cylinder 36 kW 2.23 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
6450	Heli CPYD25C-KU1H Cushion Tire Forklift S/N: 230252P8451 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6454C	2017 Toyota 8FGCU25 1700 lb Cushion Tire Forklift S/N: 83746 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 94 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 6,964 Hr
6451	Heli CPYD25C-KU1H 4080 lb Cushion Tire Forklift		Asset located in: Lake Worth, TX
	S/N: 230252P8453 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6454D	Tusk 500CG-16 3975 lb Cushion Tire Forklift S/N: 590948A C/W: 3 Stage Mast, 188 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2005 US EPA Label, Nissan 4 Cylinder 55 hp 2.1 L LPG Engine Usage: Not Available
6452	Heli CPYD25C-KU1H 4080 lb Cushion Tire		Asset located in: Lake Worth, TX
	Forklift S/N: 230252P8452 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6456	1989 Nissan CPF02A25V Cushion Tire Forklift S/N: CPH02026383 C/W: EQUIPMENT FROM CENTRAL FREIGHT LINES INC Usage: Not Available Asset located in: Lake Worth, TX
6453	2014 Toyota 8FGCU20 4000 lb Cushion Tire Forklift S/N: 8FGCU25-64619 C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in Lowered Mast Height, 36 in Forks, Side Shift, Toyota 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6457	2012 Toyota 7FGCU35 4900 lb Pneumatic Tire Forklift S/N: 72810 C/W: 4 Stage Mast, Full Free Lift, 230 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Solid Pneumatic Tires, PSI 4 Cylinder LPG Engine Usage: 9,584 Hr Notes: LOCATED-IN-FORT-WORTH-TX
6454	2005 Komatsu FG20ST-14R 4000 lb Cushion Tire Forklift		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 587879A C/W: 2 Stage Mast, 72 in Max Lift Height, 55 in Lowered Mast Height, 48 in Forks, Load Weigh System, 2006 US EPA Label, Nissan 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW- CORP Usage: 19,433 Hr Asset located in: El Paso, TX 2002 Daewoo GC15S-2 2550 lb Cushion Tire	6458	Asset located in: Lake Worth, TX 2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36479 C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available
U404A	Forklift		Asset located in: Lake Worth, TX
	S/N: D100192 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, 2002 US EPA Label, DAEWOO G420 4 Cylinder LPG Engine Usage: 9,145 Hr Asset located in: Lake Worth, TX	6459	2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36483 C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6460	2013 Raymond 960-CSR30TT 3000 lb Electric Order Picker S/N: 9601302364 C/W: 2 Stage Mast, 250 in Max Lift Height, 130 in Lowered Mast Height, 24 V Usage: Not Available	6468	2024 JQ POWER JQ2T-MAX 2000 kg Electric Forklift (Unused) S/N: 24482052 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 64 V, Battery Charger Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6461	2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36471 C/W: 2 Stage Mast, Full Free Lift, 240 in Max Lift Height, 106 in Lowered Mast Height, 42 in Forks, 24 V, Battery Watering System Usage: Not Available Asset located in: Lake Worth, TX	6469	2024 STL Industrial STL2TN Electric Forklift (Unused) S/N: DM202401A06213 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 29 Hr Asset located in: Lake Worth, TX
6462	2024 STL Industrial STL3TN Electric Forklift (Unused) S/N: 01A06131 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 5 Hr Asset located in: Lake Worth, TX	6470	2024 STL Industrial STL1TN Electric Forklift (Unused) S/N: 24A0235 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift Usage: Not Available Asset located in: Lake Worth, TX
6463	2017 Raymond 4750C50 4850 lb Electric Forklift S/N: 4751710850 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 81 in Lowered Mast Height, 42 in	6474	2025 STL Industrial Electric Forklift S/N: DM202401A06206 C/W: 2 Stage Mast, 48 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 26 Hr Asset located in: Lake Worth, TX
	Forks, Side Shift, 36 V, Battery Watering System Usage: 5,947 Hr Asset located in: Lake Worth, TX		2011 Toyota 7FBCU18 2900 lb Electric Forklift S/N: Not Available Usage: Not Available
6464	2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused) S/N: 24482054 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Humble, TX Cat R80 2800 lb Electric Forklift S/N: 4SM01049 C/W: 3 Stage Mast, Full Free Lift, 191 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: 69 Hr
6465	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused)		Asset located in: Lake Worth, TX
	S/N: 24482026 C/W: 2 Stage Mast, 118 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: 3 Km Asset located in: Lake Worth, TX	6476	Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused) S/N: Not Available C/W: One crate Usage: Not Available Asset located in: Lake Worth, TX
6466	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482051 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	6477	Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused) S/N: PHT6206139 C/W: 610 lb Capacity, 24 V, One Crate Usage: Not Available Asset located in: Lake Worth, TX
6467	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482008 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	6478	2012 Raymond 960-CSR30TT 3000 lb Electric Reach Truck S/N: 9601202198 C/W: 2 Stage Mast, 250 in Max Lift Height, 130 in Lowered Mast Height, 24 V Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6479	2016 Jungheinrich ETR340 4000 lb Reach Truck S/N: 82820438 C/W: 2 Stage Mast, 302 in Max Lift Height, 42 in Forks, 36 V, Battery Charger, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 5,007 Hr Notes: . Asset located in: Lake Worth, TX	6486	2013 Genie S125 4WD Diesel Telescopic Boom Lift S/N: S12513D505 C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, Deutz td2011 4 Cylinder 74 hp 3.6 L Diesel Engine, 445 /50D710 Tires Usage: 3,738 Hr Notes: AERIAL UNITS REQUIRE PROPER
6480	Crown RR5700 Order Picker S/N: Not Available Usage: Not Available		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6481	Asset located in: Lake Worth, TX 2012 Moffett P6000 6000 lb 3x3 Truck Mounted Forklift S/N: L270049 C/W: 3 Stage Mast, 124 in Max Lift Height, 78 in Lowered Mast Height, 74 in Forks, Fork Rotation, Tier 4, 2012 US EPA Label, Kubota V2203 4 Cylinder 2.2 L Diesel Engine Usage: 1,732 Hr Asset located in: Humble, TX	_6487	2012 Genie S-125 4WD Diesel Telescopic Boom Lift S/N: S125123373 C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, Deutz TD2011L04 4 Cylinder 3.6 L Diesel Engine Usage: 4,191 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6482	2013 Navigator RT5500 5500 lb 3x3 Truck Mounted Forklift		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	S/N: 413847 C/W: 2 Stage Mast, 144 in Max Lift Height, 93 in Lowered Mast Height, 48 in Forks, Side Shift, Kubota 4 Cylinder 2.0 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	6488	2002 Genie S-125 Telescopic Boom Lift S/N: S125525 C/W: 125 m Max Lift Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine, 445/65D22.5 Tires Usage: 5,200 Hr
6483	2013 Princeton PB50X 5000 lb 3x3 Truck Mounted Forklift		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	S/N: M480268C C/W: Single Stage Mast 24 in Lowered Mast Height, 47 in Forks, Tier 4, 2012 US EPA Label, Kubota v2203 4 Cylinder 35 kW 2.2 L Diesel Engine Usage: 2,060 Hr Asset located in: Lake Worth, TX	6489	Asset located in: Midland, TX 2018 Genie S-85 XC 4WD Diesel Telescopic Boom Lift S/N: S85XCH-262 C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform,
6484	2013 Moffett M50 Lite 5000 lb 3x3 Truck Mounted Forklift S/N: M220415A C/W: Single Stage Mast 12 in Max Lift Height, 1 in Lowered Mast Height, 48 in Forks, Side Shift, Kubota 4 Cylinder 1.5 L Diesel Engine Usage: 3,850 Hr Asset located in: Lake Worth, TX		Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Tires Usage: 3,157 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6485	2021 Combilift COMBI-RT 3000 lb 3x3 Rough Terrain Forklift S/N: 55866 C/W: 2 Stage Mast, 124 in Max Lift Height, 24 in Lowered Mast Height, 72 in Forks, Side Shift, 2020 US EPA Label, Deutz TD2.9L4 4 Cylinder 55 kW 2.9 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	 6490	2018 Genie S85XC 4WD Diesel Telescopic Boom Lift S/N: S85XCH260 C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2017 US EPA Label, Deutz TD 2.9 LP 4 Cylinder 2.95 L Diesel Engine, 18-625NHS Tires Usage: 4,567 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6491	2011 Genie S85 4WD Diesel Telescopic Boom Lift S/N: S85118854 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2011 US EPA Label, Deutz 4 Cylinder 74 hp 3.6 L Diesel Engine, 18-625 Tires Usage: 2,485 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX	6496	2014 Genie S-80X Telescopic Boom Lift S/N: S80X14-12022 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,561 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2014 Genie S-80X 4WD Diesel Telescopic Boom Lift
6492	2010 Genie S85 4WD Diesel Telescopic Boom	1	S/N: S80X1412022 C/W: 80 ft Max Platform Height, 500 lb Max
	Lift S/N: S85108432 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, 2010 US EPA Label, Deutz TD 2011L04l 4 Cylinder 3.61 L Diesel Engine, 18-625NHS Tires Usage: 5,544 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6499	Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,562 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2012 JLG 800S 4WD Diesel Telescopic Boom Lift
6493	2018 Haulotte HT85RT 4WD Diesel Telescopic Boom Lift S/N: 2030133 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 4 Cylinder Diesel Engine Usage: 1,938 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: 0300158033 C/W: 80 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2011 US EPA Label, Deutz D2011L04 4 Cylinder 3.6 L Diesel Engine Usage: 2,352 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6494	Asset located in: Lake Worth, TX 2017 Haulotte HT85RTJ PRO 4WD Diesel		Haulotte HT67RTJ Telescopic Boom Lift S/N: TD500215
0494	Telescopic Boom Lift S/N: 2021508 C/W: 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2016 US EPA Label, Kubota V2607 4 Cylinder 2.6 L Diesel Engine Usage: Not Available		Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300236291 C/W: 65 ft Max Platform Height, 750 lb Max
6495	Asset located in: Lake Worth, TX 2015 Snorkel TB85J 4WD Diesel Telescopic		Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp
U+30	Boom Lift S/N: TB85J-04-000049 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Kubota V2403 4 Cylinder 44 kW 2.4 L Diesel Engine, 15-625 Tires Usage: 4,173 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 748 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6501	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300236292 C/W: 65 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,928 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6506	2015 Genie S60X 4WD Diesel Telescopic Boom Lift S/N: S60X15A-29654 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D 2.9 L4 49 hp 2.92 L Diesel Engine, 355/55D625 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,781 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6502	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300233965 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,192 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6507	2017 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 300236812 C/W: 59 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,026 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6503	2016 Genie S-65 4WD Dual Fuel Telescopic Boom Lift S/N: S6016H-35454 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, CARB Compliant, 4 Cylinder 64.3 kW 2.5 L Dual Fuel Engine, 355/55D625 NHS Tires Usage: 3,590 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	-6508	2017 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 300229396 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,530 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6504	2012 Genie S-65 Telescopic Boom Lift S/N: S6012-23502 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6509	2017 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300233241 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 Foam-Filled Tires, EQUIPMENT-FROM-
6505	Lift S/N: S60XH-37752 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, CARB Compliant, Deutz D2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355 /55D625 NHS Tires Usage: 2,105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX		SUNSTATE-EQUIPMENT Usage: 6,286 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6510A	2006 Genie S60 4WD Diesel Telescopic Boom Lift S/N: S600614228 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Diesel Engine, 355/55D625 Tires Usage: 973 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Humble, TX 2017 JLG 460SJ 4WD Diesel Telescopic Boom	6514	2015 Genie S40 4WD Diesel Telescopic Boom Lift S/N: S4015-20737 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,771 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Lift S/N: 0300236779 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, Deutz D 2.9 L4 36.4 kW 2.9 L Diesel Engine, 1417.5 NHS Tires Usage: 3,690 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6515	2017 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300236550 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6511	2019 Skyjack SJ45T 4WD Diesel Telescopic Boom Lift S/N: 98003735 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Deutz Diesel Engine Usage: 2,136 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR	6516	2016 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300211074 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,626 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6513	2007 Snorkel TB42DZ 4WD Diesel Telescopic Boom Lift S/N: MR07088RBLT C/W: 42 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2008 US EPA Label, Deutz F3L2011 3 Cylinder 48 hp 2.33 L Diesel Engine, 12.16.5N Tires Usage: 3,176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6517	2016 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300210880 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 4,719 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6518	2015 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300209072 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,731 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6522	2014 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300191770 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,228 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6519	2015 JLG 400S 4WD Telescopic Boom Lift		Asset located in: Lake Worth, TX
0017	S/N: 0300204969 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, Deutz 4 Cylinder Diesel Engine, 12- 16.5 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,775 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK	6523	2014 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300192112 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,661 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6520	2015 JLG 400S 2WD Diesel Telescopic Boom		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6504	Lift S/N: 0300210976 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, 2015 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 14-17.5 NHS Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,245 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6524	2016 Haulotte HA130RTJPRO 4WD Diesel Articulating Boom Lift S/N: AD127595 C/W: 129 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Perkins Engine Usage: 3,370 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6521	2015 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300208881 C/W: 40 ft Max Platform Height, 600 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 4,536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6525	2015 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300198551 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Tires Usage: 3,975 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6526	2018 JLG 600AJ 4WD Diesel Articulating Boom Lift S/N: 0300239502 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz 2.9l4 4 Cylinder 67 hp 2.9 L Diesel Engine Usage: 1,081 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6531	2015 Snorkel A46JRT 4WD Diesel Articulating Boom Lift S/N: A46JRT-04-000348 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505 4 Cylinder 18.5 kW 1.5 L Diesel Engine, 355/55D62.5 Tires Usage: 1,226 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6527	2011 JLG 600AJ 4WD Diesel Articulating	6532	Skyjack SJ46AJ 4WD Diesel Articulating Boom
	Boom Lift S/N: 0300143499 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2010 US EPA Label, Deutz D2011L4 4 Cylinder 3.1 L Diesel Engine, 355/55D625 Tires Usage: 4,083 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Lift S/N: 95000588 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine Usage: 2,493 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6504	<u> </u>
6528	2015 Snorkel AB60J Articulating Boom Lift S/N: AB60J-04-000082 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	653 4	2012 JLG 450AJ 4WD Articulating Boom Lift S/N: 0300161279 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D2011 3 Cylinder 49 hp 2.3 L Diesel Engine, 33X15.50 Tires Usage: 3,162 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6529	2014 Genie Z-60/34 4WD Diesel Articulating Boom Lift		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6530	S/N: Z601414246 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Deutz D2011L03I 4 Cylinder 49 hp Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,716 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2014 Genie Z60/34 Articulating Boom Lift	6535	2015 Genie Z-45/25J 2WD Electric Articulating Boom Lift S/N: Z452515A54948 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,406 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	S/N: Z6014-14246	1701	·
	C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,714 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6536	Boom Lift S/N: Z452515A-53530 C/W: 24 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz U2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 315/55D20 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,249 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
6537	2014 Genie Z45/25 2WD Electric Articulating Boom Lift S/N: Z452514A52188 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam- Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6543	2017 Genie Z-33/18 2WD Electric Articulating Boom Lift S/N: Z3318M1589 C/W: 32 ft Max Platform Height, 440 lb Max Weight Capacity, Power to Platform, 22X9 Solid Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 619 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6538	2012 Genie Z40/23NRJ 2WD Electric	6544	2015 JLG E300 AJP 2WD Electric Articulating
	Articulating Boom Lift S/N: Z40N12-1774 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 25.6 X7 Non-Marking Tires Usage: 1,120 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Boom Lift S/N: 0300203331 C/W: 30 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 823 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6539	Asset located in: Lake Worth, TX 2012 Genie Z40/23NRJ 2WD Electric	6545	Asset located in: Lake Worth, TX 2018 JLG T500J Electric Towable Lift
	Articulating Boom Lift S/N: Z40N12-1683 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22X7X17 Non-Marking Tires Usage: 1,393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: 0030009466 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 37 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6546	2018 JLG T500J Electric Towable Lift S/N: 5DYACJ1J3JF009464
6540	2012 Genie Z40/23NRJ Articulating Boom Lift S/N: Z40N12-1786 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 50 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6541	2012 Genie Z40/23NRJ Articulating Boom Lift S/N: Z40N12-1775 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2012 Genie Z40/23NRJ Articulating Boom Lift	6547	2018 JLG T500J Electric Towable Lift S/N: 5DYACJ1J5JF009465 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 55 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	S/N: Z40N12001797	6548	2014 JLG T500J Towable Lift
	Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 0030008920 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 182 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6550	Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40002479 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,620 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6553A 6554	2013 JLG M4069 4x4 Hybrid Scissor Lift S/N: 0200217745 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2012 US EPA Label, Kubota 1 Cylinder 0.2 L Diesel Engine Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX 2007 JLG 3394RT Scissor Lift
6551	·		S/N: 200164159 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Platform, Stabilizers, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,292 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6555	2017 Genie GS3390RT 4x4 Dual Fuel Scissor Lift S/N: GS90F-54078 C/W: 2500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, 2017 US EPA Label, 4 Cylinder 64.3 kW 2.5 L LPG Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,011 Hr
6552	2015 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40001765		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK
	C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2015 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,788 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6556	2015 Genie GS-3369RT Scissor Lift S/N: GS6915-7051 Usage: 1,360 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6557	2015 Genie GS-3369RT Scissor Lift S/N: GS6915-7099
6553	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40001309 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, Kubota WG972 3 Cylinder Dual Fuel Engine Usage: 2,649 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Usage: 1,738 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
		6558	Lift S/N: 37010203 C/W: 32 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2016 US EPA Label, Kubota WG752-GL-ET 3 Cylinder 740 cc Dual Fuel Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,144 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6560	2015 Genie GS-2669RT 4x4 LPG Scissor Lift S/N: GS6915-7055 C/W: 26 m Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2014 US EPA Label, Kubota WG972-GL-ET 3 Cylinder LPG Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,044 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6565	2013 JLG 4069LE Electric Scissor Lift S/N: 0200219769 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 694 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2017 Genie GS-4047 Electric Scissor Lift
	Asset located in: Oklahoma City, OK	6566	S/N: GS47P-1728
6561	2017 Skyjack SJ6826 RT Scissor Lift S/N: 37010550 Usage: 1,397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
4740	Asset located in: Lake Worth, TX	4=4=	Asset located in: Oklahoma City, OK
6562	2017 Skyjack SJ6826 RT Dual Fuel Scissor Lift S/N: 37010717 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Foam Filled Tires, Upper Control Box, Kubota WG752- GL - ET 3 Cylinder 740.5 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,991 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6567	2017 Genie GS-4047 Scissor Lift S/N: GS47P-1715 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 478 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD;		2017 Genie GS-4047 Electric Scissor Lift
6562A	Asset located in: Lake Worth, TX 2000 Skyjack SJ8841RT Scissor Lift S/N: 42378 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: GS47P1715 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 479 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6563	2014 JLG M4069LE Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 0200238747 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6569	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1734 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 502 Hr Notes: AERIAL UNITS REQUIRE PROPER
6564	2013 JLG M4069LE 4x4 Diesel Scissor Lift S/N: 0200217747 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Power Inverter, Solid Non-Marking Tires, Upper Control Box, Tier 4, 2012 US EPA Label, Kubota 0C60-ET01 1 Cylinder 0.27 L Diesel Engine Usage: 276 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK

		I	
Lot #	Details	Lot #	Details
6570	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1802 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 504 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6575	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1678 C/W: 39 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 615 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6571	2017 Genie GS-4047 Electric Scissor Lift	6576	2017 Genie GS-4047 Electric Scissor Lift
	S/N: GS47P1430 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 509 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS47D6070 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6572	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1824 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 594 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6577	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P2225 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6573	2017 Genie GS-4047 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS47P1822 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 628 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6578	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-1545 C/W: 20 ft Max Platform Height, 550 lb Max Weight Capacity, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 498 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6574	2017 Genie GS-4047 Scissor Lift S/N: GS47P-1822 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 628 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	-6579	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1620 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 499 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6580	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-3104 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 500 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6584A	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1543 C/W: 39 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6581	2016 Genie GS-4047 Scissor Lift S/N: GS4716D-1513 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 589 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	- 6585	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1286 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6582	2016 Genie GS-4047 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS4716D1580 C/W: 40 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 590 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6586	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1278 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 534 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6583	2016 Genie GS-4047 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS4716D-2977 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 627 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6587	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1054 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 788 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
6584	2016 Genie GS-4047 Electric Scissor Lift	6588	Skyjack SJIII-4740 Electric Scissor Lift
3337	S/N: GS4716D-1511 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 633 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 70202991 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

		_	
Lot #	Details	Lot #	Details
6589	Skyjack SJIII-4740 Electric Scissor Lift S/N: 70202542 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 515 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6594	2015 JLG 3248RS Electric Scissor Lift S/N: 0200237506 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 480 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6590	2017 Skyjack SJIII4740 Electric Scissor Lift	6E0E	2015 JLG 3248RS Electric Scissor Lift
	S/N: 70201795 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Stabilizers, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6595	S/N: 0200243786 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 538 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6591	Skyjack SJIII-4740 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 349 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6597	2017 Snorkel S4732E Electric Scissor Lift S/N: S4732E-04-900112 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT FROM UNITED RENTALS Usage: 180 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6592	2017 MEC 4046SE Electric Scissor Lift S/N: 16700245 C/W: 38 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6598	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P-143973 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6599	2017 Genie GS-3246 Electric Scissor Lift
6593	2017 MEC 4046SE Electric Scissor Lift S/N: 16700250 C/W: 38 ft 7 in Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: 143969 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 114 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

		1	
Lot #	Details	Lot #	Details
6600	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P-143947 C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 290 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6604A	2017 Genie GS3246 Electric Scissor Lift S/N: GS46P143724 C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6601	2017 Genie GS-3246 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS46P143978 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 335 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6605	2015 Genie GS-3246 Scissor Lift S/N: GS4615-137265 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 362 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6606	2015 Genie GS-3246 Electric Scissor Lift
6602	2017 Genie GS-3246 Scissor Lift S/N: GS46P-143966 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 337 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	_	S/N: GS4615A137584 C/W: 33 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 484 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6603	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P143966		Asset located in: Lake Worth, TX
	C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 337 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6607	2017 JLG 3246ES Electric Scissor Lift S/N: 0200263928 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 59 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6604	2017 Genie GS3246 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS46P143806 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 297 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6608	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266401 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 81 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6609	2017 JLG 3246ES Scissor Lift S/N: 0200266190 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 189 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6614	S/N: M200013176 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE: EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	S/N: M200013176 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6610	10 2017 JLG 3246ES Electric Scissor Lift S/N: 0200263931 C/W: 31 ft Max Platform Height, 750 lb Max		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 206 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		2017 JLG 3246ES Electric Scissor Lift S/N: 0200266205 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER	
6611	Asset located in: Lake Worth, TX 2017 JLG 3246ES Scissor Lift	1	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	
	S/N: 0200266023 C/W: EQUIPMENT-FROM-SUNSTATE-		Asset located in: Lake Worth, TX	
6612	EQUIPMENT Usage: 328 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2017 JLG 3246ES Electric Scissor Lift	6616	2015 JLG 3246ES Electric Scissor Lift S/N: M200001109 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE EQUIPMENT Usage: 413 Hr	
	S/N: M200013247 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 401 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2017 JLG 3246ES Electric Scissor Lift S/N: M200013175 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 425 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
6613	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266207 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper			
	Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 402 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6618	2017 JLG 3246ES Electric Scissor Lift S/N: M200013211 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
6619	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266209 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6624	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70017904 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 289 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
6620	2017 JLG 3246ES Electric Scissor Lift S/N: M200013245 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	-6625	2015 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70022067 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6626	2015 Skyjack SJIII 4632 Scissor Lift S/N: 70022705	
6621	2016 JLG 3246ES Electric Scissor Lift S/N: M200000621 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT	6627	Usage: 419 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2014 Skyjack SJIII 4632 Electric Scissor Lift	
	Usage: 492 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 70019200 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER	
6622	2017 Skyjack SJIII-4632 Electric Scissor Lift S/N: 80180032		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	
	C/W: 32 ft Max Platform Height, 750 lb Max		Asset located in: Lake Worth, TX	
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6628	S/N: 70019482 C/W: 32 ft Max Platform Height, 70 Weight Capacity, Platform Extension Platform, Solid Non-Marking Tires, Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PR SAFETY HARNESS, LANYARD, AND	C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6623	2019 Skyjack SJIII4632 Electric Scissor Lift S/N: 70041193		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 189 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6629	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70019116 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6630	2014 Skyjack SJIII4632 Electric Scissor Lift S/N: 70017856 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 339 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6636	2017 Genie GS-3232 Electric Scissor Lift S/N: GS32P-148830 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 509 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6631	Skyjack SJIII 4632 Electric Scissor Lift S/N: Not Available C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 325 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6637	2017 Genie GS-3232 Electric Scissor Lift S/N: GS32P148756 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6632	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70018708 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension Usage: 358 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6638	2017 Genie GS3232 Electric Scissor Lift S/N: GS32P-149344 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6633	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70018805 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 358 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6640	2015 Genie GS3232 Electric Scissor Lift S/N: GS3215A141191 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 465 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6634	2018 Genie GS3232 Electric Scissor Lift S/N: GS32P-157610 C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6641	Asset located in: Lake Worth, TX 2015 Genie GS-3232 Electric Scissor Lift S/N: 141232 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 398 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6635	2017 Genie GS3232 Electric Scissor Lift S/N: GS32P-154160 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	FUNCTION TEST AND LOA	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

	Details	l ot #	Dataila
Lot #	Details	Lot #	Details
6642	2014 Genie GS-3232 Electric Scissor Lift S/N: 135791 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6647	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70022572 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 200 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6643	2018 Snorkel S4726E Electric Scissor Lift	6648	2015 Skyjack SJIII4626 Electric Scissor Lift
0043	S/N: S4726E-04-180500837 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 109 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: 70022293 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 240 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6644	2017 JLG 2646ES Electric Scissor Lift	6649	2015 Skyjack SJIII4626 Electric Scissor Lift
	S/N: M200007467 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 291 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6650	S/N: 70022355 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 260 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6645	2015 JLG 2646ES Electric Scissor Lift	70030	2015 Skyjack SJIII4626 Electric Scissor Lift S/N: 70021519
	S/N: M200001100 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 477 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 282 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6651	2014 Skyjack SJIII4626 Electric Scissor Lift
6646	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70026601 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: 70021343 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 410 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6652	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263898 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 328 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6657	2015 JLG 2646ES Electric Scissor Lift S/N: M200000271 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6653	2017 JLG 2646ES Electric Scissor Lift	6658	2015 Genie GS2646 Electric Scissor Lift
	S/N: 0200263463 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 375 Hr Notes : AERIAL UNITS REQUIRE PROPER		S/N: 137357 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 246 Hr Notes : AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6654	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263458 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr	6659	2015 Genie GS2646 Electric Scissor Lift S/N: GS4615A136705 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 362 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6655	2016 JLG 2646ES Electric Scissor Lift S/N: M200001128 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 227 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6660	2015 Genie GS-2646 Electric Scissor Lift S/N: GS4615A137346 C/W: 25 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lake Worth, TX
6656	2015 JLG 2646ES Electric Scissor Lift S/N: M200001101 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 373 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6661	2015 Genie GS-2646 Electric Scissor Lift S/N: GS4615A137130 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

			1 age 310 01 307
Lot #	Details	Lot #	Details
6662	2016 Genie GS-2632 Electric Scissor Lift S/N: GS3216P-145511 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 489 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6667	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A140092 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6663	2016 Genie GS-2632 Electric Scissor Lift	6668	2015 Genie GS-2632 Electric Scissor Lift
	S/N: GS3216P145971 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 540 Hr		S/N: GS3215A-138165 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 343 Hr
	Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6664	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140574 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 28 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	6669	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140139 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 404 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6665	2015 Genie GS-2632 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS3215A-140508 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 245 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6670	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A138159 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 424 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6671	2015 Genie GS-2632 Scissor Lift
6666	2015 Genie GS-2632 Scissor Lift S/N: GS3215A-139249 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 312 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: GS3215A-139266 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 435 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6672	2015 Genie GS-2632 Scissor Lift S/N: GS3215A-139149 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 497 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6677	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140565 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6673	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A138162		FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	C/W: 26 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6677A	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A139156 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 525 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6674	2015 Genie GS-2632 Electric Scissor Lift	1	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	S/N: GS3215A137939 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6678	2014 Genie GS-2632 Scissor Lift S/N: GS3214A-136132 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 383 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6679	2014 Genie GS-2632 Electric Scissor Lift
6675	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A140581 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 380 Hr		S/N: GS3214A136069 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 396 Hr Notes : AERIAL UNITS REQUIRE PROPER
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6680	2014 Genie GS-2632 Electric Scissor Lift
6676	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A-139158 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3214A-118609 C/W: 26 ft Max Platform Height, 26 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6681	2013 Genie GS-2632 Electric Scissor Lift S/N: GS3213A116224 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6686	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252789 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6682	2016 JLG 2632ES Electric Scissor Lift	6687	2016 JLG 2632ES Electric Scissor Lift
	S/N: 200252535 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 339 Hr		S/N: M200002023 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 435 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6683	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252837 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr	6688	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252492 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 482 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6684	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252763 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6688A	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252564 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6689	2015 JLG 2632ES Electric Scissor Lift
6685	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252494 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: M200000541 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6690	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244222 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6695	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244248 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 421 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6691	2015 JLG 2632ES Electric Scissor Lift	6696	2015 JLG 2632ES Electric Scissor Lift
	S/N: 0200246996 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 444 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: 0200247096 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes : AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6692	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244228 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 470 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6697	2015 JLG 2632ES Electric Scissor Lift S/N: 0200251446 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 370 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD;		FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6693	2015 JLG 2632ES Electric Scissor Lift S/N: 0200243900 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6698	2015 Skyjack SJ III 3226 Electric Scissor Lift S/N: 27023528 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6699	2014 Skyjack SJIII 3226 Electric Scissor Lift
6694	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244546 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 471 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 27020188 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 299 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6700	2014 Skyjack SJIII-3226 Electric Scissor Lift S/N: 27017585 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 251 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	6705	Hangcha 81XE-II Electric Scissor Lift S/N: Not Available C/W: 400 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2018 Skyjack SJIII-3219 Electric Scissor Lift
6701	2016 JLG 2630ES Electric Scissor Lift S/N: 0200252795 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 388 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6710	S/N: 22135992 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 284 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX Skyjack SJIII-3219 Electric Scissor Lift S/N: 1000025
6702	Asset located in: Lake Worth, TX 2011 JLG 2630ES Electric Scissor Lift S/N: 0200200580 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 369 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	-	C/W: 19 m Max Platform Height, 600 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 161 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6703	Asset located in: Lake Worth, TX 2017 Snorkel S3220E Electric Scissor Lift S/N: S3220E-04-900021 C/W: 20 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6711	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22063947 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 218 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6704	2013 Genie GS2032 Electric Scissor Lift S/N: GS3213A113424 C/W: 20 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 144 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6712	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22060591 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 258 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

		1	
Lot #	Details	Lot #	Details
6713	2019 JLG 1932R Electric Scissor Lift S/N: M200029543 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 83 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6718	2015 JLG 1932RS Electric Scissor Lift S/N: 0200247820 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 409 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6714	2015 JLG 1932RS Scissor Lift	6710	
	S/N: 0200243362 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 332 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6719	2015 JLG 1932RS Electric Scissor Lift S/N: 0200244479 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER
	2015 JLG 1932RS Electric Scissor Lift	-	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6715	S/N: 0200244480		Asset located in: Lake Worth, TX
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 383 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6720	2015 JLG 1932RS Scissor Lift S/N: 0200243355 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 437 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD		FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6716	2015 JLG 1932RS Electric Scissor Lift S/N: 0200243353 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6721	2015 JLG 1932RS Scissor Lift S/N: 0200244472 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 505 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD;	6722	2015 JLG 1932RS Electric Scissor Lift
6717	Asset located in: Oklahoma City, OK 2015 JLG 1932RS Electric Scissor Lift S/N: 0200251219 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 0200243354 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6723	2014 JLG 1932RS Electric Scissor Lift S/N: 200235081 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 158 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6727	2014 JLG 1932RS Scissor Lift S/N: 0200236066 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 460 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6728	2014 JLG 1932RS Scissor Lift S/N: 0200236060
6724	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236585 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 488 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Usage: 373 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6729	2014 JLG 1932RS Scissor Lift S/N: 0200236064 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 490 Hr
6725	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234422 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6730	2014 JLG 1932RS Scissor Lift S/N: 0200235088 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 510 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6725A	2014 JLG 1932RS Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 0200236594 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 623 Hr Asset located in: Lake Worth, TX	6731	JLG 1932RS Electric Scissor Lift S/N: 0200234825 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 520 Hr
6726	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234817 C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Platform, Solid Non-Marking Tires, Upper	6732	2014 JLG 1932RS Electric Scissor Lift
	Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 423 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 0200235386 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
			SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6733	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235121 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6738	2018 Snorkel S3129E Electric Scissor Lift S/N: S3219E-04-181006644 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6734	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234070 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6739	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P168879 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX 2017 Genie GS-1930 Electric Scissor Lift
6735	2014 JLG 1932RS Electric Scissor Lift S/N: 200234879 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 594 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	0740	S/N: GS30P166134 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 65 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6736	Asset located in: Lake Worth, TX 2014 JLG 1932RS Electric Scissor Lift S/N: 0200236058 C/W: 19 m Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6741	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166091 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6737	2016 Snorkel S3219E Electric Scissor Lift S/N: S3219E-04-001508 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 1,362 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	- 6742	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P168863 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6743	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6748 6749	2016 Genie GS-1930 Scissor Lift S/N: GS3016P-159299 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 396 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2016 Genie GS-1930 Electric Scissor Lift
6744	Asset located in: Lake Worth, TX	6750	S/N: GS3016P159321 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 399 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6744	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P-167041 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 438 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		
	FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P153060
6745	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-150796 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 64 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2016 Genie GS-1930 Electric Scissor Lift
6746	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156688 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 312 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: GS3016A-151109 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6752	2016 Genie GS-1930 Electric Scissor Lift
6747	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-151099 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 381 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3016A150812 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6753	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156662 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6757A	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159322 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 544 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6754	2016 Genie GS-1930 Scissor Lift S/N: GS3016P-156662 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6758	2016 Genie GS-1930 Scissor Lift S/N: GS3016P-159736 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6755	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156684 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6759	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159736 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6756	2016 Genie GS-1930 Scissor Lift S/N: GS3016P-156684 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2016 Genie GS-1930 Electric Scissor Lift	6760	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P-159631 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
0/0/	S/N: GS3016A-150674 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 471 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6761	Asset located in: Lake Worth, TX 2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156681 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 603 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

6768	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149270 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146342 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 329 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	S/N: GS3015A149270 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146342 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 329 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6768	S/N: GS3015A-146342 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 329 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
4	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6770	2015 Genie GS-1930 Scissor Lift S/N: GS3015A-145107 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 332 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2015 Genie GS-1930 Scissor Lift S/N: GS3015A-146337
	C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 353 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-148159 C/W: Platform Extension, Power to Platform,
_	C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 360 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	6771

Lot #	Details	Lot #	Details
6772	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146154 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6777	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146331 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6773	2015 Genie GS-1930 Electric Scissor Lift	6778	2015 Genie GS-1930 Electric Scissor Lift
0,,,0	S/N: GS3015A149284 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER	0770	S/N: GS3015A-142980 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 410 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6774	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3016159299 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6779	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145103 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6775	2015 Genie GS-1930 Electric Scissor Lift	6780	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A-149399 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 400 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0700	S/N: GS3015A148246 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
		\dashv	Asset located in: Lake Worth, TX
6776	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146310 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6781	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146258 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 424 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6782	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145084 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6787	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145117 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 442 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6783	2015 Genie GS-1930 Electric Scissor Lift	6788	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A146435 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr		S/N: GS3015A146104 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 443 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lake Worth, TX
6784	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149417 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6789	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-148249 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 448 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX	6790	2015 Genie GS-1930 Electric Scissor Lift
6785	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149321 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: GS3015A146319 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 449 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6791	2015 Genie GS-1930 Electric Scissor Lift
6786	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145121 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 439 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: GS3015A149351 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6792	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146194 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6796	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149305 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 466 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6793	2015 Genie GS-1930 Electric Scissor Lift	6797	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A-145141 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER		S/N: GS3015A149397 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 468 Hr Notes : AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6794	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015149276 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 445 Hr Notes: AERIAL UNITS REQUIRE PROPER	6798	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149413 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 491 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6705		6700	<u> </u>
6795	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149414 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr	6799	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149349 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 493 Hr
	Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6795A	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148197 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6800	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148168 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6801	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146325 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6806	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A142971 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6802	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149391 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 504 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6807	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146318 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6803	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146335 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 408 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6808	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138135 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6804	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149262 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 543 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6809	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A138418 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 412 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6805	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146282 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6810	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138412 C/W: 19 ft Max Platform Height, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6811	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-136463 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 429 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6816	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A136467 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 561 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6812	2014 Genie GS-1930 Electric Scissor Lift	6817	2013 Genie GS-1930 Electric Scissor Lift
	S/N: GS3014A138505 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 453 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		S/N: GS3013A124360 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 367 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD		FUNCTION TEST AND LOAD;
6813	Asset located in: Lake Worth, TX 2014 Genie GS-1930 Electric Scissor Lift	6818	Asset located in: Lake Worth, TX 2013 Genie GS-1930 Scissor Lift
0010	S/N: GS3014A-138417 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 459 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: GS3013A124169 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6814	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138080 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6819	2017 JLG 1930ES Electric Scissor Lift S/N: M200012853 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 324 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6815	2014 Genie GS-1930 Electric Scissor Lift	6820	2017 JLG 1930ES Electric Scissor Lift
	S/N: GS3014A-138082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 464 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: 0200264250 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 392 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6821	2017 JLG 1930ES Electric Scissor Lift S/N: M200012778 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6826	2017 JLG 1930 ES Electric Scissor Lift S/N: 0200264702 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 379 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6822	2017 JLG 1930ES Electric Scissor Lift S/N: M200006460 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 488 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6827	2017 JLG 1930 ES Electric Scissor Lift S/N: M200005469 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6823	2017 JLG 1930ES Electric Scissor Lift S/N: 0200264246 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 525 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6827A	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006504 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 447 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6824	2017 JLG 1930ES Electric Scissor Lift S/N: M200006500 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	-6828 -6829	2016 JLG 1930 ES Electric Scissor Lift S/N: 0200256735 C/W: 18 ft 8 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2017 JLG 1930 ES Electric Scissor Lift
6825	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006381 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 521 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	-10829	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006299 C/W: 18 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 382 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details	
6830	SO 2016 JLG 1930 ES Electric Scissor Lift S/N: M200003881 C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr	6837	2012 JLG 1930ES Scissor Lift S/N: B200004837 Usage: 496 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2020 MEC MICRO 19 Electric Scissor Lift S/N: 16907444 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-	
6832	2016 JLG 1930ES Electric Scissor Lift S/N: M200003701 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 446 Hr		Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 88 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2018 MEC 1330SE Electric Scissor Lift	
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 16301468 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-	
6834	2015 JLG 1930 ES Electric Scissor Lift S/N: 0200248756 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		EQUIPMENT Usage: 24 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	Usage: 236 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		2018 MEC 1330SE Electric Scissor Lift S/N: 16301584 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	
6835	2015 JLG 1930 ES Electric Scissor Lift S/N: 0200246003 C/W: 18 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		Control Box, EQUIPMENT-FŘOM-SUN: EQUIPMENT Usage: Not Available Notes : AERIAL UNITS REQUIRE PROP	Control Box, EQUIPMENT-FŘOM-SUNSTATE- EQUIPMENT Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Usage: 402 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2018 MEC 1330SE Electric Scissor Lift S/N: 16301583 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	
6836	2015 JLG 1930ES Electric Scissor Lift S/N: 0200246832 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 425 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6842	2018 MEC 1330SE Electric Scissor Lift S/N: 16301451 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 256 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6847	2017 MEC 1330SE Scissor Lift S/N: 16301591 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 88 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6848	2017 MEC 1330SE Electric Scissor Lift S/N: 16301447
6843	2018 MEC 1330SE Electric Scissor Lift S/N: 16301467 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER		C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD ;	6849	MEC 1330SE Electric Scissor Lift S/N: 16301456
6844	Asset located in: Lake Worth, TX 2018 MEC 1330SE Electric Scissor Lift S/N: 16301460 C/W: 13 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER		C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6850	2017 MEC 1330SE Electric Scissor Lift S/N: 16301120 C/W: 13 ft Max Platform Height, 530 lb Max
6845	2018 MEC 1330SE Electric Scissor Lift S/N: 16301603 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6846	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2017 MEC 1330SE Scissor Lift		2017 Genie AWP30SDC Vertical Mast Lift S/N: AWPG-89720 C/W: 29 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Markin Tires
0040	S/N: 16301230 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 19 Hr		Usage: Not Āvailable Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Notes: AERIAL UNITS REQUIRE PROPER	4075	Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6852	2017 Snorkel MB26J Vertical Mast Lift S/N: MB26J-01-170700055 C/W: 26 ft Max Platform Height, 475 lb Max Weight Capacity, Power to Platform, Upper Control Box Usage: 258 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6853	2018 Genie IWP-25S Vertical Mast Lift S/N: IWPG-12193 C/W: 24 ft 11 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK	6859	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-49586 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 482 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6854	2017 Genie AWP-25S Vertical Mast Lift S/N: AWPG-90308 C/W: 24 ft 11 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6860	2016 Genie GR-20 Vertical Mast Lift S/N: GR16P-40894 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 6 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6855	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-49588 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	 6861	2016 Genie GR-20 Vertical Mast Lift S/N: GR16P-43838 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 640 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6856	2017 Genie GR20 Vertical Mast Lift S/N: GRP-50131 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 342 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6862	2015 Genie GR-20 Vertical Mast Lift S/N: GR15-39295 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 487 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK
6857	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-50133 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 419 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6863	2015 Genie GR-20 Vertical Mast Lift S/N: GR1538516 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX 2015 Genie GR-20 Vertical Mast Lift S/N: GR1539023 C/W: 20 ft Max Platform Height, 350 lb Max
6858	2017 Genie GR20 Vertical Mast Lift S/N: GRP-48660 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 448 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 435 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6865 6865A	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539233 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX 2015 Genie GR-20 Vertical Mast Lift	6870	2023 Ballymore DVML-18 Vertical Mast Lift (Unused) S/N: DBA2302163 C/W: 19 ft 7 in Max Platform Height, 350 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED	
	S/N: GR1539281 Usage: Not Available Asset located in : Lake Worth, TX	FROM YARD BY OCTOBER 18TH AND CAN BE RELISTED; BUYER'S RESPONSIBILITY F REMOVAL	FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
6865B	2015 Genie GR-20 Vertical Mast Lift S/N: GR1538466	6871	Asset located in: Lake Worth, TX 2017 Genie GR-12 Vertical Mast Lift	
	Usage: Not Available Asset located in: Lake Worth, TX		S/N: GRP-49699 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension,	
6865C	2014 Genie GR-20 Vertical Mast Lift S/N: GR14-30574 Usage: 362 Hr Asset located in: Lake Worth, TX		Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 214 Hr	
6866	2013 Genie GR-20 Vertical Mast Lift S/N: GR13-27800 C/W: 19 ft Max Platform Height, 350 lb Max	6872	FUNCTION TEST AND LOAD	SAFETY HARNESS, LANYARD, AND PPE TO
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 495 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2017 Genie GR-12 Vertical Mast Lift S/N: GRP-49754 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 301 Hr	
6867	2013 Genie GR20 Vertical Mast Lift S/N: GR13-28800 Usage: Not Available		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6873	2016 Genie GR-12 Vertical Mast Lift	
6868	2013 JLG 20MVL Vertical Mast Lift S/N: 0130019279 C/W: 19 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	— 6873 	S/N: GR16P41021 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 319 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		FUNCTION TEST AND LOAD	
6869	2019 Haulotte STAR 20 Vertical Mast Lift		Asset located in: Lake Worth, TX	
	S/N: 2062580 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6874	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41028 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 476 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
S/N: GR1539738 C/W: 11 ft 4 in Max Platfo Max Weight Capacity, Pla Power to Platform, Solid N Upper Control Box, EQUIP SUNSTATE-EQUIPMENT Usage: 367 Hr	C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 367 Hr	6880	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P21140 C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket Usage: 208 Hr Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6881	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P20643
6876	2015 Genie GR-12 Vertical Mast Lift S/N: GR1538757 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires,		C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket Usage: 455 Hr Asset located in : Lake Worth, TX
6877	Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2014 Genie GR-12 Vertical Mast Lift	6882	2019 Vermeer S925TX Mini Compact Track Loader S/N: 1VRL07056J1000534 C/W: Open Operator Station, Tier 4, 2018 US EPA Label, 7 in Track Belts, Manual Coupler, 42 in Bucket Usage: 2,318 Hr Asset located in: Lake Worth, TX
08//	S/N: GR14-36227 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 495 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6883	2014 Ditch Witch SK755 Mini Ride-On Compact Track Loader S/N: CMWZ57NLCE0000057 Usage: Not Available Asset located in: Lake Worth, TX
6878	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2014 Genie GR-12 Vertical Mast Lift S/N: GR1436093 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires,	6884	2024 Eingp SCL850 Mini Compact Track Loader (Unused) S/N: SCL8500125 C/W: Open Operator Station, 9 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 544 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6885	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket Usage: 2 Hr Asset located in: Lake Worth, TX
6879	S/N: GR14-359/3 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER	6886	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
		6887	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: 1 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6888	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178459 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6896	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409043138 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	·	100=	· · · · · · · · · · · · · · · · · · ·
6889	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404163371 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6897	2024 Machpro MP-S300 Mini Compact Track Loader S/N: SLP2403080620 C/W: Open Operator Station, 2023 US EPA Label, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: 37 Hr Asset located in: Lake Worth, TX
6890	2024 JQ POWER JQ400 Mini Compact Track Loader S/N: 2404178462 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6898	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409043137 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6891	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404163356 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6899	2024 BTTL ST25M-6 Mini Compact Track Loader (Unused) S/N: A2407158825 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6892	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409073147 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6900	2024 BTTL ST25M-6 Mini Compact Track Loader (Unused) S/N: A2407158835 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6893	2024 AGT CRT23 Mini Compact Track Loader (Unused) S/N: CRT232024060000006 C/W: Open Operator Station, 2024 US EPA Label, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6901	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT232024052200230 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6894	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178498 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6902	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT23202408010005 C/W: Open Operator Station, Joystick Steering 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX
6895	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409073142 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6903	2024 AGT CH904 Wheel Loader S/N: CH9042024L0618005 C/W: Open Operator Station, 38 in Bucket, 23X8.5-12 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6904	2007 Ditch Witch R300 Wheel Loader S/N: CMW1D4XK70000069 C/W: Open Operator Station, Auxiliary Hydraulics, Manual Coupler, 36 in Bucket, 20x100-8 Tires Usage: Not Available Asset located in: Lake Worth, TX	6912	2024 Landhero LDH-KV16 Mini Excavator (Unused) S/N: Not Available C/W: 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, 15 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	
6905	2024 Digmaster DM200 Mini Excavator	6012		
0903	(Unused) S/N: DM24080305 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX	6913	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515624 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	
6906	2024 Digmaster DM200 Mini Excavator (Unused) S/N: DM24080303 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket	 6914	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515549 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available	6915	2024 Machpro MP15 Mini Excavator (Unused)	
6907	Asset located in: Lake Worth, TX 2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408069118 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available		S/N: SLP241515621 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6916	2024 Machpro MP15 Mini Excavator (Unused)	
6908	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408043843 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb		C/W: 2 ft 7 in Stick, Auxiliary F Plumbing, Backfill Blade, 7 in 12 in Digging Bucket, Manual Usage: Not Available	S/N: SLP241515538 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6917		
6909	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044079 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket		S/N: SLP241515589 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available	6918	2024 Machpro MP15 Mini Excavator (Unused)	
6910	Asset located in: Lake Worth, TX 2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044073 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Treeke, 17 in Digging Bucket, Manual Thumb		S/N: SLP241515609 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	
	Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available	6919	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515546 C/W: 2 ft 7 in Stick, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	
6911	Asset located in: Lake Worth, TX 2024 FF Industrial FF18R Mini Excavator S/N: 2408069186 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
6920	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515626 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6927	2024 VICSEC VC13 Mini Excavator (Unused) S/N: VC13240617 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Humble, TX
	·		<u> </u>
6921	2024 VICSEC VC15P Mini Excavator (Unused) S/N: VA15P240703 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Manual Quick Coupler, 17 in Digging Bucket, Manual Thumb Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6928	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136819 C/W: 2024 US EPA Label, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX 2024 FF Industrial FF-12 Mini Excavator
	Asset located in: Lake Worth, TX	_	(Unused) S/N: 423136832
6922	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423032738 C/W: Straight Travel Pedal, Tier 2, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks,	6930	C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
	14 in Digging Bucket, Manual Thumb Usage: Not Available		2024 FF Industrial FF-12 Mini Excavator (Unused)
	Asset located in: Humble, TX		S/N: 423136824 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6923	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423032626 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary		
	Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: 66 Hr Asset located in : Lake Worth, TX		2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136840
6924	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423050691 C/W: Enclosed Cab, 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket		C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available	6932	2024 BTTL ET12M-6 700718 Mini Excavator
6925	Asset located in: Lake Worth, TX 2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423105139 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb		(Unused) S/N: ET12M-6 700718 C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	6933	2024 BTTL ET12M-6 Mini Excavator (Unused)
6926	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423123854 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX		S/N: ET12M-6700717 C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6934	Quantity of (5) 2024 Landhonor LHR-SG64 6 ft x 4 ft Livestock Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6939	Quantity of (56) 2024 Suihe SP10-S-56 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
6935	Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6940	Quantity of (56) 2024 Suihe SP10-G-56 10 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6936	Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6941	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6937	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6942 Quantity of (56) 2024 Suihe NP10-Powder Coated Livestock Panel (US/N: Not Available C/W: THE PRODUCT IMAGES SHOFOR ILLUSTRATION PURPOSES OF	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6938	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	6943	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (12) 2024 Landhonor LHR-SP07 7
	Asset located in: Lake Worth, TX		ft Sheep Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		6944	Quantity of (24) 2024 Landhonor LHR-SP07 7 ft Sheep Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset Joseph Jacks Worth TV

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6945	Quantity of (4) Bundles of 10 Ft Livestock Panel S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6952	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6946	2024 Industrias America R820 20 Ft Loading Ramp (Unused) S/N: R82020242517 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6947	Asset located in: Lake Worth, TX 20 ft Loading Ramp (Unused)	+	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	S/N: Not Available C/W: 30,000 lb. Capacity Usage: Not Available	6953	Asset located in: Lake Worth, TX 2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused)
6948	Asset located in: Lake Worth, TX 2024 Landhonor LHR-CSC10 Cattle Squeeze Chute (Unused) S/N: HL00009 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6949	2024 SUNTOP S2512 12 ft x 25 ft Livestock	_	Asset located in: Lake Worth, TX
03.13	Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	:	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused)
6950	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6956	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6951	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6957	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: M12S224202 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6958	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6959	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: M12S225549 Usage: Not Available Asset located in: Lake Worth, TX	6965	Quantity of (3) 2024 Suihe NFG-20FC-3 20 ft Bi Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN
6960	Quantity of (50) 12 ft Corral Livestock Panel S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX		EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6961	2024 SUNTOP S0720 Qty of (6) 20FT Bi- Parting Wrought Iron Driveway Gate (Unused) S/N: Not Available		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6966	2024 Suihe NFG-20FGP-D 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6962	Quantity of (6) 2024 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	6967	2024 Suihe NFG-20FGP-E 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6963	Asset located in: Lake Worth, TX Quantity of (6) 2024 SUNTOP S207 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available	6968	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		Quantity of (8) 2024 Suihe NG-20D-8 20 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6964	Quantity of (3) 2024 Suihe NFG-20FB-3 Bi-	1010	Asset located in: Lake Worth, TX
	Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6969	Quantity of (8) 2024 Suihe SG-20D-8 20 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: Rectangle Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6970	2024 Suihe SG 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6975	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
6971	Quantity of (2) 2024 Suihe NG-14D -2 14 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6976	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6972	Quantity of (2) 2024 Suihe NG-14Eu-2 14 ft Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (6) 2024 SUNTOP S07020 20 ft x 7	- 6977	2024 SUNTOP S0610 Qty of (20) 10FT Portable Construction Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
09/3	ft Driveway Gate		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 20 ft x 7 ft Wrought Iron Bi Parting Driveway Gate Usage: Not Available Asset located in : Lake Worth, TX	6978	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6979	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX Quantity of (20) 2024 SUNTOP S0610 10 ft x 6
			ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6980	Quantity of (26) 2024 Suihe SF-D-26 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6991	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		6992	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6993	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available
6981	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available	6994	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft
6982	Asset located in: Lake Worth, TX Quantity of (20) 8 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	_	Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6983	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6984	Quantity of (20) 10 ft x 7 ft Site Fence (Unused)	7	Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6995	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 Fencing (Unused) S/N: Not Available
6985	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
6986	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6987	Asset located in: Lake Worth, TX Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6996	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6988	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6989	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6990	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
6997	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7005	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX Quantity of (30) 2024 SUNTOP S0710-30 10 ft
6998	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX		x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT PERPESENTATION OF
6999	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
		7007	Asset located in: Lake Worth, TX
		7007	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused)
	Asset located in: Lake Worth, TX		S/N: Not Available C/W: (30) Fence Panels, (31) Post's w
7000	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX		/Connectors THE PRODUCT IMAGES SHOW! ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODU Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
7001	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7008	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused)
7002	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	_	S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7003	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	Asset located in: Humble, TX	7000	Asset located in: Lake Worth, TX
7004	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7009	Quantity of (20) 2024 FENS FEN20 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: B44823 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7010	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7017	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7018	Quantity of (20) 2024 HUNTER PRO WLFT10-	
7011	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7019	24P 10 ft x (Unused) S/N: Not A C/W: One F Usage: Not Asset loca	S/N: Not Available C/W: One Rack Usage: Not Available Asset located in : Lake Worth, TX Quantity of (24) 2024 HUNTER PRO WLFT10 -
	Asset located in: Lake Worth, TX		24P 10 ft x 7 ft Powder Coated Fencing (Unused)	
7012	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, 7020 Quantity of (24) 2024 HUNTER 24P 10 ft x 7 ft Powder Coated (Unused) S/N: Not Available Usage: Not Available	S/N: Not Available	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available	
7013	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7021	Asset located in: Lake Worth, TX Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	
7014	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7022	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7015	Quantity of (24) 2024 HUNTER PRO WLFT10-24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7023	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7016	Quantity of (24) 2024 HUNTER PRO WLFT10-24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7024	Quantity of (44) 7 ft 10 in x 7 ft Powder Coated Fencing S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		7025	Quantity of (2) Pallets of 78 In x 10 Ft Site Fence S/N: Not Available C/W: Accessories Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7026 7027	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7034	2024 SUNTOP S4200 Qty of (21) 200ft x 40in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7035	Asset located in: Lake Worth, TX 2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES
7029	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7030	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available	7037	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused)
7031	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7032	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
7033	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7038	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	7043	Quantity of (4) Fencing S/N: Not Available C/W: Braces Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	7044	Quantity of Fencing
7039	Quantity of (36) Rolls of Field Fence 47 In x 330 Ft Fencing (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7044	S/N: Not Available C/W: 36 in. Silt Fence With Additional Wooden Stakes Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
7040	Quantity of Fencing S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING FHESE Asset located in: Lahoma, OK	7045	2024 Agriquip GLHP100 100 ton Air/Hydraulic Shop Press (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
7041	Quantity of (16) Fencing S/N: Not Available C/W: Braces. Rack Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	MAY NOT BE AN EXACT REPRESENTAT THE ACTUAL PRODUCTHE PRODUCT IN SHOWN ARE FOR ILLUSTRATION PURP ONLY AND MAY NOT BE AN EXACT	REPRESENTATION OF THE ACTUAL PRODUCT
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7046	Quantity of (4) Portable Generator Set S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7042	Quantity of (8) Fencing S/N: Not Available C/W: Braces Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	7047	Quantity of (2) Portable Generator Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7048	Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		7049	Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7050	Quantity of (2) Dewalt DXGNR6500 Portable Generator Set S/N: Not Available C/W: 2021 US EPA Label, Generac 389 cc Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7060	2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor S/N: CBV713664 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 7,936 Hr Notes: .
7051	Quantity of (2) Generac GP8000E 8 kW		Asset located in: Lake Worth, TX
	Portable Generator Set S/N: Not Available C/W: 2023 US EPA Label, Generac 420 cc Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7061	2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor S/N: CBV710808 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 2,281 Hr Notes: .
7052	Quantity of (3) Generac GP3600 3.6 kW Quantity of (1) Generac GP3500i Portable		Asset located in: Lake Worth, TX
	Generator Set S/N: Not Available C/W: Generac 212 cc Gasoline Engine, 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7062	2024 Landhonor LHR-GAC60Y 60 Gallon 2- Stage Truck Mounted Air Compressor (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7053	Quantity of Ryobi 3400 Watt & Champion 3500 Watt Portable Generator Set S/N: Not Available C/W: Dual Fuel Engine, 120 V Receptacles, Gasoline	7063	Iron Horse Electric 60 gal Shop Air Compressor S/N: Not Available C/W: 150 psi Working Pressure, 6 hp Motor Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7064	gal Air Compressor (Unused)
7056	Quantity of (3) Pallets of Portable Generator Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
7057	Multiquip GAW-180H 3 kW Skid-Mounted	7065	Asset located in: Lake Worth, TX
7058	Portable Generator Set S/N: 5682943 C/W: Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX 2020 Ingersoll Rand RS22N 115 cfm Skid-	7065	2024 Landhonor LHR-GAC40 Skid-Mounted 40 gal Air Compressor (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7000	Mounted Electric Air Compressor		Asset located in: Lake Worth, TX
	S/N: CBV699949 C/W: 3 Phase, 30 hp Motor, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 5 Hr Notes: . Asset located in: Lake Worth, TX	7066	Coltec Industries OSI370WNW41A Skid- Mounted Electric Air Compressor S/N: 94897 C/W: 175 psi Working Pressure, 230/460 volts Usage: 2,363 Hr Asset located in: Lake Worth, TX
7059	2020 Ingersoll Rand RS22N 114.6 cfm Skid- Mounted Electric Air Compressor S/N: CBV703202 C/W: 3 Phase, 30 hp Motor, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 7,397 Hr Notes: . Asset located in: Lake Worth, TX	7067	Skid-Mounted Air Compressor S/N: 380091 C/W: 2013 US EPA Label, Kohler Command Pro 1 Cylinder 429 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7068	Skid-Mounted 30 gal Air Compressor S/N: Not Available C/W: Predator 1 Cylinder 420 cc Gasoline Engine Usage: 88 Hr Asset located in: Lake Worth, TX	7075A	Northstar Pressure Washer S/N: 4K1BP1625FF001307 C/W: Water Heater, 500 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7069	Eagle 30 Gal Truck Mount Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7076	Easy-Kleen Magnum 3600 Pressure Washer (Unused) S/N: 2440130
7070	PowerTrain 18.5 cfm 30 gal Air Compressor (Unused) S/N: Not Available		C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 175 psi Working Pressure, Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7077	Easy-Kleen Magnum 3600 Pressure Washer (Unused) S/N: 243819
7071	PowerTrain 11.2 cfm 10 gal Air Compressor S/N: Not Available Usage: Not Available		C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Asset located in : Lake Worth, TX
7072	Asset located in: Lake Worth, TX Quantity of (5) Electric Air Compressor S/N: Not Available C/W: 120V, (2) Goodyear 20 gal, (1) Goodyear 10 gal, (1) Campbell Hausfeld 6 gal, (1) Hyper Tough 6 gal Usage: Not Available	7 078	Easy-Kleen Magnum 3600 Pressure Washer (Unused) S/N: 2440131 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Asset located in: Lake Worth, TX
7073	Asset located in: Lake Worth, TX Mi-T-M 13.1 cfm Skid-Mounted Air Compressor S/N: 20175543 C/W: 100 psi Working Pressure, 2013 US EPA Label, Honda GX200 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	7079	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243888 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7074	Asset located in: Lake Worth, TX Jenny Skid-Mounted Air Compressor S/N: Not Available C/W: 2008 US EPA Label, Honda 1 Cylinder 270 cc Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	7080	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244614 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7075	Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7081	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244615 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		7082	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244617 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7083	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244542 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7090	7090 All American 8357L Skid Mounted Pressure Washer (Inoperable) S/N: 105855 C/W: Water Heater, Kubota D1105 3 Cylinder Diesel Engine Usage: 1,058 Hr Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR	
7084	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243899		REMOVAL Asset located in: Lake Worth, TX	
	C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7091	S/N: 11100510101372	S/N: 11100510101372 C/W: 3500 psi Rating, Water Heater, Honda GX630 Gasoline Engine Usage: Not Available
7085	Easy-Kleen Magnum Gold Pressure Washer		Asset located in: Lake Worth, TX	
	(Unused) S/N: 244616 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7092	2020 Hotsy 1075SSE Pressure Washer S/N: 11100120168267 C/W: 3500 psi Rating, Water Heater, Hose, Spray Wand, Honda GX390 Gasoline Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 67 Hr Notes: .	
7086	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244541 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
, , ,		7094	2018 Mi-T-M HS-3505-0MDK Pressure Washer S/N: 15119001 Usage: 404 Hr Asset located in: Lake Worth, TX	
		7095	2016 Mi-T-M CW-3504-5MGH Pressure Washe S/N: Not Available	
7087	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243887		C/W: 3500 psi Rating, Honda GX390 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	
	C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available	7096	2018 Mi-T-M CW25054MGH Pressure Washer S/N: 11041408 C/W: 2500 psi Rating, Honda GX390 Gasoline Engine	
7088	Asset located in: Lake Worth, TX 2023 Power Wash Store Pressure Washer	Usage: Not Available Asset located in: Lake Worth, TX	Usage: Not Available	
	S/N: 5RHCT101XPH003995 C/W: 225 gal Water Supply, Hose, Trailer Mounted, Honda GX390 1 Cylinder 389 cc Gasoline Engine, Spring Suspension, Ball Hitch, Wood Flooring Usage: Not Available Asset located in: Midland, TX	7097	2017 Mi-T-M HSP-2503-0MMH Pressure Washer S/N: 15111154 C/W: 2500 psi Rating, Water Heater, Honda GX200 196 cc Gasoline Engine Usage: Not Available	
7089	Aladin 8430-C Pressure Washer		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: Water Heater, Electric Operated Usage: 1,411 Hr Asset located in : Midland, TX	7098	Quantity of (2) Pressure Washer S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7099	9 Simpson MS61219 Pressure Washer S/N: 05235011741 C/W: 3400 psi Rating, Hose, Spray Wand, Simpson CRX225 1 Cylinder 224 cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	7107	Landa PGDC5-3500 Pressure Washer S/N: 11100500101087 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton Vanguard 18 hp 570 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7108	2002 Pressure Washer S/N: 1P9HT1S2321293177 C/W: 3000 psi Rating, Water Heater, 500 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler Command Pro 2 Cylinder Gasoline Engine, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY
7100	Simpson Pressure Washer S/N: Not Available C/W: 4000 psi Rating, Honda 1 Cylinder		Usage: 1,068 Hr Asset located in: Lake Worth, TX
	Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7109	40 ft High Cube Office Storage Container (Unused) S/N: KDCU5211968
7101	Quantity of (4) Boxes of Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine Usage: Not Available		C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED Ceiling Lights, Interior Outlets, forklift pockets Usage: Not Available Asset located in: Lake Worth, TX
7102	Asset located in: Lake Worth, TX Quantity of (4) Simpson Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Honda GCV160 Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7110	20 ft Office Storage Container (Unused) S/N: SKYU2652356 C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED Ceiling Lights, Interior Outlets, forklift pockets Usage: Not Available
7103	Quantity of (5) Murray Pressure Washer		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 3200 psi Rating, Hose, Spray Wand, Briggs & Stratton CR950 208 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7111	2024 LEVE LE20 19 ft 5 in x 20 ft Expandable House (Unused) S/N: A0282 C/W: (2) Bedrooms w/, (1) Bathrooms, (1) Living Room Usage: Not Available
7104	Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, Hose, Spray Wand, Briggs & Stratton CR950 208 cc Gasoline Engine		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7112	2024 Suihe GS2533 Metal Shed (Unused)
7105	2019 Mi-T-M HSP-3504-3MGH Pressure Washer S/N: 15132271 C/W: 3500 psi Rating, Water Heater, Hose, Spray Wand, Honda GX390 Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7106	Quantity of (4) Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7113	2024 Suihe 2040P 40 ft x 20 ft Commercial Party Tent (Unused) S/N: Not Available C/W: (18) Removable Side Walls w/PVC Clear Windows, (2) Zipper Doors, 500 gsm PVC Coated Fabrics, Waterproof, Fire & UV Resistant, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7118	(Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	(Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
7114			THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7120	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
7115	2024 Suihe GS2119 21ft x 19ft Portable Metal Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Suihe GS2322 Metal Shed (Unused)		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	
7110	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7121	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7122	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7117	2024 Suihe M202010P Light Steel Carport (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7123	Quantity of (200) 2024 Machpro S3048C 10 ft Corrugated PPGI Steel Panels (Unused) S/N: 2408070018 C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	
		7124	Quantity of (200) 2024 Machpro S3048C 10 ft Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7125	2024 Suihe S5010023DP-750gPVC 100 ft x 50 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (4) Boxes - Builds (1) Storage Building Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Hills Industrial 805026 80 Ft x 50 Ft x 26	7131	2024 Landhonor LHR-ST3085 85 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7132	Asset located in: Lake Worth, TX 2024 Suihe S406423DP-610gPVC 64 ft x 40 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage
7127	2024 HIlls Industrial 504026 50 Ft x 40 Ft x 26 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7133	Building Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7128	2024 Hills Industrial 804024 80 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Hills Industrial 604024 60 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available
7129	2024 Suihe S408023DP-610gPVC 80 ft x 40 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Suihe S308515R-300gPE 85 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7130	2024 Suihe S408020R-300gPE 80 ft x 40 ft x 20 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7135	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		7136	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7137	2024 Suihe S306020DP-610gPVC 60 ft x 30 ft x 20 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7144	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7138	2024 Landhonor LHR-ST3040 40 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7145	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7139	2024 HIlls Industrial 604024 60 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE
7140	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7141	2024 Hills Industrial 603022 60 Ft x 30 Ft x 22 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES
7142	2024 Hills Industrial 403022 40 Ft x 30 Ft x 22 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		REPRESENTATION OF THE ACTUAL P Usage: Not Available Notes: THE PRODUCT IMAGES SHOW! FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTA
7143	2024 Suihe S304015R-300gPE 40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7148	Asset located in: Lake Worth, TX 2023 HOS HF2N1 19 ft x 21 ft Folding Storage Building S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7149	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: C/W: 2x6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX Pole Barn Package 16 ft x 32 ft x 40 ft Storage	7155	2024 Suihe C404013-300gPE x 13 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
7130	Building (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	C/W: C/W: 2 x 6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX	7156 2024 Suihe C2040-300gPE 20 ft x 40 Container Shelter Storage Canopy (U S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 7157 2024 Suihe C2040-300gPE 20 ft x 40 Container Shelter Storage Canopy (U S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 7158 2024 Suihe C2020-300gPE 20 ft x 20 Container Shelter Storage Canopy (U S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Usage: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL	2024 Suihe C2040-300gPE 20 ft x 40 ft Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
7151	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: C/W: 2 x 6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
7152	16 ft x 24 ft x 40 ft Pole Barn Package Storage Building (Unused) S/N: Not Available C/W: Includes: 2x6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX		Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
7153	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available			
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Container She S/N: Not Avail C/W: THE PRO FOR ILLUSTRA MAY NOT BE THE ACTUAL Usage: Not Av Notes: THE PI FOR ILLUSTRA	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7154	2024 Suihe C404013-300gPE x 13 ft Container Storage Canopy (Unused) S/N: Not Available		THE ACTUAL PRODUCT	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7159	2024 Suihe C504017DR-610gPVC 50 ft x 40 ft x 17 ft Container Shelter Storage Canopy (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7160	Quantity of (2) Conveyor Belts - Fits Tractor S/N: Not Available C/W: (1) 55 In, (1) 42 In ; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7167	Quantity of (3) Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7161	Quantity of (3) Uline Tool Cabinet S/N: Not Available C/W: (1) 42 In 11 Drawer, (1) 29 In 5 Drawer,	7168	Quantity of (3) Truck Toolboxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	(1) 29 In 7 Drawer; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2024 Suihe NWB-30DS-10 10 ft 30-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7162	2024 Suihe NWB-H35DS-7 7 ft 35-Drawer Tool Cabinet (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7163	18 In x 24 In Tool Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7164	Quantity of Tool Box S/N: Not Available Usage: Not Available	7171	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		2024 Suihe NWB-15DR-2-10 10 ft 15-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7165	UWS TBC60N Tool Box		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 60 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7172	2024 Suihe NWB-25DB-10 10 ft 25-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7166	Quantity of (3) Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7173	2024 Suihe NWB-H40DB-10 10 ft 40-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7180	2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7181	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30- Drawer Workbench (Unused) S/N: Not Available	
7175	Can Industrial 10 ft 40 Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7176	2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7182 2024 Suihe NWB-H18DB-7 7 ft 18-Dr. Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 7183 2024 Suihe NWB-20DS-7 7 ft 20-Draw Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
7177	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30- Drawer Workbench (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		7183 2024 Suihe NWB-20DS-7 7 ft 20 Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES S FOR ILLUSTRATION PURPOSES	2024 Suihe NWB-20DS-7 7 ft 20-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7178	2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7184	2024 Suihe NWB-H18DR-7 7 ft 18-Drawer Workbench (Unused)	
7179	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7185	2024 Suihe NWB-10DS-2-7 7 ft 10-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7195 7196	Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7187	6 ft 7 in Workbench	7197	Milwaukee 40 In 5 Drawer Workbench
	S/N: Not Available C/W: 4 doors, 16 drawers Usage: Not Available Asset located in : Lake Worth, TX		S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7188	U. S. General 72 In 18 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7198	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7189	Yukon 46 In 9 Drawer Workbench	7400	Asset located in: Lake Worth, TX
	S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7199	Quantity of (3) U. S. General 30 In Tech Carts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7190	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7200	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7191	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7201	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7192	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7202	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7193	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7203	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S.General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7194	Quantity of (2) Milwaukee 40 in 6-Drawer Workbench S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7204	U. S. General 44 in 13-Drawer Workbench S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7205	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S.General 34 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7216	2024 Kit Containers WB-60-190 26 In x 60 In Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7206	Quantity of (4) U. S. General Service Carts S/N: Not Available C/W: (3) 4 Drawer, (1) 5 Drawer; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7217	2024 Kit Containers ST-57 29 In x 57.5 In Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7207	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available	7218 7220	2024 Kit Containers ST-57 4 ft 10 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Workshop Work Table	
7208	Asset located in: Lake Worth, TX 2024 Kit Containers WB-90-243 7 ft 6 in Workbench		S/N: Not Available Usage: Not Available Asset located in : Midland, TX	
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7221	2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: B12I407	
7209	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available	7222	Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers 4Y-DH Debris Box	
7010	Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: B191402 Usage: Not Available	
7210	2024 Kit Containers WB-90-243 7 ft 6 in Workbench		Asset located in: Lake Worth, TX	
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7223	Quantity of (5) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High,	
7211	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available		EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	7224	Quantity of (4) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High,	
7212	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available		EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	7225	Quantity of (2) 2024 Suihe N-1CY -2 1 cyd Self- Dumping Hopper (Unused)	
7213	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Fork Pockets, TI SHOWN ARE FOR ILLI ONLY AND MAY NOT REPRESENTATION OI	
7214	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
7215	2024 Kit Containers WB-60-190 5 ft Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
7226	2024 Kit Containers 2YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Lake Worth, TX	7234	Quantity of (2) 2024 Suihe N-1.5CY-2 1.5 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7227	2024 Kit Containers 2YFT-SDH Skid Steer Dump Hopper (Unused) S/N: B21J1204 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7228	· · · · · · · · · · · · · · · · · · ·	7235	25 ft Loading Ramp (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	High Usage: Not Available Asset located in : Lake Worth, TX	7236	Quantity of (5) Abell-Howe 1 Ton Electric Shop Pedestal Crane S/N: Not Available
7229	2024 Kit Containers 1.5YFT-SDH Skid Steer Dump Hopper (Unused) S/N: B21J1206 Usage: Not Available		C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7237	Quantity of (5) Abell-Howe 1Ton Electric Shop
7230	O 2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in: Lake Worth, TX		Pedestal Crane S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
			Asset located in: Lake Worth, TX
7231	2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in: Lake Worth, TX	7238	Quantity of (5) 2020 Abell-Howe 1 Ton Electric Shop Pedestal Cranes S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7232	Quantity of (5) 4 ft 6 in Self-Dumping Hopper S/N: Not Available C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		Quantity of (2) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7233	Asset located in: Lake Worth, TX Quantity of (4) 4 ft 6 in Self-Dumping Hopper S/N: Not Available C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING	7241	Quantity of (3) Bundles Of Standard Beam 4" 7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset Joseph Jr. Leke Worth, TV
	Usage: Not Available Asset located in: Lake Worth, TX	7242	Asset located in: Lake Worth, TX Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7243	Quantity of (3) Bundles of Standard Beam 4" 7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7254	Quantity of (6) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX
7244	Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7255	Quantity of (2) Bundles of Horse Fence Xtreme Black 12.5-12.5 2 in x 48 in x 200 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7245	Quantity of (3) Square Bar 5/8 A-36 20' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7256	Quantity of (3) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available
7246	Quantity of (1) Bundle of 4 In x 36 Ft Wide Flange Beam S/N: Not Available	7257	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Bundles of Horse Fence Xtreme
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Black 12.5-12.5 2 in x 48 in x 200 ft S/N: Not Available Usage: Not Available
7247	Quantity of (1) Bundle of Wide Flange Beam 10 in 15.0 A992/A572-50 40 ft		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7258	Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200' S/N: Not Available
7248	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7259	Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200' S/N: Not Available
7249	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7260	Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available
7250	Quantity of (3) Bundles of Hex Netting Mazel Co 22		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	12.5-2-3/8" 72" 50 Ft	Quantity of (2) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available
7251	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black C40 12.0-12.5	1	Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7262	Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available
7252	Quantity of (6) Bundles of Panels 8 in x 34 in x 12 ft		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: One Stack Usage: Not Available	7263	Quantity of (1) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 96" 50 Ft S/N: Not Available Usage: Not Available
7253	Asset located in: Lake Worth, TX Quantity of (5) Bundles of Panels 8 in x 34 in x		Asset located in: Lake Worth, TX
	12 ft S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX	7265	Quantity of (1) Bundle Of Sheep/Goat Fence 10- 12.5 4 In x 48 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7266	Quantity of (2) Bundles of Chainlink Xtreme 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7277	Quantity of (2) Bundles of Chainlink Xtreme Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7267	Quantity of (2) Bundles of Chainlink Xtreme NC 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7278	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black C40 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7268	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7279	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7269	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7280	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7270	Quantity of Bundles of Chainlink Xtreme NC 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7281	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7271	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7282	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7272	Quantity of (4) Bundles of Horse Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7283	Quantity of (2) Bundles of Mazel 2 in x 36 in x 150 ft Hex Netting S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7273	Quantity of (2) Bundles of 9 Gauge 20 in 48 in, 50 ft S/N: Not Available Usage: Not Available	7284	Quantity of (2) Bundles of Welded Utility Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
 7274	Asset located in: Lake Worth, TX Quantity of Magnum 3 in 16d Nails S/N: Not Available C/W: One Pallet Usage: Not Available	7285	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7275	Asset located in: Lake Worth, TX Quantity of Horse Fence Xtreme Black S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	- 7286	Quantity of (3) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7276	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7287	Quantity of (2) Bundles of Welded Utility Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7288	Quantity of (4) Bundles of Horse Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7299	Quantity of (3) Bundles of Fencing S/N: Not Available C/W: (2) Fixed Knot Xtreme Black 96 In x 330 Ft, (1) Game Fixed Knot Stay Lock 96 In x 330
7289	Quantity of (4) Bundles of Galvanized Welded Fence 1 in x2 in 48 in 100 ft		Ft Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7300	Quantity of (3) Bundles of Game Fence Stay Lock C3 12.5-12.5 S/N: Not Available
7290	Bundle of Galvanized Welded Fence 2 in x4 in 60 in 100 ft		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7301	Quantity of (1) Bundle of Game Fence Stay Lock 12.5-12.5 S/N: Not Available
7291	Quantity of (3) Bundles of Galvanized Welded Fence 1"x2" 48" 100'		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7302	Quantity of High-Tensile Galvanized 15.5 Gauge Barbed Wire S/N: Not Available
7292	Quantity of (2) Bundles of Mazel Hex Netting 2" x 60" x 150'		C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7303	Quantity of Magnum 3 in 16d Nails S/N: Not Available
7293	Quantity of (2) Bundles of EZ Rol Chainlink PVC 1 1/2" 60" 50' S/N: Not Available		C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7304	4 Quantity of (2) Pallets of Magnum 3" 16d N S/N: Not Available
7294	Quantity of (1) Bundle Of Game Fence Stay Lock 12.5-12.5 6 In x 96 In x 330 Ft Fencing		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7305	Quantity of (2) Pallets of 3 1/2" 16d Bright Common Nails S/N: Not Available
7295	Quantity of (1) Bundle of Fixed Knot Fence Xtreme Black 12.0-12.5		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7306	Quantity of (2) Bundles of Barbed Wire High Tensile C3 15.5 8 Rod S/N: Not Available
7296	Quantity of (2) Bundles of Chainlink Fence (1) C3 11.5 2-3/8" 72" 50ft KT (1) C3 11.5 2-3/8"		Usage: Not Available Asset located in: Lake Worth, TX
	48" 50ft KK S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7307 Quantity of Conveyor Belt S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO Usage: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING
7297	Quantity of (2) Bundles of Game Fence Stay Lock C3 12.5-12.5 6	7308 Quantity of (4) Tool C S/N: Not Available C/W: EQUIPMENT-FR Usage: Not Available	Asset located in: Lake Worth, TX Quantity of (4) Tool Carts
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7298	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7309	Quantity of (4) Pallets of Eye Wash Stations & Spill Kits S/N: Not Available C/W: (1) Pallet of Absorbent Socks, (1) Pallet	7317	Quantity of (4) Pro-Start 25 ft Booster Cables S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	of Spill Kits, (2) Pallets of Eye Wash Stations; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7317A	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING	
7310	Electric Pump S/N: Not Available		Usage: Not Available Asset located in : Lake Worth, TX	
	C/W: MT 1/3 Hp Electric Motor, Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7317B	2023 Zetech Hydraulic drive motor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	
7311	Sipco Hydraulic Drive Notor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7318	Asset located in: Lake Worth, TX General EP8 Manhole Blower S/N: 33313 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	
7312	Enerpac MSFP10 Hydraulic Pump S/N: P392 C/W: Sheet Metal Pieces, (2) 10 Ton Jack Stands; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available	7319	Asset located in: Lake Worth, TX Quantity of (2) Discharge/Suction Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7314	hoses S/N: Not Available	7320	Quantity of (4) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	7321	Quantity of Hose S/N: Not Available C/W: 3 in. Discharge Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	
7315	Quantity of (5) Spy Pipeline Detectors & (1) Recorder S/N: Not Available Usage: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available C/W: 2 in., 3 in. Usage: Not Available Notes : ITEMS AT OFFSITE LOCATION BE PICKED UP WITHIN 14 DAYS OF T	S/N: Not Available C/W: 2 in., 3 in.
7316	Quantity of Assorted Construction parts S/N: Not Available C/W: Hydraulic Hoses, Tool Box, Caution Tape, Heavy Duty Rack, Sand Bags, and Misc Parts Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
7323		7332	2016 Wanco WTSP Solar Arrow Board S/N: 5F11S1016G1006319 C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Humble, TX
		7333	2015 Wanco WTMMB Solar Arrow Board S/N: 5F12S161XF1000503 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Lunette Ring Usage: Not Available
7324	Quantity of Water Hose S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7334	Asset located in: Lake Worth, TX Truck Mount Arrow Board S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7335	Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available
7326	2015 Wanco WTMMB Solar Message Board S/N: 5F12S1611F1000499 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Lunette Ring		C/W: One Rack Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7336	Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available
7327	2015 Wanco WTMMB Solar Message Board S/N: 5F12S161XF10005003 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch		C/W: One Rack Usage: Not Available Asset located in : Lake Worth, TX
	Jsage: Not Available Asset located in : Lake Worth, TX	7337	Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused)
7328	2012 Signal Message Board S/N: 1B9ST1012CL657441 C/W: 6 Lamps, Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch	C/W: Usage	S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7338	Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused)
7329	2012 HORIZON SIGNAL TECH SQ3TS Traffic Signal S/N: 1B9ST1010CL657471 Usage: Not Available	S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX	C/W: One Bundle Usage: Not Available
7330	Asset located in: Lake Worth, TX 2021 Wanco WTMMB Solar Arrow Board S/N: 5F12S1614M005001	7339 Quantity of (50) Traffic Barrier S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	S/N: Not Available
	C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in : Lake Worth, TX	7340	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available
7331	2016 Wanco WTSP Solar Arrow Board S/N: 5F11S1016G1006322		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Solar Doward S/A Trailor Pall Hitch	7341	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7342	Quantity of (250) 2024 HUNTER PRO C-75 Traffic Cones Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7350	Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7343	Quantity of (250) 2024 HUNTER PRO C-75 Traffic Cones Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7344	Quantity of (250) 2024 Agriquip GL28TC Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7351	2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7045	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7352	2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available Usage: Not Available
7345	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7353	Asset located in: Lake Worth, TX Quantity of (100) 2024 HUNTER PRO RB-100 Traffic Delineators & Bases (Unused) S/N: Not Available
7346	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet		C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7354	Traffic Delineators & Bases (Unused)
7347	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available		S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX
7348	Asset located in: Lake Worth, TX Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet	7355	Quantity of (130) Traffic Barrels S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7349	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (250) 2024 Suihe TC-250 Traffic	7356	Quantity of (13) 7 Ft x 4 Ft Crowd Control Barriers S/N: Not Available
70.15	Cones (Unused) S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7357	2008 Milstead 4000 gal Skid Mounted Steel Fuel Tank S/N: 1818-C881958 Usage: Not Available Asset located in: Lake Worth, TX
		7358	2024 AM Tank 2300N 2376 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82443 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7359	2024 AM Tank 2300N 2376 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82442 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment	7368	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000343 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7369	1000 gal Skid Mounted Steel Single Wall Fuel Tank
7360	2024 4-Fuel.com 4F2330 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005579		S/N: ORT1000313 C/W: Spill Containment Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 120V Pump, 13 ft Hose, Fuel Meter, Auto Nozzle, Spill Containment Usage: Not Available Asset located in : Lake Worth, TX	7370	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000310 C/W: Spill Containment Usage: Not Available
7361	2024 4-Fuel.com 4F2330 Gal Skid Mounted Diesel Fuel Tank (Unused)		Asset located in: Lake Worth, TX
	S/N: 000005580 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX	7371	2000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT2000127 C/W: Spill Containment Usage: Not Available
7362	2024 4-Fuel.com 4F1100 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005581 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX	7372	Asset located in: Lake Worth, TX 1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000350 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
7363	2000 gal Steel Gasoline Fuel Tank S/N: ST5376 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7373	2024 AM Tank 800 838 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82445 C/W: 120 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available
7364	2000 gal Steel Diesel Fuel Tank S/N: ST5384 C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7374	Asset located in: Lake Worth, TX 2024 AM Tank 800 838 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82444 C/W: 120 V Transfer Pump, Fuel Meter,
7365	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000364 C/W: Spill Containment		Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7375	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused)
7366	1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000427 C/W: Spill Containment Usage: Not Available		S/N: 000005582 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX
7367	Asset located in: Lake Worth, TX 2000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORP2000468 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7376	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005583 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7377	750 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Asset located in: Lake Worth, TX	7387	2024 AM Tank 116 gal Portable Poly Tank (Unused) S/N: 57066L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle
7378	2024 AM Tank 600 655 gal Skid Mounted Steel Fuel Tank (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 82446 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in : Lake Worth, TX	7388	2024 AM Tank 116 gal Portable Poly Tank (Unused) S/N: 57067L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle
7379	2024 AM Tank 600 655 gal Skid Mounted Steel Fuel Tank (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 82447 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in : Lake Worth, TX	7389	2024 AM Tank 116 116 gal Portable Poly Fuel Tank (Unused) S/N: 57068L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available
7380	500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005289 Usage: Not Available Asset located in: Lake Worth, TX	7390	Asset located in: Lake Worth, TX 2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused)
7381	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000332 C/W: Spill Containment Usage: Not Available		S/N: 000005586 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks Usage: Not Available Asset located in : Lake Worth, TX
7382	Asset located in: Lake Worth, TX 500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005280 Usage: Not Available Asset located in: Lake Worth, TX	7391	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005584 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks
7383	500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005362		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7392	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused)
7384	Morrison Bros Co. FTBDS-0500 Skid Mounted Steel Unknown Contents Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Midland, TX	7393	S/N: 000005585 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks Usage: Not Available Asset located in : Lake Worth, TX
7385	300 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Asset located in: Lake Worth, TX		2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND IMAGES AND INTERACTION OF THE ACTUAL PROPERTY AND IMAGES A
7386	Wen Industries Diesel Buggy Portable Steel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

	Detaile	1 "	Dataila
Lot #	Details	Lot #	Details
7394	Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL	7402	Weather Guard 92 gal Steel Diesel Fuel Tank S/N: 1915613344 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
		7403	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump
7395	2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
	IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7404	DeeZee 92 gal Portable Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump, 11 ft Hose Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7396	2022 Teran TDT116GL 116 gal Fuel Tank		Asset located in: Midland, TX
	(Unused) S/N: 46570L C/W: Polyethylene tank for diesel fuel transport equipped with a fuel transfer unit, 116 gal with 12V Pump (12GPM), 13ft Hose, Auto-Nozzle, Top Covering Lid. Usage: Not Available Asset located in: Lake Worth, TX	7405	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
7397	Quantity of (2) 100 gal Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7406	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7398	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: DEEZEE tool box; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7407	Asset located in: Midland, TX Quantity of (7) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7399	DeeZee 92 gal Portable Steel Diesel Fuel Tank		Asset located in: Corsicana, TX
	S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7408	Quantity of (3) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7400	DeeZee 92 gal Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Midland, TX	7409	Asset located in: Corsicana, TX Quantity of (2) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7401	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7410	Quantity of Steel Truck Bed Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7418	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005590 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	7419	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel
7411	Steel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE		Fuel Tank (Unused) S/N: 000005589 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7420	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005588
7412	2024 AM Tank 58 gal Portable Poly Tank (Unused) S/N: 57172A C/W: 12 V Transfer Pump, 13 ft Hose,		C/W: 12 v transfer pump, 13 ft hose, auto- nozzle Usage: Not Available Asset located in : Lake Worth, TX
	Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7421	2013 Transcube 30TCG 792 gal Skid Mounted Steel Fuel Tank S/N: D871188 C/W: 12 V Transfer Pump
7413	2024 AM Tank 58 58 gal Portable Poly Fuel Tank (Unused) S/N: 57170A C/W: 12 V Transfer Pump, 13 ft Hose,		Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX	7422	2024 AM Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 15160E
7414	2024 AM Tank 58 gal Portable Poly Tank (Unused) S/N: 57171A		C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX	7423 2024 AM Tank 29 gal Portable Poly (Unused) S/N: 15158E C/W: 12 V Transfer Pump, 10 ft Hos Automatic Shut-Off Nozzle Usage: Not Available	
7415	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005593		C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available
	C/W: 12 V Transfer Pump, 13 ft Hose,		Asset located in: Lake Worth, TX
	Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX	7424	2016 Transcube 20TCG 528 gal Skid Mounted Steel Fuel Tank S/N: A61281755
7416	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005591 C/W: 12 V Transfer Pump, 13 ft Hose,		C/W: 12 V Transfer Pump Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX	7425	Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7417	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005592 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7426	Quantity of (3) 100 Gal Transfer Fuel Tanks S/N: Not Available C/W: (2) L-Shaped, (1) Rectangle Usage: Not Available Asset located in: Lake Worth, TX Skid Mounted Steel Fuel Tank	7435	2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15157E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	
/42/	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7436	Asset located in: Lake Worth, TX Ace Roto-Mold 300 gal Poly Holding Tank S/N: LP00300BHSS	
7428	2000 gal Steel Gasoline Tank S/N: ST5369		Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7437	Steel Hydraulic Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	
7429	2000 gal Steel Oil Tank S/N: ST5383 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7439	2024 Agriquip GLDP20 Fuel Pump (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
7430	2000 gal Steel Coolant Tank S/N: ST5374 C/W: 12 V Transfer Pump, Fuel Meter,		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Automatic Shut-Off Nozzle, EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7440	2024 GLDP20 12V Diesel Transfer Fuel Pump (Unused) S/N: Not Available Usage: Not Available	
7431	300 gal Steel Windshield Wash Tank	7441	Asset located in: Lake Worth, TX	
	S/N: ST5329 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2024 Agriquip GLDP20 Fuel Pump (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
7432	2024 AM Tank 29 gal Portable Poly NH3 Tank (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
7422	Asset located in: Lake Worth, TX	7442	Quantity of (2) 2024 Agriquip GLGP20 Fuel	
7433	2024 AM Tank AM-SPRAYER 14 14 gal Portable Poly NH3 Tank (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 AM Tank 29 gal Portable Poly Tank (Unused)			Pump (Unused) S/N: Not Available C/W: Hose, Nozzle THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	S/N: 15159E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7443	Asset located in: Lake Worth, TX 2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused) S/N: Not Available C/W: 49 ft Hose Reel, 12v DC, 10 gpm Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7444	2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused) S/N: Not Available C/W: 49 ft Hose Reel, 12v DC, 10 gpm Usage: Not Available Asset located in: Lake Worth, TX	7454	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
7445	Quantity of (2) Fuel Boss 12 V DC Fuel Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7455	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
7446	Quantity of (2) Fuel Boss 12 v Fuel Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7456	Asset located in: Lake Worth, TX F250 & F350 Truck Box S/N: Not Available
7447	Fuel Boss 1 in Hose Reel W/ 110 V Pump, 50 ft. Deliver Hose Fuel Pump S/N: Not Available		C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
7440	C/W: Fuel Pump Usage: Not Available Asset located in: Lake Worth, TX	7457	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
7448	2012 IMT 30/217 Truck Mounted Boom S/N: 771397 C/W: 54 ft reach, 5 section knuckle boom, 3		Usage: Not Available Asset located in: Lake Worth, TX
	pallets of hydraulic fluid tank, stabilizers, rear bumper Usage: Not Available Asset located in : Lake Worth, TX	7458	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
7449	Knapheide 8 Ft Flatbed S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7459	S/N: Not Available
7450	Caseco MM225 11 Ft Service Body S/N: 70628170 C/W: Auto Crane 6406H 6000 LB Crane Usage: Not Available		C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
7451	Asset located in: Lake Worth, TX 2024 F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	7460	L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7461	L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump
7452	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-		Usage: Not Available Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	7462	Quantity of (25) Hendrickson S-34446-L Brake Chambers S/N: Not Available
7453	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-		C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	7463	Quantity of (2) Pallets of Trailer sub frame complete assembly S/N: 2017045964 C/W: Steel Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7464	Quantity of (4) Freightliner Fuel Tanks S/N: Not Available C/W: 100 gal Aluminum Usage: Not Available Asset located in: Lake Worth, TX	7476	Quantity of (2) Pallets of Dock Bumper (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7465	Quantity of (4) Freightliner Fuel Tanks; (2) Tanks-100gal, (1)-120gal, (1) Unknown - Fits Truck S/N: Not Available C/W: Aluminum	7477	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 256 Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7478	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 260 Usage: Not Available
7466	Quantity of Truck Parts S/N: Not Available C/W: Mud Flaps, Belts, Filter, One Pallet;	7479	Asset located in: Lake Worth, TX 2024 Neks Fifth Wheel Wrecker (Unused)
	EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX		S/N: 255 Usage: Not Available Asset located in : Lake Worth, TX
7467	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7480	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 259 Usage: Not Available Asset located in : Lake Worth, TX
7468	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7481	ProTech Aluminum Headache Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLI Usage: Not Available
7469	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available		Notes: . Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		Truck Hood S/N: Not Available C/W: Fiberglass, To Fit Peterbilt
7470	Liftmore 3200REE Service Crane S/N: 10-1123W106 Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX Peterbilt Truck Cab
7471	Asset located in: Lake Worth, TX Aerzen GMB 16.F13-12 Blower S/N: 830564 Usage: Not Available	7484	S/N: 67741 Usage: Not Available Asset located in: Lake Worth, TX Enclosed Cab & ROPS Structure - Fits Cat D6R
7472	Asset located in: Lake Worth, TX Palfinger PK15500 Knuckleboom Crane S/N: 100052586 Usage: Not Available Asset located in: Lake Worth, TX	7485	/ D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7473	HMT Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7486	Asset located in: Corsicana, TX Cat Cab - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7474	Quantity of (4) Seats & (2) Consoles S/N: Not Available Usage: Not Available		CONSTRUCTION Usage: Not Available Asset located in : Corsicana, TX
7475	Asset located in: Lake Worth, TX Quantity of Truck Toolbox & Ladder Rack S/N: Not Available C/W: Rawson Koenig tool box Usage: Not Available Asset located in: Lake Worth, TX	7487	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7488	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7498	Quantity of (2) Transmission S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
7489	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T		SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7499	2012 Hanco 20 ft Flatbed S/N: 107585 C/W: 2 storage boxes Usage: Not Available Asset located in: Lake Worth, TX
7490	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7500	Cat Radiator - Fits Truck S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7491	Cat Truck Dump Body S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length Usage: Not Available	7501	Quantity of Quarter Fenders S/N: 50567 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	7502	Hood S/N: Not Available
7492	Cat Truck Dump Body S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length Usage: Not Available		C/W: To Fit Hood Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	7503	Thermaflow Wet Kit S/N: Not Available
7493	Cat To Fit CAT 745 Truck Dump Body S/N: Not Available Usage: Not Available		C/W: Hoses, PTO, One Pallet Usage: Not Available Asset located in : Lake Worth, TX
7494	Asset located in: Lake Worth, TX John Deere To Fit Deere 410E Truck Dump Body S/N: Not Available Usage: Not Available Asset located in: Lake Worth TX	7504 	Quantity of (16) 22.5 Aluminum Rims S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7495	Asset located in: Lake Worth, TX Cat To Fit CAT 740B Truck Dump Body S/N: Not Available C/W: Lift Cylinders, Tailgate	7505	Quantity of (27) Brake chambers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Transmission	7506	Quantity of (2) Paccar 75 &100 gal 24.5 in dia Fuel Tanks (Unused) S/N: K424-0457N0102K075
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		Usage: Not Available Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7507	Volvo D13H Engine S/N: Not Available C/W: 6 Cylinder 425 hp Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
		7508	Quantity of (6) 19.5 steel rims (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7509 7510	Quantity of (2) Aluminum Fuel Tanks - Fits Freightliner Cascadia S/N: Not Available C/W: (1) 150 Gallon & (1) 125 Gallon Usage: Not Available Asset located in: Lake Worth, TX Detroit DD15AT Engine	7528	Quantity of (3) Truck Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	
	S/N: Not Available C/W: 6 Cylinder 505 hp 14.8 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	7529	Asset located in: Corsicana, TX Truck Toolbox S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	
7511	Quantity of (12) 22.5 Rims S/N: Not Available C/W: (9) Aluminum, (3) Steel, One Pallet Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUS' PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
7512	Quantity of (12) 24.5 In Steel Rims S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7531 7532 7533	Quantity of (3) Truck Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
7513	Quantity of (16) 22.5 In Aluminum Rims S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST E PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	
7515	International DT466 Engine with Spicer Transmission S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	
7516	hood to fit - Peterbilt 387 S/N: Not Available C/W: To Fit Peterbilt 387 Hood Usage: Not Available Asset located in: Lake Worth, TX		SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Merritt Saddle Box Truck Tractor Tool Box S/N: Not Available	
7517	Quantity of (2) Air ride seats S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	
7526	Quantity of (6) Truck Toolboxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		7533 Quantity of (2) Merritt Saddle Box Tr Tractor Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes : ITEM AT OFFSITE LOCATION MUST BE
7527	Truck Toolbox S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7534	Quantity of (2) ProTech Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7577	Water Pump Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7557	Truck Flatbed Body S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7578	Truck Blower Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7573	Synder Tank Corp Truck Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7579	Drive Axle S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7580	4.10 Axle S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7574	Quantity of (2) CNG Fuel Tanks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION License Not Available		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7591A	Etnyre Lowboy Stinger S/N: 30149-2 Usage: Not Available Asset located in: Lake Worth, TX
7575	Quantity of Truck Fuel Tanks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7592	Tag Axle S/N: Not Available C/W: Air Ride Suspension, 11R22.5, Aluminum Rims Usage: Not Available Asset located in: Lake Worth, TX
7576	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Wet Kit Pump and Hydraulic Tank	7593 7594 ST BE	Cat 3306 Engine S/N: 08Z32520 C/W: 6 Cylinder Diesel Engine Usage: Not Available
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		Asset located in: Lake Worth, TX Quantity of (6) PowerTrain PT240 Engine S/N: Not Available C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available Notes: Asset located in: Lake Worth, TX Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available

S/N: Not Available C/W: Gasoline Engine Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7596	Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7606	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX
7597	Quantity of (6) PowerTrain PTG2500XCS Engine (Unused) S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7607	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available
7598	Quantity of (6) PTTP300 Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7608	Asset located in: Lake Worth, TX Quantity of (4) Salvation Trailers (4)Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length
7599	Quantity of (6) PTWP400 Engine S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7609	Quantity of (4) Salvation Trailers (4) Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available
7600	Detroit 50435001 DD 453 Engine S/N: 4D0131900 C/W: 4 Cylinder Diesel Engine		C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7610	Quantity of (4) Salvation Trailers (4) Heavy Duty Metal Trailer Ramps (Unused)
7601	Isuzu Engine S/N: Not Available C/W: 4 Cylinder Diesel Engine Usage: Not Available		S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	7611	Quantity of (3) Mercury Boat Engine
7602	1996 Cat 3406E Engine S/N: 5EK38572 C/W: 6 Cylinder Diesel Engine		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7612	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T
7603	Cummins N14 Engine S/N: 11849308 C/W: 6 Cylinder Diesel Engine Usage: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
	Asset located in: Lake Worth, TX	7610	Asset located in: Corsicana, TX
7604	BMW Engine S/N: Not Available C/W: 6 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	7613	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7614	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T
7605	19 In x 71 In Loading Ramps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
7615	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7625	Quantity of (48) 205x75x15 Radial Tires & 5 Lug Wheels (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	
7616	Quantity of hydraulic hoses Hydraulic Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7626	Quantity of (4) 6-PLY RADIAL TIRE 5 ON 5 SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX	
7617	Quantity of (9) 11R24.5 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX	7627	Quantity of (4) 235/80R16 10-PLY RADIAL TRAILQUEST 16" 8-HOLE SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available	
7618	Alliance 700/40-22.5 Flotation Tire S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7628	Asset located in: Lake Worth, TX Quantity of (2) Armour 11.00-16 Tires S/N: Not Available C/W: All Tires with Wheels, EQUIPMENT-FROM-	
7619	Quantity of (2) 480/80R42 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX		WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	
7620	Quantity of (2) 1300x530x508 Tires S/N: Not Available C/W: Some Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX	7629	7629 2024 Agriquip GLTC24 Tire Changer S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESENT	2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7621	Quantity of (2) Hubs & Tires S/N: Not Available C/W: 18x8.50x10 Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
7622	Asset located in: Lake Worth, TX Quantity of John Bean Tire Balancer & Tire Changer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7630	2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
7623	Quantity of John Bean Tire Balancer & Tire Changer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7631	Quantity of (2) 2020 Weaver W-898XS Semi- Automatic Tire Changer S/N: 820052876/820052872 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	
7624	Quantity of (32) 235x80x16 10 Ply Radial Trailer Tires on Dial Wheels (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7635	Notes: . Asset located in: Lake Worth, TX Quantity of (2) Weaver W-898XS Semi Automatic Tire Changer S/N: 820052875/820052871 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7636	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042601H C/W: 110V, 2 HP Electric Motor, Bead Blaster System Usage: Not Available Asset located in: Humble, TX	7644	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050639 Usage: Not Available Asset located in: Lake Worth, TX
7637	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7645	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050640 Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7646	ARI Hetra HDML8 Electric 150000 Lbs Vehicle Lift S/N: 01050638 Usage: Not Available
7638	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7647	Asset located in: Lake Worth, TX 2024 Agriquip GLTP4500 10000 lb Two-Post Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7639	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Agriquip GLTP4500 10000 lb Two-Post Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7640	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7649	Asset located in: Lake Worth, TX Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7641	Asset located in: Lake Worth, TX Cuda H20-4860 Parts Washer - Fits CUDA H20- 4860 S/N: 10434450-100210 Usage: Not Available Asset located in: Midland, TX	7650	Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7642	Cuda H20-4860 Parts Washer - Fits CUDA H20- 4860 S/N: 10434450-100209 Usage: Not Available Asset located in: Midland, TX	7651	Quantity of (5) 2020 Weaver 10N000DWRD 10000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
7643	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050641 Usage: Not Available Asset located in: Lake Worth, TX		Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7652	Quantity of (2) 2020 Weaver F12N300BBL 12000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7659	Quantity of 2024 Landhero UBP-65-80 Universal Bucket Pin (Unused) S/N: Not Available C/W: (4) 65 mm x 475 mm & (4) 70 mm x 475 mm & (4) 80 mm x 550 mm,; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
7653	Transmission Stand S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhero UBP-90-100 Universal Bucket	
	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		Pin (Unused)	
7654	Graco Grease Injection Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES		S/N: Not Available C/W: (4) 90 mm x 650 mm, (2)100 mm x 750 mm, ;THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
	Asset located in: Corsicana, TX		THE ACTUAL PRODUCT	
7655	Quantity of (3) Bolt Bin	7661	Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Quantity of Engines and Generators S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7656	Greenlee 24 In x 48 In Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7662	7662 Excavator Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7657	Greenlee 24 In x 48 In Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	
7658	7663 2024 Landhero UBP-25-60 Universal Bucket Pin (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7663	Quantity of Parts & Tools S/N: Not Available C/W: (2) Seats, Mud Flap, Sockets, Barbed Wire, (2) Pallets Usage: Not Available Asset located in: Lake Worth, TX	
		7664	Pro Tech Aluminum Headache Rack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		7665	Quantity of PVC Fittings S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7666	Master MH190T-KFA 190000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX	7678	Quantity of Sheet Metal Parts S/N: Not Available C/W: assorted size & type Usage: Not Available Asset located in: Lake Worth, TX
7667	Quantity of (4) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7679 	Quantity of (2) Hydraulic Pumps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7668	Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	_ 7680	25' Steel Floor Ramp (Unused) S/N: Not Available C/W: 25'x101" Loading ramp, 12"x14Lbs I- beam frame, 6" channel in the middle, 3" Channel crossmembers, Smooth plate floor with expanded metal welded on, 18' long
7669	Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		angled ramp with 7' flat surface, 3-10K adjustable jacks. Usage: Not Available Asset located in : Lake Worth, TX
7670	Quantity of Parts & Tools S/N: Not Available C/W: Bosch Drill, Wrenches, Wheels, One Pallet Usage: Not Available	7681	Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7671	Asset located in: Lake Worth, TX NVE 607 Challenger Vacuum Pump S/N: 36777 Usage: Not Available Asset located in: Lake Worth, TX	7682 	Quantity of (2) Zato Hydraulic Pumps S/N: Not Available C/W: Linde HPV280; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7672	Quantity of Hydraulic Pump & Crusher Blades S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7683	Quantity of (2) Schaeffler Roller Bearings S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7673	Quantity of Contractor Supplies S/N: Not Available C/W: Hose, Poulan Pro Chain Saw, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7684	Star Industries 1210 4 ft x 8 ft Work Platform S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7674	Quantity of Truck Parts S/N: Not Available C/W: Exhausts/Pipes, Headlights Usage: Not Available Asset located in: Lake Worth, TX	7685	JLG 3248RS Parts S/N: Not Available C/W: Deck, Boom Arms, Cylinders Usage: Not Available Asset located in: Lake Worth, TX
7675	Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7686	Skyjack SJ8841 RT Parts S/N: Not Available C/W: Deck, Tires, Outriggers, Hyd Cylinders, Transfer Case, Drive Shaft, Engine, Fuel & Hydraulic Tank Box
7676	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX
7677	Quantity of (2) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7687	Quantity of Parts - Fits Chevrolet 3500 HD 6.0L S/N: Not Available C/W: Intake, Transfer Case, Wiring Harness Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7696	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7697	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7688	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7698	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7689	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7699	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7690	Crawler tractor drive motor teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7700	Asset located in: Corsicana, TX Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7691	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7701	Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311/314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available
7692	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7702	Asset located in: Lake Worth, TX Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311/314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available
7693	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		Asset located in: Lake Worth, TX Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available
7694	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7704	Asset located in: Lake Worth, TX Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear
7695	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7705 7706	Quantity of (4) Teran 1066878 Bucket Pins (Unused) - Fits Cat 315 S/N: Not Available C/W: 70mm X 508mm for Komatsu PC160 Front & Rear - 315 Linkage Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Teran 2357636 Bucket Pins (Unused) - Fits Cat 349	7710	Quantity of (2) Teran 2512558 Bucket Pins (Unused) - Fits Cat 336D S/N: Not Available C/W: 90mm X 635mm (Long total W/Flange) DB Linkage Rear for Cat 336D,330D,324E, 336ELH, 325D, 329E, 336FL, 325DLOEM, 330FL, 329DLN, 336EL, 336EH, 336ELN, 336EHVGOEM, 330CL, 324DL, 340FLLRE, 325DL, 324EL, 336FLXE, 329ELN, 385COEM, 329EL, 324ELN, 329D2L, 326D2, 329DL, 326FL
	S/N: Not Available C/W: 110mm X 705mm (Long total W/Flange) TB Linkage Front for Cat 345,345C,336DL, 352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349D2, 324D, 349DLVG, 336D2L, 349EL, 330DL, 345DL, 349FLXE, 336D2XE, 340FL, 340FLLRE, 336FLNXE, 336FL, 336DLN, 336ELN, 336D2LXE, 336FLN, 336D2, 349D2L,		340D2L, 326D2L, 324DLN, 324D, 336FLN, 336E, 385C, 340DL, 385CL, 325DLN, 329FL, 340FL, 329D2, 336FLNXE, 330FLN, 329D, 326DL, 345CLVG, 336ELNH, 336EOEM, 326FLN, 336FLH, 340FUHD, 336FXE, 340F, 336F, 328DLCR Usage: Not Available Asset located in: Lake Worth, TX
	336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH, 330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (2) Teran 4I5015 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 80mm X 735mm F Linkage for CAT 330,330B, 345B, 345C, 350, Usage: Not Available Asset located in: Lake Worth, TX
7707	(Unused) - Fits Cat 349 S/N: Not Available C/W: 100mm X 695mm (Long total W/Flange) TB Linkage Rear for Cat 345,345C,336DL, 352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349D2, 324D, 349DLVG, 336D2L, 349EL, 330DL, 345DL, 349FLXE, 336D2XE, 340FL, 340FLLRE, 336FLNXE, 336FL, 336DLN, 336ELN, 336D2LXE, 336FLN, 336D2, 349D2L, 336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH, 330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F	7711	Quantity of (4) Teran 7Y3549 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 80mm X 630mm D Linkage - Rear Usage: Not Available Asset located in: Lake Worth, TX
		7712	Quantity of (4) Teran 7Y3550 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 90mm X 650mm D Linkage - Front Usage: Not Available Asset located in: Lake Worth, TX
7708	Usage: Not Available	7713	2003 American Compaction DC-18S 18 in Backhoe Trench Wheel S/N: 4036094 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
		7714	Excavator compartment doors - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	336EHVGOEM, 336EH, 336ELN, 329D, 326DL, 345CLVG, 336ELNH, 336EOEM, 329ELN, 326FLN, 336FLH, 340FLLRE, 340FUHD, 336FXE, 340F, 336F, 328DLCR Usage: Not Available Asset located in: Lake Worth, TX	7715	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7716	Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7725	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7717	Quantity of (2) Pallets of engine bay doors S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7726	Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7718	Quantity of (2) Pallets of Bucket pins S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7727	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7719	Quantity of (2) Pallets of Misc. parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7728	Hood - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7720	Quantity of (2) Pallets of Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7729	Shovel holders S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7721	Asset located in: Corsicana, TX Quantity Of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7730	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7722	Asset located in: Corsicana, TX Quantity of Track Idlers - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	773 1	Quantity of (2) Pallets of Hand rails - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7723	Asset located in: Corsicana, TX Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7732	Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7724	Asset located in: Corsicana, TX Quantity of (2) Excavator components box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7733	Quantity Of Hydraulic Parts S/N: Not Available C/W: Hydraulic Hoses, Hydraulic Tank, Hydraulic Pump EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7734	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7743	Quantity of (2) Pallets of Crawler tractor parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7735	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7744	Bucket Cutting Edges S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7736	Quantity of (2) Pallets of Crawler tractor parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7745	Track Idlers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7737	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7746	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7738	Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7747	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7739	Asset located in: Corsicana, TX Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	— 7748	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7740	Asset located in: Corsicana, TX Quantity of (2) Pallets of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	— 7749	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7741	Quantity of (3) Track idlers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7749A	Walking Beam - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7742	Asset located in: Corsicana, TX Quantity of Parts S/N: Not Available	7749B	Middle & Front Frame - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in : Corsicana, TX	7749C	Quantity of (2) Stair/Fender Assemblies - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7750	Quantity of Shredder Teeth (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Pallets of Shredder Teeth S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING	7764	Quantity of Equipment and Vehicle Lights S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BI PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7765	Quantity of (3) Rims
7758	Quantity of (6) Wheels - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
7759	Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available	7766	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Overtice of Local Residue.
7760	Asset located in: Lake Worth, TX Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7766	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST I
7761	Quantity of Exhaust Stacks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	7767	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		Quantity of (2) 22.5 x 8.25 Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
7762	Quantity of Assorted Truck & Trailer Parts S/N: Not Available C/W: used tires, (3) Wheel barrows, air, fuel		PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	and hyd filters, banding machine, folding chairs, trash can, truck tractor seat, hyd hoses, mud flaps, brake pads, mirrors, a/c compressors, cat injectors, Denso Protal 7200 2 part resin, Black Beauty Abrasive, and misc parts Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE	7768 Quantity of 2 5/16 in Ball Hite S/N: Not Available C/W: EQUIPMENT-FROM-WA CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOG PICKED UP BY JANUARY 3RE SUBJECT TO 3RD PARTY STO Asset located in: Corsicana, 7 7769 Quantity of Mack Front Grills S/N: Not Available C/W: EQUIPMENT-FROM-WA CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOG PICKED UP BY JANUARY 3RE SUBJECT TO 3RD PARTY STO	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7763	Quantity of (3) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		

Lot #	Details	Lot #	Details
7770	Quantity of (4) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7776	Quantity of Truck Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7771	Quantity of Truck Side Panels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7777	Quantity of (2) Pallets of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7772	Quantity of Truck Metal Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7778	Quantity of Truck Tactor Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7773	Quantity of 2 5/16 in Ball Hitches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7779	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7774	Quantity of Radiators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7780	Quantity of (5) Portable Electrical Distribution Boxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Power Distribution Unit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE-
7775	Quantity of (2) 16 x 24 Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7782	EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX Ouantity of (9) Intertel Lighting Fixtures
		//82	Quantity of (8) Intertek Lighting Fixtures S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		7783	Quantity of (2) Stantion 3 Ft x 12 Ft Truck Undercarriage Wash System S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7784	101 in x 25 Ft Loading Ramp S/N: Not Available C/W: 45,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX	7794	Quantity of (3) 30 In x 42 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7784A	X-STAR 40 ft x 100 in Bridge (Unused) S/N: Not Available C/W: 14,000 lb. Usage: Not Available Asset located in: Lake Worth, TX	7795	Quantity of (3) 30 In x 42 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7785	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX	- 7796	Quantity of (3) 31 In x 72 In Metal Shop Tables S/N: Not Available C/W: Wilton Vise; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7786	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX	7797	Quantity of (2) Metal Tables S/N: Not Available C/W: (1) 20.5 in x 60 in, (1) 30 in x 72 in; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7787	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX	7798	Quantity of (5) Shop Supplies S/N: Not Available C/W: Engine Hoist, Shop Fan, (2) Dollies, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7788	101 in x 25 ft Bridge Platform Bridge - Fits xstar S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available	7800	Quantity of (2) Hydraulic Hose Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7789	Asset located in: Lake Worth, TX 101"x40' 14k Rated Bridge (Unused) S/N: Not Available C/W: 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (200) 2024 Suihe LCSS-200 Corrugated Structural Steel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7790	Quantity of (2) Stainless Steel Brewing Vats S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7791	Quantity of (2) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX		Asset located in: Lake Worth, TX Quantity of (200) 2024 Suihe LCSS-200 Corrugated Structural Steel (Unused) S/N: Not Available
7792	Quantity of (2) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7793	Quantity of (3) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7802	Quantity of (4) 2024 4-Fuel.com PFFF-ARLHALTO Safety Cabinets (Unused) S/N: Not Available C/W: DIMENSIONS 78" H x 39" W x 17" D Usage: Not Available Asset located in: Lake Worth, TX	7811	Quantity of (3) Pallets of Shop Fans S/N: Not Available C/W: (4) 42 in, (11) 24 in, (1) Air Mover; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7803	Quantity of Contractor Supplies S/N: Not Available C/W: Floor Jacks, Sockets, Bit Sets, Bottle Jack, Trolley Jack, One Pallet; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7813	Quantity of (3) Pallets of Shop Supplies S/N: Not Available C/W: (1) Pallet of Banders & Strapping, (1) Pallet of Shop Vacs & Mop Kits, (1) Table W /Roadmags; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: .
7804	Quantity of (3) Pallets of Rolling Service Carts S/N: Not Available C/W: Uline, U.S. General, (11) Carts; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7815	Asset located in: Lake Worth, TX Quantity of (3) Pallets of S/N: Not Available Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7805	Quantity of (7) Pallets of Tools & Parts S/N: Not Available C/W: Hose, Assorted Parts, Electrical Supplies; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7817	Quantity of (5) Pallets of Parts & Tools S/N: Not Available C/W: Hose, Wire, Pumps, Bolt Bins/Racks; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7807	Royal Gourmet 8 Burner Propane Grill S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7818	Quantity of (5) Hand Trucks S/N: Not Available C/W: (4) Martins 1000 lb capacity, one pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7808	31.5 In Rubber Belt S/N: Not Available C/W: Blue Rack; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7820	Quantity of (2) 30 In x 96 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7809	2020 Weg W21 Electric Motor S/N: 1053815288 C/W: 315 KW, 3 Phase, 467 Amp; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7822	Quantity of (3) Pallets of Belt Material S/N: Not Available C/W: Assorted Size/Type; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7810	Blue Diamond 1 1/4 In Sch 40 HDPE Conduit S/N: Not Available C/W: One Spool Usage: Not Available Asset located in: Lake Worth, TX	7823	Quantity of (2) Pallets of Tools S/N: Not Available C/W: Wrenches, Sockets, Drills, Impacts; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7824	Quantity of (16) 48 In x 48 In Wheeled Drain Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7833	Quantity of (7) Pallets of Misc S/N: Not Available C/W: Air Tanks, Tables, Power Strips, Cables, Misc EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7825	Quantity of (4) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7835	47.25 In Rubber Belt S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7826	GenMega G6000 Series ATM S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .	_7836	47 In x 47 In Platform Scale S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7827	Asset located in: Lake Worth, TX 300 Gallon Air Tank S/N: Not Available C/W: Ingersoll Rand PSG30 Separator System; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7838	Quantity of (3) Bundles of Cardboard Boxes S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	7839	Quantity of (4) Misc Supplies S/N: Not Available
7828	20 ton Air Press S/N: 193562011 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		C/W: (1) Pallet of Assorted Tools/Jacks, (1) Pallet of Assorted Filters, (1) Pallet of Misc, (1) Pallet of Assorted Parts/Fittings; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7830	Quantity of (4) 30 in x 96 in Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7841	Quantity of (2) Pallets of Misc Supplies S/N: Not Available C/W: Rakes/Shovels, Chains; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
7831	Modular Cage System S/N: Not Available C/W: Two Pallets; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7842	Asset located in: Lake Worth, TX Quantity of (8) Trash Cans S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7832	Quantity of Bolt Bins S/N: Not Available C/W: Contents, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7843	U. S. General 72 in 18-Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7844	Quantity of (3) Pallets of Misc Supplies S/N: Not Available C/W: (1) Pallet of Assorted Wire, (1) Pallet of Assorted Office Supplies, (1) Pallet of Chairs; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7855	Quantity of (3) Pallets of Parts, Mats & Trays S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	7856	Quantity of Tool Bins & Cabinet
7845	Quantity of (4) 30 In x 96 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: (1) 36 ln x 24 ln x 78 ln Cabinet W /Contents, Rolling Pegboard, Bolt Bins; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7846	Quantity of (3) Hopper Extensions S/N: Not Available C/W: (2) 69 In, (1) 74 In; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7857	Quantity of (10) Wen Industries 6 x 3 Ft Fluid Drain Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7847	Quantity of (3) 4 Ft x 4 Ft Storage Boxes S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7858	Quantity of (2) Pallets of Warehouse Supplies S/N: Not Available C/W: Assorted Hose, Safety Supplies; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
7848	Quantity of (4) Metal Shop Tables		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: (2) 30 In x 72 In, (1) 36 In x 72 In, vise, saw; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7860	Modular Cage System S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7849	Quantity of (5) Pallets of Assorted Filters S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7862	Gates GC32TSI Crimper Machine S/N: TSI0980E21 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7850	36 In x 44 In Steel Storage Cabinet S/N: Not Available C/W: Contents; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7863	JET JDP-15F 15" Drill Press S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7853	Quantity of (13) Pallets of Fluid Recovery Bay Protective Screens S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7864	Superwrap Taping Machine S/N: Not Available C/W: To Fit Superwrap Taping machine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
7865	Binks Pneumatic Paint Pot S/N: 316637 C/W: Hose, Hood Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7873	Quantity of Air Hose & Accessories S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7866	Carport Kit - 18 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	-7874 -	Entry Steps S/N: Not Available C/W: 36 in W, 18 in H Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
7867	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL E SUBJECT TO 3RD PARTY STORAGE F BUYER RESPONSIBLE FOR LOADOUT
7868	Carport Kit - 24 ft W x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7875	Asset located in: Lahoma, OK Quantity of (3) Piusi 017945010 DEF Pump S/N: Not Available C/W: Fits 55 Gal Drum
7869	Carport Kit - 18 ft w x 25 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
7870	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7871	Quantity of Oils, Service Fluids S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7876	Wheeler 4160 Pipe Threading Tripod S/N: Not Available C/W: Tools. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Laboras OK
7872	Quantity of (22) Wagner HPLV Paint Sprayer		Asset located in: Lahoma, OK
	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7877	Napa, Carlyle 7915070B Engine Stand S/N: Not Available C/W: To Fit Carlyle 7915070B, Geared Rotation Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
7878	Napa, Carlyle 7916021A Engine Hoist S/N: Not Available C/W: To Fit Carlyle 7916021A Engine Hoist, With Spreader Bar Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7884	Quantity of Power Washers and Generators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
		7885	Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7070	Asset located in: Lahoma, OK	7006	<u> </u>
7879	Napa, Carlyle 7917170A Transmission Jack S/N: Not Available C/W: To Fit Carlyle 7917170A Transmission Jack, 1 Ton Capacity Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7886	Quantity of Pressure Washer and Concrete Saw S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
		7887	Quantity of Weed Eater, Tools, Sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7880	Graco Line Lazer IV Walk Behind Paint Striper S/N: Not Available C/W: 2008 US EPA Label, Honda 163 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7888	Misc. shop supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7001		7000	· · · · · · · · · · · · · · · · · · ·
7881	Centech Battery Charger S/N: Not Available C/W: Shop-Vac, Oil Pump, Oil, Fencing Supplies. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of Contractor Supplies S/N: Not Available C/W: Vice, Extension Cords, Bolts, Pillow Block Bearings, Track Link for JOHN Deere 2106, Trailer Parts Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7889	Quantity of Generators and Water Pumps S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
		7890	Quantity of (4) Airless paint sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
			Asset located in: Corsicana, TX
7882		7891	Construction supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
		7892	Generator, plate compactor, water pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7000	Asset located in: Lahoma, OK Oughtity of (2) Crease of DVC Fittings 4" 12"	7000	·
7883	Quantity of (3) Crates of PVC Fittings 4"-12" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7893	mail box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7894	Quantity of (8) Torque Wrenches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7903	construction supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7895	shop tools S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7904	Quantity of Power Washers, Battery Charger, Air Compressor S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7896	Quantity of Vibratory Plate Compactor, Generator, Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7905	Asset located in: Corsicana, TX Quantity of Shop Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7897	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7906	Pipe sizers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7898	Quantity of Shop Tools S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7907	Quantity of chlorine recovery boxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7899	Asset located in: Corsicana, TX Construction supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	7908	SCBA packs S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: Not Available Asset located in : Corsicana, TX	7909	FS400ASK oil skimmer S/N: A2968 C/W: 1 Cylinder Gasoline Engine Usage: Not Available
7900	Quantity of Shop Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7910	Asset located in: Lake Worth, TX misc firefighting accessories S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7901	Misc Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7911	Miller Bobcat 225NT Stick Engine Driven Welder (Inoperable) S/N: KJ029548 C/W: Onan 2 Cylinder Gasoline Engine Usage: 763 Hr Notes: INOPERABLE ITEM MUST BE REMOVED
7902	Misc. shop supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Corsicana, TX	7912	Quantity of Misc. wiring S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available

Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7913	Quantity of (7) Pneumatic Concrete Breakers S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7923	Haul Master 5-Ton Crane Hoist S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
7914	Quantity of Napa Oil Filters (Unused) S/N: Not Available C/W: Assorted Size/Type Usage: Not Available Asset located in: Lake Worth, TX		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
7916	100 Ft Galvanized Chain S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	- 7924	Quantity of Assorted Shop Tools and Parts S/N: Not Available C/W: Hammer Wrenches, 1 in Torque Wrenches, Micro Tester, Valves, Filing Cabinet, Shop Fan, Heavy Duty Rack, Brake Bands, Pipe Benders, Caulking Guns, Misc Shop Tools
7917	Scotsman C05305A-1E Ice Machine S/N: 19051320014944 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
7918	Ice-O-Matic CIM0430FA Commercial Ice maker w/ collection bin S/N: 23011280011235		FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Usage: Not Available	7925	Quantity of Bolts
7919	Asset located in: Lake Worth, TX Comfortmaker NXA660GKA100 Air Conditioner S/N: E160802838 Usage: Not Available Asset located in: Lake Worth, TX 2020 H&S 410 S/A Running Gear	- -	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
,,,,,	S/N: 021SG10014		Asset located in: Corsicana, TX
7921	C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX Reelcraft Compressor Cart S/N: Not Available C/W: Hose Reel; EQUIPMENT-FROM-WATKINS-CONSTRUCTION	7926	Quantity of Metal Grating S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7927	Asset located in: Corsicana, TX Quantity of Safety Air Masks S/N: Not Available
7922	Asset located in: Corsicana, TX Quantity of Assorted Shop Tools and Supplies		C/W: Tank Holders, Regulators Usage: Not Available Asset located in : Lake Worth, TX
7922	(Inoperable) S/N: Not Available C/W: (1) Craftsman Weed Eater, (2) Generators, (1) Pressure Washer, (5) Trash Pumps, Ladders, Bolt Bin with Contents, Pressure Washer and Air Hoses, Spill Kits, Electrical Wire, Misc Shop Tools, Electrical Supplies and Misc Shop/Warehouse Equipment Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	7928	Suihe Mens/Womens Portable Restroom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		Greatbear 2 Ton Magnetic Lifter & 5 Ton Scale (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7930	Quantity of (4) Pallets of Chains and Clevises (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7940	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX
7931	Quantity of (9) Thermal Arc Suitcase Welders S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7941	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available
7932	Big Daddy Targets Large AR500 Shooting Target (Unused) S/N: Not Available C/W: Bigfoot W/Fish Motif Usage: Not Available Asset located in: Lake Worth, TX	7942	Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available
7933	Big Daddy Targets Large AR500 Shooting Target (Unused) S/N: Not Available C/W: T-Rex Motif Usage: Not Available Asset located in: Lake Worth, TX	7943	Asset located in: Lake Worth, TX Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available C/W: Coyote & Deer Motif Usage: Not Available Asset located in: Lake Worth, TX
7934	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Raccoons Motif Usage: Not Available Asset located in: Lake Worth, TX	7944	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available C/W: Hogs & Sheep Motif Usage: Not Available Asset located in: Lake Worth, TX
7935	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available	7945	Steel Shooting Target (Unused) S/N: Not Available C/W: Bigfoot Motif Usage: Not Available Asset located in: Lake Worth, TX
7936	Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available	7946	Steel Shooting Target (Unused) S/N: Not Available C/W: Gunfighter Motif Usage: Not Available Asset located in: Lake Worth, TX
 7937	C/W: Birds & Raccoons Motif Usage: Not Available Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting	7947	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7948	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7938	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Turkey Motif Usage: Not Available	7949	Target (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
7939	Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX	7950	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7951	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7962	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available
7952	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7963	Asset located in: Lake Worth, TX Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available
7953	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7964	Asset located in: Lake Worth, TX Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available
7954	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7965	Asset located in: Lake Worth, TX Big Daddy Fire Pits 30 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available
7955	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7966	Asset located in: Lake Worth, TX Big Daddy Fire Pits 30 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available
7956	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7967	Asset located in: Lake Worth, TX Big Daddy Fire Pits 24 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available
7957	Big Daddy Feeders Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7968	Usage: Not Available Asset located in: Lake Worth, TX Big Daddy Fire Pits 24 Inch. Decorative Met Fire Pit (Unused)
7958	Big Daddy Feeders Deer Feeder (Unused) S/N: Not Available Usage: Not Available	7060	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
7959	Asset located in: Lake Worth, TX Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7969	Quantity of Sand Bags S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
7960	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK
7961	Usage: Not Available Asset located in: Lake Worth, TX Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7970	Quantity of (2) Bundles of 40 Ft Angle Iron S/N: Not Available C/W: (1) 1 1/2 In, (1) 2 In Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7971	Quantity of (5) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX	7981	Supershear Hydraulic Catalytic Converter Cutter S/N: 1409 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7972	Quantity of (2) Bundles Of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7982	Quantity of Conveyer Belts & Rollers S/N: Not Available C/W: (1) 10 In Belt, (1) 24 In Belt, (1) 47 In Vinyl, (3) 84 In Rollers; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available
7973	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7983	Asset located in: Lake Worth, TX Quantity of HWI MC25 Plus Fireclay Based Cement S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO-
7974	Quantity of (1) Bundle of Cattle Fence Stay Lock 12.5-12.5 S/N: Not Available		RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7975	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles Of Channels 4 in x 5.4	7984	Quantity of (8) Reelcraft HD76100 Hose Reels S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING
	A36/529-50 20 ft S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
7976	Asset located in: Lake Worth, TX Manitowoc SY0324A Ice Machine S/N: 110558398 Usage: Not Available Asset located in: Lake Worth, TX	7985	Quantity of (3) Donaldson Torit MM1200 Electric Mist Collectors S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7977	Manitowoc QY0454A Ice Machine S/N: 040262489 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	7987	Hillman 15 Ton Rollers S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
7978	Asset located in: Lake Worth, TX Dust Collector S/N: Not Available Usage: Not Available	7988	Quantity of (6) Pipe Racks S/N: Not Available C/W: Assorted Sizes Usage: Not Available Asset located in: Lake Worth, TX
7979	Asset located in: Lake Worth, TX Park Indistries Fastback Electric Stone Polisher S/N: Not Available C/W: extensions Usage: Not Available Asset located in: Lake Worth, TX	7989	Quantity of Contractor Supplies S/N: Not Available C/W: Lockout Tags, Marking Paint, Measuring Wheel, Hitch Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST
7980	Supershear Hydraulic Catalytic Converter Cutter S/N: 1411 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
7990	Quantity of (3) Fuel Cans & (1) Lifting Strap S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7998	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX
		7999	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available
7991	Asset located in: Lahoma, OK Quantity of (4) Gas Monitors	-	C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	8000	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8001	Quantity of (10) Storage Crates S/N: Not Available
7992	Quantity of (10) Pallets of Shelving Guardrails & Accessories		C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	8002	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7993	Asset located in: Lake Worth, TX Oughtity of (2) Pollote of Peoleroft HD76100		Asset located in: Lake Worth, TX
7993	Quantity of (2) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7994	Quantity of (2) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	8004	Quantity of (6) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7995	Asset located in: Lake Worth, TX Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase	8005	Quantity (3) Commercial (Car Wash) Vacuum System S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8006	Quantity of (5) Pallets of Generators &
7996	Quantity of (2) Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase, (1) Koehring B150D, (1) Porta Heat 97 Usage: Not Available Asset located in: Lake Worth, TX		Pressure Washers S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac, Titan, North Star, Simpson, Ex-Cell, Mi-T-M, Power Ease Usage: Not Available Asset located in: Humble, TX
7997	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8007	10 ft x 10 ft Canopy S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	8017	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8018	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle
8010	2017 Tennant T20 Ride-On Floor Sweeper S/N: T20-9225		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 56 in Working Width, Water System, Rear Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 2,922 Hr Asset located in : Lake Worth, TX	8019	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle
8011	2016 Tennant T20 Ride-On Floor Sweeper S/N: T20-6540		Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 48 in Working Width, Water System, Rear Squeegee, PSI 4 Cylinder 2.0 L Dual Fuel Engine Usage: 1,348 Hr Asset located in : Lake Worth, TX	8020	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle
8012	2015 Tennant T20 Ride-On Floor Sweeper S/N: T20-6442		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 56 in Working Width, Water System, Rear Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 566 Hr Asset located in : Lake Worth, TX	8021	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available
8013	2019 Tennant M17 Ride-On Electric Floor Sweeper	8022	C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	S/N: M17-11001 C/W: 52 in Working Width, Water System, Rear Squeegee, 36 Volt Operating System Usage: 4,574 Hr Asset located in: Lake Worth, TX		Pipe (Unused) S/N: Not Available C/W: One Bundle
8014	2019 Tennant T17 Ride-On Floor Sweeper		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: T17-13185 C/W: 44 in Working Width, 36 Volt Operating System Usage: 2,013 Hr Asset located in : Lake Worth, TX	8023	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available
8015	2016 Tennant T17 Ride-On Electric Floor Sweeper		Asset located in: Lake Worth, TX
	S/N: T17-11025 C/W: 44 in Working Width, Water System, 36 Volt Operating System Usage: 2,098 Hr Asset located in : Lake Worth, TX	8024	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available
8016	Quantity of (16) 3-5/8 in Square Gauge 12	9025	Asset located in: Lake Worth, TX
	Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8025	Quantity of (19) 2 7/8 In OD Pipe S/N: Not Available C/W: 21 ft, one bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8026	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8035	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8027	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8036	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8028	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8037	Quantity of (25) 20 ft x 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8029	Quantity of (25) 19 ft 2 in x 2 3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8038	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8030	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8039	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8031	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8040	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8032	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8041	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8033	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8042	Quantity of (61) 21 ft x 1 5/8 in OD Schedule- 10 Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8034	Quantity of (25) 19 ft x 2 in x 2 3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8043	Quantity of (2) Water Pumps S/N: Not Available C/W: Diaphragm, (1) Wilden 2 In, (1) 2.5 In Water Pumps Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8044	Quantity of Safety Supplies S/N: Not Available C/W: (4) Fall Protection Harnesses Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8052	Donzi 32 ft Wood Cabin Cruiser (Inoperable) w/ Trailer S/N: Not Available C/W: T/A Trailer, Ball Hitch Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	8054	Quantity of (2) 2020 Ludlum Radiation
8045	Quantity of Safety Supplies S/N: Not Available C/W: Vests, Hard Hats, Safety Glasses, Latch Kits Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE		Detectors S/N: 348035 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - GEIGER COUNTER Asset located in: Lake Worth, TX
8046	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of Safety Supplies	8055	Vortex Hydraulic Catalytic Converter Decanner S/N: Not Available C/W: 10 hp hydraulic power unit, 2014 P & J Dust Extraction LTD PJB175-4.8-8-1E2-1-JMC- 60 dust collector s/n 98468, work platform; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
	S/N: Not Available C/W: Assorted Truck and Safety supplies		Asset located in: Lake Worth, TX
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	8056	Quantity of (3) 2021 Vortex PFS Gas De- Pollution Systems S/N: 139/041 C/W: (2) Gas Tank Tower System Punch; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Lahoma, OK	8057	Quantity of (4) 2020 Vortex UHPC Fluid De-
8047	Quantity of Chain Construction Hoist S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Pollution System Pump S/N: Not Available C/W: 3 Fluid Distraction, oil, coolant, washer fluid; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
8048	60 in x 565 ft Rubber Conveyor Belt		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	8058	2008 Bosch 11304KD Demolition Breaker S/N: 889-000307 C/W: EQUIPMENT-FROM-SUNSTATE-
8049	42 in x 570 ft Rubber Conveyor Belt S/N: Not Available Usage: Not Available		EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8060	2024 Landhonor LHR-PSM26A 26 in Portable
8050	Bridgestone 60 in x 525 ft Conveyor Belt S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Sawmill (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
8051	32 in Discharge Conveyor Belt - Fits Vermeer Trencher S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8061	2024 Paladin PLD-PSM31H 31 in Portable Sawmill (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	8068	2014 Jungheinrich ECR327 6000 lb Electric Pallet Jack S/N: 82800864 C/W: 6000 lb Capacity, 24 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX Jungheinrich EJE120 Electric Pallet Jack S/N: Not Available
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
8062	2020 Mcintyre 600 HD Metal Shear S/N: 765		Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8070	Toyota 8HBW23 4500 lb Electric Pallet Jack S/N: 8HBW2322023 C/W: 4500 lb Capacity, 24 V Usage: Not Available Asset located in: Lake Worth, TX
8063	2020 JET Electric Band Saw S/N: 081337 C/W: 1 Hp Electric, .75 blade, Milwaukee 40 in work station; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2012 Rico PWH-DD-300 Electric Pallet Jack S/N: R-14544 C/W: 30000 lb Capacity, 24 V, Battery Charger Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
8064	2023 MMLJ DB500 Mobile System Sand	8072	2008 Tempest PAL30 Electric Fan
0001	Blaster S/N: 1M9BU1828PH774174 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9890 lb GVWR Usage: Not Available Notes:	50,2	S/N: 6050820402234 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Midland, TX	8073	2008 Tempest PAL30 Electric Fan
8065	2019 Allegro Ambient Air Pump Sand Blaster S/N: 336581 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available		S/N: 6030820400225 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
8066	Asset located in: Lake Worth, TX Quantity of Assorted Steel Cable Cable S/N: Not Available	8074	Quantity of (3) 24 In Shop Fan S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WI SUBJECT TO 3RD PARTY STORA BUYER RESPONSIBLE FOR LOAD NOT BE ABLE TO ASSIST WITH L	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8075	Asset located in: Lake Worth, TX Quantity of (2) J & D Mfg VPRF36 36 in Fan S/N: 0621 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	8076	Quantity of (4) Pallets of 24 In x 72 In Pallet
8067	Quantity of (6) Ladder S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		Racking S/N: Not Available C/W: 24 In x 48 In Wire Racks, 96 In Crossarms; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes:

Lot #	Details	Lot #	Details
8077	Quantity of Industrial Pallet Racking S/N: Not Available C/W: (10) Pallets of 42 In x 25 Ft Uprights, (7) Pallets of 96 In Crossarms, (2) Pallets of 144 In Crossarms, (54) Pallets of 43 In x 46 In Wire Racks; EQUIPMENT-FROM-US-AUTO- RECYCLING	8086	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: Asset located in: Lake Worth, TX	8087	Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available
8078	Quantity of Uline 36 In x 72 In Shelving S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO-		C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8088	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available
8079	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle		C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8089	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft
8080	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle Usage: Not Available	8090	S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX		Quantity of (6) 5 X 4 X 11 GA Rectangle Tube
8081	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle Usage: Not Available		S/N: Not Available C/W: One Bundle Usage: Not Available
8082	Asset located in: Lake Worth, TX Quantity of (9) 5X4X11 GA Rectangle Tube	8091	Asset located in: Lake Worth, TX Quantity of (9) 5X4X11 GA Rectangle Tube
0002	17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8083	Quantity of 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8092	Quantity of 4X3X1/4 Angle Iron S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8084	Quantity of (6) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8093	Quantity of 4X3X1/4 Angle Iron S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8085	Quantity of (6) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available	8094	Quantity of (3) 1/4 in Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8095	Quantity of (5) 3/16 Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8096	Quantity of (4) Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8106A	Quantity of Corrugated Sheet Metal S/N: Not Available C/W: Assorted Length Usage: Not Available Asset located in: Lake Worth, TX
8097	Quantity of (8) Diamond Plate Steel S/N: Not Available C/W: Assorted Size Usage: Not Available Asset located in: Lake Worth, TX	8107	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8098	Quantity of (6) Diamond Plate Steel S/N: Not Available C/W: Assorted Size Usage: Not Available	8108 8109	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8099	Asset located in: Lake Worth, TX Quantity of (3) Diamond Plate S/N: Not Available C/W: Assorted Size, One Bundle Usage: Not Available	8110	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 38 ft x 40 ft Shipping Container Roof Cover Kit
8100	Asset located in: Lake Worth, TX Quantity of (2) 8GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shipping Container Roof Cover Usage: Not Available Asset located in: Lake Worth, TX
8101	Quantity of (8) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8111	38 ft x 40 ft Shipping Container Roof Cover Kit (Unused) S/N: Not Available C/W: Quantity of (2) Crates - Builds (1) Container Roof Cover Kit. Usage: Not Available
8102	Quantity of (7) 10GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8112	Asset located in: Lake Worth, TX Quantity of (100) 2024 SUNTOP S2134C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
8103	Quantity of (7) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8104	Quantity of (6) 10 GA Steel Plate S/N: Not Available C/W: One Bundle		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
8105	Usage: Not Available Asset located in: Lake Worth, TX Ouantity of (4) 10 GA Stool Plate	8113	Quantity of (100) 2024 SUNTOP S2134C 7 ft x 35 in Corrugated PPGI Steel Panels (Unused) S/N: Not Available
0100	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
8106	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8114	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8118	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
8115	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8119	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
8116	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8120 8121 8122	Quantity of Assorted Brackets S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of Filters S/N: Not Available C/W: Assorted Size/Type, One Crate Usage: Not Available Asset located in: Lake Worth, TX Quantity of Concrete Mix S/N: Not Available
8117	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8123	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of Mohawk -20 Sand S/N: Not Available
			C/W: (7) 80 lbs bags Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
8124	2015 Grainger 29AK54 Dolly Johnson Bars S/N: N/A C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8135	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
8125	2014 Grainger 4W944 72 in Dolly Johnson Bars S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8128	Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8136	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE
8129	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8130	Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8137	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE
8131	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8132	Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE
8133	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in : McAlester, OK
	Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber
8134	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK

Lot #	Details	Lot #	Details
8140	Quantity of (26) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	8146	2019 KwiKool KP05-21H Air Conditioner S/N: 1014318 Usage: Not Available Notes: .
		8147	Asset located in: Lake Worth, TX Quantity of (3) Air Conditioner S/N: Not Available Usage: Not Available
	Asset located in: McAlester, OK		Asset located in: Lake Worth, TX
8141	Quantity of (23) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available		Quantity of (2) GE Window Air Conditioner S/N: Not Available C/W: 99 sqft, 230v, 17,600 BTU Usage: Not Available Asset located in: Lake Worth, TX
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	8149	AXH 42VVF Air Cooler S/N: 149606G Usage: Not Available Asset located in: Midland, TX
	Asset located in: McAlester, OK	8150	AXH 42VVF Air Cooler
8142	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE		S/N: 149491K Usage: Not Available Asset located in : Midland, TX
		8151	AXH 42VVF Air Cooler S/N: 149491 D Usage: Not Available Asset located in: Midland, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8152	AXH 42VVF Air Cooler S/N: 149606 F Usage: Not Available Asset located in: Midland, TX
8143	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	8153	AXH 42VVF Air Cooler S/N: 149491 L Usage: Not Available Asset located in: Midland, TX
		8154	ASSET located in: Midland, TX AXH 42VVF Air Cooler S/N: 149491 Q Usage: Not Available Asset located in: Midland, TX
	Asset located in: McAlester, OK	— 8155	AXH 42VVF Air Cooler
8144	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available		S/N: 119084 C Usage: Not Available Asset located in : Midland, TX
	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	8156	AXH 42VVF Air Cooler S/N: 119084B Usage: Not Available Asset located in: Midland, TX
	FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8157	AXH 42VVF Air Cooler S/N: 1494910
8145	2019 KwiKool KPO5-21H Air Conditioner	\dashv	Usage: Not Available
J 17J	S/N: 1014321 Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8158	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149606I Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
8159	AXH 42VVF Air Cooler S/N: 149606 E Usage: Not Available Asset located in: Midland, TX	8172	AXH 36VVF Air Cooler S/N: 89463E Usage: Not Available Asset located in: Midland, TX
8160	AXH 42VVF Air Cooler S/N: 149491E Usage: Not Available Asset located in: Midland, TX	8173	AXH 36VVF Air Cooler S/N: 89463 C Usage: Not Available Asset located in: Midland, TX
8161	AXH 42VVF Air Cooler S/N: 149491 P Usage: Not Available Asset located in: Midland, TX	8174	AXH 36VVF Air Cooler S/N: 89463 D Usage: Not Available Asset located in: Midland, TX
8162	AXH 42VVF Air Cooler S/N: 149606J Usage: Not Available Asset located in: Midland, TX	8175	AXH 36VVF Air Cooler S/N: 89509A Usage: Not Available Asset located in: Midland, TX
8163	AXH 42VVF Air Cooler S/N: 149491 J Usage: Not Available Asset located in: Midland, TX	8176	AXH 36VVF Air Cooler S/N: 89509B Usage: Not Available Asset located in: Midland, TX
8164	AXH 42VVF Air Cooler S/N: 149606 H Usage: Not Available Asset located in: Midland, TX	8177	AXH 36VVF Air Cooler S/N: 89416E Usage: Not Available Asset located in: Midland, TX
8165	AXH 42VVF Air Cooler S/N: 149491 I Usage: Not Available Asset located in: Midland, TX	8178	AXH 36VVF Air Cooler S/N: 89463 F Usage: Not Available Asset located in: Midland, TX
8166	AXH 42VVF Air Cooler S/N: 149491 G Usage: Not Available Asset located in: Midland, TX	8179	AXH 36VVF Air Cooler S/N: 89416 C Usage: Not Available Asset located in: Midland, TX
8167	AXH 42VVF Air Cooler S/N: 149491 N Usage: Not Available Asset located in: Midland, TX	8180	AXH 36VVF Air Cooler S/N: 89509 C Usage: Not Available Asset located in: Midland, TX
8168	AXH 42VVF Air Cooler S/N: 119084 A Usage: Not Available Asset located in: Midland, TX	8181	AXH 36VVF Air Cooler S/N: 89463 B Usage: Not Available Asset located in: Midland, TX
8169	AXH 42VVF Air Cooler S/N: 149491 F Usage: Not Available Asset located in: Midland, TX	8182	AXH 36VVF Air Cooler S/N: 89463 A Usage: Not Available Asset located in: Midland, TX
8170	AXH 42VVF Air Cooler S/N: 149491 M Usage: Not Available Asset located in: Midland, TX	8183	2015 Air Comman AC1600 Hydraulic Oil Cooler S/N: AC29 Usage: 124 Hr Notes: .
8171	AXH 42VVF Air Cooler S/N: 149491 H Usage: Not Available Asset located in: Midland, TX	8184	Asset located in: Lake Worth, TX 2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1798 Usage: Not Available Notes: .

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8185	2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1794 Usage: Not Available Notes: . Asset located in: Lake Worth, TX 2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1797 Usage: Not Available Notes: .	8194	S/N: Not Available C/W: Propane Fueled, (3) Space Heaters, Tanks, (1) Burner Wand. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MI BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES BUYER RESPONSIBLE FOR LOADOUT. RE	S/N: Not Available C/W: Propane Fueled, (3) Space Heaters, (9) Tanks, (1) Burner Wand. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
8187	Asset located in: Lake Worth, TX Quantity of (4) Heaters S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	8196	THESE Asset located in: Lahoma, OK Innovatech Terminator 2000El Electric Ride-On Floor Scraper S/N: T200E302IB	
-	Asset located in: Corsicana, TX		Usage: 1,733 Hr Asset located in: Lake Worth, TX	
8188	2018 Campo EB400D 400000 BTU Space Heater S/N: B400-17-9254 C/W: Diesel Fueled Usage: Not Available Notes:	8197	Karcher Chariot 2 iVac 24 ATV Electric Ride-On Vacuum Cleaner (Unused) S/N: 10090690000894 Usage: Not Available Asset located in: Lake Worth, TX	
8189	Asset located in: Lake Worth, TX 2018 Campo EB400D 400000 BTU Space Heater S/N: B400-18-8975 C/W: Diesel Fueled, 120 V Input	8198	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240913 Usage: Not Available Asset located in: Lake Worth, TX	
8190	Usage: Not Available Notes: Asset located in: Lake Worth, TX Heat star HS3500DF 361439 BTU Space Heater	8199	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240915 Usage: Not Available Asset located in: Lake Worth, TX	
8191	S/N: 27901109 C/W: Kerosene Fueled, 120 V Input Usage: Not Available Asset located in: Lake Worth, TX Mi-T-M 375000 BTU Space Heater		2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240914 Usage: Not Available	
8192	S/N: Not Available C/W: Propane Fueled, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8201	Asset located in: Lake Worth, TX 2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240916 Usage: Not Available	
0192	Quantity of (4) Mr. Heater 60,000 BTU Forced Air Space Heater S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8202	Asset located in: Lake Worth, TX 2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available	
8193	Quantity of (4) Mr. Heater 60000 BTU Space Heater S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8203	Asset located in: Lake Worth, TX 2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		8204	Quantity of Human Touch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8205	2024 Landhonor LHR-MC766 Massage Chair Sofa (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8218	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8206	BarcaLounger (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8219	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available
8207	Osaki 3D Prestige Massage Chair S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8220	Asset located in: Lake Worth, TX Legend Walk Behind 20 in Garden Tiller S/N: Not Available C/W: Legend Force 212 cc Gasoline Engine
8208	Osaki 3D Prestige Massage Chair S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8221	Usage: Not Available Asset located in: Lake Worth, TX Legend Walk Behind 20 in Garden Tiller S/N: Not Available
8209	Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid		C/W: Legend Force 212 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	8222	Quantity of (18) Rhino Rugged Landscaping Tools W/ Fiberglass Handles S/N: Not Available
8210	Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: (3) # 12 Aluminum Scoop, (3) 16 in Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10 in Hoe, (3) Square Pt Shovel Usage: Not Available Asset located in: Lake Worth, TX
8211	GE Front Load Washer & Dryer Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8223	Quantity of (18) Rhino Rugged Landscaping Tools W/ Fiberglass Handles S/N: Not Available C/W: (3) # 12 Aluminum Scoop, (3) 16 in Dra
8212	Frigidaire Freezer S/N: AA15240684 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	8224	Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10 in Hoe, (3) Square Pt Shovel Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Hand Held Pump Sprayers
8214	Asset located in: Lake Worth, TX True 3-Door Commercial Refrigerator S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8224	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
8215	Quantity of (3) Meat Slicers S/N: Not Available C/W: (2) Bizerba, (1) Hobart Usage: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
8216	Asset located in: Lake Worth, TX Quantity of (7) Pallets of Landscape Sandstone Boulders S/N: Not Available C/W: assorted size, shape Usage: Not Available Asset located in: Lake Worth, TX	8225	Quantity of Chainsaws S/N: Not Available C/W: String Trimmer, Accessories Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OF WILL BE
8217	Quantity of (7) Pallets of Landscape Sandstone S/N: Not Available C/W: assorted size, shape Usage: Not Available Asset located in: Lake Worth, TX		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
8226	Predator Power Auger S/N: 44FAPL24013877 C/W: 2024 US EPA Label, Predator 1 Cylinder 52 cc Gasoline Engine, (1) 8 in Auger, (1) 6 in Auger Usage: Not Available	8235	Quantity of (2) Dolly Bars S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8236	Pearl Abrasive 15 In Floor Preparation Disc S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
8227	Asset located in: Lahoma, OK Quantity of (4) Kubota Mower Decks S/N: Not Available C/W: (3) 60 in & (1) 72 in Mower Decks Usage: Not Available Asset located in: Lake Worth, TX	8237	Quantity of Cat Final Drive Sprocket Segments - Fits Cat D6 S/N: Not Available C/W: To Fit Cat D6M, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available
8228	Crary 75060 Lawn Vacuum S/N: 103825 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	8238	Asset located in: Corsicana, TX Pipe handler S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
8229	Craftsman Walk-Behind Leaf Vacuum S/N: 1H01NK10291 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX Quantity of Rhino Rugged Landscaping Hand	8239	Quantity of (3) Cat Weights S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
8231	Tools S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Cat Engine (Inoperable) S/N: Not Available	8240	Asset located in: Corsicana, TX Grieve 333 Electric Airless oven - Fits S/N: 104626A1111 C/W: To Fit Grieve 333 Electric Industrial Oven, Grieve .33 hp 3 Phase Motor Usage: Not Available Asset located in: Midland, TX
	C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	8241	Grieve 3330 Electric Airless oven S/N: 114490A0315 C/W: To Fit Grieve 333 Electric Industrial Oven, Grieve .33 hp 3 Phase Motor Usage: Not Available Asset located in: Midland, TX
8232	Quantity of Truck Parts S/N: Not Available C/W: Hubs, Fenders, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	8242	2018 Bomag BMP8500 Trench Compactor S/N: 101720129533 C/W: 2018 US EPA Label, Kubota D1005 3 Cylinder 14.3 kW 1.0 L Diesel Engine, 32 in drums w/extensions, remote; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT
8233	72 in Forks S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	8243	Usage: Not Available Asset located in: Lake Worth, TX Mobydick Kitflex 400C Wheel Washing System
8234	Cat 48 in Q/C Wheel Loader Forks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details	
8244	Quantity of (2) Pallets of engine bay doors S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	8254	2014 Sokkia 7383-40 w/ Grade Rod Laser Level S/N: 270612 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
8245	bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	8255	Trimble EM410 Antenna Mount S/N: 2599J501CN Usage: Not Available Asset located in: Lake Worth, TX	
8246	Asset located in: Corsicana, TX JLG Man Basket S/N: 2017920 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8256	Topcon GP-3 S/N: Not Available C/W: Topcon GR-3 RTK GPS GNSS, SN#442- 0693, Topcon GR-3 RTK GPS GNSS, SN#442- 0485, Topcon FC-2600 Data Collector, SN#55802743 Usage: Not Available Asset located in: Lake Worth, TX	
8246A	S/N: 1676784 C/W: 3 ph Usage: Not Available Asset located in : Oklahoma City, OK	8257	Topcon Hiper Lite RTK S/N: Not Available C/W: Topcon Hiper Lite RTK GPS, SN#263- 1167, Topcon Hiper Lite RTK GPS, SN#296- 0181, Topcon FC-120 Data Collector, SN#2065	
8247	2024 Machpro MP-MS100 Sofa (Unused) S/N: SLP2707080862 Usage: Not Available Asset located in: Lake Worth, TX	8258	Usage: Not Available Asset located in: Lake Worth, TX Topcon GR-5 RTK	
8248	2024 Machpro MP-MS100 Sofa (Unused) S/N: SLP2707080861 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Topcon GR-5 RTK GPS GNSS Rover, SN#800-10190 Topcon FC-2600 Data Collector, Magnet Field, SN#556-06832 Usage: Not Available Asset located in: Lake Worth, TX	
8251	Quantity of Fire Extinguisher S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	8259	Quantity of Laser Equipment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AN	(Unused)
8252	Quantity of (15) Assorted Sized Fire Extinguisher S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
8253	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK 2024 Topcon RL-H5B Rotary Laser Level	8261	2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available	
0200	(Unused) S/N: 1B019363 C/W: Receiver Usage: Not Available Asset located in: Lake Worth, TX	8262	Asset located in: Lake Worth, TX 2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8263	2024 Suihe A200 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8270	Quantity of (3) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 28 In x 50 In Metal Table
8264	2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available	8272	S/N: Not Available C/W: Vise Usage: Not Available Asset located in: Lake Worth, TX Lifting Strap, Sockets
8265	Asset located in: Lake Worth, TX 2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8272	S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
8266	Quantity of Floor Jacks & Parts S/N: Not Available C/W: (4) Floor Jacks, Receiver Hitch, Scissor		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK
	Jack, Lights, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Quantity of Electric Grease Guns S/N: Not Available C/W: Tools Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST
8268	Quantity of (4) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8274	Quantity of Tools S/N: Not Available C/W: 1 in Socket Set & Misc. Tools Usage: 5 Hr
8269	Quantity of (4) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8275	Quantity of Shovels, Post Hole Diggers. S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
8276	Quantity of (16) 2024 Agriquip GLWH16 Auto Darkening Welding Helmets (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8286	2008 APT M160 60 lb Air Hammer S/N: 303907 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	8287	2007 APT 30 lb Air Hammer S/N: 502390 C/W: EQUIPMENT-FROM-SUNSTATE-	
8278	48" Frontier Job Box W/ 25 PC Makita Power Tool Set S/N: Not Available Usage: Not Available		EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	8288	2008 APT M654 Chipping Hammer S/N: 52139	
8279	Wokin 158 PC Standard & Metric Tool Set W/ 42" Job Site Box S/N: Not Available Usage: Not Available		C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
8280	Asset located in: Lake Worth, TX Wokin/Valley 8 PC Hydraulic Jack & Jack Stand Kit W/ 42" Job Site Box S/N: Not Available	8289 8290	Quantity of (5) 2024 Landhonor LDH-FPR36 36 in Fire Pit Ring S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in : Lake Worth, TX		2024 Landhonor LHR-AIW1 Pneumatic 1 in	
8281	2008 Sokkia C22 Builders Level W/Tripod S/N: 004062 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT	8290	Impact Wrench (Unuse S/N: Not Available Usage: Not Available	Impact Wrench (Unused) S/N: Not Available
	Usage: Not Available Asset located in: Lake Worth, TX	8294	Quantity of (3) Battery Charger S/N: Not Available Usage: Not Available	
8282	Wood Tuff Tow 48" Job Site Box W/ 7 PC Cub Cadet Tool Kit		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: HT24E- Hedge Trimmer - CS160E- Cordless Chainsaw - LB600E- Leaf Blower - ST15E- String Trimmer - Battery - Charger Usage: Not Available Asset located in: Lake Worth, TX	8295	GNB GTC12-600T1 Battery Charger S/N: Not Available C/W: Skid Mounted Basket Usage: Not Available Asset located in: Lake Worth, TX	
8283	2013 APT M133 Rivet Buster S/N: 1210195 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8296	Quantity of (2) Battery Charger S/N: Not Available C/W: Die Hard DH0168, DSR Pro Series DSR121; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
8284	2011 APT M133 Rivet Buster S/N: 1010004M133 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8297	Quantity of (4) Midtronics GR8 Commercial Battery Charger S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
8285	2012 APT M190 1-1/8"X6" 90 lb Air Hammer S/N: 312531M190BV C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details	
8298	2024 Suihe WW 20000 lb Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8306	Quantity of Bottle Cart & Torches S/N: Not Available C/W: Gauges; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8307	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
8299	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	8308	THE ACTUAL PRODUCT Usage: Not Available Asset located in : Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
8300	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
8301	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available	8310	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		8310 Quantity of (5) 2024 Suihe BC-9200 920 Ratchet Binders & (10) 20 ft Chains (Unit S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN A	Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8302	2024 Landhonor LHR-EW20000 20000 lb Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8303	Wood WW15000V12 15000 lb Winch		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: 4.5hp, Remote Control Usage: Not Available Asset located in : Lake Worth, TX	8311	Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available	
8305	Quantity of (8) 3 in OD Fire Water Hose S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
8312	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8318	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
8313	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8319	Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
8314	Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-RC5400 5400 Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available Asset located in: Lake Worth, TX		Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRO IMAGES SHOWN ARE FOR ILLUSTRAT PURPOSES ONLY AND MAY NOT BE A EXACT REPRESENTATION OF THE ACT PRODUCT	S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8315	Quantity of 2024 Landhonor LHR-RC5400 5400		Usage: Not Available Asset located in: Lake Worth, TX	
	Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available Asset located in: Lake Worth, TX	8321	2024 Landhonor LHR-LB8850 Leaf Blower (Unused) S/N: Not Available C/W: 1 Cylinder 3.1 kW 75.6 cc Gasoline Engine Usage: Not Available	
8316	Quantity of (48) 2024 SKLP SK003 Ratchet Straps (Unused) S/N: B31577 C/W: (32) 2 in x 27 ft, (16) 1.5 in x 27 ft Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8322	Asset located in: Lake Worth, TX Little Wonder Optimax Walk-Behind Leaf Blower S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Arcan Farm Jack S/N: Not Available Usage: Not Available Usage: Not Available Notes: Asset located in: Lake Worth, TX	
8317	Quantity of 2024 Landhonor LHR-RF24 1.5 In x 27 Ft Ratchet Straps (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8325	Quantity of (5) 2024 Powertek 20 Ton Pneumatic Bottle Jack (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		8328	Sunex Transmission Jack S/N: Not Available C/W: Under Hoist Stands, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8329	Quantity of (3) Boxes of Wokin 3 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8338	Armor Titanium Series 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For
8330	Quantity of (3) Boxes of 10 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX
8331	Semi-Trailer Landing Gear S/N: Not Available C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available Asset located in: Lake Worth, TX	8339	Armor Titanium Series 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action
8332	Semi-Trailer Landing Gear S/N: Not Available C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available		Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8340	2024 Agriquip GLGS14 14 Gun Safe (Unused) S/N: Not Available
8333	Electric Submersible Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8334	Armor Titanium Series 64 Gun Safe (Unused)	8341	2024 Raccoon RC-G1.5 Electric Bicycle
0334	S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For		(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in : Lake Worth, TX	8342	2024 Raccoon RC-G1.5 Electric Bicycle (Unused) S/N: RC2405310
8335	Armor Titanium Series 40 Gun Safe (Unused)		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX	8343	2024 Landhonor LHR-GLS34 Gasoline Tow Behind Log Splitter (Unused) S/N: Not Available C/W: Ball Hitch, Kohler 7 hp Engine Usage: Not Available Asset located in: Lake Worth, TX
8336	2024 Agriquip GLGS40 40 Gun Safe (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8344	2024 Landhonor LS-13-36D Skid Steer Log Splitter (Unused) S/N: Not Available C/W: Skid Steer Carpet Pole, One Crate Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8345	2019 Morbark Boxer X7 Tow-Behind Wood
8337	Armor Titanium Series 24 Gun Safe S/N: Not Available C/W: 24 in Wide x 56 in High x 24 in Deep, 1400 Degree Fire Rating, Digital Combination key pad, 5 live action locking bolts Usage: Not Available Asset located in: Lake Worth, TX		Chipper S/N: 4S8SZ1010KW006193 C/W: 2018 US EPA Label, CARB Compliant, Kohler ech740 2 Cylinder 747 cc Gasoline Engine, 36 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Ball Hitch Usage: 110 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8346	2024 Landhonor LHR-PWC6 Wood Chipper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	8356	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX
8347	2024 LANM LAM750 Electric Remote Control Crawler Lawn Mower (Unused) S/N: LAM750240707 C/W: 22 in Mower Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	8357	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX
8348	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Landhero LHR-HT550 Remote Control	8358	White Outdoor 17BK2ACK090 Zero-Turn Lawn Mower S/N: 1B208G90011 C/W: Hydrostatic Drive, 13x5.00x6 Front Tires, 20x10 00x8 Peor Tires, 54 in Mower
00-10	Lawn Mower (Unused) S/N: Not Available		20x10.00x8 Rear Tires, 54 in Mower Usage: 631 Hr Asset located in : Lake Worth, TX
8349	Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhero LHR-HT550 REMOTE	8359	2016 Kubota Z725KH Zero-Turn Lawn Mower S/N: 21339 C/W: Hydrostatic Drive, 13x6.5-6 Front Tires,
0049	CONTROL Lawn Mower (Unused) S/N: Not Available Usage: Not Available		24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 2,329 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8360 8362	Quantity of (3) Yard Force 22 in Walk Behind
8350	2024 Machpro MP-M500 Tracked Lawn Mower (Unused) S/N: MP20240711180 C/W: Remote Control		String Trimmer S/N: Not Available C/W: Briggs & Stratton Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (3) Yard Force 9 in Edger
8351	2024 Machpro MP-M500 Tracked Lawn Mower (Unused) S/N: MP20240711182 C/W: Remote Control		S/N: Not Available C/W: 79 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8367	2021 Polaris 500 Utility Vehicle S/N: 3NSRM2504ME534422
8353	Hustler Dash XD 34 Zero-Turn Lawn Mower S/N: 23100864 C/W: Hydrostatic Drive, 2023 US EPA Label, 11x4.00-5 Front Tires, 18x6.5/8 Rear Tires, Hustler 34 in Mower		C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 500 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8371	2018 Kubota RTVX1140WH Utility Vehicle S/N: A5KD2GDBTJG027894
8354	2014 Kubota GR2100 Lawn Mower S/N: 12438 Usage: Not Available		C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,192 Hr Asset located in : Lake Worth, TX
8355	Asset located in: Lake Worth, TX 2018 Kubota Z725KH Zero-Turn Lawn Mower S/N: 23133 C/W: Hydrostatic Drive, 2017 US EPA Label, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 180 Hr Asset located in: Lake Worth, TX	8381	2012 Polaris 800 EFI Crew Cab 6 Passenger Utility Vehicle S/N: 4XAWH76AXDE646836 C/W: Canopy, 6 Passenger, Manual Dump Bed, Diesel Engine, Gas Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8381A	Utility Vehicle S/N: 1B9AC2110PA284014 C/W: Canopy, 4 Passenger, Windshield, 4 Cylinder Gasoline Engine Usage: 2,637 Mi Asset located in: Lake Worth, TX	8406	2017 Taylor Dunn SS5-36 Utility Cart S/N: 205453 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 177 Hr Asset located in: Lake Worth, TX
8382	2012 Polaris Ranger XP Utility Vehicle S/N: 4XATH7EA1CE289808 C/W: Canopy, 2 Passenger, Windshield, Hitch Receiver, Manual Dump Bed Usage: 1,799 Hr Asset located in: Lake Worth, TX Bobcat UV34XL Utility Vehicle	8407	Tao Motor Boulder 4x2 ATV (Unused) S/N: L9NACFB30N1604821 C/W: 2022 US EPA Label, Tao 107 cc Gasoline Engine Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY
	S/N: B53721117 C/W: Canopy, 4 Passenger, Windshield, Manual Dump Bed, Polaris Gasoline Engine Usage: 1,521 Hr Asset located in : Lake Worth, TX	8408	Asset located in: Lake Worth, TX Tao Motor Boulder 4x2 ATV (Unused) S/N: L9NACFB34N1402404 C/W: Electric Start, 2022 US EPA Label, Tao 107 cc Gasoline Engine Usage: Not Available
8384	2021 John Deere Gator XUV 855M Utility Vehicle S/N: 1M0855MBPMM040235 C/W: Canopy, 4 Passenger, Windshield, Manual		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY Asset located in: Lake Worth, TX
	Dump Bed, 2021 US EPA Label, John Deere 3tnv70 Gasoline Engine Usage: 3,905 Hr Asset located in: Lake Worth, TX		Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0112975 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit
8396	2017 Club Car Carryall 1700 Utility Vehicle S/N: A5CUAA4FTHA840664		Usage: 9 Hr Asset located in : Lake Worth, TX
	C/W: Canopy, 4 Passenger, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,294 Hr Asset located in: Lake Worth, TX	8410	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140193 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit Usage: 12 Hr
8397	2017 Club Car Carryall 1700 Utility Vehicle		Asset located in: Lake Worth, TX
	S/N: A5CUAA4FTHA841104 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,674 Hr Asset located in: Lake Worth, TX	8411	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140519 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit Usage: 7 Hr
8403	2007 John Deere TX Turf Gator Utility Vehicle	8412	Asset located in: Lake Worth, TX 2024 HUNTER PRO GFE-4.0 Electric Golf Cart
	S/N: Not Available C/W: Open Operator Station, 2 Passenger, Hitch Receiver, Manual Dump Bed Usage: Not Available Asset located in: Lake Worth, TX	0412	(Unused) S/N: 202409051 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
8404	1998 E-Z-Go 898445 Club Car Utility Vehicle	8413	Asset located in: Lake Worth, TX 2024 HUNTER PRO GFE-4.0 Electric Golf Cart
	S/N: C98004700 C/W: Canopy, 2 Passenger, Windshield, Rear Screen, 3 Cylinder Diesel Engine, Diesel Engine Usage: 2,184 Hr	0413	S/N: 202409097 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8405	Asset located in: Lake Worth, TX 2017 Taylor Dunn Rigfoot 48V N/M Utility Cart	8414	2024 HUNTER PRO GFE-4.0 Electric Golf Cart
0403	2017 Taylor Dunn Bigfoot 48V N/M Utility Cart S/N: 205477 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 560 Hr Asset located in: Lake Worth, TX		(Unused) S/N: 202409072 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8415	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409071 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8424	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409115 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8416	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409096 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8425	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409114 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8417	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409061 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8426	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 3702020241243 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8418	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409062 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8427	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 3702020241242 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8419	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409098 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available	8428	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 37020241100 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
8420	Asset located in: Lake Worth, TX 2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409100 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8429	Asset located in: Lake Worth, TX 2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409116 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8421	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409099 C/W: 4 Passenger, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8430	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused) S/N: 37020241241 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8422	2024 HUNTER PRO GFX-4.0 Electric Golf Cart (Unused) S/N: 202409069 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8431	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused) S/N: 37020241240 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8423	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 37020241084 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8433	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8CPC001632 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield Usage: Not Available	8437	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8EPC001671 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8434	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001670 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8438	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8TPC001673 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8435	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)	8439	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)
	S/N: A07DE5W8HPC001636 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8EPC001606 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX	0.4.40	Asset located in: Lake Worth, TX
8436	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8KPC001613 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8440	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8VPC001633 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8441	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001605 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8445	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8PPC001593 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8442	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8LPC001604 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE	8446	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8JPC001662 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE
	CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8443	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused)	8447	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)
	S/N: A07DE5W8TPC001656 C/W: 48 Volt Battery Charger, 4 Passenger, 5 kW Engine Usage: Not Available		S/N: A07DE5W8TPC001687 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX	0.440	Asset located in: Lake Worth, TX
8444	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8HPC001653 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8448	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8CPC001646 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8449	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8JPC001600 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine	8453	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8VPC001602 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine
	Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
-	Asset located in: Lake Worth, TX	-	Asset located in: Lake Worth, TX
8450	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8JPC001676 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN	8454	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8APC001679 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN
	WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
8451	Asset located in: Lake Worth, TX 2023 Kandi KS4PSLR-W Electric Golf Cart	8455	Asset located in: Lake Worth, TX 2023 Kandi KS4PSLR-W Electric Golf Cart
0431	(Unused)	0433	(Unused)
	S/N: A07DE5W8KPC001689 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8PPC001688 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8452	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8CPC001677 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8456	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8PPC001691 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8457	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8TPC001690 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED	8463	45 ft High Cube Storage Container S/N: HDHM94691473 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8464	2024 40 ft High Cube Multi-Door Storage Container S/N: CICU6930839 C/W: One-Way
8458	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: A07DE5W8VPC001678 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING	8465	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0174629 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0174613
8459	Electric Golf Cart S/N: JW9-200800 C/W: Battery Charger, 2 Passenger, Canopy, Windshield, Utility Body Usage: Not Available Asset located in: Lake Worth, TX		C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8460	2024 RCcar Electric 3 Person Scooter S/N: SLP2413080202 Usage: Not Available Asset located in: Lake Worth, TX	8467	Container S/N: LYPU0173793
8461	Quantity of (4) Synergy DP209 285/75R24.5 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX		C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8462	53 ft High Cube Storage Container S/N: GTJU968067 Usage: Not Available Asset located in: Lake Worth, TX	8468	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU0101019 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8469	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU0101003 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8478	2024 40 ft Multi-Door Storage Container S/N: LYPU0173772 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8470	2024 40 ft Multi-Door Storage Container S/N: XHCU5647588 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8479 8480 8481 8482 8483	2024 40 ft Multi-Door Storage Container S/N: LYPU0173807 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8471	2024 40 ft High Cube Multi-Door Storage Container		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: JPCU0101024 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2024 40 ft Multi-Door Storage Container S/N: XHCU5647593 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8472	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0026300 Usage: Not Available Asset located in: Lake Worth, TX		2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0173788 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
8473	2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0026260 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage
8474	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0025562 Usage: Not Available		Container S/N: MMPU1045114 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8475	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212025 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX		2024 40 ft Multi-Door Storage Container S/N: LYGU0185801 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8476	2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212046 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8484	2024 40 ft High Cube Storage Container S/N: DFCU1640658 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8477	40 ft High Cube Multi-Door Storage Container S/N: HHXU3309737 Usage: Not Available Asset located in: Lake Worth, TX	8485	2024 40 ft High Cube Storage Container S/N: DFCU1640663 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8486	2024 40 ft High Cube Multi-Door Storage Container S/N: LYGU4159586 C/W: One-Way	8497	20 ft Standard Multi-Door Storage Container S/N: SPRU2808250 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8498	20 ft Standard Multi-Door Storage Container
8487	2024 40 ft High Cube Multi-Door Storage Container		S/N: SPRU2807871 Usage: Not Available Asset located in : Humble, TX
	S/N: LYGU4159436 C/W: One-Way Usage: Not Available Asset located in : Lake Worth, TX	8499	20 ft Standard Multi-Door Storage Container S/N: SPRU2808266 Usage: Not Available Asset located in: Humble, TX
8488	2024 40 ft High Cube Multi-Door Storage Container S/N: ZXJU0152117 C/W: One-Way Usage: Not Available	8500	2024 SHANG 20 ft One-Way Storage Container S/N: MCCU1088835 Usage: Not Available Asset located in: Lake Worth, TX
8489	Asset located in: Lake Worth, TX 2024 40 ft High Cube Multi-Door Storage Container S/N: ZXJU0151928	8501	2024 20 ft Storage Container S/N: HYJU1077876 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: One-Way Usage: Not Available Asset located in : Lake Worth, TX	8502	2024 20 ft Storage Container S/N: VSLU3245246 Usage: Not Available
8490	2024 40 ft High Cube Storage Container S/N: DFCU1640679 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8503	Asset located in: Lake Worth, TX 2024 20 ft Standard Storage Container S/N: MCCU1088917 Usage: Not Available
8491	2024 40 ft High Cube Storage Container S/N: SPRU9037160 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8504	Asset located in: Lake Worth, TX 2024 20 ft Standard Double-Ended Storage Container S/N: SPRU2611786 Usage: Not Available
8492	20 ft Standard Open-Sided Storage Container S/N: SPRU2813703 Usage: Not Available Asset located in: Lake Worth, TX	8505	Asset located in: Lake Worth, TX 20 ft Standard Storage Container S/N: SPRU3086580 Usage: Not Available Asset located in: Lake Worth, TX
8493	20 ft Standard Open-Sided Storage Container S/N: SPRU2813880 Usage: Not Available Asset located in: Lake Worth, TX	8506	20 ft Standard Storage Container S/N: SPRU3086189 Usage: Not Available Asset located in: Lake Worth, TX
8494	2024 20 ft Multi-Door Storage Container S/N: XHCU2623751 Usage: Not Available Asset located in: Lake Worth, TX	8507	2024 20 ft Standard Storage Container S/N: SPRI3098791 Usage: Not Available Asset located in: Lake Worth, TX
8495	2024 20 ft Multi-Door Storage Container S/N: XHCU2626766 Usage: Not Available Asset located in: Lake Worth, TX	8508	20 ft Standard Multi-Door Storage Container S/N: SPRU280883 Usage: Not Available
8496	20 ft Standard Multi-Door Storage Container S/N: SPRU2807634 Usage: Not Available Asset located in: Humble, TX	8509	Asset located in: Humble, TX 2024 20 ft Standard Storage Container S/N: SPRU3078970 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8510	20 ft Standard Multi-Door Storage Container S/N: SPRU2812287 Usage: Not Available Asset located in: Humble, TX	8522	2024 12 ft Storage Container S/N: GMPU9027419 C/W: Man Door, Window Usage: Not Available	
8511	2024 20 ft Standard Double-Ended Storage Container S/N: SPRU2611575 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
8512	20 ft Standard Multi-Door Storage Container S/N: SPRU2810812 Usage: Not Available Asset located in: Humble, TX	8523	2024 12 ft Storage Container S/N: GMPU9027430 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
8513	20 ft Standard Multi-Door Storage Container S/N: SPRU2810833 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
8514	Asset located in: Humble, TX 20 ft Standard Storage Container S/N: SPRU3063223 Usage: Not Available Asset located in: Lake Worth, TX	8524	2024 9 ft Storage Container S/N: GMPU9002935 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
8515	20 ft Standard Storage Container S/N: SPRU3064493 Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
8516	20 ft Standard Storage Container S/N: APZU3578440 Usage: Not Available Asset located in: Lake Worth, TX	8525 	2024 9 ft Storage Container S/N: GMPU9026027 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
8517	20 ft Standard Storage Container S/N: ECMU1513031 Usage: Not Available		MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8518	Asset located in: Lake Worth, TX 2006 20 ft Storage Container S/N: HDMU2493989 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2024 9 ft Storage Container S/N: GMPU9026285 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8519	20 ft Standard Storage Container S/N: AXIU2245734 C/W: Man Door, AC Unit Usage: Not Available Asset located in: Lake Worth, TX	8527	Asset located in: Lake Worth, T 8527 2024 8 ft Storage Container S/N: GMPU9027893 C/W: Man Door, Window	S/N: GMPU9027893 C/W: Man Door, Window
8520	20 ft Storage Container S/N: TCKU2807327 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8521	20 ft Standard Storage Container S/N: CBHU3069110 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8528	2024 8 ft Storage Container S/N: GMPU9026520 C/W: Man Door, Window Usage: Not Available Notes: THE PROTION BURDOOFS ONLY AND	8535	40 ft High Cube Storage Container S/N: NYKU7937152 C/W: 2007 Carrier Transicold Reefer Unit Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8536	Quantity of (6) 2022 Box Gang 22 ft 30 YD Roll- Off Container S/N: Not Available
8529	2022 Suihe Storage Container S/N: LYPU00109 Usage: Not Available Notes: .		C/W: 22 ft Long x 8 ft Wide x 5 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8530	Asset located in: Lake Worth, TX 7 ft Storage Container S/N: LYP710660 C/W: Window Usage: Not Available Asset located in: Lake Worth, TX	8537	Quantity of (4) 22 ft 30 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 5 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
8531	2024 7 ft Storage Container S/N: GMPU9027851 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8538	Asset located in: Lake Worth, TX Quantity of (2) 2022 Box Gang 22 ft 40 YD Roll- Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 6 ft 9 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
8532	2004 40 ft Storage Container S/N: 749036 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Huntsville, TX	8539	Quantity of (2) 22 ft 20 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 4 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8533	3 2002 40 ft Storage Container S/N: KKFU72268889 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8540	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 5 in Wide x 4 ft 11 in High Usage: Not Available Asset located in: Lake Worth, TX
		8541	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 4 in Wide x 5 ft 8 in High Usage: Not Available Asset located in: Lake Worth, TX
8534	Asset located in: Huntsville, TX 2002 Storage Container S/N: XAH318284 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Huntsville, TX	8542	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 6 in Wide x 5 ft 8 in High Usage: Not Available Asset located in: Lake Worth, TX
		8543	18 ft Roll-Off Container (Unused) S/N: C202461 C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8544	18 ft Roll-Off Container (Unused) S/N: C202462 C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available Asset located in: Lake Worth, TX	8552	2019 Mercedes-Benz Sprinter Van Passenger Van S/N: WD3PF0CD3KT003689 C/W: 3.0 L Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View
8545 8546	17 ft Roll-Off Container (Unused) S/N: Not Available C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available Asset located in: Lake Worth, TX		Camera, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 167,464 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	17 ft Roll-Off Container (Unused) S/N: C202462 C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2022 Chrysler Voyager Minivan S/N: 2C4RC1CG3NR103312 Usage: Not Available Asset located in: Lake Worth, TX
8547	Quantity of (2) Waste Container S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8554	2011 Dodge Caravan SE Minivan S/N: 2D4RN5DG0BR682712 C/W: V6 3.6 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks
8548	1956 Chevrolet Bel Air Classic Car S/N: VC56S103217 C/W: V8 4.3 L Gasoline Engine, Automatic Transmission, Air Conditioner Usage: 9,673 Mi		Usage: 169,386 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
	Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8555 8556 8557	2021 Nissan Sentra Automobile S/N: 3N1AB8BV5MY267560 C/W: 4 cyl 2.0 L Gasoline Engine, 2021 US EP
8549	1976 Chevrolet Corvette Stingray Classic Car S/N: 1Z37L6S414551 C/W: V8 Gasoline Engine, Automatic Transmission, Power Windows Usage: 45,448 Mi		Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 54,098 Mi Asset located in : Midland, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		2019 Ford Fusion Automobile S/N: 3FA6P0HD8KR223201 C/W: 4 cyl 1.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 41,980 Mi
8550	1976 Ford 4x2 Pickup S/N: F10GLB78702 C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb GVWR, 265/70R17		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Tires, 8 ft Bed Usage: 20,841 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		2019 Kia Optima Automobile S/N: 5XXGT4L3XKG357335 Usage: Not Available Asset located in: Lake Worth, TX
8551	Asset located in: Lake Worth, TX 2015 Ford E350 4x2 14-Seat Passenger Van S/N: 1FDEE3FL1FDA16098 C/W: Air Conditioner, Automatic Transmission, Wheelchair Ramp, Wheelchair Lift, V8 5.4 L Gasoline Engine, 2014 US EPA Label, 225 /75R16, Spring Suspension, 158 in Wheelbase Usage: 103,717 Mi Notes: . Asset located in: Lake Worth, TX	8558	2018 Chevrolet Malibu Automobile S/N: 1G1ZF5SU0JF291884 C/W: 4 cyl 1.8 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 50,772 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8558A 8559	2018 Ford Fusion Automobile S/N: 3FA6P0HD1JR180576 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 83,930 Mi Asset located in: Lake Worth, TX 2017 Nissan Altima Automobile S/N: 1N4AL3AP5HN317978	8564	2014 Toyota Camry Automobile S/N: 4T4BF1FK5ER408856 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 138,538 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: 67,245 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX		2013 Nissan Sentra RS Automobile S/N: 3N1AB7AP4DL790448 C/W: 4 cyl 1.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, sunroof Usage: 127,946 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8560	2016 Dodge Challenger Automobile S/N: 2C3CDZAG7GH256566 C/W: V6 3.6 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows Usage: 55,445 Mi		TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A FLOODED BRAND ON THE TITLE Asset located in: Humble, TX		2013 Mini Cooper Automobile S/N: WMWSS5C53DWN49392 C/W: 4 cyl 1.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 137,997 Mi
8561	2016 Kia Optima Automobile		Asset located in: Lake Worth, TX
	S/N: 5XXGT4L38GG043240 C/W: 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 176,089 Mi Asset located in: Lake Worth, TX	8566A	2012 Subaru Outback AWD Automobile S/N: 4S4BRBLC3C3303630 C/W: 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 209,226 Mi
8562	2015 Nissan Juke Automobile		Asset located in: Lake Worth, TX
	S/N: JN8AF5MR0FT505833 C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 147,550 Mi	8567	2011 Mercedes-Benz E350 Automobile S/N: WDDGF5GB0BR142256 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	8568	2011 Toyota Camry Automobile S/N: 4T4BF3EK3BR115028 C/W: 4 cyl 2.4 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,
8563	2015 Chevrolet Impala Automobile S/N: 2G11Y5SN8F9263766 C/W: 6 cyl 3.6 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 92,389 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8569	Rear View Camera Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2008 Saab 9-3 Aero Automobile S/N: YS3FH41U081156520 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8570	2007 BMW 328I Automobile S/N: WBAVC535X7FZ77345 C/W: 6 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 138,111 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	8575	2017 Ford Escape 2WD SUV S/N: 1FMCU0GD9HUE71445 C/W: 3 cyl 1.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 175,892 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
8571	S/N: 1C4HJWEG2DL570305 C/W: V6 3.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 57,484 Mi Notes: COMPLETE CUSTOM BUILD IN UTAH - COMES WITH BLUE OX AVENTA LX MOTORHOME/COACH CUSHION TOW BAR; ALL DOORS AND TOPS ARE REMOVEABLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY	8576	2017 Chevrolet Traverse SUV S/N: 1GNKRFKDXHJ203590 Usage: 187,606 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
		8577	2017 Chevrolet Trax 2WD SUV S/N: 3GNCJKSB6HL220642 C/W: 1.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 131,519 Mi
0.570	Asset located in: Lake Worth, TX	-	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8572	2018 Ford Expedition 4x4 SUV S/N: 1FMJU2ATXJEA25730		Asset located in: Humble, TX
	C/W: V6 3.5 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 130,626 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8578	2017 Chevrolet Tahoe 4WD SUV S/N: 1GNSKFEC1HR217144 C/W: V8 5.3 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera Usage: 152,407 Mi Asset located in: Lake Worth, TX
8573	2018 Nissan Pathfinder SV 2WD SUV S/N: 5N1DR2MN0JC605382 C/W: V6 3.5 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear View Camera Usage: 134,053 Mi Asset located in: Lake Worth, TX 2017 Ford Escape S 2WD SUV	8579	2016 Chevrolet Tahoe 4WD SUV S/N: 1GNSKFEC8GR440859 C/W: V8 5.3 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 145,373 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	S/N: 1FMCU0F70HUB26560 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 134,079 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	8580	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC5GR437584 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 155,738 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8581 8582	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC6GR252511 C/W: V8 5.3 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Towing Hitch Usage: 202,310 Mi Asset located in: Lake Worth, TX 2016 Nissan Rogue 2WD SUV	8586	2015 Infiniti QX60 2WD SUV S/N: 5N1AL0MN6FC525522 C/W: V6 3.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 132,145 Mi Notes: TEXAS BUYERS MUST STOP IN OFFIC TO SIGN REQUIRED DOCUMENTS TO
0302	S/N: JN8AT2MT0GW019414 C/W: 4 cyl 2.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 143,099 Mi		PROCESS TITLE; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX 2015 Land Rover Range Rover 4WD SUV
8583	Asset located in: Lake Worth, TX 2016 Nissan Rogue SV SUV S/N: KNMAT2MT6GP624673 C/W: 4 cyl 2.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 159,117 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED	8587	S/N: SALVP2BG7FH957087 C/W: 4 cyl Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 144,024 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
8584	DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX 2016 Dodge Journey SUV	8588	2015 Dodge Durango SUV S/N: 1C4RDHDG1FC702143 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 3C4PDCAB6GT219191 C/W: 4 cyl 2.4 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 3rd Row Usage: 88,015 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Lake Worth, TX	8589	2015 Chevrolet Tahoe LS 2WD SUV S/N: 1GNSCAKC2FR521634 C/W: V8 5.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: 144,233 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8585	2016 Kia Soul Automobile S/N: KNDJP3A52G7276905 C/W: 4 cyl 2.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 134,403 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX	8590	Asset located in: Lake Worth, TX 2014 Chevrolet Tahoe 2WD SUV S/N: 1GNLC2E03ER162966 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 197,207 Mi Asset located in: Lake Worth, TX
		8591	2014 Audi Q7 2WD SUV (Inoperable) S/N: WA1LGAFE6ED011693 C/W: V6 3.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8592 8593	2012 Ford Expedition 2WD SUV S/N: 1FMJK1K58CEF12802 C/W: V8 5.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 131,092 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; NTHIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Lake Worth, TX 2011 Jeep Grand Cherokee 2WD SUV	8599	2006 Chevrolet Suburban LT 4WD SUV S/N: 1GNFK16Z86J170794 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Brush Guard and Rear Bumper., Towing Hitch Usage: 193,404 Mi Asset located in: Midland, TX 2006 Chevrolet Tahoe Z71 4WD SUV S/N: 1GNEK13Z26R125089 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air
	S/N: 1J4RS4GGXBC513599 C/W: V6 3.6 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 168,573 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Conditioner, Power Windows, Power Locks, 3rd Row Usage: 229,606 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
8594	2009 Chevrolet Suburban LT SUV S/N: 1GNFC26J89R299573 C/W: 6 cyl 5.3 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Towing Hitch Usage: 301,880 Mi Asset located in: Lake Worth, TX	8601	2003 Lincoln Aviator 2WD SUV S/N: 5LMEU68H33ZJ43427 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 218,683 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8595	2008 Land Rover LR2 2WD SUV S/N: SALFP24N68H043304		Asset located in: Lake Worth, TX
 8596	C/W: 6 cyl 3.2 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: Not Available Asset located in: Lake Worth, TX 2007 Cadillac Escalade SUV S/N: 1GYEC63867R384531 C/W: 6.2 L Gasoline Engine, Automatic	8602	2019 Chevrolet Silverado 3500HD 4x4 Crew Cab Pickup S/N: 1GC4KVCG9KF138086 C/W: V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11000 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 79,152 Mi Asset located in: Lake Worth, TX
	Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row, Towing Hitch Usage: 137,706 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2019 Chevrolet 3500HD 4x4 Crew Cab Pickup S/N: 1GC4KVCG2KF227899 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 11000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available Asset located in: Lake Worth, TX
8597	2007 Jeep Grand Cherokee 4WD SUV S/N: 1J8HR78327C629860 Usage: Not Available Asset located in: Lake Worth, TX	8604	2014 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KZCGXEF154345
8598	2006 BMW X5 4WD SUV S/N: 5UXFA13596LY40272 C/W: V6 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 189,977 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX		C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 245/75R17 Front Tire 235/80R17 Rear Tires, Spring Suspension, 17 in Wheelbase, 9 ft 4 in x 92 in Bed Usage: 244,091 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8605	2018 Ford F-350 XL 4x4 Crew Cab Pickup S/N: 1FT8W3BT1JEC94927 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11500 lb GVWR, 275/65R18 Tires, 8 ft Bed Usage: 44,439 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8612	2013 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3CT8DEB22137 C/W: 6.7 L Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Dual Rear Wheel, Spray-On Bed Liner, 14000.0 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 386,746 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8606	2018 Ford F-350 4x4 Crew Cab Pickup S/N: 1FD8W3H62JEB96227 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	8613	2009 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FTWW32Y29EA83928 C/W: 6.8 L V10 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 12600.0 lb GVWR, 265/70R17 Tires, 8 ft
8607	2018 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT2JEC44330 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US		Bed Usage: 57,245 Mi Asset located in : Lake Worth, TX
	EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, Drop-In Bed Liner, 11500 lb GVWR, 275/70R16 Tires, 8 ft Bed Usage: 186,195 Mi Asset located in : Humble, TX	8614	2009 Chevrolet Silverado 3500HD 4x2 Crew Cab Pickup S/N: 1GCJC83619F178424 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Dual Rear Wheel, Spray-On Bed Liner, 11400 lb
8608	2016 Ford F-350 4x4 Crew Cab Pickup S/N: 1FD8W3HT1GED26318 Usage: Not Available Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8609	2011 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT0BEC51343 C/W: 6.7 L V8 Diesel Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Drop-In Bed Liner, 11200 lb GVWR, 35x12.50R22 Tires, 8 ft Bed Usage: 106,357 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL	8615	Asset located in: Lake Worth, TX 2024 GMC Sierra 3500HD 4x4 Pickup S/N: 1GT39SE7XRF130995 C/W: 6.6 L V8 Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 14000 lb GVWR, 235/80R17 Tires, 8 ft Bed Usage: 43,278 Mi Asset located in: Lake Worth, TX
8610	MILEAGE Asset located in: Lake Worth, TX 2003 GMC Sierra 3500HD 4x4 Crew Cab Pickup S/N: 1GTJK33183F161783 Usage: Not Available		S/N: 1GD311CG4FZ538 C/W: V8 6.0 L Gasoline E Label, Automatic Transn Axle, 9750 lb Rears, 132
8611	Asset located in: Lake Worth, TX 1999 Ford F-350 4x4 Crew Cab Pickup S/N: 1FTSW31F2XEA09050 C/W: Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, 9900 lb GVWR, 295/60R20 Tires, 8 ft Bed Usage: 263,566 Mi Asset located in: Humble, TX	8617	Usage: 97,811 Mi Asset located in: Lake Worth, TX 2011 Ford F-350 XL 4x2 Pickup S/N: 1FTBF3A63BEC53993 C/W: 6.2 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 127,569 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8618	2023 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5DL0PG517224 C/W: 6.7 L V8 Diesel Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 10000.0 lb GVWR, 37X12.50R20 Tires, 6 ft 4 in Bed Usage: 12,741 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8623	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CJ3JG404410 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 96,524 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8619	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ7MG630043 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 65,623 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8623A	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJOJG327360 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Fuel Tank /w Pump, WeatherGuard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 122,776 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8620	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ8MG631265 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 122,390 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8624	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ6JG354370 C/W: 6.4 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 167,897 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8621	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ2MG631262 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 275/70R18 Tires, 8 ft 1 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 176,662 Mi Asset located in: Lake Worth, TX 2021 Ram 2500 4x4 Crew Cab Pickup	- 8625 -	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL8JG274920 C/W: 6.7 L Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/65R18 Tires, 6 ft 4 in Bed Usage: 197,428 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	S/N: 3C6UR5HJ5MG631241 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; EQUIPMENT FROM A PRIMORIS SERVICES CORP COMPANY Asset located in: Lake Worth, TX	8626	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL3JG148321 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 2 in Bed Usage: 159,765 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8627	2017 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL0HG589107 C/W: 6.7 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 6 ft 4 in Bed Usage: 196,427 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8632	2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2B68KED41291 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 139,607 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8628	2017 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL9HG570121		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: 6.7 L 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 35X12.50R20 Tires, 6 ft 2 in Bed Usage: 133,929 Mi Asset located in: Lake Worth, TX	8633	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63KEF04896 C/W: 6.2 L V8 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265
8629	2021 Ford F-250 King Ranch 4x4 Crew Cab Pickup S/N: 1FT7W2BT9MEC11318 C/W: 6.7 L V8 Diesel Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power		/70R17 Tires, 6 ft 6 in Bed Usage: 142,484 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 10000 lb GVWR, 275 /65R20 Tires, 7 ft Bed Usage: 16,533 Mi Asset located in: Lake Worth, TX		2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B6XKEF04796 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Tool Box, 10000
8630	2020 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63LEE12818 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, PROTECH Tool Box, Spray-On Bed Liner, 10000		Ib GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 176,645 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Ib GVWR, 265/70R17 Tires, 8 ft 2 in Bed Usage: 140,719 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2BT1KEE55378 C/W: 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Sunroof, Better Built 100 gal Fuel Tank /w Pump, Drop-In Bed
8631	2020 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B66LEE12831 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack,		Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 8 in Bed Usage: 145,565 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX
	Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 153,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8636	2016 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2BT2GEA52971 C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 7 ft Bed Usage: 121,086 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details		
8637	2013 Ford F-250 Lariat 4x4 Crew Cab Pickup S/N: 1FT7W2BT3DEA48102 C/W: 6.7 L V8 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 35x12.5R20 Tires, 6 ft 10 in Bed Usage: 226,784 Mi Asset located in: Lake Worth, TX 2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19ME73MF197398	8642	8642	8642	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE73MF131055 C/W: 6.6 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 112,785 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows,		Asset located in: Lake Worth, TX		
	Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 104,683 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8643	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223689 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 115,084 Mi		
8639	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE75MF221517 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 119,305 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		
			Asset located in: Lake Worth, TX		
		8644	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF222266 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,468 Mi		
8640	Asset located in: Lake Worth, TX 2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19ME74MF197121 C/W: 6.6 L V8 Gasoline Engine, Automatic		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		
	Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 106,361 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8645	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223837 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Rawson Koenig Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		
8641	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE72MF223676 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows,		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		
	RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 109,870 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8646	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE79MF223755 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 131,224 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8647	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF135301 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 105,910 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8652	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEGXKF172537 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 121,433 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8648	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup	8653	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup
	S/N: 1GT12NEG8KF128147 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 103,405 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 1GT12NEG5KF273565 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 245 /75R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 121,235 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8649	2019 GMC Sierra 2500 4x4 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1GT12NEG5KF172137 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 117,114 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8654	2018 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12REG3JF174233 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 128,754 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8650	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG9KF243775 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 9900 lb GVWR, 265 /70R17 Tires, 8 ft Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 121,440 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8655	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12REG6JF173030 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 156,754 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE
	PROCESS TITLE		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8656	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup
8651	2019 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12NEG7KF143089 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, Tool Box, 265 /70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 130,846 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 1GT12REG5JF173486 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 158,292 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8657	2016 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12RE87GF259741 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 169,025 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8662	2017 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KUEG5HF192312 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 128,022 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
8658	2014 GMC Sierra 2500HD 4x4 Crew Cab Pickup		PROCESS TITLE Asset located in: Lake Worth, TX
	S/N: 1GT12ZCG9EF123876 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 9900 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 162,483 Mi Asset located in: Lake Worth, TX	8663	Crew Cab Pickup S/N: 1GC1KVEG8HF198725 C/W: 6.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 6 ft Bed, Wireless Charging Usage: 149,617 Mi
8659	2019 Chevrolet Silverado 2500HD LT 4x4 Crew Cab Pickup S/N: 1GC1KSEY0KF118493 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fuel Tank, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		
			Asset located in: Lake Worth, TX
		8664	2012 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KVCG5CF145928 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 322,629 Mi
8660	2019 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KSEG2KF213547 C/W: V8 Gasoline Engine, Automatic		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
		8665	2012 Dodge Ram 2500 4x4 Crew Cab Pickup
	Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 245 /75R17 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 138,145 Mi Asset located in: Lake Worth, TX		S/N: 3C6TD5JT7CG347856 C/W: 5.7 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, 8000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 218,934 Mi
8661	2019 Chevrolet 2500HD Z71 4x4 Crew Cab Pickup		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Apart Jacobs dir. Lake Worth TY
	S/N: 1GC1KTEG8KF220198	0667	Asset located in: Lake Worth, TX
	C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 9500 lb GVWR, 275/65R18 Tires, 6 ft Bed, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 144,285 Mi Asset located in: Lake Worth, TX	8667	2019 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A66KED56261 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 122,599 Mi
			Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8668	2018 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A69JEC58484 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weatherguard Tool Box, 10000 lb GVWR, 265/70R15 Tires, 8 ft Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 157,129 Mi Asset located in: Humble, TX 2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A61HEE08405	8673	2019 Ram 2500 4x2 Crew Cab Flatbed Truck S/N: 3C6UR4HJ5KG590150 C/W: V8 6.4 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 5500 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 275 /70R18, Spring Suspension, 170 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 158,739 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA	0674	<u> </u>
	Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 176,168 Mi Asset located in: Humble, TX	8674	2019 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ6KG603858 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6800.0 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 170,384 Mi
8670	2015 Ford F-250 4x2 Crew Cab Pickup S/N: 1FT7W2A64FEC22645		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA		Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 268,869 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8675	2019 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJXKG643411 Usage: 224,960 Mi
			Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	PROCESS TITLE		Asset located in: Lake Worth, TX
8671 2014 Ford F-250 XL 4x S/N: 1FT7W2A69EEB4 C/W: 6.2 L V8 Gasoline Label, Automatic Trans Conditioner, Power Wi Gate, Aluminum Truck 10000 lb GVWR, 265/7 Usage: 173,752 Hr Notes: TEXAS BUYERS TO SIGN REQUIRED DO PROCESS TITLE Asset located in: Midla 8672 2021 Ram 2500 4x2 C S/N: 3C6UR4HJ6MG6- C/W: 6.4 L V8 Gasoline Transmission, Air Cone Windows, 10000 lb GV	Asset located in: Lake Worth, TX 2014 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A69EEB42367 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear Power Lift Gate, Aluminum Truck Cap, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed	8676	2019 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ7KG631829 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 180,148 Mi Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8677	2018 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ1JG188981 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air
	Asset located in: Midland, TX 2021 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ6MG648396 C/W: 6.4 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/70R17 Tires, 8 ft Bed		Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires Usage: 204,579 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Usage: 166,144 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8678	2018 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ8JG287331 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Fuel Tank, Weather Guard Tool Box, 10000 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 175,042 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8679	2015 Chevrolet 2500HD 4x4 Crew Cab Pickup S/N: 1GC1KWE89FF640746 C/W: 6.6 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 7 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A BONDED TITLE;	8683	2018 Chevrolet Silverado 2500 HD 4x4 Dual Cab Pickup S/N: 1GC2KWEG9JZ193614 C/W: 6.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 162,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8684	2016 Chevrolet 2500HD 4x4 Extended Cab
8680	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B68LEC63951 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 166,422 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Pickup S/N: 1GC2KUEG4GZ109955 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 9500.0 lb GVWR, 8 ft Bed Usage: 355,555 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8680A	2016 Ford F-250 4x4 Extended Cab Pickup S/N: 1FT7X2BT8GEC22330 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 8 ft Bed Usage: 154,291 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8685	2015 GMC 2500 4x4 Extended Cab Pickup S/N: 1GT22XEG0FZ106115 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8686	2017 Ford F-250 XL 4x2 Extended Cab Pickup
8681	2015 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B61FEB25480 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Fuel Tank /w Pump, Tractor Supply Co Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 2 in Bed Usage: 111,775 Mi	8086	S/N: 1FT7X2A64HEF24694 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Notes: TEXAS BUYERS MUST STOP IN OFFICE		Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8687	2017 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A65HEB28242 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA
8682	2015 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B61FEC04213 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 320,450 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 238,717 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details		
8688	2016 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A69GEC19075 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 10000.0 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 199,413 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8693	8693	E S C C E C C L iii U N	2012 Chevrolet Silverado 2500HD 4x2 Extended Cab Pickup S/N: 1GC2VC83CZ320119 C/W: 6.6 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 7 in Bed Usage: 279,928 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
8689	2016 Ford F-250 XL 4x2 Extended Cab Pickup		PROCESS TITLE Asset located in: Lake Worth, TX		
	S/N: 1FT7X2A69GEB70864 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 10 in Bed Usage: 201,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8693A	2008 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FTSX20578EE54529 C/W: 5.4 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, 9200 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 331,802 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		
8690	2014 Ford F-250 4x2 Extended Cab Pickup	0.004	Asset located in: Lake Worth, TX		
	S/N: 1FT7X2A66EEB24227 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, GPI Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 195,848 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8694	2020 Ram 2500 4x4 Pickup S/N: 3C6MR5AJ9LG164012 C/W: V8 Engine, Automatic Transmission Usage: 102,553 Mi Asset located in: Lake Worth, TX		
		8695	2020 Ram 2500 4x4 Pickup S/N: 3C6MR5AJ5LG164010 C/W: V8 Engine, Automatic Transmission Usage: 107,621 Mi Asset located in: Lake Worth, TX		
8691	2014 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A6XEEA58748 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, WeatherGuard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 312,914 Mi	8696	2017 Chevrolet Silverado 2500 HD 4x4 Pickup S/N: 1GC0KUEG2HZ225955 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 99,657 Mi Asset located in: Lake Worth, TX		
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8697	2015 Ram 2500 4x2 Pickup S/N: 3C6LR4AT0FG649313 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air		
8692	2014 Ford F-250 4x2 Extended Cab Pickup S/N: 1FT7X2A67EEB17769 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 191,870 Mi		Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 9000 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 106,565 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8697A	2015 Ford F-250 4x2 Pickup S/N: 1FTBF2ATXFEA40769 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8698	S/N: 1FTBF2A60DEB82104 C/W: 6.2 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Truck Cap, 10000 lb GVWR, 245/70R17 Tires	8704	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED6MG240892 Usage: Not Available Asset located in: Lake Worth, TX
		8704A	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED2MG205545 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear
8699	2012 Chevrolet Silverado 2500 HD LS 4x2 Pickup S/N: 1GC0CVCG6CF138379 C/W: 6.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 8 ft 3 in Bed Usage: 223,391 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8704B	Window, 7100 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 109,324 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2021 GMC Sierra 1500 Crew Cab 4x4 Pickup S/N: 3GTU9BED7MG203323 C/W: EQUIPMENT-FROM-WATKINS-
8700	PROCESS TITLE Asset located in: Lake Worth, TX 2022 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTU9DED3NZ162699		CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	Usage: Not Available Asset located in: Lake Worth, TX		PROCESS TITLE Asset located in: Lake Worth, TX
8701	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED4MG242107 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7100 lb GVWR, 275 /60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 97,407 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8705 2020 GMC Sierra 1500 4x4 Crew Cab Denal Pickup S/N: 1GTU9FEL4LZ152697 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPL Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Spray-On Bed Liner, 7106 GVWR, 5 ft 7 in Bed Usage: 98,858 Mi Notes: TEXAS BUYERS MUST STOP IN OFFI TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 8705A 2020 GMC Sierra 1500 4x4 Crew Cab Pickut S/N: 1GTP9EEL1LZ336096 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPL Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Wind Drop-In Bed Liner, 7000 Ib GVWR, 275/60R2 Tires, 5 ft 8 in Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 113,313 Mi	S/N: 1GTU9FEL4LZ152697 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Spray-On Bed Liner, 7100 II GVWR, 5 ft 7 in Bed Usage: 98,858 Mi
8702	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2021 GMC Sierra 1500 4x4 Crew Cab Pickup		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	S/N: 3GTU9DEDXMG239485 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7100 lb GVWR, 275 /60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 107,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTP9EEL1LZ336096 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Drop-In Bed Liner, 7000 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION
8703	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED3MG200127 C/W: 5.3 L V8 Gasoline Engine, Automatic		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 255/70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 117,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8706	2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED0LG267777 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8707	S/N: 3GTU2TECXEG385182 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 265/70R17 Tires, 5 ft 9 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 127,548 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8712	2019 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFJT8KN822441 Usage: Not Available Asset located in: Lake Worth, TX
		8713	2017 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7LT4HS620059 Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8714	2016 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7MT0GS416856
8708	2016 Chevrolet Silverado 1500 LT 4x4 Crew Cab Pickup S/N: 1GCUKREC4GF141714 C/W: 5.3 L V8 Gasoline Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Decked Tool Box, Drop-In Bed Liner, 7200 lb GVWR, 265 /70R17 Tires, 6 ft 6 in Bed Usage: 263,036 Mi		C/W: 5.7 L V8 Gasoline Engine, 20 Label, Automatic Transmission, A Conditioner, Power Driver's Seat, Windows, Power Sliding Rear Win Tonneau Cover, Spray-On Bed Lin GVWR, 6 ft 5 in Bed, EQUIPMENT- PRIMORIS-SERVICES-CORP-COM Usage: 88,711 Mi Notes: TEXAS BUYERS MUST STO TO SIGN REQUIRED DOCUMENTS PROCESS TITLE
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX	8715	2018 Toyota Tundra 4x4 Crew Cab Pickup S/N: 5TFDW5F19JX740667
8709	2020 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFLT1LN227445 Usage: Not Available Asset located in: Lake Worth, TX		C/W: 5.7 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 275/70R18 Tires, 5 ft 7 in Bed Usage: 260,621 Mi
8709A	2020 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFLT1LN333989 Usage: Not Available Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8710	2019 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFFT7KN714613 C/W: 5.7 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 7100.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in	8716 8717	2017 Toyota Tundra SR5 4x4 Crew Cab Pickup S/N: 5TFUW5F16HX610386 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Spray-On Bed Liner, 7100 lb GVWR, 275 /55R20 Tires, 6 ft Bed Usage: 262,750 Mi Asset located in: Lake Worth, TX
	Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 129,734 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 5TFDW5F12GX506041 C/W: 5.7 L V8 Gasoline Engine, 201 Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Po Windows, Spray-On Bed Liner, 7200
8711	2019 Ram 1500 Big Horn 4x4 Crew Cab Pickup S/N: 1C6SRFFT3KN739606 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100.0 lb GVWR, 285/65R18 Tires, 5 ft 3 in Bed Usage: 196,574 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Usage: 276,601 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8718	S/N: 5TFDW5F17GX526706 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray- On Bed Liner, 7200.0 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 323,409 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8722 8723	2020 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1E53LKD47734 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Protech Tool Box, Spray-On Bed Liner, 7000 lb GVWR, 265 /70R17 Tires, 5 ft 6 in Bed Usage: 121,047 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8719	Asset located in: Lake Worth, TX 2018 Nissan Titan Platinum Reserve 4x4 Crew Cab Pickup	_8/23	2020 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTEW1E52LKE45508 Usage: Not Available
	Cab Pickup S/N: 1N6AA1E55 IN509451		Asset located in: Lake Worth, TX
	S/N: 1N6AA1E55JN509451 C/W: 5.6 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Tool Box, Spray-On Bed Liner, 7300 lb GVWR, 275 /60R20 Tires, 5 ft 7 in Bed Usage: 2,600 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; ODOMETER DISCREPENCY - ODOMETER SHOWS 2600 TITLE SHOWS 105570	8724	2019 Ford F-150 STX 4x4 Crew Cab Pickup S/N: 1FTEW1E56KKC96325 C/W: 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed Usage: 90,968 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
		8725	2019 Ford F-150 XL 4x4 Crew Cab Pickup
8720	Asset located in: Lake Worth, TX 2021 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E55MKD34831 C/W: 5.0 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050.0 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 96,289 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		S/N: 1FTFW1E49KKC43100 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 140,907 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	PROCESS TITLE	8726	2018 Ford F-150 XL 4x4 Crew Cab Pickup
8721	Asset located in: Lake Worth, TX 2020 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1E58LKD34168 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 245/70R17 Tires, 5 ft 7 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 96,164 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		S/N: 1FTFW1EG1JKD95560 C/W: 3.5 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 245/75R17 Tires, 7 ft Bed Usage: 124,873 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
		8727	2017 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTEW1EP9HFB20551 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8728	2016 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1EF5GFA47779 C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 155,109 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8735	2011 Dodge Ram 1500 4x4 Crew Cab Pickup S/N: 1D7RV1GT9BS552169 C/W: V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6700 lb GVWR, 275/65R20 Tires, 6 ft 8 in Bed Usage: 154,689 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPENCY - ODOMETER SHOWS 154689 TITLE SHOWS 155742
8729	2014 Ford F-150 XLT 4x4 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FTFW1EF4EKF62314 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7350 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 99,175 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8736	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CP5JKD52645 C/W: 2.7 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, 6360 lb GVWR, 265 /60R18 Tires, 5 ft 8 in Bed Usage: 121,549 Mi
8730	Asset located in: Lake Worth, TX 2014 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF3EFA28438 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPANCY-UNIT SHOWS 121,549, TITLE SHOWS 139,907 Asset located in: Humble, TX
	Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7350 lb GVWR, 275/65R18 Tires, 5 ft 6 in Bed Usage: 167,074 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8737	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C56JKC10769 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 Bed, EQUIPMENT-FROM-PULICE-
8731	2013 Ford F-150 Raptor 4x4 Crew Cab Pickup S/N: 1FTFW1R66DFA62527 Usage: Not Available		CONSTRUCTION Usage: 145,418 Hr Asset located in: Humble, TX
8732	Asset located in: Lake Worth, TX 2013 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1ET9DKF21987 C/W: 3.5 L V6 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Better Built Tool Box, 7200 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 100,112 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C52JKC10770 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 146,917 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	8739	2018 Ford F-150 4x2 Crew Cab Pickup
8733	2013 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF8DKF76148 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Drop-In Bed Liner, 7350 lb GVWR, 275/65R18 Tires, 5 ft 5 in Bed Usage: 289,799 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 1FTEW1C54JKC10768 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Weatherguard Tool Box, Drop-In Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 120,300 Mi Asset located in: Humble, TX

		T	
Lot #	Details	Lot #	Details
8740 8741	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1E52JKE26129 Usage: Not Available Asset located in: Lake Worth, TX 2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1E58JFD71503	8746	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF6HKE23725 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Too Box, Spray-On Bed Liner, 6800 lb GVWR, 265
	Usage: Not Available Asset located in: Lake Worth, TX		/70R17 Tires, 5 ft 5 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 142,764 Mi
8742	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CFXHKE23730 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 86,433 Mi Asset located in: Humble, TX	8747	2017 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1CP8HKD86640 C/W: 2.7 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6260 lb GVWR, 275/55R20 Tires, 5 ft 5 in Bed Usage: 199,080 Mi
8743	2017 Ford F-150 XL 4x2 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FTEW1CF5HKC49971 C/W: 5.0 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, Spray-On Bed Liner, 6800 lb GVWR, 245/70R17 Tires, 5 ft 6 in Bed Usage: 119,231 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		2016 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTEW1CF9GKF65372 C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 6950 lb GVWR, 255/70R17 Tires, 6 ft 5 in Bed Usage: 196,241 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8744	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF0HKE23722		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA	0740	
	Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 4 ft 6 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 119,473 Mi Asset located in: Humble, TX	8749	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF4EKG33790 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 6 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 129,930 Mi Asset located in: Humble, TX
8745	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF2HKE53076 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 7 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 140,099 Mi Asset located in: Humble, TX	8750	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF3EKG33800 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 133,616 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8751	2014 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTFW1CFXEKG11583 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, BETTER BUILT Tool Box, Spray-On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 322,798 Mi	8757	2010 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFTM5F17AX001055 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 255/70R18 Tires, 8 ft Bed Usage: 244,207 Mi
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8752	2019 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFRM5F17KX141585 C/W: 4.6 L V8 Gasoline Engine, 2019 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Craftsman Tool Box, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 195,476 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8758	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTR9AEHXMZ203075 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 107,212 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8753	Asset located in: Lake Worth, TX	8759	Asset located in: Lake Worth, TX
	2019 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFRM5F18KX141630 Usage: 291,345 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8739	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTR9AEH4MZ201452 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 113,431 Mi
8754	2016 Ram 1500 SLT 4x2 Crew Cab Pickup S/N: 1C6RR6GG7GS403918 C/W: 3.6 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air		Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Conditioner, Power Driver's Seat, Power Windows, 6800 lb GVWR, 275/55R20 Tires, 6 ft 3 in Bed Usage: 67,066 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8760	2019 Chevrolet Silverado 1500 LT 4x4 Dual Cab Pickup S/N: 1GCRYDED9KZ191418 C/W: 5.3 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR,
8755	2014 Ram 1500 4x2 Crew Cab Pickup S/N: 1C6RR6KM8ES408801 C/W: 3.0 L V6 Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6800 lb		265/65R18 Tires, 6 ft 8 in Bed Usage: 148,223 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	GVWR, 265/70R17 Tires, 5 ft 10 in Bed Usage: 266,474 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC3HZ107938 C/W: 5.3 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 7200 lb
8756	2014 GMC Sierra 1500 4x2 Crew Cab Pickup S/N: 3GTP1UEC6EG110768 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7000 lb GVWR, 275/55R20 Tires, 6 ft 7 in Bed Usage: 216,631 Hr Asset located in: Lake Worth, TX		GVWR, 295/55R20 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-HERC-RENTALS Usage: 63,030 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT EQUIPMENT FROM HERC RENTALS; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8762	2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC6HZ350529 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 189,063 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8767	2015 Ram 1500 4x4 Dual Cab Pickup S/N: 1C6RR7GMXFS671274 C/W: 3.0 L V6 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6950 lb GVWR, 35x12.5R20 Tires, 6 ft 3 in Bed Usage: 137,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8763	2015 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKPEH5FZ173329 C/W: Gasoline Engine, Automatic	8768	2015 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7GT4FS643767 Usage: Not Available Asset located in: Lake Worth, TX
	Transmission, Air Conditioner, Power Windows, RKI Tool Box, Drop-In Bed Liner, 7100.0 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 91,050 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX	8769	2018 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E53JKE13763 C/W: 5.0 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 149,967 Mi
8764	2015 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKREC2FZ382091 C/W: 5.3 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 231,215 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
		8770	70 2016 Ford F-150 XLT 4x4 Extended Cab Pickup S/N: 1FTFX1EF6GFB81556 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7050 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 127,639 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8765	Asset located in: Lake Worth, TX 2018 GMC Sierra 1500 4x4 Extended Cab Pickup	8771	
	S/N: 1GTV2LEC5JZ370765 C/W: 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 7200 lb GVWR, 265/70R17 Tires, 6 ft 9 in Bed, EQUIPMENT-FROM-5J-GROUP Usage: 227,149 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		2012 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTEX1EM1CFC36807 C/W: 3.7 L V6 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 275/65R18 Tires, 6 ft 10 in Bed Usage: 84,649 Mi Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	8772	2006 Chevrolet Silverado 1500 4x4 Extended Cab Pickup
8766	2016 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7FT9GS207693 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 285/70R17 Tires, 6 ft Bed Usage: 177,486 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 1GCEK19V36Z259882 C/W: 4.8 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 6 ft 6 Bed Usage: 129,610 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8773	2004 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V84Z272706 C/W: 4.8 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6400 lb GVWR, 245/75R16 Tires, 6 ft 10 in Bed Usage: 172,966 Mi Asset located in: Lake Worth, TX	8780	2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C89HKC50152 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 5 in Bed Usage: 169,011 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8774	2021 Chevrolet Silverado 4x2 Extended Cab		Asset located in: Lake Worth, TX
	Pickup S/N: 1GCRWAEH8MZ261016 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8781	2015 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CFXFKE52008 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR,
8775	2014 Chevrolet Silverado 1500 4x2 Extended		265/70R17 Tires, 6 ft 6 in Bed Usage: 199,497 Mi
	Cab Pickup S/N: 1GCRCPEC8EZ211055 Usage: Not Available Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8776	·	_	Asset located in: Lake Worth, TX
	2019 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C43KKE83254 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 255/70R18 Tires, 6 ft 6 in Bed Usage: 139,472 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8782	2015 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1CF9FKE51996 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 219,104 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8777	2018 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C56JKF84490 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 4 in Bed Usage: 135,767 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8783	2014 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTFX1CF8EKF95610 C/W: 5.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 7 in Bed Usage: 209,297 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8778	2018 Ford F-150 XL 4x2 Extended Cab Pickup	8784	
	S/N: 1FTEX1C55JKF84478 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 172,916 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	0/04	2010 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CWXAFB90668 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray-On Bed Liner, 6700 lb GVWR, 235/75R17 Tires, 6 ft 5 in Bed Usage: 215,747 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8785	2005 Chevrolet Silverado 1500 4x4 Pickup S/N: 1GCEK14V55Z288807 C/W: 4.8 L V8 Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft 5 in Bed Usage: 99,043 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8790	2020 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1C50LKD46068 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6750 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 124,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8786	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH3FZ285656 C/W: 4.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 125,012 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2018 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1E55JKF44493 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray- On Bed Liner, 6950 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 140,414 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8787	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH5FZ270933 C/W: 4.3 L V6 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Fiberglass Truck Cap, 6700 lb GVWR, 265/70R17 Tires, 8 ft Bed, Pump, Tank, Reel Usage: 194,254 Mi Asset located in: Humble, TX	8792	2017 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1CF4HKD34876 C/W: 5.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, protech Tool Box, Spray-On Bed Liner, 6750 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 117,485 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8788	2014 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH7EZ346442 C/W: 4.3 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 114,136 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8793	Asset located in: Lake Worth, TX 2010 Ford F-150 4x2 Pickup S/N: 1FTMF1CW8AKE17930 C/W: 4.7 L V6 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6750 lb GVWR, 235/75R17 Tires, 8 ft 5 in Bed Usage: 126,592 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8789	2013 Chevrolet 1500 4x2 Pickup S/N: 1GCNCPEA5DZ356873 C/W: 4.8 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 74,650 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; ODOMETER DISCREPANCY-UNIT SHOWS 74,650, TITLE SHOWS 145,093 Asset located in: Lake Worth, TX	8794	Asset located in: Lake Worth, TX 2003 Ford F-150 4x2 Pickup S/N: 2FTRF17L83CB00193 C/W: 5.4 L V8 Gasoline Engine, 2003 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6050 lb GVWR, 235/75R16 Tires, 8 ft 4 in Bed Usage: 94,369 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 1989 GMC Sierra 2500 4x2 Pickup S/N: 1GTFC24C1KE543722 C/W: V8 Diesel Engine, 4 Speed Manual Transmission, Drop-In Bed Liner, 72000 lb GVWR, 225/75R16 Tires, 8 ft Bed, EQUIPMENT-FROM-YELLOW-CORP

Lot #	Details	Lot #	Details
8796	2022 Ford Ranger 4x2 Crew Cab Pickup S/N: 1FTER4EH5NLD35536 C/W: 2.3 L 4 Cylinder Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 3500 lb GVWR, 265/70R16 Tires, 5 ft Bed Usage: 20,876 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8801	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN719166 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 100,824 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8797	2021 Chevrolet Colorado 4x2 Crew Cab Pickup	8802	2020 Nissan Frontier 4x2 Extended Cab Pickup
0737	S/N: 1GCGSCEN1M1296032 C/W: 2.5 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 5800 lb GVWR, 255/65R17 Tires, 5 ft Bed Usage: 47,944 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	0002	S/N: 1N6ED0CE1LN721059 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 101,844 Mi Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE:	8803	2020 Nissan Frontier 4x2 Extended Cab Pickup
	Asset located in: Lake Worth, TX	8804	S/N: 1N6ED0CE1LN721210
8798	2022 Chevrolet Colorado 4x2 Extended Cab Pickup S/N: 1GCHSBEA4N1311703 C/W: Automatic Transmission, Air Conditioner, Power Windows, 255/65R17 Tires, 6 ft 2 in Bed Usage: 34,661 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 109,927 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	PROCESS TITLE		2020 Nissan Frontier 4x2 Extended Cab Pickup
8799	Asset located in: Lake Worth, TX 2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN724934 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Stainless Steel Truck Cap, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 84,482 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8804	S/N: 1N6ED0CE3LN721807 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 111,655 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE5LN721727 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 103,120 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8805	2020 Nissan Frontier 4x2 Extended Cab Pickup
8800			S/N: 1N6ED0CE9LN721892 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/75R16 Tires, 6 ft Bed Usage: 116,183 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	PROCESS TITLE	8806	2017 Nissan Frontier 4x2 Extended Cab Pickup
	Asset located in: Lake Worth, TX		S/N: 1N6BD0CT1HN724360 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft 6 in Bed Usage: 103,998 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8807	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CTXHN757261 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 118,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8813	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19JNC000011 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 13 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8808	2017 Nissan Frontier 4x2 Extended Cab Pickup	8814	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19PNC000023
	S/N: 1N6BD0CT3HN721511 C/W: 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 4700.0 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 127,844 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8815	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19ANC000014
8809	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19CNC000009 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 2 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED		C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.
	SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.		Asset located in: Lake Worth, TX
8810	Asset located in: Lake Worth, TX 2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000010 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 4 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.	8816	2022 Kandi K32S-R Utility Vehicle (Unused) S/N: A074EA19KNC000007 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 9 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8817	2022 Kandi K32S-R Utility Vehicle (Unused) S/N: A074EA19LNC000015
8811	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000024 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.		C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 15 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8818	2022 Kandi K32S-W Utility Vehicle (Unused)
8812	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19PNC000006 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 12 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX		S/N: A074EA19CNC000021 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi Notes: ***FOR OFF ROAD USE ONLY***; PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8819	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19TNC000005 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8824	2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X0ND759228 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 213663 TITLE SHOWS 213700 Asset located in: Lake Worth, TX 2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X9MD759078
8820	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19TNC000022 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch, Charger Usage: 16 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.		
8821	Asset located in: Lake Worth, TX Subaru Sambar 4x4 COE Flatbed Truck S/N: TT2096235 C/W: Subaru Clover4 4 Cylinder Gasoline Engine, 5-Speed Manual Transmission, 145R12, Spring Suspension, 74 in Wheelbase, 77 ft x 55 in Bed Usage: 98,817 Mi Notes: **This item is right hand drive** Asset located in: Humble, TX		C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000
8822	2022 Peterbilt 579 6x2 S/A Day Cab Truck		Asset located in: Lake Worth, TX
	Tractor S/N: 1XPBAK9X2ND758793 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 5233.9 Engine hrs, Engine Brake, Paccar Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 150 in Wheelbase, Air Sliding 5th Wheel Usage: 231,143 Mi	8826	2017 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X2HD428752 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel Usage: 933,275 Mi Asset located in: Lake Worth, TX
8823	Asset located in: Lake Worth, TX 2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X1ND759335 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4478 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires,	8827	2017 Peterbilt 348 S/A Day Cab Truck Tractor S/N: 1NP3A28X9HD409487 Usage: Not Available Asset located in: Lake Worth, TX
		8828	2017 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X0HD428751 Usage: Not Available Asset located in: Lake Worth, TX
	Air Trac Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 200,027 Mi Asset located in : Lake Worth, TX	8829	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339556 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 896,378 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8830	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor	8838	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor
	S/N: 1XPBA48X6GD339491 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1XPBA48X8FD286307 C/W: Cummins ISX15 6 Cylinder 15 L Petrol 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
8831	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339671 C/W: Cummins ISX15 6 Cylinder 15.0 L 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17898.4 Engine hrs, Engine Brake, Eaton Fuller UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Trac Air Ride Suspension, 159 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 888,673 Mi	8839	2016 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXGJ119241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 828,937 Mi
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8832	2016 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X6GD339488 Usage: Not Available Asset located in: Lake Worth, TX	8840	2016 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X9GJ496496 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires
8833	2016 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X6GD339555 Usage: Not Available Asset located in: Lake Worth, TX		Diesel Exhaust Fluid, 17916 Engine hrs, Engine Brake, Eaton Fuller ADV Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295
8834	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X6FD286306 Usage: Not Available Asset located in: Lake Worth, TX		/75R22.5, 4-Bag Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 912,222 Mi Asset located in: Lake Worth, TX
8835	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X5FD286278 Usage: Not Available Asset located in: Lake Worth, TX	8841	2015 Kenworth T680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXFJ403449 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
8836	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X5FD286314 Usage: Not Available Asset located in: Lake Worth, TX	Engine, 2014 US EPA Labe Exhaust Fluid, 22634 Engi Eaton Fuller Automated To Ib Front Axle, 22700 Ib Rea Drive Axles, 2.53:1 Axle Ra 295/75R22.5 Front Tires, 2 Tires, 4-Bag Air Ride Susp Wheelbase, Air Sliding 5th Tanks Usage: 1,009,300 Mi	Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22634 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 Ib Front Axle, 22700 Ib Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 Ib GVWR,
8837	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X7FD286248 Usage: Not Available Asset located in: Lake Worth, TX		295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, 4-Bag Air Ride Suspension, 168 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Lot #	Details	Lot #	Details
8842	2015 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X0FJ443782 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 990,189 Mi	8850	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXEJ402851 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Eaton Fuller FM-15E310B-LAS Automatic Transmission, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700.0 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,154,795 Mi Asset located in: Lake Worth, TX
	Notes: X2-No frame stamp vin pic Asset located in: Lake Worth, TX	8851	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor
8843	2015 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X6FJ443771 C/W: Cummins ISX 6 Cylinder 15 L Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 17203 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Airglide 4-Bag Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel		S/N: 1XKYA48X4EJ403168 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 767,305 Mi Asset located in: Lake Worth, TX
	Usage: 732,450 Mi Asset located in: Lake Worth, TX	8852	2014 Kenworth T-680 4x2 S/A Day Cab Truck
8844	2015 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYD49X7FJ466031 Usage: Not Available Asset located in: Lake Worth, TX 2015 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48XXFJ403435		Tractor S/N: 1XKYA48X9EJ403215 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19302.4 Engine hrs, Engine Brake, Eaton Fuller FM- 15E310B 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23 190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, AG200 4- Bag Air Ride Suspension, 159 in Wheelbase, Ai Sliding 5th Wheel, Dual Fuel Tanks Usage: 937,106 Mi
	Usage: Not Available Asset located in: Lake Worth, TX		
8846	2014 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48X9EJ402288 Usage: Not Available Asset located in: Lake Worth, TX	8853	Asset located in: Lake Worth, TX 2013 Kenworth T660 4x2 S/A Day Cab Truck Tractor S/N: 1XKAA48X1DJ354916 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
8847	2014 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48X7EJ402287 Usage: Not Available Asset located in: Lake Worth, TX		400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 769,223 Mi
8848	2014 Kenworth T680 S/A Day Cab Truck Tractor		Asset located in: Humble, TX
	S/N: 1XKYA48X3EJ402450 Usage: Not Available Asset located in: Lake Worth, TX	8854	2013 Kenworth T660 S/A Day Cab Truck Tractor S/N: 1XKAD48X1DJ367527 Usage: Not Available
8849	2014 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48X0EJ403264 Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8855	2013 Kenworth T660 4x2 S/A Day Cab Truck Tractor S/N: 1XKAA48X8DJ354945 C/W: Cummins ISX15 6 Cylinder 15 L 400 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 4-Bag Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	8861	2018 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGEDV5JSJH1844 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10441 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, 3.08:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 244,661 Mi
8857	2019 Mack AN42T 4x2 S/A Day Cab Truck		Asset located in: Lake Worth, TX
	Tractor S/N: 1M1AN2AY6KM001154 C/W: Mack MP7 6 Cylinder Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 154 in Wheelbase, Auto Lube Usage: 537,481 Mi Asset located in: Lake Worth, TX	Cab Truck Tractor S/N: 3AKBGDDV1HDHY5841 C/W: Detroit DD13 6 Cylinder 12.8 L Diese hp Engine, 2016 US EPA Label, Requires I Exhaust Fluid, 12543 Engine hrs, Engine E Detroit 12-Speed Automated Transmission 12000 lb Front Axle, 21000 lb Rears, Merit 23-161 Drive Axles, 2.50:1 Axle Ratio, 330	
8858	2019 Mack Anthem 4x2 S/A Day Cab Truck		5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
0030	Tractor		
	S/N: 1M1AN2AY2KM001152 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel		Usage: 553,773 Mi Asset located in : Lake Worth, TX
	Exhaust Fluid, 4523 Engine hrs, Engine Brake, Mack 12-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase Usage: 476,581 Mi Asset located in: Lake Worth, TX	8863	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV4HDHY5848 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air
8859	2017 Mack CXU612 6x2 S/A Day Cab Truck Tractor S/N: 1M1AW01Y9HM010179 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic		Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 569,326 Mi Asset located in : Lake Worth, TX
	Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Air Ride Suspension, 159 in Wheelbase Usage: 477,424 Mi	8864	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV6HDHY5849
	Asset located in: Lake Worth, TX		C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525
8860	2017 Mack CXU612 4x2 S/A Day Cab Truck Tractor S/N: 1M1AW01Y7HM010164 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14979 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 548,175 Mi Asset located in: Lake Worth, TX		hp Engine, 2016 US EPA Label, Requires Diese Exhaust Fluid, 15402 Engine hrs, Engine Brake Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-161 Drive Axles, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 620,515 Mi Asset located in: Lake Worth, TX

			rage 455 01 507
Lot #	Details	Lot #	Details
8865	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV5HDHY5843 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 588,024 Mi	8869	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0206 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19010 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 865,103 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8870	2015 Freightliner Cascadia 125 4x2 S/A Day
8866	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0385 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17775 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 920,721 Mi		Cab Truck Tractor S/N: 1FUBGDD58FLGB0017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 20941 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 984,115 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8871	2015 Freightliner Cascadia 125 4x2 S/A Day
8867	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0401 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18682 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,203 Mi		Cab Truck Tractor S/N: 1FUBGDD51FLGJ1241 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 2052 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 703,022 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8872	2015 Freightliner Cascadia 125 4x2 S/A Day
8868	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0164 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18936 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor MFS-12-143A Drive Axles, 3.42:1 Axle Ratio, 33000 kg GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 871,985 Mi	3072	Cab Truck Tractor S/N: 1FUBGDD5XFLGB0245 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19950 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,022 Mi Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Details Lot# **Details** Lot # 8873 8877 2015 Freightliner Cascadia 125 4x2 S/A Day 2015 Freightliner Cascadia 125 4x2 S/A Day **Cab Truck Tractor Cab Truck Tractor** S/N: 1FUBGDD57FLGB0459 S/N: 1FUBGDD56FLGJ1204 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17399 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20437 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 802,794 Mi Usage: 882,971 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 8874 2015 Freightliner Cascadia 125 4x2 S/A Day 8878 2015 Freightliner Cascadia 125 4x2 S/A Day **Cab Truck Tractor** Cab Truck Tractor S/N: 1FUBGDD56FLGB0324 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel S/N: 1FUBGDD55FLGB0301 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Exhaust Fluid, 18129 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 Ib GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 Transmission, 12000 lb Front Äxle, 21000 lb /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab. Usage: 818,368 Mi 10R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Asset located in: Lake Worth, TX **Dual Fuel Tanks** 8875 2015 Freightliner Cascadia 125 4x2 S/A Day Usage: 771,423 Mi **Cab Truck Tractor** Asset located in: Lake Worth, TX S/N: 1FUBGDD55FLGJ1193 8880 2015 Freightliner Cascadia 125 4x2 S/A Day C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19725 Engine hrs, Engine Brake, Cab Truck Tractor S/N: 1FUBGDD50FLGJ1327 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Exhaust Fluid, 20282 Engine hrs, Engine Brake, Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, Dual Fuel Tanks Usage: 871,783 Mi Airliner Suspension, 158 in Wheelbase, Dual **Fuel Tanks** Asset located in: Lake Worth, TX Usage: 896,379 Mi 8876 2015 Freightliner Cascadia 125 4x2 S/A Day Asset located in: Lake Worth, TX **Cab Truck Tractor** 8881 2015 Freightliner Cascadia 125 4x2 S/A Day S/N: 1FUBGDD51FLGJ1322 **Cab Truck Tractor** C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel S/N: 1FUBGDD52FLGJ1233

S/N: 1FUBGDD51FLGJ1322 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 16251 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,874 Mi

Asset located in: Lake Worth, TX

S/N: 1FUBGDD52FLGJ1233 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 21113 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks

Usage: 927,772 Mi

			rage 437 01 307
Lot #	Details	Lot #	Details
8882	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0254 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14024 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,066,619 Mi	8886	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0423 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 870,847 Mi Asset located in: Lake Worth, TX
8883	Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1297 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 847,972 Mi Asset located in: Lake Worth, TX	8887	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0200 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 840,242 Mi Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
8884	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGJ1248 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 853,850 Mi Asset located in: Lake Worth, TX	8889	Cab Truck Tractor S/N: 1FUBGDD52FLGB0420 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21049 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 971,468 Mi Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
8885	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0455 C/W: 21346 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23- 186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner II Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 978,516 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT		Cab Truck Tractor S/N: 1FUBGDD51FLGB0084 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21221 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,002,152 Mi Asset located in: Lake Worth, TX

			Page 458 01 50/
Lot #	Details	Lot #	Details
8890	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGJ1150 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor Drive Axles, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 844,869 Mi Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day	8894	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0247 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19933 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 926,620 Mi
	Cab Truck Tractor S/N: 1FUBGDD54FLGJ1217 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18209 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,386 Mi Asset located in: Lake Worth, TX	8895	Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0266 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 910,815 Mi Asset located in: Lake Worth, TX
8892	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0278 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20497 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 954,240 Mi Asset located in: Lake Worth, TX	8896	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22008 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,012,404 Mi Asset located in: Lake Worth, TX
8893	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1249 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 995,766 Mi Asset located in: Lake Worth, TX	8897	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0161 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19325 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 889,925 Mi

Lot #	Details	Lot #	Details
8898	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0351 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19389 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 867,504 Mi Asset located in: Lake Worth, TX	8902	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0173 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 842,483 Mi Asset located in: Lake Worth, TX
8899	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0283 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18643 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 985,816 Mi Asset located in: Lake Worth, TX	8903	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGJ1328 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4695 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 862,038 Mi Asset located in: Lake Worth, TX
8900	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0208 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 19799 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks Usage: 922,423 Mi Asset located in: Lake Worth, TX	8904	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0145 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19762 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,268 Mi Asset located in: Lake Worth, TX
8901	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGJ1223 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19901 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 851,964 Mi Asset located in: Lake Worth, TX	8905	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGJ1227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17987 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 859,845 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8906	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8910	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDD55FLGB0153 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,039,845 Mi Asset located in: Lake Worth, TX		S/N: 1FUBGDD56FLGB0176 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 792,126 Mi
8907	2015 Freightliner Cascadia 125 4x2 S/A Day		Asset located in: Lake Worth, TX
	Cab Truck Tractor S/N: 1FUBGDD51FLGB0120 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19024 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 874,425 Mi Asset located in: Lake Worth, TX	8911	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0347 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1735 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 940,040 Mi Asset located in: Lake Worth, TX
8908	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0339 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19629 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 766,317 Mi Asset located in: Lake Worth, TX	8912	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55ELFL7286 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR0-15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 777,001 Mi Asset located in: Lake Worth, TX
8909	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0314 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19888 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 854,701 Mi Asset located in: Lake Worth, TX	8913	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XELFL7283 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20475 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 868,356 Mi Asset located in: Lake Worth, TX

Details Lot# **Details** Lot # 8914 2014 Freightliner Cascadia 125 4x2 S/A Day 8919 2013 Freightliner Cascadia 125 4x2 S/A Day **Cab Truck Tractor Cab Truck Tractor** S/N: 1FUBGDD50ELFL7275 S/N: 1FUBGDDR6DLBX1162 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19027 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 16476 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, **Dual Fuel Tanks** Usage: 783,595 Mi **Dual Fuel Tanks** Usage: 647,254 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 8915 2014 Freightliner Cascadia 125 4x2 S/A Day 8920 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor Cab Truck Tractor S/N: 1FUBGDD58ELFL7265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel S/N: 1FUBGDDRXDLBX1102 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 Exhaust Fluid, Engine Brake, Eaton Fuller FROhp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19727 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air **Dual Fuel Tanks** Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 730,348 Mi Usage: 662,005 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 8916 2014 Freightliner Cascadia 125 4x2 S/A Day 8921 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor Cab Truck Tractor S/N: 1FUBGEBG0ELFT4306 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires S/N: 1FUBGDDR0DLBX1156 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Exhaust Fluid, 18326 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb FM-14E310B Automated Transmission, Meritor RS-23-160 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Wheel, Dual Fuel Tanks 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 552,293 Mi Asset located in: Humble, TX Usage: 422,808 Mi 8918 2013 Freightliner Cascadia 125 4x2 S/A Day Asset located in: Lake Worth, TX **Cab Truck Tractor** 8922 2013 Freightliner Cascadia 125 4x2 S/A Day S/N: 1FUBGDDRXDLBX1004 **Cab Truck Tractor** C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp

Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel

Usage: 748,352 Mi

Asset located in: Lake Worth, TX

S/N: 1FUBGDDR4DLBX0897 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20167 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks

Usage: 812,847 Mi

Lot #	Details	Lot #	Details
8923	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX1080 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 515,155 Mi Asset located in: Lake Worth, TX 2013 Freightliner Cascadia 125 4x2 S/A Day	8927	2012 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR9CLBF2891 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 19508 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 712,633 Mi
0,24	Cab Truck Tractor		Asset located in: Lake Worth, TX
	S/N: 1FUBGDDR1DLBX0906 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19497 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 724,603 Mi Asset located in: Lake Worth, TX	8928	2018 Freightliner Cascadia 113 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGBDV9JSJR3316 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, 13472 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 22700 lb Rears, 3.08:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 165 in Wheelbase,
8925	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR7DLBX1185		Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 623,326 Mi
			Asset located in: Lake Worth, TX
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21125 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 790,333 Mi Asset located in: Lake Worth, TX		2014 Freightliner M2 112 6x4 T/A Day Cab Truck Tractor S/N: 1FUJC5DV2EHFX4554 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.62:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel
8926	2013 Freightliner Cascadia 125 4x2 S/A Day		Tanks
	Cab Truck Tractor S/N: 1FUBGDDR1DLBX0985		Usage: 698,878 Mi Asset located in : Lake Worth, TX
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21973 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 802,200 Mi Asset located in: Lake Worth, TX	8930	2015 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCYCY6FDGJ1937 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8522 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Detroit DA-RS-23.0-4 Drive Axles, 5.22:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Spring Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 147,777 Mi Asset located in: Lake Worth, TX
		8931	2015 Freightliner M2 106 S/A Day Cab Truck Tractor

S/N: 3AKBCYCY2FDGJ1949 Usage: Not Available

Lot #	Details	Lot #	Details
8932 8933	2014 Freightliner M2 106 S/A Day Cab Truck Tractor S/N: 3AKBCYCY3EDFY1228 Usage: Not Available Asset located in: Lake Worth, TX 2014 Freightliner M2 106 S/A Day Cab Truck Tractor S/N: 3AKBCYCY3EDFY1164	8938	2021 Volvo VNR300 6x4 S/A Day Cab Truck Tractor S/N: 4V4WC9EG1MN286031 C/W: 7784 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, 275/80R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 286,472 Mi
	Usage: Not Available Asset located in: Lake Worth, TX	9030	Asset located in: Lake Worth, TX
8934	2014 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCYCY4EDFX5745 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9009 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 5.38:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, steel, 295/75R22.5, Spring Suspension, 155 in Wheelbase, Dual Fuel Tanks	8939 8940	2019 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W39EG8KN226146 C/W: Volvo 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, 35350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 664,493 Mi Asset located in: Lake Worth, TX
	Usage: 120,247 Mi Asset located in : Lake Worth, TX		2019 Volvo VNR300 4x2 S/A Day Cab Truck
8935	2022 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG7NN285618 C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 7146 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, 275/80R22.5, Volvo Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 295,698 Mi Asset located in: Lake Worth, TX		Tractor S/N: 4V4W39EGXKN226147 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15950 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, Meritor RS23-160 Drive Axles, 35350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 730,594 Mi Asset located in: Lake Worth, TX
8936	2022 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG7NN285540 C/W: Volvo D13N405 6 Cylinder 12.8 L 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 8483 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 347,925 Mi	8941	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EGXKN907544 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000.0 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Air Ride Suspension, 133 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 680,054 Mi Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	8942	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor
8937	2021 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG7MN285326 C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 7976 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, 295/75R22.5, Volvo Air Ride Suspension, 151 in Wheelbase, Dual Fuel Tanks Usage: 322,314 Mi Asset located in: Lake Worth, TX		S/N: 4V4W19EG1KN907528 C/W: Volvo D13M-405 6 Cylinder 12.8 L 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 706,546 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8943	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG3KN901925 C/W: Volvo D13M405 6 Cylinder 12.8 L 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17551 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 754,359 Mi	8947	2013 Volvo VNL200 4x2 S/A Day Cab Truck Tractor S/N: 4V4N39EG8DN142388 C/W: Volvo D13H405 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, 35350 lb GVWR, 11R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel Usage: 535,477 Mi Asset located in: Lake Worth, TX
9044	·	8948	2012 Volvo VNL300 4x2 S/A Day Cab Truck
8944	2018 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG1JN901758 C/W: Volvo D13M405 6 Cylinder 12.8 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-		Tractor S/N: 4V4N19EG6CN560842 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 32350.0 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 311,531 Mi Asset located in: Humble, TX
	CORP	8949	2014 International ProStar 4x2 S/A Day Cab
	Usage: Not Available Asset located in: Lake Worth, TX		Truck Tractor S/N: 1HSDGAPN6EH036926
8945	2017 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EG1HN985095 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 22474 Engine hrs, Volvo AT2612D 12-Speed Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, VOLVO Air Ride		C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, Aluminum Outer Rear Wheels, 11R22.5, Air Ride Suspension, 173 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 360,386 Mi Asset located in: Lake Worth, TX
	Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 876,316 Mi	8950	2015 International 4400 4x2 S/A Day Cab Truck Tractor S/N: 1HSMTSTN8FH726444 C/W: Navistar N9 6 Cylinder 9.3 L Diesel Engine, Requires Diesel Exhaust Fluid, 3580 Engine hrs, Engine Brake, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 152 in Wheelbase, PTO Usage: 85,797 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
8946	2015 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH4FN184666 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15123 Engine hrs, Engine Brake, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32350 lb GVWR, Air Ride Cab, 295/75R22.5,		
	Volvo Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks	8951	2012 International 4400 4x2 S/A Day Cab
	Usage: 579,823 Mi Notes: TITLE COMES WITH A CORRECTION OF AFFIDAVIT Asset located in: Humble, TX		Truck Tractor S/N: 1HSMTAAN4CH561985 C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel 300 hp Engine, 2011 US EPA Label, 4407 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 148 in Wheelbase, Dual Fuel Tanks Usage: 136,823 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8952 8953	2009 International ProStar Premium 4x2 S/A Day Cab Truck Tractor S/N: 2HSCSAPN49C045678 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, 275 /80R22.5, Air Ride Suspension, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 610,101 Mi Asset located in: Lake Worth, TX 2008 International TranStar 8600 4x2 S/A Day	8956A	2007 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GFX7N451743 C/W: Volvo 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Engine Brake, Eaton Fuller FR13210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-186 Drive Axles, 2.93:1 Axle Ratio, 32000 lb GVWR, Aluminum Front Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 144 in Wheelbase, Dual Fuel Tanks Usage: 1,551,805 Mi Asset located in: Lake Worth, TX
	Cab Truck Tractor S/N: 1HSHWAHN68J673895 C/W: Cummins 6 Cylinder Engine, 22559 Engine hrs, Eaton Fuller 10-Speed Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 148 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 582,442 Mi Asset located in: Midland, TX	8957	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GF32N335289 C/W: Volvo DT12C345 6 Cylinder 12.1 L Diesel 345 hp Engine, 2001 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 2.93:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP
8954	2005 International 9400i 4x2 S/A Day Cab Truck Tractor		Usage: 344,373 Mi Asset located in : Lake Worth, TX
	S/N: 3HSCPAPN05N049267 C/W: Cummins ISX 6 Cylinder 400 hp Engine, 2004 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 835,214 Mi Notes: CANNOT VERIFY ODOMETER READING - VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE Asset located in: Lake Worth, TX	8958	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19RF72N324549 C/W: Detroit 6 Cylinder 12.7 L Diesel 470 hp Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 32000 lb GVWR, 295/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 154 mm Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 1,393,840 Mi
8955	2003 Freightliner FLD 112 4x2 S/A Day Cab Truck Tractor S/N: 1FUBACA873DK79061 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel 370 hp Engine, 2002 US EPA Label, Meritor 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 2.93:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 919,458 Mi Asset located in: Lake Worth, TX	8959	2014 Kenworth T370 S/A Sleeper Truck Tract S/N: 2NKHHJ7X8EM417041 C/W: EQUIPMENT FROM A PRIMORIS SERVICES CORP COMPANY Usage: Not Available Notes: Asset located in: Midland, TX 1999 Volvo VN 4x2 Flatbed Truck S/N: 4VG7DBUF5XN768395 C/W: Cummins ISM 6 Cylinder 10.8 L Ultra Lor Sulfur Diesel 330 hp Engine, 1998 US EPA Label, Eaton Fuller Automatic Transmission, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Spring Suspension, 237 in Wheelbase, 10 ft 4 in x 96 in Bed Usage: 834,602 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DM PRIOR TO BIDDING Asset located in: Lake Worth, TX
8956	2008 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH28N498237 C/W: Volvo 6 Cylinder 12.8 L Diesel Engine, 2007 US EPA Label, Engine Coolant Heater, 10- Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 295 /75R22.5, Paccar Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 1,428,300 Mi Asset located in: Midland, TX		

Lot #	Details	Lot #	Details
8961	2017 Peterbilt 579 4x2 (CNG) S/A Day Cab Truck Tractor S/N: 1NPBAH8X7HD421460 C/W: Cummins ISX12 6 Cylinder 11.9 L Compressed Natural Gas (CNG) 400 hp Engine, 2016 US EPA Label, Engine Brake, Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, 35050 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel Usage: 549,140 Mi Asset located in: Lake Worth, TX	8966	2016 Etnyre RTN60TD4-PS Quad/A Removable Gooseneck Lowboy Trailer S/N: 1E9320301GE111172 C/W: Air Ride Suspension, Lift 4th- Axles, Hydraulic Removable Gooseneck, 26 ft Main Deck, 16 ft Rear Deck, 102 in Usable Deck Width, Folding Side Extensions, Deck Over Tires, Manual Ramps, 275/70R22.5 Tires, 66842 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Humble, TX
8962	2017 Freightliner Cascadia 113 CNG 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGBD98HLGV4596 C/W: Cummins ISX12G 11.9 L Compressed Natural Gas (CNG) 400 hp Engine, 2015 US EPA Label, Allison 4000 HS Automatic Transmission, 12500 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 3.91:1 Axle Ratio, 35050 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 182 in	8967	2015 XL Specialized 120SDE Tri/A 53 ft Extendable Lowboy Trailer S/N: 4U3B05337FL014387 C/W: Air Ride Suspension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 42 ft Main Deck, 97 in Overall Deck Width, 102 in Widening Width, 235/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Wheelbase Usage: 23,705 Mi Asset located in : Lake Worth, TX		2007 Trail King TK110HDG 55 t Tri/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533X7M051363
8963	2008 Trail King TK140MDG-693 70 ton Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ069368B045330 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, Tri/A Jeep, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 30 ft Main Deck, 108 in Usable Deck Width, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275/70R22.5 Tires, 175300 lb GVWR Usage: Not Available Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED		C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 102 in Usable Deck Width, 12 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 132800 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED Asset located in: Lake Worth, TX 2007 Trail King TK55T 55 ton Quad/A
8964	Asset located in: Lake Worth, TX 2008 Etnyre RTN65TD3-RA 3+1+1 Lowboy Trailer S/N: 1E92980888E111025 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 25 ft 7 in Main Deck, 98 in Usable Deck Width, 108 in Overall Deck Width, 275/70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Removable Gooseneck Lowboy Trailer S/N: 1TKJ053347B051452 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, S/A Flip Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 102 in Usable Deck Width, Folding Side Extensions, Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275/70R22.5 Tires, 110000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2024 Witzco RG-52 Challenger 52 ton Tri/A
8965	2006 Trail King TK130HDG-573 Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ057386M014661 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 28 ft Main Deck, 120 in Overall Deck Width, Honda Gas Powered Self Contained Hydraulic System, 235/75R17.5 Tires, 161280 lb GVWR, Spreader Bar Usage: Not Available Asset located in: Humble, TX		Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E32RS000472 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8971	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E36RS000474 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	8976	2013 Trail King TK110HDG 55 t Tri/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533XDM109113 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in Usable Deck Width, 126 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 134660 lb GVWR, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED
8972	2024 Witzco RG-52 Challenger 52 ton Tri/A		Asset located in: Lake Worth, TX
	Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E34RS000473 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	8977	2010 Trail King TK110HDG533 55 ton Tri/A Single Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ05330AM109858 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft 7 in Rear Deck, 102 in Usable Deck Width, 24 in Widening Width, Folding Side Extensions, Boom Recess, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 255/70R22.5 Tires, 133820 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED Asset located in: Lake Worth, TX
8973	2015 XL Specialized 120SDE Lowboy Trailer S/N: 4U3B05330FL014621 Usage: Not Available Asset located in: Lake Worth, TX		
8974	2013 Trail King TK110HDG533 55 t Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ05333DM041625 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 26 ft Main Deck, 102 in Usable Deck Width, Folding Side Extensions, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, 275/70R22.5 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	8978	2022 Pitts LB51-22 51 ton Tri/A Single Drop Lowboy Trailer S/N: 5JYLB5137NPP24054 C/W: Air Ride Suspension, Air Brakes, Lift 3rd-Axles, Hydraulic Removable Gooseneck, 26 ft Main Deck, 16 ft Rear Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Deck Over Tires, Aluminum Outer Wheels, 255 /70R22.5 Tires, 121500 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8975	Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ05334DM109110 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in Usable Deck Width, 126 in Widening Width, Folding Side Extensions, Boom Recess, Pack		Asset located in: Humble, TX
		8980	2010 Witzco Challenger RG50 Tri/A Lowboy Trailer S/N: 1W8A11F37AS000227 Usage: Not Available Asset located in: Lake Worth, TX
		8981	2009 Etnyre RTN60TD3-PS Tri/A Removable Gooseneck Lowboy Trailer S/N: 1E93014909E111031 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, S/A Flip Booster Axle, 24 ft 4 in Main Deck, 17 ft 2 in Rear Deck, 102 in Usable Deck Width, 275/70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8982	2019 Fontaine T/A Removable Gooseneck Lowboy Trailer S/N: 57J348208K3575771 C/W: Air Ride Suspension, Air Brakes, 255 /70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	8988	1981 Nuttall 225-E T/A Lowboy Trailer S/N: NMC50296 C/W: Spring Suspension, 9 ft 4 in Upper Deck, 23 ft 5 in Main Deck, 5 ft 4 in Fixed Dovetail, 90 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Manual Ramps, 10.00R15 Tires
8983	2004 Fontaine 552-2MWNGB 55 ton 2+2		Usage: Not Available Asset located in : Lake Worth, TX
	Removable Gooseneck Lowboy Trailer S/N: 4LFE7640943523624 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, 29 ft Main Deck, 96 in Usable Deck Width, 120 in Widening Width, Folding Side Extensions, Gas Powered Self Contained Hydraulic System, 275	8989	1990 Talbert TJ-11R22.5 35 ton T/A Heavy-Haul Jeep S/N: 40FJK2725L1008821 C/W: Air Ride Suspension, 275/70R22.5 Tires, 67079 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	/70R22.5 Tires, 147500 lb GVWR Usage: Not Available	8990	T/A Heavy-Haul Jeep
8984	Asset located in: Lake Worth, TX 2000 Fontaine T/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 13ND48291Y1590100 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, 9 ft 7 in Upper Deck, 29 ft 2 in Main Deck, 7 ft 8 in Rear Deck, 102 in	_	S/N: Not Available C/W: Sliding 5th Wheel, Pickup Throat, Tail Roller, Rubber Block Suspension, 11R24.5 Tires, Low-Boy Ramps, Neck Roller Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Usable Deck Width, Deck Over Tires, 255 /70R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	8992	2018 Liddell C55 S/A Booster Axle S/N: 1L93J0517JB564012 C/W: Flip-Up, Air Ride Suspension, 255/70R22. 5 Tires Usage: Not Available
8985	1984 Cozad 2+2+2 Removable Gooseneck		Asset located in: Lake Worth, TX
C/W: Walking Removable G Axle, 30 ft Ma Width, Drops Cozad 16 Wh	S/N: 1C9B48207E1167105 C/W: Walking Beam Suspension, Mechanical Removable Gooseneck, Plumbed for Booster Axle, 30 ft Main Deck, 102 in Usable Deck Width, Dropside Deck, 11R24.5 Tires, 1984 Cozad 16 Wheel Expando Jeep w/Hyd Tower, s	8993	2015 XL Specialized XL24FA S/A Booster Axle S/N: 4U3S00514FL014398 C/W: Pin-On, Air Ride Suspension, 235/75R17. 5 Tires, 26300 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Pin-On Booster, 70R22.5 Tires; Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT.	8994	1989 Fontaine S/A Booster Axle S/N: 13NM04107K1547671 C/W: Pin-On, Air Ride Suspension, 255/70R22. 5 Tires, 18160 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
8986	Asset located in: Humble, TX 2008 Viking VFDD46R18F35T T/A Double Drop	8995	2020 Wabash TCD/CDC-CDH S/A Dolly
	Lowboy Trailer S/N: 1V9CR46288N062389 C/W: Spring Suspension, 9 ft Upper Deck, 21 ft 5 in Main Deck, 9 ft 2 in Rear Deck, 4 ft Fixed Dovetail, 102 in Usable Deck Width, Upper Deck	8995	S/N: 1JJD061X6LL222455 C/W: Spring Suspension, 275/80R22.5 Tires, 20000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
	Ramps, Deck Over Tires, Spring Assisted Ramps, 255/70R22.5 Tires, 87000 lb GVWR Usage: Not Available Asset located in : Midland, TX		1994 Pines S/A Dolly S/N: 1PNA09101RK056464 C/W: Spring Suspension, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP
8987	2002 Kalyn Siebert LB0353T Quad/A Lowboy Trailer S/N: 5DDKE404221000577 C/W: Walking Beam Suspension, 39 ft Main Deck, 98 in Usable Deck Width, 102 in Overall Deck Width, Tail Roller, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8996A 8997	1987 Fruehauf ELF-1 S/A Dolly S/N: 1H2E00617HH031475 C/W: 295/75R22.5 Tires, 20000 lb GVWR Usage: Not Available Notes: LOCATED-IN-MONTICELLO-MD- YELLOW; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX 2016 Trail-Eze TE70XT T/A Hydraulic Tail Trailer	9002	2016 Trail-Eze TE70XT 28983 lb T/A Hydraulic Tail Trailer S/N: 1DAHFC725GC021848 C/W: Aluminum Frame, Spring Suspension, Air Brakes, 6 ft 6 in Upper Deck, 25 ft Main Deck, 2-Position Dovetail, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Hydraulic Ramps, 10r17.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available
	S/N: 1DAHFC725GP022068 C/W: Air Ride Suspension, Sliding Suspension,	9004	Asset located in: Lake Worth, TX 2007 Ledwell LW48 T/A Hydraulic Tail Trailer
	7 ft 9 in Upper Deck, 38 ft Main Deck, 5 ft 2- Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R17. 5 Tires, 86720 lb GVWR, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9004	S/N: 1L9GA72A37L033118 C/W: Spring Suspension, 7 ft Upper Deck, 28 ft Main Deck, 8 ft 2-Position Dovetail, 102 in Overall Deck Width, Winch, Deck Over Tires, Hydraulic Ramps, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
8998	2019 Trail King TK70HT T/A Hydraulic Tail Trailer	9005	2006 Ledwell T/A Hydraulic Tail Trailer
	S/N: 1TKA04828KM102376 C/W: 84800 lb GVWR, Spring Suspension, 9 ft Upper Deck, 38 ft 8 in Main Deck, 9 ft 2- Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 215/75R17.5 Tires Usage: Not Available		S/N: 1L9GA72A96L033669 C/W: Air Ride Suspension, 8 ft Upper Deck, 29 ft 2 in Main Deck, 8 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Winch, 255/70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9006	2023 Maxey YHX T/A Gooseneck Hydraulic
8999	2018 Fontaine Traverse HT T/A Hydraulic Tail Trailer S/N: 57JV482DXJ3574695 C/W: Air Ride Suspension, 6 ft 10 in Upper Deck, 38 ft 5 in Main Deck, 4 ft 3 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, 10R17.5 Tires, 83200 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available		Tail Trailer S/N: 5R8GF4023PM106833 C/W: Spring Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, 40000 lb GVWR, Hydraulic Landing Gear Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9007	1996 Trail-Eze DHT7048 T/A Hydraulic Tail Trailer
9000	2016 Trail King TK80HT T/A Hydraulic Tail Trailer S/N: 1TKA04823GM031272 C/W: Air Ride Suspension, 7 ft 8 in Upper Deck, 38 ft 10 in Main Deck, 7 ft 8 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R-17.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available		S/N: 1DA72C7D9TM012261 C/W: Air Ride Suspension, 9 ft 9 in Upper Deck, 30 ft 2 in Main Deck, 8 ft 2-Position Dovetail, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 83520 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
0001	Asset located in: Lake Worth, TX	9008	2014 Landoll 930C T/A Sliding Axle Trailer S/N: 1LH930UHXE1C20991
9001	2016 Trail-Eze TE70XT T/A Hydraulic Tail Trailer S/N: 1DAHFC727GP022069 C/W: Air Ride Suspension, Sliding Suspension, 7 ft Upper Deck, 38 ft 1 in Main Deck, 4 ft 10 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, 10R17.5 Tires, 86720 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		C/W: Spring Suspension, Air Brakes, Sliding Suspension, 4 ft Upper Deck, 23 ft Main Deck, 13 ft Rear Deck, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10r17.5 Tires, 86300 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9008A 9009	2011 Landoll 48 ft T/A Sliding Axle Trailer S/N: 1LH317UHXB1D18600 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck, 37 ft Main Deck, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 87000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2012 Lucon 44 ft T/A Sliding Axle Trailer	9015	2012 Manac 14353A000 Tri/A 53 ft - 73 ft Extendable Single Drop Step Deck Trailer S/N: 2M5131611C1130362 C/W: Air Ride Suspension, 10 ft 6 in Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Extendable Deck, Tail Roller, Wood Flooring, Aluminum Outer Wheels, 255/70R22. 5 Tires, 45360 lb GVWR Usage: Not Available
	S/N: 1L9SC5322CG423002 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 44 ft Main Deck, 97 in Usable Deck Width, 99 in Overall Deck Width, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Humble, TX 2006 Transcraft DTL-2100 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE5320061080090 C/W: Air Ride Suspension, 10 ft Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in
9010	2025 Maxey 40 ft T/A Sliding Axle Trailer (Unused) S/N: 5R8GF4025SM118166 C/W: Spring Suspension, Electric Brakes, Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Back Width, 23F (2001) Fixed 25F (2001) For the C		Overall Deck Width, Wood Flooring, Aluminum Outer Wheels, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Deck Width, 235/80R16 Tires, 25990 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9017	2018 Trail King 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB04825JY067453
9011	Deck Trailer S/N: 1GR4M0629PH443585 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck, 43 ft Main Deck, 96 in Usable Deck Width, Deck		C/W: Air Ride Suspension, 9 ft 10 in Upper Deck, 37 ft Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Aluminum Flooring, 255/70R22.5 Tires, 90420 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Over Tires, Aluminum Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in : Humble, TX	9018	2014 Direct Trailers 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 5UJDS4829EE002311
9012	2022 Brazo 80000 lb 53 ft T/A Single Drop Step Deck Trailer S/N: 4B9BKFS23NH054914 C/W: 80000 lb GVWR, Air Ride Suspension, Aluminum w/Wood Strips Flooring, 255/70R22. 5 Tires		C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, 255/70R22. 5 Tires, 70852 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9019	2013 Fontaine 48 ft T/A Spread Axle Single Drop Step Deck Trailer
9013	2017 Trail King TK80ACS-40 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB05326HY082695 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 10 ft 4 in Upper Deck, 42 ft 2 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires, 90930 lb GVWR	9020	S/N: 13N248206D1557385 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Center Roller, Tail Roller, Wood Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2013 Transcraft 48 ft T/A Spread Axle Single Drop Step Deck Trailer
9014	2013 Utility FS2CDHA 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1UYFS2534DA605126 C/W: Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: Asset located in: Oklahoma City, OK		S/N: 1TTE482S6D3756769 C/W: Air Ride Suspension, 11 ft Upper Deck, 37 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9021	2006 Transcraft 48 ft T/A Single Drop Step Deck Trailer S/N: 1TTE4820861081701 C/W: Air Ride Suspension, Lift 1st- Axles, 10 ft 3 in Upper Deck, 36 ft Main Deck, 92 in Usable Deck Width, 102 in Overall Deck Width, 255 /70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9027	2016 Fontaine 53 ft T/A Step Deck Curtain Side Trailer S/N: 13N2532C2G1512734 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, Ramp, Roll-Up Door, Aluminum Outer Wheels, 225/70R22.5 Tires, 66667 lb GVWR Usage: Not Available Asset located in: Humble, TX
9022	2005 Fontaine DFT-5-8048WSAWK 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N24830851529149 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 8 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, 255/70R22.5 Tires, 69556 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9028	2013 Utility FS2CHS 53 ft T/A Flatbed Trailer S/N: 1UYFS253XDA605017 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9023	2000 Pro-Trak 53 ft T/A Step Deck Trailer S/N: 5BNDG5322YC001797 C/W: Spring Suspension, Electric Brakes, 9 ft Upper Deck, 39 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 225/75R16 Tires Usage: Not Available	9030	Trailer S/N: 1GRDM0625CH715673 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2005 Benson 53 ft Tri/A Flatbed Trailer
9024	2023 Utility 53 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2530P5872213 C/W: 73000 lb GVWR, Air Ride Suspension, 97 in Deck Width, 97 in Overall Width, Aluminum w /Wood Strips Flooring, Aluminum Outer		S/N: 5DMFABTC85M000235 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9025	Wheels, 295/75R22.5 Tires, Storage box Usage: Not Available Asset located in: Humble, TX 2023 Utility 53 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2534P5872215 C/W: 73000 lb GVWR, Air Ride Suspension, 97	9031	2007 Chaparral 50 ft T/A Spread Axle Flatbed Trailer S/N: 1C92F50257M949174 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 90000 lb GVWR
	in Deck Width, 97 in Overall Width, Aluminum w /Wood Strips Flooring, Aluminum Outer Wheels, 295/75R22.5 Tires, Storage box Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Lake Worth, TX 2023 Transcraft 40000 lb 48 ft T/A Spread Axle Flatbed Trailer (Unused) S/N: 1TTF482C2P3354782
9026	2023 Utility FS2CHA 53 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2532P5872214 C/W: Air Ride Suspension, 97 in Deck Width, 97 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 295/75R22. 5 Tires, Storage box Usage: Not Available Asset located in: Humble, TX		C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		9032A	2020 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GR4M9624LH151129 C/W: Air Ride Suspension, Air Brakes, 97 in Deck Width, 102 in Overall Width, Aluminum w /Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9033	2019 Manac 10248K001L 48 ft T/A Flatbed Trailer S/N: 5MC124811K3181128 C/W: Air Ride Suspension, 92 in Deck Width, 102 in Overall Width, Wood Flooring, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9039	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A26FR032319 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2015 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A8F3882257
9034	2016 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM9622GH729220 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Aluminum Flooring, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available	9041	C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2015 Fontaine 48 ft T/A Spread Axle Flatbed Trailer
9035	Asset located in: Lake Worth, TX 2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A22FR032303 C/W: Aluminum Frame, Air Ride Suspension,		S/N: 13N148202F1571993 C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 11R22.5 Tires, 70543 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		2013 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482S7D3749530 C/W: Air Ride Suspension, Air Brakes, Sliding
9036	2015 Benson 524 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A1F3882259 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9043	Suspension, 97 in Deck Width, 102 in Overall Width, Wood Flooring, Aluminum Wheels, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX 2012 Manac 48 ft T/A 48 ft - 80 ft Extendable Flatbed Trailer S/N: 2M5121463C1128632 C/W: Spring Suspension, Air Brakes, Sliding
9037	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A29FR032427 C/W: Aluminum Frame, Air Ride Suspension,		Suspension, 91 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 73855 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		Tr S/ C/
9038	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A26FR032336 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Strips Flooring, 285/75R24.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX
		9045	2012 Utility FS2CHA 48 ft T/A Flatbed Trailer S/N: 1UYFS2483CA431528 C/W: Air Ride Suspension, 97.5 in Deck Width, 100.5 in Overall Width, Aluminum w/Wood Strips Flooring, 285/75R24.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9046	2009 Wade WH1-48FT T/A Extendable Flatbed Trailer S/N: 1W9FH48289E285033 C/W: Spring Suspension, Sliding Suspension, 11R22.5 Tires, 80000 lb GVWR, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP-	9053	1999 Fontaine T/A Extendable Flatbed Trailer S/N: 13N548209X1586994 C/W: Air Ride Suspension, 98 in Deck Width, 98 in Overall Width, 11R22.5 Tires, 75074 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	COMPANY Usage: Not Available Notes: BENT FRAME PER SELLER Asset located in: Lake Worth, TX	9054	1999 Fontaine 48 ft T/A Spread Axle Flatbed Trailer S/N: 1R1F94820XK990187 C/W: Aluminum Frame, Air Ride Suspension,	
9047	2008 Fontaine 48 ft T/A Spread Axle Flatbed Trailer S/N: 5TR34830081001876 C/W: Aluminum Frame, Air Ride Suspension, 98 in Deck Width, 102 in Overall Width,		98 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 11R24.5 Tires, 79600 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Aluminum Flooring, 11R24.5 Tires, 71473 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9055	1988 Fontaine FTW-3-8045SL 45 ft T/A Flatbed Trailer S/N: 13N1452CXJ1544459 C/W: Spring Suspension, Sliding Suspension,	
9048	2007 Lufkin 45 ft T/A Flatbed Trailer S/N: 1L01B452471164518 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires	9056	92 in Deck Width, 96 in Overall Width, Wood Flooring, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX		2025 Atro 34 ft T/A Frameless End Dump Trailer	
9049	2006 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B482761159825 C/W: Spring Suspension, Sliding Suspension, 96 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires, 80000 lb GVWR,		Walls, Steel Body, Air Lift Tailgate, 1 Tires, 74957 lb GVWR Usage: Not Available	C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR
	EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9057	2025 Atro 34 ft T/A Frameless End Dump Trailer	
9050	2006 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820961078665 C/W: Spring Suspension, Sliding Suspension, 95 in Deck Width, 102 in Overall Width, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available		S/N: 3ELA6EH27SG000348 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	9058	2025 Atro 34 ft T/A Frameless End Dump Trailer	
9051	2008 Transcraft TL-2000N 45 ft T/A Flatbed Trailer S/N: 1TTF4520082021315 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available		S/N: 3ELA6EH29SG000349 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
		9059	2025 Atro T/A End Dump Trailer	
9052	2005 Fontaine T/A 35 ft Extendable Flatbed Trailer S/N: 13N43620651527739 C/W: Spring Suspension, 87 in Deck Width, 91 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		S/N: 3ELA6EH25SG000347 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls, Aluminum Body, Electric Roll Tarp, 11R24.5 Tires, 74957 lb GVWR, Aluminum Lead Body, 4 ft Lead Side Walls, Electric Lead Tarp Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9060	2025 Atro T/A End Dump Trailer S/N: 3ELA6EH25SG000350 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls Usage: Not Available Asset located in: Lake Worth, TX	9067	2015 MAC 40 ft T/A Frameless End Dump Trailer S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available
9061	2025 Atro 34 ft T/A Frameless End Dump Trailer		Asset located in: Lake Worth, TX
	S/N: 3ELA6EH27SG000382 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9068	2022 Discount Dumps 36 ft T/A End Dump Trailer S/N: 1D91A3925N1865007 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 36 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires
9062	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH24SG000386		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9069	2016 Dragon 34 ft Tri/A Quarter Frame End Dump Trailer S/N: 1UNSD3431GS128862 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 34 ft Body, 50 in Side Walls,
9063	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH22SG000385 C/W: Spring Suspension, 34 ft Body, 40 in Side		Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available Notes: . Asset located in: Humble, TX
	Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9070 2016 Ranco ED 26-34 34 ft T/A Frameless Dump Trailer S/N: 591SD3429GR136697 C/W: Spring Suspension, 34 ft Body, 44 in Walls, Steel Body, Electric Roll Tarp, 11R2- Tires, 70000 lb GVWR Usage: Not Available	•
9064	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH29SG000383		Usage: Not Available
	C/W: Spring Suspension, 34 ft Body, 49 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 Ib GVWR Usage: Not Available Asset located in : Lake Worth, TX	9071	Asset located in: Lake Worth, TX 2004 Midland MG34ST2400 34 ft T/A Quarter Frame End Dump Trailer S/N: 2MFB2R5CX4R002967
9065	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH20SG000384 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 Ib GVWR		C/W: Spring Suspension, 34 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, Aluminum Outer Wheels, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9072	2017 Manac 32 ft T/A Frameless End Dump Trailer
9066	2015 MAC 40 ft T/A Aluminum Frameless End Dump Trailer S/N: 5MADN4020FC033902 C/W: Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 5MC423214H3163988 C/W: Spring Suspension, 32 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 82000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		9074	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515423AP011370 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9075	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515427AP011372 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2010 Manac HRS32 32 ft T/A Frameless End	9081	2018 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A30339JH036173 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available Notes: Asset located in: Humble, TX
	Dump Trailer S/N: 5MC515420AP011374 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9082	2001 Travis 39 ft T/A Frameless End Dump
			Trailer S/N: 48X1F392911001782 C/W: Air Ride Suspension, 39 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 275/80R24.5 Tires
9077	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 5MC515429AP011373 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9083	2003 Ranco 36 ft T/A Frameless End Dump Trailer S/N: 1R9ESD5073L008627 C/W: Spring Suspension, 36 ft Body, 46 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R22.5 Tires, 70000 lb GVWR Usage: Not Available
9078	2021 Mate 30 ft Tri/A Aluminum Quarter Frame End Dump Trailer S/N: 1M9A30333MH036271 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes: . Asset located in: Humble, TX		Asset located in: Lake Worth, TX
		9084	2002 Vantage 37 ft T/A Aluminum Frameless End Dump Trailer S/N: 4EPAA37292ATA4342 C/W: Air Ride Suspension, 37 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9079	2018 Mate 30 ft Tri/A Quarter Frame End	9085	1999 Smithco T/A Side Dump Trailer
	Dump Trailer S/N: 1M9A30332JH036175 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum		S/N: 1S9SS4022XL476665 C/W: Spring Suspension, Dumps to Both Sides, 36 in Side Walls, Steel Body, 425/66R22.5 Tires Usage: Not Available Asset located in : Lake Worth, TX
9080	Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available Notes: . Asset located in: Humble, TX 2021 Mate 30 ft Tri/A Quarter Frame End	9086	1983 Fontaine 12 ft T/A Pup Dump Trailer S/N: 1A1V2920XD16PT113 C/W: Spring Suspension, 12 ft Body, 46 in Side Walls, Steel Body, Manual Roll Tarp, 10.00-22 Tires, 47500 lb GVWR
	Dump Trailer S/N: 1M9A3033XMH036270		Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes: . Asset located in: Humble, TX	9087	2017 CTS BDT 40 T/A Belly Dump Trailer S/N: 5TU114021HS000432 C/W: Air Ride Suspension, Clam Gate Electric Roll Tarp Push Block, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		9088	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114021GS000512 C/W: Air Ride Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

		T		
Lot #	Details	Lot #	Details	
9089	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114028GS000197 C/W: Spring Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2016 Construction Trailer Specialist BDT-40 T	9097	2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX	
	/A Belly Dump Trailer	0000		
	S/N: 5TU114024GS000021 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9098	1999 Timpte 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42224XB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available	
9092	2014 Armor Lite SBD-40 40 ft T/A Belly Dump		Asset located in: Lake Worth, TX	
	Trailer S/N: 56EA53K23EA000188 C/W: Spring Suspension, Cross Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	9099	2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	9100	2012 Western 53 ft T/A Spread Axle Curtain	
9093	2013 Manac 40 ft T/A Belly Dump Trailer S/N: 5MC424017D3133810 C/W: Air Ride Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Side Trailer S/N: 5DN115323CB000814 C/W: Air Ride Suspension, Aluminum Wheels, 295/75R22.5 Tires, 69000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Lake Worth, TX	9101	1999 Nu Van NVSS 53 ft 53 ft x 102 in T/A	
9094	2003 Trail King BD237 T/A Belly Dump Trailer S/N: 1TKSC40213W101924 C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1N9F532P7X10 C/W: Air Ride Suspe Swing Door, 295/75I GVWR Usage: Not Available	Curtain Side Trailer S/N: 1N9F532P7X1045092 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, 295/75R22.5 Tires, 66000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9095	1999 Midland MG36CLAM T/A Belly Dump	9102	1998 Raven 48 ft T/A Spread Axle Curtain Side	
J0 J0	Trailer S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available		Trailer S/N: 1R1F04823WK980200 C/W: Aluminum Frame, Air Ride Suspension, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	9103	2024 Atro 53 ft x 102 in T/A Van Trailer	
9096	1997 Schaller Manufacturing Roadmaster G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	Ride Suspension, Sliding Suspen Aluminum Roof, Hardwood Floo Swing Door, 295/75R22.5 Tires Usage: Not Available	C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires	

Lot #	Details	Lot #	Details	
9104	2023 Atro 53 ft x 102 in Van Trailer S/N: 3ELA6RX28PG000052 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION	9110	2022 Inland IN53-DPA-HK40 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N5NM180012 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	
0105	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9111	2021 Inland 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N9MM180044 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof,	
9105	2023 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX24PG003157 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Outer Wheels, 295		Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Asset located in : Lake Worth, TX	
	Swing Door, Aluminum Outer Wheels, 295	9112	2021 Inland 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N0MM180045 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door Usage: Not Available	
0106	Asset located in: Lake Worth, TX	9113	Asset located in: Lake Worth, TX 2021 Inland IN53-DPA-HK40 53 ft x 102 in T/A	
9106	2023 Vanguard REM VXP 53 53 ft x 102 in T/A Van Trailer S/N: 5V8VC5324PT305207 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN	3113	Van Trailer S/N: 3T9S372N7MM180124 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	9115	2020 Utility VS2DX 53 ft x 102 in T/A Van Trailer	
9107	2022 Vanguard MaxCube 53 ft x 102 in T/A Van Trailer S/N: 5V8VA5321NM211220 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door,	9116		S/N: 1UYVS2533L3961520 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in : Lake Worth, TX		9116 2020 Utility VS2DX 53 ft x 102 in T/A Var Trailer S/N: 1UYVS2532L7961064	S/N: 1UYVS2532L7961064
9108	2022 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX21NG001704 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires		C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX	
9109	Usage: Not Available Asset located in: Lake Worth, TX 2022 Hyundai VC2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532K6NS852024 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: FRAME IS DAMAGED; Asset located in: Lake Worth, TX		2020 Utility VS2DX 53 ft T/A Van Trailer S/N: 1UYVS2531L3961595 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9118	2020 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2534L3961509 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9125	2016 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2535GG724302 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9119	2020 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D4LL162426 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275 /80R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV	9126	2015 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D5FL877087 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9120	PRIOR TO BIDDING Asset located in: Lake Worth, TX 2019 Great Dane CCC-3314-21053 53 ft x 102	9127	2015 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2531FG241727 C/W: 65000 lb GVWR, Aluminum/Steel
9120	in T/A Van Trailer S/N: 1GRAP0621KJ137637 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Combination Frame, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DN PRIOR TO BIDDING
9121	2019 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2539K3560164 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9128	Asset located in: Lake Worth, TX 2015 Wabash DVHDHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D9FL880526 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Notes: Asset located in: Lake Worth, TX
9122	2018 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9JR390021 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door Usage: Not Available	S/N: 1JJV532D1FL799987 C/W: 68000 lb GVWR, Spring Suspe Sliding Suspension, Hardwood Floo Skirts, Swing Door, 295/75R22.5 Til Usage: Not Available Asset located in: Lake Worth, TX	C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Lake Worth, TX
9123	Asset located in: Lake Worth, TX 2018 Stoughton ZGPVW-535T-S-C 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5320JSA09456 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9130	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D3FL845934 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9131	2015 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532DXFL833585 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9142	2008 Hyundai 53 ft x 102 in T/A Van Trailer S/N: 3H3V532C18T249117 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, Mixed Tires Usage: Not Available Notes: THE CLOSING TIME OF LOTS 8674 TO 8675 ARE TIED TOGETHER. IF A BID IS
9132	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532DXFL842528 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER OF LOTS 8674 TO 8675 IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER Asset located in: Lake Worth, TX
9136	2012 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9CT100009 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	9143	2008 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E95388E520408 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9137	Asset located in: Lake Worth, TX 2012 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0628CT566670 C/W: Air Ride Suspension, Sliding Suspension,	9144	2008 Utility 53 ft Van Trailer S/N: 1UYVS25338U340103 Usage: Not Available Asset located in: Lake Worth, TX
	Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX		2008 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS253X8P320087 C/W: Aluminum/Steel Combination Frame, Air
9139	2009 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VA53269M903270 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR		Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Humble, TX	9146	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06287T539717
9140	2009 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VA532X9M903272 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires		C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX		Asset located in: Lake Worth, TX
9141	2008 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53208B027611 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Humble, TX	- 9147	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06247G341628 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9148	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06277J622907 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2007 Great Dane 7411TP-SA 53 ft x 102 in T/A	9154	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06257J618967 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
	Van Trailer S/N: 1GRAA06217J618769 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX		2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06217D423608 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Asset located in: Humble, TX	
9150	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06277D423628 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 30845 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06207J623042 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX		2007 Lufkin TFV-CL-SP 53 ft x 102 in T/A Van	
9151	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06227D423651 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445 /50R22.5 Super Single Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Trailer S/N: 1L01A532071163667 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Asset located in: Humble, TX	9159	2007 Wabash 53 ft x 102 in T/A Van Trailer	
9152	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06287D426747 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 68000 lb GVWR		C/W: 68000 lb GVWR, Air Ride Su Sliding Suspension, Translucent Hardwood Floor, Swing Door Usage: Not Available	Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Humble, TX	9160	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W37L094904	
9153	2007 Great Dane 7411TP 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06237D423576 C/W: Air Ride Suspension, Air Brakes, Sliding		C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445 /50R22.5 Super Single Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9161	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W07L051279 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9162	2007 Wabash DVLHHSA 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W37L064138 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9168	2006 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS25386G753257 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE
9163	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W97L079985	0170	Asset located in: Lake Worth, TX
	C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9170	2006 Lufkin TFC-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532361161071 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door,
9164	2007 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer		295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	S/N: 1JJV532W27L080010 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9171	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532261160929 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts,
9165	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W97L080022 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor,		Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9172	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Va Trailer S/N: 1L01A532661160948 C/W: Air Ride Suspension, Sliding Suspension
9166	2006 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W16L944656		Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2006 Lufkin TFV-CL-110 53 ft T/A Van Trailer S/N: 1L01A532461161032 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floo Side Skirts, Swing Door, 295/75R22.5 Tires,
9167	2006 Wabash 53 ft x 102 in Van Trailer S/N: 1JJV532W76L978391 C/W: Air Ride Suspension, Air Brakes, Sliding		65000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9174	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532X61161066 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb
9167A	2006 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W36L985340 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		GVWŘ Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9175	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532261161062 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9183	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06274G332238 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer
9177	2006 Great Dane 7411T-SSL 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06206J610192 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9185	S/N: 1GRAA06244G332231 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2004 Great Dane 7311TP-S 53 ft x 102 in T/A
9178	Asset located in: Lake Worth, TX 2006 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532468871342 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available		Van Trailer S/N: 1GRAA06274G332286 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9179	Asset located in: Humble, TX 2006 Stoughton AVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53266E813926		2004 Wabash DVLHHSA 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W74L875727 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires
	C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Humble, TX 2004 Wabash JWHDHPC 53 ft x 102 in T/A Van Trailer
9180	2005 Hyundai 53 ft Van Trailer S/N: 3H3V532C05T169027 Usage: Not Available Asset located in: Lake Worth, TX		Suspension, Aluminum Roof, Hardwo Side Skirts, Swing Door, 295/75R22.5 Usage: Not Available
9181	2005 Trailmobile 53 ft x 102 in T/A Van Trailer S/N: 2MN01JAH751003219 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9188	2004 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W74L873251 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9182	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06224G332275 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9189	2003 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W23L815529 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9190	2003 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W43L835135 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	9197	1998 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532Y4WL427465 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
9191	2003 Great Dane 7411TP-SA 53 ft x 102 in T/A	Ī	Asset located in: Lake Worth, TX
	Van Trailer S/N: 1GRAA06203G327168 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9198Z	1998 Dorsey AIDT-LS 53 ft x 102 in T/A Van Trailer S/N: 1DTV11520WA267474 C/W: Spring Suspension, Sliding Suspension, Lift Gate, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
9192	2001 Wabash Unknown 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W41L763639 C/W: Air Ride Suspension, Sliding Suspension, Hardwood Floor, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9199	1997 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532YX4VL387234 C/W: Air Ride Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9193	Asset located in: Midland, TX 2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W9YL723387 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door Usage: Not Available Asset located in: Lake Worth, TX	-9200	1997 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E953XVD412521 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX
9194	2000 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0626YB016106 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX 2000 Strick 53 ft x 102 in T/A Van Trailer	9201	1996 Lufkin TFV-IPST 53 ft x 102 in T/A Van Trailer S/N: 1L01A5322T1120913 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1S12E953XYD455230 C/W: 65000.0 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX		2016 Wabash DVCVHPC 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D9GL957237 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM-YELLOW-CORP
9196	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W6YL657722 C/W: Spring Suspension, Air Brakes, Sliding		Usage: Not Available Asset located in: Lake Worth, TX
	Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Humble, TX	9213	2016 Wabash DVCVHPC 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D1GL957202 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9219	2004 Great Dane 48 ft x 102 in T/A Van Trailer S/N: 1GRAA962X4K262283 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX 2004 Great Dane 7311TPS 40 ft x 102 in T/A Van Trailer	9227Z	2004 Great Dane 7311TP-S 40 ft x 102 in T/A Van Trailer S/N: 1GRAA80274K262745 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 22.5 mix Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP
	S/N: 1GRAA80234K262726		Asset located in: Greenwood, LA
	C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9229	1999 Fruehauf 45 ft x 102 in T/A Van Trailer S/N: 1JJV452FXXF543251 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available
9220A	2001 Great Dane 48 ft x 102 in T/A Van Trailer S/N: 1GRAA962X1K237671		Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Notes: LOCATED-IN-JUSTIN-TX-YELLOW; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Lake Worth, TX	9231	1995 Strick 48 ft x 102 in T/A Van Trailer S/N: 1S12E9489SD398829 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, hardwood floors with steel plate on top, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available
9221	2001 Great Dane 7311 T S 48 ft x 102 in T/A		Asset located in: Lake Worth, TX
	Van Trailer S/N: 1GRAA96281G318316 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9232	1995 Pines 48 ft x 102 in T/A Van Trailer S/N: 1PNV482N3SKB67178 C/W: Aluminum Frame, Spring Suspension, Air Brakes, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX
		9233	1993 Wabash 48 ft x 102 in T/A Van Trailer
9222	2000 Trailmobile 48 ft x 102 in T/A Van Trailer S/N: 1PT01JPH0Y8002343 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available		S/N: 1JJV482Y1PL197966 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: . Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	9234Z	1988 Fruehauf 48 ft x 102 in T/A Van Trailer
9223	2001 Fruehauf 40 ft T/A Van Trailer S/N: 1JJV402F81F732037 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP		S/N: 1H2V04826JH035669 C/W: Spring Suspension, Hardwood Floor, Roll- Up Door, 11R24.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in : Midland, TX
	Usage: Not Available	9235	1988 Lufkin 48 ft T/A Van Trailer
9224	Asset located in: Lake Worth, TX 2001 Fruehauf Unknown 40 ft x 102 in T/A Van Trailer S/N: 1JJV402F31F732060 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Lift Gate, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Midland, TX		S/N: 1L01A4828J1078828 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, 295/75R22.5 Tires, 65000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9236	1985 Budd 45 ft x 102 in T/A Van Trailer S/N: 1BK10W925FE217508 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9243	2014 Stoughton 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2819EB457745 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	
9237	1999 Fruehauf 40 ft x 102 in T/A Van Trailer	_	Asset located in: Lake Worth, TX	
	S/N: 1JJV402FXXF543849 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9244	2009 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281W29L286194 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	
9238	1963 Fruehauf VG-X-F2-40 40 ft x 96 in T/A	Ī	Asset located in: Lake Worth, TX	
	Van Trailer S/N: MED289407 C/W: Spring Suspension, Sliding Suspension, Hardwood Floor, Roll-Up Door, 10.00-20 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX	9245	2008 Great Dane Unknown 28 ft x 102 in S/A Van Trailer S/N: 1GRAA56178K295814 C/W: Spring Suspension, Pintle Hitch, Translucent Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP	
9239	2020 Wabash DVDBHPC 28 ft x 102 in S/A Van		Usage: Not Available Asset located in : Midland, TX	
	Trailer S/N: 1JJV281DXLL216433 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Aluminum Roof, Wood and Aluminum Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9250	2003 Great Dane 28 ft x 102 in S/A Van Trailer S/N: 1GRAA56103K246687 C/W: 34000 lb GVWR, Spring Suspension, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	
9240	2020 Wabash DVDBHPC 28 ft x 102 in S/A Van	9251	2002 Fruehauf 28 ft x 102 in S/A Van Trailer	
3240	Trailer S/N: 1JJV281D5LL216422 C/W: 40000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP	9231	S/N: 1JJV281F32F778964 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	9252	1990 Stoughton FRPD-323S 32 ft S/A	
9241	2017 Stoughton 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2812HB720243 C/W: Spring Suspension, Pintle Hitch, Hardwood Floor, Side Skirts, Roll-Up Door, R22. 5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available			Generator Trailer S/N: 1DW1A3217LS669202 C/W: Spring Suspension, Pintle Hitch, 295 /75R22.5 Tires, 68080 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Rosharon, TX	9253	1999 Fruehauf 28 ft x 102 in S/A Van Trailer	
9242	2017 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D9HL987165 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1JJV281F7XF625530 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	

	D	I	
Lot #	Details	Lot #	Details
9254	1998 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F4WF456405 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Ramp, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9261Z	1978 Fruehauf FBB X F1 27 27 ft x 96 in S/A Van Trailer S/N: MEY545851 C/W: Spring Suspension, Pintle Hitch, Roll-Up Door, 11R24.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
9255	1992 Fruehauf FPP9-NF1-28 28 ft x 102 in S/A Van Trailer S/N: IH2V02815NE029459 C/W: 50000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Aluminum w/Wood Strips Flooring, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9262Z 9263	1977 Trailmobile 27 ft x 96 in S/A Van Trailer S/N: P95650 C/W: Spring Suspension, Pintle Hitch, Hardwood Floor, Roll-Up Door, 11R24.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX		Trailer
9256	1990 Trailmobile 28 ft x 96 in S/A Van Trailer S/N: 1PT071NE8L9001242 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 3UTVS2536N8451727 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2020 Thermo King Precedent S-600 Refrigeration Unit, Serial Number 6001327716,, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: 8,204 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES
9257	1988 TRMO 28 ft x 96 in S/A Van Trailer		NOTED - PLEASE SEE THE INSPECTION
7207	S/N: 1PT071NE8J9009726		REPORT Asset located in: Humble, TX
	C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9264	2020 Wabash 53 ft x 102 in T/A Spread Axle Refrigerated Trailer S/N: 1JJV532B4LL218265 C/W: 68000 lb GVWR, Aluminum/Steel Combination Frame, Air Ride Suspension, Air
9258	1988 Trim 28 ft x 102 in S/A Van Trailer S/N: 1PT071NE1J9006327 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Aluminum Floor, Ducted Floor, Roll-Up Door, 295/75R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 1988 Trailmobile 28 ft x 102 in S/A Van Trailer		Brakes, Sliding Suspension, Fro Swing Door, 2008 Thermo King Refrigeration Unit, Aluminum W /75R22.5 Tires Usage: Not Available Notes : SELLING WITH A REPOS AFFIDAVIT AND MAY NOT BE A YOUR STATE. VERIFY WITH YO PRIOR TO BIDDING
9239	S/N: 1PT071NE4J9002630	0065	<u> </u>
	C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Aluminum Floor, Ducted Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9265	2020 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2539L2821820 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Thermo King Precedent Refrigeration Unit, Serial Number 6001278644,
9260Z	1978 Pines 31 ft x 96 in S/A Van Trailer S/N: 323CDV7748 C/W: Spring Suspension, Hardwood Floor, Roll- Up Door, 10.00-20 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Midland, TX		295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9265A	2019 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B6KL090898 C/W: Spring Suspension, Air Brakes, Side Skirts, Ducted Floor, Swing Door, Carrier X4 7500 Refrigeration Unit, Serial Number SAW91536396,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9271	2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538HU767213 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2016 Carrier 7300 X4 Refrigeration Unit, Serial Number RAV91457566,, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9267	2018 Utility 53 ft x 102 in T/A Spread Axle Refrigerated Trailer S/N: 1UYVS2536J2076912 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 11R22.5 Tires Usage: Not Available	9272	2017 Great Dane FTL-1114-31053 Refrigerated Trailer S/N: 1GRAA0627HB700016 Usage: 14,488 Hr Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; Asset located in: Humble, TX
	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9272A	2017 CIMC 53 ft x 102 in T/A Refrigerated Trailer S/N: 527SR5326HM009310 C/W: Air Ride Suspension, Sliding Suspension,
9268	2018 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XJ6106924 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, Carrier 7300 Refrigeration Unit,		Side Skirts, Ducted Floor, Swing Door, Carrier Refrigeration Unit, Aluminum Wheels, 295 /75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Serial Number SAL91508417,, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9273	2016 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538GU615320 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier 7500X4 Refrigeration Unit, Serial Number N/A, Aluminum Wheels, 295
9269	Asset located in: Lake Worth, TX 2018 Utility 53 ft x 102 in T/A Spread Axle Multi-Temp Refrigerated Trailer S/N: 1UYVS2536J2130709	_	/75R22.5 Tires Usage: 14,454 Hr Notes: . Asset located in: Lake Worth, TX
9270	C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 2017 Utility VS2RA 53 ft x 102 in T/A	9274	2016 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2532GU723903 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2016 Thermo King S600 Refrigeration Unit, Serial Number 6001214678,, Aluminum Outer Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: 14,614 Hr
	Refrigerated Trailer S/N: 1UYVS2530HU891122 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Thermo King S-600 Refrigeration Unit, Serial Number 6001220977,, Aluminum Wheels, 295/75R22.5 Tires Usage: 19,620 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9275	Asset located in: Lake Worth, TX 2016 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538GU451907 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, 2015 Thermo King 3000R Refrigeration Unit, Serial Number 6001196770,, 295/75R22.5 Tires Usage: 15,487 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9276	2015 Utility Multi Temp 53 ft T/A Refrigerated	9282	2014 Wabash RFALHSA 53 ft x 102 in T/A
9277	Trailer S/N: 1UYVS2488FU171108 C/W: 65000 lb GVWR, Aluminum Frame, Spring Suspension Usage: Not Available Asset located in: Lake Worth, TX 2015 Utility 53 ft x 102 in T/A Refrigerated		Refrigerated Trailer S/N: 1JJV532B9EL817679 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King Precedent Refrigeration Unit, Serial Number 6001144132,, 295/75R22.5 Tires, 68000 lb GVWR
	Trailer S/N: 1UYVS253XFM838425		Usage: 29,942 Hr Asset located in: Lake Worth, TX
	C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Swing Door, Carrier Refrigeration Unit, 295/75R22.5 Tires Usage: 5,800 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	9283	2014 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2532EU019102 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Swing Door, 2013 Carrier X4 7500 Refrigeration Unit, Serial Number PAP91356207,, 295/75R22.5 Tires Usage: 17,869 Hr Asset located in: Lake Worth, TX
9278	2015 Great Dane 53 ft Refrigerated Trailer S/N: 1GRAA0625FE701757	9284	2014 Utility 53 ft Refrigerated Trailer
	Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1UYVS2533EM974720 C/W: Thermo King Refrigeration Unit Usage: Not Available
9279	2015 Great Dane ETL-1114-11053 53 ft x 102		Asset located in: Lake Worth, TX
	in T/A Refrigerated Trailer S/N: 1GRAA0624FB702447 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier Vector 6500 Refrigeration	9285	2013 Utility 48 ft Refrigerated Trailer S/N: 1UYVS2481DM771708 Usage: Not Available Asset located in: Lake Worth, TX
	Unit, Serial Number NAN9127382,, 295/75R22. 5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	9286 LEASE SEE 02 in T/A g Suspension, Carrier X2 al Number	2013 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B1DL763731 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing
	THE INSPECTION REPORT Asset located in: Humble, TX		
9280	2014 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B0EL788928		Door, Thermo King SB-230 Refrigeration Unit, 295/75R22.5 Tires Usage: 15,345 Hr Asset located in : Lake Worth, TX
	C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2013 Carrier X2 2500APX Refrigeration Unit, Serial Number PAM91348526,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Refrigerated Trailer S/N: 1JJV532B2DL763740 C/W: 68000 lb GVWR, Air Ride Su Brakes, Sliding Suspension, Side Floor, Swing Door, Thermo King S
9281	2014 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer		Usage: 12,753 Hr Asset located in: Lake Worth, TX
	S/N: 1JJV532BXEL817674 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Ducted Floor, Swing Door, Thermo King Refrigeration Unit, Serial Number 6001144127,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 9,279 Hr Asset located in: Lake Worth, TX	9288	2013 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C3DT256001 Usage: 17,316 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9289	2013 Hyundai 53 ft x 102 in T/A Refrigerated Trailer	9295	2012 Wabash 53 ft x 102 in T/A Refrigerated Trailer
	S/N: 3H3V532C8DT512004 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001128459,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 20,603 Hr		S/N: 1JJV532BXCL686629 C/W: Spring Suspension, Air Brakes, Ducted Floor, Swing Door, Carrier 2100A Refrigeration Unit, 295/75R22.5 Tires, 68000 lb GVWR Usage: 16,897 Hr
			Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9296	2012 Wabash RFALHSA 53 ft T/A Refrigerated
9290	2013 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C5DT512008 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King SB230 Refrigeration Unit, Serial Number		Trailer S/N: 1JJV532B3CL703187 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Swing Door, Carrier X2500 Refrigeration Unit, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	6001128461,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	9297	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer
	Asset located in: Lake Worth, TX		S/N: 1JJV532B7CL686636 C/W: Spring Suspension, Sliding Suspension,
9291	2012 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537CM264524		Side Skirts, Ducted Floor, Front/Rear Vents, Swing Door, Carrier 2100A Refrigeration Unit, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
	C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2013 Carrier 2500R		Asset located in: Lake Worth, TX
	Refrigeration Unit, Serial Number NAB91209850,, 295/75R22.5 Tires, 65000 lb GVWR Usage: 13,798 Hr Asset located in : Humble, TX	9298	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B1CL686633 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door,
9292	2012 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C4CT436005		Carrier X2500R Refrigeration Unit, 295/75R22. 5 Tires Usage: 16,418 Mi Asset located in : Lake Worth, TX
	C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Roll-Up Door, Thermo King SB230 Refrigeration Unit, Serial Number 6001103448,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9299	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV53CB1CL718268 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial Number NAN91272008,, 295/75R22.5
9293	2012 Hyundai 53 ft x 102 in T/A Refrigerated Trailer		Tires, 68000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 3H3V532C7CT436001 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001103459,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 23,320 Hr Asset located in: Lake Worth, TX	9300	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B8CL686824 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Swing Door, Carrier X2100A Refrigeration Unit, 295/75R22.5 Tires Usage: 16,925 Hr
9294	2012 Wabash 53 ft x 102 in T/A Refrigerated		Asset located in: Lake Worth, TX
	Trailer S/N: 1JJV532B7CL718324 C/W: Spring Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial Number NAM91270893,, 295/75R22.5 Tires Usage: 16,367 Hr Asset located in: Lake Worth, TX	9301	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B4CL718345 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial Number NAN91274448,, 295/75R22.5 Tires Usage: 17,075 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9302	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0622CW703603 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Side Skirts, Swing Door, Carrier 2100A Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9308	2014 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2480EU771507 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King Refrigeration Unit, Serial Number 600133514,, 11R22.5 Tires, 65000 lb GVWR Usage: 27,250 Hr Asset located in: Lake Worth, TX
9303	2011 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B7BL330878 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2010 Carrier X2 2500A Refrigeration Unit, Serial Number NAA91203262, Usage: 32,464 Hr Notes:	9309	2013 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2480DM567319 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 60011112528,, 11R22.5 Tires, 65000 lb GVWR Usage: 48,998 Hr Asset located in: Lake Worth, TX 2013 Utility VS2RA 48 ft x 102 in T/A
9304	Asset located in: Lake Worth, TX 2011 Great Dane SUP-1114-01053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0627BW702896 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier 2500R Refrigeration Unit, 295 /75R22.5 Tires, 68000 lb GVWR Usage: 20,695 Hr Asset located in: Lake Worth, TX	9310	Refrigerated Trailer S/N: 1UYVS248XDM771710 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 6001128316,, 11R22.5 Tires, 65000 lb GVWR Usage: 42,743 Hr Asset located in: Lake Worth, TX 2014 Utility 48 ft x 102 in T/A Refrigerated
9305	2010 Graet Dane SUP-1114-11053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625AQ702846 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Swing Door, Carrier X2 2100 Advance Refrigeration Unit, 295/75R22.5 Tires Usage: 27,108 Hr Asset located in: Lake Worth, TX	9311	Trailer S/N: 1UYVS2483EU771503 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001133500,, 11R22.5 Tires, 65000 lb GVWR Usage: 31,576 Hr Asset located in: Lake Worth, TX
9306	2006 Wabash 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532W86L980540 C/W: Spring Suspension, Sliding Suspension, Swing Door, Carrier Refrigeration Unit, 295 /75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2015 Great Dane ECM-113 48 ft x 102 in T/A	9312	2012 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2483CU463504 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2011 Thermo King Smart Reefer 2 Refrigeration Unit, 11R22.5 Tires, 65000 lb GVWR Usage: 48,492 Hr Asset located in: Lake Worth, TX
	Refrigerated Trailer S/N: 1GRAA9622FE702031 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Whisper Refrigeration Unit, Serial Number 6001178338,, 295/75R22.5 Tires Usage: 27,626 Hr Asset located in: Lake Worth, TX	9313	2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2489CU248709 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2013 Thermo King Refrigeration Unit, Serial Number 6001133500,, 295/75R22.5 Tires, 65000 lb GVWR Usage: 31,576 Hr Asset located in: Lake Worth, TX

1 0+ 4	Detaile	1 04 #	Dataila
Lot #	Details	Lot #	Details
9314	2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2488CU463501 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001103810,, 11R22.5 Tires, 65000 lb GVWR Usage: 49,586 Hr Asset located in: Lake Worth, TX	9321	1992 TRMB 28 ft x 96 in S/A Refrigerated Trailer S/N: 1PT071NE4N9012595 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Thermo King SII-50 MAX Refrigeration Unit, Serial Number 0322628122, Usage: Not Available Asset located in: Lake Worth, TX
9315	2012 Utility 48 ft x 102 in T/A Refrigerated	9322	2019 Holcombe HM12H 12 cft Portable Concrete Mixer
	Trailer S/N: 1UYVS248XCU463502 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2011		S/N: 16MBB3132KF078754 C/W: Deutz Diesel Engine Usage: Not Available Asset located in : Lake Worth, TX
	Thermo King Refrigeration Unit, Serial Number 6001103816,, 65000 lb GVWR Usage: 50,063 Hr Asset located in: Lake Worth, TX	9323	2024 44 ft x 12 ft 1 in Portable Tri/A Mobile Office S/N: 102410 C/W: (2) Offices, (1) Bathrooms, Air
9316	2001 Great Dane Refrigerated Trailer S/N: 1GRAA06221W001925 Usage: Not Available		Conditioner, Ball Hitch, Spring Suspension, 8- 14.5 Tires Usage: Not Available Asset located in : Lake Worth, TX
0017	Asset located in: Lake Worth, TX	9324	2022 20 ft x 8 ft Mobile Office
9317	1996 Trailmobile 28 ft x 96 in S/A Refrigerated Trailer S/N: 1PT071NE2T9002371 C/W: Spring Suspension, Air Brakes, Ducted Floor, Roll-Up Door, Thermo King Sentry II Max Refrigeration Unit, Serial Number 1145AL6026,, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	J921	S/N: TJCC22122989 C/W: 12000 BTU Heat and AC Split System, Indoor Breaker Box, R-13 Insulation, 2 windows, Metal Front Door, Security Bars, Security Locks on all Doors, LED Lighting, Wood Trim, Laminated Flooring Storage Room for High Value Tools and Equipment, Charging Dock for Power Tools, Wire Shelving in Store Room Usage: Not Available
9318	1995 Trailmobile 28 ft S/A Refrigerated Trailer S/N: 1PT071NE6S9012996		Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Roll-Up Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9325	28 ft x 8 ft Portable S/A Mobile Office S/N: Not Available C/W: (2) Offices, Spring Suspension, Sliding Suspension, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
9319	1993 Great Dane 7011Z-1 28 ft x 102 in S/A		Asset located in: Lake Worth, TX
	Refrigerated Trailer S/N: 1GRAA5614PB081703 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 0132822805,, 11R22.5 Tires, 39000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9326	28 ft x 8 ft Portable S/A Mobile Office S/N: Not Available C/W: (2) Offices, Air Conditioner, Spring Suspension, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
9320	1993 Great Dane 7011Z-1 28 ft x 102 in S/A	9327	2024 Garper GP8-24 Mobile Office
	Refrigerated Trailer S/N: 1GRAA5615PB081709 C/W: Spring Suspension, Air Brakes, Roll-Up		S/N: 3ECG24C1XRGEP0174 Usage: Not Available Asset located in: Lake Worth, TX
	Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 39000 lb GVWR	9328Z	2024 Garper GP8-24 Mobile Office
	Usage: Not Available Asset located in: Lake Worth, TX		S/N: 3ECG24C1XRGEP0175 Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details	
9329	36 ft x 12 ft 1 in Portable T/A Mobile Office S/N: 135369 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, 8-14.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9351	2023 Kerr-Bilt 40 ft Container Trailer S/N: 1J9GC402XPB253228 C/W: Aluminum Frame, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9330	2025 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR29SG000287 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9351A	2018 Benlee TASMRS26S T/A Roll-Off Trailer S/N: 1B9A12625JB180059 C/W: Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9334	2025 Atro 40 ft T/A Quantity of (4) Container Trailer S/N: 3ELA6CR21SG000297 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available	9352	2011 Dragon T/A Roll-Off Trailer S/N: 1D9SH4824BC661799 C/W: 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
9335	Asset located in: Lake Worth, TX 2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR22SG000292 C/W: Spring Suspension, 40 ft - Container Pins,	9353	2008 Dragon TCT440 T/A Roll-Off Trailer S/N: 1UNSH48288C066531 C/W: Air Ride Suspension, Aluminum Wheels, 285/75R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
9346	295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2024 Atro 53 ft T/A Container Trailer (Unused) S/N: 3ELA6CX24RG000212	9354	2000 ESPM TCT1101 T/A Roll-Off Trailer S/N: 1E9RS4823Y1229101 C/W: Air Ride Suspension, Aluminum Wheels, 285/75R24.5 Tires, 80000 lb GVWR Usage: Not Available	
	C/W: Spring Suspension, Sliding Suspension, 53 ft - Container Pins, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		S/N: 4P53D2328R1401125 C/W: 15680 lb GVWR, Spring Suspension	2024 PJ Trailers D7142 T/A Roll-Off Trailer S/N: 4P53D2328R1401125 C/W: 15680 lb GVWR, Spring Suspension,
9347	2023 Horizon 40 ft T/A Container Trailer (Unused) S/N: 3H7KC402XPR000334		Electric Brakes, Manual Roll Tarp, Aluminum Wheels, 235/80R16 Tires Usage: Not Available Asset located in : Humble, TX	
	C/W: Spring Suspension, 40 ft - Container Pins, 11R22.5 Tires, 50000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9356	2023 MaxxD RPX8316G T/A Roll-Off Trailer (Unused) S/N: 5R8GR1625PM105017 C/W: Spring Suspension, Electric Brakes, 215	
9348	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR2XPG001679 C/W: 65000.0 lb GVWR, Air Ride Suspension, 11R22.5 Tires		/75R17.5 Tires, 19200 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	9357	2023 Texas Pride RO71618KGN T/A Roll-Off Trailer S/N: 7HCGD1626PB039384	
9349	2016 Hyundai DDT 40 ft T/A Container Trailer S/N: 145C412S3GL006968 C/W: Spring Suspension, 40 ft - Container Pins, 10.00-20 Tires Usage: Not Available		C/W: 18000 lb GVWR, Spring Suspension, Electric Brakes, Electric Roll Tarp, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9350	Asset located in: Lake Worth, TX 2023 GRUPO 15 ft 8 in T/A Container Trailer S/N: 3BZPN402XPC008328 C/W: 65000 lb GVWR, Air Ride Suspension, 295 /75R22.5 Tires Usage: Not Available Asset located in: Midland, TX	9358	2016 Texas Pride Tri/A Gooseneck Roll-Off Trailer S/N: 1B973HGD9GB624110 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 7.50R16 Tires, 24000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9359	2016 Texas Pride T/A Roll-Off Trailer S/N: 1B9G2DGD1GB624162 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9367	2023 Freedom 8.5x28TA4G T/A Graco Spray Foam Trailer S/N: 5WKGE2829P1078616 C/W: 14000 lb GVWR, Torsion Axle, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9360	1996 T/A Roll-Off Trailer	0060	·
9300	S/N: 1B9B14526TB183122 C/W: Air Ride Suspension, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9368	2015 ACSI Tri/A Emergency Shower Recovery Station Trailer S/N: 1A9V6G631F1247629 C/W: Spring Suspension, Electric Brakes, 235 /80R16 Tires
9361	1987 G & H T/A Roll-Off Trailer S/N: 87080757		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Spring Suspension, 11R24.5 Tires Usage: Not Available Asset located in : Lake Worth, TX	9369	2018 ED Trailers T/A Cooling Trailer S/N: 3A9BD1829J7266191 C/W: Ball Hitch, Walking Beam Suspension,
9362	2023 Diamond Cargo T/A 20' Concession Trailer S/N: 53NBE2020P1101295 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9990 lb GVWR, Side Entry Door Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Electric Brakes, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
		9370	T/A Cooling Trailer S/N: Not Available C/W: Ball Hitch, Walking Beam Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	0074	
9364	2021 Margo Concessions Trailer S/N: 3A9M1C329MM050514 C/W: 2260 lb GVWR, Ball Hitch, Spring Suspension, 195R15C Tires, LPG Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	— 9371 —	2019 Cargo Craft T/A Splicing Trailer S/N: 4D6EB1225KC054750 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9365	2022 FUD Concessions Trailer		Asset located in: Lake Worth, TX
	S/N: 3F9F1A329NM066595 C/W: Ball Hitch, Spring Suspension, 195R15C Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9372	S/A BBQ trailer S/N: Not Available C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, Two benches with storage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9366	2020 TFT T/A Concessions Trailer	9373	2018 Wylie EXP500S Water Tank Trailer
	S/N: 3A9M1FD28LM050504 C/W: 2260 lb GVWR, Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 195R15C Tires		S/N: 63510 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9375	2016 CZ Engineering Pole Trailer S/N: 4CZPR2717G113G030 C/W: Lunette Ring Hitch, Air Ride Suspension, Electric Brakes, 2 Stanchions, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9376	76 2014 Bat 35TA Pole Trailer S/N: 1B9FB35264A439L69 C/W: 22400 lb GVWR Lunette Ring Hitch, Spring Suspension, Electric Brakes, 4 Stanchions, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9386A	2019 PJ DD202 19 ft T/A Dump Utility Trailer S/N: 4P5DD2029K1311819 C/W: Spring Suspension, Hydraulic Brakes, 97 in Deck Width, 97 in Overall Width, Steel Decking, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Asset located in: Midland, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9387	2016 Texas Made 22 ft T/A Dump Utility Trailer S/N: 59JT1DG22GD595842
9379	2024 Silverback 45CHGN3 Tri/A 3 Car Open Car Carrier Trailer S/N: 4S9GC4535RH623425 C/W: Spring Suspension, 235/85R16 Tires Usage: Not Available Asset located in: Humble, TX		C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 85 in Overall Width, Steel Decking, 215/75R17.5 Tires, 12000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
9380	2025 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2121ST012579 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9388	2024 East Texas 16 ft T/A Dump Utility Trailer S/N: 58SBD1625RE038870 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9383	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1920HA988585 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX	9389	2024 MaxxD DTX8316 16 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1620RM116972 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available
9384	2017 Demco AT7000P T/A 1 Car Open Car		Asset located in: Lake Worth, TX
	Carrier Trailer S/N: 15DPC1927HA989006 C/W: Spring Suspension, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9390	2024 STL Industrial 16 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1629RM336009 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 12800 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9385	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1927HA988910 C/W: Aluminum Frame, Ball Hitch, Surge Brakes, Soft Ties, 225/75R15 Tires, 5000 lb GVWR, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9391	2024 MaxxD D9X9616 16 ft Tri/A Dump Utility Trailer (Unused) S/N: 5R8BD1637RM116735 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 21000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2022 Big Tex 16 ft T/A Dump Utility Trailer S/N: 16V1D2122N5116206 C/W: Lunette Ring Hitch, Spring Suspension,
9386	2017 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1926HA989031 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: . Asset located in: Lake Worth, TX		C/W. Luffette King Affett, Spring Suspension, Electric Brakes, 82 in Deck Width, 98 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9393	2016 Texas Made DT71616KBP 16 ft T/A Dump Utility Trailer S/N: 59JT1DG22GD595839 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 86 in Overall Width, Steel Decking, 235/85R16 Tires, 12000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	9399	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3363S1120884 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	9400	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused)
9394	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1120875 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR		S/N: 2SFJL3360S1116825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9401	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3366S1120877
9395	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1120873 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9402	2025 Southland SL714-14K 14 ft S/A Dump Utility Trailer (Unused)
9396	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1116826 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires		S/N: 2SFJL3361S1120883 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused)
9397	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL336XS1120655 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available		S/N: 2SFJL3364S1120876 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9404	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused)
9398	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116824 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR		S/N: 2SFJL3367S1116823 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9405	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1118976 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9406	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1120405 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9412	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4364S1113436 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9407	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118932 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9413	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4362S1113435 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9408	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3360S1115257 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9414	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3367S1118981 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9409	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3366S1118924 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9415	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118980 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9410	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3364S1118923 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9416	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer S/N: 2SFKL4368S1113438 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9411	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3368S1118925 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9417	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4366S1113437 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 88 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9418	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1116854 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9424	2025 Maxey MaxxD 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1420SM117659 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9419	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116855 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9425	2024 MaxxD DTX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD142XRM116741 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9420	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3360S1116856 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available	9426	2024 ED Trailers 14 ft T/A Dump Utility Trailer S/N: 3LHBS1423R7000182 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 84 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9421	Asset located in: Lake Worth, TX 2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3365S1116853 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR	9427	2024 Maxey Maxx-D DKX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1420RM116473 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9422	Usage: Not Available Asset located in: Lake Worth, TX 2025 Industrias America 7014R 14 ft T/A	9428 2024 MaxxD D9X9614 14 ft T/A Trailer (Unused) S/N: 5R8BD1428RM116057 C/W: Ball Hitch, Spring Suspens Brakes, 96 in Deck Width, 100 in Steel Decking, 235/80R16 Tires GVWR Usage: Not Available Asset located in: Lake Worth, TX 9429 2024 MaxxD DKX8314 14 ft T/A Trailer (Unused) S/N: 5R8BD1424RM116489 C/W: Ball Hitch, Spring Suspens	
J-766	2025 Industrias America 7014R 14 ft T/A Dump Utility Trailer S/N: 3EZBTC14XSA003766 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 7000 lb GVWR		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Trailer (Unused) S/N: 5R8BD1424RM116489 C/W: Ball Hitch, Spring Suspension
9423	2025 MaxxD DTX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1421SM118478 C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum Flooring, 215/75R17.5 Tires, 17500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in : Lake Worth, TX
		9430	2023 Park Performance HD142 14 ft T/A Dump Utility Trailer S/N: 13ZHD1426P1000074 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9432	2025 MaxxD DTX8312 T/A Utility Trailer (Unused) S/N: 5R8BD1221SM118015 C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2025 Industrias America FT510 10 ft T/A Dump Utility Trailer	9437A	Maxey T/A Gooseneck 40 Ft Hydraulic Tail Trailer S/N: Not Available C/W: Spring Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 3EZBTC10XSA004056 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 59 in Deck Width, 78 in Overall Width, Steel Decking, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9438	2023 HD 30 ft T/A Tilt Deck Trailer S/N: 7LKH3AL2XPP001032 C/W: 16500 lb GVWR, Spring Suspension, Electric Brakes, Storage Compartments, Deck Over Tires, 97 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9439	2021 Delco 24 ft T/A Tilt Deck Trailer
9434	2025 Industrias America FT510 10 ft T/A Dump Utility Trailer S/N: 3EZBTC105SA004059 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 59 in Deck Width, 77 in Overall Width, Steel Decking, 235/75R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		S/N: 5WWGC2422M6016631 C/W: Torsion Axle, Electric Brakes, 24 ft Deck Tilting Length, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	PROCESS TITLE Asset located in: Lake Worth, TX	9440	Asset located in: Lake Worth, TX
9435	2023 Lamar 10 ft T/A Dump Utility Trailer S/N: 5RVDS1027PP119903 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, 65 in Overall Width, Steel Decking, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available	9440	2019 Big Tex 22 ft T/A Tilt Deck Trailer S/N: 16VEX222XK2093519 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft 9 in Deck Tilting Length, 75 in Deck Width, 215/75R17.5 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9441	9
9436	2015 Texas Bragg 5X10 Dump Utility Trailer S/N: 17XFP1010F1051441 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX 2014 Interstate 40 ft T/A Tilt Deck Trailer S/N: 1JKGTL605EM012923 C/W: Spring Suspension, Deck Over Tires, 24 ft 5 in Deck Tilting Length, 102 in Deck Width, 245 /70R17.5 Tires Usage: Not Available		S/N: 5FTCE2923H1002738 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Deck Tilting Length, 82 in Deck Width, 215/75R17.5 Tires, 19120 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		9442	2025 Double A 21 ft T/A Tilt Deck Trailer (Unused)
9437			S/N: 1UFBU2125ST012570 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9443	2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP225SA004019 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

		_	
Lot #	Details	Lot #	Details
9444	2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP223SA004021 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9450 9450A	2025 Double A 12 ft S/A Tilt Deck Trailer (Unused) S/N: 1UFBU1219ST012572 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 12 ft Deck Tilting Length, 79 in Deck Width, 225/75R15 Tires, 5200 lb GVWR, 2" Adjustable Bulldog Style Coupler, 2000# Set Back Jack, 7 Way Plug And Wiring, Sealed LED Lights, Diamond Plate Fenders, 6 Stake pockets, 2" Treated Lumber Floor, Safety
9445	2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP221SA004020 C/W: Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available		Chains, Spare Rack Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 1974 Miller 18 ft T/A Tilt Deck Trailer
9446	Asset located in: Lake Worth, TX 2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP225SA004022 C/W: Ball Hitch, Spring Suspension, Electric	Suspension, Deck Over Tires, 18 ft Dec Length, 96 in Deck Width, 8.25R15 Tire Usage: Not Available Asset located in: Lake Worth, TX 9451 2018 PJ Trailers 20 ft T/A Equipment S/N: 4P5L52025J1284500 C/W: Ball Hitch, Spring Suspension, Ele Brakes, 20 ft Main Deck, 101.5 in Usab Width, Deck Over Tires, Manual Ramps Flooring, 205/75R15 Tires, 7000 lb GV Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX 9452 2007 B.A.T. Custom Trailers 35 ft T/A Gooseneck Equipment Trailer S/N: 1B9E???267A439M49 C/W: Spring Suspension, Electric Brak Main Deck, 96 in Usable Deck Width, 1 Overall Deck Width, Deck Over Tires, W	C/W: Lunette Ring Hitch, Walking Beam Suspension, Deck Over Tires, 18 ft Deck Tilting Length, 96 in Deck Width, 8.25R15 Tires Usage: Not Available
	Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 101.5 in Usable Deck Width, Deck Over Tires, Manual Ramps, Wood
9447	2023 Big Tex 20 ft T/A Tilt Deck Trailer S/N: 16V1C252XP2271331 C/W: Ball Hitch, Spring Suspension, 16 ft Deck Tilting Length, 72 in Deck Width, 235/80R16 Tires Usage: Not Available		Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		S/N: 1B9E???267A439M49 C/W: Spring Suspension, Electric Brakes, 35 ft
9448	2015 Butler 20 ft T/A Tilt Deck Trailer S/N: 1BUD18202F1007915 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 78 in Deck Width, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available		Overall Deck Width, Deck Over Tires, Wo Flooring, 215/75R17.5 Tires, EQUIPMEN FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available
9449	Asset located in: Lake Worth, TX 2015 Towmaster 16 ft T/A Tilt Deck Trailer S/N: 4KNTT162XFL160923 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Winch, 16 ft Deck Tilting Length, 82 in Deck Width, 235/85R16 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	-9453	1995 Norris 40 ft T/A Gooseneck Flatbed Trailer S/N: 1N9FS4023SC007555 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9454	2019 Interstate 50DLA 30 ft Tri/A Equipment Trailer S/N: 1JKDLA500KM016883 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 24 ft Main Deck, 6 ft 2 in Fixed Dovetail, 96 in Usable Deck Width, 101 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires, 60100 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9460	2024 RAWMAXX FDX-40-27K 40 ft T/A Gooseneck Equipment Trailer S/N: 3EVGF4027R1109090 C/W: Spring Suspension, Electric Brakes, 34 ft 6 in Main Deck, 6 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/85R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Midland, TX
9455	2001 Phelan 25TA-D 25 ton 29 ft Tri/A Equipment Trailer S/N: 40FR0303113020550 C/W: Lunette Ring Hitch, Spring Suspension, 24 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 60540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9461	2024 Horizon 40 ft T/A Gooseneck Equipment Trailer S/N: 3H7GF4022RR001350 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Asset located in: Midland, TX
9456	2008 Towmaster 25 ft T/A Equipment Trailer S/N: 4NKTF20298L163620 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 101 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235 /85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9462	2024 Big Tex 40 ft T/A Gooseneck Equipment Trailer S/N: 16V3F4821R6323173 C/W: Spring Suspension, Electric Brakes, 40 ft Main Deck, 93 in Usable Deck Width, 98 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 23900 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9457	2016 Load Trail 40 ft Tri/A Gooseneck Equipment Trailer S/N: 4ZEGC4031G1100325 C/W: Spring Suspension, Electric Brakes, 40 ft 4 in Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, 101.5 in Overall Deck Width, 0 in Widening Width, Storage Compartments, Manual Ramps, Wood Flooring, 235/80R16 Tires, 24990 lb GVWR Usage: Not Available Asset located in: Midland, TX	9463	2024 East Texas 40 ft T/A Gooseneck Equipment Trailer S/N: 58SGF4027RE040193 C/W: Spring Suspension, Electric Brakes, 34 ft 6 in Main Deck, 5 ft 6 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9458	2025 X-STAR 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1X9T3GS28SH039957 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9464	2023 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4025PM101424 C/W: Spring Suspension, Electric Brakes, 34 ft 11 in Main Deck, 5 ft 9 in Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires, 25990 lb GVWR
9459	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 5R8GF4025SM119348 C/W: Air Ride Suspension, Electric Brakes, 34 ft 11 in Main Deck, 5 ft 9 in Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires, 25990 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9465	2023 Delco 40 ft T/A Gooseneck Equipment Trailer S/N: 5WWGF4023P6029756 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
9466	2023 HD Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 7LKH3AP29PP000996 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9472	2017 Texline 35' GNI/D 35 ft T/A Gooseneck Equipment Trailer S/N: 5HNGN352XH1000107 C/W: Spring Suspension, Electric Brakes, 30 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22000 lb GVWR Usage: Not Available
9467 9467A	2023 Trailmaxx 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H4027TM000406 C/W: 12000 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Midland, TX 2022 PJ Trailers 3F492 40 ft T/A Equipment		Asset located in: Lake Worth, TX 2012 Texas Bragg 35 ft T/A Gooseneck Equipment Trailer S/N: 17XFG3528C1024464 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manua Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available
7.077	Trailer	0474	Asset located in: Lake Worth, TX
9469	S/N: 4P53F4924N1364159 C/W: 25900 lb GVWR, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Midland, TX 2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer S/N: 4ZEGH4023J1155164 C/W: Spring Suspension, Electric Brakes, 35 ft	9474	2009 Texas Bragg 35 ft T/A Gooseneck Equipment Trailer S/N: 17XFG352791093459 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 92 in Usable Deck Width, 102 in Overall Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 2025 MaxxD LDX10232 32 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 5R8GF3227SM117723 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 6 ft 1 in Fixed Dovetail, 93 in Usab Deck Width, 96 in Overall Deck Width, Deck
	Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 101 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		
9470	2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer S/N: 4ZEGH4021J1162680 C/W: Spring Suspension, Electric Brakes, 35 ft		Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		2023 Big Tex 16GN-25BK+5MR 30 ft T/A Gooseneck Equipment Trailer S/N: 16V3F3828P6255347 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable
9471	2009 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GN40229M011427 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 225/90D16 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9477	2020 Sure-Pull 30 ft T/A Gooseneck Equipment Trailer S/N: 1J9DG3024LJ143049 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 101 in Usable Deck Width, 101 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR TO REPORT	9482	2024 Golden Arm 25 ft T/A Gooseneck Equipment Trailer S/N: 7S8GF2526RM000313 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft 6 in Fixed Dovetail, 94 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX 2012 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer
	PRIOR TO BIDDING Asset located in: Lake Worth, TX		S/N: 16VGX2521C2632812
9478	2013 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer S/N: 16VGX2527D2674032 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22400 lb GVWR, EQUIPMENT-FROM-WATKINS-		C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22500 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9484	2009 Starlite 25TAGN 25 ft T/A Gooseneck Equipment Trailer S/N: 13YFS25269C113505
9479	2001 HaWN 30 ft T/A Gooseneck Equipment Trailer S/N: 1H9GN302911176001 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires		C/W: Spring Suspension, 20 ft Main Deck, 5 ft 2 Position Dovetail, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Lake Worth, TX
	Usage: Not Available Notes: SELLING WITH AN SPI (FORM VTR-270) AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9485	2023 East Texas 24 ft T/A Gooseneck Equipment Trailer S/N: 58SGM2424PE036183 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 102 in Usable Deck Width, Wood Flooring, 235/80R16 Tires
9480	2015 Kearney 28 ft Tri/A Gooseneck Equipment Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 5LCFT2830F1037125 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 4 ft Fixed Dovetail, 82 in Usable Deck Width, Hydraulic Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9486	2025 Salvation 20 ft T/A Equipment Trailer (Unused) S/N: 7GG1U2022SW023510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Main Deck, 3 ft Fixed Dovetail, 82 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 225 /75R15 Tires, 10400 lb GVWR
9481	2025 Double A 26 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1UFGN2624ST012569 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring		Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9487	2023 Maxey XX-D 26 ft T/A Equipment Trailer S/N: 5R8BC2627PM106865 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9488	2002 Parker 24 ft T/A Equipment Trailer S/N: 13ZPF242121003713 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 18 ft 10 in Main Deck, 5 ft 2 in Fixed Dovetail, 85 in Usable Deck Width, 91 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/85R16 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9494	2025 Southland LBATR7-20 20 ft Tri/A Equipment Trailer S/N: 2SFHL4464S1120265 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9489	2020 Sure-Trac 23 ft T/A Equipment Trailer (Inoperable) S/N: 5JW2U2320L3262538 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 7 ft 6 in Upper Deck, 12 ft 4 in Main Deck, 3 ft 6 in Fixed Dovetail, 79 in Usable Deck Width, 79 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available	9495	2025 Southland LBATR7-20 20 ft Tri/A Equipment Trailer S/N: 2SFHL4462S1120264 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9496	2025 Salvation Trailers 20 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 7GG3U2022SW023483 C/W: Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 82 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR
9490	2014 Kaufman 23 ft T/A Equipment Trailer S/N: 5SHFP2329EB001257 C/W: Lunette Ring Hitch, Spring Suspension,		Usage: Not Available Asset located in : Lake Worth, TX
	Electric Brakes, 18 ft Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9497	2025 X-STAR 20 ft T/A Equipment Trailer (Unused) S/N: 1X9T7GF21SH039958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 97 in Usable Deck Width, 101 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR, 2
9491	2025 Southland LBATR7-22 22 ft Tri/A Equipment Trailer (Unused) S/N: 2SFHL4463S1120662		in x 8 in Treated Lumber Floor, 7k Axles Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 2 ft Fixed Dovetail, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2025 Double A 20 ft T/A Equipment Trailer (Unused) S/N: 1UFBU2029ST012573 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 0 ft Dovetail, 83 in Usable Deck Width, 102 in Overall Deck Width,
9492	2023 Maxey T/A 40 Ft Tilt Deck Trailer S/N: 5R8BC2226PM099011 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Electric Powered Self Contained Hydraulic System, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Manual Ramps, Wood Flooring, 235/85R16 Tires, 14000 lb GVWR, 6" Channel Frame, 6" Wrap Tng, 3" Channel Cross Members, 2- 7000# Axles, 1 Brake 2-5/16 Coupler, 5' Slide in Ramps, 2' Dovetail, All LED Lighting, 10-Ply on 8 Hole Silver Mod, 12k Drop Leg Jack, Diamond Plate Fenders Usage: Not Available
9493	2022 Norstar 22 ft T/A Equipment Trailer S/N: 3EUGB2221N1011572 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Fixed Dovetail, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9499	Asset located in: Lake Worth, TX 2025 Double A 20 ft T/A Equipment Trailer (Unused) S/N: 1UFBU2026ST012580 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9500	2022 East Texas 20 ft T/A Equipment Trailer S/N: 58SBM202XNE030305 C/W: Spring Suspension, 20 ft Main Deck, 96 in Usable Deck Width, 101 in Overall Deck Width, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9506	2025 Double A 18 ft T/A Equipment Trailer (Unused) S/N: 1UFBU1822ST012574 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 77 in Usable Deck Width, 96 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires,
9501	2018 Big Tex 14ET-20BK-MR 20 ft T/A Equipment Trailer S/N: 16VEX2024J2005825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft 6 in Main Deck, 3 ft 6 in Fixed Dovetail, 84 in Usable Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available		14000 lb GVWR, HDCH, 6" Channel Frame, 6" Wrap Tng, 3" Channel Cross Members, 2-7000# Axles, 1 Brake 2-5/16 Coupler, 5' Slide in Ramps, 2' Dovetail, All LED Lighting, 10-Ply on 8 Hole Silver Mod, 12k Drop Leg Jack, Diamond Plate Fenders Usage: Not Available Asset located in: Lake Worth, TX 2005 Ditch Witch T18B 17 ft T/A Equipment
9502	Asset located in: Midland, TX 2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC331XS1121177 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR		Trailer S/N: 1DSB232N0517Z2161 C/W: 18000 lb GVWR, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 17 ft Main Deck, Manual Ramps, 215/75R17.5 Tires Usage: Not Available Notes: Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	9508	2025 Southland LBAT7-16 16 ft T/A Equipment Trailer
9503	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3318S1121176 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires,		S/N: 2SFJL336XS1116038 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	15432 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9509	2024 MaxxD H5X10216 16 ft T/A Equipment Trailer (Unused)
9504	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3313S1121179 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 5R8BC1625RM116789 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Main Deck, 2 ft 2 in Fixed Dovetail, 82 in Usable Deck Width, 97 in Overall Deck Width, Manual Ramps, Wood Flooring, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9505	2025 Double A 18 ft T/A Equipment Trailer		Asset located in: Lake Worth, TX
	(Unused) S/N: 1UFBU1827ST012571 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 77 in Usable Deck Width, 96 in Overall Deck Width, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR, 2" Bulldog Style Coupler, Brake and EBA, 5' Slide In Ramps Out Back, 2' Diamond	9510	2021 Buck Dandy 16 ft T/A Equipment Trailer S/N: 4DHCS2028MS047369 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 225/75R15 Tires, 10400 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Plate Dovetail, 2000# Set Back Jack, Safety Chains, Wiring and Flush Mount LED lights, ST205/75R15 5 on 5 silver mod, Diamond Plate Fenders, 2" Treated Lumber Floor, Stake pockets and Rub rail, Spare Rack Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9511	2013 Felling FT-10 P Equipment Trailer S/N: 5FTPH1626D1042166 Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
Trailer S/N: 5631F2024JM001703 C/W: Torsion Axle, 14 ft Main Deck, 5 Dovetail, 70 in Usable Deck Width, 97 Deck Width, Steel Decking, 225/75R1! Usage: Not Available	S/N: 5631F2024JM001703 C/W: Torsion Axle, 14 ft Main Deck, 5 ft 2 in Dovetail, 70 in Usable Deck Width, 97 in Overall Deck Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	5 ft 2 in 7 in Overall 15 Tires IN OFFICE	2021 Big Tex 10Pl-20BK 24 ft T/A Utility Trailer S/N: 16V1W242XM2070825 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, Wood Flooring Usage: Not Available Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9520	2022 Salvation Trailers 20 ft T/A Utility Trailer S/N: 7GG1U2021NW019503
9513	2017 MMDI 7 ft S/A Equipment Trailer S/N: 5631F1419HM017255 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 7 ft Main Deck, 48 in Usable Deck Width, Manual Ramps, Steel Decking, 225 /75R15 Tires		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 88 in Deck Width, Wood Flooring, 235 /80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	9521	2018 Texline 20 ft T/A Utility Trailer S/N: 7HACU2025J1000949
9514	2016 Pratt CP0510 10 ft T/A Equipment Trailer S/N: 1P9UT1722GN343532 C/W: Torsion Axle, Surge Brakes, 60 in Usable Deck Width, Deck Over Tires, Manual Ramps, Steel Decking, 205/75R15 Tires Usage: Not Available		C/W: Spring Suspension, Electric Brakes, 79 in Deck Width, 102 in Overall Width, Wood Flooring, 215/75R17.5 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9522	2018 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2021JB069894
9515	Asset located in: Lake Worth, TX 1998 Interstate 18 ft T/A Equipment Trailer S/N: 1JK0DT202WA001000 C/W: Spring Suspension, Air Brakes, 18 ft 9 in Main Deck, 5 ft Fixed Dovetail, 91 in Usable Deck Width, 96 in Overall Deck Width, Deck		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
	Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Asset located in : Lake Worth, TX		S/N: 5LCLB2023J1047150 C/W: Ball Hitch, Spring Suspension, Elec
9516	1995 Norris 25 ft T/A Gooseneck Equipment Trailer S/N: 1N9FS252XSC007758		Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available
	C/W: Spring Suspension, Electric Brakes, 20 ft		Asset located in: Lake Worth, TX
	Main Deck, 5 ft Fixed Dovetail, 91 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: Asset located in: Lake Worth, TX	9524	2018 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2029JB069898 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
9517	1998 SHIRLEY FB 12 ft T/A Utility Trailer S/N: 4XMFS1220WL000008 C/W: Ball Hitch, Spring Suspension, 77 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 10000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9525	2013 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2029DB053351 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9526	2011 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2026B1014824 C/W: Ball Hitch, Spring Suspension, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 225 /90R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9533	2004 Cortex 18 ft T/A Utility Trailer S/N: WCC108200 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
9527	2025 Double A 18 ft T/A Utility Trailer (Unused) S/N: 1UFBU1828ST012577 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Wood Flooring, 225 /75R15 Tires, 9995 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9534	2002 Diamond Pacesetter 18 ft T/A Utility Trailer S/N: 46UFU182721078242 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: Asset located in: Lake Worth, TX
9528	2014 Lamar 18 ft T/A Utility Trailer S/N: 5RVUT1823EM017580 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9535	2017 Top Hat 16 ft T/A Utility Trailer S/N: 4R7BU1625HT167477 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Wood Flooring, 205 /75R15 Tires, 6000 lb GVWR, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9529	2014 CM 18 ft T/A Tilt Deck Trailer S/N: 5VNBU1821ET121130 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9536	Asset located in: Humble, TX 2025 East Texas 14 ft T/A Trash/Restroom Utility Trailer S/N: 58SBU1821SE042305 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 102 in Overall Wid
9530	2008 Big Tex 18 ft T/A Utility Trailer S/N: 16VPX182381320591 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, 90 in Overall Width, Wood Flooring, 235/85R16 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available	9537	Wood Flooring, 225/75R15 Tires, 7000 lb GVWR, w/(2) restrooms Usage: Not Available Asset located in: Midland, TX 2025 Double A 14 ft S/A Utility Trailer (Unused) S/N: 1UFBU1418ST012575
9531	Asset located in: Lake Worth, TX 2008 Pero 18 ft T/A Utility Trailer S/N: 4PTU718248M014902 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 100 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY		Width, 102 in Overall Width, F Flooring, 205/75R15 Tires, 2 Top, 2" BD Coupler, All LED L Back Jack, Diamond Plate Fe Lumber Floor, Stake Pockets Exp Dovetail, 2' Gate Usage: Not Available
	Usage: Not Available Notes: The chassis was manufactured in 2008, but was assigned as a 2009 when VIN was issued Asset located in: Lake Worth, TX	9538	2015 Big Tex 12 ft T/A Utility Trailer S/N: 16VNX1224F2021991 C/W: Ball Hitch, Spring Suspension, 76 in Deck Width, 81 in Overall Width, Steel Decking, 205 /75R15 Tires, 5000 lb GVWR Usage: Not Available
9532	2005 Cortex 18 ft T/A Utility Trailer S/N: WCC108217 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Wood Flooring, 235 /85R16 Tires, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9539	Asset located in: Lake Worth, TX 11 ft S/A Utility Trailer S/N: Not Available C/W: Ball Hitch, Wood Flooring, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9540	2019 Pratt EZ-1980 19 ft T/A Tilt Deck Trailer S/N: 1P9UT1929KN343758 C/W: Ball Hitch, Electric Brakes, Electric Powered Self Contained Hydraulic System, 19 ft Deck Tilting Length, 69 in Deck Width, 225 /90R16 Tires, 14000 lb GVWR Usage: Not Available	9547	2015 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA21FA018786 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9548	Asset located in: Midland, TX 2025 Southland LARCT52-826V-86 26 ft T/A
9541	Asset located in: Humble, TX 2020 Pratt EZ-1480S 14 ft T/A Tilt Deck Trailer S/N: 1P9UT1425LN343409 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Electric Powered Self Contained Hydraulic System, 14 ft 10 in Deck Tilting Length, 79 in Deck Width, 235/85R16 Tires, 14000 lb GVWR Usage: Not Available		Enclosed Trailer (Unused) S/N: 2SFPL636XS1120196 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9542	Asset located in: Humble, TX 2024 STL Industrial 12 ft Hydraulic Drop Deck Ground Load Trailer (Unused) S/N: 4B9BZ1220SM336008 C/W: Ball Hitch, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9549	2025 Southland LARCT52-826V-86 25 ft T/A Enclosed Trailer S/N: 2SFPK5313S1118257 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9550	2017 Forest River 24 ft T/A Enclosed Trailer
9543	2018 Barreto 6 ft S/A Trencher Trailer S/N: 1B9UC0616DL280544 C/W: Torsion Axle, 5.30-12 Tires Usage: Not Available Asset located in: Lake Worth, TX 2018 Barreto 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0612JL280312 C/W: Aluminum Frame, Ball Hitch, 6 ft 3 in Deck Tilting Length, 45 in Deck Width, 5.30-12 Tires, 2200 lb GVWR	9551	S/N: 5NHUVHZ24HY029016 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 98 in Deck Width, 101 in Overall Width, Side Door 225/75R16 Tires, 9800 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Midland, TX
	Usage: Not Available Asset located in : Lake Worth, TX		2025 Southland LARCT52-822V-86 22 ft T/A
9545	2019 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA29KU036221 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Side Door 225 /75R15 Tires, 7000 lb GVWR, Interior Racking Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE		Enclosed Trailer S/N: 2SFPK4318S1120466 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9552	2025 Southland LARCT52-822V-86 21 ft T/A
9546	2015 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA23FA018790 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Midland, TX		Enclosed Trailer S/N: 2SFPK4310S1118274 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Ramp, Side Door Aluminum Wheels, 225 /75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9553	2025 Southland LARCT52-820F-86 20 ft T/A Enclosed Trailer S/N: 2SFPK5365S1118272 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9559	2014 Haulmark 18 ft T/A Cooling/Heating station Enclosed Trailer S/N: 575GB1826ET265922 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: 8,663 Hr Asset located in: Lake Worth, TX	
		9560	2014 Haulmark 18 ft T/A Cooling/Heating	
9554			station Enclosed Trailer S/N: 575GB1828ET265923 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/85R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	GVWR Usage: Not Available Asset located in : Lake Worth, TX	9561	2018 Lark 17 ft T/A Enclosed Trailer S/N: 571BE1626JM030477 C/W: Ball Hitch, Spring Suspension, 80 in Deck	
9555	2017 Cargo Craft Expedition 20 ft T/A Enclosed Trailer S/N: 4D6EB2021HC046825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 102 in Overall Width, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY	9562	205/75R15 Tires Usage: Not Available	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH331XS1120960	
9556	2025 Southland LCHT35-718V-86 18 ft T/A Enclosed Trailer S/N: 2SFFL4367S1120950 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7716 lb GVWR		Side Door 205/75R15 Tires, 7716 lb (Usage: Not Available Notes: TEXAS BUYERS MUST STOP I TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	Brakes, 79 in Deck Width, 84 in Overall Width, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3363S1118428 C/W: Ball Hitch, Spring Suspension, Electric	
9557	2014 Haulmark 18 ft T/A Enclosed Trailer S/N: 575GB1821ET265892 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Brakes, 81 in Deck Width, 96 Ramp, Side Door 205/75R15 GVWR Usage: Not Available Notes: TEXAS BUYERS MUS TO SIGN REQUIRED DOCUM PROCESS TITLE	Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9558	2014 Haulmark 18 ft T/A Enclosed Trailer S/N: 575GB1823ET265909 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9564	2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3365S1118429 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9565	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL336XS1120371 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11709 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9570	2020 Carry-On 7X16 16 ft T/A Enclosed Trailer S/N: 4YMBC1621LT010101 C/W: Walking Beam Suspension, Electric Brakes, 74 in Deck Width, 83 in Overall Width, 225/75R15 Tires, 9990 lb GVWR, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
9566	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused)		Asset located in: Humble, TX
	S/N: 2SFFL3365S1112775 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9571	2020 Carry-On 16 ft T/A Enclosed Trailer S/N: 4YMBC1627LT038050 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 78 in Deck Width, 86 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7000 lb GVWR, Interior Racking; EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available
9567	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer		Notes: . Asset located in: Humble, TX
	S/N: 2SFFH3313S1118418 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7815 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9572	2013 CM Trailers 16 ft T/A Enclosed Trailer S/N: 49TCB1621D1009364 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 79 in Deck Width, 80 in Overall Width, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; Asset located in: Lake Worth, TX
9568	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer S/N: 2SFFL4368S1120956 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9573	2013 Lark United 7X16 16 ft T/A Enclosed Trailer S/N: 5RTBE1628DD034600 C/W: Walking Beam Suspension, 78 in Deck Width, 80 in Overall Width, Side Door 205 /75R15 Tires, 7000 lb GVWR, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
9569 20 Ti S, C, Si 84 U. N Ti	2022 Rock Solid Cargo 16 ft T/A Enclosed Trailer S/N: 7H2BE1626ND044095 C/W: 7000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 84 in Overall Width, Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9574	2013 Contract 16 ft T/A Enclosed Trailer S/N: 49TCB1624D1009164 C/W: Ball Hitch, Torsion Axle, 78 in Deck Width, 98 in Overall Width, 235/80R16 Tires, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Midland, TX
		9575	2017 Doolittle 16 ft T/A Enclosed Trailer S/N: 1DGCS1422HM022245 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 84 in Overall Width, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9576	2025 Southland LCHT35-716V-86 15 ft T/A Enclosed Trailer S/N: 2SFFH3311S1120958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7815 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9581	2016 Lark United MFG VT6X14SA 14 ft S/A Enclosed Trailer S/N: 571BE1417GM017644 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, Ramp, 225/75R15 Tires, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
9577		9582	2009 Mongoose 15 ft T/A Enclosed Trailer S/N: 5SMFL142091005960 C/W: Spring Suspension, Electric Brakes, 80 in Deck Width, 225/75R15 Tires, 10000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
9578	PROCESS TITLE Asset located in: Lake Worth, TX 2018 Interstate 14.5 ft T/A Enclosed Trailer S/N: 1UK500F28J1095011 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY	9583	2015 Wells Cargo TW101 10 ft S/A Enclosed Trailer S/N: 575200D14FT278094 C/W: Ball Hitch, Spring Suspension, 72 in Deck Width, 205/75R15 Tires, Honda EM6000SX Generator; EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX
9579	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2017 Doolittle 15 ft T/A Enclosed Trailer S/N: 1DGCS1428HM021181 C/W: Lunette Ring Hitch, Spring Suspension, 80 in Deck Width, 84 in Overall Width, 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available	9585	2017 Lark 12 ft T/A Enclosed Trailer S/N: 571BE1226HM022380 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 92 in Deck Width, 101 in Overall Width, Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9580	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9586	2017 Lark VT712TA 13 ft T/A Enclosed Trailer S/N: 5RTBE122XHD058103 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	9587	2015 Arising 7X12VTDW 12 ft T/A Enclosed Trailer S/N: 5YCBE1228FH021263 C/W: Walking Beam Suspension, Electric Brakes, 76 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9588 9589	2006 Forest River 12 ft T/A Enclosed Trailer S/N: 5NHUTB2236W053121 C/W: Spring Suspension, Electric Brakes, Side Door 205/75R14 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 12 ft T/A Enclosed Trailer	9595	2016 Heartland Cyclone 44 ft Tri/A Toy Hauler Travel Trailer S/N: 5SFCG4436GE301886 C/W: Sleeps 2 People, 2 Slide Outs, Power Leveling Jacks, Cummins 5.5 kW Generator, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN	
	S/N: Not Available C/W: Ball Hitch, Spring Suspension, Electric Brakes, 69 in Deck Width, 71 in Overall Width, Side Door 205/75R15 Tires, 11000 lb GVWR Usage: Not Available	9595A	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 2015 Gateway 3900SE 42 ft T/A Travel Trailer	
9590	Asset located in: Lake Worth, TX 2019 Lark VT612TA 12 ft T/A Enclosed Trailer S/N: 571BE1228KM031668 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, 425 gal Poly Tank Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9596 9597 9597A	S/N: 5SFSG4129FE293059 C/W: Sleeps 8 People, 3 Slide Outs, Exterior Entertainment, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 7.5/16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
9591	2012 Atlas AU712SA 12 ft S/A Enclosed Trailer S/N: 5HCKU1219CE025510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width, Ramp, Side Door 205/75R15 Tires, 3500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2015 Kuntry Kustom 34 ft Tri/A Travel Trailer S/N: 1K9BU3933F1236485 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9592	2012 Arising 8 ft S/A Enclosed Trailer S/N: 5YCBE0817CH005074 C/W: Spring Suspension, 205/75R15 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		2014 Rich Kuntry Kustom 34 ft Tri/A Travel Trailer S/N: 1K9BU3934E1236252 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9593	1995 Wells Cargo CVC4025 40 ft T/A Gooseneck Enclosed Trailer S/N: 1WC200R24S2028367 C/W: Spring Suspension, Electric Brakes, 95 in Deck Width, 97 in Overall Width, Side Door 225 /90/16 Tires, 12000 lb GVWR, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 4YDF35326FA74053 C/W: Sleeps 8 People, Power Awning, Roof Mour Receiver, 5th Wheel, Sprin Electric Brakes, 235/80R1 Usage: Not Available Notes: TEXAS BUYERS MI	S/N: 4YDF35326FA740535 C/W: Sleeps 8 People, Power Leveling Jacks, Power Awning, Roof Mounted Satellite Receiver, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9594	2000 Wells Cargo T/A 12 ft Fiber Optic Trailer S/N: 1WC200E27Y1093265 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 225/75R15 Tires, Predator 9000 Watt Generator, Roof Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9598	2012 Keystone Fuzion 37 ft Tri/A Toy Hauler Travel Trailer S/N: 4YDF37527CF811331 C/W: 7000 lb GVWR, 2 Slide Outs, 5th Wheel, Spring Suspension, Electric Brakes, 235/80/16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9600	2021 Forest River Alpha Wolf 29 ft T/A Travel Trailer S/N: 5ZT2CKUB5M2001919 C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9598A 9598B	2012 Keystone Alpine 34 ft T/A Travel Trailer S/N: 4YDF34927CE780709 C/W: Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires, 5 Slide Outs Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2011 Forest River Wildcat 34 ft T/A Travel	9600A	2015 Keystone 30 ft T/A Travel Trailer S/N: 4YDT30R26F7207465 C/W: 2 Slide Outs, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH
	Trailer	YOUR LOCAL DMV PRIOR TO Asset located in: Lake Worth, 9600B 2014 Forest River 31 ft T/A Tr. S/N: 4X4TRLG28E1853494 C/W: Air Conditioner, 2 Slide O Kitchen, Power Leveling Jacks Bumper Pull, Torsion Axle Sus Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST TO SIGN REQUIRED DOCUMEN PROCESS TITLE. SELLING WIT REPOSESSION AFFIDAVIT AN ACCEPTED IN YOUR STATE. V YOUR LOCAL DMV PRIOR TO Asset located in: Lake Worth, 9600C 2014 Forest River Lacrosse 33 Trailer S/N: 5ZT2LCYB9EB004792 C/W: Air Conditioner, 3 Slide O Leveling Jacks, Power Awning Spring Suspension, Electric Br Tires Usage: Not Available Notes: TEXAS BUYERS MUST TO SIGN REQUIRED DOCUMEN PROCESS TITLE. SELLING WIT REPOSESSION AFFIDAVIT AN ACCEPTED IN YOUR STATE. V YOUR LOCAL DMV PRIOR TO	YOUR LOCAL DMV PRIOR TO BIDDING
	S/N: 4X4FWCK28BV024670 C/W: 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		2014 Forest River 31 ft T/A Travel Trailer S/N: 4X4TRLG28E1853494 C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Leveling Jacks, Power Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires
9599	2008 McKenzie Starwood LX 33 ft T/A Travel Trailer		ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	S/N: 4K03B1M278E176497 C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX		S/N: 5ZT2LCYB9EB004792 C/W: Air Conditioner, 3 Slide Outs, Power Leveling Jacks, Power Awning, Bumper Pull,
9599A	2016 Keystone Montana Travel Trailer S/N: 4YDF3102XGA740309 Usage: Not Available Asset located in: Lake Worth, TX		
9599B	2011 Heartland Sundance 26 ft T/A Travel Trailer S/N: 5SFSG3427BE213855 C/W: 3 Slide Outs, Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235 /80 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9601	2015 Gulf Stream Trailmaster 27 ft T/A Travel Trailer S/N: 1NL1GTM21F1117001 C/W: 7860 lb GVWR, Single Slide Out, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9603	1993 Case 580SK 4x2 Backhoe Loader (Inoperable) S/N: JJG0172373 C/W: Enclosed Cab, Air Conditioner, 82 in Loader Bucket Usage: 6,290 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9601A	2012 Forest River 3006W 30 ft T/A Travel Trailer S/N: 4X4TRLF22C1843526 C/W: Sleeps 10 People, Single Slide Out, Power Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9604A 9605	2016 John Deere 8245R 4WD Tractor (Inoperable) S/N: 1RW8245RCGP110724 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 4 Reverse, PowerShift, Forward/ Reverse Shuttle, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, HID Lights, 4 Rear Remotes, Exterior 3-Point Hitch Controls, 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar,
9601B	2016 Keystone Outback 32 ft T/A Travel Trailer S/N: 4YDT32429GB451256 C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: THIS UNIT IT BEING SOLD WITH A BONDED TITLE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		420/85R34 Front Tires, 480/80R50 Rear Tires Usage: Not Available Notes: ENGINE RUNS BUT SMOKES, HYDRAULICS AND DRIVETRAIN ARE OPERATIONAL; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX LS XU6168 4WD Utility Tractor (Inoperable) S/N: 2273000807 C/W: Enclosed Cab, Air Conditioner, 16 Forward 16 Reverse, Power Shuttle, Forward/ Reverse Shuttle, Tier 4, 68 hp Engine, Loader,
9601C	2016 Shadow Cruiser 28 ft T/A Travel Trailer S/N: 5RXTD2821G1033089 C/W: Sleeps 2 People, Single Slide Out, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		Quick Coupler, Auxiliary Hydraulics, 72 in Scraper Blade, 9.5x24 Front Tires, 16.9-28 Rear Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Ford 2WD Tractor (Inoperable) S/N: Not Available C/W: 4 Forward 1 Reverse, Manual Transmission, 540 PTO, 4.00-19 Front Tires, 11.2x28 Rear Tires
9602	2009 Case 590 Super M 4x2 Backhoe Loader (Inoperable) S/N: N9C529033 C/W: Enclosed Cab, Air Conditioner, 94 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Usage: 126 Hr Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9606	(Inoperable) S/N: 40219921 C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive, Requires Diesel Exhaust Fluid, 580/70R26 Front Tires, 16.5-16.1 Rear Tires, Header S/N - 43062222, 2022 MacDon R216 16 ft Rotary Header Usage: Not Available	9610	2000 Terex S17E Motor Scraper (Inoperable) S/N: S8031011 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	Notes: UNIT HAS A BAD ENGINE, DRIVETRAIN, HYDRAULIC SYSTEM AND HEADER ARE COMPLETE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9611	2017 John Deere 9570R Scraper Special Articulated Tractor (Inoperable) S/N: 1RW9570RLGE054151 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, 2016 US EPA Label, Requires	
9606A	2017 Cat 966M Wheel Loader (Inoperable) S/N: CAT0966MJKJP02417 C/W: Enclosed Cab, Air Ride Seat, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, Log Grapple, 26.5-25 Tires Usage: 6,530 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Diesel Exhaust Fluid, Front Weights, 4 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Front Wheel Weights Usage: Not Available Notes: ENGINE RUNS, DRIVETRAIN IS COMPLETE BUT HAS A BAD REAR END, HYDRAULICS ARE COMPLETE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	Asset located in: Humble, TX	9612	2016 Cat D6K2 LGP Crawler Dozer (Inoperable)	
9607	2013 Volvo L70G Wheel Loader (Inoperable) S/N: VCE0L70GK00002765 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires Usage: 24,316 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS ITEM. BUYER WILL NEED TO SET UP OUTSIDE ASSISTANCE. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		S/N: CAT00D6KVJTR00286 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 144 in Wide PAT Blade, 36 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 10,000 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
9608	1999 Volvo L90C Wheel Loader (Inoperable)	Ī	Asset located in: Humble, TX	
	S/N: L90CV63189 C/W: Enclosed Cab, Hydraulic Coupler, 20.5 R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9612A	(Inoperable) S/N: 1T0750JXKBD203024 C/W: Enclosed Cab, Air Conditioner 152 in Wide PAT Blade, 33.5 in Sing Track Shoes Usage: 8,566 Hr Notes: INOPERABLE ITEM MUST BI FROM YARD BY JANUARY 10TH AN	S/N: 1T0750JXKBD203024 C/W: Enclosed Cab, Air Conditioner, Sweeps, 152 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 8,566 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9609	2001 Terex S17E Motor Scraper (Inoperable)		BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL ; UNIT RUNS, DRIVES HYDRAULICS	
	S/N: S8311020 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lake Worth, TX		ARE OPERATIONAL - WILL NOT THROTTLE UP Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details		
9613	016 Cat D5K2 LGP Crawler Dozer (Inoperable) (A) CAT00D5KCKY202614 (A) Enclosed Cab, Air Conditioner, 2016 US PA Label, Requires Diesel Exhaust Fluid, (weeps, 124 in Wide PAT Blade, 26 in Single (irouser Track Shoes, SystemOne (Indercarriage, EQUIPMENT-FROM-PULICE- (INDERCARROW) (Indercarriage) (Inderca	9616A	2011 Cat CD54 Double Drum Roller (Inoperable) S/N: CAT0CD54HJ5R00162 C/W: 67 in Compaction Width Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		
	THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9617	2006 Ingersoll Rand DD-34HF Double Drum Roller (Inoperable) S/N: 188489 C/W: Open Operator Station, 2005 US EPA Label, Kubota V2203-M-ES 4 Cylinder 36.4 kW		
9613A	2001 Cat 963C LGP Crawler Loader (Inoperable) S/N: 2DS01267 C/W: Open Operator Station, 86 in Bucket, 21 in Double Grouser Track Shoes, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY			2.2 L Diesel Engine, 54 in Compaction Width, Water System Usage: 5,526 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		2011 Lay-Mor 8HC Self-Propelled Broom (Inoperable) S/N: 33225 C/W: Open Operator Station, 7 ft 9 in Broom, Water System, 2019 US EPA Label, Kubota 3 Cylinder 26 kW 1.5 L Diesel Engine		
9614			Usage: 854 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9620	1999 Broce BB250 Self-Propelled Broom (Inoperable) S/N: 981111 C/W: Open Operator Station, 6 ft 3 in Broom,		
9615	1998 Cat CP433C Padfoot Drum Compactor (Inoperable) S/N: 2JM00524 C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, 66 in Drum, Leveling Blade Usage: 5,226 Hr Notes: INOPERABLE ITEM MUST BE REMOVED		N N F E F	Usage: 542 Hr Notes: INOPERABLE ITEM MUST BE FROM YARD BY JANUARY 10TH AN	Water System, 4 Cylinder Diesel Engine Usage: 542 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		2013 Komatsu PC360LC-10 Tracked Excavator (Inoperable) S/N: KMTPC242A54A32676		
9616	2017 Bomag BW 124 Smooth Drum Compactor (Inoperable) S/N: 861832121160 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX		C/W: Air Conditioner, Rear View Camera, US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 56 in Digging Bucket, Thumb Bracket Usage: 13,098 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9622	(Inoperable) S/N: CAT0330FCMBX00322 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 10,017 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM	9623C	2016 John Deere 35G Mini Excavator (Inoperable) S/N: 1FF035GXTGK276310 C/W: Swing Boom, 4 ft 4 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9624	2006 Komatsu PC27MR-2 Mini Excavator (Inoperable) S/N: KMTPC120A05016215
9623	2020 Cat 320 Tracked Excavator (Inoperable) S/N: CAT00320KHEX20346 C/W: Air Conditioner, Straight Travel Pedal, Cab Screens, Rear & Side View Cameras, 2019 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, Manual Quick Coupler, Thumb Bracket Usage: 4,956 Hr		C/W: Control Pattern Changer, Swing Boom, 3 ft 8 in Stick, Backfill Blade, 12 in Rubber Tracks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9624A	2018 Wacker Neuson EZ53 Mini Excavator (Inoperable) S/N: WNCE0510TPAL00649 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing,
9623A			Backfill Blade, 16 in Rubber Tracks, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,989 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	EQUIPMENT-FROM-À-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9625	2014 Terex TC16 Mini Excavator (Inoperable) S/N: TC00163259 C/W: Swing Boom, 3 ft 8 in Stick, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 8 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9623B	·		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 4,351 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9627	1998 Vermeer 8550A 4x4 Trencher (Inoperable) S/N: 1VRT112P2W1000109 C/W: Canopy, Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Rock Trencher Chain, Straight Blade Usage: 1,406 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details
9628	1998 Vermeer V4150A 4x4 Trencher (Inoperable) S/N: 1VRP082R0W1000592 C/W: Deutz 4 Cylinder Diesel Engine, 8.5 in Wide x 7 ft Long Rock Trencher Chain, Crumbling Shoe, 8600 Backhoe Attachment, Angle Blade, Side Shift Usage: 349 Hr	9631	2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DLDTB05827 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9628A	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2016 LOKT T/A Vacuum Excavation Unit	9632	2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DPDTB05818 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
	(Inoperable) S/N: 4M9E2TG22GE015001		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Front Hose Reel, 320 L Fresh Water Tank, Drop Down Tailgate, Manual Tailgate Locks, 3.5 in Suction Hose, Engine Driven Pump, 235/80R16 Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	9632A	2018 Cat 226D Skid Steer Loader (Inoperable) S/N: CAT0226DJHRD03498 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket Usage: 1,238 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	REMOVAL	9634 9634A	2017 Cat 299D2 Compact Track Loader
9629	Asset located in: Lake Worth, TX 2011 Vermeer LP555DT T/A Vacuum Excavation Unit (Inoperable) S/N: 5HZBF1624BLHB1501 C/W: 5440 lb GVWR, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Vermeer Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Full Open Tailgate, Manual Tailgate		(Inoperable) S/N: CAT0299DHFD202254 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Locks, Annovi Reverberi Engine Driven Pump, Blower, Remote Control w/ Cord, ST235/85R16 Tires, Yanmar 3TNV88-BDSA 3 Cylinder Engine Usage: 2,108 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		2018 Cat 289D Two-Speed Compact Track Loader (Inoperable) S/N: CAT0289DJTAW08857 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Tier 4, 2017 US EPA Label, 18 in Track Belts, 9 Pin Electric Kit, Manual Coupler, 78 in Bucket Usage: 4,582 Hr
9629A	4x4 Articulated Water Truck (Inoperable) S/N: Not Available C/W: Open Operator Station, 23.1-26 Tires		Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
	Usage: 2,976 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		2014 Cat 289D Compact Track Loader (Inoperable) S/N: CAT0289DVTAW00650 C/W: Enclosed Cab, Joystick Steering, 18 in Track Belts, Manual Coupler, 74 in Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-
9630	Weiler P355 Track Asphalt Paver (Inoperable) S/N: P355-1010 C/W: Dual Controls, 8 ft - Screed, 12 in Rubber Tracks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9635 9635A	2019 Kubota SVL95-2S Compact Track Loader S/N: KBCC0953CK1D46350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available Asset located in: Midland, TX 2020 Bobcat T590 Compact Track Loader (Inoperable)	9638	9638	2008 John Deere CT332 Compact Track Loader (Inoperable) S/N: T0332TA168479 C/W: Enclosed Cab (Door missing), 18 in Track Belts, Manual Coupler Usage: 6,793 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	S/N: ALJU32175 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket	9639	2010 Bobcat T190 Compact Track Loader (Inoperable)	
	Usage: 1,749 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		S/N: A3LN36903 C/W: Open Operator Station, 12.5 in Track Belts, Manual Coupler Usage: 5,228 Hr	
9636	REMOVAL Asset located in: Humble, TX 2018 Case TR310 Compact Track Loader		Notes: UNIT STARTS AND RUNS, PARKING BRAKE INOPERABLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S	
9000	(Inoperable)		RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
	S/N: JAFTR310AJM449342 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2018 US EPA Label, 15.5 in Track Belts, Manual Coupler, 77 in Bucket Usage: 3,405 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9640	2019 Toro 22322 Compact Track Loader (Inoperable) S/N: 405588028 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
9636A	2018 Case TR270 Compact Track Loader		Asset located in: Lake Worth, TX	
9030A	(Inoperable) S/N: NJM448663 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manual Coupler, 68 in Bucket Usage: 2,404 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9641	2015 JLG 10054 Telehandler (Inoperable) S/N: 0160070159 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	
9637	2017 John Deere 317G Compact Track Loader (Inoperable)		Asset located in: Humble, TX	
	S/N: 1T0317GJPHJ308175 C/W: Open Operator Station, Joystick Steering, 13 in Track Belts, Hydraulic Coupler, 72 in Bucket, EQUIPMENT FROM UNITED RENTALS Usage: 2,121 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9642	2013 JCB 9404 8000 lb Rough Terrain Forklift (Inoperable) S/N: JCB94004A02228045 C/W: 3 Stage Mast, 72 in Forks, 2012 US EPA Label, JCB tc-55 4 Cylinder 4.4 L Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	

1 - 1 "	D. A. II.	1 "	D. A. H.	
Lot #	Details	Lot #	Details	
9642A	1999 Mack RB688S 6x4 85 in Tree Spade Truck (Inoperable) S/N: 1M2AM08C9XM004800 C/W: Mack 6 Cylinder Diesel Engine, 1998 US EPA Label, Aluminum Front Wheels, 385 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 258 in Wheelbase Usage: 216,359 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9645	2009 Toyota 7FGAU50 7550 lb Pneumatic Tire Forklift (Inoperable) S/N: 70256 C/W: 3 Stage Mast, 219 in Max Lift Height, 84 in Lowered Mast Height, 84 in Forks, Side Shift, 2009 US EPA Label, IMPCO 6 Cylinder 4.3 L LPG Engine Usage: 6,371 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Bryan, TX	
06.15	·	9646	2010 Toyota 7FGAU50 5950 lb Pneumatic Tire	
9643	2007 Ford F-550 XL 4x2 Extended Cab Utility Truck (Inoperable) S/N: 1FDAX56P57EA34588 C/W: Ford V8 Diesel Engine, Automatic Transmission, 225/70R19.5, Spring Suspension, 166 in Wheelbase, Knapheide 9 ft Body Usage: 296,251 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Forklift (Inoperable) S/N: 70533 C/W: 3 Stage Mast, 219 in Max Lift Height, 109 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, Vortec LPG Engine Usage: 8,220 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Elmendorf, TX	
	Asset located in: Lake Worth, TX	9646A	2012 Toyota 8FGCU30 5120 lb Cushion Tire	
9644	Mitsubishi FG50K 11000 lb Pneumatic Tire Forklift (Inoperable) S/N: AF33B50068 C/W: 2 Stage Mast, 148 in Max Lift Height, Solid Pneumatic Tires, 5 Cylinder LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9646A 	F S C L F U L U N F B	Forklift (Inoperable) S/N: 17847 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, Toyota 4Y ECS 4 Cylinder 2.23 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9644A	2021 Yale GLC155VX 10000 lb Cushion Tire Forklift (Inoperable)	<u> </u>	Asset located in: Lake Worth, TX	
	S/N: F879V02835V C/W: 3 Stage Mast, 221 in Max Lift Height, 111 in Lowered Mast Height, Paper Roll Clamp, 2021 US EPA Label, PSI 6 Cylinder 4.3 L Dual Fuel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9647	1990 Cat T50D 5000 lb Cushion Tire Forklift (Inoperable) S/N: 8EB09438 C/W: 3 Stage Mast, 173 in Max Lift Height, 83 in Lowered Mast Height, 36 in Forks, Side Shift, Cat 4 Cylinder LPG Engine Usage: 20,099 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9648	2004 Hyundai HLF25-5 5000 lb Pneumatic Tire Forklift (Inoperable) S/N: FU0211429 C/W: Single Stage Mast 130 in Max Lift Height, 86 in Lowered Mast Height, 47 in Forks, 2004 US EPA Label, CARB Compliant, IMPCO 6Z9XB02.4MPN 4 Cylinder 2.4 L LPG Engine Usage: 1,363 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9652	2013 Nissan CF40LP 4000 lb Pneumatic Tire Forklift (Inoperable) S/N: CP1F2-9W1966 C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2013 US EPA Label, 4 Cylinder 2.1 L LPG Engine Usage: 10,133 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9649	2012 Cat 2EPC5000 4870 lb Electric Forklift (Inoperable) S/N: FN459381 C/W: 3 Stage Mast, 86 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 80 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9653	2000 Toyota 52-6FGCU45 8600 lb Cushion Tire Forklift (Inoperable) S/N: 62206 C/W: 3 Stage Mast, Full Free Lift, 218.5 in Max Lift Height, 106 in Lowered Mast Height, 72 in Forks, Side Shift, V6 LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9650	2012 Doosan G25P-5 4600 lb Pneumatic Tire		Asset located in: Lake Worth, TX
	Forklift (Inoperable) S/N: FGA0B133002925 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, 4 Cylinder 46.8 kW 2.4 L LPG Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9654	2011 Yale GLP040SVXNURV084 4000 lb Pneumatic Tire Forklift (Inoperable) S/N: C810V04664J C/W: 2 Stage Mast, 127.2 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, 2011 US EPA Label, 4 Cylinder 2.0 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Asset located in: Humble, TX		2014 Toyota 8FGCU20 4000 lb Cushion Tire
9651	2016 Cat GP25N 4500 lb Pneumatic Tire Forklift (Inoperable) S/N: AT35A02995 C/W: 3 Stage Mast, 188 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.5 L LPG Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 3,439 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		Forklift (Inoperable) S/N: 62727 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Load Weigh System, 2014 US EPA Label, CARB Compliant, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9655A	2012 TCM FG25T3 3700 lb Pneumatic Tire Forklift (Inoperable) S/N: 2H507316 C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, Tier 2, 2012 US EPA Label, Nissan 4 Cylinder 2.1 L Dual Fuel Engine Usage: 3,696 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9657C	2017 Toyota 8FGCU25 1700 lb Cushion Tire Forklift (Inoperable) S/N: 88346 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 95 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 7,554 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9655B	2012 Toyota 7FBEU20 3050 lb Electric Forklift (Inoperable) S/N: 7FBEU20-20440 C/W: 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, 36 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9658	Toyota Cushion Tire Forklift (Inoperable) S/N: Not Available C/W: 2 Stage Mast, 77 in Lowered Mast Height, 42 in Forks, 4 Cylinder Gasoline Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
9656	2003 Linde E30C 3060 lb Electric Forklift (Inoperable) S/N: A1X347P00155 C/W: 3 Stage Mast, 24 in Lowered Mast Height, 36 in Forks, 48 V, Battery Charger Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	-9659	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift (Inoperable) S/N: 40001322 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2014 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, LP Tank is not included Usage: 1,512 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; INOPERABLE
9657	1998 Toyota 5FBE18 2800 lb Electric Forklift (Inoperable) S/N: 24164 C/W: 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 93 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9659A	ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2000 UpRight RT27 4x4 Gasoline Scissor Lift (Inoperable) S/N: 2922 C/W: 27 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Upper Control Box, 2000 US EPA Label, Kubota 3 Cylinder 740 cc Gasoline Engine Usage: 4,028 Hr
9657A	1995 Toyota 5FBE18 Electric Forklift (Inoperable) S/N: 15611 C/W: 3 Stage Mast, Full Free Lift, 82 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

		Т	
Lot #	Details	Lot #	Details
9659B	2016 Genie GS-3232 Electric Scissor Lift (Inoperable) S/N: GS3216P-144587 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	9662	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: Tier 4, 2013 US EPA Label, Kubota V1505 16 kW 1.5 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,620 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9660	2016 Skyjack SJ3226 Electric Scissor Lift (Inoperable) S/N: 27028952 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Onboard Generator, Solid Non-Marking Tires Usage: 285 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2016 Snorkel S3219E Electric Scissor Lift (Inoperable) S/N: S3219E04001808 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box Usage: 47 Hr Notes: AERIAL UNITS REQUIRE PROPER	9663 Lind Mul (Ino S/N C/W 4 Cy Rati Usa Not FRC BE I REN Ass 9664 Lind C/W Con Cyli Lea Usa Not FRC BE I REN	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: Tier 4, 2013 US EPA Label, Kubota v1505 4 Cylinder 16 kW 1.5 L Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 4,216 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Lincoln RA-250-V1903 300 A Skid-Mounted Engine Driven Welder (Inoperable) S/N: C1080500072 C/W: Tier 4, 2008 US EPA Label, CARB Compliant, Kubota V2003-M-BG-ET02e 4 Cylinder 24.3 kW 2.0 L Diesel Engine, Welding Leads Not Included, 40 V Rated Voltage Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;		FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
0661 4	Asset located in: Lake Worth, TX	9665	1992 Onan 37DGBA 37 kW Skid-Mounted Generator Set (Inoperable)
9661A	2017 Generac MLT6SMD Light Tower (Inoperable) S/N: 7FSBL1018HB880619 C/W: 2017 US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,155 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; 3001880619; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		S/N: I910419145 C/W: Cummins 4B3.9G 4 Cylinder 66 hp 3.9 L Diesel Engine, /37 kW Rated 3 Phase Output Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9665A	2009 Drash 23 kW Mobile Generator Set (Inoperable) S/N: 610 C/W: 2009 US EPA Label, Perkins 4 Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 4,337 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9666B 9666C	2006 Ingersoll Rand G25 Mobile Generator Set (Inoperable) S/N: 4FVGCBAA06U374217 C/W: Ingersoll-Rand 3 Cylinder Diesel Engine, 480 V Rated Voltage, S/A Trailer, Lunette Ring Usage: 34,921 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2016 Multiquip DCA220SSJU4F Generator Set (Inoperable)	
9665B	Drash 20 kW Mobile Generator Set (Inoperable) S/N: 359 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V Receptacles, S/A Trailer, Lunette Ring Usage: 737 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		S/N: 5SLBG1825GL018612 C/W: 2016 US EPA Label, John Deere 6 Cylinder 6.8 L Diesel Engine, 220 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 10,985 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
9665C	2008 Drash 20 kW Mobile Generator Set (Inoperable) S/N: 346 C/W: Perkins 4 Cylinder 33 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, Sound Attenuated, S/A Trailer, Lunette Ring Usage: 265 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9667	Gardner-Denver EAUSPG Skid-Mounted Electric Air Compressor (Inoperable) S/N: FACP8X0 C/W: 3 Phase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2018 Tsurumi TPG4-4500HDX 4.5 kW Portable	
9666	Asset located in: Lake Worth, TX Cummins 682F9R7032 640 kW Skid-Mounted Generator Set (Inoperable) S/N: C9M0682005 C/W: 2008 US EPA Label, Volvo TWD1643GE 6 Cylinder 1800 kW 16.2 L Diesel Engine, 800 kVA /640 kW Rated 3 Phase Output, 440 V Rated	9668	Generator Set (Inoperable) S/N: 051272 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	
	Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Humble, TX			2019 Tsurumi TPG4-4500HDX 4.5 kW Portable Generator Set (Inoperable) S/N: 051460 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available
9666A	Redco Skid-Mounted Generator Set (Inoperable) S/N: Not Available C/W: Cummins 6 Cylinder Diesel Engine Usage: 269 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX		Notes: INOPERABLE ITEM MUST BE REMOVEI FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9670	Sullivan Palatek Skid-Mounted Electric Air Compressor (Inoperable) S/N: 11F046 C/W: 200 psi Working Pressure, 230, 75 hp Motor Usage: 18,303 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9673B	9673B 2001 Sullivan 185DPQ Mobile Air Compresso (Inoperable) S/N: 4135193 C/W: 200 psi Working Pressure, 2001 US EPA Label, John Deere 4045DP150B 4 Cylinder 4. L Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 1,078 Hr Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR	
9671	2010 MGS Trailer-Mounted Water Pump (Inoperable) S/N: 16MPF0922AD056753 C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, 2010 US EPA Label, John Deere 4 Cylinder 60 kW 4.5 L Diesel Engine, T/A Trailer, Lunette Ring, Surge Brakes Usage: 4,558 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		REMOVAL Asset located in: Lake Worth, TX 2017 Atlas Copco XAS110KD 110 cfm Mobile Air Compressor (Inoperable) S/N: YA3064283H0480254 C/W: 2017 US EPA Label, Kubota D902-EF01 3 Cylinder 0.89 L Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S	
9672	MMDI Trailer-Mounted Water Pump (Inoperable) S/N: Not Available C/W: 5 in Intake, 6 in Discharge, Centrifugal Water Pump, Kohler KD11903TCR 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9674	RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX Ingersoll Rand Electric Air Compressor (Inoperable) S/N: Not Available C/W: 3 Phase, 20 hp Motor Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
9673	2011 Magnum MAG MTP 4000D Trailer- Mounted Water Pump (Inoperable) S/N: 1105549 C/W: 4 in Intake, 4 in Discharge, Centrifugal 2013 US EPA Label, CARB Compliant, John Deere 4024TF281A 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,333 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9675	9675 Gardner-Denver WCC-1001 Vertical Compressor (Inoperable) S/N: 414039 Usage: Not Available Notes: INOPERABLE ITEM MUST BIFROM YARD BY JANUARY 10TH AN BE RELISTED; BUYER'S RESPONSIE REMOVAL Asset located in: Lake Worth, TX 9676 Gardner-Denver Air Compressor (Inc.)	S/N: 414039 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Gardner-Denver Air Compressor (Inoperable) S/N: Not Available
9673A			Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9677	Ingersoll Rand 20VX15 Air Compressor (Inoperable) S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9682	Landa PGDC5-3500 Pressure Washer (Inoperable) S/N: 11100500101088 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton 570 cc Gasoline Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9678	Pneumatic Skid Mounted Lube Pan - Fits Truck		Asset located in: Lake Worth, TX
	(Inoperable) S/N: Not Available C/W: Kohler Command Pro 14 429 cc Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9682A	2A 2022 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBVNG053697 C/W: Open Operator Station, 4 Passenger, Windshield, Electric Dump Bed, Tier 4, 2022 US EPA Label, Kubota d1105 3 Cylinder 8 kW 1.1 L Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9679	Gardner-Denver Air Compressor (Inoperable)	1	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL
	S/N: Not Available Usage: Not Available		Asset located in: Lake Worth, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9682B	2021 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBCMG044293 C/W: Canopy, 4 Passenger, Electric Dump Bed, Tier 4, 2021 US EPA Label, Kubota d1105 3 Cylinder 8 kW 1.1 L Diesel Engine Usage: 1,144 Hr
9680	Asset located in: Lake Worth, TX		
9080	Quantity of (2) Water Pump (Inoperable) S/N: Not Available C/W: Trash Pump, 1 Cylinder Gasoline Engine, (1) Tsurumi 4 In, (1) 3 In, One Pallet Usage: Not Available		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Notes : INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	0694	2017 Kubota RTV-X1140 Utility Vehicle
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL ;	9684	(Inoperable)
9680A	Asset located in: Lake Worth, TX 2019 Cub Cadet Pro Z 500 Zero-Turn Lawn Mower (Inoperable) S/N: 1C089H70016 C/W: 2019 US EPA Label, 24x12.00-14 Rear Tires, 54 in Mower Usage: 105 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		Receiver, Hydraulic Dump Be EQUIPMENT-FROM-A-PRIMO CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MI FROM YARD BY JANUARY 10 BE RELISTED; BUYER'S RESF REMOVAL
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL	06844	Asset located in: Humble, TX 2020 Club Car Carryall 17000 Utility Vehicle
9681	Asset located in: Lake Worth, TX 2016 Airrex Air Conditioner (Inoperable) S/N: 161010989L Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9684A 	2020 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD2013059325 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 758 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

			1 450 320 01 307		
Lot #	Details	Lot #	Details		
9685A	Club Car Carryall 1500 Utility Vehicle (Inoperable) S/N: 104027428 C/W: Canopy, 2 Passenger, Brush Guard, Manual Dump Bed, 2 Cylinder 1500 cc Gasoline Engine Usage: 610 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9689	9688 2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X2FD262706 C/W: Cummins ISX12 6 Cylinder 11.9 L Diese 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21970 Engine hrs, Eator Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Rid Cab, 11R22.5, Air Trac Air Ride Suspension, 206 in Wheelbase, PTO, Auto Lube Usage: 745,623 Mi Notes: INOPERABLE ITEM MUST BE REMOVI FROM YARD BY JANUARY 10TH AND CANNO		
9686	John Deere Gator XUV Utility Vehicle (Inoperable) S/N: Not Available		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		
	C/W: Canopy, 2 Passenger, Manual Dump Bed, John Deere 3 Cylinder Engine Usage: 1,574 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X0FD263191 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 7302 Engine hrs, Eaton Fuller 8LL Manual Transmission, 13200 lb		
9687			Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube Usage: 539,809 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		
9687A	Tractor (Inoperable) S/N: 1XPSD79X0GD263208		9689A 	Tractor (Inoperable) S/N: 1XPSD79X8CD1668 C/W: Cummins ISX11.9 3 Diesel 385 hp Engine, 201 Requires Diesel Exhaust F hrs, Eaton Fuller 8LL Man 12000 lb Front Axle, 4000 GVWR, Air Ride Cab, Alum 5, Air Trac Suspension, 20 Usage: 656,774 Mi Notes: INOPERABLE ITEN	Tractor (Inoperable) S/N: 1XPSD79X8CD166896 C/W: Cummins ISX11.9 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 26030 Engine hrs, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Trac Suspension, 202 in Wheelbase, PTO Usage: 656,774 Mi Notes: INOPERABLE ITEM MUST BE REMOVED
	C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab,		FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		
	Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 202 in Wheelbase, PTO	9690	2013 Kenworth T800 6x4 T/A Day Cab Truck		
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Tractor (Inoperable) S/N: 1XKDDP9X9DJ369135 C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 199 in Wheelbase, Air Sliding 5th Wheel, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED		

Lot #	Details	Lot #	Details
9691	2019 Peterbilt 567 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPCD79X0KD612896	9694	2014 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGBDV6ESFU4154
C/W: Cummins ISX12 385V 6 Cylinder 1 Diesel 385 hp Engine, 2018 US EPA Lab- Requires Diesel Exhaust Fluid, 13200 lb Axle, 40000 lb Rears, 53200 lb GVWR, A Cab, Aluminum Wheels, 11R22.5, Air Tra Ride Suspension, 202 in Wheelbase Usage: Not Available	C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 202 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED		C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-14210c 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 46000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 200 in Wheelbase, PTO, Blower
	FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED
9692	Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 6x4 T/A Day	+	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	Cab Truck Tractor (Inoperable)		Asset located in: Lake Worth, TX
	S/N: 3AKJGEBG6FDGN5797 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18055.3 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, 295 /75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 621,649 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9695	2007 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9GF47N449500 C/W: Volvo D12D365 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Manual Transmission, 275/80R22.5, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,615,127 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9693	2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJGEDV1DLBV2601 C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 195 in Wheelbase, Dual Fuel Tanks Usage: 588,339 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9696	2003 Volvo VNL 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4NC9GH93N350140 C/W: Volvo 6 Cylinder Diesel Engine, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Meritor RT-40-145 Drive Axles, 3.58:1 Axle Ratio, 50000 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX

9697 2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X1LD655901 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 23259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 5200 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 752,578 Mi

Details

Lot #

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Humble, TX

2020 Peterbilt 579 6x4 T/A Sleeper Truck 9698 Tractor (Inoperable)

S/N: 1XPBD49X6I D655909 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED: BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Humble, TX

9700 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X1GD326444 C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 245 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL:

Asset located in: Lake Worth, TX

Lot # **Details**

9701 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X2GD346556 C/W: Cummins ISX15 6 Cylinder 15.0 L 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24608.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 249 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks

Usage: 707,094 Mi

Asset located in: Lake Worth, TX

9701A 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor

S/N: 1XKYD49X5KJ310239 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Paccar Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 233 in Wheelbase, PTO, Dual Fuel Tanks

Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Midland, TX

9702 2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XKYD49X6GJ463607 C/W: Cummins ISX15 450ST2 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPÁ Label, Requires Diesel Exhaust Fluid, 23925 Engine hrs, Engine Brake, Eaton Fuller 12-Speed Automated Transmission, 12350 lb Front Axle, 36000 lb Rears, 2.64:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Flex Air Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 793,933 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9703	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKYDP9X0FJ437603 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 12000 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX	9706	2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR2MSMU7290 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9704	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKYDP9X0FJ464641 C/W: Paccar 6 Cylinder Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19664 Engine hrs, Engine Brake, Eaton Fuller FO-16E310C- LAS Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, 36 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 204 in Wheelbase, Dual Fuel Tanks Usage: 683,198 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9707	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR5LSKS3557 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 608,756 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
9705	2011 Mack CHU613 6x2 T/A Sleeper Truck Tractor (Inoperable) S/N: 1M1AN07Y2BM006847 C/W: Mack MP8 6 Cylinder Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Mack Drive Axles, 52000 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 248 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9708	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR7LSLJ3051 C/W: Detroit DD15 6 Cylinder 14.5 L 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor DA-RT-40.0-4S Drive Axles, 3.23:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 594,374 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Details Lot # **Details** Lot # 9709 2019 Freightliner Cascadia 126 6x4 T/A 9712 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR0KSKC2651 S/N: 3AKJGLDR5JSJK6667 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12-Speed Exhaust Fluid, 27034 Engine hrs, Engine Brake, Detroit DT12-1750-HD1 12-Speed Automated Automated Transmission, 13300 lb Front Axle, Transmission, 12000 lb Front Axle, 40000 lb 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.16:1 GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Sliding 5th Wheel, Headache Rack, Dual Fuel Rear Tires, Airliner Air Ride Suspension, 223 in Tanks Wheelbase, Air Sliding 5th Wheel, Headache Usage: Not Available Rack, Dual Fuel Tanks Notes: INOPERABLE ITEM MUST BE REMOVED Usage: 623,235 Mi FROM THE YARD BY JANUARY 10TH AND Notes: INOPERABLE ITEM MUST BE REMOVED CANNOT BE RELISTED FROM YARD BY JANUARY 10TH AND CANNOT Asset located in: Lake Worth, TX BE RELISTED; BUYER'S RESPONSIBILITY FOR 9713 2017 Freightliner Cascadia 125 6x4 T/A REMOVAL; Sleeper Truck Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 3AKJGLDR9HSJC5723 9710 2018 Freightliner Cascadia 126 6x4 T/A C/W: Detroit DD15 14.8 L Engine, Requires Sleeper Truck Tractor (Inoperable) Diesel Exhaust Fluid, Engine Brake, Eaton Fuller S/N: 3AKJHHDR3JSJW8538 10-Speed Manual Transmission, Differential C/W: 6 Cylinder Diesel Engine, Detroit 12-Speed Lock, 13300 lb Front Axle, 40000 lb Rears, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5 Front Tires, 425/65R22.5 Super 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 295/75R22.5, Singles Rear Tires, Airliner Air Ride Suspension, Airliner Air Ride Suspension, Air Sliding 5th 234 in Wheelbase, Air Sliding 5th Wheel, Dual Wheel **Fuel Tanks** Usage: Not Available Usage: Not Available Notes: SELLING WITH A REPOSESSION Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY PRIOR TO BIDDING; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH 10TH AND CANNOT BE RELISTED AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Asset located in: Midland, TX 9711 2018 Freightliner Cascadia 125 6x4 T/A 9714 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR0JSJR7937 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel S/N: 1FUJGLD5XGLGU2219 Exhaust Fluid, Retarder, Detroit DT12-OA-1650 Exhaust Fluid, 24994 Engine hrs, Engine Brake, 12-Speed Automated Transmission, 12350 lb Eaton Fuller FRW-15210B 10-Speed Manual Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in High Rise

Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR

Asset located in: Humble, TX

C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, MIXED, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 730,665 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

9715 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

Details

Lot #

S/N: 3AKJGLDV4GSHD4846 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: Not Available

Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL:

Asset located in: Lake Worth, TX

9716 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 3AKJGLD5XGSHJ8963 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND

CANNOT BE RELISTED

Asset located in: Humble, TX

Usage: 696,122 Mi

9716A 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 3AKJGLDR8GSGV0892 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 21275 Engine hrs, Engine Brake, Detroit DT12-OH-1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 873,267 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR

REMOVAL

Asset located in: Lake Worth, TX

Lot # Details

9719 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 3AKJGLDR4ESFD3920 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10571 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,029,912 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Lake Worth, TX

9720 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1FUJGLD61ELFM1902 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 244 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Asset located in: Midland, TX

9721 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1FUJGLBG8CSBM1768 C/W: Cummins ISX 6 Cylinder 450 hp Engine, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DS404 Drive Axles, 3.55:1 Axle Ratio, 53200 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel

Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Details Lot # **Details** Lot # 9722 2018 Volvo VNL 6x4 T/A Sleeper Truck Tractor 9725 2019 International LT625 6x4 T/A Sleeper (Inoperable) Truck Tractor (Inoperable) S/N: 4V4NC9EH1JN961795 S/N: 3HSDZAPR7KN110756 C/W: Cummins X15 6 Cylinder 15 L 450 hp C/W: Volvo D13M455 6 Cylinder 12.8 L 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Drive Axles, 2.47:1 Axle Ratio, 50350.0 lb Cab, 72 in High Rise Sleeper Cab, Bunk Beds, GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, /80R22.5, Air Ride Suspension, 224 in Air Sliding 5th Wheel, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Usage: 1,015,854 Mi FROM THE YARD BY JANUARY 10TH AND Notes: INOPERABLE ITEM MUST BE REMOVED CANNOT BE RELISTED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Asset located in: Lake Worth, TX RFMOVAL 9726 2019 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 3HSDZAPR0KN110761 9723 2017 Volvo VNL670 6x4 T/A Sleeper Truck C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Tractor (Inoperable) S/N: 4V4NC9THXHN983209 Exhaust Fluid, Engine Brake, Automatic C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 10-Speed Manual Transmission, 12350 lb Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Usage: Not Available Beds, 11R22.5, Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND **CANNOT BE RELISTED** Usage: Not Available Asset located in: Lake Worth, TX Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT 9727 2019 International LT625 6x4 T/A Sleeper BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE Truck Tractor (Inoperable) S/N: 3HSDZAPR5KN098185 SEE THE INSPECTION REPORT C/W: Cummins X15 6 Cylinder 15 L 450 hp Asset located in: Humble, TX Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic 2016 Volvo VNL 780 6x2 T/A Sleeper Truck 9724 Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Tractor (Inoperable) S/N: 4V4N99EH7GN950842 Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks C/W: Volvo D13 6 Cylinder 12.8 L Diesel 425 hp Engine, Requires Diésel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, Usage: Not Available 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, **Notes**: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Volvo CANNOT BE RELISTED Corporate Air Air Ride Suspension, 228 in Asset located in: Lake Worth, TX Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 9728 2019 International LT625 6x4 T/A Sleeper Usage: 826,608 Mi Truck Tractor (Inoperable) Notes: INOPERABLE ITEM MUST BE REMOVED S/N: 3HSDZAPRXKN109682 FROM YARD BY JANUARY 10TH AND CANNOT C/W: Cummins X15 6 Cylinder 15 L 450 hp BE RELISTED; BUYER'S RESPONSIBILITY FOR Engine, 2018 US EPA Label, Requires Diesel REMOVAL Exhaust Fluid, Engine Brake, Automatic Asset located in: Lake Worth, TX Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED

Lot #	Details	Lot #	Details
9729	2018 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDZAPR2JN438729 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO- 18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 73 in High Rise Sleeper Cab, Aluminum Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9732	2000 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1FUYSSZB1YLF32067 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 1999 Volvo VNL 6x4 T/A Sleeper Truck Tractor
9730	Asset located in: Lake Worth, TX 2018 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDZTZR4JN416241 C/W: Navistar A26 6 Cylinder 13 L Diesel Engine, Requires Diesel Exhaust Fluid, 6691 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 73 in Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Hendrickson Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 671,789 Mi Notes: UNIT STARTS AND RUNS, ENGINE SEVERELY DERATED; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9734	(Inoperable) S/N: 4VG7DAJJ8XN788188 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller FRO-16210C Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, Eaton Drive Axles, 3.7:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 212 in Wheelbase, Lowboy Ramps, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX 1998 Freightliner FLD 120 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1FUYDDYB5WPA02987 C/W: 12000 lb Front Axle, 38000 lb Rears, 48000 lb GVWR, Air Ride Cab, 48 in Flat Top
9731	Asset located in: Lake Worth, TX 2006 Volvo VT 880 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 4V4LC9KL86N419522 C/W: Volvo D16D600 6 Cylinder 16.1 L Diesel 600 hp Engine, 2006 US EPA Label, Eaton Fuller 18-Speed Manual Transmission, 12500 lb Front Axle, 38000 lb Rears, 50500 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 256 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9735	Sleeper Cab, 285/75R24.5, Air Ride Suspension, 211 in Wheelbase, Dual Fuel Tanks Usage: 535,289 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2011 Capacity TJ5000 4x2 Spotter Truck (Inoperable) S/N: 4LMBR2118BL022572 C/W: Cummins 6 Cylinder 6.7 L Diesel 173 hp Engine, Allison Automatic Transmission, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

		1	
Lot #	Details	Lot #	Details
9736	2012 Peterbilt 367 6x4 Winch Truck (Inoperable) S/N: 1XPTD40X4CD146614 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 15245 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 225 in Wheelbase, PTO, Tail Roll, Ramsey Winch, Lowboy Ramps Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9740	2010 Mack 6x4 Cab and Chassis (Inoperable) S/N: 1M2AN09C3AN006300 C/W: Mack MP8 6 Cylinder 12.8 L 425 hp Engine, 2008 US EPA Label, Engine Brake, Allison Automatic Transmission, Mack Drive Axles, Air Ride Cab, 11R24.5, Camelback Spring Suspension, 220 in Wheelbase, 130 in Cab to Axle, 180 in Cab to End of Frame Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, CANNOT BE DRIVEN. TEMP TAGS WILL NOT BE ISSUED; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9741	2012 Freightliner M2 106 4x2 Cab and Chassis
9737	2013 International 7600 6x4 Vacuum Excavator Truck (Inoperable) S/N: 1HTGSSJT1DJ167340 C/W: International 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 385 /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 263 in Wheelbase, 58000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		(Inoperable) S/N: 1FVACWDT5CDBD9009 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 5.29:1 Axle Ratio, 10R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 252 in Wheelbase, 90 in Cab to Axle, 139 in Cab to End of Frame Usage: 151,346 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
9738	1988 International 1954 4x2 Vacuum	9742	1999 Volvo VN 4x2 Cab and Chassis
7700	Excavator (Inoperable) S/N: 1HTLDTVN5JH610926 C/W: 6 Cylinder Diesel Engine, 5809 Engine hrs, Manual Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 188 in Wheelbase, PTO, Dual Fuel Tanks Usage: 326,151 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9/42	(Inoperable) S/N: 4VA7BBRF8XN784017 C/W: Detroit Series 60 6 Cylinder 11.1 L Diesel 365 hp Engine, 1998 US EPA Label, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 152 in Wheelbase, 89 in Cab to Axle, 121 in Cab to End of Frame, Pintle Hitch Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; LOCATED-IN-JUSTIN- TX; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Lake Worth, TX
9739	2008 International 4400 4x2 Pressure Truck (Inoperable) S/N: 1HTMKAAN08H535972 C/W: 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 208 in Wheelbase, Dual PTO, Triplex Pump, Steel Tank Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
9743	2016 Chevrolet Express G3500 4x2 Cab and Chassis (Inoperable) S/N: 1GB3GRCG1G1277688 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225 /75R16, Spring Suspension, 142 in Wheelbase, 81 in Cab to Axle, 139 in Cab to End of Frame Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9746	2018 Ram 4500 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 3C7WRKEL5JG259100 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 175 in Wheelbase, 9 ft 5 in x 93 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9744	2010 Mitsubishi Fuso 4x2 COE Extended Cab Flatbed Truck (Inoperable) S/N: JL6CCG1S4AK009133 C/W: Mitsubishi 4 Cylinder Diesel Engine, Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 17995 lb GVWR, 215/75R17.5, Spring Suspension, 153 in Wheelbase, 14 ft 3 in x 91 in Bed Usage: 162,766 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9747	2006 Ford F-450 XL 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1FDXW46P46EB71060 C/W: V8 6.0 L Diesel Engine, 2008 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 245 /70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft x 93 in Bed Usage: 170,254 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9745	2020 International CV515 4x2 Crew Cab	Ī	Asset located in: Humble, TX
	Flatbed Truck (Inoperable) S/N: 1HTKSSWKXLH228328 C/W: International 6.6 L 350 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 1750 RDS 6-Speed Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 4.30:1 Axle Ratio, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 175 in Wheelbase, 9 ft 6 in x 96 in Bed Usage: 49,405 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9748	2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT7KEC83810 C/W: Ford Power Stroke V8 6.7 L Diesel 330 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 2 in x 92 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9745A	1998 International 4900 6x4 Flatbed Truck	9749	2018 Ford F-250 XL 4x4 Crew Cab Flatbed
	(Inoperable) S/N: 1HTSHAAR5WH533334 C/W: 6 Cylinder Diesel Engine, International 6- Speed Manual Transmission, 11R22.5, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 226 in Wheelbase, 23 ft x 94 in Bed, Dovetail, Hydraulic Ramps Usage: 58,070 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	77.47	Truck (Inoperable) S/N: 1FT7W2BT4JEB73055 C/W: V8 6.7 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 6340 lb Rears, 10000 lb GVWR, 33X12. 50R18, Spring Suspension, 176 in Wheelbase, 8 ft 6 in x 80 in Bed, Fuel Tank /w Pump Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED

Lot #	Details	Lot #	Details
9750	2007 Ford F-550 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1FDAW56PX7EA92103 C/W: Automatic Transmission, 6500 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225- 70R19.5, Spring Suspension, 12 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9753	2015 Freightliner 114SD 6x4 Mixer Truck (Inoperable) S/N: 1FVHG3DV3FHGC6645 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17826 Engine hrs, Engine Brake, Allison 4000 Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5
9751	2017 GMC 3500 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1GT42VCY6HF232993 C/W: V8 Diesel Engine, Automatic Transmission, 5600 lb Front Axle, 7050 lb Rears, 11600 lb GVWR, 275/65R18, Spring Suspension, 166 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: Not Available		Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 208,567 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		2015 Freightliner 114 SD 6x4 Mixer Truck (Inoperable) S/N: 1FVHG3DV7FHGD3310 C/W: Detroit 6 Cylinder 12.8 L Ultra Low Sulfu Diesel Engine, Requires Diesel Exhaust Fluid,
9751A	2001 Peterbilt 379 Car Carrier Truck (Inoperable) S/N: 1NP5DB9X81N539761 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, 425/65R22.5, Double Frame, Rubber over Walking Beam Suspension, 229 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM
9752	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck (Inoperable) S/N: 1HTMMMMN6HH474540 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8160 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 198 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 55,091 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9755	Asset located in: Lake Worth, TX 1999 Peterbilt 357 8x4 Mixer Truck (Inoperable) S/N: 1NPALTOX7XD494329 C/W: Cat C10 6 Cylinder Ultra Low Sulfur Diesel Engine, 21033 Engine hrs, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 53200 lb Rears, 60000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Trailing Tag Axle, Hendrickson Walking Beam Suspension, 250 in Wheelbase, PTO, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 212,655 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX

Details Lot# **Details** Lot # 9756 2019 International 4300 4x2 Rollback Truck 9760 2021 Ford 4x2 Step Van (Inoperable) (Inoperable) S/N: 1F66F5KN2M0A15011 C/W: V8 7.3 L Gasoline Engine, 2021 US EPA S/N: 3HAEUMML5KL556456 Label, Automatic Transmission, 8000 lb Front C/W: Cummins B 6 Cylinder 6.7 L 300 hp Axle, 15000 lb Rears, 22000 lb GVWR, 225 Engine, 2018 US EPA Label, Requires Diesel /70R19.5 Front Tires, 225/70R19.5 Rear Tires. Exhaust Fluid, 7063 Engine hrs. Allison Spring Suspension, 210 in Wheelbase, 22 ft x Automatic Transmission, 8000 lb Front Axle, 102 in Wide x 87 in High Body 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 255/70R22.5, Air Ride Usage: Not Available Suspension, 210 in Wheelbase, PTO, Miller **Notes**: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT Rollback Body, 19 ft 4 in x 102 in Bed, Ramsey HD234 8000 lb Winch BE RELISTED; BUYER'S RESPONSIBILITY FOR Usage: 142,777 Mi REMOVAL Notes: INOPERABLE ITEM MUST BE REMOVED Asset located in: Lake Worth, TX FROM YARD BY JANUARY 10TH AND CANNOT 9761 2021 Ford F59 4x2 Step Van (Inoperable) BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL: S/N: 1F66F5KN4M0A15012 C/W: 7.3 L Gasoline Engine, 2021 US EPA Asset located in: Lake Worth, TX Label, Automatic Transmission, 8000 lb Front 9757 2016 International 4300 4x2 Van Truck Axle, 15000 lb Rears, 22000 lb GVWR, 225 /70R19.5 Front Tires, 245/70R19.5 Rear Tires, (Inoperable) Spring Suspension, 210 in Wheelbase, 22 ft x 102 in Wide x 87 in High Body S/N: 1HTMNAAL1GH031595 C/W: Navistar 6 Cylinder Engine, 2016 US EPA Usage: Not Available Label, Automatic Transmission, 9000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 8002 Engine hrs, 11R22.5, Spring Suspension, 254 in Wheelbase, 24 ft x 96 in Wide x 97 in High Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Body, Curbside Door, Liftgate REMOVAL Usage: 149,593 Mi Asset located in: Lake Worth, TX Notes: INOPERABLE ITEM MUST BE REMOVED 9761A 2006 MCI J4500 6x2 56-Seat Coach FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR (Inoperable) REMOVAL OF THIS ITEM S/N: 2M93JMPA76W063464 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit 6 Cylinder Diesel Engine, Asset located in: Lake Worth, TX 9758 2012 Isuzu NPR 4x2 COE Van Truck Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 362 in Wheelbase (Inoperable) Usage: Not Available S/N: JALE5W163C7301062 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT 210 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, BE RELISTED; BUYER'S RESPONSIBILITY FOR 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 177 REMOVAL Asset located in: Humble, TX in Wheelbase, Morgan 18 ft x 96 in Wide x 85 in High Body, Curbside Door, Liftgate 9761B 2006 MCI J4500 6x2 56-Seat Coach Usage: Not Available (Inoperable) S/N: 2M93JMPA46W063454 Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT C/W: Air Conditioner, Automatic Transmission, BE RELISTED; BUYER'S RESPONSIBILITY FOR Lavatory, Detroit 6 Cylinder Diesel Engine, 315 /80R22.5, Air Ride Suspension, 363 in Wheelbase Asset located in: Lake Worth, TX Usage: Not Available 9759 2020 GMC G3500 4x2 Van Truck (Inoperable) Notes: INOPERABLE ITEM MUST BE REMOVED S/N: 7GZ37TCG1LN010503 FROM YARD BY JANUARY 10TH AND CANNOT C/W: GM V8 6.0 L Gasoline Engine, 2020 US BE RELISTED; BUYER'S RESPONSIBILITY FOR EPA Label, Automatic Transmission, 4300 lb REMOVAL Front Axle, 8600 lb Rears, 12300 lb GVWR, 225 Asset located in: Humble, TX /75R16, Spring Suspension, 178 in Wheelbase, 17 ft x 96 in Wide x 76 in High Body, Curbside Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

			1 age 330 of 307
Lot #	Details	Lot #	Details
9761C	2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPA26W063548 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9762B	2005 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMDA65W063118 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
9761D	2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPA06W063547 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9763	2018 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYAP8X5JJ207624 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11R22.5, Air Ride Suspension, EQUIPMENT-FROM-YELLOW- CORP Usage: 490,446 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9762	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XPBA48X4GD339490 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21678.6 Engine hrs, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 862,236 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9764	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYA48X2EJ355427 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2019 US EPA Label, 16235 Engine hrs, Eaton Fuller FM-15E310B-LAS Automated Transmission, 12700 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 155 in Wheelbase, Air Sliding 5th Wheel Usage: 723,788 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9762A	2005 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMDA45W062954 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9764A	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBGDD55FLGB0203 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

		_	
Lot #	Details	Lot #	Details
9764B	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3AKBGDDV3ESFV6407 C/W: Detroit DD13 6 Cylinder 12.8 L Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 15959 Engine hrs, Engine Brake, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-161 Drive Axles, 3.58:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 542,172 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9767	2009 International TranStar 8600 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1HSHWAHN59J674277 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel Engine, 24234 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 151 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 615,671 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9768	2005 International 9400i 4x2 S/A Day Cab
9765	·		Truck Tractor (Inoperable) S/N: 3HSCPSBN35N049230 C/W: Cat 6 Cylinder Engine, Eaton Fuller Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Notes: CANNOT VERIFY ODOMETER READING - VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9769	2002 International 9200i 4x2 S/A Day Cab
			Truck Tractor (Inoperable) S/N: 2HSCDAMN82C032078 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, 2001 US EPA Label, Eaton Fuller 9-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED
9766	2015 Freightliner M2 112 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBC5CY4FHGK0774 C/W: Cummins ISL9 Diesel 330 hp Engine, Eaton Fuller FO-10E310C-VAS Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 4.56:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 158 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		
			FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED
			Asset located in: Lake Worth, TX
		9770	2019 Chevrolet 2500 LT 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KSEY4KF120067 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, 275/70R18 Tires, 7 ft 11 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

	Details	I ot #	Dataila
Lot #	Details 2010 Chauralet 2500 4v4 Crow Cab Biokup	Lot #	Details 2014 Ford F 250 VI 4v2 Crow Cob Biokup
9771	2019 Chevrolet 2500 4x4 Crew Cab Pickup (Inoperable)	9775	2014 Ford F-250 XL 4x2 Crew Cab Pickup (Inoperable)
	S/N: 1GC1KSEY4KF119050 C/W: 6.6 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Fuel Tank, 10000 lb GVWR, 265/70R17 Tires, 4 ft 11 in Bed Usage: Not Available		S/N: 1FT7W2A63EEB14161 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;		/70R17 Tires, 6 ft 8 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9772	Asset located in: Lake Worth, TX 2019 Ford F-250 XL 4x4 Crew Cab Pickup	4	PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S
	(Inoperable)		RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	S/N: 1FT7W2BT9KEE68282 C/W: Automatic Transmission, Air Conditioner,	9776	2013 Chevrolet Silverado 2500 HD 4x4 Crew
Power Windows, Fuel Tank, RKI Tool Box, Drop- In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN	9776	Cab Pickup (Inoperable) S/N: 1GC1KVCG2DF243378 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	
	OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO
9773		-	PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
			Asset located in: Lake Worth, TX
		9777A	2011 GMC Sierra 2500HD 4x4 Extended Cab Pickup (Inoperable) S/N: 1GT22ZCG7BZ412902 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray-On Bed Liner, 9500 Ib GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 154,930 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9774	2015 GMC 2500 4x4 Crew Cab Pickup		REMOVAL;
	(Inoperable) S/N: 1GT12XE87FF109762	0777P	Asset located in: Lake Worth, TX 2011 Ford F-150 4v4 Crew Cab Bickup
C/W: 6.6 L I Automatic Power Wind GVWR, 265, Usage: Not Notes : INOI FROM YARI BE RELISTE REMOVAL; OFFICE TO	C/W: 6.6 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9777B	2011 Ford F-150 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTFW1EF8BKD94995 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 221,657 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9778 9778A	2014 Ford F-150 XLT 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTEX1CM5EKG46930 C/W: 3.7 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, UWS Tool Box, 6700 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 177,206 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2012 Chevrolet 1500 4x2 Extended Cab Pickup	9781	2021 Ford Ranger XL 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTER1EH0MLD55223 C/W: 2.3 L 4 Cylinder Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Northern Tool Equipment Tool Box, 255/70R16 Tires, 6 ft Bed Usage: 32,412 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	(Inoperable) S/N: 1GCRCPE00CZ144809		PROCESS TITLE Asset located in: Lake Worth, TX
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9782	2015 Chevrolet Spark Automobile (Inoperable) S/N: KL8CD6S93FC709764 C/W: 4 cyl 1.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 94,644 Mi
9779	1994 Dodge Ram 2500 4x2 Pickup (Inoperable) S/N: 1B7KC26C5RS655611 C/W: 5.9 L 6 Cylinder Diesel Engine, 5 Speed Manual Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 245/75R16 Tires, 8 ft	9783	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
	Bed, EQUIPMENT-FROM-YELLOW-CORP Usage: 184,458 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;		2017 Jaguar F-Pace AWD SUV (Inoperable) S/N: SADCJ2BN8HA089275 C/W: 4 cyl 2.0 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 77,696 Mi
9779A	Cab Pickup (Inoperable) S/N: 1GCRCPE04BZ255670 C/W: Gasoline Engine, Automatic		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Transmission, Air Conditioner, Headache Rack, RKI Tool Box, 6800 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed	9784	Asset located in: Lake Worth, TX 1995 Fontaine 352J 70000 lb T/A Heavy-Haul
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Jeep (Inoperable) S/N: 4LF3N2625S3503582 C/W: Sliding 5th Wheel, Air Ride Suspension, 275/70R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9780	1997 Ford F-150 XL 4x4 Pickup (Inoperable) S/N: 1FTDF1823VNC21842 C/W: 4.2 L V6 Gasoline Engine, Automatic Transmission, Air Conditioner, 6000 lb GVWR, 255/70R16 Tires, 8 ft Bed, EQUIPMENT-FROM- YELLOW-CORP Usage: 191,594 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9786	2005 Wilson 42 ft T/A Belly Dump Grain Trailer (Inoperable) S/N: 1W1MCF1A35B240910 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 2 Hoppers, Manual Traps, 9 ft Aluminum Box, 72 in, Side Walls, Manual Roll Tarp, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9790	Cat Engine S/N: Not Available C/W: Cat 3116 6 Cylinder 6.6 L Diesel Engine, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Quantity of (2) Electric Motor S/N: Not Available
	Asset located in: Lake Worth, TX	_	C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
9787	2015 Wabash RFALHSA 53 ft T/A Refrigerated Trailer (Inoperable)		Asset located in: Lake Worth, TX
	S/N: 1JJV532B4FL840000 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED	9792	Quantity of (2) Electric Motor S/N: Not Available C/W: Electrico, Sew-Eurodrive; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9793	Quantity of Electric Motor S/N: Not Available C/W: Assorted Size, One Pallet; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9794	2005 McElroy Roller Fusion Machine
9788	2013 Great Dane 48 ft x 96 in T/A Refrigerated Trailer (Inoperable) S/N: 1GRAA9625DB711787 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Swing Door, Carrier Transcd Refrigeration Unit, Serial Number JAV90746822,, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX		(Inoperable) S/N: C11420 C/W: 8 in Clamp SIze, Pipe Cutter Usage: 606 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lahoma, OK
9788A	2016 Lucon T-125 S/A (1) Reel Trailer	9795	McElroy Roller Fusion Machine
	(Inoperable) S/N: 1L9PU1012GG423949 C/W: 225/75R15 Tires, 4260 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; INOPERABLE ITEM MUST BE		S/N: C14830 C/W: 8 in Clamp Slze, Pipe Cutter Usage: 352 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
	REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9796	McElroy PitBull 412 Tracked Fusion Machine S/N: C15330 C/W: 13 in Clamp Slze, On-Board Generator,
9789	2014 Sauber 1570-B Hydraulic Cable Puller and Tensioner S/N: 1F9UZ1310EV048032 C/W: 2013 US EPA Label, Honda 1 Cylinder .68 L Gasoline Engine Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 2,119 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9797	McElroy PitBull 618 Tracked Fusion Machine S/N: C29981 C/W: 18 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 397 Hr	9806	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	9807	Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
9798	McElroy PitBull 412 Tracked Fusion Machine S/N: C22603 C/W: 13 in Clamp SIze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW Diesel Engine, 7 in Rubber Tracks Usage: Not Available	9808	Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
9799	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK McElroy PitBull 618 Tracked Fusion Machine	9809	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	S/N: C32754 C/W: 18 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 444 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE	9810	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
9800	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK Quantity of Tongs S(A): Not Available	9811	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in : Cedar Bluff, VA	9812	Torus Blowout Preventer S/N: Not Available
9801	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC		C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Usage: Not Available Asset located in: Cedar Bluff, VA	9813	Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-ING
9802	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC	9814	Usage: Not Available Asset located in: Cedar Bluff, VA Quantity of Sioux S195667 Pipe Stands
	Usage: Not Available Asset located in : Cedar Bluff, VA		S/N: Not Available
9803	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
9804	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK
9805	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		

Lot #	Details	Lot #	Details
9815	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	9820	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9816	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9821	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9817	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9822	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9818	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9823	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9819	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9824	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9825	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	9830	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK	 	Asset located in: Lahoma, OK
9826	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available	9831	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK	ļ	Asset located in: Lahoma, OK
9827	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9832	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9828	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9833	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9829	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	9834	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9835	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	9840	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK	20.44	Asset located in: Lahoma, OK
9836	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9841	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK	1	Asset located in: Lahoma, OK
9837	Quantity of Sioux \$180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9842	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9838	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9843	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9839	Quantity of Sioux S15813 Pipe Stands	9844	Quantity of Pipe Stands
	S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9846 Quantity of Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: TEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available C/W: 48 in: x 6 in: x 4 in. Usage: Not Availa	Lot #	Details	Lot #	Details
AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9846 Quantity of Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available C/W: 6 Stacks Usage: Not Available C/W: 8 In x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48	9845	S/N: Not Available C/W: 2 Stacks Usage: Not Available Notes : ITEMS AT OFFSITE LOCATION MUST	9850	S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes : ITEMS AT OFFSITE LOCATION MUST
9846 Quantity of Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE ASSET LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE ASSET LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE A		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 48 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 8847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9852 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Avai		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE ASSET located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE ASSET located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Avail	9846	S/N: Not Available C/W: 4 Stacks	9851	S/N: Not Available C/W: 48 in x 6 in x 4 in
9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS BE PICKED UP W		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE NOTE BE ABLE TO ASSIST WITH LOADING THESE NOTE BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE ASSET located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. Usage: Not Available C/W: 48 in. x 6 in. Usage:	9847	S/N: Not Available C/W: 5 Stacks	9852	S/N: Not Available C/W: 48 in. x 6 in. x 4 in.
9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE NOT BE ABLE TO ASSIST WITH LOADING THESE REPORT O 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE ROUTH OF (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in.		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. U	9848	Quantity of (700) Pipeline Skids	9853	Quantity of (616) Pipeline Skids
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK 9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE BE PICKED UP WITHIN 14 DAYS SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		S/N: Not Available C/W: 48 in. x 6 in. x 4 in.		S/N: Not Available C/W: 48 in. x 6 in. x 4 in.
9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE 9854 Quantity of (610) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCA BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCA BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOAD NOT BE ABLE TO ASSIST WITH LOADING THESE		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORA BUYER RESPONSIBLE FOR LOAD NOT BE ABLE TO ASSIST WITH L	9849	S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available	9854	S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available
Asset located in: Lahoma, OK Asset located in: Lahoma, OK		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
· ·				Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9855	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in, There are some 4x4 in mixed in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9860	Pipeline Cradle S/N: Not Available C/W: Double Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9856	Quantity of (600) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	-9861	Pipeline Cradle S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lahoma, OK	9862	Pipeline Cradle
9857	Quantity of (580) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		S/N: Not Available C/W: Single Head, Single Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9858	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9863	Pipeline Cradle S/N: Not Available C/W: Single Head, Double Roller Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9859	Quantity of (10) Approximately 16 ft x 4 ft Skids (10) Stacks & Misc Pieces Pipeline Skids S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	-9864	Darby Pipeline Cradle S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9865	DMH RO Pipeline Cradle S/N: 485 C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9870	Mathey Dearman 12 in Beveling Machine S/N: CE106814 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9866	2013 Mcclain 28 Ft T/A Mobile Flare S/N: 4LYUS2223DH000570	9871	Quantity of Denso Protal 7200 Liquid Epoxy Coating & Brushes
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, (2) Tool Boxes, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Part A & B Coating Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
9866A	Quantity of Assorted Drill Bit S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	9872	Quantity of (102) Rolls of PipelineRock Guard
9867	57 2009 MacElroy LT0048 T/A Hydraulic Line Tamer S/N: C30327 C/W: To Fit McElroy Manufacturing, Inc LineTamer poly pipe straightener, 2002 US EPA Label, Honda GXV160 1 Cylinder 163 cc Gasoline Engine Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE		Mesh S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	9873	S/N: Not Available
9868	Quantity of (3) Vaculifter S/N: LT30-000101 C/W: To Fit lift technology LT36 pipe vac lift, Tier 1, 2012 US EPA Label, Hatz CHZXL 445V42 1 Cylinder 6.4 kW .44 L Diesel Engine		C/W: Seller Supplied Info: Approximate dimensions 8ft x 20ft. Buyer responsible for load-out and transport. Usage: Not Available Asset located in: Midland, TX
	Usage: 1,278 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	9874	Quantity of (4) 15 Ft Pipe Cartridges S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
9869	Mathey Dearman 20 in Pipe Beveling Machine S/N: M68048 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9875	Quantity of (3) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 All Terrain S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		9876	Quantity of (2) 10 ft Pipe Cartridges - Fits Ditch Wtich JT30 & JT3020 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9877	Quantity of (2) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 Mach I S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Pipe Elevators S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	9884	Quantity of (8) Foam Pigs S/N: Not Available C/W: (7) 16 in, (1) 18 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
9879	Pipe Elevator		Asset located in: Lahoma, OK
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	9885	Quantity of (2) Pipeline Cleaners Plate Sizing Pigs S/N: H582, P615
9880	Quantity of (15) 10 in Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		C/W: (1) 16 in, (1) 10 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
0001	Asset located in: Lahoma, OK	9886	Quantity of (7) Stringing Cables S/N: Not Available
; 	Quantity of (20) Crates of 8 in Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9882	Asset located in: Lahoma, OK Quantity of (13) Assorted Pigs S/N: Not Available C/W: (8) 8 in Bull nose, (1) 8 in Brush, (1) 8 in	9887	Quantity of (12) Boxes of Tape & Primer S/N: Not Available C/W: 3M Tape, RD-6 Tape & Primer Usage: Not Available
	Bidirectional, (1) 10 in Bidirectional Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lahoma, OK	9888	Quantity of Wax Tape, Primer S/N: Not Available
9883	Quantity of 8 In Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
9889	Quantity of Assorted Night Caps S/N: Not Available C/W: 4 in - 16 in gg Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9894	Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: 4 in, 6 in, 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
9890	Quantity of (2) Rock Shield S/N: Not Available C/W: (1) 36 in, (1-60) in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9895	Quantity of Dies - Fits McElroy 618 Poly Pipe Welding Machine S/N: Not Available C/W: 16 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
9891	Quantity of (6) Felt Lined Rock Shield S/N: Not Available C/W: (5) 60 in, (1) 36 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	9896	Asset located in: Lahoma, OK Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: To Fit McElroy 412 Dies, (4) 6 in, (4) 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	
9892	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available		AUCTION (JANUARY 3RD) OR WILL B SUBJECT TO 3RD PARTY STORAGE F BUYER RESPONSIBLE FOR LOADOUT, NOT BE ABLE TO ASSIST WITH LOAD THESE	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
	C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (9) 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: To Fit McElroy 412 Dies, 10 in, 12 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	
9893	Quantity of Balon Valves S/N: Not Available C/W: One Pallet Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9898	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Dies, Poly PipeWelding Machine 6 in, 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9902	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Poly Pipe Welding Machine, 6 in., 8 in. dies Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9899	Quantity of Dies	9903	Quantity of McElroy Poly Pipe Welding
	S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, 7- 8 in, 4- 6 in. Incomplete Sets. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Machine Parts S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9900	Quantity of Dies	9904	Quantity of Extension Hydraulic Hoses S/N: Not Available
	S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in, (8)12 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		C/W: To Fit McElroy Poly Pipe Welding Machines Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9901	·	9905	Quantity of Flange Gaskets
9901	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, (12)10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	THESE Asset located in: Lahoma, OK	9906	Quantity of Dies S/N: Not Available
		ı	C/W: To Fit McElroy 618 Poly Pipe Welding Mchine, (8) 16 in., (8) 12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9907	Heater - Fits S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9912	Bending Shoe S/N: Not Available C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9908	Quantity of Dies S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, (4) 2 in., (4) 3 in., (7) 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9913	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9909	McElroy 848701 Electric Heater S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	-9914	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9910	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 618 Poly Pipe Welding Machine, 12 in., 16 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9915	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9911	Quantity of Dies S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, 2 in., 3 in., 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	-9916	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
9917	MMI Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9922	Bending Shoe Bucket S/N: Not Available C/W: 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
9918	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9923	Bending Shoe Bucket S/N: 015M C/W: 6 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
	Asset located in: Lahoma, OK	9924	Bending Shoe Bucket	
9919	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8) 6 in, (8) 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATIO BE PICKED UP WITHIN 14 DAYS OF AUCTION (JANUARY 3RD) OR WILL SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOU	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	THESE	9925	Remco Bending Shoe	
9920	Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in., (8)12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOG BE PICKED UP WITHIN 14 DAY AUCTION (JANUARY 3RD) OR SUBJECT TO 3RD PARTY STO BUYER RESPONSIBLE FOR LO NOT BE ABLE TO ASSIST WIT THESE Asset located in: Lahoma, OK 9926 Quantity of (2) Roller Stands S/N: Not Available	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe
9921	Quantity of (2) Bending Shoe	1	Usage: Not Available	
	S/N: 3040918 C/W: (1) 8 in., (1) 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9927	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9931	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9928	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9932	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9929	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9933	McElroy 1242112 Heater S/N: Not Available C/W: To Fit McElroy Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9930	MMI Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9934	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
9935	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9940	Quantity of McElroy Pitt Bull 14 Hot Plate, Facer S/N: C147848 C/W: 1-4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
9936	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9941	Quantity of (5) Calipers S/N: 29897, 52770 C/W: 6 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
	Asset located in: Lahoma, OK	9942	Quantity of (5) Calipers	
9937	Rigid BF86C Electric Tie In Machine S/N: 086C03820A46 C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		BE PICKED UP WITHIN 14 DAYS OF T AUCTION (JANUARY 3RD) OR WILL B SUBJECT TO 3RD PARTY STORAGE F BUYER RESPONSIBLE FOR LOADOUT NOT BE ABLE TO ASSIST WITH LOAD THESE Asset located in: Lahoma, OK	C/W: 12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lahoma, OK	9943	Quantity of (4) Calipers S/N: 43635	
9938	Mustang DBG60 Polyethylene Pipe Squeeze Tool S/N: Not Available C/W: To Fit Poly Pipe, 4 in & 6 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9944	C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCAT BE PICKED UP WITHIN 14 DAYS OF AUCTION (JANUARY 3RD) OR WITE SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADE NOT BE ABLE TO ASSIST WITH LETHESE Asset located in: Lahoma, OK 9944 Quantity of (3) Calipers	C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	·	4	C/W: 16 in.	
9939	Quantity of McElroy Pitt Bull 14 Electric Facer S/N: C20800 C/W: Hester not included Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WIL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9945	Quantity of (3) Calipers S/N: 53951, 32791 C/W: 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9953	Quantity of (4) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY, (1) 16 ft, (3) 20 ft Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Spy Model 780 Pipeline Detectors S/N: Not Available C/W: (2) Spy Model 670 wet sponge detectors, Fisher TW-6 Pipe and cable locator
9946	Quantity of (4) Calipers S/N: Not Available C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9955	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK Quantity of (6) Assorted Pipeline Detectors S/N: Not Available C/W: (4) Spy Detectors, (2) Vivax Metrotech Detectors, misc parts and batteries
9947	Quantity of (2) Calipers S/N: 57397 C/W: 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL B SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
9948	THESE Asset located in: Lahoma, OK Pipe Fittings S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR W SUBJECT TO 3RD PARTY STORAGE FE FORKLIFT ASSISTANCE WILL NOT BE
9949	Quantity of Pipelayer Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	9957	Asset located in: McAlester, OK 32 ft x 8 ft Mobile Test Unit S/N: DCS489-196 Usage: Not Available Asset located in: Midland, TX
9950	Drilling Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	9958	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-07 C/W: To Fit FMC Technologies FM100300 Usage: Not Available
9951	Drilling Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Drilling Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	9959	Asset located in: Midland, TX 2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-09 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details	
9960	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-10 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Asset located in: Midland, TX	9967	Quantity of (3) Metrotech 810DX Line Locator S/N: 004314 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	
9961	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-03 C/W: To Fit FMC Technologies FM100300 Usage: Not Available	0060	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK	
	Asset located in: Midland, TX	9968	Radiodetection Cat4+ Locator S/N: 10C4EN144291	
9962	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-05 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Asset located in: Midland, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES BUYER RESPONSIBLE FOR LOADOUT. RE NOT BE ABLE TO ASSIST WITH LOADING	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
9963	Quantity of (8) Reelcraft CA3319L Grease Hose Reel Skid		Asset located in: Lahoma, OK	
	S/N: 230508-004 Usage: Not Available Asset located in : Midland, TX	9969	Quantity of (41) Mats S/N: Not Available Usage: Not Available	
9964	S/N: 7804998 C/W: To Fit Spy 780 Jeep Detector, 4", 6", 8", 10", 12", 16" springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
		9970	Evans HBM Horizontal Boring Machine S/N: 016 C/W: 2002 US EPA Label, Deutz BF4L913 4 Cylinder 99 hp Diesel Engine Usage: 5 Hr	
9965	Quantity of (7) Spy 780 Jeep Detector S/N: 7805001 C/W: 4 in, 6 in, 8 in, 10 in, 12 in, 16 in Springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9971	International Boring 224 Horizontal Boring Machine S/N: 1504	
9966	Quantity of (4) Fisher Research Labs Gemini 3 Metal & Mineral Detector S/N: 102201652 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		C/W: 16 in Boring Auger, Wisconsin VH4D1A 4 Cylinder Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9971A	2008 Lufkin Tri/A Lowboy Trailer S/N: 1L01D513181166341 C/W: Air Ride Suspension, 28 ft Main Deck, 102 in Usable Deck Width, Pickup Throat, Tail Roller, 255/70R22.5 Tires, 90000 lb GVWR Usage: Not Available	9979	2016 John Evans 3TSLR S/A (1) Reel Trailer S/N: 1J9T112A4G0003908 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 6000 lb GVWR Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
9972	2014 Dynacorp TL1280 Tri Axle HS Separator Trailer S/N: 2C9T3DFA1E3161480 C/W: 9.9 Mpa/1440psi Usage: Not Available Asset located in: Midland, TX	9980	2014 Brindle T/A (4) Reel Trailer S/N: 1L90R2626EG085221 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires, 21000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9973	2013 Wyatt's Trailer Sales 24 ft T/A Spooling Trailer S/N: 1W9GU24253L364589 C/W: 24000 lb GVWR, Spring Suspension, Electric Brakes, Deck Over Tires, Kubota Diesel Powered Self Contained Hydraulic System, 235 /80R16 Tires Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: El Reno, OK	9981	2012 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK18N3C1000066 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/75R17.5 Tires, 10000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9974	1988 Big Tex 18 Ft T/A Gooseneck Chemical Trailer S/N: 16VGB1622J1416669 C/W: Spring Suspension, Electric Brakes, Deck Over Tires, 235/85R16 Tires, 19400 lb GVWR, 4 Cylinder Diesel, Triplex Pump, (2) - 500 gallon tanks; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,660 Hr	9982	2011 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK16N6B1000015 C/W: Lunette Ring Hitch, 12-16.5 Tires, 7500 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9982A	1999 Butler S/A (1) Reel Trailer
9975	2005 C & S Trailer World Tri/A (3) Reel Trailer S/N: 44Z255LKX5T014462 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9982A	S/N: 1BUC10105X1001719 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 8000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9976	2012 Drake T/A (3) Reel Trailer S/N: 1D9BU1410CP472777		PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: Spring Suspension, 225/75R15 Tires,	9984	1995 Redi-Haul S/A Reel Trailer
	9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	9984	S/N: 47SZ041T5S1010806 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Hydraulic Reel Hoist, 235/75R17.5 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
9977	2020 Pro Fabrication S/A Reel Trailer S/N: 1P9BR101XLC495135 C/W: Lunette Ring Hitch, Torsion Axle, Electric		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Brakes, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9985	1989 Sauber 1531 T/A (3) Reel Trailer S/N: 1F9RE1822KV048271 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9986	2011 Dragon 8400 gal T/A Tanker Trailer S/N: 1UNST4422BS082564 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 70000 lb GVWR Usage: Not Available Notes:	9992	2025 X-STAR 990 gal T/A Tanker Trailer S/N: 1X9T7BA20SH039931 C/W: Ball Hitch, Spring Suspension, 235/80R16 Tires, 14000 lb GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Humble, TX	9993	2025 Industrias America 750 gal Trailer	
9987	2011 Heil 9500 gal T/A Tanker Trailer S/N: 5HTDL4529B5H23926 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 73000 lb GVWR, Roper Hydraulic Powered Pump, 73000 lb GVWR		Mounted Fuel Tank S/N: 3EZBTT088SA003625 C/W: 12 V Transfer Pump, DEF Tank Usage: Not Available Asset located in: Lake Worth, TX	S/N: 3EZBTT088SA003625 C/W: 12 V Transfer Pump, DEF Tank Usage: Not Available
	Usage: Not Available Notes: . Asset located in: Humble, TX	9994	2025 X-STAR 750 gal T/A Tanker Trailer S/N: 1X9T7B829SH039934 C/W: Ball Hitch, Spring Suspension, 225/75R15 Tires, 10400 lb GVWR, Steel Tank, (1) Reels	
9988A	2011 Stephens T/A Tanker Trailer S/N: 1S9AB15B9BH474104 C/W: 68000 lb GVWR, Air Ride Suspension,		Electric Powered Pump, 10400 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	
	11R22.5 Tires, Steel Tank Usage: Not Available Asset located in : Lake Worth, TX	9995	2025 X-STAR 750 gal T/A Tanker Trailer S/N: 1X9T7B827SH039933 C/W: Ball Hitch, 225/75R15 Tires, 10400 lb GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 10400 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
9989	2010 Galyean 130 BBL T/A Tanker Trailer S/N: 1G9VT4020AH017248 C/W: Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Steel Tank, 3 Compartments, CHALLENGER Hydraulic Powered Pump Usage: Not Available Notes: Asset located in: Humble, TX			
		9996	2024 DNJ 750 T/A Tanker Trailer S/N: 1D9D7B927RH870580 C/W: Spring Suspension, Electric Brakes, 225 /75R15 Tires, 12000 lb GVWR, Steel Tank, FILL- RITE Electric Powered Pump, 12000 lb GVWR	
9990	2005 Polar SRJH 3800 gal T/A Tanker Trailer S/N: 1PMS1452X51028313		Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: Air Ride Suspension, Air Brakes, Aluminum Wheels, 445/50R22.5 Super Single Tires, 68000 lb GVWR, Insulated Stainless Steel Tank Usage: Not Available Asset located in: Livingston, LA	9997	1998 Comptank 6250 gal Tri/A FRP Tanker Trailer S/N: 2C9LTA3C3WB075132 C/W: Spring Suspension, Lift 1st- Axles, 11R24. 5 Tires, FRP Tank, Catwalk w/Guardrails Usage: Not Available	
9990A	2003 Heil 8400 gal T/A Tanker Trailer S/N: 5HTDL452X35G14702		Asset located in: Lake Worth, TX	
	C/W: Spring Suspension, 11R24.5 Tires, Stainless Steel Tank Usage: Not Available Asset located in: Lake Worth, TX	9998	1997 Trailmaster 8400 gal T/A Tanker Trailer S/N: 190DL4428V3G13006 C/W: Aluminum Frame, Spring Suspension, 11R24.5 Tires, Aluminum Tank	
9991	2025 X-STAR 990 gal T/A Tanker Trailer	\dashv	Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: 1X9T7BA22SH039932 C/W: Aluminum Frame, Ball Hitch, 235/80R16 Tires, 14000 lb GVWR, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9999	1995 Polar 4400 gal 4/Axle Tanker Trailer S/N: 1R9212339SL040301 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
10000	1973 Trim T/A Tanker Trailer S/N: K40092 C/W: Spring Suspension, Aluminum Wheels, 11R22.5 Tires, Stainless Steel Tank, Catwalk, Gasoline Powered Pump Usage: Not Available Asset located in: Lake Worth, TX	10008	2015 Keith Huber 5500 gal T/A Vacuum Tanker Trailer S/N: 1K9TS5522F1077001 C/W: Spring Suspension, 11R24.5 Tires, 45000 lb GVWR, Steel Tank, Catwalk w/Guardrails, Fruitland Diesel Powered Pump, 45000 lb GVWR
10001	·	1	Usage: Not Available
10001	2020 Troxell 5460 gal T/A Vacuum Tanker Trailer S/N: 1T9TA4320L1867597		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT.
	C/W: Spring Suspension, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Challenger 607 Hydraulic Blower, 50000 lb GVWR Usage: Not Available	10009	Asset located in: Humble, TX 2014 Dragon 150 BBL 6300 gal T/A Vacuum Tanker Trailer S/N: 1UNST4224ES128600
	Asset located in: Humble, TX	4	C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 70000 lb
10002	2019 Southern 150 bbl T/A Vacuum Tanker Trailer S/N: 4T9V6TA27KJ329225 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 63700 lb GVWR, 63700 lb GVWR Usage: Not Available		GVWR, Aluminum Tank, Challenger 607SV Blower Usage: Not Available Notes: . Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	10010	2013 Dragon 130 bbl T/A Vacuum Tanker
10003	2018 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA25JG347005 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available	Trailer S/N: 1UNST4223DL C/W: Spring Suspen Tank Usage: Not Available	S/N: 1UNST4223DL130024 C/W: Spring Suspension, 11R24.5 Tires, Steel
	Asset located in: Lake Worth, TX 10011	10011	2012 Troxell 140 BBL 5880 gal T/A Vacuum
10004	2017 Southern 150 gal T/A Vacuum Tanker Trailer S/N: 4S9V6TA26HG347007 C/W: Air Ride Suspension, 11R24.5 Tires, 10000 lb GVWR, Aluminum Tank, 10000 lb GVWR Usage: Not Available		Tanker Trailer S/N: 1T9TA4320C1867101 C/W: Spring Suspension, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Catwalk w/Guardrails, 50000 lb GVWR, 45 ft Pup Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	10012	2011 Troxell 140 BBL 5880 gal T/A Vacuum
10005	2016 Southern 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA24GG347036 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 10000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Tanker Trailer S/N: 1T9TA432XB1867783 C/W: Spring Suspension, Aluminum Outer Wheels, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Catwalk w/Guardrails, 50000 lb GVWR, 45 ft Pup Usage: Not Available Asset located in: Lake Worth, TX
10006	2016 Southern Welding 150 bbl T/A Vacuum	10013	2011 Dragon 150 bbl T/A Vacuum Tanker
	Tanker Trailer S/N: 4S9V6TA29GG347047 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 1UNST4225BL068770 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Catwalk w /Guardrails
10007	2016 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA27GG347032 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: . Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
10014	2007 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST42277L063710 C/W: Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Steel Tank, Catwalk w/Guardrails Usage: Not Available Asset located in: Lake Worth, TX	10022	2001 Heil 1000 cft T/A Pneumatic Bulk Trailer S/N: 5JLSN422415T05772 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 295/75R22.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX	
10015	1979 Reliable 8400 gal T/A Vacuum Tanker Trailer S/N: 2316 C/W: Air Ride Suspension, 295/75R22.5 Tires, 60000 lb GVWR, Aluminum Tank, 60000 lb GVWR Usage: Not Available	10023	1998 LBT 1000 cft T/A Pneumatic Bulk Trailer S/N: 4J8B04229WT00303 C/W: Spring Suspension, 11R22.5 Tires, 68000 lb GVWR, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX	
10016	Asset located in: Lake Worth, TX 2008 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGFT473888506205 C/W: 2 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available Asset located in: Lake Worth, TX	10024	1996 Heil 1040 cft T/A Pneumatic Bulk Trailer S/N: 5HTSN4223T9T07318 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX 1994 Heil 1600 cft T/A Pneumatic Bulk Trailer	
10017	1999 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGSB471XXS249824 C/W: Manifold, 1 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available		S/N: 1HLS5N8B8R9W07014 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Aluminum Tank, 4 Compartments, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	10026	1994 Polar 1000 cft T/A Pneumatic Bulk Trailer S/N: 1PMB14225R2013531 C/W: Aluminum Frame, Air Ride Suspension,	
10018	VE Enterprises 435 bbl Flat Top S/A Frac Tank S/N: FTI1298115FT C/W: 3 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available		Air Brakes, 11R24.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX	10027	1984 Fruehauf 1000 cft T/A Pneumatic Bulk Trailer S/N: 1H4B04121EK004312	
10019	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR27KP104096 C/W: Air Ride Suspension, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank		C/W: Aluminum Frame, Spring Suspension, Aluminum Wheels, 285/75R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in : Lake Worth, TX	10028	2015 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer	
10020	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR29KP104097 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX			S/N: 1Z9GG3228FN374020 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX
10021	2012 Delu T/A Pneumatic Bulk Trailer S/N: 3BYD6TE29CH005151 C/W: Air Ride Suspension, 11R24.5 Tires, Steel Tank, 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX	10029	2015 Intech 32 ft x 102 ft Portable T/A Lab Trailer S/N: 1Z9GG3228FN374017 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235 /80R16 Tires, 14400 lb GVWR Usage: Not Available Asset located in: Oklahoma City, OK	

Lot #	Details	Lot #	Details
10030	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG322XFN374018 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX	10036	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG2820EN374917 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX
10031	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab	10037	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab
	Trailer S/N: 1Z9GG3226FN374016 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX		Trailer S/N: 1Z9GG2827EN374915 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: Asset located in: Midland, TX
10032	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab	10038	2014 Intech 28 ft x 102 ft Portable T/A Lab
10032	Trailer S/N: 1Z9GG3221FN374019 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR	10000	Trailer S/N: 1Z9GG2822EN374918 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235 /80R16 Tires, 14400 lb GVWR Usage: Not Available
	Usage: Not Available Notes: .	<u> </u>	Asset located in: Oklahoma City, OK
	Asset located in: Midland, TX	10039	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab
10033	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3222FN374014 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available		Trailer S/N: 1Z9GG2829EN374916 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX
	Notes: . Asset located in: Midland, TX	10040	2007 William Scotsman 52 ft x 11 ft 11 in
10034	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG322XFN374021 C/W: (1) Offices, Air Conditioner, Aluminum		Portable Tri/A Crew House S/N: 24348 C/W: To Fit SPACE MASTERS 40440 Usage: Not Available Asset located in: Lake Worth, TX
	/Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: .	95000	Kubota SUL-75 Skid Steer Loader S/N: 1034889 Usage: Not Available Asset located in: Midland, TX
	Asset located in: Midland, TX	95024	2014 Toyota 8FGCU30 5020 lb Cushion Tire
10035	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3224FN374015 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle.	70027	Forklift S/N: 60401 Usage: Not Available Asset located in: Lake Worth, TX
		95051	Moffett M5000 Placeholder Cushion Tire Forklift S/N: A05171R Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
95053	2014 Ford F-450 Pickup S/N: 1FD0W4GT0EEB80852 Usage: Not Available Asset located in: Lake Worth, TX 2015 Cat 16T 36 BU Excavator Bucket	95080	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
	S/N: 316-36-MHJ06857 Usage: Not Available Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
95073	smooth Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	95081	2018 Arrow 4' Block Forks Telehandler S/N: L19846 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	
95075	Scissor Lift S/N: Not Available		Asset located in: Lake Worth, TX	
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	95083	2016 Genie 1255567 Telescopic Boom Lift S/N: ORD FOR 135270 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	
95076	Scissor Lift		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	95084	Scissor Lift S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	
95077	Scissor Lift	95085	Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Scissor Lift S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	
95078	Scissor Lift		Asset located in: Lake Worth, TX	
95079	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	95090	Pallet S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	
930/9	2015 Sullair Air Compressor S/N: 2015071-30056		Asset located in: Corsicana, TX	
	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95091	Pallet S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
95092	. S/N: Not Available Usage: Not Available	95098	. S/N: Not Available Usage: Not Available
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95093	<u> </u>	95099	·
	S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95094		95100	•
	S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available
	Notes: LOADOUT BY APPOINTMENT ONLY;		Notes: LOADOUT BY APPOINTMENT ONLY;
	ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95095	·	95101	·
	S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95096	•	95102	•
	S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95097	S/N: Not Available Usage: Not Available	95103	S/N: Not Available Usage: Not Available
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK

Lot #	Details	Lot #	Details
95106	S/N: Not Available Usage: Not Available	95112	S/N: Not Available Usage: Not Available
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95107	S/N: Not Available Usage: Not Available Notes : LOADOUT BY APPOINTMENT ONLY;	95113	S/N: Not Available Usage: Not Available Notes : LOADOUT BY APPOINTMENT ONLY;
	ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95108	S/N: Not Available Usage: Not Available Notes : LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE	95116	S/N: Not Available Usage: Not Available Notes : LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK		Asset located in: McAlester, OK
95109	S/N: Not Available	95117	S/N: Not Available
	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
	Asset located in: McAlester, OK	1000	Asset located in: McAlester, OK
95110	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95133	2015 JLG Telehandler S/N: 0160071104 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
		95145	1977 Pines Van Trailer S/N: 320CDV6061 C/W: EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
95111	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE		Asset located in: Lake Worth, TX
		95146	2025 MaxxD D7X7212 End Dump Trailer S/N: 117643 Usage: Not Available
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	054 15	Asset located in: Lake Worth, TX
	FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95147	2025 MaxxD DTX8314 End Dump Trailer S/N: 118238 Usage: Not Available Asset located in: Lake Worth, TX

	Details	l o+ #	Dotoile
Lot #		Lot #	Details
95152	1991 Belshe 20 ft T/A Utility Trailer S/N: 16JF01827M1021861 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 102 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 225/90R16 Tires Usage: Not Available Asset located in: Midland, TX		
95160	1995 Talbert T/A Test Package S/N: 40FWK5239S1012196 C/W: To Fit Shop Built Pressure Test Trailer Usage: Not Available Asset located in: Midland, TX		
95267	2009 Dodge Ram 1500 4x4 Pickup S/N: 1D3HV16P59J518182 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		
95270	2006 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06256J612598 C/W: Spring Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Roll-Up Door, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Humble, TX		