

Fort Worth, TX, USA - Dec 10, 2024

Lot #	Details	Lot #	Details	
1	2017 Case 570 N EP 4x4 Landscape Loader S/N: JJGN570NEHC739167 C/W: Open Operator Station, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Weight Box Usage: 4,852 Hr Asset located in: Lake Worth, TX	6A	2018 Cat 415F2 IL 4x4 Landscape Loader S/N: 0PF400836 C/W: Open Operator Station, 89 in Bucket, 89 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier Usage: 2,540 Hr Asset located in: Lake Worth, TX	
2	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380199 C/W: Open Operator Station, 2006 US EPA Label, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 7,966 Hr Asset located in: Lake Worth, TX	7	2022 Cat 420 IT 4x4 Backhoe Loader S/N: CAT00420TH8T02368 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Forks, Quick Coupler, 24 in Backhoe Digging Bucket, Thumb Bracket,	
	E OF 2 - Lot #'s: 3, 4		E U N	EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 66 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS;
3	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380435 C/W: Open Operator Station, 2006 US EPA Label, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 2,597 Hr Asset located in: Lake Worth, TX		PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	
		8	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420CH8T00232 C/W: Open Operator Station, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 12 i	
4	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380358 C/W: Open Operator Station, 2006 US EPA Label, 82 in Bucket, 84 in Hydraulic Tilting Box		Backhoe Digging Bucke Hydraulics, Thumb Brad Usage: 4,244 Hr	Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket
	Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 4,932 Hr Asset located in : Lake Worth, TX	9 2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420AH8T00225 C/W: Open Operator Station, Air Ride Seat, 7 4, 2020 US EPA Label, Requires Diesel Exha Fluid, 96 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,803 Hr	S/N: CAT00420AH8T00225 C/W: Open Operator Station, Air Ride Seat, Tier	
5	2015 John Deere 210L EP 4x4 Landscape Loader S/N: 1T8210ELEFJ892655 C/W: Open Operator Station, 2015 US EPA Label, 84 in Bucket, 89 in Box Blade, Rear		Fluid, 96 in Loader Bucket, 24 in Bac Digging Bucket, Rear Auxiliary Hydra Thumb Bracket Usage: 4,803 Hr	Fluid, 96 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket
	Wheel Weights, with Rippers Usage: 4,261 Hr Asset located in: Lake Worth, TX	CHOICE	E OF 4 - Lot #'s: 10, 11, 8, 9	
6	2006 Case 570 MXT 4x4 Landscape Loader S/N: JJG0380343 C/W: Enclosed Cab, 83 in Bucket, 83 in Hydraulic Tilting Box Blade Usage: 2,554 Hr Asset located in: Lake Worth, TX	Backhoe Pilot Controls, Tier 4, 2020 U Label, Requires Diesel Exhaust Fluid, 9 Loader Bucket, 24 in Backhoe Digging	S/N: CAT00420AH8T00287 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 5,611 Hr	

Lot #	Details	Lot #	Details
11	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420JH8T00303 C/W: Open Operator Station, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket Usage: 5,904 Hr Asset located in: Lake Worth, TX	17	2016 Cat 420 F2 4x4 Backhoe Loader S/N: CAT0420FEHWC01679 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, 86 in Multi-Purpose Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, (2) Rear Auxiliary Hydraulics
12	2017 Cat 420F2 4x4 Backhoe Loader		Usage: 2,720 Hr Asset located in: Lake Worth, TX
	S/N: CAT0420FJHWC02726 C/W: Open Operator Station, Backhoe Pilot Controls, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 15 in Backhoe Cleanup Bucket, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,487 Hr Asset located in: Lake Worth, TX	18	2015 Cat 420F2 IT 4x4 Backhoe Loader S/N: CAT0420FAHWD00353 C/W: Open Operator Station, Backhoe Pilot Controls, Control Pattern Changer, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 94 in Loader Bucket, Forks, 23 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,443 Hr
CHOIC	E OF 2 - Lot #'s: 13, 14		Asset located in: Humble, TX
13	2017 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FAHWD01616 C/W: Open Operator Station, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92.5 in Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	19	2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FVHWD00240 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket Usage: 5,953 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	сноіс	E OF 2 - Lot #'s: 20, 21
14	2017 Cat 420F2 IT 4x4 Backhoe Loader S/N: CAT0420FHHWD01618 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92 in Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	20	2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FCHWD00205 C/W: Open Operator Station, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 5,886 Hr Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	21	2014 Cat 420FIT 4x4 Backhoe Loader
15	2016 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FKHWD00461 C/W: Open Operator Station, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 96 in Loader Bucket, 25 in Backhoe Digging Bucket Usage: 5,256 Hr		S/N: CAT0420FKJWJ02630 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 5,652 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
16	2016 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FCHWD01301 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket Usage: 4,376 Hr Asset located in: Lake Worth, TX	22	2015 Cat 420F 4x4 Backhoe Loader S/N: CAT0420FVSKR04978 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, 2014 US EPA Label, 92 in Loader Bucket, Quick Coupler, 22 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,681 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
24	2012 Cat 420E 4x4 Backhoe Loader S/N: CAT0420EHDJL03428 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, 86 in Loader Bucket, 24 in Backhoe Digging Bucket, Manual Thumb Usage: 4,236 Hr	33	2018 John Deere 310L EP 4x2 Backhoe Loader S/N: 1T0310ELEJG337511 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 3,151 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	34	2018 John Deere 310L EP 4x2 Backhoe Loader
25	2011 Cat 420E IT 4x4 Backhoe Loader S/N: CAT0420EPDAN01657 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 90 in Multi-Purpose Loader Bucket, 30 in Backhoe Digging Bucket, Thumb Bracket Usage: 6,276 Hr		S/N: 1T0310ELCJG334570 C/W: Open Operator Station, 2018 US EPA Label, 84 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 3,480 Hr Asset located in: Lake Worth, TX
26	Asset located in: Lake Worth, TX 2020 Cat 416F2 4x4 Backhoe Loader	 сноіс	E OF 2 - Lot #'s: 35, 36
20	S/N: CAT0416FTHWB02400 C/W: Open Operator Station, Air Ride Seat, Requires Diesel Exhaust Fluid, 89 in Loader Bucket, 20 in Backhoe Cleanup Bucket Usage: 2,510 Hr Asset located in: Lake Worth, TX	35	2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKKEE263557 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,207 Hr
27	2017 Cat 416F2 4x4 Backhoe Loader		Asset located in: Lake Worth, TX
	S/N: CAT0416FTHWB01148 C/W: Open Operator Station, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 88 in Loader Bucket, 10 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY	36	2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKAEE263368 C/W: Open Operator Station, 90 in Loader Bucket, 16 in Backhoe Digging Bucket Usage: 2,948 Hr Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	37	2012 John Deere 310SJ 4x4 Backhoe Loader
28	2022 Cat 415 4x4 Backhoe Loader S/N: CAT00415HH8A00347 C/W: Open Operator Station, Air Ride Seat, 2022 US EPA Label, 89 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 41 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		S/N: 1T0310SJABD210971 C/W: Enclosed Cab, Air Conditioner, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 92 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,804 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
30	2017 Cat 415F2 4x4 Backhoe Loader S/N: CAT0415FCHWA00473 C/W: Open Operator Station, 88 in Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,258 Hr	38	2016 Case 580N 4x4 Backhoe Loader S/N: JJGN580NJFC717602 C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,827 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	39	2014 Case 580 Super N 4x4 Backhoe Loader
31	2016 John Deere 410L 4x4 Backhoe Loader S/N: 1T0410LXPGF298786 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid, 94 in Loader Bucket, 25 in Backhoe Digging Bucket Usage: 7,966 Hr Asset located in: Lake Worth, TX	Seat, Ride Control, Backhoe Pilot Cor Control Pattern Changer, 2014 US EF	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 2014 US EPA Label, 82 in Loader Bucket, Extendable Stick, 23 in Backhoe Digging Bucket Usage: 3,941 Hr

Lot #	Details	Lot #	Details
40	2013 Case 580N 4x4 Backhoe Loader S/N: JJGN580NLDC581006 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 82 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,697 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	47	2001 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX895009 C/W: Open Operator Station, 2000 US EPA Label, 84 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 7,556 Hr Asset located in: Lake Worth, TX
		48	2008 Case 580 Super M Series 3 4x4 Backhoe Loader
	Asset located in: Lake Worth, TX		S/N: N8C504007
41	2018 JCB 3CX 4x4 Backhoe Loader S/N: JCB3CXTTCJ2667099 C/W: Open Operator Station, 2018 US EPA Label, 86 in Loader Bucket, Quick Coupler, 24		C/W: Enclosed Cab, 82 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 9,616 Hr Asset located in : Lake Worth, TX
	in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 1,433 Hr Asset located in : Humble, TX	49	2003 Case 580M 4x4 Backhoe Loader S/N: JJG0312663 C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket,
42	2012 New Holland B95C 4x4 Backhoe Loader S/N: FNH0B95CNCHH02653 C/W: Open Operator Station, 88 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,544 Hr		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,258 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
43	2005 Cat 430D 4x4 Backhoe Loader S/N: CAT0430DKBML05163 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Hydraulic Coupler, 92 in Loader Bucket, 24 in Backhoe Cleanup Bucket Usage: 7,018 Hr	49A	2018 Case 580SN 4x2 Backhoe Loader S/N: JJGN58SNPJC75003 C/W: Open Operator Station, 81 in, Quick Coupler Usage: 2,055 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	49B	2018 Case 580SN 4x2 Backhoe Loader
44	2005 Cat 420D 4x4 Backhoe Loader S/N: CAT0420DJFDP23675 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 89 in Loader Bucket, 26 in Backhoe Digging Bucket Usage: 5,495 Hr		S/N: JGN58SNCJC753046 C/W: Open Operator Station, Backhoe Pilot Controls, 81 in Loader Bucket, Quick Coupler, 30 in Backhoe Digging Bucket Usage: 3,537 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
45	2008 John Deere 310SJ 4x4 Backhoe Loader S/N: T0310SJ156742 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, Tier 2, 2007 US EPA Label, 92 in Loader Bucket,	50 t 51	2006 Cat 416E 4x2 Backhoe Loader S/N: CAT0416EVSHA00900 C/W: Open Operator Station, Air Ride Seat, 89 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 12,955 Hr Asset located in: Lake Worth, TX
	Extendable Stick, 36 in Backhoe Digging Bucket Usage: 4,508 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.		2008 John Deere 310J 4x2 Backhoe Loader S/N: T0310JX159493 C/W: Open Operator Station, Manual Coupler, 84 in Loader Bucket Usage: 2,804 Hr Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	52	2007 John Deere 310J 4x4 Backhoe Loader
46	2005 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX945350 C/W: Enclosed Cab, Air Conditioner, 86 in Loader Bucket, 18 in Backhoe Digging Bucket Usage: 7,887 Hr Asset located in: Lake Worth, TX		S/N: T0310JX149906 C/W: Open Operator Station, Manual Couple 86 in Loader Bucket, 25 in Backhoe Usage: 2,809 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
53	2005 Case 590 Super M 4x2 Backhoe Loader S/N: N5C394910 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 93 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 4,876 Hr Asset located in: Lake Worth, TX	CHOIC	E OF 2 - Lot #'s: 61, 9606A 2017 Cat 966M Wheel Loader S/N: CAT0966MPKJP02589 C/W: Enclosed Cab, Air Conditioner, Ride
54	2004 Case 580M 4x2 Backhoe Loader S/N: N4C303573 C/W: Open Operator Station, 2004 US EPA Label, 83 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-WATKINS-	Control, Joystick Steering, 2017 Requires Diesel Exhaust Fluid, 2 Auxiliary Hydraulics, Pipe Grapp Usage: 4,818 Hr	Control, Joystick Steering, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 26.5-25 Tires, Auxiliary Hydraulics, Pipe Grapple Usage: 4,818 Hr Asset located in: Bridgeport, NJ
	CONSTRUCTION Usage: 2,191 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	62	2021 Cat 950GC Wheel Loader S/N: CAT00950TM5T04416 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 23.5-25 Tires, 4.5 cyd 114 in Bucket Usage: 1,455 Hr Asset located in: Baton Rouge, LA
55	2016 Kubota L47TLB 4x4 Backhoe Loader S/N: 50136 C/W: Open Operator Station, Manual Coupler, 71 in Loader Bucket, 11 in Backhoe Digging Bucket Usage: 671 Hr Asset located in: Lake Worth, TX	63	2020 Cat 950GC Wheel Loader S/N: CAT00950AM5T03307 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 3.30 m3 116 in Bucket, 23.5-25 Tires Usage: 4,902 Hr Asset located in: Lake Worth, TX
56	2019 John Deere 844K-III Wheel Loader S/N: 1DW844KACJF692631 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick Steering, Loadrite On-Board Scale, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9.3 cyd 144 in Bucket, Auto Lube, 875/65R29 Tires Usage: 9,476 Hr Asset located in: Lake Worth, TX	64 CHOICE 65	2019 Cat 950 M Wheel Loader S/N: CAT0950MVJ1S02214 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 116 in Bucket, Auto Lube, 23.5R25 Tires Usage: 9,296 Hr
 57			Asset located in: Lake Worth, TX
	2015 Cat 980M High Lift Wheel Loader S/N: LKRS00731 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Joystick Steering, loadrite On-Board Scale, 7.5 cyd 135 in Bucket, 29.5R25 Tires Usage: 20,599 Hr Notes: PLEASE SEE SELLER SUPPLIED ENGINE REBUILD INFORMATION IN THE SUPPORTING DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		E OF 2 - Lot #'s: 65, 66 2017 Cat 950MZ Wheel Loader S/N: CAT0950MCHE810302 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 3.40 m3 117 in Bucket, 23.5R25 Tires Usage: 6,932 Hr
58	2018 Case 1121G Wheel Loader S/N: JEEN1121KJF246039 C/W: Enclosed Cab, Air Conditioner, Rear View	66	Asset located in: Lake Worth, TX 2016 Cat 950M Wheel Loader
	Camera, Joystick Steering, 6.1 cyd 126 in Bucket, 26.5R25 Tires Usage: 6,569 Hr Asset located in : Lake Worth, TX	C/W: Enclosed Cab, Air Cond Camera, Air Ride Seat, Ride C 2016 US EPA Label, Requires Fluid, Hydraulic Coupler, 114 R25 Tires, EQUIPMENT-FRON CONSTRUCTION Usage: 6,168 Hr Notes: DEFICIENCIES NOTED THE INSPECTION REPORT	S/N: CAT0950MKEMB02486 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2016 US EPA Label, Requires Diesel Exhaust Fluid Hydraulic Coupler, 114 in Bucket, 23 5
59	2022 Komatsu WA475-10 Wheel Loader S/N: KMTWA142VNNA40104 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4.4 m3 124 in Bucket, Auto Lube, 26.5-25 Tires Usage: 7,012 Hr Asset located in: Lake Worth, TX		R25 Tirés, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,168 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE

Lot #	Details	Lot #	Details
67	2014 Cat 950 K Wheel Loader S/N: CAT0950KTR4A02440 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Traction Control, 2017 US EPA Label, 118 in Bucket, 23.5-25 Tires Usage: 20,054 Hr Asset located in: Lake Worth, TX	76	2019 Volvo L90H Wheel Loader S/N: VCEOL90HL0S624993 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 6,927 Hr
68	2011 Cat 950H Wheel Loader		Asset located in: Lake Worth, TX
	S/N: CAT0950HEJAD00705 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 114 in Bucket, 23.5 R25 Tires Usage: 23,037 Hr Asset located in: Lake Worth, TX	77	2015 Volvo L90G Wheel Loader S/N: VCE0L90GT0S617667 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2014 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires
69	2013 Komatsu WA380-7 Wheel Loader S/N: KMTWA118L36A64146		Usage: 12,859 Hr Asset located in : Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2012 US EPA Label, Hydraulic Coupler, 23.5R25 Tires Usage: 23,049 Hr Asset located in : Lake Worth, TX	78	2016 Cat 938M Wheel Loader S/N: CAT0938MTJ3R02448 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 106 in
70	2018 Volvo L110H Wheel Loader S/N: VCEL110HT0S631498 C/W: Enclosed Cab, Air Conditioner, Rear View		Bucket, 20.5R25 Tires Usage: 19,902 Hr Asset located in: Lake Worth, TX
	Camera, Air Ride Seat, Ride Control, Autoshift, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 118 in Bucket, Forks, 23.5R25 Tires Usage: 6,898 Hr Asset located in: Lake Worth, TX	79	2014 Cat 938K Wheel Loader S/N: CAT0938KPSWL02223 C/W: Enclosed Cab, Rear View Camera, 2013 US EPA Label, 20.5R25 Tires Usage: 21,033 Hr
71	2023 John Deere 644P Wheel Loader S/N: 1DW644PAVPLZ17531 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 23.5R25 Tires, Hydraulic Coupler, 4 cyd 120 in Bucket Usage: 3,296 Hr Asset located in: St. Rose, LA	79A	Asset located in: Lake Worth, TX 2018 Case 621G Wheel Loader S/N: JEEN0621HJF243666 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 102 in Bucket, 20.5x25 Tires Usage: 5,236 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 73, 74	СНОІС	E OF 1 - Lot #'s: 81
73	2014 John Deere 644 K Wheel Loader S/N: 1DW644KZLED661608 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2014 US EPA Label, Forks, 23.5R25 Tires Usage: 15,623 Hr Asset located in: Lake Worth, TX	81	2020 Hyundai HL955 Wheel Loader S/N: HHKHW500AL0000844 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 20.5 R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 4,328 Hr
74	2013 John Deere 644 K Wheel Loader S/N: 1DW644KZKCE650141 C/W: Enclosed Cab, Air Conditioner, Air Ride		Notes: . Asset located in: Lake Worth, TX
	Seat, 2012 US EPA Label, 102 in Bucket, 23.5 R25 Tires Usage: 16,918 Hr Asset located in: Lake Worth, TX	82	2023 John Deere 544P Wheel Loader S/N: 1DW544PALPLX19742 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Autoshift, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 20.5R25 Tires, Auxiliary Hydraulics, Hydraulic Coupler, 3.5 cyd 106 in Bucket Usage: 1,546 Hr Asset located in: Greenville, TX

Lot #	Details	Lot #	Details
85	2007 John Deere 544J Wheel Loader S/N: DW544JZ610127 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, Traction Control, 2006 US EPA Label, CARB Compliant, 3.0 cyd 103 in Bucket, 20.5R25 Tires Usage: 7,496 Hr Asset located in: Midland, TX	93	2017 Komatsu WA320-8 Wheel Loader S/N: KMTWA135JHA085240 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 108 in Bucket, 20.5R25 Tires Usage: 15,207 Hr Asset located in: Lake Worth, TX
87	2020 Hitachi ZW180-6 Wheel Loader	CHOIC	E OF 2 - Lot #'s: 95, 96
СНОІС	S/N: RYUPD860CH8405515 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 104 in Bucket, 23.5R25 Tires Usage: 12,123 Hr Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 88, 89	95	2014 Komatsu WA270-7 Wheel Loader S/N: KMTWA122C01080092 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, 2013 US EPA Label, Hydraulic Coupler, 104 in Bucket, 60 in Forks, 20.5R25 Tires Usage: 8,531 Hr Asset located in: Lake Worth, TX
88	2015 Cat 930M Wheel Loader S/N: CAT0930MKKTG00791 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 11,259 Hr Asset located in: Lake Worth, TX	96	2013 Komatsu WA270-7 Wheel Loader S/N: KMTWA122C01080021 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Hydraulic Coupler, 104 in Bucket, 60 in Forks, Auto Lube, 20.5R25 Tires Usage: 11,558 Hr Asset located in: Lake Worth, TX
89	2014 Cat 930K Wheel Loader	СНОІС	E OF 1 - Lot #'s: 98
	S/N: CAT0930KTRHN03712 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 101 in Bucket, Forks, 20.5 R25 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 10,745 Hr Asset located in: Livingston, LA	98	2013 Cat 924K Wheel Loader S/N: CAT0924KLPWR01641 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2012 US EPA Label, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires Usage: 8,775 Hr
90	2012 Cat 930K Wheel Loader		Asset located in: Lake Worth, TX
01	S/N: CAT0930KHRHN00708 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 110 in Bucket, Forks, 20.5R25 Tires Usage: 12,980 Hr Asset located in: Lake Worth, TX	99	2012 Volvo L60G Wheel Loader S/N: VCE0L60GH00001263 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 11,335 Hr
91	2012 Cat 930 H Wheel Loader S/N: CAT0930HEDHC03679		Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Ride Seat, Auxiliary Hydraulics, Hydraulic Coupler, 101 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 12,460 Hr Asset located in: Lake Worth, TX	100	2014 Cat IT14G2 Wheel Loader S/N: CATIT14GLERP00499 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.40 m3 94 in Bucket, Forks, 17.5-25 Tires
92	2012 Volvo L70G Wheel Loader		Usage: 2,976 Hr Asset located in : Lake Worth, TX
	S/N: VCE0L70GC00002431 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires Usage: 33,042 Hr Asset located in: Lake Worth, TX	101	2022 Bobcat L85 Wheel Loader S/N: B53C11128 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 405/70R18 Tires Usage: 1,595 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
103	2018 Cat 908M Wheel Loader S/N: CAT0908MEH8803041 C/W: Enclosed Cab, Air Conditioner, 78 in Grapple Bucket, Solid Tires Usage: 10,102 Mi Asset located in: Lake Worth, TX	112	2000 Cat 938G Wheel Loader S/N: 4YS01303 C/W: Enclosed Cab, Air Conditioner, 2000 US EPA Label, 110 in Bucket, Forks, 20.5R25 Tires Usage: 12,027 Hr Asset located in: Lake Worth, TX	
СНОІС	CHOICE OF 2 - Lot #'s: 105, 106		1985 Cat 966D Wheel Loader S/N: 99Y04055 C/W: Enclosed Cab, Manual Coupler, Forks, 26.5-25 Tires	
105	2023 Cat 906 Wheel Loader (Unused) S/N: CAT00906HHZ600672		Usage: 5,678 Hr Asset located in: Lake Worth, TX	
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2023 US EPA Label, Hydraulic Coupler, 70 in Forks, 405/70R18 Tires, 25 MPH Machine Usage: 27 Hr Asset located in : Humble, TX	114 114A 115	1989 Cat 950 E Wheel Loader S/N: 22Z04456 C/W: Open Operator Station, Hydraulic Coupler, 110 in Bucket, Forks, 23.5-25 Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5.198 Hr	
106	2023 Cat 906 Wheel Loader (Unused) S/N: CAT00906CHZ601041 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2023 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 74 in		LOADER FORKS ; PLEASE SEE A PERSO NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	Notes: LOT 5887 FITS THIS MACHINE - WHEEL LOADER FORKS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE
	Bucket, Forks, 405/70R18 Tires, 25 MPH Machine Usage: 3 Hr Asset located in : Humble, TX		1998 Cat IT28G Wheel Loader S/N: 8CR01014 C/W: Enclosed Cab, Air Conditioner, Ride Control, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5-25 Tires Usage: 18,294 Hr Asset located in: Lake Worth, TX	
107	2017 Cat 906M Wheel Loader S/N: CAT0906MKH6602101 C/W: Open Operator Station, 2011 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler,			
	1.6 cyd 82 in Bucket, 340/80R18 Tires Usage: 3,249 Hr Asset located in: Midland, TX		1998 Case 621B Wheel Loader S/N: JEE0055157 C/W: Enclosed Cab, Air Conditioner, 1997 US	
108	2006 Volvo L110E Wheel Loader S/N: L110EV61151 C/W: Enclosed Cab, 2006 US EPA Label,		Coupler, 100 in Bucket, 20.5R25 Tire Usage: Not Available	EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: Not Available Asset located in : Lake Worth, TX
	Hydraulic Coupler, 112 in Bucket, 23.5R25 Tires Usage: 9,676 Hr Asset located in : Lake Worth, TX	123	2011 John Deere 872GP AWD Motor Grader S/N: 1DW872GPCBE636116	
109	2005 Cat 924G Wheel Loader S/N: CAT0924GJDDA02066 C/W: Enclosed Cab, Air Conditioner, Autoshift, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires		ft / 4.88 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Usage: 7,669 Hr	Seat, Differential Lock, 2011 US EPA Label, 16 ft / 4.88 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires
	Usage: 14,142 Hr Asset located in : Lake Worth, TX		BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	
110	1990 Cat 980C Wheel Loader S/N: 63X09341 C/W: Enclosed Cab, Air Conditioner, 29.5R25 Tires Usage: Not Available Asset located in: Lake Worth, TX		THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY	
111	2000 Cat 966G Wheel Loader S/N: 3SW00657 C/W: Enclosed Cab, 128 in Bucket, 26.5-25 Tires Usage: 23,327 Hr Asset located in: Lake Worth, TX		EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTIC PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
124	2019 Cat 140M3 Motor Grader S/N: CAT0140MKN9D01607 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 6,884 Hr Asset located in: Lake Worth, TX	133	2015 John Deere 772GP AWD Motor Grader S/N: 1DW772GPLFF667809 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 6,172 Hr Asset located in: Lake Worth, TX 2019 John Deere 672G Motor Grader
125	2017 Cat 140M3 Motor Grader S/N: CAT0140MJN9D00717 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires	135	S/N: 1DW672GXCKF693988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Differential Lock, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 5,387 Hr Asset located in: Lake Worth, TX 2015 John Deere 672G AWD Motor Grader
126	Usage: 10,845 Hr Asset located in: Lake Worth, TX 2016 Cat 140M3 Motor Grader S/N: CAT0140MHN9M00322 C/W: Enclosed Cab, Air Conditioner, Air Ride	136	S/N: 1DW672GXHEF665845 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Differential Lock, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 6,673 Hr
	Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Ripper, 17.5R25 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 9,287 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2013 John Deere 672GP AWD Motor Grader S/N: 1DW672GPHDE651559 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Accumulator
127	2015 Cat 140M3 Motor Grader S/N: CAT0140MLN9D00447 C/W: Enclosed Cab, Air Conditioner, Low		Combination Ripper/Scarifier, 17.5R25 Tires Usage: 7,517 Hr Asset located in : Lake Worth, TX
	Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires Usage: 5,571 Hr	137	2012 John Deere 672G AWD Motor Grader S/N: 1DW672GPKCE643998 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 12,634 Hr
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
128	2015 Cat 140M3 Motor Grader S/N: CAT0140MQN9D00463 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Pre- Wired for Grade Control, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper /Scarifier, Rear Auxiliary Hydraulics, 17.5R25	139	2012 Case 865B Motor Grader S/N: HBZN0865TCAF01360 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 2,653 Hr Asset located in: Lake Worth, TX
	Tires, EQUIPMENT-FRÓM-Á-PRIMORIS- SERVICES-CORP-COMPANY Usage: 11,666 Hr Asset located in : Lake Worth, TX	140	2013 LeeBoy 785 Motor Grader S/N: 413760-141 C/W: Enclosed Cab, Front Scarifier, 15.5-25 Tires
132	2011 Cat 140M2 VHP Plus Motor Grader S/N: CAT0140MEM9D00692		Usage: 3,051 Hr Asset located in : Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, 2011 US EPA Label, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 14.00-24 Tires, Topcon GX-60 Display, Topcon 3D MC-R3 Radio Receiver, Topcon MC2 Sensors with Masts Usage: 9,084 Hr Asset located in: Lake Worth, TX	142	1991 Cat 120G Motor Grader S/N: 87V09411 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, 14.00-24 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
142A	1991 Champion 740A Motor Grader S/N: 21849 C/W: Enclosed Cab, 1991 US EPA Label, 14 ft / 4.27 m Moldboard, Front Auxiliary Hydraulics, 14.00R24 Tires Usage: 4,668 Hr Asset located in: Lake Worth, TX	149	2017 Bell B50E Articulated Dump Truck S/N: B93A650EA01105727 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Steel Body Liner, 875 /65R29 Tires Usage: 9,289 Hr Asset located in: Lake Worth, TX
143	2022 John Deere 460E-II Articulated Dump		
	Truck S/N: 1DW460EBJNF713715 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Tailgate, 29.5R25 Tires Usage: 4,497 Hr	CHOIC 150	E OF 3 - Lot #'s: 150, 151, 152 2022 Komatsu HM400-5 Articulated Dump Truck
СНОІС	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 144, 145		S/N: KMTHM016JMD012108 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 4,566 Hr
144	2020 Cat 745 Articulated Dump Truck		Asset located in: Lake Worth, TX
	S/N: CAT00745P3T602347 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 5,300 Hr Asset located in : Humble, TX	151	2021 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016HMD011998 C/W: Air Conditioner, Engine Brake, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 4,217 Hr
145	2018 Cat 745 Articulated Dump Truck		Asset located in: Lake Worth, TX
	S/N: CAT00745V3T600426 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2017 US EPA Label, Tailgate, Steel Body Liner, Auto Lube, 29.5R25 Tires Usage: 6,080 Hr Asset located in: Humble, TX	152	2021 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016LMD011997 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 4,708 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 146, 147, 148	152A	2022 Komatsu HM400-5 Articulated Dump
146	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CVTFK00176 C/W: Air Conditioner, Retarder, Engine Brake, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner, 29.5R25 Tires Usage: 14,026 Hr Asset located in: Lake Worth, TX		Truck S/N: KMTHM016KMD012141 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 29.5R25 Tires Usage: 3,235 Hr Asset located in: Lake Worth, TX
147	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CATFK00437 C/W: 29.5R25 Tires Usage: 13,799 Hr Asset located in: Lake Worth, TX	153	2017 Bell B40E Articulated Dump Truck S/N: B93A640EJ01105751 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 29.5R25 Tires Usage: 7,600 Hr
148	2015 Cat 745C Articulated Dump Truck		Asset located in: Humble, TX
	S/N: CAT0745CHTFK00280 C/W: Air Conditioner, Engine Brake, Air Ride Seat, 2015 US EPA Label, 29.5R25 Tires Usage: 13,904 Hr		E OF 2 - Lot #'s: 154, 155
	Asset located in: Lake Worth, TX	154	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BHT4R01959 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2013 US EPA Label, 29.5R25 Tires Usage: 10,492 Hr

155			Details
155	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BKT4R01967 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2017 US EPA Label, CARB Compliant, 29.5R25 Tires Usage: 10,336 Hr	163	2007 John Deere 250D Articulated Dump Truck S/N: DW250DT611160 C/W: Air Conditioner, 23.5R25 Tires Usage: 14,758 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	164	2007 Cat 725 Articulated Dump Truck
	E OF 4 - Lot #'s: 156, 157, 158, 159		S/N: CAT00725HB1L01150 C/W: Air Conditioner, 2007 US EPA Label, Tailgate, 23.5R25 Tires Usage: 9,403 Hr Asset located in : Lake Worth, TX
156	2015 Terex TA300 Articulated Dump Truck S/N: A11861079 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Steel Body Liner, 23.5R25 Tires Usage: 7,974 Hr Asset located in: Lake Worth, TX	165	2007 Cat 735 Articulated Dump Truck S/N: CAT00735AB1N01005 C/W: Air Conditioner, Retarder, Steel Body Liner, 26.5R25 Tires Usage: 22,553 Hr Asset located in: Lake Worth, TX
157	2015 Terex TA300 Articulated Dump Truck S/N: A11861065 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Steel Body Liner, 23.5R25 Tires Usage: 8,896 Hr Asset located in: Lake Worth, TX	166	Cat D35C Articulated Dump Truck S/N: Not Available C/W: Air Conditioner, Air Ride Seat, 26.5R25 Tires Usage: 9,124 Hr Asset located in: Lake Worth, TX
158	2014 Terex TA300 Articulated Dump Truck S/N: A11001282 C/W: Air Conditioner, Retarder, Rear View Camera, Steel Body Liner, 23.5R25 Tires Usage: 8,693 Hr	– 167	Cat D250E Articulated Dump Truck S/N: 5TN01384 C/W: Air Conditioner, 23.5R25 Tires Usage: 13,304 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	168	2017 Cat 631K Motor Scraper
159	2014 Terex TA300 Articulated Dump Truck S/N: A11001278 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 23.5R25 Tires Usage: 8,343 Hr Asset located in: Lake Worth, TX		S/N: CAT0631KVWTR00117 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 37.25R35 Tires Usage: 8,898 Hr Asset located in: Midland, TX
160	2007 Terex TA30 Articulated Dump Truck	СНОІС	E OF 2 - Lot #'s: 169, 170
	S/N: A8941541 C/W: Air Conditioner, 23.5R25 Tires Usage: 11,472 Hr Asset located in: Lake Worth, TX	169	2006 Cat 621G Motor Scraper S/N: CAT0621GPDBB00312 C/W: Enclosed Cab, Air Conditioner, 33.25R29
161	2006 Terex TA27 Articulated Dump Truck S/N: A8681159 C/W: Air Conditioner, Steel Body Liner, 23.5R25 Tires		Tires Usage: 17,540 Hr Asset located in: Lake Worth, TX
	Usage: 5,855 Hr Asset located in : Lake Worth, TX	170 2006 Cat 621G Motor Scraper S/N: CAT0621GTDBB00311	S/N: CAT0621GTDBB00311
162	2019 John Deere 260E Articulated Dump Truck S/N: 1DW260ETCKF697666 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Heated Body, Tailgate, 23.5R25 Tires Usage: 4,508 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, 33.25-29 Tires Usage: 18,093 Hr Asset located in : Lake Worth, TX
		171	2004 Cat 615C Series II Elevating Motor Scraper
			S/N: CAT0615CE9XG01708 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 29.5R29 Tires Usage: 7,020 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
173	2016 John Deere 9620R Articulated Tractor S/N: 1RW9620RPGE052942 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, Autosteer, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade, 6 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Rear Wheel Weights Usage: 5,943 Hr Asset located in: Lake Worth, TX	181	2023 Cat D8 Crawler Dozer S/N: CAT000D8AAW800429 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 153 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank Ripper w/Hydraulic Pin Puller Usage: 1,311 Hr Asset located in: Lake Worth, TX	
175	2016 John Deere 9570R Articulated Tractor S/N: 1RW9570RCGP052988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, Autosteer, Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade, LED Lights, 5 Rear Remotes, Auxiliary Hydraulics, ISOBUS, Dual IF800/70R38 Tires, Rear Wheel Weights, Front Wheel Weights Usage: 7,520 Hr		2012 Cat D8T Crawler Dozer S/N: CAT00D8TKMLN01612 C/W: Enclosed Cab, Air Conditioner, 153 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank Ripper Usage: 11,995 Hr Asset located in: Lake Worth, TX 2006 Cat D7R LGP Crawler Dozer S/N: CAT00D7RLABJ01502	
176	Asset located in: Lake Worth, TX 2014 Case IH Steiger 580S Scraper Tractor S/N: ZEF300648 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 16 Forward 2 Reverse, Requires Diesel Exhaust Fluid, 6 Rear Remotes,	186	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2006 US EPA Label, 192 in Wide Angle Blade w/ Dual Tilt, 36 in Single Grouser Track Shoes, Allied Winch Usage: 7,907 Hr Asset located in: Lake Worth, TX	
	ISOBUS, Scraper Hitch, Dual 710/70R42 Front Tires, Front Wheel Weights, Dual 710/70R42 Rear Tires Usage: 3,479 Hr Notes: FEBRUARY 2023 - COMPLETE DEALER INSTALLED LONG BLOCK ENGINE; UNIT WAS PULLING K-TEC 1233 SCRAPER - ALSO IN THE AUCTION LOT 176; NEW PTO DRIVEN WATER PUMP; NEW BOOM HOSES AND CLAMPS Asset located in: Lake Worth, TX		2023 Cat D6 LGP Crawler Dozer S/N: CAT000D6LRDC01363 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 156 in Wide PAT Blade, 36 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 627 Hr	
177	2017 MTS MT42LGP 4 Tire Hydraulic Pull Scraper S/N: MT42LGP00287 C/W: 29.5R29, Rear Hydraulic Outlets Usage: Not Available		THROUGH NOVEMBER 202 PLEASE SEE A PERSONAL I SELLER IN THE DOCUMENT Asset located in: Lake Wort	Notes: EMISSIONS SYSTEM WARRANTY THROUGH NOVEMBER 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
178	Asset located in: Lake Worth, TX 2015 K-TEC 1233 4 Tire Ejector Pull Scraper S/N: KS2538 C/W: 33 cyd Capacity, Lead Scraper, 26.5R25 Tires, Rear Hydraulic Outlets Usage: Not Available Notes: UNIT WAS BEING PULLED BY CASE STEIGER 580S - ALSO IN AUCTION LOT 176; NEW PTO DRIVEN WATER PUMP; NEW BOOM HOSES AND CLAMPS Asset located in: Lake Worth, TX		S/N: CAT000D6KD5M01006 C/W: Enclosed Cab, Air Conditioner, A Seat, Pre-Wired for Grade Control, 202 EPA Label, Requires Diesel Exhaust Fl Sweeps, 144 in Wide PAT Blade, 24 in	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 144 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 811 Hr
179	1994 Cat 621F Water Wagon S/N: 4SK00164 C/W: Enclosed Cab, Air Conditioner, In-Cab Remote Controlled Water Cannon, Rear Spray, Side Spray, 83.25-29 Tires Usage: 8,377 Hr Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details	
СНОІС	E OF 2 - Lot #'s: 188, 189	193	2019 Cat D6T XW Crawler Dozer S/N: CAT00D6TEJNM00566 C/W: Enclosed Cab, Air Conditioner, Rear View	
188	2022 Cat D6 XL Crawler Dozer S/N: CAT000D6CRBP01052 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 144 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,172 Hr Notes: EMISSIONS SYSTEM WARRANTY		Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 160 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,211 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	
	THROUGH JULY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	194	2019 Cat D6T XL Crawler Dozer S/N: CAT00D6TCNDY00513 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, US	
189	2022 Cat D6 XL Crawler Dozer S/N: CAT000D6TRBP01067 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 137 in Wide PAT Blade, 24 in Single Grouser		EPA Label, Requires Diesel Exhaust Fluid, 125 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 4,082 Hr Asset located in: Lake Worth, TX	
	Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,538 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	195	2019 Cat D6T XL Crawler Dozer S/N: CAT00D6THHYT00409 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 152 in Wide PAT Blade, 22 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 4,693 Hr	
CHOIC	E OF 3 - Lot #'s: 190, 191, 192	106	Asset located in: Lake Worth, TX 2018 Cat D6T XL Crawler Dozer	
190	2020 Cat D6 Crawler Dozer S/N: CAT000D6ESA900371 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide Semi-U Blade w/ Single Tilt, 23 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics Usage: 2,769 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	196	S/N: CAT00D6TJ2I C/W: Enclosed Cab Camera, Air Ride Sc Control, 2018 US E Exhaust Fluid, Swe Blade w/ Single Tile Shoes, 1 Cylinder N EQUIPMENT-FROM Usage: 2,831 Hr EE Notes: ; PLEASE SE FROM THE SELLER	S/N: CAT00D6TJ2B300199 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION
 191	2020 Cat D6 Crawler Dozer	-	Asset located in: Lake Worth, TX	
	S/N: CAT000D6CSA900372 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes Usage: 3,462 Hr Asset located in: Bridgeport, NJ	197	2018 Cat D6T XL Crawler Dozer S/N: CAT00D6TCNDY00387 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
192	2019 Cat D6 Crawler Dozer S/N: CAT000D6KHNK00387 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, GRADE with 3D, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes Usage: 4,017 Hr Asset located in: North East, MD		Usage: 3,768 Hr Notes: NEW RAILS, TRACK PADS, SPROCKET SEGMENTS, AND TOP ROLLERS INTALLED DECEMBER 3RD 2024; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
198	2018 Cat D6T XW Crawler Dozer S/N: CAT00D6TVJNM00416 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 163 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 8,360 Hr Asset located in: Lake Worth, TX	204	2023 Cat D5 LGP Crawler Dozer S/N: CAT000D5KZ6A01796 C/W: Enclosed Cab, Air Conditioner, Rear Viev Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 160 in Wide PAT Blade, 33 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper
200	2013 Cat D6T XL Crawler Dozer S/N: CAT00D6TCDTD01184 C/W: Enclosed Cab, Air Conditioner, Sweeps, 150 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION	205	Usage: 878 Hr Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH APRIL 2026 OR 5,000 HOURS; DECEMBER 9TH EGR REPLACED Asset located in: Lake Worth, TX
	Usage: 4,275 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		2022 Cat D5 Crawler Dozer S/N: CAT000D5AZ2K01218 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 127 in Wide PAT Blade, 22.5 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper
201	2013 Cat D6T XL Crawler Dozer S/N: CAT00D6TAGMK01351		Usage: 1,409 Hr Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Sweeps, 127 in Wide Semi-U Blade w/ Single Tilt, 22 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 8,504 Hr Asset located in: Lake Worth, TX		2019 Cat D6N XL Crawler Dozer S/N: CAT00D6NENJN00388 C/W: Enclosed Cab, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps 128 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper
202	2012 Cat D6T XL Crawler Dozer S/N: CAT00D6TCDTD00253		Usage: 8,394 Hr Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Sweeps, 152 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,059 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	207	2015 Cat D6N LGP Crawler Dozer S/N: PBA02428 C/W: Enclosed Cab, Air Conditioner, 2014 US EPA Label, Sweeps, 160 in Wide PAT Blade, 9 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 10,608 Hr
	Asset located in: Lake Worth, TX		Asset located in: Livingston, LA
203	2011 Cat D6T XL Crawler Dozer S/N: CAT00D6TCGMK00352 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2011 US EPA Label, Sweeps, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,782 Hr	208	2012 Cat D6N XL Crawler Dozer S/N: CAT00D6NALJR00640 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 132 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 10,669 Hr Asset located in: Lake Worth, TX
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	209	2011 Cat D6N XL Crawler Dozer S/N: CAT00D6NELJR00562 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 126 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 18,107 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
210	2008 Cat D6N LGP Crawler Dozer S/N: DJY01194 C/W: Open Operator Station, 2008 US EPA	сноіс	E OF 3 - Lot #'s: 216, 217, 218
	Label, 160 in Wide PAT Blade, 24 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, Rear Auxiliary Hydraulics, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,289 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	216	2019 Komatsu D65WX-18 Crawler Dozer S/N: KMT0D127PKA091866 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Carco Winch, 30 in Single Grouser Track Shoes, PLUS Undercarriage Usage: 1,389 Hr Notes: LOADOUT BY APPOINTMENT ONLY;
211	2007 Cat D6R XL Series III Crawler Dozer S/N: CAT00D6RCGJB00986 C/W: Enclosed Cab, Air Conditioner, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single		ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK
	Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 9,162 Hr Asset located in : Lake Worth, TX	217	2019 Komatsu D65WX-18 Crawler Dozer S/N: 91854 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires
212	2014 Komatsu D155AX-7 Crawler Dozer S/N: KMT0D118L02090176 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, 2013 US EPA Label, 156 in Wide Sigmadozer w/ Dual Tilt, 2 Cylinder Single-Shank Ripper, Sweeps, 24 in Single Grouser Track Shoes Usage: 9,795 Hr		Diesel Exhaust Fluid, 153 in Wide PAT Blade, Carco H85-178VKOMD65-17/18 Winch, 30 in Single Grouser Track Shoes Usage: 1,872 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK
213	Asset located in: Poteau, OK 2018 John Deere 950K LGP Crawler Dozer S/N: 1T0950KPPJF332504 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 185 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Carco Winch Usage: 5,936 Hr Asset located in: Lake Worth, TX	218	2018 Komatsu D65WX-18 Crawler Dozer S/N: 91248 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Allied H6H Winch, 30 in Single Grouser Track Shoes Usage: 2,060 Hr
СНОІС	E OF 2 - Lot #'s: 214, 215		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
214	2019 John Deere 850L LGP Crawler Dozer S/N: 1T0850LXJKF360852 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 194 in Wide Angle Blade w/ Dual Tilt, Carco Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 1,640 Hr Asset located in: Robstown, TX	219	Asset located in: McAlester, OK 2015 Komatsu D65WX-17 Crawler Dozer S/N: KMT0D117E01002551 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 159 in Wide PAT Blade, 30 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 13,875 Hr
215	2019 John Deere 850L LGP Crawler Dozer S/N: 1T0850LXTKF359972 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 195 in Wide Straight Blade w/ Dual Tilt, Carco H85-178V Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 2,054 Hr Asset located in: Baytown, TX	220	Asset located in: Lake Worth, TX 2008 Komatsu D65EX-15E0 Crawler Dozer S/N: 70954 C/W: Enclosed Cab, Air Conditioner, 135 in Wide Semi-U Blade w/ Single Tilt, Winch, Sweeps, 24 in Single Grouser Track Shoes Usage: 6,584 Hr Asset located in: Poteau, OK

Lot #	Details	Lot #	Details
221	2022 John Deere 750L Crawler Dozer S/N: 1T0750LXCNF415326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 155 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,349 Hr Asset located in: Lake Worth, TX	228	E OF 2 - Lot #'s: 228, 229 2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKTMF401153 C/W: Open Operator Station, US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide 18 in Single Grouser Track Shoes Usage: 469 Hr
221A	2022 John Deere 750L Crawler Dozer S/N: 1T0750LXJNF417535 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 5,287 Hr Asset located in: Lake Worth, TX	229	Asset located in: Lake Worth, TX 2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKPMF392830 C/W: Enclosed Cab, Air Conditioner, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank
222	2019 John Deere 750K LGP Crawler Dozer S/N: 1T0750KXAKF365020 C/W: Enclosed Cab, Air Conditioner, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 5,330 Hr Asset located in: Lake Worth, TX		Ripper Usage: 1,549 Hr Asset located in: Lake Worth, TX 2019 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKKKF349894 C/W: Enclosed Cab, Air Conditioner, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single
224	2017 John Deere 700K Crawler Dozer S/N: 1T0700KXCHF313276 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 2 Cylinder Multi-Shank Ripper, 560 mm Single Grouser Track Shoes Usage: 4,035 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	231	Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,283 Hr Asset located in: Lake Worth, TX 2017 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKAHF307207 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics Usage: 8,434 Hr Asset located in: Lake Worth, TX
225	2013 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US EPA Label, 142 in Wide PAT Blade, 30 in Single Grouser Track Shoes Usage: 2,583 Hr Asset located in: Lake Worth, TX	232 233	2017 John Deere 650KLGP Crawler Dozer S/N: 1T0650KKTHF316190 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT
226	2012 Cat D6K XL Crawler Dozer S/N: CAT00D6KHFBH02165 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 132 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 4,856 Hr Asset located in: Lake Worth, TX		Blade, 24 in Single Grouser Track Shoes, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 7,369 Hr Asset located in: Humble, TX 2017 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKHHF316153 C/W: Enclosed Cab, Air Conditioner, Pre-Wired
227	2022 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKCNF421869 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 27.5 in Single Grouser Track Shoes Usage: 1,047 Hr Asset located in: Beaumont, TX		for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide Blade, 24 in Single Grouser Track Shoes, Drawbar, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 8,590 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
234	2013 Komatsu D61PX-23 Crawler Dozer S/N: 30310 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2013 US EPA Label, 156 in Wide PAT Blade, Allied H6H Winch, 34 in Single Grouser Track Shoes Usage: 5,210 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	240	2016 Cat D4K2 LGP Crawler Dozer S/N: CAT00D4KJKR202288 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 121 in Wide PAT Blade, 25 in Single Grouser Track Shoes, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 5,218 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
235	2012 Cat D5K2 XL Crawler Dozer S/N: CAT0D5K2VKWW00232 C/W: Open Operator Station, 2012 US EPA Label, 106 in Wide PAT Blade, 20 in Single Grouser Track Shoes Usage: 7,645 Hr	CHOIC 241	E OF 2 - Lot #'s: 241, 242 2012 Cat D4K2 XL Crawler Dozer
236	Asset located in: Lake Worth, TX 2016 Cat D5K2 LGP Crawler Dozer S/N: CAT00D5KKKY202228 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 124 in Wide PAT Blade, 26 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-	242	S/N: CAT0D4K2CKMM00228 C/W: Open Operator Station, Air Ride Seat, 2012 US EPA Label, Sweeps, 114 in Wide PAT Blade, 18 in Single Grouser Track Shoes, SystemOne Undercarriage, 2 Cylinder Multi- Shank Ripper Usage: 3,515 Hr Asset located in: Lake Worth, TX
	PULICE-CONSTRUCTION Usage: 12,759 Hr Asset located in: Humble, TX		2011 Cat D4K XL Crawler Dozer S/N: CAT00D4KHMMM00764 C/W: Open Operator Station, Air Ride Seat,
237	2012 Cat D5K2 LGP Crawler Dozer S/N: CAT0D5K2HKYY00309 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 125 in Wide PAT Blade, 26 in Single Grouser Track Shoes		in Single Grouser Track Shoes, Shank Ripper Usage: 2,915 Hr
	Usage: 9,847 Hr Asset located in : Lake Worth, TX	243	2008 Cat D4K XL Crawler Dozer S/N: CAT00D4KLMMM00181
238	2019 John Deere 450K LGP Crawler Dozer S/N: 1T0450KXKKF347727 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 114 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 2,420 Hr		C/W: Open Operator Station, Air Rid Sweeps, 115 in Wide PAT Blade, 18
	Asset located in: Humble, TX	244	2021 Cat D1 Crawler Dozer S/N: CAT000D1EXKF00156
239	2021 Cat D2 Crawler Dozer S/N: CAT000D2TXKM00230 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 116 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 2,453 Hr		C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 115 in Wide PAT Blade, 16 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,144 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	245	2005 John Deere 700J XLT Crawler Dozer S/N: T0700JX110023 C/W: Enclosed Cab, Air Conditioner, 2005 US EPA Label, 120 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 246, 247	сноіс	E OF 3 - Lot #'s: 252, 253, 254
246	2005 Cat D5G LGP Crawler Dozer S/N: CAT00D5GVRKG01267 C/W: Open Operator Station, 127 in Wide PAT Blade, 24 in Single Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX	252	1977 Cat 561C Pipelayer w/ 2007 Conversion S/N: 92J776 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft 0 in Side Boom, Hydraulic Hoists Usage: 997 Hr
247	2004 Cat D5G LGP Crawler Dozer S/N: CAT00D5GARKG01013 C/W: Open Operator Station, Sweeps, 120 in Wide PAT Blade, 18 in Single Grouser Track		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	Shoes Usage: 5,087 Hr Asset located in: Lake Worth, TX	253	1975 Cat 561C Pipelayer S/N: 92J593 C/W: 3 Lever Boom Control, 18 in Single
249	1996 Cat D6E Crawler Dozer S/N: 2MJ02195 C/W: Open Operator Station, 146 in Wide Straight Blade w/ Dual Tilt, Winch, 560 mm Single Grouser Track Shoes Usage: 10,574 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK		Grouser Track Shoes, 25 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 539 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
		254 1973 Cat 561C Pipelayer S/N: 92J413 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom, Hydraulic Hoists Usage: 903 Hr Notes: ITEM AT OFFSITE LOCATION MUST E PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	S/N: 92J413 C/W: 3 Lever Boom Control, 20 in Single
250			Hydraulic Hoists Usage: 903 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.
	Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.	CHOIC 255	E OF 2 - Lot #'s: 255, 256 1969 Cat 561C Pipelayer w/ Midwestern
251	Asset located in: Lahoma, OK 2008 John Deere 700J Combination Pipelayer w/ 2008 Midwestern M540 Conversion S/N: T0700JX156344 C/W: Canopy, 3 Lever Boom Control, 2007 US EPA Label, Hydraulic Hoists, 30 in Single Grouser Track Shoes Usage: 6,999 Hr Notes: COMES WITH IRONCLAD ASSURANCE.		M561C Conversion S/N: 92J233 C/W: 3 Lever Boom Control, 510 mm Single Grouser Track Shoes, 20 ft 0 in Side Boom, Mechanical Hoists Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	256	1969 Cat 561C Pipelayer S/N: 92J238 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom, Hydraulic Hoists Usage: 1,795 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
257	7 1982 Cat D5B Pipelayer S/N: 44X01116 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 17 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 52 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE	262	2021 John Deere 755K Crawler Loader S/N: 1T0755KXPMF399113 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,525 Hr Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK	263	2021 John Deere 755K Crawler Loader S/N: 1T0755KXKMF400262 C/W: Enclosed Cab, Air Conditioner, Requires
	E OF 2 - Lot #'s: 258, 259		Diesel Exhaust Fluid, Manual Coupler, 94 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 6,008 Hr
258	1971 Cat D4D Pipelayer w/ Midwestern D4D		Asset located in: Lake Worth, TX
	Conversion S/N: 60J2695 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft 0 in Side Boom, Hydraulic Hoists, Winch Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	264	2021 John Deere 755K Crawler Loader S/N: 1T0755KXVMF409838 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, 95 in Bucket, 22 in Double Grouser Track Shoes, Multi-Shank Ripper Usage: 5,530 Hr Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK	265	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF411719
259	1966 Cat D4D Pipelayer w/ Midwestern 0D4D Conversion S/N: 86A1705 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft Side Boom, Hydraulic Hoists Usage: 6,536 Hr		C/W: Enclosed Cab, Requires Diesel Exhaust Fluid, 99 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,012 Hr Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	CHOIC	E OF 2 - Lot #'s: 266, 267
	SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in : Lahoma, OK	266 	2017 John Deere 605K Crawler Loader S/N: 1T0605KXCHE310174
260	1956 Cat D7C Pipelayer w/ Conversion S/N: 17A4488 C/W: 560 mm Single Grouser Track Shoes, 20		C/W: Open Operator Station, Air Ride Seat, 88 in Bucket, 18 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,822 Hr
	ft Side Boom, Mechanical Hoists Usage: Not Available		Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	267	2017 John Deere 605K Crawler Loader S/N: 1T0605KXPHE310856 C/W: Open Operator Station, Air Ride Seat, 88 in Bucket, 18 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper
СНОІС	E OF 5 - Lot #'s: 261, 262, 263, 264, 265		Úsage: 1,632 Hr Asset located in : Lake Worth, TX
261	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF402857 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 101 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: Not Available Asset located in: Lake Worth, TX	268	2015 Cat 963D Crawler Loader S/N: CAT0963DTLCS02294 C/W: Enclosed Cab, Air Conditioner, 101 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,156 Hr Asset located in: Lake Worth, TX
Ripper Usage: No		269	2005 Cat 963C Crawler Loader S/N: CAT0963CCBBD01372 C/W: Enclosed Cab, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 24,275 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
269A	2004 Cat 963C Crawler Loader S/N: CAT0963CPBBD00676 C/W: Enclosed Cab, Air Conditioner, Manual Coupler, 100 in Bucket, 22 in Double Grouser Track Shoes Usage: 11,701 Hr Asset located in: Lake Worth, TX	277	2003 Cat CP-433E Padfoot Drum Compactor S/N: CATCP433JCFK00238 C/W: Open Operator Station, 2003 US EPA Label, Perkins 3PKXL03.9AKI 4 Cylinder 74.5 kW 3.99 L Diesel Engine, 66 in Drum, Leveling Blade Usage: 1,105 Hr Asset located in: Lake Worth, TX	
271	2009 Cat 939C Crawler Loader S/N: CAT0939CC6DS02032 C/W: Open Operator Station, 84 in Multi- Purpose Bucket, 18 in Double Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 2,351 Hr Asset located in: Lake Worth, TX	278	2014 Bomag BW145PDH Padfoot Drum Compactor S/N: 101586021003 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2014 US EPA Label, Kubota v3307 4 Cylinder 37 kW 3.3 L Diesel Engine, 60 in Drum Usage: Not Available	
272	2007 Cat 815F Soil Compactor S/N: CAT0815FCBYN00307		Asset located in: Lake Worth, TX	
	C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, 38 in Compaction Wheel Width, 146 in Straight Blade w/ Single Tilt, Fast Fuel Usage: 10,824 Hr Asset located in: Lake Worth, TX	279	2007 Bomag BW145PDH-3 Padfoot Drum Compactor S/N: 901581491236 C/W: Open Operator Station, Diesel Engine, 58 in Drum Usage: 616 Hr	
273	2013 Hamm 3410P Padfoot Drum Compactor S/N: H1791920 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Deutz TCD2012L042V 134 hp 4.03 L Diesel Engine, 84 in Drum Usage: 6,559 Hr Asset located in: Lake Worth, TX	280	Asset located in: Lake Worth, TX Sakai SV201TB-1 Padfoot Drum Compactor S/N: LSV2720110 C/W: Open Operator Station, Tier 4, 2008 US EPA Label, Kubota V3307-D1-T-ET04 4 Cylinder 55.4 kW 3.3 L Diesel Engine, 55 in Drum, Leveling Blade	
274	2016 Dynapac CA2500PD Padfoot Drum		Usage: 1,882 Hr Asset located in : Lake Worth, TX	
	Compactor S/N: 10000167PHA020589 C/W: Open Operator Station, 2017 US EPA Label, Cummins QSF 4 Cylinder 89 kW 3.8 L Diesel Engine, 84 in Drum Usage: 2,102 Hr		281 Volvo SD45 Padfoot Drum Compactor S/N: VCE00S45L0S229308 C/W: Open Operator Station, Kubota Dies Engine, 54 in Drum Usage: 833 Hr	Volvo SD45 Padfoot Drum Compactor S/N: VCE00S45L0S229308 C/W: Open Operator Station, Kubota Diesel Engine, 54 in Drum Usage: 833 Hr
274A	Asset located in: Lake Worth, TX Vibromax 1106 Padfoot Drum Compactor S/N: JKC8305502 C/W: Enclosed Cab, Diesel Engine, 82 in Drum Usage: 2,512 Hr Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
275	2008 Dynapac CA250PD Padfoot Drum		Asset located in: Fort Smith, AR	
276	Compactor S/N: 6582US5658 C/W: Open Operator Station, 4 Cylinder Diesel Engine, 84 in Drum Usage: 3,598 Hr Asset located in: Lake Worth, TX 2007 Cat CP563E Padfoot Drum Compactor S/N: CATCP563ACNT01503 C/W: Open Operator Station, Cat 6 Cylinder Diesel Engine, 84 in Drum, Leveling Blade	283	2021 XCMG CV123PDU Smooth Drum Compactor S/N: XUG01231CMJE04323 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Cummins 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum, Padfoot Shell Kit Usage: 692 Hr Asset located in: Lake Worth, TX	
276	2007 Cat CP563E Padfoot Drum Compactor S/N: CATCP563ACNT01503 C/W: Open Operator Station, Cat 6 Cylinder		84 in Drum, Padfoot Shell k Usage: 692 Hr	

Lot #	Details	Lot #	Details	
284	2018 Volvo SD115B Smooth Drum Compactor S/N: VCES115BA0S236505 C/W: Open Operator Station, Air Ride Seat, 2018 US EPA Label, Volvo D4J 4 Cylinder 148 hp 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 85 in Drum, Padfoot Shell Kit Usage: 2,594 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	291	2019 Dynapac CA1500D Smooth Drum Compactor S/N: 10000160AKA024661 C/W: Open Operator Station, Swivel Operator Controls, 2021 US EPA Label, Deutz TD3.6L4 4 Cylinder 3.6 L Diesel Engine, 66 in Drum Usage: 749 Hr Asset located in: Lake Worth, TX	
	Asset located in: Humble, TX	292	2015 Dynapac CA1500D Padfoot Drum	
285	2015 Volvo SD115 Padfoot Drum Compactor S/N: VCES115BL0S236313 C/W: Open Operator Station, 2017 US EPA Label, Volvo D4J 4 Cylinder 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 1,488 Hr Asset located in: Lake Worth, TX			Compactor S/N: 10000156CFA016214 C/W: Open Operator Station, 2014 US EPA Label, Cummins QSB3.3 100 hp 3.26 L Diesel Engine, 66 in Drum, Leveling Blade, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,459 Hr Notes: SUNSTATE EQUIPMENT CO. RENTAL
286	2013 Bomag BW211D-50 Smooth Drum		PEOPLE YOU CAN DEPEND ON Asset located in: Oklahoma City, OK	
	Compactor S/N: 901583531097 C/W: Open Operator Station, 2013 US EPA Label, Duetz 4 Cylinder 121 hp 3.6 L Diesel Engine, 84 in Drum Usage: 3,618 Hr Asset located in: Lake Worth, TX	293	2015 Bomag BW177DH-5 Smooth Drum Compactor S/N: 101586041089 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 66 in Drum	
287	2013 Dynapac CA2500D Smooth Drum Compactor S/N: 10000138C0A012121 C/W: Open Operator Station, 2013 US EPA		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
		294 2010 Volvo SD70D Smooth Drum Compactor S/N: VC500670A00225225 C/W: Open Operator Station, Tier 3, 2009 US EPA Label, Kubota V3800-DI-T-ET02 4 Cylind 74 kW Diesel Engine, 66 in Drum Usage: 2,841 Hr Asset located in: Lake Worth, TX		
288	2006 Cat CS563E Smooth Drum Compactor S/N: CATCS563PCNG01830 C/W: Open Operator Station, Cat 6 Cylinder		74 kW Diesel Engine, 66 in Drum Usage: 2,841 Hr	
	Diesel Engine, 84 in Drum Usage: 4,090 Hr Asset located in : Lake Worth, TX	294A	2007 Ingersoll Rand SD70D-TF Smooth Drum Compactor S/N: 196662	
289	2005 Ingersoll Rand SD122DX Smooth Drum Compactor S/N: 183705 C/W: Open Operator Station, 4 Cylinder Diesel Engine, 84 in Drum Usage: Not Available Asset located in: Lake Worth, TX		C/W: Open Operator Station, 2007 US EPA Label, Cummins b4.5 4 Cylinder 78 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,215 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	
290	2019 Volvo SD75B Padfoot Drum Compactor		Asset located in: Lake Worth, TX	
	S/N: VCE0S75BK0S241348 C/W: Open Operator Station, Tier 4, Volvo Diesel Engine, 66 in Drum Usage: 1,190 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR	294B	2004 Ingersoll Rand SD70D-TF Smooth Drum Compactor S/N: 177760 C/W: Open Operator Station, 2004 US EPA Label, Cummins B4.5 4 Cylinder 79 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
295	2015 Hamm H5i Smooth Drum Compactor S/N: H2220266 C/W: Open Operator Station, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 54 in Drum Usage: 220 Hr	CHOIC 304	E OF 2 - Lot #'s: 304, 305 2023 Hamm HD12VV Double Drum Roller (Unused)	
	Asset located in: Lake Worth, TX		S/N: WGH0H230CHAA06595	
296	2018 Bomag BW124DH-5 Smooth Drum Compactor S/N: 861586571071 C/W: Open Operator Station, 2018 US EPA Label, Kubota V2403-CR-EF04 4 Cylinder 33.6 kW 2.4 L Diesel Engine, 47.5 in Drum		20 Di Sy Us	C/W: Open Operator Station, E-Stops, Tier 4, 2020 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 22 Hr Asset located in: Lake Worth, TX
	Usage: Not Available	305	2022 Hamm HD12VV Double Drum Roller	
	Asset located in: Lake Worth, TX	_	S/N: WGH0H230KHAA05864	
298	2011 Cat CB54 Double Drum Roller S/N: CAT0CB54VJLM00434 C/W: Open Operator Station, Swivel Operator Controls, Cat C4.4 4 Cylinder Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available	Diesel Engine, 47 in Compaction System Usage: 63 Hr	2022 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 63 Hr Asset located in : Lake Worth, TX	
	Asset located in: Lake Worth, TX	305A	2019 Hamm HD12VV Double Drum Roller	
299	2006 Cat CB-534D XW Double Drum Roller S/N: CATCB534KEAA00412 C/W: Open Operator Station, Swivel Operator Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction		C/W: Open Operator Station, Kubota 3 Cylinder 1.7 hp Engine, 47 in Compaction Width, Water System Usage: 3,656 Hr	
	Width, Water System Usage: Not Available	307	Volvo DD24 Double Drum Roller S/N: 196371	
	Asset located in: Lake Worth, TX			
300	2005 Cat CB-534D XW Double Drum Roller S/N: CATCB534AEAA00397 C/W: Open Operator Station, Swivel Operator Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available			C/W: Open Operator Station, 3 Cylinder Diesel Engine, 47.25 in Compaction Width, Water System Usage: 2,886 Hr Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 308, 309	
301A	2015 Case DV210C Double Drum Roller S/N: DDDD210CNENTL2010 C/W: Open Operator Station, Swivel Operator Controls, 2014 US EPA Label, Deutz 100 hp 3.62 L Diesel Engine, 66 in Compaction Width, Water System Usage: 1,004 Hr Asset located in: Lake Worth, TX	308	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263LHHAA00855 C/W: Open Operator Station, Tier 4, 2021 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 39 in Compaction Width, Water System Usage: 148 Hr Asset located in: Lake Worth, TX	
302	2016 Cat CB36B Double Drum Roller S/N: CATCB36BAM3600111 C/W: Open Operator Station, Cat 4 Cylinder Diesel Engine, 55 in Compaction Width, Water System, Edge Cutter Usage: Not Available Asset located in: Lake Worth, TX	309	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263THAA00778 C/W: Open Operator Station, Kubota D1105 Diesel Engine, 39 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX	
303	2013 Hamm HD13VV Double Drum Roller S/N: H2011675 C/W: Open Operator Station, Kubota V2203 4 Cylinder 2.2 L Diesel Engine, 51 in Compaction Width, Edge Cutter Usage: 1,104 Hr Asset located in: Lake Worth, TX	310	2017 Hamm HD10C VV Double Drum Roller S/N: H1994782 C/W: Open Operator Station, Tier 4, 2016 US EPA Label, Kubota D1005-EF05 3 Cylinder 14.8 kW 1.0 L Diesel Engine, 39 in Compaction Width, Water System Usage: 892 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 314, 315	сноіс	E OF 2 - Lot #'s: 320, 321
314	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072137 C/W: Open Operator Station, Honda 2 Cylinder Gasoline Engine, 36 in Compaction Width Usage: Not Available Asset located in: Lake Worth, TX	320	2015 Broce KR350 Self-Propelled Broom S/N: 409370 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota V3600-T-ET03 4 Cylinder 55.4 kW 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
315	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072138 C/W: Open Operator Station, Honda 2 Cylinder		Usage: 1,930 Hr Asset located in: Lake Worth, TX
	Gasoline Engine, 35.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX	321	2015 Broce KR350 Self-Propelled Broom S/N: 409369 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder 55.4 kW 3.6 L Diesel Engine,
316	Wacker Neuson RD11A Double Drum Roller S/N: 5613749 C/W: Open Operator Station, 2014 US EPA		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 698 Hr Asset located in: Lake Worth, TX
	Label, Honda GX 630 2 Cylinder Gasoline Engine, 35 in Compaction Width Usage: 594 Hr Asset located in: Humble, TX	322	2015 Broce KR-350 Self-Propelled Broom S/N: 409307 C/W: Enclosed Cab, Air Conditioner, 8 ft
316A	Elgin Crosswind on 2013 Freightliner M2 106 Sweeper Truck S/N: 1FVACXDT5DHFB1562 C/W: Cummins 6.7 L Diesel 200 hp Engine,		Broom, Water System, Kubota 4 Cylinder Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,522 Hr
			Asset located in: Oklahoma City, OK
	Requires Diesel Exhaust Fluid, Automatic Transmission, 11R22.5, Spring Suspension, Auxiliary Engine, Under Body Broom Usage: 44,365 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; RITCHIE-BROS- ENERGY	323	2015 Broce KR350 Self-Propelled Broom S/N: 409308 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2015 US EPA Label, Kubota V3600-T-ET03 4 Cylinder 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,137 Hr
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
317	2006 Isuzu NQR Sweeper Truck S/N: JALE5B16267903657 C/W: Isuzu 4 Cylinder Diesel 190 hp Engine, 2005 US EPA Label, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 134 in Wheelbase, Kubota Auxiliary Engine, Vacuum Sweeper, Under Body Broom, Gutter Brooms Usage: 93,999 Mi	324	2015 Broce KR350 Self-Propelled Broom S/N: 409371 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder Diesel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 1,187 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	325A	2014 Broce CRT350 Self-Propelled Broom
318	2019 LeeBoy CB95 Self-Propelled Broom S/N: 242550 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2019 US EPA Label, Hatz 4H50TIC 4 Cylinder 55 kW 1.9 L Diesel Engine	325A	S/N: 408677 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, 2013 US EPA Label, Cat 4 Cylinder 60.5 kW 4.4 L Diesel Engine Usage: 5,095 Hr
	Usage: 359 Hr Asset located in: Lake Worth, TX	00.5	Asset located in: Lake Worth, TX
319	2019 Broce RJT-350 Self-Propelled Broom S/N: 411566 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2018 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	326	2014 Superior DT80J Self-Propelled Broom S/N: 814877 C/W: Enclosed Cab, Air Conditioner, 8 ft 7 in Broom, Water System, 2014 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 691 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
327	2014 Superior DT80J Self-Propelled Broom S/N: 814869 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, John Deere 4045TF290 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,536 Hr Asset located in: Lake Worth, TX	334A	2015 Komatsu PC650LC-8E0 Tracked Excavator S/N: 65343 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 10 ft Stick, 36 in Triple Grouser Track Shoes, 80 in Digging Bucket, Counterweight Removal System Usage: 18,316 Hr Asset located in: Lake Worth, TX
СНОІС	E OF 2 - Lot #'s: 329, 330	335	2015 Kobelco SK500LC-9 Tracked Excavator S/N: YS1203617 C/W: Air Conditioner, 11 ft 6 in Stick, 35.5 in
329	2001 Broce BB250B Self-Propelled Broom S/N: 304993 C/W: Open Operator Station, 8 ft Broom, Water		Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 8,275 Hr Asset located in : Lake Worth, TX
	System, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 18.5 kW 1.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available	СНОІС	E OF 2 - Lot #'s: 337, 338
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	337	2017 Cat 349FL Tracked Excavator S/N: CAT0349FCHPD10110 C/W: Air Conditioner, Straight Travel Pedal, Air
330	Asset located in: Lake Worth, TX 2001 Broce BB250B Self-Propelled Broom S/N: 304910 C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2015 US EPA Label, Kubota V1505-EF01 4 Cylinder 18.5 kW 1.5 L Diesel	Rid Ex Gr 30 Us	Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 30 in V-Bottom Bucket Usage: 13,440 Hr Asset located in: Lake Worth, TX
	Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 100 Hr Asset located in : Lake Worth, TX	338	2017 Cat 349F L Tracked Excavator S/N: CAT0349FAHPD10053 C/W: Air Conditioner, Straight Travel Pedal, Air
330A	2001 Broce BB250B Self-Propelled Broom S/N: 305062 C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2018 US EPA Label, Kubota V1505 18.2 kW 1.5 L Diesel Engine Usage: 663 Hr	339	Ride Seat, Rear View Camera, 2016 US EPA Label, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Manual Quick Coupler, 30 in V- Bottom Bucket Usage: 13,635 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2013 Cat 349E Tracked Excavator
333	2000 Rosco RB48 Self-Propelled Broom S/N: 36730 C/W: Enclosed Cab, Air Conditioner, 7 ft Broom, Water System, Cummins 4 Cylinder Diesel Engine Usage: 1,635 Hr Asset located in: Lake Worth, TX		S/N: CAT0349EPMPZ00695 C/W: Air Conditioner, Straight Travel Pedal, Rear View Camera, 2013 US EPA Label, 12 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket Usage: 10,831 Hr Asset located in: San Antonio, TX
334	2021 John Deere 870G LC Tracked Excavator S/N: 1FF870GXJMF890112 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, 9 ft 8 in Stick, 36 in Double Grouser Track Shoes, 96 in Digging Bucket, Counterweight Removal System Usage: 5,764 Hr Asset located in: Lake Worth, TX	340	2021 Hyundai HX480L Tracked Excavator S/N: HHKHKB01JL0000163 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 72 in Digging Bucket, Auto Lube Usage: 6,810 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
340A 341	2014 John Deere 470GLC Tracked Excavator S/N: 1FF470GXTCE470692 C/W: Requires Diesel Exhaust Fluid, 13 ft 5 in Stick, 35.5 in Triple Grouser Track Shoes, 72 in Digging Bucket Usage: 12,526 Hr Asset located in: Lake Worth, TX 2013 Hitachi ZX470LC-5B Tracked Excavator S/N: HCMJAA70A00030283 C/W: Air Ride Seat, Tier 4, US EPA Label, 9 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes,	346	2018 Cat 336FL Tracked Excavator S/N: TZA20175 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 43 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,883 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	Hydraulic Quick Coupler, 68 in Digging Bucket,		Asset located in: Lake Worth, TX
	Catwalks Usage: 11,455 Hr Asset located in : Humble, TX	347	2018 Cat 336FL Tracked Excavator S/N: CAT0336FKTZA20109
342	2016 John Deere 380G LC Tracked Excavator S/N: 1FF380GXTGF900147 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 10,290 Hr	348	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 46 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,561 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELECTION FOR THE SECTION F
242	Asset located in: Lake Worth, TX		SECTION BELOW Asset located in: Lake Worth, TX
343	2019 Cat 336 Tracked Excavator S/N: CAT00336PDKS00399 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 12,251 Hr Asset located in: Lake Worth, TX		2018 Cat 336FL Tracked Excavator S/N: CAT0336FKRKB21071 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 42 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,613 Hr
344	2019 Cat 336 Tracked Excavator S/N: CAT00336LDKS01786 C/W: Air Conditioner, Straight Travel Pedal, Air		Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, 33.5 in Triple		Asset located in: Lake Worth, TX
	Grouser Track Shoes, 43 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX	349	2017 Cat 336F L Tracked Excavator S/N: CAT0336FLTZA10137 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA
CHOIC	E OF 4 - Lot #'s: 345, 346, 347, 348	L S H	Label, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 13,138 Hr
345	2018 Cat 336FL Tracked Excavator	050	Asset located in: Lake Worth, TX
	S/N: CAT0336FARKB21335 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 44 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 4,625 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	350	2016 Cat 336FL Tracked Excavator S/N: CAT0336FJSSN00477 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Cab Screens, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 10,564 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
351	2016 Cat 336FL Tracked Excavator S/N: CAT0336FCTZA00440 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 56 in Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 12,821 Hr Asset located in: Lake Worth, TX	355	2013 Cat 336 EL Tracked Excavator S/N: CAT0336EEFJH00483 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 45 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 7,199 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 352, 353	356	2013 Cat 336EL Tracked Excavator
352	S/N: CAT0336FJRKB00903 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2014 US EPA Label, 12 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 31 in Digging Bucket, Hydraulic		S/N: CAT0336ECFJH00355 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, 33.5 in Triple Grouser Track Shoes, 50 in Digging Bucket Usage: 8,712 Hr Asset located in: Midland, TX
	Thumb Usage: 7,433 Hr	357	2012 Cat 336 EL Tracked Excavator
353	Asset located in: Midland, TX 2015 Cat 336FL Tracked Excavator S/N: RKB00900 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Rock Guards, 39 in Digging Bucket Usage: 6,370 Hr		S/N: CAT0336EKBZY01618 C/W: Air Conditioner, Straight Travel Pedal, A Ride Seat, Rear View Camera, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 34 in Trip Grouser Track Shoes, 42 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 9,409 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	_	,
CHOIC	E OF 2 - Lot #'s: 354, 355	сноіс	E OF 2 - Lot #'s: 358, 359
354	2013 Cat 336 EL Tracked Excavator S/N: CAT0336EJRZA00234 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 12 ft 10 in Stick, 34 in Triple Grouser Track Shoes, 48 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,605 Hr	358	2012 Cat 336E L Tracked Excavator S/N: CAT0336EVBZY01509 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 58 in Digging Bucket Usage: 12,654 Hr Asset located in: Lake Worth, TX
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	359	2012 Cat 336E L Tracked Excavator S/N: CAT0336EKBZY00808 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2011 US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 14,076 Hr Asset located in: Lake Worth, TX
		360	2010 Cat 336D Tracked Excavator S/N: CAT0336DKW3K01214 C/W: Air Conditioner, 2010 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 34 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: 89,205 Hr

Lot #	Details	Lot #	Details	
361	2017 Komatsu PC360LC 11 Tracked Excavator S/N: KMTPC256HHWA35865 C/W: Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 60 in Digging Bucket Usage: 15,343 Hr Asset located in: Lake Worth, TX	366	2012 John Deere 350G LC Tracked Excavator S/N: 1FF350GXCCE808325 C/W: Air Conditioner, Air Ride Seat, 2011 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX	
361A	2017 Komatsu PC360LC-11 Tracked Excavator S/N: KMTPC256AHWA35992 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 13 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 63 in Digging Bucket, Manual Thumb, Nye 516541, PC 360 Grapple Usage: 5,789 Hr Asset located in: Midland, TX	367	2022 Cat 330 Tracked Excavator S/N: CAT00330VWCH30051 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-	
362	2012 Komatsu PC360LC-10 Tracked Excavator S/N: KMTPC24202070045 C/W: Air Conditioner, 2011 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 56 in Digging Bucket, Hydraulic Thumb Usage: 12,043 Hr Asset located in: Lake Worth, TX		FROM-WATKINS-CONSTRUCTION Usage: 1,104 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	
363	2017 XCMG XE360U Tracked Excavator S/N: XUG03600KHKA00061 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, US EPA Label, 8 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 823 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	368	S/N: CAT00330AWCH20489 C/W: Air Conditioner, Straight Tra Ride Seat, Rear & Side View Came Wired for Grade Control, 2021 US Requires Diesel Exhaust Fluid, 10 Auxiliary Hydraulic Plumbing, 32 i Grouser Track Shoes, 36 in Diggir	S/N: CAT00330AWCH20489 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,395 Hr
364	2018 Cat 335F LCR Tracked Excavator S/N: SGJ20006 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 4 in Stick, Auxiliary	369	Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2020 Cat 330 Tracked Excavator	
	Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 43 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 5,806 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	369	S/N: CAT00330JWCH10184 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Surround View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION	
365	2010 Komatsu PC350LC-8 Tracked Excavator S/N: KMTPC19IJ54A10246 C/W: Air Conditioner, Rear View Camera, 2010 US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 56 in Digging Bucket Usage: 11,202 Hr Asset located in: Lake Worth, TX		Usage: 1,590 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	

Lot#	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 370, 371	373	2020 Cat 330GC Tracked Excavator S/N: CAT00330CSCZ10029 C/W: Air Conditioner, Straight Travel Pedal, Air
370	2020 Cat 330 Tracked Excavator S/N: CAT00330TWCH10651 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,428 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB	074	Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,443 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	374	2020 Cat 330GC Tracked Excavator
371	2020 Cat 330 TC Tracked Excavator S/N: CAT00330JWCH10654 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,072 Hr Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN		S/N: CAT00330VGDW10047 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 2,462 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
	THE DOCUMENTS SECTION BELOW		
	Asset located in: Lake Worth, TX	Сноіс	E OF 3 - Lot #'s: 375, 376, 377
СНОІС	E OF 3 - Lot #'s: 372, 373, 374	375	2020 Cat 330GC Tracked Excavator S/N: CAT00330KGDW10058
372	2 2020 Cat 330GC Tracked Excavator S/N: CAT00330CGDW10069 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,885 Hr Notes: EMISSIONS SYSTEM WARRANTY		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 38 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,503 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE	376	2020 Cat 330GC Tracked Excavator
	SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		S/N: CAT00330ESCZ10028 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 35 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,558 Hr

Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE

Asset located in: Lake Worth, TX

SELLER IN THE DOCUMENTS SECTION BELOW

Lot #	Details	Lot #	Details
377	2020 Cat 330GC Tracked Excavator S/N: CAT00330LGDW10049 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Cleanup Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,882 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	381	2018 Cat 330F L Tracked Excavator S/N: CAT0330FEMBX20643 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 3,732 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
378	2019 Cat 330 Tracked Excavator S/N: CAT00330TLHW00257 C/W: Air Conditioner, Rear & Side View Cameras, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 5,554 Hr Asset located in: Lake Worth, TX	382	2018 Cat 330F L Tracked Excavator S/N: CAT0330FCMBX20666 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control;
379	2019 Cat 330F L Tracked Excavator S/N: CAT0330FJHCK20408 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,557 Hr Notes: ; PLEASE SEE A PERSONAL NOTE		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,894 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
		CHOICE OF 2 - Lot #'s: 383, 384	
	FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	383	2018 Cat 330F L Tracked Excavator S/N: CAT0330FTHCK20095 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel
CHOIC	2018 Cat 330F L Tracked Excavator S/N: MBX20638 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,586 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,836 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB
			Asset located in: Lake Worth, TX
		384	2018 Cat 330F L Tracked Excavator S/N: CAT0330FPMBX20257 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,485 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
		385	2012 Volvo EC300DL Tracked Excavator S/N: VCEC300DC00210349 C/W: Straight Travel Pedal, 2012 US EPA Label, 10 ft Stick, 36 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 9,162 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
386	2017 John Deere 300G LC Tracked Excavator S/N: 1FF300GXKHF730514 C/W: Air Conditioner, 2017 US EPA Label, CARB Compliant, 13 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 28 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 43 in Digging Bucket, Hydraulic Thumb Usage: 6,335 Hr Asset located in: Lake Worth, TX 2017 Volvo ECR305CL Tracked Excavator S/N: VCECR305V00110701	391	2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27915 C/W: Air Conditioner, Control Pattern Changer, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 5 in Stick, 31.5 in Triple Grouser Track Shoes Usage: 4,248 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK
	C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, 2016 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 6,005 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: El Paso, TX	392	2019 Komatsu PC290LC-11 Tracked Excavator S/N: KMTPC255AJKK73097 C/W: Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 0 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31.5 in Triple Grouser Track Shoes, Rock Guards, 48 in Digging Bucket Usage: 4,542 Hr Notes: LOADOUT BY APPOINTMENT ONLY;
388	Hyundai R300LC-9A Tracked Excavator S/N: HHKHZ803ED0000030 C/W: Air Conditioner, Rear View Camera, 2012 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket		ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Usage: 4,396 Hr Asset located in : Lake Worth, TX		2018 Komatsu PC290LC-11 Tracked Excavato S/N: A27917
389	2018 Volvo EC250ELR Tracked Excavator S/N: VCEC250EK00310554 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 25 ft 6 in Boom, 26 ft Stick, 36 in Triple Grouser Track Shoes, 60 in Cleanup Bucket Usage: 4,986 Hr Asset located in: Lake Worth, TX		201 Hyd Trac Usa Not e ITEN PICI SUB
390	2019 Komatsu PC290LC-11 Tracked Excavator S/N: JKK73093 C/W: Air Conditioner, Rear View Camera, 10 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 42 in Cleanup Bucket Usage: 3,632 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE	394	2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27916 C/W: Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,473 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	AVAILABLE Asset located in: McAlester, OK	395	2018 Komatsu PC290LC-11 Tracked Excavator S/N: KMTPC255CJWA27918 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 5,920 Hr Asset located in: Lake Worth, TX

2009 Cat 329DL Tracked Excavator	401	2020 LiuCong 00002EE Trooked Eventuates
S/N: CAT0329DLJHJ00330 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Manual Thumb, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 10,025 Hr Notes: COMES WITH UNUSED HYDRAULIC		2020 LiuGong 888925E Tracked Excavator S/N: 888925EZJLU004037 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 2,191 Hr Asset located in: Humble, TX
FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	402	2016 John Deere 245G LC Tracked Excavator S/N: 1FF245GXJGF800123 C/W: Air Conditioner, Control Pattern Changer, 2016 US EPA Label, Requires Diesel Exhaust
E OF 2 - Lot #'s: 397, 398		Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 6,879 Hr
		Asset located in: Lake Worth, TX
S/N: CA10326FPFBR20575 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 34 in Digging Bucket, Hydraulic Thumb, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 3,230 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB	404	2012 Cat 324 EL Tracked Excavator S/N: CAT0324EPPNW00408 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 8,469 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM
Asset located in: Lake Worth, TX		THE SELLER IN THE DOCUMENTS SECTION
2019 Cat 326F L Tracked Excavator S/N: CAT0326FLFBR20679 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,973 Hr Notes: UNUSED HYDRAULIC THUMB: PLEASE		BELOW Asset located in: Lake Worth, TX
	405	2012 Cat 324E L Tracked Excavator S/N: CAT0324EHPNW00497 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA Label, 9 ft 5 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Manual Thumb Usage: 10,768 Hr Asset located in: Lake Worth, TX
Asset located in: Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 406, 407
2019 Cat 326F L Tracked Excavator S/N: CAT0326FEFBR20653 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 9,619 Hr Asset located in: Lake Worth, TX	406	2023 Cat 323 Tracked Excavator S/N: CAT00323ENDL20616 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-
2015 Cat 326FL Tracked Excavator		CONSTRUCTION Usage: 240 Hr
S/N: CAT0326FVWGL00317 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 54 in Digging Bucket Usage: 9,061 Hr		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX E OF 2 - Lot #s: 397, 398 2019 Cat 326F L Tracked Excavator S/N: CAT0326FPFBR20575 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 34 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,230 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB Asset located in: Lake Worth, TX 2019 Cat 326F L Tracked Excavator S/N: CAT0326FLFBR20679 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,973 Hr Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2019 Cat 326F L Tracked Excavator S/N: CAT0326FEFBR20653 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 9,619 Hr Asset located in: Lake Worth, TX 2015 Cat 326FL Tracked Excavator S/N: CAT0326FEVMGL00317 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 9,619 Hr Asset located in: Lake Worth, TX	THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX E OF 2 - Lot #s: 397, 398 2019 Cat 326F L Tracked Excavator S/N: CAT0326FPBR20575 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 34 in Digging Bucket, Hydraulic Thumb, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 3,230 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB Asset located in: Lake Worth, TX 2019 Cat 326F L Tracked Excavator S/N: CAT0326FLFBR20679 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,973 Hr Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2019 Cat 326F L Tracked Excavator S/N: CAT0326FEFBR20653 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 9,619 Hr Asset located in: Lake Worth, TX 2015 Cat 326FL Tracked Excavator S/N: CAT0326FVWGL00317 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 54 in Digging Bucket, Usage: 9,061 Hr

Lot #	Details	Lot #	Details
407	2023 Cat 323 Tracked Excavator S/N: CAT00323LNDL20614 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 490 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	410	2022 Cat 323 Tracked Excavator S/N: CAT00323CNDL20219 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Surround View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 34 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 156 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
408	2023 Cat 323 Tracked Excavator S/N: CAT00323JNDL20736 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 866 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	411	2022 Cat 323 Tracked Excavator S/N: NDL20218 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 814 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
CHOICI	E OF 2 - Lot #'s: 409, 410	сноісі	E OF 3 - Lot #'s: 412, 413, 414
409	2022 Cat 323 Tracked Excavator S/N: CAT00323CNDL20262 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 120 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE	412	2019 Cat 323 Tracked Excavator S/N: CAT00323ARAZ10687 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,393 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	413	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10552 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,527 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
414	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ11197 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,958 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	418	2019 Cat 323 Tracked Excavator S/N: RAZ10628 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 4,636 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
СНОІС	E OF 3 - Lot #'s: 415, 416, 417	сноіс	E OF 4 - Lot #'s: 419, 420, 421, 422
415	2019 Cat 323 Tracked Excavator S/N: CAT00323CRAZ11070 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,062 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	419	2018 Cat 323 Tracked Excavator S/N: CAT00323LRAZ00176 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, ; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,439 Hr Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2018 Cat 323 Tracked Excavator
416	Asset located in: Lake Worth, TX 2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10972 C/W: Air Conditioner, Straight Travel Pedal, Rear & Side View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.25 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,205 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	421	S/N: CAT00323ERAZ00293 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,103 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2018 Cat 323 Tracked Excavator S/N: CAT00323HRAZ00227
417	2019 Cat 323 Tracked Excavator S/N: CAT00323KRAZ11087 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,253 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,498 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
422	2018 Cat 323 Tracked Excavator S/N: CAT00323JRAZ00303 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,641 Hr	427	2018 Cat 323 Tracked Excavator S/N: CAT00323HRAZ01166 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 48 in Digging Bucket, Thumb Bracket Usage: 4,053 Hr Asset located in: Lake Worth, TX
	Notes: UNUSED HYDRAULIC THUMB; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 424, 425, 426	428	2017 Cat 323F L Tracked Excavator S/N: CAT0323FTXCF10375 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb FOLIDMENT-EROM-
424	2018 Cat 323 Tracked Excavator S/N: CAT00323ARAZ00290 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires	SEE A PERSONAL NOTE FROM THE DOCUMENTS SECTION BELO	WATKINS-CONSTRUCTION
	Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,808 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	429	2015 Cat 323FL Tracked Excavator S/N: CAT0323FCXCF00606 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2014 US EPA Label, 10 ft Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 10,595 Hr
425	Asset located in: Lake Worth, TX 2018 Cat 323 Tracked Excavator S/N: CAT00323KRAZ00266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging	430	Asset located in: Lake Worth, TX 2022 John Deere 210GLC Tracked Excavator S/N: 1FF210GXENF529761 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, 9 ft 7 in Stick, 27.5 in Triple Grouser Track Shoes, 24 in Digging Bucket Usage: 2,416 Hr Asset located in: Lake Worth, TX
	Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,852 Hr Notes: ; PLEASE SEE A PERSONAL NOTE	СНОІС	E OF 2 - Lot #'s: 431, 432
	FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	431	2018 John Deere 210G LC Tracked Excavator S/N: 1FF210GXLJF526477
426	2018 Cat 323 Tracked Excavator S/N: CAT00323LRAZ00288 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,063 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		C/W: Air Conditioner, Straight Travel Pedal, A Ride Seat, Rear View Camera, Requires Diese Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydrau Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucke Usage: 4,374 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
432	S/N: 1FF210GXPJF526258 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 700 mm Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 5,427 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.	439	2019 XCMG XE210U Tracked Excavator S/N: XUGA210BVKKA00083 C/W: Air Conditioner, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 1 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 23 in Digging Bucket Usage: 721 Hr Asset located in: Humble, TX
		440A	2018 Hitachi ZX210LC-5N Tracked Excavator S/N: 1FFDCJ70JEE330489 C/W: Air Conditioner, Cab Screens, 8 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in
434	Asset located in: Lahoma, OK 2012 Hitachi ZX210LC-5N Tracked Excavator S/N: 1FFDCJ70TCE330100 C/W: Air Conditioner, 2012 US EPA Label, 9 ft 7 in Stick, 32 in Triple Grouser Track Shoes, 38 in	441	Triple Grouser Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket Usage: 11,575 Hr Asset located in: Lake Worth, TX 2022 Cat 320GC Tracked Excavator
	Digging Bucket Usage: 8,923 Hr Asset located in : Lake Worth, TX	J	S/N: CAT00320HLKS20318 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear View Camera,
435	2017 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257CGTC80149 C/W: Air Conditioner, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 34 in Digging Bucket Usage: 15,090 Hr Asset located in: Lake Worth, TX		Control Pattern Changer, Rear View Camera, 2022 US EPA Label, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Trac Shoes, 36 in Digging Bucket Usage: 1,075 Hr Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH DECEMBER 2025 OR 5,000 HOURS Asset located in: Lake Worth, TX
436	2020 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257KKWA12903 C/W: Air Conditioner, Rear View Camera, 2019 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Breaker Usage: 5,171 Hr Asset located in: Lake Worth, TX	442	2020 Cat 320 Tracked Excavator S/N: CAT00320JHEX20266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-
437	2013 Komatsu PC210LC-10 Tracked Excavator S/N: KMTPC243C02450042 C/W: Air Conditioner, Cab Screens, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, Auto Lube Usage: 14,738 Hr Asset located in: Lake Worth, TX		Wired for Grade Control, 2019 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 30 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,298 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2025 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
438	2013 Komatsu PC210LC-10 Tracked Excavator S/N: KMTPC243H02450734 C/W: Air Conditioner, 2013 US EPA Label, 10 ft 2 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 8,296 Hr Asset located in: Lake Worth, TX	443	Asset located in: Lake Worth, TX 2020 Cat 320 Tracked Excavator S/N: CAT00320HHEX20212 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,419 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
444	2020 Cat 320 Tracked Excavator S/N: CAT00320CHEX20219 C/W: Air Conditioner, Straight Travel Pedal, Air	СНОІСІ	E OF 4 - Lot #'s: 447, 448, 449, 450
Wired for Grade Control, 2019 US EPA Requires Diesel Exhaust Fluid, 9 ft 6 in Auxiliary Hydraulic Plumbing, 32 in Tri Grouser Track Shoes, 42 in Digging Bu Tool Control; EQUIPMENT-FROM-WAT CONSTRUCTION Usage: 1,582 Hr Notes: EMISSIONS SYSTEM WARRAN THROUGH MARCH 2026 OR 3000 HOU PLEASE SEE A PERSONAL NOTE FROI	Usage: 1,582 Hr Notes : EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	447	2019 Cat 320 Tracked Excavator S/N: CAT00320CHEX12081 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,445 Hr
СНОІС	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 445, 446		Notes: EMISSIONS SYSTEM WARRANTY THROUGH FEBRUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
445	2020 Cat 320 Tracked Excavator S/N: CAT00320KHEX20265 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 37 in Digging Bucket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,321 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS;	448	2019 Cat 320 Tracked Excavator S/N: CAT00320VHEX11425 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2018 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,539 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE
	PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
446	2020 Cat 320 Tracked Excavator S/N: CAT00320AHEX20207 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,462 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; UNUSED HYDRAULIC THUMB; PLEASE SEE A	-449	2019 Cat 320 Tracked Excavator S/N: HEX11857 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,702 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	450	2019 Cat 320 Tracked Excavator S/N: CAT00320KHEX12604 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Cleanup Bucket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,129 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
451	2019 Cat 320 Tracked Excavator S/N: CAT00320LHEX11329 C/W: Rear & Side View Cameras, 2018 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 3,617 Hr Asset located in: Lake Worth, TX	457	2014 Cat 320 EL Tracked Excavator S/N: CAT0320EPWBK02668 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 8 ft 6 in Stick, 31 in Triple Grouser Track Shoes, Hydraulic Breaker Usage: 18,583 Hr
452	2018 Cat 320 Tracked Excavator S/N: CAT00320THEX01650 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 2,890 Hr Asset located in: Lake Worth, TX	CHOIC	Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 458, 459, 460 2013 Cat 320 EL Tracked Excavator S/N: CAT0320ELWBK01626 C/W: Air Conditioner, Straight Travel Pedal, Air
453	2017 Cat 320FL Tracked Excavator S/N: CAT0320FKYBM10403 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 9 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 27 in Cleanup Bucket Usage: 6,755 Hr Asset located in: Midland, TX		Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,381 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
CHOIC	CHOICE OF 2 Lot #'o: 454 455		2013 Cat 320 EL Tracked Excavator
CHOICE OF 2 - Lot #'s: 454, 455		459	S/N: CATO320EKREE00514

454 2014 Cat 320EL Tracked Excavator

S/N: CAT0320EEWBK01967 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2012 US EPA Label, 9 ft 7 in Stick, 31 in Triple Grouser Track Shoes, 31 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,345 Hr

Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION **BELOW**

Asset located in: Lake Worth, TX

455 2014 Cat 320 EL Tracked Excavator

S/N: CAT0320EAWBK02595 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,912 Hr

Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION **BELOW**

Asset located in: Lake Worth, TX

456 2014 Cat 320 EL Tracked Excavator

S/N: CAT0320ECWBK02652 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Cab Screens, Rear View Camera, 2013 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb

Usage: 10,473 Hr

Asset located in: Lake Worth, TX

S/N: CAT0320EKREE00514 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,468 Hr

Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW

Asset located in: Lake Worth, TX

460 2013 Cat 320 EL Tracked Excavator

S/N: CAT0320EHWBK02230 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION

Usage: 6,019 Hr

Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION **BELOW**

Lot #	Details	Lot #	Details
CHOICI	CHOICE OF 2 - Lot #'s: 461, 462		2019 Cat 316FL Tracked Excavator S/N: CAT0316FKYDL21033 C/W: Air Conditioner, Straight Travel Pedal, Air
461	2012 Cat 320 EL Tracked Excavator S/N: CAT0320EKWBK00212 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 32		Ride Seat, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft in Stick, 24 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 3,683 Hr Asset located in: Lake Worth, TX
	in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,775 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	467	2013 Cat 316E L Tracked Excavator S/N: CAT0316EJDZW00889 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2012 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 40 in Digging Bucket, Manual Thumb Usage: 14,360 Hr
462	2012 Cat 320E L Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT0320EJWBK00387 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 7,386 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	468	2020 Cat 315FLCR Tracked Excavator S/N: CAT0315FJTDY14173 C/W: Air Conditioner, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Boom Check Valves, 27.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 1,758 Hr Asset located in: St. Rose, LA
	Asset located in: Lake Worth, TX	469	2019 Kobelco SK140SRLC-5 Tracked Excavato
CHOICI 463	E OF 2 - Lot #'s: 463, 464 2006 Komatsu PC200-LC-7 Tracked Excavator S/N: C50926 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes		S/N: YH08015117 C/W: Air Conditioner, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 2,068 Hr Asset located in: Baton Rouge, LA
	Usage: Not Available	470	2012 Kobelco SK140SRLC Tracked Excavator
464	Asset located in: Lake Worth, TX 2006 Komatsu PC200LC-8 Tracked Excavator S/N: KMTPC180J54A88082 C/W: 2006 US EPA Label, 9 ft 8 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick		S/N: YH0608690 C/W: 2011 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, 31 in Digging Bucket Usage: 6,456 Hr Asset located in: Humble, TX
	Coupler Usage: 17,098 Hr Asset located in: Lake Worth, TX	471	2019 Cat 313F L GC Tracked Excavator S/N: CAT0313FEHDK10481
465	2006 John Deere 200C LC Tracked Excavator S/N: FF200CX507611 C/W: Air Conditioner, Control Pattern Changer, Tier 2, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 800 mm Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 8,607 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK		C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, CARB Compliant, 10 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 19.5 in Digging Bucket Usage: 3,746 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 473, 474	478A	2017 Case CX130D Tracked Excavator S/N: DAC130K7NHS7D1310 C/W: Air Conditioner, Air Ride Seat, Rear View
473	2019 Cat 313F L GC Tracked Excavator S/N: ZGS00152 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 10 ft Stick, 27.5 in Track Shoes, Hydraulic		Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 34 in Digging Bucket, Manual Thumb Usage: 934 Hr
			Asset located in: Lake Worth, TX
	Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 2,826 Hr Asset located in : Lake Worth, TX	479	2004 Kobelco SK480LC Tracked Excavator S/N: YS06U0308 C/W: US EPA Label, 11 ft 6 in Stick, 36 in Triple Grouser Track Shoes, Hydraulic Quick Coupler
474	2019 Cat 313F L GC Tracked Excavator S/N: ZGS00141		Usage: 15,245 Hr Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Rear & Side View Cameras, 2018 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,843 Hr Asset located in: Lake Worth, TX	480	1996 Cat 350L Tracked Excavator S/N: 3ML00899 C/W: Air Conditioner, Cab Screens, 10 ft 6 in Stick, 29.5 in Double Grouser Track Shoes, Catwalks, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: Not Available Asset located in: Humble, TX
CHOIC	E OF 4 - Lot #'s: 475, 476, 477, 478	480A	2004 Komatsu PC200LC-7L Tracked Excavator
475 2019 Sany S S/N: SY013J C/W: Air Cor in Stick, Auxi Blade, 24 in	2019 Sany SY135C Tracked Excavator S/N: SY013JBJM3218 C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 48 in Cleanup Bucket		S/N: A86747 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 51 in Digging Bucket Usage: 11,171 Hr Asset located in: Lake Worth, TX
	Usage: 6,558 Hr Asset located in: Lake Worth, TX	СНОІСІ	E OF 4 - Lot #'s: 482, 483, 484, 485
476	2019 Sany SY135C Tracked Excavator S/N: SY013JBJL6958 C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 6,291 Hr Asset located in: Lake Worth, TX	482	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88H00215346 C/W: Air Conditioner, Swing Boom, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,742 Hr
477			Asset located in: Lake Worth, TX
477	2018 Sany SY135C Tracked Excavator S/N: SY013EBJL6208 C/W: Air Conditioner, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 4,154 Hr Asset located in: Lake Worth, TX	483	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88K00215385 C/W: Air Conditioner, Tier 4, 2019 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, 22 in Digging Bucket, Hydraulic Thumb Usage: 2,972 Hr Asset located in: Lake Worth, TX
478	2018 Sany SY135C Tracked Excavator	404	<u>_</u>
	S/N: SY013JBJL2718 C/W: Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 43 in Cleanup Bucket Usage: 5,357 Hr	484	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88J00215338 C/W: Air Conditioner, 2019 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 901 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
485	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88H00215332 C/W: Air Conditioner, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Boom Check Valves, Backfill Blade, 17.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,792 Hr Asset located in: Lake Worth, TX	491	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308EVPC800527 C/W: Air Conditioner, 2018 US EPA Label, 5 ft 5 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 28 in Digging Bucket Usage: 1,694 Hr Asset located in: Lake Worth, TX
486	2021 Bobcat E85 Tracked Excavator S/N: B48414957 C/W: 2020 US EPA Label, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, 24 in Digging Bucket, Thumb Bracket Usage: 1,865 Hr Asset located in: Lake Worth, TX	CHOICI 492	E OF 4 - Lot #'s: 492, 493, 494, 495 2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELFJX10405 C/W: Air Ride Seat, Rear View Camera, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.75 in Triple
	E OF 2 - Lot #'s: 488, 489		Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,681 Hr Asset located in : Lake Worth, TX
488	2022 Cat 308 CR Tracked Excavator S/N: CAT00308HGG805305 C/W: Air Ride Seat, Rear View Camera, 2021 US EPA Label, Swing Boom, 7 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 22 in Digging Bucket, Manual Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,546 Hr Notes: EMISSIONS SYSTEM WARRANTY	493	2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELFJX07584 C/W: Air Conditioner, Air Ride Seat, 2016 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, 35.5 in Digging Bucket, Hydraulic Thumb Usage: 3,891 Hr Asset located in: Lake Worth, TX
	THROUGH MAY 2027 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	494	2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETFJX07574 C/W: Air Conditioner, 2016 US EPA Label,
489	2021 Cat 308 CR Tracked Excavator S/N: CAT00308VGG803324 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, Tier 4, 2020 US EPA Label, Swing Boom, 6 ft Stick, Auxiliary Hydraulic Plumbing,		Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 4,033 Hr Asset located in: Lake Worth, TX
	Backfill Blade, 18 in Track Shoes w/Rubber Inserts, 21 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,093 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	495	2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308EEFJX08253 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Single Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb, Strickland ZX85 MK2 Hydraulic Thumb
CHOIC	E OF 2 - Lot #'s: 490, 491		Usage: 4,117 Hr Asset located in: Lake Worth, TX
490	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETMC500734 C/W: Air Conditioner, 2018 US EPA Label, CARB Compliant, 5 ft 5 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 38 in Digging Bucket Usage: 1,492 Hr		

Lot #	Details	Lot #	Details
СНОІС			E OF 15 - Lot #'s: 501, 502, 503, 504, 505, 506, 507 19, 510, 511, 512, 513, 514, 515
496	2015 Cat 308E2 CR Tracked Excavator S/N: CAT0308EKFJX02698 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,281 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	501	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55HPAJAL584 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX 2023 Yanmar ViO55-6A Mini Excavator
497	2014 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETFJX00852 C/W: Air Conditioner, Control Pattern Changer, 2013 US EPA Label, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Double Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,625 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION		(Unused) S/N: YMRVIO55PPAJAL520 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX 2023 Yanmar ViO55-6A Mini Excavator
	BELOW Asset located in: Lake Worth, TX	503	(Unused) S/N: YMRVIO55PPAJAL422
498	2014 Cat 308E2 CR Mini Excavator S/N: CAT0308ELFJX00151 C/W: Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, 36 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Lake Worth, TX	504	C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS
499	2020 John Deere 75G Tracked Excavator S/N: 1FF075GXTKJ017240 C/W: 2019 US EPA Label, 6 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Track Shoes w/Rubber Pads, 30 in Bucket Usage: 2,121 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55EPAJAL456 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr
500	2021 Bobcat E60R2 Mini Excavator S/N: B4GR11148 C/W: Enclosed Cab, Air Conditioner, 2020 US EPA Label, Swing Boom, 6 ft 4 in Stick, Backfill		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Blade, 16 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,271 Hr Asset located in: Lake Worth, TX	505	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55JPAJAL786 C/W: Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
506	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55CPAJAL420 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb, Yanmar A-T30-V55BKP Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	511	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55LPAJAL848 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
		512	2023 Yanmar ViO55-6A Mini Excavator
507	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55KPAJAL429 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE		(Unused) S/N: YMRVIO55VPAJAL846 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	DOCUMENTS Asset located in: Lake Worth, TX	513	2023 Yanmar ViO55-6A Mini Excavator
508	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55APAJAL461 C/W: 2023 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS	C/W: 2023 US EPA Label, S Stick, Auxiliary Hydraulic Pl Rubber Tracks, Hydraulic Q Digging Bucket, Hydraulic T Usage: 2 Hr Notes : WARRANTY AVAILA DOCUMENTS	S/N: YMRVIO55EPAJAL702 C/W: 2023 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	514 	2023 Yanmar ViO55-6A Mini Excavator
509	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55KPAJAL415 C/W: US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		(Unused) S/N: YMRVIO55LPAJAL454 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 15.5 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX 2023 Yanmar VIO55-6A Mini Excavator
510	2023 Yanmar VIO55 Yanmar ViO 55 Mini Excavator (Unused) S/N: YMRVIO55KPAJAK958 C/W: 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		(Unused) S/N: YMRVIO55HPAJAL553 C/W: 2016 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 17 in Rubber Tracks, Hydraulic Quick Coupler, Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 3 - Lot #'s: 516, 517, 518	CHOIC 532, 53	E OF 10 - Lot #'s: 525, 526, 527, 528, 529, 530, 531 3, 534
516	2019 Cat 305.5E2 Mini Excavator S/N: CAT3055EPWE209294 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 5 ft Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 863 Hr Asset located in: Lake Worth, TX 2018 Cat 305.5E2 Mini Excavator	525	2023 Yanmar VIO35-6A Mini Excavator (Unused) S/N: YMRVIO35APAJAT785 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr
017	S/N: CAT3055EVWE205445 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 5 ft Stick, Backfill Blade,		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 792 Hr Asset located in : Lake Worth, TX	526	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35APAJAT947 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Abber Tracks,
518	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055ETWE204417 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 4 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.75 in Triple Grouser Track Shoes, Manual Quick Coupler, 28 in Digging Bucket	527	Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX
	Usage: 910 Hr Asset located in: Lake Worth, TX		2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35JPAJAT581 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thum Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
518A	2018 Cat 305E2 CR Mini Excavator S/N: CAT0305EPH5M06269 C/W: Swing Boom, 5 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, 18 in Digging Bucket Usage: 3,912 Hr Asset located in: Lake Worth, TX		
520	2019 Sany SY50U Mini Excavator S/N: SY005CBJZ2158 C/W: Enclosed Cab, Swing Boom, 4 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 18 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX	528	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35HPAJAT989 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE
522	2017 John Deere 50G Mini Excavator		DOCUMENTS Asset located in: Lake Worth, TX
	S/N: 1FF050GXCGH285257 C/W: Control Pattern Changer, 2016 US EPA Label, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 4,712 Hr Asset located in: Lake Worth, TX	529	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35LPAJAT772 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr
523	2016 John Deere 50G Mini Excavator S/N: 1FF050GXPGH284631 C/W: Control Pattern Changer, 2016 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 19 in Digging Bucket, Thumb Bracket Usage: 6,107 Hr Asset located in: Lake Worth, TX		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
530	2023 Yanmar VIO35-6A Mini Excavator (Unused) S/N: YMRVIO35VPAJAT865 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	CHOICI 542, 54 535	E OF 10 - Lot #'s: 535, 536, 537, 538, 539, 540, 541 3, 544 2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35LPAJAU087 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: Not Available
531	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35VAPJAT722 C/W: 4 ft 6 in Stick Backfill Blade 12 in Rubber		Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	C/W: 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: Not Available Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	536	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35EPAJAT671 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket,
532	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35KPAJAT868 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket,		Hydraulic Thumb Usage: 2 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in : Lake Worth, TX
	Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	S/N: YMRVIO35VPAJAT851 C/W: Control Pattern Changer, S ft 6 in Stick, Backfill Blade, 12 in Tracks, Hydraulic Quick Coupler Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE DOCUMENTS Asset located in: Lake Worth, T) 538 2023 Yanmar VIO35 Mini Excav S/N: YMRVIO35CPAJAT808 C/W: Swing Boom, 4 ft 6 in Stick Blade, 12 in Rubber Tracks, Hyd Coupler, 24 in Digging Bucket, H	C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging
533	· · · · · · · · · · · · · · · · · · ·		Usage: 3 Hr Notes : WARRANTY AVAILABLE - SEE
			C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb
534	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35HPAJAU091 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
		539	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35VPAJAU322 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
540	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35JPAJAT970 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr	546	2021 John Deere 35G Mini Excavator S/N: 1FF035GXLLK291536 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 10 in Digging Bucket Usage: 1,292 Hr
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	CHOIC	Asset located in: Lake Worth, TX E OF 4 - Lot #'s: 547, 548, 549, 550
541	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35TPAJAT700 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	547	2021 John Deere 35G Mini Excavator S/N: 1FF035GXVMK293316 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 18 in Bucket Usage: 466 Hr Asset located in: Lake Worth, TX
542	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35PPAJAT794 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE	548	2021 John Deere 35G Mini Excavator S/N: 1FF035GXCMK292861 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 729 Hr Asset located in: Lake Worth, TX
	DOCUMENTS Asset located in: Lake Worth, TX	549	2021 John Deere 35G Mini Excavator S/N: 1FF035GXVMK292537
543	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35LPAJAS623 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 11.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 922 Hr Asset located in: Lake Worth, TX
	Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX	550	S/N: 1FF035GXCMK292536 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary
544	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35APAJAT625 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 12 in Bucket Usage: 1,134 Hr Asset located in : Lake Worth, TX
	Usage: 3 Hr Notes : WARRANTY AVAILABLE - SEE DOCUMENTS	CHOIC	E OF 2 - Lot #'s: 551, 9623C
545	Asset located in: Lake Worth, TX Yanmar V1035-5B Mini Excavator S/N: YMRVI035J8YY53169 C/W: 2008 US EPA Label, Swing Boom, 4 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket, Thumb Bracket Usage: 7,897 Hr Asset located in: Lake Worth, TX	-551	2017 John Deere 35G Mini Excavator S/N: 1FF035GXEHK279948 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Lake Worth, TX

			1 4 6 6 6 7 7
Lot #	Details	Lot #	Details
553	2007 John Deere 35D Mini Excavator S/N: FF035DX237345 C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket Usage: 8,759 Hr Asset located in: Lake Worth, TX	560	2015 Cat 303E CR Mini Excavator S/N: CAT0303EAHHM01212 C/W: Control Pattern Changer, Tier 4, 2015 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION
554	54 2016 Bobcat E35I Mini Excavator S/N: AUYM13355 C/W: Enclosed Cab, Control Pattern Changer, Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup		Usage: Not Available Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Bucket, Thumb Bracket Usage: 2,462 Hr Asset located in : Midland, TX	563	2017 Bobcat E26 Mini Excavator S/N: B3JE13055 C/W: Swing Boom, 3 ft 6 in Stick, Backfill
555	2012 Komatsu PC35MR Mini Excavator S/N: KMTPC201C04018745 C/W: 2012 US EPA Label, Swing Boom, 5 ft 6 in		Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 2,327 Hr Asset located in : Lake Worth, TX
	Stick, Backfill Blade, 12 in Track Shoes w /Rubber Pads, 24 in Cleanup Bucket, Hydraulic Thumb Usage: Not Available Asset located in : Lake Worth, TX	564	2017 Takeuchi TB260 Mini Excavator S/N: 126102065 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Swing Boom, 5 ft 6 in Stick,
556	2016 Hitachi ZX35U-5N Mini Excavator S/N: HCMADG60E00273351 C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in		Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Thumb Bracket, EQUIPMENT FROM UNITED RENTALS Usage: 3,025 Hr Asset located in: Lake Worth, TX
	Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 6,514 Hr Asset located in: Humble, TX	565	565 2021 Bobcat E20 Mini Excavator S/N: B3BL19286 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 1 in Stick, Auxiliary
558	2018 Cat 303E CR Mini Excavator S/N: CAT0303EAHHM02733 C/W: Tier 4, 2017 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing,		Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 753 Hr Asset located in : Lake Worth, TX
	Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 590 Hr	сноіс	E OF 4 - Lot #'s: 566, 567, 568, 569
	Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	S/N: 1FF017GXJNK232661 C/W: Control Pattern Changer, 2022 Label, Swing Boom, 3 ft Stick, Auxil Hydraulic Plumbing, Backfill Blade, Tracks, Manual Quick Coupler, 12 in Bucket	2022 John Deere 17G Mini Excavator S/N: 1FF017GXJNK232661 C/W: Control Pattern Changer, 2022 US EPA
СНОІС	E OF 2 - Lot #'s: 559, 560		Label, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 12 in Digging
559	2016 Cat 303E CR Mini Excavator		Asset located in: Lake Worth, TX
	S/N: CAT0303EVHHM01984 C/W: Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,021 Hr Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	567	2021 John Deere 17G Mini Excavator S/N: 1FF017GXPMK231345 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Bucket Usage: 467 Hr Asset located in: Lake Worth, TX
	Appart laggered in 1 also Warth TV		

Lot #	Details	Lot #	Details
568	2021 John Deere 17G Mini Excavator S/N: 1FF017GXLMK231337 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 473 Hr Asset located in: Lake Worth, TX 2021 John Deere 17G Mini Excavator S/N: 1FF017GXTMK231117 C/W: Control Pattern Changer, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Manual Quick Coupler, 12 in	575	2011 Link-Belt HTC8675 75 ton 8x4 Series II Hydraulic Truck Crane S/N: 1F9P9K221CL028751 C/W: Air Conditioner, 13310 hrs Carrier Engine, Cat C13 8 Cylinder Diesel Carrier Engine, Air Conditioner, Anti Two-Block, Hirschmann Load Moment Indicator, 34 ft Minimum 113 ft Maximum Boom Length, Rooster Sheave, Bifold Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 356 lb Overhaul Ball, 18400 lb Counterweight, Counterweight Removal System Usage: 1,190 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION
	Digging Bucket Usage: 479 Hr		AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
569A	Asset located in: Lake Worth, TX 2018 Yanmar SV08-1B Mini Excavator S/N: YMRSV08YEJBJBF106 C/W: 2017 US EPA Label, Swing Boom, 2 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Expandable Width Tracks, 14 in Digging Bucket Usage: 1,259 Hr Asset located in: Lake Worth, TX	577A	2001 Link-Belt RTC-8075 70 ton 4x4x4 Rough Terrain Crane S/N: D7J1-5709LB C/W: Air Conditioner, Anti Two-Block, Microguard 534 Load Moment Indicator, 4994 hrs Crane Operation, Cummins 6 Cylinder 215 hp 8.3 L Diesel Engine, 41 ft Minimum 127 ft Maximum Boom Length, Auxiliary Hoist,
571	JCB HD110W Wheel Excavator S/N: JCBW11CFEN3148944 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9-20 Tires, Steelwrist X12 650-650 GR FPL Tiltrotator Attachment Usage: 202 Hr		Rooster Sheave, 39.5 ft to 67 ft Bifold Swingaway Offset Jib, 1502 lb 65 ton Capacity Johnson 5 Sheave Hook Block, Overhaul Ball, 15000 lb Counterweight, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 4,994 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
572	Asset located in: Lake Worth, TX 2004 Cat M318C Wheel Excavator S/N: CATM318CPBCZ00846 C/W: 2 Piece Hyd. Boom, 9 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Front and Rear Stabilizers, 10.00x20 Tires, 78 in Hydraulic Tilting Bucket Usage: Not Available Asset located in: Lake Worth, TX		Terrain Crane S/N: J9J80231 C/W: Air Conditioner, Anti Two-Block, Link Belt MicroGuard 534 Load Moment Indicator, 11225 hrs Crane Operation, Cat C6.6 Acert 6 Cylinder 6.6 L Diesel Engine, 38 ft Minimum 115 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 35 ft to 58 ft Bifold Swingaway Offset Jib, 1154 lb 70 ton Capacity Johnson 5 Sheave Hock Block, 247 lb 8 5 ton
574	2003 Mantis 3612 18 ton Telescopic Crawler Crane S/N: 36250 C/W: Anti Two-Block, PAT DS160 Load Moment Indicator, 2002 US EPA Label, 29 ft Minimum 71 ft Maximum Boom Length, Rooster Sheave, Overhaul Ball, Counterweight	578	Johnson 5 Sheave Hook Block, 347 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 11,225 Hr Asset located in: Humble, TX 2001 Link-Belt RTC-8065 65 ton 4x4x4 Rough Terrain Crane
	Removal System, 30 in Triple Grouser Track Shoes, Expandable Width Tracks Usage: 7,472 Hr Asset located in : Humble, TX		S/N: D7J1-5707 C/W: Air Conditioner, Anti Two-Block, Link Belt MicroGuard 534 Load Moment Indicator, 6824 hrs Crane Operation, Cummins C8.3C 6 Cylinder 215 hp 8.3 L Diesel Engine, 38 ft Minimum 115 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 36.5 ft to 61 ft Bifold Swingaway Offset Jib, 1103 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 350 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,828 Hr

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
579	2012 Grove RT765E-2 65 ton 4x4x4 Rough Terrain Crane S/N: 232495 C/W: Air Conditioner, Anti Two-Block, Hirschmann iScout Load Moment Indicator, 7421 hrs Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 240 hp 6.7 L Diesel Engine, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 56 ft Bifold Swingaway Offset Jib, 1252 lb 66 ton Capacity Johnson 5 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball, Counterweight Removal System	584	1998 Grove RT880 160000 lb 4x4 Rough Terrain Crane S/N: 87272 C/W: PAT Load Moment Indicator, 13418 hrs Crane Operation, Cummins 6 Cylinder 249 hp 8.3 L Diesel Engine, 36 ft Minimum 114 ft Maximum Boom Length, 30 ft Swingaway Jib, 1390 lb 70 ton Capacity Johnson 4 Sheave Hook Block, 404 lb 12 ton Capacity Overhaul Ball, 14000 lb Counterweight Usage: 13,420 Hr Asset located in: Hot Springs, AR
	Usage: 7,421 Hr Asset located in: Humble, TX	585	1996 Grove RT528C 28 ton 4x4x4 Rough Terrain Crane
581	581 2008 Link-Belt RTC 8050 II 50 ton 4x4x4 Rough Terrain Crane S/N: J6J8-9992 C/W: Microguard 534 Load Moment Indicator, 12354 hrs Crane Operation, Cummins B5.9C 6 Cylinder 173 hp 5.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 33 ft Minimum 110 ft		S/N: 83337 C/W: Anti Two-Block, PAT DS 350 GW Load Moment Indicator, Cummins cbd126 6 Cylinder 128 hp Diesel Engine, 28 ft Minimum 70 ft Maximum Boom Length, 566 lb 30 ton Capacity McKissick 3 Sheave Hook Block Usage: 511 Hr Asset located in: Lake Worth, TX
	Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Bifold Swingaway Offset Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, Overhaul Ball Usage: 12,353 Hr	585A	P & H Century 122 22 ton 4x4 Rough Terrain Crane S/N: 32R1032 C/W: Anti Two-Block, PAT Load Moment Indicator, 8653 hrs Crane Operation, Detroit 4087-7100 V8 8.2 L Diesel Engine, 29 ft Minimum 72 ft Maximum Boom Length, 25 ft Swingaway Jib, Overhaul Ball Usage: 8,653 Hr Asset located in: Midland, TX 2007 International 4200 4x2 Boom Truck S/N: 1HTMPAFN37H426012 C/W: International A215 4 Cylinder 6.0 L Diesel 200 hp Engine, 2006 US EPA Label, 11193 Engine hrs, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring Suspension, 236 in Wheelbase, PTO, 34000 lb Capacity, Center Mounted, 27 ft - 70 ft 3 Section Boom,
Terrain Crane S/N: 231622 C/W: Air Conditioner, Anti Tw iFlex5 Load Moment Indicato Crane Operation, 2011 US EP QSB 6 Cylinder 173 hp 6.7 L I ft Minimum 105 ft Maximum Auxiliary Hoist, Rooster Shea Extendable Swingaway Offse ton Capacity Johnson 3 Shea 354 lb 8.3 ton Capacity Overh Usage: 11,660 Hr	2011 Grove RT600E 50 ton 4x4x4 Rough Terrain Crane	-	
	Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball	587	
583	2009 Grove RT600E 50 ton 4x4x4 Rough Terrain Crane S/N: 229898 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, 10124 hrs Crane Operation, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, Overhaul Ball Usage: 10,124 Hr Asset located in: Humble, TX		McKissick 170 lb 1 Sheave 7 ton Capacity Hook Block, Dual Controls, A-Outriggers, Rear Outriggers, 20 ft 0 in x 96 in Bed Usage: 103,701 Mi Asset located in : Lake Worth, TX
		588	Ditch Witch C99 Walk Behind Trencher S/N: 116761 C/W: Gasoline Engine, 6 in Wide x 3 ft Long Dirt Trencher Chain, Discharge Conveyor Usage: Not Available Asset located in: Lake Worth, TX
		589	2000 Vermeer LM11 Walk Behind Cable Plow S/N: 1VRP04095Y1000294 C/W: Kawasaki FE350 Gasoline Engine, 6 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
590	Barreto 912 Walk Behind Trencher S/N: M2913 C/W: Honda GX270 1 Cylinder Gasoline Engine, 4 in Wide x 39 in Long Combination Trencher Chain, Crumbling Shoe Usage: 73 Hr Asset located in: Lake Worth, TX	599	CE OF 2 - Lot #'s: 599, 600 2014 Vermeer T755III Tracked Trencher S/N: 1VR2160RXE1000550
591	2018 Barreto E1324STK-4MS Walk Behind Trencher S/N: STK202 C/W: 2021 US EPA Label, Honda GX390 1 Cylinder Gasoline Engine, Hydrostatic Drive, 5 in Wide x 24 in Long Combination Trencher Chain, 7 in Rubber Tracks Usage: 303 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Cat C9 6 Cylinder 746 hp 8.8 L Diesel Engine, 16 in Wide x 11 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab Usage: 2,792 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
592	2007 Ditch Witch RT36 4x4 Trencher S/N: CMWRT36XJ70000141 C/W: Deutz Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Combination Trencher Chain, Angle Blade Usage: 1,182 Hr Asset located in: Lake Worth, TX	600	2012 Vermeer T755III Tracked Trencher S/N: 1VR2160R3C1000516 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C9 375 hp Diesel Engine, 12 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab,
593	2004 Charles Machine Works 3700DD 4x4 Trencher S/N: 3Y0864 C/W: Canopy, Diesel Engine, 5 in Wide x 87 in Long Dirt Trencher Chain, A322 Backhoe Attachment, Straight Blade		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,066 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Usage: 1,924 Hr Asset located in: Lake Worth, TX	601	2007 Vermeer T755III Tracked Trencher S/N: 1VR2190S371000123
594	2007 Ditch Witch RT155H 4x4 Trencher S/N: CMWRT115E70000255 C/W: Canopy, US EPA Label, John Deere 4 Cylinder 82 kW 4.5 L Diesel Engine, Hydrostatic Drive, 10 in Wide x 80 in Long Dirt Trencher Chain, Crumbling Shoe Usage: 452 Hr		C/W: Enclosed Cab, Air Conditioner, 2007 US EPA Label, Cat C9 6 Cylinder 480 hp 8.8 L Diesel Engine, 16 in Wide x 12 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab Usage: 5,025 Hr Notes: ; PLEASE SEE A PERSONAL NOTE
595	Asset located in: Lake Worth, TX 2001 Vermeer V120 4x4 Trencher	1	FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	S/N: 1VRT1124411000207 C/W: Canopy, Cummins 3 Cylinder Diesel Engine, Hydrostatic Drive, 6 in Wide x 9 ft 3 in Long Dirt Trencher Chain, Straight Blade Usage: 2,431 Hr Asset located in: Lake Worth, TX	602	2009 Tesmec TRS975 Tracked Trencher S/N: 975-111 C/W: Enclosed Cab, Air Conditioner, Cat C9DI 6 Cylinder 300 hp Diesel Engine, Hydrostatic Drive, 23 in Wide x 186 in Long Rock Trencher
596	2015 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XEF0002812 C/W: Deutz Diesel Engine, Hydrostatic Drive, 6		Chain, Crumbling Shoe, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: 4,256 Hr Asset located in : Midland, TX
	in Wide x 64 in Long Rock Trencher Chain, Straight Blade, Side Shift Usage: 996 Hr	603	2000 Tesmec 1075 Tracked Trencher S/N: 15211
597	Asset located in: Lake Worth, TX 2018 Vermeer RTX450 4x4 Trencher S/N: 1VR4092U0J1003787 C/W: 2017 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Hydrostatic Drive, 6 in Wide x 4 ft 8 in Long Combination Trencher Chain, Angle Blade, Side Shift Usage: 417 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Hydrostatic Drive, 24 in Trenching Width, 160 in Trenching Depth, Discharge Conveyor, Side Shift, Hydraulic Leveling, 22 in Single Grouser Track Shoes Usage: 185 Hr Asset located in: Midland, TX

Lot #	Details	Lot #	Details
604	1997 Trencor 960HD Tracked Trencher S/N: 136 C/W: Enclosed Cab, Air Conditioner, 6 Cylinder Engine, Trencor Cable Plow, 26 in Trenching Width, 84 in Trenching Depth, Discharge Conveyor, 24 in Triple Grouser Track Shoes Usage: 5,333 Hr Asset located in: Lake Worth, TX	609 1959 (unv Bucket W S/N: K328 C/W: Encl Engine, M Width, Dis Grouser T Usage: No Notes: ITE PICKED U SUBJECT Asset loca 610 Cleveland S/N: 3514 C/W: Can Diesel Eng Trenching Single Grousage: No Notes: ITE BE PICKE AUCTION SUBJECT BUYER RE NOT BE A THESE Asset loca 610A Cleveland S/N: K280 C/W: Can Engine, M Width, 84	E OF 2 - Lot #'s: 609, 610 1959 (unverified) Cleveland 320 Tracked Bucket Wheel Trencher S/N: K328 C/W: Enclosed Cab, Cat 4 Cylinder Diesel
605	1978 (unverified) Cleveland H320 Tracked Bucket Wheel Trencher S/N: 325300 C/W: Enclosed Cab, Cat D330 4 Cylinder Diesel Engine, Manual Transmission, 27 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available		Engine, Manual Transmission, 21 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
СНОІС	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK E OF 2 - Lot #'s: 606, 607		Cleveland 350 Tracked Bucket Wheel Trencher S/N: 3514110 C/W: Canopy, Cat 3304 4 Cylinder 165 hp Diesel Engine, Manual Transmission, 42 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available
Tro S/ C/ Tra Dis Tra Us No Plo SU	1974 Cleveland S320 Tracked Bucket Wheel Trencher S/N: K427 C/W: Canopy, Diesel Engine, Manual Transmission, 26 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
			Cleveland 320 Tracked Bucket Wheel Trencher S/N: K280 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 42 in Trenching Width, 84 in Trenching Depth, 18 in Single Grouser Track Shoes
607	1969 Cleveland 320 Tracked Bucket Wheel Trencher		Usage: Not Available Asset located in : Lahoma, OK
	S/N: K414 C/W: Enclosed Cab, Cat D333 6 Cylinder Diesel Engine, Manual Transmission, 25.5 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	610B	Cleveland 320 Tracked Bucket Wheel Trencher S/N: K364 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Asset located in: Lahoma, OK Cleveland 350S Tracked Bucket Wheel
		lo 10C	Trencher S/N: 3512290 C/W: Canopy, Cat 3304PC 4 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
614	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XLE0002319 C/W: 2004 US EPA Label, Deutz D2011 3 Cylinder 42 hp 2.33 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 3 in Long Dirt Trencher Chain Usage: 2,034 Hr Asset located in: Lake Worth, TX	621	2019 Ditch Witch JT20 Directional Drill S/N: DWPJT20BAK0000234 C/W: Open Operator Station, 2019 US EPA Label, Deutz 4 Cylinder Diesel Engine, Drill Rod Loading System 39 Drill Rods, 11 in Rubber Tracks Usage: 3,005 Hr Asset located in: Lake Worth, TX
615	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XHE0002029 C/W: US EPA Label, Deutz 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 5 in Long Dirt Trencher Chain, Straight	622	2017 Ditch Witch JT20 Directional Drill w/2016 Felling FT24 Trailer S/N: CMWJT20XKH0000950 C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, 30 Drill Rods, 11 in Rubber
	Blade Usage: 989 Hr Asset located in : Lake Worth, TX		Tracks, T/A Trailer w/ S/N- 5FTEE2923G1003458, Lunette Ring, Electric Brakes, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
616	2011 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XJC0001226 C/W: 2011 US EPA Label, Deutz D2011L03 3		Usage: Not Available Asset located in: Lake Worth, TX
	Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Combination Trencher Chain, Straight Blade Usage: 2,614 Hr		E OF 1 - Lot #'s: 625
617	Asset located in: Lake Worth, TX 2014 Ditch Witch RT45 4x4 Trencher Cable Plow S/N: CMWRT45XLE0002028 C/W: Canopy, 2011 US EPA Label, CARB Compliant, Deutz D2011L03 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 5 ft 4 in Cable Plow, 6 in Wide x 6 ft 4 in Long Combination Trencher Chain, Discharge Conveyor, H314 Traversing Trencher Attachment s/n: CMWH314XCD0002861 Usage: 2,993 Hr	625	2020 Vermeer Lp573xdt T/A Vacuum Excavation Unit S/N: 5HZJ16235LK002140 C/W: Aluminum Frame, Lunette Ring Hitch, 2019 Vermeer Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, 235/80R16 Tires, 1200 Ib GVWR, 2019 US EPA Label, Kohler 8 kW Diesel Engine Usage: 475 Hr Asset located in: Lake Worth, TX
618	Asset located in: Lake Worth, TX 2016 Vermeer D100X140S3 Directional Drill	Сноіс	E OF 1 - Lot #'s: 627
	S/N: 1VRB360W5G1000135 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Drill Rod Loading System 8 Drill Rods, 18 in Triple Grouser Track Shoes Usage: 4,790 Hr Asset located in: Lake Worth, TX	627	2015 Vermeer Vac-tron T/A Vacuum Excavation Unit S/N: 5HZBF1929FLCF2113 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Rear Hose Reel, 200 gal Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, 235/85R16 Tires, 14000 lb GVWR, 2014
619	2019 Vermeer D23x30III Directional Drill S/N: 1VRN20074K1001288 C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid,		US EPA Label, CARB Compliant, Yanmar 4TNV88C-DYEM 4 Cylinder 2.2 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
	Drill Rod Loading System 22 Drill Rods, 12 in Rubber Tracks Usage: Not Available Asset located in : Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 628, 9628A
620	2017 Vermeer 20X22III Directional Drill S/N: 1VRA170V3H1000764 C/W: 2016 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, Drill Rod Loading System 31 Drill Rods, 11 in Rubber Tracks Usage: 2,859 Hr Asset located in: Lake Worth, TX	628	2017 LOKT T/A Vacuum Excavation Unit S/N: 4M9E2TG23HE015031 C/W: Lunette Ring Hitch, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Drop Down Tailgate, Engine Driven Pump, 215/75R17.5 Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
630	Excavation Unit S/N: 1DST522N2N1701879 C/W: Spring Suspension, Electric Brakes, Steel Debris Tank, 500 gal Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Blower, 235/80R16 Tires, 2022 US EPA Label, Vanguard NBSXS.9932VB 2 Cylinder 31 hp 896 cc Gasoline Engine Usage: 162 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH	636	2012 Powerscreen XH250 Impact Crusher S/N: PIDXH250A0MC55102 C/W: Terex 7 ft Belt Feeder Terex CR004 Jaw Crusher, 2012 US EPA Label, Cat 6.6 L Diesel Engine, 16 in Triple Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX
		637	2023 Ark K-JC503 Jaw Crusher S/N: 323878 C/W: 1 ft 4 in x 6 ft 6 in Belt Feeder 12 in Rubber Tracks Usage: 186 Hr Asset located in: Lake Worth, TX
	YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	638	2020 Screen Machine 621ST Tracked Trommel Screen
631	Asset located in: Humble, TX 2011 Ditch Witch FX30 800 gal T/A Vacuum Excavation Unit S/N: 1DSB202S5B1702339 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Rear Hose Reel, 800 gal Fresh Water Tank, Manual Tailgate Locks, 8 ft Telescopic Boom, 4 in		S/N: 621ST1603 C/W: 5 ft 8 in x 14 ft 6 in Belt Feeder w/Grizzly Trommel Screen, 42 in Wide Feed Conveyor, 42 in Wide Under Screen Conveyor, 41 in Wide Left Discharge Conveyor, Cat 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 15.75 in Triple Grouser Track Shoes Usage: 307 Hr Asset located in: Lake Worth, TX
	Suction Hose, Engine Driven Pump, 215/75R17. 5 Tires, 18000 lb GVWR, Kubota D1105-T 3 Cylinder 1.1 L Diesel Engine Usage: 2,095 Hr Asset located in: Lake Worth, TX	639	2020 Terex/Finlay 883 Tracked Screen Plant S/N: TRX883M4CDGLB3827 C/W: 8 ft 7 in x 16 ft Apron Feeder 16 ft x 5 ft Double Deck Screen, 35 in Wide Fines Discharge Conveyor, 47 in Wide Under Screen Conveyor, 31 in Wide Left Discharge Conveyor 2020 US EPA Label, Cat C4.4 4 Cylinder 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Hydraulic Leveling, 15.75 in Triple Grouser Track Shoes Usage: 1,040 Hr Asset located in: Lake Worth, TX
632	2011 Vermeer VX50500 Vacuum Excavation Unit S/N: 1M9FE122XBS284256 C/W: Ball Hitch, Spring Suspension, Electric Brakes, McLaughlin Mfg Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Engine		
	Driven Pump, 235/80R16 Tires, 12000 lb GVWR, 3 Cylinder Diesel Engine Usage: Not Available Asset located in : Lake Worth, TX	640	2004 McCloskey 621RE Portable Trommel Screen S/N: 11915
634	2000 Vermeer Vac-tron Vacuum Excavation Unit S/N: 1A9AF152XYF495615 C/W: Lunette Ring Hitch, Spring Suspension, Steel Debris Tank, Fresh Water Tank, Full Open		C/W: 21 ft x 6 ft Trommel Screen, 35 in Wide Feed Conveyor, 40 in Wide Under Crusher Conveyor, Cat 6 Cylinder Diesel Engine, T/A Carrier, Spring Suspension, Hydraulic Leveling Usage: 525 Hr Asset located in: Lake Worth, TX
	Tailgate, Manual Tailgate Locks, 235/85R16 Tires, Kohler 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	СНОІСІ	E OF 4 - Lot #'s: 641, 642, 643, 644
635	1998 Nordberg LTC1416 Tracked Impact Crusher Plant S/N: 1291 C/W: Vibratory Pan Feeder 48 in Wide Under Crusher Conveyor, Radio Remote Control, 1997 US EPA Label, Cat 3406 6 Cylinder 328 kW Diesel Engine, 21.75 in Triple Grouser Track Shoes Usage: 2,847 Hr Notes: THIS UNIT MOVES ON ITS OWN WHEN IDLED UP. LOADING ASSISTANCE UNAVAILABLE ON THIS ITEM. BUYER WILL NEED TO SET UP OUTSIDE ASSISTANCE. Asset located in: Lake Worth, TX	641	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409548 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
642	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409547 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	649	2018 Bomag RS460 Wheel Soil Stabilizer Reclaimer S/N: 101590161008 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires AdBlue, 96 in Rotor, Water /Emulsion Application System, 19.7 in Cutting Depth Usage: 1,584 Hr Asset located in: Baytown, TX
	Asset located in: Lake Worth, TX	650	2016 Cat RM300 Wheel Soil Stabilizer Reclaimer
643	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409550 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring		S/N: CATRM300HBWR00791 C/W: Canopy, 96 in Soil Rotor, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: 4,284 Hr Asset located in: Humble, TX
644	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	651	Bomag MPH364R-2 Wheel Soil Stabilizer Reclaimer S/N: Not Available C/W: Canopy, 2013 US EPA Label, 84 in Combination Rotor, 14 in Cutting Depth, Water /Emulsion Application System Usage: 3,562 Hr
644	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused)		Asset located in: Poteau, OK
	S/N: M202409549 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	652	2021 Vogele S2100-31 Track Asphalt Paver S/N: 08192375 C/W: Canopy, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in - 9 ft 8 in Screed, 12 in Rubber Tracks Usage: 2,345 Hr Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	653	2011 Cat AP1055E Track Asphalt Paver
645	JCT Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2012 Klein KPT-120 12000 gal S/A Water	_	S/N: CATAP105CTJF00111 C/W: Dual Controls, CAT AS3301C 10 ft 4 in - Screed, On Board Generator, 17 in Rubber Tracks Usage: 17,079 Hr Asset located in: Lake Worth, TX
040	Tower S/N: 40797 C/W: Hydraulic Raise, Gasoline Engine Driven Hydraulic Power Pack, 12 in Downspout, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	655 CHOIC	2005 Cat AP-655C Track Asphalt Paver S/N: CATAP655PAYP00240 C/W: Dual Controls, Carlson Electric Heated 8 ft - 13 ft 6 in Screed, 16 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 656, 657
648	2020 RoadHog RH60250 60" Wheel Loader	-	0001 Oct AD CEOD Trook Apple Dover
0-70	Cold Planer Attachment S/N: 2009026 C/W: Cat C7.1, 250hp, Diesel, Diesel Exhaust Fluid, Q/C, Side Shift, 80 Gallon Water Tank Usage: 37 Hr Asset located in: Lake Worth, TX	656	2001 Cat AP-650B Track Asphalt Paver S/N: 9DN00434 C/W: Fume Extractor, Cat 7MRO2145, 8-16B Diesel Heated 8 ft 4 in - 15 ft 8 in Screed, 13.5 in Single Grouser Track Shoes w/Rubber Inserts Usage: Not Available
648A	16 Ft Trimmer Head - Fits Gomaco 9500 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
657	2000 Cat AP-650B Track Asphalt Paver S/N: 9DN00414 C/W: 8 ft 4 in - Screed, 14 in Track Shoes w /Rubber Inserts Usage: 6,827 Hr Asset located in: Lake Worth, TX	664A	S/N: 1HTSHAAR91H370891 C/W: International DT466 6 Cylinder 7.6 L Diesel 250 hp Engine, 2000 US EPA Label, 171 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 52220 lb
658	Roadtec RP195 Track Asphalt Paver S/N: 10950808 C/W: Dual Controls, Carlson Electric Heated 10 ft - 19 ft Screed, 18 in Rubber Tracks Usage: Not Available		GVWR, 11R22.5, Double Frame, Hendrickson RT /RTE Series Suspension, 188 in Wheelbase, PTO, Arrow Board Usage: 15,865 Mi Asset located in: Lake Worth, TX 2016 Cimline 410 Magma Pothole Patcher
659	Asset located in: Lake Worth, TX 2007 Mauldin 1750C Track Asphalt Paver S/N: 879G75TJS6Y201879 C/W: Dual Controls, Propane Heated 7 ft 6 in - 16 ft Screed, 12 in Track Shoes w/Rubber Pads Usage: Not Available	665	S/N: 1G9441622GM119018 C/W: Isuzu 3cj1 4 Cylinder .99 L Diesel Engine, 225/75R15, Spring Suspension, Diesel Heating System Usage: 1,838 Hr Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	667	2008 (unverified) Valmet 430FXL Track Feller Buncher S/N: AT4K-2992-052108
660	Mauldin 690G Track Asphalt Paver S/N: 459Q69TKS8Y203459 C/W: Dual Controls, Propane Heated 8 ft 1 in - 13 ft 3 in Screed, 12 in Rubber Tracks Usage: 934 Hr		C/W: Air Conditioner, Hydraulic Tilting Cab, US EPA Label, Quadco OFH 22 in Feller Buncher, 27.5 in Single Grouser Track Shoes, Rock Guards Usage: 969 Hr Asset located in: St. Rose, LA
	Asset located in: Lake Worth, TX		·
661	1982 Blaw-Knox RW100 Road Widener S/N: 956003 C/W: Open Operator Station, John Deere Engine, Automatic Transmission, 10 " Spreader Width, Truck Hitch, Open Operator Station, Dual Controls, John Deere 4 Cylinder Diesel Engine,	669	2003 Cat 525B 4x4 Line Skidder S/N: CAT0525BK3KZ00929 C/W: Air Conditioner, Blade, Single Arch, cat Single Drum Winch, 30.5x32 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Hydrostatic Drive, - 10 ft Spreading Width, Truck Hitch, 20 in Conveyor Usage: 430 Hr Asset located in : Poteau, OK	670 2013 John Deere 2954D Log Loader S/N: 1FF2954DED0290150 C/W: Air Conditioner, Air Ride Seat, Cab Screens, Hydraulic Tilting Cab, 31.5 in Tripl	
663	2016 Crafco 125D Asphalt Kettle S/N: 1C9SV1221G1418015 C/W: 125 gal Capacity Tank, Diesel Fired Heater, Hydraulic Agitator, Hydraulic Driven		Grouser Track Shoes, Rock Guards, ROTOBEC Log Grapple Usage: 9,719 Hr Asset located in: Lake Worth, TX
	Pump, Hose & Wand, Air Compressor, T/A Trailer Mounted Usage: 554 Hr	671	Finn T-30 Hydroseeder S/N: RUA730 C/W: Ball Hitch, Spring Suspension, ST8-14.5
664	Asset located in: Lake Worth, TX Etnyre 2000 gal on 2002 GMC C7500 4x2 Asphalt Distributor Truck S/N: 1GDM7H1C82J513848 C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 hp Engine, 2002 US EPA Label, 5-Speed Manual Transmission, 11000 lb Front Axle, 22000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 13 ft 2 in Folding Spray Bar, Diesel Burners, In-Cab Controls Usage: 50,865 Mi Asset located in: Lake Worth, TX	672	Tires, Aluminum Tank, Gasoline Powered Pump, T/A Utility Trailer Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX 2011 Barko 930B 4x4 Mulcher Tractor S/N: 11293023740 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, Fecon 225 7 ft, Mulcher Usage: 628 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
674	Demco Model HP 60 ft T/A Pull-Type Sprayer S/N: Not Available C/W: 540 PTO, ISOBUS, PTO Driven Pump, 500 gal Poly Tank, Chemical Mix Tank, Rinse Tank, Single Nozzle Bodies, Fence Row Nozzles, 11l-15, Hydraulic Fold Booms, Guidance and Auto Steer Ready, Section Control, 29 In. Ground Clearance, Dual Agitators, Front Tank Walkway Usage: Not Available Notes: PERSONAL SPRAYER FOR LONGTIME	678	2017 Terramac RT-14 Crawler Carrier S/N: 14C0040 C/W: 13 ft 6 in Long x 2 ft High Dump Body, 32 in Rubber Tracks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,912 Hr
			Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	CUSTOMER - FULLY OPERATIONAL	670	Asset located in: Lake Worth, TX
CHOIC	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 675, 676	679	2017 Terramac RT-14 Crawler Carrier S/N: 14C0036 C/W: Enclosed Cab, Air Conditioner, 13 ft 6 in Long Flatbed Dump Body, 32 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,703 Hr
675	2023 Bell TC7A Crawler Carrier S/N: AEBK607AA01000128 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High		Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Flatbed Dump Body, 27 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 30 Hr	СНОІС	E OF 2 - Lot #'s: 680, 681
	Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	680	2019 Morooka MST2200VD Crawler Dumper S/N: A2202131
.76	Asset located in: Lake Worth, TX	-	C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive
676	2022 Bell TC7A Crawler Carrier S/N: AEBK607AC01000118 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High Flatbed Dump Body, 27 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 26 Hr		Usage: 2,294 Hr Asset located in : Baytown, TX
		681	2019 Morooka MST2200VD Crawler Carrier S/N: A2202124 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2018 US EPA Label, Cat 6 Cylinder Diesel Engine, 29.5 in Rubber Tracks, 9 ft Wide
	Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		x 12 ft 9 in Long Flatbed Usage: 2,393 Hr Asset located in: Baytown, TX
	Asset located in: Lake Worth, TX		Asset located III. Baytowii, 1A
CHOIC	E OF 3 - Lot #'s: 677, 678, 679	СНОІС	E OF 2 - Lot #'s: 682, 683
677	2018 Terramac RT-14 Crawler Carrier S/N: 14G0060 C/W: Enclosed Cab, Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13 ft 6 in Long x 2 ft High Flatbed Dump Body, 31 in Rubber Tracks, Stake Sides; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,183 Hr Notes:; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	682	2015 Morooka MST-2200VD Crawler Carrier S/N: A220291 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 13 ft Long Flatbed Dump Body, 30 in Rubber Tracks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 679 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	683	2015 Morooka MST-2200VD Crawler Carrier S/N: A220247 C/W: Enclosed Cab, Air Conditioner, 13 ft Long Flatbed Dump Body, 30 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,659 Hr Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
	E OF 2 - Lot #'s: 684, 685	691	Morooka MST1500 Crawler Carrier S/N: 151791 C/W: Canopy, 9 ft 10 in Long Flatbed Dump
684	2014 Morooka MST-2200VD Crawler Carrier S/N: 223666 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Cat C7 6 Cylinder 7.2 L Diesel Engine, 30 in Rubber Tracks, 9 ft 2 in Wide x 13 ft 4 in Long Flatbed Usage: 4,082 Hr		Body, 26 in Rubber Tracks, Lincoln 300D Welder w/ Leads; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 8,681 Hr Notes:; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS	СНОІС	E OF 2 - Lot #'s: 692, 693
685	2011 Morooka MST-2200VD Crawler Carrier S/N: 223442 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C7 6 Cylinder 7.2 L Diesel Engine, 30 in Rubber Tracks, 13 ft 4 in Long Flatbed Dump Body Usage: 6,040 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	692	2018 Canycom S25A Crawler Carrier S/N: 9161386 C/W: Canopy, US EPA Label, Kubota V2203-M-ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 1 ft 2 in High Dump Body Usage: 194 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	Asset located in: Louisville, MS	602	Asset located in: Louisville, MS
CHOICE	2019 Morooka MST1500VD Crawler Carrier S/N: A1505075 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Cat C 7.1 Diesel Engine, Requires Diesel Exhaust Fluid, 27 in Rubber Tracks, 10 ft 5 in Long Flatbed Dump Body	693	2018 Canycom S25A Crawler Carrier S/N: 9161385 C/W: Canopy, US EPA Label, Kubota V2203-M- ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 2 ft 2 in High Dump Body Usage: 1,799 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	Usage: 864 Hr		Asset located in: Louisville, MS
688	Asset located in: Beaumont, TX 2019 Morooka MST1500VD Crawler Carrier S/N: A1505077 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Cat C 7.1 Diesel Engine, Requires Diesel Exhaust Fluid, 27.5 in Rubber Tracks, 10 ft 5 in Long Flatbed Dump Body Usage: 1,005 Hr Asset located in: Beaumont, TX	S/I C/V Mit She Mo 18 Tu 0 ir	IHI IC45-2 Crawler Carrier Digger Derrick S/N: CE000842 C/W: Enclosed Cab, Tier 2, 2018 US EPA Label, Mitsubishi 6 Cylinder Diesel Engine, 44 ft Sheave Height, 26250 lb Capacity, Rear Mounted, 33 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Turret Mounted Winch, One-Man Basket, 10 ft 0 in Body, X-Type Outriggers, Rear Outriggers, Bumper Mounted Winch, Hydraulic Hose Reel,
690	2019 Morooka MST1000VD Crawler Carrier S/N: A1001007 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Diesel Engine, Requires Diesel Exhaust Fluid, 23.5 in Rubber Tracks, 10 ft Long Flatbed Dump Body Usage: 1,115 Hr Asset located in: Beaumont, TX		24 in Rubber Tracks Usage: 3,193 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS

Lot #	Details	Lot #	Details
695	IHI IC45-2 Crawler Carrier Aerial Lift w/2001 Terex HI-Ranger HR46M S/N: CE000831 C/W: Canopy, 2007 US EPA Label, Mitsubishi S6S-DTDP 6 Cylinder 99 hp 5.0 L Diesel Engine, 26250 lb Capacity, Rear Mounted, One-Person Articulated Boom, Flatbed, Turret Mounted Winch, X-Type Outriggers, Rear Outriggers, Bumper Mounted Winch, Hydraulic Hose Reel, 24 in Rubber Tracks Usage: 2,407 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS	701 CHOIC 702 703	2019 Cat 262D Skid Steer Loader S/N: CAT0262DKDTB09532 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Tier 4, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 1,988 Hr Asset located in: Lake Worth, TX CE OF 4 - Lot #'s: 702, 703, 704, 705 2020 Bobcat S570 Skid Steer Loader S/N: ALM429836 C/W: Open Operator Station, Creep Mode,
696	2018 Cat 272D2XHP Two-Speed Skid Steer Loader S/N: CAT0272DTMD200939 C/W: Air Ride Seat, Joystick Steering, Rear View Camera, 9 Pin Electric Kit, Hydraulic Coupler, 80 in Bucket, Counterweight Kit Usage: 6,905 Hr Asset located in: Lake Worth, TX		Joystick Steering, Control Pattern Changer, Self Leveling, 2019 US EPA Label, Aperture Tires, Manual Coupler, 74 in Bucket Usage: 932 Hr Asset located in: Lake Worth, TX 2020 Bobcat S570 Skid Steer Loader S/N: ALM429810 C/W: Open Operator Station, 2019 US EPA
697A	2016 Cat 272D2 Two-Speed High Flow XPS Skid Steer Loader		Label, Manual Coupler, 67 in Bucket Usage: 1,237 Hr Asset located in : Lake Worth, TX
	S/N: CAT0272DABL200550 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket Usage: 6,097 Hr Asset located in: Lake Worth, TX	704	2020 Bobcat S570 Skid Steer Loader S/N: ALM429670 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 66 in Bucket Usage: 1,759 Hr Asset located in: Lake Worth, TX
697B	2016 Cat 272D2 Two-Speed Skid Steer Loader S/N: CAT0272DLBL200551 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket Usage: 6,474 Hr Asset located in: Lake Worth, TX	705	2017 Bobcat S570 Skid Steer Loader S/N: ALM418117 C/W: Open Operator Station, 2017 US EPA Label, Manual Coupler, 66 in Bucket Usage: 751 Hr Asset located in: Lake Worth, TX
698A	2014 Cat 272D Two-Speed Skid Steer Loader S/N: CAT0272DHB5W00695 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 9 Pin Electric Kit, Manual Coupler, 72 in Bucket Usage: 6,717 Hr Asset located in: Lake Worth, TX	CHOIC 706	E OF 2 - Lot #'s: 706, 707 2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BCTNK01891 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket
699	2021 Bobcat S66 Two-Speed Skid Steer Loader S/N: B4SA12489 C/W: Open Operator Station, Joystick Steering, Manual Coupler Usage: 985 Hr Asset located in: Lake Worth, TX	707	Usage: 13,461 Hr Asset located in: Lake Worth, TX 2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BHTNK01905 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 73 in Bucket
700	2015 Bobcat S630 Skid Steer Loader S/N: AHGL11719 C/W: Open Operator Station, 2014 US EPA	708	Usage: 11,292 Hr Asset located in: Lake Worth, TX Gehl R165 Skid Steer Loader
	Label, Manual Coupler, 66 in Bucket Usage: 9,891 Hr Asset located in: Lake Worth, TX		S/N: GHL0R165E00197514 C/W: Open Operator Station, 2015 US EPA Label, Manual Coupler Usage: 2,245 Hr Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
709	2014 Cat 246D Skid Steer Loader S/N: CAT0246DHBYF01000 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2014 US EPA Label, 9 Pin Electric Kit, Electric Coupler, 68 in Bucket Usage: 6,328 Hr	CHOIC 722	E OF 1 - Lot #'s: 722 2020 Cat 299D3 Two-Speed Compact Track Loader S/N: CAT0299DADY902326
710	Asset located in: Lake Worth, TX 710 2021 John Deere 318G Skid Steer Loader S/N: 1T0318GKCMJ407875 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2021 US EPA Label, Aperture Tires, 9 Pin Electric Kit, Hydraulic Coupler, Counterweight Kit		C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Rear View Camera, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 3,301 Hr Asset located in: Lake Worth, TX
711	Usage: 1,521 Hr Asset located in: Lake Worth, TX 2020 Cat 242D3 Two-Speed Skid Steer Loader S/N: CAT0242DAHSX00818 C/W: Open Operator Station, Joystick Steering, Tier 4, 2019 US EPA Label, Manual Coupler, 74 in Bucket	724	2019 Cat 299D3XE Two-Speed Compact Track Loader S/N: CAT0299DCBX901368 C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, 17 in Track Belts, Manual Coupler Usage: 2,412 Hr
	Usage: 2,764 Hr Asset located in: Lake Worth, TX	725	Asset located in: Lake Worth, TX 2019 Cat 299D2XHP Two-Speed High Flow Compact Track Loader
	E OF 2 - Lot #'s: 712, 713		S/N: CAT0299DEDX204437 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Rear View Camera, 15 in Track Belts, Hydraulic Coupler,
712	2014 Cat 242D Skid Steer Loader S/N: CAT0242DTDZT00301 C/W: Open Operator Station, Joystick Steering, Tier 4, 2013 US EPA Label, Manual Coupler, 68 in Bucket		84 in Bucket, Counterweight Kit Usage: 2,589 Hr Asset located in: Lake Worth, TX
	Usage: 2,904 Hr Asset located in: Midland, TX	СНОІС	E OF 2 - Lot #'s: 726, 727
713	2015 Cat 242D Skid Steer Loader S/N: CAT0242DEDZT01204 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Tier 4, 2014 US EPA Label, Hydraulic Coupler, 74 in Bucket Usage: 1,273 Hr Asset located in: Midland, TX	726	2019 Cat 299D2 Two-Speed Compact Track Loader S/N: CAT0299DCFD205903 C/W: Enclosed Cab, Air Ride Seat, Joystick Steering, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 78 in Bucket Usage: 2,224 Hr
718	2012 Bobcat S150 Skid Steer Loader S/N: A3L485751 C/W: Enclosed Cab, Manual Coupler, 70 in Usage: 2,765 Hr Asset located in: Lake Worth, TX	727	Asset located in: Lake Worth, TX 2019 Cat 299D2 Two-Speed Compact Track Loader S/N: CAT0299DHFD205803 C/W: Open Operator Station, Air Ride Seat,
720	2006 Bobcat S205 Skid Steer Loader S/N: 530512291 C/W: Open Operator Station, Tier 2, 2006 US EPA Label, Aperture Tires, Manual Coupler, 66 in Grapple Bucket, EQUIPMENT-FROM-US- AUTO-RECYCLING		Joystick Steering, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 80 in Bucket Usage: 2,733 Hr Asset located in : Lake Worth, TX
	Usage: 2,830 Hr Asset located in: Lake Worth, TX	Compact Track Loader	•
721	Case 1845C Skid Steer Loader S/N: 4810330 C/W: Enclosed Cab, Manual Coupler, 73 in Bucket Usage: 335 Hr Asset located in: Lake Worth, TX		S/N: 412002791 C/W: Enclosed Cab, Control Pattern Changer, Rear View Camera, 17.5 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 79 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,813 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
728	2017 Takeuchi TL12R2-CR Compact Track Loader S/N: 412100427	сноіс	E OF 2 - Lot #'s: 734, 735
	C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Coupler, 81 in Bucket Usage: 1,197 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	734	2022 Bobcat T76 Compact Track Loader S/N: B4CE19605 C/W: Open Operator Station, Joystick Steering, 2021 US EPA Label, Manual Coupler, 72 in Bucket Usage: 1,897 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
728A	2020 Cat 289D3 Two-Speed High Flow XPS Compact Track Loader S/N: CAT0289DCJX903131 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2020 US EPA Label, 18 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 5,426 Hr	735	2022 Bobcat T76 Compact Track Loader S/N: B4CE17367 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, Manual Coupler, 79 in Bucket Usage: 2,765 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	736	2020 Bobcat T76 R-Series Compact Track
731	2020 Cat 279D3 Compact Track Loader S/N: CAT0279DTRB901084 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2019 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler, 86 in Bucket, Counterweight Kit Usage: 2,944 Hr	700	Loader S/N: B4CE11296 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2019 US EPA Label, 12.5 in Track Belts, Manual Coupler, 80 in Bucket Usage: 1,481 Hr
	Asset located in: Beaumont, TX		Asset located in: Lake Worth, TX
731A	2019 Bobcat T770 Two-Speed Compact Track Loader (Inoperable) S/N: AT6321914 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 66 in Bucket, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,269 Hr Notes: UNIT STARTS AND RUNS, HYDRAULICS FUNCTIONAL Asset located in: Lake Worth, TX	– 737	2015 Bobcat T750 Compact Track Loader S/N: ATF614726 C/W: Open Operator Station, 18 in Track Belts, Manual Coupler, 76 in Bucket Usage: 4,848 Hr Asset located in: Lake Worth, TX
		738	2012 Bobcat T750 Compact Track Loader S/N: ANKA12005 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Manual Coupler Usage: 4,888 Hr
	,	┧	Asset located in: Lake Worth, TX
CHOIC 732	2017 Bobcat T770 Compact Track Loader S/N: AT6314655 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 66 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,422 Hr Asset located in: Lake Worth, TX	738A	2012 Bobcat T750 Compact Track Loader S/N: ANKA11840 C/W: Enclosed Cab, Joystick Steering, 18 in Track Belts, Hydraulic Coupler, 78 in Bucket Usage: 5,692 Hr Asset located in: Lake Worth, TX
		739	2019 Bobcat T740 Two-Speed Compact Track Loader S/N: B3CA15269 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 18 in Track
733	2016 Bobcat T770 Compact Track Loader S/N: AT6312284 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 17.5 in Track Belts, 7 Pin Electric Kit, Manual Coupler, 80 in Bucket Usage: 3,647 Hr Asset located in: Lake Worth, TX		Belts, Hydraulic Coupler, 78 in Bucket Usage: 3,052 Hr Asset located in : Lake Worth, TX
Steering Pin Elec Usage: 3		740	2022 John Deere 333G Compact Track Loader S/N: 1T0333GMCNF420256 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Hydraulic Coupler, 83 in Bucket Usage: 726 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICE OF 3 - Lot #'s: 741, 742, 743		746	2019 Kubota SVL95-2HFC Compact Track Loader S/N: KBCC0953LK1E47027
741	2016 John Deere 329E Compact Track Loader S/N: 1T0329EKHGE294140 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Control Pattern Changer, 17 in Track Belts, Manual Coupler, 83		C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler Usage: 1,501 Hr Asset located in: Lake Worth, TX
	in Bucket Usage: 2,760 Hr Asset located in : Lake Worth, TX	749	2017 Kubota SVL95-2SHF Compact Track Loader
742	2014 John Deere 329E Compact Track Loader S/N: 1T0329EMCEE255596 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 17.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit		S/N: JKU00953001S34806 C/W: Open Operator Station, Joystick Steering Tier 4, 2017 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler Usage: 4,389 Hr Asset located in: Lake Worth, TX
	Usage: 3,794 Hr Asset located in: Lake Worth, TX	750	Kubota SVL95-2S Compact Track Loader S/N: 1024968
743	2021 John Deere 325G Two-Speed Compact Track Loader S/N: 1T0325GKEMJ407899 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Control Pattern Changer,		C/W: Open Operator Station, Joystick Steering Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 70 in Bucket Usage: 1,813 Hr Asset located in: Lake Worth, TX
	2021 US EPA Label, 15.5 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, Counterweight Kit Usage: 1,692 Hr Asset located in : Lake Worth, TX	751	2012 Kubota SVL90 Compact Track Loader S/N: 1003128 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2011 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler
743A	Case TV380 Two-Speed Compact Track Loader S/N: JAFTV380AJM452078	752	Usage: 1,052 Hr Asset located in : Lake Worth, TX
	C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available Asset located in : Lake Worth, TX		S/N: KBCZ053CTP1E12118 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manua
744	2015 Case TV380 Compact Track Loader S/N: JAFTV380HEM482982		Coupler Usage: 388 Hr Asset located in : Humble, TX
	C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, Manual Coupler, 86 in Bucket Usage: Not Available Asset located in : Lake Worth, TX	754	2019 Kubota SVL95-2S Compact Track Loader S/N: KBCC0953PK1E47374 C/W: Enclosed Cab (Door missing), Air
CHOICE OF 2 - Lot #'s: 745, 746			Conditioner, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18 ir Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: 318 Hr
745	2020 Kubota SVL95-2S Compact Track Loader		Asset located in: Midland, TX
	S/N: KBCZ063CJL1F51637 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 17 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 1,986 Hr		E OF 3 - Lot #'s: 756, 757, 758
	Asset located in: Lake Worth, TX	756	2019 Kubota SVL75-2 Compact Track Loader S/N: KBCC0752TK1J46403 C/W: Open Operator Station, Joystick Steering 16 in Track Belts, Manual Coupler, 72 in Bucket Usage: 1,718 Hr

Lot #	Details	Lot #	Details
757 758	2019 Kubota SVL75-2 Compact Track Loader S/N: KBCC0752VK1J46375 C/W: Open Operator Station, Joystick Steering, 13 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,369 Hr Asset located in: Lake Worth, TX 2018 Kubota SVL75-2 Compact Track Loader S/N: JKUC0752L01S38233 C/W: Open Operator Station, Joystick Steering, 15.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,370 Hr Asset located in: Lake Worth, TX	765	2021 Bobcat T64 R-Series Compact Track Loader S/N: B4SD12149 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,494 Hr Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 766, 767
760	2021 Wacker Neuson ST45 LF CTL Vert Compact Track Loader S/N: WNCS0606TPUM00800 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Control Pattern Changer, 2023 US EPA Label, 16.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 1,666 Hr	766	2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506CPUM01235 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts, Hydraulic Coupler, 76 in Bucket Usage: 513 Hr Asset located in: Humble, TX
761	Asset located in: Lake Worth, TX 2018 Wacker Neuson ST45 Compact Track Loader S/N: WNCS0404PPUM01126 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 2018 US EPA Label, 18 in Track Belts, Manual Coupler, 66 in Bucket Usage: 499 Hr	767 - 	2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506HPUM01189 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts, Manual Coupler Usage: 491 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
762	Asset located in: Lake Worth, TX 2019 LiuGong 388B Compact Track Loader S/N: LGZ388BZCKZ010679 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Coupler, 82 in Bucket Usage: 4,737 Hr Asset located in: Lake Worth, TX	769	2018 Case TR310 Compact Track Loader S/N: JAFTR310VJM449341 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 76 in Bucket Usage: 3,253 Hr Asset located in: Lake Worth, TX
СНОІС	E OF 3 - Lot #'s: 763, 764, 765	сноіс	E OF 2 - Lot #'s: 771, 9635A
763	2021 Bobcat T64 Compact Track Loader S/N: B4SD13020 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,018 Hr Asset located in: Lake Worth, TX	771	2019 Bobcat T590 Compact Track Loader S/N: ALJU31295 C/W: Open Operator Station, 2019 US EPA Label, CARB Compliant, 13 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,490 Hr Asset located in: Lake Worth, TX
764	2021 Bobcat T64 Compact Track Loader S/N: B4SD12133 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,051 Hr Asset located in: Lake Worth, TX	CHOIC	E OF 2 - Lot #'s: 772, 773 2017 Bobcat T590 Compact Track Loader S/N: ALJU23267 C/W: Open Operator Station, 2017 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,715 Hr Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
773	2017 Bobcat T590 Compact Track Loader S/N: ALJU23698 C/W: Open Operator Station, Joystick Steering, 2017 US EPA Label, 12 in Track Belts, Manual Coupler, 57 in Bucket, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,084 Hr	782	2021 Cat 259D3 Compact Track Loader S/N: CAT0259DJCW914734 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Tier 4, 2021 US EPA Label, 12 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,523 Hr
	Asset located in: Lake Worth, TX	700	Asset located in: Lake Worth, TX
CHOICE OF 1 - Lot #'s: 775 775 2015 Bobcat T590 Compact Track Loader S/N: ALJU14338 C/W: Open Operator Station, 2014 US EPA Label, 12.5 in Track Belts, Manual Coupler		 783	2021 Cat 259D3 Two-Speed Compact Track Loader S/N: CAT0259DCCW907770 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2020 US EPA Label, 16 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,817 Hr Asset located in: Lake Worth, TX
	Usage: 3,479 Hr Asset located in: Lake Worth, TX	784	2018 Cat 259D Two-Speed Compact Track
776	2019 Bobcat T550 Compact Track Loader S/N: AJZV23563 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, Forks Usage: 1,453 Hr Asset located in: Lake Worth, TX		Loader S/N: CAT0259DLFTL16672 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 13 in Track Belts, Manual Coupler Usage: 3,619 Hr Asset located in: Lake Worth, TX
778	2019 Takeuchi TL10V2 Compact Track Loader		
	S/N: 410002668 C/W: Open Operator Station, Joystick Steering,	CHOICE OF 3 - Lot #'s: 785, 786, 787	
779	Tier 4, 2019 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,355 Hr Asset located in: Lake Worth, TX 2017 Takeuchi TL10V-2 Compact Track Loader	785	2017 Cat 259D Compact Track Loader S/N: CAT0259DLFTL12430 C/W: Open Operator Station, Joystick Steering, Tier 4, 2021 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in Bucket Usage: 7,140 Hr
	S/N: 410000884 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 62 in Bucket Usage: 2,690 Hr	786	Asset located in: Lake Worth, TX 2016 Cat 259D Compact Track Loader S/N: CAT0259DLFTL07339
780	Asset located in: Lake Worth, TX 2022 ASV RT-135 Two-Speed Compact Track Loader		C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Self Leveling, Tier 4, 2022 US EPA Label, 12.5 in Track Belts, Manual Coupler, 75 in Bucket Usage: 6,778 Hr
	S/N: ASVRT135ANDS00237 C/W: Enclosed Cab, Air Conditioner, 2021 US		Asset located in: Lake Worth, TX
	EPA Label, 17 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, 80 in Bucket Usage: 460 Hr Asset located in: Lake Worth, TX	787	2016 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DEFTL08493 C/W: Open Operator Station, Joystick Steering,
CHOICE OF 3 - Lot #'s: 781, 782, 783			Tier 4, 2016 US EPA Label, 16 in Track Belts, Manual Coupler, 79 in Bucket Usage: 4,493 Hr Asset located in : Lake Worth, TX
781	2021 Cat 259D3 Two-Speed Compact Track Loader S/N: CAT0259DECW912426 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 1,011 Hr Asset located in: Lake Worth, TX	788	2012 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BCYYZ02661 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 66 in Bucket Usage: 3,600 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
789	2011 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BPYYZ00856 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 12.5 in Track Belts, Manual Coupler, 72 in Bucket Usage: 4,736 Hr	798	2019 Bobcat T450 Compact Track Loader S/N: AUVP16910 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 73 in Bucket Usage: 636 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	799	2019 Bobcat T450 Compact Track Loader
790	2018 Takeuchi TL8 Two-Speed Compact Track Loader S/N: 200806258 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 12.5 in Track Belts,		S/N: AUVP15804 C/W: Open Operator Station, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 772 Hr Asset located in : Lake Worth, TX
	14 Pin Electric Kit, Manual Coupler Usage: 2,652 Hr Asset located in : Lake Worth, TX	800	2019 Bobcat T450 All-Wheel Steer Compact Track Loader
792	2020 Gehl RT165 Compact Track Loader S/N: GHLRT165GOD302276 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, Manual Coupler Usage: 397 Hr		S/N: AUVP16039 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 954 Hr Asset located in : Lake Worth, TX
Asset located in: Lake Worth, TX CHOICE OF 8 - Lot #'s: 793, 794, 795, 796, 797, 798, 799, 800		801	2009 Bobcat T180 Compact Track Loader S/N: A3LL30017 C/W: Open Operator Station, 2008 US EPA Label, 12.5 in Track Belts, Manual Coupler, 67 in Bucket
793	2020 Bobcat T450 Compact Track Loader		Usage: 3,840 Hr Asset located in : Lake Worth, TX
	S/N: AUVP16938 C/W: Open Operator Station, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 675 Hr Asset located in : Lake Worth, TX	802	2003 Cat 277 Compact Track Loader S/N: CAT00277LCNC02031 C/W: Open Operator Station, Joystick Steering, 18 in Track Belts, Manual Coupler, 79 in Bucket Usage: 6,389 Hr Asset located in: Lake Worth, TX
794	2020 Bobcat T450 Compact Track Loader S/N: AUVP16950 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 802 Hr Asset located in: Lake Worth, TX	802A	John Deere 5203 2WD Utility Tractor S/N: PY5203U004017 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, SyncReverser, 2005 US EPA Label, 540 PTO, 3-Point Hitch, Drawbar, 7.50-16 Front Tires, 14.9x28 Rear Tires Usage: 119 Hr
795	2020 Bobcat T450 Compact Track Loader S/N: AUVP16939		Asset located in: Lake Worth, TX
	C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 910 Hr Asset located in : Lake Worth, TX	803	2010 John Deere 5045E 4WD Utility Tractor S/N: PY5045E000742 C/W: Differential Lock, Forward/ Reverse Shuttle, John Deere 553 Loader w/Joystick, Quick Coupler, John Deere 68 in Bucket, 1 Rear
796	2020 Bobcat T450 Compact Track Loader S/N: AUVP17085 C/W: Open Operator Station, Joystick Steering, 2019 US EPA Label, 12 in Track Belts, Manual		Remotes, 540 PTO, 3-Point Hitch, Pickup Hitch, 9.5x24 Front Tires, 14.9x28 Rear Tires Usage: 3,181 Hr Asset located in: Humble, TX
	Coupler, 65 in Bucket Usage: 1,387 Hr Asset located in: Lake Worth, TX		2003 Kubota MX5000E 2WD Utility Tractor S/N: 11584 C/W: 4 Forward 4 Reverse, Manual
797	2019 Bobcat T450 Compact Track Loader S/N: AUVP15801 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 571 Hr Asset located in: Lake Worth, TX		Transmission, 38.0 kW Engine, 2003 US EPA Label, TAS ML280 Loader, 61 in Bucket, 3-Po Hitch, 29x12.50-15 Front Tires, 44x18.00-20 Rear Tires Usage: 481 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
806	1988 John Deere 2955 2WD Tractor S/N: L02955T626188 C/W: Enclosed Cab, 16 Forward 8 Reverse, John Deere Loader, Quick Coupler, 72 in Bucket, 540 PTO, 3-Point Hitch, Drawbar, 10.00- 16 Front Tires, 18.4-38 Rear Tires Usage: 3,219 Hr Asset located in: Lake Worth, TX	811	John Deere 8320R 4WD Tractor S/N: R0H8NBR611453 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 16 Forward 4 Reverse, PowerShift, Front Weights, 5 Rear Remotes, Auxiliary Hydraulics, ISOBUS, 380/80R38 Front Tires, Dual 480 /80R50 Rear Tires, Rear Wheel Weights Usage: 12,160 Hr Asset located in: Lake Worth, TX
807	1979 John Deere 4440 2WD Tractor S/N: 025940R C/W: Enclosed Cab, Air Ride Seat, Differential Lock, 16 Forward 6 Reverse, Quad Range, Front Weights, 2 Rear Remotes, 540 PTO, 3-Point		E OF 2 - Lot #'s: 812, 813
	Hitch, Drawbar, 38x11 Front Tires, 18.4x38 Rear Tires, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 966 Hr Notes: JERRY WATKINS PERSONAL RANCH TRACTOR Asset located in: Lake Worth, TX	812	2024 John Deere 6155M 4WD Tractor (Unused) S/N: 1L06155MTRG423600 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse, PowrQuad Plus, Left Hand Reverser, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Front 3-Point Quick Hitch, 3 Rear Remotes, Air Brake System, Exterior 3-Point Hitch Controls, 540
808	1983 John Deere 4450 2WD Tractor S/N: RW4450P005964 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 15 Forward 4 Reverse, Front Weights, 3 Rear Remotes, 540 PTO,		/1000 PTO, 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420 /70R28 Front Tires, 520/70R38 Rear Tires Usage: 4 Hr Asset located in: Lake Worth, TX
	Drawbar, 14L16.1-10 Front Tires, 20.8x38 Rear Tires Usage: 753 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	813	2024 John Deere 6155M 4WD Tractor (Unused) S/N: 1L06155MLRG423350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse, PowrQuad Plus, Left Hand Reverser, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Front 3-Point Quick Hitch, 3 Rear Remotes, Air Brake System, Exterior 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420 /70R28 Front Tires, 520/70R38 Rear Tires Usage: 1 Hr
CHOIC	E OF 2 - Lot #'s: 809, 810		Asset located in: Lake Worth, TX
809	2017 Case IH Magnum 310 4WD Tractor S/N: JJAM0310THRF01144 C/W: Enclosed Cab, Air Conditioner, Front Weights, Rear Remotes, 540 PTO, Drawbar, 380 /85R34 Front Tires, Dual 480/80r46 Rear Tires Usage: 2,635 Hr Asset located in: Robstown, TX 2017 Case MAGNUM 310 4WD Tractor	814	2013 John Deere 6105D 4WD Tractor S/N: 1P06105DADM050351 C/W: Enclosed Cab, Air Conditioner, 3 Forward 3 Reverse, Hydrostatic Drive, Forward/ Reverse Shuttle, 130 kW Engine, 2013 US EPA Label, CARB Compliant, 4 Rear Remotes, 540 PTO, 3- Point Hitch, Hydraulic Top Link, 340/85R24 Front Tires, 18.4x34 Rear Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 4,107 Hr
	S/N: JJAM0310KHRF01180 C/W: Enclosed Cab, Air Conditioner, CVT,		Asset located in: Humble, TX
	Forward/ Reverse Shuttle, Front Weights, 5 Rear Remotes, 1000 PTO, 3-Point Hitch, Dual 380/85R34 Front Tires, Dual 380/90r50 Rear Tires Usage: 2,810 Hr Notes: TODAY'S PRICE: 14% OFF \$123,419 (\$106,000) Asset located in: Baytown, TX	815	2022 John Deere 5100M 4WD Tractor S/N: 1LV5100MLNM104106 C/W: Canopy, Differential Lock, 16 Forward 16 Reverse, PowrReverser, Forward/ Reverse Shuttle, 2022 US EPA Label, Requires Diesel Exhaust Fluid, John Deere 540M Loader w /Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, 320/85R24 Front Tires, 460/85R30 Rear Tires Usage: 2,124 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble TX

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
816	2012 Kubota M7040D 4WD Tractor S/N: 87373 C/W: Enclosed Cab, Air Conditioner, 8 Forward 8 Reverse, Powershift, Kubota Loader w /Joystick, Quick Coupler, Pallet Forks, 4 Mid- Mount Remotes, 2 Rear Remotes Usage: 561 Hr Notes: **Bucket included in sale** Asset located in: Lake Worth, TX 2013 Mahindra 6110ST 4WD Tractor	823	2016 Manitou MRT2550 High Reach Rotating 4x4x4 Telehandler S/N: 769939 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Load Moment Indicator, 81 ft Max Lift Height, 11000 Ib Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 71 in Forks, Outriggers, Auxiliary Hydraulic Plumbing, 445 /65R22.5 Tires, Parked Idle Hours 265 Usage: 3,059 Hr
0.7	S/N: 61GCF00632 C/W: Enclosed Cab, Air Conditioner, Air Ride		Asset located in: Lake Worth, TX
	Seat, Differential Lock, Powershift, Forward/ Reverse Shuttle, 60 hp Engine, Mahindra ML161 Loader w/Joystick, Quick Coupler, 79 in Bucket, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, Rhino Turbo 96 96 in Mower, 10.5/80-18 Front Tires, 18.4x24 Rear Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 738 Hr	823A	2012 JCB 512-56 Telehandler S/N: 512-56 P01403134 C/W: Enclosed Cab, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 3,236 Hr Asset located in: Lake Worth, TX
	Notes: JERRY WATKINS PERSONAL RANCH TRACTOR; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	824 2 3 0 0 1 1 1 2 3 3	2019 JLG 1255 Telehandler S/N: 0160096252 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 55 ft Max Lift Height, 12000 lb Max
818	2012 Kubota M9960D 4WD Tractor S/N: 53487 C/W: Enclosed Cab, Air Conditioner, 8 Forward 8 Reverse, Powershift, 100 hp Engine, LA1353 Loader w/Joystick, Quick Coupler, 83 in Bucket, 4 Mid-Mount Remotes, 6 Rear Remotes Usage: 2,003 Hr		Lift Capacity, Requires Diesel Exhaust Fluid, 4t in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75 28 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 3,852 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		E OF 2 - Lot #'s: 825, 826
820	1998 Kubota L3600DT 4WD Tractor S/N: 56376 C/W: 4 Forward 4 Reverse, Manual Transmission, Forward/ Reverse Shuttle, Kubota LA680 Loader w/Joystick, 1 Mid-Mount Remotes, HID Lights, 540 PTO, 3-Point Hitch, 8- 16 Front Tires, 14.9x24 Rear Tires Usage: 790 Hr Asset located in: Lake Worth, TX	825	2018 JLG 1255 Telehandler S/N: 0160084208 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 12,673 Hr
822	Kioti LB1914 4WD Tractor		Asset located in: Humble, TX
	S/N: 04000837 C/W: 8 Forward 4 Reverse, Manual Transmission, 3-Point Hitch, 6-12 Front Tires, 12.4-16 Rear Tires Usage: 667 Hr Asset located in: Lake Worth, TX	826	2019 JLG 1255 Telehandler S/N: 0160091605 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 360/85-28 Solid Tires
822A	2010 John Deere 9530 Articulated Tractor S/N: 1RW9530PCAP018006 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Grouser 16 ft Blade, 4 Rear Remotes, Auxiliary Hydraulics, Rear Weights, Dual 800/70R38 Tires Usage: 11,887 Hr Asset located in: Lake Worth, TX		Usage: 9,502 Hr Asset located in: Lake Worth, TX
822B	2019 Shelbourne CVS16 16 ft Stripper Combine Header S/N: CVS16193113 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
СНОІС	CHOICE OF 4 - Lot #'s: 827, 828, 829, 830		2019 Skytrack 12054 Telehandler S/N: 0160092640 C/W: Enclosed Cab, Air Ride Seat, 12000 lb Max Lift Capacity, 48 in Forks, Hydraulic	
827	2015 JLG 1255 Telehandler S/N: 0160070550 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,988 Hr Asset located in: Oklahoma City, OK		Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 3,148 Hr Asset located in : Lake Worth, TX	
		834	2006 Dieci Pegasus 40.25 Telehandler S/N: 1560587 C/W: Enclosed Cab, 69 ft Max Lift Height, 8800 lb Max Lift Capacit, 2006 US EPA Label, Crane	
828	2015 JLG 1255 Telehandler S/N: 0160070536		Attachment, 18-22.5 Tires Usage: 5,470 Hr Asset located in : Lake Worth, TX	
	C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,626 Hr	CHOICI	E OF 1 - Lot #'s: 838 2017 Skyjack SJ1056TH Telehandler S/N: 8730578	
829	Asset located in: Lake Worth, TX 2015 JLG G12-55A Telehandler S/N: 0160065521 C/W: Open Operator Station, Air Ride Seat, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Hydraulic	839	Manual Coupler, Outriggers, Frame Lev	Height, 2017 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 4,532 Hr
	Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,930 Hr Asset located in: Lake Worth, TX		2018 Genie GTH-1056 Telehandler S/N: GTH10E12290 C/W: Open Operator Station, Air Ride Seat, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Maxual Capacita Systems In Statis	
830	2014 JLG G12-55A Telehandler S/N: 0160061321 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US	840	Manual Coupler, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 2,530 Hr Asset located in: Humble, TX	
	EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,775 Hr Asset located in: Lake Worth, TX		2013 JCB 510-56 Telehandler S/N: JCB5CGXGK01403372 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires	
831	2014 JLG G12-55A Telehandler S/N: 0160060643		Usage: 4,527 Hr Asset located in : Lake Worth, TX	
	C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 6,716 Hr Asset located in: Lake Worth, TX	841	2007 Genie GTH-1056 Telehandler S/N: GTH1007A-11371 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Tilt Carriage, Outriggers, 14.00-24 Tires Usage: 8,632 Hr	
832	2011 JLG G12-55A Telehandler S/N: 0160042364 C/W: Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2011 US EPA Label, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: Not Available Asset located in: Humble, TX	842	2017 Gehl RS10-55 Telehandler S/N: RS1055CH90900 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 3,546 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
		849	2015 JLG 10054 Telehandler
CHOIC	HOICE OF 2 - Lot #'s: 843, 844		S/N: 0160065420
			C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US
843	2018 JLG 1055 Telehandler S/N: 0160083964 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary		EPA Label, 72 in Forks, Outriggers, Frame
			Leveling, 14.00-24 Aperture Tires Usage: 8,383 Hr
			Asset located in: Lake Worth, TX
		850	2015 JLG 1055 Telehandler
	Hydraulic Plumbing, 14.00-24 Foam Filled		S/N: 0160070447
	Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires
	Usage: 5,300 Hr		Diesel Exhaust Fluid, 48 in Forks, Outriggers,
	Asset located in: Lake Worth, TX		Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires, EQUIPMENT-FROM-SUNSTATE
844	2017 JLG 1055 Telehandler		EQUIPMENT
	S/N: 160082583		Usage: 5,727 Hr
	C/W: Enclosed Cab, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2017 US EPA	0=1	Asset located in: Lake Worth, TX
	Label, Requires Diesel Exhaust Fluid, 59 in	851	2015 JLG 10054 Telehandler S/N: 0160064214
	Forks, Outriggers, Frame Leveling, 400/75-28 Tires		C/W: Open Operator Station, 42 ft Max Lift
	Usage: 7,542 Hr		Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Manual Coupler,
	Asset located in: Lake Worth, TX	_	Outriggers, Frame Leveling, 400/75-28 Tires
845	2014 JLG G10-55A Telehandler		Usage: 5,103 Hr
	S/N: 0160058853 C/W: Open Operator Station, 55 ft Max Lift		Asset located in: Lake Worth, TX
	Height, 10000 lb Max Lift Capacity, 2014 US	851A	2015 JLG 10054 Telehandler
	EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic		S/N: 0160071104 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 47 in Forks Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires Usage: 5,288 Hr
	Plumbing, 400/75-28 Foam Filled Tires		
	Usage: Not Available Asset located in: Lake Worth, TX		
0.46	2015 Gehl RS10-55 Telehandler	_	
846	S/N: RS1055CG90781		Asset located in: Lake Worth, TX
	C/W: Open Operator Station, 55 ft Max Lift	852	2014 JLG 10054 Telehandler
	Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual	002	S/N: 0160062880
	Coupler, Outriggers, Frame Leveling, Auxiliary		C/W: Open Operator Station, 54 ft Max Lift
	Hydraulic Plumbing, 14.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT		Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, Manual Coupler,
	Usage: 5,609 Hr		Outriggers, Frame Leveling, 17.5-25 Tires Usage: 5,424 Hr
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
847	2018 JLG 10054 Telehandler	852A	2013 JLG 8042 Telehandler
	S/N: 0160086824 C/W: Open Operator Station, 53 ft Max Lift	0027	S/N: 0160052932
	Height, 10000 lb Max Lift Capacity, 48 in Forks,		C/W: Open Operator Station, 42 ft Max Lift
	Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24	ng, Height, FPA La	Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame
	Aperturé Tíres		Leveling, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
	Usage: 3,294 Hr Asset located in: Humble, TX		Usage: 5,413 Hr
	Additionated III. Flamble, TX	\dashv	Asset located in: Lake Worth, TX
СНОІС	E OF 5 - Lot #'s: 848, 849, 850, 851, 852		
848	2016 JLG 10054 Telehandler		
	S/N: 0160076446		
	C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 47 in Forks,		
	Manual Coupler, Outriggers, Frame Leveling,		
	14.00-24 Aperture Tires Usage: 4,051 Hr		
	Asset located in: Lake Worth TX		

Lot #	Details	Lot #	Details
853	2007 SkyTrak 10054 Telehandler S/N: 0160029235 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Tier 3, 2007 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing Usage: 1,666 Hr Notes: COMES WITH IRONCLAD ASSURANCE. SUBJECT TO OKLAHOMA SALES TAX; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.	СНОІС	E OF 1 - Lot #'s: 859
		859	2014 Genie GTH-844 Telehandler S/N: GTH081419083 C/W: Open Operator Station, 44 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 24 Aperture Tires Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lahoma, OK	859A	JCB 509.42 Telehandler
854	2018 Haulotte HTL9055 Telehandler S/N: 2030718 C/W: Enclosed Cab, Air Conditioner, Load Moment Indicator, 55 ft Max Lift Height, 9000 lb Max Lift Capacity, Manual Coupler Usage: 635 Hr Notes: ITEMS AT OFFSITE LOCATION MUST	Joseph	S/N: JCB5CF7GPJ2755050 C/W: Open Operator Station, 42 ft Max Lift Height, 9000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 2,174 Hr Asset located in: Lake Worth, TX
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Apart located in: Fort Smith AR	860	2016 SkyTrak 8042 Telehandler S/N: 0160077066 C/W: Open Operator Station, 42 ft Max Lift Height, 4000 lb Max Lift Capacity, 47.5 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Tires, EQUIPMENT-FROM-
	Asset located in: Fort Smith, AR CHOICE OF 3 - Lot #'s: 855, 856, 857		SUNSTATE-EQUIPMENT Usage: 4,626 Hr
CHOIC			Asset located in: Lake Worth, TX
855	2017 JLG 943 Telehandler S/N: 160079731	СНОІС	E OF 2 - Lot #'s: 861, 862
	C/W: Open Operator Station, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 59 in Forks, Frame Leveling, 370 /75-28 Tires Usage: 5,224 Hr Asset located in: Lake Worth, TX	861	2015 JLG 8042 Telehandler S/N: 0160069747 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary
856	2017 JLG 943 Telehandler S/N: 160079732		Hydraulic Plumbing, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available
	C/W: Open Operator Station, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 2016 US		Asset located in: Lake Worth, TX
	EPA Label, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 7,159 Hr	862	2015 JLG 8042 Telehandler S/N: 0160070986 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary
	Asset located in: Lake Worth, TX		Hydraulic Plumbing, 13.00-24 Solid Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
857	2016 JLG 943 Telehandler S/N: 160078141		Usage: 4,470 Hr
	C/W: Enclosed Cab, 43 ft Max Lift Height, 9000	065	Asset located in: Lake Worth, TX
	lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Foam Filled Tires Usage: 6,476 Hr	865	2013 JLG 8042 Telehandler S/N: 0160054404 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US
			EPA Label, Frame Leveling, 15.5-25 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,889 Hr

Lot #	Details	Lot #	Details
866	Gehl RS8-42 Telehandler S/N: RS842JE0917426 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,721 Hr Asset located in: Lake Worth, TX	874A	2017 JLG Skytrak 6042 Telehandler S/N: 0160079780 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing Usage: 1,949 Hr Asset located in: Lake Worth, TX
867	2017 Gehl RS8-42 Telehandler S/N: RS842CJ18031 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks,	875	E OF 4 - Lot #'s: 875, 876, 877, 878 2014 JLG 6042 Telehandler
	Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,714 Hr Asset located in: Lake Worth, TX		S/N: 0160056200 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 47 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 24 Foam Filled Tires, EQUIPMENT-FROM-
CHOIC	E OF 2 - Lot #'s: 868, 869		SUNSTATE-EQUIPMENT Usage: 3,631 Hr Asset located in: Lake Worth, TX
868	2013 Gehl RS8-42 Telehandler S/N: RS842JE0617386 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,087 Hr Asset located in: Oklahoma City, OK	876	2014 JLG 6042 Telehandler S/N: 0160058949 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 47 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,476 Hr Asset located in: Lake Worth, TX
869	2013 Gehl RS8-42 Telehandler S/N: RS842JF0517510 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,342 Hr Asset located in: Oklahoma City, OK	877	2015 SkyTrak 6042 Telehandler S/N: 0160070308 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,236 Hr Asset located in: Lake Worth, TX
870	2006 Mustang 944L Telehandler S/N: 944LJX0635018 C/W: Open Operator Station, 44 ft Max Lift Height, 9000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 14.00-24 Tires Usage: 2,580 Hr Asset located in: Lake Worth, TX	878	2015 SkyTrak 6042 Telehandler S/N: 0160067892 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 kg Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,160 Hr
873	2006 SkyTrak 8042 Telehandler S/N: 0160024470 C/W: Enclosed Cab, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2006 US EPA Label, 48 in	CHOIC	Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 881, 882, 883
	Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 2,478 Hr Asset located in : Lake Worth, TX	881 —	2013 SkyTrak 6042 Telehandler S/N: 0160055011
874	2012 Genie GTH-644 Telehandler S/N: GTH061215400 C/W: Open Operator Station, 44 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, 13.00-24 Tires Usage: 4,133 Hr Asset located in: Lake Worth, TX		C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,040 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
882	2013 SkyTrak 6042 Telehandler S/N: 0160054643 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,159 Hr Notes: Asset located in: Oklahoma City, OK 2013 SkyTrak 6042 Telehandler		S/N: RS634JF0822387 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires,
	S/N: 0160047623 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 60 in Forks,		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,160 Hr Asset located in: Lake Worth, TX
	Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,052 Hr Notes: . Asset located in: Oklahoma City, OK	889	2014 Gehl RS6-34 Telehandler S/N: RS634JF0522222 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIDMENT
884	2013 JLG G6-42A Telehandler S/N: 0160051054 C/W: Open Operator Station, 42 ft Max Lift		Usage: 3,001 Hr Asset located in : Lake Worth, TX
СНОІС	Height, 6600 lb Max Lift Capacity, 2012 US EPA Label, 47 in Forks, Frame Leveling, 370/75- 28 Tires Usage: 4,609 Hr Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 885, 886	890	2014 Gehl RS6-34 Telehandler S/N: RS634DF1022527 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,227 Hr Asset located in: Lake Worth, TX
885	2014 Gehl RS6-42 Telehandler S/N: RS642JF0814891 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2014 US EPA Label, Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,499 Hr	891	2014 Gehl RS6-34 Telehandler S/N: RS634DF1022506 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 15-9.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,025 Hr Asset located in: Lake Worth, TX
886	Asset located in: Lake Worth, TX 2014 Gehl RS6-42 Telehandler S/N: RS642JF0814899 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 47 in Forks, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,177 Hr Asset located in: Lake Worth, TX	892	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921970 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,144 Hr Asset located in: Oklahoma City, OK
887	2018 JLG 6036 Telehandler S/N: 0160083772 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 315/95-28 Solid Tires Usage: 1,190 Hr Asset located in: Humble, TX	893	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921972 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,418 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
894	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921979 C/W: Open Operator Station, 35 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,678 Hr Asset located in: Oklahoma City, OK	901	Gehl RS6-34 Telehandler S/N: RS634DF0922487 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 47.5 in Forks, Manual Coupler, 15-19.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,389 Hr Asset located in: Lake Worth, TX
895	2012 Gehl RS6-34 Telehandler S/N: RS634JD0121707 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2011 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,712 Hr Asset located in: Oklahoma City, OK	904	E OF 3 - Lot #'s: 904, 905, 906 2013 Gehl RS5-19 Telehandler S/N: RS519YF0851124 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-
896	2012 Gehl RS6-34 Telehandler S/N: RS634JD0321723 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 72 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,973 Hr Asset located in: Lake Worth, TX	905	EQUIPMENT Usage: 4,272 Hr Asset located in: Lake Worth, TX 2013 Gehl RS5-19 Telehandler S/N: RS519YF0251049 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 48 in Forks, Manual Coupler, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
897	Gehl RS6-34 Telehandler S/N: RS634DG22553 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, Foam Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 4,136 Hr Asset located in: Lake Worth, TX	906	Usage: 2,838 Hr Asset located in: Lake Worth, TX Gehl RS5-19 Telehandler S/N: RS519YE1050991 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, US EPA Label, 46 in Forks, Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
898	Gehl RS6-34 Telehandler S/N: RS634JE1122021 C/W: Open Operator Station, Air Ride Seat, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 60 in Forks, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,296 Hr Asset located in: Lake Worth, TX	907 908	Usage: Not Available Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 907, 908 2020 Manitou MT625 Telehandler S/N: MAN00000J01033352
899	Gehl RS6-34 Telehandler S/N: RS634DF1022514 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,338 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 5500 lb Max Lift Capacity, Hydraulic Coupler, Auxiliary Hydraulic Plumbing, 12x16.5 Tires Usage: 2,764 Hr Asset located in: Lake Worth, TX 2019 Manitou MT625 Telehandler S/N: MAN00000J01021296
900	Gehl RS6-34 Telehandler S/N: RS634JF0722333 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,642 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, 19 ft 1 in Max Lift Height, 5500 lb Max Lift Capacity, Tier 4, 2019 US EPA Label, Hydraulic Coupler, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 2,832 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
909	2007 Genie GTH-5519 Telehandler S/N: 17897 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2007 US EPA Label, 48 in Forks, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 1,676 Hr Asset located in: Lake Worth, TX	914	2024 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HT8RED27006 C/W: Ford V8 6.7 L Diesel Engine, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 11 Engine hrs, Engine Brake, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192
910	2015 Genie GTH-5519 Telehandler S/N: GTH5515B2885 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Frame Leveling, 12-16.5 Tires Usage: 1,522 Hr		in Wheelbase, PTO, Caseco MM238 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Wireless Remote Control, American Eagle SHD-60 Hydraulic Air Compressor, Air Hose Reel Usage: 241 Mi Asset located in: Lake Worth, TX
910A	Asset located in: Lake Worth, TX 2020 JLG 3013 Telehandler S/N: H160000215 C/W: Open Operator Station, Air Ride Seat, 13 ft Max Lift Height, 2360 lb Max Lift Capacity, Tier 4, 2020 US EPA Label, 46 in Forks, Hydraulic Coupler, 11.0/65-12 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 667 Hr Asset located in: Lake Worth, TX	915	2023 Ford F-550 4x4 Extended Cab Service Truck S/N: 1FD0X5HTXPED24749 C/W: 6.7 L Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 2017 Altec 10 ft 3 in Body, Hydraulic Stabilizers, Auto Crane HC-5 5000 lb 2 Section Electric Crane, Wired Remote Control, Boss BA435 Hydraulic Air
911	Cat R80 8000 lb 4x2 Rough Terrain Forklift S/N: 49A01169 C/W: 3 Stage Mast, 192 in Max Lift Height, 117 in Lowered Mast Height, 48 in Forks, 4 Cylinder		Compressor, Air Hose Reel, Miller Bluestar 185 Welder Usage: 95 Mi Asset located in: Lake Worth, TX
	Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		2023 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HT3PEC87656
911B	2014 JCB 950-4 T4 4700 kg 4x4 Rough Terrain Forklift S/N: JCB95004H02364093 C/W: 3 Stage Mast, 127 in Lowered Mast Height, 47 in Forks, Side Shift, 2010 US EPA Label, JCB Power Sources 4 Cylinder 56 kW Diesel Engine Usage: 5,199 Hr Asset located in: Lake Worth, TX		C/W: V8 6.7 L Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 30 Engine hrs, Engine Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 11 ft Body, Hydraulic Stabilizers, Auto Crane HC-5 5000 lb 3 Section Hydraulic Crane, Tomahawk TWG120A Gasoline Generator Set, Boss BA435 Hydraulic Air Compressor, Air Hose Reel Usage: 308 Mi
912	Sellick S80J4I-2 8000 lb 4x4 Rough Terrain		Asset located in: Lake Worth, TX
	Forklift S/N: 10015609S8J4I C/W: 3 Stage Mast, 264 in Max Lift Height, 126 in Lowered Mast Height, 69 in Forks, JCB Diesel Engine Usage: 3,868 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR	916A	Truck S/N: 1FD0X5HT7PED26877 C/W: Ford 6 Cylinder 6.7 L Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, PTO, Palfinger Pro 43 11 ft Body, Hydraulic Stabilizers, 2012 Palfinger PSC4329 8000 lb 2 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC35 Hydraulic Air Compressor, Air Hose Reel Usage: 143 Mi

This catalog was created at December 11, 2024 01:25:48 AM GMT. Please check our website for the most accurate and up-to-date information.

Lot #	Details	Lot #	Details
СНОІС	E OF 1 - Lot #'s: 917	СНОІС	E OF 1 - Lot #'s: 923
917	2019 Ford F-550 4x4 Service Truck S/N: 1FDUF5HT3KEC14526 C/W: Power Stroke V8 6.7 L 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245 /70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 2018 Stellar TMAX1-11AL 11 ft 1 in Body, Hydraulic Stabilizers, Stellar 7621 3 Section Hydraulic Crane, Wireless Remote Control, American Eagle 30P Piston Series Hydraulic Air Compressor, Miller Bobcat 250 250 A Gasoline Welder Usage: 190,847 Mi Asset located in: Midland, TX	923	2012 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HY9CEB86563 C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 162 in Wheelbase, PTO, Knaphiede 9 ft 2 in Body, Hydraulic Stabilizers, Auto Crane 5005H 5000 lb 3 Section Hydraulic Crane, Wired Remote Control, Speedair 4LW38 Gasoline Air Compressor, Air Hose Reel Usage: 193,733 Mi Asset located in: Midland, TX
919	2018 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HY3JDA01060 C/W: Ford V10 6.8 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft Body, Vanair Air N Arc All-In- One Power System, Product Tanks, Hose Reels Usage: 182,415 Mi Notes: EQUIPMENT FROM UNITED RENTALS	923A	2008 Ford F-550 4x2 Utility Truck S/N: 1FDAF56R08EE06327 C/W: V8 6.4 L Diesel Engine, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, United Truck Bodies 108UTB 12 ft 4 in Body, Northstar Gasoline Air Compressor, Air Hose Reel Usage: 211,927 Mi Asset located in: Lake Worth, TX
920	Asset located in: Lake Worth, TX 2017 Ford F-550 XL 4x2 Service Truck S/N: 1FDUF5GT5HDA09578 C/W: Ford Powerstroke V8 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 Ib Front Axle, 114706 Ib Rears, 19500 Ib GVWR, Steel, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, Auto Crane Titan 38K 11 ft Body, Hydraulic Stabilizers, Auto Crane HC6 6000 Ib 3 Section Hydraulic Crane, Wired Remote Control, Gasoline Air Compressor,	S/N: 3C7WRMBL0FG594935 C/W: Cummins V8 6.7 L Diesel En Requires Diesel Exhaust Fluid, Au Transmission, 7000 lb Front Axle, Rears, 19500 lb GVWR, 225/70R1 Suspension, 168 in Wheelbase, lo Tooling DSS K187525 11 ft Body, 150 Welder, EQUIPMENT-FROM-S EQUIPMENT Usage: 205,310 Mi Asset located in: Lake Worth, TX 924 2012 Dodge Ram 5500 4x2 Servic S/N: 3C7WDMBL1CG197440 C/W: Cummins 6 Cylinder 6.7 L Di Requires Diesel Exhaust Fluid, Au Transmission, 7000 lb Front Axle, Rears, 19500 lb GVWR, 245/70R1 Suspension, 168 in Wheelbase, P Body, Hydraulic Stabilizers, Stellar	C/W: Cummins V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, Iowa Mold Tooling DSS K187525 11 ft Body, Air And Arc 150 Welder, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 205,310 Mi Asset located in: Lake Worth, TX
	Lincoln Bobcat 225 Gasoline Welder Usage: 69,562 Mi Notes: PTO HAS BEEN REPAIRED Asset located in: Lake Worth, TX		2012 Dodge Ram 5500 4x2 Service Truck S/N: 3C7WDMBL1CG197440 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb
920B	2016 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT4GEA46341 C/W: Ford 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, IMT 11 ft Body, 55 gal Oil Tanks, (5) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, Vanair Air N Arc 150 Gasoline Air Compressor, Air Hose Reel, Vanair Air N Arc 150 Welder, Rear View Camera; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 230,316 Mi Asset located in: Lake Worth, TX		Usage: 296,712 Mi

Details	Lot #	Details
CHOICE OF 1 - Lot #'s: 925		2012 Ford F-550 XL 4x2 Crew Cab Utility Truck S/N: 1FD0W5GT8CEC42968 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US
2023 Chevrolet 4500 4x2 Service Truck S/N: 1HTKHPVH4PH293943 C/W: International 350 V8 6.6 L Diesel 350 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 10 Engine hrs, Allison Automatic Transmission, 7000 lb Front Axle, 11000 lb		EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 202 in Wheelbase, Knapheide 6132D54 11 ft Body Usage: 319,591 Mi Asset located in: Lake Worth, TX
Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 141 in Wheelbase, PTO, Knapheide 9 ft Body, Manual Stabilizers, Liftmoore 4000X 4000 lb 3 Section Electric Crane, Wired Remote Control, Land Honor LHR- GAC40T Gasoline Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 54 Mi	933	2012 Ford F-550 4x2 Utility Truck S/N: 1FDUF5GT7CEB42748 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 163 in Wheelbase, 10 ft 11 in Body, Manual Stabilizers, Liftmoore 3200 lb
2023 Ram 4500HD 4x2 Service Truck S/N: 3C7WRKBL5PG620080 C/W: Cummins B6.7 360 6 Cylinder 6.7 L Diesel 360 hp Engine, 2023 US EPA Label,		Hydraulic Crane, Wired Remote Control, Miller Wildcat 200 6500 W Gasoline Generator Set, Gasoline Air Compressor Usage: 296,236 Mi Asset located in : Lake Worth, TX
Requires Diesel Exhaust Fluid, 16 Engine hrs, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, Hydraulic Stabilizers, Palfinger PSC 6025 6000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 302 Mi	935	2017 Ram 3500 4x2 Crew Cab Utility Truck S/N: 3C7WRSCL3HG632261 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 170 in Wheelbase, Knapheide 9 ft Body, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available
Notes: 3 YEAR 36,000 MILE - FACTORY BUMPER TO BUMPER WARRANTY; 5 YEAR 60,000 MILE - FACTORY POWERTRAIN WARRANTY Asset located in: Lake Worth, TX	936	Asset located in: Lake Worth, TX 2017 Ram 3500 4x2 Crew Cab Utility Truck S/N: 3C7WRSCL5HG632262 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine,
2013 Ford F-450 4x4 Crew Cab Service Truck S/N: 1FD0W4HY5DEB45653 C/W: Ford V8 6.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500.0 lb GVWR, 225/70R19.5, Spring Suspension, 202 in Wheelbase, PTO, 2007 11 ft Body, Manual Stabilizers, Stahl 3200 LRX 3200 lb 3 Section Electric Crane, Wired Remote Control Usage: 215,755 Mi Asset located in: Lake Worth, TX		2017 US EPA Label, Requires Diesel Exhaust Fluid, 4102 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235 /80R17, Spring Suspension, 172 in Wheelbase, Knapheide 6108D54J1 9 ft Body, Vanair Viper Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 104,083 Mi Asset located in: Lake Worth, TX
2017 Ford F-250 XL 4x2 Utility Truck S/N: 1FDBF2A62HED60788 C/W: Gasoline Engine, Automatic Transmission, 3800 lb Front Axle, 6340 lb Rears, 9900 lb GVWR, Steel, 245/75R17, Spring Suspension, 142 in Wheelbase, Knapheide 8 ft Body Usage: 190,429 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		
	2023 Chevrolet 4500 4x2 Service Truck S/N: 1HTKHPVH4PH293943 C/W: International 350 V8 6.6 L Diesel 350 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 10 Engine hrs, Allison Automatic Transmission, 7000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 141 in Wheelbase, PTO, Knapheide 9 ft Body, Manual Stabilizers, Liftmoore 4000X 4000 lb 3 Section Electric Crane, Wired Remote Control, Land Honor LHR- GAC40T Gasoline Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 54 Mi Asset located in: Lake Worth, TX 2023 Ram 4500HD 4x2 Service Truck S/N: 3C7WRKBL5PG620080 C/W: Cummins B6.7 360 6 Cylinder 6.7 L Diesel 360 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 16 Engine hrs, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GWWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, Hydraulic Stabilizers, Palfinger PSC 6025 6000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 302 Mi Notes: 3 YEAR 36,000 MILE - FACTORY BUMPER TO BUMPER WARRANTY; 5 YEAR 60,000 MILE - FACTORY POWERTRAIN WARRANTY Asset located in: Lake Worth, TX 2013 Ford F-450 4x4 Crew Cab Service Truck S/N: 1FD0W4HY5DEB45653 C/W: Ford V8 6.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500.0 lb GWR, 225/70R19.5, Spring Suspension, 202 in Wheelbase, PTO, 2007 11 ft Body, Manual Stabilizers, Stahl 3200 LRX 3200 lb 3 Section Electric Crane, Wired Remote Control Usage: 215,755 Mi Asset located in: Lake Worth, TX	2023 Chevrolet 4500 4x2 Service Truck S/N: 1HTKHPVH4PH293943 C/W: International 350 V8 6.6 L Diesel 350 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 10 Engine hrs, Allison Automatic Transmission, 7000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 141 in Wheelbase, PTO, Knapheide 9 ft Body, Manual Stabilizers, Liftmoore 4000X 4000 lb 3 Section Electric Crane, Wired Remote Control, Land Honor LHR- GAC40T Gasoline Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 54 Mi Asset located in: Lake Worth, TX 2023 Ram 4500HD 4x2 Service Truck S/N: 3C7WRKBL5PG620080 C/W: Cummins B6.7 360 6 Cylinder 6.7 L Diesel 360 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 16 Engine hrs, Exhaust Brake, Automatic Transmission, 7000 Ib Front Axle, 12000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, Hydraulic Stabilizers, Palfinger PSC 6025 6000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Stabilizers, Palfinger PSC 6025 6000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 302 Mi Notes: 3 YEAR 36,000 MILE - FACTORY BUMPER TO BUMPER WARRANTY; 5 YEAR 60,000 MILE - FACTORY POWERTRAIN WARRANTY Asset located in: Lake Worth, TX 2013 Ford F-450 4x4 Crew Cab Service Truck S/N: 1FD0W4HY5DEB45653 C/W: Ford V8 6.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500.0 lb GVWR, 225/70R19.5, Spring Suspension, 202 in Wheelbase, PTO, 2007 11 ft Body, Manual Stabilizers, Stahl 3200 LRX 3200 lb S Section Electric Crane, Wired Remote Control Usage: 215,755 Mi Asset located in: Lake Worth, TX 2017 Ford F-250 XL 4x2 Utility Truck S/N: 1FDBF2A62HED60788 C/W: Gasoline Engine, Automatic Transmission, 3800 lb Front Axle, 6340 lb Rears, 9900 lb GWW, Steel, 245/75R17, Spring Suspension, 142 in Wheelbase, Knapheide 8 ft Body Usage: 190,429

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 938, 939	942	2014 Ford F-250 XL 4x4 Extended Cab Utility Truck S/N: 1FT7X2B68EEB70690
938	Cab Utility Truck S/N: 1GB2WLE77MF235677 C/W: V8 6.6 L Gasoline Engine, 2021 US EPA Label, 2137 Engine hrs, Automatic Transmission, 4400 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 162 in Wheelbase, 2021 Harbor 8 ft 2 in Body		C/W: Ford V8 6.2 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 225 /70R19.5, Spring Suspension, 142 in Wheelbase, 6 ft 10 in Body Usage: 421,371 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
		942A	2015 GMC Sierra 3500HD 4x2 Utility Truck S/N: 1GD311CG4FZ538631 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4400 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235 /80R17, Spring Suspension, 10 ft Body
939	2021 Chevrolet Silverado 2500 HD 4x2 Utility Truck		Usage: 97,811 Mi Asset located in: Lake Worth, TX
939A	S/N: 1GB0WLE72MF189165 C/W: V8 6.6 L Gasoline Engine, 2021 US EPA Label, 2015 Engine hrs, Automatic Transmission, 4400 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 140 in Wheelbase, Scelzi 8 ft 2 in Body Usage: 109,730 Km Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX 2016 GMC 2500HD 4x4 Crew Cab Utility Truck	943	2014 Chevrolet 2500HD 4x2 Crew Cab Utility Truck S/N: 1GC1CVCG7EF160110 C/W: V8 6.0 L Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9500 lb GVWR, 265/70R17, Spring Suspension, 167 in Wheelbase, Omaha 8 ft Body, Air Hose Reel Usage: 161,768 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
939A	S/N: 1GT12REG1GF303868 C/W: GM V8 6.0 L Gasoline Engine, 2016 US EPA Label, 8880 Engine hrs, Automatic Transmission, 4800 lb Front Axle, 6200 lb Rears, 9900 lb GVWR, 265/70R17, Spring Suspension, Reading 9 ft Body Usage: 214,244 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	944	Asset located in: Lake Worth, TX 2012 Ford F-250 XL 4x2 Extended Cab Utility Truck S/N: 1FD7X2A6XCEC57999 C/W: Ford 6.2 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 4250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 245 /75R17, Spring Suspension, 158 in Wheelbase, Knapheide 696J 8 ft Body Usage: 215,738 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
941	2015 Chevrolet Silverado 2500 HD 4x2 Utility Truck		TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	S/N: 1GC0CUEG1FZ528560 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9300 lb GVWR, 245/75R17, Spring Suspension, 130 in Wheelbase Usage: 230,081 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPANCY-UNIT SHOWS 230,081, TITLE SHOWS 232,270 Asset located in: Humble, TX	946	2009 Ford F-250 XL 4x2 Utility Truck S/N: 1FDNF20569EA84459 C/W: Ford 5.4 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, 3950 lb Front Axle, 5892 lb Rears, 8800 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, 2009 Omaha 8 ft Body Usage: 152,394 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

			Page 76 of 574
Lot #	Details	Lot #	Details
947	2008 Ford F-250 XL 4x4 Utility Truck S/N: 1FTNF21548EE41543 C/W: V8 5.4 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 9000 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, Knapheide 8 ft Body Usage: 195,357 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	952 2015 Peterbilt 348 6x4 W S/N: 2NP3LJ0XXFM2804 C/W: Paccar PX-9 6 Cylin Requires Diesel Exhaust I Engine Brake, Allison Aut Differential Lock, 20000 I Rears, Dana DSH44 Drive Ratio, 64000 Ib GVWR, Ali /80R22.5 Front Tires, 11F Double Frame, Air Trac 4- Suspension, 209 in Whee curry supply Steel Tank, F 5 in, Spray Bar, Hose Ree Controlled Water Cannon Spray Usage: 118,261 Mi Asset located in: Lake Wo 953 2018 Kenworth T370 6x4 S/N: 2NKHLJ9X7JM1892 C/W: Paccar 6 Cylinder D Label, 4518.8 Engine hrs, Manual Transmission, 14 20000 Ib Rears, 54600 Ib Tires, 11R22.5 Rear Tires PTO Driven Pump, Front S Side Spray, EQUIPMENT- EQUIPMENT Usage: 30,539 Mi Asset located in: Lake Wo 954 2014 International 5900I Truck S/N: 3HSXYSNR9EN7958 C/W: International MaxxF 12.4 L Diesel 476 hp Engi Label, Requires Diesel Ex Engine hrs, Engine Brake, Speed Manual Transmiss 14320 Ib Front Axle, 4000 GVWR, Air Ride Cab, Alun 285/75R24.5, Dual Steeri Suspension, 214 in Whee Reinforced Plastic Tank Usage: 382,841 Mi	2015 Peterbilt 348 6x4 Water Truck S/N: 2NP3LJ0XXFM280411 C/W: Paccar PX-9 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9583 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 44000 lb Rears, Dana DSH44 Drive Axles, 4.88:1 Axle Ratio, 64000 lb GVWR, Aluminum Wheels, 315 /80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Air Trac 4-Bag Air Ride Suspension, 209 in Wheelbase, PTO, 2008
948	2006 Chevrolet 2500 4x2 Utility Truck S/N: 1GBHC24U76E153672 C/W: V8 6.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, 245/75R16, Spring Suspension, 8 ft 2 in Body		5 in, Spray Bar, Hose Reel, In-Cab Remote Controlled Water Cannon, Front Spray, Rear Spray
	Usage: 33,621 Mi Asset located in : Lake Worth, TX		2018 Kenworth T370 6x4 Water Truck S/N: 2NKHLJ9X7JM189233
СНОІС 950	2020 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 1NP3LJ0X8LD732020 C/W: Paccar L9 6 Cylinder 8.9 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8871 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission,		
	Differential Lock, 18740 lb Front Axle, 40000 lb Rears, 58740 lb GVWR, Steel, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Suspension, 210 in Wheelbase, PTO, Niece WT-4K 4000 gal Tank, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 100,644 Mi Asset located in: Lake Worth, TX		S/N: 3HSXYSNR9EN795890 C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 476 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 14777 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb
951	2019 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 2NP3LJ0XXKM624300 C/W: Paccar PX-9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 18180 lb Front Axle, 40000 lb		GVWR, Air Ride Cab, Aluminum Outer Wheels, 285/75R24.5, Dual Steering Boxes, Air Ride Suspension, 214 in Wheelbase, Fiberglass Reinforced Plastic Tank

Transmission, 18180 lb Front Axle, 40000 lb Rears, 4.11:1 Axle Ratio, 58180 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 210 in Wheelbase, PTO, 2018 Niece Tank, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 92,315 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 955, 956

955 2014 Freightliner M2 106 4000 gal 6x4 Water Truck

S/N: 1FVHCYCYOEHFN9171 C/W: Cummins ISL 6 Cylinder Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, 7676 Engine hrs, Eaton Fuller FRO-11210C 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.11:1 Axle Ratio, 58000 lb GVWR, 315/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 196 in Wheelbase, PTO, Ledwell LW4000 WT 4000 gal Steel Tank, PTO Driven Pump, 0 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 49,100 Mi

Lot #	Details	Lot #	Details
956	2012 Freightliner M2 106 4000 gal 6x4 Water Truck S/N: 1FVHCYBS3CHBS9418 C/W: Cummins ISB 6 Cylinder 8.3 L Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 4544.0 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 315 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Double Frame, Airliner Air Ride Suspension, 200 in Wheelbase, PTO, 2012 Ledwell 4000 gal Steel Tank, BERKELEY PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 35,988 Mi Asset located in: Midland, TX	960 CHOICI	1995 International 8200 6x4 Water Truck S/N: 1HSHGAER3SH682251 C/W: Cummins 6 Cylinder Diesel Engine, 31586 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Steel, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 164 in Wheelbase, 1 Compartments, PTO Driven Pump, Rear Spray Usage: 658,690 Mi Asset located in: Lake Worth, TX
956A	2008 Peterbilt 340 6x4 Water Truck S/N: 2NPRLN9X48M764601 C/W: Paccar PX-8 6 Cylinder Diesel Engine, 13743 Engine hrs, Exhaust Brake, Allison 3000 Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, Spicer DSP41P Drive Axles, 5.57:1 Axle Ratio, 54600 lb GVWR, Aluminum Front Wheels, 11R22.5, Hendrickson Spring over Walking Beam Suspension, 196 in Wheelbase, PTO, Steel Tank, ARMS PTO Driven Pump, 5 ft, Spray Bar, Hose Reel, Rear Spray, Side Spray Usage: 53,003 Mi Asset located in: Lake Worth, TX	961	2021 International MV607 2000 gal 4x2 Water Truck S/N: 3HAEUMMN0ML087250 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6485 Engine hrs, Automatic Transmission, 12350 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 151 in Wheelbase, PTO, Unused Lands Powder Coated 2000 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 44,002 Mi Asset located in: Lake Worth, TX
957	2003 International 5600i 4500 gal 6x4 Water Truck S/N: 1HTXHAHT13J068496 C/W: Cummins ISM 320V 6 Cylinder Diesel 305 hp Engine, 19509 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 212 in Wheelbase, 2013 United Truck & Equipment 4500 gal Steel Tank, Franklin Electric Hydraulic Driven Pump, 6 ft 8 in, Spray Bar, In-Cab Remote Controlled Water Cannon, Rear Spray, Side Spray Usage: 159,456 Mi	962	2019 International 4300 2500 gal 4x2 Water Truck S/N: 1HTMMMML3KH515096 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4450 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 164 in Wheelbase, PTO, Unused Lands Powder Coated 2500 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 191,161 Mi Asset located in: Lake Worth, TX
959	Asset located in: Lake Worth, TX 1998 Oshkosh FF-115 6x6 Water Truck S/N: 10TDCKY32WS064147 C/W: Cummins L10 6 Cylinder 10 L Diesel 260 hp Engine, 1997 US EPA Label, 4536 Engine hrs, Eaton Fuller 9-Speed Manual Transmission, Differential Lock, 23000 lb Front Axle, 45000 lb Rears, 69000 lb GVWR, Air Ride Cab, Steel, 445/65R22.5 Front Tires, 12R22.5 Rear Tires, Hendrickson Rubber over Walking Beam Suspension, 212 in Wheelbase, Housby Tank, Rear Spray, Side Spray Usage: 105,114 Mi Asset located in: Lake Worth, TX	963	2019 International MA025 2500 gal 4x2 Water Truck S/N: 1HTMMMML4KH515138 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4769 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 168 in Wheelbase, PTO, Unused Lands Powder Coated 2500 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 197,374 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
964	2018 International MA025 2000 gal 4x2 Water Truck S/N: 1HTMMMML0JH351983	СНОІС	E OF 2 - Lot #'s: 969, 970
	C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 6760 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 157 in Wheelbase, PTO, Unused Lands Powder Coated 2000 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 223,707 Mi Asset located in: Lake Worth, TX	969	2013 Ford F-750 4x2 Water Truck S/N: 3FRXF7FA1DV026323 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 14,173 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 965, 966	970	2013 Ford F-750 4x2 Water Truck
965	2014 International 4300 4x2 Water Truck S/N: 1HTMMAAM8EH467675 C/W: International 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 177,213 Mi Asset located in: Humble, TX	970	S/N: 3FRXF7FA8DV026450 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 3997 Engine hrs, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 12,250 Mi Asset located in: Lake Worth, TX
966	<u> </u>	971	2007 Ford F-750 XL 4x2 Water Truck
	2013 International 4300 2000 gal 4x2 Water Truck S/N: 1HTMMAAL4DH202404 C/W: 6 Cylinder Diesel Engine, 7386 Engine hrs, Automatic Transmission, Steel, 11R22.5, Air Ride Suspension, 156 in Wheelbase, PTO, 2000 gal Tank, 1 Compartments, 7 ft 6 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 238,027 Mi Asset located in: Lake Worth, TX		S/N: 3FRWF75RX7V441258 C/W: Cat C7 6 Cylinder 7.2 L Diesel 230 hp Engine, 2006 US EPA Label, 5138.2 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, Aluminum Front Wheels, 11R22.5, Spring Suspension, 178 in Wheelbase, PTO, Tiger Steel Tank, Hydraulic Driven Pump, 7 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 176,955 Mi Asset located in: Lake Worth, TX
968	2005 International 4200 2000 gal 4x2 Water Truck	972	
	S/N: 1HTMPAFP95H166536 C/W: International VT365 6 Cylinder Diesel 215 hp Engine, 2004 US EPA Label, 5463 Engine hrs, 5-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5 Front Tires, 22.5 MIX Rear Tires, Spring Suspension, 152 in Wheelbase, PTO, Ledwell LW2000WT 2000 gal Steel Tank, Berkeley PTO Driven Pump, 6 ft 2 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray	7/4	2007 Ford F-750 4x2 Water Truck S/N: 3FRXF75N07V509486 C/W: Caterpillar C7 7.2 L Diesel Engine, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 162 in Wheelbase, PTO, Steel Tank, Berkeley PTO Driven Pump, 5 ft 5 in, Spray Bar, Rear Spray, Side Spray Usage: 19,377 Mi Asset located in: Lake Worth, TX
	Usage: 15,846 Mi Asset located in: Humble, TX	973	2003 Ford F-650 XL 4x2 Water Truck S/N: 3FDNF65AX3MB00757 C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 hp Engine, 2002 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, Steel Tank, Berkeley PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 21,069 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
974	2008 Ford F-650 2000 gal 4x2 Water Truck S/N: 3FRNF65A88V660849 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2007 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 11R22. 5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 17,325 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 17,325, TITLE SHOWS 40,000 Asset located in: Lake Worth, TX	979	1996 International 4700 4x2 Water Truck S/N: 1HTSCABN1TH276159 C/W: 6 Cylinder Diesel Engine, 9393 Engine hrs, Automatic Transmission, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 182 in Wheelbase, Steel Tank, Pump w/ Engine, 8 ft, Spray Bar, Dribble Bar Usage: 233,739 Mi Asset located in: Lake Worth, TX
		980	1990 Ford L8000F 2000 gal 4x2 Water Truck S/N: 1FTXR82A2LVA15969 C/W: Ford 6 Cylinder 7.8 L Diesel 210 hp
975	2005 Ford F-650 XL 2000 gal 4x2 Water Truck S/N: 3FRNF65905V181715 C/W: Cat C7 6 Cylinder 7.2 L Diesel 350 hp Engine, 2005 US EPA Label, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 10R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension,		Engine, Manual Transmission, 9000 lb Front Axle, 21000 lb Rears, 30000 lb GVWR, Steel, 11R22.5, Spring Suspension, 150 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 6 ft 6 in, Spray Bar, Water Cannon, Front Spray, Rear Spray Usage: 457,293 Mi Asset located in: Lake Worth, TX
	158 in Wheelbase, PTO, Niece 2000 gal Steel Tank, PTO Driven Pump, 7 ft, Spray Bar, Front Spray, Rear Spray Usage: 45,392 Mi Asset located in : Lake Worth, TX	981	2014 Freightliner M2 106 4x2 Propane Tanker Truck S/N: 3ALACXDT3EDFV6933 C/W: Cummins ISB 6.7 L Diesel 280 hp Engine
976	2001 International 4700 4x2 Water Truck S/N: 1HTSCAAM31H382229 C/W: International 6 Cylinder Diesel Engine, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, Steel, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, Hose Reel, Rear Spray Usage: 138,204 Mi		2013 US EPA Label, Requires Diesel Exhaust Fluid, Allison 3500 6-Speed Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 6.14:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 207 in Wheelbase, Westmor 3200 gal Steel Tank, 2 Reels Usage: 302,437 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2019 Hino 338 2600 gal 4x2 Fuel Truck
977	2000 Sterling A9513 4x2 Water Truck S/N: 2FWWJWDBXYAB94058 C/W: Cat C12 6 Cylinder 12 L Diesel Engine, 5610 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 12000 lb Front Axle, 22000 lb Rears, 34000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft, Spray Bar, Front Spray, Rear Spray, Side Spray		S/N: 5PVNV8JV1K4S58832 C/W: Hino J08E-VB 6 Cylinder 469 cid 260 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12537 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 197 in Wheelbase, PTO, 2600 gal Aluminum Tank, 3 Compartments, 2 Reels Usage: 274,979 Mi
	Usage: 23,621 Mi Asset located in: Lake Worth, TX		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
978	1998 International 4700 4x2 Water Truck S/N: 1HTSCABN9WH510827		PRIOR TO BIDDING Asset located in: Lake Worth, TX
	C/W: International T444E V8 7.3 L Diesel Engine, US EPA Label, 1166 Engine hrs, Spicer 6-Speed Manual Transmission, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft 8 in, Spray Bar, Front Spray, Rear Spray Usage: 15,286 Hr Asset located in: Lake Worth, TX	983	2014 Ram 5500 4x2 Lube Truck S/N: 3C7WRMBL1EG241604 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, 11 ft Body, (3) Oil Tanks, (4) Hose Reels, Metered Nozzles, Air Hose Reel, Vanair Air N Arc 150 All-In-One Power System; EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 202,597 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
984	2016 Freightliner M2 106 1000 gal 4x2 Fuel and Lube Truck S/N: 3ALACXDT1GDGY4896	сноіс	E OF 2 - Lot #'s: 988, 989
	C/W: Cummins ISB 6 Cylinder 6.7 L 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 14852 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.00:1 Axle Ratio, 33000.0 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 2008 1000 gal Steel Tank, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 269,399 Mi Notes: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Asset located in: Lake Worth, TX	988	2014 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT4EEB70543 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft Body, (4) Hose Reels, Metered Nozzles, Vanair Gasoline Air Compressor, Air Hose Reel, Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 163,834 Mi Asset located in: Lake Worth, TX
	·	989	2013 Ford F-550 4x2 Fuel and Lube Truck
986	36 2015 Ford F-550 4x4 Fuel and Lube Truck S/N: 1FDUF5HT8FEB16131 C/W: V8 6.7 L Diesel 309 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 162 in Wheelbase, 10 ft 10 in Body, (2) Oil Tanks, (5) Hose Reels, Metered Nozzles, Oil Recovery System, AirnArc 150 Gasoline Generator Set, Ingersoll-Rand Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 172,086 Mi Asset located in: Lake Worth, TX		S/N: 1FDUF5GT9DEA86667 C/W: 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 14 ft 4 in Body, (1) Diesel Tank, Metered Nozzles, Ingersoll-Rand Air Compressor, Air Hose Reel, Miller Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 120,748 Mi Asset located in: Lake Worth, TX
		989A	2013 Ford F-550 XL 4x2 Fuel and Lube Truck S/N: 1FDUF5GT8DEB37379 C/W: Ford V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, IMT 11
СНОІС	E OF 1 - Lot #'s: 987		ft Body, (3) Oil Tanks, (4) Hose Reels, Metered Nozzles, Air Hose Reel, Vanair Air N Arc 150 All-In-One Power System, EQUIPMENT-
987	2015 Ford F-550 4x4 Fuel and Lube Truck		FROM-SUNSTATE-EQUIPMENT Usage: 211,871 Mi
	S/N: 1FDUF5HT5FEA45745 C/W: V8 6.7 L Diesel 300 hp Engine, 2015 US		Asset located in: Lake Worth, TX
	EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, CTEC 12 ft Body, (2) Oil Tanks, (6) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, NAPA 82133GTH 20 cfm Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 129,968 Mi	990	2024 Peterbilt 567 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1XPCP4EX2RD669008 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 18-Speed Manual Transmission, 20000 lb Front Axle, 66280 lb Rears, 80000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual

Transmission, 20000 lb Front Axle, 66280 lb Rears, 80000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 273 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 696 Mi

Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED

Asset located in: Lake Worth, TX

Lot # **Details** Lot # Details 991 994 2013 Peterbilt 389 8x4 Heavy Haul Tri/A Day 2001 Peterbilt 379 8x4 Tri/A Day Cab Truck **Cab Truck Tractor Tractor** S/N: 1XPXP4EX8DD177786 S/N: 1XP5PBEXX1D567716 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel C/W: Cat C15 6 Cylinder 15.2 L Diesel 475 hp 600 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20678.2 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Engine, Engine Brake, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, 14060 lb Front Axle, 63000 lb Rears, Spicer Transmission, Double Differential Locks, 20000 DS463P Drive Axles, 3.90:1 Axle Ratio, 77060 lb Front Axle, 60400 lb Rears, 80000 lb GVWR, Ib GVWR, Air Ride Cab, 385/65R22.5 Front Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Tires, 315/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Axle, Dual Steering Boxes, Double Frame, Air Wheel, Dual Fuel Tanks Trac Air Ride Suspension, 265 in Wheelbase, Usage: 656,865 Mi PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Asset located in: Lake Worth, TX 995 2009 Mack CHU613 8x4 Tri/A Day Cab Truck Usage: 461,474 Mi Tractor Notes: JUNE 2023 - COMPLETE LONG BLOCK S/N: 1M2AN07Y39N003780 ENGINE REPLACEMENT; THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 16784 Engine POLLUTION CONTROL SYSTEMS WITH hrs, Mack MAXITORQUE 18-Speed Manual Transmission, 11R24.5, Air Lift Tag Axle, LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 Camelback Spring Suspension, Air Sliding 5th AND 114.50. THIS MAY APPLY IF YOU Wheel, Rolling Tailboard, Dual Fuel Tanks OPERATE THE UNIT PRIOR TO THE ADEQUATE Usage: 258,896 Mi RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY Asset located in: Lake Worth, TX EQUIPPED. BUYER OF THIS UNIT MUST SIGN 995A 2008 Mack CHU613 8x4 Tri/A Day Cab Truck ACKNOWLEDGEMENT FORM OF THIS NOTICE **Tractor** PRIOR TO REMOVAL OF UNIT FROM YARD S/N: 1M1AN07Y98N002197 PLEASE SEE A PERSONAL NOTE FROM THE C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 SELLER IN THE DOCUMENTS SECTION BELOW hp Engine, 2007 US ÉPA Label, 6242 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Asset located in: Lake Worth, TX Manual Transmission, 13220 lb Front Axle, 992 2013 Kenworth T800 8x4 Heavy Haul Tri/A Day 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Cab Truck Tractor Aluminum Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, 243 in Wheelbase, S/N: 1XKDP4EX0DJ358004 C/W: Cummins ISX15 6 Cylinder 15 L Diesel PTO, Wet Kit, Air Sliding 5th Wheel, Headache 550 hp Engine, 2012 US EPA Label, Requires Rack Diesel Exhaust Fluid, 18818 Engine hrs, Engine Brake, Eaton Fuller 8-Speed Manual Usage: 591,040 Mi Asset located in: Lake Worth, TX Transmission, Double Differential Locks, 20000 lb Front Axle, 66000 lb Rears, 4.10:1 Axle Ratio, 996 2007 Mack CHN613 8x4 Heavy Haul Tri/A Day 80000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Cab Truck Tractor S/N: 1M1AJ07Y57N007228 Rear Tires, Air Lift Pusher Axle, Air Lift Tag C/W: Mack AC 6 Cylinder 11.9 L Diesel 460 hp Engine, 2005 US EPA Label, 13255 Engine hrs, Axle, Dual Steering Boxes, Double Frame, 8-Bag Air Ride Suspension, 258 in Wheelbase, PTO, Engine Brake, Mack Maxitorque 18-Speed Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Manual Transmission, Differential Lock, 20000 Usage: 403,162 Mi Ib Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, Asset located in: Lake Worth, TX 11R24.5 Rear Tires, Air Lift Pusher Axle, Twin Y 993 2013 Peterbilt 579 8x4 Tri/A Day Cab Truck Air Ride Suspension, 254 in Wheelbase, PTO, Tractor Wet Kit, Air Sliding 5th Wheel, Headache Rack, S/N: 1XPBD49X9DD193833 Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2012 US EPA Label, Requires Diesel Usage: 272,150 Mi Exhaust Fluid, 20865.5 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, **Notes**: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS 13200 lb Front Axle, 38000 lb Rears, 51200.0 lb SECTION BELOW GVWR, Air Ride Cab, Aluminum Outer Wheels, Asset located in: Lake Worth, TX 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Lift Pusher Axle, Paccar Air Ride Suspension, 244 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks

Usage: 585,366 Mi

Details Lot # **Details** Lot # 996A 2000 Western Star 4964EX 8x4 Tri/A Day Cab 998 2015 Kenworth T800 Wide Hood 8x4 Tri/A **Truck Tractor** Sleeper Truck Tractor S/N: 1XKDP4TX3FJ427032 C/W: Cummins ISX15 15.0 L 550 hp Engine, S/N: 2WKEDDCJ2YK963807 C/W: Cat 3406 6 Cylinder 14.6 L Diesel 475 hp Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 12000 2014 US EPA Label, Requires Diesel Exhaust Fluid, 9997 Engine hrs, Engine Brake, Eaton lb Front Axle, 58000 lb GVWR, Air Ride Cab, Fuller RTLO-18918B 18-Speed Manual Aluminum Outer Wheels, 11R24.5, Air Lift Transmission, 20000 lb Front Axle, 46000 lb Pusher Axle, Air Lift Tag Axle, Air over Walking Rears, Dana D46-170H Drive Axles, 3.91:1 Axle Beam Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Ratio, 86000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 425 /65R22.5 Front Tires, 285/75R24.5 Rear Tires, Tanks Air Lift Pusher Axle, Dual Steering Boxes Usage: 594,259 Mi Double Frame, Hendrickson Primaax EX Air Asset located in: Lake Worth, TX Ride Suspension, 278 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, 997 2021 Peterbilt 389 8x4 Tri/A Sleeper Truck Dual Fuel Tanks, EQUIPMENT-FROM-A-Tractor PRIMORIS-SERVICES-CORP-COMPANY S/N: 1XPXP4EX9MD740781 Usage: 356,920 Mi C/W: Cummins X15 6 Cylinder 15 L Diesel 605 hp Engine, 2020 US EPA Label, Requires Diesel Notes: EQUIPMENT FROM A PRIMORIS SERVICES CORP COMPANY Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 20000 lb Front Asset located in: Midland, TX Axle, 66000 lb Rears, 80000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 999 2008 Western Star 4900 8x4 Tri/A Sleeper **Truck Tractor** Rear Tires, Steerable Air Lift Pusher Axle, Dual S/N: 5KJNALAV48PZ19813 Steering Boxes, Air Ride Suspension, Air Sliding C/W: Cat C15 6 Cylinder 14.6 L Diesel 550 hp 5th Wheel, Headache Rack, Dual Fuel Tanks Engine, Engine Brake, Eaton Fuller RTLO-Usage: 290,846 Mi 22918B 18-Speed Manual Transmission, 20000 lb Front Axle, 66000 lb Rears, 4.56:1 Axle Ratio, 78150 lb GVWR, Air Ride Cab, 40 in Mid Roof Sleeper Cab, Aluminum Wheels, 425 Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS /65R22.5 Front Tires, 11R22.5 Rear Tires, Air 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE Lift Pusher Axle, Dual Steering Boxes, Airliner Air Ride Suspension, 265 in Wheelbase, Air RESTORATION OF ALL POLLUTION CONTROL Sliding 5th Wheel, Headache Rack, Lowboy SYSTEMS OR DEVICES AS ORIGINALLY Ramps, Dual Fuel Tanks EQUIPPED. BUYER OF THIS UNIT MUST SIGN Usage: 777,671 Mi ACKNOWLEDGEMENT FORM OF THIS NOTICE Asset located in: Lake Worth, TX PRIOR TO REMOVAL OF UNIT FROM YARD 1000 2020 Peterbilt 389 6x4 T/A Day Cab Truck Asset located in: Lake Worth, TX Tractor 997B 2012 Peterbilt 367 8x6 Heavy Haul Tri/A S/N: 1XPXD49X4LD636684 **Sleeper Truck Tractor** C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel S/N: 1XPTP4EX7CD136935 C/W: Cummins ISX15 6 Cylinder 15 L Diesel Exhaust Fluid, 13970 Engine hrs, Engine Brake, 485 hp Engine, 2011 US EPA Label, Requires Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Diesel Exhaust Fluid, 20857 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 18000 lb Front Aluminum Wheels, 11R24.5, Air Trac Air Ride Axle, 66000 lb Rears, 87000 lb GVWR, Air Ride Suspension, 240 in Wheelbase, Headache Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rack, Dual Fuel Tanks Usage: 391,604 Mi Rear Tires, Air Ride Suspension, 260 in Asset located in: Lake Worth, TX Wheelbase, PTO Usage: 528,928 Mi 1001 2019 Peterbilt 389 6x4 T/A Day Cab Truck Asset located in: Lake Worth, TX Tractor S/N: 1XPXD49X0KD266266 C/W: Cummins X15 6 Cylinder 15 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 17028 Engine hrs, 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 11R24.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding

5th Wheel

Usage: 470,871 Mi

Lot # **Details** Lot # Details 1006 2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor CHOICE OF 6 - Lot #'s: 1002, 1003, 1004, 1005, 1006, 1007 S/N: 1XPXD49X0JD468930 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12410.3 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual 1002 2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X0JD468877 Transmission, Differential Lock, 13200 lb Front C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires. Diesel Exhaust Fluid, 11115 Engine hrs, Engine 11R24.5 Rear Tires, Paccar Air Ride Suspension, 242 in Wheelbase, PTO, Wet Kit, Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Air Sliding 5th Wheel Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Usage: Not Available Cab, Aluminum Wheels, Paccar Air Ride Suspension, 218 in Wheelbase, Air Sliding 5th Asset located in: Lake Worth, TX Wheel 1007 2018 Peterbilt 389 6x4 T/A Day Cab Truck Usage: 239,179 Mi Asset located in: Lake Worth, TX S/N: 1XPXD49X4JD468879 1003 2018 Peterbilt 389 6x4 T/A Day Cab Truck C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Tractor Diesel Exhaust Fluid, 12212 Engine hrs, Engine S/N: 1XPXD49X3JD468940 Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12339 Engine hrs, Engine Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Usage: 292,060 Mi Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, Asset located in: Lake Worth, TX 216 in Wheelbase, PTO, Wet Kit, Air Sliding 5th 1009 2012 Peterbilt 389 6x4 T/A Day Cab Truck Usage: 251,546 Mi Tractor S/N: 1XPXDP9X2CD158752 Asset located in: Lake Worth, TX C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 1004 2018 Peterbilt 389 6x4 T/A Day Cab Truck 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 17118.9 Engine hrs, Tractor Engine Brake, Eaton Fuller 13-Speed Manual S/N: 1XPXD49X1JD468922 Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12890 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Trac Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Transmission, Differential Lock, 13200 lb Front Wheel, Headache Rack, Dual Fuel Tanks, Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride **EQUIPMENT-FROM-WATKINS-CONSTRUCTION** Cab, Aluminum Wheels, 11R24.5, Paccar Air Usage: 350,526 Mi Ride Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 254,950 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN Asset located in: Lake Worth, TX TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU 1005 2018 Peterbilt 389 6x4 T/A Day Cab Truck OPERATE THE UNIT PRIOR TO THE ADEQUATE **Tractor** RESTORATION OF ALL POLLUTION CONTROL S/N: 1XPXD49X0JD468958 SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11932.4 Engine hrs, ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; Engine Brake, Eaton Fuller 10-Speed Manual PLEASE SEE A PERSONAL NOTE FROM THE Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, SELLER IN THE DOCUMENTS SECTION BELOW

Asset located in: Lake Worth, TX

Usage: 261,845 Mi

11R24.5 Rear Tires, Paccar Air Ride Suspension, 216 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Air Sliding 5th Wheel

			1 age 64 01 374
Lot #	Details	Lot #	Details
Tractor S/N: 1XPTD40X3GD334935 C/W: Cummins ISX15 6 Cylinder 15 L Die 485 hp Engine, 2015 US EPA Label, CARE Compliant, Requires Diesel Exhaust Fluid 5172.2 Engine hrs, Engine Brake, Eaton F Manual Transmission, Double Differentia	2016 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTD40X3GD334935 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5172.2 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears,	1021	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X2LF369055 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 18503.8 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 243 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 262,049 Mi Asset located in: Lake Worth, TX
 СНОІСІ 1017	Wheels, TTR24.5, All Trac All Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 181,470 Mi Notes: . Asset located in: Humble, TX E OF 6 - Lot #'s: 1017, 1020, 1021, 1022, 1023, 1024 2020 Kenworth T800 6x4 T/A Day Cab Truck	1022	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD40X1LR369030 C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 19464 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 305,184 Mi
1020	Tractor S/N: 3WKDD40X9LF369053 C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 525,807 Mi Asset located in: Lake Worth, TX 2020 Kenworth T800 6x4 T/A Day Cab Truck	Tractor S/N: 1XKDD40X2LR369036 C/W: Cummins X15 6 Cylinder 15.0 450 hp Engine, 2019 US EPA Label, F Diesel Exhaust Fluid, 10215 Engine h Brake, Eaton Fuller Automated Trans Double Differential Locks, 14320 lb F 46000 lb Rears, 3.73:1 Axle Ratio, 60 GVWR, Air Ride Cab, Aluminum Whe 5, 8-Bag Air Ride Suspension, 215 in	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD40X2LR369036 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10215 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, 8-Bag Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel
1020	Tractor S/N: 3WKDD40X8LF369044		Usage: 112,632 Mi
	C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 21597.7 Engine hrs, Eaton Fuller FAO-16810C 10-Speed Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, Dana D46-170 Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 216 in Wheelbase, PTO, Blower, Dual Fuel	1024	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40XXLF369059 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9057 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle,

C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9057 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, 8-Bag Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 100,288 Mi

Asset located in: Lake Worth, TX

Tanks

Usage: 363,166 Mi

Lot #	Details	Lot #	Details
СНОІСІ	CHOICE OF 6 - Lot #'s: 1025, 1026, 1027, 1028, 1029, 1030		2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X7KF369082
1025	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X7KF257267 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23462.2 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 243 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel	1030	C/W: Cummins X15 V10 15 L 450 hp Engine, 2018 US EPA Label, CARB Compliant, 19985 Engine hrs, Eaton Fuller UltraShift Plus 18-Speed Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Aluminum Wheels, 11R24.5, AG400 8-Bag Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Blower Usage: 298,935 Mi Asset located in: Lake Worth, TX 2019 Kenworth T800 6x4 T/A Day Cab Truck
	Tanks Usage: 358,214 Mi Asset located in : Lake Worth, TX		Tractor S/N: 3WKDD40XXKF369089 C/W: Cummins X15 6 Cylinder 15 L Diesel 450
1026	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X9KF257268 C/W: Cummins X15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 23630.9 Engine hrs, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 279,656 Mi		hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19786 Engine hrs, Engine Brake, Automatic Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, Dana D46-172 Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 325,018 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1031	2014 Kenworth T800 6x4 T/A Day Cab Truck
1027	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X7KF369101 C/W: Cummins ISX15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19647 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 338,611 Mi		Tractor S/N: 1XKDDP9X7EJ387103 C/W: Paccar MX 6 Cylinder 12.9 L Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 15503 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 324,545 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1032	2014 Kenworth T800 6x4 T/A Day Cab Truck
1028	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X6KF257275 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 16403.1 Engine hrs, Engine Brake, Eaton UltraShift Plus Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, AG400 8-Bag Air Ride Suspension, 243 in Wheelbase, Blower, Dual Fuel Tanks Usage: 237,353 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKDDP9X9EJ404502 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11282 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Differential Lock, 12350 Ib Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 3.70:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airglide Suspension, 185 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 282,261 Mi Asset located in: Lake Worth, TX

This catalog was created at December 11, 2024 01:25:48 AM GMT. Please check our website for the most accurate and up-to-date information.

Lot #	Details	Lot #	Details
1033	2014 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9XXEJ367542 C/W: Paccar 6 Cylinder 12.9 L 455 hp Engine, 2012 US EPA Label, 13028 Engine hrs, Eaton Fuller FO-16E313A-MHP ULT Automatic Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 295/75R22. 5, 8-Bag Air Ride Suspension, 194 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 297,728 Mi Asset located in: Humble, TX	1037A	2018 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X1JJ215858 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8375 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel Usage: 237,444 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
CHOIC	E OF 2 - Lot #'s: 1035, 1036	CHOICE	E OF 4 - Lot #'s: 1039, 1041, 1042, 1043
1035	2012 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9X2CJ335276 C/W: Paccar MX 6 Cylinder 12.9 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18030 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.55:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 343,666 Mi Asset located in: Lake Worth, TX	1039	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X2GJ495377 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FR015210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Detroit Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 293,721 Mi
1036	2012 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDP9X0CJ335275 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 181 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, Dana Drive Axles, 3.55:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Suspension, 187 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 297,724 Mi Asset located in: Lake Worth, TX 2012 Kenworth T800 6x4 T/A Day Cab Truck	1041	Asset located in: Lake Worth, TX 2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9XXGJ486765 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 269,329 Mi Asset located in: Lake Worth, TX
	Tractor S/N: 1XKDD40X4CR298390 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 500 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 17475 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.89:1 Axle Ratio, 60321 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Neway Air Ride Suspension, 209 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: 324,740 Mi Asset located in: Lake Worth, TX	1042	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X0GJ495376 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Double Frame, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 280,242 Mi Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 1043 2016 Kenworth T880 6x4 T/A Day Cab Truck **Tractor** CHOICE OF 3 - Lot #'s: 1046, 1047, 1048 S/N: 1XKZDP9X3GJ495372 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires 1046 2022 Peterbilt 567 6x4 T/A Day Cab Truck Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Tractor FRO-15210C Manual Transmission, 13200 lb S/N: 1XPCD49X8ND788534 Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, C/W: Cummins X15 6 Cylinder 15 L Diesel 500 53200 lb GVWR, Air Ride Cab, Aluminum Front hp Engine, 2021 US EPÁ Label, Requires Diesel Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase, Air Sliding 5th Wheel, Headache Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Rack, EQUIPMENT-FROM-SUNSTATE-Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 226 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks **EQUIPMENT** Usage: 352,092 Mi Asset located in: Lake Worth, TX Usage: 140,650 Mi 1043A 2016 Kenworth T880 6x4 T/A Day Cab Truck Notes: UNIT IS BEING SOLD WITH A TITLE IN Tractor TRANSIT FOR 14 DAYS AND UNIT CANNOT S/N: 1XKZDP9X6GJ486763 LEAVE YARD UNTIL TITLE IS RECEIVED C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Asset located in: Lake Worth, TX 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 16144.0 Engine hrs, 1047 2022 Peterbilt 567 6x4 T/A Day Cab Truck Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Tractor S/N: 1XPCD49X4ND788532 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, US EPA Label, Requires Diesel 11R22.5, 8-Bag Air Ride Suspension, 186 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, SUNSTATE-EQUIPMENT Aluminum Wheels, 11R24.5, Air Ride Usage: 282,982 Mi Suspension, 225 in Wheelbase, Air Sliding 5th Asset located in: Lake Worth, TX Wheel, Dual Fuel Tanks Usage: 152,789 Mi Notes: UNIT IS BEING SOLD WITH A TITLE IN CHOICE OF 2 - Lot #'s: 1044, 1045 TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED Asset located in: Lake Worth, TX 1044 2015 Kenworth T880 6x4 T/A Day Cab Truck Tractor 1048 2022 Peterbilt 567 6x4 T/A Day Cab Truck S/N: 1XKZDP9XXFJ445423 Tractor C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel S/N: 1XPCD49X6ND788533 430 hp Engine, 2014 US EPA Label, Requires C/W: Cummins X15 6 Cylinder 15 L Diesel 500 Diesel Exhaust Fluid, 15520 Engine hrs, Engine hp Engine, 2021 US EPÁ Label, Requires Diesel Brake, Eaton Fuller FRO-15210Č 10-Speed Exhaust Fluid, 4410 Engine hrs, Engine Brake, Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 11R22.5, 8-Bag Air Ride Suspension, 186 in 5, Air Trac Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks **EQUIPMENT** Usage: 106,800 Mi Usage: 376,184 Mi

1045 2015 Kenworth T880 6x4 T/A Day Cab Truck Tractor

Asset located in: Lake Worth, TX

S/N: 1XKZDP9X8FJ425865 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT

Usage: 316,151 Mi Asset located in: Lake Worth, TX Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED

Lot #	Details	Lot #	Details
		1053	2016 Peterbilt 365 6x4 T/A Day Cab Truck
CHOICE OF 2 - Lot #'s: 1049, 1050			Tractor S/N: 1XPSD79X4GD332529
1049	2020 Peterbilt 567 6x4 T/A Day Cab Truck Tractor S/N: 1NPCD40X8LD649153 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Dual Steering Boxes, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 198,766 Mi Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED Asset located in: Lake Worth, TX		C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24210 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22 5, Air Ride Suspension, 206 in Wheelbase, PTO Blower, Auto Lube Usage: 565,546 Mi Asset located in: Lake Worth, TX
		1054	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X9FD262699 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20820 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb
1050	2019 Peterbilt 567 6x4 T/A Day Cab Truck Tractor S/N: 1XPCD40X7KD611272 C/W: Cummins X15 6 Cylinder 15 L Diesel 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-		GVWR, Air Ride Cab, Aluminum Wheels, 11R22 5, Air Ride Suspension, 206 in Wheelbase, PTC Blower, Auto Lube Usage: 553,424 Mi
			Asset located in: Lake Worth, TX
	Speed Manual Transmission, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 239,603 Mi Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED Asset located in: Lake Worth, TX	1055	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X3FD262701 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 27922 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22 5, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, Blower, Dual Fuel Tanks Usage: 719,738 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 4 - Lot #'s: 1051, 1053, 1054, 1055	1056	2014 Peterbilt 365 6x4 T/A Day Cab Truck
1051	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X6GD332564 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27335.9 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube	Tractor S/N: 1XPSD79X7ED225682 C/W: Cummins ISX12 6 Cylinde 385 hp Engine, 2013 US EPA La Engine hrs, Engine Brake, Eator Manual Transmission, 13200 lb 40000 lb Rears, 53200 lb GVWI Aluminum Wheels, 11R22.5, Ai Suspension, 203 in Wheelbase, Usage: 620,451 Mi Asset located in: Lake Worth, T 1056A 2012 Peterbilt 367 6x4 T/A Day Tractor S/N: 2XPTD40X9CM137840 C/W: Cummins ISX15 6 Cylinde 485 hp Engine, 2011 US EPA La Compliant, Requires Diesel Exh 17714 Engine hrs, Engine Brake 8LL Manual Transmission, 146 46000 lb Rears, 60600 lb GVWI Aluminum Outer Wheels, 11R2- Suspension, 206 in Wheelbase	Tractor S/N: 1XPSD79X7ED225682 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2013 US EPA Label, 35544 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 203 in Wheelbase, Auto Lube
	Usage: 596,995 Mi Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - MAIN KEY Asset located in: Lake Worth, TX		Tractor S/N: 2XPTD40X9CM137840 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 17714 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 14600 lb Front Axle 46000 lb Rears, 60600 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 344,254 Mi

Details Lot # **Details** Lot # 1062 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor** CHOICE OF 8 - Lot #'s: 1058, 1059, 1060, 1061, 1062, S/N: 3AKJGNDV6LDMF6944 1063, 1064, 1065 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7652 Engine hrs, Engine Brake, 2020 Freightliner SD122 6x4 T/A Day Cab 1058 Allison 4700 RDS Automatic Transmission, **Truck Tractor** Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, S/N: 3AKJGNDV2LDLZ5581 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6973 Engine hrs, Engine Brake, Hendrickson Air Ride Suspension, 196 in Allison 4700 RDS Automatic Transmission. Wheelbase, Air Sliding 5th Wheel Usage: 137,436 Mi 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 Asset located in: Lake Worth, TX lb GVWR, Air Ride Cab, Steel, 11R24.5, Hendrickson Air Ride Suspension, 196 in 1063 2020 Freightliner SD122 6x4 T/A Day Cab Wheelbase, Air Sliding 5th Wheel Truck Tractor Usage: 109,108 Mi S/N: 3AKJGNDV3LDMF6934 Asset located in: Lake Worth, TX C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, CARB 1059 2020 Freightliner SD122 6x4 T/A Day Cab Compliant, Requires Diesel Exhaust Fluid, 8183 Truck Tractor Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, S/N: 3AKJGNDV4LDLZ5582 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 Exhaust Fluid, 7090.33 Engine hrs, Engine lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Brake, Allison Automatic Transmission, 13300 Air Ride Suspension, 196 in Wheelbase, Air lb Front Axle, 46000 lb Rears, Air Ride Cab, All Steel, 11R24.5, Hendrickson Air Ride Sliding 5th Wheel Usage: 139,306 Mi Suspension, 196 in Wheelbase, Air Sliding 5th Asset located in: Lake Worth, TX Wheel Usage: 109,592 Mi 1064 2020 Freightliner SD122 6x4 T/A Day Cab Asset located in: Lake Worth, TX **Truck Tractor** S/N: 3AKJGNDV5LDMF6935 1060 2020 Freightliner SD122 6x4 T/A Day Cab C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel **Truck Tractor** S/N: 3AKJGNDV6LDLZ5583 Exhaust Fluid, 7764 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Exhaust Fluid, 8086 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor R7-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300.0 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Usage: 144,087 Mi Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Asset located in: Lake Worth, TX Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 114,295 Mi 1065 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor** Asset located in: Lake Worth, TX S/N: 3AKJGNDV0LDMF6938 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 1061 2020 Freightliner SD122 6x4 T/A Day Cab hp Engine, 2019 US EPA Label, Requires Diesel **Truck Tractor** Exhaust Fluid, 8251.39 Engine hrs, Engine S/N: 3AKJGNDV8LDMF6945 Brake, Allison 4700 RDS Automatic C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7577 Engine hrs, Engine Brake, Axles, 4.30:1 Axle Ratio, Air Ride Cab, All Steel, Allison 4700 RDS Automatic Transmission, 11R24.5 Front Tires, 11R24.5 Rear Tires, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-Hendrickson Air Ride Suspension, 196 in 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 Wheelbase, Air Sliding 5th Wheel Ib GVWR, Air Ride Cab, All Steel, 11R24.5, Usage: 146,736 Mi Hendrickson Air Ride Suspension, 196 in

This catalog was created at December 11, 2024 01:25:48 AM GMT. Please check our website for the most accurate and up-to-date information.

Wheelbase, Air Sliding 5th Wheel

Asset located in: Lake Worth, TX

Usage: 125,283 Mi

Details Lot # **Details** Lot # 1070 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor** CHOICE OF 8 - Lot #'s: 1066, 1067, 1068, 1069, 1070, S/N: 3AKJGNDV9LDMF6940 1071, 1072, 1073 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7512.45 Engine hrs, Engine Brake, Allison 4700 RDS Automatic 2020 Freightliner SD122 6x4 T/A Day Cab 1066 **Truck Tractor** Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive S/N: 3AKJGNDV2LDMF6942 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6915 Engine hrs, Engine Brake, Suspension, 196 in Wheelbase, Air Sliding 5th Allison 4700 RDS Automatic Transmission. Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, Wheel Usage: 166,473 Mi Asset located in: Lake Worth, TX 11R24.5, Hendrickson Air Ride Suspension, 1071 2020 Freightliner SD122 6x4 T/A Day Cab 196 in Wheelbase, Air Sliding 5th Wheel **Truck Tractor** Usage: 149,353 Mi S/N: 3AKJGNDV2LDMF6939 Asset located in: Lake Worth, TX C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel 1067 2020 Freightliner SD122 6x4 T/A Day Cab Exhaust Fluid, 8294 Engine hrs, Engine Brake, Truck Tractor Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 59300 S/N: 3AKJGNDVXLDMF6946 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7122.12 Engine hrs, Engine lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase. Air Brake, Allison 4700 RDS Automatic Sliding 5th Wheel Usage: 182,995 Mi Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Asset located in: Lake Worth, TX Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24. 1072 2020 Freightliner SD122 6x4 T/A Day Cab 5 Rear Tires, Hendrickson Air Ride Suspension, **Truck Tractor** 196 in Wheelbase, Air Sliding 5th Wheel S/N: 3AKJGNDV4LDMF6943 Usage: 158,266 Mi C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Asset located in: Lake Worth, TX hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8575.57 Engine hrs, Engine 1068 2020 Freightliner SD122 6x4 T/A Day Cab Brake, Allison 4700 RDS Automatic **Truck Tractor** Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive S/N: 3AKJGNDV7LDMF6936 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Axles, 4.30:1 Axle Ratio, Air Ride Cab, 11R24.5, hp Engine, 2019 US EPA Label, Requires Diesel Hendrickson Air Ride Suspension, 196 in Exhaust Fluid, 8247 Engine hrs, Engine Brake, Wheelbase, Air Sliding 5th Wheel Allison 4700 RDS Automatic Transmission, Usage: 206,153 Mi Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Asset located in: Lake Worth, TX Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, 1073 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor** Hendrickson Air Ride Suspension, 196 in S/N: 3AKJGNDV9LDMF6937 Wheelbase, Air Sliding 5th Wheel C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Usage: 159,984 Mi Asset located in: Lake Worth, TX Exhaust Fluid, 8897.09 Engine hrs, Engine Brake, Allison 4700 RDS Automatic 1069 2020 Freightliner SD122 6x4 T/A Day Cab Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive **Truck Tractor** S/N: 3AKJGNDV0LDMF6941 Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Ride Cab. All Steel, 11R24.5 Front Tires, 11R24. hp Engine, 2019 US EPA Label, Requires Diesel 5 Rear Tires, Hendrickson Air Ride Suspension, Exhaust Fluid, 7204 Engine hrs, Engine Brake, Allison 4700 RDS 6-Speed Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive 196 in Wheelbase, Air Sliding 5th Wheel Usage: 212,117 Mi Asset located in: Lake Worth, TX Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5, Hendrickson Air

Ride Suspension, 196 in Wheelbase, Air Sliding

5th Wheel

Usage: 163,146 Mi

			Page 91 of 574
Lot #	Details	Lot #	Details
1074	2019 Freightliner Coronado 122SD 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDR5KDKK3918 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12990 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.58:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 497,607 Mi	1078	2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 1FVXFB008BDBC0202 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 709,338 Mi Asset located in: Lake Worth, TX
-	Asset located in: Lake Worth, TX	CHOICE	E OF 2 - Lot #'s: 1079, 1080
1075	2014 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV4EDFU3235 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 9972 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.91:1 Axle Ratio, 52000 lb GVWR, 275 /80R22.5, Airliner Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 210,817 Mi	1079	2015 Western Star 4700 6x4 T/A Day Cab Truck Tractor S/N: 5KJJAVDV9FPGC9066 C/W: Detroit DD13 12.8 L Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 220 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 537,904 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1080	2015 Western Star 4700 6x4 T/A Day Cab
1076	2014 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGND64EDFT1921 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 18532 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner 4-Bag Air Ride Suspension, 224 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel		Truck Tractor S/N: 5KJJAVDV4FLGW9017 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 hp Engine, Requires Diesel Exhaust Fluid, 13494 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 3.91:1 Axle Ratio, 58000 lb GVWR, Air Ride Cab, 11R24.5, Airliner Air Ride Suspension, 210 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 325,533 Mi Asset located in: Lake Worth, TX
	Usage: 394,360 Mi	1082	2012 Cat CT660S 6x4 T/A Day Cab Truck

CHOICE OF 2 - Lot #'s: 1077, 1078

1077 2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor

Asset located in: Lake Worth, TX

S/N: 1FVXFB00XBDBC0203

C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks Usage: 669,379 Mi

Asset located in: Lake Worth, TX

1082 2012 Cat CT660S 6x4 T/A Day Cab Truck Tractor

S/N: 1HTJGTKT7CJ635078 C/W: Cat CT13 6 Cylinder 13 L Di

C/W: Cat CT13 6 Cylinder 13 L Diesel Engine, 2011 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 70000 lb GVWR, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, 241 in Wheelbase

Usage: 123,545 Mi

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
CHOIC 1083	2017 International 8600 6x4 T/A Day Cab Truck Tractor S/N: 3HSHXSNRXHN412325 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 430 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8150 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295 /75R22.5, Air Ride Suspension, 176 in Wheelbase, Dual Fuel Tanks Usage: 355,024 Mi Asset located in: Lake Worth, TX	1088	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X6PD875834 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2323 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Air Leaf Air Ride Suspension, 190 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 72,678 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble, TX
1085	2013 International 7500 6x4 T/A Day Cab Truck Tractor S/N: 1HSWPAZR8DJ239297 C/W: International International 570 6 Cylinder 9.3 L Diesel Engine, 2012 US EPA Label, 5501 Engine hrs, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, PTO, Wet Kit Usage: 28,123 Mi Asset located in: Lake Worth, TX	_1089 _	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X8PD875835 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3195 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Leaf Air Ride Suspension, 189 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 77,420 Mi Notes: Asset located in: Humble, TX
CHOIC	E OF 4 - Lot #'s: 1086, 1087, 1088, 1089	1089A	2022 Peterbilt 579 6x2 T/A Day Cab Truck
1086	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X2PD889441 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2693 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 186 in Wheelbase, Wet Kit, Air Sliding 5th Wheel		Tractor S/N: 1XPBAK9X2ND758793 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 5233.9 Engine hrs, Engine Brake, Paccar Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 150 in Wheelbase, Air Sliding 5th Wheel Usage: 231,143 Mi Asset located in: Lake Worth, TX
	Usage: 54,153 Mi Notes:	1090	2020 Peterbilt 579 6x2 T/A Day Cab Truck Tractor
1087	Asset located in: Humble, TX 2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X4PD889442 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3278 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 192 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 62,819 Mi		S/N: 1XPBAK9X6LD656295 C/W: Paccar MX11 6 Cylinder 10.8 L Diesel Engine, 2019 US EPA Label, 9406 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,689 Mi Asset located in: Lake Worth, TX

Notes: .

Asset located in: Humble, TX

			rage 93 01 374
Lot #	Details	Lot #	Details
1091	2019 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBD49X5KD619305 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10474.6 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 19000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 153,131 Mi Asset located in: Lake Worth, TX	1095	2019 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY4KM002736 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 429,136 Mi Asset located in: Lake Worth, TX
1092	2022 Mack PI64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY9NM010092 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MDrive 12- Speed Automated Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Neway Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1096	2019 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 1FUJHLDR2KLKW2362 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, Differential Lock, 13300 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 621,528 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 621528 TITLE SHOWS 751164
1093	2019 Mack AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY6KM008144 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11664 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 174 in Wheelbase Usage: 517,765 Mi Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2021 Freightliner Cascadia 116 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHTDV3MSMF5488 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2020 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 9731 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride
1094	2019 Mack AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN4GY6KM003456 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15036 Engine hrs, Engine Brake, Mack mDrive Automatic Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 189 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 743,483 Mi Asset located in: Humble, TX		Suspension, 184 in Wheelbase Usage: 356,606 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUAT RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1100	2019 International LT625 6x4 T/A Day Cab Truck Tractor	1105	2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor
	S/N: 3HCDZAPR8KL194089 C/W: Cummins X15 505 6 Cylinder 15.0 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10422 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 199 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 171,523 Mi		S/N: 1XPHDP9X9DD190443 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Leaf Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel Usage: 346,321 Mi
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX
1102	2017 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X1HD387523 C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19516 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 11R24.5, Paccar Air Ride Suspension, 192 in Wheelbase, PTO, Blower Usage: 731,511 Mi Asset located in: Lake Worth, TX	1106	2012 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHD49X2CD135202 C/W: Cummins ISX15 15.0 L Diesel 500 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 20630 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Trac Air Ride Suspension, 212 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 372,724 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 1103, 1104, 1105	1108	2015 Kenworth T680 6x2 T/A Day Cab Truck Tractor
1103	2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X5DD190441 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Leaf Air Ride Suspension, 186 in Wheelbase, Air Sliding		S/N: 1XKYAP9X7FJ437901 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 34000 lb Rears, 3.42:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22. 5, Flex Air Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: 575,781 Mi Asset located in: Lake Worth, TX
	5th Wheel Usage: 783,395 Mi	1112	2017 Mack CXU613 6x4 T/A Day Cab Truck
	Asset located in: Humble, TX	_	Tractor S/N: 1M1AW02Y1HM081245
1104	2013 Peterbilt 386 6x4 T/A Day Cab Truck Tractor S/N: 1XPHDP9X7DD190442 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20012 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Leaf 4-Bag Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel Usage: 382,740 Mi		C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 4592 Engine hrs, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 204 in Wheelbase Usage: 569,651 Mi Asset located in: Humble, TX

Asset located in: Humble, TX

			Page 95 of 5/4	
Lot #	Details	Lot #	Details	
СНОІС 1113	E OF 3 - Lot #'s: 1113, 1114, 1115 2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW09YXGM056302 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual	1117	2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y3EM036867 C/W: Mack 6 Cylinder 10.8 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, Air Ride Suspension, 222 in Wheelbase Usage: 384,415 Mi Asset located in: Lake Worth, TX	
	Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 174,528 Mi Asset located in: Lake Worth, TX	1118	2012 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y8CM017308 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 11235 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 12000	
1114	Tractor S/N: 1M1AW09Y6GM056281 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 7091 Engine hrs, Engine Brake, Mack 10-Speed Manual Transmission, 13220		lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Twin Y Air Ride Suspension, 182 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 300,710 Mi Asset located in: Lake Worth, TX	
		1119	Tractor S/N: 1M1AN07YXJM027640 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2017 US EPA Label, Requires Dies Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front	
1115	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y7FM048675 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26801 Engine hrs, Engine Brake, Mack MPrive 40000 lb Pages 52000 lb (2000)		Cab, Aluminum Wheels, 11R24.5, Air R Suspension, 220 in Wheelbase, PTO, W Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 590,377 Mi	Usage: 590,377 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295/75R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 271,385 Mi		E OF 5 - Lot #'s: 1121, 1122, 1123, 1125, 1126	
	Asset located in: Lake Worth, TX	1121	2014 Mack CHU613 6x4 T/A Day Cab Truck	
CHOICE OF 2 - Lot #'s: 1116, 1117			Tractor S/N: 1M2AN07Y0EM015773 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel	
1116	2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y4EM043164 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel		Exhaust Fluid, 32141 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Hendrickson Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks	

hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 190 in Wheelbase Usage: 484,651 Mi

Asset located in: Humble, TX

Fuel Tanks Usage: 731,351 Mi

Lot #	Details	Lot #	Details
1122	Tractor S/N: 1M2AN07YXEM016719 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445	CHOIC	E OF 2 - Lot #'s: 1127, 1128 2013 Mack CHU613 6x4 T/A Day Cab Truck
			Tractor S/N: 1M1AN07Y8DM011473 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum
1123	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y5EM015669 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445		Outer Wheels, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 536,413 Mi Asset located in : Lake Worth, TX
	13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, 11R24.5, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 569,098 Mi	1128	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y5DM014492 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel
	Asset located in: Lake Worth, TX		Exhaust Fluid, Engine Brake, Mack MAXITORQUE 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 488,617 Mi Asset located in: Humble, TX 2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y1DM014095 C/W: Mack MP8 12.8 L Diesel 445 hp Engine,
1125	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y0DM013475 C/W: Mack MP8 6 Cylinder 12.7 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 22679 lb GVWR, 11R24.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 847,795 Mi		
		1129	
	Asset located in: Lake Worth, TX		
1126	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y5DM014066 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 31299 Engine hrs, Engine Brake, Mack 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks		2011 US EPA Label, Requires Diesel Exhaust Fluid, 29537 Engine hrs, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 747,931 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 767,495 Mi	1130	2013 Mack CHU613 6x4 T/A Day Cab Truck
	Asset located in: Lake Worth, TX		Tractor S/N: 1M2AN07Y1DM013920 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack MaxiTorque 18-Speed Manual Transmission, 13220 lb Front Axle,

C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack MaxiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, 11R24.5, Spring over Walking Beam Suspension, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: 211,417 Mi

		_	
Lot #	Details	Lot #	Details
1132	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07YXCM010660 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MultiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 97,753 Mi Asset located in: Lake Worth, TX	1138	2011 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y6BM006995 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 963 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Twin Y Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 333,241 Mi
CHOIC	E OF 3 - Lot #'s: 1133, 1136, 1137		Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN
1133	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y8CM008989 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Mack maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 511,996 Mi		TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		5.05.4 J. a. Way 44.00
1136	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y3CM009662 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28676 Engine hrs, Mack 8-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Mack Drive Axles, 50000 lb GVWR, Air Ride Cab, 11R24.5, Twin Y Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 732,133 Mi Asset located in: Lake Worth, TX	1139	2019 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDR8KSKM6301 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16826 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer
1137	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y7CM011172 C/W: Mack MP8 6 Cylinder Diesel Engine,		Wheels, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 760,027 Mi
	Requires Diesel Exhaust Fluid, 18044 Engine hrs, Engine Brake, Mack 8-Speed Manual	46.45	Asset located in: Lake Worth, TX
	Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, 4-Bag Air Ride Suspension, 219 in Wheelbase, Dual Fuel Tanks Usage: 710,969 Mi Asset located in: Lake Worth, TX	1141	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV7JSJK4542 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10452 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 393,960 Mi

Lot # Details | Lot # Details

CHOICE OF 3 - Lot #'s: 1142, 1143, 1144

1142 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV6JDJN8606 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Brake, Detroit DT12-OB-1650 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Air Assist Front Suspension, Airliner Air Ride Suspension, 183 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 870,330 Mi

Asset located in: Lake Worth, TX

1143 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV0JDJN8598 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OB-1650HD 12-Speed Automated Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22. 5, Air Assist Front Suspension, Air Ride Suspension, 183 in Wheelbase, PTO Usage: 852,283 Mi

Asset located in: Lake Worth, TX

1144 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDR1JDJW5319 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 9924 Engine hrs, Engine Brake, Detroit DT12-OA-1650 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,742 Mi

Asset located in: Lake Worth, TX

1145 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV7JSJH2022 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 520,949 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1146, 1147

1146 2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGEDV9HSJB4181 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 550,503 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

1147 2017 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor

S/N: 1FUGGEDV1HLJF1652 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 485,070 Mi

Asset located in: Humble, TX

CHOICE OF 2 - Lot #'s: 1149, 1150

1149 2016 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor

S/N: 3AKGGEDV4GDHC4943 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.50:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 850,687 Mi

Page 99 of 574 **Details** Lot # **Details** Lot # 1150 2015 Freightliner Cascadia 125 6x4 T/A Day 1152 2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor **Cab Truck Tractor** S/N: 1FUJGED63FLGD5692 S/N: 1FUJGEDV1DSBV1048 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15861 Engine hrs, Engine Brake, Engine, Requires Diesel Exhaust Fluid, 7413 Engine hrs, Engine Brake, Eaton Fuller FRO-Eaton Fuller 10-Speed Manual Transmission, 15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, Spicer DS404 Drive Axles, 3.70:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, PTO, Wet Kit, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel **Dual Fuel Tanks** Tanks Usage: 570,528 Mi Usage: 675,354 Mi Asset located in: Lake Worth, TX Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - CPC 1150A 2015 Freightliner Cascadia 125 6x2 T/A Day Asset located in: Lake Worth, TX Cab Truck Tractor 1153 2012 Freightliner Cascadia 125 6x4 T/A Day S/N: 3AKGGEDV8FSGK3449 C/W: Detroit 6 Cylinder Engine, 2015 US EPA **Cab Truck Tractor** Label, Requires Diesel Exhaust Fluid, 21446 S/N: 1FUJGEDR3CSBM7925 Engine hrs, Eaton Fuller 10-Speed Manual C/W: Detroit 6 Cylinder Diesel Engine, 1828.42 Engine hrs, Automated Transmission, 13300 lb Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Front Axle, 46000 lb Rears, 59300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tanks Suspension, 151 in Wheelbase, Air Sliding 5th Usage: 512,461 Mi Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-Asset located in: Lake Worth, TX YELLOW-CORP Usage: Not Available Notes: SELLING WITH A BANKRUPTCY CHOICE OF 2 - Lot #'s: 1156, 1157 DOCUMENTS AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; ALL INOPERABLE ITEMS 1156 2016 Freightliner Cascadia 113 6x4 T/A Day NEED TO BE REMOVED FROM THE YARD BY **Cab Truck Tractor** SEPTEMBER 20th CAN NOT BE RECONSIGNED S/N: 3AKJGBDV7GDHA6151 BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE C/W: Detroit DD13 6 Cylinder 12.8 L 380 hp Engine, Requires Diesel Exhaust Fluid, 17605 Engine hrs, Retarder, Detroit DT12-DB-1450 HD 12-Speed Automated Transmission, 12000 lb INSPECTION REPORT Asset located in: Livingston, LA Front Axle, 40000 lb Rears, Meritor MT-40-14X 1150B 2015 Freightliner Cascadia 125 6x2 T/A Day Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Cab Truck Tractor Air Ride Cab, Aluminum Front Wheels, 295 S/N: 3AKGGEDV8FSGK3628 /75R22.5, Airliner Air Ride Suspension, 174 in C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp Wheelbase, Dual Fuel Tanks Engine, 2022 US EPA Label, Requires Diesel Usage: 520,442 Mi Exhaust Fluid, 8724 Engine hrs, Engine Brake, Notes: DEFICIENCIES NOTED - PLEASE SEE Eaton Fuller Automated Transmission, 12000 THE INSPECTION REPORT Asset located in: Humble, TX

lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 176 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP

Usage: 912,917 Mi

Notes: CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; DEFICIENCIES NOTED - PLEASE

SEE THE INSPECTION REPORT Asset located in: Humble, TX

1157 2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor

S/N: 1FUJGBDVXGLGS4295 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 11444 Engine hrs, Engine Brake, Detroit DT12-OB-1450 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 355,568 Mi

Lot #	Details	Lot #	Details
CHOIC	E OF 3 - Lot #'s: 1158, 1159, 1160	СНОІСІ	E OF 2 - Lot #'s: 1162, 1163
1158	2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV5BSBB6309	1162	2015 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1911
	C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 2153 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 275/80R22.5 Front Tires, 445 /50R22.5 Super Singles Rear Tires, Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 861,133 Mi		C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 500 hp Engine, 15249 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 3.73:1 Axle Ratio, 12000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider Kit
	Asset located in: Lake Worth, TX		Usage: 697,934 Mi Asset located in : Lake Worth, TX
1159	2011 Freightliner Cascadia 113 6x4 S/A Day Cab Truck Tractor	1163	2015 Freightliner Columbia 120 6x4 T/A Day
	S/N: 1FUJGBDV9BSAX2724 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 1001 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 36576 lb Rears, 48546 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 884,817 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1908 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 500 hp Engine, 17818 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.73:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider Kit Usage: 333,663 Mi
1160	2011 Freightliner Cascadia 113 6x4 T/A Day		Asset located in: Lake Worth, TX
	Cab Truck Tractor S/N: 1FUJGBDV4BSBB6320 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 8206 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, Air Ride Cab, 275/80R22.5, Airliner Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 856,222 Mi Asset located in: Lake Worth, TX	1163A	2021 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EG1MN286031 C/W: Volvo D13 6 Cylinder Diesel 405 hp Engine, 7784 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50000 lb GVWR, 275/80R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1161	2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor		Usage: 286,472 Mi Asset located in : Lake Worth, TX
	S/N: 1FUJGBDV6BSBB6321 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 29567 Engine hrs, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 869,100 Mi	1166	2016 Volvo VNL 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG4GN973794 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2358 Engine hrs, Engine Brake, Volvo Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Rear Tires, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 805,146 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

			1 450 101 01 57
Lot #	Details	Lot #	Details
1167	2016 Volvo VNL300 6x2 T/A Day Cab Truck Tractor S/N: 4V4NC9EH7GN941916 C/W: Volvo D13J435 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D 12- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 503,664 Mi Asset located in: Lake Worth, TX	1171	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR8JN406076 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12523 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 294,702 Mi Asset located in: Lake Worth, TX
	E OF 9 - Lot #'s: 1168, 1169, 1170, 1171, 1172, 174, 1175, 1176	1172	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR9JN404529
1168	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPRXJN404541 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11699 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Hydraulic		C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13473 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 208 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
	Oil Cooler, Dual Fuel Tanks Usage: 274,941 Mi Asset located in : Lake Worth, TX	1173	2018 International HX620 6x4 T/A Day Cab Truck Tractor
1169	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR0JN406699 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14368 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit,		
	Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 277,391 Mi Asset located in: Lake Worth, TX	1174	2018 International HX620 6x4 T/A Day Cab Truck Tractor
1170	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR4JN405670		S/N: 3HSDTAPR2JN405652 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14783 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual

S/N: 3HSDTAPR4JN405670 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12721 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 286,193 Mi

Asset located in: Lake Worth, TX

450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14783 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 206 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 330,024 Mi

Details Lot # **Details** Lot # 1175 2018 International HX620 6x4 T/A Day Cab **Truck Tractor** CHOICE OF 2 - Lot #'s: 1181, 1182 S/N: 3HSDTAPR5JN404544 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15215 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual 1181 2006 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5DB9X16D644337 Transmission, 13200 lb Front Axle, 40000 lb C/W: Cat C15 6 Cylinder 15.2 L Diesel 435 hp Engine, 2005 US EPA Label, CARB Compliant, Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Hydraulic Oil Cooler, Dual Fuel Tanks Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Usage: 331,216 Mi Outer Wheels, 11R22.5, Air Ride Suspension, Asset located in: Lake Worth, TX 230 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks** 1176 2018 International HX620 6x4 T/A Day Cab Usage: 1,086,784 Mi Truck Tractor Notes: ENGINE REBUILD NOVEMBER 2024 S/N: 3HSDTAPR6JN405671 Asset located in: Humble, TX C/W: Cummins X15 6 Cylinder 15 L Diesel Engine, 2017 US EPA Label, Requires Diesel 1182 2006 Peterbilt 379 6x4 T/A Day Cab Truck Exhaust Fluid, Engine Brake, Eaton Fuller 10-Tractor Speed Manual Transmission, 13200 lb Front S/N: 1XP5DB9X56D648777 Axle, 40000 kg Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, C/W: Cat C15 6 Cylinder 15 L Diesel Engine, Engine Brake, Eaton Fuller 15-Speed Manual 11R24.5 Rear Tires, Hendrickson 4-Bag Air Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Cab, Aluminum Wheels, 11R24.5, Air Ride Usage: 375,019 Mi Suspension, 208 in Wheelbase, Air Sliding 5th Asset located in: Lake Worth, TX Wheel, Headache Rack, Dual Fuel Tanks Usage: 652,502 Mi 1177 2016 International Prostar+122 6x4 T/A Day Asset located in: Lake Worth, TX Cab Truck Tractor S/N: 3HSDJSNR4GN748793 C/W: 6 Cylinder Diesel Engine, Requires Diesel CHOICE OF 1 - Lot #'s: 1184 Exhaust Fluid, 13825 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 1184 2008 Kenworth T800 6x4 T/A Day Cab Truck Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Tractor Wheel, Dual Fuel Tanks S/N: 1XKDD49X38J237363 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2007 US EPA Label, CARB Compliant, 17065 Engine hrs, Engine Brake, Usage: 390.546 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb Asset located in: Humble, TX GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 1178 2011 International Prostar 6x2 T/A Day Cab 5, Air Ride Suspension, 162 in Wheelbase, Headache Rack, Dual Fuel Tanks Truck Tractor S/N: 3HSCUAPRXBN346408 Usage: 508,579 Mi C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2009 US EPA Label, 15012 Asset located in: Lake Worth, TX Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front CHOICE OF 3 - Lot #'s: 1185, 1186, 1187 Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 148 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

1185 2007 Kenworth T800 6x4 T/A Day Cab Truck Tractor

S/N: 1XKDDU9X37R154046 C/W: Cat C13 6 Cylinder 12.5 L Diesel 430 hp Engine, 2006 US EPA Label, 19630 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Asset located in: Lake Worth, TX

Usage: 28,954 Mi

Notes: THE AGE AND CONDITION OF THE

TRUCK INDICATES MORE MILES THAN

SHOWN ON THE ODOMETER

Lot #	Details	Lot #	Details	
1186	2006 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X46R114993 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.70:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 202 in Wheelbase, Dual Fuel Tanks Usage: 566,399 Mi	1191	ICE OF 2 - Lot #'s: 1191, 1193 2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y98N001127 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 485 hp Engine, 2006 US EPA Label, Engine Brake,	
1187	Asset located in: Lake Worth, TX 2005 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X45R086045 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Manual Transmission, 3.70: 1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		Manual Transmission, 12000 lb Fron 38000 lb Rears, 50000 lb GVWR, Air Aluminum Front Wheels, 11R24.5, Ca Spring Suspension, 218 in Wheelbas Sliding 5th Wheel, Lowboy Ramps, R Tailboard, Dual Fuel Tanks Usage: 299,016 Mi	Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: 299,016 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 675,236 Mi Asset located in : Lake Worth, TX		2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y58N003666 C/W: Mack MP8 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 60,062 Mi Asset located in: Lake Worth, TX	
1189	1990 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5D29X1LN295315 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 9-Speed Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 11R24.5, Air Trac Air Ride Suspension, 227 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks			
	Usage: 211,059 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILAGE		E OF 3 - Lot #'s: 1194, 1195, 1196	
1190	Asset located in: Humble, TX 2009 Peterbilt 384 6x4 T/A Day Cab Truck Tractor S/N: 1XPVD09X29D784986 C/W: Cummins 6 Cylinder Diesel 425 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 191 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 310,703 Mi Asset located in: Lake Worth, TX	1194	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y68N001683 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2006 US EPA Label, 11687 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 206 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 437,607 Mi Asset located in: Lake Worth, TX	
		סצוו	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y48N001827 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338	

S/N: 1M1AN09Y48N001827 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 37,316 Mi

Lot #	Details	Lot #	Details
1196	2007 Mack CHU613 6x4 T/A Day Cab Truck Tractor	CHOICE 1201	E OF 2 - Lot #'s: 1201, 1202
	S/N: 1M1AJ06Y47N008341 C/W: Mack 6 Cylinder Diesel Engine, 14078 Engine hrs, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, 11R24.5, Camelback Suspension, 207 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 85,326 Mi Asset located in: Lake Worth, TX		2007 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CK97DZ42349 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb
1198	2006 Mack CV713 6x4 Cab and Chassis S/N: 1M2AG11Y96M034378 C/W: Mack AI 6 Cylinder 12.0 L Diesel Engine, 20885 Engine hrs, Manual Transmission, Air Ride Cab, Aluminum Outer Wheels, 11R22.5,		GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 901,926 Mi Asset located in : Lake Worth, TX
	Hendrickson Air Ride Suspension, 215 in Wheelbase, 113 in Cab to Axle, 191 in Cab to End of Frame Usage: 282,800 Mi Asset located in : Lake Worth, TX	1202 2006 Freightliner Columbia 120 6x Cab Truck Tractor S/N: 1FUJA6CK36LX13895 C/W: Detroit Series 60 6 Cylinder 1 455 hp Engine, 8563 Engine hrs, Er Eaton Fuller FRO-15210C 10-Speed Transmission, Meritor RT-40-145 D 4.11:1 Axle Ratio, Air Ride Cab, 11F Airliner Air Ride Suspension, 182 ir Air Sliding 5th Wheel, Dual Fuel Ta Usage: 174,408 Mi Asset located in: Lake Worth, TX 1204 2009 Volvo VNL300 6x4 T/A Day O Tractor S/N: 4V4NC9EG89N270007 C/W: Volvo D13F405 6 Cylinder 12 338 hp Engine, 2008 US EPA Label Engine hrs, Engine Brake, Eaton Fu Speed Manual Transmission, 1200 Axle, 38000 lb Rears, 2.64:1 Axle R lb GVWR, Steel, 295/75R22.5, Air R Suspension, 168 in Wheelbase, Air Wheel, Dual Fuel Tanks Usage: 607,811 Mi	S/N: 1FUJA6CK36LX13895 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 8563 Engine hrs, Engine Brake,
1199	2003 Mack CX613 Vision 6x4 T/A Day Cab Truck Tractor S/N: 1M1AE07Y23W014985 C/W: Mack AC 6 Cylinder 12.0 L Diesel Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb		•
	Rears, 52000 lb GVWR, Air Ride Cab, 285/75/24.5, Air Lift Pusher Axle, Air Ride Suspension, 242 in Wheelbase, PTO, Wet Kit, Hydraulic System, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,917 Mi Asset located in: Humble, TX		
1200	2009 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CK79LAH0941 C/W: Detroit Series 60 6 Cylinder 14 L Diesel Engine, 2008 US EPA Label, Requires Diesel Exhaust Fluid, 15762.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb		
	Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 225,283 Mi	СНОІСІ	Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 1206, 9694A
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1206	2008 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG98N498365 C/W: Volvo D13 6 Cylinder 13 8 L Diesel 375 hp.

S/N: 4V4MC9EG98N498365 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 375 hp Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, Aluminum Wheels, 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 167 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,449,683 Mi

			Page 105 of 574
Lot #	Details	Lot #	Details
1209	2019 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X1KJ257014 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15624 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, 75 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275 /80R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 286 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 662,371 Mi Asset located in: Lake Worth, TX	1213	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3LD648549 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 39980 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 266,350 Mi Asset located in: Lake Worth, TX
1210	2017 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDP9X6HR157986 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 500 hp Engine, 2016 US EPA Label, Engine Brake, Eaton Fuller FRO-18210C 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, 3.55: 1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 28 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 232 in Wheelbase, Dual Fuel Tanks Usage: 626,873 Mi Notes: THIS UNIT RUNS BUT MAY HAVE	1214	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X1LD702883 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 261 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 273,148 Mi Asset located in: Lake Worth, TX
сноіс	DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX E OF 6 - Lot #'s: 1212, 1213, 1214, 1215, 1216, 1217	1215	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X5LD648553 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, 266 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 276,137 Mi Asset located in: Lake Worth, TX
1212	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49XXLD648550 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 40155 Engine hrs, Engine Brake, 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid	1216	2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X6KD612210 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39162 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11824 5 Air Trac Air Ride Suspension

Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 259 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 306,491 Mi

Asset located in: Lake Worth, TX

Wheels, 11R24.5, Air Trac Air Ride Suspension, 259 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 330,281 Mi

		T	
Lot #	Details	Lot #	Details
1217	2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X9KD611195 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39138 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Suspension, 259 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 313,841 Mi	1221	2012 Peterbilt 388 6x4 T/A Sleeper Truck Tractor S/N: 1XPWD40X9CD164118 C/W: Cummins 6 Cylinder Diesel Engine, 15073.9 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 273 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 326,225 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1222	2015 Peterbilt 567 6x4 T/A Sleeper Truck Tractor
1219	2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3GD369706 C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 57373 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 5320 lb GVWR, 63 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 261 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,399 Mi		S/N: 1XPCDP9X2FD297265 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21748.4 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 39000 lb Rears, 52200 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,572 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT.
	Asset located in: Humble, TX		Asset located in: Humble, TX
1220	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X2FD291241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 23876 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Wet Kit, Dual Fuel Tanks Usage: 402,552 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1223	2013 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDD49X1DJ346141 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 62 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Headache Rack Usage: 637,776 Mi Asset located in: Lake Worth, TX
	THE INSPECTION REPORT . Asset located in : Humble, TX	1224	2018 Freightliner Coronado 122SD 6x4 T/A Sleeper Truck Tractor
1220A			S/N: 3AKJGNDR7JDJV8925 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automated Transmission, 52350.0 lb GVWR, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 264 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 485,348 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1225	2011 Freightliner Coronado 122 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGNDR6BDBB8157 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 391 Engine hrs, Engine Brake, Eaton Fuller RTLO- 16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.90:1 Axle Ratio, Air Ride Cab, 34 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 11R24.5 Rear Tires, Airliner Air Ride Suspension, 245 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 6,330 Mi Asset located in: Lake Worth, TX	CHOICI 1230	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X2LJ317474 C/W: Paccar 6 Cylinder Engine, 12173 Engine hrs, Paccar P016F112C Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Paccar Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, 75 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Sliding 5th Wheel Usage: 523,545 Mi Asset located in: Lake Worth, TX
1225A	2021 Western Star 4900EX 6x4 T/A Sleeper Truck Tractor S/N: 5KJJABD14MPMU5583 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2020 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7129 Engine hrs, Engine Brake, 18-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 60 in Flat Top Sleeper Cab, 285/75R24.5, Airliner Air Ride Suspension, 286 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 258,341 Mi Asset located in: Lake Worth, TX	1231	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 3WKYD49X5LF407169 C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10333 Engine hrs, Engine Brake, Eaton Fuller 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 53200 lb GVWR, 76 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 481,871 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN
1226	2019 Western Star 4900FA 6x4 T/A Sleeper Truck Tractor S/N: 5KJJAEDRXKPKC9060 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Eaton Fuller RTLO 13-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,054 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
		1232	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X4LJ348287 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15421 Engine hrs, Engine Brake, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52500.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 589,051 Mi Asset located in: Humble, TX
1229A	<u>`</u>		

			Page 108 of 574
Lot #	Details	Lot #	Details
1233	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3LJ357819 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16890.8 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 660,370 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	1235	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X6KJ236748 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23865 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks Usage: 632,548 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1233A 2020 Kenworth T680 Tractor S/N: 1XKYDP9X7LJ34 C/W: Paccar MX-13 6 Sulfur Diesel 340 hp E Label, Requires Diesel Engine hrs, Engine Bra Automated Transmiss 40000 lb Rears, Merite 2.79:1 Axle Ratio, 532 72 in High Rise Sleepe Aluminum Wheels, 29 Suspension, Air Slidin Tanks Usage: 474,515 Mi Notes: DEFICIENCIES THE INSPECTION REF	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X7LJ344640 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 340 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15907 Engine hrs, Engine Brake, Paccar 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT4014x3 Drive Axles, 2.79:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks	-1236	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X3KJ239771 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 13393 Engine hrs, Engine Brake, Paccar PO-16F112 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 2.79:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 75 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 581,308 Mi Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	1237	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X2KJ257324 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel
CHOICE OF 5 - Lot #'s: 1234, 1235, 1236, 1237, 1238			455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar Po- 16F112 Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Paccar Drive Axles,
1234	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X2KJ220594 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 25999 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350		2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, TriPac evolution Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,832 Km

S/N: 1XKYD49X2KJ220594 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 25999 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 295/75R22.5, Paccar Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 608,021 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Asset located in: Lake Worth, TX

1238 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor

Asset located in: Humble, TX

S/N: 1XKYD49X3KJ247254 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14976.3 Engine hrs, Engine Brake, Eaton Fuller EED-16F112C 12-Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.79:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 692,454 Mi

Lot #	Details	Lot #	Details
CHOIC	E OF 3 - Lot #'s: 1239, 1240, 1241	СНОІСІ	E OF 3 - Lot #'s: 1242, 1244, 1245
1239	2022 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7ND782896 C/W: Cummins X15 6 Cylinder 15.0 L 500 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 8204 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 359,739 Mi Asset located in: Lake Worth, TX	1242	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2KD263251 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23729 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Paccar Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 671,185 Mi Asset located in: Midland, TX
1240	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X5MD741828 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 8557.7 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 461,648 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1244	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X9KD607207 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 275 /80R22.5 Front Tires, 11R22.5 Rear Tires, AG210 Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 488,776 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE
1241	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7MD755875 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 19042 Engine hrs, Engine Brake, Paccar Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION		ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Midland, TX 2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X6KD604443 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 80 in Condo Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride
	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 565,195 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 565195 TITLE SHOWS 565852

Details Lot # **Details** Lot # 1246 2022 Mack AN64T 6x4 T/A Sleeper Truck Tractor CHOICE OF 4 - Lot #'s: 1249, 1250, 1251, 1252 S/N: 1M1AN4GYXNM023469 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 1249 hp Engine, Requires Diesel Exhaust Fluid, 2020 Freightliner Cascadia 126 6x4 T/A 19021 Engine hrs, Engine Brake, Mack Sleeper Truck Tractor Automated Transmission, 12350 lb Front Axle, S/N: 3AKJHHDR9LSLR4781 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Exhaust Fluid, 14419.45 Engine hrs, Engine Brake, Automatic Transmission, Differential Wheel, Dual Fuel Tanks Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Usage: 409,839 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX Usage: 534,026 Mi 1248 2022 Freightliner Cascadia 126 6x4 T/A Asset located in: Lake Worth, TX **Sleeper Truck Tractor** 1250 2020 Freightliner Cascadia 126 6x4 T/A S/N: 3AKJHHDV6NSMY0047 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Sleeper Truck Tractor S/N: 3AKJHHDR1LSMG6164 Engine Brake, Detroit DT12-HL 12-Speed C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16808 Engine hrs, Engine Brake, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab. Detroit DT12-1650 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb 72 in High Rise Sleeper Cab, Bunk Beds, Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Usage: 298,212 Mi Asset located in: Lake Worth, TX Wheel, Dual Fuel Tanks 1248A 2021 Freightliner Cascadia 126 6x4 T/A Usage: 449,805 Mi Sleeper Truck Tractor Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A S/N: 1FUJHHDR4MLMN0476 REPOSESSION AFFIDAVIT AND MAY NOT BE C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 8554 Engine hrs, Engine Brake, Detroit DT12-1750-OH 12-Speed Automated ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX Transmission, 12350 lb Front Axle, 40000 lb 1251 2020 Freightliner Cascadia 126 6x4 T/A Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in Sleeper Truck Tractor High Rise Sleeper Cab, Bunk Beds, Thermo S/N: 3AKJHHDR6LSLY5486 King TriPac Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16924 Engine hrs, Engine Brake, Rear Tires, Airliner Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

S/N: 3AKJHHDR6LSLY5486 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16924 Engine hrs, Engine Brake, Detroit Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 625,619 Mi

Asset located in: Lake Worth, TX

Tanks

Usage: 321,498 Mi

Asset located in: North East, MD

Details Lot # **Details** Lot # 1252 2020 Freightliner Cascadia 126 6x4 T/A **Sleeper Truck Tractor** CHOICE OF 4 - Lot #'s: 1259, 1263, 1264, 1265 S/N: 3AKJHHDR6LSLT5963 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13413 Engine hrs, Engine Brake, 1259 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor Detroit 12-Speed Automated Transmission, S/N: 3AKJHHDR9KSLG7882 13220 lb Front Axle, 40000 lb Rears, Detroit DA-C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Suspension, Exhaust Fluid, 19617 Engine hrs, Engine Brake, Detroit DT12 12-Speed Automated 229 in Wheelbase, Air Sliding 5th Wheel, Dual Transmission, 13220 lb Front Axle, 40000 lb **Fuel Tanks** Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in Usage: 466,120 Mi High Rise Sleeper Cab, Bunk Beds, Aluminum Notes: COLL B37639 LOT 871 (P53-46) \$45K NON PYMT 2024221 PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-Asset located in: Lake Worth, TX FLEET-VEHICLE-PAG Usage: 527,337 Mi Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1255, 1256 2019 Freightliner Cascadia 126 6x4 T/A 1263 1255 Sleeper Truck Tractor 2020 Freightliner Cascadia 126 6x4 T/A **Sleeper Truck Tractor** S/N: 3AKJHHDR7KSLG7847 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 S/N: 1FUJHHDR2LLLL3459 hp Engine, Engine Brake, Detroit DT12-1650-C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 OH1 12-Speed Automated Transmission, hp Engine, 2019 US EPA Label, Requires Diesel 13220 lb Front Axle, 40000 lb Rears, Detroit DA-Exhaust Fluid, 16366 Engine hrs, Engine Brake, Detroit DT12-1650-OH1 12-Speed Automated RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Air Ride Suspension, 241 in Wheelbase, Air Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in Sliding 5th Wheel, Dual Fuel Tanks, High Rise Sleeper Cab, Bunk Beds, Thermo PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG King TriPac Evolution Auxiliary Power Unit, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 570,587 Mi Asset located in: Lake Worth, TX 1264 2019 Freightliner Cascadia 126 6x4 T/A Usage: 549.606 Mi Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 3AKJHHDRXKSKF0425

1256 2020 Freightliner Cascadia 126 6x4 T/A **Sleeper Truck Tractor**

S/N: 3AKJHHDR8LSMC8947 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, 72 in Condo Sleeper Cab, Bunk Beds, ParkSmart Electric Sleeper Air Conditioner, Aluminum Wheels, 11R22.5, 228 in Wheelbase, Air Sliding 5th Wheel, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG

Usage: 552,948 Mi

Asset located in: Lake Worth, TX

C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18430 Engine hrs, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-

VEHICLE-PAG Usage: 588,359 Mi

Details Lot # **Details** Lot # 1265 2019 Freightliner Cascadia 126 6x4 T/A 1269 2019 Freightliner Cascadia 126 6x4 T/A **Sleeper Truck Tractor** Sleeper Truck Tractor S/N: 3AKJHHDR7KSKE1407 S/N: 3AKJHHDR5KSKJ2878 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit Automated Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 Transmission, Differential Lock, 13220 lb Front lb Front Axle, 40000 lb Rears, 52350.0 lb Axle, 40000 lb Rears, Meritor MT-40-14X Drive GVWR, Air Ride Cab, High Rise Sleeper Cab, Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Bunk Beds, 275/80R22.5, Airliner Air Ride Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-Suspension, 232 in Wheelbase, Air Sliding 5th Whėel Usage: 662,065 Mi Asset located in: Lake Worth, TX FLEET-VEHICLE-PAG 1270 Usage: 609,505 Mi 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 3AKJHHDR1KSKJ2876 1266 2019 Freightliner Cascadia 126 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Sleeper Truck Tractor S/N: 3AKJHHDR2KSKE4277 Exhaust Fluid, 17776 Engine hrs, Engine Brake, C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor Exhaust Fluid, 17458 Engine hrs, Engine Brake, Detroit DT12-V 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb MT-40-14X Drive Axles, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Heater, Sleeper Air Conditioner, Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Usage: 718,586 Mi Air Ride Suspension, 229 in Wheelbase, Air Asset located in: Lake Worth, TX Sliding 5th Wheel, Dual Fuel Tanks Usage: 634,187 Mi Asset located in: Lake Worth, TX CHOICE OF 7 - Lot #'s: 1271, 1272, 1275, 1276, 1277, 1278, 1280 1267 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3KSKH0824 2019 Freightliner Cascadia 126 6x4 T/A 1271 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 Sleeper Truck Tractor hp Engine, Requires Diesel Exhaust Fluid, S/N: 1FUJHHDR3KLKM1453 10620 Engine hrs, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8310 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Rear Tires, Airliner Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner 4-Bag Tanks

Usage: 477,320 Mi

Asset located in: Humble, TX

CHOICE OF 3 - Lot #'s: 1268, 1269, 1270

1268 2019 Freightliner Cascadia 126 6x4 T/A **Sleeper Truck Tractor**

S/N: 3AKJHHDR3KSKJ2880 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 684,650 Mi

Asset located in: Lake Worth, TX

1272 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor

Sliding 5th Wheel, Dual Fuel Tanks Usage: 579,939 Mi

Asset located in: Lake Worth, TX

S/N: 3AKJHHDR7KSKB3770 C/W: Detroit DD15 6 Cylinder 14.8 L Engine, 2017 US EPA Label, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Air Ride Suspension, 240 in Wheelbase, Air

Usage: 701,338 Mi

Lot #	Details	Lot #	Details
1275	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSKK8191 C/W: Detroit DD15 14.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 22547.51 Engine hrs, Engine Brake, Detroit DT12-1650-OH 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 727,804 Mi Asset located in: Lake Worth, TX	1280	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXKSKL3824 C/W: Detroit DD15 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14214 Engine hrs, Engine Brake, Detroit DT-12 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 783,761 Mi Asset located in: Lake Worth, TX
1276	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDV5KSKJ2974 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Eaton Fuller FAO- 16810C 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 445,195 Mi Asset located in: Humble, TX	1281	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR0KLLJ6173 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23298 Engine hrs, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 685,332 Mi Asset located in: Lake Worth, TX
1277	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2KSKP1628 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15930 Engine hrs, Engine Brake, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,964 Mi Asset located in: Lake Worth, TX	1283	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXJSJW4146 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 550,012 Mi Asset located in: Lake Worth, TX
1278	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR4KSKS9784 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 20138.21 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 256 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 593,973 Mi		

Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG

Page 114 of 574 **Details** Lot # **Details** Lot # 1283A 2018 Freightliner Cascadia 126 6x4 T/A 1286 2022 Volvo VNL880 6x4 T/A Sleeper Truck **Sleeper Truck Tractor** Tractor S/N: 3AKJHHFGXJSJW1596 S/N: 4V4NC9EH6NN600794 C/W: Volvo D13H455 6 Cylinder 13.0 L Diesel C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 25160 Engine hrs, Engine Brake, Eaton Fuller FAOM-15810S-EC Automated 455 hp Engine, Requires Diesel Exhaust Fluid, 21619.0 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, Transmission, 13300 lb Front Axle, 40000 lb 13200 lb Front Åxle, 38000 lb Rears, Meritor Rears, Meritor MT-40-14X Drive Axles, 2.64:1 MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 789,122 Mi Notes: SELLING WITH A REPOSESSION Usage: 830,526 Mi AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A PRIOR TO BIDDING REPOSESSION AFFIDAVIT AND MAY NOT BE Asset located in: Lake Worth, TX ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX CHOICE OF 3 - Lot #'s: 1287, 1288, 1289 1284A 2023 Volvo VNL860 6x4 T/A Sleeper Truck Tractor 1287 2021 Volvo VNL860 6x4 T/A Sleeper Truck S/N: 4V4NC9EH2PN605221 C/W: Volvo D13N425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2022 US EPA S/N: 4V4NC9EH8MN600892 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, 8277 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Label, Requires Diesel Exhaust Fluid, 12528 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.47:1 Axle Ratio, Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GVWR, Air Ride Cab, 77 in High Rise 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 77 in High Rise Sleeper Cab, Bunk Beds, /75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Tanks Wheel, Dual Fuel Tanks Usage: 274,809 Mi Usage: 374,829 Mi Notes: . Notes: PER THE DEALER ACTUAL MILEAGE IS Asset located in: Lake Worth, TX HIGHER THAN SHOWING ON ODO AND ECM -TRUE MILEAGE IS UNKNOWN 1285 2022 Volvo VNL860 6x4 T/A Sleeper Truck Asset located in: Lake Worth, TX Tractor S/N: 4V4NC9EH6NN603923 1288

C/W: Volvo 6 Cylinder 12.8 L Diesel 425 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transposition, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks**

Usage: 283,601 Mi

Asset located in: Lake Worth, TX

2020 Volvo VNL860 6x4 T/A Sleeper Truck Tractor

S/N: 4V4NC9EG7LN223199 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 19723 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 511,249 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
1289	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN249446 C/W: Volvo 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 26447 Engine hrs, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,184 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1293A	2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2LN265207 C/W: Volvo 6 Cylinder Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 9030 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 379,291 Mi Asset located in: North East, MD
1292	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor	СНОІСЕ	E OF 3 - Lot #'s: 1294, 1295, 1296
	S/N: 4V4NC9EHOLN249443 C/W: Volvo D13M 6 Cylinder 12.8 L 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 22710.9 Engine hrs, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200.0 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 611,970 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	1294	2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN221498 C/W: Volvo 6 Cylinder 12.8 L 425 hp Engine, Requires Diesel Exhaust Fluid, 19160 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 739,489 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1295	2020 Volvo VNL760 6x4 T/A Sleeper Truck
1293	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3LN245807 C/W: Volvo D13M 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 16978.1 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50500 lb GVWR, Air Ride Cab, 70 in Flat Top Sleeper Cab, 11R22.5, Volvo Air Ride Suspension, 254 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 366,216 Mi	Tractor S/N: 4V4NC9EH6LN249009 C/W: Volvo 6 Cylinder Diese Requires Diesel Exhaust Flu Volvo AT02612F 12-Speed Transmission, 12350 lb Fro Rears, 50350 lb GVWR, Air F Rise Sleeper Cab, Bunk Bed Wheels, 295/75R22.5, Air R 225 in Wheelbase, Air Slidin Fuel Tanks Usage: 387,288 Mi	S/N: 4V4NC9EH6LN249009 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1296	2019 Volvo VNL760 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6KN195791 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12- Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel Usage: 412,464 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1297	2020 Volvo VNL64T740 6x4 T/A Sleeper Truck Tractor	1300A	2019 Volvo VNL760 6x4 T/A Sleeper Truck Tractor
	S/N: 4V4NC9EH8LN258469 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14884 Engine hrs, Automatic Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, 295 /75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,732 Hr		S/N: 4V4NC9EH7KN193984 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 480,468 Mi
	Asset located in: Humble, TX		Asset located in: Lake Worth, TX
CHOIC 1299	CHOICE OF 2 - Lot #'s: 1299, 1300		2020 Volvo VNR 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DH1LN270436 C/W: Volvo 6 Cylinder Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8942 Engine hrs, Engine Brake, Eaton Fuller 10-
	S/N: 4V4NC9TJ3KN204274 C/W: Cummins X15 500ST 6 Cylinder 15.0 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-20913A 13-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 51200.0 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Assist Front Suspension, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 251,927 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
		1303	2022 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR0NN285693 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 15135 Engine hrs, Engine Brake Eaton Fuller 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb
300 2019 Volvo VNL 6 S/N: 4V4NC9EH1 C/W: Volvo D13M hp Engine, 2018 L Exhaust Fluid, Eng 18210C 10-Speed 13200 lb Front Ax Axle Ratio, 51200 in High Rise Sleep /75R22.5, Volvo A Wheelbase, Air SI Tanks Usage: Not Availa Notes: SELLING V AFFIDAVIT AND N YOUR STATE. VEI PRIOR TO BIDDIN	2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH1KN232987 C/W: Volvo D13M 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 18210C 10-Speed Automated Transmission,		Rears, 2.64:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 73 in Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 450,018 Mi Asset located in: Lake Worth, TX
	13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1304	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3LN800182 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16079 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 484,652 Mi

Lot#	Details	Lot #	Details
СНОІС	E OF 3 - Lot #'s: 1305, 1306, 1307	1309	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR8KN566457
1305	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZTZR3LN684488 C/W: International A26 6 Cylinder 12.4 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16142 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	сноіс	C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14830 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 118,050 Mi Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1310, 1311, 1312
1306	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR5LN854650 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12492 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 351,096 Mi Asset located in: Lake Worth, TX	1310	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR0KN070889 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15367 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22. 5, Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 467,363 Mi Asset located in: Lake Worth, TX
1307	2020 International LT625 4x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR7LN854651 C/W: Cummins X15 6 Cylinder Diesel 450 hp Engine, 2019 US EPA Label, Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, Air Ride Cab, 51 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Sliding 5th Wheel Usage: 471,259 Mi Asset located in: Lake Worth, TX	1311	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9KN748748 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19547 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 73 in Condo Sleeper Cab, Bunk Beds,
1308	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR8KN122995 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	Steel, 11R2 Wheelbase Tanks Usage: 46 Asset loca 1312 2019 Inter Truck Track S/N: 3HSD C/W: Cum 450 hp Eng Diesel Exh Transmiss Axle, 4000 High Rise s Ride Suspe 5th Wheel, MAINTAIN Usage: 56	Steel, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 467,585 Mi Asset located in: Lake Worth, TX 2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3KN350628 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 73 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 561,974 Mi Asset located in: Lake Worth, TX

Details Lot# **Details** Lot # 1313 2019 International LT 6x4 T/A Sleeper Truck 1318 2018 Peterbilt 579 6x4 T/A Sleeper Truck **Tractor** Tractor S/N: 1XPBDP9X6JD488661 S/N: 3HSDZAPR3KN319055 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 22731.5 Engine hrs, Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab. 295 Ride Cab, 73 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air /75R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Sliding 5th Wheel, Dual Fuel Tanks Usage: 623,951 Mi Usage: 459,002 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL Asset located in: Humble, TX SYSTEMS WITH LIABILITIES OUTLINED IN 1314 2019 International LT625 6x4 T/A Sleeper TEXAS; ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE Truck Tractor S/N: 3HSDZAPR5KN284342 RESTORATION OF ALL POLLUTION CONTROL C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2018 US EPA Label, Requires Diesel SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; SELLING WITH A REPOSESSION AFFIDAVIT Exhaust Fluid, 19700 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 AND MAY NOT BE ACCEPTED IN YOUR STATE. /75R22.5, Air Ride Suspension, 228 in VERIFY WITH YOUR LOCAL DMV PRIOR TO Wheelbase, Air Sliding 5th Wheel, Dual Fuel **BIDDING** Tanks Usage: 603,242 Mi Asset located in: Lake Worth, TX Notes: . Asset located in: Lake Worth, TX CHOICE OF 1 - Lot #'s: 1319

CHOICE OF 2 - Lot #'s: 1317, 1318

1317 2018 Peterbilt 579 6x4 T/A Sleeper Truck

S/N: 1XPBDP9X7JD457743 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15889 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000.0 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 685,817 Mi

Asset located in: Lake Worth, TX

1319 2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor

S/N: 1XPBD49X6HD423821 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 23493.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 730,143 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1321, 1322

1321 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor

S/N: 1XPBD49X0GD330582 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19825 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 908,570 Mi

			Page 119 01 5/4
Lot #	Details	Lot #	Details
1322	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9XXGD298189 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 20896 Engine hrs, Engine Brake, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 635,966 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1326	2013 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49XXDD206468 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller 8-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Low Air Leaf Air Ride Suspension, 246 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes:
СНОІС	E OF 2 - Lot #'s: 1323, 1324	1327	Asset located in: Midland, TX 2013 Peterbilt 386 6x4 T/A Sleeper Truck
1323	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD262361 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 37998 lb Rears, 50000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Flex Air Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 893,094 Mi Asset located in: Lake Worth, TX	1327	Tractor S/N: 1XPHD49X8DD173180 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Low Air Leaf Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 820,824 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Humble, TX
1324	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD285266 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Coolant Heater, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 80 in High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel Usage: 862,250 Mi Asset located in: Lake Worth, TX	1328	2012 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49X0CD142424 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28592 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Front Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Leaf Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 778,429 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE

			Page 120 of 5/4
Lot #	Details	Lot #	Details
1329	2011 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7D49X7BD121337 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 23966.7 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,350 Mi Asset located in: Lake Worth, TX	CHOICE 1333	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9XXHJ144648 C/W: Paccar MX-13 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 24355 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Aluminum
СНОІС	E OF 2 - Lot #'s: 1330, 1331		Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 901,856 Mi
1330	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X2JJ216429 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.93:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Paccar 4-Bag Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Midland, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		1334	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X2HJ146961 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 25916 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT40-14X3 Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1331	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor		Usage: 643,846 Mi Asset located in : Lake Worth, TX
	S/N: 1XKYD49X3JJ185028 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 31003 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295/75R22.5, Paccar Air Ride Suspension, 222 in Wheelbase, Dual Fuel Tanks Usage: 630,153 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	1335	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X3HJ145768 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 26851 Engine hrs, Engine Brake, Eaton Fuller Eaton Advantage 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,016 Mi Asset located in: Livingston, LA

Lot #	Details	Lot #	Details
1336	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X0HJ153938 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19893 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 76 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 238 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks	1340	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X9FJ449653 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 23432 Engine hrs, Engine Brake, Automatic Transmission, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, 295/75R22.5, 8-Bag Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 810,190 Mi Asset located in: Humble, TX
	Usage: 631,336 Mi	1341	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor
1337	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP8X6GJ121464 C/W: Paccar 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2310 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Differential Lock, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 60,967 Mi Asset located in: Lake Worth, TX		S/N: 1XKYD48XXFJ420758 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810C 10-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 3.36:1 Axle Ratio, 46350 lb GVWR, Air Ride Cab, 75 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,063,376 Mi Asset located in: Humble, TX
1338	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X4GJ118091 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 2504 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 38 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 827,511 Mi Asset located in: Lake Worth, TX	1342	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD48X2FJ420768 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 30258 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, 46350 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,080,201 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
CHOICI	E OF 4 - Lot #'s: 1339, 1340, 1341, 1342	1343	2015 Kenworth T680 6x4 T/A Sleeper Truck
1339	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X7FJ430257 C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: 866,880 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKYDP9X1FJ450926 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 231 in Wheelbase, Dual Fuel Tanks Usage: 809,582 Mi Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED

			Page 122 of 574
Lot #	Details	Lot #	Details
СНОІС	CHOICE OF 1 - Lot #'s: 1345		2016 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X4GJ481394
1345	2012 Kenworth T700 6x4 T/A Sleeper Truck Tractor S/N: 1XKFDP9X9CJ325479 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 16210B 10-Speed Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, 11R22.5, Paccar Air Ride Suspension, 231 in Wheelbase, Dual Fuel Tanks		C/W: Cummins ISX 6 Cylinder 14.9 L Diesel 500 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4526 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, Flat Top Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 244 in Wheelbase, Dual Fuel Tanks Usage: 1,002,171 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN
	Usage: Not Available Asset located in : Midland, TX		TEXAS ADMINISTRATIVE CODE SECTIONS
CHOIC 1346	CHOICE OF 3 - Lot #'s: 1346, 1347, 1348		114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD
	Tractor		Asset located in: Lake Worth, TX
	S/N: 1XKAD49X2GJ481393 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel	1348	2014 Kenworth T660 6x4 T/A Sleeper Truck
	485 hp Engine, 31744 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, Spicer DSP40 Drive Axles, 3.55:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 52 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 244 in Wheelbase, Dual Fuel Tanks Usage: 908,066 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX		Tractor S/N: 1XKAD49XXEJ397691 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 35718 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Dual Fuel Tanks Usage: 970,194 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX

1349 2014 Kenworth T600 6x4 T/A Sleeper Truck **Tractor**

S/N: 1XKAD48X8EJ414196 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17145 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Air Ride Cab, 50 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, 11824 5 Air Cab, Sleeper Air Conditioner, 11R24.5, Air Assist Front Suspension, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel

Usage: 555,466 Mi

Details Lot# **Details** Lot # 1350 1351C 2013 Kenworth T660 6x4 T/A Sleeper Truck 2012 Kenworth T660 6x4 T/A Sleeper Truck **Tractor** Tractor S/N: 1XKADP9X9CJ336573 S/N: 1XKADP9X3DJ353712 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 485 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 340 hp Engine, 2011 US ÉPA Label, Requires Diesel hp Engine, 2012 US ÉPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Exhaust Fluid, 14246 Engine hrs, Engine Brake, RTOC16909A Manual Transmission, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb 12000 lb Front Axle, 40000 lb Rears, 52000 lb Rears, Dana DSP41 Drive Axles, 3.36:1 Axle GVWR, Air Ride Cab, 62 in High Rise Sleeper Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 295 Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 121 in Wheelbase, Air Sliding /75R22.5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 128 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel 5th Wheel, Dual Fuel Tanks Usage: 481,647 Mi Tanks Notes: SELLING WITH A REPOSESSION Usage: 554,558 Mi AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV Notes: UNIT HAS NO THROTTLE PRIOR TO BIDDING Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1351A 2012 Kenworth T660 6x4 T/A Sleeper Truck 1351D 2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor Tractor S/N: 1XKAD49X6CJ297018 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel S/N: 1XKAD49X9CJ297000 400 hp Engine, Requires Diesel Exhaust Fluid, 24434 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 47200 lb C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 22628 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, Wheel, Dual Fuel Tanks 235 in Wheelbase, Air Sliding 5th Wheel, Dual Usage: 809,118 Mi **Fuel Tanks** Asset located in: Lake Worth, TX Usage: 724,564 Mi 1351B 2012 Kenworth T660 6x4 T/A Sleeper Truck Asset located in: Lake Worth, TX **Tractor** S/N: 1XKAD49X6CJ297052 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel CHOICE OF 2 - Lot #'s: 1353, 1354 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 34000 lb Rears, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in Mid Roof Sleeper Cab, Thermo 1353 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3FM051337 King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Paccar Air Ride C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22586 Engine hrs, Engine Brake, Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 13-Speed Manual Transmission, 12350 lb Usage: Not Available Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Asset located in: Lake Worth, TX Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 607,391 Mi Asset located in: Lake Worth, TX 1354 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM049326

S/N: 1M1AW02YXFM049326 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel

hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase

Usage: Not Available

Lot #	Details	Lot #	Details
CHOICI	CHOICE OF 7 - Lot #'s: 1355, 1356, 1357, 1358, 1359, 1360, 1361		2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y1EM042263 C/W: Mack MP7 6 Cylinder 10.8 L Diesel
1355	355 2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y2EM036889 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front		Engine, 2013 US EPÅ Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tanks Usage: 778,799 Mi Asset located in: Lake Worth, TX
	Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 897,867 Mi Asset located in : Lake Worth, TX	1360 2014 Mack CXU613 6x4 T/A Sleeper Tru Tractor S/N: 1M1AW02YXEM040902 C/W: Mack MP7 6 Cylinder 10.8 L Diese hp Engine, 2013 US EPA Label, Requires Exhaust Fluid, 13-Speed Manual Transm 12350 lb Front Axle, 40000 lb Rears, 523 GVWR, Air Ride Cab, 60 in Mid Roof Slee Cab, Aluminum Wheels, 285/75R24.5, A Suspension, 222 in Wheelbase Usage: 805,702 Mi Asset located in: Lake Worth, TX 1361 2014 Mack CXU613 6x4 T/A Sleeper Tru Tractor S/N: 1M1AW02Y6EM036877 C/W: Mack MP7 6 Cylinder 10.8 L Diese hp Engine, 2013 US EPA Label, Requires Exhaust Fluid, 9682 Engine hrs, Engine E Eaton Fuller 13-Speed Manual Transmis 12350 lb Front Axle, 40000 lb Rears, 523 GVWR, Air Ride Cab, 70 in Mid Roof Slee Cab, 285/75R24.5, Air Ride Suspension, Wheelbase Usage: 794,371 Mi Asset located in: Lake Worth, TX CHOICE OF 6 - Lot #'s: 1362, 1363, 1364, 1365, 15 Tractor	S/N: 1M1AW02YXEM040902 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel
1356	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM040890 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-		12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 222 in Wheelbase Usage: 805,702 Mi
	Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R22.5, Air Ride Suspension, 214 in Wheelbase Usage: 773,925 Mi Asset located in: Lake Worth, TX		2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM036877 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9682 Engine hrs, Engine Brake,
1357	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y1EM036897 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 25651 Engine hrs, Engine Brake, Manual Transmission, 12350 lb Front Axle,		12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, 285/75R24.5, Air Ride Suspension, 217 in Wheelbase Usage: 794,371 Mi
	40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in		E OF 6 - Lot #'s: 1362, 1363, 1364, 1365, 1366, 136
	Wheelbase, PTO, Air Sliding 5th Wheel Usage: 836,651 Mi Asset located in : Lake Worth, TX		
1358	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM042227 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 22893 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285 /75R24.5 Front Tires, 275/80R22.5 Rear Tires, 4-Bag Air Ride Suspension, 219 in Wheelbase, PTO Usage: 822,170 Mi		S/N: 1M1AW02Y9EM042236 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 675,329 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1363	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4EM042225 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, mRide	1367	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM042244 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Wheels, 285 /75R24.5, Air Ride Suspension, 222 in	
	Air Ride Suspension, 218 in Wheelbase Usage: 730,061 Mi Asset located in : Lake Worth, TX		Wheelbase Usage: 741,289 Mi Asset located in : Lake Worth, TX	
1364	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM033793 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 31248 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 218 in Wheelbase Usage: 755,801 Mi	1368	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW07Y6EM042008 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18- Speed Manual Transmission, 6600 kg Front Axle, 20800 kg Rears, 27400 kg GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 707,937 Mi	
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX	
1365	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM042243	СНОІС	E OF 6 - Lot #'s: 1369, 1370, 1371, 1372, 1373, 137	
	C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 791,657 Mi Asset located in: Lake Worth, TX	1369	Tractor S/N: 1M1AW02Y8EM036878 C/W: Mack MP7 6 Cylinder 10.8 L D hp Engine, 2013 US EPA Label, 2679 hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 4 Rears, 52350.0 lb GVWR, Air Ride Ca	S/N: 1M1AW02Y8EM036878 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, 26792 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5 Front
1366	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor		Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 217 in Wheelbase Usage: 871,001 Mi	
	S/N: 1M1AW02Y7EM040887 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395	1070	Asset located in: Humble, TX	
	hp Engine, 2013 US ÉPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 690,857 Mi Asset located in: Lake Worth, TX	1370	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7DM024736 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 214 in Wheelbase Usage: 701,446 Mi	

Lot #	Details	Lot #	Details
1371	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8DM029525	СНОІСІ	E OF 6 - Lot #'s: 1375, 1376, 1377, 1378, 1379, 138
	C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension Usage: 643,699 Mi Asset located in: Lake Worth, TX	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXDM029512 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 24261 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper	
1372	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6DM029524		Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase Usage: 648,076 Mi
	C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395		Asset located in: Lake Worth, TX
	hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 13523 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 756,971 Mi Asset located in: Lake Worth, TX 2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3DM029500	1376	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y2DM024739 C/W: Mack MP7 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 26124 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Mid Roof Sleeper Cab,
1373			Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 218 in Wheelbase Usage: 690,603 Mi
			Asset located in: Lake Worth, TX
1374	C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 3225 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension, 220 in Wheelbase Usage: 674,399 Mi Asset located in: Lake Worth, TX 2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor	1377	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033782 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20338 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase Usage: 658,728 Mi Asset located in: Lake Worth, TX
	S/N: 1M1AW21Y6DM034381 C/W: Mack MP8 6 Cylinder 12.7 L Diesel Engine, 30700 Engine hrs, Mack Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase Usage: 813,858 Mi Asset located in: Lake Worth, TX	1378	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033751 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 783,814 Mi

Details Lot # **Details** Lot # 1379 2013 Mack CXU613 6x4 T/A Sleeper Truck 1383 2014 Mack CHU613 6x4 T/A Sleeper Truck **Tractor** Tractor S/N: 1M1AN07Y1EM015852 S/N: 1M1AW02Y4DM033748 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US ÉPA Label, Engine Brake, hp Engine, 2013 US ÉPA Label, Requires Diesel Exhaust Fluid, 2950 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Mid Roof Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase Usage: 624,802 Mi Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 462,432 Mi 1380 2013 Mack CXU613 6x4 T/A Sleeper Truck Notes: DEFICIENCIES NOTED - PLEASE SEE Tractor THE INSPECTION REPORT. S/N: 1M1AW02Y8DM031484 Asset located in: Humble, TX C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front CHOICE OF 2 - Lot #'s: 1385, 1386 Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 1385 2019 Freightliner Cascadia 125 6x4 T/A Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 216 in Wheelbase Sleeper Truck Tractor S/N: 3AKJGLDR6KSKS1465 Usage: Not Available C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Asset located in: Humble, TX Exhaust Fluid, 19541.1 Engine hrs, Detroit 1381 2011 Mack CXU613 6x4 T/A Sleeper Truck DT12-1550 OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in **Tractor** S/N: 1M1AW07Y3BM015005 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2010 US ÉPA Label, Requires Diesel Exhaust Fluid, Mack MDrive Automated High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 723,931 Mi Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 295 **Notes:**; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION /75R22.5, Air Ride Suspension, 226 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual **BELOW SUPPLIED** Fuel Tanks Asset located in: Lake Worth, TX Usage: 1,133,741 Mi Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1382, 1383

1382 2015 Mack CHU613 6x4 T/A Sleeper Truck Tractor

S/N: 1M1AN07Y2FM019667 C/W: Mack MP8 6 Cylinder Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 237 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks

Usage: 510,043 Mi

Notes: .

Asset located in: Humble, TX

1386 2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLDV6KSKH9486 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23543 Engine hrs, Detroit DT12-1550-OH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 720,855 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Details Lot # **Details** Lot # 1387 2019 Freightliner Cascadia 125 6x4 T/A 1395 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGLDV2JLJP4880 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 S/N: 3AKJGLDR3KDKM9521 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 12000 lb Front 21109 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, Ride Cab, 70 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Tanks Usage: 890,800 Mi Wheel Usage: 512,155 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Asset located in: Lake Worth, TX THE INSPECTION REPORT Asset located in: Humble, TX 1388 2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor 1397 2018 Freightliner Cascadia 125 6x4 T/A S/N: 3AKJGLDR9KDKM9524 Sleeper Truck Tractor C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 S/N: 1FUJGLDV0JLJK2888 C/W: Detroit DD13 12.8 L Diesel Engine, hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Requires Diesel Exhaust Fluid, Engine Brake, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Eaton Fuller 10-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Rears, 52000 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air 11R22.5, Airliner Air Ride Suspension, 252 in Ride Cab, 72 in Mid Roof Sleeper Cab, Wheelbase, Air Sliding 5th Wheel Aluminum Wheels, 11R22.5, Air Ride Usage: 525,435 Mi Suspension, 240 in Wheelbase, Air Sliding 5th Asset located in: Humble, TX Wheel, Dual Fuel Tanks Usage: 408,806 Mi 1393 2018 Freightliner Cascadia 125 6x4 T/A Asset located in: Lake Worth, TX **Sleeper Truck Tractor** S/N: 1FUJGLDV4JLJV0967 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel CHOICE OF 5 - Lot #'s: 1398, 1399, 1401, 1402, 1403 Exhaust Fluid, 8996 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C-EA Automated 1398 2018 Freightliner Cascadia 125 6x4 T/A Transmission, 12000 lb Front Axle, 40000 lb Sleeper Truck Tractor Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Thermo King TriPac S/N: 1FUJGLDR4JLJV0566 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Evolution Auxiliary Power Unit, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension,

CHOICE OF 3 - Lot #'s: 1394, 1395, 1397

Usage: 373,961 Mi

Fuel Tanks

1394 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

Asset located in: Lake Worth, TX

S/N: 3AKJGLDR8JSHF3927 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

240 in Wheelbase, Air Sliding 5th Wheel, Dual

Asset located in: Lake Worth, TX

Usage: 604,042 Mi

Exhaust Fluid, 12180 Engine hrs, Engine Brake, Detroit DT12-1650-OA 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Steel, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG

Asset located in: Lake Worth, TX

Usage: 420,575 Mi

Details Lot # **Details** Lot # 1399 2018 Freightliner Cascadia 125 6x4 T/A 1403 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGLDR7JLJV0576 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 S/N: 1FUJGLDR2JLJV0565 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 20205 Engine hrs, Engine Brake, Detroit DT12-OA-1750 12-Speed Automated hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13300 lb Front Axle, Transmission, 13300 lb Front Axle, 40000 lb 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Cab, Bunk Beds, Carrier Comfort Pro Auxiliary Power Unit, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Power Unit, Aluminum Front Wheels, 295 Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel VEHICLE-PAG Tanks, PROFESSIONÄLLY-MAINTAINED-FLEET-Usage: 442,347 Mi VEHICLE-PAG Usage: 528.613 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1401 2018 Freightliner Cascadia 125 6x4 T/A

Sleeper Truck Tractor

S/N: 1FUJGLDR5JLJV0558 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12958 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum Front Wheels, 295 /75R22.5, Airliner Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 479,989 Mi

Asset located in: Lake Worth, TX

1402 2018 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor**

S/N: 1FUJGLDR3JLJV0560 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OA-1750 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks PROFESSIONALLY-MAINTAINED-FLEET-**VEHICLE-PAG**

Usage: 506,969 Mi

Asset located in: Lake Worth, TX

1405 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

CHOICE OF 2 - Lot #'s: 1405, 1406

S/N: 3AKJGLDR0HSHY7696 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, Requires Diesel Exhaust Fluid, 24725.4 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor RT-40-145A Drive Axles, 3.42:1 Axle Ratio, 53300 lb GVWR, 58 in Flat Top Sleeper Cab, 295 /75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks Usage: 695,017 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Lot # Details 1406 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR1HSHY7691 C/W: Detroit DD15 6 Cylinder 14.8 L Dies hp Engine, 2018 US EPA Label, Requires Exhaust Fluid, 24671 Engine hrs, Engine Eaton Fuller 10-Speed Manual Transmis 13300 lb Front Ayle 40000 lb Rears 3.47

C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 24671 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.42:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Suspension, 224 in Wheelbase, Dual Fuel Tanks

Usage: 879,236 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

CHOICE OF 5 - Lot #'s: 1407, 1408, 1409, 1410, 1411

1407 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR6HLHW3673 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1650 12-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 713,350 Mi

Asset located in: Lake Worth, TX

1408 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR5HLHF2174 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1750 HD 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 813,536 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Asset located in: Lake Worth, TX

Lot # Details 1409 2017 Freightliner Cascadia 125 6x4 T/A

Sleeper Truck Tractor
S/N: 3AKJGLDR6HSHF0874
C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400
hp Engine, Requires Diesel Exhaust Fluid,
Engine Brake, Detroit DT12-DA-1750 12-Speed
Automated Transmission, 12500 lb Front Axle,
40000 lb Rears, Meritor MT-40-14X Drive Axles,
2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab,
70 in High Rise Sleeper Cab, Bunk Beds,
Aluminum Wheels, 295/75R22.5, Air Ride
Suspension, 224 in Wheelbase, Air Sliding 5th
Wheel, Dual Fuel Tanks

Asset located in: Lake Worth, TX

Usage: 720,617 Mi

1410 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLBG4HSJE6318 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 2448 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 785,075 Mi

Asset located in: Lake Worth, TX

1411 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR0HLHX4331 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 610,011 Mi

CHOICE OF 6 - Lot #'s: 1412, 1413, 1414, 1415, 1416, 1421

1412 2016 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor**

Lot #

Details

S/N: 3AKJGLD57GSHV4416 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 27284 Engine hrs, Engine Brake, Detroit DT12-DA-1550 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 873,575 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Lake Worth, TX

1413 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLBG0GSGY9123 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 3793 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 666,327 Mi

Notes: .

Asset located in: Lake Worth, TX

1414 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLBG2GSHB0517 C/W: Cummins ISX15 450ST2 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 29538 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 772,091 Mi

Asset located in: Lake Worth, TX

Lot # **Details** 1415 2016 Freightliner Cascadia 125 6x4 T/A

Sleeper Truck Tractor S/N: 3AKJGLD52GSGU0419 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Engine Brake, Detroit DT12-DA 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-

4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Tanks Usage: 1,114,394 Mi

Asset located in: Lake Worth, TX

1416 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLBG3GSGX0680 C/W: Cummins ISX 6 Cylinder Diesel 450 hp Engine, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 790,465 Mi

Asset located in: Lake Worth, TX

1421 2016 Freightliner Cascadia 125 6x2 T/A Sleeper Truck Tractor

S/N: 3AKGGLD55GSGC5502 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 25874 Engine hrs, Engine Brake, Detroit DT12 Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, 295 /75R22.5. Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 618,196 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Asset located in: Lake Worth, TX

CHOICE OF 5 - Lot #'s: 1422, 1423, 1424, 1425, 1426

1422 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLD59GLGU1997 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel **Tanks**

Usage: 880,832 Mi

Details Lot # **Details** Lot # 1423 1427 2015 Freightliner Cascadia 125 6x4 T/A 2016 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** Sleeper Truck Tractor S/N: 3AKJGLBGXGSHT7100 S/N: 1FUJGLDV4FLGM6667 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24362 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18642 Engine hrs, Eaton Fuller 10-Speed Automated Transmission, 12000 lb Front Axle, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 52000 lb 40000 lb Rears, Detroit DA-RT-40.0-4 Drive GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Usage: 632,880 Mi Suspension, 228 in Wheelbase, Air Sliding 5th Asset located in: Humble, TX Wheel, Dual Fuel Tanks Usage: 606,456 Mi 1427A 2015 Freightliner Cascadia 125 6x4 T/A Asset located in: Lake Worth, TX Sleeper Truck Tractor S/N: 3AKJGLD66FSGL9720 1424 2016 Freightliner Cascadia 125 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2014 US EPA Label, Requires Diesel Sleeper Truck Tractor S/N: 1FUJGLD56GLGU2007 Exhaust Fluid, Automated Transmission, 12000 Ib Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27811 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual 295/75R22.5 Rear Tires, Airliner Air Ride Transmission, 12350 lb Front Axle, 40000 lb Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Usage: 843,243 Mi Asset located in: Humble, TX Air Ride Suspension, 230 in Wheelbase, Dual **Fuel Tanks** Usage: 812,953 Mi CHOICE OF 4 - Lot #'s: 1428, 1432, 1433, 1435 Asset located in: Livingston, LA 1425 2016 Freightliner Cascadia 125 6x4 T/A 1428 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJGLDR6GSHD7573 S/N: 1FUJGLD57FLGE5847 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 C/W: Detroit 6 Cylinder 14.8 L Diesel Engine, hp Engine, Requires Diesel Exhaust Fluid, 2014 US EPA Label, Engine Brake, Detroit DT12-Engine Brake, Detroit DT12-DA-1750 12-Speed DA 12-Speed Automated Transmission, 12000 Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Ib Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in Condo Sleeper Cab, Bunk Beds, Cab, Bunk Beds, Aluminum Outer Wheels, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 222 in Wheelbase, Air 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Sliding 5th Wheel, Dual Fuel Tanks Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 669,139 Mi Usage: 834,687 Mi Notes: THIS UNIT IS BEING SOLD WITH A Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX 1426 2016 Freightliner Cascadia 125 6x4 T/A

BONDED TITLE

Sleeper Truck Tractor

S/N: 1FUJGLD50GLHF0201 C/W: Detroit Remanufactured 1/19/23 6 Cylinder Ultra Low Sulfur Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OA-1750 12-Speed Automated Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4HT Drive Axles, 3.23:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes:

Asset located in: Lake Worth, TX

1432 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLD55FSGB5654 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 33891 Engine hrs, Engine Brake, Detroit DT12-OA-1650 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 986,645 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
1433	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor	1438	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
	S/N: 1FUJGLD54FLGE3862 C/W: Detroit 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 724,909 Mi		S/N: 3AKJGLD54FSFK4749 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 22930 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 588,173 Mi
	Asset located in: Midland, TX	-	Asset located in: Midland, TX
1435	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGHDV8FSGL7536	СНОІС	E OF 2 - Lot #'s: 1439, 1442
	C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17707 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 664,589 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1439	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD53FSGM5613 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 724,691 Mi Asset located in: Humble, TX
1436		1442	2014 Freightliner Cascadia 125 6x4 T/A
1430	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG1FSGN2970 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FO-16E313A-MHP ULT 13-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.58:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 921,108 Mi Asset located in: Lake Worth, TX		Sleeper Truck Tractor S/N: 1FUJGLD5XELFM3669 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO- 16913A 13-Speed Manual Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.20:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 733,766 Mi Asset located in: Humble, TX
1437	2015 Freightliner Cascadia 125 6x4 T/A	1	·
	Sleeper Truck Tractor S/N: 3AKJGLD52FSGK9029 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 24896 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 52000 lb GVWR, Air Ride Cab. 72 in High Rise Sleeper Cab. Bunk Beds.		

Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 697,727 Mi

Lot # **Details** Lot # **Details** 1446 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor CHOICE OF 4 - Lot #'s: 1443, 1444, 1445, 1446 S/N: 3AKJGLD52ESFR3485 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22596 Engine hrs, Engine Brake, 1443 2014 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** Eaton Fuller 10-Speed Manual Transmission, S/N: 1FUJGLDV0ELFK3902 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Engine Brake, Eaton Fuller FM-15E310B-LAS Automated Transmission, 13220 lb Front Axle. Ride Suspension, 238 in Wheelbase, Air Sliding 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb 5th Wheel, Headache Rack, Dual Fuel Tanks GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Usage: 899,662 Mi Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 542,197 Mi YOUR LOCAL DMV PRIOR TO BIDDING Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Humble, TX Asset located in: Lake Worth, TX 1446A 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor 1444 2014 Freightliner Cascadia 125 6x4 T/A S/N: 1FUJGLBG8ELBY9400 Sleeper Truck Tractor C/W: Cummins ISX15 450 6 Cylinder 15.0 L Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 23297 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-S/N: 3AKJGLD58ESFK2646 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 27101 Engine hrs, Engine Brake, Eaton Fuller RTOCM-16909A 13-Speed Manual Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Transmission, 12350 lb Front Axle, 34000 lb Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 46350 lb GVWR, 70 in High Rise Aluminum Outer Wheels, 295/75R22.5, Airliner Sleeper Cab, Bunk Beds, Aluminum Outer Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 803,269 Mi Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Asset located in: Lake Worth, TX Usage: 191,299 Mi Asset located in: Humble, TX CHOICE OF 3 - Lot #'s: 1447, 1448, 1449 1445 2014 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** 1447 2013 Freightliner Cascadia 125 6x4 T/A S/N: 3AKJGLD50ESFY3229 Sleeper Truck Tractor C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, S/N: 1FUJGLDR8DLBV8807 24797 Engine hrs, Engine Brake, Detroit DT12-OA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Manual Transmission, Air Ride Cab, 70 in High Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 285/75R24.5

Conditioner, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 816,732 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT Asset located in: Humble, TX Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel

Usage: 1,278,392 Mi

Details Lot # 1448 2013 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** S/N: 1FUJGLBG4DSBZ8339 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A **BONDED TITLE** Asset located in: Lake Worth, TX 1449 2013 Freightliner Cascadia 6x4 T/A Sleeper **Truck Tractor** S/N: 3AKJGLDR7DSBB5155 C/W: 6 Cylinder Diesel 455 hp Engine, 27508.2 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air

Tanks Usage: 799,106 Mi

Notes: ODOMETER DISCREPANCY-PLEASE SEE INSPECTION REPORT DEFICIENCIES

Ride Cab, 60 in High Rise Sleeper Cab, Bunk

Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Beds, Bunk Heater, Aluminum Rear Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in

NOTED

Asset located in: Humble, TX

CHOICE OF 3 - Lot #'s: 1450, 1451, 1452

1450 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR8CSBT4009 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 497.836 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

Lot # Details

1451 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLBG4CSBP1768
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
450 hp Engine, 2011 US EPA Label, Requires
Diesel Exhaust Fluid, Engine Brake, Eaton Fuller
FRO-15210C 10-Speed Manual Transmission,
12000 lb Front Axle, 40000 lb Rears, Meritor
MT-40-14X Drive Axles, 3.55:1 Axle Ratio,
52000 lb GVWR, Air Ride Cab, 72 in High Rise
Sleeper Cab, Bunk Beds, Auxiliary Power Unit,
Aluminum Front Wheels, 295/75R22.5, Airliner
Air Ride Suspension, 230 in Wheelbase, PTO,
Hydraulic Oil Cooler, Air Sliding 5th Wheel, Dual
Fuel Tanks

Usage: 592,035 Mi

Asset located in: Humble, TX

1452 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLBG1CSBM5211 C/W: Cummins ISX 15 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 3.42: 1 Axle Ratio, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 899,518 Mi

Asset located in: Lake Worth, TX

1453 2010 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR0ASAS4603 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 35268 lb Rears, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, 47268 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 836,813 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1454, 1455

1454 2018 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGHDV8JSJX1807 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650-OH 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 815,447 Mi

Details Lot # **Details** Lot # 1455 2018 Freightliner Cascadia 113 6x4 T/A **Sleeper Truck Tractor** CHOICE OF 2 - Lot #'s: 1461, 1462 S/N: 3AKJGHDV9JSJJ2300 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low 1461 2018 Western Star 5700 6x4 T/A Sleeper Truck Sulfur Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Tractor Automated Transmission, 12000 lb Front Axle, S/N: 5KJJBHDR2JLJZ0716 40000 lb Rears, Detroit DA-RT-40.0-4 Drive C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Engine, Requires Diesel Exhaust Fluid, 27535 Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle. Ride Suspension, 209 in Wheelbase, Air Sliding 40009 lb Rears, Detroit DA-RT-40.0-4 Drive 5th Wheel Axles, 2.41:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Usage: 649,665 Mi Asset located in: Midland, TX Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 653,881 Mi CHOICE OF 2 - Lot #'s: 1457, 1458 Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 2016 Freightliner Cascadia 113 6x4 T/A 1457 Asset located in: Humble, TX Sleeper Truck Tractor 1462 2017 Western Star 5700 XE 6x4 T/A Sleeper S/N: 1FUJGHDV9GLGS0046 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 Truck Tractor hp Engine, 2015 US EPA Label, CARB S/N: 5KJJBHDRXHLJE5495 Compliant, Requires Diesel Exhaust Fluid, C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2017 US EPA Label, Requires Diesel Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb Exhaust Fluid, 27690 Engine hrs, Retarder, Detroit DT12-OA-1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Rears, 3.23:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 54 in Mid Roof Sleeper Cab, 11R22.5, Usage: 762,092 Mi Airliner Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,491 Mi Asset located in: Humble, TX 1458 2016 Freightliner Cascadia 113 6x4 T/A Asset located in: Lake Worth, TX **Sleeper Truck Tractor** 1463 2020 Volvo VNR400 6x4 T/A Sleeper Truck S/N: 1FUJGHDV2GLGS0048 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-Tractor S/N: 4V4WC9DH8LN270434 C/W: Volvo D11 6 Cylinder 10.8 L Diesel 425 hp 16210C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.31:1 Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10991 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 Transmission, 13200 lb Front Axle, 40000 lb /75R22.5, Airliner Air Ŕide Suspension, 225 in Rears, 53200 lb GVWR, Air Ride Cab, 42 in Flat Wheelbase, Hydraulic Oil Cooler, Air Sliding 5th Top Sleeper Cab, Aluminum Wheels, 295 Wheel, Blower, Dual Fuel Tanks /75R22.5, Volvo Air Ride Suspension, 197 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: 634,517 Mi Asset located in: Humble, TX Tanks Usage: 304,892 Mi 1459 2014 Freightliner Cascadia 113 6x4 T/A Notes: DEFICIENCIES NOTED - PLEASE SEE Sleeper Truck Tractor THE INSPECTION REPORT S/N: 3AKJGHDV1ESFN7414 Asset located in: Humble, TX C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2013 US EPA Label, CARB 1464 2018 Volvo VNL300 6x4 T/A Sleeper Truck

Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12300 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, Air Assist Front Suspension, Airliner 4-Bag Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Asset located in: Midland, TX

Tractor

S/N: 4V4NC9EH1JN899041 C/W: Volvo D13M425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12-Speed Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 568,767 Mi

			Page 137 of 574
Lot #	Details	Lot #	Details
1466	2017 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH4HN971537 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 838,421 Mi Asset located in: Lake Worth, TX	1470	2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TH2FN912681 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 42 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 480,143 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 480,143, TITLE SHOWS 485,418; THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1468	2017 Volvo VNL630 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EG2HN990322 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 405 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612D 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 50350 lb GVWR, 61 in Mid Roof Sleeper Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 645,246 Mi Asset located in: Lake Worth, TX		
1469	Truck Tractor S/N: 4V4NC9EJ3GN946212 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 500 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 61 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Volvo Air Ride Suspension, 136 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3FN916526 C/W: Volvo D13J425 6 Cylinder 12.8 L 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 763,466 Mi Asset located in: Lake Worth, TX
		1473	2012 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH0CN543487 C/W: Volvo D13H425 6 Cylinder 12.8 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 3279 Engine hrs, Volvo AT02612D Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 214 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 937,793 Mi

Details Lot# **Details** Lot # 1473A 2012 Volvo VNL64T 6x4 T/A Sleeper Truck 1476B 2018 International LT625 6x4 T/A Sleeper **Tractor Truck Tractor** S/N: 3HSDZAPR9JN326333 S/N: 4V4NC9EJ9CN542468 C/W: Volvo D13H475 6 Cylinder 12.8 L Diesel C/W: Cummins X15 15.0 L Diesel 450 hp 475 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 5946 Engine hrs, Engine Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14594 Engine hrs, Engine Brake, Brake, Eaton Fuller FRO-16210C 10-Speed Eaton Fuller 10-Speed Manual Transmission, Manual Transmission, 12350 lb Front Axle, 13220 lb Front Axle, 40000 lb Rears, 53220 lb 38000 lb Rears, Meritor MT-40-14X Drive Axles, GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, International IROS Air Ride Suspension, 223 in Wheelbase, 3.42:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 61 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 238 Air Sliding 5th Wheel, Dual Fuel Tanks in Wheelbase, PTO, Hydraulic Oil Cooler, Air Usage: 519,692 Mi Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX Usage: 567,803 Mi Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1478, 1480 1473B 2017 International Lonestar 6x4 T/A Sleeper **Truck Tractor** 1478 S/N: 3HSCXAPRXHN752298 2017 International Prostar+ 122 6x4 T/A C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 475 hp Engine, 2016 US EPA Label, Requires Sleeper Truck Tractor S/N: 3HSDJSNR2HN447862 Diesel Exhaust Fluid, 22842 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Exhaust Fluid, 19396 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Beds, 295/75R22.5, Air Ride Suspension, 247 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, Usage: 736,300 Mi 445/50R22.5 Super Singles Rear Tires, Air Ride **Notes**: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks CANNOT BE DRIVEN. TEMP TAGS WILL NOT Usage: 542,861 Mi BE ISSUED Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1480 2017 International ProStar 6x4 T/A Sleeper **Truck Tractor** CHOICE OF 1 - Lot #'s: 1476 S/N: 3HSDJAPR1HN204325 C/W: Cummins ISX 450ST 6 Cylinder 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 1476 2018 International LT625 6x4 T/A Sleeper Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb **Truck Tractor** S/N: 3HSDZAPR2JN247098 GVWR, Air Ride Cab, 73 in Mid Roof Sleeper C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Cab, Aluminum Outer Wheels, 11R22.5, 267 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Diesel Exhaust Fluid, 11639 Engine hrs, Engine **Tanks** Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Usage: 505,833 Mi Ride Cab, 56 in Mid Roof Sleeper Cab, Asset located in: Humble, TX Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 429,685 Mi CHOICE OF 5 - Lot #'s: 1481, 1482, 1483, 1484, 1485 Asset located in: Lake Worth, TX 1481 2016 International Prostar 6x2 T/A Sleeper 1476A 2018 International LT625 6x4 T/A Sleeper **Truck Tractor** Truck Tractor

S/N: 3HSDZAPR4JN233073 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 16277 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 507,109 Mi

Asset located in: Humble, TX

S/N: 3HSDJSNR0GN058653 C/W: International N13 6 Cylinder 12.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Dual Fuel Tanks Usage: 842,762 Mi

Details Lot # **Details** Lot # 1482 2016 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor CHOICE OF 2 - Lot #'s: 1486, 1487 S/N: 3HSDJAPR2GN428556 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel 1486 2014 International Prostar+ 122 6x4 T/A Exhaust Fluid, 16496 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, Sleeper Truck Tractor S/N: 3HSDJAPR7EN796955 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17185 Engine hrs, Engine 72 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks Brake, Automated Transmission, 12350 lb Usage: 614,573 Mi Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Asset located in: Lake Worth, TX Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, 1483 2015 International ProStar 6x4 T/A Sleeper **Truck Tractor** Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks S/N: 3HSDJAPR3FN676250 C/W: Cummins ISX15 15 L Engine, 2014 US Usage: 658,173 Mi EPA Label, Requires Diesel Exhaust Fluid, Notes: DEFICIENCIES NOTED - PLEASE SEE 19816 Engine hrs, Engine Brake, 9-Speed THE INSPECTION REPORT Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Asset located in: Humble, TX 73 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th 1487 2014 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR7EN759578 Wheel, Dual Fuel Tanks C/W: International MaxxForce 13 6 Cylinder Usage: 654,586 Hr 12.4 L Diesel 450 hp Engine, 2013 US EPA Notes: THIS UNIT RUNS BUT MAY HAVE Label, Requires Diesel Exhaust Fluid, 17281 DEFICIENCIES IN ITS POLLUTION CONTROL Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 549,311 Mi Asset located in: Lake Worth, TX PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX CHOICE OF 2 - Lot #'s: 1490, 1491 1484 2015 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor 1490 2012 International Prostar 6x4 T/A Sleeper S/N: 3HSDJAPR9FN526675 **Truck Tractor** C/W: Cummins ISX 400ST 6 Cylinder Diesel S/N: 3HSDJSJR7CN094078 218 hp Engine, 2014 US EPA Label, CARB C/W: 6 Cylinder Diesel Engine, 34209 Engine Compliant, Requires Diesel Exhaust Fluid, hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Engine Brake, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 275 Cab, 56 in Mid Roof Sleeper Cab, 11R22.5, Air /80R22.5, 252 in Wheelbase, Air Sliding 5th Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Wheel, Dual Fuel Tanks Usage: 676,438 Mi Usage: 689,264 Mi Asset located in: Humble, TX Notes: DEFICIENCIES NOTED - PLEASE SEE 1485 2015 International Prostar+ 122 6x4 T/A THE INSPECTION REPORT Sleeper Truck Tractor Asset located in: Humble, TX S/N: 3HSDJAPR3FN668830 C/W: Cummins ISX 400ST 6 Cylinder Diesel 218 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 19195 Engine hrs, Engine Brake, 13200 lb Front

This catalog was created at December 11, 2024 01:25:48 AM GMT. Please check our website for the most accurate and up-to-date information.

Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, 252 in

Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Tanks

Usage: 658,953 Mi

Lot #	Details	Lot #	Details
1491	2012 International Prostar 6x4 T/A Sleeper Truck Tractor	1495	2000 Peterbilt 379 6x4 T/A Sleeper Truck Tractor
	S/N: 3HSDJSJR1CN094075 C/W: 6 Cylinder Diesel Engine, 27815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 798,884 Mi		S/N: 1XP5DR9X3YD506553 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 450 hp Engine, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 58 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Leaf 4-Bag Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 455,326 Mi
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes : THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE
	Asset located in: Humble, TX		Asset located in: Humble, TX
1492	2005 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X55R076276 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, 13-Speed Manual Transmission, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 106,655 Mi Asset located in: Lake Worth, TX	1497	2005 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDB9X95J099229 C/W: Cat C15 6 Cylinder 15 L Diesel 475 hp Engine, 30565 Engine hrs, Engine Brake, Eaton Fuller 10-Speed hybrid, automatic with clutch Transmission, 40000 lb Rears, Dana DSP40 Drive Axles, 3.36:1 Axle Ratio, 62 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, 4- Bag Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 161,706 Mi
1493	2007 Peterbilt 379 6x4 T/A Sleeper Truck		Asset located in: Lake Worth, TX
	Tractor S/N: 1XP5DB9X87N667738 C/W: Cat C15 6 Cylinder Diesel 550 hp Engine, 35138.1 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, COLEMAN MACK Electric Sleeper Air Conditioner, 3cyl KUBOTA Auxiliary Power Unit, 315/80R22.5 Front Tires, 285/75R24.5 Rear Tires, Low Air Leaf Air Ride Suspension, 312 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, Custom Condo Sleeper Equipped with Shower/Toilet Combo, Convection Oven and Refrigerator	1498	1996 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDR9XXTR729761 C/W: Detroit/series60 6 Cylinder 12.7 L Diesel 470 hp Engine, 1996 US EPA Label, Engine Brake, Manual Transmission, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 258 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 310,988 Mi Asset located in: Lake Worth, TX 2005 Freightliner Coronado 132 6x4 T/A
	Usage: 1,479,428 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		Sleeper Truck Tractor S/N: 1FUJCRCK65PU90416 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2004 US EPA Label, 5051 Engine hrs, Engine Brake, Eaton Fuller RTLO- 16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT 40-145 Drive Axles, 3.58:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5, Air Assist Front Suspension, Airliner Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,885,684 Mi Asset located in: Lake Worth, TX
1494	2003 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DB9X43D802164 C/W: Cat C15 6 Cylinder 14.6 L Diesel 475 hp Engine, 2001 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Aluminum Wheels, 285/75R24.5, Low Air Leaf Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 93,811 Mi		

Lot #	Details	Lot #	Details
1499A	2007 Western Star 4900SA 6x4 T/A Sleeper Truck Tractor S/N: 5KJJALCK77PX38561 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2006 US EPA Label, 24734 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 4.11:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 34 in Flat Top Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 210 in Wheelbase, PTO, Dual Fuel Tanks Usage: 258,812 Mi Asset located in: Lake Worth, TX	1503	2005 Kenworth T2000 6x4 T/A Sleeper Truck Tractor S/N: 1XKTDB9X15J058198 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, Spicer DSP40 Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
1500	2006 International 9400L 6x4 T/A Sleeper		
	Truck Tractor S/N: 2HSCNSCR46C195887 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 72 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,001,440 Mi Asset located in: Lake Worth, TX	1505	2006 Mack CXN613 8x4 Tri/A Sleeper Truck Tractor S/N: 1M1AK07YX6N011822 C/W: Mack 6 Cylinder Diesel Engine, 2005 US EPA Label, 23598 Engine hrs, Engine Brake, Mack 18-Speed Manual Transmission, 13220 Ib Front Axle, 46000 Ib Rears, 59220 Ib GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, 233 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: 414,912 Mi Asset located in: Lake Worth, TX
1501	2006 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7DB9X16D896274 C/W: Cat C15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, Low Air Leaf Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,814,828 Mi Asset located in: Lake Worth, TX		
		1506	2006 Mack CXN613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AK06Y86N014932 C/W: Mack AC 6 Cylinder Diesel 380 hp Engine, 2005 US EPA Label, 23678 Engine hrs, Engine Brake, Mack T310 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Flat Top Sleeper Cab, Bunk Heater, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 214 in Wheelbase, PTO, Headache Rack Usage: 549,542 Mi Asset located in: Humble, TX
1502	2007 Kenworth T600 6x4 T/A Sleeper Truck Tractor S/N: 1XKADB9X57J158461 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller RTLOC16909AT2 Manual Transmission, Dana DSP40 Drive Axles, 3.55:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,098,883 Mi Asset located in: Lake Worth, TX		
		1507	2005 Mack CX613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AE05Y75N021491 C/W: Mack 6 Cylinder Diesel Engine, 2004 US EPA Label, 15393 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 211 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 517,922 Hr Asset located in: Lake Worth, TX

Details Lot# **Details** Lot # 1508 1512A 2001 Freightliner Columbia 120 6x4 T/A 2008 International ProStar Premium 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJA6CG81LJ21493 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, 2000 US EPA Label, 21047 S/N: 2HSCUAPR48C686955 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, Engine hrs, Engine Brake, Meritor MO-15G10C-12350 lb Front Axle, 40000 lb Rears, 52350 lb M15 10-Speed Manual Transmission, 12000 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Cab, Aluminum Outer Wheels, 295/75R22.5, Air Air Ride Cab, 60 in Flat Top Sleeper Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 218 in Wheelbase, PTO, Dual Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,049,713 Mi Fuel Tanks Asset located in: Lake Worth, TX Usage: 379,721 Mi 1509 2006 International 9400i 6x4 T/A Sleeper Asset located in: Lake Worth, TX Truck Tractor 1514 2001 Freightliner ST120 6x4 T/A Sleeper Truck S/N: 2HSCNAPR16C228106 C/W: Cummins ISX 14.9 L Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air S/N: 1FUJBBBD91LH91702 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 435 hp Engine, 2000 US EPA Label, Meritor MO-Ride Cab, 51 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride 14G10A-M14 10-Speed Manual Transmission, Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,412,255 Mi 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, Asset located in: Lake Worth, TX 11R22.5 Front Tires, 295/75R22.5 Rear Tires, 1510 2009 Freightliner Columbia 120 6x4 T/A Airliner Suspension, 226 in Wheelbase, Dual **Fuel Tanks Sleeper Truck Tractor** Usage: 854,362 Mi S/N: 1FUJA6CK19LAD2685 Asset located in: Lake Worth, TX C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, Engine Brake, Eaton Fuller RTO-16910B-DM 10-Speed Automated 1515 2000 Freightliner FLD 120 6x4 T/A Sleeper **Truck Tractor** Transmission, 12000 lb Front Axle, 40000 lb Rears, Dana DS404 Drive Axles, 3.55:1 Axle S/N: 1FUPCSEB4YDF85578 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, 1999 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Wheel, Dual Fuel Tanks Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Usage: 587,873 Mi Asset located in: Humble, TX 1511 2007 Freightliner Century Class CST120 6x4 T Wheel, Dual Fuel Tanks Usage: 972,743 Mi /A Sleeper Truck Tractor Asset located in: Midland, TX S/N: 1FUJBBAV37LX21774 C/W: Cat C15 6 Cylinder Diesel Engine, 18993 1516 1995 Freightliner FLD 120 6x4 T/A Sleeper Engine hrs, Engine Brake, Eaton Fuller Manual Truck Tractor Transmission, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Áluminum Outer Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Dual S/N: 1FUPDZYB7SH718722 C/W: Detroit 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual **Fuel Tanks** Usage: 955,175 Mi Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Asset located in: Humble, TX Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R24.5, Air Ride Suspension, 246 in 1512 2006 Freightliner Columbia 120 6x4 T/A Wheelbase, Air Sliding 5th Wheel, Dual Fuel Sleeper Truck Tractor **Tanks** S/N: 1FUJA6CK86LV66960 Usage: 687,717 Mi C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2005 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Asset located in: Humble, TX Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, 295/75R22.5, Airliner Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 1,027,381 Mi

Lot #	Details	Lot #	Details	
1517	1996 Freightliner USF-E1 6x4 T/A Sleeper Truck Tractor S/N: 1FUYDDYBXTP613588 C/W: 6 Cylinder Diesel Engine, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 285/75R24.5 Front Tires, 11R24. 5 Rear Tires, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks	1522	2019 Ottawa 4x2 Spotter Truck S/N: 4LMSB2114KL031788 C/W: Cummins QSB4.5 4 Cylinder 5.4 L Diesel 173 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 24000 lb Rears, Steel, 11R22.5, 115 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 10,626 Mi Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	1523	2017 Ottawa T2 4x2 Spotter Truck	
	CHOICE OF 2 - Lot #'s: 1518, 1519		S/N: 343984 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, 7207 Engine hrs, Allison Transmission, Steel, 11R22.5, Spring Suspension, 116 in Wheelbase,	
1518	2023 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBF5111PL041353 C/W: Cummins 6 Cylinder Diesel Engine, 2063 Engine hrs, Allison Automatic Transmission, 12000 b Front Axle, 30000 lb Rears, 36000 lb		Hydraulic Lift 5th Wheel Usage: 30,805 Mi Notes : NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in : Lake Worth, TX	
	GVWR, 295/75R22.5, 130 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 6,329 Mi Asset located in : Lake Worth, TX	1524 2015 Ottawa Sabre 5 4x2 Spotter S/N: 335984 C/W: Cummins QSB 6.7 L 165 hp I US EPA Label, Allison Transmissio /75R22.5, 118 in Wheelbase, PTO, Lift 5th Wheel Usage: Not Available	C/W: Cummins QSB 6.7 L 165 hp Engine, 2014	
1519	2023 Capacity 4x2 Spotter Truck S/N: 4LMBF5119PL041360 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 11R22.5, 132 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Asset located in: Humble, TX		/75R22.5, 118 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes : TITLE IS BRANDED AS NOT ACTUAL MILEAGE	
1520	· · · · · · · · · · · · · · · · · · ·		CHOICE OF 4 - Lot #'s: 1525, 1526, 1527, 1529	
	S/N: 4LMBF2115ML029314 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, 116 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 30,689 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	1525	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2110BL022565 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2014 US EPA Label, Allison Automatic Transmission, 12000 lb Front Axle, 23000 lb Rears, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	
CHOICE OF 2 - Lot #'s: 1521, 1522		1526	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2112BL022566 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel	
1521	2019 Ottawa 6x4 Spotter Truck S/N: 4LMDB7136KL027975 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 173 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5750 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Steel, 11R22.5 Front Tires, 255/70R22.5 Rear Tires, 154 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 8,516 Mi	16 Tr Hy Us N i Ol	160 hp Engine, 2014 US EPA Label, Automati Transmission, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BII OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
1527	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2113BL022611 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2021 US EPA Label, 2649 Engine hrs, Allison Automatic Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 87,798 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL	1534	2012 Sauber 1570-B Portable Tensioner S/N: 1F9UZ1313CV048037 C/W: Kawasaki FD731V 2 Cylinder Gasoline Engine Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	1535	2008 TSE DPT40B T/A Tensioner S/N: 1T92C15238S268017 C/W: 2007 US EPA Label, John Deere 4024TF270C 36 kW 2.4 L Diesel Engine Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
1529	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR211XBL022573 C/W: Cummins 6.7 L Diesel Engine, Allison Automatic Transmission, 275/80R22.5, 112 in		
	Wheelbase, Hydraulic Lift 5th Wheel Usage: 25,696 Hr Notes : NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in : Lake Worth, TX		2003 Sherman Reily T/A Tensioner S/N: 123WM212831T16188 C/W: Honda 2 Cylinder Gasoline Engine Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
1530	2008 Ottawa TY30 4x2 Spotter Truck S/N: 318992 C/W: Cummins QSB 6 Cylinder 6.7 L Diesel Engine, Allison Automatic Transmission, 275 /80R22.5, 111 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		2011 Wagner-Smith T-5DP-120 Hydraulic Cable Puller S/N: 1W9DP4321BA161085 C/W: 2010 US EPA Label, John Deere 4 Cylinder Diesel Engine, (5) Reels; EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
1531	2006 Ottawa TY30 4x2 Spotter Truck S/N: 314014 C/W: Cummins USB 6 Cylinder 5.9 L 155 hp Engine, Automatic Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 8,254 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX	1538	Altec AT235P 35 ft on 2015 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GT5FED59378 C/W: Ford 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 165 in Wheelbase, 300 lb Capacity, Front Mounted, One-Person Articulating-Telescopic Boom, Utility Body, 11 ft x 94 in Bed Usage: 75,582 Mi
1532	CRC PB Pipe Bending Machine S/N: 20-267 C/W: Bends 6 in to 20 in Pipe, Tow Behind, Winch, Kubota Diesel Engine Usage: 1,103 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

1539 Tornado F4SL on 2015 Western Star 4900 8x6 Vacuum Excavator Truck

Details

Lot #

S/N: 5KKPALD10FPGA1440
C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600
hp Engine, 2014 US EPA Label, Requires Diesel
Exhaust Fluid, 35902 Engine hrs, Engine Brake,
Eaton Fuller 18-Speed Manual Transmission,
Triple Differential Locks, 20000 lb Front Axle,
57000 lb Rears, 4.30:1 Axle Ratio, 77000 lb
GVWR, Air Ride Cab, Aluminum Wheels, 445
/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual
Steering Boxes, Double Frame, Airliner
Suspension, 303 in Wheelbase, Steel 2150 gal
Debris Tank, Hydraulic Tailgate Locks,
Telescopic Boom, 8 in Suction Hose, Cat
Hydraulic Driven Pump, Robuschi Blower w/
5642 hrs, Hotshot Boiler, Cordless Remote
Control, 77000 lb GVWR
Usage: 10,861 Km

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

1540 Foremost on 2013 Western Star 4900 8x6 Vacuum Excavator Truck

S/N: 5KKPALDR6DPBH7992
C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 530
hp Engine, Requires Diesel Exhaust Fluid, 8104
Engine hrs, Engine Brake, Eaton Fuller RTLO18918B Manual Transmission, Double
Differential Locks, 20000 lb Front Axle, 56700
lb Rears, Meritor RZ-166 Drive Axles, 4.56:1
Axle Ratio, 76700 lb GVWR, Air Ride Cab,
Aluminum Front Wheels, 445/65R22.5 Front
Tires, 11R24.5 Rear Tires, Dual Steering Boxes,
Double Frame, Airliner Air Ride Suspension,
318 in Wheelbase, PTO, Hydraulic Oil Cooler,
Steel Debris Tank, Hydraulic Lift Tailgate,
Hydraulic Tailgate Locks, Telescopic Boom, 8
in Suction Hose, Cat Hydraulic Driven Pump,
Robuschi Blower, Cordless Remote Control,
76700 lb GVWR

Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX

Usage: 105,864 Mi

1540A Vactor Guzzler on 2014 Kenworth T800 8x4 Vacuum Excavator Truck

S/N: 1NKDX4EX4EJ386464
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
485 hp Engine, 2012 US EPA Label, Requires
Diesel Exhaust Fluid, 19129 Engine hrs, Engine
Brake, Eaton Fuller FRO-16210C 10-Speed
Manual Transmission, 20000 lb Front Axle,
58350 lb Rears, 4.10:1 Axle Ratio, 78350 lb
GVWR, Air Ride Cab, Aluminum Outer Wheels,
425/65R22.5 Front Tires, 11R22.5 Rear Tires,
Steerable Air Lift Pusher Axle, Dual Steering
Boxes, Double Frame, Hendrickson RT/RTE
Series Suspension, 307 in Wheelbase, PTO,
Steel Debris Tank, Hoist, Fresh Water Tank,
Hydraulic Lift Tailgate, Hydraulic Tailgate
Locks, Telescopic Boom, 8 in Suction Hose,
Cat Hydraulic Driven Pump, Ingersoll-Rand
SIAV 8702 Blower w/ 13367 hrs, 49786 Boiler,
78350 lb GVWR

Usage: 203,514 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot # Details

1540B 2013 Kenworth T800 8x4 Vacuum Excavator Truck

S/N: 1NKDX4EX6DJ352704
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
485 hp Engine, 2012 US EPA Label, Requires
Diesel Exhaust Fluid, 19700 Engine hrs, Engine
Brake, Eaton Fuller FRO-16210C 10-Speed
Manual Transmission, 20000 lb Front Axle,
58350 lb Rears, 4.10:1 Axle Ratio, 78350 lb
GVWR, Air Ride Cab, Aluminum Outer Wheels,
425/65R22.5 Front Tires, 11R22.5 Rear Tires,
Steerable Air Lift Pusher Axle, Dual Steering
Boxes, Double Frame, Hendrickson RT/RTE
Series Suspension, 307 in Wheelbase, PTO,
Steel Debris Tank, Hoist, Fresh Water Tank,
Hydraulic Lift Tailgate, Hydraulic Tailgate
Locks, Telescopic Boom, 8 in Suction Hose,
Cat Hydraulic Driven Pump, Ingersoll-Rand
SIAV 8702 Blower w/ 3004 hrs, 78350 lb GVWR
Usage: 251,604 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

1540C 2013 Kenworth T800 8x4 Vacuum Excavator Truck

S/N: 1NKDX4EX3DJ334497
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21666 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 20000 lb Front Axle, 58350 lb Rears, 4.10:1 Axle Ratio, 78350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Suspension, 307 in Wheelbase, PTO, Steel Debris Tank, Hoist, Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Telescopic Boom, 8 in Suction Hose, Cat Hydraulic Driven Pump, Ingersoll-Rand SIAV 8702 Blower w/ 13716 hrs, Water ProTech 47390L Boiler, 78350 lb GVWR Usage: 262,312 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

1540D 2013 Kenworth T800 8x4 Vacuum Excavator Truck

S/N: 1NKDX4EX1DJ334496
C/W: Cummins ISX 6 Cylinder 15.0 L Diesel
Engine, Requires Diesel Exhaust Fluid, 1616
Engine hrs, Eaton Fuller 10-Speed Manual
Transmission, 20000 lb Front Axle, 46000 lb
Rears, 78350 lb GVWR, Aluminum Outer
Wheels, 425/65R22.5 Front Tires, 11R22.5
Rear Tires, Steerable Air Lift Pusher Axle, Dual
Steering Boxes, Double Frame, Hendrickson RT
/RTE Series Spring over Walking Beam
Suspension, 305 in Wheelbase, PTO, Steel
Debris Tank, Hydraulic Lift Tailgate, Hydraulic
Tailgate Locks, 12 ft Boom, 8 in Suction Hose,
Cat PTO Driven Pump, Blower w/ 11961 hrs,
Boiler, 78350 lb GVWR

Usage: 222,254 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Details Lot # **Details** Lot # 1542 Gap-Vac on 2002 Volvo VHD 6x4 Vacuum **Excavator Truck** CHOICE OF 2 - Lot #'s: 1545, 1546 S/N: 4V5KC9UF92N321981 C/W: Cummins ISM 10.8 L Diesel 325 hp 1545 2013 Mack GU713 3800 gal 6x4 Vacuum Engine, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Tanker Truck Rears, 64000 lb GVWR, 385/65R22.5 Front S/N: 1M2AX07C0DM014703 Tires, 11R22.5 Rear Tires, Double Frame, C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Spring over Walking Beam Suspension, 254 in Wheelbase, PTO, Steel Debris Tank, Front Hose Exhaust Fluid, 27175 Engine hrs, Engine Brake, Reel, Hydraulic Lift Tailgate, Hydraulic Tailgate Eaton Fuller 18-Speed Manual Transmission, Locks, PTO Driven Pump, 64000 lb GVWR Differential Lock, 38000 lb GVWR, Air Ride Cab, Usage: Not Available Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Notes: DEFICIENCIES NOTED - PLEASE SEE Steering Boxes, Double Frame, Air Ride THE INSPECTION REPORT; RITCHIE-BROS-Suspension, 268 in Wheelbase, Aluminum ENERGY 3800 gal Debris Tank, Non Code Code, Manual Asset located in: Humble, TX Tailgate Locks, PTO Driven Pump, 38000 lb 1543 Vactor 2100 Series on 2002 Sterling L9500 6x4 **GVWR** Usage: 402,799 Mi Vacuum Excavator Truck Notes: RITCHIE-BROS-ENERGY S/N: 2FZHAZAS02AK42561 C/W: Cat C12 6 Cylinder Diesel 355 hp Engine, Asset located in: Lake Worth, TX 8023 Engine hrs, Éngine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 1546 2012 Mack GU713 8x4 Vacuum Tanker Truck 46000 lb Rears, 66000 lb GVWR, Steel, 425 /65R22.5, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Spring over S/N: 1M2AX07C8CM012213 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Walking Beam Suspension, 252 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Fresh Transmission, 20000 lb Front Axle, 44000 lb Water Tank, Boom, 8 in Suction Hose, PTO Rears, 64000 lb GVWR, Air Ride Cab, 425 Driven Pump, Roots 824RSCV18 Blower, 66000 /65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Ib GVWR Steering Boxes, Double Frame, Air Ride Suspension, 272 in Wheelbase, Aluminum Usage: 134,573 Mi Debris Tank, 64000 lb GVWR Notes: RITCHIE-BROS-ENERGY Usage: 469,818 Mi Asset located in: Lake Worth, TX Notes: RITCHIE-BROS-ENERGY 1544 2001 Ford F-550 XL 4x2 Vacuum Excavator Asset located in: Lake Worth, TX Truck 1547 2014 International 7600 6x4 Vacuum Tanker S/N: 1FDAF56F71EC85002 Truck C/W: Ford 7.3 V8 7.3 L Diesel Engine, 978 Engine hrs, Automatic Transmission, 6000 lb S/N: 1HTGSSNTXEH029640 C/W: 6 Cylinder Diesel Engine, Engine Brake,

Front Axle, 13500 lb Rears, 17500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 201 in Wheelbase, 100 gal Debris Tank, Rear Hose Reel, 4 in Suction Hose, 17500 lb GVWR Usage: 233,622 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Eaton Fuller Manual Transmission, 18000 lb Front Axle, 46000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Air Ride Suspension, 228 in Wheelbase, 2000 gal Debris Tank, 64000 lb GVWR Usage: 240,009 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

1548 2013 International 7400 4x2 Pressure Truck

S/N: 1HTWCAZN2DJ200547 C/W: 6 Cylinder Diesel Engine, Eaton Fuller 8LL Manual Transmission, 10000 lb Front Axle, 23000 lb Rears, 33000 lb GVWR, Air Ride Cab,

295/75R22.5, Spring Suspension, 222 in Wheelbase, PTO, weatherford Triplex Pump, Fiberglass Reinforced Plastic Tank

Usage: 221,859 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1549A 1550	2008 Mack CHU613 8x4 Winch Truck S/N: 1M2AN07Y08N003038 C/W: Mack MP8 6 Cylinder 12.8 L 338 hp Engine, 2007 US EPA Label, 8203 Engine hrs, Mack Manual Transmission, Air Ride Cab, 11R24.5, Air Lift Pusher Axle, Camelback Spring Suspension, 252 in Wheelbase, PTO, Tail Roll, Tulsa Winch RN65WM-RFO 65000 lb Winch Usage: 168,363 Mi Notes: LOCATED-IN-FORT-WORTH-TX RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2000 International 9900 6x4 Winch Truck	1554	Texoma 500-15 on 2004 International 7400 6x4 Pressure Digger S/N: 1HTWGADT34J083149 C/W: Detroit 4 Cylinder Upper Engine, Winch, Straight Down Outriggers, Rear Outriggers, Bumper Mounted Winch, International 6 Cylinder Diesel Engine, 10013 Engine hrs, Allison Automatic Transmission, Differential Lock, 16000 lb Front Axle, 53120 lb Rears, 56000 lb GVWR, Air Ride Cab, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 205 in Wheelbase Usage: 91,448 Mi Notes: RITCHIE-BROS-ENERGY
	S/N: 2HSFTAER6YC050198 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 435 hp Engine, Eaton Fuller 8LL Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Steel, 11R22.5, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, Tail Roll, Tulsa Winch Usage: 540,116 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Texoma 3301500 on 1993 Mack RD690S 4x2 Drill Truck S/N: 1M2P264Y0PM013308 C/W: Cummins 4BTA3.9-C 3.9 L 4 Cylinder Upper Engine, Mack EM7 6 Cylinder Diesel 300 hp Engine, 1993 US EPA Label, 16469 Engine hrs, Eaton Fuller 9-Speed Manual Transmission, Steel, 11R24.5, Camelback Spring Suspension, 212 in Wheelbase
1551	1995 International 9200 6x4 Winch Truck S/N: 2HSFMAHR6SC052503 C/W: Cummins 6 Cylinder 10.8 L Diesel 370 hp Engine, 1995 US EPA Label, Spicer 10-Speed Manual Transmission, 295/75R22.5, Air Ride Suspension, 190 in Wheelbase, Tulsa Winch, Air sliding fifth wheel Usage: 691,448 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		Drill Truck S/N: 1HTLKTVR9FHA26144 C/W: Deutz TCD2012L042V 4.0 L 4 Upper Engine, Winch, Out and Down Rear Outriggers, 6 Cylinder Diesel E
1551A	2012 Kenworth T300 6x4 Wireline Logging Truck S/N: 2NKHLN9X6CM298275 C/W: Cummins ISC 6 Cylinder Diesel Engine, 6734 Engine hrs, Engine Brake, Eaton Fuller FRO-11210C 10-Speed Manual Transmission, Double Differential Locks, 14600 lb Front Axle, 40000 lb Rears, Meritor RT-41-145 Drive Axles, 4.63:1 Axle Ratio, 54600 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 249 in Wheelbase, PTO Usage: 57,977 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		11R22.5, Double Frame, Hendrickson RT/RTE Series Suspension, 206 in Wheelbase Usage: 164,298 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
		1556	Texoma 270 on 1984 International 1954 4x2 Drill Truck S/N: 1HTLDUXP6EHA31702 C/W: John Deere 4045DF 6.8 L 4 Cylinder Upper Engine, Straight Down Outriggers, Rear Outriggers, 6 Cylinder Diesel Engine, Manual Transmission, 11R22.5, Spring Suspension, 170 in Wheelbase Usage: 280,022 Mi Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
		1557	2019 Thunder Vermeer R250C Mud Mixing System S/N: 56ZL2UZ20KP000069 C/W: (4) Shale Shakers, John Deere 4045 4 Cylinder 4.5 L Diesel Engine Usage: 1,607 Hr Notes: RITCHIE-BROS-ENERGY

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1575	Star 185K on 2008 Gefco Star 185K 10x4 Twin- Steer Drill Truck S/N: 907835 C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder 14 L Diesel 665 hp Engine, 2007 US EPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 44000 lb Front Axle, 74240 lb Rears, 118240 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 8,461 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1579	(Rig#24) 28 ft x 16 ft x 46 ft 9 in Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX (Rig#24) 10 ft x 32 ft Doghouse S/N: Not Available C/W: knowledge box, bench storage, lockers, parts bins, fluorescent lighting, skidded;; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available
1576	Star 150K on 2006 Gefco Star 150K 10x4 Twin-		Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
	Steer Drill Truck S/N: 907730 C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder 14.0 L Diesel 665 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 44000 lb Front Axle, 54240 lb Rears, 98240 lb GVWR, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 3,356 Hr Notes: RITCHIE-BROS-ENERGY; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Cedar Bluff, VA	1581	(Rig#24) 8 ft x 31 ft Mud House S/N: Not Available C/W: shelving, misc rig parts, skidded, Parts /Change House, Bench Storage, Parts Room; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
		1582	(Rig#24) Quantity of (2) 10 ft x 33 ft 500 bbl Water Tank S/N: Not Available C/W: cent pump, ladder, skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC
1577	Star 150 on 2004 Gefco Star 150K 10x4 Twin- Steer Drill Truck S/N: 907612		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
	C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 42000 lb Front Axle, 74240 lb Rears, 116240 lb GVWR, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 294 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1583	(Rig#24) 3-Pit Mud System Mud Tank S/N: Not Available C/W: shopbuilt 8'W x 6'h x 20'L 220-BBL premix tank mud agitator, shopbuilt 8'W x 6'H x 30'L 206-BBL suction tank mud agitators, Shopbuilt 8'W x 6'H x 30'L 206-BBL shaker tank, Vortex Orbital 3000M single screen linear motion shale shaker, all skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
1578	(Rig#24) Lee C Moore 133 ft Cantilever Mast S/N: T1728 C/W: 470,000 Lb Static Hook Load, Crown Block, w/ Sheave Cluster, Fastline Sheave, Racking Board, Tong Counter Weights, Ladder, Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, qty 4 (2) sets of 40"H x 30'L triangular pipe racks, block hook combo, drill line spool; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1584	(Rig#24) Fuel Tank & Parts House S/N: Not Available C/W: 7'W x 12'L round top flat steel parts house w/ 4'L covered porch extension, shelving fluorescent lighting skidded, 8'W x 8'H x 21'L 10,000 gallon fuel tank, w/ 8'L porch extension, (2) 110V pumps, skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX

Lot #	Details	Lot #	Details
1585	(Rig#24) Quantity of (2) Cat Containerized Generator Set S/N: Not Available C/W: Cat 3406 Diesel Engine, Electrical panels, Fluorescent lighting, Storage area, Sullivan Palatek compressor; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1590	(Rig#24) Quantity of Closing Unit, Choke Manifold, Lubester, Swivel, Catwalk, Basket S/N: Not Available C/W: 5,000# choke manifold, 8'x 10' x 5' junk basket skidded w/contents, 5-station closing unit, 4-compartment lubester; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
1586	(Rig#24) National 55 S/D Drawworks Drawworks S/N: T1890 C/W: 1,000 Hp, Lebus Grooved for 1-1/8" line, FOSTER Makeup & Breakout Catheads,2- Engine in line compound, (2) National c300185 torque converters, 2-stage air compressor, radiators, air start, muffler, master skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-	1591	(Rig#24) 27-½ in Rotary Table S/N: Not Available C/W: w/ Kelly drive bushing housing, chain guard; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
 1587	LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1592	(Rig#24) 6 ft x 3 ft - 6 ft x 28 ft Catwalk S/N: Not Available C/W: assorted gates Usage: Not Available Notes: RITCHIE-BROS-ENERGY
	(Rig#24) Triplex Mud Pump S/N: Not Available C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/ screw in caps, pulsation dampener, mud gauge, cent pump, Cat 12V Diesel engine, air start, radiator, muffler, air and fuel tanks, master skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1593	Asset located in: Coleman, TX (Rig#24) Junk Basket S/N: Not Available C/W: air hoist, elevator links, tongs, closing of remote panel, mud bucket, drill pipe slips, drocollar slips and misc drilling equipment; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
1588	2010 (Rig#24) RS-F1000 Triplex Mud Pump S/N: RS11012 C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/screw in caps, pulsation dampener, mud gauge, cent pump, bull wheel, belt guard, Cat 12V Diesel engine, air start, radiator, muffler, air volume tank, fuel tank, master skidded; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1594	Asset located in: Coleman, TX (Rig#24) Quantity of Drill Collars S/N: Not Available C/W: 6" OD Drill Collars w/4-1/25" XH Connections (3) 8" OD Drill Collars w/ 6-3/4" REG Connections, (1) Hex Kelley; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX (Rig#25) Lee C Moore 131 ft Cantilever Mast
1589	(Rig#24) 10 ft x 40 ft Toolpusher's House S/N: Not Available C/W: office area, bedroom, bathroom area, kitchen area (gutted) skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1090	S/N: T3067 C/W: 440,000 Lb Static Hook Load, Crown, Block w/ (4) 36" Cluster, 54" Fastline Sheave, Racking Board, Tong Counter Weights, Ladder, Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, spool of 1-1/8" drill line, racking board ' EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX

Lot #	Details	Lot #	Details
1596	(Rig#25) 26 ft 1 in x 16 ft x 47 ft Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp, Stairs, Safety Rails, Emsco type 17-1/2" rotary table, Ingeraoll Rand Air hoist, weight indicator, wireline measuring device, National deadman anchor, air volume tank, fold doghouse supports, pony subs, skidded 'EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	1602	Parts House S/N: Not Available C/W: flat steel, round top, shelving, bench storage, fluorescent lighting, misc rig parts, skidded; EQUIPMENT-FROM-TPI-COLEMAN PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX Cat (Rig#25) Containerized Generator Set S/N: Not Available
1597	Asset located in: Coleman, TX (Rig#25) 8 ft x 32 ft Doghouse S/N: Not Available C/W: Doghouse, 8'L Covered Porch, Lockers, Knowledge Box, Bench Storage, Cabinets; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY		C/W: Cat SR4B generator p/b Cat 6-cylinder diesel engine, generator p/b 6-cylinder diesel engine, skidded, electrical control panel, Curtis 30HP air compressor, all mud in 10'W x 40'L generator house, skidded; ; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
1598	Asset located in: Coleman, TX (Rig#25) 10 ft x 5 ft 10 in x 30 ft 300 bbl Mud Tank S/N: Not Available C/W: VORTEX Orbital 3000M Single, Single Screen, Linear Motion Shale Shaker, mud house, skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY		(Rig#25) National 50-CA S/D Drawworks S/N: Not Available C/W: w/ (2) Cat D353 Diesel Engines, (2) National C-245-80 Torque Converters, 2-Engine inline compound, Quincy type air compressor, Air start, radiators, Foster makeup and breakout catheads, Levi's grooved f/1-1/8" drill line; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
1599	Asset located in: Coleman, TX (Rig#25) Quantity of (2) 500 bbl Water Tank	1605	Asset located in: Coleman, TX (Rig#25) Quantity of (2) Bomco 3NB1300C
1099	S/N: Not Available C/W: skidded, w/water pump, (4) cent pumps; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1605	Triplex Mud Pump S/N: Not Available C/W: each with forged fluid ends w/ screw in caps, cent pump, Hydril pulsation dampeners, mud gauges, p/b (1) Cat D398, (1) Cat D399PC 12-Cylinder & 16-Cylinder Diesel engines, radiators, master skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC
1600	(Rig#25) 8000 gal Fuel Tank S/N: Not Available C/W: (2) transfer pumps, ladder; EQUIPMENT-		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
	FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX		(Rig#25) Toolpushers House S/N: Not Available C/W: (1) office, (1) bedroom, (1) bathroom, skidded (doors locked could not access);
1601	(Rig#25) Skidded Parts house S/N: Not Available C/W: shelving, lockers, bench storage, fluorescent lighting, skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC		EQUIPMÈNT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
	Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1607	(Rig#25) Sowa Block Hook Combination S/N: Not Available C/W: (2) WTM 4- ¼" - 6 ¾" Rotary Tongs, elevator links, elevator, drill pipe slips, drill collar slips, lift subs, and bit breaker; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX

Lot #	Details	Lot #	Details
1608	(Rig#25) 4-Station Accumulator Closing Unit S/N: Not Available C/W: Parkersburg brake, (3) suitcases, stairs, tong and misc drilling equipment; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	1614	Pai PAI70HP3250 Mud Pump S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine Usage: 168 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX
1609	(Rig#25) 2-Section Catwalk S/N: Not Available C/W: Steel Deck, Ideco swivel, hex Kelly, mouse hole, hex Kelly drive bushing, junk basket w/lift subs and misc, water pump, v- door ramp; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1615 1616	Tulsa Rig Iron Mud Pump S/N: TT150-52 C/W: Triplex 2014 US EPA Label, Cummins 6 Cylinder Diesel Engine Usage: 642 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX 1998 Triplex Mud Pump S/N: 160 TP 6L C/W: 4 in Intake, 3 in Discharge, Mud Pump,
1610	(Rig#25) Junk Box S/N: Not Available C/W: EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available		Cat 6 Cylinder Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
CHOIC	Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX E OF 2 - Lot #'s: 1611, 1612	1617	Wheatley HP-250H Skid Mounted Triplex Test Pump S/N: Not Available C/W: 1 in Intake, 1 in Discharge, Triplex Detroit 8W-71 8 Cylinder Diesel Engine, EQUIPMENT-
1611	2006 Bomco 3NB1000C Triplex Mud Pump S/N: 1060917 C/W: Cat 12 Cylinder Diesel Engine, pulsation dampener, bolt on caps, mud gauge, bull wheel,		FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: RITCHIE-BROS-ENERGY; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	skidded, Parkersburg torque converter, radiator, skidded ; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX		2012 Keystone Skid-Mounted Booster Air Compressor S/N: MCW02262 C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC
1612	2006 Bomco 3NB1000C Triplex Mud Pump S/N: 1060919 C/W: Cat 12 Cylinder Diesel Engine, bolt on		Usage: 1,899 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	caps, pulsation dampener, mud gauge, cent pump, manifold, torque converter, radiator, air and fuel tanks, master skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available	сноіс	E OF 4 - Lot #'s: 1619, 1620, 1621, 1622
	Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX	1619	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 378088
1613	2008 NLB Skid Mounted Triplex Test Pump S/N: P4012901 C/W: Triplex Cummins N14 6 Cylinder Diesel Engine, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: RITCHIE-BROS-ENERGY; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 8,391 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
1620	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 380841ULQB78 C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 8,256 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1626	2003 Ariel Skid-Mounted Booster Air Compressor S/N: KB-10 C/W: Cat 3126 6 Cylinder 309 hp 7.2 L Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING- INC Usage: 3,541 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1621	2007 Ingersoll Rand XHP1170 1170 cfm Skid- Mounted Air Compressor S/N: 378089 C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 9,385 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1627	2003 Ariel Skid-Mounted Booster Air Compressor S/N: BEJ02783 C/W: Cat 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 906 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1622	2007 Ingersoll Rand XHP1170 Skid-Mounted Air Compressor S/N: 380840ULQB78 C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 11,640 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	— 1628	Quantity of (152 joints)(4,712') 4-1/2 in Range 2 Drill Pipe S/N: Not Available C/W: (4,712 ft), w/ 4-1/2" FH conns, w/(6) 3 sets of 40"H x 30'L triangular pipe racks; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
CHOIC	E OF 2 - Lot #'s: 1623, 1624	1629	Quantity of (144) 3-1/2 in Range 2 (4,464') Drill Pipe
1623	2004 Sullair 1170 Skid-Mounted Air Compressor S/N: 006-04011489 C/W: Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY		S/N: Not Available C/W: (4,464 ft), w/3-1/2"IF conns, HB, w/(4) (2) sets of 40"H x 30'L trainagular pipe racks; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Coleman, TX
1624	Asset located in: Cedar Bluff, VA 2004 Sullair 1170 1170 cfm Skid-Mounted Air Compressor S/N: 006-04011490 C/W: 365 psi Working Pressure, Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available	1630	Quantity of Approximately 6353 ft 4 in Drill Pipe S/N: Not Available C/W: Approximately 6353 ft, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA Quantity of Approximately 12114 ft of 3.5 in
CHOIC 1625	Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA E OF 3 - Lot #'s: 1625, 1626, 1627 2008 Ariel JGQ/2 Skid-Mounted Booster Air	1631	Drill Pipe S/N: Not Available C/W: Approximately 12114 ft; EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	Compressor S/N: KB102 C/W: Cat C7 6 Cylinder 250 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 4,357 Hr Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1632	Quantity of Approximately 5767 ft of 4 in Drill Pipe S/N: Not Available C/W: Approximately 5767 ft; EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
	E OF 10 - Lot #'s: 1633, 1634, 1635, 1636, 1637, 639, 1640, 1641, 1642 Quantity of (7) 4.5 in Drill Collars	1641	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1642	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
1634	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Asset located in: Cedar Bluff, VA E OF 10 - Lot #'s: 1643, 1644, 1645, 1646, 1647, 1649, 1650, 1651, 1652
1635	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1643	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
1636	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1644	RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC
1637	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1638	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1645	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1639	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1646	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
1640	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details	
1647	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		E OF 10 - Lot #'s: 1653, 1654, 1655, 1656, 1657, 659, 1660, 1661, 1662	
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1653	Quantity of (4) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available	
1648	Quantity of (5) 4.5 in Drill Collars S/N: Not Available		Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE		Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC	
	SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
1649	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	1655	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in : Cedar Bluff, VA	1656	S/N: Not Available	
1650	Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	Notes: RITCHIE-BROS-ENERGY
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY	
1651	Quantity of (4) 4.5 in Drill Collars		Asset located in: Cedar Bluff, VA	
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY	1658	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	Asset located in: Cedar Bluff, VA	1659	Quantity of (3) 6 in Drill Collars	
1652	Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE		S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1660	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	

Lot #	Details	Lot #	Details
1661	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1669	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1662	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1670	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	E OF 10 - Lot #'s: 1663, 1664, 1665, 1666, 1667, 1669, 1670, 1671, 1672 Quantity of (3) 6 in Drill Collars	1671	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1672	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
1664	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Asset located in: Cedar Bluff, VA E OF 9 - Lot #'s: 1673, 1674, 1675, 1676, 1677, 1679, 1680, 1681
1665	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1673	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1666	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1674	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1667	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1675	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
1668	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1676	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details	
1677	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1685	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
1678	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1686	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
1679	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1687	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
1680	Quantity of (2) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1688	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
1681	Quantity of (2) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1689	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	E OF 8 - Lot #'s: 1682, 1683, 1684, 1685, 1686, 688, 1689 Quantity of (1) 7.5 in Drill Collars	1690	Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	1691	2014 Kenworth T800 8x4 Cab and Chassis S/N: 1NKDX4EXXEJ404952 C/W: Cummins ISX15 15.0 L 525 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20872.4 Engine hrs, Engine Brake, Eaton	
1683	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA			Fuller 8LL Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 71340 lb GVWR, Air Ride Cab, 11R24. 5 Front Tires, 11R24.5 Rear Tires, Hendrickson Primaax EX Air Ride Suspension, 229 in Wheelbase, 103 in Cab to Axle, 286 in Cab to End of Frame, Pintle Hitch
1684	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		Usage: 514,573 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
1692	2018 Mack GU713 6x4 Cab and Chassis S/N: 1M1AX07YXJM038681 C/W: Mack MP8 6 Cylinder 12.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 189 Engine hrs, Engine Brake, Mack Automated Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Double Frame, Rubber Suspension, 206 in Wheelbase Usage: 463,795 Mi Asset located in: Lake Worth, TX	1696	2018 International 8600 4x2 Cab and Chassis S/N: 3HTHWSNNXJN626104 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 3: hp Engine, 2017 US EPA Label, Requires Dies Exhaust Fluid, 9390 Engine hrs, Eaton Fuller Automated Transmission, 13000 lb Front Axl 20000 lb Rears, 33000 lb GVWR, Air Ride Cab Aluminum Wheels, 12R22.5 Front Tires, 11R2 5 Rear Tires, Air Ride Suspension, 264 in Wheelbase, 204 in Cab to Axle, 300 in Cab to End of Frame Usage: 393,327 Mi
1692A	2011 International 4400 6x4 Cab and Chassis		Asset located in: Lake Worth, TX
	S/N: 1HTMSAZR3BH340351 C/W: International MaxxForce 9 6 Cylinder 9.3 L Diesel Engine, Engine Brake, Allison Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 271 in Wheelbase, 208 in Cab to Axle, 315 in Cab to End of Frame Usage: 198,057 Mi Asset located in: Humble, TX	1697	2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV9J4S57961 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10275 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Spring Suspension, 272 in Wheelbase, 206 in Cab to Axle, 283 in Cab to End of Frame Usage: 284,232 Mi
1693	2011 Kenworth T370 4x2 Cab and Chassis		Asset located in: Lake Worth, TX
	S/N: 2NKHHN7X2BM296249 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8574 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Spring Suspension, 229 in Wheelbase, 164 in Cab to Axle, 216 in Cab to End of Frame Usage: 163,110 Mi Asset located in: Lake Worth, TX		2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV0J4S58139 C/W: Hino J08E-VB 6 Cylinder Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9483 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 204 in Cab to Axle, 284 in Cab to End of Frame
1694	2020 Freightliner M2 106 4x2 Cab and Chassis	1	Usage: 301,522 Mi Asset located in: Lake Worth, TX
	S/N: 3ALACWFC1LDMA1987 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller EDCO- 6F107A Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 204 in Wheelbase, 140 in Cab to Axle, 212 in Cab to End of Frame Usage: 221,672 Mi Asset located in: Humble, TX	1699	2018 Hino 268 4x2 Cab and Chassis S/N: 5PVNJ8JV8J4S68672 C/W: J08E 6 Cylinder 7.6 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6352 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 205 in Cab to Axle, 319 in Cab to End of Frame Usage: 234,436 Mi Asset located in: Lake Worth, TX
1695	2019 International 4300 4x2 Cab and Chassis	1700	2014 Freightliner M2 106 4x2 Cab and Chassis
	S/N: 3HAMMMMN5KL559225 C/W: Cummins B6.7 260 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12755 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 254 in Wheelbase, 186 in Cab to Axle, 278 in Cab to End of Frame Usage: 193,556 Mi Asset located in: Lake Worth, TX		S/N: 1FVACXDT6EHFY9046 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 7129 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 270 in Wheelbase, 204 in Cab to Axle, 300 in Cab to End of Frame Usage: 200,956 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1701	2014 Hino 268 4x2 Cab and Chassis S/N: 5PVNJ8JL5E4S51770 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, 102 in Cab to Axle, 162 in Cab to End of Frame Usage: 263,506 Mi	1708 1708A 1709	10ICE OF 2 - Lot #'s: 1707, 1708 07 2017 Ford F-550 4x4 Extended Cab Cab and Chassis S/N: 1FD0X5HT8HEE59326 C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel	
1702	Asset located in: Lake Worth, TX 2013 Peterbilt 337 4x2 Cab and Chassis S/N: 2NP2HN7X2DM190208 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel Engine, Requires Diesel Exhaust Fluid, 10775 Engine hrs, Allison 3500 Automatic		Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 86 in Cab to Axle, 128 in Cab to End of Frame Usage: 141,292 Mi Asset located in: Lake Worth, TX	
	Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, Dana Drive Axles, 5.29:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Double Frame, Reyco Spring Suspension, 238 in Wheelbase, 168 in Cab to Axle, 222 in Cab to End of Frame Usage: 204,502 Mi Asset located in: Humble, TX		Chassis S/N: 1FDOX5GT0HEE87879 C/W: Ford Power Stroke 6.7 L Diesel 330 h Engine, 2017 US EPA Label, CARB Complia Requires Diesel Exhaust Fluid, 8271 Engin Automatic Transmission, 7000 lb Front Ax	
1703A	2012 International 4300 4x2 Cab and Chassis S/N: 3HAMMAAN5CL562842 C/W: 6 Cylinder Diesel Engine, 6570 Engine hrs, Automatic Transmission, 10000 lb Front Axle,		Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 134 in Cab to End of Frame Usage: 204,811 Mi Asset located in: Lake Worth, TX	
	23000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 255 in Wheelbase, 188 in Cab to Axle, 298 in Cab to End of Frame Usage: 205,283 Mi Asset located in: Humble, TX		Chassis S/N: 1FD0X5GT9HEC48136 C/W: V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaus	
1704A	2018 Isuzu NPR-XD 4x2 COE Cab and Chassis S/N: JALC4W161J7K00299 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 176		Brake, Automatic Transmission, 65 Axle, 14706 lb Rears, 19500 lb GVW /70R19.5, Spring Suspension, 192 i	Brake, Automatic Transmission, 65000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 122 in Cab to End of Frame Usage: 131,502 Mi
	in Wheelbase, 159 in Cab to Axle, 204 in Cab to End of Frame Usage: 316,607 Mi Asset located in : Humble, TX		2016 Ram 5500 4x2 Cab and Chassis S/N: 3C7WRMDL1GG283996 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine,	
1706	2019 Ford F-550 XL 4x4 Extended Cab Cab and Chassis S/N: 1FD0X5HT1KEF25139 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 192 in Wheelbase, 86 in		2016 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 255/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 204 in Wheelbase, 120 in Cab to Axle, 173 in Cab to End of Frame Usage: 185,092 Mi Asset located in: Lake Worth, TX	
	Cab to Axle, 134 in Cab to End of Frame Usage: Not Available Asset located in: Midland, TX	1709A	2012 Ford F-550 4x2 Extended Cab Cab and Chassis S/N: 1FD0X5GT5CEC83751 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 183 in Wheelbase, 80 in Cab to Axle, 130 in Cab to End of Frame Usage: 204,360 Mi	

Lot #	Details	Lot #	Details
1711	2009 Peterbilt 335 4x2 Cab and Chassis S/N: 2NPLHN7X19M788656 C/W: Paccar 6 Cylinder Diesel Engine, Engine Brake, Allison 3500 Automatic Transmission, 10000 lb Front Axle, 23000 lb Rears, Dana S23- 170 Drive Axles, 6.14:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, 134 in Cab to Axle, 171 in Cab to End of Frame Usage: 102,359 Mi	1718 1719	1990 International 4600 4x2 Cab and Chassis S/N: 1HTSAZRN0MH332118 C/W: International 7.3 L Diesel 155 hp Engine, Steel, 255/70R22.5, Double Frame, Spring Suspension, 152 in Wheelbase, 84 in Cab to Axle, 147 in Cab to End of Frame Usage: 218,680 Mi Asset located in: Lake Worth, TX 2019 Freightliner M2 106 6x4 Flatbed Truck
1713	Asset located in: Humble, TX 2007 Hino 258 4x2 Cab and Chassis S/N: 5PVND8JT672S50164 C/W: Hino 6 Cylinder Diesel 220 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 255 /70R22.5, Spring Suspension, 219 in Wheelbase, 150 in Cab to Axle, 183 in Cab to End of Frame Usage: 329,692 Mi Asset located in: Lake Worth, TX	-	S/N: 3ALHCYFE7KDKU9146 C/W: Cummins L9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6627 Engine hrs, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.33:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 28 ft x 102 in Bed, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 288,102 Mi
1715	2005 Peterbilt 335 4x2 Cab and Chassis		Asset located in: Lake Worth, TX
	S/N: 2NPLHD6X45M857023 C/W: Cat C7 6 Cylinder 7.2 L Diesel 250 hp Engine, 2006 US EPA Label, 15489 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 4.88:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22. 5, Low Air Leaf Suspension, 191 in Wheelbase, PTO, 120 in Cab to Axle, 195 in Cab to End of Frame Usage: 459,210 Mi Asset located in: Lake Worth, TX	1720	2014 International 7600 6x4 Flatbed Truck S/N: 1HTGSSJT6EH786752 C/W: International 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Ride Suspension, 261 in Wheelbase, 20 ft 10 in x 97 in Bed Usage: 323,203 Mi Asset located in: Lake Worth, TX
1715A	2007 GMC C7500 4x2 Cab and Chassis S/N: 1GDK7C1C67F900371 C/W: Cat C7 6 Cylinder 7.2 L Diesel 210 hp Engine, 2006 US EPA Label, Automatic Transmission, 8001 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, 192 in Cab to Axle, 228 in Cab to End of Frame Usage: 226,533 Mi Asset located in: Lake Worth, TX	1721	2003 Mack RD688S 6x4 Flatbed Truck S/N: 1M2P267C93M065482 C/W: Mack E7 6 Cylinder Diesel 350 hp Engine, 2002 US EPA Label, 28682 Engine hrs, Eaton Fuller 8LL Manual Transmission, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Camelback Spring Suspension, 252 in Wheelbase, PTO, 20 ft 6 in x 92 in Bed Usage: Not Available Asset located in: Lake Worth, TX
1716	1998 Peterbilt 330 4x2 Cab and Chassis S/N: 3BPNHD7X1WF459167 C/W: Cat 3126B 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 274 in Wheelbase, PTO, 200 in Cab to Axle, 329 in Cab to End of Frame Usage: 912,630 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX	1721A	2018 International 4300 4x2 Flatbed Truck S/N: 1HTMMMMMXJH632780 C/W: Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11497 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 10R22.5, Spring Suspension, 181 in Wheelbase, 14 ft 5 in x 96 in Bed Usage: 148,134 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1722	2016 Freightliner M2 106 4x2 Flatbed Truck S/N: 1FVACXDT0GHHR9676 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 13474 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.56:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 96 in Bed, Aluminum Frame, Liftgate Usage: 206,090 Mi Asset located in: Lake Worth, TX	1726	2019 Ford F-750 4x2 Flatbed Truck S/N: 1FDXF7DE5KDF11884 C/W: 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 260 in Wheelbase, 18 ft x 92 in Bed, Pintle Hitch Usage: 34,747 Mi Asset located in: Lake Worth, TX
1723	2014 Freightliner M2 106 6x4 Flatbed Truck	сноісі	E OF 2 - Lot #'s: 1727, 1728
	S/N: 1FVHCYCY5EHFV7934 C/W: Cummins ISL9 6 Cylinder Diesel 350 hp Engine, Requires Diesel Exhaust Fluid, 9346 Engine hrs, Allison Automatic Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 274 in Wheelbase, 24 ft x 91 in Bed, Forklift Mount Kit Usage: 158,702 Mi Asset located in: Humble, TX	1727	2009 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF65C79V065767 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2008 US EPA Label, 2379 Engine hrs, Eaton Fuller Automated Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, 13 ft x 94 in Bed, Winch Usage: 14,420 Mi Asset located in: Lake Worth, TX
1724	2019 Isuzu NPR HD 4x2 COE Crew Cab Flatbed	1728	2009 Ford F-650 XL 4x2 Flatbed Truck
	Truck S/N: 54DC4J1B6KS801218 C/W: 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225/70R19.5, Spring Suspension, 181 in Wheelbase, 19 ft x 93 in Bed, Dovetail, Manual Ramps Usage: 138,503 Mi Asset located in: Lake Worth, TX		S/N: 3FRNF65H89V109657 C/W: Cummins 6 Cylinder Diesel Engine, Automatic Transmission, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 195 in Wheelbase, 8 ft x 96 in Bed Usage: 74,757 Mi Asset located in: Lake Worth, TX
1724B	2007 International 4300 4x2 Flatbed Truck		E OE 2 - Lat #a: 1720 1720
	S/N: 1HTMMAAM17H382700 C/W: International DT466 6 Cylinder 7.6 L Diesel 210 hp Engine, 2006 US EPA Label, 7485 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, 18 ft x 92 in Bed, Poly Tank, MultiQuip Concrete Mixer, Usage: 238,996 Mi Asset located in: Lake Worth, TX	1729 2 F S C E T 1 A E U N F S	2001 Stewart and Stevenson M1078 4x4 Flatbed Truck S/N: 14619G C/W: cat 3126 6 Cylinder 7.2 L Diesel 246 hp Engine, 1999 US EPA Label, Automatic Transmission, 395/85R20, Spring Suspension, 154 in Wheelbase, 12 ft 6 in x 96 in Bed, Diesel, Allison Auto, Central Tire Inflation;
1725	2006 Hino 268 4x2 Flatbed Truck S/N: 5PVNE8JT462S12363 C/W: Hino 6 Cylinder Diesel Engine, Automatic Transmission, 11R22.5, Spring Suspension, 245 in Wheelbase, 23 ft 8 in x 94 in Bed Usage: 672,876 Mi		
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1730	1998 Stewart and Stevenson M1079 4x4 COE
1725B	Asset located in: Humble, TX 2007 International 4400 4x2 Flatbed Truck S/N: 1HTMRAAL97H464165 C/W: 6 Cylinder Diesel Engine, Allison Automatic Transmission, Aluminum Wheels,	S/N: V011285EDKG C/W: Cat 6 Cylinder Diesel En Automatic Transmission, 395 Suspension, 154 in Wheelbas in Bed, Pintle Hitch, EQUIPME	C/W: Cat 6 Cylinder Diesel Engine, Allison Automatic Transmission, 395/85R20, Spring Suspension, 154 in Wheelbase, 12 ft 6 in x 94 in Bed, Pintle Hitch, EQUIPMENT-FROM-
	255/70R22.5, Air Ride Suspension, 207 in Wheelbase, 14 ft x 90 in Bed Usage: 215,347 Mi Asset located in: Humble, TX		WATKINS-CONSTRUCTION Usage: 4,949 Mi Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 1731, 1732 1998 Stewart and Stevenson M1078 4x4 COE Flatbed Truck S/N: AT9310EDEG C/W: Diesel Engine, Automatic Transmission, 395/88820, Spring Suspension, 152 in	S/N: 1FDUFS C/W: power 2022 US EPA Automatic T 14706 lb Rea Spring Suspe 96 in Bed, Al Usage: 46,06 Asset locate 1742 2018 Ford F- Truck S/N: 1FD0W C/W: 6 Cylin 2018 US EPA Fluid, Autom Axle, 14706 /70R19.5, Sp Wheelbase, Usage: 160,0	2022 Ford F-550 XL 4x4 Flatbed Truck S/N: 1FDUF5HT4NEE52440 C/W: power stroke V8 6.7 L Diesel Engine, 2022 US EPA Label, 1589 Engine hrs, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5 Spring Suspension, 169 in Wheelbase, 12 ft x 96 in Bed, Aluminum Frame Usage: 46,064 Mi Asset located in: Lake Worth, TX
	Wheelbase, 12 ft 7 in x 96 in Bed, Diesel, Allison Automatic, Central Tire Inflation; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 7,226 Mi Notes:; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		2018 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT6JEC24738 C/W: 6 Cylinder 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225
1732	1995 Stewart and Stevenson M1078 COE 4x4 Flatbed Truck S/N: AT0761BEC C/W: Allison Automatic Transmission, 395		/70R19.5, Spring Suspension, 203 in Wheelbase, 10 ft 6 in x 89 in Bed, Fuel Tank Usage: 160,056 Mi Asset located in : Lake Worth, TX
	/85R20, 155 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch, Diesel, Allison Auto, Central Tire Inflation; EQUIPMENT-FROM-WATKINS- CONSTRUCTION	CHOIC	E OF 2 - Lot #'s: 1743, 1744
	Usage: 3,055 Mi Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	S/N: 3C7WRNFL1JG157387 C/W: Cummins ISB6.7 325 Engine, 2018 US EPA Label, Automatic Transmission, 72	2018 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL1JG157387 C/W: Cummins ISB6.7 325 6.7 L 325 hp Engine, 2018 US EPA Label, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500.0 lb GVWR, 225/70R19.
CHOIC	E OF 3 - Lot #'s: 1734, 1735, 1736		5, Spring Suspension, 197 in Wheelbase, 12 ft x 96 in Bed, Fuel Tank /w Pump, Pintle Hitch Usage: 81,063 Mi Asset located in : Lake Worth, TX
1734	2006 GMC 4500 4x2 Flatbed Truck S/N: 1GDE4C12X6F431782 C/W: V8 6.6 L Diesel 300 hp Engine, 2006 US EPA Label, Automatic Transmission, 225 /70R19.5, Spring Suspension, 179 in Wheelbase, 14 ft 4 in x 93 in Bed Usage: 214,436 Mi Asset located in: Lake Worth, TX	1744	2018 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL8JG207251 C/W: Cummins 6.7 L Diesel Engine, 6818 Engine hrs, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 194 in Wheelbase
1735	2006 GMC 4500 4x2 Flatbed Truck		Usage: 114,766 Mi Asset located in: Lake Worth, TX
	S/N: 1GDE4C1256F431754 C/W: Chevy V8 6.6 L Diesel Engine, US EPA Label, Allison 4 Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 177 in Wheelbase, 14 ft x 92 in Bed, Receiver Usage: 182,782 Mi Asset located in: Lake Worth, TX	1746 20 S/ C/ La Au 13 Sp 96 Us	2017 Ford F-550 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT4HEC85077 C/W: V8 6.7 L 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 187 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch Usage: 147,936 Mi
1736	2006 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBE4C1226F434247 C/W: V8 6.6 L Diesel Engine, Allison Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225/70R19.5, Spring Suspension, 190 in Wheelbase, 13 ft x 96 in Bed, Hitch Receiver Usage: 179,635 Mi Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1747	2017 Ford F-450 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W4HY8HEC86836 C/W: 6 Cylinder 6.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 205 in Wheelbase, 11 ft 6 in x 60 in Bed, Fuel Tank, Pintle Hitch Usage: 45,366 Mi	1757	2013 Ford F-450 4x2 Flatbed Truck S/N: 1FDUF4GY5DEA18226 C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, 5-Speed Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 201 in Wheelbase, 17 ft 5 in x 96 in Bed, Liftgate Usage: 204,057 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1758	2013 Ford F-450 XL 4x2 Flatbed Truck
1749	2016 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT2GEB95778 C/W: Power Stroke V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 200 in		S/N: 1FDUF4GT4DEB86573 C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft x 94 in Bed Usage: 201,329 Mi Asset located in: Lake Worth, TX
	Wheelbase, 12 ft 6 in x 96 in Bed, Liftgate, Rear View Camera ; EQUIPMENT-FROM-SUNSTATE-	1759	2011 Ford F-450 XL 4x4 Crew Cab Flatbed
	EQUIPMENT Usage: 120,695 Mi Asset located in: Lake Worth, TX	1759 -	Truck S/N: 1FD0W4HT0BEC98605 C/W: Ford Power Stroke V8 6.7 L Ultra Low Sulfur Diesel Engine, 2011 US EPA Label,
1750	2016 Ford F-550 XL 4x4 Extended Cab Flatbed Truck S/N: 1FD0X5HT8GEC75339 C/W: 6.7 L 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8438 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5,		Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, 8 ft 9 in x 94 in Bed Usage: 290,111 Mi Asset located in: Lake Worth, TX
	Spring Suspension, 186 in Wheelbase, 11 ft x 91 in Bed, Fuel Tank Usage: 191,492 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	1760	2003 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBC4E1E93F503492 C/W: V8 8.1 L Gasoline Engine, Automatic Transmission, 6000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring
1751			Suspension, 186 in Wheelbase, 13 ft 4 in x 97 in Bed
1751	2016 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL3GG329797		Usage: 281,996 Mi
	C/W: Cummins 6 Cylinder 6.7 L Ultra Low		Asset located in: Lake Worth, TX
	Sulfur Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Bunk Beds, 225/70R19. 5, Spring Suspension, 198 in Wheelbase, 12 ft x 55 in Bed, Pintle Hitch Usage: 158,301 Mi Asset located in: Lake Worth, TX	1762	2021 GMC Sierra 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GD49SE76MF148113 C/W: V8 6.6 L Gasoline Engine, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 182 in Wheelbase, 9 ft x 96 in Bed, Fuel Tank /w Pump, EQUIPMENT-FROM-
1754	2013 Ford F-550 XL 4x4 Crew Cab Flatbed		WATKINS-CONSTRUCTION
	Truck S/N: 1FD0W5HT9DEB58125 C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft 2 in x 88 in Bed Usage: 301,436 Mi Asset located in: Midland, TX		Usage: 116,066 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICI TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1764	2022 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3GN1NEC44542 C/W: Ford V8 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 245 /75R17, 9 ft x 93 in Bed Usage: 111,959 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	1769	2019 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FT8W3DT6KEG85635 C/W: Ford Power Stroke 6.7 L Diesel Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5246 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 9900 lb Rears, Ford-Factory Drive Axles, 14000 lb GVWR, Aluminum Wheels, 245/75R17, Ford- Factory Spring Suspension, 178 in Wheelbase, 9 ft x 98 in Bed, Receiver hitch, Fifth wheel ball Usage: 194,430 Mi
1765	2020 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3G6XLEE32269 C/W: V8 6.2 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 90 in Bed Usage: 121,378 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	1773	2019 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT6KDA03912 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 5452 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 245/70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft 6 in x 96 in Bed Usage: 176,902 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
Asset locate 1767 2019 Ford F Truck S/N: 1FD8W C/W: 6.7 L I Label, Requ Automatic 1 10040 lb Re Spring Susp x 98 in Bed,	S/N: 1FD8W3HT3KEF22298 C/W: 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 181 in Wheelbase, 9 ft 6 in x 98 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	1774	2018 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT5JEC95579 C/W: V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 8284 Engine hrs, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 3 in x 98 in Bed Usage: 221,150 Mi Asset located in: Humble, TX
1768	Usage: Not Available Asset located in: Lake Worth, TX 2019 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3G63KEC30873 C/W: V8 6.2 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase, 9 ft 5 in x 90 in Bed Usage: 93,217 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	1776	2017 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3H62HEE73498 C/W: Ford V8 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 5200 lb Front Axle, 10040 lb Rears, 14000.0 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 92 in Bed, Pintle Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 119,438 Mi Asset located in: Lake Worth, TX 2016 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT6GEA98185 C/W: Ford V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, 11342 Engine hrs, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 265/70R17, Spring Suspension, 176 in Wheelbase, 9 ft 4 in x 92 in Bed Usage: 279,994 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICE	E OF 2 - Lot #'s: 1778, 1779	СНОІСІ	E OF 2 - Lot #'s: 1782, 1783
1778	2018 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL7JG325302 C/W: Cumins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 640 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80/17, Spring Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in Bed Usage: 90,276 Mi Asset located in: Lake Worth, TX	1782	2017 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY3HF162424 C/W: V8 6.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 8853 Engine hrs, Exhaust Brake, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 172 in Wheelbase, 9 ft 4 in x 92 in Bed Usage: 113,083 Mi Asset located in: Lake Worth, TX
1779	2017 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL9HG759022 C/W: 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 173 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 382,795 Mi Asset located in: Midland, TX	1783	2017 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY0HF162509 C/W: V8 6.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 12354 Engine hrs, Automatic Transmission, 5600 lb GVWR, 255/80R17, Spring Suspension, 172 in Wheelbase, 9 ft 4 ir x 86 in Bed Usage: 113,385 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICI
1779A	779A 2017 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL9HG684368 C/W: Cummins V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 171 in Wheelbase, 9 ft 6 in x 90 in Bed Usage: 343,489 Mi Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
		Cab Flatbed Truck S/N: 1GB4KZCGXEF154345 C/W: V8 Gasoline Engine, Aut Transmission, 4800 lb Front A Rears, 13200 lb GVWR, 245/7 235/80R17 Rear Tires, Spring in Wheelbase, 9 ft 4 in x 92 in Usage: 244,091 Mi Asset located in: Lake Worth, 1784 2012 Dodge Ram 3500HD 4x2 Flatbed Truck S/N: 3C7WDSCLXCG193793 C/W: Cummins 6 Cylinder 6.7 Requires Diesel Exhaust Fluid hrs, Automatic Transmission, Axle, 9350 lb Rears, 13000 lb /79R17 Front Tires, 265/70R1	
1780	2019 GMC Sierra 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GD42TCG9KF236339		in Wheelbase, 9 ft 4 in x 92 in Bed
17004	C/W: V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 9375 lb Rears, 13025 lb GVWR, 265 /70R17, Spring Suspension, 168 in Wheelbase, 8 ft x 92 in Bed, Fuel Tank Usage: 112,708 Mi Notes: NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX		
1780A	2019 GMC 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KVCG5KF127400		in Bed, Receiver, Fifth wheel ball Usage: 329,146 Mi Asset located in : Lake Worth, TX
	C/W: V8 6.0 L Gasoline Engine, 11709 Engine hrs, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235 /80R17, Spring Suspension, 171 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 178,678 Mi Asset located in: Lake Worth, TX	1785	2011 Chevrolet 3500 HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4K1CL3BF151507 C/W: General Motors V8 6.6 L Diesel Engine, 2011 US EPA Label, Automatic Transmission, 245/70R17, Spring Suspension, 175 in Wheelbase, 8 ft 6 in x 84 in Bed, Better Built 50 gallons Fuel Tank Usage: 264,873 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE;

Lot #	Details	Lot #	Details	
1785A	2019 Ram 2500 4x2 Crew Cab Flatbed Truck S/N: 3C6UR4HJ5KG590150 C/W: V8 6.4 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 5500 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 275 /70R18, Spring Suspension, 170 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 158,739 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	1789	2015 Chevrolet Silverado 1500 4X4 Crew Cab Flatbed Truck S/N: 1GB4KYC87FF132971 C/W: V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 173 in Wheelbase, 9 ft 5 in x 86 in Bed Usage: 61,854 Mi Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	1790	2015 Chevrolet Silverado 1500 4x4 Crew Cab	
1786	2017 Ford F-250 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD7W2B67HED35955 C/W: Ford V8 6.2 L Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 6340 lb Rears, 10000.0 lb GVWR, 285/70R17, Spring Suspension, 176 in Wheelbase, 8 ft 6 in x 80 in Bed, Fuel Tank /w Pump Usage: 105,808 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		C/W: V8 6.6 L Diesel Engin Label, Requires Diesel Exh Automatic Transmission, 5 9750 lb Rears, 13200 lb G\ Spring Suspension, 174 in x 87 in Bed Usage: 117,117 Mi	S/N: 1GB4KYC84FF512267 C/W: V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 174 in Wheelbase, 9 ft 6 in x 87 in Bed
	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	1791	1971 Ford F100 4x2 Flatbed Truck	
1787	2015 Ford F-250 XL 4x2 Crew Cab Flatbed Truck S/N: 1FT7W2AT3FEB68857 C/W: V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 265/70R17, Spring Suspension, 171 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 288,298 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		C/W: Trans Susp Pintle Inger: EQUII Usag Notes VEHIO DISCI PROC	S/N: F10YRM02564 C/W: V8 Gasoline Engine, Automatic Transmission, 4500 lb GVWR, 7.00-15, Spring Suspension, 131 in Wheelbase, 8 ft x 78 in Be Pintle Hitch, Goodall Start-All Jumpstart Pack Ingersoll-Rand T30 Air Compressor; EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: CANNOT VERIFY ODOMETER READIN VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE;TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	1794	2012 Peterbilt 388 6x4 Sleeper Car Carrier	
1788	2011 Ford F-250 4x4 Crew Cab Flatbed Truck S/N: 1FT7W2B6XBED03559 C/W: Gasoline Engine, 2011 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 10000.0 lb GVWR, 245/75R17, Spring Suspension, 154 in Wheelbase, 7 ft x 84 in Bed Usage: 316,515 Mi Asset located in: Lake Worth, TX		S/N: 1NPWD49X2CD134987 C/W: Cummins ISX15 6 Cylinder Engine, 2011 US EPA Label, Req Exhaust Fluid, 44842 Engine hrs, Eaton Fuller 8LL Manual Transm Ib Front Axle, 40000 lb Rears, 53 Air Ride Cab, 58 in Flat Top Slee Aluminum Wheels, 295/60R22.5	C/W: Cummins ISX15 6 Cylinder 15.0 L 525 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 44842 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 Ib Front Axle, 40000 Ib Rears, 53200 Ib GVWR, Air Ride Cab, 58 in Flat Top Sleeper Cab, Aluminum Wheels, 295/60R22.5 Front Tires, 255/70R22.5 Rear Tires, Low Low Air Leaf Air
1788A	2011 Ford F-250 4x2 Flatbed Truck S/N: 1FTBF2A67BEC16567 C/W: Ford V8 6.2 L Gasoline Engine, US EPA Label, Automatic Transmission, 3950 lb Front Axle, 9800 lb Rears, 9800 lb GVWR, LT245 /75R17, Spring Suspension, 136 in Wheelbase, 8 ft 3 in x 79 in Bed, Receiver, Fifth wheel ball Usage: 318,291 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Ride Suspension, 264 in Wheelbase, PTO, Hydraulic Lift, Soft Tie Downs, SOLD WITH - Cottrell CX-11HCSI T/A, Trailer S/N - 5E0AJ144XCG335301, Soft Ties, Aluminum Wheels, 225/70R22.5 Tires Usage: 1,087,566 Mi Asset located in: Lake Worth, TX	

Details Lot # **Details** Lot # 1796 1800 2015 Freightliner Cascadia 113 8x4 Tri/A 2012 Kenworth T800 14x4 Five Axle Dump Truck **Dump Truck** S/N: 1NKDL40X0CJ335866 S/N: 1FUJGHDVXFLGF1087 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 C/W: Cummins 6 Cylinder 15 L Diesel 248 hp Engine, 2011 US EPA Label, Requires Diesel hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12000 lb Front Exhaust Fluid, 24448.6 Engine hrs, Engine Brake, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, Double Differential Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 Locks, 14320 lb Front Axle, 46000 lb Rears, lb GVWR, Air Ride Cab, Aluminum Outer 3.91:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Airliner Air Ride 11R24.5 Rear Tires, 3 Steerable Air Lift Pusher Suspension, 207 in Wheelbase, PTO, 16 ft 8 in Axle, Trailing Tag Axle, Double Frame, Long x 4 ft 3 in High Steel Body, Flat Bed, Hendrickson Haulmaax Rubber over Walking Electric Roll Tarp Beam Suspension, PTO, 14 ft 8 in Long x 5 ft 8 Usage: 816,761 Mi in High Steel Body, Electric Roll Tarp Notes: DEFICIENCIES NOTED - PLEASE SEE Usage: 259,946 Mi THE INSPECTION REPORT Asset located in: Lake Worth, TX Asset located in: Humble, TX 1797 2012 Freightliner Cascadia 125 10x4 Quad/A 1800A 2010 Freightliner M2 106 8x4 Tri/A Dump Truck **Dump Truck** S/N: 1FVHCYBS4ADAR3923 S/N: 1FUJGEDV2CSBM1515 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 C/W: 6 Cylinder Diesel Engine, 10275 Engine hrs, Engine Brake, Allison Automatic Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Dana DS404 Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5, Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 226 in Wheelbase, PTO, 17 ft 6 in Long x 3 ft 6 in High Steel Body, Electric Steerable Air Lift Tag Axle, Double Frame, Roll Tarp Usage: 242,980 Mi Airliner Air Ride Suspension, 312 mm Wheelbase, PTO, 21 ft Long x 4 ft High Steel Asset located in: Lake Worth, TX Body, Manual Roll Tarp Usage: 520,916 Mi 1800B 2009 Freightliner Cascadia 125 8x4 Tri/A Notes: DEFICIENCIES NOTED - PLEASE SEE **Dump Truck** THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION S/N: 1FUJGLCK89LAF1778 C/W: Detroit Series 60 14.0 L Diesel 515 hp Engine, 2008 US EPA Label, Engine Brake, REPORT Eaton Fuller 13-Speed Manual Transmission, Asset located in: Humble, TX 12000 lb Front Axle. 40000 lb Rears. 3.58:1 1798 2014 Kenworth T440 6x4 Dump Truck Axle Ratio, 52000 lb GVWR, Air Ride Cab, S/N: 1NKBLJ9X0EJ389440 Aluminum Outer Wheels, 11R22.5, Air Lift C/W: Paccar 6 Cylinder Diesel Engine, Requires Pusher Axle, Airliner Air Ride Suspension, 230 Diesel Exhaust Fluid, Engine Brake, Eaton Fuller in Wheelbase, 16 ft Long x 4 ft High Body, 10-Speed Manual Transmission, 14600 lb Electric Roll Tarp Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Usage: Not Available Ride Cab, Aluminum Wheels, 11R22.5, 2 Asset located in: Lake Worth, TX Steerable Air Lift Pusher Axle, Spring Suspension, 233 in Wheelbase, PTO, OX Bodies 1801 2007 Sterling LT9500 8x4 Tri/A Dump Truck 17 ft 9 in Long x 4 ft 3 in High Steel Body, S/N: 2FZMAZCV87AX38981 Round Bottom, Electric Roll Tarp C/W: Mercedes-Benz MBE4000 6 Cylinder 12.8 Usage: 376,489 Mi L Diesel Engine, 2006 US EPA Label, Engine Asset located in: Humble, TX Brake, Allison 6-Speed Automatic Transmission, Differential Lock, 20000 lb Front Axle, 66000 lb Rears, 86000 lb GVWR, Air Ride 1799 2014 Freightliner 114SD 8x4 Tri/A Dump Truck S/N: 3AKJG3DV2EDGA1049 Cab, Aluminum Front Wheels, 425/65R22.5 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 202 in hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller RTO-16908LL Manual Transmission, 12000 lb Front Axle, Wheelbase, PTO, OX Bodies 16 ft Long x 4 ft 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Steerable High Steel Body, Flat Bed, Electric Roll Tarp, Pintle Hitch Usage: 528,890 Mi Air Lift Pusher Axle, Airliner Air Ride Suspension, 202 in Wheelbase, 16 ft 5 in Long Asset located in: Lake Worth, TX x 2 ft 6 in High Steel Body, Electric Roll Tarp Usage: 525,886 Mi Asset located in: Lake Worth, TX

1 -+ "	D. A. H.	1	D. d. d.
Lot #	Details	Lot #	Details
1802	2003 Mack CHU613 8x4 Tri/A Dump Truck S/N: 1M1AA12Y23W149926 C/W: 6 Cylinder Diesel Engine, 22935 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22. 5 Rear Tires, Air Lift Pusher Axle, Air Ride Suspension, 196 in Wheelbase, PTO, 16 ft 5 in Long x 5 ft 6 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 706,035 Mi Asset located in: Humble, TX 1999 Mack RD600 8x4 Tri/A Dump Truck	1806	2016 Volvo VHD 8x4 T/A Dump Truck S/N: 4V5KC9EH4GN923100 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Volvo Automatic Transmission, Differential Lock, 20000 lb Front Axle, 40000 lb Rears, 53500 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 286 in Wheelbase, PTO, Strong Inc. 16 ft Long x 4 ft 8 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 408,393 Mi
1000	S/N: 1M2P270C4XM046117		Asset located in: Lake Worth, TX
	C/W: Mack E7 6 Cylinder 11.9 L Diesel 400 hp Engine, 1999 US EPA Label, 34470 Engine hrs, Manual Transmission, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Camelback Spring Suspension, 234 in Wheelbase, PTO, 16 ft Long x 3 ft 2 in High Steel Body, Flat Bed, Electric Roll Tarp, Split Swing Tailgate, Pintle Hitch Usage: 654,884 Mi	S/N: 1HSJGTKR3DJ30 ^o C/W: Cat CT13 13 L Die Engine hrs, Engine Brak Transmission, Different Axle, 40000 lb Rears, 5 ^o Cab, Aluminum Wheels Tires, 11R22.5 Rear Tire Hendrickson Air Ride So Wheelbase, PTO, 14 ft L Body, Bed Vibrator, Elec	2013 Cat CT660S 6x4 T/A Dump Truck S/N: 1HSJGTKR3DJ301284 C/W: Cat CT13 13 L Diesel Engine, 23623 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Air Ride Suspension, 199 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High
	Asset located in: Lake Worth, TX		Body, Bed Vibrator, Electric Roll Tarp, High-Lift Tailgate
1804	2015 Peterbilt 365 6x4 T/A Dump Truck		Usage: 250,468 Mi
	S/N: 1XPSD79X9FD262718		Asset located in: Lake Worth, TX
	C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, 14 ft Long x 4 ft 3 in High Steel Body, Electric Roll Tarp Usage: 598,800 Mi Asset located in: Humble, TX	1808	2012 International 7500 6x4 T/A Dump Truc S/N: 1HTWNAZR5CJ587087 C/W: International MaxxForce 10 6 Cylinder L Diesel 310 hp Engine, 2011 US EPA Label, 7272 Engine hrs, Eaton Fuller 10-Speed Man Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Hendrickson Haulmaax Suspension, 171 in Wheelbase, PTO, Warren ft Long x 4 ft High Steel Body, 14 cyd, Capac
1805	305 2018 Kenworth T370 4x2 S/A Dump Truck S/N: 2NKHHM7X3JM183693		Usage: 157,181 Mi Asset located in: Lake Worth, TX
	C/W: Paccar px7 6 Cylinder 6.7 L Diesel Engine,	1809	2006 International 7600 6x4 T/A Dump Truck
	2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 6-Speed Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 5.29:1 Axle Ratio, 33000 lb GVWR, Aluminum Outer Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Reyco Spring Suspension, 165 in Wheelbase, PTO, 11 ft Long x 3 ft 10 in High Steel Body, Electric Roll Tarp, Pintle Hitch Usage: 80,967 Mi Asset located in: Lake Worth, TX	1009	S/N: 1HTWYAHT76J239980 C/W: 6 Cylinder Diesel Engine, Engine Brake, Automated Transmission, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 248 in Wheelbase, PTO, 18 ft Long x 6 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 1,054,079 Km Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1811	2005 Mack CH613 6x4 T/A Dump Truck S/N: 1M2AA18Y65N157393 C/W: Mack 6 Cylinder Diesel Engine, 29778 Engine hrs, Manual Transmission, Differential Lock, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 223 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 10 in High Steel Body, Pintle Hitch Usage: 637,484 Mi Asset located in: Lake Worth, TX	1815A	1992 Ford LT8000F 6x4 T/A Dump Truck S/N: 1FDYU82A8NVA25956 C/W: Ford 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 54600 lb GVWR, 11R24.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 236 in Wheelbase, PTO, 17 ft Long x 3 ft High Steel Body, Flat Bed, Manual Roll Tarp, Pintle Hitch Usage: 336,571 Mi Asset located in: Midland, TX
1812	2002 Volvo VHD 8x4 T/A Dump Truck S/N: 4V5K99GH02N332959 C/W: Volvo 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Double Frame, TufTrac Suspension, PTO, 16 ft 6 in Long x 4 ft 2 in High Steel Body, Electric Roll Tarp Usage: 587,078 Mi Asset located in: Lake Worth, TX	-1816	1991 International 2574 6x4 T/A Dump Truck S/N: 1HSGGGRRXMH360976 C/W: Cummins NTC-350 6 Cylinder 14.0 L Diesel 350 hp Engine, Eaton Fuller 13-Speed Manual Transmission, Aluminum Front Wheels, 11R24.5, Double Frame, Hendrickson RT/RTE Series Suspension, 197 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Body, Manual Roll Tarp Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX
1814	1998 Mack CH613 6x4 T/A Dump Truck S/N: 1M2AA18Y6WW094985 C/W: Mack E7 6 Cylinder Diesel 427 hp Engine, 1999 US EPA Label, 20507 Engine hrs, Mack 13-Speed Manual Transmission, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Double Frame, Camelback Suspension, 216 in Wheelbase, PTO, Warren 15 ft Long x 3 ft 6 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 37,076 Mi Asset located in: Lake Worth, TX	1817	1981 Kenworth W900 6x4 T/A Dump Truck S/N: 1XKWDB9X3BK188647 C/W: Cat 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller RTO12513 Manual Transmission, 10600 lb Front Axle, 38000 lb Rears, 4.11:1 Axle Ratio, 48600 lb GVWR, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Galion 14 ft Long x 4 ft High Steel Body, Manual Roll Tarp Usage: 316,268 Mi Asset located in: Lake Worth, TX
1814A	1998 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUYDCYB2WP980791 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 370 hp Engine, 1998 US EPA Label, Engine Brake, Eaton Fuller RTLO-14610B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 192 in Wheelbase, PTO, OX Bodies 14 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Manual Roll Tarp, Ball hitch	1818	2016 Freightliner M2 106 4x2 S/A Dump Truck S/N: 1FVACXDU3GHGZ0167 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 152 in Wheelbase, PTO, Ledwell 10 ft Long x 3 ft High Body, Manual Roll Tarp, Double Tailgate Chutes Usage: 33,240 Mi Asset located in: Lake Worth, TX
1815	Usage: 864,969 Mi Asset located in: Midland, TX 1996 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUYDDYB6TH854798 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Rockwell 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 210 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 8 in High Body, Electric Roll Tarp, Pintle Hitch Usage: 647,766 Mi Asset located in: Lake Worth, TX	1819	2013 Kenworth T300 4x2 S/A Dump Truck S/N: 2NKHHM7XXDM348014 C/W: Paccar PX6 6 Cylinder 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 6897 Engine hrs, Engine Brake, Allison 6-Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 6.17:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 178 in Wheelbase, 12 ft Long x 0 ft 32 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 96,126 Mi Asset located in: Lake Worth, TX

			Page 109 01 3/4
Lot #	Details	Lot #	Details
1820	2008 International 4300 4x2 S/A Dump Truck S/N: 1HTMMAAN28J688226 C/W: International 6 Cylinder Diesel Engine, 2007 US EPA Label, 8057 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 19000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 153 in Wheelbase, PTO, 8 ft Long x 3 ft High Steel Body, Manual Roll Tarp, Pintle Hitch Usage: 188,392 Mi Asset located in: Lake Worth, TX	1822	Altec on 2016 Freightliner M2 106 4x2 Digger Derrick Truck S/N: 1FVACXDT4GHHL5754 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5611 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 46 ft Sheave Height, Rear Mounted, 18 in Auger, Pole Guide, Auxiliary Hydraulics, One-
1821	2005 Ford F-750 XL 4x2 S/A Dump Truck S/N: 3FRNF75Y05V169058 C/W: 1000 All Colonial V8 6.0 L Diesel 200 hp		Man Basket, 14 ft 6 in Body, Straight Down Outriggers, Rear Outriggers Usage: 75,001 Mi Asset located in : Lake Worth, TX
	Engine, 2004 US EPA Label, Allison Automatic Transmission, 9080 lb Front Axle, 17200 lb Rears, 25999 lb GVWR, 10R22.5, Spring Suspension, 158 in Wheelbase, PTO, Heil 10 ft Long x 3 ft 8 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 52,237 Mi Asset located in: Lake Worth, TX	1823	2017 Altec DB37 Tracked Digger Derrick S/N: 0817FT1063 C/W: Kubota 3 Cylinder Diesel Engine, 3800 lb Capacity, 30 ft Reach, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Remote Control w/ Cord, 12 in Rubber Tracks, T/A Trailer, Lunette Ring, Electric Brakes Usage: 368 Hr
1821A	•		Asset located in: Lake Worth, TX
	S/N: 1FD0W4HTXCEB65433 C/W: Ford V8 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft Long x 1 ft 3 in High Body, Pintle Hitch Usage: 188,303 Mi Asset located in: Lake Worth, TX	1824	2017 Altec L42M 42 ft on 2017 Freightliner M2 106 4x2 Bucket Truck S/N: 3ALACXDT9HDJE9096 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 280 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8165 Engine hrs, Allison 3500 Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb
1821B	2017 International 4300 4x2 Flatbed Dump Truck S/N: 3HAMMMMN4HL489029 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9826 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5,		GVWR, 11R22.5, 154 in Wheelbase, PTO, 400 lb Capacity, Center Mounted, Insulated One- Person Articulating-Telescopic Boom, Material Handling Jib, A-Outriggers, Rear Outriggers, 12 ft 6 in x 48 in Bed, Pintle Hitch Usage: 137,691 Mi Asset located in: Lake Worth, TX
	Spring Suspension, 223 in Wheelbase, 20 ft Long Steel Body Usage: 275,502 Mi		E OF 4 - Lot #'s: 1825, 1826, 1827, 1828
1821C	Asset located in: Humble, TX 2015 International 4300 4x2 Flatbed Dump	1825	Altec AA55 56 ft on 2017 International 4300
	Truck S/N: 3HAMMAAN7FL683988		4x2 Bucket Truck S/N: 1HTMMMMN2HH474504 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low

S/N: 3HAMMAAN7FL683988 C/W: 6 Cylinder 7.6 L Diesel 230 hp Engine, 2014 US EPA Label, 8701 Engine hrs, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring Suspension, 238 in Wheelbase, PTO, OX Bodies 20 ft Long Steel Body Usage: 269,403 Mi

Asset located in: Lake Worth, TX

S/N: 1HTMMMMN2HH474504 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9996 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 65,169 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1826	2017 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH161930 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8422 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Boom, Utility Body, Material Handling Jib, A- Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 72,652 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	CHOICI 1829	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN0HH474565 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 7992 Engine hrs, Allison Automatic Transmission, 11R22.5, 192 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, Pintle Hitch Usage: 61,145 Mi Asset located in: Lake Worth, TX
1827	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH474542 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11175 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, 700 lb Capacity, Rear Mounted, Insulated One-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 16 ft 3 in x 94 in Bed, Pintle Hitch Usage: 76,773 Mi	-1830	2017 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN5HH161964 C/W: Cummins ISB 6 Cylinder 6.7 L 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8818 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 92 in Bed, Pintle Hitch Usage: 53,675 Mi Asset located in: Lake Worth, TX
1828	Asset located in: Humble, TX 2016 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN3HH161820 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8357 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 196 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed Usage: 82,950 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1831	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH474556 C/W: Cummins Engine, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 330000 lb GVWR, 11R22.5, PTO, 700 lb Capacity, Center Mounted, Insulated Two- Person Articulated Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, Pintle Hitch Usage: 76,812 Mi Asset located in: Lake Worth, TX
		1832	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN3HH474544 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8552 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 16 ft x 94 in Bed, Pintle Hitch Usage: 80,587 Mi

Lot #	Details	Lot #	Details
CHOIC	E OF 3 - Lot #'s: 1833, 1834, 1835 2016 Altec AA55 56 ft on 2017 International	1837	2011 Terex Hi Ranger TL41-51 51 ft on 2011 Freightliner M2 4x2 Bucket Truck S/N: 1FVACXDT1BHBB4508 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 260
1000	4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH452529 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 13023 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 96 in Bed, Pintle Hitch Usage: 133,654 Mi Asset located in: Lake Worth, TX		hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 7733 Engine hrs, Eaton Fuller EH-8EX06A Automated Transmission, Differential Lock, 13220 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 6.14:1 Axle Ratio, 32220 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 177 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, One-Person Articulating-Telescopic Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 9 ft x 94 in Bed, Pintle Hitch Usage: 95,253 Mi Asset located in: Lake Worth, TX
1834	2017 Altec AA55 56 ft on 2017 International	-сноіс	E OF 2 - Lot #'s: 1838, 1839
1835	4300 4x2 Bucket Truck S/N: 1HTMMMMN0HH161936 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8428 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 66000 lb Rears, 11R22.5, 194 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulating-Telescopic Boom, Utility Body, A-Outriggers, Rear Outriggers, Remote Control w/Cord, 16 ft x 60 in Bed, Pintle Hitch Usage: 89,264 Mi Asset located in: Lake Worth, TX 2016 Altec AA55 55 ft on 2017 International	1838	2019 Altec AT41M 41 ft on 2019 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GTXKED88465 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7500 Ib Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, Insulated One-Person Articulating-Telescopic Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Bumper Mounted Winch, 13 ft 6 in x 94 in Bed Usage: 190,407 Mi Asset located in: Lake Worth, TX
	4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH474515 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8241 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, A-Outriggers, Rear Outriggers, 17 ft x 96 in Bed, Pintle Hitch Usage: 65,063 Mi Asset located in: Lake Worth, TX	1839	2019 Altec AT41M 40 ft on 2019 Ford F-550 4x2 Bucket Truck S/N: 1FDUF5GT7KED57111 C/W: Ford V8 6.7 L 330 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 7500 lb Front Axle, 19500 lb GVWR, 225/70R19.5, PTO, 400 lb Capacity, Center Mounted, Insulated One-Person Articulating-Telescopic Boom, Material Handling Jib, Straight Down Outriggers, Bumper Mounted Winch, 13 ft 6 in x 96 in Bed Usage: 149,980 Mi Asset located in: Lake Worth, TX
1836	2012 Altec AA755 55 ft on 2013 Freightliner 4x4 Bucket Truck S/N: 1FVDCXDTXDHBY0785 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10422 Engine hrs, Eaton Fuller 6- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor MS-21-14X Drive Axles, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Spring Suspension, 190 in Wheelbase, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Winch, Pintle Hitch Usage: 66,347 Mi Asset located in: Lake Worth, TX		

Details Lot# **Details** Lot # 1840 2012 Altec LRV55 55 ft on 2011 Freightliner 1847 2005 Mack CV713 8x4 Volumetric Mixer Truck M2 106 4x2 Forestry Bucket Truck S/N: 1M2AG11C65M015628 C/W: Mack 6 Cylinder Diesel Engine, 12565 S/N: 1FVACXDU3BDAU8449 Engine hrs, Engine Brake, Manual Transmission, 16540 lb Front Axle, 44000 lb Rears, 60540 lb GVWR, Air Ride Cab, Aluminum C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2009 US EPA Label, Requires Diesel Exhaust Fluid, 15196 Engine hrs, Eaton Fuller Front Wheels, 425/65R22.5 Front Tires, 11R24. FS-6406A 6-Speed Manual Transmission, 5 Rear Tires, Steerable Air Lift Pusher Axle, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-Double Frame, Camelback Spring Suspension, 21-145 Drive Axles, 4.88:1 Axle Ratio, 33000 lb 252 in Wheelbase, PTO, 2005 Cemen Tech GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 187 in MCD10-150 Mixer Unit Wheelbase, PTO, 400 lb Capacity, Front Usage: 265,336 Mi Mounted, Insulated One-Person Articulating-Asset located in: Lake Worth, TX Telescopic Boom, Chip Body, A-Outriggers, 11 1848 2004 Kenworth T800 8x4 Volumetric Mixer ft x 92 in Bed Usage: 84,033 Mi Notes: ODOMETER DISCREPANCY-UNIT S/N: 1NKDXUTX94J051508 SHOWS 84,033, TITLE SHOWS 999,999, TITLE C/W: Cat C12 6 Cylinder 11.9 L Diesel 380 hp BRANDED NOT ACTUAL MILEAGE Engine, 2003 US ÉPA Label, 13738 Engine hrs, Eaton Fuller 8LL Manual Transmission, 4.33:1 Asset located in: Lake Worth, TX Axle Ratio, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double 1843 Versalift on 1999 Ford F-450 4x2 Crew Cab **Bucket Truck** Frame, Hendrickson RT/RTE Series S/N: 1FDXW46F9XEA93643 Suspension, 224 in Wheelbase, PTO C/W: V8 7.3 L Diesel Engine, Automatic Usage: 52,449 Mi Transmission, 5790 lb Front Axle, 10880 lb Rears, 15000 lb GVWR, 225/70R19.5, Spring Asset located in: Lake Worth, TX Suspension, 176 in Wheelbase, Center Mounted, Insulated One-Person Articulating-Telescopic Boom, Utility Body, Out and Down Outriggers, 13 ft 9 in x 96 in Bed Usage: 143,468 Mi CHOICE OF 2 - Lot #'s: 1849, 1850 1849 2018 Freightliner 114 SD 10x4 Mixer Truck Asset located in: Lake Worth, TX S/N: 3ALHG3DV5JDJL7485 1844 2011 Ford F-550 XL 4x2 Chipper Truck C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel S/N: 1FDUF5GT2BEB53610 Exhaust Fluid, 14464 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, C/W: 6 Cylinder 6.7 L 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Automatic Transmission, 6500 lb Front Axle, 14704 lb Rears, 19500 lb GVWR, 225/70R19.5. Axle Ratio, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 165 in Wheelbase, 11 ft x x 78 in High Body, Pintle Hitch Usage: 101,174 Mi Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, Notes: DEFICIENCIES NOTED - PLEASE SEE 248 in Wheelbase, PTO, Beck 11 cyd Mixer THE INSPECTION REPORT Unit, 3 Removable Chutes Asset located in: Humble, TX Usage: 51,410 Mi Asset located in: Lake Worth, TX 1846 2009 Peterbilt 340 6x4 Volumetric Mixer Truck S/N: 2NPRLN0X69M771130 1850 2018 Freightliner 114 SD 10x4 Mixer Truck C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 315 S/N: 3ALHG3DV7JDJM2090 hp Engine, 2008 US EPA Label, 15485 Engine hrs, Eaton Fuller RTO-11908LL 8LL Manual C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12913 Engine hrs, Engine Brake, Transmission, 20000 lb Front Axle, 46000 lb Rears, Dana D46-170HP Drive Axles, 4.56:1 Allison Automatic Transmission, Differential Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Lock, Air Ride Cab, 425/65R22.5 Front Tires,

Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring over Walking Beam

Suspension, 240 in Wheelbase, PTO, 2008

Cemen Tech MCD8-130 8 cyd Mixer Unit

Asset located in: Lake Worth, TX

Usage: 141,364 Mi

11R22.5 Rear Tires, Steerable Air Lift Pusher

Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Spring Suspension, 238 in Wheelbase,

Beck 11 cyd Mixer Unit, 3 Removable Chutes

Asset located in: Lake Worth, TX

Usage: 107,793 Mi

			Page 1/3 of 5/4
Lot #	Details	Lot #	Details
СНОІС	CHOICE OF 3 - Lot #'s: 1851, 1852, 1853		E OF 3 - Lot #'s: 1854, 1855, 1856
1851	2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV0JDJM2089 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, Double Frame, TufTrac Spring Suspension, 249 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 175,339 Mi Asset located in: Lake Worth, TX	1854	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJL7486 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17360 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 205,429 Mi Asset located in: Lake Worth, TX
1852	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJM2087 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 13808 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 176,719 Mi Asset located in: Lake Worth, TX	1855	2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV3JDJL7484 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, Double Frame, TufTrac Suspension, 248 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 208,663 Mi Asset located in: Lake Worth, TX
1853	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV9JDJM2088 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14895 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, 11 cyd Mixer Unit, 3 Removable Chutes Usage: 198,768 Mi Asset located in: Lake Worth, TX	1856	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV0JDJM2092 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15416 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 184,716 Mi

Lot # **Details** Lot # Details 1860 2019 Freightliner 114SD 6x4 Mixer Truck S/N: 1FVHG3DV7KHJS0957 CHOICE OF 2 - Lot #'s: 1857, 1858 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15048 Engine hrs, Engine Brake, 1857 2014 Kenworth W900 8x4 Mixer Truck Allison Automatic Transmission, Differential S/N: 1NKWL70X3EJ387392 Lock, 20000 lb Front Axle, 46000 lb Rears, C/W: Cummins 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Exhaust Fluid, Automatic Transmission, Double Rear Tires, Dual Steering Boxes, TufTrac Differential Locks, 20000 lb Front Axle, 46000 Suspension, 232 in Wheelbase, PTO, 11 cyd lb Rears, 66000 lb GVWR, Aluminum Wheels, Mixer Unit, 3 Removable Chutes, Remote 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Control w/Cord Trailing Tag Axle, Dual Steering Boxes, Double Usage: 147,481 Mi Frame, Hendrickson Haulmaax Rubber over Asset located in: Lake Worth, TX Walking Beam Suspension, 3 Removable 1861 2019 Freightliner 114 SD 6x4 Mixer Truck Usage: Not Available S/N: 1FVHG3DV9KHKF4834 Asset located in: Lake Worth, TX C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, CARB 1858 2014 Kenworth W900 8x4 Mixer Truck Compliant, Requires Diesel Exhaust Fluid, S/N: 1NKWL70X1EJ387391 14290 Engine hrs, Allison Automatic C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17553 Engine hrs, Allison Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front 4500 Automatic Transmission, 20000 lb Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Axle, 46000 lb Rears, Meritor RT-46-160 Drive TufTrac Suspension, 232 in Wheelbase, PTO, Axles, 4.89:1 Axle Ratio, 66000 lb GVWR 10.5 cyd Mixer Unit, 3 Removable Chutes, Aluminum Wheels, 385/65R22.5 Front Tires, Remote Control w/Cord 11R22.5 Rear Tires, Trailing Tag Axle, Dual Usage: 167,132 Mi Steering Boxes, Hendrickson Haulmaax Rubber Asset located in: Lake Worth, TX over Walking Beam Suspension, 250 in Wheelbase, PTO, 2 Removable Chutes, Remote Control w/Cord Usage: 182,221 Mi CHOICE OF 3 - Lot #'s: 1862, 1863, 1864 Asset located in: Lake Worth, TX 1862 2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV4JDJW4872 CHOICE OF 3 - Lot #'s: 1859, 1860, 1861 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13917 Engine hrs, Engine Brake, 1859 2019 Freightliner 114 SD 6x4 Mixer Truck Allison 4500 Automatic Transmission, S/N: 1FVHG3DV5KHJS0956 Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Alumont Wheels, 425/65R22.5 Front Tires, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 11R22.5 Rear Tires, Dual Steering Boxes, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425 TufTrac Spring Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Remote Control w/Cord Steering Boxes, TufTrac Spring Suspension, 234 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Usage: 143,981 Mi Asset located in: Lake Worth, TX Removable Chutes, Remote Control w/Cord Usage: 133,211 Mi 1863 2018 Freightliner 114 SD 6x4 Mixer Truck Asset located in: Lake Worth, TX S/N: 3ALHG3DVXJDJW4875 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14693 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Spring

Suspension, 232 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote

Asset located in: Lake Worth, TX

Control w/Cord Usage: 159,856 Mi

Lot #	Details	Lot #	Details
1864	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV6JDJW4873 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410	CHOIC	E OF 3 - Lot #'s: 1868, 1869, 1870
СНОІС	hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 16397 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Spring Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 171,963 Mi Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1865, 1866, 1867	1868	2015 Freigthliner 114SD 6x4 Mixer Truck S/N: 1FVHG3DV9FHGD2918 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 20129 Engine hrs, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, PTO, 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 242,364 Mi Asset located in: Lake Worth, TX
		1869	·
1865	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV8JDJW4874 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15138 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Spring Suspension, 216 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 174,579 Mi	1809	2015 Freightliner 114SD 6x4 Mixer Truck S/N: 3ALHG3DV8FDGP8010 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15144 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 231 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 162,097 Mi
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
1866	2018 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV1JDJW4876 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14061 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit Usage: 139,282 Mi	-1870	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DVXFHGC6643 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 186,822 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
1867	2017 Freightliner 114 SD 6x4 Mixer Truck	CHOIC	E OF 3 - Lot #'s: 1871, 1872, 1873
	S/N: 3ALHG3DV6HDJG5267 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, Requires Diesel Exhaust Fluid, 13679 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 36,162 Mi Asset located in: Lake Worth, TX	1871	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV8FDGK8255 C/W: Detroit DD13 6 Cylinder Diesel Engine, 18450 Engine hrs, Engine Brake, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 234 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 204,227 Mi

Page 176 of 574 **Details** Lot# **Details** Lot # 1872 1875 2015 Freightliner 114 SD 6x4 Mixer Truck 2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV6FHGC6641 S/N: 1FVHG3DV7FHGD2917 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19288.9 Engine hrs, Engine Exhaust Fluid, 19762.9 Engine hrs, Engine Brake, Allison 4000 Automatic Transmission, Brake, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Beck 10.5 Double Frame, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes cyd Mixer Unit, 3 Removable Chutes, Remote Usage: 225,694 Mi Control w/Cord Usage: 201,518 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1873 2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV0FHGD3309 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, CHOICE OF 2 - Lot #'s: 1876, 1877 20105.7 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 1876 2015 Freightliner 114 SD 6x4 Mixer Truck 22000 lb Front Axle, 46000 lb Rears, Meritor RT-S/N: 1FVHG3DVXFHGS0264 46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Exhaust Fluid, Allison 4500 Automatic Steering Boxes, Double Frame, Rubber over Transmission, 20000 lb Front Axle, 46000 lb Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. Chutes, Remote Control w/Cord 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Usage: Not Available Boxes, Double Frame, Hendrickson Haulmaax Asset located in: Lake Worth, TX Suspension, 222 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w /Cord CHOICE OF 2 - Lot #'s: 1874, 1875 Usage: 34,426 Mi Notes: ADDITIONAL INFORMATION **AVAILABLE IN OFFICE:** 1874 2015 Freightliner 114 SD 6x4 Mixer Truck Asset located in: Lake Worth, TX S/N: 3ALHG3DVXFDGK8256

C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 5810 Engine hrs, Engine Brake, Allison 6-Speed Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.86:1 Axle Ratio, 68000.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 204,689 Mi

Asset located in: Lake Worth, TX

1877 2015 Freightliner 114 SD 6x4 Mixer Truck

S/N: 1FVHG3DV2FHGN1430 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 350 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 222 in Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 36,664 Mi

Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE;

Asset located in: Lake Worth, TX

1878 2014 Freightliner 114 SD 6x4 Mixer Truck

S/N: 1FVHG3DV7EHFW3536 C/W: Detroit DD15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18254 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, Composite Water Tank Usage: 185,216 Mi

Lot #	Details	Lot #	Details
1879	2015 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C9FM028775 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14199 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5, Dual Steering Boxes, Camelback Suspension, 234 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes Usage: 133,877 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV	1886	2003 Peterbilt 357 6x4 Mixer Truck S/N: 1NPALT0X53D802186 C/W: Cat C10 6 Cylinder Diesel 305 hp Engine, 7071 Engine hrs, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, 3 Removable Chutes Usage: 266,861 Mi Notes: LOCATED-IN-HOUSTON-TX Asset located in: Humble, TX
	PRIOR TO BIDDING	1888	2002 Kenworth T800 6x4 Mixer Truck S/N: 1NKDLU0X12J703485 C/W: Cat C-12 6 Cylinder 11.9 L Diesel 505 hp Engine, 2002 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 425/65R22. 5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 3 Removable Chutes Usage: 159,586 Mi Asset located in: Lake Worth, TX
1881	Asset located in: Lake Worth, TX 2007 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C07M061944 C/W: Mack AMI 6 Cylinder Diesel 325 hp Engine, 10175 Engine hrs, Mack 10-Speed Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Camelback Spring Suspension, 227 in		
	Wheelbase, CBMW 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 38,616 Mi Asset located in : Lake Worth, TX		S/N: 1M2E178CXXM002704 C/W: Mack EM7 6 Cylinder 728 cid Diesel Engine, 1998 US EPA Label, 47454 Engine hrs, 8LL Manual Transmission, Aluminum Front Wheels, 445/65R22.5, Walking Beam Suspension, 180 in Wheelbase, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 89,880 Mi Asset located in: Lake Worth, TX
1884	2005 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C75M034222 C/W: Mack 6 Cylinder Diesel Engine, 28940 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum	1890	
	Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 229 in Wheelbase, 3 Removable Chutes Usage: 337,303 Mi Asset located in: Lake Worth, TX		
1885	2006 Peterbilt 357 6x4 Mixer Truck S/N: 1NPALT0X46D890572 C/W: Cat 6 Cylinder Diesel Engine, 9701 Engine hrs, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Aluminum Wheels, 445/65R22.5 Front Tires,		
	12R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Suspension, 216 in Wheelbase, PTO, 3 Removable Chutes, Remote Control w/Cord Usage: 267,072 Mi Asset located in: Lake Worth, TX	1891	1997 Freightliner FL70 4x2 Attenuator Truck S/N: 1FV3HLAA4VH739867 C/W: Cummins C8.3 8.3 L Diesel Engine, 1996 US EPA Label, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 216 in Wheelbase, Flatbed Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1892	2017 Freightliner M2 106 4x2 Attenuator Truck S/N: 3ALACWDT6HDJE8126 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 4774 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, 5.13:1 Axle Ratio, 26000 lb GVWR, 10R22.5, Airliner Suspension, 282 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 84,841 Mi Asset located in: Lake Worth, TX	1898	2020 Peterbilt 567 6x4 Roll-Off Truck S/N: 1NPCL40X3LD650696 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10554 Engine hrs, Engine Brake, 10-Speed Manual Transmission, Triple Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 276 in Wheelbase, PTO, 2019 Galbreath U5-OR-174 Roll-Off Body, 23 ft 4 in Hoist, Winch Usage: 285,990 Mi
1893	2012 International 4300 4x2 Attenuator Truck S/N: 3HAJTSKL8CL606518		Asset located in: Lake Worth, TX
	C/W: International 6 Cylinder Diesel Engine, 11142 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 214 in Wheelbase, Flatbed Usage: 157,339 Mi Asset located in: Lake Worth, TX	1899	2013 Freightliner 114 6x4 Roll-Off Truck S/N: 3ALHG3DV8DDFF1962 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 16000 lb Front Axle, 44000 lb Rears, 60000 lb GVWR, Air Ride Cab, 295/75R22.5, Double Frame, TufTrac Suspension, 23 ft 4 in Hoist Usage: 472,556 Mi
1894A	2017 Ford F-650 4x2 Attenuator Truck	10001	Asset located in: Lake Worth, TX
	S/N: 1FDNF6DC7HDB04478 C/W: V8 6.7 L Diesel 270 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 218 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 91,813 Mi Asset located in: Lake Worth, TX	1899A	2007 Volvo VHD 6x4 Roll-Off Truck S/N: 4V5KC9GG07N427019 C/W: Volvo D12D395 6 Cylinder 12.1 L Diesel 395 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller 8LL Manual Transmission, 18740 lb Front Axle, 44000 lb Rears, 4.11:1 Axle Ratio, 62740 lb GVWR, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 285/75R24. Rear Tires, Double Frame, Hendrickson RT/RT Series Suspension, 240 in Wheelbase, PTO, 23 ft Hoist Usage: 727,039 Mi
1895	2008 Hino 338 4x2 Attenuator Truck S/N: 5PVNV8JT682S50910 C/W: J08-TW 6 Cylinder Diesel 260 hp Engine, 2007 US EPA Label, 684 Engine hrs, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring		Notes: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, CANNOT BE DRIVEN. TEMP TAGS WILL NOT BE ISSUED Asset located in: Lake Worth, TX
	Suspension, 196 in Wheelbase, Flatbed, Arrow Board, In-Cab Arrow Board Controller Usage: 194,141 Mi Asset located in : Lake Worth, TX	1900	2005 Peterbilt 357 6x4 Roll-Off Truck S/N: 1NPALTOXX5N857701 C/W: Cat C11 6 Cylinder Diesel Engine, 1888 Engine hrs, Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 266 in Wheelbase, PTO, GH 1560 Roll-Off Body, 23 ft Hoist Usage: Not Available Asset located in: Lake Worth, TX
1897	2007 International 8000 4x2 Toter Truck S/N: 1HSHWAHN67J535045 C/W: 6 Cylinder Diesel Engine, 21882 Engine hrs, Eaton Fuller Manual Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 156 in Wheelbase Usage: 239,028 Mi Asset located in: Midland, TX		

Lot #	Details	Lot #	Details
1901	2022 Chevrolet Silverado 5500HD 4x2 Rollback Truck S/N: 1HTKHPVM6NH675305 C/W: Navistar Duramax V8 6.6 L Diesel 350 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7940 lb Front Axle, 15000 lb Rears, 4.10:1 Axle Ratio, 22940 lb GVWR, 225/70R19.5, Spring Suspension, 232 in Wheelbase, PTO, Century Steel Wrecker Body, 5000 lb Winch Capacity, Tow Dollies Usage: 60,704 Mi Notes: X2-CNV Dash Vin from photo; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1904B	2007 Gulf Stream Independence Motor Home S/N: 4UZACLBW57CZ34853 C/W: Air Conditioner, Automatic Transmission, 1899.5 hrs Carrier Engine, Cummins 6 Cylinder Diesel Engine, 2007 US EPA Label, 3 Slide Outs, Power Entrance Step, Power Leveling Jacks, Power Awning, Generator w/ 266 hrs Usage: 82,082 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
		1905	1999 Prevost H3-45 Motor Home S/N: 2PCV33491X1013393 C/W: Air Conditioner, Allison Automatic Transmission, Detroit 6 Cylinder 12.7 L 500 hp Engine, Sleeps 2 People, Clothes Washer & Dryer, Power Awning, Power Tech 25 kW Generator
1902	2020 Ram 5500 4x4 Rollback Truck S/N: 3C7WRNDL4LG136586		Usage: 142,465 Mi Asset located in: Lake Worth, TX
	C/W: Cummins 6 Cylinder 6.7 L Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 205 in Wheelbase, PTO, Danco 12SR20 Rollback Body, 20 ft x 96 in Bed, Ramsey 8000 lb Winch, Hydraulic Wheel Lift, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 70,701 Mi Asset located in: Lake Worth, TX	1906	S/N: 5PVNJ8JV5J4S67771 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9282 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Carrier Reefer Unit, 8457 Reefer Total Hours:, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate
1903	2019 Isuzu NRR 4x2 COE Rollback Truck S/N: JALE5W160K7304175 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5916 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500.0 lb GVWR, 225/70R19.5, Spring Suspension, 178 in Wheelbase, PTO, Wet Kit, 21 ft 6 in x 96 in Bed, Aluminum Frame, 18000 lb Winch Usage: 196,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		Usage: 171,017 Mi Notes: SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Lake Worth, TX
		1907	2018 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JL0J4S52089 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Hendrickson Air Ride Suspension, 188 in Wheelbase, Carrier Reefer Unit, 9213 Reefer Total Hours:, Morgan 16 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 184,843 Mi
1904A	S/N: 1F6NF53Y590A00112		Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2009 US EPA Label, 3 Slide Outs, Power Entrance Step, Power Leveling Jacks, Power Awning, Onan RV QG 5500 LP 5.5 kW Generator, Rear View Camera Usage: 23,619 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1908	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JV1H4S66305 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel 11P22 5 Air Pide Suspension, Thermo

Steel, 11R22.5, Air Ride Suspension, Thermo King T-1080R Whisper Reefer Unit, 8637 Reefer Engine Hours:, 8637 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 293,547 Mi

Lot #	Details	Lot #	Details
1909	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT8H4S57955 C/W: Hino 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 254 in Wheelbase, Thermo King T-1080R Reefer Unit, 9481 Reefer Engine Hours:, 9481 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 297,803 Mi Asset located in: Lake Worth, TX	1913	Truck S/N: 3ALACWFC0KDKL2452 C/W: Cummins B 6 Cylinder 6.7 L Diesel 250 hp Engine, 2018 US EPA Label, 9375 Engine hrs, Eaton Fuller 3 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Thermo King T- 680R Reefer Unit, Morgan 24 ft x 102 in Wide x 96 in High Body, Curbside Door, Liftgate Usage: 332,255 Mi Asset located in: Lake Worth, TX
1910 CHOIC 1911	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT2H4S57952 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 254 in Wheelbase, Thermo King T-1080R Whisper Reefer Unit, 5965 Reefer Engine Hours:, 5965 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 322,392 Mi Asset located in: Lake Worth, TX E OF 2 - Lot #'s: 1911, 1912 2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JTXH4S57455 C/W: Hino 6 Cylinder Diesel Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic	1914	
1912	Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, Carrier Transicold Reefer Unit, 12952 Reefer Engine Hours:, 16707 Reefer Total Hours:, Supreme 24 ft x 102 in Wide x 98 in High Body, Curbside Door Usage: 237,435 Mi Asset located in: Lake Worth, TX 2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT1H4S57439 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb	1915	2016 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWDT5GDHE5396 C/W: Cummins 6 Cylinder Diesel Engine, 11342 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 256 in Wheelbase, Carrier Reefer Unit, 13046 Reefer Total Hours:, Kidron 24 ft x 102 in Wide x 97 in High Body Usage: 297,043 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL

S/N: 5PVNJ8JT1H4S57439 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 252 in Wheelbase, Carrier Reefer Unit, Supreme 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Walk-Up Ramp, PROFESSIONALLY-MAINTAINED-FLEET-

VEHICLE-PAG Usage: 284,077 Mi

Asset located in: Lake Worth, TX

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Lot #	Details	Lot #	Details
1916	2015 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACXDT1FDGF1570 C/W: Cummins ISB 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10137 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 5.88:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, steel, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Carrier Transicold Reefer Unit, 11638 Reefer Total Hours:, Morgan 22 ft x 102 in Wide x 97 in High Body, Liftgate	1920	2019 Isuzu NQR 4x2 COE Refrigerated Truck S/N: JALE5W167K7900576 C/W: Isuzu 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6830 lb Front Axle, 12980 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 150 in Wheelbase, Thermo King T-680R Reefer Unit, supreme 18 ft x 102 in Wide x 92 in High Body, Curbside Door, Liftgate Usage: 179,717 Mi
	Usage: 313,978 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD	1921	2017 Chevrolet G3500 4x2 Refrigerated Truck S/N: 1GB0GRFF4H1344050 C/W: V8 Gasoline Engine, 8673 Engine hrs, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, Aluminum Wheels, 245/75R16, Spring Suspension, 139 in Wheelbase, Thermo King V-520 NM Max Reefer Unit, GCE 11 ft x 88 in Wide x 72 in High Body, Curbside Door Usage: 328,694 Mi Asset located in: Lake Worth, TX
Truck S/N: 1FVACWDT0CHBS3944 C/W: Cummins 6 Cylinder Diesel Er Requires Diesel Exhaust Fluid, 1194 hrs, Automated Transmission, 1000 Axle, 17500 lb Rears, 26000 lb GVW Airliner Air Ride Suspension, 270 in Thermo King Reefer Unit, Morgan 2 Wide x 97 in High Body, Liftgate Usage: 324,437 Hr Notes: THIS UNIT RUNS BUT MAY DEFICIENCIES IN ITS POLLUTION OF SYSTEMS WITH LIABILITIES OUTLE TEXAS ADMINISTRATIVE CODE SE 114.20 AND 114.50. THIS MAY API OPERATE THE UNIT PRIOR TO THE RESTORATION OF ALL POLLUTION SYSTEMS OR DEVICES AS ORIGINA EQUIPPED. BUYER OF THIS UNIT NACKNOWLEDGEMENT FORM OF TE PRIOR TO REMOVAL OF UNIT FROM Asset located in: Lake Worth, TX	2012 Freightliner M2 106 4x2 Refrigerated Truck S/N: 1FVACWDT0CHBS3944 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11946 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Thermo King Reefer Unit, Morgan 26 ft x 96 in Wide x 97 in High Body, Liftgate Usage: 324,437 Hr	-1922	2016 International 4300 4x2 Beverage Truck S/N: 1HTMMMML3GH225609 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 6-Speed Automatic Transmission, 8618 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 235 in Wheelbase, Mickey 21 ft Body, 36 in Wide Bays, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 343,147 Mi Asset located in: Lake Worth, TX
	DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	1923	2018 Peterbilt 337 4x2 Van Truck S/N: 2NP2HM7X2JM491941 C/W: Paccar B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7218 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 6.17:1 Axle Ratio, 32000 lb GVWR, 275/80R22.5, Spring Suspension, 275 in Wheelbase, Wabash 24 ft x 102 in Wide x 88 in High Body, Liftgate, EQUIPMENT-FROM- YELLOW-CORP Usage: 110,293 Mi Asset located in: Lake Worth, TX
	S/N: 3HAMMMML4JL736540 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5440 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 156,143 Mi Asset located in: Lake Worth, TX	1924	2017 Peterbilt 337 4x2 Van Truck S/N: 2NP2HM6X2HM409086 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9288 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, Dana S21170 Drive Axles, 4.56: 1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 260 in Wheelbase, Morgan 24 ft x 102 in Wide x 101 in High Body, Curbside Door, Liftgate Usage: 312,144 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1925	2015 Peterbilt 337 4x2 Van Truck S/N: 2NP2HJ7X9FM275736 C/W: Paccar ISL 6 Cylinder 8.9 L Diesel 260 hp Engine, Requires Diesel Exhaust Fluid, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 4.11:1 Axle Ratio, 33000.0 lb GVWR, Aluminum Outer Wheels, 295 /75R22.5, Paccar Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 287,399 Mi Asset located in: Lake Worth, TX	CHOICE 1932	E OF 5 - Lot #'s: 1932, 1933, 1934, 1935, 1936 2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S74135 C/W: Hino 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 7853 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 252,005 Mi
			Asset located in: Lake Worth, TX
1927	2020 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV4L4S75931 C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5949 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 237,576 Mi Asset located in: Lake Worth, TX	1933	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3K4S70413 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6861 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hino Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body Usage: 195,635 Mi Asset located in: Lake Worth, TX
		1934	2019 Hino 268 4x2 Van Truck
CHOIC 1928	CHOICE OF 2 - Lot #'s: 1928, 1929 1928 2020 Hino 268 4x2 Van Truck S/N: 5PVNE8JVXL4S57650 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 5054 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan		S/N: 5PVNJ8JVXK4S70473 C/W: Hino Motors J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7082 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 199,209 Mi Asset located in: Lake Worth, TX
	26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 243,455 Mi	1935	2019 Hino 268 4x2 Van Truck
1929	Asset located in: Lake Worth, TX 2020 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0L4S57611 C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body,	1930	S/N: 5PVNJ8JV3K4S70475 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 Ib Front Axle, 19000 Ib Rears, 25950 Ib GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in Wide x 103 in High Body Usage: 220,034 Mi Asset located in: Lake Worth, TX
	Liftgate Usage: 274,702 Mi Asset located in: Lake Worth, TX	1936	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV1K4S70474 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8646 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 227,375 Mi

Lot # **Details** Lot # Details 1944 2016 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXG4S61134 CHOICE OF 4 - Lot #'s: 1937, 1938, 1939, 1940 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 999 Engine hrs, Allison 1937 2019 Hino 268 4x2 Van Truck Automatic Transmission, 10000 lb Front Axle, S/N: 5PVNJ8JV5K4S71661 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, C/W: Hino 6 Cylinder Diesel Engine, 2018 US Spring Suspension, 270 in Wheelbase, Morgan EPA Label, Requires Diesel Exhaust Fluid, 7844 26 ft x 102 in Wide x 103 in High Body, Liftgate Engine hrs. Allison Automatic Transmission. Usage: 466,707 Mi 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x Asset located in: Lake Worth, TX 102 in Wide x 103 in High Body, Walk-Up Ramp, CHOICE OF 3 - Lot #'s: 1945, 1946, 1947 Usage: 264,419 Mi Asset located in: Lake Worth, TX 1945 2016 Hino 268 4x2 Van Truck 1938 2019 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0G4S54665 C/W: J08E-VC 6 Cylinder Diesel 220 hp Engine, 2015 US EPA Label, CARB Compliant, Requires S/N: 5PVNJ8JV7K4S70785 C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11645 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in Hendrickson Air Ride Suspension, 271 in High Body, Liftgate Wheelbase, Morgan 26 ft x 102 in Wide x 103 Usage: 779,914 Mi in High Body, Liftgate Asset located in: Lake Worth, TX Usage: 394,055 Mi 1946 2015 Hino 268 4x2 Van Truck Asset located in: Lake Worth, TX S/N: 5PVNJ8JV7F4S58836 1939 2018 Hino 268 4x2 Van Truck C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2014 US EPA Lábel, CARB Compliant, S/N: 5PVNJ8JV9J4S67062 C/W: Hino 6 Cylinder Diesel Engine, 2017 US Requires Diesel Exhaust Fluid, 999 Engine hrs. EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, Allison Automatic Transmission, 10000 lb 19000 lb Rears, 25950 lb GVWR, 11R22.5 Spring Suspension, 274 in Wheelbase, 26 ft x Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, Mickey 26 ft x 102 in Wide x 103 in High Body, 102 in Wide x 98 in High Body, Liftgate Usage: 762,239 Mi Liftgate Asset located in: Lake Worth, TX Usage: 226,779 Mi 1947 2014 Hino 268 4x2 Van Truck Asset located in: Lake Worth, TX S/N: 5PVNE8JT3E4S55904 C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel 1940 2018 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV5J4S67334 Exhaust Fluid, Automatic Transmission, 10000 C/W: 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Supreme Corp 24 ft x 102 in Wide x 103 in High Wheelbase, Morgan 26 ft x 102 in Wide x 103 Body, Liftgate in High Body, Liftgate Usage: 665,898 Mi Usage: Not Available Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1948 2013 Hino 268 4x2 Van Truck S/N: 5PVNE8JVXD4S52658 C/W: Hino Motors J08E-VC 6 Cylinder 7.7 L CHOICE OF 2 - Lot #'s: 1943, 1944 Diesel 220 hp Engine, 2012 US ÉPA Label, Requires Diesel Exhaust Fluid, 20 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, 1943 2017 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0H4S55963 Spring Suspension, 239 in Wheelbase, Morgan C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel 20 ft x 102 in Wide x 93 in High Body 230 hp Engine, 2016 US EPA Label, Requires Usage: 163,671 Mi Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Asset located in: Lake Worth, TX Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate

Usage: 302,562 Mi

			Page 184 01 374
Lot #	Details	Lot #	Details
1948A	2013 Hino 268 4x2 Van Truck S/N: 5PVNE8JT8D4S54925 C/W: 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 251 in Wheelbase, Reading 24 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 733,693 Mi Asset located in: Lake Worth, TX	1953	2010 Toyota Hino 268 4x2 Van Truck S/N: 5PVNE8JV3A4S51573 C/W: Hino J08E-TV 6 Cylinder Diesel 220 hp Engine, 2009 US EPA Label, 999 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 269 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 542,329 Mi Asset located in: Lake Worth, TX
CHOICE	E OF 2 - Lot #'s: 1949, 1950	1955	2020 Freightliner M2 112 4x2 Moving Van
1949	2017 Hino 165 4x2 Van Truck S/N: 5PVNE8JV8H4S55600 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 235 in Wheelbase, Supreme 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 691,347 Mi Asset located in: Lake Worth, TX		Truck S/N: 3ALAC4DV3LDME8608 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2019 US EPA Label, 9094 Engine hrs, Engine Brake, Eaton Fuller FAO-14810C Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-21-160 Drive Axles, 3.07:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 533,064 Mi
1950	2016 Hino 268 4x2 Van Truck		Asset located in: Lake Worth, TX
	S/N: 5PVNE8JV7G4S54761 C/W: 6 Cylinder Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 253 in Wheelbase, Supreme 26 ft x 96 in Wide x 102 in High Body, Liftgate Usage: 601,140 Mi Asset located in: Lake Worth, TX	1956	2020 Freightliner M2 106 4x2 Van Truck S/N: 3ALACXFC5LDMA4042 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, MARION 26 ft x 102 in Wide x 109 in High
1951	2013 Hino 165 4x2 Van Truck		Body, Liftgate Usage: 294,302 Mi
	S/N: 5PVNE8JT2D4S55035 C/W: 6 Cylinder Diesel Engine, Requires Diesel		Asset located in: Lake Worth, TX
	Exhaust Éluid Automatic Transmission 10000	1961	2019 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC8KDKK6432 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, Smyrna 26 ft x 96 in Wide x Body, Liftgate

CHOICE OF 2 - Lot #'s: 1952, 1953

1952 2010 Hino 165 4x2 Van Truck

S/N: 5PVNJ8JV5A4S52235 C/W: Hino Motors J08E-TV 6 Cylinder 7.7 L Diesel 220 hp Engine, 2009 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 413,815 Mi

Asset located in: Lake Worth, TX

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

Usage: Not Available

PRIOR TO BIDDING

Lot #	Details	Lot #	Details
CHOIC 1962	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB3KDKH7131 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2018 US EPA Label, 5566 Engine hrs, Allison 2200 4 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19- 14X Drive Axles, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 214,259 Mi Asset located in: Lake Worth, TX	1966	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFCXJDJZ7465 C/W: Cummins B 6 Cylinder 6.7 L 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10762.9 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 256 in Wheelbase, Morgan 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 379,528 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1963	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB4KDKH7137 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,942 Mi Asset located in: Lake Worth, TX	1967	2018 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWFB4JHJH4986 C/W: Detroit DD5 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7569.8 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000.0 lb GVWR, Air Ride Cab, 11R22. 5, Airliner Air Ride Suspension, 270 in Wheelbase, PTO, AMH 26 ft x 102 in Wide x 97 in High Body, Liftgate, Asset includes a 2.5Ton pallet jack and straps Usage: 288,869 Mi Notes:
1964	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC5JDJH4350 C/W: Cummins 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 312,803 Mi Asset located in: Lake Worth, TX	1968	Asset located in: Livingston, LA 2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC6JDJK7266 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7811 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Steel, 295 /75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, AMH 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 259,719 Mi Asset located in: Lake Worth, TX
CHOIC 1965	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC1JDJZ7466 C/W: Cummins 6 Cylinder 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17000 lb Rears, 26000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, Morgan 24 ft x x Body, Curbside Door, Liftgate Usage: 397,493 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV	1969	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC1JDJS4825 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17126 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 28 ft x 102 in Wide x Body, Liftgate Usage: 431,154 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Midland, TX
	PRIOR TO BIDDING		

Lot #	Details	Lot #	Details
1970	2017 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWCY4HDJF0552 C/W: Cummins ISL 6 Cylinder Diesel 270 hp	сноісі	E OF 5 - Lot #'s: 1974, 1975, 1976, 1977, 1978
	Engine, Requires Diesel Exhaust Fluid, 8157 Engine hrs, Engine Brake, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 215 in Wheelbase, MORGAN 18 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 305,761 Mi Asset located in: Humble, TX	1974	2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACXDT2GDHA4391 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 280 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.56:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 271 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 in High Body, Liftgate
1971	2017 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT8HDJA1678		Usage: 102,796 Mi Asset located in: Lake Worth, TX
	C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 316,107 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1975 2016 F S/N: 1F C/W: C Engine, Exhaus Automa 17500 GVWR, in Whee	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDU2GHGW9627 C/W: Cummins ISB 6 Cylinder 6.7 L 200 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8376 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 6.14:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 294,823 Mi
			Asset located in: Lake Worth, TX
1972	2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT8GDHM0083 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 5608 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Steel, 11R22.5, Spring Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 180,227 Mi	1976	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT7GHHG9662 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 374,343 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1977	2016 Freightliner M2 106 4x2 Van Truck
1973	2016 Freightliner M2 4x2 Van Truck S/N: 3ALACWDT2GDHN0995 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2018 US EPA Label, 7610 Engine hrs, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 589,467 Mi Asset located in: Lake Worth, TX		S/N: 1FVACWDT6GHHK2059 C/W: Cummins ISB6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8186 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 234 in Wheelbase, Morgan 22 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 170,085 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1978	2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT3GDHM9628 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11463 Engine hrs, 6-Speed Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 334,137 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE	1981	2019 International MV607 4x2 Van Truck S/N: 3HAEUMML6KL437363 C/W: Cummins B 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, 7555 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 271 in Wheelbase, AMH 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 250,820 Mi Asset located in: Lake Worth, TX
	ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	1982	2020 International MV607LP 4x2 Moving Van Truck S/N: 1HTEWMML1LH870977
1979	2015 Freightliner M2 106 4x2 Moving Van Truck S/N: 1FVACXDT1FHGJ9796 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 7175.8 Engine hrs, Eaton Fuller FO-6406B Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, 295/75R22.5 Front Tires, 275 /80P22 5 Pear Tires, Spring Suspension, 270 in		C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6412 Engine hrs, Allison Automatic Transmission, 9000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 245 /70R19.5, Air Ride Suspension, 187 in Wheelbase, Morgan 16 ft x 102 in Wide x 97 in High Body Usage: 292,284 Mi Asset located in: Lake Worth, TX
	/80R22.5 Rear Tires, Spring Suspension, 270 in Wheelbase, Wabash 22 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 191,299 Mi	СНОІС	E OF 3 - Lot #'s: 1983, 1984, 1985
1980 1980A	2020 International MV607 4x2 Van Truck S/N: 3HAEUMML2LL115482 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 552 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 54,274 Mi Notes: ODOMETER REPLACED AT 171,023 MILES -PLEASE SEE INSPECTION REPORT, ACTUAL MILEAGE IS 225,297 Asset located in: Lake Worth, TX	1983	2019 International 4300 4x2 Moving Van Truck S/N: 1HTMMMML5KH382549 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3964 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.57:1 Axle Ratio, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Ball Hitch Usage: Not Available Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX
	S/N: 1HTEUMML4LH377008 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7035 Engine hrs, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 275 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 248,149 Mi Asset located in: Lake Worth, TX	1984	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML5KH519554 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 4381 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.29:1 Axle Ratio, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 202,297 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW

		1	
Lot #	Details	Lot #	Details
1985	2019 International 4300 4x2 Dry Van Van Truck S/N: 1HTMMMML6KH382477 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3654	СНОІС	E OF 4 - Lot #'s: 1991, 1992, 1993, 1994
СНОІС	Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.57:1 Axle Ratio, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Ball Hitch Usage: 155,349 Mi Asset located in: Lake Worth, TX E OF 3 - Lot #'s: 1987, 1988, 1990	1991	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML4KL382553 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3570 Engine hrs, Allison 2200 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x Body, Ball Hitch Usage: 165,388 Mi Asset located in: Lake Worth, TX
1987	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML1KH382497 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3778 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in High Body, Pintle Hitch Usage: 146,547 Mi Asset located in: Lake Worth, TX	1992	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML0KL382789 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4077 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body Usage: 180,545 Mi Asset located in: Lake Worth, TX
1988	2019 International 4300 4x2 Van Truck	1003	2019 International 4300 4x2 Van Truck
	S/N: 3HAMMMML8KL382233 C/W: Cummins ISB6.7 6.7 L Diesel Engine, 2019 US EPA Label, 3703 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, Ball Usage: 150,368 Mi Asset located in: Lake Worth, TX	1993	S/N: 1HTMMMML6KH514928 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4766 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.29:1 Axle Ratio, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Walk-Up Ramp, Ball Hitch
1990	2019 International 4300 4x2 Moving Van Truck S/N: 3HAMMMML7KL383325		Usage: 211,781 Mi Asset located in: Lake Worth, TX
	C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3819 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.57:1 Axle Ratio, 11783 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 156,125 Mi Asset located in: Lake Worth, TX	1994	2019 International 4300 4x2 Van Truck S/N: 3HAMMML3KL382012 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3995 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in High Body, Walk-Up Ramp Usage: 162,399 Mi

Lot #	Details	Lot #	Details	
CHOIC	2019 International 4300 4x2 Van Truck S/N: 3HAMMMMLXKL382265 C/W: Cummins ISB 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4095 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25000 lb GVWR, 11R22.5, International IROS Air Ride Suspension, 272 in Wheelbase, Supreme Corp 26 ft x 102 in Wide x 98 in High Body, Walk-Up Ramp Usage: 173,191 Mi Asset located in: Lake Worth, TX	2000	2019 International 4300 SBA 4x2 Van Truck S/N: 3HAMMMML3KL559187 C/W: Cummins B6.7 6 Cylinder 6.7 L 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5636 Engine hrs, Allison 2500 5-Speed Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 4.63:1 Axle Ratio, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, SMYRNA TRUCK 26 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 147,079 Mi Asset located in: Lake Worth, TX	
1997	2019 International 4300 4x2 Van Truck S/N: 1HTMMMMLXKH519808 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4042 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 175,179 Mi Asset located in: Lake Worth, TX	2001	2018 International Durastar 4300 SBA 4x2 Van Truck S/N: 1HTMMMML9JH589637 C/W: Cummins 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 233,934 Mi	
1998	2019 International 4300 4x2 Moving Van Truck S/N: 3HAMMMMLXKL383447 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4243 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body Usage: 188,842 Mi Asset located in: Lake Worth, TX	2002	S/N: 3HAMMMML9JL589552 C/W: Cummins B 6 Cylinder 6.7 L Di Engine, 2017 US EPA Label, Require Exhaust Fluid, 8327 Engine hrs, Auto Transmission, 10000 lb Front Axle, Rears, 25999.0 lb GVWR, 11R22.5, S Suspension, 256 in Wheelbase, 26 f High Body, Liftgate Usage: 262,670 Mi	2018 International 4300 4x2 Van Truck S/N: 3HAMMMML9JL589552 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8327 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Spring Suspension, 256 in Wheelbase, 26 ft x x 104 in High Body, Liftgate Usage: 262,670 Mi Notes: SELLING WITH A REPOSESSION
1999	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML8KH514655 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4722 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.29:1 Axle Ratio, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 207,720 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX	2003	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX 2018 International 4300 4x2 Van Truck S/N: 3HAMMMML2JL544906 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in Wide x 109 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,961 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
CHOICI 2004	2018 International 4300 4x2 Van Truck S/N: 1HTMMMML6JH350045 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9004 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 275,971 Mi	2009	2015 International Durstar 4300 4x2 Van Truck S/N: 3HAMMMML2FL040069 C/W: Cummins B6.7 220 6.7 L Diesel 220 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 6550 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 272,236 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
2005	2017 International 4300 4x2 Van Truck S/N: 1HTMMMML2HH654807 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 6442 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 179,428 Mi	2010	2008 Hino 268 4x2 Van Truck S/N: 5PVNE8JV582S50883 C/W: Hino J08E-TV 6 Cylinder 469 cid Diesel 220 hp Engine, 2007 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 112,668 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	2011	2008 International 4300 4x2 Van Truck
2006	2016 International 4300 4x2 Van Truck S/N: 3HAMMMML4GL740046 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17251 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 260 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body,		S/N: 1HTMMAAL38H572202 C/W: International MaxxForce DT 7.6 L Diesel 225 hp Engine, 2007 US EPA Label, CARB Compliant, 9586 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 226 in Wheelbase, Morgan 26 ft x 102 in Wide x 93 in High Body, Liftgate Usage: 245,473 Mi Asset located in: Lake Worth, TX
	Liftgate Usage: 222,929 Mi	2012	2005 International 4300 SBA 4x2 Van Truck
2007	Asset located in: Lake Worth, TX 2016 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML9GH012776 C/W: Cummins ISB V6 6.7 L 240 hp Engine, 2015 US EPA Label, 7922 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 15999 lb Rears, 25999.0 lb GVWR, 295/75R22. 5, Supreme 26 ft x 96 in Wide x 102 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 247,400 Mi		S/N: 1HTMMAAN05H119538 C/W: International D226 6 Cylinder 7.6 L Diesel 225 hp Engine, 2004 US EPA Label, 10254 Engine hrs, Eaton Fuller Manual Transmission, Aluminum Wheels, 295/75R22.5, Spring Suspension, Morgan 26 ft x 102 in Wide x 104 in High Body, Curbside Door, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: 196,863 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	2014	1998 International 4700 4x2 Moving Van Truck
2008	2015 International 4300 4x2 Van Truck S/N: 1HTMMMMLXFH710991 C/W: Cummins 6 Cylinder 6.7 L Diesel 240 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 28 ft x 96 in Wide x Body, Curbside Door, Liftgate Usage: 491,297 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		S/N: 1HTSCABM3WH533169 C/W: International V8 7.3 L Diesel Engine, US EPA Label, Spicer 5-Speed Manual Transmission, Spring Suspension, 188 in Wheelbase, Timpte 16 ft x 96 in Wide x 84 in High Body Usage: 41,973 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2015	2007 GMC C5500 4x2 Van Truck S/N: 1GDE5C1207F411068 C/W: GM Duramax 6.6 L Diesel Engine, 2006 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 285/70R19.5, Spring Suspension, 208 in Wheelbase, 18 ft x 96 in Wide x 90 in High Body, Liftgate Usage: 292,010 Mi Notes: **Shelving built in box area** Asset located in: Humble, TX	2021	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W168K7008461 C/W: Isuzu 4HK1TC 4 Cylinder 5.2 L Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6880 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, Steel, 215/85R16, Spring Suspension, 151 in Wheelbase, Morgan 16 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 236,438 Mi Asset located in: Lake Worth, TX
2016	2006 Nissan 4x2 COE Van Truck S/N: JNAPA80H66AS55788 C/W: Hino J08E-UJ 6 Cylinder 469 cid Diesel 230 hp Engine, 2007 US EPA Label, Automatic Transmission, 9480 lb Front Axle, 18000 lb Rears, 25995 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 259,568 Mi Asset located in: Lake Worth, TX	2022	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W16XK7009739 C/W: Isuzu 4HK1TC 4 Cylinder Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, 215/85R16, Spring Suspension, 151 in Wheelbase, 16 ft x 96 in Wide x 94 in High Body, Liftgate Usage: 271,219 Mi Asset located in: Lake Worth, TX
2017	2021 Chevrolet 4500 4x2 COE Van Truck S/N: 54DCDW1D5MS205390 C/W: Isuzu V8 Gasoline Engine, 2021 US EPA Label, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Morgan 20 ft x 96 in Wide x 91 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX	2023	2018 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B9JS802729 C/W: V8 6.0 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, Supreme 16 ft x 96 in Wide x 94 in High Body, Liftgate Usage: 105,477 Mi Asset located in: Lake Worth, TX
2018	2018 Chevrolet 4500 4x2 COE Van Truck S/N: 54DCDW1B6JS807385 C/W: V8 6.0 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, 149 in Wheelbase, Smyrna 16 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 174,853 Mi Asset located in: Lake Worth, TX	2024	2016 Isuzu NPR 4x2 COE Extended Cab Van Truck S/N: 54DC4J1B8GS803916 C/W: Isuzu Gasoline Engine, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Supreme 16 ft x 102 in Wide x 85 in High Body, Curbside Door, Liftgate Usage: 137,402 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 2020, 2021, 2022	2025	2012 Mitsubishi Fuso 4x2 COE Van Truck S/N: JL6BNG1A5CK002630
2020	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B2KS806624 C/W: GM V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, 150 in Wheelbase, Morgan 16 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 187,646 Mi		C/W: Fuso F1C 3.0 L Engine, 2011 US EPA Label, Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 15995 lb GVWR, 215 /75R17.5, Spring Suspension, 153 in Wheelbase, 16 ft x 102 in Wide x 94 in High Body, Liftgate Usage: 169,508 Mi Notes: LOCATED-IN-LAKE WORTH-TX Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	2027	2015 Ram 5500 4x2 Van Truck S/N: 3C7WRMDL6FG506015 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, Morgan 16 ft x 96 in Wide x 80 in High Body, Curbside Door, Liftgate Usage: 169,865 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2029A	2020 GMC Savana G3500 4x2 Van Truck S/N: 1GD07RFP9L1182263 C/W: V6 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 74 in High Body Usage: 89,341 Mi Notes: TITLE SHOWS NOT ACTUAL MILEAGE Asset located in: Humble, TX	2044	2016 Ford Transit 350 Passenger Van S/N: 1FBZX2ZM3GKA06205 C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
2030	2019 Ford E350 4x2 Van Truck		Asset located in: Midland, TX
	S/N: 1FDWE3FS8KDC22914 C/W: Ford 6.8 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, Steel, 225 /75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 78,825 Mi Asset located in: Humble, TX	2045	2014 Freightliner Sprinter 3500 4x2 Van Truck S/N: WDPPF4CC7E9564671 C/W: V6 3.0 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 4080 lb Front Axle, 7720 lb Rears, 11030 lb GVWR, 215/85R16, Spring Suspension, 16 ft x 86 in Wide x 78 in High Body, Curbside Door, Walk-Up Ramp
2031	2019 Ford E350 4x2 Van Truck S/N: 1FDWE3FS4KDC15555		Usage: 313,155 Mi Asset located in: Lake Worth, TX
	C/W: Gasoline Engine, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, 225/75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 81,416 Mi Asset located in: Lake Worth, TX	2046	2024 Chevrolet Express 2500 Cargo Van S/N: 1GCWGAF70R1101434 C/W: V8 6.6 L Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera, Towing Hitch Usage: 131 Mi
2038	2015 Ford E-350 4x2 14-Seat Transit Bus S/N: 1FDEE3FS2FDA21995		Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2014 US EPA Label, 225/75R16, Spring Suspension, 156 in Wheelbase Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	2047 CHOICE	2016 Ford Transit 250 4x2 Cargo Van S/N: 1FTYR2ZM4GKA77642 C/W: Ford V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5515 lb Rears, 9000 lb GVWR, 235 /65R16, Spring Suspension, 138 in Wheelbase, 9 ft x 78 in Wide x 56 in High Body Usage: 214,134 Mi
2042	2007 Chevrolet C5500 4x2 26-Seat Transit Bus S/N: 1GBE5V1G67F425251 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, GM V8 8.1 L Gasoline Engine, 2007 US EPA Label, 225/70R19.5, Spring Suspension, 232 in Wheelbase, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 80,972 Mi Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED; DOCUMENTS TO PROCESS TITLE; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; Asset located in: Humble, TX E OF 2 - Lot #'s: 2049, 2050
	Asset located in: Lake Worth, TX	2049	2019 Ram ProMaster 2500 4x2 Cargo Van
2043	2021 Nissan NV200 4x2 Cargo Van S/N: 1N6BF0KY5MN807503 C/W: V6 4.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 3825 lb Front Axle, 5875 lb Rears, 9100 lb GVWR, 245/70R17, Spring Suspension, 146 in Wheelbase, 9 ft x x 50 in High Body Usage: 80,655 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX		(Inoperable) S/N: 3C6TRVDG2KE531385 C/W: V6 3.6 L Gasoline 280 hp Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 3.86:1 Axle Ratio, 8900 lb GVWR, 225/75R16, Spring Suspension, 159 in Wheelbase, 11 ft x 80 in Wide x 76 in High Body, Curbside Door Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2050	2019 Ram ProMaster 2500 4x2 Cargo Van S/N: 3C6TRVDGXKE557829 C/W: V6 3.6 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 8900.0 lb GVWR, 225 /75R16, Spring Suspension, 159 in Wheelbase, 11 ft x x 76 in High Body, Curbside Door Usage: 44,182 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	2055	2016 Ford Transit 150 4x2 Cargo Van S/N: 1FTYE1YM9GKB48843 C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5070 lb Rears, 8600 lb GVWR, 235/65R16, Spring Suspension, 132 in Wheelbase, 9 ft x 96 in Wide x 55 in High Body, Curbside Door Usage: 144,833 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
	THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	2056	2020 Mercedes-Benz 135 WB 4x2 Cargo Van S/N: W1YV0CEY3L3688564
2051	2019 GMC Savana 1500 Cargo Van S/N: 1GTW7BFP3K1277096 C/W: V6 4.3 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 91,916 Hr		C/W: Mercedes-Benz 2.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 3307 lb Front Axle, 3307 lb Rears, 6614.0 lb GVWR, 225/55R17, Spring Suspension, 136 in Wheelbase Usage: 74,107 Mi
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
2052	2007 Chevrolet 2500 Express 4x2 Cargo Van		Asset located in: Lake Worth, TX
	S/N: 1GCGG25V471223513 C/W: Chevy V8 4.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245 /75R16, Spring Suspension, 139 in Wheelbase, 9 ft x 72 in Wide x 54 in High Body, Curbside Door Usage: 135,450 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	5000	2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: HL00249 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
CHOICI	E OF 2 - Lot #'s: 2053, 2054	5001	2024 Landhonor ABC-13-125A Articulating
2053	2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E25M1496971 C/W: 4 Cylinder 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 215 /55R16, 121 in Wheelbase, 6 ft x x 44 in High Body Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	5002	2024 Raytree RMC72 72 in Skid Steer Brush
2054	2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E27M1496972 C/W: ford 4 Cylinder 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 205/55R16, 121 in Wheelbase, 6 ft x 72 in Wide x 44 in High Body Usage: 46,847 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		Cutter (Unused) S/N: C20241007112 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX	5003	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

		I			
Lot #	Details	Lot #	Details		
5004	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5014	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		
5005	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			M T U	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5006	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		
5007	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available	5015	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		
5008	Asset located in: Lake Worth, TX All-Star 72 in Skid Steer Brush Cutter (Unused)		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		
5009	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available	5016	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Wolverine BC-13-72W 72 in Skid Steer		
5010	Asset located in: Lake Worth, TX All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		
5011	2023 Mower King SSRC 72 in Skid Steer Brush Cutter S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		
5012	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC20240919 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		
5013	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5018	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5027	2024 Suihe SSBC 66 in Skid Steer Brush Cutter (Unused) S/N: 001602498 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5019	All-Star 72 in Skid Steer Brush Cutter (Unused)	5028	2024 Suihe SSBC 0 ft 66 in Skid Steer Brush
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	_	Cutter (Unused) S/N: 001602505 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5020	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5021	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5029	Quantity of (2) 2024 Wolverine SBM-12-72W 72
5022	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		in Sickle Bar Skid Steer Mower (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5023	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5024	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	5030	2024 Handy HSBM72 72 in Sickle Bar Skid
5025	2021 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC21092604 Usage: Not Available Asset located in: Lake Worth, TX		Steer Mower (Unused) S/N: SBM202409115 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5026	Wolverine 70 in Pallet Skid Steer Brush Cutter		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5031	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202409114 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	5032	2023 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW02312 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5033	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5041	2024 Wolverine BBS-11-72W 72 in Skid Stee Sweeper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5034	2024 Handy HAB72 72 in Skid Steer Broom (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	S/N: AB202409111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5042	2024 Wolverine PBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW00289	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
5035	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409110 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5043	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Wolverine MBS-11-48W 48 in Mini Skid Steer Sweeper (Unused) S/N: ZW00327 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES	
5036	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			
5037	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S C F	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5038	JCT 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 TOFT TOFT750 Skid Steer Post Driver (Unused) S/N: JW43Z5685 Usage: Not Available Asset located in: Lake Worth, TX	
5039	Bobcat 84 in Skid Steer Angle Broom S/N: 231412786 Usage: Not Available Asset located in: Lake Worth, TX		2024 TOFT TOFT680 Skid Steer Post Driver (Unused) S/N: JW40Z17058 Usage: Not Available	
5040	5048 2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5047	Asset located in: Lake Worth, TX 2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202406543 Usage: Not Available Asset located in: Lake Worth, TX	
		5048	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202409560 Usage: Not Available	
		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
5049	2024 Raytree RMH680 Skid Steer Breaker (Unused) S/N: HH20241012180 Usage: Not Available	5056	Mini Skid Steer Breaker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5050	Asset located in: Lake Worth, TX 2024 Wolverine CB-11-750F Skid Steer Breaker (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5057	2024 TOFT TOFT750 Skid Steer Breaker (Unused) S/N: JW43Z5799 Usage: Not Available Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5058	2024 TOFT TOFT680 Skid Steer Breaker (Unused) S/N: JW40Z17265 Usage: Not Available Asset located in: Lake Worth, TX	
5051	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan JSB400SL Skid Steer Breaker	5059	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409143	
	(Unused) S/N: 2404298 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5060	2024 Handy HPD680 Skid Steer Post Driver (Unused)	
5052 2024 Jisan JSB400 (Unused) S/N: 2404295 Usage: Not Availab Notes: THE PRODU	•		S/N: PD202409145 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5061	2024 Handy HPD680 Skid Steer Post Driver (Unused)	
5053	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: 2406091 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		S/N: PD202409142 Usage: Not Available Notes : THE PRODUCT FOR ILLUSTRATION PL MAY NOT BE AN EXAC THE ACTUAL PRODUC	S/N: PD202409142
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5062	2024 Handy HPD680 Skid Steer Post Driver (Unused)	
5054	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: CP2406092 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5063	S/N: PD202409144 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused)	
5055	2024 Trojan TH35SSL Skid Steer Breaker (Unused) S/N: SB30YOM20247065 Usage: Not Available Asset located in: Lake Worth, TX		S/N: HL00017 Usage: Not Available Asset located in : Lake Worth, TX	

Lot #	Details	Lot #	Details
5064	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00018 Usage: Not Available Asset located in: Lake Worth, TX	5069	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241012195 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/
5065	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Jisan JSB400SLT Skid Steer Post Driver (Unused) S/N: CP2407183 Usage: Not Available
5066	Asset located in: Lake Worth, TX 2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5071	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00381 Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5072	72 2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00384 Usage: Not Available
5067	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241009192	5073	Asset located in: Lake Worth, TX 2024 Landhonor TP2-13-08D Skid Steer Post
	C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR		Puller (Unused) S/N: HL00382 Usage: Not Available Asset located in: Lake Worth, TX
	ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5074	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00383 Usage: Not Available Asset located in: Lake Worth, TX
5068	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241012196 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5075	2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused) S/N: VR202409472 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5076	2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused) S/N: VR202409474 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5082	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused) S/N: T20241008159 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5077	2024 Handy HVR76 72 in Skid Steer Vibratory	5083	2024 Handy HST48 48 in Skid Steer Trencher
	Roller (Unused) S/N: VR202409473 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: Not Available C/W: 8 In Dirt & Rock Chain, Crumbling Shoe Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5078	2024 Raytree RMVR76 76 in Skid Steer	5084	2024 Handy HST48 48 in Skid Steer Trencher
	Vibratory Roller (Unused) S/N: VR20241012184 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: TR202409613 C/W: 8 In Dirt & Rock Chain, Crumbling Shoe Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5079	2024 Suihe SSVR-72 72 in Skid Steer Vibratory		Asset located in: Lake Worth, TX
	Roller (Unused) S/N: 001300876 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5085	2024 Suihe SST-1000/200 Skid Steer Trencher (Unused) S/N: 001702343 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5080	2024 Wolverine VR-11-66W 66 in Skid Steer		Asset located in: Lake Worth, TX
	Vibratory Roller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5086	2024 Suihe SST-1000/200 Skid Steer Trencher (Unused) S/N: 001702342 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5081	TMC 72 in Skid Steer Vibratory Roller S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5087	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5092	2024 Handy HSD96 96 in 6 Way dozer Skid Steer Dozer (Unused) S/N: SD202409300 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HSD96 96 in 6 Way dozer Skid Steer Dozer (Unused) S/N: SD202409301
5088	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT	5094	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Raytree RSWD96 94 in Six Way Skid Stee Dozer (Unused) S/N: SW20241012042 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5089	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX 2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused) S/N: 031789472 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5090	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HSD96 96 in 6 Way Skid Steer Dozer (Unused) S/N: SD202409302 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5096	Asset located in: Lake Worth, TX 2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused) S/N: 031789296 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5097	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused) S/N: 031789880 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5104	2024 Handy HGB86 96 in Heavy Duty Skid Steer Grader (Unused) S/N: GB86202409216 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused)	
5098	2024 Wolverine DB-15-84W 84 in Angle Skid Steer Dozer (Unused)		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5106	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5099	Asset located in: Lake Worth, TX All-Star 72 in Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5107	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5100	Mid-State 72 in Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5108	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5101	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202409595 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SIES FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5110 2024 Wolverine TL-12-72W 72 in STILLER (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHO	5109	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5102	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202409594 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES S	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5103	2024 Handy HGB86 96 in Skid Steer Grader (Unused) S/N: GB86202409217 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5111	11 2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5117	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		5118	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5119	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409392 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in,	
5112	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available		(1) 18 in Bits, One Crate Usage: Not Available Notes : THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	S/N: SSA2409390	C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available	
5113	Asset located in: Lake Worth, TX 2024 Suihe SSTL 72 in Skid Steer Tiller (Unused) S/N: 002402687	FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT Asset located in: Lake Worth, 5121 2024 Handy SSA18 Skid Stee S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGE FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT Asset located in: Lake Worth, 5122 2024 Handy SSA18 Skid Stee S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGE FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT Asset located in: Lake Worth, 5123 2024 Handy SSA18 Skid Stee S/N: SSA2409389 C/W: (1) 10 in bit, (1) 12 in bit crate Usage: Not Available Notes: THE PRODUCT IMAGE FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT IMAGE FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT	FOR ILLUSTRATION PURPOSES ONI MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5114	2024 Suihe SSTL 72 in Skid Steer Tiller (Unused) S/N: 002402685 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
	Asset located in: Lake Worth, TX		2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409389	
5115	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			
5116	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF	

Lot #	Details	Lot #	Details
5124	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409391 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5128	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5125	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5129	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20241012230 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5126	Asset located in: Lake Worth, TX 2024 Wolverine ADB-13-1218R Skid Steer	5130	2024 Raytree RMA42 Skid Steer Auger
5126	Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: A20241012229 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
		5131	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503461 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR
5127	2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5132	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503471 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5133	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503502 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5142	2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409146 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409147 Usage: Not Available
	Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5134	Belltec LC350 Skid Steer Auger (Unused) S/N: L09284 C/W: Quick Attach 2 in Hex Head Auger Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5144	2024 Handy HBC72 Concrete Crusher (Unused)
5135	2018 Bobcat 15C Skid Steer Auger S/N: 944261257 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		S/N: CC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5136	16 in Mini Skid Steer Auger (Unused)	5145	2024 Raytree RMBC72 72 in Skid Steer Block
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5145	Crusher (Unused) S/N: BC20241010172 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available
5137	Quantity of (3) Mini Skid Steer Augers (Unused) S/N: Not Available C/W: (1) 16 in, (1) 12 in, (1) 8 in Bits Usage: Not Available		
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5138	Pengo 10-2500 Auger Bit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	5146	2024 Landhonor CC-11-08V 24 in Skid Steer Concrete Crusher (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5147	2024 Handy HFB52 Skid Steer Feller Buncher
5139	2024 Raytree RMSC78 72 in Skid Steer Soil Conditioner S/N: SC20241010053 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: FB202409119 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5140	Level Best LBSS6 72 in Skid Steer Laser	5148	2024 Handy HSRC12 Rotating Skid Steer Pole Clamp (Unused)
	Grading Box Blade S/N: 1187 Usage: Not Available Asset located in: Lake Worth, TX		S/N: RC202409626 Usage: Not Available Notes : THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5141	Raytree 28 in Skid Steer Hyd Pole Jack (Unused) S/N: 20231025031 Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION (THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details		
5149	Clamp (Unused) S/N: RC202409627 Usage: Not Available	5158	All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
		5159	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5150	2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5160 5161 5162	5160 Kubota PS2086 84 in Skid Steer Grain F S/N: 1064217K C/W: 3 Pt Hitch Usage: Not Available Asset located in: Lake Worth, TX 5161 2024 Handy HSNC78 72 in Skid Steer F Rake (Unused) S/N: SC202409110 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY A MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 5162 2024 Handy HSNC78 72 in Skid Steer P	Kubota PS2086 84 in Skid Steer Grain Planter S/N: 1064217K C/W: 3 Pt Hitch Usage: Not Available Asset located in: Lake Worth, TX 2024 Handy HSNC78 72 in Skid Steer Power Rake (Unused)	
5151	Asset located in: Lake Worth, TX 2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: RP202409465 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF			Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: SC202409112 Usage: Not Available		
5152	2024 Landhonor FW-13-15000G 15000 lb Skid Steer Winch (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT		
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX		
5153	2024 Industrias America Post/Tree Puller (Unused) S/N: HPOST202421670 Usage: Not Available Asset located in: Lake Worth, TX 2024 Industrias America Post/Tree Puller	5163	Rake (Unused) S/N: SC202409111 Usage: Not Available Notes: THE PRODUCT IMAGES S FOR ILLUSTRATION PURPOSES	S/N: SC202409111	
	(Unused) S/N: POST202421749		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		
	Usage: Not Available Asset located in: Lake Worth, TX	5164	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused)		
5155	2024 Industrias America Post/Tree Puller (Unused) S/N: POST202421748 Usage: Not Available Asset located in: Lake Worth, TX				S/N: HL01191 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5156	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		
5157	All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		AGGET IOCATEG III. LANG WOTHI, TA		

Lot #	Details	Lot #	Details
5165	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: HL01192 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5171	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409925 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (2) 2024 Landhonor BH-11-06H Big Arm Skid Steer Backhoe (Unused)
	Asset located in: Lake Worth, TX		S/N: Not Available
5166	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused)		C/W: 18 In Bucket, One Crate Usage: Not Available Asset located in : Lake Worth, TX
	S/N: HL01193 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5173	All-Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5174	All Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX
5167	2024 Raytree RTSG30 31 in Transverse Skid Steer Stump Grinder (Unused) S/N: TS20241012241 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5175	Bobcat 709FDS Skid Steer Backhoe S/N: 270020062 C/W: NO BUCKET Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5176	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused)
5168	2024 Raytree RMSG29 29 in Skid Steer Stump Grinder (Unused) S/N: SG20241010315	5177	S/N: HM20241012049 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		77 2024 Raytree RMDM72A 72 in Skid Steer Mulcher (Unused) S/N: HM20241009048 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
5169	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409926		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012445 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5170	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409924 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5179	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012450 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5186	2024 Raytree RMDM70 60 in Skid Steer Mulcher (Unused) S/N: DM20241012194 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5180	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012447 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5187	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241009067 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5181	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241008440 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5188	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241010069 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5182	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409470 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5189	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241009068 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5183	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409469 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5190 5191	All-Star 78 in E-Series Rock Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX All-Star 78 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available
5184	2024 Handy HSDM70 Skid Steer Mulcher (Unused) S/N: DM202409332 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5192 5193	Asset located in: Lake Worth, TX All-Star 72 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX All-Star 72 In E-Series Rock Skid Steer Grapple
5185	2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124060901E Usage: Not Available Asset located in: Oklahoma City, OK		Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5194	All-Star 72 In Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available	5205	All Star 74 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5195	Asset located in: Lake Worth, TX 2024 Landhonor RG-11-5000G Rotating Skid Steer Grapple (Unused) S/N: HL00372 Usage: Not Available	5206	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5196	Asset located in: Lake Worth, TX All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5207	All-Star 72 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5197	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5208	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5198	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available	5209	All Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5199	72 in Skid Steer Grapple Bucket S/N: Not Available Usage: Not Available	5210	All-Star E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5200	Asset located in: Lake Worth, TX Kit Containers 48 in Skeleton Mini Skid Steer Grapple (Unused) S/N: B14E1606 Usage: Not Available	5211	All Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5201	Asset located in: Lake Worth, TX All-Star 80 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5212	All-Star 68 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5202	Asset located in: Lake Worth, TX All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5213	All-Star 68 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5203	All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5214	Mid-State 60 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5204	Asset located in: Lake Worth, TX All Star 78 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5215	All Star 48 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5216	36 in Q/C Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5223	All-Star 80 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available
5217	All-Star 40 in Stump Skid Steer Grapple		Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5224	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available
5218	All-Star 40 in Stump Skid Steer Grapple		Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5225	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset Inseted in: Lake Worth, TV
5219	All-Star 40 in Stump Skid Steer Grapple Bucket	5006	Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5226	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5220	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused)	5227	All-Star 74 in Skid Steer Grapple Bucket
	Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	0227	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5228	All Star 72 in E-Series Skid Steer Grapple
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Bucket (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5221	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5229	2024 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	<u>`</u>	5230	2024 Wolverine GB-11-72W 72 in Skid Steer
5222	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5231	Raptor 72 in Skid Steer Grapple Bucket (Unused) S/N: 23400249 Usage: Not Available Asset located in: Lake Worth, TX	5241	All Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5232	All-Star 68 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5242	All-Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5233	Cat 66 in Skid Steer Grapple Bucket S/N: A4164CB50022 Usage: Not Available Asset located in: Lake Worth, TX	5243	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5234	30 in Mini Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5244	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5235	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5245	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5236	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5246	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808766 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OITHE ACTUAL PRODUCT
5237	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5238	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5247	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808741 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5239	2024 Suihe SSRGB-72 72 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5240	Asset located in: Lake Worth, TX All-Star 68 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5248	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808738 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5257	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5258	Mid-State 68 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5259	Mid-State 68 In E-Series Skid Steer Root Rake (Unused)
5249	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808746		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5260	All-Star 68 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5250	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX All-Star 78 In E-Series Skid Steer Root Rake	5261	Mid-State 60 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5262	Mid-State 60 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available
5251	All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5263	Asset located in: Lake Worth, TX Mid-State 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5252	All-Star 78 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5264	All-Star 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5253	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5265	All-Star 68 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5254	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5266	All-Star 72 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5255	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5267	All-Star 60 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5256	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5268	All-Star 84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5269	84 in Skid Steer Ripper Scarifier (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5276	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241009347 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5270	2024 Handy HVSB72 72 in Screening Skid Steer Bucket (Unused) S/N: VSB202409688		
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5277	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241012354 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5271	2024 Handy HVSB72 72 in Screening Skid Steer Bucket (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: VSB202409689 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5278	Mid-State General Purpose 84 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5272	Asset located in: Lake Worth, TX 2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: Not Available	5279	Mid-State General Purpose 80 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5280	Mid-State 84 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5273	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5281	Mid-State 84 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5282	All-Star 80 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available
5274	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused)		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5283	All-Star 80 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5275	Asset located in: Lake Worth, TX 2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241009346 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5284	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5285	Mid-State General Purpose 78 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5286	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5296	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION (
5287	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5297	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused)
5288	2024 Kit Containers QT-DB-S78 78 in Skid Steer Bucket (Unused) S/N: B28J1613 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5289	Teran BKT26278 78 in Skid Steer Bucket - Fits		Asset located in: Lake Worth, TX
	Cat 226 (Unused) S/N: 1220 C/W: 0.5m3 with 8HD Tips for CAT 226 - 299 Usage: Not Available Asset located in: Lake Worth, TX	5298	Mid-State 74 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5290	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5299	Mid-State 74 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5291	Kit Containers 78 in Skid Steer Bucket (Unused) S/N: B26J1610 Usage: Not Available Asset located in: Lake Worth, TX	5300	72 in Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5292	78 in General Purpose Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5301	Asset located in: Lake Worth, TX 72 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available
5293	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX 72 In Low Pro W/Teeth Skid Steer Bucket
	Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: Not Available
5294	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused)		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5303	Mid-State General Purpose 72 in Skid Steer Bucket (Unused) S/N: Not Available
5295	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5304	72 in General Purpose Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
		5306	Teran BKT26272 72 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 3142 C/W: 0.45m3 with 8 HD Tips to fit Cat 226 - 299 Usage: Not Available

Lot #	Details	Lot #	Details
5307	Mid-State 72 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5320	Teran BKT26260 60 in C Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 3119 C/W: 0.35m3 with 7 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Lake Worth, TX
5308	All Star 72 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5321	Bobcat 80 in General Purpose Skid Steer Bucket S/N: 6726344 Usage: Not Available Asset located in: Lake Worth, TX
5309	All Star 68 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5322	Arrow 2307206BUN 74 in Skid Steer Bucket S/N: YB12397 Usage: Not Available Asset located in: Lake Worth, TX
5310	All-Star 68 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	5324	67 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5311	Asset located in: Lake Worth, TX Mid-State 68 In Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available	5325	61 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5312	Usage: Not Available Asset located in: Lake Worth, TX Mid-State 68 In Low Profile Skid Steer Bucket	5326	2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: B30J1625
-	(Unused) S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
5315	Asset located in: Lake Worth, TX 2024 Kit Containers QT-DB-T66 66 in Skid Steer Bucket (Unused)	5327	2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: B29J1617 Usage: Not Available
	S/N: B23J1617 Usage: Not Available Asset located in : Lake Worth, TX	5328	Asset located in: Lake Worth, TX Mid-State 78 In Snow & Litter Skid Steer Bucket (Unused)
5316	2024 Kit Containers QT-DB-S66 66 in Skid Steer Bucket (Unused) S/N: B23J1632		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5329	All-Star 74 In Snow & Litter Skid Steer Bucket (Unused)
5317	Mid-State 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5330	Mid-State 80 in Snow & Litter Skid Steer Bucket (Unused)
5318	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	F221	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Mid State 69 in Space 8 Litter Skid Steer Bucket
	Asset located in: Lake Worth, TX	5331	Mid-State 68 in Snow & Litter Skid Steer Bucket (Unused)
5319	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
5332	All Star 68 in Snow & Litter Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5343	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5333	All-Star 80 In Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5344	Asset located in: Lake Worth, TX 2024 Landhonor RB-14-84W 84 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5334	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: With Teeth Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5335	All-Star 84 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5345	2024 Landhonor RB-14-78W 78 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available
5336	All-Star 84 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5346	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5337	Kit Containers 82 in Rock Skid Steer Bucket (Unused) S/N: B22J1604 Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		Kit Containers 76 in Skeleton Skid Steer Bucke
5338	All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available		(Unused) S/N: B17J1620 Usage: Not Available Asset located in: Lake Worth, TX
5339	Asset located in: Lake Worth, TX All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	5347	Kit Containers 76 in Skeleton Skid Steer Bucket (Unused) S/N: B16J1620 Usage: Not Available Asset located in: Lake Worth, TX
5340	Asset located in: Lake Worth, TX Kit Containers 72 in Rock Skid Steer Bucket (Unused) S/N: B21J1615 Usage: Not Available	5348	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5341	Asset located in: Lake Worth, TX All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5349	2024 Landhonor RB-14-72W 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5342	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5350	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5359	2024 Kit Containers QT-TS-40 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5351	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5360	2024 Kit Containers QT-RD 36 in Skeleton Stump Skid Steer Bucket (Unused) S/N: B28J1958 Usage: Not Available Asset located in: Lake Worth, TX
5352	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5361	Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OI THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OI THE ACTUAL PRODUCT
5353	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5354	All-Star 68 in Skeleton Skid Steer Bucket (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5362	2024 Landhonor DCM-11-250G 48 in Skid Ste Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5355	2024 Landhonor RB-14-66W 66 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5363	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Suihe SSM 56 in Skid Steer Concrete Mixer (Unused) S/N: 008000909 C/W: THE PRODUCT IMAGES SHOWN ARE
5356	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ON MAY NOT BE AN EXACT REPRESENTHE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHO
5357	All-Star 40 in Stump Skid Steer Bucket		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	(Unused) S/N: Not Available		Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5364	2024 Kit Containers 2YFT-SST 5 ft 7 in Self-
5358	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 7 in Long x 4 ft 7 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5365 5366	2024 Kit Containers 2YFT-SST 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in: Lake Worth, TX	(Unused) S/N: LS202409283 Usage: Not Available Notes: THE PRODUCT IMAE FOR ILLUSTRATION PURP MAY NOT BE AN EXACT R THE ACTUAL PRODUCT Asset located in: Lake Wor 5373 2024 Handy HLS35 Skid S (Unused) S/N: LS202409281 Usage: Not Available Notes: THE PRODUCT IMAE FOR ILLUSTRATION PURP MAY NOT BE AN EXACT R THE ACTUAL PRODUCT Asset located in: Lake Wor 5374 2024 Raytree RMLS18T 18 Splitter (Unused) S/N: LS20241012044 C/W: THE PRODUCT IMAE FOR ILLUSTRATION PURP	(Unused) S/N: LS202409283 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT
	Dump Hopper (Unused) S/N: B29E1207 Usage: Not Available Asset located in: Lake Worth, TX		2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202409281
5367	2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		• • •
5368	Asset located in: Lake Worth, TX 2024 Suihe SSBG 75 in Skid Steer Landplane		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: 005500748 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5375	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5376	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5377	2024 Handy HSP24 24 in Skid Steer Planer (Unused)
5369	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	S/N: SP202409130 Usage: Not Available Notes: THE PRODUCT IMAGES S FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT	S/N: SP202409130 Usage: Not Available Notes : THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5370	42 in Mini Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5378	2024 Handy HSP24 Skid Steer Planer (Unused)
5371	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202409282 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: SP202404110 Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5379	2024 Landhonor VPC-11-72W 72 in Skid Steer Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5385	2024 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5380	2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409139 Usage: Not Available	5386	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available
5381	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Handy HSSB72 72 in Skid Steer	5387	Asset located in: Lake Worth, TX 2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Snowblower (Unused) S/N: SBM202409138 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5388	2024 Landhonor HRB-11-127A Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00018 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available Asset located in: Lake Worth, TX
5382	Asset located in: Lake Worth, TX 2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused) S/N: SBM202409137 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5389	2024 Landhonor HRB-11-127A Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00017 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5390	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409301 C/W: Fork Positioner
5383	2024 Kit Containers QT-RR-70 70 in Skid Steer Ripper Scarifier (Unused) S/N: B24J1305 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5384	84 in Skid Steer Ripper Scarifier (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5391	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409297 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5392	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409299 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5398	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5393	2024 Handy HF2T 48 in Skid Steer Forks (Unused)		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: HF202409300 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5394	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409298 C/W: Fork Positioner Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX
5395	Quantity of (4) 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: (4) Universal Adapter Plates, One Crate Usage: Not Available	5401	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX
5396	Asset located in: Lake Worth, TX 2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5402	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX
		5403	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5404	Handy HSRF48 48 in Rotating Skid Steer Forks (Unused)
5397	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available		S/N: RF202401136 Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5405	2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot#	Details	Lot #	Details
5406	2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5417	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5407	Asset located in: Lake Worth, TX 2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available	5418	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5419	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available
5408	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5420	Usage: Not Available Asset located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
5409	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5421	Asset located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available
- 440	Asset located in: Lake Worth, TX		Usage: Not Available Asset located in : Lake Worth, TX
5410	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5422	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5411	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5423	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5412	Asset located in: Lake Worth, TX 2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused)	5424	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5413	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers QT-45-FF-42 42 in Skid	5425	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5426	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5414	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5427	ASSET located in: Lake Worth, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5415	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5428	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5416	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5429	Land Pride 48 in Skid Steer Forks S/N: 999569 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5430	Trojan SPF15 48 in Skid Steer Forks (Unused) S/N: 124438 Usage: Not Available	5443	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5431	48 in Skid Steer Forks S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5444	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5432	38 in Skid Steer Forks S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5445	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5433	All Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5446	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5434	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5447	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5435	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5448	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5436	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5449	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5437	48 in Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5450	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5438	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5451	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5439	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5440	Asset located in: Lake Worth, TX All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5441	ASSET located in: Lake Worth, TX All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Bal S/N C/V FOI MA THI Usa No i FOI MA	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear Frame (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5442	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5453	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5461	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5462	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5463	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5454	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5464	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5455	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5465	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5456	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5466	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available
5457	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5467	Asset located in: Lake Worth, TX 32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5458	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5468	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5459	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5469	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5460	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5470	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5471	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5479	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5472			FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5480	Asset located in: Lake Worth, TX 2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available
5473	Asset located in: Lake Worth, TX 2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused) S/N: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
		5481	Asset located in: Lake Worth, TX 2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5474	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00018		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5475	Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor RP-12-72W 72 in Skid Steer		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
0470	Rock Picker (Unused)		Asset located in: Lake Worth, TX
	S/N: HL00017 Usage: Not Available Asset located in : Lake Worth, TX	5482	·
5476	2024 Landhonor DPC-21-13W Skid Steer Pole Clamp (Unused) S/N: HL00009 Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5477	2024 Kit Containers QT-TM Receiver Hitch (Unused) S/N: B06J1903		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Usage: Not Available	F 400	All Char Booking Hitch (University
5478	Asset located in: Lake Worth, TX 2024 Kit Containers QT-TM Skid Steer Receiver Hitch (Unused) S/N: B06J1913 Usage: Not Available Asset located in: Lake Worth, TX	5483	All-Star Receiver Hitch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5484	All-Star Receiver Hitch (Unused) S/N: Not Available Usage: Not Available
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5485	Titan SSJ2.5 Extendable Skid Steer Material Handling Arm S/N: Not Available Usage: Not Available Asset located in: Midland, TX	5494	Quantity of (10) 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: One Pallet
5486	Set of Grouser Steel Skid Steer Tracks S/N: Not Available Usage: Not Available	5495	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) All-Star Skid Steer Attachment
	Asset located in: Lake Worth, TX		Mounting Plate (Unused)
5487	Set of McLaren Steel Skid Steer Tracks S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	5496	Quantity of (3) All-Star Skid Steer Attachment
5488	Set of OTT Tracks for Skid Steer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5489	2024 Handy HSTS12 Skid Steer Tree Shear (Unused) S/N: TS202409117 Usage: Not Available	5497	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5498	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available
5490	Quantity of (4) All-Star Quick Attach Skid Steer		Asset located in: Lake Worth, TX
	Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5499	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available
5491	Quantity of (10) 2024 Kit Containers QT-F-		Asset located in: Lake Worth, TX
	BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	5500	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5492	Quantity of (10) 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused) S/N: DM20241009163 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5493	Quantity of 2024 Kit Containers QT-F-BLANK		Asset located in: Lake Worth, TX
	Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5502	Quantity of (9) Agrotek Mini Excavator Attachments (Unused) S/N: 12EXATA24042002A C/W: (3) Buckets, Quick Coupler, Grapple, Auger, Two Bits, Rake, Ripper, One Pallet Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5503	All-Star E35 40 in Q/C Excavator Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5512	KBKC 48 in Excavator Rake - Fits Cat 305-306 (Unused) S/N: RR240103 Usage: Not Available Asset located in: Lake Worth, TX
5504	All-Star 40 in Excavator Brush Cutter (Unused) S/N: Not Available C/W: No Coupler Usage: Not Available Asset located in: Lake Worth, TX	5513	Excavator Ripper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5505	Paladin Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5514	2018 John Deere Excavator Auger - Fits John Deere 310SJ S/N: Not Available C/W: 45 mm Diameter Pins, 340 mm Center of Pin Boss to Center of Pin Boss, 205 mm Inside
5506	Cat Misc. attachment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE		PICKED UP BY JANUARY 3RD OR WIL SUBJECT TO 3RD PARTY STORAGE F Asset located in: Lahoma, OK
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5515	Digga PDI-13-13-DDS Excavator Auger - Fits John Deere 210 S/N: 1804110013 C/W: 75 mm Diameter Pins, 470 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside
5507	Asset located in: Corsicana, TX Quantity of (2) Pallets of Okada Padding Bucket Screens S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		to Inside Pin Boss Spacing, 16 in & 20 in Auger Bits Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5516	2019 Stanley MB/XP4035 Hydraulic Breaker S/N: XP40350054 C/W: 8000 lb class, 5.6 in Tool / Chisel, Fits Excavators Usage: Not Available Asset located in: Lake Worth, TX
5509	Asset located in: Corsicana, TX Contech 2200 Excavator Plate Compactor S/N: 7800220A1191132 Usage: Not Available Asset located in: Lake Worth, TX	5517	2024 JESON HM3300 Hydraulic Breaker (Unused) S/N: JQ HM 012 Usage: Not Available Asset located in: Lake Worth, TX
5510	Volvo ARM-EC380E-9FT6IN BARE Excavator stick S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5518	2024 Jisan JSB3200B Hydraulic Breaker (Unused) S/N: CP2404445 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5511	KBKC 72 in Excavator Rake - Fits Cat 320 (Unused) S/N: RR240122 Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5519	2024 JESON HM3200 Hydraulic Breaker (Unused) S/N: JQ HM 011 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5520	2024 JESON HM3150 Hydraulic Breaker (Unused) S/N: JQ HM 015 Usage: Not Available Asset located in: Lake Worth, TX	5529	2024 Jisan JSB2200T Hydraulic Breaker (Unused) S/N: CP2406139 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5521	2024 JQ POWER JQB3000STB Hydraulic Breaker (Unused) S/N: 814075918 Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5522	Asset located in: Lake Worth, TX 2024 JESON HM3070 Hydraulic Breaker (Unused) S/N: JQ HM 014 Usage: Not Available Asset located in: Lake Worth, TX	5530	FOR ILLUSTRATION PURPOSES OF	S/N: CP2407167 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5523	2024 JESON HM3070SL Skid Steer Breaker (Unused) S/N: JQHM010 Usage: Not Available Asset located in: Lake Worth, TX	5531	2024 Elephant EPB2200T Hydraulic Breaker S/N: CP2406053 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5524	2024 Jisan JSB2200B 144 mm Hydraulic Breaker (Unused) S/N: 2404338 Usage: Not Available	EE22	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX		Teran THH2000B Hydraulic Breaker - Fits Cat 320 (Unused)	
5525	2024 Jisan JSB2200B 140 mm Hydraulic Breaker (Unused) S/N: 2404339 Usage: Not Available Asset located in: Lake Worth, TX		S/N: CEH715D14HZ C/W: B Linkage For all 18-25 Ton Excavators - With Auto - Lubrication Pre-Disposition. Box Type - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With	
5526	2024 TOFT TOFT1550 Hydraulic Breaker (Unused) S/N: JW121Z0715 Usage: Not Available Asset located in: Lake Worth, TX		Kit, Toil Box With Mai Operations Manual. Usage: Not Available	
5527	2024 TOFT TOFT1400 Hydraulic Breaker (Unused) S/N: JW81Z3340 Usage: Not Available Asset located in: Lake Worth, TX	5533	2024 TOFT TOFT1000 Hydraulic Breaker (Unused) S/N: JW50Z2170 Usage: Not Available Asset located in: Lake Worth, TX	
5528	2024 Jisan JSB2200B Hydraulic Breaker (Unused) S/N: CP2404401 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	 5534	2024 Jisan JSB800B Hydraulic Breaker (Unused) S/N: CP2406128 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	5535	2024 Elephant EPB800T Hydraulic Breaker (Unused) S/N: CP2406101 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5536 5537	2024 Elephant EPB430BL Hydraulic Breaker (Unused) S/N: CP2406079 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan JSB430B Hydraulic Breaker	5543 5544	2024 Jisan JSB400B Hydraulic Breaker (Unused) S/N: CP2403166 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan JSB400BL Hydraulic Breaker	
	(Unused) S/N: CP2408266 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: CP2404523 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5540	2024 Elephant EPB430BL Hydraulic Breaker S/N: CP2406081 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Elephant EPB400T Hydraulic Breaker (Unused) S/N: CP2406114	5545	Teran THH400B-CAT308 Hydraulic Breaker - Fits Cat 307 (Unused) S/N: Not Available C/W: For Mini Excavators CAT 307/308 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Teran THH400BH Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAB00398C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre-	
5541	2024 Elephant EPB400T Hydraulic Breaker (Unused) S/N: CP2406112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Disposition - All New Teran H Hammers are supplied with a Point M Type, 2 Hoses, 1 Set Charging Kit with N2 Bottle a Gauge, 1 Spare Seal Kit, Too Maintenance Tools and Ope ManualWith Auto - Lubrication - All New Teran Hydraulic Ha supplied with 2 Chisels Moil Hoses, 1 Set of N2 Nitrogen	Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal
5542	2024 Jisan JSB400B Hydraulic Breaker (Unused) S/N: CP2403154 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5547	Teran THH400B-SSL Skid Steer Breaker - Fits Cat 226 (Unused) S/N: Not Available C/W: For Skid Steer Loader Cat 226-299 With Mounting Plate included -68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available	5555 5556	Kent 5 in Hydraulic Breaker - Fits John Deere 200C LC S/N: F272749 C/W: 80 mm Diameter Pins, 440 mm Center of Pin Boss to Center of Pin Boss, 325 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK Hydraulic Breaker
	Asset located in: Lake Worth, TX		S/N: Not Available
5548	Teran THH400BT Hydraulic Breaker - Fits Cat 416 (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: CAA3496B54HR C/W: For Backhoe Loaders CAT 416, 428, 444 -68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil	5557	Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available	5558	2024 TOFT TOFT280R Rotating Demolition Shear (Unused) S/N: TOFT280R24032 Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5549	Trojan 50CL Hydraulic Breaker - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused)	5559	2019 Hammer GRP150 15 in Excavator Grapple S/N: H183515GRP Usage: Not Available Asset located in: Lake Worth, TX
	S/N: SB40Y0M20246073 Usage: Not Available Asset located in : Lake Worth, TX	5560	Viper Metal VPH 3-1700 68 in Padding Excavator Bucket (Unused) S/N: Not Available
5550	Trojan 35CL Hydraulic Breaker - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: SB30YOM20246119 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
5551	Teledyne TB8309X Hydraulic Breaker		Asset located in: McAlester, OK
	S/N: 9991991983 Usage: Not Available Asset located in : Lake Worth, TX	5561	Viper Metal VPH 4-1500 57 in Padding Excavator Bucket (Unused)
5553	2017 Okada 100A Hydraulic Breaker S/N: 3160R C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
5554	Kelly Hydraulic Breaker - Fits Kelly CB7500		Asset located in: McAlester, OK
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5562	2019 Remu EX140 48 in Screening Excavator Bucket S/N: 14000062 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5563	Remu CAT C/EX140 48 in Padding Excavator Bucket - Fits REMU EX140 S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE	5569	2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 058 Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	5570	2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 040 Usage: Not Available
	Asset located in: McAlester, OK		Asset located in: Lake Worth, TX
5564	Excavator Bucket - Fits CAT EX140 S/N: B93283 Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE	5571	2024 Jisan BKT336D72HD 72 in Excavator Bucket (Unused) S/N: 24062202043 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	AVAILABLE Asset located in: McAlester, OK	5572	Teran BKT336D72HD 72 in Digging Excavator
5564A	Rockland 84 in Excavator Bucket S/N: 9757101 Usage: Not Available Asset located in: Lake Worth, TX		Bucket - Fits Cat 336D (Unused) S/N: 0838 C/W: DB Linkage - 2.00m3 for Cat 336D, 336D2, 336E, 336F, 340D2, 340F With Side Cutters Side Protectors Heel Shrouds Lip
5565	2024 Jisan BKT32078DB 78 in Cleanup Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: 24072902553		Protectors Reinforcement Plates and 6RC T - DB Linkage Usage: Not Available Asset located in : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5573	2024 JESON BKT 336-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 053 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5574	2024 Warrior WBRC40-1700 72 in Digging 40- 45T 1700mm to fit CAT349 Rock Excavator Bucket (Unused) S/N: 2024-09-20-JL01
5566	2024 JESON BKT 345-78 78 in Digging Excavator Bucket (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: JQ BKT 059 Usage: Not Available Asset located in : Lake Worth, TX	5575	2024 JESON BKT 345-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 039
5567	2024 JESON BKT 345-78 78 in Digging Excavator Bucket (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: JQ BKT 049 Usage: Not Available Asset located in: Lake Worth, TX	5576	2024 JESON BKT 345-66 66 in Excavator Bucket (Unused) S/N: JQBKT037
5568	2024 Jisan BKT34572HD 72 in Excavator Bucket (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 24072902536 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5577	2024 JESON BKT 345-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 057 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5578	2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 052 Usage: Not Available Asset located in: Lake Worth, TX	5586	2024 JESON BKT 336-60 60 in Digging Excavator Bucket (Unused) S/N: JQ BKT 023 Usage: Not Available Asset located in: Lake Worth, TX
5579	2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 028 Usage: Not Available Asset located in: Lake Worth, TX	5587	Esco 58 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: RH80487 Usage: Not Available Asset located in: Lake Worth, TX
5580	2024 Jisan BKT36066HD 66 in 2.2 cyd Digging Excavator Bucket - Fits Komatsu PC360 (Unused) S/N: 24072902567 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5588	Teran BKT325D54HD 54 in Digging Excavator Bucket - Fits Cat 329D (Unused) S/N: 3655 C/W: CB Linkage - 1.22m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6RC Tips Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5589	2024 Jisan BKT32054HD 54 in Excavator Bucket (Unused) S/N: 2406220204 Usage: Not Available
5581	2022 Werk-Brau 480-66-VO-HC 66 in Digging Excavator Bucket S/N: 48834 Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5500	·
5582 	2024 BTTL CAT345 60 in Digging Excavator Bucket (Unused) S/N: TOFTEB24581 Usage: Not Available Asset located in: Lake Worth, TX 2024 Elephant BKT336D60HD 60 in Excavator Bucket (Unused) S/N: 24062200411	5590	Teran BKT32054HD 54 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 1847 C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 6HD Tips Usage: Not Available Asset located in: Lake Worth, TX
5584	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan BKT336D60HD 60 in Excavator		2024 Elephant BKT22054HD 54 in Excavator Bucket (Unused) S/N: 2407280051 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	Bucket (Unused) S/N: 24062202027		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5592	2024 Jisan BKT22054HD 54 in Excavator Bucket (Unused) S/N: 24062300918 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5585	2024 JESON BKT 336-60 60 in Digging Excavator Bucket (Unused) S/N: JQ BKT 020 Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5593	C & P 60 in Digging Excavator Bucket S/N: NHK50615 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5594 5595	56 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: 1844 Usage: Not Available Asset located in: Lake Worth, TX 2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton	5601	Trojan 200CL 48 in Digging Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5602	Teran 48 in .88 cyd Digging Excavator Bucket - Fits Cat 312 S/N: BKT31248 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
5596	2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5603	Teran 48 in 1.16 cyd Digging Excavator Bucket - Fits Cat 320 S/N: BKT32048HD C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5604	48 in Q/C Digging Excavator Bucket S/N: 804560244191 Usage: Not Available
5597	2024 Elephant BKT32048HD 48 in Excavator Bucket (Unused) S/N: 24151503617 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Asset located in: Lake Worth, TX
		5605	Paladin 48 in Digging Excavator Bucket - Fits John Deere 350G S/N: J000094897-1 Usage: Not Available Asset located in: Lake Worth, TX
5598	Asset located in: Lake Worth, TX 2024 JESON BKT 320-48 48 in Digging Excavator Bucket (Unused) S/N: JQ BKT 054 Usage: Not Available	(Unused) S/N: TOFTEB24553 Usage: Not Available	S/N: TOFTEB24553
5599	Asset located in: Lake Worth, TX 2024 JESON BKT 320-48 48 in Digging Excavator Bucket (Unused) S/N: JQ BKT 055 Usage: Not Available Asset located in: Lake Worth, TX	5607	Trojan 120CL 42 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5600	Trojan 200CL 48 in Digging Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5608	Trojan 120CL 42 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Acceptation III. Lake Worth, 17	5609	Teran BKT30742 42 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 1208 C/W: 0.41m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 7HD Tips Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5610	2020 Cat A 42 BU 42 in Excavator Bucket S/N: 0XC702965 Usage: Not Available Asset located in: Lake Worth, TX	5619	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused)
5611	Komatsu 42 in Digging Excavator Bucket S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	5620	Trojan 80CL 30 in Digging Excavator Bucket -
5612	Teran BKT31236 36 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 5583 C/W: 312 Linkage - 0.48m3 for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available	5621	Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Trojan 80CL 30 in Digging Excavator Bucket -
	Asset located in: Lake Worth, TX		Fits 50mm Cat 307/308, Komatsu PC78/88
5613	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available	_	Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5622	Teran BKT30730 30 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 1205
5614	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused)		C/W: 0.27m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5623	2014 Tag 30 in Digging Excavator Bucket S/N: 102177-41 C/W: EQUIPMENT-FROM-SUNSTATE-
5615	Trojan 120CL 36 cyd Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135,		EQUIPMENT Usage: Not Available Asset located in: Oklahoma City, OK
	Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5624	30 in Q/C Digging Excavator Bucket S/N: 60941C Usage: Not Available Asset located in: Lake Worth, TX
5616	36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5625	Tooth Pro 26 in V-Ditching Excavator Bucket S/N: 2360 Usage: Not Available Asset located in: Lake Worth, TX
5617	Esco 36 in Excavator Bucket - Fits Komatsu PC220 S/N: 56553	5626	Teran BKT31224 24 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 0171
 5618	Usage: Not Available Asset located in: Lake Worth, TX 22 in Dissing Everyotes Bucket		C/W: 312 Linkage - 0.32m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 3HD Tips
3010	32 in Digging Excavator Bucket S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5627	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5628	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5635	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5629	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5636	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5630	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341	5637	24 in Digging Excavator Bucket S/N: 3181 Usage: Not Available Asset located in: Lake Worth, TX
5631	/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5638	2018 Cat B 24 BU 24 in Digging Excavator Bucket S/N: B-24-MHJ74545 Usage: Not Available Asset located in: Lake Worth, TX
3031	Frojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 Fits 45mm Cat 305, 305.5 Komatsu	5639	24 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5632	Usage: Not Available Asset located in: Lake Worth, TX Trojan 50CL 24 in Digging Excavator Bucket -	5640	24 in Digging Excavator Bucket S/N: Not Available Usage: Not Available
3032	Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Bobcat 24 in Q/C Digging Mini Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5633	Teran BKT305C24 24 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2941 C/W: 0.16m3 with Side Cutters Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5643	Rockland 18 in V-Ditching Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5634	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused)	5643A	Adco 16 in V-Ditching Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5644	Tooth Pro 15 in Mini Excavator Bucket S/N: 5707 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5645	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available	5653	12 in Q/C Digging Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5654	Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available
5646	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case,		C/W: (1) 7 in, (1) 23 in Usage: Not Available Asset located in: Lake Worth, TX
	New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5655	Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available C/W: (1) 7 in, (1) 23 in Usage: Not Available Asset located in: Lake Worth, TX
5647	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5656	2024 Jisan BKT34572SKEL 72 in Skeleton Excavator Bucket (Unused) S/N: 24072903037 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5648	Trojan 35CL 12 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Trojan 35CL 12 in Digging Excavator Bucket -	5657	2024 Elephant BKT336D72SKEL 72 in Skeleton Excavator Bucket (Unused) S/N: 2407290019 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
3049	Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5658	Asset located in: Lake Worth, TX 2024 JESON BKT 336-72 SKEL 78 in Skeleton Excavator Bucket (Unused) S/N: JQBKT051 Usage: Not Available Asset located in: Lake Worth, TX
5650	Trojan 35CL 12 cyd Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5659	2024 Jisan BKT336D66SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: 2409040117 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5651	Teran BKT305C12 12 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2920 C/W: 0.08m3 With Side Cutters Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5660	Asset located in: Lake Worth, TX 2024 JESON BKT 336-66 SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: JQ BKT 056 Usage: Not Available Asset located in: Lake Worth, TX
5652	Tooth Pro 12 in Mini Excavator Bucket S/N: 5480 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5661	2024 JESON BKT 336-66 SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: JQ BKT 050 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5662	2024 Warrior WBSC30-1600 62 in Skeleton Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5668	2024 TOFT CAT336 48 in Skeleton Excavator Bucket (Unused) S/N: TOFTEB24674 Usage: Not Available Asset located in: Lake Worth, TX
		5669	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT
5663	Teran BKT325D60SKEL 60 in Skeleton Excavator Bucket - Fits Cat 329D (Unused) S/N: 2220 C/W: CB Linkage - 1.14m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters		IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips Usage: Not Available Asset located in : Lake Worth, TX	5670	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available
5664	2024 Jisan BKT32060SKEL 60 in Skeleton Excavator Bucket (Unused) S/N: 24072903014 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	C/W: 80 m Pin Boss to to Inside P IMAGES SI PURPOSES EXACT REI PRODUCT Usage: No	C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL
5665	Asset located in: Lake Worth, TX Teran BKT32054SKEL 54 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 2159 C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6HD Tips 80mm Pins Usage: Not Available	5671	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5666	Asset located in: Lake Worth, TX 2024 Jisan BKT32048SKEL 48 in Skeleton	-	Usage: Not Available Asset located in: Lake Worth, TX
	Excavator Bucket (Unused) S/N: 2407290301 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5672	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT
5667	Teran BKT31248SKEL 48 in Skeleton Excavator Bucket - Fits Cat 312 (Unused) S/N: 3112 C/W: 312 Linkage - 0.77m3 for CAT 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F,		IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	314D, 314E, 314F, 315F with Side Cutters and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5673	Teran BKT30742SKEL 42 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 0573 C/W: 0.39m3 for Cat 307, 308 with 5 HD Tips Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5674	Teran BKT30736SKEL 36 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 1126 C/W: 0.34m3 for Cat 307/308 with 6HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5681	Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available
5675	Trojan 200CL 72 in Tilting Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210		Usage: Not Available Asset located in: Lake Worth, TX
	Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5676	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5683	Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available
5677	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5684	Asset located in: Lake Worth, TX Trojan 200CL 72 in Ditch Cleaning Excavator Bucket - Fits 80mm Cat 320/321/323, Hyun R210 Komatsu PC200/220, Deere 160/200 /225 Kobelco SK210, Case 210/225, Doosal DX225 (Unused) S/N: Not Available
5678	Trojan 80CL 48 in Tilting Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88		Usage: Not Available Asset located in: Lake Worth, TX
5679	Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Trojan 80CL 48 in Tilting Excavator Bucket -	5685 5686 5687	Teran BKT32072CLN 72 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 4843 C/W: B Linkage - 0.66m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available
	Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available		Asset located in: Lake Worth, TX 72 in Excavator Bucket - Fits Mobile Excavator S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5680	Asset located in: Lake Worth, TX Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Teran BKT32060CLN 60 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 1319 C/W: B Linkage - 0.54m3 for CAT 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5688	2024 Warrior WBRC30-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside	5693	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5694	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available
5689	2024 Warrior WBRC30-1500 59 in Cleanup Excavator Bucket - Fits Cat 320/ 20 - 25 ton		Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5695	Teran BKT31260CLN 60 in Cleanup Excavator Bucket - Fits Cat 312 (Unused) S/N: 0183 C/W: 312 Linkage - 0.38m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Lake Worth, TX
		5696	Trojan 80CL 48 in Ditch Cleaning Excavator
5690	Asset located in: Lake Worth, TX 2024 Warrior WBMCC20-1500 60 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5697	Trojan 80CL 48 in Ditch Cleaning Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused)
5691	2024 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused)		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL	5698	Teran BKT30748CLN 48 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3045 C/W: 0.23m3 for Cat 307/308 Usage: Not Available Asset located in: Lake Worth, TX
	PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5699	Teran BKT305C48CLN 48 in Cleanup Excavator Bucket - Fits Cat 305 (Unused)
5692	Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused)		S/N: 01071 C/W: 0.15m3 Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5700	Teran BKT30448CLN 48 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 2301 C/W: 0.15m3 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5701	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D /G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available	5709	Bobcat 36 in Q/C Mini Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5710	84 in Bucket
5702	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
	/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5711	2019 Viper 3-1700 67.5 in Padding Shaker Bucket - Fits Komatsu PC200 S/N: 3-17001714 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside
5703	Teran BKT30742CLN 42 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3032 C/W: 0.20m3 for Cat 307/308 Usage: Not Available Asset located in: Lake Worth, TX		to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
5704	Trojan 35CL 42 in Ditch Cleaning Excavator		Asset located in: McAlester, OK
	Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D /G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5712	2019 Viper 4-1100 48 in Padding Shaker Bucket S/N: 4-1100218 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside to Inside Pin Boss Spacing Usage: Not Available
5705	Trojan 35CL 42 in Ditch Cleaning Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D /G (Unused) S/N: Not Available Usage: Not Available		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Asset located in: Lake Worth, TX	5713	2018 Viper 4-1100 48 in Padding Shaker
5706	Teran BKT30342CLN 42 in Cleanup Excavator Bucket - Fits Cat 303 (Unused) S/N: 2836 C/W: 0.13m3 Usage: Not Available Asset located in: Lake Worth, TX		Bucket - Fits Komatsu PC-200 S/N: 4-1100214 C/W: 80 mm Diameter Pins, 415 mm Center of Pin Boss to Center of Pin Boss, 328 mm Inside to Inside Pin Boss Spacing Usage: Not Available
5707	Teran BKT30436CLN 36 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 01063 C/W: 0.12m3 Usage: Not Available Asset located in: Lake Worth, TX		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
5708	Teran BKT30136CLN 36 in Cleanup Excavator Bucket - Fits Cat 301 (Unused) S/N: 2645 C/W: 0.07m3 30mm Pins Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5715	REMU EX140 48 in Padding Bucket - Fits Cat S/N: 14270 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE	5722	American Compaction DC18S 18 in Q/C Excavator Compaction Wheel S/N: 100711104 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5723	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 0801012007 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5716	REMU EX140 48 in Padding Bucket - Fits Cat		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 14268 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	5724	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 121817519 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5725	Rockland 24 in Excavator Compaction Wheel S/N: 9412601 C/W: EQUIPMENT-FROM-A-PRIMORIS-
5717	19.5 in Digging Bucket - Fits Hitachi 160 S/N: 779435681 C/W: 80 mm Diameter Pins, 392 mm Center of Pin Boss to Center of Pin Boss, 307 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX
		5726	American Compaction DC18S 18 in Excavator Compaction Wheel S/N: 111012261 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Lahoma, OK		American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 041212842
5718	Tooth Pro 25 in Digging Bucket S/N: 3333 C/W: 80 mm Diameter Pins, 390 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside		
	to Inside Pin Boss Spacing Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	5728	Tooth Pro 24 in Excavator Compaction Wheel S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	5729	Rockland 24 in Excavator Compaction Wheel S/N: 7102601
5719	82 in Q/C Wheel Loader Bucket S/N: CH031182522 Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX
5721	61 in Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5730	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 031012020 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5739	2024 Jisan QCCAT320 Excavator Coupler (Unused) S/N: 24042900737 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5731	American Compaction DC24BLWP 24 in Excavator Compaction Wheel		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: 041212819 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5740	2024 Elephant QCCAT320 Excavator Coupler (Unused) S/N: 2407290022 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5732	Entek 36 in Excavator Compaction Wheel S/N: 8420 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5741	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Teran QCCAT305 Excavator Coupler - Fits Cat
5733	Rockland WE36-4 36 in Excavator Compaction Wheel S/N: 7921501 C/W: EQUIPMENT-FROM-A-PRIMORIS-	5742	305 (Unused) S/N: 2014 C/W: For Cat 305 - 45mm Pins Usage: Not Available Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX		Quantity of (2) Pallets of Cat Excavator Coupler - Fits Cat
5734	Entek 18 in Excavator Compaction Wheel S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
5735	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 080710899		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX Quantity of (3) Pallets of Cat Excavator Coupler - Fits Cat
5736	2015 Vacuworx RC12 Vacuum Lifter S/N: RC1200144 Usage: 413 Hr Asset located in: Sulphur, LA		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
5737	2007 Superior SVL90 Pipe Vacuum Lifter S/N: VL153 Usage: Not Available Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
5738	2024 Jisan QCCAT336D Excavator Coupler (Unused) S/N: 24042900759 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
5744	Quantity of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5750	2024 TOFT TOFT04G Excavator Grapple (Unused) S/N: TOFTHG24110 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5752	Tysea 60 in Q/C Clamshell Style Q/C Hydraulic Excavator Grapple S/N: TY14465 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5745	Asset located in: Corsicana, TX Cat Executer Coupler		Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE
3/43	Cat Excavator Coupler S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5753	Tysea 60 in Hydraulic Excavator Grapple S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	5754	2024 Elephant RAKE32065 65 in Excavator Rake (Unused)
5746 	Simex SM3-17 84 in Excavator Crusher Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Elephant JXJMQC345 51 in Excavator		S/N: 24072900230 Usage: Not Available Notes : THE PRODUCT I FOR ILLUSTRATION PU MAY NOT BE AN EXAC
	Grapple (Unused) S/N: 24072900212		Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5755	2024 Jisan RIPPER336D Excavator Ripper (Unused) S/N: 24072903240 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5748	2024 Elephant JXJMQC336 46 in Excavator Grapple (Unused)		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5749	S/N: 2406220032 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Jisan JXJMQC320 44 in Excavator Grapple (Unused)	5756	2024 Elephant RIPPER320 Excavator Ripper (Unused) S/N: 24072900226 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: 2407290131 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5757	2024 Jisan RIPPER320 Excavator Ripper (Unused) S/N: 24072903228 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5758	2024 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5765 5766	REMU EX140 48 in Q/C Screening Excavator Screening Bucket S/N: 14000061 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX REMU EX140 48 in Q/C Screening Excavator	
5759	Asset located in: Lake Worth, TX 2024 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION DIAMOGES SHOWN ARE FOR ILLUSTRATION	5767	Screening Bucket S/N: 14000058 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REM FROM MACHINE	S/N: 14000058 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED
	PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Okada TMB70 Excavator Screening Bucket S/N: 508 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	
5760	Teran RIPPER307 Excavator Ripper - Fits Cat 307 (Unused) S/N: 1307		Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
	C/W: For Cat 307/308 50mm Pin Usage: Not Available Asset located in : Lake Worth, TX		Okada TMB70 Trommel Excavator Screening Bucket S/N: 262	
5761	2024 TOFT TOFT08R Excavator Ripper (Unused) S/N: TOFTERP24117 Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
5762 5763	2024 TOFT TOFT04R Excavator Ripper (Unused) S/N: TOFTERP24073147 Usage: Not Available Asset located in: Lake Worth, TX Trojan 200CL 72 in Excavator Screening	5769 Okada TMB70 Excavator Screening Bucker S/N: 7050 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMO FROM MACHINE Asset located in: Lake Worth, TX	Okada TMB70 Excavator Screening Bucket S/N: 7050 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	
3703	Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200		FROM MACHINE	
	/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	
5764	REMU PD3150 69 in Q/C Screening Excavator Screening Bucket - Fits CAT C/EX140 S/N: B99434	5771	Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
	C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX		Okada TMB70 Excavator Screening Bucket S/N: 351 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5772	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903054 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5780	Teran THUMB5M 11 in Excavator Thumb - Fits Cat 305 (Unused) S/N: 3177 C/W: Manual Thumb for Cat 305 and 5 Ton Mini Excavators Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5781	Teran THUMB2-3.5M 8 in Excavator Thumb - Fits Cat 303 (Unused)
5773	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903057 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		S/N: Not Available C/W: Manual Thumb for all 2-3.5 Ton Mini Excavators Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5782	Trojan 120CL Excavator Thumb - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere /Hitachi ZX120/135 Case 130/135, Doosan
5774	Quantity of (2) Cat Excavator Thumb - Fits Cat 320 S/N: Not Available		DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: (1) 28 In Hydraulic, (1) 24 In Manual Usage: Not Available Asset located in : Lake Worth, TX	5783 5784 5785	Trojan 120CL Excavator Thumb - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere
5775	Teran THUMB30-35 M 40 in Excavator Thumb - Fits Cat 336D (Unused) S/N: Not Available C/W: 4 Tines - For Cat 330,336D and 30-36 Ton Excavators		/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		Gentec HT1035 30 in Excavator Thumb S/N: Not Available C/W: Hydraulic - Fits loader-backhoes & excavators from 10000 to 20000 lbs Usage: Not Available Asset located in: Lake Worth, TX
5776	Trojan 200CL Excavator Thumb - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco		
	SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Trojan 80CL Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75 /85 Case, New Holland, Kobelco SK80 Bobcat
5777	Trojan 200CL Excavator Thumb - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco		E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5786	Diesel Equipment 80CL 16 in Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland,
5778	Teran THUMB20-25 M 30 in Excavator Thumb - Fits Cat 320 (Unused) S/N: Not Available C/W: 4 Tines - For Cat 320,325 and 20 - 25 Ton		Kobelco SK80 Bobcat E80 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Excavators Usage: Not Available Asset located in: Lake Worth, TX		2022 Rockland BTH-CL Excavator Thumb - Fits Rockland BTHCL S/N: 238845
5779	Teran THUMB12 - 15 M 26 in Excavator Thumb - Fits Cat 312 (Unused) S/N: 3188 C/W: For Cat 312, 315 and all 12-15 Ton Excavators 4 Tines Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5788	Quantity of (4) Cat Excavator Thumb - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5794	Gentec HT830 25 in Excavator Thumb S/N: Not Available C/W: Fits loader-backhoes & excavators from 6000 - 10000 lbs Usage: Not Available Asset located in: Lake Worth, TX
		5795	Gentec MT830 Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5789	Asset located in: Corsicana, TX Quantity of (4) Cat Excavator Thumb S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	5796	Gentec MT824 - Fits mini excavators from 4000 - 9000 lbs Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5797	Trojan 35CL Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Corsicana, TX	5798	Trojan 35CL Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco
5790	Trojan 80CL Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75 /85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused)		SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: XD202408201 Usage: Not Available Asset located in : Lake Worth, TX		Diesel Equipment 35CL 14 in Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G
5791	Trojan 50CL Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused)		(Unused) S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	5800	Gentec HT618 16 in Excavator Thumb - Fits Gentec S/N: Not Available
5792	Trojan 50CL Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland,		C/W: Fits mini excavators up to 4000 lbs Usage: Not Available Asset located in: Lake Worth, TX
	Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5801	Excavator Thumb S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
5793	Diesel Equipment 50CL 15 in Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
5802	2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused) S/N: DM20241009164 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5811	Cat Radiator - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
5803	Edge TH4800 48 in Skid Steer Mulcher S/N: TH0226 Usage: Not Available		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Corsicana, TX
	Asset located in: Lake Worth, TX	5812	Cat Scarifier
5804	Fecon 90 in Mulcher Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5805	2024 Jisan JSV765S Demolition Pulverizer (Unused) S/N: 24072903210 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	THE ACTUAL PRODUCT	5813	Quantity of Cat Misc. Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
5806	Asset located in: Lake Worth, TX 2024 TOFT TOFT08P Demolition Pulverizer (Unused) S/N: TOFTHP24107 Usage: Not Available Asset located in: Lake Worth, TX		
5807	Bodine 200 Demolition Pulverizer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
5808	Quantity of (4) Crawler Pipelayer Side Booms S/N: Not Available C/W: (2) 20 ft, (1) 18 ft, (1) 13 ft Usage: Not Available Asset located in: Lake Worth, TX	5814	Cat Pipelayer hook and block - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5809	Hill 144 in Dozer Rake S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
5810	Cat Light brackets - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
5815	Quantity of (3) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5819	System One Undercarriage Chain / Rails - Fits Cat D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
5816	Quantity of (3) Pallets of Trunnion ball - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	5820	Asset located in: Corsicana, TX Cat Crawler Tractor Counterweight (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX
 5817	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of (4) Hook & Block	5821	Cat Crawler Tractor Counterweight (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5818	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of (4) Hook & Block	5822	Asset located in: Lake Worth, TX Cat Crawler Tractor Drawbar - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5823 5824	Carco Crawler Tractor Winch - Fits Cat D8 S/N: 12608 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX Carco Crawler Tractor Winch - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
		5826	2012 Midwestern M 530C Winch Pipe Laying System: Fits Cat D5 Dozer Attachment S/N: 13A12187 C/W: 15 Ft Folding Boom Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5827	Rear Screen Dozer Attachment - Fits John Deere 700K S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	5833	Allied W6G Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX	
		5834	Cat Crawler Tractor Winch - Fits Cat S/N: Not Available	
5828	Allied W6G Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	
5829	Paccar PA56 Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX	5835	198 in Angle Dozer Blade - Fits Cat D6 LGP S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	
5830	Paccar PA56 Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5836	SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADO	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX		194 in Angle Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
5831	Paccar PA56 Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	
5832	Paccar PA56 Crawler Tractor Winch S/N: 1300340 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE; TO FIT CAT D6T/D6 - CAME OFF WATKINS DOZERS IN THE AUCTION Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
5843	164 in Angle Dozer Blade - Fits Cat D6T XL	5852	160 in Angle Dozer Blade - Fits Cat D6TXL
3643	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	3632	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Corsicana, TX		Asset located in: Corsicana, TX
5844	162 in U-Blade Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	5853	152 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
-	Asset located in: Corsicana, TX		Asset located in: Corsicana, TX
5846	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5854	150 in Angle Dozer Blade - Fits Cat D6DT S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Corsicana, TX		Asset located in: Corsicana, TX
5851	160 in Angle Dozer Blade - Fits Cat D6T XL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	5855	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	ASSEL IUCALEU III. COI SICAITA, TA		ASSEL IUCALEU III. COISICAITA, TA

Lot #	Details	Lot #	Details
5856	148 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5862	Mini Excavator 280x72x56 Rubber Tracks S/N: Not Available C/W: 12 in, one set Usage: Not Available Asset located in: Lake Worth, TX
		5863	Bobcat Mini Excavator 12 In All Purpose Rubber Tracks S/N: Not Available C/W: (1) 300x 52.5x74, (1) 300x52.5x98 Usage: Not Available Asset located in: Lake Worth, TX
-	Asset located in: Corsicana, TX	5864	Cat scarifier, drawbars, trench box - Fits Cat
5857	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Corsicana, TX		Asset located in: Corsicana, TX
5858	128 in PAT Dozer Blade - Fits Cat D6M	5867	90 in Multi-Shank Motor Grader Ripper - Fits Cat 140G
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		S/N: RP125 Usage: Not Available Asset located in : Lake Worth, TX
		5867A	Motor Grader Scarifier - Fits Cat 140M S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5868	AMI JRB416 108 in 3.5 cyd Q/C Grapple Wheel Loader Bucket - Fits Hyundai HL955
5859	Bobcat 96 in PAT Skid Steer Dozer S/N: 224403408 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 21041840101 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5860	24 in single grouser Tracks - Fits Cat D6 S/N: Not Available C/W: System 1 ; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5869	102 in Q/C Wheel Loader Bucket S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	5870	2022 Cat IT 1.5YD BU 96 in Q/C Wheel Loader Bucket S/N: CY220505839 Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Corsicana, TX	5871	2022 Cat 908 1.4YD E ISO 82 in Q/C General
5861	Ditch Witch Drill Rubber Tracks S/N: Not Available C/W: 300x52.5x98, 12 in Usage: Not Available Asset located in: Lake Worth, TX		Purpose Wheel Loader Bucket S/N: CH031182822 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5872 5873	2022 Cat 908 1.4YD E ISO 82 in Q/C General Purpose Wheel Loader Bucket S/N: CH031183322 Usage: Not Available Asset located in: Lake Worth, TX 2022 Cat 908 1.4YD E ISO 82 in Q/C Wheel Loader Bucket S/N: CH021139822	5884	884 60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
	Usage: Not Available Asset located in: Lake Worth, TX		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
5875	JRB 102 in Q/C Wheel Loader Bucket - Fits Case 621D/ New Holland LW130B S/N: 0106-172069-211 Usage: Not Available Asset located in: Lake Worth, TX	5885	Asset located in: Corsicana, TX 60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
5876	2018 Volvo L150H4.7POSPN 35 m3 Digging Wheel Loader Bucket S/N: 18599 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
5877	KA Fabrication 164 in Q/C Wheel Loader Forks - Fits Hyundai HL955		THESE Asset located in: Corsicana, TX
	S/N: KA3246 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5885A	56 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5878	96 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5886	53 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5879	2021 BR Co 84 in Q/C Wheel Loader Forks - Fits Hyundai HL955 S/N: 63782 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5887	Balderson BF9360 59 in Q/C Wheel Loader Forks - Fits Cat 950 S/N: 3WL1826 C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: FITS LOT 114 - CAT 950E
5881	Cat 72 in Q/C Wheel Loader Forks - Fits Cat 950 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5888	Asset located in: Lake Worth, TX 68 in Wheel Loader Quick Coupler S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5882	JRB 60 in Q/C Wheel Loader Forks S/N: J458821 Usage: Not Available Asset located in: Lake Worth, TX		
5883	Pemberton 60 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5883A	60 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5889	Teran THH400BH Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAB00407C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen	5896	2013 Woods Wainroy 30 in Backhoe Rear Bucket S/N: 102344430 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Oklahoma City, OK
	Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are	5897	28 in Digging Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available	5898	24 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5890	Asset located in: Lake Worth, TX Teran THH400BT Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAA2730B54HR Usage: Not Available	5899	Tooth Pro 18 in Backhoe Rear Bucket S/N: 2382 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5890A	Asset located in: Lake Worth, TX Stanley Q/C Backhoe Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5900	Geith 18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5891	2018 Stanley MBX15E09 Q/C Backhoe Hydraulic Breaker S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5901	Tooth Pro 18 in Backhoe Rear Bucket S/N: 5108 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5892	Construction Tools RX8-11 Backhoe Hydraulic Breaker S/N: BES062129 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5902 5903	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 17 in Backhoe Rear Bucket
5893	FRD F6 Q/C Backhoe Hydraulic Breaker S/N: 12453 Usage: Not Available Asset located in: Lake Worth, TX	3903	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX
5894	Kent F6 Backhoe Hydraulic Breaker S/N: 6137 Usage: Not Available Asset located in: Lake Worth, TX	5904	Hensley 13 in Backhoe Rear Bucket S/N: 19943 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5895	Tooth Pro 46 in Cleanup Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5905	Asset located in: Lake Worth, TX 12 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5906	Strickland 12 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5916 5917 5918	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5907	12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-		
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX		Tag 12 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-
5908	16 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX Tooth Pro 18 in V-Ditching Backhoe Rear
5909	Asset located in: Lake Worth, TX 12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Bucket S/N: 2611 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5910	Hensley 16 in V-Ditching Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5919	24 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5911	Quantity of (2) 18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5920	Hensley 16 in V-Ditching Backhoe Rear Bucket S/N: 33666 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5912	Bobcat 18 in Q/C Digging Backhoe Rear Bucket S/N: 1720020 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5921	Hensley 12 in Digging Backhoe Rear Bucket S/N: 19884 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5913	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5922	Asset located in: Lake Worth, TX Tooth Pro 18 in V-Ditching Backhoe Rear Bucket S/N: 4933 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5914	24 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-		Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX	5923	Tooth Pro 12 in Backhoe Rear Bucket S/N: 2916 C/W: EQUIPMENT-FROM-A-PRIMORIS-
5915	John Deere 18 in Backhoe Rear Bucket S/N: 1852831 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details	
5924	24 in Digging Backhoe Rear Bucket	5933	Cat 96 in Backhoe Loader Bucket	
	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-		S/N: 190300051 Usage: Not Available	
	SERVICES-CORP-COMPANY		Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	5934	Cat 96 in Backhoe Loader Bucket	
5925	WB 12 in Backhoe Rear Bucket	1	S/N: 190500058 Usage: Not Available	
	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-		Asset located in: Lake Worth, TX	
	SERVICES-CORP-COMPANY	5935	96 in Forks	
	Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available	
5926	Quantity of (2) 60 in Backhoe Forks		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5936	Quantity of (6) 72 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
5927	42 in Backhoe Forks - Fits Terex 760	1	Asset located in: Corsicana, TX	
	S/N: Not Available C/W: accessories Usage: Not Available Asset located in: Lake Worth, TX	5937	Quantity of (4) 72 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
5928	Quantity of (3) 48 in Backhoe Forks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		BE PICKED UP WITHIN 14 DAYS OF TAUCTION (JANUARY 3RD) OR WILL IS SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOUT	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL	5938	Quantity of (4) 48 in Fork tines	
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
5929	48 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	_	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	
5930	44 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Corsicana, TX	
5931	Cat 96 in Backhoe Loader Bucket S/N: 190300052 Usage: Not Available Asset located in: Lake Worth, TX			
5932	Cat 96 in Backhoe Loader Bucket S/N: 190300048 Usage: Not Available Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
5939	939 Quantity of (8) 40 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	5949	30 in Auger Bit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5949A	Quantity of (2) System One Idlers - Fits Cat D6T S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	5950	2024 Mower King SSECAGY Skid Steer Auger (Unused) S/N: SSECAG-Y24060902F
5941	Quantity of (2) 48 ln x 56 ln Screens S/N: Not Available Usage: Not Available		C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits Usage: Not Available Asset located in : Oklahoma City, OK
5942	Asset located in: Lake Worth, TX Post Driver Guide S/N: Not Available Usage: Not Available	5952	CXI 44 in Excavator Grapple S/N: ZZA1398 Usage: Not Available Asset located in: Lake Worth, TX
5943	Asset located in: Lake Worth, TX Quantity of Forks (Unused) S/N: Not Available C/W: (1) 48 in set, (1) 42 in set Usage: Not Available Asset located in: Lake Worth, TX	5953	Quantity of (2) 2024 Landhonor BA-22-09W 105 in Tractor Rear Blade Blade Attachment (Unused) S/N: HL00018/HL00017 C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX
5944	Post Driver Guide S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5954	Frontier LL1410 119 in Land Leveler Box Blade S/N: XFLL14X000009 Usage: Not Available Asset located in: Lake Worth, TX
5945	38 In x 98 In Material Basket S/N: Not Available C/W: fork pockets Usage: Not Available Asset located in: Lake Worth, TX	5956	2024 Industrias America F10T 10 ft Box Scraper (Unused) S/N: F10T202435760 Usage: Not Available Asset located in: Lake Worth, TX
5946 5947	Post Driver Guide S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 44 in Misc. attachment	5957	2024 Industrias America F08T 96 in Box Scraper (Unused) S/N: F08T202537998 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5958	2005 ICON 18D 4 Tire Hydraulic Pull Scraper S/N: 5075A C/W: Lead Scraper, 20.5x25 Tires Usage: Not Available Asset located in: Lake Worth, TX
		5961	Volvo 72 in Wheel Loader Forks S/N: 15200002 Usage: Not Available Asset located in: Lake Worth, TX
5948	Asset located in: Corsicana, TX American Compaction DC18S 18 in Q/C Excavator Compaction Wheel S/N: 04038094	- 5965	Volvo 48 in L50-L120 Fork Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX	5966	42 in Fork Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
S/N: Not Availab C/W: THE PRODI FOR ILLUSTRATI MAY NOT BE AN	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5973	96 in Fork Extensions S/N: Not Available C/W: Vise Stand Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5974	Volvo Wheel Loader Material Handling Arm S/N: 252 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5976	Caldwell 8000 lb Material Handling Arm - Fits Forklift
5968	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	5976A	2013 Arrow 1000100-12-152 140 in Material
5969	2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Handling Arm S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5979	2024 Jisan JSC160 Excavator Plate Compactor (Unused) S/N: 24072903224 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5970	2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Apost located in: Lake Worth, TY
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5000	Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5980	2024 Jisan JSC50 Excavator Plate Compactor (Unused) S/N: 2404290048 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5971	Quantity of (5) 2024 Wolverine EX-66-78L/84L	5001	<u> </u>
5972	Sets of 78 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 84 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX	5981	2024 Elephant EPC50 Excavator Plate Compactor (Unused) S/N: 24072900219 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5983	Teran QCCAT336D Quick Coupler - Fits Cat 336D (Unused) S/N: 5704 C/W: DB Linkage for Cat 330D, 336D Usage: Not Available Asset located in: Lake Worth, TX	5994	Johnson 4 Sheave Hook Block S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5984	Teran QCCAT320 Quick Coupler - Fits Cat 320 (Unused) S/N: 5311 C/W: B Linkage - 80mm Pins Usage: Not Available Asset located in: Lake Worth, TX	5995	60 ton 5 Sheave Hook Block S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5985	Teran QCCAT312 Quick Coupler - Fits Cat 312 (Unused) S/N: 6159 C/W: 312 Linkage for Cat 311, 312, 314 - 65mm Pins Usage: Not Available	5996	Crane Ball S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5986	Asset located in: Lake Worth, TX Quantity of (4) 16 In Trench Compactor Drums S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5997	Quantity of (2) Material Handling Arm S/N: Not Available C/W: (1) Arrow CE60TH 6000 lb 80 in boom, (1) 116 in boom Usage: Not Available Asset located in: Lake Worth, TX
5987	23 in Excavator Compaction Wheel S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5998	40 ft Crane Boom - Fits Grove S/N: Not Available C/W: 23 Ft Swimg Away Job Usage: Not Available
5988	66 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5999	Asset located in: Lake Worth, TX 60 ton 5 Sheave Hook Block S/N: Not Available Usage: Not Available
5989	66 in Padfoot Shell Kit - Fits Padfoot Shell Kit (Unused) S/N: 32598 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: FITS LOT 294A AND 294B OR INGERSOLL RAND 66IN ROLLER	6000	Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX
5990	Asset located in: Lake Worth, TX 2018 Cat CS34 50 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6001	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX
5991	Quantity of (4) 48 In x 48 In Steel Crane Pads S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6002	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available
5992	Quantity of (4) 48 In x 50 In Steel Crane Pads S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6003	Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available
5993	Quantity of (3) Crane Caps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6004	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6012B	SKLP 60 in 3-Point 9 Row No Till Drill (Unused) S/N: BZJ9240616 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX
6005	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	6013	Scherer 28 In Kernel Processor S/N: W0602106010 Usage: Not Available Asset located in: Lake Worth, TX
6006	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available	_6013A	Strauss Clipper 20 ft Offset Sickle Bar Mower S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Assorted Size, One Pallet Usage: Not Available Asset located in : Lake Worth, TX	6014	2012 Rhino SE8 15 ft 0 in Batwing Brush Cutter Attachment - Fits Tractor Drawbar S/N: 11278
6007	2025 Double A 18 ft Bale Mover (Unused) S/N: 1UFBU182XST012578 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	6015	60 in Rotary Brush Cutter S/N: Not Available
6008	2024 Landhonor UC-22-60W Bale Unroller (Unused)		Usage: Not Available Asset located in: Midland, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6016	Land Pride RCF2060 60 in 3-Point Brush Cutter S/N: Not Available C/W: 540 PTO
6009	2024 Landhonor UC-22-60W Bale Unroller (Unused)		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6017 60 in 3-Point Brush Cutter S/N: Not Available C/W: 540 PTO	
6010	1999 Rome TAW20S 10 ft Disc S/N: 10TAW3237R		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 25 in Notched Front Discs, 26 in Notched Rear Discs, 11 in Spacing, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Livingston, LA	6017A	6 ft 3-Point Hitch Rotary Mower S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX
6011	International 5100 13 ft 16 ft Pull-Type Air Drill S/N: 0390213C003164 C/W: 7 in Spacing, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX	6017B	John Deere MX15 15 ft Batwing Brush Cutter S/N: W0MX15E001181 C/W: 540 PTO Usage: Not Available
6012	Case 12 ft Seed Drill	6018	Asset located in: Lake Worth, TX Steel Fluid Filter Tank
	S/N: 0419636 C/W: 4 in Spacing, 13 in Discs Usage: Not Available Asset located in : Lake Worth, TX	0018	S/N: Not Available C/W: 3 Compartments Usage: Not Available
6012A		 	Asset located in: Lake Worth, TX
OUIZA	SKLP 60 in 3-Point 9 Row No Till Drill (Unused) S/N: BZJ9240617 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX	6019	Scherer 28 In Kernel Processor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6020	Quantity of Ratchet Binders S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6029	Burcham Ultimate Bagger Electric Sandbag Filling Machine S/N: Not Available C/W: 12 in Conveyor, DeWalt 4 Gal Air Compressor, 12 in Conveyor & Accessories	
6021	Land Pride PD15 10 in 3-Point 15 Series Utility Post Hole Digger		Usage: Not Available Asset located in : Lake Worth, TX	
	S/N: 1747822 C/W: 540 PTO Usage: Not Available Asset located in : Lake Worth, TX	6030	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available	
6022	Land Pride RCR1260 60 in 3-Point Brush Cutter S/N: 1820706		Asset located in: Lake Worth, TX	
	C/W: 540 PTO, 3 hp Standard Duty w/Shear Bolt Usage: Not Available Asset located in: Lake Worth, TX	6031	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
6024	Cat Bale Spear S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	6032	2024 Genius GSM-66IN Separator Magnet (Unused) S/N: GSM09112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	THESE Asset located in: Corsicana, TX	6033	2024 Genius GSM-66IN Separator Magnet (Unused)	
6025 6025A	Euro Double 42 in Bale Spear S/N: Not Available C/W: c/w: 2 prongs and stabilizer prong Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Auger Bit		S/N: G Usage Notes FOR IL MAY N THE A	S/N: GSM09111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: Not Available C/W: (1) 15 in, (1) 22 In, (1) 30 In Usage: Not Available Asset located in : Lake Worth, TX	6034	2024 Paladin SM-66-3206E 32 in x 6 ft Separator Magnet (Unused) S/N: Not Available	
6027	2024 Landhonor SMS-64-40G Skid-Mounted Screen (Unused) S/N: Not Available C/W: 4 ft 9 in x 4 ft 2 in Double Deck Screen Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES O MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCTHE PRODU SHOWN ARE FOR ILLUSTRATION ONLY AND MAY NOT BE AN EXAC	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6028	2024 Suihe VG Skid-Mounted Vibratory Screen (Unused)		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: 5 ft x 4 ft 6 in Double Deck Screen, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE	6035	Storage Container S/N: 2-682990-01 Usage: Not Available Asset located in: Midland, TX	
, I I I	NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6036	16 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (0) Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6037	20 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (4) 96 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX 8 ft x 18 ft Trench Shield S/N: 982669 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available	6044	2024 Suihe BX-5 5 cyd Bedding Box (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6039	Asset located in: Lake Worth, TX 20 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (4) 96 in Spreader Bars	6045	Quantity of (2) 2024 Kit Containers Steel 5 ft 4 in x 8 ft 2 in (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
6040	Usage: Not Available Asset located in: Lake Worth, TX 16 ft x 8 ft Trench Shield S/N: 982678 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available	6046	Quantity of (2) 2024 Kit Containers Steel 5 ft x 8 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
6041	Asset located in: Lake Worth, TX 2024 Suihe BX-12 12 cyd Bedding Box (Unused) 5/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6047	Quantity of (2) 2024 Kit Containers Steel 5 ft x 8 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6048	Quantity of (2) 2024 Kit Containers Steel 6 ft x 8 ft 3 in (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
6042	2024 Suihe BX-9 9 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6049	Quantity of (2) 2024 Kit Containers Steel 5 ft x 10 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) 5 ft x 10 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle
6043	Asset located in: Lake Worth, TX 2024 Suihe BX-7 7 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6051	Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6052	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor LHR-PC90 Vibratory Plate	6057	S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMEN FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WI NOT BE ABLE TO ASSIST WITH LOADING
	Compactor (Unused) S/N: Not Available		THESE Asset located in: Corsicana, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6058	Quantity of (3) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available
6054	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Asset located in: Lake Worth, TX	6059	Quantity of Mustang & Wacker Vibratory Plate
6055	Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		6060	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705481 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6056	Asset located in: Corsicana, TX Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	6061	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815555 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		6062	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705482 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		6063	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11743231 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5064	Wacker Neuson Vibroplate BPS2050B Vibratory Plate Compactor (Unused) S/N: 11862553 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6072	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11738234 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6065	Wacker Neuson BPS1550B Vibratory Plate Compactor (Unused) S/N: 11728975 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6073	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738225 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6066	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733549 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6074	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815554 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6067	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733550 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6075	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11662551 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
5068	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738243 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6076	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11737833 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
5069	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738734 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6077	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728974 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
5070	Wacker Neuson Vibroplate BPS2050BW Vibratory Plate Compactor (Unused) S/N: 11666297 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6078	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728979 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
5071	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11743232 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6079	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705489 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6080	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738240 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6088	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11705485 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6081	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738224 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6089	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815552 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6082	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738235 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6090	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11728978 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6083	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666300 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6091	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666299 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6084	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666298 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6092	2015 Wacker Neuson RT Trench Compactor S/N: 24250030 C/W: 2024 US EPA Label, Kohler 3 Cylinder Diesel Engine, / 32 in Drums, Remote Control w/ Cord Usage: 305 Hr Asset located in: Lake Worth, TX
6085	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815550 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6093	Wacker Neuson RT Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA Label, CARB Compliant, Lombardini 6LBDL1. 37SFO:IFI 3 Cylinder 15.5 kW 1028 cc Diesel Engine, 33 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available
6086	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815551		Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	6094	Wacker Neuson Articulating Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA
6087	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815553 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Label, CARB Compliant, Lombardini 6LBD1. 37SFO:IFI 3 Cylinder 15.5 kW 1023 cc Diesel Engine, 32 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6095	Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Open Operator Station, Tier 4, 2013 US EPA Label, CARB Compliant, Kubota D1005- EF06 3 Cylinder 14.5 kW 1.0 L Diesel Engine, 24 in / 33 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	6100	2011 Wacker Neuson RTSC2 Trench Compactor S/N: Not Available C/W: Open Operator Station, 2011 US EPA Label, 3 Cylinder Diesel Engine, 32 in Drums, Articulated Steering Usage: Not Available Asset located in: Lake Worth, TX Wacker Neuson Trench Compactor	
			S/N: 24540169 C/W: Tier 4, 2020 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in Drums, Cordless Remote Control, EQUIPMENT-	
6096	2016 Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available		FROM-SUNSTATE-EQUIPMENT Usage: 512 Hr Asset located in: Lake Worth, TX	
	C/W: Kubota 3 Cylinder Diesel Engine, 24 in / 33 in Drums, Cordless Remote Control, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	6102	Wacker Neuson Trench Compactor S/N: 24498021 C/W: 2019 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in Drums, Remote Control w/ Cord, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 520 Hr Asset located in: Lake Worth, TX	
6097	Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Kubota 3 Cylinder Diesel Engine, 24 in / 33 in Drums, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	6103	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
6009		6104	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
6098	2016 Bomag BMP8500 Trench Compactor S/N: 101720125102 C/W: Tier 4, 2015 US EPA Label, Kubota D1005 3 Cylinder 14.5 kW 1.0 L Diesel Engine, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED	6105	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	6106	Jumping Jack Tamper (Unused) S/N: Not Available	S/N: Not Available C/W: 1 Cylinder Gasoline Engine
6099	Bomag BMP8500 Trench Compactor S/N: 101720134167 C/W: Open Operator Station, Tier 4, 2019 US		Usage: Not Available Asset located in: Lake Worth, TX	
	EPA Label, Kubota D1005-EF06 3 Cylinder 14.3 kW 1.0 L Diesel Engine, 25 in / 35 in Drums, Remote Control w/ Cord, Articulated Steering Usage: Not Available Asset located in: Lake Worth, TX	6107	2024 Landhonor LHR-RM90 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
		6110	Quantity of Concrete Hoppers & Stand S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
6111	2007 Starind 1550 Concrete Chute S/N: Not Available C/W: Fork Pockets; EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	6122	2024 Landhonor LHR-CM300 Portable Concrete Mixer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
6112	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6123	2024 Landhonor LHR-CM400 Portable Concrete Mixer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
6113	Quantity of (3) Pneumatic Chipping Hammers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6124	Quantity of (2) Walk-Behind Saws S/N: 2800003 / 3A9S46M10G1168026 C/W: Water Hose Connection, Manual Blade Raise / Lower, Honda GX390 1 Cylinder	
6114	Quantity of (3) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Gasoline Engine, (1) Husqvarna FS513 Walk- Behind Saw s/n: 2800003 & (1)Tiger MSM Walk-Behind Saw s/n: 3A9S46M10G1168026 (Inoperable) Usage: Not Available Asset located in: Lake Worth, TX	
6115	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6126	2024 Landhonor LHR-Q300 Heavy Duty Concrete Floor Walk-Behind Saw (Unused) S/N: Not Available	
6116	Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available		C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	
	Asset located in: Lake Worth, TX	6129	2019 Core Cut Walk-Behind Saw S/N: 162276	
6117	Toro 23135 Mini Skid Steer Breaker S/N: 313000111 Usage: Not Available Asset located in: Lake Worth, TX		C/W: 30 in Max Blade Diameter, 15 in Max Cutting Depth, Hydraulic Blade Raise / Lower, 2019 US EPA Label, Kubota 4 Cylinder 2.6 L Diesel Engine Usage: 1,607 Hr	
6118	2024 Gar-Bro Concrete Bucket S/N: 427-R DWG 14-11 Usage: Not Available Asset located in: Lake Worth, TX	6130	Asset located in: Lake Worth, TX 2012 Hsqvarna 4000 Walk-Behind Saw S/N: 001309168002	
6119	2014 Toro MB-1600 Walk-Behind Concrete Buggy S/N: 314000161 C/W: Hydrostatic Drive, Honda 1 Cylinder	6131	Cutting Depth, Manual Blade R Kohler 20 hp 624 cc Gasoline E Usage: Not Available	C/W: 13 in Max Blade Diameter, 6.5 in Max Cutting Depth, Manual Blade Raise / Lower, Kohler 20 hp 624 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX		Merit 600.62DR4 Walk-Behind Saw S/N: 10002020 C/W: 4 Cylinder Diesel Engine, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP-	
6120	Bad Boy Electric Utility Vehicle S/N: BBE514B3785006557 C/W: Canopy, 2 Passenger, Winch, Brush Guard		COMPANY Usage: 780 Hr Asset located in : Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	6133	Quantity of (3) 2018 Multiquip B46H11H Power Trowel	
6121	Mortar and Grout Mixer S/N: Not Available C/W: 2013 US EPA Label, Honda GX240 Gasoline Engine, S/A Trailer, Ball Hitch, FOUIDMENT-FROM-SUNSTATE-FOUIDMENT		S/N: MG0112140/MF0111393/MG0112160 C/W: Honda Gas Engine, (2) 42 In, (1) 36 In Usage: Not Available Asset located in: Lake Worth, TX	
		6134	Wacker Electric Concrete Vibrator S/N: 1782595 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6136	2013 Edco 2EC-NG-1.5 Electric Concrete Grinder S/N: 130910129 C/W: 22 in Grinding Width, 2 Grinding Discs, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available	6145	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6146	2024 DG2642 42 ft x 26 ft All Vertical Metal
6137	2010 Whiteman WRS-5200 Concrete Screed S/N: WG1800464 C/W: 7 ft Screed, 41 ft Boom Length, 2009 US EPA Label, Daihatsu 3 Cylinder Diesel Engine Usage: 24 Hr Asset located in: Lake Worth, TX		Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX
	·	6147	2024 DG2642 42 ft x 26 ft All Vertical Metal
6138	Quantity of (3) 16 in Sono-Tube Concrete Forms S/N: Not Available C/W: 16 in Wide, (1) 7 ft 6 in, (1) 8 ft, (1) 10 ft Usage: 5 Hr	014/	Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	6148	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	6140	· · · · · · · · · · · · · · · · · · ·
6139	8 ft Man Guard S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6149	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available
6140	8 ft Man Guard		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	6150	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused)
6141	NTS 52-88 in Trench Shield S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6142	2024 DG2642 42 ft x 26 ft All Vertical Metal		Asset located in: Lake Worth, TX
	Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	6151	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6143	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused)
6144	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

		1	
Lot #	Details	Lot #	Details
6153	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused)	6159	2024 Agriquip DG2322 Double Garage Metal Shed (Unused)
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6154	2024 Agriquip CP2030 30 ft x 20 ft Steel	6160	2024 Agriquip DG2322 Double Garage Metal
0104	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	0100	Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6155	2024 Agriquip CP2030 30 ft x 20 ft Steel	6161	2024 Agriquip DG2322 Double Garage Metal
0.00	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6156	2024 Agriquip CP2030 30 ft x 20 ft Steel	6162	2024 Agriquip DG2322 Double Garage Metal
	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6157	2024 Agriquip DG2322 Double Garage Metal	6163	2024 Agriquip CP2020 20 ft x 20 ft Steel
	Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	0100	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6158	2024 Agriquip DG2322 Double Garage Metal	6164	2024 Agriquip CP2020 20 ft x 20 ft Steel
	Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	 Details
6165	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6172	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6166	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6173	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6167	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6174	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6168	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6175	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6169	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6176	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6170	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6177	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6171	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6178	2024 SUNTOP S1220 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6184	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6185	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)
6179	2024 SUNTOP S1220 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 6186 2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 6187 2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6180	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available		THE ACTUAL PRODUCT Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6181	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6188	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6182	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6189	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6183	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
		6190	KJ K1220 12 Ft x 20 Ft Single Garage Metal Shed S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6191	2024 Landhonor LHR-CP1119 11 ft x 19 ft All-Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Landhonor LHR-CP1119 11 ft x 19 ft All-Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available	6201	Cummins 200DGFC-5199 200 kW Skid-Mounted Stand-By Generator Set S/N: D050767149 C/W: US EPA Label, Cummins 6CTAA8.3G3 6 Cylinder 8.3 L Diesel Engine, 250 kVA/200 kW Rated 3 Phase Output, 134 kVA,/134 kW, Rated Single Phase Output, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, E-Stops Usage: 136,004 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6193	2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6206	2016 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 7353339 C/W: Isuzu BR-4JJ1X 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated
6194	2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 12,507 Hr Notes:
6195	2024 Landhonor PLD-MS0608 6 ft x 8 ft	6208	Asset located in: Lake Worth, TX
	Galvanized Metal Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available Asset located in: Lake Worth, TX		2005 Katolight 50 kW Mobile Stand-By Generator Set S/N: 5FTGE102051024328 C/W: 2004 US EPA Label, John Deere 5030TF270C 5 Cylinder 60 kW 3.0 L Diesel
6196	2024 Landhonor PLD-MS0608 6 ft x 8 ft Galvanized Metal Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available		Engine, 50 kVA,/50 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 20,410 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6209	Allmand MP45-8E1 45 kVA Mobile Generator
6197	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	6210	Set S/N: 1338E10446 C/W: 2018 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 120 V Rated Voltage, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: 2,301 Hr Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2019 Magnum Pro MMG45IF4 38 kW Mobile Generator Set S/N: 3004557276
6100	Asset located in: Lake Worth, TX 2024 Landboror PLD-MS0604P 6 ft v 4 ft		C/W: 2019 US EPA Label, Isuzu BQ4IE2X 19 kW
6198	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Galvanized Metal Pent Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available Asset located in: Lake Worth, TX		2.2 L Diesel Engine, 33 kVA/ Rated 3 Phase Output, 480 V / 208 V Rated Voltage, 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes, EQUIPMENT FROM UNITED RENTALS Usage: 13,399 Hr
6199	Quantity of (2) 4 Ft x 6 Ft Metal Shed S/N: Not Available C/W: two boxes Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6212	2013 Wacker Neuson G50 38 kW Mobile Generator Set S/N: 4TCSU1851DH189075 C/W: 2013 US EPA Label, John Deere 4045Tf290B 4 Cylinder 4.5 L Diesel Engine, 48 kVA/38 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Lunette Ring Usage: Not Available	6218	Allmand MP25 25 kVA Skid-Mounted Generator Set S/N: 1238E12050 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 10,981 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6219	Allmand MP25 25 kVA Skid-Mounted Generator Set
6213	2014 Multiquip DCA-45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1222EL014135 C/W: 2014 US EPA Label, Isuzu 4LE2X 4 Cylinder 56 kW 2.1 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V &	6220	S/N: 1238E12221 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 11,249 Hr Asset located in: Lake Worth, TX
	120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,121 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; SUNSTATE EQUIPMENT CO. RENTAL PEOPLE YOU CAN DEPEND ON Asset located in: Lake Worth, TX		Airman SDG25S 25 kVA Skid-Mounted Generator Set S/N: 1238E13551 C/W: 2022 US EPA Label, Isuzu 4 Cylinder 30 kW Diesel Engine, 25 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 13,453 Hr
6214	2012 Multiquip DCA-45SSIU4 36 kW Mobile		Asset located in: Lake Worth, TX
	Generator Set S/N: 4GNBG1221CB030860 C/W: Isuzu 4JJ1T 4 Cylinder 2.99 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 24,512 Hr Asset located in: Lake Worth, TX	6221	2017 Multiquip DCA-25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0918HB044057 C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 768 Hr
6215	Cat Mobile Generator Set		Asset located in: Lake Worth, TX
	S/N: 1JG110206N1606402 C/W: Cat 4 Cylinder Diesel Engine, T/A Trailer, Ball Hitch, Electric Brakes Usage: 1,300 Hr Asset located in : Lake Worth, TX	6222	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0910GB043032 C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 37 kW 2.1 L Diesel Engine, 25 kVA/20
6217	Allmand MP25 25 kVA Skid-Mounted Generator Set S/N: 1238E12204 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 9,942 Hr Asset located in: Lake Worth, TX		kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 7,983 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6223	Generator Set S/N: 7152111 C/W: 2015 US EPA Label, Isuzu 4LE2T 4	6234	1997 Kohler 40RZ Electric Transfer Switch S/N: 384987 Usage: Not Available Asset located in : Lake Worth, TX
	Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14 kVA,/14 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 2,725 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	6235	2018 Allmand 7 kW Light Tower S/N: 5AEA1AC17JH000125 C/W: Tier 4, 2015 US EPA Label, Kubota d1105 3 Cylinder 12 kW 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,070 Hr Asset located in: Lake Worth, TX
6224	<u>`</u>	6236	2018 Allmand 7 kW Light Tower S/N: 5AEA1AC19JH000334 C/W: Tier 4, 2017 US EPA Label, Kubota d1005 3 Cylinder 10 kW 1 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,493 Hr Asset located in: Lake Worth, TX
	Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer Usage: 1,822 Hr Asset located in: Lake Worth, TX	6237	2018 Allmand NLV-P Light Tower S/N: 5AEA1DA16KH003245 C/W: Perkins 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball
6225	225 Multiquip DCA45SSIU4F 45 kW Mobile Generator Set S/N: 7252100 C/W: US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, T/A Trailer, Lunette Ring, Surge Brakes Usage: 10,993 Hr		Hitch Usage: 3,502 Hr Asset located in : Lake Worth, TX
		6238	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07-001037 C/W: Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D1005-BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Balloon Diffuser, S/A Trailer, Ball Hitch Usage: 4,887 Hr
	Asset located in: Lake Worth, TX		Asset located in: Midland, TX
6226	2016 Atlas Copco 20 kW Mobile Generator Set S/N: 4500G1111GR121222 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 1,895 Hr	6239	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07000969 C/W: 2015 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: 4,827 Hr Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	6240	2016 Allmand 8KWNLP 1250 W Light Tower
6228	2006 MMD SDG25S 20 kVA Mobile Generator Set S/N: 5UABU09196V000009 C/W: 2006 US EPA Label, Isuzu 4LE1 4 Cylinder 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 5,460 Hr Asset located in: Lake Worth, TX		S/N: 07-000162 C/W: Cat c1.1 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 2,815 Hr Asset located in : Lake Worth, TX
		6241	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA4LU497838 C/W: Tier 4, 2019 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 300 Hr Asset located in: Lake Worth, TX
6233	Generac Guardian 24 kW Stand-By Generator Set S/N: Not Available C/W: Natural Gas Engine Usage: Not Available Asset located in: Lake Worth, TX	6242	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA2LU497952 C/W: Tier 4, 2019 US EPA Label, Kubota D1005-BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 294 Hr Asset located in: Lake Worth, TX

S.N.: SXFLV0419M003593 C.W.: 2023 US EPA Label, CARB Compilant, Kohler 19 kW 1.0 L Diesel Engine, 2 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1 Hr Asset located in: Humble, TX 6244 2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416-M003596 C.W.: 2023 US EPA Label, CARB Compilant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 1 hr Asset located in: Humble, TX 6245 2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0419M003595 C.W.: 2023 US EPA Label, CARB Compilant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S./A Trailer, Ball Hitch Usage: 8 Hr Asset located in: Humble, TX 6246 2023 Wacker Neuson & kW Light Tower S/N: 5XFLV0419M003595 C.W.: 2023 US EPA Label, CARB Compilant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S./A Trailer, Ball Hitch Usage: 8 Hr Asset located in: Humble, TX 6246 2023 Wacker Neuson & kW Light Tower S/N: 5XFLV0419M00389 C.W.: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S./A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Lake Worth, TX 6247 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0413JM03162 C.W.: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S./A Trailer, Ball Hitch Usage: 3,74 Frailer, Ball Hitch Usage: 3,74 Frailer, Ball Hitch Usage: 3,74 Frailer, Ball Hitch Usage: 3,75 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C.W.: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S./A Trailer, Ball Hitch Usage: 3,75 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6259 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003247 C.W.: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S./A Trailer, Ball Hitch Usage: 3,910 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFIC	Lot #	Details	Lot #	Details
 Asset located in: Lake Worth, TX Bage: 1 Hr Asset located in: Humble, TX CW: 2018 US EPA Label, Mitsubishi L3E: CW: 2018 US EPA Label, Witsubishi L3E: CW: 2018 US EPA Labe	6243	S/N: 5XFLV0410PM003593 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 2 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1 Hr	6250	C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,346 Hr Notes : ADDITIONAL INFORMATION
C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, S /A Trailer, Ball Hitch Usage: 1 Hr Asset located in: Humble, TX 6245 2023 Wacker Neuson LTV6 6 kW Light Tower S/N: SXFLV0414PM003595 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8 Hr Asset located in: Humble, TX 6246 2023 Wacker Neuson 6 kW Light Tower S/N: SXFLV041PM0003899 C/W: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX 6247 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: SXFLV0417/M03162 C/W: 2018 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: SXFLV0415/JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: SXFLV0415/JM003256 C/W: 2018 US EPA Label, Missubishi L3E: Cylinder 10 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: SXFLV0416-JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6250 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: SXFLV0416-JM003847 C/W: Cylinder 10 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake	6244	<u> </u>		
S/N: 5XFLV0414PM003595 C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX CVW: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX CVW: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX CVW: 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0417JM03162 C/W: 2018 Wacker Neuson LTV6 6 kW Light Tower Receptacles, S/A Trailer, Ball Hitch Usage: 34.18 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6256 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6258 2018 Magnum MLT6SK Light Tower S/N: 5XFLV0416JM003847 C/W: Z018 US EPA Label, Mitisubishi L3E: Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Tra		C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, S /A Trailer, Ball Hitch Usage: 1 Hr Asset located in : Humble, TX	6251	C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch
C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8 Hr Asset located in: Humble, TX 6246 2023 Wacker Neuson 6 kW Light Tower S/N: 5XFLV0416PM000889 C/W: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX 6247 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0417/JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415,JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415,JM003256 C/W: 2018 US EPA Label, Mistusibini L3E: Cylinder 10 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6256 2018 Magnum MLT6SK Light Tower S/N: 5XFLV0415,JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6256 2018 Magnum MLT6SK Light Tower S/N: 5XFLV0415,JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,74 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV66 6 kW Light Tower S/N: 5XFLV0416,JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9,720 Hr Notes: ADDITIONAL	6245	<u> </u>		Asset located in: Lake Worth, TX
S/N: SXFLV0416PM000889 C/W: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX 6247 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0417JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3A18 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3A574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3A574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Fower Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6250 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6251 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6252 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6253 2018 Wacker Neuson LTV6 K 6 kW Light Tower S/N: 3003103485		C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8 Hr	6252	S/N: 7FSBL1013JB992752 C/W: US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch
Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX 6247 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 57kLV0417JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 57kLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 57kLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,374 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 57kLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,317 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6250 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 57kLV0416JM003847 C/W: Kohler 3 Cylinder 10 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,2017 US EPA Label, Mitsubishi L2E: Cylinder 10 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 4,2017 US EPA Label, Mitsubishi L2E: Cylinder 10 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 4,2017 US EPA Label, Mitsubishi L2E: Cylinder 8 kW 0. L Diesel Engine, 4 Lamps, Liphting, S/A Trailer, Ball Hitch Usage: 4,2017 US EPA Label, Mitsubishi L2E: Cylinder 8 kW 0. L Diesel Engine, 4 Lamps, Liphting, S/A Trailer, Ball Hitch Usage: 4,2017 US EPA Label, Mitsubishi L2E: Cylinder 8 kW 0. L Diesel Engine, 4 Lamps Liphting, S/A Trailer, Ball Hitch Usage: 4,2017 US EPA Label, Mit	6246	S/N: 5XFLV0416PM000889		AVAILABLE IN OFFICE - MSO
2018 Wacker Neuson LTV6 6 kW Light Tower S/N: SXFLV0417JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6256 2018 Magnum Pro MLT6SM 6 kW Light T S/N: 7FSBL1010JB586914 C/W: 2018 US EPA Label, Mitsubishi L3E: Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,674 Trailer, Ball Hitch Usage: Motavailable Asset located in: Lake Worth, TX 6258 2018 Magnum Pro MLT6SM 6 kW Light T Asset located in: Lake Worth, TX 6256 2018 Magnum MLT6SK Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch, EQUIPMEN FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6K 6 kW Light Tower S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Mitsubishi L2E: Cylinder 8 kW .6 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6258 2022 Generac MLT6S 2.5 kW Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E: Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch Usage: Motavailable Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6259 2018 Wacker Neuson LTV6K 6 kW Light Tower S/N: SYFLV0416JM003847 C/W: Kobler 3 Cylinder 10 k		Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr	6253	2018 Magnum MLT6SMD 6 kW Light Tower S/N: 7FSBL1010JB983099 C/W: 2018 US EPA Label, Mitsubishi L3E 3
Usage: 3,418 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Kubota D BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6258 2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E: Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX	6247	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0417JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		LED Lighting, S/A Trailer, Ball Hitch Usage: Not Available Notes : ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
6248 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6K 6 kW Light T S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Kubota D BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6258 2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E: Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch			6254	
kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6K 6 kW Light Tower S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Kubota D BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6258 2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch	6248	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256	\dashv	Usage: 8,910 Hr
Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6K 6 kW Light T S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Kubota D BG-FF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6258 2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch			6256	<u> </u>
Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6249 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 6258 Lamps, S/A Trailer, Ball Hitch, EQÜIPMEN FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX 6257 2018 Wacker Neuson LTV6K 6 kW Light T S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Kubota D BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6258 2022 Generac MLT6S 2.5 kVA Light Towe S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch		Receptacles, S/A Trailer, Ball Hitch	6256	S/N: 3003103485
 2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2018 Wacker Neuson LTV6K 6 kW Light T S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Kubota D BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch 				Lamps, S/A Trailer, Ball Hitch, EQUIPMENT-
S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 6258 C/W: Tier 4, 2017 US EPA Label, Kubota D BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr Asset located in: Lake Worth, TX 6258 C/W: 2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch		<u> </u>		•
C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX **Set located in: Lake Worth, TX**	6249	<u> </u>	6257	
Asset located in: Lake Worth, TX 6258 2022 Generac MLT6S 2.5 kVA Light Towe S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch		C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes : ADDITIONAL INFORMATION	023/	S/N: WNCLTV02CPUM04886 C/W: Tier 4, 2017 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,720 Hr
S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps Lighting, S/A Trailer, Ball Hitch		Asset located in: Lake Worth, TX	6258	<u> </u>
Asset located in: Lake Worth, TX				S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,788 Hr

Lot #	Details	Lot #	Details
6259	2017 Generac MLT6SMD Light Tower S/N: 3001517568 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 803 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6266	2016 Terex RL4 6 kW Light Tower S/N: RL416J-1024 C/W: 2015 US EPA Label, Kohler FKHXL1.3 3 Cylinder 8 kW 1.3 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8,753 Mi Notes: LOCATED-IN-HOUSTON-TX; EQUIPMENT FROM SUNBELT RENTALS; Asset located in: Humble, TX
6261	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1016HB880618 C/W: US EPA Label, Mitsubishi 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,312 Hr	6267	2011 Magnum MLT3060M Light Tower S/N: 5AJLS1614BB006243 C/W: 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,275 Hr Asset located in: Lake Worth, TX
6262	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2017 Generac MLT6SMD Light Tower S/N: 7FSBL1013HB568871 C/W: 2016 US EPA Label, Mitsubishi L3E 3	6268	2014 Allmand PAL1250W2 Light Tower S/N: 0202PAL14 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 3,886 Hr Notes : ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in : Lake Worth, TX	6269	2014 Allmand PAL1250W2 Light Tower S/N: 0203PAL14 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
6263	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1011HB880896 C/W: 2017 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,613 Hr	6270	2012 Allmand Light Tower S/N: 0229PAL12 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
6264	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2017 Generac MLT6SMD Light Tower S/N: 7FSBL1011HB880607 C/W: 2017 US EPA Label, Mitsubishi L3E-	6271	2012 Allmand Light Tower S/N: 0224PAL12 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
6265	W464MLD 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch, Electric Brakes Usage: 6,831 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; 3001880607 Asset located in: Lake Worth, TX	6273	2018 Doosan HP1600WCU-T4F 1600 cfm Mobile Air Compressor S/N: 4FVCCBPB8JU483256 C/W: 150 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, T/A Trailer, Lunette Ring, Electric Brakes Usage: 1,806 Hr
6265	2019 Terex RL4 6 kW Light Tower S/N: 4ZJSA1015J1009757 C/W: 2018 US EPA Label, Deutz 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: Not Available Asset located in: Midland, TX	6275	Asset located in: Lake Worth, TX 2011 Doosan HP1600 Mobile Air Compressor S/N: 419233UJUB83 C/W: 200 psi Working Pressure, 2019 US EPA Label, Cummins QSX15 6 Cylinder 344 hp 15 L Diesel Engine, T/A Trailer, Lunette Ring Usage: 9,344 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6276	2012 Sullair 900H Mobile Air Compressor S/N: 201202150037 C/W: Air Dryer, 250 psi Working Pressure, Cat C9 6 Cylinder Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: CERTIFICATE OF ORIGIN AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX	6284	2017 Doosan P425/HP375WCU-T4F Mobile Air Compressor S/N: Not Available C/W: 2017 US EPA Label, Cummins 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes Usage: 3,099 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION
6277	2015 Doosan XP825WCU Mobile Air Compressor		AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX
	S/N: 4FVCBBFB3FU46608 C/W: 250 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, T/A Trailer, Lunette Ring, Electric Brakes Usage: 3,198 Hr Asset located in: Lake Worth, TX	6285	2016 Atlas Copco XATS400PEJD7 Mobile Air Compressor S/N: 4500B1315GR076376 C/W: 175 psi Working Pressure, John Deere 4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,560 Hr
6278	2012 Atlas Copco XAS750JD7T3 Mobile Air		Asset located in: Lake Worth, TX
	Compressor S/N: 4500B1611CR080883 C/W: 261 psi Working Pressure, John Deere 6 Cylinder 6.8 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 468 Hr Asset located in: Lake Worth, TX	6286	2013 Atlas Copco XATS400JD7 Mobile Air Compressor S/N: 4500B1310DR074160 C/W: 175 psi Working Pressure, John Deere 4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,323 Hr Asset located in: Lake Worth, TX
6280	Airman PDS400S Mobile Air Compressor	6007	·
	S/N: C16B10076 C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 6,172 Hr Asset located in : Lake Worth, TX	6287	2011 Atlas Copco XAVS375 Mobile Air Compressor S/N: 4500B1312BR071984 C/W: 2011 US EPA Label, John Deere 4045HF285 4 Cylinder 4.5 L Diesel Engine Usage: 889 Hr
6281	Airman PDS400S Mobile Air Compressor S/N: C16B10484 C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 3,252 Hr Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lahoma, OK
6282	2018 Doosan HP375WCU-T4F Mobile Air	6291	2021 Atlas Copco XAS188 KD8 Mobile Air
	Compressor S/N: Not Available C/W: 250 psi Working Pressure, 2018 US EPA Label, Cummins QSB4.5 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch, Electric Brakes Usage: 4,337 Hr Asset located in: Lake Worth, TX		Compressor S/N: 4500A1017MR200473 C/W: 125 psi Working Pressure, Kubota D1803-T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX
6283	2017 Doosan P425/HP375 Mobile Air Compressor S/N: Not Available C/W: 2017 US EPA Label, Cummins 6 Cylinder 130 hp 4.8 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes Usage: 1,709 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6292	2021 Atlas Copco XAS188 KD8 Mobile Air Compressor S/N: 4500A1012MR200476 C/W: 125 psi Working Pressure, Kubota D1803- T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6293	2021 Kaeser M55 PE 185 cfm Mobile Air Compressor S/N: WKA0N1000M8357329 C/W: 125 psi Working Pressure, Kubota D1803- CR-EF01 3 Cylinder 1.8 L Diesel Engine, S/A Trailer Usage: Not Available Asset located in: Lake Worth, TX	6301	2019 Allmand Maxi-Air 185 Mobile Air Compressor S/N: 5AEA1KF10KH000628 C/W: 200 psi Working Pressure, 2018 US EPA Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 9,961 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION
0294	Compressor S/N: WKA0N1000M8357356		AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX
	C/W: 125 psi Working Pressure, 2019 US EPA Label, Kubota D1803-CR-T-EF01 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,054 Hr Asset located in : Lake Worth, TX	6302	2019 Allmand MA185-5E1 185 cfm Mobile Air Compressor S/N: 5AEA1KF15KH000737 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L Dieses 6055 Lb.
6295	2020 Kaesar M58 210 cfm Skid-Mounted Air		Usage: 6,855 Hr Asset located in : Lake Worth, TX
	Compressor S/N: 10627593833 C/W: 100 psi Working Pressure, Kubota V2403- CR-EF08 4 Cylinder 36 kW 2.4 L Diesel Engine Usage: 3,987 Hr Asset located in: Lake Worth, TX	6304	2020 Allmand MA185-6E1 185 cfm Mobile Air Compressor S/N: 5AEA1KF16LH000831 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L
6296	2020 Kaeser M58 210 cfm Skid-Mounted Air Compressor S/N: 10607586681 C/W: 100 psi Working Pressure, 2018 US EPA Label, Kubota V2403-CR-EF08 3 Cylinder 36 kW 2.4 L Diesel Engine		Diesel Engine, S/A Trailer, Ball Hitch Usage: 8,456 Hr Notes : NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; CERTIFICATE OF ORIGIN AVAILABLE IN OFFICE; Asset located in : Lake Worth, TX
	Usage: 4,335 Hr Asset located in: Lake Worth, TX		2018 Sullair 185DPQ-KU-T3 185 cfm Mobile Air Compressor
6297	2015 Atlas Copco XAS185KD7PE 185 cfm Mobile Air Compressor S/N: 4500A1013FR049103 C/W: 123 psi Working Pressure, 2014 US EPA Label, Kubota V2403-CR-EF02 3 Cylinder 36.8 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 976 Hr		C/W: 2 Label, I Diesel EQUIPI Usage:
	Asset located in: Lake Worth, TX	6305	2018 Doosan P185WDOU-T4F 185 cfm Skid-
6299	2021 Airman PDS185S Mobile Air Compressor S/N: 7H6BY11A6MA002935 C/W: 200 psi Working Pressure, 2021 US EPA Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 185 Hr		Mounted Air Compressor S/N: 486622UFAGF89 C/W: 185 psi Working Pressure, 2018 US EPA Label, CARB Compliant, Doosan 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Midland, TX
	Notes : NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY	6306	2017 Doosan C185WDZ Mobile Air Compresso
6300	Asset located in: Lake Worth, TX Airman PDS185S 185 cfm Skid-Mounted Air Compressor S/N: B4-6811098 C/W: 150 psi Working Pressure, 2003 US EPA Label, Isuzu NE2 4 Cylinder 2.17 L Diesel Engine		S/N: 4FVCABAA8HU479739 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,131 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	Usage: 1,840 Hr Asset located in : Lake Worth, TX		Asset located III. Lake Worth, 1A

Lot #	Details	Lot #	Details
	2017 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 479354UAABG07 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,381 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE -MSO	6313	2013 Sullivan Palatek 185 cfm Mobile Air Compressor S/N: 101343 C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF231A 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,018 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6314	2018 Sullair 185DPQ Mobile Air Compressor
6308	·		S/N: 201802270074 C/W: 185 psi Working Pressure, 2017 US EPA Label, Kubota 4 Cylinder 36 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,685 Hr Asset located in : Lake Worth, TX
	Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,825 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6315	2011 Sullair 185DPQJD Skid-Mounted Air Compressor S/N: 201107210060 C/W: 185 psi Working Pressure, 2011 US EPA Label, John Deere 4024TF 4 Cylinder 37 kW 2.4
6309	2012 Doosan C185WJD-T4I Mobile Air Compressor S/N: 4314506UIVE43		L Diesel Engine Usage: 2,365 Hr Asset located in : Lake Worth, TX
	C/W: 200 psi Working Pressure, 2011 US EPA Label, CARB Compliant, John Deere 4024TF281C 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,197 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6316	2004 Sullair 250DPQ-JDD Mobile Air Compressor S/N: 2004100085 C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine Usage: 3,195 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
6310	2010 Doosan C185 185 cfm Mobile Air Compressor S/N: Not Available C/W: 2010 US EPA Label, Kubota V2403 36.5		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,140 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	EASE SEE 6317	2017 Atlas Copco XAS185KD Mobile Air Compressor S/N: 4500A1014HR055415 C/W: 185 psi Working Pressure, 2017 US EPA
6311	Ingersoll Rand 185 Mobile Air Compressor S/N: 151780U85957 C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine Usage: 3,697 Hr		Label, Kubota 3 Cylinder 1.8 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 1,075 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	6318	2017 Atlas Copco XAS185KD7PET4F Mobile Air Compressor S/N: 4500A1012HR055090 C/W: Kubota 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring
6312	Asset located in: McAlester, OK 2013 Sullivan D185PJDSB Mobile Air Compressor S/N: 31811 C/W: 100 psi Working Pressure, John Deere 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,438 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: 947 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BIL OF SALE ONLY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6319	2017 Atlas Copco XAS185KD7PET4F Mobile Air Compressor S/N: 4500A1012HR055414 C/W: 2017 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available	6325B	Genaer Skid-Mounted Air Compressor S/N: 1611 C/W: 15 hp Motor, 2014 US EPA Label, Kubota V3800 4 Cylinder 3.8 L Diesel Engine Usage: Not Available Asset located in: Midland, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX	6325C	Smith Mobile Air Compressor S/N: 100510361 C/W: 125 psi Working Pressure, Ford 4
6320	2013 Ingersoll Rand 185 cfm Mobile Air Compressor S/N: 4FVCABAAXDU454478		Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF281C 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6327	2006 Miller Bobcat 250 Multi-Process Engine Driven Welder S/N: LG076841 C/W: Kohler Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 213 Hr Asset located in: Lake Worth, TX
6321	2011 Atlas Copco XAS185JDRSC Mobile Air Compressor S/N: 4500A1019BR038617 C/W: 2011 US EPA Label, John Deere 4024TF281A 4 Cylinder 2.4 L Diesel Engine Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	6328	2013 Lincoln Vantage 300 400 A Skid-Mounted Multi-Process Engine Driven Welder S/N: U1130305650 C/W: Tier 4, 2012 US EPA Label, CARB Compliant, Kohler V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 4,763 Hr Asset located in: Lake Worth, TX
6322	2007 Airman PDS185S 185 cfm Mobile Air Compressor S/N: B46B44752 C/W: 150 psi Working Pressure, 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 1,309 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	6329	2013 Lincoln Vantage 300 400 A Skid-Mounted Multi-Process Engine Driven Welder S/N: U1130301883 C/W: 2012 US EPA Label, CARB Compliant, Kubota V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 5,080 Hr Asset located in: Lake Worth, TX
6324	2021 Rotair D400T4F 150 cfm Mobile Air Compressor S/N: 16MBB1319MD081696 C/W: 150 psi Working Pressure, 2021 US EPA Label, Cummins QSF3.8 4 Cylinder 3.8 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch Usage: 1,709 Hr Asset located in: Lake Worth, TX	6330	2020 Miller Bobcat 260 Multi-Process Engine Driven Welder S/N: NA300101R C/W: Kohler Engine, Welding Leads, 120 V / 240 V Rated Voltage, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 496 Hr Notes: . Asset located in: Lake Worth, TX
6325A		6332	2015 Miller Trailblazer 251 Multi-Process Engine Driven Welder S/N: MF500520R C/W: 2015 US EPA Label, Kohler CH730 725 cc Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 2,736 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6333	2016 Miller Bobcat 250 Mobile Multi-Process Engine Driven Welder S/N: MG310150R C/W: 2016 US EPA Label, Kohler 3 Cylinder 725 cc Engine, 240 V / 208 V Rated Voltage, 120 V Rated Voltage Usage: 619 Hr Asset located in: Lake Worth, TX	6341	Gorman-Rupp Mobile Centrifugal Pump S/N: Not Available C/W: US EPA Label, John Deere 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX Slanzi Skid-Mounted Water Pump	
6334	2014 Lincoln Vantage 500 Multi-Process Engine Driven Welder S/N: U11400 C/W: Diesel Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 1,576 Hr Asset located in: Lake Worth, TX 2005 Miller Bobcat 250 Skid-Mounted Multi-	6343	S/N: 249606 C/W: 4 in Intake, 3 in Discharge, Centrifugal Water Pump, Slanzi 4 Cylinder Diesel Engine Usage: 183 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
6337	Process Engine Driven Welder S/N: LF041958 C/W: 2005 US EPA Label, Kohler CH20S 624 cc Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 1,686 Hr Asset located in: Lake Worth, TX Lincoln Vantage 520SD 520 A Mobile Stick		Asset located in: Lahoma, OK 2022 Stealth Trailer-Mounted Water Pump S/N: 1R9RBUAA7NS723142 C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, 2021 US EPA Label, CARB Compliant, Deutz TD2.9L4 4 Cylinder 55.4 kW 2.92 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,064 Hr	
	Engine Driven Welder S/N: Not Available C/W: 2015 US EPA Label, Deutz d2.9l 4 Cylinder 40 hp 2.9 L Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX	6344	Asset located in: Midland, TX 6 In Water Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Water Pump	
6338	Quantity of (2) Miller Millermatic 255 Wire Electric Welder S/N: NA168518N/NB358903N C/W: Single Phase, 200 V/ 240 V Input, Welding Leads, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		C/W: 3 in Intake, 3 in Discharge, W EQUIPMENT-FROM-WATKINS-CON Usage: Not Available Notes: ITEMS AT OFFSITE LOCAT BE PICKED UP WITHIN 14 DAYS O AUCTION (JANUARY 3RD) OR WILL SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADO	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
6339	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder S/N: Not Available C/W: 2013 US EPA Label, Kubota v1505 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage Usage: 4,301 Hr Asset located in: Lake Worth, TX	6346	Asset located in: Corsicana, TX Quantity of (3) Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	
6340	2012 Gorman-Rupp PA6C60-4045T Trailer- Mounted Water Pump S/N: 1493129N C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring	6247	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of (3) Water Pump	
	Usage: 8,350 Hr Asset located in: Lake Worth, TX	6347	Quantity of (3) Water Pump S/N: Not Available C/W: 3 in Intake, 2 in Discharge Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6348	Quantity of (3) Water Pump S/N: Not Available C/W: 2 in Intake, 3 in Discharge Usage: Not Available Asset located in: Lake Worth, TX	6358	Doosan GC55C-9 11850 lb Pneumatic Tire Forklift S/N: FGB1C256000013 C/W: 2 Stage Mast, 162 in Max Lift Height, 82 in Lowered Mast Height, 59 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 3
6349	Quantity of (3) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: Trash Pump, 1 Cylinder Gasoline Engine		Cylinder LPG Engine Usage: 7,819 Hr Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	6359	2017 Toyota 8FG45U 9300 lb Pneumatic Tire Forklift S/N: 11419
6350	Quantity of (2) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Trash Pump Usage: Not Available Asset located in: Lake Worth, TX		C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 92 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4 Cylinder 3.6 L LPG Engine Usage: 1,152 Hr
6352	Cornell 25WHRPPF86 Electric Skid-Mounted	6360	Asset located in: Lake Worth, TX 1998 Mitsubishi FD35 8000 lb Pneumatic Tire
	Water Pump S/N: 2530458 C/W: 3 in Intake, 2.5 in Discharge, Centrifugal, WEC 25 Hp Electric Motor; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	6360	Forklift S/N: AF19B00320 C/W: 2 Stage Mast, 148 in Max Lift Height, 97 in Lowered Mast Height, 48 in Forks, Side Shift, Mitsubishi 6 Cylinder Diesel Engine Usage: 9,917 Hr
6353	Skid-Mounted Water Pump		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal Trash Pump, 2014 US EPA Label, Honda 270 cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	6361	2001 Hyster H80XM 7700 lb Pneumatic Tire Forklift S/N: K005A04243Y C/W: 2 Stage Mast, 122 in Max Lift Height, 57 in Forks, Fork Positioner, Solid Pneumatic Tires, V6 LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	6361A	2015 Toyota 8FG35U 7300 lb Cushion Tire Forklift S/N: 10863 C/W: 3 Stage Mast, 159.5 in Max Lift Height,
6354	Quantity of Pump & PTO S/N: Not Available C/W: MC L0614SC Triplex pump, Muncie PTO, (2) Tanks, One Pallet Usage: Not Available		106 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 2015 US EPA Label, Toyota 4 Cylinder 63 kW 3.6 L LPG Engine Usage: 1,917 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6362	2007 TCM FD70-9 12980 lb Pneumatic Tire Forklift
6356	Taylor Y-23WOF 23000 lb Dual Front Tires Pneumatic Tire Forklift S/N: S2113943 C/W: 2 Stage Mast, 24 in Lowered Mast Height, 93 in Forks, Solid Pneumatic Tires, Detroit 4 Cylinder Diesel Engine Usage: 6,519 Hr	S/N: A30K00809 C/W: 2 Stage Mast, 157 in Max Lift in Lowered Mast Height, 94 in Fork	S/N: A30K00809 C/W: 2 Stage Mast, 157 in Max Lift Height, 96 in Lowered Mast Height, 94 in Forks, Fork Positioner, 4 Cylinder Diesel Engine Usage: 5,357 Hr
	Asset located in: Lake Worth, TX	6363	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused)
6357	2005 Hyster H155XL2 12700 lb Pneumatic Tire Forklift S/N: G006V03382C C/W: 2 Stage Mast, 212.6 in Max Lift Height, 145 in Lowered Mast Height, 47 in Forks, Side Shift, V6 LPG Engine Usage: 4,200 Hr Asset located in: Lake Worth, TX		S/N: 23L3001161 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 22 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6364	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001163 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX	6370	2004 Tailift FD30 4270 lb Pneumatic Tire Forklift S/N: 318920B C/W: 3 Stage Mast, 196 in Max Lift Height, 85 in Lowered Mast Height, 72 in Forks, Solid Pneumatic Tires, 2005 US EPA Label, Isuzu 4JG2 4 Cylinder 3.1 L Diesel Engine Usage: Not Available
6365	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001164 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1 Hr Asset located in: Lake Worth, TX	6371	Asset located in: Lake Worth, TX Doosan G30P-5 5550 lb Pneumatic Tire Forklift S/N: FGA0C-1330-02057 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, GM Vortec 4 Cylinder Dual Fuel Engine Usage: 6,566 Hr
6366	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001157 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX 2014 Toyota 8FD35U 6500 lb Pneumatic Tire	6372	Asset located in: Lake Worth, TX 2017 Hyundai 30L-7A 5900 lb Pneumatic Tire Forklift S/N: HHKHHF09CH001849 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 86 in Lowered Mast Height, 45 in Forks, Side Shift, 2017 US EPA Label, CARB Compliant, Hyundai E Controls 4 Cylinder 20.6 kW 2.4 L LPG Engine Usage: 4,100 Hr Asset located in: Lake Worth, TX
	Forklift S/N: 8FD35U-10678 C/W: 3 Stage Mast, 187 in Max Lift Height, 72 in Forks, Fork Positioner, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4 Cylinder Diesel Engine Usage: 5,597 Hr Asset located in: Lake Worth, TX	6374	Cat 2PD6000 6000 lb Pneumatic Tire Forklift S/N: AT14E30364 C/W: 2 Stage Mast, 147 in Max Lift Height, 96 in Lowered Mast Height, 53 in Forks, Side Shift, Solid Pneumatic Tires, 2010 US EPA Label, 4 Cylinder 3.3 L Diesel Engine Usage: 18,085 Hr
6367A 6368	2004 Toyota 7FGU32 6500 lb Pneumatic Tire Forklift S/N: 65549 C/W: 3 Stage Mast, Full Free Lift, 171 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Solid Pneumatic Tires, LPG Engine Usage: Not Available Asset located in: Lake Worth, TX 2019 Toyota 8FD35U 7000 lb Pneumatic Tire Forklift	6376	Asset located in: Lake Worth, TX 2015 Toyota 8FGU30 5820 lb Pneumatic Tire Forklift S/N: 65650 C/W: 2 Stage Mast, 159 in Max Lift Height, 102 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 3,750 Hr Asset located in: Lake Worth, TX
6369	S/N: 8FD35U13204 C/W: 3 Stage Mast, 187 in Max Lift Height, 78 in Lowered Mast Height, 48 in Forks, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4 Cylinder 2.9 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX 2005 Toyota 7FGU32 6020 lb Pneumatic Tire Forklift	6377	2006 Toyota 7FGU30 5750 lb Pneumatic Tire Forklift S/N: 69901 C/W: 3 Stage Mast, Full Free Lift, 171 in Max Lift Height, 83 in Lowered Mast Height, 45 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2006 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 68341 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Side Shift, 2006 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 8,373 Hr Asset located in: Lake Worth, TX	6378	2015 Cat DP30N Pneumatic Tire Forklift S/N: AT14G00200 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 11,524 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6379	2017 Cat 2C6000 5750 lb Cushion Tire Forklift S/N: AT83F42214 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 52 in Forks, Side Shift, Tier 2, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6384A	2016 Toyota 8FGU30 5620 lb Pneumatic Tire Forklift S/N: 68413 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.3 L Dual Fuel Engine Usage: 6,167 Hr
6380	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift		Asset located in: Lake Worth, TX
	S/N: 69980 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 4,420 Hr	6385	2000 Toyota 7FGU30 Pneumatic Tire Forklift S/N: 61163 C/W: 3 Stage Mast, 47 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6386	Cat 2PD6000 5500 lb Pneumatic Tire Forklift
6381	81 2017 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift S/N: 8FDU30-62078 C/W: 3 Stage Mast, 187 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires. 2017 US EPA Label.		S/N: AT14E30407 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 58 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 11,707 Hr Asset located in: Lake Worth, TX
		6386A	Doosan D30G 5467 lb Pneumatic Tire Forklift S/N: K360403
			C/W: 3 Stage Mast, Full Free Lift, 185.6 in Max Lift Height, 42 in Forks, Side Shift, Solid
6382	2014 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift		Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available
	S/N: 60256 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 88 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 2,134 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
		6387	2018 Toyota 8FDU25 4800 lb Pneumatic Tire Forklift S/N: 8FDU25-62405 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Toyota Diese
6383	2017 Toyota 8FGU30 5750 lb Pneumatic Tire		Engine Usage: 2,362 Hr
	Forklift S/N: 69985 C/W: 2 Stage Mast, Full Free Lift, 187 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4Y ECS 4 Cylinder 42 kW 2.23 L LPG Engine		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Usage: 3,920 Hr		Asset located in: Fort Smith, AR
6384	Asset located in: Lake Worth, TX 2015 Toyota 8FGU30 5820 lb Cushion Tire Forklift S/N: 65668 C/W: 2 Stage Mast, 159 in Max Lift Height, 100 in Lowered Mast Height, 42 in Forks, 2016 US EPA Label, Toyota 4Y ECS 4 Cylinder 42 hp 2.23 L LPG Engine Usage: 4,257 Hr Asset located in: Lake Worth, TX	-6388	2007 Cat P6000LP 5050 lb Pneumatic Tire Forklift S/N: AT13F10861 C/W: 3 Stage Mast, 186 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Block Forks, Solid Pneumatic Tires, Tier 2, 2007 US EPA Label, Nissan K25 L 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6389	2019 Toyota 8FDU25 5000 lb Pneumatic Tire Forklift S/N: 62836 C/W: Enclosed Cab, 2 Stage Mast, Full Free Lift, 131.5 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2019 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 1,127 Hr Asset located in: Lake Worth, TX	6395	2019 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift S/N: 94056 C/W: 3 Stage Mast, 131 in Max Lift Height, 24 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 11,841 Hr Asset located in: Lake Worth, TX	
6390	2016 Cat GP25N2-LE 5000 lb Pneumatic Tire Forklift S/N: AT35A02417 C/W: 3 Stage Mast, 83 in Lowered Mast Height, 60 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2016 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 4,117 Hr Asset located in: Midland, TX	6396	2015 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift S/N: 8FGU25-67336 C/W: 2 Stage Mast, 131.5 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 10,669 Hr	
6391	2004 Cat P5000 Pneumatic Tire Forklift S/N: AT3500741 C/W: 3 Stage Mast, Full Free Lift, 46 in Forks, Side Shift, Solid Pneumatic Tires, 2004 US EPA Label, Nissan 4NSXB02.5 4 Cylinder 61.5 hp 2.5 L LPG Engine, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2016 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift S/N: 72494 C/W: 2 Stage Mast, Full Free Lift, 131.5 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, CARB Compliant, Toyota 4YECS	
6391A	Hyundai G25SP-3 5000 lb Pneumatic Tire Forklift	6398A 6398A	4 Cylinder 38 kW 2.23 L LPG Engine Usage: Not Available Asset located in : Lake Worth, TX	
	S/N: D201409 C/W: 3 Stage Mast, 186 in Max Lift Height, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, Daewoo G430-LP 4 Cylinder LPG Engine Usage: 9,190 Hr Asset located in: Lake Worth, TX		Forklift (Unused) S/N: 23L3000549 C/W: 3 Stage Mast, 189 in Max Lift Heig in Lowered Mast Height, 47 in Forks, Sid 2023 US EPA Label, CARB Compliant, Hy	· · · · · · · · · · · · · · · · · · ·
6392	2020 Cat Gp25N 4500 lb Pneumatic Tire Forklift		Usage: 2 Hr Asset located in: Lake Worth, TX	
	S/N: AT35A09092 C/W: 3 Stage Mast, 188 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2020 US EPA Label, CARB Compliant, GCT 4 Cylinder 20.6 kW 2.5 L LPG Engine Usage: 1,558 Hr Asset located in: Lake Worth, TX		Heli 4600 lb Pneumatic Tire Forklift S/N: 25025117944 C/W: 3 Stage Mast, 75 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder 3.0 L Dual Fuel Engine Usage: Not Available Asset located in: Lake Worth, TX	
6393	2018 Doosan G25N7 4600 lb Pneumatic Tire Forklift S/N: FGA14-1290-00939 C/W: 2 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Tier 2, 2018 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 2,390 Hr Asset located in: Lake Worth, TX		Tire Forklift S/N: A260155 C/W: 3 Stage Mast, Full Free Lift, Lift Height, 84 in Lowered Mast Forks, Side Shift, Solid Pneumation 2014 US EPA Label, GCT 4 Cylind Fuel Engine, EQUIPMENT-FROMEQUIPMENT	S/N: A260155 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2014 US EPA Label, GCT 4 Cylinder 2.5 L Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-
6393A	2011 Doosan G25P-5 Pneumatic Tire Forklift S/N: FGA0B133001275 C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, 2011 US EPA Label, GM 4 Cylinder 46 kW 2.4 L LPG Engine Usage: 3,885 Hr Asset located in: Lake Worth, TX		Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
6399A	2016 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 78142 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 87 in Lowered Mast Height, 48 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L Dual Fuel Engine Usage: 4,861 Hr	6403	Komatsu FG25 3990 lb Pneumatic Tire Forklift S/N: 144043A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 24 in Lowered Mast Height, 46 in Forks, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 4,607 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6404	Nissan PJ02A25PV 3975 lb Pneumatic Tire
6400	2015 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 67140 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 81 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4YECS 2.2 L Dual Fuel Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:		Forklift S/N: PJ029H3529 C/W: 3 Stage Mast, 188 in Max Lift Height, 86 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 13,012 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	6405	2024 Viper FY25BCS 3900 lb Pneumatic Tire
6401	2019 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 94048 C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2.2 L LPG Engine	6406A 6407	Forklift (Unused) S/N: 222010033 C/W: 3 Stage Mast, 189 in Max Lift Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Mitsubishi 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX
	Usage: 28,396 Mi		2024 Viper FY25C 3900 lb Pneumatic Tire Forklift (Unused)
6401A	Asset located in: Lake Worth, TX 2015 Doosan D253-7 4200 lb Pneumatic Tire Forklift S/N: FDA00193000440 C/W: 2 Stage Mast, 163 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, 4 Cylinder 45 kW 2.4 L Diesel Engine		S/N: 222011086 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Kubota WG2503 4 Cylinder 41 kW 2.5 L LPG Engine Usage: 3 Hr Asset located in: Lake Worth, TX
	Usage: 3,385 Hr Asset located in: Lake Worth, TX		2004 Toyota 7FGU25 4500 lb Pneumatic Tire Forklift
6401B	2016 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 78039 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2017		S/N: 72616 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 24 in Lowered Mast Height, 41 in Forks, Solid Pneumatic Tires, 2004 US EPA Label, 4 Cylinder 2.2 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 1,247 Hr Asset located in : Lake Worth, TX		Heli CPYD25 3900 lb Pneumatic Tire Forklift S/N: 2302574499 C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Most Height, 50 in Forks, Side Shift
6402	1994 Hyster H40XM 4000 lb Pneumatic Tire Forklift S/N: D177G9392R C/W: 3 Stage Mast, 153 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Isuzu 4 Cylinder Diesel Engine Usage: 2,238 Hr Asset located in: Lake Worth, TX		in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
		6407A	1997 Mitsubishi FG30 5300 lb Pneumatic Tire Forklift S/N: AF13D30869 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 83 in Lowered Mast Height, 41 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: 2,369 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6407C	1989 Hyster H30XL 3500 lb Pneumatic Tire Forklift S/N: C001B08966K C/W: 3 Stage Mast, Full Free Lift, 174 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: 5,094 Hr	6414	2013 Toyota 7FGCU45 Cushion Tire Forklift S/N: 72832 C/W: 3 Stage Mast, Full Free Lift, 47 in Forks, Auxiliary Hydraulic Plumbing, LPG Engine Usage: 7,006 Hr Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6414A	2018 Toyota 8FGC35U 7250 lb Cushion Tire
6408	1989 Clark GPS25MB 3800 lb Pneumatic Tire Forklift S/N: GP138MB03476968K0F C/W: 2 Stage Mast, 196 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1,200 Hr Asset located in: Lake Worth, TX		Forklift S/N: 13300 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 48 in Forks, Side Shift, 2018 US EPA Label, Toyota 4 Cylinder 3.6 L LPG Engine Usage: 2,828 Hr Asset located in: Lake Worth, TX
6409A	2015 Doosan D25S-7 3650 lb Pneumatic Tire Forklift S/N: FDA0Q-1930-01126 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 2,689 Hr	6415	2017 Cat 2C6000 5750 lb Cushion Tire Forklift S/N: AT83F42218 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6416	2017 Cat 2C6000 5750 lb Cushion Tire Forklift
6410	2002 Komatsu FG15HC-16 2500 lb Pneumatic Tire Forklift S/N: 652910A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan		S/N: AT83F42219 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 53 in Forks, Side Shift, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	4 Cylinder Gasoline Engine Usage: 9,201 Hr Asset located in : Lake Worth, TX	6416A 	2019 Toyota 8FGCU30 2450 lb Cushion Tire Forklift
6410A	Crown Cushion Tire Forklift S/N: Not Available C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, John Deere 4 Cylinder LPG Engine Usage: 6,624 Hr Asset located in: Lake Worth, TX		S/N: 74094 C/W: 4 Stage Mast, Full Free Lift, 259.5 in Max Lift Height, 79 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Paper Roll Clamp, 2019 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 5,355 Hr Asset located in: Lake Worth, TX
6412	2021 Yale GLC155VX 10000 lb Cushion Tire Forklift S/N: F879V02837V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6419	2015 Toyota 8FGCU30 5820 lb Cushion Tire Forklift S/N: 62544 C/W: 2 Stage Mast, 147 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Side Shift, 2017 US EPA Label, Toyota 37 kW 1.79 L Diesel Engine Usage: 5,361 Hr
6413	2021 Yale GLC155VX 10000 lb Cushion Tire		Asset located in: Lake Worth, TX
	Forklift S/N: F879V02836V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6420	2011 Toyota 8FGCU25 7500 lb Cushion Tire Forklift S/N: 31741 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 36 kW 2.23 L LPG Engine Usage: 2,786 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6421	Toyota 2600 lb Cushion Tire Forklift S/N: 74438 C/W: 3 Stage Mast, 258 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Toyota 4YECS LPG Engine Usage: 5,098 Hr Asset located in: Lake Worth, TX 2021 Mitsubishi FGC25N 5000 lb Cushion Tire	6426	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19413W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Forklift S/N: AF82F50153 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Load Weigh System, 2021 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,245 Hr Asset located in: Humble, TX	6427	Asset located in: Humble, TX 2022 Hyster S50FT 4800 lb Cushion Tire Forklift
			S/N: H187V19411W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine
6423	2021 Mitsubishi FGC25N4 5000 lb Cushion Tire Forklift S/N: AF82F50026	6428	Usage: Not Available Notes: . Asset located in: Humble, TX
	C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 56 in Forks, Load Weigh System, 2022 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,534 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19408W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
6424	2021 Mitsubishi FGC25N 5000 lb Cushion Tire Forklift		THE INSPECTION REPORT Asset located in: Humble, TX
6424B	S/N: AF82F49734 C/W: 2 Stage Mast, Full Free Lift, 80 in Max Lift Height, 58 in Lowered Mast Height, 60 in Forks, Side Shift, Tier 2, 2021 US EPA Label, CARB Compliant, 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 3,757 Hr Asset located in: Lake Worth, TX Komatsu FG25C-11 5000 lb Pneumatic Tire Forklift	6429	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19417W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 463417A C/W: 2 Stage Mast, 128 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, Nissan 4 Cylinder Gasoline Engine Usage: 5,084 Hr Asset located in: Lake Worth, TX	6430	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19410W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine
6425	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19416W C/W: 3 Stage Mast, 189 in Max Lift Height, 82		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19409W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6432	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19415W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6438	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19419W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: . Asset located in: Humble, TX
6433	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19412W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6439	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19401W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: . Asset located in: Humble, TX
6434	2020 Yale GLC050VX 4750 lb Cushion Tire Forklift S/N: C910V14422U C/W: 3 Stage Mast, 189 in Max Lift Height, 58 in Lowered Mast Height, 56 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6440	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19414W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
6435	2020 Yale GC050VX 4750 lb Cushion Tire Forklift S/N: C910V14424U C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 58 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6441	THE INSPECTION REPORT Asset located in: Humble, TX 2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19400W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in
6436	2006 Yale GLC050VXNVSE083 4700 lb Cushion Tire Forklift S/N: A910V06226D C/W: 3 Stage Mast, 189 in Max Lift Height, 80 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6442	Forks, Šide Shift, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2022 Hyster S50FT 4650 lb Cushion Tire
6437	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19418W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Forklift S/N: H187V19406W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6443	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19407W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: Asset located in: Humble, TX	6446B	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 72871 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.3 L LPG Engine Usage: 1,944 Hr Asset located in: Lake Worth, TX 2015 Toyota 8FGCU25 4500 lb Cushion Tire
6443A	2017 Toyota 8FGCU25 4600 lb Cushion Tire Forklift S/N: 85179 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 87 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 1,226 Hr Asset located in: Lake Worth, TX	6446D	Forklift S/N: 67976 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 6,206 Hr Asset located in: Lake Worth, TX 2015 Toyota 8FGCU25 4500 lb Cushion Tire
6443B	2017 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 84139 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine	6447	Forklift S/N: 72623 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 3,747 Hr Asset located in: Lake Worth, TX
	Usage: 7,442 Hr Asset located in: Lake Worth, TX	6447	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift
6443C	2021 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: C0242 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2020 US EPA Label, Toyota		S/N: 70241 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 6,085 Hr Asset located in: Lake Worth, TX
	4YECS 4 Cylinder 2.2 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6447A	2014 Toyota 8FGCU25 4500 lb Cushion Tire Forklift
6444	2017 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 83017 C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine		S/N: 62161 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 5,663 Hr Asset located in: Lake Worth, TX
	Usage: 5,739 Hr Asset located in: Lake Worth, TX	6447B	2015 Toyota 8FGCU25 4500 lb Cushion Tire
6444A	2016 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 80050 C/W: 3 Stage Mast, 189 in Max Lift Height, 76 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 5,987 Hr Asset located in: Lake Worth, TX		Forklift S/N: 69963 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, Toyota 4YECS 4 Cylinder LPG Engine Usage: 6,922 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6447C	2011 Toyota 8FGCU25 4500 lb Cushion Tire	6453	2014 Toyota 8FGCU20 4000 lb Cushion Tire	
04470	Forklift S/N: 32218 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, 2011 US EPA Label, Toyota 4yECS 4 Cylinder 2.2 L LPG Engine Usage: 6,731 Hr	0433	Forklift S/N: 8FGCU25-64619 C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in Lowered Mast Height, 36 in Forks, Side Shift, Toyota 4 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6453A	2018 Cat DP25N 3700 lb Pneumatic Tire	
6448	2007 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 12090 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2007 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 4,459 Hr Asset located in: Lake Worth, TX	6453B	Forklift S/N: AT18E00601 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX 2013 Cat Cushion Tire Forklift	
6 4 4 0 D	·	+	S/N: AU2187	
6448B	2015 Doosan GC25E-5 4300 lb Cushion Tire Forklift S/N: FGA0L179001251 C/W: 3 Stage Mast, Full Free Lift, 76 in Max Lift Height, 189 in Lowered Mast Height, 40 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2015 US EPA Label, Woodward 4 Cylinder 2.4 L LPG Engine	6454	C/W: 3 Stage Mast, Full Free Lift, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2013 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 3,851 Hr Asset located in: Lake Worth, TX 2005 Komatsu FG20ST-14R 4000 lb Cushion	
	Usage: 6,001 Hr Asset located in: Lake Worth, TX		Tire Forklift S/N: 587879A	
6449	Heli CPYD25C-KU1H 4190 lb Cushion Tire Forklift S/N: 23025N7358 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine		C/W: 2 Stage Mast, 72 in Max Lift Height, 55 in Lowered Mast Height, 48 in Forks, Load Weigh System, 2006 US EPA Label, Nissan 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW- CORP Usage: 19,433 Hr Asset located in: El Paso, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	6454A	2002 Daewoo GC15S-2 2550 lb Cushion Tire Forklift	
6450	Heli CPYD25C-KU1H Cushion Tire Forklift S/N: 230252P8451 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX		Lift Height, 24 in Lowered Mast He	C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, 2002 US EPA Label, DAEWOO G420 4 Cylinder LPG Engine Usage: 9,145 Hr Asset located in: Lake Worth, TX
6451	Heli CPYD25C-KU1H 4080 lb Cushion Tire	6454B	2015 Toyota 8FGCU15 2500 lb Cushion Tire	
	Forklift S/N: 230252P8453 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX		Forklift S/N: 31743 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4Y ECS 4 Cylinder 36 kW 2.23 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	
6452	Heli CPYD25C-KU1H 4080 lb Cushion Tire	6454C	2017 Toyota 8FGCU25 1700 lb Cushion Tire	
	Forklift S/N: 230252P8452 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX		Forklift S/N: 83746 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 94 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 6,964 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6457	2012 Toyota 7FGCU35 4900 lb Pneumatic Tire Forklift S/N: 72810 C/W: 4 Stage Mast, Full Free Lift, 230 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Solid Pneumatic Tires, PSI 4 Cylinder LPG Engine	6464	2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused) S/N: 24482054 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX
6458	Usage: 9,584 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2017 Raymond 550-OPC30TT 3000 lb Order	6465	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482026 C/W: 2 Stage Mast, 118 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger
	Picker S/N: 55017A36479		Usage: 3 Km Asset located in : Lake Worth, TX
6450	C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	6466	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482051 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger
6459	2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36483		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	6467	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482008 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger
6460	2013 Raymond 960-CSR30TT 3000 lb Order Picker		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 9601302364 C/W: 2 Stage Mast, 250 in Max Lift Height, 130 in Lowered Mast Height, 24 V Usage: Not Available Asset located in: Lake Worth, TX		2024 JQ POWER JQ2T-MAX 2000 kg Electric Forklift (Unused) S/N: 24482052 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 64 V, Battery Charger Usage: Not Available
6461	2017 Raymond 550-OPC30TT 3000 lb Order Picker	6469	Asset located in: Lake Worth, TX
	S/N: 55017A36471 C/W: 2 Stage Mast, Full Free Lift, 240 in Max Lift Height, 106 in Lowered Mast Height, 42 in Forks, 24 V, Battery Watering System Usage: Not Available Asset located in : Lake Worth, TX		2024 STL Industrial STL2TN Electric Forklift (Unused) S/N: DM202401A06213 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 29 Hr
6462	2024 STL Industrial STL3TN Electric Forklift	6.470	Asset located in: Lake Worth, TX
	(Unused) S/N: 01A06131 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 5 Hr Asset located in: Lake Worth, TX	6470	2024 STL Industrial STL1TN Electric Forklift (Unused) S/N: 24A0235 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift Usage: Not Available
6463	2017 Raymond 4750C50 4850 lb Electric	6 471	Asset located in: Lake Worth, TX
	Forklift S/N: 4751710850 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V, Battery Watering System Usage: 5,947 Hr Asset located in: Lake Worth, TX	6471	2025 STL Industrial Electric Forklift S/N: DM202401A06206 C/W: 2 Stage Mast, 48 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 26 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6471A	2018 Toyota 8FBCU25 4400 lb Electric Forklift S/N: 77312 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 47 in Forks, Side Shift, 36 V, Battery Charger Usage: 1,972 Hr Asset located in: Lake Worth, TX	6483	2013 Princeton PB50X 5000 lb 3x3 Truck Mounted Forklift S/N: M480268C C/W: Single Stage Mast 24 in Lowered Mast Height, 47 in Forks, Tier 4, 2012 US EPA Label, Kubota v2203 4 Cylinder 35 kW 2.2 L Diesel Engine Usage: 2,060 Hr
6475	Cat R80 2800 lb Electric Forklift S/N: 4SM01049		Asset located in: Lake Worth, TX
	C/W: 3 Stage Mast, Full Free Lift, 191 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: 69 Hr Asset located in : Lake Worth, TX	6484	2013 Moffett M50 Lite 5000 lb 3x3 Truck Mounted Forklift S/N: M220415A C/W: Single Stage Mast 144 in Max Lift Height, 48 in Forks, Side Shift, Kubota V1505-T-ET03 4 Cylinder 1.5 L Diesel Engine
6476	Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused)		Usage: 3,850 Hr Asset located in: Lake Worth, TX
	S/N: Not Available C/W: One crate Usage: Not Available Asset located in : Lake Worth, TX	6484A	2001 Moffett M5000 5000 lb 3x3 Truck Mounted Forklift S/N: A05171R
6477	Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused) S/N: PHT6206139 C/W: 610 lb Capacity, 24 V, One Crate Usage: Not Available		C/W: 2 Stage Mast, 98 in Lowered Mast Height, 45 in Forks, Side Shift, 1999 US EPA Label, Kubota V2203-E 4 Cylinder 36.1 kW 2.2 L Diesel Engine Usage: 4,353 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6486	2013 Genie S125 4WD Diesel Telescopic Boom
6478	2012 Raymond 960-CSR30TT 3000 lb Electric Reach Truck S/N: 9601202198 C/W: 2 Stage Mast, 250 in Max Lift Height, 130 in Lowered Mast Height, 24 V Usage: Not Available Asset located in: Lake Worth, TX		Lift S/N: S12513D505 C/W: 125 ft Max Platform Height, 500 lb Ma: Weight Capacity, Jib, Extendable Axles, Pow to Platform, 2012 US EPA Label, Deutz td2014 Cylinder 74 hp 3.6 L Diesel Engine, 445 /50D710 Tires
6479	2016 Jungheinrich ETR340 4000 lb Electric Reach Truck S/N: 82820438 C/W: 2 Stage Mast, 302 in Max Lift Height, 130		Usage: 3,738 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	in Lowered Mast Height, 42 in Forks, 36 V, Battery Charger, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 5,032 Hr Notes: . Asset located in: Lake Worth, TX	6487	2012 Genie S-125 4WD Diesel Telescopic Boom Lift S/N: S125123373 C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, Deutz
6481	2012 Moffett P6000 6000 lb 3x3 Truck Mounted Forklift S/N: L270049 C/W: 3 Stage Mast, 124 in Max Lift Height, 78 in Lowered Mast Height, 74 in Forks, Fork Rotation, Tier 4, 2012 US EPA Label, Kubota V2203 4 Cylinder 2.2 L Diesel Engine Usage: 1,732 Hr Asset located in: Humble, TX		TD2011L04 4 Cylinder 3.6 L Diesel Engine Usage: 4,191 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6482	2013 Navigator RT5500 5500 lb 3x3 Truck Mounted Forklift S/N: 413847 C/W: 2 Stage Mast, 144 in Max Lift Height, 93 in Lowered Mast Height, 48 in Forks, Side Shift, Kubota 4 Cylinder 2.0 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
6489	2018 Genie S-85 XC 4WD Diesel Telescopic Boom Lift S/N: S85XCH-262 C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Tires Usage: 3,157 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6495	2015 Snorkel TB85J 4WD Diesel Telescopic Boom Lift S/N: TB85J-04-000049 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Kubota V2403 4 Cylinder 44 kW 2.4 L Diesel Engine, 15-625 Tires Usage: 4,173 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6490	2018 Genie S85XC 4WD Diesel Telescopic Boom Lift S/N: S85XCH260 C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2017 US EPA Label, Deutz TD 2.9 LP 4 Cylinder 2.95 L Diesel Engine, 18-625NHS Tires Usage: 4,567 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	- 6497	2014 Genie S-80X 4WD Diesel Telescopic Boom Lift S/N: S80X1412022 C/W: 80 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,562 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6498	2012 JLG 800S 4WD Diesel Telescopic Boom
6491	2011 Genie S85 4WD Diesel Telescopic Boom Lift S/N: S85118854 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2011 US EPA Label, Deutz 4 Cylinder 74 hp 3.6 L Diesel Engine, 18-625 Tires Usage: 2,485 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX		Lift S/N: 0300158033 C/W: 80 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2011 US EPA Label, Deutz D2011L04 4 Cylinder 3.6 L Diesel Engine Usage: 2,352 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6493	2018 Haulotte HT85RT 4WD Diesel Telescopic Boom Lift S/N: 2030133 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 4 Cylinder Diesel Engine Usage: 1,938 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	- 6499	2018 Haulotte HT67RTJ 4WD Diesel Telescopic Boom Lift S/N: TD500215 C/W: 67 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2017 US EPA Label, Kubota V2403-CR-TI-EF02 4 Cylinder 47 kW 2.4 L Diesel Engine, 385/65- 22.5 Tires Usage: 3,522 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6494	2017 Haulotte HT85 RTJ PRO 4WD Diesel Telescopic Boom Lift S/N: 2021508 C/W: 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2016 US EPA Label, Kubota V2607 4 Cylinder 2.6 L Diesel Engine Usage: 1,938 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6500	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300236291 C/W: 65 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 748 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6502	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift	6506	2015 Genie S60X 4WD Diesel Telescopic Boom Lift
	S/N: 0300233965 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		S/N: S60X15A-29654 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D 2.9 L4 49 hp 2.92 L Diesel Engine, 355/55D625 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,781 Hr
	Usage: 5,192 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6503	2016 Genie S-65 4WD Dual Fuel Telescopic Boom Lift S/N: S6016H-35454 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, CARB Compliant, 4 Cylinder 64.3 kW 2.5 L Dual Fuel Engine, 355/55D625 NHS Tires Usage: 3,590 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	-6507	Lift S/N: 300236812 C/W: 59 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,026 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
<u></u>	Asset located in: Humble, TX	6540	<u></u>
6504	2012 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S6012-23502 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2011 US EPA Label, Deutz D2011L03I 4 Cylinder 49 hp 2.3 L Diesel Engine, 355/55D625 Tires Usage: 4,624 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6510	2006 Genie S60 4WD Diesel Telescopic Boom Lift S/N: S600614228 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Diesel Engine, 355/55D625 Tires Usage: 973 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	6510A	• • • • • • • • • • • • • • • • • • •
6505	2017 Genie S60X 4WD Diesel Telescopic Boom Lift S/N: S60XH-37752 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, CARB Compliant, Deutz D2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355 /55D625 NHS Tires Usage: 2,105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX		Lift S/N: 0300236779 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, Deutz D 2.9 L4 36.4 kW 2.9 L Diesel Engine, 1417.5 NHS Tires Usage: 3,690 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6511	2019 Skyjack SJ45T 4WD Diesel Telescopic Boom Lift S/N: 98003735 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Deutz Diesel Engine Usage: 2,136 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	6515	2017 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300236550 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Fort Smith, AR	6516	2016 JLG 400S 4WD Diesel Telescopic Boom
6511A	2019 Genie S45 4WD Diesel Telescopic Boom Lift S/N: S45H-26957 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Tires Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Lift S/N: 0300211074 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,626 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6511B	2018 Genie S-45 4WD Diesel Telescopic Boom Lift S/N: S45H-26987 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Tires Usage: 2,186 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6517	2016 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300210880 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,719 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6513	2007 Snorkel TB42DZ 4WD Diesel Telescopic Boom Lift S/N: MR07088RBLT C/W: 42 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2008 US EPA Label, Deutz F3L2011 3 Cylinder 48 hp 2.33 L Diesel Engine, 12.16.5N Tires Usage: 3,176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2015 Genie S40 4WD Diesel Telescopic Boom	6518	2015 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300209072 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,731 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Lift S/N: S4015-20737 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,771 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6519	2015 JLG 400S 4WD Telescopic Boom Lift S/N: 0300204969 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, Deutz 4 Cylinder Diesel Engine, 12- 16.5 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,775 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
6521	2015 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300208881 C/W: 40 ft Max Platform Height, 600 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.914 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6525	2015 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300198551 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Tires Usage: 3,975 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6522	2014 JLG 400S 4WD Diesel Telescopic Boom Lift		Asset located in: Humble, TX
	S/N: 0300191770 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz d2.914 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,228 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6526	2018 JLG 600AJ 4WD Diesel Articulating Boom Lift S/N: 0300239502 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz 2.9l4 4 Cylinder 67 hp 2.9 L Diesel Engine Usage: 1,081 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6523	2014 JLG 400S 4WD Diesel Telescopic Boom	6527	2011 JLG 600AJ 4WD Diesel Articulating
0020	Lift S/N: 0300192112 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,661 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Boom Lift S/N: 0300143499 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2010 US EPA Label, Deutz D2011L4 4 Cylinder 3.1 L Diesel Engine, 355/55D625 Tires Usage: 4,083 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6524	2016 Haulotte HA130RTJPRO 4WD Diesel Articulating Boom Lift S/N: AD127595 C/W: 129 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Perkins Engine Usage: 3,370 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	- 6529	Boom Lift S/N: Z601414246 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Deutz D2011L03I 4 Cylinder 49 hp Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,716 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6531	2015 Snorkel A46JRT 4WD Diesel Articulating Boom Lift S/N: A46JRT-04-000348 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505 4 Cylinder 18.5 kW 1.5 L Diesel Engine, 355/55D62.5 Tires Usage: 1,226 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6537	2014 Genie Z45/25 2WD Electric Articulating Boom Lift S/N: Z452514A52188 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6532	Skyjack SJ46AJ 4WD Diesel Articulating Boom	6538	2012 Genie Z40/23NRJ 2WD Electric
	Lift S/N: 95000588 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine Usage: 2,493 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Articulating Boom Lift S/N: Z40N12-1774 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 25.6 X7 Non-Marking Tires Usage: 1,120 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6534	2012 JLG 450AJ 4WD Articulating Boom Lift	6539	2012 Genie Z40/23NRJ 2WD Electric
	S/N: 0300161279 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D2011 3 Cylinder 49 hp 2.3 L Diesel Engine, 33X15.50 Tires Usage: 3,162 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Articulating Boom Lift S/N: Z40N12-1683 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22X7X17 Non-Marking Tires Usage: 1,393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6535	2015 Genie Z-45/25J 2WD Electric Articulating Boom Lift S/N: Z452515A54948 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam- Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,406 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6541	2012 Genie Z40/23NRJ 2WD Electric Articulating Boom Lift S/N: Z40N12-1775 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, 25.6x7 Solid Tires Usage: 1,288 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6542	2012 Genie Z40/23NRJ 2WD Electric
6536	2015 Genie Z45/25J 4WD Diesel Articulating Boom Lift S/N: Z452515A-53530 C/W: 24 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz U2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 315/55D20 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,249 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK		Articulating Boom Lift S/N: Z40N12-1797 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Solid Tires Usage: 1,230 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6543	2017 Genie Z-33/18 2WD Electric Articulating Boom Lift S/N: Z3318M1589 C/W: 32 ft Max Platform Height, 440 lb Max Weight Capacity, Power to Platform, 22X9 Solid Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 619 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6550	2017 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40002479 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,620 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6544	2015 JLG E300 AJP 2WD Electric Articulating		Asset located in: Lake Worth, TX
	Boom Lift S/N: 0300203331 C/W: 30 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 823 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6551 2017 Skyjack S Lift S/N: 40002473 C/W: 41 ft May Weight Capaci Platform, Stab Control Box, 20 WG972-GL-ET Engine, EQUIPH EQUIPMENT Usage: 3,292 F Notes: AERIAL SAFETY HARN FUNCTION TES	S/N: 40002473 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-
6545	2018 JLG T500J Electric Towable Lift S/N: 0030009466 C/W: 50 ft Max Platform Height, 500 lb Max		Usage: 3,292 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	Weight Capacity, Jib, Power to Platform Usage: 37 Hr		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6552	2015 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40001765 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2015 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,788 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6546	2018 JLG T500J Electric Towable Lift S/N: 5DYACJ1J3JF009464 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 50 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		
6547	2018 JLG T500J Electric Towable Lift	6552	Asset located in: Lake Worth, TX
	S/N: 5DYACJ1J5JF009465 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 55 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6553	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40001309 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, Kubota WG972 3 Cylinder Dual Fuel Engine Usage: 2,649 Hr Notes: AERIAL UNITS REQUIRE PROPER
6548	2014 JLG T500J Towable Lift S/N: 0030008920 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 182 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
6553A	2013 JLG M4069 4x4 Diesel Scissor Lift S/N: 0200217745 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2012 US EPA Label, Kubota 1 Cylinder 0.2 L Diesel Engine Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX	6562	2017 Skyjack SJ6826 RT Dual Fuel Scissor Lift S/N: 37010717 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Foam Filled Tires, Upper Control Box, Kubota WG752-GL - ET 3 Cylinder 740.5 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,991 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6554	2007 JLG 3394RT 4x4 Dual Fuel Scissor Lift S/N: 0200164159 C/W: 33 ft Max Platform Height, 2250 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 4 Cylinder Dual Fuel Engine Usage: 998 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2017 Genie GS3390RT 4x4 Dual Fuel Scissor	6564	2013 JLG M4069LE 4x4 Diesel Scissor Lift S/N: 0200217747 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Power Inverter, Solid Non-Marking Tires, Upper Control Box, Tier 4, 2012 US EPA Label, Kubota 0C60-ET01 1 Cylinder 0.27 L Diesel Engine Usage: 276 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
0333	Lift S/N: GS90F-54078 C/W: 2500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, 2017 US EPA Label, 4 Cylinder 64.3 kW 2.5 L LPG Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,011 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK	6565	Asset located in: Midland, TX 2013 JLG 4069LE Electric Scissor Lift S/N: 0200219769 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 694 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6558	2017 Skyjack SJ6832RT 4x4 Dual Fuel Scissor Lift S/N: 37010203 C/W: 32 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2016 US EPA Label, Kubota WG752-GL-ET 3 Cylinder 740 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,144 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6566 6568	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1728 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK 2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P1715
6560	Asset located in: Lake Worth, TX 2015 Genie GS-2669RT 4x4 LPG Scissor Lift S/N: GS6915-7055 C/W: 26 m Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2014 US EPA Label, Kubota WG972-GL-ET 3 Cylinder LPG Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,044 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK		C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 479 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6569	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1734 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 502 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	6575	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1678 C/W: 39 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 615 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6570	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1802 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 504 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6576	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47D6070 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
0371	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P1430 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 509 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6577	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P2225 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6572	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P-1824 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 594 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6578	Asset located in: Lake Worth, TX 2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-1545 C/W: 20 ft Max Platform Height, 550 lb Max Weight Capacity, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 498 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6573	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P1822 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 628 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6579	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1620 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 499 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

	D : 1	I		
Lot #	Details	Lot #	Details	
6580	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-3104 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 500 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6586	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1278 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 534 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
6582	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1580 C/W: 40 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 590 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	-6587	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1054 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 788 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	
	FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6588	2018 Skyjack SJIII-4740 Electric Scissor Lift S/N: 70202991 C/W: 40 ft Max Platform Height, 500 lb Max	
6583	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-2977 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 627 Hr Notes: AERIAL UNITS REQUIRE PROPER		Weight Capacity, Platform Extensic Platform, Solid Non-Marking Tires, Control Box Usage: Not Available Notes : AERIAL UNITS REQUIRE PRO SAFETY HARNESS, LANYARD, AND FUNCTION TEST AND LOAD	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2018 Skyjack SJIII-4740 Electric Scissor Lift S/N: 70202542	
6584	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-1511 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 633 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 515 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6590	2017 Skyjack SJIII4740 Electric Scissor Lift S/N: 70201795	
6585	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1286 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Stabilizers, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6591	Skyjack SJIII-4740 Electric Scissor Lift S/N: Not Available C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 349 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6597	2017 Snorkel S4732E Electric Scissor Lift S/N: S4732E-04-900112 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT FROM UNITED RENTALS Usage: 180 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6592	2017 MEC 4046SE Electric Scissor Lift S/N: 16700245 C/W: 38 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6598	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P-143973 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6593	Asset located in: Lake Worth, TX 2017 MEC 4046SE Electric Scissor Lift S/N: 16700250 C/W: 38 ft 7 in Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6599	2017 Genie GS-3246 Electric Scissor Lift S/N: 143969 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 114 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6594	Asset located in: Lake Worth, TX 2015 JLG 3248RS Electric Scissor Lift S/N: 0200237506 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 480 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6600	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P-143947 C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 290 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P143978
6595	2015 JLG 3248RS Electric Scissor Lift S/N: 0200243786 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 538 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 335 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6603	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P143966 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 337 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6608	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266401 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 81 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6604	2017 Genie GS3246 Electric Scissor Lift S/N: GS46P143806 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 297 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6610	2017 JLG 3246ES Electric Scissor Lift S/N: 0200263931 C/W: 31 ft Max Platform Height, 750 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 206 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6604A	2017 Genie GS3246 Electric Scissor Lift S/N: GS46P143724		FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6612	2017 JLG 3246ES Electric Scissor Lift S/N: M200013247 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 401 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6606	2015 Genie GS-3246 Electric Scissor Lift		Asset located in: Lake Worth, TX
6607	S/N: GS4615A137584 C/W: 33 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 484 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2017 JLG 3246ES Electric Scissor Lift	6613	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266207 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 402 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
0007	S/N: 0200263928		Asset located in: Lake Worth, TX
	C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 59 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6614	2017 JLG 3246ES Electric Scissor Lift S/N: M200013176 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6615	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266205 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6620	2017 JLG 3246ES Electric Scissor Lift S/N: M200013245 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6616	2015 JLG 3246ES Electric Scissor Lift S/N: M200001109 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 413 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6621	2016 JLG 3246ES Electric Scissor Lift S/N: M200000621 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 492 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6617	2017 JLG 3246ES Electric Scissor Lift S/N: M200013175 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 425 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6622	2017 Skyjack SJIII-4632 Electric Scissor Lift S/N: 80180032 C/W: 32 ft Max Platform Height, 750 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6618	2017 JLG 3246ES Electric Scissor Lift S/N: M200013211 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6623	2019 Skyjack SJIII4632 Electric Scissor Lift S/N: 70041193 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 189 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6619	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266209 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	- 6624	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70017904 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 289 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6625	2015 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70022067 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6631	Skyjack SJIII 4632 Electric Scissor Lift S/N: Not Available C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 325 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	
6626	2015 Skyjack SJIII-4632 Electric Scissor Lift		Asset located in: Lake Worth, TX	
	S/N: 70022705 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 368 Hr Notes: AERIAL UNITS REQUIRE PROPER	6632	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70018708 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension Usage: 358 Hr Notes: AERIAL UNITS REQUIRE PROPER	
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
6627	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70019200 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6633	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70018805 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 358 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	
6628	2014 Skyjack SJIII 4632 Electric Scissor Lift	6634	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
	S/N: 70019482 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2018 Genie GS3232 Electric Scissor Lift S/N: GS32P-157610 C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
6629	2014 Skyjack SJIII 4632 Electric Scissor Lift	6635	2017 Genie GS3232 Electric Scissor Lift	
	S/N: 70019116 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0035	S/N: GS32P-154160 C/W: Platform Extension, Power to Solid Non-Marking Tires, Upper Co EQUIPMENT-FROM-SUNSTATE-EQ Usage: Not Available Notes : AERIAL UNITS REQUIRE PR SAFETY HARNESS, LANYARD, ANI FUNCTION TEST AND LOAD;	S/N: GS32P-154160 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6630	2014 Skyjack SJIII4632 Electric Scissor Lift S/N: 70017856 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 339 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
6636	2017 Genie GS-3232 Electric Scissor Lift S/N: GS32P-148830 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 509 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6642	2014 Genie GS-3232 Electric Scissor Lift S/N: 135791 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6637	2017 Genie GS-3232 Electric Scissor Lift	6642	2018 Snorkel S4726E Electric Scissor Lift
	S/N: GS32P148756 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6643	S/N: S4726E-04-180500837 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 109 Hr Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6638	2017 Genie GS3232 Electric Scissor Lift S/N: GS32P-149344 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2015 Genie GS3232 Electric Scissor Lift		2017 JLG 2646ES Electric Scissor Lift S/N: M200007467 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 291 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	S/N: GS3215A141191	6645	·
	C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 465 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6645	2015 JLG 2646ES Electric Scissor Lift S/N: M200001100 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 477 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6641	2015 Genie GS-3232 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 141232 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 398 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6646	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70026601 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6647	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70022572 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 200 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6652	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263898 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 328 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6648	2015 Skyjack SJIII4626 Electric Scissor Lift S/N: 70022293	6653	2017 JLG 2646ES Electric Scissor Lift
	C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 240 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 0200263463 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 375 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6649	S/N: 70022355 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 260 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
		6654	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263458 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr
		_	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6650	2015 Skyjack SJIII4626 Electric Scissor Lift S/N: 70021519		FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 282 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6655	2016 JLG 2646ES Electric Scissor Lift S/N: M200001128 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 227 Hr Notes: AERIAL UNITS REQUIRE PROPER
6651	2014 Skyjack SJIII4626 Electric Scissor Lift		SAFETY HARNESS, LANYARD, AND PPE TO
	S/N: 70021343 C/W: 26 ft Max Platform Height, 1000 lb Max		FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Weight Capacity, Platform Extension, Upper Control Box Usage: 410 Hr Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in : Lake Worth, TX	6656	2015 JLG 2646ES Electric Scissor Lift S/N: M200001101 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 373 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6657	2015 JLG 2646ES Electric Scissor Lift S/N: M200000271 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6662	2016 Genie GS-2632 Electric Scissor Lift S/N: GS3216P-145511 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 489 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6658	2015 Genie GS2646 Electric Scissor Lift	6663	2016 Genie GS-2632 Electric Scissor Lift
	S/N: 137357 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 246 Hr Notes : AERIAL UNITS REQUIRE PROPER		S/N: GS3216P145971 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 540 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6659	2015 Genie GS2646 Electric Scissor Lift S/N: GS4615A136705 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 362 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6664	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140574 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 28 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX	6665	2015 Genie GS-2632 Electric Scissor Lift
6660	2015 Genie GS-2646 Electric Scissor Lift S/N: GS4615A137346 C/W: 25 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: GS3215A-140508 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 245 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6667	2015 Genie GS-2632 Electric Scissor Lift
6661	2015 Genie GS-2646 Electric Scissor Lift S/N: GS4615A137130 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3215A140092 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6668	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-138165 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 343 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6675	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A140581 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 380 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6669	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140139 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 404 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6676	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A-139158 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6670	Asset located in: Lake Worth, TX 2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A138159 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 424 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6677	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140565 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6673	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A138162 C/W: 26 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6677A	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A139156 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 525 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6674	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A137939 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	-6679	2014 Genie GS-2632 Electric Scissor Lift S/N: GS3214A136069 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 396 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6680	2014 Genie GS-2632 Electric Scissor Lift S/N: GS3214A-118609 C/W: 26 ft Max Platform Height, 26 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6685	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252494 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6681	2013 Genie GS-2632 Electric Scissor Lift S/N: GS3213A116224 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6686	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252789 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6682	2016 JLG 2632ES Electric Scissor Lift S/N: 200252535 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 339 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6687	2016 JLG 2632ES Electric Scissor Lift S/N: M200002023 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 435 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6683	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252837 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6688	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252492 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 482 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6684	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252763 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6688A	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252564 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6689	2015 JLG 2632ES Electric Scissor Lift S/N: M200000541 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6694	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244546 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 471 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6690	2015 JLG 2632ES Electric Scissor Lift	6695	2015 JLG 2632ES Electric Scissor Lift
	S/N: 0200244222 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: 0200244248 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 421 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6691	2015 JLG 2632ES Electric Scissor Lift S/N: 0200246996 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 444 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6696	2015 JLG 2632ES Electric Scissor Lift S/N: 0200247096 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6692	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244228 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 470 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6697	2015 JLG 2632ES Electric Scissor Lift S/N: 0200251446 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 370 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6693	2015 JLG 2632ES Electric Scissor Lift	6698	2015 Skyjack SJ III 3226 Electric Scissor Lift
	S/N: 0200243900 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 27023528 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6699	2014 Skyjack SJIII 3226 Electric Scissor Lift S/N: 27020188 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 299 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6704	2013 Genie GS2032 Electric Scissor Lift S/N: GS3213A113424 C/W: 20 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 144 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6700	2014 Skyjack SJIII-3226 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 27017585 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 251 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6705	Hangcha 81XE-II Electric Scissor Lift S/N: Not Available C/W: 400 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Oklahoma City, OK	6706	2016 Skyjack SJIII-3219 Electric Scissor Lift
6701	1 2016 JLG 2630ES Electric Scissor Lift S/N: 0200252795 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 388 Hr		S/N: 22104289 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Solid Non Marking Tires, Upper Control Box Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6707	Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD;		2016 Skyjack SJIII-3219 Electric Scissor Lift
6702	Asset located in: Lake Worth, TX 2011 JLG 2630ES Electric Scissor Lift S/N: 0200200580 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 369 Hr		S/N: 22104294 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Solid Non Marking Tires, Upper Control Box Usage: 279 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6708	2017 Skyjack SJIII-3219 Electric Scissor Lift
6703	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2017 Snorkel S3220E Electric Scissor Lift S/N: S3220E-04-900021 C/W: 20 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER		S/N: 22104310 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 391 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	SAFETY HARNESS, LANYARD, AND PPE TO		Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6709	2018 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22135992 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 284 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
			Accet located in: Lake Worth TV

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6710	Skyjack SJIII-3219 Electric Scissor Lift S/N: 1000025 C/W: 19 m Max Platform Height, 600 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 161 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6716	2015 JLG 1932RS Electric Scissor Lift S/N: 0200243353 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX	6717	2015 JLG 1932RS Electric Scissor Lift
6711	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22063947 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 218 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: 0200251219 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6712	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22060591 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 258 Hr	-6718	2015 JLG 1932RS Electric Scissor Lift S/N: 0200247820 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 409 Hr Notes: AERIAL UNITS REQUIRE PROPER
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6719	2015 JLG 1932RS Electric Scissor Lift
6713	2019 JLG 1932R Electric Scissor Lift S/N: M200029543 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 83 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	-0719	S/N: 0200244479 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6721	2015 JLG 1932RS Electric Scissor Lift
6715	2015 JLG 1932RS Electric Scissor Lift S/N: 0200244480 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 383 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 0200244472 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

		1	
Lot #	Details	Lot #	Details
6722	2015 JLG 1932RS Electric Scissor Lift S/N: 0200243354 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6726	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234817 C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 423 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6723	2014 JLG 1932RS Electric Scissor Lift	6731	JLG 1932RS Electric Scissor Lift
0723	S/N: 200235081 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 158 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 0200234825 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 520 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6724	<u> </u>	6732	2014 JLG 1932RS Electric Scissor Lift
0724	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236585 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 373 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: 0200235386 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6733	2014 JLG 1932RS Electric Scissor Lift
6725	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234422 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6766	S/N: 0200235121 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6734	2014 JLG 1932RS Electric Scissor Lift
6725A	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236594 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 623 Hr Asset located in: Lake Worth, TX		S/N: 0200234070 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6735	2014 JLG 1932RS Electric Scissor Lift S/N: 200234879 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 594 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6740	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166134 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 65 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6736	2014 JLG 1932RS Electric Scissor Lift	6741	2017 Genie GS-1930 Electric Scissor Lift
	S/N: 0200236058 C/W: 19 m Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: GS30P166091 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6737	2016 Snorkel S3219E Electric Scissor Lift S/N: S3219E-04-001508 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 1,362 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6742	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P168863 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6738	2018 Snorkel S3129E Electric Scissor Lift	6743	
	S/N: S3219E-04-181006644 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
.700	Asset located in: Lake Worth, TX	_	FUNCTION TEST AND LOAD
6739	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P168879		Asset located in: Lake Worth, TX
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	6744	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P-167041 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 438 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6745	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-150796 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 64 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6751	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-151109 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6746	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156688 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 312 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6752	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A150812 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset Joseph In: Lake Worth, TY
6747	2016 Genie GS-1930 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS3016A-151099 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 381 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6753	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156662 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6749	2016 Genie GS-1930 Electric Scissor Lift	6755	2016 Genie GS-1930 Electric Scissor Lift
	S/N: GS3016P159321 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 399 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6766	S/N: GS3016P156684 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
<u></u>	· · · · · · · · · · · · · · · · · · ·	\dashv	Asset located in: Lake Worth, TX
6750	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P153060 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6757	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-150674 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 471 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6757A	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159322 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 544 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6763	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159709 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6759	2016 Genie GS-1930 Electric Scissor Lift	6764	2016 Genie GS-1930 Electric Scissor Lift
	S/N: GS3016P159736 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr		S/N: GS3016P-159326 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 622 Hr
	Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	ļ	Asset located in: Lake Worth, TX
6760	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P-159631 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER	6765	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A150748 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 450 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6761	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156681 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 603 Hr	6767	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149270 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6762	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159764 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6768	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146342 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 329 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6771	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-148159 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 360 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK 2015 Genie GS-1930 Electric Scissor Lift	6776	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146310 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	S/N: GS3015A146154 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6777	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146331 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6773	2015 Genie GS-1930 Electric Scissor Lift		Asset located in: Lake Worth, TX
6774	S/N: GS3015A149284 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2015 Genie GS-1930 Electric Scissor Lift	6778	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-142980 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 410 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6775	S/N: GS3016P159299 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2015 Genie GS-1930 Electric Scissor Lift	6779	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145103 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	S/N: GS3015A-149399		Asset located in: Lake Worth, TX
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 400 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6780	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148246 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6781	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146258 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 424 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6786	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145121 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 439 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6782	2015 Genie GS-1930 Electric Scissor Lift	6787	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A145084 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: GS3015A145117 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 442 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	-	Asset located in: Lake Worth, TX
6783	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146435 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr Notes: AERIAL UNITS REQUIRE PROPER	6788	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146104 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 443 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6784	2015 Genie GS-1930 Electric Scissor Lift	6789	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A149417 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: GS3015A-148249 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 448 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX	6790	2015 Genie GS-1930 Electric Scissor Lift
6785	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149321 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3015A146319 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 449 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6791	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149351 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6795A	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148197 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6792	2015 Genie GS-1930 Electric Scissor Lift	6796	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A146194 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes : AERIAL UNITS REQUIRE PROPER		S/N: GS3015A-149305 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 466 Hr Notes : AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6793	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-145141 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	6797	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149397 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 468 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6794	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015149276 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 445 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6798	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149413 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 491 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6795	2015 Genie GS-1930 Electric Scissor Lift	6799	2015 Genie GS-1930 Electric Scissor Lift
0/70	S/N: GS3015A-149414 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0/77	S/N: GS3015A-149349 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 493 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6800	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148168 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6805	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146282 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6801	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146325 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6806	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A142971 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6802	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149391 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 504 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6808	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138135 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6803	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146335 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 408 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6809	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A138418 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 412 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6804	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149262 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 543 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6810	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138412 C/W: 19 ft Max Platform Height, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6811	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-136463 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 429 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6816	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A136467 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 561 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6812	2014 Genie GS-1930 Electric Scissor Lift	6817	2013 Genie GS-1930 Electric Scissor Lift
	S/N: GS3014A138505 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 453 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		S/N: GS3013A124360 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 367 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD		FUNCTION TEST AND LOAD;
6813	Asset located in: Lake Worth, TX 2014 Genie GS-1930 Electric Scissor Lift	6818	Asset located in: Lake Worth, TX 2013 Genie GS-1930 Scissor Lift
0010	S/N: GS3014A-138417 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 459 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: GS3013A124169 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6814	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138080 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6819	2017 JLG 1930ES Electric Scissor Lift S/N: M200012853 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 324 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6815	2014 Genie GS-1930 Electric Scissor Lift	6820	2017 JLG 1930ES Electric Scissor Lift
	S/N: GS3014A-138082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 464 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: 0200264250 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 392 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6821	2017 JLG 1930ES Electric Scissor Lift	6826	2017 JLG 1930 ES Electric Scissor Lift
0821	S/N: M200012778 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0820	S/N: 0200264702 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 379 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6822	2017 JLG 1930ES Electric Scissor Lift	6827	2017 JLG 1930 ES Electric Scissor Lift
	S/N: M200006460 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 488 Hr		S/N: M200005469 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6823	2017 JLG 1930ES Electric Scissor Lift S/N: 0200264246 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 525 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6827A	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006504 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 447 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6824	2017 JLG 1930ES Electric Scissor Lift	6828	2016 JLG 1930 ES Electric Scissor Lift
0624	S/N: M200006500 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: 0200256735 C/W: 18 ft 8 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6829	2017 JLG 1930 ES Electric Scissor Lift
6825	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006381 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 521 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: M200006299 C/W: 18 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 382 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
6830	2016 JLG 1930 ES Electric Scissor Lift S/N: M200003881 C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6836	2015 JLG 1930ES Electric Scissor Lift S/N: 0200246832 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 425 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6830A	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006461 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6837	2012 JLG 1930 ES Electric Scissor Lift S/N: B200004837 C/W: 18 ft 10 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 496 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX 2020 MEC MICRO 19 Electric Scissor Lift
6832	2016 JLG 1930ES Electric Scissor Lift S/N: M200003701 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 446 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6839	S/N: 16907444 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 88 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2018 MEC 1330SE Electric Scissor Lift
6834	2015 JLG 1930 ES Electric Scissor Lift S/N: 0200248756 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 236 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6840	S/N: 16301468 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 24 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2018 MEC 1330SE Electric Scissor Lift
6835	2015 JLG 1930 ES Electric Scissor Lift S/N: 0200246003 C/W: 18 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 402 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 16301584 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6841	2018 MEC 1330SE Electric Scissor Lift S/N: 16301583 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6846	2017 MEC 1330SE Electric Scissor Lift S/N: 16301230 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 19 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6842	2018 MEC 1330SE Electric Scissor Lift	6847	2017 MEC 1330SE Electric Scissor Lift
	S/N: 16301451 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 256 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: 16301591 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6843	2018 MEC 1330SE Electric Scissor Lift S/N: 16301467 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6848	2017 MEC 1330SE Electric Scissor Lift S/N: 16301447 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6044		6849	MEC 1330SE Electric Scissor Lift
6844	2018 MEC 1330SE Electric Scissor Lift S/N: 16301460 C/W: 13 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: 16301456 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6845	·	6850	2017 MEC 1330SE Electric Scissor Lift
0043	2018 MEC 1330SE Electric Scissor Lift S/N: 16301603 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 16301120 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6851	2017 Genie AWP-30S Vertical Mast Lift S/N: AWPG89720 C/W: 29 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6857	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-50133 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 419 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6852	2017 Snorkel MB26J Vertical Mast Lift S/N: MB26J-01-170700055 C/W: 26 ft Max Platform Height, 475 lb Max Weight Capacity, Power to Platform, Upper Control Box Usage: 258 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6858	2017 Genie GR-20 Vertical Mast Lift S/N: GRP48660 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 448 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6853	2018 Genie IWP-25S Vertical Mast Lift S/N: IWPG-12193		FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	C/W: 24 ft 11 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK	6860 2016 Genie GR-20 Vertical Mast Lift S/N: GR16P-40894 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 6 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 6861 2016 Genie GR-20 Vertical Mast Lift S/N: GR16P-43838 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 640 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 6862 2015 Genie GR-20 Vertical Mast Lift S/N: GR15-39295 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT Usage: 487 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK	S/N: GR16P-40894 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 6 Hr
6854	2017 Genie AWP-25S Vertical Mast Lift S/N: AWPG-90308 C/W: 24 ft 11 in Max Platform Height, 350 lb		
	Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GR16P-43838 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT
6855	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-49588 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GR15-39295 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-
6856	2017 Genie GR20 Vertical Mast Lift S/N: GRP-50131 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 342 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Usage: 487 Hr Notes : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD

Lot #	Details	Lot #	Details
6863	2015 Genie GR-20 Vertical Mast Lift S/N: GR1538516 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 448 Hr Asset located in: Lake Worth, TX	6866	6866 2013 Genie GR-20 Vertical Mast Lift S/N: GR13-27800 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power t Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 495 Hr Notes: AERIAL UNITS REQUIRE PROPER
6864	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539023 C/W: 20 ft Max Platform Height, 350 lb Max		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 435 Hr Asset located in: Lake Worth, TX	6867	2013 Genie GR-20 Vertical Mast Lift S/N: GR1328800 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires,
6865	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539233 C/W: 19 ft 9 in Max Platform Height, 350 lb		Upper Control Box Usage: Not Available Asset located in : Lake Worth, TX
	Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 452 Hr Asset located in: Lake Worth, TX	6868	2013 JLG 20MVL Vertical Mast Lift S/N: 0130019279 C/W: 19 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available
6865A	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539281 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension,	6869	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 498 Hr Asset located in : Lake Worth, TX		2019 Haulotte STAR 20 Vertical Mast Lift S/N: 2062580 C/W: 19 ft Max Platform Height, 580 lb Max Weight Capacity, Platform Extension, Solid Non-
6865B	2015 Genie GR-20 Vertical Mast Lift S/N: GR1538466 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box		Marking Tires, Upper Control Box Usage: 400 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Usage: 410 Hr Asset located in : Lake Worth, TX	6870	2023 Ballymore DVML-18 Vertical Mast Lift (Unused)
6865C	2014 Genie GR-20 Vertical Mast Lift S/N: GR1430574 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 361 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: DBA2302163 C/W: 19 ft 7 in Max Platform Height, 350 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6871	2017 Genie GR-12 Vertical Mast Lift S/N: GRP-49699 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 214 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6876	2015 Genie GR-12 Vertical Mast Lift S/N: GR1538757 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6872	2017 Genie GR-12 Vertical Mast Lift	6878	2014 Genie GR-12 Vertical Mast Lift
	S/N: GRP-49754 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 301 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: GR1436093 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 544 Hr Notes : AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6873	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41021 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 319 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6879	2014 Genie GR-12 Vertical Mast Lift S/N: GR14-35973 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	1000	Asset located in: Lake Worth, TX
6874	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41028 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 476 Hr	-6880	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P21140 C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket Usage: 208 Hr Asset located in: Lake Worth, TX
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6881	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P20643
	Asset located in: Humble, TX		C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36
6875	2015 Genie GR-12 Vertical Mast Lift S/N: GR1539738 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension,		in Bucket Usage: 455 Hr Asset located in: Lake Worth, TX
	Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 367 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6881A	2016 Bobcat MT55 Mini Compact Track Loade S/N: B38T12812 C/W: Open Operator Station, Tier 4, 2016 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,344 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6882	2019 Vermeer S925TX Mini Compact Track Loader S/N: 1VRL07056J1000534 C/W: Open Operator Station, Tier 4, 2018 US EPA Label, 7 in Track Belts, Manual Coupler, 42 in Bucket Usage: 2,318 Hr	6890	2024 JQ POWER JQ400 Mini Compact Track Loader S/N: 2404178462 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6891	2024 JQ POWER JQ400 Mini Compact Track
6883	2014 Ditch Witch SK755 Tracked Trencher Cable Plow S/N: CMWZ57NLCE0000057 C/W: Tier 4, 2012 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, Hydrostatic Drive, 7 in Wide x 48 in Long Combination Trencher Chain, 9 in Rubber Tracks Usage: 3,874 Hr		Loader (Unused) S/N: 2404163356 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX 2024 Machpro MP-S300 Mini Compact Track
	Asset located in: Lake Worth, TX	6892	Loader (Unused)
6884	2024 Eingp SCL850 Mini Compact Track Loader (Unused) S/N: SCL8500125 C/W: Open Operator Station, 9 in Track Belts, Manual Coupler, 40 in Bucket		S/N: MP2409073147 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Àvailable	6893	2024 AGT CRT23 Mini Compact Track Loader
6885	Asset located in: Lake Worth, TX 2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket		(Unused) S/N: CRT232024060000006 C/W: Open Operator Station, 2024 US EPA Label, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 2 Hr Asset located in : Lake Worth, TX	6894	2024 JQ POWER JQ400 Mini Compact Track
6886	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket Usage: Not Available		Loader (Unused) S/N: 2404178498 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6895	2024 Machpro MP-S300 Mini Compact Track
6887	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: 1 Hr		Loader (Unused) S/N: MP2409073142 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6896	2024 Machpro MP-S300 Mini Compact Track
6888	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178459 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available		Loader (Unused) S/N: MP2409043138 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6897	2024 Machpro MP-S300 Mini Compact Track
6889	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404163371 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX		Loader S/N: SLP2403080620 C/W: Open Operator Station, 2023 US EPA Label, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: 37 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6898	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409043137 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6906	2024 Digmaster DM200 Mini Excavator (Unused) S/N: DM24080303 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket Usage: Not Available
6899	2024 BTTL ST25M-6 Mini Compact Track		Asset located in: Lake Worth, TX
	Loader (Unused) S/N: A2407158825 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6907	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408069118 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available
6900	2024 BTTL ST25M-6 Mini Compact Track	6000	Asset located in: Lake Worth, TX
	Loader (Unused) S/N: A2407158835 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6908	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408043843 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6901	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT232024052200230 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX		2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044079 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket Usage: Not Available
6902	2024 AGT LRT23 Mini Compact Track Loader	6010	Asset located in: Lake Worth, TX
	(Unused) S/N: LRT23202408010005 C/W: Open Operator Station, Joystick Steering, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	6910	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044073 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6903	2024 AGT CH904 Wheel Loader	6011	·
	S/N: CH9042024L0618005 C/W: Open Operator Station, 38 in Bucket, 23X8.5-12 Tires Usage: Not Available Asset located in : Lake Worth, TX	6911	2024 FF Industrial FF18R Mini Excavator S/N: 2408069186 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available
6904	2007 Ditch Witch R300 Wheel Loader	6010	Asset located in: Lake Worth, TX
	S/N: CMW1D4XK70000069 C/W: Open Operator Station, Auxiliary Hydraulics, Manual Coupler, 36 in Bucket, 20x100-8 Tires Usage: Not Available Asset located in : Lake Worth, TX	6912	2024 Landhero LDH-KV16 Mini Excavator (Unused) S/N: Not Available C/W: 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, 15 in Digging Bucket, Manual Thumb Usage: Not Available
6905	2024 Digmaster DM200 Mini Excavator (Unused) S/N: DM24080305 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket Usage: Not Available	6913	Asset located in: Lake Worth, TX 2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515624 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6914	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515549 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6922	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423032738 C/W: Straight Travel Pedal, Tier 2, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb
6915	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515621		Usage: Ñot Åvailable Asset located in : Humble, TX
	C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6923	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423032626 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber
6916	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515538 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic		Tracks, 17 in Digging Bucket, Manual Thumb Usage: 66 Hr Asset located in : Lake Worth, TX
	Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6924	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423050691
6917	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515589 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic	6925	C/W: Enclosed Cab, 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket Usage: Not Available Asset located in : Lake Worth, TX
	Plumbing, Backfill Blade, 7 İn Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available		2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423105139
6918	Asset located in: Lake Worth, TX 2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515609 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic		C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
	Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Lake Worth, TX	6926	2024 FF Industrial FF-13 Mini Excavator (Unused)
6919	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515546 C/W: 2 ft 7 in Stick, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available		S/N: 423123854 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6927	2024 VICSEC VC13 Mini Excavator (Unused)
6920	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515626 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available	3727	S/N: VC13240617 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	6928	2024 FF Industrial FF-12 Mini Excavator
6921	2024 VICSEC VC15P Mini Excavator (Unused) S/N: VA15P240703 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Manual Quick Coupler, 17 in Digging Bucket, Manual Thumb Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: 423136819 C/W: 2024 US EPA Label, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6929	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136832 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX 2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136824 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic	6936	Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available	6937	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused)
6931	Asset located in: Lake Worth, TX 2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136840 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
6932	2024 BTTL ET12M-6 700718 Mini Excavator		Asset located in: Lake Worth, TX
	(Unused) S/N: ET12M-6 700718 C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6938	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
6933	2024 BTTL ET12M-6 Mini Excavator (Unused)		Asset located in: Lake Worth, TX
	S/N: ET12M-6700717 C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6939	Quantity of (56) 2024 Suihe SP10-S-56 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6934	Quantity of (5) 2024 Landhonor LHR-SG64 6 ft x 4 ft Livestock Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6935	Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6940	Quantity of (56) 2024 Suihe SP10-G-56 10 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6941	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6949	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
6942	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6950	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
6943	Quantity of (12) 2024 Landhonor LHR-SP07 7 ft Sheep Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6951	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6944	Quantity of (24) 2024 Landhonor LHR-SP07 7 ft Sheep Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
6945	Quantity of (4) Bundles of 10 Ft Livestock Panel S/N: Not Available Usage: Not Available	6952	Asset located in: Lake Worth, TX 2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused)
6946	Asset located in: Lake Worth, TX 2024 Industrias America R820 20 Ft Loading Ramp (Unused) S/N: R82020242517 Usage: Not Available Asset located in: Lake Worth, TX	S/N: Not Available C/W: THE PRODUCT IMAGES SH FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SH FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT.	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6947	20 ft Loading Ramp (Unused) S/N: Not Available C/W: 30,000 lb. Capacity Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6948	Asset located in: Lake Worth, TX 2024 Landhonor LHR-CSC10 Cattle Squeeze Chute (Unused) S/N: HL00009 Usage: Not Available Asset located in: Lake Worth, TX	6953	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6954	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6962	Quantity of (6) 2024 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available
6955	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX Quantity of (6) 2024 SUNTOP S207 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused)
6956	Asset located in: Lake Worth, TX 2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
6957	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: M12S224202 Usage: Not Available Asset located in: Lake Worth, TX	6964	·
6958	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6959	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: M12S225549 Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (3) 2024 Suihe NFG-20FC-3 20 ft Bi-Parting Farm Driveway Gate (Unused)
6960	Asset located in: Lake Worth, TX Quantity of (50) 12 ft Corral Livestock Panel S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6961	2024 SUNTOP S0720 Qty of (6) 20FT Bi- Parting Wrought Iron Driveway Gate (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6966	2024 Suihe NFG-20FGP-D 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6971	Quantity of (2) 2024 Suihe NG-14D -2 14 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (2) 2024 Suihe NG-14Eu-2 14 ft Bi- Parting Driveway Gate (Unused)
6967	2024 Suihe NFG-20FGP-E 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6973	S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (6) 2024 SUNTOP SO7020 20 ft x 7 ft Driveway Gate S/N: Not Available C/W: 20 ft x 7 ft Wrought Iron Bi Parting Driveway Gate Usage: Not Available Asset located in: Lake Worth, TX
6969	Quantity of (8) 2024 Suihe NG-20D-8 20 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (8) 2024 Suihe SG-20D-8 20 ft Bi- Parting Driveway Gate (Unused)	6974	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6970	S/N: Not Available C/W: Rectangle Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 Suihe SG 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6975	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6976	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6977	2024 SUNTOP S0610 Qty of (20) 10FT Portable Construction Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	6983	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		6984	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6985	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle
6978	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6	1	Usage: Not Available Asset located in : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6986	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		6987	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6988	Quantity of (30) 6 ft x 8 ft Site Fence (Unused)
6979	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
		6989	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		6990	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
6980	Quantity of (26) 2024 Suihe SF-D-26 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6991	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		6992	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6993	Quantity of (20) 10 ft x 7 ft Site Fence (Unused)
6981	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
6982	Quantity of (20) 8 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
6994	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6999	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX
		7000	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX
6995		7001 7002	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (24) 10 ft x 7 ft Galvanized Fencing
			(Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX
6996	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7003	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		7004	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6997	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7005	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
		7006	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Papels (21) Post's W
6998	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	/Connectors Usage: Not Available Notes: THE PRODUCT IMAGE FOR ILLUSTRATION PURPO MAY NOT BE AN EXACT RE THE ACTUAL PRODUCT.	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF

Lot #	Details	Lot #	Details
7007	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	7012	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7008	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	/Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7014	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7015 Quantity of (24) 2024 H 24P 10 ft x 7 ft Powder (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake N 7016 Quantity of (24) 2024 H 24P 10 ft x 7 ft Powder (Unused) S/N: Not Available Usage: Not Available	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing
7009	Quantity of (20) 2024 FENS FEN20 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: B44823 C/W: THE PRODUCT IMAGES SHOWN ARE		S/N: Not Available
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: Not Available
7010	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7017	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX
7011	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7018	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7019	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7020	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7030	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7021	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: One Rack	7031	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (21) 2024 SUNTOP S4200 200 ft x	
	Usage: Not Available Asset located in: Lake Worth, TX	7032	40 in Galvanized Farm Fencing (Unused)	
7022	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
7023	Quantity of (24) 2024 HUNTER PRO WLFT10-	1	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	
	24P 10 ft x 7 ft Powder Coated Fencing (Unused)		Asset located in: Lake Worth, TX	
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7033	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available	
7024	Quantity of (44) 7 ft 10 in x 7 ft Powder Coated Fencing S/N: Not Available Usage: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
7025	Asset located in: Lake Worth, TX Quantity of (2) Pallets of 78 In x 10 Ft Site Fence		\exists	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	S/N: Not Available C/W: Accessories		Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	7034	2024 SUNTOP S4200 Qty of (21) 200ft x 40in Galvanized Farm Fencing (Unused)	
7026	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
7027	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7035	2024 SUNTOP G500 500 ft x 7 ft Chain Link	
7028	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
7029	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	
	Asset located in. Lake Worth, 1 X	ı	Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7036	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7041	Quantity of (16) Fencing S/N: Not Available C/W: Braces. Rack Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (8) Fencing
7037	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	- / U+2	S/N: Not Available C/W: Braces Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7038	THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX 2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7043	Quantity of (4) Fencing S/N: Not Available C/W: Braces Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of Fencing S/N: Not Available C/W: 36 in. Silt Fence With Additional Wooden
7039	Quantity of (36) Rolls of Field Fence 47 In x 330 Ft Fencing (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX Quantity of Fencing S/N: Not Available Usage: 5 Hr		Stakes Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	<u> </u>	7045	2024 Agriquip GLHP100 100 ton Air/Hydraulic Shop Press (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7046	Quantity of (4) Portable Generator Set S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7056	Quantity of (3) Pallets of Portable Generator Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7057	Multiquip GAW-180H 3 kW Skid-Mounted Portable Generator Set S/N: 5682943 C/W: Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available
7047	Quantity of (2) Portable Generator Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7058	Asset located in: Lake Worth, TX 2020 Ingersoll Rand RS22N 115 cfm Skid- Mounted Electric Air Compressor S/N: CBV699949
7048	Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available		C/W: 3 Phase, 30 hp Motor, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 5 Hr Notes: . Asset located in: Lake Worth, TX
7049	Asset located in: Lake Worth, TX Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7059 	2020 Ingersoll Rand RS22N 114.6 cfm Skid- Mounted Electric Air Compressor S/N: CBV703202 C/W: 3 Phase, 30 hp Motor, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 7,397 Hr Notes: . Asset located in: Lake Worth, TX
7050	Quantity of (2) Dewalt DXGNR6500 Portable Generator Set S/N: Not Available C/W: 2021 US EPA Label, Generac 389 cc Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7060	2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor S/N: CBV713664 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 7,936 Hr Notes: .
7051	Quantity of (2) Generac GP8000E 8 kW Portable Generator Set S/N: Not Available C/W: 2023 US EPA Label, Generac 420 cc Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7061	Asset located in: Lake Worth, TX 2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor S/N: CBV710808 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 2,281 Hr
7052	Quantity of (3) Generac GP3600 3.6 kW Quantity of (1) Generac GP3500i Portable Generator Set		Notes: . Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Generac 212 cc Gasoline Engine, 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	7062	2024 Landhonor LHR-GAC60Y 60 Gallon 2- Stage Truck Mounted Air Compressor (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7053	Quantity of Ryobi 3400 Watt & Champion 3500 Watt Portable Generator Set S/N: Not Available C/W: Dual Fuel Engine, 120 V Receptacles, Gasoline Usage: Not Available Asset located in: Lake Worth, TX	7063	Iron Horse Electric 60 gal Shop Air Compressor S/N: Not Available C/W: 150 psi Working Pressure, 6 hp Motor Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7064	2024 Landhonor LHR-GAC60 Skid-Mounted 60 gal Air Compressor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7073	Mi-T-M 13.1 cfm Skid-Mounted Air Compressor S/N: 20175543 C/W: 100 psi Working Pressure, 2013 US EPA Label, Honda GX200 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7074	Jenny Skid-Mounted Air Compressor
7065	2024 Landhonor LHR-GAC40 Skid-Mounted 40 gal Air Compressor (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, THE PRODUCT IMAGES SHOWN ARE FOR		S/N: Not Available C/W: 2008 US EPA Label, Honda 1 Cylinder 270 cc Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available
	ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE		Asset located in: Lake Worth, TX
	ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7075	2024 Suihe PW Skid-Mounted Pressure Washer (Unused) S/N: Not Available
7066	Coltec Industries OSI370WNW41A Skid- Mounted Electric Air Compressor S/N: 94897		C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available
	C/W: 175 psi Working Pressure, 230/460 volts Usage: 2,363 Hr Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7067	Skid-Mounted Air Compressor		Asset located in: Lake Worth, TX
	S/N: 380091 C/W: 2013 US EPA Label, Kohler Command Pro 1 Cylinder 429 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7075A	Northstar Pressure Washer S/N: 4K1BP1625FF001307 C/W: Water Heater, 500 gal Water Supply, Hose, Spraine, Engine
7068	Skid-Mounted 30 gal Air Compressor S/N: Not Available]	Cylinder Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Predator 1 Cylinder 420 cc Gasoline Engine Usage: 88 Hr Asset located in : Lake Worth, TX	7076	Easy-Kleen Magnum 3600 Pressure Washer (Unused) S/N: 2440130
7069	Eagle 30 Gal Truck Mount Air Compressor S/N: Not Available		C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available
	Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
7070	PowerTrain 18.5 cfm 30 gal Air Compressor (Unused) S/N: Not Available C/W: 175 psi Working Pressure, Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7077	Easy-Kleen Magnum 3600 Pressure Washer (Unused) S/N: 243819 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Asset located in: Lake Worth, TX Easy-Kleen Magnum 3600 Pressure Washer
7071	PowerTrain 11.2 cfm 10 gal Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7078 	(Unused) S/N: 2440131 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available
7072	Quantity of (5) Electric Air Compressor S/N: Not Available C/W: 120V, (2) Goodyear 20 gal, (1) Goodyear 10 gal, (1) Campbell Hausfeld 6 gal, (1) Hyper Tough 6 gal Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7079	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243888 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7086	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244541 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7080	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244614 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7087	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243887 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7081	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244615 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available	7089 7090	Aladin 8430-C Pressure Washer S/N: Not Available C/W: Water Heater, Electric Operated Usage: 1,411 Hr Asset located in: Midland, TX All American 8357L Skid Mounted Pressure Washer (Inoperable)
7082	Asset located in: Lake Worth, TX Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244617 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		S/N: 105855 C/W: Water Heater, Kubota D1105 3 Cylinder Diesel Engine Usage: 1,058 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
7083	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244542 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine	7091	Landa PGDC5-3500 Pressure Washer S/N: 11100510101372 C/W: 3500 psi Rating, Water Heater, Honda GX630 Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Ávailable Asset located in : Lake Worth, TX	7092	2020 Hotsy 1075SSE Pressure Washer
7084	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243899 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available		S/N: 11100120168267 C/W: 3500 psi Rating, Water Heater, Hose, Spray Wand, Honda GX390 Gasoline Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 67 Hr Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7095	2016 Mi-T-M CW-3504-5MGH Pressure Washer S/N: Not Available
7085	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244616 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		C/W: 3500 psi Rating, Honda GX390 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		7096	2018 Mi-T-M CW25054MGH Pressure Washer S/N: 11041408 C/W: 2500 psi Rating, Honda GX390 Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7097	2017 Mi-T-M HSP-2503-0MMH Pressure Washer S/N: 15111154 C/W: 2500 psi Rating, Water Heater, Honda GX200 196 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7104	Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, Hose, Spray Wand, Briggs & Stratton CR950 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7098	·	7105	2019 Mi-T-M HSP-3504-3MGH Pressure Washer S/N: 15132271 C/W: 3500 psi Rating, Water Heater, Hose, Spray Wand, Honda GX390 Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine
7099	Asset located in: Corsicana, TX Simpson MS61219 Pressure Washer	1	Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 05235011741 C/W: 3400 psi Rating, Hose, Spray Wand, Simpson CRX225 1 Cylinder 224 cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7107	Landa PGDC5-3500 Pressure Washer S/N: 11100500101087 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton Vanguard 18 hp 570 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7108	2002 Pressure Washer S/N: 1P9HT1S2321293177 C/W: 3000 psi Rating, Water Heater, 500 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler Command Pro 2 Cylinder
7100	Simpson Pressure Washer S/N: Not Available C/W: 4000 psi Rating, Honda 1 Cylinder Gasoline Engine		Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 1,068 Hr Asset located in: Lake Worth, TX
	Usage: Not Āvailable Asset located in : Lake Worth, TX	7109	40 ft High Cube Office Storage Container
7101	Quantity of (4) Boxes of Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: KDCU5211968 C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED Ceiling Lights, Interior Outlets, forklift pockets Usage: Not Available Asset located in: Lake Worth, TX
7102	Quantity of (4) Simpson Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Honda GCV160 Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7110	20 ft Office Storage Container (Unused) S/N: SKYU2652356 C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED
7103	Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, Hose, Spray Wand, Briggs & Stratton CR950 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Ceiling Lights, Interior Outlets, forklift pockets Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
7111	2024 LEVE LE20 19 ft 5 in x 20 ft Expandable House (Unused) S/N: A0282 C/W: (2) Bedrooms w/, (1) Bathrooms, (1) Living Room Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7116	2024 Suihe GS2322 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7112	2024 Suihe GS2533 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7117	2024 Suihe M202010P Light Steel Carport (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7118	2024 Suihe M122009P Light Steel Carport
7113	2024 Suihe 2040P 40 ft x 20 ft Commercial Party Tent (Unused) S/N: Not Available C/W: (18) Removable Side Walls w/PVC Clear Windows, (2) Zipper Doors, 500 gsm PVC Coated Fabrics, Waterproof, Fire & UV Resistant, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7119	(Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX 2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused)
		_	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7114			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF	7120	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7120	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7115	2024 Suihe GS2119 21ft x 19ft Portable Metal Shed (Unused) S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7121	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

This catalog was created at December 11, 2024 01:25:48 AM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7122	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (200) 2024 Machpro S3048C 10 ft Corrugated PPGI Steel Panels (Unused) S/N: 2408070018 C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	7130	2024 Suihe S408020R-300gPE 80 ft x 40 ft x 20 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7124	Quantity of (200) 2024 Machpro S3048C 10 ft	1	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	7131	2024 Landhonor LHR-ST3085 85 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7125	2024 Suihe S5010023DP-750gPVC 100 ft x 50 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (4) Boxes - Builds (1) Storage Building Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7132	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Suihe S406423DP-610gPVC 64 ft x 40 f x 23 ft Storage Building (Unused) S/N: Not Available
7126	2024 Hills Industrial 805026 80 Ft x 50 Ft x 26 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Hills Industrial 504026 50 Ft x 40 Ft x 26		C/W: Quantity of (3) Boxes - Builds (1) Storage Building Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
, 12,	Ft Storage Building (Unused)		Asset located in: Lake Worth, TX
7128	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Hills Industrial 804024 80 Ft x 40 Ft x 24 Et Storage Building (Unused)	7133	3 2024 Hills Industrial 604024 60 Ft x 40 Ft x 2 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Suihe S308515R-300gPE 85 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available
7129	2024 Suihe S408023DP-610gPVC 80 ft x 40 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7135	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7142	2024 Hills Industrial 403022 40 Ft x 30 Ft x 22 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Suihe S304015R-300gPE 40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available
7136	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7137	2024 Suihe S306020DP-610gPVC 60 ft x 30 ft x 20 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7144	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7138	2024 Landhonor LHR-ST3040 40 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7145	t Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7139	2024 Hills Industrial 604024 60 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7146	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES
7140	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7141	2024 Hills Industrial 603022 60 Ft x 30 Ft x 22 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
7147	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7154	2024 Suihe C404013-300gPE x 13 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
7149	Pole Barn Package 16 ft x 24 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: 2 x 6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX	-7155	Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWI	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7150	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	C/W: 2 x 6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX	7157	2024 Suihe C2040-300gPE 20 ft x 40 ft Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
7151	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused) S/N: Not Available C/W: 2 x 6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
7152	Asset located in: Lake Worth, TX 16 ft x 24 ft x 40 ft Pole Barn Package Storage Building (Unused) S/N: Not Available C/W: 2x6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX		2024 Suihe C2040-300gPE 20 ft x 40 ft Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
7153	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7158	2024 Suihe C2020-300gPE 20 ft x 20 ft Container Shelter Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	SHOWN ARE ES ONLY AND RESENTATION OF S SHOWN ARE ES ONLY AND	Quantity of Tool Box S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7165	UWS TBC60N Tool Box
7159	2024 Suihe C504017DR-610gPVC 50 ft x 40 ft x 17 ft Container Shelter Storage Canopy (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: Not Available C/W: 60 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7160	Quantity of (2) Conveyor Belts - Fits Tractor S/N: Not Available C/W: (1) 55 In, (1) 42 In; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7166	Quantity of (3) Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
7161	Quantity of (3) Uline Tool Cabinet S/N: Not Available C/W: (1) 42 In 11 Drawer, (1) 29 In 5 Drawer, (1) 29 In 7 Drawer; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7167	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Oughtity of (2) Tool Poy
	Notes: . Asset located in: Lake Worth, TX		Quantity of (3) Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7162	2024 Suihe NWB-H35DS-7 7 ft 35-Drawer Tool Cabinet (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7168	Quantity of (3) Truck Toolboxes S/N: Not Available
	Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX
7163	18 In x 24 In Tool Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		ASSEL IOCALCU III. LANE WOLLII, TA

Lot #	Details	Lot #	Details
7169	2024 Suihe NWB-30DS-10 10 ft 30-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7175	Can Industrial 10 ft 40 Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7176	2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7170	2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7177	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7178	2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused)
7171	2024 Suihe NWB-15DR-2-10 10 ft 15-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7179	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30-
7172	2024 Suihe NWB-25DB-10 10 ft 25-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7180 2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drav Workbench (Unused) S/N: Not Available	
7173	Asset located in: Lake Worth, TX 2024 Suihe NWB-H40DB-10 10 ft 40-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7181	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7182	2024 Suihe NWB-H18DB-7 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7189	Yukon 46 In 9 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7183	2024 Suihe NWB-20DS-7 7 ft 20-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7191	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7192	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7184	2024 Suihe NWB-H18DR-7 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7193	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		7194	Quantity of (2) Milwaukee 40 in 6-Drawer Workbench S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7185	Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7195	Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		7196	Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7187	6 ft 7 in Workbench S/N: Not Available C/W: 4 doors, 16 drawers Usage: Not Available Asset located in: Lake Worth, TX	7197	Milwaukee 40 In 5 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7188	U. S. General 72 In 18 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Addet located III. Lake Worth, TA

Lot #	Details	Lot #	Details	
7198	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7208	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7199	Quantity of (3) U. S. General 30 In Tech Carts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7209	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7200	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7210	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7201	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7211	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7202	Asset located in: Lake Worth, TX U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7212 7213	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers WB-90-243 7 ft 6 in Workbench	
7203	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S.General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING		S/N: Not Available Usage: Not Available Asset located in : Lak	
7204	Usage: Not Available Asset located in: Lake Worth, TX U. S. General 44 in 13-Drawer Workbench S/N: Not Available		Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7215	2024 Kit Containers WB-60-190 5 ft Workbench S/N: Not Available Usage: Not Available	
7205	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S.General 34 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7216	Asset located in: Lake Worth, TX 2024 Kit Containers WB-60-190 26 In x 60 In Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7206	Quantity of (4) U. S. General Service Carts S/N: Not Available C/W: (3) 4 Drawer, (1) 5 Drawer; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7217	Asset located in: Lake Worth, TX 2024 Kit Containers ST-57 29 In x 57.5 In Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7207	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7218	2024 Kit Containers ST-57 4 ft 10 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7220	Quantity of (4) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX	7229	2024 Kit Containers 1.5YFT-SDH Skid Steer Dump Hopper (Unused) S/N: B21J1206 Usage: Not Available
7221	2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: B12I407 Usage: Not Available Asset located in: Lake Worth, TX	7230	Asset located in: Lake Worth, TX 2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High
7222	2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: B191402	7231	Usage: Not Available Asset located in: Lake Worth, TX 2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self-
	Usage: Not Available Asset located in : Lake Worth, TX		Dumping Hopper (Unused)
7223	Quantity of (5) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	7232	Quantity of (5) 4 ft 6 in Self-Dumping Hopper S/N: Not Available
7224	Quantity of (4) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING	7233	C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX		Quantity of (4) 4 ft 6 in Self-Dumping Hopper
7225	Quantity of (2) 2024 Suihe N-1CY -2 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		7234	Quantity of (2) 2024 Suihe N-1.5CY-2 1.5 cyd Self-Dumping Hopper (Unused) S/N: Not Available
			C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7226	Asset located in: Lake Worth, TX 2024 Kit Containers 2YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available		Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONLY
	C/W: 5 ft 6 in Long x 4 ft 1 in Wide x 3 ft 10 in High	7005	Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7235	25 ft Loading Ramp (Unused) S/N: Not Available
7227	2024 Kit Containers 2YFT-SDH Skid Steer		Usage: Not Available Asset located in: Humble, TX
	Dump Hopper (Unused) S/N: B21J1204 Usage: Not Available Asset located in: Lake Worth, TX	Pedestal Crane S/N: Not Available C/W: JLC 1 Ton Electric EQUIPMENT-FROM-US-A Usage: Not Available	S/N: Not Available
7228	2024 Kit Containers 2YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Lake Worth, TX		C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7237	Quantity of (5) Abell-Howe 1Ton Electric Shop Pedestal Crane S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7248	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7249	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft
7238	Quantity of (5) 2020 Abell-Howe 1 Ton Electric Shop Pedestal Cranes S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7250	Quantity of (3) Bundles of Hex Netting Mazel Co 22 S/N: Not Available Usage: Not Available
7240	Quantity of (2) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7251	Asset located in: Lake Worth, TX Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black C40 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7241	Quantity of (3) Bundles Of Standard Beam 4" 7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (6) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available
7242	Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44" S/N: Not Available	7253	Asset located in: Lake Worth, TX Quantity of (5) Bundles of Panels 8 in x 34 in x
	sage: Not Available sset located in : Lake Worth, TX		12 ft S/N: Not Available
7243	Quantity of (3) Bundles of Standard Beam 4" 7.7 A36/572-50 44'		C/W: One Stack Usage: Not Available Asset located in : Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7254	12 ft
7244	Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44 ft S/N: Not Available		S/N: Not Available C/W: One Stack Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7255	Quantity of (2) Bundles of Horse Fence Xtreme Black 12.5-12.5 2 in x 48 in x 200 ft
7245	Quantity of (3) Square Bar 5/8 A-36 20' S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
7246	Asset located in: Lake Worth, TX Quantity of (1) Bundle of 4 In x 36 Ft Wide Flange Beam S/N: Not Available Usage: Not Available	7256	Quantity of (3) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7247	Asset located in: Lake Worth, TX Quantity of (1) Bundle of Wide Flange Beam 10 in 15.0 A992/A572-50 40 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7257	Quantity of (3) Bundles of Horse Fence Xtreme Black 12.5-12.5 2 in x 48 in x 200 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7258	Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7270	Quantity of Bundles of Chainlink Xtreme NC 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7259	Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7271	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7260	Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7272	Quantity of (4) Bundles of Horse Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7261	Quantity of (2) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7273	Quantity of (2) Bundles of 9 Gauge 20 in 48 in, 50 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7262	Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7274	Quantity of Magnum 3 in 16d Nails S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7263	Quantity of (1) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 96" 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7275	Quantity of Horse Fence Xtreme Black S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7265	Quantity of (1) Bundle Of Sheep/Goat Fence 10- 12.5 4 In x 48 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7276	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7266	Quantity of (2) Bundles of Chainlink Xtreme 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7277	Quantity of (2) Bundles of Chainlink Xtreme Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7267	Quantity of (2) Bundles of Chainlink Xtreme NC 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7278	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black C40 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7268	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7279	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7269	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7280	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7281	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7292	Quantity of (2) Bundles of Mazel Hex Netting 2" x 60" x 150' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7282	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7293	Quantity of (2) Bundles of EZ Rol Chainlink PVC 1 1/2" 60" 50' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7283	Quantity of (2) Bundles of Mazel 2 in x 36 in x 150 ft Hex Netting S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7294	Quantity of (1) Bundle Of Game Fence Stay Lock 12.5-12.5 6 In x 96 In x 330 Ft Fencing S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7284	Quantity of (2) Bundles of Welded Utility Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7295	Quantity of (1) Bundle of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7285	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7296	Quantity of (2) Bundles of Chainlink Fence (1) C3 11.5 2-3/8" 72" 50ft KT (1) C3 11.5 2-3/8" 48" 50ft KK S/N: Not Available
7286	Quantity of (3) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available	7297	Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Bundles of Game Fence Stay Lock C3 12.5-12.5 6
7287	Asset located in: Lake Worth, TX Quantity of (2) Bundles of Welded Utility Fence		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7298	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5
7288	Quantity of (4) Bundles of Horse Fence S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
7289	Asset located in: Lake Worth, TX Quantity of (4) Bundles of Galvanized Welded Fence 1 in x2 in 48 in 100 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7299	Quantity of (3) Bundles of Fencing S/N: Not Available C/W: (2) Fixed Knot Xtreme Black 96 In x 330 Ft, (1) Game Fixed Knot Stay Lock 96 In x 330 Ft Usage: Not Available Asset located in: Lake Worth, TX
7290	Bundle of Galvanized Welded Fence 2 in x4 in 60 in 100 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7300	Quantity of (3) Bundles of Game Fence Stay Lock C3 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7291	Quantity of (3) Bundles of Galvanized Welded Fence 1"x2" 48" 100' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7301	Quantity of (1) Bundle of Game Fence Stay Lock 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7302	Quantity of High-Tensile Galvanized 15.5 Gauge Barbed Wire S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7312	Enerpac MSFP10 Hydraulic Pump S/N: P392 C/W: Sheet Metal Pieces, (2) 10 Ton Jack Stands; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
7303	Quantity of Magnum 3 in 16d Nails S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7314	Quantity of (2) Pallets of Assorted fittings and hoses S/N: Not Available Usage: Not Available	
7304	Quantity of (2) Pallets of Magnum 3" 16d Nails S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	
7305	Quantity of (2) Pallets of 3 1/2" 16d Bright		Asset located in: McAlester, OK	
	Common Nails S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7315	Quantity of (5) Spy Pipeline Detectors & (1) Recorder S/N: Not Available	
7306	Quantity of (2) Bundles of Barbed Wire High Tensile C3 15.5 8 Rod S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		ITEM AT OFFSITE LOCATION MUS PICKED UP BY DECEMBER 31ST O SUBJECT TO 3RD PARTY STORAG FORKLIFT ASSISTANCE WILL NOT	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
7307	Quantity of Conveyor Belt		Asset located in: McAlester, OK	
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX	7316	Quantity of Assorted Construction parts S/N: Not Available C/W: Hydraulic Hoses, Tool Box, Caution Tape Heavy Duty Rack, Sand Bags, and Misc Parts	
7308	Quantity of (4) Tool Carts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: LOADOUT BY APPOINTMEN ITEM AT OFFSITE LOCATION MUS' PICKED UP BY DECEMBER 31ST OF SUBJECT TO 3RD PARTY STORAGE FORKLIFT ASSISTANCE WILL NOT	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE
7309	Quantity of (4) Pallets of Eye Wash Stations & Spill Kits		AVAILABLE Asset located in: McAlester, OK	
	S/N: Not Available C/W: (1) Pallet of Absorbent Socks, (1) Pallet of Spill Kits, (2) Pallets of Eye Wash Stations; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		Quantity of (4) Pro-Start 25 ft Booster Cables S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7317A	•	
7310	Electric Pump S/N: Not Available C/W: MT 1/3 Hp Electric Motor, Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING		S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available	7317B	2023 Zetech Hydraulic drive motor	
7311	Asset located in: Lake Worth, TX Sipco Hydraulic Drive Notor S/N: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	
	C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING		Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	7318	General EP8 Manhole Blower S/N: 33313 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7319	Quantity of (2) Discharge/Suction Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7327	2015 Wanco WTMMB Solar Message Board S/N: 5F12S161XF10005003 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available
7320	Quantity of (4) Pallets of 5 In Water Hose	7328	Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		2012 Solar Signal Message Board S/N: 1B9ST1012CL657441 C/W: 6 Lamps, Solar Powered, Hydraulic Raise
7321	Quantity of Hose S/N: Not Available C/W: 3 in. Discharge		and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	7329	2012 HORIZON SIGNAL TECH SQ3TS Traffic Signal S/N: 1B9ST1010CL657471 Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Laborna, OK	7330	2021 Wanco WTMMB Solar Arrow Board S/N: 5F12S1614M005001
7322	S/N: Not Available C/W: 2 in., 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX
		7331	2016 Wanco WTSP Solar Arrow Board S/N: 5F11S1016G1006322 C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Humble, TX
7000	Asset located in: Lahoma, OK	7332	2016 Wanco WTSP Solar Arrow Board
7323	Quantity of Hose S/N: Not Available C/W: 2 in. Discharge Hose Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST		S/N: 5F11S1016G1006319 C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE		Asset located in: Humble, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7333	2015 Wanco WTMMB Solar Arrow Board S/N: 5F12S161XF1000503 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Lunette Ring Usage: Not Available
7324	Asset located in: Lahoma, OK Oughtity of Water Hann		Asset located in: Lake Worth, TX
7324	Quantity of Water Hose S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7334	Truck Mount Arrow Board S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7335	Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available
7326	Asset located in: Corsicana, TX 2015 Wanco WTMMB Solar Message Board S/N: 5F12S1611F1000499		C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX
	C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Lunette Ring Usage: Not Available Asset located in: Lake Worth, TX	7336	Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7337	Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	7347	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7338	Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available	7348 	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX Quantity of (250) 2024 Suihe TC-250 Traffic
7339	Asset located in: Lake Worth, TX Quantity of (50) Traffic Barrier S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7042	Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7340	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7341	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7350	Asset located in: Lake Worth, TX Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7342	Quantity of (250) 2024 HUNTER PRO C-75 Traffic Cones Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7343	Quantity of (250) 2024 HUNTER PRO C-75 Traffic Cones Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7351	Asset located in: Lake Worth, TX 2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7344	Quantity of (250) 2024 Agriquip GL28TC Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7352	2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7353	Quantity of (100) 2024 HUNTER PRO RB-100 Traffic Delineators & Bases (Unused) S/N: Not Available
7345	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available	7354	C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX Quantity of (100) 2024 HUNTER PRO RB-100
7346	Asset located in: Lake Worth, TX Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		Traffic Delineators & Bases (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7355	Quantity of (130) Traffic Barrels S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7364	2000 gal Steel Diesel Fuel Tank S/N: ST5384 C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7356	Quantity of (13) 7 Ft x 4 Ft Crowd Control Barriers		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7365	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000364 C/W: Spill Containment Usage: Not Available
7357	2008 Milstead 4000 gal Skid Mounted Steel Fuel Tank		Asset located in: Lake Worth, TX
	S/N: 1818-C881958 Usage: Not Available Asset located in : Lake Worth, TX	7366	1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000427
7358	2024 AM Tank 2300N 2376 gal Skid Mounted		C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
	Steel Fuel Tank (Unused) S/N: 82443 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7367	2000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORP2000468 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
7359	2024 AM Tank 2300N 2376 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82442 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available	7368	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000343 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7369	1000 gal Skid Mounted Steel Single Wall Fuel Tank
7360	2024 4-Fuel.com 4F2330 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005579 C/W: 120V Pump, 13 ft Hose, Fuel Meter, Auto		S/N: ORT1000313 C/W: Spill Containment Usage: Not Available Asset located in : Lake Worth, TX
	Nozzle, Spill Containment Usage: Not Available Asset located in : Lake Worth, TX	7370	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000310 C/W: Spill Containment
7361	2024 4-Fuel.com 4F2330 Gal Skid Mounted Diesel Fuel Tank (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
7362	S/N: 000005580 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX 2024 4-Fuel.com 4F1100 Gal Skid Mounted	7371	2000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT2000127 C/W: Spill Containment Usage: Not Available
7302	Diesel Fuel Tank (Unused) S/N: 000005581 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available	7372	Asset located in: Lake Worth, TX 1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000350 C/W: Spill Containment
	Asset located in: Lake Worth, TX	4	Usage: Not Available Asset located in : Lake Worth, TX
7363	2000 gal Steel Gasoline Fuel Tank S/N: ST5376 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7373	2024 AM Tank 800 838 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82445 C/W: 120 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7374	2024 AM Tank 800 838 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82444 C/W: 120 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available	7384	Morrison Bros Co. FTBDS-0500 Skid Mounted Steel Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	7385	300 gal Steel Fuel Tank (Unused) S/N: Not Available
7375	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005582 C/W: 120V pump, 13 ft hose, fuel meter, auto	7386	C/W: 12 V Transfer Pump Usage: Not Available Asset located in: Lake Worth, TX
	nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX		Wen Industries Diesel Buggy Portable Steel Fuel Tank S/N: Not Available
7376	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005583		C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX	7387	2024 AM Tank 116 gal Portable Poly Tank (Unused) S/N: 57066L C/W: 12 V Transfer Pump, 13 ft Hose,
7377	750 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump		Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX		2024 AM Tank 116 gal Portable Poly Tank (Unused)
7378	2024 AM Tank 600 655 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82446 C/W: 12 V Transfer Pump, Fuel Meter,		S/N: 57067L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Lake Worth, TX
	Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7389 2024 AM Tank 116 116 gal Portab Tank (Unused) S/N: 57068L	2024 AM Tank 116 116 gal Portable Poly Fuel
7379	2024 AM Tank 600 655 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82447		S/N: 57068L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle
	C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment		Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7390	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused)
7380	500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005289 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 000005586 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks Usage: Not Available Asset located in: Lake Worth, TX
7381	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000332 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7391	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005584 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks
7382	500 gal Skid Mounted Steel Fuel Tank		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: ORT5005280 Usage: Not Available Asset located in : Lake Worth, TX	7392	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused)
7383	500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005362 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 000005585 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks Usage: Not Available Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
7393	2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX 2024 Agriquip GLDP480 116 gal Portable Poly	7398	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: DEEZEE tool box; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
/39 4	Fuel Tank (Unused)		Asset located in: Corsicana, TX
	S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7399	DeeZee 92 gal Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
7395	2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT	7400	DeeZee 92 gal Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Midland, TX
	IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7401	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7396	2022 Teran TDT116GL 116 gal Fuel Tank (Unused) S/N: 46570L C/W: Polyethylene tank for diesel fuel transport equipped with a fuel transfer unit, 116 gal with 12V Pump (12GPM), 13ft Hose, Auto-Nozzle, Top Covering Lid. Usage: Not Available	7402	Asset located in: Midland, TX Weather Guard 92 gal Steel Diesel Fuel Tank
			S/N: 1915613344 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
7397	Asset located in: Lake Worth, TX Quantity of (2) 100 gal Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7403 7404	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX DeeZee 92 gal Portable Steel Diesel Fuel Tank
			S/N: Not Available C/W: 12 V Transfer Pump, 11 ft Hose Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
		7405	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX

Lot #	Details	Lot #	Details
7406	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7411	Steel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7407	407 Quantity of (7) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	7412 7413	2024 AM Tank 58 gal Portable Poly Tank (Unused) S/N: 57172A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX 2024 AM Tank 58 58 gal Portable Poly Fuel
7408	THESE Asset located in: Corsicana, TX Quantity of (3) Steel Diesel Fuel Tank S/N: Not Available		Tank (Unused) S/N: 57170A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	7414	Asset located in: Lake Worth, TX 2024 AM Tank 58 gal Portable Poly Tank (Unused) S/N: 57171A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
7409	THESE Asset located in: Corsicana, TX Quantity of (2) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7415	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005593 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7416	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005591 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
7410	Quantity of Steel Truck Bed Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7417	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005592 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
		7418	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005590 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7419	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005589 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	7429	2000 gal Steel Oil Tank S/N: ST5383 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7430	2000 gal Steel Coolant Tank	
7420	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005588 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle		S/N: ST5374 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, EQUIPMENT-FROM US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	7431	300 gal Steel Windshield Wash Tank	
7421	2013 Transcube 30TCG 792 gal Skid Mounted Steel Fuel Tank S/N: D871188 C/W: 12 V Transfer Pump Usage: Not Available Notes: .		S/N: ST5329 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, EQUIPMENT-FROM US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7432	2024 AM Tank 29 gal Portable Poly NH3 Tank	
7422	2024 AM Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 15160E		(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TY	
	C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	7433	Portable Poly NH3 Tank (Unused) S/N: Not Available	
	Asset located in: Lake Worth, TX			
7423	2024 AM Tank 29 gal Portable Poly Fuel Tank (Unused)		Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: 15158E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	7434	7434 2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15159E	(Unused)
7404	Asset located in: Lake Worth, TX	-	Automatic Shut-Off Nozzle	
7424	2016 Transcube 20TCG 528 gal Skid Mounted Steel Fuel Tank		Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: A61281755 C/W: 12 V Transfer Pump Usage: Not Available Notes : . Asset located in : Lake Worth, TX	7435 2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15157E C/W: 12 V Transfer Pump, 10 ft Hose,	2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15157E	
7426	Quantity of (3) 100 Gal Transfer Fuel Tanks		Usage: Not Available	
	S/N: Not Available C/W: (2) L-Shaped, (1) Rectangle Usage: Not Available	7436	Asset located in: Lake Worth, TX Ace Roto-Mold 300 gal Poly Holding Tank S/N: LP00300BHSS	
7407	Asset located in: Lake Worth, TX	-	Usage: Not Available Asset located in: Lake Worth, TX	
7427	Skid Mounted Steel Fuel Tank S/N: Not Available Usage: Not Available		Asset located III. Lake Worth, 1A	
7400	Asset located in: Humble, TX	4		
7428	2000 gal Steel Gasoline Tank S/N: ST5369 C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details	
7437	Steel Hydraulic Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7445	Quantity of (2) Fuel Boss 12 V DC Fuel Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		7446	Quantity of (2) Fuel Boss 12 v Fuel Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		7447	Fuel Boss 1 in Hose Reel W/ 110 V Pump, 50 ft. Deliver Hose Fuel Pump	
7439	Asset located in: Corsicana, TX 2024 Agriquip GLDP20 Fuel Pump (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		S/N: Not Available C/W: Fuel Pump Usage: Not Available Asset located in : Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7448	2012 IMT 30/217 Truck Mounted Boom S/N: 771397 C/W: 54 ft reach, 5 section knuckle boom, 3 pallets of hydraulic fluid tank, stabilizers, rear bumper	
7440	2024 GLDP20 12V Diesel Transfer Fuel Pump (Unused)		Usage: Not Available Asset located in : Lake Worth, TX	
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	7449	Knapheide 8 Ft Flatbed S/N: Not Available Usage: Not Available	
7441	2024 Agriquip GLDP20 Fuel Pump (Unused)	-	Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7450	Caseco MM225 11 Ft Service Body S/N: 70628170 C/W: Auto Crane 6406H 6000 LB Crane Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7460	L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump Usage: Not Available Asset located in: Lake Worth, TX	
7442	Quantity of (2) 2024 Agriquip GLGP20 Fuel Pump (Unused) S/N: Not Available C/W: Hose, Nozzle THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7461	L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump Usage: Not Available Asset located in: Lake Worth, TX	
		7462	Quantity of (25) Hendrickson S-34446-L Brake Chambers S/N: Not Available	
7443	2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused) S/N: Not Available		C/W: One Pallet Usage: Not Available Asset located in : Lake Worth, TX	C/W: One Pallet Usage: Not Available
	C/W: 49 ft Hose Reel, 12v DC, 10 gpm Usage: Not Available Asset located in: Lake Worth, TX	7463	Quantity of (2) Pallets of Trailer sub frame complete assembly S/N: 2017045964	
7444	2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused) S/N: Not Available		C/W: Steel Usage: Not Available Asset located in : Lake Worth, TX	
	C/W: 49 ft Hose Reel, 12v DC, 10 gpm Usage: Not Available Asset located in: Lake Worth, TX	7464	Quantity of (4) Freightliner Fuel Tanks S/N: Not Available C/W: 100 gal Aluminum Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7465	Quantity of (4) Freightliner Fuel Tanks; (2) Tanks-100gal, (1)-120gal, (1) Unknown - Fits Truck S/N: Not Available	7480	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 259 Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Aluminum Usage: Not Available Asset located in : Lake Worth, TX	7481	ProTech Aluminum Headache Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING
7466	Quantity of Truck Parts S/N: Not Available C/W: Mud Flaps, Belts, Filter, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7482	Usage: Not Available Notes: Asset located in: Lake Worth, TX Truck Hood S/N: Not Available
7467	Asset located in: Lake Worth, TX HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7484	C/W: Fiberglass, To Fit Peterbilt Usage: Not Available Asset located in: Lake Worth, TX Peterbilt Truck Cab
7468	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available		S/N: 67741 Usage: Not Available Asset located in: Lake Worth, TX
7469	Asset located in: Lake Worth, TX HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7485	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7473	HMT Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7486	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB W NOT BE ABLE TO ASSIST WITH LOADING
7474	Quantity of (4) Seats & (2) Consoles S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THESE Asset located in: Corsicana, TX Cat Cab - Fits Cat D6
7475	Quantity of Truck Toolbox & Ladder Rack S/N: Not Available C/W: Rawson Koenig tool box Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
7476	Quantity of (2) Pallets of Dock Bumper (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7477	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 256 Usage: Not Available Asset located in: Lake Worth, TX	7487	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7478	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 260 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
7479	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 255 Usage: Not Available Asset located in : Lake Worth, TX		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7488	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7495	Cat To Fit CAT 740B Truck Dump Body S/N: Not Available C/W: Lift Cylinders, Tailgate Usage: Not Available Asset located in: Lake Worth, TX
		7497	Quantity of (2) Transmission S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7489	Enclosed Cab & ROPS Structure - Fits Cat D6R		Asset located in: Corsicana, TX
	/ D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7498	Quantity of (2) Transmission S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
		7400	Asset located in: Corsicana, TX
		7499	2012 Hanco 20 ft Flatbed S/N: 107585
	Asset located in: Corsicana, TX		C/W: 2 storage boxes Usage: Not Available
7490	/ D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Asset located in: Lake Worth, TX
		7500	Cat Radiator - Fits Truck S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
 7491	Asset located in: Corsicana, TX Cat Truck Dump Body	_	Asset located in: Corsicana, TX
	S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length Usage: Not Available Asset located in: Lake Worth, TX	7501	Quantity of Quarter Fenders S/N: 50567 Usage: Not Available Asset located in: Humble, TX
7492	Cat Truck Dump Body S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length Usage: Not Available Asset located in: Lake Worth, TX	7502	Truck Hood S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7402		7503	Thermaflow Wet Kit
7493	Cat To Fit CAT 745 Truck Dump Body S/N: Not Available Usage: Not Available Asset Joseph January Description		S/N: Not Available C/W: Hoses, PTO, One Pallet Usage: Not Available
7404	Asset located in: Lake Worth, TX	7504	Asset located in: Lake Worth, TX Oughtity of (16) 22 5 Aluminum Pime
7494	John Deere To Fit Deere 410E Truck Dump Body S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7504	Quantity of (16) 22.5 Aluminum Rims S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7505	Quantity of (27) Brake chambers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7517	Quantity of (2) Air ride seats S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7506	Quantity of (2) Paccar 75 &100 gal 24.5 in dia Fuel Tanks (Unused) S/N: K424-0457N0102K075 Usage: Not Available Asset located in: Lake Worth, TX	7526	Quantity of (6) Truck Toolboxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
7507	Volvo D13H Engine S/N: Not Available C/W: 6 Cylinder 425 hp Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	7527	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Truck Toolbox
7508	Quantity of (6) 19.5 steel rims (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
7509	Quantity of (2) Aluminum Fuel Tanks - Fits Freightliner Cascadia		SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	S/N: Not Available C/W: (1) 150 Gallon & (1) 125 Gallon Usage: Not Available Asset located in : Lake Worth, TX	7528	Quantity of (3) Truck Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7510	Detroit DD15AT Engine S/N: Not Available C/W: 6 Cylinder 505 hp 14.8 L Diesel Engine Usage: Not Available		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX
7511	Quantity of (12) 22.5 Rims S/N: Not Available C/W: (9) Aluminum, (3) Steel, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7529	Truck Toolbox S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7512	Quantity of (12) 24.5 In Steel Rims S/N: Not Available C/W: One Pallet Usage: Not Available		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Asset located in: Lake Worth, TX	7530	Quantity of (3) Truck Tool Boxes
7513	Quantity of (16) 22.5 In Aluminum Rims S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
7515	International DT466 Engine with Spicer		SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Transmission S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7531	Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7516	Truck Hood S/N: Not Available C/W: To Fit Peterbilt 387 Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7532	Merritt Saddle Box Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7575	Quantity of Truck Fuel Tanks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7533	Quantity of (2) Merritt Saddle Box Truck Tractor Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7576	Wet Kit Pump and Hydraulic Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7534	Asset located in: Corsicana, TX Quantity of (2) ProTech Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7577	Water Pump Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7557	Truck Flatbed Body S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7578	Truck Blower Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7573	Asset located in: Corsicana, TX Synder Tank Corp Truck Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7579 7580	Drive Axle S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 4.10 Axle S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7574	Quantity of (2) CNG Fuel Tanks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
		7592	Trailing Tag Axle S/N: Not Available C/W: Air Ride Suspension, 11R22.5, Aluminum Rims Usage: Not Available Asset located in: Lake Worth, TX
		7593	Cat 3306 Engine S/N: 08Z32520 C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7594	Quantity of (6) PowerTrain PT240 Engine S/N: Not Available C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7604	BMW Engine S/N: Not Available C/W: 6 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
7595	Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available C/W: Gasoline Engine		SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7605 -	19 In x 71 In Loading Ramps S/N: Not Available Usage: Not Available
7596	Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7606	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length
7597	Quantity of (6) PowerTrain PTG2500XCS Engine (Unused)		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7607	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available
7598	Quantity of (6) PTTP300 Engine S/N: Not Available		C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX	7608	Quantity of (4) Salvation Trailers (4)Heavy Du Metal Trailer Ramps (Unused)
7599	Quantity of (6) PTWP400 Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available		S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX
7600	Asset located in: Lake Worth, TX Detroit 50435001 DD 453 Engine S/N: 4D0131900 C/W: 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (4) Salvation Trailers (4) Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX
7601	Isuzu Engine S/N: Not Available C/W: 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	7610	Quantity of (4) Salvation Trailers (4) Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX
7602	1996 Cat 3406E Engine S/N: 5EK38572 C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	7611	Quantity of (3) Mercury Boat Engine S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7603	Cummins N14 Engine S/N: 11849308 C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7612	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7616 	Quantity of hydraulic hoses Hydraulic Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of (9) 11R24.5 Tires
7613	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	7618 7619	S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX Alliance 700/40-22.5 Flotation Tire S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) 480/80R42 Tires S/N: Not Available
7614	THESE Asset located in: Corsicana, TX		C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX
7614	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	7620	Quantity of (2) 1300x530x508 Tires S/N: Not Available C/W: Some Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX
		7621	Quantity of (2) Hubs & Tires S/N: Not Available C/W: 18x8.50x10 Usage: Not Available Asset located in: Lake Worth, TX
7615	THESE Asset located in: Corsicana, TX Quantity of Cat Hydraulic Blade Lift Cylinders -	7622	Quantity of John Bean Tire Balancer & Tire Changer S/N: Not Available Usage: Not Available
	Fits Cat D6R/D6T S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7623 7624	Quantity of John Bean Tire Balancer & Tire Changer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (32) 235x80x16 10 Ply Radial
			Trailer Tires on Dial Wheels (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7625	Quantity of (48) 205x75x15 Radial Tires & 5 Lug Wheels (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7636	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042601H C/W: 110V, 2 HP Electric Motor, Bead Blaster System Usage: Not Available Asset located in: Humble, TX	
7626 7627	Quantity of (4) 6-PLY RADIAL TIRE 5 ON 5 SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) 235/80R16 10-PLY RADIAL	7637	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
7027	TRAILQUEST 16" 8-HOLE SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX	7638	Asset located in: Lake Worth, TX 2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
7628	Quantity of (2) Armour 11.00-16 Tires S/N: Not Available C/W: All Tires with Wheels, EQUIPMENT-FROM- WATKINS-CONSTRUCTION		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		7639 2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
7629	2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND			
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7640	640 2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
7630	2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF			Usage: Not Available
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Cuda H20-4860 Parts Washer - Fits CUDA H20- 4860 S/N: 10434450-100210	
7631	Quantity of (2) 2020 Weaver W-898XS Semi- Automatic Tire Changer		Usage: Not Available Asset located in : Midland, TX	
	S/N: 820052876/820052872 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7642	Cuda H20-4860 Parts Washer - Fits CUDA H20- 4860 S/N: 10434450-100209 Usage: Not Available Asset located in: Midland, TX	
7635	Quantity of (2) Weaver W-898XS Semi Automatic Tire Changer S/N: 820052875/820052871 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7643	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050641 Usage: Not Available Asset located in: Lake Worth, TX	

	Details	Lot #	Details
7644	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050639 Usage: Not Available Asset located in: Lake Worth, TX	7652 7653	Quantity of (2) 2020 Weaver F12N300BBL 12000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
7645	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050640 Usage: Not Available		Notes: . Asset located in: Lake Worth, TX Transmission Stand
7646	Asset located in: Lake Worth, TX ARI Hetra HDML8 Electric 150000 Lbs Vehicle		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
	Lift S/N: 01050638 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7647	2024 Agriquip GLTP4500 10000 lb Two-Post	Ī	Asset located in: Corsicana, TX
	Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7654	Graco Grease Injection Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7648	2024 Agriquip GLTP4500 10000 lb Two-Post		Asset located in: Corsicana, TX
	Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7655	Quantity of (3) Bolt Bin S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7656	Greenlee 24 In x 48 In Job Site Box
7649	Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX	7657	Greenlee 24 In x 48 In Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7650	Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts	7659	2024 Landhero UBP-25-60 Universal Bucket
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7658	Pin (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
10000 L S/N: No C/W: 2 I RECYCL	Quantity of (5) 2020 Weaver 10N000DWRD 10000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PROPUGT
	Usage: Not Available		THE ACTUAL PRODUCT

Lot #	Details	Lot #	Details
7659	Quantity of 2024 Landhero UBP-65-80 Universal Bucket Pin (Unused) S/N: Not Available C/W: (4) 65 mm x 475 mm & (4) 70 mm x 475 mm & (4) 80 mm x 550 mm,; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7667	Quantity of (4) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		7668	Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7670	Quantity of Parts & Tools S/N: Not Available C/W: Bosch Drill, Wrenches, Wheels, One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7660	2024 Landhero UBP-90-100 Universal Bucket Pin (Unused) S/N: Not Available C/W: (4) 90 mm x 650 mm, (2)100 mm x 750	7671	NVE 607 Challenger Vacuum Pump S/N: 36777 Usage: Not Available Asset located in: Lake Worth, TX
	mm, ;THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	7672	Quantity of Hydraulic Pump & Crusher Blades S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7673	Quantity of Contractor Supplies S/N: Not Available C/W: Hose, Poulan Pro Chain Saw, One Pallet
7662	Excavator Parts		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes : ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	7674	Quantity of Truck Parts S/N: Not Available C/W: Exhausts/Pipes, Headlights Usage: Not Available Asset located in: Lake Worth, TX
7663	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Quantity of Parts & Tools	7677	Quantity of (2) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available
	S/N: Not Available C/W: (2) Seats, Mud Flap, Sockets, Barbed Wire, (2) Pallets Usage: Not Available Asset located in : Lake Worth, TX	7678	Asset located in: Lake Worth, TX Quantity of Sheet Metal Parts S/N: Not Available C/W: assorted size & type
7664	Pro Tech Aluminum Headache Rack S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7679	Quantity of (2) Hydraulic Pumps S/N: Not Available
7665	Quantity of PVC Fittings S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7680 25' Steel Floor Ramp (Unused) S/N: Not Available C/W: 25'x101" Loading ramp, 12" beam frame, 6" channel in the mic Channel crossmembers, Smooth with expanded metal welded on,	Asset located in: Lake Worth, TX 25' Steel Floor Ramp (Unused) S/N: Not Available
7666	Master MH190T-KFA 190000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available

Details	Lot #	Details
Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7689	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
Quantity of (2) Zato Hydraulic Pumps S/N: Not Available C/W: Linde HPV280; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		
S/N: Not Available	7600	Asset located in: Corsicana, TX Crawler tractor drive motor teeth
C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7090	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
Star Industries 1210 4 ft x 8 ft Work Platform S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
JLG 3248RS Parts S/N: Not Available C/W: Deck, Boom Arms, Cylinders Usage: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Corsicana, TX
Asset located in: Lake Worth, TX	7691	Quantity of (2) Pallets of Bucket teeth
Skyjack SJ8841 RT Parts S/N: Not Available C/W: Deck, Tires, Outriggers, Hyd Cylinders, Transfer Case, Drive Shaft, Engine, Fuel & Hydraulic Tank Box Usage: Not Available	S/N: Not Available C/W: EQUIPMENT-FROM-WATK CONSTRUCTION Usage: Not Available Notes : ITEMS AT OFFSITE LOCA	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
Asset located in: Lake Worth, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
Quantity of Parts - Fits Chevrolet 3500 HD 6.0L S/N: Not Available C/W: Intake, Transfer Case, Wiring Harness Usage: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7692 Quantity of (2) Pallets of Bucket t S/N: Not Available C/W: EQUIPMENT-FROM-WATKIN CONSTRUCTION Usage: Not Available	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
Asset located in: Lahoma, OK		BE PICKED UP WITHIN 14 DAYS OF THE
Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Zato Hydraulic Pumps S/N: Not Available C/W: Linde HPV280; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Schaeffler Roller Bearings S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Star Industries 1210 4 ft x 8 ft Work Platform S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX JLG 3248RS Parts S/N: Not Available C/W: Deck, Boom Arms, Cylinders Usage: Not Available C/W: Deck, Boom Arms, Cylinders Usage: Not Available Asset located in: Lake Worth, TX Skyjack SJ8841 RT Parts S/N: Not Available C/W: Deck, Tires, Outriggers, Hyd Cylinders, Transfer Case, Drive Shaft, Engine, Fuel & Hydraulic Tank Box Usage: Not Available Asset located in: Lake Worth, TX Quantity of Parts - Fits Chevrolet 3500 HD 6.0L S/N: Not Available C/W: Intake, Transfer Case, Wiring Harness Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (2) Pallets of Bucket teeth S/N: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Zato Hydraulic Pumps S/N: Not Available C/W: Linde HPV280; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Schaeffler Roller Bearings S/N: Not Available Asset located in: Lake Worth, TX Quantity of (2) Schaeffler Roller Bearings S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Star Industries 1210 4 ft x 8 ft Work Platform S/N: Not Available Asset located in: Lake Worth, TX JLG 3248RS Parts S/N: Not Available C/W: Deck, Boom Arms, Cylinders Usage: Not Available C/W: Deck, Boom Arms, Cylinders Usage: Not Available C/W: Deck, Tires, Outriggers, Hyd Cylinders, Transfer Case, Drive Shaft, Engine, Fuel & Hydraulic Tank Box Usage: Not Available C/W: Deck, Tires, Outriggers, Hyd Cylinders, Transfer Case, Drive Shaft, Engine, Fuel & Hydraulic Tank Box Usage: Not Available C/W: Lintake, Transfer Case, Wiring Harness Usage: Not Available C/W: Intake, Transfer Case, Wiring Harness Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (2) Pallets of Bucket teeth S/N: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE

Lot #	Details	Lot #	Details
7693	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7697	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7694	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7698	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7695	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7699	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7696	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7700	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311/314

S/N: Not Available C/W: 65mm x 410mm Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7702	Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311/314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available	7708	Quantity of (2) Teran 2512552 Bucket Pins (Unused) - Fits Cat 336D S/N: Not Available C/W: 100mm X 640mm (Long total) DB LinkageFront W/Flange for Cat 336D,330D, 385CL, 336FLN, 340FL, 329DL, 324D, 325DL, 329EL, 336FLNXE, 324DL, 330FLN, 336EL, 330FL, 324ELN, 385COEM, 329D2L, 326D2, 326FL, 349ELVG, 336FLXE, 340D2L, 324DLN, 326D2L, 329DLN, 349EL, 325DLOEM, 336E, 385C, 336FL, 340DL, 325DLN, 329FL, 324EL,
7704	C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available Asset located in: Lake Worth, TX Overtity of (4) Toron 0875805 Byelot Bine		329D2, 336ELH, 324E, 329E, 325D, 336EHVGOEM, 336EH, 336ELN, 329D, 326DL, 345CLVG, 336ELNH, 336EOEM, 329ELN, 326FLN, 336FLH, 340FLLRE, 340FUHD,
7704	Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available	7709	336FXE, 340F, 336F, 328DLCR Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Teran 2512558 Bucket Pins
7705	Asset located in: Lake Worth, TX Quantity of (4) Teran 1066878 Bucket Pins (Unused) - Fits Cat 315 S/N: Not Available C/W: 70mm X 508mm for Komatsu PC160 Front & Rear - 315 Linkage Usage: Not Available Asset located in: Lake Worth, TX	7710	(Unused) - Fits Cat 336D S/N: Not Available C/W: 90mm X 635mm (Long total W/Flange) DB Linkage Rear for Cat 336D,330D,324E, 336ELH, 325D, 329E, 336FL, 325DLOEM, 330FL, 329DLN, 336EL, 336EH, 336ELN, 336EHVGOEM, 330CL, 324DL, 340FLLRE, 325DL, 324EL, 336FLXE, 329ELN, 385COEM, 329EL, 324ELN, 329D2L, 326D2, 329DL, 326FL, 340D2L, 326D2L, 324DLN, 324D, 336FLN, 336E, 385C, 340DL, 385CL, 325DLN, 329FL, 340FL, 329D2, 336FLNXE, 330FLN, 329FL, 340FL, 345CLVG, 336ELNH, 336EOEM, 326FLN, 336FLH, 340FUHD, 336FXE, 340F, 336F, 328DLCR Usage: Not Available Asset located in: Lake Worth, TX
7706	Quantity of (2) Teran 2357636 Bucket Pins (Unused) - Fits Cat 349 S/N: Not Available C/W: 110mm X 705mm (Long total W/Flange) TB Linkage Front for Cat 345,345C,336DL, 352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349D2, 324D, 349DLVG, 336D2L,		
	349EL, 330DL, 345DL, 349FLXE, 336D2XE, 340FL, 340FLLRE, 336FLNXE, 336FL, 336DLN, 336ELN, 336D2LXE, 336FLN, 336D2, 349D2L, 336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH, 330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F Usage: Not Available		Quantity of (2) Teran 4l5015 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 80mm X 735mm F Linkage for CAT 330,330B, 345B, 345C, 350, Usage: Not Available Asset located in: Lake Worth, TX
7707	Asset located in: Lake Worth, TX Quantity of (2) Teran 2357642 Bucket Pins	7711	Quantity of (4) Teran 7Y3549 Bucket Pins (Unused) - Fits Cat 330
7707	(Unused) - Fits Cat 349 S/N: Not Available C/W: 100mm X 695mm (Long total W/Flange) TB Linkage Rear for Cat 345,345C,336DL,		S/N: Not Available C/W: 80mm X 630mm D Linkage - Rear Usage: Not Available Asset located in : Lake Worth, TX
	352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349DL, 349DLVG, 336D2L, 349EL, 330DL, 345DL, 349FLXE, 336D2XE, 340FL, 340FLLRE, 336FLNXE, 336FL, 336DLN, 336ELN, 336D2LXE, 336FLN, 336D2, 349D2L, 336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH, 330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F Usage: Not Available Asset located in: Lake Worth, TX	7712	Quantity of (4) Teran 7Y3550 Bucket Pins (Unused) - Fits Cat 330 S/N: Not Available C/W: 90mm X 650mm D Linkage - Front Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7714	Excavator compartment doors - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7718	Quantity of (2) Pallets of Bucket pins S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7715	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7719	Quantity of (2) Pallets of Misc. parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7716	Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7720	Quantity of (2) Pallets of Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7717	Quantity of (2) Pallets of engine bay doors S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7721	Asset located in: Corsicana, TX Quantity Of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

_		T.	
Lot #	Details	Lot #	Details
7722	Quantity of Track Idlers - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7726	Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7723	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7727	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7724	Quantity of (2) Excavator components box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7728	Hood - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7725	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7729	Shovel holders S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7730	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7734	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7731	Quantity of (2) Pallets of Hand rails - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7735	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7732	Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7736	Quantity of (2) Pallets of Crawler tractor parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7733	Quantity Of Hydraulic Parts S/N: Not Available C/W: Hydraulic Hoses, Hydraulic Tank, Hydraulic Pump EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7737	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

		1	
Lot #	Details	Lot #	Details
7738	Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7742	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7739	Asset located in: Corsicana, TX Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	-7743	Quantity of (2) Pallets of Crawler tractor parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	Asset located in: Corsicana, TX	7744	Bucket Cutting Edges
7740	Quantity of (2) Pallets of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
	·	7745	Track Idlers
7741	Quantity of (3) Track idlers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7746	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7749C	Quantity of (2) Stair/Fender Assemblies - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		7750	Quantity of Shredder Teeth (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	7751	Quantity of (2) Pallets of Shredder Teeth
7747	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX
	CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	7758	Quantity of (6) Wheels - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Corsicana, TX	7759	Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7748	8 Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7760	Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		7761	Quantity of Exhaust Stacks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BI
	Asset located in: Corsicana, TX		PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7749	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T		Asset located in: Corsicana, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7762	Quantity of Assorted Truck & Trailer Parts S/N: Not Available C/W: used tires, (3) Wheel barrows, air, fuel and hyd filters, banding machine, folding chairs, trash can, truck tractor seat, hyd hoses, mud flaps, brake pads, mirrors, a/c compressors, cat injectors, Denso Protal 7200 2 part resin, Black Beauty Abrasive, and misc parts Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE
7749A	Walking Beam - Fits Cat 740B		SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX		AVAILABLE Asset located in: McAlester, OK
7749B	Middle & Front Frame - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
7763	Quantity of (3) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7769	Quantity of Mack Front Grills S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7764	Quantity of Equipment and Vehicle Lights S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7770	Quantity of (4) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7765	Quantity of (3) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7771	Quantity of Truck Side Panels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7766	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7772	Quantity of Truck Metal Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7767	Quantity of (2) 22.5 x 8.25 Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7773	Quantity of 2 5/16 in Ball Hitches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7768	Quantity of 2 5/16 in Ball Hitches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7774	Quantity of Radiators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7775	Quantity of (2) 16 x 24 Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7783	Quantity of (2) Stantion 3 Ft x 12 Ft Truck Undercarriage Wash System S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX 101 in x 25 Ft Loading Ramp S/N: Not Available C/W: 45,000 lb Rated with 2x8 Treated Lumber Floor
7776	Quantity of Truck Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		Usage: Not Available Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7784A	X-STAR 40 ft x 100 in Bridge (Unused) S/N: Not Available C/W: 14,000 lb. Usage: Not Available Asset located in: Lake Worth, TX
7777	Quantity of (2) Pallets of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7786	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor
7778	Quantity of Truck Tactor Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7787	Usage: Not Available Asset located in: Lake Worth, TX 101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
7779	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	7788	101 in x 25 ft Bridge Platform Bridge - Fits xstar S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
7780	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX Quantity of (5) Portable Electrical Distribution		101"x40' 14k Rated Bridge (Unused) S/N: Not Available C/W: 2x8 Treated Lumber Floor Usage: Not Available
	Boxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7790	Asset located in: Lake Worth, TX Quantity of (2) Stainless Steel Brewing Vats S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7781	Power Distribution Unit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	7791	Quantity of (2) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX
7782	Quantity of (8) Intertek Lighting Fixtures S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7792	Quantity of (2) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details	
7793	Quantity of (3) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX	7801	Corrugated Structural Steel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
7794	Quantity of (3) 30 In x 42 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available			
7795	Asset located in: Lake Worth, TX Quantity of (3) 30 In x 42 In Metal Tables S/N: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7802	Asset located in: Lake Worth, TX Quantity of (4) 2024 4-Fuel.com PFFF- ARLHALTO Safety Cabinets (Unused)	
7796	Quantity of (3) 31 In x 72 In Metal Shop Tables S/N: Not Available C/W: Wilton Vise; EQUIPMENT-FROM-US- AUTO-RECYCLING		S/N: Not Available C/W: DIMENSIONS 78" H x 39" W x 17" D Usage: Not Available Asset located in : Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	7803	Quantity of Contractor Supplies S/N: Not Available	
7797	Quantity of (2) Metal Tables S/N: Not Available C/W: (1) 20.5 in x 60 in, (1) 30 in x 72 in; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		C/W: Floor Jacks, Sockets, Bit Sets, Bottle Jack, Trolley Jack, One Pallet; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
7798	Quantity of (5) Shop Supplies S/N: Not Available C/W: Engine Hoist, Shop Fan, (2) Dollies, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7804	Quantity of (3) Pallets of Rolling Service Carts S/N: Not Available C/W: Uline, U.S. General, (11) Carts; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	
7799	Quantity of (2) Hydraulic Hose Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Quantity of (200) 2024 Suihe LCSS-200	7805	Quantity of (7) Pallets of Tools & Parts S/N: Not Available C/W: Hose, Assorted Parts, Electrical Supplies; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:	
7000	Corrugated Structural Steel (Unused) S/N: Not Available		Asset located in: Lake Worth, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	7807	Royal Gourmet 8 Burner Propane Grill S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7808	31.5 In Rubber Belt S/N: Not Available C/W: Blue Rack; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7809	2020 Weg W21 Electric Motor S/N: 1053815288 C/W: 315 KW, 3 Phase, 467 Amp; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7822	Quantity of (3) Pallets of Belt Material S/N: Not Available C/W: Assorted Size/Type; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7810 7811	Blue Diamond 1 1/4 In Sch 40 HDPE Conduit S/N: Not Available C/W: One Spool Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) Pallets of Shop Fans	7823	Quantity of (2) Pallets of Tools S/N: Not Available C/W: Wrenches, Sockets, Drills, Impacts; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
 7813	S/N: Not Available C/W: (4) 42 in, (11) 24 in, (1) Air Mover; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX Quantity of (3) Pallets of Shop Supplies	7824	Asset located in: Lake Worth, TX Quantity of (16) 48 In x 48 In Wheeled Drain Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
	S/N: Not Available C/W: (1) Pallet of Banders & Strapping, (1) Pallet of Shop Vacs & Mop Kits, (1) Table W /Roadmags; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7825	Asset located in: Lake Worth, TX Quantity of (4) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7815	Quantity of (3) Pallets of S/N: Not Available Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7826	GenMega G6000 Series ATM S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
7817	Quantity of (5) Pallets of Parts & Tools S/N: Not Available C/W: Hose, Wire, Pumps, Bolt Bins/Racks; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7827	Asset located in: Lake Worth, TX 300 Gallon Air Tank S/N: Not Available C/W: Ingersoll Rand PSG30 Separator System; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:
7818	Quantity of (5) Hand Trucks S/N: Not Available C/W: (4) Martins 1000 lb capacity, one pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7828	Asset located in: Lake Worth, TX 20 ton Air Press S/N: 193562011 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7820	Quantity of (2) 30 In x 96 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7830	Quantity of (4) 30 in x 96 in Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7831	Modular Cage System S/N: Not Available C/W: Two Pallets; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7842 -7843	Quantity of (8) Trash Cans S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX U. S. General 72 in 18-Drawer Workbench
7832	Quantity of Bolt Bins S/N: Not Available C/W: Contents, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7833	Quantity of (7) Pallets of Misc S/N: Not Available C/W: Air Tanks, Tables, Power Strips, Cables, Misc EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	- 7844	Quantity of (3) Pallets of Misc Supplies S/N: Not Available C/W: (1) Pallet of Assorted Wire, (1) Pallet of Assorted Office Supplies, (1) Pallet of Chairs; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7835	47.25 In Rubber Belt S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7845	Quantity of (4) 30 In x 96 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7836	47 In x 47 In Platform Scale S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7846	Quantity of (3) Hopper Extensions S/N: Not Available C/W: (2) 69 In, (1) 74 In; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: Apper Jacobia in: Lake Worth, TY
7838	Quantity of (3) Bundles of Cardboard Boxes S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7847	Asset located in: Lake Worth, TX Quantity of (3) 4 Ft x 4 Ft Storage Boxes S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7839	Quantity of (4) Misc Supplies S/N: Not Available C/W: (1) Pallet of Assorted Tools/Jacks, (1) Pallet of Assorted Filters, (1) Pallet of Misc, (1) Pallet of Assorted Parts/Fittings; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Apart Invested in: Lake Worth, TY	7848	Quantity of (4) Metal Shop Tables S/N: Not Available C/W: (2) 30 In x 72 In, (1) 36 In x 72 In, vise, saw; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7841	Asset located in: Lake Worth, TX Quantity of (2) Pallets of Misc Supplies S/N: Not Available C/W: Rakes/Shovels, Chains; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7849	Quantity of (5) Pallets of Assorted Filters S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX

	D 1 1	1 "	
Lot #	Details	Lot #	Details
7850	36 In x 44 In Steel Storage Cabinet S/N: Not Available C/W: Contents; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7863	JET JDP-15F 15" Drill Press S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7853	Quantity of (13) Pallets of Fluid Recovery Bay Protective Screens S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	 7864	Superwrap Taping Machine S/N: Not Available C/W: To Fit Superwrap Taping machine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
7855	Quantity of (3) Pallets of Parts, Mats & Trays S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7865	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Binks Pneumatic Paint Pot S/N: 316637 C/W: Hose, Hood
7856	Quantity of Tool Bins & Cabinet S/N: Not Available C/W: (1) 36 ln x 24 ln x 78 ln Cabinet W /Contents, Rolling Pegboard, Bolt Bins; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WII NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7857	Quantity of (10) Wen Industries 6 x 3 Ft Fluid Drain Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING	7866	Carport Kit - 18 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
 7858	Usage: Not Available Notes: . Asset located in: Lake Worth, TX Quantity of (2) Pallets of Warehouse Supplies	7867	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available
7000	S/N: Not Available C/W: Assorted Hose, Safety Supplies; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes:	7868	Asset located in: Lake Worth, TX Carport Kit - 24 ft W x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7860	Asset located in: Lake Worth, TX Modular Cage System S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING	7869 	Carport Kit - 18 ft w x 25 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7870	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available
7862	Gates GC32TSI Crimper Machine S/N: TSI0980E21 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

		1_	
Lot #	Details	Lot #	Details
7871	Quantity of Oils, Service Fluids S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7876	Wheeler 4160 Pipe Threading Tripod S/N: Not Available C/W: Tools. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7872	Quantity of (22) Wagner HPLV Paint Sprayer	7877	Napa, Carlyle 7915070B Engine Stand
	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	,,,,	S/N: Not Available C/W: To Fit Carlyle 7915070B, Geared Rotation Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7873	Quantity of Air Hose & Accessories		Asset located in: Lahoma, OK
7874	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Entry Steps S/N: Not Available C/W: 36 in W, 18 in H Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	7879	Napa, Carlyle 7916021A Engine Hoist S/N: Not Available C/W: To Fit Carlyle 7916021A Engine Hoist, With Spreader Bar Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Napa, Carlyle 7917170A Transmission Jack S/N: Not Available C/W: To Fit Carlyle 7917170A Transmission Jack, 1 Ton Capacity
7875	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (3) Piusi 017945010 DEF Pump S/N: Not Available C/W: Fits 55 Gal Drum Usage: Not Available		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7880	Graco Line Lazer IV Walk Behind Paint Striper S/N: Not Available C/W: 2008 US EPA Label, Honda 163 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7881	Centech Battery Charger S/N: Not Available C/W: Shop-Vac, Oil Pump, Oil, Fencing Supplies. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7886	Quantity of Pressure Washer and Concrete Saw S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
7882	Quantity of Contractor Supplies S/N: Not Available C/W: Vice, Extension Cords, Bolts, Pillow Block Bearings, Track Link for JOHN Deere 2106, Trailer Parts Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	7887	Asset located in: Corsicana, TX Quantity of Weed Eater, Tools, Sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	
7883	Quantity of (3) Crates of PVC Fittings 4"-12" S/N: Not Available Usage: Not Available	7888	Misc. shop supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	
7884	Asset located in: Lake Worth, TX Quantity of Power Washers and Generators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7889	BE PICKED UP WITHIN 14 DAYS OF AUCTION (JANUARY 3RD) OR WILL SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOU NOT BE ABLE TO ASSIST WITH LOATHESE	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		Quantity of Generators and Water Pumps S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
7885	Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7890	Quantity of (4) Airless paint sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7895	shop tools S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7891	Quantity of Construction Suppiles S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7896	Quantity of Vibratory Plate Compactor, Generator, Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7892	Generator, plate compactor, water pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7897	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7893	mail box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7898	Asset located in: Corsicana, TX Quantity of Shop Tools S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7894	Quantity of (8) Torque Wrenches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7899	Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7903	Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7900	Quantity of Shop Supplies	7904	Quantity of Power Washers, Battery Charger,
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	_	Air Compressor S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7901	Misc Supplies	7905	Asset located in: Corsicana, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7 900	Quantity of Shop Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
7902	Misc. shop supplies	7006	·
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7906	Pipe sizers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
		7907	Quantity of chlorine recovery boxes
			S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
		7908	SCBA packs S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7909	FS400ASK oil skimmer S/N: A2968 C/W: 1 Cylinder Gasoline Engine Usage: Not Available	7919	Comfortmaker NXA660GKA100 Air Conditioner S/N: E160802838 Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7921	Reelcraft Compressor Cart	
7910	misc firefighting accessories S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		7921	S/N: Not Available C/W: Hose Reel; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
7911	Miller Bobcat 225NT Stick Engine Driven Welder (Inoperable) S/N: KJ029548 C/W: Open 2 Odlinder Casaline Engine	7922	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	
	C/W: Onan 2 Cylinder Gasoline Engine Usage: 763 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Quantity of Assorted Shop Tools and Supplies (Inoperable) S/N: Not Available C/W: (1) Craftsman Weed Eater, (2) Generators, (1) Pressure Washer, (5) Trash Pumps, Ladders, Bolt Bin with Contents, Pressure Washer and Air Hoses, Spill Kits,	
7912	Quantity of Misc. wiring S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Electrical Wire, Misc Shop Tools, Electrical Wire, Misc Shop/Warehouse Education Supplies and Misc Shop/Warehouse Education Warehouse Education Street LOADOUT BY APPOINTMENT OF ITEM AT OFFSITE LOCATION MUST BE	Electrical Wire, Misc Shop Tools, Electrical Supplies and Misc Shop/Warehouse Equipment Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	7923	Haul Master 5-Ton Crane Hoist S/N: Not Available	
7913	Quantity of (7) Pneumatic Concrete Breakers S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	
7914	Quantity of Napa Oil Filters (Unused)		Asset located in: McAlester, OK	
	S/N: Not Available C/W: Assorted Size/Type Usage: Not Available Asset located in : Lake Worth, TX	7924	Quantity of Assorted Shop Tools and Parts S/N: Not Available C/W: Hammer Wrenches, 1 in Torque Wrenches, Micro Tester, Valves, Filing Cabinet,	
7916	100 Ft Galvanized Chain S/N: Not Available Usage: Not Available		Shop Fan, Heavy Duty Rack, Brake Benders, Caulking Guns, Misc Shop Usage: Not Available Notes: LOADOUT BY APPOINTMENT ITEM AT OFFSITE LOCATION MUST PICKED UP BY DECEMBER 31ST OR SUBJECT TO 3RD PARTY STORAGE	Shop Fan, Heavy Duty Rack, Brake Bands, Pipe Benders, Caulking Guns, Misc Shop Tools Usage: Not Available
7917	Asset located in: Lake Worth, TX Scotsman C05305A-1E Ice Machine S/N: 19051320014944 Usage: Not Available Asset located in: Lake Worth, TX			ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
7918	Ice-O-Matic CIM0430FA Commercial Ice maker		Asset located in: McAlester, OK	
, , 10	w/ collection bin S/N: 23011280011235 Usage: Not Available Asset located in: Lake Worth, TX	7925	Quantity of Bolts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	
			Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7926	Quantity of Metal Grating S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7935	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7936	Big Daddy Targets Small AR500 Shooting Target (Unused)
7927	Quantity of Safety Air Masks S/N: Not Available C/W: Tank Holders, Regulators		S/N: Not Available C/W: Birds & Raccoons Motif Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7937	Big Daddy Targets Small AR500 Shooting
7928	Suihe Mens/Womens Portable Restroom (Unused) S/N: Not Available Usage: Not Available		Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7938	Big Daddy Targets Small AR500 Shooting
7929	Greatbear 2 Ton Magnetic Lifter & 5 Ton Scale (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Target (Unused) S/N: Not Available C/W: Birds & Turkey Motif Usage: Not Available Asset located in: Lake Worth, TX
7930	Quantity of (4) Pallets of Chains and Clevises (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7939	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX
7931	Quantity of (9) Thermal Arc Suitcase Welders S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	 7940	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX
7932	Big Daddy Targets Large AR500 Shooting Target (Unused) S/N: Not Available C/W: Bigfoot W/Fish Motif Usage: Not Available Asset located in: Lake Worth, TX	7941	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX
7933	Big Daddy Targets Large AR500 Shooting Target (Unused) S/N: Not Available C/W: T-Rex Motif Usage: Not Available Asset located in: Lake Worth, TX	7942	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX
7934	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Raccoons Motif Usage: Not Available	7943	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available C/W: Coyote & Deer Motif Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7944	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available C/W: Hogs & Sheep Motif Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7945	Steel Shooting Target (Unused) S/N: Not Available C/W: Bigfoot Motif Usage: Not Available	7957	Big Daddy Feeders Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7946	Asset located in: Lake Worth, TX Steel Shooting Target (Unused) S/N: Not Available C/W: Gunfighter Motif Usage: Not Available	7958	Big Daddy Feeders Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7947	Asset located in: Lake Worth, TX Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7959	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7948	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7960 	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7949 7950	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7961	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7962	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available
7951	Target (Unused) S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
7952	Asset located in: Lake Worth, TX Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available	7963 	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7964	Big Daddy Targets Small AR500 Shooting Target (Unused)
7953	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available		S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in : Lake Worth, TX
7954	Asset located in: Lake Worth, TX Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available	7965	Big Daddy Fire Pits 30 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7955	Asset located in: Lake Worth, TX Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available	7966	Big Daddy Fire Pits 30 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7956	Asset located in: Lake Worth, TX Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7967	Big Daddy Fire Pits 24 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7968 7969	Big Daddy Fire Pits 24 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of Sand Bags S/N: Not Available Usage: Not Available Usage: Not Available	7977	Manitowoc QY0454A Ice Machine S/N: 040262489 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	7978	Dust Collector S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7970	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (2) Bundles of 40 Ft Angle Iron	7979	Park Indistries Fastback Electric Stone Polisher S/N: Not Available C/W: extensions Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: (1) 1 1/2 In, (1) 2 In Usage: Not Available Asset located in : Lake Worth, TX	7980	Supershear Hydraulic Catalytic Converter Cutter S/N: 1411 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING
7971	771 Quantity of (5) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX	7981	Supershear Hydraulic Catalytic Converter Cutter S/N: 1409 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING
7972	Quantity of (2) Bundles Of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7982	Quantity of Conveyer Belts & Rollers S/N: Not Available C/W: (1) 10 In Belt, (1) 24 In Belt, (1) 47 In
7973	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available		Vinyl, (3) 84 In Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 In Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 In Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 24 III Belt, (1) 47 III Vinyl, (3) 84 III Belt, (1) 47 III Vinyl, (4) 84 III Belt, (4) 84 III Vinyl,
7974	Asset located in: Lake Worth, TX Quantity of (1) Bundle of Cattle Fence Stay Lock 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7983 	Quantity of HWI MC25 Plus Fireclay Based Cement S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7975	Quantity of (2) Bundles Of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7984	Quantity of (8) Reelcraft HD76100 Hose Reels S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
7976	Manitowoc SY0324A Ice Machine S/N: 110558398 Usage: Not Available Asset located in: Lake Worth, TX	7985	Asset located in: Lake Worth, TX Quantity of (3) Donaldson Torit MM1200 Electric Mist Collectors S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7987	Hillman 15 Ton Rollers S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	7994	Quantity of (2) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7988	Quantity of (6) Pipe Racks S/N: Not Available C/W: Assorted Sizes Usage: Not Available Asset located in: Lake Worth, TX	7995	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX
7909	S/N: Not Available C/W: Lockout Tags, Marking Paint, Measuring Wheel, Hitch Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Quantity of (3) Fuel Cans & (1) Lifting Strap	7996	Quantity of (2) Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase, (1) Koehring B150D, (1) Porta Heat 97 Usage: Not Available Asset located in: Lake Worth, TX
7000		7997	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX
7990		7998	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX
7991	THESE Asset located in: Lahoma, OK Quantity of (4) Gas Monitors S/N: Not Available Usage: 5 Hr	7999	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8000	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7992	Asset located in: Lahoma, OK Quantity of (10) Pallets of Shelving Guardrails & Accessories S/N: Not Available	8001	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7993	C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Pallets of Reelcraft HD76100	8002	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
, , , , ,	Hose Reels		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in : Lake Worth, TX	8003	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8004	Quantity of (6) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8015	2016 Tennant T17 Ride-On Electric Floor Sweeper S/N: T17-11025 C/W: 44 in Working Width, Water System, 36 Volt Operating System Usage: 2,098 Hr
8005	Quantity (3) Commercial (Car Wash) Vacuum System		Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX	8016	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle
8006	Quantity of (5) Pallets of Generators & Pressure Washers		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac, Titan, North Star, Simpson, Ex-Cell, Mi-T-M, Power Ease Usage: Not Available Asset located in : Humble, TX	8017	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available
8007	10 ft x 10 ft Canopy S/N: Not Available	8018	Asset located in: Lake Worth, TX Quantity of (16) 3-5/8 in Square Gauge 12
	Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8019	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle
0010	Asset located in: Lahoma, OK	_	
8010	2017 Tennant T20 Ride-On Floor Sweeper S/N: T20-9225 C/W: 56 in Working Width, Water System, Rear		Usage: Not Available Asset located in: Lake Worth, TX
	Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 2,922 Hr Asset located in: Lake Worth, TX	8020	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available
8011	2016 Tennant T20 Ride-On Floor Sweeper S/N: T20-6540 C/W: 48 in Working Width, Water System, Rear		C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Squeegee, PSI 4 Cylinder 2.0 L Dual Fuel Engine Usage: 1,348 Hr Asset located in: Lake Worth, TX	8021	·
8012	2015 Tennant T20 Ride-On Floor Sweeper S/N: T20-6442 C/W: 56 in Working Width, Water System, Rear	S/N: Not Available C/W: One Bundle Usage: Not Available	C/W: One Bundle
	Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 566 Hr Asset located in: Lake Worth, TX	8022	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused)
8013	2019 Tennant M17 Ride-On Electric Floor Sweeper S/N: M17-11001		S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 52 in Working Width, Water System, Rear Squeegee, 36 Volt Operating System Usage: 4,574 Hr	8023	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused)
001 1	Asset located in: Lake Worth, TX	-	S/N: Not Available C/W: One Bundle
8014	2019 Tennant T17 Ride-On Floor Sweeper S/N: T17-13185 C/W: 44 in Working Width, 36 Volt Operating System Usage: 2,013 Hr Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8024	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8033	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8025	Quantity of (19) 2 7/8 In OD Pipe S/N: Not Available C/W: 21 ft, one bundle Usage: Not Available Asset located in: Lake Worth, TX	8034	Quantity of (25) 19 ft x 2 in x 2 3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available
8026	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8027	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8036	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available
8028	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8037	Asset located in: Lake Worth, TX Quantity of (25) 20 ft x 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available
8029	Quantity of (25) 19 ft 2 in x 2 3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8038	Asset located in: Lake Worth, TX Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available
8030	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8039	Asset located in: Lake Worth, TX Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available
8031	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8040	Asset located in: Lake Worth, TX Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available
8032	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8041	Asset located in: Lake Worth, TX Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8042	Quantity of (61) 21 ft x 1 5/8 in OD Schedule- 10 Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle	8050	Bridgestone 60 in x 525 ft Conveyor Belt S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	8051	32 in Discharge Conveyor Belt - Fits Vermeer Trencher
8043	Quantity of (2) Water Pumps S/N: Not Available C/W: Diaphragm, (1) Wilden 2 In, (1) 2.5 In Water Pumps Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes : ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
8044	Quantity of Safety Supplies S/N: Not Available C/W: (4) Fall Protection Harnesses Usage: 5 Hr		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE		Asset located in: Corsicana, TX
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8054	Quantity of (2) 2020 Ludlum Radiation Detectors S/N: 348035 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: ADDITIONAL COMPONENTS
8045	Quantity of Safety Supplies		AVAILABLE IN OFFICE - GEIGER COUNTER Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Vests, Hard Hats, Safety Glasses, Latch Kits Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	8055	Vortex Hydraulic Catalytic Converter Decanner S/N: Not Available C/W: 10 hp hydraulic power unit, 2014 P & J Dust Extraction LTD PJB175-4.8-8-1E2-1-JMC- 60 dust collector s/n 98468, work platform; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	THESE Asset located in: Lahoma, OK	8056	Quantity of (3) 2021 Vortex PFS Gas De- Pollution Systems
8046	Quantity of Safety Supplies S/N: Not Available C/W: Assorted Truck and Safety supplies Usage: Not Available		S/N: 139/041 C/W: (2) Gas Tank Tower System Punch; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8057	Quantity of (4) 2020 Vortex UHPC Fluid De- Pollution System Pump S/N: Not Available C/W: 3 Fluid Distraction, oil, coolant, washer fluid; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
8047	Quantity of Chain Construction Hoist S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8048	60 in x 565 ft Rubber Conveyor Belt S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
8049	42 in x 570 ft Rubber Conveyor Belt S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8060	2024 Landhonor LHR-PSM26A 26 in Portable Sawmill (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8067	Quantity of (6) Ladder S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
8061	·	8068	2014 Jungheinrich ECR327 6000 lb Electric Pallet Jack S/N: 82800864 C/W: 6000 lb Capacity, 24 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
2000	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8069	Jungheinrich EJE120 Electric Pallet Jack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
8062	2020 Mcintyre 600 HD Metal Shear S/N: 765		Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8070	Toyota 8HBW23 4500 lb Electric Pallet Jack S/N: 8HBW2322023 C/W: 4500 lb Capacity, 24 V Usage: Not Available Asset located in: Lake Worth, TX
8063	2020 JET Electric Band Saw S/N: 081337 C/W: 1 Hp Electric, .75 blade, Milwaukee 40 in work station; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8071	2012 Rico PWH-DD-300 Electric Pallet Jack S/N: R-14544 C/W: 30000 lb Capacity, 24 V, Battery Charger Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
8064	2023 MMLJ DB500 Mobile System Sand Blaster S/N: 1M9BU1828PH774174 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9890 lb GVWR Usage: Not Available	8072	2008 Tempest PAL30 Electric Fan S/N: 6050820402234 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Notes: . Asset located in: Midland, TX	8073	2008 Tempest PAL30 Electric Fan
8066	Quantity of Assorted Steel Cable Cable S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST		S/N: 6030820400225 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8074	Quantity of (3) 24 In Shop Fan S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8075	Quantity of (2) J & D Mfg VPRF36 36 in Fan S/N: 0621 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8084	Quantity of (6) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available
8076	Quantity of (4) Pallets of 24 In x 72 In Pallet Racking S/N: Not Available C/W: 24 In x 48 In Wire Racks, 96 In Crossarms; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: .		Asset located in: Lake Worth, TX
		8085	Quantity of (6) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8086	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft
8077	Quantity of Industrial Pallet Racking S/N: Not Available C/W: (10) Pallets of 42 In x 25 Ft Uprights, (7) Pallets of 96 In Crossarms, (2) Pallets of 144 In Crossarms, (54) Pallets of 43 In x 46 In Wire		S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	Racks; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8087	Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available
8078	Quantity of Uline 36 In x 72 In Shelving		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: One Pallet ; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in : Lake Worth, TX	8088	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available
8079	Quantity of 2 3/8 In Pipe		Asset located in: Lake Worth, TX
8080	S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX Quantity of 2 3/8 In Pipe S/N: Not Available	8089	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	C/W: One Bundle Usage: Not Available Asset located in : Lake Worth, TX	8090	Quantity of (6) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available
8081	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle	C/W: Usage	C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8091	Quantity of (9) 5X4X11 GA Rectangle Tube
8082	Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle		17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	8092	Quantity of 4X3X1/4 Angle Iron
8083	Asset located in: Lake Worth, TX Quantity of 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available Usage: Not Available		S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	8093	Quantity of 4X3X1/4 Angle Iron S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8094	Quantity of (3) 1/4 in Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8105	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8095	Quantity of (5) 3/16 Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8106	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8096	Quantity of (4) Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8106A	Quantity of Corrugated Sheet Metal S/N: Not Available C/W: Assorted Length Usage: Not Available Asset located in: Lake Worth, TX
8097	Quantity of (8) Diamond Plate Steel S/N: Not Available C/W: Assorted Size Usage: Not Available Asset located in: Lake Worth, TX	8107	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8098	Quantity of (6) Diamond Plate Steel S/N: Not Available C/W: Assorted Size Usage: Not Available	8108	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8099	Asset located in: Lake Worth, TX Quantity of (3) Diamond Plate S/N: Not Available	8109	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Assorted Size, One Bundle Usage: Not Available Asset located in : Lake Worth, TX	8110	38 ft x 40 ft Shipping Container Roof Cover Kit (Unused)
8100	Quantity of (2) 8GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shipping Container Roof Cover Usage: Not Available Asset located in: Lake Worth, TX
8101	Quantity of (8) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8111	38 ft x 40 ft Shipping Container Roof Cover Kit (Unused) S/N: Not Available C/W: Quantity of (2) Crates - Builds (1) Container Roof Cover Kit. Usage: Not Available
8102	Quantity of (7) 10GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8112	Asset located in: Lake Worth, TX Quantity of (100) 2024 SUNTOP S2134C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
8103	Quantity of (7) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8104	Quantity of (6) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8113	Quantity of (100) 2024 SUNTOP S2134C 7 ft x 35 in Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8117	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
8114	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8118	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
8115	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8119	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
8116	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8120 8121 8122	Quantity of Assorted Brackets S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of Filters S/N: Not Available C/W: Assorted Size/Type, One Crate Usage: Not Available Asset located in: Lake Worth, TX Quantity of Concrete Mix S/N: Not Available Usage: Not Available Usage: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
8123	Quantity of Mohawk -20 Sand S/N: Not Available C/W: (7) 80 lbs bags Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8136	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
8128 8129	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber	− 8137 −	Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONL ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL	Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
	S/N: Not Available Usage: Not Available		FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
8130	Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8138	Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
8131	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available			
8132	Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8139	Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE	
8133	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
8134	Asset located in: Lake Worth, TX Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (26) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE	
8135	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	

Lot #	Details	Lot #	Details
8141	Quantity of (23) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	8148	Quantity of (2) GE Window Air Conditioner S/N: Not Available C/W: 99 sqft, 230v, 17,600 BTU Usage: Not Available Asset located in: Lake Worth, TX
		8149	AXH 42VVF Air Cooler S/N: 149606G Usage: Not Available Asset located in: Midland, TX
	Asset located in: McAlester, OK	8150	AXH 42VVF Air Cooler
8142	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available		S/N: 149491K Usage: Not Available Asset located in : Midland, TX
	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE	8151	AXH 42VVF Air Cooler S/N: 149491 D Usage: Not Available Asset located in: Midland, TX
8143	AVAILABLE Asset located in: McAlester, OK Quantity of (18) Pallets of 4 ft x 6 in x 4 in	8152	AXH 42VVF Air Cooler S/N: 149606 F Usage: Not Available Asset located in: Midland, TX
	Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8153	AXH 42VVF Air Cooler S/N: 149491 L Usage: Not Available Asset located in: Midland, TX
		8154	AXH 42VVF Air Cooler S/N: 149491 Q Usage: Not Available Asset located in: Midland, TX
8144	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available	8155	AXH 42VVF Air Cooler S/N: 119084 C Usage: Not Available Asset located in: Midland, TX
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE	8156	AXH 42VVF Air Cooler S/N: 119084B Usage: Not Available Asset located in: Midland, TX
 8145	AVAILABLE Asset located in: McAlester, OK 2019 KwiKool KPO5-21H Air Conditioner	8157	AXH 42VVF Air Cooler S/N: 1494910 Usage: Not Available
	S/N: 1014321 Usage: Not Available Notes : . Asset located in : Lake Worth, TX	8158	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149606l Usage: Not Available
8146	2019 KwiKool KP05-21H Air Conditioner S/N: 1014318 Usage: Not Available Notes : .	8159	Asset located in: Midland, TX AXH 42VVF Air Cooler S/N: 149606 E Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Midland, TX
8147	Quantity of (3) Air Conditioner S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8160	AXH 42VVF Air Cooler S/N: 149491E Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
8161	AXH 42VVF Air Cooler S/N: 149491 P Usage: Not Available Asset located in: Midland, TX	8174	AXH 36VVF Air Cooler S/N: 89463 D Usage: Not Available Asset located in: Midland, TX
8162	AXH 42VVF Air Cooler S/N: 149606J Usage: Not Available Asset located in: Midland, TX	8175	AXH 36VVF Air Cooler S/N: 89509A Usage: Not Available Asset located in: Midland, TX
8163	AXH 42VVF Air Cooler S/N: 149491 J Usage: Not Available Asset located in: Midland, TX	8176	AXH 36VVF Air Cooler S/N: 89509B Usage: Not Available Asset located in: Midland, TX
8164	AXH 42VVF Air Cooler S/N: 149606 H Usage: Not Available Asset located in: Midland, TX	8177	AXH 36VVF Air Cooler S/N: 89416E Usage: Not Available Asset located in: Midland, TX
8165	AXH 42VVF Air Cooler S/N: 149491 I Usage: Not Available Asset located in: Midland, TX	8178	AXH 36VVF Air Cooler S/N: 89463 F Usage: Not Available Asset located in: Midland, TX
8166	AXH 42VVF Air Cooler S/N: 149491 G Usage: Not Available Asset located in: Midland, TX	8179	AXH 36VVF Air Cooler S/N: 89416 C Usage: Not Available Asset located in: Midland, TX
8167	AXH 42VVF Air Cooler S/N: 149491 N Usage: Not Available Asset located in: Midland, TX	8180	AXH 36VVF Air Cooler S/N: 89509 C Usage: Not Available Asset located in: Midland, TX
8168	AXH 42VVF Air Cooler S/N: 119084 A Usage: Not Available Asset located in: Midland, TX	8181	AXH 36VVF Air Cooler S/N: 89463 B Usage: Not Available Asset located in: Midland, TX
8169	AXH 42VVF Air Cooler S/N: 149491 F Usage: Not Available Asset located in: Midland, TX	8182	AXH 36VVF Air Cooler S/N: 89463 A Usage: Not Available Asset located in: Midland, TX
8170	AXH 42VVF Air Cooler S/N: 149491 M Usage: Not Available Asset located in: Midland, TX	8183	2015 Air Comman AC1600 Hydraulic Oil Cooler S/N: AC29 Usage: 124 Hr Notes: .
8171	AXH 42VVF Air Cooler S/N: 149491 H Usage: Not Available Asset located in: Midland, TX	8184	Asset located in: Lake Worth, TX 2018 Dri-Eaz DRITEC 4000l Dehumidifier S/N: 1798 Usage: Not Available
8172	AXH 36VVF Air Cooler S/N: 89463E Usage: Not Available Asset located in: Midland, TX	8185	Notes: . Asset located in: Lake Worth, TX 2018 Dri-Eaz DRITEC 4000l Dehumidifier S/N: 1794
8173	AXH 36VVF Air Cooler S/N: 89463 C Usage: Not Available Asset located in: Midland, TX		Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8186	2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1797 Usage: Not Available Notes : .	8193	Quantity of (4) Mr. Heater 60000 BTU Space Heater S/N: Not Available Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8187	Quantity of (4) Heaters S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	8194	Mr. Heater 30000 BTU Space Heater S/N: Not Available C/W: Propane Fueled, (3) Space Heaters, (9) Tanks, (1) Burner Wand. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Corsicana, TX		Asset located in: Lahoma, OK
8187A	Allmand MH1000 Maxi-Heat 1000000 BTU Space Heater S/N: 0039MXH3 C/W: Furnace oil Fueled, Single Phase, 115 V Input, Isuzu 3 Cylinder Diesel Engine Usage: 3,316 Hr	8196	Innovatech Terminator 2000El Electric Ride-On Floor Scraper S/N: T200E302IB Usage: 1,733 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8197	Karcher Chariot 2 iVac 24 ATV Electric Ride-On
8188	2018 Campo EB400D 400000 BTU Space Heater S/N: B400-17-9254		Vacuum Cleaner (Unused) S/N: 10090690000894 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Diesel Fueled Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8198	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240913 Usage: Not Available
8189	2018 Campo EB400D 400000 BTU Space Heater		Asset located in: Lake Worth, TX
	S/N: B400-18-8975 C/W: Diesel Fueled, 120 V Input Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8199	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240915 Usage: Not Available Asset located in: Lake Worth, TX
8190	Heat star HS3500DF 361439 BTU Space Heater S/N: 27901109 C/W: Kerosene Fueled, 120 V Input Usage: Not Available Asset located in: Lake Worth, TX	8200	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240914 Usage: Not Available Asset located in: Lake Worth, TX
8191	Mi-T-M 375000 BTU Space Heater S/N: Not Available C/W: Propane Fueled, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available	8201	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240916 Usage: Not Available Asset located in: Lake Worth, TX
8192	Asset located in: Lake Worth, TX Quantity of (4) Mr. Heater 60,000 BTU Forced Air Space Heater S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8202	2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8203	2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8216	Quantity of (7) Pallets of Landscape Sandstone Boulders S/N: Not Available C/W: assorted size, shape Usage: Not Available Asset located in: Lake Worth, TX
8204	Quantity of Human Touch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8217	Quantity of (7) Pallets of Landscape Sandstone S/N: Not Available C/W: assorted size, shape Usage: Not Available
8205	2024 Landhonor LHR-MC766 Massage Chair Sofa (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available
8206	BarcaLounger (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8219	Asset located in: Lake Worth, TX Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8"
8207	Osaki 3D Prestige Massage Chair S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8208	Asset located in: Lake Worth, TX Osaki 3D Prestige Massage Chair S/N: Not Available Usage: Not Available	8220	Legend Walk Behind 20 in Garden Tiller S/N: Not Available C/W: Legend Force 212 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
8209	Asset located in: Lake Worth, TX Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid S/N: Not Available Usage: Not Available	8221	Legend Walk Behind 20 in Garden Tiller S/N: Not Available C/W: Legend Force 212 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
8210	Asset located in: Lake Worth, TX Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8222	Quantity of (18) Rhino Rugged Landscaping Tools W/ Fiberglass Handles S/N: Not Available C/W: (3) # 12 Aluminum Scoop, (3) 16 in Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10 in Hoe, (3) Square Pt Shovel Usage: Not Available
8211	GE Front Load Washer & Dryer Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8223	Asset located in: Lake Worth, TX Quantity of (18) Rhino Rugged Landscaping Tools W/ Fiberglass Handles
8212	Frigidaire Freezer S/N: AA15240684 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		S/N: Not Available C/W: (3) # 12 Aluminum Scoop, (3) 16 in Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10 in Hoe, (3) Square Pt Shovel Usage: Not Available Asset located in: Lake Worth, TX
8214	Asset located in: Lake Worth, TX True 3-Door Commercial Refrigerator S/N: Not Available Usage: Not Available	8224	Quantity of (3) Hand Held Pump Sprayers S/N: Not Available Usage: Not Available
8215	Asset located in: Lake Worth, TX Quantity of (3) Meat Slicers S/N: Not Available C/W: (2) Bizerba, (1) Hobart Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
8225	Quantity of Chainsaws S/N: Not Available C/W: String Trimmer, Accessories Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8233	72 in Forks S/N: Not Available Usage: Not Available Asset located in : Lake Worth, TX
		8234	Cat 48 in Q/C Wheel Loader Forks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	8235	Quantity of (2) Dolly Bars
8226	Predator Power Auger S/N: 44FAPL24013877 C/W: 2024 US EPA Label, Predator 1 Cylinder 52 cc Gasoline Engine, (1) 8 in Auger, (1) 6 in Auger	0233	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8236	Pearl Abrasive 15 In Floor Preparation Disc S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	8237	Quantity of Cat Final Drive Sprocket Segments
8227	Quantity of (4) Kubota Mower Decks S/N: Not Available C/W: (3) 60 in & (1) 72 in Mower Decks Usage: Not Available Asset located in: Lake Worth, TX		- Fits Cat D6 S/N: Not Available C/W: To Fit Cat D6M, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
8228	Crary 75060 Lawn Vacuum S/N: 103825 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
8229	Craftsman Walk-Behind Leaf Vacuum S/N: 1H01NK10291 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	8238	Pipe handler S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
8230	Quantity of Rhino Rugged Landscaping Hand Tools S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
8231	Cat Engine (Inoperable)		Asset located in: Corsicana, TX
	S/N: Not Available C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	8239	Quantity of (3) Cat Weights S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
8232	Quantity of Truck Parts S/N: Not Available C/W: Hubs, Fenders, One Pallet Usage: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
8240	Grieve 333 Industrial Oven S/N: 104626A1111 Usage: Not Available Asset located in: Midland, TX	8247	2024 Machpro MP-MS100 Sofa (Unused) S/N: SLP2707080862 Usage: Not Available Asset located in: Lake Worth, TX	
8241	Grieve 3330 Electric Airless oven S/N: 114490A0315 C/W: To Fit Grieve 333 Electric Industrial Oven, Grieve .33 hp 3 Phase Motor Usage: Not Available	8248	2024 Machpro MP-MS100 Sofa (Unused) S/N: SLP2707080861 Usage: Not Available Asset located in: Lake Worth, TX	
8242	Asset located in: Midland, TX 2018 Bomag BMP8500 Trench Compactor S/N: 101720129533 C/W: 2018 US EPA Label, Kubota D1005 3 Cylinder 14.3 kW 1.0 L Diesel Engine, 32 in drums w/extensions, remote; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8251	S/N Usa Not BE I AUC SUE BUY NO	Quantity of Fire Extinguisher S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
8243	Mobydick Kitflex 400C Wheel Washing System S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8252	Quantity of (15) Assorted Sized Fire Extinguisher S/N: Not Available	
8244	94 Quantity of (2) Pallets of engine bay doors S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX	8253	2024 Topcon RL-H5B Rotary Laser Level (Unused) S/N: 1B019363 C/W: Receiver Usage: Not Available	
8245	bucket teeth		Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	8254 8255	2014 Sokkia 7383-40 w/ Grade Rod Laser Level S/N: 270612 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX		Trimble EM410 Antenna Mount S/N: 2599J501CN Usage: Not Available Asset located in: Lake Worth, TX	
8246	JLG Man Basket S/N: 2017920 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8256	Topcon GP-3 S/N: Not Available C/W: Topcon GR-3 RTK GPS GNSS, SN#442- 0693, Topcon GR-3 RTK GPS GNSS, SN#442- 0485, Topcon FC-2600 Data Collector, SN#55802743 Usage: Not Available	
8246A	Hydraulic Scrap Metal Baler S/N: 1676784 C/W: 3 ph Usage: Not Available Asset located in: Oklahoma City, OK		Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8257	Topcon Hiper Lite RTK S/N: Not Available C/W: Topcon Hiper Lite RTK GPS, SN#263- 1167, Topcon Hiper Lite RTK GPS, SN#296- 0181, Topcon FC-120 Data Collector, SN#A30665	8265	2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	8266	Quantity of Floor Jacks & Parts S/N: Not Available
8258	Topcon GR-5 RTK S/N: Not Available C/W: Topcon GR-5 RTK GPS GNSS Rover, SN#800-10190 Topcon FC-2600 Data Collector, Magnet Field, SN#556-06832 Usage: Not Available		C/W: (4) Floor Jacks, Receiver Hitch, Scissor Jack, Lights, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8268	Quantity of (4) Jack Stands
8259	Quantity of Laser Equipment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8269	S/N: Not Available Usage: Not Available Notes : ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
8260	2024 Suihe A400 400 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Quantity of (4) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
8261	2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Usage: Not Available Asset located in: Lake Worth, TX	8270	Quantity of (3) Jack Stands S/N: Not Available
8262	2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
8263	2024 Suihe A200 200 lb Cast Iron Anvil (Unused)		NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8271	28 In x 50 In Metal Table S/N: Not Available C/W: Vise Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Lifting Strap, Sockets S/N: Not Available Usage: 5 Hr
8264	Asset located in: Lake Worth, TX 2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
8273	Quantity of Electric Grease Guns S/N: Not Available C/W: Tools Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	8281	2008 Sokkia C22 Builders Level W/Tripod S/N: 004062 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8282	Wood Tuff Tow 48" Job Site Box W/ 7 PC Cub Cadet Tool Kit S/N: Not Available C/W: HT24E- Hedge Trimmer - CS160E- Cordless Chainsaw - LB600E- Leaf Blower - ST15E- String Trimmer - Battery - Charger
8274	Quantity of Tools S/N: Not Available C/W: 1 in Socket Set & Misc. Tools		Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	ir S U	Quantity of (5) 2024 Landhonor LDH-FPR36 36 in Fire Pit Ring S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in : Lahoma, OK	8290	2024 Landhonor LHR-AIW1 Pneumatic 1 in Impact Wrench (Unused) S/N: Not Available
8275	Quantity of Shovels, Post Hole Diggers. S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Usage: Not Available Asset located in: Lake Worth, TX
		8294	Quantity of (3) Battery Charger S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8295	GNB GTC12-600T1 Battery Charger S/N: Not Available C/W: Skid Mounted Basket Usage: Not Available
8276	Quantity of (16) 2024 Agriquip GLWH16 Auto		Asset located in: Lake Worth, TX
	Darkening Welding Helmets (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8296	Quantity of (2) Battery Charger S/N: Not Available C/W: Die Hard DH0168, DSR Pro Series DSR121; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
8278	48" Frontier Job Box W/ 25 PC Makita Power Tool Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8297	Quantity of (4) Midtronics GR8 Commercial Battery Charger S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8279	Wokin 158 PC Standard & Metric Tool Set W/ 42" Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8298	2024 Suihe WW 20000 lb Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8280	Wokin/Valley 8 PC Hydraulic Jack & Jack Stand Kit W/ 42" Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8299	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8307	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8300	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8308	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8301	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8309	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8302	2024 Landhonor LHR-EW20000 20000 lb Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8310	Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
8303	Wood WW15000V12 15000 lb Winch S/N: Not Available C/W: 4.5hp, Remote Control Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8305	Quantity of (8) 3 in OD Fire Water Hose S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8311	Asset located in: Lake Worth, TX Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
8306	Quantity of Bottle Cart & Torches S/N: Not Available C/W: Gauges ; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8312	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset Joseph In: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8313	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8319 8320	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX Quantity of 2024 Landhonor LHR-RF24 27 ft
	Asset located in: Lake Worth, TX	4	Ratchet Straps (Unused) S/N: Not Available
8314	Quantity of 2024 Landhonor LHR-RC5400 5400 Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available Asset located in: Lake Worth, TX	8321	C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8315	Quantity of 2024 Landhonor LHR-RC5400 5400 Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available Asset located in: Lake Worth, TX		2024 Landhonor LHR-LB8850 Leaf Blower (Unused) S/N: Not Available C/W: 1 Cylinder 3.1 kW 75.6 cc Gasoline Engine Usage: Not Available
8316	Quantity of (48) 2024 SKLP SK003 Ratchet	-	Asset located in: Lake Worth, TX
8316	Straps (Unused) S/N: B31577 C/W: (32) 2 in x 27 ft, (16) 1.5 in x 27 ft Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8322	Little Wonder Optimax Walk-Behind Leaf Blower S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		8324	Quantity of (3) Arcan Farm Jack S/N: Not Available Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8317	Quantity of 2024 Landhonor LHR-RF24 1.5 In x 27 Ft Ratchet Straps (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8325	Quantity of (5) 2024 Powertek 20 Ton Pneumatic Bottle Jack (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8318	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8328	Sunex Transmission Jack S/N: Not Available C/W: Under Hoist Stands, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		8329	Quantity of (3) Boxes of Wokin 3 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8330	Quantity of (3) Boxes of 10 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8331	Semi-Trailer Landing Gear S/N: Not Available C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available Asset located in: Lake Worth, TX Semi-Trailer Landing Gear S/N: Not Available	8339	Armor Titanium Series 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digit Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available
	C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available Asset located in : Lake Worth, TX	8340	Asset located in: Lake Worth, TX 2024 Agriquip GLGS14 14 Gun Safe (Unused) S/N: Not Available
8333	Electric Submersible Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8334	Armor Titanium Series 64 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action	8341 8342 8343	2024 Raccoon RC-G1.5 Electric Bicycle (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8335	Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX Armor Titanium Series 40 Gun Safe (Unused)		2024 Raccoon RC-G1.5 Electric Bicycle (Unused) S/N: RC2405310 Usage: Not Available
	S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX 2024 Landhonor LHR-GLS34 Gasoline Tow Behind Log Splitter (Unused) S/N: Not Available C/W: Ball Hitch, Kohler 7 hp Engine Usage: Not Available Asset located in: Lake Worth, TX
8336	2024 Agriquip GLGS40 40 Gun Safe (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8344	2024 Landhonor LS-13-36D Skid Steer Log Splitter (Unused) S/N: Not Available C/W: Skid Steer Carpet Pole, One Crate Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8345	2019 Morbark Boxer X7 Tow-Behind Wood Chipper
8337	Armor Titanium Series 24 Gun Safe S/N: Not Available C/W: 24 in Wide x 56 in High x 24 in Deep, 1400 Degree Fire Rating, Digital Combination key pad, 5 live action locking bolts Usage: Not Available Asset located in: Lake Worth, TX	S/N C/W Koh Eng Chu Usa	S/N: 4S8SZ1010KW006193 C/W: 2018 US EPA Label, CARB Compliant, Kohler ech740 2 Cylinder 747 cc Gasoline Engine, 36 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Ball Hitch Usage: 110 Hr Asset located in: Lake Worth, TX
8338	Armor Titanium Series 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX	8346	2024 Landhonor LHR-PWC6 Wood Chipper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8347	2024 LANM LAM750 Electric Remote Control Crawler Lawn Mower (Unused) S/N: LAM750240707 C/W: 22 in Mower Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	8358	White Outdoor 17BK2ACK090 Zero-Turn Lawn Mower S/N: 1B208G90011 C/W: Hydrostatic Drive, 13x5.00x6 Front Tires, 20x10.00x8 Rear Tires, 54 in Mower Usage: 631 Hr Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8359	2016 Kubota Z725KH Zero-Turn Lawn Mower S/N: 21339
8348	2024 Landhero LHR-HT550 Remote Control Lawn Mower (Unused) S/N: Not Available		C/W: Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 2,329 Hr Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8360	Quantity of (3) Yard Force 22 in Walk Behind String Trimmer
8349	2024 Landhero LHR-HT550 REMOTE CONTROL Lawn Mower (Unused) S/N: Not Available Usage: Not Available		S/N: Not Available C/W: Briggs & Stratton Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	8362	Quantity of (3) Yard Force 9 in Edger
8350	2024 Machpro MP-M500 Tracked Lawn Mower (Unused) S/N: MP20240711180 C/W: Remote Control		S/N: Not Available C/W: 79 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	8367	2021 Polaris 500 Utility Vehicle S/N: 3NSRM2504ME534422
8351	2024 Machpro MP-M500 Tracked Lawn Mower (Unused) S/N: MP20240711182 C/W: Remote Control Usage: Not Available		C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 500 cc Gasoline Engine Usage: Not Available Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX		2018 Kubota RTVX1140 Utility Vehicle
8353	Hustler Dash XD 34 Zero-Turn Lawn Mower S/N: 23100864 C/W: Hydrostatic Drive, 2023 US EPA Label, 11x4.00-5 Front Tires, 18x6.5/8 Rear Tires, Hustler 34 in Mower Usage: Not Available Asset located in: Lake Worth, TX		S/N: A5KD2GDBTJG027894 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed, 2018 US EPA Label, Kubota D1105 3 Cylinder Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,192 Hr Asset located in: Lake Worth, TX
8355	2018 Kubota Z725KH Zero-Turn Lawn Mower S/N: 23133 C/W: Hydrostatic Drive, 2017 US EPA Label, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 180 Hr Asset located in: Lake Worth, TX	8381	2012 Polaris 800 EFI Crew Cab 6 Passenger Utility Vehicle S/N: 4XAWH76AXDE646836 C/W: Canopy, 6 Passenger, Manual Dump Bed, Diesel Engine, Gas Engine Usage: Not Available Asset located in: Lake Worth, TX
8356	Quantity of (6) Yard Force Walk-Behind Lawn	8381A	Utility Vehicle
2000	Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1B9AC2110PA284014 C/W: Canopy, 4 Passenger, Windshield, 4 Cylinder Gasoline Engine Usage: 2,637 Mi Asset located in : Lake Worth, TX
8357	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX	8382	2012 Polaris Ranger XP Utility Vehicle S/N: 4XATH7EA1CE289808 C/W: Canopy, 2 Passenger, Windshield, Hitch Receiver, Manual Dump Bed Usage: 1,799 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8383	Bobcat UV34XL Utility Vehicle S/N: B53721117 C/W: Canopy, 4 Passenger, Windshield, Manual Dump Bed, Polaris Gasoline Engine Usage: 1,521 Hr Asset located in: Lake Worth, TX	8396	2017 Club Car Carryall 1700 Utility Vehicle S/N: A5CUAA4FTHA840664 C/W: Canopy, 4 Passenger, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,294 Hr Asset located in: Lake Worth, TX
8384	2021 John Deere Gator XUV 855M Utility	8397	2017 Club Car Carryall 1700 Utility Vehicle
	Vehicle S/N: 1M0855MBPMM040235 C/W: Canopy, 4 Passenger, Windshield, Manual Dump Bed, 2021 US EPA Label, John Deere 3tnv70 Gasoline Engine Usage: 3,905 Hr	6397	S/N: A5CUAA4FTHA841104 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,674 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8387	2020 Club Car Carryall 1700D Utility Vehicle S/N: SD2011054694 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 1,055 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	8400	2019 Club Car Carryall 1500G Utility Vehicle S/N: RC1918967773 C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 912 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8388	2019 Club Car Carryall 1700G Utility Vehicle S/N: SC1919-968737 C/W: Canopy, 4 Passenger, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 936 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	8403	2007 John Deere TX Turf Gator Utility Vehicle S/N: Not Available C/W: Open Operator Station, 2 Passenger, Hitch Receiver, Manual Dump Bed Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8391	2019 Club Car Carryall 1700D Utility Vehicle S/N: SD1919970463 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota 3 Cylinder Diesel Engine Usage: 967 Hr	8404	1998 E-Z-Go 898445 Club Car Utility Vehicle S/N: C98004700 C/W: Canopy, 2 Passenger, Windshield, Rear Screen, 3 Cylinder Diesel Engine, Diesel Engine Usage: 2,184 Hr Asset located in: Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8407	Tao Motor Boulder 4x2 ATV (Unused) S/N: L9NACFB30N1604821
8393	2019 Club Car Carryall 1700D Utility Vehicle S/N: SD1919969371 C/W: Open Operator Station, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 1,237 Hr		C/W: 2022 US EPA Label, Tao 107 cc Gasoline Engine Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY Asset located in: Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8408	Tao Motor Boulder 4x2 ATV (Unused) S/N: L9NACFB34N1402404 C/W: Electric Start, 2022 US EPA Label, Tao
8394	2019 Club Car Carryall 1700D Utility Vehicle S/N: SD1920-970849 C/W: Canopy, 4 Passenger, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 1,305 Hr		107 cc Gasoline Engine Usage: Not Available Notes : ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY Asset located in : Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8409	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0112975 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit Usage: 9 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8410	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140193 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit Usage: 12 Hr Asset located in: Lake Worth, TX	8419	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409098 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8411	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140519 C/W: Battery Charger, 4 Passenger, Canopy, Windshield, Lift Kit Usage: 7 Hr Asset located in: Lake Worth, TX	8420	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409100 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8412	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409051 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8421	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409099 C/W: 4 Passenger, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8413	2024 HUNTER PRO GFE-4.0 Electric Golf Cart S/N: 202409097 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8422	2024 HUNTER PRO GFX-4.0 Electric Golf Cart (Unused) S/N: 202409069 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
8414	2024 HUNTER PRO GFE-4.0 Electric Golf Cart	8423	Asset located in: Lake Worth, TX
	(Unused) S/N: 202409072 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 37020241084 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
8415	2024 HUNTER PRO GFE-4.0 Electric Golf Cart		Asset located in: Lake Worth, TX
	(Unused) S/N: 202409071 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8424	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409115 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
8416	2024 HUNTER PRO GFE-4.0 Electric Golf Cart		Asset located in: Lake Worth, TX
	(Unused) S/N: 202409096 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8425	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409114 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
8417	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused)		Asset located in: Lake Worth, TX
	S/N: 202409061 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8426	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 3702020241243 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available
8418	2024 HUNTER PRO GFE-4.0 Electric Golf Cart		Asset located in: Lake Worth, TX
	(Unused) S/N: 202409062 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8427	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 3702020241242 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8428	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 37020241100 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8435	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001636 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
8429	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409116 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	CONSITION. EXCESS INVENTORY STORED WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-I AND BATTERIES WILL NOT BE REPLACED E SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING	BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL
8430	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused)		INFORMATION AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX
	S/N: 37020241241 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in : Lake Worth, TX	8436	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8KPC001613
8431	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused)		C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	S/N: 37020241240 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS
8433	433 2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8CPC001632 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield		AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
			Asset located in: Lake Worth, TX
		8437	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8EPC001671 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE
	SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO	
8434	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001670 C/W: 48 Volt Battery Charger, 4 Passenger,		SELLER. PLEASE SEE SELLER SUPPLIED
	Canopy, Windshield, 5 kW Engine Usage: Not Available	8438	2023 Kandi KS4PSLR-MB Electric Golf Cart
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	(Unused) S/N: A07DE5W8TPC001673 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY	
		•	SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8439	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8EPC001606 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine	8443	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8TPC001656 C/W: 48 Volt Battery Charger, 4 Passenger, 5 kW Engine
	Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL		Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL
	INFORMATION AVAILABLE IN OFFICE - MSO ; Asset located in : Lake Worth, TX		INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in : Lake Worth, TX
8440	2023 Kandi KS4PSLR-MB Electric Golf Cart	8444	2023 Kandi KS4PSLR-R Electric Golf Cart
0440	(Unused) S/N: A07DE5W8VPC001633 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	0-7-7-	(Unused) S/N: A07DE5W8HPC001653 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8441	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)	8445	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused)
	S/N: A07DE5W8HPC001605 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8PPC001593 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX	2444	Asset located in: Lake Worth, TX
8442	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8LPC001604 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8446	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8JPC001662 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8447	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8TPC001687 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8451	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8KPC001689 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8448	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8CPC001646 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE	8452	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8CPC001677 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE
	CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8449	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)	8453	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)
	S/N: A07DE5W8JPC001600 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8VPC001602 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX	0.454	Asset located in: Lake Worth, TX
8450	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8JPC001676 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8454	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8APC001679 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8455	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8PPC001688 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS	8459 8460	Electric Golf Cart S/N: JW9-200800 C/W: Battery Charger, 2 Passenger, Canopy, Windshield, Utility Body Usage: Not Available Asset located in: Lake Worth, TX 2024 RCcar Electric 3 Person Scooter S/N: SLP2413080202 Usage: Not Available
	AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8461	Asset located in: Lake Worth, TX Quantity of (4) Synergy DP209 285/75R24.5 Tires S/N: Not Available C/W: All Tires with Wheels
8456	2023 Kandi KS4PSLR-W Electric Golf Cart		Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: A07DE5W8PPC001691 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8462	53 ft High Cube Storage Container S/N: GTJU968067 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8463	45 ft High Cube Storage Container S/N: HDHM94691473 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
8457	2023 Kandi KS4PSLR-W Electric Golf Cart		THESE Asset located in: Lahoma, OK
	(Unused) S/N: A07DE5W8TPC001690 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN	8464	2024 40 ft High Cube Multi-Door Storage Container S/N: CICU6930839 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8458	WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX 2023 Kandi KS4PSLR-W Electric Golf Cart (Uppeed)	8465	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0174629 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	(Unused) S/N: A07DE5W8VPC001678		Asset located in: Lake Worth, TX
	C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8466	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0174613 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8467	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0173793 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	8475	2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212025 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8476	2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212046	
8468	2024 40 ft High Cube Multi-Door Storage Container		C/W: One-Way Usage: Not Available Asset located in : Lake Worth, TX	
	S/N: JPCU0101019 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8477	40 ft High Cube Multi-Door Storage Container S/N: HHXU3309737 Usage: Not Available Asset located in : Lake Worth, TX	
	Asset located in: Lake Worth, TX	8478	2024 40 ft Multi-Door Storage Container	
8469	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU0101003 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		S/N: LYPU0173772 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TY	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8479	Asset located in: Lake Worth, TX 2024 40 ft Multi-Door Storage Container S/N: LYPU0173807 C/W: One-Way	
		_		
8470	2024 40 ft Multi-Door Storage Container S/N: XHCU5647588 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
8471	2024 40 ft High Cube Multi-Door Storage		Asset located in: Lake Worth, TX	
04/1	Container S/N: JPCU0101024 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	8480	2024 40 ft Multi-Door Storage Container S/N: XHCU5647593 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8481	2024 40 ft High Cube Multi-Door Storage Container	
8472	2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0026300 Usage: Not Available Asset located in: Lake Worth, TX		S/N: LYPU0173788 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8473	2024 40 ft High Cube Multi-Door Storage		Asset located in: Lake Worth, TX	
	Container S/N: RYDU0026260 Usage: Not Available Asset located in: Lake Worth, TX	8482	2024 40 ft High Cube Multi-Door Storage Container S/N: MMPU1045114 C/W: One-Way	
8474	2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0025562 Usage: Not Available Asset located in: Lake Worth, TX		C/W: One-Way Usage: Not Available Asset located in : Lake Worth, TX	

Lot #	Details	Lot #	Details
8483	2024 40 ft Multi-Door Storage Container S/N: LYGU0185801 Usage: Not Available	8493	20 ft Standard Open-Sided Storage Container S/N: SPRU2813880 Usage: Not Available
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF	8494	2024 20 ft Multi-Door Storage Container
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: XHCU2623751 Usage: Not Available
8484	<u> </u>		Asset located in: Lake Worth, TX
8484	2024 40 ft High Cube Storage Container S/N: DFCU1640658 C/W: One-Way Usage: Not Available	8495	2024 20 ft Multi-Door Storage Container S/N: XHCU2626766 Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8485	2024 40 ft High Cube Storage Container S/N: DFCU1640663 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8496	20 ft Standard Multi-Door Storage Container S/N: SPRU2807634 Usage: Not Available Asset located in: Humble, TX
0406	<u> </u>	8497	20 ft Standard Multi-Door Storage Container
8486	2024 40 ft High Cube Multi-Door Storage Container		S/N: SPRU2808250 Usage: Not Available
	S/N: LYGU4159586 C/W: One-Way Usage: Not Available		Asset located in: Humble, TX
		8498	20 ft Standard Multi-Door Storage Container
	Asset located in: Lake Worth, TX		S/N: SPRU2807871
8487	2024 40 ft High Cube Multi-Door Storage		Usage: Not Available Asset located in : Humble, TX
	C/W: One-Way	8499	20 ft Standard Multi-Door Storage Container
		0.55	S/N: SPRU2808266
	Usage: Not Available		Usage: Not Available Asset located in : Humble, TX
0.400	Asset located in: Lake Worth, TX	8500	·
8488	2024 40 ft High Cube Multi-Door Storage Container S/N: ZXJU0152117 C/W: One-Way Usage: Not Available	0300	2024 SHANG 20 ft One-Way Storage Container S/N: MCCU1088835
			Usage: Not Available
			Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8501	2024 20 ft Storage Container S/N: HYJU1077876
8489	2024 40 ft High Cube Multi-Door Storage	7	Usage: Not Available
	Container		Asset located in: Lake Worth, TX
	S/N: ZXJU0151928 C/W: One-Way	8502	2024 20 ft Storage Container
	Usage: Not Available		S/N: VSLU3245246 Usage: Not Available
0.400	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
8490	2024 40 ft High Cube Storage Container S/N: DFCU1640679	8503	2024 20 ft Standard Storage Container
	C/W: One-Way		S/N: MCCU1088917 Usage: Not Available
	Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8491	2024 40 ft High Cube Storage Container	8504	2024 20 ft Standard Double-Ended Storage
0471	S/N: SPRU9037160		Container
	C/W: One-Way Usage: Not Available		S/N: SPRU2611786 Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8492	20 ft Standard Open-Sided Storage Container	8505	20 ft Standard Storage Container
_	S/N: SPRU2813703		S/N: SPRU3086580
	Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX
			ASSEL IOCALEU III. LANE WOLLI, IA

N: SPRU3086189 age: Not Available set located in: Lake Worth, TX 24 20 ft Standard Storage Container N: SPRI3098791 age: Not Available set located in: Lake Worth, TX ft Standard Multi-Door Storage Container N: SPRU280883 age: Not Available set located in: Humble, TX 24 20 ft Standard Storage Container N: SPRU3078970 age: Not Available set located in: Lake Worth, TX ft Standard Multi-Door Storage Container N: SPRU3078970 age: Not Available set located in: Lake Worth, TX ft Standard Multi-Door Storage Container N: SPRU2812287 age: Not Available set located in: Humble, TX 24 20 ft Standard Double-Ended Storage	8520 8521 8522	20 ft Standard Storage Container S/N: AXIU2245734 C/W: Man Door, AC Unit Usage: Not Available Asset located in: Lake Worth, TX 20 ft Storage Container S/N: TCKU2807327 Usage: Not Available Asset located in: Humble, TX 20 ft Standard Storage Container S/N: CBHU3069110 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 2024 12 ft Storage Container S/N: GMPU9027419 C/W: Man Door, Window Usage: Not Available
N: SPRI3098791 age: Not Available set located in: Lake Worth, TX ft Standard Multi-Door Storage Container N: SPRU280883 age: Not Available set located in: Humble, TX 24 20 ft Standard Storage Container N: SPRU3078970 age: Not Available set located in: Lake Worth, TX ft Standard Multi-Door Storage Container N: SPRU2812287 age: Not Available set located in: Humble, TX 24 20 ft Standard Double-Ended Storage	8521	20 ft Storage Container S/N: TCKU2807327 Usage: Not Available Asset located in: Humble, TX 20 ft Standard Storage Container S/N: CBHU3069110 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 2024 12 ft Storage Container S/N: GMPU9027419 C/W: Man Door, Window
N: SPRU280883 age: Not Available set located in: Humble, TX 24 20 ft Standard Storage Container N: SPRU3078970 age: Not Available set located in: Lake Worth, TX ft Standard Multi-Door Storage Container N: SPRU2812287 age: Not Available set located in: Humble, TX 24 20 ft Standard Double-Ended Storage		20 ft Standard Storage Container S/N: CBHU3069110 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 2024 12 ft Storage Container S/N: GMPU9027419 C/W: Man Door, Window
N: SPRU3078970 age: Not Available set located in: Lake Worth, TX ft Standard Multi-Door Storage Container N: SPRU2812287 age: Not Available set located in: Humble, TX 24 20 ft Standard Double-Ended Storage	8522	Usage: Not Available Asset located in: Lake Worth, TX 2024 12 ft Storage Container S/N: GMPU9027419 C/W: Man Door, Window
ft Standard Multi-Door Storage Container N: SPRU2812287 age: Not Available set located in: Humble, TX 24 20 ft Standard Double-Ended Storage		S/N: GMPU9027419 C/W: Man Door, Window
_		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
ntainer N: SPRU2611575	8523	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
age: Not Available set located in: Lake Worth, TX		2024 12 ft Storage Container S/N: GMPU9027430 C/W: Man Door, Window
ft Standard Multi-Door Storage Container N: SPRU2810812 age: Not Available set located in: Humble, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
ft Standard Multi-Door Storage Container		Asset located in: Lake Worth, TX
N: SPRU2810833 age: Not Available set located in : Humble, TX	8524	2024 9 ft Storage Container S/N: GMPU9002935 C/W: Man Door, Window
ft Standard Storage Container N: SPRU3063223 age: Not Available set located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTA
ft Standard Storage Container		Asset located in: Lake Worth, TX
age: Not Available set located in: Lake Worth, TX	8525	2024 9 ft Storage Container S/N: GMPU9026027 C/W: Man Door, Window
ft Standard Storage Container N: APZU3578440 age: Not Available set located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
ft Standard Storage Container		Asset located in: Lake Worth, TX
age: Not Available set located in: Lake Worth, TX	8526	2024 9 ft Storage Container S/N: GMPU9026285 C/W: Man Door, Window
		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION (THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
N: se fi N: se fi N:	s SPRU3064493 ge: Not Available et located in: Lake Worth, TX t Standard Storage Container APZU3578440 ge: Not Available et located in: Lake Worth, TX t Standard Storage Container ECMU1513031 ge: Not Available	SPRU3064493 ge: Not Available et located in: Lake Worth, TX t Standard Storage Container APZU3578440 ge: Not Available et located in: Lake Worth, TX t Standard Storage Container ECMU1513031 ge: Not Available et located in: Lake Worth, TX 5 20 ft Storage Container HDMU2493989 EQUIPMENT-FROM-US-AUTO-RECYCLING

Lot #	Details	Lot #	Details
8527	2024 8 ft Storage Container S/N: GMPU9027893 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8534	2002 Storage Container S/N: XAH318284 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8528	2024 8 ft Storage Container	8535	Asset located in: Huntsville, TX
	S/N: GMPU9026520 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		40 ft High Cube Storage Container S/N: NYKU7937152 C/W: 2007 Carrier Transicold Reefer Unit Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8536	Quantity of (6) 2022 Box Gang 22 ft 30 YD Roll- Off Container
8529	2022 Suihe Storage Container S/N: LYPU00109 Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 5 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8530	7 ft Storage Container	8537	Quantity of (4) 22 ft 30 YD Roll-Off Container
	S/N: LYP710660 C/W: Window Usage: Not Available Asset located in : Lake Worth, TX		S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 5 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
8531	2024 7 ft Storage Container S/N: GMPU9027851 C/W: Man Door, Window		Notes: . Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8538	Quantity of (2) 2022 Box Gang 22 ft 40 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 6 ft 9 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
8532	2004 40 ft Storage Container		Notes: . Asset located in: Lake Worth, TX
0500	S/N: 749036 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Huntsville, TX	8539	Quantity of (2) 22 ft 20 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 4 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
8533	2002 40 ft Storage Container S/N: KKFU72268889	8540	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	0040	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 5 in Wide x 4 ft 11 in High Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Huntsville, TX	8541	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 4 in Wide x 5 ft 8 in High Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8542	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 6 in Wide x 5 ft 8 in High Usage: Not Available Asset located in: Lake Worth, TX	8552	2019 Mercedes-Benz Sprinter Van Passenger Van S/N: WD3PF0CD3KT003689 C/W: 3.0 L Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 167,464 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8543	18 ft Roll-Off Container (Unused) S/N: C202461 C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available		
	Asset located in: Lake Worth, TX	4	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8544	18 ft Roll-Off Container (Unused) S/N: C202462		Asset located in: Lake Worth, TX
	C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available Asset located in : Lake Worth, TX	8554	2011 Dodge Caravan SE Minivan S/N: 2D4RN5DG0BR682712 C/W: V6 3.6 L Gasoline Engine, 2011 US EPA
8545	17 ft Roll-Off Container (Unused) S/N: Not Available		Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 169,386 Mi
	C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;
8546	17 ft Roll-Off Container (Unused)		Asset located in: Lake Worth, TX
	S/N: C202462 C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available	8555	2021 Nissan Sentra Automobile S/N: 3N1AB8BV5MY267560 C/W: 4 cyl 2.0 L Gasoline Engine, 2021 US EPA
	Asset located in: Lake Worth, TX	_	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,
8547	Quantity of (2) Waste Container S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Rear View Camera Usage: 54,098 Mi Notes: TEXAS BUYERS MUST STOP IN OFF TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8548	1956 Chevrolet Bel Air Classic Car		Asset located in: Midland, TX
	S/N: VC56S103217 C/W: V8 5.7 L Gasoline Engine, Automatic Transmission, Air Conditioner Usage: 9,673 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;	8556	2019 Ford Fusion Automobile S/N: 3FA6P0HD8KR223201 C/W: 4 cyl 1.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 41,980 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
	Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS
8549	1976 Chevrolet Corvette Stingray Classic Car		Asset located in: Lake Worth, TX
	S/N: 1Z37L6S414551 C/W: V8 Gasoline Engine, Automatic Transmission, Power Windows Usage: 45,448 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;	8557	2019 Kia Optima Automobile S/N: 5XXGT4L3XKG357335 C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 61,987 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN
	Asset located in: Lake Worth, TX	_	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST
8551	2015 Ford E350 4x2 14-Seat Passenger Van S/N: 1FDE3FL1FDA16098 C/W: Air Conditioner, Automatic Transmission, Wheelchair Ramp, Wheelchair Lift, V8 5.4 L Gasoline Engine, 2014 US EPA Label, 225 /75R16, Spring Suspension, 158 in Wheelbase Usage: 103,717 Mi Notes: . Asset located in: Lake Worth, TX		STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8558	2018 Chevrolet Malibu Automobile S/N: 1G1ZF5SU0JF291884 C/W: 4 cyl 1.8 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 50,772 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8562	2015 Nissan Juke Automobile S/N: JN8AF5MR0FT505833 C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 147,550 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT;TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
8558A	2018 Ford Fusion Automobile S/N: 3FA6P0HD1JR180576 C/W: 4 cyl 1.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 83,930 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8563	2015 Chevrolet Impala Automobile S/N: 2G11Y5SN8F9263766 C/W: 6 cyl 3.6 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 92,389 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8559	2017 Nissan Altima Automobile S/N: 1N4AL3AP5HN317978 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: 67,245 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	8564	2014 Toyota Camry Automobile S/N: 4T4BF1FK5ER408856 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 138,538 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8560 8561	2016 Dodge Challenger Automobile S/N: 2C3CDZAG7GH256566 C/W: V6 3.6 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows Usage: 55,445 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A FLOODED BRAND ON THE TITLE Asset located in: Humble, TX 2016 Kia Optima Automobile S/N: 5XXGT4L38GG043240	8565	2013 Nissan Sentra RS Automobile S/N: 3N1AB7AP4DL790448 C/W: 4 cyl 1.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, sunroof Usage: 127,946 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	C/W: 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 176,089 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8566	2013 Mini Cooper Automobile S/N: WMWSS5C53DWN49392 C/W: 4 cyl 1.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 137,997 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8566A	2012 Subaru Outback AWD Automobile S/N: 4S4BRBLC3C3303630 C/W: 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 209,226 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8572	2018 Ford Expedition 4x4 SUV S/N: 1FMJU2ATXJEA25730 C/W: V6 3.5 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 130,626 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8568	2011 Toyota Camry Automobile S/N: 4T4BF3EK3BR115028 C/W: 4 cyl 2.4 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8573	2018 Nissan Pathfinder SV 2WD SUV S/N: 5N1DR2MN0JC605382 C/W: V6 3.5 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear View Camera Usage: 134,053 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED
8569	2008 Saab 9-3 Aero Automobile S/N: YS3FH41U081156520		DOCUMENTS Asset located in: Lake Worth, TX
	C/W: V6 2.8 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 160,781 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		2017 Ford Escape S 2WD SUV S/N: 1FMCU0F70HUB26560 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 134,079 Mi
8570	2007 BMW 328I Automobile S/N: WBAVC535X7FZ77345 C/W: 6 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 138,111 Mi	8575	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX		2017 Ford Escape 2WD SUV S/N: 1FMCU0GD9HUE71445 C/W: 3 cyl 1.5 L Gasoline Engine, 2017 US EPA
8571	2013 Jeep Wrangler 4WD 6-Door SUV S/N: 1C4HJWEG2DL570305 C/W: V6 3.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 57,484 Mi		Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 175,892 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
		8576	2017 Chevrolet Traverse LS 2WD SUV S/N: 1GNKRFKDXHJ203590 C/W: 6 cyl 3.6 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 187,718 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8577	2017 Chevrolet Trax 2WD SUV S/N: 3GNCJKSB6HL220642 C/W: 1.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 131,519 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8583	2016 Nissan Rogue SV SUV S/N: KNMAT2MT6GP624673 C/W: 4 cyl 2.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 159,117 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8578	2017 Chevrolet Tahoe 4WD SUV S/N: 1GNSKFEC1HR217144	0504	Asset located in: Humble, TX
	C/W: V8 5.3 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera Usage: 152,407 Mi Asset located in : Lake Worth, TX	8584	2016 Dodge Journey SUV S/N: 3C4PDCAB6GT219191 C/W: 4 cyl 2.4 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 3rd Row Usage: 88,015 Mi
8579	2016 Chevrolet Tahoe 4WD SUV S/N: 1GNSKFEC8GR440859 C/W: V8 5.3 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE
	Windows, Power Locks, Rear View Camera Usage: 145,373 Mi		Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8585	2016 Kia Soul Automobile S/N: KNDJP3A52G7276905 C/W: 4 cyl 2.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,
8580	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC5GR437584 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 155,738 Mi		Rear View Camera, Navigation Usage: 134,403 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	0506	Asset located in: Humble, TX
	PROCESS TITLE Asset located in: Lake Worth, TX	8586	2015 Infiniti QX60 2WD SUV S/N: 5N1AL0MN6FC525522
8581	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC6GR252511 C/W: V8 5.3 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Towing Hitch Usage: 202,310 Mi Asset located in: Lake Worth, TX		C/W: V6 3.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 132,145 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE
8582	2016 Nissan Rogue 2WD SUV		ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	S/N: JN8AT2MT0GW019414 C/W: 4 cyl 2.5 L Gasoline Engine, 2016 US EPA		Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 143,099 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8587	2015 Land Rover Range Rover 4WD SUV S/N: SALVP2BG7FH957087 C/W: 4 cyl Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 144,024 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8589	2015 Chevrolet Tahoe LS 2WD SUV S/N: 1GNSCAKC2FR521634 C/W: V8 5.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: 144,233 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8598	2006 BMW X5 4WD SUV S/N: 5UXFA13596LY40272 C/W: V6 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 189,977 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
8590	2014 Chevrolet Tahoe 2WD SUV	8599	2006 Chevrolet Suburban LT 4WD SUV
6590	S/N: 1GNLC2E03ER162966 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 197,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	6399	S/N: 1GNFK16Z86J170794 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Brush Guard and Rear Bumper., Towing Hitch Usage: 193,404 Mi Asset located in: Midland, TX
0500	<u> </u>	8600	2006 Chevrolet Tahoe Z71 4WD SUV
8592	2012 Ford Expedition 2WD SUV S/N: 1FMJK1K58CEF12802 C/W: V8 5.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 131,092 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; NTHIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Lake Worth, TX		S/N: 1GNEK13Z26R125089 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 229,606 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
8593	2011 Jeep Grand Cherokee 2WD SUV		Asset located in: Humble, TX
0090	S/N: 1J4RS4GGXBC513599 C/W: V6 3.6 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 168,573 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8602	2019 Chevrolet Silverado 3500HD 4x4 Crew Cab Pickup S/N: 1GC4KVCG9KF138086 C/W: V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11000 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 79,152 Mi Asset located in: Lake Worth, TX
8594	2009 Chevrolet Suburban LT SUV	8605	2018 Ford F-350 XL 4x4 Crew Cab Pickup
	S/N: 1GNFC26J89R299573 C/W: 6 cyl 5.3 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Towing Hitch Usage: 301,880 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 1FT8W3BT1JEC94927 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11500 lb GVWR, 275/65R18 Tires, 8 ft Bed Usage: 44,439 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8596	2007 Cadillac Escalade 2WD SUV	8607	2018 Ford F-350 XLT 4x4 Crew Cab Pickup
	S/N: 1GYEC63867R384531 C/W: 6.2 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row, Towing Hitch Usage: 137,706 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 1FT8W3BT2JEC44330 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, Drop-In Bed Liner, 11500 lb GVWR, 275/70R16 Tires, 8 ft Bed Usage: 186,195 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8608A	2015 Ford F-350 4x4 Crew Cab Pickup S/N: 1FT8W3BT8FEB31733 C/W: 6.7 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear Power Lift Gate, Weather Guard Tool Box, Spray-On Bed Liner, 11200 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: Not Available Asset located in: Lake Worth, TX	8614	2009 Chevrolet Silverado 3500HD 4x2 Crew Cab Pickup S/N: 1GCJC83619F178424 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Window Dual Rear Wheel, Spray-On Bed Liner, 11400 lt GVWR, 245/75R17 Tires, 8 ft Bed Usage: 368,242 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
8608B	2016 Ford F-350 XLT 4x4 Crew Cab Pickup		PROCESS TITLE Asset located in: Lake Worth, TX
	S/N: 1FT8W3BT4GED37892 C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Spray-On Bed Liner, 11500 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 252,228 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8614A	2012 Ford F-350 4x4 Extended Cab Pickup S/N: 1FT8X3BT4CEA06351 C/W: 6.7 L Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 275 /70R18 Tires, 8 ft 3 in Bed Usage: 252,510 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8609	2011 Ford F-350 XLT 4x4 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FT8W3BT0BEC51343 C/W: 6.7 L V8 Diesel Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Drop-In Bed Liner, 11200 lb GVWR, 35x12.50R22 Tires, 8 ft Bed Usage: 106,357 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX	8618	2023 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5DL0PG517224 C/W: 6.7 L V8 Diesel Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 10000.0 lb GVWR, 37X12.50R20 Tires, 6 ft 4 in Bed Usage: 12,741 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;
8611	1999 Ford F-350 4x4 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FTSW31F2XEA09050 C/W: Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, 9900 lb GVWR, 295/60R20 Tires, 8 ft Bed Usage: 263,566 Mi Asset located in: Humble, TX	8619	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ7MG630043 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS-
8612	2 2013 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3CT8DEB22137 C/W: 6.7 L Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Dual Rear Wheel, Spray-On Bed Liner, 14000.0 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 386,746 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		SERVICES-CORP-COMPANY Usage: 65,623 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
		8620	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ8MG631265 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 122,390 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8621	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ2MG631262 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 275/70R18 Tires, 8 ft 1 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 176,662 Mi Asset located in: Lake Worth, TX	8624	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ6JG354370 C/W: 6.4 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000.0 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 167,897 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8622	2021 Ram 2500 4x4 Crew Cab Pickup (Inoperable)		Asset located in: Lake Worth, TX
S/N: 3C6UR5HJ5MG631241 C/W: 6.4 L V8 Gasoline Engine, 2021 US EP Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Ra RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMO SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMO FROM YARD BY JANUARY 10TH AND CAN BE RELISTED; BUYER'S RESPONSIBILITY F	S/N: 3C6UR5HJ5MG631241 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	8625	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL8JG274920 C/W: 6.7 L Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-O Bed Liner, 10000 lb GVWR, 275/65R18 Tires, 6 ft 4 in Bed Usage: 197,428 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICITO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	OFFICE TO SIGN REQUIRED DOCUMENTS;		Asset located in: Lake Worth, TX
	EQUIPMENT FROM A PRIMORIS SERVICES CORP COMPANY Asset located in: Lake Worth, TX	8626	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL3JG148321 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US
8623	S/N: 3C6UR5CJ3JG404410 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 96,524 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 2 in Bed Usage: 159,765 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
		8627	8627 2017 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL0HG589107 C/W: 6.7 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner,
8623A			Power Driver's Seat, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 6 ft 4 in Bed Usage: 196,427 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
	Bed Usage: 122,776 Mi	8628	2017 Ram 2500 4x4 Crew Cab Pickup
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 3C6UR5CL9HG570121 C/W: 6.7 L 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 35X12.50R20 Tires, 6 ft 2 in Bed Usage: 133,929 Mi
			Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Details 2021 Ford F-250 King Ranch 4x4 Crew Cab Pickup S/N: 1FT7W2BT9MEC11318 C/W: 6.7 L V8 Diesel Engine, 2021 US EPA	Lot # 8633	Details 2019 Ford F-250 XL 4x4 Crew Cab Pickup
Pickup S/N: 1FT7W2BT9MEC11318	8633	•
Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 10000 lb GVWR, 275 /65R20 Tires, 7 ft Bed Usage: 16,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8634	S/N: 1FT7W2B63KEF04896 C/W: 6.2 L V8 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 6 ft 6 in Bed Usage: 142,484 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2019 Ford F-250 XL 4x4 Crew Cab Pickup
Asset located in: Lake Worth, TX	4	S/N: 1FT7W2B6XKEF04796 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA
2020 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63LEE12818 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, PROTECH Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265770R17 Tires, 8 ft 2 in Bed		Label, Automatic Transmission, Air Conditioner, Headache Rack, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 176,645 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
3		Asset located in: Lake Worth, TX
TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	S/N: 1FT7W2BT1KEE55378 C/W: 6.7 L V8 Diesel Engine, 201 Label, Automatic Transmission, Conditioner, Power Windows, Su Built 100 gal Fuel Tank /w Pump Liner, 10000 lb GVWR, 35x12.50l 8 in Bed Usage: 145,565 Mi Notes: TEXAS BUYERS MUST ST	C/W: 6.7 L V8 Diesel Engine, 2019 US EPA
2020 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B66LEE12831 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 153,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Conditioner, Power Windows, Sunroof, Better Built 100 gal Fuel Tank /w Pump, Drop-In Bed Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 8 in Bed Usage: 145,565 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	8636	2016 Ford F-250 4x4 Crew Cab Pickup
		S/N: 1FT7W2BT2GEA52971
2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2B68KED41291 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 139,607 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8637	C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 7 ft Bed Usage: 121,086 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2013 Ford F-250 Lariat 4x4 Crew Cab Pickup S/N: 1FT7W2BT3DEA48102 C/W: 6.7 L V8 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 35x12.5R20 Tires, 6 ft 10 in Bed Usage: 226,784 Mi
	Usage: 16,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2020 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63LEE12818 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, PROTECH Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed Usage: 140,719 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2020 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B66LEE12831 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 153,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2B68KED41291 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 139,607 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	Usage: 16,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2020 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63LEE12818 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, PROTECH Tool Box, Spray-On Bed Liner, 10000 Ib GVWR, 265/70R17 Tires, 8 ft 2 in Bed Usage: 140,719 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2020 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B66LEE12831 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 Ib GVWR, 265 //70R17 Tires, 8 ft Bed Usage: 153,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2B68KED41291 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 Ib GVWR, 265/70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 139,607 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE

Lot #	Details	Lot #	Details
8638	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19ME73MF197398 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 104,683 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8642	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE73MF131055 C/W: 6.6 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 112,785 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8639	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE75MF221517 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 119,305 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8643	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223689 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 115,084 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8640	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19ME74MF197121 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 106,361 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8644	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF222266 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,468 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8641	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE72MF223676 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 109,870 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8645	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223837 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Rawson Koenig Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8646	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE79MF223755 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 131,224 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8650	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG9KF243775 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 9900 lb GVWR, 265 /70R17 Tires, 8 ft Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 121,440 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8647	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF135301 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 105,910 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8651	2019 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12NEG7KF143089 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, Tool Box, 265 /70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 130,846 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8648	Asset located in: Lake Worth, TX 2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG8KF128147 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 103,405 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	-8652	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEGXKF172537 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 121,433 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8649	2019 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF172137 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 117,114 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8653	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF273565 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 245 /75R17 Tires, 8 ft Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 121,235 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8654	2018 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12REG3JF174233 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 128,754 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	8659 8660	2019 Chevrolet Silverado 2500 HD LT 4x4 Crew Cab Pickup S/N: 1GC1KSEY0KF118493 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fuel Tank, 10000.0 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2019 Chevrolet Silverado 2500 HD 4x4 Crew
	Asset located in: Lake Worth, TX	4	Cab Pickup
8655	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12REG6JF173030 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 156,754 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE		S/N: 1GC1KSEG2KF213547 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 245 /75R17 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 138,145 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8656	Asset located in: Lake Worth, TX 2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup	8661	2019 Chevrolet 2500HD Z71 4x4 Crew Cab
	S/N: 1GT12REG5JF173486 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 158,292 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX		Pickup S/N: 1GC1KTEG8KF220198 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 9500 lb GVWR, 275/65R18 Tires, 6 ft Bed, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 144,285 Mi Asset located in: Lake Worth, TX
8657		8662	2017 Chevrolet Silverado 2500 HD 4x4 Crew
8037	2016 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12RE87GF259741 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 169,025 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8002	Cab Pickup S/N: 1GC1KUEG5HF192312 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 128,022 Mi
	PROCESS TITLE		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
8658	Asset located in: Lake Worth, TX 2014 GMC Sierra 2500HD 4x4 Crew Cab Pickup	-	PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	S/N: 1GT12ZCG9EF123876 C/W: V8 Gasoline Engine, Automatic		Asset located in: Lake Worth, TX
	Transmission, Air Conditioner, Power Windows, Headache Rack, 9900 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 162,483 Mi Asset located in: Lake Worth, TX	8663	2017 Chevrolet Silverado 2500 HD LT Z71 4x4 Crew Cab Pickup S/N: 1GC1KVEG8HF198725 C/W: 6.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 6 ft Bed, Wireless Charging Usage: 149,617 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
			Accet leasted in Lake Worth TV

Lot #	Details	Lot #	Details
8664	2012 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KVCG5CF145928 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 322,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8669A	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A66HEC56637 C/W: 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, WeatherGuard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 205,176 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8667	2019 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A66KED56261 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 122,599 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	8670	2015 Ford F-250 4x2 Crew Cab Pickup S/N: 1FT7W2A64FEC22645 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 268,869 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8667A	2019 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A65KEC11406 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, 10000 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 204,188 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8671	2014 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A69EEB42367 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear Power Lift Gate, Aluminum Truck Cap, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed Usage: 173,752 Hr Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX
8668	2018 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A69JEC58484 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weatherguard Tool Box, 10000 lb GVWR, 265/70R15 Tires, 8 ft Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 157,129 Mi Asset located in: Humble, TX 2017 Ford F-250 XL 4x2 Crew Cab Pickup	8672	2021 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ6MG648396 C/W: 6.4 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 166,144 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	S/N: 1FT7W2A61HEE08405 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 176,168 Mi Asset located in: Humble, TX	8674	2019 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ6KG603858 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6800.0 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 170,384 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8676	2019 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ7KG631829 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 180,148 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8680A	2016 Ford F-250 4x4 Extended Cab Pickup S/N: 1FT7X2BT8GEC22330 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 8 ft Bed Usage: 154,291 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8677	2018 Ram 2500 4x2 Crew Cab Pickup	8681	2015 Ford F-250 XL 4x4 Extended Cab Pickup
	S/N: 3C6UR4HJ1JG188981 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires Usage: 204,579 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8681	S/N: 1FT7X2B61FEB25480 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Fuel Tank /w Pump, Tractor Supply Co Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 2 in Bed Usage: 111,775 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8678	2018 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ8JG287331		Asset located in: Lake Worth, TX
	C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Fuel Tank, Weather Guard Tool Box, 10000 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 175,042 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8682	2015 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B61FEC04213 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 320,450 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8679	2015 Chevrolet 2500HD 4x4 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1GC1KWE89FF640746 C/W: 6.6 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 7 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A BONDED TITLE; Asset located in: Lake Worth, TX	8683	2018 Chevrolet Silverado 2500 HD 4x4 Dual Cab Pickup S/N: 1GC2KWEG9JZ193614 C/W: 6.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 162,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8680	2020 Ford F-250 XL 4x4 Extended Cab Pickup	8684	2016 Chevrolet 2500HD 4x4 Extended Cab
	S/N: 1FT7X2B68LEC63951 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 166,422 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Pickup S/N: 1GC2KUEG4GZ109955 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 9500.0 lb GVWR, 8 ft Bed Usage: 355,555 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8686	2017 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A64HEF24694 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 192,889 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8691	2014 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A6XEEA58748 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, WeatherGuard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 312,914 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8687	2017 Ford F-250 XL 4x2 Extended Cab Pickup	0602	Asset located in: Lake Worth, TX
	S/N: 1FT7X2A65HEB28242 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 238,717 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8692	2014 Ford F-250 4x2 Extended Cab Pickup S/N: 1FT7X2A67EEB17769 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 191,870 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
	PROCESS TITLE Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8688	2016 Ford F-250 XL 4x2 Extended Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FT7X2A69GEC19075 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 10000.0 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 199,413 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8693	2012 Chevrolet Silverado 2500HD 4x2 Extended Cab Pickup S/N: 1GC2VC83CZ320119 C/W: 6.6 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 7 in Bed Usage: 279,928 Mi
	Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
8689	2016 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A69GEB70864		PROCESS TITLE
	C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA		Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 10 in Bed Usage: 201,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8693A	2008 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FTSX20578EE54529 C/W: 5.4 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, 9200 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 331,802 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8690	2014 Ford F-250 4x2 Extended Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FT7X2A66EEB24227 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, GPI Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 195,848 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8694	2020 Ram 2500 4x4 Pickup S/N: 3C6MR5AJ9LG164012 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 102,553 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8695	2020 Ram 2500 4x4 Pickup S/N: 3C6MR5AJ5LG164010 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 107,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8699	2012 Chevrolet Silverado 2500 HD LS 4x2 Pickup S/N: 1GC0CVCG6CF138379 C/W: 6.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 8 ft 3 in Bed Usage: 223,391 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
8696	2017 Chevrolet Silverado 2500 HD 4x4 Pickup S/N: 1GC0KUEG2HZ225955 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 99,657 Mi Asset located in: Lake Worth, TX	8700	2022 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTU9DED3NZ162699 C/W: 5.3 L V8 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 275/65R18 Tires, 6 ft	
8697	7 2015 Ram 2500 4x2 Pickup S/N: 3C6LR4AT0FG649313 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 9000 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 106,565 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		Bed Usage: 102,807 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	
		8701	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED4MG242107 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7100 lb GVWR, 275 /60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-	
8697A	Asset located in: Lake Worth, TX 2015 Ford F-250 4x2 Pickup S/N: 1FTBF2ATXFEA40769 C/W: 6.7 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft	8702	Usage: 97,407 Mi Notes: TEXAS BUYERS MUST STO TO SIGN REQUIRED DOCUMENTS SEE A PERSONAL NOTE FROM T	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
	Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		S/N: 3GTU9DEDXMG239485 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Powe Seat, Power Windows, 7100 lb GVWF /60R20 Tires, 5 ft 8 in Bed, EQUIPME	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DEDXMG239485 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7100 lb GVWR, 275 /60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION
8698	2013 Ford F-250 4x2 Pickup S/N: 1FTBF2A60DEB82104 C/W: 6.2 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Truck Cap, 10000 lb GVWR, 245/70R17 Tires Usage: 81,563 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Usage: 107,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOV Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8703	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED3MG200127 C/W: 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 255/70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 117,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8705A	2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTP9EEL1LZ336096 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Drop-In Bed Liner, 7000 Ib GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 113,313 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8704	2021 GMC 1500 4x4 Crew Cab Pickup	8706	2020 GMC Sierra 1500 4x4 Crew Cab Pickup
	S/N: 3GTU9DED6MG240892 C/W: 5.3 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 265/60R18 Tires, 6 ft Bed Usage: 116,077 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8700	S/N: 3GTU9DED0LG267777 C/W: 5.3 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 130,184 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8704A			Asset located in: Lake Worth, TX
07U4A	S/N: 3GTU9BED2MG205545 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 109,324 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8707	2014 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU2TECXEG385182 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 265/70R17 Tires, 5 ft 9 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 127,548 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8705	2020 GMC Sierra 1500 4x4 Crew Cab Denali Pickup S/N: 1GTU9FEL4LZ152697 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Spray-On Bed Liner, 7100 lb GVWR, 5 ft 7 in Bed Usage: 98,858 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8708	2016 Chevrolet Silverado 1500 LT 4x4 Crew Cab Pickup S/N: 1GCUKREC4GF141714 C/W: 5.3 L V8 Gasoline Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Decked Tool Box, Drop-In Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 263,036 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX

Lot #	Details	Lot #	Details
8709	2020 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFLT1LN227445 C/W: 5.7 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Tonneau Cover, 7100 lb GVWR, 265/65R18 Tires, 5 ft 7 in Bed Usage: 123,133 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8713	2017 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7LT4HS620059 C/W: 5.7 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6900 lb GVWR, 275 /65R20 Tires, 5 ft 6 in Bed Usage: 130,275 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED
8709A	S/N: 1C6SRFLT1LN333989		DOCUMENTS Asset located in: Lake Worth, TX
	C/W: 5.7 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 275/70R18 Tires, 5 ft 6 in Bed Usage: 144,587 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8714	2016 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7MT0GS416856 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 6900 lb GVWR, 6 ft 5 in Bed, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY
8710	S/N: 1C6SRFFT7KN714613 C/W: 5.7 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 7100.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 129,734 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Usage: 88,711 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
		8715	2018 Toyota Tundra 4x4 Crew Cab Pickup S/N: 5TFDW5F19JX740667 C/W: 5.7 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 275/70R18 Tires, 5 ft 7 in Bed Usage: 260,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8711	2019 Ram 1500 Big Horn 4x4 Crew Cab Pickup S/N: 1C6SRFFT3KN739606	-	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100.0 lb GVWR, 285/65R18 Tires, 5 ft 3 in Bed Usage: 196,574 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2019 Ram 1500 Laramie 4x4 Crew Cab Pickup	8716	2017 Toyota Tundra SR5 4x4 Crew Cab Pickup S/N: 5TFUW5F16HX610386 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Spray-On Bed Liner, 7100 lb GVWR, 275 /55R20 Tires, 6 ft Bed Usage: 262,750 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
5,12	S/N: 1C6SRFJT8KN822441 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 265/60R18 Tires, 5 ft 7 in Bed Usage: 165,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8717	2016 Toyota Tundra 4x4 Crew Cab Pickup S/N: 5TFDW5F12GX506041 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 285/65R18 Tires, 5 ft 6 in Bed Usage: 276,601 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8718	S/N: 5TFDW5F17GX526706 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray- On Bed Liner, 7200.0 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 323,409 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8722	2020 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1E53LKD47734 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Protech Tool Box, Spray-On Bed Liner, 7000 lb GVWR, 265 /70R17 Tires, 5 ft 6 in Bed Usage: 121,047 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
		8723	2020 Ford F-150 Lariat 4x4 Crew Cab Pickup
8719	2018 Nissan Titan Platinum Reserve 4x4 Crew Cab Pickup S/N: 1N6AA1E55JN509451 C/W: 5.6 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Tool		S/N: 1FTEW1E52LKE45508 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 119,650 Mi Asset located in: Lake Worth, TX
	Box, Spray-On Bed Liner, 7300 lb GVWR, 275 /60R20 Tires, 5 ft 7 in Bed	8724	2019 Ford F-150 STX 4x4 Crew Cab Pickup
0700	Usage: 2,600 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; ODOMETER DISCREPENCY - ODOMETER SHOWS 2600 TITLE SHOWS 105570 Asset located in: Lake Worth, TX		S/N: 1FTEW1E56KKC96325 C/W: 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed Usage: 90,968 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8720	2021 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E55MKD34831		Asset located in: Humble, TX
	C/W: 5.0 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050.0 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 96,289 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8724A	2019 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1E40KKD90146 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 275/65R18 Tires, 6 ft 6 in Bed Usage: 147,441 Mi
	Asset located in: Lake Worth, TX	4	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
8721	2020 Ford F-150 XL 4x4 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FTEW1E58LKD34168 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 245/70R17 Tires, 5 ft 7 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 96,164 Mi	8725	2019 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E49KKC43100 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 140,907 Mi
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8726	2018 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1EG1JKD95560 C/W: 3.5 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 245/75R17 Tires, 7 ft Bed Usage: 124,873 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8730	2014 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF3EFA28438 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7350 lb GVWR, 275/65R18 Tires, 5 ft 6 in Bed Usage: 167,074 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8727	2017 Ford F-150 4x4 Crew Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FTEW1EP9HFB20551 C/W: 2.7 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6500 lb GVWR, 33x12.50R18 Tires, 6 ft Bed Usage: 96,312 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED	8731	2013 Ford F-150 Raptor 4x4 Crew Cab Pickup S/N: 1FTFW1R66DFA62527 C/W: 5.4 L V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, 7450 lb GVWR, 315/70R17 Tires, 5 ft 6 in Bed Usage: 80,237 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; TRUE MILEAGE UNKNOWN Asset located in: Lake Worth, TX
	DOCUMENTS Asset located in: Lake Worth, TX	8732	2013 Ford F-150 XL 4x4 Crew Cab Pickup
8727A	2017 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTFW1EF7HKD98738 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 100,730 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		S/N: 1FTFW1ET9DKF21987 C/W: 3.5 L V6 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Better Built Tool Box, 7200 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 100,112 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8735	2011 Dodge Ram 1500 4x4 Crew Cab Pickup
8728	2016 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1EF5GFA47779 C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 155,109 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	18/35	S/N: 1D7RV1GT9BS552169 C/W: V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6700 lb GVWR, 275/65R20 Tires, 6 ft 8 in Bed Usage: 154,689 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPENCY - ODOMETER SHOWS 154689 TITLE SHOWS 155742 Asset located in: Lake Worth, TX
8729	2014 Ford F-150 XLT 4x4 Crew Cab Pickup	0706	
	S/N: 1FTFW1EF4EKF62314 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7350 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 99,175 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8736	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CP5JKD52645 C/W: 2.7 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, 6360 lb GVWR, 265 /60R18 Tires, 5 ft 8 in Bed Usage: 121,549 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPANCY- UNIT SHOWS 121,549, TITLE SHOWS 139,907 Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8737	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C56JKC10769 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 ft Bed, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 145,418 Hr Asset located in: Humble, TX	8742	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CFXHKE23730 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 86,433 Mi Asset located in: Humble, TX
8738	2018 Ford F-150 XLT 4x2 Crew Cab Pickup	8743	2017 Ford F-150 XL 4x2 Crew Cab Pickup
	S/N: 1FTEW1C52JKC10770 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 146,917 Mi		S/N: 1FTEW1CF5HKC49971 C/W: 5.0 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, Spray-On Bed Liner, 6800 lb GVWR, 245/70R17 Tires, 5 ft 6 in Bed Usage: 119,231 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	0744	<u>.</u>
8739	S739 2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1C54JKC10768 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Weatherguard Tool Box, Drop-In Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 120,300 Mi	8744	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF0HKE23722 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 4 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 119,473 Mi
	Asset located in: Humble, TX	<u></u>	Asset located in: Humble, TX
8740	2018 Ford F-150 Lariat 4x4 Crew Cab Pickup S/N: 1FTEW1E52JKE26129 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7000 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 109,847 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8745	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF2HKE53076 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 7 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 140,099 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	8746	2017 Ford F-150 XLT 4x2 Crew Cab Pickup
8741	2018 Ford F-150 Lariat 4x4 Crew Cab Pickup S/N: 1FTEW1E58JFD71503 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 121,466 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 1FTEW1CF6HKE23725 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 5 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 142,764 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8747	2017 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1CP8HKD86640 C/W: 2.7 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6260 lb GVWR, 275/55R20 Tires, 5 ft 5 in Bed Usage: 199,080 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8752	2019 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFRM5F17KX141585 C/W: 4.6 L V8 Gasoline Engine, 2019 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Craftsman Tool Box, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 195,476 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8748	2016 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTEW1CF9GKF65372 C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 6950 lb GVWR, 255/70R17 Tires, 6 ft 5 in Bed Usage: 196,241 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8754	2016 Ram 1500 SLT 4x2 Crew Cab Pickup S/N: 1C6RR6GG7GS403918 C/W: 3.6 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6800 lb GVWR, 275/55R20 Tires, 6 ft 3 in Bed Usage: 67,066 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8755	2014 Ram 1500 4x2 Crew Cab Pickup
8749	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF4EKG33790 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 6 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 129,930 Mi Asset located in: Humble, TX		S/N: 1C6RR6KM8ES408801 C/W: 3.0 L V6 Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6800 lb GVWR, 265/70R17 Tires, 5 ft 10 in Bed Usage: 266,474 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8750	2014 Ford F-150 XLT 4x2 Crew Cab Pickup		Asset located in: Lake Worth, TX
8751	S/N: 1FTFW1CF3EKG33800 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 133,616 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Ford F-150 XL 4x2 Crew Cab Pickup	8756	2014 GMC Sierra 1500 4x2 Crew Cab Pickup S/N: 3GTP1UEC6EG110768 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7000 lb GVWR, 275/55R20 Tires, 6 ft 7 in Bed Usage: 216,631 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED
	S/N: 1FTFW1CFXEKG11583 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air		DOCUMENTS Asset located in: Lake Worth, TX
	Conditioner, Headache Rack, Tool Box, Spray- On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 322,798 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8757	2010 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFTM5F17AX001055 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 255/70R18 Tires, 8 ft Bed Usage: 244,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8758	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTR9AEHXMZ203075 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 107,212 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; PLEASE SEE A PERSONAL NOTE FROM THE	8762	2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC6HZ350529 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 189,063 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	
	SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8763	2015 Chevrolet Silverado 1500 4x4 Extended Cab Pickup	
8759	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTR9AEH4MZ201452 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 113,431 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL		S/N: 1GCVKPEHS C/W: Gasoline En Transmission, Air Windows, RKI Too 7100.0 lb GVWR, Usage: 91,050 Mi Notes : TEXAS BU TO SIGN REQUIRI PROCESS TITLE;	S/N: 1GCVKPEH5FZ173329 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, Drop-In Bed Liner, 7100.0 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 91,050 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE
	MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS;	8764	Asset located in: Lake Worth, TX 2015 Chevrolet Silverado 1500 4x4 Extended	
	PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8765	Cab Pickup S/N: 1GCVKREC2FZ382091 C/W: 5.3 L V8 Gasoline Engine, 2015 US EPA	
8760	2019 Chevrolet Silverado 1500 LT 4x4 Dual Cab Pickup S/N: 1GCRYDED9KZ191418 C/W: 5.3 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 265/65R18 Tires, 6 ft 8 in Bed		Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 231,215 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	
	Usage: 148,223 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		2018 GMC Sierra 1500 4x4 Extended Cab Pickup	
8761	Asset located in: Lake Worth, TX 2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC3HZ107938 C/W: 5.3 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 7200 lb GVWR, 295/55R20 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-HERC-RENTALS Usage: 63,030 Mi		Transmission, Air Conditioner, Pov 7200 lb GVWR, 265/70R17 Tires, 6 EQUIPMENT-FROM-5J-GROUP Usage: 227,149 Mi Notes: DEFICIENCIES NOTED - PLI THE INSPECTION REPORT; TEXAS	C/W: 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 7200 lb GVWR, 265/70R17 Tires, 6 ft 9 in Bed, EQUIPMENT-FROM-5J-GROUP Usage: 227,149 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT EQUIPMENT FROM	8766	2016 Ram 1500 4x4 Extended Cab Pickup	
	HERC RENTALS; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		S/N: 1C6RR7FT9GS207693 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 285/70R17 Tires, 6 ft Bed Usage: 177,486 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8767	2015 Ram 1500 4x4 Dual Cab Pickup S/N: 1C6RR7GMXFS671274 C/W: 3.0 L V6 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6950 Ib GVWR, 35x12.5R20 Tires, 6 ft 3 in Bed Usage: 137,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8769	2018 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E53JKE13763 C/W: 5.0 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 149,967 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8768	2015 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7GT4FS643767 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6900 lb GVWR, 275/60R20 Tires, 6 ft 3 in Bed Usage: 118,037 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8770	2016 Ford F-150 XLT 4x4 Extended Cab Pickup S/N: 1FTFX1EF6GFB81556 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7050 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 127,639 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8768A	Asset located in: Lake Worth, TX 2023 Ford F-150 XL 4x4 Extended Cab Pickup	8771	2012 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTEX1EM1CFC36807 C/W: 3.7 L V6 Gasoline Engine, US EPA Label,
8768B	S/N: 1FTFX1E52PKE72666 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 7150 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 25,106 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2023 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E52PKE96014 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2023 US		Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 275/65R18 Tires, 6 ft 10 in Bed Usage: 84,649 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; ODOMETER DISCREPANCY-UNIT SHOWS 84,649, TITLE SHOWS 182,835 Asset located in: Lake Worth, TX
	EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7150 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 29,947 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		2006 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V36Z259882 C/W: 4.8 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air
8768C	Asset located in: Lake Worth, TX 2023 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTFX1E54PKE88612 C/W: 5.0 L V8 Gasoline Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack,		Conditioner, Power Windows, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 129,610 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	RKI Tool Box, Spray-On Bed Liner, 7150 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 35,130 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8773	2004 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V84Z272706 C/W: 4.8 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6400 lb GVWR, 245/75R16 Tires, 6 ft 10 in Bed Usage: 172,966 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS

Lot #	Details	Lot #	Details
8774	2021 Chevrolet Silverado 4x2 Extended Cab Pickup S/N: 1GCRWAEH8MZ261016 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 kg GVWR, 255/70R17 Tires, 7 ft Bed Usage: 164,523 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8780	2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C89HKC50152 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 5 in Bed Usage: 169,011 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8775	2014 Chevrolet Silverado 1500 4x2 Extended Cab Pickup S/N: 1GCRCPEC8EZ211055 C/W: V8 Gasoline Engine, Air Conditioner, Power Windows, Tonneau Cover, Spray-On Bed Liner, 7000 lb GVWR, 37x13.5R24LT Tires, 6 ft 8 in Bed Usage: 26,768 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8781	2015 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CFXFKE52008 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 199,497 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8776	2019 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C43KKE83254 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 255/70R18 Tires, 6 ft 6 in Bed Usage: 139,472 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8782	2015 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1CF9FKE51996 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 219,104 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8777	2018 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C56JKF84490 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 4 in Bed Usage: 135,767 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8783	2014 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTFX1CF8EKF95610 C/W: 5.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 7 in Bed Usage: 209,297 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8778	2018 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C55JKF84478 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 172,916 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8784A	2009 Dodge Ram 1500 4x4 Pickup S/N: 1D3HV16P59J518182 C/W: 4.7 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6350 lb GVWR, 285/70R17 Tires, 6 ft 5 in Bed Usage: 92,230 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8785	2005 Chevrolet Silverado 1500 4x4 Pickup S/N: 1GCEK14V55Z288807 C/W: 4.8 L V8 Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft 5 in Bed Usage: 99,043 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8791	2018 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1E55JKF44493 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray- On Bed Liner, 6950 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 140,414 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8786	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH3FZ285656	8792	Asset located in: Lake Worth, TX 2017 Ford F-150 XL 4x2 Pickup
	C/W: 4.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 125,012 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	6772	S/N: 1FTMF1CF4HKD34876 C/W: 5.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, protech Tool Box, Spray-On Bed Liner, 6750 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 117,485 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8788	2014 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH7EZ346442 C/W: 4.3 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 114,136 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;	8793	2010 Ford F-150 4x2 Pickup S/N: 1FTMF1CW8AKE17930 C/W: 4.7 L V6 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6750 lb GVWR, 235/75R17 Tires, 8 ft 5 in Bed Usage: 126,592 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8789	2013 Chevrolet 1500 4x2 Pickup S/N: 1GCNCPEA5DZ356873 C/W: 4.8 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 74,650 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN	8794	2003 Ford F-150 4x2 Pickup S/N: 2FTRF17L83CB00193 C/W: 5.4 L V8 Gasoline Engine, 2003 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6050 lb GVWR, 235/75R16 Tires, 8 ft 4 in Bed Usage: 94,369 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	OFFICE TO SIGN REQUIRED DOCUMENTS; ODOMETER DISCREPANCY-UNIT SHOWS 74,650, TITLE SHOWS 145,093; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8795	1989 GMC Sierra 2500 4x2 Pickup S/N: 1GTFC24C1KE543722 C/W: V8 Diesel Engine, 4 Speed Manual Transmission, Drop-In Bed Liner, 72000 lb GVWR, 225/75R16 Tires, 8 ft Bed, EQUIPMENT- FROM-YELLOW-CORP
8790	2020 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1C50LKD46068 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA		Usage: 113,113 Mi Asset located in: Midland, TX
		8796	2022 Ford Ranger 4x2 Crew Cab Pickup S/N: 1FTER4EH5NLD35536 C/W: 2.3 L 4 Cylinder Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 3500 lb GVWR, 265/70R16 Tires, 5 ft Bed Usage: 20,876 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8797	2021 Chevrolet Colorado 4x2 Crew Cab Pickup S/N: 1GCGSCEN1M1296032 C/W: 2.5 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 5800 lb GVWR, 255/65R17 Tires, 5 ft Bed Usage: 47,944 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8803	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE1LN721210 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 109,927 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8798	2022 Chevrolet Colorado 4x2 Extended Cab Pickup S/N: 1GCHSBEA4N1311703 C/W: Automatic Transmission, Air Conditioner, Power Windows, 5400 lb GVWR, 255/65R17 Tires, 6 ft 2 in Bed Usage: 34,661 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8804	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN721807 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012.0 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 111,655 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8799	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN724934 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Stainless Steel Truck Cap, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 84,482 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8805	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE9LN721892 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012.0 lb GVWR, 265/75R16 Tires, 6 ft Bed Usage: 116,183 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8800	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE5LN721727 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012.0 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 103,120 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8806	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT1HN724360 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft 6 in Bed Usage: 103,998 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
8801	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN719166 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 100,824 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8807	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CTXHN757261 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 118,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8802	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE1LN721059 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 101,844 Mi Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8808	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT3HN721511 C/W: 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 127,844 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;	8814	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19PNC000023 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8815	2022 Kandi K32S-GY Utility Vehicle (Unused)
8809	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19CNC000009 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 2 Mi Notes: ***FOR OFF ROAD USE ONLY***		S/N: A074EA19ANC000014 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED
	PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.		SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8816	2022 Kandi K32S-R Utility Vehicle (Unused)
8810	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000010 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 4 Mi		S/N: A074EA19KNC000007 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 9 Mi Notes: ***FOR OFF ROAD USE ONLY***
	Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.		PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.
	Asset located in: Lake Worth, TX	0017	Asset located in: Lake Worth, TX
8811	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000024 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.	 8817	2022 Kandi K32S-R Utility Vehicle (Unused) S/N: A074EA19LNC000015 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 15 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8818	2022 Kandi K32S-W Utility Vehicle (Unused)
8812	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19PNC000006 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 12 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.		S/N: A074EA19CNC000021 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi Notes: ***FOR OFF ROAD USE ONLY***; PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8819	2022 Kandi K32S-W Utility Vehicle (Unused)
8813	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19JNC000011 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 13 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE		S/N: A074EA19TNC000005 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.
	DOCUMENT SECTION. Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8820	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19TNC000022 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch, Charger Usage: 16 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX Subaru Sambar 4x4 COE Flatbed Truck S/N: TT2096235 C/W: Subaru Clover4 4 Cylinder Gasoline Engine, 5-Speed Manual Transmission, 145R12, Spring Suspension, 74 in Wheelbase,	8825	2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X9MD759078 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 238,812 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000 Asset located in: Lake Worth, TX
	77 ft x 55 in Bed Usage: 98,817 Mi	8826	2017 Peterbilt 579 4x2 S/A Day Cab Truck
	Notes: THIS ITEM IS RIGHT HAND DRIVE; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	0020	Tractor S/N: 1XPBA48X2HD428752 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2016 US EPA Label, Requires
8823	23 2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X1ND759335 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires		Diesel Exhaust Fluid, Automated Transmission 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel Usage: 933,275 Mi Asset located in: Lake Worth, TX
		8828	2017 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X0HD428751 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 16727 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 827,012 Mi
8824	2022 Peterbilt 579 4x2 S/A Day Cab Truck		Asset located in: Lake Worth, TX
	Tractor S/N: 1XPBAP8X0ND759228 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 213663 TITLE SHOWS	8829	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339556 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 896,378 Mi Asset located in: Lake Worth, TX
	213700	8830	2016 Peterbilt 579 4x2 S/A Day Cab Truck
	Asset located in: Lake Worth, TX		Tractor S/N: 1XPBA48X6GD339491 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21591 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 808,551 Mi

Lot #	Details	Lot #	Details
8831	831 2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339671 C/W: Cummins ISX15 6 Cylinder 15.0 L 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17898.4 Engine hrs, Engine Brake, Eaton Fuller UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Trac Air Ride Suspension, 159 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 888,673 Mi	8836	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X5FD286314 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	8837	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X7FD286248 C/W: Cummins ISX15 15.0 L Diesel 400 hp
8832	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X6GD339488 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 18871 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension,		Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19447 Engine hrs, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 839,056 Mi Asset located in: Lake Worth, TX
	160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 672,222 Mi Asset located in : Lake Worth, TX	8838	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8FD286307
8833	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X6GD339555 C/W: Cummins X15 6 Cylinder 15.0 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel		C/W: Cummins ISX15 6 Cylinder 15 L Petrol 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 919,106 Mi Asset located in: Lake Worth, TX	8839	2016 Kenworth T-680 4x2 S/A Day Cab Truck Tractor
8834	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X6FD286306 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18127 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Trac Air Ride		S/N: 1XKYA48XXGJ119241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

275/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 883,053 Mi

Asset located in: Lake Worth, TX

Wheel, Dual Fuel Ta Usage: 828,937 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8840	2016 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X9GJ496496 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17916 Engine hrs, Engine Brake, Eaton Fuller ADV Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, 4-Bag Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	8844	2015 Kenworth T-680 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYD49X7FJ466031 C/W: Cummins ISX15 6 Cylinder 15 L Diesel Engine, 2014 US EPA Label, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, Differential Lock, 2.64:1 Axle Ratio, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, AG400 8-Bag Air Ride Suspension, 179 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 338,458 Mi Asset located in: Lake Worth, TX
	Usage: 912,222 Mi Asset located in : Lake Worth, TX	8845	2015 Kenworth T680 4x2 S/A Day Cab Truck
8841	2015 Kenworth T680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXFJ403449 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22634 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, 4-Bag Air Ride Suspension, 168 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	Tractor S/N: 1XKYA48XXFJ403435 C/W: Cummins ISX15 6 Cylinder 400 hp Engine, 2014 US EPA Lal Diesel Exhaust Fluid, Engine Bra Automated Transmission, 1200 22700 lb Rears, Dana S23-190 D 1 Axle Ratio, 34700 lb GVWR, Ai /75R22.5, Air Ride Suspension, Wheelbase, Air Sliding 5th Wheelbase, Air Sliding 5th Wheelbase: 973,817 Mi Asset located in: Lake Worth, TX 8846 2014 Kenworth T-680 4x2 S/A D	Tractor S/N: 1XKYA48XXFJ403435 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53 1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	Usage: 1,009,300 Mi		2014 Kenworth T-680 4x2 S/A Day Cab Truck
8842	Asset located in: Lake Worth, TX 2015 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X0FJ443782 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 990,189 Mi		Tractor S/N: 1XKYA48X9EJ402288 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM- 15E310B-LAS Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airglide Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel Usage: 323,990 Mi Asset located in: Lake Worth, TX
	Notes: X2-No frame stamp vin pic	8847	2014 Kenworth T680 4x2 S/A Day Cab Truck
	Asset located in: Lake Worth, TX		Tractor
8843	2015 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X6FJ443771 C/W: Cummins ISX 6 Cylinder 15 L Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 17203 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Airglide 4-Bag Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel Usage: 732,450 Mi		S/N: 1XKYA48X7EJ402287 C/W: Cummins ISX15 6 Cylinder 15.0 L Diese 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fu Automated Transmission, 12000 lb Front Ax 22700 lb Rears, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, 4-Bag Air Ride Suspension, 156 in Wheelbase, Air Slidi 5th Wheel, Dual Fuel Tanks Usage: 940,369 Mi Asset located in: Lake Worth, TX

		_	
Lot #	Details	Lot #	Details
8848	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor	8852	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor
	S/N: 1XKYA48X3EJ402450 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5 Front Tires, 275/80R22.5 Rear Tires, AG400 4-Bag Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 696,531 Mi		S/N: 1XKYA48X9EJ403215 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19302.4 Engine hrs, Engine Brake, Eaton Fuller FM- 15E310B 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23- 190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, AG200 4- Bag Air Ride Suspension, 159 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 937,106 Mi
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
8849	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X0EJ403264 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 16967.1 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 157 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 538,940 Mi	8853	2013 Kenworth T660 4x2 S/A Day Cab Truck Tractor S/N: 1XKAA48X1DJ354916 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 769,223 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	8854	2013 Kenworth T660 6x4 T/A Day Cab Truck
8850	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXEJ402851 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Eaton Fuller FM-15E310B-LAS Automatic Transmission, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700.0 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,154,795 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKAD48X1DJ367527 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 11435.7 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Differential Lock, 12000 lb Front Axle, 34000 lb Rears, 2.64:1 Axle Ratio, 46000 lb GVWR, 275/80R22.5, 8- Bag Air Ride Suspension, 210 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 744,800 Mi Asset located in: Lake Worth, TX
8851	2014 Kenworth T680 4x2 S/A Day Cab Truck	8855	2013 Kenworth T660 4x2 S/A Day Cab Truck
	Tractor S/N: 1XKYA48X4EJ403168 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 767,305 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XKAA48X8DJ354945 C/W: Cummins ISX15 6 Cylinder 15 L 400 hp Engine, Requires Diesel Exhaust Fluid, 22347.6 Engine hrs, Engine Brake, Eaton Fuller FM- 15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 4-Bag Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 888,882 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8856	2013 Peterbilt 337 4x2 S/A Day Cab Truck Tractor S/N: 2XP2AN7X0DM211082 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 6874 Engine hrs, Engine Brake, Allison 6- Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 5.38:1 Axle Ratio, 33000 lb GVWR, Aluminum Front Wheels, 11R22.5, Paccar Air Ride Suspension, 156 in Wheelbase Usage: 213,485 Mi Asset located in: Lake Worth, TX	8861	Cab Truck Tractor S/N: 3AKBGEDV5JSJH1844 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diese Exhaust Fluid, 10441 Engine hrs, Engine Brake Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, 3.08:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEE
8857	2019 Mack AN42T 4x2 S/A Day Cab Truck		Usage: 244,661 Mi Asset located in : Lake Worth, TX
	Tractor S/N: 1M1AN2AY6KM001154 C/W: Mack MP7 6 Cylinder Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 154 in Wheelbase, Auto Lube Usage: 537,481 Mi Asset located in: Lake Worth, TX	8862	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV1HDHY5841 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 529 hp Engine, 2016 US EPA Label, Requires Diese Exhaust Fluid, 12543 Engine hrs, Engine Brake Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor R 23-161 Drive Axles, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22 5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel
8858	2019 Mack Anthem 4x2 S/A Day Cab Truck		
	Tractor S/N: 1M1AN2AY2KM001152 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4523 Engine hrs, Engine Brake, Mack 12-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase Usage: 476,581 Mi Asset located in: Lake Worth, TX		Tanks Usage: 553,773 Mi
			Asset located in: Lake Worth, TX
		6803	8863 2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV4HDHY5848 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner
8859	2017 Mack CXU612 4x2 S/A Day Cab Truck Tractor S/N: 1M1AW01Y9HM010179 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive		Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 569,326 Mi Asset located in: Lake Worth, TX
	Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 477,424 Mi		2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV6HDHY5849 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 15402 Engine hrs, Engine Brake,
8860	Asset located in: Lake Worth, TX 2017 Mack CXU612 4x2 S/A Day Cab Truck	-	Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb
	Tractor S/N: 1M1AW01Y7HM010164 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14979 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 548,175 Mi Asset located in: Lake Worth, TX		Rears, Meritor RS-23-161 Drive Axles, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 620,515 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8865	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV5HDHY5843 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 588,024 Mi	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0206 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19010 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 865,103 Mi Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	8870	2015 Freightliner Cascadia 125 4x2 S/A Day
8866	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0385 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17775 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase,		Cab Truck Tractor S/N: 1FUBGDD58FLGB0017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 20941 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 984,115 Mi
	Dual Fuel Tanks Usage: 920,721 Mi		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8867	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0401 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18682 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,203 Mi Asset located in: Lake Worth, TX	8871	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGJ1241 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 2052 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 703,022 Mi
8868	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
	S/N: 1FUBGDD5XFLGB0164 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18936 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor MFS-12-143A Drive Axles, 3.42:1 Axle Ratio, 33000 kg GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 871,985 Mi Asset located in: Lake Worth, TX	8872	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0245 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19950 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,022 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8873	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0459 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17399 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 802,794 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8877	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1204 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20437 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 882,971 Mi Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
8874	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0324 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 818,368 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	_00/0	Cab Truck Tractor S/N: 1FUBGDD55FLGB0301 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18129 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 10R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 771,423 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8875	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGJ1193 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19725 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, Dual Fuel Tanks Usage: 871,783 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8880	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGJ1327 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20282 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 896,379 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8876	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGJ1322 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 16251 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,874 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8881	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGJ1233 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 21113 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 927,772 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;

Lot #	Details	Lot #	Details
8882	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0254 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14024 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,066,619 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;	8886	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0423 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 870,847 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8883	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1297 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks	8887	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0200 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 840,242 Mi Asset located in: Lake Worth, TX
	Usage: 847,972 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8888	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGB0420
8884	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGJ1248 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 853,850 Mi		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21049 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 971,468 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8889	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0084
8885	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0455 C/W: 21346 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23- 186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner II Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 978,516 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21221 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,002,152 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8890	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGJ1150 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor Drive Axles, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 844,869 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8894	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0247 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 509 hp Engine, 2014 US EPA Label, Requires Diese Exhaust Fluid, 19933 Engine hrs, Engine Brake Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase Dual Fuel Tanks Usage: 926,620 Mi Notes: ADDITIONAL INFORMATION
8891	2015 Freightliner Cascadia 125 4x2 S/A Day		AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
	Cab Truck Tractor S/N: 1FUBGDD54FLGJ1217 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18209 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,386 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;	8895	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0266 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 910,815 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8892	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0278 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20497 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 954,240 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX		2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22008 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,012,404 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8893	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1249 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 995,766 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8897	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0161 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19325 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 889,925 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8898	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0351 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19389 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 867,504 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8902	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0173 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 842,483 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8899	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0283 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18643 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 985,816 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8903	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGJ1328 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4695 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 862,038 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY Asset located in: Lake Worth, TX
8900	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0208 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 19799 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks Usage: 922,423 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8904	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0145 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19762 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,268 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8901	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGJ1223 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19901 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 851,964 Mi Asset located in: Lake Worth, TX	8905	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGJ1227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17987 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 859,845 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8906	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGB0153 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,039,845 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8910	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0176 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 792,126 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8907	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0120 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19024 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 874,425 Mi Asset located in: Lake Worth, TX	8911	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0347 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1735 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 940,040 Mi Asset located in: Lake Worth, TX
8908	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0339 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19629 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 766,317 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8912	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55ELFL7286 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 777,001 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX
8909	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0314 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19888 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks Usage: 854,701 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8913	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XELFL7283 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20475 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 868,356 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX

Details	Lot #	Details	
2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50ELFL7275 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19027 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 783,595 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY Asset located in: Lake Worth, TX	8919	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR6DLBX1162 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 16476 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 647,254 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;	
2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58ELFL7265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 730,348 Mi Asset located in: Lake Worth, TX	8920	Asset located in: Lake Worth, TX 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBX1102 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19727 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 662,005 Mi	
2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	
S/N: 1FUBGEBG0ELFT4306 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-14E310B Automated Transmission, Meritor RS-23-160 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 552,293 Mi Asset located in: Humble, TX	8921	8921 2013 Freightliner Cascadia 125 4x2 S/A D Cab Truck Tractor S/N: 1FUBGDDR0DLBX1156 C/W: Detroit DD15 6 Cylinder 14.8 L Diese hp Engine, 2012 US EPA Label, Requires D Exhaust Fluid, 18326 Engine hrs, Engine B Eaton Fuller FRO-15210C 10-Speed Manu- Transmission, 12000 lb Front Axle, 23000 Rears, Meritor RS-23-186 Drive Axles, 3.42 Axle Ratio, 33000 lb GVWR, Air Ride Cab,	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR0DLBX1156 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18326 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab,
8 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FURGDDRYDL BY1004		11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 422,808 Mi Asset located in : Lake Worth, TX	
C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 748,352 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8922	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX0897 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20167 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 812,847 Mi	
	Cab Truck Tractor S/N: 1FUBGDD50ELFL7275 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19027 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 783,595 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY Asset located in: Lake Worth, TX 2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58ELFL7265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GWWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 730,348 Mi Asset located in: Lake Worth, TX 2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGEBG0ELFT4306 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-14E310B Automated Transmission, Meritor RS-23-160 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 552,293 Mi Asset located in: Humble, TX 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBX1004 C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 34:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 748,352 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50ELFL7275 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19027 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 783,595 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY Asset located in: Lake Worth, TX 2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58ELFL7265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GWWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 730,348 Mi Asset located in: Lake Worth, TX 2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGEDSBGELFT4306 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-14E310B Automated Transmission, Meritor RS-23-160 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 552,293 Mi Asset located in: Humble, TX 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBX1004 C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 2:1000 lb Rears, Meritor RS- 23-186 Drive Axles, 3:42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 748,352 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;	

	D 1 1	I	B : 1
Lot #	Details	Lot #	Details
8923	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8927	2012 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDDR4DLBX1080 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 515,155 Mi Asset located in: Lake Worth, TX		S/N: 1FUBGDDR9CLBF2891 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 19508 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks
8924	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor		Usage: 712,633 Mi Notes : ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;
	S/N: 1FUBGDDR1DLBX0906		Asset located in: Lake Worth, TX
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid,	8928	2018 Freightliner Cascadia 113 4x2 S/A Day
	19497 Engine hrs, Engine Brake, Eaton Fuller		Cab Truck Tractor
	FRO-15210C 10-Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 724,603 Mi		S/N: 3AKBGBDV9JSJR3316 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, 13472 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission,
	Asset located in: Lake Worth, TX		12000 lb Front Axle, 22700 lb Rears, 3.08:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275
8925	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR7DLBX1185 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21125 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb		/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 623,326 Mi Notes : ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;
			Asset located in: Lake Worth, TX
	Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 790,333 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	Truck Tractor S/N: 1FUJC5DV2EHFX4554 C/W: Detroit DD13 6 Cylinder 12.8 L Dies hp Engine, 2013 US EPA Label, Requires Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Fron	
8926	2013 Freightliner Cascadia 125 4x2 S/A Day		GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 172
	Cab Truck Tractor S/N: 1FUBGDDR1DLBX0985 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560		in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 698,878 Mi
	hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21973 Engine hrs, Engine Brake,	0000	Asset located in: Lake Worth, TX
	Eaton Fuller FRO-15210Č 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 802,200 Mi Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY; Asset located in: Lake Worth, TX	8930	2015 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCYCY6FDGJ1937 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8522 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Detroit DA-RS-23.0-4 Drive Axles, 5.22:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Spring Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 147,777 Mi

Lot #	Details	Lot #	Details
8934	2014 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCYCY4EDFX5745 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9009 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 5.38:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, steel, 295/75R22.5, Spring Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 120,247 Mi Asset located in: Lake Worth, TX	8939	2019 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W39EG8KN226146 C/W: Volvo 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, 35350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 664,493 Mi Asset located in: Lake Worth, TX
8935	2022 Volvo VNR300 4x2 S/A Day Cab Truck	8940	2019 Volvo VNR300 4x2 S/A Day Cab Truck
	Tractor S/N: 4V4W19EG7NN285618 C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 7146 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, 275/80R22.5, Volvo Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 295,698 Mi Asset located in: Lake Worth, TX		Tractor S/N: 4V4W39EGXKN226147 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15950 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, Meritor RS23-160 Drive Axles, 35350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 730,594 Mi Asset located in: Lake Worth, TX
8936	2022 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG7NN285540 C/W: Volvo D13N405 6 Cylinder 12.8 L 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 8483 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 347,925 Mi	00.41	·
		8941	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EGXKN907544 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000.0 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 680,054 Mi Asset located in: Lake Worth, TX
8937	2021 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG7MN285326 C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 7976 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, 295/75R22.5, Volvo Air Ride Suspension, 151 in Wheelbase, Dual Fuel Tanks Usage: 322,314 Mi Notes: ODOMETER DISCREPANCY-UNIT	8942	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG1KN907528 C/W: Volvo D13M-405 6 Cylinder 12.8 L 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 706,546 Mi
	SHOWS 322,314, TITLE SHOWS 322,500 Asset located in: Lake Worth, TX	8943	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG3KN901925 C/W: Volvo D13M405 6 Cylinder 12.8 L 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17551 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 754,359 Mi

Asset located in: Midland, TX

			1 490 107 0107
Lot #	Details	Lot #	Details
8944	2018 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG1JN901758 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 18039 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000.0 lb GVWR, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP	8948	2012 Volvo VNL300 4x2 S/A Day Cab Truck Tractor S/N: 4V4N19EG6CN560842 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 32350.0 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 311,531 Mi Asset located in: Humble, TX
	Usage: 735,581 Mi Asset located in: Lake Worth, TX	8949	2014 International ProStar 4x2 S/A Day Cab Truck Tractor
8945	2017 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EG1HN985095 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 22474 Engine hrs, Volvo AT2612D 12-Speed Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, VOLVO Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks	S/N: 1HSI C/W: Cum 400 hp En Diesel Exh Automate 20000 lb I Aluminum Ride Susp 5th Whee Usage: 36 Asset loca 8950 2015 Inter Truck Tra S/N: 1HSI C/W: Nav Engine, Re Engine hrs Transmis: Rears, 32(Wheels, 1 Wheelbas Usage: 85	S/N: 1HSDGAPN6EH036926 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, Aluminum Outer Rear Wheels, 11R22.5, Air Ride Suspension, 173 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 360,386 Mi Asset located in: Lake Worth, TX
	Usage: 876,316 Mi		2015 International 4400 4x2 S/A Day Cab
8946	Asset located in: Lake Worth, TX 2015 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH4FN184666 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15123 Engine hrs, Engine Brake, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32350 lb GVWR, Air Ride Cab, 295/75R22.5, Volvo Air Ride Suspension, 156 in Wheelbase,		S/N: 1HSMTSTN8FH726444 C/W: Navistar N9 6 Cylinder 9.3 L Diesel Engine, Requires Diesel Exhaust Fluid, 3580 Engine hrs, Engine Brake, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 152 in Wheelbase, PTO Usage: 85,797 Mi Asset located in: Lake Worth, TX
		8951	12 International 4400 4x2 S/A Day Cabuck Tractor N: 1HSMTAAN4CH561985 W: International MaxxForce DT 6 Cylinder 6 L Diesel 300 hp Engine, 2011 US EPA Label,
8947	2013 Volvo VNL200 4x2 S/A Day Cab Truck Tractor S/N: 4V4N39EG8DN142388 C/W: Volvo D13H405 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D Automated Transmission, 12350 lb		4407 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 148 in Wheelbase, Dual Fuel Tanks Usage: 136,823 Mi Asset located in: Lake Worth, TX
Fror 11R Whe Usa	Front Axle, 23000 lb Rears, 35350 lb GVWR, 11R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel Usage: 535,477 Mi Asset located in: Lake Worth, TX	8952	2009 International ProStar Premium 4x2 S/A Day Cab Truck Tractor S/N: 2HSCSAPN49C045678 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, 275 /80R22.5, Air Ride Suspension, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 610,101 Mi

Lot #	Details	Lot #	Details
8953	2008 International TranStar 8600 4x2 S/A Day Cab Truck Tractor S/N: 1HSHWAHN68J673895 C/W: Cummins 6 Cylinder Engine, 22559 Engine hrs, Eaton Fuller 10-Speed Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 148 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 582,442 Mi Asset located in: Midland, TX	8957	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GF32N335289 C/W: Volvo DT12C345 6 Cylinder 12.1 L Diesel 345 hp Engine, 2001 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 2.93:1 Axle Ratio, 32000.0 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks Usage: 344,373 Mi Asset located in: Lake Worth, TX
8953A	2005 International 8600 4x2 S/A Day Cab Truck Tractor S/N: 1HSHWAHN55J029493 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel Engine, 2084 Engine hrs, Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 169 in Wheelbase, Dual Fuel Tanks Usage: 495,481 Mi Asset located in: Lake Worth, TX	8958	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19RF72N324549 C/W: Detroit 6 Cylinder 12.7 L Diesel 470 hp Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 32000 lb GVWR, 295/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 154 mm Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,393,840 Mi Asset located in: Midland, TX
8955	2003 Freightliner FLD 112 4x2 S/A Day Cab Truck Tractor S/N: 1FUBACA873DK79061 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel 370 hp Engine, 2002 US EPA Label, Meritor 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 2.93:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 919,458 Mi Asset located in: Lake Worth, TX 2008 Volvo VNM 4x2 S/A Day Cab Truck		2017 Peterbilt 579 4x2 (CNG) S/A Day Cab Truck Tractor S/N: 1NPBAH8X7HD421460 C/W: Cummins ISX12 6 Cylinder 11.9 L Compressed Natural Gas (CNG) 400 hp Engin 2016 US EPA Label, Engine Brake, Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, 35050 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel Usage: 549,140 Mi
	Tractor S/N: 4V4M19EH28N498237 C/W: Volvo 6 Cylinder 12.8 L Diesel Engine, 2007 US EPA Label, Engine Coolant Heater, 10- Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 295 /75R22.5, Paccar Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 1,428,300 Mi Asset located in: Midland, TX		Asset located in: Lake Worth, TX 2017 Freightliner Cascadia 113 CNG 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGBD98HLGV4596 C/W: Cummins ISX12G 11.9 L Compressed Natural Gas (CNG) 400 hp Engine, 2015 US EPA Label, Allison 4000 HS Automatic Transmission, 12500 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 3.91:1 Axle Ratio, 35050 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 182 in
8956A	2007 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GFX7N451743 C/W: Volvo 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Engine Brake, Eaton Fuller FR13210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-186 Drive Axles, 2.93:1 Axle Ratio, 32000 lb GVWR, Aluminum Front Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 144 in Wheelbase, Dual Fuel Tanks Usage: 1,551,805 Mi Asset located in: Lake Worth, TX		Wheelbase Usage: 23,705 Mi Asset located in : Lake Worth, TX

1 "	Dataila	1.4"	Dataila
Lot #	Details	Lot #	Details
8963	2008 Trail King TK140MDG-693 70 ton Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ069368B045330 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, Tri/A Jeep, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 30 ft Main Deck, 108 in Usable Deck Width, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275/70R22.5 Tires, 175300 lb GVWR Usage: Not Available Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED; COMING FROM A WELL MAINTAINED CENTRAL TEXAS TOWING & WRECKER SERVICE FLEET Asset located in: Lake Worth, TX	8968	2007 Trail King TK110HDG 55 t Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533X7M051363 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 102 in Usable Deck Width, 12 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 132800 lb GVWR, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
8964	2008 Etnyre RTN65TD3-RA 3+1+1 Lowboy Trailer S/N: 1E92980888E111025 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 25 ft 7 in Main Deck, 98 in Usable Deck Width, 108 in Overall Deck Width, 275/70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	8969	2007 Trail King TK55T 55 ton Quad/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ053347B051452 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, S/A Flip Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 102 in Usable Deck Width, Folding Side Extensions, Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275/70R22.5 Tires, 110000 lb GVWR Usage: Not Available
8965	2006 Trail King TK130HDG-573 Tri/A		Asset located in: Lake Worth, TX
8967	Removable Gooseneck Lowboy Trailer S/N: 1TKJ057386M014661 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 28 ft Main Deck, 120 in Overall Deck Width, Honda Gas Powered Self Contained Hydraulic System, 235/75R17.5 Tires, 161280 lb GVWR, Spreader Bar Usage: Not Available Asset located in: Humble, TX 2015 XL Specialized 120SDE Tri/A 41 ft - 64 ft	8970	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E32RS000472 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Extendable Lowboy Trailer		
	S/N: 4U3B05337FL014387 C/W: Air Ride Suspension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 42 ft Main Deck, 97 in Overall Deck Width, 102 in Widening Width, 235/75R17.5 Tires Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 8967 AND 8973 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX	8971	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E36RS000474 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

			rage 470 01 374
Lot #	Details	Lot #	Details
8972	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E34RS000473 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	8976	2013 Trail King TK110HDG 55 t Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533XDM109113 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in Usable Deck Width, 126 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 134660 lb GVWR, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED;
8973	2015 XL Specialized 120SDE Tri/A 41 ft - 64 ft Extendable Lowboy Trailer S/N: 4U3B05330FL014621		PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in : Lake Worth, TX
	C/W: Air Ride Suspension, Plumbed for Booster Axle, 40 ft Main Deck, 102 in Usable Deck Width, Aluminum Outer Wheels, 235 /75R17.5 Tires, 143575 lb GVWR Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 8967 AND 8973 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX		2010 Trail King TK110HDG533 55 ton Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ05330AM109858 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft 7 in Rear Deck, 102 in Usable Deck Width, 24 in Widening Width, Folding Side Extensions, Boom Recess, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 255/70R22.5 Tires, 133820 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION
8974	4 2013 Trail King TK110HDG533 55 t Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ05333DM041625 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 26 ft Main Deck, 102 in		Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELO Asset located in: Lake Worth, TX
	Usable Deck Width, Folding Side Extensions, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, 275/70R22.5 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX		Lowboy Trailer S/N: 5JYLB5137NPP24054 C/W: Air Ride Suspension, Air Brakes, I Axles, Hydraulic Removable Goosened Main Deck, 16 ft Rear Deck, 102 in Usa
8975	2013 Trail King TK110HDG 55 t Tri/A Expandable Axle Removable Gooseneck Lowboy Trailer S/N: 1TKJ05334DM109110 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in		Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Deck Over Tires, Aluminum Outer Wheels, 255 /70R22.5 Tires, 121500 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usable Deck Width, 126 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 134820 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	8980	2010 Witzco Challenger RG50 Tri/A Removable Gooseneck Lowboy Trailer S/N: 1W8A11F37AS000227 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 25 ft Main Deck, 102 in Usable Deck Width, Deck Over Tires, Gas Powered Self Contained Hydraulic System, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8982	2019 Fontaine T/A Removable Gooseneck Lowboy Trailer S/N: 57J348208K3575771 C/W: Air Ride Suspension, Air Brakes, 255 /70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	8988	1981 Nuttall 225-E T/A Lowboy Trailer S/N: NMC50296 C/W: Spring Suspension, 9 ft 4 in Upper Deck, 23 ft 5 in Main Deck, 5 ft 4 in Fixed Dovetail, 90 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Manual Ramps, 10.00R15 Tires Usage: Not Available
8983	2004 Fontaine 552-2MWNGB 55 ton 2+2		Asset located in: Lake Worth, TX
	Removable Gooseneck Lowboy Trailer S/N: 4LFE7640943523624 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, 29 ft Main Deck, 96 in Usable Deck Width, 120 in Widening Width, Folding Side Extensions, Gas Powered Self Contained Hydraulic System, 275	8989	1990 Talbert TJ-11R22.5 35 ton T/A Heavy-Haul Jeep S/N: 40FJK2725L1008821 C/W: Air Ride Suspension, 275/70R22.5 Tires, 67079 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	/70R22.5 Tires, 147500 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	8992	2018 Liddell C55 S/A Booster Axle S/N: 1L93J0517JB564012
8984	2000 Fontaine T/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 13ND48291Y1590100		C/W: Flip-Up, Air Ride Suspension, 255/70R22. 5 Tires Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Air Ride Suspension, Mechanical Removable Gooseneck, 9 ft 7 in Upper Deck, 29 ft 2 in Main Deck, 7 ft 8 in Rear Deck, 102 in Usable Deck Width, Deck Over Tires, 255 /70R22.5 Tires, 70000 lb GVWR Usage: Not Available	8994	1989 Fontaine S/A Booster Axle S/N: 13NM04107K1547671 C/W: Pin-On, Air Ride Suspension, 255/70R22. 5 Tires, 18160 lb GVWR Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8985	1984 Cozad 2+2+2 Removable Gooseneck Lowboy Trailer S/N: 1C9B48207E1167105 C/W: Walking Beam Suspension, Mechanical Removable Gooseneck, Plumbed for Booster Axle, 30 ft Main Deck, 102 in Usable Deck Width, Dropside Deck, 11R24.5 Tires, 1984 Cozad 16 Wheel Expando Jeep w/Hyd Tower, s /n 1C9H24204E11677104. 1984 - Cozad Booster s/n: 1C9B48207E1167106 c/w: T/A Pin-On Booster, 70R22.5 Tires; Usage: Not Available	8995	2020 Wabash TCD/CDC-CDH S/A Dolly S/N: 1JJD061X6LL222455 C/W: Spring Suspension, 275/80R22.5 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		8996	1994 Pines S/A Dolly S/N: 1PNA09101RK056464 C/W: Spring Suspension, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT . Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8986	·	8996A	1987 Fruehauf ELF-1 S/A Dolly
3900	2008 Viking VFDD46R18F35T T/A Double Drop Lowboy Trailer S/N: 1V9CR46288N062389 C/W: Spring Suspension, 9 ft Upper Deck, 21 ft 5 in Main Deck, 9 ft 2 in Rear Deck, 4 ft Fixed Dovetail, 102 in Usable Deck Width, Upper Deck Ramps, Deck Over Tires, Spring Assisted	0330A	S/N: 1H2E00617HH031475 C/W: 295/75R22.5 Tires, 20000 lb GVWR Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX
	Ramps, 255/70R22.5 Tires, 87000 lb GVWR Usage: Not Available	8998	2019 Trail King TK70HT T/A Hydraulic Tail
8987	Asset located in: Midland, TX 2002 Kalyn Siebert LB0353T Quad/A Lowboy Trailer S/N: 5DDKE404221000577 C/W: Walking Beam Suspension, 39 ft Main Deck, 98 in Usable Deck Width, 102 in Overall Deck Width, Tail Roller, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 1TKA04828KM102376 C/W: 84800 lb GVWR, Spring Suspension, 9 ft Upper Deck, 38 ft 8 in Main Deck, 9 ft 2- Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8999	2018 Fontaine Traverse HT T/A Hydraulic Tail Trailer S/N: 57JV482DXJ3574695 C/W: Air Ride Suspension, 6 ft 10 in Upper Deck, 38 ft 5 in Main Deck, 4 ft 3 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, 10R17.5 Tires, 83200 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9006	2023 Maxey YHX T/A Gooseneck Hydraulic Tail Trailer S/N: 5R8GF4023PM106833 C/W: Spring Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, 40000 lb GVWR, Hydraulic Jacks Usage: Not Available Asset located in: Lake Worth, TX
9000	2016 Trail King TK80HT T/A Hydraulic Tail Trailer S/N: 1TKA04823GM031272 C/W: Air Ride Suspension, 7 ft 8 in Upper Deck, 38 ft 10 in Main Deck, 7 ft 8 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R-17.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9007	1996 Trail-Eze DHT7048 T/A Hydraulic Tail Trailer S/N: 1DA72C7D9TM012261 C/W: Air Ride Suspension, 9 ft 9 in Upper Deck, 30 ft 2 in Main Deck, 8 ft 2-Position Dovetail, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 83520 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
9001	2016 Trail-Eze TE70XT T/A Hydraulic Tail Trailer S/N: 1DAHFC727GP022069 C/W: Air Ride Suspension, Sliding Suspension, 7 ft Upper Deck, 38 ft 1 in Main Deck, 4 ft 10 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, 10R17.5 Tires, 86720 lb GVWR, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	9008	2014 Landoll 930C T/A Sliding Axle Trailer S/N: 1LH930UHXE1C20991 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 4 ft Upper Deck, 23 ft Main Deck, 13 ft Rear Deck, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10r17.5 Tires, 86300 lb GVWR, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
9002	2016 Trail-Eze TE70XT 28983 lb T/A Hydraulic Tail Trailer S/N: 1DAHFC725GC021848 C/W: Aluminum Frame, Spring Suspension, Air Brakes, 6 ft 6 in Upper Deck, 25 ft Main Deck, 2-Position Dovetail, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Hydraulic Ramps, 10r17.5 Tires, 40000 lb GVWR, EQUIPMENT-	9008A 9009	2011 Landoll 48 ft T/A Sliding Axle Trailer S/N: 1LH317UHXB1D18600 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck, 37 ft Main Deck, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 87000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
0004	FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in : Lake Worth, TX		9009
9004	2007 Ledwell LW48 T/A Hydraulic Tail Trailer S/N: 1L9GA72A37L033118 C/W: Spring Suspension, 7 ft Upper Deck, 28 ft Main Deck, 8 ft 2-Position Dovetail, 102 in Overall Deck Width, Winch, Deck Over Tires, Hydraulic Ramps, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Width, 99 in Overall Deck Width, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
		9010	2025 Maxey 40 ft T/A Sliding Axle Trailer (Unused) S/N: 5R8GF4025SM118166 C/W: Spring Suspension, Electric Brakes, Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, 235/80R16 Tires, 25990 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9011	2023 Great Dane 53 ft T/A Single Drop Step Deck Trailer S/N: 1GR4M0629PH443585 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck, 43 ft Main Deck, 96 in Usable Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9017	2018 Trail King 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB04825JY067453 C/W: Air Ride Suspension, 9 ft 10 in Upper Deck, 37 ft Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Aluminum Flooring, 255/70R22.5 Tires, 90420 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9012	2022 Brazo 80000 lb 53 ft T/A Single Drop Step Deck Trailer S/N: 4B9BKFS23NH054914 C/W: 80000 lb GVWR, Air Ride Suspension, Aluminum w/Wood Strips Flooring, 255/70R22. 5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9018	2014 Direct Trailers 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 5UJDS4829EE002311 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, 255/70R22. 5 Tires, 70852 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9013	2017 Trail King TK80ACS-40 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB05326HY082695 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 10 ft 4 in Upper Deck, 42 ft 2 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires, 90930 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9019	2013 Fontaine 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N248206D1557385 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Center Roller, Tail Roller, Wood Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX
9014	2013 Utility FS2CDHA 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1UYFS2534DA605126 C/W: Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes:	9020	2013 Transcraft 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE482S6D3756769 C/W: Air Ride Suspension, 11 ft Upper Deck, 37 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9015	Asset located in: Oklahoma City, OK 2012 Manac 14353A000 Tri/A 53 ft - 73 ft Extendable Single Drop Step Deck Trailer S/N: 2M5131611C1130362 C/W: Air Ride Suspension, 10 ft 6 in Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Extendable Deck, Tail Roller, Wood Flooring, Aluminum Over	9021	2006 Transcraft 48 ft T/A Single Drop Step Deck Trailer S/N: 1TTE4820861081701 C/W: Air Ride Suspension, Lift 1st- Axles, 10 ft 3 in Upper Deck, 36 ft Main Deck, 92 in Usable Deck Width, 102 in Overall Deck Width, 255 /70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	5 Tires, 45360 lb GVWR Usage: Not Available Asset located in : Humble, TX	9022	2005 Fontaine DFT-5-8048WSAWK 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N24830851529149 C/W: Air Ride Suspension, 10 ft Upper Deck, 3 ft 8 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, 255/70R22.5 Tires, 69556 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9016	2006 Transcraft DTL-2100 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE5320061080090 C/W: Air Ride Suspension, 10 ft Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, Aluminum Outer Wheels, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
9023	2000 Pro-Trak 53 ft T/A Step Deck Trailer S/N: 5BNDG5322YC001797 C/W: Spring Suspension, Electric Brakes, 9 ft Upper Deck, 39 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 225/75R16 Tires Usage: Not Available Asset located in: Humble, TX	9032A	2020 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GR4M9624LH151129 C/W: Air Ride Suspension, Air Brakes, 97 in Deck Width, 102 in Overall Width, Aluminum w /Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9027	2016 Fontaine 53 ft T/A Step Deck Curtain Side Trailer S/N: 13N2532C2G1512734 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, Ramp, Roll-Up Door, Aluminum Outer Wheels, 225/70R22.5 Tires, 66667 lb GVWR Usage: Not Available Asset located in: Humble, TX	9033	2019 Manac 10248K001L 48 ft T/A Flatbed Trailer S/N: 5MC124811K3181128 C/W: Air Ride Suspension, 92 in Deck Width, 102 in Overall Width, Wood Flooring, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
9028	2013 Utility FS2CHS 53 ft T/A Flatbed Trailer		PRIOR TO BIDDING Asset located in: Lake Worth, TX
	S/N: 1UYFS253XDA605017 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9033A	2018 Fontaine HCVSF12WSA 80000 lb 48 ft T /A Spread Axle Flatbed Trailer S/N: 13N14820XJ1525028 C/W: Air Ride Suspension, 97.5 in Deck Width, 101.5 in Overall Width, Wood Flooring, 11R24.5
9029	2012 Great Dane 53 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM0625CH715673		Tires, 70543 lb GVWR Usage: Not Available Asset located in : Humble, TX
	C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9034	2016 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM9622GH729220 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead,
9030	30 2005 Benson 53 ft Tri/A Flatbed Trailer S/N: 5DMFABTC85M000235 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width,		Aluminum Flooring, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
	Aluminum Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9035 20 Tri S/ C/ 97 Al Ib Us 4 9036 20 Fl S/ C/ 97 Al Ib Us	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A22FR032303 C/W: Aluminum Frame, Air Ride Suspension,
9031	2007 Chaparral 50 ft T/A Spread Axle Flatbed Trailer S/N: 1C92F50257M949174 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width,		97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Bulkhead, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		2015 Benson 524 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A1F3882259 C/W: Aluminum Frame, Air Ride Suspension,
9032	2023 Transcraft 40000 lb 48 ft T/A Spread Axle Flatbed Trailer (Unused) S/N: 1TTF482C2P3354782 C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 8400 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9037	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A29FR032427 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9044	2012 Utility 48 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2481CA431530 C/W: Air Ride Suspension, 79.5 in Deck Width, 100.5 in Overall Width, Aluminum w/Wood Strips Flooring, 285/75R24.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9038	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A26FR032336 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9045	2012 Utility FS2CHA 48 ft T/A Flatbed Trailer S/N: 1UYFS2483CA431528 C/W: Air Ride Suspension, 97.5 in Deck Width, 100.5 in Overall Width, Aluminum w/Wood Strips Flooring, 285/75R24.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2009 Wade WH1-48FT T/A Extendable Flatbed
9039	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A26FR032319 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9046	Trailer S/N: 1W9FH48289E285033 C/W: Spring Suspension, Sliding Suspension, 11R22.5 Tires, 80000 lb GVWR, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: BENT FRAME PER SELLER Asset located in: Lake Worth, TX
9040	2015 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A8F3882257 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available	9047A	1996 Fontaine FL120 48 ft T/A Flatbed Trailer S/N: 13N1482C4T1573640 C/W: Spring Suspension, Sliding Suspension, 96 in Deck Width, Bulkhead, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9041	Asset located in: Lake Worth, TX 2015 Fontaine 48 ft T/A Spread Axle Flatbed Trailer S/N: 13N148202F1571993 C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 11R22.5 Tires, 70543 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9048	2007 Lufkin 45 ft T/A Flatbed Trailer S/N: 1L01B452471164518 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2006 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B482761159825
9042	2013 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482S7D3749530 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Wood Flooring, Aluminum Wheels, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX		C/W: Spring Suspension, Sliding Suspension, 96 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires, 80000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
9043	2012 Manac 48 ft T/A 48 ft - 80 ft Extendable Flatbed Trailer S/N: 2M5121463C1128632 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 91 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 73855 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9050	2006 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820961078665 C/W: Spring Suspension, Sliding Suspension, 95 in Deck Width, 102 in Overall Width, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9051	2008 Transcraft TL-2000N 45 ft T/A Flatbed Trailer S/N: 1TTF4520082021315 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9058	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH29SG000349 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9052	2005 Fontaine T/A 35 ft Extendable Flatbed Trailer S/N: 13N43620651527739 C/W: Spring Suspension, 87 in Deck Width, 91 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9059	2025 Atro T/A End Dump Trailer S/N: 3ELA6EH25SG000347 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls, Aluminum Body, Electric Roll Tarp, 11R24.5 Tires, 74957 lb GVWR, Aluminum Lead Body, 4 ft Lead Side Walls, Electric Lead Tarp Usage: Not Available
9053	1999 Fontaine T/A Extendable Flatbed Trailer S/N: 13N548209X1586994 C/W: Air Ride Suspension, 98 in Deck Width, 98 in Overall Width, 11R22.5 Tires, 75074 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 1999 Fontaine 48 ft T/A Spread Axle Flatbed	9060	Asset located in: Lake Worth, TX 2025 Atro T/A End Dump Trailer S/N: 3ELA6EH25SG000350 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls Usage: Not Available Asset located in: Lake Worth, TX
	Trailer S/N: 1R1F94820XK990187 C/W: Aluminum Frame, Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 11R24.5 Tires, 79600 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9061	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000382 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9055	1988 Fontaine FTW-3-8045SL 45 ft T/A Flatbed Trailer S/N: 13N1452CXJ1544459 C/W: Spring Suspension, Sliding Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9062	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH24SG000386 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9056	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000351 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9063	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH22SG000385 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9057	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000348 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9064	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH29SG000383 C/W: Spring Suspension, 34 ft Body, 49 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9065	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH20SG000384 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 Ib GVWR Usage: Not Available Asset located in: Lake Worth, TX	9071	2004 Midland MG34ST2400 34 ft T/A Quarter Frame End Dump Trailer S/N: 2MFB2R5CX4R002967 C/W: Spring Suspension, 34 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, Aluminum Outer Wheels, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A
9066	2015 MAC 40 ft T/A Aluminum Frameless End Dump Trailer S/N: 5MADN4020FC033902		BONDED TITLE Asset located in: Lake Worth, TX
	C/W: Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9074	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515423AP011370 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tress, 68000 lb GVWR
9067	2015 MAC 40 ft T/A Frameless End Dump Trailer		Usage: Not Available Asset located in : Lake Worth, TX
	S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9075	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515427AP011372 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR
9068	2022 Discount Dumps 36 ft T/A End Dump Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1D91A3925N1865007 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 36 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Wheels, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9076	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515420AP011374 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available
9069	2016 Dragon 34 ft Tri/A Quarter Frame End		Asset located in: Lake Worth, TX
	Dump Trailer S/N: 1UNSD3431GS128862 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 34 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available Notes: Asset located in: Humble, TX		2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515429AP011373 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT
9070	2016 Ranco ED 26-34 34 ft T/A Frameless End		LEAVE YARD UNTIL TITLE IS RECEIVED Asset located in: Lake Worth, TX
	Dump Trailer S/N: 591SD3429GR136697 C/W: Spring Suspension, 34 ft Body, 44 in Side Walls, Steel Body, Electric Roll Tarp, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9078	2021 Mate 30 ft Tri/A Aluminum Quarter Frame End Dump Trailer S/N: 1M9A30333MH036271 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes: . Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9079	2018 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A30332JH036175 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available	9086	1983 Fontaine 12 ft T/A Pup Dump Trailer S/N: 1A1V2920XD16PT113 C/W: Spring Suspension, 12 ft Body, 46 in Side Walls, Steel Body, Manual Roll Tarp, 10.00-22 Tires, 47500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: . Asset located in: Humble, TX	9087	2017 CTS BDT 40 T/A Belly Dump Trailer S/N: 5TU114021HS000432 C/W: Air Ride Suspension, Clam Gate Electric
9080	2021 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A3033XMH036270 C/W: Aluminum Frame, Air Ride Suspension,		Roll Tarp Push Block, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes: . Asset located in: Humble, TX	9088	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114021GS000512 C/W: Air Ride Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9081	2018 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A30339JH036173 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available Notes:	9089	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114028GS000197 C/W: Spring Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9091	2016 Construction Trailer Specialist BDT-40 T /A Belly Dump Trailer
9082	2001 Travis 39 ft T/A Frameless End Dump Trailer S/N: 48X1F392911001782 C/W: Air Ride Suspension, 39 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 275/80R24.5 Tires Usage: Not Available		S/N: 5TU114024GS000021 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9083	Asset located in: Lake Worth, TX 2003 Ranco 36 ft T/A Frameless End Dump	9092	2014 Armor Lite SBD-40 40 ft T/A Belly Dump Trailer
	Trailer S/N: 1R9ESD5073L008627 C/W: Spring Suspension, 36 ft Body, 46 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 56EA53K23EA000188 C/W: Spring Suspension, Cross Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW
9084	2002 Vantage 37 ft T/A Aluminum Frameless End Dump Trailer		Asset located in: Lake Worth, TX
	S/N: 4EPAA37292ATA4342 C/W: Air Ride Suspension, 37 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9093	2013 Manac 40 ft T/A Belly Dump Trailer S/N: 5MC424017D3133810 C/W: Air Ride Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
9085	1999 Smithco T/A Side Dump Trailer S/N: 1S9SS4022XL476665 C/W: Spring Suspension, Dumps to Both Sides, 36 in Side Walls, Steel Body, 425/66R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

	1.	
Details	Lot #	Details
2007 CTS BDT-40 42 ft T/A Belly Dump Trailer S/N: 5TU1140287S000202 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Clam Gate, Push Block, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9100	2012 Western 53 ft T/A Spread Axle Curtain Side Trailer S/N: 5DN115323CB000814 C/W: Air Ride Suspension, Aluminum Wheels, 295/75R22.5 Tires, 69000 lb GVWR Usage: Not Available Asset located in: Humble, TX
2003 Trail King BD237 T/A Belly Dump Trailer		
C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9101	1999 Nu Van NVSS 53 ft 53 ft x 102 in T/A Curtain Side Trailer S/N: 1N9F532P7X1045092 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, 295/75R22.5 Tires, 66000 lb GVWR Usage: Not Available
		Asset located in: Humble, TX
S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9102 1 T S C 2	1998 Raven 48 ft T/A Spread Axle Curtain Side Trailer S/N: 1R1F04823WK980200 C/W: Aluminum Frame, Air Ride Suspension, 285/75R24.5 Tires Usage: Not Available
1997 Schaller Manufacturing Roadmaster		Asset located in: Lake Worth, TX
G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS	9103	2024 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX22RG000079 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	9104	2023 Atro 53 ft x 102 in Van Trailer
2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX		S/N: 3ELA6RX28PG000052 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
1999 Timpte 42 ft T/A Belly Dump Grain Trailer		Asset located in: Lake Worth, TX
S/N: 1TDH42224XB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9105	2023 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX24PG003157 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Outer Wheels, 295 /75R22.5 Tires, 68000 lb GVWR Usage: Not Available
2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	S/N: 5TU1140287S000202 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Clam Gate, Push Block, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2003 Trail King BD237 T/A Belly Dump Trailer S/N: 1TKSC40213W101924 C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 1999 Midland MG36CLAM T/A Belly Dump Trailer S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 1997 Schaller Manufacturing Roadmaster G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX 1999 Timpte 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42224KB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 Ib GVWR Usage: Not Available	2007 CTS BDT-40 42 ft T/A Belly Dump Trailer S/N: 5TU1140287S000202 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Clam Gate, Push Block, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2003 Trail King BD237 T/A Belly Dump Trailer S/N: 1TKSC40213W101924 C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GWWR Usage: Not Available Asset located in: Lake Worth, TX 1999 Midland MG36CLAM T/A Belly Dump Trailer S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GWWR Usage: Not Available Asset located in: Lake Worth, TX 1997 Schaller Manufacturing Roadmaster G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GWWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX 1999 Timpte 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42224XB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available

Lot#	Details	Lot #	Details
9106	2023 Vanguard REM VXP 53 53 ft x 102 in T/A Van Trailer S/N: 5V8VC5324PT305207 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9109	2022 Hyundai VC2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532K6NS852024 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: FRAME IS DAMAGED; Asset located in: Lake Worth, TX 2022 Inland IN53-DPA-HK40 53 ft x 102 in T/A
01064	Asset located in: Humble, TX	-	Van Trailer
9106A	2023 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D1PL364744 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires		S/N: 3T9S372N5NM180012 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	9111	2021 Inland 53 ft x 102 in T/A Van Trailer
	Notes: . Asset located in: Lake Worth, TX		S/N: 3T9S372N9MM180044 C/W: 68000 lb GVWR, Air Ride Suspension, Air
9106B	·		Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Asset located in : Lake Worth, TX
		9112	2021 Inland 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N0MM180045 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door Usage: Not Available
9106C	2023 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer	0112	Asset located in: Lake Worth, TX
	S/N: 1JJV532D3PL364745 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX	9113	2021 Inland IN53-DPA-HK40 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N7MM180124 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9107	2022 Vanguard MaxCube 53 ft x 102 in T/A	9119	2020 Wabash 53 ft x 102 in T/A Van Trailer
	Van Trailer S/N: 5V8VA5321NM211220 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9119	S/N: 1JJV532D4LL162426 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275 /80R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
9108	2022 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX21NG001704 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9120	2019 Great Dane CCC-3314-21053 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0621KJ137637 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9128	2015 Wabash DVHDHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D9FL880526 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Notes:
9121	2019 Utility 53 ft x 102 in T/A Van Trailer	2422	Asset located in: Lake Worth, TX
	S/N: 1UYVS2539K3560164 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION	9129	2015 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D1FL799987 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9130	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer
9122	Asset located in: Lake Worth, TX 2018 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9JR390021 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood		S/N: 1JJV532D3FL845934 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
l L	Floor, Swing Door Usage: Not Available	9131	2015 Wabash DVCVHPC 53 ft x 102 in T/A Van
9123 2018 Stoughton ZGPVW-535 in T/A Van Trailer S/N: 1DW1A5320JSA09456 C/W: Aluminum/Steel Combi Spring Suspension, Sliding Si	-		Trailer S/N: 1JJV532DXFL833585 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9132	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer
9126	2015 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D5FL877087 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension,		S/N: 1JJV532DXFL842528 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9136	2012 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9CT100009 C/W: Air Ride Suspension, Sliding Suspension,
9127	2015 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2531FG241727 C/W: 65000 lb GVWR, Aluminum/Steel Combination Frame, Air Ride Suspension, Air		Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9137	2012 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0628CT566670 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9137A	2012 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0628CT567767 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR, Right Weigh Load Scale Usage: Not Available Asset located in: Lake Worth, TX	9146	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06287T539717 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
9139	2009 Vanguard 53 ft x 102 in T/A Van Trailer		Asset located in: Lake Worth, TX
	S/N: 5V8VA53269M903270 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9147	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06247G341628 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb
9140	2009 Vanguard 53 ft x 102 in T/A Van Trailer		GVWR Usage: Not Available
	S/N: 5V8VA532X9M903272 C/W: Air Ride Suspension, Sliding Suspension,		Asset located in: Humble, TX
	Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX	9148	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06277J622907 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Page 205 (TERO) 5 Time (2000 lb.)
9141	2008 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53208B027611 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor,	9149	Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in : Humble, TX		2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06217J618769 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9142	2008 Hyundai 53 ft x 102 in T/A Van Trailer S/N: 3H3V532C18T249117 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor,		
	Roll-Up Door, Mixed Tires Usage: Not Available Notes: THE CLOSING TIME OF LOTS 8674 TO 8675 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER OF LOTS 8674 TO 8675 IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER.	9150	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06277D423628 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 30845 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9143	Asset located in: Lake Worth, TX 2008 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E95388E520408 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9151	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06227D423651 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445 /50R22.5 Super Single Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9145	2008 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS253X8P320087 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9152	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06287D426747 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 68000 lb GVWR Usage: Not Available	9160	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W37L094904 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9161	2007 Wabash 53 ft x 102 in T/A Van Trailer
9153	2007 Great Dane 7411TP 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06237D423576 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445 /50R22.5 Super Single Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1JJV532W07L051279 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9162	2007 Wabash DVLHHSA 53 ft x 102 in T/A Van Trailer
9154	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06257J618967 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR		S/N: 1JJV532W37L064138 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	9163	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W97L079985 C/W: Air Ride Suspension, Sliding Suspension,
9155	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06217D423608 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing		Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Door, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Asset located in : Humble, TX	9164	2007 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W27L080010 C/W: Air Ride Suspension, Sliding Suspension,
9157	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06207J623042 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR		Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2007 Wabash 53 ft x 102 in T/A Van Trailer
	Usage: Not Available Asset located in: Humble, TX		S/N: 1JJV532W97L080022 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor,
9158	2007 Lufkin TFV-CL-SP 53 ft x 102 in T/A Van Trailer S/N: 1L01A532071163667 C/W: Air Ride Suspension, Air Brakes, Sliding		Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9167	2006 Wabash 53 ft x 102 in Van Trailer S/N: 1JJV532W76L978391 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available
9159	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W07L048317 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door Usage: Not Available Asset located in: Lake Worth, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9167A	2006 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W36L985340 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9175	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532261161062 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR
9168	2006 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS25386G753257 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension,		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX	9177	2006 Great Dane 7411T-SSL 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06206J610192 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
9170	2006 Lufkin TFC-CL-110 53 ft x 102 in T/A Van Trailer		Asset located in: Lake Worth, TX
	S/N: 1L01A532361161071 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9178	2006 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532468871342 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9171	2006 Lufkin TFVCL110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532261160929 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9179	2006 Stoughton AVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53266E813926 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9172	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532661160948 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9180A	2005 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W95L938795 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9173	2006 Lufkin TFV-CL-110 53 ft T/A Van Trailer S/N: 1L01A532461161032 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9181	2005 Trailmobile 53 ft x 102 in T/A Van Trailer S/N: 2MN01JAH751003219 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9174	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532X61161066 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9182	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06224G332275 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9183	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06274G332238 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9191	2003 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06203G327168 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9184	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06244G332231 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9191A	2001 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06291B078413 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP
9185	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06274G332286		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX	9192	2001 Wabash Unknown 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W41L763639 C/W: Air Ride Suspension, Sliding Suspension, Hardwood Floor, Roll-Up Door, R22.5 Tires,
9186	2004 Wabash DVLHHSA 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W74L875727	9193	EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
	C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX		9193 2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W9YL723387 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door
9187	2004 Wabash JWHDHPC 53 ft x 102 in T/A Van Trailer	9194	Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1JJV532W44L873952 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		2000 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0626YB016106 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP
9188	2004 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W74L873251		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Lake Worth, TX	9195	2000 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E953XYD455230 C/W: 65000.0 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5
9189	2003 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W23L815529		Tires, EQUIPMENT-FRŎM-YELLOW-CORP Usage: Not Available Asset located in : Lake Worth, TX
	C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9197	1998 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532Y4WL427465 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9200	1997 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E953XVD412521 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	9223	2001 Fruehauf 40 ft T/A Van Trailer S/N: 1JJV402F81F732037 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX
9201	1996 Lufkin TFV-IPST 53 ft x 102 in T/A Van	9224	2001 Fruehauf Unknown 40 ft x 102 in T/A Van
9201	Trailer S/N: 1L01A5322T1120913 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 1JJV402F31F732060 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Lift Gate, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
9212	2016 Wabash DVCVHPC 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D9GL957237 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9229	1999 Fruehauf 45 ft x 102 in T/A Van Trailer S/N: 1JJV452FXXF543251 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX 1995 Strick 48 ft x 102 in T/A Van Trailer
9213	Trailer S/N: 1JJV401D1GL957202 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM-		S/N: 1S12E9489SD398829 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, hardwood floors with steel plate on top, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9232	1995 Pines 48 ft x 102 in T/A Van Trailer S/N: 1PNV482N3SKB67178 C/W: Aluminum Frame, Spring Suspension, Air
9220	2004 Great Dane 7311TPS 40 ft x 102 in T/A Van Trailer S/N: 1GRAA80234K262726		Brakes, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in : Lake Worth, TX
	C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9235	1988 Lufkin 48 ft T/A Van Trailer S/N: 1L01A4828J1078828 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, 295/75R22.5 Tires, 65000 I GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
9221	2001 Great Dane 7311 T S 48 ft x 102 in T/A Van Trailer		Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1GRAA96281G318316 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9236	1985 Budd 45 ft x 102 in T/A Van Trailer S/N: 1BK10W925FE217508 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9222	2000 Trailmobile 48 ft x 102 in T/A Van Trailer S/N: 1PT01JPH0Y8002343 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
9239	2020 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281DXLL216433 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Aluminum Roof, Wood and Aluminum Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available	9251	2002 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F32F778964 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX 1990 Stoughton FRPD-323S 32 ft S/A	
9240	Asset located in: Lake Worth, TX 2020 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D5LL216422 C/W: 40000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295	9252	Generator Trailer S/N: 1DW1A3217LS669202 C/W: Spring Suspension, Pintle Hitch, 295 /75R22.5 Tires, 68080 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
0041	/75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP Usage: Not Available Asset located in : Lake Worth, TX		1999 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F7XF625530 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT-	
9241	2017 Stoughton 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2812HB720243 C/W: Spring Suspension, Pintle Hitch, Hardwood Floor, Side Skirts, Roll-Up Door, R22.		FROM-YELLOW-CORP Usage: Not Available Asset located in : Lake Worth, TX	
	5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Rosharon, TX	9254	1998 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F4WF456405 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Ramp Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX 1990 Trailmobile 28 ft x 96 in S/A Van Trailer S/N: 1PT071NE8L9001242	
9242	2017 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D9HL987165 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 40000 lb GVWR			
9243	Usage: Not Available Asset located in: Lake Worth, TX 2014 Stoughton 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2819EB457745 C/W: Spring Suspension, Air Brakes, Pintle	9257	C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Hitch, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX		1988 TRMO 28 ft x 96 in S/A Van Trailer S/N: 1PT071NE8J9009726 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb	
9244	2009 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281W29L286194		GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	C/W: Spring Suspension, Air Brakes, Pintle Hitch, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9258	S/N: 1PT071NE1J9006327 C/W: Aluminum/Steel Combination F Spring Suspension, Aluminum Roof,	1988 Trim 28 ft x 102 in S/A Van Trailer S/N: 1PT071NE1J9006327 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Aluminum Floor, Ducted Floor, Roll-Up Door, 295/75R22.5
9245	2008 Great Dane Unknown 28 ft x 102 in S/A Van Trailer S/N: 1GRAA56178K295814 C/W: Spring Suspension, Pintle Hitch, Translucent Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX		Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9259	1988 Trailmobile 28 ft x 102 in S/A Van Trailer S/N: 1PT071NE4J9002630 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Aluminum Floor, Ducted Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2020 Wabash 53 ft x 102 in T/A Spread Axle Refrigerated Trailer S/N: 1JJV532B4LL218265 C/W: 68000 lb GVWR, Aluminum/Steel	9268	2018 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XJ6106924 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, Carrier 7300 Refrigeration Unit, Serial Number SAL91508417,, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	Combination Frame, Air Ride Suspension, Air Brakes, Sliding Suspension, Front/Rear Vents, Swing Door, 2008 Thermo King TK486V Refrigeration Unit, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9269	2018 Utility 53 ft x 102 in T/A Spread Axle Multi-Temp Refrigerated Trailer S/N: 1UYVS2536J2130709 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
9265	2020 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer		Asset located in: Lake Worth, TX
	S/N: 1UYVS2539L2821820 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Thermo King Precedent Refrigeration Unit, Serial Number 6001278644,, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9270	2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2530HU891122 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Thermo King S-600 Refrigeration Unit, Serial Number 6001220977, Aluminum Wheels, 295/75R22.5 Tires Usage: 19,620 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
9265A	2019 Wabash RFALHSA 53 ft x 102 in T/A		PRIOR TO BIDDING Asset located in: Lake Worth, TX
9267	Refrigerated Trailer S/N: 1JJV532B6KL090898 C/W: Spring Suspension, Air Brakes, Side Skirts, Ducted Floor, Swing Door, Carrier X4 7500 Refrigeration Unit, Serial Number SAW91536396,, 295/75R22.5 Tires, 68000.0 lb GVWR Usage: 23,849 Hr Asset located in: Lake Worth, TX 2018 Utility 53 ft x 102 in T/A Spread Axle	9271	2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538HU767213 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2016 Carrier 7300 X4 Refrigeration Unit, Serial Number RAV91457566,, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available
323	Refrigerated Trailer S/N: 1UYVS2536J2076912 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 11R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9272	Asset located in: Lake Worth, TX 2017 Great Dane FTL-1114-31053 Refrigerated Trailer S/N: 1GRAA0627HB700016 Usage: 14,488 Hr Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; Asset located in: Humble, TX

Wabash RFALHSA 53 ft x 102 in T/A gerated Trailer 1JJV532B0EL788928 Air Ride Suspension, Sliding Suspension, ed Floor, Swing Door, 2013 Carrier X2 APX Refrigeration Unit, Serial Number 91348526,, 295/75R22.5 Tires, 68000 lb R e: Not Available t located in: Humble, TX Wabash RFALHSA 53 ft x 102 in T/A gerated Trailer 1JJV532BXEL817674 Air Ride Suspension, Air Brakes, Sliding ension, Ducted Floor, Swing Door, Thermo Refrigeration Unit, Serial Number 144127,, 295/75R22.5 Tires, 68000 lb R
gerated Trailer 1JJV532BXEL817674 Air Ride Suspension, Air Brakes, Sliding ension, Ducted Floor, Swing Door, Thermo Refrigeration Unit, Serial Number 144127,, 295/75R22.5 Tires, 68000 lb R
1JJV532BXEL817674 Air Ride Suspension, Air Brakes, Sliding ension, Ducted Floor, Swing Door, Thermo Refrigeration Unit, Serial Number 144127,, 295/75R22.5 Tires, 68000 lb R
e: 9,279 Hr t located in : Lake Worth, TX
Wabash RFALHSA 53 ft x 102 in T/A
gerated Trailer 1JJV532B9EL817679 Aluminum/Steel Combination Frame, Air Suspension, Sliding Suspension, Curbside Ducted Floor, Swing Door, Thermo King edent Refrigeration Unit, Serial Number 144132,, 295/75R22.5 Tires, 68000 lb R e: 29,942 Hr
t located in: Lake Worth, TX
Hyundai 53 ft x 102 in T/A Refrigerated er 3H3V532C8DT512004 Aluminum/Steel Combination Frame, Air Suspension, Sliding Suspension, Curbside, Ducted Floor, Roll-Up Door, Thermo King geration Unit, Serial Number 6001128459,,75R22.5 Tires, 68000 lb GVWR e: 20,603 Hr t located in: Lake Worth, TX
Hyundai 53 Ft x 102 In T/A Refrigerated er 3H3V532C5DT512008 Aluminum/Steel Combination Frame, Air Suspension, Sliding Suspension, Curbside, Ducted Floor, Swing Door, Thermo King to Refrigeration Unit, Serial Number 128461,, 295/75R22.5 Tires, 68000 lb R e: Not Available t located in: Lake Worth, TX Utility VS2RA 53 ft x 102 in T/A gerated Trailer 1UYVS2537CM264524 Air Ride Suspension, Sliding Suspension, ed Floor, Swing Door, 2013 Carrier 2500R
C :: (3) (1) (2)

Lot #	Details	Lot #	Details
9292	2012 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C4CT436005 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Roll-Up Door, Thermo King SB230 Refrigeration Unit, Serial Number 6001103448,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	9308	2014 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2480EU771507 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King Refrigeration Unit, Serial Number 600133514,, 11R22.5 Tires, 65000 lb GVWR Usage: 27,250 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9309	2013 Utility VS2RA 48 ft x 102 in T/A
9293	2012 Hyundai 53 ft x 102 in T/A Refrigerated Trailer S/N: 3H3V532C7CT436001 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001103459,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 23,320 Hr	9310	Refrigerated Trailer S/N: 1UYVS2480DM567319 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 60011112528,, 11R22.5 Tires, 65000 lb GVWR Usage: 48,998 Hr Asset located in: Lake Worth, TX 2013 Utility VS2RA 48 ft x 102 in T/A
	Asset located in: Lake Worth, TX		Refrigerated Trailer
9302	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0622CW703603 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Side Skirts, Swing Door, Carrier 2100A Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available		S/N: 1UYVS248XDM771710 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 6001128316,, 11R22.5 Tires, 65000 lb GVWR Usage: 42,743 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9311	2014 Utility 48 ft x 102 in T/A Refrigerated
9303	<u> </u>		Trailer S/N: 1UYVS2483EU771503 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001133500,, 11R22.5 Tires, 65000 lb GVWR Usage: 31,576 Hr Asset located in: Lake Worth, TX
	Usage: 32,464 Hr Notes: .	9312	2012 Utility VS2RA 48 ft x 102 in T/A
9306	Asset located in: Lake Worth, TX 2006 Wabash 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532W86L980540 C/W: Spring Suspension, Sliding Suspension, Swing Door, Carrier Refrigeration Unit, 295 /75R22.5 Tires		Refrigerated Trailer S/N: 1UYVS2483CU463504 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2011 Thermo King Smart Reefer 2 Refrigeration Unit, 11R22.5 Tires, 65000 lb GVWR Usage: 48,492 Hr Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in : Lake Worth, TX	9313	2012 Utility 48 ft x 102 in T/A Refrigerated
9307	2015 Great Dane ECM-113 48 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA9622FE702031 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Whisper Refrigeration Unit, Serial Number 6001178338,, 295/75R22.5 Tires Usage: 27,626 Hr Asset located in: Lake Worth, TX		Trailer S/N: 1UYVS2489CU248709 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2013 Thermo King Refrigeration Unit, Serial Number 6001133500,, 295/75R22.5 Tires, 65000 lb GVWR Usage: 31,576 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9314	2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2488CU463501 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001103810,, 11R22.5 Tires, 65000 lb GVWR	9322	2019 Holcombe HM12H Tri/A Volumetric Mixer Trailer S/N: 16MBB3132KF078754 C/W: Spring Suspension, 255/70R22.5 Tires, 75000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: 49,586 Hr Asset located in: Lake Worth, TX	9323	2024 44 ft x 12 ft 1 in Portable Tri/A Mobile Office	
9315	2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS248XCU463502 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2011 Thermo King Refrigeration Unit, Serial Number	9324	S/N: 102410 C/W: (2) Offices, (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 8- 14.5 Tires Usage: Not Available Asset located in: Lake Worth, TX 2022 20 ft x 8 ft Mobile Office	
	6001103816,, 65000 lb GVWR Usage: 50,063 Hr Asset located in : Lake Worth, TX		S/N: TJCC22122989 C/W: 12000 BTU Heat and AC Split System, Indoor Breaker Box, R-13 Insulation, 2	
9317	1996 Trailmobile 28 ft x 96 in S/A Refrigerated Trailer S/N: 1PT071NE2T9002371 C/W: Spring Suspension, Air Brakes, Ducted Floor, Roll-Up Door, Thermo King Sentry II Max Refrigeration Unit, Serial Number 1145AL6026,, 11R22.5 Tires, 40000 lb GVWR		windows, Metal Front Door, Security Bars, Security Locks on all Doors, LED Lighting, Wood Trim, Laminated Flooring Storage Roof for High Value Tools and Equipment, Chargin Dock for Power Tools, Wire Shelving in Store Room Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in: Lake Worth, TX	9325	28 ft x 8 ft Portable S/A Mobile Office S/N: Not Available C/W: (2) Offices, Spring Suspension, Sliding Suspension, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
9318	1995 Trailmobile 28 ft S/A Refrigerated Trailer S/N: 1PT071NE6S9012996 C/W: Spring Suspension, Roll-Up Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available	9326		
	Asset located in: Lake Worth, TX		28 ft x 8 ft Portable S/A Mobile Office S/N: Not Available C/W: (2) Offices, Air Conditioner, Spring Suspension, EQUIPMENT-FROM-A-PRIMORIS SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
9319 1993 Great Dane 7011Z-1 28 ft Refrigerated Trailer S/N: 1GRAA5614PB081703 C/W: Spring Suspension, Air Bra	S/N: 1GRAA5614PB081703 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Roll-Up Door, Thermo King Refrigeration	9327 9328Z		
	Unit, Serial Number 0132822805,, 11R22.5 Tires, 39000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		2024 Garper GP8-24 19 ft 8 in x 8 ft 3 in Portable S/A Mobile Office S/N: 3ECG24C1XRGEP0174	
9320	1993 Great Dane 7011Z-1 28 ft x 102 in S/A Refrigerated Trailer S/N: 1GRAA5615PB081709		Usage: Not Available	Hitch, Spring Suspension, 225/75R15 Tires
	C/W: Spring Suspension, Air Brakes, Roll-Up Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 39000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX		2024 Garper GP8-24 19 ft 9 in x 8 ft 3 in Portable S/A Mobile Office (Unused) S/N: 3ECG24C1XRGEP0175 C/W: (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 225/75R15 Tires	
9321	1992 TRMB 28 ft x 96 in S/A Refrigerated Trailer		Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: 1PT071NE4N9012595 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Thermo King SII-50 MAX Refrigeration Unit, Serial Number 0322628122,, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9329	36 ft x 12 ft 1 in Portable T/A Mobile Office S/N: 135369 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, 8-14.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9330	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR29SG000287 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 9330	9347	2023 Horizon 40 ft T/A Container Trailer (Unused) S/N: 3H7KC402XPR000334 C/W: Spring Suspension, 40 ft - Container Pins, 11R22.5 Tires, 50000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	THRU 9335 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX	9350	2023 GRUPO 15 ft 8 in T/A Container Trailer S/N: 3BZPN402XPC008328 C/W: 65000 lb GVWR, Air Ride Suspension, 295 /75R22.5 Tires Usage: Not Available Asset located in: Midland, TX
9330A	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR21SG000302 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 9330	9351	2023 Kerr-Bilt 40 ft Container Trailer S/N: 1J9GC402XPB253228 C/W: Aluminum Frame, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
	THRU 9335 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX	9351A	2018 Benlee TASMRS26S T/A Roll-Off Trailer S/N: 1B9A12625JB180059 C/W: Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9334	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR21SG000297 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available	9352	2011 Dragon T/A Roll-Off Trailer S/N: 1D9SH4824BC661799 C/W: 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE CLOSING TIMES OF LOTS 9330 THRU 9335 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX	9353	2008 Dragon TCT440 T/A Two Rolloff Can Roll-Off Trailer S/N: 1UNSH48288C066531 C/W: Air Ride Suspension, Aluminum Wheels, 285/75R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9335	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR22SG000292 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THE CLOSING TIMES OF LOTS 9330 THRU 9335 ARE TIED TOGETHER. IF A BID IS	9354	2000 ESPM TCT1101 T/A Two Rolloff Can Roll-Off Trailer S/N: 1E9RS4823Y1229101 C/W: Air Ride Suspension, Aluminum Wheels, 285/75R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9346	RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES, THE HIGH BIDDER ON EACH PIECE WILL BE THE WINNER Asset located in: Lake Worth, TX 2024 Atro 53 ft T/A Container Trailer (Unused) S/N: 3ELA6CX24RG000212	9356	2023 MaxxD RPX8316G T/A Roll-Off Trailer (Unused) S/N: 5R8GR1625PM105017 C/W: Spring Suspension, Electric Brakes, 215 /75R17.5 Tires, 19200 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Sliding Suspension, 53 ft - Container Pins, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9357	2023 Texas Pride RO71618KGN T/A Roll-Off Trailer S/N: 7HCGD1626PB039384 C/W: 18000 lb GVWR, Spring Suspension, Electric Brakes, Electric Roll Tarp, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9358	2016 Texas Pride Tri/A Gooseneck Roll-Off Trailer S/N: 1B973HGD9GB624110 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 7.50R16 Tires, 24000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9370	2012 Texas Bragg T/A Cooling Trailer S/N: 17XFT162XC1026523 C/W: Ball Hitch, Walking Beam Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9359	2016 Texas Pride T/A Roll-Off Trailer S/N: 1B9G2DGD1GB624162 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9371	2019 Cargo Craft T/A Splicing Trailer S/N: 4D6EB1225KC054750 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available
9360	1996 T/A Roll-Off Trailer S/N: 1B9B14526TB183122 C/W: Air Ride Suspension, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9361	1987 G & H T/A Roll-Off Trailer S/N: 87080757 C/W: Spring Suspension, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9372	S/A BBQ trailer S/N: Not Available C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, Two benches with storage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9362	2023 Diamond Cargo T/A 20' Concession Trailer		Asset located in: Humble, TX
	S/N: 53NBE2020P1101295 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9990 lb GVWR, Side Entry Door Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9375	2016 CZ Engineering Pole Trailer S/N: 4CZPR2717G113G030 C/W: Lunette Ring Hitch, Air Ride Suspension, Electric Brakes, 2 Stanchions, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9376	2014 Bat 35TA Pole Trailer S/N: 1B9FB35264A439L69
9365	2022 FUD Concessions Trailer S/N: 3F9F1A329NM066595 C/W: Ball Hitch, Spring Suspension, 195R15C Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		C/W: 22400 lb GVWR Lunette Ring Hitch, Spring Suspension, Electric Brakes, 4 Stanchions, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9376B	2001 Pole Trailer
9367	2023 Freedom 8.5x28TA4G T/A Graco Spray Foam Trailer S/N: 5WKGE2829P1078616 C/W: 14000 lb GVWR, Torsion Axle, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX 2018 ED Trailers T/A Cooling Trailer		S/N: 1U9CL47401A001680 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 3 Stanchions, 235/85R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
7307	S/N: 3A9BD1829J7266191 C/W: Ball Hitch, Walking Beam Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9379	2024 Silverback 45CHGN3 Tri/A 3 Car Open Car Carrier Trailer S/N: 4S9GC4535RH623425 C/W: Spring Suspension, 235/85R16 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9380	2025 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2121ST012579 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9388	2024 East Texas 16 ft T/A Dump Utility Trailer S/N: 58SBD1625RE038870 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9383	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1920HA988585 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX	9389	2024 MaxxD DTX8316 16 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1620RM116972 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available
9384	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1927HA989006 C/W: Spring Suspension, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9390	Asset located in: Lake Worth, TX 2024 STL Industrial 16 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1629RM336009 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 12800 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9385	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1927HA988910 C/W: Aluminum Frame, Ball Hitch, Surge Brakes, Soft Ties, 225/75R15 Tires, 5000 lb GVWR, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	9391	2024 MaxxD D9X9616 16 ft Tri/A Dump Utility Trailer (Unused) S/N: 5R8BD1637RM116735 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 21000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9386	PROCESS TITLE Asset located in: Lake Worth, TX 2017 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1926HA989031 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: Asset located in: Lake Worth, TX		2022 Big Tex 16 ft T/A Dump Utility Trailer S/N: 16V1D2122N5116206 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 98 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9386A	2019 PJ DD202 20 ft T/A Gooseneck Dump Utility Trailer S/N: 4P5DD2029K1311819 C/W: Spring Suspension, 97 in Deck Width, Steel Decking, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Asset located in: Midland, TX		2016 Texas Made DT71616KBP 16 ft T/A Dump Utility Trailer S/N: 59JT1DG22GD595839 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 86 in Overall Width, Steel Decking, 235/85R16 Tires, 12000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
9387	2016 Texas Made 22 ft T/A Dump Utility Trailer S/N: 59JT1DG22GD595842 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 85 in Overall Width, Steel Decking, 215/75R17.5 Tires, 12000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9394	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1120875 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9401	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3366S1120877 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9395	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1120873 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9402	2025 Southland SL714-14K 14 ft S/A Dump Utility Trailer (Unused) S/N: 2SFJL3361S1120883 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9396	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1116826 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9403	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3364S1120876 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available
9397	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL336XS1120655 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9404	Asset located in: Lake Worth, TX 2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1116823 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available
9398	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116824 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9405	Asset located in: Lake Worth, TX 2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1118976 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9399	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3363S1120884 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9406	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1120405 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9400	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3360S1116825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9407	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118932 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9408	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3360S1115257 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9414	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3367S1118981 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9409	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3366S1118924 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9415	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118980 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9410	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3364S1118923 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9416	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer S/N: 2SFKL4368S1113438 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9411	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3368S1118925 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX	9417	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4366S1113437 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 88 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9412	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4364S1113436 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9418	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1116854 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9413	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4362S1113435 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9419	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116855 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

	Details	Lot #	Details
Lot # 9420	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3360S1116856 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9426	2024 ED Trailers 14 ft T/A Dump Utility Trailer S/N: 3LHBS1423R7000182 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 84 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9421	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3365S1116853 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available	9427	2024 Maxey Maxx-D DKX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1420RM116473 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2024 MaxxD D9X9614 14 ft T/A Dump Utility
9422	Asset located in: Lake Worth, TX 2025 Industrias America 7014R 14 ft T/A Dump Utility Trailer S/N: 3EZBTC14XSA003766 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 7000 lb GVWR		Trailer (Unused) S/N: 5R8BD1428RM116057 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9423	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2025 MaxxD DTX8314 14 ft T/A Dump Utility	9429	Trailer (Unused) S/N: 5R8BD1424RM116489 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires
	Trailer (Unused) S/N: 5R8BD1421SM118478 C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum Flooring, 215/75R17.5 Tires, 17500 lb GVWR Usage: Not Available	9432	Usage: Not Available Asset located in: Lake Worth, TX 2025 MaxxD DTX8312 T/A Utility Trailer (Unused) S/N: 5R8BD1221SM118015
9424	Asset located in: Lake Worth, TX 2025 Maxey MaxxD 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1420SM117659	9433	C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2025 Industrias America FT510 10 ft T/A Dump Utility Trailer S/N: 3EZBTC10XSA004056 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 59 in Deck Width, 78 in Overall Width, Steel Decking, 225/75R15 Tires, 7000 lb GVWR
9425	2024 MaxxD DTX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD142XRM116741 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9434	2025 Industrias America FT510 10 ft T/A Dump Utility Trailer S/N: 3EZBTC105SA004059 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 59 in Deck Width, 77 in Overall Width, Steel Decking, 235/75R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9442	2025 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2125ST012570 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9443	2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer
9437	2014 Interstate 40 ft T/A Tilt Deck Trailer S/N: 1JKGTL605EM012923 C/W: Spring Suspension, Deck Over Tires, 24 ft 5 in Deck Tilting Length, 102 in Deck Width, 245 /70R17.5 Tires Usage: Not Available		S/N: 3EZBTP225SA004019 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9444	2025 Industrias America 167T 20 ft T/A Tilt
9437A	Maxey T/A Gooseneck Hydraulic Tail Trailer S/N: Not Available C/W: Spring Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, Hydraulic Jacks Usage: Not Available		Deck Trailer S/N: 3EZBTP223SA004021 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9445	2025 Industrias America 167T 20 ft T/A Tilt
9438	2023 HD 30 ft T/A Tilt Deck Trailer S/N: 7LKH3AL2XPP001032 C/W: 16500 lb GVWR, Spring Suspension, Electric Brakes, Storage Compartments, Deck Over Tires, 97 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX		Deck Trailer S/N: 3EZBTP221SA004020 C/W: Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9439	2021 Delco 24 ft T/A Tilt Deck Trailer	0446	· · · · · · · · · · · · · · · · · · ·
3403	S/N: 5WWGC2422M6016631 C/W: Torsion Axle, Electric Brakes, 24 ft Deck Tilting Length, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	9446	2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP225SA004022 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9447	2023 Big Tex 20 ft T/A Tilt Deck Trailer
9440	2019 Big Tex 22 ft T/A Tilt Deck Trailer S/N: 16VEX222XK2093519 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft 9 in Deck Tilting Length, 75 in Deck Width, 215/75R17.5 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 16V1C252XP2271331 C/W: Ball Hitch, Spring Suspension, 16 ft Deck Tilting Length, 72 in Deck Width, 235/80R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
9441	2017 Felling 22 ft T/A Tilt Deck Trailer		PRIOR TO BIDDING Asset located in: Humble, TX
	S/N: 5FTCE2923H1002738 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Deck Tilting Length, 82 in Deck Width, 215/75R17.5 Tires, 19120 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9448	2015 Butler 20 ft T/A Tilt Deck Trailer S/N: 1BUD18202F1007915 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 78 in Deck Width, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9449	2015 Towmaster 16 ft T/A Tilt Deck Trailer S/N: 4KNTT162XFL160923 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Winch, 16 ft Deck Tilting Length, 82 in Deck Width, 235/85R16 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2025 Double A 12 ft S/A Tilt Deck Trailer (Unused) S/N: 1UFBU1219ST012572	9455	2001 Phelan 25TA-D 25 ton 29 ft Tri/A Equipment Trailer S/N: 40FR0303113020550 C/W: Lunette Ring Hitch, Spring Suspension, 24 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 60540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2008 Towmaster 25 ft T/A Equipment Trailer S/N: 4NKTF20298L163620
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 12 ft Deck Tilting Length, 79 in Deck Width, 225/75R15 Tires, 5200 lb GVWR, 2" Adjustable Bulldog Style Coupler, 2000# Set Back Jack, 7 Way Plug And Wiring, Sealed LED Lights, Diamond Plate Fenders, 6 Stake pockets, 2" Treated Lumber Floor, Safety Chains, Spare Rack	9457	C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 101 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235 /85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2016 Load Trail 42 ft Tri/A Gooseneck Equipment Trailer S/N: 4ZEGC4031G1100325 C/W: Spring Suspension, Electric Brakes, 40 ft 4 in Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, 101.5 in Overall Deck Width,
9450A	1974 Miller 18 ft T/A Tilt Deck Trailer S/N: 16982 C/W: Lunette Ring Hitch, Walking Beam Suspension, Deck Over Tires, 18 ft Deck Tilting		Storage Compartments, Manual Ramps, Wood Flooring, 235/80R16 Tires, 24990 lb GVWR Usage: Not Available Asset located in: Midland, TX
	Length, 96 in Deck Width, 8.25R15 Tires Usage: Not Available Asset located in: Lake Worth, TX		2025 X-STAR 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1X9T3GS28SH039957
9451	2018 PJ Trailers 20 ft T/A Equipment Trailer S/N: 4P5L52025J1284500 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 101.5 in Usable Deck		C/W: Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Width, Deck Over Tires, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available	9459	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Midland, TX	9460	S/N: 5R8GF4025SM119348 C/W: Air Ride Suspension, Electric Brakes, 34 ft 11 in Main Deck, 5 ft 9 in Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted
9453	1995 Norris 40 ft T/A Gooseneck Flatbed Trailer S/N: 1N9FS4023SC007555 C/W: Spring Suspension, Electric Brakes, Wood		Ramps, Wood Flooring, 215/75R17.5 Tires, 25990 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Flooring, 235/85R16 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2024 RAWMAXX FDX-40-27K 40 ft T/A Gooseneck Equipment Trailer S/N: 3EVGF4027R1109090 C/W: Spring Suspension, Electric Brakes, 34 ft
9454	2019 Interstate 50DLA 30 ft Tri/A Equipment Trailer S/N: 1JKDLA500KM016883 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 24 ft Main Deck, 6 ft 2 in Fixed Dovetail, 96 in Usable Deck Width, 101 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires, 60100 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		6 in Main Deck, 6 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/85R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
9461	2024 Horizon 40 ft T/A Gooseneck Equipment Trailer S/N: 3H7GF4022RR001350 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /85R16 Tires Usage: Not Available Asset located in: Midland, TX	9469	2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer S/N: 4ZEGH4023J1155164 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 101 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9464	2023 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4025PM101424 C/W: Spring Suspension, Electric Brakes, 34 ft 11 in Main Deck, 5 ft 9 in Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires, 25990 lb GVWR Usage: Not Available	9470	2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer S/N: 4ZEGH4021J1162680 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9465	Asset located in: Lake Worth, TX 2023 Delco 40 ft T/A Gooseneck Equipment Trailer S/N: 5WWGF4023P6029756 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires Usage: Not Available Asset located in: Midland, TX	9471	2009 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GN40229M011427 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 225/90D16 Tires, 20000 lb GVWR Usage: Not Available
9466	2023 HD Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 7LKH3AP29PP000996 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9472	Asset located in: Lake Worth, TX 2017 Texline 35' GNI/D 35 ft T/A Gooseneck Equipment Trailer S/N: 5HNGN352XH1000107 C/W: Spring Suspension, Electric Brakes, 30 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22000 lb GVWR Usage: Not Available
9467 9467A	Trailer	9473	Asset located in: Lake Worth, TX 2012 Texas Bragg 35 ft T/A Gooseneck Equipment Trailer S/N: 17XFG3528C1024464 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 4P53F4924N1364159 C/W: 25900 lb GVWR, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Midland, TX	9474	2009 Texas Bragg 35 ft T/A Gooseneck Equipment Trailer S/N: 17XFG352791093459 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 92 in Usable Deck Width, 102 in Overall Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9475	2025 MaxxD LDX10232 32 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 5R8GF3227SM117723 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 6 ft 1 in Fixed Dovetail, 93 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9480	2015 Kearney 28 ft Tri/A Gooseneck Equipment Trailer S/N: 5LCFT2830F1037125 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 4 ft Fixed Dovetail, 82 in Usable Deck Width, Hydraulic Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9476	2023 Big Tex 16GN-25BK+5MR 30 ft T/A Gooseneck Equipment Trailer S/N: 16V3F3828P6255347 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9481	2025 Double A 26 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1UFGN2624ST012569 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9477	2020 Sure-Pull 30 ft T/A Gooseneck Equipment Trailer S/N: 1J9DG3024LJ143049 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 101 in Usable Deck Width, 101 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available	-9482	2024 Golden Arm 25 ft T/A Gooseneck Equipment Trailer S/N: 7S8GF2526RM000313 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft 6 in Fixed Dovetail, 94 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9484	2012 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer S/N: 16VGX2521C2632812 C/W: Spring Suspension, Electric Brakes, 25 ft
9478	2013 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer S/N: 16VGX2527D2674032 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22400 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION		Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22500 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
	Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX		2009 Starlite 25TAGN 25 ft T/A Gooseneck Equipment Trailer S/N: 13YFS25269C113505 C/W: Spring Suspension, 20 ft Main Deck, 5 ft 2-
9479	2001 HaWN 30 ft T/A Gooseneck Equipment Trailer S/N: 1H9GN302911176001 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 502 in Overall Deck Width, Spring		Position Dovetail, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Lake Worth, TX
	Assisted Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Notes: SELLING WITH AN SPI (FORM VTR-270) AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9485	2023 East Texas 24 ft T/A Gooseneck Equipment Trailer S/N: 58SGM2424PE036183 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 102 in Usable Deck Width, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9486	2025 Salvation 20 ft T/A Equipment Trailer (Unused) S/N: 7GG1U2022SW023510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Main Deck, 3 ft Fixed Dovetail, 82 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 225 /75R15 Tires, 10400 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9491	2025 Southland LBATR7-22 22 ft Tri/A Equipment Trailer (Unused) S/N: 2SFHL4463S1120662 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 2 ft Fixed Dovetail, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9492	2023 Maxey T/A 40 Ft Tilt Deck Trailer S/N: 5R8BC2226PM099011 C/W: Ball Hitch, Torsion Axle, Electric Brakes,
9487	2023 Maxey XX-D 26 ft T/A Equipment Trailer S/N: 5R8BC2627PM106865 C/W: Ball Hitch, Spring Suspension, Electric		Electric Powered Self Contained Hydraulic System, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
	Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9493	2022 Norstar 22 ft T/A Equipment Trailer S/N: 3EUGB2221N1011572 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Fixed Dovetail, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available
9488	2002 Parker 24 ft T/A Equipment Trailer	9494	Asset located in: Lake Worth, TX 2025 Southland LBATR7-20 20 ft Tri/A
	S/N: 13ZPF242121003713 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 18 ft 10 in Main Deck, 5 ft 2 in Fixed Dovetail, 85 in Usable Deck Width, 91 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/85R16 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Equipment Trailer S/N: 2SFHL4464S1120265 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available
9489	2020 Sure-Trac 23 ft T/A Equipment Trailer		Asset located in: Lake Worth, TX
	(Inoperable) S/N: 5JW2U2320L3262538 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 7 ft 6 in Upper Deck, 12 ft 4 in Main Deck, 3 ft 6 in Fixed Dovetail, 79 in Usable Deck Width, 79 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available	9495	2025 Southland LBATR7-20 20 ft Tri/A Equipment Trailer S/N: 2SFHL4462S1120264 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX 2014 Kaufman 23 ft T/A Equipment Trailer S/N: 5SHFP2329EB001257 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	Equipment Trailer (Unused) S/N: 7GG3U2022SW023483 C/W: Spring Suspension, Electric Brakes, Main Deck, 2 ft Fixed Dovetail, 82 in Usab	S/N: 7GG3U2022SW023483 C/W: Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 82 in Usable
			Deck Width, 102 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in : Lake Worth, TX
		9497	2025 X-STAR 20 ft T/A Equipment Trailer (Unused) S/N: 1X9T7GF21SH039958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 97 in Usable Deck Width, 101 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR, 2 in x 8 in Treated Lumber Floor, 7k Axles Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9498	2025 Double A 20 ft T/A Equipment Trailer (Unused) S/N: 1UFBU2029ST012573 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 0 ft Dovetail, 83 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/85R16 Tires, 14000 lb GVWR, 6" Channel Frame, 6" Wrap Tng, 3" Channel Cross Members, 2- 7000# Axles, 1 Brake 2-5/16 Coupler, 5' Slide in Ramps, 2' Dovetail, All LED Lighting, 10-Ply on 8 Hole Silver Mod, 12k Drop Leg Jack, Diamond Plate Fenders Usage: Not Available Asset located in: Lake Worth, TX	9504	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3313S1121179 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX 2025 Double A 18 ft T/A Equipment Trailer	
			(Unused) S/N: 1UFBU1827ST012571 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 77 in Usable Deck	
9499	2025 Double A 20 ft T/A Equipment Trailer (Unused) S/N: 1UFBU2026ST012580 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Width, 96 in Overall Deck Width, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR, 2" Bulldog Style Coupler, Brake and EBA, 5' Slide In Ramps Out Back, 2' Diamond Plate Dovetail, 2000# Set Back Jack, Safety Chains, Wiring and Flush Mount LED lights, ST205/75R15 5 on 5 silver mod, Diamond Plate Fenders, 2" Treated Lumber Floor, Stake pockets and Rub rail, Spare Rack Usage: Not Available	
9500	2022 East Texas 20 ft T/A Equipment Trailer S/N: 58SBM202XNE030305 C/W: Spring Suspension, 20 ft Main Deck, 96 in Usable Deck Width, 101 in Overall Deck Width,		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
	Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9506	2025 Double A 18 ft T/A Equipment Trailer (Unused) S/N: 1UFBU1822ST012574	
9501	2018 Big Tex 14ET-20BK-MR 20 ft T/A Equipment Trailer S/N: 16VEX2024J2005825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft 6 in Main Deck, 3 ft 6 in Fixed Dovetail, 84 in Usable Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Midland, TX		Brakes, 18 ft Main Deck, 77 in Us Width, 96 in Overall Deck Width, Ramps, Wood Flooring, 235/80R 14000 lb GVWR, HDCH, 6" Chanr Wrap Tng, 3" Channel Cross Mer 7000# Axles, 1 Brake 2-5/16 Cou Ramps, 2' Dovetail, All LED Light Hole Silver Mod, 12k Drop Leg Ja Plate Fenders Usage: Not Available	Usage: Not Available
9502	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC331XS1121177 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		9508 2025 Southland LBAT7-16 16 ft T/A Trailer S/N: 2SFJL336XS1116038 C/W: Ball Hitch, Spring Suspension, I Brakes, 81 in Usable Deck Width, 102 Deck Width, Manual Ramps, Wood F 235/80R16 Tires, 15432 lb GVWR Usage: Not Available	S/N: 2SFJL336XS1116038 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available
9503	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3318S1121176 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9509	2024 MaxxD H5X10216 16 ft T/A Equipment Trailer (Unused) S/N: 5R8BC1625RM116789 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Main Deck, 2 ft 2 in Fixed Dovetail, 82 in Usable Deck Width, 97 in Overall Deck Width, Manual Ramps, Wood Flooring, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	9515 9516	1998 Interstate 18 ft T/A Equipment Trailer S/N: 1JK0DT202WA001000 C/W: Spring Suspension, Air Brakes, 18 ft 9 in Main Deck, 5 ft Fixed Dovetail, 91 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX 1995 Norris 25 ft T/A Gooseneck Equipment
	PROCESS TITLE Asset located in: Lake Worth, TX		Trailer S/N: 1N9FS252XSC007758
9510	2021 Buck Dandy 16 ft T/A Equipment Trailer S/N: 4DHCS2028MS047369 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 225/75R15 Tires, 10400 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	_	C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 91 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX
9511		9516A	1991 Belshe 20 ft T/A Equipment Trailer S/N: 16JF01827M1021861 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Decking, 225/90R16 Tires Usage: Not Available Asset located in: Midland, TX
	Ib GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9517	1998 SHIRLEY FB 12 ft T/A Utility Trailer S/N: 4XMFS1220WL000008 C/W: Ball Hitch, Spring Suspension, 77 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 10000 lb GVWR Usage: Not Available
9512	2018 MMDI 614SLTD 14 ft T/A Equipment		Asset located in: Lake Worth, TX
	Trailer S/N: 5631F2024JM001703 C/W: Torsion Axle, 14 ft Main Deck, 5 ft 2 in Dovetail, 70 in Usable Deck Width, 97 in Overall Deck Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9520	2022 Salvation Trailers 20 ft T/A Utility Trailer S/N: 7GG1U2021NW019503 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 88 in Deck Width, Wood Flooring, 235 /80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9521	2018 Texline 20 ft T/A Utility Trailer
9513	2017 MMDI 7 ft S/A Equipment Trailer S/N: 5631F1419HM017255 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 7 ft Main Deck, 48 in Usable Deck Width, Manual Ramps, Steel Decking, 225 /75R15 Tires Usage: Not Available		S/N: 7HACU2025J1000949 C/W: Spring Suspension, Electric Brakes, 79 in Deck Width, 102 in Overall Width, Wood Flooring, 215/75R17.5 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9522	2018 Ameritrail 20 ft T/A Utility Trailer
9514	2016 Pratt CP0510 10 ft T/A Equipment Trailer S/N: 1P9UT1722GN343532 C/W: Torsion Axle, Surge Brakes, 60 in Usable Deck Width, Deck Over Tires, Manual Ramps, Steel Decking, 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 17YBP2021JB069894 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9523	2018 Kearney 20 ft T/A Utility Trailer S/N: 5LCLB2023J1047150 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 101 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	9527	2025 Double A 18 ft T/A Utility Trailer (Unused) S/N: 1UFBU1828ST012577 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Wood Flooring, 225 /75R15 Tires, 9995 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	9528	2014 Lamar 18 ft T/A Utility Trailer	
9524	2018 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2029JB069898 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION		S/N: 5RVUT1823EM017580 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available	
	Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW		Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW	
	Asset located in: Lake Worth, TX	0.500	Asset located in: Lake Worth, TX	
9524A	2014 PJ 20 ft T/A Utility Trailer S/N: 4P5P82022E1215956 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 235/85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9529	2014 CM 18 ft T/A Tilt Deck Trailer S/N: 5VNBU1821ET121130 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9525	2013 Ameritrail 20 ft T/A Utility Trailer	9530	2008 Big Tex 18 ft T/A Utility Trailer	
7020	S/N: 17YBP2029DB053351 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX		S/N: 16VPX182381320591 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, 90 in Overall Width, Wood Flooring, 235/85R16 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
9525A		0532	2005 Cortex 18 ft T/A Utility Trailer	
	S/N: 17XFT2026C1020393 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 97 in Overall Width, Wood Flooring, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9532	9532	S/N: WCC108217 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Wood Flooring, 235 /85R16 Tires, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX
9526	2011 Texas Bragg 20 ft T/A Utility Trailer	0500	<u> </u>	
	S/N: 17XFP2026B1014824 C/W: Ball Hitch, Spring Suspension, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 225 /90R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9533	2004 Cortex 18 ft T/A Utility Trailer S/N: WCC108200 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9534	2002 Diamond Pacesetter 18 ft T/A Utility Trailer S/N: 46UFU182721078242 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX	9542	2024 STL Industrial 12 ft Hydraulic Drop Deck Ground Load Trailer (Unused) S/N: 4B9BZ1220SM336008 C/W: Ball Hitch, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
9535	2017 Top Hat 16 ft T/A Utility Trailer S/N: 4R7BU1625HT167477 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Wood Flooring, 205 /75R15 Tires, 6000 lb GVWR, EQUIPMENT- FROM-PULICE-CONSTRUCTION	9543	2018 Barreto 6 ft S/A Trencher Trailer S/N: 1B9UC0616DL280544 C/W: Torsion Axle, 5.30-12 Tires Usage: Not Available Asset located in: Lake Worth, TX
9537	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX 2025 Double A 14 ft S/A Utility Trailer (Unused)		2018 Barreto 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0612JL280312 C/W: Aluminum Frame, Ball Hitch, 6 ft 3 in Deck Tilting Length, 45 in Deck Width, 5.30-12 Tires, 2200 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 1UFBU1418ST012575 C/W: Ball Hitch, Spring Suspension, 83 in Deck Width, 102 in Overall Width, Ramp, Wood Flooring, 205/75R15 Tires, 2995 lb GVWR, Pipe Top, 2" BD Coupler, All LED Lighting, 2k Set Back Jack, Diamond Plate Fenders, Treated Lumber Floor, Stake Pockets, Spare Rack, 2' Exp Dovetail, 2' Gate Usage: Not Available Asset located in: Lake Worth, TX		2019 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA29KU036221 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Side Door 225 /75R15 Tires, 7000 lb GVWR, Interior Racking Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
9539A	S/N: 16VAX101042A19454 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Wood Flooring, 225 /75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9546	2015 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA23FA018790 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Midland, TX 2015 LGS 16 ft T/A Enclosed Trailer
9540	Asset located in: Lake Worth, TX 2019 Pratt EZ-1980 19 ft T/A Tilt Deck Trailer S/N: 1P9UT1929KN343758 C/W: Ball Hitch, Electric Brakes, Electric Powered Self Contained Hydraulic System, 19 ft Deck Tilting Length, 69 in Deck Width, 225 /90R16 Tires, 14000 lb GVWR Usage: Not Available		S/N: 53BLTEA21FA018786 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Midland, TX
	Asset located in: Humble, TX	9548	2025 Southland LARCT52-826V-86 26 ft T/A
9541	2020 Pratt EZ-1480S 14 ft T/A Tilt Deck Trailer S/N: 1P9UT1425LN343409 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Electric Powered Self Contained Hydraulic System, 14 ft 10 in Deck Tilting Length, 79 in Deck Width, 235/85R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Enclosed Trailer (Unused) S/N: 2SFPL636XS1120196 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9549	2025 Southland LARCT52-826V-86 25 ft T/A Enclosed Trailer S/N: 2SFPK5313S1118257 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9555	2017 Cargo Craft Expedition 20 ft T/A Enclosed Trailer S/N: 4D6EB2021HC046825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 102 in Overall Width, 235/80R16 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: .
9550	2017 Forest River 24 ft T/A Enclosed Trailer		Asset located in: Lake Worth, TX
	S/N: 5NHUVHZ24HY029016 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 98 in Deck Width, 101 in Overall Width, Side Door 225/75R16 Tires, 9800 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Midland, TX	9556	2025 Southland LCHT35-718V-86 18 ft T/A Enclosed Trailer S/N: 2SFFL4367S1120950 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9551	2025 Southland LARCT52-822V-86 22 ft T/A		Asset located in: Lake Worth, TX
	Enclosed Trailer S/N: 2SFPK4318S1120466 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9557	2014 Haulmark 18 ft T/A Enclosed Trailer S/N: 575GB1821ET265892 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9552	2025 Southland LARCT52-822V-86 21 ft T/A	9558	2014 Haulmark 18 ft T/A Enclosed Trailer
	Enclosed Trailer S/N: 2SFPK4310S1118274 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Ramp, Side Door Aluminum Wheels, 225 /75R15 Tires, 11464 lb GVWR Usage: Not Available	3000	S/N: 575GB1823ET265909 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available
	Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9553	2025 Southland LARCT52-820F-86 20 ft T/A		PROCESS TITLE Asset located in: Lake Worth, TX
	Enclosed Trailer S/N: 2SFPK5365S1118272 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9559	2014 Haulmark 18 ft T/A Cooling/Heating station Enclosed Trailer S/N: 575GB1826ET265922 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: 8,663 Hr Asset located in: Lake Worth, TX
9554	2025 Southland LARCT52-820F-86 20 ft T/A Enclosed Trailer S/N: 2SFFK4310S1118271 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9560	2014 Haulmark 18 ft T/A Cooling/Heating station Enclosed Trailer S/N: 575GB1828ET265923 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/85R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9561	2018 Lark 17 ft T/A Enclosed Trailer S/N: 571BE1626JM030477 C/W: Ball Hitch, Spring Suspension, 80 in Deck Width, 102 in Overall Width, Ramp, Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9566	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3365S1112775 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9562	2025 Southland LCHT35-716V-86 16 ft T/A	9567	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer
7002	Enclosed Trailer (Unused) S/N: 2SFFH331XS1120960 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 84 in Overall Width, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		S/N: 2SFFH3313S1118418 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7815 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	PROCESS TITLE		PROCESS TITLE Asset located in: Lake Worth, TX
0560	Asset located in: Lake Worth, TX	9568	2025 Southland LCHT35-716V-86 16 ft T/A
9563	2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3363S1118428 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9300	Enclosed Trailer S/N: 2SFFL4368S1120956 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
9564	2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3365S1118429 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9569	2022 Rock Solid Cargo 16 ft T/A Enclosed Trailer S/N: 7H2BE1626ND044095 C/W: 7000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 84 in Overall Width, Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
0565	Asset located in: Lake Worth, TX	9570	2020 Carry-On 7X16 16 ft T/A Enclosed Trailer
9565	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL336XS1120371 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11709 lb GVWR		S/N: 4YMBC1621LT010101 C/W: Walking Beam Suspension, Electric Brakes, 74 in Deck Width, 83 in Overall Width, 225/75R15 Tires, 9990 lb GVWR, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	Usage: Not Available Asset located in: Lake Worth, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9572	2013 CM Trailers 16 ft T/A Enclosed Trailer S/N: 49TCB1621D1009364 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 79 in Deck Width, 80 in Overall Width, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; Asset located in: Lake Worth, TX	9578	2018 Interstate 14.5 ft T/A Enclosed Trailer S/N: 1UK500F28J1095011 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
9573	Trailer S/N: 5RTBE1628DD034600 C/W: Walking Beam Suspension, 78 in Deck Width, 80 in Overall Width, Side Door 205 /75R15 Tires, 7000 lb GVWR, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9579	2017 Doolittle 15 ft T/A Enclosed Trailer S/N: 1DGCS1428HM021181 C/W: Lunette Ring Hitch, Spring Suspension, 80 in Deck Width, 84 in Overall Width, 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
9574	2013 Contract 16 ft T/A Enclosed Trailer S/N: 49TCB1624D1009164 C/W: Ball Hitch, Torsion Axle, 78 in Deck Width, 98 in Overall Width, 235/80R16 Tires, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Midland, TX	9580	2018 Cargo Mate 14 ft T/A Enclosed Trailer S/N: 5NHULE420JY077081 C/W: Spring Suspension, Electric Brakes, 78 in Deck Width, 78 in Overall Width, 205/75R15 Tires, Bumper Pull with Plywood Decking and Walls. Wooden Shelving.; EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	
9575	2017 Doolittle 16 ft T/A Enclosed Trailer S/N: 1DGCS1422HM022245 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 84 in Overall Width, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX		THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX 2016 Lark United MFG VT6X14SA 14 ft S/A Enclosed Trailer S/N: 571BE1417GM017644	
9576	2025 Southland LCHT35-716V-86 15 ft T/A Enclosed Trailer S/N: 2SFFH3311S1120958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7815 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE		Brakes, 60 in Deck Width, Ramp, 2 Tires, EQUIPMENT-FROM-PULICE CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST ST	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2009 Mongoose 15 ft T/A Enclosed Trailer S/N: 5SMFL142091005960 C/W: Spring Suspension, Electric Brakes, 80 in Deck Width, 225/75R15 Tires, 10000 lb GVWR,	
9577	2025 Southland LCHT35-614V-78 14 ft T/A Enclosed Trailer S/N: 2SFFL2369S1120937 C/W: Ball Hitch, Torsion Axle, Electric Brakes,		EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
	69 in Deck Width, 92 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9583	2015 Wells Cargo TW101 10 ft S/A Enclosed Trailer S/N: 575200D14FT278094 C/W: Ball Hitch, Spring Suspension, 72 in Deck Width, 205/75R15 Tires, Honda EM6000SX Generator; EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9586	2017 Lark VT712TA 13 ft T/A Enclosed Trailer S/N: 5RTBE122XHD058103 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9593	1995 Wells Cargo CVC4025 40 ft T/A Gooseneck Enclosed Trailer S/N: 1WC200R24S2028367 C/W: Spring Suspension, Electric Brakes, 95 in Deck Width, 97 in Overall Width, Side Door 225 /90/16 Tires, 12000 lb GVWR, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	9594	2000 Wells Cargo T/A 12 ft Fiber Optic Trailer S/N: 1WC200E27Y1093265
9587	2015 Arising 7X12VTDW 12 ft T/A Enclosed Trailer S/N: 5YCBE1228FH021263 C/W: Walking Beam Suspension, Electric Brakes, 76 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY		C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 225/75R15 Tires, Predator 9000 Watt Generator, Roof Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFIC TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Usage: Not Available		Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9595	2016 Heartland Cyclone 44 ft Tri/A Toy Hauler Travel Trailer S/N: 5SFCG4436GE301886 C/W: Sleeps 2 People, 2 Slide Outs, Power
9589	12 ft T/A Enclosed Trailer S/N: Not Available C/W: Ball Hitch, Spring Suspension, Electric Brakes, 69 in Deck Width, 71 in Overall Width, Side Door 205/75R15 Tires, 11000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Leveling Jacks, Cummins 5.5 kW Generator, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
9590	2019 Lark VT612TA 12 ft T/A Enclosed Trailer S/N: 571BE1228KM031668		Asset located in: Lake Worth, TX
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, 425 gal Poly Tank Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9595A	2015 Gateway 3900SE 42 ft T/A Travel Trailer S/N: 5SFSG4129FE293059 C/W: Sleeps 8 People, 3 Slide Outs, Exterior Entertainment, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 7.5/16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
	Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A
9591	2012 Atlas AU712SA 12 ft S/A Enclosed Trailer S/N: 5HCKU1219CE025510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width,		REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	Ramp, Side Door 205/75R15 Tires, 3500 lb	OFOER	Asset located in: Lake Worth, TX
	GVWR Usage: Not Available Asset located in : Lake Worth, TX	9595B _	2013 Heartland 37QB Bighorn 41 ft T/A Travel Trailer S/N: 5SFBG4123DE255887
9592	2012 Arising 8 ft S/A Enclosed Trailer S/N: 5YCBE0817CH005074 C/W: Spring Suspension, 205/75R15 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		C/W: Sleeps 2 People, 4 Slide Outs, Power Leveling Jacks, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9595C	2014 Big Country 36 ft T/A Travel Trailer S/N: 5SFBG3629EE280670 C/W: Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9598	2012 Keystone Fuzion 37 ft Tri/A Toy Hauler Travel Trailer S/N: 4YDF37527CF811331 C/W: 7000 lb GVWR, 2 Slide Outs, 5th Wheel, Spring Suspension, Electric Brakes, 235/80/16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
9595D	2007 K-Z Montego Bay 36 ft T/A Travel Trailer S/N: 4EZFM372X7S052451	9598A	2012 Keystone Alpine 34 ft T/A Travel Trailer
	C/W: Sleeps 2 People, Dish Washer, 15400 lb GVWR, 4 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	J 5 5 5 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6	S/N: 4YDF34927CE780709 C/W: Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires, 5 Slide Outs Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
9596	2015 Kuntry Kustom 34 ft Tri/A Travel Trailer		Asset located in: Lake Worth, TX
	S/N: 1K9BU3933F1236485 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9598B	2011 Forest River Wildcat 34 ft T/A Travel Trailer S/N: 4X4FWCK28BV024670 C/W: 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires
9597	2014 Rich Kuntry Kustom 34 ft Tri/A Travel Trailer S/N: 1K9BU3934E1236252 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available		Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
05074	Asset located in: Lake Worth, TX	9599	2008 McKenzie Starwood LX 33 ft T/A Travel
9597A	2015 Keystone HM353RL15 37 ft T/A Travel Trailer S/N: 4YDF35326FA740535 C/W: Sleeps 8 People, Power Leveling Jacks, Power Awning, Roof Mounted Satellite Receiver, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available		Trailer S/N: 4K03B1M278E176497 C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9599A	2016 Keystone Montana 32 ft T/A Travel Trailer S/N: 4YDF3102XGA740309 C/W: 14285 lb GVWR, 3 Slide Outs, Power Leveling Jacks, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9599B	2011 Heartland Sundance 26 ft T/A Travel Trailer	9600C	2014 Forest River Lacrosse 33 ft T/A Travel Trailer
	S/N: 5SFSG3427BE213855 C/W: 3 Slide Outs, Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235 /80 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		S/N: 5ZT2LCYB9EB004792 C/W: Air Conditioner, 3 Slide Outs, Power Leveling Jacks, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available
			Notes: TEXAS BUYERS MUST STOP IN OFFICE
9599C	2014 Heartland Wilderness 28 ft T/A Travel Trailer S/N: 5SFNB3127EE271422 C/W: 2 Slide Outs, Bumper Pull, Spring		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available		Asset located in: Lake Worth, TX
	Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9601	2015 Gulf Stream Trailmaster 27 ft T/A Travel Trailer S/N: 1NL1GTM21F1117001 C/W: 7860 lb GVWR, Single Slide Out, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires
9600	2021 Forest River Alpha Wolf 29 ft T/A Travel Trailer		Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
	S/N: 5ZT2CKUB5M2001919 C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		PRIOR TO BIDDING
		06014	Asset located in: Lake Worth, TX
		960 IA	2012 Forest River 3006W 30 ft T/A Travel Trailer
			S/N: 4X4TRLF22C1843526 C/W: Sleeps 10 People, Single Slide Out, Powe Awning, Bumper Pull, Torsion Axle Suspension Electric Brakes, 225/75R15 Tires
06004	Asset located in: Lake Worth, TX	_	Usage: Not Available
9600A	2015 Keystone 30 ft T/A Travel Trailer S/N: 4YDT30R26F7207465		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	C/W: 2 Slide Outs, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available	9601B	2016 Keystone Outback 32 ft T/A Travel Trailer S/N: 4YDT32429GB451256
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE		C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available
	ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		Notes: THIS UNIT IT BEING SOLD WITH A BONDED TITLE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A
9600B	2014 Forest River 31 ft T/A Travel Trailer S/N: 4X4TRLG28E1853494 C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Leveling Jacks, Power Awning,		REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires	9601C	2016 Shadow Cruiser 28 ft T/A Travel Trailer
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		S/N: 5RXTD2821G1033089 C/W: Sleeps 2 People, Single Slide Out, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available
			Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9602	2009 Case 590 Super M 4x2 Backhoe Loader (Inoperable) S/N: N9C529033 C/W: Enclosed Cab, Air Conditioner, 94 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9604A	LS XU6168 4WD Utility Tractor (Inoperable) S/N: 2273000807 C/W: Enclosed Cab, Air Conditioner, 16 Forward 16 Reverse, Power Shuttle, Forward/ Reverse Shuttle, Tier 4, 68 hp Engine, Loader, Quick Coupler, Auxiliary Hydraulics, 72 in Scraper Blade, 9.5x24 Front Tires, 16.9-28 Rear Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9603	1993 Case 580SK 4x2 Backhoe Loader		Asset located in: Lake Worth, TX
	(Inoperable) S/N: JJG0172373 C/W: Enclosed Cab, Air Conditioner, 82 in Loader Bucket Usage: 6,290 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9604B	Massey Ferguson 471 2WD Tractor (Inoperable) S/N: 9363BL18041 C/W: Canopy, Manual Transmission, 2 Rear Remotes, 540 PTO, 3-Point Hitch, 7.50-16 Front Tires, 16.9/14-30 Rear Tires Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9605	Ford 2WD Tractor (Inoperable)
9603A	(Inoperable) S/N: 1T0410KXKCE223394 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Control Pattern Changer, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT	9605A	S/N: Not Available C/W: 4 Forward 1 Reverse, Manual Transmission, 540 PTO, 4.00-19 Front Tires, 11.2x28 Rear Tires Usage: 126 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 1959 Allis Chalmers D17 Antique Tractor
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL		(Inoperable) S/N: D1726103 C/W: 8 Forward 2 Reverse, Partial Powershift,
9604	Asset located in: Midland, TX 2016 John Deere 8245R 4WD Tractor (Inoperable) S/N: 1RW8245RCGP110724 C/W: Enclosed Cab, Air Conditioner, Air Ride		Gasoline Engine, Electric Start, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, 6.00-16 Front Tires, 16.9-28 Rear Tires Usage: Not Available Asset located in: Lake Worth, TX
	Seat, Differential Lock, 16 Forward 4 Reverse, PowerShift, Forward/ Reverse Shuttle, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, HID Lights, 4 Rear Remotes, Exterior 3-Point Hitch Controls, 1000 PTO, 3-Point Hitch w/ Quick Hitch, Drawbar, 420/85R34 Front Tires, 480/80R50 Rear Tires Usage: Not Available Notes: ENGINE RUNS BUT SMOKES, HYDRAULICS AND DRIVETRAIN ARE OPERATIONAL; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9606	2021 MacDon M1240 16 ft Windrower (Inoperable) S/N: 40219921 C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive, Requires Diesel Exhaust Fluid, 580/70R26 Front Tires, 16.5-16.1 Rear Tires, Header S/N - 43062222, 2022 MacDon R216 16 ft Rotary Header Usage: Not Available Notes: 2018 ENGINE HOURS; 1207 HEADER HOURS; LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. UNIT HAS A BAD ENGINE, DRIVETRAIN, HYDRAULIC SYSTEM AND HEADER ARE COMPLETE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9606A	2017 Cat 966M Wheel Loader (Inoperable) S/N: CAT0966MJKJP02417 C/W: Enclosed Cab, Air Ride Seat, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, Log Grapple, 26.5-25 Tires Usage: 6,530 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9608B	2012 Cat 140M2 VHP Plus Motor Grader (Inoperable) S/N: CAT0140MAM9D01207 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2012 US EPA Label, 14 ft / 4.2 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 8,784 Hr Notes: ENGINE RUNS BUT HAS FUEL IN THE OIL - NEEDS HIGH PRESSURE FUEL PUMP,
9606B	2011 Volvo L110F Wheel Loader (Inoperable) S/N: VCEL110FP00005039 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Hydraulic Coupler, 114 in Bucket, 23.5R25 Tires Usage: Not Available		DRIVETRAIN AND HYDRAULICS ARE OPERATIONAL; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9609	2001 Terex S17E Motor Scraper (Inoperable) S/N: S8311020 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available
9608	1999 Volvo L90C Wheel Loader (Inoperable) S/N: L90CV63189 C/W: Enclosed Cab, Hydraulic Coupler, 20.5 R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET LIP		Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. Asset located in: Lake Worth, TX
		9610	2000 Terex S17E Motor Scraper (Inoperable) S/N: S8031011 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available
9608A	2013 Volvo L70G Wheel Loader (Inoperable) S/N: VCE0L70GK00002765 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires Usage: 24,316 Hr Notes: ENGINE RUNS BUT SMOKES;		Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	DRIVETRAIN AND HYDRAULICS ARE OPERATIONAL; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9611	2017 John Deere 9570R Scraper Special Articulated Tractor (Inoperable) S/N: 1RW9570RLGE054151 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Front Weights, 4 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Front Wheel Weights Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. DRIVETRAIN IS COMPLETE BUT HAS A BAD REAR END, HYDRAULICS ARE COMPLETE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details
9612A	2A 2011 John Deere 750J LGP Crawler Dozer (Inoperable) S/N: 1T0750JXKBD203024 C/W: Enclosed Cab, Air Conditioner, Sweeps, 152 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 8,566 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM	9615	1998 Cat CP433C Padfoot Drum Compactor (Inoperable) S/N: 2JM00524 C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, 66 in Drum, Leveling Blade Usage: 5,226 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
	YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; UNIT RUNS, DRIVES HYDRAULICS ARE OPERATIONAL - WILL NOT THROTTLE UP Asset located in: Lake Worth, TX	9615A	Bomag BW124PDH-40 Padfoot Drum Compactor (Inoperable) S/N: 901581401027 C/W: Open Operator Station, 2011 US EPA Label, Deuts 3 Cylinder 45 hp 2.3 L Diesel
9613	S/N: CAT00D5KCKY202614 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 124 in Wide PAT Blade, 26 in Single Grouser Track Shoes, SystemOne Undercarriage, EQUIPMENT-FROM-PULICE-		Engine, 48 in Drum Usage: 1,423 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
		9616A	2011 Cat CD54 Double Drum Roller (Inoperable) S/N: CAT0CD54HJ5R00162 C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, 67 in Offsetting Compaction Width, Water System Usage: 4,502 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9613A	2001 Cat 963C LGP Crawler Loader (Inoperable) S/N: 2DS01267 C/W: Open Operator Station, 86 in Bucket, 21 in Double Grouser Track Shoes, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9617	Asset located in: Lake Worth, TX 2006 Ingersoll Rand DD-34HF Double Drum Roller (Inoperable) S/N: 188489 C/W: Open Operator Station, 2005 US EPA Label, Kubota V2203-M-ES 4 Cylinder 36.4 kW 2.2 L Diesel Engine, 54 in Compaction Width, Water System Usage: 5,526 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX 2011 Lay-Mor 8HC Self-Propelled Broom
9614	Asset located in: Lake Worth, TX Dynapac CA2500 Padfoot Drum Compactor (Inoperable) S/N: 10000138K0A011328 C/W: Enclosed Cab, 2013 US EPA Label, Cummins 4.5 L Diesel Engine, 74 in Drum Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		(Inoperable) S/N: 33225 C/W: Open Operator Station, 7 ft 9 in Broom, Water System, 2019 US EPA Label, Kubota 3 Cylinder 26 kW 1.5 L Diesel Engine Usage: 854 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9620	1999 Broce BB250 Self-Propelled Broom (Inoperable) S/N: 981111 C/W: Open Operator Station, 6 ft 3 in Broom, Water System, 4 Cylinder Diesel Engine Usage: 542 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9623B	2018 Bobcat E50 Mini Excavator (Inoperable) S/N: AJ1814335 C/W: Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 4,351 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
9621	2013 Komatsu PC360LC-10 Tracked Excavator (Inoperable) S/N: KMTPC242A54A32676 C/W: Air Conditioner, Rear View Camera, US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 56 in Digging Bucket, Thumb Bracket Usage: 13,098 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	9623C	2016 John Deere 35G Mini Excavator (Inoperable) S/N: 1FF035GXTGK276310 C/W: Swing Boom, 4 ft 4 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	REMOVAL; Asset located in: Humble, TX	9624	2006 Komatsu PC27MR-2 Mini Excavator (Inoperable)	
9622A	2001 Komatsu PC200-6 Tracked Excavator (Inoperable) S/N: C10758 C/W: 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 96 in Cleanup Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED		S/N: KMTPC120A05016215 C/W: Control Pattern Changer, S ft 8 in Stick, Backfill Blade, 12 in Usage: Not Available Notes: INOPERABLE ITEM MUS FROM YARD BY JANUARY 10TH BE RELISTED; BUYER'S RESPON REMOVAL	C/W: Control Pattern Changer, Swing Boom, 3 ft 8 in Stick, Backfill Blade, 12 in Rubber Tracks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9624A	2018 Wacker Neuson EZ53 Mini Excavator (Inoperable) S/N: WNCE0510TPAL00649	
9623A	2014 John Deere 135G Tracked Excavator (Inoperable) S/N: 1FF135GXJEE400550 C/W: Air Conditioner, Air Ride Seat, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 24 in Double Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 24 in Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING	9624B	C/W: Enclosed Cab, Air Conditioner, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,989 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2018 Case CX37C Mini Excavator (Inoperable) S/N: NSUC37CRNZLN55583 C/W: 2017 US EPA Label, Swing Boom, 4 ft 3 in	
	ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9625	2014 Terex TC16 Mini Excavator (Inoperable) S/N: TC00163259 C/W: Swing Boom, 3 ft 8 in Stick, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 8 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX	9628	(Inoperable) S/N: 1VRP082R0W1000592 C/W: Deutz 4 Cylinder Diesel Engine, 8.5 ir Wide x 7 ft Long Rock Trencher Chain, Crumbling Shoe, 8600 Backhoe Attachme Angle Blade, Side Shift Usage: 349 Hr Notes: INOPERABLE ITEM MUST BE REMORED YARD BY JANUARY 10TH AND CAN BE RELISTED; BUYER'S RESPONSIBILITY	(Inoperable) S/N: 1VRP082R0W1000592 C/W: Deutz 4 Cylinder Diesel Engine, 8.5 in Wide x 7 ft Long Rock Trencher Chain, Crumbling Shoe, 8600 Backhoe Attachment, Angle Blade, Side Shift
9625A	Simon-Ro TC-120-4 10 ton Straight Boom on		Asset located in: Lake Worth, TX	
	1998 International 9100 6x4 Boom Truck (Inoperable) S/N: 2HSFRAHR5WC056727 C/W: Cummins M11-330E+ 6 Cylinder Diesel 330 hp Engine, 1998 US EPA Label, Spicer 10- Speed Manual Transmission, 11R22.5, Double Frame, International IROS Air Ride Suspension, 207 in Wheelbase, 10 ton Capacity, Front Mounted, 20 ft - 48 ft 3 Section Boom, Dual Controls, Straight Down Outriggers, Rear Outriggers, 15 ft x 94 in Bed Usage: 185,516 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY	9628A	el S/N: 4M9E2TG22GE015001 10- C/W: Lunette Ring Hitch, Spring Sus ible Electric Brakes, Steel Debris Tank, F Reel, 320 L Fresh Water Tank, Drop Tailgate, Manual Tailgate Locks, 3.5 Hose, Engine Driven Pump, 235/80R Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SE CORP-COMPANY Usage: Not Available NOT Notes: INOPERABLE ITEM MUST BE FROM YARD BY JANUARY 10TH AN BE RELISTED; BUYER'S RESPONSIB	S/N: 4M9E2TG22GE015001 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Front Hose Reel, 320 L Fresh Water Tank, Drop Down Tailgate, Manual Tailgate Locks, 3.5 in Suction Hose, Engine Driven Pump, 235/80R16 Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
9625B 9625C	2006 Gradall XL3100 Wheel Excavator (Inoperable) S/N: 210018006 C/W: Air Conditioner, 2006 US EPA Label, 385 /65R22.5 Tires, Cleanup Bucket, Eaton fuller 9 speed manual transmission, Usage: Not Available Asset located in: Lake Worth, TX 2005 Gradall XL3300 Wheel Excavator	9629A	4x4 Articulated Water Truck (Inoperable) S/N: Not Available C/W: Open Operator Station, 23.1-26 Tires Usage: 2,976 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	
	(Inoperable) S/N: 0210017540		REMOVAL Asset located in: Lake Worth, TX	
9627	C/W: Backfill Blade, Stabilizers, 60 in Cleanup Bucket, Additional 30 in Digging Bucket Usage: 2,899 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 1998 Vermeer 8550A 4x4 Trencher (Inoperable)	9629B	1995 Etnyre K Series Chip Spreader (Inoperable) S/N: K5706 C/W: Open Operator Station, Diesel Engine, Hydrostatic Drive, 11 ft - Spreader Usage: Not Available Notes: UNIT STARTS AND RUNS, DRIVETRAIN IS INOPERABLE Asset located in: Lake Worth, TX	
	S/N: 1VRT112P2W1000109 C/W: Canopy, Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Rock Trencher Chain, Straight Blade Usage: 1,406 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9629C	Cat BG-260C Wheel Asphalt Paver S/N: CATBG260C8GN00575 C/W: 2001 US EPA Label, 10 ft - Screed, On Board Generator Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9630	Weiler P355 Track Asphalt Paver (Inoperable) S/N: P355-1010 C/W: Dual Controls, 8 ft - Screed, 12 in Rubber Tracks Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9632	2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DPDTB05818 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Manual Coupler, 74 in Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9630A		-9632A	2018 Cat 226D Skid Steer Loader (Inoperable) S/N: CAT0226DJHRD03498 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket Usage: 1,238 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9630B	FORWARD - NO REVERSE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2014 Cat 242D Skid Steer Loader (Inoperable) S/N: CAT0242DJDZT00366	9632B	2016 Kubota SSV65 Skid Steer Loader (Inoperable) S/N: JKUS0651L01S12051 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Aperture Tires, Manual Coupler, 66 in Bucket Usage: 2,937 Hr Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Tier 4, 2013 US EPA Label, CARB Compliant, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: 689 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Midland, TX	9632C	2021 Bobcat S510 Skid Steer Loader (Inoperable) S/N: B4RE11047 C/W: Open Operator Station, 2020 US EPA Label, Aperture Tires, Manual Coupler, EQUIPMENT FROM UNITED RENTALS Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9630C	2008 John Deere CT332 Compact Track Loader (Inoperable)		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9631	S/N: T0332TA168479 C/W: Enclosed Cab (Door missing), US EPA Label, 18 in Track Belts, Manual Coupler Usage: 6,793 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DLDTB05827	9633	2017 Cat 299D2 High Flow XPS Compact Track Loader (Inoperable) S/N: CAT0299DHFD202254 C/W: Enclosed Cab (Door missing), Joystick Steering, Tier 4, 2017 US EPA Label, 16 in Track Belts, Hydraulic Coupler Usage: 3,440 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Manual Coupler Usage: 6,509 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICE	CHOICE OF 2 - Lot #'s: 9633A, 9634A		2019 Case TR310 Compact Track Loader (Inoperable) S/N: JAFTR310JJM450180
9633A	2014 Cat 289D Two-Speed High Flow XPS Compact Track Loader (Inoperable) S/N: TAW01012 C/W: Enclosed Cab (Door missing), Air	9636	C/W: Enclosed Cab (Door missing), Joystick Steering, 16 in Track Belts, Electric Coupler, 72 in Bucket Usage: Not Available Asset located in : Lake Worth, TX
	Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Self Leveling, Tier 4, 2014 US EPA Label, 18 in Track Belts, Hydraulic Coupler, 74 in Bucket, Counterweight Kit Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Midland, TX		2018 Case TR310 Compact Track Loader (Inoperable) S/N: JAFTR310AJM449342 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2018 US EPA Label, 15.5 in Track Belts, Manual Coupler, 77 in Bucket Usage: 3,405 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND
9634A	2014 Cat 289D Compact Track Loader		CANNOT BE RELISTED
	(Inoperable) S/N: CAT0289DVTAW00650	06264	Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Joystick Steering, 18 in Track Belts, Manual Coupler, 74 in Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9636A	2018 Case TR270 Compact Track Loader (Inoperable) S/N: NJM448663 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manual Coupler, 68 in Bucket Usage: 2,404 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
	Asset located in: Lake Worth, TX	4	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL
9634B	2017 Kubota SVL75-2 Compact Track Loader (Inoperable)		Asset located in: Lake Worth, TX
	S/N: JKUC0752T01S29876 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 15 in Track Belts, Hydraulic Coupler, 74 in Bucket Usage: 799 Hr Asset located in: Lake Worth, TX	9637	2017 John Deere 317G Compact Track Load (Inoperable) S/N: 1T0317GJPHJ308175 C/W: Open Operator Station, Joystick Steeri 13 in Track Belts, Hydraulic Coupler, 72 in Bucket, EQUIPMENT FROM UNITED RENTAL
9635	2019 Kubota SVL95-2S Compact Track Loader	-	Usage: 2,121 Hr
	(Inoperable) S/N: KBCC0953CK1D46350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 2019 US EPA Label,	9637A	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available Asset located in : Midland, TX		2017 Kubota SVL95-2S Two-Speed Compact Track Loader (Inoperable) S/N: JKUC0953L01S34123
9635A	2020 Bobcat T590 Compact Track Loader (Inoperable) S/N: ALJU32175 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,749 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX		C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler Usage: 2,023 Hr Notes: UNIT STARTS AND RUNS, ENGINE IS DERATED, POWERTRAIN IS DERATED Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9639	2010 Bobcat T190 Compact Track Loader (Inoperable) S/N: A3LN36903 C/W: Open Operator Station, 12.5 in Track Belts, Manual Coupler Usage: 5,228 Hr Notes: UNIT STARTS AND RUNS, PARKING BRAKE INOPERABLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9642	2013 JCB 9404 8000 lb Rough Terrain Forklift (Inoperable) S/N: JCB94004A02228045 C/W: 3 Stage Mast, 72 in Forks, 2012 US EPA Label, JCB tc-55 4 Cylinder 4.4 L Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM
9639A	2012 Takeuchi TL230 Compact Track Loader (Inoperable)		YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	S/N: 223101077 C/W: Open Operator Station, Joystick Steering,	9642A	1999 Mack RB688S 6x4 85 in Tree Spade
	2012 US EPA Label, 12.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 67 in Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9642A	Truck (Inoperable) S/N: 1M2AM08C9XM004800 C/W: Mack 6 Cylinder Diesel Engine, 1998 US EPA Label, Aluminum Front Wheels, 385 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 258 in Wheelbase
9640	2019 Toro 22322 Mini Compact Track Loader (Inoperable) S/N: 405588028 C/W: Open Operator Station, 2019 US EPA Label, 9 in Track Belts, Manual Coupler, 14 in Bucket Usage: 1,147 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Usage: 216,359 Mi Notes: INOPERABLE ITEM MUST BE REMOVED
70.10			FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
			Asset located in: Lake Worth, TX
		Truck (Inoperable) S/N: 1FDNX20L13EC09631 C/W: V8 5.4 L Gasoline Engine, 2003 US EP Label, Automatic Transmission, 4250 lb Fro Axle, 6084 lb Rears, 8800 lb GVWR, 235/80 Front Tires, 235/85R16 Rear Tires, Spring Suspension, 159 in Wheelbase, 2003 Knapheide 696FJ 8 ft 2 in Body Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMO FROM YARD BY JANUARY 10TH AND CAN BE RELISTED; BUYER'S RESPONSIBILITY FREMOVAL; TEXAS BUYERS MUST STOP IN	S/N: 1FDNX20L13EC09631 C/W: V8 5.4 L Gasoline Engine, 2003 US EPA Label, Automatic Transmission, 4250 lb Front Axle, 6084 lb Rears, 8800 lb GVWR, 235/80R16
9641			Suspension, 159 in Wheelbase, 2003 Knapheide 696FJ 8 ft 2 in Body
	ON THIS UNIT. OUTSIDE LOADING		Asset located in: Lake Worth, TX
	ASSISTANCE WILL NEED TO BE SET UP. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX	9643	2007 Ford F-550 XL 4x2 Extended Cab Utility Truck (Inoperable) S/N: 1FDAX56P57EA34588 C/W: Ford V8 Diesel Engine, Automatic Transmission, 225/70R19.5, Spring Suspension, 166 in Wheelbase, Knapheide 9 ft Body Usage: 296,251 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details
9643A 9643B	Crown RR5700 Order Picker (Inoperable) S/N: 1A388576 C/W: 3 Stage Mast, 240 in Max Lift Height, 107 in Lowered Mast Height, 42 in Forks, Side Shift, Push/Pull Attachment Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 1980 Hyster Cushion Tire Forklift (Inoperable)	9646B	2014 Toyota 8FGCU30 5020 lb Cushion Tire Forklift (Inoperable) S/N: 60401 C/W: 3 Stage Mast, 198 in Max Lift Height, 91 in Lowered Mast Height, 42 in Forks, Side Shift, 2014 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 3,999 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
30.00	S/N: F006V02094A C/W: 2 Stage Mast, 146 in Lowered Mast Height, 96 in Forks, 4 Cylinder Diesel Engine Usage: 5,119 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9646C	Asset located in: Lake Worth, TX 2013 Linde H25CT 5000 lb Cushion Tire Forklift (Inoperable) S/N: A1131D00241 C/W: 2 Stage Mast, Full Free Lift, 180 in Max Lift Height, 81 in Lowered Mast Height, 41 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 10,212 Hr
9644	Mitsubishi FG50K 11000 lb Pneumatic Tire Forklift (Inoperable) S/N: AF33B50068 C/W: 2 Stage Mast, 148 in Max Lift Height,		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Solid Pneumatic Tires, 5 Cylinder LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9647	1990 Cat T50D 5000 lb Cushion Tire Forklift (Inoperable) S/N: 8EB09438 C/W: 3 Stage Mast, 173 in Max Lift Height, 83 in Lowered Mast Height, 36 in Forks, Side Shift, Cat 4 Cylinder LPG Engine Usage: 20,099 Mi
9644A	2021 Yale GLC155VX 10000 lb Cushion Tire Forklift (Inoperable) S/N: F879V02835V C/W: 3 Stage Mast, 221 in Max Lift Height, 111 in Lowered Mast Height, Paper Roll Clamp,		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	2021 US EPA Label, PSI 6 Cylinder 4.3 L Dual Fuel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9648	2004 Hyundai HLF25-5 5000 lb Pneumatic Tire Forklift (Inoperable) S/N: FU0211429 C/W: Single Stage Mast 130 in Max Lift Height, 86 in Lowered Mast Height, 47 in Forks, 2004 US EPA Label, CARB Compliant, IMPCO 6Z9XB02.4MPN 4 Cylinder 2.4 L LPG Engine Usage: 1,363 Mi
9646A	2012 Toyota 8FGCU30 5120 lb Cushion Tire Forklift (Inoperable) S/N: 17847 C/W: 3 Stage Mast, Full Free Lift, 187 in Max		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, Toyota 4Y ECS 4 Cylinder 2.23 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9649	2012 Cat 2EPC5000 4870 lb Electric Forklift (Inoperable) S/N: FN459381 C/W: 3 Stage Mast, 86 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 80 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details		
9649A	1995 Hyster S50XL 4750 lb Pneumatic Tire Forklift (Inoperable) S/N: C187V157475S C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Fork Positioner, LPG Engine Usage: 9,483 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9651B	2010 Doosan GC25P-5 4450 lb Cushion Tire Forklift (Inoperable) S/N: MW00736 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift, 2010 US EPA Label, Woodward 4 Cylinder 46.8 kW 2.4 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		
9650	2012 Doosan G25P-5 4600 lb Pneumatic Tire Forklift (Inoperable)	9652	2013 Nissan CF40LP 4000 lb Pneumatic Tire		
	S/N: FGA0B133002925 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, 4 Cylinder 46.8 kW 2.4 L LPG Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX	9653	Forklift (Inoperable) S/N: CP1F2-9W1966 C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2013 US EPA Label, 4 Cylinder 2.1 L LPG Engine Usage: 10,133 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2000 Toyota 52-6FGCU45 8600 lb Cushion Tire		
9651	2016 Cat GP25N 4500 lb Pneumatic Tire	1	Forklift (Inoperable)		
9031	Forklift (Inoperable) S/N: AT35A02995 C/W: 3 Stage Mast, 188 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.5 L LPG Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 3,439 Hr Notes: INOPERABLE ITEM MUST BE REMOVED	9654			S/N: 62206 C/W: 3 Stage Mast, Full Free Lift, 218.5 in Max Lift Height, 106 in Lowered Mast Height, 72 in Forks, Side Shift, V6 LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	FROM THE YARD BY JANUARY 10TH AND		2011 Yale GLP040SVXNURV084 4000 lb		
	CANNOT BE RELISTED Asset located in: Lake Worth, TX		Pneumatic Tire Forklift (Inoperable) S/N: C810V04664J		
9651A	Tusk 500CG-14 4480 lb Cushion Tire Forklift (Inoperable) S/N: 590948A C/W: 3 Stage Mast, 188 in Max Lift Height, 42 in Forks, Side Shift, Tier 1, 2005 US EPA Label, Nissan 4 Cylinder 55 hp 2.1 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		C/W: 2 Stage Mast, 127.2 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, 2011 US EPA Label, 4 Cylinder 2.0 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
9655	2014 Toyota 8FGCU20 4000 lb Cushion Tire Forklift (Inoperable) S/N: 62727 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Load Weigh System, 2014 US EPA Label, CARB Compliant, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9657	1998 Toyota 5FBE18 2800 lb Electric Forklift (Inoperable) S/N: 24164 C/W: 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 93 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	9657A	1995 Toyota 5FBE18 Electric Forklift	
9655A	2012 TCM FG25T3 3700 lb Pneumatic Tire Forklift (Inoperable) S/N: 2H507316 C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, Tier 2, 2012 US EPA Label, Nissan 4 Cylinder 2.1 L Dual Fuel Engine Usage: 3,696 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Lowered Mast Height, 47 in Forl 48 V Usage: Not Available Notes : INOPERABLE ITEM MUS FROM YARD BY JANUARY 10TH BE RELISTED; BUYER'S RESPOI REMOVAL	S/N: 15611 C/W: 3 Stage Mast, Full Free Lift, 82 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
	Asset located in: Lake Worth, TX	9657C	2017 Toyota 8FGCU25 1700 lb Cushion Tire Forklift (Inoperable)	
9655B	2012 Toyota 7FBEU20 3050 lb Electric Forklift (Inoperable) S/N: 7FBEU2020440 C/W: 3 Stage Mast, 218 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		S/N: 88346 C/W: 4 Stage Mast, F Lift Height, 95 in Low Forks, Side Shift, 201 4YECS 4 Cylinder 2.2 Usage: 7,554 Hr Notes : INOPERABLE FROM YARD BY JAN	S/N: 88346 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 95 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 7,554 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
9655C	1992 Cat T50E 3600 lb Cushion Tire Forklift (Inoperable) S/N: 2ND00404 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 82 in Lowered Mast Height, 43 in Forks, Side Shift, 4 Cylinder Dual Fuel Engine Usage: 4,569 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	-9657D	1989 Nissan CPF02A25V 5000 lb Cushion Tire Forklift (Inoperable) S/N: CPH02026383 C/W: 106 in Max Lift Height, 68 in Lowered Mast Height, Nissan 4 Cylinder Dual Fuel Engine, EQUIPMENT FROM CENTRAL FREIGHT LINES INC Usage: 8,015 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; NO LPG TANK Asset located in: Lake Worth, TX	
0656	·	0659	<u> </u>	
9656	2003 Linde E30C 3060 lb Electric Forklift (Inoperable) S/N: A1X347P00155 C/W: 3 Stage Mast, 24 in Lowered Mast Height, 36 in Forks, 48 V, Battery Charger Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9658	Toyota Cushion Tire Forklift (Inoperable) S/N: Not Available C/W: 2 Stage Mast, 77 in Lowered Mast Height, 42 in Forks, 4 Cylinder Gasoline Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	

		I	1 age 324 01 374	
Lot #	Details	Lot #	Details	
9658A	2021 Combilift COMBI-RT 3000 lb 3x3 Rough Terrain Forklift S/N: 55866 C/W: 2 Stage Mast, 124 in Max Lift Height, 24 in Lowered Mast Height, 72 in Forks, Side Shift, 2020 US EPA Label, Deutz TD2.9L4 4 Cylinder 55 kW 2.9 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	9659B	2000 UpRight RT27 4x4 Gasoline Scissor Lift (Inoperable) S/N: 2922 C/W: 27 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Upper Control Box, 2000 US EPA Label, Kubota 3 Cylinder 740 cc Gasoline Engine Usage: 4,028 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	
9658B	2010 Genie S85 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: S85108432 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, 2010 US EPA Label, Doubt TD 2011 10414 Cylinder 2 61 L Diesel			BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Deutz TD 2011L04I 4 Cylinder 3.61 L Diesel Engine, 18-625NHS Tires Usage: 5,544 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2016 Genie GS-3232 Electric Scissor Lift (Inoperable) S/N: GS3216P-144587 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	
9658C	2015 JLG 400S 2WD Diesel Telescopic Boom Lift (Inoperable) S/N: 0300210976 C/W: 40 ft Max Platform Height, 1000 lb Max		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
	Weight Capacity, 2015 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 14-17.5 NHS Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,245 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	9659C	2017 JLG 600S 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: 300229396 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 5,530 Hr Notes: INOPERABLE ITEM MUST BE REMOVED	
9659	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift (Inoperable) S/N: 40001322 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2014		FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	
U 90 In V S. F1 J. B		9660	2016 Skyjack SJ3226 Electric Scissor Lift (Inoperable) S/N: 27028952 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Onboard Generator, Solid Non-Marking Tires Usage: 285 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth TX	

Lot #	Details	Lot #	Details
9660A	2017 JLG 600S 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: 0300233241 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 6,286 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	9661 9661A	2016 Snorkel S3219E Electric Scissor Lift (Inoperable) S/N: S3219E04001808 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box Usage: 47 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9660B	Asset located in: Lake Worth, TX 2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: 0300236292 C/W: 65 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,928 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	_	(Inoperable) S/N: 7FSBL1018HB880619 C/W: 2017 US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,155 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; 3001880619; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9660C	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX 2016 Genie GS-4047 Electric Scissor Lift (Inoperable) S/N: GS4716D1543 C/W: 39 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	9661B	2017 Magnum Pro MLT6SM 6 kW Light Tower (Inoperable) S/N: 3001715479 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,347 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	Control Box Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX Husqvarna FS6600D Walk-Behind Saw (Inoperable) S/N: 001298383001 C/W: Water Hose Connection, Electric Blade Raise / Lower, US EPA Label, John Deere 4024HF295 4 Cylinder Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED
9660D	2015 Genie GS-1930 Electric Scissor Lift (Inoperable) S/N: GS3015A146318 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9662	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: Tier 4, 2013 US EPA Label, Kubota V1505 16 kW 1.5 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,620 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9664B	Cat Mobile Generator Set (Inoperable) S/N: C11-12-05372 C/W: 2011 US EPA Label, CARB Compliant, Perkins 3362 4 Cylinder 116.9 kW 4.4 L Diesel Engine, 100 kVA/80 kW Rated 3 Phase Output, 480 V / 208 V / 120 V Rated Voltage, 100 kVA, /80 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	9665	1992 Onan 37DGBA 37 kW Skid-Mounted
9663			Generator Set (Inoperable) S/N: I910419145 C/W: Cummins 4B3.9G 4 Cylinder 66 hp 3.9 L Diesel Engine, /37 kW Rated 3 Phase Output Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		Asset located in: Humble, TX
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL	9665A	2009 Drash 23 kW Mobile Generator Set (Inoperable)
9664	Asset located in: Lake Worth, TX Lincoln RA-250-V1903 300 A Skid-Mounted Engine Driven Welder (Inoperable) S/N: C1080500072 C/W: Tier 4, 2008 US EPA Label, CARB Compliant, Kubota V2003-M-BG-ET02e 4 Cylinder 24.3 kW 2.0 L Diesel Engine, Welding Leads Not Included, 40 V Rated Voltage Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		S/N: 610 C/W: 2009 US EPA Label, Perkins 4 Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 4,337 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	REMOVAL	9665B	` '
9664A	Generator Set (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, 24.4 kVA/19.5 kW Rated 3 Phase Output, 240 V / 480 V / 120 V Rated Voltage, 16 kVA,/16 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 661 Hr	_	S/N: 359 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V Receptacles, S/A Trailer, Lunette Ring Usage: 737 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Notes : INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT	9665C	2008 Drash 20 kW Mobile Generator Set
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		(Inoperable) S/N: 346 C/W: Perkins 4 Cylinder 33 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, Sound Attenuated, S/A Trailer, Lunette Ring Usage: 265 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details	
9666	Cummins 682F9R7032 640 kW Skid-Mounted Generator Set (Inoperable) S/N: C9M0682005 C/W: 2008 US EPA Label, Volvo TWD1643GE 6 Cylinder 1800 kW 16.2 L Diesel Engine, 800 kVA /640 kW Rated 3 Phase Output, 440 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Humble, TX	9668	2018 Tsurumi TPG4-4500HDX 4.5 kW Portable Generator Set (Inoperable) S/N: 051272 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX 2019 Tsurumi TPG4-4500HDX 4.5 kW Portable Generator Set (Inoperable) S/N: 051460 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/	
9666A	Redco Skid-Mounted Generator Set (Inoperable) S/N: Not Available C/W: Cummins 6 Cylinder Diesel Engine Usage: 269 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Sullivan Palatek Skid-Mounted Electric Air	
	REMOVAL; Asset located in: Humble, TX	9670	Compressor (Inoperable)	
9666B	2006 Ingersoll Rand G25 Mobile Generator Set (Inoperable) S/N: 4FVGCBAA06U374217 C/W: Ingersoll-Rand 3 Cylinder Diesel Engine, 480 V Rated Voltage, S/A Trailer, Lunette Ring Usage: 34,921 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		Motor Usage: 18,303 Hr Notes : INOPERABLE FROM YARD BY JANI BE RELISTED; BUYER REMOVAL Asset located in : Lak	C/W: 200 psi Working Pressure, 230, 75 hp Motor Usage: 18,303 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	REMOVAL Asset located in: Lake Worth, TX	9671	2010 MGS Trailer-Mounted Water Pump (Inoperable)	
9666C	2016 Multiquip DCA220SSJU4F Generator Set (Inoperable) S/N: 5SLBG1825GL018612 C/W: 2016 US EPA Label, John Deere 6 Cylinder 6.8 L Diesel Engine, 220 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 10,985 Hr Notes: INOPERABLE ITEM MUST BE REMOVED		C/W: 6 in Intake, 6 in Discharge, Ce Water Pump, 2010 US EPA Label, J Cylinder 60 kW 4.5 L Diesel Engine, Lunette Ring, Surge Brakes Usage: 4,558 Hr Notes: INOPERABLE ITEM MUST B FROM YARD BY JANUARY 10TH Al	Usage: 4,558 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		MMDI Trailer-Mounted Water Pump (Inoperable) S/N: Not Available C/W: 5 in Intake, 6 in Discharge, Centrifugal	
9667	Gardner-Denver EAUSPG Skid-Mounted Electric Air Compressor (Inoperable) S/N: FACP8X0 C/W: 3 Phase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Water Pump, Kohler KD11903TCR 4 Cylinde Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMON FROM YARD BY JANUARY 10TH AND CANN BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9673	2011 Magnum MAG MTP 4000D Trailer-Mounted Water Pump (Inoperable) S/N: 1105549 C/W: 4 in Intake, 4 in Discharge, Centrifugal 2013 US EPA Label, CARB Compliant, John Deere 4024TF281A 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,333 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	9675 9676	Gardner-Denver WCC-1001 Vertical Air Compressor (Inoperable) S/N: 414039 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Gardner-Denver Air Compressor (Inoperable)	
	REMOVAL Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available	
9673A	2018 Atlas Copco XAS440JDT4F Mobile Air Compressor (Inoperable) S/N: H0P077169 C/W: John Deere 4 Cylinder 4.5 L Diesel	9677	Notes: INOPERABLE ITEM MUST BE REMO' FROM YARD BY JANUARY 10TH AND CANI BE RELISTED; BUYER'S RESPONSIBILITY FOR	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch, Electric Brakes Usage: 3,319 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Ingersoll Rand 20VX15 Air Compressor (Inoperable) S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	
9673B	2001 Sullivan 185DPQ Mobile Air Compressor (Inoperable)		REMOVAL Asset located in: Lake Worth, TX	
	S/N: 4135193 C/W: 200 psi Working Pressure, 2001 US EPA Label, John Deere 4045DP150B 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 1,078 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	9678	Pneumatic Skid Mounted Lube Pan - Fits Truck (Inoperable) S/N: Not Available C/W: Kohler Command Pro 14 429 cc Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED	
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
9673C	2017 Atlas Copco XAS110KD 110 cfm Mobile Air Compressor (Inoperable) S/N: YA3064283H0480254 C/W: 2017 US EPA Label, Kubota D902-EF01 3 Cylinder 0.89 L Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9679	S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUS FROM YARD BY JANUARY 10T BE RELISTED; BUYER'S RESPOREMOVAL Asset located in: Lake Worth, T 9680 Quantity of (2) Water Pump (In	Gardner-Denver Air Compressor (Inoperable) S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Quantity of (2) Water Pump (Inoperable) S/N: Not Available
	Asset located in: Humble, TX		C/W: Trash Pump, 1 Cylinder Gasoline Engine, (1) Tsurumi 4 In, (1) 3 In, One Pallet	
9674	Ingersoll Rand Electric Air Compressor (Inoperable) S/N: Not Available C/W: 3 Phase, 20 hp Motor Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
9680A	2019 Cub Cadet Pro Z 500 Zero-Turn Lawn Mower (Inoperable) S/N: 1C089H70016 C/W: 2019 US EPA Label, 24x12.00-14 Rear Tires, 54 in Mower Usage: 105 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9682B	2021 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBCMG044293 C/W: Canopy, 4 Passenger, Electric Dump Bed, Tier 4, 2021 US EPA Label, Kubota d1105 3 Cylinder 8 kW 1.1 L Diesel Engine Usage: 1,144 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9681	2016 Airrex Air Conditioner (Inoperable) S/N: 161010989L Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9684A 9684B	2017 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBLHG019685 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available
9681A	1954 Chris-Craft 33 ft Wood Cabin Crew Boat (Inoperable) w/ Custom Built Trailer S/N: Not Available C/W: T/A Trailer, Ball Hitch Usage: Not Available		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL, NO VISIBLE VIN Asset located in: Lake Worth, TX		2020 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD2013059325 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3
9682	Landa PGDC5-3500 Pressure Washer (Inoperable) S/N: 11100500101088 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton 570 cc Gasoline Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED		Cylinder Diesel Engine Usage: 758 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		2020 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD2010053177 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2019 US EPA Label, Kubota D722-EF01 3 Cylinder 14.7 kW Diesel Engine Usage: 1,029 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
9682A	2022 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBVNG053697 C/W: Open Operator Station, 4 Passenger, Windshield, Electric Dump Bed, Tier 4, 2022 US EPA Label, Kubota d1105 3 Cylinder 8 kW 1.1 L Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		

Lot #	Details	Lot #	Details
9684C	2019 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD1919970458 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2018 US EPA Label, Kubota D722-EF01 3 Cylinder 14.7 kW Diesel Engine Usage: 964 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	9685A	Club Car Carryall 1500 Utility Vehicle (Inoperable) S/N: 104027428 C/W: Canopy, 2 Passenger, Brush Guard, Manual Dump Bed, 2 Cylinder 1500 cc Gasoline Engine Usage: 610 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9685B	2018 Club Car Carryall 1500G Utility Vehicle
9684D	2019 Club Car Carryall 1700D Utility Vehicle (Inoperable) S/N: SD1919969449 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2018 US EPA Label, Kubota D722-EF01 3 Cylinder 14.7 kW Diesel Engine Usage: 1,308 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION		(Inoperable) S/N: RC1918967726 C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 482 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	AVAILABLE IN OFFICE - MSO;	9686	John Deere Gator XUV Utility Vehicle
9684E	Asset located in: Lake Worth, TX 2019 Club Car Carryall 1700G Utility Vehicle (Inoperable) S/N: SC1918-968334 C/W: Canopy, 4 Passenger, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE DELISTED: BLIVED'S DESPONSIBILITY FOR		(Inoperable) S/N: 1M0835EAPMM040361 C/W: Canopy, 2 Passenger, Manual Dump Bed, John Deere 3 Cylinder Engine Usage: 1,574 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	9687	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X2GD332545 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 22171.7 Engine hrs, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, PTO, Auto Lube Usage: 693,335 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9685	2019 Club Car Carryall 1500G Utility Vehicle (Inoperable) S/N: RC1918-967901 C/W: Canopy, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine Usage: 668 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
9687A	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X0GD263208 C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 202 in Wheelbase, PTO Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9690	2013 Kenworth T800 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XKDDP9X9DJ369135 C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 199 in Wheelbase, Air Sliding 5th Wheel, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED
9688	2015 Peterbilt 365 6x4 T/A Day Cab Truck	┧	Asset located in: Lake Worth, TX
	Tractor (Inoperable) S/N: 1XPSD79X2FD262706 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21970 Engine hrs, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 206 in Wheelbase, PTO, Auto Lube Usage: 745,623 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9691	2019 Peterbilt 567 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPCD79X0KD612896 C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 202 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
9689	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X0FD263191 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 7302 Engine hrs, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube Usage: 539,809 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9691A	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGEDVXGSGV9490 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 596,350 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9689A	<u> </u>	1	Asset located in: Lake Worth, TX
	Tractor (Inoperable) S/N: 1XPSD79X8CD166896 C/W: Cummins ISX11.9 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 26030 Engine hrs, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Trac Suspension, 202 in Wheelbase, PTO Usage: 656,774 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		

REMOVAL

 Lot #	Details	Lot #	Details
9693	2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJGEDV1DLBV2601 C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 195 in Wheelbase, Dual Fuel Tanks Usage: 588,339 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9695	2007 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9GF47N449500 C/W: Volvo D12D365 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Manual Transmission, 275/80R22.5, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,615,127 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2003 Volvo VNL 6x4 T/A Day Cab Truck
			Tractor (Inoperable)
9694			S/N: 4V4NC9GH93N350140 C/W: Volvo 6 Cylinder Diesel Engine, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Meritor RT-40-145 Drive Axles, 3.58:1 Axle Ratio, 50000 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	Usage: Not Available		Asset located in: Lake Worth, TX
9694A	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2009 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9EG39N283601 C/W: Volvo D13 6 Cylinder 375 hp Engine, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 18739 lb Rears, 49478 lb GVWR, 275/80R22.5, Air Ride Suspension, 168 in Wheelbase, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9696A 	2004 Peterbilt 379 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XP5DB9X74D827027 C/W: Cat C15 6 Cylinder 14.6 L 475 hp Engine, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, PTO, Hydraulic System, Air Sliding 5th Wheel, Winch, Headache Rack, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: Not Available Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM; LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Notes: INOPERABLE ITEM MUST BE REMOVED		2014 Mack GU713 6x4 T/A Day Cab Truck
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Tractor (Inoperable) S/N: 1M2AX04Y5EM019283 C/W: Mack 6 Cylinder Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Mack Maxitorque 10-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, 11R24.5, Air Ride Suspension, 219 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM; LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Details 9697 2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPBD49X1LD655901 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 23259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb

450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 23259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 5200 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 752,578 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Humble, TX

9698 2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X6LD655909 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Humble, TX

Usage: Not Available

9700 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X1GD326444 C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 245 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL:

Asset located in: Lake Worth, TX

Lot # Details

9701 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X2GD346556 C/W: Cummins ISX15 6 Cylinder 15.0 L 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24608.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 249 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks

Usage: 707,094 Mi

Asset located in: Lake Worth, TX

9701A 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor

S/N: 1XKYD49X5KJ310239 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Paccar Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 233 in Wheelbase, PTO, Dual Fuel Tanks

Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Midland, TX

9703 2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XKYDP9X0FJ437603 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 12000 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks

Usage: Not Available

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL:

Asset located in: Humble, TX

			Page 334 01 374
Lot #	Details	Lot #	Details
9704	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKYDP9X0FJ464641 C/W: Paccar 6 Cylinder Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19664 Engine hrs, Engine Brake, Eaton Fuller FO-16E310C- LAS Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, 36 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 204 in Wheelbase, Dual Fuel Tanks Usage: 683,198 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9705	2011 Mack CHU613 6x2 T/A Sleeper Truck Tractor (Inoperable) S/N: 1M1AN07Y2BM006847 C/W: Mack MP8 6 Cylinder Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Mack Drive Axles, 52000 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 248 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
9704A	Asset located in: Lake Worth, TX 2013 Kenworth T660 6x2 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKAA48X9DJ365291 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 20304 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 34000 lb Rears, 2.53:1 Axle Ratio, 46000 lb GVWR, Air Ride Cab, 52 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 914,459 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9706	2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR2MSMU7290 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9704B	Asset located in: Lake Worth, TX 2019 International LoneStar 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSLGAPR6KN527657 C/W: Cummins X15 500 6 Cylinder 15.0 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,536 Mi Asset located in: Lake Worth, TX	9707	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR5LSKS3557 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 608,756 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED

Details Lot # **Details** Lot # 9707A 2020 Freightliner Cascadia 125 6x4 T/A 9710 2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR6LDLX1078 S/N: 3AKJHHDR3JSJW8538 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 C/W: 6 Cylinder Diesel Engine, Detroit 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650-3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride OH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor Cab, 72 in High Rise Sleeper Cab, 295/75R22.5, MT-40-14X Drive Axles, 3.08:1 Axle Ratio, Airliner Air Ride Suspension, Air Sliding 5th 53300 lb GVWR, Air Ride Cab, 72 in High Rise Wheel Sleeper Cab, Bunk Beds, Carrier ComfortPro Usage: Not Available Auxiliary Power Unit, Aluminum Wheels, 295 **Notes**: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV /75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks PRIOR TO BIDDING; INOPERABLE ITEM MUST Usage: Not Available BE REMOVED FROM THE YARD BY JANUARY Notes: INOPERABLE ITEM MUST BE REMOVED 10TH AND CANNOT BE RELISTED FROM YARD BY JANUARY 10TH AND CANNOT Asset located in: Lake Worth, TX BE RELISTED; BUYER'S RESPONSIBILITY FOR 2018 Freightliner Cascadia 126 6x4 T/A REMOVAL 9710A Asset located in: Lake Worth, TX Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR3JSJW9253 9709 2019 Freightliner Cascadia 126 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.7 L 455 hp Sleeper Truck Tractor (Inoperable) Engine, Requires Diesel Exhaust Fluid, Detroit S/N: 3AKJHHDR0KSKC2651 DT12-1650-OHI HD 12-Speed Automated C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Exhaust Fluid, 27034 Engine hrs, Engine Brake, Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in Detroit DT12-1750-HD1 12-Speed Automated High Rise Sleeper Cab, Bunk Beds, 295/75R22. Transmission, 12000 lb Front Axle, 40000 lb 5, Airliner Air Ride Suspension, 235 in Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.16:1 Wheelbase, Air Sliding 5th Wheel, Dual Fuel Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Tanks High Rise Sleeper Cab, Bunk Beds, Aluminum Usage: Not Available Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Notes: INOPERABLE ITEM MUST BE REMOVED Rear Tires, Airliner Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Wheel, Headache FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Rack, Dual Fuel Tanks REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN Usage: 623,235 Mi YOUR STATE. VERIFY WITH YOUR LOCAL DMV Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT PRIOR TO BIDDING BE RELISTED; BUYER'S RESPONSIBILITY FOR Asset located in: Lake Worth, TX REMOVAL: 9711 2018 Freightliner Cascadia 125 6x4 T/A Asset located in: Lake Worth, TX Sleeper Truck Tractor (Inoperable) 9709A 2019 Freightliner Cascadia 126 6x4 T/A S/N: 3AKJGLDR0JSJR7937 Sleeper Truck Tractor (Inoperable) C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel S/N: 3AKJHHDR5KSKA2508 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-OA-1650 12-Speed Automated Transmission, 12350 lb Exhaust Fluid, Engine Brake, Detroit 12-Speed Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000.0 lb GVWR, Air Ride 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Suspension, 228 in Wheelbase, Air Sliding 5th Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Wheel, Dual Fuel Tanks Usage: Not Available Tires, 11R22.5 Rear Tires, Airliner Suspension, Notes: INOPERABLE ITEM MUST BE REMOVED 225 in Wheelbase, Air Sliding 5th Wheel, FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Lowboy Ramps, Dual Fuel Tanks Usage: 677,092 Mi REMOVAL: Notes: INOPERABLE ITEM MUST BE REMOVED Asset located in: Humble, TX FROM YARD BY JANUARY 10TH AND CANNOT

BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Page 536 of 574 Lot # **Details** Lot # **Details** 9713A 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor CHOICE OF 1 - Lot #'s: 9711A S/N: 3AKJGLDR2HSGV8021 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 9711A 2018 Freightliner Cascadia 125 6x4 T/A hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 12-Sleeper Truck Tractor (Inoperable) Speed Automatic Transmission, 12500 lb Front S/N: 3AKJGLDR7JSJU3695 Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Requires Diesel Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Tanks Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Usage: 742,975 Mi Beds, Thermo King TriPac Evolution Auxiliary Power Unit, 11R22.5, Airliner Suspension, 228 Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR in Wheelbase, Air Sliding 5th Wheel, Dual Fuel REMOVAL Usage: 484,584 Mi Asset located in: Lake Worth, TX Notes: INOPERABLE ITEM MUST BE REMOVED 9714 2016 Freightliner Cascadia 125 6x4 T/A FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Sleeper Truck Tractor (Inoperable) REMOVAL S/N: 1FUJGLD5XGLGU2219 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Asset located in: Lake Worth, TX hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24994 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual 9712 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Transmission, Differential Lock, 12350 lb Front S/N: 3AKJGLDR5JSJK6667 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2017 US EPA Label, Requires Diesel 60 in High Rise Sleeper Cab, Bunk Beds, Exhaust Fluid, 12-Speed Automated Aluminum Wheels, MIXED, Airliner Air Ride Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Usage: 730,665 Mi

Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED

Asset located in: Lake Worth, TX

9713 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 3AKJGLDR9HSJC5723 C/W: Detroit DD15 14.8 L Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5 Front Tires, 425/65R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks**

Usage: Not Available

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Asset located in: Midland, TX

Axle, 40000 lb Rears, Planetary Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Suspension, 230 in Wheelbase, Dual Fuel Tanks

Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

9714A 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 3AKJGLD50GSHA9524 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 778,378 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Lot # Details 9715 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDV4GSHD4846 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission. 12500 lb Front Axle. 40000 lb

hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: Not Available

Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL:

Asset located in: Lake Worth, TX

9716A 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 3AKJGLDR8GSGV0892 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 21275 Engine hrs, Engine Brake, Detroit DT12-OH-1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 873,267 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Asset located in: Lake Worth, TX

9716B 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 3AKJGLBG5FSGC7243 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 23900 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 216 in Wheelbase Usage: 742,719 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Lake Worth, TX

9719 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

Lot #

Details

S/N: 3AKJGLDR4ESFD3920 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10571 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,029,912 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Lake Worth, TX

9720 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1FUJGLD61ELFM1902 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 244 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Asset located in: Midland, TX

9721 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1FUJGLBG8CSBM1768 C/W: Cummins ISX 6 Cylinder 450 hp Engine, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DS404 Drive Axles, 3.55:1 Axle Ratio, 53200 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel

Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Details Lot# **Details** Lot # 9721A 2020 Volvo VNL860 6x4 T/A Sleeper Truck 9724 2016 Volvo VNL 780 6x2 T/A Sleeper Truck Tractor (Inoperable) Tractor (Inoperable) S/N: 4V4N99EH7GN950842 S/N: 4V4NC9TJ8LN253794 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 425 hp hp Engine, 2019 US EPÁ Label, Requires Diesel Engine, Requires Diésel Exhaust Fluid, Exhaust Fluid, 18160 Engine hrs, Engine Brake, Eaton Fuller FO-18E313A MHP Automatic Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, Aluminum Wheels, 295/75R22.5, Volvo 51200.0 lb GVWR, Air Ride Cab, 77 in High Rise Corporate Air Air Ride Suspension, 228 in Sleeper Cab, Bunk Beds, Aluminum Wheels, 275 Wheelbase, Air Sliding 5th Wheel, Dual Fuel /70R22.5, Air Ride Suspension, 240 in Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: 826,608 Mi Notes: INOPERABLE ITEM MUST BE REMOVED Usage: 540,590 Mi FROM YARD BY JANUARY 10TH AND CANNOT Notes: INOPERABLE ITEM MUST BE REMOVED BE RELISTED; BUYER'S RESPONSIBILITY FOR FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN 9725 2019 International LT625 6x4 T/A Sleeper YOUR STATE. VERIFY WITH YOUR LOCAL DMV Truck Tractor (Inoperable) PRIOR TO BIDDING S/N: 3HSDZAPR7KN110756 Asset located in: Lake Worth, TX C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel 9722 2018 Volvo VNL 6x4 T/A Sleeper Truck Tractor Exhaust Fluid, Engine Brake, Automatic (Inoperable) Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, S/N: 4V4NC9EH1JN961795 C/W: Volvo D13M455 6 Cylinder 12.8 L 455 hp 275/80R22.5 Front Tires, 275/80R22.5 Rear Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Tires, Air Ride Suspension, 228 in Wheelbase, Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Drive Axles, 2.47:1 Axle Ratio, 50350.0 lb Notes: INOPERABLE ITEM MUST BE REMOVED GVWR, Air Ride Cab, 77 in High Rise Sleeper FROM THE YARD BY JANUARY 10TH AND Cab, Bunk Beds, Aluminum Outer Wheels, 275 /80R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel CANNOT BE RELISTED Asset located in: Lake Worth, TX Tanks 9726 2019 International LT625 6x4 T/A Sleeper Usage: 1,015,854 Mi Truck Tractor (Inoperable) Notes: INOPERABLE ITEM MUST BE REMOVED S/N: 3HSDZAPR0KN110761 FROM YARD BY JANUARY 10TH AND CANNOT C/W: Cummins X15 6 Cylinder 15 L 450 hp BE RELISTED; BUYER'S RESPONSIBILITY FOR Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Asset located in: Lake Worth, TX Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 228 in Wheelbase, Air 9723 2017 Volvo VNL670 6x4 T/A Sleeper Truck Tractor (Inoperable) Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available S/N: 4V4NC9THXHN983209 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Notes: LOADING ASSISTANCE UNAVAILABLE Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM Ride Cab, 61 in High Rise Sleeper Cab, Bunk THE YARD BY JANUARY 10TH AND CANNOT Beds, 11R22.5, Air Ride Suspension, 217 in BE RELISTED Wheelbase, Air Sliding 5th Wheel, Dual Fuel Asset located in: Lake Worth, TX

Tanks

Usage: Not Available

SEE THE INSPECTION REPORT Asset located in: Humble, TX

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE

Details Lot# **Details** Lot # 9727 2019 International LT625 6x4 T/A Sleeper 9730 2018 International LT625 6x4 T/A Sleeper **Truck Tractor (Inoperable)** Truck Tractor (Inoperable) S/N: 3HSDZTZR4JN416241 S/N: 3HSDZAPR5KN098185 C/W: Cummins X15 6 Cylinder 15 L 450 hp C/W: Navistar A26 6 Cylinder 13 L Diesel Engine, Requires Diesel Exhaust Fluid, 6691 Engine hrs, Engine Brake, Automated Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Transmission, 12350 lb Front Axle, 40000 lb Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Rears, 52350.0 lb GVWR, Air Ride Cab, 73 in Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Usage: Not Available Super Singles Rear Tires, Hendrickson Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Notes: LOADING ASSISTANCE UNAVAILABLE Wheel, Dual Fuel Tanks ON THIS UNIT. OUTSIDE LOADING Usage: 671,789 Mi ASSISTANCE WILL NEED TO BE SET UP. **Notes**: UNIT STARTS AND RUNS, ENGINE SEVERELY DERATED ; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED 10TH AND CANNOT BE RELISTED; BUYER'S Asset located in: Lake Worth, TX RESPONSIBILITY FOR REMOVAL; 9728 2019 International LT625 6x4 T/A Sleeper Asset located in: Lake Worth, TX Truck Tractor (Inoperable) 2006 Volvo VT 880 6x4 T/A Sleeper Truck 9731 S/N: 3HSDZAPRXKN109682 Tractor (Inoperable) C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel S/N: 4V4LC9KL86N419522 C/W: Volvo D16D600 6 Cylinder 16.1 L Diesel 600 hp Engine, 2006 US EPA Label, Eaton Exhaust Fluid, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Fuller 18-Speed Manual Transmission, 12500 Ib Front Axle, 38000 lb Rears, 50500 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Suspension, 256 in Wheelbase, Air Sliding 5th Notes: LOADING ASSISTANCE UNAVAILABLE Wheel, Headache Rack, Dual Fuel Tanks ON THIS UNIT. OUTSIDE LOADING Usage: Not Available ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED REMOVAL Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 9729 2018 International LT625 6x4 T/A Sleeper 9732 2000 Freightliner Columbia 120 6x4 T/A **Truck Tractor (Inoperable)** Sleeper Truck Tractor (Inoperable) S/N: 3HSDZAPR2JN438729 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp S/N: 1FUYSSZB1YLF32067 Engine, 2017 US EPA Label, Requires Diesel C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 13200 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 73 in 70 in High Rise Sleeper Cab, Bunk Beds, High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 244 in Wheelbase, Air Aluminum Outer Wheels, 295/75R22.5, Airliner Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED

FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Asset located in: Lake Worth, TX

REMOVAL;

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT

BE RELISTED; BUYER'S RESPONSIBILITY FOR

Lot #	Details	Lot #	Details
9733	1999 Volvo VNL 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 4VG7DAJJ8XN788188 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller FRO-16210C Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, Eaton Drive Axles, 3.7:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 212 in Wheelbase, Lowboy Ramps, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9735	2011 Capacity TJ5000 4x2 Spotter Truck (Inoperable) S/N: 4LMBR2118BL022572 C/W: Cummins 6 Cylinder 6.7 L Diesel 173 hp Engine, Allison Automatic Transmission, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9734	1998 Freightliner FLD 120 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1FUYDDYB5WPA02987 C/W: 12000 lb Front Axle, 38000 lb Rears, 48000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, 285/75R24.5, Air Ride Suspension, 211 in Wheelbase, Dual Fuel Tanks Usage: 535,289 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9735A	2011 Capacity TJ5000 4x2 Spotter Truck (Inoperable) S/N: 4LMBR2118BL022569 C/W: Cummins 6 Cylinder Diesel Engine, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
9734A	2012 Ford F-550 XL 4x2 Extended Cab Service		Asset located in: Lake Worth, TX
	Truck (Inoperable) S/N: 1FD0X5GT6CEC35272 C/W: V8 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 186 in Wheelbase, 14 ft Body, Hydraulic Stabilizers, Liberator 6HYD-LS 6000 lb 3 Section Hydraulic Crane Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9736	2012 Peterbilt 367 6x4 Winch Truck (Inoperable) S/N: 1XPTD40X4CD146614 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 15245 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 225 in Wheelbase, PTO, Tail Roll, Ramsey Winch, Lowboy Ramps Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9734B	2019 Nissan Frontier 4x2 Extended Cab Utility		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	Truck (Inoperable) S/N: 1N6AD0CU5KN753789		Asset located in: Lake Worth, TX
	C/W: Nissan V6 4.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 3296 lb Front Axle, 3331 lb Rears, 5588 lb GVWR, 265 /70R16, Spring Suspension, 126 in Wheelbase, 6 ft 8 in Body Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9737	2013 International 7600 6x4 Vacuum Excavator Truck (Inoperable) S/N: 1HTGSSJT1DJ167340 C/W: International 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 38: /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 263 in Wheelbase, 58000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details
9738	1988 International 1954 4x2 Vacuum Excavator Truck (Inoperable) S/N: 1HTLDTVN5JH610926 C/W: 6 Cylinder Diesel Engine, 5809 Engine hrs, Manual Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 188 in Wheelbase, PTO, Dual Fuel Tanks Usage: 326,151 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9742	1999 Volvo VN 4x2 Cab and Chassis (Inoperable) S/N: 4VA7BBRF8XN784017 C/W: Detroit Series 60 6 Cylinder 11.1 L Diesel 365 hp Engine, 1998 US EPA Label, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 152 in Wheelbase, 89 in Cab to Axle, 121 in Cab to End of Frame, Pintle Hitch Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND TAX FOR
9739	2008 International 4400 4x2 Pressure Truck (Inoperable) S/N: 1HTMKAAN08H535972 C/W: 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab,		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; LOCATED-IN-JUSTIN-TX; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Lake Worth, TX
	11R22.5, Air Ride Suspension, 208 in Wheelbase, Dual PTO, Triplex Pump, Steel Tank Usage: Not Available Asset located in : Lake Worth, TX	9742A	2012 Chevrolet 3500 4x2 Crew Cab Cab and Chassis (Inoperable) S/N: 1GB4CZCL2CF161801 C/W: GM 6.6 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic
9740	2010 Mack 6x4 Cab and Chassis (Inoperable) S/N: 1M2AN09C3AN006300 C/W: Mack MP8 6 Cylinder 12.8 L 425 hp Engine, 2008 US EPA Label, Engine Brake, Allison Automatic Transmission, Mack Drive Axles, Air Ride Cab, 11R24.5, Camelback Spring Suspension, 220 in Wheelbase, 130 in Cab to Axle, 180 in Cab to End of Frame Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, CANNOT BE DRIVEN. TEMP TAGS WILL NOT BE ISSUED; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX		Transmission, 5200 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 265/70R17, Spring Suspension, 172 in Wheelbase, 60 in Cab to Axle, 112 in Cab to End of Frame Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
		9743	2016 Chevrolet Express G3500 4x2 Cab and Chassis (Inoperable) S/N: 1GB3GRCG1G1277688 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225
9741			/75R16, Spring Suspension, 142 in Wheelbase, 81 in Cab to Axle, 139 in Cab to End of Frame Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
	Wheelbase, 90 in Cab to Axle, 139 in Cab to End of Frame Usage: 151,346 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX	9743A	(Inoperable) S/N: 1FDAF56P64EC24687 C/W: V8 6.0 L Diesel 325 hp Engine, 2004 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 19000 lb GVWR, Aluminum Outer Wheels, 245/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 165 in Wheelbase, 84 in Cab to Axle, 132 in Cab to End of Frame Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Details Lot # **Details** Lot # 9745B 9743B 2006 International 4300 SBA 4x2 Flatbed Truck 2011 Dodge Ram 5500 4x2 Crew Cab Flatbed Truck (Inoperable) (Inoperable) S/N: 3D6WA7CL0BG612391 S/N: 1HTMMAAM46H186863 C/W: International D210CFF 6 Cylinder 7.6 L C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Diesel 210 hp Engine, 2005 US ÉPA Label, Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, 153 in Wheelbase, Arrow Suspension, 196 in Wheelbase, 12 ft x 102 in Board Bed Usage: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Asset located in: Lake Worth, TX FROM YARD BY JANUARY 10TH AND CANNOT 9746 2018 Ram 4500 4x2 Crew Cab Flatbed Truck BE RELISTED; BUYER'S RESPONSIBILITY FOR (Inoperable) RFMOVAL S/N: 3C7WRKEL5JG259100 Asset located in: Lake Worth, TX C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 325 9743C 1999 Volvo VN 4x2 Flatbed Truck (Inoperable) hp Engine, 2018 US EPÁ Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 S/N: 4VG7DBUF5XN768395 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 175 in Wheelbase, 9 ft 5 in x 93 in Bed C/W: Cummins ISM 6 Cylinder 10.8 L Ultra Low Sulfur Diesel 330 hp Engine, 1998 US EPA Label, Eaton Fuller Automatic Transmission, Aluminum Wheels, 295/75R22.5 Front Tires, Usage: Not Available 275/80R22.5 Rear Tires, Volvo Spring Notes: INOPERABLE ITEM MUST BE REMOVED Suspension, 237 in Wheelbase, 10 ft 4 in x 96 FROM YARD BY JANUARY 10TH AND CANNOT in Bed BE RELISTED; BUYER'S RESPONSIBILITY FOR Usage: 834,602 Mi REMOVAL Notes: INOPERABLE ITEM MUST BE REMOVED Asset located in: Lake Worth, TX FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR 9747 2006 Ford F-450 XL 4x2 Crew Cab Flatbed REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV Truck (Inoperable) S/N: 1FDXW46P46EB71060 C/W: V8 6.0 L Diesel Engine, 2008 US EPA PRIOR TO BIDDING Label, Automatic Transmission, 6500 lb Front Asset located in: Lake Worth, TX Axle, 12000 lb Rears, 16000 lb GVWR, 245 /70R19.5, Spring Suspension, 200 in 9744 2010 Mitsubishi Fuso 4x2 COE Extended Cab Wheelbase, 12 ft x 93 in Bed Usage: 170,254 Mi Flatbed Truck (Inoperable) S/N: JL6CCG1S4AK009133 Notes: INOPERABLE ITEM MUST BE REMOVED C/W: Mitsubishi 4 Cylinder Diesel Engine, FROM YARD BY JANUARY 10TH AND CANNOT Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 17995 lb GVWR, 215/75R17.5, BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Spring Suspension, 153 in Wheelbase, 14 ft 3 Asset located in: Humble, TX in x 91 in Bed Usage: 162,766 Mi 9747A 2022 Ram 3500 4x4 Crew Cab Flatbed Truck Notes: INOPERABLE ITEM MUST BE REMOVED (Inoperable) FROM YARD BY JANUARY 10TH AND CANNOT S/N: 3C7WRTCL3NG365057 BE RELISTED; BUYER'S RESPONSIBILITY FOR C/W: 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Asset located in: Humble, TX Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring 9745A 1998 International 4900 6x4 Flatbed Truck Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in (Inoperable) Bed S/N: 1HTSHAAR5WH533334 Usage: Not Available C/W: 6 Cylinder Diesel Engine, International 6-Notes: INOPERABLE ITEM MUST BE REMOVED Speed Manual Transmission, 11R22.5, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 226 in Wheelbase, FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN 23 ft x 94 in Bed, Dovetail, Hydraulic Ramps Usage: 58,070 Mi YOUR STATE. VERIFY WITH YOUR LOCAL DMV Notes: INOPERABLE ITEM MUST BE REMOVED PRIOR TO BIDDING; PLEASE SEE DEFICIENCIES, TRANSMISSION IS IN VERY FROM YARD BY JANUARY 10TH AND CANNOT **BAD CONDITION** BE RELISTED; BUYER'S RESPONSIBILITY FOR Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9748	2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT7KEC83810 C/W: Ford Power Stroke V8 6.7 L Diesel 330 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 2 in x 92 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9750A	2016 Ford F-350 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT1GED26318 C/W: Ford Power Stroke 6.2 L Diesel Engine, 2016 US EPA Label, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, Aluminum Wheels, 245/75R17, Spring Suspension, 178 in Wheelbase, 9 ft 4 in x 93 in Bed, Receiver, Fifth wheel ball Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9748A	2018 Ford F-350 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT7JEC67900 C/W: Ford Power Stroke V8 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 Ib Front Axle, 10040 Ib Rears, 3.73:1 Axle Ratio, 140000 Ib GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 2 in x 90 in Bed, Receiver hitch, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9751A	2017 GMC 3500 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1GT42VCY6HF232993 C/W: V8 Diesel Engine, Automatic Transmission, 5600 lb Front Axle, 7050 lb Rears, 11600 lb GVWR, 275/65R18, Spring Suspension, 166 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2012 Peterbilt 388 6x4 Sleeper Car Carrier Truck (Inoperable)
9749	2018 Ford F-250 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FT7W2BT4JEB73055 C/W: V8 6.7 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 6340 lb Rears, 10000 lb GVWR, 33X12. 50R18, Spring Suspension, 176 in Wheelbase, 8 ft 6 in x 80 in Bed, Fuel Tank /w Pump Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		S/N: 1NPWD49X3CD134979 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 45000 lb GVWR, 48 in Mid Roof Sleeper Cab, 295/60R22.5, Air Leaf Air Ride Suspension, 254 in Wheelbase, PTO, Hydraulic Lift, Soft Tie Downs, SOLD WITH - 2011 Cottrell CX-11HCSD T/A, Trailer S/N - 5E0AJ1445CG349901, Soft Ties, 255/70R22.5 Tires, 45000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9750	2007 Ford F-550 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1FDAW56PX7EA92103 C/W: Automatic Transmission, 6500 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225- 70R19.5, Spring Suspension, 12 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9753	2015 Freightliner 114SD 6x4 Mixer Truck (Inoperable) S/N: 1FVHG3DV3FHGC6645 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17826 Engine hrs, Engine Brake, Allison 4000 Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 208,567 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	9756	2019 International 4300 4x2 Rollback Truck (Inoperable) S/N: 3HAEUMML5KL556456 C/W: Cummins B 6 Cylinder 6.7 L 300 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7063 Engine hrs, Allison Automatic Transmission, 8000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 255/70R22.5, Air Ride Suspension, 210 in Wheelbase, PTO, Miller Rollback Body, 19 ft 4 in x 102 in Bed, Ramsey HD234 8000 lb Winch Usage: 142,777 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM	9757	2016 International 4300 4x2 Van Truck	
9754	2015 Freightliner 114 SD 6x4 Mixer Truck (Inoperable) S/N: 1FVHG3DV7FHGD3310 C/W: Detroit 6 Cylinder 12.8 L Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, 425/65R22.5, Double Frame, Rubber over Walking Beam Suspension, 229 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT		Label, Automatic Transmission, Axle, 19000 lb Rears, 25999 lb 0 Engine hrs, 11R22.5, Spring Sus Wheelbase, 24 ft x 96 in Wide x Body, Curbside Door, Liftgate Usage: 149,593 Mi Notes: INOPERABLE ITEM MUS FROM YARD BY JANUARY 10TH BE RELISTED. BUYER'S RESPON REMOVAL OF THIS ITEM	S/N: 1HTMNAAL1GH031595 C/W: Navistar 6 Cylinder Engine, 2016 US EPA Label, Automatic Transmission, 9000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 8002 Engine hrs, 11R22.5, Spring Suspension, 254 in Wheelbase, 24 ft x 96 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 149,593 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM	9758	2012 Isuzu NPR 4x2 COE Van Truck (Inoperable)	
9755	Asset located in: Lake Worth, TX 1999 Peterbilt 357 8x4 Mixer Truck (Inoperable) S/N: 1NPALTOX7XD494329 C/W: Cat C10 6 Cylinder Ultra Low Sulfur Diesel Engine, 21033 Engine hrs, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 53200 lb Rears, 60000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Trailing Tag Axle, Hendrickson Walking Beam Suspension, 250 in Wheelbase, PTO, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 212,655 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		S/N: JALE5W163C7301062 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 177 in Wheelbase, Morgan 18 ft x 96 in Wide x 85 in High Body, Curbside Door, Liftgate Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9759	2020 GMC G3500 4x2 Van Truck (Inoperable) S/N: 7GZ37TCG1LN010503 C/W: GM V8 6.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225 /75R16, Spring Suspension, 178 in Wheelbase, 17 ft x 96 in Wide x 76 in High Body, Curbside Door Usage: Not Available Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9761D 9762	2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPA06W063547 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX 2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor (Inoperable)
9761A	Asset located in: Lake Worth, TX 2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPA76W063464 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 362 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX		S/N: 1XPBA48X4GD339490 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21678.6 Engine hrs, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 862,236 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
9761B	2006 MCI J4500 6x2 56-Seat Coach		Asset located in: Lake Worth, TX
9761C	(Inoperable) S/N: 2M93JMPA46W063454 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit 6 Cylinder Diesel Engine, 315 /80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX 2006 MCI J4500 6x2 56-Seat Coach	9762A	2005 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMDA45W062954 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX
37010	(Inoperable) S/N: 2M93JMPA26W063548 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9762B	2005 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMDA65W063118 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX

			rage 340 01 374
Lot #	Details	Lot #	Details
9762C	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XPBA48X5FD286278 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 12-Speed Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Trac Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9764A	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBGDD55FLGB0203 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9763	2018 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYAP8X5JJ207624 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11R22.5, Air Ride Suspension, EQUIPMENT-FROM-YELLOW-CORP Usage: 490,446 Mi Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9764B	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3AKBGDDV3ESFV6407 C/W: Detroit DD13 6 Cylinder 12.8 L Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 15959 Engine hrs, Engine Brake, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-161 Drive Axles, 3.58:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 542,172 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9764	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYA48X2EJ355427 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2019 US EPA Label, 16235 Engine hrs, Eaton Fuller FM-15E310B-LAS Automated Transmission, 12700 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 155 in Wheelbase, Air Sliding 5th Wheel Usage: 723,788 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9765	2014 Freightliner Cascadia 113 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBGADV6ELFR1033 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 380 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-14210B 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 2.67:1 Axle Ratio, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 901,385 Mi Notes: CANNOT VERIFY ODOMETER READING - VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9766	2015 Freightliner M2 112 4x2 S/A Day Cab Truck Tractor (Inoperable)	9768A	2005 International 9400i 4x2 S/A Day Cab Truck Tractor (Inoperable)
	S/N: 1FUBC5CY4FHGK0774 C/W: Cummins ISL9 Diesel 330 hp Engine, Eaton Fuller FO-10E310C-VAS Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 4.56:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 158 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available		S/N: 3HSCPAPN05N049267 C/W: Cummins ISX 6 Cylinder 400 hp Engine, 2004 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 835,214 Mi
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; CANNOT VERIFY ODOMETER
9767	2009 International TranStar 8600 4x2 S/A Day	1	READING - VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE
	Cab Truck Tractor (Inoperable) S/N: 1HSHWAHN59J674277		Asset located in: Lake Worth, TX
9767A	C/W: Cummins ISM 6 Cylinder 10.8 L Diesel Engine, 24234 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 151 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 615,671 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9769	2002 International 9200i 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 2HSCDAMN82C032078 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 470 hp Engine, 2001 US EPA Label, Eaton Fuller 9-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED
9/0/A	2009 International 4400 4x2 S/A Day Cab Truck Tractor (Inoperable)		Asset located in: Lake Worth, TX
	S/N: 1HSMKAAN99J696805 C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel Engine, 16364 Engine hrs, Allison 6- Speed Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 295 /75R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 153 in Wheelbase Usage: 236,461 Mi Asset located in: Lake Worth, TX	9769A	2019 Chevrolet 3500HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC4KVCG2KF227899 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 11000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available
9768	2005 International 9400i 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HSCPSBN35N049230		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	C/W: Cat 6 Cylinder Engine, Eaton Fuller		Asset located in: Lake Worth, TX
	Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9770	2019 Chevrolet 2500 LT 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KSEY4KF120067 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, 275/70R18 Tires, 7 ft 11 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9771	2019 Chevrolet 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KSEY4KF119050 C/W: 6.6 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Fuel Tank, 10000 lb GVWR, 265/70R17 Tires, 4 ft 11 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9774A 9775	2019 Toyota Tundra SR5 4x2 Crew Cab Pickup (Inoperable) S/N: 5TFRM5F18KX141630 C/W: 4.6 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 6 ft 2 in Bed Usage: 291,346 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9772	2019 Ford F-250 XL 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2BT9KEE68282 C/W: Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, RKI Tool Box, Drop- In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed		REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2014 Ford F-250 XL 4x2 Crew Cab Pickup (Inoperable) S/N: 1FT7W2A63EEB14161
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 6 ft 8 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
9773	2017 Ford F-250 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2B65HEF24902 C/W: 6.7 L V8 Diesel Engine, 2017 US EPA Label, Automatic Transmission, Power Windows, Weather Guard Fuel Tank /w Pump, Tool Box, 10000 lb GVWR, 285/70R17 Tires, 6 ft 10 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2015 GMC 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 1GT12XE87FF109762 C/W: 6.6 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
		9775A	2012 Dodge Ram 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6TD5JT7CG347856 C/W: 5.7 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, 8000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 218,934 Mi Notes: INOPERABLE ITEM MUST BE REMOVED
9774			FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
		9776	2013 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KVCG2DF243378 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9777A	2011 GMC Sierra 2500HD 4x4 Extended Cab Pickup (Inoperable) S/N: 1GT22ZCG7BZ412902 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 154,930 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9778B	2014 Ford F-150 XLT 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTEX1CM5EKG46930 C/W: 3.7 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, UWS Tool Box, 6700 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 177,206 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX 2014 Chevrolet Silverado 1500 4x4 Crew Cab
9777B	Asset located in: Lake Worth, TX 2011 Ford F-150 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTFW1EF8BKD94995 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 221,657 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9779A	Plug-In Hybrid Pickup (Inoperable) S/N: 3GCUKPEH6EG534447 C/W: 4.3 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, BetterBuilt Tool Box, Drop-In Bed Liner, 7600 lb GVWR, 265 /70R17 Tires, 6 ft Bed Usage: 19,155 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 1994 Dodge Ram 2500 4x2 Pickup (Inoperable)
9777C	Asset located in: Lake Worth, TX 2019 Ram 2500 4x2 Crew Cab Pickup (Inoperable) S/N: 3C6UR4HJXKG643411 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 224,960 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		S/N: 1B7KC26C5RS655611 C/W: 5.9 L 6 Cylinder Diesel Engine, 5 Speed Manual Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 245/75R16 Tires, 8 ft Bed, EQUIPMENT-FROM-YELLOW-CORP Usage: 184,458 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX 2011 Chevrolet Silverado 1500 4x2 Extended
9777D	PROCESS TITLE Asset located in: Lake Worth, TX 2015 GMC 2500 4x4 Extended Cab Pickup (Inoperable) S/N: 1GT22XEG0FZ106115 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		Cab Pickup (Inoperable) S/N: 1GCRCPE04BZ255670 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Headache Rack, RKI Tool Box, 6800 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9780	1997 Ford F-150 XL 4x4 Pickup (Inoperable) S/N: 1FTDF1823VNC21842 C/W: 4.2 L V6 Gasoline Engine, Automatic Transmission, Air Conditioner, 6000 lb GVWR, 255/70R16 Tires, 8 ft Bed, EQUIPMENT-FROM- YELLOW-CORP Usage: 191,594 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN	D T	2014 Audi Q7 2WD SUV (Inoperable) S/N: WA1LGAFE6ED011693 C/W: V6 3.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth TX	9783B	2003 Lincoln Aviator 2WD SUV (Inoperable) S/N: 5LMEU68H33ZJ43427
9781	Asset located in: Lake Worth, TX 2021 Ford Ranger XL 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTER1EH0MLD55223 C/W: 2.3 L 4 Cylinder Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Northern Tool Equipment Tool Box, 255/70R16	C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Powe Windows, Power Locks, 3rd Row Usage: 218,683 Mi Notes : TEXAS BUYERS MUST STOP	C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 218,683 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	Tires, 6 ft Bed Usage: 32,412 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9784	1995 Fontaine 352J 70000 lb T/A Heavy-Haul Jeep (Inoperable) S/N: 4LF3N2625S3503582 C/W: Sliding 5th Wheel, Air Ride Suspension, 275/70R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9782	2015 Chevrolet Spark Automobile (Inoperable) S/N: KL8CD6S93FC709764 C/W: 4 cyl 1.2 L Gasoline Engine, 2015 US EPA	9786	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 94,644 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX		2005 Wilson 42 ft T/A Belly Dump Grain Trailer (Inoperable) S/N: 1W1MCF1A35B240910 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 2 Hoppers, Manual Traps, 9 ft Aluminum Box, 72 in, Side Walls, Manual Roll Tarp, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available
9783	2017 Jaguar F-Pace AWD SUV (Inoperable) S/N: SADCJ2BN8HA089275 C/W: 4 cyl 2.0 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 77,696 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS UNIT. OUTSIDE LOADING ASSISTANCE WILL NEED TO BE SET UP. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9787	2015 Wabash RFALHSA 53 ft T/A Refrigerated Trailer (Inoperable) S/N: 1JJV532B4FL840000 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	9791	Quantity of (2) Electric Motor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
		9792	Quantity of (2) Electric Motor S/N: Not Available C/W: Electrico, Sew-Eurodrive; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
		9793	Quantity of Electric Motor S/N: Not Available C/W: Assorted Size, One Pallet; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available
9788	2013 Great Dane 48 ft x 96 in T/A Refrigerated Trailer (Inoperable)		Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	S/N: 1GRAA9625DB711787 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Swing Door, Carrier Transcd Refrigeration Unit, Serial Number JAV90746822,, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE	9794 2005 McElroy Roller Fusion I (Inoperable) S/N: C11420 C/W: 8 in Clamp SIze, Pipe C Usage: 606 Hr Notes: ITEM AT OFFSITE LO	2005 McElroy Roller Fusion Machine (Inoperable) S/N: C11420 C/W: 8 in Clamp SIze, Pipe Cutter Usage: 606 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
9788A	Asset located in: Lake Worth, TX 7788A 2016 Lucon T-125 S/A (1) Reel Trailer (Inoperable) S/N: 1L9PU1012GG423949 C/W: 225/75R15 Tires, 4260 lb GVWR,		SUBJECT TO 3RD PARTY STORAGE FEES; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
			REMOVAL; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK
		9795	McElroy Roller Fusion Machine S/N: C14830 C/W: 8 in Clamp Slze, Pipe Cutter Usage: 352 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9789	2014 Sauber 1570-B Hydraulic Cable Puller and Tensioner S/N: 1F9UZ1310EV048032 C/W: 2013 US EPA Label, Honda 1 Cylinder .68 L Gasoline Engine Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9796	McElroy PitBull 412 Tracked Fusion Machine S/N: C15330 C/W: 13 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 2,119 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY
9790	Cat Engine S/N: Not Available C/W: Cat 3116 6 Cylinder 6.6 L Diesel Engine, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Corsicana, TX		Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9797	McElroy PitBull 618 Tracked Fusion Machine S/N: C29981 C/W: 18 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 397 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE	9804	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9805	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available
9798	McElroy PitBull 412 Tracked Fusion Machine S/N: C22603		Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	C/W: 13 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW Diesel Engine, 7 in Rubber Tracks Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY	9806	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	Asset located in: Lahoma, OK	9807	Blowout Preventer S/N: Not Available
9799	McElroy PitBull 618 Tracked Fusion Machine S/N: C32754 C/W: 18 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW		C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
	719 cc Diesel Engine, 7 in Rubber Tracks Usage: 444 Hr Notes : ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY	9808	Blowout Preventer
			S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	_	Asset located in: Cedar Bluff, VA
9800	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9809	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
9801	Quantity of Tongs	9810	Regan Torus Blowout Preventer
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA		S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
9802	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9811	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA
9803	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9812	Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details	
9813	Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Cedar Bluff, VA	9818	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	
9814	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	9819	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	
9815	THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	9820	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	
9816	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	9821	BUYER RESPONSIBLE FOR LOADOUT. NOT BE ABLE TO ASSIST WITH LOADI THESE; RITCHIE-BROS-ENERGY	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
9817	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Sioux S195667 Pipe Stands S/N: Not Available		Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	
	C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST		NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	
		9822	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9823	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9828	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9824	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9829	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9825	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9830	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9826	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9831	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9827	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9832	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9833	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9838	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9834	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9839	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9835	Quantity of Sioux \$180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9840	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9836	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9841	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9837	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9842	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9843	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	9848	Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
	NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK		NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in : Lahoma, OK
9844	Quantity of Pipe Stands	9849	Quantity of (616) Pipeline Skids
2011	S/N: Not Available C/W: 6 Stacks Usage: Not Available	3013	S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK	ļ	Asset located in: Lahoma, OK
9845	Quantity of Pipe Stands S/N: Not Available C/W: 2 Stacks Usage: Not Available	9850	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9846	Quantity of Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9851	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9847	Quantity of Pipe Stands	9852	Quantity of (616) Pipeline Skids
	S/N: Not Available C/W: 5 Stacks		S/N: Not Available C/W: 48 in. x 6 in. x 4 in.
	Usage: Not Available		Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9853	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9858	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9854	Quantity of (610) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9859	Quantity of (10) Approximately 16 ft x 4 ft Skids (10) Stacks & Misc Pieces Pipeline Skids S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE; RITCHIE-BROS-ENERGY Asset located in: McAlester, OK
9855	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in, There are some 4x4 in mixed in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9860	Pipeline Cradle S/N: Not Available C/W: Double Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9856	Asset located in: Lahoma, OK Quantity of (600) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9861	Pipeline Cradle S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Pipeline Cradle
9857	Quantity of (580) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		S/N: Not Available C/W: Single Head, Single Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9863	Pipeline Cradle S/N: Not Available C/W: Single Head, Double Roller Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9867	2009 MacElroy LT0048 T/A Hydraulic Line Tamer S/N: C30327 C/W: To Fit McElroy Manufacturing, Inc LineTamer poly pipe straightener, 2002 US EPA Label, Honda GXV160 1 Cylinder 163 cc Gasoline Engine Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9864	Darby Pipeline Cradle	0060	<u>`</u>
	S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9868	Quantity of (3) Vaculifter S/N: LT30-000101 C/W: To Fit lift technology LT36 pipe vac lift, Tier 1, 2012 US EPA Label, Hatz CHZXL 445V42 1 Cylinder 6.4 kW .44 L Diesel Engine Usage: 1,278 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES .; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9865	DMH RO Pipeline Cradle S/N: 485	9869	Mathey Dearman 20 in Pipe Beveling Machine
	C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		S/N: M68048 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9866	2013 Mcclain 28 ft Mobile Flare System	9870	Mathey Dearman 12 in Beveling Machine
	S/N: 4LYUS2223DH000570 C/W: T/A, Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, (2) Tool Boxes, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	_	S/N: CE106814 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9866A	Quantity of Assorted Drill Bit S/N: Not Available	9871	Quantity of Denso Protal 7200 Liquid Epoxy
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Coating & Brushes S/N: Not Available C/W: Part A & B Coating Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9872	Mesh S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE	9878	Quantity of (3) Pipe Elevators S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
		9879	Pipe Elevator S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9873	Sand Silo S/N: Not Available C/W: Seller Supplied Info: Approximate dimensions 8ft x 20ft. Buyer responsible for load-out and transport. Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX Quantity of (4) 15 Ft Pipe Cartridges	9880	Quantity of (15) 10 in Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
307 1	S/N: Not Available Usage: Not Available	0001	THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Overtice of (20) Orates of 8 in February Birds
	Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9881	Quantity of (20) Crates of 8 in Foam Pigs S/N: Not Available Usage: Not Available
9874A 	Quantity of (4) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9875	Quantity of (3) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 All Terrain S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9882	Quantity of (13) Assorted Pigs S/N: Not Available C/W: (8) 8 in Bull nose, (1) 8 in Brush, (1) 8 in Bidirectional, (1) 10 in Bidirectional Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
9876	Quantity of (2) 10 ft Pipe Cartridges - Fits Ditch Wtich JT30 & JT3020 S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9877	Quantity of (2) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 Mach I S/N: Not Available Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9883	Quantity of 8 In Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
9877A	Quantity of (2) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		BUYER RESPONSIBLE FOR LOADOUT. RB V NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9884	Quantity of (8) Foam Pigs S/N: Not Available C/W: (7) 16 in, (1) 18 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9889	Quantity of Assorted Night Caps S/N: Not Available C/W: 4 in - 16 in gg Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9885	Quantity of (2) Pipeline Cleaners Plate Sizing Pigs S/N: H582, P615 C/W: (1) 16 in, (1) 10 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY	9890	Quantity of (2) Rock Shield S/N: Not Available C/W: (1) 36 in, (1-60) in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9886	Asset located in: Lahoma, OK Quantity of (7) Stringing Cables S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	-9891	Quantity of (6) Felt Lined Rock Shield S/N: Not Available C/W: (5) 60 in, (1) 36 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9887	Quantity of (12) Boxes of Tape & Primer S/N: Not Available C/W: 3M Tape, RD-6 Tape & Primer Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9892	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (9) 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9888	Quantity of Wax Tape, Primer S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9893	Quantity of Balon Valves S/N: Not Available C/W: One Pallet Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

	Dataila	l ot #	Details
Lot #	Details Overtity of Disc. Fite Daly Disc. Wolding	Lot #	
9894	Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: 4 in, 6 in, 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9898	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Dies, Poly PipeWelding Machine 6 in, 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9895	Quantity of Dies - Fits McElroy 618 Poly Pipe Welding Machine S/N: Not Available C/W: 16 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9899	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, 7-8 in, 4-6 in. Incomplete Sets. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9896	Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: To Fit McElroy 412 Dies, (4) 6 in, (4) 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9900	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in, (8)12 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9897	Quantity of Dies - Fits Poly Pipe Welding Machine S/N: Not Available C/W: To Fit McElroy 412 Dies, 10 in, 12 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9901	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, (12)10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9902	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Poly Pipe Welding Machine, 6 in., 8 in. dies Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9907	Heater - Fits S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9903	Quantity of McElroy Poly Pipe Welding Machine Parts S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	-9908	Quantity of Dies S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, (4) 2 in., (4) 3 in., (7) 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9904	Quantity of Extension Hydraulic Hoses S/N: Not Available C/W: To Fit McElroy Poly Pipe Welding Machines Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9909	McElroy 848701 Electric Heater S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Dies
9905	Quantity of Flange Gaskets S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		S/N: Not Available C/W: To Fit McElroy 618 Poly Pipe Welding Machine, 12 in., 16 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9906	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 618 Poly Pipe Welding Mchine, (8) 16 in., (8) 12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9911	Quantity of Dies S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, 2 in., 3 in., 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9912	Bending Shoe S/N: Not Available C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9917	MMI Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9913	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9918	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9915	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	9919	Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8) 6 in, (8) 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in., (8)12 in.
9916	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9921	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (2) Bending Shoe S/N: 3040918 C/W: (1) 8 in., (1) 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY

Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9922	Bending Shoe Bucket S/N: Not Available C/W: 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9927	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9923	Bending Shoe Bucket S/N: 015M C/W: 6 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9928	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9924	Bending Shoe Bucket		Asset located in: Lahoma, OK
	S/N: Not Available C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9929	929 McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WIL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9925	Remco Bending Shoe S/N: Not Available		
9926	C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe		S/N: Not Available C/W: To Fit Poly Pipe Welding Machir Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION BE PICKED UP WITHIN 14 DAYS OF T AUCTION (JANUARY 3RD) OR WILL B SUBJECT TO 3RD PARTY STORAGE F BUYER RESPONSIBLE FOR LOADOUT NOT BE ABLE TO ASSIST WITH LOAD THESE; RITCHIE-BROS-ENERGY
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY		Total Control of the

Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9931	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9935	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9932	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9936	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9933	McElroy 1242112 Heater S/N: Not Available C/W: To Fit McElroy Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9937	Rigid BF86C Electric Tie In Machine S/N: 086C03820A46 C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9934	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9938	Mustang DBG60 Polyethylene Pipe Squeeze Tool S/N: Not Available C/W: To Fit Poly Pipe, 4 in & 6 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of McElroy Pitt Bull 14 Electric Facer S/N: C20800 C/W: Hester not included Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9940	Quantity of McElroy Pitt Bull 14 Hot Plate, Facer S/N: C147848 C/W: 1-4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9945	Quantity of (3) Calipers S/N: 53951, 32791 C/W: 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9941	Quantity of (5) Calipers S/N: 29897, 52770 C/W: 6 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9946	Quantity of (4) Calipers S/N: Not Available C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9942	Quantity of (5) Calipers S/N: 55693, 1708, 51799, 56642. 77426 C/W: 12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9947	Quantity of (2) Calipers S/N: 57397 C/W: 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK
9943	Quantity of (4) Calipers S/N: 43635 C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9948	Pipe Fittings S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX
9944	Quantity of (3) Calipers S/N: 84426, 82563, 84437 C/W: 16 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9949	Quantity of Pipelayer Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details		
9953	Quantity of (4) Drill Racks S/N: Not Available C/W: (1) 16 ft, (3) 20 ft; EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY, Usage: Not Available Asset located in: Lake Worth, TX	9959	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-09 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		
9954	Quantity of (4) Spy Model 780 Pipeline Detectors S/N: Not Available C/W: (2) Spy Model 670 wet sponge detectors, Fisher TW-6 Pipe and cable locator Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE	9960	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-10 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX 2015 Kaymore FM100300 Pneumatic Grease		
9955	AVAILABLE; RITCHIE-BROS-ENERGY Asset located in: McAlester, OK Quantity of (6) Assorted Pipeline Detectors S/N: Not Available C/W: (4) Spy Detectors, (2) Vivax Metrotech		Hose Reel Skid S/N: 58240-03 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		
	Detectors, misc parts and batteries Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE; RITCHIE-BROS-ENERGY Asset located in: McAlester, OK	9962	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-05 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		
9956	<u></u>	9963	Quantity of (8) Reelcraft CA3319L Grease Hose Reel Skid S/N: 230508-004 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		
		9964	Quantity of (14) Spy 780 Jeep Detector S/N: 7804998 C/W: To Fit Spy 780 Jeep Detector, 4", 6", 8", 10", 12", 16" springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST		
9957	32 ft x 8 ft Mobile Test Unit S/N: DCS489-196 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		
9958	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-07 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	9965	Quantity of (7) Spy 780 Jeep Detector S/N: 7805001 C/W: 4 in, 6 in, 8 in, 10 in, 12 in, 16 in Springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK		

Lot #	Details	Lot #	Details
9966	Quantity of (4) Fisher Research Labs Gemini 3 Metal & Mineral Detector S/N: 102201652 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9971	International Boring 224 Horizontal Boring Machine S/N: 1504 C/W: 16 in Boring Auger, Wisconsin VH4D1A 4 Cylinder Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY
9967	Quantity of (3) Metrotech 810DX Line Locator S/N: 004314 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9971A	Asset located in: Lahoma, OK 2008 Lufkin Tri/A Lowboy Trailer S/N: 1L01D513181166341 C/W: Air Ride Suspension, 28 ft Main Deck, 102 in Usable Deck Width, Pickup Throat, Tail Roller, 255/70R22.5 Tires, 90000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9968	Radiodetection Cat4+ Locator S/N: 10C4EN144291 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	9972	2014 Dynacorp TL1280 Tri/Axle HS Separator Trailer S/N: 2C9T3DFA1E3161480 C/W: 9.9 Mpa/1440psi Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX 2013 Wyatt's Trailer Sales 24 ft T/A Spooling Trailer
9969	THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Quantity of (41) Mats S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	9974	S/N: 1W9GU24253L364589 C/W: 24000 lb GVWR, Spring Suspension, Electric Brakes, Deck Over Tires, Kubota Diesel Powered Self Contained Hydraulic System, 235 /80R16 Tires Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: El Reno, OK 1988 Big Tex 18 Ft T/A Gooseneck Chemical
9970	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK Evans HBM Horizontal Boring Machine S/N: 016 C/W: 2002 US EPA Label, Deutz BF4L913 4 Cylinder 99 hp Diesel Engine Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE; RITCHIE-BROS-ENERGY Asset located in: Lahoma, OK	9974	Trailer S/N: 16VGB1622J1416669 C/W: Spring Suspension, Electric Brakes, Deck Over Tires, 235/85R16 Tires, 19400 lb GVWR, 4 Cylinder Diesel, Triplex Pump, (2) - 500 gallon tanks; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,660 Hr Notes: RITCHIE-BROS-ENERGY; PLEASE SEE A PERSONAL NOTE FROM THE SELLER IN THE DOCUMENTS SECTION BELOW Asset located in: Lake Worth, TX 2005 C & S Trailer World Tri/A (3) Reel Trailer S/N: 44Z255LKX5T014462 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires Usage: Not Available Notes: RITCHIE-BROS-ENERGY

Lot #	Details	Lot #	Details
9975A	2022 Reelstrong CLD20 Tri/A (1) Reel Trailer S/N: 1R9BU1636N1626315 C/W: Honda GX390 Gasoline Engine, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Hydraulic Reel Hoist, 215/75R17.5 Tires, 12451 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9980	2014 Brindle T/A (4) Reel Trailer S/N: 1L90R2626EG085221 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires, 21000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9975B	2022 Reelstrong CLD20 Tri/A (1) Reel Trailer S/N: 1R9BU163XN1626267 C/W: Honda GX390 Gasoline Engine, Lunette Ring Hitch, Torsion Axle, Electric Brakes, 215 /75R17.5 Tires, 12451 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	- 9981	2012 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK18N3C1000066 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/75R17.5 Tires, 10000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9976	2012 Drake T/A (3) Reel Trailer S/N: 1D9BU1410CP472777 C/W: Spring Suspension, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9982	2011 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK16N6B1000015 C/W: Lunette Ring Hitch, 12-16.5 Tires, 7500 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
9977	2020 Pro Fabrication S/A Reel Trailer S/N: 1P9BR101XLC495135 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9982A	1999 Butler S/A (1) Reel Trailer S/N: 1BUC10105X1001719 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 8000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	2020 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK18N6L1000160 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/75R17.5 Tires, 9950 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9984	1995 Redi-Haul S/A Reel Trailer S/N: 47SZ041T5S1010806 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Hydraulic Reel Hoist, 235/75R17.5 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; RITCHIE-BROS-ENERGY
9979 9979A	2016 John Evans 3TSLR S/A (1) Reel Trailer S/N: 1J9T112A4G0003908 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 6000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2016 Mobile Tech S/A (1) Reel Trailer S/N: 1M9BR1013GA859016 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY	9986	2011 Dragon 8400 gal T/A Tanker Trailer S/N: 1UNST4422BS082564 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 70000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX

Lot #	Details	Lot #	Details		
9987	2011 Heil 9500 gal T/A Tanker Trailer S/N: 5HTDL4529B5H23926 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 73000 lb GVWR, Roper Hydraulic Powered Pump, 73000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY	9993	2025 Industrias America 750 gal Trailer Mounted Fuel Tank S/N: 3EZBTT088SA003625 C/W: 12 V Transfer Pump, DEF Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		
	Asset located in: Humble, TX	9994	2025 X-STAR 750 gal T/A Tanker Trailer		
9988A	2011 Stephens T/A Tanker Trailer S/N: 1S9AB15B9BH474104 C/W: 68000 lb GVWR, Air Ride Suspension, 11R22.5 Tires, Steel Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		S/N: 1X9T7B829SH039934 C/W: Ball Hitch, Spring Suspension, 225/75R15 Tires, 10400 lb GVWR, Steel Tank, (1) Reels Electric Powered Pump, 10400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		
9989	2010 Galyean 130 BBL T/A Tanker Trailer S/N: 1G9VT4020AH017248 C/W: Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Steel Tank, 3 Compartments, CHALLENGER Hydraulic Powered Pump Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	9995	2025 X-STAR 750 gal T/A Tanker Trailer S/N: 1X9T7B827SH039933 C/W: Ball Hitch, 225/75R15 Tires, 10400 lb GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 10400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2024 DNJ 750 T/A Tanker Trailer		
9990	<u> </u>		S/N: 1D9D7B927RH870580 C/W: Spring Suspension, Electric Brakes, 225 /75R15 Tires, 12000 lb GVWR, Steel Tank, FILL RITE Electric Powered Pump, 12000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 1998 Comptank 6250 gal Tri/A FRP Tanker Trailer		
	Notes: RITCHIE-BROS-ENERGY Asset located in: Livingston, LA	9997			
9990A	2003 Heil 8400 gal T/A Tanker Trailer S/N: 5HTDL452X35G14702 C/W: Spring Suspension, 11R24.5 Tires, Stainless Steel Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY		S/N: 2C9LTA3C3WB075132 C/W: Spring Suspension, Lift 1st- Axles, 11R24. 5 Tires, FRP Tank, Catwalk w/Guardrails Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		
	Asset located in: Lake Worth, TX	9998	1997 Trailmaster 8400 gal T/A Tanker Trailer		
9991	2025 X-STAR 990 gal T/A Tanker Trailer S/N: 1X9T7BA22SH039932 C/W: Aluminum Frame, Ball Hitch, 235/80R16 Tires, 14000 lb GVWR, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available		S/N: 190DL4428V3G13006 C/W: Aluminum Frame, Spring Suspension, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		
	Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	9999	1995 Polar 4400 gal 4/Axle Tanker Trailer		
9992	2025 X-STAR 990 gal T/A Tanker Trailer S/N: 1X9T7BA20SH039931 C/W: Ball Hitch, Spring Suspension, 235/80R16 Tires, 14000 lb GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		S/N: 1R9212339SL040301 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
10000	1973 Trim T/A Tanker Trailer S/N: K40092 C/W: Spring Suspension, Aluminum Wheels, 11R22.5 Tires, Stainless Steel Tank, Catwalk, Gasoline Powered Pump Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10007	2016 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA27GG347032 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	
10001	2020 Troxell 5460 gal T/A Vacuum Tanker Trailer S/N: 1T9TA4320L1867597 C/W: Spring Suspension, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Challenger 607 Hydraulic Blower, 50000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	10008	2015 Keith Huber 5500 gal T/A Vacuum Tanker Trailer S/N: 1K9TS5522F1077001 C/W: Spring Suspension, 11R24.5 Tires, 45000 lb GVWR, Steel Tank, Catwalk w/Guardrails, Fruitland Diesel Powered Pump, 45000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; RITCHIE-BROS-	
10002	2019 Southern 150 bbl T/A Vacuum Tanker Trailer		ENERGY Asset located in: Humble, TX	
	S/N: 4T9V6TA27KJ329225 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 63700 lb GVWR, 63700 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10009	2014 Dragon 150 BBL 6300 gal T/A Vacuum Tanker Trailer S/N: 1UNST4224ES128600 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Challenger 607SV	
T. S. C 1 U N	2018 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA25JG347005 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		Blower Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	
		10010	2013 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4223DL130024 C/W: Spring Suspension, 11R24.5 Tires, Steel	
10004	2017 Southern 150 gal T/A Vacuum Tanker Trailer S/N: 4S9V6TA26HG347007 C/W: Air Ride Suspension, 11R24.5 Tires,		Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	
	10000 lb GVWR, Aluminum Tank, 10000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10011	2012 Troxell 140 BBL 5880 gal T/A Vacuum Tanker Trailer S/N: 1T9TA4320C1867101 C/W: Spring Suspension, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Catwalk w/Guardrails,	
10005	2016 Southern 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA24GG347036 C/W: Aluminum Frame, Air Ride Suspension,		50000 lb GVWR, 45 ft Pup Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	
	11R24.5 Tires, 10000 lb GVWR Usage: Not Available Notes : RITCHIE-BROS-ENERGY Asset located in : Lake Worth, TX	10012	2011 Troxell 140 BBL 5880 gal T/A Vacuum Tanker Trailer S/N: 1T9TA432XB1867783 C/W: Spring Suspension, Aluminum Outer	
10006	2016 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA29GG347047 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		Wheels, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Catwalk w/Guardrails, 50000 lb GVWR, 45 ft Pup Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
10013	2011 Dragon 150 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4225BL068770 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Catwalk w /Guardrails Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Humble, TX	10020	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR29KP104097 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, Aluminum Tank, 68000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 2001 Heil 1000 cft T/A Pneumatic Bulk Trailer
10014	2007 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST42277L063710 C/W: Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Steel Tank, Catwalk w/Guardrails Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX	10023	S/N: 5JLSN422415T05772 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 295/75R22.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 1998 LBT 1000 cft T/A Pneumatic Bulk Trailer
10015	1979 Reliable 8400 gal T/A Vacuum Tanker Trailer S/N: 2316 C/W: Air Ride Suspension, 295/75R22.5 Tires, 60000 lb GVWR, Aluminum Tank, 60000 lb GVWR Usage: Not Available	10024	S/N: 4J8B04229WT000303 C/W: Spring Suspension, 11R22.5 Tires, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 1996 Heil 1040 cft T/A Pneumatic Bulk Trailer
10016	Asset located in: Lake Worth, TX 2008 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGFT473888506205 C/W: 2 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available		S/N: 5HTSN4223T9T07318 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
10017	Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX 1999 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGSB471XXS249824 C/W: Manifold, 1 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available	10025	1994 Heil 1600 cft T/A Pneumatic Bulk Trailer S/N: 1HLS5N8B8R9W07014 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Aluminum Tank, 4 Compartments, 70000 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
10018	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; RITCHIE-BROS- ENERGY Asset located in: Lake Worth, TX VE Enterprises 435 bbl Flat Top S/A Frac Tank S/N: FTI1298115FT C/W: 3 Hatches, Access Stairs, Spring Suspension, Air Brakes Upage: Not Available	10026	1994 Polar 1000 cft T/A Pneumatic Bulk Trailer S/N: 1PMB14225R2013531 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 11R24.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; RITCHIE-BROS- ENERGY Asset located in: Lake Worth, TX	10027	1984 Fruehauf 1000 cft T/A Pneumatic Bulk Trailer S/N: 1H4B04121EK004312 C/W: Aluminum Frame, Spring Suspension,
10019	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR27KP104096 C/W: Air Ride Suspension, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		Aluminum Wheels, 285/75R24.5 Tires, Aluminum Tank Usage: Not Available Notes : RITCHIE-BROS-ENERGY Asset located in : Lake Worth, TX

			C
Lot #	Details	Lot #	Details
10028	2015 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3228FN374020 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	10034	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG322XFN374021 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
10029	2015 Intech 32 ft x 102 ft Portable T/A Lab Trailer S/N: 1Z9GG3228FN374017 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235 /80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Oklahoma City, OK	10035	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3224FN374015 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
10030	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG322XFN374018 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	10036	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG2820EN374917 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
10031	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3226FN374016 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	10037	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG2827EN374915 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX
10032	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3221FN374019 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	10038	2014 Intech 28 ft x 102 ft Portable T/A Lab Trailer S/N: 1Z9GG2822EN374918 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235 /80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Oklahoma City, OK
10033	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3222FN374014 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX	10039	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG2829EN374916 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Midland, TX

Lot #	Details	Lot #	Deta
10040	2007 William Scotsman 52 ft x 11 ft 11 in Portable Tri/A Crew House S/N: 24348 C/W: To Fit SPACE MASTERS 40440 Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX		
11013A	2011 Overland 5460 gal T/A Vacuum Tanker Trailer S/N: 1Z9241528B1258322 C/W: Spring Suspension, 11R24.5 Tires, 64500 lb GVWR, Steel Tank, Catwalk, Fruitland Hydraulic Blower, 64500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		
95160	Pressure Testing Unit On 1995 Talbert Lowboy Trailer S/N: 40FWK5239S1012196 Usage: Not Available Asset located in: Midland, TX		